| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | LTCM000096 | LTCMechanism | 664-3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | LTCM000096 | LTCMechanism | 664-3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | LTCM000096 | LTCMechanism | 664-3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | LTCM000096 | LTCMechanism | 664-3 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | LTCM000096 | LTCMechanism | 664-3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | LTCM000096 | LTCMechanism | 664-3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | LTCM000096 | LTCMechanism | 664-3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Readings | General Comments | | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Readings | LTC Totalizer Reading | 4066.56 | kw |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Readings | Totalizer Meter Reading | .4236 | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | LTCC000717 | LTCControl | 664-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | LTCC000717 | LTCControl | 664-2 | LTC Control Insp | All Connections OK? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | LTCC000717 | LTCControl | 664-2 | LTC Control Insp | General Comments | | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | LTCC000717 | LTCControl | 664-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | LTCC000717 | LTCControl | 664-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | LTCC000717 | LTCControl | 664-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | LTCC000717 | LTCControl | 664-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | LTCC000717 | LTCControl | 664-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Counter Readings | LTC As Found Counter | 10283 | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Counter Readings | LTC As Left Counter | 10283 | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Counter Readings | General Comments | | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Counter Readings | LTC Operations Since Last Insp | 255 | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Readings | Totalizer Meter Reading | .6460 | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 6000 | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Readings | Oil Temp Present | 50 | °C |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Readings | General Comments | | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Readings | LTC Totalizer Reading | 3876.00 | kw |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | BCH001156 | Charger | 664-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | BCH001156 | Charger | 664-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | BCH001156 | Charger | 664-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.0 | VDC |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | BCH001156 | Charger | 664-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.0 | VDC |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | BCH001156 | Charger | 664-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 3.8 | amps |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | BCH001156 | Charger | 664-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | BCH001156 | Charger | 664-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | BCH001156 | Charger | 664-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | General Comments | | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | General Comments | | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | Ambient Temp | 46 | °F |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | General Comments | | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/26/2023 9:14 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | 9 Month Operations | 1 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Operations Counter AL | 162 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Operations Counter AF | 162 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | General Comments | | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Amps C Ø | 20.0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Amps B Ø | 21.0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Amps A Ø | 21.0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | 9 Month Operations | 4 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Amps A Ø | 16.0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Amps B Ø | 48.0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Amps C Ø | 10.0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Fault Operations Ground | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | General Comments | | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Operations Counter AF | 49 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Operations Counter AL | 49 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | 9 Month Operations | 8 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Amps A Ø | 240.0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Amps C Ø | 240.0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Amps B Ø | 240.0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | General Comments | | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Operations Counter AF | 99933 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Operations Counter AL | 99933 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Operations This Read Vac | 4 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Switching Operations | 4 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Counter Readings | LTC Max Tap Position | 11R | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Counter Readings | LTC Operations Since Last Insp | 414 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Counter Readings | Reset Tap Drag Hands | Unable to Reset | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Counter Readings | LTC As Left Counter | 73642 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Counter Readings | LTC As Found Counter | 73642 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Counter Readings | General Comments | Drag hands not working properly | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Counter Readings | LTC Current Tap Position | 11L | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | LTCC000975 | LTCControl | 835-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | LTCC000975 | LTCControl | 835-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | LTCC000975 | LTCControl | 835-1 | LTC Control Insp | LTC Output Voltage Level | 124.5 | VAC |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | LTCC000975 | LTCControl | 835-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | LTCC000975 | LTCControl | 835-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | LTCC000975 | LTCControl | 835-1 | LTC Control Insp | General Comments | | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | LTCC000975 | LTCControl | 835-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | LTCC000975 | LTCControl | 835-1 | LTC Control Insp | All Connections OK? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Readings | LTC Totalizer Reading | 5952.00 | kw |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Readings | General Comments | | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Readings | Totalizer Meter Reading | .6200 | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BAT001491 | Battery | 835-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BAT001491 | Battery | 835-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 66 | °F |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BAT001491 | Battery | 835-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BAT001491 | Battery | 835-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BAT001491 | Battery | 835-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BAT001491 | Battery | 835-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BAT001491 | Battery | 835-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BAT001491 | Battery | 835-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BAT001491 | Battery | 835-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BAT001491 | Battery | 835-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.0 | VDC |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BAT001491 | Battery | 835-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.0 | VDC |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BAT001491 | Battery | 835-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BAT001491 | Battery | 835-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BCH001422 | Charger | 835-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BCH001422 | Charger | 835-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BCH001422 | Charger | 835-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BCH001422 | Charger | 835-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BCH001422 | Charger | 835-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BCH001422 | Charger | 835-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BCH001422 | Charger | 835-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | BCH001422 | Charger | 835-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | General Comments | | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | General Comments | | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | General Comments | | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | Ambient Temp | 66 | °F |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/25/2023 16:42 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Operations Counter AL | 150 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Operations Counter AF | 150 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | General Comments | | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | 9 Month Operations | 150 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | 9 Month Operations VCB New | 150 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Amps A Ø | 0.0 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Amps B Ø | 0.0 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Amps C Ø | 0.0 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | General Comments | | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Operations Counter AF | 259 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Operations Counter AL | 259 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | 9 Month Operations | 5 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Amps C Ø | 120.0 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Amps B Ø | 110.0 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Amps A Ø | 90.0 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Counter Readings | LTC Operations Since Last Insp | 224 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Counter Readings | General Comments | | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Counter Readings | LTC As Found Counter | 34272 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Counter Readings | LTC As Left Counter | 34272 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | LTCC000978 | LTCControl | 413-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | LTCC000978 | LTCControl | 413-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | LTCC000978 | LTCControl | 413-1 | LTC Control Insp | All Connections OK? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | LTCC000978 | LTCControl | 413-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | LTCC000978 | LTCControl | 413-1 | LTC Control Insp | General Comments | | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | LTCC000978 | LTCControl | 413-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | LTCC000978 | LTCControl | 413-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | LTCC000978 | LTCControl | 413-1 | LTC Control Insp | LTC Output Voltage Level | 124.6 | VAC |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Readings | General Comments | | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Readings | LTC Totalizer Reading | 3576.96 | kw |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Readings | Totalizer Meter Reading | .3726 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BAT001629 | Battery | 413-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BAT001629 | Battery | 413-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BAT001629 | Battery | 413-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BAT001629 | Battery | 413-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BAT001629 | Battery | 413-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BAT001629 | Battery | 413-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BAT001629 | Battery | 413-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BAT001629 | Battery | 413-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 63 | °F |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BAT001629 | Battery | 413-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BAT001629 | Battery | 413-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BAT001629 | Battery | 413-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BAT001629 | Battery | 413-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BAT001629 | Battery | 413-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BCH001577 | Charger | 413-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BCH001577 | Charger | 413-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BCH001577 | Charger | 413-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BCH001577 | Charger | 413-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BCH001577 | Charger | 413-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .8 | amps |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BCH001577 | Charger | 413-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BCH001577 | Charger | 413-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | BCH001577 | Charger | 413-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | General Comments | | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | General Comments | | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | Ambient Temp | 63 | °F |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | General Comments | No spill kit. No berm | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/25/2023 15:32 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Ambient Temperature | 55 | °F |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | General Comments | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | SF6 Pressure Indicator | good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Readings | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Readings | Fault Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Readings | Switching Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Readings | Operations This Read SF6 | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Readings | Operations Counter AL | 71 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Readings | Operations Counter AF | 71 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Counter Readings | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Counter Readings | LTC As Found Counter | 28442 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Counter Readings | LTC As Left Counter | 28442 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Counter Readings | LTC Operations Since Last Insp | 576 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCC000725 | LTCControl | 930-Offline-Distribution | LTC Control Insp | All Connections OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCC000725 | LTCControl | 930-Offline-Distribution | LTC Control Insp | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCC000725 | LTCControl | 930-Offline-Distribution | LTC Control Insp | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCC000725 | LTCControl | 930-Offline-Distribution | LTC Control Insp | LTC Operation Checked? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCC000725 | LTCControl | 930-Offline-Distribution | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCC000725 | LTCControl | 930-Offline-Distribution | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCC000725 | LTCControl | 930-Offline-Distribution | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCC000725 | LTCControl | 930-Offline-Distribution | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 40 | °C |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 18 | °C |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Readings | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Readings | LTC Totalizer Reading | 9696.00 | kw |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Readings | Oil Temp Max | 28 | °C |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Readings | Totalizer Meter Reading | .4040 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Readings | Winding Temp Max | 29 | °C |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Readings | Winding Temp Present | 46 | °C |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1400 | psi |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | 9 Month Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Operations Counter AF | 198 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Operations Counter AL | 198 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Amps A Ø | 295.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Amps B Ø | 325.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Amps C Ø | 365.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | 9 Month Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Operations Counter AL | 171 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Operations Counter AF | 171 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Operations Counter AL | 224 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Operations Counter AF | 224 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Amps C Ø | 90.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Amps B Ø | 85.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Amps A Ø | 80.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | 9 Month Operations | 2 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | 9 Month Operations | 2 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Operations Counter AF | 228 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Operations Counter AL | 228 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Amps A Ø | 85.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Amps B Ø | 70.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Amps C Ø | 80.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Amps A Ø | 150.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | 9 Month Operations | 8 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Operations This Read Vac | 3 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Operations Counter AL | 202 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Operations Counter AF | 202 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Amps B Ø | 190.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Fault Operations C Ø | 1 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Fault Operations B Ø | 1 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Fault Adjusted Amps C Phase V | 12.37 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Amps C Ø | 165.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Fault Adjusted Amps A Phase V | 12.37 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Fault Adjusted Amps B Phase V | 12.37 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations | 3 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Amps A Ø | 60.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AF | 8 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Amps B Ø | 60.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Amps C Ø | 60.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AL | 8 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations | 3 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Maintenance Operations | 1 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Operations This Read Vac | 1 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Amps C Ø | 0.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AL | 855 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AF | 855 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Amps B Ø | 0.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Amps A Ø | 0.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations A Ø | 3 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 36.09 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Amps C Ø | 120.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Amps B Ø | 90.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Amps A Ø | 90.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations VCB New | 5 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations | 12 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Maintenance Operations | 4 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Operations This Read Vac | 7 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AL | 455 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AF | 455 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations | 7 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations VCB New | 7 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Amps A Ø | 60.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AL | 997 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AF | 997 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Amps B Ø | 60.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Amps C Ø | 60.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Amps B Ø | 400.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Amps A Ø | 400.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Amps C Ø | 400.0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AL | 265 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AF | 265 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Counter Readings | LTC As Left Counter | 53939 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Counter Readings | LTC As Found Counter | 53939 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Counter Readings | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Counter Readings | LTC Operations Since Last Insp | 28 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCC000818 | LTCControl | 930-Offline-Distribution | LTC Control Insp | All Connections OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCC000818 | LTCControl | 930-Offline-Distribution | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCC000818 | LTCControl | 930-Offline-Distribution | LTC Control Insp | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCC000818 | LTCControl | 930-Offline-Distribution | LTC Control Insp | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCC000818 | LTCControl | 930-Offline-Distribution | LTC Control Insp | LTC Operation Checked? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCC000818 | LTCControl | 930-Offline-Distribution | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCC000818 | LTCControl | 930-Offline-Distribution | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | LTCC000818 | LTCControl | 930-Offline-Distribution | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Readings | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Readings | LTC Totalizer Reading | 11646.00 | kw |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Readings | Totalizer Meter Reading | .6470 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Readings | Winding Temp Max | 45 | °C |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Readings | Switching Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Readings | Operations This Read SF6 | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Readings | Operations Counter AL | 52 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Readings | Operations Counter AF | 52 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Readings | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Readings | Fault Operations | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | SF6 Pressure Indicator | good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Ambient Temperature | 55 | °F |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | General Comments | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BCH001161 | Charger | 853-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BCH001161 | Charger | 853-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BCH001161 | Charger | 853-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.9 | amps |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BCH001161 | Charger | 853-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.0 | VDC |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BCH001161 | Charger | 853-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.0 | VDC |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | BCH001161 | Charger | 853-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | General Comments | CAN YOU REMOVE THIS HOUSE FROM THE CHECK IT ONLY HAS A/C FOR LIGHTS. | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | General Comments | | |
| 4/25/2023 14:48 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Amps C Ø | 50.0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Amps B Ø | 50.0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Amps A Ø | 50.0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | 9 Month Operations | 4 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | General Comments | | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Operations Counter AL | 101 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Operations Counter AF | 101 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Amps B Ø | 50.0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Amps A Ø | 50.0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Amps C Ø | 50.0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | 9 Month Operations | 4 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | General Comments | | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Operations Counter AF | 520 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Operations Counter AL | 520 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | General Comments | | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Operations Counter AF | 250 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Operations Counter AL | 250 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | 9 Month Operations | 2 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Amps A Ø | 240.0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Amps B Ø | 195.0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Amps C Ø | 200.0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Amps A Ø | 20.0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Amps B Ø | 20.0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Amps C Ø | 20.0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | 9 Month Operations | 4 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Operations Counter AL | 471 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | General Comments | | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Operations Counter AF | 471 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Amps C Ø | 120.0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | General Comments | | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | 9 Month Operations | 5 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Operations Counter AF | 417 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Amps A Ø | 120.0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Amps B Ø | 120.0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Operations Counter AL | 417 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000742 | LTCControl | 808-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000742 | LTCControl | 808-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000742 | LTCControl | 808-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000742 | LTCControl | 808-2 | LTC Control Insp | All Connections OK? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000742 | LTCControl | 808-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000742 | LTCControl | 808-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000742 | LTCControl | 808-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000742 | LTCControl | 808-2 | LTC Control Insp | General Comments | | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Counter Readings | General Comments | | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Counter Readings | LTC As Found Counter | 118810 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Counter Readings | LTC As Left Counter | 118810 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Counter Readings | LTC Operations Since Last Insp | 484 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 6000 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Readings | LTC Totalizer Reading | 3888.00 | kw |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Readings | General Comments | | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Readings | Totalizer Meter Reading | .6480 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000767 | LTCControl | 808-1 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000767 | LTCControl | 808-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000767 | LTCControl | 808-1 | LTC Control Insp | General Comments | | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000767 | LTCControl | 808-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000767 | LTCControl | 808-1 | LTC Control Insp | All Connections OK? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000767 | LTCControl | 808-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000767 | LTCControl | 808-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000767 | LTCControl | 808-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Counter Readings | General Comments | | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Counter Readings | LTC As Found Counter | 12398 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Counter Readings | LTC As Left Counter | 12398 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Counter Readings | LTC Operations Since Last Insp | 444 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 8000 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Readings | Totalizer Meter Reading | .6730 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Readings | LTC Totalizer Reading | 5384.00 | kw |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Readings | General Comments | | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -1.0 | psi |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BCH001562 | Charger | 808-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BCH001562 | Charger | 808-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BCH001562 | Charger | 808-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BCH001562 | Charger | 808-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BCH001562 | Charger | 808-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BCH001562 | Charger | 808-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.1 | amps |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BCH001562 | Charger | 808-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BCH001562 | Charger | 808-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 45 | °F |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | General Comments | | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | General Comments | | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | General Comments | | |
| 4/25/2023 14:28 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 56.8 | VDC |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 65.3 | VDC |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BCH000287 | Charger | 535-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 134 | VDC |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BCH000287 | Charger | 535-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 134 | VDC |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BCH000287 | Charger | 535-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .7 | amps |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BCH000287 | Charger | 535-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BCH000287 | Charger | 535-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BCH000287 | Charger | 535-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Operations Counter AL | 3 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Operations Counter AF | 3 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Amps C Ø | 25 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Amps B Ø | 20 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | 9 Month Operations | 4 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Amps A Ø | 20 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Amps B Ø | 35 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Amps C Ø | 30 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Amps A Ø | 30 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Operations This Read Vac | 1 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Operations Counter AL | 11 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | 9 Month Operations | 11 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Operations Counter AF | 11 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Maintenance Operations | 1 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Counter Readings | LTC Max Tap Position | 7R | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Counter Readings | LTC As Left Counter | 132570 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Counter Readings | LTC As Found Counter | 132565 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Counter Readings | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Counter Readings | LTC Operations Since Last Insp | 261 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Readings | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Readings | Winding Temp Max | 65 | °C |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | LTCC000689 | LTCControl | 535-3 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | LTCC000689 | LTCControl | 535-3 | LTC Control Insp | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | LTCC000689 | LTCControl | 535-3 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | LTCC000689 | LTCControl | 535-3 | LTC Control Insp | VRR Time Delay | 45 | Seconds |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | LTCC000689 | LTCControl | 535-3 | LTC Control Insp | VRR Base Voltage AL | 113.5 | VAC |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | LTCC000689 | LTCControl | 535-3 | LTC Control Insp | VRR Base Voltage AF | 113.5 | VAC |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | LTCC000689 | LTCControl | 535-3 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | LTCC000689 | LTCControl | 535-3 | LTC Control Insp | LTC Output Voltage Level | 113.7 | VAC |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | LTCC000689 | LTCControl | 535-3 | LTC Control Insp | All Connections OK? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Counter Readings | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Counter Readings | LTC Operations Since Last Insp | 266 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Counter Readings | LTC As Found Counter | 41755 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Counter Readings | LTC As Left Counter | 41765 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Counter Readings | LTC Max Tap Position | 8R | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 530.28 | kw |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Readings | General Comments | x | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 10.00 | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Readings | Oil Temp Max | 75 | °C |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 600 | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .8838 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | 9 Month Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Operations Counter AL | 124 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Operations Counter AF | 124 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Operations Counter AF | 158 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Operations Counter AL | 158 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | 9 Month Operations | 3 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Amps A Ø | 0.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Amps B Ø | 0.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Amps C Ø | 0.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | 9 Month Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Operations Counter AF | 162 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Operations Counter AL | 162 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Amps A Ø | 70.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Amps B Ø | 65.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Amps C Ø | 70.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 38.33 | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Operations Counter AF | 157 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Amps A Ø | 0.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Amps B Ø | 0.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Amps C Ø | 0.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Operations Counter AL | 157 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | 9 Month Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | General Comments | | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Operations Counter AL | 199 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Operations Counter AF | 199 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Amps B Ø | 60.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Amps A Ø | 60.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Amps C Ø | 60.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | 9 Month Operations | 6 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | General Comments | | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | General Comments | | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | Ambient Temp | 44 | °F |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Amps C Ø | 122.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Operations Counter AF | 202 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Amps B Ø | 130.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Amps A Ø | 110.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | 9 Month Operations | 1 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Operations Counter AL | 202 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 728 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.7 | volts |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Current Tap Position | 4R | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Min Tap Position | 1L | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | 9 Month Operations | 1 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Operations Counter AL | 185 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Operations Counter AF | 185 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Amps A Ø | 230.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Amps B Ø | 230.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Amps C Ø | 230.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Readings | Winding Temp Present | 35 | °C |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Readings | Winding Temp Max | 35 | °C |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Readings | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 787 | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Min Tap Position | 2L | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Current Tap Position | 4R | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Operations Counter AL | 260 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Operations Counter AF | 260 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | 9 Month Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Amps A Ø | 119.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Amps B Ø | 125.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Amps C Ø | 123.0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | 9 Month Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Operations Counter AL | 225 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Operations Counter AF | 225 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Amps A Ø | 55.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Amps B Ø | 55.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Amps C Ø | 55.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | 9 Month Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Amps A Ø | 0.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Amps B Ø | 0.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Amps C Ø | 0.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Operations Counter AL | 186 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Operations Counter AF | 186 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Operations Counter AL | 126 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Operations Counter AF | 126 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | 9 Month Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Amps C Ø | 0.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Amps B Ø | 0.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Amps A Ø | 0.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | LTCC000688 | LTCControl | 535-2 | LTC Control Insp | All Connections OK? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | LTCC000688 | LTCControl | 535-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | LTCC000688 | LTCControl | 535-2 | LTC Control Insp | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | LTCC000688 | LTCControl | 535-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | LTCC000688 | LTCControl | 535-2 | LTC Control Insp | LTC Output Voltage Level | 113.2 | VAC |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | LTCC000688 | LTCControl | 535-2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | LTCC000688 | LTCControl | 535-2 | LTC Control Insp | VRR Base Voltage AF | 113.5 | VAC |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | LTCC000688 | LTCControl | 535-2 | LTC Control Insp | VRR Base Voltage AL | 113.5 | VAC |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | LTCC000688 | LTCControl | 535-2 | LTC Control Insp | VRR Time Delay | 45 | Seconds |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | 9 Month Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Maintenance Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Operations Counter AF | 167 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Operations Counter AL | 167 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Amps C Ø | 175.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Amps B Ø | 195.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Amps A Ø | 175.0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Switching Operations | 0 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Unknown Operations | 0 | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Min Tap Position | 2L | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Current Tap Position | 3R | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 653 | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Patrol Inspection | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | GND000031 | BreakerGroundDevice | 459-Offline Distribution | Breaker Ground Device Inspection | All Connections OK? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | GND000031 | BreakerGroundDevice | 459-Offline Distribution | Breaker Ground Device Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | GND000031 | BreakerGroundDevice | 459-Offline Distribution | Breaker Ground Device Inspection | Ground Connections Intact? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | GND000031 | BreakerGroundDevice | 459-Offline Distribution | Breaker Ground Device Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | GND000031 | BreakerGroundDevice | 459-Offline Distribution | Breaker Ground Device Inspection | Rosettes Clean and Lubed? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | GND000031 | BreakerGroundDevice | 459-Offline Distribution | Breaker Ground Device Inspection | Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | GND000031 | BreakerGroundDevice | 459-Offline Distribution | Breaker Ground Device Inspection | Bearings lubricated? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | GND000031 | BreakerGroundDevice | 459-Offline Distribution | Breaker Ground Device Inspection | Vacuum and Clean Breaker? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Counter Readings | LTC Max Tap Position | 6L | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Counter Readings | LTC Current Tap Position | 10L | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Counter Readings | LTC As Left Counter | 28064 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Counter Readings | LTC As Found Counter | 28064 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Counter Readings | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Counter Readings | LTC Operations Since Last Insp | 402 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 30 | °C |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 35 | °C |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCC000611 | LTCControl | 459-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCC000611 | LTCControl | 459-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCC000611 | LTCControl | 459-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCC000611 | LTCControl | 459-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCC000611 | LTCControl | 459-1 | LTC Control Insp | All Connections OK? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCC000611 | LTCControl | 459-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCC000611 | LTCControl | 459-1 | LTC Control Insp | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCC000611 | LTCControl | 459-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Readings | LTC Totalizer Reading | 942.00 | kw |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Readings | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 1000 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Readings | Totalizer Meter Reading | .9420 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Readings | Winding Temp Max | 30 | °C |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Counter Readings | LTC As Left Counter | 278700 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Counter Readings | LTC Operations Since Last Insp | 615 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Counter Readings | LTC As Found Counter | 278965 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Counter Readings | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | LTCC000687 | LTCControl | 535-1 | LTC Control Insp | VRR Time Delay | 45 | Seconds |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | LTCC000687 | LTCControl | 535-1 | LTC Control Insp | VRR Base Voltage AL | 113.5 | VAC |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | LTCC000687 | LTCControl | 535-1 | LTC Control Insp | VRR Base Voltage AF | 113.5 | VAC |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | LTCC000687 | LTCControl | 535-1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | LTCC000687 | LTCControl | 535-1 | LTC Control Insp | LTC Output Voltage Level | 113.2 | VAC |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | LTCC000687 | LTCControl | 535-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | LTCC000687 | LTCControl | 535-1 | LTC Control Insp | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | LTCC000687 | LTCControl | 535-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | LTCC000687 | LTCControl | 535-1 | LTC Control Insp | All Connections OK? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Amps A Ø | 0.0 | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Amps B Ø | 0.0 | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Amps C Ø | 0.0 | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Operations Counter | 5 | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1000 | psi |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Operations Counter | 8 | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Amps C Ø | 58.0 | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Amps B Ø | 30.0 | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Amps A Ø | 51.0 | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 11:05 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCC000793 | LTCControl | 459-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCC000793 | LTCControl | 459-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCC000793 | LTCControl | 459-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCC000793 | LTCControl | 459-2 | LTC Control Insp | All Connections OK? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCC000793 | LTCControl | 459-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCC000793 | LTCControl | 459-2 | LTC Control Insp | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCC000793 | LTCControl | 459-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCC000793 | LTCControl | 459-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Counter Readings | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Counter Readings | LTC As Found Counter | 14059 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Counter Readings | LTC As Left Counter | 14059 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Counter Readings | LTC Current Tap Position | 10L | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Counter Readings | LTC Max Tap Position | 5L | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Counter Readings | LTC Operations Since Last Insp | 484 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 19 | °C |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 19 | °C |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Readings | Oil Temp Present | 27 | °C |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Readings | Oil Temp Max | 27 | °C |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Readings | LTC Totalizer Reading | 8688.00 | kw |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Readings | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Readings | Totalizer Meter Reading | .3620 | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Readings | Winding Temp Max | 27 | °C |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Readings | Winding Temp Present | 27 | °C |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1600 | psi |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BCH001006 | Charger | 459-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BCH001006 | Charger | 459-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.0 | VDC |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BCH001006 | Charger | 459-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.0 | VDC |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BCH001006 | Charger | 459-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 4.1 | amps |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BCH001006 | Charger | 459-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BCH001006 | Charger | 459-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BCH001006 | Charger | 459-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 135 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Readings | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0 | psi |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Ambient Temp | 65 | °F |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | General Comments | | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/25/2023 11:07 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Readings | Operations This Read SF6 | 2 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Readings | Switching Operations | 0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Readings | Unknown Operations | 0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Readings | Num Operations Last 9 Months | 2 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Readings | Maintenance Operations | 1 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Readings | General Comments | Fault on customer cables | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Readings | Operations Counter AF | 55 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Readings | Operations Counter AL | 55 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Readings | Fault Operations | 1 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | SF6 Pressure | 70 | psi |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Ambient Temperature | 55 | °F |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Readings | Operations This Read SF6 | 1 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Readings | Operations Counter AL | 86 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Readings | Switching Operations | 0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Readings | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Readings | Fault Operations | 0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Readings | Unknown Operations | 0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Readings | Maintenance Operations | 1 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Readings | Num Operations Last 9 Months | 1 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Readings | Operations Counter AF | 86 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | SF6 Pressure | 64 | psi |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | SF6 Compressor Belt Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | General Comments | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Ambient Temperature | 55 | °F |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Readings | Operations Counter AL | 74 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Readings | Operations This Read SF6 | 1 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Readings | Switching Operations | 0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Readings | Operations Counter AF | 74 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Readings | Num Operations Last 9 Months | 1 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Readings | Maintenance Operations | 1 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Readings | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Readings | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Readings | Fault Operations | 0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Ambient Temperature | 55 | °F |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Grounds in Place? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | SF6 Pressure | 67 | psi |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Floor Swept? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | General Comments | | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | General Comments | Washout under 2nd gate | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | n | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/25/2023 10:17 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Amps C Ø | 67.0 | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Amps B Ø | 62.0 | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Amps A Ø | 64.0 | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Operations Counter | 137 | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Amps A Ø | 37.0 | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Amps B Ø | 36.6 | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Amps C Ø | 28.0 | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Operations Counter | 11 | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Counter Readings | LTC Operations Since Last Insp | 609 | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Counter Readings | LTC As Left Counter | 28867 | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Counter Readings | General Comments | | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Counter Readings | LTC As Found Counter | 28867 | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | LTCC000641 | LTCControl | 744-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | LTCC000641 | LTCControl | 744-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | LTCC000641 | LTCControl | 744-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | LTCC000641 | LTCControl | 744-1 | LTC Control Insp | LTC Output Voltage Level | 125.4 | VAC |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | LTCC000641 | LTCControl | 744-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | LTCC000641 | LTCControl | 744-1 | LTC Control Insp | All Connections OK? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | LTCC000641 | LTCControl | 744-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | LTCC000641 | LTCControl | 744-1 | LTC Control Insp | General Comments | | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 2.0 | psi |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Readings | General Comments | | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Readings | LTC Totalizer Reading | 3513.60 | kw |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Readings | Totalizer Meter Reading | .7320 | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | General Comments | | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Interruptrs/Puffrs Visual OK? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | General Comments | | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | General Comments | | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/24/2023 16:39 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Switching Operations | 3 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Operations This Read Vac | 3 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Operations Counter AL | 206 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Operations Counter AF | 206 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | General Comments | | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | 9 Month Operations | 4 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Amps A Ø | 102.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Amps B Ø | 117.0 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Amps C Ø | 116.0 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | 9 Month Operations | 1 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Operations This Read Vac | 0 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Operations Counter AL | 280 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Operations Counter AF | 280 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Amps A Ø | 64.0 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Amps B Ø | 46.0 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Amps C Ø | 60.0 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Switching Operations | 0 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | General Comments | | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 43657 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 189336 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 125.6 | volts |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 86670 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.8 | volts |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Readings | General Comments | | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 4239.36 | kw |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Readings | Oil Temp Max | 60 | °C |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Readings | Oil Temp Present | 60 | °C |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .4416 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 58 | °F |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BCH001424 | Charger | 726-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BCH001424 | Charger | 726-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BCH001424 | Charger | 726-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BCH001424 | Charger | 726-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BCH001424 | Charger | 726-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.4 | amps |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BCH001424 | Charger | 726-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BCH001424 | Charger | 726-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BCH001424 | Charger | 726-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | General Comments | | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | General Comments | | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/24/2023 15:38 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | Ambient Temp | 58 | °F |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Switching Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Operations Counter AL | 144 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Operations Counter AF | 144 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Amps C Ø | 330.0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Amps B Ø | 350.0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Amps A Ø | 315.0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | 9 Month Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Operations Counter AF | 206 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Operations Counter AL | 206 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Operations This Read Vac | 2 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Switching Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Fault Operations B Ø | 2 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Fault Adjusted Amps B Phase V | 12.82 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | 9 Month Operations | 4 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Amps A Ø | 85.0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Amps B Ø | 100.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Amps C Ø | 80.0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | 9 Month Operations | 3 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Amps A Ø | 0.0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Switching Operations | 2 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Operations This Read Vac | 2 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Operations Counter AL | 182 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Operations Counter AF | 182 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | General Comments | | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Amps C Ø | 0.0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Amps B Ø | 0.0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Operations Counter AF | 160 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Operations Counter AL | 160 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Operations This Read Vac | 12 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Switching Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Fault Operations B Ø | 6 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Fault Operations A Ø | 6 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Fault Adjusted Amps B Phase V | 38.45 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Fault Adjusted Amps A Phase V | 38.45 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Amps C Ø | 110.0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Amps B Ø | 95.0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Amps A Ø | 95.0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | 9 Month Operations | 19 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | 9 Month Operations | 5 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | 9 Month Operations VCB New | 1 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Amps A Ø | 31.0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Amps B Ø | 35.0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Amps C Ø | 37.0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Switching Operations | 4 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Operations This Read Vac | 4 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | General Comments | | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Operations Counter AL | 224 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Operations Counter AF | 224 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Operations Counter AL | 248 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Operations This Read Vac | 4 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Switching Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | 9 Month Operations | 6 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Amps A Ø | 180.0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Amps B Ø | 190.0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Amps C Ø | 180.0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Fault Adjusted Amps C Phase V | 25.63 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Fault Operations C Ø | 4 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Operations Counter AF | 248 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | 9 Month Operations | 2 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Amps A Ø | 59.0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Amps B Ø | 60.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Amps C Ø | 59.0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Operations Counter AF | 227 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Operations Counter AL | 227 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Operations This Read Vac | 1 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Switching Operations | 1 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | 9 Month Operations | 4 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Switching Operations | 2 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Operations Counter AF | 164 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | General Comments | | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Operations This Read Vac | 2 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Amps A Ø | 73.0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Amps B Ø | 74.0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Amps C Ø | 57.0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Operations Counter AL | 164 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Switching Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Operations Counter AL | 182 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Operations Counter AF | 182 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | General Comments | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | 9 Month Operations | 2 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Operations Counter AF | 482 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Fault Operations C Ø | 4 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Fault Adjusted Amps C Phase V | 67.82 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | 9 Month Operations | 8 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Amps C Ø | 100.0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Amps B Ø | 100.0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Amps A Ø | 100.0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Operations Counter AL | 482 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Operations This Read Vac | 4 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Switching Operations | 0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Min Tap Position | 13L | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 202668 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Amps A Ø | 70.0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Amps B Ø | 55.0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Amps C Ø | 75.0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | 9 Month Operations | 2 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Operations Counter AF | 239 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Operations Counter AL | 239 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Operations This Read Vac | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Switching Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 32885 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | 9 Month Operations | 4 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Switching Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Operations This Read Vac | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Operations Counter AL | 423 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Operations Counter AF | 423 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Amps C Ø | 100.0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Amps B Ø | 100.0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Amps A Ø | 100.0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Amps A Ø | 250.0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Amps B Ø | 230.0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Amps C Ø | 260.0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | 9 Month Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Switching Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Operations Counter AL | 182 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Operations Counter AF | 182 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 212902 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Min Tap Position | 15L | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Current Tap Position | 9L | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | LTCC000813 | LTCControl | 863-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | LTCC000813 | LTCControl | 863-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | LTCC000813 | LTCControl | 863-2 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | LTCC000813 | LTCControl | 863-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | LTCC000813 | LTCControl | 863-2 | LTC Control Insp | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | LTCC000813 | LTCControl | 863-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | LTCC000813 | LTCControl | 863-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | LTCC000813 | LTCControl | 863-2 | LTC Control Insp | All Connections OK? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Counter Readings | LTC Operations Since Last Insp | 570 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Counter Readings | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Counter Readings | LTC As Found Counter | 151402 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Counter Readings | LTC As Left Counter | 151402 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Readings | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Readings | LTC Totalizer Reading | 9253.44 | kw |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Readings | Totalizer Meter Reading | .6426 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Readings | Winding Temp Max | 55 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .3310 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Readings | Oil Temp Max | 55 | °C |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3177.60 | kw |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Readings | General Comments | | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Counter Readings | LTC Operations Since Last Insp | 452 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Counter Readings | LTC As Left Counter | 24178 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Counter Readings | LTC As Found Counter | 24178 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Counter Readings | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | LTCC000349 | LTCControl | 930-Offline-Distribution | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | LTCC000349 | LTCControl | 930-Offline-Distribution | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | LTCC000349 | LTCControl | 930-Offline-Distribution | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | LTCC000349 | LTCControl | 930-Offline-Distribution | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | LTCC000349 | LTCControl | 930-Offline-Distribution | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | LTCC000349 | LTCControl | 930-Offline-Distribution | LTC Control Insp | LTC Operation Checked? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | LTCC000349 | LTCControl | 930-Offline-Distribution | LTC Control Insp | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | LTCC000349 | LTCControl | 930-Offline-Distribution | LTC Control Insp | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | LTCC000349 | LTCControl | 930-Offline-Distribution | LTC Control Insp | All Connections OK? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Readings | Totalizer Meter Reading | .4860 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Readings | Winding Temp Present | 20 | °C |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Readings | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Readings | LTC Totalizer Reading | 6998.40 | kw |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1800 | psi |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BCH001482 | Charger | 863-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BCH001482 | Charger | 863-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BCH001482 | Charger | 863-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BCH001482 | Charger | 863-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 4.1 | amps |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BCH001482 | Charger | 863-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BCH001482 | Charger | 863-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BCH001482 | Charger | 863-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BCH001482 | Charger | 863-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BAT001551 | Battery | 863-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BAT001551 | Battery | 863-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BAT001551 | Battery | 863-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BAT001551 | Battery | 863-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BAT001551 | Battery | 863-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BAT001551 | Battery | 863-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BAT001551 | Battery | 863-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BAT001551 | Battery | 863-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BAT001551 | Battery | 863-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BAT001551 | Battery | 863-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BAT001551 | Battery | 863-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BAT001551 | Battery | 863-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | BAT001551 | Battery | 863-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BAT001543 | Battery | 848-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 55 | °F |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BAT001543 | Battery | 848-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BAT001543 | Battery | 848-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BAT001543 | Battery | 848-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BAT001543 | Battery | 848-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BAT001543 | Battery | 848-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BAT001543 | Battery | 848-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 25.0 | VDC |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BAT001543 | Battery | 848-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BAT001543 | Battery | 848-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BAT001543 | Battery | 848-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BAT001543 | Battery | 848-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BAT001543 | Battery | 848-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BAT001543 | Battery | 848-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BCH001365 | Charger | 848-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BCH001365 | Charger | 848-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BCH001365 | Charger | 848-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BCH001365 | Charger | 848-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BCH001365 | Charger | 848-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.8 | VDC |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BCH001365 | Charger | 848-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.8 | VDC |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BCH001365 | Charger | 848-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.0 | amps |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | BCH001365 | Charger | 848-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | General Comments | | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/24/2023 14:41 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | General Comments | | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | General Comments | | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | General Comments | | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/24/2023 14:52 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Operations Counter AL | 185 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Amps C Ø | 325.0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Amps B Ø | 325.0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Amps A Ø | 320.0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Operations This Read Vac | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Switching Operations | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | General Comments | | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Operations Counter AF | 185 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | 9 Month Operations | 2 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | 9 Month Operations | 2 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Amps A Ø | 0.0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Amps B Ø | 0.0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Amps C Ø | 0.0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | General Comments | | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Operations Counter AF | 183 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Operations Counter AL | 183 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Operations This Read Vac | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Switching Operations | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | 9 Month Operations | 2 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Amps A Ø | 6.0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Amps B Ø | 6.0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Amps C Ø | 6.0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | General Comments | | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Operations Counter AF | 205 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Operations Counter AL | 205 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Operations This Read Vac | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Switching Operations | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Switching Operations | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Operations This Read Vac | 4 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Operations Counter AL | 194 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Operations Counter AF | 194 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | 9 Month Operations | 6 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Fault Adjusted Amps C Phase V | 9.88 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | General Comments | | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Fault Operations A Ø | 2 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Fault Operations C Ø | 2 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Amps A Ø | 18.0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Amps B Ø | 6.0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Amps C Ø | 0.0 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Fault Adjusted Amps A Phase V | 9.88 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | LTCC000708 | LTCControl | 659-1 | LTC Control Insp | General Comments | | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | LTCC000708 | LTCControl | 659-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | LTCC000708 | LTCControl | 659-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | LTCC000708 | LTCControl | 659-1 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | LTCC000708 | LTCControl | 659-1 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | LTCC000708 | LTCControl | 659-1 | LTC Control Insp | LTC Output Voltage Level | 126.0 | VAC |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | LTCC000708 | LTCControl | 659-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | LTCC000708 | LTCControl | 659-1 | LTC Control Insp | All Connections OK? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Readings | Totalizer Meter Reading | .6730 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Readings | General Comments | | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Readings | LTC Totalizer Reading | 9691.20 | kw |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Counter Readings | LTC Operations Since Last Insp | 210 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Counter Readings | LTC Min Tap Position | 16L | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Counter Readings | LTC Max Tap Position | 10L | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Counter Readings | LTC Current Tap Position | 10L | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Counter Readings | LTC As Left Counter | 70104 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Counter Readings | LTC As Found Counter | 70104 | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Counter Readings | General Comments | | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BCH001127 | Charger | 659-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BCH001127 | Charger | 659-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BCH001127 | Charger | 659-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BCH001127 | Charger | 659-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BCH001127 | Charger | 659-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.0 | amps |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BCH001127 | Charger | 659-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | BCH001127 | Charger | 659-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | General Comments | | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | General Comments | | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | YD000474 | Yard | 659-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | YD000474 | Yard | 659-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | YD000474 | Yard | 659-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | YD000474 | Yard | 659-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | YD000474 | Yard | 659-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | YD000474 | Yard | 659-Yard | Yard Patrol Inspection | General Comments | | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | YD000474 | Yard | 659-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | YD000474 | Yard | 659-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | YD000474 | Yard | 659-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | YD000474 | Yard | 659-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | YD000474 | Yard | 659-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | YD000474 | Yard | 659-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:29 | Distribution | GE Lamp Works Quarterly Inspection | YD000474 | Yard | 659-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | General Comments | VARMIT GUARD ON LOW SIDE HAS BLOWN OFF | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | LTCC000314 | LTCControl | 629-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | LTCC000314 | LTCControl | 629-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | LTCC000314 | LTCControl | 629-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | LTCC000314 | LTCControl | 629-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | LTCC000314 | LTCControl | 629-1 | LTC Control Insp | LTC Output Voltage Level | 0.0 | VAC |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | LTCC000314 | LTCControl | 629-1 | LTC Control Insp | LTC Operation Checked? | n | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | LTCC000314 | LTCControl | 629-1 | LTC Control Insp | General Comments | LTC has no station supply open per mine inspector | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | LTCC000314 | LTCControl | 629-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | LTCC000314 | LTCControl | 629-1 | LTC Control Insp | All Connections OK? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | MX0471 | RecloserHydraulic | 629-0469 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | MX0471 | RecloserHydraulic | 629-0469 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | MX0471 | RecloserHydraulic | 629-0469 | Recloser Hydraulic Patrol Inspection | Operations Counter | 432 | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | MX0471 | RecloserHydraulic | 629-0469 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | MX0471 | RecloserHydraulic | 629-0469 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | MX0471 | RecloserHydraulic | 629-0469 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | MX0471 | RecloserHydraulic | 629-0469 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | MX0471 | RecloserHydraulic | 629-0469 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0.0 | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | MX0471 | RecloserHydraulic | 629-0469 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | MX0471 | RecloserHydraulic | 629-0469 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | MX0471 | RecloserHydraulic | 629-0469 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | MX0471 | RecloserHydraulic | 629-0469 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | MX0471 | RecloserHydraulic | 629-0469 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Counter Readings | LTC As Left Counter | 407686 | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Counter Readings | LTC As Found Counter | 407686 | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Counter Readings | Reset Tap Drag Hands | Unable to Reset | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Counter Readings | LTC Operations Since Last Insp | 0 | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Counter Readings | General Comments | LTC OFF | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Counter Readings | LTC Min Tap Position | 16L | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Readings | General Comments | | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Readings | LTC Totalizer Reading | 0.00 | kw |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Readings | Oil Temp Present | 22 | °C |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 2000 | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | General Comments | | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | General Comments | | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | n | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | YD000008 | Yard | 629-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | YD000008 | Yard | 629-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | YD000008 | Yard | 629-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | YD000008 | Yard | 629-Yard | Yard Patrol Inspection | General Comments | | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | YD000008 | Yard | 629-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | YD000008 | Yard | 629-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | YD000008 | Yard | 629-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | YD000008 | Yard | 629-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | YD000008 | Yard | 629-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | YD000008 | Yard | 629-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | YD000008 | Yard | 629-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | YD000008 | Yard | 629-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/24/2023 14:35 | Distribution | Jacks Creek Quarterly Inspection | YD000008 | Yard | 629-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Amps C Ø | 5.0 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Amps B Ø | 5.0 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Amps A Ø | 18.0 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | 9 Month Operations | 9 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Switching Operations | 8 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Operations This Read Vac | 8 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Operations Counter AL | 180 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Operations Counter AF | 180 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | General Comments | | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Amps C Ø | 42.0 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Amps B Ø | 33.9 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Amps A Ø | 35.4 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Operations Counter | 11 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 6377 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 125.0 | volts |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 43195 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.2 | volts |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Max Tap Position | 9R | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 125.3 | volts |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 44150 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .6840 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Readings | General Comments | | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1641.60 | kw |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 49 | °F |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BCH000619 | Charger | 775-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BCH000619 | Charger | 775-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BCH000619 | Charger | 775-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .6 | amps |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BCH000619 | Charger | 775-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BCH000619 | Charger | 775-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BCH000619 | Charger | 775-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | General Comments | | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | General Comments | | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | Ambient Temp | 49 | °F |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | General Comments | | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/24/2023 12:21 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | 9 Month Operations | 5 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | General Comments | | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Operations Counter AF | 315 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Amps C Ø | 108.0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Amps B Ø | 96.0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Amps A Ø | 12.0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Operations Counter AL | 315 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Operations This Read Vac | 1 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Switching Operations | 1 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Amps C Ø | 9.0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | 9 Month Operations | 1 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Amps A Ø | 7.0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | General Comments | | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Operations Counter AF | 158 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Operations Counter AL | 158 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Amps B Ø | 31.0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Operations This Read Vac | 0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Switching Operations | 0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | 9 Month Operations | 1 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Amps A Ø | 121.0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Amps B Ø | 138.0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Amps C Ø | 110.0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | General Comments | | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Operations Counter AF | 182 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Operations Counter AL | 182 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Switching Operations | 0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Operations This Read Vac | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | 9 Month Operations | 2 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Amps C Ø | 420.0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Switching Operations | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Amps B Ø | 450.0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Amps A Ø | 420.0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Operations Counter AF | 183 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Operations Counter AL | 183 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | LTCC000553 | LTCControl | 884-1 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | LTCC000553 | LTCControl | 884-1 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | LTCC000553 | LTCControl | 884-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | LTCC000553 | LTCControl | 884-1 | LTC Control Insp | LTC Output Voltage Level | 125.1 | VAC |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | LTCC000553 | LTCControl | 884-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | LTCC000553 | LTCControl | 884-1 | LTC Control Insp | General Comments | | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | LTCC000553 | LTCControl | 884-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | LTCC000553 | LTCControl | 884-1 | LTC Control Insp | All Connections OK? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Operations Counter AF | 227 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Operations Counter AL | 227 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Operations This Read Vac | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Amps C Ø | 120.0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Amps B Ø | 120.0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Amps A Ø | 120.0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | 9 Month Operations | 4 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Switching Operations | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Counter Readings | LTC Operations Since Last Insp | 1321 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Counter Readings | General Comments | | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Counter Readings | LTC As Found Counter | 111706 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Counter Readings | LTC As Left Counter | 111706 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | 9 Month Operations | 2 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Operations Counter AF | 386 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Amps C Ø | 130.0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Amps B Ø | 140.0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Operations Counter AL | 386 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Operations This Read Vac | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Switching Operations | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Amps A Ø | 115.0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | 9 Month Operations VCB New | 2 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Amps C Ø | 90.0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Amps B Ø | 90.0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Amps A Ø | 90.0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | 9 Month Operations | 3 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Operations Counter AF | 199 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Operations Counter AL | 199 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Operations This Read Vac | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Switching Operations | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Readings | Totalizer Meter Reading | .8556 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Readings | Oil Temp Present | 55 | °C |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Readings | General Comments | | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Readings | Oil Temp Max | 65 | °C |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Readings | LTC Totalizer Reading | 2053.44 | kw |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | 9 Month Operations | 1 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Amps C Ø | 590.0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Amps B Ø | 670.0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Amps A Ø | 625.0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Operations Counter AF | 203 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Operations Counter AL | 204 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Operations This Read Vac | 1 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Switching Operations | 1 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Readings | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Readings | LTC Totalizer Reading | 16776.00 | kw |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Readings | Totalizer Meter Reading | .6990 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Readings | Winding Temp Max | 70 | °C |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Readings | Winding Temp Present | 45 | °C |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BCH001309 | Charger | 884-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BCH001309 | Charger | 884-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BCH001309 | Charger | 884-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BCH001309 | Charger | 884-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BCH001309 | Charger | 884-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BCH001309 | Charger | 884-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BCH001309 | Charger | 884-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BCH001309 | Charger | 884-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.2 | amps |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 46 | °F |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000916 | LTCControl | 716-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000916 | LTCControl | 716-1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000916 | LTCControl | 716-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000916 | LTCControl | 716-1 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000916 | LTCControl | 716-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000916 | LTCControl | 716-1 | LTC Control Insp | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000916 | LTCControl | 716-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000916 | LTCControl | 716-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000916 | LTCControl | 716-1 | LTC Control Insp | All Connections OK? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Interruptrs/Puffrs Visual OK? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | General Comments | | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Counter Readings | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Counter Readings | LTC As Found Counter | 56086 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Counter Readings | LTC As Left Counter | 56086 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Counter Readings | LTC Current Tap Position | 5R | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Counter Readings | LTC Max Tap Position | 5R | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Counter Readings | LTC Min Tap Position | 3L | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Counter Readings | LTC Operations Since Last Insp | 525 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | General Comments | | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | General Comments | | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/24/2023 11:22 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | Ambient Temp | 46 | °F |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | 9 Month Operations | 2 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Amps A Ø | 0.0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Amps B Ø | 0.0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Operations Counter AF | 870 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Operations Counter AL | 870 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Amps C Ø | 0.0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Switching Operations | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Operations This Read Vac | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Amps B Ø | 450.0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Amps C Ø | 420.0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Operations Counter AF | 668 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Operations Counter AL | 668 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Operations This Read Vac | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Switching Operations | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | 9 Month Operations | 4 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Amps A Ø | 420.0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | 9 Month Operations | 1 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Unknown Operations | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Switching Operations | 1 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Amps A Ø | 0.0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Amps B Ø | 0.0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Amps C Ø | 0.0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Operations This Read Vac | 1 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Operations Counter AL | 744 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Operations Counter AF | 743 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000874 | LTCControl | 716-2 | LTC Control Insp | VRR Base Voltage AL | 0.0 | VAC |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000874 | LTCControl | 716-2 | LTC Control Insp | VRR Base Voltage AF | 0.0 | VAC |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000874 | LTCControl | 716-2 | LTC Control Insp | LTC Output Voltage Level | 0.0 | VAC |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000874 | LTCControl | 716-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000874 | LTCControl | 716-2 | LTC Control Insp | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000874 | LTCControl | 716-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000874 | LTCControl | 716-2 | LTC Control Insp | All Connections OK? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000874 | LTCControl | 716-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Readings | Winding Temp Max | 25 | °C |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Readings | Winding Temp Present | 10 | °C |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Readings | Oil Temp Present | 10 | °C |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Readings | Oil Temp Max | 25 | °C |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Readings | LTC Totalizer Reading | 0.00 | kw |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Readings | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Counter Readings | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Counter Readings | LTC As Found Counter | 14005 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Counter Readings | LTC As Left Counter | 14005 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Counter Readings | LTC Min Tap Position | Neutral | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Counter Readings | LTC Operations Since Last Insp | 18 | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -1.0 | psi |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | YD000356 | Yard | 716-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | YD000356 | Yard | 716-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | YD000356 | Yard | 716-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | YD000356 | Yard | 716-Yard | Yard Patrol Inspection | General Comments | | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | YD000356 | Yard | 716-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | YD000356 | Yard | 716-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | YD000356 | Yard | 716-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | YD000356 | Yard | 716-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | YD000356 | Yard | 716-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | YD000356 | Yard | 716-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | YD000356 | Yard | 716-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | YD000356 | Yard | 716-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | YD000356 | Yard | 716-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/24/2023 11:16 | Distribution | Higby Mill Distribution Quarterly Inspection | YD000356 | Yard | 716-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Counter Readings | LTC Operations Since Last Insp | 203 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Counter Readings | LTC As Left Counter | 54766 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Counter Readings | General Comments | Counter was put in wrong on last quarter check, this is the correct count. (JB corrected the LTC overhaul counter) | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Counter Readings | LTC As Found Counter | 54766 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | General Comments | | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Operations Counter AF | 214 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Operations Counter AL | 214 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Operations This Read Vac | 0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Amps A Ø | 75.0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Amps B Ø | 83.0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Operations This Read Vac | 2 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Amps C Ø | 79.0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Fault Adjusted Amps A Phase V | 12.82 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Fault Operations A Ø | 2 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Accumulated Fault Duty C Ph V | 1.43 | % |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Accumulated Fault Duty B Ph V | 1.43 | % |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Accumulated Fault Duty A Ph V | 1.43 | % |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | 9 Month Operations VCB New | 11 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | General Comments | | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Operations Counter AL | 179 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Amps C Ø | 125.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Amps B Ø | 119.0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Amps A Ø | 151.0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Accumulated Fault Duty C Ph V | .96 | % |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Accumulated Fault Duty B Ph V | .48 | % |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Accumulated Fault Duty A Ph V | .48 | % |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | 9 Month Operations | 3 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | 9 Month Operations | 13 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Operations Counter AF | 179 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Counter Readings | LTC Operations Since Last Insp | 784 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Counter Readings | LTC As Left Counter | 203743 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Counter Readings | LTC As Found Counter | 203743 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Counter Readings | General Comments | Counter was entered wrong in last quarter check. (JB corrected as left counter reading on last quarter check ) | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | 9 Month Operations | 10 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Fault Adjusted Amps C Phase V | 19.22 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Fault Operations C Ø | 3 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Operations Counter AF | 515 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Amps C Ø | 160.0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Amps B Ø | 160.0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Amps A Ø | 149.0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Accumulated Fault Duty C Ph V | 2.39 | % |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Operations Counter AL | 515 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Amps A Ø | 121.0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Amps B Ø | 134.0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Amps C Ø | 124.0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Operations This Read Vac | 2 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Fault Operations B Ø | 2 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Operations Counter AF | 293 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Fault Adjusted Amps B Phase V | 51.32 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Amps C Ø | 200.0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Amps B Ø | 120.0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Amps A Ø | 120.0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Operations Counter AL | 293 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Operations This Read Vac | 3 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Unknown Operations | 6 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Operations This Read Vac | 6 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Operations Counter AL | 183 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Operations Counter AF | 183 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Fault Adjusted Amps C Phase V | 38.45 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Fault Adjusted Amps B Phase V | 38.45 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Fault Adjusted Amps A Phase V | 38.45 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | 9 Month Operations | 5 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | 9 Month Operations | 7 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Accumulated Fault Duty A Ph V | 6.69 | % |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Accumulated Fault Duty B Ph V | 2.39 | % |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Counter Readings | General Comments | corrected as left counter from 20959 to 202959 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Counter Readings | LTC As Left Counter | 202959 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Counter Readings | LTC Current Tap Position | 2R | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Counter Readings | LTC Operations Since Last Insp | 840 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Counter Readings | LTC As Found Counter | 202959 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Amps C Ø | 90.0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Amps B Ø | 90.0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Amps A Ø | 85.0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Accumulated Fault Duty C Ph V | 2.39 | % |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Accumulated Fault Duty B Ph V | 2.39 | % |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Accumulated Fault Duty A Ph V | 6.69 | % |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | 9 Month Operations | 4 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Fault Operations Ground | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Maintenance Operations | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Operations Counter AF | 288 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Operations Counter AL | 290 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Operations This Read Vac | 3 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Switching Operations | 3 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Operations This Read Vac | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Operations Counter AL | 185 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Operations Counter AF | 185 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | General Comments | | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | 9 Month Operations | 3 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Amps A Ø | 0.0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Amps B Ø | 0.0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Amps C Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Operations This Read Vac | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Operations Counter AL | 215 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Operations Counter AF | 215 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | General Comments | | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | 9 Month Operations VCB New | 11 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | 9 Month Operations | 11 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Amps A Ø | 43.0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Amps B Ø | 30.0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Amps C Ø | 38.0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | 9 Month Operations | 3 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Amps A Ø | 42.0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Amps B Ø | 66.0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Amps C Ø | 49.0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | General Comments | | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Operations This Read Vac | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Operations Counter AF | 1696 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Operations Counter AL | 1696 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Amps C Ø | 107.0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Amps B Ø | 145.0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Amps A Ø | 143.0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | General Comments | | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Operations Counter AF | 461 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Switching Operations | 2 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | 9 Month Operations | 9 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Operations Counter AL | 461 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Operations This Read Vac | 2 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Counter Readings | General Comments | | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Counter Readings | LTC As Found Counter | 15038 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Counter Readings | LTC As Left Counter | 15038 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Counter Readings | LTC Operations Since Last Insp | 423 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | LTCC000678 | LTCControl | 417-1 | LTC Control Insp | All Connections OK? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | LTCC000678 | LTCControl | 417-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | LTCC000678 | LTCControl | 417-1 | LTC Control Insp | General Comments | | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | LTCC000678 | LTCControl | 417-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | LTCC000678 | LTCControl | 417-1 | LTC Control Insp | LTC Output Voltage Level | 123.1 | VAC |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | LTCC000678 | LTCControl | 417-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | LTCC000678 | LTCControl | 417-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | LTCC000678 | LTCControl | 417-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Readings | LTC Totalizer Reading | 5195.52 | kw |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Readings | Totalizer Meter Reading | .5412 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Readings | General Comments | | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BCH000468 | Charger | 417-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.3 | VDC |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BCH000468 | Charger | 417-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.0 | amps |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BCH000468 | Charger | 417-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BCH000468 | Charger | 417-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.3 | VDC |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BCH000468 | Charger | 417-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BCH000468 | Charger | 417-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BCH000468 | Charger | 417-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | General Comments | | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | General Comments | | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | Ambient Temp | 70 | °F |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | General Comments | | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/21/2023 14:36 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | General Comments | | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Operations Counter AF | 184 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Operations Counter AL | 184 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Operations This Read Vac | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Amps C Ø | 126.0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Amps B Ø | 102.0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | 9 Month Operations | 8 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Amps A Ø | 106.0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Operations This Read Vac | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Operations Counter AL | 200 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Operations Counter AF | 200 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | General Comments | | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | 9 Month Operations | 7 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Amps A Ø | 30.0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Amps C Ø | 16.0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Amps B Ø | 40.0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | 9 Month Operations | 5 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Fault Adjusted Amps A Phase V | 6.55 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Amps C Ø | 104.0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Amps B Ø | 130.0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Amps A Ø | 113.0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | General Comments | | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Operations Counter AF | 201 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Operations Counter AL | 201 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Operations This Read Vac | 1 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | 9 Month Operations | 4 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Operations Counter AF | 197 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Operations Counter AL | 197 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | General Comments | | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Fault Operations C Ø | 1 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Operations This Read Vac | 2 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Amps A Ø | 44.0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Amps B Ø | 40.0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Amps C Ø | 41.0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Fault Adjusted Amps A Phase V | 4.94 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Fault Adjusted Amps C Phase V | 4.94 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Amps A Ø | 117.0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Amps B Ø | 127.0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Amps C Ø | 142.0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Operations This Read Vac | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Operations Counter AL | 205 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Operations Counter AF | 205 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | General Comments | | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | 9 Month Operations | 2 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | 9 Month Operations | 2 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Switching Operations | 2 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Operations This Read Vac | 2 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Operations Counter AL | 302 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Operations Counter AF | 300 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | General Comments | FTC | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Amps B Ø | 271.0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Amps C Ø | 231.0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Amps A Ø | 240.0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | 9 Month Operations | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | General Comments | | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Operations Counter AF | 176 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Operations Counter AL | 176 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Counter Readings | LTC As Found Counter | 34012 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Counter Readings | General Comments | | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Counter Readings | LTC Operations Since Last Insp | 291 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Counter Readings | LTC Max Tap Position | 5L | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Counter Readings | LTC As Left Counter | 34012 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | LTCC000942 | LTCControl | 717-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | LTCC000942 | LTCControl | 717-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | LTCC000942 | LTCControl | 717-1 | LTC Control Insp | All Connections OK? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | LTCC000942 | LTCControl | 717-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | LTCC000942 | LTCControl | 717-1 | LTC Control Insp | General Comments | | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | LTCC000942 | LTCControl | 717-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | LTCC000942 | LTCControl | 717-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | LTCC000942 | LTCControl | 717-1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | LTCC000942 | LTCControl | 717-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Readings | Totalizer Meter Reading | .6660 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Readings | Oil Temp Present | 50 | °C |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Readings | LTC Totalizer Reading | 4795.20 | kw |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Readings | General Comments | | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 135.00 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Readings | Winding Temp Present | 45 | °C |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Readings | Winding Temp Max | 50 | °C |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Readings | Totalizer Meter Reading | .5140 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Readings | LTC Totalizer Reading | 7401.60 | kw |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Readings | General Comments | | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | LTCC000835 | LTCControl | 717-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | LTCC000835 | LTCControl | 717-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | LTCC000835 | LTCControl | 717-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | LTCC000835 | LTCControl | 717-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | LTCC000835 | LTCControl | 717-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | LTCC000835 | LTCControl | 717-2 | LTC Control Insp | General Comments | | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | LTCC000835 | LTCControl | 717-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | LTCC000835 | LTCControl | 717-2 | LTC Control Insp | All Connections OK? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Counter Readings | LTC As Left Counter | 35695 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Counter Readings | LTC As Found Counter | 35695 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Counter Readings | General Comments | | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Counter Readings | LTC Operations Since Last Insp | 412 | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Mechanism Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BAT001674 | Battery | 717-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BAT001674 | Battery | 717-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BAT001674 | Battery | 717-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BAT001674 | Battery | 717-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BAT001674 | Battery | 717-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BAT001674 | Battery | 717-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BAT001674 | Battery | 717-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BAT001674 | Battery | 717-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BAT001674 | Battery | 717-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BAT001674 | Battery | 717-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BAT001674 | Battery | 717-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BAT001674 | Battery | 717-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BAT001674 | Battery | 717-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 73 | °F |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BCH001565 | Charger | 717-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BCH001565 | Charger | 717-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 4.2 | amps |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BCH001565 | Charger | 717-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BCH001565 | Charger | 717-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BCH001565 | Charger | 717-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BCH001565 | Charger | 717-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BCH001565 | Charger | 717-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | BCH001565 | Charger | 717-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | General Comments | | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | General Comments | | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | Ambient Temp | 73 | °F |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/21/2023 14:24 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Switching Operations | 1 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Operations This Read Vac | 1 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Operations Counter AL | 224 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Operations Counter AF | 223 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | General Comments | | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Amps C Ø | 80.0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Amps B Ø | 99.0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Amps A Ø | 89.0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | 9 Month Operations | 3 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Operations Counter AF | 182 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Operations Counter AL | 182 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Operations This Read Vac | 1 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Amps C Ø | 283.0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Amps B Ø | 296.0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Amps A Ø | 313.0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Switching Operations | 1 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | 9 Month Operations | 1 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | General Comments | | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | LTCC000800 | LTCControl | 526-1 | LTC Control Insp | All Connections OK? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | LTCC000800 | LTCControl | 526-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | LTCC000800 | LTCControl | 526-1 | LTC Control Insp | General Comments | | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | LTCC000800 | LTCControl | 526-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | LTCC000800 | LTCControl | 526-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | LTCC000800 | LTCControl | 526-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | LTCC000800 | LTCControl | 526-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | LTCC000800 | LTCControl | 526-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Readings | Totalizer Meter Reading | .5310 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Readings | General Comments | | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Readings | LTC Totalizer Reading | 7646.40 | kw |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BCH001559 | Charger | 526-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BCH001559 | Charger | 526-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BCH001559 | Charger | 526-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BCH001559 | Charger | 526-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BCH001559 | Charger | 526-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BCH001559 | Charger | 526-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.8 | amps |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BCH001559 | Charger | 526-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BCH001559 | Charger | 526-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BAT000530 | Battery | 526-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BAT000530 | Battery | 526-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BAT000530 | Battery | 526-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BAT000530 | Battery | 526-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BAT000530 | Battery | 526-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BAT000530 | Battery | 526-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BAT000530 | Battery | 526-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BAT000530 | Battery | 526-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BAT000530 | Battery | 526-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BAT000530 | Battery | 526-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BAT000530 | Battery | 526-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BAT000530 | Battery | 526-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 78 | °F |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | BAT000530 | Battery | 526-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | General Comments | | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | General Comments | | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | Ambient Temp | 78 | °F |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | General Comments | | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 13:59 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Amps A Ø | 260.0 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Operations Counter AF | 41 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | General Comments | fault on c phase cap bank on the line | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Fault Operations C Ø | 1 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Operations Counter AL | 41 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Operations This Read Vac | 1 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Fault Adjusted Amps C Phase V | 4.44 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | 9 Month Operations | 3 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Amps B Ø | 260.0 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Amps C Ø | 240.0 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | General Comments | | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | 9 Month Operations | 2 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Operations Counter AF | 227 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Operations Counter AL | 227 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Operations This Read Vac | 0 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Amps A Ø | 1.0 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Amps B Ø | 1.0 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Amps C Ø | 1.0 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Counter Readings | General Comments | | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Counter Readings | LTC As Found Counter | 183568 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Counter Readings | LTC As Left Counter | 183568 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Counter Readings | LTC Operations Since Last Insp | 423 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | LTCC000287 | LTCControl | 404-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | LTCC000287 | LTCControl | 404-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | LTCC000287 | LTCControl | 404-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | LTCC000287 | LTCControl | 404-1 | LTC Control Insp | LTC Output Voltage Level | 123.3 | VAC |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | LTCC000287 | LTCControl | 404-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | LTCC000287 | LTCControl | 404-1 | LTC Control Insp | General Comments | | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | LTCC000287 | LTCControl | 404-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | LTCC000287 | LTCControl | 404-1 | LTC Control Insp | All Connections OK? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 3.0 | psi |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Readings | Totalizer Meter Reading | .6650 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Readings | LTC Totalizer Reading | 6384.00 | kw |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Readings | General Comments | | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | BCH001329 | Charger | 404-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | BCH001329 | Charger | 404-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | BCH001329 | Charger | 404-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | BCH001329 | Charger | 404-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .8 | amps |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | BCH001329 | Charger | 404-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | BCH001329 | Charger | 404-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | BCH001329 | Charger | 404-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | BCH001329 | Charger | 404-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | General Comments | | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | General Comments | | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | General Comments | | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | Ambient Temp | 70 | °F |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/21/2023 13:46 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Operations Counter AF | 162 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Operations Counter AL | 162 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Operations This Read Vac | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Amps C Ø | 126.0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | 9 Month Operations | 4 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Amps A Ø | 137.0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Amps B Ø | 133.0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Amps A Ø | 0.0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Operations This Read Vac | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Operations Counter AL | 146 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Operations Counter AF | 146 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Amps C Ø | 0.0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Amps B Ø | 0.0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | 9 Month Operations | 2 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Operations Counter AF | 518 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Operations This Read Vac | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Operations Counter AL | 518 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | 9 Month Operations | 4 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Amps A Ø | 60.0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Amps B Ø | 100.0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Amps C Ø | 100.0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Amps A Ø | 390.0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Amps B Ø | 410.0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Amps C Ø | 411.0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Operations Counter AL | 197 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Operations Counter AF | 197 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | 9 Month Operations | 8 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000740 | LTCControl | 898-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000740 | LTCControl | 898-1 | LTC Control Insp | All Connections OK? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000740 | LTCControl | 898-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000740 | LTCControl | 898-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000740 | LTCControl | 898-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000740 | LTCControl | 898-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000740 | LTCControl | 898-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000740 | LTCControl | 898-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000740 | LTCControl | 898-1 | LTC Control Insp | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Readings | Totalizer Meter Reading | .4180 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 155.00 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Readings | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Readings | LTC Totalizer Reading | 3344.00 | kw |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 8000 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000073 | LTCControl | 898-2 | LTC Control Insp | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000073 | LTCControl | 898-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000073 | LTCControl | 898-2 | LTC Control Insp | All Connections OK? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000073 | LTCControl | 898-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000073 | LTCControl | 898-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000073 | LTCControl | 898-2 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000073 | LTCControl | 898-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000073 | LTCControl | 898-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000073 | LTCControl | 898-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 45 | °C |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Counter Readings | LTC Operations Since Last Insp | 437 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Counter Readings | LTC As Left Counter | 47326 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Counter Readings | LTC As Found Counter | 47326 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Counter Readings | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Readings | Winding Temp Max | 45 | °C |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Readings | Totalizer Meter Reading | .7020 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Readings | LTC Totalizer Reading | 10108.80 | kw |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Readings | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1500 | psi |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BCH001569 | Charger | 898-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BCH001569 | Charger | 898-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BCH001569 | Charger | 898-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BCH001569 | Charger | 898-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 4.4 | amps |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BCH001569 | Charger | 898-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BCH001569 | Charger | 898-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BCH001569 | Charger | 898-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BCH001569 | Charger | 898-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 66 | °F |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | General Comments | | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/21/2023 12:32 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | Ambient Temp | 66 | °F |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | 9 Month Operations | 5 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Amps A Ø | 130.0 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Amps B Ø | 124.0 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Amps C Ø | 141.0 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | General Comments | | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Operations Counter AF | 177 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Operations Counter AL | 177 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Operations This Read Vac | 4 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Switching Operations | 4 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | 9 Month Operations | 6 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Operations Counter AL | 185 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Operations Counter AF | 185 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | General Comments | | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Amps A Ø | 89.0 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Amps C Ø | 91.0 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Switching Operations | 5 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Operations This Read Vac | 5 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Amps B Ø | 96.0 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Counter Readings | LTC Operations Since Last Insp | 415 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Counter Readings | LTC As Left Counter | 242968 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Counter Readings | LTC As Found Counter | 242968 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Counter Readings | General Comments | | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | LTCC000969 | LTCControl | 586-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | LTCC000969 | LTCControl | 586-1 | LTC Control Insp | General Comments | | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | LTCC000969 | LTCControl | 586-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | LTCC000969 | LTCControl | 586-1 | LTC Control Insp | LTC Output Voltage Level | 124.2 | VAC |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | LTCC000969 | LTCControl | 586-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | LTCC000969 | LTCControl | 586-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | LTCC000969 | LTCControl | 586-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | LTCC000969 | LTCControl | 586-1 | LTC Control Insp | All Connections OK? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | LTCC000969 | LTCControl | 586-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Readings | General Comments | | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Readings | LTC Totalizer Reading | 890.88 | kw |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Readings | Totalizer Meter Reading | .2784 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BCH001299 | Charger | 586-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BCH001299 | Charger | 586-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BCH001299 | Charger | 586-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BCH001299 | Charger | 586-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BCH001299 | Charger | 586-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.0 | amps |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BCH001299 | Charger | 586-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BCH001299 | Charger | 586-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BCH001299 | Charger | 586-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BAT001376 | Battery | 586-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BAT001376 | Battery | 586-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BAT001376 | Battery | 586-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BAT001376 | Battery | 586-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BAT001376 | Battery | 586-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BAT001376 | Battery | 586-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BAT001376 | Battery | 586-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BAT001376 | Battery | 586-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BAT001376 | Battery | 586-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BAT001376 | Battery | 586-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BAT001376 | Battery | 586-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BAT001376 | Battery | 586-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | BAT001376 | Battery | 586-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Interruptrs/Puffrs Visual OK? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | General Comments | | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | General Comments | | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Ambient Temp | 70 | °F |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | General Comments | | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/21/2023 12:06 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Amps C Ø | 60.0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Amps B Ø | 60.0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Amps A Ø | 60.0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Switching Operations | 29 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Operations This Read Vac | 29 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Operations Counter AL | 99991 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | 9 Month Operations | 39 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Operations Counter AF | 99962 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | General Comments | problems with reclosure on ftc | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Switching Operations | 8 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Operations This Read Vac | 8 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Operations Counter AL | 93 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | 9 Month Operations | 21 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Operations Counter AF | 85 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | General Comments | | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | 9 Month Operations VCB New | 13 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Amps A Ø | 120.0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Amps B Ø | 80.0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Amps C Ø | 80.0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Operations This Read Vac | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Operations Counter AL | 173 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | 9 Month Operations | 1 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Amps A Ø | 70.0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Amps B Ø | 65.0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Operations Counter AF | 173 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Amps C Ø | 74.0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | General Comments | | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | 9 Month Operations | 1 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Amps A Ø | 100.0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Amps B Ø | 110.0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Amps C Ø | 77.0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Operations This Read Vac | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Operations Counter AL | 151 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Operations Counter AF | 151 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.3 | volts |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 10491 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Max Tap Position | 1L | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 11181 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 122.9 | volts |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.4 | volts |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 9215 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Operations Counter AF | 169 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Operations Counter AL | 169 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Operations This Read Vac | 24 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Fault Adjusted Amps C Phase V | 5.72 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Fault Operations A Ø | 8 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Fault Operations B Ø | 8 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Fault Operations C Ø | 8 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Fault Adjusted Amps B Phase V | 5.72 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Fault Adjusted Amps A Phase V | 5.72 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Amps C Ø | 30.0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Amps B Ø | 50.0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Amps A Ø | 40.0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | General Comments | | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | 9 Month Operations | 28 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .4880 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Readings | Oil Temp Max | 100 | °C |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 200.00 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1561.60 | kw |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Readings | General Comments | | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | 9 Month Operations | 2 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | General Comments | | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Amps A Ø | 515.0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Amps B Ø | 530.0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Amps C Ø | 545.0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Operations Counter AF | 179 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Operations Counter AL | 179 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Operations This Read Vac | 0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 217.50 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Operations This Read Vac | 0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Operations Counter AL | 225 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Amps C Ø | 0.0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Operations Counter AF | 225 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Amps B Ø | 0.0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Amps A Ø | 0.0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | General Comments | | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | 9 Month Operations | 2 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Counter Readings | LTC As Found Counter | 147449 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Counter Readings | LTC Operations Since Last Insp | 359 | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Counter Readings | General Comments | | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Counter Readings | LTC As Left Counter | 147452 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | General Comments | | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Operations Counter AF | 258 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Operations Counter AL | 258 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | 9 Month Operations | 2 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Amps C Ø | 0.0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Amps B Ø | 0.0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Amps A Ø | 0.0 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Min Tap Position | 15L | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Max Tap Position | 7L | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | General Comments | | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Current Tap Position | 12L | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Reg Output Voltage Level | 122.0 | volts |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Regulator As Left Counter | 32580 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Current Tap Position | 12L | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | General Comments | | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Min Tap Position | 15L | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Reg Output Voltage Level | 122.0 | volts |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Regulator As Left Counter | 36014 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | LTCC000971 | LTCControl | 860-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | LTCC000971 | LTCControl | 860-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | LTCC000971 | LTCControl | 860-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | LTCC000971 | LTCControl | 860-2 | LTC Control Insp | LTC Output Voltage Level | 123.2 | VAC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | LTCC000971 | LTCControl | 860-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | LTCC000971 | LTCControl | 860-2 | LTC Control Insp | General Comments | | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | LTCC000971 | LTCControl | 860-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | LTCC000971 | LTCControl | 860-2 | LTC Control Insp | All Connections OK? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Current Tap Position | 12L | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Max Tap Position | 8L | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | General Comments | | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Regulator As Left Counter | 27594 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Reg Output Voltage Level | 122.0 | volts |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Min Tap Position | 16L | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | General Comments | | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Readings | Winding Temp Present | 20 | °C |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Readings | Winding Temp Max | 30 | °C |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Readings | Totalizer Meter Reading | .4245 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Readings | Oil Temp Max | 30 | °C |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 2037.60 | kw |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Readings | General Comments | | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | General Comments | | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | General Comments | | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 4/21/2023 10:55 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 6000 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Readings | Totalizer Meter Reading | .6623 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Readings | LTC Totalizer Reading | 3973.80 | kw |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Readings | General Comments | | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Counter Readings | LTC Operations Since Last Insp | 30 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Counter Readings | LTC As Left Counter | 1179 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Counter Readings | LTC As Found Counter | 1179 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Counter Readings | General Comments | | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | LTCC000390 | LTCControl | 710-1 | LTC Control Insp | All Connections OK? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | LTCC000390 | LTCControl | 710-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | LTCC000390 | LTCControl | 710-1 | LTC Control Insp | General Comments | | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | LTCC000390 | LTCControl | 710-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | LTCC000390 | LTCControl | 710-1 | LTC Control Insp | LTC Output Voltage Level | 122.0 | VAC |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | LTCC000390 | LTCControl | 710-1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | LTCC000390 | LTCControl | 710-1 | LTC Control Insp | VRR Base Voltage AF | 123.0 | VAC |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | LTCC000390 | LTCControl | 710-1 | LTC Control Insp | VRR Base Voltage AL | 123.0 | VAC |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | LTCC000390 | LTCControl | 710-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | LTCC000300 | LTCControl | 710-3 | LTC Control Insp | VRR Base Voltage AF | 123.0 | VAC |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | LTCC000300 | LTCControl | 710-3 | LTC Control Insp | All Connections OK? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | LTCC000300 | LTCControl | 710-3 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | LTCC000300 | LTCControl | 710-3 | LTC Control Insp | General Comments | | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | LTCC000300 | LTCControl | 710-3 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | LTCC000300 | LTCControl | 710-3 | LTC Control Insp | LTC Output Voltage Level | 122.0 | VAC |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | LTCC000300 | LTCControl | 710-3 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | LTCC000300 | LTCControl | 710-3 | LTC Control Insp | VRR Base Voltage AL | 123.0 | VAC |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Readings | LTC Totalizer Reading | 0.00 | kw |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Readings | General Comments | | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Readings | Totalizer Meter Multiplier | 8000 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Counter Readings | General Comments | | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Counter Readings | LTC As Found Counter | 26068 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Counter Readings | LTC As Left Counter | 26068 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Counter Readings | LTC Operations Since Last Insp | 361 | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 30 | °C |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 30 | °C |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BCH001042 | Charger | 710-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BCH001042 | Charger | 710-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BCH001042 | Charger | 710-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BCH001042 | Charger | 710-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 3.4 | amps |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BCH001042 | Charger | 710-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BCH001042 | Charger | 710-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BCH001042 | Charger | 710-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | BCH001042 | Charger | 710-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | General Comments | | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | General Comments | | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | Ambient Temp | 65 | °F |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/21/2023 10:46 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | General Comments | | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | 9 Month Operations | 14 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | 9 Month Operations VCB New | 14 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Amps A Ø | 140.0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Amps B Ø | 120.0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Amps C Ø | 138.0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Operations This Read Vac | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | General Comments | | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Operations Counter AF | 250 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Operations Counter AL | 250 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Operations This Read Vac | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Amps C Ø | 0.0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Amps B Ø | 0.0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Amps A Ø | 0.0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | 9 Month Operations | 1 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | General Comments | | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Operations Counter AF | 254 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Operations Counter AL | 254 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Amps A Ø | 0.0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Amps B Ø | 0.0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Amps C Ø | 0.0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | 9 Month Operations | 2 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | General Comments | | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Operations Counter AF | 244 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Operations Counter AL | 244 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Operations This Read Vac | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Amps B Ø | 120.0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Amps A Ø | 141.0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Amps C Ø | 138.0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Switching Operations | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Operations Counter AL | 174 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | 9 Month Operations | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Operations Counter AF | 174 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | General Comments | | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Counter Readings | LTC Operations Since Last Insp | 334 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Counter Readings | General Comments | | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Counter Readings | LTC As Found Counter | 92805 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Counter Readings | LTC As Left Counter | 92805 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | LTCC000834 | LTCControl | 812-1 | LTC Control Insp | All Connections OK? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | LTCC000834 | LTCControl | 812-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | LTCC000834 | LTCControl | 812-1 | LTC Control Insp | General Comments | | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | LTCC000834 | LTCControl | 812-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | LTCC000834 | LTCControl | 812-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | LTCC000834 | LTCControl | 812-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | LTCC000834 | LTCControl | 812-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | LTCC000834 | LTCControl | 812-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Readings | Totalizer Meter Reading | .2920 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Readings | LTC Totalizer Reading | 4204.80 | kw |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Readings | General Comments | | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BAT001625 | Battery | 812-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BAT001625 | Battery | 812-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 67 | °F |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BAT001625 | Battery | 812-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BAT001625 | Battery | 812-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BAT001625 | Battery | 812-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BAT001625 | Battery | 812-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BAT001625 | Battery | 812-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BAT001625 | Battery | 812-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BAT001625 | Battery | 812-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BAT001625 | Battery | 812-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BAT001625 | Battery | 812-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BAT001625 | Battery | 812-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BAT001625 | Battery | 812-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BCH001545 | Charger | 812-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BCH001545 | Charger | 812-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BCH001545 | Charger | 812-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BCH001545 | Charger | 812-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BCH001545 | Charger | 812-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 3.2 | amps |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BCH001545 | Charger | 812-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BCH001545 | Charger | 812-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | BCH001545 | Charger | 812-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Follow-up Action Required? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | General Comments | CHAINLINK TIED TO BACK CORNERS RAILROAD SIDE OF SUB | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | General Comments | | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | YD000475 | Yard | 812-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | YD000475 | Yard | 812-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | YD000475 | Yard | 812-Yard | Yard Patrol Inspection | General Comments | | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | YD000475 | Yard | 812-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | YD000475 | Yard | 812-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | YD000475 | Yard | 812-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | YD000475 | Yard | 812-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | YD000475 | Yard | 812-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | YD000475 | Yard | 812-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | YD000475 | Yard | 812-Yard | Yard Patrol Inspection | Ambient Temp | 67 | °F |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | YD000475 | Yard | 812-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/21/2023 10:44 | Distribution | Eastland Quarterly Inspection | YD000475 | Yard | 812-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Amps C Ø | 62.0 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Amps B Ø | 38.0 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | 9 Month Operations | 2 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Amps A Ø | 20.0 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | General Comments | | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Operations Counter AF | 250 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Operations Counter AL | 252 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Operations This Read Vac | 2 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Switching Operations | 2 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Amps C Ø | 87.0 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Fault Adjusted Amps A Phase V | 29.12 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Fault Operations A Ø | 3 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Fault Operations Ground | 0 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Follow-up Action Required? | n | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | General Comments | | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Maintenance Operations | 0 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Operations Counter AF | 394 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Operations Counter AL | 394 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Operations This Read Vac | 4 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Switching Operations | 1 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Unknown Operations | 0 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | 9 Month Operations | 9 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Amps A Ø | 67.0 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Amps B Ø | 60.0 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | General Comments | | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 125.0 | volts |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 14844 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 12738 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.0 | volts |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 15055 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .5290 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1269.60 | kw |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Readings | General Comments | | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Readings | Oil Temp Max | 55 | °C |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 55.00 | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 66 | °F |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | BCH001174 | Charger | 745-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | BCH001174 | Charger | 745-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | BCH001174 | Charger | 745-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | BCH001174 | Charger | 745-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.4 | amps |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | BCH001174 | Charger | 745-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | BCH001174 | Charger | 745-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | BCH001174 | Charger | 745-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | BCH001174 | Charger | 745-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | General Comments | | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | General Comments | | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | General Comments | | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | Ambient Temp | 66 | °F |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/21/2023 9:53 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Patrol Inspection | General Comments | | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Operations This Read Vac | 0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Switching Operations | 0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Unknown Operations | 0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Operations Counter AL | 164 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Operations Counter AF | 164 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Maintenance Operations | 0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | 9 Month Operations | 3 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | General Comments | | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Amps A Ø | 12.0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Amps B Ø | 15.0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Follow-up Action Required? | n | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Fault Operations Ground | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Amps C Ø | 9.0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Patrol Inspection | General Comments | | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Operations Counter AF | 208 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Fault Adjusted Amps A Phase V | 5.07 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Amps C Ø | 47.0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Amps B Ø | 43.0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Amps A Ø | 33.0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Maintenance Operations | 0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | General Comments | | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Follow-up Action Required? | n | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Fault Operations Ground | 0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | 9 Month Operations | 6 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Unknown Operations | 0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Switching Operations | 1 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Operations This Read Vac | 2 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Operations Counter AL | 208 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Maintenance Operations | 0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Operations Counter AF | 189 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Operations Counter AL | 189 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Operations This Read Vac | 0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | General Comments | | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Switching Operations | 0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Unknown Operations | 0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Follow-up Action Required? | n | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Fault Operations Ground | 0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Amps C Ø | 33.0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Amps B Ø | 34.0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Amps A Ø | 33.0 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | 9 Month Operations | 1 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Patrol Inspection | General Comments | | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 11760 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 9178 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.4 | volts |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Max Tap Position | 5L | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.5 | volts |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 11173 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Readings | Oil Temp Max | 28 | °C |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1776.00 | kw |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Readings | Oil Temp Present | 26 | °C |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Readings | General Comments | | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .1850 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Readings | Winding Temp Max | 31 | °C |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Readings | Winding Temp Present | 30 | °C |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 20.0 | VDC |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 24.0 | VDC |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 81 | °F |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BCH000612 | Charger | 731-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BCH000612 | Charger | 731-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BCH000612 | Charger | 731-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.9 | amps |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BCH000612 | Charger | 731-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BCH000612 | Charger | 731-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | BCH000612 | Charger | 731-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | General Comments | no spare fuses | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | General Comments | | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | Ambient Temp | 81 | °F |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | General Comments | | |
| 4/20/2023 13:58 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 207 | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0.0 | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 0 | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 7 | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | General Comments | no amp meter. Can not read B phase counter | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | Operations Counter | 0 | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 0 | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 0 | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0.0 | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 0 | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | General Comments | no amp gauge | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | Operations Counter | 232 | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 122.6 | volts |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 80354 | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Min Tap Position | 2L | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 102814 | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.3 | volts |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 122.9 | volts |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 91179 | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .3040 | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Readings | Oil Temp Present | 37 | °C |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 364.80 | kw |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Readings | General Comments | | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 10.00 | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | General Comments | | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | General Comments | | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | General Comments | | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/20/2023 11:50 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | Ambient Temp | 79 | °F |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Amps A Ø | 300.0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | 9 Month Operations | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Amps B Ø | 315.0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Amps C Ø | 275.0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Follow-up Action Required? | n | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | General Comments | | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Maintenance Operations | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Operations Counter AF | 396 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Operations Counter AL | 396 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Switching Operations | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Unknown Operations | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | General Comments | | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Unknown Operations | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Switching Operations | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Operations This Read Vac | 44 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Operations Counter AL | 532 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Operations Counter AF | 532 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Maintenance Operations | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | General Comments | | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Follow-up Action Required? | n | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Fault Operations Ground | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Fault Operations C Ø | 22 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Fault Operations B Ø | 22 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Fault Adjusted Amps C Phase V | 268.43 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Fault Adjusted Amps B Phase V | 268.43 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Amps C Ø | 55.0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Amps B Ø | 40.0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Amps A Ø | 55.0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | 9 Month Operations | 50 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | General Comments | | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Amps C Ø | 75.0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | 9 Month Operations | 2 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Amps A Ø | 75.0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Amps B Ø | 80.0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Unknown Operations | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Fault Operations Ground | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Follow-up Action Required? | n | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Switching Operations | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Operations This Read Vac | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Operations Counter AL | 604 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | General Comments | | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Maintenance Operations | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Operations Counter AF | 604 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | General Comments | | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Amps C Ø | 40.0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Amps B Ø | 60.0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Amps A Ø | 65.0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | 9 Month Operations | 2 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Unknown Operations | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Switching Operations | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Operations This Read Vac | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Operations Counter AL | 510 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Operations Counter AF | 510 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Maintenance Operations | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | General Comments | | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Follow-up Action Required? | n | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Fault Operations Ground | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Patrol Inspection | General Comments | | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Maintenance Operations | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Operations Counter AF | 517 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Operations Counter AL | 517 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Operations This Read Vac | 8 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Switching Operations | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Unknown Operations | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Fault Adjusted Amps C Phase V | 48.81 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | 9 Month Operations | 12 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Amps A Ø | 90.0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Amps B Ø | 130.0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Amps C Ø | 110.0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Fault Adjusted Amps B Phase V | 48.81 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | General Comments | | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Follow-up Action Required? | n | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Fault Operations Ground | 0 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Fault Operations C Ø | 4 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Fault Operations B Ø | 4 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | General Comments | | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | LTCC000854 | LTCControl | 532-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | LTCC000854 | LTCControl | 532-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | LTCC000854 | LTCControl | 532-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | LTCC000854 | LTCControl | 532-1 | LTC Control Insp | All Connections OK? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | LTCC000854 | LTCControl | 532-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | LTCC000854 | LTCControl | 532-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | LTCC000854 | LTCControl | 532-1 | LTC Control Insp | General Comments | | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | LTCC000854 | LTCControl | 532-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Counter Readings | LTC As Left Counter | 75382 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Counter Readings | LTC As Found Counter | 75382 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Counter Readings | General Comments | | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Counter Readings | LTC Operations Since Last Insp | 324 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Readings | General Comments | | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Readings | Totalizer Meter Reading | .5130 | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Readings | LTC Totalizer Reading | 12312.00 | kw |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BCH001104 | Charger | 930-Offline-Distribution | Battery Charger Patrol Insp | General Comments | | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BCH001104 | Charger | 930-Offline-Distribution | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BCH001104 | Charger | 930-Offline-Distribution | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BCH001104 | Charger | 930-Offline-Distribution | Battery Charger Patrol Insp | Battery Charger Current | 2.2 | amps |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BCH001104 | Charger | 930-Offline-Distribution | Battery Charger Patrol Insp | As Left Float Voltage | 133.0 | VDC |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BCH001104 | Charger | 930-Offline-Distribution | Battery Charger Patrol Insp | As Found Float Voltage | 133.0 | VDC |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BCH001104 | Charger | 930-Offline-Distribution | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 68 | °F |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | General Comments | | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | MOD Motor Jaw Coupling | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Moisture and Leak Free? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | General Comments | | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | MOD Cabinet Heater functional? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | MOD Cabinet Internals Clean? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | General Comments | | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | General Comments | | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/20/2023 7:58 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | 9 Month Operations | 8 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Switching Operations | 4 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Operations This Read Vac | 4 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Operations Counter AL | 164 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Operations Counter AF | 164 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Amps C Ø | 38.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Amps B Ø | 41.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Amps A Ø | 44.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Switching Operations | 2 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Operations This Read Vac | 2 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Operations Counter AL | 96 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | 9 Month Operations | 2 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Operations Counter AF | 96 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Amps C Ø | 250.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Amps B Ø | 220.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Amps A Ø | 255.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | PF000351 | PowerFuse | TA-12KV TR 4 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | PF000351 | PowerFuse | TA-12KV TR 4 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | PF000351 | PowerFuse | TA-12KV TR 4 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | PF000352 | PowerFuse | TA-STA SER NO 4 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | PF000352 | PowerFuse | TA-STA SER NO 4 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | PF000352 | PowerFuse | TA-STA SER NO 4 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Counter Readings | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Counter Readings | LTC As Found Counter | 237424 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Counter Readings | LTC As Left Counter | 237424 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Counter Readings | LTC Current Tap Position | 12L | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Counter Readings | LTC Max Tap Position | 8L | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Counter Readings | LTC Operations Since Last Insp | 105 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCC000337 | LTCControl | TA-TRANS 4 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCC000337 | LTCControl | TA-TRANS 4 | LTC Control Insp | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCC000337 | LTCControl | TA-TRANS 4 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Readings | X3 Winding Temp Present | 40 | °C |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Readings | X3 Winding Temp Max | 45 | °C |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Readings | X2 Winding Temp Present | 40 | °C |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Readings | X2 Winding Temp Max | 45 | °C |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Readings | X1 Winding Temp Present | 40 | °C |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Readings | X1 Winding Temp Max | 65 | °C |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Readings | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 750 | psi |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .7 | psi |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | PF000350 | PowerFuse | TA-12KV TR 3 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | PF000350 | PowerFuse | TA-12KV TR 3 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | PF000350 | PowerFuse | TA-12KV TR 3 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | PF000353 | PowerFuse | TA-STA SER NO 3 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | PF000353 | PowerFuse | TA-STA SER NO 3 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | PF000353 | PowerFuse | TA-STA SER NO 3 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCC000335 | LTCControl | TA-TRANS 3 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCC000335 | LTCControl | TA-TRANS 3 | LTC Control Insp | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCC000335 | LTCControl | TA-TRANS 3 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Counter Readings | LTC Operations Since Last Insp | 1422 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Counter Readings | LTC Current Tap Position | 10L | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Counter Readings | LTC As Left Counter | 74956 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Counter Readings | LTC As Found Counter | 74956 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Counter Readings | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Readings | Oil Temp Present | 50 | °C |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Readings | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Max | 65 | °C |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Present | 60 | °C |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Max | 65 | °C |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Present | 60 | °C |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | General Comments | TR in vacuum | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.7 | psi |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | PF000355 | PowerFuse | TA-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | PF000355 | PowerFuse | TA-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | PF000355 | PowerFuse | TA-12KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | PF000354 | PowerFuse | TA-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | PF000354 | PowerFuse | TA-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | PF000354 | PowerFuse | TA-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCC000336 | LTCControl | TA-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCC000336 | LTCControl | TA-TRANS 1 | LTC Control Insp | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCC000336 | LTCControl | TA-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 38 | °C |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 42 | °C |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 554 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 32242 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 32242 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Counter Readings | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 45 | °C |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 40 | °C |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 40 | °C |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 38 | °C |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 50 | °C |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 45 | °C |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 2000 | psi |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Switching Operations | 1 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Amps C Ø | 0.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Operations Counter AF | 66 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Operations Counter AL | 66 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Operations This Read Vac | 1 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Amps B Ø | 0.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Amps A Ø | 0.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | 9 Month Operations | 1 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Vacuum Monitor Self-Check OK? | na | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Vacuum Monitor Antenna Paint | NA | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Switching Operations | 5 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Operations This Read Vac | 5 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Operations Counter AL | 97 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Operations Counter AF | 97 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Amps C Ø | 109.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Amps A Ø | 82.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | 9 Month Operations | 5 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Amps B Ø | 71.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | 9 Month Operations | 10 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Amps C Ø | 120.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Amps B Ø | 107.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Switching Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Operations This Read Vac | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Operations Counter AL | 75 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Operations Counter AF | 75 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Amps A Ø | 125.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Switching Operations | 1 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Operations This Read Vac | 1 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Operations Counter AL | 58 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Operations Counter AF | 58 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Amps C Ø | 236.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Amps B Ø | 259.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Amps A Ø | 245.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | 9 Month Operations | 1 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | 9 Month Operations | 10 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Amps A Ø | 88.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Amps B Ø | 88.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Amps C Ø | 100.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Switching Operations | 10 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Operations This Read Vac | 10 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Operations Counter AL | 105 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Operations Counter AF | 105 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Amps C Ø | 104.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Amps B Ø | 131.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Amps A Ø | 109.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | 9 Month Operations | 2 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Operations Counter AF | 126 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Operations Counter AL | 126 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Operations This Read Vac | 2 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Switching Operations | 2 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Operations Counter AF | 166 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Operations Counter AL | 166 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Operations This Read Vac | 1 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Switching Operations | 1 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Amps C Ø | 0.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Amps B Ø | 0.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Amps A Ø | 0.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | 9 Month Operations | 1 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Amps C Ø | 33.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Amps B Ø | 36.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Amps A Ø | 41.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | 9 Month Operations | 13 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Switching Operations | 5 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Operations Counter AF | 142 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Operations Counter AL | 142 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Operations This Read Vac | 5 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Amps C Ø | 456.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Operations Counter AF | 75 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Operations Counter AL | 75 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Operations This Read Vac | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Switching Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Amps B Ø | 453.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Amps A Ø | 451.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | 9 Month Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Operations Counter AL | 87 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Operations This Read Vac | 4 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Switching Operations | 4 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | 9 Month Operations | 4 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Operations Counter AF | 87 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Amps C Ø | 143.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Amps B Ø | 140.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Amps A Ø | 130.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | General Comments | DNO | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Amps A Ø | 0.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Amps B Ø | 0.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Amps C Ø | 0.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | 9 Month Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Operations Counter AF | 63 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Operations Counter AL | 63 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Operations This Read Vac | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Switching Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Amps C Ø | 251.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Amps B Ø | 254.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Amps A Ø | 259.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | 9 Month Operations | 2 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Switching Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Operations This Read Vac | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Operations Counter AL | 70 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Operations Counter AF | 70 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Amps A Ø | 69.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Amps B Ø | 67.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Switching Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Operations This Read Vac | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Operations Counter AL | 74 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Operations Counter AF | 74 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Amps C Ø | 71.0 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | 9 Month Operations | 2 | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 16:15 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Operations This Read Vac | 5 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Operations Counter AL | 1211 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Operations Counter AF | 1211 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Amps C Ø | 0.0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Amps B Ø | 0.0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Amps A Ø | 0.0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Maintenance Operations | 5 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | General Comments | | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | 9 Month Operations | 9 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Switching Operations | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Patrol Inspection | General Comments | ok | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Switching Operations | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Operations This Read Vac | 15 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Fault Adjusted Amps B Phase V | 55.90 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Fault Adjusted Amps A Phase V | 55.90 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Fault Adjusted Amps C Phase V | 55.90 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Fault Operations A Ø | 5 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Fault Operations B Ø | 5 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Fault Operations C Ø | 5 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | General Comments | | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Amps C Ø | 79.0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Operations Counter AF | 679 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Operations Counter AL | 679 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Amps B Ø | 80.0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | 9 Month Operations | 15 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Amps A Ø | 70.0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Amps A Ø | 60.0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Amps B Ø | 60.0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Amps C Ø | 60.0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | General Comments | | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Operations Counter AF | 110 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Operations Counter AL | 110 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Operations This Read Vac | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Switching Operations | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | 9 Month Operations VCB New | 30 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | 9 Month Operations | 30 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | 9 Month Operations | 18 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | 9 Month Operations VCB New | 18 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Switching Operations | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Operations This Read Vac | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Amps A Ø | 100.0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Operations Counter AL | 405 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Operations Counter AF | 405 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | General Comments | | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Amps C Ø | 110.0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Amps B Ø | 94.0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | 9 Month Operations VCB New | 24 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | 9 Month Operations | 24 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Amps A Ø | 100.0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Amps B Ø | 110.0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Amps C Ø | 115.0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | General Comments | | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Operations Counter AF | 8 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Operations Counter AL | 8 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Operations This Read Vac | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Switching Operations | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Amps C Ø | 360.0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Amps B Ø | 345.0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Amps A Ø | 350.0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | 9 Month Operations VCB New | 22 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | 9 Month Operations | 22 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Operations Counter AL | 245 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Operations Counter AF | 245 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | General Comments | | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | PF000196 | PowerFuse | LO-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | PF000196 | PowerFuse | LO-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | PF000196 | PowerFuse | LO-12KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | PF000195 | PowerFuse | LO-STA SER NO 2 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | PF000195 | PowerFuse | LO-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | PF000195 | PowerFuse | LO-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Counter Readings | General Comments | | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 23 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 26761 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 26761 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 65 | °C |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 55 | °C |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 55 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 45 | °C |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 50 | °C |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 45 | °C |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | General Comments | | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | BAT000887 | Battery | LO-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | BAT000887 | Battery | LO-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | BAT000887 | Battery | LO-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | BAT000887 | Battery | LO-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | BAT000887 | Battery | LO-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | BAT000887 | Battery | LO-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | BAT000887 | Battery | LO-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | BAT000887 | Battery | LO-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | BAT000887 | Battery | LO-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | BAT000887 | Battery | LO-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | BAT000887 | Battery | LO-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | BAT000887 | Battery | LO-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | BCH001596 | Charger | LO-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | BCH001596 | Charger | LO-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.6 | VDC |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | BCH001596 | Charger | LO-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.6 | VDC |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | BCH001596 | Charger | LO-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.5 | amps |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | BCH001596 | Charger | LO-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | BCH001596 | Charger | LO-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | BCH001596 | Charger | LO-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | BCH001596 | Charger | LO-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | General Comments | | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Restroom Clean & OK? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | General Comments | | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Ambient Temp | 65 | °F |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | General Comments | | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/19/2023 12:12 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Amps C Ø | 15.0 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Amps B Ø | 25.0 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Amps A Ø | 25.0 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | 9 Month Operations VCB New | 2 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Switching Operations | 0 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Operations This Read Vac | 0 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Operations Counter AL | 200 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Operations Counter AF | 200 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | General Comments | | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | 9 Month Operations | 2 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Operations Counter AL | 204 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Operations This Read Vac | 0 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Switching Operations | 0 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Operations Counter AF | 204 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | General Comments | | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | 9 Month Operations | 2 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Amps A Ø | 100.0 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Amps B Ø | 95.0 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Amps C Ø | 80.0 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 60309 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 119.0 | volts |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 119.0 | volts |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 53998 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 60144 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 119.0 | volts |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 2.2785 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 2734.20 | kw |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Readings | General Comments | | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | LTCC000110 | LTCControl | 607-2 | LTC Control Insp | All Connections OK? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | LTCC000110 | LTCControl | 607-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | LTCC000110 | LTCControl | 607-2 | LTC Control Insp | General Comments | | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | LTCC000110 | LTCControl | 607-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | LTCC000110 | LTCControl | 607-2 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | LTCC000110 | LTCControl | 607-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | LTCC000110 | LTCControl | 607-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | LTCC000110 | LTCControl | 607-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Counter Readings | General Comments | | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Counter Readings | LTC As Found Counter | 266357 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Counter Readings | LTC As Left Counter | 266357 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Counter Readings | LTC Operations Since Last Insp | 487 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Readings | Totalizer Meter Reading | .5840 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Readings | Oil Temp Present | 15 | °C |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Readings | Oil Temp Max | 15 | °C |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Readings | LTC Totalizer Reading | 5606.40 | kw |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Readings | General Comments | | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 45 | °F |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BCH001249 | Charger | 607-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BCH001249 | Charger | 607-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BCH001249 | Charger | 607-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BCH001249 | Charger | 607-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.2 | amps |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BCH001249 | Charger | 607-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BCH001249 | Charger | 607-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | BCH001249 | Charger | 607-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | General Comments | | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | General Comments | | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | General Comments | | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/19/2023 11:21 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Amps C Ø | 144.0 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Amps B Ø | 174.0 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Amps A Ø | 110.0 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Operations Counter | 188 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Amps C Ø | 82.0 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Amps B Ø | 93.0 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Amps A Ø | 88.0 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Operations Counter | 347 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Switching Operations | 0 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Operations This Read Vac | 0 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Operations Counter AL | 340 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Amps C Ø | 51.0 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Amps B Ø | 53.0 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Amps A Ø | 51.0 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | General Comments | | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Operations Counter AF | 340 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | 9 Month Operations | 1 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | General Comments | | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Operations Counter AF | 332 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Amps C Ø | 41.0 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Amps B Ø | 40.0 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Operations Counter AL | 332 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Amps A Ø | 40.0 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | 9 Month Operations | 1 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Switching Operations | 0 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Operations This Read Vac | 0 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Current Tap Position | 11L | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 70121 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 118.9 | volts |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Max Tap Position | 8L | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Max Tap Position | 5L | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 119.4 | volts |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 71392 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 73638 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 120.0 | volts |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Max Tap Position | 6L | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Current Tap Position | 9L | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .4590 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1600 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Readings | Oil Temp Max | 58 | °C |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 734.40 | kw |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Readings | General Comments | | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 130.00 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | LTCC000935 | LTCControl | 677-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | LTCC000935 | LTCControl | 677-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | LTCC000935 | LTCControl | 677-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | LTCC000935 | LTCControl | 677-2 | LTC Control Insp | LTC Output Voltage Level | 122.9 | VAC |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | LTCC000935 | LTCControl | 677-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | LTCC000935 | LTCControl | 677-2 | LTC Control Insp | General Comments | | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | LTCC000935 | LTCControl | 677-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | LTCC000935 | LTCControl | 677-2 | LTC Control Insp | All Connections OK? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Counter Readings | LTC As Left Counter | 38912 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Counter Readings | LTC As Found Counter | 38912 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Counter Readings | General Comments | | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Counter Readings | LTC Operations Since Last Insp | 403 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Counter Readings | LTC Min Tap Position | 8L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Readings | Totalizer Meter Reading | .7008 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Readings | General Comments | | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Readings | LTC Totalizer Reading | 6727.68 | kw |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | BCH001304 | Charger | 677-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | BCH001304 | Charger | 677-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | BCH001304 | Charger | 677-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | BCH001304 | Charger | 677-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.1 | amps |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | BCH001304 | Charger | 677-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | BCH001304 | Charger | 677-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | BCH001304 | Charger | 677-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | BCH001304 | Charger | 677-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | General Comments | | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | General Comments | | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | General Comments | | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/19/2023 9:50 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Amps C Ø | 95.0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Amps B Ø | 105.0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Amps A Ø | 95.0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Switching Operations | 1 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Operations This Read Vac | 1 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | 9 Month Operations | 1 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Operations Counter AL | 153 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Operations Counter AF | 152 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Switching Operations | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Operations This Read Vac | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Operations Counter AL | 200 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Operations Counter AF | 200 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | 9 Month Operations | 2 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Amps A Ø | 70.0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Amps B Ø | 60.0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Amps C Ø | 60.0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCC000753 | LTCControl | 507-2 | LTC Control Insp | All Connections OK? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCC000753 | LTCControl | 507-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCC000753 | LTCControl | 507-2 | LTC Control Insp | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCC000753 | LTCControl | 507-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCC000753 | LTCControl | 507-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCC000753 | LTCControl | 507-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCC000753 | LTCControl | 507-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCC000753 | LTCControl | 507-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Counter Readings | LTC As Found Counter | 13682 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Counter Readings | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Counter Readings | LTC As Left Counter | 13682 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Counter Readings | LTC Operations Since Last Insp | 358 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 20 | °C |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 25 | °C |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Readings | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Readings | LTC Totalizer Reading | 5846.40 | kw |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Readings | Totalizer Meter Reading | .4060 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Readings | Winding Temp Present | 25 | °C |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 2100 | psi |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCC000933 | LTCControl | 507-1 | LTC Control Insp | All Connections OK? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCC000933 | LTCControl | 507-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCC000933 | LTCControl | 507-1 | LTC Control Insp | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCC000933 | LTCControl | 507-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCC000933 | LTCControl | 507-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCC000933 | LTCControl | 507-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCC000933 | LTCControl | 507-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | LTCC000933 | LTCControl | 507-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Readings | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Readings | LTC Totalizer Reading | 4492.80 | kw |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Readings | Oil Temp Max | 25 | °C |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Readings | Totalizer Meter Reading | .3120 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Readings | Winding Temp Max | 35 | °C |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Readings | Winding Temp Present | 35 | °C |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Counter Readings | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Counter Readings | LTC As Found Counter | 62849 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Counter Readings | LTC As Left Counter | 62849 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Counter Readings | LTC Operations Since Last Insp | 292 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Readings | Switching Operations | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Readings | Operations This Read SF6 | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Readings | Operations Counter AL | 73 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Readings | Fault Operations | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Readings | Operations Counter AF | 72 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Readings | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Operations Counter AL | 202 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Operations Counter AF | 202 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Switching Operations | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Operations This Read Vac | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Amps C Ø | 90.0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Amps B Ø | 90.0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Amps A Ø | 95.0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | 9 Month Operations | 2 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | 9 Month Operations | 2 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Switching Operations | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Amps A Ø | 70.0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Operations Counter AF | 156 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Operations Counter AL | 156 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Operations This Read Vac | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Amps C Ø | 60.0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Amps B Ø | 55.0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | 9 Month Operations | 1 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Switching Operations | 1 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Operations This Read Vac | 1 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Operations Counter AL | 187 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Operations Counter AF | 186 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Amps B Ø | 125.0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Amps A Ø | 150.0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Amps C Ø | 150.0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | 9 Month Operations | 1 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Operations Counter AF | 160 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Operations Counter AL | 161 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Operations This Read Vac | 1 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Switching Operations | 1 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Amps C Ø | 85.0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Unknown Operations | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Switching Operations | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Operations This Read Vac | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Operations Counter AL | 192 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Operations Counter AF | 192 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Fault Operations Ground | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | 9 Month Operations | 2 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Amps A Ø | 80.0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Amps B Ø | 80.0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Unknown Operations | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Switching Operations | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Operations Counter AL | 113 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Operations Counter AF | 113 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | General Comments | | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Amps C Ø | 320.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Amps B Ø | 320.0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Amps A Ø | 320.0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | 9 Month Operations | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Operations Counter AL | 361 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Operations This Read Vac | 4 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Operations Counter AF | 357 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | General Comments | | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Switching Operations | 4 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Unknown Operations | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Amps A Ø | 110.0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Amps B Ø | 110.0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Amps C Ø | 100.0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | 9 Month Operations | 4 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | General Comments | | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Amps C Ø | 40.0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Unknown Operations | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Switching Operations | 4 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Operations This Read Vac | 4 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Operations Counter AL | 423 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Amps B Ø | 40.0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Amps A Ø | 40.0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Operations Counter AF | 419 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | 9 Month Operations | 4 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Operations This Read Vac | 4 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Switching Operations | 4 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Unknown Operations | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Operations Counter AL | 437 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Operations Counter AF | 433 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Amps C Ø | 105.0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Amps B Ø | 110.0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Amps A Ø | 105.0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | General Comments | | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | 9 Month Operations | 4 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | General Comments | | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Operations Counter AF | 195 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Operations Counter AL | 195 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Fault Operations B Ø | 5 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Operations This Read Vac | 9 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Switching Operations | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Unknown Operations | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Fault Operations A Ø | 4 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Fault Adjusted Amps B Phase V | 31.35 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Fault Adjusted Amps A Phase V | 25.08 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Amps C Ø | 33.0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Amps B Ø | 35.0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Amps A Ø | 32.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | 9 Month Operations | 9 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | 9 Month Operations | 6 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Unknown Operations | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Switching Operations | 4 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Operations This Read Vac | 4 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Operations Counter AL | 334 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Operations Counter AF | 330 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | General Comments | | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Amps A Ø | 160.0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Amps B Ø | 160.0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Amps C Ø | 160.0 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Readings | Non LTC Totalizer Reading | 716.16 | kw |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Readings | General Comments | | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Readings | Totalizer Meter Reading | .2238 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Counter Readings | LTC Operations Since Last Insp | 268 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Counter Readings | LTC Max Tap Position | 8L | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Counter Readings | LTC Current Tap Position | 10L | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Counter Readings | LTC As Left Counter | 96277 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Counter Readings | LTC As Found Counter | 96277 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Counter Readings | General Comments | | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | LTCC000972 | LTCControl | 582-2 | LTC Control Insp | All Connections OK? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | LTCC000972 | LTCControl | 582-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | LTCC000972 | LTCControl | 582-2 | LTC Control Insp | General Comments | | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | LTCC000972 | LTCControl | 582-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | LTCC000972 | LTCControl | 582-2 | LTC Control Insp | LTC Output Voltage Level | 123.5 | VAC |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | LTCC000972 | LTCControl | 582-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | LTCC000972 | LTCControl | 582-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | LTCC000972 | LTCControl | 582-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Readings | General Comments | | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Readings | LTC Totalizer Reading | 6458.40 | kw |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 55.00 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Readings | Winding Temp Max | 50 | °C |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Readings | Totalizer Meter Reading | .3588 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 68 | °F |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BCH000609 | Charger | 582-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BCH000609 | Charger | 582-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.0 | amps |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BCH000609 | Charger | 582-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BCH000609 | Charger | 582-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BCH000609 | Charger | 582-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | BCH000609 | Charger | 582-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | General Comments | | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | General Comments | | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | General Comments | | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | Ambient Temp | 68 | °F |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 9632 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Max Tap Position | 7L | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Current Tap Position | 9L | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Max Tap Position | 8L | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Min Tap Position | 15L | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Current Tap Position | 10L | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.7 | volts |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 9476 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Current Tap Position | 9L | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Max Tap Position | 5L | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Min Tap Position | 13L | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 11027 | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/18/2023 15:34 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | General Comments | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | SF6 Pressure Indicator | good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Ambient Temperature | 55 | °F |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Readings | Switching Operations | 1 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Readings | Fault Operations | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Readings | Operations Counter AL | 68 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Readings | Operations Counter AF | 67 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Readings | Num Operations Last 9 Months | 1 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Readings | Maintenance Operations | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Readings | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Readings | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Readings | Operations This Read SF6 | 1 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Ambient Temperature | 55 | °F |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | General Comments | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | SF6 Pressure Indicator | good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Patrol Inspection | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 68 | °F |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BCH001189 | Charger | 507-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BCH001189 | Charger | 507-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BCH001189 | Charger | 507-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BCH001189 | Charger | 507-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BCH001189 | Charger | 507-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.7 | amps |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BCH001189 | Charger | 507-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.0 | VDC |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BCH001189 | Charger | 507-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.0 | VDC |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | BCH001189 | Charger | 507-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Ambient Temp | 65 | °F |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | General Comments | | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 4/19/2023 8:44 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.2138 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Readings | LTC Totalizer Reading | 5826.24 | kw |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Readings | General Comments | | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Operations Counter | 13 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Amps C Ø | 35.0 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Amps B Ø | 34.0 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Amps A Ø | 33.0 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Amps B Ø | 10.0 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Amps A Ø | 12.0 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | 9 Month Operations | 4 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | 9 Month Operations VCB New | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Amps C Ø | 15.0 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Operations Counter AL | 336 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Switching Operations | 4 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Operations This Read Vac | 4 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Unknown Operations | 0 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | General Comments | | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Operations Counter AF | 336 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Amps A Ø | 10.0 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Amps B Ø | 12.0 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Amps C Ø | 14.0 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | General Comments | | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Operations Counter AF | 19 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Operations Counter AL | 19 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Operations This Read Vac | 4 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Switching Operations | 4 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Unknown Operations | 0 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | 9 Month Operations | 4 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | LTCC000395 | LTCControl | 587-1 | LTC Control Insp | All Connections OK? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | LTCC000395 | LTCControl | 587-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | LTCC000395 | LTCControl | 587-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | LTCC000395 | LTCControl | 587-1 | LTC Control Insp | General Comments | | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | LTCC000395 | LTCControl | 587-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | LTCC000395 | LTCControl | 587-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | LTCC000395 | LTCControl | 587-1 | LTC Control Insp | LTC Output Voltage Level | 124.2 | VAC |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | LTCC000395 | LTCControl | 587-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Counter Readings | General Comments | | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Counter Readings | LTC As Found Counter | 1444 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Counter Readings | LTC As Left Counter | 1444 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Counter Readings | LTC Operations Since Last Insp | 195 | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 59 | °F |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | BCH001579 | Charger | 587-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | BCH001579 | Charger | 587-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | BCH001579 | Charger | 587-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | BCH001579 | Charger | 587-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .2 | amps |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | BCH001579 | Charger | 587-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | BCH001579 | Charger | 587-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | BCH001579 | Charger | 587-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | BCH001579 | Charger | 587-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | General Comments | | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | General Comments | | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | Ambient Temp | 59 | °F |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | General Comments | | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/18/2023 12:16 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Counter Readings | General Comments | Tap changer not working, checked overloads and fuses. overloads not tripped and fuses are good. Notified SC&M | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 337703 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 337703 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 5 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 5 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 5 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Unknown Operations | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Switching Operations | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Operations This Read AM | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Operations Counter AL | 413 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Operations Counter AF | 413 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | General Comments | | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Amps C Ø | 50.0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Amps B Ø | 75.0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Amps A Ø | 60.0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | 9 Months Operations | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Operations Counter AF | 682 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Operations Counter AL | 682 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Operations This Read AM | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | General Comments | | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Switching Operations | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Unknown Operations | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Amps C Ø | 90.0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Amps B Ø | 30.0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Amps A Ø | 100.0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | 9 Months Operations | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Amps A Ø | 60.0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Amps B Ø | 85.0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Amps C Ø | 25.0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Operations Counter AL | 454 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Operations This Read AM | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Switching Operations | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Unknown Operations | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Operations Counter AF | 454 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | General Comments | | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | 9 Months Operations | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 72 | °F |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | 9 Month Operations | 12 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Amps A Ø | 95.0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Amps B Ø | 76.0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Amps C Ø | 111.0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Operations Counter AF | 228 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Operations Counter AL | 230 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Operations This Read Vac | 2 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Switching Operations | 2 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Unknown Operations | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Unknown Operations | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Switching Operations | 2 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Operations This Read Vac | 2 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Operations Counter AL | 211 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Operations Counter AF | 209 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | General Comments | | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | 9 Month Operations | 11 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Amps A Ø | 231.0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Amps B Ø | 197.0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Amps C Ø | 180.0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | 9 Month Operations | 13 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | 9 Month Operations VCB New | 11 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Amps A Ø | 109.0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Amps B Ø | 134.0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Amps C Ø | 116.0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Operations Counter AF | 697 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Operations Counter AL | 699 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Operations This Read Vac | 2 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | General Comments | | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Switching Operations | 2 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Unknown Operations | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Unknown Operations | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Switching Operations | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Operations This Read Vac | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | 9 Month Operations | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | General Comments | | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Operations Counter AF | 161 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Operations Counter AL | 163 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Amps C Ø | 175.0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Amps B Ø | 180.0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Amps A Ø | 167.0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Operations Counter AL | 159 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Operations Counter AF | 159 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Switching Operations | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Unknown Operations | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | General Comments | | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Amps C Ø | 567.0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Amps B Ø | 599.0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Amps A Ø | 593.0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | 9 Month Operations | 7 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Switching Operations | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Unknown Operations | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Operations This Read Vac | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Operations Counter AL | 278 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Operations Counter AF | 278 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | General Comments | | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | 9 Month Operations | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | LTCC000738 | LTCControl | 529-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | LTCC000738 | LTCControl | 529-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | LTCC000738 | LTCControl | 529-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | LTCC000738 | LTCControl | 529-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | LTCC000738 | LTCControl | 529-1 | LTC Control Insp | General Comments | | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | LTCC000738 | LTCControl | 529-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | LTCC000738 | LTCControl | 529-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | LTCC000738 | LTCControl | 529-1 | LTC Control Insp | All Connections OK? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | LTCC000738 | LTCControl | 529-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Counter Readings | General Comments | | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Counter Readings | LTC As Found Counter | 166448 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Counter Readings | LTC As Left Counter | 166448 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Counter Readings | LTC Operations Since Last Insp | 586 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Readings | General Comments | | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Readings | LTC Totalizer Reading | 14976.00 | kw |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 145.00 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Readings | Totalizer Meter Reading | .8320 | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Readings | Winding Temp Max | 60 | °C |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BCH001290 | Charger | 529-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BCH001290 | Charger | 529-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BCH001290 | Charger | 529-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BCH001290 | Charger | 529-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 4.7 | amps |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BCH001290 | Charger | 529-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BCH001290 | Charger | 529-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BCH001290 | Charger | 529-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BCH001290 | Charger | 529-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BAT001604 | Battery | 529-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BAT001604 | Battery | 529-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BAT001604 | Battery | 529-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BAT001604 | Battery | 529-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BAT001604 | Battery | 529-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BAT001604 | Battery | 529-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BAT001604 | Battery | 529-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BAT001604 | Battery | 529-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BAT001604 | Battery | 529-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BAT001604 | Battery | 529-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BAT001604 | Battery | 529-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BAT001604 | Battery | 529-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | BAT001604 | Battery | 529-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | General Comments | | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | General Comments | | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | General Comments | | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | General Comments | | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/18/2023 7:18 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Amps C Ø | 77.0 | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Amps B Ø | 61.0 | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Amps A Ø | 60.0 | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | 9 Month Operations VCB New | 15 | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | 9 Month Operations | 15 | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | General Comments | | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Operations Counter AF | 197 | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Operations Counter AL | 197 | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Operations This Read Vac | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Unknown Operations | 0 | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Switching Operations | 0 | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Counter Readings | General Comments | | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Counter Readings | LTC As Found Counter | 278053 | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Counter Readings | LTC As Left Counter | 278053 | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Counter Readings | LTC Operations Since Last Insp | 435 | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Readings | Totalizer Meter Reading | .1520 | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Readings | LTC Totalizer Reading | 486.40 | kw |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Readings | General Comments | | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | LTCC000666 | LTCControl | 769-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | LTCC000666 | LTCControl | 769-1 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | LTCC000666 | LTCControl | 769-1 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | LTCC000666 | LTCControl | 769-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | LTCC000666 | LTCControl | 769-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | LTCC000666 | LTCControl | 769-1 | LTC Control Insp | General Comments | | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | LTCC000666 | LTCControl | 769-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | LTCC000666 | LTCControl | 769-1 | LTC Control Insp | All Connections OK? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BCH001176 | Charger | 769-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BCH001176 | Charger | 769-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BCH001176 | Charger | 769-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BCH001176 | Charger | 769-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BCH001176 | Charger | 769-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BCH001176 | Charger | 769-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BCH001176 | Charger | 769-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | BCH001176 | Charger | 769-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | General Comments | | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | General Comments | | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | General Comments | | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/18/2023 7:10 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Operations Counter AF | 170 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Operations Counter AL | 170 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Operations This Read Vac | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Unknown Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Switching Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | 9 Month Operations | 2 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Amps A Ø | 0.0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Amps C Ø | 0.0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Amps B Ø | 0.0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Amps C Ø | 164.0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | 9 Month Operations | 3 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Operations Counter AL | 183 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Operations Counter AF | 183 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Amps B Ø | 184.0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Amps A Ø | 183.0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Unknown Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Switching Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Operations This Read Vac | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Operations This Read Vac | 3 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Amps B Ø | 101.0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Switching Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Amps C Ø | 101.0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Fault Adjusted Amps A Phase V | 39.76 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Fault Adjusted Amps B Phase V | 39.76 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Amps A Ø | 108.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Unknown Operations | 3 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | 9 Month Operations | 5 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Operations Counter AL | 207 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Operations Counter AF | 207 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Fault Adjusted Amps C Phase V | 39.76 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Unknown Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Switching Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Fault Operations A Ø | 5 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Fault Adjusted Amps A Phase V | 70.75 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Operations This Read Vac | 5 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Operations Counter AL | 243 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Operations Counter AF | 243 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | 9 Month Operations | 11 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Amps C Ø | 184.0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Amps B Ø | 181.0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Amps A Ø | 176.0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Operations This Read Vac | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Switching Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Unknown Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Operations Counter AL | 181 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Operations Counter AF | 181 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Amps C Ø | 336.0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Amps B Ø | 352.0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Amps A Ø | 362.0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | 9 Month Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Fault Adjusted Amps B Phase V | 39.76 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Amps C Ø | 167.0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Amps B Ø | 129.0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Fault Operations B Ø | 3 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Amps A Ø | 156.0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Switching Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Unknown Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Operations This Read Vac | 3 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Operations Counter AL | 318 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Operations Counter AF | 318 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | 9 Month Operations | 11 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | 9 Month Operations | 12 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Operations Counter AF | 256 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Operations Counter AL | 256 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Fault Operations A Ø | 2 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Operations This Read Vac | 2 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Switching Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Unknown Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Amps A Ø | 80.0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Amps B Ø | 93.0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Amps C Ø | 69.0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Fault Adjusted Amps A Phase V | 26.50 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Unknown Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Switching Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Operations This Read Vac | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Operations Counter AL | 345 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Operations Counter AF | 345 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Amps C Ø | 120.0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Amps B Ø | 120.0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Amps A Ø | 150.0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | 9 Month Operations | 4 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | LTCC000705 | LTCControl | 060-6 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | LTCC000705 | LTCControl | 060-6 | LTC Control Insp | All Connections OK? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | LTCC000705 | LTCControl | 060-6 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | LTCC000705 | LTCControl | 060-6 | LTC Control Insp | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | LTCC000705 | LTCControl | 060-6 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | LTCC000705 | LTCControl | 060-6 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | LTCC000705 | LTCControl | 060-6 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | LTCC000705 | LTCControl | 060-6 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | LTCC000705 | LTCControl | 060-6 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Counter Readings | LTC Operations Since Last Insp | 1164 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Counter Readings | LTC As Left Counter | 130164 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Counter Readings | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Counter Readings | LTC As Found Counter | 130164 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Readings | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Readings | LTC Totalizer Reading | 10782.00 | kw |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Readings | Oil Temp Max | 65 | °C |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Readings | Oil Temp Present | 55 | °C |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Readings | Totalizer Meter Reading | .5990 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Readings | Winding Temp Max | 55 | °C |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Unknown Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Switching Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Operations This Read Vac | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Operations Counter AL | 214 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Operations Counter AF | 214 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | 9 Month Operations | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Amps A Ø | 487.0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Amps B Ø | 478.0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Amps C Ø | 461.0 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | LTCC000709 | LTCControl | 060-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | LTCC000709 | LTCControl | 060-5 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | LTCC000709 | LTCControl | 060-5 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | LTCC000709 | LTCControl | 060-5 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | LTCC000709 | LTCControl | 060-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | LTCC000709 | LTCControl | 060-5 | LTC Control Insp | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | LTCC000709 | LTCControl | 060-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | LTCC000709 | LTCControl | 060-5 | LTC Control Insp | All Connections OK? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Counter Readings | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Counter Readings | LTC As Found Counter | 162993 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Counter Readings | LTC Operations Since Last Insp | 493 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Counter Readings | LTC Max Tap Position | 6L | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Counter Readings | LTC As Left Counter | 162993 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Counter Readings | LTC Current Tap Position | 10L | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Readings | Oil Temp Max | 70 | °C |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Readings | LTC Totalizer Reading | 13644.00 | kw |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Readings | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Readings | Winding Temp Max | 80 | °C |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Readings | Totalizer Meter Reading | .7580 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/18/2023 7:07 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | 9 Month Operations | 1 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Amps A Ø | 55.0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Amps B Ø | 47.0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Amps C Ø | 48.0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | General Comments | | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Operations Counter AF | 188 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Operations Counter AL | 188 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Amps A Ø | 220.0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | 9 Month Operations | 1 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Amps B Ø | 223.0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Amps C Ø | 224.0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | General Comments | | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Operations Counter AF | 342 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Operations Counter AL | 343 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | General Comments | | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Amps C Ø | 19.0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Operations Counter AF | 518 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Operations Counter AL | 518 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Amps B Ø | 22.0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Amps A Ø | 10.0 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | 9 Month Operations | 1 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 146611 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.7 | volts |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 138944 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Max Tap Position | 1L | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Current Tap Position | 7L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 133012 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 8678.40 | kw |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .9040 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Readings | Oil Temp Present | 46 | °C |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Readings | General Comments | | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Readings | Oil Temp Max | 60 | °C |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BCH001361 | Charger | 409-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BCH001361 | Charger | 409-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BCH001361 | Charger | 409-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BCH001361 | Charger | 409-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BCH001361 | Charger | 409-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BCH001361 | Charger | 409-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.3 | amps |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BCH001361 | Charger | 409-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BCH001361 | Charger | 409-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 66 | °F |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | General Comments | | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | General Comments | | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | General Comments | | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/17/2023 17:05 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | Ambient Temp | 66 | °F |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | LTCC000904 | LTCControl | 788-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | LTCC000904 | LTCControl | 788-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | LTCC000904 | LTCControl | 788-2 | LTC Control Insp | All Connections OK? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | LTCC000904 | LTCControl | 788-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | LTCC000904 | LTCControl | 788-2 | LTC Control Insp | LTC Output Voltage Level | 123.9 | VAC |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | LTCC000904 | LTCControl | 788-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | LTCC000904 | LTCControl | 788-2 | LTC Control Insp | General Comments | | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | LTCC000904 | LTCControl | 788-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Amps B Ø | 56.0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Amps C Ø | 64.0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Fault Operations Ground | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Fault Adjusted Amps A Phase V | 4.56 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | 9 Month Operations | 2 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | General Comments | | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Operations This Read Vac | 1 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Operations Counter AL | 178 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Operations Counter AF | 178 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Amps A Ø | 70.0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Operations Counter AF | 174 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Operations Counter AL | 174 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Amps A Ø | 29.0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Amps B Ø | 26.0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Amps C Ø | 24.0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | 9 Month Operations | 1 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | General Comments | | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Amps A Ø | 124.0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | 9 Month Operations | 7 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | General Comments | | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Amps B Ø | 115.0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Amps C Ø | 89.0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Fault Adjusted Amps A Phase V | 18.24 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Fault Operations A Ø | 4 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Operations This Read Vac | 4 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Operations Counter AL | 289 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Operations Counter AF | 289 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Counter Readings | LTC As Left Counter | 31663 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Counter Readings | LTC As Found Counter | 31663 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Counter Readings | General Comments | | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Counter Readings | LTC Operations Since Last Insp | 412 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Readings | Totalizer Meter Reading | .4362 | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Readings | LTC Totalizer Reading | 4187.52 | kw |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Readings | General Comments | | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BAT001489 | Battery | 788-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BAT001489 | Battery | 788-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BAT001489 | Battery | 788-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BAT001489 | Battery | 788-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BAT001489 | Battery | 788-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BAT001489 | Battery | 788-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BAT001489 | Battery | 788-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BAT001489 | Battery | 788-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BAT001489 | Battery | 788-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BAT001489 | Battery | 788-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BAT001489 | Battery | 788-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BAT001489 | Battery | 788-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 66 | °F |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BAT001489 | Battery | 788-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BCH001420 | Charger | 788-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BCH001420 | Charger | 788-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BCH001420 | Charger | 788-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BCH001420 | Charger | 788-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BCH001420 | Charger | 788-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.5 | amps |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BCH001420 | Charger | 788-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BCH001420 | Charger | 788-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | BCH001420 | Charger | 788-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | General Comments | | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | General Comments | | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | General Comments | | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/17/2023 16:23 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Ambient Temp | 66 | °F |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BCH001115 | Charger | 427-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BCH001115 | Charger | 427-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BCH001115 | Charger | 427-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 3.5 | amps |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BCH001115 | Charger | 427-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.3 | VDC |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BCH001115 | Charger | 427-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.3 | VDC |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BCH001115 | Charger | 427-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | SF6 Pressure Indicator | good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | General Comments | | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Ambient Temperature | 56 | °F |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Readings | Fault Operations | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Readings | Operations Counter AL | 72 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Readings | Operations This Read SF6 | 1 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Readings | Switching Operations | 1 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Readings | Operations Counter AF | 72 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Readings | Num Operations Last 9 Months | 1 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Readings | General Comments | | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | General Comments | | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Reg Output Voltage Level | 125.3 | volts |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Regulator As Left Counter | 23266 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Regulator As Left Counter | 24234 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.4 | volts |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | General Comments | | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | General Comments | | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Regulator As Left Counter | 21863 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Reg Output Voltage Level | 125.0 | volts |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Readings | General Comments | | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 7334.40 | kw |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Readings | Oil Temp Max | 60 | °C |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Readings | Totalizer Meter Reading | .7640 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Amps A Ø | 90.0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | 9 Month Operations | 3 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Amps B Ø | 96.0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Amps C Ø | 96.0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | General Comments | | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Operations Counter AF | 244 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Operations Counter AL | 244 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Operations This Read Vac | 2 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Switching Operations | 2 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Amps A Ø | 202.0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Amps B Ø | 206.0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Amps C Ø | 221.0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | 9 Month Operations | 7 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Switching Operations | 2 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Operations This Read Vac | 2 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Operations Counter AL | 260 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Operations Counter AF | 260 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | General Comments | | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Operations Counter AF | 268 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | 9 Month Operations | 2 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Operations Counter AL | 268 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Amps A Ø | 247.0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | General Comments | | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Amps C Ø | 252.0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Amps B Ø | 255.0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Operations Counter AL | 293 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Operations Counter AF | 293 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | 9 Month Operations | 1 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Amps A Ø | 0.0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Amps B Ø | 0.0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Amps C Ø | 0.0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | General Comments | | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Switching Operations | 3 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Operations This Read Vac | 3 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Operations Counter AL | 180 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Operations Counter AF | 180 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Amps B Ø | 0.0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Amps C Ø | 0.0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | General Comments | | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Amps A Ø | 0.0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | 9 Month Operations | 5 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Fault Adjusted Amps C Phase V | 6.27 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Fault Adjusted Amps B Phase V | 6.27 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Fault Adjusted Amps A Phase V | 6.27 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Amps C Ø | 119.0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Amps B Ø | 121.0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Amps A Ø | 121.0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | 9 Month Operations | 3 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Unknown Operations | 1 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Operations This Read Vac | 1 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Operations Counter AL | 188 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Operations Counter AF | 188 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | General Comments | | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 34373 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 125.0 | volts |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 2180 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Min Tap Position | 13L | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | General Comments | | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Amps C Ø | 112.0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Operations Counter AF | 207 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Operations Counter AL | 207 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Amps B Ø | 108.0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Amps A Ø | 105.0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | 9 Month Operations | 3 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Amps B Ø | 122.0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Amps A Ø | 137.0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | 9 Month Operations | 2 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Operations Counter AF | 178 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | General Comments | | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Operations Counter AL | 178 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Amps C Ø | 127.0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.8 | volts |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 84828 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | 9 Month Operations | 2 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Amps A Ø | 149.0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | General Comments | | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Operations Counter AF | 185 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Operations Counter AL | 185 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Amps B Ø | 157.0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Amps C Ø | 133.0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | 9 Month Operations | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Operations Counter AL | 141 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Operations Counter AF | 141 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | General Comments | | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Amps A Ø | 502.0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Amps B Ø | 493.0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Amps C Ø | 472.0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | LTCC000704 | LTCControl | 807-1 | LTC Control Insp | All Connections OK? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | LTCC000704 | LTCControl | 807-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | LTCC000704 | LTCControl | 807-1 | LTC Control Insp | General Comments | | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | LTCC000704 | LTCControl | 807-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | LTCC000704 | LTCControl | 807-1 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | LTCC000704 | LTCControl | 807-1 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | LTCC000704 | LTCControl | 807-1 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | LTCC000704 | LTCControl | 807-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Counter Readings | General Comments | | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Counter Readings | LTC As Left Counter | 45570 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Counter Readings | LTC Operations Since Last Insp | 972 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Counter Readings | LTC As Found Counter | 45566 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.5 | psi |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Readings | Totalizer Meter Reading | .8073 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Readings | Winding Temp Max | 65 | °C |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Readings | Winding Temp Present | 45 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Readings | Oil Temp Max | 65 | °C |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Readings | LTC Totalizer Reading | 11625.12 | kw |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Readings | General Comments | | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Switching Operations | 1 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | 9 Month Operations | 1 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Operations This Read Vac | 1 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Operations Counter AF | 46 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Operations Counter AL | 47 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Amps A Ø | 360.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Amps B Ø | 375.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Amps C Ø | 370.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BCH001244 | Charger | 807-Battery Charger Distribution | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BCH001244 | Charger | 807-Battery Charger Distribution | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BCH001244 | Charger | 807-Battery Charger Distribution | Battery Charger Patrol Insp | General Comments | | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BCH001244 | Charger | 807-Battery Charger Distribution | Battery Charger Patrol Insp | Battery Charger Current | 4.1 | amps |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BCH001244 | Charger | 807-Battery Charger Distribution | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BCH001244 | Charger | 807-Battery Charger Distribution | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BCH001244 | Charger | 807-Battery Charger Distribution | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BCH001244 | Charger | 807-Battery Charger Distribution | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Operations Counter AL | 263 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Operations Counter AF | 263 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Amps C Ø | 0.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Amps B Ø | 0.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Amps A Ø | 0.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | 9 Month Operations | 2 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | All Connections OK? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | Battery Area Ambient Temp | 55 | °F |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | General Comments | | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | General Comments | | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Amps A Ø | 130.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Amps B Ø | 145.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Amps C Ø | 140.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Operations Counter AL | 90502 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Operations Counter AF | 90502 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | 9 Month Operations | 2 | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | General Comments | | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | General Comments | | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/17/2023 15:04 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Operations Counter AL | 386 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Operations Counter AF | 386 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Amps A Ø | 80.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Amps B Ø | 60.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Amps C Ø | 65.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | 9 Month Operations | 2 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .7116 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Readings | Oil Temp Present | 29 | °C |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Readings | General Comments | | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Readings | Winding Temp Max | 60 | °C |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 6831.36 | kw |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Readings | Winding Temp Present | 30 | °C |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | 9 Month Operations | 4 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Operations Counter AF | 405 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Amps C Ø | 50.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Amps B Ø | 50.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Amps A Ø | 50.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Operations Counter AL | 405 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | General Comments | no follow up required | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Free of Audible Arcing? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Follow-up Action Required? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Operations Counter AF | 205 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Operations Counter AL | 206 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Operations This Read Vac | 1 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Switching Operations | 1 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Amps C Ø | 225.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Amps B Ø | 235.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Amps A Ø | 235.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | 9 Month Operations | 1 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | 9 Month Operations | 1 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Operations This Read Vac | 1 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Switching Operations | 1 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Operations Counter AF | 288 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Operations Counter AL | 289 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Amps A Ø | 100.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Amps B Ø | 150.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Amps C Ø | 150.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | 9 Month Operations | 6 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Operations This Read Vac | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Operations Counter AL | 414 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Operations Counter AF | 414 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | General Comments | | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Amps C Ø | 85.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Amps B Ø | 95.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Amps A Ø | 100.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | 9 Month Operations | 2 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Operations Counter AF | 263 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Operations Counter AL | 263 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | 9 Month Operations | 2 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Amps A Ø | 135.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Operations Counter AF | 261 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Operations Counter AL | 261 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Amps B Ø | 150.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Amps C Ø | 145.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Operations Counter AL | 242 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Operations This Read Vac | 2 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Switching Operations | 2 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Operations Counter AF | 240 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Amps C Ø | 0.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Amps B Ø | 0.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Amps A Ø | 0.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | 9 Month Operations | 2 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | 9 Month Operations | 4 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Amps A Ø | 200.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Amps B Ø | 200.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Amps C Ø | 200.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Operations Counter AL | 473 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Operations Counter AF | 473 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Amps B Ø | 195.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Amps A Ø | 205.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Operations Counter AF | 165 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Operations Counter AL | 166 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Operations This Read Vac | 1 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Switching Operations | 1 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | 9 Month Operations | 1 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Amps C Ø | 205.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | General Comments | | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | General Comments | | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | Ambient Temp | 56 | °F |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | LTCC000047 | LTCControl | 427-1 C | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | LTCC000047 | LTCControl | 427-1 C | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | LTCC000047 | LTCControl | 427-1 C | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | LTCC000047 | LTCControl | 427-1 C | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | LTCC000047 | LTCControl | 427-1 C | LTC Control Insp | All Connections OK? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | LTCC000047 | LTCControl | 427-1 C | LTC Control Insp | Follow-up Action Required? | n | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | LTCC000047 | LTCControl | 427-1 C | LTC Control Insp | General Comments | | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | LTCC000047 | LTCControl | 427-1 C | LTC Control Insp | LTC Operation Checked? | y | |
| 4/17/2023 15:15 | Distribution | Lebanon East Quarterly Inspection | LTCC000047 | LTCControl | 427-1 C | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Counter Readings | LTC Operations Since Last Insp | 451 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Counter Readings | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Counter Readings | LTC As Found Counter | 43044 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Counter Readings | LTC As Left Counter | 43044 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | LTCC000662 | LTCControl | 549-3 | LTC Control Insp | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | LTCC000662 | LTCControl | 549-3 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | LTCC000662 | LTCControl | 549-3 | LTC Control Insp | All Connections OK? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | LTCC000662 | LTCControl | 549-3 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | LTCC000662 | LTCControl | 549-3 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | LTCC000662 | LTCControl | 549-3 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | LTCC000662 | LTCControl | 549-3 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | LTCC000662 | LTCControl | 549-3 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 35 | °C |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Readings | Totalizer Meter Reading | .5832 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Readings | LTC Totalizer Reading | 8398.08 | kw |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Readings | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 600 | psi |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | LTCC000915 | LTCControl | 549-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | LTCC000915 | LTCControl | 549-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | LTCC000915 | LTCControl | 549-2 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | LTCC000915 | LTCControl | 549-2 | LTC Control Insp | All Connections OK? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | LTCC000915 | LTCControl | 549-2 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | LTCC000915 | LTCControl | 549-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | LTCC000915 | LTCControl | 549-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | LTCC000915 | LTCControl | 549-2 | LTC Control Insp | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Counter Readings | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Counter Readings | LTC As Found Counter | 65697 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Counter Readings | LTC As Left Counter | 65697 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Counter Readings | LTC Operations Since Last Insp | 386 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Readings | Totalizer Meter Reading | .5273 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Readings | LTC Totalizer Reading | 7593.12 | kw |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Readings | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -1.0 | psi |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Operations Counter AL | 193 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Operations Counter AF | 193 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Amps C Ø | 319.0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | 9 Month Operations | 1 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Amps B Ø | 290.0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Amps A Ø | 276.0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Counter Readings | LTC Operations Since Last Insp | 561 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Counter Readings | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Counter Readings | LTC As Found Counter | 116444 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Counter Readings | LTC As Left Counter | 116444 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | 9 Month Operations | 6 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Amps A Ø | 87.0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Amps B Ø | 86.0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Amps C Ø | 112.0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Fault Adjusted Amps A Phase V | 5.99 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Fault Adjusted Amps C Phase V | 11.99 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Fault Operations C Ø | 2 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Operations This Read Vac | 3 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Operations Counter AL | 412 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Operations Counter AF | 412 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | LTCC000768 | LTCControl | 549-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | LTCC000768 | LTCControl | 549-1 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | LTCC000768 | LTCControl | 549-1 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | LTCC000768 | LTCControl | 549-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | LTCC000768 | LTCControl | 549-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | LTCC000768 | LTCControl | 549-1 | LTC Control Insp | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | LTCC000768 | LTCControl | 549-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | LTCC000768 | LTCControl | 549-1 | LTC Control Insp | All Connections OK? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Readings | Winding Temp Present | 20 | °C |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Readings | Winding Temp Max | 55 | °C |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Readings | Totalizer Meter Reading | .8210 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Readings | LTC Totalizer Reading | 11822.40 | kw |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Readings | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | 9 Month Operations | 3 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Operations Counter AL | 228 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Operations Counter AF | 228 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | 9 Month Operations | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Amps A Ø | 263.0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Amps B Ø | 316.0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Amps C Ø | 293.0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Operations Counter AL | 175 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Operations Counter AF | 175 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Amps A Ø | 105.0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Operations Counter AF | 241 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Operations Counter AL | 241 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Amps B Ø | 102.0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | 9 Month Operations | 5 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Amps C Ø | 126.0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BCH001173 | Charger | 549-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BCH001173 | Charger | 549-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BCH001173 | Charger | 549-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BCH001173 | Charger | 549-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 5.1 | amps |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BCH001173 | Charger | 549-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BCH001173 | Charger | 549-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BCH001173 | Charger | 549-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | BCH001173 | Charger | 549-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Operations This Read Vac | 5 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Operations Counter AL | 371 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Operations Counter AF | 371 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Fault Operations C Ø | 2 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Fault Operations B Ø | 2 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Fault Adjusted Amps C Phase V | 11.99 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Fault Adjusted Amps B Phase V | 11.99 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Fault Adjusted Amps A Phase V | 5.99 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Amps C Ø | 81.0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | 9 Month Operations | 7 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Amps A Ø | 61.0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Amps B Ø | 78.0 | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | General Comments | | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/17/2023 14:58 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | 9 Month Operations | 5 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Fault Operations B Ø | 2 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Amps C Ø | 161.0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Amps B Ø | 150.0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Amps A Ø | 150.0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Fault Adjusted Amps A Phase V | 5.99 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Operations Counter AF | 363 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Operations Counter AL | 363 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Operations This Read Vac | 3 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Fault Adjusted Amps B Phase V | 11.99 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Fault Adjusted Amps C Phase V | 59.95 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Amps C Ø | 93.0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Amps B Ø | 127.0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Amps A Ø | 99.0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Fault Operations C Ø | 10 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Operations Counter AF | 397 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Operations Counter AL | 397 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Operations This Read Vac | 10 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | 9 Month Operations | 18 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Operations Counter AL | 301 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Operations Counter AF | 301 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | 9 Month Operations | 4 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Amps C Ø | 45.0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Amps B Ø | 53.0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Amps A Ø | 40.0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Counter Readings | LTC Operations Since Last Insp | 343 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Counter Readings | LTC As Found Counter | 51324 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Counter Readings | LTC As Left Counter | 51324 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Counter Readings | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCC000944 | LTCControl | 846-2 | LTC Control Insp | All Connections OK? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCC000944 | LTCControl | 846-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCC000944 | LTCControl | 846-2 | LTC Control Insp | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCC000944 | LTCControl | 846-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCC000944 | LTCControl | 846-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCC000944 | LTCControl | 846-2 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCC000944 | LTCControl | 846-2 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCC000944 | LTCControl | 846-2 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Readings | LTC Totalizer Reading | 10116.00 | kw |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Readings | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Readings | Totalizer Meter Reading | .5620 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Readings | Winding Temp Present | 35 | °C |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 20.00 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 100.00 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Readings | LTC Totalizer Reading | 9518.40 | kw |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Readings | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Readings | Totalizer Meter Reading | .6610 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Readings | Winding Temp Max | 50 | °C |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 65.00 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCC000743 | LTCControl | 846-1 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCC000743 | LTCControl | 846-1 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCC000743 | LTCControl | 846-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCC000743 | LTCControl | 846-1 | LTC Control Insp | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCC000743 | LTCControl | 846-1 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCC000743 | LTCControl | 846-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCC000743 | LTCControl | 846-1 | LTC Control Insp | All Connections OK? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | LTCC000743 | LTCControl | 846-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Counter Readings | LTC As Left Counter | 69743 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Counter Readings | LTC Operations Since Last Insp | 725 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Counter Readings | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Counter Readings | LTC As Found Counter | 69743 | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | Battery Area Ambient Temp | 53 | °F |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | All Connections OK? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | Bat Volt 1Min After Chgr Trip | 49.0 | VDC |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BCH001432 | Charger | 846-Battery Charger Distribution | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BCH001432 | Charger | 846-Battery Charger Distribution | Battery Charger Patrol Insp | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BCH001432 | Charger | 846-Battery Charger Distribution | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BCH001432 | Charger | 846-Battery Charger Distribution | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BCH001432 | Charger | 846-Battery Charger Distribution | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BCH001432 | Charger | 846-Battery Charger Distribution | Battery Charger Patrol Insp | Battery Charger Current | 3.8 | amps |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BCH001432 | Charger | 846-Battery Charger Distribution | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | BCH001432 | Charger | 846-Battery Charger Distribution | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | Ambient Temp | 53 | °F |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | General Comments | | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 14:48 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Amps A Ø | 120.0 | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | 9 Month Operations | 4 | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Operations Counter AL | 744 | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Operations Counter AF | 744 | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Amps B Ø | 100.0 | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Amps C Ø | 110.0 | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | General Comments | | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Counter Readings | General Comments | | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Counter Readings | LTC As Found Counter | 443529 | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Counter Readings | LTC As Left Counter | 443529 | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Counter Readings | LTC Current Tap Position | 1R | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Counter Readings | LTC Operations Since Last Insp | 792 | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | LTCC000981 | LTCControl | 719-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | LTCC000981 | LTCControl | 719-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | LTCC000981 | LTCControl | 719-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | LTCC000981 | LTCControl | 719-1 | LTC Control Insp | LTC Output Voltage Level | 123.2 | VAC |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | LTCC000981 | LTCControl | 719-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | LTCC000981 | LTCControl | 719-1 | LTC Control Insp | General Comments | | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | LTCC000981 | LTCControl | 719-1 | LTC Control Insp | All Connections OK? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | LTCC000981 | LTCControl | 719-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Readings | Totalizer Meter Reading | .3503 | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 10.00 | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Readings | General Comments | | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Readings | LTC Totalizer Reading | 2522.16 | kw |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Readings | Oil Temp Present | 37 | °C |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | BCH001332 | Charger | 719-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | BCH001332 | Charger | 719-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | BCH001332 | Charger | 719-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | BCH001332 | Charger | 719-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | BCH001332 | Charger | 719-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | BCH001332 | Charger | 719-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | BCH001332 | Charger | 719-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | BCH001332 | Charger | 719-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 56 | °F |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | General Comments | | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | General Comments | | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | General Comments | | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | Ambient Temp | 56 | °F |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/17/2023 12:29 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Operations Counter AF | 116 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Operations Counter AL | 116 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Amps C Ø | 16.0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Amps B Ø | 21.0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Amps A Ø | 21.0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | 9 Month Operations | 10 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | LTCC000850 | LTCControl | 158-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | LTCC000850 | LTCControl | 158-2 | LTC Control Insp | All Connections OK? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | LTCC000850 | LTCControl | 158-2 | LTC Control Insp | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | LTCC000850 | LTCControl | 158-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | LTCC000850 | LTCControl | 158-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | LTCC000850 | LTCControl | 158-2 | LTC Control Insp | VRR Base Voltage AL | 118.0 | VAC |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | LTCC000850 | LTCControl | 158-2 | LTC Control Insp | VRR Base Voltage AF | 118.0 | VAC |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | LTCC000850 | LTCControl | 158-2 | LTC Control Insp | LTC Output Voltage Level | 116.8 | VAC |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Counter Readings | LTC As Left Counter | 67583 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Counter Readings | LTC Operations Since Last Insp | 399 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Counter Readings | LTC Max Tap Position | 7R | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Counter Readings | LTC As Found Counter | 67573 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Counter Readings | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Counter Readings | LTC Min Tap Position | 5L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Readings | LV Winding Temp Present | 30 | °C |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Readings | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Readings | HV Winding Temp Max | 46 | °C |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Readings | HV Winding Temp Present | 30 | °C |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Readings | LV Winding Temp Max | 46 | °C |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Readings | Oil Temp Max | 49 | °C |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Readings | TV Winding Temp Max | 44 | °C |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Readings | TV Winding Temp Present | 29 | °C |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1110 | psi |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | LTCC000919 | LTCControl | 158-6 | LTC Control Insp | All Connections OK? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | LTCC000919 | LTCControl | 158-6 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | LTCC000919 | LTCControl | 158-6 | LTC Control Insp | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | LTCC000919 | LTCControl | 158-6 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | LTCC000919 | LTCControl | 158-6 | LTC Control Insp | LTC Output Voltage Level | 124.5 | VAC |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | LTCC000919 | LTCControl | 158-6 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | LTCC000919 | LTCControl | 158-6 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | LTCC000919 | LTCControl | 158-6 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Counter Readings | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Counter Readings | LTC Operations Since Last Insp | 632 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Counter Readings | LTC As Found Counter | 85190 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Counter Readings | LTC As Left Counter | 85196 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Readings | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Readings | LTC Totalizer Reading | 1612.80 | kw |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Readings | Oil Temp Max | 39 | °C |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Readings | Oil Temp Present | 26 | °C |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Readings | Totalizer Meter Reading | .1680 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Readings | Winding Temp Max | 39 | °C |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Readings | Winding Temp Present | 25 | °C |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.2 | psi |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Switching Operations | 1 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | 9 Month Operations | 3 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Amps A Ø | 84.0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Amps B Ø | 87.0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Operations This Read Vac | 1 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Operations Counter AL | 180 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Operations Counter AF | 179 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Amps C Ø | 93.0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Switching Operations | 1 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Operations This Read Vac | 1 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Operations Counter AL | 197 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Operations Counter AF | 196 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Amps C Ø | 81.0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Amps B Ø | 69.0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Amps A Ø | 57.0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | 9 Month Operations | 1 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Operations Counter AF | 80 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Operations Counter AL | 81 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Operations This Read Vac | 5 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Switching Operations | 1 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Fault Adjusted Amps A Phase V | 8.63 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Amps A Ø | 17.0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Amps C Ø | 13.0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Fault Operations B Ø | 2 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Amps B Ø | 17.0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Fault Adjusted Amps B Phase V | 8.63 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Fault Operations A Ø | 2 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | 9 Month Operations | 9 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Amps A Ø | 4.0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Amps B Ø | 4.0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Amps C Ø | 1.0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | 9 Month Operations | 1 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | General Comments | BFTC | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Switching Operations | 1 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Operations Counter AF | 132 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Operations Counter AL | 133 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Operations This Read Vac | 1 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | LTCC000918 | LTCControl | 158-5 | LTC Control Insp | All Connections OK? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | LTCC000918 | LTCControl | 158-5 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | LTCC000918 | LTCControl | 158-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | LTCC000918 | LTCControl | 158-5 | LTC Control Insp | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | LTCC000918 | LTCControl | 158-5 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | LTCC000918 | LTCControl | 158-5 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | LTCC000918 | LTCControl | 158-5 | LTC Control Insp | LTC Output Voltage Level | 124.9 | VAC |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | LTCC000918 | LTCControl | 158-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Counter Readings | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Counter Readings | LTC As Found Counter | 97158 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Counter Readings | LTC As Left Counter | 97168 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Counter Readings | LTC Operations Since Last Insp | 639 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Readings | Totalizer Meter Reading | .3500 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Readings | Winding Temp Max | 41 | °C |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Readings | Oil Temp Present | 29 | °C |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Readings | Oil Temp Max | 43 | °C |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Readings | LTC Totalizer Reading | 3360.00 | kw |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Readings | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Readings | Winding Temp Present | 26 | °C |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Amps C Ø | 151.0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Amps B Ø | 173.0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Amps A Ø | 148.0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Operations Counter AF | 188 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Operations Counter AL | 194 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Operations This Read Vac | 6 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Switching Operations | 6 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | 9 Month Operations | 7 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | 9 Month Operations | 1 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Amps A Ø | 91.0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Amps B Ø | 104.0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Amps C Ø | 70.0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Switching Operations | 1 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Operations This Read Vac | 1 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Operations Counter AL | 176 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Operations Counter AF | 176 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | General Comments | BFTC | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Amps C Ø | 0.0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Amps B Ø | 0.0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Amps A Ø | 0.0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Operations This Read Vac | 11 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | 9 Month Operations | 13 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Operations Counter AL | 68 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Switching Operations | 1 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Operations Counter AF | 57 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Maintenance Operations | 10 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Amps C Ø | 93.0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Amps B Ø | 87.0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Operations Counter AF | 210 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Amps A Ø | 84.0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Operations Counter AL | 214 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Operations This Read Vac | 4 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Switching Operations | 4 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | 9 Month Operations | 7 | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | All Connections OK? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | Positive DC Ground | 67.2 | VDC |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | Cell Electrolyte Level | Low | If low,note cell #~'s |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | Battery Area Ambient Temp | 68 | °F |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | General Comments | Created W/O to add water. They are midway between, high and low | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | Negative DC Ground | 67.2 | VDC |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BCH001481 | Charger | 158-Battery Charger 1 | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BCH001481 | Charger | 158-Battery Charger 1 | Battery Charger Patrol Insp | Battery Charger Current | 2.1 | amps |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BCH001481 | Charger | 158-Battery Charger 1 | Battery Charger Patrol Insp | As Left Float Voltage | 134.6 | VDC |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BCH001481 | Charger | 158-Battery Charger 1 | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 3.100 | millivolts |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BCH001481 | Charger | 158-Battery Charger 1 | Battery Charger Patrol Insp | As Found Float Voltage | 134.6 | VDC |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BCH001481 | Charger | 158-Battery Charger 1 | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BCH001481 | Charger | 158-Battery Charger 1 | Battery Charger Patrol Insp | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | BCH001481 | Charger | 158-Battery Charger 1 | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | YD000113 | Yard | 158-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | YD000113 | Yard | 158-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | YD000113 | Yard | 158-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | YD000113 | Yard | 158-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | YD000113 | Yard | 158-Yard | Yard Patrol Inspection | Ambient Temp | 48 | °F |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | YD000113 | Yard | 158-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | YD000113 | Yard | 158-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | YD000113 | Yard | 158-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | YD000113 | Yard | 158-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | YD000113 | Yard | 158-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | YD000113 | Yard | 158-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | YD000113 | Yard | 158-Yard | Yard Patrol Inspection | General Comments | | |
| 4/17/2023 13:10 | Distribution | Bond Quarterly Inspection | YD000113 | Yard | 158-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Patrol Inspection | General Comments | | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Patrol Inspection | General Comments | | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Patrol Inspection | General Comments | | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 35 | °C |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 65 | °C |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | BCH000115 | Charger | BK-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | BCH000115 | Charger | BK-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.7 | VDC |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | BCH000115 | Charger | BK-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.7 | VDC |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | BCH000115 | Charger | BK-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | BCH000115 | Charger | BK-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | BCH000115 | Charger | BK-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | BCH000115 | Charger | BK-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | CH000476 | ControlHouse | BK-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | CH000476 | ControlHouse | BK-Battery Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | CH000476 | ControlHouse | BK-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | CH000476 | ControlHouse | BK-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | CH000476 | ControlHouse | BK-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | CH000476 | ControlHouse | BK-Battery Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | CH000476 | ControlHouse | BK-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | CH000476 | ControlHouse | BK-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | CH000476 | ControlHouse | BK-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | CH000476 | ControlHouse | BK-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | CH000476 | ControlHouse | BK-Battery Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | CH000476 | ControlHouse | BK-Battery Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Ambient Temp | 52 | °F |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | General Comments | | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | General Comments | | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PF001288 | PowerFuse | BK-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/18/2023 11:26 | Distribution | Brook Quarterly Inspection | PF001288 | PowerFuse | BK-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | 9 Month Operations | 8 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Switching Operations | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Operations Counter AL | 156 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Operations Counter AF | 156 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | General Comments | | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Amps C Ø | 297.0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Amps A Ø | 280.0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Amps B Ø | 277.0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Amps A Ø | 0.0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | 9 Month Operations | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Amps B Ø | 0.0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Amps C Ø | 0.0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | General Comments | | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Operations Counter AF | 161 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Operations Counter AL | 161 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Operations This Read Vac | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Switching Operations | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | General Comments | | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Operations Counter AF | 154 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Operations Counter AL | 154 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Operations This Read Vac | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Switching Operations | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Amps C Ø | 36.0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Amps B Ø | 30.0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Amps A Ø | 35.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | 9 Month Operations | 5 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Switching Operations | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | 9 Month Operations | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Amps A Ø | 86.0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Amps B Ø | 81.0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Amps C Ø | 92.0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Operations This Read Vac | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Operations Counter AL | 194 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Operations Counter AF | 194 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | General Comments | | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Operations Counter AL | 289 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Operations Counter AF | 289 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Amps B Ø | 132.0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | General Comments | | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Amps A Ø | 133.0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Operations This Read Vac | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Switching Operations | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | 9 Month Operations | 1 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Amps C Ø | 130.0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Patrol Inspection | General Comments | | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Fault Adjusted Amps A Phase V | 11.18 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Switching Operations | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Operations This Read Vac | 1 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Operations Counter AL | 194 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Operations Counter AF | 194 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | General Comments | | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Amps C Ø | 61.0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Amps B Ø | 50.0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Amps A Ø | 34.0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Fault Operations Ground | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | 9 Month Operations | 2 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | 9 Month Operations | 2 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Operations Counter AL | 213 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Operations Counter AF | 213 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Amps A Ø | 132.0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Amps B Ø | 103.0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Amps C Ø | 111.0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | General Comments | | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Readings | Fault Operations | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Readings | Follow-up Action Required? | n | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Readings | General Comments | | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Readings | Maintenance Operations | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Readings | Operations Counter AF | 61 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Readings | Operations Counter AL | 61 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Readings | Switching Operations | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Readings | Operations This Read SF6 | 0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | SF6 Pressure Indicator | good | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | General Comments | | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Ambient Temperature | 52 | °F |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 573 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 11R | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 37081 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 37081 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Counter Readings | General Comments | | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | 9 Month Operations | 6 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Operations Counter AL | 217 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Operations Counter AF | 217 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | General Comments | L and B side disconnects where open and verified breaker is open per DCC | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Operations This Read Vac | 4 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Amps C Ø | 0.0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Switching Operations | 4 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Amps B Ø | 0.0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Amps A Ø | 0.0 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 39 | °C |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 20 | °C |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 42 | °C |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 24 | °C |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 40 | °C |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 20 | °C |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 43 | °C |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 24 | °C |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 43 | °C |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 24 | °C |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 900 | psi |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Amps C Ø | 200.0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Amps B Ø | 200.0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Amps A Ø | 200.0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | 9 Month Operations | 4 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Operations Counter AL | 417 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Operations Counter AF | 417 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | General Comments | | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BCH000890 | Charger | EW-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BCH000890 | Charger | EW-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BCH000890 | Charger | EW-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BCH000890 | Charger | EW-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.1 | VDC |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BCH000890 | Charger | EW-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.1 | VDC |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BCH000890 | Charger | EW-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.1 | amps |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BCH000890 | Charger | EW-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BCH000890 | Charger | EW-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BAT000150 | Battery | EW-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BAT000150 | Battery | EW-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BAT000150 | Battery | EW-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BAT000150 | Battery | EW-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BAT000150 | Battery | EW-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BAT000150 | Battery | EW-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BAT000150 | Battery | EW-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BAT000150 | Battery | EW-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BAT000150 | Battery | EW-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BAT000150 | Battery | EW-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BAT000150 | Battery | EW-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | BAT000150 | Battery | EW-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | General Comments | | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Ambient Temp | 52 | °F |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | LTCC000840 | LTCControl | 847-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | LTCC000840 | LTCControl | 847-1 | LTC Control Insp | General Comments | | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | LTCC000840 | LTCControl | 847-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | LTCC000840 | LTCControl | 847-1 | LTC Control Insp | LTC Output Voltage Level | 122.0 | VAC |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | LTCC000840 | LTCControl | 847-1 | LTC Control Insp | VRR Base Voltage AF | 123.0 | VAC |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | LTCC000840 | LTCControl | 847-1 | LTC Control Insp | VRR Base Voltage AL | 123.0 | VAC |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | LTCC000840 | LTCControl | 847-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | LTCC000840 | LTCControl | 847-1 | LTC Control Insp | All Connections OK? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Counter Readings | LTC As Found Counter | 31308 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Counter Readings | LTC As Left Counter | 31308 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Counter Readings | General Comments | | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Counter Readings | LTC Operations Since Last Insp | 390 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Readings | General Comments | | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Readings | LTC Totalizer Reading | 2928.00 | kw |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 8000 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Readings | Totalizer Meter Reading | .3660 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 48 | °F |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BCH000876 | Charger | 847-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BCH000876 | Charger | 847-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BCH000876 | Charger | 847-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BCH000876 | Charger | 847-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.0 | amps |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BCH000876 | Charger | 847-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BCH000876 | Charger | 847-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | BCH000876 | Charger | 847-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | General Comments | | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | General Comments | | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | YD000342 | Yard | 847-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | YD000342 | Yard | 847-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | YD000342 | Yard | 847-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | YD000342 | Yard | 847-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | YD000342 | Yard | 847-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | YD000342 | Yard | 847-Yard | Yard Patrol Inspection | Ambient Temp | 48 | °F |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | YD000342 | Yard | 847-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | YD000342 | Yard | 847-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | YD000342 | Yard | 847-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | YD000342 | Yard | 847-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | YD000342 | Yard | 847-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 11:38 | Distribution | Buchanan Quarterly Inspection | YD000342 | Yard | 847-Yard | Yard Patrol Inspection | General Comments | | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Readings | Switching Operations | 0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Readings | Operations This Read SF6 | 0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Readings | Operations Counter AL | 68 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Readings | Fault Operations | 0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Readings | General Comments | | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Readings | Operations Counter AF | 68 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | Ambient Temperature | 48 | °F |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | SF6 Pressure | 90 | psi |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | General Comments | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | General Comments | | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Operations Counter AF | 100 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Operations Counter AL | 100 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Operations This Read Vac | 5 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Switching Operations | 5 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Amps C Ø | 40.0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Amps B Ø | 60.0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Amps A Ø | 30.0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | 9 Month Operations | 9 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | General Comments | | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Operations Counter AF | 253 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Operations Counter AL | 253 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Operations This Read Vac | 2 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Amps B Ø | 30.0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Amps A Ø | 30.0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | 9 Month Operations | 12 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Fault Operations A Ø | 2 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Fault Adjusted Amps A Phase V | 8.63 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Amps C Ø | 30.0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Unknown Operations | 0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | 9 Month Operations | 9 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Amps A Ø | 180.0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Amps B Ø | 180.0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Amps C Ø | 180.0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Switching Operations | 5 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Operations This Read Vac | 5 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Operations Counter AL | 35 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Operations Counter AF | 35 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | General Comments | | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | LTCC000696 | LTCControl | 874-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | LTCC000696 | LTCControl | 874-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | LTCC000696 | LTCControl | 874-1 | LTC Control Insp | All Connections OK? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | LTCC000696 | LTCControl | 874-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | LTCC000696 | LTCControl | 874-1 | LTC Control Insp | General Comments | | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | LTCC000696 | LTCControl | 874-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | LTCC000696 | LTCControl | 874-1 | LTC Control Insp | LTC Output Voltage Level | 124.5 | VAC |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | LTCC000696 | LTCControl | 874-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Counter Readings | General Comments | | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Counter Readings | LTC As Found Counter | 16553 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Counter Readings | LTC As Left Counter | 16553 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Counter Readings | LTC Operations Since Last Insp | 511 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | General Comments | | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | General Comments | | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | General Comments | | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/18/2023 6:42 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Readings | LTC Totalizer Reading | 6013.44 | kw |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Readings | General Comments | | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Readings | Totalizer Meter Reading | .6264 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 65.0 | VDC |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 68.0 | VDC |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 48 | °F |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BCH001311 | Charger | 874-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BCH001311 | Charger | 874-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BCH001311 | Charger | 874-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BCH001311 | Charger | 874-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BCH001311 | Charger | 874-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BCH001311 | Charger | 874-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.7 | VDC |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BCH001311 | Charger | 874-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.7 | VDC |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | BCH001311 | Charger | 874-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | General Comments | | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | General Comments | | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | General Comments | | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | Ambient Temp | 48 | °F |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 9:59 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | General Comments | | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Amps C Ø | 80.0 | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Amps B Ø | 80.0 | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Operations Counter | 944 | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Amps A Ø | 80.0 | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Amps C Ø | 56.0 | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Amps B Ø | 47.0 | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Amps A Ø | 56.0 | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Operations Counter | 111 | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Amps C Ø | 80.0 | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Amps B Ø | 80.0 | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Amps A Ø | 80.0 | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Operations Counter | 1841 | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 122.5 | volts |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 137630 | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 130701 | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 122.4 | volts |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Operations Counter | 29 | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Amps A Ø | 2.0 | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Amps B Ø | 1.0 | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Amps C Ø | 3.0 | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | LTCC000912 | LTCControl | 656-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | LTCC000912 | LTCControl | 656-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | LTCC000912 | LTCControl | 656-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | LTCC000912 | LTCControl | 656-1 | LTC Control Insp | LTC Output Voltage Level | 124.5 | VAC |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | LTCC000912 | LTCControl | 656-1 | LTC Control Insp | All Connections OK? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | LTCC000912 | LTCControl | 656-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | LTCC000912 | LTCControl | 656-1 | LTC Control Insp | General Comments | | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | LTCC000912 | LTCControl | 656-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Counter Readings | LTC As Left Counter | 15207 | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Counter Readings | LTC As Found Counter | 15195 | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Counter Readings | General Comments | | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Counter Readings | LTC Operations Since Last Insp | 893 | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 130814 | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 122.5 | volts |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Max Tap Position | 2R | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Readings | Oil Temp Present | 33 | °C |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Readings | Totalizer Meter Reading | .0360 | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Readings | General Comments | | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Readings | LTC Totalizer Reading | 345.60 | kw |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Readings | General Comments | | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 7551.36 | kw |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Readings | Oil Temp Max | 60 | °C |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.0488 | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | General Comments | | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | General Comments | | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | General Comments | | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | Ambient Temp | 75 | °F |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | General Comments | | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | General Comments | | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Ambient Temp | 75 | °F |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | General Comments | | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 4/14/2023 14:47 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Amps A Ø | 37.0 | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Amps B Ø | 38.0 | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Amps C Ø | 38.0 | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/14/2023 14:48 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Operations Counter | 10 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | General Comments | | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.4 | volts |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Regulator As Left Counter | 54226 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | General Comments | | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Operations Counter AF | 353 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Operations Counter AL | 353 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Operations This Read Vac | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Amps B Ø | 227.0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Switching Operations | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Unknown Operations | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | 9 Month Operations | 1 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Amps C Ø | 248.0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Amps A Ø | 257.0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | General Comments | | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Unknown Operations | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Switching Operations | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Operations This Read Vac | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Amps A Ø | 59.0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Operations Counter AL | 278 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Operations Counter AF | 278 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | General Comments | | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Amps B Ø | 59.0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Amps C Ø | 63.0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | 9 Month Operations | 1 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | General Comments | | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | BCH001544 | Charger | 642-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | BCH001544 | Charger | 642-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | BCH001544 | Charger | 642-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .7 | amps |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | BCH001544 | Charger | 642-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | BCH001544 | Charger | 642-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | BCH001544 | Charger | 642-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 75 | °F |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.0 | VDC |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.0 | VDC |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | General Comments | | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | 9 Month Operations | 4 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Unknown Operations | 0 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Switching Operations | 0 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Operations This Read Vac | 1 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Operations Counter AL | 241 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Operations Counter AF | 240 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Maintenance Operations | 1 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Amps A Ø | 78.0 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | General Comments | BFTC | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Amps B Ø | 76.0 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Amps C Ø | 72.0 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Patrol Inspection | General Comments | | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | General Comments | | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | 9 Month Operations | 4 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Amps A Ø | 60.0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Amps B Ø | 60.0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Amps C Ø | 60.0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | General Comments | | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Unknown Operations | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Switching Operations | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Operations This Read Vac | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Operations Counter AL | 674 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Operations Counter AF | 674 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Operations Counter AL | 238 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Operations Counter AF | 237 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Maintenance Operations | 1 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | 9 Month Operations | 2 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Amps A Ø | 26.0 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Amps B Ø | 19.0 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Amps C Ø | 16.0 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | General Comments | BFTC | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Operations This Read Vac | 1 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Unknown Operations | 0 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Switching Operations | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | General Comments | | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Amps C Ø | 60.0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Amps B Ø | 60.0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Unknown Operations | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Switching Operations | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Operations This Read Vac | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | 9 Month Operations VCB New | 29 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | 9 Month Operations | 29 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Amps A Ø | 60.0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | General Comments | | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Operations Counter AF | 711 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Operations Counter AL | 711 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | General Comments | | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | General Comments | | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Reg Output Voltage Level | 122.6 | volts |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Regulator As Left Counter | 57224 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 44968 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.6 | volts |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | LTCC000618 | LTCControl | 642-1 B | LTC Control Insp | LTC Operation Checked? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | LTCC000618 | LTCControl | 642-1 B | LTC Control Insp | LTC Output Voltage Level | 123.6 | VAC |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | LTCC000618 | LTCControl | 642-1 B | LTC Control Insp | General Comments | | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | LTCC000618 | LTCControl | 642-1 B | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | LTCC000618 | LTCControl | 642-1 B | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | LTCC000618 | LTCControl | 642-1 B | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | LTCC000618 | LTCControl | 642-1 B | LTC Control Insp | All Connections OK? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | LTCC000618 | LTCControl | 642-1 B | LTC Control Insp | Follow-up Action Required? | n | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 52483 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Max Tap Position | 4L | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Min Tap Position | 2R | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Current Tap Position | 10L | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 34585 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Counter Readings | LTC Max Tap Position | 8R | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Counter Readings | LTC Operations Since Last Insp | 841 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Counter Readings | LTC As Left Counter | 80853 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Counter Readings | LTC As Found Counter | 80850 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Counter Readings | General Comments | | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Regulator As Left Counter | 55486 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Reg Output Voltage Level | 122.9 | volts |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | General Comments | | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Min Tap Position | 4R | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | LTCC000945 | LTCControl | 951-Offline-Distribution | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | LTCC000945 | LTCControl | 951-Offline-Distribution | LTC Control Insp | VRR Base Voltage AF | 124.5 | VAC |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | LTCC000945 | LTCControl | 951-Offline-Distribution | LTC Control Insp | General Comments | | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | LTCC000945 | LTCControl | 951-Offline-Distribution | LTC Control Insp | LTC Output Voltage Level | 124.7 | VAC |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | LTCC000945 | LTCControl | 951-Offline-Distribution | LTC Control Insp | LTC Operation Checked? | y | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | LTCC000945 | LTCControl | 951-Offline-Distribution | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | LTCC000945 | LTCControl | 951-Offline-Distribution | LTC Control Insp | Follow-up Action Required? | n | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | LTCC000945 | LTCControl | 951-Offline-Distribution | LTC Control Insp | All Connections OK? | y | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Readings | Winding Temp Present | 47 | °C |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Readings | Winding Temp Max | 55 | °C |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Readings | Totalizer Meter Reading | .8220 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Readings | General Comments | | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 7891.20 | kw |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Readings | Oil Temp Max | 51 | °C |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 20.00 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Readings | Oil Temp Max | 41 | °C |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Readings | LTC Totalizer Reading | 2822.40 | kw |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Readings | General Comments | | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Readings | Oil Temp Present | 34 | °C |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Readings | Totalizer Meter Reading | .2940 | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.1 | psi |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 12:05 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 25.00 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1987.20 | kw |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Readings | Oil Temp Present | 37 | °C |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .2760 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Readings | Winding Temp Max | 30 | °C |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Readings | Winding Temp Present | 30 | °C |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Readings | General Comments | | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | General Comments | | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | General Comments | | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | Ambient Temp | 75 | °F |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | General Comments | | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/14/2023 12:29 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | 9 Months Operations | 2 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Switching Operations | 2 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Operations This Read AM | 2 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Operations Counter AL | 118 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Operations Counter AF | 118 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Amps A Ø | 0.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Amps B Ø | 0.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Amps C Ø | 0.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Amps C Ø | 0.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Amps B Ø | 0.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Amps A Ø | 0.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | 9 Months Operations | 2 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | 9 Month Ops New | 1 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Switching Operations | 1 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Operations Counter AF | 425 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Operations Counter AL | 425 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Operations This Read AM | 1 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Patrol Inspection | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | 9 Months Operations | 7 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Operations This Read AM | 3 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Operations Counter AL | 242 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Amps A Ø | 275.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Amps B Ø | 250.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Operations Counter AF | 242 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Amps C Ø | 330.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | 9 Month Ops New | 4 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Switching Operations | 3 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Patrol Inspection | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Amps A Ø | 0.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | 9 Months Operations | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Switching Operations | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Operations This Read AM | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Operations Counter AL | 536 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Operations Counter AF | 536 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Amps B Ø | 0.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Amps C Ø | 0.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Patrol Inspection | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Amps C Ø | 100.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Amps B Ø | 100.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Amps A Ø | 100.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | 9 Months Operations | 2 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | 9 Month Ops New | 1 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Switching Operations | 1 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Operations This Read AM | 1 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Operations Counter AL | 237 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Operations Counter AF | 237 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Patrol Inspection | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Amps C Ø | 250.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Amps B Ø | 250.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Operations Counter AF | 86 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Operations Counter AL | 86 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Operations This Read AM | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | 9 Months Operations | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Switching Operations | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Amps A Ø | 250.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Patrol Inspection | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | PF000349 | PowerFuse | SW-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | PF000349 | PowerFuse | SW-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | PF000348 | PowerFuse | SW-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | PF000348 | PowerFuse | SW-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 0.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 0.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 0.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 11.18 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 11.18 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 1 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 1 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 4 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | IOC on B & C phase | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 999 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 999 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 4 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 2 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 100.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 762 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 762 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 6 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 6 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 6 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 100.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 100.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 100.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 100.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 100.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 646 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 646 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 6 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 7 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 1 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 6 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 528 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 528 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 20 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 300.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 20 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 20 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 300.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 300.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | PF000346 | PowerFuse | SW-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | PF000346 | PowerFuse | SW-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | PF000347 | PowerFuse | SW-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | PF000347 | PowerFuse | SW-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCC000334 | LTCControl | SW-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCC000334 | LTCControl | SW-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCC000334 | LTCControl | SW-TRANS 1 | LTC Control Insp | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCC000334 | LTCControl | SW-TRANS 1 | LTC Control Insp | All Connections OK? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Counter Readings | General Comments | ok | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Counter Readings | LTC As Left Counter | 12261 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Counter Readings | LTC As Found Counter | 12261 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 214 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 37 | °C |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 30 | °C |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 244 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 84460 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 84460 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Counter Readings | General Comments | This is the correct operation counter. The previous readings were inputed incorrectly. SW-B TRANS 1 & TRANS 1 were mixed up. | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Patrol Inspection | General Comments | | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Unknown Operations | 1 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Switching Operations | 1 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Amps B Ø | 82.0 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Operations This Read Vac | 2 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Amps A Ø | 79.0 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Operations Counter AL | 170 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Operations Counter AF | 170 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | General Comments | | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | 9 Month Operations | 2 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Fault Adjusted Amps C Phase V | 8.76 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Fault Adjusted Amps B Phase V | 8.76 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Fault Adjusted Amps A Phase V | 8.76 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Amps C Ø | 80.0 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Patrol Inspection | General Comments | | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Amps A Ø | 65.0 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Amps B Ø | 72.0 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Amps C Ø | 79.0 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Fault Adjusted Amps A Phase V | 17.52 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Fault Adjusted Amps B Phase V | 17.52 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Fault Adjusted Amps C Phase V | 17.52 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | General Comments | | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Operations Counter AF | 184 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Operations Counter AL | 184 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Operations This Read Vac | 3 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Switching Operations | 1 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | 9 Month Operations | 10 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Unknown Operations | 2 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | Tap changer needs a new screw in desiccant filter. | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | LTCC000824 | LTCControl | 691-1 | LTC Control Insp | All Connections OK? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | LTCC000824 | LTCControl | 691-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | LTCC000824 | LTCControl | 691-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | LTCC000824 | LTCControl | 691-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | LTCC000824 | LTCControl | 691-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | LTCC000824 | LTCControl | 691-1 | LTC Control Insp | LTC Output Voltage Level | 124.5 | VAC |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | LTCC000824 | LTCControl | 691-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | LTCC000824 | LTCControl | 691-1 | LTC Control Insp | General Comments | | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Counter Readings | General Comments | | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Counter Readings | LTC As Found Counter | 15620 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Counter Readings | LTC As Left Counter | 15632 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Counter Readings | LTC Min Tap Position | 5R | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Counter Readings | LTC Operations Since Last Insp | 829 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 6000 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Readings | LTC Totalizer Reading | 3852.00 | kw |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Readings | General Comments | | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Readings | Totalizer Meter Reading | .6420 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BCH001334 | Charger | 691-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .8 | amps |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BCH001334 | Charger | 691-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BCH001334 | Charger | 691-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BCH001334 | Charger | 691-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BCH001334 | Charger | 691-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BCH001334 | Charger | 691-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Broom on Site? | n | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Door Alarms OK? | n | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Floor Swept? | n | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | General Comments | | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 85 | °F |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.0 | VDC |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | General Comments | turned heater down | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | General Comments | | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Fence Ties Intact? | n | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | n | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Fence Grounds in Place? | n | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | General Comments | trees growing over fence | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 46 | °C |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 35 | °C |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 34 | °C |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 43 | °C |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 34 | °C |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 46 | °C |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 44 | °C |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 34 | °C |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | Had to repair one fan. Fan needed a new capacitor. | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | 9 Month Operations | 2 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Amps A Ø | 145.0 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Amps B Ø | 135.0 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Amps C Ø | 125.0 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | General Comments | | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Operations Counter AF | 192 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Operations Counter AL | 192 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Operations This Read Vac | 0 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Switching Operations | 0 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Unknown Operations | 0 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Patrol Inspection | General Comments | | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Operations Counter AF | 243 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Operations Counter AL | 243 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Operations This Read Vac | 0 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Switching Operations | 0 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | General Comments | | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | 9 Month Operations | 2 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Amps A Ø | 260.0 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Amps B Ø | 235.0 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Amps C Ø | 255.0 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | General Comments | | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 122.0 | volts |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Fans Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Fans Operational? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 14154 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 122.0 | volts |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 14413 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | PF001262 | PowerFuse | SW-B 14KV GND RLY POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | PF001262 | PowerFuse | SW-B 14KV GND RLY POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | PF001153 | PowerFuse | SW-B 14KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | PF001153 | PowerFuse | SW-B 14KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 15918 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 122.0 | volts |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BAT000089 | Battery | SW-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BAT000089 | Battery | SW-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BAT000089 | Battery | SW-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BAT000089 | Battery | SW-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BAT000089 | Battery | SW-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BAT000089 | Battery | SW-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BAT000089 | Battery | SW-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BAT000089 | Battery | SW-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BAT000089 | Battery | SW-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BAT000089 | Battery | SW-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BAT000089 | Battery | SW-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BAT000089 | Battery | SW-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Ambient Temp | 75 | °F |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .6450 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 2064.00 | kw |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Readings | General Comments | | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Readings | Oil Temp Max | 60 | °C |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Fault Operations B Ø | 3 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Fault Operations A Ø | 3 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | 9 Month Operations VCB New | 33 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | 9 Month Operations | 50 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Amps C Ø | 35.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Amps B Ø | 35.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Amps A Ø | 35.0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Fault Adjusted Amps C Phase V | 28.64 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Fault Adjusted Amps B Phase V | 28.64 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Fault Adjusted Amps A Phase V | 28.64 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Fault Operations C Ø | 3 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Operations Counter AF | 250 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Unknown Operations | 0 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Switching Operations | 8 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | General Comments | IOC & TOC on all three phases. | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Operations Counter AL | 250 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Operations This Read Vac | 17 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 52.50 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Counter Readings | General Comments | | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Counter Readings | LTC As Found Counter | 87581 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Counter Readings | LTC As Left Counter | 87581 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Counter Readings | LTC Operations Since Last Insp | 350 | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | YD000117 | Yard | 691-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | YD000117 | Yard | 691-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | YD000117 | Yard | 691-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | YD000117 | Yard | 691-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | YD000117 | Yard | 691-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | YD000117 | Yard | 691-Yard | Yard Patrol Inspection | Ambient Temp | 72 | °F |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | YD000117 | Yard | 691-Yard | Yard Patrol Inspection | General Comments | | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | YD000117 | Yard | 691-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | YD000117 | Yard | 691-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | YD000117 | Yard | 691-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | YD000117 | Yard | 691-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/14/2023 11:26 | Distribution | Cloverlick Quarterly Inspection | YD000117 | Yard | 691-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Readings | LTC Totalizer Reading | 3129.60 | kw |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Readings | General Comments | | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Readings | Totalizer Meter Reading | .9780 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BCH001568 | Charger | 735-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BCH001568 | Charger | 735-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BCH001568 | Charger | 735-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BCH001568 | Charger | 735-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.4 | amps |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BCH001568 | Charger | 735-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BCH001568 | Charger | 735-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BCH001568 | Charger | 735-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BCH001568 | Charger | 735-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000206 | WithLTC | SW-B TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000206 | WithLTC | SW-B TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000206 | WithLTC | SW-B TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000206 | WithLTC | SW-B TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000206 | WithLTC | SW-B TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000206 | WithLTC | SW-B TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000206 | WithLTC | SW-B TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000206 | WithLTC | SW-B TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000206 | WithLTC | SW-B TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000206 | WithLTC | SW-B TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | General Comments | | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | General Comments | | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | General Comments | | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | Ambient Temp | 70 | °F |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | LTCC000937 | LTCControl | 735-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | LTCC000937 | LTCControl | 735-2 | LTC Control Insp | All Connections OK? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | LTCC000937 | LTCControl | 735-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | LTCC000937 | LTCControl | 735-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | LTCC000937 | LTCControl | 735-2 | LTC Control Insp | General Comments | | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | LTCC000937 | LTCControl | 735-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | LTCC000937 | LTCControl | 735-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | LTCC000937 | LTCControl | 735-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/14/2023 11:18 | Distribution | Scott Street Quarterly Inspection | LTCC000937 | LTCControl | 735-2 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCC000013 | LTCControl | 412-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCC000013 | LTCControl | 412-2 | LTC Control Insp | VRR Base Voltage AL | 123.0 | VAC |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCC000013 | LTCControl | 412-2 | LTC Control Insp | VRR Base Voltage AF | 123.0 | VAC |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCC000013 | LTCControl | 412-2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCC000013 | LTCControl | 412-2 | LTC Control Insp | LTC Output Voltage Level | 122.0 | VAC |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCC000013 | LTCControl | 412-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCC000013 | LTCControl | 412-2 | LTC Control Insp | General Comments | | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCC000013 | LTCControl | 412-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCC000013 | LTCControl | 412-2 | LTC Control Insp | All Connections OK? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 37 | °C |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 47 | °C |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 44 | °C |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 36 | °C |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 47 | °C |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 37 | °C |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 47 | °C |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 37 | °C |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Counter Readings | General Comments | | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Counter Readings | LTC As Found Counter | 22629 | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Counter Readings | LTC As Left Counter | 22629 | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Counter Readings | LTC Current Tap Position | 7L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Counter Readings | LTC Max Tap Position | 5L | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Counter Readings | LTC Operations Since Last Insp | 338 | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 400 | psi |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Readings | Winding Temp Present | 55 | °C |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Readings | Winding Temp Max | 55 | °C |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Readings | Totalizer Meter Reading | .9480 | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Readings | General Comments | | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Readings | LTC Totalizer Reading | 13651.20 | kw |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCC000846 | LTCControl | SW-TRANS 2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCC000846 | LTCControl | SW-TRANS 2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCC000846 | LTCControl | SW-TRANS 2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCC000846 | LTCControl | SW-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCC000846 | LTCControl | SW-TRANS 2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCC000846 | LTCControl | SW-TRANS 2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCC000846 | LTCControl | SW-TRANS 2 | LTC Control Insp | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCC000846 | LTCControl | SW-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCC000846 | LTCControl | SW-TRANS 2 | LTC Control Insp | All Connections OK? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Counter Readings | LTC Operations Since Last Insp | 303 | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Counter Readings | General Comments | | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Counter Readings | LTC As Found Counter | 38884 | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Counter Readings | LTC As Left Counter | 38884 | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCC000962 | LTCControl | 412-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCC000962 | LTCControl | 412-1 | LTC Control Insp | VRR Base Voltage AL | 123.0 | VAC |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCC000962 | LTCControl | 412-1 | LTC Control Insp | VRR Base Voltage AF | 123.0 | VAC |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCC000962 | LTCControl | 412-1 | LTC Control Insp | LTC Output Voltage Level | 122.0 | VAC |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCC000962 | LTCControl | 412-1 | LTC Control Insp | All Connections OK? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCC000962 | LTCControl | 412-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCC000962 | LTCControl | 412-1 | LTC Control Insp | General Comments | | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | LTCC000962 | LTCControl | 412-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Counter Readings | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 6313 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 6313 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 256 | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 40 | °C |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 30 | °C |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 3.0 | psi |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 44 | °C |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 36 | °C |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BCH001600 | Charger | SW-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BCH001600 | Charger | SW-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BCH001600 | Charger | SW-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BCH001600 | Charger | SW-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BCH001600 | Charger | SW-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 4.8 | amps |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BCH001600 | Charger | SW-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BCH001600 | Charger | SW-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 4/14/2023 11:40 | Distribution | Stewart Quarterly Inspection | BCH001600 | Charger | SW-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.000 | millivolts |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Readings | LTC Totalizer Reading | 7212.48 | kw |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Readings | General Comments | | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Readings | Totalizer Meter Reading | .7513 | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Readings | Winding Temp Max | 50 | °C |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Readings | Winding Temp Present | 45 | °C |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Readings | Switching Operations | 0 | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Readings | Operations This Read SF6 | 0 | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Readings | Operations Counter AL | 52 | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Readings | Operations Counter AF | 52 | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Readings | General Comments | | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Readings | Fault Operations | 0 | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | General Comments | | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Ambient Temperature | 70 | °F |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | SF6 Pressure Indicator | good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | General Comments | | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | FE000673 | Fence | 412-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | FE000673 | Fence | 412-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | FE000673 | Fence | 412-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | FE000673 | Fence | 412-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | FE000673 | Fence | 412-Fence | Fence Patrol Inspection | General Comments | | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | FE000673 | Fence | 412-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | FE000673 | Fence | 412-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | FE000673 | Fence | 412-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | FE000673 | Fence | 412-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | FE000673 | Fence | 412-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | YD000680 | Yard | 412-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | YD000680 | Yard | 412-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | YD000680 | Yard | 412-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | YD000680 | Yard | 412-Yard | Yard Patrol Inspection | General Comments | | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | YD000680 | Yard | 412-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | YD000680 | Yard | 412-Yard | Yard Patrol Inspection | Ambient Temp | 70 | °F |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | YD000680 | Yard | 412-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/14/2023 11:07 | Distribution | UK West Quarterly Inspection | YD000680 | Yard | 412-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Switching Operations | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Operations Counter AL | 154 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Operations Counter AF | 154 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | General Comments | | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | 9 Month Operations | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Operations Counter AL | 255 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Operations Counter AF | 255 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Amps C Ø | 300.0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Amps B Ø | 300.0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Amps A Ø | 300.0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | 9 Month Operations | 1 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Switching Operations | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Unknown Operations | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | General Comments | | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | General Comments | | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | 9 Month Operations | 1 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Switching Operations | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Operations Counter AF | 553 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Operations Counter AL | 553 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | General Comments | | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Amps A Ø | 400.0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Amps B Ø | 400.0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Amps C Ø | 400.0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Unknown Operations | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | General Comments | | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Unknown Operations | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Switching Operations | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | 9 Month Operations | 2 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Amps A Ø | 0.0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | General Comments | | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Operations Counter AF | 227 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Amps B Ø | 0.0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Amps C Ø | 0.0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Operations Counter AL | 227 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Operations This Read Vac | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Patrol Inspection | General Comments | | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | 9 Month Operations | 5 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Switching Operations | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Unknown Operations | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Amps A Ø | 105.0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Amps B Ø | 100.0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Amps C Ø | 110.0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Operations This Read Vac | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Operations Counter AL | 242 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | General Comments | | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Operations Counter AF | 242 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | General Comments | | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Readings | Winding Temp Present | 50 | °C |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Readings | Winding Temp Max | 56 | °C |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Readings | Totalizer Meter Reading | .4490 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Readings | Oil Temp Present | 50 | °C |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Readings | LTC Totalizer Reading | 10776.00 | kw |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Readings | General Comments | | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1000 | psi |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | LTCC000218 | LTCControl | 896-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | LTCC000218 | LTCControl | 896-2 | LTC Control Insp | All Connections OK? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | LTCC000218 | LTCControl | 896-2 | LTC Control Insp | General Comments | | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | LTCC000218 | LTCControl | 896-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | LTCC000218 | LTCControl | 896-2 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | LTCC000218 | LTCControl | 896-2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | LTCC000218 | LTCControl | 896-2 | LTC Control Insp | VRR Base Voltage AF | 123.0 | VAC |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | LTCC000218 | LTCControl | 896-2 | LTC Control Insp | VRR Base Voltage AL | 123.0 | VAC |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | LTCC000218 | LTCControl | 896-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Counter Readings | LTC Operations Since Last Insp | 235 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Counter Readings | General Comments | | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Counter Readings | LTC As Found Counter | 25472 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Counter Readings | LTC As Left Counter | 25472 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 41 | °C |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 47 | °C |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | LTCC000886 | LTCControl | 896-1 | LTC Control Insp | VRR Base Voltage AL | 123.0 | VAC |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | LTCC000886 | LTCControl | 896-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | LTCC000886 | LTCControl | 896-1 | LTC Control Insp | VRR Base Voltage AF | 123.0 | VAC |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | LTCC000886 | LTCControl | 896-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | LTCC000886 | LTCControl | 896-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | LTCC000886 | LTCControl | 896-1 | LTC Control Insp | All Connections OK? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | LTCC000886 | LTCControl | 896-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | LTCC000886 | LTCControl | 896-1 | LTC Control Insp | General Comments | | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Counter Readings | LTC Operations Since Last Insp | 354 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Counter Readings | General Comments | | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Counter Readings | LTC Current Tap Position | 10L | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Counter Readings | LTC As Left Counter | 51050 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Counter Readings | LTC As Found Counter | 51050 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Readings | General Comments | | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Readings | Winding Temp Max | 50 | °C |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Readings | Totalizer Meter Reading | .4850 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Readings | LTC Totalizer Reading | 11640.00 | kw |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Readings | Winding Temp Present | 50 | °C |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/14/2023 10:59 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | General Comments | | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Operations Counter AF | 184 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Operations Counter AL | 184 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Operations This Read Vac | 3 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Switching Operations | 1 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Unknown Operations | 0 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | 9 Month Operations | 6 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Amps A Ø | 17.0 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Amps B Ø | 16.0 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Amps C Ø | 18.0 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Fault Adjusted Amps B Phase V | 2.94 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Fault Operations C Ø | 1 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Fault Operations B Ø | 1 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Fault Adjusted Amps C Phase V | 2.94 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Patrol Inspection | General Comments | | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Unknown Operations | 0 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Switching Operations | 0 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Operations This Read Vac | 0 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Amps A Ø | 32.0 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Amps C Ø | 47.0 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Amps B Ø | 44.0 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | General Comments | | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Operations Counter AF | 159 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Operations Counter AL | 159 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | 9 Month Operations | 5 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Patrol Inspection | General Comments | | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | 9 Month Operations | 5 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | General Comments | | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Operations Counter AF | 228 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Operations Counter AL | 228 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Operations This Read Vac | 1 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Switching Operations | 0 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Unknown Operations | 0 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Amps C Ø | 124.0 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Fault Adjusted Amps A Phase V | 2.94 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Amps A Ø | 124.0 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Amps B Ø | 122.0 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Patrol Inspection | General Comments | | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Counter Readings | LTC Operations Since Last Insp | 882 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Counter Readings | General Comments | | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Counter Readings | LTC As Left Counter | 221902 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Counter Readings | LTC As Found Counter | 221902 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Counter Readings | LTC Max Tap Position | 7R | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | LTCC000626 | LTCControl | 408-1 | LTC Control Insp | General Comments | | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | LTCC000626 | LTCControl | 408-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | LTCC000626 | LTCControl | 408-1 | LTC Control Insp | All Connections OK? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | LTCC000626 | LTCControl | 408-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | LTCC000626 | LTCControl | 408-1 | LTC Control Insp | LTC Output Voltage Level | 123.9 | VAC |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | LTCC000626 | LTCControl | 408-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | LTCC000626 | LTCControl | 408-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | LTCC000626 | LTCControl | 408-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | LTCC000626 | LTCControl | 408-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Readings | Totalizer Meter Reading | .5596 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Readings | Oil Temp Present | 38 | °C |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Readings | Oil Temp Max | 38 | °C |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Readings | LTC Totalizer Reading | 5372.16 | kw |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Readings | General Comments | | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BCH001364 | Charger | 408-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BCH001364 | Charger | 408-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BCH001364 | Charger | 408-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BCH001364 | Charger | 408-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BCH001364 | Charger | 408-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.4 | amps |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BCH001364 | Charger | 408-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BCH001364 | Charger | 408-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BCH001364 | Charger | 408-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 75 | °F |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | General Comments | | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | General Comments | | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | General Comments | | |
| 4/14/2023 10:30 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | Ambient Temp | 75 | °F |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Switching Operations | 1 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Operations This Read Vac | 2 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Operations Counter AL | 225 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Unknown Operations | 1 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Operations Counter AF | 224 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | General Comments | | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Fault Adjusted Amps C Phase V | 9.07 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Fault Adjusted Amps B Phase V | 9.07 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Fault Adjusted Amps A Phase V | 9.07 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Amps C Ø | 100.0 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Amps B Ø | 104.0 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Amps A Ø | 119.0 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | 9 Month Operations | 2 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | General Comments | | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Amps A Ø | 76.0 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Amps B Ø | 82.0 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | 9 Month Operations | 2 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Amps C Ø | 84.0 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Fault Adjusted Amps A Phase V | 9.07 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Fault Adjusted Amps B Phase V | 9.07 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Fault Adjusted Amps C Phase V | 9.07 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Unknown Operations | 1 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Switching Operations | 1 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Operations This Read Vac | 2 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Operations Counter AL | 367 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Fault Operations Ground | 0 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Operations Counter AF | 366 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | General Comments | | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | General Comments | | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | LTCC000229 | LTCControl | 842-1 | LTC Control Insp | LTC Output Voltage Level | 124.3 | VAC |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | LTCC000229 | LTCControl | 842-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | LTCC000229 | LTCControl | 842-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | LTCC000229 | LTCControl | 842-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | LTCC000229 | LTCControl | 842-1 | LTC Control Insp | All Connections OK? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | LTCC000229 | LTCControl | 842-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | LTCC000229 | LTCControl | 842-1 | LTC Control Insp | General Comments | | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | LTCC000229 | LTCControl | 842-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Counter Readings | LTC Operations Since Last Insp | 895 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Counter Readings | General Comments | | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Counter Readings | LTC Min Tap Position | 6R | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Counter Readings | LTC As Found Counter | 260891 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Counter Readings | LTC As Left Counter | 260902 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Readings | General Comments | | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Readings | LTC Totalizer Reading | 2053.44 | kw |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Readings | Totalizer Meter Reading | .8556 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 10.00 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | BCH001557 | Charger | 842-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | BCH001557 | Charger | 842-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | BCH001557 | Charger | 842-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | BCH001557 | Charger | 842-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | BCH001557 | Charger | 842-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | BCH001557 | Charger | 842-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 2.000 | millivolts |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | BCH001557 | Charger | 842-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | BCH001557 | Charger | 842-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Exp/Missing Not Repl | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 25.0 | VDC |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 25.0 | VDC |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | General Comments | | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | General Comments | | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | General Comments | may need 8 more warning signs | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | YD000101 | Yard | 842-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | YD000101 | Yard | 842-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | YD000101 | Yard | 842-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | YD000101 | Yard | 842-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | YD000101 | Yard | 842-Yard | Yard Patrol Inspection | General Comments | | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | YD000101 | Yard | 842-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | YD000101 | Yard | 842-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | YD000101 | Yard | 842-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | YD000101 | Yard | 842-Yard | Yard Patrol Inspection | Ambient Temp | 65 | °F |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | YD000101 | Yard | 842-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | YD000101 | Yard | 842-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/14/2023 10:23 | Distribution | Cumberland Quarterly Inspection | YD000101 | Yard | 842-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Readings | 9 Months Operations OCB New | 0 | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Readings | General Comments | | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Readings | Follow-up Action Required? | n | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Readings | Fault Operations | 0 | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Readings | Maintenance Operations | 0 | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Readings | Number of Ops last 9 Months | 0 | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Readings | Operations Counter AL | 31 | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Readings | Operations This Read Oil | 0 | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Readings | Switching Operations | 0 | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Readings | Unknown Operations | 0 | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Readings | Operations Counter AF | 31 | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Hydraulic Pressure Acceptable? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Hydraulic Oil Levels OK? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Hydraulic Leaks | None | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Tank Oil Level | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | General Comments | | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | LTCC000932 | LTCControl | 475-1 | LTC Control Insp | All Connections OK? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | LTCC000932 | LTCControl | 475-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | LTCC000932 | LTCControl | 475-1 | LTC Control Insp | General Comments | | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | LTCC000932 | LTCControl | 475-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | LTCC000932 | LTCControl | 475-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | LTCC000932 | LTCControl | 475-1 | LTC Control Insp | LTC Output Voltage Level | 122.0 | VAC |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | LTCC000932 | LTCControl | 475-1 | LTC Control Insp | VRR Base Voltage AF | 123.0 | VAC |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | LTCC000932 | LTCControl | 475-1 | LTC Control Insp | VRR Base Voltage AL | 123.0 | VAC |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Counter Readings | General Comments | | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Counter Readings | LTC As Found Counter | 57568 | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Counter Readings | LTC As Left Counter | 57568 | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Counter Readings | LTC Min Tap Position | 13L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Counter Readings | LTC Operations Since Last Insp | 331 | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Readings | Totalizer Meter Reading | .5218 | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Readings | LTC Totalizer Reading | 12523.20 | kw |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Readings | General Comments | | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | BCH001032 | Charger | 475-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | BCH001032 | Charger | 475-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 132.0 | VDC |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | BCH001032 | Charger | 475-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 132.0 | VDC |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | BCH001032 | Charger | 475-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.8 | amps |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | BCH001032 | Charger | 475-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | BCH001032 | Charger | 475-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | BCH001032 | Charger | 475-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | BCH001032 | Charger | 475-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | BAT001468 | Battery | 475-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | BAT001468 | Battery | 475-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | BAT001468 | Battery | 475-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | BAT001468 | Battery | 475-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | BAT001468 | Battery | 475-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | BAT001468 | Battery | 475-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | BAT001468 | Battery | 475-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | BAT001468 | Battery | 475-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | BAT001468 | Battery | 475-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | BAT001468 | Battery | 475-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | BAT001468 | Battery | 475-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | BAT001468 | Battery | 475-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 66 | °F |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | BAT001468 | Battery | 475-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | General Comments | | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | General Comments | | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | General Comments | | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Ambient Temp | 66 | °F |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/14/2023 7:55 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 424962 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 424962 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Counter Readings | General Comments | | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 10L | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 7L | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 2205 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 8 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 8 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 10 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 9 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 77179 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 77179 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Counter Readings | General Comments | | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | needs nirto | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 27 | °C |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 57 | °C |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Patrol Inspection | General Comments | | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Operations Counter AF | 34896 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | General Comments | | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Switching Operations | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Operations This Read AM | 1 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Operations Counter AL | 34896 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Fault Operations C Ø | 1 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Fault Adjusted Amps C Phase AM | 9.55 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Amps C Ø | 260.0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Amps B Ø | 260.0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Amps A Ø | 100.0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | 9 Months Operations | 1 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Unknown Operations | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Patrol Inspection | General Comments | | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Operations This Read AM | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Switching Operations | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Unknown Operations | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Operations Counter AL | 326 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Operations Counter AF | 326 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | General Comments | | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Amps A Ø | 135.0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | 9 Months Operations | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Amps C Ø | 125.0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Amps B Ø | 125.0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Patrol Inspection | General Comments | | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Amps B Ø | 160.0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Operations Counter AF | 1302 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Operations Counter AL | 1302 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Amps C Ø | 200.0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Operations This Read AM | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Switching Operations | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Unknown Operations | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | 9 Months Operations | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Amps A Ø | 140.0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Patrol Inspection | General Comments | | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | 9 Months Operations | 2 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Fault Operations B Ø | 2 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Unknown Operations | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Switching Operations | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Operations This Read AM | 2 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Operations Counter AL | 411 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Operations Counter AF | 411 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 19.09 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Amps C Ø | 140.0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Amps B Ø | 90.0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Amps A Ø | 50.0 | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | General Comments | | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | BCH000129 | Charger | FC-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | BCH000129 | Charger | FC-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | BCH000129 | Charger | FC-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | BCH000129 | Charger | FC-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | BCH000129 | Charger | FC-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.8 | VDC |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | BCH000129 | Charger | FC-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.8 | VDC |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | BCH000129 | Charger | FC-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | CH000453 | ControlHouse | FC-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | CH000453 | ControlHouse | FC-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | CH000453 | ControlHouse | FC-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | CH000453 | ControlHouse | FC-Battery Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | CH000453 | ControlHouse | FC-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | CH000453 | ControlHouse | FC-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | CH000453 | ControlHouse | FC-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | CH000453 | ControlHouse | FC-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | CH000453 | ControlHouse | FC-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | Vegetation | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | General Comments | | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | General Comments | | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PF001305 | PowerFuse | FC-4KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PF001305 | PowerFuse | FC-4KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PF001305 | PowerFuse | FC-4KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PF001304 | PowerFuse | FC-4KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PF001304 | PowerFuse | FC-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/13/2023 16:05 | Distribution | Falls City Quarterly Inspection | PF001304 | PowerFuse | FC-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Amps C Ø | 10.0 | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Amps B Ø | 6.0 | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Amps A Ø | 8.0 | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | General Comments | 26.8/24.8 | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Operations Counter | 18 | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Amps B Ø | 47.0 | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Amps C Ø | 66.0 | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Operations Counter | 13 | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Amps A Ø | 48.0 | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | General Comments | 26.9/24.8 | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | LTCC000760 | LTCControl | 499-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | LTCC000760 | LTCControl | 499-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | LTCC000760 | LTCControl | 499-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | LTCC000760 | LTCControl | 499-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | LTCC000760 | LTCControl | 499-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | LTCC000760 | LTCControl | 499-1 | LTC Control Insp | All Connections OK? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | LTCC000760 | LTCControl | 499-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | LTCC000760 | LTCControl | 499-1 | LTC Control Insp | General Comments | | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Counter Readings | General Comments | | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Counter Readings | LTC As Found Counter | 286710 | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Counter Readings | LTC As Left Counter | 286718 | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Counter Readings | LTC Operations Since Last Insp | 663 | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Readings | Oil Temp Max | 56 | °C |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Readings | Totalizer Meter Reading | .8390 | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Readings | LTC Totalizer Reading | 4027.20 | kw |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Readings | General Comments | | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | General Comments | | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | n | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | General Comments | large tree growing over top of fence to the right of the station. tree in customer yard. | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | n | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | YD000082 | Yard | 499-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | YD000082 | Yard | 499-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | YD000082 | Yard | 499-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | YD000082 | Yard | 499-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | YD000082 | Yard | 499-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | YD000082 | Yard | 499-Yard | Yard Patrol Inspection | Ambient Temp | 85 | °F |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | YD000082 | Yard | 499-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | YD000082 | Yard | 499-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | YD000082 | Yard | 499-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | YD000082 | Yard | 499-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | YD000082 | Yard | 499-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | YD000082 | Yard | 499-Yard | Yard Patrol Inspection | General Comments | small wash out to the left of entrance gate washing gravel into customer yard | |
| 4/13/2023 14:07 | Distribution | Kentenia Quarterly Inspection | YD000082 | Yard | 499-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Amps C Ø | 310.0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Amps B Ø | 310.0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Amps A Ø | 310.0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | 9 Month Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Operations Counter AL | 151 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Operations Counter AF | 151 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | 9 Month Operations | 3 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Amps A Ø | 40.0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Operations Counter AF | 220 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Operations Counter AL | 220 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Operations This Read Vac | 1 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Fault Adjusted Amps A Phase V | 12.55 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Amps C Ø | 40.0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Amps B Ø | 55.0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Amps B Ø | 95.0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Amps A Ø | 95.0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | 9 Month Operations | 2 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Amps C Ø | 90.0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Operations Counter AF | 197 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Operations Counter AL | 197 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Operations This Read Vac | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Operations This Read Vac | 2 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Operations Counter AL | 224 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Operations Counter AF | 224 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Fault Operations C Ø | 1 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Fault Operations B Ø | 1 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Amps C Ø | 130.0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Amps B Ø | 130.0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Amps A Ø | 140.0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | 9 Month Operations | 10 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Fault Adjusted Amps B Phase V | 12.55 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Fault Adjusted Amps C Phase V | 12.55 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Operations Counter AF | 196 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Operations Counter AL | 196 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | 9 Month Operations | 2 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Amps B Ø | 265.0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Operations Counter AF | 190 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Operations Counter AL | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Amps A Ø | 250.0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Amps C Ø | 250.0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | 9 Month Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCC000796 | LTCControl | 621-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCC000796 | LTCControl | 621-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCC000796 | LTCControl | 621-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCC000796 | LTCControl | 621-2 | LTC Control Insp | All Connections OK? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCC000796 | LTCControl | 621-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCC000796 | LTCControl | 621-2 | LTC Control Insp | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCC000796 | LTCControl | 621-2 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCC000796 | LTCControl | 621-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Counter Readings | LTC Operations Since Last Insp | 391 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Counter Readings | LTC As Left Counter | 12593 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Counter Readings | LTC As Found Counter | 12593 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Counter Readings | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 37 | °C |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 32 | °C |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Readings | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Readings | LTC Totalizer Reading | 13488.00 | kw |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Readings | Oil Temp Max | 42 | °C |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Readings | Oil Temp Present | 36 | °C |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Readings | Winding Temp Present | 36 | °C |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Readings | Winding Temp Max | 42 | °C |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Readings | Totalizer Meter Reading | .5620 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1100 | psi |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | 9 Month Operations | 2 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Operations This Read Vac | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Operations Counter AL | 225 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Amps A Ø | 110.0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Amps B Ø | 125.0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Operations Counter AF | 225 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Amps C Ø | 100.0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Switching Operations | 2 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Amps C Ø | 145.0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Fault Adjusted Amps A Phase V | 37.65 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Fault Adjusted Amps B Phase V | 37.65 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Fault Operations A Ø | 3 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Fault Operations B Ø | 3 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Amps A Ø | 145.0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Amps B Ø | 155.0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | 9 Month Operations | 12 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Operations This Read Vac | 8 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Operations Counter AL | 210 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Operations Counter AF | 210 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Operations Counter AF | 197 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Operations Counter AL | 197 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Operations This Read Vac | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | 9 Month Operations | 3 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Amps C Ø | 60.0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Amps A Ø | 70.0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Amps B Ø | 45.0 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Readings | Totalizer Meter Reading | .6740 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Readings | Winding Temp Max | 60 | °C |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Readings | Winding Temp Present | 45 | °C |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Readings | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Readings | LTC Totalizer Reading | 16176.00 | kw |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCC000690 | LTCControl | 621-1 | LTC Control Insp | All Connections OK? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCC000690 | LTCControl | 621-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCC000690 | LTCControl | 621-1 | LTC Control Insp | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCC000690 | LTCControl | 621-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCC000690 | LTCControl | 621-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCC000690 | LTCControl | 621-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCC000690 | LTCControl | 621-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | LTCC000690 | LTCControl | 621-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Counter Readings | LTC As Left Counter | 11151 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Counter Readings | LTC As Found Counter | 11151 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Counter Readings | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Counter Readings | LTC Operations Since Last Insp | 645 | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | MOD Motor Jaw Coupling | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | MOD Cabinet Internals Clean? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | MOD Cabinet Heater functional? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Follow-up Action Required? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | General Comments | RIGHT SIDE BACK CORNER AND MID WAY DOWN BACK FENCE. | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | Ambient Temp | 68 | °F |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | General Comments | | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/13/2023 13:44 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | PT000854 | PT | ML-12KV TR 3 POT | PT Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | PT000854 | PT | ML-12KV TR 3 POT | PT Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | PT000854 | PT | ML-12KV TR 3 POT | PT Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | PT000854 | PT | ML-12KV TR 3 POT | PT Patrol Inspection | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | PT000854 | PT | ML-12KV TR 3 POT | PT Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | PT000854 | PT | ML-12KV TR 3 POT | PT Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | PT000854 | PT | ML-12KV TR 3 POT | PT Patrol Inspection | PT Free of Leaks? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | PT000854 | PT | ML-12KV TR 3 POT | PT Patrol Inspection | Tank Oil Level | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Operations Counter AL | 355 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Operations Counter AF | 355 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Amps C Ø | 0.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Amps B Ø | 0.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Amps A Ø | 0.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | 9 Month Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Amps B Ø | 0.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Amps C Ø | 0.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Operations Counter AF | 156 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Operations Counter AL | 156 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Amps A Ø | 0.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | 9 Month Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Amps C Ø | 57.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Amps B Ø | 58.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Amps A Ø | 55.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | 9 Month Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Operations Counter AF | 267 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Operations Counter AL | 267 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Operations Counter AL | 383 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Operations Counter AF | 383 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | 9 Month Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Amps A Ø | 50.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Amps B Ø | 44.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Amps C Ø | 32.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Amps A Ø | 204.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Operations Counter AL | 585 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Amps B Ø | 190.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Operations Counter AF | 585 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Amps C Ø | 184.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | 9 Month Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | 9 Month Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Amps A Ø | 242.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Amps C Ø | 216.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Amps B Ø | 230.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Operations Counter AF | 416 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Operations Counter AL | 416 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | General Comments | AB Phase IOC | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Fault Operations B Ø | 1 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Fault Adjusted Amps B Phase V | 11.18 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Fault Adjusted Amps A Phase V | 11.18 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Amps C Ø | 114.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Amps B Ø | 128.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Amps A Ø | 124.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | 9 Month Operations | 4 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Operations Counter AF | 623 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Operations Counter AL | 623 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Operations This Read Vac | 2 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Switching Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Operations This Read Vac | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | 9 Month Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Amps A Ø | 689.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Amps B Ø | 665.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Amps C Ø | 627.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Operations Counter AL | 390 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Operations Counter AF | 390 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Patrol Inspection | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | PF000250 | PowerFuse | ML-12KV TR 3 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | PF000250 | PowerFuse | ML-12KV TR 3 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | PF000250 | PowerFuse | ML-12KV TR 3 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | PF000248 | PowerFuse | ML-STA SER NO 3 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | PF000248 | PowerFuse | ML-STA SER NO 3 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | PF000248 | PowerFuse | ML-STA SER NO 3 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Amps C Ø | 103.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | 9 Months Operations | 2 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | 9 Month Ops New | 2 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Operations Counter AF | 318 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Amps A Ø | 95.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Switching Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Amps B Ø | 93.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Operations This Read AM | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Operations Counter AL | 318 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Patrol Inspection | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Switching Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Operations This Read AM | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Operations Counter AL | 82 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Amps C Ø | 130.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Amps B Ø | 135.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Amps A Ø | 136.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Operations Counter AF | 82 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | 9 Months Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | General Comments | A Phase IOC | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | 9 Month Ops New | 5 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Operations Counter AF | 422 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Operations Counter AL | 422 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Fault Operations A Ø | 5 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Fault Adjusted Amps A Phase AM | 55.90 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Amps C Ø | 167.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Amps B Ø | 158.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Amps A Ø | 148.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Operations This Read AM | 5 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Switching Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | 9 Months Operations | 10 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Patrol Inspection | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Amps A Ø | 123.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Amps B Ø | 112.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Amps C Ø | 98.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Fault Adjusted Amps C Phase AM | 11.18 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | 9 Months Operations | 1 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Fault Operations C Ø | 1 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Switching Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Operations This Read AM | 1 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Operations Counter AL | 621 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Operations Counter AF | 621 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | General Comments | C Phase IOC | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Patrol Inspection | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Operations Counter AF | 51 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Operations Counter AL | 51 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Operations This Read AM | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Switching Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Amps C Ø | 92.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Amps B Ø | 90.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Amps A Ø | 81.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | 9 Month Ops New | 2 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | 9 Months Operations | 2 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Patrol Inspection | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Amps A Ø | 564.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Amps B Ø | 581.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Operations Counter AF | 577 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Operations Counter AL | 577 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Operations This Read AM | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Switching Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Amps C Ø | 570.0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Maintenance Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | 9 Months Operations | 0 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Patrol Inspection | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | PF000251 | PowerFuse | ML-12KV TR 6 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | PF000251 | PowerFuse | ML-12KV TR 6 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | PF000251 | PowerFuse | ML-12KV TR 6 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | PF000249 | PowerFuse | ML-STA SER NO 6 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | PF000249 | PowerFuse | ML-STA SER NO 6 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | PF000249 | PowerFuse | ML-STA SER NO 6 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Counter Readings | LTC Operations Since Last Insp | 201 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Counter Readings | LTC Min Tap Position | 3L | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Counter Readings | LTC Max Tap Position | 5R | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Counter Readings | LTC Current Tap Position | 3R | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Counter Readings | LTC As Left Counter | 84018 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Counter Readings | LTC As Found Counter | 84018 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Counter Readings | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | H2 Winding Temp Max | 35 | °C |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | H2 Winding Temp Present | 25 | °C |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 65.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Max | 25 | °C |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Present | 25 | °C |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Present | 40 | °C |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Max | 40 | °C |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Present | 30 | °C |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Max | 40 | °C |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.5 | psi |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1100 | psi |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Readings | X1 Winding Temp Present | 43 | °C |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Readings | X1 Winding Temp Max | 58 | °C |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Readings | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Readings | X2 Winding Temp Max | 60 | °C |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Readings | X3 Winding Temp Present | 44 | °C |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Readings | X3 Winding Temp Max | 60 | °C |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Readings | X2 Winding Temp Present | 45 | °C |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Counter Readings | LTC Operations Since Last Insp | 212 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Counter Readings | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Counter Readings | LTC As Found Counter | 24165 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Counter Readings | LTC As Left Counter | 24165 | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Counter Readings | LTC Max Tap Position | 5L | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | PF000252 | PowerFuse | ML-STA SER NO 4 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | PF000252 | PowerFuse | ML-STA SER NO 4 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/17/2023 5:00 | Distribution | Mud Lane Quarterly Inspection | PF000252 | PowerFuse | ML-STA SER NO 4 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Amps A Ø | 20.0 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | 9 Month Operations | 3 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Amps B Ø | 12.0 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Amps C Ø | 12.0 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Operations This Read Vac | 0 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Operations Counter AL | 12 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Operations Counter AF | 12 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | General Comments | | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Operations Counter AF | 1332 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Operations Counter AL | 1332 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Operations This Read Vac | 3 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Amps C Ø | 12.0 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | 9 Month Operations | 15 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | 9 Month Operations VCB New | 12 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Amps B Ø | 12.0 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Amps A Ø | 12.0 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Fault Adjusted Amps A Phase V | 6.09 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Fault Adjusted Amps B Phase V | 9.13 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Fault Adjusted Amps C Phase V | 6.09 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Fault Operations B Ø | 1 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Fault Operations Ground | 2 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | General Comments | | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | LTCC000733 | LTCControl | 403-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | LTCC000733 | LTCControl | 403-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | LTCC000733 | LTCControl | 403-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | LTCC000733 | LTCControl | 403-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | LTCC000733 | LTCControl | 403-1 | LTC Control Insp | All Connections OK? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | LTCC000733 | LTCControl | 403-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | LTCC000733 | LTCControl | 403-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | LTCC000733 | LTCControl | 403-1 | LTC Control Insp | General Comments | | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Counter Readings | General Comments | | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Counter Readings | LTC Operations Since Last Insp | 975 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Counter Readings | LTC Max Tap Position | 8R | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Counter Readings | LTC As Left Counter | 36042 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Counter Readings | LTC As Found Counter | 36031 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Readings | Oil Temp Present | 36 | °C |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Readings | Oil Temp Max | 52 | °C |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Readings | LTC Totalizer Reading | 2846.40 | kw |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Readings | General Comments | | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Readings | Totalizer Meter Reading | .5930 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.2 | VDC |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.2 | VDC |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | BCH000271 | Charger | 403-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | BCH000271 | Charger | 403-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | BCH000271 | Charger | 403-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | BCH000271 | Charger | 403-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | BCH000271 | Charger | 403-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | CH000235 | ControlHouse | 403-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | CH000235 | ControlHouse | 403-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | CH000235 | ControlHouse | 403-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | CH000235 | ControlHouse | 403-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | CH000235 | ControlHouse | 403-Control House | Control House Patrol Inspection | Evidence of Insects | Yes_needs_sprayed | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | CH000235 | ControlHouse | 403-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | CH000235 | ControlHouse | 403-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | CH000235 | ControlHouse | 403-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | CH000235 | ControlHouse | 403-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | CH000235 | ControlHouse | 403-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | CH000235 | ControlHouse | 403-Control House | Control House Patrol Inspection | General Comments | | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | CH000235 | ControlHouse | 403-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | CH000235 | ControlHouse | 403-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | CH000235 | ControlHouse | 403-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | CH000235 | ControlHouse | 403-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | CH000235 | ControlHouse | 403-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | General Comments | 2 arrestors blown on cir 414 and one blown on cir 414, center insulator on transfer buss has chipped skirt | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | General Comments | | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | n | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | YD000053 | Yard | 403-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | YD000053 | Yard | 403-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | YD000053 | Yard | 403-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | YD000053 | Yard | 403-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | YD000053 | Yard | 403-Yard | Yard Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | YD000053 | Yard | 403-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | YD000053 | Yard | 403-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | YD000053 | Yard | 403-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | YD000053 | Yard | 403-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | YD000053 | Yard | 403-Yard | Yard Patrol Inspection | Ambient Temp | 75 | °F |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | YD000053 | Yard | 403-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | YD000053 | Yard | 403-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/13/2023 12:24 | Distribution | Dayhoit Quarterly Inspection | YD000053 | Yard | 403-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Amps C Ø | 52.0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Amps B Ø | 48.0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Fault Adjusted Amps A Phase V | 3.95 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Amps A Ø | 35.0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | 9 Month Operations | 3 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Fault Adjusted Amps C Phase V | 3.95 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Operations This Read Vac | 2 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Operations Counter AL | 184 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Operations Counter AF | 184 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Fault Operations C Ø | 1 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | General Comments | | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Amps C Ø | 29.0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Operations This Read Vac | 0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Operations Counter AL | 168 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Operations Counter AF | 168 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | General Comments | counter entered wrong last time | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | 9 Month Operations | 1 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Amps A Ø | 29.0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Amps B Ø | 29.0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | 9 Month Operations | 1 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | General Comments | | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Operations Counter AF | 189 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Operations Counter AL | 189 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Operations This Read Vac | 0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Amps A Ø | 101.0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Amps B Ø | 95.0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Amps C Ø | 104.0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Counter Readings | LTC Operations Since Last Insp | 787 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Counter Readings | General Comments | | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Counter Readings | LTC As Found Counter | 59912 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Counter Readings | LTC As Left Counter | 59912 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | LTCC000289 | LTCControl | 784-1 | LTC Control Insp | All Connections OK? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | LTCC000289 | LTCControl | 784-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | LTCC000289 | LTCControl | 784-1 | LTC Control Insp | General Comments | | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | LTCC000289 | LTCControl | 784-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | LTCC000289 | LTCControl | 784-1 | LTC Control Insp | LTC Output Voltage Level | 124.4 | VAC |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | LTCC000289 | LTCControl | 784-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | LTCC000289 | LTCControl | 784-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | LTCC000289 | LTCControl | 784-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | LTCC000289 | LTCControl | 784-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Readings | General Comments | | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Readings | LTC Totalizer Reading | 4486.08 | kw |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Readings | Totalizer Meter Reading | .4673 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BCH001469 | Charger | 784-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BCH001469 | Charger | 784-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BCH001469 | Charger | 784-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BCH001469 | Charger | 784-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.4 | amps |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BCH001469 | Charger | 784-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BCH001469 | Charger | 784-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BCH001469 | Charger | 784-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BCH001469 | Charger | 784-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BAT001069 | Battery | 784-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BAT001069 | Battery | 784-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.7 | VDC |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BAT001069 | Battery | 784-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.7 | VDC |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BAT001069 | Battery | 784-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BAT001069 | Battery | 784-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BAT001069 | Battery | 784-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BAT001069 | Battery | 784-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BAT001069 | Battery | 784-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BAT001069 | Battery | 784-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BAT001069 | Battery | 784-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BAT001069 | Battery | 784-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BAT001069 | Battery | 784-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | BAT001069 | Battery | 784-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 72 | °F |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | General Comments | | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | General Comments | | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | General Comments | | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | Ambient Temp | 72 | °F |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/13/2023 11:42 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | 9 Month Operations | 4 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Operations This Read Vac | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Operations Counter AL | 244 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Operations Counter AF | 244 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Amps B Ø | 0.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Amps C Ø | 0.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Amps A Ø | 0.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Operations Counter AF | 287 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Operations Counter AL | 287 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Operations This Read Vac | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | 9 Month Operations | 2 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Amps A Ø | 12.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Amps B Ø | 13.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Amps C Ø | 12.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | 9 Month Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Amps A Ø | 0.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Amps B Ø | 0.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Amps C Ø | 0.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Operations This Read Vac | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Operations Counter AL | 184 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Operations Counter AF | 184 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | 9 Month Operations | 5 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Operations Counter AF | 359 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Operations Counter AL | 359 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Operations This Read Vac | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Amps C Ø | 105.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Amps A Ø | 112.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Amps B Ø | 111.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Operations Counter AF | 177 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Operations Counter AL | 177 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Amps C Ø | 70.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Amps B Ø | 54.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Amps A Ø | 64.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Operations This Read Vac | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | 9 Month Operations | 3 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Amps A Ø | 37.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Amps B Ø | 42.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Operations Counter AF | 371 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Operations Counter AL | 371 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Operations This Read Vac | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Amps C Ø | 44.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | 9 Month Operations VCB New | 23 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | 9 Month Operations | 23 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | 9 Month Operations | 3 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Amps C Ø | 230.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Amps B Ø | 222.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Amps A Ø | 231.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Operations This Read Vac | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Operations Counter AL | 183 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Operations Counter AF | 183 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | PF001161 | PowerFuse | HK-12KV TR 3 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | PF001161 | PowerFuse | HK-12KV TR 3 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | PF001162 | PowerFuse | HK-STA SER NO 3 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | PF001162 | PowerFuse | HK-STA SER NO 3 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Vent Fans OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LTCC000099 | LTCControl | HK-TRANS 3 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LTCC000099 | LTCControl | HK-TRANS 3 | LTC Control Insp | All Connections OK? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LTCC000099 | LTCControl | HK-TRANS 3 | LTC Control Insp | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LTCC000099 | LTCControl | HK-TRANS 3 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Counter Readings | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Counter Readings | LTC As Found Counter | 53816 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Counter Readings | LTC As Left Counter | 53816 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Counter Readings | LTC Operations Since Last Insp | 72 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 22 | °C |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 33 | °C |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Max | 36 | °C |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Present | 22 | °C |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Readings | Oil Temp Present | 27 | °C |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Present | 27 | °C |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Readings | Oil Temp Max | 37 | °C |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Max | 38 | °C |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Present | 22 | °C |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Readings | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Max | 38 | °C |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1150 | psi |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Amps A Ø | 0.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | 9 Month Ops New | 5 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | 9 Months Operations | 5 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Unknown Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Switching Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Operations This Read AM | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Operations Counter AL | 139 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Operations Counter AF | 139 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Amps C Ø | 0.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Amps B Ø | 0.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | 9 Months Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Amps A Ø | 0.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Amps B Ø | 0.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Amps C Ø | 0.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Operations Counter AF | 41 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Operations Counter AL | 41 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Unknown Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Switching Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Operations This Read AM | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Patrol Inspection | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Operations Counter AF | 253 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Operations Counter AL | 253 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Operations This Read AM | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Switching Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Amps B Ø | 24.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Amps C Ø | 22.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Amps A Ø | 16.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Unknown Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | 9 Month Ops New | 3 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | 9 Months Operations | 3 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Patrol Inspection | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | 9 Months Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Amps C Ø | 0.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Amps B Ø | 0.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Amps A Ø | 0.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Unknown Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Switching Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Operations This Read AM | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Operations Counter AL | 429 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Operations Counter AF | 429 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Patrol Inspection | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Amps B Ø | 161.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Amps A Ø | 141.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Amps C Ø | 161.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Unknown Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | 9 Month Ops New | 14 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Operations Counter AF | 334 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | 9 Months Operations | 14 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Switching Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Operations This Read AM | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Operations Counter AL | 334 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Patrol Inspection | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Amps C Ø | 185.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Unknown Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Switching Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Amps B Ø | 184.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Operations This Read AM | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Operations Counter AL | 94 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Operations Counter AF | 94 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Amps A Ø | 153.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | 9 Months Operations | 1 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | 9 Month Ops New | 1 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Patrol Inspection | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | PF000184 | PowerFuse | HK-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | PF000184 | PowerFuse | HK-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | PF000183 | PowerFuse | HK-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | PF000183 | PowerFuse | HK-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | PF000182 | PowerFuse | HK-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | PF000182 | PowerFuse | HK-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | PF000181 | PowerFuse | HK-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | PF000181 | PowerFuse | HK-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LTCC000429 | LTCControl | HK-TRANS 2 | LTC Control Insp | All Connections OK? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LTCC000429 | LTCControl | HK-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LTCC000429 | LTCControl | HK-TRANS 2 | LTC Control Insp | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LTCC000429 | LTCControl | HK-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Counter Readings | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 244360 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 244360 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 14L | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 10L | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 16L | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 73 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 30 | °C |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 38 | °C |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 30 | °C |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 40 | °C |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 40 | °C |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 30 | °C |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LTCC000519 | LTCControl | HK-TRANS 1 | LTC Control Insp | All Connections OK? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LTCC000519 | LTCControl | HK-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LTCC000519 | LTCControl | HK-TRANS 1 | LTC Control Insp | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LTCC000519 | LTCControl | HK-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 107 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 5L | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 11L | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 278541 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 278541 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Counter Readings | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 40 | °C |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 44 | °C |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 45 | °C |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 55 | °C |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 50 | °C |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 40 | °C |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 52 | °C |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.2 | psi |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 500 | psi |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | 9 Month Operations | 6 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Operations Counter AF | 267 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Operations Counter AL | 267 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Amps A Ø | 275.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Amps B Ø | 278.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Amps C Ø | 269.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Amps C Ø | 112.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Amps B Ø | 111.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Amps A Ø | 112.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Operations Counter AF | 338 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Operations Counter AL | 338 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Operations This Read Vac | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | 9 Month Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Operations Counter AF | 176 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Operations Counter AL | 176 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Operations This Read Vac | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Amps C Ø | 0.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Amps B Ø | 0.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Amps A Ø | 0.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | 9 Month Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Amps C Ø | 90.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Operations Counter AF | 238 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Operations Counter AL | 238 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Operations This Read Vac | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | 9 Month Operations VCB New | 12 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | 9 Month Operations | 12 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Amps B Ø | 81.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Amps A Ø | 96.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Operations This Read Vac | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Operations Counter AL | 230 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Operations Counter AF | 230 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | General Comments | | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | 9 Month Operations | 1 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Amps C Ø | 111.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Amps B Ø | 92.0 | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Amps A Ø | 80.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Amps C Ø | 60.0 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Amps B Ø | 60.0 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Amps A Ø | 60.0 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | 9 Month Operations | 4 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Operations This Read Vac | 0 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Operations Counter AL | 300 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Operations Counter AF | 300 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | General Comments | | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Operations This Read Vac | 0 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Operations Counter AL | 231 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Operations Counter AF | 231 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Amps C Ø | 30.0 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | General Comments | | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Amps B Ø | 30.0 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Amps A Ø | 30.0 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | 9 Month Operations | 4 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.4 | volts |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 121877 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Unknown Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Switching Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Operations Counter AL | 4 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Operations Counter AF | 4 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Amps A Ø | 0.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | 9 Months Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Amps C Ø | 0.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Amps B Ø | 0.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Amps B Ø | 0.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Amps A Ø | 0.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | 9 Months Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Amps C Ø | 0.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Operations Counter AF | 6 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Operations Counter AL | 6 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Switching Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Unknown Operations | 0 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 126896 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Fault Adjusted Amps A Phase AM | 33.54 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Amps C Ø | 75.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Amps B Ø | 75.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Fault Adjusted Amps B Phase AM | 33.54 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Fault Operations A Ø | 3 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Fault Operations B Ø | 3 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | General Comments | AB Phase TOC | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Operations Counter AF | 169 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Operations Counter AL | 169 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Operations This Read AM | 6 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Switching Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Unknown Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Amps A Ø | 75.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | 9 Months Operations | 11 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | General Comments | B Phase IOC/TOC | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Operations Counter AF | 334 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Operations Counter AL | 334 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Operations This Read AM | 2 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Switching Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Unknown Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Fault Operations B Ø | 2 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Fault Adjusted Amps B Phase AM | 22.36 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Amps C Ø | 150.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Amps B Ø | 140.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Amps A Ø | 150.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | 9 Months Operations | 6 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 121587 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Unknown Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Switching Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | General Comments | B Phase IOC | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Operations Counter AF | 163 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Operations This Read AM | 2 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Operations Counter AL | 163 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | 9 Months Operations | 7 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Amps A Ø | 150.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Amps B Ø | 150.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Amps C Ø | 150.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Fault Adjusted Amps B Phase AM | 22.36 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Fault Operations B Ø | 2 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Readings | General Comments | | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 20.00 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3183.36 | kw |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .3316 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Amps B Ø | 325.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Amps A Ø | 325.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Amps C Ø | 325.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | 9 Months Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Operations Counter AF | 125 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Operations Counter AL | 125 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Switching Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Unknown Operations | 0 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 25.00 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | PF000031 | PowerFuse | AB-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | PF000031 | PowerFuse | AB-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | BCH001359 | Charger | 407-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | BCH001359 | Charger | 407-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | BCH001359 | Charger | 407-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | BCH001359 | Charger | 407-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | BCH001359 | Charger | 407-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | BCH001359 | Charger | 407-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | BCH001359 | Charger | 407-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.3 | amps |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | BCH001359 | Charger | 407-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | PF000030 | PowerFuse | AB-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | PF000030 | PowerFuse | AB-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Amps B Ø | 150.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Amps C Ø | 150.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Fault Adjusted Amps A Phase AM | 22.36 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Fault Operations A Ø | 2 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Operations Counter AF | 909 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Fault Operations B Ø | 2 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Operations Counter AL | 909 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Operations This Read AM | 6 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Switching Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Unknown Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Fault Adjusted Amps B Phase AM | 22.36 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Fault Adjusted Amps C Phase AM | 22.36 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Amps A Ø | 160.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Fault Operations C Ø | 2 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | 9 Months Operations | 10 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | BAT001486 | Battery | 407-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | BAT001486 | Battery | 407-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | BAT001486 | Battery | 407-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | BAT001486 | Battery | 407-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | BAT001486 | Battery | 407-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | BAT001486 | Battery | 407-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | BAT001486 | Battery | 407-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | BAT001486 | Battery | 407-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | BAT001486 | Battery | 407-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | BAT001486 | Battery | 407-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.4 | VDC |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | BAT001486 | Battery | 407-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.1 | VDC |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | BAT001486 | Battery | 407-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | BAT001486 | Battery | 407-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | General Comments | | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | 9 Months Operations | 6 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Amps B Ø | 90.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Amps A Ø | 75.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Amps C Ø | 50.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Operations Counter AF | 985 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Operations Counter AL | 985 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Switching Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Unknown Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | General Comments | | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Amps C Ø | 140.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Amps B Ø | 160.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Amps A Ø | 130.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | 9 Months Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Unknown Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Switching Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Operations Counter AL | 861 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Operations Counter AF | 861 | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | General Comments | | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 4/13/2023 10:46 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Operations Counter AL | 67 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Switching Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | 9 Months Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Amps A Ø | 0.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Unknown Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Amps B Ø | 0.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Amps C Ø | 0.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Operations Counter AF | 67 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Amps B Ø | 350.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Amps C Ø | 340.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | 9 Months Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Unknown Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Operations Counter AF | 687 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Amps A Ø | 320.0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Operations Counter AL | 687 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Switching Operations | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | PF000028 | PowerFuse | AB-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | PF000028 | PowerFuse | AB-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | PF000029 | PowerFuse | AB-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | PF000029 | PowerFuse | AB-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LTCC000226 | LTCControl | AB-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LTCC000226 | LTCControl | AB-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 190630 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 190630 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 46 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 60 | °C |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 47 | °C |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 48 | °C |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 40 | °C |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 40 | °C |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 40 | °C |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 40 | °C |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 97351 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 97351 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 48 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LTCC000401 | LTCControl | AB-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LTCC000401 | LTCControl | AB-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 50 | °C |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 48 | °C |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 48 | °C |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 48 | °C |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 48 | °C |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 48 | °C |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 48 | °C |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 46 | °C |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.5 | psi |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Restroom Clean & OK? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | Ambient Temp | 54 | °F |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Amps C Ø | 0.0 | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Amps B Ø | 0.0 | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Amps A Ø | 0.0 | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Operations Counter | 88 | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Min Tap Position | 16L | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Max Tap Position | 6L | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.2 | volts |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 67464 | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Current Tap Position | 14L | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Current Tap Position | 11L | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 71362 | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Min Tap Position | 16L | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Max Tap Position | 4L | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Min Tap Position | 16L | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Current Tap Position | 11L | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 64243 | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Counter Readings | General Comments | | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 347 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 418526 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 418526 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 4 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 6 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 3 | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 0.00 | kw |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Readings | General Comments | | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Readings | Oil Temp Max | 32 | °C |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Readings | Winding Temp Present | 24 | °C |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Readings | Winding Temp Max | 38 | °C |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Readings | LV Winding Temp Present | 30 | °C |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 110.00 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 32 | °C |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 30 | °C |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | General Comments | | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Patrol Inspection | General Comments | | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Fault Operations A Ø | 1 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Fault Operations C Ø | 1 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 9.55 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 9.55 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Amps C Ø | 75.0 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Amps B Ø | 25.0 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Amps A Ø | 75.0 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | 9 Months Operations | 3 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | 9 Month Ops New | 1 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | General Comments | | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Operations Counter AF | 547 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Operations Counter AL | 547 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Operations This Read AM | 2 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Switching Operations | 0 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Unknown Operations | 0 | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | General Comments | | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Patrol Inspection | General Comments | | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | YD000080 | Yard | 606-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | YD000080 | Yard | 606-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | YD000080 | Yard | 606-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | YD000080 | Yard | 606-Yard | Yard Patrol Inspection | General Comments | | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | YD000080 | Yard | 606-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | YD000080 | Yard | 606-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | YD000080 | Yard | 606-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | YD000080 | Yard | 606-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | YD000080 | Yard | 606-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | YD000080 | Yard | 606-Yard | Yard Patrol Inspection | Ambient Temp | 65 | °F |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | YD000080 | Yard | 606-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/13/2023 10:33 | Distribution | Forester Creek Quarterly Inspection | YD000080 | Yard | 606-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | General Comments | | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | 9 Month Ops New | 1 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | 9 Months Operations | 1 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Operations Counter AF | 16 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Operations Counter AL | 16 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Amps A Ø | 100.0 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Amps B Ø | 100.0 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Amps C Ø | 100.0 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Operations This Read AM | 0 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Unknown Operations | 0 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Switching Operations | 0 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Patrol Inspection | General Comments | | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | 9 Months Operations | 4 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | General Comments | | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Fault Operations C Ø | 2 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Fault Operations B Ø | 1 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Fault Operations A Ø | 1 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 19.09 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 9.55 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 9.55 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Amps C Ø | 25.0 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Amps B Ø | 25.0 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Amps A Ø | 25.0 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Unknown Operations | 0 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Switching Operations | 0 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Operations Counter AF | 595 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Operations Counter AL | 595 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Operations This Read AM | 4 | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Battery Bank Amps | .1 | AMPS |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Battery Bank Volts | 26.6 | VDC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | BCH000120 | Charger | DU-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | BCH000120 | Charger | DU-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.6 | VDC |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | BCH000120 | Charger | DU-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.6 | VDC |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | BCH000120 | Charger | DU-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | BCH000120 | Charger | DU-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | BCH000120 | Charger | DU-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | BCH000120 | Charger | DU-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | CH000455 | ControlHouse | DU-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | CH000455 | ControlHouse | DU-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | CH000455 | ControlHouse | DU-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | CH000455 | ControlHouse | DU-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | CH000455 | ControlHouse | DU-Battery Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | CH000455 | ControlHouse | DU-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | CH000455 | ControlHouse | DU-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | CH000455 | ControlHouse | DU-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | CH000455 | ControlHouse | DU-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | YD000619 | Yard | DU-Yard | Yard Patrol Inspection | Ambient Temp | 65 | °F |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | YD000619 | Yard | DU-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | YD000619 | Yard | DU-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | YD000619 | Yard | DU-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | YD000619 | Yard | DU-Yard | Yard Patrol Inspection | General Comments | | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | YD000619 | Yard | DU-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | YD000619 | Yard | DU-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | YD000619 | Yard | DU-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | YD000619 | Yard | DU-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | YD000619 | Yard | DU-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | YD000619 | Yard | DU-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | General Comments | | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PF001300 | PowerFuse | DU-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PF001300 | PowerFuse | DU-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:30 | Distribution | Dumesnil Quarterly Inspection | PF001300 | PowerFuse | DU-4KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Amps B Ø | 129.0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Amps A Ø | 128.0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Operations This Read Vac | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Operations Counter AL | 179 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Operations Counter AF | 179 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | General Comments | | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | 9 Month Operations | 1 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Amps C Ø | 130.0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Amps C Ø | 160.0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Amps B Ø | 120.0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Amps A Ø | 140.0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | 9 Month Operations | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Operations Counter AF | 53 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Operations Counter AL | 53 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | General Comments | | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Amps B Ø | 21.0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | General Comments | | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | 9 Month Operations | 2 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Operations Counter AF | 222 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Operations Counter AL | 222 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Operations This Read Vac | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Amps C Ø | 19.0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Amps A Ø | 24.0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | 9 Month Operations VCB New | 63 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | 9 Month Operations | 63 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Amps A Ø | 10.0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Fault Operations Ground | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Follow-up Action Required? | n | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | General Comments | | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Maintenance Operations | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Operations Counter AF | 5 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Operations Counter AL | 5 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Operations This Read Vac | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Switching Operations | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Unknown Operations | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Amps B Ø | 10.0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Amps C Ø | 15.0 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | General Comments | | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Counter Readings | LTC As Found Counter | 86888 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Counter Readings | General Comments | | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Counter Readings | LTC As Left Counter | 86888 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Counter Readings | LTC Operations Since Last Insp | 824 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCC000592 | LTCControl | 472-1 | LTC Control Insp | LTC Output Voltage Level | 124.1 | VAC |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCC000592 | LTCControl | 472-1 | LTC Control Insp | All Connections OK? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCC000592 | LTCControl | 472-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCC000592 | LTCControl | 472-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCC000592 | LTCControl | 472-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCC000592 | LTCControl | 472-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCC000592 | LTCControl | 472-1 | LTC Control Insp | General Comments | | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCC000592 | LTCControl | 472-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Readings | General Comments | | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Readings | LTC Totalizer Reading | 6534.00 | kw |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Readings | Winding Temp Present | 45 | °C |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Readings | Winding Temp Max | 45 | °C |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Readings | Totalizer Meter Reading | .3630 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BCH001153 | Charger | 472-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BCH001153 | Charger | 472-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .9 | amps |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BCH001153 | Charger | 472-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BCH001153 | Charger | 472-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BCH001153 | Charger | 472-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BCH001153 | Charger | 472-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BCH001153 | Charger | 472-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BCH001153 | Charger | 472-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 54 | °F |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.3 | VDC |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.2 | VDC |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | General Comments | | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | n | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | General Comments | need signs updated | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | n | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | General Comments | there is not a spill kit | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/13/2023 9:10 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | Ambient Temp | 54 | °F |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Current Tap Position | 3R | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Current Tap Position | 4R | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Readings | General Comments | | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Readings | Totalizer Meter Reading | .3940 | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 200 | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Readings | General Comments | | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 78.80 | kw |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Platform/Walkway/Railing OK? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | General Comments | | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Ambient Temp | 72 | °F |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | General Comments | | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/13/2023 8:16 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Counter Readings | LTC Operations Since Last Insp | 31 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Counter Readings | LTC Min Tap Position | 1L | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Counter Readings | LTC Current Tap Position | Neutral | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Counter Readings | LTC As Left Counter | 296816 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Counter Readings | LTC As Found Counter | 296816 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Counter Readings | General Comments | counter was entered wrong last 1/4 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | General Comments | | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Maintenance Operations | 1 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Amps C Ø | 60.0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Amps C Ø | 12.0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Amps B Ø | 18.0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Amps A Ø | 16.0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Accumulated Fault Duty C Ph V | 1.27 | % |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Accumulated Fault Duty B Ph V | 1.27 | % |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Accumulated Fault Duty A Ph V | 1.27 | % |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | 9 Month Operations | 0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Operations This Read Vac | 1 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Operations Counter AL | 167 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Operations Counter AF | 167 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Maintenance Operations | 1 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | General Comments | | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Amps B Ø | 70.0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Operations Counter AF | 219 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Operations Counter AL | 219 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Operations This Read Vac | 1 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | General Comments | | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Operations Counter AF | 4 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Operations Counter AL | 4 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Amps A Ø | 86.0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Accumulated Fault Duty C Ph V | 5.48 | % |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Accumulated Fault Duty B Ph V | 5.27 | % |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Accumulated Fault Duty A Ph V | 4.43 | % |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | 9 Month Operations | 1 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | 9 Month Operations | 3 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Accumulated Fault Duty A Ph V | 1.69 | % |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Accumulated Fault Duty B Ph V | 1.69 | % |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Accumulated Fault Duty C Ph V | 2.11 | % |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Amps A Ø | 7.0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Amps B Ø | 10.0 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Amps C Ø | 9.0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Counter Readings | LTC Current Tap Position | 5R | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Counter Readings | LTC As Left Counter | 296785 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Counter Readings | LTC As Found Counter | 296785 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Counter Readings | General Comments | | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Counter Readings | LTC Max Tap Position | 7R | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Counter Readings | LTC Min Tap Position | 3L | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Counter Readings | LTC Operations Since Last Insp | 304 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Operations Counter AL | 131 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | 9 Month Operations | 2 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Operations Counter AF | 131 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | General Comments | | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Amps C Ø | 18.0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Amps B Ø | 23.0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Amps A Ø | 31.0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Accumulated Fault Duty C Ph V | 1.27 | % |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Accumulated Fault Duty B Ph V | 1.27 | % |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | Accumulated Fault Duty A Ph V | 1.27 | % |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Readings | 9 Month Operations | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Accumulated Fault Duty A Ph V | 1.69 | % |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Operations Counter AF | 218 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Operations Counter AL | 218 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | General Comments | | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | General Comments | | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Operations Counter AF | 166 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Operations Counter AL | 166 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Amps C Ø | 17.0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Amps B Ø | 17.0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Amps A Ø | 20.0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Accumulated Fault Duty C Ph V | 2.11 | % |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Accumulated Fault Duty B Ph V | 1.69 | % |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | 9 Month Operations | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Accumulated Fault Duty A Ph V | 4.43 | % |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Accumulated Fault Duty B Ph V | 5.27 | % |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Accumulated Fault Duty C Ph V | 5.48 | % |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Amps A Ø | 128.0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Amps B Ø | 976.0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Amps C Ø | 96.0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Operations Counter AL | 165 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Operations Counter AF | 165 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Amps C Ø | 0.0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Amps B Ø | 0.0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Amps A Ø | 0.0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | 9 Month Operations | 5 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Operations Counter AF | 190 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Operations Counter AL | 190 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Amps A Ø | 255.0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Amps B Ø | 240.0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Fault Operations C Ø | 2 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Fault Operations B Ø | 2 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Operations This Read Vac | 4 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Amps C Ø | 280.0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Fault Adjusted Amps B Phase V | 27.22 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Fault Adjusted Amps C Phase V | 27.22 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | 9 Month Operations VCB New | 13 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | 9 Month Operations | 17 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Amps C Ø | 35.0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Amps B Ø | 35.0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Amps A Ø | 35.0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Operations Counter AF | 330 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Operations Counter AL | 330 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | 9 Month Operations VCB New | 18 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | 9 Month Operations | 18 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Operations Counter AL | 341 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Operations Counter AF | 341 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | 9 Month Operations | 12 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Amps C Ø | 325.0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Amps B Ø | 320.0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Amps A Ø | 340.0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | 9 Month Operations VCB New | 12 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Fault Adjusted Amps C Phase V | 13.97 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Fault Operations C Ø | 1 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Amps C Ø | 145.0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Amps B Ø | 170.0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Operations This Read Vac | 1 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Amps A Ø | 160.0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Operations Counter AL | 257 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Operations Counter AF | 257 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | 9 Month Operations | 11 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | 9 Month Operations | 9 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Operations Counter AF | 291 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Operations Counter AL | 291 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | 9 Month Operations | 26 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Maintenance Operations | 15 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Operations Counter AF | 363 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Operations Counter AL | 363 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Switching Operations | 1 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Operations This Read Vac | 16 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Bat Volt 1Min After Chgr Trip | 128.8 | VDC |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery 3 Load Test Volts | 0.0 | VDC |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery 2 Pre-test Volts | 0.0 | VDC |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery 1 Pre-test Volts | 0.0 | VDC |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery 1 Load Test Volts | 0.0 | VDC |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery 2 Post-test Volts | 0.0 | VDC |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery 2 Load Test Volts | 0.0 | VDC |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Dry Cell Battery Install Date | 1900-01-01 00:00:00.000000 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Exp/Missing Not Repl | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | General Comments | this shouldn't be on this insp | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery 1 Post-test Volts | 0.0 | VDC |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery 3 Post-test Volts | 0.0 | VDC |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery 3 Pre-test Volts | 0.0 | VDC |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery 4 Load Test Volts | 0.0 | VDC |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery 4 Post-test Volts | 0.0 | VDC |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery 4 Pre-test Volts | 0.0 | VDC |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery Bank Volts | 134.3 | VDC |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery Bank Amps | 2.8 | AMPS |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Amps A Ø | 415.0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Operations Counter AL | 225 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Amps B Ø | 415.0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Operations Counter AF | 225 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | 9 Month Operations | 9 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Amps C Ø | 420.0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 758 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 12L | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 95362 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 95362 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Counter Readings | General Comments | | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Operations Counter AF | 203 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | 9 Month Operations | 6 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Operations Counter AL | 203 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Amps A Ø | 375.0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Amps B Ø | 350.0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Amps C Ø | 360.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 33 | °C |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 47 | °C |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Counter Readings | LTC Operations Since Last Insp | 364 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Counter Readings | LTC As Left Counter | 130873 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Counter Readings | LTC As Found Counter | 130873 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Counter Readings | General Comments | | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Unknown Operations | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Switching Operations | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Operations This Read AM | 9 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Operations Counter AL | 968 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Operations Counter AF | 868 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | General Comments | | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | 9 Months Operations | 9 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Amps A Ø | 22.0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Amps B Ø | 35.0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Amps C Ø | 43.0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Fault Adjusted Amps A Phase AM | 33.54 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Fault Adjusted Amps B Phase AM | 33.54 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Fault Adjusted Amps C Phase AM | 33.54 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Fault Operations A Ø | 3 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Fault Operations B Ø | 3 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Fault Operations C Ø | 3 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Patrol Inspection | General Comments | | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Fault Operations B Ø | 2 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Fault Operations C Ø | 2 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | General Comments | | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Operations Counter AF | 942 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Fault Operations A Ø | 2 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Fault Adjusted Amps C Phase AM | 22.36 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Fault Adjusted Amps B Phase AM | 22.36 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Fault Adjusted Amps A Phase AM | 22.36 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Amps C Ø | 73.0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | 9 Month Ops New | 2 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Amps B Ø | 67.0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Amps A Ø | 78.0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Operations Counter AL | 942 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Operations This Read AM | 6 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Unknown Operations | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Switching Operations | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | 9 Months Operations | 8 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | LTCC000775 | LTCControl | 617-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | LTCC000775 | LTCControl | 617-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | LTCC000775 | LTCControl | 617-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | LTCC000775 | LTCControl | 617-2 | LTC Control Insp | All Connections OK? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | LTCC000775 | LTCControl | 617-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | LTCC000775 | LTCControl | 617-2 | LTC Control Insp | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | LTCC000775 | LTCControl | 617-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | LTCC000775 | LTCControl | 617-2 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 100.00 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Readings | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Readings | LTC Totalizer Reading | 11404.80 | kw |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Readings | Totalizer Meter Reading | .6336 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Readings | Winding Temp Max | 50 | °C |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Readings | Winding Temp Present | 45 | °C |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Patrol Inspection | General Comments | | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | General Comments | | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Operations Counter AF | 1328 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Operations Counter AL | 1338 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Operations This Read AM | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Amps C Ø | 152.0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Amps B Ø | 153.0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Amps A Ø | 145.0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Unknown Operations | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Switching Operations | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | 9 Months Operations | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Counter Readings | LTC Operations Since Last Insp | 395 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Counter Readings | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Counter Readings | LTC As Found Counter | 15258 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Counter Readings | LTC As Left Counter | 15258 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Patrol Inspection | General Comments | | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Operations Counter AL | 898 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Operations This Read AM | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Switching Operations | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Unknown Operations | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Operations Counter AF | 898 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | General Comments | | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | 9 Month Ops New | 2 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Amps C Ø | 14.0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | 9 Months Operations | 2 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Amps A Ø | 24.0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Amps B Ø | 21.0 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Readings | Totalizer Meter Reading | .5630 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Readings | Winding Temp Max | 60 | °C |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Readings | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 290.00 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Readings | Oil Temp Max | 505 | °C |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Readings | LTC Totalizer Reading | 10134.00 | kw |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Patrol Inspection | General Comments | | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Amps C Ø | 214.0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Switching Operations | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Amps B Ø | 219.0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Operations This Read AM | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Unknown Operations | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Amps A Ø | 242.0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Operations Counter AL | 540 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Operations Counter AF | 540 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | 9 Months Operations | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | General Comments | | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | LTCC000762 | LTCControl | 617-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | LTCC000762 | LTCControl | 617-1 | LTC Control Insp | All Connections OK? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | LTCC000762 | LTCControl | 617-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | LTCC000762 | LTCControl | 617-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | LTCC000762 | LTCControl | 617-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | LTCC000762 | LTCControl | 617-1 | LTC Control Insp | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | LTCC000762 | LTCControl | 617-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | LTCC000762 | LTCControl | 617-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Patrol Inspection | General Comments | | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | PF000180 | PowerFuse | HL-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | PF000180 | PowerFuse | HL-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | PF000180 | PowerFuse | HL-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | PF000179 | PowerFuse | HL-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | PF000179 | PowerFuse | HL-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | PF000179 | PowerFuse | HL-12KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | Yes_sprayed | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BCH001564 | Charger | 617-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BCH001564 | Charger | 617-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BCH001564 | Charger | 617-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BCH001564 | Charger | 617-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BCH001564 | Charger | 617-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 6.0 | amps |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BCH001564 | Charger | 617-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BCH001564 | Charger | 617-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BCH001564 | Charger | 617-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | YD000341 | Yard | 617-Yard | Yard Patrol Inspection | Ambient Temp | 65 | °F |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | YD000341 | Yard | 617-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | YD000341 | Yard | 617-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | YD000341 | Yard | 617-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | YD000341 | Yard | 617-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | YD000341 | Yard | 617-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | YD000341 | Yard | 617-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | YD000341 | Yard | 617-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | YD000341 | Yard | 617-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | YD000341 | Yard | 617-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | YD000341 | Yard | 617-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | YD000341 | Yard | 617-Yard | Yard Patrol Inspection | General Comments | | |
| 4/12/2023 13:51 | Distribution | IBM Quarterly Inspection | YD000341 | Yard | 617-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | General Comments | | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Restroom Clean & OK? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | General Comments | relay work in C. house | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BCH001076 | Charger | HL-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BCH001076 | Charger | HL-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BCH001076 | Charger | HL-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.8 | amps |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BCH001076 | Charger | HL-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 134.2 | VDC |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BCH001076 | Charger | HL-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 134.2 | VDC |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BCH001076 | Charger | HL-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BCH001076 | Charger | HL-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | BCH001076 | Charger | HL-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | 9 Month Operations | 4 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Amps A Ø | 92.0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Amps B Ø | 79.0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Fault Adjusted Amps C Phase V | 5.72 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Fault Operations B Ø | 1 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Fault Operations C Ø | 1 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Fault Adjusted Amps B Phase V | 5.72 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Fault Adjusted Amps A Phase V | 5.72 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Amps C Ø | 77.0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Operations This Read Vac | 3 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Operations Counter AL | 165 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Operations Counter AF | 165 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Operations Counter AF | 161 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Operations Counter AL | 161 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | 9 Month Operations | 1 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Amps C Ø | 53.0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Amps B Ø | 62.0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Amps A Ø | 65.0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | 9 Month Operations | 1 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Operations Counter AF | 172 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Amps A Ø | 77.0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Amps B Ø | 68.0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Amps C Ø | 65.0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Operations Counter AL | 172 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Operations Counter AF | 181 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Operations Counter AL | 181 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | 9 Month Operations | 1 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Amps A Ø | 231.0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Amps B Ø | 208.0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Amps C Ø | 202.0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Amps A Ø | 17.0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | 9 Month Operations | 4 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Amps B Ø | 28.0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Amps C Ø | 24.0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Operations Counter AF | 401 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Operations Counter AL | 401 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Operations Counter AF | 356 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Operations Counter AL | 356 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Amps C Ø | 90.0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Amps B Ø | 95.0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Amps A Ø | 84.0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | 9 Month Operations | 6 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | 9 Month Operations | 2 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Operations Counter AL | 278 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Operations Counter AF | 278 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Amps A Ø | 0.0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Amps B Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Amps C Ø | 0.0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Counter Readings | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Counter Readings | LTC As Found Counter | 72552 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Counter Readings | LTC As Left Counter | 72552 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Counter Readings | LTC Operations Since Last Insp | 692 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Amps A Ø | 107.0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Amps B Ø | 125.0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Amps C Ø | 117.0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Operations Counter AF | 166 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Operations Counter AL | 166 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | 9 Month Operations | 1 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000572 | LTCControl | 768-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000572 | LTCControl | 768-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000572 | LTCControl | 768-2 | LTC Control Insp | LTC Output Voltage Level | 123.4 | VAC |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000572 | LTCControl | 768-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000572 | LTCControl | 768-2 | LTC Control Insp | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000572 | LTCControl | 768-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000572 | LTCControl | 768-2 | LTC Control Insp | All Connections OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000572 | LTCControl | 768-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.5 | psi |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Readings | Totalizer Meter Reading | .4200 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Readings | Winding Temp Present | 38 | °C |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Readings | LTC Totalizer Reading | 7560.00 | kw |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Readings | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Counter Readings | LTC Operations Since Last Insp | 750 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Counter Readings | LTC Min Tap Position | 1R | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Counter Readings | LTC As Left Counter | 46969 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Counter Readings | LTC As Found Counter | 46969 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Counter Readings | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000085 | LTCControl | 768-3 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000085 | LTCControl | 768-3 | LTC Control Insp | LTC Output Voltage Level | 123.5 | VAC |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000085 | LTCControl | 768-3 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000085 | LTCControl | 768-3 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000085 | LTCControl | 768-3 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000085 | LTCControl | 768-3 | LTC Control Insp | All Connections OK? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000085 | LTCControl | 768-3 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000085 | LTCControl | 768-3 | LTC Control Insp | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Readings | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Readings | LTC Totalizer Reading | 3348.00 | kw |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Readings | Winding Temp Max | 34 | °C |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Readings | Totalizer Meter Reading | .1860 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BCH001384 | Charger | 768-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BCH001384 | Charger | 768-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 3.9 | amps |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BCH001384 | Charger | 768-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BCH001384 | Charger | 768-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BCH001384 | Charger | 768-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BCH001384 | Charger | 768-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BCH001384 | Charger | 768-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BCH001384 | Charger | 768-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 84 | °F |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Ambient Temp | 84 | °F |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | General Comments | | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/12/2023 13:28 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 13.6 | VDC |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 12.8 | VDC |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 72 | °F |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | BCH000431 | Charger | 753-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | BCH000431 | Charger | 753-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | BCH000431 | Charger | 753-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | BCH000431 | Charger | 753-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | BCH000431 | Charger | 753-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Max Tap Position | 1L | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 11844 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Max Tap Position | 1R | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.0 | volts |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 11735 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.6 | volts |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 10191 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Readings | Winding Temp Present | 30 | °C |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Readings | Winding Temp Max | 30 | °C |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Readings | Oil Temp Present | 33 | °C |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Readings | Oil Temp Max | 33 | °C |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Readings | General Comments | | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | General Comments | | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Operations Counter AF | 133 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Operations Counter AL | 133 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | 9 Month Operations | 0 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Amps C Ø | 57.0 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Amps B Ø | 74.0 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Amps A Ø | 67.0 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | 9 Month Operations | 2 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Amps A Ø | 61.0 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Amps B Ø | 56.0 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Amps C Ø | 43.0 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | General Comments | | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Maintenance Operations | 1 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Operations Counter AF | 254 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Operations Counter AL | 254 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Operations This Read Vac | 1 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | General Comments | | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | General Comments | | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | General Comments | | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | Ambient Temp | 75 | °F |
| 4/12/2023 13:02 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Operations Counter AL | 200 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Operations Counter AF | 200 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | General Comments | | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Amps C Ø | 95.0 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Amps B Ø | 90.0 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Amps A Ø | 115.0 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | 9 Month Operations | 4 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Amps A Ø | 17.0 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Amps B Ø | 15.0 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Amps C Ø | 15.0 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Operations Counter AL | 181 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Operations Counter AF | 181 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | General Comments | | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | 9 Month Operations | 2 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Readings | General Comments | | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Readings | LTC Totalizer Reading | 5644.80 | kw |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Readings | Totalizer Meter Reading | .5880 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | LTCC000646 | LTCControl | 660-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | LTCC000646 | LTCControl | 660-1 | LTC Control Insp | VRR Base Voltage AL | 123.0 | VAC |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | LTCC000646 | LTCControl | 660-1 | LTC Control Insp | VRR Base Voltage AF | 123.0 | VAC |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | LTCC000646 | LTCControl | 660-1 | LTC Control Insp | All Connections OK? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | LTCC000646 | LTCControl | 660-1 | LTC Control Insp | LTC Output Voltage Level | 122.0 | VAC |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | LTCC000646 | LTCControl | 660-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | LTCC000646 | LTCControl | 660-1 | LTC Control Insp | General Comments | | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | LTCC000646 | LTCControl | 660-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Counter Readings | General Comments | | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Counter Readings | LTC As Found Counter | 118823 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Counter Readings | LTC As Left Counter | 118823 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Counter Readings | LTC Operations Since Last Insp | 531 | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BCH001563 | Charger | 660-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BCH001563 | Charger | 660-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BCH001563 | Charger | 660-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.2 | amps |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BCH001563 | Charger | 660-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BCH001563 | Charger | 660-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BCH001563 | Charger | 660-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BCH001563 | Charger | 660-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BCH001563 | Charger | 660-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | General Comments | | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | General Comments | | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | General Comments | | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/12/2023 11:23 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | LTCC000111 | LTCControl | 195-5 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | LTCC000111 | LTCControl | 195-5 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | LTCC000111 | LTCControl | 195-5 | LTC Control Insp | LTC Output Voltage Level | 124.8 | VAC |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | LTCC000111 | LTCControl | 195-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | LTCC000111 | LTCControl | 195-5 | LTC Control Insp | All Connections OK? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | LTCC000111 | LTCControl | 195-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | LTCC000111 | LTCControl | 195-5 | LTC Control Insp | General Comments | | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | LTCC000111 | LTCControl | 195-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Readings | Totalizer Meter Reading | .3714 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Readings | Oil Temp Present | 60 | °C |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Readings | LTC Totalizer Reading | 2674.08 | kw |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Readings | General Comments | | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Operations Counter AL | 321 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Operations Counter AF | 321 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | General Comments | | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | 9 Month Operations | 2 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Amps C Ø | 0.0 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Amps B Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Amps A Ø | 0.0 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | General Comments | | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Operations Counter AF | 267 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Operations Counter AL | 267 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | 9 Month Operations | 0 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Amps A Ø | 65.0 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Amps B Ø | 70.0 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Amps C Ø | 75.0 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Counter Readings | LTC As Left Counter | 40492 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Counter Readings | LTC As Found Counter | 40492 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Counter Readings | General Comments | | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Counter Readings | LTC Operations Since Last Insp | 201 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | LTCC000910 | LTCControl | 658-1 | LTC Control Insp | All Connections OK? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | LTCC000910 | LTCControl | 658-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | LTCC000910 | LTCControl | 658-1 | LTC Control Insp | General Comments | | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | LTCC000910 | LTCControl | 658-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | LTCC000910 | LTCControl | 658-1 | LTC Control Insp | LTC Output Voltage Level | 121.0 | VAC |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | LTCC000910 | LTCControl | 658-1 | LTC Control Insp | VRR Base Voltage AF | 122.0 | VAC |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | LTCC000910 | LTCControl | 658-1 | LTC Control Insp | VRR Base Voltage AL | 122.0 | VAC |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | LTCC000910 | LTCControl | 658-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Readings | General Comments | | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Readings | LTC Totalizer Reading | 1713.60 | kw |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Readings | Winding Temp Max | 55 | °C |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Readings | Totalizer Meter Reading | .1190 | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | General Comments | | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | General Comments | | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/12/2023 13:45 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BCH000873 | Charger | 658-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.0 | amps |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BCH000873 | Charger | 658-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BCH000873 | Charger | 658-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BCH000873 | Charger | 658-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.0 | VDC |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BCH000873 | Charger | 658-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BCH000873 | Charger | 658-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.0 | VDC |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | BCH000873 | Charger | 658-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | General Comments | | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | MOD Cabinet Heater functional? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | MOD Cabinet Internals Clean? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | MOD Motor Jaw Coupling | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | General Comments | | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | General Comments | | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | General Comments | | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/12/2023 11:11 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | Ambient Temp | 65 | °F |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | General Comments | Neighbor's fence is within 6 feet. Trees hanging over fence on east side of station. | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Follow-up Action Required? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | n | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | General Comments | No fuses in this station. Please remove from inspection | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | General Comments | | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | n | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | General Comments | | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/12/2023 11:44 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | Ambient Temp | 70 | °F |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | 9 Month Operations | 1 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Amps C Ø | 14.0 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | General Comments | | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Operations Counter AF | 372 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Operations Counter AL | 372 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Amps A Ø | 4.0 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Amps B Ø | 10.0 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Unknown Operations | 1 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Operations This Read Vac | 4 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Operations Counter AL | 343 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Operations Counter AF | 343 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | General Comments | | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Fault Operations C Ø | 1 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Fault Operations B Ø | 1 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Fault Adjusted Amps C Phase V | 10.13 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Fault Adjusted Amps B Phase V | 10.13 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Fault Adjusted Amps A Phase V | 10.13 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Amps C Ø | 58.0 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Amps B Ø | 60.0 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Amps A Ø | 60.0 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | 9 Month Operations | 5 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Fault Adjusted Amps A Phase V | 5.07 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Operations This Read Vac | 1 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Operations Counter AL | 301 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | General Comments | | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Operations Counter AF | 301 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Amps C Ø | 48.0 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Amps B Ø | 51.0 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Amps A Ø | 59.0 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | 9 Month Operations | 5 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 115627 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 109823 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Current Tap Position | 2R | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 133351 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .3570 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Readings | Oil Temp Present | 43 | °C |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Readings | Oil Temp Max | 70 | °C |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3427.20 | kw |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Readings | General Comments | | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | BCH001331 | Charger | 783-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | BCH001331 | Charger | 783-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | BCH001331 | Charger | 783-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | BCH001331 | Charger | 783-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | BCH001331 | Charger | 783-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.3 | amps |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | BCH001331 | Charger | 783-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | BCH001331 | Charger | 783-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | BCH001331 | Charger | 783-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 55 | °F |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Amps A Ø | 0.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Amps B Ø | 0.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Amps C Ø | 0.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AL | 314 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AF | 314 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Amps A Ø | 221.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Amps B Ø | 231.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Amps C Ø | 224.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Operations Counter AF | 235 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Operations Counter AL | 235 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | 9 Month Operations | 2 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | 9 Month Operations | 3 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Amps A Ø | 31.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Amps B Ø | 35.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Amps C Ø | 29.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Fault Adjusted Amps A Phase V | 11.18 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Fault Adjusted Amps B Phase V | 11.18 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | General Comments | A and B phase TOC | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Fault Operations B Ø | 1 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Operations This Read Vac | 2 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Operations Counter AL | 305 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Operations Counter AF | 305 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | 9 Month Operations | 9 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Fault Operations A Ø | 3 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Fault Operations B Ø | 4 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | General Comments | A and B phase TOC | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Fault Adjusted Amps B Phase V | 44.72 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Fault Adjusted Amps A Phase V | 33.54 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Amps C Ø | 314.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Operations This Read Vac | 7 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Amps B Ø | 323.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Amps A Ø | 330.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Operations Counter AL | 332 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Operations Counter AF | 332 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | 9 Months Operations | 2 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Amps A Ø | 110.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Amps B Ø | 98.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Amps C Ø | 122.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Unknown Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Switching Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Fault Adjusted Amps B Phase AM | 11.18 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Fault Adjusted Amps C Phase AM | 11.18 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Fault Operations B Ø | 1 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Fault Operations C Ø | 1 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | General Comments | B and C phase IOC | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Operations Counter AF | 1000 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Operations Counter AL | 1000 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Operations This Read AM | 2 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Amps B Ø | 52.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Amps A Ø | 58.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Amps C Ø | 52.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Fault Adjusted Amps A Phase V | 11.18 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | 9 Month Operations | 4 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Operations This Read Vac | 2 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Operations Counter AL | 366 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Operations Counter AF | 366 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | General Comments | A and B phase IOC | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Fault Operations B Ø | 1 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Fault Adjusted Amps B Phase V | 11.18 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Operations Counter AL | 132 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Operations Counter AF | 132 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Amps C Ø | 600.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Amps B Ø | 635.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Amps A Ø | 611.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | 9 Month Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | PF000192 | PowerFuse | KE-STA SER NO 2 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | PF000192 | PowerFuse | KE-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | PF000192 | PowerFuse | KE-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | PF000191 | PowerFuse | KE-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | PF000191 | PowerFuse | KE-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | PF000191 | PowerFuse | KE-12KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Amps A Ø | 77.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Amps B Ø | 78.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Amps C Ø | 73.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Fault Adjusted Amps B Phase AM | 22.36 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | 9 Months Operations | 2 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Operations Counter AF | 1241 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Operations Counter AL | 1241 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Operations This Read AM | 2 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Fault Operations B Ø | 2 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Switching Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Unknown Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Patrol Inspection | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Amps B Ø | 15.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Amps A Ø | 15.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | 9 Months Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Amps C Ø | 22.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Operations Counter AF | 724 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Operations Counter AL | 724 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Operations This Read AM | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Switching Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Unknown Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Patrol Inspection | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Patrol Inspection | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | 9 Months Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Amps A Ø | 53.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Amps B Ø | 51.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Operations Counter AF | 705 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Operations Counter AL | 705 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Unknown Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Amps C Ø | 49.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Switching Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Operations This Read AM | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Patrol Inspection | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Amps C Ø | 261.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Amps B Ø | 239.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Amps A Ø | 250.0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | 9 Months Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Unknown Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Switching Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Operations This Read AM | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Operations Counter AL | 586 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Operations Counter AF | 586 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Patrol Inspection | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | PF000189 | PowerFuse | KE-12KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | PF000189 | PowerFuse | KE-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | PF000189 | PowerFuse | KE-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | PF000190 | PowerFuse | KE-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | PF000190 | PowerFuse | KE-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | PF000190 | PowerFuse | KE-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LTCC000015 | LTCControl | KE-TRANS 2 | LTC Control Insp | All Connections OK? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LTCC000015 | LTCControl | KE-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LTCC000015 | LTCControl | KE-TRANS 2 | LTC Control Insp | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LTCC000015 | LTCControl | KE-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 5R | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 117954 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 117954 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Counter Readings | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 784 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 50 | °C |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 45 | °C |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 55 | °C |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 45 | °C |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 55 | °C |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 45 | °C |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 65 | °C |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LTCC000016 | LTCControl | KE-TRANS 1 | LTC Control Insp | All Connections OK? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LTCC000016 | LTCControl | KE-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LTCC000016 | LTCControl | KE-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LTCC000016 | LTCControl | KE-TRANS 1 | LTC Control Insp | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 213 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 204611 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 204611 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Counter Readings | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 47 | °C |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 35 | °C |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 40 | °C |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 35 | °C |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 40 | °C |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 35 | °C |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Platform/Walkway/Railing OK? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | BCH000023 | Charger | KE-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | BCH000023 | Charger | KE-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | BCH000023 | Charger | KE-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | BCH000023 | Charger | KE-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | BCH000023 | Charger | KE-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 9.0 | amps |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | BCH000023 | Charger | KE-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 54.0 | VDC |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | BCH000023 | Charger | KE-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 54.0 | VDC |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | BCH000023 | Charger | KE-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | BAT001016 | Battery | KE-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | BAT001016 | Battery | KE-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | BAT001016 | Battery | KE-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | BAT001016 | Battery | KE-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | BAT001016 | Battery | KE-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | BAT001016 | Battery | KE-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | BAT001016 | Battery | KE-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | BAT001016 | Battery | KE-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | BAT001016 | Battery | KE-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | BAT001016 | Battery | KE-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | BAT001016 | Battery | KE-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | BAT001016 | Battery | KE-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Restroom Clean & OK? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | General Comments | | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/12/2023 16:47 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | General Comments | | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | General Comments | | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | General Comments | | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/12/2023 10:42 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | TR has active oil leaks | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | Dripping | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Counter Readings | General Comments | | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 24871 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 24871 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 10 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 6 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 15 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 426 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | LTC oil is very low. The LTC filter pump is pulling air. | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Very Low | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Patrol Inspection | General Comments | | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | 9 Months Operations | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Operations Counter AF | 536 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Operations Counter AL | 536 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Operations This Read AM | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Switching Operations | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | General Comments | 105 amps is the actual reading on C phase | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Unknown Operations | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Amps A Ø | 30.0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Amps B Ø | 40.0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Amps C Ø | 105.0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Patrol Inspection | General Comments | | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | 9 Months Operations | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Amps A Ø | 60.0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Amps B Ø | 55.0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Amps C Ø | 50.0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Operations Counter AF | 505 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | General Comments | | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Unknown Operations | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Switching Operations | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Operations This Read AM | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Operations Counter AL | 505 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Patrol Inspection | General Comments | | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | 9 Month Ops New | 1 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | 9 Months Operations | 1 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Unknown Operations | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Switching Operations | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | General Comments | | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Amps A Ø | 30.0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Amps B Ø | 50.0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Amps C Ø | 50.0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Operations Counter AF | 295 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Operations Counter AL | 295 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Operations This Read AM | 0 | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | BCH000121 | Charger | EI-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | BCH000121 | Charger | EI-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | BCH000121 | Charger | EI-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | BCH000121 | Charger | EI-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | BCH000121 | Charger | EI-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.8 | VDC |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | BCH000121 | Charger | EI-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.8 | VDC |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | BCH000121 | Charger | EI-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 77 | °F |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | CH000456 | ControlHouse | EI-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | CH000456 | ControlHouse | EI-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | CH000456 | ControlHouse | EI-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | CH000456 | ControlHouse | EI-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | CH000456 | ControlHouse | EI-Battery Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | CH000456 | ControlHouse | EI-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | CH000456 | ControlHouse | EI-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | CH000456 | ControlHouse | EI-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | CH000456 | ControlHouse | EI-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | YD000620 | Yard | EI-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | YD000620 | Yard | EI-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | YD000620 | Yard | EI-Yard | Yard Patrol Inspection | General Comments | | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | YD000620 | Yard | EI-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | YD000620 | Yard | EI-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | YD000620 | Yard | EI-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | YD000620 | Yard | EI-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | YD000620 | Yard | EI-Yard | Yard Patrol Inspection | Ambient Temp | 72 | °F |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | YD000620 | Yard | EI-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | YD000620 | Yard | EI-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | YD000620 | Yard | EI-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | General Comments | | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PF001303 | PowerFuse | EI-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PF001303 | PowerFuse | EI-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/12/2023 9:14 | Distribution | Eighth Street Quarterly Inspection | PF001303 | PowerFuse | EI-4KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | General Comments | Battery voltage after 1 min trip: 50.1 volts. Need to add a spot on this inps. | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | 9 Month Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | General Comments | | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Amps C Ø | 84.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Amps B Ø | 85.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Operations Counter AF | 28 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Operations Counter AL | 28 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Amps A Ø | 83.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | 9 Month Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Amps A Ø | 9.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Amps C Ø | 8.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Amps B Ø | 16.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Operations Counter AL | 53 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Operations Counter AF | 53 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | General Comments | | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Amps B Ø | 423.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Amps A Ø | 451.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Amps C Ø | 467.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Operations Counter AL | 13 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Operations Counter AF | 13 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | General Comments | | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | 9 Month Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Operations Counter AL | 28 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Operations Counter AF | 28 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | General Comments | | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Amps C Ø | 69.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Amps B Ø | 61.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Amps A Ø | 78.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | 9 Month Operations | 3 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | 9 Month Operations | 6 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Amps A Ø | 100.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | General Comments | | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Operations Counter AF | 23 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Amps B Ø | 93.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Operations Counter AL | 23 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Amps C Ø | 107.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | General Comments | | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Unknown Operations | 2 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Operations This Read Vac | 2 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Operations Counter AL | 21 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Operations Counter AF | 21 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | 9 Month Operations | 8 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Amps A Ø | 59.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Amps B Ø | 62.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Amps C Ø | 59.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Fault Adjusted Amps A Phase V | 22.36 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Fault Adjusted Amps B Phase V | 22.36 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Fault Adjusted Amps C Phase V | 22.36 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Amps A Ø | 49.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Amps B Ø | 55.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Amps C Ø | 60.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | 9 Month Operations VCB New | 12 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | 9 Month Operations | 12 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | General Comments | | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Operations Counter AF | 50 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Operations Counter AL | 50 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | 9 Month Operations | 37 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | 9 Month Operations VCB New | 37 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Operations Counter AL | 37 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Operations Counter AF | 37 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Amps B Ø | 166.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Amps A Ø | 171.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Amps C Ø | 183.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | General Comments | | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Operations Counter AF | 50 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Operations Counter AL | 50 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | General Comments | | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | 9 Month Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Amps A Ø | 250.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Amps B Ø | 258.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Amps C Ø | 241.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | 9 Month Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Amps A Ø | 0.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Amps B Ø | 0.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Amps C Ø | 0.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | General Comments | | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Operations Counter AF | 32 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Operations Counter AL | 32 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | 9 Month Operations | 12 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | 9 Month Operations VCB New | 11 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Amps A Ø | 50.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Amps B Ø | 52.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Amps C Ø | 48.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Fault Adjusted Amps C Phase V | 24.78 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Fault Operations C Ø | 1 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | General Comments | | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Operations Counter AF | 53 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Operations Counter AL | 53 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Operations This Read Vac | 1 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | 9 Month Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Amps A Ø | 61.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Amps B Ø | 63.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Amps C Ø | 63.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | General Comments | | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Operations Counter AF | 35 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Operations Counter AL | 35 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Operations This Read Vac | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Unknown Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | General Comments | There are two dozen trees within 5 feet of the fence on the east and south sides of the station. | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Follow-up Action Required? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | General Comments | Need to replace two 8', single pin light bulbs in the house. None onsite.There is a pile of old relays in the coner of the control house th | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Restroom Clean & OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Control House Lighting OK? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | There is one fan in bank 1 (north side, top) that is not working | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 10.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 45 | °C |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 40 | °C |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 60 | °C |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 60 | °C |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 50 | °C |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 40 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 74446 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 74446 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 1L | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 230 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Counter Readings | General Comments | | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | General Comments | oil level just above low mark | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | Tank Oil Level | Low | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | .9 | psi |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .3 | psi |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | There are 3 fans not working. The nitro bottle is empty and alarm ISO | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 55.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 45 | °C |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 45 | °C |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 50 | °C |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 45 | °C |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 45 | °C |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 40 | °C |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 105970 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 105970 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Counter Readings | General Comments | | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 328 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Operations This Read Vac | 6 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Operations Counter AL | 268 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Operations Counter AF | 268 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | General Comments | | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Switching Operations | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Fault Operations B Ø | 3 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Fault Operations A Ø | 3 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | 9 Month Operations | 6 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Fault Adjusted Amps B Phase V | 74.34 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Fault Adjusted Amps A Phase V | 74.34 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Amps C Ø | 55.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Amps B Ø | 56.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Amps A Ø | 55.0 | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | PF000168 | PowerFuse | HC-STA SER NO 2 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | PF000168 | PowerFuse | HC-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | PF000168 | PowerFuse | HC-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | PF000169 | PowerFuse | HC-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | PF000169 | PowerFuse | HC-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | PF000169 | PowerFuse | HC-12KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | PF001312 | PowerFuse | HC-1431 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | PF001312 | PowerFuse | HC-1431 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | PF001312 | PowerFuse | HC-1431 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Patrol Inspection | General Comments | | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | PF000166 | PowerFuse | HC-14KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | PF000166 | PowerFuse | HC-14KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | PF000166 | PowerFuse | HC-14KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | PF000167 | PowerFuse | HC-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | PF000167 | PowerFuse | HC-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | PF000167 | PowerFuse | HC-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LTCC000433 | LTCControl | HC-TRANS 2 | LTC Control Insp | All Connections OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LTCC000433 | LTCControl | HC-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LTCC000433 | LTCControl | HC-TRANS 2 | LTC Control Insp | General Comments | | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LTCC000433 | LTCControl | HC-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LTCC000520 | LTCControl | HC-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LTCC000520 | LTCControl | HC-TRANS 1 | LTC Control Insp | General Comments | | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LTCC000520 | LTCControl | HC-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LTCC000520 | LTCControl | HC-TRANS 1 | LTC Control Insp | All Connections OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | UG Pothead Condition Good? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | General Comments | | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BCH001208 | Charger | HC-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BCH001208 | Charger | HC-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 8.7 | amps |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BCH001208 | Charger | HC-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BCH001208 | Charger | HC-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BCH001208 | Charger | HC-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BCH001208 | Charger | HC-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BCH001208 | Charger | HC-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | General Comments | | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | General Comments | There is no/we cannot verify: Foundation/tank paint condition, bushing/ bushing riser condition. Remove from inspection. | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | General Comments | There is no/we cannot verify: Foundation/tank paint condition, bushing/ bushing riser condition. Remove from inspection. | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | General Comments | There is no/we cannot verify: Foundation/tank paint condition, bushing/ bushing riser condition. Remove from inspection. | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | General Comments | There is no/we cannot verify: Foundation/tank paint condition, bushing/ bushing riser condition. Remove from inspection. | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | General Comments | There is no/we cannot verify: Foundation/tank paint condition, bushing/ bushing riser condition. Remove from inspection. | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | General Comments | There is no/we cannot verify: Foundation/tank paint condition, bushing/ bushing riser condition. Remove from inspection. | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | General Comments | There is no/we cannot verify: Foundation/tank paint condition, bushing/ bushing riser condition. Remove from inspection. | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | General Comments | There is no/we cannot verify: Foundation/tank paint condition, bushing/ bushing riser condition. Remove from inspection. | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | General Comments | There is no/we cannot verify: Foundation/tank paint condition, bushing/ bushing riser condition. Remove from inspection. | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | General Comments | There is no/we cannot verify: Foundation/tank paint condition, bushing/ bushing riser condition. Remove from inspection. | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | General Comments | There is no/we cannot verify: Foundation/tank paint condition, bushing/ bushing riser condition. Remove from inspection. | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | General Comments | There is no/we cannot verify: Foundation/tank paint condition, bushing/ bushing riser condition. Remove from inspection. | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 9:05 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 297 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 408936 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 408936 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Counter Readings | General Comments | | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Readings | LV Winding Temp Present | -60 | °C |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Readings | LV Winding Temp Max | -60 | °C |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Patrol Inspection | General Comments | | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | 9 Months Operations | 1 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | 9 Month Ops New | 1 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | General Comments | | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Operations Counter AF | 547 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Operations Counter AL | 547 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Operations This Read AM | 0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Switching Operations | 0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Amps C Ø | 80.0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Amps B Ø | 80.0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Amps A Ø | 80.0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Unknown Operations | 0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Patrol Inspection | General Comments | | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Switching Operations | 0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Unknown Operations | 0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | 9 Months Operations | 0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Operations This Read AM | 0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Operations Counter AL | 460 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Operations Counter AF | 460 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | General Comments | | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Amps A Ø | 60.0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Amps B Ø | 40.0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Amps C Ø | 40.0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Switching Operations | 0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Unknown Operations | 0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | General Comments | | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | 9 Months Operations | 1 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Fault Operations B Ø | 1 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Operations This Read AM | 1 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Operations Counter AL | 368 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Operations Counter AF | 368 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Amps A Ø | 80.0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Amps B Ø | 100.0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Amps C Ø | 100.0 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 9.55 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Patrol Inspection | General Comments | | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | CH000474 | ControlHouse | GI-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | CH000474 | ControlHouse | GI-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | CH000474 | ControlHouse | GI-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | CH000474 | ControlHouse | GI-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | CH000474 | ControlHouse | GI-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | CH000474 | ControlHouse | GI-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | CH000474 | ControlHouse | GI-Battery Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | CH000474 | ControlHouse | GI-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | CH000474 | ControlHouse | GI-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | General Comments | | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | General Comments | | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | BCH001338 | Charger | GI-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | BCH001338 | Charger | GI-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | BCH001338 | Charger | GI-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | BCH001338 | Charger | GI-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.7 | VDC |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | BCH001338 | Charger | GI-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | BCH001338 | Charger | GI-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.7 | VDC |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PF001309 | PowerFuse | GI-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/12/2023 7:56 | Distribution | Gilligan Quarterly Inspection | PF001309 | PowerFuse | GI-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 11:06 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | 9 Month Operations | 7 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Amps A Ø | 96.0 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Amps B Ø | 95.0 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Amps C Ø | 79.0 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Unknown Operations | 0 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Switching Operations | 0 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | General Comments | | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Operations This Read Vac | 0 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Operations Counter AL | 229 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Operations Counter AF | 229 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Amps C Ø | 51.0 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Amps B Ø | 49.0 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Amps A Ø | 55.0 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Operations Counter | 2 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Counter Readings | LTC Operations Since Last Insp | 205 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Counter Readings | LTC Min Tap Position | 3L | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Counter Readings | LTC As Left Counter | 1988 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Counter Readings | LTC As Found Counter | 1980 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Counter Readings | General Comments | | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | LTCC000805 | LTCControl | 401-1 | LTC Control Insp | All Connections OK? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | LTCC000805 | LTCControl | 401-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | LTCC000805 | LTCControl | 401-1 | LTC Control Insp | General Comments | | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | LTCC000805 | LTCControl | 401-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | LTCC000805 | LTCControl | 401-1 | LTC Control Insp | LTC Output Voltage Level | 123.6 | VAC |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | LTCC000805 | LTCControl | 401-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | LTCC000805 | LTCControl | 401-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | LTCC000805 | LTCControl | 401-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Readings | General Comments | | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Readings | LTC Totalizer Reading | 2939.04 | kw |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.2246 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BAT001421 | Battery | 401-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BAT001421 | Battery | 401-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 76 | °F |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BAT001421 | Battery | 401-Battery Bank | Battery Patrol Inspection | Bat Volt 1Min After Chgr Trip | 0.0 | VDC |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BAT001421 | Battery | 401-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BAT001421 | Battery | 401-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BAT001421 | Battery | 401-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BAT001421 | Battery | 401-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BAT001421 | Battery | 401-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BAT001421 | Battery | 401-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BAT001421 | Battery | 401-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 9.0 | VDC |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BAT001421 | Battery | 401-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 9.0 | VDC |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BAT001421 | Battery | 401-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BAT001421 | Battery | 401-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BCH000238 | Charger | 401-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.500 | millivolts |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BCH000238 | Charger | 401-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BCH000238 | Charger | 401-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BCH000238 | Charger | 401-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BCH000238 | Charger | 401-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 54.7 | VDC |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | BCH000238 | Charger | 401-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 54.7 | VDC |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | General Comments | | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | Ambient Temp | 76 | °F |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | General Comments | | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | General Comments | | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/11/2023 16:37 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | BAT001678 | Battery | 912-Offline-Distribution | Battery Patrol Inspection | All Connections OK? | y | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | BAT001678 | Battery | 912-Offline-Distribution | Battery Patrol Inspection | Bat Volt 1Min After Chgr Trip | 0.0 | VDC |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | BAT001678 | Battery | 912-Offline-Distribution | Battery Patrol Inspection | Battery Area Ambient Temp | 76 | °F |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | BAT001678 | Battery | 912-Offline-Distribution | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | BAT001678 | Battery | 912-Offline-Distribution | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | BAT001678 | Battery | 912-Offline-Distribution | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | BAT001678 | Battery | 912-Offline-Distribution | Battery Patrol Inspection | Positive DC Ground | .5 | VDC |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | BAT001678 | Battery | 912-Offline-Distribution | Battery Patrol Inspection | Negative DC Ground | .5 | VDC |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | BAT001678 | Battery | 912-Offline-Distribution | Battery Patrol Inspection | General Comments | | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | BAT001678 | Battery | 912-Offline-Distribution | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | BAT001678 | Battery | 912-Offline-Distribution | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | BAT001678 | Battery | 912-Offline-Distribution | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | BAT001678 | Battery | 912-Offline-Distribution | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | BCH000845 | Charger | Retired Distribution | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | BCH000845 | Charger | Retired Distribution | Battery Charger Patrol Insp | General Comments | | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | BCH000845 | Charger | Retired Distribution | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .600 | millivolts |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | BCH000845 | Charger | Retired Distribution | Battery Charger Patrol Insp | As Left Float Voltage | 55.7 | VDC |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Amps B Ø | 240.0 | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Operations Counter AF | 30 | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Operations Counter AL | 30 | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | General Comments | | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Amps A Ø | 240.0 | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Unknown Operations | 0 | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | 9 Month Operations | 0 | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Amps C Ø | 250.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Operations This Read Vac | 0 | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Switching Operations | 0 | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | LTCC000232 | LTCControl | 159-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | LTCC000232 | LTCControl | 159-5 | LTC Control Insp | VRR Base Voltage AL | 115.0 | VAC |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | LTCC000232 | LTCControl | 159-5 | LTC Control Insp | VRR Base Voltage AF | 115.0 | VAC |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | LTCC000232 | LTCControl | 159-5 | LTC Control Insp | LTC Output Voltage Level | 114.6 | VAC |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | LTCC000232 | LTCControl | 159-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | LTCC000232 | LTCControl | 159-5 | LTC Control Insp | General Comments | | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | LTCC000232 | LTCControl | 159-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | LTCC000232 | LTCControl | 159-5 | LTC Control Insp | All Connections OK? | y | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Counter Readings | General Comments | | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Counter Readings | LTC As Found Counter | 77333 | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Counter Readings | LTC As Left Counter | 77346 | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Counter Readings | LTC Current Tap Position | 5R | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Counter Readings | LTC Operations Since Last Insp | 100 | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Readings | Totalizer Meter Reading | .5416 | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Readings | Oil Temp Present | 42 | °C |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Readings | LTC Totalizer Reading | 1733.12 | kw |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Readings | General Comments | | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 4/11/2023 16:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 100.00 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Switching Operations | 4 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Operations This Read Vac | 4 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Operations Counter AL | 239 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | General Comments | | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Amps C Ø | 20.0 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Amps B Ø | 15.0 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Amps A Ø | 15.0 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Operations Counter AF | 239 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | 9 Month Operations | 6 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | 9 Month Operations | 2 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Unknown Operations | 0 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Amps C Ø | 10.0 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | General Comments | | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Operations Counter AF | 751 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Operations Counter AL | 751 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Operations This Read Vac | 2 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Amps B Ø | 10.0 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Amps A Ø | 10.0 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Switching Operations | 2 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Unknown Operations | 0 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Switching Operations | 2 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Operations This Read Vac | 6 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Operations Counter AL | 202 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Operations Counter AF | 202 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | General Comments | | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Fault Operations B Ø | 2 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Fault Operations A Ø | 2 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | 9 Month Operations | 6 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Fault Adjusted Amps B Phase V | 9.88 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Fault Adjusted Amps A Phase V | 9.88 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Amps C Ø | 52.0 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Amps B Ø | 62.0 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Amps A Ø | 65.0 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Counter Readings | LTC Operations Since Last Insp | 325 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Counter Readings | LTC As Left Counter | 191086 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Counter Readings | LTC As Found Counter | 191086 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Counter Readings | General Comments | | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | LTCC000977 | LTCControl | 204-5 | LTC Control Insp | All Connections OK? | y | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | LTCC000977 | LTCControl | 204-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | LTCC000977 | LTCControl | 204-5 | LTC Control Insp | General Comments | | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | LTCC000977 | LTCControl | 204-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | LTCC000977 | LTCControl | 204-5 | LTC Control Insp | LTC Output Voltage Level | 123.5 | VAC |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | LTCC000977 | LTCControl | 204-5 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | LTCC000977 | LTCControl | 204-5 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | LTCC000977 | LTCControl | 204-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Readings | Totalizer Meter Reading | .5010 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 65.00 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Readings | General Comments | | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Readings | LTC Totalizer Reading | 4809.60 | kw |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Readings | Oil Temp Max | 80 | °C |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BCH001472 | Charger | 204-Battery Charger Dist | Battery Charger Patrol Insp | Battery Charger Current | .6 | amps |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BCH001472 | Charger | 204-Battery Charger Dist | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BCH001472 | Charger | 204-Battery Charger Dist | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BCH001472 | Charger | 204-Battery Charger Dist | Battery Charger Patrol Insp | General Comments | | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BCH001472 | Charger | 204-Battery Charger Dist | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BCH001472 | Charger | 204-Battery Charger Dist | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | Battery Area Ambient Temp | 75 | °F |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | All Connections OK? | y | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | General Comments | | |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | Negative DC Ground | 26.7 | VDC |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | Positive DC Ground | 26.8 | VDC |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/11/2023 15:34 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | BCH001614 | Charger | 758-Battery Charger | Battery Charger Patrol Insp | General Comments | no amps on display | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | BCH001614 | Charger | 758-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | BCH001614 | Charger | 758-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | BCH001614 | Charger | 758-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | BCH001614 | Charger | 758-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 0.0 | amps |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | BCH001614 | Charger | 758-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | BCH001614 | Charger | 758-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | BCH001614 | Charger | 758-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .700 | millivolts |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | BAT001677 | Battery | 758-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.5 | VDC |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | BAT001677 | Battery | 758-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | BAT001677 | Battery | 758-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | BAT001677 | Battery | 758-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | BAT001677 | Battery | 758-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | BAT001677 | Battery | 758-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.5 | VDC |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | BAT001677 | Battery | 758-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | BAT001677 | Battery | 758-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | BAT001677 | Battery | 758-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | BAT001677 | Battery | 758-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | BAT001677 | Battery | 758-Battery Bank | Battery Patrol Inspection | Bat Volt 1Min After Chgr Trip | 0.0 | VDC |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | BAT001677 | Battery | 758-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 80 | °F |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | BAT001677 | Battery | 758-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 85789 | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.3 | volts |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.0 | volts |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 91398 | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Max Tap Position | 6L | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.6 | volts |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 72549 | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Readings | General Comments | | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1090.08 | kw |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .4542 | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 10.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Operations This Read Vac | 1 | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Operations Counter AL | 99946 | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Operations Counter AF | 99946 | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Maintenance Operations | 1 | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | General Comments | | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Amps A Ø | 80.0 | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Amps B Ø | 110.0 | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Amps C Ø | 120.0 | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Switching Operations | 0 | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Unknown Operations | 0 | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | 9 Month Operations | 1 | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | n | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | General Comments | Metering equipment conduit in need of repair | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | General Comments | Barbed wire rusty and droopping in areas. | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | n | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | Ambient Temp | 76 | °F |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | General Comments | | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/11/2023 14:56 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Counter Readings | LTC Operations Since Last Insp | 382 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Counter Readings | LTC As Left Counter | 13984 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Counter Readings | LTC As Found Counter | 13984 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Counter Readings | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCC000723 | LTCControl | 196-6 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCC000723 | LTCControl | 196-6 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCC000723 | LTCControl | 196-6 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCC000723 | LTCControl | 196-6 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCC000723 | LTCControl | 196-6 | LTC Control Insp | All Connections OK? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCC000723 | LTCControl | 196-6 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCC000723 | LTCControl | 196-6 | LTC Control Insp | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCC000723 | LTCControl | 196-6 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 30 | °C |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 40 | °C |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Readings | Winding Temp Max | 60 | °C |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Readings | Totalizer Meter Reading | .5470 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Readings | LTC Totalizer Reading | 7876.80 | kw |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Readings | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 4.0 | psi |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1700 | psi |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | 9 Month Operations | 2 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Amps A Ø | 7.0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Amps B Ø | 7.0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Amps C Ø | 10.0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Operations Counter AF | 224 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Operations Counter AL | 224 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Operations This Read Vac | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Switching Operations | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Unknown Operations | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Amps C Ø | 320.0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Amps B Ø | 335.0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Amps A Ø | 325.0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | 9 Month Operations | 1 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Operations Counter AF | 176 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Operations Counter AL | 177 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Unknown Operations | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Switching Operations | 1 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Operations This Read Vac | 1 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Unknown Operations | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Switching Operations | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Operations This Read Vac | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Operations Counter AL | 208 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Operations Counter AF | 208 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Amps A Ø | 100.0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Amps B Ø | 85.0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | 9 Month Operations | 2 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Amps C Ø | 75.0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Amps C Ø | 240.0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Amps B Ø | 255.0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Amps A Ø | 225.0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Operations Counter AF | 225 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | 9 Month Operations | 2 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Operations Counter AL | 225 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Unknown Operations | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Switching Operations | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Operations This Read Vac | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Unknown Operations | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Switching Operations | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Operations This Read Vac | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Operations Counter AL | 225 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Operations Counter AF | 225 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Amps C Ø | 95.0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Amps B Ø | 100.0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | 9 Month Operations | 2 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Amps A Ø | 90.0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Operations Counter AF | 219 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Operations Counter AL | 219 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | 9 Month Operations | 3 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Amps A Ø | 7.0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Operations This Read Vac | 1 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Amps B Ø | 15.0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Switching Operations | 1 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Unknown Operations | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Amps C Ø | 6.0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Unknown Operations | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Switching Operations | 1 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Operations This Read Vac | 1 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Operations Counter AL | 172 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Operations Counter AF | 171 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Amps C Ø | 150.0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Amps B Ø | 165.0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Amps A Ø | 150.0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | 9 Month Operations | 1 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Amps A Ø | 0.0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Amps B Ø | 0.0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Amps C Ø | 0.0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | 9 Month Operations | 1 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Unknown Operations | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Switching Operations | 1 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Operations This Read Vac | 1 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Operations Counter AL | 190 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Operations Counter AF | 189 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Unknown Operations | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Amps C Ø | 50.0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Amps B Ø | 50.0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Amps A Ø | 48.0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Operations Counter AF | 251 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Operations Counter AL | 251 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Operations This Read Vac | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Switching Operations | 0 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | 9 Month Operations | 2 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCC000736 | LTCControl | 196-5 | LTC Control Insp | All Connections OK? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCC000736 | LTCControl | 196-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCC000736 | LTCControl | 196-5 | LTC Control Insp | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCC000736 | LTCControl | 196-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCC000736 | LTCControl | 196-5 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCC000736 | LTCControl | 196-5 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCC000736 | LTCControl | 196-5 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCC000736 | LTCControl | 196-5 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | LTCC000736 | LTCControl | 196-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | LTCMechanism | 196-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | LTCMechanism | 196-5 | LTC Counter Readings | LTC Operations Since Last Insp | 415 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | LTCMechanism | 196-5 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | LTCMechanism | 196-5 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | LTCMechanism | 196-5 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | LTCMechanism | 196-5 | LTC Counter Readings | LTC As Left Counter | 46544 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | LTCMechanism | 196-5 | LTC Counter Readings | LTC As Found Counter | 46544 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | LTCMechanism | 196-5 | LTC Counter Readings | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | LTCMechanism | 196-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | LTCMechanism | 196-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | LTCMechanism | 196-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | LTCMechanism | 196-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | LTCMechanism | 196-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | LTCMechanism | 196-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Readings | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Readings | LTC Totalizer Reading | 5644.80 | kw |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Readings | Totalizer Meter Reading | .3920 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/11/2023 14:40 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Amps C Ø | 36.0 | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Amps B Ø | 35.0 | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Amps A Ø | 41.0 | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Operations Counter | 67 | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Readings | General Comments | | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Readings | LTC Totalizer Reading | 2842.56 | kw |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Readings | Totalizer Meter Reading | .5922 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Operations Counter | 82 | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Amps A Ø | 29.0 | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Amps B Ø | 18.0 | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Amps C Ø | 18.0 | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | LTCC000024 | LTCControl | 581-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | LTCC000024 | LTCControl | 581-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | LTCC000024 | LTCControl | 581-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | LTCC000024 | LTCControl | 581-1 | LTC Control Insp | LTC Output Voltage Level | 124.3 | VAC |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | LTCC000024 | LTCControl | 581-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | LTCC000024 | LTCControl | 581-1 | LTC Control Insp | General Comments | | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | LTCC000024 | LTCControl | 581-1 | LTC Control Insp | All Connections OK? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | LTCC000024 | LTCControl | 581-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 72039 | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Counter Readings | LTC Operations Since Last Insp | 159 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Counter Readings | LTC As Left Counter | 531022 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Counter Readings | LTC As Found Counter | 531016 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Counter Readings | General Comments | | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 77738 | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.5 | volts |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | BCH000449 | Charger | Retired Distribution | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | BCH000449 | Charger | Retired Distribution | Battery Charger Patrol Insp | As Left Float Voltage | 55.5 | VDC |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | BCH000449 | Charger | Retired Distribution | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .700 | millivolts |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | BCH000449 | Charger | Retired Distribution | Battery Charger Patrol Insp | General Comments | | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | BAT001676 | Battery | 581-Battery Bank | Battery Patrol Inspection | Negative DC Ground | .4 | VDC |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | BAT001676 | Battery | 581-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 85.0 | VDC |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | BAT001676 | Battery | 581-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | BAT001676 | Battery | 581-Battery Bank | Battery Patrol Inspection | Bat Volt 1Min After Chgr Trip | 1.0 | VDC |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | BAT001676 | Battery | 581-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | BAT001676 | Battery | 581-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | BAT001676 | Battery | 581-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | BAT001676 | Battery | 581-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | BAT001676 | Battery | 581-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | BAT001676 | Battery | 581-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | BAT001676 | Battery | 581-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 85 | °F |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | BAT001676 | Battery | 581-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | BAT001676 | Battery | 581-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 213597 | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.2 | volts |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Amps C Ø | 67.0 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Amps B Ø | 71.0 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Amps A Ø | 71.0 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Operations Counter | 106 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | General Comments | 4 unkown ops | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Readings | General Comments | | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .6048 | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Readings | Oil Temp Max | 60 | °C |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1451.52 | kw |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Unknown Operations | 0 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Switching Operations | 0 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Operations This Read Vac | 0 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Operations Counter AL | 1 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Operations Counter AF | 1 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | General Comments | | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Amps C Ø | 20.0 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Amps B Ø | 25.0 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Amps A Ø | 20.0 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | 9 Month Operations | 2 | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | General Comments | | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | General Comments | | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | Ambient Temp | 76 | °F |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | General Comments | | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/11/2023 14:12 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | Ambient Temp | 76 | °F |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | General Comments | | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | n | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Amps A Ø | 38.0 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Amps B Ø | 32.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Amps C Ø | 32.0 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | 9 Month Operations | 2 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | General Comments | | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Operations Counter AF | 212 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Operations Counter AL | 213 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Operations This Read Vac | 1 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Switching Operations | 1 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Unknown Operations | 0 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Unknown Operations | 0 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Switching Operations | 1 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Operations This Read Vac | 1 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Operations Counter AL | 168 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Operations Counter AF | 167 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | General Comments | BFTC | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Amps C Ø | 36.0 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Amps B Ø | 13.0 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Amps A Ø | 21.0 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | 9 Month Operations | 3 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | LTCC000761 | LTCControl | 879-1 | LTC Control Insp | VRR Time Delay | 45 | Seconds |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | LTCC000761 | LTCControl | 879-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | LTCC000761 | LTCControl | 879-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | LTCC000761 | LTCControl | 879-1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | LTCC000761 | LTCControl | 879-1 | LTC Control Insp | LTC Output Voltage Level | 123.8 | VAC |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | LTCC000761 | LTCControl | 879-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | LTCC000761 | LTCControl | 879-1 | LTC Control Insp | General Comments | | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | LTCC000761 | LTCControl | 879-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | LTCC000761 | LTCControl | 879-1 | LTC Control Insp | All Connections OK? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Counter Readings | LTC Operations Since Last Insp | 685 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Counter Readings | LTC As Left Counter | 76258 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Counter Readings | LTC As Found Counter | 76249 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Counter Readings | General Comments | | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Readings | General Comments | | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Readings | LTC Totalizer Reading | 4039.20 | kw |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Readings | Oil Temp Max | 58 | °C |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Readings | Oil Temp Present | 37 | °C |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Readings | Totalizer Meter Reading | .5610 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BCH001494 | Charger | 879-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.780 | millivolts |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BCH001494 | Charger | 879-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BCH001494 | Charger | 879-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BCH001494 | Charger | 879-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .7 | amps |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BCH001494 | Charger | 879-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BCH001494 | Charger | 879-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BCH001494 | Charger | 879-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BCH001494 | Charger | 879-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 80 | °F |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.8 | VDC |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.7 | VDC |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | General Comments | | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | General Comments | | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | YD000068 | Yard | 879-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | YD000068 | Yard | 879-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | YD000068 | Yard | 879-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | YD000068 | Yard | 879-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | YD000068 | Yard | 879-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | YD000068 | Yard | 879-Yard | Yard Patrol Inspection | Ambient Temp | 72 | °F |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | YD000068 | Yard | 879-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | YD000068 | Yard | 879-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | YD000068 | Yard | 879-Yard | Yard Patrol Inspection | General Comments | | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | YD000068 | Yard | 879-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | YD000068 | Yard | 879-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/11/2023 13:55 | Distribution | Verda Quarterly Inspection | YD000068 | Yard | 879-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | General Comments | | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | General Comments | | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Operations This Read AM | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Accumulated Fault Duty C Ph AM | 2.43 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Accumulated Fault Duty A Ph AM | 2.66 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Accumulated Fault Duty C Ph AM | 3.64 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Accumulated Fault Duty B Ph AM | 4.85 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Accumulated Fault Duty A Ph AM | 3.64 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Accumulated Fault Duty B Ph AM | 1.33 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | 9 Month Ops New | 5 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | 9 Month Ops New | 6 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Accumulated Fault Duty A Ph AM | 5.32 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Accumulated Fault Duty B Ph AM | 9.3 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Operations This Read AM | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Accumulated Fault Duty B Ph AM | 3.64 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Operations This Read AM | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Operations This Read AM | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 25.99 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 25.99 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | 9 Month Ops New | 4 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 25.99 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Accumulated Fault Duty A Ph AM | 2.43 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Operations This Read AM | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Operations This Read AM | 0 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | 9 Month Ops New | 5 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Accumulated Fault Duty A Ph AM | 1.21 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Accumulated Fault Duty B Ph AM | 10.92 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Accumulated Fault Duty C Ph AM | 7.28 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Accumulated Fault Duty C Ph AM | 5.32 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | 9 Month Ops New | 4 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Accumulated Fault Duty A Ph AM | 7.97 | % |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Accumulated Fault Duty B Ph AM | 7.97 | % |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | PF001352 | PowerFuse | 627-1F | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | PF001352 | PowerFuse | 627-1F | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/11/2023 14:12 | Distribution | Shakertown Quarterly Inspection | PF001352 | PowerFuse | 627-1F | Disconnect Powerfuse Inspection | General Comments | all good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Counter Readings | General Comments | | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 72574 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 72574 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 230 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 53 | °C |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 422 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Counter Readings | General Comments | | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 541658 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 541658 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 10L | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Readings | LV Winding Temp Max | 70 | °C |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Readings | LV Winding Temp Present | 30 | °C |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Patrol Inspection | General Comments | | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Amps C Ø | 0.0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Amps B Ø | 0.0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Amps A Ø | 0.0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | 9 Months Operations | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | 9 Month Ops New | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | General Comments | DNO | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Operations Counter AF | 326 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Operations Counter AL | 326 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Operations This Read AM | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Switching Operations | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Unknown Operations | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Patrol Inspection | General Comments | | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Amps C Ø | 0.0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Amps B Ø | 0.0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Amps A Ø | 0.0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | 9 Months Operations | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | 9 Month Ops New | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | General Comments | DNO | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Unknown Operations | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Switching Operations | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Operations This Read AM | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Operations Counter AL | 336 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Operations Counter AF | 336 | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Operations Counter | 30 | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Amps A Ø | 37.0 | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Amps B Ø | 28.0 | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Amps C Ø | 34.0 | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Patrol Inspection | General Comments | | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Fault Adjusted Amps A Phase AM | 9.55 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Fault Operations A Ø | 1 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Fault Operations B Ø | 1 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Amps C Ø | 50.0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Amps B Ø | 70.0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Amps A Ø | 60.0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | General Comments | | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | 9 Months Operations | 3 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | 9 Month Ops New | 1 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Fault Adjusted Amps B Phase AM | 9.55 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Operations Counter AF | 282 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Operations Counter AL | 282 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Operations This Read AM | 2 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Switching Operations | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Unknown Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Amps C Ø | 0.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Amps B Ø | 0.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Switching Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Operations Counter AL | 95 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Operations Counter AF | 95 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Amps A Ø | 0.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Unknown Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Switching Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Operations Counter AL | 86 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Operations Counter AF | 86 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Amps C Ø | 0.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Amps B Ø | 0.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Amps A Ø | 0.0 | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 36503 | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Patrol Inspection | General Comments | | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | 9 Month Ops New | 3 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | 9 Months Operations | 3 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Amps A Ø | 30.0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Amps B Ø | 30.0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Amps C Ø | 20.0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Unknown Operations | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Switching Operations | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Operations This Read AM | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Operations Counter AL | 412 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Operations Counter AF | 412 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | General Comments | | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Operations Counter AL | 101 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Operations Counter AF | 101 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Switching Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Unknown Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Amps A Ø | 0.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Amps B Ø | 0.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Amps C Ø | 0.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Patrol Inspection | General Comments | | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Unknown Operations | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Operations Counter AL | 488 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Operations Counter AF | 488 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | General Comments | | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Fault Operations B Ø | 1 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Fault Operations A Ø | 1 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Operations This Read AM | 2 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Switching Operations | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 9.55 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 9.55 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Amps C Ø | 90.0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Amps B Ø | 100.0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Amps A Ø | 80.0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | 9 Months Operations | 3 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | 9 Month Ops New | 1 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Unknown Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Switching Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Operations Counter AL | 76 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Operations Counter AF | 76 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Amps A Ø | 0.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Amps B Ø | 0.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Amps C Ø | 0.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 91923 | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Unknown Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Switching Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Operations Counter AL | 106 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Operations Counter AF | 106 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Amps A Ø | 0.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Amps B Ø | 0.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Amps C Ø | 0.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Patrol Inspection | General Comments | | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 35051 | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.6 | volts |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Unknown Operations | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | General Comments | | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Maintenance Operations | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Operations Counter AF | 506 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Operations Counter AL | 506 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Operations This Read AM | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Switching Operations | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Amps C Ø | 110.0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Amps B Ø | 100.0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Amps A Ø | 80.0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | 9 Months Operations | 3 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | 9 Month Ops New | 3 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Unknown Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Switching Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Operations Counter AL | 121 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Operations Counter AF | 121 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Amps A Ø | 0.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Amps B Ø | 0.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Amps C Ø | 0.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | BCH001034 | Charger | CB-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | BCH001034 | Charger | CB-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.7 | VDC |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | BCH001034 | Charger | CB-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.7 | VDC |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | BCH001034 | Charger | CB-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .2 | amps |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | BCH001034 | Charger | CB-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | BCH001034 | Charger | CB-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | BCH001034 | Charger | CB-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Readings | Winding Temp Present | 30 | °C |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Readings | Winding Temp Max | 35 | °C |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .5030 | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Readings | Oil Temp Max | 30 | °C |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 2414.40 | kw |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Readings | General Comments | | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 75 | °F |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Totalizer Meter Multiplier | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Top Oil Temperature Present | 20 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Top Oil Temperature Max | 20 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Percent Thermal Load C Ø Max | 0 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Percent Thermal Load B Ø Max | 0 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Percent Thermal Load A Ø Max | 0 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | TV Winding Temp Max | 0 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | TV Winding Temp Present | 0 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Winding Temp Max | 20 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Winding Temp Present | 20 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 35 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 35 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 35 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 35 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 35 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 35 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Y1 Winding Temp Max | 0 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Y1 Winding Temp Present | 0 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Y2 Winding Temp Max | 0 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Y2 Winding Temp Present | 0 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Y3 Winding Temp Max | 0 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Y3 Winding Temp Present | 0 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | LV Winding Temp Present | 0 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | LV Winding Temp Max | 0 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | LTC Totalizer Reading | 0.00 | kw |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | HV Winding Temp Present | 0 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | HV Winding Temp Max | 0 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | H3 Winding Temp Present | 0 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | H3 Winding Temp Max | 0 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | H2 Winding Temp Present | 0 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | H2 Winding Temp Max | 0 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | H1 Winding Temp Present | 0 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | H1 Winding Temp Max | 0 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | CH000440 | ControlHouse | CB-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | CH000440 | ControlHouse | CB-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | CH000440 | ControlHouse | CB-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | CH000440 | ControlHouse | CB-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | CH000440 | ControlHouse | CB-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | CH000440 | ControlHouse | CB-Battery Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | CH000440 | ControlHouse | CB-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | CH000440 | ControlHouse | CB-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | CH000440 | ControlHouse | CB-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | Ambient Temp | 75 | °F |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | General Comments | | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | General Comments | | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PF001297 | PowerFuse | CB-4KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PF001297 | PowerFuse | CB-4KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCC000898 | LTCControl | CF-TRANS 2 | LTC Control Insp | All Connections OK? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCC000898 | LTCControl | CF-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCC000898 | LTCControl | CF-TRANS 2 | LTC Control Insp | LTC Operation Checked? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCC000898 | LTCControl | CF-TRANS 2 | LTC Control Insp | LTC Output Voltage Level | 122.5 | VAC |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCC000898 | LTCControl | CF-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCC000898 | LTCControl | CF-TRANS 2 | LTC Control Insp | VRR Base Voltage AF | 0.0 | VAC |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCC000898 | LTCControl | CF-TRANS 2 | LTC Control Insp | VRR Base Voltage AL | 0.0 | VAC |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCC000898 | LTCControl | CF-TRANS 2 | LTC Control Insp | VRR Time Delay | 0 | Seconds |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PF001296 | PowerFuse | CB-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/12/2023 10:58 | Distribution | Crop Quarterly Inspection | PF001296 | PowerFuse | CB-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 20 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 20 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Counter C Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Counter B Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Counter A Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1225 | psi |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | General Comments | there is not a berm here | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | Ambient Temp | 73 | °F |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | General Comments | | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/11/2023 13:32 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Operations Counter AL | 70 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Operations Counter AF | 70 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | General Comments | | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Amps C Ø | 86.0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | 9 Month Operations | 1 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | 9 Month Operations VCB New | 1 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Amps B Ø | 93.0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Amps A Ø | 88.0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | PF001203 | PowerFuse | CF-STA SER NO 6 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | PF001203 | PowerFuse | CF-STA SER NO 6 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | PF001203 | PowerFuse | CF-STA SER NO 6 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Fault Adjusted Amps B Phase AM | 44.72 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Fault Operations B Ø | 4 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | General Comments | B IOC | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Operations Counter AF | 19 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Operations Counter AL | 19 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Operations This Read AM | 4 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Switching Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Amps C Ø | 100.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Amps B Ø | 100.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Unknown Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | 9 Months Operations | 15 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Amps A Ø | 100.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Amps A Ø | 400.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Amps B Ø | 500.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Amps C Ø | 380.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Unknown Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Switching Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Operations Counter AL | 278 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Operations Counter AF | 278 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Operations Counter AF | 386 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Operations Counter AL | 386 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Switching Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Unknown Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Amps B Ø | 250.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Amps A Ø | 250.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Amps C Ø | 250.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Switching Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Unknown Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Operations Counter AL | 99987 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Operations Counter AF | 99987 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Amps C Ø | 250.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Amps B Ø | 250.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Amps A Ø | 250.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Amps A Ø | 100.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Amps B Ø | 100.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Amps C Ø | 100.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Operations Counter AF | 106 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Operations Counter AL | 106 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Switching Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Unknown Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Amps A Ø | 500.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Amps B Ø | 500.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Amps C Ø | 500.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Operations Counter AF | 99785 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Operations Counter AL | 99785 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Switching Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Unknown Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | PF001326 | PowerFuse | CF-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | PF001326 | PowerFuse | CF-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | PF001326 | PowerFuse | CF-12KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | PF000108 | PowerFuse | CF-12KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | PF000108 | PowerFuse | CF-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | PF000108 | PowerFuse | CF-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | PF000107 | PowerFuse | CF-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | PF000107 | PowerFuse | CF-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | PF000107 | PowerFuse | CF-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCC000536 | LTCControl | CF-TRANS 1 | LTC Control Insp | All Connections OK? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCC000536 | LTCControl | CF-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 28765 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 28765 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 344 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | needs nitro bottle filled | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.8 | psi |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 35 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 25 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 35 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 38 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 25 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 35 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 23 | °C |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | ANN000018 | Annunciator | CF-Annunciator Panel | Annunciator Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 2843 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 2843 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 21 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 5L | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | SF6 Pressure Pole 2 | 90 | psi |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | SF6 Pressure Pole 1 | 90 | psi |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | SF6 Pressure Pole 3 | 90 | psi |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Ambient Temperature | 65 | °F |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | Amps A Ø | 45.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | Amps B Ø | 47.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | Amps C Ø | 46.0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | Fault Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | Operations Counter AF | 121 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | Operations Counter AL | 121 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | Switching Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | Unknown Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | Fault Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | Operations Counter AF | 195 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | Operations Counter AL | 195 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | Unknown Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | Switching Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | Amps C Ø | .6 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | Amps B Ø | .2 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | Amps A Ø | .6 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Ambient Temperature | 65 | °F |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | SF6 Pressure Pole 1 | 90 | psi |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | SF6 Pressure Pole 2 | 90 | psi |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | SF6 Pressure Pole 3 | 90 | psi |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 22.2 | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 40 | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 119 | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 25.6 | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 38.4 | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 61 | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 16346 | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 485650 | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 120877 | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 829.44 | kw |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Readings | Oil Temp Max | 69 | °C |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Readings | Oil Temp Present | 39 | °C |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Readings | General Comments | | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .3456 | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | General Comments | Added Nitrogen | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | General Comments | | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | General Comments | Barbed wire is very rusty | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | YD000085 | Yard | 564-Yard | Yard Patrol Inspection | Ambient Temp | 68 | °F |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | YD000085 | Yard | 564-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | YD000085 | Yard | 564-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | YD000085 | Yard | 564-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | YD000085 | Yard | 564-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | YD000085 | Yard | 564-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | YD000085 | Yard | 564-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | YD000085 | Yard | 564-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | n | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | YD000085 | Yard | 564-Yard | Yard Patrol Inspection | General Comments | | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | YD000085 | Yard | 564-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | YD000085 | Yard | 564-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/11/2023 12:05 | Distribution | Bailey Creek Quarterly Inspection | YD000085 | Yard | 564-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | PF000360 | PowerFuse | TT-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | PF000360 | PowerFuse | TT-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | PF000360 | PowerFuse | TT-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 70 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 2L | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 56250 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 56250 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Counter Readings | General Comments | | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 120 | °C |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 200.00 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 35 | °C |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 35 | °C |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 25 | °C |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 20 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 35 | °C |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 35 | °C |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 700 | psi |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | PF000362 | PowerFuse | TT-34KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | PF000362 | PowerFuse | TT-34KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | PF000362 | PowerFuse | TT-34KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Amps A Ø | 115.0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Amps B Ø | 114.0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | 9 Month Operations | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Amps C Ø | 114.0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | General Comments | | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Operations Counter AF | 71 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Operations Counter AL | 71 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Operations Counter AF | 116 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | General Comments | | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Fault Operations Ground | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Amps C Ø | 87.0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Amps B Ø | 87.0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Amps A Ø | 85.0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | 9 Month Operations | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Switching Operations | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Operations This Read Vac | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Operations Counter AL | 116 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Operations Counter AF | 122 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Operations Counter AL | 122 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Operations This Read Vac | 3 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | General Comments | A and B phase IOC and TOC | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Switching Operations | 1 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Fault Operations B Ø | 1 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Fault Adjusted Amps B Phase V | 11.52 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Fault Adjusted Amps A Phase V | 11.52 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Amps A Ø | 31.0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Amps B Ø | 31.0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | 9 Month Operations | 3 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Amps C Ø | 29.0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Follow-up Action Required? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Capacitor Rack Condition OK? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Capacitor Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Cap bank PT in Good Condition? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Cap bank CT in Good Condition? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | All Connections OK? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Warning Signs OK? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Tank Paint Condition | Adequate | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Insulators In Good Condition? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | General Comments | 2 fuses blown | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Fuses Blown? Y / N | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Capacitor Rack Condition OK? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Follow-up Action Required? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Fuses Blown? Y / N | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Capacitor Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | General Comments | 3 fuses blown on bank | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Insulators In Good Condition? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Tank Paint Condition | Adequate | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Warning Signs OK? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | All Connections OK? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Cap bank PT in Good Condition? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Cap bank CT in Good Condition? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | 9 Month Operations | 14 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | 9 Month Operations VCB New | 14 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Switching Operations | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Amps A Ø | 0.0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Amps B Ø | 0.0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Amps C Ø | 0.0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Operations Counter AL | 310 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | General Comments | | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Operations Counter AF | 310 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Switching Operations | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Operations This Read Vac | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Operations Counter AL | 141 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Operations Counter AF | 141 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Fault Operations B Ø | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Fault Operations A Ø | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Amps C Ø | 0.0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Amps B Ø | 0.0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Amps A Ø | 0.0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | 9 Month Operations | 1 | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Amps B Ø | 13.0 | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | General Comments | Trip Check | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Amps A Ø | 31.0 | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Operations Counter | 23 | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Amps C Ø | 33.0 | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Operations Counter | 42 | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | General Comments | Trip Check | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Amps C Ø | 2.0 | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Amps B Ø | 0.0 | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Amps A Ø | 0.0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Amps A Ø | 56.0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Amps B Ø | 58.0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Fault Adjusted Amps A Phase V | 27.00 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Amps C Ø | 54.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | 9 Month Operations | 4 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Fault Adjusted Amps B Phase V | 27.00 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Fault Operations B Ø | 1 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | General Comments | A and B IOC and TOC | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Operations Counter AF | 109 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Operations Counter AL | 109 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Operations This Read Vac | 3 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Switching Operations | 1 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Switching Operations | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Operations This Read Vac | 2 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Operations Counter AL | 127 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Operations Counter AF | 127 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Maintenance Operations | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | General Comments | A and B phase IOC | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Follow-up Action Required? | n | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Fault Operations Ground | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Fault Operations B Ø | 1 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Fault Adjusted Amps B Phase V | 27.00 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Fault Adjusted Amps A Phase V | 27.00 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Amps C Ø | 32.0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Amps B Ø | 35.0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Amps A Ø | 31.0 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | 9 Month Operations | 9 | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Counter Readings | LTC Min Tap Position | 15L | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Counter Readings | LTC Operations Since Last Insp | 619 | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Counter Readings | LTC Current Tap Position | 10L | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Counter Readings | General Comments | | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Counter Readings | LTC As Found Counter | 62701 | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Counter Readings | LTC As Left Counter | 62710 | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | LTCC000804 | LTCControl | 711-1 | LTC Control Insp | LTC Output Voltage Level | 124.2 | VAC |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | LTCC000804 | LTCControl | 711-1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | LTCC000804 | LTCControl | 711-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | LTCC000804 | LTCControl | 711-1 | LTC Control Insp | All Connections OK? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | LTCC000804 | LTCControl | 711-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | LTCC000804 | LTCControl | 711-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | LTCC000804 | LTCControl | 711-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | LTCC000804 | LTCControl | 711-1 | LTC Control Insp | General Comments | | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | LTCC000804 | LTCControl | 711-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | PF000361 | PowerFuse | TT-34KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | PF000361 | PowerFuse | TT-34KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/11/2023 13:23 | Distribution | Tip Top Quarterly Inspection | PF000361 | PowerFuse | TT-34KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Mechanism Patrol Inspection | General Comments | Added Nirtogen | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.5 | psi |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Readings | Totalizer Meter Reading | .1220 | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Readings | Oil Temp Present | 15 | °C |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Readings | Oil Temp Max | 28 | °C |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Readings | LTC Totalizer Reading | 1171.20 | kw |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Readings | General Comments | | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | General Comments | Added Nitrogen | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | General Comments | | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | General Comments | | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | YD000070 | Yard | 711-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | YD000070 | Yard | 711-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | YD000070 | Yard | 711-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | YD000070 | Yard | 711-Yard | Yard Patrol Inspection | General Comments | | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | YD000070 | Yard | 711-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | YD000070 | Yard | 711-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | YD000070 | Yard | 711-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | YD000070 | Yard | 711-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | YD000070 | Yard | 711-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | YD000070 | Yard | 711-Yard | Yard Patrol Inspection | Ambient Temp | 62 | °F |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | YD000070 | Yard | 711-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | YD000070 | Yard | 711-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/11/2023 10:46 | Distribution | Highsplint Quarterly Inspection | YD000070 | Yard | 711-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Operations This Read Vac | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Operations This Read Vac | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | 9 Month Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Operations This Read Vac | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | 9 Month Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Operations This Read Vac | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | 9 Month Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Operations This Read Vac | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | 9 Month Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | 9 Month Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | 9 Month Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | 9 Month Operations GCB New | 1 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | Num Operations Last 9 Months | 1 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | Operations This Read SF6 | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | Operations This Read SF6 | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | 9 Month Ops New | 1 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | 9 Months Operations | 1 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | 9 Month Ops New | 2 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | 9 Months Operations | 2 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Accumulated Fault Duty A Ph AM | 22.59 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Operations This Read AM | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Accumulated Fault Duty B Ph AM | 17.28 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | 9 Month Ops New | 11 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Accumulated Fault Duty A Ph AM | 15.95 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Accumulated Fault Duty B Ph AM | 21.26 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Accumulated Fault Duty C Ph AM | 37.21 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Accumulated Fault Duty C Ph AM | 27.91 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Accumulated Fault Duty B Ph AM | 3.99 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Operations This Read AM | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Accumulated Fault Duty C Ph AM | 35.88 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Operations This Read AM | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | 9 Month Ops New | 3 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | 9 Months Operations | 3 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | 9 Months Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | 9 Months Operations | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Accumulated Fault Duty A Ph AM | 23.92 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Accumulated Fault Duty B Ph AM | 34.55 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Accumulated Fault Duty C Ph AM | 13.29 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Accumulated Fault Duty A Ph AM | 50.5 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Accumulated Fault Duty C Ph AM | 53.16 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Accumulated Fault Duty B Ph AM | 49.17 | % |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Operations This Read AM | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Operations This Read AM | 0 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCC000898 | LTCControl | CF-TRANS 2 | LTC Control Insp | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCC000536 | LTCControl | CF-TRANS 1 | LTC Control Insp | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Gas Accumulation Gauge | Normal | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Counter Readings | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Counter Readings | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Patrol Inspection | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | General Comments | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Grounds in Place? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | General Comments | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Foundation Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Patrol Inspection | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Patrol Inspection | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Patrol Inspection | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Patrol Inspection | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Patrol Inspection | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Patrol Inspection | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | ANN000018 | Annunciator | CF-Annunciator Panel | Annunciator Patrol Inspection | General Comments | | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | ANN000018 | Annunciator | CF-Annunciator Panel | Annunciator Patrol Inspection | ESOC  Received Alarm Test? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | ANN000018 | Annunciator | CF-Annunciator Panel | Annunciator Patrol Inspection | Control House Alarm Audible? | y | |
| 4/11/2023 13:32 | Distribution | Centerfield Quarterly Inspection | ANN000018 | Annunciator | CF-Annunciator Panel | Annunciator Patrol Inspection | All Lights Functioning? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | General Comments | | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | 9 Month Operations | 9 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Maintenance Operations | 0 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Operations Counter AF | 246 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Operations Counter AL | 246 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Operations This Read Vac | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Switching Operations | 0 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Unknown Operations | 0 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Amps A Ø | 830.0 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Amps B Ø | 25.0 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Follow-up Action Required? | n | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Fault Operations Ground | 0 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Amps C Ø | 30.0 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | General Comments | | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Counter Readings | LTC Operations Since Last Insp | 328 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Counter Readings | LTC As Left Counter | 77587 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Counter Readings | LTC As Found Counter | 77537 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Counter Readings | General Comments | | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Readings | General Comments | | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Readings | LTC Totalizer Reading | 1286.40 | kw |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Readings | Totalizer Meter Reading | .2680 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BCH001178 | Charger | 823-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BCH001178 | Charger | 823-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BCH001178 | Charger | 823-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BCH001178 | Charger | 823-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.2 | amps |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BCH001178 | Charger | 823-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BCH001178 | Charger | 823-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BCH001178 | Charger | 823-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | General Comments | | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | General Comments | | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | General Comments | | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | LTCC000856 | LTCControl | 823-1 | LTC Control Insp | All Connections OK? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | LTCC000856 | LTCControl | 823-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | LTCC000856 | LTCControl | 823-1 | LTC Control Insp | General Comments | | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | LTCC000856 | LTCControl | 823-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | LTCC000856 | LTCControl | 823-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | LTCC000856 | LTCControl | 823-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | LTCC000856 | LTCControl | 823-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | LTCC000856 | LTCControl | 823-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | LTCC000856 | LTCControl | 823-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Maintenance Operations | 0 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | General Comments | | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | 9 Month Operations VCB New | 25 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Fault Adjusted Amps A Phase V | 3.31 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | 9 Month Operations | 27 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Fault Operations Ground | 0 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Follow-up Action Required? | n | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Amps C Ø | 30.0 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Amps B Ø | 35.0 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Amps A Ø | 30.0 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Unknown Operations | 0 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Operations Counter AF | 176 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Switching Operations | 0 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Operations This Read Vac | 2 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Operations Counter AL | 176 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Fault Operations A Ø | 2 | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | General Comments | | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/10/2023 11:27 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Patrol Inspection | General Comments | | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Unknown Operations | 0 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Switching Operations | 0 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | 9 Month Operations | 14 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Operations This Read Vac | 12 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Amps A Ø | 35.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Amps B Ø | 30.0 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Amps C Ø | 60.0 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Fault Adjusted Amps A Phase V | 19.25 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Fault Adjusted Amps B Phase V | 19.25 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Fault Adjusted Amps C Phase V | 19.25 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Operations Counter AL | 195 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Operations Counter AF | 195 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Fault Operations A Ø | 4 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Fault Operations B Ø | 4 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Fault Operations C Ø | 4 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Fault Operations Ground | 0 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Follow-up Action Required? | n | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | General Comments | | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Maintenance Operations | 0 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Patrol Inspection | General Comments | | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Unknown Operations | 0 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Switching Operations | 0 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Operations This Read Vac | 0 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Operations Counter AL | 195 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Operations Counter AF | 195 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Amps B Ø | 115.0 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Amps C Ø | 110.0 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Amps A Ø | 130.0 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | 9 Month Operations | 2 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Maintenance Operations | 0 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | General Comments | | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Follow-up Action Required? | n | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Fault Operations Ground | 0 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Patrol Inspection | General Comments | | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Amps B Ø | 35.0 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Operations Counter AF | 218 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Maintenance Operations | 0 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Unknown Operations | 0 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Switching Operations | 0 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Operations This Read Vac | 9 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | General Comments | | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Follow-up Action Required? | n | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Fault Operations Ground | 0 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | 9 Month Operations | 11 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Amps C Ø | 25.0 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Fault Adjusted Amps A Phase V | 14.43 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Fault Operations C Ø | 3 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Amps A Ø | 25.0 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Fault Operations B Ø | 3 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Fault Adjusted Amps B Phase V | 14.43 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Fault Adjusted Amps C Phase V | 14.43 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Operations Counter AL | 218 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Fault Operations A Ø | 3 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Readings | Totalizer Meter Reading | .7870 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Readings | General Comments | | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Readings | LTC Totalizer Reading | 7555.20 | kw |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Counter Readings | LTC As Left Counter | 41585 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Counter Readings | LTC As Found Counter | 41585 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Counter Readings | General Comments | | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Counter Readings | LTC Operations Since Last Insp | 472 | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | LTCC000079 | LTCControl | 832-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | LTCC000079 | LTCControl | 832-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | LTCC000079 | LTCControl | 832-1 | LTC Control Insp | All Connections OK? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | LTCC000079 | LTCControl | 832-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | LTCC000079 | LTCControl | 832-1 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | LTCC000079 | LTCControl | 832-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | LTCC000079 | LTCControl | 832-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | LTCC000079 | LTCControl | 832-1 | LTC Control Insp | General Comments | | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | LTCC000079 | LTCControl | 832-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BCH001561 | Charger | 832-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BCH001561 | Charger | 832-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BCH001561 | Charger | 832-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BCH001561 | Charger | 832-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.0 | amps |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BCH001561 | Charger | 832-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BCH001561 | Charger | 832-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BCH001561 | Charger | 832-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BCH001561 | Charger | 832-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 55 | °F |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | Bat Volt 1Min After Chgr Trip | 49.2 | VDC |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | General Comments | | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | General Comments | | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | YD000351 | Yard | 832-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | YD000351 | Yard | 832-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | YD000351 | Yard | 832-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | YD000351 | Yard | 832-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | YD000351 | Yard | 832-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | YD000351 | Yard | 832-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | YD000351 | Yard | 832-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | YD000351 | Yard | 832-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | YD000351 | Yard | 832-Yard | Yard Patrol Inspection | General Comments | | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | YD000351 | Yard | 832-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | YD000351 | Yard | 832-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | YD000351 | Yard | 832-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/10/2023 11:20 | Distribution | Donerail Quarterly Inspection | YD000351 | Yard | 832-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 55 | °C |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 35 | °C |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 50 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 40 | °C |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 50 | °C |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 35 | °C |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Accumulated Fault Duty A Ph V | 2.39 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | 9 Month Operations | 1 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | General Comments | | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Fault Operations A Ø | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Fault Operations B Ø | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Fault Operations C Ø | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | 9 Month Operations | 6 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Fault Operations Ground | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Amps A Ø | 0.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Amps B Ø | 0.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Amps C Ø | 0.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Fault Operations A Ø | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Fault Operations B Ø | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Fault Operations C Ø | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Fault Operations Ground | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | General Comments | | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Maintenance Operations | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Maintenance Operations | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Operations Counter AF | 11 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Operations Counter AL | 11 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | General Comments | | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Maintenance Operations | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | 9 Month Operations | 20 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Unknown Operations | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Switching Operations | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Operations This Read Vac | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Operations Counter AF | 588 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Operations Counter AL | 588 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Maintenance Operations | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Operations Counter AF | 270 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Operations Counter AL | 270 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | General Comments | | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Amps A Ø | 97.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Amps B Ø | 100.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Amps C Ø | 98.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Fault Adjusted Amps A Phase V | 11.18 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Accumulated Fault Duty C Ph V | 43.68 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Amps A Ø | 202.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Accumulated Fault Duty B Ph V | 71.99 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Accumulated Fault Duty A Ph V | 76.04 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Fault Operations A Ø | 1 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | 9 Month Operations | 3 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Fault Operations B Ø | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Fault Operations C Ø | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | 9 Month Operations | 10 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Operations This Read Vac | 8 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Switching Operations | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Unknown Operations | 6 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Fault Operations Ground | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | General Comments | | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Amps B Ø | 195.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Amps C Ø | 392.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Amps B Ø | 358.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Amps A Ø | 361.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 1.93 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Accumulated Fault Duty C Ph V | 2.39 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Amps C Ø | 220.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Accumulated Fault Duty B Ph V | 2.39 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 1.93 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 1.93 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Accumulated Fault Duty A Ph V | 43.84 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Accumulated Fault Duty B Ph V | 34.28 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Accumulated Fault Duty C Ph V | 22.32 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Amps A Ø | 136.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Amps B Ø | 149.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Amps C Ø | 147.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Operations This Read Vac | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | 9 Month Operations | 9 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Fault Adjusted Amps A Phase V | 67.08 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | General Comments | | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Fault Operations Ground | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Fault Operations C Ø | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Operations Counter AL | 151 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Maintenance Operations | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Operations Counter AF | 28 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Operations Counter AL | 28 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Accumulated Fault Duty A Ph V | .8 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Operations This Read Vac | 4 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | 9 Month Operations | 1 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Operations Counter AF | 151 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Maintenance Operations | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | General Comments | | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Accumulated Fault Duty B Ph V | .8 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Fault Operations B Ø | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Accumulated Fault Duty C Ph V | .8 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Switching Operations | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Amps A Ø | 52.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Fault Adjusted Amps B Phase V | 67.08 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Fault Adjusted Amps C Phase V | 89.44 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Fault Operations A Ø | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Fault Operations B Ø | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Fault Operations C Ø | 2 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Fault Operations A Ø | 2 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Fault Adjusted Amps C Phase V | 22.36 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Fault Adjusted Amps B Phase V | 22.36 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Amps B Ø | 48.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Operations Counter AL | 152 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Fault Adjusted Amps A Phase V | 44.72 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Switching Operations | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Unknown Operations | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Fault Operations Ground | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Amps C Ø | 57.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Amps B Ø | 58.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Amps A Ø | 54.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | 9 Month Operations VCB New | 16 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Fault Operations Ground | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Operations Counter AF | 152 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Switching Operations | 1 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Operations This Read Vac | 1 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Operations Counter AL | 295 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Operations Counter AF | 295 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Unknown Operations | 2 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Unknown Operations | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Amps C Ø | 49.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Fault Operations C Ø | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Switching Operations | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Unknown Operations | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Switching Operations | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Operations This Read Vac | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Fault Operations B Ø | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Operations This Read Vac | 1 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 316714 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 296841 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.7 | volts |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 284850 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Readings | General Comments | | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 565.92 | kw |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 335.00 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Readings | Oil Temp Max | 54 | °C |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Readings | Oil Temp Present | 39 | °C |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 3600 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .1572 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | n | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Broken skirts | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Readings | General Comments | | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Readings | Oil Temp Max | 36 | °C |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Readings | General Comments | | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 470.16 | kw |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Readings | Oil Temp Present | 32 | °C |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Readings | Totalizer Meter Reading | .3918 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Readings | General Comments | | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Readings | Oil Temp Max | 39 | °C |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | 9 Month Operations | 1 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Amps A Ø | 47.0 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Amps B Ø | 47.0 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Amps C Ø | 46.0 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Operations This Read Vac | 0 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Operations Counter AL | 184 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Operations Counter AF | 184 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | General Comments | | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 322 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 14.6 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 210 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 19.1 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 262 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 16.6 | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BAT001654 | Battery | 426-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BAT001654 | Battery | 426-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BAT001654 | Battery | 426-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BAT001654 | Battery | 426-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BAT001654 | Battery | 426-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BAT001654 | Battery | 426-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BAT001654 | Battery | 426-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BAT001654 | Battery | 426-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BAT001654 | Battery | 426-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.5 | VDC |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BAT001654 | Battery | 426-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BAT001654 | Battery | 426-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BAT001654 | Battery | 426-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BAT001654 | Battery | 426-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.5 | VDC |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BCH001572 | Charger | 426-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BCH001572 | Charger | 426-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BCH001572 | Charger | 426-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .700 | millivolts |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BCH001572 | Charger | 426-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .4 | amps |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BCH001572 | Charger | 426-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BCH001572 | Charger | 426-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BCH001572 | Charger | 426-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | BCH001572 | Charger | 426-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | General Comments | | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | General Comments | | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | YD000261 | Yard | 426-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | YD000261 | Yard | 426-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | YD000261 | Yard | 426-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | YD000261 | Yard | 426-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | YD000261 | Yard | 426-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | YD000261 | Yard | 426-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | YD000261 | Yard | 426-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | YD000261 | Yard | 426-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | YD000261 | Yard | 426-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | YD000261 | Yard | 426-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | YD000261 | Yard | 426-Yard | Yard Patrol Inspection | General Comments | Back left corner washout under fence | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | YD000261 | Yard | 426-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | n | |
| 4/7/2023 14:23 | Distribution | Fredonia Quarry Quarterly Inspection | YD000261 | Yard | 426-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Max Tap Position | 7L | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Current Tap Position | 10L | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 69248 | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Current Tap Position | 11L | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Max Tap Position | 5L | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 118862 | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 118219 | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Current Tap Position | 10L | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Min Tap Position | 11L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Max Tap Position | 7L | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Readings | General Comments | | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 0.00 | kw |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Readings | Oil Temp Max | 65 | °C |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Readings | Oil Temp Present | 60 | °C |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 0 | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | 9 Month Operations | 1 | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Amps A Ø | 80.0 | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Amps B Ø | 80.0 | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Amps C Ø | 100.0 | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | General Comments | 1-TC | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Maintenance Operations | 1 | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Operations Counter AF | 141 | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Operations Counter AL | 141 | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Operations This Read Vac | 1 | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | BCH001571 | Charger | 616-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | BCH001571 | Charger | 616-Battery Charger | Battery Charger Patrol Insp | General Comments | float voltage entry error | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | BCH001571 | Charger | 616-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | BCH001571 | Charger | 616-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | BCH001571 | Charger | 616-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 0.0 | amps |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | BCH001571 | Charger | 616-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | BCH001571 | Charger | 616-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | BCH001571 | Charger | 616-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | BAT001653 | Battery | 616-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.3 | VDC |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | BAT001653 | Battery | 616-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | BAT001653 | Battery | 616-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | BAT001653 | Battery | 616-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | BAT001653 | Battery | 616-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | BAT001653 | Battery | 616-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | BAT001653 | Battery | 616-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | BAT001653 | Battery | 616-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | BAT001653 | Battery | 616-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | BAT001653 | Battery | 616-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | BAT001653 | Battery | 616-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | BAT001653 | Battery | 616-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.3 | VDC |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | General Comments | | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | General Comments | | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | General Comments | | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/7/2023 14:12 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | BAT001406 | Battery | 822-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | BAT001406 | Battery | 822-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | BAT001406 | Battery | 822-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | BAT001406 | Battery | 822-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | BAT001406 | Battery | 822-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | BAT001406 | Battery | 822-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | BAT001406 | Battery | 822-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | BAT001406 | Battery | 822-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | BAT001406 | Battery | 822-Battery Bank | Battery Patrol Inspection | Negative DC Ground | .2 | VDC |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | BAT001406 | Battery | 822-Battery Bank | Battery Patrol Inspection | Positive DC Ground | .2 | VDC |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | BAT001406 | Battery | 822-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | BAT001406 | Battery | 822-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | BCH000453 | Charger | 822-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.3 | VDC |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | BCH000453 | Charger | 822-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | BCH000453 | Charger | 822-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 61147 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | General Comments | lower arm will not reset | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.0 | volts |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 50027 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Max Tap Position | 10R | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | General Comments | lower arm will not reset | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 70844 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .4008 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Readings | Oil Temp Max | 42 | °C |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 961.92 | kw |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Readings | General Comments | | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | WX0177 | RecloserHydraulic | 822-1515 | Recloser Hydraulic Patrol Inspection | General Comments | 2 ops | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | WX0177 | RecloserHydraulic | 822-1515 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | WX0177 | RecloserHydraulic | 822-1515 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | WX0177 | RecloserHydraulic | 822-1515 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | WX0177 | RecloserHydraulic | 822-1515 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | WX0177 | RecloserHydraulic | 822-1515 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | WX0177 | RecloserHydraulic | 822-1515 | Recloser Hydraulic Patrol Inspection | Operations Counter | 262 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | WX0177 | RecloserHydraulic | 822-1515 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 10.6 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | WX0177 | RecloserHydraulic | 822-1515 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 15.5 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | WX0177 | RecloserHydraulic | 822-1515 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 8.0 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | WX0177 | RecloserHydraulic | 822-1515 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | WX0177 | RecloserHydraulic | 822-1515 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | WX0177 | RecloserHydraulic | 822-1515 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Unknown Operations | 1 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Operations This Read Vac | 2 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Operations Counter AL | 163 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Operations Counter AF | 163 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Maintenance Operations | 1 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Fault Adjusted Amps C Phase V | 2.41 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Fault Adjusted Amps B Phase V | 2.41 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Fault Adjusted Amps A Phase V | 2.41 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Amps C Ø | 30.0 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Amps B Ø | 30.0 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Amps A Ø | 30.0 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | 9 Month Operations | 2 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | General Comments | | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | General Comments | insulator skirts cracked | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | General Comments | | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | Ambient Temp | 57 | °F |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | General Comments | | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/7/2023 13:40 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BCH001609 | Charger | 453-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BCH001609 | Charger | 453-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BCH001609 | Charger | 453-Battery Charger | Battery Charger Patrol Insp | General Comments | float voltage entry shows an error for any voltage | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BCH001609 | Charger | 453-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BCH001609 | Charger | 453-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BCH001609 | Charger | 453-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .4 | amps |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BCH001609 | Charger | 453-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BAT001663 | Battery | 453-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BAT001663 | Battery | 453-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BAT001663 | Battery | 453-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.3 | VDC |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BAT001663 | Battery | 453-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.3 | VDC |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BAT001663 | Battery | 453-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BAT001663 | Battery | 453-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BAT001663 | Battery | 453-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BAT001663 | Battery | 453-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BAT001663 | Battery | 453-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BAT001663 | Battery | 453-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BAT001663 | Battery | 453-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BAT001663 | Battery | 453-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BCH000422 | Charger | Retired Distribution | Battery Charger Patrol Insp | General Comments | removed from service | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BCH000422 | Charger | Retired Distribution | Battery Charger Patrol Insp | Follow-up Action Required? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BCH000422 | Charger | Retired Distribution | Battery Charger Patrol Insp | As Left Float Voltage | 0.0 | VDC |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 191416 | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Max Tap Position | 6L | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Current Tap Position | 10L | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Current Tap Position | 14L | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Max Tap Position | 7L | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 26409 | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Max Tap Position | 4L | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Current Tap Position | 11L | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Max Tap Position | 7L | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Min Tap Position | 13L | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 30837 | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 0 | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 300.00 | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 0.00 | kw |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Readings | General Comments | | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.7 | volts |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 324.17 | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Operations This Read Vac | 2 | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Operations Counter AL | 180 | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Operations Counter AF | 180 | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Maintenance Operations | 1 | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | General Comments | 1 C-N, 1- TC | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Fault Operations C Ø | 1 | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Fault Adjusted Amps C Phase V | 9.87 | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Amps C Ø | 89.0 | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Amps B Ø | 93.0 | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Amps A Ø | 115.0 | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | 9 Month Operations | 3 | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Readings | General Comments | | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 528.00 | kw |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .6600 | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Readings | Oil Temp Max | 51 | °C |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 800 | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 97.50 | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | General Comments | | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | X0080 | RecloserHydraulic | 440-1709 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | X0080 | RecloserHydraulic | 440-1709 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | X0080 | RecloserHydraulic | 440-1709 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | X0080 | RecloserHydraulic | 440-1709 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 30.5 | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | X0080 | RecloserHydraulic | 440-1709 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 16.8 | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | X0080 | RecloserHydraulic | 440-1709 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 12.0 | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | X0080 | RecloserHydraulic | 440-1709 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | X0080 | RecloserHydraulic | 440-1709 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | X0080 | RecloserHydraulic | 440-1709 | Recloser Hydraulic Patrol Inspection | Operations Counter | 439 | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | X0080 | RecloserHydraulic | 440-1709 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | X0080 | RecloserHydraulic | 440-1709 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | X0080 | RecloserHydraulic | 440-1709 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | X0080 | RecloserHydraulic | 440-1709 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | General Comments | | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | WX0332 | RecloserHydraulic | 440-1708 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 21.3 | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | WX0332 | RecloserHydraulic | 440-1708 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 34.7 | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | WX0332 | RecloserHydraulic | 440-1708 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 23.7 | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | WX0332 | RecloserHydraulic | 440-1708 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | WX0332 | RecloserHydraulic | 440-1708 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | WX0332 | RecloserHydraulic | 440-1708 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | WX0332 | RecloserHydraulic | 440-1708 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | WX0332 | RecloserHydraulic | 440-1708 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | WX0332 | RecloserHydraulic | 440-1708 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | WX0332 | RecloserHydraulic | 440-1708 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | WX0332 | RecloserHydraulic | 440-1708 | Recloser Hydraulic Patrol Inspection | Operations Counter | 487 | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | WX0332 | RecloserHydraulic | 440-1708 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | WX0332 | RecloserHydraulic | 440-1708 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | General Comments | | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/7/2023 13:27 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | Ambient Temp | 59 | °F |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | General Comments | Whole station needs wildlife protection and fiberglass is exposed on all xfmr fuse barrels including spare. | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | General Comments | | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | YD000259 | Yard | 440-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | YD000259 | Yard | 440-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | YD000259 | Yard | 440-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | YD000259 | Yard | 440-Yard | Yard Patrol Inspection | General Comments | | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | YD000259 | Yard | 440-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | YD000259 | Yard | 440-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | YD000259 | Yard | 440-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | YD000259 | Yard | 440-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | YD000259 | Yard | 440-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | YD000259 | Yard | 440-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | YD000259 | Yard | 440-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | YD000259 | Yard | 440-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/7/2023 13:25 | Distribution | Mexico Quarterly Inspection | YD000259 | Yard | 440-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | General Comments | | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 0.00 | kw |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Readings | Oil Temp Present | 28 | °C |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Readings | Oil Temp Max | 44 | °C |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Readings | General Comments | | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | BAT001440 | Battery | 362-1 Battery Bank 1 | Battery Patrol Inspection | General Comments | | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | BAT001440 | Battery | 362-1 Battery Bank 1 | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | BAT001440 | Battery | 362-1 Battery Bank 1 | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | BAT001440 | Battery | 362-1 Battery Bank 1 | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | BAT001440 | Battery | 362-1 Battery Bank 1 | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | BAT001440 | Battery | 362-1 Battery Bank 1 | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | BAT001440 | Battery | 362-1 Battery Bank 1 | Battery Patrol Inspection | All Connections OK? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | BAT001440 | Battery | 362-1 Battery Bank 1 | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | BAT001440 | Battery | 362-1 Battery Bank 1 | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | BCH000800 | Charger | 362-1 Charger 1 | Battery Charger Patrol Insp | General Comments | | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | BCH000800 | Charger | 362-1 Charger 1 | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | BCH000800 | Charger | 362-1 Charger 1 | Battery Charger Patrol Insp | As Found Float Voltage | 52.7 | VDC |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | General Comments | | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | 9 Month Operations | 0 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Amps A Ø | 0.0 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Amps B Ø | 0.0 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Amps C Ø | 0.0 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Operations Counter AF | 264 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Operations Counter AL | 264 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Operations This Read Vac | 0 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 122.8 | volts |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 48954 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.4 | volts |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 46846 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 47251 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 122.9 | volts |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Min Tap Position | 4L | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | General Comments | counter inoperable | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Current Tap Position | 3R | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | General Comments | counter inoperable | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Current Tap Position | 4R | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Readings | General Comments | | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 78.80 | kw |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 200 | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Readings | Totalizer Meter Reading | .3940 | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Platform/Walkway/Railing OK? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | General Comments | | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | General Comments | | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/7/2023 12:52 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Ambient Temp | 58 | °F |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | General Comments | | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Switching Operations | 1 | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Operations This Read Vac | 1 | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Operations Counter AL | 252 | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | 9 Month Operations | 1 | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Amps C Ø | 37.0 | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Amps B Ø | 44.0 | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Amps A Ø | 34.0 | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Operations Counter AF | 252 | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | General Comments | | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Readings | Winding Temp Present | 40 | °C |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Readings | Winding Temp Max | 60 | °C |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Readings | Top Oil Temperature Present | 30 | °C |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Readings | Top Oil Temperature Max | 35 | °C |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 100.00 | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Readings | General Comments | | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 105.00 | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1650 | psi |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 12:46 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | General Comments | | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 105.00 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Readings | General Comments | | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 100.00 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .0006 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1600 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | .96 | kw |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Readings | General Comments | | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Operations This Read Vac | 0 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Operations Counter AL | 323 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Operations Counter AF | 323 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | General Comments | | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | 9 Month Operations | 0 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Amps A Ø | 0.0 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Amps B Ø | 0.0 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Amps C Ø | 0.0 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | BCH000801 | Charger | 362-2 Charger 2 | Battery Charger Patrol Insp | General Comments | | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | BCH000801 | Charger | 362-2 Charger 2 | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | BCH000801 | Charger | 362-2 Charger 2 | Battery Charger Patrol Insp | As Found Float Voltage | 52.0 | VDC |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | BAT001441 | Battery | 362-2 Battery Bank 2 | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | BAT001441 | Battery | 362-2 Battery Bank 2 | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | BAT001441 | Battery | 362-2 Battery Bank 2 | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | BAT001441 | Battery | 362-2 Battery Bank 2 | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | BAT001441 | Battery | 362-2 Battery Bank 2 | Battery Patrol Inspection | All Connections OK? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | BAT001441 | Battery | 362-2 Battery Bank 2 | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | BAT001441 | Battery | 362-2 Battery Bank 2 | Battery Patrol Inspection | General Comments | | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | BAT001441 | Battery | 362-2 Battery Bank 2 | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | BAT001441 | Battery | 362-2 Battery Bank 2 | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.7 | volts |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 69334 | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 62443 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.8 | volts |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 65643 | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Readings | Oil Temp Present | 23 | °C |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .7032 | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Readings | Oil Temp Max | 39 | °C |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 135.00 | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Readings | General Comments | | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1687.68 | kw |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | General Comments | H1 and H3 bushings are pretty badly broken | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.5 | psi |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 145.00 | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 1220 | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 806 | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 12.4 | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 18.5 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 14.2 | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 882 | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | Operations Counter | 0 | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 197 | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 210 | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 13.1 | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 11.5 | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 7.0 | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 180 | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 276 | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 18.9 | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 249 | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 4.0 | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 21.7 | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 201 | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | General Comments | Fuses are Frayed | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | General Comments | | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | General Comments | | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/7/2023 12:32 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | Ambient Temp | 57 | °F |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | PF000172 | PowerFuse | HB-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | PF000172 | PowerFuse | HB-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | PF000171 | PowerFuse | HB-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | PF000171 | PowerFuse | HB-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1336 | BreakerVacuum | HB-Sec 1 Spare Vac Bkr | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1336 | BreakerVacuum | HB-Sec 1 Spare Vac Bkr | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1336 | BreakerVacuum | HB-Sec 1 Spare Vac Bkr | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Operations Counter AF | 131 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Operations Counter AL | 131 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Amps B Ø | 672.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Amps A Ø | 654.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | 9 Month Operations | 2 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Amps C Ø | 649.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | PF000173 | PowerFuse | HB-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | PF000173 | PowerFuse | HB-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | PF000170 | PowerFuse | HB-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | PF000170 | PowerFuse | HB-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LTCC000038 | LTCControl | HB-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LTCC000038 | LTCControl | HB-TRANS 2 | LTC Control Insp | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LTCC000038 | LTCControl | HB-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LTCC000038 | LTCControl | HB-TRANS 2 | LTC Control Insp | All Connections OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 33805 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 16L | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 6L | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 33805 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Counter Readings | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 134 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 55 | °C |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 40 | °C |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 45 | °C |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 55 | °C |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 45 | °C |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 50 | °C |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | FAULT LIGHT ON LTC | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LTCC000573 | LTCControl | HB-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LTCC000573 | LTCControl | HB-TRANS 1 | LTC Control Insp | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LTCC000573 | LTCControl | HB-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LTCC000573 | LTCControl | HB-TRANS 1 | LTC Control Insp | All Connections OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 225 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 16L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 31746 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 31746 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Counter Readings | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 60 | °C |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 45 | °C |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 65 | °C |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 40 | °C |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 55 | °C |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 45 | °C |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 58 | °C |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Operations Counter AL | 70 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Operations This Read Vac | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Operations Counter AF | 70 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | 9 Month Operations | 2 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Amps A Ø | 171.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Amps B Ø | 142.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Amps C Ø | 167.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | 9 Month Operations | 3 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Amps A Ø | 196.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Amps B Ø | 208.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Amps C Ø | 171.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Fault Adjusted Amps A Phase V | 11.18 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Fault Adjusted Amps B Phase V | 11.18 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Fault Operations B Ø | 1 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Operations Counter AF | 223 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Operations Counter AL | 223 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Operations This Read Vac | 2 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | 9 Month Operations | 11 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | 9 Month Operations VCB New | 11 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Amps A Ø | 125.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Amps B Ø | 130.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Amps C Ø | 122.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Operations This Read Vac | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Operations Counter AL | 205 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Operations Counter AF | 205 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Amps B Ø | 138.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Amps A Ø | 93.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Operations This Read Vac | 5 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Operations Counter AL | 263 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Operations Counter AF | 263 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | 9 Month Operations | 47 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | 9 Month Operations VCB New | 42 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Amps C Ø | 145.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Fault Adjusted Amps A Phase V | 22.36 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Fault Adjusted Amps B Phase V | 33.54 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Fault Operations A Ø | 2 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Fault Operations B Ø | 3 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Amps C Ø | 17.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Amps B Ø | 21.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Amps A Ø | 20.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | 9 Month Operations | 2 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Operations Counter AF | 179 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Operations Counter AL | 179 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Switching Operations | 1 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Operations This Read Vac | 1 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | 9 Month Operations | 9 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Operations Counter AF | 165 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Amps A Ø | 0.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Operations Counter AL | 165 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Amps C Ø | 0.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Amps B Ø | 0.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Panels Dusted? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Restroom Clean & OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Ambient Temp | 40 | °F |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Amps C Ø | 91.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Amps B Ø | 95.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Amps A Ø | 90.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Operations This Read Vac | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | 9 Month Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Operations Counter AF | 12 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Operations Counter AL | 12 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Operations Counter AL | 24 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Operations Counter AF | 24 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | 9 Month Operations | 5 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Operations This Read Vac | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Amps A Ø | 105.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Amps B Ø | 95.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Amps C Ø | 82.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Operations Counter AF | 31 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Operations Counter AL | 31 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Operations This Read Vac | 9 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Unknown Operations | 9 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | 9 Month Operations | 9 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Fault Adjusted Amps C Phase V | 100.62 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Fault Adjusted Amps B Phase V | 100.62 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Fault Adjusted Amps A Phase V | 100.62 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Amps A Ø | 134.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Amps C Ø | 125.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Amps B Ø | 133.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Unknown Operations | 10 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Operations This Read Vac | 12 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Operations Counter AL | 42 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Operations Counter AF | 42 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | 9 Month Operations | 14 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Fault Operations B Ø | 2 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Fault Adjusted Amps C Phase V | 111.80 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Fault Adjusted Amps B Phase V | 134.16 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Fault Adjusted Amps A Phase V | 111.80 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Amps C Ø | 118.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Amps B Ø | 127.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Amps A Ø | 115.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Operations Counter AF | 19 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Operations Counter AL | 19 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Operations This Read Vac | 1 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | 9 Month Operations | 1 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Amps A Ø | 173.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Amps B Ø | 173.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Amps C Ø | 164.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Fault Adjusted Amps A Phase V | 11.18 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Amps C Ø | 625.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Amps B Ø | 649.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Operations This Read Vac | 1 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Switching Operations | 1 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Operations Counter AL | 14 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Operations Counter AF | 14 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Amps A Ø | 632.0 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | 9 Month Operations | 3 | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 12:05 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | General Comments | | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | YD000798 | Yard | 362-2 Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | YD000798 | Yard | 362-2 Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | YD000798 | Yard | 362-2 Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | YD000798 | Yard | 362-2 Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | YD000798 | Yard | 362-2 Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | YD000798 | Yard | 362-2 Yard | Yard Patrol Inspection | Clear of Trash? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | YD000798 | Yard | 362-2 Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | YD000798 | Yard | 362-2 Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | YD000798 | Yard | 362-2 Yard | Yard Patrol Inspection | Ambient Temp | 43 | °F |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | YD000798 | Yard | 362-2 Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | YD000798 | Yard | 362-2 Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | YD000798 | Yard | 362-2 Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | YD000798 | Yard | 362-2 Yard | Yard Patrol Inspection | General Comments | | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | General Comments | Brush needs cut back to 5' of clearance | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | YD000078 | Yard | 362-Yard | Yard Patrol Inspection | Ambient Temp | 43 | °F |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | YD000078 | Yard | 362-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | YD000078 | Yard | 362-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | YD000078 | Yard | 362-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | YD000078 | Yard | 362-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | YD000078 | Yard | 362-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | YD000078 | Yard | 362-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | YD000078 | Yard | 362-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | YD000078 | Yard | 362-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | YD000078 | Yard | 362-Yard | Yard Patrol Inspection | General Comments | | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | YD000078 | Yard | 362-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/7/2023 15:29 | Distribution | Guest River Quarterly Inspection | YD000078 | Yard | 362-Yard | Yard Patrol Inspection | Vegetation | None | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | 9 Month Operations | 10 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Amps A Ø | 10.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Amps B Ø | 9.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Amps C Ø | 8.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Fault Operations A Ø | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Fault Operations B Ø | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Fault Operations C Ø | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Fault Operations Ground | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | General Comments | | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Maintenance Operations | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Operations Counter AF | 106 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Operations Counter AL | 106 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Operations This Read Vac | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Switching Operations | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Unknown Operations | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations | 16 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations VCB New | 12 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Unknown Operations | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Switching Operations | 4 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Operations This Read Vac | 4 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AL | 43 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations Ground | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Amps A Ø | 0.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Amps B Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AF | 43 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Maintenance Operations | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | General Comments | | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Amps C Ø | 0.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Operations Counter AF | 27 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | General Comments | | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 81.00 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Operations Counter AL | 27 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Operations This Read Vac | 3 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | 9 Month Operations | 12 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Unknown Operations | 3 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Amps A Ø | 157.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Amps B Ø | 150.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Amps C Ø | 135.0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 81.00 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 81.00 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | PF000268 | PowerFuse | OX-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | PF000268 | PowerFuse | OX-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | PF000269 | PowerFuse | OX-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | PF000269 | PowerFuse | OX-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LTCC000215 | LTCControl | OX-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LTCC000215 | LTCControl | OX-TRANS 2 | LTC Control Insp | General Comments | | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LTCC000215 | LTCControl | OX-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LTCC000215 | LTCControl | OX-TRANS 2 | LTC Control Insp | All Connections OK? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | FILTER NEEDS ATTEN..... | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 349 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 105074 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 105074 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Counter Readings | General Comments | | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 25 | °C |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 30 | °C |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 45 | °C |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 30 | °C |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 45 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 45 | °C |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 500 | psi |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Patrol Inspection | General Comments | | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Patrol Inspection | General Comments | | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Patrol Inspection | General Comments | | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Patrol Inspection | General Comments | | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Patrol Inspection | General Comments | OK | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | PF000267 | PowerFuse | OX-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | PF000267 | PowerFuse | OX-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | PF000266 | PowerFuse | OX-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | PF000266 | PowerFuse | OX-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | HEATER NOT WORKING | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LTCC000281 | LTCControl | OX-TRANS 1 | LTC Control Insp | All Connections OK? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LTCC000281 | LTCControl | OX-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LTCC000281 | LTCControl | OX-TRANS 1 | LTC Control Insp | General Comments | | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LTCC000281 | LTCControl | OX-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 214078 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 214078 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 459 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Counter Readings | General Comments | | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Operations This Read Vac | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Amps C Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Amps B Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Amps A Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | 9 Month Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Operations Counter AF | 337 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Operations Counter AL | 337 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Amps A Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Amps B Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | 9 Month Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Switching Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Operations This Read Vac | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Operations Counter AL | 364 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Amps C Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Operations Counter AF | 364 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Unknown Operations | 1 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Operations This Read Vac | 1 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Operations Counter AL | 44 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Operations Counter AF | 44 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Amps A Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Amps B Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Amps C Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Fault Adjusted Amps C Phase V | 27.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Fault Adjusted Amps B Phase V | 27.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Fault Adjusted Amps A Phase V | 27.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | 9 Month Operations | 2 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Amps C Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Amps B Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Amps A Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Operations Counter AF | 52 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Operations Counter AL | 52 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Operations This Read Vac | 23 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Switching Operations | 23 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | 9 Month Operations | 23 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Operations This Read Vac | 7 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Switching Operations | 7 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | 9 Month Operations | 9 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Operations Counter AF | 89 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Operations Counter AL | 89 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Amps A Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Amps B Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Amps C Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Operations Counter AF | 75 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Operations Counter AL | 75 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Operations This Read Vac | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | 9 Month Operations | 3 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Amps A Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Amps B Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Amps C Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Amps C Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Amps B Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Amps A Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | 9 Month Operations | 8 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Switching Operations | 7 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Operations This Read Vac | 7 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Operations Counter AL | 31 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Operations Counter AF | 31 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | 9 Month Operations | 3 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Amps A Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Amps B Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Operations Counter AF | 24 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Operations Counter AL | 24 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Amps C Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Operations This Read Vac | 3 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Switching Operations | 3 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BCH001203 | Charger | BR-Battery Charger 48V | Battery Charger Patrol Insp | Battery Charger Current | 10.8 | amps |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BCH001203 | Charger | BR-Battery Charger 48V | Battery Charger Patrol Insp | As Left Float Voltage | 54.0 | VDC |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BCH001203 | Charger | BR-Battery Charger 48V | Battery Charger Patrol Insp | As Found Float Voltage | 54.0 | VDC |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BCH001203 | Charger | BR-Battery Charger 48V | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BCH001203 | Charger | BR-Battery Charger 48V | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BCH001203 | Charger | BR-Battery Charger 48V | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BCH001203 | Charger | BR-Battery Charger 48V | Battery Charger Patrol Insp | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Operations Counter AF | 56 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Operations Counter AL | 56 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Operations This Read Vac | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | 9 Month Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Amps A Ø | 392.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Amps B Ø | 431.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Amps C Ø | 424.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Amps C Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Amps A Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Amps B Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Operations Counter AF | 54 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | 9 Month Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Operations Counter AL | 54 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Operations This Read Vac | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Amps A Ø | 14.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Amps B Ø | 13.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Amps C Ø | 17.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | 9 Month Operations | 2 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Operations This Read Vac | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Operations Counter AL | 17 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Operations Counter AF | 17 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Fault Operations Ground | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Operations This Read Vac | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Operations Counter AL | 54 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Operations Counter AF | 54 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Amps C Ø | 130.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Amps B Ø | 125.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Amps A Ø | 108.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | 9 Month Operations | 2 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | 9 Month Operations | 9 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Amps A Ø | 282.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Amps B Ø | 306.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Amps C Ø | 280.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Operations Counter AF | 52 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Operations Counter AL | 52 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Operations This Read Vac | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Fault Operations B Ø | 0 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Foundation Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | General Comments | OK | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Grounds in Place? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Operations This Read Vac | 1 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Operations Counter AL | 91 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Switching Operations | 1 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Amps A Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Operations Counter AF | 91 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Amps B Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Amps C Ø | 0.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | 9 Month Operations | 3 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Bushing Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Grounds in Place? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | General Comments | OK | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Foundation Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Grounds in Place? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | General Comments | OK | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Foundation Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Bushing Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Operations This Read Vac | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Operations Counter AL | 69 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Operations Counter AF | 69 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Amps C Ø | 403.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Amps B Ø | 451.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Amps A Ø | 454.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | 9 Month Operations | 1 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | General Comments | OK | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Unknown Operations | 4 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Operations This Read Vac | 4 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Operations Counter AL | 140 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Operations Counter AF | 140 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Fault Adjusted Amps C Phase V | 44.72 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Fault Adjusted Amps B Phase V | 44.72 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | 9 Month Operations | 4 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Amps A Ø | 106.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Amps B Ø | 84.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Amps C Ø | 127.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Fault Adjusted Amps A Phase V | 44.72 | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | General Comments | OK | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | Bushing Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | Grounds in Place? | y | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | Foundation Condition | Good | |
| 6/1/2023 7:38 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | General Comments | OK | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Unknown Operations | 1 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Operations This Read Vac | 1 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Amps A Ø | 200.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Amps B Ø | 183.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Amps C Ø | 189.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Fault Adjusted Amps A Phase V | 11.18 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Operations Counter AF | 54 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Fault Adjusted Amps B Phase V | 11.18 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Fault Adjusted Amps C Phase V | 11.18 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Operations Counter AL | 54 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | 9 Month Operations | 1 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Amps A Ø | 178.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Amps B Ø | 160.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Amps C Ø | 149.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Fault Adjusted Amps A Phase V | 22.36 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Fault Adjusted Amps B Phase V | 22.36 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Fault Adjusted Amps C Phase V | 22.36 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | 9 Month Operations | 2 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Operations Counter AF | 144 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Operations Counter AL | 144 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Operations This Read Vac | 2 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Unknown Operations | 2 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | 9 Month Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Operations Counter AL | 180 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Operations Counter AF | 180 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Amps A Ø | 204.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Amps B Ø | 193.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Amps C Ø | 196.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Operations Counter AL | 143 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Operations Counter AF | 143 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Amps A Ø | 208.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Amps C Ø | 203.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | 9 Month Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Amps B Ø | 196.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Switching Operations | 2 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Operations This Read Vac | 2 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Operations Counter AL | 230 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Operations Counter AF | 230 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | 9 Month Operations | 2 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Amps C Ø | 86.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Amps B Ø | 81.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Amps A Ø | 88.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Switching Operations | 5 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | 9 Month Operations | 6 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Amps A Ø | 68.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Amps B Ø | 67.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Amps C Ø | 68.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Operations This Read Vac | 5 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Operations Counter AL | 240 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Operations Counter AF | 240 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | 9 Month Operations | 5 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Amps C Ø | 153.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Amps B Ø | 147.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Amps A Ø | 152.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Switching Operations | 1 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Operations This Read Vac | 1 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Operations Counter AF | 246 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Operations Counter AL | 246 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Unknown Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Amps A Ø | 137.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Switching Operations | 4 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | 9 Month Operations VCB New | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Amps B Ø | 129.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Amps C Ø | 134.0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | 9 Month Operations | 4 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Operations Counter AL | 184 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Operations Counter AF | 184 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Maintenance Operations | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Fault Operations Ground | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Operations This Read Vac | 4 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000050 | PowerFuse | BR-12KV TR 5 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000050 | PowerFuse | BR-12KV TR 5 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000051 | PowerFuse | BR-STA SER NO 5 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000051 | PowerFuse | BR-STA SER NO 5 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LTCC000529 | LTCControl | BR-TRANS 5 | LTC Control Insp | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LTCC000529 | LTCControl | BR-TRANS 5 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LTCC000529 | LTCControl | BR-TRANS 5 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Counter Readings | LTC Operations Since Last Insp | -487 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Counter Readings | LTC Min Tap Position | Neutral | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Counter Readings | LTC Max Tap Position | 6L | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Counter Readings | LTC As Left Counter | 186055 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Counter Readings | LTC As Found Counter | 186055 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Counter Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Readings | X3 Winding Temp Max | 55 | °C |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Readings | Oil Temp Present | 10 | °C |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Readings | X3 Winding Temp Present | 10 | °C |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Readings | X2 Winding Temp Present | 10 | °C |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Readings | Oil Temp Max | 51 | °C |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Readings | X2 Winding Temp Max | 55 | °C |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Readings | X1 Winding Temp Present | 13 | °C |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Readings | X1 Winding Temp Max | 55 | °C |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000049 | PowerFuse | BR-12KV TR 3 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000049 | PowerFuse | BR-12KV TR 3 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000048 | PowerFuse | BR-STA SER NO 3 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000048 | PowerFuse | BR-STA SER NO 3 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LTCC000475 | LTCControl | BR-TRANS 3 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LTCC000475 | LTCControl | BR-TRANS 3 | LTC Control Insp | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LTCC000475 | LTCControl | BR-TRANS 3 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Counter Readings | LTC Operations Since Last Insp | 650 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Counter Readings | LTC As Found Counter | 177048 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Counter Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Counter Readings | LTC As Left Counter | 177048 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Max | 60 | °C |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Present | 40 | °C |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Max | 60 | °C |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Present | 40 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Max | 60 | °C |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Present | 40 | °C |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000046 | PowerFuse | BR-12KV TR 4 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000046 | PowerFuse | BR-12KV TR 4 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000047 | PowerFuse | BR-STA SER NO 4 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000047 | PowerFuse | BR-STA SER NO 4 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LTCC000496 | LTCControl | BR-TRANS 4 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LTCC000496 | LTCControl | BR-TRANS 4 | LTC Control Insp | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LTCC000496 | LTCControl | BR-TRANS 4 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Counter Readings | LTC Max Tap Position | 8L | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Counter Readings | LTC Min Tap Position | 1R | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Counter Readings | LTC Operations Since Last Insp | 450 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Counter Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Counter Readings | LTC As Found Counter | 187792 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Counter Readings | LTC As Left Counter | 187792 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Readings | Oil Temp Present | 34 | °C |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Readings | X3 Winding Temp Present | 36 | °C |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Readings | X3 Winding Temp Max | 59 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Readings | X2 Winding Temp Present | 37 | °C |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Readings | X2 Winding Temp Max | 58 | °C |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Readings | X1 Winding Temp Present | 37 | °C |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Readings | X1 Winding Temp Max | 59 | °C |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 300 | psi |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | General Comments | NEED NITROGEN BOTTLE FILLED | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LTCC000839 | LTCControl | BR-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LTCC000839 | LTCControl | BR-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LTCC000839 | LTCControl | BR-TRANS 2 | LTC Control Insp | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 40 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 2 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 4 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 3 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 104093 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 104093 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Counter Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000041 | PowerFuse | BR-14KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000041 | PowerFuse | BR-14KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LTCC000838 | LTCControl | BR-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LTCC000838 | LTCControl | BR-TRANS 1 | LTC Control Insp | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LTCC000838 | LTCControl | BR-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | LTCMechanism | BR-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | LTCMechanism | BR-TRANS 1 | LTC Counter Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | LTCMechanism | BR-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | LTCMechanism | BR-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 2302 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | LTCMechanism | BR-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 3 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | LTCMechanism | BR-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 88393 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | LTCMechanism | BR-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 88393 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | LTCMechanism | BR-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | LTCMechanism | BR-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | LTCMechanism | BR-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | LTCMechanism | BR-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | LTCMechanism | BR-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 110.00 | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000042 | PowerFuse | BR-14KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000042 | PowerFuse | BR-14KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000038 | PowerFuse | BR-14KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000038 | PowerFuse | BR-14KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000045 | PowerFuse | BR-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000045 | PowerFuse | BR-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Tank Oil Level | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0245 | GroundTransformer | BR-GND TR 2 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0245 | GroundTransformer | BR-GND TR 2 | Ground Transformer Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0245 | GroundTransformer | BR-GND TR 2 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0245 | GroundTransformer | BR-GND TR 2 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0245 | GroundTransformer | BR-GND TR 2 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0245 | GroundTransformer | BR-GND TR 2 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0245 | GroundTransformer | BR-GND TR 2 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0245 | GroundTransformer | BR-GND TR 2 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0245 | GroundTransformer | BR-GND TR 2 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0245 | GroundTransformer | BR-GND TR 2 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0245 | GroundTransformer | BR-GND TR 2 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000040 | PowerFuse | BR-GND TR 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000040 | PowerFuse | BR-GND TR 2 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000043 | PowerFuse | BR-14KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000043 | PowerFuse | BR-14KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000044 | PowerFuse | BR-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000044 | PowerFuse | BR-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000039 | PowerFuse | BR-GND TR 1 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | PF000039 | PowerFuse | BR-GND TR 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Station Ground Set On Site? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Follow-up Action Required? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Floor Swept? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Broom on Site? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Door Alarms OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | General Comments | need grounds, and ladder in control house | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Trash Emptied? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | All Connections OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | ANN000006 | Annunciator | BR-Annunciator Panel 1 | Annunciator Patrol Inspection | All Lights Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | ANN000006 | Annunciator | BR-Annunciator Panel 1 | Annunciator Patrol Inspection | Control House Alarm Audible? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | ANN000006 | Annunciator | BR-Annunciator Panel 1 | Annunciator Patrol Inspection | ESOC Received Alarm Test? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | ANN000006 | Annunciator | BR-Annunciator Panel 1 | Annunciator Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | ANN000006 | Annunciator | BR-Annunciator Panel 1 | Annunciator Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | General Comments | | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 14:57 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Switching Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Operations This Read Vac | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Operations Counter AL | 109 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Operations Counter AF | 109 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Amps C Ø | 0.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | 9 Month Operations | 2 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Amps B Ø | 0.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Amps A Ø | 0.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Switching Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Operations Counter AF | 112 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Operations Counter AL | 112 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | 9 Month Operations | 8 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Amps A Ø | 90.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Amps B Ø | 85.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Operations This Read Vac | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Amps C Ø | 95.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Amps A Ø | 80.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Amps B Ø | 80.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Amps C Ø | 70.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | 9 Month Operations | 2 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Operations Counter AF | 102 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Operations Counter AL | 102 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Operations This Read Vac | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Switching Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Amps C Ø | 50.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Operations Counter AF | 135 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Operations This Read Vac | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Amps A Ø | 65.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Switching Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Amps B Ø | 50.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Operations Counter AL | 135 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | 9 Month Operations | 2 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Switching Operations | 1 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Operations This Read Vac | 1 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Operations Counter AL | 109 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Operations Counter AF | 108 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | 9 Month Operations | 1 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Amps C Ø | 0.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Amps B Ø | 0.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Amps A Ø | 0.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Amps C Ø | 205.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | 9 Month Operations | 1 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Amps B Ø | 210.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Amps A Ø | 220.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Switching Operations | 1 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Operations This Read Vac | 1 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Operations Counter AL | 144 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Operations Counter AF | 143 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | 9 Month Operations | 2 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Amps A Ø | 0.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Switching Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Operations This Read Vac | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Operations Counter AL | 138 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Operations Counter AF | 138 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Amps C Ø | 0.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Amps B Ø | 0.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | 9 Month Operations | 8 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Amps C Ø | 145.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Amps B Ø | 115.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Amps A Ø | 130.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Operations This Read Vac | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Switching Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Operations Counter AL | 128 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Operations Counter AF | 128 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | 9 Month Operations | 2 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Switching Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Operations This Read Vac | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Amps A Ø | 35.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Amps B Ø | 25.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Operations Counter AL | 115 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Operations Counter AF | 115 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Amps C Ø | 35.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | 9 Month Operations | 2 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Amps A Ø | 140.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Amps B Ø | 120.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Amps C Ø | 100.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Operations Counter AF | 111 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Operations Counter AL | 111 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Operations This Read Vac | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Switching Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Switching Operations | 1 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Operations This Read Vac | 1 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Operations Counter AL | 99 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Operations Counter AF | 98 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | 9 Month Operations | 1 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Switching Operations | 1 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Operations This Read Vac | 1 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Operations Counter AL | 216 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Operations Counter AF | 115 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Amps A Ø | 290.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | 9 Month Operations | 1 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Amps B Ø | 255.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Amps C Ø | 270.0 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Counter Readings | LTC Operations Since Last Insp | 321 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Counter Readings | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Counter Readings | LTC As Found Counter | 5372 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Counter Readings | LTC As Left Counter | 5372 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 26 | °C |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 43 | °C |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCC000866 | LTCControl | 899-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCC000866 | LTCControl | 899-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCC000866 | LTCControl | 899-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCC000866 | LTCControl | 899-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCC000866 | LTCControl | 899-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCC000866 | LTCControl | 899-1 | LTC Control Insp | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCC000866 | LTCControl | 899-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCC000866 | LTCControl | 899-1 | LTC Control Insp | All Connections OK? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | Totalizer Meter Reading | .7650 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | X3 Winding Temp Present | 30 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | X3 Winding Temp Max | 60 | °C |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | X2 Winding Temp Present | 30 | °C |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | X2 Winding Temp Max | 60 | °C |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | X1 Winding Temp Max | 60 | °C |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | X1 Winding Temp Present | 30 | °C |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | LTC Totalizer Reading | 18360.00 | kw |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | Oil Temp Max | 49 | °C |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 600 | psi |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Counter Readings | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Counter Readings | LTC As Found Counter | 6035 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Counter Readings | LTC As Left Counter | 6035 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Counter Readings | LTC Operations Since Last Insp | 285 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 26 | °C |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 42 | °C |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCC000867 | LTCControl | 899-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCC000867 | LTCControl | 899-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCC000867 | LTCControl | 899-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCC000867 | LTCControl | 899-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCC000867 | LTCControl | 899-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCC000867 | LTCControl | 899-2 | LTC Control Insp | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCC000867 | LTCControl | 899-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | LTCC000867 | LTCControl | 899-2 | LTC Control Insp | All Connections OK? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | X3 Winding Temp Present | 31 | °C |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | X3 Winding Temp Max | 42 | °C |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | X2 Winding Temp Present | 31 | °C |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | X2 Winding Temp Max | 42 | °C |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | X1 Winding Temp Present | 31 | °C |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | X1 Winding Temp Max | 42 | °C |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | Totalizer Meter Reading | .4632 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | LTC Totalizer Reading | 11116.80 | kw |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 2000 | psi |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | MOD Cabinet Heater functional? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | MOD Cabinet Internals Clean? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | MOD Motor Jaw Coupling | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Platform/Walkway/Railing OK? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | UG Pothead Condition Good? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | General Comments | | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | YD000377 | Yard | 899-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | YD000377 | Yard | 899-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | YD000377 | Yard | 899-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | YD000377 | Yard | 899-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | YD000377 | Yard | 899-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | YD000377 | Yard | 899-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | YD000377 | Yard | 899-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | YD000377 | Yard | 899-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | YD000377 | Yard | 899-Yard | Yard Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | YD000377 | Yard | 899-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | YD000377 | Yard | 899-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | YD000377 | Yard | 899-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/6/2023 15:16 | Distribution | Wilson Downing Quarterly Inspection | YD000377 | Yard | 899-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Max Tap Position | 9R | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Min Tap Position | 2L | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Regulator As Left Counter | 26835 | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Current Tap Position | 4R | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | General Comments | | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Min Tap Position | 3R | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Max Tap Position | 15R | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | General Comments | | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Regulator As Left Counter | 179973 | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.7 | volts |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Current Tap Position | 9R | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Regulator As Left Counter | 78702 | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Min Tap Position | 1L | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | General Comments | | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Current Tap Position | 2R | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Readings | Oil Temp Present | 26 | °C |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Readings | Oil Temp Max | 43 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 135.00 | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Readings | General Comments | | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 140.00 | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | General Comments | H2 bushing has chipped skirt. | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Readings | Oil Temp Max | 59 | °C |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Readings | General Comments | | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 95.00 | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Readings | General Comments | | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 349.20 | kw |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 135.00 | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Readings | Oil Temp Present | 33 | °C |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 600 | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Readings | Totalizer Meter Reading | .5820 | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 140.00 | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 236 | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 4.5 | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 7.2 | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 6.3 | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 204 | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 194 | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | General Comments | Xfmr fuse barrels are starting to fray. | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | n | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | General Comments | Gate side fence is not grounded. Every other side is just grounded in one spot. | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | YD000214 | Yard | 448-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | YD000214 | Yard | 448-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | YD000214 | Yard | 448-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | YD000214 | Yard | 448-Yard | Yard Patrol Inspection | General Comments | | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | YD000214 | Yard | 448-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | YD000214 | Yard | 448-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | YD000214 | Yard | 448-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | YD000214 | Yard | 448-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | YD000214 | Yard | 448-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | YD000214 | Yard | 448-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | YD000214 | Yard | 448-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | YD000214 | Yard | 448-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/6/2023 14:07 | Distribution | Outwood Quarterly Inspection | YD000214 | Yard | 448-Yard | Yard Patrol Inspection | Ambient Temp | 51 | °F |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | 9 Month Operations | 3 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Amps A Ø | 0.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Amps B Ø | 0.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Amps C Ø | 0.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Switching Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Operations This Read Vac | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Operations Counter AL | 241 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Operations Counter AF | 241 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | 9 Month Operations | 2 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Amps A Ø | 240.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Amps B Ø | 257.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Switching Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Operations Counter AL | 219 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Amps C Ø | 227.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Operations Counter AF | 219 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Switching Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Operations Counter AL | 209 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Operations Counter AF | 209 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Amps C Ø | 362.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Amps B Ø | 418.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Amps A Ø | 423.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | 9 Month Operations | 2 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | 9 Month Operations | 2 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Switching Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Operations Counter AF | 162 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Operations Counter AL | 162 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Switching Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Operations This Read Vac | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Operations Counter AL | 201 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Operations Counter AF | 201 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Amps C Ø | 0.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Amps B Ø | 0.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Amps A Ø | 0.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | 9 Month Operations | 2 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Switching Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Operations This Read Vac | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Operations Counter AL | 230 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Operations Counter AF | 230 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | 9 Month Operations | 2 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Amps C Ø | 0.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Amps B Ø | 0.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Amps A Ø | 0.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Switching Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Operations This Read Vac | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Operations Counter AL | 229 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Operations Counter AF | 229 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Amps C Ø | 94.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Amps B Ø | 124.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Amps A Ø | 95.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | 9 Month Operations | 4 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | 9 Month Operations | 3 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Switching Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Operations This Read Vac | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Operations Counter AL | 262 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Operations Counter AF | 262 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Amps C Ø | 137.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Amps B Ø | 144.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Amps A Ø | 153.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | 9 Month Operations | 7 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Switching Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Operations This Read Vac | 5 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Operations Counter AL | 273 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Operations Counter AF | 273 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Fault Operations B Ø | 5 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Amps A Ø | 165.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Fault Adjusted Amps B Phase V | 60.15 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Amps C Ø | 136.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Amps B Ø | 161.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Fault Operations B Ø | 5 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Fault Adjusted Amps B Phase V | 60.15 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Amps C Ø | 155.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Switching Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Operations This Read Vac | 5 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Operations Counter AL | 223 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Operations Counter AF | 223 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Amps B Ø | 182.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Amps A Ø | 180.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | 9 Month Operations | 7 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Switching Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Operations This Read Vac | 23 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Operations Counter AL | 275 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Operations Counter AF | 275 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Fault Operations B Ø | 23 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Fault Adjusted Amps B Phase V | 276.67 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Amps C Ø | 79.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Amps B Ø | 70.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Amps A Ø | 80.0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | 9 Month Operations | 25 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCC000726 | LTCControl | 428-2 | LTC Control Insp | All Connections OK? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCC000726 | LTCControl | 428-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCC000726 | LTCControl | 428-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCC000726 | LTCControl | 428-2 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCC000726 | LTCControl | 428-2 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCC000726 | LTCControl | 428-2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCC000726 | LTCControl | 428-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCC000726 | LTCControl | 428-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCC000726 | LTCControl | 428-2 | LTC Control Insp | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BCH001552 | Charger | 116-Battery Charger Control House | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BCH001552 | Charger | 116-Battery Charger Control House | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BCH001552 | Charger | 116-Battery Charger Control House | Battery Charger Patrol Insp | Battery Charger Current | 4.1 | amps |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BCH001552 | Charger | 116-Battery Charger Control House | Battery Charger Patrol Insp | As Left Float Voltage | 133.7 | VDC |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BCH001552 | Charger | 116-Battery Charger Control House | Battery Charger Patrol Insp | As Found Float Voltage | 133.7 | VDC |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BCH001552 | Charger | 116-Battery Charger Control House | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 10.000 | millivolts |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BCH001552 | Charger | 116-Battery Charger Control House | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BCH001552 | Charger | 116-Battery Charger Control House | Battery Charger Patrol Insp | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 20 | °C |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 30 | °C |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BAT001624 | Battery | 116-Battery Bank Control House | Battery Patrol Inspection | Negative DC Ground | 67.0 | VDC |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BAT001624 | Battery | 116-Battery Bank Control House | Battery Patrol Inspection | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BAT001624 | Battery | 116-Battery Bank Control House | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BAT001624 | Battery | 116-Battery Bank Control House | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BAT001624 | Battery | 116-Battery Bank Control House | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BAT001624 | Battery | 116-Battery Bank Control House | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BAT001624 | Battery | 116-Battery Bank Control House | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BAT001624 | Battery | 116-Battery Bank Control House | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BAT001624 | Battery | 116-Battery Bank Control House | Battery Patrol Inspection | Positive DC Ground | 66.0 | VDC |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BAT001624 | Battery | 116-Battery Bank Control House | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BAT001624 | Battery | 116-Battery Bank Control House | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BAT001624 | Battery | 116-Battery Bank Control House | Battery Patrol Inspection | Battery Area Ambient Temp | 68 | °F |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BAT001624 | Battery | 116-Battery Bank Control House | Battery Patrol Inspection | All Connections OK? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Counter Readings | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Counter Readings | LTC As Found Counter | 12176 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Counter Readings | LTC As Left Counter | 12176 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Counter Readings | LTC Operations Since Last Insp | 350 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | LTC Totalizer Reading | 4500.00 | kw |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | Top Oil Temperature Max | 25 | °C |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | Winding Temp Present | 25 | °C |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 10.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | X1 Winding Temp Max | 30 | °C |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | Top Oil Temperature Present | 22 | °C |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 1000 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | Totalizer Meter Reading | 4.5000 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | Winding Temp Max | 30 | °C |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | X3 Winding Temp Present | 25 | °C |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | X1 Winding Temp Present | 25 | °C |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | X3 Winding Temp Max | 30 | °C |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | X2 Winding Temp Max | 30 | °C |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | X2 Winding Temp Present | 25 | °C |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 700 | psi |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Counter Readings | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Counter Readings | LTC Max Tap Position | 5R | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Counter Readings | LTC Operations Since Last Insp | 431 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Counter Readings | LTC As Left Counter | 30946 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Counter Readings | LTC As Found Counter | 30946 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Switching Operations | 1 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Operations This Read Vac | 1 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Operations Counter AL | 182 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Operations Counter AF | 181 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Amps C Ø | 45.0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Amps B Ø | 46.0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Amps A Ø | 32.0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | 9 Month Operations | 14 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | 9 Month Operations VCB New | 13 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCC000299 | LTCControl | 428-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCC000299 | LTCControl | 428-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCC000299 | LTCControl | 428-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCC000299 | LTCControl | 428-1 | LTC Control Insp | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCC000299 | LTCControl | 428-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCC000299 | LTCControl | 428-1 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCC000299 | LTCControl | 428-1 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCC000299 | LTCControl | 428-1 | LTC Control Insp | All Connections OK? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | LTCC000299 | LTCControl | 428-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 25 | °C |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 20 | °C |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | 9 Month Operations | 8 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Amps A Ø | 90.0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Amps B Ø | 98.0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Amps C Ø | 90.0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Operations Counter AF | 244 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Operations Counter AL | 248 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Operations This Read Vac | 4 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Switching Operations | 4 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 1000 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | Totalizer Meter Reading | 6.9000 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | Winding Temp Max | 35 | °C |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 100.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | X1 Winding Temp Max | 35 | °C |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | X1 Winding Temp Present | 30 | °C |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | X2 Winding Temp Max | 35 | °C |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | X2 Winding Temp Present | 30 | °C |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | X3 Winding Temp Max | 35 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | X3 Winding Temp Present | 30 | °C |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | Kwh Reading | 53015 | KwH |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | Top Oil Temperature Present | 25 | °C |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | Top Oil Temperature Max | 30 | °C |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | LTC Totalizer Reading | 6900.00 | kw |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | MegaVar Demand Meter Max | 1.00 | MegaVars |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Amps B Ø | 53.0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Amps C Ø | 59.0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Amps A Ø | 57.0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | 9 Month Operations | 7 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Switching Operations | 1 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Operations This Read Vac | 1 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Operations Counter AL | 250 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Operations Counter AF | 249 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Water Added | If low,note cell #~'s |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Switching Operations | 4 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Operations This Read Vac | 4 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Operations Counter AL | 202 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Operations Counter AF | 198 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Amps A Ø | 122.0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Amps B Ø | 122.0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | 9 Month Operations | 7 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Amps C Ø | 119.0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | T.C. filter has power but will not come on. | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Amps A Ø | 107.0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Amps B Ø | 111.0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Amps C Ø | 96.0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Switching Operations | 1 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Operations This Read Vac | 1 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Operations Counter AF | 171 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Operations Counter AL | 172 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | 9 Month Operations | 4 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | 9 Month Operations | 4 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Amps A Ø | 15.0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Amps B Ø | 11.0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Amps C Ø | 23.0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Operations Counter AF | 161 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Operations Counter AL | 162 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Switching Operations | 1 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Operations This Read Vac | 1 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Switching Operations | 1 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Operations This Read Vac | 9 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Operations Counter AL | 292 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Operations Counter AF | 283 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Maintenance Operations | 8 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | 9 Month Operations | 14 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Amps A Ø | 0.0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Amps B Ø | 0.0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Amps C Ø | 0.0 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | Ambient Temp | 46 | °F |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Operations Counter AF | 85 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Operations Counter AL | 85 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Switching Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | 9 Month Operations | 3 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 13:59 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BAT001525 | Battery | 764-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BAT001525 | Battery | 764-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BAT001525 | Battery | 764-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.5 | VDC |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BAT001525 | Battery | 764-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.5 | VDC |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BAT001525 | Battery | 764-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BAT001525 | Battery | 764-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BAT001525 | Battery | 764-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BAT001525 | Battery | 764-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BAT001525 | Battery | 764-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BAT001525 | Battery | 764-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BAT001525 | Battery | 764-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BAT001525 | Battery | 764-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BCH001451 | Charger | 764-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .700 | millivolts |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BCH001451 | Charger | 764-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.1 | VDC |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BCH001451 | Charger | 764-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BCH001451 | Charger | 764-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Min Tap Position | 4L | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 50247 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 36750 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.7 | volts |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 58061 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Min Tap Position | 3L | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Readings | General Comments | | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3250.80 | kw |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Readings | Oil Temp Present | 24 | °C |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 3600 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .9030 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Needs Replacing | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 114.17 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.5 | psi |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Operations Counter AL | 194 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Operations This Read Vac | 0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Switching Operations | 0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | 9 Month Operations VCB New | 1 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | 9 Month Operations | 1 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Operations Counter AF | 194 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | General Comments | | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Amps A Ø | 0.0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Amps C Ø | 0.0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Amps B Ø | 0.0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Counter Readings | General Comments | | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 506707 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 506707 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 357 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Operations Counter AF | 184 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Operations Counter AL | 184 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | General Comments | | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Amps A Ø | 45.0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Amps B Ø | 64.0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Amps C Ø | 40.0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Operations This Read Vac | 0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Switching Operations | 0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | 9 Month Operations | 1 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Amps A Ø | 30.0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Amps B Ø | 31.0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Amps C Ø | 31.0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | 9 Month Operations | 1 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Switching Operations | 0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Operations This Read Vac | 0 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Operations Counter AL | 197 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | General Comments | | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Operations Counter AF | 197 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 40 | °C |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 60 | °C |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 40 | °C |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 60 | °C |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 38 | °C |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 60 | °C |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | General Comments | | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | General Comments | gap under fence on ditch side, gravel has washed out | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 325 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 496178 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Counter Readings | General Comments | | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 496178 | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | General Comments | | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:18 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Readings | Percent Thermal Load A Ø Max | -60 | % |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Readings | Percent Thermal Load B Ø Max | -60 | % |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Readings | Percent Thermal Load C Ø Max | -60 | % |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Patrol Inspection | General Comments | | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | 9 Months Operations | 1 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Amps A Ø | 0.0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Amps B Ø | 0.0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Amps C Ø | 0.0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Unknown Operations | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Switching Operations | 1 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Operations This Read AM | 1 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Operations Counter AL | 329 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Operations Counter AF | 329 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | General Comments | | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Patrol Inspection | General Comments | | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Amps C Ø | 70.0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Amps B Ø | 90.0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | 9 Months Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | General Comments | | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Operations Counter AF | 525 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Operations Counter AL | 525 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Operations This Read AM | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Switching Operations | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Unknown Operations | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Amps A Ø | 80.0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Patrol Inspection | General Comments | | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Unknown Operations | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Operations Counter AF | 298 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Amps A Ø | 50.0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Switching Operations | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Operations This Read AM | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Operations Counter AL | 298 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | 9 Months Operations | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | General Comments | | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Amps C Ø | 40.0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Amps B Ø | 40.0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Patrol Inspection | General Comments | | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Amps B Ø | 130.0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Amps C Ø | 120.0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Amps A Ø | 130.0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Operations Counter AL | 619 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Operations Counter AF | 619 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | 9 Months Operations | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Operations This Read AM | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | General Comments | | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Switching Operations | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Unknown Operations | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Patrol Inspection | General Comments | | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Fault Operations B Ø | 1 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Fault Operations C Ø | 1 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Amps B Ø | 50.0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Amps C Ø | 50.0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 9.55 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 9.55 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | General Comments | b,c phase ioc | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Operations Counter AF | 381 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Operations Counter AL | 381 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Amps A Ø | 50.0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Operations This Read AM | 2 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Switching Operations | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Unknown Operations | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | 9 Months Operations | 2 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | BCH000842 | Charger | CT-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | BCH000842 | Charger | CT-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.7 | VDC |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | BCH000842 | Charger | CT-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.7 | VDC |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | BCH000842 | Charger | CT-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | BCH000842 | Charger | CT-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | BCH000842 | Charger | CT-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | BCH000842 | Charger | CT-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | LTCC000988 | LTCControl | 116-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | LTCC000988 | LTCControl | 116-5 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | LTCC000988 | LTCControl | 116-5 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | LTCC000988 | LTCControl | 116-5 | LTC Control Insp | LTC Output Voltage Level | 123.1 | VAC |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | LTCC000988 | LTCControl | 116-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | LTCC000988 | LTCControl | 116-5 | LTC Control Insp | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | LTCC000988 | LTCControl | 116-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | LTCC000988 | LTCControl | 116-5 | LTC Control Insp | All Connections OK? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Counter Readings | LTC Operations Since Last Insp | 457 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Counter Readings | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Counter Readings | LTC As Found Counter | 174089 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Counter Readings | LTC As Left Counter | 174095 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Readings | Totalizer Meter Reading | .6372 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Readings | Winding Temp Max | 36 | °C |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 10.00 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Readings | Oil Temp Present | 36 | °C |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Readings | Oil Temp Max | 36 | °C |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Readings | LTC Totalizer Reading | 6117.12 | kw |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Readings | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | CH000452 | ControlHouse | CT-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | CH000452 | ControlHouse | CT-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | CH000452 | ControlHouse | CT-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | CH000452 | ControlHouse | CT-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | CH000452 | ControlHouse | CT-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | CH000452 | ControlHouse | CT-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | CH000452 | ControlHouse | CT-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | CH000452 | ControlHouse | CT-Battery Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | CH000452 | ControlHouse | CT-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | General Comments | | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | General Comments | | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PF001299 | PowerFuse | CT-4KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PF001299 | PowerFuse | CT-4KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PF001299 | PowerFuse | CT-4KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PF001298 | PowerFuse | CT-4KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PF001298 | PowerFuse | CT-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/6/2023 13:35 | Distribution | Carter Quarterly Inspection | PF001298 | PowerFuse | CT-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | LTCC000947 | LTCControl | 116-6 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | LTCC000947 | LTCControl | 116-6 | LTC Control Insp | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | LTCC000947 | LTCControl | 116-6 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | LTCC000947 | LTCControl | 116-6 | LTC Control Insp | All Connections OK? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | LTCC000947 | LTCControl | 116-6 | LTC Control Insp | LTC Output Voltage Level | 123.7 | VAC |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | LTCC000947 | LTCControl | 116-6 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | LTCC000947 | LTCControl | 116-6 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | LTCC000947 | LTCControl | 116-6 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Counter Readings | LTC Operations Since Last Insp | 380 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Counter Readings | LTC As Left Counter | 159029 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Counter Readings | LTC As Found Counter | 159026 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Counter Readings | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Readings | LTC Totalizer Reading | 3617.28 | kw |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Readings | Winding Temp Present | 34 | °C |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Readings | Winding Temp Max | 39 | °C |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Readings | Totalizer Meter Reading | .3768 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Readings | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | General Comments | | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/6/2023 14:36 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | Ambient Temp | 75 | °F |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | General Comments | | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | General Comments | | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Operations Counter | 0 | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Amps A Ø | .3 | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Amps B Ø | .3 | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Amps C Ø | .3 | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Amps C Ø | .3 | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Amps B Ø | .2 | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Amps A Ø | .3 | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Operations Counter | 0 | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | YD000044 | Yard | 224-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | YD000044 | Yard | 224-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | YD000044 | Yard | 224-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | YD000044 | Yard | 224-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | YD000044 | Yard | 224-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | YD000044 | Yard | 224-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | YD000044 | Yard | 224-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | YD000044 | Yard | 224-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | YD000044 | Yard | 224-Yard | Yard Patrol Inspection | General Comments | no yard light | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | YD000044 | Yard | 224-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | YD000044 | Yard | 224-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/7/2023 8:19 | Distribution | Newtown Switching Quarterly Inspection | YD000044 | Yard | 224-Yard | Yard Patrol Inspection | Ambient Temp | 67 | °F |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 679 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0.0 | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 310 | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 92 | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 10.5 | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 87 | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 109 | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 4.2 | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 94 | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 7.1 | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 170557 | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Current Tap Position | 13L | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.2 | volts |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Max Tap Position | 4L | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Current Tap Position | 11L | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 11424 | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.4 | volts |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Max Tap Position | 6L | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Current Tap Position | 12L | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Max Tap Position | 7L | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 211015 | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.3 | volts |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Readings | General Comments | | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1027.08 | kw |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Readings | Oil Temp Present | 42 | °C |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1800 | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .5706 | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | General Comments | | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Amps A Ø | 47.0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | General Comments | | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Operations Counter AF | 1491 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Amps B Ø | 72.0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Amps C Ø | 71.0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Fault Adjusted Amps B Phase AM | 55.90 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Fault Adjusted Amps C Phase AM | 55.90 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Fault Operations B Ø | 5 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Fault Operations C Ø | 5 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Unknown Operations | 0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Switching Operations | 0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Operations This Read AM | 10 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Operations Counter AL | 1491 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | 9 Month Ops New | 2 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | 9 Months Operations | 12 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Patrol Inspection | General Comments | | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Amps C Ø | 0.0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Amps B Ø | 0.0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Operations Counter AL | 1342 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Operations Counter AF | 1342 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Operations This Read AM | 0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | General Comments | | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Switching Operations | 0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Unknown Operations | 0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Amps A Ø | 0.0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | 9 Months Operations | 0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Patrol Inspection | General Comments | | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | PF000425 | PowerFuse | WH-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | PF000425 | PowerFuse | WH-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LTCC000387 | LTCControl | WH-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LTCC000387 | LTCControl | WH-TRANS 2 | LTC Control Insp | General Comments | | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LTCC000387 | LTCControl | WH-TRANS 2 | LTC Control Insp | All Connections OK? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 540 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 6L | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 11L | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 23071 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 23071 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Counter Readings | General Comments | | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Readings | H3 Winding Temp Present | 60 | °C |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Readings | H3 Winding Temp Max | 30 | °C |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Readings | Percent Thermal Load B Ø Max | 60 | % |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Readings | Percent Thermal Load C Ø Max | 60 | % |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Readings | Percent Thermal Load A Ø Max | 60 | % |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.5 | psi |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LTCC000182 | LTCControl | WH-TRANS 3 | LTC Control Insp | All Connections OK? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LTCC000182 | LTCControl | WH-TRANS 3 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LTCC000182 | LTCControl | WH-TRANS 3 | LTC Control Insp | General Comments | | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Counter Readings | LTC As Left Counter | 34695 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Counter Readings | LTC As Found Counter | 34695 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Counter Readings | General Comments | | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Counter Readings | LTC Operations Since Last Insp | 159 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | YD000007 | Yard | 365-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | YD000007 | Yard | 365-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | YD000007 | Yard | 365-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | YD000007 | Yard | 365-Yard | Yard Patrol Inspection | General Comments | | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | YD000007 | Yard | 365-Yard | Yard Patrol Inspection | Ambient Temp | 64 | °F |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | YD000007 | Yard | 365-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | YD000007 | Yard | 365-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | YD000007 | Yard | 365-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | YD000007 | Yard | 365-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | YD000007 | Yard | 365-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | YD000007 | Yard | 365-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/6/2023 11:05 | Distribution | White Oak Quarterly Inspection | YD000007 | Yard | 365-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Readings | General Comments | | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.5 | psi |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BCH000122 | Charger | WH-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.9 | VDC |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BCH000122 | Charger | WH-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.9 | VDC |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BCH000122 | Charger | WH-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BCH000122 | Charger | WH-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 5.5 | amps |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BCH000122 | Charger | WH-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BCH000122 | Charger | WH-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BCH000122 | Charger | WH-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BCH000122 | Charger | WH-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BAT001023 | Battery | WH-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BAT001023 | Battery | WH-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BAT001023 | Battery | WH-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BAT001023 | Battery | WH-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BAT001023 | Battery | WH-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BAT001023 | Battery | WH-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BAT001023 | Battery | WH-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BAT001023 | Battery | WH-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BAT001023 | Battery | WH-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BAT001023 | Battery | WH-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BAT001023 | Battery | WH-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BAT001023 | Battery | WH-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | General Comments | | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | General Comments | | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Ambient Temp | 42 | °F |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | General Comments | | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | General Comments | | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Amps C Ø | 59.0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Amps B Ø | 69.0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Amps A Ø | 52.0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Switching Operations | 0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Operations This Read Vac | 0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Operations Counter AL | 199 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | 9 Month Operations | 0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Operations Counter AF | 199 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | PF001301 | PowerFuse | WH-12KV TR 3 POTS | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | PF001301 | PowerFuse | WH-12KV TR 3 POTS | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | PF001301 | PowerFuse | WH-12KV TR 3 POTS | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | PF001302 | PowerFuse | WH-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | PF001302 | PowerFuse | WH-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | PF001302 | PowerFuse | WH-12KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | PT002279 | PT | WH-12KV TR 3 POT | PT Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | PT002279 | PT | WH-12KV TR 3 POT | PT Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | PT002279 | PT | WH-12KV TR 3 POT | PT Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | PT002279 | PT | WH-12KV TR 3 POT | PT Patrol Inspection | General Comments | | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | PT002279 | PT | WH-12KV TR 3 POT | PT Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | PT002279 | PT | WH-12KV TR 3 POT | PT Patrol Inspection | PT Free of Leaks? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | PT002279 | PT | WH-12KV TR 3 POT | PT Patrol Inspection | Tank Oil Level | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | PT002279 | PT | WH-12KV TR 3 POT | PT Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | PT002280 | PT | WH-12KV TR 2 POT | PT Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | PT002280 | PT | WH-12KV TR 2 POT | PT Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | PT002280 | PT | WH-12KV TR 2 POT | PT Patrol Inspection | General Comments | | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | PT002280 | PT | WH-12KV TR 2 POT | PT Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | PT002280 | PT | WH-12KV TR 2 POT | PT Patrol Inspection | PT Free of Leaks? | y | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | PT002280 | PT | WH-12KV TR 2 POT | PT Patrol Inspection | Tank Oil Level | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | PT002280 | PT | WH-12KV TR 2 POT | PT Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 11:00 | Distribution | WHAS Quarterly Inspection | PT002280 | PT | WH-12KV TR 2 POT | PT Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Switching Operations | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Operations This Read Vac | 3 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Operations Counter AL | 165 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Operations Counter AF | 165 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | General Comments | | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | 9 Month Operations VCB New | 1 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | 9 Month Operations | 4 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Fault Operations C Ø | 2 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Fault Operations B Ø | 1 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Fault Adjusted Amps C Phase V | 24.40 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Fault Adjusted Amps B Phase V | 12.20 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Amps C Ø | 112.0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Amps B Ø | 107.0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Amps A Ø | 90.0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Switching Operations | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Operations This Read Vac | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Operations Counter AL | 160 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Operations Counter AF | 160 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | General Comments | | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | 9 Month Operations | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Amps C Ø | 285.0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Amps B Ø | 258.0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Amps A Ø | 277.0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Readings | Totalizer Meter Reading | .3110 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Readings | Oil Temp Present | 50 | °C |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Readings | LTC Totalizer Reading | 7464.00 | kw |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Readings | General Comments | | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Counter Readings | LTC As Left Counter | 157073 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Counter Readings | LTC Operations Since Last Insp | 365 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Counter Readings | LTC As Found Counter | 157073 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Counter Readings | General Comments | | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | LTCC000857 | LTCControl | 176-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | LTCC000857 | LTCControl | 176-5 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | LTCC000857 | LTCControl | 176-5 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | LTCC000857 | LTCControl | 176-5 | LTC Control Insp | All Connections OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | LTCC000857 | LTCControl | 176-5 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | LTCC000857 | LTCControl | 176-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | LTCC000857 | LTCControl | 176-5 | LTC Control Insp | General Comments | | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | LTCC000857 | LTCControl | 176-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Operations Counter AF | 172 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Operations Counter AL | 174 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Operations This Read Vac | 2 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Switching Operations | 2 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | General Comments | | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Amps A Ø | 89.0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | 9 Month Operations | 2 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Amps B Ø | 92.0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Amps C Ø | 102.0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | 9 Month Operations | 2 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Amps A Ø | 122.0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Amps B Ø | 93.0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Amps C Ø | 90.0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Fault Operations Ground | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Follow-up Action Required? | n | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | General Comments | | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Switching Operations | 2 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Unknown Operations | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Maintenance Operations | 0 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Operations This Read Vac | 2 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Operations Counter AL | 154 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Operations Counter AF | 152 | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | General Comments | | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/6/2023 7:24 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Operations Counter AF | 161 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Operations Counter AL | 161 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | 9 Month Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Amps A Ø | 740.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Amps B Ø | 760.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Amps C Ø | 770.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Operations This Read Vac | 24 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Operations Counter AL | 194 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Operations Counter AF | 194 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | 9 Month Operations | 29 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Fault Operations C Ø | 12 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Fault Operations B Ø | 12 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Amps A Ø | 150.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Amps B Ø | 160.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Amps C Ø | 140.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Fault Adjusted Amps B Phase V | 150.58 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Fault Adjusted Amps C Phase V | 150.58 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Amps B Ø | 215.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Amps A Ø | 185.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | 9 Month Operations | 8 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Operations Counter AL | 272 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Operations Counter AF | 272 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Amps C Ø | 215.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Fault Operations Ground | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Operations Counter AF | 651 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Amps C Ø | 125.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Amps B Ø | 140.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Operations Counter AL | 651 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Amps A Ø | 145.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | 9 Month Operations | 4 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | 9 Month Operations | 3 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Amps A Ø | 250.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Amps B Ø | 260.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Amps C Ø | 290.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Operations Counter AF | 814 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Operations Counter AL | 814 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | 9 Month Operations | 2 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Operations Counter AL | 682 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Operations Counter AF | 682 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Amps A Ø | 240.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Amps B Ø | 235.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Amps C Ø | 270.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Operations Counter AL | 282 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Operations Counter AF | 282 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Amps C Ø | 110.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Amps B Ø | 110.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Amps A Ø | 105.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | 9 Month Operations | 2 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Operations Counter AF | 250 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Operations Counter AL | 250 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Operations This Read Vac | 1 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Fault Adjusted Amps A Phase V | 12.20 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Amps C Ø | 100.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Amps B Ø | 110.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Amps A Ø | 110.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | 9 Month Operations | 3 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Amps B Ø | 235.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Amps A Ø | 250.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Fault Operations A Ø | 4 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Fault Operations B Ø | 4 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Fault Operations C Ø | 4 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | 9 Month Operations | 16 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Operations Counter AF | 360 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Operations Counter AL | 360 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Operations This Read Vac | 12 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Fault Adjusted Amps C Phase V | 50.19 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Fault Adjusted Amps B Phase V | 50.19 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Fault Adjusted Amps A Phase V | 50.19 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Amps C Ø | 250.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Operations Counter AL | 163 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Operations Counter AF | 163 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Amps B Ø | 515.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Amps C Ø | 490.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Amps A Ø | 500.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | 9 Month Operations VCB New | 21 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | 9 Month Operations | 21 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Readings | Winding Temp Present | 50 | °C |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Readings | Winding Temp Max | 50 | °C |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Readings | Oil Temp Present | 50 | °C |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Readings | LTC Totalizer Reading | 0.00 | kw |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Readings | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | LTCC000859 | LTCControl | 463-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | LTCC000859 | LTCControl | 463-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | LTCC000859 | LTCControl | 463-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | LTCC000859 | LTCControl | 463-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | LTCC000859 | LTCControl | 463-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | LTCC000859 | LTCControl | 463-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | LTCC000859 | LTCControl | 463-1 | LTC Control Insp | All Connections OK? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | LTCC000859 | LTCControl | 463-1 | LTC Control Insp | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Counter Readings | LTC Operations Since Last Insp | 245 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Counter Readings | LTC As Left Counter | 69283 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Counter Readings | LTC As Found Counter | 69283 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Counter Readings | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | LTCC000812 | LTCControl | 463-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | LTCC000812 | LTCControl | 463-2 | LTC Control Insp | All Connections OK? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | LTCC000812 | LTCControl | 463-2 | LTC Control Insp | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | LTCC000812 | LTCControl | 463-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | LTCC000812 | LTCControl | 463-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | LTCC000812 | LTCControl | 463-2 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | LTCC000812 | LTCControl | 463-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | LTCC000812 | LTCControl | 463-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Counter Readings | LTC As Left Counter | 78868 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Counter Readings | LTC As Found Counter | 78868 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Counter Readings | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Counter Readings | LTC Operations Since Last Insp | 395 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 135.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Readings | Winding Temp Present | 50 | °C |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Readings | Winding Temp Max | 60 | °C |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Readings | Totalizer Meter Reading | .8450 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Readings | Oil Temp Present | 50 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Readings | LTC Totalizer Reading | 20280.00 | kw |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Readings | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | YD000394 | Yard | 463-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | YD000394 | Yard | 463-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | YD000394 | Yard | 463-Yard | Yard Patrol Inspection | Ambient Temp | 75 | °F |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | YD000394 | Yard | 463-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | YD000394 | Yard | 463-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | YD000394 | Yard | 463-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | YD000394 | Yard | 463-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | YD000394 | Yard | 463-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | YD000394 | Yard | 463-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | YD000394 | Yard | 463-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | YD000394 | Yard | 463-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | YD000394 | Yard | 463-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | YD000394 | Yard | 463-Yard | Yard Patrol Inspection | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Operations Counter AL | 192 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Operations Counter AF | 192 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | General Comments | | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | 9 Month Operations VCB New | 16 | |
| 4/5/2023 15:21 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | 9 Month Operations | 16 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | General Comments | | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Operations Counter AF | 231 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Operations Counter AL | 231 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Amps C Ø | 572.0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Amps B Ø | 560.0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Amps A Ø | 565.0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | 9 Month Operations | 2 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | General Comments | | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Operations Counter AL | 188 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Operations Counter AF | 188 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | 9 Month Operations | 2 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Amps C Ø | 69.0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Amps A Ø | 116.0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Amps B Ø | 119.0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Amps A Ø | 132.0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Amps B Ø | 136.0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Amps C Ø | 149.0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | 9 Month Operations | 2 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | General Comments | | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Operations Counter AF | 182 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Operations Counter AL | 182 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Amps C Ø | 191.0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Amps B Ø | 193.0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Amps A Ø | 183.0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | General Comments | | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Operations Counter AF | 201 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | 9 Month Operations | 2 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Operations Counter AL | 201 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Readings | Totalizer Meter Reading | .9162 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 8000 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Readings | Oil Temp Present | 50 | °C |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Readings | LTC Totalizer Reading | 7329.60 | kw |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Readings | General Comments | | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Counter Readings | LTC Operations Since Last Insp | 604 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Counter Readings | General Comments | | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Counter Readings | LTC As Found Counter | 70288 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Counter Readings | LTC As Left Counter | 70288 | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | LTCC000780 | LTCControl | 875-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | LTCC000780 | LTCControl | 875-1 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | LTCC000780 | LTCControl | 875-1 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | LTCC000780 | LTCControl | 875-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | LTCC000780 | LTCControl | 875-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | LTCC000780 | LTCControl | 875-1 | LTC Control Insp | General Comments | | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | LTCC000780 | LTCControl | 875-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | LTCC000780 | LTCControl | 875-1 | LTC Control Insp | All Connections OK? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BCH000548 | Charger | 875-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BCH000548 | Charger | 875-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BCH000548 | Charger | 875-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BCH000548 | Charger | 875-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.6 | amps |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BCH000548 | Charger | 875-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | BCH000548 | Charger | 875-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | General Comments | | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | General Comments | | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | YD000353 | Yard | 875-Yard | Yard Patrol Inspection | Ambient Temp | 70 | °F |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | YD000353 | Yard | 875-Yard | Yard Patrol Inspection | General Comments | | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | YD000353 | Yard | 875-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | YD000353 | Yard | 875-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | YD000353 | Yard | 875-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | YD000353 | Yard | 875-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | YD000353 | Yard | 875-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | YD000353 | Yard | 875-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | YD000353 | Yard | 875-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | YD000353 | Yard | 875-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | YD000353 | Yard | 875-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | YD000353 | Yard | 875-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/5/2023 14:55 | Distribution | Procter and Gamble Quarterly Inspection | YD000353 | Yard | 875-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 89 | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 92 | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 5.5 | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 77 | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.3 | volts |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 167859 | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 128507 | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.7 | volts |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 1211 | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Readings | Oil Temp Max | 33 | °C |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Readings | Oil Temp Present | 33 | °C |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Non LTC Totalizer Reading | 125.64 | kw |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Readings | Totalizer Meter Reading | .2094 | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Readings | Totalizer Meter Multiplier | 600 | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Readings | Oil Temp Present | 34 | °C |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Readings | Oil Temp Max | 34 | °C |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Readings | General Comments | | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Readings | General Comments | | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Readings | Oil Temp Max | 37 | °C |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Readings | Oil Temp Present | 36 | °C |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 132.0 | VDC |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BCH000306 | Charger | Retired Distribution | Battery Charger Patrol Insp | General Comments | | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BCH000306 | Charger | Retired Distribution | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BCH000306 | Charger | Retired Distribution | Battery Charger Patrol Insp | Battery Charger Current | .9 | amps |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BCH000306 | Charger | Retired Distribution | Battery Charger Patrol Insp | As Left Float Voltage | 132.6 | VDC |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BCH000306 | Charger | Retired Distribution | Battery Charger Patrol Insp | As Found Float Voltage | 132.6 | VDC |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | General Comments | BG T, AB | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Operations Counter AF | 245 | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Operations Counter AL | 245 | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Operations This Read Vac | 2 | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | 9 Month Operations | 3 | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Fault Operations B Ø | 1 | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Fault Adjusted Amps B Phase V | 2.12 | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Fault Adjusted Amps A Phase V | 2.12 | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | General Comments | | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Readings | Winding Temp Max | 48 | °C |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Readings | Winding Temp Present | 40 | °C |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Readings | General Comments | | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Readings | Top Oil Temperature Max | 49 | °C |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Readings | Top Oil Temperature Present | 40 | °C |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | General Comments | | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | YD000013 | Yard | 342-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | YD000013 | Yard | 342-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | YD000013 | Yard | 342-Yard | Yard Patrol Inspection | General Comments | | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | YD000013 | Yard | 342-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | YD000013 | Yard | 342-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | YD000013 | Yard | 342-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | YD000013 | Yard | 342-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | YD000013 | Yard | 342-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | YD000013 | Yard | 342-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | YD000013 | Yard | 342-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | YD000013 | Yard | 342-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | YD000013 | Yard | 342-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/5/2023 15:23 | Distribution | Rocky Fork Quarterly Inspection | YD000013 | Yard | 342-Yard | Yard Patrol Inspection | Ambient Temp | 0 | °F |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1100 | psi |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | General Comments | | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | General Comments | | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | General Comments | | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | General Comments | | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | Ambient Temp | 81 | °F |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/5/2023 14:04 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.4 | volts |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Regulator As Left Counter | 824868 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Regulator As Left Counter | 164249 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Regulator As Left Counter | 148068 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Readings | Totalizer Meter Reading | .3264 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Readings | Oil Temp Max | 60 | °C |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 2350.08 | kw |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | LTCC000676 | LTCControl | 557-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | LTCC000676 | LTCControl | 557-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | LTCC000676 | LTCControl | 557-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | LTCC000676 | LTCControl | 557-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | LTCC000676 | LTCControl | 557-1 | LTC Control Insp | General Comments | | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | LTCC000676 | LTCControl | 557-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | LTCC000676 | LTCControl | 557-1 | LTC Control Insp | All Connections OK? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | LTCC000676 | LTCControl | 557-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | LTCC000676 | LTCControl | 557-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Counter Readings | General Comments | | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Counter Readings | LTC As Found Counter | 377487 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Counter Readings | LTC As Left Counter | 377498 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Counter Readings | LTC Operations Since Last Insp | 687 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Readings | Oil Temp Max | 44 | °C |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Readings | Totalizer Meter Reading | .1350 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Readings | LTC Totalizer Reading | 648.00 | kw |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Readings | General Comments | | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 4 | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 4 | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 5.3 | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 6.8 | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 20 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BCH001347 | Charger | 557-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 3.000 | millivolts |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BCH001347 | Charger | 557-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BCH001347 | Charger | 557-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BCH001347 | Charger | 557-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.2 | amps |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BCH001347 | Charger | 557-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BCH001347 | Charger | 557-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BCH001347 | Charger | 557-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BCH001347 | Charger | 557-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.2 | VDC |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.3 | VDC |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Operations Counter AL | 185 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Operations This Read Vac | 1 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Switching Operations | 1 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Operations Counter AF | 184 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | General Comments | BFTC | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Amps C Ø | 0.0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Amps B Ø | 0.0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Amps A Ø | 0.0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | 9 Month Operations VCB New | 1 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | 9 Month Operations | 2 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | 9 Month Operations | 0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Amps A Ø | 112.0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Amps B Ø | 82.0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Amps C Ø | 96.0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Operations Counter AL | 211 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Operations Counter AF | 210 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | General Comments | BFTC | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Switching Operations | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Amps C Ø | 0.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Amps B Ø | 0.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Amps A Ø | 0.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | 9 Months Operations | 2 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | 9 Month Ops New | 2 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Operations Counter AF | 106 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Operations Counter AL | 106 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Operations This Read AM | 0 | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 199 | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 127 | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0.0 | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 445 | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | 9 Month Operations | 1 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Switching Operations | 1 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Operations This Read Vac | 1 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Operations Counter AL | 242 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Operations Counter AF | 241 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Amps C Ø | 3.0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | General Comments | BFTC | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Amps B Ø | 16.0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Amps A Ø | 1.0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.2 | volts |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Operations This Read Vac | 2 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Operations Counter AL | 186 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Operations Counter AF | 186 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | General Comments | | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Fault Operations Ground | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Fault Operations C Ø | 1 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Fault Operations B Ø | 1 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Fault Adjusted Amps C Phase V | 5.07 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Fault Adjusted Amps B Phase V | 5.07 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Amps C Ø | 78.0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Amps B Ø | 103.0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Amps A Ø | 113.0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | 9 Month Operations | 2 | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Current Tap Position | 2R | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Min Tap Position | 4L | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 125.2 | volts |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 127301 | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 380538 | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.4 | volts |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | General Comments | | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | General Comments | | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | General Comments | | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | YD000032 | Yard | 557-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | YD000032 | Yard | 557-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | YD000032 | Yard | 557-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | YD000032 | Yard | 557-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | YD000032 | Yard | 557-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | YD000032 | Yard | 557-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | YD000032 | Yard | 557-Yard | Yard Patrol Inspection | General Comments | | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | YD000032 | Yard | 557-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | YD000032 | Yard | 557-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | YD000032 | Yard | 557-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | YD000032 | Yard | 557-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | YD000032 | Yard | 557-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/5/2023 13:50 | Distribution | Harlan Quarterly Inspection | YD000032 | Yard | 557-Yard | Yard Patrol Inspection | Ambient Temp | 80 | °F |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Readings | General Comments | | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 339.84 | kw |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Readings | Oil Temp Max | 38 | °C |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Readings | Oil Temp Present | 38 | °C |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .1416 | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.8 | psi |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 97.50 | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Readings | Oil Temp Present | 41 | °C |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Regulator As Left Counter | 155920 | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | General Comments | | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | General Comments | | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | YD000111 | Yard | 383-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | YD000111 | Yard | 383-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | YD000111 | Yard | 383-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | YD000111 | Yard | 383-Yard | Yard Patrol Inspection | Ambient Temp | 78 | °F |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | YD000111 | Yard | 383-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | YD000111 | Yard | 383-Yard | Yard Patrol Inspection | General Comments | | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | YD000111 | Yard | 383-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | YD000111 | Yard | 383-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | YD000111 | Yard | 383-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | YD000111 | Yard | 383-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | YD000111 | Yard | 383-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/5/2023 13:45 | Distribution | Lipps Quarterly Inspection | YD000111 | Yard | 383-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Readings | Oil Temp Max | 56 | °C |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Readings | Oil Temp Present | 42 | °C |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Regulator As Left Counter | 152340 | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Regulator As Left Counter | 163559 | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Readings | Totalizer Meter Reading | .8910 | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Readings | Oil Temp Present | 42 | °C |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Readings | Oil Temp Max | 52 | °C |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Readings | Non LTC Totalizer Reading | 2138.40 | kw |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Readings | General Comments | | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Amps C Ø | 0.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Operations Counter AF | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Operations Counter AL | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Switching Operations | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | General Comments | NO BREAKER IN CUBICLE | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | 9 Months Operations | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Amps A Ø | 0.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Amps B Ø | 0.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Operations This Read AM | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | General Comments | corner of foundation next to house is crumbling, multiple insulators are crakced and chipped in the steel | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | General Comments | | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Max Tap Position | 1L | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Regulator As Left Counter | 64012 | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | YD000093 | Yard | 493-Yard | Yard Patrol Inspection | General Comments | | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | YD000093 | Yard | 493-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | YD000093 | Yard | 493-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | YD000093 | Yard | 493-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | YD000093 | Yard | 493-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | YD000093 | Yard | 493-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | YD000093 | Yard | 493-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | YD000093 | Yard | 493-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | YD000093 | Yard | 493-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | YD000093 | Yard | 493-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | YD000093 | Yard | 493-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/5/2023 13:28 | Distribution | Benham Quarterly Inspection | YD000093 | Yard | 493-Yard | Yard Patrol Inspection | Ambient Temp | 80 | °F |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Patrol Inspection | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Operations Counter AF | 369 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Operations Counter AL | 369 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Operations This Read AM | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Switching Operations | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Amps C Ø | 181.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Amps B Ø | 170.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Amps A Ø | 181.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | 9 Months Operations | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Readings | Totalizer Meter Reading | .6784 | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 300 | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Readings | Oil Temp Present | 39 | °C |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Readings | Oil Temp Max | 39 | °C |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 203.52 | kw |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Readings | General Comments | | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Switching Operations | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Operations This Read AM | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Operations Counter AL | 212 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Operations Counter AF | 212 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Amps C Ø | 112.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Amps B Ø | 118.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Amps A Ø | 114.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | 9 Months Operations | 0 | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 97.50 | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | RC001331 | RecloserHydraulic | 861-1523 A | Recloser Hydraulic Patrol Inspection | Amps A Ø | 5.3 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | RC001331 | RecloserHydraulic | 861-1523 A | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | RC001331 | RecloserHydraulic | 861-1523 A | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | RC001331 | RecloserHydraulic | 861-1523 A | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | RC001331 | RecloserHydraulic | 861-1523 A | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | RC001331 | RecloserHydraulic | 861-1523 A | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | RC001331 | RecloserHydraulic | 861-1523 A | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | RC001331 | RecloserHydraulic | 861-1523 A | Recloser Hydraulic Patrol Inspection | Operations Counter | 42 | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | RC001331 | RecloserHydraulic | 861-1523 A | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | RC001331 | RecloserHydraulic | 861-1523 A | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Patrol Inspection | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Patrol Inspection | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Operations This Read AM | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Switching Operations | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Operations Counter AF | 61 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Amps C Ø | 390.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Amps B Ø | 365.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Operations Counter AL | 61 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | 9 Month Ops New | 2 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Amps A Ø | 391.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | 9 Months Operations | 2 | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | WX0478 | RecloserHydraulic | 861-1524 A | Recloser Hydraulic Patrol Inspection | Amps A Ø | 12.7 | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | WX0478 | RecloserHydraulic | 861-1524 A | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | WX0478 | RecloserHydraulic | 861-1524 A | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | WX0478 | RecloserHydraulic | 861-1524 A | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | WX0478 | RecloserHydraulic | 861-1524 A | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | WX0478 | RecloserHydraulic | 861-1524 A | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | WX0478 | RecloserHydraulic | 861-1524 A | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | WX0478 | RecloserHydraulic | 861-1524 A | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | WX0478 | RecloserHydraulic | 861-1524 A | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | WX0478 | RecloserHydraulic | 861-1524 A | Recloser Hydraulic Patrol Inspection | Operations Counter | 298 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Amps C Ø | 190.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | 9 Months Operations | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Switching Operations | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Amps B Ø | 81.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Operations This Read AM | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Operations Counter AL | 190 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Amps A Ø | 100.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Operations Counter AF | 190 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Readings | Totalizer Meter Reading | .5524 | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Readings | General Comments | | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Readings | Non LTC Totalizer Reading | 2651.52 | kw |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 100.00 | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Readings | Oil Temp Max | 52 | °C |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Patrol Inspection | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | General Comments | BFTC | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Amps C Ø | 12.0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Amps B Ø | 12.0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Amps A Ø | 12.0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | 9 Month Operations | 3 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Switching Operations | 1 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Operations Counter AF | 467 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Operations Counter AL | 468 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Operations This Read Vac | 1 | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | General Comments | spare fuse deteriorated | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | General Comments | | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | Ambient Temp | 79 | °F |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | General Comments | | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/5/2023 13:18 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Patrol Inspection | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | PF000306 | PowerFuse | SY-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | PF000306 | PowerFuse | SY-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | PF000307 | PowerFuse | SY-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | PF000307 | PowerFuse | SY-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Switching Operations | 1 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Operations This Read Vac | 1 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Operations Counter AL | 356 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Operations Counter AF | 355 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | 9 Month Operations | 2 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Amps A Ø | 0.0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Amps B Ø | 0.0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Amps C Ø | 0.0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | General Comments | BFTC | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Operations Counter AL | 258 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Operations Counter AF | 258 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Amps C Ø | 125.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Amps B Ø | 152.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Amps A Ø | 133.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | 9 Month Operations | 3 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Counter Readings | General Comments | | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Counter Readings | LTC As Found Counter | 144648 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Counter Readings | LTC As Left Counter | 144657 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Counter Readings | LTC Operations Since Last Insp | 452 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | LTCC000894 | LTCControl | 032-6 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | LTCC000894 | LTCControl | 032-6 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | LTCC000894 | LTCControl | 032-6 | LTC Control Insp | General Comments | | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | LTCC000894 | LTCControl | 032-6 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | LTCC000894 | LTCControl | 032-6 | LTC Control Insp | All Connections OK? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | LTCC000894 | LTCControl | 032-6 | LTC Control Insp | LTC Output Voltage Level | 124.1 | VAC |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | LTCC000894 | LTCControl | 032-6 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | LTCC000894 | LTCControl | 032-6 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Amps A Ø | 99.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Amps B Ø | 96.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Amps C Ø | 109.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | 9 Month Operations | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Operations Counter AF | 191 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Operations Counter AL | 191 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Readings | Totalizer Meter Reading | .3510 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Readings | Oil Temp Present | 38 | °C |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Readings | Oil Temp Max | 39 | °C |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Readings | LTC Totalizer Reading | 3369.60 | kw |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Readings | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Switching Operations | 4 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Operations This Read Vac | 4 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Operations Counter AL | 200 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Operations Counter AF | 200 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Amps C Ø | 117.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Amps B Ø | 106.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Amps A Ø | 111.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | 9 Month Operations | 4 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Fans Operational? | n | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | General Comments | One fan not working | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | 9 Month Operations | 5 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Amps A Ø | 344.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Amps B Ø | 348.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Amps C Ø | 336.0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Operations Counter AF | 199 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Operations Counter AL | 199 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Readings | Unknown Operations | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Readings | Switching Operations | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Readings | Operations This Read SF6 | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Readings | Operations Counter AL | 94 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Readings | Operations Counter AF | 94 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Readings | 9 Month Operations GCB New | 2 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Readings | Fault Operations | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Readings | Num Operations Last 9 Months | 2 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Readings | General Comments | | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | Ambient Temperature | 77 | °F |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | General Comments | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | SF6 Pressure | 69 | psi |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | PF000305 | PowerFuse | SY-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | PF000305 | PowerFuse | SY-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | PF000304 | PowerFuse | SY-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | PF000304 | PowerFuse | SY-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | CHANGED BLANKS TO FILTERS | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | 9 Month Operations | 2 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Amps A Ø | 64.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Amps B Ø | 54.0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Amps C Ø | 57.0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | General Comments | BFTC | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Operations Counter AF | 240 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Operations Counter AL | 241 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Operations This Read Vac | 1 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Switching Operations | 1 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Switching Operations | 1 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Operations This Read Vac | 1 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Operations Counter AL | 228 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Operations Counter AF | 227 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | General Comments | BFTC | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Amps C Ø | 66.0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Amps B Ø | 99.0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Amps A Ø | 78.0 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | 9 Month Operations | 2 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LTCC000485 | LTCControl | SY-TRANS 2 | LTC Control Insp | All Connections OK? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LTCC000485 | LTCControl | SY-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LTCC000485 | LTCControl | SY-TRANS 2 | LTC Control Insp | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LTCC000485 | LTCControl | SY-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 28 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 15L | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 7L | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 10L | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Counter Readings | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 252991 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 252991 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 45 | °C |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 45 | °C |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 40 | °C |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 40 | °C |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 40 | °C |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 40 | °C |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Regulator As Left Counter | 32100 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Regulator As Left Counter | 36839 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Regulator As Left Counter | 32537 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Regulator As Left Counter | 115215 | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Readings | Winding Temp Max | 38 | °C |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Readings | Winding Temp Present | 38 | °C |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.2138 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Readings | Oil Temp Present | 36 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Readings | Oil Temp Max | 36 | °C |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 10.00 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 8739.36 | kw |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Readings | General Comments | | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Min Tap Position | 4L | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Reg Output Voltage Level | 124.9 | volts |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Regulator As Left Counter | 25557 | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 15.00 | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 13:16 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LTCC000328 | LTCControl | SY-TRANS 1 | LTC Control Insp | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LTCC000328 | LTCControl | SY-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LTCC000328 | LTCControl | SY-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LTCC000328 | LTCControl | SY-TRANS 1 | LTC Control Insp | All Connections OK? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 203 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | Neutral | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 8L | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 87730 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 87730 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Counter Readings | General Comments | | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Regulator As Left Counter | 1016 | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Reg Output Voltage Level | 124.9 | volts |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Min Tap Position | 4L | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Readings | Oil Temp Present | 39 | °C |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Readings | Oil Temp Max | 39 | °C |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 2347.20 | kw |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Readings | General Comments | | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .4890 | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -1.5 | psi |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | X0079 | RecloserHydraulic | 912-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | X0079 | RecloserHydraulic | 912-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Operations Counter | 525 | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | X0079 | RecloserHydraulic | 912-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | X0079 | RecloserHydraulic | 912-Offline-Distribution | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | X0079 | RecloserHydraulic | 912-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | X0079 | RecloserHydraulic | 912-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | X0079 | RecloserHydraulic | 912-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | X0079 | RecloserHydraulic | 912-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | X0079 | RecloserHydraulic | 912-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | X0079 | RecloserHydraulic | 912-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Amps C Ø | 68.5 | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | X0079 | RecloserHydraulic | 912-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | X0079 | RecloserHydraulic | 912-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Amps B Ø | 69.8 | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | X0079 | RecloserHydraulic | 912-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Amps A Ø | 52.5 | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | WX0333 | RecloserHydraulic | 827-1553 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 13.3 | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | WX0333 | RecloserHydraulic | 827-1553 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 16.6 | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | WX0333 | RecloserHydraulic | 827-1553 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 8.1 | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | WX0333 | RecloserHydraulic | 827-1553 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | WX0333 | RecloserHydraulic | 827-1553 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | WX0333 | RecloserHydraulic | 827-1553 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | WX0333 | RecloserHydraulic | 827-1553 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | WX0333 | RecloserHydraulic | 827-1553 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | WX0333 | RecloserHydraulic | 827-1553 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | WX0333 | RecloserHydraulic | 827-1553 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | WX0333 | RecloserHydraulic | 827-1553 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | WX0333 | RecloserHydraulic | 827-1553 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | WX0333 | RecloserHydraulic | 827-1553 | Recloser Hydraulic Patrol Inspection | Operations Counter | 809 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 45 | °C |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 45 | °C |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 45 | °C |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 45 | °C |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 45 | °C |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 45 | °C |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | General Comments | Broken porcelain on middle phase fuse holder. Xfmr fuses are starting to fray. | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | n | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | General Comments | fence is connected to neighbor fence | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | General Comments | | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | Ambient Temp | 80 | °F |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/5/2023 13:03 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | DOES NOT HAVE A NITROGEN BOTTLE | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | 9 Month Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Operations Counter AL | 167 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Operations Counter AF | 167 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Amps C Ø | 285.0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Amps B Ø | 260.0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Amps A Ø | 310.0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | 9 Month Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Operations Counter AF | 202 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Operations Counter AL | 202 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Amps A Ø | 0.0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Amps B Ø | 0.0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Amps C Ø | 0.0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | ST000846 | Structure | 364-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | ST000846 | Structure | 364-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | ST000846 | Structure | 364-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | ST000846 | Structure | 364-Structure | Structure Patrol Inspection | General Comments | | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | ST000846 | Structure | 364-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | ST000846 | Structure | 364-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | ST000846 | Structure | 364-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | ST000846 | Structure | 364-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | ST000846 | Structure | 364-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | General Comments | Brush needs cleared around fence | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | n | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | 9 Month Operations | 5 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Amps A Ø | 80.0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Amps B Ø | 50.0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Amps C Ø | 80.0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Operations This Read Vac | 3 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Operations Counter AL | 203 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Operations Counter AF | 203 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Fault Adjusted Amps C Phase V | 38.70 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Fault Operations C Ø | 3 | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | YD000120 | Yard | 364-Yard | Yard Patrol Inspection | General Comments | | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | YD000120 | Yard | 364-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | YD000120 | Yard | 364-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | YD000120 | Yard | 364-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | YD000120 | Yard | 364-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | YD000120 | Yard | 364-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | YD000120 | Yard | 364-Yard | Yard Patrol Inspection | Ambient Temp | 78 | °F |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | YD000120 | Yard | 364-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | YD000120 | Yard | 364-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | YD000120 | Yard | 364-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | YD000120 | Yard | 364-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/5/2023 12:53 | Distribution | Critical Fork Quarterly Inspection | YD000120 | Yard | 364-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Station Ground Set On Site? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Restroom Clean & OK? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | General Comments | high sewage alarm | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Follow-up Action Required? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | 9 Month Operations | 7 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Amps A Ø | 255.0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Amps B Ø | 230.0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Amps C Ø | 250.0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Operations This Read Vac | 3 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Operations Counter AL | 232 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Operations Counter AF | 232 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Fault Adjusted Amps B Phase V | 38.70 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Fault Operations B Ø | 3 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BCH000098 | Charger | SY-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BCH000098 | Charger | SY-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 4.5 | amps |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BCH000098 | Charger | SY-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 135.0 | VDC |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BCH000098 | Charger | SY-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 135.0 | VDC |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BCH000098 | Charger | SY-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BCH000098 | Charger | SY-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BCH000098 | Charger | SY-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BCH000098 | Charger | SY-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Fault Operations B Ø | 3 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Fault Adjusted Amps C Phase V | 38.70 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Fault Adjusted Amps B Phase V | 38.70 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Fault Operations C Ø | 3 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Amps C Ø | 30.0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Amps B Ø | 50.0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Amps A Ø | 25.0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | 9 Month Operations | 8 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Operations This Read Vac | 6 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Operations Counter AF | 214 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Operations Counter AL | 214 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BAT001591 | Battery | SY-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BAT001591 | Battery | SY-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BAT001591 | Battery | SY-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BAT001591 | Battery | SY-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BAT001591 | Battery | SY-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BAT001591 | Battery | SY-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BAT001591 | Battery | SY-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BAT001591 | Battery | SY-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BAT001591 | Battery | SY-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BAT001591 | Battery | SY-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BAT001591 | Battery | SY-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | BAT001591 | Battery | SY-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Ambient Temp | 70 | °F |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | General Comments | ok | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Operations Counter AF | 202 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Operations Counter AL | 202 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | 9 Month Operations | 4 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Amps A Ø | 160.0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Amps B Ø | 160.0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Amps C Ø | 130.0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | General Comments | | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/5/2023 13:46 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Operations This Read Vac | 4 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Operations Counter AL | 213 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Operations Counter AF | 213 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Amps A Ø | 80.0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Amps B Ø | 90.0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Amps C Ø | 85.0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Fault Adjusted Amps B Phase V | 25.80 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Fault Adjusted Amps C Phase V | 25.80 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Fault Operations B Ø | 2 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Fault Operations C Ø | 2 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | 9 Month Operations | 12 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | 9 Month Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Amps A Ø | 350.0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Amps B Ø | 350.0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Amps C Ø | 350.0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Operations Counter AL | 164 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Operations Counter AF | 164 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BAT001668 | Battery | 498-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BAT001668 | Battery | 498-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BAT001668 | Battery | 498-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.0 | VDC |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BAT001668 | Battery | 498-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BAT001668 | Battery | 498-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 79 | °F |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BAT001668 | Battery | 498-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BAT001668 | Battery | 498-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BAT001668 | Battery | 498-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BAT001668 | Battery | 498-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BAT001668 | Battery | 498-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BAT001668 | Battery | 498-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BAT001668 | Battery | 498-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 28.1 | VDC |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BCH001098 | Charger | 498-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .700 | millivolts |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BCH001098 | Charger | 498-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.1 | VDC |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BCH001098 | Charger | 498-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.1 | VDC |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BCH001098 | Charger | 498-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .7 | amps |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BCH001098 | Charger | 498-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BCH001098 | Charger | 498-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BCH001098 | Charger | 498-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BCH001098 | Charger | 498-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Max Tap Position | 5L | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 49155 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Max Tap Position | 5L | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 26257 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Current Tap Position | 9L | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 43357 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Readings | General Comments | | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3240.00 | kw |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Readings | Oil Temp Present | 45 | °C |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.3500 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | 9 Month Operations | 1 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Amps A Ø | 27.0 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Amps B Ø | 29.0 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Amps C Ø | 17.0 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | General Comments | | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Operations Counter AF | 194 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Operations Counter AL | 194 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | 9 Month Operations | 2 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Amps A Ø | 51.0 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Amps B Ø | 53.0 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Amps C Ø | 59.0 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | General Comments | | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Operations Counter AF | 229 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Operations Counter AL | 229 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | General Comments | | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | General Comments | | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | Ambient Temp | 79 | °F |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | General Comments | | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/5/2023 12:41 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Readings | General Comments | | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Readings | General Comments | | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 65.00 | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Readings | Oil Temp Max | 89 | °C |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 70.00 | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 107.50 | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 2400 | psi |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | General Comments | New Nitro Bottle installed | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Readings | General Comments | | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 100.00 | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Readings | Top Oil Temperature Max | 42 | °C |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Readings | Top Oil Temperature Present | 39 | °C |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Readings | Winding Temp Present | 40 | °C |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Readings | Winding Temp Max | 45 | °C |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | All Connections OK? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | Negative DC Ground | 68.9 | VDC |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | Positive DC Ground | 65.9 | VDC |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | General Comments | | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | BCH001146 | Charger | 191-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | BCH001146 | Charger | 191-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | BCH001146 | Charger | 191-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 135.0 | VDC |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | BCH001146 | Charger | 191-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 135.0 | VDC |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | BCH001146 | Charger | 191-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | 9 Month Operations | 2 | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Operations Counter AL | 195 | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Operations Counter AF | 195 | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | General Comments | | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Amps A Ø | 80.0 | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Amps B Ø | 80.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Amps C Ø | 80.0 | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | General Comments | | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | General Comments | No fuses. Has xfmr breaker. | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | n | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | General Comments | | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | Ambient Temp | 80 | °F |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | General Comments | | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/5/2023 12:30 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Broom on Site? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Door Alarms OK? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Floor Swept? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Follow-up Action Required? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | General Comments | SEWEGAG HI LEVEL ALARM IS IN. | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Trash Emptied? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BAT001686 | Battery | 782-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BAT001686 | Battery | 782-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BAT001686 | Battery | 782-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.7 | VDC |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BAT001686 | Battery | 782-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 28.0 | VDC |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BAT001686 | Battery | 782-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BAT001686 | Battery | 782-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BAT001686 | Battery | 782-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BAT001686 | Battery | 782-Battery Bank | Battery Patrol Inspection | Bat Volt 1Min After Chgr Trip | 0.0 | VDC |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BAT001686 | Battery | 782-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 79 | °F |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BAT001686 | Battery | 782-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BAT001686 | Battery | 782-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BAT001686 | Battery | 782-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BAT001686 | Battery | 782-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BCH001219 | Charger | 782-Battery Bank | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.100 | millivolts |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BCH001219 | Charger | 782-Battery Bank | Battery Charger Patrol Insp | As Found Float Voltage | 54.8 | VDC |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BCH001219 | Charger | 782-Battery Bank | Battery Charger Patrol Insp | As Left Float Voltage | 54.8 | VDC |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BCH001219 | Charger | 782-Battery Bank | Battery Charger Patrol Insp | Battery Charger Current | .6 | amps |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BCH001219 | Charger | 782-Battery Bank | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BCH001219 | Charger | 782-Battery Bank | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BCH001219 | Charger | 782-Battery Bank | Battery Charger Patrol Insp | General Comments | | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BCH001219 | Charger | 782-Battery Bank | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 168617 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.6 | volts |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 70269 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 100518 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.2 | volts |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Max Tap Position | 1L | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 380.00 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 2369.28 | kw |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Readings | General Comments | | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .7404 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 397.50 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | 9 Month Operations | 4 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Operations This Read Vac | 1 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Operations Counter AL | 194 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Operations Counter AF | 194 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Amps A Ø | 96.0 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Amps B Ø | 121.0 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Amps C Ø | 113.0 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Fault Adjusted Amps B Phase V | 6.55 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | General Comments | B-C on 308-23 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Fault Operations B Ø | 1 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Unknown Operations | 2 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Amps A Ø | 70.0 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Amps B Ø | 100.0 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Amps C Ø | 90.0 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Operations This Read Vac | 2 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Operations Counter AL | 280 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Operations Counter AF | 280 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | General Comments | | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | 9 Month Operations | 5 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Fault Adjusted Amps A Phase V | 13.10 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Fault Adjusted Amps B Phase V | 13.10 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Fault Adjusted Amps C Phase V | 13.10 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | General Comments | | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | General Comments | | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | YD000233 | Yard | 782-Yard | Yard Patrol Inspection | Ambient Temp | 79 | °F |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | YD000233 | Yard | 782-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | YD000233 | Yard | 782-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | YD000233 | Yard | 782-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | YD000233 | Yard | 782-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | YD000233 | Yard | 782-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | YD000233 | Yard | 782-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | YD000233 | Yard | 782-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | YD000233 | Yard | 782-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | YD000233 | Yard | 782-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | YD000233 | Yard | 782-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | YD000233 | Yard | 782-Yard | Yard Patrol Inspection | General Comments | | |
| 4/5/2023 11:57 | Distribution | Mortons Gap Quarterly Inspection | YD000233 | Yard | 782-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Operations This Read AM | 1 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Operations Counter AL | 809 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | 9 Month Ops New | 1 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | 9 Months Operations | 2 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Amps A Ø | 0.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Amps B Ø | 0.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Amps C Ø | 0.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | General Comments | | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Operations Counter AF | 809 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Switching Operations | 1 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Switching Operations | 1 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Operations This Read AM | 5 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Operations Counter AL | 841 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Operations Counter AF | 841 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | General Comments | A & B Phase IOC | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Fault Operations B Ø | 2 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Fault Operations A Ø | 2 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Fault Adjusted Amps B Phase AM | 22.36 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Fault Adjusted Amps A Phase AM | 22.36 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Amps C Ø | 0.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Amps B Ø | 0.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Amps A Ø | 0.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | 9 Months Operations | 6 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | 9 Month Ops New | 1 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | General Comments | | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Patrol Inspection | General Comments | | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Amps A Ø | 50.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Amps B Ø | 50.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Amps C Ø | 50.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Fault Adjusted Amps A Phase AM | 22.36 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Fault Adjusted Amps B Phase AM | 22.36 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Fault Adjusted Amps C Phase AM | 22.36 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Fault Operations A Ø | 2 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Fault Operations B Ø | 2 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Fault Operations C Ø | 2 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | General Comments | A,  B & C Phase IOC | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Operations Counter AF | 1430 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Operations Counter AL | 1430 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Operations This Read AM | 6 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Switching Operations | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | 9 Months Operations | 9 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | 9 Month Ops New | 3 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Patrol Inspection | General Comments | | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Amps C Ø | 200.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Amps B Ø | 200.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Amps A Ø | 200.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | 9 Month Ops New | 2 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | 9 Months Operations | 2 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | General Comments | | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Operations Counter AF | 794 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Operations Counter AL | 794 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Operations This Read AM | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Switching Operations | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Patrol Inspection | General Comments | | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Switching Operations | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Operations This Read AM | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Operations Counter AL | 556 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Operations Counter AF | 556 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | General Comments | | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Amps A Ø | 200.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Amps B Ø | 200.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Amps C Ø | 200.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | 9 Month Ops New | 2 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | 9 Months Operations | 2 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Patrol Inspection | General Comments | | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | PF000093 | PowerFuse | CO-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | PF000093 | PowerFuse | CO-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Counter Readings | General Comments | | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 29989 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 29989 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 366 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 41 | °C |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 32 | °C |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 10.00 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 54 | °C |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 30 | °C |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 53 | °C |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 30 | °C |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 53 | °C |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 30 | °C |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1700 | psi |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | PF000094 | PowerFuse | CO-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | PF000094 | PowerFuse | CO-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Amps A Ø | 120.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | 9 Month Operations | 9 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Amps B Ø | 120.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Amps C Ø | 120.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Fault Adjusted Amps A Phase V | 22.36 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Fault Adjusted Amps B Phase V | 22.36 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Fault Adjusted Amps C Phase V | 33.54 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Fault Operations A Ø | 2 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Fault Operations B Ø | 2 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Fault Operations C Ø | 3 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | General Comments | A,B, & C Phase C Phase TOC | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Operations Counter AF | 475 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Operations Counter AL | 475 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Operations This Read Vac | 7 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Operations Counter | 98 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | General Comments | BFTC | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Amps A Ø | 48.1 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Amps B Ø | 42.3 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Amps C Ø | 50.0 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0493 | RecloserHydraulic | 310-4650 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0493 | RecloserHydraulic | 310-4650 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0493 | RecloserHydraulic | 310-4650 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0493 | RecloserHydraulic | 310-4650 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0493 | RecloserHydraulic | 310-4650 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0493 | RecloserHydraulic | 310-4650 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0493 | RecloserHydraulic | 310-4650 | Recloser Hydraulic Patrol Inspection | Operations Counter | 396 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0493 | RecloserHydraulic | 310-4650 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0493 | RecloserHydraulic | 310-4650 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0493 | RecloserHydraulic | 310-4650 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 14.4 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0493 | RecloserHydraulic | 310-4650 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 13.3 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0493 | RecloserHydraulic | 310-4650 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 17.6 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | MX0493 | RecloserHydraulic | 310-4650 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Switching Operations | 3 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Operations This Read Vac | 3 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Operations Counter AL | 158 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Operations Counter AF | 159 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | General Comments | | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Amps C Ø | 50.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Amps B Ø | 40.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Amps A Ø | 40.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | 9 Month Operations | 8 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Readings | Totalizer Meter Reading | .8118 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Readings | Oil Temp Present | 37 | °C |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Readings | General Comments | | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1948.32 | kw |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Readings | Oil Temp Max | 37 | °C |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 95.00 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | 9 Month Operations | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Operations Counter AL | 256 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Amps C Ø | 200.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Amps B Ø | 200.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Amps A Ø | 200.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | General Comments | | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Operations Counter AF | 256 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Regulator As Left Counter | 132915 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.7 | volts |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Regulator As Left Counter | 86269 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.0 | volts |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | 9 Month Operations | 2 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Amps A Ø | 0.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Amps B Ø | 0.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Amps C Ø | 0.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | General Comments | | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Operations Counter AF | 177 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Operations Counter AL | 177 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Operations This Read Vac | 1 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Switching Operations | 1 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.1 | volts |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Regulator As Left Counter | 165154 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | PF000091 | PowerFuse | CO-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | PF000091 | PowerFuse | CO-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | PF000092 | PowerFuse | CO-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | PF000092 | PowerFuse | CO-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 1R | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 126836 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 126836 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Counter Readings | General Comments | | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 554 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 55 | °C |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 45 | °C |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 55 | °C |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 45 | °C |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 55 | °C |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 45 | °C |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Readings | 9 Month Operations VCB New | 15 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Readings | 9 Month Operations | 15 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Readings | Amps A Ø | 0.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Readings | Operations Counter AL | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Readings | Amps B Ø | 0.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Readings | Amps C Ø | 0.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Readings | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Readings | Operations Counter AF | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1900 | psi |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | Nitrogen regulator has been removed for repair. Bottle is full. | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002177 | BreakerVacuum | DA-1237 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Readings | 9 Month Operations | 35 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Readings | 9 Month Operations VCB New | 35 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Readings | Amps A Ø | 0.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Readings | Amps B Ø | 0.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Readings | Amps C Ø | 0.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Readings | Operations Counter AL | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Readings | Operations Counter AF | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Readings | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002179 | BreakerVacuum | DA-1239 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Readings | Operations Counter AL | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Readings | Operations Counter AF | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Readings | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Readings | Amps C Ø | 0.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Readings | Amps B Ø | 0.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Readings | Amps A Ø | 0.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 21 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Readings | 9 Month Operations | 21 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002181 | BreakerVacuum | DA-12KV TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Readings | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Readings | 9 Month Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Readings | Operations Counter AF | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Readings | Operations Counter AL | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Readings | Amps A Ø | 0.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Readings | Amps B Ø | 0.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Readings | Amps C Ø | 0.0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BAT001027 | Battery | CO-Battery Bank 1 | Battery Patrol Inspection | All Connections OK? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BAT001027 | Battery | CO-Battery Bank 1 | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BAT001027 | Battery | CO-Battery Bank 1 | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BAT001027 | Battery | CO-Battery Bank 1 | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BAT001027 | Battery | CO-Battery Bank 1 | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BAT001027 | Battery | CO-Battery Bank 1 | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BAT001027 | Battery | CO-Battery Bank 1 | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BAT001027 | Battery | CO-Battery Bank 1 | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BAT001027 | Battery | CO-Battery Bank 1 | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BAT001027 | Battery | CO-Battery Bank 1 | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BAT001027 | Battery | CO-Battery Bank 1 | Battery Patrol Inspection | General Comments | | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BAT001027 | Battery | CO-Battery Bank 1 | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002178 | BreakerVacuum | DA-1238 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Readings | Operations Counter AL | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Readings | Operations Counter AF | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Readings | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Readings | Amps C Ø | 0.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Readings | Amps B Ø | 0.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Readings | Amps A Ø | 0.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Readings | 9 Month Operations | 0 | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BCH001599 | Charger | CO-Battery Charger 1 | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BCH001599 | Charger | CO-Battery Charger 1 | Battery Charger Patrol Insp | General Comments | | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BCH001599 | Charger | CO-Battery Charger 1 | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BCH001599 | Charger | CO-Battery Charger 1 | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BCH001599 | Charger | CO-Battery Charger 1 | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 2.100 | millivolts |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BCH001599 | Charger | CO-Battery Charger 1 | Battery Charger Patrol Insp | Battery Charger Current | 5.4 | amps |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BCH001599 | Charger | CO-Battery Charger 1 | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 4/5/2023 12:05 | Distribution | Collins Quarterly Inspection | BCH001599 | Charger | CO-Battery Charger 1 | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 105.00 | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 13:16 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | PF000101 | PowerFuse | DX-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | PF000101 | PowerFuse | DX-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | PF000100 | PowerFuse | DX-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | PF000100 | PowerFuse | DX-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | n | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | one bad fan on noryh side, inof send to Link | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.3 | psi |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 28 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Counter Readings | General Comments | | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 7457 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 7457 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LTCC000117 | LTCControl | Retired Distribution | LTC Control Insp | General Comments | | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LTCC000117 | LTCControl | Retired Distribution | LTC Control Insp | Follow-up Action Required? | n | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LTCC000117 | LTCControl | Retired Distribution | LTC Control Insp | All Connections OK? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | 9 Month Operations | 9 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Fault Adjusted Amps C Phase V | 8.00 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Fault Operations C Ø | 1 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Amps A Ø | 300.0 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Amps B Ø | 300.0 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Amps C Ø | 300.0 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | General Comments | Inst target on C phase | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Operations Counter AF | 276 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Operations Counter AL | 284 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Operations This Read Vac | 9 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Switching Operations | 8 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Counter Readings | General Comments | | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Counter Readings | LTC As Found Counter | 56364 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Counter Readings | LTC As Left Counter | 56368 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Counter Readings | LTC Operations Since Last Insp | 1144 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | LTCC000985 | LTCControl | 310-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | LTCC000985 | LTCControl | 310-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | LTCC000985 | LTCControl | 310-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | LTCC000985 | LTCControl | 310-1 | LTC Control Insp | LTC Output Voltage Level | 123.4 | VAC |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | LTCC000985 | LTCControl | 310-1 | LTC Control Insp | All Connections OK? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | LTCC000985 | LTCControl | 310-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | LTCC000985 | LTCControl | 310-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | LTCC000985 | LTCControl | 310-1 | LTC Control Insp | General Comments | | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Needs Replaced | check oil cup |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Mechanism Patrol Inspection | General Comments | Need to move dessicant cartridge down from top of LTC Compartment. Created work order | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 55.00 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 50 | °C |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 60 | °C |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 50 | °C |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 50 | °C |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 50 | °C |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 50 | °C |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 50 | °C |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Readings | Totalizer Meter Reading | .1084 | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Readings | General Comments | | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 65.04 | kw |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 600 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 245.00 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Readings | Totalizer Meter Reading | .7010 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Readings | General Comments | | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Readings | LTC Totalizer Reading | 2243.20 | kw |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Readings | Oil Temp Max | 32 | °C |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Readings | Oil Temp Present | 32 | °C |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 4.0 | psi |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | MOD Motor Jaw Coupling | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | MOD Cabinet Internals Clean? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | MOD Cabinet Heater functional? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Interruptrs/Puffrs Visual OK? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | General Comments | | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.1 | VDC |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.5 | VDC |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 75 | °F |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | BCH001407 | Charger | 310-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | BCH001407 | Charger | 310-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | BCH001407 | Charger | 310-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | BCH001407 | Charger | 310-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | BCH001407 | Charger | 310-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | BCH001407 | Charger | 310-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | BCH001407 | Charger | 310-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | BCH001407 | Charger | 310-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .700 | millivolts |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | CH000491 | ControlHouse | 310-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | CH000491 | ControlHouse | 310-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | CH000491 | ControlHouse | 310-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | CH000491 | ControlHouse | 310-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | CH000491 | ControlHouse | 310-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | CH000491 | ControlHouse | 310-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | CH000491 | ControlHouse | 310-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | CH000491 | ControlHouse | 310-Control House | Control House Patrol Inspection | General Comments | | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | CH000491 | ControlHouse | 310-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | CH000491 | ControlHouse | 310-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | General Comments | | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Restroom Clean & OK? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | General Comments | | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ANN000087 | Annunciator | DX-Annunciator Panel | Annunciator Patrol Inspection | ESOC Received Alarm Test? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ANN000087 | Annunciator | DX-Annunciator Panel | Annunciator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ANN000087 | Annunciator | DX-Annunciator Panel | Annunciator Patrol Inspection | General Comments | | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ANN000087 | Annunciator | DX-Annunciator Panel | Annunciator Patrol Inspection | Control House Alarm Audible? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | ANN000087 | Annunciator | DX-Annunciator Panel | Annunciator Patrol Inspection | All Lights Functioning? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Ambient Temp | 80 | °F |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | General Comments | | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | General Comments | | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | General Comments | | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | General Comments | Vegetation needs cut off of back fence | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Follow-up Action Required? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Operations Counter AL | 72 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Operations Counter AF | 72 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | General Comments | | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | 9 Month Operations | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Amps A Ø | 100.0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Amps B Ø | 130.0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Amps C Ø | 120.0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | General Comments | | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/5/2023 11:39 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | Ambient Temp | 65 | °F |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Fault Operations C Ø | 2 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | General Comments | a,b,c phase ioc | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Operations Counter AF | 65 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Fault Operations B Ø | 2 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Operations Counter AL | 65 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Operations This Read Vac | 6 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Fault Operations A Ø | 2 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Fault Adjusted Amps C Phase V | 22.36 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Fault Adjusted Amps B Phase V | 22.36 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Fault Adjusted Amps A Phase V | 22.36 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Amps B Ø | 170.0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Amps C Ø | 175.0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Amps A Ø | 170.0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | 9 Month Operations | 6 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | General Comments | unable to obtain amp readings, amp meter not working | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 463 | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 93 | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0.0 | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 83 | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Surge Arrester Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Min Tap Position | 16L | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | General Comments | | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Reg Output Voltage Level | 122.5 | volts |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 200.00 | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Readings | General Comments | | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 205.00 | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Readings | General Comments | | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | General Comments | Multiple insulators have chipped and broken skirts above transformers | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | n | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | General Comments | | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Poor | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | n | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | General Comments | large washout across driveway in front of substation | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | Ambient Temp | 65 | °F |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | n | |
| 4/5/2023 11:11 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | n | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | General Comments | | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Amps A Ø | 100.0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Operations Counter AF | 76 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Operations Counter AL | 76 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Amps B Ø | 100.0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Amps C Ø | 100.0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | 9 Month Operations | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Operations Counter AF | 73 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Fault Operations C Ø | 1 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Fault Operations B Ø | 1 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Fault Adjusted Amps C Phase V | 11.18 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Fault Adjusted Amps B Phase V | 11.18 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Fault Adjusted Amps A Phase V | 11.18 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Amps C Ø | 170.0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | General Comments | a,b,c, phase ioc | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Amps A Ø | 170.0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Amps B Ø | 170.0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | 9 Month Operations | 12 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Operations Counter AL | 76 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Operations This Read Vac | 3 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | General Comments | | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Amps C Ø | 590.0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Amps B Ø | 570.0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | 9 Month Operations | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Operations Counter AL | 47 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Operations Counter AF | 47 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Amps A Ø | 530.0 | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 11:20 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 10:59 | Distribution | Beargrass Quarterly Inspection | PF000017 | PowerFuse | BG-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 10:59 | Distribution | Beargrass Quarterly Inspection | PF000017 | PowerFuse | BG-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/5/2023 10:59 | Distribution | Beargrass Quarterly Inspection | PF000017 | PowerFuse | BG-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | 9 Month Operations | 21 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Operations Counter AF | 214 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Fault Operations C Ø | 5 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Fault Operations B Ø | 5 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Fault Operations A Ø | 5 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Fault Adjusted Amps C Phase V | 64.49 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Fault Adjusted Amps B Phase V | 64.49 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Fault Adjusted Amps A Phase V | 64.49 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Operations Counter AL | 214 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Operations This Read Vac | 15 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Amps C Ø | 80.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Amps B Ø | 80.0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Amps A Ø | 75.0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Counter Readings | LTC Operations Since Last Insp | 200 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Counter Readings | LTC As Left Counter | 11848 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Counter Readings | LTC As Found Counter | 11848 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Counter Readings | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCC000983 | LTCControl | 509-2 | LTC Control Insp | All Connections OK? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCC000983 | LTCControl | 509-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCC000983 | LTCControl | 509-2 | LTC Control Insp | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCC000983 | LTCControl | 509-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCC000983 | LTCControl | 509-2 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCC000983 | LTCControl | 509-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCC000983 | LTCControl | 509-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCC000983 | LTCControl | 509-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 28 | °C |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 30 | °C |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Readings | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Readings | LTC Totalizer Reading | 9964.80 | kw |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Readings | Oil Temp Max | 39 | °C |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Readings | Oil Temp Present | 36 | °C |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Readings | Totalizer Meter Reading | .4152 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Readings | Winding Temp Max | 39 | °C |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Readings | Winding Temp Present | 36 | °C |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1600 | psi |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCC000815 | LTCControl | 509-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCC000815 | LTCControl | 509-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCC000815 | LTCControl | 509-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCC000815 | LTCControl | 509-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCC000815 | LTCControl | 509-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCC000815 | LTCControl | 509-1 | LTC Control Insp | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCC000815 | LTCControl | 509-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | LTCC000815 | LTCControl | 509-1 | LTC Control Insp | All Connections OK? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Counter Readings | LTC Operations Since Last Insp | 498 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Counter Readings | LTC Max Tap Position | 6L | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Counter Readings | LTC As Left Counter | 214656 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Counter Readings | LTC As Found Counter | 214656 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Counter Readings | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Readings | Totalizer Meter Reading | .4830 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Readings | LTC Totalizer Reading | 11592.00 | kw |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Readings | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | General Comments | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | SF6 Pressure Pole 1 | 60 | psi |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | SF6 Pressure Pole 3 | 62 | psi |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | SF6 Pressure Pole 2 | 64 | psi |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Ambient Temperature | 65 | °F |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Readings | Fault Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Readings | Unknown Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Readings | Switching Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Readings | Operations This Read SF6 | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Readings | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Readings | Operations Counter AF | 82 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Readings | Operations Counter AL | 82 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Readings | Operations Counter AL | 114 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Readings | Operations Counter AF | 114 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Readings | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Readings | Fault Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Readings | Operations This Read SF6 | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Readings | Switching Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Readings | Unknown Operations | 0 | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Ambient Temperature | 65 | °F |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | General Comments | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | SF6 Pressure Pole 3 | 60 | psi |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | SF6 Pressure Pole 2 | 60 | psi |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | SF6 Pressure Pole 1 | 60 | psi |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BCH001263 | Charger | 509-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BCH001263 | Charger | 509-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.0 | VDC |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BCH001263 | Charger | 509-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.0 | VDC |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BCH001263 | Charger | 509-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 4.9 | amps |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BCH001263 | Charger | 509-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BCH001263 | Charger | 509-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BCH001263 | Charger | 509-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BCH001263 | Charger | 509-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BAT001322 | Battery | 509-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BAT001322 | Battery | 509-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BAT001322 | Battery | 509-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BAT001322 | Battery | 509-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BAT001322 | Battery | 509-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BAT001322 | Battery | 509-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BAT001322 | Battery | 509-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BAT001322 | Battery | 509-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BAT001322 | Battery | 509-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BAT001322 | Battery | 509-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BAT001322 | Battery | 509-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BAT001322 | Battery | 509-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | BAT001322 | Battery | 509-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | General Comments | | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/5/2023 12:54 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | Ambient Temp | 65 | °F |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 0.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 0.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 0.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 2 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 109 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 109 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 2 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 2 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | No psi Guage | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 0.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 0.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 105 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 105 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 0.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 3 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 3 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 602 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 602 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 33.54 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 33.54 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 33.54 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 144.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 134.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 140.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 3 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 16 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 16 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 76 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 76 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | 16 0PS NO INFO | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 178.89 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 178.89 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 178.89 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 80.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 72.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 82.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 20 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 4 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 1 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 1 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 112.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 120.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 111.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 278 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 278 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 305.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 152 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 152 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 308.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 313.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | PF000097 | PowerFuse | DA-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | PF000097 | PowerFuse | DA-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | PF000096 | PowerFuse | DA-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | PF000096 | PowerFuse | DA-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 4 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 4 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 73.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 79.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 75.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 20 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 20 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 69.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 73.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 43 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 43 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 75.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 16 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 16 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 81.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 61.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 58.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 1 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 1 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 20 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 6 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 6 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 20 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 50.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 52.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 58.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 262.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 264.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 258.0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 49 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 49 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | PF000095 | PowerFuse | DA-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | PF000095 | PowerFuse | DA-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | PF000115 | PowerFuse | DA-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | PF000115 | PowerFuse | DA-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | R N K IS WORKING ON ROOF 4-5-23 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LTCC000116 | LTCControl | SSC-Offline-Distribution | LTC Control Insp | All Connections OK? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LTCC000116 | LTCControl | SSC-Offline-Distribution | LTC Control Insp | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LTCC000116 | LTCControl | SSC-Offline-Distribution | LTC Control Insp | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LTCC000116 | LTCControl | SSC-Offline-Distribution | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 201 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 77698 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 77698 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Counter Readings | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 41 | °C |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 41 | °C |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 41 | °C |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 41 | °C |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 41 | °C |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 41 | °C |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | LOW OIL ALARM IN BUT OIL IS GOOD | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 4.0 | psi |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1300 | psi |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Counter Readings | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 9325 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 9325 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 3L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 250 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Low | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | NEEDS OIL | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 39 | °C |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 39 | °C |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 41 | °C |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 41 | °C |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 41 | °C |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 41 | °C |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 41 | °C |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 41 | °C |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BCH001070 | Charger | DA-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 135.0 | VDC |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BCH001070 | Charger | DA-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 3.6 | amps |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BCH001070 | Charger | DA-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 135.0 | VDC |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BCH001070 | Charger | DA-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BCH001070 | Charger | DA-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BCH001070 | Charger | DA-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BCH001070 | Charger | DA-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BCH001070 | Charger | DA-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BAT000111 | Battery | Retired Distribution | Battery Patrol Inspection | All Connections OK? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BAT000111 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BAT000111 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BAT000111 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Post Condition OK? | n | If no, which cells in comments |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BAT000111 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BAT000111 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BAT000111 | Battery | Retired Distribution | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BAT000111 | Battery | Retired Distribution | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BAT000111 | Battery | Retired Distribution | Battery Patrol Inspection | Follow-up Action Required? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BAT000111 | Battery | Retired Distribution | Battery Patrol Inspection | General Comments | ALL POST NEEDS ATTEN..... | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BAT000111 | Battery | Retired Distribution | Battery Patrol Inspection | Straps Corrosion Free? | n | If no, which cells in comments |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BAT000111 | Battery | Retired Distribution | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Restroom Clean & OK? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | UG Pothead Condition Good? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Ambient Temp | 65 | °F |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 11:31 | Distribution | Dahlia Quarterly Inspection | BK002180 | BreakerVacuum | DA-1240 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0298 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0298 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0298 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0298 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0298 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0298 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0298 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0298 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0298 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0298 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0298 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0298 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0298 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0298 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0298 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0298 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0298 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0298 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0298 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0298 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0298 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0298 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | There are no high side bushings in xfmr. | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000069 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000069 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000069 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000069 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000069 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000069 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 95.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000069 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000069 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000069 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000069 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000069 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000069 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000069 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000069 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | M0042 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | M0042 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | M0042 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 2.5 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | M0042 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | M0042 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | M0042 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | There's not a Nitrogen bottle on XFMR, Did not operate pumps | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | M0042 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | M0042 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | M0042 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | M0042 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | M0042 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | Tank oil level high due to radiators empty | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0007 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0007 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0007 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0007 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0007 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0007 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0007 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0007 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0007 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0007 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 55.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | Needs new oil level gauge and oil temp gauge. | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 217.50 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 252.50 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 15.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 60.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 15.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 60.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0187 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0187 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0187 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0187 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0187 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0187 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0187 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0187 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0187 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0187 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0187 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0187 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0187 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .3 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.3 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0333 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0333 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0333 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0333 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0333 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0333 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0333 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0333 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0333 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0333 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0333 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0333 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 15.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | no psi gauge | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 15.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | no psi gauge | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 60.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | Needs new oil level gauge | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | No psi gauge | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 52.50 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 60.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Needs Replacing | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | Needs psi gauge | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | Needs psi gauge | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Needs Replacing | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | No psi gauge | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | No psi or oil level gauge | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0376 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0376 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0376 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0376 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0376 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0376 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 52.50 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0376 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0376 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0376 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0376 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0376 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0376 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | No psi or oil level gauge. | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | No psi or oil level gauge | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0375 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0375 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 97.50 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0375 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0375 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0375 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0375 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0375 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0375 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0375 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0375 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0375 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0375 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | No psi gauge | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 236.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | No psi gauge | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0356 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0356 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0356 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0356 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0356 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | No psi gauge | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0356 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0356 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0356 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0356 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0356 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0356 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0356 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Needs Replacing | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | Needs new nitrogen gauge. | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Needs Replacing | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | Needs psi gauge | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | Needs new oil level gauge. | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 9:22 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LTCC000226 | LTCControl | AB-TRANS 2 | LTC Control Insp | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LTCC000401 | LTCControl | AB-TRANS 1 | LTC Control Insp | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Counter Readings | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Counter Readings | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Patrol Inspection | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Patrol Inspection | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Patrol Inspection | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Patrol Inspection | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Patrol Inspection | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Patrol Inspection | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Patrol Inspection | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Patrol Inspection | General Comments | | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/13/2023 10:44 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Patrol Inspection | General Comments | | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 34 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0.0 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 31 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 39 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | General Comments | no amp gauge | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | General Comments | no amp gauge | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 177 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 299 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0.0 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 300 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0658 | RecloserHydraulic | 122-2159 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0658 | RecloserHydraulic | 122-2159 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0.0 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0658 | RecloserHydraulic | 122-2159 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0658 | RecloserHydraulic | 122-2159 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0658 | RecloserHydraulic | 122-2159 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0658 | RecloserHydraulic | 122-2159 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0658 | RecloserHydraulic | 122-2159 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0658 | RecloserHydraulic | 122-2159 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0658 | RecloserHydraulic | 122-2159 | Recloser Hydraulic Patrol Inspection | General Comments | no amp gauge | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0658 | RecloserHydraulic | 122-2159 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0658 | RecloserHydraulic | 122-2159 | Recloser Hydraulic Patrol Inspection | Operations Counter | 166 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0658 | RecloserHydraulic | 122-2159 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | CX0658 | RecloserHydraulic | 122-2159 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Regulator As Left Counter | 49681 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.8 | volts |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | General Comments | | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Operations Counter AF | 223 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Operations Counter AL | 223 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Operations This Read Vac | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Amps C Ø | 192.0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Amps B Ø | 187.0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Amps A Ø | 167.0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | 9 Month Operations VCB New | 13 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | 9 Month Operations | 13 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Regulator As Left Counter | 51916 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Operations This Read Vac | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Operations Counter AL | 487 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Operations Counter AF | 487 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | General Comments | | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | 9 Month Operations | 2 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Amps A Ø | 380.0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Amps B Ø | 390.0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Amps C Ø | 384.0 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Regulator As Left Counter | 48840 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Switching Operations | 1 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Operations This Read Vac | 1 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Operations Counter AL | 176 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Operations Counter AF | 175 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | General Comments | | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Amps C Ø | 329.0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Amps B Ø | 325.0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | 9 Month Operations | 3 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Amps A Ø | 304.0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Amps A Ø | 42.0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Amps B Ø | 41.0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Amps C Ø | 42.0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Operations This Read Vac | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | 9 Month Operations | 7 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | General Comments | | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Operations Counter AF | 194 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Operations Counter AL | 194 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Readings | Oil Temp Max | 25 | °C |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Readings | General Comments | | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 95.00 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Operations This Read Vac | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | General Comments | | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Operations Counter AF | 171 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Amps C Ø | 926.0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Amps B Ø | 919.0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Operations Counter AL | 171 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Amps A Ø | 876.0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | 9 Month Operations | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Counter Readings | General Comments | | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Counter Readings | LTC As Found Counter | 56493 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Counter Readings | LTC As Left Counter | 56493 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Counter Readings | LTC Current Tap Position | 7R | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Counter Readings | LTC Max Tap Position | 7R | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Counter Readings | LTC Operations Since Last Insp | 981 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Readings | Oil Temp Present | 15 | °C |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Readings | Oil Temp Max | 15 | °C |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Readings | General Comments | | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 95.00 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | 9 Month Operations | 26 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | 9 Month Operations VCB New | 26 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | General Comments | | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Operations Counter AF | 153 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Operations Counter AL | 153 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Operations This Read Vac | 0 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 100.00 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Readings | General Comments | | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Readings | Winding Temp Present | 50 | °C |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Readings | Winding Temp Max | 60 | °C |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Readings | Totalizer Meter Reading | 1.3040 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Readings | LTC Totalizer Reading | 23472.00 | kw |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Readings | Oil Temp Present | 55 | °C |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Readings | General Comments | | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 400.00 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Readings | Top Oil Temperature Present | 35 | °C |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Readings | Top Oil Temperature Max | 40 | °C |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | LTCC000745 | LTCControl | 127-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | LTCC000745 | LTCControl | 127-5 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | LTCC000745 | LTCControl | 127-5 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | LTCC000745 | LTCControl | 127-5 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | LTCC000745 | LTCControl | 127-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | LTCC000745 | LTCControl | 127-5 | LTC Control Insp | General Comments | | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | LTCC000745 | LTCControl | 127-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | LTCC000745 | LTCControl | 127-5 | LTC Control Insp | All Connections OK? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 405.00 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Bushing Connection/Risers | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Readings | General Comments | | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 15:03 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 95.00 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Readings | Switching Operations | 1 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Readings | Operations This Read SF6 | 1 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Readings | Operations Counter AL | 751 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Readings | Operations Counter AF | 750 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Readings | Num Operations Last 9 Months | 1 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Readings | General Comments | | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Readings | 9 Month Operations GCB New | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Readings | Fault Operations | 0 | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Ambient Temperature | 60 | °F |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | General Comments | | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | SF6 Pressure Indicator | good | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 14:56 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | BAT001526 | Battery | 794-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | BAT001526 | Battery | 794-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | BAT001526 | Battery | 794-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.6 | VDC |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | BAT001526 | Battery | 794-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.6 | VDC |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | BAT001526 | Battery | 794-Battery Bank | Battery Patrol Inspection | General Comments | float voltage validations | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | BAT001526 | Battery | 794-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | BAT001526 | Battery | 794-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | BAT001526 | Battery | 794-Battery Bank | Battery Patrol Inspection | Bat Volt 1Min After Chgr Trip | 52.2 | VDC |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | BAT001526 | Battery | 794-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 83 | °F |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | BAT001526 | Battery | 794-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | BAT001526 | Battery | 794-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | BAT001526 | Battery | 794-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | BAT001526 | Battery | 794-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | BCH001452 | Charger | 794-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | BCH001452 | Charger | 794-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | BCH001452 | Charger | 794-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | BCH001452 | Charger | 794-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 0.0 | amps |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | BCH001452 | Charger | 794-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | BCH001452 | Charger | 794-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | BCH001452 | Charger | 794-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | BCH001452 | Charger | 794-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 36064 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.2 | volts |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.2 | volts |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 36361 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.7 | volts |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 37007 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Max Tap Position | 16R | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Readings | Winding Temp Present | 35 | °C |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Readings | Winding Temp Max | 35 | °C |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .9294 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 3600 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Readings | Top Oil Temperature Present | 30 | °C |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Readings | Top Oil Temperature Max | 30 | °C |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3345.84 | kw |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Readings | General Comments | | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Amps A Ø | 19.0 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Amps B Ø | 32.0 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Amps C Ø | 24.0 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Operations Counter | 107 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Unknown Operations | 3 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Operations This Read Vac | 4 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Operations Counter AL | 297 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Operations Counter AF | 297 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Maintenance Operations | 1 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | General Comments | 1-TC, 3-A B | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Fault Adjusted Amps C Phase V | 22.66 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Fault Adjusted Amps B Phase V | 22.66 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | 9 Month Operations | 6 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Fault Adjusted Amps A Phase V | 22.66 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Amps C Ø | 0.0 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Amps A Ø | 0.0 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Amps B Ø | 0.0 | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | General Comments | | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | General Comments | | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | Ambient Temp | 84 | °F |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | General Comments | | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/4/2023 14:43 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 600 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1200 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 500 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LTCC000737 | LTCControl | CY-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LTCC000737 | LTCControl | CY-TRANS 2 | LTC Control Insp | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LTCC000737 | LTCControl | CY-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 180 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 6L | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 20786 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 20786 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Counter Readings | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 29 | °C |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 33 | °C |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 39 | °C |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 44 | °C |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | Top Oil Temperature Present | 38 | °C |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | Top Oil Temperature Max | 43 | °C |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 38 | °C |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 43 | °C |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 44 | °C |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 39 | °C |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 44 | °C |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 39 | °C |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000128 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000128 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000128 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000128 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000128 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000304 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000304 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000304 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000304 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000304 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000304 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000304 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000304 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000304 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000304 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000304 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000304 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000304 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000304 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000304 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000304 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000304 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000304 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000304 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000304 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | LTCMechanism | 667-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | LTCMechanism | 667-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | LTCMechanism | 667-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | LTCMechanism | 667-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | LTCMechanism | 667-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | LTCMechanism | 667-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 72.50 | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000038 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000038 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000038 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000038 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000038 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000038 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0182 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0182 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0182 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0182 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0182 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0182 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0177 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0177 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0177 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0177 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0177 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0177 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0177 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0177 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0177 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0177 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0177 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0177 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0177 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0177 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0177 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | O0177 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Oil Temp Max | 55 | °C |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | .3 | psi |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 30 | °C |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 20 | °C |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | M0069 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0046 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0046 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0046 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0046 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0046 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0046 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0046 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0046 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0046 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0046 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0046 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0046 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0045 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0045 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0045 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0045 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0045 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0045 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0045 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0045 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0045 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0045 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LTCC000538 | LTCControl | CY-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LTCC000538 | LTCControl | CY-TRANS 1 | LTC Control Insp | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LTCC000538 | LTCControl | CY-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 2 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 57 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 6 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 6 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Counter Readings | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 259701 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 259701 | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 30 | °C |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 20 | °C |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0025 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0025 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0025 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0025 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0025 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0025 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0025 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0025 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0025 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0025 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0025 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | KT0025 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0529 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0529 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0529 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0529 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0529 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0529 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0529 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0529 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0529 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0529 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0529 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0529 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000048 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000048 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000048 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000048 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000048 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000048 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000048 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 20 | °C |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000048 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 30 | °C |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000048 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000048 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0464 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0464 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0464 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0464 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 10 | °C |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0464 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0464 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0464 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0464 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0464 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0464 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 10 | °C |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0464 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0464 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0464 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0464 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0464 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0464 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0464 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0405 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0405 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0405 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0405 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0405 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0313 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0313 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0313 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0313 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0313 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0313 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0313 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0313 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 250.00 | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0313 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0313 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0313 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0313 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | C0313 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0473 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0473 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0473 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0473 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0473 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0473 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0432 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0432 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0432 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0432 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0432 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0432 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0432 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0432 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0432 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0432 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0432 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0432 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0432 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0432 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0432 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0432 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0432 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000036 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000036 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 0 | °C |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000036 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000036 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000036 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000036 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 0 | °C |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000036 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000036 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000036 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000036 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 45 | °C |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 40 | °C |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000049 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000049 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000049 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000049 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000049 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 10 | °C |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 10 | °C |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0384 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | nitrogen bottle is empty , needs new desiccant | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1 | psi |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0369 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0369 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0369 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0369 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0369 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0430 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0430 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0430 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0430 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0430 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000076 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000076 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000076 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000076 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | LTCM000076 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 70.00 | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0284 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0284 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0284 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0284 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0284 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0284 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0284 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0284 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0284 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0284 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0284 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0284 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0284 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0284 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0284 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0284 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0271 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0271 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0271 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0271 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0271 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0271 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0271 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 206.00 | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0271 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0190 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0190 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0190 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0190 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 117.50 | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0190 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0190 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0190 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0190 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0190 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0190 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0190 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | B0190 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0984 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0984 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0984 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0984 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0984 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 27.50 | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | Vegetation | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | General Comments | | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/4/2023 14:18 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | RC001321 | RecloserHydraulic | 635-1707 A | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 0 | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | RC001321 | RecloserHydraulic | 635-1707 A | Recloser Hydraulic Patrol Inspection | Amps A Ø | 11.0 | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | RC001321 | RecloserHydraulic | 635-1707 A | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | RC001321 | RecloserHydraulic | 635-1707 A | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | RC001321 | RecloserHydraulic | 635-1707 A | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | RC001321 | RecloserHydraulic | 635-1707 A | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | RC001321 | RecloserHydraulic | 635-1707 A | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | RC001321 | RecloserHydraulic | 635-1707 A | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | RC001321 | RecloserHydraulic | 635-1707 A | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | RC001321 | RecloserHydraulic | 635-1707 A | Recloser Hydraulic Patrol Inspection | Operations Counter | 263 | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | RC001321 | RecloserHydraulic | 635-1707 A | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | RC001321 | RecloserHydraulic | 635-1707 A | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.9 | volts |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 61259 | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Min Tap Position | 3L | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Readings | General Comments | Oil temp gauge is broken. | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 121.28 | kw |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Readings | Oil Temp Max | 0 | °C |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Readings | Totalizer Meter Reading | .1516 | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 800 | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Readings | Oil Temp Present | 34 | °C |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | General Comments | No spare fuses | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | General Comments | | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | YD000238 | Yard | 635-Yard | Yard Patrol Inspection | Ambient Temp | 82 | °F |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | YD000238 | Yard | 635-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | YD000238 | Yard | 635-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | YD000238 | Yard | 635-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | YD000238 | Yard | 635-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | YD000238 | Yard | 635-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | YD000238 | Yard | 635-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | YD000238 | Yard | 635-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | YD000238 | Yard | 635-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | YD000238 | Yard | 635-Yard | Yard Patrol Inspection | General Comments | | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | YD000238 | Yard | 635-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/4/2023 13:56 | Distribution | Dycusburg Quarterly Inspection | YD000238 | Yard | 635-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 650 | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 868 | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 8.3 | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | Amps B Ø | .2 | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 448 | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Operations Counter | 53 | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Amps A Ø | 21.0 | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Amps B Ø | 23.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Amps C Ø | 17.0 | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 18884 | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 384170 | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 92299 | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .7902 | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Readings | Oil Temp Present | 36 | °C |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 948.24 | kw |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Readings | General Comments | | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | General Comments | | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Unknown Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Switching Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Operations This Read AM | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Operations Counter AL | 443 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Operations Counter AF | 433 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | 9 Months Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Amps A Ø | 0.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Amps B Ø | 0.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Amps C Ø | 0.0 | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | YD000099 | Yard | 311-Yard | Yard Patrol Inspection | Ambient Temp | 78 | °F |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | YD000099 | Yard | 311-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | YD000099 | Yard | 311-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | YD000099 | Yard | 311-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | YD000099 | Yard | 311-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | YD000099 | Yard | 311-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | YD000099 | Yard | 311-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | YD000099 | Yard | 311-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | YD000099 | Yard | 311-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | YD000099 | Yard | 311-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | YD000099 | Yard | 311-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | YD000099 | Yard | 311-Yard | Yard Patrol Inspection | General Comments | | |
| 4/6/2023 8:47 | Distribution | Dwina Quarterly Inspection | YD000099 | Yard | 311-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Patrol Inspection | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Unknown Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Switching Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Operations This Read AM | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Operations Counter AL | 99968 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Operations Counter AF | 99968 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Amps C Ø | 0.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Amps B Ø | 0.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Amps A Ø | 0.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | 9 Months Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | 9 Month Ops New | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Patrol Inspection | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Operations This Read Vac | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Operations Counter AL | 182 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Operations Counter AF | 182 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Amps C Ø | 100.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Amps B Ø | 100.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Amps A Ø | 100.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | 9 Month Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Amps A Ø | 90.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Amps B Ø | 90.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Amps C Ø | 90.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | 9 Month Operations | 2 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Operations This Read Vac | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Operations Counter AF | 412 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Operations Counter AL | 412 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | PF000074 | PowerFuse | CY-14KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | PF000074 | PowerFuse | CY-14KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | PF000072 | PowerFuse | CY-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | PF000072 | PowerFuse | CY-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Oil Temp Max | 40 | °C |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1000 | psi |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Fault Adjusted Amps C Phase V | 208.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Fault Operations A Ø | 26 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Fault Operations B Ø | 26 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Fault Adjusted Amps B Phase V | 208.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Fault Adjusted Amps A Phase V | 208.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Amps C Ø | 150.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Amps B Ø | 150.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Amps A Ø | 150.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | 9 Month Operations | 81 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Fault Operations C Ø | 26 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Operations This Read Vac | 78 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Operations Counter AL | 308 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Operations Counter AF | 308 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Operations Counter AL | 204 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Operations This Read Vac | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Operations Counter AF | 204 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | 9 Month Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Amps A Ø | 20.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Amps B Ø | 20.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Amps C Ø | 20.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Fault Operations C Ø | 1 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Fault Operations B Ø | 1 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Fault Operations A Ø | 1 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Fault Adjusted Amps C Phase V | 8.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Fault Adjusted Amps B Phase V | 8.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Fault Adjusted Amps A Phase V | 8.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Amps C Ø | 75.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Amps B Ø | 75.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Amps A Ø | 75.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | 9 Month Operations | 9 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Operations Counter AF | 194 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Operations Counter AL | 194 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Operations This Read Vac | 3 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Amps C Ø | 100.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Follow-up Action Required? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | General Comments | relay is getting wet, needs new door seals on most of both sections | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Amps B Ø | 100.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Operations Counter AF | 369 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Operations Counter AL | 369 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Operations This Read Vac | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Amps A Ø | 100.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | 9 Month Operations | 6 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | PF000073 | PowerFuse | CY-14KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | PF000073 | PowerFuse | CY-14KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | PF000071 | PowerFuse | CY-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | PF000071 | PowerFuse | CY-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | 9 Month Operations | 1 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Switching Operations | 1 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Operations This Read Vac | 1 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Amps A Ø | 20.0 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Amps B Ø | 35.0 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Amps C Ø | 35.0 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Operations Counter AL | 217 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Operations Counter AF | 216 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | General Comments | | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | 9 Month Operations | 4 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Amps A Ø | 80.0 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Amps B Ø | 95.0 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Amps C Ø | 80.0 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Switching Operations | 1 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Operations Counter AF | 302 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | General Comments | 80 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Operations Counter AL | 303 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Operations This Read Vac | 1 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | LTCC000909 | LTCControl | 932-Offline Distribution | LTC Control Insp | All Connections OK? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | LTCC000909 | LTCControl | 932-Offline Distribution | LTC Control Insp | Follow-up Action Required? | n | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | LTCC000909 | LTCControl | 932-Offline Distribution | LTC Control Insp | General Comments | | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | LTCC000909 | LTCControl | 932-Offline Distribution | LTC Control Insp | LTC Operation Checked? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | LTCC000909 | LTCControl | 932-Offline Distribution | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | LTCC000909 | LTCControl | 932-Offline Distribution | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | LTCC000909 | LTCControl | 932-Offline Distribution | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | LTCC000909 | LTCControl | 932-Offline Distribution | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | 9 Month Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | 9 Month Operations VCB New | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Amps A Ø | 200.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Amps B Ø | 200.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Amps C Ø | 200.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Operations Counter AF | 49 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Operations Counter AL | 49 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Counter Readings | LTC Operations Since Last Insp | 505 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Counter Readings | LTC Max Tap Position | 5R | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Counter Readings | LTC As Left Counter | 157623 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Counter Readings | LTC As Found Counter | 157623 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Counter Readings | General Comments | | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 32223 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 122.9 | volts |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Operations This Read Vac | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Operations Counter AL | 84 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Operations Counter AF | 84 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Amps C Ø | 0.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Amps B Ø | 0.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Amps A Ø | 0.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | 9 Month Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Readings | General Comments | | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Readings | LTC Totalizer Reading | 6432.00 | kw |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Readings | Totalizer Meter Reading | .6700 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Amps A Ø | 0.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Amps B Ø | 0.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Amps C Ø | 0.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | 9 Month Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Operations Counter AF | 42 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Operations Counter AL | 42 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 35647 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.1 | volts |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Operations Counter AL | 28 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Operations Counter AF | 28 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Amps A Ø | 0.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Amps B Ø | 0.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Amps C Ø | 0.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | 9 Month Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 20481 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 122.8 | volts |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BCH000881 | Charger | 667-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BCH000881 | Charger | 667-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BCH000881 | Charger | 667-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BCH000881 | Charger | 667-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.0 | amps |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BCH000881 | Charger | 667-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | BCH000881 | Charger | 667-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .4416 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3179.52 | kw |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Readings | General Comments | | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | General Comments | | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | General Comments | | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | General Comments | | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/4/2023 13:23 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Unknown Operations | 2 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Operations This Read Vac | 3 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Operations Counter AL | 367 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Operations Counter AF | 367 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Maintenance Operations | 1 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | General Comments | 1 trip check and 2 unknowns | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Fault Adjusted Amps C Phase V | 16.00 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Fault Adjusted Amps B Phase V | 16.00 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Fault Adjusted Amps A Phase V | 16.00 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Amps C Ø | 60.0 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Amps B Ø | 60.0 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Amps A Ø | 50.0 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | 9 Month Operations | 6 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Operations Counter AL | 13 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Operations Counter AF | 13 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | 9 Month Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Amps A Ø | 270.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Amps B Ø | 270.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Amps C Ø | 270.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | 9 Month Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Operations Counter AF | 43 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Amps A Ø | 0.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Amps B Ø | 0.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Amps C Ø | 0.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Operations Counter AL | 43 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | 9 Month Operations | 5 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Amps A Ø | 0.0 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Amps B Ø | 0.0 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Amps C Ø | 0.0 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Fault Adjusted Amps A Phase V | 16.00 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Fault Adjusted Amps B Phase V | 8.00 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Fault Adjusted Amps C Phase V | 8.00 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Fault Operations Ground | 1 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | General Comments | 2-A to N inst ops | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Operations Counter AF | 7 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Operations Counter AL | 7 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Operations This Read Vac | 2 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Operations Counter AF | 59 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Operations Counter AL | 59 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Operations This Read Vac | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Amps C Ø | 0.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Amps B Ø | 0.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Amps A Ø | 0.0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | 9 Month Operations | 0 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Fault Adjusted Amps C Phase V | 45.75 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Fault Operations B Ø | 3 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Fault Operations C Ø | 3 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Operations Counter AF | 257 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Operations Counter AL | 257 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | General Comments | | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Fault Adjusted Amps B Phase V | 45.75 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Amps A Ø | 370.0 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Amps B Ø | 380.0 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Amps C Ø | 380.0 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | 9 Month Operations | 8 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Operations This Read Vac | 6 | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 14:10 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | BAT001608 | Battery | 803-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | BAT001608 | Battery | 803-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 83 | °F |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | BAT001608 | Battery | 803-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | BAT001608 | Battery | 803-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | BAT001608 | Battery | 803-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | BAT001608 | Battery | 803-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | BAT001608 | Battery | 803-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | BAT001608 | Battery | 803-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | BAT001608 | Battery | 803-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.6 | VDC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | BAT001608 | Battery | 803-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.6 | VDC |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | BAT001608 | Battery | 803-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | BAT001608 | Battery | 803-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | BCH001535 | Charger | 803-Battery Charger | Battery Charger Patrol Insp | General Comments | AF and AL float voltage shows an error for any value | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | BCH001535 | Charger | 803-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | BCH001535 | Charger | 803-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | BCH001535 | Charger | 803-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | BCH001535 | Charger | 803-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | BCH001535 | Charger | 803-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | BCH001535 | Charger | 803-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | BCH001535 | Charger | 803-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | General Comments | | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | General Comments | | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Operations This Read Vac | 0 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Operations Counter AL | 253 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Operations Counter AF | 253 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Amps C Ø | 75.0 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Amps B Ø | 70.0 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Amps A Ø | 75.0 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | 9 Month Operations VCB New | 3 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | 9 Month Operations | 3 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | General Comments | | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | YD000236 | Yard | 803-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | YD000236 | Yard | 803-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | YD000236 | Yard | 803-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | YD000236 | Yard | 803-Yard | Yard Patrol Inspection | General Comments | | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | YD000236 | Yard | 803-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | YD000236 | Yard | 803-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | YD000236 | Yard | 803-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | YD000236 | Yard | 803-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | YD000236 | Yard | 803-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | YD000236 | Yard | 803-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | YD000236 | Yard | 803-Yard | Yard Patrol Inspection | Ambient Temp | 81 | °F |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | YD000236 | Yard | 803-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/4/2023 13:22 | Distribution | Nortonville Quarterly Inspection | YD000236 | Yard | 803-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | LTCC000392 | LTCControl | 420-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | LTCC000392 | LTCControl | 420-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | LTCC000392 | LTCControl | 420-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | LTCC000392 | LTCControl | 420-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | LTCC000392 | LTCControl | 420-1 | LTC Control Insp | General Comments | | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | LTCC000392 | LTCControl | 420-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | LTCC000392 | LTCControl | 420-1 | LTC Control Insp | All Connections OK? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | LTCC000392 | LTCControl | 420-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Counter Readings | General Comments | | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Counter Readings | LTC As Found Counter | 16512 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Counter Readings | LTC As Left Counter | 16512 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Counter Readings | LTC Operations Since Last Insp | 405 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Readings | General Comments | | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Readings | LTC Totalizer Reading | 3216.00 | kw |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Readings | Oil Temp Present | 935 | °C |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Readings | Totalizer Meter Reading | .6700 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | BCH000565 | Charger | 420-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | BCH000565 | Charger | 420-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.0 | amps |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | BCH000565 | Charger | 420-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | BCH000565 | Charger | 420-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | BCH000565 | Charger | 420-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | BCH000565 | Charger | 420-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | BCH000565 | Charger | 420-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | General Comments | | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | General Comments | | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | General Comments | | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | YD000504 | Yard | 420-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | YD000504 | Yard | 420-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | YD000504 | Yard | 420-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | YD000504 | Yard | 420-Yard | Yard Patrol Inspection | General Comments | | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | YD000504 | Yard | 420-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | YD000504 | Yard | 420-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | YD000504 | Yard | 420-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | YD000504 | Yard | 420-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | YD000504 | Yard | 420-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | YD000504 | Yard | 420-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | YD000504 | Yard | 420-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/4/2023 13:16 | Distribution | Briar Hill Road Quarterly Inspection | YD000504 | Yard | 420-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | BAT001664 | Battery | 671-Battery Bank | Battery Patrol Inspection | Ambient Temp | 65 | °F |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | BAT001664 | Battery | 671-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | BAT001664 | Battery | 671-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | BAT001664 | Battery | 671-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.9 | VDC |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | BAT001664 | Battery | 671-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 28.2 | VDC |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | BAT001664 | Battery | 671-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | BAT001664 | Battery | 671-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | BAT001664 | Battery | 671-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 79 | °F |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | BAT001664 | Battery | 671-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | BAT001664 | Battery | 671-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | BAT001664 | Battery | 671-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | BAT001664 | Battery | 671-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | BAT001664 | Battery | 671-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | BCH000428 | Charger | 671-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .700 | millivolts |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | BCH000428 | Charger | 671-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.1 | VDC |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | BCH000428 | Charger | 671-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.1 | VDC |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | BCH000428 | Charger | 671-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .3 | amps |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | BCH000428 | Charger | 671-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | BCH000428 | Charger | 671-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | BCH000428 | Charger | 671-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | BCH000428 | Charger | 671-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | LTCC000327 | LTCControl | 671-1 | LTC Control Insp | General Comments | | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | LTCC000327 | LTCControl | 671-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | LTCC000327 | LTCControl | 671-1 | LTC Control Insp | LTC Output Voltage Level | 123.4 | VAC |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | LTCC000327 | LTCControl | 671-1 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | LTCC000327 | LTCControl | 671-1 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | LTCC000327 | LTCControl | 671-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | LTCC000327 | LTCControl | 671-1 | LTC Control Insp | All Connections OK? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | LTCC000327 | LTCControl | 671-1 | LTC Control Insp | VRR Time Delay | 40 | Seconds |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Counter Readings | LTC Operations Since Last Insp | 53 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Counter Readings | LTC As Left Counter | 79815 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Counter Readings | LTC As Found Counter | 79800 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Counter Readings | General Comments | | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Readings | Totalizer Meter Reading | .2754 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Readings | LTC Totalizer Reading | 2643.84 | kw |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Readings | General Comments | | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Amps A Ø | 53.0 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Operations This Read Vac | 1 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Amps B Ø | 54.0 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Amps C Ø | 55.0 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Fault Adjusted Amps A Phase V | 2.83 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Operations Counter AL | 215 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Operations Counter AF | 215 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | General Comments | 1 - AG | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | 9 Month Operations | 2 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | 9 Month Operations | 1 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Amps A Ø | 5.0 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Amps B Ø | 5.0 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Amps C Ø | 5.0 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | General Comments | | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Operations Counter AF | 158 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Operations Counter AL | 158 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Operations This Read Vac | 0 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | General Comments | | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | General Comments | | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | General Comments | | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/4/2023 13:01 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | Ambient Temp | 79 | °F |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 39383 | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Readings | Totalizer Meter Reading | .1038 | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Bad | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 135.00 | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 150.00 | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 249.12 | kw |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Readings | General Comments | | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Needs Replacing | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | KX0140 | RecloserHydraulic | 637-0812 A | Recloser Hydraulic Patrol Inspection | Amps A Ø | 20.1 | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | KX0140 | RecloserHydraulic | 637-0812 A | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | KX0140 | RecloserHydraulic | 637-0812 A | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | KX0140 | RecloserHydraulic | 637-0812 A | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | KX0140 | RecloserHydraulic | 637-0812 A | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | KX0140 | RecloserHydraulic | 637-0812 A | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | KX0140 | RecloserHydraulic | 637-0812 A | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | KX0140 | RecloserHydraulic | 637-0812 A | Recloser Hydraulic Patrol Inspection | Operations Counter | 95 | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | KX0140 | RecloserHydraulic | 637-0812 A | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | KX0140 | RecloserHydraulic | 637-0812 A | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | BAT001403 | Battery | 574-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | BAT001403 | Battery | 574-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | BAT001403 | Battery | 574-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.4 | VDC |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | BAT001403 | Battery | 574-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.6 | VDC |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | BAT001403 | Battery | 574-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | BAT001403 | Battery | 574-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | BAT001403 | Battery | 574-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | BAT001403 | Battery | 574-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | BAT001403 | Battery | 574-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | BAT001403 | Battery | 574-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | BAT001403 | Battery | 574-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 75 | °F |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | BAT001403 | Battery | 574-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | BCH001277 | Charger | 574-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | BCH001277 | Charger | 574-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | BCH001277 | Charger | 574-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.200 | millivolts |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | BCH001277 | Charger | 574-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 54.0 | VDC |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | BCH001277 | Charger | 574-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 54.0 | VDC |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | BCH001277 | Charger | 574-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | BCH001277 | Charger | 574-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | BCH001277 | Charger | 574-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | LTCC000979 | LTCControl | 574-1 | LTC Control Insp | All Connections OK? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | LTCC000979 | LTCControl | 574-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | LTCC000979 | LTCControl | 574-1 | LTC Control Insp | General Comments | | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | LTCC000979 | LTCControl | 574-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | LTCC000979 | LTCControl | 574-1 | LTC Control Insp | LTC Output Voltage Level | 124.3 | VAC |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | LTCC000979 | LTCControl | 574-1 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | LTCC000979 | LTCControl | 574-1 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | LTCC000979 | LTCControl | 574-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Counter Readings | General Comments | | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Counter Readings | LTC As Found Counter | 1345 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Counter Readings | LTC Operations Since Last Insp | 194 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Counter Readings | LTC As Left Counter | 1352 | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Platform/Walkway/Railing OK? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | General Comments | | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 10.00 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Readings | Totalizer Meter Reading | .6408 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Readings | Oil Temp Present | 39 | °C |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Readings | LTC Totalizer Reading | 6151.68 | kw |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Readings | General Comments | | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | General Comments | | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Amps A Ø | 72.0 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Amps B Ø | 71.0 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Amps C Ø | 75.0 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Operations Counter | 236 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Operations Counter | 169 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Amps A Ø | 46.0 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Amps B Ø | 37.0 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Amps C Ø | 43.0 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Fault Operations Ground | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | General Comments | storm ops | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Operations Counter AF | 485 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Operations Counter AL | 485 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Operations This Read Vac | 2 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Fault Operations B Ø | 1 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Fault Adjusted Amps B Phase V | 4.44 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Fault Adjusted Amps A Phase V | 4.44 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | 9 Month Operations | 4 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Amps C Ø | 69.0 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Amps B Ø | 78.0 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Amps A Ø | 63.0 | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | General Comments | outside needs painting, rust | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Tank Paint Condition | Bad | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | General Comments | | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | General Comments | | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | n | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | General Comments | SPR removed | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | Ambient Temp | 75 | °F |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/4/2023 12:08 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | Follow-up Action Required? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | BAT001417 | Battery | 862-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | BAT001417 | Battery | 862-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | BAT001417 | Battery | 862-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | BAT001417 | Battery | 862-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.5 | VDC |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | BAT001417 | Battery | 862-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | BAT001417 | Battery | 862-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 76 | °F |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | BAT001417 | Battery | 862-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | BAT001417 | Battery | 862-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | BAT001417 | Battery | 862-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.5 | VDC |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | BAT001417 | Battery | 862-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | BAT001417 | Battery | 862-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | BAT001417 | Battery | 862-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | BCH001055 | Charger | 862-Battery Charger | Battery Charger Patrol Insp | General Comments | ok | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | BCH001055 | Charger | 862-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | BCH001055 | Charger | 862-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | BCH001055 | Charger | 862-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.3 | amps |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | BCH001055 | Charger | 862-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.1 | VDC |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | BCH001055 | Charger | 862-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.1 | VDC |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 22146 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 21385 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | General Comments | drag hands stuck on indicaton | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 20874 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Min Tap Position | 2L | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Operations This Read Vac | 1 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Operations Counter AL | 299 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Operations Counter AF | 299 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | General Comments | | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | 9 Month Operations | 2 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Fault Adjusted Amps A Phase V | 2.83 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Amps A Ø | 87.0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Amps B Ø | 89.0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Amps C Ø | 83.0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Amps C Ø | 0.0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Amps B Ø | 0.0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Amps A Ø | 0.0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | 9 Month Operations | 1 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | General Comments | | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Operations Counter AF | 243 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Operations Counter AL | 243 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Operations This Read Vac | 0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | 9 Month Operations | 5 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Fault Operations A Ø | 4 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Fault Adjusted Amps A Phase V | 11.31 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Amps C Ø | 105.0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Amps B Ø | 88.0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | General Comments | AG | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Operations Counter AF | 58 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Operations Counter AL | 58 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Amps A Ø | 80.0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Operations This Read Vac | 4 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | General Comments | | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | General Comments | | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | General Comments | | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | Ambient Temp | 76 | °F |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/4/2023 11:58 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | YD000324 | Yard | 637-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | YD000324 | Yard | 637-Yard | Yard Patrol Inspection | General Comments | | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | YD000324 | Yard | 637-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | YD000324 | Yard | 637-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | YD000324 | Yard | 637-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | YD000324 | Yard | 637-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | YD000324 | Yard | 637-Yard | Yard Patrol Inspection | Ambient Temp | 70 | °F |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | YD000324 | Yard | 637-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | YD000324 | Yard | 637-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | YD000324 | Yard | 637-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | YD000324 | Yard | 637-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/4/2023 12:12 | Distribution | Crossroads Quarterly Inspection | YD000324 | Yard | 637-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | PF001322 | PowerFuse | 746-1F | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | PF001322 | PowerFuse | 746-1F | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | PF001322 | PowerFuse | 746-1F | Disconnect Powerfuse Inspection | General Comments | x | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Switching Operations | 1 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Operations This Read Vac | 1 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Operations Counter AL | 191 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Operations Counter AF | 190 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Amps C Ø | 240 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Amps B Ø | 186 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Amps A Ø | 196 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | 9 Month Operations | 3 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Operations Counter AF | 156 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Operations Counter AL | 157 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Switching Operations | 1 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Operations This Read Vac | 1 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | 9 Month Operations | 1 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Amps C Ø | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Amps A Ø | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Amps B Ø | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | 9 Month Operations | 2 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Amps A Ø | 360 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Amps B Ø | 240 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Amps C Ø | 240 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Switching Operations | 1 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Operations This Read Vac | 1 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Operations Counter AF | 240 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Operations Counter AL | 241 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Regulator As Left Counter | 84075 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Reg Output Voltage Level | 121 | volts |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Min Tap Position | 2L | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Max Tap Position | 1L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Min Tap Position | 1L | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Reg Output Voltage Level | 120.6 | volts |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Regulator As Left Counter | 50853 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Reg Output Voltage Level | 120.5 | volts |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Regulator As Left Counter | 21414 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Amps C Ø | 7.0 | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | 9 Month Operations | 1 | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Amps B Ø | 2.0 | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Amps A Ø | 2.0 | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | General Comments | | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Operations Counter AF | 169 | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Operations Counter AL | 170 | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Operations This Read Vac | 1 | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Switching Operations | 1 | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Regulator As Left Counter | 53478 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Reg Output Voltage Level | 120 | volts |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Min Tap Position | 1R | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Readings | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Readings | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Readings | Oil Temp Present | 49 | °C |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Readings | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Readings | Oil Temp Max | 55 | °C |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Readings | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Readings | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3720 | kw |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Readings | Totalizer Meter Reading | .62 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 6000 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Readings | Oil Temp Present | 45 | °C |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Readings | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3 | psi |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2 | psi |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 122816 | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.3 | volts |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Max Tap Position | 4L | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Min Tap Position | 5L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 310614 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 4 | psi |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Min Tap Position | 16L | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Max Tap Position | 8L | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.7 | volts |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 116591 | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Current Tap Position | 12L | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | LTCC000319 | LTCControl | 746-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | LTCC000319 | LTCControl | 746-1 | LTC Control Insp | VRR Base Voltage AL | 121 | VAC |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | LTCC000319 | LTCControl | 746-1 | LTC Control Insp | VRR Base Voltage AF | 121 | VAC |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | LTCC000319 | LTCControl | 746-1 | LTC Control Insp | LTC Output Voltage Level | 120.1 | VAC |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | LTCC000319 | LTCControl | 746-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | LTCC000319 | LTCControl | 746-1 | LTC Control Insp | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | LTCC000319 | LTCControl | 746-1 | LTC Control Insp | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | LTCC000319 | LTCControl | 746-1 | LTC Control Insp | All Connections OK? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Counter Readings | LTC Operations Since Last Insp | 398 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Counter Readings | LTC As Left Counter | 334636 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Counter Readings | LTC As Found Counter | 334634 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Counter Readings | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BCH001470 | Charger | 746-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BCH001470 | Charger | 746-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BCH001470 | Charger | 746-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BCH001470 | Charger | 746-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.1 | amps |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BCH001470 | Charger | 746-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BCH001470 | Charger | 746-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.7 | VDC |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.7 | VDC |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 134157 | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 122.9 | volts |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Readings | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Readings | LTC Totalizer Reading | 656.4 | kw |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 6000 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Readings | Totalizer Meter Reading | .1094 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | X0252 | RecloserHydraulic | 419-0557 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | X0252 | RecloserHydraulic | 419-0557 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | X0252 | RecloserHydraulic | 419-0557 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | X0252 | RecloserHydraulic | 419-0557 | Recloser Hydraulic Patrol Inspection | Operations Counter | 297 | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | X0252 | RecloserHydraulic | 419-0557 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | X0252 | RecloserHydraulic | 419-0557 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | X0252 | RecloserHydraulic | 419-0557 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 33.0 | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | X0252 | RecloserHydraulic | 419-0557 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 19.7 | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | X0252 | RecloserHydraulic | 419-0557 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 28.4 | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | X0252 | RecloserHydraulic | 419-0557 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | X0252 | RecloserHydraulic | 419-0557 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | X0252 | RecloserHydraulic | 419-0557 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | X0252 | RecloserHydraulic | 419-0557 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Readings | Oil Temp Present | 37 | °C |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Readings | Oil Temp Max | 42 | °C |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Readings | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | General Comments | | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Ambient Temp | 70 | °F |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/4/2023 11:17 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Readings | Totalizer Meter Reading | .3720 | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 446.40 | kw |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Readings | General Comments | | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | General Comments | needs new gauges | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Readings | General Comments | | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | General Comments | needs new gauges | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Min Tap Position | 3L | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 159172 | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 347492 | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.7 | volts |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Min Tap Position | 2L | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Readings | General Comments | | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 187.20 | kw |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .0780 | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Readings | Oil Temp Present | 29 | °C |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | General Comments | added nitrogen | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | General Comments | | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BAT001416 | Battery | 351-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BAT001416 | Battery | 351-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 110 | °F |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BAT001416 | Battery | 351-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BAT001416 | Battery | 351-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BAT001416 | Battery | 351-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BAT001416 | Battery | 351-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BAT001416 | Battery | 351-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BAT001416 | Battery | 351-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BAT001416 | Battery | 351-Battery Bank | Battery Patrol Inspection | General Comments | house heater was stuck | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BAT001416 | Battery | 351-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.3 | VDC |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BAT001416 | Battery | 351-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.2 | VDC |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BAT001416 | Battery | 351-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BAT001416 | Battery | 351-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BCH001333 | Charger | 351-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.600 | millivolts |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BCH001333 | Charger | 351-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BCH001333 | Charger | 351-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BCH001333 | Charger | 351-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .6 | amps |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BCH001333 | Charger | 351-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BCH001333 | Charger | 351-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BCH001333 | Charger | 351-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | BCH001333 | Charger | 351-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | General Comments | | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/4/2023 12:35 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 74700 | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Min Tap Position | 13L | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Max Tap Position | 6L | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Current Tap Position | 9L | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Max Tap Position | 6L | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 192752 | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 20304 | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Max Tap Position | 6L | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1674.00 | kw |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Readings | Oil Temp Max | 42 | °C |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .4650 | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 3600 | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Readings | Oil Temp Present | 39 | °C |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Amps A Ø | 36.0 | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Amps B Ø | 36.0 | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Amps C Ø | 35.0 | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Operations Counter | 18 | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Amps C Ø | 39.0 | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Amps B Ø | 32.0 | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Amps A Ø | 32.0 | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | General Comments | 1-trip check | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Operations Counter | 116 | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | General Comments | no spare fuses | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | General Comments | | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | General Comments | | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | Ambient Temp | 71 | °F |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | General Comments | | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/4/2023 10:17 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BAT001402 | Battery | 673-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 25.0 | VDC |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BAT001402 | Battery | 673-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.1 | VDC |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BAT001402 | Battery | 673-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BAT001402 | Battery | 673-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BAT001402 | Battery | 673-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BAT001402 | Battery | 673-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BAT001402 | Battery | 673-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BAT001402 | Battery | 673-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BAT001402 | Battery | 673-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BAT001402 | Battery | 673-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BAT001402 | Battery | 673-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 69 | °F |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BAT001402 | Battery | 673-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BCH000259 | Charger | 673-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BCH000259 | Charger | 673-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BCH000259 | Charger | 673-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.1 | VDC |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BCH000259 | Charger | 673-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.100 | millivolts |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | LTCC000785 | LTCControl | 673-1 | LTC Control Insp | All Connections OK? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | LTCC000785 | LTCControl | 673-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | LTCC000785 | LTCControl | 673-1 | LTC Control Insp | General Comments | | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | LTCC000785 | LTCControl | 673-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | LTCC000785 | LTCControl | 673-1 | LTC Control Insp | LTC Output Voltage Level | 123.6 | VAC |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | LTCC000785 | LTCControl | 673-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | LTCC000785 | LTCControl | 673-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | LTCC000785 | LTCControl | 673-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Counter Readings | General Comments | | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Counter Readings | LTC As Found Counter | 11273 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Counter Readings | LTC As Left Counter | 11281 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Counter Readings | LTC Operations Since Last Insp | 172 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Readings | Totalizer Meter Reading | .5706 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Readings | General Comments | | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Readings | LTC Totalizer Reading | 2738.88 | kw |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Readings | Oil Temp Max | 42 | °C |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Amps C Ø | 21.0 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Amps B Ø | 20.0 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Amps A Ø | 23.0 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | 9 Month Operations | 3 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Operations This Read Vac | 0 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | General Comments | | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Operations Counter AL | 223 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Operations Counter AF | 223 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | 9 Month Operations | 2 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Amps A Ø | 76.0 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Amps B Ø | 98.0 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Amps C Ø | 93.0 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Fault Adjusted Amps B Phase V | 1.66 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Fault Operations B Ø | 1 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | General Comments | B-G | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Operations Counter AF | 178 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Operations Counter AL | 178 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Operations This Read Vac | 1 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | General Comments | | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | General Comments | | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | YD000228 | Yard | 673-Yard | Yard Patrol Inspection | Ambient Temp | 69 | °F |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | YD000228 | Yard | 673-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | YD000228 | Yard | 673-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | YD000228 | Yard | 673-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | YD000228 | Yard | 673-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | YD000228 | Yard | 673-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | YD000228 | Yard | 673-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | YD000228 | Yard | 673-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | YD000228 | Yard | 673-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | YD000228 | Yard | 673-Yard | Yard Patrol Inspection | General Comments | | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | YD000228 | Yard | 673-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | YD000228 | Yard | 673-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/4/2023 10:04 | Distribution | Salem 12kV Quarterly Inspection | YD000228 | Yard | 673-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | General Comments | | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | YD000202 | Yard | 419-Yard | Yard Patrol Inspection | Ambient Temp | 70 | °F |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | YD000202 | Yard | 419-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | YD000202 | Yard | 419-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | YD000202 | Yard | 419-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | YD000202 | Yard | 419-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | YD000202 | Yard | 419-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | YD000202 | Yard | 419-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | YD000202 | Yard | 419-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | YD000202 | Yard | 419-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | YD000202 | Yard | 419-Yard | Yard Patrol Inspection | General Comments | | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | YD000202 | Yard | 419-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | YD000202 | Yard | 419-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/4/2023 11:07 | Distribution | Daniel Boone Quarterly Inspection | YD000202 | Yard | 419-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Operations Counter AF | 174 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Operations Counter AL | 175 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Amps C Ø | 264 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Operations This Read Vac | 1 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Amps B Ø | 280 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Amps A Ø | 264 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Switching Operations | 1 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | 9 Month Operations | 1 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Switching Operations | 1 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Operations This Read Vac | 1 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Operations Counter AL | 181 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Operations Counter AF | 180 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | 9 Month Operations | 1 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Amps C Ø | 118 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Amps B Ø | 286 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Amps A Ø | 290 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Amps B Ø | 271 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Amps A Ø | 256 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Amps C Ø | 255 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Operations Counter AF | 126 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Operations Counter AL | 127 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Operations This Read Vac | 1 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Switching Operations | 1 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | 9 Month Operations | 1 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Operations Counter AF | 198 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Operations Counter AL | 199 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | 9 Month Operations | 1 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Amps A Ø | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Amps B Ø | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Amps C Ø | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Operations This Read Vac | 1 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Switching Operations | 1 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Switching Operations | 1 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Operations This Read Vac | 1 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Operations Counter AL | 139 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Operations Counter AF | 138 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | 9 Month Operations | 1 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Amps A Ø | 284 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Amps C Ø | 122 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Amps B Ø | 279 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | SF6 Pressure | 62 | psi |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Ambient Temperature | 65 | °F |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Readings | Switching Operations | 1 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Readings | Operations This Read SF6 | 1 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Readings | Operations Counter AL | 84 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Readings | Operations Counter AF | 83 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Readings | Num Operations Last 9 Months | 1 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Readings | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Readings | Fault Operations | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | SF6 Pressure | 66 | psi |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Ambient Temperature | 65 | °F |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Readings | Switching Operations | 1 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Readings | Operations This Read SF6 | 1 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Readings | Operations Counter AL | 85 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Readings | Operations Counter AF | 84 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Readings | Num Operations Last 9 Months | 1 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Readings | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Readings | Fault Operations | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | BAT001667 | Battery | 082-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | BAT001667 | Battery | 082-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | BAT001667 | Battery | 082-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | BAT001667 | Battery | 082-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | BAT001667 | Battery | 082-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | BAT001667 | Battery | 082-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | BAT001667 | Battery | 082-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | BAT001667 | Battery | 082-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 28.2 | VDC |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | BAT001667 | Battery | 082-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.1 | VDC |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | BAT001667 | Battery | 082-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | BAT001667 | Battery | 082-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | BAT001667 | Battery | 082-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | LTCC000069 | LTCControl | 825-2 | LTC Control Insp | VRR Base Voltage AF | 121 | VAC |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | LTCC000069 | LTCControl | 825-2 | LTC Control Insp | VRR Base Voltage AL | 121 | VAC |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | LTCC000069 | LTCControl | 825-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | LTCC000069 | LTCControl | 825-2 | LTC Control Insp | LTC Output Voltage Level | 120.7 | VAC |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | LTCC000069 | LTCControl | 825-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | LTCC000069 | LTCControl | 825-2 | LTC Control Insp | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | LTCC000069 | LTCControl | 825-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | LTCC000069 | LTCControl | 825-2 | LTC Control Insp | All Connections OK? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | BCH001053 | Charger | 082-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.3 | VDC |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | BCH001053 | Charger | 082-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.3 | VDC |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | BCH001053 | Charger | 082-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .700 | millivolts |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | BCH001053 | Charger | 082-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .3 | amps |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | BCH001053 | Charger | 082-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | BCH001053 | Charger | 082-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | BCH001053 | Charger | 082-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | BCH001053 | Charger | 082-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | LTCC000589 | LTCControl | 825-3 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | LTCC000589 | LTCControl | 825-3 | LTC Control Insp | VRR Base Voltage AL | 121 | VAC |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | LTCC000589 | LTCControl | 825-3 | LTC Control Insp | VRR Base Voltage AF | 121 | VAC |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | LTCC000589 | LTCControl | 825-3 | LTC Control Insp | LTC Output Voltage Level | 120.8 | VAC |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | LTCC000589 | LTCControl | 825-3 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | LTCC000589 | LTCControl | 825-3 | LTC Control Insp | All Connections OK? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | LTCC000589 | LTCControl | 825-3 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | LTCC000589 | LTCControl | 825-3 | LTC Control Insp | General Comments | | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 36279 | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Min Tap Position | 3L | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 15 | °C |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 45 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2 | psi |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Min Tap Position | 3L | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 36932 | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Readings | Oil Temp Max | 32 | °C |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Readings | LTC Totalizer Reading | 4171.68 | kw |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Readings | Oil Temp Present | 16 | °C |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Readings | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Readings | Totalizer Meter Reading | .2897 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Readings | Winding Temp Max | 32 | °C |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Readings | Winding Temp Present | 15 | °C |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 39741 | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Min Tap Position | 2L | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Current Tap Position | 2R | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Counter Readings | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Counter Readings | LTC As Found Counter | 27287 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Counter Readings | LTC As Left Counter | 27290 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Counter Readings | LTC Operations Since Last Insp | 523 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Readings | Winding Temp Present | 39 | °C |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Readings | Winding Temp Max | 39 | °C |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Readings | General Comments | | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | General Comments | Nitro prress gauge needs replacing or new face cover | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Counter Readings | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Counter Readings | LTC As Found Counter | 26617 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Counter Readings | LTC Operations Since Last Insp | 509 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Counter Readings | LTC As Left Counter | 26619 | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Operations Counter | 305 | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Amps C Ø | 47.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Amps B Ø | 48.0 | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Amps A Ø | 47.0 | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Readings | 9 Months Operations OCB New | 0 | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Readings | Fault Operations | 0 | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Readings | General Comments | | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Readings | Number of Ops last 9 Months | 0 | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Readings | Operations Counter AF | 99992 | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Readings | Operations Counter AL | 99992 | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Readings | Operations This Read Oil | 0 | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Readings | Unknown Operations | 0 | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Readings | Switching Operations | 0 | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | General Comments | | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Pop-off Valve Tested Date | 2023-04-04 00:00:00.000000 | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Pressure Vessel Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | AirCompressor Heater Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Air Tank Bleed (> 40°F)? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Air Pressure OK? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Air Leaks | None | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Air Compressor Oil Status | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Air Compressor Belt Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 15 | °C |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 45 | °C |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | General Comments | | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 20 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Readings | Winding Temp Present | 29 | °C |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Readings | Winding Temp Max | 50 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Readings | Totalizer Meter Reading | .3576 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Readings | Oil Temp Present | 29 | °C |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Readings | LTC Totalizer Reading | 5149.44 | kw |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Readings | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | General Comments | | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | General Comments | | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | General Comments | | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/4/2023 9:39 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | Ambient Temp | 68 | °F |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 4 | psi |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | BAT001186 | Battery | 825-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | BAT001186 | Battery | 825-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | BAT001186 | Battery | 825-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | BAT001186 | Battery | 825-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | BAT001186 | Battery | 825-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | BAT001186 | Battery | 825-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | BAT001186 | Battery | 825-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | BAT001186 | Battery | 825-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | BAT001186 | Battery | 825-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | BAT001186 | Battery | 825-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 66 | VDC |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | BAT001186 | Battery | 825-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 67 | VDC |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | BAT001186 | Battery | 825-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | BAT001186 | Battery | 825-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | BCH000587 | Charger | 825-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0 | millivolts |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | BCH000587 | Charger | 825-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 132 | VDC |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | BCH000587 | Charger | 825-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 132 | VDC |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | BCH000587 | Charger | 825-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | BCH000587 | Charger | 825-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | BCH000587 | Charger | 825-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | BCH000587 | Charger | 825-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2 | amps |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Ambient Temp | 65 | °F |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | General Comments | | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/4/2023 9:44 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | General Comments | no spares | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BCH001097 | Charger | 437-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BCH001097 | Charger | 437-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BCH001097 | Charger | 437-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BCH001097 | Charger | 437-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.3 | amps |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BCH001097 | Charger | 437-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BCH001097 | Charger | 437-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BCH001097 | Charger | 437-Battery Charger | Battery Charger Patrol Insp | General Comments | validation error on both float voltages | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BCH001097 | Charger | 437-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BAT001658 | Battery | 437-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BAT001658 | Battery | 437-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BAT001658 | Battery | 437-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.9 | VDC |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BAT001658 | Battery | 437-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 28.2 | VDC |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BAT001658 | Battery | 437-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BAT001658 | Battery | 437-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BAT001658 | Battery | 437-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BAT001658 | Battery | 437-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BAT001658 | Battery | 437-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BAT001658 | Battery | 437-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BAT001658 | Battery | 437-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BAT001658 | Battery | 437-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Operations Counter AF | 209 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Maintenance Operations | 1 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | General Comments | 1-TC | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Amps C Ø | 4.0 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Amps B Ø | 2.0 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Amps A Ø | 2.0 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | 9 Month Operations | 11 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Operations Counter AL | 209 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Operations This Read Vac | 1 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | 9 Month Operations | 25 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | 9 Month Operations VCB New | 23 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Amps A Ø | 5.0 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Operations This Read Vac | 2 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Operations Counter AL | 190 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Operations Counter AF | 190 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Maintenance Operations | 1 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | General Comments | 1-TC, 1-C | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Fault Operations C Ø | 1 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Fault Adjusted Amps C Phase V | 1.00 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Amps C Ø | 9.0 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Amps B Ø | 5.0 | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Operations Counter AL | 184 | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Operations This Read Vac | 1 | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Operations Counter AF | 184 | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Maintenance Operations | 1 | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | General Comments | | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Amps C Ø | 114.0 | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | 9 Month Operations | 2 | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Amps B Ø | 95.0 | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Amps A Ø | 121.0 | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.3 | volts |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 731 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.5 | volts |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 99539 | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Current Tap Position | 5L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 596 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.3 | volts |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 649 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 32672 | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 60.00 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Readings | Totalizer Meter Reading | .5124 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Readings | Oil Temp Max | 48 | °C |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 55.00 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 614.88 | kw |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Readings | General Comments | | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 15.00 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 10.00 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Readings | General Comments | | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Readings | Oil Temp Max | 47 | °C |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Readings | General Comments | | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 30908 | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .7332 | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 2346.24 | kw |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Readings | General Comments | | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | n | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | General Comments | deteriorated fuse barrels No spare fuses | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BAT001613 | Battery | 421-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BAT001613 | Battery | 421-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 71 | °F |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BAT001613 | Battery | 421-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BAT001613 | Battery | 421-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BAT001613 | Battery | 421-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 8.3 | VDC |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BAT001613 | Battery | 421-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 8.6 | VDC |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BAT001613 | Battery | 421-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BAT001613 | Battery | 421-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BAT001613 | Battery | 421-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BAT001613 | Battery | 421-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BAT001613 | Battery | 421-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BAT001613 | Battery | 421-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BCH000310 | Charger | 421-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BCH000310 | Charger | 421-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BCH000310 | Charger | 421-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | BCH000310 | Charger | 421-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.100 | millivolts |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | General Comments | | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | Ambient Temp | 71 | °F |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | Drive/Lot Free of Washouts? | n | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | General Comments | Small washout is forming in back of station by containment berm. | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | Vegetation | None | |
| 4/4/2023 9:15 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Operations Counter AL | 354 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Operations Counter AF | 354 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Amps C Ø | 449.0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Amps B Ø | 445.0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Amps A Ø | 420.0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | 9 Month Operations VCB New | 20 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | 9 Month Operations | 20 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | General Comments | | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | 9 Month Operations VCB New | 19 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | 9 Month Operations | 19 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Amps A Ø | 24.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Amps B Ø | 23.0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Amps C Ø | 23.0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Operations Counter AL | 362 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Operations Counter AF | 362 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | General Comments | | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | General Comments | | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | General Comments | | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | Ambient Temp | 69 | °F |
| 4/4/2023 9:17 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Amps C Ø | 270.0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Amps B Ø | 261.0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Amps A Ø | 235.0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | 9 Month Operations VCB New | 29 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | 9 Month Operations | 29 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | General Comments | | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Operations Counter AF | 382 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Operations Counter AL | 382 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 486131 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Operations This Read Vac | 1 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Operations Counter AL | 185 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Operations Counter AF | 185 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Maintenance Operations | 1 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | General Comments | | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Amps C Ø | 13.0 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Amps B Ø | 26.0 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Amps A Ø | 18.0 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | 9 Month Operations | 4 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Operations This Read Vac | 1 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Operations Counter AL | 222 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Operations Counter AF | 222 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Maintenance Operations | 1 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Amps A Ø | 17.0 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Amps B Ø | 17.0 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Amps C Ø | 31.0 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | General Comments | TC 1 op | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | 9 Month Operations | 3 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.1 | volts |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 3710 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 3812 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.5 | volts |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | PF000022 | PowerFuse | AS-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | PF000022 | PowerFuse | AS-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | PF000022 | PowerFuse | AS-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 3621 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.2 | volts |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Mechanism Patrol Inspection | General Comments | OIL INSIDE LTC CABINET | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | 9 Month Operations | 1 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Amps A Ø | 68.0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Amps B Ø | 90.0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Amps C Ø | 65.0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Operations This Read Vac | 0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Operations Counter AL | 176 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Operations Counter AF | 176 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | General Comments | | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LTCC000419 | LTCControl | AS-TRANS 3 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LTCC000419 | LTCControl | AS-TRANS 3 | LTC Control Insp | General Comments | | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LTCC000419 | LTCControl | AS-TRANS 3 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Counter Readings | LTC Max Tap Position | 21 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Counter Readings | LTC Min Tap Position | 18 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Counter Readings | LTC Current Tap Position | 20 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Counter Readings | General Comments | | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Counter Readings | LTC As Found Counter | 17221 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Counter Readings | LTC As Left Counter | 17221 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Counter Readings | LTC Operations Since Last Insp | 23 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | 9 Month Operations | 2 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Operations This Read Vac | 0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Operations Counter AL | 193 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Operations Counter AF | 193 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Maintenance Operations | 0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | General Comments | | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Amps A Ø | 120.0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Amps B Ø | 90.0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Amps C Ø | 75.0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Amps A Ø | 47.0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Amps B Ø | 49.0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Amps C Ø | 49.0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Fault Operations Ground | 0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Follow-up Action Required? | n | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | General Comments | | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | 9 Month Operations | 1 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Unknown Operations | 0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Switching Operations | 0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Operations This Read Vac | 0 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Operations Counter AL | 213 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Operations Counter AF | 213 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 100.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Max | 55 | °C |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | General Comments | | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | H2 Winding Temp Max | 60 | °C |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | H2 Winding Temp Present | 45 | °C |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Present | 50 | °C |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | Y2 Winding Temp Max | 50 | °C |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | Y2 Winding Temp Present | 45 | °C |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Patrol Inspection | General Comments | | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Readings | Winding Temp Present | 30 | °C |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Readings | Winding Temp Max | 32 | °C |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .4374 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Readings | General Comments | | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 2099.52 | kw |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | LTCC000806 | LTCControl | 438-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | LTCC000806 | LTCControl | 438-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | LTCC000806 | LTCControl | 438-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | LTCC000806 | LTCControl | 438-1 | LTC Control Insp | LTC Output Voltage Level | 124.1 | VAC |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | LTCC000806 | LTCControl | 438-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | LTCC000806 | LTCControl | 438-1 | LTC Control Insp | General Comments | | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | LTCC000806 | LTCControl | 438-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | LTCC000806 | LTCControl | 438-1 | LTC Control Insp | All Connections OK? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Gas Accumulation Gauge | Normal | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Counter Readings | LTC Operations Since Last Insp | 147 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Counter Readings | LTC As Left Counter | 3971 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Counter Readings | LTC As Found Counter | 3967 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Counter Readings | General Comments | | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | PF001291 | PowerFuse | AS-14KV BUS SEC 3 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | PF001291 | PowerFuse | AS-14KV BUS SEC 3 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | PF001291 | PowerFuse | AS-14KV BUS SEC 3 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | PF000025 | PowerFuse | AS-14KV TR 3 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | PF000025 | PowerFuse | AS-14KV TR 3 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | PF000025 | PowerFuse | AS-14KV TR 3 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .8 | psi |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | BAT001607 | Battery | 770-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 276.0 | VDC |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | BAT001607 | Battery | 770-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | BAT001607 | Battery | 770-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | BAT001607 | Battery | 770-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | BAT001607 | Battery | 770-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | BAT001607 | Battery | 770-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | BAT001607 | Battery | 770-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | BAT001607 | Battery | 770-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.6 | VDC |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | BAT001607 | Battery | 770-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | BAT001607 | Battery | 770-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | BAT001607 | Battery | 770-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | BAT001607 | Battery | 770-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Readings | LTC Totalizer Reading | 2357.76 | kw |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Readings | General Comments | | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Readings | Totalizer Meter Reading | .7368 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | BCH001574 | Charger | 770-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | BCH001574 | Charger | 770-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | BCH001574 | Charger | 770-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | BCH001574 | Charger | 770-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .9 | amps |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | BCH001574 | Charger | 770-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | BCH001574 | Charger | 770-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | BCH001574 | Charger | 770-Battery Charger | Battery Charger Patrol Insp | General Comments | the as found and as left float voltages always have an error no matter what value is entered | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | BCH001574 | Charger | 770-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | PF000024 | PowerFuse | AS-GND TR 3 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | PF000024 | PowerFuse | AS-GND TR 3 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | PF000024 | PowerFuse | AS-GND TR 3 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BAT001358 | Battery | 438-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BAT001358 | Battery | 438-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BAT001358 | Battery | 438-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BAT001358 | Battery | 438-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 28.2 | VDC |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BAT001358 | Battery | 438-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.7 | VDC |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BAT001358 | Battery | 438-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BAT001358 | Battery | 438-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BAT001358 | Battery | 438-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BAT001358 | Battery | 438-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BAT001358 | Battery | 438-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BAT001358 | Battery | 438-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 68 | °F |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BAT001358 | Battery | 438-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Amps C Ø | 0.0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Amps B Ø | 0.0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Amps A Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Operations Counter AL | 385 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | 9 Month Operations VCB New | 19 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | 9 Month Operations | 19 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Operations Counter AF | 385 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | General Comments | | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Readings | General Comments | | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.0740 | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 600 | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 644.40 | kw |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BCH001270 | Charger | 438-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BCH001270 | Charger | 438-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BCH001270 | Charger | 438-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BCH001270 | Charger | 438-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BCH001270 | Charger | 438-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .9 | amps |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BCH001270 | Charger | 438-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.100 | millivolts |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BCH001270 | Charger | 438-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.1 | VDC |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | BCH001270 | Charger | 438-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.1 | VDC |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | General Comments | | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | .8 | psi |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | General Comments | | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | General Comments | | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/4/2023 8:32 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | Ambient Temp | 68 | °F |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | General Comments | | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | General Comments | no gauges working | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | General Comments | | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Operations Counter AL | 172 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Operations Counter AF | 172 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | General Comments | | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Amps C Ø | 0.0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Amps B Ø | 0.0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Amps A Ø | 0.0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | 9 Month Operations | 13 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | 9 Month Operations VCB New | 13 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Fault Adjusted Amps B Phase V | 24.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Fault Operations B Ø | 3 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Amps C Ø | 42.0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Amps B Ø | 47.0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Amps A Ø | 47.0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | 9 Month Operations VCB New | 17 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | 9 Month Operations | 20 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | General Comments | B phase TOC | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Operations Counter AF | 663 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Operations Counter AL | 663 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Operations This Read Vac | 3 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Operations Counter AL | 87 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Operations Counter AF | 87 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | General Comments | | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | 9 Month Operations | 15 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | 9 Month Operations VCB New | 15 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Amps C Ø | 6.0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Amps B Ø | 6.0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Amps A Ø | 6.0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Operations This Read Vac | 1 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Operations Counter AL | 255 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Operations Counter AF | 255 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | General Comments | C phase TOC. NO VC CHANGE | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Follow-up Action Required? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Fault Operations C Ø | 1 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Fault Adjusted Amps C Phase V | 8.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Amps C Ø | 236.0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Amps B Ø | 231.0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Amps A Ø | 245.0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | 9 Month Operations | 1 | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | General Comments | | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | YD000199 | Yard | 708-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | YD000199 | Yard | 708-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | YD000199 | Yard | 708-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | YD000199 | Yard | 708-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | YD000199 | Yard | 708-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | YD000199 | Yard | 708-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | YD000199 | Yard | 708-Yard | Yard Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | YD000199 | Yard | 708-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | YD000199 | Yard | 708-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | YD000199 | Yard | 708-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | YD000199 | Yard | 708-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | YD000199 | Yard | 708-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/4/2023 8:39 | Distribution | Claxton Quarterly Inspection | YD000199 | Yard | 708-Yard | Yard Patrol Inspection | Ambient Temp | 67 | °F |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | PF000026 | PowerFuse | AS-14KV TR 4 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | PF000026 | PowerFuse | AS-14KV TR 4 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | PF000026 | PowerFuse | AS-14KV TR 4 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | PF000027 | PowerFuse | AS-STA SER NO 4 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | PF000027 | PowerFuse | AS-STA SER NO 4 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | PF000027 | PowerFuse | AS-STA SER NO 4 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | General Comments | | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LTCC000473 | LTCControl | AS-TRANS 4 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LTCC000473 | LTCControl | AS-TRANS 4 | LTC Control Insp | General Comments | | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LTCC000473 | LTCControl | AS-TRANS 4 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Counter Readings | LTC Operations Since Last Insp | 56 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Counter Readings | LTC Current Tap Position | 6 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Counter Readings | LTC As Left Counter | 60200 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Counter Readings | LTC As Found Counter | 60200 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Counter Readings | General Comments | | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Readings | Percent Thermal Load X2 Max | 60 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Readings | Percent Thermal Load Y2 Max | 60 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Readings | General Comments | | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Amps C Ø | 269.0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Amps B Ø | 271.0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Fault Operations Ground | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | General Comments | | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Maintenance Operations | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Operations Counter AF | 172 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Operations Counter AL | 172 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Operations This Read Vac | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Switching Operations | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Unknown Operations | 0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Amps A Ø | 283.0 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | 9 Month Operations VCB New | 17 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | 9 Month Operations | 17 | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | General Comments | | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/5/2023 10:44 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | General Comments | | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | Ambient Temp | 68 | °F |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | General Comments | | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/4/2023 8:37 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Amps A Ø | 120 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Amps B Ø | 120 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Amps C Ø | 120 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Operations Counter | 1432 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Operations Counter | 1873 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Amps C Ø | 60 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Amps B Ø | 60 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Amps A Ø | 60 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | 9 Month Operations | 11 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | 9 Month Operations VCB New | 2 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Accumulated Fault Duty A Ph V | .71 | % |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Amps A Ø | 186 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Amps B Ø | 168 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Amps C Ø | 179 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Unknown Operations | 0 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Switching Operations | 9 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Operations This Read Vac | 9 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Fault Operations Ground | 0 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Follow-up Action Required? | n | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | General Comments | | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Maintenance Operations | 0 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Operations Counter AF | 396 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Operations Counter AL | 396 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | 9 Month Operations | 2 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Amps A Ø | 48 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Amps B Ø | 43 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Amps C Ø | 48 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Fault Operations Ground | 0 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Follow-up Action Required? | n | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | General Comments | | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Maintenance Operations | 0 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Operations Counter AF | 307 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Operations Counter AL | 307 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Operations This Read Vac | 1 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Switching Operations | 1 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Unknown Operations | 0 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | General Comments | | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | General Comments | | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Counter Readings | LTC As Left Counter | 24087 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Counter Readings | LTC Operations Since Last Insp | 530 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Counter Readings | LTC As Found Counter | 24085 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Counter Readings | General Comments | | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | LTCC000902 | LTCControl | 826-2 | LTC Control Insp | All Connections OK? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | LTCC000902 | LTCControl | 826-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | LTCC000902 | LTCControl | 826-2 | LTC Control Insp | General Comments | | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | LTCC000902 | LTCControl | 826-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | LTCC000902 | LTCControl | 826-2 | LTC Control Insp | LTC Output Voltage Level | 124.7 | VAC |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | LTCC000902 | LTCControl | 826-2 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | LTCC000902 | LTCControl | 826-2 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | LTCC000902 | LTCControl | 826-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Readings | Totalizer Meter Reading | 1.216 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Readings | Oil Temp Present | 50 | °C |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Readings | LTC Totalizer Reading | 5836.8 | kw |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Readings | General Comments | | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | LTCC000976 | LTCControl | 826-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | LTCC000976 | LTCControl | 826-1 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | LTCC000976 | LTCControl | 826-1 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | LTCC000976 | LTCControl | 826-1 | LTC Control Insp | LTC Output Voltage Level | 124.2 | VAC |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | LTCC000976 | LTCControl | 826-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | LTCC000976 | LTCControl | 826-1 | LTC Control Insp | All Connections OK? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | LTCC000976 | LTCControl | 826-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | LTCC000976 | LTCControl | 826-1 | LTC Control Insp | General Comments | | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Counter Readings | General Comments | | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Counter Readings | LTC As Found Counter | 3762 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Counter Readings | LTC As Left Counter | 3764 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Counter Readings | LTC Operations Since Last Insp | 582 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Readings | Totalizer Meter Reading | .594 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Readings | LTC Totalizer Reading | 5702.4 | kw |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Readings | General Comments | | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3 | psi |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | BCH001312 | Charger | 826-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | BCH001312 | Charger | 826-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .9 | amps |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | BCH001312 | Charger | 826-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | BCH001312 | Charger | 826-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | BCH001312 | Charger | 826-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | BCH001312 | Charger | 826-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0 | millivolts |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | BCH001312 | Charger | 826-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | BCH001312 | Charger | 826-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | BAT001384 | Battery | 826-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | BAT001384 | Battery | 826-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | BAT001384 | Battery | 826-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | BAT001384 | Battery | 826-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | BAT001384 | Battery | 826-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | BAT001384 | Battery | 826-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27 | VDC |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | BAT001384 | Battery | 826-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26 | VDC |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | BAT001384 | Battery | 826-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | BAT001384 | Battery | 826-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | BAT001384 | Battery | 826-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | BAT001384 | Battery | 826-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | BAT001384 | Battery | 826-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 75 | °F |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | BAT001384 | Battery | 826-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | General Comments | | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | General Comments | | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | Ambient Temp | 75 | °F |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | General Comments | | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/3/2023 16:00 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Operations Counter | 8 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Amps A Ø | 22.4 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Amps B Ø | 29.7 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Amps C Ø | 26.9 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Operations Counter AL | 190 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Operations This Read Vac | 0 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Operations Counter AF | 190 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Maintenance Operations | 0 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | General Comments | | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Follow-up Action Required? | n | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Fault Operations Ground | 0 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Switching Operations | 0 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Unknown Operations | 0 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Amps C Ø | 820.0 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | 9 Month Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Amps B Ø | 805.0 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Amps A Ø | 790.0 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | General Comments | | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Counter Readings | General Comments | | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Counter Readings | LTC Operations Since Last Insp | 1221 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Counter Readings | LTC As Left Counter | 73020 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Counter Readings | LTC As Found Counter | 73017 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | LTCC000849 | LTCControl | 369-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | LTCC000849 | LTCControl | 369-1 | LTC Control Insp | VRR Base Voltage AL | 121.0 | VAC |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | LTCC000849 | LTCControl | 369-1 | LTC Control Insp | VRR Base Voltage AF | 121.0 | VAC |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | LTCC000849 | LTCControl | 369-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | LTCC000849 | LTCControl | 369-1 | LTC Control Insp | LTC Output Voltage Level | 121.0 | VAC |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | LTCC000849 | LTCControl | 369-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | LTCC000849 | LTCControl | 369-1 | LTC Control Insp | General Comments | | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | LTCC000849 | LTCControl | 369-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | LTCC000849 | LTCControl | 369-1 | LTC Control Insp | All Connections OK? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Readings | General Comments | | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Readings | LTC Totalizer Reading | 6148.80 | kw |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Readings | Oil Temp Present | 44 | °C |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.2810 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | BCH001411 | Charger | 369-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | BCH001411 | Charger | 369-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | BCH001411 | Charger | 369-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.000 | millivolts |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | BCH001411 | Charger | 369-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .2 | amps |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | BCH001411 | Charger | 369-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | BCH001411 | Charger | 369-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | BCH001411 | Charger | 369-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | BCH001411 | Charger | 369-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | BAT001477 | Battery | 369-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | BAT001477 | Battery | 369-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | BAT001477 | Battery | 369-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.2 | VDC |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | BAT001477 | Battery | 369-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.4 | VDC |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | BAT001477 | Battery | 369-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | BAT001477 | Battery | 369-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | BAT001477 | Battery | 369-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | BAT001477 | Battery | 369-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | BAT001477 | Battery | 369-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | BAT001477 | Battery | 369-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | BAT001477 | Battery | 369-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 68 | °F |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | BAT001477 | Battery | 369-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | BAT001477 | Battery | 369-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | General Comments | | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | General Comments | | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | YD000037 | Yard | 369-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | YD000037 | Yard | 369-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | YD000037 | Yard | 369-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | YD000037 | Yard | 369-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | YD000037 | Yard | 369-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | YD000037 | Yard | 369-Yard | Yard Patrol Inspection | General Comments | | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | YD000037 | Yard | 369-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | YD000037 | Yard | 369-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | YD000037 | Yard | 369-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | YD000037 | Yard | 369-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | YD000037 | Yard | 369-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | YD000037 | Yard | 369-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/3/2023 14:35 | Distribution | Toms Creek 2 Quarterly Inspection | YD000037 | Yard | 369-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .5430 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Readings | Oil Temp Present | 36 | °C |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Readings | Oil Temp Max | 42 | °C |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Readings | General Comments | | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1303.20 | kw |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Amps A Ø | 12.0 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Amps B Ø | 12.0 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Amps C Ø | 12.0 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Fault Operations Ground | 0 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Follow-up Action Required? | n | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | General Comments | | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Maintenance Operations | 0 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Operations Counter AF | 668 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Operations Counter AL | 672 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Operations This Read Vac | 4 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Switching Operations | 4 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Unknown Operations | 0 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | 9 Month Operations | 4 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | General Comments | | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Fault Operations Ground | 0 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Fault Operations C Ø | 3 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Fault Operations B Ø | 3 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Fault Operations A Ø | 2 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Follow-up Action Required? | n | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Fault Adjusted Amps C Phase V | 9.13 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Fault Adjusted Amps B Phase V | 9.13 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Fault Adjusted Amps A Phase V | 6.09 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Amps C Ø | 60.0 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Amps B Ø | 120.0 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Amps A Ø | 60.0 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Switching Operations | 4 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | 9 Month Operations | 12 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | General Comments | BFTC | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Maintenance Operations | 0 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Operations Counter AF | 725 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Unknown Operations | 0 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Operations Counter AL | 729 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Operations This Read Vac | 12 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | General Comments | | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Patrol Inspection | General Comments | | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Unknown Operations | 0 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Switching Operations | 0 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Operations This Read Vac | 1 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Operations Counter AL | 200 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Operations Counter AF | 200 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Maintenance Operations | 0 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | General Comments | | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Follow-up Action Required? | n | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Fault Operations Ground | 0 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | 9 Month Operations | 5 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Amps A Ø | 168.0 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Amps B Ø | 164.0 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Amps C Ø | 164.0 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Fault Adjusted Amps A Phase V | 6.55 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 141889 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 211123 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.6 | volts |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 74700 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | LTCC000654 | LTCControl | 444-3 | LTC Control Insp | All Connections OK? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | LTCC000654 | LTCControl | 444-3 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | LTCC000654 | LTCControl | 444-3 | LTC Control Insp | General Comments | | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | LTCC000654 | LTCControl | 444-3 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | LTCC000654 | LTCControl | 444-3 | LTC Control Insp | LTC Output Voltage Level | 124.9 | VAC |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | LTCC000654 | LTCControl | 444-3 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | LTCC000654 | LTCControl | 444-3 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | LTCC000654 | LTCControl | 444-3 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | LTCC000654 | LTCControl | 444-3 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Counter Readings | LTC Operations Since Last Insp | 655 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Counter Readings | LTC As Left Counter | 14259 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Counter Readings | LTC As Found Counter | 14247 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Counter Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Readings | Totalizer Meter Reading | .3730 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Readings | Oil Temp Present | 38 | °C |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Readings | LTC Totalizer Reading | 2685.60 | kw |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Readings | General Comments | | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Unknown Operations | 1 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Switching Operations | 1 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Operations This Read Vac | 2 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Operations Counter AL | 202 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Operations Counter AF | 202 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Maintenance Operations | 0 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | General Comments | | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Follow-up Action Required? | n | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Fault Operations Ground | 0 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Fault Adjusted Amps C Phase V | 2.94 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Fault Adjusted Amps B Phase V | 2.94 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Fault Adjusted Amps A Phase V | 2.94 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Amps C Ø | 2.0 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Amps B Ø | 1.0 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Amps A Ø | 1.0 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | 9 Month Operations | 2 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BCH001320 | Charger | 444-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.600 | millivolts |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BCH001320 | Charger | 444-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BCH001320 | Charger | 444-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BCH001320 | Charger | 444-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .6 | amps |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BCH001320 | Charger | 444-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BCH001320 | Charger | 444-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BCH001320 | Charger | 444-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BCH001320 | Charger | 444-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Patrol Inspection | General Comments | | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.2 | VDC |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.2 | VDC |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 78 | °F |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Low | If low,note cell #~'s |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | 9 Month Operations | 11 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Amps A Ø | 29.0 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Amps B Ø | 28.0 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Amps C Ø | 28.0 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Fault Adjusted Amps A Phase V | 8.81 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Fault Adjusted Amps B Phase V | 5.87 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Fault Adjusted Amps C Phase V | 5.87 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Fault Operations A Ø | 3 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Fault Operations B Ø | 2 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Fault Operations C Ø | 2 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Fault Operations Ground | 0 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Follow-up Action Required? | n | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | General Comments | | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Maintenance Operations | 0 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Unknown Operations | 0 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Switching Operations | 1 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Operations This Read Vac | 8 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Operations Counter AL | 216 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Operations Counter AF | 216 | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | General Comments | | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | General Comments | | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Patrol Inspection | General Comments | | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | General Comments | 26.2/24 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Operations Counter | 41 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Amps A Ø | 0.0 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Amps B Ø | 0.0 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Amps C Ø | 0.0 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | General Comments | | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | YD000014 | Yard | 444-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | YD000014 | Yard | 444-Yard | Yard Patrol Inspection | General Comments | | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | YD000014 | Yard | 444-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | YD000014 | Yard | 444-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | YD000014 | Yard | 444-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | YD000014 | Yard | 444-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | YD000014 | Yard | 444-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | YD000014 | Yard | 444-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | YD000014 | Yard | 444-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | YD000014 | Yard | 444-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | YD000014 | Yard | 444-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | YD000014 | Yard | 444-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/3/2023 13:59 | Distribution | Shawnee Gas Quarterly Inspection | YD000014 | Yard | 444-Yard | Yard Patrol Inspection | Ambient Temp | 70 | °F |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | LTCC000776 | LTCControl | 841-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | LTCC000776 | LTCControl | 841-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | LTCC000776 | LTCControl | 841-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | LTCC000776 | LTCControl | 841-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | LTCC000776 | LTCControl | 841-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | LTCC000776 | LTCControl | 841-1 | LTC Control Insp | General Comments | | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | LTCC000776 | LTCControl | 841-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | LTCC000776 | LTCControl | 841-1 | LTC Control Insp | All Connections OK? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Counter Readings | LTC Operations Since Last Insp | 909 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Counter Readings | General Comments | | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Counter Readings | LTC As Found Counter | 15216 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Counter Readings | LTC As Left Counter | 15225 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Readings | Totalizer Meter Reading | .2200 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Readings | Oil Temp Present | 41 | °C |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Readings | LTC Totalizer Reading | 1584.00 | kw |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Readings | General Comments | | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BCH001555 | Charger | 841-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BCH001555 | Charger | 841-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BCH001555 | Charger | 841-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BCH001555 | Charger | 841-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .9 | amps |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BCH001555 | Charger | 841-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BCH001555 | Charger | 841-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BCH001555 | Charger | 841-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.200 | millivolts |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BCH001555 | Charger | 841-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.2 | VDC |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.3 | VDC |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | General Comments | | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | General Comments | | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | General Comments | barb wire rusty and top rail is rusty back left corner posts need replaaced, multiple bayonets loose on fence | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | n | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | YD000003 | Yard | 841-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | YD000003 | Yard | 841-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | YD000003 | Yard | 841-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | YD000003 | Yard | 841-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | YD000003 | Yard | 841-Yard | Yard Patrol Inspection | General Comments | | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | YD000003 | Yard | 841-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | YD000003 | Yard | 841-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | YD000003 | Yard | 841-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | YD000003 | Yard | 841-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | YD000003 | Yard | 841-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | YD000003 | Yard | 841-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | YD000003 | Yard | 841-Yard | Yard Patrol Inspection | Ambient Temp | 73 | °F |
| 4/3/2023 13:48 | Distribution | Robbins Quarterly Inspection | YD000003 | Yard | 841-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Fault Adjusted Amps A Phase V | 25.88 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Amps C Ø | 200.0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Amps B Ø | 200.0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Amps A Ø | 200.0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | 9 Month Operations | 2 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | 9 Month Operations VCB New | 1 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Maintenance Operations | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Operations Counter AF | 91 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Operations Counter AL | 91 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Operations This Read Vac | 1 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Switching Operations | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Fault Operations Ground | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Follow-up Action Required? | n | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | General Comments | | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Unknown Operations | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | General Comments | | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Unknown Operations | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Switching Operations | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Operations This Read Vac | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Operations Counter AL | 254 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Operations Counter AF | 254 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Maintenance Operations | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | General Comments | | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Follow-up Action Required? | n | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | 9 Month Operations | 1 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Fault Operations Ground | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Amps C Ø | 96.0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Amps B Ø | 122.0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Amps A Ø | 113.0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | General Comments | | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Unknown Operations | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Switching Operations | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Operations This Read Vac | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Operations Counter AL | 178 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Operations Counter AF | 178 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Maintenance Operations | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | 9 Month Operations | 1 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Amps A Ø | 97.0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Amps B Ø | 120.0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Amps C Ø | 105.0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Follow-up Action Required? | n | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Fault Operations Ground | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Patrol Inspection | General Comments | | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Unknown Operations | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Switching Operations | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Operations This Read Vac | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Operations Counter AL | 551 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Operations Counter AF | 551 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Maintenance Operations | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | General Comments | | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Follow-up Action Required? | n | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Fault Operations Ground | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Amps C Ø | 200.0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Amps B Ø | 200.0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Amps A Ø | 180.0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | 9 Month Operations | 1 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | General Comments | | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Unknown Operations | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Switching Operations | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Operations This Read Vac | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Operations Counter AL | 345 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Operations Counter AF | 345 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Maintenance Operations | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | 9 Month Operations | 2 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | 9 Month Operations VCB New | 2 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Amps A Ø | 0.0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Amps B Ø | 0.0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Amps C Ø | 0.0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Fault Operations Ground | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Follow-up Action Required? | n | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | General Comments | | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | General Comments | | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Unknown Operations | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Switching Operations | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Operations This Read Vac | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Operations Counter AL | 210 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Operations Counter AF | 210 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Maintenance Operations | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | General Comments | | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Follow-up Action Required? | n | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Fault Operations Ground | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | 9 Month Operations | 1 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Amps C Ø | 137.0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Amps B Ø | 148.0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Amps A Ø | 124.0 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Patrol Inspection | General Comments | | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | LTCC000739 | LTCControl | 028-6 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | LTCC000739 | LTCControl | 028-6 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | LTCC000739 | LTCControl | 028-6 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | LTCC000739 | LTCControl | 028-6 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | LTCC000739 | LTCControl | 028-6 | LTC Control Insp | General Comments | | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | LTCC000739 | LTCControl | 028-6 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | LTCC000739 | LTCControl | 028-6 | LTC Control Insp | All Connections OK? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | LTCC000739 | LTCControl | 028-6 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Counter Readings | LTC As Left Counter | 31880 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Counter Readings | LTC Operations Since Last Insp | 210 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Counter Readings | LTC As Found Counter | 31880 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Counter Readings | General Comments | | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Readings | Totalizer Meter Reading | .4410 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Readings | Totalizer Meter Multiplier | 8000 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Readings | LTC Totalizer Reading | 3528.00 | kw |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Readings | General Comments | | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | LTCC000799 | LTCControl | 028-5 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | LTCC000799 | LTCControl | 028-5 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | LTCC000799 | LTCControl | 028-5 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | LTCC000799 | LTCControl | 028-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | LTCC000799 | LTCControl | 028-5 | LTC Control Insp | All Connections OK? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | LTCC000799 | LTCControl | 028-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | LTCC000799 | LTCControl | 028-5 | LTC Control Insp | General Comments | | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | LTCC000799 | LTCControl | 028-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Counter Readings | LTC Operations Since Last Insp | 217 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Counter Readings | LTC As Left Counter | 18274 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Counter Readings | LTC As Found Counter | 18274 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Counter Readings | General Comments | | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Readings | Totalizer Meter Reading | .9370 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 8000 | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Readings | Oil Temp Max | 65 | °C |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Readings | LTC Totalizer Reading | 7496.00 | kw |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Readings | General Comments | | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 13:38 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Operations This Read Vac | 0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Switching Operations | 0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Unknown Operations | 0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Operations Counter AL | 180 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Operations Counter AF | 180 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Maintenance Operations | 0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | General Comments | | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Follow-up Action Required? | n | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Fault Operations Ground | 0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Amps C Ø | 115.0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Amps B Ø | 107.0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Amps A Ø | 129.0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | 9 Month Operations | 2 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Patrol Inspection | General Comments | | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Fault Operations Ground | 0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Follow-up Action Required? | n | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | General Comments | | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Amps C Ø | 157.0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Amps B Ø | 180.0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Operations Counter AF | 387 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Operations Counter AL | 387 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Operations This Read Vac | 0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Amps A Ø | 154.0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | 9 Month Operations | 5 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Switching Operations | 0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Unknown Operations | 0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | General Comments | | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Unknown Operations | 0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Fault Adjusted Amps C Phase V | 15.63 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Fault Adjusted Amps A Phase V | 15.63 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Amps C Ø | 68.0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Amps B Ø | 93.0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Amps A Ø | 86.0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | 9 Month Operations | 5 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Fault Operations C Ø | 1 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Fault Operations Ground | 0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Follow-up Action Required? | n | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | General Comments | | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Maintenance Operations | 0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Operations Counter AF | 281 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Operations Counter AL | 281 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Operations This Read Vac | 2 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Switching Operations | 0 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | General Comments | | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Counter Readings | LTC Operations Since Last Insp | 224 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Counter Readings | LTC As Left Counter | 84707 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Counter Readings | LTC As Found Counter | 84707 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Counter Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | LTCC000907 | LTCControl | 446-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | LTCC000907 | LTCControl | 446-1 | LTC Control Insp | VRR Base Voltage AL | 125.6 | VAC |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | LTCC000907 | LTCControl | 446-1 | LTC Control Insp | VRR Base Voltage AF | 125.6 | VAC |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | LTCC000907 | LTCControl | 446-1 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | LTCC000907 | LTCControl | 446-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | LTCC000907 | LTCControl | 446-1 | LTC Control Insp | General Comments | | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | LTCC000907 | LTCControl | 446-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | LTCC000907 | LTCControl | 446-1 | LTC Control Insp | All Connections OK? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | Ambient Temp | 62 | °F |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | General Comments | | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | General Comments | | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | General Comments | | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | MX0195 | RecloserHydraulic | 353-0672 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 5.0 | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | MX0195 | RecloserHydraulic | 353-0672 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 6.0 | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | MX0195 | RecloserHydraulic | 353-0672 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 7.0 | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | MX0195 | RecloserHydraulic | 353-0672 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | MX0195 | RecloserHydraulic | 353-0672 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | MX0195 | RecloserHydraulic | 353-0672 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | MX0195 | RecloserHydraulic | 353-0672 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | MX0195 | RecloserHydraulic | 353-0672 | Recloser Hydraulic Patrol Inspection | General Comments | Herald sub is backfeeding the 22kv line back down the mountain temporarily. | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | MX0195 | RecloserHydraulic | 353-0672 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | MX0195 | RecloserHydraulic | 353-0672 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | MX0195 | RecloserHydraulic | 353-0672 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 101.67 | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Readings | General Comments | | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1.44 | kw |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Readings | Oil Temp Present | 36 | °C |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .0012 | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Readings | General Comments | | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Readings | LTC Totalizer Reading | 4374.00 | kw |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Readings | Totalizer Meter Reading | .7290 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 6000 | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 12973 | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BAT001488 | Battery | 446-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BAT001488 | Battery | 446-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 73 | °F |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BAT001488 | Battery | 446-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BAT001488 | Battery | 446-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BAT001488 | Battery | 446-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BAT001488 | Battery | 446-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BAT001488 | Battery | 446-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BAT001488 | Battery | 446-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BAT001488 | Battery | 446-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BAT001488 | Battery | 446-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.0 | VDC |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BAT001488 | Battery | 446-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BAT001488 | Battery | 446-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BAT001488 | Battery | 446-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BCH001385 | Charger | 446-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BCH001385 | Charger | 446-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BCH001385 | Charger | 446-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BCH001385 | Charger | 446-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BCH001385 | Charger | 446-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.4 | amps |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BCH001385 | Charger | 446-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BCH001385 | Charger | 446-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | BCH001385 | Charger | 446-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | General Comments | | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | General Comments | | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | General Comments | | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | Ambient Temp | 73 | °F |
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 13:24 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CAP000014 | CapacitorBank | 583-Cap Bank | Capacitor Patrol Inspection | All Connections OK? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CAP000014 | CapacitorBank | 583-Cap Bank | Capacitor Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CAP000014 | CapacitorBank | 583-Cap Bank | Capacitor Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CAP000014 | CapacitorBank | 583-Cap Bank | Capacitor Patrol Inspection | Capacitor Condition | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CAP000014 | CapacitorBank | 583-Cap Bank | Capacitor Patrol Inspection | Capacitor Rack Condition OK? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CAP000014 | CapacitorBank | 583-Cap Bank | Capacitor Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CAP000014 | CapacitorBank | 583-Cap Bank | Capacitor Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CAP000014 | CapacitorBank | 583-Cap Bank | Capacitor Patrol Inspection | General Comments | | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CAP000014 | CapacitorBank | 583-Cap Bank | Capacitor Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CAP000014 | CapacitorBank | 583-Cap Bank | Capacitor Patrol Inspection | Insulators In Good Condition? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CAP000014 | CapacitorBank | 583-Cap Bank | Capacitor Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CAP000014 | CapacitorBank | 583-Cap Bank | Capacitor Patrol Inspection | Tank Paint Condition | Adequate | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Unknown Operations | 0 | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Switching Operations | 1 | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Operations This Read Vac | 1 | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Operations Counter AL | 81 | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Operations Counter AF | 80 | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Maintenance Operations | 0 | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | General Comments | BFTC | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Follow-up Action Required? | n | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Fault Operations Ground | 0 | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Amps C Ø | 82.0 | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | 9 Month Operations | 1 | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Amps A Ø | 51.0 | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Amps B Ø | 55.0 | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | General Comments | | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Counter Readings | LTC Operations Since Last Insp | 311 | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Counter Readings | LTC Current Tap Position | 12L | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Counter Readings | LTC As Left Counter | 56034 | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Counter Readings | LTC As Found Counter | 56027 | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Counter Readings | General Comments | | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | LTCC000984 | LTCControl | 583-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | LTCC000984 | LTCControl | 583-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | LTCC000984 | LTCControl | 583-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | LTCC000984 | LTCControl | 583-1 | LTC Control Insp | LTC Output Voltage Level | 123.7 | VAC |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | LTCC000984 | LTCControl | 583-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | LTCC000984 | LTCControl | 583-1 | LTC Control Insp | All Connections OK? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | LTCC000984 | LTCControl | 583-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | LTCC000984 | LTCControl | 583-1 | LTC Control Insp | General Comments | | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Readings | Totalizer Meter Reading | .2958 | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Readings | LTC Totalizer Reading | 2129.76 | kw |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Readings | General Comments | | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | BCH001342 | Charger | 583-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.100 | millivolts |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | BCH001342 | Charger | 583-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | BCH001342 | Charger | 583-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | BCH001342 | Charger | 583-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .2 | amps |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | BCH001342 | Charger | 583-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | BCH001342 | Charger | 583-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | BCH001342 | Charger | 583-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | BCH001342 | Charger | 583-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.2 | VDC |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.2 | VDC |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Exp/Missing Not Repl | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | General Comments | | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | General Comments | | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | General Comments | | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | Ambient Temp | 65 | °F |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol  Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol  Inspection | Acceptable Building Appearnce? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol  Inspection | Broom on Site? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol  Inspection | Control House Lighting OK? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol  Inspection | Controlhouse Grounds in Place? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol  Inspection | Door Alarms OK? | n | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol  Inspection | Floor Swept? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol  Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol  Inspection | Fresh Rat/Mouse Poison? | n | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol  Inspection | General Comments | | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol  Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol  Inspection | Panel Lights OK? | n | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol  Inspection | Panels Dusted? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol  Inspection | Station Ground Set On Site? | n | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol  Inspection | Windows/Doors Condition OK? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol  Inspection | Floor Condition Acceptable? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol  Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol  Inspection | Evidence of Insects | None | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol  Inspection | Doors and Locks Secure? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol  Inspection | Ventilation Free of Debris? | y | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol  Inspection | Trash Emptied? | n | |
| 4/3/2023 12:59 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol  Inspection | Switch Diagram Present/Current | n | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.0 | VDC |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Exp/Missing Not Repl | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Fans Operational? | n | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | General Comments | 1 fan isnt working | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Radiator Leaks | Seeping | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 426158 | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Readings | General Comments | | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Readings | LTC Totalizer Reading | 509.76 | kw |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Readings | Oil Temp Max | 52 | °C |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Counter Readings | LTC Operations Since Last Insp | 469 | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Counter Readings | General Comments | | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Counter Readings | LTC As Found Counter | 434792 | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Counter Readings | LTC As Left Counter | 434805 | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Counter Readings | LTC Current Tap Position | 11L | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Counter Readings | LTC Max Tap Position | 5L | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 853757 | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/4/2023 8:53 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Readings | Totalizer Meter Reading | .2124 | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Fault Operations Ground | 0 | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Follow-up Action Required? | n | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | General Comments | | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Maintenance Operations | 0 | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Operations Counter AF | 36 | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Operations Counter AL | 40 | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Operations This Read Vac | 4 | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Switching Operations | 4 | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Unknown Operations | 0 | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Amps C Ø | 20.0 | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Amps B Ø | 0.0 | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Amps A Ø | 20.0 | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | 9 Month Operations | 5 | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | General Comments | | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | BCH001131 | Charger | 859-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 2.110 | millivolts |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | BCH001131 | Charger | 859-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | BCH001131 | Charger | 859-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | BCH001131 | Charger | 859-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | BCH001131 | Charger | 859-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | BCH001131 | Charger | 859-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | BCH001131 | Charger | 859-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | General Comments | | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | General Comments | | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | LTCC000895 | LTCControl | 859-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | LTCC000895 | LTCControl | 859-1 | LTC Control Insp | VRR Base Voltage AL | 122.0 | VAC |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | LTCC000895 | LTCControl | 859-1 | LTC Control Insp | VRR Base Voltage AF | 122.0 | VAC |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | LTCC000895 | LTCControl | 859-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | LTCC000895 | LTCControl | 859-1 | LTC Control Insp | LTC Output Voltage Level | 122.7 | VAC |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | LTCC000895 | LTCControl | 859-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | LTCC000895 | LTCControl | 859-1 | LTC Control Insp | General Comments | | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | LTCC000895 | LTCControl | 859-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | LTCC000895 | LTCControl | 859-1 | LTC Control Insp | All Connections OK? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | YD000030 | Yard | 859-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | YD000030 | Yard | 859-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | YD000030 | Yard | 859-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | YD000030 | Yard | 859-Yard | Yard Patrol Inspection | General Comments | | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | YD000030 | Yard | 859-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | YD000030 | Yard | 859-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | YD000030 | Yard | 859-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | YD000030 | Yard | 859-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | YD000030 | Yard | 859-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | YD000030 | Yard | 859-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | YD000030 | Yard | 859-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/3/2023 15:10 | Distribution | Turtle Creek Quarterly Inspection | YD000030 | Yard | 859-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Amps A Ø | 31.0 | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Amps B Ø | 31.0 | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Amps C Ø | 15.0 | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Operations Counter | 29 | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | General Comments | | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Operations Counter | 41 | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Amps A Ø | 56.0 | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Amps B Ø | 46.0 | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Amps C Ø | 45.0 | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 102463 | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 53512 | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Max Tap Position | 9R | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 268611 | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1936.80 | kw |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Readings | General Comments | | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .2690 | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | General Comments | | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | General Comments | | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | YD000116 | Yard | 707-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | YD000116 | Yard | 707-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | YD000116 | Yard | 707-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | YD000116 | Yard | 707-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | YD000116 | Yard | 707-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | YD000116 | Yard | 707-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | YD000116 | Yard | 707-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | YD000116 | Yard | 707-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | YD000116 | Yard | 707-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | YD000116 | Yard | 707-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | YD000116 | Yard | 707-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:37 | Distribution | Cawood Quarterly Inspection | YD000116 | Yard | 707-Yard | Yard Patrol Inspection | General Comments | | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Amps A Ø | 18.0 | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Amps C Ø | 22.0 | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | General Comments | BFTC | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Operations Counter | 7 | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Amps B Ø | 23.0 | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Amps A Ø | 6.0 | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Operations Counter | 7 | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Amps B Ø | 6.0 | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | General Comments | BFTC | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Amps C Ø | 3.0 | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | LTCC000673 | LTCControl | 883-1 | LTC Control Insp | VRR Time Delay | 40 | Seconds |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | LTCC000673 | LTCControl | 883-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | LTCC000673 | LTCControl | 883-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | LTCC000673 | LTCControl | 883-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | LTCC000673 | LTCControl | 883-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | LTCC000673 | LTCControl | 883-1 | LTC Control Insp | General Comments | | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | LTCC000673 | LTCControl | 883-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | LTCC000673 | LTCControl | 883-1 | LTC Control Insp | All Connections OK? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Counter Readings | LTC Operations Since Last Insp | 654 | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Counter Readings | LTC Max Tap Position | 3R | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Counter Readings | LTC As Left Counter | 5782 | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Counter Readings | LTC As Found Counter | 5774 | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Counter Readings | General Comments | | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Readings | General Comments | | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Readings | LTC Totalizer Reading | 1850.40 | kw |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Readings | Totalizer Meter Reading | .2570 | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | General Comments | above breaker 4427 on line side, insulator has a large chip in skirt on bottom of line side disconnect | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | General Comments | | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | Ambient Temp | 56 | °F |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | General Comments | | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:54 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | BCH001166 | Charger | 328-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | BCH001166 | Charger | 328-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | BCH001166 | Charger | 328-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | BCH001166 | Charger | 328-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | BCH001166 | Charger | 328-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .700 | millivolts |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | BCH001166 | Charger | 328-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | BCH001166 | Charger | 328-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | BCH001166 | Charger | 328-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 62 | °F |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Broom on Site? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Evidence of Insects | None | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Floor Swept? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | General Comments | | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Trash Emptied? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 56.67 | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.4 | volts |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 126926 | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 95649 | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.7 | volts |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 14 | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 20 | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 2.0 | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 3.0 | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 1.0 | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 16 | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 449 | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 570 | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 388 | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 19.0 | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 17.0 | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 20.0 | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 196449 | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 110834 | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.1 | volts |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 76567 | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 125.0 | volts |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 358947 | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3198.24 | kw |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Readings | General Comments | | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.3326 | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Operations This Read Vac | 9 | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Operations Counter AL | 263 | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Operations Counter AF | 254 | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Maintenance Operations | 0 | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | General Comments | | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Follow-up Action Required? | n | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Fault Operations Ground | 0 | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Amps B Ø | 49.0 | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Amps C Ø | 52.0 | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Amps A Ø | 47.0 | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | 9 Month Operations | 15 | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Unknown Operations | 0 | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Switching Operations | 9 | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 836.64 | kw |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Readings | General Comments | | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Readings | Oil Temp Max | 55 | °C |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Readings | Oil Temp Present | 45 | °C |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .6972 | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 96.00 | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | General Comments | | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | General Comments | | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | YD000009 | Yard | 810-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | YD000009 | Yard | 810-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | YD000009 | Yard | 810-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | YD000009 | Yard | 810-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | YD000009 | Yard | 810-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | YD000009 | Yard | 810-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | YD000009 | Yard | 810-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | YD000009 | Yard | 810-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | YD000009 | Yard | 810-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | YD000009 | Yard | 810-Yard | Yard Patrol Inspection | General Comments | | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | YD000009 | Yard | 810-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | YD000009 | Yard | 810-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/3/2023 11:27 | Distribution | Holmes Mill Quarterly Inspection | YD000009 | Yard | 810-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | General Comments | | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Operations Counter | 2337 | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | General Comments | BFTC | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | n | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Amps C Ø | 0.0 | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Amps B Ø | 0.0 | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Amps A Ø | 0.0 | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | X0113 | RecloserHydraulic | 544-0429 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | X0113 | RecloserHydraulic | 544-0429 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0.0 | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | X0113 | RecloserHydraulic | 544-0429 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | X0113 | RecloserHydraulic | 544-0429 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | X0113 | RecloserHydraulic | 544-0429 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | X0113 | RecloserHydraulic | 544-0429 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | X0113 | RecloserHydraulic | 544-0429 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | X0113 | RecloserHydraulic | 544-0429 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | X0113 | RecloserHydraulic | 544-0429 | Recloser Hydraulic Patrol Inspection | General Comments | BFTC | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | X0113 | RecloserHydraulic | 544-0429 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | X0113 | RecloserHydraulic | 544-0429 | Recloser Hydraulic Patrol Inspection | Operations Counter | 184 | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | X0113 | RecloserHydraulic | 544-0429 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | X0113 | RecloserHydraulic | 544-0429 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 95050 | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 126765 | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 0.00 | kw |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Readings | General Comments | | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Readings | Oil Temp Max | 59 | °C |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Readings | Oil Temp Present | 34 | °C |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | General Comments | | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | n | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | General Comments | | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | YD000071 | Yard | 544-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | YD000071 | Yard | 544-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | YD000071 | Yard | 544-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Exp Boom Corrected | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | YD000071 | Yard | 544-Yard | Yard Patrol Inspection | General Comments | | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | YD000071 | Yard | 544-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | YD000071 | Yard | 544-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | YD000071 | Yard | 544-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | YD000071 | Yard | 544-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | YD000071 | Yard | 544-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | YD000071 | Yard | 544-Yard | Yard Patrol Inspection | Ambient Temp | 54 | °F |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | YD000071 | Yard | 544-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | YD000071 | Yard | 544-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/3/2023 11:11 | Distribution | Liggett Quarterly Inspection | YD000071 | Yard | 544-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | General Comments | | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | General Comments | | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | General Comments | | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/3/2023 12:34 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | 9 Month Operations | 4 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Fault Adjusted Amps A Phase V | 5.20 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Fault Adjusted Amps B Phase V | 5.20 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Fault Adjusted Amps C Phase V | 5.20 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Fault Operations A Ø | 1 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Amps A Ø | 31.0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Fault Operations B Ø | 1 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Fault Operations C Ø | 1 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Fault Operations Ground | 0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Follow-up Action Required? | n | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | General Comments | | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Amps C Ø | 38.0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Amps B Ø | 30.0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Maintenance Operations | 0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Operations Counter AF | 177 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Operations Counter AL | 177 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Operations This Read Vac | 4 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Switching Operations | 1 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Unknown Operations | 0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Unknown Operations | 0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Switching Operations | 0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Operations This Read Vac | 0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Operations Counter AL | 173 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Operations Counter AF | 173 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Maintenance Operations | 0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | General Comments | | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Follow-up Action Required? | n | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Fault Operations Ground | 0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Amps C Ø | 39.0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Amps B Ø | 51.0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Amps A Ø | 79.0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | 9 Month Operations | 0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Patrol Inspection | General Comments | | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Unknown Operations | 0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Switching Operations | 0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Operations This Read Vac | 0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Operations Counter AL | 202 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Fault Operations Ground | 0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Operations Counter AF | 202 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Maintenance Operations | 0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | General Comments | | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Follow-up Action Required? | n | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Amps C Ø | 60.0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | 9 Month Operations | 1 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Amps A Ø | 55.0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Amps B Ø | 67.0 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Patrol Inspection | General Comments | | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Patrol Inspection | General Comments | | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.6 | volts |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 47358 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 41730 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.3 | volts |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 52356 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Min Tap Position | 3L | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Readings | General Comments | | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 9982.08 | kw |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.0398 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | General Comments | | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BAT001456 | Battery | 580-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BAT001456 | Battery | 580-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 56 | °F |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BAT001456 | Battery | 580-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BAT001456 | Battery | 580-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BAT001456 | Battery | 580-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BAT001456 | Battery | 580-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BAT001456 | Battery | 580-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BAT001456 | Battery | 580-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BAT001456 | Battery | 580-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BAT001456 | Battery | 580-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BAT001456 | Battery | 580-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BAT001456 | Battery | 580-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BAT001456 | Battery | 580-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BCH001357 | Charger | 580-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BCH001357 | Charger | 580-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BCH001357 | Charger | 580-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BCH001357 | Charger | 580-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.5 | amps |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BCH001357 | Charger | 580-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BCH001357 | Charger | 580-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BCH001357 | Charger | 580-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | BCH001357 | Charger | 580-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Readings | General Comments | | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Readings | Totalizer Meter Reading | .3720 | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Readings | Oil Temp Present | 33 | °C |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Readings | Non LTC Totalizer Reading | 446.40 | kw |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 236774 | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 167561 | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.7 | volts |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 62125 | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 35 | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Amps A Ø | 12.0 | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Amps B Ø | 15.0 | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Amps C Ø | 20.0 | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 3 | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 64 | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 52.50 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Readings | General Comments | | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Readings | Oil Temp Present | 33 | °C |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Readings | General Comments | | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 52.50 | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | General Comments | | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | General Comments | | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | YD000056 | Yard | 555-Yard | Yard Patrol Inspection | Ambient Temp | 46 | °F |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | YD000056 | Yard | 555-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | YD000056 | Yard | 555-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | YD000056 | Yard | 555-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | YD000056 | Yard | 555-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | YD000056 | Yard | 555-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | YD000056 | Yard | 555-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | YD000056 | Yard | 555-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Exp Boom Needs Corr | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | YD000056 | Yard | 555-Yard | Yard Patrol Inspection | General Comments | | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | YD000056 | Yard | 555-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | YD000056 | Yard | 555-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | YD000056 | Yard | 555-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/3/2023 11:58 | Distribution | Daniel Branch Quarterly Inspection | YD000056 | Yard | 555-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | General Comments | | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | Ambient Temp | 56 | °F |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | General Comments | | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/3/2023 10:32 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BAT001121 | Battery | 550-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BAT001121 | Battery | 550-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BAT001121 | Battery | 550-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BAT001121 | Battery | 550-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.0 | VDC |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BAT001121 | Battery | 550-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BAT001121 | Battery | 550-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BAT001121 | Battery | 550-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BAT001121 | Battery | 550-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BAT001121 | Battery | 550-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BAT001121 | Battery | 550-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BAT001121 | Battery | 550-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BAT001121 | Battery | 550-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 49 | °F |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BAT001121 | Battery | 550-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BCH001471 | Charger | 550-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BCH001471 | Charger | 550-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BCH001471 | Charger | 550-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BCH001471 | Charger | 550-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BCH001471 | Charger | 550-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BCH001471 | Charger | 550-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BCH001471 | Charger | 550-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BCH001471 | Charger | 550-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 137020 | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | General Comments | | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | General Comments | | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 76269 | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 469873 | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | General Comments | | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Operations Counter AF | 176 | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Operations Counter AL | 176 | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | General Comments | | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Follow-up Action Required? | n | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Fault Operations Ground | 0 | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Fault Operations C Ø | 0 | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Fault Operations B Ø | 0 | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Fault Operations A Ø | 0 | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Amps C Ø | 0.0 | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Amps B Ø | 1.0 | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Amps A Ø | 1.0 | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | 9 Month Operations | 1 | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Operations This Read Vac | 0 | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Unknown Operations | 0 | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Switching Operations | 0 | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .6042 | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 800 | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Readings | Oil Temp Max | 57 | °C |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 55.00 | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 483.36 | kw |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Readings | General Comments | | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 62.50 | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Patrol Inspection | Grounds in Place? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Patrol Inspection | General Comments | | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Patrol Inspection | Bushing Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | General Comments | | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | General Comments | | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | General Comments | No berm in station | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Vegetation | None | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 4/3/2023 9:11 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Ambient Temp | 49 | °F |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Patrol Inspection | General Comments | | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Readings | Unknown Operations | 0 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Readings | Switching Operations | 0 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Readings | Operations This Read Vac | 2 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Readings | Operations Counter AL | 225 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Readings | Operations Counter AF | 225 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Readings | Maintenance Operations | 0 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Readings | General Comments | | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Readings | Follow-up Action Required? | n | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Readings | Fault Operations Ground | 0 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Readings | Fault Operations B Ø | 2 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Readings | Fault Adjusted Amps B Phase V | 8.87 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Readings | Amps C Ø | 92.0 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Readings | Amps B Ø | 85.0 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Readings | Amps A Ø | 114.0 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BK001333 | BreakerVacuum | 868-4502 | VCB Readings | 9 Month Operations | 3 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Patrol Inspection | General Comments | | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Readings | Operations Counter AL | 232 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Readings | Unknown Operations | 0 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Readings | Amps A Ø | 118.0 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Readings | Amps B Ø | 120.0 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Readings | Amps C Ø | 104.0 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Readings | Operations Counter AF | 232 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Readings | Maintenance Operations | 3 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Readings | Switching Operations | 1 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Readings | Operations This Read Vac | 4 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Readings | 9 Month Operations | 4 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Readings | General Comments | | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Readings | Follow-up Action Required? | n | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Readings | Fault Operations Ground | 0 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | KB0115 | BreakerVacuum | 868-4500 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Readings | Switching Operations | 1 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Readings | Operations This Read Vac | 6 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Readings | Operations Counter AL | 165 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Readings | Operations Counter AF | 165 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Readings | Maintenance Operations | 4 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Readings | General Comments | | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Readings | Unknown Operations | 0 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Readings | Follow-up Action Required? | n | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Readings | Fault Operations Ground | 0 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Readings | Fault Operations A Ø | 1 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Readings | Fault Adjusted Amps A Phase V | 4.44 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Readings | Amps C Ø | 92.0 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Readings | Amps B Ø | 90.0 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Readings | Amps A Ø | 74.0 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Readings | 9 Month Operations | 6 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Patrol Inspection | General Comments | | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | K0201 | BreakerVacuum | 868-4501 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | LTCMechanism | 868-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | LTCMechanism | 868-1 | LTC Counter Readings | General Comments | | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | LTCMechanism | 868-1 | LTC Counter Readings | LTC As Found Counter | 54302 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | LTCMechanism | 868-1 | LTC Counter Readings | LTC As Left Counter | 54312 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | LTCMechanism | 868-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | LTCMechanism | 868-1 | LTC Counter Readings | LTC Max Tap Position | 11R | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | LTCMechanism | 868-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | LTCMechanism | 868-1 | LTC Counter Readings | LTC Operations Since Last Insp | 1786 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | LTCMechanism | 868-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | LTCC000848 | LTCControl | 868-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | LTCC000848 | LTCControl | 868-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | LTCC000848 | LTCControl | 868-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | LTCC000848 | LTCControl | 868-1 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | LTCC000848 | LTCControl | 868-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | LTCC000848 | LTCControl | 868-1 | LTC Control Insp | General Comments | | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | LTCC000848 | LTCControl | 868-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | LTCC000848 | LTCControl | 868-1 | LTC Control Insp | All Connections OK? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | LTCMechanism | 868-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | LTCMechanism | 868-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | LTCMechanism | 868-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | LTCMechanism | 868-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | LTCMechanism | 868-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | LTCMechanism | 868-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Readings | General Comments | | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Readings | LTC Totalizer Reading | 10101.60 | kw |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Readings | Oil Temp Max | 102 | °C |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Readings | Oil Temp Present | 50 | °C |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.4030 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 245.00 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | M0072 | WithLTC | 868-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BCH001350 | Charger | 868-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.800 | millivolts |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BCH001350 | Charger | 868-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BCH001350 | Charger | 868-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BCH001350 | Charger | 868-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.2 | amps |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BCH001350 | Charger | 868-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BCH001350 | Charger | 868-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BCH001350 | Charger | 868-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BCH001350 | Charger | 868-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BAT000160 | Battery | 868-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.2 | VDC |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BAT000160 | Battery | 868-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.2 | VDC |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BAT000160 | Battery | 868-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BAT000160 | Battery | 868-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BAT000160 | Battery | 868-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BAT000160 | Battery | 868-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #'s |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BAT000160 | Battery | 868-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BAT000160 | Battery | 868-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BAT000160 | Battery | 868-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BAT000160 | Battery | 868-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BAT000160 | Battery | 868-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BAT000160 | Battery | 868-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BAT000160 | Battery | 868-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | BAT000160 | Battery | 868-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | CH000244 | ControlHouse | 868-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | CH000244 | ControlHouse | 868-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | CH000244 | ControlHouse | 868-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | CH000244 | ControlHouse | 868-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | CH000244 | ControlHouse | 868-Control House | Control House Patrol Inspection | General Comments | | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | CH000244 | ControlHouse | 868-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | CH000244 | ControlHouse | 868-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | CH000244 | ControlHouse | 868-Control House | Control House Patrol Inspection | Floor Swept? | n | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | CH000244 | ControlHouse | 868-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | CH000244 | ControlHouse | 868-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | CH000244 | ControlHouse | 868-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | CH000244 | ControlHouse | 868-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | CH000244 | ControlHouse | 868-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | CH000244 | ControlHouse | 868-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | CH000244 | ControlHouse | 868-Control House | Control House Patrol Inspection | Broom on Site? | n | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | CH000244 | ControlHouse | 868-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | CH000244 | ControlHouse | 868-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | ST000025 | Structure | 868-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | ST000025 | Structure | 868-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | ST000025 | Structure | 868-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | ST000025 | Structure | 868-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | ST000025 | Structure | 868-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | ST000025 | Structure | 868-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | ST000025 | Structure | 868-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | ST000025 | Structure | 868-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | ST000025 | Structure | 868-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | ST000025 | Structure | 868-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | ST000025 | Structure | 868-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | ST000025 | Structure | 868-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | ST000025 | Structure | 868-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | ST000025 | Structure | 868-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | ST000025 | Structure | 868-Structure | Structure Patrol Inspection | General Comments | | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | ST000025 | Structure | 868-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | ST000025 | Structure | 868-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | ST000025 | Structure | 868-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | ST000025 | Structure | 868-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | ST000025 | Structure | 868-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | ST000025 | Structure | 868-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | ST000025 | Structure | 868-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | FE000030 | Fence | 868-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | FE000030 | Fence | 868-Fence | Fence Patrol Inspection | General Comments | | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | FE000030 | Fence | 868-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | FE000030 | Fence | 868-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | FE000030 | Fence | 868-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | FE000030 | Fence | 868-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | FE000030 | Fence | 868-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | FE000030 | Fence | 868-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | FE000030 | Fence | 868-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | FE000030 | Fence | 868-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | FE000030 | Fence | 868-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | FE000030 | Fence | 868-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | FE000030 | Fence | 868-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | FE000030 | Fence | 868-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | FE000030 | Fence | 868-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | FE000030 | Fence | 868-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | YD000025 | Yard | 868-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | YD000025 | Yard | 868-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | YD000025 | Yard | 868-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | YD000025 | Yard | 868-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | YD000025 | Yard | 868-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | YD000025 | Yard | 868-Yard | Yard Patrol Inspection | Ambient Temp | 64 | °F |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | YD000025 | Yard | 868-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | YD000025 | Yard | 868-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | YD000025 | Yard | 868-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | YD000025 | Yard | 868-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | YD000025 | Yard | 868-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | YD000025 | Yard | 868-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | YD000025 | Yard | 868-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/31/2023 7:27 | Distribution | Somerset 3 Quarterly Inspection | YD000025 | Yard | 868-Yard | Yard Patrol Inspection | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Amps C Ø | 0.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Amps B Ø | 0.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Amps A Ø | 0.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | 9 Month Operations | 4 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Operations Counter AF | 244 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Operations Counter AL | 244 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Operations This Read Vac | 3 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Switching Operations | 3 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000074 | BreakerVacuum | HK-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Operations Counter AF | 287 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Operations Counter AL | 287 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Operations This Read Vac | 1 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Switching Operations | 1 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Amps C Ø | 15.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Amps B Ø | 15.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Amps A Ø | 15.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Readings | 9 Month Operations | 2 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000071 | BreakerVacuum | HK-1245 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | 9 Month Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Amps A Ø | 0.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Amps B Ø | 0.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Amps C Ø | 0.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Operations Counter AF | 184 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Operations Counter AL | 184 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Operations This Read Vac | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Switching Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000070 | BreakerVacuum | HK-1244 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Amps C Ø | 120.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Amps B Ø | 120.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Amps A Ø | 130.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | 9 Month Operations | 5 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Switching Operations | 4 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Operations This Read Vac | 4 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Operations Counter AL | 359 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Operations Counter AF | 359 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000069 | BreakerVacuum | HK-1243 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | 9 Month Operations | 3 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Amps A Ø | 65.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Amps B Ø | 60.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Amps C Ø | 75.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Operations Counter AF | 177 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Switching Operations | 3 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Operations This Read Vac | 3 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Readings | Operations Counter AL | 177 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000068 | BreakerVacuum | HK-1242 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Amps C Ø | 45.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Amps B Ø | 50.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Amps A Ø | 40.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | 9 Month Operations VCB New | 15 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | 9 Month Operations | 23 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Operations Counter AF | 371 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Operations Counter AL | 371 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Operations This Read Vac | 8 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Switching Operations | 8 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000060 | BreakerVacuum | HK-1241 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | 9 Month Operations | 3 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Amps A Ø | 250.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Amps B Ø | 240.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Amps C Ø | 250.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Operations Counter AF | 183 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Operations Counter AL | 183 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Operations This Read Vac | 2 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Switching Operations | 2 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000066 | BreakerVacuum | HK-12KV TR 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | PF001161 | PowerFuse | HK-12KV TR 3 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | PF001161 | PowerFuse | HK-12KV TR 3 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Vent Fans OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000199 | Switchgear | HK-Swgr Sec 3 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | PF001162 | PowerFuse | HK-STA SER NO 3 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | PF001162 | PowerFuse | HK-STA SER NO 3 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LTCC000099 | LTCControl | HK-TRANS 3 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LTCC000099 | LTCControl | HK-TRANS 3 | LTC Control Insp | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LTCC000099 | LTCControl | HK-TRANS 3 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LTCC000099 | LTCControl | HK-TRANS 3 | LTC Control Insp | All Connections OK? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Counter Readings | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Counter Readings | LTC As Found Counter | 53744 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Counter Readings | LTC As Left Counter | 53744 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Counter Readings | LTC Operations Since Last Insp | 844 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 24 | °C |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 35 | °C |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | LTCMechanism | HK-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Max | 30 | °C |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Readings | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Readings | Oil Temp Present | 24 | °C |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Present | 24 | °C |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Max | 35 | °C |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Present | 24 | °C |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Max | 35 | °C |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Present | 18 | °C |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | General Comments | The low side bus/ bushings has animal guard that has shifted or started coming undone.  There are parts of the bus that are exposed t | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1200 | psi |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0320 | WithLTC | HK-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Unknown Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Switching Operations | 5 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Operations This Read AM | 5 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Operations Counter AL | 139 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Operations Counter AF | 139 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Amps C Ø | 0.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Amps B Ø | 0.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Amps A Ø | 0.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | 9 Months Operations | 5 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0454 | BreakerAirMagnetic | HK-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Unknown Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Switching Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Operations This Read AM | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Operations Counter AL | 41 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Operations Counter AF | 41 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Amps C Ø | 0.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Amps B Ø | 0.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Amps A Ø | 0.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | 9 Months Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0451 | BreakerAirMagnetic | HK-1239 | AMCB Patrol Inspection | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | 9 Month Ops New | 3 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | 9 Months Operations | 3 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Amps A Ø | 15.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Amps B Ø | 30.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Amps C Ø | 25.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Operations Counter AF | 253 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Operations Counter AL | 253 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Operations This Read AM | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Switching Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Readings | Unknown Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Patrol Inspection | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0450 | BreakerAirMagnetic | HK-1238 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | 9 Months Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Amps A Ø | 0.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Amps B Ø | 0.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Amps C Ø | 0.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Operations Counter AF | 429 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Operations Counter AL | 429 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Operations This Read AM | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Switching Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Readings | Unknown Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0449 | BreakerAirMagnetic | HK-1237 | AMCB Patrol Inspection | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Unknown Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Switching Operations | 8 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Operations This Read AM | 8 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Operations Counter AL | 334 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Operations Counter AF | 334 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Amps B Ø | 175.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Amps A Ø | 150.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | 9 Months Operations | 14 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | 9 Month Ops New | 6 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Amps C Ø | 180.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0446 | BreakerAirMagnetic | HK-1234 | AMCB Patrol Inspection | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | 9 Months Operations | 1 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Amps A Ø | 160.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Amps B Ø | 200.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Unknown Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Switching Operations | 1 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Operations This Read AM | 1 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Operations Counter AF | 94 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Operations Counter AL | 94 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Readings | Amps C Ø | 200.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Patrol Inspection | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LB0456 | BreakerAirMagnetic | HK-12KV TR 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | PF000184 | PowerFuse | HK-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | PF000184 | PowerFuse | HK-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | PF000183 | PowerFuse | HK-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | PF000183 | PowerFuse | HK-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000128 | Switchgear | HK-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | PF000182 | PowerFuse | HK-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | PF000182 | PowerFuse | HK-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | Seeping | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 500 | psi |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | Replaced bad fuse for heaters in control cabinet.  There are several radiators that are seeping oil. | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Readings | Amps A Ø | 97.0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Readings | Amps B Ø | 95.0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Readings | Amps C Ø | 85.0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Readings | 9 Month Operations | 4 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Readings | General Comments | | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Readings | Operations Counter AF | 191 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Readings | Operations Counter AL | 191 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Readings | Operations This Read Vac | 0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Readings | Switching Operations | 0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001438 | BreakerVacuum | 790-0531 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Readings | 9 Month Operations | 5 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Readings | Switching Operations | 0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Readings | Operations This Read Vac | 0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Readings | Operations Counter AL | 169 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Readings | Operations Counter AF | 169 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Readings | Amps A Ø | 29.0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Readings | Amps B Ø | 54.0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Readings | General Comments | | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Readings | Amps C Ø | 31.0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BK001437 | BreakerVacuum | 790-0530 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Readings | 9 Month Operations | 4 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Readings | Amps A Ø | 157.0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Readings | Amps B Ø | 148.0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Readings | Amps C Ø | 152.0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Readings | Fault Adjusted Amps A Phase V | 4.69 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Readings | Fault Operations A Ø | 1 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Readings | General Comments | | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Readings | Operations Counter AF | 340 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Readings | Operations Counter AL | 340 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Readings | Operations This Read Vac | 1 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Readings | Switching Operations | 0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | K0029 | BreakerVacuum | 790-0529 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | LTCMechanism | 790-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | LTCMechanism | 790-1 | LTC Counter Readings | General Comments | | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | LTCMechanism | 790-1 | LTC Counter Readings | LTC As Found Counter | 67933 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | LTCMechanism | 790-1 | LTC Counter Readings | LTC As Left Counter | 67941 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | LTCMechanism | 790-1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | LTCMechanism | 790-1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | LTCMechanism | 790-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | LTCMechanism | 790-1 | LTC Counter Readings | LTC Operations Since Last Insp | 488 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | LTCMechanism | 790-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0096 | RecloserElectronic | 604-2445 | Recloser Electronic Patrol Inspection | Amps B Ø | 11 | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0096 | RecloserElectronic | 604-2445 | Recloser Electronic Patrol Inspection | Amps A Ø | 12 | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0096 | RecloserElectronic | 604-2445 | Recloser Electronic Patrol Inspection | Amps C Ø | 14 | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0096 | RecloserElectronic | 604-2445 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0096 | RecloserElectronic | 604-2445 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0096 | RecloserElectronic | 604-2445 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0096 | RecloserElectronic | 604-2445 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0096 | RecloserElectronic | 604-2445 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0096 | RecloserElectronic | 604-2445 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0096 | RecloserElectronic | 604-2445 | Recloser Electronic Patrol Inspection | Operations Counter | 32 | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0096 | RecloserElectronic | 604-2445 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0096 | RecloserElectronic | 604-2445 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0096 | RecloserElectronic | 604-2445 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0096 | RecloserElectronic | 604-2445 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0096 | RecloserElectronic | 604-2445 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0096 | RecloserElectronic | 604-2445 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0096 | RecloserElectronic | 604-2445 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0096 | RecloserElectronic | 604-2445 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0096 | RecloserElectronic | 604-2445 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0096 | RecloserElectronic | 604-2445 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0095 | RecloserElectronic | 604-2444 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0095 | RecloserElectronic | 604-2444 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0095 | RecloserElectronic | 604-2444 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0095 | RecloserElectronic | 604-2444 | Recloser Electronic Patrol Inspection | Operations Counter | 24 | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0095 | RecloserElectronic | 604-2444 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0095 | RecloserElectronic | 604-2444 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0095 | RecloserElectronic | 604-2444 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0095 | RecloserElectronic | 604-2444 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0095 | RecloserElectronic | 604-2444 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0095 | RecloserElectronic | 604-2444 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0095 | RecloserElectronic | 604-2444 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0095 | RecloserElectronic | 604-2444 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0095 | RecloserElectronic | 604-2444 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0095 | RecloserElectronic | 604-2444 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0095 | RecloserElectronic | 604-2444 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0095 | RecloserElectronic | 604-2444 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0095 | RecloserElectronic | 604-2444 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0095 | RecloserElectronic | 604-2444 | Recloser Electronic Patrol Inspection | Amps C Ø | 60 | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0095 | RecloserElectronic | 604-2444 | Recloser Electronic Patrol Inspection | Amps B Ø | 61 | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0095 | RecloserElectronic | 604-2444 | Recloser Electronic Patrol Inspection | Amps A Ø | 68 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | LTCC000921 | LTCControl | 790-1 | LTC Control Insp | VRR Base Voltage AL | 123.8 | VAC |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | LTCC000921 | LTCControl | 790-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | LTCC000921 | LTCControl | 790-1 | LTC Control Insp | VRR Base Voltage AF | 124.6 | VAC |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | LTCC000921 | LTCControl | 790-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | LTCC000921 | LTCControl | 790-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | LTCC000921 | LTCControl | 790-1 | LTC Control Insp | General Comments | | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | LTCC000921 | LTCControl | 790-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | LTCC000921 | LTCControl | 790-1 | LTC Control Insp | All Connections OK? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | LTCMechanism | 790-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | LTCMechanism | 790-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | LTCMechanism | 790-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | LTCMechanism | 790-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | LTCMechanism | 790-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Readings | General Comments | | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Readings | LTC Totalizer Reading | 7954.56 | kw |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Readings | Oil Temp Max | 41 | °C |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Readings | Oil Temp Present | 31 | °C |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Readings | Totalizer Meter Reading | .8286 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 65.00 | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0098 | RecloserElectronic | 604-2333 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0098 | RecloserElectronic | 604-2333 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0098 | RecloserElectronic | 604-2333 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0098 | RecloserElectronic | 604-2333 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0098 | RecloserElectronic | 604-2333 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0098 | RecloserElectronic | 604-2333 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0098 | RecloserElectronic | 604-2333 | Recloser Electronic Patrol Inspection | Amps A Ø | 13 | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0098 | RecloserElectronic | 604-2333 | Recloser Electronic Patrol Inspection | Operations Counter | 10 | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0098 | RecloserElectronic | 604-2333 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0098 | RecloserElectronic | 604-2333 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0098 | RecloserElectronic | 604-2333 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0098 | RecloserElectronic | 604-2333 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0098 | RecloserElectronic | 604-2333 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0098 | RecloserElectronic | 604-2333 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0098 | RecloserElectronic | 604-2333 | Recloser Electronic Patrol Inspection | Amps B Ø | 11 | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0098 | RecloserElectronic | 604-2333 | Recloser Electronic Patrol Inspection | Amps C Ø | 9 | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0098 | RecloserElectronic | 604-2333 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0098 | RecloserElectronic | 604-2333 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0098 | RecloserElectronic | 604-2333 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0098 | RecloserElectronic | 604-2333 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | B0477 | WithLTC | 790-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BAT001196 | Battery | 790-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BAT001196 | Battery | 790-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BAT001196 | Battery | 790-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BAT001196 | Battery | 790-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BAT001196 | Battery | 790-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BAT001196 | Battery | 790-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BAT001196 | Battery | 790-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BAT001196 | Battery | 790-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BAT001196 | Battery | 790-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BAT001196 | Battery | 790-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Exp/Missing Not Repl | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BAT001196 | Battery | 790-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BAT001196 | Battery | 790-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BAT001196 | Battery | 790-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.3 | VDC |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BAT001196 | Battery | 790-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.2 | VDC |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BAT001196 | Battery | 790-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0097 | RecloserElectronic | 604-2446 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0097 | RecloserElectronic | 604-2446 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0097 | RecloserElectronic | 604-2446 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0097 | RecloserElectronic | 604-2446 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0097 | RecloserElectronic | 604-2446 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0097 | RecloserElectronic | 604-2446 | Recloser Electronic Patrol Inspection | Operations Counter | 26 | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0097 | RecloserElectronic | 604-2446 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0097 | RecloserElectronic | 604-2446 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0097 | RecloserElectronic | 604-2446 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0097 | RecloserElectronic | 604-2446 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0097 | RecloserElectronic | 604-2446 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0097 | RecloserElectronic | 604-2446 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0097 | RecloserElectronic | 604-2446 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0097 | RecloserElectronic | 604-2446 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0097 | RecloserElectronic | 604-2446 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0097 | RecloserElectronic | 604-2446 | Recloser Electronic Patrol Inspection | Amps A Ø | 37 | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0097 | RecloserElectronic | 604-2446 | Recloser Electronic Patrol Inspection | Amps B Ø | 44 | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0097 | RecloserElectronic | 604-2446 | Recloser Electronic Patrol Inspection | Amps C Ø | 36 | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0097 | RecloserElectronic | 604-2446 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | KX0097 | RecloserElectronic | 604-2446 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BCH001390 | Charger | 790-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BCH001390 | Charger | 790-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.3 | VDC |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BCH001390 | Charger | 790-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.3 | VDC |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BCH001390 | Charger | 790-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.5 | amps |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BCH001390 | Charger | 790-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BCH001390 | Charger | 790-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BCH001390 | Charger | 790-Battery Charger | Battery Charger Patrol Insp | General Comments | meter unable to read ripple | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | BCH001390 | Charger | 790-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | LTCC000316 | LTCControl | 604-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | LTCC000316 | LTCControl | 604-1 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | LTCC000316 | LTCControl | 604-1 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | LTCC000316 | LTCControl | 604-1 | LTC Control Insp | LTC Output Voltage Level | 125.1 | VAC |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | LTCC000316 | LTCControl | 604-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | LTCC000316 | LTCControl | 604-1 | LTC Control Insp | General Comments | | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | LTCC000316 | LTCControl | 604-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | LTCC000316 | LTCControl | 604-1 | LTC Control Insp | All Connections OK? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | CH000416 | ControlHouse | 790-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | CH000416 | ControlHouse | 790-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | CH000416 | ControlHouse | 790-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | CH000416 | ControlHouse | 790-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | CH000416 | ControlHouse | 790-Control House | Control House Patrol Inspection | Broom on Site? | n | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | CH000416 | ControlHouse | 790-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | CH000416 | ControlHouse | 790-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | CH000416 | ControlHouse | 790-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | CH000416 | ControlHouse | 790-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | CH000416 | ControlHouse | 790-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | CH000416 | ControlHouse | 790-Control House | Control House Patrol Inspection | General Comments | | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | CH000416 | ControlHouse | 790-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | CH000416 | ControlHouse | 790-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | CH000416 | ControlHouse | 790-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | CH000416 | ControlHouse | 790-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | CH000416 | ControlHouse | 790-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | CH000416 | ControlHouse | 790-Control House | Control House Patrol Inspection | Floor Swept? | n | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | ST000183 | Structure | 790-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | ST000183 | Structure | 790-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | ST000183 | Structure | 790-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | ST000183 | Structure | 790-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | ST000183 | Structure | 790-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | ST000183 | Structure | 790-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | ST000183 | Structure | 790-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | ST000183 | Structure | 790-Structure | Structure Patrol Inspection | General Comments | | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | ST000183 | Structure | 790-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | ST000183 | Structure | 790-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | ST000183 | Structure | 790-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | ST000183 | Structure | 790-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | ST000183 | Structure | 790-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | ST000183 | Structure | 790-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | ST000183 | Structure | 790-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | ST000183 | Structure | 790-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | ST000183 | Structure | 790-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | ST000183 | Structure | 790-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | ST000183 | Structure | 790-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | ST000183 | Structure | 790-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | ST000183 | Structure | 790-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | ST000183 | Structure | 790-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | FE000834 | Fence | 790-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | FE000834 | Fence | 790-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | FE000834 | Fence | 790-Fence | Fence Patrol Inspection | General Comments | | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | FE000834 | Fence | 790-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | FE000834 | Fence | 790-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | FE000834 | Fence | 790-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | FE000834 | Fence | 790-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | FE000834 | Fence | 790-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | FE000834 | Fence | 790-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | FE000834 | Fence | 790-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | FE000834 | Fence | 790-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | FE000834 | Fence | 790-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | FE000834 | Fence | 790-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | FE000834 | Fence | 790-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | FE000834 | Fence | 790-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | FE000834 | Fence | 790-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | YD000176 | Yard | 790-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | YD000176 | Yard | 790-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | YD000176 | Yard | 790-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | YD000176 | Yard | 790-Yard | Yard Patrol Inspection | General Comments | | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | YD000176 | Yard | 790-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | YD000176 | Yard | 790-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | YD000176 | Yard | 790-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | YD000176 | Yard | 790-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | YD000176 | Yard | 790-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | YD000176 | Yard | 790-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | YD000176 | Yard | 790-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/30/2023 12:02 | Distribution | Denham Street Quarterly Inspection | YD000176 | Yard | 790-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | LTCMechanism | 604-1 | LTC Counter Readings | LTC Max Tap Position | 5R | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | LTCMechanism | 604-1 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | LTCMechanism | 604-1 | LTC Counter Readings | LTC As Left Counter | 13877 | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | LTCMechanism | 604-1 | LTC Counter Readings | LTC As Found Counter | 13875 | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | LTCMechanism | 604-1 | LTC Counter Readings | General Comments | | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | LTCMechanism | 604-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | LTCMechanism | 604-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | LTCMechanism | 604-1 | LTC Counter Readings | LTC Operations Since Last Insp | 305 | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | LTCMechanism | 604-1 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | LTCMechanism | 604-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | LTCMechanism | 604-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | LTCMechanism | 604-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0 | psi |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | LTCMechanism | 604-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | LTCMechanism | 604-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | LTCMechanism | 604-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Readings | General Comments | | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Readings | LTC Totalizer Reading | 5391.36 | kw |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45 | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Readings | Winding Temp Present | 38 | °C |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Readings | Winding Temp Max | 42 | °C |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Readings | Totalizer Meter Reading | .7488 | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Readings | Oil Temp Present | 38 | °C |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | C0412 | WithLTC | 604-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | ST000439 | Structure | 604-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | ST000439 | Structure | 604-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | ST000439 | Structure | 604-Structure | Structure Patrol Inspection | General Comments | | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | ST000439 | Structure | 604-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | ST000439 | Structure | 604-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | ST000439 | Structure | 604-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | ST000439 | Structure | 604-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | ST000439 | Structure | 604-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | ST000439 | Structure | 604-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | ST000439 | Structure | 604-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | ST000439 | Structure | 604-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | ST000439 | Structure | 604-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | ST000439 | Structure | 604-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | ST000439 | Structure | 604-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | ST000439 | Structure | 604-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | ST000439 | Structure | 604-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | ST000439 | Structure | 604-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | ST000439 | Structure | 604-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | ST000439 | Structure | 604-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | ST000439 | Structure | 604-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | ST000439 | Structure | 604-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | ST000439 | Structure | 604-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | FE000432 | Fence | 604-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | FE000432 | Fence | 604-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | FE000432 | Fence | 604-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | FE000432 | Fence | 604-Fence | Fence Patrol Inspection | General Comments | | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | FE000432 | Fence | 604-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | FE000432 | Fence | 604-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | FE000432 | Fence | 604-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | FE000432 | Fence | 604-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | FE000432 | Fence | 604-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | FE000432 | Fence | 604-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | FE000432 | Fence | 604-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | FE000432 | Fence | 604-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | FE000432 | Fence | 604-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | FE000432 | Fence | 604-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | FE000432 | Fence | 604-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | FE000432 | Fence | 604-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | YD000436 | Yard | 604-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | YD000436 | Yard | 604-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | YD000436 | Yard | 604-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | YD000436 | Yard | 604-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | YD000436 | Yard | 604-Yard | Yard Patrol Inspection | General Comments | | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | YD000436 | Yard | 604-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | YD000436 | Yard | 604-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | YD000436 | Yard | 604-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | YD000436 | Yard | 604-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | YD000436 | Yard | 604-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | YD000436 | Yard | 604-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | YD000436 | Yard | 604-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | YD000436 | Yard | 604-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | YD000436 | Yard | 604-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/30/2023 11:59 | Distribution | New Haven Quarterly Inspection | YD000436 | Yard | 604-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | PF000181 | PowerFuse | HK-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | PF000181 | PowerFuse | HK-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | SWG000028 | Switchgear | HK-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LTCC000429 | LTCControl | HK-TRANS 2 | LTC Control Insp | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LTCC000429 | LTCControl | HK-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LTCC000429 | LTCControl | HK-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LTCC000429 | LTCControl | HK-TRANS 2 | LTC Control Insp | All Connections OK? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Counter Readings | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 244287 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 244287 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 13L | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 4L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 1025 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | LTCMechanism | HK-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 25 | °C |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 50 | °C |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 25 | °C |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 45 | °C |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 35 | °C |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 45 | °C |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LTCC000519 | LTCControl | HK-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LTCC000519 | LTCControl | HK-TRANS 1 | LTC Control Insp | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LTCC000519 | LTCControl | HK-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LTCC000519 | LTCControl | HK-TRANS 1 | LTC Control Insp | All Connections OK? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0089 | WithLTC | HK-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 278434 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Counter Readings | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 278434 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 1325 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | LTCMechanism | HK-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 40 | °C |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 60 | °C |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 40 | °C |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 52 | °C |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 35 | °C |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 50 | °C |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 135.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | LT0090 | WithLTC | HK-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Switching Operations | 3 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | 9 Month Operations | 6 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Amps A Ø | 422.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Amps B Ø | 419.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Amps C Ø | 419.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Operations This Read Vac | 3 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Operations Counter AL | 267 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Readings | Operations Counter AF | 267 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000507 | BreakerVacuum | HK-12KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Switching Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Operations This Read Vac | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Operations Counter AL | 338 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Operations Counter AF | 338 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Amps C Ø | 220.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Amps B Ø | 225.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Amps A Ø | 220.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Readings | 9 Month Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000509 | BreakerVacuum | HK-1240 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Amps C Ø | 0.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Operations Counter AF | 176 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Operations Counter AL | 176 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Operations This Read Vac | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Switching Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Amps B Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Amps A Ø | 0.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Readings | 9 Month Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000511 | BreakerVacuum | HK-1236 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Switching Operations | 10 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Operations This Read Vac | 10 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Operations Counter AL | 238 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Operations Counter AF | 238 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Amps C Ø | 115.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Amps B Ø | 100.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Amps A Ø | 120.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Readings | 9 Month Operations | 12 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Readings | Switching Operations | 2 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Readings | Operations This Read Vac | 2 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Readings | Operations Counter AL | 178 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Readings | Operations Counter AF | 176 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Readings | General Comments | | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Readings | Amps C Ø | 120.0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Readings | 9 Month Operations | 2 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Readings | Amps B Ø | 110.0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Readings | Amps A Ø | 125.0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001775 | BreakerVacuum | 690-0855 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Readings | 9 Month Operations | 2 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Readings | Amps A Ø | 5.0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Readings | Amps B Ø | 10.0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Readings | Amps C Ø | 5.0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Readings | General Comments | | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Readings | Switching Operations | 2 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Readings | Operations This Read Vac | 2 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Readings | Operations Counter AL | 171 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Readings | Operations Counter AF | 169 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001774 | BreakerVacuum | 690-0854 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Readings | Switching Operations | 2 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Readings | 9 Month Operations | 6 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Readings | Amps A Ø | 100.0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Readings | Operations This Read Vac | 2 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Readings | Operations Counter AL | 177 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Readings | Operations Counter AF | 175 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Readings | Amps C Ø | 100.0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Readings | Amps B Ø | 100.0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001773 | BreakerVacuum | 690-0853 | VCB Readings | General Comments | | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Readings | Switching Operations | 2 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Readings | Operations This Read Vac | 2 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Readings | Operations Counter AL | 173 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Readings | Operations Counter AF | 171 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Readings | General Comments | | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Readings | 9 Month Operations | 2 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Readings | Amps C Ø | 150.0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Readings | Amps B Ø | 140.0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001768 | BreakerVacuum | 690-0852 | VCB Readings | Amps A Ø | 195.0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Readings | Switching Operations | 2 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Readings | Operations This Read Vac | 8 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Readings | Operations Counter AL | 193 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Readings | Operations Counter AF | 191 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Readings | General Comments | | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Readings | Fault Operations B Ø | 3 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Readings | Fault Operations A Ø | 3 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Readings | Fault Adjusted Amps B Phase V | 29.60 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Readings | Fault Adjusted Amps A Phase V | 29.60 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Readings | Amps C Ø | 90.0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Readings | Amps B Ø | 70.0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Readings | Amps A Ø | 150.0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BK001771 | BreakerVacuum | 690-0851 | VCB Readings | 9 Month Operations | 8 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000510 | BreakerVacuum | HK-1235 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Amps C Ø | 95.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Amps B Ø | 100.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Amps A Ø | 95.0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | 9 Month Operations | 1 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Switching Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Operations This Read Vac | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Operations Counter AL | 230 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Operations Counter AF | 230 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/30/2023 12:24 | Distribution | Harrods Creek Quarterly Inspection | BK000508 | BreakerVacuum | HK-1233 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000098 | Regulator | 690-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000098 | Regulator | 690-1 C | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000098 | Regulator | 690-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000098 | Regulator | 690-1 C | Regulator Patrol Inspection | General Comments | | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000098 | Regulator | 690-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000098 | Regulator | 690-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000098 | Regulator | 690-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000098 | Regulator | 690-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000098 | Regulator | 690-1 C | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000098 | Regulator | 690-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000098 | Regulator | 690-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000098 | Regulator | 690-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000098 | Regulator | 690-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000098 | Regulator | 690-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000098 | Regulator | 690-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000098 | Regulator | 690-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000098 | Regulator | 690-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000098 | Regulator | 690-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000098 | Regulator | 690-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000098 | Regulator | 690-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000098 | Regulator | 690-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 14586 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000098 | Regulator | 690-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000098 | Regulator | 690-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000098 | Regulator | 690-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000097 | Regulator | 690-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000097 | Regulator | 690-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000097 | Regulator | 690-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000097 | Regulator | 690-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000097 | Regulator | 690-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 19110 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000097 | Regulator | 690-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000097 | Regulator | 690-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000097 | Regulator | 690-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000097 | Regulator | 690-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000097 | Regulator | 690-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000097 | Regulator | 690-1 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000097 | Regulator | 690-1 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000097 | Regulator | 690-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000097 | Regulator | 690-1 A | Regulator Patrol Inspection | General Comments | | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000097 | Regulator | 690-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000097 | Regulator | 690-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000097 | Regulator | 690-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000097 | Regulator | 690-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000097 | Regulator | 690-1 A | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000097 | Regulator | 690-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000097 | Regulator | 690-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000097 | Regulator | 690-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000097 | Regulator | 690-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000097 | Regulator | 690-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000014 | Regulator | 690-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000014 | Regulator | 690-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000014 | Regulator | 690-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000014 | Regulator | 690-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000014 | Regulator | 690-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000014 | Regulator | 690-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 24706 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000014 | Regulator | 690-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000014 | Regulator | 690-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000014 | Regulator | 690-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000014 | Regulator | 690-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000014 | Regulator | 690-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000014 | Regulator | 690-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000014 | Regulator | 690-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000014 | Regulator | 690-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000014 | Regulator | 690-1 B | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000014 | Regulator | 690-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000014 | Regulator | 690-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000014 | Regulator | 690-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000014 | Regulator | 690-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000014 | Regulator | 690-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000014 | Regulator | 690-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000014 | Regulator | 690-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000014 | Regulator | 690-1 B | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | RG000014 | Regulator | 690-1 B | Regulator Patrol Inspection | Min Tap Position | 4L | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Readings | General Comments | | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 2893.44 | kw |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 180.00 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .9042 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 187.50 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0230 | NonLTC | 690-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | LTCC000770 | LTCControl | 690-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | LTCC000770 | LTCControl | 690-2 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | LTCC000770 | LTCControl | 690-2 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | LTCC000770 | LTCControl | 690-2 | LTC Control Insp | All Connections OK? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | LTCC000770 | LTCControl | 690-2 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | LTCC000770 | LTCControl | 690-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | LTCC000770 | LTCControl | 690-2 | LTC Control Insp | General Comments | | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | LTCC000770 | LTCControl | 690-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | LTCMechanism | 690-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | LTCMechanism | 690-2 | LTC Counter Readings | LTC Operations Since Last Insp | 205 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | LTCMechanism | 690-2 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | LTCMechanism | 690-2 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | LTCMechanism | 690-2 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | LTCMechanism | 690-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | LTCMechanism | 690-2 | LTC Counter Readings | General Comments | | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | LTCMechanism | 690-2 | LTC Counter Readings | LTC As Found Counter | 7979 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | LTCMechanism | 690-2 | LTC Counter Readings | LTC As Left Counter | 7979 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | LTCMechanism | 690-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | LTCMechanism | 690-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | LTCMechanism | 690-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | LTCMechanism | 690-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | LTCMechanism | 690-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | LTCMechanism | 690-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | LTCMechanism | 690-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Readings | LTC Totalizer Reading | 7464.96 | kw |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Readings | Totalizer Meter Reading | .7776 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Readings | General Comments | | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Readings | Operations Counter AF | 491 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Readings | Operations Counter AL | 491 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Readings | Operations This Read Vac | 0 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Readings | Switching Operations | 0 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Readings | Amps C Ø | 0.0 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Readings | Amps B Ø | 0.0 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Readings | Amps A Ø | 0.0 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Readings | 9 Month Operations | 0 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | B0372 | WithLTC | 690-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BAT001464 | Battery | 690-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BAT001464 | Battery | 690-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 40 | °F |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BAT001464 | Battery | 690-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BAT001464 | Battery | 690-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BAT001464 | Battery | 690-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BAT001464 | Battery | 690-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BAT001464 | Battery | 690-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BAT001464 | Battery | 690-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BAT001464 | Battery | 690-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BAT001464 | Battery | 690-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BAT001464 | Battery | 690-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BAT001464 | Battery | 690-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BAT001464 | Battery | 690-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BAT001464 | Battery | 690-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BCH001343 | Charger | 690-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BCH001343 | Charger | 690-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BCH001343 | Charger | 690-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BCH001343 | Charger | 690-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.8 | amps |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BCH001343 | Charger | 690-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BCH001343 | Charger | 690-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BCH001343 | Charger | 690-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | BCH001343 | Charger | 690-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0409 | BreakerVacuum | 565-4517 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Readings | Switching Operations | 2 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Readings | Operations This Read Vac | 2 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Readings | Operations Counter AL | 79 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Readings | Operations Counter AF | 79 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Readings | General Comments | | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Readings | Amps C Ø | 6.0 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Readings | Amps B Ø | 6.0 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Readings | Amps A Ø | 6.0 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Readings | 9 Month Operations | 2 | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | ST000365 | Structure | 690-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | ST000365 | Structure | 690-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | ST000365 | Structure | 690-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | ST000365 | Structure | 690-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | ST000365 | Structure | 690-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | ST000365 | Structure | 690-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | ST000365 | Structure | 690-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | ST000365 | Structure | 690-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | ST000365 | Structure | 690-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | ST000365 | Structure | 690-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | ST000365 | Structure | 690-Structure | Structure Patrol Inspection | General Comments | | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | ST000365 | Structure | 690-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | ST000365 | Structure | 690-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | ST000365 | Structure | 690-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | ST000365 | Structure | 690-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | ST000365 | Structure | 690-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | ST000365 | Structure | 690-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | ST000365 | Structure | 690-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | ST000365 | Structure | 690-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | ST000365 | Structure | 690-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | ST000365 | Structure | 690-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | ST000365 | Structure | 690-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | FE000379 | Fence | 690-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | FE000379 | Fence | 690-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | FE000379 | Fence | 690-Fence | Fence Patrol Inspection | General Comments | | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | FE000379 | Fence | 690-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | FE000379 | Fence | 690-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | FE000379 | Fence | 690-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | FE000379 | Fence | 690-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | FE000379 | Fence | 690-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | FE000379 | Fence | 690-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | FE000379 | Fence | 690-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | FE000379 | Fence | 690-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | FE000379 | Fence | 690-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | FE000379 | Fence | 690-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | FE000379 | Fence | 690-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | FE000379 | Fence | 690-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | FE000379 | Fence | 690-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | YD000362 | Yard | 690-Yard | Yard Patrol Inspection | Ambient Temp | 38 | °F |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | YD000362 | Yard | 690-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | YD000362 | Yard | 690-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | YD000362 | Yard | 690-Yard | Yard Patrol Inspection | General Comments | | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | YD000362 | Yard | 690-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | YD000362 | Yard | 690-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | YD000362 | Yard | 690-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | YD000362 | Yard | 690-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | YD000362 | Yard | 690-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | YD000362 | Yard | 690-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | YD000362 | Yard | 690-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | YD000362 | Yard | 690-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | YD000362 | Yard | 690-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | YD000362 | Yard | 690-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/30/2023 11:29 | Distribution | Cynthiana Quarterly Inspection | YD000362 | Yard | 690-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BB0410 | BreakerVacuum | 565-4516 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | LTCMechanism | 565-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | LTCMechanism | 565-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | LTCMechanism | 565-1 | LTC Counter Readings | General Comments | | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | LTCMechanism | 565-1 | LTC Counter Readings | LTC As Found Counter | 251837 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | LTCMechanism | 565-1 | LTC Counter Readings | LTC As Left Counter | 251845 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | LTCMechanism | 565-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | LTCMechanism | 565-1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | LTCMechanism | 565-1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | LTCMechanism | 565-1 | LTC Counter Readings | LTC Operations Since Last Insp | 592 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | LTCC000659 | LTCControl | 565-1 | LTC Control Insp | All Connections OK? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | LTCC000659 | LTCControl | 565-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | LTCC000659 | LTCControl | 565-1 | LTC Control Insp | General Comments | | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | LTCC000659 | LTCControl | 565-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | LTCC000659 | LTCControl | 565-1 | LTC Control Insp | LTC Output Voltage Level | 124.4 | VAC |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | LTCC000659 | LTCControl | 565-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | LTCC000659 | LTCControl | 565-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | LTCC000659 | LTCControl | 565-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | LTCC000659 | LTCControl | 565-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | LTCMechanism | 565-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | LTCMechanism | 565-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | LTCMechanism | 565-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | LTCMechanism | 565-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | LTCMechanism | 565-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | LTCMechanism | 565-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | LTCMechanism | 565-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Readings | LTC Totalizer Reading | 109.44 | kw |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Readings | Totalizer Meter Reading | .0342 | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Readings | General Comments | | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | C0352 | WithLTC | 565-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BCH001410 | Charger | 565-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BCH001410 | Charger | 565-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BCH001410 | Charger | 565-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 0.0 | amps |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BCH001410 | Charger | 565-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BCH001410 | Charger | 565-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BCH001410 | Charger | 565-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BAT001476 | Battery | 565-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BAT001476 | Battery | 565-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BAT001476 | Battery | 565-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Exp/Missing Not Repl | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BAT001476 | Battery | 565-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BAT001476 | Battery | 565-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BAT001476 | Battery | 565-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BAT001476 | Battery | 565-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BAT001476 | Battery | 565-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.2 | VDC |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BAT001476 | Battery | 565-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.2 | VDC |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BAT001476 | Battery | 565-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BAT001476 | Battery | 565-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BAT001476 | Battery | 565-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BAT001476 | Battery | 565-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BAT001476 | Battery | 565-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | BAT001476 | Battery | 565-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | CH000493 | ControlHouse | 565-Control House | Control House Patrol Inspection | Door Alarms OK? | n | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | CH000493 | ControlHouse | 565-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | CH000493 | ControlHouse | 565-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | CH000493 | ControlHouse | 565-Control House | Control House Patrol Inspection | Broom on Site? | n | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | CH000493 | ControlHouse | 565-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | CH000493 | ControlHouse | 565-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | CH000493 | ControlHouse | 565-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | CH000493 | ControlHouse | 565-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | CH000493 | ControlHouse | 565-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | CH000493 | ControlHouse | 565-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | CH000493 | ControlHouse | 565-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | CH000493 | ControlHouse | 565-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | CH000493 | ControlHouse | 565-Control House | Control House Patrol Inspection | Floor Swept? | n | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | CH000493 | ControlHouse | 565-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | CH000493 | ControlHouse | 565-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | n | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | CH000493 | ControlHouse | 565-Control House | Control House Patrol Inspection | Station Ground Set On Site? | n | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | CH000493 | ControlHouse | 565-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | CH000493 | ControlHouse | 565-Control House | Control House Patrol Inspection | Panel Lights OK? | n | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | CH000493 | ControlHouse | 565-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | CH000493 | ControlHouse | 565-Control House | Control House Patrol Inspection | General Comments | | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | CH000493 | ControlHouse | 565-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | CH000493 | ControlHouse | 565-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | ST000040 | Structure | 565-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | ST000040 | Structure | 565-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | ST000040 | Structure | 565-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | ST000040 | Structure | 565-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | ST000040 | Structure | 565-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | ST000040 | Structure | 565-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | ST000040 | Structure | 565-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | ST000040 | Structure | 565-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | ST000040 | Structure | 565-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | ST000040 | Structure | 565-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | ST000040 | Structure | 565-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | ST000040 | Structure | 565-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | ST000040 | Structure | 565-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | ST000040 | Structure | 565-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | ST000040 | Structure | 565-Structure | Structure Patrol Inspection | General Comments | | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | ST000040 | Structure | 565-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | ST000040 | Structure | 565-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | ST000040 | Structure | 565-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | ST000040 | Structure | 565-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | ST000040 | Structure | 565-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | ST000040 | Structure | 565-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | ST000040 | Structure | 565-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | FE000039 | Fence | 565-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | FE000039 | Fence | 565-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | FE000039 | Fence | 565-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | FE000039 | Fence | 565-Fence | Fence Patrol Inspection | General Comments | | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | FE000039 | Fence | 565-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | FE000039 | Fence | 565-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | FE000039 | Fence | 565-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | FE000039 | Fence | 565-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | FE000039 | Fence | 565-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | FE000039 | Fence | 565-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | FE000039 | Fence | 565-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | FE000039 | Fence | 565-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | FE000039 | Fence | 565-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | FE000039 | Fence | 565-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | FE000039 | Fence | 565-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | FE000039 | Fence | 565-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | YD000036 | Yard | 565-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | YD000036 | Yard | 565-Yard | Yard Patrol Inspection | General Comments | | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | YD000036 | Yard | 565-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | YD000036 | Yard | 565-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | YD000036 | Yard | 565-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | YD000036 | Yard | 565-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | YD000036 | Yard | 565-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | YD000036 | Yard | 565-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | YD000036 | Yard | 565-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | YD000036 | Yard | 565-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | YD000036 | Yard | 565-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | YD000036 | Yard | 565-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/30/2023 13:02 | Distribution | Somerset GE Quarterly Inspection | YD000036 | Yard | 565-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Readings | Switching Operations | 0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Readings | Operations This Read Vac | 0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Readings | Operations Counter AL | 202 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Readings | Operations Counter AF | 202 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Readings | General Comments | | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Readings | Amps C Ø | 113.0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Readings | Amps B Ø | 137.0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Readings | 9 Month Operations | 1 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BK001192 | BreakerVacuum | 802-0521 | VCB Readings | Amps A Ø | 131.0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Readings | 9 Month Operations | 1 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Readings | Amps A Ø | 10.0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Readings | Amps B Ø | 10.0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Readings | Amps C Ø | 10.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Readings | General Comments | | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Readings | Operations Counter AF | 345 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Readings | Operations Counter AL | 345 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Readings | Operations This Read Vac | 0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Readings | Switching Operations | 0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0156 | BreakerVacuum | 802-0523 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Readings | 9 Month Operations | 4 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Readings | Amps A Ø | 10.0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Readings | Amps B Ø | 10.0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Readings | Amps C Ø | 10.0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Readings | Fault Adjusted Amps B Phase V | 26.28 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Readings | Fault Operations B Ø | 3 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Readings | Operations Counter AF | 11 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Readings | Operations Counter AL | 11 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Readings | Operations This Read Vac | 3 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Readings | Switching Operations | 0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Readings | General Comments | 3 faults without lockout 3/4/23 during windstorm. T-B0 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Patrol Inspection | General Comments | blown line arrestor | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | MB0155 | BreakerVacuum | 802-0522 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | LTCMechanism | 802-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | LTCMechanism | 802-1 | LTC Counter Readings | General Comments | | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | LTCMechanism | 802-1 | LTC Counter Readings | LTC As Found Counter | 83468 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | LTCMechanism | 802-1 | LTC Counter Readings | LTC As Left Counter | 83484 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | LTCMechanism | 802-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | LTCMechanism | 802-1 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | LTCMechanism | 802-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | LTCMechanism | 802-1 | LTC Counter Readings | LTC Operations Since Last Insp | 557 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | LTCMechanism | 802-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | LTCC000952 | LTCControl | 802-1 | LTC Control Insp | All Connections OK? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | LTCC000952 | LTCControl | 802-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | LTCC000952 | LTCControl | 802-1 | LTC Control Insp | General Comments | | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | LTCC000952 | LTCControl | 802-1 | LTC Control Insp | LTC Operation Checked? | n | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | LTCC000952 | LTCControl | 802-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | LTCC000952 | LTCControl | 802-1 | LTC Control Insp | VRR Time Delay | 45 | Seconds |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | LTCC000952 | LTCControl | 802-1 | LTC Control Insp | VRR Base Voltage AL | 123.8 | VAC |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | LTCC000952 | LTCControl | 802-1 | LTC Control Insp | VRR Base Voltage AF | 124.6 | VAC |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | LTCMechanism | 802-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | LTCMechanism | 802-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | LTCMechanism | 802-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | LTCMechanism | 802-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | LTCMechanism | 802-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | LTCMechanism | 802-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | LTCMechanism | 802-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Readings | Totalizer Meter Reading | .4626 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Readings | LTC Totalizer Reading | 1480.32 | kw |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Readings | General Comments | | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Patrol Inspection | General Comments | heater and cabinet lights not working | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | n | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | 0981 | WithLTC | 802-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BAT001389 | Battery | 802-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BAT001389 | Battery | 802-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BAT001389 | Battery | 802-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BAT001389 | Battery | 802-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BAT001389 | Battery | 802-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BAT001389 | Battery | 802-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BAT001389 | Battery | 802-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BAT001389 | Battery | 802-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BAT001389 | Battery | 802-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BAT001389 | Battery | 802-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.2 | VDC |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BAT001389 | Battery | 802-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.1 | VDC |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BAT001389 | Battery | 802-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BAT001389 | Battery | 802-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BCH001293 | Charger | 802-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BCH001293 | Charger | 802-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BCH001293 | Charger | 802-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.3 | VDC |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BCH001293 | Charger | 802-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.3 | VDC |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BCH001293 | Charger | 802-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .6 | amps |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BCH001293 | Charger | 802-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BCH001293 | Charger | 802-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | BCH001293 | Charger | 802-Battery Charger | Battery Charger Patrol Insp | General Comments | meter unable to read ripple | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | CH000482 | ControlHouse | 802-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | CH000482 | ControlHouse | 802-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | CH000482 | ControlHouse | 802-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | CH000482 | ControlHouse | 802-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | CH000482 | ControlHouse | 802-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | CH000482 | ControlHouse | 802-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | CH000482 | ControlHouse | 802-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | CH000482 | ControlHouse | 802-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | CH000482 | ControlHouse | 802-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | CH000482 | ControlHouse | 802-Control House | Control House Patrol Inspection | General Comments | | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | CH000482 | ControlHouse | 802-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | CH000482 | ControlHouse | 802-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | CH000482 | ControlHouse | 802-Control House | Control House Patrol Inspection | Floor Swept? | n | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | CH000482 | ControlHouse | 802-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | CH000482 | ControlHouse | 802-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | CH000482 | ControlHouse | 802-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | CH000482 | ControlHouse | 802-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | CH000482 | ControlHouse | 802-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | CH000482 | ControlHouse | 802-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | CH000482 | ControlHouse | 802-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | CH000482 | ControlHouse | 802-Control House | Control House Patrol Inspection | Broom on Site? | n | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | CH000482 | ControlHouse | 802-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | ST000030 | Structure | 802-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | ST000030 | Structure | 802-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | ST000030 | Structure | 802-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | ST000030 | Structure | 802-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | ST000030 | Structure | 802-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | ST000030 | Structure | 802-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | ST000030 | Structure | 802-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | ST000030 | Structure | 802-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | ST000030 | Structure | 802-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | ST000030 | Structure | 802-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | ST000030 | Structure | 802-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | ST000030 | Structure | 802-Structure | Structure Patrol Inspection | General Comments | two large birds nests in steel above transformer fuses | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | ST000030 | Structure | 802-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | ST000030 | Structure | 802-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | ST000030 | Structure | 802-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | ST000030 | Structure | 802-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | ST000030 | Structure | 802-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | ST000030 | Structure | 802-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | ST000030 | Structure | 802-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | ST000030 | Structure | 802-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | ST000030 | Structure | 802-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | ST000030 | Structure | 802-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | FE000897 | Fence | 802-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | FE000897 | Fence | 802-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | FE000897 | Fence | 802-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | FE000897 | Fence | 802-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | FE000897 | Fence | 802-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | FE000897 | Fence | 802-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | FE000897 | Fence | 802-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | FE000897 | Fence | 802-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | FE000897 | Fence | 802-Fence | Fence Patrol Inspection | General Comments | | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | FE000897 | Fence | 802-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | FE000897 | Fence | 802-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | FE000897 | Fence | 802-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | FE000897 | Fence | 802-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | FE000897 | Fence | 802-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | FE000897 | Fence | 802-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | FE000897 | Fence | 802-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | YD000039 | Yard | 802-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | YD000039 | Yard | 802-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | YD000039 | Yard | 802-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | YD000039 | Yard | 802-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | YD000039 | Yard | 802-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | YD000039 | Yard | 802-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | YD000039 | Yard | 802-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | YD000039 | Yard | 802-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | YD000039 | Yard | 802-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | YD000039 | Yard | 802-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | YD000039 | Yard | 802-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | YD000039 | Yard | 802-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | YD000039 | Yard | 802-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:56 | Distribution | Somerset 1 Quarterly Inspection | YD000039 | Yard | 802-Yard | Yard Patrol Inspection | General Comments | | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0133 | RecloserElectronic | 774-2430 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0133 | RecloserElectronic | 774-2430 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0133 | RecloserElectronic | 774-2430 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0133 | RecloserElectronic | 774-2430 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0133 | RecloserElectronic | 774-2430 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0133 | RecloserElectronic | 774-2430 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0133 | RecloserElectronic | 774-2430 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0133 | RecloserElectronic | 774-2430 | Recloser Electronic Patrol Inspection | Operations Counter | 14 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0133 | RecloserElectronic | 774-2430 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0133 | RecloserElectronic | 774-2430 | Recloser Electronic Patrol Inspection | Amps A Ø | 146 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0133 | RecloserElectronic | 774-2430 | Recloser Electronic Patrol Inspection | Amps B Ø | 155 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0133 | RecloserElectronic | 774-2430 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0133 | RecloserElectronic | 774-2430 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0133 | RecloserElectronic | 774-2430 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0133 | RecloserElectronic | 774-2430 | Recloser Electronic Patrol Inspection | Amps C Ø | 175 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0133 | RecloserElectronic | 774-2430 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0133 | RecloserElectronic | 774-2430 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0133 | RecloserElectronic | 774-2430 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0133 | RecloserElectronic | 774-2430 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0133 | RecloserElectronic | 774-2430 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0885 | RecloserElectronic | 774-2467 | Recloser Electronic Patrol Inspection | Operations Counter | 243 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0885 | RecloserElectronic | 774-2467 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0885 | RecloserElectronic | 774-2467 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0885 | RecloserElectronic | 774-2467 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0885 | RecloserElectronic | 774-2467 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0885 | RecloserElectronic | 774-2467 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0885 | RecloserElectronic | 774-2467 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0885 | RecloserElectronic | 774-2467 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0885 | RecloserElectronic | 774-2467 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0885 | RecloserElectronic | 774-2467 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0885 | RecloserElectronic | 774-2467 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0885 | RecloserElectronic | 774-2467 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0885 | RecloserElectronic | 774-2467 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0885 | RecloserElectronic | 774-2467 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0885 | RecloserElectronic | 774-2467 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0885 | RecloserElectronic | 774-2467 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0885 | RecloserElectronic | 774-2467 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0885 | RecloserElectronic | 774-2467 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0885 | RecloserElectronic | 774-2467 | Recloser Electronic Patrol Inspection | Amps C Ø | 14 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0885 | RecloserElectronic | 774-2467 | Recloser Electronic Patrol Inspection | Amps B Ø | 25 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | CX0885 | RecloserElectronic | 774-2467 | Recloser Electronic Patrol Inspection | Amps A Ø | 26 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | MX0323 | RecloserElectronic | 774-2431 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | MX0323 | RecloserElectronic | 774-2431 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | MX0323 | RecloserElectronic | 774-2431 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | MX0323 | RecloserElectronic | 774-2431 | Recloser Electronic Patrol Inspection | Operations Counter | 1984 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | MX0323 | RecloserElectronic | 774-2431 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | MX0323 | RecloserElectronic | 774-2431 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | MX0323 | RecloserElectronic | 774-2431 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | MX0323 | RecloserElectronic | 774-2431 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | MX0323 | RecloserElectronic | 774-2431 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | MX0323 | RecloserElectronic | 774-2431 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | MX0323 | RecloserElectronic | 774-2431 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | MX0323 | RecloserElectronic | 774-2431 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | MX0323 | RecloserElectronic | 774-2431 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | MX0323 | RecloserElectronic | 774-2431 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | MX0323 | RecloserElectronic | 774-2431 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | MX0323 | RecloserElectronic | 774-2431 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | MX0323 | RecloserElectronic | 774-2431 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | MX0323 | RecloserElectronic | 774-2431 | Recloser Electronic Patrol Inspection | Amps C Ø | 25 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | MX0323 | RecloserElectronic | 774-2431 | Recloser Electronic Patrol Inspection | Amps B Ø | 10 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | MX0323 | RecloserElectronic | 774-2431 | Recloser Electronic Patrol Inspection | Amps A Ø | 10 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Readings | Switching Operations | 1 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Readings | Operations This Read Vac | 1 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Readings | Operations Counter AL | 34 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Readings | Operations Counter AF | 33 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Readings | General Comments | | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Readings | Amps C Ø | 154 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Readings | Amps B Ø | 178 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Readings | Amps A Ø | 144 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Readings | 9 Month Operations | 1 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Readings | Switching Operations | 1 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Readings | Operations This Read Vac | 1 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Readings | Operations Counter AL | 26 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Readings | Operations Counter AF | 25 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Readings | General Comments | | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Readings | Amps C Ø | 164 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Readings | Amps B Ø | 157 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Readings | Amps A Ø | 150 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Readings | 9 Month Operations | 1 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0133 | BreakerVacuum | 774-2428 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | K0132 | BreakerVacuum | 774-2429 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1485 | Regulator | 774-2 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1485 | Regulator | 774-2 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1485 | Regulator | 774-2 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1485 | Regulator | 774-2 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1485 | Regulator | 774-2 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1485 | Regulator | 774-2 A | Regulator Patrol Inspection | Regulator As Left Counter | 41471 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1485 | Regulator | 774-2 A | Regulator Patrol Inspection | Reg Output Voltage Level | 125.1 | volts |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1485 | Regulator | 774-2 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1485 | Regulator | 774-2 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1485 | Regulator | 774-2 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1485 | Regulator | 774-2 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1485 | Regulator | 774-2 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1485 | Regulator | 774-2 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1485 | Regulator | 774-2 A | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1485 | Regulator | 774-2 A | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1485 | Regulator | 774-2 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1485 | Regulator | 774-2 A | Regulator Patrol Inspection | General Comments | wrong counter last qtr | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1485 | Regulator | 774-2 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1485 | Regulator | 774-2 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1485 | Regulator | 774-2 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1485 | Regulator | 774-2 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1485 | Regulator | 774-2 A | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1485 | Regulator | 774-2 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1486 | Regulator | 774-2 B | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1486 | Regulator | 774-2 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1486 | Regulator | 774-2 B | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1486 | Regulator | 774-2 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1486 | Regulator | 774-2 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125 | volts |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1486 | Regulator | 774-2 B | Regulator Patrol Inspection | Regulator As Left Counter | 84052 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1486 | Regulator | 774-2 B | Regulator Patrol Inspection | General Comments | | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1486 | Regulator | 774-2 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1486 | Regulator | 774-2 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1486 | Regulator | 774-2 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1486 | Regulator | 774-2 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1486 | Regulator | 774-2 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1486 | Regulator | 774-2 B | Regulator Patrol Inspection | Current Tap Position | 9L | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1486 | Regulator | 774-2 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1486 | Regulator | 774-2 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1486 | Regulator | 774-2 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1486 | Regulator | 774-2 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1486 | Regulator | 774-2 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1486 | Regulator | 774-2 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1486 | Regulator | 774-2 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1486 | Regulator | 774-2 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1486 | Regulator | 774-2 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1486 | Regulator | 774-2 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Readings | Amps A Ø | 180.0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Readings | Amps B Ø | 180.0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Readings | Amps C Ø | 120.0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Readings | Switching Operations | 1 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Readings | Operations This Read Vac | 1 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Readings | Operations Counter AL | 731 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Readings | Operations Counter AF | 731 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Readings | General Comments | | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Readings | 9 Month Operations | 1 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0146 | BreakerVacuum | 779-4508 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Readings | 9 Month Operations | 0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Readings | Amps A Ø | 30.0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Readings | Amps B Ø | 12.0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Readings | Amps C Ø | 12.0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Readings | General Comments | | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Readings | Operations Counter AF | 761 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Readings | Operations Counter AL | 761 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Readings | Operations This Read Vac | 0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Readings | Switching Operations | 0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1487 | Regulator | 774-2 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1487 | Regulator | 774-2 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1487 | Regulator | 774-2 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1487 | Regulator | 774-2 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1487 | Regulator | 774-2 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1487 | Regulator | 774-2 C | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1487 | Regulator | 774-2 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1487 | Regulator | 774-2 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1487 | Regulator | 774-2 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1487 | Regulator | 774-2 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1487 | Regulator | 774-2 C | Regulator Patrol Inspection | General Comments | wrong counter put in last qtr | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1487 | Regulator | 774-2 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1487 | Regulator | 774-2 C | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1487 | Regulator | 774-2 C | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1487 | Regulator | 774-2 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1487 | Regulator | 774-2 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1487 | Regulator | 774-2 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1487 | Regulator | 774-2 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1487 | Regulator | 774-2 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1487 | Regulator | 774-2 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1487 | Regulator | 774-2 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1487 | Regulator | 774-2 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.7 | volts |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | R1487 | Regulator | 774-2 C | Regulator Patrol Inspection | Regulator As Left Counter | 91227 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0147 | BreakerVacuum | 779-4507 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Readings | Operations Counter AL | 325 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Readings | Operations Counter AF | 325 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Readings | General Comments | | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Readings | Amps C Ø | 12.0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Readings | Amps B Ø | 12.0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Readings | Amps A Ø | 12.0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Readings | 9 Month Operations | 0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Readings | Operations This Read Vac | 0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Readings | Switching Operations | 0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | MB0161 | BreakerVacuum | 779-4506 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Readings | General Comments | | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 7763.04 | kw |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.0782 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | LTCC000701 | LTCControl | 779-1 | LTC Control Insp | All Connections OK? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | LTCC000701 | LTCControl | 779-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | LTCC000701 | LTCControl | 779-1 | LTC Control Insp | General Comments | | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | LTCC000701 | LTCControl | 779-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | LTCC000701 | LTCControl | 779-1 | LTC Control Insp | LTC Output Voltage Level | 125.3 | VAC |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | LTCC000701 | LTCControl | 779-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | LTCC000701 | LTCControl | 779-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | LTCC000701 | LTCControl | 779-1 | LTC Control Insp | VRR Time Delay | 45 | Seconds |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | S0031 | NonLTC | 774-2 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | LTCMechanism | 774-1 | LTC Counter Readings | LTC As Found Counter | 87569 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | LTCMechanism | 774-1 | LTC Counter Readings | LTC As Left Counter | 87571 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | LTCMechanism | 774-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | LTCMechanism | 774-1 | LTC Counter Readings | General Comments | | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | LTCMechanism | 774-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | LTCMechanism | 774-1 | LTC Counter Readings | LTC Operations Since Last Insp | 224 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | LTCMechanism | 774-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | LTCMechanism | 774-1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | LTCMechanism | 774-1 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Patrol Inspection | General Comments | Added nitrogen | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | LTCMechanism | 779-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | LTCMechanism | 779-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | LTCMechanism | 779-1 | LTC Counter Readings | LTC As Found Counter | 71819 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | LTCMechanism | 779-1 | LTC Counter Readings | LTC As Left Counter | 71819 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | LTCMechanism | 779-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | LTCMechanism | 779-1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | LTCMechanism | 779-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | LTCMechanism | 779-1 | LTC Counter Readings | LTC Operations Since Last Insp | 0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | LTCMechanism | 779-1 | LTC Counter Readings | General Comments | counter not working | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Readings | Amps C Ø | 0.0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Readings | 9 Month Operations | 0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Readings | Amps B Ø | 0.0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Readings | Amps A Ø | 0.0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Readings | Switching Operations | 0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Readings | General Comments | | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Readings | Operations Counter AF | 396 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Readings | Operations Counter AL | 396 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Readings | Operations This Read Vac | 0 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | LTCC000903 | LTCControl | 774-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | LTCC000903 | LTCControl | 774-1 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | LTCC000903 | LTCControl | 774-1 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | LTCC000903 | LTCControl | 774-1 | LTC Control Insp | LTC Output Voltage Level | 124.8 | VAC |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | LTCC000903 | LTCControl | 774-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | LTCC000903 | LTCControl | 774-1 | LTC Control Insp | General Comments | | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | LTCC000903 | LTCControl | 774-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | LTCC000903 | LTCControl | 774-1 | LTC Control Insp | All Connections OK? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Readings | Switching Operations | 0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Readings | 9 Month Operations | 0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Readings | Operations This Read Vac | 0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Readings | Amps C Ø | 1.0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Readings | Amps B Ø | 16.0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Readings | Amps A Ø | 13.0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Readings | Operations Counter AL | 199 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Readings | Operations Counter AF | 199 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Readings | General Comments | | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | BK001288 | BreakerVacuum | 199-0632 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0086 | BreakerVacuum | 199-0633 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | LTCMechanism | 774-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | LTCMechanism | 774-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | LTCMechanism | 774-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | LTCMechanism | 774-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | LTCMechanism | 774-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Readings | Switching Operations | 0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Readings | Operations This Read Vac | 0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Readings | Operations Counter AL | 304 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Readings | Operations Counter AF | 304 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Readings | General Comments | | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Readings | Amps C Ø | 96.0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Readings | Amps B Ø | 115.0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Readings | Amps A Ø | 121.0 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Readings | 9 Month Operations | 1 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Readings | General Comments | | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Readings | LTC Totalizer Reading | 3110.4 | kw |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Readings | Totalizer Meter Reading | .972 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45 | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | LTCMechanism | 779-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | LTCMechanism | 779-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | LTCMechanism | 779-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | LTCMechanism | 779-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | LTCMechanism | 779-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | K0085 | BreakerVacuum | 199-0634 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Readings | General Comments | | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Readings | LTC Totalizer Reading | 3066.00 | kw |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Readings | Oil Temp Max | 72 | °C |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Readings | Oil Temp Present | 46 | °C |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 6000 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Readings | Totalizer Meter Reading | .5110 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 10.00 | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | B0310 | WithLTC | 779-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000056 | Regulator | 199-5 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000056 | Regulator | 199-5 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000056 | Regulator | 199-5 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000056 | Regulator | 199-5 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000056 | Regulator | 199-5 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000056 | Regulator | 199-5 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000056 | Regulator | 199-5 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000056 | Regulator | 199-5 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000056 | Regulator | 199-5 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000056 | Regulator | 199-5 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000056 | Regulator | 199-5 B | Regulator Patrol Inspection | General Comments | | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000056 | Regulator | 199-5 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000056 | Regulator | 199-5 B | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000056 | Regulator | 199-5 B | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000056 | Regulator | 199-5 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000056 | Regulator | 199-5 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000056 | Regulator | 199-5 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000056 | Regulator | 199-5 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000056 | Regulator | 199-5 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000056 | Regulator | 199-5 B | Regulator Patrol Inspection | Regulator As Left Counter | 19903 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000056 | Regulator | 199-5 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000056 | Regulator | 199-5 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000056 | Regulator | 199-5 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000056 | Regulator | 199-5 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | C0439 | WithLTC | 774-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | BAT001544 | Battery | 774-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | BAT001544 | Battery | 774-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | BAT001544 | Battery | 774-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | BAT001544 | Battery | 774-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | BAT001544 | Battery | 774-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | BAT001544 | Battery | 774-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | BAT001544 | Battery | 774-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.6 | VDC |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | BAT001544 | Battery | 774-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.8 | VDC |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | BAT001544 | Battery | 774-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | BAT001544 | Battery | 774-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | BAT001544 | Battery | 774-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | BAT001544 | Battery | 774-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | BAT001544 | Battery | 774-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 40 | °F |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | BAT001544 | Battery | 774-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000055 | Regulator | 199-5 C | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000055 | Regulator | 199-5 C | Regulator Patrol Inspection | Min Tap Position | 2L | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000055 | Regulator | 199-5 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000055 | Regulator | 199-5 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000055 | Regulator | 199-5 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000055 | Regulator | 199-5 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000055 | Regulator | 199-5 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000055 | Regulator | 199-5 C | Regulator Patrol Inspection | Regulator As Left Counter | 21486 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000055 | Regulator | 199-5 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000055 | Regulator | 199-5 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000055 | Regulator | 199-5 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000055 | Regulator | 199-5 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000055 | Regulator | 199-5 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000055 | Regulator | 199-5 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000055 | Regulator | 199-5 C | Regulator Patrol Inspection | General Comments | | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000055 | Regulator | 199-5 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000055 | Regulator | 199-5 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000055 | Regulator | 199-5 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000055 | Regulator | 199-5 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000055 | Regulator | 199-5 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000055 | Regulator | 199-5 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000055 | Regulator | 199-5 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000055 | Regulator | 199-5 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000055 | Regulator | 199-5 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | BCH001474 | Charger | 774-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0 | millivolts |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | BCH001474 | Charger | 774-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | BCH001474 | Charger | 774-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | BCH001474 | Charger | 774-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .8 | amps |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | BCH001474 | Charger | 774-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | BCH001474 | Charger | 774-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | BCH001474 | Charger | 774-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | BCH001474 | Charger | 774-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000054 | Regulator | 199-5 A | Regulator Patrol Inspection | General Comments | | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000054 | Regulator | 199-5 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000054 | Regulator | 199-5 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000054 | Regulator | 199-5 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000054 | Regulator | 199-5 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000054 | Regulator | 199-5 A | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000054 | Regulator | 199-5 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000054 | Regulator | 199-5 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000054 | Regulator | 199-5 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000054 | Regulator | 199-5 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000054 | Regulator | 199-5 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000054 | Regulator | 199-5 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000054 | Regulator | 199-5 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000054 | Regulator | 199-5 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000054 | Regulator | 199-5 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000054 | Regulator | 199-5 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000054 | Regulator | 199-5 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000054 | Regulator | 199-5 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000054 | Regulator | 199-5 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000054 | Regulator | 199-5 A | Regulator Patrol Inspection | Regulator As Left Counter | 24679 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000054 | Regulator | 199-5 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000054 | Regulator | 199-5 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000054 | Regulator | 199-5 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | RG000054 | Regulator | 199-5 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | BCH001322 | Charger | 779-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.000 | millivolts |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | BCH001322 | Charger | 779-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | BCH001322 | Charger | 779-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | BCH001322 | Charger | 779-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .2 | amps |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | BCH001322 | Charger | 779-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | BCH001322 | Charger | 779-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | BCH001322 | Charger | 779-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | BCH001322 | Charger | 779-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | ST000457 | Structure | 774-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | ST000457 | Structure | 774-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | ST000457 | Structure | 774-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | ST000457 | Structure | 774-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | ST000457 | Structure | 774-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | ST000457 | Structure | 774-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | ST000457 | Structure | 774-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | ST000457 | Structure | 774-Structure | Structure Patrol Inspection | General Comments | | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | ST000457 | Structure | 774-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | ST000457 | Structure | 774-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | ST000457 | Structure | 774-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | ST000457 | Structure | 774-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | ST000457 | Structure | 774-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | ST000457 | Structure | 774-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | ST000457 | Structure | 774-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | ST000457 | Structure | 774-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | ST000457 | Structure | 774-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | ST000457 | Structure | 774-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | ST000457 | Structure | 774-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | ST000457 | Structure | 774-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | ST000457 | Structure | 774-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | ST000457 | Structure | 774-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | FE000825 | Fence | 774-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | FE000825 | Fence | 774-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | FE000825 | Fence | 774-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | FE000825 | Fence | 774-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | FE000825 | Fence | 774-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | FE000825 | Fence | 774-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | FE000825 | Fence | 774-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | FE000825 | Fence | 774-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | FE000825 | Fence | 774-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | FE000825 | Fence | 774-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | FE000825 | Fence | 774-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | FE000825 | Fence | 774-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | FE000825 | Fence | 774-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | FE000825 | Fence | 774-Fence | Fence Patrol Inspection | General Comments | | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | FE000825 | Fence | 774-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | FE000825 | Fence | 774-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Readings | Totalizer Meter Reading | .3750 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1200.00 | kw |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Readings | General Comments | | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | YD000455 | Yard | 774-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | YD000455 | Yard | 774-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | YD000455 | Yard | 774-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | YD000455 | Yard | 774-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | YD000455 | Yard | 774-Yard | Yard Patrol Inspection | General Comments | | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | YD000455 | Yard | 774-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | YD000455 | Yard | 774-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | YD000455 | Yard | 774-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | YD000455 | Yard | 774-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | YD000455 | Yard | 774-Yard | Yard Patrol Inspection | Ambient Temp | 40 | °F |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | YD000455 | Yard | 774-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | YD000455 | Yard | 774-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | YD000455 | Yard | 774-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | YD000455 | Yard | 774-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/30/2023 10:18 | Distribution | Hodgenville Quarterly Inspection | YD000455 | Yard | 774-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | BAT001396 | Battery | 779-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | BAT001396 | Battery | 779-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | BAT001396 | Battery | 779-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | BAT001396 | Battery | 779-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | BAT001396 | Battery | 779-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | BAT001396 | Battery | 779-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | BAT001396 | Battery | 779-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | BAT001396 | Battery | 779-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | BAT001396 | Battery | 779-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | BAT001396 | Battery | 779-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | BAT001396 | Battery | 779-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.2 | VDC |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | BAT001396 | Battery | 779-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.2 | VDC |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | BAT001396 | Battery | 779-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | BAT001396 | Battery | 779-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 97.50 | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 10:09 | Distribution | Winchester Quarterly Inspection | B0231 | NonLTC | 199-5 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | CH000477 | ControlHouse | 779-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | CH000477 | ControlHouse | 779-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | CH000477 | ControlHouse | 779-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | CH000477 | ControlHouse | 779-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | CH000477 | ControlHouse | 779-Control House | Control House Patrol Inspection | Station Ground Set On Site? | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | CH000477 | ControlHouse | 779-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | CH000477 | ControlHouse | 779-Control House | Control House Patrol Inspection | Panel Lights OK? | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | CH000477 | ControlHouse | 779-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | CH000477 | ControlHouse | 779-Control House | Control House Patrol Inspection | General Comments | | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | CH000477 | ControlHouse | 779-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | CH000477 | ControlHouse | 779-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | CH000477 | ControlHouse | 779-Control House | Control House Patrol Inspection | Floor Swept? | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | CH000477 | ControlHouse | 779-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | CH000477 | ControlHouse | 779-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | CH000477 | ControlHouse | 779-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | CH000477 | ControlHouse | 779-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | CH000477 | ControlHouse | 779-Control House | Control House Patrol Inspection | Door Alarms OK? | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | CH000477 | ControlHouse | 779-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | CH000477 | ControlHouse | 779-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | CH000477 | ControlHouse | 779-Control House | Control House Patrol Inspection | Broom on Site? | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | CH000477 | ControlHouse | 779-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | CH000477 | ControlHouse | 779-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | ST000015 | Structure | 779-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | ST000015 | Structure | 779-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | ST000015 | Structure | 779-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | ST000015 | Structure | 779-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | ST000015 | Structure | 779-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | ST000015 | Structure | 779-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | ST000015 | Structure | 779-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | ST000015 | Structure | 779-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | ST000015 | Structure | 779-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | ST000015 | Structure | 779-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | ST000015 | Structure | 779-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | ST000015 | Structure | 779-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | ST000015 | Structure | 779-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | ST000015 | Structure | 779-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | ST000015 | Structure | 779-Structure | Structure Patrol Inspection | Interruptrs/Puffrs Visual OK? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | ST000015 | Structure | 779-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | ST000015 | Structure | 779-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | ST000015 | Structure | 779-Structure | Structure Patrol Inspection | General Comments | | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | ST000015 | Structure | 779-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | ST000015 | Structure | 779-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | ST000015 | Structure | 779-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | ST000015 | Structure | 779-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | ST000015 | Structure | 779-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | ST000015 | Structure | 779-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | ST000015 | Structure | 779-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | ST000015 | Structure | 779-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | FE000021 | Fence | 779-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | FE000021 | Fence | 779-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | FE000021 | Fence | 779-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | FE000021 | Fence | 779-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | FE000021 | Fence | 779-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | FE000021 | Fence | 779-Fence | Fence Patrol Inspection | General Comments | posts and rails rusty, cudzu and growing up fence in back corner of station | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | FE000021 | Fence | 779-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | FE000021 | Fence | 779-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | FE000021 | Fence | 779-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | FE000021 | Fence | 779-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | FE000021 | Fence | 779-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | FE000021 | Fence | 779-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | FE000021 | Fence | 779-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | FE000021 | Fence | 779-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | FE000021 | Fence | 779-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | FE000021 | Fence | 779-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | YD000016 | Yard | 779-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | YD000016 | Yard | 779-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | YD000016 | Yard | 779-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | YD000016 | Yard | 779-Yard | Yard Patrol Inspection | General Comments | | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | YD000016 | Yard | 779-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | YD000016 | Yard | 779-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | YD000016 | Yard | 779-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | YD000016 | Yard | 779-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | YD000016 | Yard | 779-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | YD000016 | Yard | 779-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | YD000016 | Yard | 779-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | YD000016 | Yard | 779-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | YD000016 | Yard | 779-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | YD000016 | Yard | 779-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | n | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | YD000016 | Yard | 779-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/30/2023 11:06 | Distribution | Somerset 2 Quarterly Inspection | YD000016 | Yard | 779-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001966 | BreakerSF6 | 805-628 | GCB Readings | Switching Operations | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001966 | BreakerSF6 | 805-628 | GCB Readings | Operations This Read SF6 | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001966 | BreakerSF6 | 805-628 | GCB Readings | Operations Counter AL | 91 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001966 | BreakerSF6 | 805-628 | GCB Readings | Operations Counter AF | 91 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001966 | BreakerSF6 | 805-628 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001966 | BreakerSF6 | 805-628 | GCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001966 | BreakerSF6 | 805-628 | GCB Readings | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001966 | BreakerSF6 | 805-628 | GCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001966 | BreakerSF6 | 805-628 | GCB Readings | Fault Operations | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001966 | BreakerSF6 | 805-628 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001966 | BreakerSF6 | 805-628 | GCB Patrol Inspection | Ambient Temperature | 55 | °F |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001966 | BreakerSF6 | 805-628 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001966 | BreakerSF6 | 805-628 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001966 | BreakerSF6 | 805-628 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001966 | BreakerSF6 | 805-628 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001966 | BreakerSF6 | 805-628 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001966 | BreakerSF6 | 805-628 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001966 | BreakerSF6 | 805-628 | GCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001966 | BreakerSF6 | 805-628 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001966 | BreakerSF6 | 805-628 | GCB Patrol Inspection | General Comments | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001966 | BreakerSF6 | 805-628 | GCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001966 | BreakerSF6 | 805-628 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001966 | BreakerSF6 | 805-628 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001966 | BreakerSF6 | 805-628 | GCB Patrol Inspection | SF6 Pressure | 66 | psi |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001966 | BreakerSF6 | 805-628 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCC000963 | LTCControl | 805-2 | LTC Control Insp | VRR Base Voltage AF | 0.0 | VAC |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCC000963 | LTCControl | 805-2 | LTC Control Insp | All Connections OK? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCC000963 | LTCControl | 805-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCC000963 | LTCControl | 805-2 | LTC Control Insp | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCC000963 | LTCControl | 805-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCC000963 | LTCControl | 805-2 | LTC Control Insp | LTC Output Voltage Level | 0.0 | VAC |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCC000963 | LTCControl | 805-2 | LTC Control Insp | VRR Base Voltage AL | 0.0 | VAC |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCC000963 | LTCControl | 805-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000127 | LTCMechanism | 805-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000127 | LTCMechanism | 805-2 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000127 | LTCMechanism | 805-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 10 | °C |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000127 | LTCMechanism | 805-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000127 | LTCMechanism | 805-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 10 | °C |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000127 | LTCMechanism | 805-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000127 | LTCMechanism | 805-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000127 | LTCMechanism | 805-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000127 | LTCMechanism | 805-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000127 | LTCMechanism | 805-2 | LTC Counter Readings | LTC Operations Since Last Insp | 252 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000127 | LTCMechanism | 805-2 | LTC Counter Readings | LTC Min Tap Position | Neutral | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000127 | LTCMechanism | 805-2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000127 | LTCMechanism | 805-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000127 | LTCMechanism | 805-2 | LTC Counter Readings | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000127 | LTCMechanism | 805-2 | LTC Counter Readings | LTC As Found Counter | 1189 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000127 | LTCMechanism | 805-2 | LTC Counter Readings | LTC As Left Counter | 1189 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000127 | LTCMechanism | 805-2 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Readings | X3 Winding Temp Present | 10 | °C |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Readings | X3 Winding Temp Max | 10 | °C |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Readings | X2 Winding Temp Present | 10 | °C |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Readings | X2 Winding Temp Max | 10 | °C |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Readings | X1 Winding Temp Present | 10 | °C |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Readings | X1 Winding Temp Max | 10 | °C |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Readings | Winding Temp Present | 10 | °C |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Readings | Winding Temp Max | 10 | °C |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Readings | Oil Temp Present | 10 | °C |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Readings | Oil Temp Max | 10 | °C |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Readings | LTC Totalizer Reading | 0.00 | kw |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Readings | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 800 | psi |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000303 | WithLTC | 805-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Readings | 9 Month Operations | 7 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Readings | Amps A Ø | 0.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Readings | Switching Operations | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Readings | Amps B Ø | 0.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Readings | Amps C Ø | 0.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Readings | Operations This Read Vac | 7 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Readings | Operations Counter AL | 191 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Readings | Operations Counter AF | 191 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Readings | Maintenance Operations | 7 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Readings | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001920 | BreakerVacuum | 805-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Readings | Maintenance Operations | 6 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Readings | Operations Counter AF | 168 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Readings | Operations Counter AL | 168 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Readings | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Readings | Switching Operations | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Readings | Operations This Read Vac | 6 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Readings | 9 Month Operations | 6 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Readings | Amps A Ø | 0.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Readings | Amps B Ø | 0.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Readings | Amps C Ø | 0.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001916 | BreakerVacuum | 805-0659 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Readings | Switching Operations | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Readings | 9 Month Operations | 10 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Readings | Operations This Read Vac | 10 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Readings | Operations Counter AL | 270 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Readings | Operations Counter AF | 270 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Readings | Maintenance Operations | 10 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Readings | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Readings | Amps A Ø | 187.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Readings | Amps B Ø | 160.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Readings | Amps C Ø | 190.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001913 | BreakerVacuum | 805-0604 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Readings | Operations This Read Vac | 10 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Readings | Switching Operations | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Readings | Operations Counter AL | 167 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Readings | Operations Counter AF | 167 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Readings | Maintenance Operations | 10 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Readings | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Readings | Amps C Ø | 49.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Readings | Amps B Ø | 53.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Readings | Amps A Ø | 81.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Readings | 9 Month Operations | 10 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001915 | BreakerVacuum | 805-0658 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Readings | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Readings | Amps C Ø | 243.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Readings | Amps B Ø | 217.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Readings | Amps A Ø | 262.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Readings | Maintenance Operations | 8 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Readings | Operations Counter AF | 169 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Readings | Operations Counter AL | 169 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Readings | Operations This Read Vac | 8 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Readings | Switching Operations | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Readings | 9 Month Operations | 8 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001921 | BreakerVacuum | 805-BT2-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Readings | Switching Operations | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Readings | Operations This Read Vac | 9 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Readings | Operations Counter AL | 200 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Readings | Operations Counter AF | 200 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Readings | Maintenance Operations | 9 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Readings | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Readings | Amps C Ø | 29.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Readings | Amps B Ø | 32.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Readings | Amps A Ø | 28.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Readings | 9 Month Operations | 9 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001918 | BreakerVacuum | 805-0664 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Readings | Switching Operations | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Readings | Operations This Read Vac | 9 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Readings | Operations Counter AL | 212 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Readings | Operations Counter AF | 212 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Readings | Maintenance Operations | 9 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Readings | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Readings | Amps C Ø | 13.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Readings | Amps B Ø | 2.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Readings | Amps A Ø | 3.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Readings | 9 Month Operations | 9 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001912 | BreakerVacuum | 805-0603 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Readings | Switching Operations | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Readings | Operations This Read Vac | 6 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Readings | Operations Counter AL | 167 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Readings | Operations Counter AF | 167 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Readings | Maintenance Operations | 6 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Readings | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Readings | Amps C Ø | 101.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Readings | Amps B Ø | 105.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Readings | Amps A Ø | 108.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Readings | 9 Month Operations | 6 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001917 | BreakerVacuum | 805-0663 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Readings | Operations Counter AL | 188 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Readings | Operations Counter AF | 188 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Readings | Maintenance Operations | 9 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Readings | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Readings | Amps C Ø | 92.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Readings | Amps B Ø | 148.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Readings | Amps A Ø | 122.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Readings | 9 Month Operations | 9 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Readings | Operations This Read Vac | 9 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Readings | Switching Operations | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001914 | BreakerVacuum | 805-0605 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Readings | Switching Operations | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Readings | Operations This Read Vac | 8 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Readings | Operations Counter AL | 212 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Readings | Operations Counter AF | 212 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Readings | Maintenance Operations | 8 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Readings | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Readings | Amps C Ø | 456.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Readings | Amps B Ø | 476.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Readings | Amps A Ø | 486.0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Readings | 9 Month Operations | 8 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Patrol Inspection | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001919 | BreakerVacuum | 805-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCC000959 | LTCControl | 805-1 | LTC Control Insp | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCC000959 | LTCControl | 805-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCC000959 | LTCControl | 805-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCC000959 | LTCControl | 805-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCC000959 | LTCControl | 805-1 | LTC Control Insp | All Connections OK? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCC000959 | LTCControl | 805-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCC000959 | LTCControl | 805-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCC000959 | LTCControl | 805-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Readings | Amps A Ø | 55.0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Readings | Amps B Ø | 25.0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Readings | Amps C Ø | 30.0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Readings | 9 Month Operations | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Readings | General Comments | | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Readings | Operations Counter AF | 177 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Readings | Operations Counter AL | 177 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Readings | Operations This Read Vac | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Readings | Switching Operations | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Readings | Unknown Operations | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000126 | LTCMechanism | 805-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000126 | LTCMechanism | 805-1 | LTC Counter Readings | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000126 | LTCMechanism | 805-1 | LTC Counter Readings | LTC As Found Counter | 2132 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000126 | LTCMechanism | 805-1 | LTC Counter Readings | LTC As Left Counter | 2132 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000126 | LTCMechanism | 805-1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000126 | LTCMechanism | 805-1 | LTC Counter Readings | LTC Max Tap Position | 9R | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000126 | LTCMechanism | 805-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000126 | LTCMechanism | 805-1 | LTC Counter Readings | LTC Operations Since Last Insp | 974 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000126 | LTCMechanism | 805-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BK001440 | BreakerVacuum | 416-0631 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000126 | LTCMechanism | 805-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 20 | °C |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000126 | LTCMechanism | 805-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 20 | °C |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000126 | LTCMechanism | 805-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000126 | LTCMechanism | 805-1 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000126 | LTCMechanism | 805-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000126 | LTCMechanism | 805-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000126 | LTCMechanism | 805-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | LTCM000126 | LTCMechanism | 805-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Readings | Unknown Operations | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Readings | Switching Operations | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Readings | Operations This Read Vac | 1 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Readings | Operations Counter AL | 364 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Readings | Operations Counter AF | 364 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Readings | General Comments | | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Readings | 9 Month Operations | 5 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Readings | Amps A Ø | 50.0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Readings | Amps B Ø | 75.0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Readings | Amps C Ø | 40.0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Readings | Fault Adjusted Amps B Phase V | 6.13 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Readings | Fault Operations B Ø | 1 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Readings | Winding Temp Present | 25 | °C |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Readings | Winding Temp Max | 35 | °C |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Readings | Totalizer Meter Reading | .7560 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Readings | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Readings | LTC Totalizer Reading | 18144.00 | kw |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1900 | psi |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | TX000290 | WithLTC | 805-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BB0467 | BreakerVacuum | 416-0629 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Readings | Operations Counter AL | 380 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Readings | Operations Counter AF | 380 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Readings | Operations This Read Vac | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Readings | Switching Operations | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Readings | Unknown Operations | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Readings | General Comments | | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Readings | Amps C Ø | 185.0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Readings | Amps B Ø | 200.0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Readings | Amps A Ø | 190.0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Readings | 9 Month Operations | 2 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001965 | BreakerSF6 | 805-618 | GCB Readings | Switching Operations | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001965 | BreakerSF6 | 805-618 | GCB Readings | Operations This Read SF6 | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001965 | BreakerSF6 | 805-618 | GCB Readings | Operations Counter AL | 142 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001965 | BreakerSF6 | 805-618 | GCB Readings | Operations Counter AF | 142 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001965 | BreakerSF6 | 805-618 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001965 | BreakerSF6 | 805-618 | GCB Readings | Maintenance Operations | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001965 | BreakerSF6 | 805-618 | GCB Readings | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001965 | BreakerSF6 | 805-618 | GCB Readings | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001965 | BreakerSF6 | 805-618 | GCB Readings | Fault Operations | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001965 | BreakerSF6 | 805-618 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001965 | BreakerSF6 | 805-618 | GCB Patrol Inspection | Grounds in Place? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001965 | BreakerSF6 | 805-618 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001965 | BreakerSF6 | 805-618 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001965 | BreakerSF6 | 805-618 | GCB Patrol Inspection | SF6 Pressure | 66 | psi |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001965 | BreakerSF6 | 805-618 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001965 | BreakerSF6 | 805-618 | GCB Patrol Inspection | General Comments | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001965 | BreakerSF6 | 805-618 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001965 | BreakerSF6 | 805-618 | GCB Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001965 | BreakerSF6 | 805-618 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001965 | BreakerSF6 | 805-618 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001965 | BreakerSF6 | 805-618 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001965 | BreakerSF6 | 805-618 | GCB Patrol Inspection | Ambient Temperature | 55 | °F |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001965 | BreakerSF6 | 805-618 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001965 | BreakerSF6 | 805-618 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | BK001965 | BreakerSF6 | 805-618 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | ST000388 | Structure | 805-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | ST000388 | Structure | 805-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | ST000388 | Structure | 805-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | ST000388 | Structure | 805-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | ST000388 | Structure | 805-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | ST000388 | Structure | 805-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | ST000388 | Structure | 805-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | ST000388 | Structure | 805-Structure | Structure Patrol Inspection | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | ST000388 | Structure | 805-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | ST000388 | Structure | 805-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | ST000388 | Structure | 805-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | ST000388 | Structure | 805-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | ST000388 | Structure | 805-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | ST000388 | Structure | 805-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | ST000388 | Structure | 805-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | ST000388 | Structure | 805-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | ST000388 | Structure | 805-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | ST000388 | Structure | 805-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | ST000388 | Structure | 805-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | ST000388 | Structure | 805-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | ST000388 | Structure | 805-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | FE000380 | Fence | 805-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | FE000380 | Fence | 805-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | FE000380 | Fence | 805-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | FE000380 | Fence | 805-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | FE000380 | Fence | 805-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | FE000380 | Fence | 805-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | FE000380 | Fence | 805-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | FE000380 | Fence | 805-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | FE000380 | Fence | 805-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | FE000380 | Fence | 805-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | FE000380 | Fence | 805-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | FE000380 | Fence | 805-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | FE000380 | Fence | 805-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | FE000380 | Fence | 805-Fence | Fence Patrol Inspection | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | FE000380 | Fence | 805-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | FE000380 | Fence | 805-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | YD000385 | Yard | 805-Yard Distribution | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | YD000385 | Yard | 805-Yard Distribution | Yard Patrol Inspection | Vegetation | None | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | YD000385 | Yard | 805-Yard Distribution | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | YD000385 | Yard | 805-Yard Distribution | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | YD000385 | Yard | 805-Yard Distribution | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | YD000385 | Yard | 805-Yard Distribution | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | YD000385 | Yard | 805-Yard Distribution | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | YD000385 | Yard | 805-Yard Distribution | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | YD000385 | Yard | 805-Yard Distribution | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | YD000385 | Yard | 805-Yard Distribution | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | YD000385 | Yard | 805-Yard Distribution | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | YD000385 | Yard | 805-Yard Distribution | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | YD000385 | Yard | 805-Yard Distribution | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | YD000385 | Yard | 805-Yard Distribution | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | YD000385 | Yard | 805-Yard Distribution | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | YD000385 | Yard | 805-Yard Distribution | Yard Patrol Inspection | General Comments | | |
| 3/30/2023 7:18 | Distribution | Camargo Quarterly Inspection | YD000385 | Yard | 805-Yard Distribution | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0002 | BreakerVacuum | 416-0630 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Readings | Amps A Ø | 275.0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Readings | Amps B Ø | 280.0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Readings | Amps C Ø | 250.0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Readings | 9 Month Operations | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Readings | General Comments | | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Readings | Operations Counter AF | 234 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Readings | Unknown Operations | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Readings | Switching Operations | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Readings | Operations Counter AL | 234 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | KB0019 | BreakerVacuum | 416-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | LTCC000871 | LTCControl | 416-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | LTCC000871 | LTCControl | 416-1 | LTC Control Insp | General Comments | | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | LTCC000871 | LTCControl | 416-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | LTCC000871 | LTCControl | 416-1 | LTC Control Insp | All Connections OK? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | LTCC000871 | LTCControl | 416-1 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | LTCC000871 | LTCControl | 416-1 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | LTCC000871 | LTCControl | 416-1 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | LTCC000871 | LTCControl | 416-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | LTCMechanism | 416-1 | LTC Counter Readings | LTC Operations Since Last Insp | 564 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | LTCMechanism | 416-1 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | LTCMechanism | 416-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | LTCMechanism | 416-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | LTCMechanism | 416-1 | LTC Counter Readings | LTC As Left Counter | 120848 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | LTCMechanism | 416-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | LTCMechanism | 416-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | LTCMechanism | 416-1 | LTC Counter Readings | General Comments | | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | LTCMechanism | 416-1 | LTC Counter Readings | LTC As Found Counter | 120848 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | LTCMechanism | 416-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | LTCMechanism | 416-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | LTCMechanism | 416-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | LTCMechanism | 416-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | LTCMechanism | 416-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | LTCMechanism | 416-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Readings | LTC Totalizer Reading | 9748.80 | kw |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Readings | General Comments | | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Readings | Totalizer Meter Reading | .6770 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | B0423 | WithLTC | 416-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BCH001373 | Charger | 416-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BCH001373 | Charger | 416-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BCH001373 | Charger | 416-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BCH001373 | Charger | 416-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BCH001373 | Charger | 416-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BCH001373 | Charger | 416-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.6 | amps |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BCH001373 | Charger | 416-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BCH001373 | Charger | 416-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BAT001459 | Battery | 416-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BAT001459 | Battery | 416-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 40 | °F |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BAT001459 | Battery | 416-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BAT001459 | Battery | 416-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BAT001459 | Battery | 416-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BAT001459 | Battery | 416-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BAT001459 | Battery | 416-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BAT001459 | Battery | 416-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BAT001459 | Battery | 416-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BAT001459 | Battery | 416-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BAT001459 | Battery | 416-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BAT001459 | Battery | 416-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | BAT001459 | Battery | 416-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | ST000378 | Structure | 416-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | ST000378 | Structure | 416-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | ST000378 | Structure | 416-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | ST000378 | Structure | 416-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | ST000378 | Structure | 416-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | ST000378 | Structure | 416-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | ST000378 | Structure | 416-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | ST000378 | Structure | 416-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | ST000378 | Structure | 416-Structure | Structure Patrol Inspection | General Comments | | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | ST000378 | Structure | 416-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | ST000378 | Structure | 416-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | ST000378 | Structure | 416-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | ST000378 | Structure | 416-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | ST000378 | Structure | 416-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | ST000378 | Structure | 416-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | ST000378 | Structure | 416-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | ST000378 | Structure | 416-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | ST000378 | Structure | 416-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | ST000378 | Structure | 416-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | ST000378 | Structure | 416-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | FE000368 | Fence | 416-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | FE000368 | Fence | 416-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | FE000368 | Fence | 416-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | FE000368 | Fence | 416-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | FE000368 | Fence | 416-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | FE000368 | Fence | 416-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | FE000368 | Fence | 416-Fence | Fence Patrol Inspection | General Comments | | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | FE000368 | Fence | 416-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | FE000368 | Fence | 416-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | FE000368 | Fence | 416-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | FE000368 | Fence | 416-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | FE000368 | Fence | 416-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | FE000368 | Fence | 416-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | FE000368 | Fence | 416-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | FE000368 | Fence | 416-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | FE000368 | Fence | 416-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | YD000374 | Yard | 416-Yard | Yard Patrol Inspection | Ambient Temp | 40 | °F |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | YD000374 | Yard | 416-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | YD000374 | Yard | 416-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | YD000374 | Yard | 416-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | YD000374 | Yard | 416-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | YD000374 | Yard | 416-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | YD000374 | Yard | 416-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | YD000374 | Yard | 416-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | YD000374 | Yard | 416-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | YD000374 | Yard | 416-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | YD000374 | Yard | 416-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | YD000374 | Yard | 416-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | YD000374 | Yard | 416-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | YD000374 | Yard | 416-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/29/2023 15:15 | Distribution | Parker Seal Quarterly Inspection | YD000374 | Yard | 416-Yard | Yard Patrol Inspection | General Comments | | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Readings | Amps A Ø | 115.0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Readings | Amps B Ø | 85.0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Readings | Amps C Ø | 125.0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Readings | 9 Month Operations | 2 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Readings | General Comments | | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Readings | Operations Counter AF | 207 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Readings | Operations Counter AL | 207 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Readings | Operations This Read Vac | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Readings | Switching Operations | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Readings | Unknown Operations | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001286 | BreakerVacuum | 766-0847 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Readings | 9 Month Operations | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Readings | Amps A Ø | 15.0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Readings | Amps B Ø | 14.0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Readings | Amps C Ø | 15.0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Readings | General Comments | | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Readings | Operations Counter AF | 189 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Readings | Operations Counter AL | 189 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Readings | Operations This Read Vac | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Readings | Switching Operations | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Readings | Unknown Operations | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK001275 | BreakerVacuum | 766-0848 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Readings | Amps A Ø | 300.0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Readings | Amps B Ø | 260.0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Readings | Amps C Ø | 300.0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Readings | General Comments | | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Readings | Operations Counter AF | 69 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Readings | Operations Counter AL | 69 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Readings | Switching Operations | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Readings | Unknown Operations | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | K0009 | BreakerVacuum | 766-2 | VCB Readings | 9 Month Operations | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Readings | Amps A Ø | 140.0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Readings | 9 Month Operations | 7 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Readings | Amps B Ø | 165.0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Readings | Unknown Operations | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Readings | Switching Operations | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Readings | Operations This Read Vac | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Readings | Operations Counter AL | 230 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Readings | Operations Counter AF | 230 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Readings | General Comments | | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Readings | Amps C Ø | 155.0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BK000254 | BreakerVacuum | 766-0849 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | LTCMechanism | 766-2 | LTC Counter Readings | LTC As Left Counter | 64553 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | LTCMechanism | 766-2 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | LTCMechanism | 766-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | LTCMechanism | 766-2 | LTC Counter Readings | General Comments | | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | LTCMechanism | 766-2 | LTC Counter Readings | LTC As Found Counter | 64553 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | LTCMechanism | 766-2 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | LTCMechanism | 766-2 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | LTCMechanism | 766-2 | LTC Counter Readings | LTC Operations Since Last Insp | 571 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | LTCMechanism | 766-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | LTCC000939 | LTCControl | 766-2 | LTC Control Insp | All Connections OK? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | LTCC000939 | LTCControl | 766-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | LTCC000939 | LTCControl | 766-2 | LTC Control Insp | General Comments | | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | LTCC000939 | LTCControl | 766-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | LTCC000939 | LTCControl | 766-2 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | LTCC000939 | LTCControl | 766-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | LTCC000939 | LTCControl | 766-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | LTCC000939 | LTCControl | 766-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | LTCMechanism | 766-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | LTCMechanism | 766-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | LTCMechanism | 766-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | LTCMechanism | 766-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | LTCMechanism | 766-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Readings | Totalizer Meter Reading | 1.1772 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Readings | General Comments | | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Readings | LTC Totalizer Reading | 11301.12 | kw |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | S0005 | WithLTC | 766-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BAT001039 | Battery | 766-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BAT001039 | Battery | 766-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BAT001039 | Battery | 766-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BAT001039 | Battery | 766-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BAT001039 | Battery | 766-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BAT001039 | Battery | 766-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BAT001039 | Battery | 766-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BAT001039 | Battery | 766-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BAT001039 | Battery | 766-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BAT001039 | Battery | 766-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BAT001039 | Battery | 766-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BAT001039 | Battery | 766-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BAT001039 | Battery | 766-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BAT001039 | Battery | 766-Battery Bank | Battery Patrol Inspection | Battery Bank Volts | 53.0 | VDC |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BAT001039 | Battery | 766-Battery Bank | Battery Patrol Inspection | Battery Bank Amps | 1.7 | AMPS |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BAT001039 | Battery | 766-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 45 | °F |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BAT001039 | Battery | 766-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BCH001316 | Charger | 766-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BCH001316 | Charger | 766-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BCH001316 | Charger | 766-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BCH001316 | Charger | 766-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BCH001316 | Charger | 766-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.7 | amps |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BCH001316 | Charger | 766-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BCH001316 | Charger | 766-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | BCH001316 | Charger | 766-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | ST000299 | Structure | 766-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | ST000299 | Structure | 766-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | ST000299 | Structure | 766-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | ST000299 | Structure | 766-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | ST000299 | Structure | 766-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | ST000299 | Structure | 766-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | ST000299 | Structure | 766-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | ST000299 | Structure | 766-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | ST000299 | Structure | 766-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | ST000299 | Structure | 766-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | ST000299 | Structure | 766-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | ST000299 | Structure | 766-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | ST000299 | Structure | 766-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | ST000299 | Structure | 766-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | ST000299 | Structure | 766-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | ST000299 | Structure | 766-Structure | Structure Patrol Inspection | General Comments | | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | ST000299 | Structure | 766-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | ST000299 | Structure | 766-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | ST000299 | Structure | 766-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | ST000299 | Structure | 766-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | ST000299 | Structure | 766-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | ST000299 | Structure | 766-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | FE000288 | Fence | 766-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | FE000288 | Fence | 766-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | FE000288 | Fence | 766-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | FE000288 | Fence | 766-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | FE000288 | Fence | 766-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | FE000288 | Fence | 766-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | FE000288 | Fence | 766-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | FE000288 | Fence | 766-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | FE000288 | Fence | 766-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | FE000288 | Fence | 766-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | FE000288 | Fence | 766-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | FE000288 | Fence | 766-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | FE000288 | Fence | 766-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | FE000288 | Fence | 766-Fence | Fence Patrol Inspection | General Comments | | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | FE000288 | Fence | 766-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | FE000288 | Fence | 766-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | YD000291 | Yard | 766-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | YD000291 | Yard | 766-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | YD000291 | Yard | 766-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | YD000291 | Yard | 766-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | YD000291 | Yard | 766-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | YD000291 | Yard | 766-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | YD000291 | Yard | 766-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | YD000291 | Yard | 766-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | YD000291 | Yard | 766-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | YD000291 | Yard | 766-Yard | Yard Patrol Inspection | General Comments | | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | YD000291 | Yard | 766-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | YD000291 | Yard | 766-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | YD000291 | Yard | 766-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | YD000291 | Yard | 766-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | YD000291 | Yard | 766-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/29/2023 15:08 | Distribution | Sylvania Quarterly Inspection | YD000291 | Yard | 766-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Readings | Operations Counter AF | 211 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Readings | General Comments | | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Readings | Unknown Operations | 0 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Readings | Fault Operations A Ø | 3 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Readings | Fault Adjusted Amps A Phase V | 27.22 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Readings | Amps C Ø | 85.0 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Readings | Amps B Ø | 75.0 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Readings | Amps A Ø | 85.0 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Readings | 9 Month Operations | 4 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Readings | Operations Counter AL | 211 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Readings | Operations This Read Vac | 3 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Readings | Switching Operations | 0 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BK000502 | BreakerVacuum | 839-0637 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Readings | 9 Month Operations | 1 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Readings | Operations Counter AF | 342 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Readings | General Comments | | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Readings | Operations Counter AL | 342 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Readings | Operations This Read Vac | 0 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Readings | Switching Operations | 0 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Readings | Unknown Operations | 0 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Readings | Amps A Ø | 60.0 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Readings | Amps B Ø | 20.0 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Readings | Amps C Ø | 60.0 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | K0170 | BreakerVacuum | 839-0636 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | LTCC000247 | LTCControl | 839-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | LTCC000247 | LTCControl | 839-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | LTCC000247 | LTCControl | 839-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | LTCC000247 | LTCControl | 839-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | LTCC000247 | LTCControl | 839-1 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | LTCC000247 | LTCControl | 839-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | LTCC000247 | LTCControl | 839-1 | LTC Control Insp | All Connections OK? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | LTCC000247 | LTCControl | 839-1 | LTC Control Insp | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | LTCC000247 | LTCControl | 839-1 | LTC Control Insp | General Comments | | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | LTCMechanism | 839-1 | LTC Counter Readings | LTC As Left Counter | 230057 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | LTCMechanism | 839-1 | LTC Counter Readings | LTC As Found Counter | 230057 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | LTCMechanism | 839-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | LTCMechanism | 839-1 | LTC Counter Readings | LTC Max Tap Position | 16R | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | LTCMechanism | 839-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | LTCMechanism | 839-1 | LTC Counter Readings | LTC Operations Since Last Insp | 402 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | LTCMechanism | 839-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | LTCMechanism | 839-1 | LTC Counter Readings | General Comments | | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | LTCMechanism | 839-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | LTCMechanism | 839-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | LTCMechanism | 839-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | LTCMechanism | 839-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | LTCMechanism | 839-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | LTCMechanism | 839-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | LTCMechanism | 839-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | LTCMechanism | 839-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Readings | LTC Totalizer Reading | 1608.96 | kw |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Readings | General Comments | | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Readings | Totalizer Meter Reading | .5028 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | B0276 | WithLTC | 839-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BCH001014 | Charger | 839-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BCH001014 | Charger | 839-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BCH001014 | Charger | 839-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BCH001014 | Charger | 839-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BAT001362 | Battery | 839-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BAT001362 | Battery | 839-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BAT001362 | Battery | 839-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BAT001362 | Battery | 839-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BAT001362 | Battery | 839-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BAT001362 | Battery | 839-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BAT001362 | Battery | 839-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BAT001362 | Battery | 839-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BAT001362 | Battery | 839-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BAT001362 | Battery | 839-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BAT001362 | Battery | 839-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | BAT001362 | Battery | 839-Battery Bank | Battery Patrol Inspection | Battery Bank Volts | 54.0 | VDC |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | ST000363 | Structure | 839-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | ST000363 | Structure | 839-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | ST000363 | Structure | 839-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | ST000363 | Structure | 839-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | ST000363 | Structure | 839-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | ST000363 | Structure | 839-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | ST000363 | Structure | 839-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | ST000363 | Structure | 839-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | ST000363 | Structure | 839-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | ST000363 | Structure | 839-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | ST000363 | Structure | 839-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | ST000363 | Structure | 839-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | ST000363 | Structure | 839-Structure | Structure Patrol Inspection | General Comments | | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | ST000363 | Structure | 839-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | ST000363 | Structure | 839-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | ST000363 | Structure | 839-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | ST000363 | Structure | 839-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | ST000363 | Structure | 839-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | ST000363 | Structure | 839-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | ST000363 | Structure | 839-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | ST000363 | Structure | 839-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | ST000363 | Structure | 839-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | FE000877 | Fence | 839-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | FE000877 | Fence | 839-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | FE000877 | Fence | 839-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | FE000877 | Fence | 839-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | FE000877 | Fence | 839-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | FE000877 | Fence | 839-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | FE000877 | Fence | 839-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | FE000877 | Fence | 839-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | FE000877 | Fence | 839-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | FE000877 | Fence | 839-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | FE000877 | Fence | 839-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | FE000877 | Fence | 839-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | FE000877 | Fence | 839-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | FE000877 | Fence | 839-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | FE000877 | Fence | 839-Fence | Fence Patrol Inspection | General Comments | | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | FE000877 | Fence | 839-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | YD000360 | Yard | 839-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | YD000360 | Yard | 839-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | YD000360 | Yard | 839-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | YD000360 | Yard | 839-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | YD000360 | Yard | 839-Yard | Yard Patrol Inspection | General Comments | | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | YD000360 | Yard | 839-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | YD000360 | Yard | 839-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | YD000360 | Yard | 839-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | YD000360 | Yard | 839-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | YD000360 | Yard | 839-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | YD000360 | Yard | 839-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | YD000360 | Yard | 839-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | YD000360 | Yard | 839-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | YD000360 | Yard | 839-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/29/2023 15:02 | Distribution | Winchester South Quarterly Inspection | YD000360 | Yard | 839-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Readings | Operations This Read Vac | 1 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Readings | Operations Counter AL | 459 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Readings | Operations Counter AF | 458 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Readings | General Comments | | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Readings | Switching Operations | 1 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Readings | Amps C Ø | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Readings | Amps B Ø | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Readings | Amps A Ø | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Readings | 9 Month Operations | 1 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0088 | BreakerVacuum | 423-BT1-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Readings | Operations Counter AF | 256 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Readings | Operations Counter AL | 256 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Readings | General Comments | | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Readings | Unknown Operations | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Readings | Switching Operations | 5 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Readings | Amps C Ø | 412 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Readings | Amps B Ø | 415 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Readings | Operations This Read Vac | 5 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Readings | 9 Month Operations | 6 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Readings | Accumulated Fault Duty A Ph V | .76 | % |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Readings | Accumulated Fault Duty B Ph V | .76 | % |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Readings | Accumulated Fault Duty C Ph V | .76 | % |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Readings | Amps A Ø | 411 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Readings | 9 Month Operations | 1 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Readings | Accumulated Fault Duty A Ph V | .38 | % |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Readings | Accumulated Fault Duty B Ph V | 1.13 | % |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Readings | Accumulated Fault Duty C Ph V | .38 | % |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Readings | Amps A Ø | 59 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Readings | Amps B Ø | 50 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Readings | Amps C Ø | 57 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Readings | General Comments | | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Readings | Unknown Operations | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Readings | Switching Operations | 1 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Readings | Operations This Read Vac | 1 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Readings | Operations Counter AL | 226 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Readings | Operations Counter AF | 226 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Readings | 9 Month Operations | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Readings | General Comments | | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Readings | Operations Counter AF | 73 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Readings | Operations Counter AL | 73 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Readings | Switching Operations | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Readings | Unknown Operations | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Readings | Amps A Ø | 465 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Readings | Amps B Ø | 469 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Readings | Amps C Ø | 456 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0196 | BreakerVacuum | 423-2402 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0197 | BreakerVacuum | 423-2403 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | K0198 | BreakerVacuum | 423-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | TB0900 | BreakerSF6 | 423-808 | GCB Readings | Switching Operations | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | TB0900 | BreakerSF6 | 423-808 | GCB Readings | Operations This Read SF6 | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | TB0900 | BreakerSF6 | 423-808 | GCB Readings | Operations Counter AL | 51 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | TB0900 | BreakerSF6 | 423-808 | GCB Readings | Operations Counter AF | 51 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | TB0900 | BreakerSF6 | 423-808 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | TB0900 | BreakerSF6 | 423-808 | GCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | TB0900 | BreakerSF6 | 423-808 | GCB Readings | General Comments | | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | TB0900 | BreakerSF6 | 423-808 | GCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | TB0900 | BreakerSF6 | 423-808 | GCB Readings | Fault Operations | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | TB0900 | BreakerSF6 | 423-808 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | TB0900 | BreakerSF6 | 423-808 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | TB0900 | BreakerSF6 | 423-808 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | TB0900 | BreakerSF6 | 423-808 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | TB0900 | BreakerSF6 | 423-808 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | TB0900 | BreakerSF6 | 423-808 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | TB0900 | BreakerSF6 | 423-808 | GCB Patrol Inspection | SF6 Pressure | 85 | psi |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | TB0900 | BreakerSF6 | 423-808 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | TB0900 | BreakerSF6 | 423-808 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | TB0900 | BreakerSF6 | 423-808 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | TB0900 | BreakerSF6 | 423-808 | GCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | TB0900 | BreakerSF6 | 423-808 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | TB0900 | BreakerSF6 | 423-808 | GCB Patrol Inspection | Ambient Temperature | 55 | °F |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | TB0900 | BreakerSF6 | 423-808 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | TB0900 | BreakerSF6 | 423-808 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | TB0900 | BreakerSF6 | 423-808 | GCB Patrol Inspection | General Comments | | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | TB0900 | BreakerSF6 | 423-808 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | TB0900 | BreakerSF6 | 423-808 | GCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | LTCC000457 | LTCControl | 423-2 | LTC Control Insp | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | LTCC000457 | LTCControl | 423-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | LTCC000457 | LTCControl | 423-2 | LTC Control Insp | All Connections OK? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | LTCC000457 | LTCControl | 423-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | LTCC000457 | LTCControl | 423-2 | LTC Control Insp | LTC Output Voltage Level | 0 | VAC |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | LTCC000457 | LTCControl | 423-2 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | LTCC000457 | LTCControl | 423-2 | LTC Control Insp | VRR Base Voltage AF | 0 | VAC |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | LTCC000457 | LTCControl | 423-2 | LTC Control Insp | VRR Base Voltage AL | 0 | VAC |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | LTCC000457 | LTCControl | 423-2 | LTC Control Insp | VRR Time Delay | 0 | Seconds |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | LTCMechanism | 423-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | LTCMechanism | 423-2 | LTC Counter Readings | General Comments | | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | LTCMechanism | 423-2 | LTC Counter Readings | LTC As Found Counter | 4320 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | LTCMechanism | 423-2 | LTC Counter Readings | LTC As Left Counter | 4320 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | LTCMechanism | 423-2 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | LTCMechanism | 423-2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | LTCMechanism | 423-2 | LTC Counter Readings | LTC Min Tap Position | Neutral | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | LTCMechanism | 423-2 | LTC Counter Readings | LTC Operations Since Last Insp | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | LTCMechanism | 423-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | LTCMechanism | 423-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | LTCMechanism | 423-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | LTCMechanism | 423-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | LTCMechanism | 423-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | LTCMechanism | 423-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Readings | Totalizer Meter Reading | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Readings | Winding Temp Max | 18 | °C |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Readings | Winding Temp Present | 18 | °C |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Readings | LTC Totalizer Reading | 0 | kw |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Readings | General Comments | | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2 | psi |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0072 | WithLTC | 423-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | LTCC000163 | LTCControl | 423-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | LTCC000163 | LTCControl | 423-1 | LTC Control Insp | LTC Output Voltage Level | 124.1 | VAC |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | LTCC000163 | LTCControl | 423-1 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | LTCC000163 | LTCControl | 423-1 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | LTCC000163 | LTCControl | 423-1 | LTC Control Insp | General Comments | | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | LTCC000163 | LTCControl | 423-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | LTCC000163 | LTCControl | 423-1 | LTC Control Insp | All Connections OK? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | LTCC000163 | LTCControl | 423-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | LTCMechanism | 423-1 | LTC Counter Readings | LTC As Found Counter | 74673 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | LTCMechanism | 423-1 | LTC Counter Readings | LTC As Left Counter | 74677 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | LTCMechanism | 423-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | LTCMechanism | 423-1 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | LTCMechanism | 423-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | LTCMechanism | 423-1 | LTC Counter Readings | LTC Operations Since Last Insp | 908 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | LTCMechanism | 423-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | LTCMechanism | 423-1 | LTC Counter Readings | General Comments | | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | LTCMechanism | 423-1 | LTC Counter Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | LTCMechanism | 423-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | LTCMechanism | 423-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | LTCMechanism | 423-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0 | psi |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | LTCMechanism | 423-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | LTCMechanism | 423-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | LTCMechanism | 423-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | LTCMechanism | 423-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | LTCMechanism | 423-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 30 | °C |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | LTCMechanism | 423-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 50 | °C |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | LTCMechanism | 423-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Readings | Oil Temp Max | 42 | °C |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Readings | Oil Temp Present | 34 | °C |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Readings | LTC Totalizer Reading | 10108.8 | kw |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Readings | General Comments | | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.053 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Readings | Winding Temp Max | 42 | °C |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Readings | Winding Temp Present | 38 | °C |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 65 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3 | psi |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | S0071 | WithLTC | 423-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | BAT001490 | Battery | 423-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | BAT001490 | Battery | 423-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | BAT001490 | Battery | 423-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | BAT001490 | Battery | 423-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | BAT001490 | Battery | 423-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | BAT001490 | Battery | 423-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | BAT001490 | Battery | 423-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.4 | VDC |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | BAT001490 | Battery | 423-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.2 | VDC |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | BAT001490 | Battery | 423-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | BAT001490 | Battery | 423-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | BAT001490 | Battery | 423-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | BAT001490 | Battery | 423-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | BAT001490 | Battery | 423-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | BCH001421 | Charger | 423-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | BCH001421 | Charger | 423-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | BCH001421 | Charger | 423-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | BCH001421 | Charger | 423-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | BCH001421 | Charger | 423-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0 | millivolts |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | BCH001421 | Charger | 423-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.8 | amps |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | BCH001421 | Charger | 423-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | BCH001421 | Charger | 423-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | CH000106 | ControlHouse | 423-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | CH000106 | ControlHouse | 423-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | CH000106 | ControlHouse | 423-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | CH000106 | ControlHouse | 423-Control House | Control House Patrol Inspection | General Comments | | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | CH000106 | ControlHouse | 423-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | CH000106 | ControlHouse | 423-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | CH000106 | ControlHouse | 423-Control House | Control House Patrol Inspection | Trash Emptied? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | CH000106 | ControlHouse | 423-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | CH000106 | ControlHouse | 423-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | CH000106 | ControlHouse | 423-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | CH000106 | ControlHouse | 423-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | CH000106 | ControlHouse | 423-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | CH000106 | ControlHouse | 423-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | CH000106 | ControlHouse | 423-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | CH000106 | ControlHouse | 423-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | CH000106 | ControlHouse | 423-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | CH000106 | ControlHouse | 423-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | CH000106 | ControlHouse | 423-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | CH000106 | ControlHouse | 423-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | CH000106 | ControlHouse | 423-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | CH000106 | ControlHouse | 423-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | CH000106 | ControlHouse | 423-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | CH000106 | ControlHouse | 423-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | ST000503 | Structure | 423-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | ST000503 | Structure | 423-Structure | Structure Patrol Inspection | General Comments | | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | ST000503 | Structure | 423-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | ST000503 | Structure | 423-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | ST000503 | Structure | 423-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | ST000503 | Structure | 423-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | ST000503 | Structure | 423-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | ST000503 | Structure | 423-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | ST000503 | Structure | 423-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | ST000503 | Structure | 423-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | ST000503 | Structure | 423-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | ST000503 | Structure | 423-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | ST000503 | Structure | 423-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | ST000503 | Structure | 423-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | ST000503 | Structure | 423-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | ST000503 | Structure | 423-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | ST000503 | Structure | 423-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | ST000503 | Structure | 423-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | ST000503 | Structure | 423-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | ST000503 | Structure | 423-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | ST000503 | Structure | 423-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | ST000503 | Structure | 423-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | FE000494 | Fence | 423-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | FE000494 | Fence | 423-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | FE000494 | Fence | 423-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | FE000494 | Fence | 423-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | FE000494 | Fence | 423-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | FE000494 | Fence | 423-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | FE000494 | Fence | 423-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | FE000494 | Fence | 423-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | FE000494 | Fence | 423-Fence | Fence Patrol Inspection | General Comments | | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | FE000494 | Fence | 423-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | FE000494 | Fence | 423-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | FE000494 | Fence | 423-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | FE000494 | Fence | 423-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | FE000494 | Fence | 423-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | FE000494 | Fence | 423-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | FE000494 | Fence | 423-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | YD000501 | Yard | 423-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | YD000501 | Yard | 423-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | YD000501 | Yard | 423-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | YD000501 | Yard | 423-Yard | Yard Patrol Inspection | General Comments | | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | YD000501 | Yard | 423-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | YD000501 | Yard | 423-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | YD000501 | Yard | 423-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | YD000501 | Yard | 423-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | YD000501 | Yard | 423-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | YD000501 | Yard | 423-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | YD000501 | Yard | 423-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | YD000501 | Yard | 423-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | YD000501 | Yard | 423-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/29/2023 14:43 | Distribution | Lebanon Junction Quarterly Inspection | YD000501 | Yard | 423-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Readings | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Readings | Amps C Ø | 153 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Readings | Amps B Ø | 129 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Readings | Amps A Ø | 122 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Readings | Accumulated Fault Duty C Ph V | 9.86 | % |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Readings | Operations Counter AF | 30 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Readings | Operations Counter AL | 30 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Readings | Accumulated Fault Duty B Ph V | 7.67 | % |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Readings | Unknown Operations | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Readings | Switching Operations | 3 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Readings | Accumulated Fault Duty A Ph V | 10.95 | % |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Readings | Operations This Read Vac | 3 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Readings | 9 Month Operations | 3 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0203 | BreakerVacuum | 767-2415 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Readings | 9 Month Operations | 1 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Readings | Unknown Operations | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Readings | Switching Operations | 1 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Readings | Operations This Read Vac | 1 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Readings | Operations Counter AL | 285 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Readings | Operations Counter AF | 284 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Readings | Accumulated Fault Duty A Ph V | .51 | % |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Readings | Accumulated Fault Duty C Ph V | 1.02 | % |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Readings | Amps A Ø | 292 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Readings | Amps B Ø | 294 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Readings | Amps C Ø | 290 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Readings | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | WB0182 | BreakerVacuum | 767-2414 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Readings | Accumulated Fault Duty A Ph V | 1.02 | % |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Readings | Accumulated Fault Duty B Ph V | 1.02 | % |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Readings | Accumulated Fault Duty C Ph V | 1.53 | % |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Readings | Amps B Ø | 90 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Readings | Operations Counter AF | 321 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Readings | Operations Counter AL | 322 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Readings | 9 Month Operations | 1 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Readings | Operations This Read Vac | 1 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Readings | Amps A Ø | 92 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Readings | Switching Operations | 1 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Readings | Amps C Ø | 82 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Readings | Unknown Operations | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Readings | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | K0150 | BreakerVacuum | 767-2413 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Readings | 9 Month Operations | 1 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Readings | Operations Counter AF | 916 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Readings | Operations Counter AL | 917 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Readings | Operations This Read Vac | 1 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Readings | Unknown Operations | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Readings | Switching Operations | 1 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Readings | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Readings | Amps A Ø | 7 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Readings | Amps B Ø | 3 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Readings | Amps C Ø | 1 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0207 | BreakerVacuum | 767-2412 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Readings | Operations This Read Vac | 1 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Readings | Switching Operations | 1 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Readings | Amps B Ø | 37 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Readings | Amps C Ø | 53 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Readings | Amps A Ø | 50 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Readings | Operations Counter AL | 4 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Readings | Accumulated Fault Duty A Ph V | 24.58 | % |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Readings | Unknown Operations | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Readings | Operations Counter AF | 3 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Readings | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Readings | Accumulated Fault Duty C Ph V | 21.63 | % |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Readings | Accumulated Fault Duty B Ph V | 18.68 | % |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Readings | 9 Month Operations | 1 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0205 | BreakerVacuum | 767-2411 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Readings | Amps C Ø | 195 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Readings | Amps B Ø | 211 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Readings | Amps A Ø | 214 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Readings | 9 Month Operations | 1 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Readings | Unknown Operations | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Readings | Switching Operations | 1 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Readings | Operations This Read Vac | 1 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Readings | Operations Counter AL | 152 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Readings | Operations Counter AF | 152 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Readings | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK001110 | BreakerVacuum | 767-2410 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Readings | Unknown Operations | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Readings | Switching Operations | 1 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Readings | Operations This Read Vac | 1 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Readings | Operations Counter AL | 205 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Readings | Operations Counter AF | 204 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Readings | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Readings | Amps C Ø | 107 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Readings | 9 Month Operations | 1 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Readings | Accumulated Fault Duty A Ph V | 2.28 | % |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Readings | Accumulated Fault Duty B Ph V | 1.83 | % |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Readings | Accumulated Fault Duty C Ph V | 1.83 | % |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Readings | Amps A Ø | 111 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Readings | Amps B Ø | 112 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BK000421 | BreakerVacuum | 767-2409 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Readings | Amps C Ø | 480 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Readings | Amps B Ø | 480 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Readings | Amps A Ø | 480 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Readings | 9 Month Operations | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Readings | Unknown Operations | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Readings | Switching Operations | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Readings | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Readings | Operations Counter AL | 213 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Readings | Operations Counter AF | 213 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BB0381 | BreakerVacuum | 767-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Readings | Unknown Operations | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Readings | Switching Operations | 1 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Readings | Operations This Read Vac | 1 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Readings | Operations Counter AL | 67 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Readings | Operations Counter AF | 66 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Readings | Amps C Ø | 320 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Readings | Amps B Ø | 320 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Readings | Amps A Ø | 320 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Readings | Accumulated Fault Duty C Ph V | .79 | % |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Readings | 9 Month Operations | 1 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | CB0153 | BreakerVacuum | 767-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCC000009 | LTCControl | 767-2 | LTC Control Insp | All Connections OK? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCC000009 | LTCControl | 767-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCC000009 | LTCControl | 767-2 | LTC Control Insp | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCC000009 | LTCControl | 767-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCC000009 | LTCControl | 767-2 | LTC Control Insp | LTC Output Voltage Level | 124.4 | VAC |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCC000009 | LTCControl | 767-2 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCC000009 | LTCControl | 767-2 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCC000009 | LTCControl | 767-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | LTCMechanism | 767-2 | LTC Counter Readings | LTC As Left Counter | 125433 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | LTCMechanism | 767-2 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | LTCMechanism | 767-2 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | LTCMechanism | 767-2 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | LTCMechanism | 767-2 | LTC Counter Readings | LTC Operations Since Last Insp | 503 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | LTCMechanism | 767-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | LTCMechanism | 767-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | LTCMechanism | 767-2 | LTC Counter Readings | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | LTCMechanism | 767-2 | LTC Counter Readings | LTC As Found Counter | 125431 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | LTCMechanism | 767-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | LTCMechanism | 767-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | LTCMechanism | 767-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | LTCMechanism | 767-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | LTCMechanism | 767-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | LTCMechanism | 767-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Readings | LTC Totalizer Reading | 14893.2 | kw |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Readings | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Readings | Winding Temp Max | 80 | °C |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Readings | Totalizer Meter Reading | .8274 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | C0505 | WithLTC | 767-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCC000639 | LTCControl | 767-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCC000639 | LTCControl | 767-1 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCC000639 | LTCControl | 767-1 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCC000639 | LTCControl | 767-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCC000639 | LTCControl | 767-1 | LTC Control Insp | LTC Output Voltage Level | 124.2 | VAC |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCC000639 | LTCControl | 767-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCC000639 | LTCControl | 767-1 | LTC Control Insp | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCC000639 | LTCControl | 767-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCC000639 | LTCControl | 767-1 | LTC Control Insp | All Connections OK? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCM000023 | LTCMechanism | 767-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCM000023 | LTCMechanism | 767-1 | LTC Counter Readings | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCM000023 | LTCMechanism | 767-1 | LTC Counter Readings | LTC As Found Counter | 16188 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCM000023 | LTCMechanism | 767-1 | LTC Counter Readings | LTC As Left Counter | 16190 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCM000023 | LTCMechanism | 767-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCM000023 | LTCMechanism | 767-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCM000023 | LTCMechanism | 767-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCM000023 | LTCMechanism | 767-1 | LTC Counter Readings | LTC Operations Since Last Insp | 343 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCM000023 | LTCMechanism | 767-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCM000023 | LTCMechanism | 767-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCM000023 | LTCMechanism | 767-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCM000023 | LTCMechanism | 767-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCM000023 | LTCMechanism | 767-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCM000023 | LTCMechanism | 767-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | LTCM000023 | LTCMechanism | 767-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Readings | LTC Totalizer Reading | 8629.2 | kw |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Readings | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Readings | Winding Temp Max | 45 | °C |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Readings | Winding Temp Present | 35 | °C |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Readings | Totalizer Meter Reading | .4794 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | B0421 | WithLTC | 767-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BAT001562 | Battery | 767-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BAT001562 | Battery | 767-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BAT001562 | Battery | 767-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26 | VDC |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BAT001562 | Battery | 767-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27 | VDC |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BAT001562 | Battery | 767-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BAT001562 | Battery | 767-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BAT001562 | Battery | 767-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BAT001562 | Battery | 767-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BAT001562 | Battery | 767-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BAT001562 | Battery | 767-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BAT001562 | Battery | 767-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BAT001562 | Battery | 767-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 48 | °F |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BAT001562 | Battery | 767-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | YD000525 | Yard | 767-Yard | Yard Patrol Inspection | Ambient Temp | 48 | °F |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | YD000525 | Yard | 767-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | YD000525 | Yard | 767-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | YD000525 | Yard | 767-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | YD000525 | Yard | 767-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | YD000525 | Yard | 767-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | YD000525 | Yard | 767-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | YD000525 | Yard | 767-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | YD000525 | Yard | 767-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | YD000525 | Yard | 767-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | YD000525 | Yard | 767-Yard | Yard Patrol Inspection | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | YD000525 | Yard | 767-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | YD000525 | Yard | 767-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | YD000525 | Yard | 767-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | YD000525 | Yard | 767-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | YD000525 | Yard | 767-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | YD000525 | Yard | 767-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BCH001253 | Charger | 767-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.3 | VDC |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BCH001253 | Charger | 767-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 3.4 | amps |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BCH001253 | Charger | 767-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BCH001253 | Charger | 767-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BCH001253 | Charger | 767-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BCH001253 | Charger | 767-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BCH001253 | Charger | 767-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.3 | VDC |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | BCH001253 | Charger | 767-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0 | millivolts |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | ST000529 | Structure | 767-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | ST000529 | Structure | 767-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | ST000529 | Structure | 767-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | ST000529 | Structure | 767-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | ST000529 | Structure | 767-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | ST000529 | Structure | 767-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | ST000529 | Structure | 767-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | ST000529 | Structure | 767-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | ST000529 | Structure | 767-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | ST000529 | Structure | 767-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | ST000529 | Structure | 767-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | ST000529 | Structure | 767-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | ST000529 | Structure | 767-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | ST000529 | Structure | 767-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | ST000529 | Structure | 767-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | ST000529 | Structure | 767-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | ST000529 | Structure | 767-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | ST000529 | Structure | 767-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | ST000529 | Structure | 767-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | ST000529 | Structure | 767-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | ST000529 | Structure | 767-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | ST000529 | Structure | 767-Structure | Structure Patrol Inspection | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | FE000519 | Fence | 767-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | FE000519 | Fence | 767-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | FE000519 | Fence | 767-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | FE000519 | Fence | 767-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | FE000519 | Fence | 767-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | FE000519 | Fence | 767-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | FE000519 | Fence | 767-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | FE000519 | Fence | 767-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | FE000519 | Fence | 767-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | FE000519 | Fence | 767-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | FE000519 | Fence | 767-Fence | Fence Patrol Inspection | General Comments | | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | FE000519 | Fence | 767-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | FE000519 | Fence | 767-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | FE000519 | Fence | 767-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | FE000519 | Fence | 767-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 11:25 | Distribution | Elizabethtown 2 Quarterly Inspection | FE000519 | Fence | 767-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Readings | 9 Month Operations | 2 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Readings | Amps A Ø | 75.0 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Readings | Amps B Ø | 55.0 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Readings | Amps C Ø | 50.0 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Readings | General Comments | | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Readings | Operations Counter AF | 175 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Readings | Operations Counter AL | 177 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Readings | Unknown Operations | 0 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Readings | Switching Operations | 2 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Readings | Operations This Read Vac | 2 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000918 | BreakerVacuum | 824-0961 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Readings | Operations This Read Vac | 2 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Readings | Switching Operations | 2 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Readings | Unknown Operations | 0 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Readings | Operations Counter AL | 185 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Readings | Operations Counter AF | 183 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Readings | 9 Month Operations | 8 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Readings | General Comments | | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Readings | Amps A Ø | 105.0 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Readings | Amps C Ø | 105.0 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Readings | Amps B Ø | 90.0 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BK000917 | BreakerVacuum | 824-0960 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | Tank Leaks | None | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | Pressure Vessel Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | Pop-off Valve Tested Date | 2023-03-28 00:00:00.000000 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | General Comments | | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | Air Compressor Belt Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | Air Compressor Oil Status | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | Air Leaks | None | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | Air Pressure OK? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | Air Tank Bleed (> 40°F)? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | AirCompressor Heater Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Readings | 9 Months Operations OCB New | 0 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Readings | Fault Operations | 0 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Readings | General Comments | | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Readings | Number of Ops last 9 Months | 0 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Readings | Operations Counter AF | 427 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Readings | Operations Counter AL | 427 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Readings | Operations This Read Oil | 0 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Readings | Switching Operations | 0 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TB0237 | BreakerOil | 824-708 | OCB Readings | Unknown Operations | 0 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.1790 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Readings | General Comments | | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Readings | LTC Totalizer Reading | 5659.20 | kw |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1400 | psi |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | TX000055 | WithLTC | 824-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | LTCC000648 | LTCControl | 824-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | LTCC000648 | LTCControl | 824-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | LTCC000648 | LTCControl | 824-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | LTCC000648 | LTCControl | 824-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | LTCC000648 | LTCControl | 824-1 | LTC Control Insp | All Connections OK? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | LTCC000648 | LTCControl | 824-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | LTCC000648 | LTCControl | 824-1 | LTC Control Insp | General Comments | | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | LTCC000648 | LTCControl | 824-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | LTCM000037 | LTCMechanism | 824-1 | LTC Counter Readings | LTC As Found Counter | 16198 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | LTCM000037 | LTCMechanism | 824-1 | LTC Counter Readings | LTC As Left Counter | 16198 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | LTCM000037 | LTCMechanism | 824-1 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | LTCM000037 | LTCMechanism | 824-1 | LTC Counter Readings | LTC Max Tap Position | 5R | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | LTCM000037 | LTCMechanism | 824-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | LTCM000037 | LTCMechanism | 824-1 | LTC Counter Readings | LTC Operations Since Last Insp | 267 | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | LTCM000037 | LTCMechanism | 824-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | LTCM000037 | LTCMechanism | 824-1 | LTC Counter Readings | General Comments | | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | LTCM000037 | LTCMechanism | 824-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | LTCM000037 | LTCMechanism | 824-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | LTCM000037 | LTCMechanism | 824-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | LTCM000037 | LTCMechanism | 824-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | LTCM000037 | LTCMechanism | 824-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | LTCM000037 | LTCMechanism | 824-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 35 | °C |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | LTCM000037 | LTCMechanism | 824-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 20 | °C |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | LTCM000037 | LTCMechanism | 824-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | LTCM000037 | LTCMechanism | 824-1 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BCH001154 | Charger | 824-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BCH001154 | Charger | 824-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BCH001154 | Charger | 824-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BCH001154 | Charger | 824-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BCH001154 | Charger | 824-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BCH001154 | Charger | 824-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 132.0 | VDC |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BCH001154 | Charger | 824-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 132.0 | VDC |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BCH001154 | Charger | 824-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BAT001213 | Battery | 824-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BAT001213 | Battery | 824-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BAT001213 | Battery | 824-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BAT001213 | Battery | 824-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BAT001213 | Battery | 824-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BAT001213 | Battery | 824-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BAT001213 | Battery | 824-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BAT001213 | Battery | 824-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BAT001213 | Battery | 824-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BAT001213 | Battery | 824-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BAT001213 | Battery | 824-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BAT001213 | Battery | 824-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BAT001213 | Battery | 824-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | BAT001213 | Battery | 824-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | CH000349 | ControlHouse | 824-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | CH000349 | ControlHouse | 824-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | CH000349 | ControlHouse | 824-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | CH000349 | ControlHouse | 824-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | CH000349 | ControlHouse | 824-Control House | Control House Patrol Inspection | General Comments | | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | CH000349 | ControlHouse | 824-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | CH000349 | ControlHouse | 824-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | CH000349 | ControlHouse | 824-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | CH000349 | ControlHouse | 824-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | CH000349 | ControlHouse | 824-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | CH000349 | ControlHouse | 824-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | CH000349 | ControlHouse | 824-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | CH000349 | ControlHouse | 824-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | CH000349 | ControlHouse | 824-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | CH000349 | ControlHouse | 824-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | CH000349 | ControlHouse | 824-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | CH000349 | ControlHouse | 824-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | CH000349 | ControlHouse | 824-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | CH000349 | ControlHouse | 824-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | ST000297 | Structure | 824-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | ST000297 | Structure | 824-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | ST000297 | Structure | 824-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | ST000297 | Structure | 824-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | ST000297 | Structure | 824-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | ST000297 | Structure | 824-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | ST000297 | Structure | 824-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | ST000297 | Structure | 824-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | ST000297 | Structure | 824-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | ST000297 | Structure | 824-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | ST000297 | Structure | 824-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | ST000297 | Structure | 824-Structure | Structure Patrol Inspection | General Comments | | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | ST000297 | Structure | 824-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | ST000297 | Structure | 824-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | ST000297 | Structure | 824-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | ST000297 | Structure | 824-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | ST000297 | Structure | 824-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | ST000297 | Structure | 824-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | ST000297 | Structure | 824-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | ST000297 | Structure | 824-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | FE000829 | Fence | 824-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | FE000829 | Fence | 824-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | FE000829 | Fence | 824-Fence | Fence Patrol Inspection | General Comments | | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | FE000829 | Fence | 824-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | FE000829 | Fence | 824-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | FE000829 | Fence | 824-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | FE000829 | Fence | 824-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | FE000829 | Fence | 824-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | FE000829 | Fence | 824-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | FE000829 | Fence | 824-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | FE000829 | Fence | 824-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | FE000829 | Fence | 824-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | FE000829 | Fence | 824-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | FE000829 | Fence | 824-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | FE000829 | Fence | 824-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | FE000829 | Fence | 824-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | YD000289 | Yard | 824-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | YD000289 | Yard | 824-Yard | Yard Patrol Inspection | General Comments | | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | YD000289 | Yard | 824-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | YD000289 | Yard | 824-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | YD000289 | Yard | 824-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | YD000289 | Yard | 824-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | YD000289 | Yard | 824-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | YD000289 | Yard | 824-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | YD000289 | Yard | 824-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | YD000289 | Yard | 824-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | YD000289 | Yard | 824-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | YD000289 | Yard | 824-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | YD000289 | Yard | 824-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/29/2023 7:28 | Distribution | Flemingsburg Quarterly Inspection | YD000289 | Yard | 824-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Readings | Unknown Operations | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Readings | Switching Operations | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Readings | Operations This Read Vac | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Readings | Operations Counter AL | 56 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Readings | Operations Counter AF | 56 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Readings | General Comments | | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Readings | Amps C Ø | 10.0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Readings | Amps B Ø | 30.0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Readings | Amps A Ø | 30.0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Readings | 9 Month Operations | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Readings | Operations This Read Vac | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Readings | Switching Operations | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Readings | Operations Counter AL | 317 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Readings | Operations Counter AF | 317 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Readings | General Comments | | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Readings | Unknown Operations | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Readings | Fault Operations Ground | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Readings | 9 Month Operations | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Readings | Amps C Ø | 45.0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Readings | Amps B Ø | 45.0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Readings | Amps A Ø | 45.0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Readings | General Comments | | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Readings | Operations Counter AF | 1010 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Readings | Operations Counter AL | 1010 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Readings | Operations This Read Vac | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Readings | Switching Operations | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Readings | Unknown Operations | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Readings | Amps C Ø | 50.0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Readings | Amps B Ø | 45.0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Readings | Amps A Ø | 15.0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0358 | BreakerVacuum | 696-0965 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0227 | BreakerVacuum | 696-0966 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Patrol Inspection | General Comments | | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BB0379 | BreakerVacuum | 696-0967 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Readings | Unknown Operations | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Readings | Switching Operations | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Readings | Operations This Read Oil | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Readings | Operations Counter AL | 1091 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Readings | Operations Counter AF | 1091 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Readings | Number of Ops last 9 Months | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Readings | 9 Months Operations OCB New | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Readings | Fault Operations | 0 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Readings | General Comments | | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | Air Compressor Belt Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | Air Compressor Oil Status | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | Air Leaks | None | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | Air Pressure OK? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | Air Tank Bleed (> 40°F)? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | AirCompressor Heater Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | Tank Leaks | None | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | Pressure Vessel Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | Pop-off Valve Tested Date | 2023-03-28 00:00:00.000000 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | General Comments | | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | TB0238 | BreakerOil | 696-708 | OCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | LTCC000636 | LTCControl | 930-Offline-Distribution | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | LTCC000636 | LTCControl | 930-Offline-Distribution | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | LTCC000636 | LTCControl | 930-Offline-Distribution | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | LTCC000636 | LTCControl | 930-Offline-Distribution | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | LTCC000636 | LTCControl | 930-Offline-Distribution | LTC Control Insp | LTC Operation Checked? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | LTCC000636 | LTCControl | 930-Offline-Distribution | LTC Control Insp | General Comments | | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | LTCC000636 | LTCControl | 930-Offline-Distribution | LTC Control Insp | Follow-up Action Required? | n | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | LTCC000636 | LTCControl | 930-Offline-Distribution | LTC Control Insp | All Connections OK? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | LTCM000098 | LTCMechanism | 696-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | LTCM000098 | LTCMechanism | 696-1 | LTC Counter Readings | General Comments | | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | LTCM000098 | LTCMechanism | 696-1 | LTC Counter Readings | LTC As Found Counter | 401 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | LTCM000098 | LTCMechanism | 696-1 | LTC Counter Readings | LTC As Left Counter | 401 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | LTCM000098 | LTCMechanism | 696-1 | LTC Counter Readings | LTC Current Tap Position | 1R | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | LTCM000098 | LTCMechanism | 696-1 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | LTCM000098 | LTCMechanism | 696-1 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | LTCM000098 | LTCMechanism | 696-1 | LTC Counter Readings | LTC Operations Since Last Insp | 200 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | LTCM000098 | LTCMechanism | 696-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | LTCM000098 | LTCMechanism | 696-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | LTCM000098 | LTCMechanism | 696-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | LTCM000098 | LTCMechanism | 696-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | LTCM000098 | LTCMechanism | 696-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | LTCM000098 | LTCMechanism | 696-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | LTCM000098 | LTCMechanism | 696-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | LTCM000098 | LTCMechanism | 696-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Readings | LTC Totalizer Reading | 4599.36 | kw |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Readings | Totalizer Meter Reading | .9582 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | B0365 | WithLTC | 696-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BAT001214 | Battery | 696-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BAT001214 | Battery | 696-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BAT001214 | Battery | 696-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BAT001214 | Battery | 696-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BAT001214 | Battery | 696-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BAT001214 | Battery | 696-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BAT001214 | Battery | 696-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BAT001214 | Battery | 696-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BAT001214 | Battery | 696-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BAT001214 | Battery | 696-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BAT001214 | Battery | 696-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BAT001214 | Battery | 696-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BAT001214 | Battery | 696-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BCH001570 | Charger | 696-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BCH001570 | Charger | 696-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BCH001570 | Charger | 696-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BCH001570 | Charger | 696-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BCH001570 | Charger | 696-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BCH001570 | Charger | 696-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 134.0 | VDC |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BCH001570 | Charger | 696-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 134.0 | VDC |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | BCH001570 | Charger | 696-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | CH000379 | ControlHouse | 696-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | CH000379 | ControlHouse | 696-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | CH000379 | ControlHouse | 696-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | CH000379 | ControlHouse | 696-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | CH000379 | ControlHouse | 696-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | CH000379 | ControlHouse | 696-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | CH000379 | ControlHouse | 696-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | CH000379 | ControlHouse | 696-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | CH000379 | ControlHouse | 696-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | CH000379 | ControlHouse | 696-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | CH000379 | ControlHouse | 696-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | CH000379 | ControlHouse | 696-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | CH000379 | ControlHouse | 696-Control House | Control House Patrol Inspection | General Comments | | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | CH000379 | ControlHouse | 696-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | CH000379 | ControlHouse | 696-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | CH000379 | ControlHouse | 696-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | CH000379 | ControlHouse | 696-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | CH000379 | ControlHouse | 696-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | CH000379 | ControlHouse | 696-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | ST000321 | Structure | 696-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | ST000321 | Structure | 696-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | ST000321 | Structure | 696-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | ST000321 | Structure | 696-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | ST000321 | Structure | 696-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | ST000321 | Structure | 696-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | ST000321 | Structure | 696-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | ST000321 | Structure | 696-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | ST000321 | Structure | 696-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | ST000321 | Structure | 696-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | ST000321 | Structure | 696-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | ST000321 | Structure | 696-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | ST000321 | Structure | 696-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | ST000321 | Structure | 696-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | ST000321 | Structure | 696-Structure | Structure Patrol Inspection | General Comments | | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | ST000321 | Structure | 696-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | ST000321 | Structure | 696-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | ST000321 | Structure | 696-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | ST000321 | Structure | 696-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | ST000321 | Structure | 696-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | ST000321 | Structure | 696-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | ST000321 | Structure | 696-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | FE000309 | Fence | 696-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | FE000309 | Fence | 696-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | FE000309 | Fence | 696-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | FE000309 | Fence | 696-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | FE000309 | Fence | 696-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | FE000309 | Fence | 696-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | FE000309 | Fence | 696-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | FE000309 | Fence | 696-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | FE000309 | Fence | 696-Fence | Fence Patrol Inspection | General Comments | | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | FE000309 | Fence | 696-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | FE000309 | Fence | 696-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | FE000309 | Fence | 696-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | FE000309 | Fence | 696-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | FE000309 | Fence | 696-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | FE000309 | Fence | 696-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | FE000309 | Fence | 696-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | YD000314 | Yard | 696-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | YD000314 | Yard | 696-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | YD000314 | Yard | 696-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | YD000314 | Yard | 696-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | YD000314 | Yard | 696-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | YD000314 | Yard | 696-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | YD000314 | Yard | 696-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | YD000314 | Yard | 696-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | YD000314 | Yard | 696-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | YD000314 | Yard | 696-Yard | Yard Patrol Inspection | Ambient Temp | 48 | °F |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | YD000314 | Yard | 696-Yard | Yard Patrol Inspection | General Comments | | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | YD000314 | Yard | 696-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | YD000314 | Yard | 696-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | YD000314 | Yard | 696-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/29/2023 7:13 | Distribution | Wedonia Quarterly Inspection | YD000314 | Yard | 696-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Readings | Follow-up Action Required? | n | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Readings | Fault Operations Ground | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Readings | Switching Operations | 2 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Readings | General Comments | | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Readings | Maintenance Operations | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Readings | Operations Counter AF | 168 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Readings | Operations Counter AL | 168 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Readings | Operations This Read Vac | 2 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Readings | Unknown Operations | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Readings | Amps C Ø | 58 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Readings | Amps B Ø | 58 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Readings | Amps A Ø | 55 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Readings | 9 Month Operations | 3 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Readings | Accumulated Fault Duty C Ph V | 1.87 | % |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Readings | Accumulated Fault Duty B Ph V | 2.34 | % |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Readings | Accumulated Fault Duty A Ph V | 3.27 | % |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Patrol Inspection | General Comments | | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001118 | BreakerVacuum | 636-2427 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Readings | Amps B Ø | 45 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Readings | Amps C Ø | 47 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Readings | Operations This Read Vac | 1 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Readings | Operations Counter AL | 162 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Readings | Amps A Ø | 48 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Readings | Operations Counter AF | 161 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Readings | Maintenance Operations | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Readings | General Comments | | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Readings | Follow-up Action Required? | n | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Readings | Fault Operations Ground | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Readings | 9 Month Operations | 1 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Readings | Switching Operations | 1 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Readings | Unknown Operations | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Patrol Inspection | General Comments | | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001119 | BreakerVacuum | 636-2425 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Readings | 9 Month Operations | 3 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Readings | Follow-up Action Required? | n | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Readings | Amps A Ø | 77 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Readings | Amps B Ø | 73 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Readings | Fault Operations Ground | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Readings | Unknown Operations | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Readings | Amps C Ø | 69 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Readings | Switching Operations | 3 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Readings | Operations This Read Vac | 3 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Readings | Operations Counter AL | 180 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Readings | Operations Counter AF | 180 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Readings | Maintenance Operations | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Readings | General Comments | | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Patrol Inspection | General Comments | | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BK001117 | BreakerVacuum | 636-2426 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Readings | 9 Month Operations | 1 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Readings | General Comments | | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Readings | Maintenance Operations | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Readings | Unknown Operations | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Readings | Switching Operations | 1 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Readings | Operations This Read Vac | 1 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Readings | Operations Counter AL | 176 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Readings | Follow-up Action Required? | n | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Readings | Fault Operations Ground | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Readings | Operations Counter AF | 175 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Readings | Accumulated Fault Duty A Ph V | .47 | % |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Readings | Accumulated Fault Duty B Ph V | .47 | % |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Readings | Amps A Ø | 292 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Readings | Amps B Ø | 276 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Readings | Amps C Ø | 271 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Patrol Inspection | General Comments | | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | KB0110 | BreakerVacuum | 636-2461 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Readings | Operations Counter AL | 226 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Readings | Operations Counter AF | 226 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Readings | General Comments | | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Readings | Amps C Ø | 480 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Readings | Amps B Ø | 480 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Readings | Amps A Ø | 480 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Readings | 9 Month Operations | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Readings | Switching Operations | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Readings | Unknown Operations | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Patrol Inspection | General Comments | | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | CB0213 | BreakerVacuum | 636-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | LTCC000697 | LTCControl | 636-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | LTCC000697 | LTCControl | 636-1 | LTC Control Insp | LTC Output Voltage Level | 124.7 | VAC |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | LTCC000697 | LTCControl | 636-1 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | LTCC000697 | LTCControl | 636-1 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | LTCC000697 | LTCControl | 636-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | LTCC000697 | LTCControl | 636-1 | LTC Control Insp | General Comments | | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | LTCC000697 | LTCControl | 636-1 | LTC Control Insp | All Connections OK? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | LTCC000697 | LTCControl | 636-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | LTCM000024 | LTCMechanism | 636-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | LTCM000024 | LTCMechanism | 636-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | LTCM000024 | LTCMechanism | 636-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | LTCM000024 | LTCMechanism | 636-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | LTCM000024 | LTCMechanism | 636-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | LTCM000024 | LTCMechanism | 636-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | LTCM000024 | LTCMechanism | 636-1 | LTC Counter Readings | General Comments | | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | LTCM000024 | LTCMechanism | 636-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | LTCM000024 | LTCMechanism | 636-1 | LTC Counter Readings | LTC As Found Counter | 24545 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | LTCM000024 | LTCMechanism | 636-1 | LTC Counter Readings | LTC As Left Counter | 24547 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | LTCM000024 | LTCMechanism | 636-1 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | LTCM000024 | LTCMechanism | 636-1 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | LTCM000024 | LTCMechanism | 636-1 | LTC Counter Readings | LTC Min Tap Position | 15L | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | LTCM000024 | LTCMechanism | 636-1 | LTC Counter Readings | LTC Operations Since Last Insp | 400 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | LTCM000024 | LTCMechanism | 636-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Readings | General Comments | | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Readings | Winding Temp Present | 55 | °C |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Readings | Winding Temp Max | 55 | °C |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Readings | Totalizer Meter Reading | .605 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Readings | LTC Totalizer Reading | 10890 | kw |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 4 | psi |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | C0500 | WithLTC | 636-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BAT001070 | Battery | 636-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BAT001070 | Battery | 636-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BAT001070 | Battery | 636-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BAT001070 | Battery | 636-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BAT001070 | Battery | 636-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BAT001070 | Battery | 636-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BAT001070 | Battery | 636-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BAT001070 | Battery | 636-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BAT001070 | Battery | 636-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BAT001070 | Battery | 636-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BAT001070 | Battery | 636-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BAT001070 | Battery | 636-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BAT001070 | Battery | 636-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.2 | VDC |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BAT001070 | Battery | 636-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.3 | VDC |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BAT001070 | Battery | 636-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BCH001257 | Charger | 636-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0 | millivolts |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BCH001257 | Charger | 636-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BCH001257 | Charger | 636-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BCH001257 | Charger | 636-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.1 | amps |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BCH001257 | Charger | 636-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | BCH001257 | Charger | 636-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | ST000566 | Structure | 636-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | ST000566 | Structure | 636-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | ST000566 | Structure | 636-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | ST000566 | Structure | 636-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | ST000566 | Structure | 636-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | ST000566 | Structure | 636-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | ST000566 | Structure | 636-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | ST000566 | Structure | 636-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | ST000566 | Structure | 636-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | ST000566 | Structure | 636-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | ST000566 | Structure | 636-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | ST000566 | Structure | 636-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | ST000566 | Structure | 636-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | ST000566 | Structure | 636-Structure | Structure Patrol Inspection | General Comments | | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | ST000566 | Structure | 636-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | ST000566 | Structure | 636-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | ST000566 | Structure | 636-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | ST000566 | Structure | 636-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | ST000566 | Structure | 636-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | ST000566 | Structure | 636-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | ST000566 | Structure | 636-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | ST000566 | Structure | 636-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | FE000556 | Fence | 636-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | FE000556 | Fence | 636-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | FE000556 | Fence | 636-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | FE000556 | Fence | 636-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | FE000556 | Fence | 636-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | FE000556 | Fence | 636-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | FE000556 | Fence | 636-Fence | Fence Patrol Inspection | General Comments | | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | FE000556 | Fence | 636-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | FE000556 | Fence | 636-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | FE000556 | Fence | 636-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | FE000556 | Fence | 636-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | FE000556 | Fence | 636-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | FE000556 | Fence | 636-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | FE000556 | Fence | 636-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | FE000556 | Fence | 636-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | FE000556 | Fence | 636-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | YD000562 | Yard | 636-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | YD000562 | Yard | 636-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | YD000562 | Yard | 636-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | YD000562 | Yard | 636-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | YD000562 | Yard | 636-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | YD000562 | Yard | 636-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | YD000562 | Yard | 636-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | YD000562 | Yard | 636-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | YD000562 | Yard | 636-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | YD000562 | Yard | 636-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | YD000562 | Yard | 636-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | YD000562 | Yard | 636-Yard | Yard Patrol Inspection | General Comments | | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | YD000562 | Yard | 636-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | YD000562 | Yard | 636-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | YD000562 | Yard | 636-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/28/2023 14:38 | Distribution | Elizabethtown West Quarterly Inspection | YD000562 | Yard | 636-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Readings | Unknown Operations | 0 | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Readings | Switching Operations | 0 | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Readings | 9 Month Operations | 13 | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Readings | Accumulated Fault Duty A Ph V | 2.13 | % |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Readings | Accumulated Fault Duty B Ph V | 7.12 | % |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Readings | Accumulated Fault Duty C Ph V | 1.42 | % |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Readings | Amps A Ø | 55.0 | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Readings | Amps B Ø | 64.0 | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Readings | Amps C Ø | 64.0 | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Readings | Operations This Read Vac | 9 | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Readings | Operations Counter AL | 249 | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Readings | Operations Counter AF | 249 | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Readings | Fault Adjusted Amps C Phase V | 85.91 | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Readings | Fault Operations C Ø | 9 | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Readings | Fault Operations Ground | 0 | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Readings | Follow-up Action Required? | n | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Readings | General Comments | | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Readings | Maintenance Operations | 0 | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | LTCMechanism | WP-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | LTCMechanism | WP-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | LTCMechanism | WP-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 171825 | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | LTCMechanism | WP-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 171825 | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | LTCMechanism | WP-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | LTCMechanism | WP-TRANS 1 | LTC Counter Readings | General Comments | | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | LTCMechanism | WP-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | LTCMechanism | WP-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 683 | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | LTCMechanism | WP-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | LTCMechanism | WP-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | LTCMechanism | WP-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | LTCMechanism | WP-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | LTCMechanism | WP-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | LTCMechanism | WP-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | LTCMechanism | WP-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | LTCMechanism | WP-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PN71 | WithLTC | WP-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BCH001018 | Charger | WP-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BCH001018 | Charger | WP-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BCH001018 | Charger | WP-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BCH001018 | Charger | WP-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BCH001018 | Charger | WP-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BCH001018 | Charger | WP-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BCH001018 | Charger | WP-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BAT001326 | Battery | Retired Distribution | Battery Patrol Inspection | All Connections OK? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BAT001326 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BAT001326 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Bank Amps | .5 | AMPS |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BAT001326 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Bank Volts | 53.5 | VDC |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BAT001326 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BAT001326 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BAT001326 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BAT001326 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BAT001326 | Battery | Retired Distribution | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BAT001326 | Battery | Retired Distribution | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BAT001326 | Battery | Retired Distribution | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BAT001326 | Battery | Retired Distribution | Battery Patrol Inspection | General Comments | | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BAT001326 | Battery | Retired Distribution | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BAT001326 | Battery | Retired Distribution | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BAT001326 | Battery | Retired Distribution | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BAT001326 | Battery | Retired Distribution | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PF001197 | PowerFuse | WP-33KV TR 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PF001197 | PowerFuse | WP-33KV TR 1 | Disconnect Powerfuse Inspection | General Comments | oki | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | YD000608 | Yard | WP-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | YD000608 | Yard | WP-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | YD000608 | Yard | WP-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | YD000608 | Yard | WP-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | YD000608 | Yard | WP-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | YD000608 | Yard | WP-Yard | Yard Patrol Inspection | General Comments | | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | YD000608 | Yard | WP-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | YD000608 | Yard | WP-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | YD000608 | Yard | WP-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | YD000608 | Yard | WP-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | YD000608 | Yard | WP-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | YD000608 | Yard | WP-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | YD000608 | Yard | WP-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | YD000608 | Yard | WP-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | YD000608 | Yard | WP-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | FE000605 | Fence | WP-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | FE000605 | Fence | WP-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | FE000605 | Fence | WP-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | FE000605 | Fence | WP-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | FE000605 | Fence | WP-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | FE000605 | Fence | WP-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | FE000605 | Fence | WP-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | FE000605 | Fence | WP-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | FE000605 | Fence | WP-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | FE000605 | Fence | WP-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | FE000605 | Fence | WP-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | FE000605 | Fence | WP-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | FE000605 | Fence | WP-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | FE000605 | Fence | WP-Fence | Fence Patrol Inspection | General Comments | | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | FE000605 | Fence | WP-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | FE000605 | Fence | WP-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PF001255 | PowerFuse | WP-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | PF001255 | PowerFuse | WP-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Patrol Inspection | General Comments | | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/28/2023 14:20 | Distribution | West Point Quarterly Inspection | BK001430 | BreakerVacuum | WP-1104 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | LTCMechanism | MU-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | LTCMechanism | MU-TRANS 1 | LTC Counter Readings | General Comments | | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | LTCMechanism | MU-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 217232 | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | LTCMechanism | MU-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 217232 | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | LTCMechanism | MU-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | LTCMechanism | MU-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | LTCMechanism | MU-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | LTCMechanism | MU-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 138 | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | LTCMechanism | MU-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | LTCMechanism | MU-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | LTCMechanism | MU-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | LTCMechanism | MU-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | LTCMechanism | MU-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | LTCMechanism | MU-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | LTCMechanism | MU-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | LTCMechanism | MU-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .2 | psi |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 28 | °C |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | LT0135 | WithLTC | MU-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | PF000254 | PowerFuse | MU-33KV TR 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | PF000254 | PowerFuse | MU-33KV TR 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | YD000591 | Yard | MU-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | YD000591 | Yard | MU-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | YD000591 | Yard | MU-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | YD000591 | Yard | MU-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | YD000591 | Yard | MU-Yard | Yard Patrol Inspection | General Comments | | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | YD000591 | Yard | MU-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | YD000591 | Yard | MU-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | YD000591 | Yard | MU-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | YD000591 | Yard | MU-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | YD000591 | Yard | MU-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | YD000591 | Yard | MU-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | YD000591 | Yard | MU-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | YD000591 | Yard | MU-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | YD000591 | Yard | MU-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | YD000591 | Yard | MU-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | FE000585 | Fence | MU-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | FE000585 | Fence | MU-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | FE000585 | Fence | MU-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | FE000585 | Fence | MU-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | FE000585 | Fence | MU-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | FE000585 | Fence | MU-Fence | Fence Patrol Inspection | General Comments | | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | FE000585 | Fence | MU-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | FE000585 | Fence | MU-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | FE000585 | Fence | MU-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | FE000585 | Fence | MU-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | FE000585 | Fence | MU-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | FE000585 | Fence | MU-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | FE000585 | Fence | MU-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | FE000585 | Fence | MU-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | FE000585 | Fence | MU-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | FE000585 | Fence | MU-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | ST000862 | Structure | MU-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | ST000862 | Structure | MU-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | ST000862 | Structure | MU-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | ST000862 | Structure | MU-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | ST000862 | Structure | MU-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | ST000862 | Structure | MU-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | ST000862 | Structure | MU-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | ST000862 | Structure | MU-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | ST000862 | Structure | MU-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | ST000862 | Structure | MU-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | ST000862 | Structure | MU-Structure | Structure Patrol Inspection | General Comments | | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | ST000862 | Structure | MU-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | ST000862 | Structure | MU-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | ST000862 | Structure | MU-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | ST000862 | Structure | MU-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | ST000862 | Structure | MU-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | ST000862 | Structure | MU-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/28/2023 14:21 | Distribution | Muldraugh Quarterly Inspection | ST000862 | Structure | MU-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Patrol Inspection | General Comments | | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Readings | Follow-up Action Required? | n | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Readings | General Comments | | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Readings | Maintenance Operations | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Readings | Operations Counter AF | 190 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Readings | Operations Counter AL | 190 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Readings | Operations This Read Vac | 1 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Readings | Switching Operations | 1 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Readings | Unknown Operations | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Readings | Fault Operations Ground | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Readings | 9 Month Operations | 4 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Readings | Amps A Ø | 148 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Readings | Amps B Ø | 152 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Readings | Amps C Ø | 161 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001116 | BreakerVacuum | 811-2417 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Patrol Inspection | General Comments | | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Readings | Operations Counter AL | 156 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Readings | Operations This Read Vac | 1 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Readings | Switching Operations | 1 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Readings | Unknown Operations | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Readings | Amps B Ø | 108 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Readings | Amps A Ø | 97 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Readings | Accumulated Fault Duty C Ph V | .46 | % |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Readings | Accumulated Fault Duty B Ph V | .46 | % |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Readings | Accumulated Fault Duty A Ph V | .46 | % |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Readings | 9 Month Operations | 4 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Readings | Amps C Ø | 101 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Readings | Operations Counter AF | 155 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Readings | Fault Operations Ground | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Readings | Follow-up Action Required? | n | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Readings | General Comments | | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK001115 | BreakerVacuum | 811-2418 | VCB Readings | Maintenance Operations | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Patrol Inspection | General Comments | | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Readings | Fault Operations Ground | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Readings | Follow-up Action Required? | n | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Readings | General Comments | | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Readings | Maintenance Operations | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Readings | Operations Counter AF | 200 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Readings | Operations Counter AL | 200 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Readings | Operations This Read Vac | 3 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Readings | Switching Operations | 3 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Readings | Unknown Operations | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Readings | 9 Month Operations | 6 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Readings | Accumulated Fault Duty A Ph V | 7.77 | % |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Readings | Amps A Ø | 165 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Readings | Amps B Ø | 151 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Readings | Amps C Ø | 127 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK000845 | BreakerVacuum | 811-2420 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Patrol Inspection | General Comments | | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Readings | Amps C Ø | 62 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Readings | Amps B Ø | 77 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Readings | Amps A Ø | 74 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Readings | Accumulated Fault Duty C Ph V | 1.83 | % |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Readings | Accumulated Fault Duty B Ph V | 2.28 | % |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Readings | Accumulated Fault Duty A Ph V | 3.2 | % |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Readings | 9 Month Operations | 4 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Readings | Unknown Operations | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Readings | Fault Operations Ground | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Readings | Follow-up Action Required? | n | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Readings | General Comments | | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Readings | Operations Counter AF | 190 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Readings | Operations Counter AL | 191 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Readings | Operations This Read Vac | 1 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | KB0127 | BreakerVacuum | 811-2419 | VCB Readings | Switching Operations | 1 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Patrol Inspection | General Comments | | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Readings | Amps C Ø | 432 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Readings | Operations Counter AF | 174 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Readings | Operations Counter AL | 174 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Readings | General Comments | | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Readings | Switching Operations | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Readings | Unknown Operations | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Readings | Amps B Ø | 419 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Readings | Amps A Ø | 467 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Readings | 9 Month Operations VCB New | 18 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BK002039 | BreakerVacuum | 811-1 | VCB Readings | 9 Month Operations | 18 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | LTCMechanism | 811-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | LTCMechanism | 811-1 | LTC Counter Readings | General Comments | | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | LTCMechanism | 811-1 | LTC Counter Readings | LTC As Found Counter | 3141 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | LTCMechanism | 811-1 | LTC Counter Readings | LTC As Left Counter | 3143 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | LTCMechanism | 811-1 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | LTCMechanism | 811-1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | LTCMechanism | 811-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | LTCMechanism | 811-1 | LTC Counter Readings | LTC Operations Since Last Insp | 252 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | LTCMechanism | 811-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | LTCC000926 | LTCControl | 811-1 | LTC Control Insp | LTC Output Voltage Level | 124.8 | VAC |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | LTCC000926 | LTCControl | 811-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | LTCC000926 | LTCControl | 811-1 | LTC Control Insp | General Comments | | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | LTCC000926 | LTCControl | 811-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | LTCC000926 | LTCControl | 811-1 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | LTCC000926 | LTCControl | 811-1 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | LTCC000926 | LTCControl | 811-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | LTCC000926 | LTCControl | 811-1 | LTC Control Insp | All Connections OK? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | LTCMechanism | 811-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | LTCMechanism | 811-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | LTCMechanism | 811-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | LTCMechanism | 811-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | LTCMechanism | 811-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | LTCMechanism | 811-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | LTCMechanism | 811-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Readings | Totalizer Meter Reading | .8802 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Readings | LTC Totalizer Reading | 15843.6 | kw |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Readings | General Comments | | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | C0461 | WithLTC | 811-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BAT001386 | Battery | 811-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BAT001386 | Battery | 811-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BAT001386 | Battery | 811-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BAT001386 | Battery | 811-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BAT001386 | Battery | 811-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BAT001386 | Battery | 811-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BAT001386 | Battery | 811-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BAT001386 | Battery | 811-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BAT001386 | Battery | 811-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BAT001386 | Battery | 811-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26 | VDC |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BAT001386 | Battery | 811-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.2 | VDC |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BAT001386 | Battery | 811-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BAT001386 | Battery | 811-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BAT001386 | Battery | 811-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BCH001254 | Charger | 811-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BCH001254 | Charger | 811-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BCH001254 | Charger | 811-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BCH001254 | Charger | 811-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BCH001254 | Charger | 811-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.5 | amps |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BCH001254 | Charger | 811-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BCH001254 | Charger | 811-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | BCH001254 | Charger | 811-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0 | millivolts |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | ST000560 | Structure | 811-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | ST000560 | Structure | 811-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | ST000560 | Structure | 811-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | ST000560 | Structure | 811-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | ST000560 | Structure | 811-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | ST000560 | Structure | 811-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | ST000560 | Structure | 811-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | ST000560 | Structure | 811-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | ST000560 | Structure | 811-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | ST000560 | Structure | 811-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | ST000560 | Structure | 811-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | ST000560 | Structure | 811-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | ST000560 | Structure | 811-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | ST000560 | Structure | 811-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | ST000560 | Structure | 811-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | ST000560 | Structure | 811-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | ST000560 | Structure | 811-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | ST000560 | Structure | 811-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | ST000560 | Structure | 811-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | ST000560 | Structure | 811-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | ST000560 | Structure | 811-Structure | Structure Patrol Inspection | General Comments | | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | ST000560 | Structure | 811-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | FE000521 | Fence | 811-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | FE000521 | Fence | 811-Fence | Fence Patrol Inspection | General Comments | | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | FE000521 | Fence | 811-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | FE000521 | Fence | 811-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | FE000521 | Fence | 811-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | FE000521 | Fence | 811-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | FE000521 | Fence | 811-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | FE000521 | Fence | 811-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | FE000521 | Fence | 811-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | FE000521 | Fence | 811-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | FE000521 | Fence | 811-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | FE000521 | Fence | 811-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | FE000521 | Fence | 811-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | FE000521 | Fence | 811-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | FE000521 | Fence | 811-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | FE000521 | Fence | 811-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | YD000556 | Yard | 811-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | YD000556 | Yard | 811-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | YD000556 | Yard | 811-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | YD000556 | Yard | 811-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | YD000556 | Yard | 811-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | YD000556 | Yard | 811-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | YD000556 | Yard | 811-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | YD000556 | Yard | 811-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | YD000556 | Yard | 811-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | YD000556 | Yard | 811-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | YD000556 | Yard | 811-Yard | Yard Patrol Inspection | General Comments | | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | YD000556 | Yard | 811-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | YD000556 | Yard | 811-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | YD000556 | Yard | 811-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/28/2023 12:37 | Distribution | Elizabethtown 4 Quarterly Inspection | YD000556 | Yard | 811-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | LTCMechanism | SS-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 4433 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | LTCMechanism | SS-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 4433 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | LTCMechanism | SS-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 12 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | LTCMechanism | SS-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 13 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | LTCMechanism | SS-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 9 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | LTCMechanism | SS-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | LTCMechanism | SS-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | LTCMechanism | SS-TRANS 1 | LTC Counter Readings | General Comments | | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | LTCMechanism | SS-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 333 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | LTCMechanism | SS-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | LTCMechanism | SS-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | LTCMechanism | SS-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | LTCMechanism | SS-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | LTCMechanism | SS-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | LTCMechanism | SS-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | WithLTC | SS-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | WithLTC | SS-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | WithLTC | SS-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | WithLTC | SS-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | WithLTC | SS-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | WithLTC | SS-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | WithLTC | SS-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | WithLTC | SS-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | WithLTC | SS-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | WithLTC | SS-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | WithLTC | SS-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | WithLTC | SS-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | WithLTC | SS-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | WithLTC | SS-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | WithLTC | SS-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | WithLTC | SS-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | WithLTC | SS-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | WithLTC | SS-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | WithLTC | SS-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | WithLTC | SS-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | WithLTC | SS-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | WithLTC | SS-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | WithLTC | SS-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | WithLTC | SS-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | WithLTC | SS-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PN28 | WithLTC | SS-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | SWG000097 | Switchgear | SS-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | SWG000097 | Switchgear | SS-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | SWG000097 | Switchgear | SS-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | SWG000097 | Switchgear | SS-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | SWG000097 | Switchgear | SS-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | SWG000097 | Switchgear | SS-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | SWG000097 | Switchgear | SS-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | SWG000097 | Switchgear | SS-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | SWG000097 | Switchgear | SS-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | SWG000097 | Switchgear | SS-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | SWG000097 | Switchgear | SS-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | SWG000097 | Switchgear | SS-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | SWG000097 | Switchgear | SS-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | SWG000097 | Switchgear | SS-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | SWG000097 | Switchgear | SS-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | SWG000097 | Switchgear | SS-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0885 | BreakerAirMagnetic | SS-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0885 | BreakerAirMagnetic | SS-3 | AMCB Patrol Inspection | General Comments | | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0885 | BreakerAirMagnetic | SS-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0885 | BreakerAirMagnetic | SS-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0885 | BreakerAirMagnetic | SS-3 | AMCB Readings | Unknown Operations | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0885 | BreakerAirMagnetic | SS-3 | AMCB Readings | Switching Operations | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0885 | BreakerAirMagnetic | SS-3 | AMCB Readings | Operations This Read AM | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0885 | BreakerAirMagnetic | SS-3 | AMCB Readings | Operations Counter AL | 295 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0885 | BreakerAirMagnetic | SS-3 | AMCB Readings | Operations Counter AF | 295 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0885 | BreakerAirMagnetic | SS-3 | AMCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0885 | BreakerAirMagnetic | SS-3 | AMCB Readings | General Comments | | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0885 | BreakerAirMagnetic | SS-3 | AMCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0885 | BreakerAirMagnetic | SS-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0885 | BreakerAirMagnetic | SS-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0885 | BreakerAirMagnetic | SS-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0885 | BreakerAirMagnetic | SS-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0885 | BreakerAirMagnetic | SS-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0885 | BreakerAirMagnetic | SS-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0885 | BreakerAirMagnetic | SS-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0885 | BreakerAirMagnetic | SS-3 | AMCB Readings | Amps C Ø | 110.0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0885 | BreakerAirMagnetic | SS-3 | AMCB Readings | Amps B Ø | 100.0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0885 | BreakerAirMagnetic | SS-3 | AMCB Readings | Amps A Ø | 50.0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0885 | BreakerAirMagnetic | SS-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0885 | BreakerAirMagnetic | SS-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0885 | BreakerAirMagnetic | SS-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0885 | BreakerAirMagnetic | SS-3 | AMCB Readings | 9 Months Operations | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0885 | BreakerAirMagnetic | SS-3 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0884 | BreakerAirMagnetic | SS-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0884 | BreakerAirMagnetic | SS-2 | AMCB Patrol Inspection | General Comments | | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0884 | BreakerAirMagnetic | SS-2 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0884 | BreakerAirMagnetic | SS-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0884 | BreakerAirMagnetic | SS-2 | AMCB Readings | Unknown Operations | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0884 | BreakerAirMagnetic | SS-2 | AMCB Readings | Switching Operations | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0884 | BreakerAirMagnetic | SS-2 | AMCB Readings | Operations This Read AM | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0884 | BreakerAirMagnetic | SS-2 | AMCB Readings | Operations Counter AL | 254 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0884 | BreakerAirMagnetic | SS-2 | AMCB Readings | Operations Counter AF | 254 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0884 | BreakerAirMagnetic | SS-2 | AMCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0884 | BreakerAirMagnetic | SS-2 | AMCB Readings | General Comments | | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0884 | BreakerAirMagnetic | SS-2 | AMCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0884 | BreakerAirMagnetic | SS-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0884 | BreakerAirMagnetic | SS-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0884 | BreakerAirMagnetic | SS-2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0884 | BreakerAirMagnetic | SS-2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0884 | BreakerAirMagnetic | SS-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0884 | BreakerAirMagnetic | SS-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0884 | BreakerAirMagnetic | SS-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0884 | BreakerAirMagnetic | SS-2 | AMCB Readings | Amps C Ø | 150.0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0884 | BreakerAirMagnetic | SS-2 | AMCB Readings | Amps B Ø | 140.0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0884 | BreakerAirMagnetic | SS-2 | AMCB Readings | Amps A Ø | 180.0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0884 | BreakerAirMagnetic | SS-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0884 | BreakerAirMagnetic | SS-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0884 | BreakerAirMagnetic | SS-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0884 | BreakerAirMagnetic | SS-2 | AMCB Readings | 9 Months Operations | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0884 | BreakerAirMagnetic | SS-2 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0887 | BreakerAirMagnetic | SS-1 SPARE | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0887 | BreakerAirMagnetic | SS-1 SPARE | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0887 | BreakerAirMagnetic | SS-1 SPARE | AMCB Patrol Inspection | General Comments | | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0887 | BreakerAirMagnetic | SS-1 SPARE | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0887 | BreakerAirMagnetic | SS-1 SPARE | AMCB Readings | Maintenance Operations | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0887 | BreakerAirMagnetic | SS-1 SPARE | AMCB Readings | General Comments | | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0887 | BreakerAirMagnetic | SS-1 SPARE | AMCB Readings | Follow-up Action Required? | n | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0887 | BreakerAirMagnetic | SS-1 SPARE | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0887 | BreakerAirMagnetic | SS-1 SPARE | AMCB Readings | Fault Operations Ground | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0887 | BreakerAirMagnetic | SS-1 SPARE | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0887 | BreakerAirMagnetic | SS-1 SPARE | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0887 | BreakerAirMagnetic | SS-1 SPARE | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0887 | BreakerAirMagnetic | SS-1 SPARE | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0887 | BreakerAirMagnetic | SS-1 SPARE | AMCB Readings | Amps A Ø | 0.0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0887 | BreakerAirMagnetic | SS-1 SPARE | AMCB Readings | Amps B Ø | 0.0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0887 | BreakerAirMagnetic | SS-1 SPARE | AMCB Readings | Amps C Ø | 0.0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0887 | BreakerAirMagnetic | SS-1 SPARE | AMCB Readings | Unknown Operations | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0887 | BreakerAirMagnetic | SS-1 SPARE | AMCB Readings | Switching Operations | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0887 | BreakerAirMagnetic | SS-1 SPARE | AMCB Readings | Operations This Read AM | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0887 | BreakerAirMagnetic | SS-1 SPARE | AMCB Readings | Operations Counter AL | 325 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0887 | BreakerAirMagnetic | SS-1 SPARE | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0887 | BreakerAirMagnetic | SS-1 SPARE | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0887 | BreakerAirMagnetic | SS-1 SPARE | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0887 | BreakerAirMagnetic | SS-1 SPARE | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0887 | BreakerAirMagnetic | SS-1 SPARE | AMCB Readings | Operations Counter AF | 325 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0887 | BreakerAirMagnetic | SS-1 SPARE | AMCB Readings | 9 Months Operations | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | LB0887 | BreakerAirMagnetic | SS-1 SPARE | AMCB Readings | 9 Month Ops New | 0 | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | BAT001434 | Battery | SS-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | BAT001434 | Battery | SS-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | BAT001434 | Battery | SS-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | BAT001434 | Battery | SS-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | BAT001434 | Battery | SS-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | BAT001434 | Battery | SS-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | BAT001434 | Battery | SS-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | BAT001434 | Battery | SS-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | BAT001434 | Battery | SS-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | BAT001434 | Battery | SS-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | BAT001434 | Battery | SS-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | BAT001434 | Battery | SS-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | BAT001434 | Battery | SS-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | BAT001434 | Battery | SS-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | CH000461 | ControlHouse | SS-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | CH000461 | ControlHouse | SS-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | CH000461 | ControlHouse | SS-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | CH000461 | ControlHouse | SS-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | CH000461 | ControlHouse | SS-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | CH000461 | ControlHouse | SS-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | CH000461 | ControlHouse | SS-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | CH000461 | ControlHouse | SS-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | YD000575 | Yard | SS-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | YD000575 | Yard | SS-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | YD000575 | Yard | SS-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | YD000575 | Yard | SS-Yard | Yard Patrol Inspection | Ambient Temp | 39 | °F |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | YD000575 | Yard | SS-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | YD000575 | Yard | SS-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | YD000575 | Yard | SS-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | YD000575 | Yard | SS-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | YD000575 | Yard | SS-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | YD000575 | Yard | SS-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | YD000575 | Yard | SS-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | YD000575 | Yard | SS-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | YD000575 | Yard | SS-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | YD000575 | Yard | SS-Yard | Yard Patrol Inspection | General Comments | | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | YD000575 | Yard | SS-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | YD000575 | Yard | SS-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | YD000575 | Yard | SS-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | YD000575 | Yard | SS-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | FE000565 | Fence | SS-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | FE000565 | Fence | SS-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | FE000565 | Fence | SS-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | FE000565 | Fence | SS-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | FE000565 | Fence | SS-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | FE000565 | Fence | SS-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | FE000565 | Fence | SS-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | FE000565 | Fence | SS-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | FE000565 | Fence | SS-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | FE000565 | Fence | SS-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | FE000565 | Fence | SS-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | FE000565 | Fence | SS-Fence | Fence Patrol Inspection | General Comments | | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | FE000565 | Fence | SS-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | FE000565 | Fence | SS-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | FE000565 | Fence | SS-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | FE000565 | Fence | SS-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | BCH001337 | Charger | SS-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.6 | VDC |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | BCH001337 | Charger | SS-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.6 | VDC |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | BCH001337 | Charger | SS-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | BCH001337 | Charger | SS-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | BCH001337 | Charger | SS-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | BCH001337 | Charger | SS-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PF001344 | PowerFuse | SS-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/29/2023 16:08 | Distribution | Southern Baptist Seminary Quarterly Inspection | PF001344 | PowerFuse | SS-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Readings | Operations Counter AL | 337 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Readings | Operations Counter AF | 337 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Readings | Amps C Ø | 38.0 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Readings | Amps B Ø | 38.0 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Readings | Unknown Operations | 0 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Readings | Switching Operations | 0 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Readings | Operations This Read Vac | 0 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Readings | Amps A Ø | 20.0 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Readings | Accumulated Fault Duty C Ph V | 9.51 | % |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Readings | Operations Counter AL | 484 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Readings | Operations This Read Vac | 0 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Readings | Switching Operations | 0 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Readings | Unknown Operations | 0 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Readings | Maintenance Operations | 0 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Readings | General Comments | | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Readings | 9 Month Operations | 1 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Readings | Accumulated Fault Duty A Ph V | 7.31 | % |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Readings | 9 Month Operations | 1 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Readings | Accumulated Fault Duty A Ph V | 29.25 | % |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Readings | Accumulated Fault Duty B Ph V | 26.33 | % |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Readings | Accumulated Fault Duty C Ph V | 19.75 | % |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Readings | Amps A Ø | 176.0 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Readings | Amps B Ø | 223.0 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Readings | Amps C Ø | 183.0 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Readings | Operations Counter AF | 484 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Readings | Maintenance Operations | 0 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Readings | Fault Operations Ground | 0 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Readings | Accumulated Fault Duty B Ph V | 9.51 | % |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Readings | General Comments | | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Readings | Follow-up Action Required? | n | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Readings | Fault Operations Ground | 0 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Readings | Follow-up Action Required? | n | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Readings | Unknown Operations | 0 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Readings | 9 Month Operations | 7 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Readings | Amps A Ø | 100.0 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Readings | Switching Operations | 1 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Readings | Operations This Read Vac | 4 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Readings | Operations Counter AL | 291 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Readings | Fault Operations Ground | 0 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Readings | Follow-up Action Required? | n | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Readings | General Comments | | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Readings | Maintenance Operations | 3 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Readings | Operations Counter AF | 287 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Readings | Amps B Ø | 101.0 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Readings | Amps C Ø | 100.0 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Patrol Inspection | General Comments | | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0032 | BreakerVacuum | 569-0881 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Readings | 9 Month Operations | 5 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Readings | General Comments | | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Readings | Maintenance Operations | 3 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Readings | Operations Counter AF | 243 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Readings | Operations Counter AL | 247 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Readings | Operations This Read Vac | 4 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Readings | Switching Operations | 1 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Readings | Unknown Operations | 0 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Readings | Follow-up Action Required? | n | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Readings | Fault Operations Ground | 0 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Readings | Amps A Ø | 30.0 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Readings | Amps B Ø | 30.0 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Readings | Amps C Ø | 30.0 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Patrol Inspection | General Comments | | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | K0045 | BreakerVacuum | 569-0880 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | LTCMechanism | 569-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | LTCMechanism | 569-1 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | LTCMechanism | 569-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | LTCMechanism | 569-1 | LTC Counter Readings | LTC Operations Since Last Insp | 443 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | LTCMechanism | 569-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | LTCMechanism | 569-1 | LTC Counter Readings | General Comments | | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | LTCMechanism | 569-1 | LTC Counter Readings | LTC As Found Counter | 78596 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | LTCMechanism | 569-1 | LTC Counter Readings | LTC As Left Counter | 78596 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | LTCMechanism | 569-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | LTCC000769 | LTCControl | 569-1 | LTC Control Insp | General Comments | | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | LTCC000769 | LTCControl | 569-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | LTCC000769 | LTCControl | 569-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | LTCC000769 | LTCControl | 569-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | LTCC000769 | LTCControl | 569-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | LTCC000769 | LTCControl | 569-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | LTCC000769 | LTCControl | 569-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | LTCC000769 | LTCControl | 569-1 | LTC Control Insp | All Connections OK? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | LTCMechanism | 569-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | LTCMechanism | 569-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | LTCMechanism | 569-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | LTCMechanism | 569-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | LTCMechanism | 569-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | LTCMechanism | 569-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Readings | General Comments | | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Readings | LTC Totalizer Reading | 3763.20 | kw |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Readings | Totalizer Meter Reading | .3920 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | B0416 | WithLTC | 569-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | BCH001560 | Charger | 569-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | BCH001560 | Charger | 569-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | BCH001560 | Charger | 569-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | BCH001560 | Charger | 569-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | BCH001560 | Charger | 569-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .3 | amps |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | BCH001560 | Charger | 569-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | BCH001560 | Charger | 569-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | BCH001560 | Charger | 569-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | BAT001172 | Battery | 569-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | BAT001172 | Battery | 569-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | BAT001172 | Battery | 569-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | BAT001172 | Battery | 569-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | BAT001172 | Battery | 569-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | BAT001172 | Battery | 569-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | BAT001172 | Battery | 569-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | BAT001172 | Battery | 569-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | BAT001172 | Battery | 569-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 55 | °F |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | BAT001172 | Battery | 569-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | BAT001172 | Battery | 569-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | BAT001172 | Battery | 569-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | BAT001172 | Battery | 569-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | BAT001172 | Battery | 569-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | BAT001172 | Battery | 569-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | ST000314 | Structure | 569-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | ST000314 | Structure | 569-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | ST000314 | Structure | 569-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | ST000314 | Structure | 569-Structure | Structure Patrol Inspection | General Comments | | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | ST000314 | Structure | 569-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | ST000314 | Structure | 569-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | ST000314 | Structure | 569-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | ST000314 | Structure | 569-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | ST000314 | Structure | 569-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | ST000314 | Structure | 569-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | ST000314 | Structure | 569-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | ST000314 | Structure | 569-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | ST000314 | Structure | 569-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | ST000314 | Structure | 569-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | ST000314 | Structure | 569-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | ST000314 | Structure | 569-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | ST000314 | Structure | 569-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | ST000314 | Structure | 569-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | ST000314 | Structure | 569-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | ST000314 | Structure | 569-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | ST000314 | Structure | 569-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | ST000314 | Structure | 569-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | FE000303 | Fence | 569-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | FE000303 | Fence | 569-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | FE000303 | Fence | 569-Fence | Fence Patrol Inspection | General Comments | | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | FE000303 | Fence | 569-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | FE000303 | Fence | 569-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | FE000303 | Fence | 569-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | FE000303 | Fence | 569-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | FE000303 | Fence | 569-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | FE000303 | Fence | 569-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | FE000303 | Fence | 569-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | FE000303 | Fence | 569-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | FE000303 | Fence | 569-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | FE000303 | Fence | 569-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | FE000303 | Fence | 569-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | FE000303 | Fence | 569-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | FE000303 | Fence | 569-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | YD000307 | Yard | 569-Yard | Yard Patrol Inspection | General Comments | | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | YD000307 | Yard | 569-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | YD000307 | Yard | 569-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | YD000307 | Yard | 569-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | YD000307 | Yard | 569-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | YD000307 | Yard | 569-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | YD000307 | Yard | 569-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | YD000307 | Yard | 569-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | YD000307 | Yard | 569-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | YD000307 | Yard | 569-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | YD000307 | Yard | 569-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | YD000307 | Yard | 569-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | YD000307 | Yard | 569-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 3/28/2023 7:08 | Distribution | Cynthiana South Quarterly Inspection | YD000307 | Yard | 569-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Readings | 9 Month Operations | 2 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Readings | Unknown Operations | 0 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Readings | Switching Operations | 2 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Readings | Operations This Read Vac | 2 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Readings | Operations Counter AL | 187 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Readings | Operations Counter AF | 185 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Readings | Fault Operations Ground | 0 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Readings | Amps C Ø | 4.0 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Readings | Amps B Ø | 4.0 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Readings | Amps A Ø | 5.0 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Readings | Maintenance Operations | 0 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Readings | General Comments | | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Readings | Follow-up Action Required? | n | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Patrol Inspection | General Comments | | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BK001802 | BreakerVacuum | 885-0857 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Readings | Operations This Read Vac | 4 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Readings | Operations Counter AL | 278 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Readings | Operations Counter AF | 274 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Readings | Amps A Ø | 120.0 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Readings | Amps B Ø | 120.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Readings | Amps C Ø | 180.0 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Readings | 9 Month Operations | 4 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Readings | Maintenance Operations | 0 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Readings | Switching Operations | 4 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Readings | Unknown Operations | 0 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Readings | General Comments | | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Readings | Fault Operations Ground | 0 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Readings | Follow-up Action Required? | n | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Patrol Inspection | General Comments | | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BB0295 | BreakerVacuum | 885-0856 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | LTCMechanism | 885-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | LTCMechanism | 885-1 | LTC Counter Readings | General Comments | | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | LTCMechanism | 885-1 | LTC Counter Readings | LTC As Found Counter | 23973 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | LTCMechanism | 885-1 | LTC Counter Readings | LTC As Left Counter | 23973 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | LTCMechanism | 885-1 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | LTCMechanism | 885-1 | LTC Counter Readings | LTC Max Tap Position | 5L | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | LTCMechanism | 885-1 | LTC Counter Readings | LTC Min Tap Position | 15L | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | LTCMechanism | 885-1 | LTC Counter Readings | LTC Operations Since Last Insp | 173 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | LTCMechanism | 885-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | LTCC000841 | LTCControl | 885-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | LTCC000841 | LTCControl | 885-1 | LTC Control Insp | All Connections OK? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | LTCC000841 | LTCControl | 885-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | LTCC000841 | LTCControl | 885-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | LTCC000841 | LTCControl | 885-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | LTCC000841 | LTCControl | 885-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | LTCC000841 | LTCControl | 885-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | LTCC000841 | LTCControl | 885-1 | LTC Control Insp | General Comments | | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | LTCMechanism | 885-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | LTCMechanism | 885-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | LTCMechanism | 885-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | LTCMechanism | 885-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | LTCMechanism | 885-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | LTCMechanism | 885-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | LTCMechanism | 885-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Readings | Totalizer Meter Reading | .3804 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Readings | LTC Totalizer Reading | 2738.88 | kw |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Readings | General Comments | | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | B0322 | WithLTC | 885-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BCH001040 | Charger | 885-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BCH001040 | Charger | 885-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BCH001040 | Charger | 885-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BCH001040 | Charger | 885-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BCH001040 | Charger | 885-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .4 | amps |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BCH001040 | Charger | 885-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BCH001040 | Charger | 885-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BCH001040 | Charger | 885-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BAT001173 | Battery | 885-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BAT001173 | Battery | 885-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BAT001173 | Battery | 885-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BAT001173 | Battery | 885-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 55 | °F |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BAT001173 | Battery | 885-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BAT001173 | Battery | 885-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BAT001173 | Battery | 885-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BAT001173 | Battery | 885-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BAT001173 | Battery | 885-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BAT001173 | Battery | 885-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BAT001173 | Battery | 885-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BAT001173 | Battery | 885-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BAT001173 | Battery | 885-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | BAT001173 | Battery | 885-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | ST000316 | Structure | 885-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | ST000316 | Structure | 885-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | ST000316 | Structure | 885-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | ST000316 | Structure | 885-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | ST000316 | Structure | 885-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | ST000316 | Structure | 885-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | ST000316 | Structure | 885-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | ST000316 | Structure | 885-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | ST000316 | Structure | 885-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | ST000316 | Structure | 885-Structure | Structure Patrol Inspection | General Comments | | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | ST000316 | Structure | 885-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | ST000316 | Structure | 885-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | ST000316 | Structure | 885-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | ST000316 | Structure | 885-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | ST000316 | Structure | 885-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | ST000316 | Structure | 885-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | ST000316 | Structure | 885-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | ST000316 | Structure | 885-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | ST000316 | Structure | 885-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | ST000316 | Structure | 885-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | ST000316 | Structure | 885-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | ST000316 | Structure | 885-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | FE000305 | Fence | 885-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | FE000305 | Fence | 885-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | FE000305 | Fence | 885-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | FE000305 | Fence | 885-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | FE000305 | Fence | 885-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | FE000305 | Fence | 885-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | FE000305 | Fence | 885-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | FE000305 | Fence | 885-Fence | Fence Patrol Inspection | General Comments | | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | FE000305 | Fence | 885-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | FE000305 | Fence | 885-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | FE000305 | Fence | 885-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | FE000305 | Fence | 885-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | FE000305 | Fence | 885-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | FE000305 | Fence | 885-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | FE000305 | Fence | 885-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | FE000305 | Fence | 885-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | YD000309 | Yard | 885-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | YD000309 | Yard | 885-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | YD000309 | Yard | 885-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | YD000309 | Yard | 885-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | YD000309 | Yard | 885-Yard | Yard Patrol Inspection | General Comments | | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | YD000309 | Yard | 885-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | YD000309 | Yard | 885-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | YD000309 | Yard | 885-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | YD000309 | Yard | 885-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | YD000309 | Yard | 885-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | YD000309 | Yard | 885-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | YD000309 | Yard | 885-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | YD000309 | Yard | 885-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | YD000309 | Yard | 885-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/27/2023 15:16 | Distribution | Kawneer Quarterly Inspection | YD000309 | Yard | 885-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Patrol Inspection | General Comments | | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Readings | Amps C Ø | 250.0 | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Readings | Amps B Ø | 305.0 | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Readings | Unknown Operations | 0 | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Readings | Switching Operations | 2 | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Readings | Operations This Read Vac | 3 | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Readings | Operations Counter AL | 178 | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Readings | Operations Counter AF | 176 | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Readings | Maintenance Operations | 0 | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Readings | Amps A Ø | 241.0 | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Readings | General Comments | | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Readings | Follow-up Action Required? | n | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Readings | Fault Operations Ground | 0 | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Readings | Fault Operations C Ø | 1 | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Readings | Fault Adjusted Amps C Phase V | 8.76 | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Readings | 9 Month Operations | 3 | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BK001548 | BreakerVacuum | 796-0796 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000008 | Regulator | 796-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000008 | Regulator | 796-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000008 | Regulator | 796-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000008 | Regulator | 796-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000008 | Regulator | 796-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000008 | Regulator | 796-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000008 | Regulator | 796-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000008 | Regulator | 796-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000008 | Regulator | 796-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000008 | Regulator | 796-1 C | Regulator Patrol Inspection | General Comments | | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000008 | Regulator | 796-1 C | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000008 | Regulator | 796-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000008 | Regulator | 796-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000008 | Regulator | 796-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000008 | Regulator | 796-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000008 | Regulator | 796-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000008 | Regulator | 796-1 C | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000008 | Regulator | 796-1 C | Regulator Patrol Inspection | Min Tap Position | 4L | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000008 | Regulator | 796-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000008 | Regulator | 796-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000008 | Regulator | 796-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000008 | Regulator | 796-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000008 | Regulator | 796-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 22985 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000007 | Regulator | 796-1 B | Regulator Patrol Inspection | Current Tap Position | 4R | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000007 | Regulator | 796-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000007 | Regulator | 796-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000007 | Regulator | 796-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000007 | Regulator | 796-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000007 | Regulator | 796-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000007 | Regulator | 796-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000007 | Regulator | 796-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000007 | Regulator | 796-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000007 | Regulator | 796-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000007 | Regulator | 796-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 27452 | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000007 | Regulator | 796-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000007 | Regulator | 796-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000007 | Regulator | 796-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000007 | Regulator | 796-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000007 | Regulator | 796-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000007 | Regulator | 796-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000007 | Regulator | 796-1 B | Regulator Patrol Inspection | Min Tap Position | 4L | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000007 | Regulator | 796-1 B | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000007 | Regulator | 796-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000007 | Regulator | 796-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000007 | Regulator | 796-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000007 | Regulator | 796-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000006 | Regulator | 796-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000006 | Regulator | 796-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000006 | Regulator | 796-1 A | Regulator Patrol Inspection | General Comments | | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000006 | Regulator | 796-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000006 | Regulator | 796-1 A | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000006 | Regulator | 796-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000006 | Regulator | 796-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000006 | Regulator | 796-1 A | Regulator Patrol Inspection | Max Tap Position | 13R | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000006 | Regulator | 796-1 A | Regulator Patrol Inspection | Min Tap Position | 4L | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000006 | Regulator | 796-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000006 | Regulator | 796-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000006 | Regulator | 796-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000006 | Regulator | 796-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000006 | Regulator | 796-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000006 | Regulator | 796-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 25223 | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000006 | Regulator | 796-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000006 | Regulator | 796-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000006 | Regulator | 796-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000006 | Regulator | 796-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000006 | Regulator | 796-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000006 | Regulator | 796-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000006 | Regulator | 796-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | RG000006 | Regulator | 796-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Readings | General Comments | | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 5632.00 | kw |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.7600 | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | 0982 | NonLTC | 796-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BAT001587 | Battery | 796-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BAT001587 | Battery | 796-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BAT001587 | Battery | 796-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BAT001587 | Battery | 796-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BAT001587 | Battery | 796-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BAT001587 | Battery | 796-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BAT001587 | Battery | 796-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BAT001587 | Battery | 796-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BAT001587 | Battery | 796-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BAT001587 | Battery | 796-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BAT001587 | Battery | 796-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BAT001587 | Battery | 796-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 62 | °F |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | ST000371 | Structure | 796-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | ST000371 | Structure | 796-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | ST000371 | Structure | 796-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | ST000371 | Structure | 796-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | ST000371 | Structure | 796-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | ST000371 | Structure | 796-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | ST000371 | Structure | 796-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | ST000371 | Structure | 796-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | ST000371 | Structure | 796-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | ST000371 | Structure | 796-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | ST000371 | Structure | 796-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | ST000371 | Structure | 796-Structure | Structure Patrol Inspection | General Comments | | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | ST000371 | Structure | 796-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | ST000371 | Structure | 796-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | ST000371 | Structure | 796-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | ST000371 | Structure | 796-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | ST000371 | Structure | 796-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | ST000371 | Structure | 796-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | ST000371 | Structure | 796-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | ST000371 | Structure | 796-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | ST000371 | Structure | 796-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | ST000371 | Structure | 796-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | FE000363 | Fence | 796-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | FE000363 | Fence | 796-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | FE000363 | Fence | 796-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | FE000363 | Fence | 796-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | FE000363 | Fence | 796-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | FE000363 | Fence | 796-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | FE000363 | Fence | 796-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | FE000363 | Fence | 796-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | FE000363 | Fence | 796-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | FE000363 | Fence | 796-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | FE000363 | Fence | 796-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | FE000363 | Fence | 796-Fence | Fence Patrol Inspection | General Comments | | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | FE000363 | Fence | 796-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | FE000363 | Fence | 796-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | FE000363 | Fence | 796-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | FE000363 | Fence | 796-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | YD000369 | Yard | 796-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | YD000369 | Yard | 796-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | YD000369 | Yard | 796-Yard | Yard Patrol Inspection | General Comments | | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | YD000369 | Yard | 796-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | YD000369 | Yard | 796-Yard | Yard Patrol Inspection | Ambient Temp | 62 | °F |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | YD000369 | Yard | 796-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | YD000369 | Yard | 796-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | YD000369 | Yard | 796-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | YD000369 | Yard | 796-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | YD000369 | Yard | 796-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | YD000369 | Yard | 796-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | YD000369 | Yard | 796-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | YD000369 | Yard | 796-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | YD000369 | Yard | 796-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BCH000522 | Charger | 796-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BCH000522 | Charger | 796-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BCH000522 | Charger | 796-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BCH000522 | Charger | 796-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .6 | amps |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BCH000522 | Charger | 796-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 3/27/2023 13:29 | Distribution | Falmouth Quarterly Inspection | BCH000522 | Charger | 796-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0307 | RecloserElectronic | 751-0527 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0307 | RecloserElectronic | 751-0527 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0307 | RecloserElectronic | 751-0527 | Recloser Electronic Patrol Inspection | Amps A Ø | 17.0 | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0307 | RecloserElectronic | 751-0527 | Recloser Electronic Patrol Inspection | Amps B Ø | 21.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0307 | RecloserElectronic | 751-0527 | Recloser Electronic Patrol Inspection | Amps C Ø | 20.0 | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0307 | RecloserElectronic | 751-0527 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0307 | RecloserElectronic | 751-0527 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0307 | RecloserElectronic | 751-0527 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0307 | RecloserElectronic | 751-0527 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0307 | RecloserElectronic | 751-0527 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0307 | RecloserElectronic | 751-0527 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0307 | RecloserElectronic | 751-0527 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0307 | RecloserElectronic | 751-0527 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0307 | RecloserElectronic | 751-0527 | Recloser Electronic Patrol Inspection | Operations Counter | 54 | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0307 | RecloserElectronic | 751-0527 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0307 | RecloserElectronic | 751-0527 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0307 | RecloserElectronic | 751-0527 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0307 | RecloserElectronic | 751-0527 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0306 | RecloserElectronic | 751-0528 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0306 | RecloserElectronic | 751-0528 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0306 | RecloserElectronic | 751-0528 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0306 | RecloserElectronic | 751-0528 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0306 | RecloserElectronic | 751-0528 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0306 | RecloserElectronic | 751-0528 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0306 | RecloserElectronic | 751-0528 | Recloser Electronic Patrol Inspection | Operations Counter | 75 | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0306 | RecloserElectronic | 751-0528 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0306 | RecloserElectronic | 751-0528 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0306 | RecloserElectronic | 751-0528 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0306 | RecloserElectronic | 751-0528 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0306 | RecloserElectronic | 751-0528 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0306 | RecloserElectronic | 751-0528 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0306 | RecloserElectronic | 751-0528 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0306 | RecloserElectronic | 751-0528 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0306 | RecloserElectronic | 751-0528 | Recloser Electronic Patrol Inspection | Amps C Ø | 27.0 | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0306 | RecloserElectronic | 751-0528 | Recloser Electronic Patrol Inspection | Amps B Ø | 29.0 | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | X0306 | RecloserElectronic | 751-0528 | Recloser Electronic Patrol Inspection | Amps A Ø | 41.0 | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1499 | Regulator | 751-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1499 | Regulator | 751-1 C | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1499 | Regulator | 751-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1499 | Regulator | 751-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1499 | Regulator | 751-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1499 | Regulator | 751-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1499 | Regulator | 751-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1499 | Regulator | 751-1 C | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1499 | Regulator | 751-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1499 | Regulator | 751-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1499 | Regulator | 751-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1499 | Regulator | 751-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1499 | Regulator | 751-1 C | Regulator Patrol Inspection | General Comments | | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1499 | Regulator | 751-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1499 | Regulator | 751-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1499 | Regulator | 751-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1499 | Regulator | 751-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1499 | Regulator | 751-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1499 | Regulator | 751-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1499 | Regulator | 751-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 55102 | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1499 | Regulator | 751-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1499 | Regulator | 751-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1499 | Regulator | 751-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1498 | Regulator | 751-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1498 | Regulator | 751-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1498 | Regulator | 751-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1498 | Regulator | 751-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1498 | Regulator | 751-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1498 | Regulator | 751-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1498 | Regulator | 751-1 B | Regulator Patrol Inspection | Max Tap Position | 9R | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1498 | Regulator | 751-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1498 | Regulator | 751-1 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1498 | Regulator | 751-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1498 | Regulator | 751-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1498 | Regulator | 751-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1498 | Regulator | 751-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1498 | Regulator | 751-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1498 | Regulator | 751-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1498 | Regulator | 751-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1498 | Regulator | 751-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 61187 | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1498 | Regulator | 751-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1498 | Regulator | 751-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1498 | Regulator | 751-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1498 | Regulator | 751-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1498 | Regulator | 751-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1498 | Regulator | 751-1 B | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1497 | Regulator | 751-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1497 | Regulator | 751-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 63242 | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1497 | Regulator | 751-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1497 | Regulator | 751-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1497 | Regulator | 751-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1497 | Regulator | 751-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1497 | Regulator | 751-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1497 | Regulator | 751-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1497 | Regulator | 751-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1497 | Regulator | 751-1 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1497 | Regulator | 751-1 A | Regulator Patrol Inspection | Max Tap Position | 11R | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1497 | Regulator | 751-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1497 | Regulator | 751-1 A | Regulator Patrol Inspection | General Comments | | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1497 | Regulator | 751-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1497 | Regulator | 751-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1497 | Regulator | 751-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1497 | Regulator | 751-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1497 | Regulator | 751-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1497 | Regulator | 751-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1497 | Regulator | 751-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1497 | Regulator | 751-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1497 | Regulator | 751-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | R1497 | Regulator | 751-1 A | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Readings | General Comments | | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1855.20 | kw |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Readings | Winding Temp Present | 36 | °C |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Readings | Winding Temp Max | 40 | °C |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .7730 | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Readings | Oil Temp Present | 45 | °C |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | S0058 | NonLTC | 751-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | CH000479 | ControlHouse | 751-Control House | Control House Patrol Inspection | Floor Swept? | n | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | CH000479 | ControlHouse | 751-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | CH000479 | ControlHouse | 751-Control House | Control House Patrol Inspection | Broom on Site? | n | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | CH000479 | ControlHouse | 751-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | CH000479 | ControlHouse | 751-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | CH000479 | ControlHouse | 751-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | CH000479 | ControlHouse | 751-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | CH000479 | ControlHouse | 751-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | CH000479 | ControlHouse | 751-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | CH000479 | ControlHouse | 751-Control House | Control House Patrol Inspection | General Comments | | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | CH000479 | ControlHouse | 751-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | CH000479 | ControlHouse | 751-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | CH000479 | ControlHouse | 751-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | CH000479 | ControlHouse | 751-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | CH000479 | ControlHouse | 751-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | CH000479 | ControlHouse | 751-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | CH000479 | ControlHouse | 751-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | ST000017 | Structure | 751-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | ST000017 | Structure | 751-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | ST000017 | Structure | 751-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | ST000017 | Structure | 751-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | ST000017 | Structure | 751-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | ST000017 | Structure | 751-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | ST000017 | Structure | 751-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | ST000017 | Structure | 751-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | ST000017 | Structure | 751-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | ST000017 | Structure | 751-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | ST000017 | Structure | 751-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | ST000017 | Structure | 751-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | ST000017 | Structure | 751-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | ST000017 | Structure | 751-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | ST000017 | Structure | 751-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | ST000017 | Structure | 751-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | ST000017 | Structure | 751-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | ST000017 | Structure | 751-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | ST000017 | Structure | 751-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | ST000017 | Structure | 751-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | ST000017 | Structure | 751-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | ST000017 | Structure | 751-Structure | Structure Patrol Inspection | General Comments | | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | FE000023 | Fence | 751-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | FE000023 | Fence | 751-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | FE000023 | Fence | 751-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | FE000023 | Fence | 751-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | FE000023 | Fence | 751-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | n | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | FE000023 | Fence | 751-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | FE000023 | Fence | 751-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | FE000023 | Fence | 751-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | FE000023 | Fence | 751-Fence | Fence Patrol Inspection | General Comments | | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | FE000023 | Fence | 751-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | FE000023 | Fence | 751-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | FE000023 | Fence | 751-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | FE000023 | Fence | 751-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | n | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | FE000023 | Fence | 751-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | FE000023 | Fence | 751-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | FE000023 | Fence | 751-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | YD000018 | Yard | 751-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | YD000018 | Yard | 751-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | YD000018 | Yard | 751-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | YD000018 | Yard | 751-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | YD000018 | Yard | 751-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | YD000018 | Yard | 751-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | YD000018 | Yard | 751-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | YD000018 | Yard | 751-Yard | Yard Patrol Inspection | Ambient Temp | 64 | °F |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | YD000018 | Yard | 751-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | YD000018 | Yard | 751-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | YD000018 | Yard | 751-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | YD000018 | Yard | 751-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | YD000018 | Yard | 751-Yard | Yard Patrol Inspection | General Comments | | |
| 3/27/2023 13:20 | Distribution | Science Hill Quarterly Inspection | YD000018 | Yard | 751-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0324 | RecloserElectronic | 573-0547 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0324 | RecloserElectronic | 573-0547 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0324 | RecloserElectronic | 573-0547 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0324 | RecloserElectronic | 573-0547 | Recloser Electronic Patrol Inspection | Operations Counter | 32 | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0324 | RecloserElectronic | 573-0547 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0324 | RecloserElectronic | 573-0547 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0324 | RecloserElectronic | 573-0547 | Recloser Electronic Patrol Inspection | General Comments | 27.3/25 | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0324 | RecloserElectronic | 573-0547 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0324 | RecloserElectronic | 573-0547 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0324 | RecloserElectronic | 573-0547 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0324 | RecloserElectronic | 573-0547 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0324 | RecloserElectronic | 573-0547 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0324 | RecloserElectronic | 573-0547 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0324 | RecloserElectronic | 573-0547 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0324 | RecloserElectronic | 573-0547 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0324 | RecloserElectronic | 573-0547 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0324 | RecloserElectronic | 573-0547 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0324 | RecloserElectronic | 573-0547 | Recloser Electronic Patrol Inspection | Amps C Ø | 16.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0324 | RecloserElectronic | 573-0547 | Recloser Electronic Patrol Inspection | Amps B Ø | 26.0 | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0324 | RecloserElectronic | 573-0547 | Recloser Electronic Patrol Inspection | Amps A Ø | 22.0 | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0304 | RecloserElectronic | 573-0546 | Recloser Electronic Patrol Inspection | Amps A Ø | 36.0 | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0304 | RecloserElectronic | 573-0546 | Recloser Electronic Patrol Inspection | Amps B Ø | 28.0 | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0304 | RecloserElectronic | 573-0546 | Recloser Electronic Patrol Inspection | Amps C Ø | 38.0 | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0304 | RecloserElectronic | 573-0546 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0304 | RecloserElectronic | 573-0546 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0304 | RecloserElectronic | 573-0546 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0304 | RecloserElectronic | 573-0546 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0304 | RecloserElectronic | 573-0546 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0304 | RecloserElectronic | 573-0546 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0304 | RecloserElectronic | 573-0546 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0304 | RecloserElectronic | 573-0546 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0304 | RecloserElectronic | 573-0546 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0304 | RecloserElectronic | 573-0546 | Recloser Electronic Patrol Inspection | Operations Counter | 54 | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0304 | RecloserElectronic | 573-0546 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0304 | RecloserElectronic | 573-0546 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0304 | RecloserElectronic | 573-0546 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0304 | RecloserElectronic | 573-0546 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0304 | RecloserElectronic | 573-0546 | Recloser Electronic Patrol Inspection | General Comments | 26.9/24.7 | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0304 | RecloserElectronic | 573-0546 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | MX0304 | RecloserElectronic | 573-0546 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1441 | Regulator | 573-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1441 | Regulator | 573-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1441 | Regulator | 573-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1441 | Regulator | 573-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 79353 | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1441 | Regulator | 573-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1441 | Regulator | 573-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1441 | Regulator | 573-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1441 | Regulator | 573-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1441 | Regulator | 573-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1441 | Regulator | 573-1 C | Regulator Patrol Inspection | Min Tap Position | 13L | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1441 | Regulator | 573-1 C | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1441 | Regulator | 573-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1441 | Regulator | 573-1 C | Regulator Patrol Inspection | General Comments | | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1441 | Regulator | 573-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1441 | Regulator | 573-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1441 | Regulator | 573-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1441 | Regulator | 573-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1441 | Regulator | 573-1 C | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1441 | Regulator | 573-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1441 | Regulator | 573-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1441 | Regulator | 573-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1441 | Regulator | 573-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1441 | Regulator | 573-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1440 | Regulator | 573-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1440 | Regulator | 573-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1440 | Regulator | 573-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1440 | Regulator | 573-1 B | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1440 | Regulator | 573-1 B | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1440 | Regulator | 573-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1440 | Regulator | 573-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1440 | Regulator | 573-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1440 | Regulator | 573-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1440 | Regulator | 573-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1440 | Regulator | 573-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1440 | Regulator | 573-1 B | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1440 | Regulator | 573-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1440 | Regulator | 573-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1440 | Regulator | 573-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1440 | Regulator | 573-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1440 | Regulator | 573-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1440 | Regulator | 573-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1440 | Regulator | 573-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1440 | Regulator | 573-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1440 | Regulator | 573-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1440 | Regulator | 573-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.8 | volts |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R1440 | Regulator | 573-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 71512 | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R0867 | Regulator | 573-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R0867 | Regulator | 573-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R0867 | Regulator | 573-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R0867 | Regulator | 573-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R0867 | Regulator | 573-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R0867 | Regulator | 573-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R0867 | Regulator | 573-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R0867 | Regulator | 573-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 150940 | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R0867 | Regulator | 573-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R0867 | Regulator | 573-1 A | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R0867 | Regulator | 573-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.7 | volts |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R0867 | Regulator | 573-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R0867 | Regulator | 573-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R0867 | Regulator | 573-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R0867 | Regulator | 573-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R0867 | Regulator | 573-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R0867 | Regulator | 573-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R0867 | Regulator | 573-1 A | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R0867 | Regulator | 573-1 A | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R0867 | Regulator | 573-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R0867 | Regulator | 573-1 A | Regulator Patrol Inspection | General Comments | | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R0867 | Regulator | 573-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | R0867 | Regulator | 573-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Readings | Winding Temp Present | 29 | °C |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Readings | Winding Temp Max | 33 | °C |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.5546 | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Readings | Oil Temp Present | 29 | °C |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3731.04 | kw |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Readings | General Comments | | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | S0059 | NonLTC | 573-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | ST000021 | Structure | 573-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | ST000021 | Structure | 573-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | ST000021 | Structure | 573-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | ST000021 | Structure | 573-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | ST000021 | Structure | 573-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | ST000021 | Structure | 573-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | ST000021 | Structure | 573-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | ST000021 | Structure | 573-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | ST000021 | Structure | 573-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | ST000021 | Structure | 573-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | ST000021 | Structure | 573-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | ST000021 | Structure | 573-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | ST000021 | Structure | 573-Structure | Structure Patrol Inspection | General Comments | | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | ST000021 | Structure | 573-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | ST000021 | Structure | 573-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | ST000021 | Structure | 573-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | ST000021 | Structure | 573-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | ST000021 | Structure | 573-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | ST000021 | Structure | 573-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | ST000021 | Structure | 573-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | ST000021 | Structure | 573-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | ST000021 | Structure | 573-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | FE000027 | Fence | 573-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | FE000027 | Fence | 573-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | FE000027 | Fence | 573-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | FE000027 | Fence | 573-Fence | Fence Patrol Inspection | General Comments | fence fabric and posts rustY | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | FE000027 | Fence | 573-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | FE000027 | Fence | 573-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | FE000027 | Fence | 573-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | FE000027 | Fence | 573-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | n | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | FE000027 | Fence | 573-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | FE000027 | Fence | 573-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | FE000027 | Fence | 573-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | FE000027 | Fence | 573-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | FE000027 | Fence | 573-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | FE000027 | Fence | 573-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | FE000027 | Fence | 573-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | n | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | FE000027 | Fence | 573-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | n | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | YD000022 | Yard | 573-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | YD000022 | Yard | 573-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | YD000022 | Yard | 573-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | YD000022 | Yard | 573-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | YD000022 | Yard | 573-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | YD000022 | Yard | 573-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | YD000022 | Yard | 573-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | YD000022 | Yard | 573-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | YD000022 | Yard | 573-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | YD000022 | Yard | 573-Yard | Yard Patrol Inspection | General Comments | heavy vegitation on and through fence. | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | YD000022 | Yard | 573-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/27/2023 12:24 | Distribution | Waynesburg Quarterly Inspection | YD000022 | Yard | 573-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Patrol Inspection | General Comments | | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0160 | BreakerVacuum | 537-0534 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Patrol Inspection | General Comments | | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | MB0159 | BreakerVacuum | 537-0533 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | LTCC000847 | LTCControl | 537-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | LTCC000847 | LTCControl | 537-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | LTCC000847 | LTCControl | 537-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | LTCC000847 | LTCControl | 537-1 | LTC Control Insp | LTC Output Voltage Level | 123.6 | VAC |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | LTCC000847 | LTCControl | 537-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | LTCC000847 | LTCControl | 537-1 | LTC Control Insp | General Comments | | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | LTCC000847 | LTCControl | 537-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | LTCC000847 | LTCControl | 537-1 | LTC Control Insp | All Connections OK? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | LTCMechanism | 537-1 | LTC Counter Readings | LTC Min Tap Position | 5R | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | LTCMechanism | 537-1 | LTC Counter Readings | LTC Operations Since Last Insp | 683 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | LTCMechanism | 537-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | LTCMechanism | 537-1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | LTCMechanism | 537-1 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | LTCMechanism | 537-1 | LTC Counter Readings | LTC As Left Counter | 15188 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | LTCMechanism | 537-1 | LTC Counter Readings | LTC As Found Counter | 15177 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | LTCMechanism | 537-1 | LTC Counter Readings | General Comments | | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | LTCMechanism | 537-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | LTCMechanism | 537-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | LTCMechanism | 537-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | LTCMechanism | 537-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | LTCMechanism | 537-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | LTCMechanism | 537-1 | LTC Mechanism Patrol Inspection | General Comments | has dessicant filter | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | LTCMechanism | 537-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.0824 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Readings | LTC Totalizer Reading | 10391.04 | kw |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | M0099 | WithLTC | 537-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | BCH001353 | Charger | 537-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | BCH001353 | Charger | 537-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | BCH001353 | Charger | 537-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | BCH001353 | Charger | 537-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | BCH001353 | Charger | 537-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .9 | amps |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | BCH001353 | Charger | 537-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.3 | VDC |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | BCH001353 | Charger | 537-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.3 | VDC |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | BCH001353 | Charger | 537-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.360 | millivolts |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | CH000399 | ControlHouse | 537-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | CH000399 | ControlHouse | 537-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | CH000399 | ControlHouse | 537-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | CH000399 | ControlHouse | 537-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | CH000399 | ControlHouse | 537-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | CH000399 | ControlHouse | 537-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | CH000399 | ControlHouse | 537-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | CH000399 | ControlHouse | 537-Control House | Control House Patrol Inspection | Filters Condition OK? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | CH000399 | ControlHouse | 537-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | CH000399 | ControlHouse | 537-Control House | Control House Patrol Inspection | Floor Swept? | n | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | CH000399 | ControlHouse | 537-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | CH000399 | ControlHouse | 537-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | CH000399 | ControlHouse | 537-Control House | Control House Patrol Inspection | General Comments | | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | CH000399 | ControlHouse | 537-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | CH000399 | ControlHouse | 537-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | CH000399 | ControlHouse | 537-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | CH000399 | ControlHouse | 537-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | BAT001060 | Battery | 537-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | BAT001060 | Battery | 537-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | BAT001060 | Battery | 537-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | BAT001060 | Battery | 537-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | BAT001060 | Battery | 537-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | BAT001060 | Battery | 537-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | BAT001060 | Battery | 537-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | BAT001060 | Battery | 537-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Exp/Missing Not Repl | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | BAT001060 | Battery | 537-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | BAT001060 | Battery | 537-Battery Bank | Battery Patrol Inspection | General Comments | turned heater down | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | BAT001060 | Battery | 537-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.0 | VDC |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | BAT001060 | Battery | 537-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | BAT001060 | Battery | 537-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | BAT001060 | Battery | 537-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 85 | °F |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | BAT001060 | Battery | 537-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | ST000080 | Structure | 537-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | ST000080 | Structure | 537-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | ST000080 | Structure | 537-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | ST000080 | Structure | 537-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | ST000080 | Structure | 537-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | ST000080 | Structure | 537-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | ST000080 | Structure | 537-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | ST000080 | Structure | 537-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | ST000080 | Structure | 537-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | ST000080 | Structure | 537-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | ST000080 | Structure | 537-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | ST000080 | Structure | 537-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | ST000080 | Structure | 537-Structure | Structure Patrol Inspection | General Comments | | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | ST000080 | Structure | 537-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | ST000080 | Structure | 537-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | ST000080 | Structure | 537-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | ST000080 | Structure | 537-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | ST000080 | Structure | 537-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | ST000080 | Structure | 537-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | ST000080 | Structure | 537-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | ST000080 | Structure | 537-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | ST000080 | Structure | 537-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | FE000072 | Fence | 537-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | FE000072 | Fence | 537-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | FE000072 | Fence | 537-Fence | Fence Patrol Inspection | General Comments | | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | FE000072 | Fence | 537-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | FE000072 | Fence | 537-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | FE000072 | Fence | 537-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | FE000072 | Fence | 537-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | n | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | FE000072 | Fence | 537-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | FE000072 | Fence | 537-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | FE000072 | Fence | 537-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | FE000072 | Fence | 537-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | n | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | FE000072 | Fence | 537-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | FE000072 | Fence | 537-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | FE000072 | Fence | 537-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | FE000072 | Fence | 537-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | FE000072 | Fence | 537-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | YD000073 | Yard | 537-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | YD000073 | Yard | 537-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | YD000073 | Yard | 537-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | YD000073 | Yard | 537-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | n | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | YD000073 | Yard | 537-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | YD000073 | Yard | 537-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | YD000073 | Yard | 537-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | YD000073 | Yard | 537-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | YD000073 | Yard | 537-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | YD000073 | Yard | 537-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | YD000073 | Yard | 537-Yard | Yard Patrol Inspection | General Comments | spr is gone | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | YD000073 | Yard | 537-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | YD000073 | Yard | 537-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/28/2023 7:05 | Distribution | Waitsboro Quarterly Inspection | YD000073 | Yard | 537-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Readings | 9 Month Operations | 3 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Readings | Amps A Ø | 109.0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Readings | Amps B Ø | 118.0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Readings | Amps C Ø | 116.0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Readings | Fault Operations Ground | 0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Readings | Follow-up Action Required? | n | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Readings | General Comments | | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Readings | Maintenance Operations | 0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Readings | Operations Counter AF | 174 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Readings | Operations Counter AL | 174 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Readings | Operations This Read Vac | 0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Readings | Switching Operations | 0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Readings | Unknown Operations | 0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Patrol Inspection | General Comments | | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BK001445 | BreakerVacuum | 546-0543 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Readings | Amps B Ø | 70.0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Readings | Amps C Ø | 60.0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Readings | Amps A Ø | 57.0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Readings | Fault Operations Ground | 0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Readings | 9 Month Operations | 5 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Readings | Unknown Operations | 0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Readings | Switching Operations | 0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Readings | Operations This Read Vac | 0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Readings | Operations Counter AL | 277 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Readings | Operations Counter AF | 277 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Readings | Maintenance Operations | 0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Readings | General Comments | | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Readings | Follow-up Action Required? | n | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Patrol Inspection | General Comments | | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | MB0177 | BreakerVacuum | 546-0542 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Readings | Amps A Ø | 51.0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Readings | Amps B Ø | 34.0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Readings | Operations Counter AF | 304 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Readings | Amps C Ø | 35.0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Readings | Maintenance Operations | 4 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Readings | 9 Month Operations | 6 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Readings | Operations Counter AL | 394 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Readings | Operations This Read Vac | 4 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Readings | Switching Operations | 0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Readings | Unknown Operations | 0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Readings | Fault Operations Ground | 0 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Readings | Follow-up Action Required? | n | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Readings | General Comments | Setting changes and testing 2-15-23 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Readings | Switching Operations | 4 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Readings | Unknown Operations | 0 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Readings | Maintenance Operations | 0 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Readings | Operations Counter AF | 487 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Readings | Fault Operations Ground | 0 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Readings | Operations Counter AL | 491 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Readings | Operations This Read Vac | 4 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Readings | General Comments | | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Readings | Follow-up Action Required? | n | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Readings | 9 Month Operations | 4 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Readings | Amps C Ø | 0.0 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Readings | Amps B Ø | 0.0 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Readings | Amps A Ø | 0.0 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Patrol Inspection | General Comments | | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0445 | BreakerVacuum | 512-0951 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Readings | Operations Counter AF | 494 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Readings | Operations Counter AL | 498 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Readings | Operations This Read Vac | 4 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Readings | Switching Operations | 4 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Readings | Unknown Operations | 0 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Readings | Maintenance Operations | 0 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Readings | General Comments | | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Readings | Follow-up Action Required? | n | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Readings | Fault Operations Ground | 0 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Readings | Amps C Ø | 80.0 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Readings | Amps B Ø | 70.0 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Readings | Amps A Ø | 80.0 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Readings | 9 Month Operations | 4 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Patrol Inspection | General Comments | | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | KB0020 | BreakerVacuum | 546-0541 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | LTCC000661 | LTCControl | 546-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | LTCC000661 | LTCControl | 546-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | LTCC000661 | LTCControl | 546-1 | LTC Control Insp | VRR Base Voltage AF | 124.1 | VAC |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | LTCC000661 | LTCControl | 546-1 | LTC Control Insp | VRR Base Voltage AL | 1246.0 | VAC |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | LTCC000661 | LTCControl | 546-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | LTCC000661 | LTCControl | 546-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | LTCC000661 | LTCControl | 546-1 | LTC Control Insp | General Comments | | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | LTCC000661 | LTCControl | 546-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | LTCC000661 | LTCControl | 546-1 | LTC Control Insp | All Connections OK? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Patrol Inspection | General Comments | | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BB0444 | BreakerVacuum | 512-0950 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | LTCMechanism | 546-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | LTCMechanism | 546-1 | LTC Counter Readings | General Comments | | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | LTCMechanism | 546-1 | LTC Counter Readings | LTC As Found Counter | 206451 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | LTCMechanism | 546-1 | LTC Counter Readings | LTC As Left Counter | 206462 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | LTCMechanism | 546-1 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | LTCMechanism | 546-1 | LTC Counter Readings | LTC Max Tap Position | 7R | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | LTCMechanism | 546-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | LTCMechanism | 546-1 | LTC Counter Readings | LTC Operations Since Last Insp | 935 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | LTCMechanism | 546-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Readings | 9 Months Operations OCB New | 0 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Readings | Fault Operations | 0 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Readings | Follow-up Action Required? | n | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Readings | Unknown Operations | 0 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Readings | Switching Operations | 0 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Readings | Operations This Read Oil | 0 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Readings | Operations Counter AL | 352 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Readings | Operations Counter AF | 352 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Readings | General Comments | | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Readings | Maintenance Operations | 0 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Readings | Number of Ops last 9 Months | 0 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | General Comments | | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | Pop-off Valve Tested Date | 2023-03-27 00:00:00.000000 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | Air Compressor Belt Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | Air Compressor Oil Status | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | Air Leaks | None | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | Air Pressure OK? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | Air Tank Bleed (> 40°F)? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | AirCompressor Heater Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | Tank Leaks | None | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | Pressure Vessel Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | TB0163 | BreakerOil | 512-708 | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | LTCMechanism | 512-1 | LTC Counter Readings | LTC As Left Counter | 13158 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | LTCMechanism | 512-1 | LTC Counter Readings | LTC As Found Counter | 13158 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | LTCMechanism | 512-1 | LTC Counter Readings | General Comments | | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | LTCMechanism | 512-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | LTCMechanism | 512-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | LTCMechanism | 512-1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | LTCMechanism | 512-1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | LTCMechanism | 512-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | LTCMechanism | 512-1 | LTC Counter Readings | LTC Operations Since Last Insp | 324 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | LTCMechanism | 546-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | LTCMechanism | 546-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | LTCMechanism | 546-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Replace Next Maint | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | LTCMechanism | 546-1 | LTC Mechanism Patrol Inspection | General Comments | Gasket is cracking and LTC tank is seaping | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | LTCMechanism | 546-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | LTCC000923 | LTCControl | 512-1 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | LTCC000923 | LTCControl | 512-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | LTCC000923 | LTCControl | 512-1 | LTC Control Insp | General Comments | | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | LTCC000923 | LTCControl | 512-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | LTCC000923 | LTCControl | 512-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | LTCC000923 | LTCControl | 512-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | LTCC000923 | LTCControl | 512-1 | LTC Control Insp | All Connections OK? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | LTCC000923 | LTCControl | 512-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.0998 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Readings | Oil Temp Present | 32 | °C |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Readings | Oil Temp Max | 59 | °C |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Readings | General Comments | | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Readings | LTC Totalizer Reading | 10558.08 | kw |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | LTCMechanism | 512-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | LTCMechanism | 512-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | LTCMechanism | 512-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | LTCMechanism | 512-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | LTCMechanism | 512-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | LTCMechanism | 512-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | LTCMechanism | 512-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Readings | Totalizer Meter Reading | .4800 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Readings | LTC Totalizer Reading | 2304.00 | kw |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Readings | General Comments | | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | B0340 | WithLTC | 512-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Patrol Inspection | Tank Leaks | Seeping | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | C0435 | WithLTC | 546-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BCH001516 | Charger | 512-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BCH001516 | Charger | 512-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.0 | VDC |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BCH001516 | Charger | 512-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.0 | VDC |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BCH001516 | Charger | 512-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .8 | amps |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BCH001516 | Charger | 512-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BCH001516 | Charger | 512-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BCH001516 | Charger | 512-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BCH001516 | Charger | 512-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BAT001123 | Battery | 512-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BAT001123 | Battery | 512-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 52 | °F |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BAT001123 | Battery | 512-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BAT001123 | Battery | 512-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BAT001123 | Battery | 512-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BAT001123 | Battery | 512-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BAT001123 | Battery | 512-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BAT001123 | Battery | 512-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BAT001123 | Battery | 512-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BAT001123 | Battery | 512-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BAT001123 | Battery | 512-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BAT001123 | Battery | 512-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | BAT001123 | Battery | 512-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | CH000340 | ControlHouse | 512-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | CH000340 | ControlHouse | 512-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | CH000340 | ControlHouse | 512-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | CH000340 | ControlHouse | 512-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | CH000340 | ControlHouse | 512-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | CH000340 | ControlHouse | 512-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | CH000340 | ControlHouse | 512-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | CH000340 | ControlHouse | 512-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | CH000340 | ControlHouse | 512-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | CH000340 | ControlHouse | 512-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | CH000340 | ControlHouse | 512-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | CH000340 | ControlHouse | 512-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | CH000340 | ControlHouse | 512-Control House | Control House Patrol Inspection | General Comments | | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | CH000340 | ControlHouse | 512-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | CH000340 | ControlHouse | 512-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | CH000340 | ControlHouse | 512-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | CH000340 | ControlHouse | 512-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | CH000340 | ControlHouse | 512-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | CH000340 | ControlHouse | 512-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | ST000302 | Structure | 512-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | ST000302 | Structure | 512-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | ST000302 | Structure | 512-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | ST000302 | Structure | 512-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | ST000302 | Structure | 512-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | ST000302 | Structure | 512-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | ST000302 | Structure | 512-Structure | Structure Patrol Inspection | General Comments | | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | ST000302 | Structure | 512-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | ST000302 | Structure | 512-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | ST000302 | Structure | 512-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | ST000302 | Structure | 512-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | ST000302 | Structure | 512-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | ST000302 | Structure | 512-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | ST000302 | Structure | 512-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | ST000302 | Structure | 512-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | ST000302 | Structure | 512-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | ST000302 | Structure | 512-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | ST000302 | Structure | 512-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | ST000302 | Structure | 512-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | ST000302 | Structure | 512-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BCH001351 | Charger | 546-Battery Charger | Battery Charger Patrol Insp | General Comments | meter unable to read ripple | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BCH001351 | Charger | 546-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BCH001351 | Charger | 546-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BCH001351 | Charger | 546-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.4 | amps |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BCH001351 | Charger | 546-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BCH001351 | Charger | 546-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BCH001351 | Charger | 546-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BCH001351 | Charger | 546-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | FE000291 | Fence | 512-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | FE000291 | Fence | 512-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | FE000291 | Fence | 512-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | FE000291 | Fence | 512-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | FE000291 | Fence | 512-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | FE000291 | Fence | 512-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | FE000291 | Fence | 512-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | FE000291 | Fence | 512-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | FE000291 | Fence | 512-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | FE000291 | Fence | 512-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | FE000291 | Fence | 512-Fence | Fence Patrol Inspection | General Comments | | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | FE000291 | Fence | 512-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | FE000291 | Fence | 512-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | FE000291 | Fence | 512-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | FE000291 | Fence | 512-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | FE000291 | Fence | 512-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | YD000294 | Yard | 512-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | YD000294 | Yard | 512-Yard | Yard Patrol Inspection | General Comments | | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | YD000294 | Yard | 512-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | YD000294 | Yard | 512-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | YD000294 | Yard | 512-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | YD000294 | Yard | 512-Yard | Yard Patrol Inspection | Ambient Temp | 52 | °F |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | YD000294 | Yard | 512-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | YD000294 | Yard | 512-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | YD000294 | Yard | 512-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | YD000294 | Yard | 512-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | YD000294 | Yard | 512-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | YD000294 | Yard | 512-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | YD000294 | Yard | 512-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/27/2023 11:20 | Distribution | Butler Quarterly Inspection | YD000294 | Yard | 512-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BAT001496 | Battery | 546-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BAT001496 | Battery | 546-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BAT001496 | Battery | 546-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BAT001496 | Battery | 546-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BAT001496 | Battery | 546-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BAT001496 | Battery | 546-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BAT001496 | Battery | 546-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BAT001496 | Battery | 546-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BAT001496 | Battery | 546-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BAT001496 | Battery | 546-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BAT001496 | Battery | 546-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BAT001496 | Battery | 546-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.2 | VDC |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | BAT001496 | Battery | 546-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.4 | VDC |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | CH000335 | ControlHouse | 546-Control house | Control House Patrol  Inspection | Doors and Locks Secure? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | CH000335 | ControlHouse | 546-Control house | Control House Patrol  Inspection | Evidence of Insects | None | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | CH000335 | ControlHouse | 546-Control house | Control House Patrol  Inspection | Windows/Doors Condition OK? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | CH000335 | ControlHouse | 546-Control house | Control House Patrol  Inspection | Ventilation Free of Debris? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | CH000335 | ControlHouse | 546-Control house | Control House Patrol  Inspection | Moisture and Leak Free? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | CH000335 | ControlHouse | 546-Control house | Control House Patrol  Inspection | General Comments | | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | CH000335 | ControlHouse | 546-Control house | Control House Patrol  Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | CH000335 | ControlHouse | 546-Control house | Control House Patrol  Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | CH000335 | ControlHouse | 546-Control house | Control House Patrol  Inspection | Acceptable Building Appearnce? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | CH000335 | ControlHouse | 546-Control house | Control House Patrol  Inspection | Broom on Site? | n | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | CH000335 | ControlHouse | 546-Control house | Control House Patrol  Inspection | Control House Lighting OK? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | CH000335 | ControlHouse | 546-Control house | Control House Patrol  Inspection | Controlhouse Grounds in Place? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | CH000335 | ControlHouse | 546-Control house | Control House Patrol  Inspection | Follow-up Action Required? | n | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | CH000335 | ControlHouse | 546-Control house | Control House Patrol  Inspection | Floor Swept? | n | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | CH000335 | ControlHouse | 546-Control house | Control House Patrol  Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | CH000335 | ControlHouse | 546-Control house | Control House Patrol  Inspection | Floor Condition Acceptable? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | ST000022 | Structure | 546-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | ST000022 | Structure | 546-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | ST000022 | Structure | 546-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | ST000022 | Structure | 546-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | ST000022 | Structure | 546-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | ST000022 | Structure | 546-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | ST000022 | Structure | 546-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | ST000022 | Structure | 546-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | ST000022 | Structure | 546-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | ST000022 | Structure | 546-Structure | Structure Patrol Inspection | General Comments | | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | ST000022 | Structure | 546-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | ST000022 | Structure | 546-Structure | Structure Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | ST000022 | Structure | 546-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | ST000022 | Structure | 546-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | ST000022 | Structure | 546-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | ST000022 | Structure | 546-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | ST000022 | Structure | 546-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | ST000022 | Structure | 546-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | ST000022 | Structure | 546-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | ST000022 | Structure | 546-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | ST000022 | Structure | 546-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | ST000022 | Structure | 546-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | FE000841 | Fence | 546-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | FE000841 | Fence | 546-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | FE000841 | Fence | 546-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | FE000841 | Fence | 546-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | FE000841 | Fence | 546-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | FE000841 | Fence | 546-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | FE000841 | Fence | 546-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | FE000841 | Fence | 546-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | FE000841 | Fence | 546-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | FE000841 | Fence | 546-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | FE000841 | Fence | 546-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | FE000841 | Fence | 546-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | FE000841 | Fence | 546-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | FE000841 | Fence | 546-Fence | Fence Patrol Inspection | General Comments | | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | FE000841 | Fence | 546-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | FE000841 | Fence | 546-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | YD000024 | Yard | 546-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | YD000024 | Yard | 546-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | YD000024 | Yard | 546-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | YD000024 | Yard | 546-Yard | Yard Patrol Inspection | General Comments | | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | YD000024 | Yard | 546-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | YD000024 | Yard | 546-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | YD000024 | Yard | 546-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | YD000024 | Yard | 546-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | YD000024 | Yard | 546-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | YD000024 | Yard | 546-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | YD000024 | Yard | 546-Yard | Yard Patrol Inspection | Ambient Temp | 57 | °F |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | YD000024 | Yard | 546-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/27/2023 11:22 | Distribution | Somerset South Quarterly Inspection | YD000024 | Yard | 546-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Patrol Inspection | General Comments | | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Readings | Fault Operations B Ø | 9 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Readings | Fault Operations C Ø | 9 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Readings | Fault Operations Ground | 0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Readings | Follow-up Action Required? | n | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Readings | General Comments | | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Readings | Maintenance Operations | 0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Readings | Operations Counter AF | 245 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Readings | Operations Counter AL | 245 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Readings | Operations This Read Vac | 18 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Readings | Fault Adjusted Amps C Phase V | 37.73 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Readings | Fault Adjusted Amps B Phase V | 37.73 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Readings | Amps C Ø | 55.0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Readings | Amps B Ø | 30.0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Readings | Amps A Ø | 55.0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Readings | Switching Operations | 0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Readings | 9 Month Operations | 18 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001156 | BreakerVacuum | 084-0937 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Patrol Inspection | General Comments | | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Readings | 9 Month Operations | 0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Readings | Fault Operations Ground | 0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Readings | Follow-up Action Required? | n | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Readings | General Comments | | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Readings | Amps A Ø | 45.0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Readings | Amps B Ø | 50.0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Readings | Amps C Ø | 55.0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Readings | Unknown Operations | 0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Readings | Switching Operations | 0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Readings | Operations This Read Vac | 0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Readings | Operations Counter AL | 181 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Readings | Operations Counter AF | 181 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001427 | BreakerVacuum | 084-0936 | VCB Readings | Maintenance Operations | 0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Patrol Inspection | General Comments | | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Readings | Amps C Ø | 125.0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Readings | Amps B Ø | 130.0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Readings | Amps A Ø | 105.0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Readings | Fault Operations Ground | 0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Readings | Follow-up Action Required? | n | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Readings | General Comments | | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Readings | Maintenance Operations | 0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Readings | Operations Counter AF | 185 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Readings | Operations Counter AL | 185 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Readings | Operations This Read Vac | 0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Readings | Switching Operations | 0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Readings | Unknown Operations | 0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BK001426 | BreakerVacuum | 084-0935 | VCB Readings | 9 Month Operations | 0 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | LTCC000853 | LTCControl | 084-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | LTCC000853 | LTCControl | 084-5 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | LTCC000853 | LTCControl | 084-5 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | LTCC000853 | LTCControl | 084-5 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | LTCC000853 | LTCControl | 084-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | LTCC000853 | LTCControl | 084-5 | LTC Control Insp | All Connections OK? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | LTCC000853 | LTCControl | 084-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | LTCC000853 | LTCControl | 084-5 | LTC Control Insp | General Comments | | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | LTCM000032 | LTCMechanism | 084-5 | LTC Counter Readings | LTC Operations Since Last Insp | 394 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | LTCM000032 | LTCMechanism | 084-5 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | LTCM000032 | LTCMechanism | 084-5 | LTC Counter Readings | LTC Max Tap Position | 5R | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | LTCM000032 | LTCMechanism | 084-5 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | LTCM000032 | LTCMechanism | 084-5 | LTC Counter Readings | LTC As Left Counter | 14956 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | LTCM000032 | LTCMechanism | 084-5 | LTC Counter Readings | LTC As Found Counter | 14956 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | LTCM000032 | LTCMechanism | 084-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | LTCM000032 | LTCMechanism | 084-5 | LTC Counter Readings | General Comments | | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | LTCM000032 | LTCMechanism | 084-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | LTCM000032 | LTCMechanism | 084-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | LTCM000032 | LTCMechanism | 084-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | LTCM000032 | LTCMechanism | 084-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | LTCM000032 | LTCMechanism | 084-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | LTCM000032 | LTCMechanism | 084-5 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | LTCM000032 | LTCMechanism | 084-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Readings | General Comments | | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Readings | LTC Totalizer Reading | 8386.56 | kw |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Readings | Totalizer Meter Reading | .8736 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | B0414 | WithLTC | 084-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BCH001374 | Charger | 084-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BCH001374 | Charger | 084-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BCH001374 | Charger | 084-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BCH001374 | Charger | 084-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BCH001374 | Charger | 084-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BCH001374 | Charger | 084-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.9 | amps |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BCH001374 | Charger | 084-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BCH001374 | Charger | 084-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BAT001452 | Battery | 084-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BAT001452 | Battery | 084-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BAT001452 | Battery | 084-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BAT001452 | Battery | 084-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BAT001452 | Battery | 084-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 45 | °F |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BAT001452 | Battery | 084-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BAT001452 | Battery | 084-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BAT001452 | Battery | 084-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BAT001452 | Battery | 084-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BAT001452 | Battery | 084-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BAT001452 | Battery | 084-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BAT001452 | Battery | 084-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | BAT001452 | Battery | 084-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | ST000391 | Structure | 084-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | ST000391 | Structure | 084-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | ST000391 | Structure | 084-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | ST000391 | Structure | 084-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | ST000391 | Structure | 084-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | ST000391 | Structure | 084-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | ST000391 | Structure | 084-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | ST000391 | Structure | 084-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | ST000391 | Structure | 084-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | ST000391 | Structure | 084-Structure | Structure Patrol Inspection | General Comments | | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | ST000391 | Structure | 084-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | ST000391 | Structure | 084-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | ST000391 | Structure | 084-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | ST000391 | Structure | 084-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | ST000391 | Structure | 084-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | ST000391 | Structure | 084-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | ST000391 | Structure | 084-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | ST000391 | Structure | 084-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | ST000391 | Structure | 084-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | ST000391 | Structure | 084-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | ST000391 | Structure | 084-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | FE000383 | Fence | 084-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | FE000383 | Fence | 084-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | FE000383 | Fence | 084-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | FE000383 | Fence | 084-Fence | Fence Patrol Inspection | General Comments | | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | FE000383 | Fence | 084-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | FE000383 | Fence | 084-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | FE000383 | Fence | 084-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | FE000383 | Fence | 084-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | FE000383 | Fence | 084-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | FE000383 | Fence | 084-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | FE000383 | Fence | 084-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | FE000383 | Fence | 084-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | FE000383 | Fence | 084-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | FE000383 | Fence | 084-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | FE000383 | Fence | 084-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | FE000383 | Fence | 084-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | CH000368 | ControlHouse | 084-Control House | Control House Patrol Inspection | General Comments | | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | CH000368 | ControlHouse | 084-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | CH000368 | ControlHouse | 084-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | CH000368 | ControlHouse | 084-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | CH000368 | ControlHouse | 084-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | CH000368 | ControlHouse | 084-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | CH000368 | ControlHouse | 084-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | CH000368 | ControlHouse | 084-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | CH000368 | ControlHouse | 084-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | CH000368 | ControlHouse | 084-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | CH000368 | ControlHouse | 084-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | CH000368 | ControlHouse | 084-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | CH000368 | ControlHouse | 084-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | CH000368 | ControlHouse | 084-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | CH000368 | ControlHouse | 084-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | CH000368 | ControlHouse | 084-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | CH000368 | ControlHouse | 084-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | CH000368 | ControlHouse | 084-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | CH000368 | ControlHouse | 084-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | YD000388 | Yard | 084-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | YD000388 | Yard | 084-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | YD000388 | Yard | 084-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | YD000388 | Yard | 084-Yard | Yard Patrol Inspection | General Comments | | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | YD000388 | Yard | 084-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | YD000388 | Yard | 084-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | YD000388 | Yard | 084-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | YD000388 | Yard | 084-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | YD000388 | Yard | 084-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | YD000388 | Yard | 084-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | YD000388 | Yard | 084-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | YD000388 | Yard | 084-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | YD000388 | Yard | 084-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/24/2023 7:38 | Distribution | Sharon Quarterly Inspection | YD000388 | Yard | 084-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Patrol Inspection | General Comments | | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Readings | Amps B Ø | 39.0 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Readings | Amps A Ø | 38.0 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Readings | 9 Month Operations | 4 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Readings | Operations Counter AL | 221 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Readings | Amps C Ø | 42.0 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Readings | Maintenance Operations | 0 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Readings | General Comments | | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Readings | Follow-up Action Required? | n | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Readings | Fault Operations Ground | 0 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Readings | Operations This Read Vac | 4 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Readings | Switching Operations | 4 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Readings | Unknown Operations | 0 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Readings | Operations Counter AF | 217 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0105 | BreakerVacuum | 452-2335 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Patrol Inspection | General Comments | | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Readings | Unknown Operations | 0 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Readings | Switching Operations | 3 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Readings | Operations This Read Vac | 3 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Readings | Operations Counter AL | 230 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Readings | Operations Counter AF | 227 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Readings | Maintenance Operations | 0 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Readings | General Comments | | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Readings | Follow-up Action Required? | n | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Readings | Fault Operations Ground | 0 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Readings | Amps C Ø | 54.0 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Readings | Amps B Ø | 56.0 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Readings | Amps A Ø | 43.0 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KB0104 | BreakerVacuum | 452-2334 | VCB Readings | 9 Month Operations | 6 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | RG000145 | Regulator | 452-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | RG000145 | Regulator | 452-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | RG000145 | Regulator | 452-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | RG000145 | Regulator | 452-1 C | Regulator Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | RG000145 | Regulator | 452-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | RG000145 | Regulator | 452-1 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | RG000145 | Regulator | 452-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | RG000145 | Regulator | 452-1 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | RG000145 | Regulator | 452-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | RG000145 | Regulator | 452-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | RG000145 | Regulator | 452-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | RG000145 | Regulator | 452-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | RG000145 | Regulator | 452-1 C | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | RG000145 | Regulator | 452-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | RG000145 | Regulator | 452-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | RG000145 | Regulator | 452-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | RG000145 | Regulator | 452-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | RG000145 | Regulator | 452-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | RG000145 | Regulator | 452-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 14806 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | RG000145 | Regulator | 452-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | RG000145 | Regulator | 452-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | RG000145 | Regulator | 452-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | RG000145 | Regulator | 452-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | RG000145 | Regulator | 452-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0117 | Regulator | 452-1 B | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0117 | Regulator | 452-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0117 | Regulator | 452-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0117 | Regulator | 452-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0117 | Regulator | 452-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0117 | Regulator | 452-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0117 | Regulator | 452-1 B | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0117 | Regulator | 452-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0117 | Regulator | 452-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0117 | Regulator | 452-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0117 | Regulator | 452-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0117 | Regulator | 452-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0117 | Regulator | 452-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 31444 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0117 | Regulator | 452-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0117 | Regulator | 452-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0117 | Regulator | 452-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0117 | Regulator | 452-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0117 | Regulator | 452-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0117 | Regulator | 452-1 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0117 | Regulator | 452-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0117 | Regulator | 452-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0117 | Regulator | 452-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0117 | Regulator | 452-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0117 | Regulator | 452-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0116 | Regulator | 452-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0116 | Regulator | 452-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0116 | Regulator | 452-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0116 | Regulator | 452-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 29301 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0116 | Regulator | 452-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0116 | Regulator | 452-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0116 | Regulator | 452-1 A | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0116 | Regulator | 452-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0116 | Regulator | 452-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0116 | Regulator | 452-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0116 | Regulator | 452-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0116 | Regulator | 452-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0116 | Regulator | 452-1 A | Regulator Patrol Inspection | General Comments | | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0116 | Regulator | 452-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0116 | Regulator | 452-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0116 | Regulator | 452-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0116 | Regulator | 452-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0116 | Regulator | 452-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0116 | Regulator | 452-1 A | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0116 | Regulator | 452-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0116 | Regulator | 452-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0116 | Regulator | 452-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0116 | Regulator | 452-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | KR0116 | Regulator | 452-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 60.00 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 55.00 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3177.60 | kw |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Readings | General Comments | | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .3310 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | S0035 | NonLTC | 452-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | CS000003 | CircuitSwitcher | 452-1 Trans-Rupter | Circuit Switcher Patrol Inspection | SF6 Indicator Zone | OK | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | CS000003 | CircuitSwitcher | 452-1 Trans-Rupter | Circuit Switcher Patrol Inspection | SF6 Bushing Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | CS000003 | CircuitSwitcher | 452-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | CS000003 | CircuitSwitcher | 452-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Ambient Temperature | 70 | °F |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | CS000003 | CircuitSwitcher | 452-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | CS000003 | CircuitSwitcher | 452-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | CS000003 | CircuitSwitcher | 452-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | CS000003 | CircuitSwitcher | 452-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | CS000003 | CircuitSwitcher | 452-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | CS000003 | CircuitSwitcher | 452-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Trip-energy Supply Verified | y | LED lights? |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | CS000003 | CircuitSwitcher | 452-1 Trans-Rupter | Circuit Switcher Patrol Inspection | General Comments | | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | CS000003 | CircuitSwitcher | 452-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | BCH000934 | Charger | 452-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | BCH000934 | Charger | 452-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | BCH000934 | Charger | 452-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | BCH000934 | Charger | 452-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.6 | amps |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | BCH000934 | Charger | 452-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | BCH000934 | Charger | 452-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | BAT000882 | Battery | 452-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | BAT000882 | Battery | 452-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | BAT000882 | Battery | 452-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | BAT000882 | Battery | 452-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | BAT000882 | Battery | 452-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | BAT000882 | Battery | 452-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | BAT000882 | Battery | 452-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | BAT000882 | Battery | 452-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | BAT000882 | Battery | 452-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | BAT000882 | Battery | 452-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | BAT000882 | Battery | 452-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | BAT000882 | Battery | 452-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | BAT000882 | Battery | 452-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | BAT000882 | Battery | 452-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | BAT000882 | Battery | 452-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | ST000833 | Structure | 452-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | ST000833 | Structure | 452-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | ST000833 | Structure | 452-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | ST000833 | Structure | 452-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | ST000833 | Structure | 452-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | ST000833 | Structure | 452-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | ST000833 | Structure | 452-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | ST000833 | Structure | 452-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | ST000833 | Structure | 452-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | ST000833 | Structure | 452-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | ST000833 | Structure | 452-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | ST000833 | Structure | 452-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | ST000833 | Structure | 452-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | ST000833 | Structure | 452-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | ST000833 | Structure | 452-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | ST000833 | Structure | 452-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | ST000833 | Structure | 452-Structure | Structure Patrol Inspection | General Comments | | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | ST000833 | Structure | 452-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | ST000833 | Structure | 452-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | ST000833 | Structure | 452-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | ST000833 | Structure | 452-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | ST000833 | Structure | 452-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | ST000833 | Structure | 452-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | ST000833 | Structure | 452-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | FE000799 | Fence | 452-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | FE000799 | Fence | 452-Fence | Fence Patrol Inspection | General Comments | | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | FE000799 | Fence | 452-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | FE000799 | Fence | 452-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | FE000799 | Fence | 452-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | FE000799 | Fence | 452-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | FE000799 | Fence | 452-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | FE000799 | Fence | 452-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | FE000799 | Fence | 452-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | FE000799 | Fence | 452-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | FE000799 | Fence | 452-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | FE000799 | Fence | 452-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | FE000799 | Fence | 452-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | FE000799 | Fence | 452-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | FE000799 | Fence | 452-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | FE000799 | Fence | 452-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | YD000842 | Yard | 452-Yard | Yard Patrol Inspection | Ambient Temp | 70 | °F |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | YD000842 | Yard | 452-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | YD000842 | Yard | 452-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | YD000842 | Yard | 452-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | YD000842 | Yard | 452-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | YD000842 | Yard | 452-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | YD000842 | Yard | 452-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | YD000842 | Yard | 452-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | YD000842 | Yard | 452-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | YD000842 | Yard | 452-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | YD000842 | Yard | 452-Yard | Yard Patrol Inspection | General Comments | | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | YD000842 | Yard | 452-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | YD000842 | Yard | 452-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | YD000842 | Yard | 452-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | YD000842 | Yard | 452-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | YD000842 | Yard | 452-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | YD000842 | Yard | 452-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | YD000842 | Yard | 452-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/23/2023 14:37 | Distribution | Rineyville Quarterly Inspection | YD000842 | Yard | 452-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Readings | Follow-up Action Required? | n | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Readings | 9 Month Operations | 5 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Readings | Unknown Operations | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Readings | Switching Operations | 5 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Readings | Operations This Read Vac | 5 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Readings | Operations Counter AL | 181 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Readings | Operations Counter AF | 176 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Readings | Maintenance Operations | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Readings | General Comments | | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Readings | Fault Operations Ground | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Readings | Amps A Ø | 54.0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Readings | Amps B Ø | 74.0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Readings | Amps C Ø | 73.0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Patrol Inspection | General Comments | | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000751 | BreakerVacuum | 605-2452 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Readings | Unknown Operations | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Readings | Switching Operations | 1 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Readings | Operations This Read Vac | 1 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Readings | Operations Counter AL | 173 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Readings | Operations Counter AF | 172 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Readings | Maintenance Operations | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Readings | General Comments | | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Readings | Follow-up Action Required? | n | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Readings | Fault Operations Ground | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Readings | Amps C Ø | 5.0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Readings | Amps B Ø | 10.0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Readings | Amps A Ø | 10.0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Readings | 9 Month Operations | 2 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK000752 | BreakerVacuum | 605-2454 | VCB Patrol Inspection | General Comments | | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Readings | 9 Month Operations | 4 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Readings | Amps A Ø | 100.0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Readings | Amps B Ø | 100.0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Readings | Amps C Ø | 100.0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Readings | Fault Operations Ground | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Readings | Follow-up Action Required? | n | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Readings | General Comments | | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Readings | Maintenance Operations | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Readings | Operations Counter AF | 233 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Readings | Operations Counter AL | 237 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Readings | Operations This Read Vac | 4 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Readings | Switching Operations | 4 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Readings | Unknown Operations | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Patrol Inspection | General Comments | | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Readings | 9 Month Operations | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Readings | General Comments | | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Readings | Maintenance Operations | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Readings | Operations Counter AF | 212 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Readings | Operations Counter AL | 212 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Readings | Operations This Read Vac | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Readings | Switching Operations | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Readings | Unknown Operations | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Readings | Follow-up Action Required? | n | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Readings | Fault Operations Ground | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Readings | Amps A Ø | 89.0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Readings | Amps B Ø | 147.0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Readings | Amps C Ø | 199.0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001096 | BreakerVacuum | 692-0913 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Patrol Inspection | General Comments | | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | CB0183 | BreakerVacuum | 605-2455 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Readings | Operations This Read Vac | 1 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Readings | Switching Operations | 1 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Readings | Unknown Operations | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Readings | Operations Counter AL | 291 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Readings | Operations Counter AF | 290 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Readings | Maintenance Operations | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Readings | General Comments | | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Readings | Follow-up Action Required? | n | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Readings | Fault Operations Ground | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Readings | Amps C Ø | 41.0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Readings | Amps B Ø | 41.0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Readings | Amps A Ø | 32.0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Readings | 9 Month Operations | 3 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | K0048 | BreakerVacuum | 605-2453 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Readings | Operations Counter AF | 158 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Readings | General Comments | | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Readings | Amps C Ø | 202.0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Readings | Unknown Operations | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Readings | Switching Operations | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Readings | Operations Counter AL | 158 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Readings | Amps B Ø | 208.0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Readings | Amps A Ø | 181.0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Readings | 9 Month Operations | 14 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Readings | 9 Month Operations VCB New | 14 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Patrol Inspection | General Comments | | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Readings | Amps B Ø | 57.0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Readings | Follow-up Action Required? | n | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Readings | Fault Operations Ground | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Readings | Unknown Operations | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Readings | 9 Month Operations | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Readings | Amps A Ø | 64.0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Readings | Switching Operations | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Readings | General Comments | | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Readings | Amps C Ø | 58.0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Readings | Maintenance Operations | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Readings | Operations Counter AF | 205 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Readings | Operations Counter AL | 205 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001095 | BreakerVacuum | 692-0912 | VCB Readings | Operations This Read Vac | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Patrol Inspection | General Comments | | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BK002054 | BreakerVacuum | 605-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | LTCMechanism | 605-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | LTCMechanism | 605-1 | LTC Counter Readings | LTC Operations Since Last Insp | 227 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | LTCMechanism | 605-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | LTCMechanism | 605-1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | LTCMechanism | 605-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | LTCMechanism | 605-1 | LTC Counter Readings | General Comments | | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | LTCMechanism | 605-1 | LTC Counter Readings | LTC As Found Counter | 89271 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | LTCMechanism | 605-1 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | LTCMechanism | 605-1 | LTC Counter Readings | LTC As Left Counter | 89276 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Patrol Inspection | General Comments | | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Readings | Amps A Ø | 45.0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Readings | Switching Operations | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Readings | Unknown Operations | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Readings | Operations Counter AL | 201 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Readings | Operations Counter AF | 201 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Readings | Follow-up Action Required? | n | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Readings | Fault Operations Ground | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Readings | 9 Month Operations | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Readings | Amps C Ø | 48.0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Readings | Amps B Ø | 49.0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Readings | Maintenance Operations | 0 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Readings | General Comments | | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BK001097 | BreakerVacuum | 692-0914 | VCB Readings | Operations This Read Vac | 0 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | LTCC000931 | LTCControl | 605-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | LTCC000931 | LTCControl | 605-1 | LTC Control Insp | All Connections OK? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | LTCC000931 | LTCControl | 605-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | LTCC000931 | LTCControl | 605-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | LTCC000931 | LTCControl | 605-1 | LTC Control Insp | General Comments | | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | LTCC000931 | LTCControl | 605-1 | LTC Control Insp | LTC Output Voltage Level | 123.7 | VAC |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | LTCC000931 | LTCControl | 605-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | LTCC000931 | LTCControl | 605-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | LTCMechanism | 605-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | LTCMechanism | 605-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | LTCMechanism | 605-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | LTCMechanism | 605-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | LTCMechanism | 605-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Readings | General Comments | | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Readings | LTC Totalizer Reading | 10980.00 | kw |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Readings | Totalizer Meter Reading | .6100 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Readings | Winding Temp Max | 30 | °C |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Readings | Winding Temp Present | 25 | °C |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | LTCMechanism | 692-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | LTCMechanism | 692-1 | LTC Counter Readings | LTC Current Tap Position | 11L | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | LTCMechanism | 692-1 | LTC Counter Readings | LTC Max Tap Position | 7L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | LTCMechanism | 692-1 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | LTCMechanism | 692-1 | LTC Counter Readings | LTC Operations Since Last Insp | 87 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | LTCMechanism | 692-1 | LTC Counter Readings | LTC As Left Counter | 83683 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | LTCMechanism | 692-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | LTCMechanism | 692-1 | LTC Counter Readings | General Comments | | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | LTCMechanism | 692-1 | LTC Counter Readings | LTC As Found Counter | 83683 | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | B0470 | WithLTC | 605-1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BAT001455 | Battery | 605-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BAT001455 | Battery | 605-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BAT001455 | Battery | 605-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BAT001455 | Battery | 605-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BAT001455 | Battery | 605-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BAT001455 | Battery | 605-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BAT001455 | Battery | 605-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BAT001455 | Battery | 605-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BAT001455 | Battery | 605-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BAT001455 | Battery | 605-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BAT001455 | Battery | 605-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BAT001455 | Battery | 605-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BCH001356 | Charger | 605-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BCH001356 | Charger | 605-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BCH001356 | Charger | 605-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BCH001356 | Charger | 605-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.0 | amps |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BCH001356 | Charger | 605-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BCH001356 | Charger | 605-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BCH001356 | Charger | 605-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | BCH001356 | Charger | 605-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | ST000486 | Structure | 605-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | ST000486 | Structure | 605-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | ST000486 | Structure | 605-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | ST000486 | Structure | 605-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | ST000486 | Structure | 605-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | ST000486 | Structure | 605-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | ST000486 | Structure | 605-Structure | Structure Patrol Inspection | General Comments | | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | ST000486 | Structure | 605-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | ST000486 | Structure | 605-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | ST000486 | Structure | 605-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | ST000486 | Structure | 605-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | ST000486 | Structure | 605-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | ST000486 | Structure | 605-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | ST000486 | Structure | 605-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | ST000486 | Structure | 605-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | ST000486 | Structure | 605-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | ST000486 | Structure | 605-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | ST000486 | Structure | 605-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | ST000486 | Structure | 605-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | ST000486 | Structure | 605-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | ST000486 | Structure | 605-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | ST000486 | Structure | 605-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | LTCC000851 | LTCControl | 692-1 | LTC Control Insp | LTC Operation Checked? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | LTCC000851 | LTCControl | 692-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | LTCC000851 | LTCControl | 692-1 | LTC Control Insp | VRR Base Voltage AF | 123.0 | VAC |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | LTCC000851 | LTCControl | 692-1 | LTC Control Insp | VRR Base Voltage AL | 123.0 | VAC |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | LTCC000851 | LTCControl | 692-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | LTCC000851 | LTCControl | 692-1 | LTC Control Insp | All Connections OK? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | LTCC000851 | LTCControl | 692-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | LTCC000851 | LTCControl | 692-1 | LTC Control Insp | General Comments | | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | FE000856 | Fence | 605-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | FE000856 | Fence | 605-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | FE000856 | Fence | 605-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | FE000856 | Fence | 605-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | FE000856 | Fence | 605-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | FE000856 | Fence | 605-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | FE000856 | Fence | 605-Fence | Fence Patrol Inspection | General Comments | | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | FE000856 | Fence | 605-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | FE000856 | Fence | 605-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | FE000856 | Fence | 605-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | FE000856 | Fence | 605-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | FE000856 | Fence | 605-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | FE000856 | Fence | 605-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | FE000856 | Fence | 605-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | FE000856 | Fence | 605-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | FE000856 | Fence | 605-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | LTCMechanism | 692-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | LTCMechanism | 692-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | LTCMechanism | 692-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | LTCMechanism | 692-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | LTCMechanism | 692-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | LTCMechanism | 692-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | LTCMechanism | 692-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | YD000485 | Yard | 605-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | YD000485 | Yard | 605-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | YD000485 | Yard | 605-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | YD000485 | Yard | 605-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | YD000485 | Yard | 605-Yard | Yard Patrol Inspection | General Comments | | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | YD000485 | Yard | 605-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | YD000485 | Yard | 605-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | YD000485 | Yard | 605-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | YD000485 | Yard | 605-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | YD000485 | Yard | 605-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | YD000485 | Yard | 605-Yard | Yard Patrol Inspection | Ambient Temp | 70 | °F |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | YD000485 | Yard | 605-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | YD000485 | Yard | 605-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | YD000485 | Yard | 605-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | YD000485 | Yard | 605-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/23/2023 13:14 | Distribution | Rogersville City Quarterly Inspection | YD000485 | Yard | 605-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Readings | General Comments | | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Readings | LTC Totalizer Reading | 2580.00 | kw |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Readings | Oil Temp Present | 55 | °C |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 6000 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Readings | Totalizer Meter Reading | .4300 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Patrol Inspection | Tank Leaks | Seeping | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | B0295 | WithLTC | 692-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BAT001557 | Battery | 692-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BAT001557 | Battery | 692-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BAT001557 | Battery | 692-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BAT001557 | Battery | 692-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BAT001557 | Battery | 692-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BAT001557 | Battery | 692-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BAT001557 | Battery | 692-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BAT001557 | Battery | 692-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BAT001557 | Battery | 692-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BAT001557 | Battery | 692-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BAT001557 | Battery | 692-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BAT001557 | Battery | 692-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BAT001557 | Battery | 692-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BCH001489 | Charger | 692-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BCH001489 | Charger | 692-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BCH001489 | Charger | 692-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BCH001489 | Charger | 692-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.5 | amps |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BCH001489 | Charger | 692-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BCH001489 | Charger | 692-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BCH001489 | Charger | 692-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | BCH001489 | Charger | 692-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | ST000320 | Structure | 692-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | ST000320 | Structure | 692-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | ST000320 | Structure | 692-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | ST000320 | Structure | 692-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | ST000320 | Structure | 692-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | ST000320 | Structure | 692-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | ST000320 | Structure | 692-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | ST000320 | Structure | 692-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | ST000320 | Structure | 692-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | ST000320 | Structure | 692-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | ST000320 | Structure | 692-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | ST000320 | Structure | 692-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | ST000320 | Structure | 692-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | ST000320 | Structure | 692-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | ST000320 | Structure | 692-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | ST000320 | Structure | 692-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | ST000320 | Structure | 692-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | ST000320 | Structure | 692-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | ST000320 | Structure | 692-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | ST000320 | Structure | 692-Structure | Structure Patrol Inspection | General Comments | | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | ST000320 | Structure | 692-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | ST000320 | Structure | 692-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | FE000308 | Fence | 692-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | FE000308 | Fence | 692-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | FE000308 | Fence | 692-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | FE000308 | Fence | 692-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | FE000308 | Fence | 692-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | FE000308 | Fence | 692-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | FE000308 | Fence | 692-Fence | Fence Patrol Inspection | General Comments | | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | FE000308 | Fence | 692-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | FE000308 | Fence | 692-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | FE000308 | Fence | 692-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | FE000308 | Fence | 692-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | FE000308 | Fence | 692-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | FE000308 | Fence | 692-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | FE000308 | Fence | 692-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | FE000308 | Fence | 692-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | FE000308 | Fence | 692-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | YD000313 | Yard | 692-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | YD000313 | Yard | 692-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | YD000313 | Yard | 692-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | YD000313 | Yard | 692-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | YD000313 | Yard | 692-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | YD000313 | Yard | 692-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | YD000313 | Yard | 692-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | YD000313 | Yard | 692-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | YD000313 | Yard | 692-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | YD000313 | Yard | 692-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | YD000313 | Yard | 692-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | YD000313 | Yard | 692-Yard | Yard Patrol Inspection | General Comments | | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | YD000313 | Yard | 692-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | YD000313 | Yard | 692-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 3/23/2023 13:27 | Distribution | Maysville East Quarterly Inspection | YD000313 | Yard | 692-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Readings | 9 Month Operations | 1 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Readings | Fault Operations Ground | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Readings | Follow-up Action Required? | n | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Readings | General Comments | | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Readings | Amps A Ø | 10.0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Readings | Amps B Ø | 20.0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Readings | Amps C Ø | 10.0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Readings | Maintenance Operations | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Readings | Operations Counter AF | 175 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Readings | Operations Counter AL | 175 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Readings | Operations This Read Vac | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Readings | Switching Operations | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Readings | Unknown Operations | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Patrol Inspection | General Comments | | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0320 | BreakerVacuum | 531-0906 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Readings | Fault Operations Ground | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Readings | Follow-up Action Required? | n | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Readings | General Comments | | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Readings | Amps B Ø | 0.0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Readings | Amps C Ø | 0.0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Readings | Unknown Operations | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Readings | Switching Operations | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Readings | Operations This Read Vac | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Readings | Operations Counter AL | 568 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Readings | Operations Counter AF | 568 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Readings | Maintenance Operations | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Readings | Amps A Ø | 0.0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Readings | 9 Month Operations | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Patrol Inspection | General Comments | | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0376 | BreakerVacuum | 531-0908 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Readings | 9 Month Operations | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Readings | Unknown Operations | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Readings | Switching Operations | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Readings | Operations This Read Vac | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Readings | Amps A Ø | 100.0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Readings | Amps B Ø | 90.0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Readings | Amps C Ø | 100.0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Readings | Fault Operations Ground | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Readings | Follow-up Action Required? | n | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Readings | General Comments | | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Readings | Maintenance Operations | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Readings | Operations Counter AL | 428 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Readings | Operations Counter AF | 428 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Patrol Inspection | General Comments | | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BB0429 | BreakerVacuum | 531-0907 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Readings | Operations Counter AF | 122 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Readings | Operations Counter AL | 122 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Readings | Maintenance Operations | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Readings | General Comments | | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Readings | Follow-up Action Required? | n | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Readings | Fault Operations Ground | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Readings | Amps A Ø | 79.0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Readings | Operations This Read Vac | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Readings | Switching Operations | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Readings | 9 Month Operations | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Readings | Amps B Ø | 107.0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Readings | Amps C Ø | 109.0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Readings | Unknown Operations | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Patrol Inspection | General Comments | | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BK000642 | BreakerVacuum | 531-0909 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | LTCC000707 | LTCControl | 531-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | LTCC000707 | LTCControl | 531-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | LTCC000707 | LTCControl | 531-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | LTCC000707 | LTCControl | 531-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | LTCC000707 | LTCControl | 531-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | LTCC000707 | LTCControl | 531-1 | LTC Control Insp | All Connections OK? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | LTCC000707 | LTCControl | 531-1 | LTC Control Insp | General Comments | | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | LTCC000707 | LTCControl | 531-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | LTCMechanism | 531-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | LTCMechanism | 531-1 | LTC Counter Readings | LTC Operations Since Last Insp | 209 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | LTCMechanism | 531-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | LTCMechanism | 531-1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | LTCMechanism | 531-1 | LTC Counter Readings | LTC Current Tap Position | 10L | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | LTCMechanism | 531-1 | LTC Counter Readings | LTC As Left Counter | 87719 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | LTCMechanism | 531-1 | LTC Counter Readings | LTC As Found Counter | 87719 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | LTCMechanism | 531-1 | LTC Counter Readings | General Comments | | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | LTCMechanism | 531-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | LTCMechanism | 531-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | LTCMechanism | 531-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | LTCMechanism | 531-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | LTCMechanism | 531-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | LTCMechanism | 531-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 265.00 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Readings | Totalizer Meter Reading | .4110 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 8000 | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Readings | LTC Totalizer Reading | 3288.00 | kw |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Readings | General Comments | | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | B0366 | WithLTC | 531-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BAT001451 | Battery | 531-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BAT001451 | Battery | 531-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BAT001451 | Battery | 531-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BAT001451 | Battery | 531-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BAT001451 | Battery | 531-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BAT001451 | Battery | 531-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BAT001451 | Battery | 531-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BAT001451 | Battery | 531-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BAT001451 | Battery | 531-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BAT001451 | Battery | 531-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BAT001451 | Battery | 531-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BAT001451 | Battery | 531-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BAT001451 | Battery | 531-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BCH001372 | Charger | 531-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BCH001372 | Charger | 531-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BCH001372 | Charger | 531-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .4 | amps |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BCH001372 | Charger | 531-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BCH001372 | Charger | 531-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BCH001372 | Charger | 531-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BCH001372 | Charger | 531-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | BCH001372 | Charger | 531-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | ST000409 | Structure | 531-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | ST000409 | Structure | 531-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | ST000409 | Structure | 531-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | ST000409 | Structure | 531-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | ST000409 | Structure | 531-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | ST000409 | Structure | 531-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | ST000409 | Structure | 531-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | ST000409 | Structure | 531-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | ST000409 | Structure | 531-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | ST000409 | Structure | 531-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | ST000409 | Structure | 531-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | ST000409 | Structure | 531-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | ST000409 | Structure | 531-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | ST000409 | Structure | 531-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | ST000409 | Structure | 531-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | ST000409 | Structure | 531-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | ST000409 | Structure | 531-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | ST000409 | Structure | 531-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | ST000409 | Structure | 531-Structure | Structure Patrol Inspection | General Comments | | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | ST000409 | Structure | 531-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | ST000409 | Structure | 531-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | ST000409 | Structure | 531-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | FE000830 | Fence | 531-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | FE000830 | Fence | 531-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | FE000830 | Fence | 531-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | FE000830 | Fence | 531-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | FE000830 | Fence | 531-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | FE000830 | Fence | 531-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | FE000830 | Fence | 531-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | FE000830 | Fence | 531-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | FE000830 | Fence | 531-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | FE000830 | Fence | 531-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | FE000830 | Fence | 531-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | FE000830 | Fence | 531-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | FE000830 | Fence | 531-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | FE000830 | Fence | 531-Fence | Fence Patrol Inspection | General Comments | | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | FE000830 | Fence | 531-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | FE000830 | Fence | 531-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | YD000407 | Yard | 531-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | YD000407 | Yard | 531-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | YD000407 | Yard | 531-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | YD000407 | Yard | 531-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | YD000407 | Yard | 531-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | YD000407 | Yard | 531-Yard | Yard Patrol Inspection | General Comments | | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | YD000407 | Yard | 531-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | YD000407 | Yard | 531-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | YD000407 | Yard | 531-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | YD000407 | Yard | 531-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | YD000407 | Yard | 531-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | YD000407 | Yard | 531-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | YD000407 | Yard | 531-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | YD000407 | Yard | 531-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/23/2023 12:38 | Distribution | Maysville Mid Quarterly Inspection | YD000407 | Yard | 531-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Readings | Switching Operations | 1 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Readings | Operations This Read Vac | 1 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Readings | Operations Counter AL | 167 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Readings | Operations Counter AF | 166 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Readings | Maintenance Operations | 0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Readings | General Comments | | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Readings | Follow-up Action Required? | n | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Readings | Fault Operations Ground | 0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Readings | Amps C Ø | 48.0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Readings | Amps B Ø | 57.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Readings | Unknown Operations | 0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Readings | Amps A Ø | 38.0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Readings | 9 Month Operations | 3 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Patrol Inspection | General Comments | | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001421 | BreakerVacuum | 698-2449 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Readings | Amps B Ø | 72.0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Readings | Amps A Ø | 60.0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Readings | Amps C Ø | 68.0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Readings | Fault Adjusted Amps A Phase V | 16.37 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Readings | Fault Operations A Ø | 3 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Readings | Fault Operations Ground | 0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Readings | Follow-up Action Required? | n | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Readings | General Comments | | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Readings | Maintenance Operations | 0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Readings | Operations Counter AF | 167 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Readings | Operations Counter AL | 181 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Readings | Operations This Read Vac | 14 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Readings | 9 Month Operations | 16 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Readings | Switching Operations | 11 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Readings | Unknown Operations | 0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Patrol Inspection | General Comments | | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001420 | BreakerVacuum | 698-2448 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Readings | Switching Operations | 1 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Readings | Amps B Ø | 98.0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Readings | Unknown Operations | 0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Readings | Operations This Read Vac | 1 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Readings | Amps A Ø | 94.0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Readings | Operations Counter AL | 178 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Readings | Operations Counter AF | 177 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Readings | Maintenance Operations | 0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Readings | Amps C Ø | 109.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Readings | Fault Operations Ground | 0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Readings | Follow-up Action Required? | n | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Readings | General Comments | | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Readings | 9 Month Operations | 3 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Patrol Inspection | General Comments | | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001419 | BreakerVacuum | 698-2447 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Readings | 9 Month Operations | 1 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Readings | Amps A Ø | 184.0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Readings | Amps B Ø | 230.0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Readings | General Comments | | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Readings | Operations Counter AF | 162 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Readings | Operations Counter AL | 162 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Readings | Amps C Ø | 218.0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Readings | Switching Operations | 0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Readings | Unknown Operations | 0 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Patrol Inspection | General Comments | | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BK001781 | BreakerVacuum | 698-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | LTCC000375 | LTCControl | 698-1 | LTC Control Insp | All Connections OK? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | LTCC000375 | LTCControl | 698-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | LTCC000375 | LTCControl | 698-1 | LTC Control Insp | General Comments | | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | LTCC000375 | LTCControl | 698-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | LTCC000375 | LTCControl | 698-1 | LTC Control Insp | LTC Output Voltage Level | 124.1 | VAC |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | LTCC000375 | LTCControl | 698-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | LTCC000375 | LTCControl | 698-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | LTCC000375 | LTCControl | 698-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | LTCC000375 | LTCControl | 698-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | LTCMechanism | 698-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | LTCMechanism | 698-1 | LTC Counter Readings | LTC Operations Since Last Insp | 503 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | LTCMechanism | 698-1 | LTC Counter Readings | LTC Min Tap Position | 15L | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | LTCMechanism | 698-1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | LTCMechanism | 698-1 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | LTCMechanism | 698-1 | LTC Counter Readings | General Comments | | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | LTCMechanism | 698-1 | LTC Counter Readings | LTC As Found Counter | 260630 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | LTCMechanism | 698-1 | LTC Counter Readings | LTC As Left Counter | 260634 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | LTCMechanism | 698-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | LTCMechanism | 698-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | LTCMechanism | 698-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | LTCMechanism | 698-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | LTCMechanism | 698-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | LTCMechanism | 698-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Readings | Winding Temp Max | 35 | °C |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Readings | Totalizer Meter Reading | .3774 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Readings | General Comments | | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Readings | LTC Totalizer Reading | 6793.20 | kw |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | C0478 | WithLTC | 698-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BCH001363 | Charger | 698-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BCH001363 | Charger | 698-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BCH001363 | Charger | 698-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BCH001363 | Charger | 698-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.3 | amps |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BCH001363 | Charger | 698-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BCH001363 | Charger | 698-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BCH001363 | Charger | 698-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BCH001363 | Charger | 698-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BAT000571 | Battery | 698-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BAT000571 | Battery | 698-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BAT000571 | Battery | 698-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BAT000571 | Battery | 698-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BAT000571 | Battery | 698-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BAT000571 | Battery | 698-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BAT000571 | Battery | 698-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BAT000571 | Battery | 698-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 25.0 | VDC |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BAT000571 | Battery | 698-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BAT000571 | Battery | 698-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BAT000571 | Battery | 698-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BAT000571 | Battery | 698-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BAT000571 | Battery | 698-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BAT000571 | Battery | 698-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 67 | °F |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | BAT000571 | Battery | 698-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | CH000383 | ControlHouse | 698-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | CH000383 | ControlHouse | 698-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | CH000383 | ControlHouse | 698-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | CH000383 | ControlHouse | 698-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | CH000383 | ControlHouse | 698-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | CH000383 | ControlHouse | 698-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | CH000383 | ControlHouse | 698-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | CH000383 | ControlHouse | 698-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | CH000383 | ControlHouse | 698-Control House | Control House Patrol Inspection | General Comments | | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | CH000383 | ControlHouse | 698-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | CH000383 | ControlHouse | 698-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | CH000383 | ControlHouse | 698-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | CH000383 | ControlHouse | 698-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | CH000383 | ControlHouse | 698-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | CH000383 | ControlHouse | 698-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | CH000383 | ControlHouse | 698-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | CH000383 | ControlHouse | 698-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | ST000444 | Structure | 698-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | ST000444 | Structure | 698-Structure | Structure Patrol Inspection | General Comments | | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | ST000444 | Structure | 698-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | ST000444 | Structure | 698-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | ST000444 | Structure | 698-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | ST000444 | Structure | 698-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | ST000444 | Structure | 698-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | ST000444 | Structure | 698-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | ST000444 | Structure | 698-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | ST000444 | Structure | 698-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | ST000444 | Structure | 698-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | ST000444 | Structure | 698-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | ST000444 | Structure | 698-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | ST000444 | Structure | 698-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | ST000444 | Structure | 698-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | ST000444 | Structure | 698-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | ST000444 | Structure | 698-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | ST000444 | Structure | 698-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | ST000444 | Structure | 698-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | ST000444 | Structure | 698-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | ST000444 | Structure | 698-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | ST000444 | Structure | 698-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | FE000437 | Fence | 698-Fence | Fence Patrol Inspection | General Comments | | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | FE000437 | Fence | 698-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | FE000437 | Fence | 698-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | FE000437 | Fence | 698-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | FE000437 | Fence | 698-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | FE000437 | Fence | 698-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | FE000437 | Fence | 698-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | FE000437 | Fence | 698-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | FE000437 | Fence | 698-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | FE000437 | Fence | 698-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | FE000437 | Fence | 698-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | FE000437 | Fence | 698-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | FE000437 | Fence | 698-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | FE000437 | Fence | 698-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | FE000437 | Fence | 698-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | FE000437 | Fence | 698-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | YD000441 | Yard | 698-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | YD000441 | Yard | 698-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | YD000441 | Yard | 698-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | YD000441 | Yard | 698-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | YD000441 | Yard | 698-Yard | Yard Patrol Inspection | General Comments | | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | YD000441 | Yard | 698-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | YD000441 | Yard | 698-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | YD000441 | Yard | 698-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | YD000441 | Yard | 698-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | YD000441 | Yard | 698-Yard | Yard Patrol Inspection | Ambient Temp | 67 | °F |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | YD000441 | Yard | 698-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | YD000441 | Yard | 698-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | YD000441 | Yard | 698-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | YD000441 | Yard | 698-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/23/2023 11:02 | Distribution | Radcliff Quarterly Inspection | YD000441 | Yard | 698-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Readings | Amps C Ø | 40.0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Readings | General Comments | | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Readings | Maintenance Operations | 0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Readings | Operations Counter AF | 140 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Readings | Operations Counter AL | 140 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Readings | Operations This Read Vac | 0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Readings | Switching Operations | 0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Readings | Amps B Ø | 20.0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Readings | Amps A Ø | 20.0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Readings | Unknown Operations | 0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Readings | Follow-up Action Required? | n | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Readings | Fault Operations Ground | 0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Readings | 9 Month Operations | 6 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Readings | 9 Month Operations | 5 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Readings | Switching Operations | 0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Readings | Operations This Read Vac | 3 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Readings | Operations Counter AL | 50 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Readings | Operations Counter AF | 50 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Readings | Amps A Ø | 70.0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Readings | Amps B Ø | 60.0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Readings | Maintenance Operations | 0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Readings | General Comments | | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Readings | Unknown Operations | 0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Readings | Follow-up Action Required? | n | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Readings | Fault Operations Ground | 0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Readings | Fault Operations C Ø | 1 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Readings | Fault Operations B Ø | 1 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Readings | Fault Operations A Ø | 1 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Readings | Fault Adjusted Amps C Phase V | 14.15 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Readings | Fault Adjusted Amps B Phase V | 14.15 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Readings | Amps C Ø | 60.0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Readings | Fault Adjusted Amps A Phase V | 14.15 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Readings | Unknown Operations | 0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Readings | Fault Operations Ground | 0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Readings | Follow-up Action Required? | n | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Readings | General Comments | | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Readings | Maintenance Operations | 0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Readings | Switching Operations | 0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Readings | Operations This Read Vac | 0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Readings | Operations Counter AL | 130 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Readings | Operations Counter AF | 130 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Readings | Amps C Ø | 60.0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Readings | Amps B Ø | 60.0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Readings | Amps A Ø | 60.0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Readings | 9 Month Operations | 2 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Readings | Unknown Operations | 0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Readings | Switching Operations | 0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Readings | Operations This Read Vac | 0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Readings | Operations Counter AL | 176 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Readings | Operations Counter AF | 176 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Readings | Maintenance Operations | 0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Readings | General Comments | | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Readings | 9 Month Operations | 4 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Readings | Follow-up Action Required? | n | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Readings | Amps A Ø | 50.0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Readings | Fault Operations Ground | 0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Readings | Amps B Ø | 60.0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Readings | Amps C Ø | 50.0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Patrol Inspection | General Comments | | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0400 | BreakerVacuum | 697-0902 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Patrol Inspection | General Comments | | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0206 | BreakerVacuum | 697-0903 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Patrol Inspection | General Comments | | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0234 | BreakerVacuum | 697-0901 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Patrol Inspection | General Comments | | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BB0319 | BreakerVacuum | 697-0900 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | LTCMechanism | 697-1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | LTCMechanism | 697-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | LTCMechanism | 697-1 | LTC Counter Readings | LTC Operations Since Last Insp | 167 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | LTCMechanism | 697-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | LTCMechanism | 697-1 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | LTCMechanism | 697-1 | LTC Counter Readings | LTC As Left Counter | 181613 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | LTCMechanism | 697-1 | LTC Counter Readings | LTC As Found Counter | 181613 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | LTCMechanism | 697-1 | LTC Counter Readings | General Comments | | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | LTCMechanism | 697-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | LTCC000511 | LTCControl | 697-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | LTCC000511 | LTCControl | 697-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | LTCC000511 | LTCControl | 697-1 | LTC Control Insp | VRR Base Voltage AF | 123.0 | VAC |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | LTCC000511 | LTCControl | 697-1 | LTC Control Insp | General Comments | | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | LTCC000511 | LTCControl | 697-1 | LTC Control Insp | VRR Base Voltage AL | 123.0 | VAC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | LTCC000511 | LTCControl | 697-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | LTCC000511 | LTCControl | 697-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | LTCC000511 | LTCControl | 697-1 | LTC Control Insp | All Connections OK? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | LTCMechanism | 697-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | LTCMechanism | 697-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | LTCMechanism | 697-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | LTCMechanism | 697-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | LTCMechanism | 697-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | LTCMechanism | 697-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | LTCMechanism | 697-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Readings | Totalizer Meter Reading | .3942 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 55.00 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 8000 | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Readings | LTC Totalizer Reading | 3153.60 | kw |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Readings | General Comments | | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | B0245 | WithLTC | 697-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BAT001462 | Battery | 697-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BAT001462 | Battery | 697-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BAT001462 | Battery | 697-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BAT001462 | Battery | 697-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BAT001462 | Battery | 697-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BAT001462 | Battery | 697-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BAT001462 | Battery | 697-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BAT001462 | Battery | 697-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BAT001462 | Battery | 697-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BAT001462 | Battery | 697-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BAT001462 | Battery | 697-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BAT001462 | Battery | 697-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BAT001462 | Battery | 697-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BAT001462 | Battery | 697-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BCH001399 | Charger | 697-Battery Bank | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BCH001399 | Charger | 697-Battery Bank | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BCH001399 | Charger | 697-Battery Bank | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BCH001399 | Charger | 697-Battery Bank | Battery Charger Patrol Insp | Battery Charger Current | .2 | amps |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BCH001399 | Charger | 697-Battery Bank | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BCH001399 | Charger | 697-Battery Bank | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BCH001399 | Charger | 697-Battery Bank | Battery Charger Patrol Insp | General Comments | | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | BCH001399 | Charger | 697-Battery Bank | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | ST000400 | Structure | 697-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | ST000400 | Structure | 697-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | ST000400 | Structure | 697-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | ST000400 | Structure | 697-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | ST000400 | Structure | 697-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | ST000400 | Structure | 697-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | ST000400 | Structure | 697-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | ST000400 | Structure | 697-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | ST000400 | Structure | 697-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | ST000400 | Structure | 697-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | ST000400 | Structure | 697-Structure | Structure Patrol Inspection | General Comments | | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | ST000400 | Structure | 697-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | ST000400 | Structure | 697-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | ST000400 | Structure | 697-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | ST000400 | Structure | 697-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | ST000400 | Structure | 697-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | ST000400 | Structure | 697-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | ST000400 | Structure | 697-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | ST000400 | Structure | 697-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | ST000400 | Structure | 697-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | ST000400 | Structure | 697-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | ST000400 | Structure | 697-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | FE000857 | Fence | 697-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | FE000857 | Fence | 697-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | FE000857 | Fence | 697-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | FE000857 | Fence | 697-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | FE000857 | Fence | 697-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | FE000857 | Fence | 697-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | FE000857 | Fence | 697-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | FE000857 | Fence | 697-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | FE000857 | Fence | 697-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | FE000857 | Fence | 697-Fence | Fence Patrol Inspection | General Comments | | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | FE000857 | Fence | 697-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | FE000857 | Fence | 697-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | FE000857 | Fence | 697-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | FE000857 | Fence | 697-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | FE000857 | Fence | 697-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | FE000857 | Fence | 697-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | YD000397 | Yard | 697-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | YD000397 | Yard | 697-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | YD000397 | Yard | 697-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | YD000397 | Yard | 697-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | YD000397 | Yard | 697-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | YD000397 | Yard | 697-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | YD000397 | Yard | 697-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | YD000397 | Yard | 697-Yard | Yard Patrol Inspection | General Comments | | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | YD000397 | Yard | 697-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | YD000397 | Yard | 697-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | YD000397 | Yard | 697-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | YD000397 | Yard | 697-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | YD000397 | Yard | 697-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | YD000397 | Yard | 697-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | YD000397 | Yard | 697-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | YD000397 | Yard | 697-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/23/2023 10:49 | Distribution | Maysville West Quarterly Inspection | YD000397 | Yard | 697-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0339 | LTCMechanism | 091-Offline-Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0339 | LTCMechanism | 091-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0339 | LTCMechanism | 091-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0339 | LTCMechanism | 091-Offline-Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0339 | LTCMechanism | 091-Offline-Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0339 | WithLTC | 091-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0339 | WithLTC | 091-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0339 | WithLTC | 091-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0339 | WithLTC | 091-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0339 | WithLTC | 091-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0339 | WithLTC | 091-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0339 | WithLTC | 091-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0339 | WithLTC | 091-Offline-Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0339 | WithLTC | 091-Offline-Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0339 | WithLTC | 091-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0339 | WithLTC | 091-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0339 | WithLTC | 091-Offline-Distribution | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0339 | WithLTC | 091-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0339 | WithLTC | 091-Offline-Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0339 | WithLTC | 091-Offline-Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0339 | WithLTC | 091-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0339 | WithLTC | 091-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0339 | WithLTC | 091-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0339 | WithLTC | 091-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0339 | WithLTC | 091-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0339 | WithLTC | 091-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Readings | General Comments | | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Readings | Operations Counter AF | 269 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Readings | Operations Counter AL | 271 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Readings | Operations This Read Vac | 2 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Readings | Switching Operations | 2 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Readings | 9 Month Operations | 2 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Readings | Amps A Ø | 52.0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Readings | Amps B Ø | 31.0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Readings | Amps C Ø | 69.0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | KB0111 | BreakerVacuum | 091-0924 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Readings | Operations Counter AF | 394 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Readings | Operations Counter AL | 396 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Readings | Operations This Read Vac | 2 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Readings | General Comments | | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Readings | Switching Operations | 2 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Readings | 9 Month Operations | 2 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Readings | Amps A Ø | 0.0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Readings | Amps B Ø | 0.0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Readings | Amps C Ø | 0.0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BB0463 | BreakerVacuum | 091-BT6-5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Readings | General Comments | | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Readings | Operations Counter AF | 219 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Readings | Operations Counter AL | 219 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Readings | Amps C Ø | 180.0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Readings | Amps B Ø | 191.0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Readings | Amps A Ø | 184.0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Readings | 9 Month Operations | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Readings | Switching Operations | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Readings | Operations This Read Vac | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001172 | BreakerVacuum | 828-2202 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Readings | General Comments | | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Readings | Amps C Ø | 120.0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Readings | Amps B Ø | 116.0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Readings | Operations Counter AF | 196 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Readings | Operations Counter AL | 196 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Readings | Operations This Read Vac | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Readings | Switching Operations | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Readings | 9 Month Operations | 2 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Readings | Amps A Ø | 107.0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001173 | BreakerVacuum | 828-2201 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Readings | Operations Counter AL | 151 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Readings | Operations Counter AF | 151 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Readings | General Comments | | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Readings | Switching Operations | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Readings | 9 Month Operations | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Readings | Amps C Ø | 300.0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Readings | Amps B Ø | 305.0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Readings | Amps A Ø | 288.0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001174 | BreakerVacuum | 828-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | LTCC000808 | LTCControl | 828-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | LTCC000808 | LTCControl | 828-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | LTCC000808 | LTCControl | 828-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | LTCC000808 | LTCControl | 828-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | LTCC000808 | LTCControl | 828-1 | LTC Control Insp | LTC Output Voltage Level | 123.6 | VAC |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | LTCC000808 | LTCControl | 828-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | LTCC000808 | LTCControl | 828-1 | LTC Control Insp | General Comments | | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | LTCC000808 | LTCControl | 828-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | LTCC000808 | LTCControl | 828-1 | LTC Control Insp | All Connections OK? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | LTCM000092 | LTCMechanism | 828-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | LTCM000092 | LTCMechanism | 828-1 | LTC Counter Readings | LTC Operations Since Last Insp | 532 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | LTCM000092 | LTCMechanism | 828-1 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | LTCM000092 | LTCMechanism | 828-1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | LTCM000092 | LTCMechanism | 828-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | LTCM000092 | LTCMechanism | 828-1 | LTC Counter Readings | LTC As Left Counter | 11286 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | LTCM000092 | LTCMechanism | 828-1 | LTC Counter Readings | LTC As Found Counter | 11286 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | LTCM000092 | LTCMechanism | 828-1 | LTC Counter Readings | General Comments | | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | LTCM000092 | LTCMechanism | 828-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | LTCM000092 | LTCMechanism | 828-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | LTCM000092 | LTCMechanism | 828-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | LTCM000092 | LTCMechanism | 828-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | LTCM000092 | LTCMechanism | 828-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | LTCM000092 | LTCMechanism | 828-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | LTCM000092 | LTCMechanism | 828-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 20 | °C |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | LTCM000092 | LTCMechanism | 828-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 35 | °C |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | LTCM000092 | LTCMechanism | 828-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | LTCM000092 | LTCMechanism | 828-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Readings | LTC Totalizer Reading | 6868.80 | kw |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Readings | Totalizer Meter Reading | .4770 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Readings | General Comments | | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | TX000223 | WithLTC | 828-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Readings | Operations Counter AL | 96 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Readings | Operations Counter AF | 96 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Readings | Fault Operations | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Readings | General Comments | | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Readings | Operations This Read SF6 | 1 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Readings | Switching Operations | 1 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Readings | Unknown Operations | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Readings | Num Operations Last 9 Months | 1 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Patrol Inspection | SF6 Pressure | 68 | psi |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Patrol Inspection | General Comments | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Patrol Inspection | Ambient Temperature | 51 | °F |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BK001038 | BreakerSF6 | 828-608 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BCH001380 | Charger | 828-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BCH001380 | Charger | 828-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.1 | VDC |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BCH001380 | Charger | 828-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.1 | VDC |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BCH001380 | Charger | 828-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.3 | amps |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BCH001380 | Charger | 828-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BCH001380 | Charger | 828-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Readings | Amps B Ø | 159.0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Readings | Amps C Ø | 119.0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Readings | Amps A Ø | 148.0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Readings | 9 Month Operations | 10 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Readings | General Comments | | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Readings | Operations Counter AF | 214 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Readings | Operations Counter AL | 216 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Readings | Operations This Read Vac | 2 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Readings | Switching Operations | 2 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BAT001422 | Battery | 828-Battery Bank | Battery Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BAT001422 | Battery | 828-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BAT001422 | Battery | 828-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BAT001422 | Battery | 828-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BAT001422 | Battery | 828-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BAT001422 | Battery | 828-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BAT001422 | Battery | 828-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BAT001422 | Battery | 828-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BAT001422 | Battery | 828-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BAT001422 | Battery | 828-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BAT001422 | Battery | 828-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BAT001422 | Battery | 828-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BAT001422 | Battery | 828-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BAT001422 | Battery | 828-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 66.4 | VDC |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BAT001422 | Battery | 828-Battery Bank | Battery Patrol Inspection | Bat Volt 1Min After Chgr Trip | 130.2 | VDC |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | BAT001422 | Battery | 828-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 66.5 | VDC |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000729 | BreakerVacuum | 091-0920 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Readings | Switching Operations | 2 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Readings | Operations This Read Vac | 2 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Readings | 9 Month Operations | 2 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Readings | Operations Counter AL | 216 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Readings | Operations Counter AF | 214 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Readings | Amps C Ø | 68.0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Readings | Amps B Ø | 84.0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Readings | Amps A Ø | 77.0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Readings | General Comments | | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | CH000502 | ControlHouse | 828-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | CH000502 | ControlHouse | 828-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | CH000502 | ControlHouse | 828-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | CH000502 | ControlHouse | 828-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | CH000502 | ControlHouse | 828-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | CH000502 | ControlHouse | 828-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | CH000502 | ControlHouse | 828-Control House | Control House Patrol Inspection | General Comments | | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | CH000502 | ControlHouse | 828-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | CH000502 | ControlHouse | 828-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | CH000502 | ControlHouse | 828-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | CH000502 | ControlHouse | 828-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | CH000502 | ControlHouse | 828-Control House | Control House Patrol Inspection | Filters Condition OK? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | CH000502 | ControlHouse | 828-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | CH000502 | ControlHouse | 828-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | CH000502 | ControlHouse | 828-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | CH000502 | ControlHouse | 828-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | CH000502 | ControlHouse | 828-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | CH000502 | ControlHouse | 828-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | CH000502 | ControlHouse | 828-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | CH000502 | ControlHouse | 828-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | CH000502 | ControlHouse | 828-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | ST000851 | Structure | 828-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | ST000851 | Structure | 828-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | ST000851 | Structure | 828-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | ST000851 | Structure | 828-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | ST000851 | Structure | 828-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | ST000851 | Structure | 828-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | ST000851 | Structure | 828-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | ST000851 | Structure | 828-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | ST000851 | Structure | 828-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | ST000851 | Structure | 828-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | ST000851 | Structure | 828-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | ST000851 | Structure | 828-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | ST000851 | Structure | 828-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | ST000851 | Structure | 828-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | ST000851 | Structure | 828-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | ST000851 | Structure | 828-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | ST000851 | Structure | 828-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | ST000851 | Structure | 828-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | ST000851 | Structure | 828-Structure | Structure Patrol Inspection | General Comments | | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000730 | BreakerVacuum | 091-0921 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | FE000557 | Fence | 828-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | FE000557 | Fence | 828-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | FE000557 | Fence | 828-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | FE000557 | Fence | 828-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | FE000557 | Fence | 828-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | FE000557 | Fence | 828-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | FE000557 | Fence | 828-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | FE000557 | Fence | 828-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | FE000557 | Fence | 828-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | FE000557 | Fence | 828-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | FE000557 | Fence | 828-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | FE000557 | Fence | 828-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | FE000557 | Fence | 828-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | FE000557 | Fence | 828-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | FE000557 | Fence | 828-Fence | Fence Patrol Inspection | General Comments | | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | FE000557 | Fence | 828-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Readings | Fault Adjusted Amps B Phase V | 14.06 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Readings | Amps C Ø | 76.0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Readings | Amps B Ø | 92.0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Readings | Amps A Ø | 81.0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Readings | 9 Month Operations | 3 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Readings | Fault Operations B Ø | 3 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Readings | Switching Operations | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Readings | Operations This Read Vac | 3 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Readings | Operations Counter AL | 173 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Readings | Operations Counter AF | 173 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Readings | General Comments | | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | YD000493 | Yard | 828-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | YD000493 | Yard | 828-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | YD000493 | Yard | 828-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | YD000493 | Yard | 828-Yard | Yard Patrol Inspection | General Comments | | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | YD000493 | Yard | 828-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | YD000493 | Yard | 828-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | YD000493 | Yard | 828-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | YD000493 | Yard | 828-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | YD000493 | Yard | 828-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | YD000493 | Yard | 828-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | YD000493 | Yard | 828-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | YD000493 | Yard | 828-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | YD000493 | Yard | 828-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | YD000493 | Yard | 828-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | YD000493 | Yard | 828-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/22/2023 14:30 | Distribution | Barton Quarterly Inspection | YD000493 | Yard | 828-Yard | Yard Patrol Inspection | Ambient Temp | 51 | °F |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK001411 | BreakerVacuum | 091-0922 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Readings | Amps B Ø | 107.0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Readings | Switching Operations | 2 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Readings | Operations This Read Vac | 2 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Readings | Operations Counter AL | 197 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Readings | Operations Counter AF | 195 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Readings | General Comments | | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Readings | 9 Month Operations | 4 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Readings | Amps C Ø | 113.0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Readings | Amps A Ø | 124.0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | BK000731 | BreakerVacuum | 091-0923 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCC000873 | LTCControl | 091-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCC000873 | LTCControl | 091-5 | LTC Control Insp | General Comments | Reset Beckwidth. Verfied Raise and Lower Limits | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCC000873 | LTCControl | 091-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCC000873 | LTCControl | 091-5 | LTC Control Insp | All Connections OK? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCC000873 | LTCControl | 091-5 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCC000873 | LTCControl | 091-5 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCC000873 | LTCControl | 091-5 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCC000873 | LTCControl | 091-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | LTCMechanism | 091-5 | LTC Counter Readings | LTC As Found Counter | 75822 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | LTCMechanism | 091-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | LTCMechanism | 091-5 | LTC Counter Readings | General Comments | Reset Beckwidth. Verfied Raise and Lower Limits | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | LTCMechanism | 091-5 | LTC Counter Readings | LTC As Left Counter | 75822 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | LTCMechanism | 091-5 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | LTCMechanism | 091-5 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | LTCMechanism | 091-5 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | LTCMechanism | 091-5 | LTC Counter Readings | LTC Operations Since Last Insp | 20 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | LTCMechanism | 091-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | LTCMechanism | 091-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | LTCMechanism | 091-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | LTCMechanism | 091-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | LTCMechanism | 091-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | LTCMechanism | 091-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Readings | General Comments | | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Readings | LTC Totalizer Reading | 7562.88 | kw |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Readings | Totalizer Meter Reading | .7878 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | C0503 | WithLTC | 091-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCM000022 | LTCMechanism | 091-6 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCM000022 | LTCMechanism | 091-6 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCM000022 | LTCMechanism | 091-6 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCM000022 | LTCMechanism | 091-6 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCM000022 | LTCMechanism | 091-6 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCM000022 | LTCMechanism | 091-6 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCM000022 | LTCMechanism | 091-6 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCM000022 | LTCMechanism | 091-6 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCC000872 | LTCControl | 091-6 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCC000872 | LTCControl | 091-6 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCC000872 | LTCControl | 091-6 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCC000872 | LTCControl | 091-6 | LTC Control Insp | LTC Output Voltage Level | 123.5 | VAC |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCC000872 | LTCControl | 091-6 | LTC Control Insp | All Connections OK? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCC000872 | LTCControl | 091-6 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCC000872 | LTCControl | 091-6 | LTC Control Insp | General Comments | | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCC000872 | LTCControl | 091-6 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCM000022 | LTCMechanism | 091-6 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCM000022 | LTCMechanism | 091-6 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCM000022 | LTCMechanism | 091-6 | LTC Counter Readings | LTC Operations Since Last Insp | 141 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCM000022 | LTCMechanism | 091-6 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCM000022 | LTCMechanism | 091-6 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCM000022 | LTCMechanism | 091-6 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCM000022 | LTCMechanism | 091-6 | LTC Counter Readings | LTC As Left Counter | 41517 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCM000022 | LTCMechanism | 091-6 | LTC Counter Readings | LTC As Found Counter | 41517 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | LTCM000022 | LTCMechanism | 091-6 | LTC Counter Readings | General Comments | | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Readings | General Comments | | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Readings | LTC Totalizer Reading | 8184.96 | kw |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Readings | Totalizer Meter Reading | .8526 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 3/22/2023 14:43 | Distribution | Kenton Quarterly Inspection | B0463 | WithLTC | 091-6 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | CX0612 | RecloserHydraulic | 759-2450 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 19 | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | CX0612 | RecloserHydraulic | 759-2450 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 11 | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | CX0612 | RecloserHydraulic | 759-2450 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 1 | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | CX0612 | RecloserHydraulic | 759-2450 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | CX0612 | RecloserHydraulic | 759-2450 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | CX0612 | RecloserHydraulic | 759-2450 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | CX0612 | RecloserHydraulic | 759-2450 | Recloser Hydraulic Patrol Inspection | Operations Counter | 15 | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | CX0612 | RecloserHydraulic | 759-2450 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | CX0612 | RecloserHydraulic | 759-2450 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | CX0612 | RecloserHydraulic | 759-2450 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | CX0612 | RecloserHydraulic | 759-2450 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | CX0612 | RecloserHydraulic | 759-2450 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | CX0612 | RecloserHydraulic | 759-2450 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | CX0069 | RecloserHydraulic | 759-2451 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | CX0069 | RecloserHydraulic | 759-2451 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | CX0069 | RecloserHydraulic | 759-2451 | Recloser Hydraulic Patrol Inspection | Operations Counter | 429 | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | CX0069 | RecloserHydraulic | 759-2451 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | CX0069 | RecloserHydraulic | 759-2451 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | CX0069 | RecloserHydraulic | 759-2451 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | CX0069 | RecloserHydraulic | 759-2451 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | CX0069 | RecloserHydraulic | 759-2451 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | CX0069 | RecloserHydraulic | 759-2451 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | CX0069 | RecloserHydraulic | 759-2451 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | CX0069 | RecloserHydraulic | 759-2451 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 50 | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | CX0069 | RecloserHydraulic | 759-2451 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 40 | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | CX0069 | RecloserHydraulic | 759-2451 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 45 | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0778 | Regulator | 759-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0778 | Regulator | 759-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0778 | Regulator | 759-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0778 | Regulator | 759-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0778 | Regulator | 759-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0778 | Regulator | 759-1 C | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0778 | Regulator | 759-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0778 | Regulator | 759-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0778 | Regulator | 759-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0778 | Regulator | 759-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0778 | Regulator | 759-1 C | Regulator Patrol Inspection | General Comments | control changed since last inspection | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0778 | Regulator | 759-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0778 | Regulator | 759-1 C | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0778 | Regulator | 759-1 C | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0778 | Regulator | 759-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0778 | Regulator | 759-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0778 | Regulator | 759-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0778 | Regulator | 759-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0778 | Regulator | 759-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0778 | Regulator | 759-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 43613 | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0778 | Regulator | 759-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0778 | Regulator | 759-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0778 | Regulator | 759-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0778 | Regulator | 759-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0776 | Regulator | 759-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0776 | Regulator | 759-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 31983 | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0776 | Regulator | 759-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0776 | Regulator | 759-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0776 | Regulator | 759-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0776 | Regulator | 759-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0776 | Regulator | 759-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0776 | Regulator | 759-1 B | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0776 | Regulator | 759-1 B | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0776 | Regulator | 759-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0776 | Regulator | 759-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0776 | Regulator | 759-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0776 | Regulator | 759-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0776 | Regulator | 759-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0776 | Regulator | 759-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0776 | Regulator | 759-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0776 | Regulator | 759-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0776 | Regulator | 759-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0776 | Regulator | 759-1 B | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0776 | Regulator | 759-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0776 | Regulator | 759-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0776 | Regulator | 759-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0776 | Regulator | 759-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | R0776 | Regulator | 759-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | KR0043 | Regulator | 759-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | KR0043 | Regulator | 759-1 A | Regulator Patrol Inspection | General Comments | | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | KR0043 | Regulator | 759-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | KR0043 | Regulator | 759-1 A | Regulator Patrol Inspection | Max Tap Position | 10R | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | KR0043 | Regulator | 759-1 A | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | KR0043 | Regulator | 759-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | KR0043 | Regulator | 759-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | KR0043 | Regulator | 759-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | KR0043 | Regulator | 759-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | KR0043 | Regulator | 759-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | KR0043 | Regulator | 759-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 42657 | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | KR0043 | Regulator | 759-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | KR0043 | Regulator | 759-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | KR0043 | Regulator | 759-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | KR0043 | Regulator | 759-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | KR0043 | Regulator | 759-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | KR0043 | Regulator | 759-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | KR0043 | Regulator | 759-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | KR0043 | Regulator | 759-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | KR0043 | Regulator | 759-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | KR0043 | Regulator | 759-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | KR0043 | Regulator | 759-1 A | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | KR0043 | Regulator | 759-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | KR0043 | Regulator | 759-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0 | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1904.04 | kw |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 245 | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.0578 | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Readings | Oil Temp Max | 60 | °C |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Readings | General Comments | | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1800 | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 255 | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | C0305 | NonLTC | 759-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | ST000483 | Structure | 759-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | ST000483 | Structure | 759-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | ST000483 | Structure | 759-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | ST000483 | Structure | 759-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | ST000483 | Structure | 759-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | ST000483 | Structure | 759-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | ST000483 | Structure | 759-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | ST000483 | Structure | 759-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | ST000483 | Structure | 759-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | ST000483 | Structure | 759-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | ST000483 | Structure | 759-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | ST000483 | Structure | 759-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | ST000483 | Structure | 759-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | ST000483 | Structure | 759-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | ST000483 | Structure | 759-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | ST000483 | Structure | 759-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | ST000483 | Structure | 759-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | ST000483 | Structure | 759-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | ST000483 | Structure | 759-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | ST000483 | Structure | 759-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | ST000483 | Structure | 759-Structure | Structure Patrol Inspection | General Comments | | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | ST000483 | Structure | 759-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | ST000483 | Structure | 759-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | ST000483 | Structure | 759-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | FE000475 | Fence | 759-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | FE000475 | Fence | 759-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | FE000475 | Fence | 759-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | FE000475 | Fence | 759-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | FE000475 | Fence | 759-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | FE000475 | Fence | 759-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | FE000475 | Fence | 759-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | FE000475 | Fence | 759-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | FE000475 | Fence | 759-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | FE000475 | Fence | 759-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | FE000475 | Fence | 759-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | FE000475 | Fence | 759-Fence | Fence Patrol Inspection | General Comments | | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | FE000475 | Fence | 759-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | FE000475 | Fence | 759-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | FE000475 | Fence | 759-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | FE000475 | Fence | 759-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | YD000482 | Yard | 759-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | YD000482 | Yard | 759-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | YD000482 | Yard | 759-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | YD000482 | Yard | 759-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | YD000482 | Yard | 759-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | YD000482 | Yard | 759-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | YD000482 | Yard | 759-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | YD000482 | Yard | 759-Yard | Yard Patrol Inspection | General Comments | | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | YD000482 | Yard | 759-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | YD000482 | Yard | 759-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | YD000482 | Yard | 759-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | YD000482 | Yard | 759-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | YD000482 | Yard | 759-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | YD000482 | Yard | 759-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | YD000482 | Yard | 759-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | YD000482 | Yard | 759-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | YD000482 | Yard | 759-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/22/2023 13:11 | Distribution | Rio Quarterly Inspection | YD000482 | Yard | 759-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0732 | RecloserElectronic | 845-2458 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0732 | RecloserElectronic | 845-2458 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0732 | RecloserElectronic | 845-2458 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0732 | RecloserElectronic | 845-2458 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0732 | RecloserElectronic | 845-2458 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0732 | RecloserElectronic | 845-2458 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0732 | RecloserElectronic | 845-2458 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0732 | RecloserElectronic | 845-2458 | Recloser Electronic Patrol Inspection | Operations Counter | 302 | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0732 | RecloserElectronic | 845-2458 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0732 | RecloserElectronic | 845-2458 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0732 | RecloserElectronic | 845-2458 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0732 | RecloserElectronic | 845-2458 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0732 | RecloserElectronic | 845-2458 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0732 | RecloserElectronic | 845-2458 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0732 | RecloserElectronic | 845-2458 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0732 | RecloserElectronic | 845-2458 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0732 | RecloserElectronic | 845-2458 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0732 | RecloserElectronic | 845-2458 | Recloser Electronic Patrol Inspection | Amps C Ø | 61 | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0732 | RecloserElectronic | 845-2458 | Recloser Electronic Patrol Inspection | Amps B Ø | 57 | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0732 | RecloserElectronic | 845-2458 | Recloser Electronic Patrol Inspection | Amps A Ø | 54 | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | CX0131 | RecloserElectronic | 845-2457 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | CX0131 | RecloserElectronic | 845-2457 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | CX0131 | RecloserElectronic | 845-2457 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | CX0131 | RecloserElectronic | 845-2457 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | CX0131 | RecloserElectronic | 845-2457 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | CX0131 | RecloserElectronic | 845-2457 | Recloser Electronic Patrol Inspection | Amps C Ø | 54 | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | CX0131 | RecloserElectronic | 845-2457 | Recloser Electronic Patrol Inspection | Amps B Ø | 56 | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | CX0131 | RecloserElectronic | 845-2457 | Recloser Electronic Patrol Inspection | Amps A Ø | 51 | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | CX0131 | RecloserElectronic | 845-2457 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | CX0131 | RecloserElectronic | 845-2457 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | CX0131 | RecloserElectronic | 845-2457 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | CX0131 | RecloserElectronic | 845-2457 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | CX0131 | RecloserElectronic | 845-2457 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | CX0131 | RecloserElectronic | 845-2457 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | CX0131 | RecloserElectronic | 845-2457 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | CX0131 | RecloserElectronic | 845-2457 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | CX0131 | RecloserElectronic | 845-2457 | Recloser Electronic Patrol Inspection | Operations Counter | 302 | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | CX0131 | RecloserElectronic | 845-2457 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | CX0131 | RecloserElectronic | 845-2457 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | CX0131 | RecloserElectronic | 845-2457 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0820 | RecloserElectronic | 845-2456 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0820 | RecloserElectronic | 845-2456 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0820 | RecloserElectronic | 845-2456 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0820 | RecloserElectronic | 845-2456 | Recloser Electronic Patrol Inspection | Operations Counter | 8 | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0820 | RecloserElectronic | 845-2456 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0820 | RecloserElectronic | 845-2456 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0820 | RecloserElectronic | 845-2456 | Recloser Electronic Patrol Inspection | General Comments | control changed out since last inspection | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0820 | RecloserElectronic | 845-2456 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0820 | RecloserElectronic | 845-2456 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0820 | RecloserElectronic | 845-2456 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0820 | RecloserElectronic | 845-2456 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0820 | RecloserElectronic | 845-2456 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0820 | RecloserElectronic | 845-2456 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0820 | RecloserElectronic | 845-2456 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0820 | RecloserElectronic | 845-2456 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0820 | RecloserElectronic | 845-2456 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0820 | RecloserElectronic | 845-2456 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0820 | RecloserElectronic | 845-2456 | Recloser Electronic Patrol Inspection | Amps C Ø | 23 | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0820 | RecloserElectronic | 845-2456 | Recloser Electronic Patrol Inspection | Amps B Ø | 38 | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | BX0820 | RecloserElectronic | 845-2456 | Recloser Electronic Patrol Inspection | Amps A Ø | 34 | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | LTCC000373 | LTCControl | 845-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | LTCC000373 | LTCControl | 845-1 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | LTCC000373 | LTCControl | 845-1 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | LTCC000373 | LTCControl | 845-1 | LTC Control Insp | LTC Output Voltage Level | 123.5 | VAC |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | LTCC000373 | LTCControl | 845-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | LTCC000373 | LTCControl | 845-1 | LTC Control Insp | General Comments | | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | LTCC000373 | LTCControl | 845-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | LTCC000373 | LTCControl | 845-1 | LTC Control Insp | All Connections OK? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | LTCMechanism | 845-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | LTCMechanism | 845-1 | LTC Counter Readings | General Comments | | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | LTCMechanism | 845-1 | LTC Counter Readings | LTC As Found Counter | 236564 | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | LTCMechanism | 845-1 | LTC Counter Readings | LTC As Left Counter | 236566 | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | LTCMechanism | 845-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | LTCMechanism | 845-1 | LTC Counter Readings | LTC Max Tap Position | 5R | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | LTCMechanism | 845-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | LTCMechanism | 845-1 | LTC Counter Readings | LTC Operations Since Last Insp | 458 | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | LTCMechanism | 845-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | LTCMechanism | 845-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | LTCMechanism | 845-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | LTCMechanism | 845-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | LTCMechanism | 845-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | LTCMechanism | 845-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0 | psi |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | LTCMechanism | 845-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | LTCMechanism | 845-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | LTCMechanism | 845-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0 | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Readings | Totalizer Meter Reading | .7716 | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Readings | LTC Totalizer Reading | 5555.52 | kw |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Readings | General Comments | | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | C0469 | WithLTC | 845-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | ST000479 | Structure | 845-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | ST000479 | Structure | 845-Structure | Structure Patrol Inspection | General Comments | | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | ST000479 | Structure | 845-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | ST000479 | Structure | 845-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | ST000479 | Structure | 845-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | ST000479 | Structure | 845-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | ST000479 | Structure | 845-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | ST000479 | Structure | 845-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | ST000479 | Structure | 845-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | ST000479 | Structure | 845-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | ST000479 | Structure | 845-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | ST000479 | Structure | 845-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | ST000479 | Structure | 845-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | ST000479 | Structure | 845-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | ST000479 | Structure | 845-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | ST000479 | Structure | 845-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | ST000479 | Structure | 845-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | ST000479 | Structure | 845-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | ST000479 | Structure | 845-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | ST000479 | Structure | 845-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | ST000479 | Structure | 845-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | ST000479 | Structure | 845-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | FE000827 | Fence | 845-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | FE000827 | Fence | 845-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | FE000827 | Fence | 845-Fence | Fence Patrol Inspection | General Comments | | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | FE000827 | Fence | 845-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | FE000827 | Fence | 845-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | FE000827 | Fence | 845-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | FE000827 | Fence | 845-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | FE000827 | Fence | 845-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | FE000827 | Fence | 845-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | FE000827 | Fence | 845-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | FE000827 | Fence | 845-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | FE000827 | Fence | 845-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | FE000827 | Fence | 845-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | FE000827 | Fence | 845-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | FE000827 | Fence | 845-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | FE000827 | Fence | 845-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | YD000477 | Yard | 845-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | YD000477 | Yard | 845-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | YD000477 | Yard | 845-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | YD000477 | Yard | 845-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | YD000477 | Yard | 845-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | YD000477 | Yard | 845-Yard | Yard Patrol Inspection | General Comments | | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | YD000477 | Yard | 845-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | YD000477 | Yard | 845-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | YD000477 | Yard | 845-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | YD000477 | Yard | 845-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | YD000477 | Yard | 845-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | YD000477 | Yard | 845-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | YD000477 | Yard | 845-Yard | Yard Patrol Inspection | Ambient Temp | 48 | °F |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | YD000477 | Yard | 845-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/22/2023 11:35 | Distribution | Sonora Quarterly Inspection | YD000477 | Yard | 845-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Interruptrs/Puffrs Visual OK? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | MOD Cabinet Heater functional? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | MOD Cabinet Internals Clean? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | MOD Motor Jaw Coupling | Good | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | General Comments | | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | General Comments | | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Ambient Temp | 46 | °F |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | General Comments | | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Switch Stick Next Test Date | 2023-06-23 00:00:00.000000 | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 3/22/2023 11:33 | Distribution | Bardstown City Customer Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Readings | Switching Operations | 0 | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Readings | Operations This Read Vac | 0 | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Readings | Operations Counter AL | 19 | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Readings | Operations Counter AF | 19 | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Readings | General Comments | | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Readings | Amps C Ø | 320.0 | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Readings | Amps B Ø | 320.0 | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Readings | Amps A Ø | 320.0 | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Readings | 9 Month Operations | 0 | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | CB0248 | BreakerVacuum | 619-2200 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | LTCMechanism | 619-2 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | LTCMechanism | 619-2 | LTC Counter Readings | LTC As Left Counter | 135033 | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | LTCMechanism | 619-2 | LTC Counter Readings | LTC As Found Counter | 135033 | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | LTCMechanism | 619-2 | LTC Counter Readings | General Comments | | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | LTCMechanism | 619-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | LTCMechanism | 619-2 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | LTCMechanism | 619-2 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | LTCMechanism | 619-2 | LTC Counter Readings | LTC Operations Since Last Insp | 845 | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | LTCMechanism | 619-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | KRC000349 | RegulatorControl | 619-2 | Regulator Annual Control Inspection | VRR Time Delay | 30 | Seconds |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | KRC000349 | RegulatorControl | 619-2 | Regulator Annual Control Inspection | VRR R Compensation AF | 0 | Position |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | KRC000349 | RegulatorControl | 619-2 | Regulator Annual Control Inspection | VRR Counter AL | 135033 | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | KRC000349 | RegulatorControl | 619-2 | Regulator Annual Control Inspection | VRR Counter AF | 135033 | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | KRC000349 | RegulatorControl | 619-2 | Regulator Annual Control Inspection | VRR Base Voltage AL | 123.0 | VAC |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | KRC000349 | RegulatorControl | 619-2 | Regulator Annual Control Inspection | VRR Bandwidth AL | 2.0 | VAC |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | KRC000349 | RegulatorControl | 619-2 | Regulator Annual Control Inspection | Reset Tap Drag Hands | Reset | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | KRC000349 | RegulatorControl | 619-2 | Regulator Annual Control Inspection | Min Tap Position | 12L | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | KRC000349 | RegulatorControl | 619-2 | Regulator Annual Control Inspection | Max Tap Position | 2L | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | KRC000349 | RegulatorControl | 619-2 | Regulator Annual Control Inspection | General Comments | | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | KRC000349 | RegulatorControl | 619-2 | Regulator Annual Control Inspection | Follow-up Action Required? | n | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | KRC000349 | RegulatorControl | 619-2 | Regulator Annual Control Inspection | FCP Lower AL | 0.0 | VAC |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | KRC000349 | RegulatorControl | 619-2 | Regulator Annual Control Inspection | FCP Lower AF | 0.0 | VAC |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | KRC000349 | RegulatorControl | 619-2 | Regulator Annual Control Inspection | FCP Block Raise AF | 0.0 | VAC |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | KRC000349 | RegulatorControl | 619-2 | Regulator Annual Control Inspection | Current Tap Position | 8L | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | KRC000349 | RegulatorControl | 619-2 | Regulator Annual Control Inspection | All Connections OK? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | LTCMechanism | 619-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | LTCMechanism | 619-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | LTCMechanism | 619-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | LTCMechanism | 619-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | LTCMechanism | 619-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | LTCMechanism | 619-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | LTCMechanism | 619-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Readings | General Comments | | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Readings | LTC Totalizer Reading | 9306.00 | kw |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Readings | Winding Temp Max | 30 | °C |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Readings | Totalizer Meter Reading | .5170 | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | C0517 | WithLTC | 619-2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | BCH001497 | Charger | 619-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | BCH001497 | Charger | 619-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | BCH001497 | Charger | 619-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | BCH001497 | Charger | 619-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 0.0 | amps |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | BCH001497 | Charger | 619-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | BCH001497 | Charger | 619-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | BCH001497 | Charger | 619-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | BCH001497 | Charger | 619-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | BAT001545 | Battery | 619-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | BAT001545 | Battery | 619-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | BAT001545 | Battery | 619-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | BAT001545 | Battery | 619-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | BAT001545 | Battery | 619-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | BAT001545 | Battery | 619-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | BAT001545 | Battery | 619-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.6 | VDC |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | BAT001545 | Battery | 619-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.7 | VDC |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | BAT001545 | Battery | 619-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | BAT001545 | Battery | 619-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | BAT001545 | Battery | 619-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 46 | °F |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | BAT001545 | Battery | 619-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | BAT001545 | Battery | 619-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | General Comments | | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | ST000555 | Structure | 619-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | General Comments | | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | FE000544 | Fence | 619-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Ambient Temp | 46 | °F |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | General Comments | | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/22/2023 11:23 | Distribution | Bardstown City Quarterly Inspection | YD000551 | Yard | 619-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Readings | 9 Month Operations | 1 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Readings | Switching Operations | 1 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Readings | Operations This Read Vac | 1 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Readings | Operations Counter AL | 168 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Readings | Operations Counter AF | 167 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Readings | General Comments | | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Readings | Amps C Ø | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Readings | Amps B Ø | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Readings | Amps A Ø | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001777 | BreakerVacuum | 466-4598 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Readings | 9 Month Operations | 1 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Readings | Amps A Ø | 24 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Readings | Amps B Ø | 25 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Readings | Amps C Ø | 25 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Readings | General Comments | | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Readings | Operations Counter AF | 198 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Readings | Operations Counter AL | 198 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Readings | Operations This Read Vac | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Readings | Switching Operations | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001776 | BreakerVacuum | 466-4597 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Readings | General Comments | | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Readings | Switching Operations | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Readings | Operations This Read Vac | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Readings | Operations Counter AL | 156 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Readings | Operations Counter AF | 156 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Readings | 9 Month Operations | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Readings | Amps A Ø | 23 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Readings | Amps B Ø | 26 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Readings | Amps C Ø | 29 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK001826 | BreakerVacuum | 466-9 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | LTCC000171 | LTCControl | 466-9 | LTC Control Insp | All Connections OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | LTCC000171 | LTCControl | 466-9 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | LTCC000171 | LTCControl | 466-9 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | LTCC000171 | LTCControl | 466-9 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | LTCC000171 | LTCControl | 466-9 | LTC Control Insp | LTC Output Voltage Level | 123.2 | VAC |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | LTCC000171 | LTCControl | 466-9 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | LTCC000171 | LTCControl | 466-9 | LTC Control Insp | General Comments | | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | LTCC000171 | LTCControl | 466-9 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | LTCMechanism | 466-9 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | LTCMechanism | 466-9 | LTC Counter Readings | LTC Operations Since Last Insp | 412 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | LTCMechanism | 466-9 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | LTCMechanism | 466-9 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | LTCMechanism | 466-9 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | LTCMechanism | 466-9 | LTC Counter Readings | LTC As Left Counter | 3766 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | LTCMechanism | 466-9 | LTC Counter Readings | LTC As Found Counter | 3763 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | LTCMechanism | 466-9 | LTC Counter Readings | General Comments | | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | LTCMechanism | 466-9 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | LTCMechanism | 466-9 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | LTCMechanism | 466-9 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | LTCMechanism | 466-9 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | LTCMechanism | 466-9 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0 | psi |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | LTCMechanism | 466-9 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | LTCMechanism | 466-9 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | LTCMechanism | 466-9 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Readings | Winding Temp Present | 20 | °C |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Readings | Winding Temp Max | 35 | °C |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Readings | Totalizer Meter Reading | .043 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Readings | LTC Totalizer Reading | 774 | kw |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Readings | General Comments | | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 10 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | S0019 | WithLTC | 466-9 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Readings | General Comments | | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Readings | Amps A Ø | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Readings | Amps B Ø | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Readings | Amps C Ø | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Readings | Fault Operations | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Readings | Unknown Operations | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Readings | Switching Operations | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Readings | Operations This Read SF6 | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Readings | Operations Counter AL | 1026 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Readings | Operations Counter AF | 1026 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Patrol Inspection | SF6 Pressure | 68 | psi |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Patrol Inspection | Ambient Temperature | 45 | °F |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Patrol Inspection | General Comments | | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BK000192 | BreakerSF6 | 466-698 | GCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BCH001377 | Charger | 466-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BCH001377 | Charger | 466-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BCH001377 | Charger | 466-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BCH001377 | Charger | 466-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BCH001377 | Charger | 466-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.8 | amps |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BCH001377 | Charger | 466-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BCH001377 | Charger | 466-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BCH001377 | Charger | 466-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0 | millivolts |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BAT001622 | Battery | 466-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BAT001622 | Battery | 466-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BAT001622 | Battery | 466-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26 | VDC |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BAT001622 | Battery | 466-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.2 | VDC |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BAT001622 | Battery | 466-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BAT001622 | Battery | 466-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BAT001622 | Battery | 466-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BAT001622 | Battery | 466-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BAT001622 | Battery | 466-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BAT001622 | Battery | 466-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BAT001622 | Battery | 466-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BAT001622 | Battery | 466-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | BAT001622 | Battery | 466-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | CH000371 | ControlHouse | 466-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | CH000371 | ControlHouse | 466-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | CH000371 | ControlHouse | 466-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | CH000371 | ControlHouse | 466-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | CH000371 | ControlHouse | 466-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | CH000371 | ControlHouse | 466-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | CH000371 | ControlHouse | 466-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | CH000371 | ControlHouse | 466-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | CH000371 | ControlHouse | 466-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | CH000371 | ControlHouse | 466-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | CH000371 | ControlHouse | 466-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | CH000371 | ControlHouse | 466-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | CH000371 | ControlHouse | 466-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | CH000371 | ControlHouse | 466-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | CH000371 | ControlHouse | 466-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | CH000371 | ControlHouse | 466-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | CH000371 | ControlHouse | 466-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | ST000858 | Structure | 466-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | ST000858 | Structure | 466-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | ST000858 | Structure | 466-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | ST000858 | Structure | 466-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | ST000858 | Structure | 466-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | ST000858 | Structure | 466-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | ST000858 | Structure | 466-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | ST000858 | Structure | 466-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | ST000858 | Structure | 466-Structure | Structure Patrol Inspection | General Comments | | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | ST000858 | Structure | 466-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | ST000858 | Structure | 466-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | ST000858 | Structure | 466-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | ST000858 | Structure | 466-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | ST000858 | Structure | 466-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | ST000858 | Structure | 466-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | ST000858 | Structure | 466-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | ST000858 | Structure | 466-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | ST000858 | Structure | 466-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | ST000858 | Structure | 466-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | ST000858 | Structure | 466-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | FE000883 | Fence | 466-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | FE000883 | Fence | 466-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | FE000883 | Fence | 466-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | FE000883 | Fence | 466-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | FE000883 | Fence | 466-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | FE000883 | Fence | 466-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | FE000883 | Fence | 466-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | FE000883 | Fence | 466-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | FE000883 | Fence | 466-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | FE000883 | Fence | 466-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | FE000883 | Fence | 466-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | FE000883 | Fence | 466-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | FE000883 | Fence | 466-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | FE000883 | Fence | 466-Fence | Fence Patrol Inspection | General Comments | | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | FE000883 | Fence | 466-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | FE000883 | Fence | 466-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | YD000968 | Yard | 466-Yard | Yard Patrol Inspection | General Comments | | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | YD000968 | Yard | 466-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | YD000968 | Yard | 466-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | YD000968 | Yard | 466-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | YD000968 | Yard | 466-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | YD000968 | Yard | 466-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | YD000968 | Yard | 466-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | YD000968 | Yard | 466-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | YD000968 | Yard | 466-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | YD000968 | Yard | 466-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | YD000968 | Yard | 466-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | YD000968 | Yard | 466-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | YD000968 | Yard | 466-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | YD000968 | Yard | 466-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/22/2023 10:45 | Distribution | Glendale Temporary Construction Quarterly Inspection | YD000968 | Yard | 466-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | MOD Cabinet Heater functional? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | MOD Cabinet Internals Clean? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | MOD Motor Jaw Coupling | Good | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Interruptrs/Puffrs Visual OK? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | General Comments | | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | General Comments | signs need updating | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | n | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Switch Stick Next Test Date | 2023-06-23 00:00:00.000000 | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | General Comments | | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Ambient Temp | 46 | °F |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 3/22/2023 10:24 | Distribution | Bardstown Industrial Customer Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0077 | RecloserElectronic | 872-0940 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0077 | RecloserElectronic | 872-0940 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0077 | RecloserElectronic | 872-0940 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0077 | RecloserElectronic | 872-0940 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0077 | RecloserElectronic | 872-0940 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0077 | RecloserElectronic | 872-0940 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0077 | RecloserElectronic | 872-0940 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0077 | RecloserElectronic | 872-0940 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0077 | RecloserElectronic | 872-0940 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0077 | RecloserElectronic | 872-0940 | Recloser Electronic Patrol Inspection | Amps C Ø | 45.0 | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0077 | RecloserElectronic | 872-0940 | Recloser Electronic Patrol Inspection | Amps B Ø | 60.0 | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0077 | RecloserElectronic | 872-0940 | Recloser Electronic Patrol Inspection | Amps A Ø | 45.0 | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0077 | RecloserElectronic | 872-0940 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0077 | RecloserElectronic | 872-0940 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0077 | RecloserElectronic | 872-0940 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0077 | RecloserElectronic | 872-0940 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0077 | RecloserElectronic | 872-0940 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0077 | RecloserElectronic | 872-0940 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0077 | RecloserElectronic | 872-0940 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0077 | RecloserElectronic | 872-0940 | Recloser Electronic Patrol Inspection | Operations Counter | 6 | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0078 | RecloserElectronic | 872-0941 | Recloser Electronic Patrol Inspection | Amps A Ø | 0.0 | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0078 | RecloserElectronic | 872-0941 | Recloser Electronic Patrol Inspection | Amps B Ø | 12.0 | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0078 | RecloserElectronic | 872-0941 | Recloser Electronic Patrol Inspection | Amps C Ø | 0.0 | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0078 | RecloserElectronic | 872-0941 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0078 | RecloserElectronic | 872-0941 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0078 | RecloserElectronic | 872-0941 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0078 | RecloserElectronic | 872-0941 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0078 | RecloserElectronic | 872-0941 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0078 | RecloserElectronic | 872-0941 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0078 | RecloserElectronic | 872-0941 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0078 | RecloserElectronic | 872-0941 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0078 | RecloserElectronic | 872-0941 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0078 | RecloserElectronic | 872-0941 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0078 | RecloserElectronic | 872-0941 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0078 | RecloserElectronic | 872-0941 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0078 | RecloserElectronic | 872-0941 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0078 | RecloserElectronic | 872-0941 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0078 | RecloserElectronic | 872-0941 | Recloser Electronic Patrol Inspection | Operations Counter | 1 | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0078 | RecloserElectronic | 872-0941 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | KX0078 | RecloserElectronic | 872-0941 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000109 | Regulator | 872-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000109 | Regulator | 872-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000109 | Regulator | 872-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000109 | Regulator | 872-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000109 | Regulator | 872-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 5582 | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000109 | Regulator | 872-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.0 | volts |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000109 | Regulator | 872-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000109 | Regulator | 872-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000109 | Regulator | 872-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000109 | Regulator | 872-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000109 | Regulator | 872-1 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000109 | Regulator | 872-1 A | Regulator Patrol Inspection | Max Tap Position | 4R | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000109 | Regulator | 872-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000109 | Regulator | 872-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000109 | Regulator | 872-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000109 | Regulator | 872-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000109 | Regulator | 872-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000109 | Regulator | 872-1 A | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000109 | Regulator | 872-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000109 | Regulator | 872-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000109 | Regulator | 872-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000109 | Regulator | 872-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000109 | Regulator | 872-1 A | Regulator Patrol Inspection | General Comments | | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000109 | Regulator | 872-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000110 | Regulator | 872-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000110 | Regulator | 872-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000110 | Regulator | 872-1 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000110 | Regulator | 872-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000110 | Regulator | 872-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000110 | Regulator | 872-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000110 | Regulator | 872-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000110 | Regulator | 872-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000110 | Regulator | 872-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000110 | Regulator | 872-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000110 | Regulator | 872-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000110 | Regulator | 872-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000110 | Regulator | 872-1 B | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000110 | Regulator | 872-1 B | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000110 | Regulator | 872-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000110 | Regulator | 872-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000110 | Regulator | 872-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000110 | Regulator | 872-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000110 | Regulator | 872-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.0 | volts |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000110 | Regulator | 872-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 6842 | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000110 | Regulator | 872-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000110 | Regulator | 872-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000110 | Regulator | 872-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000110 | Regulator | 872-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000111 | Regulator | 872-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000111 | Regulator | 872-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000111 | Regulator | 872-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000111 | Regulator | 872-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000111 | Regulator | 872-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000111 | Regulator | 872-1 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000111 | Regulator | 872-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000111 | Regulator | 872-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000111 | Regulator | 872-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000111 | Regulator | 872-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000111 | Regulator | 872-1 C | Regulator Patrol Inspection | General Comments | | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000111 | Regulator | 872-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000111 | Regulator | 872-1 C | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000111 | Regulator | 872-1 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000111 | Regulator | 872-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000111 | Regulator | 872-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000111 | Regulator | 872-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000111 | Regulator | 872-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000111 | Regulator | 872-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.0 | volts |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000111 | Regulator | 872-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 5663 | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000111 | Regulator | 872-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000111 | Regulator | 872-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000111 | Regulator | 872-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | RG000111 | Regulator | 872-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Readings | Amps A Ø | 330.0 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Readings | Amps B Ø | 299.0 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Readings | Amps C Ø | 295.0 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Readings | Switching Operations | 0 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Readings | Operations Counter AL | 215 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Readings | Operations Counter AF | 215 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Readings | 9 Month Operations | 0 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KB0011 | BreakerVacuum | 593-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | LTCC000030 | LTCControl | 593-2 | LTC Control Insp | All Connections OK? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | LTCC000030 | LTCControl | 593-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | LTCC000030 | LTCControl | 593-2 | LTC Control Insp | General Comments | | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | LTCC000030 | LTCControl | 593-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | LTCC000030 | LTCControl | 593-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | LTCC000030 | LTCControl | 593-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | LTCC000030 | LTCControl | 593-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | LTCC000030 | LTCControl | 593-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | LTCMechanism | 593-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | LTCMechanism | 593-2 | LTC Counter Readings | LTC Operations Since Last Insp | 1045 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | LTCMechanism | 593-2 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | LTCMechanism | 593-2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | LTCMechanism | 593-2 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | LTCMechanism | 593-2 | LTC Counter Readings | LTC As Left Counter | 80635 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | LTCMechanism | 593-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | LTCMechanism | 593-2 | LTC Counter Readings | General Comments | | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | LTCMechanism | 593-2 | LTC Counter Readings | LTC As Found Counter | 80635 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | LTCMechanism | 593-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | LTCMechanism | 593-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | LTCMechanism | 593-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | LTCMechanism | 593-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 45 | °C |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | LTCMechanism | 593-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 20 | °C |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | LTCMechanism | 593-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | LTCMechanism | 593-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | LTCMechanism | 593-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Readings | General Comments | | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Readings | LTC Totalizer Reading | 7830.00 | kw |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Readings | Totalizer Meter Reading | .4350 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Readings | Winding Temp Max | 35 | °C |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Readings | Winding Temp Present | 35 | °C |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 65.00 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Readings | Winding Temp Present | 35 | °C |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Readings | Winding Temp Max | 45 | °C |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Readings | Totalizer Meter Reading | .4915 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Readings | LTC Totalizer Reading | 8847.00 | kw |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Readings | General Comments | | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | KT0015 | WithLTC | 593-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Readings | General Comments | | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Readings | Operations Counter AF | 173 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Readings | Operations Counter AL | 173 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Readings | Switching Operations | 0 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Readings | 9 Month Operations | 0 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Readings | Amps A Ø | 320.0 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Readings | Amps B Ø | 320.0 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Readings | Amps C Ø | 360.0 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | CB0249 | BreakerVacuum | 593-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | LTCC000645 | LTCControl | 593-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | LTCC000645 | LTCControl | 593-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | LTCC000645 | LTCControl | 593-1 | LTC Control Insp | LTC Output Voltage Level | 123.7 | VAC |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | LTCC000645 | LTCControl | 593-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | LTCC000645 | LTCControl | 593-1 | LTC Control Insp | All Connections OK? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | LTCC000645 | LTCControl | 593-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | LTCC000645 | LTCControl | 593-1 | LTC Control Insp | General Comments | | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | LTCC000645 | LTCControl | 593-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | LTCMechanism | 593-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | LTCMechanism | 593-1 | LTC Counter Readings | LTC Operations Since Last Insp | 648 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | LTCMechanism | 593-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | LTCMechanism | 593-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | LTCMechanism | 593-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | LTCMechanism | 593-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | LTCMechanism | 593-1 | LTC Counter Readings | General Comments | | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | LTCMechanism | 593-1 | LTC Counter Readings | LTC As Found Counter | 169876 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | LTCMechanism | 593-1 | LTC Counter Readings | LTC As Left Counter | 169876 | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | LTCMechanism | 593-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | LTCMechanism | 593-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | LTCMechanism | 593-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | LTCMechanism | 593-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 35 | °C |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | LTCMechanism | 593-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 25 | °C |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | LTCMechanism | 593-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | LTCMechanism | 593-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | S0053 | WithLTC | 593-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | BAT001633 | Battery | 593-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | BAT001633 | Battery | 593-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 46 | °F |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | BAT001633 | Battery | 593-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | BAT001633 | Battery | 593-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | BAT001633 | Battery | 593-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | BAT001633 | Battery | 593-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | BAT001633 | Battery | 593-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | BAT001633 | Battery | 593-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | BAT001633 | Battery | 593-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | BAT001633 | Battery | 593-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | BAT001633 | Battery | 593-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.0 | VDC |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | BAT001633 | Battery | 593-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | BAT001633 | Battery | 593-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | BCH001582 | Charger | 593-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | BCH001582 | Charger | 593-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | BCH001582 | Charger | 593-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | BCH001582 | Charger | 593-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .3 | amps |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | BCH001582 | Charger | 593-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | BCH001582 | Charger | 593-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | BCH001582 | Charger | 593-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | BCH001582 | Charger | 593-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | General Comments | | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | ST000558 | Structure | 593-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Ambient Temp | 46 | °F |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Clear of Trash? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | General Comments | | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | YD000554 | Yard | 593-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | General Comments | signs need updating | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | n | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/22/2023 10:14 | Distribution | Bardstown Industrial Quarterly Inspection | FE000547 | Fence | 593-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | 0964 | NonLTC | 872-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | 0964 | NonLTC | 872-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | 0964 | NonLTC | 872-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | 0964 | NonLTC | 872-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | 0964 | NonLTC | 872-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | 0964 | NonLTC | 872-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | 0964 | NonLTC | 872-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | 0964 | NonLTC | 872-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | 0964 | NonLTC | 872-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | 0964 | NonLTC | 872-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | 0964 | NonLTC | 872-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 52.50 | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | 0964 | NonLTC | 872-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | 0964 | NonLTC | 872-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | 0964 | NonLTC | 872-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | 0964 | NonLTC | 872-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | 0964 | NonLTC | 872-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | 0964 | NonLTC | 872-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | 0964 | NonLTC | 872-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | 0964 | NonLTC | 872-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | 0964 | NonLTC | 872-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | 0964 | NonLTC | 872-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | 0964 | NonLTC | 872-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | 0964 | NonLTC | 872-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | 0964 | NonLTC | 872-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | 0964 | NonLTC | 872-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | ST000373 | Structure | 872-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | ST000373 | Structure | 872-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | ST000373 | Structure | 872-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | ST000373 | Structure | 872-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | ST000373 | Structure | 872-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | ST000373 | Structure | 872-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | ST000373 | Structure | 872-Structure | Structure Patrol Inspection | General Comments | | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | ST000373 | Structure | 872-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | ST000373 | Structure | 872-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | ST000373 | Structure | 872-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | ST000373 | Structure | 872-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | ST000373 | Structure | 872-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | ST000373 | Structure | 872-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | ST000373 | Structure | 872-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | ST000373 | Structure | 872-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | ST000373 | Structure | 872-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | ST000373 | Structure | 872-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | ST000373 | Structure | 872-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | ST000373 | Structure | 872-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | ST000373 | Structure | 872-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | ST000373 | Structure | 872-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | ST000373 | Structure | 872-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | FE000864 | Fence | 872-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | FE000864 | Fence | 872-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | FE000864 | Fence | 872-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | FE000864 | Fence | 872-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | FE000864 | Fence | 872-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | FE000864 | Fence | 872-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | FE000864 | Fence | 872-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | FE000864 | Fence | 872-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | FE000864 | Fence | 872-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | FE000864 | Fence | 872-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | FE000864 | Fence | 872-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | FE000864 | Fence | 872-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | FE000864 | Fence | 872-Fence | Fence Patrol Inspection | General Comments | | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | FE000864 | Fence | 872-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | FE000864 | Fence | 872-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | FE000864 | Fence | 872-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | YD000371 | Yard | 872-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | YD000371 | Yard | 872-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | YD000371 | Yard | 872-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | YD000371 | Yard | 872-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | YD000371 | Yard | 872-Yard | Yard Patrol Inspection | General Comments | | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | YD000371 | Yard | 872-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | YD000371 | Yard | 872-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | YD000371 | Yard | 872-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | YD000371 | Yard | 872-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | YD000371 | Yard | 872-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | YD000371 | Yard | 872-Yard | Yard Patrol Inspection | Ambient Temp | 44 | °F |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | YD000371 | Yard | 872-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/22/2023 10:15 | Distribution | Sardis Quarterly Inspection | YD000371 | Yard | 872-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0235 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0235 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0235 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0235 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0235 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0235 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0217 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0217 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0217 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0217 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0217 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0217 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0195 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0195 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0195 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0195 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0195 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0195 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0195 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0236 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0236 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0236 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0236 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0236 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0236 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0162 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0162 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0162 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0162 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0162 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0162 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0162 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0194 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0194 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0194 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0194 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0194 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0194 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/22/2023 9:49 | Distribution | Big Stone Gap Storeroom Spare Transformer Quarterly Inspection | O0194 | NonLTC | 977-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | LTCMechanism | WE-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | LTCMechanism | WE-TRANS 1 | LTC Counter Readings | General Comments | | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | LTCMechanism | WE-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 254105 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | LTCMechanism | WE-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 254105 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | LTCMechanism | WE-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | LTCMechanism | WE-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | LTCMechanism | WE-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | LTCMechanism | WE-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 293 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | LTCMechanism | WE-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1151 | BreakerAirMagnetic | WE-6 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1151 | BreakerAirMagnetic | WE-6 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1151 | BreakerAirMagnetic | WE-6 | AMCB Patrol Inspection | General Comments | | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1151 | BreakerAirMagnetic | WE-6 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1151 | BreakerAirMagnetic | WE-6 | AMCB Readings | 9 Month Ops New | 2 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1151 | BreakerAirMagnetic | WE-6 | AMCB Readings | 9 Months Operations | 2 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1151 | BreakerAirMagnetic | WE-6 | AMCB Readings | Switching Operations | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1151 | BreakerAirMagnetic | WE-6 | AMCB Readings | Unknown Operations | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1151 | BreakerAirMagnetic | WE-6 | AMCB Readings | Accumulated Fault Duty A Ph AM | 1.07 | % |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1151 | BreakerAirMagnetic | WE-6 | AMCB Readings | Accumulated Fault Duty B Ph AM | 1.07 | % |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1151 | BreakerAirMagnetic | WE-6 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1151 | BreakerAirMagnetic | WE-6 | AMCB Readings | Amps A Ø | 50.0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1151 | BreakerAirMagnetic | WE-6 | AMCB Readings | Amps B Ø | 50.0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1151 | BreakerAirMagnetic | WE-6 | AMCB Readings | Amps C Ø | 50.0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1151 | BreakerAirMagnetic | WE-6 | AMCB Readings | Operations Counter AF | 424 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1151 | BreakerAirMagnetic | WE-6 | AMCB Readings | Operations Counter AL | 424 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1151 | BreakerAirMagnetic | WE-6 | AMCB Readings | Operations This Read AM | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1151 | BreakerAirMagnetic | WE-6 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1151 | BreakerAirMagnetic | WE-6 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1151 | BreakerAirMagnetic | WE-6 | AMCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1151 | BreakerAirMagnetic | WE-6 | AMCB Readings | General Comments | | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1151 | BreakerAirMagnetic | WE-6 | AMCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1151 | BreakerAirMagnetic | WE-6 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1151 | BreakerAirMagnetic | WE-6 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1151 | BreakerAirMagnetic | WE-6 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1151 | BreakerAirMagnetic | WE-6 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1151 | BreakerAirMagnetic | WE-6 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1150 | BreakerAirMagnetic | WE-5 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1150 | BreakerAirMagnetic | WE-5 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1150 | BreakerAirMagnetic | WE-5 | AMCB Patrol Inspection | General Comments | | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1150 | BreakerAirMagnetic | WE-5 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1150 | BreakerAirMagnetic | WE-5 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1150 | BreakerAirMagnetic | WE-5 | AMCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1150 | BreakerAirMagnetic | WE-5 | AMCB Readings | General Comments | | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1150 | BreakerAirMagnetic | WE-5 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1150 | BreakerAirMagnetic | WE-5 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1150 | BreakerAirMagnetic | WE-5 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1150 | BreakerAirMagnetic | WE-5 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1150 | BreakerAirMagnetic | WE-5 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1150 | BreakerAirMagnetic | WE-5 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1150 | BreakerAirMagnetic | WE-5 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1150 | BreakerAirMagnetic | WE-5 | AMCB Readings | Amps C Ø | 50.0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1150 | BreakerAirMagnetic | WE-5 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1150 | BreakerAirMagnetic | WE-5 | AMCB Readings | 9 Months Operations | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1150 | BreakerAirMagnetic | WE-5 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1150 | BreakerAirMagnetic | WE-5 | AMCB Readings | Amps B Ø | 50.0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1150 | BreakerAirMagnetic | WE-5 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1150 | BreakerAirMagnetic | WE-5 | AMCB Readings | Amps A Ø | 50.0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1150 | BreakerAirMagnetic | WE-5 | AMCB Readings | Operations Counter AF | 1006 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1150 | BreakerAirMagnetic | WE-5 | AMCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1150 | BreakerAirMagnetic | WE-5 | AMCB Readings | Operations Counter AL | 1006 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1150 | BreakerAirMagnetic | WE-5 | AMCB Readings | Operations This Read AM | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1150 | BreakerAirMagnetic | WE-5 | AMCB Readings | Switching Operations | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1150 | BreakerAirMagnetic | WE-5 | AMCB Readings | Unknown Operations | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1147 | BreakerAirMagnetic | WE-4 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1147 | BreakerAirMagnetic | WE-4 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1147 | BreakerAirMagnetic | WE-4 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1147 | BreakerAirMagnetic | WE-4 | AMCB Patrol Inspection | General Comments | | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1147 | BreakerAirMagnetic | WE-4 | AMCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1147 | BreakerAirMagnetic | WE-4 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1147 | BreakerAirMagnetic | WE-4 | AMCB Readings | Operations This Read AM | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1147 | BreakerAirMagnetic | WE-4 | AMCB Readings | General Comments | | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1147 | BreakerAirMagnetic | WE-4 | AMCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1147 | BreakerAirMagnetic | WE-4 | AMCB Readings | Switching Operations | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1147 | BreakerAirMagnetic | WE-4 | AMCB Readings | Unknown Operations | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1147 | BreakerAirMagnetic | WE-4 | AMCB Readings | Amps B Ø | 180.0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1147 | BreakerAirMagnetic | WE-4 | AMCB Readings | Amps C Ø | 170.0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1147 | BreakerAirMagnetic | WE-4 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1147 | BreakerAirMagnetic | WE-4 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1147 | BreakerAirMagnetic | WE-4 | AMCB Readings | Amps A Ø | 150.0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1147 | BreakerAirMagnetic | WE-4 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1147 | BreakerAirMagnetic | WE-4 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1147 | BreakerAirMagnetic | WE-4 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1147 | BreakerAirMagnetic | WE-4 | AMCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1147 | BreakerAirMagnetic | WE-4 | AMCB Readings | Operations Counter AF | 612 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1147 | BreakerAirMagnetic | WE-4 | AMCB Readings | Operations Counter AL | 612 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1147 | BreakerAirMagnetic | WE-4 | AMCB Readings | Accumulated Fault Duty C Ph AM | 1.07 | % |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1147 | BreakerAirMagnetic | WE-4 | AMCB Readings | Accumulated Fault Duty B Ph AM | 1.07 | % |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1147 | BreakerAirMagnetic | WE-4 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1147 | BreakerAirMagnetic | WE-4 | AMCB Readings | 9 Months Operations | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1147 | BreakerAirMagnetic | WE-4 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1146 | BreakerAirMagnetic | WE-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1146 | BreakerAirMagnetic | WE-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1146 | BreakerAirMagnetic | WE-3 | AMCB Patrol Inspection | General Comments | | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1146 | BreakerAirMagnetic | WE-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1146 | BreakerAirMagnetic | WE-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 35.22 | % |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1146 | BreakerAirMagnetic | WE-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 46.96 | % |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1146 | BreakerAirMagnetic | WE-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 30.95 | % |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1146 | BreakerAirMagnetic | WE-3 | AMCB Readings | Amps A Ø | 175.0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1146 | BreakerAirMagnetic | WE-3 | AMCB Readings | Amps B Ø | 230.0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1146 | BreakerAirMagnetic | WE-3 | AMCB Readings | Amps C Ø | 250.0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1146 | BreakerAirMagnetic | WE-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1146 | BreakerAirMagnetic | WE-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1146 | BreakerAirMagnetic | WE-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1146 | BreakerAirMagnetic | WE-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1146 | BreakerAirMagnetic | WE-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1146 | BreakerAirMagnetic | WE-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1146 | BreakerAirMagnetic | WE-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1146 | BreakerAirMagnetic | WE-3 | AMCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1146 | BreakerAirMagnetic | WE-3 | AMCB Readings | General Comments | | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1146 | BreakerAirMagnetic | WE-3 | AMCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1146 | BreakerAirMagnetic | WE-3 | AMCB Readings | Operations Counter AF | 491 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1146 | BreakerAirMagnetic | WE-3 | AMCB Readings | Operations Counter AL | 491 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1146 | BreakerAirMagnetic | WE-3 | AMCB Readings | Operations This Read AM | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1146 | BreakerAirMagnetic | WE-3 | AMCB Readings | Switching Operations | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1146 | BreakerAirMagnetic | WE-3 | AMCB Readings | Unknown Operations | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1146 | BreakerAirMagnetic | WE-3 | AMCB Readings | 9 Months Operations | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1146 | BreakerAirMagnetic | WE-3 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1145 | BreakerAirMagnetic | WE-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1145 | BreakerAirMagnetic | WE-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1145 | BreakerAirMagnetic | WE-2 | AMCB Patrol Inspection | General Comments | | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1145 | BreakerAirMagnetic | WE-2 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1145 | BreakerAirMagnetic | WE-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1145 | BreakerAirMagnetic | WE-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1145 | BreakerAirMagnetic | WE-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1145 | BreakerAirMagnetic | WE-2 | AMCB Readings | Amps C Ø | 120.0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1145 | BreakerAirMagnetic | WE-2 | AMCB Readings | Unknown Operations | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1145 | BreakerAirMagnetic | WE-2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1145 | BreakerAirMagnetic | WE-2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1145 | BreakerAirMagnetic | WE-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1145 | BreakerAirMagnetic | WE-2 | AMCB Readings | Switching Operations | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1145 | BreakerAirMagnetic | WE-2 | AMCB Readings | Operations This Read AM | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1145 | BreakerAirMagnetic | WE-2 | AMCB Readings | Amps B Ø | 180.0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1145 | BreakerAirMagnetic | WE-2 | AMCB Readings | Operations Counter AL | 430 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1145 | BreakerAirMagnetic | WE-2 | AMCB Readings | Operations Counter AF | 430 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1145 | BreakerAirMagnetic | WE-2 | AMCB Readings | Amps A Ø | 150.0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1145 | BreakerAirMagnetic | WE-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1145 | BreakerAirMagnetic | WE-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 3.2 | % |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1145 | BreakerAirMagnetic | WE-2 | AMCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1145 | BreakerAirMagnetic | WE-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 6.4 | % |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1145 | BreakerAirMagnetic | WE-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 6.4 | % |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1145 | BreakerAirMagnetic | WE-2 | AMCB Readings | 9 Months Operations | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1145 | BreakerAirMagnetic | WE-2 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1145 | BreakerAirMagnetic | WE-2 | AMCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1145 | BreakerAirMagnetic | WE-2 | AMCB Readings | General Comments | | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1144 | BreakerAirMagnetic | WE-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1144 | BreakerAirMagnetic | WE-1 | AMCB Patrol Inspection | General Comments | | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1144 | BreakerAirMagnetic | WE-1 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1144 | BreakerAirMagnetic | WE-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1144 | BreakerAirMagnetic | WE-1 | AMCB Readings | Operations Counter AF | 552 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1144 | BreakerAirMagnetic | WE-1 | AMCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1144 | BreakerAirMagnetic | WE-1 | AMCB Readings | General Comments | | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1144 | BreakerAirMagnetic | WE-1 | AMCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1144 | BreakerAirMagnetic | WE-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1144 | BreakerAirMagnetic | WE-1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1144 | BreakerAirMagnetic | WE-1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1144 | BreakerAirMagnetic | WE-1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1144 | BreakerAirMagnetic | WE-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1144 | BreakerAirMagnetic | WE-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1144 | BreakerAirMagnetic | WE-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1144 | BreakerAirMagnetic | WE-1 | AMCB Readings | Amps C Ø | 380.0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1144 | BreakerAirMagnetic | WE-1 | AMCB Readings | Amps B Ø | 370.0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1144 | BreakerAirMagnetic | WE-1 | AMCB Readings | Amps A Ø | 390.0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1144 | BreakerAirMagnetic | WE-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1144 | BreakerAirMagnetic | WE-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1144 | BreakerAirMagnetic | WE-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 1.07 | % |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1144 | BreakerAirMagnetic | WE-1 | AMCB Readings | Unknown Operations | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1144 | BreakerAirMagnetic | WE-1 | AMCB Readings | Switching Operations | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1144 | BreakerAirMagnetic | WE-1 | AMCB Readings | Operations This Read AM | 0 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1144 | BreakerAirMagnetic | WE-1 | AMCB Readings | 9 Months Operations | 1 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1144 | BreakerAirMagnetic | WE-1 | AMCB Readings | 9 Month Ops New | 1 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | LB1144 | BreakerAirMagnetic | WE-1 | AMCB Readings | Operations Counter AL | 552 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | LTCMechanism | WE-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | LTCMechanism | WE-TRANS 2 | LTC Counter Readings | General Comments | | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | LTCMechanism | WE-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 33419 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | LTCMechanism | WE-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 33419 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | LTCMechanism | WE-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | LTCMechanism | WE-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 5L | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | LTCMechanism | WE-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | LTCMechanism | WE-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 980 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | LTCMechanism | WE-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | LTCMechanism | WE-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | LTCMechanism | WE-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Low | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | LTCMechanism | WE-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | LTCMechanism | WE-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | LTCMechanism | WE-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | LTCMechanism | WE-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | LTCMechanism | WE-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 200.00 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Readings | MegaVar Demand Meter Max | .50 | MegaVars |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Readings | MegaVar Demand Meter Min | 0.00 | MegaVars |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Readings | MegaWatt Demand Meter Min | 1.00 | MegaWatts |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN64 | WithLTC | WE-TRANS 2 | LTC Transformer Readings | MegaWatt Demand Meter Max | 0.00 | MegaWatts |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | LTCMechanism | WE-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | LTCMechanism | WE-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Low | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | LTCMechanism | WE-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | LTCMechanism | WE-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | LTCMechanism | WE-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | LTCMechanism | WE-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | LTCMechanism | WE-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Readings | MegaVar Demand Meter Max | .25 | MegaVars |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Readings | MegaVar Demand Meter Min | -.15 | MegaVars |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Readings | MegaWatt Demand Meter Max | 3.00 | MegaWatts |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Readings | MegaWatt Demand Meter Min | 1.90 | MegaWatts |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 10 | °C |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PN69 | WithLTC | WE-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000040 | Switchgear | WE-Swgr Sec 2 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000040 | Switchgear | WE-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000040 | Switchgear | WE-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000040 | Switchgear | WE-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000040 | Switchgear | WE-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000040 | Switchgear | WE-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000040 | Switchgear | WE-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000040 | Switchgear | WE-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000040 | Switchgear | WE-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000040 | Switchgear | WE-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000040 | Switchgear | WE-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000040 | Switchgear | WE-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000040 | Switchgear | WE-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000040 | Switchgear | WE-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000040 | Switchgear | WE-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000040 | Switchgear | WE-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000040 | Switchgear | WE-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000040 | Switchgear | WE-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000040 | Switchgear | WE-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000040 | Switchgear | WE-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000041 | Switchgear | WE-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000041 | Switchgear | WE-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000041 | Switchgear | WE-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000041 | Switchgear | WE-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000041 | Switchgear | WE-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000041 | Switchgear | WE-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000041 | Switchgear | WE-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000041 | Switchgear | WE-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000041 | Switchgear | WE-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000041 | Switchgear | WE-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000041 | Switchgear | WE-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000041 | Switchgear | WE-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000041 | Switchgear | WE-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000041 | Switchgear | WE-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000041 | Switchgear | WE-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000041 | Switchgear | WE-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000041 | Switchgear | WE-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000041 | Switchgear | WE-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000041 | Switchgear | WE-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | SWG000041 | Switchgear | WE-Swgr Sec 1 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | BCH000093 | Charger | WE-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | BCH000093 | Charger | WE-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.9 | VDC |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | BCH000093 | Charger | WE-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.9 | VDC |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | BCH000093 | Charger | WE-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .7 | amps |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | BCH000093 | Charger | WE-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | BCH000093 | Charger | WE-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | BCH000093 | Charger | WE-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | BAT001293 | Battery | WE-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | BAT001293 | Battery | WE-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | BAT001293 | Battery | WE-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | BAT001293 | Battery | WE-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | BAT001293 | Battery | WE-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | BAT001293 | Battery | WE-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | BAT001293 | Battery | WE-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | BAT001293 | Battery | WE-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | BAT001293 | Battery | WE-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | BAT001293 | Battery | WE-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | BAT001293 | Battery | WE-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | BAT001293 | Battery | WE-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | BAT001293 | Battery | WE-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | BAT001293 | Battery | WE-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | CH000448 | ControlHouse | WE-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | CH000448 | ControlHouse | WE-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | CH000448 | ControlHouse | WE-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | CH000448 | ControlHouse | WE-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | CH000448 | ControlHouse | WE-Battery Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | CH000448 | ControlHouse | WE-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | CH000448 | ControlHouse | WE-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | CH000448 | ControlHouse | WE-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | CH000448 | ControlHouse | WE-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | YD000610 | Yard | WE-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | YD000610 | Yard | WE-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | YD000610 | Yard | WE-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | YD000610 | Yard | WE-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | YD000610 | Yard | WE-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | YD000610 | Yard | WE-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | YD000610 | Yard | WE-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | YD000610 | Yard | WE-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | YD000610 | Yard | WE-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | YD000610 | Yard | WE-Yard | Yard Patrol Inspection | Ambient Temp | 52 | °F |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | YD000610 | Yard | WE-Yard | Yard Patrol Inspection | General Comments | | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | YD000610 | Yard | WE-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | YD000610 | Yard | WE-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | YD000610 | Yard | WE-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | YD000610 | Yard | WE-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | YD000610 | Yard | WE-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | YD000610 | Yard | WE-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | YD000610 | Yard | WE-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | YD000610 | Yard | WE-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | YD000610 | Yard | WE-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0892 | BreakerAirMagnetic | SP-12KV BUS TIE SEC 2 | AMCB Readings | Unknown Operations | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0892 | BreakerAirMagnetic | SP-12KV BUS TIE SEC 2 | AMCB Readings | Switching Operations | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0892 | BreakerAirMagnetic | SP-12KV BUS TIE SEC 2 | AMCB Readings | Operations This Read AM | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0892 | BreakerAirMagnetic | SP-12KV BUS TIE SEC 2 | AMCB Readings | Operations Counter AL | 81 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0892 | BreakerAirMagnetic | SP-12KV BUS TIE SEC 2 | AMCB Readings | Operations Counter AF | 81 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0892 | BreakerAirMagnetic | SP-12KV BUS TIE SEC 2 | AMCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0892 | BreakerAirMagnetic | SP-12KV BUS TIE SEC 2 | AMCB Readings | General Comments | | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0892 | BreakerAirMagnetic | SP-12KV BUS TIE SEC 2 | AMCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0892 | BreakerAirMagnetic | SP-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0892 | BreakerAirMagnetic | SP-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0892 | BreakerAirMagnetic | SP-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0892 | BreakerAirMagnetic | SP-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0892 | BreakerAirMagnetic | SP-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0892 | BreakerAirMagnetic | SP-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0892 | BreakerAirMagnetic | SP-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0892 | BreakerAirMagnetic | SP-12KV BUS TIE SEC 2 | AMCB Readings | Amps C Ø | 0.0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0892 | BreakerAirMagnetic | SP-12KV BUS TIE SEC 2 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0892 | BreakerAirMagnetic | SP-12KV BUS TIE SEC 2 | AMCB Readings | 9 Months Operations | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0892 | BreakerAirMagnetic | SP-12KV BUS TIE SEC 2 | AMCB Readings | Amps B Ø | 0.0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0892 | BreakerAirMagnetic | SP-12KV BUS TIE SEC 2 | AMCB Readings | Amps A Ø | 0.0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0892 | BreakerAirMagnetic | SP-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0892 | BreakerAirMagnetic | SP-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0892 | BreakerAirMagnetic | SP-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0892 | BreakerAirMagnetic | SP-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0892 | BreakerAirMagnetic | SP-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0892 | BreakerAirMagnetic | SP-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | General Comments | | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0891 | BreakerAirMagnetic | SP-1117 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0891 | BreakerAirMagnetic | SP-1117 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0891 | BreakerAirMagnetic | SP-1117 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0891 | BreakerAirMagnetic | SP-1117 | AMCB Readings | General Comments | | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0891 | BreakerAirMagnetic | SP-1117 | AMCB Readings | Amps B Ø | 50.0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0891 | BreakerAirMagnetic | SP-1117 | AMCB Readings | Amps A Ø | 50.0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0891 | BreakerAirMagnetic | SP-1117 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0891 | BreakerAirMagnetic | SP-1117 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0891 | BreakerAirMagnetic | SP-1117 | AMCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0891 | BreakerAirMagnetic | SP-1117 | AMCB Readings | Operations Counter AF | 241 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0891 | BreakerAirMagnetic | SP-1117 | AMCB Readings | Operations Counter AL | 241 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0891 | BreakerAirMagnetic | SP-1117 | AMCB Readings | Operations This Read AM | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0891 | BreakerAirMagnetic | SP-1117 | AMCB Readings | Switching Operations | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0891 | BreakerAirMagnetic | SP-1117 | AMCB Readings | Unknown Operations | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0891 | BreakerAirMagnetic | SP-1117 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0891 | BreakerAirMagnetic | SP-1117 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0891 | BreakerAirMagnetic | SP-1117 | AMCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0891 | BreakerAirMagnetic | SP-1117 | AMCB Readings | Accumulated Fault Duty B Ph AM | 3.64 | % |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0891 | BreakerAirMagnetic | SP-1117 | AMCB Readings | Accumulated Fault Duty A Ph AM | 2.43 | % |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0891 | BreakerAirMagnetic | SP-1117 | AMCB Readings | 9 Months Operations | 4 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0891 | BreakerAirMagnetic | SP-1117 | AMCB Readings | 9 Month Ops New | 4 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0891 | BreakerAirMagnetic | SP-1117 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0891 | BreakerAirMagnetic | SP-1117 | AMCB Readings | Amps C Ø | 50.0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0891 | BreakerAirMagnetic | SP-1117 | AMCB Patrol Inspection | General Comments | | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0891 | BreakerAirMagnetic | SP-1117 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0891 | BreakerAirMagnetic | SP-1117 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0890 | BreakerAirMagnetic | SP-1116 | AMCB Readings | 9 Month Ops New | 5 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0890 | BreakerAirMagnetic | SP-1116 | AMCB Readings | 9 Months Operations | 5 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0890 | BreakerAirMagnetic | SP-1116 | AMCB Readings | Accumulated Fault Duty A Ph AM | 26.69 | % |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0890 | BreakerAirMagnetic | SP-1116 | AMCB Readings | Accumulated Fault Duty B Ph AM | 20.63 | % |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0890 | BreakerAirMagnetic | SP-1116 | AMCB Readings | Unknown Operations | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0890 | BreakerAirMagnetic | SP-1116 | AMCB Readings | Switching Operations | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0890 | BreakerAirMagnetic | SP-1116 | AMCB Readings | Operations This Read AM | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0890 | BreakerAirMagnetic | SP-1116 | AMCB Readings | Operations Counter AL | 447 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0890 | BreakerAirMagnetic | SP-1116 | AMCB Readings | Accumulated Fault Duty C Ph AM | 4.85 | % |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0890 | BreakerAirMagnetic | SP-1116 | AMCB Readings | Amps A Ø | 160.0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0890 | BreakerAirMagnetic | SP-1116 | AMCB Readings | Amps B Ø | 190.0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0890 | BreakerAirMagnetic | SP-1116 | AMCB Readings | Amps C Ø | 170.0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0890 | BreakerAirMagnetic | SP-1116 | AMCB Readings | Operations Counter AF | 447 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0890 | BreakerAirMagnetic | SP-1116 | AMCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0890 | BreakerAirMagnetic | SP-1116 | AMCB Readings | General Comments | | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0890 | BreakerAirMagnetic | SP-1116 | AMCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0890 | BreakerAirMagnetic | SP-1116 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0890 | BreakerAirMagnetic | SP-1116 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0890 | BreakerAirMagnetic | SP-1116 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0890 | BreakerAirMagnetic | SP-1116 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0890 | BreakerAirMagnetic | SP-1116 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0890 | BreakerAirMagnetic | SP-1116 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0890 | BreakerAirMagnetic | SP-1116 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0890 | BreakerAirMagnetic | SP-1116 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0890 | BreakerAirMagnetic | SP-1116 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0890 | BreakerAirMagnetic | SP-1116 | AMCB Patrol Inspection | General Comments | | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0889 | BreakerAirMagnetic | SP-1115 | AMCB Readings | 9 Months Operations | 10 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0889 | BreakerAirMagnetic | SP-1115 | AMCB Readings | 9 Month Ops New | 5 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0889 | BreakerAirMagnetic | SP-1115 | AMCB Readings | Unknown Operations | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0889 | BreakerAirMagnetic | SP-1115 | AMCB Readings | Switching Operations | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0889 | BreakerAirMagnetic | SP-1115 | AMCB Readings | Operations This Read AM | 5 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0889 | BreakerAirMagnetic | SP-1115 | AMCB Readings | Operations Counter AL | 2846 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0889 | BreakerAirMagnetic | SP-1115 | AMCB Readings | Operations Counter AF | 2846 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0889 | BreakerAirMagnetic | SP-1115 | AMCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0889 | BreakerAirMagnetic | SP-1115 | AMCB Readings | General Comments | ABC Phase IOC | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0889 | BreakerAirMagnetic | SP-1115 | AMCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0889 | BreakerAirMagnetic | SP-1115 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0889 | BreakerAirMagnetic | SP-1115 | AMCB Readings | Fault Operations C Ø | 2 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0889 | BreakerAirMagnetic | SP-1115 | AMCB Readings | Fault Operations B Ø | 2 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0889 | BreakerAirMagnetic | SP-1115 | AMCB Readings | Fault Operations A Ø | 1 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0889 | BreakerAirMagnetic | SP-1115 | AMCB Readings | Fault Adjusted Amps C Phase AM | 22.36 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0889 | BreakerAirMagnetic | SP-1115 | AMCB Readings | Accumulated Fault Duty A Ph AM | 3.64 | % |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0889 | BreakerAirMagnetic | SP-1115 | AMCB Readings | Accumulated Fault Duty B Ph AM | 6.07 | % |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0889 | BreakerAirMagnetic | SP-1115 | AMCB Readings | Accumulated Fault Duty C Ph AM | 3.64 | % |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0889 | BreakerAirMagnetic | SP-1115 | AMCB Readings | Amps A Ø | 170.0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0889 | BreakerAirMagnetic | SP-1115 | AMCB Readings | Fault Adjusted Amps B Phase AM | 22.36 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0889 | BreakerAirMagnetic | SP-1115 | AMCB Readings | Fault Adjusted Amps A Phase AM | 11.18 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0889 | BreakerAirMagnetic | SP-1115 | AMCB Readings | Amps B Ø | 170.0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0889 | BreakerAirMagnetic | SP-1115 | AMCB Readings | Amps C Ø | 170.0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0889 | BreakerAirMagnetic | SP-1115 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0889 | BreakerAirMagnetic | SP-1115 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0889 | BreakerAirMagnetic | SP-1115 | AMCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0888 | BreakerAirMagnetic | SP-1114 | AMCB Readings | Unknown Operations | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0888 | BreakerAirMagnetic | SP-1114 | AMCB Readings | Switching Operations | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0888 | BreakerAirMagnetic | SP-1114 | AMCB Readings | Operations This Read AM | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0888 | BreakerAirMagnetic | SP-1114 | AMCB Readings | 9 Month Ops New | 3 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0888 | BreakerAirMagnetic | SP-1114 | AMCB Readings | 9 Months Operations | 3 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0888 | BreakerAirMagnetic | SP-1114 | AMCB Readings | Accumulated Fault Duty A Ph AM | 3.64 | % |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0888 | BreakerAirMagnetic | SP-1114 | AMCB Readings | Accumulated Fault Duty B Ph AM | 3.64 | % |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0888 | BreakerAirMagnetic | SP-1114 | AMCB Readings | Accumulated Fault Duty C Ph AM | 3.64 | % |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0888 | BreakerAirMagnetic | SP-1114 | AMCB Readings | Amps A Ø | 100.0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0888 | BreakerAirMagnetic | SP-1114 | AMCB Readings | Amps B Ø | 160.0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0888 | BreakerAirMagnetic | SP-1114 | AMCB Readings | Amps C Ø | 100.0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0888 | BreakerAirMagnetic | SP-1114 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0888 | BreakerAirMagnetic | SP-1114 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0888 | BreakerAirMagnetic | SP-1114 | AMCB Readings | Operations Counter AL | 114 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0888 | BreakerAirMagnetic | SP-1114 | AMCB Readings | Operations Counter AF | 114 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0888 | BreakerAirMagnetic | SP-1114 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0888 | BreakerAirMagnetic | SP-1114 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0888 | BreakerAirMagnetic | SP-1114 | AMCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0888 | BreakerAirMagnetic | SP-1114 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0888 | BreakerAirMagnetic | SP-1114 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0888 | BreakerAirMagnetic | SP-1114 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0888 | BreakerAirMagnetic | SP-1114 | AMCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0888 | BreakerAirMagnetic | SP-1114 | AMCB Readings | General Comments | | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0888 | BreakerAirMagnetic | SP-1114 | AMCB Patrol Inspection | General Comments | | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0888 | BreakerAirMagnetic | SP-1114 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0888 | BreakerAirMagnetic | SP-1114 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0893 | BreakerAirMagnetic | SP-12KV TR 2 | AMCB Readings | 9 Months Operations | 5 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0893 | BreakerAirMagnetic | SP-12KV TR 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 2.6 | % |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0893 | BreakerAirMagnetic | SP-12KV TR 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 2.6 | % |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0893 | BreakerAirMagnetic | SP-12KV TR 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0893 | BreakerAirMagnetic | SP-12KV TR 2 | AMCB Readings | Operations Counter AL | 151 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0893 | BreakerAirMagnetic | SP-12KV TR 2 | AMCB Readings | Operations This Read AM | 2 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0893 | BreakerAirMagnetic | SP-12KV TR 2 | AMCB Readings | 9 Month Ops New | 3 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0893 | BreakerAirMagnetic | SP-12KV TR 2 | AMCB Readings | Amps C Ø | 388.0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0893 | BreakerAirMagnetic | SP-12KV TR 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 54.00 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0893 | BreakerAirMagnetic | SP-12KV TR 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 54.00 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0893 | BreakerAirMagnetic | SP-12KV TR 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 54.00 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0893 | BreakerAirMagnetic | SP-12KV TR 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0893 | BreakerAirMagnetic | SP-12KV TR 2 | AMCB Readings | Amps A Ø | 409.0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0893 | BreakerAirMagnetic | SP-12KV TR 2 | AMCB Readings | Amps B Ø | 440.0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0893 | BreakerAirMagnetic | SP-12KV TR 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0893 | BreakerAirMagnetic | SP-12KV TR 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0893 | BreakerAirMagnetic | SP-12KV TR 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0893 | BreakerAirMagnetic | SP-12KV TR 2 | AMCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0893 | BreakerAirMagnetic | SP-12KV TR 2 | AMCB Readings | General Comments | | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0893 | BreakerAirMagnetic | SP-12KV TR 2 | AMCB Readings | Switching Operations | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0893 | BreakerAirMagnetic | SP-12KV TR 2 | AMCB Readings | Unknown Operations | 2 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0893 | BreakerAirMagnetic | SP-12KV TR 2 | AMCB Readings | Operations Counter AF | 151 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0893 | BreakerAirMagnetic | SP-12KV TR 2 | AMCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0893 | BreakerAirMagnetic | SP-12KV TR 2 | AMCB Patrol Inspection | General Comments | | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0893 | BreakerAirMagnetic | SP-12KV TR 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LB0893 | BreakerAirMagnetic | SP-12KV TR 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | PF000334 | PowerFuse | SP-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | PF000334 | PowerFuse | SP-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | PF000334 | PowerFuse | SP-12KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | PF000333 | PowerFuse | SP-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | PF000333 | PowerFuse | SP-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | PF000333 | PowerFuse | SP-STA SER NO 2 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000100 | Switchgear | SP-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000100 | Switchgear | SP-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000100 | Switchgear | SP-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000100 | Switchgear | SP-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000100 | Switchgear | SP-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000100 | Switchgear | SP-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000100 | Switchgear | SP-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000100 | Switchgear | SP-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000100 | Switchgear | SP-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000100 | Switchgear | SP-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000100 | Switchgear | SP-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000100 | Switchgear | SP-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000100 | Switchgear | SP-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000100 | Switchgear | SP-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000100 | Switchgear | SP-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000100 | Switchgear | SP-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000100 | Switchgear | SP-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000100 | Switchgear | SP-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000100 | Switchgear | SP-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LTCC000567 | LTCControl | SP-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LTCC000567 | LTCControl | SP-TRANS 2 | LTC Control Insp | General Comments | ok | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | LTCMechanism | SP-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | LTCMechanism | SP-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 450 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | LTCMechanism | SP-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 15L | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | LTCMechanism | SP-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 15R | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | LTCMechanism | SP-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 10L | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | LTCMechanism | SP-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 233719 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | LTCMechanism | SP-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 233719 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | LTCMechanism | SP-TRANS 2 | LTC Counter Readings | General Comments | | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | LTCMechanism | SP-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | LTCMechanism | SP-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | LTCMechanism | SP-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | LTCMechanism | SP-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | LTCMechanism | SP-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | LTCMechanism | SP-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 40 | °C |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 26 | °C |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 40 | °C |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 26 | °C |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 40 | °C |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 39 | °C |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 26 | °C |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0174 | WithLTC | SP-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000179 | Switchgear | SP-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000179 | Switchgear | SP-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000179 | Switchgear | SP-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000179 | Switchgear | SP-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000179 | Switchgear | SP-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000179 | Switchgear | SP-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000179 | Switchgear | SP-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000179 | Switchgear | SP-Swgr Sec 1 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000179 | Switchgear | SP-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000179 | Switchgear | SP-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000179 | Switchgear | SP-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000179 | Switchgear | SP-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000179 | Switchgear | SP-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000179 | Switchgear | SP-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000179 | Switchgear | SP-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000179 | Switchgear | SP-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000179 | Switchgear | SP-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000179 | Switchgear | SP-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000179 | Switchgear | SP-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | SWG000179 | Switchgear | SP-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Readings | Oil Temp Present | 10 | °C |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 245.00 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Readings | General Comments | | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 256.67 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | LT0175 | NonLTC | SP-TRANS 3 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Readings | Operations This Read Vac | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Readings | Operations Counter AL | 722 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Readings | Operations Counter AF | 772 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Readings | General Comments | | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Readings | Amps C Ø | 25.0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Readings | Amps B Ø | 25.0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Readings | Amps A Ø | 25.0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Readings | Accumulated Fault Duty C Ph V | 2.09 | % |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Readings | Accumulated Fault Duty B Ph V | 3.07 | % |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Readings | Switching Operations | 0 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Readings | Accumulated Fault Duty A Ph V | 2.37 | % |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Readings | 9 Month Operations VCB New | 22 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Readings | 9 Month Operations | 22 | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | KB0035 | BreakerVacuum | SP-3302 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | ST000582 | Structure | SP-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | ST000582 | Structure | SP-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | ST000582 | Structure | SP-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | ST000582 | Structure | SP-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | ST000582 | Structure | SP-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | ST000582 | Structure | SP-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | ST000582 | Structure | SP-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | ST000582 | Structure | SP-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | ST000582 | Structure | SP-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | ST000582 | Structure | SP-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | ST000582 | Structure | SP-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | ST000582 | Structure | SP-Structure | Structure Patrol Inspection | General Comments | | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | ST000582 | Structure | SP-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | ST000582 | Structure | SP-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | ST000582 | Structure | SP-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | ST000582 | Structure | SP-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | ST000582 | Structure | SP-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | ST000582 | Structure | SP-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | ST000582 | Structure | SP-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | ST000582 | Structure | SP-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | ST000582 | Structure | SP-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | ST000582 | Structure | SP-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | YD000582 | Yard | SP-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | YD000582 | Yard | SP-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | YD000582 | Yard | SP-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | YD000582 | Yard | SP-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | YD000582 | Yard | SP-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | YD000582 | Yard | SP-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | YD000582 | Yard | SP-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | YD000582 | Yard | SP-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | YD000582 | Yard | SP-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | YD000582 | Yard | SP-Yard | Yard Patrol Inspection | General Comments | | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | YD000582 | Yard | SP-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | YD000582 | Yard | SP-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | YD000582 | Yard | SP-Yard | Yard Patrol Inspection | Ambient Temp | 43 | °F |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | YD000582 | Yard | SP-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | YD000582 | Yard | SP-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | YD000582 | Yard | SP-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | YD000582 | Yard | SP-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | FE000576 | Fence | SP-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | FE000576 | Fence | SP-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | FE000576 | Fence | SP-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | FE000576 | Fence | SP-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | FE000576 | Fence | SP-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | FE000576 | Fence | SP-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | FE000576 | Fence | SP-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | FE000576 | Fence | SP-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | FE000576 | Fence | SP-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | FE000576 | Fence | SP-Fence | Fence Patrol Inspection | General Comments | | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | FE000576 | Fence | SP-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | FE000576 | Fence | SP-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | FE000576 | Fence | SP-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | FE000576 | Fence | SP-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | FE000576 | Fence | SP-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | FE000576 | Fence | SP-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | BCH001089 | Charger | SP-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | BCH001089 | Charger | SP-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | BCH001089 | Charger | SP-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | BCH001089 | Charger | SP-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 3.8 | amps |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | BCH001089 | Charger | SP-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | BCH001089 | Charger | SP-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | BCH001089 | Charger | SP-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | BAT001509 | Battery | SP-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | BAT001509 | Battery | SP-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | BAT001509 | Battery | SP-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | BAT001509 | Battery | SP-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | BAT001509 | Battery | SP-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | BAT001509 | Battery | SP-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | BAT001509 | Battery | SP-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | BAT001509 | Battery | SP-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | BAT001509 | Battery | SP-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | BAT001509 | Battery | SP-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | BAT001509 | Battery | SP-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | BAT001509 | Battery | SP-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | BAT001509 | Battery | SP-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | BAT001509 | Battery | SP-Battery Bank | Battery Patrol Inspection | Bat Volt 1Min After Chgr Trip | 51.4 | VDC |
| 3/22/2023 9:14 | Distribution | South Park Quarterly Inspection | BAT001509 | Battery | SP-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0859 | BreakerSF6 | SH-1284 | GCB Readings | Operations This Read SF6 | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0859 | BreakerSF6 | SH-1284 | GCB Readings | Operations Counter AL | 111 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0859 | BreakerSF6 | SH-1284 | GCB Readings | Operations Counter AF | 111 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0859 | BreakerSF6 | SH-1284 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0859 | BreakerSF6 | SH-1284 | GCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0859 | BreakerSF6 | SH-1284 | GCB Readings | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0859 | BreakerSF6 | SH-1284 | GCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0859 | BreakerSF6 | SH-1284 | GCB Readings | Fault Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0859 | BreakerSF6 | SH-1284 | GCB Readings | Amps C Ø | 79.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0859 | BreakerSF6 | SH-1284 | GCB Readings | Amps B Ø | 72.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0859 | BreakerSF6 | SH-1284 | GCB Readings | Amps A Ø | 67.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0859 | BreakerSF6 | SH-1284 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0859 | BreakerSF6 | SH-1284 | GCB Readings | Unknown Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0859 | BreakerSF6 | SH-1284 | GCB Readings | Switching Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0859 | BreakerSF6 | SH-1284 | GCB Patrol Inspection | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0859 | BreakerSF6 | SH-1284 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0859 | BreakerSF6 | SH-1284 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0858 | BreakerSF6 | SH-1283 | GCB Readings | Fault Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0858 | BreakerSF6 | SH-1283 | GCB Readings | 9 Month Operations GCB New | 17 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0858 | BreakerSF6 | SH-1283 | GCB Readings | Amps A Ø | 146.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0858 | BreakerSF6 | SH-1283 | GCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0858 | BreakerSF6 | SH-1283 | GCB Readings | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0858 | BreakerSF6 | SH-1283 | GCB Readings | Amps B Ø | 130.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0858 | BreakerSF6 | SH-1283 | GCB Readings | Amps C Ø | 141.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0858 | BreakerSF6 | SH-1283 | GCB Readings | Unknown Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0858 | BreakerSF6 | SH-1283 | GCB Readings | Switching Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0858 | BreakerSF6 | SH-1283 | GCB Readings | Operations This Read SF6 | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0858 | BreakerSF6 | SH-1283 | GCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0858 | BreakerSF6 | SH-1283 | GCB Readings | Num Operations Last 9 Months | 17 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0858 | BreakerSF6 | SH-1283 | GCB Readings | Operations Counter AL | 824 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0858 | BreakerSF6 | SH-1283 | GCB Readings | Operations Counter AF | 824 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0858 | BreakerSF6 | SH-1283 | GCB Patrol Inspection | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0858 | BreakerSF6 | SH-1283 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0858 | BreakerSF6 | SH-1283 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0862 | BreakerSF6 | SH-12KV TR 2 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0862 | BreakerSF6 | SH-12KV TR 2 | GCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0862 | BreakerSF6 | SH-12KV TR 2 | GCB Readings | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0862 | BreakerSF6 | SH-12KV TR 2 | GCB Readings | Operations This Read SF6 | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0862 | BreakerSF6 | SH-12KV TR 2 | GCB Readings | Switching Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0862 | BreakerSF6 | SH-12KV TR 2 | GCB Readings | Unknown Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0862 | BreakerSF6 | SH-12KV TR 2 | GCB Readings | Amps C Ø | 486.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0862 | BreakerSF6 | SH-12KV TR 2 | GCB Readings | Amps A Ø | 482.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0862 | BreakerSF6 | SH-12KV TR 2 | GCB Readings | Fault Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0862 | BreakerSF6 | SH-12KV TR 2 | GCB Readings | Operations Counter AF | 1469 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0862 | BreakerSF6 | SH-12KV TR 2 | GCB Readings | Operations Counter AL | 1469 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0862 | BreakerSF6 | SH-12KV TR 2 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0862 | BreakerSF6 | SH-12KV TR 2 | GCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0862 | BreakerSF6 | SH-12KV TR 2 | GCB Readings | Amps B Ø | 450.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0862 | BreakerSF6 | SH-12KV TR 2 | GCB Patrol Inspection | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0862 | BreakerSF6 | SH-12KV TR 2 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0862 | BreakerSF6 | SH-12KV TR 2 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | PF000359 | PowerFuse | SH-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | PF000359 | PowerFuse | SH-12KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | PF000359 | PowerFuse | SH-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | PF000358 | PowerFuse | SH-STA SER NO 2 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | PF000358 | PowerFuse | SH-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | PF000358 | PowerFuse | SH-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000180 | Switchgear | SH-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000180 | Switchgear | SH-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000180 | Switchgear | SH-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000180 | Switchgear | SH-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000180 | Switchgear | SH-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000180 | Switchgear | SH-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000180 | Switchgear | SH-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000180 | Switchgear | SH-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000180 | Switchgear | SH-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000180 | Switchgear | SH-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000180 | Switchgear | SH-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000180 | Switchgear | SH-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000180 | Switchgear | SH-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000180 | Switchgear | SH-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000180 | Switchgear | SH-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000180 | Switchgear | SH-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000180 | Switchgear | SH-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000180 | Switchgear | SH-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000180 | Switchgear | SH-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | PF000357 | PowerFuse | SH-14KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | PF000357 | PowerFuse | SH-14KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | PF000357 | PowerFuse | SH-14KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | PF000356 | PowerFuse | SH-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | PF000356 | PowerFuse | SH-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | PF000356 | PowerFuse | SH-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000072 | Switchgear | SH-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000072 | Switchgear | SH-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000072 | Switchgear | SH-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000072 | Switchgear | SH-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000072 | Switchgear | SH-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000072 | Switchgear | SH-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000072 | Switchgear | SH-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000072 | Switchgear | SH-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000072 | Switchgear | SH-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000072 | Switchgear | SH-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000072 | Switchgear | SH-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000072 | Switchgear | SH-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000072 | Switchgear | SH-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000072 | Switchgear | SH-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | SWG000072 | Switchgear | SH-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | LTCMechanism | SH-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 6L | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | LTCMechanism | SH-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | LTCMechanism | SH-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 84 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | LTCMechanism | SH-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 90304 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | LTCMechanism | SH-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | LTCMechanism | SH-TRANS 2 | LTC Counter Readings | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | LTCMechanism | SH-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | LTCMechanism | SH-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 90304 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | LTCMechanism | SH-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | LTCMechanism | SH-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | LTCMechanism | SH-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | LTCMechanism | SH-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | LTCMechanism | SH-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | LTCMechanism | SH-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | LTCMechanism | SH-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 58 | °C |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 56 | °C |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 26 | °C |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 56 | °C |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 26 | °C |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 58 | °C |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 26 | °C |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .3 | psi |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0170 | WithLTC | SH-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0271 | GroundTransformer | SH-GND TR 1 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0271 | GroundTransformer | SH-GND TR 1 | Ground Transformer Patrol Inspection | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0271 | GroundTransformer | SH-GND TR 1 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0271 | GroundTransformer | SH-GND TR 1 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0271 | GroundTransformer | SH-GND TR 1 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.3 | psi |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0271 | GroundTransformer | SH-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0271 | GroundTransformer | SH-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0271 | GroundTransformer | SH-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0271 | GroundTransformer | SH-GND TR 1 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0271 | GroundTransformer | SH-GND TR 1 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0271 | GroundTransformer | SH-GND TR 1 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0271 | GroundTransformer | SH-GND TR 1 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0271 | GroundTransformer | SH-GND TR 1 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0271 | GroundTransformer | SH-GND TR 1 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | LTCMechanism | SH-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 124 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | LTCMechanism | SH-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 5 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | LTCMechanism | SH-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | LTCMechanism | SH-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 9 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | LTCMechanism | SH-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 8 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | LTCMechanism | SH-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 5166 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | LTCMechanism | SH-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 5166 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | LTCMechanism | SH-TRANS 1 | LTC Counter Readings | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | LTCMechanism | SH-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | LTCMechanism | SH-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | LTCMechanism | SH-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | LTCMechanism | SH-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | LTCMechanism | SH-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | LTCMechanism | SH-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 35 | °C |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 45 | °C |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 800 | psi |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LT0171 | WithLTC | SH-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Readings | Operations Counter AL | 87 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Readings | Operations Counter AF | 87 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Readings | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Readings | Amps C Ø | 253.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Readings | Amps B Ø | 247.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Readings | 9 Month Operations | 2 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Readings | Amps A Ø | 236.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001932 | BreakerVacuum | SH-14KV TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Readings | 9 Month Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Readings | Amps A Ø | 0.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Readings | Amps B Ø | 0.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Readings | Amps C Ø | 0.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Readings | Switching Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Readings | Operations Counter AL | 81 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Readings | Operations Counter AF | 81 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Readings | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001933 | BreakerVacuum | SH-GND TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Readings | Unknown Operations | 5 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Readings | Switching Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Readings | Operations This Read Vac | 5 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Readings | Operations Counter AL | 94 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Readings | Operations Counter AF | 94 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Readings | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Readings | Fault Adjusted Amps C Phase V | 55.90 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Readings | Fault Adjusted Amps B Phase V | 55.90 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Readings | Fault Adjusted Amps A Phase V | 55.90 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Readings | Amps C Ø | 167.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Readings | Amps B Ø | 165.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Readings | Amps A Ø | 144.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Readings | 9 Month Operations | 8 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001934 | BreakerVacuum | SH-1456 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Readings | Operations Counter AF | 73 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Readings | Operations Counter AL | 73 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Readings | Operations This Read Vac | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Readings | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Readings | Amps C Ø | 17.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Readings | Amps B Ø | 17.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Readings | Amps A Ø | 15.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Readings | Switching Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Readings | 9 Month Operations | 1 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001935 | BreakerVacuum | SH-1457 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Readings | 9 Month Operations | 1 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Readings | Amps A Ø | 8.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Readings | Amps B Ø | 8.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Readings | Amps C Ø | 8.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Readings | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Readings | Operations Counter AF | 75 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Readings | Operations Counter AL | 75 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Readings | Operations This Read Vac | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Readings | Switching Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001936 | BreakerVacuum | SH-1458 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Readings | Switching Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Readings | Operations This Read Vac | 6 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Readings | Operations Counter AL | 87 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Readings | Operations Counter AF | 87 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Readings | General Comments | B phase IOC | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Readings | Fault Operations B Ø | 6 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Readings | 9 Month Operations | 10 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Readings | Amps A Ø | 72.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Readings | Amps B Ø | 66.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Readings | Amps C Ø | 66.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Readings | Fault Adjusted Amps B Phase V | 67.08 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | BK001937 | BreakerVacuum | SH-1459 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Patrol Inspection | Ambient Temperature | 50 | °F |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Patrol Inspection | General Comments | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Patrol Inspection | SF6 Pressure | 0 | psi |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Readings | 9 Month Operations | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Readings | Amps A Ø | 100.0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Readings | Amps B Ø | 100.0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Readings | Amps C Ø | 95.0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Readings | Switching Operations | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Readings | Operations This Read Vac | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Readings | Operations Counter AL | 209 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Readings | Operations Counter AF | 209 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Readings | General Comments | | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BK001094 | BreakerVacuum | 773-0931 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Readings | Amps A Ø | 35.0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Readings | Amps B Ø | 45.0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Readings | 9 Month Operations | 2 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Readings | Amps C Ø | 70.0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Readings | Switching Operations | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Readings | Operations This Read Vac | 2 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Readings | Operations Counter AL | 412 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Readings | Operations Counter AF | 410 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Readings | Fault Adjusted Amps C Phase V | 8.38 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Readings | Fault Operations C Ø | 2 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Readings | General Comments | | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0110 | BreakerVacuum | 773-0929 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Readings | Amps B Ø | 80.0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Readings | Amps C Ø | 80.0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Readings | General Comments | | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Readings | Operations Counter AF | 275 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Readings | Operations Counter AL | 275 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Readings | Operations This Read Vac | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Readings | Switching Operations | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Readings | Amps A Ø | 75.0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Readings | 9 Month Operations | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | K0109 | BreakerVacuum | 773-0930 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1411 | Regulator | 773-1 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1411 | Regulator | 773-1 C | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1411 | Regulator | 773-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1411 | Regulator | 773-1 C | Regulator Patrol Inspection | General Comments | | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1411 | Regulator | 773-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1411 | Regulator | 773-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1411 | Regulator | 773-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1411 | Regulator | 773-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1411 | Regulator | 773-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1411 | Regulator | 773-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1411 | Regulator | 773-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1411 | Regulator | 773-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 55687 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1411 | Regulator | 773-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1411 | Regulator | 773-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1411 | Regulator | 773-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1411 | Regulator | 773-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1411 | Regulator | 773-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1411 | Regulator | 773-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1411 | Regulator | 773-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1411 | Regulator | 773-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1411 | Regulator | 773-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1411 | Regulator | 773-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1411 | Regulator | 773-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1411 | Regulator | 773-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1412 | Regulator | 773-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1412 | Regulator | 773-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1412 | Regulator | 773-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1412 | Regulator | 773-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1412 | Regulator | 773-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1412 | Regulator | 773-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1412 | Regulator | 773-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1412 | Regulator | 773-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1412 | Regulator | 773-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1412 | Regulator | 773-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1412 | Regulator | 773-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1412 | Regulator | 773-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1412 | Regulator | 773-1 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1412 | Regulator | 773-1 B | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1412 | Regulator | 773-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1412 | Regulator | 773-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1412 | Regulator | 773-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1412 | Regulator | 773-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1412 | Regulator | 773-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.0 | volts |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1412 | Regulator | 773-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 56928 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1412 | Regulator | 773-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1412 | Regulator | 773-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1412 | Regulator | 773-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1412 | Regulator | 773-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1413 | Regulator | 773-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1413 | Regulator | 773-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1413 | Regulator | 773-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1413 | Regulator | 773-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1413 | Regulator | 773-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1413 | Regulator | 773-1 A | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1413 | Regulator | 773-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1413 | Regulator | 773-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1413 | Regulator | 773-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1413 | Regulator | 773-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1413 | Regulator | 773-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1413 | Regulator | 773-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1413 | Regulator | 773-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1413 | Regulator | 773-1 A | Regulator Patrol Inspection | General Comments | | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1413 | Regulator | 773-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1413 | Regulator | 773-1 A | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1413 | Regulator | 773-1 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1413 | Regulator | 773-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1413 | Regulator | 773-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1413 | Regulator | 773-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1413 | Regulator | 773-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1413 | Regulator | 773-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.0 | volts |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1413 | Regulator | 773-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | R1413 | Regulator | 773-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 52679 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .6384 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 10.00 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 6128.64 | kw |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Readings | General Comments | | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 15.00 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -1.0 | psi |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | S0041 | NonLTC | 773-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | KB0132 | CircuitSwitcher | 773-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | KB0132 | CircuitSwitcher | 773-1 Trans-Rupter | Circuit Switcher Patrol Inspection | SF6 Bushing Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | KB0132 | CircuitSwitcher | 773-1 Trans-Rupter | Circuit Switcher Patrol Inspection | SF6 Indicator Zone | OK | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | KB0132 | CircuitSwitcher | 773-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Trip-energy Supply Verified | y | LED lights? |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | KB0132 | CircuitSwitcher | 773-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | KB0132 | CircuitSwitcher | 773-1 Trans-Rupter | Circuit Switcher Patrol Inspection | General Comments | | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | KB0132 | CircuitSwitcher | 773-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | KB0132 | CircuitSwitcher | 773-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | KB0132 | CircuitSwitcher | 773-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | KB0132 | CircuitSwitcher | 773-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | KB0132 | CircuitSwitcher | 773-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | KB0132 | CircuitSwitcher | 773-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Ambient Temperature | 50 | °F |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BAT001546 | Battery | 773-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BAT001546 | Battery | 773-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BAT001546 | Battery | 773-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BAT001546 | Battery | 773-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BAT001546 | Battery | 773-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BAT001546 | Battery | 773-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BAT001546 | Battery | 773-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BAT001546 | Battery | 773-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BAT001546 | Battery | 773-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BAT001546 | Battery | 773-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BAT001546 | Battery | 773-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BAT001546 | Battery | 773-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BAT001546 | Battery | 773-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BCH001475 | Charger | 773-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BCH001475 | Charger | 773-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BCH001475 | Charger | 773-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BCH001475 | Charger | 773-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.4 | amps |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BCH001475 | Charger | 773-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BCH001475 | Charger | 773-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BCH001475 | Charger | 773-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | BCH001475 | Charger | 773-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | ST000303 | Structure | 773-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | ST000303 | Structure | 773-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | ST000303 | Structure | 773-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | ST000303 | Structure | 773-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | ST000303 | Structure | 773-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | ST000303 | Structure | 773-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | ST000303 | Structure | 773-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | ST000303 | Structure | 773-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | ST000303 | Structure | 773-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | ST000303 | Structure | 773-Structure | Structure Patrol Inspection | Interruptrs/Puffrs Visual OK? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | ST000303 | Structure | 773-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | ST000303 | Structure | 773-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | ST000303 | Structure | 773-Structure | Structure Patrol Inspection | General Comments | | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | ST000303 | Structure | 773-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | ST000303 | Structure | 773-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | ST000303 | Structure | 773-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | ST000303 | Structure | 773-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | ST000303 | Structure | 773-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | ST000303 | Structure | 773-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | ST000303 | Structure | 773-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | ST000303 | Structure | 773-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Readings | Amps C Ø | 60.0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Readings | Amps B Ø | 90.0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Readings | Amps A Ø | 60.0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Readings | 9 Month Operations VCB New | 16 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Readings | 9 Month Operations | 18 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Readings | General Comments | | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Readings | Operations Counter AF | 306 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Readings | Operations Counter AL | 308 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Readings | Operations This Read Vac | 2 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Readings | Switching Operations | 2 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0095 | BreakerVacuum | 223-0948 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Readings | Switching Operations | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Readings | Operations This Read Vac | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Readings | Operations Counter AL | 192 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Readings | Operations Counter AF | 192 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Readings | General Comments | | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Readings | 9 Month Operations | 13 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Readings | 9 Month Operations VCB New | 13 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Readings | Amps A Ø | 420.0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Readings | Amps B Ø | 515.0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Readings | Amps C Ø | 480.0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0096 | BreakerVacuum | 223-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Readings | Switching Operations | 2 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Readings | Operations This Read Vac | 2 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Readings | Operations Counter AL | 255 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Readings | Operations Counter AF | 253 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Readings | General Comments | | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Readings | 9 Month Operations | 19 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Readings | 9 Month Operations VCB New | 17 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Readings | Amps C Ø | 85.0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Readings | Amps B Ø | 80.0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Readings | Amps A Ø | 45.0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | K0115 | BreakerVacuum | 223-0947 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Readings | 9 Month Operations | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Readings | Amps A Ø | 160.0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Readings | Amps B Ø | 165.0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Readings | Amps C Ø | 160.0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Readings | Switching Operations | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Readings | Operations This Read Vac | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Readings | Operations Counter AL | 235 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Readings | Operations Counter AF | 234 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Readings | General Comments | | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0094 | BreakerVacuum | 223-0946 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Patrol Inspection | General Comments | | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Readings | Fault Operations Ground | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Readings | Operations Counter AF | 225 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Readings | Operations Counter AL | 225 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Readings | Amps C Ø | 255.0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Readings | Amps B Ø | 260.0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Readings | Amps A Ø | 210.0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Readings | Operations This Read Vac | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Readings | 9 Month Operations | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Readings | Unknown Operations | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | KB0093 | BreakerVacuum | 223-0945 | VCB Readings | Switching Operations | 0 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | LTCM000007 | LTCMechanism | 223-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | LTCM000007 | LTCMechanism | 223-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | LTCM000007 | LTCMechanism | 223-5 | LTC Counter Readings | LTC Operations Since Last Insp | 404 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | LTCM000007 | LTCMechanism | 223-5 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | LTCM000007 | LTCMechanism | 223-5 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | LTCM000007 | LTCMechanism | 223-5 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | LTCM000007 | LTCMechanism | 223-5 | LTC Counter Readings | LTC As Left Counter | 24525 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | LTCM000007 | LTCMechanism | 223-5 | LTC Counter Readings | LTC As Found Counter | 24525 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | LTCM000007 | LTCMechanism | 223-5 | LTC Counter Readings | General Comments | | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | LTCM000007 | LTCMechanism | 223-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | LTCM000007 | LTCMechanism | 223-5 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | LTCM000007 | LTCMechanism | 223-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | LTCM000007 | LTCMechanism | 223-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | LTCM000007 | LTCMechanism | 223-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | LTCM000007 | LTCMechanism | 223-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | LTCC000008 | LTCControl | 223-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | LTCC000008 | LTCControl | 223-5 | LTC Control Insp | General Comments | | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | LTCC000008 | LTCControl | 223-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | LTCC000008 | LTCControl | 223-5 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | LTCC000008 | LTCControl | 223-5 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | LTCC000008 | LTCControl | 223-5 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | LTCC000008 | LTCControl | 223-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | LTCC000008 | LTCControl | 223-5 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | LTCC000008 | LTCControl | 223-5 | LTC Control Insp | All Connections OK? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Readings | Totalizer Meter Reading | .8538 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Readings | LTC Totalizer Reading | 12294.72 | kw |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Readings | General Comments | | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 700 | psi |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/22/2023 7:03 | Distribution | Carntown Quarterly Inspection | TX000003 | WithLTC | 223-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Patrol Inspection | SF6 Pressure | 0 | psi |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Patrol Inspection | Grounds in Place? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Patrol Inspection | General Comments | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Patrol Inspection | Foundation Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Patrol Inspection | Ambient Temperature | 50 | °F |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0006 | BreakerSF6 | SH-1281 | GCB Readings | Switching Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0006 | BreakerSF6 | SH-1281 | GCB Readings | Operations This Read SF6 | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0006 | BreakerSF6 | SH-1281 | GCB Readings | Operations Counter AL | 669 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0006 | BreakerSF6 | SH-1281 | GCB Readings | Operations Counter AF | 669 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0006 | BreakerSF6 | SH-1281 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0006 | BreakerSF6 | SH-1281 | GCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0006 | BreakerSF6 | SH-1281 | GCB Readings | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0006 | BreakerSF6 | SH-1281 | GCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0006 | BreakerSF6 | SH-1281 | GCB Readings | Fault Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0006 | BreakerSF6 | SH-1281 | GCB Readings | Amps C Ø | 99.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0006 | BreakerSF6 | SH-1281 | GCB Readings | Amps B Ø | 97.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0006 | BreakerSF6 | SH-1281 | GCB Readings | Amps A Ø | 88.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0006 | BreakerSF6 | SH-1281 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0006 | BreakerSF6 | SH-1281 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0006 | BreakerSF6 | SH-1281 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0006 | BreakerSF6 | SH-1281 | GCB Patrol Inspection | General Comments | y | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Readings | 9 Month Operations GCB New | 30 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Readings | Amps A Ø | 67.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Readings | Amps B Ø | 72.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Readings | Amps C Ø | 79.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Readings | Fault Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Readings | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Readings | Maintenance Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Readings | Unknown Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Readings | Switching Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Readings | Num Operations Last 9 Months | 30 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Readings | Operations Counter AF | 456 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Readings | Operations Counter AL | 456 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0856 | BreakerSF6 | SH-1285 | GCB Readings | Operations This Read SF6 | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Readings | 9 Month Operations GCB New | 21 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Readings | Amps A Ø | 104.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Readings | Amps B Ø | 98.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Readings | Amps C Ø | 95.0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Readings | Fault Operations | 0 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Readings | Follow-up Action Required? | n | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Readings | General Comments | | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Readings | Maintenance Operations | 16 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Readings | Num Operations Last 9 Months | 38 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Readings | Operations Counter AF | 777 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Readings | Operations Counter AL | 777 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Readings | Operations This Read SF6 | 17 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Readings | Switching Operations | 1 | |
| 3/22/2023 7:35 | Distribution | Shively Quarterly Inspection | LB0860 | BreakerSF6 | SH-1282 | GCB Readings | Unknown Operations | 0 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | YD000295 | Yard | 773-Yard | Yard Patrol Inspection | General Comments | | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | YD000295 | Yard | 773-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | YD000295 | Yard | 773-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | YD000295 | Yard | 773-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | YD000295 | Yard | 773-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | YD000295 | Yard | 773-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | YD000295 | Yard | 773-Yard | Yard Patrol Inspection | Switch Stick Next Test Date | 2024-06-14 00:00:00.000000 | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | YD000295 | Yard | 773-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | YD000295 | Yard | 773-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | YD000295 | Yard | 773-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | YD000295 | Yard | 773-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | YD000295 | Yard | 773-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | YD000295 | Yard | 773-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | YD000295 | Yard | 773-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | YD000295 | Yard | 773-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | FE000356 | Fence | 773-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | FE000356 | Fence | 773-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | FE000356 | Fence | 773-Fence | Fence Patrol Inspection | General Comments | | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | FE000356 | Fence | 773-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | FE000356 | Fence | 773-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | FE000356 | Fence | 773-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | FE000356 | Fence | 773-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | FE000356 | Fence | 773-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | FE000356 | Fence | 773-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | FE000356 | Fence | 773-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | FE000356 | Fence | 773-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | FE000356 | Fence | 773-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | FE000356 | Fence | 773-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | FE000356 | Fence | 773-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | FE000356 | Fence | 773-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/22/2023 7:17 | Distribution | Augusta Quarterly Inspection | FE000356 | Fence | 773-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0309 | NonLTC | SL-TRANS 1C | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0309 | NonLTC | SL-TRANS 1C | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0309 | NonLTC | SL-TRANS 1C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 210.00 | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0309 | NonLTC | SL-TRANS 1C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0309 | NonLTC | SL-TRANS 1C | NonLTC Transformer Readings | General Comments | | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0309 | NonLTC | SL-TRANS 1C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0309 | NonLTC | SL-TRANS 1C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Readings | General Comments | | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 145.00 | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Readings | Oil Temp Max | 37 | °C |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Readings | Oil Temp Present | 27 | °C |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0307 | NonLTC | SL-TRANS 1A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0307 | NonLTC | SL-TRANS 1A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0307 | NonLTC | SL-TRANS 1A | NonLTC Transformer Readings | General Comments | | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0307 | NonLTC | SL-TRANS 1A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0307 | NonLTC | SL-TRANS 1A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 445.00 | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0307 | NonLTC | SL-TRANS 1A | NonLTC Transformer Readings | Oil Temp Max | 25 | °C |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0307 | NonLTC | SL-TRANS 1A | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Readings | General Comments | | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 10.00 | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Readings | Oil Temp Max | 34 | °C |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Readings | Oil Temp Present | 16 | °C |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.2 | psi |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 15.00 | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | TX000194 | NonLTC | SL-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0309 | NonLTC | SL-TRANS 1C | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0309 | NonLTC | SL-TRANS 1C | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0309 | NonLTC | SL-TRANS 1C | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0309 | NonLTC | SL-TRANS 1C | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0309 | NonLTC | SL-TRANS 1C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0309 | NonLTC | SL-TRANS 1C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0309 | NonLTC | SL-TRANS 1C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0309 | NonLTC | SL-TRANS 1C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0309 | NonLTC | SL-TRANS 1C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0309 | NonLTC | SL-TRANS 1C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0309 | NonLTC | SL-TRANS 1C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0309 | NonLTC | SL-TRANS 1C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0309 | NonLTC | SL-TRANS 1C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 225.00 | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0309 | NonLTC | SL-TRANS 1C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0309 | NonLTC | SL-TRANS 1C | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0309 | NonLTC | SL-TRANS 1C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0309 | NonLTC | SL-TRANS 1C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0309 | NonLTC | SL-TRANS 1C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0309 | NonLTC | SL-TRANS 1C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0309 | NonLTC | SL-TRANS 1C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 150.00 | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0308 | NonLTC | SL-TRANS 1B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0307 | NonLTC | SL-TRANS 1A | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0307 | NonLTC | SL-TRANS 1A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0307 | NonLTC | SL-TRANS 1A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0307 | NonLTC | SL-TRANS 1A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0307 | NonLTC | SL-TRANS 1A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0307 | NonLTC | SL-TRANS 1A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0307 | NonLTC | SL-TRANS 1A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0307 | NonLTC | SL-TRANS 1A | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0307 | NonLTC | SL-TRANS 1A | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0307 | NonLTC | SL-TRANS 1A | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0307 | NonLTC | SL-TRANS 1A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0307 | NonLTC | SL-TRANS 1A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0307 | NonLTC | SL-TRANS 1A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0307 | NonLTC | SL-TRANS 1A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0307 | NonLTC | SL-TRANS 1A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0307 | NonLTC | SL-TRANS 1A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0307 | NonLTC | SL-TRANS 1A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 466.67 | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0307 | NonLTC | SL-TRANS 1A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0307 | NonLTC | SL-TRANS 1A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | LT0307 | NonLTC | SL-TRANS 1A | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | Moisture and Leak Free? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | MOD Motor Jaw Coupling | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | MOD Cabinet Internals Clean? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | MOD Cabinet Heater functional? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | Interruptrs/Puffrs Visual OK? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | General Comments | | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | ST000647 | Structure | SL-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | FE000668 | Fence | SL-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | FE000668 | Fence | SL-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | FE000668 | Fence | SL-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | FE000668 | Fence | SL-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | FE000668 | Fence | SL-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | FE000668 | Fence | SL-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | FE000668 | Fence | SL-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | FE000668 | Fence | SL-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | FE000668 | Fence | SL-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | FE000668 | Fence | SL-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | FE000668 | Fence | SL-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | FE000668 | Fence | SL-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | FE000668 | Fence | SL-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | FE000668 | Fence | SL-Fence | Fence Patrol Inspection | General Comments | | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | FE000668 | Fence | SL-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | FE000668 | Fence | SL-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | YD000672 | Yard | SL-Yard | Yard Patrol Inspection | Ambient Temp | 52 | °F |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | YD000672 | Yard | SL-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | YD000672 | Yard | SL-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | YD000672 | Yard | SL-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | YD000672 | Yard | SL-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | YD000672 | Yard | SL-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | YD000672 | Yard | SL-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | YD000672 | Yard | SL-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | YD000672 | Yard | SL-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | YD000672 | Yard | SL-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | YD000672 | Yard | SL-Yard | Yard Patrol Inspection | General Comments | | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | YD000672 | Yard | SL-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | YD000672 | Yard | SL-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/21/2023 12:54 | Distribution | Solite Quarterly Inspection | YD000672 | Yard | SL-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Readings | Unknown Operations | 0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Readings | 9 Month Operations | 2 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Readings | Amps A Ø | 45.0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Readings | Amps B Ø | 30.0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Readings | Amps C Ø | 70.0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Readings | Fault Operations Ground | 0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Readings | Follow-up Action Required? | n | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Readings | General Comments | | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Readings | Maintenance Operations | 0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Readings | Operations Counter AF | 224 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Readings | Switching Operations | 2 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Readings | Operations This Read Vac | 2 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Readings | Operations Counter AL | 226 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Patrol Inspection | General Comments | | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001154 | BreakerVacuum | 737-0602 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Readings | 9 Month Operations | 2 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Readings | Unknown Operations | 0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Readings | Switching Operations | 2 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Readings | Amps A Ø | 180.0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Readings | Amps B Ø | 175.0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Readings | Amps C Ø | 190.0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Readings | Fault Operations Ground | 0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Readings | Follow-up Action Required? | n | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Readings | Operations This Read Vac | 2 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Readings | Operations Counter AL | 218 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Readings | Operations Counter AF | 216 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Readings | Maintenance Operations | 0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Readings | General Comments | | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Patrol Inspection | General Comments | | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001153 | BreakerVacuum | 737-0601 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Readings | Operations Counter AL | 252 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Readings | Operations Counter AF | 250 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Readings | Maintenance Operations | 0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Readings | General Comments | | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Readings | Operations This Read Vac | 2 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Readings | Switching Operations | 2 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Readings | Unknown Operations | 0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Readings | Follow-up Action Required? | n | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Readings | Fault Operations Ground | 0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Readings | 9 Month Operations | 4 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Readings | Amps A Ø | 80.0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Readings | Amps B Ø | 90.0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Readings | Amps C Ø | 80.0 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Patrol Inspection | General Comments | | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BK001170 | BreakerVacuum | 737-0600 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | LTCMechanism | 737-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | LTCMechanism | 737-1 | LTC Counter Readings | LTC Operations Since Last Insp | 890 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | LTCMechanism | 737-1 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | LTCMechanism | 737-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | LTCMechanism | 737-1 | LTC Counter Readings | General Comments | | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | LTCMechanism | 737-1 | LTC Counter Readings | LTC As Found Counter | 16857 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | LTCMechanism | 737-1 | LTC Counter Readings | LTC As Left Counter | 16857 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | LTCMechanism | 737-1 | LTC Counter Readings | LTC Current Tap Position | 5R | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | LTCMechanism | 737-1 | LTC Counter Readings | LTC Max Tap Position | 8R | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | LTCC000938 | LTCControl | 737-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | LTCC000938 | LTCControl | 737-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | LTCC000938 | LTCControl | 737-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | LTCC000938 | LTCControl | 737-1 | LTC Control Insp | All Connections OK? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | LTCC000938 | LTCControl | 737-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | LTCC000938 | LTCControl | 737-1 | LTC Control Insp | General Comments | | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | LTCC000938 | LTCControl | 737-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | LTCC000938 | LTCControl | 737-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | LTCMechanism | 737-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | LTCMechanism | 737-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | LTCMechanism | 737-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | LTCMechanism | 737-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | LTCMechanism | 737-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | LTCMechanism | 737-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | LTCMechanism | 737-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 55.00 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Readings | Totalizer Meter Reading | .9410 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Readings | LTC Totalizer Reading | 9033.60 | kw |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Readings | General Comments | | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | S0022 | WithLTC | 737-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BCH001315 | Charger | 737-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BCH001315 | Charger | 737-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.6 | amps |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BCH001315 | Charger | 737-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BCH001315 | Charger | 737-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BCH001315 | Charger | 737-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BCH001315 | Charger | 737-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BCH001315 | Charger | 737-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BAT001124 | Battery | 737-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BAT001124 | Battery | 737-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BAT001124 | Battery | 737-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BAT001124 | Battery | 737-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BAT001124 | Battery | 737-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BAT001124 | Battery | 737-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BAT001124 | Battery | 737-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 35 | °F |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BAT001124 | Battery | 737-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BAT001124 | Battery | 737-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BAT001124 | Battery | 737-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BAT001124 | Battery | 737-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BAT001124 | Battery | 737-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BAT001124 | Battery | 737-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | BAT001124 | Battery | 737-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | ST000399 | Structure | 737-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | ST000399 | Structure | 737-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | ST000399 | Structure | 737-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | ST000399 | Structure | 737-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | ST000399 | Structure | 737-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | ST000399 | Structure | 737-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | ST000399 | Structure | 737-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | ST000399 | Structure | 737-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | ST000399 | Structure | 737-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | ST000399 | Structure | 737-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | ST000399 | Structure | 737-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | ST000399 | Structure | 737-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | ST000399 | Structure | 737-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | ST000399 | Structure | 737-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | ST000399 | Structure | 737-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | ST000399 | Structure | 737-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | ST000399 | Structure | 737-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | ST000399 | Structure | 737-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | ST000399 | Structure | 737-Structure | Structure Patrol Inspection | General Comments | | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | ST000399 | Structure | 737-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | ST000399 | Structure | 737-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | ST000399 | Structure | 737-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | FE000390 | Fence | 737-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | FE000390 | Fence | 737-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | FE000390 | Fence | 737-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | FE000390 | Fence | 737-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | FE000390 | Fence | 737-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | FE000390 | Fence | 737-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | FE000390 | Fence | 737-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | FE000390 | Fence | 737-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | FE000390 | Fence | 737-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | FE000390 | Fence | 737-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | FE000390 | Fence | 737-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | FE000390 | Fence | 737-Fence | Fence Patrol Inspection | General Comments | | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | FE000390 | Fence | 737-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | FE000390 | Fence | 737-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | FE000390 | Fence | 737-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | FE000390 | Fence | 737-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | YD000396 | Yard | 737-Yard | Yard Patrol Inspection | General Comments | | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | YD000396 | Yard | 737-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | YD000396 | Yard | 737-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | YD000396 | Yard | 737-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | YD000396 | Yard | 737-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | YD000396 | Yard | 737-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | YD000396 | Yard | 737-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | YD000396 | Yard | 737-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | YD000396 | Yard | 737-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | YD000396 | Yard | 737-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | YD000396 | Yard | 737-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | YD000396 | Yard | 737-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | YD000396 | Yard | 737-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | YD000396 | Yard | 737-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | YD000396 | Yard | 737-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/20/2023 15:07 | Distribution | Mount Sterling Quarterly Inspection | YD000396 | Yard | 737-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Readings | Amps B Ø | 170 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Readings | Amps C Ø | 186 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Readings | Fault Operations Ground | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Readings | Follow-up Action Required? | n | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Readings | General Comments | | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Readings | Maintenance Operations | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Readings | Operations Counter AF | 179 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Readings | Operations Counter AL | 179 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Readings | Operations This Read Vac | 3 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Readings | Switching Operations | 3 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Readings | Unknown Operations | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Readings | Amps A Ø | 163 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Readings | Accumulated Fault Duty C Ph V | .47 | % |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Readings | Accumulated Fault Duty A Ph V | .47 | % |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Readings | 9 Month Operations | 3 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Patrol Inspection | General Comments | | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0192 | BreakerVacuum | 809-2332 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Readings | Accumulated Fault Duty C Ph V | .93 | % |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Readings | 9 Month Operations | 1 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Readings | Amps A Ø | 61 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Readings | Amps B Ø | 54 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Readings | Amps C Ø | 59 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Readings | Accumulated Fault Duty A Ph V | .47 | % |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Readings | Fault Operations Ground | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Readings | Follow-up Action Required? | n | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Readings | General Comments | | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Readings | Maintenance Operations | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Readings | Operations Counter AF | 182 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Readings | Operations Counter AL | 183 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Readings | Operations This Read Vac | 1 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Readings | Switching Operations | 1 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Readings | Unknown Operations | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Patrol Inspection | General Comments | | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0191 | BreakerVacuum | 809-2331 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Readings | Operations Counter AL | 80 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Readings | Operations Counter AF | 80 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Readings | Amps A Ø | 202 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Readings | General Comments | | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Readings | Amps C Ø | 221 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Readings | Amps B Ø | 202 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Readings | Switching Operations | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Readings | Unknown Operations | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Readings | 9 Month Operations | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Patrol Inspection | General Comments | | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | K0195 | BreakerVacuum | 809-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | LTCMechanism | 809-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | LTCMechanism | 809-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | LTCMechanism | 809-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | LTCMechanism | 809-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 30 | °C |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | LTCMechanism | 809-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 20 | °C |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | LTCMechanism | 809-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | LTCMechanism | 809-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | LTCMechanism | 809-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | LTCMechanism | 809-2 | LTC Counter Readings | LTC Operations Since Last Insp | 534 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | LTCMechanism | 809-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | LTCMechanism | 809-2 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | LTCMechanism | 809-2 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | LTCMechanism | 809-2 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | LTCMechanism | 809-2 | LTC Counter Readings | LTC As Left Counter | 59827 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | LTCMechanism | 809-2 | LTC Counter Readings | LTC As Found Counter | 59825 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | LTCMechanism | 809-2 | LTC Counter Readings | General Comments | | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | LTCMechanism | 809-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Readings | General Comments | | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Readings | LTC Totalizer Reading | 6624 | kw |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Readings | Totalizer Meter Reading | .69 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Readings | Winding Temp Max | 35 | °C |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Readings | Winding Temp Present | 20 | °C |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | S0069 | WithLTC | 809-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | LTCC000161 | LTCControl | 809-2 | LTC Control Insp | All Connections OK? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | LTCC000161 | LTCControl | 809-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | LTCC000161 | LTCControl | 809-2 | LTC Control Insp | General Comments | | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | LTCC000161 | LTCControl | 809-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | LTCC000161 | LTCControl | 809-2 | LTC Control Insp | LTC Output Voltage Level | 125.2 | VAC |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | LTCC000161 | LTCControl | 809-2 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | LTCC000161 | LTCControl | 809-2 | LTC Control Insp | VRR Base Voltage AF | 125 | VAC |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | LTCC000161 | LTCControl | 809-2 | LTC Control Insp | VRR Base Voltage AL | 125 | VAC |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | LTCC000161 | LTCControl | 809-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | BCH001358 | Charger | 809-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | BCH001358 | Charger | 809-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | BCH001358 | Charger | 809-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | BCH001358 | Charger | 809-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | BCH001358 | Charger | 809-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | BCH001358 | Charger | 809-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | BCH001358 | Charger | 809-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | BCH001358 | Charger | 809-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0 | millivolts |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | BAT000617 | Battery | 809-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | BAT000617 | Battery | 809-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | BAT000617 | Battery | 809-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27 | VDC |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | BAT000617 | Battery | 809-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | BAT000617 | Battery | 809-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | BAT000617 | Battery | 809-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | BAT000617 | Battery | 809-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | BAT000617 | Battery | 809-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.1 | VDC |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | BAT000617 | Battery | 809-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | BAT000617 | Battery | 809-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | BAT000617 | Battery | 809-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | BAT000617 | Battery | 809-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | BAT000617 | Battery | 809-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | BAT000617 | Battery | 809-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | CH000345 | ControlHouse | 809-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | CH000345 | ControlHouse | 809-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | CH000345 | ControlHouse | 809-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | CH000345 | ControlHouse | 809-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | CH000345 | ControlHouse | 809-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | CH000345 | ControlHouse | 809-Control House | Control House Patrol Inspection | General Comments | | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | CH000345 | ControlHouse | 809-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | CH000345 | ControlHouse | 809-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | CH000345 | ControlHouse | 809-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | CH000345 | ControlHouse | 809-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | CH000345 | ControlHouse | 809-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | CH000345 | ControlHouse | 809-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | CH000345 | ControlHouse | 809-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | CH000345 | ControlHouse | 809-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | CH000345 | ControlHouse | 809-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | CH000345 | ControlHouse | 809-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | CH000345 | ControlHouse | 809-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | ST000527 | Structure | 809-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | ST000527 | Structure | 809-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | ST000527 | Structure | 809-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | ST000527 | Structure | 809-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | ST000527 | Structure | 809-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | ST000527 | Structure | 809-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | ST000527 | Structure | 809-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | ST000527 | Structure | 809-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | ST000527 | Structure | 809-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | ST000527 | Structure | 809-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | ST000527 | Structure | 809-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | ST000527 | Structure | 809-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | ST000527 | Structure | 809-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | ST000527 | Structure | 809-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | ST000527 | Structure | 809-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | ST000527 | Structure | 809-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | ST000527 | Structure | 809-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | ST000527 | Structure | 809-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | ST000527 | Structure | 809-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | ST000527 | Structure | 809-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | ST000527 | Structure | 809-Structure | Structure Patrol Inspection | General Comments | | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | ST000527 | Structure | 809-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | FE000524 | Fence | 809-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | FE000524 | Fence | 809-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | FE000524 | Fence | 809-Fence | Fence Patrol Inspection | General Comments | | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | FE000524 | Fence | 809-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | FE000524 | Fence | 809-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | FE000524 | Fence | 809-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | FE000524 | Fence | 809-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | FE000524 | Fence | 809-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | FE000524 | Fence | 809-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | FE000524 | Fence | 809-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | FE000524 | Fence | 809-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | FE000524 | Fence | 809-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | FE000524 | Fence | 809-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | FE000524 | Fence | 809-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | FE000524 | Fence | 809-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | FE000524 | Fence | 809-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | YD000522 | Yard | 809-Yard | Yard Patrol Inspection | Ambient Temp | 40 | °F |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | YD000522 | Yard | 809-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | YD000522 | Yard | 809-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | YD000522 | Yard | 809-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | YD000522 | Yard | 809-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | YD000522 | Yard | 809-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | YD000522 | Yard | 809-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | YD000522 | Yard | 809-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | YD000522 | Yard | 809-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | YD000522 | Yard | 809-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | YD000522 | Yard | 809-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | YD000522 | Yard | 809-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | YD000522 | Yard | 809-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | YD000522 | Yard | 809-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | YD000522 | Yard | 809-Yard | Yard Patrol Inspection | General Comments | | |
| 3/20/2023 14:20 | Distribution | Elizabethtown 3 Quarterly Inspection | YD000522 | Yard | 809-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | CX0123 | RecloserElectronic | 513-2231 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | CX0123 | RecloserElectronic | 513-2231 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | CX0123 | RecloserElectronic | 513-2231 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | CX0123 | RecloserElectronic | 513-2231 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | CX0123 | RecloserElectronic | 513-2231 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | CX0123 | RecloserElectronic | 513-2231 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | CX0123 | RecloserElectronic | 513-2231 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | CX0123 | RecloserElectronic | 513-2231 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | CX0123 | RecloserElectronic | 513-2231 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | CX0123 | RecloserElectronic | 513-2231 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | CX0123 | RecloserElectronic | 513-2231 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | CX0123 | RecloserElectronic | 513-2231 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | CX0123 | RecloserElectronic | 513-2231 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | CX0123 | RecloserElectronic | 513-2231 | Recloser Electronic Patrol Inspection | Amps C Ø | 10 | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | CX0123 | RecloserElectronic | 513-2231 | Recloser Electronic Patrol Inspection | Amps B Ø | 10 | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | CX0123 | RecloserElectronic | 513-2231 | Recloser Electronic Patrol Inspection | Operations Counter | 2059 | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | CX0123 | RecloserElectronic | 513-2231 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | CX0123 | RecloserElectronic | 513-2231 | Recloser Electronic Patrol Inspection | Amps A Ø | 10 | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | CX0123 | RecloserElectronic | 513-2231 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | CX0123 | RecloserElectronic | 513-2231 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | KX0058 | RecloserElectronic | 513-2232 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | KX0058 | RecloserElectronic | 513-2232 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | KX0058 | RecloserElectronic | 513-2232 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | KX0058 | RecloserElectronic | 513-2232 | Recloser Electronic Patrol Inspection | Operations Counter | 54 | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | KX0058 | RecloserElectronic | 513-2232 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | KX0058 | RecloserElectronic | 513-2232 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | KX0058 | RecloserElectronic | 513-2232 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | KX0058 | RecloserElectronic | 513-2232 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | KX0058 | RecloserElectronic | 513-2232 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | KX0058 | RecloserElectronic | 513-2232 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | KX0058 | RecloserElectronic | 513-2232 | Recloser Electronic Patrol Inspection | Amps A Ø | 70 | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | KX0058 | RecloserElectronic | 513-2232 | Recloser Electronic Patrol Inspection | Amps B Ø | 53 | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | KX0058 | RecloserElectronic | 513-2232 | Recloser Electronic Patrol Inspection | Amps C Ø | 52 | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | KX0058 | RecloserElectronic | 513-2232 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | KX0058 | RecloserElectronic | 513-2232 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | KX0058 | RecloserElectronic | 513-2232 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | KX0058 | RecloserElectronic | 513-2232 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | KX0058 | RecloserElectronic | 513-2232 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | KX0058 | RecloserElectronic | 513-2232 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | KX0058 | RecloserElectronic | 513-2232 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | LTCC000695 | LTCControl | 513-1 | LTC Control Insp | LTC Output Voltage Level | 124.2 | VAC |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | LTCC000695 | LTCControl | 513-1 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | LTCC000695 | LTCControl | 513-1 | LTC Control Insp | LTC Operation Checked? | n | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | LTCC000695 | LTCControl | 513-1 | LTC Control Insp | General Comments | | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | LTCC000695 | LTCControl | 513-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | LTCC000695 | LTCControl | 513-1 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | LTCC000695 | LTCControl | 513-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | LTCC000695 | LTCControl | 513-1 | LTC Control Insp | All Connections OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | LTCMechanism | 513-1 | LTC Counter Readings | General Comments | | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | LTCMechanism | 513-1 | LTC Counter Readings | LTC As Found Counter | 31458 | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | LTCMechanism | 513-1 | LTC Counter Readings | LTC As Left Counter | 31461 | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | LTCMechanism | 513-1 | LTC Counter Readings | LTC Current Tap Position | 1R | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | LTCMechanism | 513-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | LTCMechanism | 513-1 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | LTCMechanism | 513-1 | LTC Counter Readings | LTC Operations Since Last Insp | 449 | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | LTCMechanism | 513-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | LTCMechanism | 513-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | LTCMechanism | 513-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | LTCMechanism | 513-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | LTCMechanism | 513-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | LTCMechanism | 513-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | LTCMechanism | 513-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | LTCMechanism | 513-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Readings | General Comments | | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Readings | LTC Totalizer Reading | 5760 | kw |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Readings | Totalizer Meter Reading | .6 | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45 | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000186 | BreakerSF6 | 455-708 | GCB Patrol Inspection | General Comments | | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000186 | BreakerSF6 | 455-708 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000186 | BreakerSF6 | 455-708 | GCB Patrol Inspection | Foundation Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000186 | BreakerSF6 | 455-708 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000186 | BreakerSF6 | 455-708 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000186 | BreakerSF6 | 455-708 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000186 | BreakerSF6 | 455-708 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000186 | BreakerSF6 | 455-708 | GCB Patrol Inspection | Grounds in Place? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000186 | BreakerSF6 | 455-708 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000186 | BreakerSF6 | 455-708 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000186 | BreakerSF6 | 455-708 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000186 | BreakerSF6 | 455-708 | GCB Patrol Inspection | SF6 Pressure | 88 | psi |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000186 | BreakerSF6 | 455-708 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000186 | BreakerSF6 | 455-708 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000186 | BreakerSF6 | 455-708 | GCB Patrol Inspection | Ambient Temperature | 38 | °F |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000186 | BreakerSF6 | 455-708 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000186 | BreakerSF6 | 455-708 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000186 | BreakerSF6 | 455-708 | GCB Readings | 9 Month Operations GCB New | 2 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000186 | BreakerSF6 | 455-708 | GCB Readings | Fault Operations | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000186 | BreakerSF6 | 455-708 | GCB Readings | Follow-up Action Required? | n | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000186 | BreakerSF6 | 455-708 | GCB Readings | General Comments | | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000186 | BreakerSF6 | 455-708 | GCB Readings | Maintenance Operations | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000186 | BreakerSF6 | 455-708 | GCB Readings | Num Operations Last 9 Months | 3 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000186 | BreakerSF6 | 455-708 | GCB Readings | Operations Counter AF | 57 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000186 | BreakerSF6 | 455-708 | GCB Readings | Operations Counter AL | 57 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000186 | BreakerSF6 | 455-708 | GCB Readings | Operations This Read SF6 | 1 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000186 | BreakerSF6 | 455-708 | GCB Readings | Switching Operations | 1 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Readings | 9 Month Operations | 7 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Readings | Unknown Operations | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Readings | Switching Operations | 1 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Readings | Accumulated Fault Duty A Ph V | .22 | % |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Readings | Accumulated Fault Duty B Ph V | .07 | % |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Readings | Accumulated Fault Duty C Ph V | .22 | % |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Readings | Amps A Ø | 367 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Readings | Amps B Ø | 361 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Readings | Amps C Ø | 377 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Readings | Fault Operations Ground | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Readings | Operations This Read Vac | 1 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Readings | Follow-up Action Required? | n | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Readings | Operations Counter AL | 193 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Readings | General Comments | | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Readings | Operations Counter AF | 193 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | W0358 | WithLTC | 513-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | ST000478 | Structure | 513-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | ST000478 | Structure | 513-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | ST000478 | Structure | 513-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | ST000478 | Structure | 513-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | ST000478 | Structure | 513-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | ST000478 | Structure | 513-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | ST000478 | Structure | 513-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | ST000478 | Structure | 513-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | ST000478 | Structure | 513-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | ST000478 | Structure | 513-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | ST000478 | Structure | 513-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | ST000478 | Structure | 513-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | ST000478 | Structure | 513-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | ST000478 | Structure | 513-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | ST000478 | Structure | 513-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | ST000478 | Structure | 513-Structure | Structure Patrol Inspection | General Comments | | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | ST000478 | Structure | 513-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | ST000478 | Structure | 513-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | ST000478 | Structure | 513-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | ST000478 | Structure | 513-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | ST000478 | Structure | 513-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | ST000478 | Structure | 513-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | FE000470 | Fence | 513-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | FE000470 | Fence | 513-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | FE000470 | Fence | 513-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | FE000470 | Fence | 513-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | FE000470 | Fence | 513-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | FE000470 | Fence | 513-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | FE000470 | Fence | 513-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | FE000470 | Fence | 513-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | FE000470 | Fence | 513-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | FE000470 | Fence | 513-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | FE000470 | Fence | 513-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | FE000470 | Fence | 513-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | FE000470 | Fence | 513-Fence | Fence Patrol Inspection | General Comments | | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | FE000470 | Fence | 513-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | FE000470 | Fence | 513-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | FE000470 | Fence | 513-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Patrol Inspection | General Comments | | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000889 | BreakerVacuum | 455-2479 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | YD000476 | Yard | 513-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | YD000476 | Yard | 513-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | YD000476 | Yard | 513-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | YD000476 | Yard | 513-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | YD000476 | Yard | 513-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | YD000476 | Yard | 513-Yard | Yard Patrol Inspection | General Comments | | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | YD000476 | Yard | 513-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | YD000476 | Yard | 513-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | YD000476 | Yard | 513-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | YD000476 | Yard | 513-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | YD000476 | Yard | 513-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | YD000476 | Yard | 513-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | YD000476 | Yard | 513-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | YD000476 | Yard | 513-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | YD000476 | Yard | 513-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/20/2023 12:11 | Distribution | Woodlawn Quarterly Inspection | YD000476 | Yard | 513-Yard | Yard Patrol Inspection | Ambient Temp | 34 | °F |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Readings | Unknown Operations | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Readings | Switching Operations | 1 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Readings | Amps C Ø | 172 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Readings | Amps B Ø | 167 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Readings | Amps A Ø | 167 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Readings | 9 Month Operations | 6 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Readings | Fault Operations Ground | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Readings | Follow-up Action Required? | n | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Readings | General Comments | | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Readings | Maintenance Operations | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Readings | Operations Counter AF | 187 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Readings | Operations Counter AL | 187 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Readings | Operations This Read Vac | 1 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Patrol Inspection | General Comments | | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000075 | BreakerVacuum | 455-2478 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Readings | Fault Operations Ground | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Readings | Follow-up Action Required? | n | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Readings | General Comments | | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Readings | Amps A Ø | 99 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Readings | Unknown Operations | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Readings | Switching Operations | 1 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Readings | Operations This Read Vac | 1 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Readings | Operations Counter AL | 270 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Readings | Operations Counter AF | 270 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Readings | Amps B Ø | 103 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Readings | Amps C Ø | 66 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Readings | Maintenance Operations | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Readings | Accumulated Fault Duty C Ph V | 6.07 | % |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Readings | Accumulated Fault Duty B Ph V | 8.5 | % |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Readings | Accumulated Fault Duty A Ph V | 7.9 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Readings | 9 Month Operations VCB New | 12 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Readings | 9 Month Operations | 13 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Patrol Inspection | General Comments | | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000076 | BreakerVacuum | 455-2477 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Readings | 9 Month Operations | 3 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Readings | Amps A Ø | 616 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Readings | Amps B Ø | 613 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Readings | Amps C Ø | 590 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Readings | General Comments | | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Readings | Operations Counter AF | 156 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Readings | Operations Counter AL | 156 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Readings | Switching Operations | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Readings | Unknown Operations | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Patrol Inspection | General Comments | | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BK000077 | BreakerVacuum | 455-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Readings | Winding Temp Max | 52 | °C |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.0878 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Readings | Oil Temp Present | 29 | °C |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Readings | LTC Totalizer Reading | 15664.32 | kw |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Readings | General Comments | | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | TX000010 | WithLTC | 455-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | LTCM000015 | LTCMechanism | 455-1 | LTC Counter Readings | LTC As Found Counter | 47141 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | LTCM000015 | LTCMechanism | 455-1 | LTC Counter Readings | LTC As Left Counter | 47144 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | LTCM000015 | LTCMechanism | 455-1 | LTC Counter Readings | General Comments | | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | LTCM000015 | LTCMechanism | 455-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | LTCM000015 | LTCMechanism | 455-1 | LTC Counter Readings | LTC Operations Since Last Insp | 1375 | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | LTCM000015 | LTCMechanism | 455-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | LTCM000015 | LTCMechanism | 455-1 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | LTCM000015 | LTCMechanism | 455-1 | LTC Counter Readings | LTC Current Tap Position | 2R | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | LTCM000015 | LTCMechanism | 455-1 | LTC Counter Readings | LTC Max Tap Position | 5R | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | LTCM000015 | LTCMechanism | 455-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | LTCM000015 | LTCMechanism | 455-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | LTCM000015 | LTCMechanism | 455-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | LTCM000015 | LTCMechanism | 455-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 21 | °C |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | LTCM000015 | LTCMechanism | 455-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 44 | °C |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | LTCM000015 | LTCMechanism | 455-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | LTCM000015 | LTCMechanism | 455-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | LTCM000015 | LTCMechanism | 455-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | LTCM000015 | LTCMechanism | 455-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | LTCC000609 | LTCControl | 455-1 | LTC Control Insp | LTC Output Voltage Level | 124.2 | VAC |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | LTCC000609 | LTCControl | 455-1 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | LTCC000609 | LTCControl | 455-1 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | LTCC000609 | LTCControl | 455-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | LTCC000609 | LTCControl | 455-1 | LTC Control Insp | All Connections OK? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | LTCC000609 | LTCControl | 455-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | LTCC000609 | LTCControl | 455-1 | LTC Control Insp | General Comments | | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | LTCC000609 | LTCControl | 455-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BCH000955 | Charger | 455-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BCH000955 | Charger | 455-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BCH000955 | Charger | 455-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BCH000955 | Charger | 455-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.1 | amps |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BCH000955 | Charger | 455-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.7 | VDC |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BCH000955 | Charger | 455-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BCH000955 | Charger | 455-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0 | millivolts |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BCH000955 | Charger | 455-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.7 | VDC |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BAT000890 | Battery | 455-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BAT000890 | Battery | 455-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BAT000890 | Battery | 455-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 65.3 | VDC |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BAT000890 | Battery | 455-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 68.4 | VDC |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BAT000890 | Battery | 455-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BAT000890 | Battery | 455-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BAT000890 | Battery | 455-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BAT000890 | Battery | 455-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BAT000890 | Battery | 455-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BAT000890 | Battery | 455-Battery Bank | Battery Patrol Inspection | Bat Volt 1Min After Chgr Trip | 129 | VDC |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BAT000890 | Battery | 455-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BAT000890 | Battery | 455-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BAT000890 | Battery | 455-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BAT000890 | Battery | 455-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | BAT000890 | Battery | 455-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | CH000388 | ControlHouse | 455-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | CH000388 | ControlHouse | 455-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | CH000388 | ControlHouse | 455-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | CH000388 | ControlHouse | 455-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | CH000388 | ControlHouse | 455-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | CH000388 | ControlHouse | 455-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | CH000388 | ControlHouse | 455-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | CH000388 | ControlHouse | 455-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | CH000388 | ControlHouse | 455-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | CH000388 | ControlHouse | 455-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | CH000388 | ControlHouse | 455-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | CH000388 | ControlHouse | 455-Control House | Control House Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | CH000388 | ControlHouse | 455-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | CH000388 | ControlHouse | 455-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | CH000388 | ControlHouse | 455-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | CH000388 | ControlHouse | 455-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | CH000388 | ControlHouse | 455-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | CH000388 | ControlHouse | 455-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | CH000388 | ControlHouse | 455-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | ST000837 | Structure | 455-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | ST000837 | Structure | 455-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | ST000837 | Structure | 455-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | ST000837 | Structure | 455-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | ST000837 | Structure | 455-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | ST000837 | Structure | 455-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | ST000837 | Structure | 455-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | ST000837 | Structure | 455-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | ST000837 | Structure | 455-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | ST000837 | Structure | 455-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | ST000837 | Structure | 455-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | ST000837 | Structure | 455-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | ST000837 | Structure | 455-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | ST000837 | Structure | 455-Structure | Structure Patrol Inspection | General Comments | | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | ST000837 | Structure | 455-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | ST000837 | Structure | 455-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | ST000837 | Structure | 455-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | ST000837 | Structure | 455-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | ST000837 | Structure | 455-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | ST000837 | Structure | 455-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | FE000803 | Fence | 455-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | FE000803 | Fence | 455-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | FE000803 | Fence | 455-Fence | Fence Patrol Inspection | General Comments | | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | FE000803 | Fence | 455-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | FE000803 | Fence | 455-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | FE000803 | Fence | 455-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | FE000803 | Fence | 455-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | FE000803 | Fence | 455-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | FE000803 | Fence | 455-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | FE000803 | Fence | 455-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | FE000803 | Fence | 455-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | FE000803 | Fence | 455-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | FE000803 | Fence | 455-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | FE000803 | Fence | 455-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | FE000803 | Fence | 455-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | FE000803 | Fence | 455-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | YD000843 | Yard | 455-Yard | Yard Patrol Inspection | Ambient Temp | 38 | °F |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | YD000843 | Yard | 455-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | YD000843 | Yard | 455-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | YD000843 | Yard | 455-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | YD000843 | Yard | 455-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | YD000843 | Yard | 455-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | YD000843 | Yard | 455-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | YD000843 | Yard | 455-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | YD000843 | Yard | 455-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | YD000843 | Yard | 455-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | YD000843 | Yard | 455-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | YD000843 | Yard | 455-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | YD000843 | Yard | 455-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | YD000843 | Yard | 455-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | YD000843 | Yard | 455-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | YD000843 | Yard | 455-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | YD000843 | Yard | 455-Yard | Yard Patrol Inspection | General Comments | | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | YD000843 | Yard | 455-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | YD000843 | Yard | 455-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/20/2023 12:06 | Distribution | Black Branch Road Quarterly Inspection | YD000843 | Yard | 455-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Readings | Unknown Operations | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Readings | Switching Operations | 3 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Readings | Operations This Read Vac | 3 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Readings | Operations Counter AL | 288 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Readings | Operations Counter AF | 285 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Readings | Maintenance Operations | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Readings | General Comments | | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Readings | Follow-up Action Required? | n | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Readings | Fault Operations Ground | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Readings | 9 Month Operations | 3 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Readings | Accumulated Fault Duty A Ph V | .48 | % |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Readings | Accumulated Fault Duty B Ph V | .48 | % |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Readings | Amps A Ø | 188 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Readings | Amps B Ø | 186 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Readings | Amps C Ø | 191 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Patrol Inspection | General Comments | | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0073 | BreakerVacuum | 552-2463 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Readings | 9 Month Operations | 3 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Readings | Accumulated Fault Duty A Ph V | .96 | % |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Readings | Accumulated Fault Duty B Ph V | 1.43 | % |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Readings | Accumulated Fault Duty C Ph V | .96 | % |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Readings | Unknown Operations | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Readings | Switching Operations | 1 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Readings | Operations This Read Vac | 1 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Readings | Operations Counter AL | 399 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Readings | Operations Counter AF | 398 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Readings | Maintenance Operations | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Readings | General Comments | | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Readings | Follow-up Action Required? | n | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Readings | Fault Operations Ground | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Readings | Amps C Ø | 240 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Readings | Amps B Ø | 244 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Readings | Amps A Ø | 258 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Patrol Inspection | General Comments | | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | K0074 | BreakerVacuum | 552-2462 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Readings | 9 Month Operations | 3 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Readings | Accumulated Fault Duty A Ph V | 3.08 | % |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Readings | Accumulated Fault Duty B Ph V | 2.06 | % |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Readings | Accumulated Fault Duty C Ph V | 1.03 | % |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Readings | Amps A Ø | 140 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Readings | Amps B Ø | 144 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Readings | Fault Operations Ground | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Readings | Switching Operations | 1 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Readings | Operations This Read Vac | 1 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Readings | Operations Counter AL | 287 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Readings | Operations Counter AF | 286 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Readings | Maintenance Operations | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Readings | Follow-up Action Required? | n | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Readings | Amps C Ø | 153 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Readings | General Comments | | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Patrol Inspection | General Comments | | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0257 | BreakerVacuum | 552-2464 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Readings | Operations Counter AF | 208 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Readings | Operations Counter AL | 208 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Readings | Switching Operations | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Readings | Unknown Operations | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Readings | Amps C Ø | 480 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Readings | General Comments | | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Readings | Amps B Ø | 480 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Readings | Amps A Ø | 480 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Readings | Accumulated Fault Duty C Ph V | 1.15 | % |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Readings | Accumulated Fault Duty B Ph V | 1.15 | % |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Readings | Accumulated Fault Duty A Ph V | 1.15 | % |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Readings | 9 Month Operations | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Patrol Inspection | General Comments | | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | CB0208 | BreakerVacuum | 552-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | LTCC000627 | LTCControl | 552-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | LTCC000627 | LTCControl | 552-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | LTCC000627 | LTCControl | 552-1 | LTC Control Insp | General Comments | | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | LTCC000627 | LTCControl | 552-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | LTCC000627 | LTCControl | 552-1 | LTC Control Insp | All Connections OK? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | LTCC000627 | LTCControl | 552-1 | LTC Control Insp | LTC Output Voltage Level | 123.9 | VAC |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | LTCC000627 | LTCControl | 552-1 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | LTCC000627 | LTCControl | 552-1 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | LTCMechanism | 552-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | LTCMechanism | 552-1 | LTC Counter Readings | LTC Operations Since Last Insp | 363 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | LTCMechanism | 552-1 | LTC Counter Readings | LTC Min Tap Position | 11L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | LTCMechanism | 552-1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | LTCMechanism | 552-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | LTCMechanism | 552-1 | LTC Counter Readings | LTC As Left Counter | 321110 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | LTCMechanism | 552-1 | LTC Counter Readings | LTC As Found Counter | 321107 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | LTCMechanism | 552-1 | LTC Counter Readings | General Comments | | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | LTCMechanism | 552-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | LTCMechanism | 552-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | LTCMechanism | 552-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | LTCMechanism | 552-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | LTCMechanism | 552-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | LTCMechanism | 552-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | LTCMechanism | 552-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | LTCMechanism | 552-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Readings | General Comments | | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Readings | LTC Totalizer Reading | 14562 | kw |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Readings | Oil Temp Max | 70 | °C |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Readings | Totalizer Meter Reading | .809 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Readings | Winding Temp Max | 70 | °C |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45 | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | C0521 | WithLTC | 552-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | BAT001414 | Battery | 552-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Water Added | If low,note cell #~'s |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | BAT001414 | Battery | 552-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | BAT001414 | Battery | 552-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | BAT001414 | Battery | 552-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | BAT001414 | Battery | 552-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 33 | °F |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | BAT001414 | Battery | 552-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | BAT001414 | Battery | 552-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | BAT001414 | Battery | 552-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | BAT001414 | Battery | 552-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | BAT001414 | Battery | 552-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.3 | VDC |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | BAT001414 | Battery | 552-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | BAT001414 | Battery | 552-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | BAT001414 | Battery | 552-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26 | VDC |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | BCH001256 | Charger | 552-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0 | millivolts |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | BCH001256 | Charger | 552-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | BCH001256 | Charger | 552-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | BCH001256 | Charger | 552-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.3 | amps |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | BCH001256 | Charger | 552-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | BCH001256 | Charger | 552-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | ST000563 | Structure | 552-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | ST000563 | Structure | 552-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | ST000563 | Structure | 552-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | ST000563 | Structure | 552-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | ST000563 | Structure | 552-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | ST000563 | Structure | 552-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | ST000563 | Structure | 552-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | ST000563 | Structure | 552-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | ST000563 | Structure | 552-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | ST000563 | Structure | 552-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | ST000563 | Structure | 552-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | ST000563 | Structure | 552-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | ST000563 | Structure | 552-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | ST000563 | Structure | 552-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | ST000563 | Structure | 552-Structure | Structure Patrol Inspection | General Comments | | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | ST000563 | Structure | 552-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | ST000563 | Structure | 552-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | ST000563 | Structure | 552-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | ST000563 | Structure | 552-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | ST000563 | Structure | 552-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | ST000563 | Structure | 552-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | ST000563 | Structure | 552-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | FE000552 | Fence | 552-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | FE000552 | Fence | 552-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | FE000552 | Fence | 552-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | FE000552 | Fence | 552-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | FE000552 | Fence | 552-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | FE000552 | Fence | 552-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | FE000552 | Fence | 552-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | FE000552 | Fence | 552-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | FE000552 | Fence | 552-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | FE000552 | Fence | 552-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | FE000552 | Fence | 552-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | FE000552 | Fence | 552-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | FE000552 | Fence | 552-Fence | Fence Patrol Inspection | General Comments | | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | FE000552 | Fence | 552-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | FE000552 | Fence | 552-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | FE000552 | Fence | 552-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | YD000559 | Yard | 552-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | YD000559 | Yard | 552-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | YD000559 | Yard | 552-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | YD000559 | Yard | 552-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | YD000559 | Yard | 552-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | YD000559 | Yard | 552-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | YD000559 | Yard | 552-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | YD000559 | Yard | 552-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | YD000559 | Yard | 552-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | YD000559 | Yard | 552-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | YD000559 | Yard | 552-Yard | Yard Patrol Inspection | General Comments | | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | YD000559 | Yard | 552-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | YD000559 | Yard | 552-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | YD000559 | Yard | 552-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | YD000559 | Yard | 552-Yard | Yard Patrol Inspection | Ambient Temp | 33 | °F |
| 3/20/2023 11:15 | Distribution | Elizabethtown Industrial Quarterly Inspection | YD000559 | Yard | 552-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1419 | Regulator | 850-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1419 | Regulator | 850-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1419 | Regulator | 850-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 71200 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1419 | Regulator | 850-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1419 | Regulator | 850-1 C | Regulator Patrol Inspection | Reg Operation Checked? | n | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1419 | Regulator | 850-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1419 | Regulator | 850-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1419 | Regulator | 850-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1419 | Regulator | 850-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1419 | Regulator | 850-1 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1419 | Regulator | 850-1 C | Regulator Patrol Inspection | Max Tap Position | 9R | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1419 | Regulator | 850-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1419 | Regulator | 850-1 C | Regulator Patrol Inspection | General Comments | | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1419 | Regulator | 850-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1419 | Regulator | 850-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1419 | Regulator | 850-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1419 | Regulator | 850-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1419 | Regulator | 850-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1419 | Regulator | 850-1 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1419 | Regulator | 850-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1419 | Regulator | 850-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1419 | Regulator | 850-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1419 | Regulator | 850-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1418 | Regulator | 850-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1418 | Regulator | 850-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1418 | Regulator | 850-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1418 | Regulator | 850-1 B | Regulator Patrol Inspection | Max Tap Position | 9R | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1418 | Regulator | 850-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1418 | Regulator | 850-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1418 | Regulator | 850-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1418 | Regulator | 850-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1418 | Regulator | 850-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1418 | Regulator | 850-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1418 | Regulator | 850-1 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1418 | Regulator | 850-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1418 | Regulator | 850-1 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1418 | Regulator | 850-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1418 | Regulator | 850-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1418 | Regulator | 850-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1418 | Regulator | 850-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1418 | Regulator | 850-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1418 | Regulator | 850-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 75859 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1418 | Regulator | 850-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1418 | Regulator | 850-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1418 | Regulator | 850-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1418 | Regulator | 850-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1417 | Regulator | 850-1 A | Regulator Patrol Inspection | General Comments | | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1417 | Regulator | 850-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1417 | Regulator | 850-1 A | Regulator Patrol Inspection | Max Tap Position | 9R | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1417 | Regulator | 850-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1417 | Regulator | 850-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1417 | Regulator | 850-1 A | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1417 | Regulator | 850-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1417 | Regulator | 850-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1417 | Regulator | 850-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1417 | Regulator | 850-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1417 | Regulator | 850-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1417 | Regulator | 850-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1417 | Regulator | 850-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 71570 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1417 | Regulator | 850-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1417 | Regulator | 850-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1417 | Regulator | 850-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1417 | Regulator | 850-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1417 | Regulator | 850-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1417 | Regulator | 850-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1417 | Regulator | 850-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1417 | Regulator | 850-1 A | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1417 | Regulator | 850-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | R1417 | Regulator | 850-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | S0056 | NonLTC | 850-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | S0056 | NonLTC | 850-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | S0056 | NonLTC | 850-1 | NonLTC Transformer Readings | General Comments | | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | S0056 | NonLTC | 850-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | S0056 | NonLTC | 850-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 10788.48 | kw |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | S0056 | NonLTC | 850-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | S0056 | NonLTC | 850-1 | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | S0056 | NonLTC | 850-1 | NonLTC Transformer Readings | Oil Temp Present | 32 | °C |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | S0056 | NonLTC | 850-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | S0056 | NonLTC | 850-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.1238 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | S0056 | NonLTC | 850-1 | NonLTC Transformer Readings | Winding Temp Max | 60 | °C |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | S0056 | NonLTC | 850-1 | NonLTC Transformer Readings | Winding Temp Present | 35 | °C |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | S0056 | NonLTC | 850-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | S0056 | NonLTC | 850-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | S0056 | NonLTC | 850-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | S0056 | NonLTC | 850-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | S0056 | NonLTC | 850-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | S0056 | NonLTC | 850-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | S0056 | NonLTC | 850-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | S0056 | NonLTC | 850-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | S0056 | NonLTC | 850-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | S0056 | NonLTC | 850-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | S0056 | NonLTC | 850-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | S0056 | NonLTC | 850-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | S0056 | NonLTC | 850-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | S0056 | NonLTC | 850-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | S0056 | NonLTC | 850-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Readings | General Comments | | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Readings | Maintenance Operations | 0 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Readings | Operations Counter AF | 188 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Readings | Operations Counter AL | 188 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Readings | Operations This Read Vac | 0 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Readings | Switching Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Readings | Unknown Operations | 0 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Readings | Follow-up Action Required? | n | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Readings | Fault Operations Ground | 0 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Readings | Amps C Ø | 160.0 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Readings | 9 Month Operations | 0 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Readings | Amps B Ø | 146.0 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Readings | Amps A Ø | 138.0 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Readings | 9 Month Operations | 0 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Readings | Fault Operations Ground | 0 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Readings | Follow-up Action Required? | n | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Readings | General Comments | | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Readings | Maintenance Operations | 0 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Readings | Operations Counter AF | 210 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Readings | Operations Counter AL | 210 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Readings | Operations This Read Vac | 0 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Readings | Switching Operations | 0 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Readings | Unknown Operations | 0 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Readings | Amps C Ø | 138.0 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Readings | Amps B Ø | 132.0 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Readings | Amps A Ø | 143.0 | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Patrol Inspection | General Comments | | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001169 | BreakerVacuum | 850-4511 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Patrol Inspection | General Comments | | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BK001159 | BreakerVacuum | 850-4512 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | CH000466 | ControlHouse | 850-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | CH000466 | ControlHouse | 850-Control House | Control House Patrol Inspection | Broom on Site? | n | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | CH000466 | ControlHouse | 850-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | CH000466 | ControlHouse | 850-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | CH000466 | ControlHouse | 850-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | CH000466 | ControlHouse | 850-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | CH000466 | ControlHouse | 850-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | CH000466 | ControlHouse | 850-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | CH000466 | ControlHouse | 850-Control House | Control House Patrol Inspection | Trash Emptied? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | CH000466 | ControlHouse | 850-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | CH000466 | ControlHouse | 850-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | CH000466 | ControlHouse | 850-Control House | Control House Patrol Inspection | General Comments | | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | CH000466 | ControlHouse | 850-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | CH000466 | ControlHouse | 850-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | CH000466 | ControlHouse | 850-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | CH000466 | ControlHouse | 850-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | CH000466 | ControlHouse | 850-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | ST000112 | Structure | 850-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | ST000112 | Structure | 850-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | ST000112 | Structure | 850-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | ST000112 | Structure | 850-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | ST000112 | Structure | 850-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | ST000112 | Structure | 850-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | ST000112 | Structure | 850-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | ST000112 | Structure | 850-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | ST000112 | Structure | 850-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | ST000112 | Structure | 850-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | ST000112 | Structure | 850-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | ST000112 | Structure | 850-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | ST000112 | Structure | 850-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | ST000112 | Structure | 850-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | ST000112 | Structure | 850-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | ST000112 | Structure | 850-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | ST000112 | Structure | 850-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | ST000112 | Structure | 850-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | ST000112 | Structure | 850-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | ST000112 | Structure | 850-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | ST000112 | Structure | 850-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | ST000112 | Structure | 850-Structure | Structure Patrol Inspection | General Comments | | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | FE000108 | Fence | 850-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | FE000108 | Fence | 850-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | FE000108 | Fence | 850-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | FE000108 | Fence | 850-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | FE000108 | Fence | 850-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | FE000108 | Fence | 850-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | FE000108 | Fence | 850-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | n | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | FE000108 | Fence | 850-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | FE000108 | Fence | 850-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | FE000108 | Fence | 850-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | FE000108 | Fence | 850-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | FE000108 | Fence | 850-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | n | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | FE000108 | Fence | 850-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | FE000108 | Fence | 850-Fence | Fence Patrol Inspection | General Comments | large tree overhanging fence in front corner. | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | FE000108 | Fence | 850-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | FE000108 | Fence | 850-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BAT001195 | Battery | 850-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BAT001195 | Battery | 850-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BAT001195 | Battery | 850-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BAT001195 | Battery | 850-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.0 | VDC |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BAT001195 | Battery | 850-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BAT001195 | Battery | 850-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BAT001195 | Battery | 850-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BAT001195 | Battery | 850-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BAT001195 | Battery | 850-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BAT001195 | Battery | 850-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BAT001195 | Battery | 850-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BAT001195 | Battery | 850-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BAT001195 | Battery | 850-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BCH001285 | Charger | 850-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BCH001285 | Charger | 850-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.2 | amps |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BCH001285 | Charger | 850-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BCH001285 | Charger | 850-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BCH001285 | Charger | 850-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BCH001285 | Charger | 850-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.860 | millivolts |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BCH001285 | Charger | 850-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | BCH001285 | Charger | 850-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | YD000107 | Yard | 850-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | YD000107 | Yard | 850-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | YD000107 | Yard | 850-Yard | Yard Patrol Inspection | General Comments | | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | YD000107 | Yard | 850-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | YD000107 | Yard | 850-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | YD000107 | Yard | 850-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | YD000107 | Yard | 850-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | YD000107 | Yard | 850-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | YD000107 | Yard | 850-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | YD000107 | Yard | 850-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | YD000107 | Yard | 850-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/17/2023 12:51 | Distribution | McKee Road Quarterly Inspection | YD000107 | Yard | 850-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Readings | Amps C Ø | 240.0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Readings | Amps B Ø | 200.0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Readings | Amps A Ø | 200.0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Readings | Switching Operations | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Readings | Operations This Read Vac | 1 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Readings | Operations Counter AL | 299 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Readings | Operations Counter AF | 299 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Readings | Maintenance Operations | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Readings | 9 Month Operations | 1 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Readings | General Comments | | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Readings | Unknown Operations | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Readings | Follow-up Action Required? | n | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Readings | Fault Operations Ground | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Readings | Fault Operations A Ø | 1 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Readings | Fault Adjusted Amps A Phase V | 6.13 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Patrol Inspection | General Comments | | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0417 | BreakerVacuum | 728-0644 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Readings | Amps C Ø | 320.0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Readings | Amps B Ø | 300.0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Readings | Amps A Ø | 340.0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Readings | 9 Month Operations | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Readings | Unknown Operations | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Readings | Switching Operations | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Readings | Operations Counter AL | 160 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Readings | Operations Counter AF | 160 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Readings | General Comments | | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Patrol Inspection | General Comments | | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0419 | BreakerVacuum | 728-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Readings | Unknown Operations | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Readings | Switching Operations | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Readings | Operations This Read Vac | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Readings | Amps C Ø | 110.0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Readings | Amps B Ø | 100.0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Readings | Amps A Ø | 100.0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Readings | 9 Month Operations | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Readings | Operations Counter AL | 302 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Readings | Operations Counter AF | 302 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Readings | Maintenance Operations | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Readings | General Comments | | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Readings | Follow-up Action Required? | n | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Readings | Fault Operations Ground | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Patrol Inspection | General Comments | | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BB0476 | BreakerVacuum | 728-0649 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Readings | Fault Operations Ground | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Readings | Follow-up Action Required? | n | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Readings | General Comments | | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Readings | Maintenance Operations | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Readings | Operations Counter AF | 193 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Readings | Operations Counter AL | 193 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Readings | Operations This Read Vac | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Readings | Switching Operations | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Readings | Unknown Operations | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Readings | 9 Month Operations | 5 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Readings | Amps A Ø | 65.0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Readings | Amps B Ø | 66.0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Readings | Amps C Ø | 70.0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Patrol Inspection | General Comments | | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BK001794 | BreakerVacuum | 728-0645 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | LTCC000374 | LTCControl | 728-1 | LTC Control Insp | All Connections OK? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | LTCC000374 | LTCControl | 728-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | LTCC000374 | LTCControl | 728-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | LTCC000374 | LTCControl | 728-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | LTCC000374 | LTCControl | 728-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | LTCC000374 | LTCControl | 728-1 | LTC Control Insp | General Comments | | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | LTCC000374 | LTCControl | 728-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | LTCC000374 | LTCControl | 728-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | LTCMechanism | 728-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | LTCMechanism | 728-1 | LTC Counter Readings | General Comments | | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | LTCMechanism | 728-1 | LTC Counter Readings | LTC As Found Counter | 86760 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | LTCMechanism | 728-1 | LTC Counter Readings | LTC As Left Counter | 86760 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | LTCMechanism | 728-1 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | LTCMechanism | 728-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | LTCMechanism | 728-1 | LTC Counter Readings | LTC Operations Since Last Insp | 139 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | LTCMechanism | 728-1 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | LTCMechanism | 728-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | LTCMechanism | 728-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | LTCMechanism | 728-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | LTCMechanism | 728-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | LTCMechanism | 728-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | LTCMechanism | 728-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Readings | General Comments | | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Readings | LTC Totalizer Reading | 11606.40 | kw |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Readings | Totalizer Meter Reading | .8060 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Readings | Winding Temp Max | 50 | °C |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 65.00 | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Patrol Inspection | General Comments | | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Readings | 9 Month Operations | 3 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Readings | Amps A Ø | 35.0 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Readings | Amps B Ø | 30.0 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Readings | Amps C Ø | 28.0 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Readings | Unknown Operations | 0 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Readings | Switching Operations | 0 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Readings | Operations This Read Vac | 0 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Readings | Operations Counter AL | 186 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Readings | Operations Counter AF | 186 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Readings | Maintenance Operations | 0 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Readings | General Comments | | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Readings | Follow-up Action Required? | n | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Readings | Fault Operations Ground | 0 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001292 | BreakerVacuum | 023-0807 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Patrol Inspection | General Comments | | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Readings | Fault Operations Ground | 0 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Readings | Follow-up Action Required? | n | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Readings | General Comments | | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Readings | Maintenance Operations | 0 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Readings | Operations Counter AF | 186 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Readings | Operations Counter AL | 186 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Readings | Operations This Read Vac | 0 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Readings | 9 Month Operations | 2 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Readings | Unknown Operations | 0 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Readings | Switching Operations | 0 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Readings | Amps C Ø | 45.0 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Readings | Amps B Ø | 59.0 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Readings | Amps A Ø | 49.0 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | BK001293 | BreakerVacuum | 023-0808 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1311 | Regulator | 023-5 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1311 | Regulator | 023-5 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1311 | Regulator | 023-5 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1311 | Regulator | 023-5 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1311 | Regulator | 023-5 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1311 | Regulator | 023-5 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1311 | Regulator | 023-5 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1311 | Regulator | 023-5 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1311 | Regulator | 023-5 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1311 | Regulator | 023-5 C | Regulator Patrol Inspection | Regulator As Left Counter | 68714 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1311 | Regulator | 023-5 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1311 | Regulator | 023-5 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1311 | Regulator | 023-5 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1311 | Regulator | 023-5 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1311 | Regulator | 023-5 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1311 | Regulator | 023-5 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1311 | Regulator | 023-5 C | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1311 | Regulator | 023-5 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1311 | Regulator | 023-5 C | Regulator Patrol Inspection | General Comments | | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1311 | Regulator | 023-5 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1311 | Regulator | 023-5 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1311 | Regulator | 023-5 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1311 | Regulator | 023-5 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1311 | Regulator | 023-5 C | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1312 | Regulator | 023-5 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1312 | Regulator | 023-5 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1312 | Regulator | 023-5 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1312 | Regulator | 023-5 A | Regulator Patrol Inspection | General Comments | | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1312 | Regulator | 023-5 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1312 | Regulator | 023-5 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1312 | Regulator | 023-5 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1312 | Regulator | 023-5 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1312 | Regulator | 023-5 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1312 | Regulator | 023-5 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1312 | Regulator | 023-5 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1312 | Regulator | 023-5 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1312 | Regulator | 023-5 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1312 | Regulator | 023-5 A | Regulator Patrol Inspection | Current Tap Position | 5L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1312 | Regulator | 023-5 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1312 | Regulator | 023-5 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1312 | Regulator | 023-5 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1312 | Regulator | 023-5 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1312 | Regulator | 023-5 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1312 | Regulator | 023-5 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1312 | Regulator | 023-5 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1312 | Regulator | 023-5 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1312 | Regulator | 023-5 A | Regulator Patrol Inspection | Regulator As Left Counter | 66853 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1312 | Regulator | 023-5 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1313 | Regulator | 023-5 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1313 | Regulator | 023-5 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1313 | Regulator | 023-5 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1313 | Regulator | 023-5 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1313 | Regulator | 023-5 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1313 | Regulator | 023-5 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1313 | Regulator | 023-5 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1313 | Regulator | 023-5 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1313 | Regulator | 023-5 B | Regulator Patrol Inspection | Regulator As Left Counter | 72627 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1313 | Regulator | 023-5 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1313 | Regulator | 023-5 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1313 | Regulator | 023-5 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1313 | Regulator | 023-5 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1313 | Regulator | 023-5 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1313 | Regulator | 023-5 B | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1313 | Regulator | 023-5 B | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1313 | Regulator | 023-5 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1313 | Regulator | 023-5 B | Regulator Patrol Inspection | General Comments | | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1313 | Regulator | 023-5 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1313 | Regulator | 023-5 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1313 | Regulator | 023-5 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1313 | Regulator | 023-5 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1313 | Regulator | 023-5 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | R1313 | Regulator | 023-5 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Readings | General Comments | | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3810.24 | kw |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Readings | Totalizer Meter Reading | .7938 | |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Readings | Winding Temp Max | 35 | °C |
| 3/17/2023 11:26 | Distribution | Millersburg Quarterly Inspection | TX000231 | NonLTC | 023-5 | NonLTC Transformer Readings | Winding Temp Present | 25 | °C |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | B0424 | WithLTC | 728-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BCH001247 | Charger | 728-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BCH001247 | Charger | 728-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BCH001247 | Charger | 728-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BCH001247 | Charger | 728-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BCH001247 | Charger | 728-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .8 | amps |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BCH001247 | Charger | 728-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BCH001247 | Charger | 728-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BCH001247 | Charger | 728-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BAT001308 | Battery | 728-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BAT001308 | Battery | 728-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BAT001308 | Battery | 728-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BAT001308 | Battery | 728-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BAT001308 | Battery | 728-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BAT001308 | Battery | 728-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BAT001308 | Battery | 728-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BAT001308 | Battery | 728-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BAT001308 | Battery | 728-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BAT001308 | Battery | 728-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BAT001308 | Battery | 728-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BAT001308 | Battery | 728-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BAT001308 | Battery | 728-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BAT001308 | Battery | 728-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | BAT001308 | Battery | 728-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | ST000374 | Structure | 728-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | ST000374 | Structure | 728-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | ST000374 | Structure | 728-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | ST000374 | Structure | 728-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | ST000374 | Structure | 728-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | ST000374 | Structure | 728-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | ST000374 | Structure | 728-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | ST000374 | Structure | 728-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | ST000374 | Structure | 728-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | ST000374 | Structure | 728-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | ST000374 | Structure | 728-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | ST000374 | Structure | 728-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | ST000374 | Structure | 728-Structure | Structure Patrol Inspection | General Comments | | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | ST000374 | Structure | 728-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | ST000374 | Structure | 728-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | ST000374 | Structure | 728-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | ST000374 | Structure | 728-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | ST000374 | Structure | 728-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | ST000374 | Structure | 728-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | ST000374 | Structure | 728-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | ST000374 | Structure | 728-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | ST000374 | Structure | 728-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | FE000366 | Fence | 728-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | FE000366 | Fence | 728-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | FE000366 | Fence | 728-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | FE000366 | Fence | 728-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | FE000366 | Fence | 728-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | FE000366 | Fence | 728-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | FE000366 | Fence | 728-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | FE000366 | Fence | 728-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | FE000366 | Fence | 728-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | FE000366 | Fence | 728-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | FE000366 | Fence | 728-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | FE000366 | Fence | 728-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | FE000366 | Fence | 728-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | FE000366 | Fence | 728-Fence | Fence Patrol Inspection | General Comments | | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | FE000366 | Fence | 728-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | FE000366 | Fence | 728-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | YD000372 | Yard | 728-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | YD000372 | Yard | 728-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | YD000372 | Yard | 728-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | YD000372 | Yard | 728-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | YD000372 | Yard | 728-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | YD000372 | Yard | 728-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | YD000372 | Yard | 728-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | YD000372 | Yard | 728-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | YD000372 | Yard | 728-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | YD000372 | Yard | 728-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | YD000372 | Yard | 728-Yard | Yard Patrol Inspection | General Comments | | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | YD000372 | Yard | 728-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | YD000372 | Yard | 728-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | YD000372 | Yard | 728-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | YD000372 | Yard | 728-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | YD000372 | Yard | 728-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/17/2023 11:57 | Distribution | Winchester Industrial Quarterly Inspection | YD000372 | Yard | 728-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Patrol Inspection | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Readings | Unknown Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Readings | Switching Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Readings | Operations This Read Vac | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Readings | Operations Counter AL | 239 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Readings | Operations Counter AF | 239 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Readings | Maintenance Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Readings | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Readings | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Readings | Fault Operations Ground | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Readings | Amps C Ø | 0.0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Readings | Amps B Ø | 0.0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Readings | Amps A Ø | 0.0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001616 | BreakerVacuum | 663-0799 | VCB Readings | 9 Month Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Patrol Inspection | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Readings | 9 Month Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Readings | Amps A Ø | 108.0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Readings | Amps B Ø | 108.0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Readings | Amps C Ø | 118.0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Readings | Fault Operations Ground | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Readings | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Readings | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Readings | Maintenance Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Readings | Operations Counter AF | 167 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Readings | Unknown Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Readings | Switching Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Readings | Operations This Read Vac | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001615 | BreakerVacuum | 663-0798 | VCB Readings | Operations Counter AL | 167 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Patrol Inspection | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Readings | Unknown Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Readings | Switching Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Readings | Operations This Read Vac | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Readings | Operations Counter AL | 163 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Readings | Operations Counter AF | 163 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Readings | Maintenance Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Readings | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Readings | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Readings | Fault Operations Ground | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Readings | 9 Month Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Readings | Amps A Ø | 119.0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Readings | Amps B Ø | 128.0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001614 | BreakerVacuum | 663-0797 | VCB Readings | Amps C Ø | 138.0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Patrol Inspection | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Readings | Operations Counter AL | 176 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Readings | Operations Counter AF | 176 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Readings | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Readings | Switching Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Readings | Unknown Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Readings | 9 Month Operations | 1 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Readings | Amps A Ø | 241.0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Readings | Amps B Ø | 258.0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Readings | Amps C Ø | 248.0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001618 | BreakerVacuum | 663-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001506 | BreakerSF6 | 663-628 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001506 | BreakerSF6 | 663-628 | GCB Patrol Inspection | SF6 Pressure | 68 | psi |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001506 | BreakerSF6 | 663-628 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001506 | BreakerSF6 | 663-628 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001506 | BreakerSF6 | 663-628 | GCB Patrol Inspection | General Comments | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001506 | BreakerSF6 | 663-628 | GCB Patrol Inspection | Ambient Temperature | 50 | °F |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001506 | BreakerSF6 | 663-628 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001506 | BreakerSF6 | 663-628 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001506 | BreakerSF6 | 663-628 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001506 | BreakerSF6 | 663-628 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001506 | BreakerSF6 | 663-628 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001506 | BreakerSF6 | 663-628 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Readings | Switching Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Readings | Operations Counter AL | 176 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Readings | Operations Counter AF | 176 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Readings | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Readings | 9 Month Operations | 1 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001619 | BreakerVacuum | 663-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Patrol Inspection | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Readings | Unknown Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Readings | Switching Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Readings | Operations This Read Vac | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Readings | Operations Counter AL | 172 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Readings | Operations Counter AF | 172 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Readings | Maintenance Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Readings | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Readings | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Readings | Fault Operations Ground | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Readings | Amps C Ø | 152.0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Readings | Amps B Ø | 141.0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Readings | Amps A Ø | 132.0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001613 | BreakerVacuum | 663-0651 | VCB Readings | 9 Month Operations | 1 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Patrol Inspection | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Readings | 9 Month Operations | 9 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Readings | Amps C Ø | 444.0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Readings | Fault Adjusted Amps A Phase V | 3.67 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Readings | Fault Operations A Ø | 2 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Readings | Fault Operations Ground | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Readings | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Readings | Amps B Ø | 413.0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Readings | Amps A Ø | 418.0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Readings | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Readings | Maintenance Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Readings | Operations Counter AF | 186 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Readings | Operations Counter AL | 186 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Readings | Operations This Read Vac | 2 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Readings | Switching Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001608 | BreakerVacuum | 663-0648 | VCB Readings | Unknown Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Patrol Inspection | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Readings | 9 Month Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Readings | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Readings | Operations Counter AF | 173 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Readings | Operations Counter AL | 173 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Readings | Switching Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Readings | Unknown Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Readings | Amps C Ø | 602.0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Readings | Amps B Ø | 587.0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Readings | Amps A Ø | 574.0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001617 | BreakerVacuum | 663-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001505 | BreakerSF6 | 663-618 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001505 | BreakerSF6 | 663-618 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001505 | BreakerSF6 | 663-618 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001505 | BreakerSF6 | 663-618 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001505 | BreakerSF6 | 663-618 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001505 | BreakerSF6 | 663-618 | GCB Patrol Inspection | Ambient Temperature | 50 | °F |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001505 | BreakerSF6 | 663-618 | GCB Patrol Inspection | SF6 Pressure Indicator | good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001505 | BreakerSF6 | 663-618 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001505 | BreakerSF6 | 663-618 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001505 | BreakerSF6 | 663-618 | GCB Patrol Inspection | Grounds in Place? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001505 | BreakerSF6 | 663-618 | GCB Patrol Inspection | General Comments | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001505 | BreakerSF6 | 663-618 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001505 | BreakerSF6 | 663-618 | GCB Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001505 | BreakerSF6 | 663-618 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001505 | BreakerSF6 | 663-618 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001505 | BreakerSF6 | 663-618 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001505 | BreakerSF6 | 663-618 | GCB Readings | Switching Operations | 1 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001505 | BreakerSF6 | 663-618 | GCB Readings | Unknown Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001505 | BreakerSF6 | 663-618 | GCB Readings | Operations This Read SF6 | 1 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001505 | BreakerSF6 | 663-618 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001505 | BreakerSF6 | 663-618 | GCB Readings | Fault Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001505 | BreakerSF6 | 663-618 | GCB Readings | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001505 | BreakerSF6 | 663-618 | GCB Readings | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001505 | BreakerSF6 | 663-618 | GCB Readings | Maintenance Operations | 0 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001505 | BreakerSF6 | 663-618 | GCB Readings | Num Operations Last 9 Months | 1 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001505 | BreakerSF6 | 663-618 | GCB Readings | Operations Counter AL | 185 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BK001505 | BreakerSF6 | 663-618 | GCB Readings | Operations Counter AF | 185 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1200 | psi |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Readings | LTC Totalizer Reading | 13944.00 | kw |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Readings | Totalizer Meter Reading | .5810 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Readings | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | TX000265 | WithLTC | 663-1 | LTC Transformer Readings | Winding Temp Present | 35 | °C |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCC000882 | LTCControl | 663-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCC000882 | LTCControl | 663-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCC000882 | LTCControl | 663-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCC000882 | LTCControl | 663-1 | LTC Control Insp | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCC000882 | LTCControl | 663-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCC000882 | LTCControl | 663-1 | LTC Control Insp | All Connections OK? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCC000882 | LTCControl | 663-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCC000882 | LTCControl | 663-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCM000112 | LTCMechanism | 663-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCM000112 | LTCMechanism | 663-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCM000112 | LTCMechanism | 663-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCM000112 | LTCMechanism | 663-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 30 | °C |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCM000112 | LTCMechanism | 663-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 40 | °C |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCM000112 | LTCMechanism | 663-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCM000112 | LTCMechanism | 663-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCM000112 | LTCMechanism | 663-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCM000112 | LTCMechanism | 663-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCM000112 | LTCMechanism | 663-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCM000112 | LTCMechanism | 663-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCM000112 | LTCMechanism | 663-1 | LTC Counter Readings | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCM000112 | LTCMechanism | 663-1 | LTC Counter Readings | LTC As Found Counter | 11045 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCM000112 | LTCMechanism | 663-1 | LTC Counter Readings | LTC As Left Counter | 11045 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCM000112 | LTCMechanism | 663-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCM000112 | LTCMechanism | 663-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCM000112 | LTCMechanism | 663-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCM000112 | LTCMechanism | 663-1 | LTC Counter Readings | LTC Operations Since Last Insp | 876 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCM000112 | LTCMechanism | 663-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCC000135 | LTCControl | 663-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCC000135 | LTCControl | 663-2 | LTC Control Insp | All Connections OK? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCC000135 | LTCControl | 663-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCC000135 | LTCControl | 663-2 | LTC Control Insp | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCC000135 | LTCControl | 663-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCC000135 | LTCControl | 663-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCC000135 | LTCControl | 663-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | LTCC000135 | LTCControl | 663-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | LTCMechanism | 663-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | LTCMechanism | 663-2 | LTC Counter Readings | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | LTCMechanism | 663-2 | LTC Counter Readings | LTC As Found Counter | 138595 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | LTCMechanism | 663-2 | LTC Counter Readings | LTC As Left Counter | 138595 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | LTCMechanism | 663-2 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | LTCMechanism | 663-2 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | LTCMechanism | 663-2 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | LTCMechanism | 663-2 | LTC Counter Readings | LTC Operations Since Last Insp | 525 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | LTCMechanism | 663-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | LTCMechanism | 663-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | LTCMechanism | 663-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | LTCMechanism | 663-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | LTCMechanism | 663-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | LTCMechanism | 663-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | LTCMechanism | 663-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 120.00 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Readings | Winding Temp Present | 35 | °C |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Readings | Totalizer Meter Reading | .3726 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Readings | Oil Temp Max | 35 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Readings | LTC Totalizer Reading | 3576.96 | kw |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Readings | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | C0518 | WithLTC | 663-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BAT001514 | Battery | 663-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BAT001514 | Battery | 663-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BAT001514 | Battery | 663-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BAT001514 | Battery | 663-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BAT001514 | Battery | 663-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BAT001514 | Battery | 663-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BAT001514 | Battery | 663-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BAT001514 | Battery | 663-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BAT001514 | Battery | 663-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BAT001514 | Battery | 663-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BAT001514 | Battery | 663-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BAT001514 | Battery | 663-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BAT001514 | Battery | 663-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BAT001514 | Battery | 663-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BAT001514 | Battery | 663-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BCH001438 | Charger | 663-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.0 | VDC |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BCH001438 | Charger | 663-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BCH001438 | Charger | 663-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BCH001438 | Charger | 663-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BCH001438 | Charger | 663-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BCH001438 | Charger | 663-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.6 | amps |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | BCH001438 | Charger | 663-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.0 | VDC |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | CH000501 | ControlHouse | 663-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | CH000501 | ControlHouse | 663-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | CH000501 | ControlHouse | 663-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | CH000501 | ControlHouse | 663-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | CH000501 | ControlHouse | 663-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | CH000501 | ControlHouse | 663-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | CH000501 | ControlHouse | 663-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | CH000501 | ControlHouse | 663-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | CH000501 | ControlHouse | 663-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | CH000501 | ControlHouse | 663-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | CH000501 | ControlHouse | 663-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | CH000501 | ControlHouse | 663-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | CH000501 | ControlHouse | 663-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | CH000501 | ControlHouse | 663-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | CH000501 | ControlHouse | 663-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | CH000501 | ControlHouse | 663-Control House | Control House Patrol Inspection | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | CH000501 | ControlHouse | 663-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | ST000313 | Structure | 663-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | ST000313 | Structure | 663-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | ST000313 | Structure | 663-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | ST000313 | Structure | 663-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | ST000313 | Structure | 663-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | ST000313 | Structure | 663-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | ST000313 | Structure | 663-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | ST000313 | Structure | 663-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | ST000313 | Structure | 663-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | ST000313 | Structure | 663-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | ST000313 | Structure | 663-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | ST000313 | Structure | 663-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | ST000313 | Structure | 663-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | ST000313 | Structure | 663-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | ST000313 | Structure | 663-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | ST000313 | Structure | 663-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | ST000313 | Structure | 663-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | ST000313 | Structure | 663-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | ST000313 | Structure | 663-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | ST000313 | Structure | 663-Structure | Structure Patrol Inspection | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | ST000313 | Structure | 663-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | ST000313 | Structure | 663-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | FE000873 | Fence | 663-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | FE000873 | Fence | 663-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | FE000873 | Fence | 663-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | FE000873 | Fence | 663-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | FE000873 | Fence | 663-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | FE000873 | Fence | 663-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | FE000873 | Fence | 663-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | FE000873 | Fence | 663-Fence | Fence Patrol Inspection | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | FE000873 | Fence | 663-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | FE000873 | Fence | 663-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | FE000873 | Fence | 663-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | FE000873 | Fence | 663-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | FE000873 | Fence | 663-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | FE000873 | Fence | 663-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | FE000873 | Fence | 663-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | FE000873 | Fence | 663-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | YD000305 | Yard | 663-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | YD000305 | Yard | 663-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | YD000305 | Yard | 663-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | YD000305 | Yard | 663-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | YD000305 | Yard | 663-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | YD000305 | Yard | 663-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | YD000305 | Yard | 663-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | YD000305 | Yard | 663-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | YD000305 | Yard | 663-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | YD000305 | Yard | 663-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | YD000305 | Yard | 663-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | YD000305 | Yard | 663-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | YD000305 | Yard | 663-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | YD000305 | Yard | 663-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | YD000305 | Yard | 663-Yard | Yard Patrol Inspection | General Comments | | |
| 3/17/2023 10:50 | Distribution | Corporate Drive Quarterly Inspection | YD000305 | Yard | 663-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Readings | Operations Counter AF | 178 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Readings | Operations Counter AL | 178 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Readings | General Comments | | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Readings | Amps C Ø | 120.0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Readings | Amps B Ø | 115.0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Readings | Amps A Ø | 105.0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Readings | 9 Month Operations | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK001410 | BreakerVacuum | 539-0969 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Readings | 9 Month Operations | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Readings | Operations Counter AL | 214 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Readings | Operations Counter AF | 214 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Readings | General Comments | | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Readings | Amps A Ø | 540.0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Readings | Amps B Ø | 545.0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Readings | Amps C Ø | 550.0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0018 | BreakerVacuum | 539-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Readings | General Comments | | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Readings | Operations Counter AF | 268 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Readings | Operations Counter AL | 268 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Readings | 9 Month Operations | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Readings | Amps C Ø | 8.0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Readings | Amps B Ø | 8.0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Readings | Amps A Ø | 10.0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0037 | BreakerVacuum | 539-0968 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Readings | Operations Counter AL | 314 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Readings | Operations Counter AF | 314 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Readings | General Comments | | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Readings | Amps C Ø | 445.0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Readings | Amps B Ø | 420.0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Readings | Amps A Ø | 420.0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Readings | 9 Month Operations | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KB0001 | BreakerVacuum | 539-0970 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Readings | 9 Month Operations | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Readings | Amps A Ø | 50.0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Readings | Amps B Ø | 55.0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Readings | Amps C Ø | 80.0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Readings | Operations Counter AL | 200 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Readings | Operations Counter AF | 200 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Readings | General Comments | | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BK000799 | BreakerVacuum | 539-0646 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Readings | 9 Month Operations | 4 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Readings | Amps A Ø | 270.0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Readings | Amps B Ø | 270.0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Readings | Amps C Ø | 290.0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Readings | Operations Counter AL | 229 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Readings | Operations Counter AF | 229 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Readings | General Comments | | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BB0458 | BreakerVacuum | 539-0647 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCC000347 | LTCControl | 539-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCC000347 | LTCControl | 539-2 | LTC Control Insp | All Connections OK? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCC000347 | LTCControl | 539-2 | LTC Control Insp | General Comments | | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCC000347 | LTCControl | 539-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCC000347 | LTCControl | 539-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCC000347 | LTCControl | 539-2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCC000347 | LTCControl | 539-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCC000347 | LTCControl | 539-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCC000347 | LTCControl | 539-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | LTCMechanism | 539-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | LTCMechanism | 539-2 | LTC Counter Readings | LTC Operations Since Last Insp | 1195 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | LTCMechanism | 539-2 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | LTCMechanism | 539-2 | LTC Counter Readings | LTC Max Tap Position | 10R | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | LTCMechanism | 539-2 | LTC Counter Readings | LTC Current Tap Position | 1R | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | LTCMechanism | 539-2 | LTC Counter Readings | LTC As Left Counter | 80000 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | LTCMechanism | 539-2 | LTC Counter Readings | LTC As Found Counter | 80000 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | LTCMechanism | 539-2 | LTC Counter Readings | General Comments | | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | LTCMechanism | 539-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | LTCMechanism | 539-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | LTCMechanism | 539-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | LTCMechanism | 539-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | LTCMechanism | 539-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | LTCMechanism | 539-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | LTCMechanism | 539-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Readings | General Comments | | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Readings | Winding Temp Max | 60 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Readings | Totalizer Meter Reading | .7070 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Readings | LTC Totalizer Reading | 12726.00 | kw |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1550 | psi |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | KT0026 | WithLTC | 539-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCM000056 | LTCMechanism | 539-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCM000056 | LTCMechanism | 539-1 | LTC Counter Readings | General Comments | | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCM000056 | LTCMechanism | 539-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCM000056 | LTCMechanism | 539-1 | LTC Counter Readings | LTC Operations Since Last Insp | 1049 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCM000056 | LTCMechanism | 539-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCM000056 | LTCMechanism | 539-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCM000056 | LTCMechanism | 539-1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCM000056 | LTCMechanism | 539-1 | LTC Counter Readings | LTC As Left Counter | 205728 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCM000056 | LTCMechanism | 539-1 | LTC Counter Readings | LTC As Found Counter | 205728 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCM000056 | LTCMechanism | 539-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCM000056 | LTCMechanism | 539-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCM000056 | LTCMechanism | 539-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCM000056 | LTCMechanism | 539-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 0 | °C |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCM000056 | LTCMechanism | 539-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 0 | °C |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCM000056 | LTCMechanism | 539-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCM000056 | LTCMechanism | 539-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCM000056 | LTCMechanism | 539-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCM000056 | LTCMechanism | 539-1 | LTC Mechanism Patrol Inspection | General Comments | NO LTC TEMP GAUGE | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCM000056 | LTCMechanism | 539-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCC000512 | LTCControl | 539-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCC000512 | LTCControl | 539-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCC000512 | LTCControl | 539-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCC000512 | LTCControl | 539-1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCC000512 | LTCControl | 539-1 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCC000512 | LTCControl | 539-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCC000512 | LTCControl | 539-1 | LTC Control Insp | General Comments | | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCC000512 | LTCControl | 539-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | LTCC000512 | LTCControl | 539-1 | LTC Control Insp | All Connections OK? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.2264 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Readings | General Comments | | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | B0460 | WithLTC | 539-1 | LTC Transformer Readings | LTC Totalizer Reading | 8830.08 | kw |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BAT001207 | Battery | 539-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BAT001207 | Battery | 539-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 45 | °F |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BAT001207 | Battery | 539-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BAT001207 | Battery | 539-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BAT001207 | Battery | 539-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BAT001207 | Battery | 539-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BAT001207 | Battery | 539-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BAT001207 | Battery | 539-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BAT001207 | Battery | 539-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BAT001207 | Battery | 539-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BAT001207 | Battery | 539-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BAT001207 | Battery | 539-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BAT001207 | Battery | 539-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BCH001355 | Charger | 539-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BCH001355 | Charger | 539-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BCH001355 | Charger | 539-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BCH001355 | Charger | 539-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.6 | amps |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BCH001355 | Charger | 539-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BCH001355 | Charger | 539-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BCH001355 | Charger | 539-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | BCH001355 | Charger | 539-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | ST000405 | Structure | 539-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | ST000405 | Structure | 539-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | ST000405 | Structure | 539-Structure | Structure Patrol Inspection | General Comments | | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | ST000405 | Structure | 539-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | ST000405 | Structure | 539-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | ST000405 | Structure | 539-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | ST000405 | Structure | 539-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | ST000405 | Structure | 539-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | ST000405 | Structure | 539-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | ST000405 | Structure | 539-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | ST000405 | Structure | 539-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | ST000405 | Structure | 539-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | ST000405 | Structure | 539-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | ST000405 | Structure | 539-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | ST000405 | Structure | 539-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | ST000405 | Structure | 539-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | ST000405 | Structure | 539-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | ST000405 | Structure | 539-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | ST000405 | Structure | 539-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | ST000405 | Structure | 539-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | ST000405 | Structure | 539-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | FE000398 | Fence | 539-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | FE000398 | Fence | 539-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | FE000398 | Fence | 539-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | FE000398 | Fence | 539-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | FE000398 | Fence | 539-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | FE000398 | Fence | 539-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | FE000398 | Fence | 539-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | FE000398 | Fence | 539-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | FE000398 | Fence | 539-Fence | Fence Patrol Inspection | General Comments | | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | FE000398 | Fence | 539-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | FE000398 | Fence | 539-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | FE000398 | Fence | 539-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | FE000398 | Fence | 539-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | FE000398 | Fence | 539-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | FE000398 | Fence | 539-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | FE000398 | Fence | 539-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | YD000403 | Yard | 539-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | YD000403 | Yard | 539-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | YD000403 | Yard | 539-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | YD000403 | Yard | 539-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | YD000403 | Yard | 539-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | YD000403 | Yard | 539-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | YD000403 | Yard | 539-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | YD000403 | Yard | 539-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | YD000403 | Yard | 539-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | YD000403 | Yard | 539-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | YD000403 | Yard | 539-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | YD000403 | Yard | 539-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | YD000403 | Yard | 539-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | YD000403 | Yard | 539-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | YD000403 | Yard | 539-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/16/2023 15:15 | Distribution | Ewington Quarterly Inspection | YD000403 | Yard | 539-Yard | Yard Patrol Inspection | General Comments | | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Readings | Amps C Ø | 30.0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Readings | Amps B Ø | 25.0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Readings | Amps A Ø | 30.0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Readings | 9 Month Operations | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Readings | General Comments | | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Readings | Operations Counter AF | 273 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Readings | Operations Counter AL | 273 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0092 | BreakerVacuum | 456-0609 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Readings | General Comments | | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Readings | Operations Counter AF | 199 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Readings | Operations Counter AL | 199 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Readings | Amps A Ø | 140.0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Readings | Amps C Ø | 155.0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Readings | 9 Month Operations | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Readings | Amps B Ø | 150.0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001570 | BreakerVacuum | 456-0608 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Readings | 9 Month Operations | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Readings | Amps A Ø | 135.0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Readings | Amps B Ø | 135.0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Readings | Amps C Ø | 145.0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Readings | Operations Counter AL | 171 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Readings | Operations Counter AF | 171 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Readings | General Comments | | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001569 | BreakerVacuum | 456-0607 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Readings | Amps C Ø | 1.0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Readings | Amps B Ø | 1.0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Readings | Amps A Ø | 1.0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Readings | General Comments | | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Readings | Operations Counter AF | 184 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Readings | Operations Counter AL | 184 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Readings | 9 Month Operations | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Readings | Switching Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BK001568 | BreakerVacuum | 456-0606 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Readings | 9 Month Operations | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Readings | Operations Counter AL | 169 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Readings | Operations Counter AF | 169 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Readings | General Comments | | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Readings | Amps A Ø | 290.0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Readings | Amps B Ø | 290.0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Readings | Amps C Ø | 305.0 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | KB0108 | BreakerVacuum | 456-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | LTCC000612 | LTCControl | 456-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | LTCC000612 | LTCControl | 456-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | LTCC000612 | LTCControl | 456-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | LTCC000612 | LTCControl | 456-1 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | LTCC000612 | LTCControl | 456-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | LTCC000612 | LTCControl | 456-1 | LTC Control Insp | General Comments | | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | LTCC000612 | LTCControl | 456-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | LTCC000612 | LTCControl | 456-1 | LTC Control Insp | All Connections OK? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | LTCM000017 | LTCMechanism | 456-1 | LTC Counter Readings | General Comments | | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | LTCM000017 | LTCMechanism | 456-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | LTCM000017 | LTCMechanism | 456-1 | LTC Counter Readings | LTC As Found Counter | 40255 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | LTCM000017 | LTCMechanism | 456-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | LTCM000017 | LTCMechanism | 456-1 | LTC Counter Readings | LTC Operations Since Last Insp | 806 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | LTCM000017 | LTCMechanism | 456-1 | LTC Counter Readings | LTC Min Tap Position | 16L | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | LTCM000017 | LTCMechanism | 456-1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | LTCM000017 | LTCMechanism | 456-1 | LTC Counter Readings | LTC Current Tap Position | 10L | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | LTCM000017 | LTCMechanism | 456-1 | LTC Counter Readings | LTC As Left Counter | 40255 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | LTCM000017 | LTCMechanism | 456-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | LTCM000017 | LTCMechanism | 456-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | LTCM000017 | LTCMechanism | 456-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | LTCM000017 | LTCMechanism | 456-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 20 | °C |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | LTCM000017 | LTCMechanism | 456-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 30 | °C |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | LTCM000017 | LTCMechanism | 456-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | LTCM000017 | LTCMechanism | 456-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | LTCM000017 | LTCMechanism | 456-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Readings | Totalizer Meter Reading | .5640 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Readings | Winding Temp Max | 50 | °C |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Readings | LTC Totalizer Reading | 10152.00 | kw |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Readings | General Comments | | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 700 | psi |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.5 | psi |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | TX000022 | WithLTC | 456-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | CS000004 | CircuitSwitcher | 456-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Ambient Temperature | 50 | °F |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | CS000004 | CircuitSwitcher | 456-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | CS000004 | CircuitSwitcher | 456-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | CS000004 | CircuitSwitcher | 456-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | CS000004 | CircuitSwitcher | 456-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | CS000004 | CircuitSwitcher | 456-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | CS000004 | CircuitSwitcher | 456-1 Trans-Rupter | Circuit Switcher Patrol Inspection | General Comments | | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | CS000004 | CircuitSwitcher | 456-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | CS000004 | CircuitSwitcher | 456-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | CS000004 | CircuitSwitcher | 456-1 Trans-Rupter | Circuit Switcher Patrol Inspection | SF6 Bushing Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | CS000004 | CircuitSwitcher | 456-1 Trans-Rupter | Circuit Switcher Patrol Inspection | SF6 Indicator Zone | OK | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BCH001368 | Charger | 456-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BCH001368 | Charger | 456-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BCH001368 | Charger | 456-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BCH001368 | Charger | 456-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BCH001368 | Charger | 456-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.3 | amps |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BCH001368 | Charger | 456-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BCH001368 | Charger | 456-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BCH001368 | Charger | 456-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BAT001449 | Battery | 456-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BAT001449 | Battery | 456-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BAT001449 | Battery | 456-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BAT001449 | Battery | 456-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BAT001449 | Battery | 456-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BAT001449 | Battery | 456-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BAT001449 | Battery | 456-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BAT001449 | Battery | 456-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BAT001449 | Battery | 456-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BAT001449 | Battery | 456-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BAT001449 | Battery | 456-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BAT001449 | Battery | 456-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BAT001449 | Battery | 456-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | BAT001449 | Battery | 456-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | ST000315 | Structure | 456-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | ST000315 | Structure | 456-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | ST000315 | Structure | 456-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | ST000315 | Structure | 456-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | ST000315 | Structure | 456-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | ST000315 | Structure | 456-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | ST000315 | Structure | 456-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | ST000315 | Structure | 456-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | ST000315 | Structure | 456-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | ST000315 | Structure | 456-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | ST000315 | Structure | 456-Structure | Structure Patrol Inspection | General Comments | | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | ST000315 | Structure | 456-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | ST000315 | Structure | 456-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | ST000315 | Structure | 456-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | ST000315 | Structure | 456-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | ST000315 | Structure | 456-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | ST000315 | Structure | 456-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | ST000315 | Structure | 456-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | ST000315 | Structure | 456-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | ST000315 | Structure | 456-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | ST000315 | Structure | 456-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | ST000315 | Structure | 456-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | ST000315 | Structure | 456-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | ST000315 | Structure | 456-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | FE000304 | Fence | 456-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | FE000304 | Fence | 456-Fence | Fence Patrol Inspection | General Comments | | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | FE000304 | Fence | 456-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | FE000304 | Fence | 456-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | FE000304 | Fence | 456-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | FE000304 | Fence | 456-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | FE000304 | Fence | 456-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | FE000304 | Fence | 456-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | FE000304 | Fence | 456-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | FE000304 | Fence | 456-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | FE000304 | Fence | 456-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | FE000304 | Fence | 456-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | FE000304 | Fence | 456-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | FE000304 | Fence | 456-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | FE000304 | Fence | 456-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | FE000304 | Fence | 456-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | YD000308 | Yard | 456-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | YD000308 | Yard | 456-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | YD000308 | Yard | 456-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | YD000308 | Yard | 456-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | YD000308 | Yard | 456-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | YD000308 | Yard | 456-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | YD000308 | Yard | 456-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | YD000308 | Yard | 456-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | YD000308 | Yard | 456-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | YD000308 | Yard | 456-Yard | Yard Patrol Inspection | General Comments | | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | YD000308 | Yard | 456-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | YD000308 | Yard | 456-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | YD000308 | Yard | 456-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | YD000308 | Yard | 456-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/16/2023 15:01 | Distribution | A O Smith Quarterly Inspection | YD000308 | Yard | 456-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | LTCMechanism | 886-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | LTCMechanism | 886-1 | LTC Counter Readings | LTC Operations Since Last Insp | 461 | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | LTCMechanism | 886-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | LTCMechanism | 886-1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | LTCMechanism | 886-1 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | LTCMechanism | 886-1 | LTC Counter Readings | LTC As Left Counter | 6188 | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | LTCMechanism | 886-1 | LTC Counter Readings | LTC As Found Counter | 6185 | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | LTCMechanism | 886-1 | LTC Counter Readings | General Comments | | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | LTCMechanism | 886-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | LTCMechanism | 886-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | LTCMechanism | 886-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | LTCMechanism | 886-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | LTCMechanism | 886-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | LTCMechanism | 886-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | LTCMechanism | 886-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | LTCC000864 | LTCControl | 886-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | LTCC000864 | LTCControl | 886-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | LTCC000864 | LTCControl | 886-1 | LTC Control Insp | All Connections OK? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | LTCC000864 | LTCControl | 886-1 | LTC Control Insp | LTC Output Voltage Level | 120.2 | VAC |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | LTCC000864 | LTCControl | 886-1 | LTC Control Insp | VRR Base Voltage AF | 120 | VAC |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | LTCC000864 | LTCControl | 886-1 | LTC Control Insp | VRR Base Voltage AL | 120 | VAC |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | LTCC000864 | LTCControl | 886-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | LTCC000864 | LTCControl | 886-1 | LTC Control Insp | General Comments | | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Readings | General Comments | | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Readings | LTC Totalizer Reading | 180 | kw |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4000 | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Readings | Totalizer Meter Reading | .045 | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 55 | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | C0407 | WithLTC | 886-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | ST000516 | Structure | 886-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | ST000516 | Structure | 886-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | ST000516 | Structure | 886-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | ST000516 | Structure | 886-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | ST000516 | Structure | 886-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | ST000516 | Structure | 886-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | ST000516 | Structure | 886-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | ST000516 | Structure | 886-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | ST000516 | Structure | 886-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | ST000516 | Structure | 886-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | ST000516 | Structure | 886-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | ST000516 | Structure | 886-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | ST000516 | Structure | 886-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | ST000516 | Structure | 886-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | ST000516 | Structure | 886-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | ST000516 | Structure | 886-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | ST000516 | Structure | 886-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | ST000516 | Structure | 886-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | ST000516 | Structure | 886-Structure | Structure Patrol Inspection | General Comments | | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | ST000516 | Structure | 886-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | ST000516 | Structure | 886-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | ST000516 | Structure | 886-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | FE000548 | Fence | 886-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | FE000548 | Fence | 886-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | FE000548 | Fence | 886-Fence | Fence Patrol Inspection | General Comments | | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | FE000548 | Fence | 886-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | FE000548 | Fence | 886-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | FE000548 | Fence | 886-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | FE000548 | Fence | 886-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | FE000548 | Fence | 886-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | FE000548 | Fence | 886-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | FE000548 | Fence | 886-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | FE000548 | Fence | 886-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | FE000548 | Fence | 886-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | FE000548 | Fence | 886-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | FE000548 | Fence | 886-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | FE000548 | Fence | 886-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | FE000548 | Fence | 886-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | YD000524 | Yard | 886-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | YD000524 | Yard | 886-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | YD000524 | Yard | 886-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | YD000524 | Yard | 886-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | YD000524 | Yard | 886-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | YD000524 | Yard | 886-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | YD000524 | Yard | 886-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | YD000524 | Yard | 886-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | YD000524 | Yard | 886-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | YD000524 | Yard | 886-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | YD000524 | Yard | 886-Yard | Yard Patrol Inspection | General Comments | | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | YD000524 | Yard | 886-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | YD000524 | Yard | 886-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/16/2023 13:47 | Distribution | Gates Rubber Quarterly Inspection | YD000524 | Yard | 886-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | FE000648 | Fence | NA-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | FE000648 | Fence | NA-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | FE000648 | Fence | NA-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | FE000648 | Fence | NA-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | FE000648 | Fence | NA-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | FE000648 | Fence | NA-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | FE000648 | Fence | NA-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | FE000648 | Fence | NA-Fence | Fence Patrol Inspection | General Comments | There are trees within 5' of the fence | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | FE000648 | Fence | NA-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | FE000648 | Fence | NA-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | FE000648 | Fence | NA-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | FE000648 | Fence | NA-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | FE000648 | Fence | NA-Fence | Fence Patrol Inspection | Follow-up Action Required? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | FE000648 | Fence | NA-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | FE000648 | Fence | NA-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | FE000648 | Fence | NA-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0694 | BreakerVacuum | NA-12KV BUS TIE SEC 3 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0694 | BreakerVacuum | NA-12KV BUS TIE SEC 3 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0694 | BreakerVacuum | NA-12KV BUS TIE SEC 3 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0694 | BreakerVacuum | NA-12KV BUS TIE SEC 3 | VCB Readings | 9 Month Operations | 10 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0694 | BreakerVacuum | NA-12KV BUS TIE SEC 3 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0694 | BreakerVacuum | NA-12KV BUS TIE SEC 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0694 | BreakerVacuum | NA-12KV BUS TIE SEC 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0694 | BreakerVacuum | NA-12KV BUS TIE SEC 3 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0694 | BreakerVacuum | NA-12KV BUS TIE SEC 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0694 | BreakerVacuum | NA-12KV BUS TIE SEC 3 | VCB Readings | Amps A Ø | 0.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0694 | BreakerVacuum | NA-12KV BUS TIE SEC 3 | VCB Readings | Amps B Ø | 0.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0694 | BreakerVacuum | NA-12KV BUS TIE SEC 3 | VCB Readings | Amps C Ø | 0.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0694 | BreakerVacuum | NA-12KV BUS TIE SEC 3 | VCB Readings | Operations Counter AL | 261 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0694 | BreakerVacuum | NA-12KV BUS TIE SEC 3 | VCB Readings | Operations Counter AF | 261 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0694 | BreakerVacuum | NA-12KV BUS TIE SEC 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0694 | BreakerVacuum | NA-12KV BUS TIE SEC 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0694 | BreakerVacuum | NA-12KV BUS TIE SEC 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0694 | BreakerVacuum | NA-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0694 | BreakerVacuum | NA-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0694 | BreakerVacuum | NA-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0694 | BreakerVacuum | NA-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0694 | BreakerVacuum | NA-12KV BUS TIE SEC 3 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0694 | BreakerVacuum | NA-12KV BUS TIE SEC 3 | VCB Readings | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0691 | BreakerVacuum | NA-1274 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0691 | BreakerVacuum | NA-1274 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0691 | BreakerVacuum | NA-1274 | VCB Readings | Operations Counter AL | 187 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0691 | BreakerVacuum | NA-1274 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0691 | BreakerVacuum | NA-1274 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0691 | BreakerVacuum | NA-1274 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0691 | BreakerVacuum | NA-1274 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0691 | BreakerVacuum | NA-1274 | VCB Readings | Amps C Ø | 1.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0691 | BreakerVacuum | NA-1274 | VCB Readings | Amps B Ø | 0.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0691 | BreakerVacuum | NA-1274 | VCB Readings | Amps A Ø | 0.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0691 | BreakerVacuum | NA-1274 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0691 | BreakerVacuum | NA-1274 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0691 | BreakerVacuum | NA-1274 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0691 | BreakerVacuum | NA-1274 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0691 | BreakerVacuum | NA-1274 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0691 | BreakerVacuum | NA-1274 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0691 | BreakerVacuum | NA-1274 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0691 | BreakerVacuum | NA-1274 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0691 | BreakerVacuum | NA-1274 | VCB Readings | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0691 | BreakerVacuum | NA-1274 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0691 | BreakerVacuum | NA-1274 | VCB Readings | Operations Counter AF | 187 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0691 | BreakerVacuum | NA-1274 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0691 | BreakerVacuum | NA-1274 | VCB Readings | 9 Month Operations | 1 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0690 | BreakerVacuum | NA-1273 | VCB Readings | 9 Month Operations | 1 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0690 | BreakerVacuum | NA-1273 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0690 | BreakerVacuum | NA-1273 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0690 | BreakerVacuum | NA-1273 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0690 | BreakerVacuum | NA-1273 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0690 | BreakerVacuum | NA-1273 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0690 | BreakerVacuum | NA-1273 | VCB Readings | Amps A Ø | 0.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0690 | BreakerVacuum | NA-1273 | VCB Readings | Switching Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0690 | BreakerVacuum | NA-1273 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0690 | BreakerVacuum | NA-1273 | VCB Readings | Operations Counter AL | 201 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0690 | BreakerVacuum | NA-1273 | VCB Readings | Operations Counter AF | 201 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0690 | BreakerVacuum | NA-1273 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0690 | BreakerVacuum | NA-1273 | VCB Readings | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0690 | BreakerVacuum | NA-1273 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0690 | BreakerVacuum | NA-1273 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0690 | BreakerVacuum | NA-1273 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0690 | BreakerVacuum | NA-1273 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0690 | BreakerVacuum | NA-1273 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0690 | BreakerVacuum | NA-1273 | VCB Readings | Amps B Ø | 13.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0690 | BreakerVacuum | NA-1273 | VCB Readings | Amps C Ø | 0.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0690 | BreakerVacuum | NA-1273 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0690 | BreakerVacuum | NA-1273 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0690 | BreakerVacuum | NA-1273 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0689 | BreakerVacuum | NA-1272 | VCB Readings | 9 Month Operations | 7 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0689 | BreakerVacuum | NA-1272 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0689 | BreakerVacuum | NA-1272 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0689 | BreakerVacuum | NA-1272 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0689 | BreakerVacuum | NA-1272 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0689 | BreakerVacuum | NA-1272 | VCB Readings | Amps A Ø | 92.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0689 | BreakerVacuum | NA-1272 | VCB Readings | Amps B Ø | 90.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0689 | BreakerVacuum | NA-1272 | VCB Readings | Amps C Ø | 107.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0689 | BreakerVacuum | NA-1272 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0689 | BreakerVacuum | NA-1272 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0689 | BreakerVacuum | NA-1272 | VCB Readings | Fault Adjusted Amps C Phase V | 67.08 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0689 | BreakerVacuum | NA-1272 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0689 | BreakerVacuum | NA-1272 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0689 | BreakerVacuum | NA-1272 | VCB Readings | Fault Operations C Ø | 6 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0689 | BreakerVacuum | NA-1272 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0689 | BreakerVacuum | NA-1272 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0689 | BreakerVacuum | NA-1272 | VCB Readings | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0689 | BreakerVacuum | NA-1272 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0689 | BreakerVacuum | NA-1272 | VCB Readings | Operations Counter AF | 343 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0689 | BreakerVacuum | NA-1272 | VCB Readings | Operations Counter AL | 343 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0689 | BreakerVacuum | NA-1272 | VCB Readings | Operations This Read Vac | 6 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0689 | BreakerVacuum | NA-1272 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0689 | BreakerVacuum | NA-1272 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0688 | BreakerVacuum | NA-1271 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0688 | BreakerVacuum | NA-1271 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0688 | BreakerVacuum | NA-1271 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0688 | BreakerVacuum | NA-1271 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0688 | BreakerVacuum | NA-1271 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0688 | BreakerVacuum | NA-1271 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0688 | BreakerVacuum | NA-1271 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0688 | BreakerVacuum | NA-1271 | VCB Readings | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0688 | BreakerVacuum | NA-1271 | VCB Readings | 9 Month Operations | 1 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0688 | BreakerVacuum | NA-1271 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0688 | BreakerVacuum | NA-1271 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0688 | BreakerVacuum | NA-1271 | VCB Readings | Operations Counter AF | 290 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0688 | BreakerVacuum | NA-1271 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0688 | BreakerVacuum | NA-1271 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0688 | BreakerVacuum | NA-1271 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0688 | BreakerVacuum | NA-1271 | VCB Readings | Amps A Ø | 101.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0688 | BreakerVacuum | NA-1271 | VCB Readings | Amps B Ø | 119.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0688 | BreakerVacuum | NA-1271 | VCB Readings | Amps C Ø | 101.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0688 | BreakerVacuum | NA-1271 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0688 | BreakerVacuum | NA-1271 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0688 | BreakerVacuum | NA-1271 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0688 | BreakerVacuum | NA-1271 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0688 | BreakerVacuum | NA-1271 | VCB Readings | Operations Counter AL | 290 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0697 | BreakerVacuum | NA-12KV TR 3 | VCB Readings | Operations Counter AF | 197 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0697 | BreakerVacuum | NA-12KV TR 3 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0697 | BreakerVacuum | NA-12KV TR 3 | VCB Readings | Operations Counter AL | 197 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0697 | BreakerVacuum | NA-12KV TR 3 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0697 | BreakerVacuum | NA-12KV TR 3 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0697 | BreakerVacuum | NA-12KV TR 3 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0697 | BreakerVacuum | NA-12KV TR 3 | VCB Readings | 9 Month Operations | 1 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0697 | BreakerVacuum | NA-12KV TR 3 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0697 | BreakerVacuum | NA-12KV TR 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0697 | BreakerVacuum | NA-12KV TR 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0697 | BreakerVacuum | NA-12KV TR 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0697 | BreakerVacuum | NA-12KV TR 3 | VCB Readings | Amps A Ø | 193.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0697 | BreakerVacuum | NA-12KV TR 3 | VCB Readings | Amps B Ø | 220.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0697 | BreakerVacuum | NA-12KV TR 3 | VCB Readings | Amps C Ø | 205.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0697 | BreakerVacuum | NA-12KV TR 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0697 | BreakerVacuum | NA-12KV TR 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0697 | BreakerVacuum | NA-12KV TR 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0697 | BreakerVacuum | NA-12KV TR 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0697 | BreakerVacuum | NA-12KV TR 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0697 | BreakerVacuum | NA-12KV TR 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0697 | BreakerVacuum | NA-12KV TR 3 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0697 | BreakerVacuum | NA-12KV TR 3 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0697 | BreakerVacuum | NA-12KV TR 3 | VCB Readings | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000087 | Switchgear | NA-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000087 | Switchgear | NA-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000087 | Switchgear | NA-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000087 | Switchgear | NA-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000087 | Switchgear | NA-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000087 | Switchgear | NA-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000087 | Switchgear | NA-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000087 | Switchgear | NA-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000087 | Switchgear | NA-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000087 | Switchgear | NA-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000087 | Switchgear | NA-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000087 | Switchgear | NA-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000087 | Switchgear | NA-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000087 | Switchgear | NA-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000087 | Switchgear | NA-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000087 | Switchgear | NA-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000087 | Switchgear | NA-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000087 | Switchgear | NA-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000087 | Switchgear | NA-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | LTCMechanism | NA-TRANS 3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | LTCMechanism | NA-TRANS 3 | LTC Counter Readings | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | LTCMechanism | NA-TRANS 3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | LTCMechanism | NA-TRANS 3 | LTC Counter Readings | LTC Operations Since Last Insp | 279 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | LTCMechanism | NA-TRANS 3 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | LTCMechanism | NA-TRANS 3 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | LTCMechanism | NA-TRANS 3 | LTC Counter Readings | LTC As Found Counter | 65001 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | LTCMechanism | NA-TRANS 3 | LTC Counter Readings | LTC As Left Counter | 65001 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | LTCMechanism | NA-TRANS 3 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Leaks | Seeping | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 800 | psi |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Patrol Inspection | General Comments | Multiple leaks at RADS | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | LTCMechanism | NA-TRANS 3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | LTCMechanism | NA-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | LTCMechanism | NA-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | LTCMechanism | NA-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 31 | °C |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | LTCMechanism | NA-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | LTCMechanism | NA-TRANS 3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | LTCMechanism | NA-TRANS 3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Max | 37 | °C |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Present | 24 | °C |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Present | 24 | °C |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Max | 37 | °C |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Present | 24 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Max | 37 | °C |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Readings | Oil Temp Present | 24 | °C |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Readings | Oil Temp Max | 37 | °C |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Readings | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0136 | WithLTC | NA-TRANS 3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | oil leaks at RADS | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.9 | psi |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 700 | psi |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | Seeping | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | LTCMechanism | NA-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | LTCMechanism | NA-TRANS 2 | LTC Counter Readings | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | LTCMechanism | NA-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 81377 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | LTCMechanism | NA-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 81377 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | LTCMechanism | NA-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | LTCMechanism | NA-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 6L | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | LTCMechanism | NA-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | LTCMechanism | NA-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 232 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | LTCMechanism | NA-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 45 | °C |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 32 | °C |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 40 | °C |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 45 | °C |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 30 | °C |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 50 | °C |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | WithLTC | NA-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 40 | °C |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LTCM000042 | LTCMechanism | NA-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LTCM000042 | LTCMechanism | NA-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 436 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LTCM000042 | LTCMechanism | NA-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LTCM000042 | LTCMechanism | NA-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LTCM000042 | LTCMechanism | NA-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LTCM000042 | LTCMechanism | NA-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 28131 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LTCM000042 | LTCMechanism | NA-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 28131 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LTCM000042 | LTCMechanism | NA-TRANS 1 | LTC Counter Readings | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LTCM000042 | LTCMechanism | NA-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 48 | °C |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 36 | °C |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 55 | °C |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 40 | °C |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 60 | °C |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 49 | °C |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 46 | °C |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 34 | °C |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0137 | WithLTC | NA-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BCH001598 | Charger | NA-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BCH001598 | Charger | NA-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 134.7 | VDC |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BCH001598 | Charger | NA-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 134.7 | VDC |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BCH001598 | Charger | NA-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 5.1 | amps |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BCH001598 | Charger | NA-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BCH001598 | Charger | NA-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BCH001598 | Charger | NA-Battery Charger | Battery Charger Patrol Insp | General Comments | one minute after trip 126.2 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BCH001598 | Charger | NA-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Readings | 9 Month Operations | 16 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Readings | 9 Month Operations VCB New | 15 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Readings | Amps A Ø | 0.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Readings | Amps B Ø | 0.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Readings | Amps C Ø | 0.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Readings | General Comments | out for testing | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Readings | Operations Counter AF | 45 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Readings | Operations Counter AL | 45 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Readings | Operations This Read Vac | 1 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Readings | Switching Operations | 1 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Readings | Operations Counter AL | 29 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Readings | Operations Counter AF | 29 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Readings | 9 Month Operations | 14 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Readings | 9 Month Operations VCB New | 14 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Readings | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Readings | Amps C Ø | 72.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Readings | Amps B Ø | 98.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Readings | Amps A Ø | 72.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Readings | Switching Operations | 1 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Readings | Operations This Read Vac | 1 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Readings | Operations Counter AL | 18 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Readings | 9 Month Operations | 41 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Readings | 9 Month Operations VCB New | 40 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Readings | Operations Counter AF | 18 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Readings | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Readings | Amps C Ø | 209.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Readings | Amps B Ø | 225.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Readings | Amps A Ø | 163.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Readings | Operations Counter AL | 135 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Readings | Operations Counter AF | 135 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Readings | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Readings | Amps C Ø | 227.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Readings | Amps B Ø | 223.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Readings | Amps A Ø | 233.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Readings | 9 Month Operations | 11 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 11 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Readings | Operations Counter AL | 11 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Readings | Operations Counter AF | 11 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Readings | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Readings | Amps C Ø | 85.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Readings | Amps B Ø | 93.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Readings | Amps A Ø | 61.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Readings | 9 Month Operations VCB New | 11 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Readings | 9 Month Operations | 11 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Readings | 9 Month Operations | 22 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Readings | 9 Month Operations VCB New | 20 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Readings | Fault Operations C Ø | 2 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Readings | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Readings | Operations Counter AF | 22 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Readings | Operations Counter AL | 22 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Readings | Operations This Read Vac | 2 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Readings | Amps A Ø | 77.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Readings | Amps B Ø | 79.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Readings | Amps C Ø | 96.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Readings | Fault Adjusted Amps C Phase V | 22.36 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Readings | 9 Month Operations | 39 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Readings | 9 Month Operations VCB New | 39 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Readings | Operations Counter AL | 99973 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Readings | Operations Counter AF | 99973 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Readings | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Readings | Amps A Ø | 195.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Readings | Amps B Ø | 198.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Readings | Amps C Ø | 165.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Readings | 9 Month Operations | 16 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Readings | 9 Month Operations VCB New | 16 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Readings | Amps A Ø | 0.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Readings | Amps B Ø | 0.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Readings | Amps C Ø | 0.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Readings | General Comments | DNO | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Readings | Operations Counter AF | 16 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Readings | Operations Counter AL | 16 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Readings | Operations This Read Vac | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AL | 13 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AF | 13 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Readings | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations | 13 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations VCB New | 13 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Readings | Amps A Ø | 0.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Readings | Amps B Ø | 0.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Readings | Amps C Ø | 0.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Readings | Amps C Ø | 349.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Readings | Amps B Ø | 368.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Readings | Amps A Ø | 328.0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Readings | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Readings | Operations Counter AF | 39 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Readings | 9 Month Operations | 39 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Readings | 9 Month Operations VCB New | 39 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Readings | Operations Counter AL | 39 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Readings | Switching Operations | 1 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Readings | 9 Month Operations | 2 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Readings | Accumulated Fault Duty A Ph V | .66 | % |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Readings | Accumulated Fault Duty B Ph V | .33 | % |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Readings | Accumulated Fault Duty C Ph V | .33 | % |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Readings | Amps A Ø | 60 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Readings | Amps B Ø | 47 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Readings | Amps C Ø | 45 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Readings | Operations This Read Vac | 1 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Readings | Operations Counter AL | 170 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Readings | Operations Counter AF | 169 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Readings | General Comments | | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001111 | BreakerVacuum | 527-2421 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Readings | Switching Operations | 1 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Readings | Operations This Read Vac | 1 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Readings | Operations Counter AL | 152 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Readings | Operations Counter AF | 151 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Readings | General Comments | | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Readings | Amps C Ø | 30 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Readings | Amps B Ø | 35 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Readings | Amps A Ø | 35 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001112 | BreakerVacuum | 527-2424 | VCB Readings | 9 Month Operations | 2 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Readings | Switching Operations | 4 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Readings | Operations This Read Vac | 4 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Readings | Operations Counter AL | 201 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Readings | Operations Counter AF | 197 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Readings | General Comments | | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Readings | Amps C Ø | 33 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Readings | Amps B Ø | 22 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Readings | Amps A Ø | 25 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Readings | Accumulated Fault Duty C Ph V | .99 | % |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Readings | Accumulated Fault Duty A Ph V | .99 | % |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Readings | 9 Month Operations VCB New | 1 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001113 | BreakerVacuum | 527-2423 | VCB Readings | 9 Month Operations | 5 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Readings | Switching Operations | 1 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Readings | Operations This Read Vac | 1 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Readings | Operations Counter AL | 172 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Readings | Operations Counter AF | 171 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Readings | General Comments | | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Readings | 9 Month Operations | 1 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Readings | Accumulated Fault Duty A Ph V | .66 | % |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Readings | Accumulated Fault Duty B Ph V | .33 | % |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Readings | Accumulated Fault Duty C Ph V | .33 | % |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Readings | Amps A Ø | 60 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Readings | Amps B Ø | 47 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Readings | Amps C Ø | 45 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BK001114 | BreakerVacuum | 527-2422 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | LTCMechanism | 527-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | LTCMechanism | 527-1 | LTC Counter Readings | LTC Operations Since Last Insp | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | LTCMechanism | 527-1 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | LTCMechanism | 527-1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | LTCMechanism | 527-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | LTCMechanism | 527-1 | LTC Counter Readings | General Comments | | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | LTCMechanism | 527-1 | LTC Counter Readings | LTC As Found Counter | 205574 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | LTCMechanism | 527-1 | LTC Counter Readings | LTC As Left Counter | 205574 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | LTCMechanism | 527-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | LTCC000620 | LTCControl | 527-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | LTCC000620 | LTCControl | 527-1 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | LTCC000620 | LTCControl | 527-1 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | LTCC000620 | LTCControl | 527-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | LTCC000620 | LTCControl | 527-1 | LTC Control Insp | LTC Output Voltage Level | 123.4 | VAC |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | LTCC000620 | LTCControl | 527-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | LTCC000620 | LTCControl | 527-1 | LTC Control Insp | General Comments | | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | LTCC000620 | LTCControl | 527-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | LTCC000620 | LTCControl | 527-1 | LTC Control Insp | All Connections OK? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | LTCMechanism | 527-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | LTCMechanism | 527-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | LTCMechanism | 527-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | LTCMechanism | 527-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | LTCMechanism | 527-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Readings | General Comments | | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Readings | LTC Totalizer Reading | 5293.44 | kw |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Readings | Totalizer Meter Reading | .5514 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | B0272 | WithLTC | 527-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BAT001111 | Battery | 527-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BAT001111 | Battery | 527-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 48 | °F |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BAT001111 | Battery | 527-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BAT001111 | Battery | 527-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BAT001111 | Battery | 527-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BAT001111 | Battery | 527-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BAT001111 | Battery | 527-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BAT001111 | Battery | 527-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BAT001111 | Battery | 527-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BAT001111 | Battery | 527-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BAT001111 | Battery | 527-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27 | VDC |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BAT001111 | Battery | 527-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.1 | VDC |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BAT001111 | Battery | 527-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BAT001111 | Battery | 527-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BCH001255 | Charger | 527-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0 | millivolts |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BCH001255 | Charger | 527-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BCH001255 | Charger | 527-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BCH001255 | Charger | 527-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.5 | amps |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BCH001255 | Charger | 527-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BCH001255 | Charger | 527-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BCH001255 | Charger | 527-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | BCH001255 | Charger | 527-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | ST000530 | Structure | 527-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | ST000530 | Structure | 527-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | ST000530 | Structure | 527-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | ST000530 | Structure | 527-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | ST000530 | Structure | 527-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | ST000530 | Structure | 527-Structure | Structure Patrol Inspection | General Comments | | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | ST000530 | Structure | 527-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | ST000530 | Structure | 527-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | ST000530 | Structure | 527-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | ST000530 | Structure | 527-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | ST000530 | Structure | 527-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | ST000530 | Structure | 527-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | ST000530 | Structure | 527-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | ST000530 | Structure | 527-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | ST000530 | Structure | 527-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | ST000530 | Structure | 527-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | ST000530 | Structure | 527-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | ST000530 | Structure | 527-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | ST000530 | Structure | 527-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | ST000530 | Structure | 527-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | ST000530 | Structure | 527-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | ST000530 | Structure | 527-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | FE000520 | Fence | 527-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | FE000520 | Fence | 527-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | FE000520 | Fence | 527-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | FE000520 | Fence | 527-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | FE000520 | Fence | 527-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | FE000520 | Fence | 527-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | FE000520 | Fence | 527-Fence | Fence Patrol Inspection | General Comments | | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | FE000520 | Fence | 527-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | FE000520 | Fence | 527-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | FE000520 | Fence | 527-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | FE000520 | Fence | 527-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | FE000520 | Fence | 527-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | FE000520 | Fence | 527-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | FE000520 | Fence | 527-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | FE000520 | Fence | 527-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | FE000520 | Fence | 527-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | YD000526 | Yard | 527-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | YD000526 | Yard | 527-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | YD000526 | Yard | 527-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | YD000526 | Yard | 527-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | YD000526 | Yard | 527-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | YD000526 | Yard | 527-Yard | Yard Patrol Inspection | General Comments | | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | YD000526 | Yard | 527-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | YD000526 | Yard | 527-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | YD000526 | Yard | 527-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | YD000526 | Yard | 527-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | YD000526 | Yard | 527-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | YD000526 | Yard | 527-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | YD000526 | Yard | 527-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | YD000526 | Yard | 527-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | YD000526 | Yard | 527-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/16/2023 10:44 | Distribution | Elizabethtown 5 Quarterly Inspection | YD000526 | Yard | 527-Yard | Yard Patrol Inspection | Ambient Temp | 48 | °F |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000116 | Switchgear | SN-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000116 | Switchgear | SN-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000116 | Switchgear | SN-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000122 | Switchgear | SN-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000122 | Switchgear | SN-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000122 | Switchgear | SN-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0849 | BreakerAirMagnetic | SN-SEC 2 SPARE | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0849 | BreakerAirMagnetic | SN-SEC 2 SPARE | AMCB Readings | Operations Counter AF | 197 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0849 | BreakerAirMagnetic | SN-SEC 2 SPARE | AMCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0849 | BreakerAirMagnetic | SN-SEC 2 SPARE | AMCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0849 | BreakerAirMagnetic | SN-SEC 2 SPARE | AMCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0849 | BreakerAirMagnetic | SN-SEC 2 SPARE | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0849 | BreakerAirMagnetic | SN-SEC 2 SPARE | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0849 | BreakerAirMagnetic | SN-SEC 2 SPARE | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0849 | BreakerAirMagnetic | SN-SEC 2 SPARE | AMCB Readings | Amps C Ø | 0.0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0849 | BreakerAirMagnetic | SN-SEC 2 SPARE | AMCB Readings | Amps B Ø | 0.0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0849 | BreakerAirMagnetic | SN-SEC 2 SPARE | AMCB Readings | Amps A Ø | 0.0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0849 | BreakerAirMagnetic | SN-SEC 2 SPARE | AMCB Readings | Operations Counter AL | 197 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0849 | BreakerAirMagnetic | SN-SEC 2 SPARE | AMCB Readings | Switching Operations | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0849 | BreakerAirMagnetic | SN-SEC 2 SPARE | AMCB Readings | Unknown Operations | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0847 | BreakerAirMagnetic | SN-4 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0847 | BreakerAirMagnetic | SN-4 | AMCB Readings | Unknown Operations | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0847 | BreakerAirMagnetic | SN-4 | AMCB Readings | Switching Operations | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0847 | BreakerAirMagnetic | SN-4 | AMCB Readings | Operations Counter AL | 572 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0847 | BreakerAirMagnetic | SN-4 | AMCB Readings | Operations Counter AF | 572 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0847 | BreakerAirMagnetic | SN-4 | AMCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0847 | BreakerAirMagnetic | SN-4 | AMCB Readings | Amps A Ø | 100.0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0847 | BreakerAirMagnetic | SN-4 | AMCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0847 | BreakerAirMagnetic | SN-4 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0847 | BreakerAirMagnetic | SN-4 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0847 | BreakerAirMagnetic | SN-4 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0847 | BreakerAirMagnetic | SN-4 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0847 | BreakerAirMagnetic | SN-4 | AMCB Readings | Amps C Ø | 100.0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0847 | BreakerAirMagnetic | SN-4 | AMCB Readings | Amps B Ø | 100.0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | LTCMechanism | SN-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Very Low | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | LTCMechanism | SN-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | LTC oil level is very low. oil dripping from winding temp gauge. | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | LTCMechanism | SN-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0846 | BreakerAirMagnetic | SN-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0846 | BreakerAirMagnetic | SN-3 | AMCB Readings | Unknown Operations | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0846 | BreakerAirMagnetic | SN-3 | AMCB Readings | Switching Operations | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0846 | BreakerAirMagnetic | SN-3 | AMCB Readings | Operations Counter AL | 236 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0846 | BreakerAirMagnetic | SN-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0846 | BreakerAirMagnetic | SN-3 | AMCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0846 | BreakerAirMagnetic | SN-3 | AMCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0846 | BreakerAirMagnetic | SN-3 | AMCB Readings | Operations Counter AF | 236 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0846 | BreakerAirMagnetic | SN-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0846 | BreakerAirMagnetic | SN-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0846 | BreakerAirMagnetic | SN-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0846 | BreakerAirMagnetic | SN-3 | AMCB Readings | Amps C Ø | 20.0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0846 | BreakerAirMagnetic | SN-3 | AMCB Readings | Amps B Ø | 20.0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0846 | BreakerAirMagnetic | SN-3 | AMCB Readings | Amps A Ø | 20.0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0845 | BreakerAirMagnetic | SN-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0845 | BreakerAirMagnetic | SN-2 | AMCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0845 | BreakerAirMagnetic | SN-2 | AMCB Readings | Operations Counter AF | 393 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0845 | BreakerAirMagnetic | SN-2 | AMCB Readings | Operations Counter AL | 393 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0845 | BreakerAirMagnetic | SN-2 | AMCB Readings | Switching Operations | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0845 | BreakerAirMagnetic | SN-2 | AMCB Readings | Unknown Operations | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0845 | BreakerAirMagnetic | SN-2 | AMCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0845 | BreakerAirMagnetic | SN-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0845 | BreakerAirMagnetic | SN-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0845 | BreakerAirMagnetic | SN-2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0845 | BreakerAirMagnetic | SN-2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0845 | BreakerAirMagnetic | SN-2 | AMCB Readings | Amps C Ø | 120.0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0845 | BreakerAirMagnetic | SN-2 | AMCB Readings | Amps B Ø | 120.0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0845 | BreakerAirMagnetic | SN-2 | AMCB Readings | Amps A Ø | 110.0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0844 | BreakerAirMagnetic | SN-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0844 | BreakerAirMagnetic | SN-1 | AMCB Readings | Unknown Operations | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0844 | BreakerAirMagnetic | SN-1 | AMCB Readings | Switching Operations | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0844 | BreakerAirMagnetic | SN-1 | AMCB Readings | Operations Counter AL | 399 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0844 | BreakerAirMagnetic | SN-1 | AMCB Readings | Operations Counter AF | 399 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0844 | BreakerAirMagnetic | SN-1 | AMCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0844 | BreakerAirMagnetic | SN-1 | AMCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0844 | BreakerAirMagnetic | SN-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0844 | BreakerAirMagnetic | SN-1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0844 | BreakerAirMagnetic | SN-1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0844 | BreakerAirMagnetic | SN-1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0844 | BreakerAirMagnetic | SN-1 | AMCB Readings | Amps C Ø | 80.0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0844 | BreakerAirMagnetic | SN-1 | AMCB Readings | Amps B Ø | 90.0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0844 | BreakerAirMagnetic | SN-1 | AMCB Readings | Amps A Ø | 80.0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | BCH001123 | Charger | SN-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | BCH001123 | Charger | SN-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | BCH001123 | Charger | SN-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.7 | VDC |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | BCH001123 | Charger | SN-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.7 | VDC |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | BCH001123 | Charger | SN-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | BAT001292 | Battery | SN-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | BAT001292 | Battery | SN-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | BAT001292 | Battery | SN-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | BAT001292 | Battery | SN-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | CH000447 | ControlHouse | SN-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | CH000447 | ControlHouse | SN-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | CH000447 | ControlHouse | SN-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | YD000583 | Yard | SN-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | YD000583 | Yard | SN-Yard | Yard Patrol Inspection | Ambient Temp | 40 | °F |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | FE000577 | Fence | SN-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PF001335 | PowerFuse | SN-4KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PF001335 | PowerFuse | SN-4KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | LTCMechanism | SN-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | LTCMechanism | SN-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 1 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | LTCMechanism | SN-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | LTCMechanism | SN-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 3L | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | LTCMechanism | SN-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | LTCMechanism | SN-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 409608 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | LTCMechanism | SN-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 409608 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | LTCMechanism | SN-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | LTCMechanism | SN-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Readings | Percent Thermal Load C Ø Max | -60 | % |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 15 | °C |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Readings | Percent Thermal Load A Ø Max | -60 | % |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Readings | Percent Thermal Load B Ø Max | -60 | % |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | LTCMechanism | SN-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | LTCMechanism | SN-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 426551 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | LTCMechanism | SN-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 426551 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | LTCMechanism | SN-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | LTCMechanism | SN-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | LTCMechanism | SN-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | LTCMechanism | SN-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 831 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | LTCMechanism | SN-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Readings | Percent Thermal Load C Ø Max | -60 | % |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Readings | Percent Thermal Load B Ø Max | -60 | % |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Readings | Percent Thermal Load A Ø Max | -60 | % |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 15 | °C |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 65 | °C |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -1.0 | psi |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | Trans nitro level is in vacuum and needs nitro. | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0586 | Regulator | 791-2402 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0586 | Regulator | 791-2402 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0586 | Regulator | 791-2402 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0586 | Regulator | 791-2402 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0586 | Regulator | 791-2402 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0586 | Regulator | 791-2402 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0586 | Regulator | 791-2402 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0586 | Regulator | 791-2402 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0586 | Regulator | 791-2402 C | Regulator Patrol Inspection | Regulator As Left Counter | 31984 | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0586 | Regulator | 791-2402 C | Regulator Patrol Inspection | General Comments | | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0586 | Regulator | 791-2402 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0586 | Regulator | 791-2402 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.3 | volts |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0586 | Regulator | 791-2402 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0586 | Regulator | 791-2402 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0586 | Regulator | 791-2402 C | Regulator Patrol Inspection | Current Tap Position | 5R | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0586 | Regulator | 791-2402 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0586 | Regulator | 791-2402 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0586 | Regulator | 791-2402 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0586 | Regulator | 791-2402 C | Regulator Patrol Inspection | Min Tap Position | Neutral | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0586 | Regulator | 791-2402 C | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0586 | Regulator | 791-2402 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0586 | Regulator | 791-2402 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0586 | Regulator | 791-2402 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0586 | Regulator | 791-2402 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0652 | Regulator | 791-2402 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0652 | Regulator | 791-2402 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0652 | Regulator | 791-2402 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0652 | Regulator | 791-2402 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0652 | Regulator | 791-2402 B | Regulator Patrol Inspection | Regulator As Left Counter | 123108 | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0652 | Regulator | 791-2402 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.7 | volts |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0652 | Regulator | 791-2402 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0652 | Regulator | 791-2402 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0652 | Regulator | 791-2402 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0652 | Regulator | 791-2402 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0652 | Regulator | 791-2402 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0652 | Regulator | 791-2402 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0652 | Regulator | 791-2402 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0652 | Regulator | 791-2402 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0652 | Regulator | 791-2402 B | Regulator Patrol Inspection | Current Tap Position | 9R | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0652 | Regulator | 791-2402 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0652 | Regulator | 791-2402 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0652 | Regulator | 791-2402 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0652 | Regulator | 791-2402 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0652 | Regulator | 791-2402 B | Regulator Patrol Inspection | Min Tap Position | 3R | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0652 | Regulator | 791-2402 B | Regulator Patrol Inspection | Max Tap Position | 11R | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0652 | Regulator | 791-2402 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0652 | Regulator | 791-2402 B | Regulator Patrol Inspection | General Comments | | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0652 | Regulator | 791-2402 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000626 | RegulatorControl | 791-2402 B | Regulator Annual Control Inspection | VRR Bandwidth AL | 3 | VAC |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000626 | RegulatorControl | 791-2402 B | Regulator Annual Control Inspection | VRR Bandwidth AF | 3 | VAC |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000626 | RegulatorControl | 791-2402 B | Regulator Annual Control Inspection | VRR Time Delay | 45 | Seconds |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000626 | RegulatorControl | 791-2402 B | Regulator Annual Control Inspection | VRR R Compensation AL | 0 | Position |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000626 | RegulatorControl | 791-2402 B | Regulator Annual Control Inspection | VRR R Compensation AF | 0 | Position |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000626 | RegulatorControl | 791-2402 B | Regulator Annual Control Inspection | VRR Counter AL | 123108 | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000626 | RegulatorControl | 791-2402 B | Regulator Annual Control Inspection | VRR Counter AF | 123105 | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000626 | RegulatorControl | 791-2402 B | Regulator Annual Control Inspection | VRR Base Voltage AL | 125 | VAC |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000626 | RegulatorControl | 791-2402 B | Regulator Annual Control Inspection | All Connections OK? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000626 | RegulatorControl | 791-2402 B | Regulator Annual Control Inspection | Current Tap Position | 9R | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000626 | RegulatorControl | 791-2402 B | Regulator Annual Control Inspection | Follow-up Action Required? | n | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000626 | RegulatorControl | 791-2402 B | Regulator Annual Control Inspection | Reset Tap Drag Hands | Reset | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000626 | RegulatorControl | 791-2402 B | Regulator Annual Control Inspection | Min Tap Position | 3R | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000626 | RegulatorControl | 791-2402 B | Regulator Annual Control Inspection | Max Tap Position | 11R | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000626 | RegulatorControl | 791-2402 B | Regulator Annual Control Inspection | General Comments | | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000626 | RegulatorControl | 791-2402 B | Regulator Annual Control Inspection | VRR Base Voltage AF | 125 | VAC |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PF001334 | PowerFuse | SN-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PF001334 | PowerFuse | SN-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0502 | Regulator | 791-2402 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0502 | Regulator | 791-2402 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0502 | Regulator | 791-2402 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0502 | Regulator | 791-2402 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0502 | Regulator | 791-2402 A | Regulator Patrol Inspection | General Comments | | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0502 | Regulator | 791-2402 A | Regulator Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0502 | Regulator | 791-2402 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0502 | Regulator | 791-2402 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0502 | Regulator | 791-2402 A | Regulator Patrol Inspection | Current Tap Position | 3R | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0502 | Regulator | 791-2402 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0502 | Regulator | 791-2402 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0502 | Regulator | 791-2402 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0502 | Regulator | 791-2402 A | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0502 | Regulator | 791-2402 A | Regulator Patrol Inspection | Min Tap Position | 2L | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0502 | Regulator | 791-2402 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0502 | Regulator | 791-2402 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0502 | Regulator | 791-2402 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0502 | Regulator | 791-2402 A | Regulator Patrol Inspection | Reg Operation Checked? | n | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0502 | Regulator | 791-2402 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0502 | Regulator | 791-2402 A | Regulator Patrol Inspection | Regulator As Left Counter | 0 | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0502 | Regulator | 791-2402 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0502 | Regulator | 791-2402 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0502 | Regulator | 791-2402 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | R0502 | Regulator | 791-2402 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000499 | RegulatorControl | 791-2402 A | Regulator Annual Control Inspection | All Connections OK? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000499 | RegulatorControl | 791-2402 A | Regulator Annual Control Inspection | Current Tap Position | 3R | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000499 | RegulatorControl | 791-2402 A | Regulator Annual Control Inspection | Follow-up Action Required? | n | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000499 | RegulatorControl | 791-2402 A | Regulator Annual Control Inspection | General Comments | | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000499 | RegulatorControl | 791-2402 A | Regulator Annual Control Inspection | Max Tap Position | 6R | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000499 | RegulatorControl | 791-2402 A | Regulator Annual Control Inspection | Min Tap Position | 2L | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000499 | RegulatorControl | 791-2402 A | Regulator Annual Control Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000499 | RegulatorControl | 791-2402 A | Regulator Annual Control Inspection | VRR Bandwidth AF | 3 | VAC |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000499 | RegulatorControl | 791-2402 A | Regulator Annual Control Inspection | VRR Bandwidth AL | 3 | VAC |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000499 | RegulatorControl | 791-2402 A | Regulator Annual Control Inspection | VRR Time Delay | 45 | Seconds |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000499 | RegulatorControl | 791-2402 A | Regulator Annual Control Inspection | VRR R Compensation AL | 0 | Position |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000499 | RegulatorControl | 791-2402 A | Regulator Annual Control Inspection | VRR R Compensation AF | 0 | Position |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000499 | RegulatorControl | 791-2402 A | Regulator Annual Control Inspection | VRR Base Voltage AL | 124 | VAC |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | KRC000499 | RegulatorControl | 791-2402 A | Regulator Annual Control Inspection | VRR Base Voltage AF | 124 | VAC |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | FE000802 | Fence | 791-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | FE000802 | Fence | 791-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | FE000802 | Fence | 791-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | FE000802 | Fence | 791-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | FE000802 | Fence | 791-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | FE000802 | Fence | 791-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | FE000802 | Fence | 791-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | FE000802 | Fence | 791-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | FE000802 | Fence | 791-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | FE000802 | Fence | 791-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | FE000802 | Fence | 791-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | FE000802 | Fence | 791-Fence | Fence Patrol Inspection | General Comments | | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | FE000802 | Fence | 791-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | FE000802 | Fence | 791-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | FE000802 | Fence | 791-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | FE000802 | Fence | 791-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | ST000836 | Structure | 791-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | ST000836 | Structure | 791-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | ST000836 | Structure | 791-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | ST000836 | Structure | 791-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | ST000836 | Structure | 791-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | ST000836 | Structure | 791-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | ST000836 | Structure | 791-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | ST000836 | Structure | 791-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | ST000836 | Structure | 791-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | ST000836 | Structure | 791-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | ST000836 | Structure | 791-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | ST000836 | Structure | 791-Structure | Structure Patrol Inspection | General Comments | | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | ST000836 | Structure | 791-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | ST000836 | Structure | 791-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | ST000836 | Structure | 791-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | ST000836 | Structure | 791-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | ST000836 | Structure | 791-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | YD000848 | Yard | 791-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | YD000848 | Yard | 791-Yard | Yard Patrol Inspection | General Comments | | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | YD000848 | Yard | 791-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | YD000848 | Yard | 791-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | YD000848 | Yard | 791-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | YD000848 | Yard | 791-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | YD000848 | Yard | 791-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | YD000848 | Yard | 791-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | YD000848 | Yard | 791-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | YD000848 | Yard | 791-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | YD000848 | Yard | 791-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | YD000848 | Yard | 791-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | YD000848 | Yard | 791-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | YD000848 | Yard | 791-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | YD000848 | Yard | 791-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/16/2023 9:30 | Distribution | Boston Quarterly Inspection | YD000848 | Yard | 791-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | BAT001429 | Battery | VE-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | BAT001429 | Battery | VE-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | BAT001429 | Battery | VE-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | BAT001429 | Battery | VE-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | LTCMechanism | VE-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | LTCMechanism | VE-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 432112 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | LTCMechanism | VE-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 432112 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | LTCMechanism | VE-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | LTCMechanism | VE-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | LTCMechanism | VE-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | LTCMechanism | VE-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 970 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | LTCMechanism | VE-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | LTCMechanism | VE-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0694 | BreakerVacuum | NA-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0694 | BreakerVacuum | NA-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0694 | BreakerVacuum | NA-12KV BUS TIE SEC 3 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .8 | psi |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0691 | BreakerVacuum | NA-1274 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0691 | BreakerVacuum | NA-1274 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0691 | BreakerVacuum | NA-1274 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0690 | BreakerVacuum | NA-1273 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0690 | BreakerVacuum | NA-1273 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0690 | BreakerVacuum | NA-1273 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0689 | BreakerVacuum | NA-1272 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0689 | BreakerVacuum | NA-1272 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0689 | BreakerVacuum | NA-1272 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0688 | BreakerVacuum | NA-1271 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0688 | BreakerVacuum | NA-1271 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0688 | BreakerVacuum | NA-1271 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0697 | BreakerVacuum | NA-12KV TR 3 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0697 | BreakerVacuum | NA-12KV TR 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LB0697 | BreakerVacuum | NA-12KV TR 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Readings | H3 Winding Temp Present | 60 | °C |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Readings | H3 Winding Temp Max | 30 | °C |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Readings | H2 Winding Temp Present | 25 | °C |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Readings | H2 Winding Temp Max | 55 | °C |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Readings | H1 Winding Temp Present | 30 | °C |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Readings | H1 Winding Temp Max | 60 | °C |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | PF000259 | PowerFuse | NA-12KV TR 3 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | PF000259 | PowerFuse | NA-12KV TR 3 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | PF000259 | PowerFuse | NA-12KV TR 3 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | PF000260 | PowerFuse | NA-STA SER NO 3 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | PF000260 | PowerFuse | NA-STA SER NO 3 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | PF000260 | PowerFuse | NA-STA SER NO 3 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000123 | Switchgear | NA-Swgr Sec 3 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000123 | Switchgear | NA-Swgr Sec 3 | Switchgear Patrol Inspection | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000123 | Switchgear | NA-Swgr Sec 3 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000123 | Switchgear | NA-Swgr Sec 3 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000123 | Switchgear | NA-Swgr Sec 3 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000123 | Switchgear | NA-Swgr Sec 3 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000123 | Switchgear | NA-Swgr Sec 3 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000123 | Switchgear | NA-Swgr Sec 3 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000123 | Switchgear | NA-Swgr Sec 3 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000123 | Switchgear | NA-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000123 | Switchgear | NA-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000123 | Switchgear | NA-Swgr Sec 3 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000123 | Switchgear | NA-Swgr Sec 3 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000123 | Switchgear | NA-Swgr Sec 3 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000123 | Switchgear | NA-Swgr Sec 3 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000123 | Switchgear | NA-Swgr Sec 3 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000123 | Switchgear | NA-Swgr Sec 3 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000123 | Switchgear | NA-Swgr Sec 3 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000123 | Switchgear | NA-Swgr Sec 3 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | PF000258 | PowerFuse | NA-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | PF000258 | PowerFuse | NA-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | PF000258 | PowerFuse | NA-12KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | PF000257 | PowerFuse | NA-STA SER NO 2 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | PF000257 | PowerFuse | NA-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | PF000257 | PowerFuse | NA-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000132 | Switchgear | NA-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000132 | Switchgear | NA-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000132 | Switchgear | NA-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000132 | Switchgear | NA-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000132 | Switchgear | NA-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000132 | Switchgear | NA-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000132 | Switchgear | NA-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000132 | Switchgear | NA-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000132 | Switchgear | NA-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000132 | Switchgear | NA-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000132 | Switchgear | NA-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000132 | Switchgear | NA-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000132 | Switchgear | NA-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000132 | Switchgear | NA-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000132 | Switchgear | NA-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000132 | Switchgear | NA-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000132 | Switchgear | NA-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000132 | Switchgear | NA-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | SWG000132 | Switchgear | NA-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | PF000255 | PowerFuse | NA-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | PF000255 | PowerFuse | NA-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | PF000255 | PowerFuse | NA-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | PF000256 | PowerFuse | NA-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | PF000256 | PowerFuse | NA-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | PF000256 | PowerFuse | NA-12KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LTCC000211 | LTCControl | NA-TRANS 3 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LTCC000211 | LTCControl | NA-TRANS 3 | LTC Control Insp | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LTCC000211 | LTCControl | NA-TRANS 3 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | SWG000039 | Switchgear | VE-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | SWG000039 | Switchgear | VE-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | SWG000039 | Switchgear | VE-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1035 | BreakerAirMagnetic | VE-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1035 | BreakerAirMagnetic | VE-3 | AMCB Readings | Unknown Operations | 0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1035 | BreakerAirMagnetic | VE-3 | AMCB Readings | Switching Operations | 0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1035 | BreakerAirMagnetic | VE-3 | AMCB Readings | Operations This Read AM | 1 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1035 | BreakerAirMagnetic | VE-3 | AMCB Readings | Operations Counter AL | 476 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1035 | BreakerAirMagnetic | VE-3 | AMCB Readings | Operations Counter AF | 476 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1035 | BreakerAirMagnetic | VE-3 | AMCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1035 | BreakerAirMagnetic | VE-3 | AMCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1035 | BreakerAirMagnetic | VE-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1035 | BreakerAirMagnetic | VE-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1035 | BreakerAirMagnetic | VE-3 | AMCB Readings | Fault Operations B Ø | 1 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1035 | BreakerAirMagnetic | VE-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1035 | BreakerAirMagnetic | VE-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 9.55 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1035 | BreakerAirMagnetic | VE-3 | AMCB Readings | Amps C Ø | 80.0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1035 | BreakerAirMagnetic | VE-3 | AMCB Readings | Amps B Ø | 80.0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1035 | BreakerAirMagnetic | VE-3 | AMCB Readings | Amps A Ø | 80.0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1035 | BreakerAirMagnetic | VE-3 | AMCB Readings | 9 Months Operations | 1 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1034 | BreakerAirMagnetic | VE-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1034 | BreakerAirMagnetic | VE-2 | AMCB Readings | Unknown Operations | 0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1034 | BreakerAirMagnetic | VE-2 | AMCB Readings | Switching Operations | 0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1034 | BreakerAirMagnetic | VE-2 | AMCB Readings | Operations Counter AL | 474 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1034 | BreakerAirMagnetic | VE-2 | AMCB Readings | Operations Counter AF | 474 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1034 | BreakerAirMagnetic | VE-2 | AMCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1034 | BreakerAirMagnetic | VE-2 | AMCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1034 | BreakerAirMagnetic | VE-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1034 | BreakerAirMagnetic | VE-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1034 | BreakerAirMagnetic | VE-2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1034 | BreakerAirMagnetic | VE-2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1034 | BreakerAirMagnetic | VE-2 | AMCB Readings | Amps C Ø | 20.0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1034 | BreakerAirMagnetic | VE-2 | AMCB Readings | Amps B Ø | 20.0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1034 | BreakerAirMagnetic | VE-2 | AMCB Readings | Amps A Ø | 20.0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1033 | BreakerAirMagnetic | VE-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1033 | BreakerAirMagnetic | VE-1 | AMCB Readings | Operations This Read AM | 1 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1033 | BreakerAirMagnetic | VE-1 | AMCB Readings | Switching Operations | 0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1033 | BreakerAirMagnetic | VE-1 | AMCB Readings | Unknown Operations | 0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1033 | BreakerAirMagnetic | VE-1 | AMCB Readings | Operations Counter AL | 418 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1033 | BreakerAirMagnetic | VE-1 | AMCB Readings | Operations Counter AF | 418 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1033 | BreakerAirMagnetic | VE-1 | AMCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1033 | BreakerAirMagnetic | VE-1 | AMCB Readings | General Comments | B,C IOC | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1033 | BreakerAirMagnetic | VE-1 | AMCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1033 | BreakerAirMagnetic | VE-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1033 | BreakerAirMagnetic | VE-1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1033 | BreakerAirMagnetic | VE-1 | AMCB Readings | Fault Operations B Ø | 1 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1033 | BreakerAirMagnetic | VE-1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1033 | BreakerAirMagnetic | VE-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 9.55 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1033 | BreakerAirMagnetic | VE-1 | AMCB Readings | Amps C Ø | 90.0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1033 | BreakerAirMagnetic | VE-1 | AMCB Readings | Amps B Ø | 80.0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1033 | BreakerAirMagnetic | VE-1 | AMCB Readings | Amps A Ø | 125.0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1033 | BreakerAirMagnetic | VE-1 | AMCB Readings | 9 Months Operations | 1 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | BCH000091 | Charger | VE-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | BCH000091 | Charger | VE-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | BCH000091 | Charger | VE-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.7 | VDC |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | BCH000091 | Charger | VE-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.7 | VDC |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | BCH000091 | Charger | VE-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | CH000462 | ControlHouse | VE-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | CH000462 | ControlHouse | VE-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | CH000462 | ControlHouse | VE-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | YD000611 | Yard | VE-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | YD000611 | Yard | VE-Yard | Yard Patrol Inspection | Ambient Temp | 40 | °F |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | FE000611 | Fence | VE-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PF001341 | PowerFuse | VE-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PF001341 | PowerFuse | VE-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LTCC000213 | LTCControl | NA-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LTCC000213 | LTCControl | NA-TRANS 2 | LTC Control Insp | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LTCC000213 | LTCControl | NA-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | LTCMechanism | NA-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | LTCMechanism | NA-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | LTCMechanism | NA-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | LTCMechanism | NA-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | LTCMechanism | NA-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LT0138 | LTCMechanism | NA-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LTCM000042 | LTCMechanism | NA-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LTCM000042 | LTCMechanism | NA-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LTCM000042 | LTCMechanism | NA-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LTCM000042 | LTCMechanism | NA-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LTCM000042 | LTCMechanism | NA-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LTCM000042 | LTCMechanism | NA-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LTCM000042 | LTCMechanism | NA-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LTCC000212 | LTCControl | NA-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LTCC000212 | LTCControl | NA-TRANS 1 | LTC Control Insp | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | LTCC000212 | LTCControl | NA-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BAT000017 | Battery | NA-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BAT000017 | Battery | NA-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BAT000017 | Battery | NA-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BAT000017 | Battery | NA-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BAT000017 | Battery | NA-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BAT000017 | Battery | NA-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BAT000017 | Battery | NA-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BAT000017 | Battery | NA-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BAT000017 | Battery | NA-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BAT000017 | Battery | NA-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BAT000017 | Battery | NA-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BAT000017 | Battery | NA-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | CH000192 | ControlHouse | NA-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | CH000192 | ControlHouse | NA-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | CH000192 | ControlHouse | NA-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | CH000192 | ControlHouse | NA-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | CH000192 | ControlHouse | NA-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | CH000192 | ControlHouse | NA-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | CH000192 | ControlHouse | NA-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | CH000192 | ControlHouse | NA-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | CH000192 | ControlHouse | NA-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | CH000192 | ControlHouse | NA-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | CH000192 | ControlHouse | NA-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | CH000192 | ControlHouse | NA-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | CH000192 | ControlHouse | NA-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | CH000192 | ControlHouse | NA-Control House | Control House Patrol Inspection | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | CH000192 | ControlHouse | NA-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | CH000192 | ControlHouse | NA-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | CH000192 | ControlHouse | NA-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | CH000192 | ControlHouse | NA-Control House | Control House Patrol Inspection | Restroom Clean & OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | CH000192 | ControlHouse | NA-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | CH000192 | ControlHouse | NA-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | CH000192 | ControlHouse | NA-Control House | Control House Patrol Inspection | Trash Emptied? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | CH000192 | ControlHouse | NA-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | CH000192 | ControlHouse | NA-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | ST000632 | Structure | NA-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | ST000632 | Structure | NA-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | ST000632 | Structure | NA-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | ST000632 | Structure | NA-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | ST000632 | Structure | NA-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | ST000632 | Structure | NA-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | ST000632 | Structure | NA-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | ST000632 | Structure | NA-Structure | Structure Patrol Inspection | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | ST000632 | Structure | NA-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | ST000632 | Structure | NA-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | ST000632 | Structure | NA-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | ST000632 | Structure | NA-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | ST000632 | Structure | NA-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | ST000632 | Structure | NA-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | ST000632 | Structure | NA-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | ST000632 | Structure | NA-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | ST000632 | Structure | NA-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | YD000653 | Yard | NA-Yard | Yard Patrol Inspection | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | YD000653 | Yard | NA-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | YD000653 | Yard | NA-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | YD000653 | Yard | NA-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | YD000653 | Yard | NA-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | YD000653 | Yard | NA-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | YD000653 | Yard | NA-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | YD000653 | Yard | NA-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | YD000653 | Yard | NA-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | YD000653 | Yard | NA-Yard | Yard Patrol Inspection | Ambient Temp | 38 | °F |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | YD000653 | Yard | NA-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | YD000653 | Yard | NA-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | YD000653 | Yard | NA-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | YD000653 | Yard | NA-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | YD000653 | Yard | NA-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | YD000653 | Yard | NA-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | YD000653 | Yard | NA-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | YD000653 | Yard | NA-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | YD000653 | Yard | NA-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002099 | BreakerVacuum | NA-1264 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002100 | BreakerVacuum | NA-1265 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002101 | BreakerVacuum | NA-1266 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002107 | BreakerVacuum | NA-12KV TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002102 | BreakerVacuum | NA-1267 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002103 | BreakerVacuum | NA-1268 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002104 | BreakerVacuum | NA-1269 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002105 | BreakerVacuum | NA-1270 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002106 | BreakerVacuum | NA-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 13:16 | Distribution | Nachand Quarterly Inspection | BK002108 | BreakerVacuum | NA-12KV TR 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0801 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0801 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 60.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0801 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0801 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0801 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 4 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0801 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0801 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 80.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0801 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 70.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0801 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0801 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 22.36 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0801 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 22.36 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0801 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0801 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 2 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0801 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 2 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0801 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0801 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0801 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | B and C phase IOC | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0801 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0801 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 167 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0801 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 167 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0801 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 4 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0801 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0801 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0800 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 3 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0800 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 3 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0800 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 3 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0800 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0800 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 33.54 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0800 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 33.54 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0800 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 33.54 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0800 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 80.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0800 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 90.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0800 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 100.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0800 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0800 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0800 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0800 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 9 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0800 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0800 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0800 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | A, B, and C phase IOC; A phase TOC | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0800 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0800 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 273 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0800 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 273 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0800 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 9 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0800 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0800 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0799 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 3 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0799 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 18 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0799 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0799 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0799 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0799 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 90.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0799 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 80.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0799 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 100.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0799 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 55.90 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0799 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 55.90 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0799 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 55.90 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0799 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 5 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0799 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 5 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0799 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 5 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0799 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0799 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0799 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | A, B, and C phase IOC; B phase TOC | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0799 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0799 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 62 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0799 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 62 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0799 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 15 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0799 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0799 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0798 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0798 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 334 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0798 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 334 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0798 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0798 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0798 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0798 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0798 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0798 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0798 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0798 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0798 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0798 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0798 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0798 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0798 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 110.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0798 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 110.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0798 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 100.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0798 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0798 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0798 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0798 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0798 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0797 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0797 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0797 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0797 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0797 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0797 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0797 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0797 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 190.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0797 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0797 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0797 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0797 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0797 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 170.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0797 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 190.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0797 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0797 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0797 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0797 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0797 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 1084 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0797 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 1084 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0797 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0797 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0797 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0803 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0803 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0803 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0803 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0803 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0803 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 400.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0803 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 420.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0803 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 420.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0803 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0803 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0803 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0803 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0803 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0803 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0803 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0803 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0803 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0803 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0803 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 181 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0803 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 181 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0803 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0803 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0803 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LTCM000035 | LTCMechanism | PL-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LTCM000035 | LTCMechanism | PL-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LTCM000035 | LTCMechanism | PL-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 526 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LTCM000035 | LTCMechanism | PL-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LTCM000035 | LTCMechanism | PL-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LTCM000035 | LTCMechanism | PL-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 28778 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LTCM000035 | LTCMechanism | PL-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 28778 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LTCM000035 | LTCMechanism | PL-TRANS 1 | LTC Counter Readings | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LTCM000035 | LTCMechanism | PL-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 25 | °C |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 40 | °C |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 35 | °C |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 28 | °C |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 50 | °C |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 35 | °C |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 50 | °C |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0162 | WithLTC | PL-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .2 | psi |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001451 | BreakerVacuum | PL-12KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001451 | BreakerVacuum | PL-12KV TR 2 | VCB Readings | Switching Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001451 | BreakerVacuum | PL-12KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001451 | BreakerVacuum | PL-12KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001451 | BreakerVacuum | PL-12KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001451 | BreakerVacuum | PL-12KV TR 2 | VCB Readings | Operations Counter AL | 290 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001451 | BreakerVacuum | PL-12KV TR 2 | VCB Readings | Amps C Ø | 219.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001451 | BreakerVacuum | PL-12KV TR 2 | VCB Readings | Amps B Ø | 196.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001451 | BreakerVacuum | PL-12KV TR 2 | VCB Readings | Amps A Ø | 185.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001451 | BreakerVacuum | PL-12KV TR 2 | VCB Readings | Operations Counter AF | 290 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001451 | BreakerVacuum | PL-12KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001451 | BreakerVacuum | PL-12KV TR 2 | VCB Readings | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001451 | BreakerVacuum | PL-12KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001451 | BreakerVacuum | PL-12KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001451 | BreakerVacuum | PL-12KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001451 | BreakerVacuum | PL-12KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001451 | BreakerVacuum | PL-12KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001451 | BreakerVacuum | PL-12KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001451 | BreakerVacuum | PL-12KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001451 | BreakerVacuum | PL-12KV TR 2 | VCB Readings | 9 Month Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001451 | BreakerVacuum | PL-12KV TR 2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001451 | BreakerVacuum | PL-12KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001451 | BreakerVacuum | PL-12KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001452 | BreakerVacuum | PL-1275 | VCB Readings | General Comments | DNO | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001452 | BreakerVacuum | PL-1275 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001452 | BreakerVacuum | PL-1275 | VCB Readings | Operations Counter AF | 176 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001452 | BreakerVacuum | PL-1275 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001452 | BreakerVacuum | PL-1275 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001452 | BreakerVacuum | PL-1275 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001452 | BreakerVacuum | PL-1275 | VCB Readings | Operations Counter AL | 176 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001452 | BreakerVacuum | PL-1275 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001452 | BreakerVacuum | PL-1275 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001452 | BreakerVacuum | PL-1275 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001452 | BreakerVacuum | PL-1275 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001452 | BreakerVacuum | PL-1275 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001452 | BreakerVacuum | PL-1275 | VCB Readings | 9 Month Operations | 6 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001452 | BreakerVacuum | PL-1275 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001452 | BreakerVacuum | PL-1275 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001452 | BreakerVacuum | PL-1275 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001452 | BreakerVacuum | PL-1275 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001452 | BreakerVacuum | PL-1275 | VCB Readings | Amps A Ø | 0.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001452 | BreakerVacuum | PL-1275 | VCB Readings | Amps B Ø | 0.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001452 | BreakerVacuum | PL-1275 | VCB Readings | Amps C Ø | 0.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001452 | BreakerVacuum | PL-1275 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001452 | BreakerVacuum | PL-1275 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001452 | BreakerVacuum | PL-1275 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001453 | BreakerVacuum | PL-1276 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001453 | BreakerVacuum | PL-1276 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001453 | BreakerVacuum | PL-1276 | VCB Readings | Operations This Read Vac | 4 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001453 | BreakerVacuum | PL-1276 | VCB Readings | Operations Counter AL | 109 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001453 | BreakerVacuum | PL-1276 | VCB Readings | Operations Counter AF | 109 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001453 | BreakerVacuum | PL-1276 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001453 | BreakerVacuum | PL-1276 | VCB Readings | General Comments | A and B phase IOC | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001453 | BreakerVacuum | PL-1276 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001453 | BreakerVacuum | PL-1276 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001453 | BreakerVacuum | PL-1276 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001453 | BreakerVacuum | PL-1276 | VCB Readings | Fault Operations B Ø | 2 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001453 | BreakerVacuum | PL-1276 | VCB Readings | Fault Operations A Ø | 2 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001453 | BreakerVacuum | PL-1276 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001453 | BreakerVacuum | PL-1276 | VCB Readings | Fault Adjusted Amps B Phase V | 2.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001453 | BreakerVacuum | PL-1276 | VCB Readings | Fault Adjusted Amps A Phase V | 2.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001453 | BreakerVacuum | PL-1276 | VCB Readings | Amps C Ø | 176.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001453 | BreakerVacuum | PL-1276 | VCB Readings | Amps B Ø | 136.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001453 | BreakerVacuum | PL-1276 | VCB Readings | Amps A Ø | 139.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001453 | BreakerVacuum | PL-1276 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001453 | BreakerVacuum | PL-1276 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001453 | BreakerVacuum | PL-1276 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001453 | BreakerVacuum | PL-1276 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001453 | BreakerVacuum | PL-1276 | VCB Readings | 9 Month Operations | 4 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001454 | BreakerVacuum | PL-1277 | VCB Readings | 9 Month Operations | 1 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001454 | BreakerVacuum | PL-1277 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001454 | BreakerVacuum | PL-1277 | VCB Readings | Amps C Ø | 49.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001454 | BreakerVacuum | PL-1277 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001454 | BreakerVacuum | PL-1277 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001454 | BreakerVacuum | PL-1277 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001454 | BreakerVacuum | PL-1277 | VCB Readings | Fault Adjusted Amps C Phase V | 1.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001454 | BreakerVacuum | PL-1277 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001454 | BreakerVacuum | PL-1277 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001454 | BreakerVacuum | PL-1277 | VCB Readings | Fault Operations C Ø | 1 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001454 | BreakerVacuum | PL-1277 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001454 | BreakerVacuum | PL-1277 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001454 | BreakerVacuum | PL-1277 | VCB Readings | General Comments | C phase IOC | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001454 | BreakerVacuum | PL-1277 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001454 | BreakerVacuum | PL-1277 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001454 | BreakerVacuum | PL-1277 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001454 | BreakerVacuum | PL-1277 | VCB Readings | Amps A Ø | 54.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001454 | BreakerVacuum | PL-1277 | VCB Readings | Amps B Ø | 65.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001454 | BreakerVacuum | PL-1277 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001454 | BreakerVacuum | PL-1277 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001454 | BreakerVacuum | PL-1277 | VCB Readings | Operations This Read Vac | 1 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001454 | BreakerVacuum | PL-1277 | VCB Readings | Operations Counter AL | 110 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001454 | BreakerVacuum | PL-1277 | VCB Readings | Operations Counter AF | 110 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001457 | BreakerVacuum | PL-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001457 | BreakerVacuum | PL-12KV BUS TIE SEC 2 | VCB Readings | Amps A Ø | 0.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001457 | BreakerVacuum | PL-12KV BUS TIE SEC 2 | VCB Readings | Amps B Ø | 0.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001457 | BreakerVacuum | PL-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001457 | BreakerVacuum | PL-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001457 | BreakerVacuum | PL-12KV BUS TIE SEC 2 | VCB Readings | Amps C Ø | 0.0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001457 | BreakerVacuum | PL-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001457 | BreakerVacuum | PL-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001457 | BreakerVacuum | PL-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001457 | BreakerVacuum | PL-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001457 | BreakerVacuum | PL-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001457 | BreakerVacuum | PL-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations | 3 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001457 | BreakerVacuum | PL-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001457 | BreakerVacuum | PL-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001457 | BreakerVacuum | PL-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001457 | BreakerVacuum | PL-12KV BUS TIE SEC 2 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001457 | BreakerVacuum | PL-12KV BUS TIE SEC 2 | VCB Readings | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001457 | BreakerVacuum | PL-12KV BUS TIE SEC 2 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001457 | BreakerVacuum | PL-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AF | 166 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001457 | BreakerVacuum | PL-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AL | 166 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001457 | BreakerVacuum | PL-12KV BUS TIE SEC 2 | VCB Readings | Operations This Read Vac | 1 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001457 | BreakerVacuum | PL-12KV BUS TIE SEC 2 | VCB Readings | Switching Operations | 1 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001457 | BreakerVacuum | PL-12KV BUS TIE SEC 2 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Gas Accumulation Gauge | Normal | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1200 | psi |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 10 | °C |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 37 | °C |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 10 | °C |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 15 | °C |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 15 | °C |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 30 | °C |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 17 | °C |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Readings | H2 Winding Temp Present | 20 | °C |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Readings | H2 Winding Temp Max | 35 | °C |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | WithLTC | PL-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | LTCMechanism | PL-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | LTCMechanism | PL-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 10 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | LTCMechanism | PL-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | LTCMechanism | PL-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | LTCMechanism | PL-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | LTCMechanism | PL-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 7571 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | LTCMechanism | PL-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 7571 | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | LTCMechanism | PL-TRANS 2 | LTC Counter Readings | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | LTCMechanism | PL-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | FE000607 | Fence | WE-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | FE000607 | Fence | WE-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | FE000607 | Fence | WE-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | FE000607 | Fence | WE-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | FE000607 | Fence | WE-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | FE000607 | Fence | WE-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | FE000607 | Fence | WE-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | FE000607 | Fence | WE-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | FE000607 | Fence | WE-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | FE000607 | Fence | WE-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | FE000607 | Fence | WE-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | FE000607 | Fence | WE-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | FE000607 | Fence | WE-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | FE000607 | Fence | WE-Fence | Fence Patrol Inspection | General Comments | | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | FE000607 | Fence | WE-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | FE000607 | Fence | WE-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PF001343 | PowerFuse | WE-4KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PF001343 | PowerFuse | WE-4KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PF001342 | PowerFuse | WE-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/22/2023 9:23 | Distribution | Western Quarterly Inspection | PF001342 | PowerFuse | WE-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | LTCMechanism | PI-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | LTCMechanism | PI-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 866 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | LTCMechanism | PI-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | LTCMechanism | PI-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | LTCMechanism | PI-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | LTCMechanism | PI-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 14236 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | LTCMechanism | PI-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 14236 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | LTCMechanism | PI-TRANS 2 | LTC Counter Readings | General Comments | | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | LTCMechanism | PI-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | LTCMechanism | PI-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | LTCMechanism | PI-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | LTCMechanism | PI-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | LTCMechanism | PI-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 35 | °C |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | LTCMechanism | PI-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 25 | °C |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | LTCMechanism | PI-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | LTCMechanism | PI-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | LTCMechanism | PI-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1150 | psi |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LT0282 | WithLTC | PI-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | LTCMechanism | PI-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | LTCMechanism | PI-TRANS 1 | LTC Counter Readings | General Comments | | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | LTCMechanism | PI-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 416713 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | LTCMechanism | PI-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | LTCMechanism | PI-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 416713 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | LTCMechanism | PI-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 1R | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | LTCMechanism | PI-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 763 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | LTCMechanism | PI-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | LTCMechanism | PI-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | LTCMechanism | PI-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | LTCMechanism | PI-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | LTCMechanism | PI-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | LTCMechanism | PI-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | LTCMechanism | PI-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | LTCMechanism | PI-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Low | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -1.0 | psi |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 10 | °C |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PN65 | WithLTC | PI-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Readings | Amps A Ø | 22.0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Readings | Amps B Ø | 20.0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Readings | Amps C Ø | 28.0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Readings | 9 Month Operations | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Readings | Unknown Operations | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Readings | Switching Operations | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Readings | Operations This Read Vac | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Readings | Operations Counter AL | 42 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Readings | Operations Counter AF | 42 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Readings | General Comments | | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0788 | BreakerAirMagnetic | PI-3 | AMCB Readings | Operations This Read AM | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0788 | BreakerAirMagnetic | PI-3 | AMCB Readings | Operations Counter AL | 361 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0788 | BreakerAirMagnetic | PI-3 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0788 | BreakerAirMagnetic | PI-3 | AMCB Readings | 9 Months Operations | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0788 | BreakerAirMagnetic | PI-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0788 | BreakerAirMagnetic | PI-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0788 | BreakerAirMagnetic | PI-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0788 | BreakerAirMagnetic | PI-3 | AMCB Readings | Switching Operations | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0788 | BreakerAirMagnetic | PI-3 | AMCB Readings | Unknown Operations | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0788 | BreakerAirMagnetic | PI-3 | AMCB Readings | Amps A Ø | 100.0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0788 | BreakerAirMagnetic | PI-3 | AMCB Readings | Operations Counter AF | 361 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0788 | BreakerAirMagnetic | PI-3 | AMCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0788 | BreakerAirMagnetic | PI-3 | AMCB Readings | Amps B Ø | 95.0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0788 | BreakerAirMagnetic | PI-3 | AMCB Readings | Amps C Ø | 80.0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0788 | BreakerAirMagnetic | PI-3 | AMCB Readings | General Comments | | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0788 | BreakerAirMagnetic | PI-3 | AMCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0788 | BreakerAirMagnetic | PI-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0788 | BreakerAirMagnetic | PI-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0788 | BreakerAirMagnetic | PI-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0788 | BreakerAirMagnetic | PI-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0788 | BreakerAirMagnetic | PI-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0788 | BreakerAirMagnetic | PI-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0788 | BreakerAirMagnetic | PI-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Readings | Operations Counter AF | 99857 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Readings | Operations Counter AL | 99857 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Readings | Switching Operations | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Readings | Unknown Operations | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Readings | Amps C Ø | 100.0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Readings | Amps B Ø | 100.0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Readings | Amps A Ø | 100.0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Readings | 9 Month Operations | 1 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Readings | General Comments | | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0786 | BreakerAirMagnetic | PI-1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0786 | BreakerAirMagnetic | PI-1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0786 | BreakerAirMagnetic | PI-1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0786 | BreakerAirMagnetic | PI-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0786 | BreakerAirMagnetic | PI-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0786 | BreakerAirMagnetic | PI-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0786 | BreakerAirMagnetic | PI-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0786 | BreakerAirMagnetic | PI-1 | AMCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0786 | BreakerAirMagnetic | PI-1 | AMCB Readings | General Comments | | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0786 | BreakerAirMagnetic | PI-1 | AMCB Readings | Amps C Ø | 65.0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0786 | BreakerAirMagnetic | PI-1 | AMCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0786 | BreakerAirMagnetic | PI-1 | AMCB Readings | Operations Counter AF | 99967 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0786 | BreakerAirMagnetic | PI-1 | AMCB Readings | Operations Counter AL | 99967 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0786 | BreakerAirMagnetic | PI-1 | AMCB Readings | Operations This Read AM | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0786 | BreakerAirMagnetic | PI-1 | AMCB Readings | Amps B Ø | 65.0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0786 | BreakerAirMagnetic | PI-1 | AMCB Readings | Switching Operations | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0786 | BreakerAirMagnetic | PI-1 | AMCB Readings | Unknown Operations | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0786 | BreakerAirMagnetic | PI-1 | AMCB Readings | Amps A Ø | 40.0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0786 | BreakerAirMagnetic | PI-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0786 | BreakerAirMagnetic | PI-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0786 | BreakerAirMagnetic | PI-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0786 | BreakerAirMagnetic | PI-1 | AMCB Readings | 9 Months Operations | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0786 | BreakerAirMagnetic | PI-1 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | BCH001225 | Charger | PI-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | BCH001225 | Charger | PI-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.7 | VDC |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | BCH001225 | Charger | PI-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.7 | VDC |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | BCH001225 | Charger | PI-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .7 | amps |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | BCH001225 | Charger | PI-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | BCH001225 | Charger | PI-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | BCH001225 | Charger | PI-Battery Charger | Battery Charger Patrol Insp | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | BCH001225 | Charger | PI-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | BAT001285 | Battery | PI-Battery Bank | Battery Patrol Inspection | Battery Bank Amps | .7 | AMPS |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | BAT001285 | Battery | PI-Battery Bank | Battery Patrol Inspection | Battery Bank Volts | 26.7 | VDC |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | BAT001285 | Battery | PI-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | BAT001285 | Battery | PI-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | BAT001285 | Battery | PI-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | BAT001285 | Battery | PI-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | BAT001285 | Battery | PI-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | BAT001285 | Battery | PI-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | BAT001285 | Battery | PI-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | BAT001285 | Battery | PI-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | BAT001285 | Battery | PI-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | BAT001285 | Battery | PI-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | BAT001285 | Battery | PI-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | BAT001285 | Battery | PI-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | BAT001285 | Battery | PI-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | BAT001285 | Battery | PI-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | FE000596 | Fence | PI-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | FE000596 | Fence | PI-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | FE000596 | Fence | PI-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | FE000596 | Fence | PI-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | FE000596 | Fence | PI-Fence | Fence Patrol Inspection | General Comments | Mangate lock not functioning properly. Lock is hard to operate | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | FE000596 | Fence | PI-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | FE000596 | Fence | PI-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | FE000596 | Fence | PI-Fence | Fence Patrol Inspection | Follow-up Action Required? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | FE000596 | Fence | PI-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | FE000596 | Fence | PI-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | FE000596 | Fence | PI-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | FE000596 | Fence | PI-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | FE000596 | Fence | PI-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | FE000596 | Fence | PI-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | FE000596 | Fence | PI-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | FE000596 | Fence | PI-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Readings | Fault Operations B Ø | 4 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Readings | Fault Operations A Ø | 4 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Readings | Fault Adjusted Amps B Phase V | 23.98 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Readings | Fault Adjusted Amps A Phase V | 23.98 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Readings | Amps A Ø | 115.0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Readings | Amps B Ø | 85.0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Readings | Amps C Ø | 130.0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Readings | Fault Adjusted Amps B Phase V | 29.97 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Readings | Amps C Ø | 180.0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Readings | Amps B Ø | 160.0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Readings | Amps A Ø | 165.0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | ST000369 | Structure | 633-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | ST000369 | Structure | 633-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | ST000369 | Structure | 633-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | ST000369 | Structure | 633-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | ST000369 | Structure | 633-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Readings | Unknown Operations | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Readings | Fault Operations B Ø | 5 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Readings | Switching Operations | 2 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Readings | Operations This Read Vac | 2 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Readings | Operations Counter AL | 261 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Readings | Operations Counter AF | 259 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Readings | General Comments | | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | ST000369 | Structure | 633-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | ST000369 | Structure | 633-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | ST000369 | Structure | 633-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | ST000369 | Structure | 633-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | ST000369 | Structure | 633-Structure | Structure Patrol Inspection | General Comments | | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | ST000369 | Structure | 633-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | ST000369 | Structure | 633-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | ST000369 | Structure | 633-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | ST000369 | Structure | 633-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | ST000369 | Structure | 633-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | ST000369 | Structure | 633-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | ST000369 | Structure | 633-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | ST000369 | Structure | 633-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | FE000898 | Fence | 738-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | FE000898 | Fence | 738-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | FE000898 | Fence | 738-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | FE000898 | Fence | 738-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | FE000898 | Fence | 738-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | ST000369 | Structure | 633-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | ST000369 | Structure | 633-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | FE000361 | Fence | 633-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | FE000361 | Fence | 633-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | FE000361 | Fence | 633-Fence | Fence Patrol Inspection | General Comments | | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | FE000361 | Fence | 633-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Readings | 9 Month Operations | 7 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | ST000369 | Structure | 633-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | ST000369 | Structure | 633-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | ST000369 | Structure | 633-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | FE000898 | Fence | 738-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Readings | Unknown Operations | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Readings | Switching Operations | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Readings | Operations This Read Vac | 8 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Readings | Operations Counter AL | 140 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Readings | Operations Counter AF | 140 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | FE000898 | Fence | 738-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | FE000898 | Fence | 738-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | FE000898 | Fence | 738-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Readings | 9 Month Operations | 10 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Readings | General Comments | | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001830 | BreakerVacuum | 633-0639 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Readings | Operations Counter AL | 301 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Readings | Operations Counter AF | 297 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Readings | General Comments | | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Readings | Amps C Ø | 20 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Readings | Amps B Ø | 20 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Readings | Amps A Ø | 20 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Readings | 9 Month Operations | 4 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Readings | 9 Month Operations | 4 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Readings | 9 Month Operations | 2 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Readings | Amps A Ø | 40.0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Readings | Amps B Ø | 45.0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Readings | Amps C Ø | 35.0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Readings | General Comments | | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Readings | General Comments | | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Readings | Operations Counter AF | 423 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Readings | Operations Counter AL | 423 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Readings | Operations This Read Vac | 5 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | FE000898 | Fence | 738-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | FE000898 | Fence | 738-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | FE000898 | Fence | 738-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | FE000898 | Fence | 738-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | FE000898 | Fence | 738-Fence | Fence Patrol Inspection | General Comments | | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | FE000898 | Fence | 738-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | FE000898 | Fence | 738-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Readings | Switching Operations | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001831 | BreakerVacuum | 633-0769 | VCB Readings | Unknown Operations | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | FE000361 | Fence | 633-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | FE000361 | Fence | 633-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | FE000361 | Fence | 633-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | FE000361 | Fence | 633-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | FE000361 | Fence | 633-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | FE000361 | Fence | 633-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | FE000361 | Fence | 633-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000865 | Fence | 608-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000865 | Fence | 608-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000865 | Fence | 608-Fence | Fence Patrol Inspection | General Comments | | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000865 | Fence | 608-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000865 | Fence | 608-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000865 | Fence | 608-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000865 | Fence | 608-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000865 | Fence | 608-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | FE000361 | Fence | 633-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | FE000361 | Fence | 633-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000865 | Fence | 608-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000865 | Fence | 608-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000865 | Fence | 608-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000865 | Fence | 608-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000865 | Fence | 608-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000865 | Fence | 608-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000865 | Fence | 608-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000865 | Fence | 608-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | FE000361 | Fence | 633-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | FE000361 | Fence | 633-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | LTCC000927 | LTCControl | 608-1 | LTC Control Insp | All Connections OK? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | LTCC000927 | LTCControl | 608-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | LTCC000927 | LTCControl | 608-1 | LTC Control Insp | General Comments | | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | LTCC000927 | LTCControl | 608-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | LTCC000927 | LTCControl | 608-1 | LTC Control Insp | LTC Output Voltage Level | 126 | VAC |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | LTCC000927 | LTCControl | 608-1 | LTC Control Insp | VRR Base Voltage AF | 125 | VAC |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | LTCC000927 | LTCControl | 608-1 | LTC Control Insp | VRR Base Voltage AL | 125 | VAC |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | LTCC000927 | LTCControl | 608-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | YD000367 | Yard | 633-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | YD000367 | Yard | 633-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | YD000367 | Yard | 633-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | YD000367 | Yard | 633-Yard | Yard Patrol Inspection | General Comments | | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | YD000367 | Yard | 633-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | YD000367 | Yard | 633-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | YD000367 | Yard | 633-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | YD000367 | Yard | 633-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | YD000367 | Yard | 633-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | YD000367 | Yard | 633-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | YD000367 | Yard | 633-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | YD000367 | Yard | 633-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | YD000367 | Yard | 633-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Readings | Unknown Operations | 0 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Readings | Switching Operations | 4 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0286 | BreakerVacuum | 594-2471 | VCB Readings | Operations This Read Vac | 4 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Readings | General Comments | | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Readings | Operations Counter AF | 170 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Readings | Operations Counter AL | 172 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Readings | Operations This Read Vac | 2 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Readings | Switching Operations | 2 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Readings | Unknown Operations | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BAT001463 | Battery | 633-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BAT001463 | Battery | 633-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 45 | °F |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BAT001463 | Battery | 633-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BAT001463 | Battery | 633-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BAT001463 | Battery | 633-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BAT001463 | Battery | 633-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BAT001463 | Battery | 633-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BAT001463 | Battery | 633-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BAT001463 | Battery | 633-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BAT001463 | Battery | 633-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BAT001463 | Battery | 633-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BAT001463 | Battery | 633-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BAT001463 | Battery | 633-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BAT001463 | Battery | 633-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BCH001400 | Charger | 633-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BCH001400 | Charger | 633-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BCH001400 | Charger | 633-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BCH001400 | Charger | 633-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.5 | amps |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BCH001400 | Charger | 633-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BCH001400 | Charger | 633-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BCH001400 | Charger | 633-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BCH001400 | Charger | 633-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | LTCMechanism | 594-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | LTCMechanism | 594-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Readings | LTC Totalizer Reading | 4458.24 | kw |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | BAT001190 | Battery | 608-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | BAT001190 | Battery | 608-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | BAT001190 | Battery | 608-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.1 | VDC |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | BAT001190 | Battery | 608-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27 | VDC |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | BAT001190 | Battery | 608-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | BAT001190 | Battery | 608-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | BAT001190 | Battery | 608-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | BAT001190 | Battery | 608-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | BAT001190 | Battery | 608-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | BAT001190 | Battery | 608-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | BAT001190 | Battery | 608-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | BAT001190 | Battery | 608-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | BAT001190 | Battery | 608-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 42 | °F |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | BAT001190 | Battery | 608-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Readings | Totalizer Meter Reading | .9288 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Readings | 9 Month Operations | 2 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Readings | Amps A Ø | 70.0 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Readings | Amps B Ø | 120.0 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Readings | Amps C Ø | 80.0 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001337 | BreakerVacuum | 175-0615 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Readings | Amps A Ø | 30.0 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Readings | Amps B Ø | 30.0 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Readings | Amps C Ø | 35.0 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | LTCC000380 | LTCControl | 175-5 | LTC Control Insp | All Connections OK? | y | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | LTCC000380 | LTCControl | 175-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | LTCC000380 | LTCControl | 175-5 | LTC Control Insp | General Comments | | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | LTCC000380 | LTCControl | 175-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | LTCC000380 | LTCControl | 175-5 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | LTCC000380 | LTCControl | 175-5 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | LTCC000380 | LTCControl | 175-5 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | LTCC000380 | LTCControl | 175-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Readings | Operations Counter AL | 187 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Readings | Operations Counter AF | 185 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | LTCC000385 | LTCControl | 738-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | LTCC000385 | LTCControl | 738-1 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | LTCC000385 | LTCControl | 738-1 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Readings | General Comments | | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | LTCC000385 | LTCControl | 738-1 | LTC Control Insp | LTC Output Voltage Level | 124.4 | VAC |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | LTCC000385 | LTCControl | 738-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | LTCC000385 | LTCControl | 738-1 | LTC Control Insp | General Comments | | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | LTCC000385 | LTCControl | 738-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | LTCC000385 | LTCControl | 738-1 | LTC Control Insp | All Connections OK? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | LTCMechanism | 594-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | LTCMechanism | 594-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | LTCMechanism | 594-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Readings | Unknown Operations | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Readings | Switching Operations | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Readings | Operations Counter AL | 202 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Readings | Operations Counter AF | 202 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Readings | 9 Month Operations | 2 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Readings | General Comments | | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Readings | Amps C Ø | 370.0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Readings | Amps B Ø | 305.0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Readings | Amps A Ø | 340.0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001462 | BreakerVacuum | 633-1 | VCB Readings | 9 Month Operations | 0 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Readings | Unknown Operations | 0 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Readings | Switching Operations | 2 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Readings | Operations This Read Vac | 2 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | BK001340 | BreakerVacuum | 175-0614 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | ST000534 | Structure | 738-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | ST000534 | Structure | 738-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | ST000534 | Structure | 738-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | ST000534 | Structure | 738-Structure | Structure Patrol Inspection | General Comments | | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | ST000534 | Structure | 738-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | ST000534 | Structure | 738-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | ST000534 | Structure | 738-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | ST000534 | Structure | 738-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | ST000534 | Structure | 738-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | ST000534 | Structure | 738-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | ST000534 | Structure | 738-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | ST000534 | Structure | 738-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | ST000534 | Structure | 738-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | ST000534 | Structure | 738-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | ST000534 | Structure | 738-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | ST000534 | Structure | 738-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | ST000534 | Structure | 738-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | LTCMechanism | 175-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | LTCMechanism | 175-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | LTCMechanism | 175-5 | LTC Counter Readings | General Comments | | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | LTCMechanism | 175-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | LTCMechanism | 175-5 | LTC Counter Readings | LTC As Found Counter | 30201 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | LTCMechanism | 175-5 | LTC Counter Readings | LTC As Left Counter | 30201 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | LTCMechanism | 175-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | LTCMechanism | 175-5 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | LTCMechanism | 175-5 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | LTCMechanism | 175-5 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | LTCMechanism | 175-5 | LTC Counter Readings | LTC Operations Since Last Insp | 507 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | LTCMechanism | 175-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | LTCMechanism | 175-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | LTCMechanism | 175-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0136 | RecloserElectronic | 738-2407 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0136 | RecloserElectronic | 738-2407 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0136 | RecloserElectronic | 738-2407 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0136 | RecloserElectronic | 738-2407 | Recloser Electronic Patrol Inspection | Operations Counter | 841 | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0136 | RecloserElectronic | 738-2407 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0136 | RecloserElectronic | 738-2407 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0136 | RecloserElectronic | 738-2407 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0136 | RecloserElectronic | 738-2407 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0136 | RecloserElectronic | 738-2407 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0136 | RecloserElectronic | 738-2407 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0136 | RecloserElectronic | 738-2407 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0136 | RecloserElectronic | 738-2407 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0136 | RecloserElectronic | 738-2407 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0136 | RecloserElectronic | 738-2407 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | YD000530 | Yard | 738-Yard | Yard Patrol Inspection | Ambient Temp | 40 | °F |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | YD000530 | Yard | 738-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | YD000530 | Yard | 738-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | YD000530 | Yard | 738-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | YD000530 | Yard | 738-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | YD000530 | Yard | 738-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | YD000530 | Yard | 738-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | YD000530 | Yard | 738-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | YD000530 | Yard | 738-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | YD000530 | Yard | 738-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | YD000530 | Yard | 738-Yard | Yard Patrol Inspection | General Comments | | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | YD000530 | Yard | 738-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | YD000530 | Yard | 738-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | YD000530 | Yard | 738-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | YD000530 | Yard | 738-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | YD000530 | Yard | 738-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | ST000534 | Structure | 738-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Readings | Amps C Ø | 25.0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Readings | Amps B Ø | 15.0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Readings | Amps A Ø | 25.0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001829 | BreakerVacuum | 633-0638 | VCB Readings | 9 Month Operations | 3 | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | ST000534 | Structure | 738-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | ST000534 | Structure | 738-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | ST000534 | Structure | 738-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | ST000534 | Structure | 738-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Readings | Totalizer Meter Reading | .9610 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Readings | Winding Temp Max | 50 | °C |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Readings | Winding Temp Present | 50 | °C |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | LTCC000710 | LTCControl | 633-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | LTCC000710 | LTCControl | 633-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | LTCC000710 | LTCControl | 633-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | LTCC000710 | LTCControl | 633-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | LTCC000710 | LTCControl | 633-1 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | LTCC000710 | LTCControl | 633-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | LTCC000710 | LTCControl | 633-1 | LTC Control Insp | General Comments | | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | LTCC000710 | LTCControl | 633-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | LTCC000710 | LTCControl | 633-1 | LTC Control Insp | All Connections OK? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Readings | General Comments | | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | O0186 | WithLTC | 594-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0136 | RecloserElectronic | 738-2407 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0136 | RecloserElectronic | 738-2407 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0136 | RecloserElectronic | 738-2407 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0136 | RecloserElectronic | 738-2407 | Recloser Electronic Patrol Inspection | Amps C Ø | 50 | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0136 | RecloserElectronic | 738-2407 | Recloser Electronic Patrol Inspection | Amps B Ø | 50 | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0136 | RecloserElectronic | 738-2407 | Recloser Electronic Patrol Inspection | Amps A Ø | 40 | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0130 | RecloserElectronic | 738-2408 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0130 | RecloserElectronic | 738-2408 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0130 | RecloserElectronic | 738-2408 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0130 | RecloserElectronic | 738-2408 | Recloser Electronic Patrol Inspection | Operations Counter | 1799 | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0130 | RecloserElectronic | 738-2408 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0130 | RecloserElectronic | 738-2408 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0130 | RecloserElectronic | 738-2408 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0130 | RecloserElectronic | 738-2408 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0130 | RecloserElectronic | 738-2408 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0130 | RecloserElectronic | 738-2408 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0130 | RecloserElectronic | 738-2408 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0130 | RecloserElectronic | 738-2408 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0130 | RecloserElectronic | 738-2408 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0130 | RecloserElectronic | 738-2408 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0130 | RecloserElectronic | 738-2408 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0130 | RecloserElectronic | 738-2408 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0130 | RecloserElectronic | 738-2408 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0130 | RecloserElectronic | 738-2408 | Recloser Electronic Patrol Inspection | Amps C Ø | 50 | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0130 | RecloserElectronic | 738-2408 | Recloser Electronic Patrol Inspection | Amps B Ø | 50 | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0130 | RecloserElectronic | 738-2408 | Recloser Electronic Patrol Inspection | Amps A Ø | 50 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Readings | General Comments | | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Readings | LTC Totalizer Reading | 13838.40 | kw |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | WithLTC | 633-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Readings | Operations Counter AL | 2050 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Readings | Operations This Read Vac | 4 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Readings | Switching Operations | 4 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Readings | Unknown Operations | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | LTCMechanism | 633-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | LTCMechanism | 633-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | LTCMechanism | 633-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | LTCMechanism | 633-1 | LTC Counter Readings | LTC Operations Since Last Insp | 685 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | LTCMechanism | 633-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | LTCMechanism | 633-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | LTCMechanism | 633-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | LTCMechanism | 633-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | LTCMechanism | 633-1 | LTC Counter Readings | LTC As Left Counter | 18636 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | LTCMechanism | 633-1 | LTC Counter Readings | LTC As Found Counter | 18636 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | LTCMechanism | 633-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | LTCMechanism | 633-1 | LTC Counter Readings | General Comments | | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | LTCMechanism | 633-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | B0386 | LTCMechanism | 633-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000483 | Fence | 608-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | ST000541 | Structure | 594-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | YD000537 | Yard | 594-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | BAT001233 | Battery | 594-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | ST000541 | Structure | 594-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | ST000541 | Structure | 594-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | ST000541 | Structure | 594-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | BAT001233 | Battery | 594-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | BAT001233 | Battery | 594-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0 | VDC |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | BAT001233 | Battery | 594-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0 | VDC |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | BAT001233 | Battery | 594-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | BAT001233 | Battery | 594-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | BAT001233 | Battery | 594-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | BAT001233 | Battery | 594-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | BAT001233 | Battery | 594-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | BAT001233 | Battery | 594-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | BAT001233 | Battery | 594-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | LTCC000716 | LTCControl | 594-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | LTCC000716 | LTCControl | 594-1 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | LTCC000716 | LTCControl | 594-1 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | LTCC000716 | LTCControl | 594-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | ST000489 | Structure | 608-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | ST000489 | Structure | 608-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | BCH001370 | Charger | 608-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | FE000532 | Fence | 594-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | FE000532 | Fence | 594-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | FE000532 | Fence | 594-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | FE000532 | Fence | 594-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | FE000532 | Fence | 594-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | FE000532 | Fence | 594-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | FE000532 | Fence | 594-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | FE000532 | Fence | 594-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | FE000532 | Fence | 594-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | FE000532 | Fence | 594-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | BCH001370 | Charger | 608-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | BCH001370 | Charger | 608-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | BCH001370 | Charger | 608-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | BCH001370 | Charger | 608-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 0 | amps |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | BCH001370 | Charger | 608-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | BCH001370 | Charger | 608-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | BCH001370 | Charger | 608-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0 | millivolts |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | FE000532 | Fence | 594-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | FE000532 | Fence | 594-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | FE000532 | Fence | 594-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | ST000489 | Structure | 608-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | ST000489 | Structure | 608-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | YD000537 | Yard | 594-Yard | Yard Patrol Inspection | Ambient Temp | 44 | °F |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | YD000537 | Yard | 594-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Readings | Unknown Operations | 0 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Readings | General Comments | | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Readings | Switching Operations | 5 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Readings | Operations This Read Vac | 5 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Readings | Operations Counter AL | 250 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Readings | Operations Counter AF | 245 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | FE000532 | Fence | 594-Fence | Fence Patrol Inspection | General Comments | | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Readings | General Comments | | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | FE000532 | Fence | 594-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | FE000532 | Fence | 594-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Readings | Operations Counter AF | 2046 | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Readings | General Comments | | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Readings | LTC Totalizer Reading | 5447.52 | kw |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | ST000541 | Structure | 594-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | ST000541 | Structure | 594-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | ST000541 | Structure | 594-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | ST000541 | Structure | 594-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Readings | Oil Temp Max | 36 | °C |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Readings | Amps B Ø | 120 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Readings | Amps A Ø | 240 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Readings | Accumulated Fault Duty C Ph V | 13.45 | % |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Readings | Accumulated Fault Duty B Ph V | 5.38 | % |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Readings | Accumulated Fault Duty A Ph V | 4.04 | % |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.0548 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Readings | 9 Month Operations | 5 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | BCH001180 | Charger | 594-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0 | millivolts |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | BCH001180 | Charger | 594-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | BCH001180 | Charger | 594-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | BCH001180 | Charger | 594-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 0 | amps |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | BCH001180 | Charger | 594-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | BAT001233 | Battery | 594-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 44 | °F |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | BCH001180 | Charger | 594-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | BAT001233 | Battery | 594-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | YD000537 | Yard | 594-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | YD000537 | Yard | 594-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | YD000537 | Yard | 594-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | BCH001180 | Charger | 594-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | YD000537 | Yard | 594-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | YD000537 | Yard | 594-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Readings | Totalizer Meter Reading | .7566 | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Readings | Winding Temp Max | 34 | °C |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Readings | Winding Temp Present | 20 | °C |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | YD000537 | Yard | 594-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | YD000537 | Yard | 594-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | YD000537 | Yard | 594-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | YD000537 | Yard | 594-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | YD000537 | Yard | 594-Yard | Yard Patrol Inspection | General Comments | | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | YD000537 | Yard | 594-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | YD000537 | Yard | 594-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | LTCC000716 | LTCControl | 594-1 | LTC Control Insp | LTC Output Voltage Level | 124.9 | VAC |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | LTCC000716 | LTCControl | 594-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | LTCC000716 | LTCControl | 594-1 | LTC Control Insp | General Comments | | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | LTCC000716 | LTCControl | 594-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | LTCC000716 | LTCControl | 594-1 | LTC Control Insp | All Connections OK? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Readings | General Comments | | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Readings | LTC Totalizer Reading | 3375.36 | kw |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | BAT001233 | Battery | 594-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | BAT001233 | Battery | 594-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | K0107 | BreakerVacuum | 608-2459 | VCB Readings | Amps C Ø | 180 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | ST000541 | Structure | 594-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | LTCMechanism | 738-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | LTCMechanism | 738-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | LTCMechanism | 738-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | LTCMechanism | 738-1 | LTC Counter Readings | LTC Operations Since Last Insp | 358 | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | LTCMechanism | 738-1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | LTCMechanism | 738-1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | LTCMechanism | 738-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | LTCMechanism | 738-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | LTCMechanism | 738-1 | LTC Counter Readings | LTC As Left Counter | 39469 | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | LTCMechanism | 738-1 | LTC Counter Readings | LTC As Found Counter | 39467 | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | LTCMechanism | 738-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | LTCMechanism | 738-1 | LTC Counter Readings | General Comments | | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | LTCMechanism | 738-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | LTCMechanism | 738-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | ST000541 | Structure | 594-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | ST000541 | Structure | 594-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | ST000541 | Structure | 594-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | ST000541 | Structure | 594-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | ST000541 | Structure | 594-Structure | Structure Patrol Inspection | General Comments | | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | ST000541 | Structure | 594-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | ST000541 | Structure | 594-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | WithLTC | 608-1 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Readings | Operations This Read Vac | 4 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Readings | Operations Counter AL | 315 | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | ST000541 | Structure | 594-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | ST000541 | Structure | 594-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | ST000541 | Structure | 594-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | ST000541 | Structure | 594-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | ST000541 | Structure | 594-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | ST000541 | Structure | 594-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | S0061 | WithLTC | 738-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Readings | Amps C Ø | 100 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Readings | Amps B Ø | 100 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | ST000489 | Structure | 608-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | ST000489 | Structure | 608-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | ST000489 | Structure | 608-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | ST000489 | Structure | 608-Structure | Structure Patrol Inspection | General Comments | | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | ST000489 | Structure | 608-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | ST000489 | Structure | 608-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Readings | Switching Operations | 4 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | ST000489 | Structure | 608-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | ST000489 | Structure | 608-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | LTCMechanism | 608-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | LTCMechanism | 608-1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | LTCMechanism | 608-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | LTCMechanism | 608-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | LTCMechanism | 608-1 | LTC Counter Readings | LTC As Left Counter | 259569 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | LTCMechanism | 608-1 | LTC Counter Readings | LTC As Found Counter | 259567 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | LTCMechanism | 608-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | LTCMechanism | 608-1 | LTC Counter Readings | General Comments | | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | LTCMechanism | 608-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | LTCMechanism | 608-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | ST000489 | Structure | 608-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | ST000489 | Structure | 608-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | ST000489 | Structure | 608-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | ST000489 | Structure | 608-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | ST000489 | Structure | 608-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Readings | Amps A Ø | 100 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0128 | RecloserElectronic | 738-2406 | Recloser Electronic Patrol Inspection | Amps A Ø | 50 | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0128 | RecloserElectronic | 738-2406 | Recloser Electronic Patrol Inspection | Amps B Ø | 50 | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0128 | RecloserElectronic | 738-2406 | Recloser Electronic Patrol Inspection | Amps C Ø | 45 | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0128 | RecloserElectronic | 738-2406 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Readings | Operations Counter AF | 311 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Readings | General Comments | | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Readings | LTC Totalizer Reading | 2262.24 | kw |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Readings | Oil Temp Present | 40 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Readings | Totalizer Meter Reading | .3142 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/15/2023 7:14 | Distribution | Farmers Quarterly Inspection | C0432 | WithLTC | 175-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Readings | General Comments | | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Readings | Operations Counter AF | 166 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Readings | Operations Counter AL | 168 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Readings | Operations This Read Vac | 2 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Readings | Switching Operations | 2 | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 13:25 | Distribution | Boone Avenue Quarterly Inspection | BK001398 | BreakerVacuum | 633-0640 | VCB Readings | Unknown Operations | 0 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | LTCMechanism | 608-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | LTCMechanism | 608-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | LTCMechanism | 608-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | LTCMechanism | 608-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | C0393 | LTCMechanism | 608-1 | LTC Counter Readings | LTC Operations Since Last Insp | 305 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Readings | Unknown Operations | 0 | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000483 | Fence | 608-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000483 | Fence | 608-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000483 | Fence | 608-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/15/2023 15:03 | Distribution | Radcliff South Quarterly Inspection | CB0285 | BreakerVacuum | 594-2470 | VCB Readings | 9 Month Operations | 4 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000483 | Fence | 608-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000483 | Fence | 608-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000483 | Fence | 608-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000483 | Fence | 608-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000483 | Fence | 608-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000483 | Fence | 608-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000483 | Fence | 608-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | ST000489 | Structure | 608-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | ST000489 | Structure | 608-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | ST000489 | Structure | 608-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | ST000489 | Structure | 608-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000483 | Fence | 608-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000483 | Fence | 608-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000483 | Fence | 608-Fence | Fence Patrol Inspection | General Comments | | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000483 | Fence | 608-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | FE000483 | Fence | 608-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | YD000488 | Yard | 608-Yard | Yard Patrol Inspection | Ambient Temp | 42 | °F |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | YD000488 | Yard | 608-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | YD000488 | Yard | 608-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | YD000488 | Yard | 608-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | YD000488 | Yard | 608-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | YD000488 | Yard | 608-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | YD000488 | Yard | 608-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | YD000488 | Yard | 608-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | YD000488 | Yard | 608-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | YD000488 | Yard | 608-Yard | Yard Patrol Inspection | General Comments | | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | YD000488 | Yard | 608-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | YD000488 | Yard | 608-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | YD000488 | Yard | 608-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0128 | RecloserElectronic | 738-2406 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0128 | RecloserElectronic | 738-2406 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0128 | RecloserElectronic | 738-2406 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0128 | RecloserElectronic | 738-2406 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0128 | RecloserElectronic | 738-2406 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0128 | RecloserElectronic | 738-2406 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0128 | RecloserElectronic | 738-2406 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0128 | RecloserElectronic | 738-2406 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0128 | RecloserElectronic | 738-2406 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0128 | RecloserElectronic | 738-2406 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0128 | RecloserElectronic | 738-2406 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Readings | Amps C Ø | 120 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Readings | Amps B Ø | 120 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Readings | Amps A Ø | 120 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0128 | RecloserElectronic | 738-2406 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0128 | RecloserElectronic | 738-2406 | Recloser Electronic Patrol Inspection | Operations Counter | 1468 | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0128 | RecloserElectronic | 738-2406 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0128 | RecloserElectronic | 738-2406 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/15/2023 10:02 | Distribution | Eastview Quarterly Inspection | CX0128 | RecloserElectronic | 738-2406 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | YD000488 | Yard | 608-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Readings | Accumulated Fault Duty A Ph V | 1.43 | % |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | CB0139 | BreakerVacuum | 608-2460 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | ST000489 | Structure | 608-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | ST000489 | Structure | 608-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | ST000489 | Structure | 608-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/15/2023 14:01 | Distribution | Vine Grove Quarterly Inspection | YD000488 | Yard | 608-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BCH001345 | Charger | 301-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 2.500 | millivolts |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BCH001345 | Charger | 301-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BCH001345 | Charger | 301-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BCH001345 | Charger | 301-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.6 | amps |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BCH001345 | Charger | 301-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BCH001345 | Charger | 301-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BCH001345 | Charger | 301-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BCH001345 | Charger | 301-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BAT001494 | Battery | 301-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BAT001494 | Battery | 301-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BAT001494 | Battery | 301-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.1 | VDC |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BAT001494 | Battery | 301-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BAT001494 | Battery | 301-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BAT001494 | Battery | 301-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BAT001494 | Battery | 301-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BAT001494 | Battery | 301-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.3 | VDC |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BAT001494 | Battery | 301-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BAT001494 | Battery | 301-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BAT001494 | Battery | 301-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BAT001494 | Battery | 301-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BAT001494 | Battery | 301-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | CH000013 | ControlHouse | 301-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | CH000013 | ControlHouse | 301-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | CH000013 | ControlHouse | 301-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | CH000013 | ControlHouse | 301-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | CH000013 | ControlHouse | 301-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | CH000013 | ControlHouse | 301-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | CH000013 | ControlHouse | 301-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | CH000013 | ControlHouse | 301-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | CH000013 | ControlHouse | 301-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | CH000013 | ControlHouse | 301-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | CH000013 | ControlHouse | 301-Control House | Control House Patrol Inspection | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | CH000013 | ControlHouse | 301-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | CH000013 | ControlHouse | 301-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | CH000013 | ControlHouse | 301-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | CH000013 | ControlHouse | 301-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Readings | 9 Month Operations | 2 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Readings | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Readings | Operations Counter AF | 202 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Readings | Operations Counter AL | 202 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Readings | Amps C Ø | 199.0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Readings | Amps B Ø | 116.0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Readings | Amps A Ø | 149.0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001592 | BreakerVacuum | 301-4704 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Readings | Amps A Ø | 129.0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Readings | 9 Month Operations | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Readings | Amps B Ø | 112.0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Readings | Amps C Ø | 122.0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Readings | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Readings | Operations Counter AL | 174 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001583 | BreakerVacuum | 301-4703 | VCB Readings | Operations Counter AF | 174 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | LTCC000727 | LTCControl | 301-3 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | LTCC000727 | LTCControl | 301-3 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | LTCC000727 | LTCControl | 301-3 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | LTCC000727 | LTCControl | 301-3 | LTC Control Insp | LTC Output Voltage Level | 124.8 | VAC |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | LTCC000727 | LTCControl | 301-3 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | LTCC000727 | LTCControl | 301-3 | LTC Control Insp | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | LTCC000727 | LTCControl | 301-3 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | LTCC000727 | LTCControl | 301-3 | LTC Control Insp | VRR Time Delay | 45 | Seconds |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | LTCC000727 | LTCControl | 301-3 | LTC Control Insp | All Connections OK? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | LTCMechanism | 301-3 | LTC Counter Readings | LTC As Left Counter | 24630 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | LTCMechanism | 301-3 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | LTCMechanism | 301-3 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | LTCMechanism | 301-3 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | LTCMechanism | 301-3 | LTC Counter Readings | LTC Operations Since Last Insp | 659 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | LTCMechanism | 301-3 | LTC Counter Readings | LTC As Found Counter | 24628 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | LTCMechanism | 301-3 | LTC Counter Readings | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | LTCMechanism | 301-3 | LTC Counter Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | LTCMechanism | 301-3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | LTCMechanism | 301-3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | LTCMechanism | 301-3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Low | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | LTCMechanism | 301-3 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | LTCMechanism | 301-3 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | LTCMechanism | 301-3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | LTCMechanism | 301-3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | LTCMechanism | 301-3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Readings | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Readings | Totalizer Meter Reading | .9480 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Readings | LTC Totalizer Reading | 6825.60 | kw |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | B0337 | WithLTC | 301-3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Readings | Amps C Ø | 241.0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Readings | Amps B Ø | 184.0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Readings | Amps A Ø | 172.0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Readings | 9 Month Operations | 1 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Readings | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Readings | Operations Counter AF | 264 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Readings | Operations Counter AL | 264 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000291 | BreakerVacuum | 301-4702 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | LTCC000698 | LTCControl | 301-2 | LTC Control Insp | All Connections OK? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | LTCC000698 | LTCControl | 301-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | LTCC000698 | LTCControl | 301-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | LTCC000698 | LTCControl | 301-2 | LTC Control Insp | LTC Output Voltage Level | 124.8 | VAC |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | LTCC000698 | LTCControl | 301-2 | LTC Control Insp | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | LTCC000698 | LTCControl | 301-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | LTCC000698 | LTCControl | 301-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | LTCC000698 | LTCControl | 301-2 | LTC Control Insp | VRR Time Delay | 45 | Seconds |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | LTCMechanism | 301-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | LTCMechanism | 301-2 | LTC Counter Readings | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | LTCMechanism | 301-2 | LTC Counter Readings | LTC As Found Counter | 22251 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | LTCMechanism | 301-2 | LTC Counter Readings | LTC As Left Counter | 22253 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | LTCMechanism | 301-2 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | LTCMechanism | 301-2 | LTC Counter Readings | LTC Max Tap Position | 5R | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | LTCMechanism | 301-2 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | LTCMechanism | 301-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | LTCMechanism | 301-2 | LTC Counter Readings | LTC Operations Since Last Insp | 663 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | LTCMechanism | 301-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | LTCMechanism | 301-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | LTCMechanism | 301-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | LTCMechanism | 301-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | LTCMechanism | 301-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Readings | LTC Totalizer Reading | 4989.60 | kw |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Readings | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Readings | Totalizer Meter Reading | .6930 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Readings | Oil Temp Present | 33 | °C |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Readings | Oil Temp Max | 52 | °C |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0228 | WithLTC | 301-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Readings | Operations Counter AF | 213 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Readings | 9 Month Operations | 9 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Readings | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Readings | Amps B Ø | 144.0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Readings | Amps C Ø | 134.0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Readings | Operations Counter AL | 213 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Readings | Amps A Ø | 105.0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK001582 | BreakerVacuum | 301-4701 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Readings | Amps A Ø | 95.0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Readings | Amps B Ø | 92.0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Readings | 9 Month Operations | 1 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Readings | Amps C Ø | 88.0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Readings | Fault Operations Ground | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Readings | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Readings | Operations Counter AF | 201 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Readings | Operations Counter AL | 201 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Readings | Operations This Read Vac | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Readings | Switching Operations | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | BK000491 | BreakerVacuum | 301-4700 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | LTCC000990 | LTCControl | 301-1 | LTC Control Insp | LTC Output Voltage Level | 124.8 | VAC |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | LTCC000990 | LTCControl | 301-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | LTCC000990 | LTCControl | 301-1 | LTC Control Insp | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | LTCC000990 | LTCControl | 301-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | LTCC000990 | LTCControl | 301-1 | LTC Control Insp | All Connections OK? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | LTCC000990 | LTCControl | 301-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | LTCC000990 | LTCControl | 301-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | LTCC000990 | LTCControl | 301-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | LTCC000990 | LTCControl | 301-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | LTCMechanism | 301-1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | LTCMechanism | 301-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | LTCMechanism | 301-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | LTCMechanism | 301-1 | LTC Counter Readings | LTC As Left Counter | 78578 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | LTCMechanism | 301-1 | LTC Counter Readings | LTC Operations Since Last Insp | 502 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | LTCMechanism | 301-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | LTCMechanism | 301-1 | LTC Counter Readings | LTC As Found Counter | 78575 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | LTCMechanism | 301-1 | LTC Counter Readings | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | LTCMechanism | 301-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | LTCMechanism | 301-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | LTCMechanism | 301-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | LTCMechanism | 301-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | LTCMechanism | 301-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | LTCMechanism | 301-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Readings | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Readings | LTC Totalizer Reading | 4993.92 | kw |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Readings | Oil Temp Max | 38 | °C |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Readings | Oil Temp Present | 22 | °C |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Readings | Totalizer Meter Reading | .5202 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | O0233 | WithLTC | 301-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | ST000064 | Structure | 301-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | ST000064 | Structure | 301-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | ST000064 | Structure | 301-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | ST000064 | Structure | 301-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | ST000064 | Structure | 301-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | ST000064 | Structure | 301-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | ST000064 | Structure | 301-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | ST000064 | Structure | 301-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | ST000064 | Structure | 301-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | ST000064 | Structure | 301-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | ST000064 | Structure | 301-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | ST000064 | Structure | 301-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | ST000064 | Structure | 301-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | ST000064 | Structure | 301-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | ST000064 | Structure | 301-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | ST000064 | Structure | 301-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | ST000064 | Structure | 301-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | ST000064 | Structure | 301-Structure | Structure Patrol Inspection | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | ST000064 | Structure | 301-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | ST000064 | Structure | 301-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | ST000064 | Structure | 301-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | ST000064 | Structure | 301-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | FE000059 | Fence | 301-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | FE000059 | Fence | 301-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | FE000059 | Fence | 301-Fence | Fence Patrol Inspection | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | FE000059 | Fence | 301-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | FE000059 | Fence | 301-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | FE000059 | Fence | 301-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | FE000059 | Fence | 301-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | FE000059 | Fence | 301-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | FE000059 | Fence | 301-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | FE000059 | Fence | 301-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | FE000059 | Fence | 301-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | FE000059 | Fence | 301-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | FE000059 | Fence | 301-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | FE000059 | Fence | 301-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | FE000059 | Fence | 301-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | FE000059 | Fence | 301-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | YD000059 | Yard | 301-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | YD000059 | Yard | 301-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | YD000059 | Yard | 301-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | YD000059 | Yard | 301-Yard | Yard Patrol Inspection | General Comments | | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | YD000059 | Yard | 301-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | YD000059 | Yard | 301-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | YD000059 | Yard | 301-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | YD000059 | Yard | 301-Yard | Yard Patrol Inspection | Ambient Temp | 27 | °F |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | YD000059 | Yard | 301-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | YD000059 | Yard | 301-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | YD000059 | Yard | 301-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | YD000059 | Yard | 301-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/16/2023 7:34 | Distribution | Big Stone Gap Quarterly Inspection | YD000059 | Yard | 301-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | 0938 | NonLTC | 341-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | 0938 | NonLTC | 341-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | 0938 | NonLTC | 341-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | 0938 | NonLTC | 341-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | 0938 | NonLTC | 341-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | 0938 | NonLTC | 341-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | 0938 | NonLTC | 341-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | 0938 | NonLTC | 341-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | 0938 | NonLTC | 341-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | 0938 | NonLTC | 341-1 | NonLTC Transformer Patrol Inspection | General Comments | Oil seeping at the DETC | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | 0938 | NonLTC | 341-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | 0938 | NonLTC | 341-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | 0938 | NonLTC | 341-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | 0938 | NonLTC | 341-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | 0938 | NonLTC | 341-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | 0938 | NonLTC | 341-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | 0938 | NonLTC | 341-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | Seeping | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1125 | Regulator | 341-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.6 | volts |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1125 | Regulator | 341-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1125 | Regulator | 341-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1125 | Regulator | 341-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1125 | Regulator | 341-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1125 | Regulator | 341-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1125 | Regulator | 341-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 81826 | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1125 | Regulator | 341-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1125 | Regulator | 341-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1125 | Regulator | 341-1 C | Regulator Patrol Inspection | General Comments | | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1125 | Regulator | 341-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1125 | Regulator | 341-1 C | Regulator Patrol Inspection | Max Tap Position | 9R | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1125 | Regulator | 341-1 C | Regulator Patrol Inspection | Min Tap Position | 3L | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1125 | Regulator | 341-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1125 | Regulator | 341-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1125 | Regulator | 341-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1125 | Regulator | 341-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1125 | Regulator | 341-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1125 | Regulator | 341-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1125 | Regulator | 341-1 C | Regulator Patrol Inspection | Current Tap Position | 3R | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1125 | Regulator | 341-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1125 | Regulator | 341-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1125 | Regulator | 341-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1125 | Regulator | 341-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1111 | Regulator | 341-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1111 | Regulator | 341-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.5 | volts |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1111 | Regulator | 341-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1111 | Regulator | 341-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1111 | Regulator | 341-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1111 | Regulator | 341-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1111 | Regulator | 341-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 209126 | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1111 | Regulator | 341-1 B | Regulator Patrol Inspection | Current Tap Position | 2R | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1111 | Regulator | 341-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1111 | Regulator | 341-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1111 | Regulator | 341-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1111 | Regulator | 341-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1111 | Regulator | 341-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1111 | Regulator | 341-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1111 | Regulator | 341-1 B | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1111 | Regulator | 341-1 B | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1111 | Regulator | 341-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1111 | Regulator | 341-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1111 | Regulator | 341-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1111 | Regulator | 341-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1111 | Regulator | 341-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1111 | Regulator | 341-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1111 | Regulator | 341-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1111 | Regulator | 341-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1110 | Regulator | 341-1 A | Regulator Patrol Inspection | Max Tap Position | 9R | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1110 | Regulator | 341-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1110 | Regulator | 341-1 A | Regulator Patrol Inspection | General Comments | | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1110 | Regulator | 341-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1110 | Regulator | 341-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1110 | Regulator | 341-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1110 | Regulator | 341-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1110 | Regulator | 341-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1110 | Regulator | 341-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1110 | Regulator | 341-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1110 | Regulator | 341-1 A | Regulator Patrol Inspection | Current Tap Position | 3R | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1110 | Regulator | 341-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1110 | Regulator | 341-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1110 | Regulator | 341-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1110 | Regulator | 341-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1110 | Regulator | 341-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1110 | Regulator | 341-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1110 | Regulator | 341-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 213381 | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1110 | Regulator | 341-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1110 | Regulator | 341-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1110 | Regulator | 341-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1110 | Regulator | 341-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1110 | Regulator | 341-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | R1110 | Regulator | 341-1 A | Regulator Patrol Inspection | Min Tap Position | 4L | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | KX0151 | RecloserElectronic | 341-0743 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | KX0151 | RecloserElectronic | 341-0743 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | KX0151 | RecloserElectronic | 341-0743 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | KX0151 | RecloserElectronic | 341-0743 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | KX0151 | RecloserElectronic | 341-0743 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | KX0151 | RecloserElectronic | 341-0743 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | KX0151 | RecloserElectronic | 341-0743 | Recloser Electronic Patrol Inspection | Operations Counter | 63 | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | KX0151 | RecloserElectronic | 341-0743 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | KX0151 | RecloserElectronic | 341-0743 | Recloser Electronic Patrol Inspection | Amps B Ø | 52.0 | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | KX0151 | RecloserElectronic | 341-0743 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | KX0151 | RecloserElectronic | 341-0743 | Recloser Electronic Patrol Inspection | Amps A Ø | 50.0 | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | KX0151 | RecloserElectronic | 341-0743 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | KX0151 | RecloserElectronic | 341-0743 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | KX0151 | RecloserElectronic | 341-0743 | Recloser Electronic Patrol Inspection | Amps C Ø | 38.0 | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | KX0151 | RecloserElectronic | 341-0743 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | KX0151 | RecloserElectronic | 341-0743 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | KX0151 | RecloserElectronic | 341-0743 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | KX0151 | RecloserElectronic | 341-0743 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | KX0151 | RecloserElectronic | 341-0743 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | KX0151 | RecloserElectronic | 341-0743 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | 0938 | NonLTC | 341-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | 0938 | NonLTC | 341-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .2346 | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | 0938 | NonLTC | 341-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | 0938 | NonLTC | 341-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1600 | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | 0938 | NonLTC | 341-1 | NonLTC Transformer Readings | Oil Temp Present | 15 | °C |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | 0938 | NonLTC | 341-1 | NonLTC Transformer Readings | Oil Temp Max | 15 | °C |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | 0938 | NonLTC | 341-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | 0938 | NonLTC | 341-1 | NonLTC Transformer Readings | General Comments | | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | 0938 | NonLTC | 341-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 375.36 | kw |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | 0938 | NonLTC | 341-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | ST000104 | Structure | 341-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | ST000104 | Structure | 341-Structure | Structure Patrol Inspection | General Comments | | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | ST000104 | Structure | 341-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | ST000104 | Structure | 341-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | ST000104 | Structure | 341-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | ST000104 | Structure | 341-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | ST000104 | Structure | 341-Structure | Structure Patrol Inspection | Interruptrs/Puffrs Visual OK? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | ST000104 | Structure | 341-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | ST000104 | Structure | 341-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | ST000104 | Structure | 341-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | ST000104 | Structure | 341-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | ST000104 | Structure | 341-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | ST000104 | Structure | 341-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | ST000104 | Structure | 341-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | ST000104 | Structure | 341-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | ST000104 | Structure | 341-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | ST000104 | Structure | 341-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | ST000104 | Structure | 341-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | ST000104 | Structure | 341-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | ST000104 | Structure | 341-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | ST000104 | Structure | 341-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | FE000098 | Fence | 341-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | FE000098 | Fence | 341-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | FE000098 | Fence | 341-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | FE000098 | Fence | 341-Fence | Fence Patrol Inspection | General Comments | | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | FE000098 | Fence | 341-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | FE000098 | Fence | 341-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | FE000098 | Fence | 341-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | FE000098 | Fence | 341-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | FE000098 | Fence | 341-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | FE000098 | Fence | 341-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | FE000098 | Fence | 341-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | FE000098 | Fence | 341-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | FE000098 | Fence | 341-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | FE000098 | Fence | 341-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | FE000098 | Fence | 341-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | FE000098 | Fence | 341-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | YD000098 | Yard | 341-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | YD000098 | Yard | 341-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | YD000098 | Yard | 341-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | YD000098 | Yard | 341-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | YD000098 | Yard | 341-Yard | Yard Patrol Inspection | General Comments | | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | YD000098 | Yard | 341-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | YD000098 | Yard | 341-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | YD000098 | Yard | 341-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | YD000098 | Yard | 341-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | YD000098 | Yard | 341-Yard | Yard Patrol Inspection | Ambient Temp | 27 | °F |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | YD000098 | Yard | 341-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | YD000098 | Yard | 341-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/14/2023 12:31 | Distribution | Exeter Quarterly Inspection | YD000098 | Yard | 341-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | B0233 | NonLTC | 318-1 | NonLTC Transformer Readings | Oil Temp Present | 14 | °C |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | B0233 | NonLTC | 318-1 | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | B0233 | NonLTC | 318-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | B0233 | NonLTC | 318-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | B0233 | NonLTC | 318-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | B0233 | NonLTC | 318-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 397.20 | kw |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | B0233 | NonLTC | 318-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | B0233 | NonLTC | 318-1 | NonLTC Transformer Readings | General Comments | | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | B0233 | NonLTC | 318-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 400 | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | B0233 | NonLTC | 318-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .9930 | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | MX0455 | RecloserHydraulic | 318-0738 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | MX0455 | RecloserHydraulic | 318-0738 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | MX0455 | RecloserHydraulic | 318-0738 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | MX0455 | RecloserHydraulic | 318-0738 | Recloser Hydraulic Patrol Inspection | Operations Counter | 465 | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | MX0455 | RecloserHydraulic | 318-0738 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | MX0455 | RecloserHydraulic | 318-0738 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 39.4 | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | MX0455 | RecloserHydraulic | 318-0738 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | MX0455 | RecloserHydraulic | 318-0738 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | MX0455 | RecloserHydraulic | 318-0738 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | MX0455 | RecloserHydraulic | 318-0738 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | MX0455 | RecloserHydraulic | 318-0738 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 43.7 | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | MX0455 | RecloserHydraulic | 318-0738 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | MX0455 | RecloserHydraulic | 318-0738 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 65.2 | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | B0233 | NonLTC | 318-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | B0233 | NonLTC | 318-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | B0233 | NonLTC | 318-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | B0233 | NonLTC | 318-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | B0233 | NonLTC | 318-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | B0233 | NonLTC | 318-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | B0233 | NonLTC | 318-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | B0233 | NonLTC | 318-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | B0233 | NonLTC | 318-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | B0233 | NonLTC | 318-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | B0233 | NonLTC | 318-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | B0233 | NonLTC | 318-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | B0233 | NonLTC | 318-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | B0233 | NonLTC | 318-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | B0233 | NonLTC | 318-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | B0233 | NonLTC | 318-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | B0233 | NonLTC | 318-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0992 | Regulator | 318-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0992 | Regulator | 318-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0992 | Regulator | 318-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0992 | Regulator | 318-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0992 | Regulator | 318-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0992 | Regulator | 318-1 C | Regulator Patrol Inspection | Current Tap Position | 2R | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0992 | Regulator | 318-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0992 | Regulator | 318-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0992 | Regulator | 318-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0992 | Regulator | 318-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0992 | Regulator | 318-1 C | Regulator Patrol Inspection | General Comments | | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0992 | Regulator | 318-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0992 | Regulator | 318-1 C | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0992 | Regulator | 318-1 C | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0992 | Regulator | 318-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0992 | Regulator | 318-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0992 | Regulator | 318-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0992 | Regulator | 318-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0992 | Regulator | 318-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0992 | Regulator | 318-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0992 | Regulator | 318-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0992 | Regulator | 318-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0992 | Regulator | 318-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 302859 | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0992 | Regulator | 318-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.6 | volts |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0988 | Regulator | 318-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0988 | Regulator | 318-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0988 | Regulator | 318-1 B | Regulator Patrol Inspection | Reg Oil Level | Low | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0988 | Regulator | 318-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0988 | Regulator | 318-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.4 | volts |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0988 | Regulator | 318-1 B | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0988 | Regulator | 318-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 79893 | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0988 | Regulator | 318-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0988 | Regulator | 318-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0988 | Regulator | 318-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0988 | Regulator | 318-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0988 | Regulator | 318-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0988 | Regulator | 318-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0988 | Regulator | 318-1 B | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0988 | Regulator | 318-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0988 | Regulator | 318-1 B | Regulator Patrol Inspection | Max Tap Position | 6L | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0988 | Regulator | 318-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0988 | Regulator | 318-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0988 | Regulator | 318-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0988 | Regulator | 318-1 B | Regulator Patrol Inspection | General Comments | bad counter | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0988 | Regulator | 318-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0988 | Regulator | 318-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0988 | Regulator | 318-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0988 | Regulator | 318-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0990 | Regulator | 318-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0990 | Regulator | 318-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0990 | Regulator | 318-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0990 | Regulator | 318-1 A | Regulator Patrol Inspection | General Comments | | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0990 | Regulator | 318-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0990 | Regulator | 318-1 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0990 | Regulator | 318-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0990 | Regulator | 318-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 176187 | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0990 | Regulator | 318-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0990 | Regulator | 318-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0990 | Regulator | 318-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0990 | Regulator | 318-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0990 | Regulator | 318-1 A | Regulator Patrol Inspection | Min Tap Position | 4L | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0990 | Regulator | 318-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0990 | Regulator | 318-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0990 | Regulator | 318-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0990 | Regulator | 318-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0990 | Regulator | 318-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0990 | Regulator | 318-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0990 | Regulator | 318-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0990 | Regulator | 318-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0990 | Regulator | 318-1 A | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0990 | Regulator | 318-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | R0990 | Regulator | 318-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | ST000074 | Structure | 318-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | ST000074 | Structure | 318-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | ST000074 | Structure | 318-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | ST000074 | Structure | 318-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | ST000074 | Structure | 318-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | ST000074 | Structure | 318-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | ST000074 | Structure | 318-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | ST000074 | Structure | 318-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | ST000074 | Structure | 318-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | ST000074 | Structure | 318-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | ST000074 | Structure | 318-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | ST000074 | Structure | 318-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | ST000074 | Structure | 318-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | ST000074 | Structure | 318-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | ST000074 | Structure | 318-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | ST000074 | Structure | 318-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | ST000074 | Structure | 318-Structure | Structure Patrol Inspection | General Comments | | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | ST000074 | Structure | 318-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | ST000074 | Structure | 318-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | ST000074 | Structure | 318-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | ST000074 | Structure | 318-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | FE000011 | Fence | 318-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | FE000011 | Fence | 318-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | FE000011 | Fence | 318-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | FE000011 | Fence | 318-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | FE000011 | Fence | 318-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | FE000011 | Fence | 318-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | FE000011 | Fence | 318-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | FE000011 | Fence | 318-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | FE000011 | Fence | 318-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | FE000011 | Fence | 318-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | FE000011 | Fence | 318-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | FE000011 | Fence | 318-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | FE000011 | Fence | 318-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | FE000011 | Fence | 318-Fence | Fence Patrol Inspection | General Comments | | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | FE000011 | Fence | 318-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | FE000011 | Fence | 318-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | YD000066 | Yard | 318-Yard | Yard Patrol Inspection | Ambient Temp | 27 | °F |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | YD000066 | Yard | 318-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | YD000066 | Yard | 318-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | YD000066 | Yard | 318-Yard | Yard Patrol Inspection | General Comments | | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | YD000066 | Yard | 318-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | YD000066 | Yard | 318-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | YD000066 | Yard | 318-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | YD000066 | Yard | 318-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | YD000066 | Yard | 318-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | YD000066 | Yard | 318-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | YD000066 | Yard | 318-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/14/2023 12:31 | Distribution | Keokee Quarterly Inspection | YD000066 | Yard | 318-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0801 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0801 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0801 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0800 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0800 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0800 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0799 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0799 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0799 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0798 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0798 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0798 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0797 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0797 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0797 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0803 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0803 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LB0803 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | PF001265 | PowerFuse | PL-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | PF001265 | PowerFuse | PL-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | PF001265 | PowerFuse | PL-STA SER NO 2 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | PF001256 | PowerFuse | PL-12KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | PF001256 | PowerFuse | PL-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | PF001256 | PowerFuse | PL-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | PF000310 | PowerFuse | PL-12KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | PF000310 | PowerFuse | PL-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | PF000310 | PowerFuse | PL-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | PF000309 | PowerFuse | PL-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | PF000309 | PowerFuse | PL-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | PF000309 | PowerFuse | PL-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LTCC000114 | LTCControl | PL-TRANS 1 | LTC Control Insp | All Connections OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LTCC000114 | LTCControl | PL-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LTCC000114 | LTCControl | PL-TRANS 1 | LTC Control Insp | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LTCC000114 | LTCControl | PL-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | SWG000057 | Switchgear | PL-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | SWG000057 | Switchgear | PL-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | SWG000057 | Switchgear | PL-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | SWG000057 | Switchgear | PL-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | SWG000057 | Switchgear | PL-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | SWG000057 | Switchgear | PL-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | SWG000057 | Switchgear | PL-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | SWG000057 | Switchgear | PL-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | SWG000057 | Switchgear | PL-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | SWG000057 | Switchgear | PL-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | SWG000057 | Switchgear | PL-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | SWG000057 | Switchgear | PL-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | SWG000057 | Switchgear | PL-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | SWG000057 | Switchgear | PL-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | SWG000057 | Switchgear | PL-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | SWG000057 | Switchgear | PL-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | SWG000057 | Switchgear | PL-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | SWG000057 | Switchgear | PL-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | SWG000057 | Switchgear | PL-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LTCM000035 | LTCMechanism | PL-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LTCM000035 | LTCMechanism | PL-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LTCM000035 | LTCMechanism | PL-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LTCM000035 | LTCMechanism | PL-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LTCM000035 | LTCMechanism | PL-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LTCM000035 | LTCMechanism | PL-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001451 | BreakerVacuum | PL-12KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001451 | BreakerVacuum | PL-12KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001451 | BreakerVacuum | PL-12KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001452 | BreakerVacuum | PL-1275 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001452 | BreakerVacuum | PL-1275 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001452 | BreakerVacuum | PL-1275 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001453 | BreakerVacuum | PL-1276 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001453 | BreakerVacuum | PL-1276 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001453 | BreakerVacuum | PL-1276 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001454 | BreakerVacuum | PL-1277 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001454 | BreakerVacuum | PL-1277 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001454 | BreakerVacuum | PL-1277 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001457 | BreakerVacuum | PL-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001457 | BreakerVacuum | PL-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | BK001457 | BreakerVacuum | PL-12KV BUS TIE SEC 2 | VCB Patrol Inspection | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LTCC000096 | LTCControl | PL-TRANS 2 | LTC Annual Control Inspection | Parallel / Ind. Sw Position | parallelIND | Position |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LTCC000096 | LTCControl | PL-TRANS 2 | LTC Annual Control Inspection | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LTCC000096 | LTCControl | PL-TRANS 2 | LTC Annual Control Inspection | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LTCC000096 | LTCControl | PL-TRANS 2 | LTC Annual Control Inspection | All Connections OK? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | LTCMechanism | PL-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | LTCMechanism | PL-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | LTCMechanism | PL-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | LTCMechanism | PL-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | LTCMechanism | PL-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | LTCMechanism | PL-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | LT0179 | LTCMechanism | PL-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | ST000590 | Structure | PL-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | ST000590 | Structure | PL-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | ST000590 | Structure | PL-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | ST000590 | Structure | PL-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | ST000590 | Structure | PL-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | ST000590 | Structure | PL-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | ST000590 | Structure | PL-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | ST000590 | Structure | PL-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | ST000590 | Structure | PL-Structure | Structure Patrol Inspection | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | ST000590 | Structure | PL-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | ST000590 | Structure | PL-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | ST000590 | Structure | PL-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | ST000590 | Structure | PL-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | ST000590 | Structure | PL-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | ST000590 | Structure | PL-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | ST000590 | Structure | PL-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | CH000176 | ControlHouse | PL-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | CH000176 | ControlHouse | PL-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | CH000176 | ControlHouse | PL-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | CH000176 | ControlHouse | PL-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | CH000176 | ControlHouse | PL-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | CH000176 | ControlHouse | PL-Control House | Control House Patrol Inspection | Restroom Clean & OK? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | CH000176 | ControlHouse | PL-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | CH000176 | ControlHouse | PL-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | CH000176 | ControlHouse | PL-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | CH000176 | ControlHouse | PL-Control House | Control House Patrol Inspection | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | CH000176 | ControlHouse | PL-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | CH000176 | ControlHouse | PL-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | CH000176 | ControlHouse | PL-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | CH000176 | ControlHouse | PL-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | CH000176 | ControlHouse | PL-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | CH000176 | ControlHouse | PL-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | CH000176 | ControlHouse | PL-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | CH000176 | ControlHouse | PL-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | CH000176 | ControlHouse | PL-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | CH000176 | ControlHouse | PL-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | CH000176 | ControlHouse | PL-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | CH000176 | ControlHouse | PL-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | CH000176 | ControlHouse | PL-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | FE000593 | Fence | PL-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | FE000593 | Fence | PL-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | FE000593 | Fence | PL-Fence | Fence Patrol Inspection | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | FE000593 | Fence | PL-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | FE000593 | Fence | PL-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | FE000593 | Fence | PL-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | FE000593 | Fence | PL-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | FE000593 | Fence | PL-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | FE000593 | Fence | PL-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | FE000593 | Fence | PL-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | FE000593 | Fence | PL-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | FE000593 | Fence | PL-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | FE000593 | Fence | PL-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | FE000593 | Fence | PL-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | FE000593 | Fence | PL-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | FE000593 | Fence | PL-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | YD000597 | Yard | PL-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | YD000597 | Yard | PL-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | YD000597 | Yard | PL-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | YD000597 | Yard | PL-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | YD000597 | Yard | PL-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | YD000597 | Yard | PL-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | YD000597 | Yard | PL-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | YD000597 | Yard | PL-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | YD000597 | Yard | PL-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | YD000597 | Yard | PL-Yard | Yard Patrol Inspection | Ambient Temp | 33 | °F |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | YD000597 | Yard | PL-Yard | Yard Patrol Inspection | General Comments | | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | YD000597 | Yard | PL-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | YD000597 | Yard | PL-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | YD000597 | Yard | PL-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | YD000597 | Yard | PL-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | YD000597 | Yard | PL-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/16/2023 8:34 | Distribution | Pleasure Ridge Quarterly Inspection | YD000597 | Yard | PL-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | RC000426 | RecloserHydraulic | 229-3426 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0.0 | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | RC000426 | RecloserHydraulic | 229-3426 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | RC000426 | RecloserHydraulic | 229-3426 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | RC000426 | RecloserHydraulic | 229-3426 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | RC000426 | RecloserHydraulic | 229-3426 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | RC000426 | RecloserHydraulic | 229-3426 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | RC000426 | RecloserHydraulic | 229-3426 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | RC000426 | RecloserHydraulic | 229-3426 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | RC000426 | RecloserHydraulic | 229-3426 | Recloser Hydraulic Patrol Inspection | Operations Counter | 80 | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | RC000426 | RecloserHydraulic | 229-3426 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | RC000426 | RecloserHydraulic | 229-3426 | Recloser Hydraulic Patrol Inspection | General Comments | Recloser is open. | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | RC000426 | RecloserHydraulic | 229-3426 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | RC000426 | RecloserHydraulic | 229-3426 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1219 | BreakerVacuum | FM-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations | 6 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1219 | BreakerVacuum | FM-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1219 | BreakerVacuum | FM-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1219 | BreakerVacuum | FM-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1219 | BreakerVacuum | FM-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1219 | BreakerVacuum | FM-12KV BUS TIE SEC 2 | VCB Readings | Amps A Ø | 0.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1219 | BreakerVacuum | FM-12KV BUS TIE SEC 2 | VCB Readings | Amps B Ø | 0.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1219 | BreakerVacuum | FM-12KV BUS TIE SEC 2 | VCB Readings | Amps C Ø | 0.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1219 | BreakerVacuum | FM-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1219 | BreakerVacuum | FM-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1219 | BreakerVacuum | FM-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1219 | BreakerVacuum | FM-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1219 | BreakerVacuum | FM-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1219 | BreakerVacuum | FM-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1219 | BreakerVacuum | FM-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1219 | BreakerVacuum | FM-12KV BUS TIE SEC 2 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1219 | BreakerVacuum | FM-12KV BUS TIE SEC 2 | VCB Readings | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1219 | BreakerVacuum | FM-12KV BUS TIE SEC 2 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1219 | BreakerVacuum | FM-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AF | 251 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1219 | BreakerVacuum | FM-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AL | 251 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1219 | BreakerVacuum | FM-12KV BUS TIE SEC 2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1219 | BreakerVacuum | FM-12KV BUS TIE SEC 2 | VCB Readings | Switching Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1219 | BreakerVacuum | FM-12KV BUS TIE SEC 2 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1224 | BreakerVacuum | FM-1263 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1224 | BreakerVacuum | FM-1263 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1224 | BreakerVacuum | FM-1263 | VCB Readings | General Comments | DNO | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1224 | BreakerVacuum | FM-1263 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1224 | BreakerVacuum | FM-1263 | VCB Readings | Operations Counter AF | 206 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1224 | BreakerVacuum | FM-1263 | VCB Readings | Operations Counter AL | 206 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1224 | BreakerVacuum | FM-1263 | VCB Readings | Operations This Read Vac | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1224 | BreakerVacuum | FM-1263 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1224 | BreakerVacuum | FM-1263 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1224 | BreakerVacuum | FM-1263 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1224 | BreakerVacuum | FM-1263 | VCB Readings | Switching Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1224 | BreakerVacuum | FM-1263 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1224 | BreakerVacuum | FM-1263 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1224 | BreakerVacuum | FM-1263 | VCB Readings | 9 Month Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1224 | BreakerVacuum | FM-1263 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1224 | BreakerVacuum | FM-1263 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1224 | BreakerVacuum | FM-1263 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1224 | BreakerVacuum | FM-1263 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1224 | BreakerVacuum | FM-1263 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1224 | BreakerVacuum | FM-1263 | VCB Readings | Amps C Ø | 0.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1224 | BreakerVacuum | FM-1263 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1224 | BreakerVacuum | FM-1263 | VCB Readings | Amps A Ø | 0.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1224 | BreakerVacuum | FM-1263 | VCB Readings | Amps B Ø | 0.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1223 | BreakerVacuum | FM-1262 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1223 | BreakerVacuum | FM-1262 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1223 | BreakerVacuum | FM-1262 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1223 | BreakerVacuum | FM-1262 | VCB Readings | Amps C Ø | 177.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1223 | BreakerVacuum | FM-1262 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1223 | BreakerVacuum | FM-1262 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1223 | BreakerVacuum | FM-1262 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1223 | BreakerVacuum | FM-1262 | VCB Readings | Amps B Ø | 188.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1223 | BreakerVacuum | FM-1262 | VCB Readings | Amps A Ø | 188.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1223 | BreakerVacuum | FM-1262 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1223 | BreakerVacuum | FM-1262 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1223 | BreakerVacuum | FM-1262 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1223 | BreakerVacuum | FM-1262 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1223 | BreakerVacuum | FM-1262 | VCB Readings | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1223 | BreakerVacuum | FM-1262 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1223 | BreakerVacuum | FM-1262 | VCB Readings | Operations Counter AF | 431 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1223 | BreakerVacuum | FM-1262 | VCB Readings | Operations Counter AL | 431 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1223 | BreakerVacuum | FM-1262 | VCB Readings | Operations This Read Vac | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1223 | BreakerVacuum | FM-1262 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1223 | BreakerVacuum | FM-1262 | VCB Readings | 9 Month Operations VCB New | 14 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1223 | BreakerVacuum | FM-1262 | VCB Readings | 9 Month Operations | 14 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1223 | BreakerVacuum | FM-1262 | VCB Readings | Switching Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1223 | BreakerVacuum | FM-1262 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1222 | BreakerVacuum | FM-1261 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1222 | BreakerVacuum | FM-1261 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1222 | BreakerVacuum | FM-1261 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1222 | BreakerVacuum | FM-1261 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1222 | BreakerVacuum | FM-1261 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1222 | BreakerVacuum | FM-1261 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1222 | BreakerVacuum | FM-1261 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1222 | BreakerVacuum | FM-1261 | VCB Readings | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1222 | BreakerVacuum | FM-1261 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1222 | BreakerVacuum | FM-1261 | VCB Readings | Operations Counter AF | 223 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1222 | BreakerVacuum | FM-1261 | VCB Readings | 9 Month Operations | 1 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1222 | BreakerVacuum | FM-1261 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1222 | BreakerVacuum | FM-1261 | VCB Readings | Amps C Ø | 39.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1222 | BreakerVacuum | FM-1261 | VCB Readings | Amps B Ø | 37.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1222 | BreakerVacuum | FM-1261 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1222 | BreakerVacuum | FM-1261 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1222 | BreakerVacuum | FM-1261 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1222 | BreakerVacuum | FM-1261 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1222 | BreakerVacuum | FM-1261 | VCB Readings | Amps A Ø | 44.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1222 | BreakerVacuum | FM-1261 | VCB Readings | Operations Counter AL | 223 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1222 | BreakerVacuum | FM-1261 | VCB Readings | Operations This Read Vac | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1222 | BreakerVacuum | FM-1261 | VCB Readings | Switching Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1222 | BreakerVacuum | FM-1261 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1221 | BreakerVacuum | FM-1260 | VCB Readings | Operations Counter AL | 226 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1221 | BreakerVacuum | FM-1260 | VCB Readings | Amps A Ø | 129.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1221 | BreakerVacuum | FM-1260 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1221 | BreakerVacuum | FM-1260 | VCB Readings | Operations Counter AF | 226 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1221 | BreakerVacuum | FM-1260 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1221 | BreakerVacuum | FM-1260 | VCB Readings | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1221 | BreakerVacuum | FM-1260 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1221 | BreakerVacuum | FM-1260 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1221 | BreakerVacuum | FM-1260 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1221 | BreakerVacuum | FM-1260 | VCB Readings | Operations This Read Vac | 2 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1221 | BreakerVacuum | FM-1260 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1221 | BreakerVacuum | FM-1260 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1221 | BreakerVacuum | FM-1260 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1221 | BreakerVacuum | FM-1260 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1221 | BreakerVacuum | FM-1260 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1221 | BreakerVacuum | FM-1260 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1221 | BreakerVacuum | FM-1260 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1221 | BreakerVacuum | FM-1260 | VCB Readings | Switching Operations | 2 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1221 | BreakerVacuum | FM-1260 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1221 | BreakerVacuum | FM-1260 | VCB Readings | Amps C Ø | 98.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1221 | BreakerVacuum | FM-1260 | VCB Readings | Amps B Ø | 102.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1221 | BreakerVacuum | FM-1260 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1221 | BreakerVacuum | FM-1260 | VCB Readings | 9 Month Operations | 2 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1220 | BreakerVacuum | FM-1258 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1220 | BreakerVacuum | FM-1258 | VCB Readings | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1220 | BreakerVacuum | FM-1258 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1220 | BreakerVacuum | FM-1258 | VCB Readings | Operations Counter AF | 162 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1220 | BreakerVacuum | FM-1258 | VCB Readings | Operations Counter AL | 162 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1220 | BreakerVacuum | FM-1258 | VCB Readings | Operations This Read Vac | 1 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1220 | BreakerVacuum | FM-1258 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1220 | BreakerVacuum | FM-1258 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1220 | BreakerVacuum | FM-1258 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1220 | BreakerVacuum | FM-1258 | VCB Readings | 9 Month Operations | 1 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1220 | BreakerVacuum | FM-1258 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1220 | BreakerVacuum | FM-1258 | VCB Readings | Amps A Ø | 0.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1220 | BreakerVacuum | FM-1258 | VCB Readings | Amps B Ø | 0.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1220 | BreakerVacuum | FM-1258 | VCB Readings | Amps C Ø | 0.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1220 | BreakerVacuum | FM-1258 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1220 | BreakerVacuum | FM-1258 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1220 | BreakerVacuum | FM-1258 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1220 | BreakerVacuum | FM-1258 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1220 | BreakerVacuum | FM-1258 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1220 | BreakerVacuum | FM-1258 | VCB Readings | Switching Operations | 1 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1220 | BreakerVacuum | FM-1258 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1220 | BreakerVacuum | FM-1258 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1220 | BreakerVacuum | FM-1258 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1171 | BreakerVacuum | FM-12KV TR 2 | VCB Readings | 9 Month Operations | 1 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1171 | BreakerVacuum | FM-12KV TR 2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1171 | BreakerVacuum | FM-12KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1171 | BreakerVacuum | FM-12KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1171 | BreakerVacuum | FM-12KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1171 | BreakerVacuum | FM-12KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1171 | BreakerVacuum | FM-12KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1171 | BreakerVacuum | FM-12KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1171 | BreakerVacuum | FM-12KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1171 | BreakerVacuum | FM-12KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1171 | BreakerVacuum | FM-12KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1171 | BreakerVacuum | FM-12KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1171 | BreakerVacuum | FM-12KV TR 2 | VCB Readings | Amps C Ø | 303.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1171 | BreakerVacuum | FM-12KV TR 2 | VCB Readings | Amps B Ø | 324.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1171 | BreakerVacuum | FM-12KV TR 2 | VCB Readings | Amps A Ø | 364.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1171 | BreakerVacuum | FM-12KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1171 | BreakerVacuum | FM-12KV TR 2 | VCB Readings | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1171 | BreakerVacuum | FM-12KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1171 | BreakerVacuum | FM-12KV TR 2 | VCB Readings | Operations Counter AF | 172 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1171 | BreakerVacuum | FM-12KV TR 2 | VCB Readings | Operations Counter AL | 172 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1171 | BreakerVacuum | FM-12KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1171 | BreakerVacuum | FM-12KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1171 | BreakerVacuum | FM-12KV TR 2 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB0301 | BreakerVacuum | FM-1256 | VCB Readings | Switching Operations | 15 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB0301 | BreakerVacuum | FM-1256 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB0301 | BreakerVacuum | FM-1256 | VCB Readings | Operations This Read Vac | 15 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB0301 | BreakerVacuum | FM-1256 | VCB Readings | Operations Counter AL | 635 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB0301 | BreakerVacuum | FM-1256 | VCB Readings | Operations Counter AF | 635 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB0301 | BreakerVacuum | FM-1256 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB0301 | BreakerVacuum | FM-1256 | VCB Readings | Amps A Ø | 187.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB0301 | BreakerVacuum | FM-1256 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB0301 | BreakerVacuum | FM-1256 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB0301 | BreakerVacuum | FM-1256 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB0301 | BreakerVacuum | FM-1256 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB0301 | BreakerVacuum | FM-1256 | VCB Readings | 9 Month Operations | 15 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB0301 | BreakerVacuum | FM-1256 | VCB Readings | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB0301 | BreakerVacuum | FM-1256 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB0301 | BreakerVacuum | FM-1256 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB0301 | BreakerVacuum | FM-1256 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB0301 | BreakerVacuum | FM-1256 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB0301 | BreakerVacuum | FM-1256 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB0301 | BreakerVacuum | FM-1256 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB0301 | BreakerVacuum | FM-1256 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB0301 | BreakerVacuum | FM-1256 | VCB Readings | Amps B Ø | 167.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB0301 | BreakerVacuum | FM-1256 | VCB Readings | Amps C Ø | 175.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB0301 | BreakerVacuum | FM-1256 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LTCC000406 | LTCControl | FM-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LTCC000406 | LTCControl | FM-TRANS 2 | LTC Control Insp | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LTCC000406 | LTCControl | FM-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | LTCMechanism | FM-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | LTCMechanism | FM-TRANS 2 | LTC Counter Readings | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | LTCMechanism | FM-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 65868 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | LTCMechanism | FM-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 65868 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | LTCMechanism | FM-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | LTCMechanism | FM-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 331 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | LTCMechanism | FM-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 16L | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | LTCMechanism | FM-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | LTCMechanism | FM-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 14L | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | LTCMechanism | FM-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | LTCMechanism | FM-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | LTCMechanism | FM-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | LTCMechanism | FM-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | LTCMechanism | FM-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 28 | °C |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | LTCMechanism | FM-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | LTCMechanism | FM-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | LTCMechanism | FM-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 38 | °C |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 31 | °C |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 38 | °C |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 31 | °C |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 31 | °C |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 38 | °C |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 38 | °C |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 31 | °C |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LTCC000360 | LTCControl | FM-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LTCC000360 | LTCControl | FM-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LTCC000360 | LTCControl | FM-TRANS 1 | LTC Control Insp | General Comments | | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000089 | WithLTC | LS-Yard-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000089 | WithLTC | LS-Yard-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000089 | WithLTC | LS-Yard-Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000089 | WithLTC | LS-Yard-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000089 | WithLTC | LS-Yard-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000089 | WithLTC | LS-Yard-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000089 | WithLTC | LS-Yard-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000089 | WithLTC | LS-Yard-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000089 | WithLTC | LS-Yard-Distribution | LTC Transformer Patrol Inspection | General Comments | not here | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000089 | WithLTC | LS-Yard-Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000089 | WithLTC | LS-Yard-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | LTCMechanism | FM-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | LTCMechanism | FM-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 12L | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | LTCMechanism | FM-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 125616 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | LTCMechanism | FM-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | LTCMechanism | FM-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 610 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | LTCMechanism | FM-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | LTCMechanism | FM-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 125616 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | LTCMechanism | FM-TRANS 1 | LTC Counter Readings | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | LTCMechanism | FM-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | ST000084 | Structure | 229-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | ST000084 | Structure | 229-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | ST000084 | Structure | 229-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | ST000084 | Structure | 229-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | ST000084 | Structure | 229-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | ST000084 | Structure | 229-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | ST000084 | Structure | 229-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | ST000084 | Structure | 229-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | ST000084 | Structure | 229-Structure | Structure Patrol Inspection | General Comments | | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | ST000084 | Structure | 229-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | ST000084 | Structure | 229-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | ST000084 | Structure | 229-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | ST000084 | Structure | 229-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | ST000084 | Structure | 229-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | ST000084 | Structure | 229-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | ST000084 | Structure | 229-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | ST000084 | Structure | 229-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | ST000084 | Structure | 229-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Rust | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | ST000084 | Structure | 229-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | ST000084 | Structure | 229-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | ST000084 | Structure | 229-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | The lowside bushings are leaking | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Leaking | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0100 | WithLTC | Retired Distribution | LTC Transformer Patrol Inspection | General Comments | nitro | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0100 | WithLTC | Retired Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0100 | WithLTC | Retired Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0100 | WithLTC | Retired Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0100 | WithLTC | Retired Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0100 | WithLTC | Retired Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0100 | WithLTC | Retired Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0100 | WithLTC | Retired Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0100 | WithLTC | Retired Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0100 | WithLTC | Retired Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0100 | WithLTC | Retired Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | FE000076 | Fence | 229-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | FE000076 | Fence | 229-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | FE000076 | Fence | 229-Fence | Fence Patrol Inspection | General Comments | | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | FE000076 | Fence | 229-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | FE000076 | Fence | 229-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | FE000076 | Fence | 229-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | FE000076 | Fence | 229-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | FE000076 | Fence | 229-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | FE000076 | Fence | 229-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | FE000076 | Fence | 229-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | FE000076 | Fence | 229-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | FE000076 | Fence | 229-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | FE000076 | Fence | 229-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | FE000076 | Fence | 229-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | FE000076 | Fence | 229-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | FE000076 | Fence | 229-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | YD000076 | Yard | 229-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | YD000076 | Yard | 229-Yard | Yard Patrol Inspection | General Comments | | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | YD000076 | Yard | 229-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | YD000076 | Yard | 229-Yard | Yard Patrol Inspection | Ambient Temp | 26 | °F |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | YD000076 | Yard | 229-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | YD000076 | Yard | 229-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | YD000076 | Yard | 229-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | YD000076 | Yard | 229-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | YD000076 | Yard | 229-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | YD000076 | Yard | 229-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | YD000076 | Yard | 229-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/14/2023 11:03 | Distribution | Calvin Quarterly Inspection | YD000076 | Yard | 229-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | LTCMechanism | FM-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | LTCMechanism | FM-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | LTCMechanism | FM-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | LTCMechanism | FM-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | LTCMechanism | FM-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | LTCMechanism | FM-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 40 | °C |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 36 | °C |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 38 | °C |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 38 | °C |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 62 | °C |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 58 | °C |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 38 | °C |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Readings | H2 Winding Temp Present | 65 | °C |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Readings | H2 Winding Temp Max | 65 | °C |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0069 | WithLTC | FM-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Readings | 9 Month Operations | 4 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Readings | Switching Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Readings | Operations This Read Vac | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Readings | Operations Counter AL | 7 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Readings | Operations Counter AF | 7 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Readings | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Readings | Amps A Ø | 140.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Readings | Amps B Ø | 120.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Readings | Amps C Ø | 120.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Readings | 9 Month Operations | 5 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Readings | Amps A Ø | 387.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Readings | Amps B Ø | 356.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Readings | Amps C Ø | 324.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Readings | Operations Counter AF | 74 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Readings | Operations Counter AL | 74 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Readings | Switching Operations | 1 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Readings | Operations This Read Vac | 1 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Readings | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Readings | Amps A Ø | 90.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Readings | Operations Counter AF | 45 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Readings | 9 Month Operations | 1 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Readings | Amps B Ø | 95.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Readings | Amps C Ø | 60.0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Readings | Operations Counter AL | 45 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BCH001091 | Charger | FM-Battery Charger | Battery Charger Patrol Insp | General Comments | One minute after trip voltage 50.8 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BCH001091 | Charger | FM-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BCH001091 | Charger | FM-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BCH001091 | Charger | FM-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BCH001091 | Charger | FM-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.7 | VDC |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BCH001091 | Charger | FM-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.7 | VDC |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BCH001091 | Charger | FM-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 5.2 | amps |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0184 | NonLTC | P-Yard | NonLTC Transformer Patrol Inspection | General Comments | oil leaks, needs nitro, htrs not worikng | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0184 | NonLTC | P-Yard | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0184 | NonLTC | P-Yard | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0184 | NonLTC | P-Yard | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0184 | NonLTC | P-Yard | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0184 | NonLTC | P-Yard | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 62.50 | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0184 | NonLTC | P-Yard | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0184 | NonLTC | P-Yard | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0184 | NonLTC | P-Yard | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0184 | NonLTC | P-Yard | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0184 | NonLTC | P-Yard | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | n | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0184 | NonLTC | P-Yard | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000125 | Switchgear | PI-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000125 | Switchgear | PI-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000125 | Switchgear | PI-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000125 | Switchgear | PI-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000125 | Switchgear | PI-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000125 | Switchgear | PI-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000125 | Switchgear | PI-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000125 | Switchgear | PI-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000125 | Switchgear | PI-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000125 | Switchgear | PI-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000125 | Switchgear | PI-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000125 | Switchgear | PI-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000125 | Switchgear | PI-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000125 | Switchgear | PI-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000125 | Switchgear | PI-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000125 | Switchgear | PI-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000053 | Switchgear | PI-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000053 | Switchgear | PI-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000053 | Switchgear | PI-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000053 | Switchgear | PI-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000053 | Switchgear | PI-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000053 | Switchgear | PI-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000053 | Switchgear | PI-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000053 | Switchgear | PI-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000053 | Switchgear | PI-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000053 | Switchgear | PI-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000053 | Switchgear | PI-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000053 | Switchgear | PI-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000053 | Switchgear | PI-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000053 | Switchgear | PI-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000053 | Switchgear | PI-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | SWG000053 | Switchgear | PI-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PF000271 | PowerFuse | PI-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PF000271 | PowerFuse | PI-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0787 | BreakerAirMagnetic | PI-SEC 1 SPARE | AMCB Patrol Inspection | General Comments | | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0787 | BreakerAirMagnetic | PI-SEC 1 SPARE | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0787 | BreakerAirMagnetic | PI-SEC 1 SPARE | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0787 | BreakerAirMagnetic | PI-SEC 1 SPARE | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0787 | BreakerAirMagnetic | PI-SEC 1 SPARE | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0787 | BreakerAirMagnetic | PI-SEC 1 SPARE | AMCB Readings | 9 Months Operations | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0787 | BreakerAirMagnetic | PI-SEC 1 SPARE | AMCB Readings | 9 Month Ops New | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0787 | BreakerAirMagnetic | PI-SEC 1 SPARE | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0787 | BreakerAirMagnetic | PI-SEC 1 SPARE | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0787 | BreakerAirMagnetic | PI-SEC 1 SPARE | AMCB Readings | Amps A Ø | 0.0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0787 | BreakerAirMagnetic | PI-SEC 1 SPARE | AMCB Readings | Amps B Ø | 0.0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0787 | BreakerAirMagnetic | PI-SEC 1 SPARE | AMCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0787 | BreakerAirMagnetic | PI-SEC 1 SPARE | AMCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0787 | BreakerAirMagnetic | PI-SEC 1 SPARE | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0787 | BreakerAirMagnetic | PI-SEC 1 SPARE | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0787 | BreakerAirMagnetic | PI-SEC 1 SPARE | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0787 | BreakerAirMagnetic | PI-SEC 1 SPARE | AMCB Readings | Amps C Ø | 0.0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0787 | BreakerAirMagnetic | PI-SEC 1 SPARE | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0787 | BreakerAirMagnetic | PI-SEC 1 SPARE | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0787 | BreakerAirMagnetic | PI-SEC 1 SPARE | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0787 | BreakerAirMagnetic | PI-SEC 1 SPARE | AMCB Readings | General Comments | | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0787 | BreakerAirMagnetic | PI-SEC 1 SPARE | AMCB Readings | Unknown Operations | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0787 | BreakerAirMagnetic | PI-SEC 1 SPARE | AMCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0787 | BreakerAirMagnetic | PI-SEC 1 SPARE | AMCB Readings | Operations Counter AF | 284 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0787 | BreakerAirMagnetic | PI-SEC 1 SPARE | AMCB Readings | Switching Operations | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0787 | BreakerAirMagnetic | PI-SEC 1 SPARE | AMCB Readings | Operations This Read AM | 0 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0787 | BreakerAirMagnetic | PI-SEC 1 SPARE | AMCB Readings | Operations Counter AL | 284 | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PF001332 | PowerFuse | PI-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PF001332 | PowerFuse | PI-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PF000270 | PowerFuse | PI-4KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | PF000270 | PowerFuse | PI-4KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1167 | BreakerVacuum | PI-4 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0788 | BreakerAirMagnetic | PI-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0788 | BreakerAirMagnetic | PI-3 | AMCB Patrol Inspection | General Comments | | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0788 | BreakerAirMagnetic | PI-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0788 | BreakerAirMagnetic | PI-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB1166 | BreakerVacuum | PI-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0786 | BreakerAirMagnetic | PI-1 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0786 | BreakerAirMagnetic | PI-1 | AMCB Patrol Inspection | General Comments | | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0786 | BreakerAirMagnetic | PI-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | LB0786 | BreakerAirMagnetic | PI-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | YD000599 | Yard | PI-Yard | Yard Patrol Inspection | General Comments | | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | YD000599 | Yard | PI-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | YD000599 | Yard | PI-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | YD000599 | Yard | PI-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | YD000599 | Yard | PI-Yard | Yard Patrol Inspection | Clear of Trash? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | YD000599 | Yard | PI-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | YD000599 | Yard | PI-Yard | Yard Patrol Inspection | Ambient Temp | 34 | °F |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | YD000599 | Yard | PI-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | YD000599 | Yard | PI-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | YD000599 | Yard | PI-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | YD000599 | Yard | PI-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | YD000599 | Yard | PI-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | YD000599 | Yard | PI-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | YD000599 | Yard | PI-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | CH000442 | ControlHouse | PI-Battery Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | CH000442 | ControlHouse | PI-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | CH000442 | ControlHouse | PI-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | CH000442 | ControlHouse | PI-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | CH000442 | ControlHouse | PI-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | CH000442 | ControlHouse | PI-Battery Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/15/2023 14:17 | Distribution | Pirtle Quarterly Inspection | CH000442 | ControlHouse | PI-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | YD000290 | Yard | 798-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | YD000290 | Yard | 798-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Readings | Accumulated Fault Duty A Ph V | 1.31 | % |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Readings | Accumulated Fault Duty B Ph V | .88 | % |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Readings | Accumulated Fault Duty C Ph V | .44 | % |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | YD000290 | Yard | 798-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | YD000290 | Yard | 798-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | YD000290 | Yard | 798-Yard | Yard Patrol Inspection | Ambient Temp | 34 | °F |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | LTCC000400 | LTCControl | 683-1 | LTC Control Insp | All Connections OK? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | LTCC000400 | LTCControl | 683-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | LTCC000400 | LTCControl | 683-1 | LTC Control Insp | General Comments | | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | LTCC000400 | LTCControl | 683-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | LTCC000400 | LTCControl | 683-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | LTCC000400 | LTCControl | 683-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | LTCC000400 | LTCControl | 683-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Readings | Amps A Ø | 60 | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0847 | Regulator | 064-5 B | Regulator Patrol Inspection | General Comments | | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | LTCC000400 | LTCControl | 683-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | LTCC000400 | LTCControl | 683-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0847 | Regulator | 064-5 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0847 | Regulator | 064-5 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0847 | Regulator | 064-5 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0847 | Regulator | 064-5 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0847 | Regulator | 064-5 B | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0847 | Regulator | 064-5 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0847 | Regulator | 064-5 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0218 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Readings | Amps B Ø | 386 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Readings | Amps C Ø | 381 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0305 | GroundTransformer | SSC-Offline-Distribution | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0305 | GroundTransformer | SSC-Offline-Distribution | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0305 | GroundTransformer | SSC-Offline-Distribution | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0305 | GroundTransformer | SSC-Offline-Distribution | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0305 | GroundTransformer | SSC-Offline-Distribution | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0305 | GroundTransformer | SSC-Offline-Distribution | Ground Transformer Patrol Inspection | General Comments | | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0305 | GroundTransformer | SSC-Offline-Distribution | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Readings | Operations Counter AF | 184 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Readings | Operations Counter AL | 185 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Readings | Operations This Read Vac | 1 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Readings | Switching Operations | 1 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0305 | GroundTransformer | SSC-Offline-Distribution | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN13 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN13 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN13 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN13 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN13 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN13 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | nitro | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN13 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN13 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN13 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN13 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN13 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Readings | Operations This Read Vac | 1 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Readings | Operations Counter AL | 274 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Readings | Operations Counter AF | 273 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Readings | Operations Counter AF | 255 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Readings | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Readings | Amps C Ø | 276 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Readings | Amps B Ø | 276 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Readings | Amps A Ø | 285 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Readings | Accumulated Fault Duty B Ph V | .83 | % |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Readings | 9 Month Operations | 1 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Readings | General Comments | | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Readings | Operations Counter AF | 250 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Readings | Operations Counter AL | 250 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Readings | Operations This Read Vac | 0 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Readings | Switching Operations | 0 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0836 | BreakerAirMagnetic | SE-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0836 | BreakerAirMagnetic | SE-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0836 | BreakerAirMagnetic | SE-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0836 | BreakerAirMagnetic | SE-1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0836 | BreakerAirMagnetic | SE-1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN29 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN29 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN29 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN29 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN29 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN29 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN29 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | YD000290 | Yard | 798-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN29 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN29 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN29 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN29 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Readings | 9 Month Operations | 1 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | YD000290 | Yard | 798-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | YD000290 | Yard | 798-Yard | Yard Patrol Inspection | General Comments | | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | YD000290 | Yard | 798-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | YD000290 | Yard | 798-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | YD000290 | Yard | 798-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | YD000290 | Yard | 798-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | YD000290 | Yard | 798-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0846 | Regulator | 064-5 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Readings | General Comments | | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0847 | Regulator | 064-5 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0847 | Regulator | 064-5 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0846 | Regulator | 064-5 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0846 | Regulator | 064-5 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0846 | Regulator | 064-5 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0846 | Regulator | 064-5 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | LTCC000930 | LTCControl | 799-1 | LTC Control Insp | All Connections OK? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0178 | NonLTC | SSC-PORT TRANS 1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0178 | NonLTC | SSC-PORT TRANS 1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0178 | NonLTC | SSC-PORT TRANS 1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0178 | NonLTC | SSC-PORT TRANS 1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 62.50 | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0178 | NonLTC | SSC-PORT TRANS 1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0178 | NonLTC | SSC-PORT TRANS 1 | NonLTC Transformer Patrol Inspection | General Comments | Front outriggers are sinking into pavement. Needs Nitro | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0178 | NonLTC | SSC-PORT TRANS 1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0846 | Regulator | 064-5 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0846 | Regulator | 064-5 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0846 | Regulator | 064-5 C | Regulator Patrol Inspection | Regulator As Left Counter | 122453 | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0846 | Regulator | 064-5 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0846 | Regulator | 064-5 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0846 | Regulator | 064-5 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0846 | Regulator | 064-5 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0178 | NonLTC | SSC-PORT TRANS 1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0846 | Regulator | 064-5 C | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0846 | Regulator | 064-5 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0846 | Regulator | 064-5 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0846 | Regulator | 064-5 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0846 | Regulator | 064-5 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0846 | Regulator | 064-5 C | Regulator Patrol Inspection | General Comments | | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0846 | Regulator | 064-5 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0846 | Regulator | 064-5 C | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0846 | Regulator | 064-5 C | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0846 | Regulator | 064-5 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0178 | NonLTC | SSC-PORT TRANS 1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0218 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0218 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | LTCC000266 | LTCControl | 799-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | LTCC000266 | LTCControl | 799-2 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Readings | Operations Counter AF | 283 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Readings | Operations Counter AL | 284 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Readings | Operations This Read Vac | 1 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Readings | Switching Operations | 1 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0218 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0218 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0218 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0218 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0218 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | LTCC000266 | LTCControl | 799-2 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | LTCC000266 | LTCControl | 799-2 | LTC Control Insp | LTC Output Voltage Level | 124.7 | VAC |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | LTCC000266 | LTCControl | 799-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | LTCC000266 | LTCControl | 799-2 | LTC Control Insp | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | LTCC000266 | LTCControl | 799-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | LTCC000266 | LTCControl | 799-2 | LTC Control Insp | All Connections OK? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0178 | NonLTC | SSC-PORT TRANS 1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0847 | Regulator | 064-5 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Readings | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Readings | Amps B Ø | 63 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Readings | Amps C Ø | 38 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | FE000387 | Fence | 406-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | FE000387 | Fence | 406-Fence | Fence Patrol Inspection | General Comments | | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | FE000387 | Fence | 406-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | FE000387 | Fence | 406-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | FE000387 | Fence | 406-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | LTCMechanism | 799-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | LTCMechanism | 799-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | LTCMechanism | 799-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | LTCMechanism | 799-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | LTCMechanism | 799-2 | LTC Counter Readings | LTC Operations Since Last Insp | 1839 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | LTCMechanism | 799-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 40 | °C |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | LTCMechanism | 799-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 60 | °C |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | FE000387 | Fence | 406-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | LTCMechanism | 799-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 4 | psi |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | LTCMechanism | 799-2 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | LTCMechanism | 799-2 | LTC Counter Readings | LTC Max Tap Position | 9R | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | LTCMechanism | 799-2 | LTC Counter Readings | LTC Current Tap Position | 5R | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | LTCMechanism | 799-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | LTCMechanism | 799-2 | LTC Counter Readings | LTC As Left Counter | 140703 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | LTCMechanism | 799-2 | LTC Counter Readings | LTC As Found Counter | 140700 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | LTCMechanism | 799-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | LTCMechanism | 799-2 | LTC Counter Readings | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | LTCMechanism | 799-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | LTCMechanism | 799-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | FE000387 | Fence | 406-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | FE000387 | Fence | 406-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | FE000387 | Fence | 406-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | FE000387 | Fence | 406-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | FE000387 | Fence | 406-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | FE000387 | Fence | 406-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | FE000387 | Fence | 406-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | FE000387 | Fence | 406-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | FE000387 | Fence | 406-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0218 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0218 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0218 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | LTCC000930 | LTCControl | 799-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | LTCC000930 | LTCControl | 799-1 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | LTCC000930 | LTCControl | 799-1 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | LTCC000930 | LTCControl | 799-1 | LTC Control Insp | LTC Output Voltage Level | 124.2 | VAC |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | LTCC000930 | LTCControl | 799-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | LTCC000930 | LTCControl | 799-1 | LTC Control Insp | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | LTCC000930 | LTCControl | 799-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0846 | Regulator | 064-5 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0846 | Regulator | 064-5 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0163 | BreakerVacuum | 681-2442 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | YD000311 | Yard | 683-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | YD000311 | Yard | 683-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | YD000311 | Yard | 683-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | YD000311 | Yard | 683-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | YD000311 | Yard | 683-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | YD000311 | Yard | 683-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | YD000311 | Yard | 683-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | YD000311 | Yard | 683-Yard | Yard Patrol Inspection | Ambient Temp | 38 | °F |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | FE000307 | Fence | 683-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | FE000307 | Fence | 683-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | FE000307 | Fence | 683-Fence | Fence Patrol Inspection | General Comments | | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | FE000307 | Fence | 683-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | FE000307 | Fence | 683-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | FE000307 | Fence | 683-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | FE000307 | Fence | 683-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | FE000307 | Fence | 683-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | FE000307 | Fence | 683-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | FE000307 | Fence | 683-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | FE000307 | Fence | 683-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | FE000307 | Fence | 683-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | FE000307 | Fence | 683-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Readings | 9 Month Operations | 1 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Readings | Accumulated Fault Duty B Ph V | .83 | % |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Readings | Amps A Ø | 26 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Readings | Amps B Ø | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Readings | Amps C Ø | 14 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | LTCMechanism | 683-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | LTCMechanism | 683-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | LTCMechanism | 683-1 | LTC Counter Readings | General Comments | | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | LTCMechanism | 683-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | LTCMechanism | 683-1 | LTC Counter Readings | LTC As Found Counter | 65109 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | LTCMechanism | 683-1 | LTC Counter Readings | LTC As Left Counter | 1 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | LTCMechanism | 683-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | LTCMechanism | 683-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | LTCMechanism | 683-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | LTCMechanism | 683-1 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | LTCMechanism | 683-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | LTCMechanism | 683-1 | LTC Counter Readings | LTC Operations Since Last Insp | 501 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | LTCMechanism | 683-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | LTCMechanism | 683-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | LTCMechanism | 683-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | LTCMechanism | 683-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | BAT001286 | Battery | SE-Battery Bank | Battery Patrol Inspection | Battery Bank Amps | 0.0 | AMPS |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0848 | Regulator | 064-5 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0848 | Regulator | 064-5 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0848 | Regulator | 064-5 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0848 | Regulator | 064-5 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0848 | Regulator | 064-5 A | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0848 | Regulator | 064-5 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0848 | Regulator | 064-5 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0848 | Regulator | 064-5 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0848 | Regulator | 064-5 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0848 | Regulator | 064-5 A | Regulator Patrol Inspection | General Comments | | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0848 | Regulator | 064-5 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0848 | Regulator | 064-5 A | Regulator Patrol Inspection | Max Tap Position | 10R | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0848 | Regulator | 064-5 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0848 | Regulator | 064-5 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0848 | Regulator | 064-5 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0848 | Regulator | 064-5 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0848 | Regulator | 064-5 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0848 | Regulator | 064-5 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0848 | Regulator | 064-5 A | Regulator Patrol Inspection | Regulator As Left Counter | 7661 | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0848 | Regulator | 064-5 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0848 | Regulator | 064-5 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0848 | Regulator | 064-5 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0848 | Regulator | 064-5 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0836 | BreakerAirMagnetic | SE-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0836 | BreakerAirMagnetic | SE-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0836 | BreakerAirMagnetic | SE-1 | AMCB Readings | 9 Months Operations | 3 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0836 | BreakerAirMagnetic | SE-1 | AMCB Readings | 9 Month Ops New | 3 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Readings | Amps A Ø | 380 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Readings | Accumulated Fault Duty C Ph V | 1.25 | % |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Readings | Accumulated Fault Duty B Ph V | 2.5 | % |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Readings | Accumulated Fault Duty A Ph V | 2.08 | % |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Readings | 9 Month Operations | 1 | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | LTCC000771 | LTCControl | 727-1 | LTC Control Insp | All Connections OK? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | LTCC000771 | LTCControl | 727-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | LTCC000771 | LTCControl | 727-1 | LTC Control Insp | General Comments | | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | LTCC000771 | LTCControl | 727-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | LTCC000771 | LTCControl | 727-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | LTCC000771 | LTCControl | 727-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | LTCC000771 | LTCControl | 727-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | LTCC000771 | LTCControl | 727-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | LTCC000771 | LTCControl | 727-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | ST000318 | Structure | 683-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | ST000318 | Structure | 683-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | YD000311 | Yard | 683-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | YD000311 | Yard | 683-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | YD000311 | Yard | 683-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | YD000311 | Yard | 683-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | YD000311 | Yard | 683-Yard | Yard Patrol Inspection | General Comments | | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | YD000311 | Yard | 683-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | BAT001454 | Battery | 681-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | BAT001454 | Battery | 681-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | BAT001454 | Battery | 681-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | BAT001454 | Battery | 681-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | BAT001454 | Battery | 681-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 36 | °F |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | BCH001229 | Charger | SE-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | BCH001229 | Charger | SE-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0837 | BreakerAirMagnetic | SE-2 | AMCB Readings | Unknown Operations | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0837 | BreakerAirMagnetic | SE-2 | AMCB Readings | Switching Operations | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0837 | BreakerAirMagnetic | SE-2 | AMCB Readings | Operations This Read AM | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0837 | BreakerAirMagnetic | SE-2 | AMCB Readings | Operations Counter AL | 317 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0837 | BreakerAirMagnetic | SE-2 | AMCB Readings | Operations Counter AF | 317 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0837 | BreakerAirMagnetic | SE-2 | AMCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0837 | BreakerAirMagnetic | SE-2 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0837 | BreakerAirMagnetic | SE-2 | AMCB Readings | General Comments | | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0837 | BreakerAirMagnetic | SE-2 | AMCB Patrol Inspection | General Comments | | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0837 | BreakerAirMagnetic | SE-2 | AMCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0837 | BreakerAirMagnetic | SE-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0837 | BreakerAirMagnetic | SE-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0837 | BreakerAirMagnetic | SE-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0837 | BreakerAirMagnetic | SE-2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0837 | BreakerAirMagnetic | SE-2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0837 | BreakerAirMagnetic | SE-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0837 | BreakerAirMagnetic | SE-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Readings | Switching Operations | 1 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0837 | BreakerAirMagnetic | SE-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0837 | BreakerAirMagnetic | SE-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0837 | BreakerAirMagnetic | SE-2 | AMCB Readings | Amps C Ø | 140.0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0837 | BreakerAirMagnetic | SE-2 | AMCB Readings | Amps B Ø | 100.0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0837 | BreakerAirMagnetic | SE-2 | AMCB Readings | Amps A Ø | 180.0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | BAT001454 | Battery | 681-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Readings | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | BAT001286 | Battery | SE-Battery Bank | Battery Patrol Inspection | Battery Bank Volts | 26.7 | VDC |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | BAT001286 | Battery | SE-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | FE000307 | Fence | 683-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | FE000307 | Fence | 683-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | FE000307 | Fence | 683-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | BAT001286 | Battery | SE-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | BAT001286 | Battery | SE-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | BAT001286 | Battery | SE-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Readings | 9 Month Operations | 4 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Readings | Operations Counter AF | 181 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Readings | Operations Counter AL | 182 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Readings | 9 Month Operations | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Readings | Amps A Ø | 55.0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Readings | Amps B Ø | 40.0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Readings | Amps C Ø | 85.0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Readings | Operations This Read Vac | 1 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Readings | Switching Operations | 1 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0116 | BreakerVacuum | 799-2469 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | BCH001229 | Charger | SE-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | BCH001229 | Charger | SE-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.7 | VDC |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | BCH001229 | Charger | SE-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.7 | VDC |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | BCH001229 | Charger | SE-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 0.0 | amps |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | BAT001454 | Battery | 681-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | BAT001454 | Battery | 681-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | BAT001454 | Battery | 681-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.2 | VDC |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | BAT001454 | Battery | 681-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27 | VDC |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | BAT001454 | Battery | 681-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | BAT001454 | Battery | 681-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | BAT001454 | Battery | 681-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Readings | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Readings | Operations Counter AF | 272 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Readings | Operations Counter AL | 273 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Readings | Operations This Read Vac | 1 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Readings | Switching Operations | 1 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0847 | Regulator | 064-5 B | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0847 | Regulator | 064-5 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000150 | Regulator | 798-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000150 | Regulator | 798-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000150 | Regulator | 798-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000150 | Regulator | 798-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000150 | Regulator | 798-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000150 | Regulator | 798-1 C | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000150 | Regulator | 798-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000150 | Regulator | 798-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0847 | Regulator | 064-5 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0847 | Regulator | 064-5 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000150 | Regulator | 798-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000150 | Regulator | 798-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000150 | Regulator | 798-1 C | Regulator Patrol Inspection | General Comments | | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000150 | Regulator | 798-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000150 | Regulator | 798-1 C | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000150 | Regulator | 798-1 C | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000150 | Regulator | 798-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000150 | Regulator | 798-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000150 | Regulator | 798-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000150 | Regulator | 798-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000150 | Regulator | 798-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000150 | Regulator | 798-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 6700 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000150 | Regulator | 798-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000150 | Regulator | 798-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000150 | Regulator | 798-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0847 | Regulator | 064-5 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0847 | Regulator | 064-5 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000150 | Regulator | 798-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0847 | Regulator | 064-5 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.8 | volts |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0847 | Regulator | 064-5 B | Regulator Patrol Inspection | Regulator As Left Counter | 125284 | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0847 | Regulator | 064-5 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0847 | Regulator | 064-5 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0836 | BreakerAirMagnetic | SE-1 | AMCB Readings | Amps A Ø | 50.0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0836 | BreakerAirMagnetic | SE-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | FE000458 | Fence | 681-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | FE000458 | Fence | 681-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | FE000458 | Fence | 681-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Readings | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Readings | Operations Counter AL | 256 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Readings | Operations This Read Vac | 1 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Readings | Switching Operations | 1 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0007 | BreakerVacuum | 799-2476 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0836 | BreakerAirMagnetic | SE-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0836 | BreakerAirMagnetic | SE-1 | AMCB Readings | Amps C Ø | 10.0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0836 | BreakerAirMagnetic | SE-1 | AMCB Readings | Amps B Ø | 10.0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Readings | 9 Month Operations | 1 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Readings | Amps A Ø | 0 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Readings | Amps C Ø | 110.0 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Readings | Amps B Ø | 80.0 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Readings | Amps A Ø | 105.0 | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0847 | Regulator | 064-5 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Readings | Amps B Ø | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Readings | Amps C Ø | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0009 | BreakerVacuum | 799-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.0 | volts |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 7104 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | FE000458 | Fence | 681-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | FE000458 | Fence | 681-Fence | Fence Patrol Inspection | General Comments | | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | FE000458 | Fence | 681-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | ST000318 | Structure | 683-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | ST000318 | Structure | 683-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | ST000318 | Structure | 683-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | ST000318 | Structure | 683-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | ST000318 | Structure | 683-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | ST000318 | Structure | 683-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000151 | Regulator | 798-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | FE000458 | Fence | 681-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | YD000464 | Yard | 681-Yard | Yard Patrol Inspection | Ambient Temp | 36 | °F |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | YD000464 | Yard | 681-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | YD000464 | Yard | 681-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | YD000464 | Yard | 681-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | YD000464 | Yard | 681-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | YD000464 | Yard | 681-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | YD000464 | Yard | 681-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | YD000464 | Yard | 681-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | YD000464 | Yard | 681-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | YD000464 | Yard | 681-Yard | Yard Patrol Inspection | General Comments | | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | YD000464 | Yard | 681-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | YD000464 | Yard | 681-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | YD000464 | Yard | 681-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | YD000464 | Yard | 681-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | ST000318 | Structure | 683-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | ST000318 | Structure | 683-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | ST000318 | Structure | 683-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | ST000318 | Structure | 683-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | ST000318 | Structure | 683-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | ST000318 | Structure | 683-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0848 | Regulator | 064-5 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | KB0081 | BreakerVacuum | 798-0611 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | ST000318 | Structure | 683-Structure | Structure Patrol Inspection | General Comments | | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | ST000318 | Structure | 683-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | ST000318 | Structure | 683-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | ST000318 | Structure | 683-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | ST000318 | Structure | 683-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | ST000318 | Structure | 683-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | ST000318 | Structure | 683-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | ST000318 | Structure | 683-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0847 | Regulator | 064-5 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | R0847 | Regulator | 064-5 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | FE000458 | Fence | 681-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | FE000458 | Fence | 681-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | FE000458 | Fence | 681-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | FE000458 | Fence | 681-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | FE000458 | Fence | 681-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | FE000458 | Fence | 681-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | FE000458 | Fence | 681-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | FE000458 | Fence | 681-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | FE000458 | Fence | 681-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Current Tap Position | 2R | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Min Tap Position | 4L | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 6044 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000182 | Regulator | 798-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000151 | Regulator | 798-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000151 | Regulator | 798-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000151 | Regulator | 798-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000151 | Regulator | 798-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000151 | Regulator | 798-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000151 | Regulator | 798-1 A | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000151 | Regulator | 798-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000151 | Regulator | 798-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000151 | Regulator | 798-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000151 | Regulator | 798-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000151 | Regulator | 798-1 A | Regulator Patrol Inspection | General Comments | | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000151 | Regulator | 798-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000151 | Regulator | 798-1 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000151 | Regulator | 798-1 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000151 | Regulator | 798-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000151 | Regulator | 798-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000151 | Regulator | 798-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000151 | Regulator | 798-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000151 | Regulator | 798-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000151 | Regulator | 798-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 6044 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000151 | Regulator | 798-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000151 | Regulator | 798-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | RG000151 | Regulator | 798-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | CX0108 | RecloserElectronic | 611-2433 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | CX0108 | RecloserElectronic | 611-2433 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | CX0108 | RecloserElectronic | 611-2433 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | CX0108 | RecloserElectronic | 611-2433 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | CX0108 | RecloserElectronic | 611-2433 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | CX0108 | RecloserElectronic | 611-2433 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | CX0108 | RecloserElectronic | 611-2433 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | CX0108 | RecloserElectronic | 611-2433 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0838 | BreakerAirMagnetic | SE-3 | AMCB Readings | Switching Operations | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0838 | BreakerAirMagnetic | SE-3 | AMCB Readings | Operations This Read AM | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0838 | BreakerAirMagnetic | SE-3 | AMCB Readings | Operations Counter AL | 451 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0838 | BreakerAirMagnetic | SE-3 | AMCB Readings | Operations Counter AF | 451 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0838 | BreakerAirMagnetic | SE-3 | AMCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0838 | BreakerAirMagnetic | SE-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0838 | BreakerAirMagnetic | SE-3 | AMCB Readings | General Comments | | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0838 | BreakerAirMagnetic | SE-3 | AMCB Patrol Inspection | General Comments | | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0838 | BreakerAirMagnetic | SE-3 | AMCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0838 | BreakerAirMagnetic | SE-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0838 | BreakerAirMagnetic | SE-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0838 | BreakerAirMagnetic | SE-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0838 | BreakerAirMagnetic | SE-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0838 | BreakerAirMagnetic | SE-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0838 | BreakerAirMagnetic | SE-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0838 | BreakerAirMagnetic | SE-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0838 | BreakerAirMagnetic | SE-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000084 | Switchgear | SE-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000084 | Switchgear | SE-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BAT001226 | Battery | 406-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BAT001226 | Battery | 406-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BAT001226 | Battery | 406-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | CX0108 | RecloserElectronic | 611-2433 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | CX0108 | RecloserElectronic | 611-2433 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | CX0108 | RecloserElectronic | 611-2433 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | CX0108 | RecloserElectronic | 611-2433 | Recloser Electronic Patrol Inspection | Amps C Ø | 105 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | CX0108 | RecloserElectronic | 611-2433 | Recloser Electronic Patrol Inspection | Amps B Ø | 102 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BAT001226 | Battery | 406-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BAT001226 | Battery | 406-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000084 | Switchgear | SE-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BAT001226 | Battery | 406-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BAT001226 | Battery | 406-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BAT001226 | Battery | 406-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BAT001226 | Battery | 406-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BAT001226 | Battery | 406-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BAT001226 | Battery | 406-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BAT001226 | Battery | 406-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BAT001226 | Battery | 406-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BAT001226 | Battery | 406-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 35 | °F |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BAT001226 | Battery | 406-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000084 | Switchgear | SE-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0838 | BreakerAirMagnetic | SE-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | CX0108 | RecloserElectronic | 611-2433 | Recloser Electronic Patrol Inspection | Amps A Ø | 115 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0838 | BreakerAirMagnetic | SE-3 | AMCB Readings | Amps C Ø | 170.0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0838 | BreakerAirMagnetic | SE-3 | AMCB Readings | Amps B Ø | 140.0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0838 | BreakerAirMagnetic | SE-3 | AMCB Readings | Amps A Ø | 250.0 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Readings | Fault Operations C Ø | 1 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Readings | Fault Adjusted Amps C Phase V | 2.94 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Readings | Amps C Ø | 120.0 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Readings | Amps B Ø | 105.0 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Readings | Amps A Ø | 95.0 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Readings | 9 Month Operations | 8 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Readings | General Comments | | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Readings | Operations Counter AF | 171 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Readings | Operations Counter AL | 171 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Readings | Operations This Read Vac | 0 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Readings | Switching Operations | 0 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 200.00 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0838 | BreakerAirMagnetic | SE-3 | AMCB Readings | Unknown Operations | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | CX0108 | RecloserElectronic | 611-2433 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | CX0108 | RecloserElectronic | 611-2433 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | CX0108 | RecloserElectronic | 611-2433 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | CX0108 | RecloserElectronic | 611-2433 | Recloser Electronic Patrol Inspection | Operations Counter | 44 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | CX0108 | RecloserElectronic | 611-2433 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | CX0108 | RecloserElectronic | 611-2433 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0839 | BreakerAirMagnetic | SE-4 | AMCB Readings | Amps A Ø | 140.0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0839 | BreakerAirMagnetic | SE-4 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0839 | BreakerAirMagnetic | SE-4 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0839 | BreakerAirMagnetic | SE-4 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CH000351 | ControlHouse | 799-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CH000351 | ControlHouse | 799-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CH000351 | ControlHouse | 799-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CH000351 | ControlHouse | 799-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CH000351 | ControlHouse | 799-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CH000351 | ControlHouse | 799-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CH000351 | ControlHouse | 799-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CH000351 | ControlHouse | 799-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CH000351 | ControlHouse | 799-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CH000351 | ControlHouse | 799-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CH000351 | ControlHouse | 799-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CH000351 | ControlHouse | 799-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CH000351 | ControlHouse | 799-Control House | Control House Patrol Inspection | General Comments | | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0839 | BreakerAirMagnetic | SE-4 | AMCB Readings | 9 Months Operations | 1 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0839 | BreakerAirMagnetic | SE-4 | AMCB Readings | 9 Month Ops New | 1 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BCH001379 | Charger | 683-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.3 | amps |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BCH001379 | Charger | 683-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BCH001379 | Charger | 683-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BCH001473 | Charger | 611-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BCH001473 | Charger | 611-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BCH001473 | Charger | 611-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BCH001473 | Charger | 611-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BCH001473 | Charger | 611-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2 | amps |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BCH001473 | Charger | 611-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BCH001473 | Charger | 611-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BCH001473 | Charger | 611-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0 | millivolts |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | LTCMechanism | SE-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | LTCMechanism | SE-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | LTCMechanism | SE-TRANS 2 | LTC Counter Readings | General Comments | | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | LTCMechanism | SE-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CH000351 | ControlHouse | 799-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CH000351 | ControlHouse | 799-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CH000351 | ControlHouse | 799-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CH000351 | ControlHouse | 799-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CH000351 | ControlHouse | 799-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | LTCMechanism | SE-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 227951 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | LTCMechanism | SE-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 227951 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | LTCMechanism | SE-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | LTCMechanism | SE-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | LTCMechanism | SE-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | LTCMechanism | SE-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | LTCMechanism | SE-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | LTCMechanism | SE-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 213 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | LTCMechanism | SE-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | LTCMechanism | SE-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | LTCMechanism | SE-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | LTCMechanism | SE-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Readings | 9 Month Operations | 2 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Readings | Accumulated Fault Duty A Ph V | 2.03 | % |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Readings | Accumulated Fault Duty B Ph V | 2.44 | % |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0838 | BreakerAirMagnetic | SE-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0838 | BreakerAirMagnetic | SE-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0838 | BreakerAirMagnetic | SE-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0838 | BreakerAirMagnetic | SE-3 | AMCB Readings | 9 Months Operations | 1 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0838 | BreakerAirMagnetic | SE-3 | AMCB Readings | 9 Month Ops New | 1 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000084 | Switchgear | SE-Swgr Sec 1 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000084 | Switchgear | SE-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000084 | Switchgear | SE-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000084 | Switchgear | SE-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000084 | Switchgear | SE-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000084 | Switchgear | SE-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000084 | Switchgear | SE-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000084 | Switchgear | SE-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | BAT001155 | Battery | SSC-Distribution Maint. | Battery Patrol Inspection | General Comments | not at shop | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | BAT001155 | Battery | SSC-Distribution Maint. | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | BAT001155 | Battery | SSC-Distribution Maint. | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | BAT001155 | Battery | SSC-Distribution Maint. | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | BAT001155 | Battery | SSC-Distribution Maint. | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000084 | Switchgear | SE-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000084 | Switchgear | SE-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000084 | Switchgear | SE-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000084 | Switchgear | SE-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000084 | Switchgear | SE-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000084 | Switchgear | SE-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000084 | Switchgear | SE-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000084 | Switchgear | SE-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | BAT001154 | Battery | SSC-Distribution Maint. | Battery Patrol Inspection | General Comments | not at shop | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | BAT001154 | Battery | SSC-Distribution Maint. | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | BAT001154 | Battery | SSC-Distribution Maint. | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | BAT001154 | Battery | SSC-Distribution Maint. | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BCH001379 | Charger | 683-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BCH001379 | Charger | 683-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BCH001379 | Charger | 683-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0839 | BreakerAirMagnetic | SE-4 | AMCB Readings | Unknown Operations | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0839 | BreakerAirMagnetic | SE-4 | AMCB Readings | Switching Operations | 0 | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | BAT001154 | Battery | SSC-Distribution Maint. | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0839 | BreakerAirMagnetic | SE-4 | AMCB Readings | Operations This Read AM | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0839 | BreakerAirMagnetic | SE-4 | AMCB Readings | Operations Counter AL | 346 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0839 | BreakerAirMagnetic | SE-4 | AMCB Readings | Operations Counter AF | 346 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0839 | BreakerAirMagnetic | SE-4 | AMCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0839 | BreakerAirMagnetic | SE-4 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0839 | BreakerAirMagnetic | SE-4 | AMCB Readings | General Comments | | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0839 | BreakerAirMagnetic | SE-4 | AMCB Patrol Inspection | General Comments | | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0839 | BreakerAirMagnetic | SE-4 | AMCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0839 | BreakerAirMagnetic | SE-4 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0839 | BreakerAirMagnetic | SE-4 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0839 | BreakerAirMagnetic | SE-4 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0839 | BreakerAirMagnetic | SE-4 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0839 | BreakerAirMagnetic | SE-4 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0839 | BreakerAirMagnetic | SE-4 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0839 | BreakerAirMagnetic | SE-4 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0839 | BreakerAirMagnetic | SE-4 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0839 | BreakerAirMagnetic | SE-4 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0839 | BreakerAirMagnetic | SE-4 | AMCB Readings | Amps C Ø | 240.0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0839 | BreakerAirMagnetic | SE-4 | AMCB Readings | Amps B Ø | 180.0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Readings | Amps C Ø | 360 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Readings | Amps B Ø | 360 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Readings | Amps A Ø | 360 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Readings | Accumulated Fault Duty C Ph V | 2.44 | % |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Readings | Accumulated Fault Duty B Ph V | 2.85 | % |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Readings | Accumulated Fault Duty A Ph V | 2.44 | % |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Readings | LTC Totalizer Reading | 7032.96 | kw |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -1.0 | psi |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | LTCMechanism | SE-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 213 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Readings | 9 Month Operations | 2 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Readings | 9 Month Operations | 5 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Readings | Amps A Ø | 125.0 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Readings | Amps B Ø | 160.0 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Readings | Amps C Ø | 205.0 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | YD000513 | Yard | 799-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Readings | General Comments | | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | LTCMechanism | SE-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | LTCMechanism | SE-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | LTCMechanism | SE-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | LTCMechanism | SE-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Readings | General Comments | | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Readings | LTC Totalizer Reading | 3984 | kw |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Readings | Switching Operations | 2 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Readings | Operations This Read Vac | 2 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Readings | Operations Counter AL | 287 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Readings | Operations Counter AF | 285 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Readings | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Readings | Oil Temp Max | 65 | °C |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0295 | BreakerVacuum | 799-2468 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Readings | Winding Temp Max | 0 | °C |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Readings | Winding Temp Present | 0 | °C |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | LTCMechanism | SE-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | BCH001362 | Charger | 681-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | BCH001362 | Charger | 681-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | BCH001362 | Charger | 681-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | BCH001362 | Charger | 681-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | BCH001362 | Charger | 681-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.6 | amps |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | BCH001362 | Charger | 681-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | BCH001362 | Charger | 681-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | BCH001362 | Charger | 681-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0 | millivolts |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | LTCMechanism | SE-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Readings | Amps A Ø | 170.0 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Readings | Amps B Ø | 190.0 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Readings | Amps C Ø | 165.0 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | CH000443 | ControlHouse | SE-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | CH000443 | ControlHouse | SE-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | CH000443 | ControlHouse | SE-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | CH000443 | ControlHouse | SE-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | CH000443 | ControlHouse | SE-Battery Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | CH000443 | ControlHouse | SE-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | CH000443 | ControlHouse | SE-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | CH000443 | ControlHouse | SE-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | CH000443 | ControlHouse | SE-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BCH001175 | Charger | 406-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BCH001175 | Charger | 406-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BCH001175 | Charger | 406-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BCH001175 | Charger | 406-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.1 | amps |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Readings | Switching Operations | 1 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BCH001175 | Charger | 406-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BCH001175 | Charger | 406-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BCH001175 | Charger | 406-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BCH001175 | Charger | 406-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Readings | Operations This Read Vac | 2 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Readings | Operations Counter AL | 258 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Readings | Operations Counter AF | 256 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Readings | General Comments | | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK000251 | BreakerVacuum | 406-0616 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | YD000513 | Yard | 799-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | YD000513 | Yard | 799-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | WithLTC | 406-1 | LTC Transformer Readings | Totalizer Meter Reading | .9768 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | YD000513 | Yard | 799-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Readings | General Comments | | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Readings | Operations Counter AF | 206 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | YD000513 | Yard | 799-Yard | Yard Patrol Inspection | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | YD000513 | Yard | 799-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | YD000513 | Yard | 799-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | YD000513 | Yard | 799-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | YD000513 | Yard | 799-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | YD000513 | Yard | 799-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | YD000513 | Yard | 799-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | YD000513 | Yard | 799-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | YD000513 | Yard | 799-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Readings | Operations Counter AL | 208 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Readings | Operations This Read Vac | 2 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Readings | Switching Operations | 2 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | BK001566 | BreakerVacuum | 406-0617 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BK001567 | BreakerVacuum | 798-0610 | VCB Readings | 9 Month Operations | 1 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | YD000513 | Yard | 799-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | YD000513 | Yard | 799-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | LTCMechanism | SE-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | LTCMechanism | SE-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | LTCMechanism | SE-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 7L | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | LTCMechanism | SE-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | LTCMechanism | SE-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | LTCMechanism | SE-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 323736 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | LTCMechanism | SE-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 323736 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | LTCMechanism | SE-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | LTCMechanism | SE-TRANS 1 | LTC Counter Readings | General Comments | | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Readings | Totalizer Meter Reading | .83 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0836 | BreakerAirMagnetic | SE-1 | AMCB Patrol Inspection | General Comments | | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0836 | BreakerAirMagnetic | SE-1 | AMCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0836 | BreakerAirMagnetic | SE-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0836 | BreakerAirMagnetic | SE-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0836 | BreakerAirMagnetic | SE-1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | BCH001159 | Charger | 799-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0 | millivolts |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | BCH001159 | Charger | 799-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.3 | VDC |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | BCH001159 | Charger | 799-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.3 | VDC |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | BCH001159 | Charger | 799-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.6 | amps |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | BCH001159 | Charger | 799-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | BCH001159 | Charger | 799-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | BCH001159 | Charger | 799-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | BCH001159 | Charger | 799-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | BAT001212 | Battery | 799-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | BAT001212 | Battery | 799-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | BAT001212 | Battery | 799-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | BAT001212 | Battery | 799-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | BAT001212 | Battery | 799-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | BAT001212 | Battery | 799-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | BAT001212 | Battery | 799-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | BAT001212 | Battery | 799-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | BAT001212 | Battery | 799-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | BAT001212 | Battery | 799-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | BAT001212 | Battery | 799-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 24.4 | VDC |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | BAT001212 | Battery | 799-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.8 | VDC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | BAT001212 | Battery | 799-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | BAT001212 | Battery | 799-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Readings | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Readings | Operations Counter AF | 99947 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Readings | Operations Counter AL | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | LTCC000936 | LTCControl | 683-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | LTCC000936 | LTCControl | 683-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | LTCC000936 | LTCControl | 683-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | LTCC000936 | LTCControl | 683-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | LTCC000936 | LTCControl | 683-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | LTCC000936 | LTCControl | 683-2 | LTC Control Insp | General Comments | | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | RC901734 | RecloserElectronic | 727-0612 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | RC901734 | RecloserElectronic | 727-0612 | Recloser Electronic Patrol Inspection | Operations Counter | 18 | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | RC901734 | RecloserElectronic | 727-0612 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | RC901734 | RecloserElectronic | 727-0612 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | RC901734 | RecloserElectronic | 727-0612 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | RC901734 | RecloserElectronic | 727-0612 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | RC901734 | RecloserElectronic | 727-0612 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | RC901734 | RecloserElectronic | 727-0612 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | RC901734 | RecloserElectronic | 727-0612 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | YD000391 | Yard | 406-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Readings | Totalizer Meter Reading | .8574 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Readings | Winding Temp Max | 60 | °C |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Readings | Winding Temp Present | 55 | °C |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | YD000391 | Yard | 406-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | YD000391 | Yard | 406-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | YD000391 | Yard | 406-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | YD000391 | Yard | 406-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Readings | 9 Month Operations | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Readings | Amps A Ø | 600 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Readings | Amps B Ø | 600 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Readings | Amps C Ø | 600 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | YD000391 | Yard | 406-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | YD000391 | Yard | 406-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Readings | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Readings | Operations Counter AF | 99957 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Readings | Operations Counter AL | 99957 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Readings | Operations This Read Vac | 2 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Readings | Switching Operations | 2 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Readings | Unknown Operations | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0836 | BreakerAirMagnetic | SE-1 | AMCB Readings | Operations This Read AM | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0836 | BreakerAirMagnetic | SE-1 | AMCB Readings | Operations Counter AL | 436 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0836 | BreakerAirMagnetic | SE-1 | AMCB Readings | Operations Counter AF | 436 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | YD000391 | Yard | 406-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | YD000391 | Yard | 406-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | YD000391 | Yard | 406-Yard | Yard Patrol Inspection | Ambient Temp | 32 | °F |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | FE000387 | Fence | 406-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0836 | BreakerAirMagnetic | SE-1 | AMCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0836 | BreakerAirMagnetic | SE-1 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0836 | BreakerAirMagnetic | SE-1 | AMCB Readings | General Comments | | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Readings | Switching Operations | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Readings | Operations This Read Vac | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Readings | Operations Counter AL | 172 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Readings | Operations Counter AF | 172 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Readings | Switching Operations | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0263 | BreakerVacuum | 799-1 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Readings | General Comments | | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | LTCMechanism | 799-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | LTCMechanism | 799-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Readings | General Comments | | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0008 | BreakerVacuum | 799-2473 | VCB Readings | Switching Operations | 1 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Readings | Amps C Ø | 85.0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Readings | Amps B Ø | 70.0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Readings | Amps A Ø | 90.0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Readings | 9 Month Operations | 0 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | YD000290 | Yard | 798-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | RC901734 | RecloserElectronic | 727-0612 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | RC901734 | RecloserElectronic | 727-0612 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | RC901734 | RecloserElectronic | 727-0612 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | RC901734 | RecloserElectronic | 727-0612 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | RC901734 | RecloserElectronic | 727-0612 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | RC901734 | RecloserElectronic | 727-0612 | Recloser Electronic Patrol Inspection | Amps C Ø | 75.0 | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | RC901734 | RecloserElectronic | 727-0612 | Recloser Electronic Patrol Inspection | Amps B Ø | 75.0 | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | RC901734 | RecloserElectronic | 727-0612 | Recloser Electronic Patrol Inspection | Amps A Ø | 65.0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | LTCC000936 | LTCControl | 683-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | LTCC000936 | LTCControl | 683-2 | LTC Control Insp | All Connections OK? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Readings | Switching Operations | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Readings | Operations This Read Vac | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Readings | Operations Counter AL | 163 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Readings | Operations Counter AF | 163 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Readings | General Comments | | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Readings | Amps C Ø | 75.0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Readings | Amps B Ø | 70.0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Readings | Amps A Ø | 130.0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001397 | BreakerVacuum | 683-0619 | VCB Readings | 9 Month Operations | 1 | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0264 | GroundTransformer | SSC-Offline-Distribution | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0264 | GroundTransformer | SSC-Offline-Distribution | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0264 | GroundTransformer | SSC-Offline-Distribution | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0264 | GroundTransformer | SSC-Offline-Distribution | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0264 | GroundTransformer | SSC-Offline-Distribution | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0264 | GroundTransformer | SSC-Offline-Distribution | Ground Transformer Patrol Inspection | General Comments | | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0264 | GroundTransformer | SSC-Offline-Distribution | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0264 | GroundTransformer | SSC-Offline-Distribution | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001396 | BreakerVacuum | 683-0618 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | LTCMechanism | 611-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | LTCMechanism | 611-1 | LTC Counter Readings | LTC Operations Since Last Insp | 593 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | LTCMechanism | 611-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 35 | °C |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | LTCMechanism | 611-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 45 | °C |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | LTCMechanism | 611-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | LTCMechanism | 611-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1 | psi |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | LTCMechanism | 611-1 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | LTCMechanism | 611-1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | LTCMechanism | 611-1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | LTCMechanism | 611-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | LTCMechanism | 611-1 | LTC Counter Readings | LTC As Left Counter | 137945 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | LTCMechanism | 611-1 | LTC Counter Readings | LTC As Found Counter | 137940 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | LTCMechanism | 611-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | LTCMechanism | 611-1 | LTC Counter Readings | General Comments | | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | LTCMechanism | 611-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | LTCMechanism | 611-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0 | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0070 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0070 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0070 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0070 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Readings | Accumulated Fault Duty A Ph V | .96 | % |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Readings | Accumulated Fault Duty B Ph V | .96 | % |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Readings | Accumulated Fault Duty C Ph V | 1.29 | % |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Readings | Amps A Ø | 54 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Readings | Amps B Ø | 60 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | LTCMechanism | 799-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | LTCMechanism | 799-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | LTCMechanism | 799-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | LTCMechanism | 799-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | LTCMechanism | 799-1 | LTC Counter Readings | LTC Operations Since Last Insp | 430 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | LTCMechanism | 799-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 30 | °C |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | LTCMechanism | 799-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 35 | °C |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | LTCMechanism | 799-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1 | psi |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | LTCMechanism | 799-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | LTCMechanism | 799-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | LTCMechanism | 799-1 | LTC Counter Readings | LTC Current Tap Position | 3R | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | LTCMechanism | 799-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | LTCMechanism | 799-1 | LTC Counter Readings | LTC As Left Counter | 59612 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | LTCMechanism | 799-1 | LTC Counter Readings | LTC As Found Counter | 59609 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | LTCMechanism | 799-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | LTCMechanism | 799-1 | LTC Counter Readings | General Comments | | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Readings | Amps C Ø | 62 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Readings | Accumulated Fault Duty C Ph V | 2.03 | % |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BCH001379 | Charger | 683-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BCH001379 | Charger | 683-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | WithLTC | 681-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Readings | Amps A Ø | 270 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Readings | Amps B Ø | 270 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Readings | Amps C Ø | 180 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Readings | Winding Temp Present | 20 | °C |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Readings | Winding Temp Max | 40 | °C |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Readings | Totalizer Meter Reading | .7866 | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | CB0294 | BreakerVacuum | 799-2474 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Readings | 9 Month Operations | 8 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0 | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5 | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | TX000057 | NonLTC | 064-5 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1887.84 | kw |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | LTCMechanism | 611-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | LTCMechanism | 611-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | LTCMechanism | 611-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | YD000574 | Yard | SE-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | YD000574 | Yard | SE-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | YD000574 | Yard | SE-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0178 | NonLTC | SSC-PORT TRANS 1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | ST000394 | Structure | 406-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | ST000394 | Structure | 406-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | ST000394 | Structure | 406-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | ST000394 | Structure | 406-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | ST000394 | Structure | 406-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | ST000394 | Structure | 406-Structure | Structure Patrol Inspection | General Comments | | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | ST000394 | Structure | 406-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | ST000394 | Structure | 406-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | ST000394 | Structure | 406-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | ST000394 | Structure | 406-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | ST000394 | Structure | 406-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | ST000394 | Structure | 406-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | ST000394 | Structure | 406-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | ST000394 | Structure | 406-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | ST000394 | Structure | 406-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | YD000391 | Yard | 406-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | YD000391 | Yard | 406-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | YD000391 | Yard | 406-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | YD000391 | Yard | 406-Yard | Yard Patrol Inspection | General Comments | | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | YD000574 | Yard | SE-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | YD000574 | Yard | SE-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | YD000574 | Yard | SE-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | YD000574 | Yard | SE-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | YD000574 | Yard | SE-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | YD000574 | Yard | SE-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | YD000574 | Yard | SE-Yard | Yard Patrol Inspection | General Comments | | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | YD000574 | Yard | SE-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | YD000574 | Yard | SE-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | YD000574 | Yard | SE-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | YD000574 | Yard | SE-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | YD000574 | Yard | SE-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | YD000574 | Yard | SE-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | YD000574 | Yard | SE-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | YD000574 | Yard | SE-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | YD000574 | Yard | SE-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | FE000564 | Fence | SE-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | FE000564 | Fence | SE-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | FE000564 | Fence | SE-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | FE000564 | Fence | SE-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | FE000564 | Fence | SE-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | FE000564 | Fence | SE-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | FE000564 | Fence | SE-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | FE000564 | Fence | SE-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | FE000564 | Fence | SE-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | FE000564 | Fence | SE-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | FE000564 | Fence | SE-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | FE000564 | Fence | SE-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | FE000564 | Fence | SE-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | FE000564 | Fence | SE-Fence | Fence Patrol Inspection | General Comments | | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | FE000564 | Fence | SE-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | FE000564 | Fence | SE-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000386 | BreakerVacuum | 611-2435 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0070 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0070 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0070 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0070 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0070 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0070 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0070 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Readings | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Readings | LTC Totalizer Reading | 15433.2 | kw |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0836 | BreakerAirMagnetic | SE-1 | AMCB Readings | Unknown Operations | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0836 | BreakerAirMagnetic | SE-1 | AMCB Readings | Switching Operations | 0 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | ST000394 | Structure | 406-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | ST000394 | Structure | 406-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | ST000394 | Structure | 406-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | ST000394 | Structure | 406-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | ST000394 | Structure | 406-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | ST000394 | Structure | 406-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 4 | psi |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Readings | Oil Temp Max | 70 | °C |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Readings | Oil Temp Present | 60 | °C |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KT0012 | WithLTC | 799-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | ST000394 | Structure | 406-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | ST000394 | Structure | 406-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0178 | NonLTC | SSC-PORT TRANS 1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0313 | GroundTransformer | SSC-Offline-Distribution | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0313 | GroundTransformer | SSC-Offline-Distribution | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0313 | GroundTransformer | SSC-Offline-Distribution | Ground Transformer Patrol Inspection | General Comments | | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0313 | GroundTransformer | SSC-Offline-Distribution | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0313 | GroundTransformer | SSC-Offline-Distribution | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0313 | GroundTransformer | SSC-Offline-Distribution | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0313 | GroundTransformer | SSC-Offline-Distribution | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0313 | GroundTransformer | SSC-Offline-Distribution | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | YD000574 | Yard | SE-Yard | Yard Patrol Inspection | Ambient Temp | 33 | °F |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | LTCC000142 | LTCControl | 406-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | LTCC000142 | LTCControl | 406-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | LTCC000142 | LTCControl | 406-1 | LTC Control Insp | VRR Base Voltage AF | 123.0 | VAC |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | LTCC000142 | LTCControl | 406-1 | LTC Control Insp | VRR Base Voltage AL | 123.0 | VAC |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | LTCC000142 | LTCControl | 406-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000178 | Switchgear | SE-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000178 | Switchgear | SE-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000178 | Switchgear | SE-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000178 | Switchgear | SE-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000178 | Switchgear | SE-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Readings | General Comments | | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Readings | LTC Totalizer Reading | 5798.40 | kw |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000178 | Switchgear | SE-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000178 | Switchgear | SE-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000178 | Switchgear | SE-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000178 | Switchgear | SE-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000178 | Switchgear | SE-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000178 | Switchgear | SE-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000178 | Switchgear | SE-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000178 | Switchgear | SE-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000178 | Switchgear | SE-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000178 | Switchgear | SE-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000178 | Switchgear | SE-Swgr Sec 2 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000178 | Switchgear | SE-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000178 | Switchgear | SE-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000178 | Switchgear | SE-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Readings | 9 Month Operations | 5 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Readings | Accumulated Fault Duty C Ph V | .35 | % |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Readings | Amps A Ø | 123 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Readings | Amps B Ø | 126 | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN55 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN55 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN55 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN55 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Readings | 9 Month Operations | 1 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Readings | Amps A Ø | 64 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Readings | Amps B Ø | 47 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Readings | Amps C Ø | 56 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Readings | General Comments | | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Readings | Operations Counter AF | 172 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Readings | Operations Counter AL | 173 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Readings | Operations This Read Vac | 1 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Readings | Switching Operations | 1 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001797 | BreakerVacuum | 611-2436 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | LTCC000142 | LTCControl | 406-1 | LTC Control Insp | All Connections OK? | y | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | LTCC000142 | LTCControl | 406-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | LTCC000142 | LTCControl | 406-1 | LTC Control Insp | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | FE000508 | Fence | 799-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | FE000508 | Fence | 799-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | FE000508 | Fence | 799-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | FE000508 | Fence | 799-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | FE000508 | Fence | 799-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Readings | General Comments | | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Readings | Operations Counter AF | 184 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Readings | Operations Counter AL | 185 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Readings | Operations This Read Vac | 1 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Readings | Switching Operations | 1 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | FE000508 | Fence | 799-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | FE000508 | Fence | 799-Fence | Fence Patrol Inspection | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | FE000508 | Fence | 799-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | FE000508 | Fence | 799-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | ST000518 | Structure | 799-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | ST000518 | Structure | 799-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | ST000518 | Structure | 799-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | ST000518 | Structure | 799-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | ST000518 | Structure | 799-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | ST000518 | Structure | 799-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | ST000518 | Structure | 799-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | ST000518 | Structure | 799-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | ST000518 | Structure | 799-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | ST000518 | Structure | 799-Structure | Structure Patrol Inspection | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | ST000518 | Structure | 799-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | ST000518 | Structure | 799-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | ST000518 | Structure | 799-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | ST000518 | Structure | 799-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | ST000518 | Structure | 799-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | SWG000178 | Switchgear | SE-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0834 | RecloserHydraulic | 064-2401 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 120 | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0834 | RecloserHydraulic | 064-2401 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0 | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0834 | RecloserHydraulic | 064-2401 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0 | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0834 | RecloserHydraulic | 064-2401 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0 | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0834 | RecloserHydraulic | 064-2401 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 271 | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0834 | RecloserHydraulic | 064-2401 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | LTCC000788 | LTCControl | 681-1 | LTC Control Insp | All Connections OK? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | LTCC000788 | LTCControl | 681-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | LTCC000788 | LTCControl | 681-1 | LTC Control Insp | General Comments | | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | LTCC000788 | LTCControl | 681-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | LTCC000788 | LTCControl | 681-1 | LTC Control Insp | LTC Output Voltage Level | 125.1 | VAC |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | LTCC000788 | LTCControl | 681-1 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | LTCC000788 | LTCControl | 681-1 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | LTCC000788 | LTCControl | 681-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0834 | RecloserHydraulic | 064-2401 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0834 | RecloserHydraulic | 064-2401 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 290 | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0834 | RecloserHydraulic | 064-2401 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0834 | RecloserHydraulic | 064-2401 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0834 | RecloserHydraulic | 064-2401 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0834 | RecloserHydraulic | 064-2401 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0834 | RecloserHydraulic | 064-2401 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0834 | RecloserHydraulic | 064-2401 | Recloser Hydraulic Patrol Inspection | Operations Counter | 0 | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0834 | RecloserHydraulic | 064-2401 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0834 | RecloserHydraulic | 064-2401 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Readings | Amps C Ø | 127 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK000412 | BreakerVacuum | 611-2432 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | FE000508 | Fence | 799-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | FE000508 | Fence | 799-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | FE000508 | Fence | 799-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | FE000508 | Fence | 799-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | FE000508 | Fence | 799-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | FE000508 | Fence | 799-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | FE000508 | Fence | 799-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | General Comments | | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | Interruptrs/Puffrs Visual OK? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | MOD Cabinet Heater functional? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | MOD Cabinet Internals Clean? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | MOD Motor Jaw Coupling | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BAT001115 | Battery | 611-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BAT001115 | Battery | 611-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 33 | °F |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000261 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000261 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000261 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000261 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000261 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000261 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000261 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BAT001115 | Battery | 611-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BAT001115 | Battery | 611-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BAT001115 | Battery | 611-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BAT001115 | Battery | 611-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BAT001115 | Battery | 611-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | FE000430 | Fence | 611-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | FE000430 | Fence | 611-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | FE000430 | Fence | 611-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | FE000430 | Fence | 611-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | FE000430 | Fence | 611-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | FE000430 | Fence | 611-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | ST000467 | Structure | 681-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | ST000467 | Structure | 681-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | ST000467 | Structure | 681-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | ST000467 | Structure | 681-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | ST000467 | Structure | 681-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | ST000467 | Structure | 681-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | ST000467 | Structure | 681-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | ST000467 | Structure | 681-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | FE000430 | Fence | 611-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | FE000430 | Fence | 611-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | FE000430 | Fence | 611-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | FE000430 | Fence | 611-Fence | Fence Patrol Inspection | General Comments | | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | ST000467 | Structure | 681-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | ST000467 | Structure | 681-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | ST000467 | Structure | 681-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | FE000430 | Fence | 611-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | FE000430 | Fence | 611-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | YD000434 | Yard | 611-Yard | Yard Patrol Inspection | Ambient Temp | 33 | °F |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | YD000434 | Yard | 611-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | YD000434 | Yard | 611-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | YD000434 | Yard | 611-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | YD000434 | Yard | 611-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | YD000434 | Yard | 611-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | YD000434 | Yard | 611-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | YD000434 | Yard | 611-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | YD000434 | Yard | 611-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | YD000434 | Yard | 611-Yard | Yard Patrol Inspection | General Comments | | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | YD000434 | Yard | 611-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | YD000434 | Yard | 611-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | YD000434 | Yard | 611-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | YD000434 | Yard | 611-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | YD000434 | Yard | 611-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | YD000434 | Yard | 611-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | YD000434 | Yard | 611-Yard | Yard Patrol Inspection | Vegetation | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | YD000434 | Yard | 611-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | ST000437 | Structure | 611-Structure | Structure Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Readings | Amps A Ø | 166 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Readings | Amps B Ø | 171 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Readings | Amps C Ø | 167 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Readings | General Comments | | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Readings | Operations Counter AF | 190 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Readings | Operations Counter AL | 191 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Readings | Operations This Read Vac | 1 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Readings | Switching Operations | 1 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN55 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN55 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | BAT001118 | Battery | SSC-Distribution Maint. | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | BAT001118 | Battery | SSC-Distribution Maint. | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | BAT001118 | Battery | SSC-Distribution Maint. | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | BAT001118 | Battery | SSC-Distribution Maint. | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | BAT001118 | Battery | SSC-Distribution Maint. | Battery Patrol Inspection | General Comments | | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN55 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -1.0 | psi |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN55 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN55 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | nitro | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN55 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BAT001115 | Battery | 611-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BAT001115 | Battery | 611-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BAT001115 | Battery | 611-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BAT001115 | Battery | 611-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27 | VDC |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BAT001115 | Battery | 611-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.1 | VDC |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BAT001115 | Battery | 611-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BAT001115 | Battery | 611-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000261 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000261 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | FE000357 | Fence | 727-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000261 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000261 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000244 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000244 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000244 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000244 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000244 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000244 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000244 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000244 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000244 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000244 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000244 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | BAT001117 | Battery | SSC-Distribution Maint. | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | BAT001117 | Battery | SSC-Distribution Maint. | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | BAT001117 | Battery | SSC-Distribution Maint. | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | BAT001117 | Battery | SSC-Distribution Maint. | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | BAT001117 | Battery | SSC-Distribution Maint. | Battery Patrol Inspection | General Comments | | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | PN55 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Readings | 9 Month Operations | 3 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | BK001796 | BreakerVacuum | 611-2434 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0183 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0183 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Readings | Totalizer Meter Reading | .534 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | LTCMechanism | 681-1 | LTC Counter Readings | LTC Operations Since Last Insp | 456 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | LTCMechanism | 681-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0 | psi |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | LTCMechanism | 681-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | LTCMechanism | 681-1 | LTC Counter Readings | LTC Max Tap Position | 5R | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | LTCMechanism | 681-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | LTCMechanism | 681-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | LTCMechanism | 681-1 | LTC Counter Readings | LTC As Left Counter | 28617 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | LTCMechanism | 681-1 | LTC Counter Readings | LTC As Found Counter | 28613 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | LTCMechanism | 681-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | LTCMechanism | 681-1 | LTC Counter Readings | General Comments | | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | LTCMechanism | 681-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | LTCMechanism | 681-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BCH001404 | Charger | 798-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BCH001404 | Charger | 798-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BAT001469 | Battery | 798-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BAT001469 | Battery | 798-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Readings | General Comments | | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Readings | LTC Totalizer Reading | 5126.4 | kw |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000036 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000036 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000036 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0183 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | nitro | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0183 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Readings | MegaWatt Demand Meter Min | .20 | MegaWatts |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 15 | °C |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Readings | Percent Thermal Load B Ø Max | 40 | % |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0183 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BCH001404 | Charger | 798-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BCH001404 | Charger | 798-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BCH001404 | Charger | 798-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BCH001404 | Charger | 798-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BCH001404 | Charger | 798-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.0 | amps |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BCH001404 | Charger | 798-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | LTCMechanism | 681-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | LTCMechanism | 681-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | B0307 | LTCMechanism | 681-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0183 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0183 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | LTCMechanism | 727-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | LTCMechanism | 727-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | LTCMechanism | 406-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | LTCMechanism | 406-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | LTCMechanism | 406-1 | LTC Counter Readings | General Comments | | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | LTCMechanism | 406-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | LTCMechanism | 406-1 | LTC Counter Readings | LTC As Found Counter | 26110 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | LTCMechanism | 406-1 | LTC Counter Readings | LTC As Left Counter | 26110 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | LTCMechanism | 406-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | LTCMechanism | 406-1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | LTCMechanism | 406-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | LTCMechanism | 406-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | LTCMechanism | 406-1 | LTC Counter Readings | LTC Operations Since Last Insp | 354 | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | LTCMechanism | 406-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | LTCMechanism | 406-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/14/2023 14:32 | Distribution | Morehead West Quarterly Inspection | O0188 | LTCMechanism | 406-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BAT001469 | Battery | 798-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BAT001469 | Battery | 798-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BAT001469 | Battery | 798-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BAT001469 | Battery | 798-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BAT001469 | Battery | 798-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | needs nitro | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Readings | MegaVar Demand Meter Max | .20 | MegaVars |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Readings | MegaVar Demand Meter Min | -.20 | MegaVars |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Readings | MegaWatt Demand Meter Max | 2.30 | MegaWatts |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Readings | MegaWatt Demand Meter Min | 1.10 | MegaWatts |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.5 | psi |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 47 | °C |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 10 | °C |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BAT001469 | Battery | 798-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BAT001469 | Battery | 798-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 35 | °F |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BAT001469 | Battery | 798-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BAT001469 | Battery | 798-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN66 | WithLTC | SE-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000036 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000036 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000036 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | LTCMechanism | 727-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000036 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000036 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000036 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000036 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000036 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BAT001469 | Battery | 798-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | BAT001469 | Battery | 798-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | LTCMechanism | 727-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | LTCMechanism | 727-1 | LTC Counter Readings | General Comments | | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | LTCMechanism | 727-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | LTCMechanism | 727-1 | LTC Counter Readings | LTC As Found Counter | 136748 | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | LTCMechanism | 727-1 | LTC Counter Readings | LTC As Left Counter | 136748 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | C0489 | WithLTC | 611-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | LTCMechanism | 611-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | LTCMechanism | 727-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | LTCMechanism | 727-1 | LTC Counter Readings | LTC Current Tap Position | 1R | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | LTCMechanism | 727-1 | LTC Counter Readings | LTC Max Tap Position | 7R | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | LTCMechanism | 727-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | LTCMechanism | 727-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | LTCMechanism | 727-1 | LTC Counter Readings | LTC Operations Since Last Insp | 883 | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | LTCMechanism | 727-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | LTCMechanism | 727-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | LTCMechanism | 611-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 45 | °C |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | LTCMechanism | 611-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 35 | °C |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | LTCMechanism | 611-2 | LTC Counter Readings | LTC Operations Since Last Insp | 550 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | LTCMechanism | 611-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | LTCMechanism | 611-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | LTCMechanism | 611-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | LTCMechanism | 611-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0842 | BreakerAirMagnetic | SE-SEC-1 SPARE | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0842 | BreakerAirMagnetic | SE-SEC-1 SPARE | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0842 | BreakerAirMagnetic | SE-SEC-1 SPARE | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0842 | BreakerAirMagnetic | SE-SEC-1 SPARE | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0842 | BreakerAirMagnetic | SE-SEC-1 SPARE | AMCB Readings | 9 Month Ops New | 0 | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000260 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000260 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000260 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Readings | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Readings | LTC Totalizer Reading | 12657.6 | kw |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000260 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0181 | NonLTC | SSC-PORT TRANS 5 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0181 | NonLTC | SSC-PORT TRANS 5 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0181 | NonLTC | SSC-PORT TRANS 5 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0181 | NonLTC | SSC-PORT TRANS 5 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0181 | NonLTC | SSC-PORT TRANS 5 | NonLTC Transformer Patrol Inspection | General Comments | needs nitro, htrs not working | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0181 | NonLTC | SSC-PORT TRANS 5 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0181 | NonLTC | SSC-PORT TRANS 5 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0181 | NonLTC | SSC-PORT TRANS 5 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | n | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0181 | NonLTC | SSC-PORT TRANS 5 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | ST000518 | Structure | 799-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | ST000518 | Structure | 799-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | ST000518 | Structure | 799-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Readings | Totalizer Meter Reading | .6040 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0181 | NonLTC | SSC-PORT TRANS 5 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0181 | NonLTC | SSC-PORT TRANS 5 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0181 | NonLTC | SSC-PORT TRANS 5 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000260 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | ST000518 | Structure | 799-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | ST000518 | Structure | 799-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | ST000518 | Structure | 799-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | ST000518 | Structure | 799-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000260 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | X0132 | RecloserHydraulic | 727-0613 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 22.0 | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | X0132 | RecloserHydraulic | 727-0613 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 28.0 | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | X0132 | RecloserHydraulic | 727-0613 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 33.0 | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | X0132 | RecloserHydraulic | 727-0613 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | X0132 | RecloserHydraulic | 727-0613 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | X0132 | RecloserHydraulic | 727-0613 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | X0132 | RecloserHydraulic | 727-0613 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | X0132 | RecloserHydraulic | 727-0613 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | X0132 | RecloserHydraulic | 727-0613 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | X0132 | RecloserHydraulic | 727-0613 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | X0132 | RecloserHydraulic | 727-0613 | Recloser Hydraulic Patrol Inspection | Operations Counter | 357 | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | X0132 | RecloserHydraulic | 727-0613 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | X0132 | RecloserHydraulic | 727-0613 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000260 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000260 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000260 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0842 | BreakerAirMagnetic | SE-SEC-1 SPARE | AMCB Readings | Operations This Read AM | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0842 | BreakerAirMagnetic | SE-SEC-1 SPARE | AMCB Readings | Operations Counter AL | 18563 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0842 | BreakerAirMagnetic | SE-SEC-1 SPARE | AMCB Readings | Operations Counter AF | 18563 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0842 | BreakerAirMagnetic | SE-SEC-1 SPARE | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0842 | BreakerAirMagnetic | SE-SEC-1 SPARE | AMCB Readings | General Comments | | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0842 | BreakerAirMagnetic | SE-SEC-1 SPARE | AMCB Patrol Inspection | General Comments | | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0842 | BreakerAirMagnetic | SE-SEC-1 SPARE | AMCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0842 | BreakerAirMagnetic | SE-SEC-1 SPARE | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Readings | General Comments | | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -1.0 | psi |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 6405.84 | kw |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 15.00 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 10.00 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Readings | Oil Temp Max | 10 | °C |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .8897 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | LTCMechanism | 611-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | LTCMechanism | 611-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | LTCMechanism | 611-2 | LTC Counter Readings | General Comments | | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | LTCMechanism | 611-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | LTCMechanism | 611-2 | LTC Counter Readings | LTC As Found Counter | 37549 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | LTCMechanism | 611-2 | LTC Counter Readings | LTC As Left Counter | 37552 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | LTCMechanism | 611-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | LTCMechanism | 611-2 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | LTCMechanism | 611-2 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | LTCMechanism | 611-2 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | LTCMechanism | 611-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1 | psi |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0843 | BreakerAirMagnetic | SE-SEC-2 SPARE | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0843 | BreakerAirMagnetic | SE-SEC-2 SPARE | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0843 | BreakerAirMagnetic | SE-SEC-2 SPARE | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0843 | BreakerAirMagnetic | SE-SEC-2 SPARE | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0843 | BreakerAirMagnetic | SE-SEC-2 SPARE | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0843 | BreakerAirMagnetic | SE-SEC-2 SPARE | AMCB Readings | 9 Month Ops New | 0 | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000260 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | TX000260 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0183 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0183 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0183 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0183 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/14/2023 9:46 | Distribution | South Service Center Quarterly Inspection | LT0183 | WithLTC | SSC-Offline-Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Readings | Totalizer Meter Reading | .7032 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Readings | Winding Temp Max | 50 | °C |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Readings | Winding Temp Present | 35 | °C |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | S0016 | WithLTC | 799-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0843 | BreakerAirMagnetic | SE-SEC-2 SPARE | AMCB Readings | Operations This Read AM | 0 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0843 | BreakerAirMagnetic | SE-SEC-2 SPARE | AMCB Readings | Operations Counter AL | 99950 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Readings | MegaVar Demand Meter Max | .20 | MegaVars |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Readings | MegaVar Demand Meter Min | -.02 | MegaVars |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PN63 | WithLTC | SE-TRANS 1 | LTC Transformer Readings | MegaWatt Demand Meter Max | 1.00 | MegaWatts |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0843 | BreakerAirMagnetic | SE-SEC-2 SPARE | AMCB Readings | Operations Counter AF | 99950 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0843 | BreakerAirMagnetic | SE-SEC-2 SPARE | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0843 | BreakerAirMagnetic | SE-SEC-2 SPARE | AMCB Readings | General Comments | | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0843 | BreakerAirMagnetic | SE-SEC-2 SPARE | AMCB Patrol Inspection | General Comments | | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0843 | BreakerAirMagnetic | SE-SEC-2 SPARE | AMCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | S0045 | NonLTC | 798-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Readings | General Comments | | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Readings | Operations Counter AL | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Readings | Operations Counter AF | 213 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Readings | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | YD000363 | Yard | 727-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | YD000363 | Yard | 727-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | YD000363 | Yard | 727-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | ST000366 | Structure | 727-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | ST000366 | Structure | 727-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | YD000363 | Yard | 727-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | YD000363 | Yard | 727-Yard | Yard Patrol Inspection | General Comments | | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | YD000363 | Yard | 727-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | YD000363 | Yard | 727-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | YD000363 | Yard | 727-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | ST000366 | Structure | 727-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | ST000366 | Structure | 727-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | ST000366 | Structure | 727-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | ST000366 | Structure | 727-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Readings | LTC Totalizer Reading | 1202.40 | kw |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | ST000298 | Structure | 798-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | ST000298 | Structure | 798-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | ST000298 | Structure | 798-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0444 | RecloserHydraulic | 064-2400 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 49 | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0444 | RecloserHydraulic | 064-2400 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BAT001485 | Battery | 683-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BAT001485 | Battery | 683-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 38 | °F |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BAT001485 | Battery | 683-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BAT001485 | Battery | 683-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | YD000363 | Yard | 727-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | YD000363 | Yard | 727-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BAT001485 | Battery | 683-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BAT001485 | Battery | 683-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BAT001485 | Battery | 683-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0837 | BreakerAirMagnetic | SE-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0837 | BreakerAirMagnetic | SE-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0837 | BreakerAirMagnetic | SE-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | FE000287 | Fence | 798-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0837 | BreakerAirMagnetic | SE-2 | AMCB Readings | 9 Months Operations | 3 | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | LB0837 | BreakerAirMagnetic | SE-2 | AMCB Readings | 9 Month Ops New | 3 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | FE000287 | Fence | 798-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | FE000287 | Fence | 798-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | FE000287 | Fence | 798-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Readings | Switching Operations | 0 | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | ST000366 | Structure | 727-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | ST000366 | Structure | 727-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | ST000366 | Structure | 727-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | ST000366 | Structure | 727-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | ST000366 | Structure | 727-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | ST000366 | Structure | 727-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Readings | Totalizer Meter Reading | .2004 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 6000 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Readings | General Comments | | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Readings | LTC Totalizer Reading | 5961.6 | kw |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | LTCMechanism | 683-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | LTCMechanism | 683-2 | LTC Counter Readings | LTC As Found Counter | 12296 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | LTCMechanism | 683-2 | LTC Counter Readings | LTC As Left Counter | 12296 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | LTCMechanism | 683-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | LTCMechanism | 683-2 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | LTCMechanism | 683-2 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | ST000366 | Structure | 727-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BAT001485 | Battery | 683-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Readings | Totalizer Meter Reading | .2550 | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0444 | RecloserHydraulic | 064-2400 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0444 | RecloserHydraulic | 064-2400 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 84 | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0444 | RecloserHydraulic | 064-2400 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0 | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0444 | RecloserHydraulic | 064-2400 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Readings | Totalizer Meter Reading | .621 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BAT001485 | Battery | 683-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BAT001485 | Battery | 683-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BAT001485 | Battery | 683-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BAT001485 | Battery | 683-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | LTCMechanism | 683-2 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | LTCMechanism | 683-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PF001336 | PowerFuse | SE-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PF001336 | PowerFuse | SE-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PF001337 | PowerFuse | SE-4KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/15/2023 16:28 | Distribution | Seventh Street Quarterly Inspection | PF001337 | PowerFuse | SE-4KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BAT001485 | Battery | 683-Battery Bank | Battery Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Readings | Amps C Ø | 648 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Readings | Operations This Read Vac | 1 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Readings | Operations Counter AL | 379 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Readings | Operations Counter AF | 378 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0444 | RecloserHydraulic | 064-2400 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Readings | General Comments | | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | ST000366 | Structure | 727-Structure | Structure Patrol Inspection | General Comments | | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | ST000366 | Structure | 727-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | ST000366 | Structure | 727-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | ST000366 | Structure | 727-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | ST000366 | Structure | 727-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | ST000366 | Structure | 727-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | ST000366 | Structure | 727-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | ST000366 | Structure | 727-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0444 | RecloserHydraulic | 064-2400 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0444 | RecloserHydraulic | 064-2400 | Recloser Hydraulic Patrol Inspection | Operations Counter | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | LTCMechanism | 683-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | LTCMechanism | 683-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | LTCMechanism | 683-2 | LTC Counter Readings | General Comments | | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0444 | RecloserHydraulic | 064-2400 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0444 | RecloserHydraulic | 064-2400 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0444 | RecloserHydraulic | 064-2400 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | ST000366 | Structure | 727-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | B0335 | WithLTC | 683-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0444 | RecloserHydraulic | 064-2400 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0444 | RecloserHydraulic | 064-2400 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0444 | RecloserHydraulic | 064-2400 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 74 | |
| 3/14/2023 14:39 | Distribution | Bonnieville Quarterly Inspection | BX0444 | RecloserHydraulic | 064-2400 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | B0443 | WithLTC | 611-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | FE000287 | Fence | 798-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | FE000287 | Fence | 798-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Readings | Operations Counter AF | 176 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Readings | Operations Counter AL | 176 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Readings | Operations This Read Vac | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Readings | Switching Operations | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | FE000287 | Fence | 798-Fence | Fence Patrol Inspection | General Comments | | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | FE000287 | Fence | 798-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | FE000287 | Fence | 798-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Readings | 9 Month Operations | 1 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | WithLTC | 683-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | LTCC000714 | LTCControl | 611-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | LTCC000714 | LTCControl | 611-2 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | LTCC000714 | LTCControl | 611-2 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | LTCC000714 | LTCControl | 611-2 | LTC Control Insp | LTC Output Voltage Level | 124.1 | VAC |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | LTCC000714 | LTCControl | 611-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | LTCC000714 | LTCControl | 611-2 | LTC Control Insp | General Comments | | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | LTCC000714 | LTCControl | 611-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | LTCC000714 | LTCControl | 611-2 | LTC Control Insp | All Connections OK? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | LTCC000713 | LTCControl | 611-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | LTCC000713 | LTCControl | 611-1 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | LTCC000713 | LTCControl | 611-1 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | LTCC000713 | LTCControl | 611-1 | LTC Control Insp | LTC Output Voltage Level | 123.4 | VAC |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | LTCC000713 | LTCControl | 611-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | LTCC000713 | LTCControl | 611-1 | LTC Control Insp | General Comments | | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | ST000467 | Structure | 681-Structure | Structure Patrol Inspection | General Comments | | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | ST000467 | Structure | 681-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | FE000430 | Fence | 611-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | FE000430 | Fence | 611-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | FE000430 | Fence | 611-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | FE000430 | Fence | 611-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | ST000467 | Structure | 681-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Readings | General Comments | | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Readings | General Comments | | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Readings | Amps A Ø | 101 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Readings | Accumulated Fault Duty C Ph V | 2.19 | % |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Readings | Accumulated Fault Duty B Ph V | .88 | % |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Readings | Accumulated Fault Duty A Ph V | 1.31 | % |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Readings | 9 Month Operations | 6 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Readings | Amps B Ø | 670 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Readings | Amps A Ø | 656 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | FE000287 | Fence | 798-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Readings | Amps C Ø | 175.0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Readings | Amps B Ø | 210.0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Readings | Amps A Ø | 215.0 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001575 | BreakerVacuum | 683-0780 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | FE000287 | Fence | 798-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | ST000298 | Structure | 798-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | ST000298 | Structure | 798-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | FE000357 | Fence | 727-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | ST000298 | Structure | 798-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | ST000298 | Structure | 798-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | FE000357 | Fence | 727-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | FE000357 | Fence | 727-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | FE000357 | Fence | 727-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | FE000357 | Fence | 727-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | FE000357 | Fence | 727-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | FE000357 | Fence | 727-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | FE000357 | Fence | 727-Fence | Fence Patrol Inspection | General Comments | | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | FE000357 | Fence | 727-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | FE000357 | Fence | 727-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | YD000363 | Yard | 727-Yard | Yard Patrol Inspection | Ambient Temp | 32 | °F |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | YD000363 | Yard | 727-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | YD000363 | Yard | 727-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | ST000298 | Structure | 798-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | ST000298 | Structure | 798-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | ST000298 | Structure | 798-Structure | Structure Patrol Inspection | General Comments | | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | ST000298 | Structure | 798-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | ST000298 | Structure | 798-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | ST000298 | Structure | 798-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | ST000298 | Structure | 798-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | ST000298 | Structure | 798-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/14/2023 11:23 | Distribution | Horse Cave Industrial Quarterly Inspection | KB0010 | BreakerVacuum | 799-2 | VCB Readings | 9 Month Operations | 0 | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | ST000298 | Structure | 798-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Readings | General Comments | | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | LTCMechanism | 683-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | LTCMechanism | 683-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | LTCMechanism | 683-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | LTCMechanism | 683-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | S0010 | LTCMechanism | 683-2 | LTC Counter Readings | LTC Operations Since Last Insp | 495 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | FE000287 | Fence | 798-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | FE000287 | Fence | 798-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | YD000363 | Yard | 727-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Readings | LTC Totalizer Reading | 2448.00 | kw |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | ST000298 | Structure | 798-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | ST000298 | Structure | 798-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | ST000298 | Structure | 798-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | ST000467 | Structure | 681-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | ST000467 | Structure | 681-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | ST000467 | Structure | 681-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | ST000467 | Structure | 681-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | ST000467 | Structure | 681-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | ST000467 | Structure | 681-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | ST000467 | Structure | 681-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | ST000467 | Structure | 681-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | B0475 | WithLTC | 727-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | FE000287 | Fence | 798-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | FE000357 | Fence | 727-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | FE000357 | Fence | 727-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | FE000357 | Fence | 727-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | FE000357 | Fence | 727-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/14/2023 14:37 | Distribution | Salt Lick Quarterly Inspection | FE000357 | Fence | 727-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | FE000287 | Fence | 798-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | FE000287 | Fence | 798-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Readings | Amps B Ø | 95 | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | LTCC000713 | LTCControl | 611-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/14/2023 10:00 | Distribution | Horse Cave Quarterly Inspection | LTCC000713 | LTCControl | 611-1 | LTC Control Insp | All Connections OK? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | ST000298 | Structure | 798-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Readings | Amps C Ø | 94 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Readings | Operations Counter AF | 173 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Readings | Operations Counter AL | 173 | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Readings | Operations This Read Vac | 0 | |
| 3/14/2023 13:06 | Distribution | Munfordville Quarterly Inspection | K0164 | BreakerVacuum | 681-2443 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | ST000298 | Structure | 798-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/14/2023 14:44 | Distribution | Owingsville Quarterly Inspection | ST000298 | Structure | 798-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/14/2023 7:37 | Distribution | Morehead Quarterly Inspection | BK001574 | BreakerVacuum | 683-0779 | VCB Readings | Switching Operations | 0 | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0111 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0111 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0111 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0111 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0111 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0111 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0111 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0111 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0111 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0111 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0111 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0111 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0111 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0111 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0111 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0111 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Amps C Ø | 45.0 | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0111 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Amps B Ø | 80.0 | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0111 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Amps A Ø | 40.0 | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0111 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Operations Counter | 1517 | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0111 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001668 | BreakerVacuum | FV-1473 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001668 | BreakerVacuum | FV-1473 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Readings | Amps C Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Readings | Amps B Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Readings | Amps A Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0352 | BreakerVacuum | FV-1479 | VCB Readings | Unknown Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0352 | BreakerVacuum | FV-1479 | VCB Readings | Switching Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0352 | BreakerVacuum | FV-1479 | VCB Readings | Operations This Read Vac | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0352 | BreakerVacuum | FV-1479 | VCB Readings | Operations Counter AL | 155 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0352 | BreakerVacuum | FV-1479 | VCB Readings | Operations Counter AF | 155 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LTCC000438 | LTCControl | FV-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LTCC000437 | LTCControl | FV-TRANS 3 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LTCC000437 | LTCControl | FV-TRANS 3 | LTC Control Insp | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LTCC000437 | LTCControl | FV-TRANS 3 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LTCC000436 | LTCControl | FV-TRANS 1 | LTC Control Insp | General Comments | ok | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LTCC000436 | LTCControl | FV-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Readings | 9 Month Operations | 8 | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | ST000438 | Structure | 840-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | ST000438 | Structure | 840-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | ST000438 | Structure | 840-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | ST000438 | Structure | 840-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | ST000438 | Structure | 840-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | ST000438 | Structure | 840-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | ST000438 | Structure | 840-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | ST000438 | Structure | 840-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | ST000438 | Structure | 840-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | LTCMechanism | OR-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | LTCMechanism | OR-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 276022 | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | ST000438 | Structure | 840-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | ST000438 | Structure | 840-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | ST000438 | Structure | 840-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | ST000438 | Structure | 840-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | LTCMechanism | OR-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 276022 | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Readings | General Comments | | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | ST000438 | Structure | 840-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | ST000438 | Structure | 840-Structure | Structure Patrol Inspection | General Comments | | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1081 | Regulator | 090-5 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | FE000577 | Fence | SN-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | FE000577 | Fence | SN-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | FE000577 | Fence | SN-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Readings | Amps C Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Readings | Amps B Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Readings | Amps A Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Readings | 9 Months Operations OCB New | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000133 | PowerFuse | FV-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000133 | PowerFuse | FV-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Readings | Unknown Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Readings | Switching Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Readings | Operations This Read Vac | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Readings | Operations Counter AL | 326 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Readings | Operations Counter AF | 326 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001668 | BreakerVacuum | FV-1473 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Readings | General Comments | | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | LTCMechanism | OR-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | LTCMechanism | OR-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 134 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | LTCMechanism | OR-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | LTCMechanism | OR-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | LTCMechanism | OR-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | LTCMechanism | OR-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001668 | BreakerVacuum | FV-1473 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001668 | BreakerVacuum | FV-1473 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001668 | BreakerVacuum | FV-1473 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001668 | BreakerVacuum | FV-1473 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001668 | BreakerVacuum | FV-1473 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001668 | BreakerVacuum | FV-1473 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001668 | BreakerVacuum | FV-1473 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001668 | BreakerVacuum | FV-1473 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001668 | BreakerVacuum | FV-1473 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001668 | BreakerVacuum | FV-1473 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001668 | BreakerVacuum | FV-1473 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | FE000577 | Fence | SN-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | FE000577 | Fence | SN-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | FE000577 | Fence | SN-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | FE000577 | Fence | SN-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1081 | Regulator | 090-5 C | Regulator Patrol Inspection | General Comments | | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1081 | Regulator | 090-5 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1081 | Regulator | 090-5 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1081 | Regulator | 090-5 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1081 | Regulator | 090-5 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0420 | Regulator | 070-5 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000132 | PowerFuse | FV-GND TR 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000132 | PowerFuse | FV-GND TR 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Readings | LTC Totalizer Reading | 2296.20 | kw |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0420 | Regulator | 070-5 A | Regulator Patrol Inspection | Min Tap Position | 3L | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0420 | Regulator | 070-5 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0420 | Regulator | 070-5 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0420 | Regulator | 070-5 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0420 | Regulator | 070-5 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0420 | Regulator | 070-5 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | ST000438 | Structure | 840-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | ST000438 | Structure | 840-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | ST000438 | Structure | 840-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | ST000438 | Structure | 840-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001360 | BreakerVacuum | FV-1141 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001360 | BreakerVacuum | FV-1141 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001360 | BreakerVacuum | FV-1141 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001360 | BreakerVacuum | FV-1141 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001360 | BreakerVacuum | FV-1141 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000132 | PowerFuse | FV-GND TR 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000112 | Switchgear | FV-Swgr Sec 8 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000112 | Switchgear | FV-Swgr Sec 8 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000112 | Switchgear | FV-Swgr Sec 8 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000112 | Switchgear | FV-Swgr Sec 8 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000112 | Switchgear | FV-Swgr Sec 8 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000112 | Switchgear | FV-Swgr Sec 8 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | LTCMechanism | OR-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | LTCMechanism | OR-TRANS 1 | LTC Counter Readings | General Comments | | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | LTCMechanism | OR-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | LTCMechanism | OR-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Readings | Oil Temp Present | 15 | °C |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000137 | PowerFuse | FV-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000137 | PowerFuse | FV-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000137 | PowerFuse | FV-12KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 6000 | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Readings | Totalizer Meter Reading | .3827 | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1081 | Regulator | 090-5 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1081 | Regulator | 090-5 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1081 | Regulator | 090-5 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1081 | Regulator | 090-5 C | Regulator Patrol Inspection | Regulator As Left Counter | 105199 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000139 | PowerFuse | FV-STA SER NO 3 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000139 | PowerFuse | FV-STA SER NO 3 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000139 | PowerFuse | FV-STA SER NO 3 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1081 | Regulator | 090-5 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.0 | volts |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1081 | Regulator | 090-5 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1081 | Regulator | 090-5 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1081 | Regulator | 090-5 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000140 | PowerFuse | FV-12KV TR 3 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000140 | PowerFuse | FV-12KV TR 3 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000140 | PowerFuse | FV-12KV TR 3 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000141 | PowerFuse | FV-STA SER NO 4 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000141 | PowerFuse | FV-STA SER NO 4 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000141 | PowerFuse | FV-STA SER NO 4 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000142 | PowerFuse | FV-12KV TR 4 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000142 | PowerFuse | FV-12KV TR 4 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Readings | Oil Temp Present | 50 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | ST000438 | Structure | 840-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | ST000438 | Structure | 840-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | ST000438 | Structure | 840-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | ST000438 | Structure | 840-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000142 | PowerFuse | FV-12KV TR 4 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | ST000438 | Structure | 840-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Readings | Amps C Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Readings | Amps B Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Readings | Amps A Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001669 | BreakerVacuum | FV-1474 | VCB Readings | 9 Month Operations | 0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0420 | Regulator | 070-5 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0420 | Regulator | 070-5 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0420 | Regulator | 070-5 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0420 | Regulator | 070-5 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0420 | Regulator | 070-5 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0420 | Regulator | 070-5 A | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0420 | Regulator | 070-5 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0420 | Regulator | 070-5 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0420 | Regulator | 070-5 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0420 | Regulator | 070-5 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0420 | Regulator | 070-5 A | Regulator Patrol Inspection | General Comments | | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0420 | Regulator | 070-5 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1081 | Regulator | 090-5 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Readings | General Comments | | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1081 | Regulator | 090-5 C | Regulator Patrol Inspection | Min Tap Position | 3L | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1081 | Regulator | 090-5 C | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1081 | Regulator | 090-5 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0706 | BreakerAirMagnetic | OR-2 | AMCB Readings | Unknown Operations | 0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0706 | BreakerAirMagnetic | OR-2 | AMCB Readings | Switching Operations | 0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0706 | BreakerAirMagnetic | OR-2 | AMCB Readings | Operations This Read AM | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0706 | BreakerAirMagnetic | OR-2 | AMCB Readings | Operations Counter AL | 316 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0706 | BreakerAirMagnetic | OR-2 | AMCB Readings | Operations Counter AF | 316 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0706 | BreakerAirMagnetic | OR-2 | AMCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0706 | BreakerAirMagnetic | OR-2 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000122 | Switchgear | SN-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000122 | Switchgear | SN-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000122 | Switchgear | SN-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000122 | Switchgear | SN-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000122 | Switchgear | SN-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000122 | Switchgear | SN-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000122 | Switchgear | SN-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0706 | BreakerAirMagnetic | OR-2 | AMCB Readings | General Comments | | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0706 | BreakerAirMagnetic | OR-2 | AMCB Patrol Inspection | General Comments | | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000122 | Switchgear | SN-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000122 | Switchgear | SN-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000122 | Switchgear | SN-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | LTCC000735 | LTCControl | 597-1 | LTC Control Insp | All Connections OK? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | LTCC000735 | LTCControl | 597-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | LTCC000735 | LTCControl | 597-1 | LTC Control Insp | General Comments | | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | LTCC000735 | LTCControl | 597-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | LTCC000735 | LTCControl | 597-1 | LTC Control Insp | LTC Output Voltage Level | 124.5 | VAC |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | LTCC000735 | LTCControl | 597-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0706 | BreakerAirMagnetic | OR-2 | AMCB Readings | Follow-up Action Required? | n | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | LTCC000735 | LTCControl | 597-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000122 | Switchgear | SN-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | ST000542 | Structure | 597-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | ST000542 | Structure | 597-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | LTCC000735 | LTCControl | 597-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | ST000542 | Structure | 597-Structure | Structure Patrol Inspection | General Comments | | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | ST000542 | Structure | 597-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | YD000538 | Yard | 597-Yard | Yard Patrol Inspection | General Comments | | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | YD000538 | Yard | 597-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | YD000538 | Yard | 597-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | ST000542 | Structure | 597-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | ST000542 | Structure | 597-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0706 | BreakerAirMagnetic | OR-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0706 | BreakerAirMagnetic | OR-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0706 | BreakerAirMagnetic | OR-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0706 | BreakerAirMagnetic | OR-2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0706 | BreakerAirMagnetic | OR-2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0706 | BreakerAirMagnetic | OR-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0706 | BreakerAirMagnetic | OR-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | YD000538 | Yard | 597-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | YD000538 | Yard | 597-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0349 | BreakerVacuum | FV-1476 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0349 | BreakerVacuum | FV-1476 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0349 | BreakerVacuum | FV-1476 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | YD000538 | Yard | 597-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | YD000538 | Yard | 597-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | ST000542 | Structure | 597-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000122 | Switchgear | SN-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | YD000538 | Yard | 597-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | YD000442 | Yard | 556-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | YD000442 | Yard | 556-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | YD000442 | Yard | 556-Yard | Yard Patrol Inspection | General Comments | | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | YD000442 | Yard | 556-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | YD000442 | Yard | 556-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | YD000442 | Yard | 556-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | BAT001292 | Battery | SN-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | BAT001292 | Battery | SN-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | BAT001292 | Battery | SN-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0844 | BreakerAirMagnetic | SN-1 | AMCB Readings | Operations This Read AM | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0844 | BreakerAirMagnetic | SN-1 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | YD000442 | Yard | 556-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | YD000442 | Yard | 556-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0844 | BreakerAirMagnetic | SN-1 | AMCB Readings | General Comments | | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0844 | BreakerAirMagnetic | SN-1 | AMCB Patrol Inspection | General Comments | | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0844 | BreakerAirMagnetic | SN-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | BAT001292 | Battery | SN-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | BAT001292 | Battery | SN-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | BAT001292 | Battery | SN-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | ST000542 | Structure | 597-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | ST000542 | Structure | 597-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | ST000542 | Structure | 597-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | BAT001292 | Battery | SN-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | BAT001292 | Battery | SN-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | BAT001292 | Battery | SN-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | BAT001292 | Battery | SN-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | YD000442 | Yard | 556-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | YD000442 | Yard | 556-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | YD000442 | Yard | 556-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | YD000442 | Yard | 556-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | YD000442 | Yard | 556-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | YD000442 | Yard | 556-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | YD000442 | Yard | 556-Yard | Yard Patrol Inspection | Ambient Temp | 33 | °F |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | ST000542 | Structure | 597-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | LTCMechanism | 840-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | ST000542 | Structure | 597-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | ST000542 | Structure | 597-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | LTCMechanism | 840-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | LTCMechanism | 840-1 | LTC Counter Readings | General Comments | | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | LTCMechanism | 840-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | LTCMechanism | 840-1 | LTC Counter Readings | LTC As Found Counter | 2655 | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | LTCMechanism | 840-1 | LTC Counter Readings | LTC As Left Counter | 2660 | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | LTCMechanism | 840-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | LTCMechanism | 840-1 | LTC Counter Readings | LTC Current Tap Position | 1R | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | LTCMechanism | 840-1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | LTCMechanism | 840-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Readings | Fault Operations | 0 | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | ST000542 | Structure | 597-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Readings | Unknown Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001668 | BreakerVacuum | FV-1473 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Readings | Switching Operations | 8 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | ST000542 | Structure | 597-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | ST000542 | Structure | 597-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | ST000542 | Structure | 597-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | ST000542 | Structure | 597-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | ST000542 | Structure | 597-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | ST000542 | Structure | 597-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | ST000542 | Structure | 597-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | LTCMechanism | OR-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | LTCMechanism | OR-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | LTCMechanism | OR-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | WithLTC | 840-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Readings | Operations This Read Vac | 8 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Readings | Operations Counter AL | 309 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000136 | PowerFuse | FV-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000136 | PowerFuse | FV-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000136 | PowerFuse | FV-STA SER NO 2 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000135 | PowerFuse | FV-14KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000135 | PowerFuse | FV-14KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000135 | PowerFuse | FV-14KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000134 | PowerFuse | FV-14KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000134 | PowerFuse | FV-14KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000134 | PowerFuse | FV-14KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LTCC000438 | LTCControl | FV-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LTCC000438 | LTCControl | FV-TRANS 2 | LTC Control Insp | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Readings | Operations Counter AF | 309 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | FE000577 | Fence | SN-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | FE000577 | Fence | SN-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | FE000577 | Fence | SN-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | FE000577 | Fence | SN-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Patrol Inspection | Cabinet Heaters Functioning? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000133 | PowerFuse | FV-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Readings | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001361 | BreakerVacuum | FV-12KV TR 4 | VCB Patrol Inspection | General Comments | | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0706 | BreakerAirMagnetic | OR-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0706 | BreakerAirMagnetic | OR-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 300 | psi |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Readings | LV Winding Temp Present | 25 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Readings | LV Winding Temp Max | 45 | °C |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0706 | BreakerAirMagnetic | OR-2 | AMCB Readings | Amps C Ø | 20.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | YD000538 | Yard | 597-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | YD000538 | Yard | 597-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | YD000538 | Yard | 597-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | YD000538 | Yard | 597-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | YD000538 | Yard | 597-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | YD000538 | Yard | 597-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Readings | Unknown Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Patrol Inspection | Tank Oil Level | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Patrol Inspection | Tank Leaks | None | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0706 | BreakerAirMagnetic | OR-2 | AMCB Readings | Amps B Ø | 20.0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0706 | BreakerAirMagnetic | OR-2 | AMCB Readings | Amps A Ø | 40.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | WithLTC | FV-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0706 | BreakerAirMagnetic | OR-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0706 | BreakerAirMagnetic | OR-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0706 | BreakerAirMagnetic | OR-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Readings | Switching Operations | 4 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Readings | Operations This Read Oil | 4 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Readings | Operations Counter AL | 369 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Readings | Operations Counter AF | 369 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Readings | Number of Ops last 9 Months | 4 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Patrol Inspection | General Comments | Heater is not working. Need 230V 500W strip heater. | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | WithLTC | SN-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Readings | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0706 | BreakerAirMagnetic | OR-2 | AMCB Readings | 9 Months Operations | 0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0706 | BreakerAirMagnetic | OR-2 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | LTCMechanism | 840-1 | LTC Counter Readings | LTC Operations Since Last Insp | 857 | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | LTCMechanism | 840-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | LTCMechanism | 840-1 | LTC Counter Readings | LTC Min Tap Position | 16L | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB1290 | BreakerOil | FV-GND TR 1 | OCB Patrol Inspection | Follow-up Action Required? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | ST000542 | Structure | 597-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | FE000577 | Fence | SN-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | FE000577 | Fence | SN-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | FE000577 | Fence | SN-Fence | Fence Patrol Inspection | General Comments | | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | FE000577 | Fence | SN-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0707 | BreakerAirMagnetic | OR-3 | AMCB Patrol Inspection | General Comments | | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0707 | BreakerAirMagnetic | OR-3 | AMCB Readings | General Comments | | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0707 | BreakerAirMagnetic | OR-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0844 | BreakerAirMagnetic | SN-1 | AMCB Readings | 9 Months Operations | 0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0707 | BreakerAirMagnetic | OR-3 | AMCB Readings | Maintenance Operations | 0 | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Readings | General Comments | | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Readings | LTC Totalizer Reading | 3052.80 | kw |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | LTCMechanism | VE-TRANS 1 | LTC Counter Readings | General Comments | | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | LTCMechanism | VE-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | LTCMechanism | VE-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | LTCMechanism | VE-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | LTCMechanism | VE-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | LTCMechanism | VE-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | LTCMechanism | VE-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1034 | BreakerAirMagnetic | VE-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1034 | BreakerAirMagnetic | VE-2 | AMCB Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0354 | BreakerVacuum | FV-14KV BUS TIE SEC 8 | VCB Readings | 9 Month Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0354 | BreakerVacuum | FV-14KV BUS TIE SEC 8 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0354 | BreakerVacuum | FV-14KV BUS TIE SEC 8 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0354 | BreakerVacuum | FV-14KV BUS TIE SEC 8 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1034 | BreakerAirMagnetic | VE-2 | AMCB Readings | General Comments | | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1034 | BreakerAirMagnetic | VE-2 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Readings | Totalizer Meter Reading | .3180 | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1035 | BreakerAirMagnetic | VE-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1035 | BreakerAirMagnetic | VE-3 | AMCB Readings | General Comments | | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1035 | BreakerAirMagnetic | VE-3 | AMCB Patrol Inspection | General Comments | | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1034 | BreakerAirMagnetic | VE-2 | AMCB Readings | Operations This Read AM | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001358 | BreakerVacuum | FV-1139 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001358 | BreakerVacuum | FV-1139 | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001358 | BreakerVacuum | FV-1139 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001358 | BreakerVacuum | FV-1139 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0844 | BreakerAirMagnetic | SN-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0844 | BreakerAirMagnetic | SN-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 7.47 | % |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0707 | BreakerAirMagnetic | OR-3 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0707 | BreakerAirMagnetic | OR-3 | AMCB Readings | 9 Months Operations | 0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0707 | BreakerAirMagnetic | OR-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 3.2 | % |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0707 | BreakerAirMagnetic | OR-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0707 | BreakerAirMagnetic | OR-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0707 | BreakerAirMagnetic | OR-3 | AMCB Readings | Amps A Ø | 125.0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0707 | BreakerAirMagnetic | OR-3 | AMCB Readings | Amps B Ø | 100.0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0707 | BreakerAirMagnetic | OR-3 | AMCB Readings | Amps C Ø | 125.0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1034 | BreakerAirMagnetic | VE-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1034 | BreakerAirMagnetic | VE-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1034 | BreakerAirMagnetic | VE-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1034 | BreakerAirMagnetic | VE-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0844 | BreakerAirMagnetic | SN-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 9.61 | % |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0844 | BreakerAirMagnetic | SN-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 10.67 | % |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1034 | BreakerAirMagnetic | VE-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 1.07 | % |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1034 | BreakerAirMagnetic | VE-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 1.07 | % |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1034 | BreakerAirMagnetic | VE-2 | AMCB Readings | 9 Months Operations | 0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1034 | BreakerAirMagnetic | VE-2 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0707 | BreakerAirMagnetic | OR-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0707 | BreakerAirMagnetic | OR-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0707 | BreakerAirMagnetic | OR-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0707 | BreakerAirMagnetic | OR-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0707 | BreakerAirMagnetic | OR-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0707 | BreakerAirMagnetic | OR-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0707 | BreakerAirMagnetic | OR-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0707 | BreakerAirMagnetic | OR-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0707 | BreakerAirMagnetic | OR-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0707 | BreakerAirMagnetic | OR-3 | AMCB Readings | Follow-up Action Required? | n | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1035 | BreakerAirMagnetic | VE-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BAT001120 | Battery | 836-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BAT001120 | Battery | 836-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 38 | °F |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BAT001120 | Battery | 836-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BAT001120 | Battery | 836-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BAT001120 | Battery | 836-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BAT001120 | Battery | 836-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BAT001120 | Battery | 836-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BAT001120 | Battery | 836-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BAT001120 | Battery | 836-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BAT001120 | Battery | 836-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BAT001120 | Battery | 836-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BAT001120 | Battery | 836-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BAT001120 | Battery | 836-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1035 | BreakerAirMagnetic | VE-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 8.54 | % |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1035 | BreakerAirMagnetic | VE-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 9.61 | % |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1035 | BreakerAirMagnetic | VE-3 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001359 | BreakerVacuum | FV-1140 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0707 | BreakerAirMagnetic | OR-3 | AMCB Readings | Operations Counter AF | 471 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0707 | BreakerAirMagnetic | OR-3 | AMCB Readings | Operations Counter AL | 471 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 0 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 30 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 0 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 25 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 10 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 40 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0707 | BreakerAirMagnetic | OR-3 | AMCB Readings | Operations This Read AM | 0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0707 | BreakerAirMagnetic | OR-3 | AMCB Readings | Switching Operations | 0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0707 | BreakerAirMagnetic | OR-3 | AMCB Readings | Unknown Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001359 | BreakerVacuum | FV-1140 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001359 | BreakerVacuum | FV-1140 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001359 | BreakerVacuum | FV-1140 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001359 | BreakerVacuum | FV-1140 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001357 | BreakerVacuum | FV-1136 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001357 | BreakerVacuum | FV-1136 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001357 | BreakerVacuum | FV-1136 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001357 | BreakerVacuum | FV-1136 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001357 | BreakerVacuum | FV-1136 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001357 | BreakerVacuum | FV-1136 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001357 | BreakerVacuum | FV-1136 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0253 | GroundTransformer | FV-GND TR 1 | Ground Transformer Patrol Inspection | Winding Temp Max | 50 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0354 | BreakerVacuum | FV-14KV BUS TIE SEC 8 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0354 | BreakerVacuum | FV-14KV BUS TIE SEC 8 | VCB Readings | Amps A Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0354 | BreakerVacuum | FV-14KV BUS TIE SEC 8 | VCB Readings | Amps B Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0354 | BreakerVacuum | FV-14KV BUS TIE SEC 8 | VCB Readings | Amps C Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0354 | BreakerVacuum | FV-14KV BUS TIE SEC 8 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0354 | BreakerVacuum | FV-14KV BUS TIE SEC 8 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0354 | BreakerVacuum | FV-14KV BUS TIE SEC 8 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0354 | BreakerVacuum | FV-14KV BUS TIE SEC 8 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0354 | BreakerVacuum | FV-14KV BUS TIE SEC 8 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0354 | BreakerVacuum | FV-14KV BUS TIE SEC 8 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0354 | BreakerVacuum | FV-14KV BUS TIE SEC 8 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0354 | BreakerVacuum | FV-14KV BUS TIE SEC 8 | VCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0354 | BreakerVacuum | FV-14KV BUS TIE SEC 8 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0354 | BreakerVacuum | FV-14KV BUS TIE SEC 8 | VCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0354 | BreakerVacuum | FV-14KV BUS TIE SEC 8 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0354 | BreakerVacuum | FV-14KV BUS TIE SEC 8 | VCB Readings | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0354 | BreakerVacuum | FV-14KV BUS TIE SEC 8 | VCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0354 | BreakerVacuum | FV-14KV BUS TIE SEC 8 | VCB Readings | Operations Counter AF | 174 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0354 | BreakerVacuum | FV-14KV BUS TIE SEC 8 | VCB Readings | Operations Counter AL | 174 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0354 | BreakerVacuum | FV-14KV BUS TIE SEC 8 | VCB Readings | Operations This Read Vac | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0354 | BreakerVacuum | FV-14KV BUS TIE SEC 8 | VCB Readings | Switching Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0354 | BreakerVacuum | FV-14KV BUS TIE SEC 8 | VCB Readings | Unknown Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001357 | BreakerVacuum | FV-1136 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001357 | BreakerVacuum | FV-1136 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1035 | BreakerAirMagnetic | VE-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1035 | BreakerAirMagnetic | VE-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1035 | BreakerAirMagnetic | VE-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Readings | General Comments | | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 200.00 | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Readings | Oil Temp Max | 60 | °C |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Readings | X1 Winding Temp Max | 40 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Readings | X1 Winding Temp Present | 10 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Readings | X2 Winding Temp Max | 40 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Readings | X2 Winding Temp Present | 10 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Readings | X3 Winding Temp Max | 40 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Readings | X3 Winding Temp Present | 10 | °C |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | YD000435 | Yard | 840-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | YD000435 | Yard | 840-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | YD000435 | Yard | 840-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | YD000435 | Yard | 840-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | YD000435 | Yard | 840-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | YD000435 | Yard | 840-Yard | Yard Patrol Inspection | General Comments | | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | YD000435 | Yard | 840-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | YD000435 | Yard | 840-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | YD000435 | Yard | 840-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | YD000435 | Yard | 840-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1530.00 | kw |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001357 | BreakerVacuum | FV-1136 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001357 | BreakerVacuum | FV-1136 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001357 | BreakerVacuum | FV-1136 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001357 | BreakerVacuum | FV-1136 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001357 | BreakerVacuum | FV-1136 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 6000 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Readings | Totalizer Meter Reading | .6630 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 65.00 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 210.00 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Readings | General Comments | | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Readings | LTC Totalizer Reading | 3978.00 | kw |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Readings | Oil Temp Present | 10 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Readings | Top Oil Temperature Max | 40 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 55.00 | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | WithLTC | 597-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001357 | BreakerVacuum | FV-1136 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | ST000462 | Structure | 556-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | ST000462 | Structure | 556-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | ST000462 | Structure | 556-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | ST000462 | Structure | 556-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | ST000462 | Structure | 556-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | ST000462 | Structure | 556-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | ST000462 | Structure | 556-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | ST000462 | Structure | 556-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | ST000462 | Structure | 556-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | ST000462 | Structure | 556-Structure | Structure Patrol Inspection | General Comments | | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | ST000462 | Structure | 556-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | ST000462 | Structure | 556-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | ST000462 | Structure | 556-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | ST000462 | Structure | 556-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | ST000462 | Structure | 556-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | ST000462 | Structure | 556-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | ST000462 | Structure | 556-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | ST000462 | Structure | 556-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | ST000462 | Structure | 556-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | ST000462 | Structure | 556-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | ST000462 | Structure | 556-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | ST000462 | Structure | 556-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | ST000462 | Structure | 556-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | ST000462 | Structure | 556-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001358 | BreakerVacuum | FV-1139 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0844 | BreakerAirMagnetic | SN-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0844 | BreakerAirMagnetic | SN-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001358 | BreakerVacuum | FV-1139 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001358 | BreakerVacuum | FV-1139 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001358 | BreakerVacuum | FV-1139 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001358 | BreakerVacuum | FV-1139 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001358 | BreakerVacuum | FV-1139 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001358 | BreakerVacuum | FV-1139 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001358 | BreakerVacuum | FV-1139 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | BCH001123 | Charger | SN-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | BCH001123 | Charger | SN-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001358 | BreakerVacuum | FV-1139 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001358 | BreakerVacuum | FV-1139 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001358 | BreakerVacuum | FV-1139 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | WithLTC | 836-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1800 | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Readings | Totalizer Meter Reading | .8500 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | WithLTC | FV-TRANS 8 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | YD000435 | Yard | 840-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | YD000435 | Yard | 840-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | YD000435 | Yard | 840-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | YD000435 | Yard | 840-Yard | Yard Patrol Inspection | Ambient Temp | 32 | °F |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Readings | General Comments | | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | B0283 | NonLTC | 090-5 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0352 | BreakerVacuum | FV-1479 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0352 | BreakerVacuum | FV-1479 | VCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0352 | BreakerVacuum | FV-1479 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0352 | BreakerVacuum | FV-1479 | VCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0352 | BreakerVacuum | FV-1479 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0352 | BreakerVacuum | FV-1479 | VCB Readings | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0352 | BreakerVacuum | FV-1479 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | BCH000091 | Charger | VE-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | BCH000091 | Charger | VE-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0253 | GroundTransformer | FV-GND TR 1 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0253 | GroundTransformer | FV-GND TR 1 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0253 | GroundTransformer | FV-GND TR 1 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1080 | Regulator | 090-5 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1080 | Regulator | 090-5 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1080 | Regulator | 090-5 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.0 | volts |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0253 | GroundTransformer | FV-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0253 | GroundTransformer | FV-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0253 | GroundTransformer | FV-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Readings | Operations This Read Vac | 0 | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Readings | Switching Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000145 | PowerFuse | FV-14KV TR 8 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000144 | PowerFuse | FV-STA SER NO 8 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000144 | PowerFuse | FV-STA SER NO 8 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000144 | PowerFuse | FV-STA SER NO 8 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000112 | Switchgear | FV-Swgr Sec 8 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000112 | Switchgear | FV-Swgr Sec 8 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000112 | Switchgear | FV-Swgr Sec 8 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000112 | Switchgear | FV-Swgr Sec 8 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000112 | Switchgear | FV-Swgr Sec 8 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000112 | Switchgear | FV-Swgr Sec 8 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000112 | Switchgear | FV-Swgr Sec 8 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000112 | Switchgear | FV-Swgr Sec 8 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000112 | Switchgear | FV-Swgr Sec 8 | Switchgear Patrol Inspection | General Comments | | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0421 | Regulator | 070-5 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0421 | Regulator | 070-5 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0421 | Regulator | 070-5 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0421 | Regulator | 070-5 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.9 | volts |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0421 | Regulator | 070-5 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0421 | Regulator | 070-5 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0421 | Regulator | 070-5 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1080 | Regulator | 090-5 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1080 | Regulator | 090-5 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0844 | BreakerAirMagnetic | SN-1 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000145 | PowerFuse | FV-14KV TR 8 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000145 | PowerFuse | FV-14KV TR 8 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Readings | Fault Operations Ground | 0 | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Readings | Follow-up Action Required? | n | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Patrol Inspection | General Comments | | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Readings | General Comments | | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Readings | Maintenance Operations | 0 | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Readings | Operations Counter AF | 232 | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Readings | Operations Counter AL | 232 | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1080 | Regulator | 090-5 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1080 | Regulator | 090-5 B | Regulator Patrol Inspection | General Comments | | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1080 | Regulator | 090-5 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1080 | Regulator | 090-5 B | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1080 | Regulator | 090-5 B | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1080 | Regulator | 090-5 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1080 | Regulator | 090-5 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BAT001120 | Battery | 836-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0352 | BreakerVacuum | FV-1479 | VCB Readings | 9 Month Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0352 | BreakerVacuum | FV-1479 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0352 | BreakerVacuum | FV-1479 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0352 | BreakerVacuum | FV-1479 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0352 | BreakerVacuum | FV-1479 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0352 | BreakerVacuum | FV-1479 | VCB Readings | Amps A Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0352 | BreakerVacuum | FV-1479 | VCB Readings | Amps B Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0352 | BreakerVacuum | FV-1479 | VCB Readings | Amps C Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0352 | BreakerVacuum | FV-1479 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0352 | BreakerVacuum | FV-1479 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0352 | BreakerVacuum | FV-1479 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0352 | BreakerVacuum | FV-1479 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0352 | BreakerVacuum | FV-1479 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0352 | BreakerVacuum | FV-1479 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0253 | GroundTransformer | FV-GND TR 1 | Ground Transformer Patrol Inspection | General Comments | | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1080 | Regulator | 090-5 B | Regulator Patrol Inspection | Regulator As Left Counter | 99111 | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1080 | Regulator | 090-5 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1080 | Regulator | 090-5 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1080 | Regulator | 090-5 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1080 | Regulator | 090-5 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0420 | Regulator | 070-5 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0420 | Regulator | 070-5 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0420 | Regulator | 070-5 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001360 | BreakerVacuum | FV-1141 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001360 | BreakerVacuum | FV-1141 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001360 | BreakerVacuum | FV-1141 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001360 | BreakerVacuum | FV-1141 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001360 | BreakerVacuum | FV-1141 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001360 | BreakerVacuum | FV-1141 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001360 | BreakerVacuum | FV-1141 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0253 | GroundTransformer | FV-GND TR 1 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0253 | GroundTransformer | FV-GND TR 1 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | WithLTC | SN-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0253 | GroundTransformer | FV-GND TR 1 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0253 | GroundTransformer | FV-GND TR 1 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0253 | GroundTransformer | FV-GND TR 1 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Present | 55 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Max | 60 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Present | 50 | °C |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | CH000462 | ControlHouse | VE-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | CH000462 | ControlHouse | VE-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | CH000462 | ControlHouse | VE-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | CH000462 | ControlHouse | VE-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | CH000462 | ControlHouse | VE-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Max | 70 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001360 | BreakerVacuum | FV-1141 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001360 | BreakerVacuum | FV-1141 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001360 | BreakerVacuum | FV-1141 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Present | 40 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Max | 50 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 145.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | WithLTC | FV-TRANS 3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000112 | Switchgear | FV-Swgr Sec 8 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000112 | Switchgear | FV-Swgr Sec 8 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000112 | Switchgear | FV-Swgr Sec 8 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0421 | Regulator | 070-5 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0421 | Regulator | 070-5 B | Regulator Patrol Inspection | Min Tap Position | 2L | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0421 | Regulator | 070-5 B | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000112 | Switchgear | FV-Swgr Sec 8 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1081 | Regulator | 090-5 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000143 | PowerFuse | FV-STA SER NO 6 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000143 | PowerFuse | FV-STA SER NO 6 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | PF000143 | PowerFuse | FV-STA SER NO 6 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1081 | Regulator | 090-5 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1081 | Regulator | 090-5 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1081 | Regulator | 090-5 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1081 | Regulator | 090-5 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1081 | Regulator | 090-5 C | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0421 | Regulator | 070-5 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0421 | Regulator | 070-5 B | Regulator Patrol Inspection | General Comments | | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0421 | Regulator | 070-5 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0421 | Regulator | 070-5 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | CH000460 | ControlHouse | OR-Battery Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | CH000460 | ControlHouse | OR-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | CH000460 | ControlHouse | OR-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | CH000460 | ControlHouse | OR-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | CH000460 | ControlHouse | OR-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | CH000460 | ControlHouse | OR-Battery Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | CH000460 | ControlHouse | OR-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | CH000460 | ControlHouse | OR-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | CH000460 | ControlHouse | OR-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | CH000460 | ControlHouse | OR-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0421 | Regulator | 070-5 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0421 | Regulator | 070-5 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | LTCMechanism | SN-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | LTCMechanism | SN-TRANS 1 | LTC Counter Readings | General Comments | | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0421 | Regulator | 070-5 B | Regulator Patrol Inspection | Current Tap Position | 2R | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0421 | Regulator | 070-5 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0421 | Regulator | 070-5 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0421 | Regulator | 070-5 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0421 | Regulator | 070-5 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0421 | Regulator | 070-5 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | LTCMechanism | 840-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | LTCMechanism | 840-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0253 | GroundTransformer | FV-GND TR 1 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1079 | Regulator | 090-5 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1079 | Regulator | 090-5 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1079 | Regulator | 090-5 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1079 | Regulator | 090-5 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1079 | Regulator | 090-5 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Readings | Oil Temp Present | 15 | °C |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | LTCMechanism | SN-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | LTCMechanism | SN-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN49 | LTCMechanism | SN-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Readings | Totalizer Meter Reading | .4710 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 10 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | Replaced both desicant filters on the LTC. | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | LTCMechanism | 556-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | LTCMechanism | 556-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | LTCMechanism | 556-1 | LTC Counter Readings | General Comments | | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | LTCMechanism | 556-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | LTCMechanism | 556-1 | LTC Counter Readings | LTC As Found Counter | 104640 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | LTCMechanism | 556-1 | LTC Counter Readings | LTC As Left Counter | 104644 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001359 | BreakerVacuum | FV-1140 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001359 | BreakerVacuum | FV-1140 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001359 | BreakerVacuum | FV-1140 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Readings | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001359 | BreakerVacuum | FV-1140 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001359 | BreakerVacuum | FV-1140 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001359 | BreakerVacuum | FV-1140 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001359 | BreakerVacuum | FV-1140 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001359 | BreakerVacuum | FV-1140 | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Readings | LTC Totalizer Reading | 4521.60 | kw |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | WithLTC | 556-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001359 | BreakerVacuum | FV-1140 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001359 | BreakerVacuum | FV-1140 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1079 | Regulator | 090-5 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1079 | Regulator | 090-5 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1079 | Regulator | 090-5 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1079 | Regulator | 090-5 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1079 | Regulator | 090-5 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1079 | Regulator | 090-5 A | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1079 | Regulator | 090-5 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1079 | Regulator | 090-5 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1079 | Regulator | 090-5 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1079 | Regulator | 090-5 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1079 | Regulator | 090-5 A | Regulator Patrol Inspection | General Comments | | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1079 | Regulator | 090-5 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1079 | Regulator | 090-5 A | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1079 | Regulator | 090-5 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KT0043 | NonLTC | 070-2 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KT0043 | NonLTC | 070-2 | NonLTC Transformer Readings | Totalizer Meter Reading | .0480 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KT0043 | NonLTC | 070-2 | NonLTC Transformer Readings | Winding Temp Max | 28 | °C |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KT0043 | NonLTC | 070-2 | NonLTC Transformer Readings | Winding Temp Present | 14 | °C |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Readings | 9 Month Operations | 2 | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Readings | Amps A Ø | 22.0 | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Readings | Amps B Ø | 60.0 | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Readings | Amps C Ø | 25.0 | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | LTCMechanism | 556-1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | LTCMechanism | 556-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | LTCMechanism | 556-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | LTCMechanism | 556-1 | LTC Counter Readings | LTC Operations Since Last Insp | 414 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | LTCMechanism | 556-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | LTCMechanism | 556-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | LTCMechanism | 556-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | LTCMechanism | 556-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | C0429 | LTCMechanism | 840-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1079 | Regulator | 090-5 A | Regulator Patrol Inspection | Regulator As Left Counter | 127401 | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1079 | Regulator | 090-5 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | BK001338 | BreakerVacuum | 090-0622 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1079 | Regulator | 090-5 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1079 | Regulator | 090-5 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1079 | Regulator | 090-5 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1080 | Regulator | 090-5 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1080 | Regulator | 090-5 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1080 | Regulator | 090-5 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1080 | Regulator | 090-5 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1080 | Regulator | 090-5 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1080 | Regulator | 090-5 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | R1080 | Regulator | 090-5 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | WithLTC | FV-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | LTCMechanism | 556-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | C0524 | LTCMechanism | 556-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | BCH000131 | Charger | OR-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | BCH000131 | Charger | OR-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | BCH000131 | Charger | OR-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | BCH000131 | Charger | OR-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | BCH000131 | Charger | OR-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.7 | VDC |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | BCH000131 | Charger | OR-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.7 | VDC |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | BCH000131 | Charger | OR-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KT0043 | NonLTC | 070-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KT0043 | NonLTC | 070-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KT0043 | NonLTC | 070-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KT0043 | NonLTC | 070-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KT0043 | NonLTC | 070-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KT0043 | NonLTC | 070-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KT0043 | NonLTC | 070-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KT0043 | NonLTC | 070-2 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KT0043 | NonLTC | 070-2 | NonLTC Transformer Readings | General Comments | | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KT0043 | NonLTC | 070-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KT0043 | NonLTC | 070-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.1 | psi |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KT0043 | NonLTC | 070-2 | NonLTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 250 | psi |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KT0043 | NonLTC | 070-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KT0043 | NonLTC | 070-2 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 864.00 | kw |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KT0043 | NonLTC | 070-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KT0043 | NonLTC | 070-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KT0043 | NonLTC | 070-2 | NonLTC Transformer Readings | Oil Temp Max | 28 | °C |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KT0043 | NonLTC | 070-2 | NonLTC Transformer Readings | Oil Temp Present | 28 | °C |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KT0043 | NonLTC | 070-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KT0043 | NonLTC | 070-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KT0043 | NonLTC | 070-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KT0043 | NonLTC | 070-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KT0043 | NonLTC | 070-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | FE000611 | Fence | VE-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | YD000611 | Yard | VE-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | YD000611 | Yard | VE-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | YD000611 | Yard | VE-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | YD000585 | Yard | OR-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | BAT001436 | Battery | OR-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | BAT001436 | Battery | OR-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | BAT001436 | Battery | OR-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Readings | Fault Operations Ground | 0 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Readings | Follow-up Action Required? | n | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Patrol Inspection | General Comments | | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Readings | General Comments | | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | BAT001436 | Battery | OR-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0227 | GroundTransformer | FV-GND TR 8 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | BAT001436 | Battery | OR-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | BAT001436 | Battery | OR-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | LTCMechanism | FV-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | LTCMechanism | FV-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | LTCMechanism | FV-TRANS 1 | LTC Counter Readings | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | LTCMechanism | FV-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | LTCMechanism | FV-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 267148 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | YD000585 | Yard | OR-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | YD000585 | Yard | OR-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | YD000585 | Yard | OR-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | YD000585 | Yard | OR-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | YD000585 | Yard | OR-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | YD000611 | Yard | VE-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0705 | BreakerAirMagnetic | OR-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | YD000611 | Yard | VE-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | YD000611 | Yard | VE-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | LTCMechanism | FV-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 267148 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | LTCMechanism | FV-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | LTCMechanism | FV-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | LTCMechanism | FV-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 11L | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | LTCMechanism | FV-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | LTCMechanism | FV-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | LTCMechanism | FV-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 29 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | LTCMechanism | FV-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | LTCMechanism | FV-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0073 | LTCMechanism | FV-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | LTCMechanism | FV-TRANS 3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | LTCMechanism | FV-TRANS 3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | LTCMechanism | FV-TRANS 3 | LTC Counter Readings | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | LTCMechanism | FV-TRANS 3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | LTCMechanism | FV-TRANS 3 | LTC Counter Readings | LTC As Found Counter | 49622 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | LTCMechanism | FV-TRANS 3 | LTC Counter Readings | LTC As Left Counter | 49622 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | YD000611 | Yard | VE-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | YD000611 | Yard | VE-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LTCC000607 | LTCControl | FV-TRANS 8 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | FE000611 | Fence | VE-Fence | Fence Patrol Inspection | General Comments | | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | FE000611 | Fence | VE-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Readings | Amps C Ø | 400.0 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Readings | Amps B Ø | 400.0 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Readings | Amps A Ø | 400.0 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | FE000611 | Fence | VE-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | FE000611 | Fence | VE-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | FE000611 | Fence | VE-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | FE000611 | Fence | VE-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | FE000611 | Fence | VE-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | FE000611 | Fence | VE-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | FE000611 | Fence | VE-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | FE000611 | Fence | VE-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | YD000585 | Yard | OR-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | YD000585 | Yard | OR-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | YD000585 | Yard | OR-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | YD000585 | Yard | OR-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0227 | GroundTransformer | FV-GND TR 8 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | YD000585 | Yard | OR-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | YD000585 | Yard | OR-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | YD000585 | Yard | OR-Yard | Yard Patrol Inspection | General Comments | | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | YD000585 | Yard | OR-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | FE000611 | Fence | VE-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0705 | BreakerAirMagnetic | OR-1 | AMCB Readings | 9 Months Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Readings | Oil Temp Present | 0 | °C |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | FE000611 | Fence | VE-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Readings | 9 Month Operations | 5 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Readings | Amps A Ø | 80.0 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Readings | Amps B Ø | 100.0 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Readings | Amps C Ø | 89.0 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | LTCMechanism | FV-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | LTCMechanism | FV-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0705 | BreakerAirMagnetic | OR-1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | LTCMechanism | FV-TRANS 2 | LTC Counter Readings | General Comments | | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0705 | BreakerAirMagnetic | OR-1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0705 | BreakerAirMagnetic | OR-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0705 | BreakerAirMagnetic | OR-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0705 | BreakerAirMagnetic | OR-1 | AMCB Readings | Follow-up Action Required? | n | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Readings | 9 Month Operations | 3 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | LTCMechanism | FV-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0705 | BreakerAirMagnetic | OR-1 | AMCB Patrol Inspection | General Comments | | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0705 | BreakerAirMagnetic | OR-1 | AMCB Readings | General Comments | | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0705 | BreakerAirMagnetic | OR-1 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0705 | BreakerAirMagnetic | OR-1 | AMCB Readings | Maintenance Operations | 0 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | LTCMechanism | FV-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 22336 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | LTCMechanism | FV-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 22336 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | LTCMechanism | FV-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | LTCMechanism | FV-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | LTCMechanism | FV-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | LTCMechanism | FV-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | LTCMechanism | FV-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | LTCMechanism | FV-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 180 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | LTCMechanism | FV-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Readings | Amps A Ø | 118.0 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Readings | Amps B Ø | 114.0 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Readings | Amps C Ø | 111.0 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | LTCMechanism | FV-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Readings | Fault Operations Ground | 0 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0075 | LTCMechanism | FV-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | LTCMechanism | FV-TRANS 8 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Patrol Inspection | General Comments | | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Readings | General Comments | | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LTCC000607 | LTCControl | FV-TRANS 8 | LTC Control Insp | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LTCC000607 | LTCControl | FV-TRANS 8 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | YD000611 | Yard | VE-Yard | Yard Patrol Inspection | General Comments | | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | YD000611 | Yard | VE-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | YD000611 | Yard | VE-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | YD000611 | Yard | VE-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | YD000611 | Yard | VE-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | YD000611 | Yard | VE-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | YD000611 | Yard | VE-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | YD000611 | Yard | VE-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0847 | BreakerAirMagnetic | SN-4 | AMCB Readings | Operations This Read AM | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0847 | BreakerAirMagnetic | SN-4 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0847 | BreakerAirMagnetic | SN-4 | AMCB Readings | General Comments | | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0847 | BreakerAirMagnetic | SN-4 | AMCB Patrol Inspection | General Comments | | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0847 | BreakerAirMagnetic | SN-4 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0847 | BreakerAirMagnetic | SN-4 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0847 | BreakerAirMagnetic | SN-4 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | YD000611 | Yard | VE-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0847 | BreakerAirMagnetic | SN-4 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Readings | 9 Month Operations | 6 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0847 | BreakerAirMagnetic | SN-4 | AMCB Readings | Accumulated Fault Duty C Ph AM | 17.08 | % |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0847 | BreakerAirMagnetic | SN-4 | AMCB Readings | Accumulated Fault Duty B Ph AM | 16.01 | % |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0847 | BreakerAirMagnetic | SN-4 | AMCB Readings | Accumulated Fault Duty A Ph AM | 4.27 | % |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | CX0119 | RecloserElectronic | 090-0623 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | CX0119 | RecloserElectronic | 090-0623 | Recloser Electronic Patrol Inspection | Operations Counter | 108 | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | CX0119 | RecloserElectronic | 090-0623 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | CX0119 | RecloserElectronic | 090-0623 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | CX0119 | RecloserElectronic | 090-0623 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0847 | BreakerAirMagnetic | SN-4 | AMCB Readings | 9 Months Operations | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0847 | BreakerAirMagnetic | SN-4 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0705 | BreakerAirMagnetic | OR-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | LTCMechanism | FV-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | LTCMechanism | FV-TRANS 3 | LTC Counter Readings | LTC Current Tap Position | 13L | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | LTCMechanism | FV-TRANS 3 | LTC Counter Readings | LTC Max Tap Position | 9L | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0705 | BreakerAirMagnetic | OR-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0705 | BreakerAirMagnetic | OR-1 | AMCB Readings | Amps A Ø | 100.0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0705 | BreakerAirMagnetic | OR-1 | AMCB Readings | Amps B Ø | 80.0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0705 | BreakerAirMagnetic | OR-1 | AMCB Readings | Amps C Ø | 85.0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0705 | BreakerAirMagnetic | OR-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0705 | BreakerAirMagnetic | OR-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0705 | BreakerAirMagnetic | OR-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0705 | BreakerAirMagnetic | OR-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0705 | BreakerAirMagnetic | OR-1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | LTCMechanism | FV-TRANS 3 | LTC Counter Readings | LTC Min Tap Position | 16L | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | LTCMechanism | FV-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | LTCMechanism | FV-TRANS 3 | LTC Counter Readings | LTC Operations Since Last Insp | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | LTCMechanism | FV-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | LTCMechanism | FV-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | LTCMechanism | FV-TRANS 3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0074 | LTCMechanism | FV-TRANS 3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0422 | Regulator | 070-5 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | SWG000092 | Switchgear | OR-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | SWG000092 | Switchgear | OR-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000031 | Switchgear | FV-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000031 | Switchgear | FV-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0350 | BreakerVacuum | FV-1477 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0350 | BreakerVacuum | FV-1477 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0350 | BreakerVacuum | FV-1477 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LTCC000578 | LTCControl | FV-TRANS 4 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LTCC000578 | LTCControl | FV-TRANS 4 | LTC Control Insp | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LTCC000578 | LTCControl | FV-TRANS 4 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LTCC000578 | LTCControl | FV-TRANS 4 | LTC Control Insp | All Connections OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000031 | Switchgear | FV-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000031 | Switchgear | FV-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000031 | Switchgear | FV-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000031 | Switchgear | FV-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000031 | Switchgear | FV-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000031 | Switchgear | FV-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000031 | Switchgear | FV-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000031 | Switchgear | FV-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000031 | Switchgear | FV-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Readings | Percent Thermal Load C Ø Max | 70 | % |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Readings | Percent Thermal Load B Ø Max | 70 | % |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Readings | Percent Thermal Load A Ø Max | 70 | % |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 18 | °C |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .2 | psi |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Readings | MegaWatt Demand Meter Min | 0.00 | MegaWatts |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Readings | MegaWatt Demand Meter Max | 3.40 | MegaWatts |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Readings | MegaVar Demand Meter Min | .10 | MegaVars |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Readings | MegaVar Demand Meter Max | .80 | MegaVars |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BCH001566 | Charger | 836-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | FE000431 | Fence | 840-Fence | Fence Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | FE000431 | Fence | 840-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0422 | Regulator | 070-5 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0422 | Regulator | 070-5 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | FE000431 | Fence | 840-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0422 | Regulator | 070-5 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0422 | Regulator | 070-5 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0422 | Regulator | 070-5 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001467 | BreakerVacuum | FV-1134 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001467 | BreakerVacuum | FV-1134 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0422 | Regulator | 070-5 C | Regulator Patrol Inspection | Current Tap Position | 3R | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0422 | Regulator | 070-5 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0422 | Regulator | 070-5 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0422 | Regulator | 070-5 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001467 | BreakerVacuum | FV-1134 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001467 | BreakerVacuum | FV-1134 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001467 | BreakerVacuum | FV-1134 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0422 | Regulator | 070-5 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001467 | BreakerVacuum | FV-1134 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001467 | BreakerVacuum | FV-1134 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001467 | BreakerVacuum | FV-1134 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001467 | BreakerVacuum | FV-1134 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001467 | BreakerVacuum | FV-1134 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001467 | BreakerVacuum | FV-1134 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0422 | Regulator | 070-5 C | Regulator Patrol Inspection | General Comments | | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0422 | Regulator | 070-5 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0422 | Regulator | 070-5 C | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0422 | Regulator | 070-5 C | Regulator Patrol Inspection | Min Tap Position | 3R | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0422 | Regulator | 070-5 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0422 | Regulator | 070-5 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0422 | Regulator | 070-5 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | LTCMechanism | FV-TRANS 4 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | LTCMechanism | FV-TRANS 4 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | LTCMechanism | FV-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | LTCMechanism | FV-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | LTCMechanism | FV-TRANS 4 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0422 | Regulator | 070-5 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0422 | Regulator | 070-5 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.6 | volts |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0422 | Regulator | 070-5 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | R0422 | Regulator | 070-5 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0846 | BreakerAirMagnetic | SN-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 2.13 | % |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0846 | BreakerAirMagnetic | SN-3 | AMCB Readings | 9 Months Operations | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0846 | BreakerAirMagnetic | SN-3 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Readings | Operations This Read Vac | 4 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Readings | Operations Counter AL | 192 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Readings | Operations Counter AF | 188 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0227 | GroundTransformer | FV-GND TR 8 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0227 | GroundTransformer | FV-GND TR 8 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0227 | GroundTransformer | FV-GND TR 8 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0227 | GroundTransformer | FV-GND TR 8 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0227 | GroundTransformer | FV-GND TR 8 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0227 | GroundTransformer | FV-GND TR 8 | Ground Transformer Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0227 | GroundTransformer | FV-GND TR 8 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0227 | GroundTransformer | FV-GND TR 8 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Readings | X3 Winding Temp Present | 0 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Readings | X3 Winding Temp Max | 60 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Readings | X2 Winding Temp Present | 0 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Readings | X2 Winding Temp Max | 60 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Readings | X1 Winding Temp Present | 0 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Readings | X1 Winding Temp Max | 60 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0705 | BreakerAirMagnetic | OR-1 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Readings | Maintenance Operations | 0 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Readings | General Comments | | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Patrol Inspection | General Comments | | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Readings | Follow-up Action Required? | n | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Readings | Fault Operations Ground | 0 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | FE000611 | Fence | VE-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | FE000611 | Fence | VE-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0227 | GroundTransformer | FV-GND TR 8 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0227 | GroundTransformer | FV-GND TR 8 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0227 | GroundTransformer | FV-GND TR 8 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PN50 | WithLTC | OR-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000031 | Switchgear | FV-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000031 | Switchgear | FV-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000031 | Switchgear | FV-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000031 | Switchgear | FV-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000031 | Switchgear | FV-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000031 | Switchgear | FV-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000031 | Switchgear | FV-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000031 | Switchgear | FV-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | CX0119 | RecloserElectronic | 090-0623 | Recloser Electronic Patrol Inspection | Amps A Ø | 34.0 | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | CX0119 | RecloserElectronic | 090-0623 | Recloser Electronic Patrol Inspection | Amps B Ø | 4.0 | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | CX0119 | RecloserElectronic | 090-0623 | Recloser Electronic Patrol Inspection | Amps C Ø | 31.0 | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | CX0119 | RecloserElectronic | 090-0623 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | CX0119 | RecloserElectronic | 090-0623 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | CX0119 | RecloserElectronic | 090-0623 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | CX0119 | RecloserElectronic | 090-0623 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | CX0119 | RecloserElectronic | 090-0623 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | CX0119 | RecloserElectronic | 090-0623 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | CX0119 | RecloserElectronic | 090-0623 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | CX0119 | RecloserElectronic | 090-0623 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | CX0119 | RecloserElectronic | 090-0623 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | CX0119 | RecloserElectronic | 090-0623 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | CX0119 | RecloserElectronic | 090-0623 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/13/2023 12:31 | Distribution | Rodburn Quarterly Inspection | CX0119 | RecloserElectronic | 090-0623 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Readings | Unknown Operations | 0 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0350 | BreakerVacuum | 836-0621 | VCB Readings | Switching Operations | 4 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | PN42 | WithLTC | VE-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Readings | Operations Counter AF | 16 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Readings | Operations Counter AL | 16 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Readings | Operations This Read Vac | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Readings | Switching Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Readings | Unknown Operations | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0845 | BreakerAirMagnetic | SN-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 3.2 | % |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0845 | BreakerAirMagnetic | SN-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 4.27 | % |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0845 | BreakerAirMagnetic | SN-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 3.2 | % |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0845 | BreakerAirMagnetic | SN-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0845 | BreakerAirMagnetic | SN-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0845 | BreakerAirMagnetic | SN-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Readings | 9 Month Operations | 1 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC900514 | RecloserElectronic | 070-3420 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC900514 | RecloserElectronic | 070-3420 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC900514 | RecloserElectronic | 070-3420 | Recloser Electronic Patrol Inspection | Operations Counter | 2 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC900514 | RecloserElectronic | 070-3420 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0845 | BreakerAirMagnetic | SN-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0845 | BreakerAirMagnetic | SN-2 | AMCB Patrol Inspection | General Comments | | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0845 | BreakerAirMagnetic | SN-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 3.2 | % |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0845 | BreakerAirMagnetic | SN-2 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0845 | BreakerAirMagnetic | SN-2 | AMCB Readings | Operations This Read AM | 0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC900514 | RecloserElectronic | 070-3420 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC900514 | RecloserElectronic | 070-3420 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC900514 | RecloserElectronic | 070-3420 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC900514 | RecloserElectronic | 070-3420 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC900514 | RecloserElectronic | 070-3420 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC900514 | RecloserElectronic | 070-3420 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC900514 | RecloserElectronic | 070-3420 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC900514 | RecloserElectronic | 070-3420 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC900514 | RecloserElectronic | 070-3420 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000116 | Switchgear | SN-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000116 | Switchgear | SN-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000116 | Switchgear | SN-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000116 | Switchgear | SN-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000116 | Switchgear | SN-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000116 | Switchgear | SN-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000116 | Switchgear | SN-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000116 | Switchgear | SN-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000116 | Switchgear | SN-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000116 | Switchgear | SN-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000116 | Switchgear | SN-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | SWG000116 | Switchgear | SN-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC900514 | RecloserElectronic | 070-3420 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC900514 | RecloserElectronic | 070-3420 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC900514 | RecloserElectronic | 070-3420 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001524 | BreakerVacuum | FV-14KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001524 | BreakerVacuum | FV-14KV TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001524 | BreakerVacuum | FV-14KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001524 | BreakerVacuum | FV-14KV TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001524 | BreakerVacuum | FV-14KV TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001524 | BreakerVacuum | FV-14KV TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0845 | BreakerAirMagnetic | SN-2 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Readings | 9 Month Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Readings | Amps A Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Readings | Amps B Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Readings | Amps C Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0845 | BreakerAirMagnetic | SN-2 | AMCB Readings | 9 Months Operations | 0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Readings | Amps C Ø | 26.0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Readings | Amps B Ø | 27.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Readings | Amps A Ø | 23.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Readings | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001959 | BreakerVacuum | FV-1146 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Readings | Amps B Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Readings | Amps C Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | LTCMechanism | 836-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | LTCMechanism | 836-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | LTCMechanism | 836-1 | LTC Counter Readings | General Comments | | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | LTCMechanism | 836-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | LTCMechanism | 836-1 | LTC Counter Readings | LTC As Found Counter | 238107 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | LTCMechanism | 836-1 | LTC Counter Readings | LTC As Left Counter | 238107 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | LTCMechanism | 836-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | LTCMechanism | 836-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | LTCMechanism | 836-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | LTCMechanism | 836-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | LTCMechanism | 836-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | LTCMechanism | 836-1 | LTC Counter Readings | LTC Operations Since Last Insp | 252 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | LTCMechanism | 836-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | LTCMechanism | 836-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | LTCMechanism | 836-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | B0317 | LTCMechanism | 836-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Readings | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0353 | BreakerVacuum | FV-GND TR 8 | VCB Readings | Operations Counter AF | 186 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0353 | BreakerVacuum | FV-GND TR 8 | VCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0353 | BreakerVacuum | FV-GND TR 8 | VCB Patrol Inspection | General Comments | ok | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0353 | BreakerVacuum | FV-GND TR 8 | VCB Readings | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0353 | BreakerVacuum | FV-GND TR 8 | VCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0353 | BreakerVacuum | FV-GND TR 8 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0353 | BreakerVacuum | FV-GND TR 8 | VCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0353 | BreakerVacuum | FV-GND TR 8 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0353 | BreakerVacuum | FV-GND TR 8 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0353 | BreakerVacuum | FV-GND TR 8 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0353 | BreakerVacuum | FV-GND TR 8 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0353 | BreakerVacuum | FV-GND TR 8 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0353 | BreakerVacuum | FV-GND TR 8 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC900514 | RecloserElectronic | 070-3420 | Recloser Electronic Patrol Inspection | Amps C Ø | 28.0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC900514 | RecloserElectronic | 070-3420 | Recloser Electronic Patrol Inspection | Amps B Ø | 25.6 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC900514 | RecloserElectronic | 070-3420 | Recloser Electronic Patrol Inspection | Amps A Ø | 28.1 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0353 | BreakerVacuum | FV-GND TR 8 | VCB Readings | Unknown Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0353 | BreakerVacuum | FV-GND TR 8 | VCB Readings | Switching Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0353 | BreakerVacuum | FV-GND TR 8 | VCB Readings | Operations This Read Vac | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0353 | BreakerVacuum | FV-GND TR 8 | VCB Readings | Operations Counter AL | 186 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Readings | Switching Operations | 11 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Readings | Operations This Read Vac | 11 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Readings | Operations Counter AL | 50 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Readings | Maintenance Operations | 0 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Readings | Operations Counter AF | 390 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Readings | Operations Counter AL | 391 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Readings | Operations This Read Vac | 1 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Readings | Switching Operations | 1 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | CB0262 | BreakerVacuum | 556-2466 | VCB Readings | Unknown Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Readings | Operations Counter AF | 50 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | BAT001436 | Battery | OR-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | BAT001436 | Battery | OR-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 35 | °F |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | BAT001436 | Battery | OR-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | BAT001436 | Battery | OR-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | BAT001436 | Battery | OR-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | BAT001436 | Battery | OR-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | BAT001436 | Battery | OR-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | BAT001436 | Battery | OR-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0353 | BreakerVacuum | FV-GND TR 8 | VCB Readings | 9 Month Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0353 | BreakerVacuum | FV-GND TR 8 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0353 | BreakerVacuum | FV-GND TR 8 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0353 | BreakerVacuum | FV-GND TR 8 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0353 | BreakerVacuum | FV-GND TR 8 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0353 | BreakerVacuum | FV-GND TR 8 | VCB Readings | Amps A Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0353 | BreakerVacuum | FV-GND TR 8 | VCB Readings | Amps B Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0353 | BreakerVacuum | FV-GND TR 8 | VCB Readings | Amps C Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0353 | BreakerVacuum | FV-GND TR 8 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Readings | 9 Month Operations | 13 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001964 | BreakerVacuum | FV-12KV TR 2 | VCB Readings | Amps A Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1033 | BreakerAirMagnetic | VE-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1033 | BreakerAirMagnetic | VE-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1033 | BreakerAirMagnetic | VE-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1033 | BreakerAirMagnetic | VE-1 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Readings | Amps C Ø | 26.0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Readings | Amps B Ø | 27.0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Readings | Amps A Ø | 23.0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Readings | 9 Month Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001955 | BreakerVacuum | FV-1142 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001955 | BreakerVacuum | FV-1142 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001955 | BreakerVacuum | FV-1142 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001955 | BreakerVacuum | FV-1142 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001955 | BreakerVacuum | FV-1142 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001955 | BreakerVacuum | FV-1142 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Readings | Switching Operations | 0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001955 | BreakerVacuum | FV-1142 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001955 | BreakerVacuum | FV-1142 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001955 | BreakerVacuum | FV-1142 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001955 | BreakerVacuum | FV-1142 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001955 | BreakerVacuum | FV-1142 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001955 | BreakerVacuum | FV-1142 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001955 | BreakerVacuum | FV-1142 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001955 | BreakerVacuum | FV-1142 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001955 | BreakerVacuum | FV-1142 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Readings | 9 Month Operations | 3 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Readings | Amps A Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Readings | Amps B Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Readings | Amps C Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Readings | Maintenance Operations | 0 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Readings | Operations Counter AF | 344 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Readings | Operations Counter AL | 345 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Readings | Operations This Read Vac | 1 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Readings | Switching Operations | 1 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Patrol Inspection | General Comments | Nitrogen bottes need to be filled. | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Readings | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0705 | BreakerAirMagnetic | OR-1 | AMCB Readings | Operations Counter AF | 386 | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | K0143 | BreakerVacuum | 556-2465 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Readings | Switching Operations | 0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Readings | Operations Counter AL | 242 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Readings | Operations Counter AF | 242 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Readings | General Comments | | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | KB0090 | BreakerVacuum | 070-BT2-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0705 | BreakerAirMagnetic | OR-1 | AMCB Readings | Operations Counter AL | 386 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0705 | BreakerAirMagnetic | OR-1 | AMCB Readings | Operations This Read AM | 0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0705 | BreakerAirMagnetic | OR-1 | AMCB Readings | Switching Operations | 0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | LB0705 | BreakerAirMagnetic | OR-1 | AMCB Readings | Unknown Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0077 | WithLTC | FV-TRANS 4 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1033 | BreakerAirMagnetic | VE-1 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1033 | BreakerAirMagnetic | VE-1 | AMCB Patrol Inspection | General Comments | | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1033 | BreakerAirMagnetic | VE-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1033 | BreakerAirMagnetic | VE-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | LB1033 | BreakerAirMagnetic | VE-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Readings | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | LTCMechanism | FV-TRANS 8 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | LTCMechanism | FV-TRANS 8 | LTC Counter Readings | LTC As Found Counter | 74354 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | LTCMechanism | FV-TRANS 8 | LTC Counter Readings | LTC As Left Counter | 74354 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | LTCMechanism | FV-TRANS 8 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | LTCMechanism | FV-TRANS 8 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | LTCMechanism | FV-TRANS 8 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | LTCMechanism | FV-TRANS 8 | LTC Counter Readings | LTC Operations Since Last Insp | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | LTCMechanism | FV-TRANS 8 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | LTCMechanism | FV-TRANS 8 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | LTCMechanism | FV-TRANS 8 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Readings | Operations Counter AF | 31 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Readings | Operations Counter AL | 31 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Readings | Operations This Read Vac | 1 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Readings | Switching Operations | 1 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Readings | Unknown Operations | 0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001958 | BreakerVacuum | FV-1145 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001958 | BreakerVacuum | FV-1145 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001958 | BreakerVacuum | FV-1145 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001958 | BreakerVacuum | FV-1145 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001958 | BreakerVacuum | FV-1145 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001958 | BreakerVacuum | FV-1145 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001958 | BreakerVacuum | FV-1145 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001958 | BreakerVacuum | FV-1145 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001958 | BreakerVacuum | FV-1145 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001958 | BreakerVacuum | FV-1145 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001958 | BreakerVacuum | FV-1145 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001958 | BreakerVacuum | FV-1145 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001958 | BreakerVacuum | FV-1145 | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001958 | BreakerVacuum | FV-1145 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001958 | BreakerVacuum | FV-1145 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001524 | BreakerVacuum | FV-14KV TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001524 | BreakerVacuum | FV-14KV TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001524 | BreakerVacuum | FV-14KV TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001524 | BreakerVacuum | FV-14KV TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001524 | BreakerVacuum | FV-14KV TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001524 | BreakerVacuum | FV-14KV TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001524 | BreakerVacuum | FV-14KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001524 | BreakerVacuum | FV-14KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001524 | BreakerVacuum | FV-14KV TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | LTCMechanism | FV-TRANS 8 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Readings | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Readings | Maintenance Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Readings | Operations Counter AF | 29 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Readings | Operations Counter AL | 29 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Readings | Operations This Read Vac | 1 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Readings | Operations Counter AL | 45 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Readings | Operations Counter AF | 45 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | BK000483 | BreakerVacuum | 070-2 | VCB Readings | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Readings | Switching Operations | 1 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001956 | BreakerVacuum | FV-1143 | VCB Readings | Unknown Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Readings | 9 Month Operations | 3 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Readings | Amps A Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Readings | Amps B Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Readings | Amps C Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LT0076 | LTCMechanism | FV-TRANS 8 | LTC Counter Readings | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001957 | BreakerVacuum | FV-1144 | VCB Readings | Fault Operations Ground | 0 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | LTCC000943 | LTCControl | 836-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | LTCC000943 | LTCControl | 836-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | LTCC000943 | LTCControl | 836-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0351 | BreakerVacuum | FV-1478 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0351 | BreakerVacuum | FV-1478 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | LTCMechanism | SN-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | LTCMechanism | SN-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | LTCMechanism | SN-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | LTCMechanism | SN-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | LTCMechanism | SN-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | LTCMechanism | SN-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | PN51 | LTCMechanism | SN-TRANS 2 | LTC Counter Readings | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0351 | BreakerVacuum | FV-1478 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Readings | Unknown Operations | 0 | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001470 | BreakerVacuum | FV-1135 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001470 | BreakerVacuum | FV-1135 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001470 | BreakerVacuum | FV-1135 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Readings | Switching Operations | 1 | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Readings | Operations This Read Vac | 1 | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Readings | Operations Counter AL | 197 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001470 | BreakerVacuum | FV-1135 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Readings | Operations Counter AF | 196 | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Readings | Maintenance Operations | 0 | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Readings | General Comments | | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Patrol Inspection | General Comments | | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Readings | Follow-up Action Required? | n | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Readings | Fault Operations Ground | 0 | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001470 | BreakerVacuum | FV-1135 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001470 | BreakerVacuum | FV-1135 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001470 | BreakerVacuum | FV-1135 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | LTCMechanism | 597-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | LTCMechanism | 597-1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | LTCMechanism | 597-1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | LTCMechanism | 597-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | LTCMechanism | 597-1 | LTC Counter Readings | LTC Operations Since Last Insp | 771 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0849 | BreakerAirMagnetic | SN-SEC 2 SPARE | AMCB Readings | 9 Months Operations | 0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0849 | BreakerAirMagnetic | SN-SEC 2 SPARE | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0849 | BreakerAirMagnetic | SN-SEC 2 SPARE | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0849 | BreakerAirMagnetic | SN-SEC 2 SPARE | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | LTCMechanism | 597-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | LTCMechanism | 597-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | LTCMechanism | 597-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0849 | BreakerAirMagnetic | SN-SEC 2 SPARE | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0849 | BreakerAirMagnetic | SN-SEC 2 SPARE | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0849 | BreakerAirMagnetic | SN-SEC 2 SPARE | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0849 | BreakerAirMagnetic | SN-SEC 2 SPARE | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0849 | BreakerAirMagnetic | SN-SEC 2 SPARE | AMCB Patrol Inspection | General Comments | | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0849 | BreakerAirMagnetic | SN-SEC 2 SPARE | AMCB Readings | General Comments | | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0849 | BreakerAirMagnetic | SN-SEC 2 SPARE | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0849 | BreakerAirMagnetic | SN-SEC 2 SPARE | AMCB Readings | Operations This Read AM | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001504 | BreakerVacuum | FV-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001504 | BreakerVacuum | FV-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001504 | BreakerVacuum | FV-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001504 | BreakerVacuum | FV-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001504 | BreakerVacuum | FV-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001504 | BreakerVacuum | FV-12KV BUS TIE SEC 3 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001504 | BreakerVacuum | FV-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001504 | BreakerVacuum | FV-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001504 | BreakerVacuum | FV-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001504 | BreakerVacuum | FV-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001504 | BreakerVacuum | FV-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001504 | BreakerVacuum | FV-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001504 | BreakerVacuum | FV-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001504 | BreakerVacuum | FV-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001504 | BreakerVacuum | FV-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | BAT001429 | Battery | VE-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | BAT001429 | Battery | VE-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | BAT001429 | Battery | VE-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | BAT001429 | Battery | VE-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | BAT001429 | Battery | VE-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | BAT001429 | Battery | VE-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | BAT001429 | Battery | VE-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | BAT001429 | Battery | VE-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | BAT001429 | Battery | VE-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | BAT001429 | Battery | VE-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | LTCC000943 | LTCControl | 836-1 | LTC Control Insp | All Connections OK? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | LTCC000943 | LTCControl | 836-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | LTCC000943 | LTCControl | 836-1 | LTC Control Insp | General Comments | | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | LTCC000943 | LTCControl | 836-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | LTCC000943 | LTCControl | 836-1 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | SWG000039 | Switchgear | VE-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | SWG000039 | Switchgear | VE-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | SWG000039 | Switchgear | VE-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001469 | BreakerVacuum | FV-1137 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001469 | BreakerVacuum | FV-1137 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001469 | BreakerVacuum | FV-1137 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001469 | BreakerVacuum | FV-1137 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001469 | BreakerVacuum | FV-1137 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001469 | BreakerVacuum | FV-1137 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001469 | BreakerVacuum | FV-1137 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001469 | BreakerVacuum | FV-1137 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001469 | BreakerVacuum | FV-1137 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001469 | BreakerVacuum | FV-1137 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001469 | BreakerVacuum | FV-1137 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000072 | NonLTC | 070-5 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 10.00 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000072 | NonLTC | 070-5 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 15.00 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000072 | NonLTC | 070-5 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000072 | NonLTC | 070-5 C | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000072 | NonLTC | 070-5 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001469 | BreakerVacuum | FV-1137 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001469 | BreakerVacuum | FV-1137 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001469 | BreakerVacuum | FV-1137 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001469 | BreakerVacuum | FV-1137 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Readings | Unknown Operations | 0 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001519 | BreakerVacuum | FV-1471 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001519 | BreakerVacuum | FV-1471 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001519 | BreakerVacuum | FV-1471 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Readings | Switching Operations | 2 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Readings | Operations This Read Vac | 2 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Readings | Operations Counter AL | 646 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Readings | Operations Counter AF | 646 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Readings | Maintenance Operations | 0 | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Readings | Amps C Ø | 633.0 | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Readings | Amps B Ø | 653.0 | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Readings | Amps A Ø | 623.0 | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Readings | General Comments | | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Patrol Inspection | General Comments | | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Readings | Follow-up Action Required? | n | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Readings | Fault Operations Ground | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001470 | BreakerVacuum | FV-1135 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001470 | BreakerVacuum | FV-1135 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001470 | BreakerVacuum | FV-1135 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BAT001560 | Battery | 840-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BAT001560 | Battery | 840-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 33 | °F |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BAT001560 | Battery | 840-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BAT001560 | Battery | 840-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BAT001560 | Battery | 840-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000072 | NonLTC | 070-5 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000072 | NonLTC | 070-5 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000072 | NonLTC | 070-5 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000072 | NonLTC | 070-5 C | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000072 | NonLTC | 070-5 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000072 | NonLTC | 070-5 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000072 | NonLTC | 070-5 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000072 | NonLTC | 070-5 C | NonLTC Transformer Readings | Oil Temp Present | 18 | °C |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000072 | NonLTC | 070-5 C | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001470 | BreakerVacuum | FV-1135 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001470 | BreakerVacuum | FV-1135 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001470 | BreakerVacuum | FV-1135 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001470 | BreakerVacuum | FV-1135 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001470 | BreakerVacuum | FV-1135 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BAT001560 | Battery | 840-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BAT001560 | Battery | 840-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BAT001560 | Battery | 840-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BAT001560 | Battery | 840-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BAT001560 | Battery | 840-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BAT001560 | Battery | 840-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.0 | VDC |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BAT001560 | Battery | 840-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BAT001560 | Battery | 840-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | SWG000039 | Switchgear | VE-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | SWG000039 | Switchgear | VE-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | SWG000039 | Switchgear | VE-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | SWG000039 | Switchgear | VE-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | SWG000039 | Switchgear | VE-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | SWG000039 | Switchgear | VE-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0357 | BreakerVacuum | FV-14KV TR 8 | VCB Readings | Unknown Operations | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0357 | BreakerVacuum | FV-14KV TR 8 | VCB Readings | Switching Operations | 1 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0357 | BreakerVacuum | FV-14KV TR 8 | VCB Readings | Operations This Read Vac | 1 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | SWG000039 | Switchgear | VE-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | SWG000039 | Switchgear | VE-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | SWG000039 | Switchgear | VE-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | SWG000039 | Switchgear | VE-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | SWG000039 | Switchgear | VE-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0357 | BreakerVacuum | FV-14KV TR 8 | VCB Readings | Operations Counter AL | 345 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0357 | BreakerVacuum | FV-14KV TR 8 | VCB Readings | Operations Counter AF | 345 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0357 | BreakerVacuum | FV-14KV TR 8 | VCB Readings | Maintenance Operations | 0 | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | SWG000039 | Switchgear | VE-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | SWG000039 | Switchgear | VE-Swgr Sec 1 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 3/16/2023 9:04 | Distribution | Vermont Quarterly Inspection | SWG000039 | Switchgear | VE-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | ST000323 | Structure | 836-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | ST000323 | Structure | 836-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | ST000323 | Structure | 836-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | ST000323 | Structure | 836-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | ST000323 | Structure | 836-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | YD000316 | Yard | 836-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | YD000316 | Yard | 836-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | YD000316 | Yard | 836-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | YD000316 | Yard | 836-Yard | Yard Patrol Inspection | General Comments | | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | YD000316 | Yard | 836-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | YD000316 | Yard | 836-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | YD000316 | Yard | 836-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | YD000316 | Yard | 836-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | YD000316 | Yard | 836-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | YD000316 | Yard | 836-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | YD000316 | Yard | 836-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | YD000316 | Yard | 836-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | YD000316 | Yard | 836-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | YD000316 | Yard | 836-Yard | Yard Patrol Inspection | Ambient Temp | 38 | °F |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | FE000312 | Fence | 836-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | FE000312 | Fence | 836-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | FE000312 | Fence | 836-Fence | Fence Patrol Inspection | General Comments | | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | FE000312 | Fence | 836-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | FE000312 | Fence | 836-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | FE000312 | Fence | 836-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | FE000312 | Fence | 836-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | FE000312 | Fence | 836-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | FE000312 | Fence | 836-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | FE000312 | Fence | 836-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | FE000312 | Fence | 836-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | LTCC000928 | LTCControl | 840-1 | LTC Control Insp | All Connections OK? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | LTCC000928 | LTCControl | 840-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | LTCC000928 | LTCControl | 840-1 | LTC Control Insp | General Comments | | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | LTCC000928 | LTCControl | 840-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | LTCC000928 | LTCControl | 840-1 | LTC Control Insp | LTC Output Voltage Level | 121.6 | VAC |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | LTCC000928 | LTCControl | 840-1 | LTC Control Insp | VRR Base Voltage AF | 120.5 | VAC |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | LTCC000928 | LTCControl | 840-1 | LTC Control Insp | VRR Base Voltage AL | 120.5 | VAC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | FE000312 | Fence | 836-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | FE000312 | Fence | 836-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | FE000312 | Fence | 836-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | FE000312 | Fence | 836-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | FE000312 | Fence | 836-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | LTCC000928 | LTCControl | 840-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0112 | RecloserElectronic | 597-2405 | Recloser Electronic Patrol Inspection | Amps A Ø | 40.0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | YD000583 | Yard | SN-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001479 | BreakerVacuum | FV-1472 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001479 | BreakerVacuum | FV-1472 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001479 | BreakerVacuum | FV-1472 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001479 | BreakerVacuum | FV-1472 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000110 | Switchgear | FV-Swgr Sec 3 & 4 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000110 | Switchgear | FV-Swgr Sec 3 & 4 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0112 | RecloserElectronic | 597-2405 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0112 | RecloserElectronic | 597-2405 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0112 | RecloserElectronic | 597-2405 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0112 | RecloserElectronic | 597-2405 | Recloser Electronic Patrol Inspection | Operations Counter | 1470 | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0112 | RecloserElectronic | 597-2405 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0112 | RecloserElectronic | 597-2405 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0112 | RecloserElectronic | 597-2405 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0112 | RecloserElectronic | 597-2405 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0112 | RecloserElectronic | 597-2405 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0112 | RecloserElectronic | 597-2405 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0112 | RecloserElectronic | 597-2405 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | BAT001232 | Battery | 556-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | BAT001232 | Battery | 556-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 33 | °F |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | BAT001232 | Battery | 556-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | BAT001232 | Battery | 556-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | BAT001232 | Battery | 556-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | BAT001232 | Battery | 556-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | BAT001232 | Battery | 556-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | BAT001232 | Battery | 556-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | BAT001232 | Battery | 556-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | BAT001232 | Battery | 556-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | BAT001232 | Battery | 556-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0112 | RecloserElectronic | 597-2405 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0112 | RecloserElectronic | 597-2405 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0112 | RecloserElectronic | 597-2405 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0112 | RecloserElectronic | 597-2405 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0112 | RecloserElectronic | 597-2405 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0112 | RecloserElectronic | 597-2405 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0112 | RecloserElectronic | 597-2405 | Recloser Electronic Patrol Inspection | Amps C Ø | 45.0 | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | CX0112 | RecloserElectronic | 597-2405 | Recloser Electronic Patrol Inspection | Amps B Ø | 50.0 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | ST000323 | Structure | 836-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | ST000323 | Structure | 836-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | ST000323 | Structure | 836-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | ST000323 | Structure | 836-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | BAT001232 | Battery | 556-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | ST000323 | Structure | 836-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | ST000323 | Structure | 836-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | ST000323 | Structure | 836-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | ST000323 | Structure | 836-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | ST000323 | Structure | 836-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | ST000323 | Structure | 836-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | ST000323 | Structure | 836-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | ST000323 | Structure | 836-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | ST000323 | Structure | 836-Structure | Structure Patrol Inspection | General Comments | | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | ST000323 | Structure | 836-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | ST000323 | Structure | 836-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | ST000323 | Structure | 836-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | ST000323 | Structure | 836-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000110 | Switchgear | FV-Swgr Sec 3 & 4 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000110 | Switchgear | FV-Swgr Sec 3 & 4 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000110 | Switchgear | FV-Swgr Sec 3 & 4 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000110 | Switchgear | FV-Swgr Sec 3 & 4 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000110 | Switchgear | FV-Swgr Sec 3 & 4 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000110 | Switchgear | FV-Swgr Sec 3 & 4 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000110 | Switchgear | FV-Swgr Sec 3 & 4 | Switchgear Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000110 | Switchgear | FV-Swgr Sec 3 & 4 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000110 | Switchgear | FV-Swgr Sec 3 & 4 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000110 | Switchgear | FV-Swgr Sec 3 & 4 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000110 | Switchgear | FV-Swgr Sec 3 & 4 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000110 | Switchgear | FV-Swgr Sec 3 & 4 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000110 | Switchgear | FV-Swgr Sec 3 & 4 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000110 | Switchgear | FV-Swgr Sec 3 & 4 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000110 | Switchgear | FV-Swgr Sec 3 & 4 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | YD000583 | Yard | SN-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | YD000583 | Yard | SN-Yard | Yard Patrol Inspection | General Comments | | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | YD000583 | Yard | SN-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | YD000583 | Yard | SN-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | YD000583 | Yard | SN-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | YD000583 | Yard | SN-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | YD000583 | Yard | SN-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | YD000583 | Yard | SN-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | YD000583 | Yard | SN-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | YD000583 | Yard | SN-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | FE000580 | Fence | OR-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | FE000580 | Fence | OR-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | FE000580 | Fence | OR-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | FE000580 | Fence | OR-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | FE000580 | Fence | OR-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | FE000580 | Fence | OR-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | FE000580 | Fence | OR-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | FE000580 | Fence | OR-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | FE000580 | Fence | OR-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | FE000580 | Fence | OR-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | FE000580 | Fence | OR-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | FE000580 | Fence | OR-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | FE000580 | Fence | OR-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | FE000580 | Fence | OR-Fence | Fence Patrol Inspection | General Comments | | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | FE000580 | Fence | OR-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | FE000580 | Fence | OR-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001479 | BreakerVacuum | FV-1472 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0849 | BreakerAirMagnetic | SN-SEC 2 SPARE | AMCB Readings | 9 Month Ops New | 0 | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | LTCMechanism | 597-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | LTCMechanism | 597-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | LTCMechanism | 597-1 | LTC Counter Readings | General Comments | | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | LTCMechanism | 597-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | LTCMechanism | 597-1 | LTC Counter Readings | LTC As Found Counter | 4084 | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | M0082 | LTCMechanism | 597-1 | LTC Counter Readings | LTC As Left Counter | 4087 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | CH000447 | ControlHouse | SN-Battery Control House | Control House Patrol  Inspection | Moisture and Leak Free? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | CH000447 | ControlHouse | SN-Battery Control House | Control House Patrol  Inspection | General Comments | | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | CH000447 | ControlHouse | SN-Battery Control House | Control House Patrol  Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | CH000447 | ControlHouse | SN-Battery Control House | Control House Patrol  Inspection | Doors and Locks Secure? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | CH000447 | ControlHouse | SN-Battery Control House | Control House Patrol  Inspection | Controlhouse Grounds in Place? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | CH000447 | ControlHouse | SN-Battery Control House | Control House Patrol  Inspection | Control House Lighting OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001479 | BreakerVacuum | FV-1472 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | BAT001232 | Battery | 556-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | BAT001232 | Battery | 556-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | BAT001232 | Battery | 556-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000110 | Switchgear | FV-Swgr Sec 3 & 4 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | SWG000110 | Switchgear | FV-Swgr Sec 3 & 4 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001479 | BreakerVacuum | FV-1472 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001479 | BreakerVacuum | FV-1472 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | LTCC000929 | LTCControl | 556-1 | LTC Control Insp | All Connections OK? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | LTCC000929 | LTCControl | 556-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | LTCC000929 | LTCControl | 556-1 | LTC Control Insp | General Comments | | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | LTCC000929 | LTCControl | 556-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | LTCC000929 | LTCControl | 556-1 | LTC Control Insp | LTC Output Voltage Level | 124.5 | VAC |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | LTCC000929 | LTCControl | 556-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | FE000438 | Fence | 556-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | FE000438 | Fence | 556-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | FE000438 | Fence | 556-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | FE000438 | Fence | 556-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | FE000438 | Fence | 556-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | FE000438 | Fence | 556-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | FE000438 | Fence | 556-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | FE000438 | Fence | 556-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | FE000438 | Fence | 556-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | FE000438 | Fence | 556-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | FE000438 | Fence | 556-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | FE000438 | Fence | 556-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | FE000438 | Fence | 556-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | FE000438 | Fence | 556-Fence | Fence Patrol Inspection | General Comments | | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | FE000438 | Fence | 556-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | FE000438 | Fence | 556-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | LTCC000929 | LTCControl | 556-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | LTCC000929 | LTCControl | 556-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001479 | BreakerVacuum | FV-1472 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001479 | BreakerVacuum | FV-1472 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001479 | BreakerVacuum | FV-1472 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001479 | BreakerVacuum | FV-1472 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001479 | BreakerVacuum | FV-1472 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001479 | BreakerVacuum | FV-1472 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001479 | BreakerVacuum | FV-1472 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | YD000583 | Yard | SN-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | YD000583 | Yard | SN-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | YD000583 | Yard | SN-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | YD000583 | Yard | SN-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | YD000583 | Yard | SN-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0846 | BreakerAirMagnetic | SN-3 | AMCB Readings | Operations This Read AM | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001468 | BreakerVacuum | FV-1138 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BCH001495 | Charger | 840-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BCH001495 | Charger | 840-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BCH001495 | Charger | 840-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BCH001495 | Charger | 840-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001468 | BreakerVacuum | FV-1138 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001468 | BreakerVacuum | FV-1138 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0846 | BreakerAirMagnetic | SN-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0846 | BreakerAirMagnetic | SN-3 | AMCB Readings | General Comments | | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0846 | BreakerAirMagnetic | SN-3 | AMCB Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001503 | BreakerVacuum | FV-12KV TR 3 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001503 | BreakerVacuum | FV-12KV TR 3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001503 | BreakerVacuum | FV-12KV TR 3 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001503 | BreakerVacuum | FV-12KV TR 3 | VCB Patrol Inspection | General Comments | | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | FE000885 | Fence | 597-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | FE000885 | Fence | 597-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | FE000885 | Fence | 597-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | FE000885 | Fence | 597-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | FE000885 | Fence | 597-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | FE000885 | Fence | 597-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | FE000885 | Fence | 597-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | FE000885 | Fence | 597-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | FE000885 | Fence | 597-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | FE000885 | Fence | 597-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | FE000885 | Fence | 597-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | FE000885 | Fence | 597-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | FE000885 | Fence | 597-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001503 | BreakerVacuum | FV-12KV TR 3 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001503 | BreakerVacuum | FV-12KV TR 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001503 | BreakerVacuum | FV-12KV TR 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001503 | BreakerVacuum | FV-12KV TR 3 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001503 | BreakerVacuum | FV-12KV TR 3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001468 | BreakerVacuum | FV-1138 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC000288 | RecloserElectronic | 070-0770 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC000288 | RecloserElectronic | 070-0770 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC000288 | RecloserElectronic | 070-0770 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC000288 | RecloserElectronic | 070-0770 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC000288 | RecloserElectronic | 070-0770 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC000288 | RecloserElectronic | 070-0770 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC000288 | RecloserElectronic | 070-0770 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC000288 | RecloserElectronic | 070-0770 | Recloser Electronic Patrol Inspection | Amps C Ø | 17.0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC000288 | RecloserElectronic | 070-0770 | Recloser Electronic Patrol Inspection | Amps B Ø | 34.0 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC000288 | RecloserElectronic | 070-0770 | Recloser Electronic Patrol Inspection | Amps A Ø | 20.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001468 | BreakerVacuum | FV-1138 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0357 | BreakerVacuum | FV-14KV TR 8 | VCB Readings | 9 Month Operations | 4 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0357 | BreakerVacuum | FV-14KV TR 8 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0357 | BreakerVacuum | FV-14KV TR 8 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001468 | BreakerVacuum | FV-1138 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001468 | BreakerVacuum | FV-1138 | VCB Patrol Inspection | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001468 | BreakerVacuum | FV-1138 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001468 | BreakerVacuum | FV-1138 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001503 | BreakerVacuum | FV-12KV TR 3 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0846 | BreakerAirMagnetic | SN-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0846 | BreakerAirMagnetic | SN-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001468 | BreakerVacuum | FV-1138 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001468 | BreakerVacuum | FV-1138 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001468 | BreakerVacuum | FV-1138 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0846 | BreakerAirMagnetic | SN-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Readings | 9 Month Operations | 6 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Readings | Amps A Ø | 0.0 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Readings | Amps B Ø | 0.0 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Readings | Amps C Ø | 0.0 | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0846 | BreakerAirMagnetic | SN-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0846 | BreakerAirMagnetic | SN-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 2.13 | % |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001503 | BreakerVacuum | FV-12KV TR 3 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PF001331 | PowerFuse | OR-4KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PF001331 | PowerFuse | OR-4KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | PF001331 | PowerFuse | OR-4KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | BCH001181 | Charger | 556-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | BCH001181 | Charger | 556-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | BCH001181 | Charger | 556-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | BCH001181 | Charger | 556-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .8 | amps |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | BCH001181 | Charger | 556-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | BCH001181 | Charger | 556-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 3/13/2023 10:55 | Distribution | Leitchfield East Quarterly Inspection | BCH001181 | Charger | 556-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC000288 | RecloserElectronic | 070-0770 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC000288 | RecloserElectronic | 070-0770 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Readings | Oil Temp Present | 18 | °C |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Readings | Oil Temp Max | 39 | °C |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | FE000431 | Fence | 840-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | FE000431 | Fence | 840-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 800 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Readings | Totalizer Meter Reading | .3960 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000071 | NonLTC | 070-5 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001503 | BreakerVacuum | FV-12KV TR 3 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | FE000431 | Fence | 840-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | FE000431 | Fence | 840-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | FE000431 | Fence | 840-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | FE000431 | Fence | 840-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 10.00 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 15.00 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 316.80 | kw |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | SWG000092 | Switchgear | OR-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | SWG000092 | Switchgear | OR-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000071 | NonLTC | 070-5 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000071 | NonLTC | 070-5 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000071 | NonLTC | 070-5 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000071 | NonLTC | 070-5 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000071 | NonLTC | 070-5 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000071 | NonLTC | 070-5 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000071 | NonLTC | 070-5 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC000288 | RecloserElectronic | 070-0770 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC000288 | RecloserElectronic | 070-0770 | Recloser Electronic Patrol Inspection | Operations Counter | 26 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC000288 | RecloserElectronic | 070-0770 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | SWG000092 | Switchgear | OR-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC000288 | RecloserElectronic | 070-0770 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC000288 | RecloserElectronic | 070-0770 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC000288 | RecloserElectronic | 070-0770 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC000288 | RecloserElectronic | 070-0770 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | RC000288 | RecloserElectronic | 070-0770 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | SWG000092 | Switchgear | OR-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001468 | BreakerVacuum | FV-1138 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001468 | BreakerVacuum | FV-1138 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | SWG000092 | Switchgear | OR-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | FE000431 | Fence | 840-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000070 | NonLTC | 070-5 A | NonLTC Transformer Readings | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001468 | BreakerVacuum | FV-1138 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BCH001495 | Charger | 840-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BCH001495 | Charger | 840-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BCH001495 | Charger | 840-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BCH001495 | Charger | 840-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | FE000885 | Fence | 597-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | FE000885 | Fence | 597-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/13/2023 14:12 | Distribution | Clarkson Quarterly Inspection | FE000885 | Fence | 597-Fence | Fence Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0348 | BreakerVacuum | FV-1475 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000071 | NonLTC | 070-5 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000071 | NonLTC | 070-5 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000072 | NonLTC | 070-5 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | FE000431 | Fence | 840-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | FE000431 | Fence | 840-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000072 | NonLTC | 070-5 C | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | FE000431 | Fence | 840-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | FE000431 | Fence | 840-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | FE000431 | Fence | 840-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000072 | NonLTC | 070-5 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000072 | NonLTC | 070-5 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000072 | NonLTC | 070-5 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | FE000431 | Fence | 840-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000072 | NonLTC | 070-5 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000072 | NonLTC | 070-5 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000072 | NonLTC | 070-5 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BCH001566 | Charger | 836-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BCH001566 | Charger | 836-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BCH001566 | Charger | 836-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000072 | NonLTC | 070-5 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000072 | NonLTC | 070-5 C | NonLTC Transformer Readings | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001519 | BreakerVacuum | FV-1471 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BCH001566 | Charger | 836-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001519 | BreakerVacuum | FV-1471 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001519 | BreakerVacuum | FV-1471 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001519 | BreakerVacuum | FV-1471 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001519 | BreakerVacuum | FV-1471 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001519 | BreakerVacuum | FV-1471 | VCB Patrol Inspection | General Comments | | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BCH001566 | Charger | 836-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .2 | amps |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BCH001566 | Charger | 836-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BCH001566 | Charger | 836-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001519 | BreakerVacuum | FV-1471 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001519 | BreakerVacuum | FV-1471 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001519 | BreakerVacuum | FV-1471 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001519 | BreakerVacuum | FV-1471 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001519 | BreakerVacuum | FV-1471 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001519 | BreakerVacuum | FV-1471 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Readings | 9 Month Operations | 4 | |
| 3/13/2023 13:57 | Distribution | Mid Valley Clarkson Quarterly Inspection | BK001550 | BreakerVacuum | 840-2538 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | SWG000092 | Switchgear | OR-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | SWG000092 | Switchgear | OR-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | SWG000092 | Switchgear | OR-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0357 | BreakerVacuum | FV-14KV TR 8 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0357 | BreakerVacuum | FV-14KV TR 8 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0357 | BreakerVacuum | FV-14KV TR 8 | VCB Readings | Fault Operations Ground | 0 | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | SWG000092 | Switchgear | OR-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | SWG000092 | Switchgear | OR-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | SWG000092 | Switchgear | OR-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | SWG000092 | Switchgear | OR-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | SWG000092 | Switchgear | OR-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/13/2023 15:05 | Distribution | Ormsby Quarterly Inspection | SWG000092 | Switchgear | OR-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0357 | BreakerVacuum | FV-14KV TR 8 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0357 | BreakerVacuum | FV-14KV TR 8 | VCB Readings | Follow-up Action Required? | n | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0357 | BreakerVacuum | FV-14KV TR 8 | VCB Readings | General Comments | | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0357 | BreakerVacuum | FV-14KV TR 8 | VCB Patrol Inspection | General Comments | ok | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0357 | BreakerVacuum | FV-14KV TR 8 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0357 | BreakerVacuum | FV-14KV TR 8 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0357 | BreakerVacuum | FV-14KV TR 8 | VCB Readings | Amps C Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0357 | BreakerVacuum | FV-14KV TR 8 | VCB Readings | Amps B Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0357 | BreakerVacuum | FV-14KV TR 8 | VCB Readings | Amps A Ø | 0.0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001467 | BreakerVacuum | FV-1134 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001467 | BreakerVacuum | FV-1134 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0357 | BreakerVacuum | FV-14KV TR 8 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0357 | BreakerVacuum | FV-14KV TR 8 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000071 | NonLTC | 070-5 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000071 | NonLTC | 070-5 B | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000071 | NonLTC | 070-5 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000071 | NonLTC | 070-5 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000071 | NonLTC | 070-5 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000071 | NonLTC | 070-5 B | NonLTC Transformer Readings | Oil Temp Present | 14 | °C |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000071 | NonLTC | 070-5 B | NonLTC Transformer Readings | Oil Temp Max | 33 | °C |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000071 | NonLTC | 070-5 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 55.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000071 | NonLTC | 070-5 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 60.00 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000071 | NonLTC | 070-5 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000071 | NonLTC | 070-5 B | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000071 | NonLTC | 070-5 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000071 | NonLTC | 070-5 B | NonLTC Transformer Readings | General Comments | | |
| 3/14/2023 7:33 | Distribution | Pocket Quarterly Inspection | TX000071 | NonLTC | 070-5 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001503 | BreakerVacuum | FV-12KV TR 3 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001503 | BreakerVacuum | FV-12KV TR 3 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001503 | BreakerVacuum | FV-12KV TR 3 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/16/2023 10:18 | Distribution | Shawnee Quarterly Inspection | LB0846 | BreakerAirMagnetic | SN-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 2.13 | % |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001467 | BreakerVacuum | FV-1134 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | BK001467 | BreakerVacuum | FV-1134 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0357 | BreakerVacuum | FV-14KV TR 8 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0357 | BreakerVacuum | FV-14KV TR 8 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0357 | BreakerVacuum | FV-14KV TR 8 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0348 | BreakerVacuum | FV-1475 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/13/2023 12:38 | Distribution | Morehead East Quarterly Inspection | BB0377 | BreakerVacuum | 836-0620 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/15/2023 12:51 | Distribution | Fern Valley Quarterly Inspection | LB0348 | BreakerVacuum | FV-1475 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | WX0445 | RecloserHydraulic | Retired Distribution | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 264 | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | WX0445 | RecloserHydraulic | Retired Distribution | Recloser Hydraulic Patrol Inspection | Amps C Ø | 16.7 | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | WX0445 | RecloserHydraulic | Retired Distribution | Recloser Hydraulic Patrol Inspection | Amps B Ø | 31.9 | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | WX0445 | RecloserHydraulic | Retired Distribution | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | WX0445 | RecloserHydraulic | Retired Distribution | Recloser Hydraulic Patrol Inspection | Amps A Ø | 28.2 | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | WX0445 | RecloserHydraulic | Retired Distribution | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 276 | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | WX0445 | RecloserHydraulic | Retired Distribution | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | WX0445 | RecloserHydraulic | Retired Distribution | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 329 | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | WX0445 | RecloserHydraulic | Retired Distribution | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | WX0445 | RecloserHydraulic | Retired Distribution | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | WX0445 | RecloserHydraulic | Retired Distribution | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | WX0445 | RecloserHydraulic | Retired Distribution | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | WX0445 | RecloserHydraulic | Retired Distribution | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | WX0445 | RecloserHydraulic | Retired Distribution | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | WX0445 | RecloserHydraulic | Retired Distribution | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0066 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 200.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0066 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 190.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0066 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0066 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0066 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 1 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0066 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 1 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0066 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 972 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0066 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 972 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0066 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0066 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 7 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0066 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 6 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0066 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0066 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0066 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0066 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 210.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0066 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0066 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0066 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0066 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0066 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0066 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0066 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0065 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0065 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0065 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0065 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0065 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0065 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0065 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0065 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0065 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0065 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0065 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 4 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0065 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 14 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0065 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0065 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 808 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0065 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 808 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0065 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 10 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0065 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 10 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0065 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 190.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0065 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 190.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0065 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 170.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0065 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0065 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0066 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0066 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0066 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0065 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0065 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0065 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0064 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0064 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0064 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 697 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0064 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 697 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0064 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0064 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0064 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0064 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0064 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0064 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0064 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0064 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0064 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0064 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0064 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 85.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0064 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0064 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0064 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 90.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0064 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 90.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0064 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0064 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0064 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0064 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0064 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0064 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0063 | BreakerAirMagnetic | HI-1473 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0063 | BreakerAirMagnetic | HI-1473 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0063 | BreakerAirMagnetic | HI-1473 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0063 | BreakerAirMagnetic | HI-1473 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0063 | BreakerAirMagnetic | HI-1473 | AMCB Readings | Switching Operations | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0063 | BreakerAirMagnetic | HI-1473 | AMCB Readings | Operations This Read AM | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0063 | BreakerAirMagnetic | HI-1473 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0063 | BreakerAirMagnetic | HI-1473 | AMCB Readings | Operations Counter AL | 682 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0063 | BreakerAirMagnetic | HI-1473 | AMCB Readings | Operations Counter AF | 682 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0063 | BreakerAirMagnetic | HI-1473 | AMCB Readings | Maintenance Operations | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0063 | BreakerAirMagnetic | HI-1473 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0063 | BreakerAirMagnetic | HI-1473 | AMCB Readings | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0063 | BreakerAirMagnetic | HI-1473 | AMCB Readings | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0063 | BreakerAirMagnetic | HI-1473 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0063 | BreakerAirMagnetic | HI-1473 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0063 | BreakerAirMagnetic | HI-1473 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0063 | BreakerAirMagnetic | HI-1473 | AMCB Readings | 9 Months Operations | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0063 | BreakerAirMagnetic | HI-1473 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0063 | BreakerAirMagnetic | HI-1473 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0063 | BreakerAirMagnetic | HI-1473 | AMCB Readings | Amps A Ø | 75.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0063 | BreakerAirMagnetic | HI-1473 | AMCB Readings | Amps B Ø | 80.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0063 | BreakerAirMagnetic | HI-1473 | AMCB Readings | Amps C Ø | 80.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0063 | BreakerAirMagnetic | HI-1473 | AMCB Patrol Inspection | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0063 | BreakerAirMagnetic | HI-1473 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0063 | BreakerAirMagnetic | HI-1473 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0073 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | 9 Months Operations | 12 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0073 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0073 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0073 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0073 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Amps A Ø | 550.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0073 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Amps B Ø | 587.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0073 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Amps C Ø | 580.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0073 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0073 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0073 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0073 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0073 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0073 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0073 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Fault Operations Ground | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0073 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0073 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0073 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Maintenance Operations | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0073 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Operations Counter AF | 462 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0073 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Operations Counter AL | 462 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0073 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Operations This Read AM | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0073 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Switching Operations | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0073 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | 9 Month Ops New | 12 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0073 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Patrol Inspection | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0073 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0073 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Readings | Amps B Ø | 179.0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Readings | Amps A Ø | 227.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | ANN000010 | Annunciator | BI-Annunciator Panel | Annunciator Patrol Inspection | General Comments | | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Readings | Fault Operations Ground | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Readings | Fault Operations Ground | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Readings | Follow-up Action Required? | n | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Patrol Inspection | General Comments | | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Readings | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | ANN000010 | Annunciator | BI-Annunciator Panel | Annunciator Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | ANN000010 | Annunciator | BI-Annunciator Panel | Annunciator Patrol Inspection | ESOC  Received Alarm Test? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | ANN000010 | Annunciator | BI-Annunciator Panel | Annunciator Patrol Inspection | Control House Alarm Audible? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | ANN000010 | Annunciator | BI-Annunciator Panel | Annunciator Patrol Inspection | All Lights Functioning? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | B0127 | NonLTC | 479-1 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Readings | Amps C Ø | 229.0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | B0127 | NonLTC | 479-1 B | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | B0127 | NonLTC | 479-1 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | B0127 | NonLTC | 479-1 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0074 | BreakerAirMagnetic | BI-12KV TR 2 | AMCB Readings | 9 Month Ops New | 4 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0841 | Regulator | 479-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0074 | BreakerAirMagnetic | BI-12KV TR 2 | AMCB Readings | 9 Months Operations | 4 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0074 | BreakerAirMagnetic | BI-12KV TR 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0074 | BreakerAirMagnetic | BI-12KV TR 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0841 | Regulator | 479-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0841 | Regulator | 479-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0841 | Regulator | 479-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 376262 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0841 | Regulator | 479-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0841 | Regulator | 479-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0841 | Regulator | 479-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0841 | Regulator | 479-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0841 | Regulator | 479-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0841 | Regulator | 479-1 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0841 | Regulator | 479-1 B | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0841 | Regulator | 479-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0841 | Regulator | 479-1 B | Regulator Patrol Inspection | General Comments | ok | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0841 | Regulator | 479-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0074 | BreakerAirMagnetic | BI-12KV TR 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCC000777 | LTCControl | 093-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCC000777 | LTCControl | 093-5 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCC000777 | LTCControl | 093-5 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Readings | Unknown Operations | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Readings | Unknown Operations | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Readings | Switching Operations | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Readings | Operations This Read Vac | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Readings | Operations Counter AL | 426 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Readings | Operations Counter AF | 426 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCC000777 | LTCControl | 093-5 | LTC Control Insp | LTC Output Voltage Level | 123.7 | VAC |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCC000777 | LTCControl | 093-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Readings | Unknown Operations | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Readings | Switching Operations | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Readings | Operations This Read Vac | 0 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | B0127 | NonLTC | 479-1 B | NonLTC Transformer Readings | General Comments | gauge is broken | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Readings | Operations Counter AL | 155 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Readings | Operations Counter AF | 155 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Readings | Maintenance Operations | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Readings | General Comments | | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Patrol Inspection | General Comments | | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Readings | Follow-up Action Required? | n | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Readings | Fault Operations Ground | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | B0127 | NonLTC | 479-1 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | B0127 | NonLTC | 479-1 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | B0127 | NonLTC | 479-1 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | B0127 | NonLTC | 479-1 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | B0127 | NonLTC | 479-1 B | NonLTC Transformer Readings | Oil Temp Max | 0 | °C |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Readings | Switching Operations | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Readings | Operations This Read Vac | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Readings | Maintenance Operations | 0 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | B0127 | NonLTC | 479-1 B | NonLTC Transformer Readings | Oil Temp Present | 0 | °C |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | B0127 | NonLTC | 479-1 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | B0127 | NonLTC | 479-1 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | B0127 | NonLTC | 479-1 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Readings | General Comments | | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0942 | NonLTC | 479-1 C | NonLTC Transformer Readings | Oil Temp Present | 23 | °C |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Patrol Inspection | General Comments | | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Readings | Follow-up Action Required? | n | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Readings | Operations Counter AL | 241 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Readings | Operations Counter AF | 241 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Readings | Maintenance Operations | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0074 | BreakerAirMagnetic | BI-12KV TR 2 | AMCB Readings | Operations This Read AM | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0074 | BreakerAirMagnetic | BI-12KV TR 2 | AMCB Readings | Switching Operations | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 135.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Readings | Accumulated Fault Duty B Ph V | 1.28 | % |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Readings | Accumulated Fault Duty A Ph V | .43 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Readings | 9 Month Operations | 3 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0942 | NonLTC | 479-1 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0942 | NonLTC | 479-1 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCC000097 | LTCControl | BI-Yard | LTC Control Insp | All Connections OK? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCC000097 | LTCControl | BI-Yard | LTC Control Insp | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCC000097 | LTCControl | BI-Yard | LTC Control Insp | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCC000097 | LTCControl | BI-Yard | LTC Control Insp | LTC Operation Checked? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCC000097 | LTCControl | BI-Yard | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCC000097 | LTCControl | BI-Yard | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCC000097 | LTCControl | BI-Yard | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCC000097 | LTCControl | BI-Yard | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCC000097 | LTCControl | BI-Yard | LTC Control Insp | VRR Time Delay | 3 | Seconds |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCC000777 | LTCControl | 093-5 | LTC Control Insp | General Comments | | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCC000777 | LTCControl | 093-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCC000777 | LTCControl | 093-5 | LTC Control Insp | All Connections OK? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0942 | NonLTC | 479-1 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0942 | NonLTC | 479-1 C | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Readings | Accumulated Fault Duty A Ph V | 1.03 | % |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Readings | 9 Month Operations | 1 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0942 | NonLTC | 479-1 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0942 | NonLTC | 479-1 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0942 | NonLTC | 479-1 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0074 | BreakerAirMagnetic | BI-12KV TR 2 | AMCB Readings | Amps A Ø | 150.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0074 | BreakerAirMagnetic | BI-12KV TR 2 | AMCB Readings | Amps B Ø | 165.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0074 | BreakerAirMagnetic | BI-12KV TR 2 | AMCB Readings | Amps C Ø | 165.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0074 | BreakerAirMagnetic | BI-12KV TR 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0074 | BreakerAirMagnetic | BI-12KV TR 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0841 | Regulator | 479-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0841 | Regulator | 479-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0841 | Regulator | 479-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0841 | Regulator | 479-1 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0841 | Regulator | 479-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0841 | Regulator | 479-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0841 | Regulator | 479-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0841 | Regulator | 479-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0841 | Regulator | 479-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0074 | BreakerAirMagnetic | BI-12KV TR 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0074 | BreakerAirMagnetic | BI-12KV TR 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | PF000019 | PowerFuse | BI-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | PF000019 | PowerFuse | BI-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | PF000019 | PowerFuse | BI-12KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0074 | BreakerAirMagnetic | BI-12KV TR 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0074 | BreakerAirMagnetic | BI-12KV TR 2 | AMCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0074 | BreakerAirMagnetic | BI-12KV TR 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0074 | BreakerAirMagnetic | BI-12KV TR 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0074 | BreakerAirMagnetic | BI-12KV TR 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Readings | Operations Counter AF | 431 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Readings | Operations Counter AL | 431 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Readings | Operations This Read Vac | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Readings | Switching Operations | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Readings | Unknown Operations | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0074 | BreakerAirMagnetic | BI-12KV TR 2 | AMCB Readings | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0074 | BreakerAirMagnetic | BI-12KV TR 2 | AMCB Patrol Inspection | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0074 | BreakerAirMagnetic | BI-12KV TR 2 | AMCB Readings | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0074 | BreakerAirMagnetic | BI-12KV TR 2 | AMCB Readings | Maintenance Operations | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0074 | BreakerAirMagnetic | BI-12KV TR 2 | AMCB Readings | Operations Counter AF | 392 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0074 | BreakerAirMagnetic | BI-12KV TR 2 | AMCB Readings | Operations Counter AL | 392 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Readings | Amps C Ø | 93.0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Readings | Amps B Ø | 87.0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Readings | Amps A Ø | 79.0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0146 | BreakerVacuum | 093-0203 | VCB Readings | Accumulated Fault Duty C Ph V | .85 | % |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Readings | Amps C Ø | 420.0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Readings | Amps B Ø | 370.0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Readings | Amps A Ø | 411.0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000497 | BreakerVacuum | 093-5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 25 | °C |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 25 | °C |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 25 | °C |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 40 | °C |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 30 | °C |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 40 | °C |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | WithLTC | BI-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | LTCMechanism | BI-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | LTCMechanism | BI-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | LTCMechanism | BI-TRANS 2 | LTC Counter Readings | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | LTCMechanism | BI-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0068 | BreakerAirMagnetic | BI-1222 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0068 | BreakerAirMagnetic | BI-1222 | AMCB Readings | 9 Months Operations | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | LTCMechanism | BI-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 184916 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | LTCMechanism | BI-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 184916 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | LTCMechanism | BI-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | LTCMechanism | BI-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | LTCMechanism | BI-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | LTCMechanism | BI-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 92 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | LTCMechanism | BI-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | LTCMechanism | BI-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0017 | LTCMechanism | BI-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0068 | BreakerAirMagnetic | BI-1222 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0068 | BreakerAirMagnetic | BI-1222 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0068 | BreakerAirMagnetic | BI-1222 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0068 | BreakerAirMagnetic | BI-1222 | AMCB Readings | Amps A Ø | 11.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0068 | BreakerAirMagnetic | BI-1222 | AMCB Readings | Amps B Ø | 8.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0068 | BreakerAirMagnetic | BI-1222 | AMCB Readings | Amps C Ø | 10.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0068 | BreakerAirMagnetic | BI-1222 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0068 | BreakerAirMagnetic | BI-1222 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0068 | BreakerAirMagnetic | BI-1222 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | ST000308 | Structure | 680-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0068 | BreakerAirMagnetic | BI-1222 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0068 | BreakerAirMagnetic | BI-1222 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0068 | BreakerAirMagnetic | BI-1222 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0068 | BreakerAirMagnetic | BI-1222 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0068 | BreakerAirMagnetic | BI-1222 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0068 | BreakerAirMagnetic | BI-1222 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0068 | BreakerAirMagnetic | BI-1222 | AMCB Readings | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0068 | BreakerAirMagnetic | BI-1222 | AMCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0068 | BreakerAirMagnetic | BI-1222 | AMCB Readings | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0068 | BreakerAirMagnetic | BI-1222 | AMCB Readings | Maintenance Operations | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0068 | BreakerAirMagnetic | BI-1222 | AMCB Readings | Operations Counter AF | 585 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0068 | BreakerAirMagnetic | BI-1222 | AMCB Readings | Operations Counter AL | 585 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0068 | BreakerAirMagnetic | BI-1222 | AMCB Readings | Operations This Read AM | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0068 | BreakerAirMagnetic | BI-1222 | AMCB Readings | Switching Operations | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | ST000308 | Structure | 680-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | ST000308 | Structure | 680-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | ST000308 | Structure | 680-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | ST000308 | Structure | 680-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | ST000308 | Structure | 680-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | ST000308 | Structure | 680-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Readings | Unknown Operations | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Readings | Switching Operations | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Readings | Operations This Read Vac | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Readings | Operations Counter AL | 316 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Readings | Operations Counter AF | 316 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Readings | Maintenance Operations | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Readings | General Comments | | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Patrol Inspection | General Comments | | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Readings | Follow-up Action Required? | n | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Readings | Fault Operations Ground | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | ST000308 | Structure | 680-Structure | Structure Patrol Inspection | General Comments | | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | ST000308 | Structure | 680-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | ST000308 | Structure | 680-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | ST000308 | Structure | 680-Structure | Structure Patrol Inspection | Interruptrs/Puffrs Visual OK? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | ST000308 | Structure | 680-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | ST000308 | Structure | 680-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | ST000308 | Structure | 680-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | ST000612 | Structure | BI-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | ST000612 | Structure | BI-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | ST000612 | Structure | BI-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | ST000612 | Structure | BI-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | ST000612 | Structure | BI-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | ST000612 | Structure | BI-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | ST000612 | Structure | BI-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | ST000612 | Structure | BI-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | ST000612 | Structure | BI-Structure | Structure Patrol Inspection | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | ST000612 | Structure | BI-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | ST000612 | Structure | BI-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | ST000612 | Structure | BI-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | ST000612 | Structure | BI-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | ST000612 | Structure | BI-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | ST000612 | Structure | BI-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | ST000612 | Structure | BI-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | FE000626 | Fence | BI-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | FE000626 | Fence | BI-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | FE000626 | Fence | BI-Fence | Fence Patrol Inspection | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | FE000626 | Fence | BI-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | FE000626 | Fence | BI-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | FE000626 | Fence | BI-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | FE000626 | Fence | BI-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | FE000626 | Fence | BI-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | FE000626 | Fence | BI-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | FE000626 | Fence | BI-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | FE000626 | Fence | BI-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | FE000626 | Fence | BI-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | FE000626 | Fence | BI-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | FE000626 | Fence | BI-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | FE000626 | Fence | BI-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | FE000626 | Fence | BI-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1501 | Regulator | 680-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1501 | Regulator | 680-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1501 | Regulator | 680-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1501 | Regulator | 680-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1501 | Regulator | 680-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1501 | Regulator | 680-1 A | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1501 | Regulator | 680-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1501 | Regulator | 680-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1501 | Regulator | 680-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1501 | Regulator | 680-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1501 | Regulator | 680-1 A | Regulator Patrol Inspection | General Comments | NEW COUNTER | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1501 | Regulator | 680-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1501 | Regulator | 680-1 A | Regulator Patrol Inspection | Max Tap Position | 4L | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1501 | Regulator | 680-1 A | Regulator Patrol Inspection | Min Tap Position | 13L | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1501 | Regulator | 680-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1501 | Regulator | 680-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1501 | Regulator | 680-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1501 | Regulator | 680-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1501 | Regulator | 680-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1501 | Regulator | 680-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 412 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1501 | Regulator | 680-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1501 | Regulator | 680-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1501 | Regulator | 680-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1501 | Regulator | 680-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | ST000308 | Structure | 680-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0943 | NonLTC | 479-1 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0943 | NonLTC | 479-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0943 | NonLTC | 479-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0943 | NonLTC | 479-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0943 | NonLTC | 479-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0943 | NonLTC | 479-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0943 | NonLTC | 479-1 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCM000058 | LTCMechanism | 093-5 | LTC Counter Readings | LTC As Left Counter | 313587 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCM000058 | LTCMechanism | 093-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCM000058 | LTCMechanism | 093-5 | LTC Counter Readings | LTC Current Tap Position | 4R | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCM000058 | LTCMechanism | 093-5 | LTC Counter Readings | LTC Max Tap Position | 10R | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCM000058 | LTCMechanism | 093-5 | LTC Counter Readings | LTC Min Tap Position | 3L | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCM000058 | LTCMechanism | 093-5 | LTC Counter Readings | LTC Operations Since Last Insp | 1212 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCM000058 | LTCMechanism | 093-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCM000058 | LTCMechanism | 093-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCM000058 | LTCMechanism | 093-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | BAT000107 | Battery | BI-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | BAT000107 | Battery | BI-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | BAT000107 | Battery | BI-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | BAT000107 | Battery | BI-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | BAT000107 | Battery | BI-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | BAT000107 | Battery | BI-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | BAT000107 | Battery | BI-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | BAT000107 | Battery | BI-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | BAT000107 | Battery | BI-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | BAT000107 | Battery | BI-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | BAT000107 | Battery | BI-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | BAT000107 | Battery | BI-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 55.00 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Readings | Winding Temp Max | 60 | °C |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Readings | Totalizer Meter Reading | 1.2246 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Readings | LTC Totalizer Reading | 11756.16 | kw |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Readings | General Comments | | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Patrol Inspection | Fans Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | WithLTC | 093-6 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | YD000240 | Yard | 618-Yard | Yard Patrol Inspection | Ambient Temp | 43 | °F |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | YD000240 | Yard | 618-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | YD000240 | Yard | 618-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | YD000240 | Yard | 618-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | YD000240 | Yard | 618-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | YD000240 | Yard | 618-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | YD000240 | Yard | 618-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | YD000240 | Yard | 618-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | YD000240 | Yard | 618-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | YD000240 | Yard | 618-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | YD000240 | Yard | 618-Yard | Yard Patrol Inspection | General Comments | small washout near culvert in driveway | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | YD000240 | Yard | 618-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | YD000240 | Yard | 618-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | YD000240 | Yard | 618-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Readings | Amps C Ø | 125.0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Readings | Amps B Ø | 110.0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Readings | Amps A Ø | 30.0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0151 | BreakerVacuum | 680-0641 | VCB Readings | 9 Month Operations | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCC000946 | LTCControl | 093-6 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCC000946 | LTCControl | 093-6 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCC000946 | LTCControl | 093-6 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCC000946 | LTCControl | 093-6 | LTC Control Insp | LTC Output Voltage Level | 124.3 | VAC |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCC000946 | LTCControl | 093-6 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCC000946 | LTCControl | 093-6 | LTC Control Insp | General Comments | | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCC000946 | LTCControl | 093-6 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCC000946 | LTCControl | 093-6 | LTC Control Insp | All Connections OK? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCM000058 | LTCMechanism | 093-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCM000058 | LTCMechanism | 093-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCM000058 | LTCMechanism | 093-5 | LTC Counter Readings | General Comments | | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCM000058 | LTCMechanism | 093-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | LTCM000058 | LTCMechanism | 093-5 | LTC Counter Readings | LTC As Found Counter | 313575 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0943 | NonLTC | 479-1 A | NonLTC Transformer Readings | Totalizer Meter Reading | .5520 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0943 | NonLTC | 479-1 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 200 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0943 | NonLTC | 479-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0943 | NonLTC | 479-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0943 | NonLTC | 479-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0943 | NonLTC | 479-1 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0943 | NonLTC | 479-1 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0943 | NonLTC | 479-1 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0943 | NonLTC | 479-1 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0943 | NonLTC | 479-1 A | NonLTC Transformer Readings | Oil Temp Present | 27 | °C |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0943 | NonLTC | 479-1 A | NonLTC Transformer Readings | Oil Temp Max | 53 | °C |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0943 | NonLTC | 479-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0943 | NonLTC | 479-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 52.50 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0943 | NonLTC | 479-1 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 110.40 | kw |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0943 | NonLTC | 479-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0943 | NonLTC | 479-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0943 | NonLTC | 479-1 A | NonLTC Transformer Readings | General Comments | ok | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0943 | NonLTC | 479-1 A | NonLTC Transformer Patrol Inspection | General Comments | ok | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0943 | NonLTC | 479-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | ST000246 | Structure | 618-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | ST000246 | Structure | 618-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | ST000246 | Structure | 618-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | ST000246 | Structure | 618-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | ST000246 | Structure | 618-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | ST000246 | Structure | 618-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | ST000246 | Structure | 618-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | ST000246 | Structure | 618-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | CH000179 | ControlHouse | BI-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | CH000179 | ControlHouse | BI-Control House | Control House Patrol Inspection | Restroom Clean & OK? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | CH000179 | ControlHouse | BI-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | CH000179 | ControlHouse | BI-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | CH000179 | ControlHouse | BI-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | CH000179 | ControlHouse | BI-Control House | Control House Patrol Inspection | General Comments | Changed two 8 foot bulbs in control house. | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | CH000179 | ControlHouse | BI-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | CH000179 | ControlHouse | BI-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | CH000179 | ControlHouse | BI-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | CH000179 | ControlHouse | BI-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | CH000179 | ControlHouse | BI-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | CH000179 | ControlHouse | BI-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | CH000179 | ControlHouse | BI-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | CH000179 | ControlHouse | BI-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | CH000179 | ControlHouse | BI-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | CH000179 | ControlHouse | BI-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | CH000179 | ControlHouse | BI-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | CH000179 | ControlHouse | BI-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | CH000179 | ControlHouse | BI-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | CH000179 | ControlHouse | BI-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | YD000300 | Yard | 680-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | YD000300 | Yard | 680-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | ST000246 | Structure | 618-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | ST000246 | Structure | 618-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | ST000246 | Structure | 618-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | ST000246 | Structure | 618-Structure | Structure Patrol Inspection | General Comments | barrels starting to deteriorate | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | YD000300 | Yard | 680-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | YD000300 | Yard | 680-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | YD000300 | Yard | 680-Yard | Yard Patrol Inspection | General Comments | | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | YD000300 | Yard | 680-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | YD000300 | Yard | 680-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | YD000300 | Yard | 680-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | YD000300 | Yard | 680-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | YD000300 | Yard | 680-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | YD000300 | Yard | 680-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | YD000300 | Yard | 680-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | YD000300 | Yard | 680-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | YD000300 | Yard | 680-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | YD000300 | Yard | 680-Yard | Yard Patrol Inspection | Ambient Temp | 48 | °F |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | ST000246 | Structure | 618-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | ST000246 | Structure | 618-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | ST000246 | Structure | 618-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | ST000246 | Structure | 618-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | ST000246 | Structure | 618-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | ST000246 | Structure | 618-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | ST000246 | Structure | 618-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | ST000246 | Structure | 618-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | ST000246 | Structure | 618-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | BCH001375 | Charger | 680-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | BCH001375 | Charger | 680-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | BCH001375 | Charger | 680-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | BCH001375 | Charger | 680-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | BCH001375 | Charger | 680-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.3 | amps |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | BCH001375 | Charger | 680-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | BCH001375 | Charger | 680-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | BCH001375 | Charger | 680-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | B0127 | NonLTC | 479-1 B | NonLTC Transformer Patrol Inspection | General Comments | chipped bush | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | B0127 | NonLTC | 479-1 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | B0127 | NonLTC | 479-1 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | B0127 | NonLTC | 479-1 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | B0127 | NonLTC | 479-1 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | B0127 | NonLTC | 479-1 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | B0127 | NonLTC | 479-1 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | B0127 | NonLTC | 479-1 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0841 | Regulator | 479-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Readings | Accumulated Fault Duty C Ph V | 6.4 | % |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Readings | Accumulated Fault Duty B Ph V | 7.68 | % |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Readings | Accumulated Fault Duty A Ph V | 6.4 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0077 | BreakerVacuum | 093-0201 | VCB Readings | 9 Month Operations | 1 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Readings | Maintenance Operations | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Readings | General Comments | | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Patrol Inspection | General Comments | | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | LTCMechanism | 093-6 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | LTCMechanism | 093-6 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | LTCMechanism | 093-6 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | LTCMechanism | 093-6 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | LTCMechanism | 093-6 | LTC Counter Readings | LTC Operations Since Last Insp | 1111 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | LTCMechanism | 093-6 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | LTCMechanism | 093-6 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | LTCMechanism | 093-6 | LTC Counter Readings | LTC Max Tap Position | 16R | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | LTCMechanism | 093-6 | LTC Counter Readings | LTC Current Tap Position | 3R | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | LTCMechanism | 093-6 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | LTCMechanism | 093-6 | LTC Counter Readings | LTC As Left Counter | 140065 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | LTCMechanism | 093-6 | LTC Counter Readings | LTC As Found Counter | 140055 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | LTCMechanism | 093-6 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | LTCMechanism | 093-6 | LTC Counter Readings | General Comments | | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | LTCMechanism | 093-6 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Readings | Follow-up Action Required? | n | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Readings | Fault Operations Ground | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | M0101 | LTCMechanism | 093-6 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Readings | Amps C Ø | 206.0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Readings | Amps B Ø | 205.0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Readings | Amps A Ø | 209.0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Readings | Accumulated Fault Duty C Ph V | 7.15 | % |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Readings | Accumulated Fault Duty B Ph V | 6.25 | % |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Readings | Accumulated Fault Duty A Ph V | 5.81 | % |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0105 | BreakerVacuum | 093-0204 | VCB Readings | 9 Month Operations | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | CH000179 | ControlHouse | BI-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | CH000179 | ControlHouse | BI-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | CH000179 | ControlHouse | BI-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | CH000179 | ControlHouse | BI-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | ST000246 | Structure | 618-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Readings | Amps C Ø | 445.0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Readings | Amps B Ø | 408.0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Readings | Amps A Ø | 441.0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Readings | 9 Month Operations | 9 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | FE000296 | Fence | 680-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | FE000296 | Fence | 680-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | FE000296 | Fence | 680-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | FE000296 | Fence | 680-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | FE000296 | Fence | 680-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | FE000296 | Fence | 680-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | FE000296 | Fence | 680-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | FE000296 | Fence | 680-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | FE000296 | Fence | 680-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | FE000296 | Fence | 680-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | FE000296 | Fence | 680-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | FE000296 | Fence | 680-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | FE000296 | Fence | 680-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | FE000296 | Fence | 680-Fence | Fence Patrol Inspection | General Comments | | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | FE000296 | Fence | 680-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | FE000296 | Fence | 680-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | ST000308 | Structure | 680-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | ST000308 | Structure | 680-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | ST000308 | Structure | 680-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | ST000308 | Structure | 680-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCM000021 | LTCMechanism | BI-Yard | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCM000021 | LTCMechanism | BI-Yard | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCM000021 | LTCMechanism | BI-Yard | LTC Counter Readings | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCM000021 | LTCMechanism | BI-Yard | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCM000021 | LTCMechanism | BI-Yard | LTC Counter Readings | LTC As Found Counter | 14493 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCM000021 | LTCMechanism | BI-Yard | LTC Counter Readings | LTC As Left Counter | 14493 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCM000021 | LTCMechanism | BI-Yard | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCM000021 | LTCMechanism | BI-Yard | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCM000021 | LTCMechanism | BI-Yard | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCM000021 | LTCMechanism | BI-Yard | LTC Counter Readings | LTC Min Tap Position | Neutral | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | ST000308 | Structure | 680-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | ST000308 | Structure | 680-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCM000021 | LTCMechanism | BI-Yard | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCM000021 | LTCMechanism | BI-Yard | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCM000021 | LTCMechanism | BI-Yard | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 20 | °C |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCM000021 | LTCMechanism | BI-Yard | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 20 | °C |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCM000021 | LTCMechanism | BI-Yard | LTC Counter Readings | LTC Operations Since Last Insp | 110 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCM000021 | LTCMechanism | BI-Yard | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCM000021 | LTCMechanism | BI-Yard | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCM000021 | LTCMechanism | BI-Yard | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCM000021 | LTCMechanism | BI-Yard | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | ST000308 | Structure | 680-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | ST000308 | Structure | 680-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | ST000308 | Structure | 680-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0840 | Regulator | 479-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0840 | Regulator | 479-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0840 | Regulator | 479-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0840 | Regulator | 479-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0840 | Regulator | 479-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 205007 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0840 | Regulator | 479-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0840 | Regulator | 479-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0840 | Regulator | 479-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0840 | Regulator | 479-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0840 | Regulator | 479-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0840 | Regulator | 479-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0840 | Regulator | 479-1 A | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0840 | Regulator | 479-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0840 | Regulator | 479-1 A | Regulator Patrol Inspection | General Comments | ok | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0840 | Regulator | 479-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | FE000218 | Fence | 479-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | FE000218 | Fence | 479-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | FE000218 | Fence | 479-Fence | Fence Patrol Inspection | General Comments | ok | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | FE000218 | Fence | 479-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | FE000218 | Fence | 479-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | FE000218 | Fence | 479-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | FE000218 | Fence | 479-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0840 | Regulator | 479-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0840 | Regulator | 479-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0840 | Regulator | 479-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0840 | Regulator | 479-1 A | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0840 | Regulator | 479-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | FE000218 | Fence | 479-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | FE000218 | Fence | 479-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | FE000218 | Fence | 479-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | FE000218 | Fence | 479-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | FE000218 | Fence | 479-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | FE000218 | Fence | 479-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | FE000218 | Fence | 479-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | FE000218 | Fence | 479-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | FE000218 | Fence | 479-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | BCH000114 | Charger | BI-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | BCH000114 | Charger | BI-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | BCH000114 | Charger | BI-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | BCH000114 | Charger | BI-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | BCH000114 | Charger | BI-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 8.5 | amps |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | BCH000114 | Charger | BI-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 54.0 | VDC |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | BCH000114 | Charger | BI-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 54.0 | VDC |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | BCH000114 | Charger | BI-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0840 | Regulator | 479-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0840 | Regulator | 479-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0840 | Regulator | 479-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0840 | Regulator | 479-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Readings | Unknown Operations | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Readings | Switching Operations | 1 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Readings | Operations This Read Vac | 5 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Readings | Operations Counter AL | 267 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Readings | Operations Counter AF | 267 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Readings | Maintenance Operations | 4 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Readings | General Comments | DC ground troubleshooting | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Patrol Inspection | General Comments | | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Readings | Follow-up Action Required? | n | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Readings | Fault Operations Ground | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0170 | BreakerVacuum | 093-6 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | ST000190 | Structure | 479-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Readings | Operations Counter AF | 344 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Readings | Operations Counter AL | 344 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | YD000628 | Yard | BI-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | YD000628 | Yard | BI-Yard | Yard Patrol Inspection | Follow-up Action Required? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | YD000628 | Yard | BI-Yard | Yard Patrol Inspection | General Comments | 2 incadescent bulbs out in yard. 2 flood lights out. | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | YD000628 | Yard | BI-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | YD000628 | Yard | BI-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | YD000628 | Yard | BI-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | YD000628 | Yard | BI-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | YD000628 | Yard | BI-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Readings | Operations This Read Vac | 1 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | YD000628 | Yard | BI-Yard | Yard Patrol Inspection | Yard Lights Working? | n | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Readings | Switching Operations | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Readings | Unknown Operations | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0182 | WithLTC | BI-Yard | LTC Transformer Patrol Inspection | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0182 | WithLTC | BI-Yard | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0182 | WithLTC | BI-Yard | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | ST000190 | Structure | 479-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.1694 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0182 | WithLTC | BI-Yard | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0182 | WithLTC | BI-Yard | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0182 | WithLTC | BI-Yard | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0182 | WithLTC | BI-Yard | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | ST000190 | Structure | 479-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | ST000190 | Structure | 479-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | ST000190 | Structure | 479-Structure | Structure Patrol Inspection | General Comments | center phase of HV switch wire tied | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Readings | Unknown Operations | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Readings | Switching Operations | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Readings | Operations This Read Vac | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Readings | Operations Counter AL | 326 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Readings | Operations Counter AF | 326 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Readings | Maintenance Operations | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Readings | General Comments | | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Patrol Inspection | General Comments | | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Readings | Follow-up Action Required? | n | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Readings | Fault Operations Ground | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | WX0515 | RecloserHydraulic | 479-1903 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 182 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | WX0515 | RecloserHydraulic | 479-1903 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | WX0515 | RecloserHydraulic | 479-1903 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | WX0515 | RecloserHydraulic | 479-1903 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 129 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | WX0515 | RecloserHydraulic | 479-1903 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | WX0515 | RecloserHydraulic | 479-1903 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | WX0515 | RecloserHydraulic | 479-1903 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | WX0515 | RecloserHydraulic | 479-1903 | Recloser Hydraulic Patrol Inspection | General Comments | ok | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | WX0515 | RecloserHydraulic | 479-1903 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | WX0515 | RecloserHydraulic | 479-1903 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | WX0515 | RecloserHydraulic | 479-1903 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | YD000628 | Yard | BI-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | YD000628 | Yard | BI-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | YD000628 | Yard | BI-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | YD000628 | Yard | BI-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | YD000628 | Yard | BI-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0072 | BreakerAirMagnetic | BI-12KV BUS TIE SEC 2 | AMCB Readings | 9 Month Ops New | 1 | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0704 | Regulator | 618-1 C | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0704 | Regulator | 618-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0072 | BreakerAirMagnetic | BI-12KV BUS TIE SEC 2 | AMCB Readings | 9 Months Operations | 1 | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0704 | Regulator | 618-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | PF000054 | PowerFuse | BI-STA SER NO 2 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | PF000054 | PowerFuse | BI-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | PF000054 | PowerFuse | BI-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | PF000055 | PowerFuse | BI-12KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | PF000055 | PowerFuse | BI-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | PF000055 | PowerFuse | BI-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0704 | Regulator | 618-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0704 | Regulator | 618-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0704 | Regulator | 618-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.1 | volts |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0704 | Regulator | 618-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 97284 | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0704 | Regulator | 618-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0704 | Regulator | 618-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0704 | Regulator | 618-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0704 | Regulator | 618-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0072 | BreakerAirMagnetic | BI-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0072 | BreakerAirMagnetic | BI-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0072 | BreakerAirMagnetic | BI-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0182 | WithLTC | BI-Yard | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0072 | BreakerAirMagnetic | BI-12KV BUS TIE SEC 2 | AMCB Readings | Amps A Ø | 0.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0072 | BreakerAirMagnetic | BI-12KV BUS TIE SEC 2 | AMCB Readings | Amps B Ø | 0.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0072 | BreakerAirMagnetic | BI-12KV BUS TIE SEC 2 | AMCB Readings | Amps C Ø | 0.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0072 | BreakerAirMagnetic | BI-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0072 | BreakerAirMagnetic | BI-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0072 | BreakerAirMagnetic | BI-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0072 | BreakerAirMagnetic | BI-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0072 | BreakerAirMagnetic | BI-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | YD000628 | Yard | BI-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | YD000628 | Yard | BI-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Readings | Follow-up Action Required? | n | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | YD000184 | Yard | 479-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | YD000184 | Yard | 479-Yard | Yard Patrol Inspection | General Comments | small washout | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | YD000184 | Yard | 479-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1500 | Regulator | 680-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1500 | Regulator | 680-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1500 | Regulator | 680-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1500 | Regulator | 680-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1500 | Regulator | 680-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1500 | Regulator | 680-1 B | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1500 | Regulator | 680-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1500 | Regulator | 680-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1500 | Regulator | 680-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | BAT001558 | Battery | 680-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | BAT001558 | Battery | 680-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | BAT001558 | Battery | 680-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Readings | 9 Month Operations | 8 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | BAT001558 | Battery | 680-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | BAT001558 | Battery | 680-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | BAT001558 | Battery | 680-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | BAT001558 | Battery | 680-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | BAT001558 | Battery | 680-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | BAT001558 | Battery | 680-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | BAT001558 | Battery | 680-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | BAT001558 | Battery | 680-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | BAT001558 | Battery | 680-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | BAT001558 | Battery | 680-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1500 | Regulator | 680-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1500 | Regulator | 680-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1500 | Regulator | 680-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1500 | Regulator | 680-1 B | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1500 | Regulator | 680-1 B | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1500 | Regulator | 680-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1500 | Regulator | 680-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1500 | Regulator | 680-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Patrol Inspection | General Comments | | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Readings | General Comments | | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Readings | Maintenance Operations | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Readings | Operations Counter AF | 201 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Readings | Operations Counter AL | 201 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Readings | Operations This Read Vac | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Readings | Switching Operations | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | ST000190 | Structure | 479-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | ST000190 | Structure | 479-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Readings | Amps C Ø | 35.0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Readings | Amps B Ø | 35.0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Readings | Amps A Ø | 25.0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0152 | BreakerVacuum | 680-0642 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Readings | 9 Month Operations | 3 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Readings | Accumulated Fault Duty A Ph V | 2.13 | % |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Readings | Accumulated Fault Duty B Ph V | 1.71 | % |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Readings | Accumulated Fault Duty C Ph V | .85 | % |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Readings | Amps A Ø | 100.0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Readings | Amps B Ø | 109.0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Readings | Amps C Ø | 100.0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | ST000190 | Structure | 479-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | ST000190 | Structure | 479-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | ST000190 | Structure | 479-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | ST000190 | Structure | 479-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | n | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Readings | Fault Operations Ground | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | ST000190 | Structure | 479-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | ST000190 | Structure | 479-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | ST000190 | Structure | 479-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | YD000184 | Yard | 479-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | YD000184 | Yard | 479-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0070 | BreakerAirMagnetic | BI-1224 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Readings | Maintenance Operations | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0070 | BreakerAirMagnetic | BI-1224 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0070 | BreakerAirMagnetic | BI-1224 | AMCB Readings | 9 Months Operations | 7 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Readings | General Comments | | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .6620 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Readings | Winding Temp Max | 35 | °C |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Readings | Winding Temp Present | 25 | °C |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0702 | Regulator | 618-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Readings | Oil Temp Present | 15 | °C |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Patrol Inspection | General Comments | | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Readings | Follow-up Action Required? | n | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 97.50 | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1403.28 | kw |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0070 | BreakerAirMagnetic | BI-1224 | AMCB Readings | 9 Month Ops New | 7 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Readings | Fault Operations Ground | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Readings | Fault Operations B Ø | 1 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Readings | Fault Adjusted Amps B Phase V | 5.99 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | ST000190 | Structure | 479-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | ST000190 | Structure | 479-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | ST000190 | Structure | 479-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0070 | BreakerAirMagnetic | BI-1224 | AMCB Readings | Switching Operations | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0070 | BreakerAirMagnetic | BI-1224 | AMCB Readings | Operations This Read AM | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0070 | BreakerAirMagnetic | BI-1224 | AMCB Readings | Operations Counter AL | 977 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0070 | BreakerAirMagnetic | BI-1224 | AMCB Readings | Operations Counter AF | 977 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0070 | BreakerAirMagnetic | BI-1224 | AMCB Readings | Maintenance Operations | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0070 | BreakerAirMagnetic | BI-1224 | AMCB Readings | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0070 | BreakerAirMagnetic | BI-1224 | AMCB Patrol Inspection | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0070 | BreakerAirMagnetic | BI-1224 | AMCB Readings | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0070 | BreakerAirMagnetic | BI-1224 | AMCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0070 | BreakerAirMagnetic | BI-1224 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0070 | BreakerAirMagnetic | BI-1224 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0070 | BreakerAirMagnetic | BI-1224 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0070 | BreakerAirMagnetic | BI-1224 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0070 | BreakerAirMagnetic | BI-1224 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0070 | BreakerAirMagnetic | BI-1224 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | ST000190 | Structure | 479-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | ST000190 | Structure | 479-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Readings | General Comments | | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | S0057 | NonLTC | 680-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 6355.20 | kw |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | ST000190 | Structure | 479-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | ST000190 | Structure | 479-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0070 | BreakerAirMagnetic | BI-1224 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0070 | BreakerAirMagnetic | BI-1224 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0070 | BreakerAirMagnetic | BI-1224 | AMCB Readings | Amps C Ø | 70.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0070 | BreakerAirMagnetic | BI-1224 | AMCB Readings | Amps B Ø | 70.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0070 | BreakerAirMagnetic | BI-1224 | AMCB Readings | Amps A Ø | 65.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0070 | BreakerAirMagnetic | BI-1224 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0703 | Regulator | 618-1 B | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0703 | Regulator | 618-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0703 | Regulator | 618-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0703 | Regulator | 618-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0703 | Regulator | 618-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0703 | Regulator | 618-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0703 | Regulator | 618-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0703 | Regulator | 618-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 16041 | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0703 | Regulator | 618-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0703 | Regulator | 618-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0703 | Regulator | 618-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0704 | Regulator | 618-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0704 | Regulator | 618-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0704 | Regulator | 618-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0704 | Regulator | 618-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Readings | General Comments | | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0704 | Regulator | 618-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0704 | Regulator | 618-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0704 | Regulator | 618-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0704 | Regulator | 618-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0704 | Regulator | 618-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0704 | Regulator | 618-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Readings | Accumulated Fault Duty A Ph V | 10.72 | % |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | C0332 | NonLTC | 618-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Readings | 9 Month Operations | 3 | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0704 | Regulator | 618-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0704 | Regulator | 618-1 C | Regulator Patrol Inspection | General Comments | | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0704 | Regulator | 618-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0704 | Regulator | 618-1 C | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | YD000628 | Yard | BI-Yard | Yard Patrol Inspection | Ambient Temp | 30 | °F |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | WX0515 | RecloserHydraulic | 479-1903 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 165 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | WX0515 | RecloserHydraulic | 479-1903 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 32.8 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | WX0515 | RecloserHydraulic | 479-1903 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 38.4 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | WX0515 | RecloserHydraulic | 479-1903 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 32.5 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0702 | Regulator | 618-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0702 | Regulator | 618-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0702 | Regulator | 618-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0702 | Regulator | 618-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0702 | Regulator | 618-1 A | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0702 | Regulator | 618-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Readings | Amps C Ø | 247.0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Readings | Amps B Ø | 210.0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Readings | Amps A Ø | 240.0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Readings | Accumulated Fault Duty C Ph V | 7.59 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0182 | WithLTC | BI-Yard | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | K0078 | BreakerVacuum | 093-0205 | VCB Readings | Accumulated Fault Duty B Ph V | 9.83 | % |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0702 | Regulator | 618-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0702 | Regulator | 618-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0702 | Regulator | 618-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0702 | Regulator | 618-1 A | Regulator Patrol Inspection | General Comments | counter broken | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0182 | WithLTC | BI-Yard | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LT0182 | WithLTC | BI-Yard | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0702 | Regulator | 618-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0702 | Regulator | 618-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | PF000018 | PowerFuse | BI-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | PF000018 | PowerFuse | BI-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | PF000018 | PowerFuse | BI-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0702 | Regulator | 618-1 A | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0702 | Regulator | 618-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0702 | Regulator | 618-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0702 | Regulator | 618-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0702 | Regulator | 618-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0702 | Regulator | 618-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.2 | volts |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0702 | Regulator | 618-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 426763 | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0702 | Regulator | 618-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0702 | Regulator | 618-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0702 | Regulator | 618-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0702 | Regulator | 618-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0703 | Regulator | 618-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0703 | Regulator | 618-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0703 | Regulator | 618-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0703 | Regulator | 618-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0703 | Regulator | 618-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0703 | Regulator | 618-1 B | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0703 | Regulator | 618-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0703 | Regulator | 618-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0703 | Regulator | 618-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0703 | Regulator | 618-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0703 | Regulator | 618-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | R0703 | Regulator | 618-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0067 | BreakerAirMagnetic | BI-1221 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0067 | BreakerAirMagnetic | BI-1221 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0072 | BreakerAirMagnetic | BI-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0072 | BreakerAirMagnetic | BI-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0072 | BreakerAirMagnetic | BI-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0072 | BreakerAirMagnetic | BI-12KV BUS TIE SEC 2 | AMCB Readings | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0072 | BreakerAirMagnetic | BI-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0072 | BreakerAirMagnetic | BI-12KV BUS TIE SEC 2 | AMCB Readings | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0067 | BreakerAirMagnetic | BI-1221 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0067 | BreakerAirMagnetic | BI-1221 | AMCB Readings | Amps C Ø | 50.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0067 | BreakerAirMagnetic | BI-1221 | AMCB Readings | Amps B Ø | 51.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0067 | BreakerAirMagnetic | BI-1221 | AMCB Readings | Amps A Ø | 54.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0067 | BreakerAirMagnetic | BI-1221 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Readings | Fault Operations Ground | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Readings | Follow-up Action Required? | n | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Patrol Inspection | General Comments | | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Readings | General Comments | | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Readings | Maintenance Operations | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Readings | Operations Counter AF | 252 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Readings | Operations Counter AL | 252 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Readings | Operations This Read Vac | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Readings | Switching Operations | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Readings | Unknown Operations | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0072 | BreakerAirMagnetic | BI-12KV BUS TIE SEC 2 | AMCB Readings | Maintenance Operations | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0072 | BreakerAirMagnetic | BI-12KV BUS TIE SEC 2 | AMCB Readings | Operations Counter AF | 78 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0072 | BreakerAirMagnetic | BI-12KV BUS TIE SEC 2 | AMCB Readings | Operations Counter AL | 78 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0072 | BreakerAirMagnetic | BI-12KV BUS TIE SEC 2 | AMCB Readings | Operations This Read AM | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0072 | BreakerAirMagnetic | BI-12KV BUS TIE SEC 2 | AMCB Readings | Switching Operations | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Readings | General Comments | | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Readings | LTC Totalizer Reading | 9650.88 | kw |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Readings | Oil Temp Max | 69 | °C |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0067 | BreakerAirMagnetic | BI-1221 | AMCB Readings | Maintenance Operations | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0067 | BreakerAirMagnetic | BI-1221 | AMCB Readings | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0067 | BreakerAirMagnetic | BI-1221 | AMCB Patrol Inspection | General Comments | | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Readings | Unknown Operations | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0067 | BreakerAirMagnetic | BI-1221 | AMCB Readings | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0067 | BreakerAirMagnetic | BI-1221 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0069 | BreakerAirMagnetic | BI-1223 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Readings | Switching Operations | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Readings | Operations This Read Vac | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Readings | Operations Counter AL | 99988 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Readings | Operations Counter AF | 99988 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Readings | Maintenance Operations | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Readings | General Comments | | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Patrol Inspection | General Comments | | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Readings | Follow-up Action Required? | n | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Readings | Fault Operations Ground | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0069 | BreakerAirMagnetic | BI-1223 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0072 | BreakerAirMagnetic | BI-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0069 | BreakerAirMagnetic | BI-1223 | AMCB Readings | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0069 | BreakerAirMagnetic | BI-1223 | AMCB Patrol Inspection | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0069 | BreakerAirMagnetic | BI-1223 | AMCB Readings | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0069 | BreakerAirMagnetic | BI-1223 | AMCB Readings | Maintenance Operations | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0069 | BreakerAirMagnetic | BI-1223 | AMCB Readings | Operations Counter AF | 661 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0069 | BreakerAirMagnetic | BI-1223 | AMCB Readings | Operations Counter AL | 661 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0069 | BreakerAirMagnetic | BI-1223 | AMCB Readings | Operations This Read AM | 3 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0069 | BreakerAirMagnetic | BI-1223 | AMCB Readings | Switching Operations | 3 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0067 | BreakerAirMagnetic | BI-1221 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0067 | BreakerAirMagnetic | BI-1221 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0067 | BreakerAirMagnetic | BI-1221 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0067 | BreakerAirMagnetic | BI-1221 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0067 | BreakerAirMagnetic | BI-1221 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0842 | Regulator | 479-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0842 | Regulator | 479-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0842 | Regulator | 479-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | CH000381 | ControlHouse | 680-Control House | Control House Patrol Inspection | General Comments | | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | CH000381 | ControlHouse | 680-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | CH000381 | ControlHouse | 680-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | CH000381 | ControlHouse | 680-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | CH000381 | ControlHouse | 680-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | CH000381 | ControlHouse | 680-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | CH000381 | ControlHouse | 680-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | CH000381 | ControlHouse | 680-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | CH000381 | ControlHouse | 680-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | CH000381 | ControlHouse | 680-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | CH000381 | ControlHouse | 680-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | CH000381 | ControlHouse | 680-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000015 | Switchgear | BI-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000015 | Switchgear | BI-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000015 | Switchgear | BI-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000015 | Switchgear | BI-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000015 | Switchgear | BI-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000015 | Switchgear | BI-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000015 | Switchgear | BI-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000015 | Switchgear | BI-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0942 | NonLTC | 479-1 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0942 | NonLTC | 479-1 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0942 | NonLTC | 479-1 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000015 | Switchgear | BI-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000015 | Switchgear | BI-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000015 | Switchgear | BI-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000015 | Switchgear | BI-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000015 | Switchgear | BI-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000015 | Switchgear | BI-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000015 | Switchgear | BI-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000015 | Switchgear | BI-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000015 | Switchgear | BI-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000015 | Switchgear | BI-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000015 | Switchgear | BI-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0942 | NonLTC | 479-1 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0942 | NonLTC | 479-1 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0942 | NonLTC | 479-1 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0942 | NonLTC | 479-1 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0942 | NonLTC | 479-1 C | NonLTC Transformer Patrol Inspection | General Comments | ok | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0942 | NonLTC | 479-1 C | NonLTC Transformer Readings | General Comments | ok | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0942 | NonLTC | 479-1 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0942 | NonLTC | 479-1 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0942 | NonLTC | 479-1 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 159.17 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0942 | NonLTC | 479-1 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 135.00 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | 0942 | NonLTC | 479-1 C | NonLTC Transformer Readings | Oil Temp Max | 53 | °C |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0067 | BreakerAirMagnetic | BI-1221 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0067 | BreakerAirMagnetic | BI-1221 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0067 | BreakerAirMagnetic | BI-1221 | AMCB Readings | 9 Months Operations | 1 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0067 | BreakerAirMagnetic | BI-1221 | AMCB Readings | 9 Month Ops New | 1 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0842 | Regulator | 479-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0842 | Regulator | 479-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0842 | Regulator | 479-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0842 | Regulator | 479-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0842 | Regulator | 479-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0842 | Regulator | 479-1 C | Regulator Patrol Inspection | Current Tap Position | 9L | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0842 | Regulator | 479-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Readings | Totalizer Meter Reading | .6702 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Readings | Winding Temp Max | 50 | °C |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Readings | Winding Temp Present | 20 | °C |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0842 | Regulator | 479-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0842 | Regulator | 479-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0842 | Regulator | 479-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Readings | Amps C Ø | 0.0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Readings | Amps B Ø | 0.0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Readings | Amps A Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | MB0172 | BreakerVacuum | 093-BT6-5 | VCB Readings | 9 Month Operations | 2 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0842 | Regulator | 479-1 C | Regulator Patrol Inspection | General Comments | control door will not close, needs replacement | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0842 | Regulator | 479-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0842 | Regulator | 479-1 C | Regulator Patrol Inspection | Max Tap Position | 5L | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0842 | Regulator | 479-1 C | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCC000403 | LTCControl | BI-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCC000403 | LTCControl | BI-TRANS 2 | LTC Control Insp | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LTCC000403 | LTCControl | BI-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0842 | Regulator | 479-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0842 | Regulator | 479-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0842 | Regulator | 479-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0842 | Regulator | 479-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | CH000381 | ControlHouse | 680-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | CH000381 | ControlHouse | 680-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | CH000381 | ControlHouse | 680-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | CH000381 | ControlHouse | 680-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | CH000381 | ControlHouse | 680-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0842 | Regulator | 479-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.7 | volts |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0842 | Regulator | 479-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 3097 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | R0842 | Regulator | 479-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1502 | Regulator | 680-1 C | Regulator Patrol Inspection | Min Tap Position | 13L | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1502 | Regulator | 680-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1502 | Regulator | 680-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1502 | Regulator | 680-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1502 | Regulator | 680-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1502 | Regulator | 680-1 C | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0069 | BreakerAirMagnetic | BI-1223 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0069 | BreakerAirMagnetic | BI-1223 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1502 | Regulator | 680-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1502 | Regulator | 680-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1502 | Regulator | 680-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1502 | Regulator | 680-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1502 | Regulator | 680-1 C | Regulator Patrol Inspection | General Comments | | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1502 | Regulator | 680-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1502 | Regulator | 680-1 C | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | FE000241 | Fence | 618-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | FE000241 | Fence | 618-Fence | Fence Patrol Inspection | General Comments | | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | FE000241 | Fence | 618-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0069 | BreakerAirMagnetic | BI-1223 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0069 | BreakerAirMagnetic | BI-1223 | AMCB Readings | 9 Months Operations | 3 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0069 | BreakerAirMagnetic | BI-1223 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0069 | BreakerAirMagnetic | BI-1223 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0069 | BreakerAirMagnetic | BI-1223 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0069 | BreakerAirMagnetic | BI-1223 | AMCB Readings | Amps A Ø | 30.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0069 | BreakerAirMagnetic | BI-1223 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | FE000241 | Fence | 618-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | FE000241 | Fence | 618-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | FE000241 | Fence | 618-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | FE000241 | Fence | 618-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | FE000241 | Fence | 618-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | FE000241 | Fence | 618-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0069 | BreakerAirMagnetic | BI-1223 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0069 | BreakerAirMagnetic | BI-1223 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0069 | BreakerAirMagnetic | BI-1223 | AMCB Readings | Amps B Ø | 35.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0069 | BreakerAirMagnetic | BI-1223 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | FE000241 | Fence | 618-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000175 | Switchgear | BI-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000175 | Switchgear | BI-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000175 | Switchgear | BI-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000175 | Switchgear | BI-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000175 | Switchgear | BI-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0069 | BreakerAirMagnetic | BI-1223 | AMCB Readings | Amps C Ø | 35.0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000175 | Switchgear | BI-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000175 | Switchgear | BI-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000175 | Switchgear | BI-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000175 | Switchgear | BI-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000175 | Switchgear | BI-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000175 | Switchgear | BI-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000175 | Switchgear | BI-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000175 | Switchgear | BI-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | FE000241 | Fence | 618-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000175 | Switchgear | BI-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | FE000241 | Fence | 618-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | FE000241 | Fence | 618-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | FE000241 | Fence | 618-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | FE000241 | Fence | 618-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000175 | Switchgear | BI-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000175 | Switchgear | BI-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000175 | Switchgear | BI-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000175 | Switchgear | BI-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | SWG000175 | Switchgear | BI-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0067 | BreakerAirMagnetic | BI-1221 | AMCB Readings | Operations Counter AF | 17 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0067 | BreakerAirMagnetic | BI-1221 | AMCB Readings | Operations Counter AL | 17 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0067 | BreakerAirMagnetic | BI-1221 | AMCB Readings | Operations This Read AM | 0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | BK000590 | BreakerVacuum | 093-0200 | VCB Readings | Unknown Operations | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1500 | Regulator | 680-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1500 | Regulator | 680-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1500 | Regulator | 680-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 49207 | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | YD000184 | Yard | 479-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | YD000184 | Yard | 479-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | YD000184 | Yard | 479-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | YD000184 | Yard | 479-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | YD000184 | Yard | 479-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | YD000184 | Yard | 479-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/10/2023 12:46 | Distribution | Nelson Quarterly Inspection | FE000241 | Fence | 618-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0067 | BreakerAirMagnetic | BI-1221 | AMCB Readings | Switching Operations | 0 | |
| 3/10/2023 9:50 | Distribution | Bishop Quarterly Inspection | LB0069 | BreakerAirMagnetic | BI-1223 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1502 | Regulator | 680-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1502 | Regulator | 680-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1502 | Regulator | 680-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1502 | Regulator | 680-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1502 | Regulator | 680-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 42992 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1502 | Regulator | 680-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1502 | Regulator | 680-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | YD000184 | Yard | 479-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/10/2023 14:18 | Distribution | Echols Quarterly Inspection | YD000184 | Yard | 479-Yard | Yard Patrol Inspection | Ambient Temp | 47 | °F |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Readings | 9 Month Operations | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Readings | Amps A Ø | 60.0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Readings | Amps B Ø | 70.0 | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Readings | Amps C Ø | 55.0 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | K0124 | BreakerVacuum | 680-0555 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1500 | Regulator | 680-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1500 | Regulator | 680-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/10/2023 15:07 | Distribution | London Quarterly Inspection | C0484 | WithLTC | 093-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1502 | Regulator | 680-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1500 | Regulator | 680-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1500 | Regulator | 680-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1502 | Regulator | 680-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1502 | Regulator | 680-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/10/2023 14:45 | Distribution | Winchester Water Quarterly Inspection | R1502 | Regulator | 680-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000311 | Fence | Retired Distribution | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000311 | Fence | Retired Distribution | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000311 | Fence | Retired Distribution | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000311 | Fence | Retired Distribution | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000311 | Fence | Retired Distribution | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000311 | Fence | Retired Distribution | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000311 | Fence | Retired Distribution | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000311 | Fence | Retired Distribution | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000311 | Fence | Retired Distribution | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000311 | Fence | Retired Distribution | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000311 | Fence | Retired Distribution | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000311 | Fence | Retired Distribution | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000311 | Fence | Retired Distribution | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000311 | Fence | Retired Distribution | Fence Patrol Inspection | General Comments | | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000311 | Fence | Retired Distribution | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000311 | Fence | Retired Distribution | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BAT000141 | Battery | Retired Distribution | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BAT000141 | Battery | Retired Distribution | Battery Patrol Inspection | Straps Corrosion Free? | n | If no, which cells in comments |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BAT000141 | Battery | Retired Distribution | Battery Patrol Inspection | General Comments | There are roughly 14 fill caps broken on the batteries. There are straps with corrosion as well. | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BAT000141 | Battery | Retired Distribution | Battery Patrol Inspection | Follow-up Action Required? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BAT000141 | Battery | Retired Distribution | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BAT000141 | Battery | Retired Distribution | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BAT000141 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BAT000141 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BAT000141 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BAT000141 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BAT000141 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BAT000141 | Battery | Retired Distribution | Battery Patrol Inspection | All Connections OK? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BCH000033 | Charger | Retired Distribution | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 4.500 | millivolts |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BCH000033 | Charger | Retired Distribution | Battery Charger Patrol Insp | As Found Float Voltage | 135.0 | VDC |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BCH000033 | Charger | Retired Distribution | Battery Charger Patrol Insp | As Left Float Voltage | 135.0 | VDC |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BCH000033 | Charger | Retired Distribution | Battery Charger Patrol Insp | Battery Charger Current | 3.5 | amps |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BCH000033 | Charger | Retired Distribution | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BCH000033 | Charger | Retired Distribution | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BCH000033 | Charger | Retired Distribution | Battery Charger Patrol Insp | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BCH000033 | Charger | Retired Distribution | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0648 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0648 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 2 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0648 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 2 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0648 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 2 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0648 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 22.36 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0648 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0648 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0648 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | a,b,c phase ioc | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0648 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0648 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0648 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0648 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 30.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0648 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 50.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0648 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 55.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0648 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0648 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 11 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0648 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 22.36 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0648 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 22.36 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0648 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 5 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0648 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 99 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0648 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 99 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0648 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 6 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0648 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0648 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0648 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0648 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0647 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0647 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0647 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 62 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0647 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 62 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0647 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 2 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0647 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 2 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0647 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0647 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0647 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0647 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0647 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0647 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 36.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0647 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 27.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0647 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0647 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0647 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0647 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0647 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0647 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0647 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0647 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 36.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0647 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0647 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0647 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0647 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0647 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0646 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 266 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0646 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0646 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | a,b phase ioc, vc may not be working | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0646 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0646 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0646 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0646 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 1 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0646 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 1 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0646 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0646 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 11.18 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0646 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 11.18 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0646 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 43.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0646 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 46.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0646 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 266 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0646 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 40.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0646 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0646 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0646 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0646 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 4 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0646 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 2 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0646 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 2 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0646 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0646 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0646 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0646 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0646 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0645 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0645 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0645 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 12 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0645 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0645 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0645 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 112.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0645 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 87.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0645 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 91.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0645 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 44.72 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0645 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 44.72 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0645 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 44.72 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0645 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 4 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0645 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 4 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0645 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 4 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0645 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0645 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0645 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | a,b,c phase ioc | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0645 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0645 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 12 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0645 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 12 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0645 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 12 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0645 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0645 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0645 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0645 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0645 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0644 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0644 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0644 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0644 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0644 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0644 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0644 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0644 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0644 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 100.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0644 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 108.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0644 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 160.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0644 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 48 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0644 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 48 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0644 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0644 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0644 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0644 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0644 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0644 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 5 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0644 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 5 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0644 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0644 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0644 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0644 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0644 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0644 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0650 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0650 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0650 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 320.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0650 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 300.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0650 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 370.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0650 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0650 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0650 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0650 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 18 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0650 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 18 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0650 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0650 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 62 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0650 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 62 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0650 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0650 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0650 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0650 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0650 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0650 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0650 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0650 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0650 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0650 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0650 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0650 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LB0650 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Readings | Amps C Ø | 46.0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BAT001448 | Battery | 686-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BAT001448 | Battery | 686-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BAT001448 | Battery | 686-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Readings | Amps B Ø | 35.0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Readings | Amps A Ø | 55.0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BAT001448 | Battery | 686-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BAT001448 | Battery | 686-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BAT001448 | Battery | 686-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BAT001448 | Battery | 686-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | ST000587 | Structure | MG-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | ST000587 | Structure | MG-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | ST000587 | Structure | MG-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | ST000587 | Structure | MG-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | ST000587 | Structure | MG-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | ST000587 | Structure | MG-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | ST000587 | Structure | MG-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | ST000587 | Structure | MG-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | ST000587 | Structure | MG-Structure | Structure Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | ST000587 | Structure | MG-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000068 | CapacitorBank | WS-Cap Bank 2 | Capacitor Patrol Inspection | Tank Paint Condition | Adequate | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000068 | CapacitorBank | WS-Cap Bank 2 | Capacitor Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000068 | CapacitorBank | WS-Cap Bank 2 | Capacitor Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | ST000587 | Structure | MG-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Readings | Oil Temp Present | 26 | °C |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Readings | Maintenance Operations | 2 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | CH000167 | ControlHouse | MG-Control House-Distribution | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | CH000167 | ControlHouse | MG-Control House-Distribution | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0632 | BreakerAirMagnetic | MG-452 | AMCB Readings | 9 Month Ops New | 11 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0632 | BreakerAirMagnetic | MG-452 | AMCB Readings | 9 Months Operations | 14 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0632 | BreakerAirMagnetic | MG-452 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | YD000141 | Yard | 771-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | YD000141 | Yard | 771-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | YD000141 | Yard | 771-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0632 | BreakerAirMagnetic | MG-452 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0632 | BreakerAirMagnetic | MG-452 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0632 | BreakerAirMagnetic | MG-452 | AMCB Readings | Amps A Ø | 111.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0632 | BreakerAirMagnetic | MG-452 | AMCB Readings | Amps B Ø | 120.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0632 | BreakerAirMagnetic | MG-452 | AMCB Readings | Amps C Ø | 107.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0632 | BreakerAirMagnetic | MG-452 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0632 | BreakerAirMagnetic | MG-452 | AMCB Readings | Fault Adjusted Amps A Phase AM | 28.64 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0632 | BreakerAirMagnetic | MG-452 | AMCB Readings | Fault Adjusted Amps B Phase AM | 28.64 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0632 | BreakerAirMagnetic | MG-452 | AMCB Readings | Fault Adjusted Amps C Phase AM | 28.64 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0632 | BreakerAirMagnetic | MG-452 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0632 | BreakerAirMagnetic | MG-452 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0632 | BreakerAirMagnetic | MG-452 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0632 | BreakerAirMagnetic | MG-452 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0632 | BreakerAirMagnetic | MG-452 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0632 | BreakerAirMagnetic | MG-452 | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0632 | BreakerAirMagnetic | MG-452 | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0632 | BreakerAirMagnetic | MG-452 | AMCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0632 | BreakerAirMagnetic | MG-452 | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0632 | BreakerAirMagnetic | MG-452 | AMCB Readings | Operations Counter AF | 745 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000068 | CapacitorBank | WS-Cap Bank 2 | Capacitor Patrol Inspection | Warning Signs OK? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1212 | BreakerVacuum | WS-1315-2 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1212 | BreakerVacuum | WS-1315-2 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Patrol Inspection | Gas Accumulation Gauge | Normal | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | YD000141 | Yard | 771-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | YD000141 | Yard | 771-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | YD000141 | Yard | 771-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | YD000141 | Yard | 771-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | YD000141 | Yard | 771-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | CH000167 | ControlHouse | MG-Control House-Distribution | Control House Patrol Inspection | Broom on Site? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | PF000228 | PowerFuse | MK-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | PF000228 | PowerFuse | MK-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | PF000228 | PowerFuse | MK-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | PF000229 | PowerFuse | MK-12KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | PF000229 | PowerFuse | MK-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | PF000229 | PowerFuse | MK-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Readings | General Comments | | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | -1 | psi |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 4049.28 | kw |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Patrol Inspection | General Comments | ok | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Readings | General Comments | ok | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 206.88 | kw |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Readings | Oil Temp Max | 51 | °C |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | YD000317 | Yard | 682-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | YD000317 | Yard | 682-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | YD000317 | Yard | 682-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | YD000317 | Yard | 682-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000068 | CapacitorBank | WS-Cap Bank 2 | Capacitor Patrol Inspection | All Connections OK? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000068 | CapacitorBank | WS-Cap Bank 2 | Capacitor Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000068 | CapacitorBank | WS-Cap Bank 2 | Capacitor Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000068 | CapacitorBank | WS-Cap Bank 2 | Capacitor Patrol Inspection | Cap bank PT in Good Condition? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000068 | CapacitorBank | WS-Cap Bank 2 | Capacitor Patrol Inspection | Capacitor Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000068 | CapacitorBank | WS-Cap Bank 2 | Capacitor Patrol Inspection | Capacitor Rack Condition OK? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1212 | BreakerVacuum | WS-1315-2 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1212 | BreakerVacuum | WS-1315-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1212 | BreakerVacuum | WS-1315-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000068 | CapacitorBank | WS-Cap Bank 2 | Capacitor Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000068 | CapacitorBank | WS-Cap Bank 2 | Capacitor Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000068 | CapacitorBank | WS-Cap Bank 2 | Capacitor Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0024 | Regulator | 494-1 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1212 | BreakerVacuum | WS-1315-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1212 | BreakerVacuum | WS-1315-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1212 | BreakerVacuum | WS-1315-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0024 | Regulator | 494-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | YD000317 | Yard | 682-Yard | Yard Patrol Inspection | General Comments | ok | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | YD000317 | Yard | 682-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0024 | Regulator | 494-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000176 | Switchgear | WO-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000176 | Switchgear | WO-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000176 | Switchgear | WO-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000176 | Switchgear | WO-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000176 | Switchgear | WO-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000176 | Switchgear | WO-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000176 | Switchgear | WO-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000176 | Switchgear | WO-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000176 | Switchgear | WO-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000176 | Switchgear | WO-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1212 | BreakerVacuum | WS-1315-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1212 | BreakerVacuum | WS-1315-2 | VCB Readings | Operations Counter AL | 187 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1212 | BreakerVacuum | WS-1315-2 | VCB Readings | Operations Counter AF | 187 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1212 | BreakerVacuum | WS-1315-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | YD000141 | Yard | 771-Yard | Yard Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | YD000141 | Yard | 771-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | LTCMechanism | 641-1 | LTC Counter Readings | LTC As Left Counter | 20717 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | LTCMechanism | 641-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Readings | 9 Month Operations | 1 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1329 | Regulator | 439-1 A | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | LTCMechanism | 641-1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | LTCMechanism | 641-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | LTCMechanism | 641-1 | LTC Counter Readings | LTC As Found Counter | 20696 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000176 | Switchgear | WO-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000176 | Switchgear | WO-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | YD000670 | Yard | WO-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | LTCMechanism | 641-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | LTCMechanism | 641-1 | LTC Counter Readings | General Comments | | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | LTCMechanism | 641-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | LTCMechanism | 641-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1212 | BreakerVacuum | WS-1315-2 | VCB Readings | General Comments | | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1329 | Regulator | 439-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1329 | Regulator | 439-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1329 | Regulator | 439-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1329 | Regulator | 439-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1329 | Regulator | 439-1 A | Regulator Patrol Inspection | General Comments | | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000050 | Switchgear | MG-4KV Sec 1 Swgr | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Readings | Operations This Read Vac | 2 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0024 | Regulator | 494-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.7 | volts |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 800 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1212 | BreakerVacuum | WS-1315-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1212 | BreakerVacuum | WS-1315-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1212 | BreakerVacuum | WS-1315-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Readings | Totalizer Meter Reading | .2586 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Readings | Operations Counter AL | 123 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Readings | Operations Counter AF | 123 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0024 | Regulator | 494-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 41080 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0024 | Regulator | 494-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0024 | Regulator | 494-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0024 | Regulator | 494-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0024 | Regulator | 494-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | LTCMechanism | 641-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | ST000587 | Structure | MG-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | ST000587 | Structure | MG-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | ST000587 | Structure | MG-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | ST000587 | Structure | MG-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000068 | CapacitorBank | WS-Cap Bank 2 | Capacitor Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000068 | CapacitorBank | WS-Cap Bank 2 | Capacitor Patrol Inspection | Fuses Blown? Y / N | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000068 | CapacitorBank | WS-Cap Bank 2 | Capacitor Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000068 | CapacitorBank | WS-Cap Bank 2 | Capacitor Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000068 | CapacitorBank | WS-Cap Bank 2 | Capacitor Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | ST000587 | Structure | MG-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | ST000587 | Structure | MG-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | ST000587 | Structure | MG-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | ST000587 | Structure | MG-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | ST000587 | Structure | MG-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0024 | Regulator | 494-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0024 | Regulator | 494-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1212 | BreakerVacuum | WS-1315-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1212 | BreakerVacuum | WS-1315-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1212 | BreakerVacuum | WS-1315-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1212 | BreakerVacuum | WS-1315-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1212 | BreakerVacuum | WS-1315-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1212 | BreakerVacuum | WS-1315-2 | VCB Readings | Amps C Ø | 55.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1212 | BreakerVacuum | WS-1315-2 | VCB Readings | Amps B Ø | 49.0 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | LTCMechanism | 641-1 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | LTCMechanism | 641-1 | LTC Counter Readings | LTC Operations Since Last Insp | 362 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | LTCMechanism | 641-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | LTCMechanism | 641-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1212 | BreakerVacuum | WS-1315-2 | VCB Readings | Amps A Ø | 55.0 | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | YD000317 | Yard | 682-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | YD000317 | Yard | 682-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | YD000317 | Yard | 682-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | YD000317 | Yard | 682-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | YD000317 | Yard | 682-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | YD000317 | Yard | 682-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | YD000317 | Yard | 682-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | YD000317 | Yard | 682-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | YD000317 | Yard | 682-Yard | Yard Patrol Inspection | Ambient Temp | 47 | °F |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1329 | Regulator | 439-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1329 | Regulator | 439-1 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1329 | Regulator | 439-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1329 | Regulator | 439-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1329 | Regulator | 439-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1329 | Regulator | 439-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1329 | Regulator | 439-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1329 | Regulator | 439-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.5 | volts |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1329 | Regulator | 439-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 40477 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1329 | Regulator | 439-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1329 | Regulator | 439-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1329 | Regulator | 439-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1329 | Regulator | 439-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000050 | Switchgear | MG-4KV Sec 1 Swgr | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000050 | Switchgear | MG-4KV Sec 1 Swgr | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000050 | Switchgear | MG-4KV Sec 1 Swgr | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000050 | Switchgear | MG-4KV Sec 1 Swgr | Switchgear Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000050 | Switchgear | MG-4KV Sec 1 Swgr | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000276 | GroundTransformer | MG-GND TR 7 | Ground Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000276 | GroundTransformer | MG-GND TR 7 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | ST000248 | Structure | 467-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | ST000248 | Structure | 467-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | YD000242 | Yard | 467-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | YD000242 | Yard | 467-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | YD000242 | Yard | 467-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | n | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | YD000242 | Yard | 467-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | YD000242 | Yard | 467-Yard | Yard Patrol Inspection | General Comments | SPR not in use | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | YD000242 | Yard | 467-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | YD000242 | Yard | 467-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000276 | GroundTransformer | MG-GND TR 7 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000276 | GroundTransformer | MG-GND TR 7 | Ground Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000276 | GroundTransformer | MG-GND TR 7 | Ground Transformer Patrol Inspection | Pumps Operational? | n | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000276 | GroundTransformer | MG-GND TR 7 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000276 | GroundTransformer | MG-GND TR 7 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000276 | GroundTransformer | MG-GND TR 7 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000276 | GroundTransformer | MG-GND TR 7 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000276 | GroundTransformer | MG-GND TR 7 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000276 | GroundTransformer | MG-GND TR 7 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0099 | WithLTC | Retired Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0099 | WithLTC | Retired Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1183 | BreakerVacuum | WS-1319-1 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1183 | BreakerVacuum | WS-1319-1 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1183 | BreakerVacuum | WS-1319-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1183 | BreakerVacuum | WS-1319-1 | VCB Readings | Operations Counter AL | 162 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | YD000242 | Yard | 467-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | YD000242 | Yard | 467-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | YD000242 | Yard | 467-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | YD000242 | Yard | 467-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Readings | Amps C Ø | 15.0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Readings | Amps B Ø | 5.0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Readings | Amps A Ø | 5.0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Readings | 9 Month Operations | 1 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | ST000248 | Structure | 467-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | ST000248 | Structure | 467-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | ST000248 | Structure | 467-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | ST000248 | Structure | 467-Structure | Structure Patrol Inspection | General Comments | | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | ST000248 | Structure | 467-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | ST000248 | Structure | 467-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | ST000248 | Structure | 467-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | ST000248 | Structure | 467-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | YD000242 | Yard | 467-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | YD000242 | Yard | 467-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | YD000242 | Yard | 467-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1183 | BreakerVacuum | WS-1319-1 | VCB Readings | Operations Counter AF | 162 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1183 | BreakerVacuum | WS-1319-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1183 | BreakerVacuum | WS-1319-1 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1183 | BreakerVacuum | WS-1319-1 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1183 | BreakerVacuum | WS-1319-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1183 | BreakerVacuum | WS-1319-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1183 | BreakerVacuum | WS-1319-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1183 | BreakerVacuum | WS-1319-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1183 | BreakerVacuum | WS-1319-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1183 | BreakerVacuum | WS-1319-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1183 | BreakerVacuum | WS-1319-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BCH001412 | Charger | 570-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BCH001412 | Charger | 570-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BCH001412 | Charger | 570-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BCH001412 | Charger | 570-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BCH001412 | Charger | 570-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .8 | amps |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BCH001412 | Charger | 570-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BCH001412 | Charger | 570-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BCH001412 | Charger | 570-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.000 | millivolts |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000275 | GroundTransformer | MG-GND TR 6 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Readings | Fault Operations C Ø | 1 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000275 | GroundTransformer | MG-GND TR 6 | Ground Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000275 | GroundTransformer | MG-GND TR 6 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000275 | GroundTransformer | MG-GND TR 6 | Ground Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000275 | GroundTransformer | MG-GND TR 6 | Ground Transformer Patrol Inspection | Cleaned Mechanism Cabinet? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000275 | GroundTransformer | MG-GND TR 6 | Ground Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000275 | GroundTransformer | MG-GND TR 6 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000275 | GroundTransformer | MG-GND TR 6 | Ground Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000275 | GroundTransformer | MG-GND TR 6 | Ground Transformer Patrol Inspection | Fans Operational? | n | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Readings | Fault Adjusted Amps C Phase V | 1.93 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Readings | General Comments | 51-C Inst | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000275 | GroundTransformer | MG-GND TR 6 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000275 | GroundTransformer | MG-GND TR 6 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000275 | GroundTransformer | MG-GND TR 6 | Ground Transformer Patrol Inspection | Gas Accumulation Gauge | Normal | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000275 | GroundTransformer | MG-GND TR 6 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000275 | GroundTransformer | MG-GND TR 6 | Ground Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000275 | GroundTransformer | MG-GND TR 6 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000275 | GroundTransformer | MG-GND TR 6 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000275 | GroundTransformer | MG-GND TR 6 | Ground Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000275 | GroundTransformer | MG-GND TR 6 | Ground Transformer Patrol Inspection | Pumps Operational? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000275 | GroundTransformer | MG-GND TR 6 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000275 | GroundTransformer | MG-GND TR 6 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000275 | GroundTransformer | MG-GND TR 6 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Readings | Operations Counter AF | 224 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Readings | Operations Counter AL | 224 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0069 | BreakerVacuum | 006-1602 | VCB Readings | Operations This Read Vac | 1 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | ST000248 | Structure | 467-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | ST000248 | Structure | 467-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | ST000248 | Structure | 467-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | ST000248 | Structure | 467-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | FE000589 | Fence | MG-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | FE000589 | Fence | MG-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | FE000589 | Fence | MG-Fence | Fence Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | FE000589 | Fence | MG-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | FE000589 | Fence | MG-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | FE000589 | Fence | MG-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | FE000589 | Fence | MG-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | FE000589 | Fence | MG-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000275 | GroundTransformer | MG-GND TR 6 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000275 | GroundTransformer | MG-GND TR 6 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000275 | GroundTransformer | MG-GND TR 6 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | FE000589 | Fence | MG-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | FE000589 | Fence | MG-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | FE000589 | Fence | MG-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | FE000589 | Fence | MG-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .4218 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Readings | Winding Temp Max | 30 | °C |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | S0050 | NonLTC | 405-1 | NonLTC Transformer Readings | Winding Temp Present | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | FE000589 | Fence | MG-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | FE000589 | Fence | MG-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0099 | WithLTC | Retired Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | FE000589 | Fence | MG-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | FE000589 | Fence | MG-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000276 | GroundTransformer | MG-GND TR 7 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000276 | GroundTransformer | MG-GND TR 7 | Ground Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000276 | GroundTransformer | MG-GND TR 7 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000276 | GroundTransformer | MG-GND TR 7 | Ground Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000276 | GroundTransformer | MG-GND TR 7 | Ground Transformer Patrol Inspection | Cleaned Mechanism Cabinet? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000276 | GroundTransformer | MG-GND TR 7 | Ground Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000276 | GroundTransformer | MG-GND TR 7 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000276 | GroundTransformer | MG-GND TR 7 | Ground Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000276 | GroundTransformer | MG-GND TR 7 | Ground Transformer Patrol Inspection | Fans Operational? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000276 | GroundTransformer | MG-GND TR 7 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000276 | GroundTransformer | MG-GND TR 7 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000276 | GroundTransformer | MG-GND TR 7 | Ground Transformer Patrol Inspection | Gas Accumulation Gauge | Normal | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000276 | GroundTransformer | MG-GND TR 7 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1235 | BreakerVacuum | WS-SEC TIE 2-4 | VCB Readings | Amps B Ø | 73.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1235 | BreakerVacuum | WS-SEC TIE 2-4 | VCB Readings | Amps A Ø | 82.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1235 | BreakerVacuum | WS-SEC TIE 2-4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1235 | BreakerVacuum | WS-SEC TIE 2-4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Readings | Amps A Ø | 95.0 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Readings | Amps B Ø | 95.0 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Readings | Amps C Ø | 140.0 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | PF000185 | PowerFuse | JT-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | PF000185 | PowerFuse | JT-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | PF000185 | PowerFuse | JT-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | PF000186 | PowerFuse | JT-12KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | PF000186 | PowerFuse | JT-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | PF000186 | PowerFuse | JT-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BAT001448 | Battery | 686-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BAT001448 | Battery | 686-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BAT001448 | Battery | 686-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BAT001448 | Battery | 686-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BAT001448 | Battery | 686-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BAT001448 | Battery | 686-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BAT001448 | Battery | 686-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1235 | BreakerVacuum | WS-SEC TIE 2-4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1235 | BreakerVacuum | WS-SEC TIE 2-4 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1235 | BreakerVacuum | WS-SEC TIE 2-4 | VCB Readings | 9 Month Operations | 2 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1162 | BreakerVacuum | WO-12KV TR 1 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1162 | BreakerVacuum | WO-12KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | YD000141 | Yard | 771-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1162 | BreakerVacuum | WO-12KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1162 | BreakerVacuum | WO-12KV TR 1 | VCB Readings | Operations Counter AL | 230 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0099 | WithLTC | Retired Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0099 | WithLTC | Retired Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0099 | WithLTC | Retired Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0099 | WithLTC | Retired Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1162 | BreakerVacuum | WO-12KV TR 1 | VCB Readings | Operations Counter AF | 230 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1162 | BreakerVacuum | WO-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1162 | BreakerVacuum | WO-12KV TR 1 | VCB Readings | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1162 | BreakerVacuum | WO-12KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1162 | BreakerVacuum | WO-12KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1162 | BreakerVacuum | WO-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1162 | BreakerVacuum | WO-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1162 | BreakerVacuum | WO-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1162 | BreakerVacuum | WO-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1162 | BreakerVacuum | WO-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1162 | BreakerVacuum | WO-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1162 | BreakerVacuum | WO-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1162 | BreakerVacuum | WO-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1162 | BreakerVacuum | WO-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1162 | BreakerVacuum | WO-12KV TR 1 | VCB Readings | Amps C Ø | 570.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1162 | BreakerVacuum | WO-12KV TR 1 | VCB Readings | Amps B Ø | 620.0 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1162 | BreakerVacuum | WO-12KV TR 1 | VCB Readings | Amps A Ø | 620.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1162 | BreakerVacuum | WO-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1162 | BreakerVacuum | WO-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1162 | BreakerVacuum | WO-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1162 | BreakerVacuum | WO-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1162 | BreakerVacuum | WO-12KV TR 1 | VCB Readings | 9 Month Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0632 | BreakerAirMagnetic | MG-452 | AMCB Readings | Unknown Operations | 3 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0632 | BreakerAirMagnetic | MG-452 | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0632 | BreakerAirMagnetic | MG-452 | AMCB Readings | Operations This Read AM | 3 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0632 | BreakerAirMagnetic | MG-452 | AMCB Readings | Operations Counter AL | 745 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1183 | BreakerVacuum | WS-1319-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1183 | BreakerVacuum | WS-1319-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1183 | BreakerVacuum | WS-1319-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1183 | BreakerVacuum | WS-1319-1 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1183 | BreakerVacuum | WS-1319-1 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1183 | BreakerVacuum | WS-1319-1 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1183 | BreakerVacuum | WS-1319-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1183 | BreakerVacuum | WS-1319-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1183 | BreakerVacuum | WS-1319-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1183 | BreakerVacuum | WS-1319-1 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1183 | BreakerVacuum | WS-1319-1 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Readings | 9 Month Operations | 7 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1235 | BreakerVacuum | WS-SEC TIE 2-4 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1235 | BreakerVacuum | WS-SEC TIE 2-4 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1235 | BreakerVacuum | WS-SEC TIE 2-4 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1235 | BreakerVacuum | WS-SEC TIE 2-4 | VCB Readings | Operations Counter AL | 109 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1235 | BreakerVacuum | WS-SEC TIE 2-4 | VCB Readings | Operations Counter AF | 109 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1235 | BreakerVacuum | WS-SEC TIE 2-4 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1235 | BreakerVacuum | WS-SEC TIE 2-4 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1235 | BreakerVacuum | WS-SEC TIE 2-4 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1235 | BreakerVacuum | WS-SEC TIE 2-4 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | YD000242 | Yard | 467-Yard | Yard Patrol Inspection | Ambient Temp | 58 | °F |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | FE000243 | Fence | 467-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | FE000243 | Fence | 467-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | FE000243 | Fence | 467-Fence | Fence Patrol Inspection | General Comments | | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | FE000243 | Fence | 467-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | FE000243 | Fence | 467-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | FE000243 | Fence | 467-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | FE000243 | Fence | 467-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | FE000243 | Fence | 467-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | FE000243 | Fence | 467-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | FE000243 | Fence | 467-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | FE000243 | Fence | 467-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | FE000243 | Fence | 467-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | FE000243 | Fence | 467-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | FE000243 | Fence | 467-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | FE000243 | Fence | 467-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | FE000243 | Fence | 467-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1235 | BreakerVacuum | WS-SEC TIE 2-4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1235 | BreakerVacuum | WS-SEC TIE 2-4 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | ST000248 | Structure | 467-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | ST000248 | Structure | 467-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | ST000248 | Structure | 467-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | ST000248 | Structure | 467-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | ST000248 | Structure | 467-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | ST000248 | Structure | 467-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | ST000248 | Structure | 467-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | ST000248 | Structure | 467-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Readings | Winding Temp Present | 22 | °C |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Readings | Winding Temp Max | 32 | °C |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .4854 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 4659.84 | kw |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1235 | BreakerVacuum | WS-SEC TIE 2-4 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1235 | BreakerVacuum | WS-SEC TIE 2-4 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1235 | BreakerVacuum | WS-SEC TIE 2-4 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1235 | BreakerVacuum | WS-SEC TIE 2-4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1235 | BreakerVacuum | WS-SEC TIE 2-4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1235 | BreakerVacuum | WS-SEC TIE 2-4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1235 | BreakerVacuum | WS-SEC TIE 2-4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1235 | BreakerVacuum | WS-SEC TIE 2-4 | VCB Readings | Amps C Ø | 72.0 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Readings | 9 Month Operations | 2 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0130 | BreakerVacuum | 771-1643 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | KT0044 | NonLTC | 571-1 | NonLTC Transformer Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1207 | BreakerVacuum | WS-1303-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1207 | BreakerVacuum | WS-1303-2 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1207 | BreakerVacuum | WS-1303-2 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1207 | BreakerVacuum | WS-1303-2 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1207 | BreakerVacuum | WS-1303-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000116 | LTCMechanism | MG-TRANS 6 | LTC Counter Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000116 | LTCMechanism | MG-TRANS 6 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000116 | LTCMechanism | MG-TRANS 6 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1157 | BreakerVacuum | WO-1177 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1207 | BreakerVacuum | WS-1303-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1207 | BreakerVacuum | WS-1303-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1207 | BreakerVacuum | WS-1303-2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1207 | BreakerVacuum | WS-1303-2 | VCB Readings | 9 Month Operations | 1 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000115 | LTCMechanism | MG-TRANS 7 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000115 | LTCMechanism | MG-TRANS 7 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000115 | LTCMechanism | MG-TRANS 7 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000115 | LTCMechanism | MG-TRANS 7 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000115 | LTCMechanism | MG-TRANS 7 | LTC Counter Readings | LTC Operations Since Last Insp | 751 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000115 | LTCMechanism | MG-TRANS 7 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000115 | LTCMechanism | MG-TRANS 7 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 20 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000115 | LTCMechanism | MG-TRANS 7 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000115 | LTCMechanism | MG-TRANS 7 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000115 | LTCMechanism | MG-TRANS 7 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000115 | LTCMechanism | MG-TRANS 7 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000115 | LTCMechanism | MG-TRANS 7 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000115 | LTCMechanism | MG-TRANS 7 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000115 | LTCMechanism | MG-TRANS 7 | LTC Counter Readings | LTC As Left Counter | 6937 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000115 | LTCMechanism | MG-TRANS 7 | LTC Counter Readings | LTC As Found Counter | 6937 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0520 | BreakerVacuum | JT-1121 | VCB Readings | Operations Counter AF | 379 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0520 | BreakerVacuum | JT-1121 | VCB Readings | Operations Counter AL | 379 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0520 | BreakerVacuum | JT-1121 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0520 | BreakerVacuum | JT-1121 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0520 | BreakerVacuum | JT-1121 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000115 | LTCMechanism | MG-TRANS 7 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000115 | LTCMechanism | MG-TRANS 7 | LTC Counter Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000115 | LTCMechanism | MG-TRANS 7 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000115 | LTCMechanism | MG-TRANS 7 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCC000896 | LTCControl | MG-TRANS 7 | LTC Control Insp | VRR Time Delay | 0 | Seconds |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCC000896 | LTCControl | MG-TRANS 7 | LTC Control Insp | VRR Base Voltage AL | 0.0 | VAC |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCC000896 | LTCControl | MG-TRANS 7 | LTC Control Insp | VRR Base Voltage AF | 0.0 | VAC |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCC000896 | LTCControl | MG-TRANS 7 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCC000896 | LTCControl | MG-TRANS 7 | LTC Control Insp | LTC Output Voltage Level | 0.0 | VAC |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCC000896 | LTCControl | MG-TRANS 7 | LTC Control Insp | LTC Operation Checked? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCC000896 | LTCControl | MG-TRANS 7 | LTC Control Insp | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCC000896 | LTCControl | MG-TRANS 7 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCC000896 | LTCControl | MG-TRANS 7 | LTC Control Insp | All Connections OK? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1186 | Regulator | 596-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1186 | Regulator | 596-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1186 | Regulator | 596-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1186 | Regulator | 596-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1186 | Regulator | 596-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1186 | Regulator | 596-1 A | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1186 | Regulator | 596-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1186 | Regulator | 596-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1186 | Regulator | 596-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1186 | Regulator | 596-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1186 | Regulator | 596-1 A | Regulator Patrol Inspection | General Comments | | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1186 | Regulator | 596-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1186 | Regulator | 596-1 A | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | YD000250 | Yard | 596-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | YD000250 | Yard | 596-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | YD000250 | Yard | 596-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | YD000250 | Yard | 596-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | YD000250 | Yard | 596-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | YD000250 | Yard | 596-Yard | Yard Patrol Inspection | General Comments | There is a large washout in front of entry gate. | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1459 | Regulator | 006-5 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | YD000250 | Yard | 596-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | YD000250 | Yard | 596-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | YD000250 | Yard | 596-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Readings | 9 Month Operations | 1 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Readings | Operations Counter AL | 147 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Readings | Operations This Read Vac | 1 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0520 | BreakerVacuum | JT-1121 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0520 | BreakerVacuum | JT-1121 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0520 | BreakerVacuum | JT-1121 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1459 | Regulator | 006-5 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1459 | Regulator | 006-5 C | Regulator Patrol Inspection | Reg Output Voltage Level | 121.9 | volts |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0520 | BreakerVacuum | JT-1121 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0520 | BreakerVacuum | JT-1121 | VCB Readings | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0520 | BreakerVacuum | JT-1121 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1459 | Regulator | 006-5 C | Regulator Patrol Inspection | Regulator As Left Counter | 30154 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1459 | Regulator | 006-5 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1459 | Regulator | 006-5 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1459 | Regulator | 006-5 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1189 | BreakerVacuum | WS-CAP BK 3 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1157 | BreakerVacuum | WO-1177 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1157 | BreakerVacuum | WO-1177 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1157 | BreakerVacuum | WO-1177 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1157 | BreakerVacuum | WO-1177 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1157 | BreakerVacuum | WO-1177 | VCB Readings | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1157 | BreakerVacuum | WO-1177 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1157 | BreakerVacuum | WO-1177 | VCB Readings | Operations Counter AF | 413 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1157 | BreakerVacuum | WO-1177 | VCB Readings | Operations Counter AL | 413 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1157 | BreakerVacuum | WO-1177 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1157 | BreakerVacuum | WO-1177 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000116 | LTCMechanism | MG-TRANS 6 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000116 | LTCMechanism | MG-TRANS 6 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000116 | LTCMechanism | MG-TRANS 6 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000116 | LTCMechanism | MG-TRANS 6 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000116 | LTCMechanism | MG-TRANS 6 | LTC Counter Readings | LTC Operations Since Last Insp | 523 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000116 | LTCMechanism | MG-TRANS 6 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000116 | LTCMechanism | MG-TRANS 6 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000116 | LTCMechanism | MG-TRANS 6 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000116 | LTCMechanism | MG-TRANS 6 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 3.0 | psi |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000116 | LTCMechanism | MG-TRANS 6 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000116 | LTCMechanism | MG-TRANS 6 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000116 | LTCMechanism | MG-TRANS 6 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000116 | LTCMechanism | MG-TRANS 6 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000116 | LTCMechanism | MG-TRANS 6 | LTC Counter Readings | LTC As Left Counter | 6139 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000116 | LTCMechanism | MG-TRANS 6 | LTC Counter Readings | LTC As Found Counter | 6139 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000116 | LTCMechanism | MG-TRANS 6 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1207 | BreakerVacuum | WS-1303-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1207 | BreakerVacuum | WS-1303-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1207 | BreakerVacuum | WS-1303-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1207 | BreakerVacuum | WS-1303-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | H1 Winding Temp Present | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | H1 Winding Temp Max | 19 | °C |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0106 | Regulator | 481-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0106 | Regulator | 481-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0106 | Regulator | 481-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0106 | Regulator | 481-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0106 | Regulator | 481-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 32226 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0106 | Regulator | 481-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.8 | volts |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0106 | Regulator | 481-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0106 | Regulator | 481-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0106 | Regulator | 481-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0106 | Regulator | 481-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0106 | Regulator | 481-1 C | Regulator Patrol Inspection | Min Tap Position | 15L | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0106 | Regulator | 481-1 C | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0106 | Regulator | 481-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | ST000160 | Structure | 815-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | ST000160 | Structure | 815-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | ST000160 | Structure | 815-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | ST000160 | Structure | 815-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0633 | BreakerAirMagnetic | MG-454 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0633 | BreakerAirMagnetic | MG-454 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0633 | BreakerAirMagnetic | MG-454 | AMCB Readings | Fault Adjusted Amps C Phase AM | 19.09 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0633 | BreakerAirMagnetic | MG-454 | AMCB Readings | Fault Adjusted Amps B Phase AM | 19.09 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0633 | BreakerAirMagnetic | MG-454 | AMCB Readings | Fault Adjusted Amps A Phase AM | 19.09 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0633 | BreakerAirMagnetic | MG-454 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0633 | BreakerAirMagnetic | MG-454 | AMCB Readings | Amps C Ø | 2.0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | ST000257 | Structure | 596-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | ST000257 | Structure | 596-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | ST000257 | Structure | 596-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | ST000257 | Structure | 596-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | ST000257 | Structure | 596-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | ST000257 | Structure | 596-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | ST000257 | Structure | 596-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | ST000257 | Structure | 596-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | ST000257 | Structure | 596-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | ST000257 | Structure | 596-Structure | Structure Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0633 | BreakerAirMagnetic | MG-454 | AMCB Readings | Amps B Ø | 1.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0633 | BreakerAirMagnetic | MG-454 | AMCB Readings | Amps A Ø | 2.0 | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | ST000160 | Structure | 815-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1186 | Regulator | 596-1 A | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1186 | Regulator | 596-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1186 | Regulator | 596-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1186 | Regulator | 596-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1186 | Regulator | 596-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1186 | Regulator | 596-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1186 | Regulator | 596-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 110766 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1186 | Regulator | 596-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1186 | Regulator | 596-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1186 | Regulator | 596-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1186 | Regulator | 596-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | Y3 Winding Temp Present | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | Y3 Winding Temp Max | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | Y2 Winding Temp Present | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | Y2 Winding Temp Max | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | Y1 Winding Temp Present | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | Y1 Winding Temp Max | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | X3 Winding Temp Present | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | X3 Winding Temp Max | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | X2 Winding Temp Present | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | X2 Winding Temp Max | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | X1 Winding Temp Present | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | X1 Winding Temp Max | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | Winding Temp Present | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | Winding Temp Max | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | TV Winding Temp Present | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | TV Winding Temp Max | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | Totalizer Meter Multiplier | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | Top Oil Temperature Present | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | Top Oil Temperature Max | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | Percent Thermal Load C Ø Max | 0 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | Percent Thermal Load B Ø Max | 0 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | Percent Thermal Load A Ø Max | 0 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | Oil Temp Present | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | Oil Temp Max | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1000 | psi |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | LV Winding Temp Present | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | LV Winding Temp Max | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | LTC Totalizer Reading | 0.00 | kw |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | HV Winding Temp Present | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | HV Winding Temp Max | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | H3 Winding Temp Present | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | H3 Winding Temp Max | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | H2 Winding Temp Present | 19 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000268 | WithLTC | MG-TRANS 6 | LTC Transformer Readings | H2 Winding Temp Max | 19 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1207 | BreakerVacuum | WS-1303-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1458 | Regulator | 006-5 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1207 | BreakerVacuum | WS-1303-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1207 | BreakerVacuum | WS-1303-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1207 | BreakerVacuum | WS-1303-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1207 | BreakerVacuum | WS-1303-2 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1207 | BreakerVacuum | WS-1303-2 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1207 | BreakerVacuum | WS-1303-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1207 | BreakerVacuum | WS-1303-2 | VCB Readings | Operations Counter AF | 182 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1458 | Regulator | 006-5 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1189 | BreakerVacuum | WS-CAP BK 3 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1189 | BreakerVacuum | WS-CAP BK 3 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1189 | BreakerVacuum | WS-CAP BK 3 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1189 | BreakerVacuum | WS-CAP BK 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1189 | BreakerVacuum | WS-CAP BK 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1189 | BreakerVacuum | WS-CAP BK 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1189 | BreakerVacuum | WS-CAP BK 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1189 | BreakerVacuum | WS-CAP BK 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1189 | BreakerVacuum | WS-CAP BK 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1189 | BreakerVacuum | WS-CAP BK 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1189 | BreakerVacuum | WS-CAP BK 3 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1458 | Regulator | 006-5 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1458 | Regulator | 006-5 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1458 | Regulator | 006-5 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1458 | Regulator | 006-5 B | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1458 | Regulator | 006-5 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCC000897 | LTCControl | MG-TRANS 6 | LTC Control Insp | VRR Base Voltage AL | 0.0 | VAC |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCC000897 | LTCControl | MG-TRANS 6 | LTC Control Insp | VRR Time Delay | 0 | Seconds |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0633 | BreakerAirMagnetic | MG-454 | AMCB Readings | Operations Counter AL | 380 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0633 | BreakerAirMagnetic | MG-454 | AMCB Readings | Operations Counter AF | 380 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0633 | BreakerAirMagnetic | MG-454 | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0633 | BreakerAirMagnetic | MG-454 | AMCB Readings | General Comments | | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1458 | Regulator | 006-5 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1458 | Regulator | 006-5 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0633 | BreakerAirMagnetic | MG-454 | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0633 | BreakerAirMagnetic | MG-454 | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0633 | BreakerAirMagnetic | MG-454 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Readings | Operations This Read Vac | 1 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Readings | Operations Counter AL | 277 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0633 | BreakerAirMagnetic | MG-454 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0633 | BreakerAirMagnetic | MG-454 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1207 | BreakerVacuum | WS-1303-2 | VCB Readings | Operations Counter AL | 182 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1207 | BreakerVacuum | WS-1303-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1207 | BreakerVacuum | WS-1303-2 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1207 | BreakerVacuum | WS-1303-2 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000113 | Switchgear | MK-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000113 | Switchgear | MK-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000113 | Switchgear | MK-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000113 | Switchgear | MK-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000113 | Switchgear | MK-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000113 | Switchgear | MK-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000113 | Switchgear | MK-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000113 | Switchgear | MK-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000113 | Switchgear | MK-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000113 | Switchgear | MK-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000113 | Switchgear | MK-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000113 | Switchgear | MK-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000113 | Switchgear | MK-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1157 | BreakerVacuum | WO-1177 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1157 | BreakerVacuum | WO-1177 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1157 | BreakerVacuum | WO-1177 | VCB Readings | Amps A Ø | 200.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1157 | BreakerVacuum | WO-1177 | VCB Readings | Amps B Ø | 180.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1157 | BreakerVacuum | WO-1177 | VCB Readings | Amps C Ø | 180.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1157 | BreakerVacuum | WO-1177 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1157 | BreakerVacuum | WO-1177 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1157 | BreakerVacuum | WO-1177 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1157 | BreakerVacuum | WO-1177 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1157 | BreakerVacuum | WO-1177 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1157 | BreakerVacuum | WO-1177 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1157 | BreakerVacuum | WO-1177 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1189 | BreakerVacuum | WS-CAP BK 3 | VCB Readings | 9 Month Operations | 2 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1189 | BreakerVacuum | WS-CAP BK 3 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1189 | BreakerVacuum | WS-CAP BK 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1189 | BreakerVacuum | WS-CAP BK 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1189 | BreakerVacuum | WS-CAP BK 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Readings | Amps C Ø | 140.0 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Readings | Amps B Ø | 90.0 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Readings | Amps A Ø | 125.0 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Readings | 9 Month Operations | 1 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1157 | BreakerVacuum | WO-1177 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1157 | BreakerVacuum | WO-1177 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1157 | BreakerVacuum | WO-1177 | VCB Readings | 9 Month Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0633 | BreakerAirMagnetic | MG-454 | AMCB Readings | Unknown Operations | 2 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0633 | BreakerAirMagnetic | MG-454 | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0633 | BreakerAirMagnetic | MG-454 | AMCB Readings | Operations This Read AM | 2 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCC000897 | LTCControl | MG-TRANS 6 | LTC Control Insp | All Connections OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCC000897 | LTCControl | MG-TRANS 6 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCC000897 | LTCControl | MG-TRANS 6 | LTC Control Insp | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCC000897 | LTCControl | MG-TRANS 6 | LTC Control Insp | LTC Operation Checked? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCC000897 | LTCControl | MG-TRANS 6 | LTC Control Insp | LTC Output Voltage Level | 0.0 | VAC |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCC000897 | LTCControl | MG-TRANS 6 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCC000897 | LTCControl | MG-TRANS 6 | LTC Control Insp | VRR Base Voltage AF | 0.0 | VAC |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1207 | BreakerVacuum | WS-1303-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0520 | BreakerVacuum | JT-1121 | VCB Readings | 9 Month Operations VCB New | 11 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0520 | BreakerVacuum | JT-1121 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1189 | BreakerVacuum | WS-CAP BK 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1189 | BreakerVacuum | WS-CAP BK 3 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1189 | BreakerVacuum | WS-CAP BK 3 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1459 | Regulator | 006-5 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1189 | BreakerVacuum | WS-CAP BK 3 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1189 | BreakerVacuum | WS-CAP BK 3 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1189 | BreakerVacuum | WS-CAP BK 3 | VCB Readings | Operations Counter AF | 109 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1189 | BreakerVacuum | WS-CAP BK 3 | VCB Readings | Operations Counter AL | 109 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1189 | BreakerVacuum | WS-CAP BK 3 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1189 | BreakerVacuum | WS-CAP BK 3 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1459 | Regulator | 006-5 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0520 | BreakerVacuum | JT-1121 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0520 | BreakerVacuum | JT-1121 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0520 | BreakerVacuum | JT-1121 | VCB Readings | Amps A Ø | 76.0 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Readings | Maintenance Operations | 1 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0520 | BreakerVacuum | JT-1121 | VCB Readings | Amps B Ø | 125.0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1459 | Regulator | 006-5 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1459 | Regulator | 006-5 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1459 | Regulator | 006-5 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0520 | BreakerVacuum | JT-1121 | VCB Readings | Amps C Ø | 146.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0520 | BreakerVacuum | JT-1121 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0520 | BreakerVacuum | JT-1121 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0520 | BreakerVacuum | JT-1121 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Readings | Operations Counter AF | 147 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0520 | BreakerVacuum | JT-1121 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0520 | BreakerVacuum | JT-1121 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0520 | BreakerVacuum | JT-1121 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Readings | Amps C Ø | 52.0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Readings | Amps B Ø | 53.0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1459 | Regulator | 006-5 C | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1459 | Regulator | 006-5 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1459 | Regulator | 006-5 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1459 | Regulator | 006-5 C | Regulator Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1459 | Regulator | 006-5 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1459 | Regulator | 006-5 C | Regulator Patrol Inspection | General Comments | | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Readings | Amps A Ø | 87.0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1459 | Regulator | 006-5 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1459 | Regulator | 006-5 C | Regulator Patrol Inspection | Max Tap Position | 4L | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1459 | Regulator | 006-5 C | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1459 | Regulator | 006-5 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1459 | Regulator | 006-5 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0520 | BreakerVacuum | JT-1121 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | YD000250 | Yard | 596-Yard | Yard Patrol Inspection | Ambient Temp | 46 | °F |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | YD000250 | Yard | 596-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | YD000250 | Yard | 596-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | YD000250 | Yard | 596-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | YD000250 | Yard | 596-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Readings | Operations Counter AF | 277 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Readings | Maintenance Operations | 1 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000113 | Switchgear | MK-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000113 | Switchgear | MK-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Readings | General Comments | | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000113 | Switchgear | MK-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000113 | Switchgear | MK-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000113 | Switchgear | MK-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000113 | Switchgear | MK-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0520 | BreakerVacuum | JT-1121 | VCB Readings | 9 Month Operations | 11 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1458 | Regulator | 006-5 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1458 | Regulator | 006-5 B | Regulator Patrol Inspection | General Comments | | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1458 | Regulator | 006-5 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1458 | Regulator | 006-5 B | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1458 | Regulator | 006-5 B | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1458 | Regulator | 006-5 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1458 | Regulator | 006-5 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1458 | Regulator | 006-5 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1458 | Regulator | 006-5 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1458 | Regulator | 006-5 B | Regulator Patrol Inspection | Reg Output Voltage Level | 121.9 | volts |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | FE000249 | Fence | 596-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0161 | BreakerVacuum | 571-1648 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Readings | General Comments | | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1458 | Regulator | 006-5 B | Regulator Patrol Inspection | Regulator As Left Counter | 35854 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1458 | Regulator | 006-5 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1458 | Regulator | 006-5 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1458 | Regulator | 006-5 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | FE000249 | Fence | 596-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | FE000249 | Fence | 596-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | K0131 | BreakerVacuum | 771-1642 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | FE000249 | Fence | 596-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | FE000249 | Fence | 596-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | FE000249 | Fence | 596-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | FE000249 | Fence | 596-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | FE000249 | Fence | 596-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | FE000249 | Fence | 596-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | FE000249 | Fence | 596-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | FE000249 | Fence | 596-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | FE000249 | Fence | 596-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | FE000249 | Fence | 596-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | FE000249 | Fence | 596-Fence | Fence Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | FE000249 | Fence | 596-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | FE000249 | Fence | 596-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1245 | BreakerVacuum | WS-1336-4 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1245 | BreakerVacuum | WS-1336-4 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1245 | BreakerVacuum | WS-1336-4 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1245 | BreakerVacuum | WS-1336-4 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1245 | BreakerVacuum | WS-1336-4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1245 | BreakerVacuum | WS-1336-4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1245 | BreakerVacuum | WS-1336-4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1245 | BreakerVacuum | WS-1336-4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1331 | BreakerVacuum | JT-1120 | VCB Readings | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1331 | BreakerVacuum | JT-1120 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1331 | BreakerVacuum | JT-1120 | VCB Readings | Operations Counter AF | 197 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1245 | BreakerVacuum | WS-1336-4 | VCB Readings | Amps C Ø | 78.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1245 | BreakerVacuum | WS-1336-4 | VCB Readings | Amps B Ø | 79.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1245 | BreakerVacuum | WS-1336-4 | VCB Readings | Amps A Ø | 81.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1245 | BreakerVacuum | WS-1336-4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1331 | BreakerVacuum | JT-1120 | VCB Readings | Operations Counter AL | 197 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1331 | BreakerVacuum | JT-1120 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1331 | BreakerVacuum | JT-1120 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1331 | BreakerVacuum | JT-1120 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1245 | BreakerVacuum | WS-1336-4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1245 | BreakerVacuum | WS-1336-4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1245 | BreakerVacuum | WS-1336-4 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1245 | BreakerVacuum | WS-1336-4 | VCB Readings | 9 Month Operations | 6 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1233 | BreakerVacuum | WS-14KV TR 3 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1233 | BreakerVacuum | WS-14KV TR 3 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1233 | BreakerVacuum | WS-14KV TR 3 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1233 | BreakerVacuum | WS-14KV TR 3 | VCB Readings | Operations Counter AL | 194 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BCH001323 | Charger | 494-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.000 | millivolts |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BCH001323 | Charger | 494-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BCH001323 | Charger | 494-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BCH001323 | Charger | 494-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .9 | amps |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BCH001323 | Charger | 494-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000169 | Switchgear | MG-14KV Sec B Swgr | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000169 | Switchgear | MG-14KV Sec B Swgr | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000169 | Switchgear | MG-14KV Sec B Swgr | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000169 | Switchgear | MG-14KV Sec B Swgr | Switchgear Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000169 | Switchgear | MG-14KV Sec B Swgr | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000169 | Switchgear | MG-14KV Sec B Swgr | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BCH001323 | Charger | 494-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0024 | Regulator | 494-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0024 | Regulator | 494-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BCH001323 | Charger | 494-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BCH001323 | Charger | 494-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1329 | Regulator | 439-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1329 | Regulator | 439-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1329 | Regulator | 439-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1329 | Regulator | 439-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1329 | Regulator | 439-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0636 | BreakerAirMagnetic | MG-4KV TFR | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0636 | BreakerAirMagnetic | MG-4KV TFR | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1331 | BreakerVacuum | JT-1120 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1331 | BreakerVacuum | JT-1120 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1331 | BreakerVacuum | JT-1120 | VCB Readings | Amps A Ø | 32.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0636 | BreakerAirMagnetic | MG-4KV TFR | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0636 | BreakerAirMagnetic | MG-4KV TFR | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0636 | BreakerAirMagnetic | MG-4KV TFR | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0636 | BreakerAirMagnetic | MG-4KV TFR | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0636 | BreakerAirMagnetic | MG-4KV TFR | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0636 | BreakerAirMagnetic | MG-4KV TFR | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0636 | BreakerAirMagnetic | MG-4KV TFR | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0636 | BreakerAirMagnetic | MG-4KV TFR | AMCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0636 | BreakerAirMagnetic | MG-4KV TFR | AMCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0636 | BreakerAirMagnetic | MG-4KV TFR | AMCB Readings | Operations Counter AF | 426 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | CH000205 | ControlHouse | MK-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | CH000205 | ControlHouse | MK-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | CH000205 | ControlHouse | MK-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | CH000205 | ControlHouse | MK-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | CH000205 | ControlHouse | MK-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | CH000205 | ControlHouse | MK-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | CH000205 | ControlHouse | MK-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | CH000205 | ControlHouse | MK-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | CH000205 | ControlHouse | MK-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | CH000205 | ControlHouse | MK-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BCH001369 | Charger | 686-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BCH001369 | Charger | 686-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BCH001369 | Charger | 686-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BCH001369 | Charger | 686-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BCH001369 | Charger | 686-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.5 | amps |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BCH001369 | Charger | 686-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BCH001369 | Charger | 686-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BCH001369 | Charger | 686-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1245 | BreakerVacuum | WS-1336-4 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1245 | BreakerVacuum | WS-1336-4 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1245 | BreakerVacuum | WS-1336-4 | VCB Readings | Operations Counter AL | 100 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1245 | BreakerVacuum | WS-1336-4 | VCB Readings | Operations Counter AF | 100 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1245 | BreakerVacuum | WS-1336-4 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0636 | BreakerAirMagnetic | MG-4KV TFR | AMCB Readings | Operations Counter AL | 426 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0636 | BreakerAirMagnetic | MG-4KV TFR | AMCB Readings | Operations This Read AM | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1245 | BreakerVacuum | WS-1336-4 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1245 | BreakerVacuum | WS-1336-4 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1245 | BreakerVacuum | WS-1336-4 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1331 | BreakerVacuum | JT-1120 | VCB Readings | Amps B Ø | 50.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0636 | BreakerAirMagnetic | MG-4KV TFR | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0636 | BreakerAirMagnetic | MG-4KV TFR | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1331 | BreakerVacuum | JT-1120 | VCB Readings | Amps C Ø | 76.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1331 | BreakerVacuum | JT-1120 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1331 | BreakerVacuum | JT-1120 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1331 | BreakerVacuum | JT-1120 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1331 | BreakerVacuum | JT-1120 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1331 | BreakerVacuum | JT-1120 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1331 | BreakerVacuum | JT-1120 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1331 | BreakerVacuum | JT-1120 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1331 | BreakerVacuum | JT-1120 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1331 | BreakerVacuum | JT-1120 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1331 | BreakerVacuum | JT-1120 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1331 | BreakerVacuum | JT-1120 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1245 | BreakerVacuum | WS-1336-4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1233 | BreakerVacuum | WS-14KV TR 3 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1233 | BreakerVacuum | WS-14KV TR 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1233 | BreakerVacuum | WS-14KV TR 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1233 | BreakerVacuum | WS-14KV TR 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1233 | BreakerVacuum | WS-14KV TR 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1233 | BreakerVacuum | WS-14KV TR 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1233 | BreakerVacuum | WS-14KV TR 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1233 | BreakerVacuum | WS-14KV TR 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Readings | Amps C Ø | 20.0 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Readings | Amps B Ø | 1.0 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0024 | Regulator | 494-1 B | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0024 | Regulator | 494-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1233 | BreakerVacuum | WS-14KV TR 3 | VCB Readings | Amps C Ø | 509.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1233 | BreakerVacuum | WS-14KV TR 3 | VCB Readings | Amps B Ø | 512.0 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0024 | Regulator | 494-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0024 | Regulator | 494-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | YD000670 | Yard | WO-Yard | Yard Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1233 | BreakerVacuum | WS-14KV TR 3 | VCB Readings | Amps A Ø | 516.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1233 | BreakerVacuum | WS-14KV TR 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1233 | BreakerVacuum | WS-14KV TR 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0024 | Regulator | 494-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0024 | Regulator | 494-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0024 | Regulator | 494-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0024 | Regulator | 494-1 B | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1233 | BreakerVacuum | WS-14KV TR 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1233 | BreakerVacuum | WS-14KV TR 3 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1233 | BreakerVacuum | WS-14KV TR 3 | VCB Readings | 9 Month Operations | 8 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | YD000670 | Yard | WO-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | YD000670 | Yard | WO-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | YD000670 | Yard | WO-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | YD000670 | Yard | WO-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | YD000670 | Yard | WO-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | YD000670 | Yard | WO-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | YD000670 | Yard | WO-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | YD000670 | Yard | WO-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | YD000670 | Yard | WO-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000176 | Switchgear | WO-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000176 | Switchgear | WO-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000176 | Switchgear | WO-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000176 | Switchgear | WO-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000176 | Switchgear | WO-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000176 | Switchgear | WO-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Readings | Operations This Read Vac | 1 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Readings | Operations Counter AL | 194 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Readings | General Comments | | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Readings | LTC Totalizer Reading | 6027.84 | kw |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Readings | Totalizer Meter Reading | 1.2558 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | WithLTC | 686-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0024 | Regulator | 494-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0024 | Regulator | 494-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0024 | Regulator | 494-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Readings | Operations Counter AF | 194 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Readings | Maintenance Operations | 1 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Patrol Inspection | General Comments | ok | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000176 | Switchgear | WO-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | YD000670 | Yard | WO-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | YD000670 | Yard | WO-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | YD000670 | Yard | WO-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | YD000670 | Yard | WO-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | YD000670 | Yard | WO-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | YD000670 | Yard | WO-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | YD000670 | Yard | WO-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | YD000670 | Yard | WO-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1233 | BreakerVacuum | WS-14KV TR 3 | VCB Readings | Operations Counter AF | 194 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1233 | BreakerVacuum | WS-14KV TR 3 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1233 | BreakerVacuum | WS-14KV TR 3 | VCB Readings | General Comments | | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | W0245 | NonLTC | 212-5 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Readings | General Comments | 1 trip check | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001175 | BreakerVacuum | 212-0698 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1233 | BreakerVacuum | WS-14KV TR 3 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1233 | BreakerVacuum | WS-14KV TR 3 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1233 | BreakerVacuum | WS-14KV TR 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | ST000020 | Structure | 494-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | ST000020 | Structure | 494-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | ST000020 | Structure | 494-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | ST000020 | Structure | 494-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | ST000020 | Structure | 494-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | ST000020 | Structure | 494-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | ST000020 | Structure | 494-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | ST000020 | Structure | 494-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | ST000020 | Structure | 494-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | ST000257 | Structure | 596-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R0994 | Regulator | 212-5 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R0994 | Regulator | 212-5 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R0994 | Regulator | 212-5 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R0994 | Regulator | 212-5 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R0994 | Regulator | 212-5 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R0994 | Regulator | 212-5 B | Regulator Patrol Inspection | General Comments | ok | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R0994 | Regulator | 212-5 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R0994 | Regulator | 212-5 B | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R0994 | Regulator | 212-5 B | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R0994 | Regulator | 212-5 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R0994 | Regulator | 212-5 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R0994 | Regulator | 212-5 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | ST000020 | Structure | 494-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | ST000020 | Structure | 494-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | ST000020 | Structure | 494-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Readings | Winding Temp Present | 21 | °C |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Readings | Winding Temp Max | 30 | °C |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .3894 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 3600 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | ST000257 | Structure | 596-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | CH000205 | ControlHouse | MK-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | CH000205 | ControlHouse | MK-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | CH000205 | ControlHouse | MK-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BAT001392 | Battery | 494-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BAT001392 | Battery | 494-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BAT001392 | Battery | 494-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BAT001392 | Battery | 494-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R0994 | Regulator | 212-5 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.7 | volts |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R0994 | Regulator | 212-5 B | Regulator Patrol Inspection | Regulator As Left Counter | 244061 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R0994 | Regulator | 212-5 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R0994 | Regulator | 212-5 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R0994 | Regulator | 212-5 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | CH000205 | ControlHouse | MK-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BAT001392 | Battery | 494-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BAT001392 | Battery | 494-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BAT001392 | Battery | 494-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BAT001392 | Battery | 494-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BAT001392 | Battery | 494-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Exp/Missing Not Repl | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BAT001392 | Battery | 494-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BAT001392 | Battery | 494-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BAT001392 | Battery | 494-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.2 | VDC |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BAT001392 | Battery | 494-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.2 | VDC |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BAT001392 | Battery | 494-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BAT001392 | Battery | 494-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | CH000205 | ControlHouse | MK-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | CH000205 | ControlHouse | MK-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | ST000160 | Structure | 815-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | ST000160 | Structure | 815-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | ST000160 | Structure | 815-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | ST000160 | Structure | 815-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | n | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | ST000160 | Structure | 815-Structure | Structure Patrol Inspection | General Comments | xfmr fuses are deteriorated | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | ST000160 | Structure | 815-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | ST000160 | Structure | 815-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | ST000160 | Structure | 815-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | ST000160 | Structure | 815-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | ST000160 | Structure | 815-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | ST000160 | Structure | 815-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | ST000160 | Structure | 815-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | ST000160 | Structure | 815-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | ST000160 | Structure | 815-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | ST000160 | Structure | 815-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | ST000160 | Structure | 815-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0633 | BreakerAirMagnetic | MG-454 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0633 | BreakerAirMagnetic | MG-454 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0633 | BreakerAirMagnetic | MG-454 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0633 | BreakerAirMagnetic | MG-454 | AMCB Readings | 9 Months Operations | 9 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0633 | BreakerAirMagnetic | MG-454 | AMCB Readings | 9 Month Ops New | 7 | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | ST000160 | Structure | 815-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0106 | Regulator | 481-1 C | Regulator Patrol Inspection | General Comments | | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0106 | Regulator | 481-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0106 | Regulator | 481-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0106 | Regulator | 481-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0106 | Regulator | 481-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0106 | Regulator | 481-1 C | Regulator Patrol Inspection | Current Tap Position | 10L | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0106 | Regulator | 481-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0106 | Regulator | 481-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0106 | Regulator | 481-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0106 | Regulator | 481-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0106 | Regulator | 481-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1245 | BreakerVacuum | WS-1336-4 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R0994 | Regulator | 212-5 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R0994 | Regulator | 212-5 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R0994 | Regulator | 212-5 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R0994 | Regulator | 212-5 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R0994 | Regulator | 212-5 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | ST000257 | Structure | 596-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | ST000257 | Structure | 596-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | ST000257 | Structure | 596-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | ST000257 | Structure | 596-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | ST000257 | Structure | 596-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | ST000257 | Structure | 596-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | ST000257 | Structure | 596-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | ST000257 | Structure | 596-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | ST000257 | Structure | 596-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | ST000257 | Structure | 596-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | ST000020 | Structure | 494-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | ST000020 | Structure | 494-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | ST000020 | Structure | 494-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | ST000020 | Structure | 494-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | ST000020 | Structure | 494-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | ST000020 | Structure | 494-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | ST000020 | Structure | 494-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | ST000020 | Structure | 494-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | ST000020 | Structure | 494-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | ST000020 | Structure | 494-Structure | Structure Patrol Inspection | General Comments | tower and transformer pads crumbling | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Readings | General Comments | | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | HV Winding Temp Max | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | H3 Winding Temp Present | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | H3 Winding Temp Max | 20 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | H2 Winding Temp Present | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | H2 Winding Temp Max | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | H1 Winding Temp Present | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | H1 Winding Temp Max | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1331 | BreakerVacuum | JT-1120 | VCB Readings | 9 Month Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1331 | BreakerVacuum | JT-1120 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1331 | BreakerVacuum | JT-1120 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0636 | BreakerAirMagnetic | MG-4KV TFR | AMCB Readings | 9 Month Ops New | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0636 | BreakerAirMagnetic | MG-4KV TFR | AMCB Readings | 9 Months Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0636 | BreakerAirMagnetic | MG-4KV TFR | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0636 | BreakerAirMagnetic | MG-4KV TFR | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0636 | BreakerAirMagnetic | MG-4KV TFR | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0636 | BreakerAirMagnetic | MG-4KV TFR | AMCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0636 | BreakerAirMagnetic | MG-4KV TFR | AMCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0636 | BreakerAirMagnetic | MG-4KV TFR | AMCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0636 | BreakerAirMagnetic | MG-4KV TFR | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0636 | BreakerAirMagnetic | MG-4KV TFR | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | CH000205 | ControlHouse | MK-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | CH000205 | ControlHouse | MK-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | CH000205 | ControlHouse | MK-Control House | Control House Patrol Inspection | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | CH000205 | ControlHouse | MK-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | CH000205 | ControlHouse | MK-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | CH000205 | ControlHouse | MK-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | Y3 Winding Temp Present | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | Y3 Winding Temp Max | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | Y2 Winding Temp Present | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | Y2 Winding Temp Max | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | Y1 Winding Temp Present | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | Y1 Winding Temp Max | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | X3 Winding Temp Present | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | X3 Winding Temp Max | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | X2 Winding Temp Present | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | X2 Winding Temp Max | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | X1 Winding Temp Present | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | X1 Winding Temp Max | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | Winding Temp Present | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | Winding Temp Max | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | TV Winding Temp Present | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | TV Winding Temp Max | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | Totalizer Meter Multiplier | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | Top Oil Temperature Present | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | Top Oil Temperature Max | 20 | °C |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Readings | Oil Temp Present | 22 | °C |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Readings | Oil Temp Max | 33 | °C |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 95.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | Percent Thermal Load C Ø Max | 20 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | Percent Thermal Load B Ø Max | 20 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | Percent Thermal Load A Ø Max | 20 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | Oil Temp Max | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1100 | psi |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | LV Winding Temp Present | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | LV Winding Temp Max | 20 | °C |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1401.84 | kw |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | LTC Totalizer Reading | 0.00 | kw |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000267 | WithLTC | MG-TRANS 7 | LTC Transformer Readings | HV Winding Temp Present | 20 | °C |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KT0053 | NonLTC | 481-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Readings | Amps A Ø | 110.0 | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Readings | Amps B Ø | 70.0 | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Readings | Amps C Ø | 50.0 | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | ST000264 | Structure | 481-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | ST000264 | Structure | 481-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | ST000264 | Structure | 481-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | ST000264 | Structure | 481-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | ST000264 | Structure | 481-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | ST000264 | Structure | 481-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | ST000264 | Structure | 481-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | ST000264 | Structure | 481-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | ST000264 | Structure | 481-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | ST000264 | Structure | 481-Structure | Structure Patrol Inspection | General Comments | | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | ST000264 | Structure | 481-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | ST000264 | Structure | 481-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | ST000264 | Structure | 481-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | ST000264 | Structure | 481-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | ST000264 | Structure | 481-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | ST000264 | Structure | 481-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | ST000264 | Structure | 481-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | ST000264 | Structure | 481-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | ST000264 | Structure | 481-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | ST000264 | Structure | 481-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Readings | General Comments | | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Readings | Operations Counter AF | 153 | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Readings | Operations Counter AL | 153 | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | ST000264 | Structure | 481-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | ST000264 | Structure | 481-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Readings | General Comments | 1TC | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | ST000234 | Structure | 497-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | ST000234 | Structure | 497-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | ST000234 | Structure | 497-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | ST000234 | Structure | 497-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | ST000234 | Structure | 497-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | ST000234 | Structure | 497-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | ST000234 | Structure | 497-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | ST000234 | Structure | 497-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | ST000234 | Structure | 497-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | ST000234 | Structure | 497-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | ST000234 | Structure | 497-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | ST000234 | Structure | 497-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | ST000234 | Structure | 497-Structure | Structure Patrol Inspection | General Comments | | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | ST000234 | Structure | 497-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | ST000234 | Structure | 497-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | ST000234 | Structure | 497-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | ST000234 | Structure | 497-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | ST000234 | Structure | 497-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | ST000234 | Structure | 497-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Readings | 9 Month Operations | 5 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | FE000254 | Fence | 481-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | FE000254 | Fence | 481-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | FE000254 | Fence | 481-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | FE000254 | Fence | 481-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | FE000254 | Fence | 481-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | FE000254 | Fence | 481-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | FE000254 | Fence | 481-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | FE000254 | Fence | 481-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | FE000254 | Fence | 481-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | FE000254 | Fence | 481-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | FE000254 | Fence | 481-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | FE000254 | Fence | 481-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | FE000254 | Fence | 481-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | FE000254 | Fence | 481-Fence | Fence Patrol Inspection | General Comments | | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | FE000254 | Fence | 481-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | FE000254 | Fence | 481-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1156 | BreakerVacuum | WO-1176 | VCB Readings | Operations Counter AF | 372 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1156 | BreakerVacuum | WO-1176 | VCB Readings | Operations Counter AL | 372 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1156 | BreakerVacuum | WO-1176 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1156 | BreakerVacuum | WO-1176 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1156 | BreakerVacuum | WO-1176 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | FE000142 | Fence | 771-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | FE000142 | Fence | 771-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | FE000142 | Fence | 771-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | FE000142 | Fence | 771-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | FE000142 | Fence | 771-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | FE000142 | Fence | 771-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | FE000142 | Fence | 771-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | FE000142 | Fence | 771-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | FE000142 | Fence | 771-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | FE000142 | Fence | 771-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | FE000142 | Fence | 771-Fence | Fence Patrol Inspection | General Comments | | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | FE000142 | Fence | 771-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | FE000142 | Fence | 771-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0638 | BreakerAirMagnetic | MG-4KV TR 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0638 | BreakerAirMagnetic | MG-4KV TR 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Readings | 9 Month Operations | 0 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Readings | Fault Adjusted Amps C Phase V | 4.19 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Readings | Fault Adjusted Amps B Phase V | 4.19 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Readings | Fault Adjusted Amps A Phase V | 4.19 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Readings | Amps C Ø | 137.0 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Readings | Amps B Ø | 134.0 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | YD000257 | Yard | 481-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | YD000257 | Yard | 481-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | YD000257 | Yard | 481-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | YD000257 | Yard | 481-Yard | Yard Patrol Inspection | General Comments | | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | YD000257 | Yard | 481-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | YD000257 | Yard | 481-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | YD000257 | Yard | 481-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | YD000257 | Yard | 481-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | YD000257 | Yard | 481-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | YD000257 | Yard | 481-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | YD000257 | Yard | 481-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | YD000257 | Yard | 481-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | YD000257 | Yard | 481-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | YD000257 | Yard | 481-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Readings | Amps A Ø | 123.0 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Readings | 9 Month Operations | 7 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0638 | BreakerAirMagnetic | MG-4KV TR 2 | AMCB Readings | 9 Month Ops New | 2 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0638 | BreakerAirMagnetic | MG-4KV TR 2 | AMCB Readings | 9 Months Operations | 2 | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1526 | Regulator | 894-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1526 | Regulator | 894-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1526 | Regulator | 894-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1526 | Regulator | 894-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1526 | Regulator | 894-1 A | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1526 | Regulator | 894-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1192 | BreakerVacuum | WS-1333-3 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1192 | BreakerVacuum | WS-1333-3 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1192 | BreakerVacuum | WS-1333-3 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1192 | BreakerVacuum | WS-1333-3 | VCB Readings | Operations Counter AL | 54 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1192 | BreakerVacuum | WS-1333-3 | VCB Readings | Operations Counter AF | 54 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1192 | BreakerVacuum | WS-1333-3 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1192 | BreakerVacuum | WS-1333-3 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1192 | BreakerVacuum | WS-1333-3 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1192 | BreakerVacuum | WS-1333-3 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1192 | BreakerVacuum | WS-1333-3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1192 | BreakerVacuum | WS-1333-3 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1192 | BreakerVacuum | WS-1333-3 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1192 | BreakerVacuum | WS-1333-3 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1192 | BreakerVacuum | WS-1333-3 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1192 | BreakerVacuum | WS-1333-3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1192 | BreakerVacuum | WS-1333-3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1192 | BreakerVacuum | WS-1333-3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1192 | BreakerVacuum | WS-1333-3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1192 | BreakerVacuum | WS-1333-3 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1192 | BreakerVacuum | WS-1333-3 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1192 | BreakerVacuum | WS-1333-3 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | LTCMechanism | WS-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | LTCMechanism | WS-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | LTCMechanism | WS-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | LTCMechanism | WS-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 26893 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Readings | Maintenance Operations | 1 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1192 | BreakerVacuum | WS-1333-3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1192 | BreakerVacuum | WS-1333-3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1192 | BreakerVacuum | WS-1333-3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1192 | BreakerVacuum | WS-1333-3 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1192 | BreakerVacuum | WS-1333-3 | VCB Readings | 9 Month Operations | 3 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1526 | Regulator | 894-1 A | Regulator Patrol Inspection | General Comments | | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0852 | BreakerAirMagnetic | SV-12KV BUS TIE SEC 1 | AMCB Readings | Operations Counter AL | 585 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0852 | BreakerAirMagnetic | SV-12KV BUS TIE SEC 1 | AMCB Readings | Operations This Read AM | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0852 | BreakerAirMagnetic | SV-12KV BUS TIE SEC 1 | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1526 | Regulator | 894-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1526 | Regulator | 894-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Readings | Unknown Operations | 1 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Readings | Operations This Read Vac | 2 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Readings | Operations Counter AL | 227 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0135 | BreakerVacuum | 467-1916 | VCB Readings | Operations Counter AF | 227 | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1526 | Regulator | 894-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1526 | Regulator | 894-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1526 | Regulator | 894-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1526 | Regulator | 894-1 A | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1526 | Regulator | 894-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1526 | Regulator | 894-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1526 | Regulator | 894-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | ST000261 | Structure | 006-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | ST000261 | Structure | 006-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | ST000261 | Structure | 006-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | ST000261 | Structure | 006-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | ST000261 | Structure | 006-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | ST000261 | Structure | 006-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | ST000261 | Structure | 006-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | ST000261 | Structure | 006-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | ST000261 | Structure | 006-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | ST000261 | Structure | 006-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | ST000261 | Structure | 006-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | ST000261 | Structure | 006-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | ST000261 | Structure | 006-Structure | Structure Patrol Inspection | General Comments | Whole station needs wildlife protection. | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | ST000261 | Structure | 006-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | ST000261 | Structure | 006-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | ST000261 | Structure | 006-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | ST000261 | Structure | 006-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | ST000261 | Structure | 006-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | ST000261 | Structure | 006-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | ST000261 | Structure | 006-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | ST000261 | Structure | 006-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | ST000261 | Structure | 006-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1526 | Regulator | 894-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | ST000234 | Structure | 497-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | ST000234 | Structure | 497-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | ST000234 | Structure | 497-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | K0112 | BreakerVacuum | 815-1907 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | LTCMechanism | WO-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | LTCMechanism | WO-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | LTCMechanism | WO-TRANS 2 | LTC Counter Readings | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | LTCMechanism | WO-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | LTCMechanism | WO-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 46654 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | LTCMechanism | WO-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 46645 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | LTCMechanism | WO-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | LTCMechanism | WO-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | LTCMechanism | WO-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | LTCMechanism | WO-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 410 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | LTCMechanism | WO-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | LTCMechanism | WO-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1241 | BreakerVacuum | WS-1319-2 | VCB Readings | 9 Month Operations | 2 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0635 | BreakerAirMagnetic | MG-4KV REA TIE | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0635 | BreakerAirMagnetic | MG-4KV REA TIE | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0635 | BreakerAirMagnetic | MG-4KV REA TIE | AMCB Readings | Operations This Read AM | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0635 | BreakerAirMagnetic | MG-4KV REA TIE | AMCB Readings | Operations Counter AL | 246 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0635 | BreakerAirMagnetic | MG-4KV REA TIE | AMCB Readings | Operations Counter AF | 246 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1241 | BreakerVacuum | WS-1319-2 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1241 | BreakerVacuum | WS-1319-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1241 | BreakerVacuum | WS-1319-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1241 | BreakerVacuum | WS-1319-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1241 | BreakerVacuum | WS-1319-2 | VCB Readings | Amps A Ø | 69.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1241 | BreakerVacuum | WS-1319-2 | VCB Readings | Amps B Ø | 68.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1241 | BreakerVacuum | WS-1319-2 | VCB Readings | Amps C Ø | 68.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1241 | BreakerVacuum | WS-1319-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1241 | BreakerVacuum | WS-1319-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1241 | BreakerVacuum | WS-1319-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1241 | BreakerVacuum | WS-1319-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1241 | BreakerVacuum | WS-1319-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1241 | BreakerVacuum | WS-1319-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1241 | BreakerVacuum | WS-1319-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1241 | BreakerVacuum | WS-1319-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1241 | BreakerVacuum | WS-1319-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0635 | BreakerAirMagnetic | MG-4KV REA TIE | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0635 | BreakerAirMagnetic | MG-4KV REA TIE | AMCB Readings | General Comments | | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1526 | Regulator | 894-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1526 | Regulator | 894-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.4 | volts |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1526 | Regulator | 894-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 54676 | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1526 | Regulator | 894-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1526 | Regulator | 894-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1526 | Regulator | 894-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | LTCMechanism | WS-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | LTCMechanism | WS-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 21 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | LTCMechanism | WS-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 208 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | LTCMechanism | WS-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | LTCMechanism | WS-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | LTCMechanism | WS-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0635 | BreakerAirMagnetic | MG-4KV REA TIE | AMCB Readings | 9 Month Ops New | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | LTCMechanism | WS-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1241 | BreakerVacuum | WS-1319-2 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1241 | BreakerVacuum | WS-1319-2 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1241 | BreakerVacuum | WS-1319-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1241 | BreakerVacuum | WS-1319-2 | VCB Readings | Operations Counter AL | 140 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1241 | BreakerVacuum | WS-1319-2 | VCB Readings | Operations Counter AF | 140 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1241 | BreakerVacuum | WS-1319-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0635 | BreakerAirMagnetic | MG-4KV REA TIE | AMCB Readings | 9 Months Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0635 | BreakerAirMagnetic | MG-4KV REA TIE | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0635 | BreakerAirMagnetic | MG-4KV REA TIE | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0635 | BreakerAirMagnetic | MG-4KV REA TIE | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0635 | BreakerAirMagnetic | MG-4KV REA TIE | AMCB Readings | Amps A Ø | 14.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0635 | BreakerAirMagnetic | MG-4KV REA TIE | AMCB Readings | Amps B Ø | 14.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0635 | BreakerAirMagnetic | MG-4KV REA TIE | AMCB Readings | Amps C Ø | 14.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0635 | BreakerAirMagnetic | MG-4KV REA TIE | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0635 | BreakerAirMagnetic | MG-4KV REA TIE | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0635 | BreakerAirMagnetic | MG-4KV REA TIE | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0635 | BreakerAirMagnetic | MG-4KV REA TIE | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1241 | BreakerVacuum | WS-1319-2 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1241 | BreakerVacuum | WS-1319-2 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1241 | BreakerVacuum | WS-1319-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0635 | BreakerAirMagnetic | MG-4KV REA TIE | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0635 | BreakerAirMagnetic | MG-4KV REA TIE | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0635 | BreakerAirMagnetic | MG-4KV REA TIE | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0635 | BreakerAirMagnetic | MG-4KV REA TIE | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0635 | BreakerAirMagnetic | MG-4KV REA TIE | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0635 | BreakerAirMagnetic | MG-4KV REA TIE | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0635 | BreakerAirMagnetic | MG-4KV REA TIE | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | YD000254 | Yard | 006-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | YD000254 | Yard | 006-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | YD000254 | Yard | 006-Yard | Yard Patrol Inspection | Ambient Temp | 54 | °F |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | FE000252 | Fence | 006-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | FE000252 | Fence | 006-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | FE000252 | Fence | 006-Fence | Fence Patrol Inspection | General Comments | | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | FE000252 | Fence | 006-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | FE000252 | Fence | 006-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | FE000252 | Fence | 006-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | FE000252 | Fence | 006-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | FE000252 | Fence | 006-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | FE000252 | Fence | 006-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | FE000252 | Fence | 006-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | FE000252 | Fence | 006-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | FE000252 | Fence | 006-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | FE000252 | Fence | 006-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | FE000252 | Fence | 006-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | FE000252 | Fence | 006-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | FE000252 | Fence | 006-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Readings | General Comments | Knob is broken on temp reset | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Readings | LTC Totalizer Reading | 5258.88 | kw |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Readings | Totalizer Meter Reading | .5478 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | ST000645 | Structure | WO-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | ST000645 | Structure | WO-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | ST000645 | Structure | WO-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | ST000645 | Structure | WO-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | ST000645 | Structure | WO-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | ST000645 | Structure | WO-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1249 | BreakerVacuum | WS-1426-4 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1249 | BreakerVacuum | WS-1426-4 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1249 | BreakerVacuum | WS-1426-4 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1249 | BreakerVacuum | WS-1426-4 | VCB Readings | Operations Counter AL | 53 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1249 | BreakerVacuum | WS-1426-4 | VCB Readings | Operations Counter AF | 53 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1249 | BreakerVacuum | WS-1426-4 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1249 | BreakerVacuum | WS-1426-4 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1249 | BreakerVacuum | WS-1426-4 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1249 | BreakerVacuum | WS-1426-4 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1249 | BreakerVacuum | WS-1426-4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1249 | BreakerVacuum | WS-1426-4 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1249 | BreakerVacuum | WS-1426-4 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1249 | BreakerVacuum | WS-1426-4 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1249 | BreakerVacuum | WS-1426-4 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1249 | BreakerVacuum | WS-1426-4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1249 | BreakerVacuum | WS-1426-4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1249 | BreakerVacuum | WS-1426-4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1249 | BreakerVacuum | WS-1426-4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1249 | BreakerVacuum | WS-1426-4 | VCB Readings | Amps C Ø | 90.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1249 | BreakerVacuum | WS-1426-4 | VCB Readings | Amps B Ø | 89.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1249 | BreakerVacuum | WS-1426-4 | VCB Readings | Amps A Ø | 92.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1249 | BreakerVacuum | WS-1426-4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1249 | BreakerVacuum | WS-1426-4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1249 | BreakerVacuum | WS-1426-4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1249 | BreakerVacuum | WS-1426-4 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0104 | Regulator | 481-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0104 | Regulator | 481-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0104 | Regulator | 481-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0104 | Regulator | 481-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0104 | Regulator | 481-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0104 | Regulator | 481-1 A | Regulator Patrol Inspection | Current Tap Position | 11L | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0104 | Regulator | 481-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1398 | Regulator | 439-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1398 | Regulator | 439-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1398 | Regulator | 439-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1398 | Regulator | 439-1 C | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1398 | Regulator | 439-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1398 | Regulator | 439-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1398 | Regulator | 439-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | ST000263 | Structure | 439-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1398 | Regulator | 439-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1398 | Regulator | 439-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1397 | Regulator | 439-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1397 | Regulator | 439-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | ST000263 | Structure | 439-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | ST000263 | Structure | 439-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | ST000263 | Structure | 439-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1397 | Regulator | 439-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1397 | Regulator | 439-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1397 | Regulator | 439-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 33922 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1397 | Regulator | 439-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1397 | Regulator | 439-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1397 | Regulator | 439-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1397 | Regulator | 439-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1397 | Regulator | 439-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1397 | Regulator | 439-1 B | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1397 | Regulator | 439-1 B | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1397 | Regulator | 439-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1397 | Regulator | 439-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | ST000263 | Structure | 439-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | ST000263 | Structure | 439-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | ST000263 | Structure | 439-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | ST000263 | Structure | 439-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | ST000263 | Structure | 439-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | ST000263 | Structure | 439-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | ST000263 | Structure | 439-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | ST000263 | Structure | 439-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | ST000263 | Structure | 439-Structure | Structure Patrol Inspection | General Comments | | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | ST000263 | Structure | 439-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | ST000263 | Structure | 439-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | ST000263 | Structure | 439-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | ST000263 | Structure | 439-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1397 | Regulator | 439-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1397 | Regulator | 439-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1397 | Regulator | 439-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1397 | Regulator | 439-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1397 | Regulator | 439-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1397 | Regulator | 439-1 B | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1397 | Regulator | 439-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1397 | Regulator | 439-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1397 | Regulator | 439-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1397 | Regulator | 439-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | YD000254 | Yard | 006-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | YD000254 | Yard | 006-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | YD000254 | Yard | 006-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | YD000254 | Yard | 006-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | YD000254 | Yard | 006-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | YD000254 | Yard | 006-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | YD000254 | Yard | 006-Yard | Yard Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0116 | NonLTC | MG-TRANS 1 B PHASE | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0116 | NonLTC | MG-TRANS 1 B PHASE | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | YD000254 | Yard | 006-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | YD000254 | Yard | 006-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | YD000254 | Yard | 006-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | YD000256 | Yard | 439-Yard | Yard Patrol Inspection | Ambient Temp | 51 | °F |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | YD000256 | Yard | 439-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | YD000256 | Yard | 439-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | YD000256 | Yard | 439-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | YD000256 | Yard | 439-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | YD000256 | Yard | 439-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | YD000256 | Yard | 439-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | YD000256 | Yard | 439-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | YD000256 | Yard | 439-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | YD000256 | Yard | 439-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | YD000256 | Yard | 439-Yard | Yard Patrol Inspection | General Comments | | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | YD000256 | Yard | 439-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | YD000256 | Yard | 439-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | YD000256 | Yard | 439-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | ST000263 | Structure | 439-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | ST000263 | Structure | 439-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | ST000263 | Structure | 439-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | ST000263 | Structure | 439-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | ST000263 | Structure | 439-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0105 | Regulator | 481-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0105 | Regulator | 481-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0105 | Regulator | 481-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0105 | Regulator | 481-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.8 | volts |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1156 | BreakerVacuum | WO-1176 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1156 | BreakerVacuum | WO-1176 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1156 | BreakerVacuum | WO-1176 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1156 | BreakerVacuum | WO-1176 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0105 | Regulator | 481-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 32211 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0105 | Regulator | 481-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0105 | Regulator | 481-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0105 | Regulator | 481-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0105 | Regulator | 481-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Readings | Switching Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Readings | Operations Counter AL | 222 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Readings | Operations Counter AF | 222 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1156 | BreakerVacuum | WO-1176 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1156 | BreakerVacuum | WO-1176 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1156 | BreakerVacuum | WO-1176 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1156 | BreakerVacuum | WO-1176 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1156 | BreakerVacuum | WO-1176 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1156 | BreakerVacuum | WO-1176 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1156 | BreakerVacuum | WO-1176 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1156 | BreakerVacuum | WO-1176 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1156 | BreakerVacuum | WO-1176 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1156 | BreakerVacuum | WO-1176 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Readings | General Comments | | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Readings | Amps A Ø | 39.0 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Readings | Amps B Ø | 31.0 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Readings | Amps C Ø | 42.0 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1156 | BreakerVacuum | WO-1176 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1156 | BreakerVacuum | WO-1176 | VCB Readings | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1156 | BreakerVacuum | WO-1176 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | FE000142 | Fence | 771-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | FE000142 | Fence | 771-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | FE000142 | Fence | 771-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0638 | BreakerAirMagnetic | MG-4KV TR 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0638 | BreakerAirMagnetic | MG-4KV TR 2 | AMCB Readings | Amps A Ø | 226.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0638 | BreakerAirMagnetic | MG-4KV TR 2 | AMCB Readings | Amps B Ø | 215.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0638 | BreakerAirMagnetic | MG-4KV TR 2 | AMCB Readings | Amps C Ø | 220.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0638 | BreakerAirMagnetic | MG-4KV TR 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0638 | BreakerAirMagnetic | MG-4KV TR 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0638 | BreakerAirMagnetic | MG-4KV TR 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0638 | BreakerAirMagnetic | MG-4KV TR 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0638 | BreakerAirMagnetic | MG-4KV TR 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0638 | BreakerAirMagnetic | MG-4KV TR 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0638 | BreakerAirMagnetic | MG-4KV TR 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0638 | BreakerAirMagnetic | MG-4KV TR 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0638 | BreakerAirMagnetic | MG-4KV TR 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0638 | BreakerAirMagnetic | MG-4KV TR 2 | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0638 | BreakerAirMagnetic | MG-4KV TR 2 | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0638 | BreakerAirMagnetic | MG-4KV TR 2 | AMCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0638 | BreakerAirMagnetic | MG-4KV TR 2 | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0638 | BreakerAirMagnetic | MG-4KV TR 2 | AMCB Readings | Operations Counter AF | 245 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0638 | BreakerAirMagnetic | MG-4KV TR 2 | AMCB Readings | Operations Counter AL | 245 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1156 | BreakerVacuum | WO-1176 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | BK001436 | BreakerVacuum | 494-0575 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0104 | Regulator | 481-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0104 | Regulator | 481-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0104 | Regulator | 481-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0104 | Regulator | 481-1 A | Regulator Patrol Inspection | General Comments | | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0104 | Regulator | 481-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0104 | Regulator | 481-1 A | Regulator Patrol Inspection | Max Tap Position | 4L | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0104 | Regulator | 481-1 A | Regulator Patrol Inspection | Min Tap Position | 15L | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0104 | Regulator | 481-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0104 | Regulator | 481-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0104 | Regulator | 481-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0104 | Regulator | 481-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | ST000645 | Structure | WO-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1388 | Regulator | 212-5 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1388 | Regulator | 212-5 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | ST000645 | Structure | WO-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | ST000645 | Structure | WO-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | ST000645 | Structure | WO-Structure | Structure Patrol Inspection | Platform/Walkway/Railing OK? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | ST000645 | Structure | WO-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | ST000645 | Structure | WO-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | ST000645 | Structure | WO-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | ST000645 | Structure | WO-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | ST000645 | Structure | WO-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | ST000645 | Structure | WO-Structure | Structure Patrol Inspection | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | ST000645 | Structure | WO-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | ST000645 | Structure | WO-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | ST000645 | Structure | WO-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1388 | Regulator | 212-5 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1388 | Regulator | 212-5 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1388 | Regulator | 212-5 C | Regulator Patrol Inspection | Regulator As Left Counter | 169728 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1388 | Regulator | 212-5 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | ST000645 | Structure | WO-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | ST000645 | Structure | WO-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | ST000645 | Structure | WO-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | ST000645 | Structure | WO-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | ST000645 | Structure | WO-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0104 | Regulator | 481-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0104 | Regulator | 481-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 32045 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0104 | Regulator | 481-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0104 | Regulator | 481-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0104 | Regulator | 481-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0105 | Regulator | 481-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0105 | Regulator | 481-1 B | Regulator Patrol Inspection | Min Tap Position | 15L | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0105 | Regulator | 481-1 B | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1156 | BreakerVacuum | WO-1176 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1156 | BreakerVacuum | WO-1176 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1156 | BreakerVacuum | WO-1176 | VCB Readings | 9 Month Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0638 | BreakerAirMagnetic | MG-4KV TR 2 | AMCB Readings | Operations This Read AM | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0638 | BreakerAirMagnetic | MG-4KV TR 2 | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0638 | BreakerAirMagnetic | MG-4KV TR 2 | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0105 | Regulator | 481-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0105 | Regulator | 481-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0105 | Regulator | 481-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0105 | Regulator | 481-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0105 | Regulator | 481-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0105 | Regulator | 481-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0105 | Regulator | 481-1 B | Regulator Patrol Inspection | Current Tap Position | 10L | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0105 | Regulator | 481-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1388 | Regulator | 212-5 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1388 | Regulator | 212-5 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1388 | Regulator | 212-5 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1388 | Regulator | 212-5 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1388 | Regulator | 212-5 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1388 | Regulator | 212-5 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1388 | Regulator | 212-5 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1388 | Regulator | 212-5 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1388 | Regulator | 212-5 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1388 | Regulator | 212-5 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1388 | Regulator | 212-5 C | Regulator Patrol Inspection | General Comments | ok | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1388 | Regulator | 212-5 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1388 | Regulator | 212-5 C | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1388 | Regulator | 212-5 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1388 | Regulator | 212-5 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1388 | Regulator | 212-5 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1388 | Regulator | 212-5 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1388 | Regulator | 212-5 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0105 | Regulator | 481-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0105 | Regulator | 481-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1249 | BreakerVacuum | WS-1426-4 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0105 | Regulator | 481-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0105 | Regulator | 481-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | KR0104 | Regulator | 481-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0486 | Regulator | 686-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0486 | Regulator | 686-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0487 | Regulator | 686-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0487 | Regulator | 686-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0487 | Regulator | 686-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0487 | Regulator | 686-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0487 | Regulator | 686-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0487 | Regulator | 686-1 B | Regulator Patrol Inspection | Current Tap Position | 2R | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0487 | Regulator | 686-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0487 | Regulator | 686-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0487 | Regulator | 686-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0487 | Regulator | 686-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0487 | Regulator | 686-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0487 | Regulator | 686-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0487 | Regulator | 686-1 B | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0487 | Regulator | 686-1 B | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0487 | Regulator | 686-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0487 | Regulator | 686-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0487 | Regulator | 686-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0487 | Regulator | 686-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0487 | Regulator | 686-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.0 | volts |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0487 | Regulator | 686-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 51991 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0487 | Regulator | 686-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0487 | Regulator | 686-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0487 | Regulator | 686-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0487 | Regulator | 686-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Patrol Inspection | General Comments | ok | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Readings | General Comments | ok | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1219.68 | kw |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 197.50 | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 180.00 | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Readings | Oil Temp Max | 49 | °C |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Readings | Oil Temp Present | 22 | °C |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | C0325 | NonLTC | 682-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .5082 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0488 | Regulator | 686-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0488 | Regulator | 686-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0488 | Regulator | 686-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0488 | Regulator | 686-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0488 | Regulator | 686-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0488 | Regulator | 686-1 C | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0488 | Regulator | 686-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0488 | Regulator | 686-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0488 | Regulator | 686-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0488 | Regulator | 686-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0488 | Regulator | 686-1 C | Regulator Patrol Inspection | General Comments | CONTROL NOT WORKING | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0488 | Regulator | 686-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0488 | Regulator | 686-1 C | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0488 | Regulator | 686-1 C | Regulator Patrol Inspection | Min Tap Position | Neutral | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0488 | Regulator | 686-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0488 | Regulator | 686-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0488 | Regulator | 686-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0488 | Regulator | 686-1 C | Regulator Patrol Inspection | Reg Operation Checked? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0488 | Regulator | 686-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 125.0 | volts |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0488 | Regulator | 686-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 93616 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0488 | Regulator | 686-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0488 | Regulator | 686-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0488 | Regulator | 686-1 C | Regulator Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0488 | Regulator | 686-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1435 | Regulator | 771-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1435 | Regulator | 771-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1435 | Regulator | 771-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1435 | Regulator | 771-1 C | Regulator Patrol Inspection | Min Tap Position | 15L | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1435 | Regulator | 771-1 C | Regulator Patrol Inspection | Max Tap Position | 9L | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1435 | Regulator | 771-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1435 | Regulator | 771-1 C | Regulator Patrol Inspection | General Comments | | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1435 | Regulator | 771-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1435 | Regulator | 771-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1435 | Regulator | 771-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1435 | Regulator | 771-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1435 | Regulator | 771-1 C | Regulator Patrol Inspection | Current Tap Position | 10L | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1435 | Regulator | 771-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1435 | Regulator | 771-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1435 | Regulator | 771-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1435 | Regulator | 771-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1435 | Regulator | 771-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1433 | Regulator | 771-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1433 | Regulator | 771-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1433 | Regulator | 771-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1433 | Regulator | 771-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 86853 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1433 | Regulator | 771-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1433 | Regulator | 771-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1433 | Regulator | 771-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1433 | Regulator | 771-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1433 | Regulator | 771-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1433 | Regulator | 771-1 A | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1433 | Regulator | 771-1 A | Regulator Patrol Inspection | Max Tap Position | 6L | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1433 | Regulator | 771-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1433 | Regulator | 771-1 A | Regulator Patrol Inspection | General Comments | | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1433 | Regulator | 771-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1433 | Regulator | 771-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1433 | Regulator | 771-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1433 | Regulator | 771-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1433 | Regulator | 771-1 A | Regulator Patrol Inspection | Current Tap Position | 9L | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1433 | Regulator | 771-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1433 | Regulator | 771-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1433 | Regulator | 771-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1433 | Regulator | 771-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1433 | Regulator | 771-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0486 | Regulator | 686-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0486 | Regulator | 686-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0486 | Regulator | 686-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 117673 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0486 | Regulator | 686-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0486 | Regulator | 686-1 A | Regulator Patrol Inspection | Reg Operation Checked? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0486 | Regulator | 686-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0486 | Regulator | 686-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0486 | Regulator | 686-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0486 | Regulator | 686-1 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0486 | Regulator | 686-1 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0486 | Regulator | 686-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0486 | Regulator | 686-1 A | Regulator Patrol Inspection | General Comments | WILL NOT MOVE | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0486 | Regulator | 686-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0486 | Regulator | 686-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0486 | Regulator | 686-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0486 | Regulator | 686-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0486 | Regulator | 686-1 A | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0486 | Regulator | 686-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0486 | Regulator | 686-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0486 | Regulator | 686-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0486 | Regulator | 686-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | R0486 | Regulator | 686-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000248 | NonLTC | MG-TRANS 2 B PHASE | NonLTC Transformer Readings | Winding Temp Present | 24 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000248 | NonLTC | MG-TRANS 2 B PHASE | NonLTC Transformer Readings | Winding Temp Max | 35 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000248 | NonLTC | MG-TRANS 2 B PHASE | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000248 | NonLTC | MG-TRANS 2 B PHASE | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000248 | NonLTC | MG-TRANS 2 B PHASE | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000248 | NonLTC | MG-TRANS 2 B PHASE | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000248 | NonLTC | MG-TRANS 2 B PHASE | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000248 | NonLTC | MG-TRANS 2 B PHASE | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000248 | NonLTC | MG-TRANS 2 B PHASE | NonLTC Transformer Readings | Oil Temp Present | 24 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000248 | NonLTC | MG-TRANS 2 B PHASE | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000248 | NonLTC | MG-TRANS 2 B PHASE | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000248 | NonLTC | MG-TRANS 2 B PHASE | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 8.33 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000248 | NonLTC | MG-TRANS 2 B PHASE | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000248 | NonLTC | MG-TRANS 2 B PHASE | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.5 | psi |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000248 | NonLTC | MG-TRANS 2 B PHASE | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000248 | NonLTC | MG-TRANS 2 B PHASE | NonLTC Transformer Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000248 | NonLTC | MG-TRANS 2 B PHASE | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000248 | NonLTC | MG-TRANS 2 B PHASE | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000248 | NonLTC | MG-TRANS 2 B PHASE | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Readings | General Comments | | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Readings | Maintenance Operations | 1 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Readings | Operations Counter AF | 248 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Readings | Operations Counter AL | 248 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Readings | Operations This Read Vac | 1 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Readings | Winding Temp Present | 25 | °C |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Readings | Winding Temp Max | 35 | °C |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .8004 | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Readings | General Comments | | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1920.96 | kw |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Readings | Oil Temp Max | 29 | °C |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Readings | Oil Temp Present | 18 | °C |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Readings | Operations This Read Vac | 1 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Readings | Operations Counter AL | 162 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Readings | Operations Counter AF | 162 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Readings | Maintenance Operations | 1 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Patrol Inspection | General Comments | ok | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Readings | General Comments | 1 trip check | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | S0065 | NonLTC | 894-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0606 | BreakerAirMagnetic | MG-1328 | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0606 | BreakerAirMagnetic | MG-1328 | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0606 | BreakerAirMagnetic | MG-1328 | AMCB Readings | Operations This Read AM | 6 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0606 | BreakerAirMagnetic | MG-1328 | AMCB Readings | Operations Counter AL | 347 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0606 | BreakerAirMagnetic | MG-1328 | AMCB Readings | Operations Counter AF | 347 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0606 | BreakerAirMagnetic | MG-1328 | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Readings | Amps A Ø | 9.0 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Readings | Amps B Ø | 23.0 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Readings | Amps C Ø | 14.0 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0606 | BreakerAirMagnetic | MG-1328 | AMCB Readings | General Comments | B Phase TOC | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0606 | BreakerAirMagnetic | MG-1328 | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0606 | BreakerAirMagnetic | MG-1328 | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0606 | BreakerAirMagnetic | MG-1328 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0606 | BreakerAirMagnetic | MG-1328 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0606 | BreakerAirMagnetic | MG-1328 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0606 | BreakerAirMagnetic | MG-1328 | AMCB Readings | Fault Operations B Ø | 6 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0606 | BreakerAirMagnetic | MG-1328 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0606 | BreakerAirMagnetic | MG-1328 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0606 | BreakerAirMagnetic | MG-1328 | AMCB Readings | Fault Adjusted Amps B Phase AM | 67.08 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0606 | BreakerAirMagnetic | MG-1328 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0606 | BreakerAirMagnetic | MG-1328 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0606 | BreakerAirMagnetic | MG-1328 | AMCB Readings | Amps C Ø | 232.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0606 | BreakerAirMagnetic | MG-1328 | AMCB Readings | Amps B Ø | 224.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0606 | BreakerAirMagnetic | MG-1328 | AMCB Readings | Amps A Ø | 234.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0606 | BreakerAirMagnetic | MG-1328 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0606 | BreakerAirMagnetic | MG-1328 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0606 | BreakerAirMagnetic | MG-1328 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0606 | BreakerAirMagnetic | MG-1328 | AMCB Readings | 9 Months Operations | 16 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0606 | BreakerAirMagnetic | MG-1328 | AMCB Readings | 9 Month Ops New | 10 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Readings | Amps C Ø | 29.0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Readings | Amps B Ø | 23.0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Readings | Amps A Ø | 16.0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0160 | BreakerVacuum | 571-1646 | VCB Readings | 9 Month Operations | 1 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | BK001416 | BreakerVacuum | 212-0699 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1194 | BreakerVacuum | WS-1335-3 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1194 | BreakerVacuum | WS-1335-3 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1194 | BreakerVacuum | WS-1335-3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1194 | BreakerVacuum | WS-1335-3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1194 | BreakerVacuum | WS-1335-3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1194 | BreakerVacuum | WS-1335-3 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1194 | BreakerVacuum | WS-1335-3 | VCB Readings | Amps B Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1194 | BreakerVacuum | WS-1335-3 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1194 | BreakerVacuum | WS-1335-3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1194 | BreakerVacuum | WS-1335-3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1194 | BreakerVacuum | WS-1335-3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1194 | BreakerVacuum | WS-1335-3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1194 | BreakerVacuum | WS-1335-3 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1194 | BreakerVacuum | WS-1335-3 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1194 | BreakerVacuum | WS-1335-3 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1194 | BreakerVacuum | WS-1335-3 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1194 | BreakerVacuum | WS-1335-3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1194 | BreakerVacuum | WS-1335-3 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1194 | BreakerVacuum | WS-1335-3 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1194 | BreakerVacuum | WS-1335-3 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1194 | BreakerVacuum | WS-1335-3 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1194 | BreakerVacuum | WS-1335-3 | VCB Readings | Operations Counter AF | 153 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1194 | BreakerVacuum | WS-1335-3 | VCB Readings | Operations Counter AL | 153 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1194 | BreakerVacuum | WS-1335-3 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1194 | BreakerVacuum | WS-1335-3 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1194 | BreakerVacuum | WS-1335-3 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Readings | General Comments | | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Readings | Operations Counter AF | 144 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Readings | Operations Counter AL | 144 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1335 | BreakerVacuum | JT-1128 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1335 | BreakerVacuum | JT-1128 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1335 | BreakerVacuum | JT-1128 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1335 | BreakerVacuum | JT-1128 | VCB Readings | Operations Counter AL | 145 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1335 | BreakerVacuum | JT-1128 | VCB Readings | Operations Counter AF | 145 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1335 | BreakerVacuum | JT-1128 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1335 | BreakerVacuum | JT-1128 | VCB Readings | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1335 | BreakerVacuum | JT-1128 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1335 | BreakerVacuum | JT-1128 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1335 | BreakerVacuum | JT-1128 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1335 | BreakerVacuum | JT-1128 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1335 | BreakerVacuum | JT-1128 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1335 | BreakerVacuum | JT-1128 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1335 | BreakerVacuum | JT-1128 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1335 | BreakerVacuum | JT-1128 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1335 | BreakerVacuum | JT-1128 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1335 | BreakerVacuum | JT-1128 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1335 | BreakerVacuum | JT-1128 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1335 | BreakerVacuum | JT-1128 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1335 | BreakerVacuum | JT-1128 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1335 | BreakerVacuum | JT-1128 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1335 | BreakerVacuum | JT-1128 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1335 | BreakerVacuum | JT-1128 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1335 | BreakerVacuum | JT-1128 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1335 | BreakerVacuum | JT-1128 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1335 | BreakerVacuum | JT-1128 | VCB Readings | 9 Month Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000246 | NonLTC | MG-TRANS 2 C PHASE | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000246 | NonLTC | MG-TRANS 2 C PHASE | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000246 | NonLTC | MG-TRANS 2 C PHASE | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000246 | NonLTC | MG-TRANS 2 C PHASE | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000246 | NonLTC | MG-TRANS 2 C PHASE | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000246 | NonLTC | MG-TRANS 2 C PHASE | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000246 | NonLTC | MG-TRANS 2 C PHASE | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000246 | NonLTC | MG-TRANS 2 C PHASE | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000246 | NonLTC | MG-TRANS 2 C PHASE | NonLTC Transformer Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000246 | NonLTC | MG-TRANS 2 C PHASE | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1240 | BreakerVacuum | WS-1308-2 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1240 | BreakerVacuum | WS-1308-2 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1240 | BreakerVacuum | WS-1308-2 | VCB Readings | Operations This Read Vac | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1240 | BreakerVacuum | WS-1308-2 | VCB Readings | Operations Counter AL | 95 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1240 | BreakerVacuum | WS-1308-2 | VCB Readings | Operations Counter AF | 95 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1240 | BreakerVacuum | WS-1308-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1240 | BreakerVacuum | WS-1308-2 | VCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000246 | NonLTC | MG-TRANS 2 C PHASE | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000246 | NonLTC | MG-TRANS 2 C PHASE | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000246 | NonLTC | MG-TRANS 2 C PHASE | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 53.33 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1240 | BreakerVacuum | WS-1308-2 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1240 | BreakerVacuum | WS-1308-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1240 | BreakerVacuum | WS-1308-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1240 | BreakerVacuum | WS-1308-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1240 | BreakerVacuum | WS-1308-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1240 | BreakerVacuum | WS-1308-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1240 | BreakerVacuum | WS-1308-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1240 | BreakerVacuum | WS-1308-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1240 | BreakerVacuum | WS-1308-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1240 | BreakerVacuum | WS-1308-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1240 | BreakerVacuum | WS-1308-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1240 | BreakerVacuum | WS-1308-2 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1240 | BreakerVacuum | WS-1308-2 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1240 | BreakerVacuum | WS-1308-2 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1240 | BreakerVacuum | WS-1308-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1240 | BreakerVacuum | WS-1308-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1240 | BreakerVacuum | WS-1308-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0852 | BreakerAirMagnetic | SV-12KV BUS TIE SEC 1 | AMCB Readings | Operations Counter AF | 585 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0852 | BreakerAirMagnetic | SV-12KV BUS TIE SEC 1 | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0852 | BreakerAirMagnetic | SV-12KV BUS TIE SEC 1 | AMCB Readings | General Comments | | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0852 | BreakerAirMagnetic | SV-12KV BUS TIE SEC 1 | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0852 | BreakerAirMagnetic | SV-12KV BUS TIE SEC 1 | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0852 | BreakerAirMagnetic | SV-12KV BUS TIE SEC 1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0852 | BreakerAirMagnetic | SV-12KV BUS TIE SEC 1 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0852 | BreakerAirMagnetic | SV-12KV BUS TIE SEC 1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0852 | BreakerAirMagnetic | SV-12KV BUS TIE SEC 1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0852 | BreakerAirMagnetic | SV-12KV BUS TIE SEC 1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0852 | BreakerAirMagnetic | SV-12KV BUS TIE SEC 1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0852 | BreakerAirMagnetic | SV-12KV BUS TIE SEC 1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0852 | BreakerAirMagnetic | SV-12KV BUS TIE SEC 1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0852 | BreakerAirMagnetic | SV-12KV BUS TIE SEC 1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0852 | BreakerAirMagnetic | SV-12KV BUS TIE SEC 1 | AMCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0852 | BreakerAirMagnetic | SV-12KV BUS TIE SEC 1 | AMCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0852 | BreakerAirMagnetic | SV-12KV BUS TIE SEC 1 | AMCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0852 | BreakerAirMagnetic | SV-12KV BUS TIE SEC 1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0852 | BreakerAirMagnetic | SV-12KV BUS TIE SEC 1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0852 | BreakerAirMagnetic | SV-12KV BUS TIE SEC 1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0852 | BreakerAirMagnetic | SV-12KV BUS TIE SEC 1 | AMCB Readings | 9 Months Operations | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0852 | BreakerAirMagnetic | SV-12KV BUS TIE SEC 1 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | LTCC000826 | LTCControl | 497-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | LTCC000826 | LTCControl | 497-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | LTCC000826 | LTCControl | 497-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0631 | BreakerAirMagnetic | MG-451 | AMCB Readings | Unknown Operations | 2 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0631 | BreakerAirMagnetic | MG-451 | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0631 | BreakerAirMagnetic | MG-451 | AMCB Readings | Operations This Read AM | 2 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0631 | BreakerAirMagnetic | MG-451 | AMCB Readings | Operations Counter AL | 366 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0631 | BreakerAirMagnetic | MG-451 | AMCB Readings | Operations Counter AF | 366 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0631 | BreakerAirMagnetic | MG-451 | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0631 | BreakerAirMagnetic | MG-451 | AMCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0631 | BreakerAirMagnetic | MG-451 | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0631 | BreakerAirMagnetic | MG-451 | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0631 | BreakerAirMagnetic | MG-451 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0631 | BreakerAirMagnetic | MG-451 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0631 | BreakerAirMagnetic | MG-451 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0631 | BreakerAirMagnetic | MG-451 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0631 | BreakerAirMagnetic | MG-451 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0631 | BreakerAirMagnetic | MG-451 | AMCB Readings | Fault Adjusted Amps C Phase AM | 19.09 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Readings | Amps C Ø | 120.0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Readings | Amps B Ø | 30.0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Readings | Amps A Ø | 90.0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | K0072 | BreakerVacuum | 006-1603 | VCB Readings | 9 Month Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | LTCMechanism | WS-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | LTCMechanism | WS-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | LTCMechanism | WS-TRANS 2 | LTC Counter Readings | General Comments | | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | LTCC000826 | LTCControl | 497-1 | LTC Control Insp | All Connections OK? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | LTCMechanism | WS-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | LTCMechanism | WS-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 26893 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | LTCC000826 | LTCControl | 497-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | LTCC000826 | LTCControl | 497-1 | LTC Control Insp | General Comments | | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | LTCC000826 | LTCControl | 497-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | LTCC000826 | LTCControl | 497-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0631 | BreakerAirMagnetic | MG-451 | AMCB Readings | 9 Month Ops New | 1 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0631 | BreakerAirMagnetic | MG-451 | AMCB Readings | 9 Months Operations | 3 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0631 | BreakerAirMagnetic | MG-451 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0631 | BreakerAirMagnetic | MG-451 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0631 | BreakerAirMagnetic | MG-451 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0631 | BreakerAirMagnetic | MG-451 | AMCB Readings | Amps A Ø | 41.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0631 | BreakerAirMagnetic | MG-451 | AMCB Readings | Amps B Ø | 24.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0631 | BreakerAirMagnetic | MG-451 | AMCB Readings | Amps C Ø | 34.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0631 | BreakerAirMagnetic | MG-451 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0631 | BreakerAirMagnetic | MG-451 | AMCB Readings | Fault Adjusted Amps A Phase AM | 19.09 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0631 | BreakerAirMagnetic | MG-451 | AMCB Readings | Fault Adjusted Amps B Phase AM | 19.09 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | ST000207 | Structure | 736-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | ST000207 | Structure | 736-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | FE000316 | Fence | 641-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | FE000316 | Fence | 641-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | FE000316 | Fence | 641-Fence | Fence Patrol Inspection | General Comments | | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | FE000316 | Fence | 641-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | ST000207 | Structure | 736-Structure | Structure Patrol Inspection | General Comments | | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | ST000207 | Structure | 736-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | ST000207 | Structure | 736-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | ST000207 | Structure | 736-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | ST000207 | Structure | 736-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | ST000207 | Structure | 736-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | ST000207 | Structure | 736-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | ST000207 | Structure | 736-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | ST000207 | Structure | 736-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | ST000207 | Structure | 736-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | ST000207 | Structure | 736-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | ST000207 | Structure | 736-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | ST000207 | Structure | 736-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1217 | BreakerVacuum | WS-1332-4 | VCB Readings | Amps A Ø | 65.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1217 | BreakerVacuum | WS-1332-4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1217 | BreakerVacuum | WS-1332-4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1217 | BreakerVacuum | WS-1332-4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1217 | BreakerVacuum | WS-1332-4 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1217 | BreakerVacuum | WS-1332-4 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1179 | BreakerVacuum | WS-1306-1 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1179 | BreakerVacuum | WS-1306-1 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1179 | BreakerVacuum | WS-1306-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1179 | BreakerVacuum | WS-1306-1 | VCB Readings | Operations Counter AL | 84 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1179 | BreakerVacuum | WS-1306-1 | VCB Readings | Operations Counter AF | 84 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1179 | BreakerVacuum | WS-1306-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1179 | BreakerVacuum | WS-1306-1 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1179 | BreakerVacuum | WS-1306-1 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1179 | BreakerVacuum | WS-1306-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1179 | BreakerVacuum | WS-1306-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1179 | BreakerVacuum | WS-1306-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1179 | BreakerVacuum | WS-1306-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1179 | BreakerVacuum | WS-1306-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1179 | BreakerVacuum | WS-1306-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1179 | BreakerVacuum | WS-1306-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1435 | Regulator | 771-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1435 | Regulator | 771-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1435 | Regulator | 771-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 91347 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1435 | Regulator | 771-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1435 | Regulator | 771-1 C | Regulator Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1435 | Regulator | 771-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000248 | NonLTC | MG-TRANS 2 B PHASE | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000248 | NonLTC | MG-TRANS 2 B PHASE | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000248 | NonLTC | MG-TRANS 2 B PHASE | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000248 | NonLTC | MG-TRANS 2 B PHASE | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000248 | NonLTC | MG-TRANS 2 B PHASE | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | FE000316 | Fence | 641-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | FE000316 | Fence | 641-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | FE000316 | Fence | 641-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | FE000316 | Fence | 641-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | FE000316 | Fence | 641-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | FE000316 | Fence | 641-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | FE000316 | Fence | 641-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | FE000316 | Fence | 641-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000247 | NonLTC | MG-TRANS 2 A PHASE | NonLTC Transformer Readings | Winding Temp Present | 24 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000247 | NonLTC | MG-TRANS 2 A PHASE | NonLTC Transformer Readings | Winding Temp Max | 35 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000247 | NonLTC | MG-TRANS 2 A PHASE | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000247 | NonLTC | MG-TRANS 2 A PHASE | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000247 | NonLTC | MG-TRANS 2 A PHASE | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000247 | NonLTC | MG-TRANS 2 A PHASE | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000247 | NonLTC | MG-TRANS 2 A PHASE | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | FE000316 | Fence | 641-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | FE000316 | Fence | 641-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | FE000316 | Fence | 641-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | FE000316 | Fence | 641-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1179 | BreakerVacuum | WS-1306-1 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1179 | BreakerVacuum | WS-1306-1 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1179 | BreakerVacuum | WS-1306-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1179 | BreakerVacuum | WS-1306-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1179 | BreakerVacuum | WS-1306-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1179 | BreakerVacuum | WS-1306-1 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1179 | BreakerVacuum | WS-1306-1 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1179 | BreakerVacuum | WS-1306-1 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1179 | BreakerVacuum | WS-1306-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1179 | BreakerVacuum | WS-1306-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1179 | BreakerVacuum | WS-1306-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1240 | BreakerVacuum | WS-1308-2 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1240 | BreakerVacuum | WS-1308-2 | VCB Readings | 9 Month Operations | 7 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1187 | Regulator | 596-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1187 | Regulator | 596-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1187 | Regulator | 596-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1187 | Regulator | 596-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1187 | Regulator | 596-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 116029 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1187 | Regulator | 596-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1187 | Regulator | 596-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1187 | Regulator | 596-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1187 | Regulator | 596-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1187 | Regulator | 596-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1187 | Regulator | 596-1 B | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1187 | Regulator | 596-1 B | Regulator Patrol Inspection | Max Tap Position | 1L | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1187 | Regulator | 596-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000246 | NonLTC | MG-TRANS 2 C PHASE | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000246 | NonLTC | MG-TRANS 2 C PHASE | NonLTC Transformer Readings | Oil Temp Max | 34 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000246 | NonLTC | MG-TRANS 2 C PHASE | NonLTC Transformer Readings | Oil Temp Present | 22 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000246 | NonLTC | MG-TRANS 2 C PHASE | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000246 | NonLTC | MG-TRANS 2 C PHASE | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1187 | Regulator | 596-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1187 | Regulator | 596-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1187 | Regulator | 596-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1187 | Regulator | 596-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1187 | Regulator | 596-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1187 | Regulator | 596-1 B | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1187 | Regulator | 596-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1187 | Regulator | 596-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1187 | Regulator | 596-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1187 | Regulator | 596-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R1187 | Regulator | 596-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000246 | NonLTC | MG-TRANS 2 C PHASE | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000246 | NonLTC | MG-TRANS 2 C PHASE | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000246 | NonLTC | MG-TRANS 2 C PHASE | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000246 | NonLTC | MG-TRANS 2 C PHASE | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000246 | NonLTC | MG-TRANS 2 C PHASE | NonLTC Transformer Readings | Winding Temp Max | 34 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000246 | NonLTC | MG-TRANS 2 C PHASE | NonLTC Transformer Readings | Winding Temp Present | 22 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000247 | NonLTC | MG-TRANS 2 A PHASE | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1217 | BreakerVacuum | WS-1332-4 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1217 | BreakerVacuum | WS-1332-4 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | ST000207 | Structure | 736-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | ST000207 | Structure | 736-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | ST000207 | Structure | 736-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | ST000207 | Structure | 736-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | ST000207 | Structure | 736-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | ST000207 | Structure | 736-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000247 | NonLTC | MG-TRANS 2 A PHASE | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000247 | NonLTC | MG-TRANS 2 A PHASE | NonLTC Transformer Readings | Oil Temp Present | 24 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000247 | NonLTC | MG-TRANS 2 A PHASE | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000247 | NonLTC | MG-TRANS 2 A PHASE | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000247 | NonLTC | MG-TRANS 2 A PHASE | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 8.33 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | ST000207 | Structure | 736-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1217 | BreakerVacuum | WS-1332-4 | VCB Readings | Amps B Ø | 66.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1217 | BreakerVacuum | WS-1332-4 | VCB Readings | Amps C Ø | 66.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1217 | BreakerVacuum | WS-1332-4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1217 | BreakerVacuum | WS-1332-4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1217 | BreakerVacuum | WS-1332-4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1217 | BreakerVacuum | WS-1332-4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1217 | BreakerVacuum | WS-1332-4 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000247 | NonLTC | MG-TRANS 2 A PHASE | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000247 | NonLTC | MG-TRANS 2 A PHASE | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000247 | NonLTC | MG-TRANS 2 A PHASE | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000247 | NonLTC | MG-TRANS 2 A PHASE | NonLTC Transformer Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000247 | NonLTC | MG-TRANS 2 A PHASE | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000247 | NonLTC | MG-TRANS 2 A PHASE | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000247 | NonLTC | MG-TRANS 2 A PHASE | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000247 | NonLTC | MG-TRANS 2 A PHASE | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000247 | NonLTC | MG-TRANS 2 A PHASE | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1217 | BreakerVacuum | WS-1332-4 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1217 | BreakerVacuum | WS-1332-4 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1217 | BreakerVacuum | WS-1332-4 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1217 | BreakerVacuum | WS-1332-4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1217 | BreakerVacuum | WS-1332-4 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1217 | BreakerVacuum | WS-1332-4 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1217 | BreakerVacuum | WS-1332-4 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1217 | BreakerVacuum | WS-1332-4 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000247 | NonLTC | MG-TRANS 2 A PHASE | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000247 | NonLTC | MG-TRANS 2 A PHASE | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1217 | BreakerVacuum | WS-1332-4 | VCB Readings | Operations Counter AF | 117 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1217 | BreakerVacuum | WS-1332-4 | VCB Readings | Operations Counter AL | 117 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1217 | BreakerVacuum | WS-1332-4 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | YD000568 | Yard | JT-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | YD000568 | Yard | JT-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | YD000568 | Yard | JT-Yard | Yard Patrol Inspection | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | YD000568 | Yard | JT-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | YD000568 | Yard | JT-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | YD000568 | Yard | JT-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | YD000568 | Yard | JT-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | YD000568 | Yard | JT-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | YD000568 | Yard | JT-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | YD000568 | Yard | JT-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | YD000568 | Yard | JT-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | YD000568 | Yard | JT-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | YD000568 | Yard | JT-Yard | Yard Patrol Inspection | Ambient Temp | 36 | °F |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1199 | BreakerVacuum | WS-1426-3 | VCB Readings | Amps C Ø | 85.0 | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | FE000313 | Fence | 682-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | FE000313 | Fence | 682-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | FE000313 | Fence | 682-Fence | Fence Patrol Inspection | General Comments | ok | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | FE000313 | Fence | 682-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | ST000016 | Structure | 894-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | ST000016 | Structure | 894-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | FE000313 | Fence | 682-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | FE000313 | Fence | 682-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | FE000313 | Fence | 682-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | FE000313 | Fence | 682-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | FE000313 | Fence | 682-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | FE000313 | Fence | 682-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | FE000313 | Fence | 682-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | FE000313 | Fence | 682-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | FE000313 | Fence | 682-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | FE000313 | Fence | 682-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | FE000313 | Fence | 682-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | FE000313 | Fence | 682-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1199 | BreakerVacuum | WS-1426-3 | VCB Readings | Amps B Ø | 85.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1199 | BreakerVacuum | WS-1426-3 | VCB Readings | Amps A Ø | 85.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1199 | BreakerVacuum | WS-1426-3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1199 | BreakerVacuum | WS-1426-3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1199 | BreakerVacuum | WS-1426-3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1199 | BreakerVacuum | WS-1426-3 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1199 | BreakerVacuum | WS-1426-3 | VCB Readings | 9 Month Operations | 4 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Readings | Operations This Read Vac | 4 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Readings | Operations Counter AL | 216 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Readings | Operations Counter AF | 216 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Readings | General Comments | | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Readings | Fault Operations B Ø | 2 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Readings | Fault Operations A Ø | 2 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Readings | Fault Adjusted Amps B Phase V | 5.66 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Readings | Fault Adjusted Amps A Phase V | 5.66 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Readings | Amps C Ø | 55.0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Readings | Amps B Ø | 60.0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Readings | Amps A Ø | 45.0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001579 | BreakerVacuum | 686-0878 | VCB Readings | 9 Month Operations | 5 | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | ST000016 | Structure | 894-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | ST000016 | Structure | 894-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | ST000016 | Structure | 894-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | ST000016 | Structure | 894-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | ST000016 | Structure | 894-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0602 | BreakerAirMagnetic | MG-1322 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | ST000159 | Structure | 418-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | ST000159 | Structure | 418-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | ST000159 | Structure | 418-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | ST000159 | Structure | 418-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | ST000159 | Structure | 418-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | ST000159 | Structure | 418-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | ST000159 | Structure | 418-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | YD000154 | Yard | 418-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | YD000154 | Yard | 418-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | YD000154 | Yard | 418-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | YD000154 | Yard | 418-Yard | Yard Patrol Inspection | General Comments | | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | YD000154 | Yard | 418-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | YD000154 | Yard | 418-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | YD000154 | Yard | 418-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | YD000154 | Yard | 418-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | YD000154 | Yard | 418-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | YD000154 | Yard | 418-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | YD000154 | Yard | 418-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | YD000154 | Yard | 418-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | YD000154 | Yard | 418-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | YD000154 | Yard | 418-Yard | Yard Patrol Inspection | Ambient Temp | 53 | °F |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | FE000156 | Fence | 418-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | FE000156 | Fence | 418-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | FE000156 | Fence | 418-Fence | Fence Patrol Inspection | General Comments | | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | FE000156 | Fence | 418-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | FE000156 | Fence | 418-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000177 | Switchgear | SV-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000177 | Switchgear | SV-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000177 | Switchgear | SV-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000177 | Switchgear | SV-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000177 | Switchgear | SV-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000177 | Switchgear | SV-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1199 | BreakerVacuum | WS-1426-3 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1199 | BreakerVacuum | WS-1426-3 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1199 | BreakerVacuum | WS-1426-3 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1199 | BreakerVacuum | WS-1426-3 | VCB Readings | Operations Counter AL | 85 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1199 | BreakerVacuum | WS-1426-3 | VCB Readings | Operations Counter AF | 85 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000177 | Switchgear | SV-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000177 | Switchgear | SV-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | YD000568 | Yard | JT-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | YD000568 | Yard | JT-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | YD000568 | Yard | JT-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | YD000568 | Yard | JT-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | YD000568 | Yard | JT-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | YD000568 | Yard | JT-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1199 | BreakerVacuum | WS-1426-3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1199 | BreakerVacuum | WS-1426-3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1199 | BreakerVacuum | WS-1426-3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1199 | BreakerVacuum | WS-1426-3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1199 | BreakerVacuum | WS-1426-3 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1199 | BreakerVacuum | WS-1426-3 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1199 | BreakerVacuum | WS-1426-3 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1199 | BreakerVacuum | WS-1426-3 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1199 | BreakerVacuum | WS-1426-3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1199 | BreakerVacuum | WS-1426-3 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1199 | BreakerVacuum | WS-1426-3 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | FE000156 | Fence | 418-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | FE000156 | Fence | 418-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | FE000156 | Fence | 418-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | FE000156 | Fence | 418-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | FE000156 | Fence | 418-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | FE000156 | Fence | 418-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | FE000156 | Fence | 418-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | FE000156 | Fence | 418-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | FE000156 | Fence | 418-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | FE000156 | Fence | 418-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | FE000156 | Fence | 418-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000177 | Switchgear | SV-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000177 | Switchgear | SV-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000177 | Switchgear | SV-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000177 | Switchgear | SV-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000177 | Switchgear | SV-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000177 | Switchgear | SV-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000177 | Switchgear | SV-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000177 | Switchgear | SV-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000177 | Switchgear | SV-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1199 | BreakerVacuum | WS-1426-3 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1199 | BreakerVacuum | WS-1426-3 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000177 | Switchgear | SV-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000177 | Switchgear | SV-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Readings | 9 Month Operations | 0 | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | YD000017 | Yard | 894-Yard | Yard Patrol Inspection | Ambient Temp | 64 | °F |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | FE000022 | Fence | 894-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | FE000022 | Fence | 894-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | FE000022 | Fence | 894-Fence | Fence Patrol Inspection | General Comments | fence and barbed wire rusty, gaps under fence | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | FE000022 | Fence | 894-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | FE000022 | Fence | 894-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | FE000022 | Fence | 894-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | n | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | FE000022 | Fence | 894-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | FE000022 | Fence | 894-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | FE000022 | Fence | 894-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | FE000022 | Fence | 894-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | FE000022 | Fence | 894-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | FE000022 | Fence | 894-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | FE000022 | Fence | 894-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | FE000022 | Fence | 894-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | FE000022 | Fence | 894-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | FE000022 | Fence | 894-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1184 | BreakerVacuum | WS-1322-1 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1184 | BreakerVacuum | WS-1322-1 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1184 | BreakerVacuum | WS-1322-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | YD000593 | Yard | MG-Yard | Yard Patrol Inspection | Ambient Temp | 48 | °F |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | YD000593 | Yard | MG-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | YD000593 | Yard | MG-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | YD000593 | Yard | MG-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | YD000593 | Yard | MG-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | YD000593 | Yard | MG-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | YD000593 | Yard | MG-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | YD000593 | Yard | MG-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | YD000593 | Yard | MG-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | YD000593 | Yard | MG-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | YD000593 | Yard | MG-Yard | Yard Patrol Inspection | General Comments | Demo on goiong in yard | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | YD000593 | Yard | MG-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | YD000593 | Yard | MG-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | YD000593 | Yard | MG-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | YD000593 | Yard | MG-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | YD000593 | Yard | MG-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | YD000593 | Yard | MG-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | YD000593 | Yard | MG-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | YD000593 | Yard | MG-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1184 | BreakerVacuum | WS-1322-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1184 | BreakerVacuum | WS-1322-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1184 | BreakerVacuum | WS-1322-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1184 | BreakerVacuum | WS-1322-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1184 | BreakerVacuum | WS-1322-1 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1184 | BreakerVacuum | WS-1322-1 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1184 | BreakerVacuum | WS-1322-1 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1184 | BreakerVacuum | WS-1322-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1184 | BreakerVacuum | WS-1322-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | BCH001274 | Charger | 771-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | BCH001274 | Charger | 771-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0604 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0604 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0604 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0604 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0604 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0604 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0604 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Maintenance Operations Counter AF | 1878 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | BCH001274 | Charger | 771-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | BCH001274 | Charger | 771-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .2 | amps |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | BCH001274 | Charger | 771-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 52.8 | VDC |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | BCH001274 | Charger | 771-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 52.8 | VDC |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | BCH001274 | Charger | 771-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .500 | millivolts |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | BCH001273 | Charger | 641-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | BCH001273 | Charger | 641-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | BCH001273 | Charger | 641-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | BCH001273 | Charger | 641-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | BCH001273 | Charger | 641-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .4 | amps |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | BCH001273 | Charger | 641-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | BCH001273 | Charger | 641-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | BCH001273 | Charger | 641-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BCH001271 | Charger | 736-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BCH001271 | Charger | 736-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BCH001271 | Charger | 736-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BCH001271 | Charger | 736-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BCH001271 | Charger | 736-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.4 | amps |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BCH001271 | Charger | 736-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BCH001271 | Charger | 736-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BCH001271 | Charger | 736-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | YD000593 | Yard | MG-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | ST000016 | Structure | 894-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | ST000016 | Structure | 894-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | ST000016 | Structure | 894-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | ST000016 | Structure | 894-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | ST000016 | Structure | 894-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | ST000016 | Structure | 894-Structure | Structure Patrol Inspection | General Comments | | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | ST000016 | Structure | 894-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | ST000016 | Structure | 894-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | ST000016 | Structure | 894-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | ST000016 | Structure | 894-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | ST000016 | Structure | 894-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | ST000016 | Structure | 894-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | ST000016 | Structure | 894-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | ST000016 | Structure | 894-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | FE000025 | Fence | 494-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | FE000025 | Fence | 494-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | FE000025 | Fence | 494-Fence | Fence Patrol Inspection | General Comments | | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | FE000025 | Fence | 494-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | FE000025 | Fence | 494-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | FE000025 | Fence | 494-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | FE000025 | Fence | 494-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | FE000025 | Fence | 494-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | FE000025 | Fence | 494-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | FE000025 | Fence | 494-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | FE000025 | Fence | 494-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | FE000025 | Fence | 494-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | FE000025 | Fence | 494-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | FE000025 | Fence | 494-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | FE000025 | Fence | 494-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | FE000025 | Fence | 494-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | YD000017 | Yard | 894-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | YD000017 | Yard | 894-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | YD000017 | Yard | 894-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | YD000017 | Yard | 894-Yard | Yard Patrol Inspection | General Comments | | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | YD000017 | Yard | 894-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | YD000017 | Yard | 894-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | YD000017 | Yard | 894-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | YD000017 | Yard | 894-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Readings | Amps A Ø | 55.0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Readings | Amps B Ø | 55.0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Readings | Amps C Ø | 85.0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Readings | General Comments | | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | YD000017 | Yard | 894-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | YD000017 | Yard | 894-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | YD000017 | Yard | 894-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0604 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Operations Counter AL | 1878 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0604 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0604 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0604 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | YD000017 | Yard | 894-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Readings | Operations Counter AF | 198 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Readings | Operations Counter AL | 198 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | BK001578 | BreakerVacuum | 686-0877 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1206 | BreakerVacuum | WS-1475-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1206 | BreakerVacuum | WS-1475-2 | VCB Readings | Operations Counter AL | 180 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1206 | BreakerVacuum | WS-1475-2 | VCB Readings | Operations Counter AF | 180 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1206 | BreakerVacuum | WS-1475-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1206 | BreakerVacuum | WS-1475-2 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1206 | BreakerVacuum | WS-1475-2 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1206 | BreakerVacuum | WS-1475-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Readings | Operations Counter AL | 255 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Readings | Operations This Read Vac | 1 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1206 | BreakerVacuum | WS-1475-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1206 | BreakerVacuum | WS-1475-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1206 | BreakerVacuum | WS-1475-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1206 | BreakerVacuum | WS-1475-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1206 | BreakerVacuum | WS-1475-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1206 | BreakerVacuum | WS-1475-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1206 | BreakerVacuum | WS-1475-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1206 | BreakerVacuum | WS-1475-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1206 | BreakerVacuum | WS-1475-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1206 | BreakerVacuum | WS-1475-2 | VCB Readings | Amps C Ø | 125.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1206 | BreakerVacuum | WS-1475-2 | VCB Readings | Amps B Ø | 125.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1206 | BreakerVacuum | WS-1475-2 | VCB Readings | Amps A Ø | 125.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1206 | BreakerVacuum | WS-1475-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1206 | BreakerVacuum | WS-1475-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1206 | BreakerVacuum | WS-1475-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1206 | BreakerVacuum | WS-1475-2 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1206 | BreakerVacuum | WS-1475-2 | VCB Readings | 9 Month Operations | 4 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1251 | BreakerVacuum | WS-14KV TR 2 | VCB Readings | 9 Month Operations | 2 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1251 | BreakerVacuum | WS-14KV TR 2 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1251 | BreakerVacuum | WS-14KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1251 | BreakerVacuum | WS-14KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1251 | BreakerVacuum | WS-14KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1251 | BreakerVacuum | WS-14KV TR 2 | VCB Readings | Amps A Ø | 419.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1251 | BreakerVacuum | WS-14KV TR 2 | VCB Readings | Amps B Ø | 408.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1251 | BreakerVacuum | WS-14KV TR 2 | VCB Readings | Amps C Ø | 419.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1251 | BreakerVacuum | WS-14KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1251 | BreakerVacuum | WS-14KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1251 | BreakerVacuum | WS-14KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1251 | BreakerVacuum | WS-14KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1251 | BreakerVacuum | WS-14KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1251 | BreakerVacuum | WS-14KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1251 | BreakerVacuum | WS-14KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1251 | BreakerVacuum | WS-14KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1251 | BreakerVacuum | WS-14KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1251 | BreakerVacuum | WS-14KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1251 | BreakerVacuum | WS-14KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1251 | BreakerVacuum | WS-14KV TR 2 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1251 | BreakerVacuum | WS-14KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1251 | BreakerVacuum | WS-14KV TR 2 | VCB Readings | Operations Counter AF | 106 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1251 | BreakerVacuum | WS-14KV TR 2 | VCB Readings | Operations Counter AL | 106 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1251 | BreakerVacuum | WS-14KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1251 | BreakerVacuum | WS-14KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1251 | BreakerVacuum | WS-14KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0025 | Regulator | 494-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0025 | Regulator | 494-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0025 | Regulator | 494-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0025 | Regulator | 494-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0025 | Regulator | 494-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 45155 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0025 | Regulator | 494-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0025 | Regulator | 494-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0025 | Regulator | 494-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0025 | Regulator | 494-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0025 | Regulator | 494-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0025 | Regulator | 494-1 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1212 | BreakerVacuum | WS-1315-2 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1212 | BreakerVacuum | WS-1315-2 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Readings | General Comments | 1 TC | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Readings | Maintenance Operations | 1 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | YD000141 | Yard | 771-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | YD000141 | Yard | 771-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | YD000141 | Yard | 771-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | LTCMechanism | SV-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | LTCMechanism | SV-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | LTCMechanism | SV-TRANS 2 | LTC Counter Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | CH000167 | ControlHouse | MG-Control House-Distribution | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | CH000167 | ControlHouse | MG-Control House-Distribution | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | CH000167 | ControlHouse | MG-Control House-Distribution | Control House Patrol Inspection | Door Alarms OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | CH000167 | ControlHouse | MG-Control House-Distribution | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | CH000167 | ControlHouse | MG-Control House-Distribution | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | CH000167 | ControlHouse | MG-Control House-Distribution | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | CH000167 | ControlHouse | MG-Control House-Distribution | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | LTCMechanism | SV-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | LTCMechanism | SV-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 92450 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | LTCMechanism | SV-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 92450 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | LTCMechanism | SV-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | LTCMechanism | SV-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | LTCMechanism | SV-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | LTCMechanism | SV-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | LTCMechanism | SV-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 229 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | CH000167 | ControlHouse | MG-Control House-Distribution | Control House Patrol Inspection | Floor Swept? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | CH000167 | ControlHouse | MG-Control House-Distribution | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | CH000167 | ControlHouse | MG-Control House-Distribution | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | CH000167 | ControlHouse | MG-Control House-Distribution | Control House Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | CH000167 | ControlHouse | MG-Control House-Distribution | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | CH000167 | ControlHouse | MG-Control House-Distribution | Control House Patrol Inspection | Panel Lights OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | CH000167 | ControlHouse | MG-Control House-Distribution | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | CH000167 | ControlHouse | MG-Control House-Distribution | Control House Patrol Inspection | Restroom Clean & OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | CH000167 | ControlHouse | MG-Control House-Distribution | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1206 | BreakerVacuum | WS-1475-2 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | LTCMechanism | SV-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | LTCMechanism | SV-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Readings | General Comments | TC | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Readings | Maintenance Operations | 1 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Readings | Operations Counter AF | 262 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Readings | Operations Counter AL | 262 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Readings | Operations This Read Vac | 1 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | LTCMechanism | SV-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | LTCMechanism | SV-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | LTCMechanism | SV-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 187 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | LTCMechanism | SV-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | LTCMechanism | SV-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | LTCMechanism | SV-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | LTCMechanism | SV-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | LTCMechanism | SV-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | LTCMechanism | SV-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 92585 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | LTCMechanism | SV-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 92585 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | LTCMechanism | SV-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | LTCMechanism | SV-TRANS 1 | LTC Counter Readings | General Comments | | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | LTCMechanism | SV-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | LTCMechanism | SV-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | LTCMechanism | SV-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | LTCMechanism | SV-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Readings | Operations Counter AF | 255 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | WB0157 | BreakerVacuum | 736-1912 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | LTCMechanism | SV-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | CH000167 | ControlHouse | MG-Control House-Distribution | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | CH000167 | ControlHouse | MG-Control House-Distribution | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | CH000167 | ControlHouse | MG-Control House-Distribution | Control House Patrol Inspection | Trash Emptied? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | CH000167 | ControlHouse | MG-Control House-Distribution | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0025 | Regulator | 494-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0025 | Regulator | 494-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0025 | Regulator | 494-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0025 | Regulator | 494-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0025 | Regulator | 494-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | YD000155 | Yard | 815-Yard | Yard Patrol Inspection | Yard Lights Working? | n | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | YD000155 | Yard | 815-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | YD000155 | Yard | 815-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | YD000155 | Yard | 815-Yard | Yard Patrol Inspection | General Comments | needs yard light | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | YD000155 | Yard | 815-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | YD000155 | Yard | 815-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | YD000155 | Yard | 815-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | YD000155 | Yard | 815-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | YD000155 | Yard | 815-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | YD000155 | Yard | 815-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | YD000155 | Yard | 815-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | YD000155 | Yard | 815-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | YD000155 | Yard | 815-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | YD000155 | Yard | 815-Yard | Yard Patrol Inspection | Ambient Temp | 59 | °F |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | FE000158 | Fence | 815-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1329 | BreakerVacuum | JT-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1329 | BreakerVacuum | JT-12KV TR 1 | VCB Readings | Operations Counter AF | 150 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1329 | BreakerVacuum | JT-12KV TR 1 | VCB Readings | Operations Counter AL | 150 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1329 | BreakerVacuum | JT-12KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1329 | BreakerVacuum | JT-12KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1329 | BreakerVacuum | JT-12KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | FE000158 | Fence | 815-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | FE000158 | Fence | 815-Fence | Fence Patrol Inspection | General Comments | | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | FE000158 | Fence | 815-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | FE000158 | Fence | 815-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | FE000158 | Fence | 815-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | FE000158 | Fence | 815-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | FE000158 | Fence | 815-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | FE000158 | Fence | 815-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | FE000158 | Fence | 815-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | FE000158 | Fence | 815-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | FE000158 | Fence | 815-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | FE000158 | Fence | 815-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | FE000158 | Fence | 815-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | FE000158 | Fence | 815-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0602 | BreakerAirMagnetic | MG-1322 | AMCB Readings | 9 Months Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0602 | BreakerAirMagnetic | MG-1322 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0602 | BreakerAirMagnetic | MG-1322 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0602 | BreakerAirMagnetic | MG-1322 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0602 | BreakerAirMagnetic | MG-1322 | AMCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0602 | BreakerAirMagnetic | MG-1322 | AMCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0602 | BreakerAirMagnetic | MG-1322 | AMCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0602 | BreakerAirMagnetic | MG-1322 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0602 | BreakerAirMagnetic | MG-1322 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0602 | BreakerAirMagnetic | MG-1322 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0602 | BreakerAirMagnetic | MG-1322 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0602 | BreakerAirMagnetic | MG-1322 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0602 | BreakerAirMagnetic | MG-1322 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0602 | BreakerAirMagnetic | MG-1322 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0602 | BreakerAirMagnetic | MG-1322 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0602 | BreakerAirMagnetic | MG-1322 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0602 | BreakerAirMagnetic | MG-1322 | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0602 | BreakerAirMagnetic | MG-1322 | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0602 | BreakerAirMagnetic | MG-1322 | AMCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0602 | BreakerAirMagnetic | MG-1322 | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0602 | BreakerAirMagnetic | MG-1322 | AMCB Readings | Operations Counter AF | 318 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0602 | BreakerAirMagnetic | MG-1322 | AMCB Readings | Operations Counter AL | 318 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0602 | BreakerAirMagnetic | MG-1322 | AMCB Readings | Operations This Read AM | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0602 | BreakerAirMagnetic | MG-1322 | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0602 | BreakerAirMagnetic | MG-1322 | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | ST000159 | Structure | 418-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | ST000159 | Structure | 418-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | ST000159 | Structure | 418-Structure | Structure Patrol Inspection | General Comments | | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | ST000159 | Structure | 418-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | ST000159 | Structure | 418-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | ST000159 | Structure | 418-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | ST000159 | Structure | 418-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | ST000159 | Structure | 418-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | ST000159 | Structure | 418-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | ST000159 | Structure | 418-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | ST000159 | Structure | 418-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | ST000159 | Structure | 418-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | ST000159 | Structure | 418-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | ST000159 | Structure | 418-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | ST000159 | Structure | 418-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | FE000158 | Fence | 815-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0025 | Regulator | 494-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0025 | Regulator | 494-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0025 | Regulator | 494-1 A | Regulator Patrol Inspection | General Comments | | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0025 | Regulator | 494-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Readings | Amps C Ø | 77.0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Readings | Amps B Ø | 97.0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Readings | Amps A Ø | 86.0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | K0159 | BreakerVacuum | 405-1650 | VCB Readings | 9 Month Operations | 8 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000170 | Switchgear | MG-14KV Sec A Swgr | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000170 | Switchgear | MG-14KV Sec A Swgr | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000170 | Switchgear | MG-14KV Sec A Swgr | Switchgear Patrol Inspection | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1329 | BreakerVacuum | JT-12KV TR 1 | VCB Readings | 9 Month Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000170 | Switchgear | MG-14KV Sec A Swgr | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000170 | Switchgear | MG-14KV Sec A Swgr | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000170 | Switchgear | MG-14KV Sec A Swgr | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000171 | Switchgear | MG-14KV Sec 5 Swgr | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000171 | Switchgear | MG-14KV Sec 5 Swgr | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000171 | Switchgear | MG-14KV Sec 5 Swgr | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000171 | Switchgear | MG-14KV Sec 5 Swgr | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1329 | BreakerVacuum | JT-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1329 | BreakerVacuum | JT-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000171 | Switchgear | MG-14KV Sec 5 Swgr | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000171 | Switchgear | MG-14KV Sec 5 Swgr | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000171 | Switchgear | MG-14KV Sec 5 Swgr | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000171 | Switchgear | MG-14KV Sec 5 Swgr | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000171 | Switchgear | MG-14KV Sec 5 Swgr | Switchgear Patrol Inspection | Follow-up Action Required? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000171 | Switchgear | MG-14KV Sec 5 Swgr | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | ST000572 | Structure | JT-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | ST000572 | Structure | JT-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | ST000572 | Structure | JT-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | ST000572 | Structure | JT-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | ST000572 | Structure | JT-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | ST000572 | Structure | JT-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | ST000572 | Structure | JT-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0025 | Regulator | 494-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0025 | Regulator | 494-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0025 | Regulator | 494-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0025 | Regulator | 494-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000171 | Switchgear | MG-14KV Sec 5 Swgr | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000171 | Switchgear | MG-14KV Sec 5 Swgr | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000171 | Switchgear | MG-14KV Sec 5 Swgr | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000171 | Switchgear | MG-14KV Sec 5 Swgr | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000171 | Switchgear | MG-14KV Sec 5 Swgr | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000171 | Switchgear | MG-14KV Sec 5 Swgr | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000171 | Switchgear | MG-14KV Sec 5 Swgr | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000171 | Switchgear | MG-14KV Sec 5 Swgr | Switchgear Patrol Inspection | Heaters (All) Functioning? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000171 | Switchgear | MG-14KV Sec 5 Swgr | Switchgear Patrol Inspection | General Comments | Aisle heater not working | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1329 | BreakerVacuum | JT-12KV TR 1 | VCB Patrol Inspection | General Comments | OK | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1329 | BreakerVacuum | JT-12KV TR 1 | VCB Readings | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1329 | BreakerVacuum | JT-12KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1329 | BreakerVacuum | JT-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1329 | BreakerVacuum | JT-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1329 | BreakerVacuum | JT-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1329 | BreakerVacuum | JT-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1329 | BreakerVacuum | JT-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1329 | BreakerVacuum | JT-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1329 | BreakerVacuum | JT-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1329 | BreakerVacuum | JT-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1329 | BreakerVacuum | JT-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1329 | BreakerVacuum | JT-12KV TR 1 | VCB Readings | Amps C Ø | 295.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1329 | BreakerVacuum | JT-12KV TR 1 | VCB Readings | Amps B Ø | 259.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1329 | BreakerVacuum | JT-12KV TR 1 | VCB Readings | Amps A Ø | 202.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1329 | BreakerVacuum | JT-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1329 | BreakerVacuum | JT-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | ST000572 | Structure | JT-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | ST000572 | Structure | JT-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | ST000572 | Structure | JT-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | ST000572 | Structure | JT-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | ST000572 | Structure | JT-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | ST000572 | Structure | JT-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | ST000572 | Structure | JT-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | ST000572 | Structure | JT-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | ST000572 | Structure | JT-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | ST000572 | Structure | JT-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | ST000572 | Structure | JT-Structure | Structure Patrol Inspection | General Comments | | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1448 | Regulator | 771-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1448 | Regulator | 771-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1448 | Regulator | 771-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1528 | Regulator | 894-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1528 | Regulator | 894-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1528 | Regulator | 894-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1528 | Regulator | 894-1 C | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1448 | Regulator | 771-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1332 | BreakerVacuum | JT-1125 | VCB Readings | 9 Month Operations | 1 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1332 | BreakerVacuum | JT-1125 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1332 | BreakerVacuum | JT-1125 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1332 | BreakerVacuum | JT-1125 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1332 | BreakerVacuum | JT-1125 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1332 | BreakerVacuum | JT-1125 | VCB Readings | Amps A Ø | 42.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1332 | BreakerVacuum | JT-1125 | VCB Readings | Amps B Ø | 23.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1332 | BreakerVacuum | JT-1125 | VCB Readings | Amps C Ø | 64.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1332 | BreakerVacuum | JT-1125 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1332 | BreakerVacuum | JT-1125 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1332 | BreakerVacuum | JT-1125 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1332 | BreakerVacuum | JT-1125 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1332 | BreakerVacuum | JT-1125 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1332 | BreakerVacuum | JT-1125 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1332 | BreakerVacuum | JT-1125 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1332 | BreakerVacuum | JT-1125 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1332 | BreakerVacuum | JT-1125 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1332 | BreakerVacuum | JT-1125 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1332 | BreakerVacuum | JT-1125 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1332 | BreakerVacuum | JT-1125 | VCB Readings | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1332 | BreakerVacuum | JT-1125 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1185 | BreakerVacuum | WS-1324-1 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1332 | BreakerVacuum | JT-1125 | VCB Readings | Operations Counter AF | 241 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1332 | BreakerVacuum | JT-1125 | VCB Readings | Operations Counter AL | 241 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1332 | BreakerVacuum | JT-1125 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1332 | BreakerVacuum | JT-1125 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1332 | BreakerVacuum | JT-1125 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1185 | BreakerVacuum | WS-1324-1 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1185 | BreakerVacuum | WS-1324-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1185 | BreakerVacuum | WS-1324-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1185 | BreakerVacuum | WS-1324-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1185 | BreakerVacuum | WS-1324-1 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1185 | BreakerVacuum | WS-1324-1 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1185 | BreakerVacuum | WS-1324-1 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1185 | BreakerVacuum | WS-1324-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1185 | BreakerVacuum | WS-1324-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1185 | BreakerVacuum | WS-1324-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1185 | BreakerVacuum | WS-1324-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1185 | BreakerVacuum | WS-1324-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1185 | BreakerVacuum | WS-1324-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1185 | BreakerVacuum | WS-1324-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1185 | BreakerVacuum | WS-1324-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1185 | BreakerVacuum | WS-1324-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1185 | BreakerVacuum | WS-1324-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1185 | BreakerVacuum | WS-1324-1 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0116 | NonLTC | MG-TRANS 1 B PHASE | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0116 | NonLTC | MG-TRANS 1 B PHASE | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0116 | NonLTC | MG-TRANS 1 B PHASE | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0116 | NonLTC | MG-TRANS 1 B PHASE | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0116 | NonLTC | MG-TRANS 1 B PHASE | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1528 | Regulator | 894-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1528 | Regulator | 894-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1528 | Regulator | 894-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1528 | Regulator | 894-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1528 | Regulator | 894-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1527 | Regulator | 894-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1527 | Regulator | 894-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1527 | Regulator | 894-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1527 | Regulator | 894-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 60998 | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1527 | Regulator | 894-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1527 | Regulator | 894-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1527 | Regulator | 894-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1527 | Regulator | 894-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1527 | Regulator | 894-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1527 | Regulator | 894-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1527 | Regulator | 894-1 B | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1527 | Regulator | 894-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1527 | Regulator | 894-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1527 | Regulator | 894-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1527 | Regulator | 894-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1527 | Regulator | 894-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1527 | Regulator | 894-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R0999 | Regulator | 596-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 74368 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R0999 | Regulator | 596-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R0999 | Regulator | 596-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R0999 | Regulator | 596-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R0999 | Regulator | 596-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R0999 | Regulator | 596-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R0999 | Regulator | 596-1 C | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R0999 | Regulator | 596-1 C | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R0999 | Regulator | 596-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R0999 | Regulator | 596-1 C | Regulator Patrol Inspection | General Comments | | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R0999 | Regulator | 596-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R0999 | Regulator | 596-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R0999 | Regulator | 596-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LTCM000099 | LTCMechanism | JT-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LTCM000099 | LTCMechanism | JT-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 32 | °C |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LTCM000099 | LTCMechanism | JT-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 12 | °C |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LTCM000099 | LTCMechanism | JT-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 217 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LTCM000099 | LTCMechanism | JT-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LTCM000099 | LTCMechanism | JT-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LTCM000099 | LTCMechanism | JT-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LTCM000099 | LTCMechanism | JT-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1457 | Regulator | 006-5 A | Regulator Patrol Inspection | Regulator As Left Counter | 23860 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1457 | Regulator | 006-5 A | Regulator Patrol Inspection | Reg Output Voltage Level | 122.1 | volts |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1457 | Regulator | 006-5 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1457 | Regulator | 006-5 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1457 | Regulator | 006-5 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1457 | Regulator | 006-5 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1457 | Regulator | 006-5 A | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1457 | Regulator | 006-5 A | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1457 | Regulator | 006-5 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1457 | Regulator | 006-5 A | Regulator Patrol Inspection | General Comments | | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1457 | Regulator | 006-5 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1457 | Regulator | 006-5 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1457 | Regulator | 006-5 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1457 | Regulator | 006-5 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1457 | Regulator | 006-5 A | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1457 | Regulator | 006-5 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1457 | Regulator | 006-5 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1457 | Regulator | 006-5 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1457 | Regulator | 006-5 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1448 | Regulator | 771-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1448 | Regulator | 771-1 B | Regulator Patrol Inspection | Current Tap Position | 10L | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1448 | Regulator | 771-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1448 | Regulator | 771-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1528 | Regulator | 894-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1528 | Regulator | 894-1 C | Regulator Patrol Inspection | General Comments | | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1528 | Regulator | 894-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1528 | Regulator | 894-1 C | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1528 | Regulator | 894-1 C | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1528 | Regulator | 894-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1528 | Regulator | 894-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1448 | Regulator | 771-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1448 | Regulator | 771-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1528 | Regulator | 894-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1528 | Regulator | 894-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1528 | Regulator | 894-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.0 | volts |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1528 | Regulator | 894-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 52395 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1528 | Regulator | 894-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1448 | Regulator | 771-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1448 | Regulator | 771-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1528 | Regulator | 894-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1528 | Regulator | 894-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R0999 | Regulator | 596-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R0999 | Regulator | 596-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R0999 | Regulator | 596-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1448 | Regulator | 771-1 B | Regulator Patrol Inspection | Max Tap Position | 7L | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1448 | Regulator | 771-1 B | Regulator Patrol Inspection | Min Tap Position | 16L | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1448 | Regulator | 771-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1448 | Regulator | 771-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1448 | Regulator | 771-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1448 | Regulator | 771-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1448 | Regulator | 771-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1448 | Regulator | 771-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 68483 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1448 | Regulator | 771-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1448 | Regulator | 771-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | R1448 | Regulator | 771-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R0999 | Regulator | 596-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R0999 | Regulator | 596-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R0999 | Regulator | 596-1 C | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R0999 | Regulator | 596-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1457 | Regulator | 006-5 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000024 | Switchgear | JT-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000024 | Switchgear | JT-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000024 | Switchgear | JT-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000024 | Switchgear | JT-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | CH000149 | ControlHouse | JT-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | CH000149 | ControlHouse | JT-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | CH000149 | ControlHouse | JT-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | CH000149 | ControlHouse | JT-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | CH000149 | ControlHouse | JT-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | CH000149 | ControlHouse | JT-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | CH000149 | ControlHouse | JT-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | CH000149 | ControlHouse | JT-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | CH000149 | ControlHouse | JT-Control House | Control House Patrol Inspection | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | CH000149 | ControlHouse | JT-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | CH000149 | ControlHouse | JT-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | CH000149 | ControlHouse | JT-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | CH000149 | ControlHouse | JT-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | CH000149 | ControlHouse | JT-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | CH000149 | ControlHouse | JT-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1185 | BreakerVacuum | WS-1324-1 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1185 | BreakerVacuum | WS-1324-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1185 | BreakerVacuum | WS-1324-1 | VCB Readings | Operations Counter AF | 149 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1185 | BreakerVacuum | WS-1324-1 | VCB Readings | Operations Counter AL | 149 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1185 | BreakerVacuum | WS-1324-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1185 | BreakerVacuum | WS-1324-1 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1185 | BreakerVacuum | WS-1324-1 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0116 | NonLTC | MG-TRANS 1 B PHASE | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0116 | NonLTC | MG-TRANS 1 B PHASE | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0116 | NonLTC | MG-TRANS 1 B PHASE | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0116 | NonLTC | MG-TRANS 1 B PHASE | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 445.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0116 | NonLTC | MG-TRANS 1 B PHASE | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 460.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1191 | BreakerVacuum | WS-1332-3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1191 | BreakerVacuum | WS-1332-3 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1191 | BreakerVacuum | WS-1332-3 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1191 | BreakerVacuum | WS-1332-3 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1191 | BreakerVacuum | WS-1332-3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1191 | BreakerVacuum | WS-1332-3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1191 | BreakerVacuum | WS-1332-3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1191 | BreakerVacuum | WS-1332-3 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1191 | BreakerVacuum | WS-1332-3 | VCB Readings | 9 Month Operations | 2 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1398 | Regulator | 439-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1398 | Regulator | 439-1 C | Regulator Patrol Inspection | General Comments | | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1398 | Regulator | 439-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1398 | Regulator | 439-1 C | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1398 | Regulator | 439-1 C | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1398 | Regulator | 439-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1398 | Regulator | 439-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1398 | Regulator | 439-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1398 | Regulator | 439-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1398 | Regulator | 439-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.3 | volts |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | CH000149 | ControlHouse | JT-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | CH000149 | ControlHouse | JT-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | CH000149 | ControlHouse | JT-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | CH000149 | ControlHouse | JT-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | CH000149 | ControlHouse | JT-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | CH000149 | ControlHouse | JT-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0116 | NonLTC | MG-TRANS 1 B PHASE | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0116 | NonLTC | MG-TRANS 1 B PHASE | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0116 | NonLTC | MG-TRANS 1 B PHASE | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1398 | Regulator | 439-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 36135 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1398 | Regulator | 439-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1398 | Regulator | 439-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1398 | Regulator | 439-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | R1398 | Regulator | 439-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0116 | NonLTC | MG-TRANS 1 B PHASE | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0116 | NonLTC | MG-TRANS 1 B PHASE | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0116 | NonLTC | MG-TRANS 1 B PHASE | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0116 | NonLTC | MG-TRANS 1 B PHASE | NonLTC Transformer Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0116 | NonLTC | MG-TRANS 1 B PHASE | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0116 | NonLTC | MG-TRANS 1 B PHASE | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | CH000149 | ControlHouse | JT-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1527 | Regulator | 894-1 B | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1527 | Regulator | 894-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1527 | Regulator | 894-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1527 | Regulator | 894-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1527 | Regulator | 894-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | R1527 | Regulator | 894-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0321 | RecloserElectronic | 894-0577 | Recloser Electronic Patrol Inspection | Amps A Ø | 51.0 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1205 | Regulator | 212-5 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1205 | Regulator | 212-5 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1205 | Regulator | 212-5 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1205 | Regulator | 212-5 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1205 | Regulator | 212-5 A | Regulator Patrol Inspection | Regulator As Left Counter | 65793 | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1205 | Regulator | 212-5 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1205 | Regulator | 212-5 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1205 | Regulator | 212-5 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1205 | Regulator | 212-5 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1205 | Regulator | 212-5 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1205 | Regulator | 212-5 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1205 | Regulator | 212-5 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1205 | Regulator | 212-5 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1205 | Regulator | 212-5 A | Regulator Patrol Inspection | General Comments | ok | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1205 | Regulator | 212-5 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1205 | Regulator | 212-5 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1205 | Regulator | 212-5 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1205 | Regulator | 212-5 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1205 | Regulator | 212-5 A | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1205 | Regulator | 212-5 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1205 | Regulator | 212-5 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1205 | Regulator | 212-5 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1205 | Regulator | 212-5 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 13:36 | Distribution | Simmons Quarterly Inspection | R1205 | Regulator | 212-5 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1191 | BreakerVacuum | WS-1332-3 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1191 | BreakerVacuum | WS-1332-3 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1191 | BreakerVacuum | WS-1332-3 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1191 | BreakerVacuum | WS-1332-3 | VCB Readings | Operations Counter AL | 63 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1191 | BreakerVacuum | WS-1332-3 | VCB Readings | Operations Counter AF | 63 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1191 | BreakerVacuum | WS-1332-3 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1191 | BreakerVacuum | WS-1332-3 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1191 | BreakerVacuum | WS-1332-3 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1191 | BreakerVacuum | WS-1332-3 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000024 | Switchgear | JT-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000024 | Switchgear | JT-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000024 | Switchgear | JT-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000024 | Switchgear | JT-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000024 | Switchgear | JT-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000024 | Switchgear | JT-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000024 | Switchgear | JT-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000024 | Switchgear | JT-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000024 | Switchgear | JT-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000024 | Switchgear | JT-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000024 | Switchgear | JT-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000024 | Switchgear | JT-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000024 | Switchgear | JT-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000024 | Switchgear | JT-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000024 | Switchgear | JT-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | WithLTC | 497-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0321 | RecloserElectronic | 894-0577 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0321 | RecloserElectronic | 894-0577 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0321 | RecloserElectronic | 894-0577 | Recloser Electronic Patrol Inspection | Operations Counter | 112 | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0321 | RecloserElectronic | 894-0577 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0321 | RecloserElectronic | 894-0577 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0321 | RecloserElectronic | 894-0577 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0321 | RecloserElectronic | 894-0577 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0321 | RecloserElectronic | 894-0577 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0321 | RecloserElectronic | 894-0577 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1191 | BreakerVacuum | WS-1332-3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1191 | BreakerVacuum | WS-1332-3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1191 | BreakerVacuum | WS-1332-3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1191 | BreakerVacuum | WS-1332-3 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1191 | BreakerVacuum | WS-1332-3 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1191 | BreakerVacuum | WS-1332-3 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0321 | RecloserElectronic | 894-0577 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0321 | RecloserElectronic | 894-0577 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0321 | RecloserElectronic | 894-0577 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0321 | RecloserElectronic | 894-0577 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0321 | RecloserElectronic | 894-0577 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0321 | RecloserElectronic | 894-0577 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0321 | RecloserElectronic | 894-0577 | Recloser Electronic Patrol Inspection | Amps C Ø | 63.0 | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0321 | RecloserElectronic | 894-0577 | Recloser Electronic Patrol Inspection | Amps B Ø | 53.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1191 | BreakerVacuum | WS-1332-3 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1191 | BreakerVacuum | WS-1332-3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | BAT001355 | Battery | 641-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | BAT001355 | Battery | 641-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 28.2 | VDC |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | BAT001355 | Battery | 641-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.9 | VDC |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | BAT001355 | Battery | 641-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | BAT001355 | Battery | 641-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | BAT001356 | Battery | 771-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | BAT001356 | Battery | 771-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 45 | °F |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | BAT001356 | Battery | 771-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | BAT001356 | Battery | 771-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | BAT001356 | Battery | 771-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | BAT001356 | Battery | 771-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | BAT001356 | Battery | 771-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | BAT001356 | Battery | 771-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | BAT001356 | Battery | 771-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 28.0 | VDC |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | BAT001356 | Battery | 771-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.9 | VDC |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | BAT001356 | Battery | 771-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | BAT001356 | Battery | 771-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1231 | BreakerVacuum | WS-SEC TIE 1-3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1231 | BreakerVacuum | WS-SEC TIE 1-3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1231 | BreakerVacuum | WS-SEC TIE 1-3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1231 | BreakerVacuum | WS-SEC TIE 1-3 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1231 | BreakerVacuum | WS-SEC TIE 1-3 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0521 | BreakerVacuum | JT-1122 | VCB Readings | 9 Month Operations | 9 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0521 | BreakerVacuum | JT-1122 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0521 | BreakerVacuum | JT-1122 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0521 | BreakerVacuum | JT-1122 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0521 | BreakerVacuum | JT-1122 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0521 | BreakerVacuum | JT-1122 | VCB Readings | Amps A Ø | 87.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0521 | BreakerVacuum | JT-1122 | VCB Readings | Amps B Ø | 85.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0521 | BreakerVacuum | JT-1122 | VCB Readings | Amps C Ø | 90.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0521 | BreakerVacuum | JT-1122 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0521 | BreakerVacuum | JT-1122 | VCB Readings | Fault Adjusted Amps A Phase V | 33.54 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0604 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Readings | General Comments | | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Readings | LTC Totalizer Reading | 5639.04 | kw |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Readings | Oil Temp Max | 47 | °C |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0604 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0604 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0604 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0604 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0604 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0604 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0604 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0604 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0604 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0604 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0604 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0604 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | 9 Months Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0604 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0521 | BreakerVacuum | JT-1122 | VCB Readings | Fault Adjusted Amps B Phase V | 33.54 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0521 | BreakerVacuum | JT-1122 | VCB Readings | Fault Adjusted Amps C Phase V | 33.54 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0521 | BreakerVacuum | JT-1122 | VCB Readings | Fault Operations A Ø | 3 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0521 | BreakerVacuum | JT-1122 | VCB Readings | Fault Operations B Ø | 3 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0521 | BreakerVacuum | JT-1122 | VCB Readings | Fault Operations C Ø | 3 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0521 | BreakerVacuum | JT-1122 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0521 | BreakerVacuum | JT-1122 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1184 | BreakerVacuum | WS-1322-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1184 | BreakerVacuum | WS-1322-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1184 | BreakerVacuum | WS-1322-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1184 | BreakerVacuum | WS-1322-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0608 | BreakerAirMagnetic | MG-1330 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0608 | BreakerAirMagnetic | MG-1330 | AMCB Readings | 9 Months Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0608 | BreakerAirMagnetic | MG-1330 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0608 | BreakerAirMagnetic | MG-1330 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0608 | BreakerAirMagnetic | MG-1330 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0608 | BreakerAirMagnetic | MG-1330 | AMCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0608 | BreakerAirMagnetic | MG-1330 | AMCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0608 | BreakerAirMagnetic | MG-1330 | AMCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0608 | BreakerAirMagnetic | MG-1330 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0608 | BreakerAirMagnetic | MG-1330 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0608 | BreakerAirMagnetic | MG-1330 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0608 | BreakerAirMagnetic | MG-1330 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0608 | BreakerAirMagnetic | MG-1330 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0608 | BreakerAirMagnetic | MG-1330 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0608 | BreakerAirMagnetic | MG-1330 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0608 | BreakerAirMagnetic | MG-1330 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1184 | BreakerVacuum | WS-1322-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1184 | BreakerVacuum | WS-1322-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1184 | BreakerVacuum | WS-1322-1 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1184 | BreakerVacuum | WS-1322-1 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1184 | BreakerVacuum | WS-1322-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1184 | BreakerVacuum | WS-1322-1 | VCB Readings | Operations Counter AF | 70 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1184 | BreakerVacuum | WS-1322-1 | VCB Readings | Operations Counter AL | 70 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1184 | BreakerVacuum | WS-1322-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1184 | BreakerVacuum | WS-1322-1 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1184 | BreakerVacuum | WS-1322-1 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1231 | BreakerVacuum | WS-SEC TIE 1-3 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1231 | BreakerVacuum | WS-SEC TIE 1-3 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1231 | BreakerVacuum | WS-SEC TIE 1-3 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1231 | BreakerVacuum | WS-SEC TIE 1-3 | VCB Readings | Operations Counter AL | 151 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1231 | BreakerVacuum | WS-SEC TIE 1-3 | VCB Readings | Operations Counter AF | 151 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1231 | BreakerVacuum | WS-SEC TIE 1-3 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1231 | BreakerVacuum | WS-SEC TIE 1-3 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1231 | BreakerVacuum | WS-SEC TIE 1-3 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1231 | BreakerVacuum | WS-SEC TIE 1-3 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1231 | BreakerVacuum | WS-SEC TIE 1-3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | BAT001355 | Battery | 641-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | BAT001355 | Battery | 641-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | BAT001355 | Battery | 641-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | BAT001355 | Battery | 641-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | BAT001355 | Battery | 641-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | BAT001355 | Battery | 641-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 52 | °F |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | BAT001355 | Battery | 641-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | BAT001354 | Battery | 571-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | BAT001354 | Battery | 571-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | BAT001354 | Battery | 571-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.9 | VDC |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | BAT001354 | Battery | 571-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 28.1 | VDC |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | BAT001354 | Battery | 571-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | BAT001354 | Battery | 571-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | BAT001354 | Battery | 571-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | BAT001354 | Battery | 571-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | BAT001354 | Battery | 571-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | BAT001354 | Battery | 571-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | BAT001354 | Battery | 571-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 46 | °F |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | BAT001354 | Battery | 571-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0608 | BreakerAirMagnetic | MG-1330 | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0608 | BreakerAirMagnetic | MG-1330 | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0608 | BreakerAirMagnetic | MG-1330 | AMCB Readings | Operations This Read AM | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0608 | BreakerAirMagnetic | MG-1330 | AMCB Readings | Operations Counter AL | 476 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0608 | BreakerAirMagnetic | MG-1330 | AMCB Readings | Operations Counter AF | 476 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0608 | BreakerAirMagnetic | MG-1330 | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0608 | BreakerAirMagnetic | MG-1330 | AMCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0608 | BreakerAirMagnetic | MG-1330 | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0608 | BreakerAirMagnetic | MG-1330 | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0608 | BreakerAirMagnetic | MG-1330 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1231 | BreakerVacuum | WS-SEC TIE 1-3 | VCB Readings | Amps A Ø | 96.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1231 | BreakerVacuum | WS-SEC TIE 1-3 | VCB Readings | Amps B Ø | 103.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1231 | BreakerVacuum | WS-SEC TIE 1-3 | VCB Readings | Amps C Ø | 103.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1231 | BreakerVacuum | WS-SEC TIE 1-3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1231 | BreakerVacuum | WS-SEC TIE 1-3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1231 | BreakerVacuum | WS-SEC TIE 1-3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | BCH001274 | Charger | 771-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1231 | BreakerVacuum | WS-SEC TIE 1-3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1231 | BreakerVacuum | WS-SEC TIE 1-3 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1231 | BreakerVacuum | WS-SEC TIE 1-3 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1231 | BreakerVacuum | WS-SEC TIE 1-3 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1231 | BreakerVacuum | WS-SEC TIE 1-3 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1550 | psi |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | ST000199 | Structure | 405-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | ST000199 | Structure | 405-Structure | Structure Patrol Inspection | General Comments | no spare fuses | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | ST000199 | Structure | 405-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | ST000199 | Structure | 405-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | ST000199 | Structure | 405-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | ST000199 | Structure | 405-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | ST000199 | Structure | 405-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | ST000199 | Structure | 405-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | ST000199 | Structure | 405-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | ST000199 | Structure | 405-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | ST000199 | Structure | 405-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | ST000199 | Structure | 405-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | ST000199 | Structure | 405-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | ST000199 | Structure | 405-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 39 | °C |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 23 | °C |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R0999 | Regulator | 596-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R0999 | Regulator | 596-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LTCM000099 | LTCMechanism | JT-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R0999 | Regulator | 596-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | R0999 | Regulator | 596-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LTCM000099 | LTCMechanism | JT-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LTCM000099 | LTCMechanism | JT-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LTCM000099 | LTCMechanism | JT-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LTCM000099 | LTCMechanism | JT-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 10235 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LTCM000099 | LTCMechanism | JT-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 10235 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LTCM000099 | LTCMechanism | JT-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LTCM000099 | LTCMechanism | JT-TRANS 2 | LTC Counter Readings | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LTCM000099 | LTCMechanism | JT-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LTCM000099 | LTCMechanism | JT-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1457 | Regulator | 006-5 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1457 | Regulator | 006-5 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | R1457 | Regulator | 006-5 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0023 | Regulator | 494-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0023 | Regulator | 494-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0023 | Regulator | 494-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0023 | Regulator | 494-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0023 | Regulator | 494-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0023 | Regulator | 494-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0023 | Regulator | 494-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0023 | Regulator | 494-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0023 | Regulator | 494-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0023 | Regulator | 494-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0023 | Regulator | 494-1 C | Regulator Patrol Inspection | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 24 | °C |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 49 | °C |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 23 | °C |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 49 | °C |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 23 | °C |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 39 | °C |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0521 | BreakerVacuum | JT-1122 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0521 | BreakerVacuum | JT-1122 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0521 | BreakerVacuum | JT-1122 | VCB Readings | General Comments | ABC Phase IOC | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0521 | BreakerVacuum | JT-1122 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0521 | BreakerVacuum | JT-1122 | VCB Readings | Operations Counter AF | 442 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0521 | BreakerVacuum | JT-1122 | VCB Readings | Operations Counter AL | 442 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0521 | BreakerVacuum | JT-1122 | VCB Readings | Operations This Read Vac | 9 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0521 | BreakerVacuum | JT-1122 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0521 | BreakerVacuum | JT-1122 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | ST000199 | Structure | 405-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | ST000199 | Structure | 405-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | ST000199 | Structure | 405-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | ST000199 | Structure | 405-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | ST000199 | Structure | 405-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | ST000199 | Structure | 405-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | ST000199 | Structure | 405-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | ST000199 | Structure | 405-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Readings | Totalizer Meter Reading | .5874 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | WithLTC | 467-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BAT001359 | Battery | 736-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BAT001359 | Battery | 736-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 47 | °F |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BAT001359 | Battery | 736-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BAT001359 | Battery | 736-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BAT001359 | Battery | 736-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BAT001359 | Battery | 736-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BAT001359 | Battery | 736-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BAT001359 | Battery | 736-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BAT001359 | Battery | 736-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 28.0 | VDC |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BAT001359 | Battery | 736-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.7 | VDC |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0322 | RecloserElectronic | 894-0578 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0322 | RecloserElectronic | 894-0578 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0322 | RecloserElectronic | 894-0578 | Recloser Electronic Patrol Inspection | Operations Counter | 115 | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0322 | RecloserElectronic | 894-0578 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0322 | RecloserElectronic | 894-0578 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0322 | RecloserElectronic | 894-0578 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | TX000243 | WithLTC | JT-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0023 | Regulator | 494-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0023 | Regulator | 494-1 C | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0023 | Regulator | 494-1 C | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0023 | Regulator | 494-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0023 | Regulator | 494-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0023 | Regulator | 494-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0023 | Regulator | 494-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0023 | Regulator | 494-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0023 | Regulator | 494-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 49990 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0023 | Regulator | 494-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0023 | Regulator | 494-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0023 | Regulator | 494-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | KR0023 | Regulator | 494-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BAT001360 | Battery | 405-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BAT001360 | Battery | 405-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BAT001360 | Battery | 405-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.9 | VDC |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BAT001360 | Battery | 405-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 28.1 | VDC |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BAT001360 | Battery | 405-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BAT001360 | Battery | 405-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BAT001360 | Battery | 405-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BAT001360 | Battery | 405-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BAT001360 | Battery | 405-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BAT001360 | Battery | 405-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BAT001360 | Battery | 405-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 46 | °F |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BAT001360 | Battery | 405-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BAT001359 | Battery | 736-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0322 | RecloserElectronic | 894-0578 | Recloser Electronic Patrol Inspection | Amps A Ø | 0.0 | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0322 | RecloserElectronic | 894-0578 | Recloser Electronic Patrol Inspection | Amps B Ø | 0.0 | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0322 | RecloserElectronic | 894-0578 | Recloser Electronic Patrol Inspection | Amps C Ø | 0.0 | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0322 | RecloserElectronic | 894-0578 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BAT001359 | Battery | 736-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0322 | RecloserElectronic | 894-0578 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0322 | RecloserElectronic | 894-0578 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0322 | RecloserElectronic | 894-0578 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0322 | RecloserElectronic | 894-0578 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0322 | RecloserElectronic | 894-0578 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0322 | RecloserElectronic | 894-0578 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0322 | RecloserElectronic | 894-0578 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 15:24 | Distribution | Revelo Quarterly Inspection | X0322 | RecloserElectronic | 894-0578 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | YD000196 | Yard | 571-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | YD000196 | Yard | 571-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | YD000196 | Yard | 571-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | YD000196 | Yard | 571-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | YD000196 | Yard | 571-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | YD000196 | Yard | 571-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | YD000196 | Yard | 571-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | YD000196 | Yard | 571-Yard | Yard Patrol Inspection | Ambient Temp | 46 | °F |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Readings | Totalizer Meter Reading | .5538 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Readings | Oil Temp Present | 23 | °C |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000200 | Switchgear | WO-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000200 | Switchgear | WO-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Readings | Oil Temp Max | 65 | °C |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.5 | psi |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Readings | LTC Totalizer Reading | 3987.36 | kw |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Readings | General Comments | | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | BCH001052 | Charger | 467-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | BCH001052 | Charger | 467-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000200 | Switchgear | WO-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000200 | Switchgear | WO-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000200 | Switchgear | WO-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000200 | Switchgear | WO-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000200 | Switchgear | WO-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000200 | Switchgear | WO-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000200 | Switchgear | WO-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000200 | Switchgear | WO-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000200 | Switchgear | WO-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | Both lights on the outside of the switchgear are out. | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000200 | Switchgear | WO-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000200 | Switchgear | WO-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000200 | Switchgear | WO-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000200 | Switchgear | WO-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000200 | Switchgear | WO-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000200 | Switchgear | WO-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000200 | Switchgear | WO-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | SWG000200 | Switchgear | WO-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | BCH001052 | Charger | 467-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | BCH001052 | Charger | 467-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | BCH001052 | Charger | 467-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .9 | amps |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | BCH001052 | Charger | 467-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | BCH001052 | Charger | 467-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | BCH001052 | Charger | 467-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | WithLTC | 736-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | YD000200 | Yard | 736-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | YD000200 | Yard | 736-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | YD000200 | Yard | 736-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | YD000200 | Yard | 736-Yard | Yard Patrol Inspection | General Comments | | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | YD000200 | Yard | 736-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | YD000200 | Yard | 736-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | YD000200 | Yard | 736-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | YD000200 | Yard | 736-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | YD000200 | Yard | 736-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | YD000200 | Yard | 736-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | YD000200 | Yard | 736-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | YD000200 | Yard | 736-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1333 | BreakerVacuum | JT-1126 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1333 | BreakerVacuum | JT-1126 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1333 | BreakerVacuum | JT-1126 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1333 | BreakerVacuum | JT-1126 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1333 | BreakerVacuum | JT-1126 | VCB Readings | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1333 | BreakerVacuum | JT-1126 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1333 | BreakerVacuum | JT-1126 | VCB Readings | Operations Counter AF | 238 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1333 | BreakerVacuum | JT-1126 | VCB Readings | Operations Counter AL | 238 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1333 | BreakerVacuum | JT-1126 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1333 | BreakerVacuum | JT-1126 | VCB Readings | Switching Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1333 | BreakerVacuum | JT-1126 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | YD000200 | Yard | 736-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | YD000200 | Yard | 736-Yard | Yard Patrol Inspection | Ambient Temp | 46 | °F |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | FE000201 | Fence | 736-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | FE000201 | Fence | 736-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | FE000201 | Fence | 736-Fence | Fence Patrol Inspection | General Comments | | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | FE000201 | Fence | 736-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | FE000201 | Fence | 736-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | FE000201 | Fence | 736-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | FE000201 | Fence | 736-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | FE000201 | Fence | 736-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | FE000201 | Fence | 736-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | FE000201 | Fence | 736-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | FE000201 | Fence | 736-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | FE000201 | Fence | 736-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | FE000201 | Fence | 736-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | FE000201 | Fence | 736-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | FE000201 | Fence | 736-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | FE000201 | Fence | 736-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | ST000203 | Structure | 571-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | ST000203 | Structure | 571-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | ST000203 | Structure | 571-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | ST000203 | Structure | 571-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | ST000203 | Structure | 571-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | ST000203 | Structure | 571-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | ST000203 | Structure | 571-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | ST000203 | Structure | 571-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | ST000203 | Structure | 571-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | ST000203 | Structure | 571-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | ST000203 | Structure | 571-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | ST000203 | Structure | 571-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | ST000203 | Structure | 571-Structure | Structure Patrol Inspection | General Comments | no spare fuses | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | ST000203 | Structure | 571-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | ST000203 | Structure | 571-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | ST000203 | Structure | 571-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | ST000203 | Structure | 571-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | ST000203 | Structure | 571-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | ST000203 | Structure | 571-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | ST000203 | Structure | 571-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | ST000203 | Structure | 571-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | ST000203 | Structure | 571-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | YD000196 | Yard | 571-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | YD000196 | Yard | 571-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | YD000196 | Yard | 571-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | n | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | YD000196 | Yard | 571-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | YD000196 | Yard | 571-Yard | Yard Patrol Inspection | General Comments | Remove SPR fron inspection | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | YD000196 | Yard | 571-Yard | Yard Patrol Inspection | Follow-up Action Required? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | YD000196 | Yard | 571-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | YD000192 | Yard | 405-Yard | Yard Patrol Inspection | General Comments | Remove SPR from Inspection | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | YD000192 | Yard | 405-Yard | Yard Patrol Inspection | Follow-up Action Required? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | YD000192 | Yard | 405-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | YD000192 | Yard | 405-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | YD000192 | Yard | 405-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | YD000192 | Yard | 405-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | YD000192 | Yard | 405-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | YD000192 | Yard | 405-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | YD000192 | Yard | 405-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | YD000192 | Yard | 405-Yard | Yard Patrol Inspection | Ambient Temp | 46 | °F |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | FE000194 | Fence | 405-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | FE000194 | Fence | 405-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | FE000194 | Fence | 405-Fence | Fence Patrol Inspection | General Comments | | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Readings | 9 Month Operations | 1 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Readings | Amps A Ø | 30.0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Readings | Amps B Ø | 28.0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Readings | Amps C Ø | 37.0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | FE000194 | Fence | 405-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | FE000194 | Fence | 405-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | FE000194 | Fence | 405-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | FE000194 | Fence | 405-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | FE000194 | Fence | 405-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | FE000194 | Fence | 405-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | FE000194 | Fence | 405-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | FE000194 | Fence | 405-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | FE000194 | Fence | 405-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | FE000194 | Fence | 405-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | FE000194 | Fence | 405-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | FE000194 | Fence | 405-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | FE000194 | Fence | 405-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000107 | Regulator | 682-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000107 | Regulator | 682-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000107 | Regulator | 682-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000107 | Regulator | 682-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000107 | Regulator | 682-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 11617 | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000107 | Regulator | 682-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000107 | Regulator | 682-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Readings | General Comments | | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Readings | Maintenance Operations | 1 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Readings | Operations Counter AF | 209 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Readings | Operations Counter AL | 209 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Readings | Operations This Read Vac | 1 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | K0162 | BreakerVacuum | 571-1645 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1100 | psi |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 39 | °C |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 23 | °C |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 39 | °C |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 23 | °C |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 39 | °C |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 23 | °C |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 39 | °C |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | TX000034 | WithLTC | MK-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 23 | °C |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LTCM000018 | LTCMechanism | MK-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LTCM000018 | LTCMechanism | MK-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LTCM000018 | LTCMechanism | MK-TRANS 2 | LTC Counter Readings | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LTCM000018 | LTCMechanism | MK-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LTCM000018 | LTCMechanism | MK-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 16789 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LTCM000018 | LTCMechanism | MK-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 16789 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LTCM000018 | LTCMechanism | MK-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LTCM000018 | LTCMechanism | MK-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LTCM000018 | LTCMechanism | MK-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LTCM000018 | LTCMechanism | MK-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LTCM000018 | LTCMechanism | MK-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 11 | °C |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LTCM000018 | LTCMechanism | MK-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 31 | °C |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LTCM000018 | LTCMechanism | MK-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 173 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LTCM000018 | LTCMechanism | MK-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LTCM000018 | LTCMechanism | MK-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LTCM000018 | LTCMechanism | MK-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LTCC000622 | LTCControl | MK-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LTCC000622 | LTCControl | MK-TRANS 2 | LTC Control Insp | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LTCC000622 | LTCControl | MK-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | FE000195 | Fence | 571-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | FE000195 | Fence | 571-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | FE000195 | Fence | 571-Fence | Fence Patrol Inspection | General Comments | | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | FE000195 | Fence | 571-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | FE000195 | Fence | 571-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | FE000195 | Fence | 571-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | FE000195 | Fence | 571-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | FE000195 | Fence | 571-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | FE000195 | Fence | 571-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | FE000195 | Fence | 571-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | FE000195 | Fence | 571-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | FE000195 | Fence | 571-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | FE000195 | Fence | 571-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | FE000195 | Fence | 571-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | FE000195 | Fence | 571-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | FE000195 | Fence | 571-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | YD000192 | Yard | 405-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | YD000192 | Yard | 405-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | YD000192 | Yard | 405-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | n | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | YD000192 | Yard | 405-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | LTCMechanism | WS-TRANS 3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | LTCMechanism | WS-TRANS 3 | LTC Counter Readings | LTC As Found Counter | 30272 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .8 | psi |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1350 | psi |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 39 | °C |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 17 | °C |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 39 | °C |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 17 | °C |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 39 | °C |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 17 | °C |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 39 | °C |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 17 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | LTCMechanism | WS-TRANS 3 | LTC Counter Readings | LTC As Left Counter | 30272 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | LTCMechanism | WS-TRANS 3 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | LTCMechanism | WS-TRANS 3 | LTC Counter Readings | LTC Max Tap Position | 3R | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | LTCMechanism | WS-TRANS 3 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | LTCMechanism | WS-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 21 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | LTCMechanism | WS-TRANS 3 | LTC Counter Readings | LTC Operations Since Last Insp | 122 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | LTCMechanism | WS-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | LTCMechanism | WS-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | LTCMechanism | WS-TRANS 3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | LTCMechanism | WS-TRANS 3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | PF001201 | PowerFuse | MK-STA SER NO 2 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | PF001201 | PowerFuse | MK-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | PF001201 | PowerFuse | MK-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | PF001202 | PowerFuse | MK-12KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | PF001202 | PowerFuse | MK-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | PF001202 | PowerFuse | MK-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1330 | BreakerVacuum | JT-12KV BUS TIE SEC 1 | VCB Readings | 9 Month Operations | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Readings | Amps A Ø | 135.0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Readings | Amps B Ø | 115.0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Readings | Amps C Ø | 65.0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1330 | BreakerVacuum | JT-12KV BUS TIE SEC 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1330 | BreakerVacuum | JT-12KV BUS TIE SEC 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1330 | BreakerVacuum | JT-12KV BUS TIE SEC 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1330 | BreakerVacuum | JT-12KV BUS TIE SEC 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1330 | BreakerVacuum | JT-12KV BUS TIE SEC 1 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Readings | X1 Winding Temp Max | 40 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Readings | X1 Winding Temp Present | 26 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Readings | X2 Winding Temp Max | 40 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Readings | X2 Winding Temp Present | 26 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Readings | X3 Winding Temp Max | 40 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Readings | X3 Winding Temp Present | 26 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1174 | BreakerVacuum | WS-1474-1 | VCB Readings | 9 Month Operations | 18 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1174 | BreakerVacuum | WS-1474-1 | VCB Readings | 9 Month Operations VCB New | 18 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1174 | BreakerVacuum | WS-1474-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1174 | BreakerVacuum | WS-1474-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1174 | BreakerVacuum | WS-1474-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1174 | BreakerVacuum | WS-1474-1 | VCB Readings | Amps A Ø | 114.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1174 | BreakerVacuum | WS-1474-1 | VCB Readings | Amps B Ø | 113.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1174 | BreakerVacuum | WS-1474-1 | VCB Readings | Amps C Ø | 114.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1174 | BreakerVacuum | WS-1474-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1174 | BreakerVacuum | WS-1474-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1174 | BreakerVacuum | WS-1474-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1174 | BreakerVacuum | WS-1474-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1174 | BreakerVacuum | WS-1474-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1174 | BreakerVacuum | WS-1474-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1174 | BreakerVacuum | WS-1474-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1174 | BreakerVacuum | WS-1474-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1174 | BreakerVacuum | WS-1474-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1174 | BreakerVacuum | WS-1474-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1174 | BreakerVacuum | WS-1474-1 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1174 | BreakerVacuum | WS-1474-1 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1174 | BreakerVacuum | WS-1474-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1174 | BreakerVacuum | WS-1474-1 | VCB Readings | Operations Counter AF | 102 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1174 | BreakerVacuum | WS-1474-1 | VCB Readings | Operations Counter AL | 102 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1174 | BreakerVacuum | WS-1474-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1174 | BreakerVacuum | WS-1474-1 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1174 | BreakerVacuum | WS-1474-1 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1215 | BreakerVacuum | WS-CAP BK 2 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1215 | BreakerVacuum | WS-CAP BK 2 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1215 | BreakerVacuum | WS-CAP BK 2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1215 | BreakerVacuum | WS-CAP BK 2 | VCB Readings | Operations Counter AL | 225 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1215 | BreakerVacuum | WS-CAP BK 2 | VCB Readings | Operations Counter AF | 225 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1215 | BreakerVacuum | WS-CAP BK 2 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1215 | BreakerVacuum | WS-CAP BK 2 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1215 | BreakerVacuum | WS-CAP BK 2 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1215 | BreakerVacuum | WS-CAP BK 2 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1215 | BreakerVacuum | WS-CAP BK 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1215 | BreakerVacuum | WS-CAP BK 2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1215 | BreakerVacuum | WS-CAP BK 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1215 | BreakerVacuum | WS-CAP BK 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1215 | BreakerVacuum | WS-CAP BK 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1215 | BreakerVacuum | WS-CAP BK 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1215 | BreakerVacuum | WS-CAP BK 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1215 | BreakerVacuum | WS-CAP BK 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1215 | BreakerVacuum | WS-CAP BK 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1215 | BreakerVacuum | WS-CAP BK 2 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1215 | BreakerVacuum | WS-CAP BK 2 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1215 | BreakerVacuum | WS-CAP BK 2 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1215 | BreakerVacuum | WS-CAP BK 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1215 | BreakerVacuum | WS-CAP BK 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1215 | BreakerVacuum | WS-CAP BK 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1215 | BreakerVacuum | WS-CAP BK 2 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1215 | BreakerVacuum | WS-CAP BK 2 | VCB Readings | 9 Month Operations | 2 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | LTCMechanism | WS-TRANS 3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | LTCMechanism | WS-TRANS 3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | LTCMechanism | WS-TRANS 3 | LTC Counter Readings | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | WithLTC | JT-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0643 | BreakerAirMagnetic | MG-GND TR 5 | AMCB Readings | 9 Month Ops New | 1 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0643 | BreakerAirMagnetic | MG-GND TR 5 | AMCB Readings | 9 Months Operations | 1 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0643 | BreakerAirMagnetic | MG-GND TR 5 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0643 | BreakerAirMagnetic | MG-GND TR 5 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0643 | BreakerAirMagnetic | MG-GND TR 5 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0643 | BreakerAirMagnetic | MG-GND TR 5 | AMCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0643 | BreakerAirMagnetic | MG-GND TR 5 | AMCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0643 | BreakerAirMagnetic | MG-GND TR 5 | AMCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0643 | BreakerAirMagnetic | MG-GND TR 5 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0643 | BreakerAirMagnetic | MG-GND TR 5 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0643 | BreakerAirMagnetic | MG-GND TR 5 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0643 | BreakerAirMagnetic | MG-GND TR 5 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0643 | BreakerAirMagnetic | MG-GND TR 5 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0643 | BreakerAirMagnetic | MG-GND TR 5 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0643 | BreakerAirMagnetic | MG-GND TR 5 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0643 | BreakerAirMagnetic | MG-GND TR 5 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0643 | BreakerAirMagnetic | MG-GND TR 5 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0643 | BreakerAirMagnetic | MG-GND TR 5 | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0643 | BreakerAirMagnetic | MG-GND TR 5 | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0643 | BreakerAirMagnetic | MG-GND TR 5 | AMCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0643 | BreakerAirMagnetic | MG-GND TR 5 | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0643 | BreakerAirMagnetic | MG-GND TR 5 | AMCB Readings | Operations Counter AF | 99988 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0643 | BreakerAirMagnetic | MG-GND TR 5 | AMCB Readings | Operations Counter AL | 99988 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0643 | BreakerAirMagnetic | MG-GND TR 5 | AMCB Readings | Operations This Read AM | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0643 | BreakerAirMagnetic | MG-GND TR 5 | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0643 | BreakerAirMagnetic | MG-GND TR 5 | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1187 | BreakerVacuum | WS-CAP BK 1 | VCB Readings | 9 Month Operations | 8 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1187 | BreakerVacuum | WS-CAP BK 1 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1187 | BreakerVacuum | WS-CAP BK 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1187 | BreakerVacuum | WS-CAP BK 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1187 | BreakerVacuum | WS-CAP BK 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1187 | BreakerVacuum | WS-CAP BK 1 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1187 | BreakerVacuum | WS-CAP BK 1 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1187 | BreakerVacuum | WS-CAP BK 1 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1187 | BreakerVacuum | WS-CAP BK 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1187 | BreakerVacuum | WS-CAP BK 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1187 | BreakerVacuum | WS-CAP BK 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1187 | BreakerVacuum | WS-CAP BK 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1187 | BreakerVacuum | WS-CAP BK 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1187 | BreakerVacuum | WS-CAP BK 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1187 | BreakerVacuum | WS-CAP BK 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1187 | BreakerVacuum | WS-CAP BK 1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1187 | BreakerVacuum | WS-CAP BK 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1187 | BreakerVacuum | WS-CAP BK 1 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1187 | BreakerVacuum | WS-CAP BK 1 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1187 | BreakerVacuum | WS-CAP BK 1 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1187 | BreakerVacuum | WS-CAP BK 1 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1187 | BreakerVacuum | WS-CAP BK 1 | VCB Readings | Operations Counter AF | 213 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1187 | BreakerVacuum | WS-CAP BK 1 | VCB Readings | Operations Counter AL | 213 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1187 | BreakerVacuum | WS-CAP BK 1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1187 | BreakerVacuum | WS-CAP BK 1 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1187 | BreakerVacuum | WS-CAP BK 1 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1333 | BreakerVacuum | JT-1126 | VCB Readings | 9 Month Operations | 7 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1333 | BreakerVacuum | JT-1126 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1333 | BreakerVacuum | JT-1126 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1333 | BreakerVacuum | JT-1126 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1333 | BreakerVacuum | JT-1126 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1333 | BreakerVacuum | JT-1126 | VCB Readings | Amps A Ø | 88.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1333 | BreakerVacuum | JT-1126 | VCB Readings | Amps B Ø | 110.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1333 | BreakerVacuum | JT-1126 | VCB Readings | Amps C Ø | 110.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1333 | BreakerVacuum | JT-1126 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1333 | BreakerVacuum | JT-1126 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1333 | BreakerVacuum | JT-1126 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1333 | BreakerVacuum | JT-1126 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1333 | BreakerVacuum | JT-1126 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1333 | BreakerVacuum | JT-1126 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1333 | BreakerVacuum | JT-1126 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | YD000200 | Yard | 736-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1330 | BreakerVacuum | JT-12KV BUS TIE SEC 1 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1330 | BreakerVacuum | JT-12KV BUS TIE SEC 1 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1330 | BreakerVacuum | JT-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1330 | BreakerVacuum | JT-12KV BUS TIE SEC 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1330 | BreakerVacuum | JT-12KV BUS TIE SEC 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1330 | BreakerVacuum | JT-12KV BUS TIE SEC 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1330 | BreakerVacuum | JT-12KV BUS TIE SEC 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1330 | BreakerVacuum | JT-12KV BUS TIE SEC 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1330 | BreakerVacuum | JT-12KV BUS TIE SEC 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | FE000227 | Fence | 497-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | FE000227 | Fence | 497-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | FE000227 | Fence | 497-Fence | Fence Patrol Inspection | General Comments | | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | FE000227 | Fence | 497-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | FE000227 | Fence | 497-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | FE000227 | Fence | 497-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | BAT000888 | Battery | SV-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | BAT000888 | Battery | SV-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | BAT000888 | Battery | SV-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | BAT000888 | Battery | SV-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | BAT000888 | Battery | SV-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | BAT000888 | Battery | SV-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | BAT000888 | Battery | SV-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Water Added | If low,note cell #~'s |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | BAT000888 | Battery | SV-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | BAT000888 | Battery | SV-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | BAT000888 | Battery | SV-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | BAT000888 | Battery | SV-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | BAT000888 | Battery | SV-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | FE000227 | Fence | 497-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | FE000227 | Fence | 497-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | FE000227 | Fence | 497-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | FE000227 | Fence | 497-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | FE000227 | Fence | 497-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | FE000227 | Fence | 497-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | FE000227 | Fence | 497-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | FE000227 | Fence | 497-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | FE000227 | Fence | 497-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | FE000227 | Fence | 497-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1330 | BreakerVacuum | JT-12KV BUS TIE SEC 1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1330 | BreakerVacuum | JT-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1330 | BreakerVacuum | JT-12KV BUS TIE SEC 1 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1330 | BreakerVacuum | JT-12KV BUS TIE SEC 1 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1330 | BreakerVacuum | JT-12KV BUS TIE SEC 1 | VCB Readings | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1330 | BreakerVacuum | JT-12KV BUS TIE SEC 1 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1330 | BreakerVacuum | JT-12KV BUS TIE SEC 1 | VCB Readings | Operations Counter AF | 224 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1330 | BreakerVacuum | JT-12KV BUS TIE SEC 1 | VCB Readings | Operations Counter AL | 224 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1330 | BreakerVacuum | JT-12KV BUS TIE SEC 1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1330 | BreakerVacuum | JT-12KV BUS TIE SEC 1 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1330 | BreakerVacuum | JT-12KV BUS TIE SEC 1 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Readings | General Comments | | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Readings | Operations Counter AF | 231 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Readings | Operations Counter AL | 231 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | KB0120 | BreakerVacuum | 686-0879 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Readings | General Comments | | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1074.96 | kw |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 70.00 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 65.00 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1208 | BreakerVacuum | WS-1304-2 | VCB Readings | 9 Month Operations | 2 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1208 | BreakerVacuum | WS-1304-2 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1208 | BreakerVacuum | WS-1304-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1208 | BreakerVacuum | WS-1304-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1208 | BreakerVacuum | WS-1304-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1208 | BreakerVacuum | WS-1304-2 | VCB Readings | Amps A Ø | 34.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1208 | BreakerVacuum | WS-1304-2 | VCB Readings | Amps B Ø | 35.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1208 | BreakerVacuum | WS-1304-2 | VCB Readings | Amps C Ø | 34.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1208 | BreakerVacuum | WS-1304-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1208 | BreakerVacuum | WS-1304-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1208 | BreakerVacuum | WS-1304-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1208 | BreakerVacuum | WS-1304-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1208 | BreakerVacuum | WS-1304-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1208 | BreakerVacuum | WS-1304-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1208 | BreakerVacuum | WS-1304-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1208 | BreakerVacuum | WS-1304-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1208 | BreakerVacuum | WS-1304-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1208 | BreakerVacuum | WS-1304-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1208 | BreakerVacuum | WS-1304-2 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1208 | BreakerVacuum | WS-1304-2 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1208 | BreakerVacuum | WS-1304-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1208 | BreakerVacuum | WS-1304-2 | VCB Readings | Operations Counter AF | 179 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1208 | BreakerVacuum | WS-1304-2 | VCB Readings | Operations Counter AL | 179 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1208 | BreakerVacuum | WS-1304-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1208 | BreakerVacuum | WS-1304-2 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1208 | BreakerVacuum | WS-1304-2 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | LTCC000681 | LTCControl | 686-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | LTCC000681 | LTCControl | 686-2 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | LTCC000681 | LTCControl | 686-2 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | LTCC000681 | LTCControl | 686-2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | LTCC000681 | LTCControl | 686-2 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | LTCC000681 | LTCControl | 686-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | LTCC000681 | LTCControl | 686-2 | LTC Control Insp | General Comments | | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | LTCC000681 | LTCControl | 686-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | LTCC000681 | LTCControl | 686-2 | LTC Control Insp | All Connections OK? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | 0953 | NonLTC | 686-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .8958 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LTCC000098 | LTCControl | WO-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LTCC000098 | LTCControl | WO-TRANS 2 | LTC Control Insp | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LTCC000098 | LTCControl | WO-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1177 | BreakerVacuum | WS-1304-1 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1177 | BreakerVacuum | WS-1304-1 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1177 | BreakerVacuum | WS-1304-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0619 | BreakerAirMagnetic | MG-14KV BUS TIE SEC 5-C | AMCB Readings | Amps A Ø | 275.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0619 | BreakerAirMagnetic | MG-14KV BUS TIE SEC 5-C | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0619 | BreakerAirMagnetic | MG-14KV BUS TIE SEC 5-C | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0619 | BreakerAirMagnetic | MG-14KV BUS TIE SEC 5-C | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0619 | BreakerAirMagnetic | MG-14KV BUS TIE SEC 5-C | AMCB Readings | 9 Months Operations | 6 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0619 | BreakerAirMagnetic | MG-14KV BUS TIE SEC 5-C | AMCB Readings | 9 Month Ops New | 6 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Readings | Operations Counter AL | 166 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Readings | Operations Counter AF | 166 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1227 | BreakerVacuum | WS-1428-4 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1227 | BreakerVacuum | WS-1428-4 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1227 | BreakerVacuum | WS-1428-4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1227 | BreakerVacuum | WS-1428-4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1227 | BreakerVacuum | WS-1428-4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1227 | BreakerVacuum | WS-1428-4 | VCB Readings | Amps A Ø | 94.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1227 | BreakerVacuum | WS-1428-4 | VCB Readings | Amps B Ø | 90.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1227 | BreakerVacuum | WS-1428-4 | VCB Readings | Amps C Ø | 93.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1227 | BreakerVacuum | WS-1428-4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1227 | BreakerVacuum | WS-1428-4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1227 | BreakerVacuum | WS-1428-4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1227 | BreakerVacuum | WS-1428-4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1227 | BreakerVacuum | WS-1428-4 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1227 | BreakerVacuum | WS-1428-4 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1227 | BreakerVacuum | WS-1428-4 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1227 | BreakerVacuum | WS-1428-4 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1227 | BreakerVacuum | WS-1428-4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1227 | BreakerVacuum | WS-1428-4 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1227 | BreakerVacuum | WS-1428-4 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1227 | BreakerVacuum | WS-1428-4 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1227 | BreakerVacuum | WS-1428-4 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1227 | BreakerVacuum | WS-1428-4 | VCB Readings | Operations Counter AF | 48 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1227 | BreakerVacuum | WS-1428-4 | VCB Readings | Operations Counter AL | 48 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1227 | BreakerVacuum | WS-1428-4 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1227 | BreakerVacuum | WS-1428-4 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1227 | BreakerVacuum | WS-1428-4 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Readings | General Comments | Breaker open | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Readings | Amps B Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BK000493 | BreakerVacuum | 596-1497 | VCB Readings | 9 Month Operations | 0 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Readings | General Comments | | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 5189.76 | kw |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Readings | Oil Temp Max | 56 | °C |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Readings | Oil Temp Present | 42 | °C |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1238 | BreakerVacuum | WS-1425-3 | VCB Readings | 9 Month Operations | 4 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1238 | BreakerVacuum | WS-1425-3 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1238 | BreakerVacuum | WS-1425-3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1238 | BreakerVacuum | WS-1425-3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1238 | BreakerVacuum | WS-1425-3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1238 | BreakerVacuum | WS-1425-3 | VCB Readings | Amps A Ø | 86.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0605 | BreakerAirMagnetic | MG-1327 | AMCB Readings | 9 Month Ops New | 3 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0605 | BreakerAirMagnetic | MG-1327 | AMCB Readings | 9 Months Operations | 3 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0605 | BreakerAirMagnetic | MG-1327 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1238 | BreakerVacuum | WS-1425-3 | VCB Readings | Amps B Ø | 84.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1238 | BreakerVacuum | WS-1425-3 | VCB Readings | Amps C Ø | 84.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1238 | BreakerVacuum | WS-1425-3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1238 | BreakerVacuum | WS-1425-3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1238 | BreakerVacuum | WS-1425-3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1238 | BreakerVacuum | WS-1425-3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1238 | BreakerVacuum | WS-1425-3 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1178 | BreakerVacuum | WS-1305-1 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1178 | BreakerVacuum | WS-1305-1 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1178 | BreakerVacuum | WS-1305-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1178 | BreakerVacuum | WS-1305-1 | VCB Readings | Operations Counter AL | 91 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1178 | BreakerVacuum | WS-1305-1 | VCB Readings | Operations Counter AF | 91 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1178 | BreakerVacuum | WS-1305-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1238 | BreakerVacuum | WS-1425-3 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0605 | BreakerAirMagnetic | MG-1327 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0605 | BreakerAirMagnetic | MG-1327 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0605 | BreakerAirMagnetic | MG-1327 | AMCB Readings | Amps A Ø | 153.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0605 | BreakerAirMagnetic | MG-1327 | AMCB Readings | Amps B Ø | 132.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0605 | BreakerAirMagnetic | MG-1327 | AMCB Readings | Amps C Ø | 131.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0605 | BreakerAirMagnetic | MG-1327 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0605 | BreakerAirMagnetic | MG-1327 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0605 | BreakerAirMagnetic | MG-1327 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1238 | BreakerVacuum | WS-1425-3 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1238 | BreakerVacuum | WS-1425-3 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1238 | BreakerVacuum | WS-1425-3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0605 | BreakerAirMagnetic | MG-1327 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0605 | BreakerAirMagnetic | MG-1327 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0605 | BreakerAirMagnetic | MG-1327 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0605 | BreakerAirMagnetic | MG-1327 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0605 | BreakerAirMagnetic | MG-1327 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0605 | BreakerAirMagnetic | MG-1327 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0605 | BreakerAirMagnetic | MG-1327 | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0605 | BreakerAirMagnetic | MG-1327 | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0605 | BreakerAirMagnetic | MG-1327 | AMCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0605 | BreakerAirMagnetic | MG-1327 | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0605 | BreakerAirMagnetic | MG-1327 | AMCB Readings | Operations Counter AF | 875 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0605 | BreakerAirMagnetic | MG-1327 | AMCB Readings | Operations Counter AL | 875 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0605 | BreakerAirMagnetic | MG-1327 | AMCB Readings | Operations This Read AM | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0605 | BreakerAirMagnetic | MG-1327 | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0605 | BreakerAirMagnetic | MG-1327 | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1226 | BreakerVacuum | WS-1427-4 | VCB Readings | 9 Month Operations | 5 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1226 | BreakerVacuum | WS-1427-4 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1177 | BreakerVacuum | WS-1304-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1177 | BreakerVacuum | WS-1304-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1177 | BreakerVacuum | WS-1304-1 | VCB Readings | Amps A Ø | 45.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1177 | BreakerVacuum | WS-1304-1 | VCB Readings | Amps B Ø | 44.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1177 | BreakerVacuum | WS-1304-1 | VCB Readings | Amps C Ø | 43.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1177 | BreakerVacuum | WS-1304-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1177 | BreakerVacuum | WS-1304-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1177 | BreakerVacuum | WS-1304-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1177 | BreakerVacuum | WS-1304-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1177 | BreakerVacuum | WS-1304-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1177 | BreakerVacuum | WS-1304-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1177 | BreakerVacuum | WS-1304-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1177 | BreakerVacuum | WS-1304-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1177 | BreakerVacuum | WS-1304-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1177 | BreakerVacuum | WS-1304-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1177 | BreakerVacuum | WS-1304-1 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1177 | BreakerVacuum | WS-1304-1 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1177 | BreakerVacuum | WS-1304-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1177 | BreakerVacuum | WS-1304-1 | VCB Readings | Operations Counter AF | 104 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1177 | BreakerVacuum | WS-1304-1 | VCB Readings | Operations Counter AL | 104 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1177 | BreakerVacuum | WS-1304-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1177 | BreakerVacuum | WS-1304-1 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1177 | BreakerVacuum | WS-1304-1 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Readings | 9 Month Operations | 4 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Readings | Amps A Ø | 150.0 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Readings | Amps B Ø | 175.0 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Readings | Amps C Ø | 220.0 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Readings | Fault Adjusted Amps A Phase V | 4.56 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Readings | Fault Operations A Ø | 1 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Readings | General Comments | TC, 51-A I Flag | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Readings | Maintenance Operations | 1 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Readings | Operations Counter AF | 330 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Readings | Operations Counter AL | 330 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Readings | Operations This Read Vac | 2 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0152 | BreakerVacuum | 497-0657 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | ST000328 | Structure | 641-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | ST000328 | Structure | 641-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | ST000328 | Structure | 641-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | ST000328 | Structure | 641-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | ST000328 | Structure | 641-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | ST000328 | Structure | 641-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | ST000328 | Structure | 641-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | ST000328 | Structure | 641-Structure | Structure Patrol Inspection | General Comments | | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | ST000328 | Structure | 641-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | ST000328 | Structure | 641-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | ST000328 | Structure | 641-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | ST000328 | Structure | 641-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | ST000328 | Structure | 641-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | ST000328 | Structure | 641-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | ST000328 | Structure | 641-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | ST000328 | Structure | 641-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | ST000328 | Structure | 641-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | YD000322 | Yard | 641-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | YD000322 | Yard | 641-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | YD000322 | Yard | 641-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | YD000322 | Yard | 641-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | YD000322 | Yard | 641-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | YD000322 | Yard | 641-Yard | Yard Patrol Inspection | General Comments | | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | YD000322 | Yard | 641-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | YD000322 | Yard | 641-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | YD000322 | Yard | 641-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | YD000322 | Yard | 641-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | YD000322 | Yard | 641-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | YD000322 | Yard | 641-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | YD000322 | Yard | 641-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | YD000322 | Yard | 641-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | YD000322 | Yard | 641-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | YD000322 | Yard | 641-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LTCC000265 | LTCControl | WS-TRANS 4 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LTCC000265 | LTCControl | WS-TRANS 4 | LTC Control Insp | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LTCC000265 | LTCControl | WS-TRANS 4 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | LTCMechanism | WS-TRANS 4 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | LTCMechanism | WS-TRANS 4 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | LTCMechanism | WS-TRANS 4 | LTC Counter Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | LTCMechanism | WS-TRANS 4 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | LTCMechanism | WS-TRANS 4 | LTC Counter Readings | LTC As Found Counter | 37674 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | LTCMechanism | WS-TRANS 4 | LTC Counter Readings | LTC As Left Counter | 37674 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | LTCMechanism | WS-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | LTCMechanism | WS-TRANS 4 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | LTCMechanism | WS-TRANS 4 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | LTCMechanism | WS-TRANS 4 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | LTCMechanism | WS-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 32 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | LTCMechanism | WS-TRANS 4 | LTC Counter Readings | LTC Operations Since Last Insp | 142 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | LTCMechanism | WS-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | LTCMechanism | WS-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | LTCMechanism | WS-TRANS 4 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | LTCMechanism | WS-TRANS 4 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | CH000411 | ControlHouse | 570-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | CH000411 | ControlHouse | 570-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | CH000411 | ControlHouse | 570-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | CH000411 | ControlHouse | 570-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | CH000411 | ControlHouse | 570-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | CH000411 | ControlHouse | 570-Control House | Control House Patrol Inspection | Evidence of Insects | Yes_needs_sprayed | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | CH000411 | ControlHouse | 570-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | CH000411 | ControlHouse | 570-Control House | Control House Patrol Inspection | Filters Condition OK? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | CH000411 | ControlHouse | 570-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | CH000411 | ControlHouse | 570-Control House | Control House Patrol Inspection | Floor Swept? | n | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | CH000411 | ControlHouse | 570-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | CH000411 | ControlHouse | 570-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | CH000411 | ControlHouse | 570-Control House | Control House Patrol Inspection | General Comments | | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | CH000411 | ControlHouse | 570-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | CH000411 | ControlHouse | 570-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | CH000411 | ControlHouse | 570-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | CH000411 | ControlHouse | 570-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000107 | Regulator | 682-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000107 | Regulator | 682-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000107 | Regulator | 682-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000107 | Regulator | 682-1 C | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000107 | Regulator | 682-1 C | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000107 | Regulator | 682-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000107 | Regulator | 682-1 C | Regulator Patrol Inspection | General Comments | ok | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000107 | Regulator | 682-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000107 | Regulator | 682-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000107 | Regulator | 682-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000107 | Regulator | 682-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000107 | Regulator | 682-1 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000107 | Regulator | 682-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000107 | Regulator | 682-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000107 | Regulator | 682-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000107 | Regulator | 682-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000107 | Regulator | 682-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000106 | Regulator | 682-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000106 | Regulator | 682-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000106 | Regulator | 682-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000106 | Regulator | 682-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000106 | Regulator | 682-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 11868 | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000106 | Regulator | 682-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000106 | Regulator | 682-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000106 | Regulator | 682-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000106 | Regulator | 682-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000106 | Regulator | 682-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000106 | Regulator | 682-1 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000106 | Regulator | 682-1 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000106 | Regulator | 682-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000106 | Regulator | 682-1 A | Regulator Patrol Inspection | General Comments | ok | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000106 | Regulator | 682-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000106 | Regulator | 682-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000106 | Regulator | 682-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000106 | Regulator | 682-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000106 | Regulator | 682-1 A | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000106 | Regulator | 682-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000106 | Regulator | 682-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000106 | Regulator | 682-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000106 | Regulator | 682-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000106 | Regulator | 682-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000105 | Regulator | 682-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000105 | Regulator | 682-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000105 | Regulator | 682-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000105 | Regulator | 682-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000105 | Regulator | 682-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 11549 | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000105 | Regulator | 682-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000105 | Regulator | 682-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000105 | Regulator | 682-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000105 | Regulator | 682-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000105 | Regulator | 682-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000105 | Regulator | 682-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000105 | Regulator | 682-1 B | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000105 | Regulator | 682-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000105 | Regulator | 682-1 B | Regulator Patrol Inspection | General Comments | ok | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000105 | Regulator | 682-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000105 | Regulator | 682-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000105 | Regulator | 682-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000105 | Regulator | 682-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000105 | Regulator | 682-1 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000105 | Regulator | 682-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000105 | Regulator | 682-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000105 | Regulator | 682-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000105 | Regulator | 682-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RG000105 | Regulator | 682-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | ST000328 | Structure | 641-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | ST000328 | Structure | 641-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | ST000328 | Structure | 641-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | ST000328 | Structure | 641-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | ST000328 | Structure | 641-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1196 | BreakerVacuum | WS-1337-3 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1196 | BreakerVacuum | WS-1337-3 | VCB Readings | Operations Counter AL | 62 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1196 | BreakerVacuum | WS-1337-3 | VCB Readings | Operations Counter AF | 62 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1196 | BreakerVacuum | WS-1337-3 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1196 | BreakerVacuum | WS-1337-3 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1196 | BreakerVacuum | WS-1337-3 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1196 | BreakerVacuum | WS-1337-3 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1196 | BreakerVacuum | WS-1337-3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1196 | BreakerVacuum | WS-1337-3 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1196 | BreakerVacuum | WS-1337-3 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1196 | BreakerVacuum | WS-1337-3 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1196 | BreakerVacuum | WS-1337-3 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1196 | BreakerVacuum | WS-1337-3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1196 | BreakerVacuum | WS-1337-3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1196 | BreakerVacuum | WS-1337-3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1196 | BreakerVacuum | WS-1337-3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1196 | BreakerVacuum | WS-1337-3 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1196 | BreakerVacuum | WS-1337-3 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1196 | BreakerVacuum | WS-1337-3 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1196 | BreakerVacuum | WS-1337-3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1196 | BreakerVacuum | WS-1337-3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1196 | BreakerVacuum | WS-1337-3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1196 | BreakerVacuum | WS-1337-3 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1196 | BreakerVacuum | WS-1337-3 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1216 | BreakerVacuum | WS-CAP BK 4 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1216 | BreakerVacuum | WS-CAP BK 4 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1216 | BreakerVacuum | WS-CAP BK 4 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1216 | BreakerVacuum | WS-CAP BK 4 | VCB Readings | Operations Counter AL | 209 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1216 | BreakerVacuum | WS-CAP BK 4 | VCB Readings | Operations Counter AF | 209 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1216 | BreakerVacuum | WS-CAP BK 4 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1216 | BreakerVacuum | WS-CAP BK 4 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1216 | BreakerVacuum | WS-CAP BK 4 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1216 | BreakerVacuum | WS-CAP BK 4 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1216 | BreakerVacuum | WS-CAP BK 4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1216 | BreakerVacuum | WS-CAP BK 4 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1216 | BreakerVacuum | WS-CAP BK 4 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1216 | BreakerVacuum | WS-CAP BK 4 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1216 | BreakerVacuum | WS-CAP BK 4 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1216 | BreakerVacuum | WS-CAP BK 4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1216 | BreakerVacuum | WS-CAP BK 4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1216 | BreakerVacuum | WS-CAP BK 4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1216 | BreakerVacuum | WS-CAP BK 4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1216 | BreakerVacuum | WS-CAP BK 4 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1216 | BreakerVacuum | WS-CAP BK 4 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1216 | BreakerVacuum | WS-CAP BK 4 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1216 | BreakerVacuum | WS-CAP BK 4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1216 | BreakerVacuum | WS-CAP BK 4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1216 | BreakerVacuum | WS-CAP BK 4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1216 | BreakerVacuum | WS-CAP BK 4 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1216 | BreakerVacuum | WS-CAP BK 4 | VCB Readings | 9 Month Operations | 2 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0619 | BreakerAirMagnetic | MG-14KV BUS TIE SEC 5-C | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0619 | BreakerAirMagnetic | MG-14KV BUS TIE SEC 5-C | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0619 | BreakerAirMagnetic | MG-14KV BUS TIE SEC 5-C | AMCB Readings | Operations This Read AM | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0619 | BreakerAirMagnetic | MG-14KV BUS TIE SEC 5-C | AMCB Readings | Operations Counter AL | 121 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0619 | BreakerAirMagnetic | MG-14KV BUS TIE SEC 5-C | AMCB Readings | Operations Counter AF | 121 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0619 | BreakerAirMagnetic | MG-14KV BUS TIE SEC 5-C | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0619 | BreakerAirMagnetic | MG-14KV BUS TIE SEC 5-C | AMCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0619 | BreakerAirMagnetic | MG-14KV BUS TIE SEC 5-C | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0619 | BreakerAirMagnetic | MG-14KV BUS TIE SEC 5-C | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0619 | BreakerAirMagnetic | MG-14KV BUS TIE SEC 5-C | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0619 | BreakerAirMagnetic | MG-14KV BUS TIE SEC 5-C | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0619 | BreakerAirMagnetic | MG-14KV BUS TIE SEC 5-C | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0619 | BreakerAirMagnetic | MG-14KV BUS TIE SEC 5-C | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0619 | BreakerAirMagnetic | MG-14KV BUS TIE SEC 5-C | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0619 | BreakerAirMagnetic | MG-14KV BUS TIE SEC 5-C | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0619 | BreakerAirMagnetic | MG-14KV BUS TIE SEC 5-C | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0619 | BreakerAirMagnetic | MG-14KV BUS TIE SEC 5-C | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0619 | BreakerAirMagnetic | MG-14KV BUS TIE SEC 5-C | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0619 | BreakerAirMagnetic | MG-14KV BUS TIE SEC 5-C | AMCB Readings | Amps C Ø | 265.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0619 | BreakerAirMagnetic | MG-14KV BUS TIE SEC 5-C | AMCB Readings | Amps B Ø | 280.0 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | LTCMechanism | 418-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | LTCMechanism | 418-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | LTCMechanism | 418-1 | LTC Counter Readings | General Comments | | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | LTCMechanism | 418-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | LTCMechanism | 418-1 | LTC Counter Readings | LTC As Found Counter | 2717 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | LTCMechanism | 418-1 | LTC Counter Readings | LTC As Left Counter | 2724 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | LTCMechanism | 418-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | LTCMechanism | 418-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | LTCMechanism | 418-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | LTCMechanism | 418-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | LTCMechanism | 418-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | LTCMechanism | 418-1 | LTC Counter Readings | LTC Operations Since Last Insp | 166 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | LTCMechanism | 418-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | LTCMechanism | 418-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | LTCMechanism | 418-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | LTCMechanism | 418-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1190 | BreakerVacuum | WS-1331-3 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1190 | BreakerVacuum | WS-1331-3 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1190 | BreakerVacuum | WS-1331-3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1190 | BreakerVacuum | WS-1331-3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1190 | BreakerVacuum | WS-1331-3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1190 | BreakerVacuum | WS-1331-3 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1190 | BreakerVacuum | WS-1331-3 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1190 | BreakerVacuum | WS-1331-3 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1190 | BreakerVacuum | WS-1331-3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1190 | BreakerVacuum | WS-1331-3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1190 | BreakerVacuum | WS-1331-3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1190 | BreakerVacuum | WS-1331-3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1190 | BreakerVacuum | WS-1331-3 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1190 | BreakerVacuum | WS-1331-3 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1190 | BreakerVacuum | WS-1331-3 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1190 | BreakerVacuum | WS-1331-3 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1190 | BreakerVacuum | WS-1331-3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1190 | BreakerVacuum | WS-1331-3 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1190 | BreakerVacuum | WS-1331-3 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1190 | BreakerVacuum | WS-1331-3 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1190 | BreakerVacuum | WS-1331-3 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1190 | BreakerVacuum | WS-1331-3 | VCB Readings | Operations Counter AF | 54 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1190 | BreakerVacuum | WS-1331-3 | VCB Readings | Operations Counter AL | 54 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1190 | BreakerVacuum | WS-1331-3 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1190 | BreakerVacuum | WS-1331-3 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1190 | BreakerVacuum | WS-1331-3 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1232 | BreakerVacuum | WS-SEC TIE 3-4 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1232 | BreakerVacuum | WS-SEC TIE 3-4 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1232 | BreakerVacuum | WS-SEC TIE 3-4 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1232 | BreakerVacuum | WS-SEC TIE 3-4 | VCB Readings | Operations Counter AL | 197 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1232 | BreakerVacuum | WS-SEC TIE 3-4 | VCB Readings | Operations Counter AF | 197 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1232 | BreakerVacuum | WS-SEC TIE 3-4 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1232 | BreakerVacuum | WS-SEC TIE 3-4 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1232 | BreakerVacuum | WS-SEC TIE 3-4 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1232 | BreakerVacuum | WS-SEC TIE 3-4 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1232 | BreakerVacuum | WS-SEC TIE 3-4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1232 | BreakerVacuum | WS-SEC TIE 3-4 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1232 | BreakerVacuum | WS-SEC TIE 3-4 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1232 | BreakerVacuum | WS-SEC TIE 3-4 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1232 | BreakerVacuum | WS-SEC TIE 3-4 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1232 | BreakerVacuum | WS-SEC TIE 3-4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1232 | BreakerVacuum | WS-SEC TIE 3-4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1232 | BreakerVacuum | WS-SEC TIE 3-4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1232 | BreakerVacuum | WS-SEC TIE 3-4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1232 | BreakerVacuum | WS-SEC TIE 3-4 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1232 | BreakerVacuum | WS-SEC TIE 3-4 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1232 | BreakerVacuum | WS-SEC TIE 3-4 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1232 | BreakerVacuum | WS-SEC TIE 3-4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1232 | BreakerVacuum | WS-SEC TIE 3-4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1232 | BreakerVacuum | WS-SEC TIE 3-4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1232 | BreakerVacuum | WS-SEC TIE 3-4 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1232 | BreakerVacuum | WS-SEC TIE 3-4 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1196 | BreakerVacuum | WS-1337-3 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1196 | BreakerVacuum | WS-1337-3 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1213 | BreakerVacuum | WS-1322-2 | VCB Readings | Operations Counter AL | 302 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1213 | BreakerVacuum | WS-1322-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1213 | BreakerVacuum | WS-1322-2 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1213 | BreakerVacuum | WS-1322-2 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000049 | BreakerVacuum | WO-1184 | VCB Readings | 9 Month Operations | 1 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000049 | BreakerVacuum | WO-1184 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000049 | BreakerVacuum | WO-1184 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000049 | BreakerVacuum | WO-1184 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000049 | BreakerVacuum | WO-1184 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000049 | BreakerVacuum | WO-1184 | VCB Readings | Amps A Ø | 220.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000049 | BreakerVacuum | WO-1184 | VCB Readings | Amps B Ø | 220.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1182 | BreakerVacuum | WS-1315-1 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1182 | BreakerVacuum | WS-1315-1 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1182 | BreakerVacuum | WS-1315-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1182 | BreakerVacuum | WS-1315-1 | VCB Readings | Operations Counter AL | 92 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1182 | BreakerVacuum | WS-1315-1 | VCB Readings | Operations Counter AF | 92 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1182 | BreakerVacuum | WS-1315-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1182 | BreakerVacuum | WS-1315-1 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1182 | BreakerVacuum | WS-1315-1 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1182 | BreakerVacuum | WS-1315-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1182 | BreakerVacuum | WS-1315-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1182 | BreakerVacuum | WS-1315-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LTCC000482 | LTCControl | SV-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000049 | BreakerVacuum | WO-1184 | VCB Readings | Amps C Ø | 210.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000049 | BreakerVacuum | WO-1184 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000049 | BreakerVacuum | WO-1184 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000049 | BreakerVacuum | WO-1184 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000049 | BreakerVacuum | WO-1184 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000049 | BreakerVacuum | WO-1184 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000049 | BreakerVacuum | WO-1184 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000049 | BreakerVacuum | WO-1184 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000049 | BreakerVacuum | WO-1184 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000049 | BreakerVacuum | WO-1184 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000049 | BreakerVacuum | WO-1184 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000049 | BreakerVacuum | WO-1184 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000049 | BreakerVacuum | WO-1184 | VCB Readings | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000049 | BreakerVacuum | WO-1184 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000049 | BreakerVacuum | WO-1184 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000049 | BreakerVacuum | WO-1184 | VCB Readings | Operations Counter AF | 127 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000049 | BreakerVacuum | WO-1184 | VCB Readings | Operations Counter AL | 127 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000049 | BreakerVacuum | WO-1184 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000049 | BreakerVacuum | WO-1184 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000049 | BreakerVacuum | WO-1184 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000050 | BreakerVacuum | WO-1185 | VCB Readings | 9 Month Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000050 | BreakerVacuum | WO-1185 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LTCC000482 | LTCControl | SV-TRANS 1 | LTC Control Insp | General Comments | | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LTCC000482 | LTCControl | SV-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1182 | BreakerVacuum | WS-1315-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1182 | BreakerVacuum | WS-1315-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1182 | BreakerVacuum | WS-1315-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0610 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0610 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | 9 Months Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0610 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000050 | BreakerVacuum | WO-1185 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000050 | BreakerVacuum | WO-1185 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0610 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0610 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0610 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0610 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0610 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0610 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0610 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0610 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1182 | BreakerVacuum | WS-1315-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1182 | BreakerVacuum | WS-1315-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1182 | BreakerVacuum | WS-1315-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1182 | BreakerVacuum | WS-1315-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1182 | BreakerVacuum | WS-1315-1 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1182 | BreakerVacuum | WS-1315-1 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0630 | BreakerAirMagnetic | MG-417 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0630 | BreakerAirMagnetic | MG-417 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0630 | BreakerAirMagnetic | MG-417 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0630 | BreakerAirMagnetic | MG-417 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0630 | BreakerAirMagnetic | MG-417 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | BCH001573 | Charger | 481-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | BCH001573 | Charger | 481-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | BCH001573 | Charger | 481-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | BCH001573 | Charger | 481-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0630 | BreakerAirMagnetic | MG-417 | AMCB Readings | Amps C Ø | 128.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0630 | BreakerAirMagnetic | MG-417 | AMCB Readings | Amps B Ø | 97.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0630 | BreakerAirMagnetic | MG-417 | AMCB Readings | Amps A Ø | 135.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0630 | BreakerAirMagnetic | MG-417 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0630 | BreakerAirMagnetic | MG-417 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0630 | BreakerAirMagnetic | MG-417 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0630 | BreakerAirMagnetic | MG-417 | AMCB Readings | 9 Months Operations | 2 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0630 | BreakerAirMagnetic | MG-417 | AMCB Readings | 9 Month Ops New | 2 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000048 | BreakerVacuum | WO-1183 | VCB Readings | 9 Month Operations | 15 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000048 | BreakerVacuum | WO-1183 | VCB Readings | 9 Month Operations VCB New | 15 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000048 | BreakerVacuum | WO-1183 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000048 | BreakerVacuum | WO-1183 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000048 | BreakerVacuum | WO-1183 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000048 | BreakerVacuum | WO-1183 | VCB Readings | Amps A Ø | 100.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000048 | BreakerVacuum | WO-1183 | VCB Readings | Amps B Ø | 100.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000048 | BreakerVacuum | WO-1183 | VCB Readings | Amps C Ø | 190.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000048 | BreakerVacuum | WO-1183 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000048 | BreakerVacuum | WO-1183 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000048 | BreakerVacuum | WO-1183 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000048 | BreakerVacuum | WO-1183 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000048 | BreakerVacuum | WO-1183 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000048 | BreakerVacuum | WO-1183 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000048 | BreakerVacuum | WO-1183 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000048 | BreakerVacuum | WO-1183 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000048 | BreakerVacuum | WO-1183 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000048 | BreakerVacuum | WO-1183 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000048 | BreakerVacuum | WO-1183 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000048 | BreakerVacuum | WO-1183 | VCB Readings | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000048 | BreakerVacuum | WO-1183 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000048 | BreakerVacuum | WO-1183 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000048 | BreakerVacuum | WO-1183 | VCB Readings | Operations Counter AF | 169 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000048 | BreakerVacuum | WO-1183 | VCB Readings | Operations Counter AL | 169 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000048 | BreakerVacuum | WO-1183 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000048 | BreakerVacuum | WO-1183 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000048 | BreakerVacuum | WO-1183 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | BCH001573 | Charger | 481-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 0.0 | amps |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | BCH001573 | Charger | 481-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | BCH001573 | Charger | 481-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | BCH001573 | Charger | 481-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .600 | millivolts |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1213 | BreakerVacuum | WS-1322-2 | VCB Readings | 9 Month Operations | 18 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1213 | BreakerVacuum | WS-1322-2 | VCB Readings | 9 Month Operations VCB New | 18 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1213 | BreakerVacuum | WS-1322-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1213 | BreakerVacuum | WS-1322-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1213 | BreakerVacuum | WS-1322-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1213 | BreakerVacuum | WS-1322-2 | VCB Readings | Amps A Ø | 51.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1213 | BreakerVacuum | WS-1322-2 | VCB Readings | Amps B Ø | 49.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1213 | BreakerVacuum | WS-1322-2 | VCB Readings | Amps C Ø | 49.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1213 | BreakerVacuum | WS-1322-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1213 | BreakerVacuum | WS-1322-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1213 | BreakerVacuum | WS-1322-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1213 | BreakerVacuum | WS-1322-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1213 | BreakerVacuum | WS-1322-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1213 | BreakerVacuum | WS-1322-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1213 | BreakerVacuum | WS-1322-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1213 | BreakerVacuum | WS-1322-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1213 | BreakerVacuum | WS-1322-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1213 | BreakerVacuum | WS-1322-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1213 | BreakerVacuum | WS-1322-2 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1213 | BreakerVacuum | WS-1322-2 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1213 | BreakerVacuum | WS-1322-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1213 | BreakerVacuum | WS-1322-2 | VCB Readings | Operations Counter AF | 302 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000051 | BreakerVacuum | WO-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000051 | BreakerVacuum | WO-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000051 | BreakerVacuum | WO-12KV BUS TIE SEC 2 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000051 | BreakerVacuum | WO-12KV BUS TIE SEC 2 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000051 | BreakerVacuum | WO-12KV BUS TIE SEC 2 | VCB Readings | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000051 | BreakerVacuum | WO-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000051 | BreakerVacuum | WO-12KV BUS TIE SEC 2 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000051 | BreakerVacuum | WO-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AF | 155 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000051 | BreakerVacuum | WO-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AL | 155 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000051 | BreakerVacuum | WO-12KV BUS TIE SEC 2 | VCB Readings | Operations This Read Vac | 2 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000051 | BreakerVacuum | WO-12KV BUS TIE SEC 2 | VCB Readings | Switching Operations | 2 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000051 | BreakerVacuum | WO-12KV BUS TIE SEC 2 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1239 | BreakerVacuum | WS-1471-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1239 | BreakerVacuum | WS-1471-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1239 | BreakerVacuum | WS-1471-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1239 | BreakerVacuum | WS-1471-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1239 | BreakerVacuum | WS-1471-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1239 | BreakerVacuum | WS-1471-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1239 | BreakerVacuum | WS-1471-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1239 | BreakerVacuum | WS-1471-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1239 | BreakerVacuum | WS-1471-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1239 | BreakerVacuum | WS-1471-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1239 | BreakerVacuum | WS-1471-2 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1239 | BreakerVacuum | WS-1471-2 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1239 | BreakerVacuum | WS-1471-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1239 | BreakerVacuum | WS-1471-2 | VCB Readings | Operations Counter AF | 70 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1239 | BreakerVacuum | WS-1471-2 | VCB Readings | Operations Counter AL | 70 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LTCC000405 | LTCControl | WS-TRANS 3 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LTCC000405 | LTCControl | WS-TRANS 3 | LTC Control Insp | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LTCC000405 | LTCControl | WS-TRANS 3 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1239 | BreakerVacuum | WS-1471-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1239 | BreakerVacuum | WS-1471-2 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1239 | BreakerVacuum | WS-1471-2 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000052 | BreakerVacuum | WO-12KV TR 2 | VCB Readings | 9 Month Operations | 1 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000052 | BreakerVacuum | WO-12KV TR 2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000052 | BreakerVacuum | WO-12KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000052 | BreakerVacuum | WO-12KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000052 | BreakerVacuum | WO-12KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000052 | BreakerVacuum | WO-12KV TR 2 | VCB Readings | Amps A Ø | 540.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000052 | BreakerVacuum | WO-12KV TR 2 | VCB Readings | Amps B Ø | 530.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000052 | BreakerVacuum | WO-12KV TR 2 | VCB Readings | Amps C Ø | 650.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000052 | BreakerVacuum | WO-12KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000052 | BreakerVacuum | WO-12KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000052 | BreakerVacuum | WO-12KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000052 | BreakerVacuum | WO-12KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000052 | BreakerVacuum | WO-12KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000052 | BreakerVacuum | WO-12KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000052 | BreakerVacuum | WO-12KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000052 | BreakerVacuum | WO-12KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000052 | BreakerVacuum | WO-12KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000052 | BreakerVacuum | WO-12KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000052 | BreakerVacuum | WO-12KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1197 | BreakerVacuum | WS-FUTURE-5 | VCB Readings | 9 Month Operations | 5 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1197 | BreakerVacuum | WS-FUTURE-5 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1197 | BreakerVacuum | WS-FUTURE-5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1197 | BreakerVacuum | WS-FUTURE-5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1197 | BreakerVacuum | WS-FUTURE-5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1197 | BreakerVacuum | WS-FUTURE-5 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1197 | BreakerVacuum | WS-FUTURE-5 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1197 | BreakerVacuum | WS-FUTURE-5 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1197 | BreakerVacuum | WS-FUTURE-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000052 | BreakerVacuum | WO-12KV TR 2 | VCB Readings | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000052 | BreakerVacuum | WO-12KV TR 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000052 | BreakerVacuum | WO-12KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000052 | BreakerVacuum | WO-12KV TR 2 | VCB Readings | Operations Counter AF | 161 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000052 | BreakerVacuum | WO-12KV TR 2 | VCB Readings | Operations Counter AL | 161 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000052 | BreakerVacuum | WO-12KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000052 | BreakerVacuum | WO-12KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000052 | BreakerVacuum | WO-12KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BCH001209 | Charger | 439-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1182 | BreakerVacuum | WS-1315-1 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1182 | BreakerVacuum | WS-1315-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1182 | BreakerVacuum | WS-1315-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1182 | BreakerVacuum | WS-1315-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1182 | BreakerVacuum | WS-1315-1 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1182 | BreakerVacuum | WS-1315-1 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LTCC000409 | LTCControl | WS-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LTCC000409 | LTCControl | WS-TRANS 2 | LTC Control Insp | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LTCC000409 | LTCControl | WS-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0610 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0610 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0610 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0610 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0610 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0610 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0610 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000050 | BreakerVacuum | WO-1185 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000050 | BreakerVacuum | WO-1185 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000050 | BreakerVacuum | WO-1185 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000050 | BreakerVacuum | WO-1185 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000050 | BreakerVacuum | WO-1185 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000050 | BreakerVacuum | WO-1185 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000050 | BreakerVacuum | WO-1185 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000050 | BreakerVacuum | WO-1185 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000050 | BreakerVacuum | WO-1185 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0610 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0610 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0610 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0610 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Operations Counter AF | 685 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0610 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Operations Counter AL | 685 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0610 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0610 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0610 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1239 | BreakerVacuum | WS-1471-2 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1239 | BreakerVacuum | WS-1471-2 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1239 | BreakerVacuum | WS-1471-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1239 | BreakerVacuum | WS-1471-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1239 | BreakerVacuum | WS-1471-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1239 | BreakerVacuum | WS-1471-2 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1239 | BreakerVacuum | WS-1471-2 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000050 | BreakerVacuum | WO-1185 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000050 | BreakerVacuum | WO-1185 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000050 | BreakerVacuum | WO-1185 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000050 | BreakerVacuum | WO-1185 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000050 | BreakerVacuum | WO-1185 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000050 | BreakerVacuum | WO-1185 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000050 | BreakerVacuum | WO-1185 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1239 | BreakerVacuum | WS-1471-2 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000050 | BreakerVacuum | WO-1185 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000050 | BreakerVacuum | WO-1185 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000050 | BreakerVacuum | WO-1185 | VCB Readings | Operations Counter AF | 147 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000050 | BreakerVacuum | WO-1185 | VCB Readings | Operations Counter AL | 147 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000050 | BreakerVacuum | WO-1185 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000050 | BreakerVacuum | WO-1185 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000050 | BreakerVacuum | WO-1185 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000051 | BreakerVacuum | WO-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000051 | BreakerVacuum | WO-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000051 | BreakerVacuum | WO-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000051 | BreakerVacuum | WO-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000051 | BreakerVacuum | WO-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000051 | BreakerVacuum | WO-12KV BUS TIE SEC 2 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000051 | BreakerVacuum | WO-12KV BUS TIE SEC 2 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000051 | BreakerVacuum | WO-12KV BUS TIE SEC 2 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000051 | BreakerVacuum | WO-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000051 | BreakerVacuum | WO-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000051 | BreakerVacuum | WO-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000051 | BreakerVacuum | WO-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000051 | BreakerVacuum | WO-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000051 | BreakerVacuum | WO-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000051 | BreakerVacuum | WO-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1209 | BreakerVacuum | WS-1305-2 | VCB Readings | 9 Month Operations | 8 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | LTCMechanism | JT-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | LTCMechanism | JT-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | LTCMechanism | JT-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | LTCMechanism | JT-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | LTCMechanism | JT-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 140 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | LTCMechanism | JT-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 8 | °C |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | LTCMechanism | JT-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 31 | °C |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | LTCMechanism | JT-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | LTCMechanism | JT-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | LTCMechanism | JT-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | LTCMechanism | JT-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | LTCMechanism | JT-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | LTCMechanism | JT-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 26214 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | LTCMechanism | JT-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 26214 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | LTCMechanism | JT-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | LTCMechanism | JT-TRANS 1 | LTC Counter Readings | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | LTCMechanism | JT-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LT0314 | LTCMechanism | JT-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | LTCMechanism | 736-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | LTCMechanism | 736-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | LTCMechanism | 736-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | LTCMechanism | 736-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | LTCMechanism | 736-1 | LTC Counter Readings | LTC Operations Since Last Insp | 259 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | LTCMechanism | 736-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | LTCMechanism | 736-1 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | LTCMechanism | 736-1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | LTCMechanism | 736-1 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | LTCMechanism | 736-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | LTCMechanism | 736-1 | LTC Counter Readings | LTC As Left Counter | 15774 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | LTCMechanism | 736-1 | LTC Counter Readings | LTC As Found Counter | 15767 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | LTCMechanism | 736-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | LTCMechanism | 736-1 | LTC Counter Readings | General Comments | | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | LTCMechanism | 736-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | C0471 | LTCMechanism | 736-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | LTCC000746 | LTCControl | 641-1 | LTC Control Insp | All Connections OK? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | LTCC000746 | LTCControl | 641-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | LTCC000746 | LTCControl | 641-1 | LTC Control Insp | General Comments | | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | LTCC000746 | LTCControl | 641-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | LTCC000746 | LTCControl | 641-1 | LTC Control Insp | LTC Output Voltage Level | 124.6 | VAC |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | LTCC000746 | LTCControl | 641-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | LTCC000746 | LTCControl | 641-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | LTCC000746 | LTCControl | 641-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | LTCC000748 | LTCControl | 736-1 | LTC Control Insp | All Connections OK? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | LTCC000748 | LTCControl | 736-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | LTCC000748 | LTCControl | 736-1 | LTC Control Insp | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | LTCC000748 | LTCControl | 736-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | LTCC000748 | LTCControl | 736-1 | LTC Control Insp | LTC Output Voltage Level | 124.4 | VAC |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | LTCC000748 | LTCControl | 736-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | LTCC000748 | LTCControl | 736-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | LTCC000748 | LTCControl | 736-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | LTCC000748 | LTCControl | 736-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000073 | LTCMechanism | MG-TRANS 5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000073 | LTCMechanism | MG-TRANS 5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000073 | LTCMechanism | MG-TRANS 5 | LTC Counter Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000073 | LTCMechanism | MG-TRANS 5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000073 | LTCMechanism | MG-TRANS 5 | LTC Counter Readings | LTC As Found Counter | 17343 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000073 | LTCMechanism | MG-TRANS 5 | LTC Counter Readings | LTC As Left Counter | 17343 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000073 | LTCMechanism | MG-TRANS 5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000073 | LTCMechanism | MG-TRANS 5 | LTC Counter Readings | LTC Current Tap Position | 4R | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000073 | LTCMechanism | MG-TRANS 5 | LTC Counter Readings | LTC Max Tap Position | 7R | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000073 | LTCMechanism | MG-TRANS 5 | LTC Counter Readings | LTC Min Tap Position | Neutral | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000073 | LTCMechanism | MG-TRANS 5 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000073 | LTCMechanism | MG-TRANS 5 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 39 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000073 | LTCMechanism | MG-TRANS 5 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 18 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000073 | LTCMechanism | MG-TRANS 5 | LTC Counter Readings | LTC Operations Since Last Insp | 367 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000073 | LTCMechanism | MG-TRANS 5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000073 | LTCMechanism | MG-TRANS 5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LTCM000073 | LTCMechanism | MG-TRANS 5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1209 | BreakerVacuum | WS-1305-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1193 | BreakerVacuum | WS-1334-3 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1193 | BreakerVacuum | WS-1334-3 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1193 | BreakerVacuum | WS-1334-3 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1193 | BreakerVacuum | WS-1334-3 | VCB Readings | Operations Counter AF | 161 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1193 | BreakerVacuum | WS-1334-3 | VCB Readings | Operations Counter AL | 161 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1193 | BreakerVacuum | WS-1334-3 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1193 | BreakerVacuum | WS-1334-3 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1193 | BreakerVacuum | WS-1334-3 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000211 | Switchgear | MK-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000211 | Switchgear | MK-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000211 | Switchgear | MK-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000211 | Switchgear | MK-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000211 | Switchgear | MK-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000211 | Switchgear | MK-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000211 | Switchgear | MK-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000211 | Switchgear | MK-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000211 | Switchgear | MK-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000211 | Switchgear | MK-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000211 | Switchgear | MK-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000211 | Switchgear | MK-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1209 | BreakerVacuum | WS-1305-2 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1209 | BreakerVacuum | WS-1305-2 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1209 | BreakerVacuum | WS-1305-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1209 | BreakerVacuum | WS-1305-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1209 | BreakerVacuum | WS-1305-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1209 | BreakerVacuum | WS-1305-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1209 | BreakerVacuum | WS-1305-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1209 | BreakerVacuum | WS-1305-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | BAT001274 | Battery | Retired Distribution | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | BAT001274 | Battery | Retired Distribution | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | BAT001274 | Battery | Retired Distribution | Battery Patrol Inspection | Positive DC Ground | 26.5 | VDC |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | BAT001274 | Battery | Retired Distribution | Battery Patrol Inspection | Negative DC Ground | 28.1 | VDC |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | BAT001274 | Battery | Retired Distribution | Battery Patrol Inspection | General Comments | | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | BAT001274 | Battery | Retired Distribution | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | BAT001274 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000211 | Switchgear | MK-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000211 | Switchgear | MK-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000211 | Switchgear | MK-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000211 | Switchgear | MK-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | BAT001274 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | BAT001274 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | BAT001274 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | BAT001274 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Area Ambient Temp | 4627 | °F |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | BAT001274 | Battery | Retired Distribution | Battery Patrol Inspection | All Connections OK? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | BCH001218 | Charger | 497-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | BCH001218 | Charger | 497-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | BCH001218 | Charger | 497-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | BCH001218 | Charger | 497-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | BCH001218 | Charger | 497-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | BCH001218 | Charger | 497-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | BCH001218 | Charger | 497-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | BCH001218 | Charger | 497-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .700 | millivolts |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1209 | BreakerVacuum | WS-1305-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1209 | BreakerVacuum | WS-1305-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1209 | BreakerVacuum | WS-1305-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1209 | BreakerVacuum | WS-1305-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1209 | BreakerVacuum | WS-1305-2 | VCB Readings | Amps C Ø | 36.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1209 | BreakerVacuum | WS-1305-2 | VCB Readings | Amps B Ø | 33.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1209 | BreakerVacuum | WS-1305-2 | VCB Readings | Amps A Ø | 33.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1209 | BreakerVacuum | WS-1305-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000211 | Switchgear | MK-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000211 | Switchgear | MK-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | SWG000211 | Switchgear | MK-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LTCC000388 | LTCControl | WO-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LTCC000388 | LTCControl | WO-TRANS 1 | LTC Control Insp | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LTCC000388 | LTCControl | WO-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1209 | BreakerVacuum | WS-1305-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1209 | BreakerVacuum | WS-1305-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1209 | BreakerVacuum | WS-1305-2 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000046 | BreakerVacuum | WO-1181 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000046 | BreakerVacuum | WO-1181 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000046 | BreakerVacuum | WO-1181 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000046 | BreakerVacuum | WO-1181 | VCB Readings | Amps A Ø | 70.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000046 | BreakerVacuum | WO-1181 | VCB Readings | Amps B Ø | 40.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000046 | BreakerVacuum | WO-1181 | VCB Readings | Amps C Ø | 45.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000046 | BreakerVacuum | WO-1181 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000046 | BreakerVacuum | WO-1181 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000046 | BreakerVacuum | WO-1181 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000046 | BreakerVacuum | WO-1181 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000046 | BreakerVacuum | WO-1181 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000046 | BreakerVacuum | WO-1181 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000046 | BreakerVacuum | WO-1181 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000046 | BreakerVacuum | WO-1181 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000046 | BreakerVacuum | WO-1181 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000046 | BreakerVacuum | WO-1181 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000046 | BreakerVacuum | WO-1181 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000046 | BreakerVacuum | WO-1181 | VCB Readings | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000046 | BreakerVacuum | WO-1181 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000046 | BreakerVacuum | WO-1181 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000046 | BreakerVacuum | WO-1181 | VCB Readings | Operations Counter AF | 228 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000046 | BreakerVacuum | WO-1181 | VCB Readings | Operations Counter AL | 228 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000046 | BreakerVacuum | WO-1181 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000046 | BreakerVacuum | WO-1181 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000046 | BreakerVacuum | WO-1181 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000047 | BreakerVacuum | WO-1182 | VCB Readings | 9 Month Operations | 2 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000047 | BreakerVacuum | WO-1182 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000047 | BreakerVacuum | WO-1182 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000047 | BreakerVacuum | WO-1182 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF001351 | PowerFuse | MG-14KV TR 7 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF001351 | PowerFuse | MG-14KV TR 7 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF001351 | PowerFuse | MG-14KV TR 7 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF001350 | PowerFuse | MG-14KV TR 6 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF001350 | PowerFuse | MG-14KV TR 6 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF001350 | PowerFuse | MG-14KV TR 6 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF001349 | PowerFuse | MG-14KV BUS SEC C POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF001349 | PowerFuse | MG-14KV BUS SEC C POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000047 | BreakerVacuum | WO-1182 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000047 | BreakerVacuum | WO-1182 | VCB Readings | Amps A Ø | 170.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000047 | BreakerVacuum | WO-1182 | VCB Readings | Amps B Ø | 200.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000047 | BreakerVacuum | WO-1182 | VCB Readings | Amps C Ø | 190.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000047 | BreakerVacuum | WO-1182 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000047 | BreakerVacuum | WO-1182 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000047 | BreakerVacuum | WO-1182 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000047 | BreakerVacuum | WO-1182 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF001349 | PowerFuse | MG-14KV BUS SEC C POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000047 | BreakerVacuum | WO-1182 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000047 | BreakerVacuum | WO-1182 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000047 | BreakerVacuum | WO-1182 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000047 | BreakerVacuum | WO-1182 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000047 | BreakerVacuum | WO-1182 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000047 | BreakerVacuum | WO-1182 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000047 | BreakerVacuum | WO-1182 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000047 | BreakerVacuum | WO-1182 | VCB Readings | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000047 | BreakerVacuum | WO-1182 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000047 | BreakerVacuum | WO-1182 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000047 | BreakerVacuum | WO-1182 | VCB Readings | Operations Counter AF | 155 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000047 | BreakerVacuum | WO-1182 | VCB Readings | Operations Counter AL | 155 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000047 | BreakerVacuum | WO-1182 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000047 | BreakerVacuum | WO-1182 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000047 | BreakerVacuum | WO-1182 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0630 | BreakerAirMagnetic | MG-417 | AMCB Readings | Operations Counter AF | 454 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0630 | BreakerAirMagnetic | MG-417 | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0630 | BreakerAirMagnetic | MG-417 | AMCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0630 | BreakerAirMagnetic | MG-417 | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0630 | BreakerAirMagnetic | MG-417 | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0630 | BreakerAirMagnetic | MG-417 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0630 | BreakerAirMagnetic | MG-417 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0630 | BreakerAirMagnetic | MG-417 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0630 | BreakerAirMagnetic | MG-417 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Present | 29 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Max | 45 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Present | 29 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Max | 45 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Present | 29 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Max | 45 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Readings | Oil Temp Present | 28 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Readings | Oil Temp Max | 43 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1200 | psi |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1246 | BreakerVacuum | WS-1337-4 | VCB Readings | 9 Month Operations | 6 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1246 | BreakerVacuum | WS-1337-4 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1246 | BreakerVacuum | WS-1337-4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1246 | BreakerVacuum | WS-1337-4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1246 | BreakerVacuum | WS-1337-4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1246 | BreakerVacuum | WS-1337-4 | VCB Readings | Amps A Ø | 70.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1246 | BreakerVacuum | WS-1337-4 | VCB Readings | Amps B Ø | 69.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1246 | BreakerVacuum | WS-1337-4 | VCB Readings | Amps C Ø | 70.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1246 | BreakerVacuum | WS-1337-4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1246 | BreakerVacuum | WS-1337-4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1246 | BreakerVacuum | WS-1337-4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1246 | BreakerVacuum | WS-1337-4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1246 | BreakerVacuum | WS-1337-4 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1246 | BreakerVacuum | WS-1337-4 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1246 | BreakerVacuum | WS-1337-4 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1246 | BreakerVacuum | WS-1337-4 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1246 | BreakerVacuum | WS-1337-4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1246 | BreakerVacuum | WS-1337-4 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1246 | BreakerVacuum | WS-1337-4 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1246 | BreakerVacuum | WS-1337-4 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1246 | BreakerVacuum | WS-1337-4 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1246 | BreakerVacuum | WS-1337-4 | VCB Readings | Operations Counter AF | 127 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1246 | BreakerVacuum | WS-1337-4 | VCB Readings | Operations Counter AL | 127 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1246 | BreakerVacuum | WS-1337-4 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1246 | BreakerVacuum | WS-1337-4 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1246 | BreakerVacuum | WS-1337-4 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0285 | WithLTC | WS-TRANS 3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0630 | BreakerAirMagnetic | MG-417 | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0630 | BreakerAirMagnetic | MG-417 | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0630 | BreakerAirMagnetic | MG-417 | AMCB Readings | Operations This Read AM | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0630 | BreakerAirMagnetic | MG-417 | AMCB Readings | Operations Counter AL | 454 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000046 | BreakerVacuum | WO-1181 | VCB Readings | 9 Month Operations | 7 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | BK000046 | BreakerVacuum | WO-1181 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1203 | BreakerVacuum | WS-1472-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1203 | BreakerVacuum | WS-1472-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1203 | BreakerVacuum | WS-1472-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1203 | BreakerVacuum | WS-1472-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1203 | BreakerVacuum | WS-1472-2 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1203 | BreakerVacuum | WS-1472-2 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1203 | BreakerVacuum | WS-1472-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1203 | BreakerVacuum | WS-1472-2 | VCB Readings | Operations Counter AF | 130 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1203 | BreakerVacuum | WS-1472-2 | VCB Readings | Operations Counter AL | 130 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1203 | BreakerVacuum | WS-1472-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1203 | BreakerVacuum | WS-1472-2 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1203 | BreakerVacuum | WS-1472-2 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1176 | BreakerVacuum | WS-1303-1 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1176 | BreakerVacuum | WS-1303-1 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1176 | BreakerVacuum | WS-1303-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1176 | BreakerVacuum | WS-1303-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1176 | BreakerVacuum | WS-1303-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1176 | BreakerVacuum | WS-1303-1 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1176 | BreakerVacuum | WS-1303-1 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1176 | BreakerVacuum | WS-1303-1 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1176 | BreakerVacuum | WS-1303-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1176 | BreakerVacuum | WS-1303-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1176 | BreakerVacuum | WS-1303-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1176 | BreakerVacuum | WS-1303-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1176 | BreakerVacuum | WS-1303-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1176 | BreakerVacuum | WS-1303-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | n | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1176 | BreakerVacuum | WS-1303-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1176 | BreakerVacuum | WS-1303-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1176 | BreakerVacuum | WS-1303-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1176 | BreakerVacuum | WS-1303-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1176 | BreakerVacuum | WS-1303-1 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1176 | BreakerVacuum | WS-1303-1 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1176 | BreakerVacuum | WS-1303-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1176 | BreakerVacuum | WS-1303-1 | VCB Readings | Operations Counter AF | 94 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1176 | BreakerVacuum | WS-1303-1 | VCB Readings | Operations Counter AL | 94 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1176 | BreakerVacuum | WS-1303-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Readings | General Comments | | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Patrol Inspection | General Comments | needs new fan controls | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1380.48 | kw |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 152.50 | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 145.00 | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Readings | Oil Temp Max | 75 | °C |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1600 | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | C0334 | NonLTC | 815-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .8628 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0641 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | 9 Month Ops New | 1 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0641 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | 9 Months Operations | 1 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0641 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1244 | BreakerVacuum | WS-1335-4 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1244 | BreakerVacuum | WS-1335-4 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1244 | BreakerVacuum | WS-1335-4 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1244 | BreakerVacuum | WS-1335-4 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1244 | BreakerVacuum | WS-1335-4 | VCB Readings | Operations Counter AF | 187 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1244 | BreakerVacuum | WS-1335-4 | VCB Readings | Operations Counter AL | 187 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1244 | BreakerVacuum | WS-1335-4 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1244 | BreakerVacuum | WS-1335-4 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1244 | BreakerVacuum | WS-1335-4 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | YD000312 | Yard | 686-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | YD000312 | Yard | 686-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | YD000312 | Yard | 686-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | YD000312 | Yard | 686-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | YD000312 | Yard | 686-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | YD000312 | Yard | 686-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | YD000312 | Yard | 686-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | YD000312 | Yard | 686-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | YD000312 | Yard | 686-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | YD000312 | Yard | 686-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Readings | Operations This Read Vac | 1 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Readings | Operations Counter AL | 212 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Readings | Operations Counter AF | 212 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Readings | Maintenance Operations | 1 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Readings | General Comments | | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Readings | Amps C Ø | 43.0 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Readings | Amps B Ø | 21.0 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Readings | Amps A Ø | 20.0 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | KB0134 | BreakerVacuum | 467-1914 | VCB Readings | 9 Month Operations | 4 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1203 | BreakerVacuum | WS-1472-2 | VCB Readings | 9 Month Operations | 4 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1203 | BreakerVacuum | WS-1472-2 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1203 | BreakerVacuum | WS-1472-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1203 | BreakerVacuum | WS-1472-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1203 | BreakerVacuum | WS-1472-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1203 | BreakerVacuum | WS-1472-2 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1203 | BreakerVacuum | WS-1472-2 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1203 | BreakerVacuum | WS-1472-2 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1203 | BreakerVacuum | WS-1472-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1203 | BreakerVacuum | WS-1472-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1203 | BreakerVacuum | WS-1472-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1203 | BreakerVacuum | WS-1472-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1203 | BreakerVacuum | WS-1472-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1203 | BreakerVacuum | WS-1472-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1229 | BreakerVacuum | WS-1429-4 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1229 | BreakerVacuum | WS-1429-4 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1229 | BreakerVacuum | WS-1429-4 | VCB Readings | Operations Counter AF | 66 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1229 | BreakerVacuum | WS-1429-4 | VCB Readings | Operations Counter AL | 66 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1229 | BreakerVacuum | WS-1429-4 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1229 | BreakerVacuum | WS-1429-4 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1229 | BreakerVacuum | WS-1429-4 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1000 | psi |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 39 | °C |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 24 | °C |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 34 | °C |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 24 | °C |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 39 | °C |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 25 | °C |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 39 | °C |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0315 | WithLTC | WO-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 25 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1400 | psi |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Readings | Oil Temp Max | 39 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Readings | Oil Temp Present | 26 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0286 | WithLTC | WS-TRANS 4 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0641 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0641 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0641 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0641 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0641 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0641 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0641 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0641 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0641 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0641 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0641 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0641 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0641 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0641 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0641 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0641 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0641 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0641 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0641 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Operations Counter AF | 488 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0641 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Operations Counter AL | 488 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0641 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0641 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0641 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1237 | BreakerVacuum | WS-1471-1 | VCB Readings | 9 Month Operations | 4 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1237 | BreakerVacuum | WS-1471-1 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1237 | BreakerVacuum | WS-1471-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1237 | BreakerVacuum | WS-1471-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1237 | BreakerVacuum | WS-1471-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1237 | BreakerVacuum | WS-1471-1 | VCB Readings | Amps A Ø | 118.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1237 | BreakerVacuum | WS-1471-1 | VCB Readings | Amps B Ø | 119.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1237 | BreakerVacuum | WS-1471-1 | VCB Readings | Amps C Ø | 118.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1237 | BreakerVacuum | WS-1471-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1237 | BreakerVacuum | WS-1471-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1237 | BreakerVacuum | WS-1471-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1237 | BreakerVacuum | WS-1471-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1237 | BreakerVacuum | WS-1471-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1237 | BreakerVacuum | WS-1471-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1237 | BreakerVacuum | WS-1471-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1237 | BreakerVacuum | WS-1471-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1176 | BreakerVacuum | WS-1303-1 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1176 | BreakerVacuum | WS-1303-1 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1229 | BreakerVacuum | WS-1429-4 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1229 | BreakerVacuum | WS-1429-4 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1229 | BreakerVacuum | WS-1429-4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1229 | BreakerVacuum | WS-1429-4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1229 | BreakerVacuum | WS-1429-4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1229 | BreakerVacuum | WS-1429-4 | VCB Readings | Amps A Ø | 87.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1229 | BreakerVacuum | WS-1429-4 | VCB Readings | Amps B Ø | 85.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1229 | BreakerVacuum | WS-1429-4 | VCB Readings | Amps C Ø | 84.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1229 | BreakerVacuum | WS-1429-4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1229 | BreakerVacuum | WS-1429-4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1229 | BreakerVacuum | WS-1429-4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1229 | BreakerVacuum | WS-1429-4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1229 | BreakerVacuum | WS-1429-4 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1229 | BreakerVacuum | WS-1429-4 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1229 | BreakerVacuum | WS-1429-4 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1229 | BreakerVacuum | WS-1429-4 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1229 | BreakerVacuum | WS-1429-4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1229 | BreakerVacuum | WS-1429-4 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1229 | BreakerVacuum | WS-1429-4 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1202 | BreakerVacuum | WS-1429-3 | VCB Readings | 9 Month Operations | 4 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1202 | BreakerVacuum | WS-1429-3 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1202 | BreakerVacuum | WS-1429-3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1202 | BreakerVacuum | WS-1429-3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1202 | BreakerVacuum | WS-1429-3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1202 | BreakerVacuum | WS-1429-3 | VCB Readings | Amps A Ø | 86.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1202 | BreakerVacuum | WS-1429-3 | VCB Readings | Amps B Ø | 88.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1202 | BreakerVacuum | WS-1429-3 | VCB Readings | Amps C Ø | 84.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1202 | BreakerVacuum | WS-1429-3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1197 | BreakerVacuum | WS-FUTURE-5 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1197 | BreakerVacuum | WS-FUTURE-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1197 | BreakerVacuum | WS-FUTURE-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1197 | BreakerVacuum | WS-FUTURE-5 | VCB Readings | Fault Operations Ground | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1197 | BreakerVacuum | WS-FUTURE-5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1197 | BreakerVacuum | WS-FUTURE-5 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1197 | BreakerVacuum | WS-FUTURE-5 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1197 | BreakerVacuum | WS-FUTURE-5 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1197 | BreakerVacuum | WS-FUTURE-5 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1197 | BreakerVacuum | WS-FUTURE-5 | VCB Readings | Operations Counter AF | 154 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1197 | BreakerVacuum | WS-FUTURE-5 | VCB Readings | Operations Counter AL | 154 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1197 | BreakerVacuum | WS-FUTURE-5 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1197 | BreakerVacuum | WS-FUTURE-5 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1197 | BreakerVacuum | WS-FUTURE-5 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1202 | BreakerVacuum | WS-1429-3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1202 | BreakerVacuum | WS-1429-3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1202 | BreakerVacuum | WS-1429-3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1202 | BreakerVacuum | WS-1429-3 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1202 | BreakerVacuum | WS-1429-3 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1202 | BreakerVacuum | WS-1429-3 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1202 | BreakerVacuum | WS-1429-3 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1202 | BreakerVacuum | WS-1429-3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1202 | BreakerVacuum | WS-1429-3 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1202 | BreakerVacuum | WS-1429-3 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1202 | BreakerVacuum | WS-1429-3 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1202 | BreakerVacuum | WS-1429-3 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1202 | BreakerVacuum | WS-1429-3 | VCB Readings | Operations Counter AF | 191 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1202 | BreakerVacuum | WS-1429-3 | VCB Readings | Operations Counter AL | 191 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1202 | BreakerVacuum | WS-1429-3 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1202 | BreakerVacuum | WS-1429-3 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1202 | BreakerVacuum | WS-1429-3 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Readings | General Comments | | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1622.40 | kw |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Readings | Oil Temp Max | 59 | °C |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Readings | Oil Temp Present | 22 | °C |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | C0339 | NonLTC | 771-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .5070 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | LTCMechanism | 497-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BCH001209 | Charger | 439-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BCH001209 | Charger | 439-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.0 | amps |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BCH001209 | Charger | 439-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BCH001209 | Charger | 439-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Readings | Operations This Read Vac | 3 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Readings | Operations Counter AL | 13 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Readings | Operations Counter AF | 13 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Readings | Maintenance Operations | 1 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Readings | General Comments | | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Readings | Fault Operations C Ø | 2 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Readings | Fault Adjusted Amps C Phase V | 17.83 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Readings | Amps C Ø | 5.0 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Readings | Amps B Ø | 5.0 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Readings | Amps A Ø | 5.0 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | K0068 | BreakerVacuum | 418-1329 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0607 | BreakerAirMagnetic | MG-1329 | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0607 | BreakerAirMagnetic | MG-1329 | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0607 | BreakerAirMagnetic | MG-1329 | AMCB Readings | Operations This Read AM | 2 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0607 | BreakerAirMagnetic | MG-1329 | AMCB Readings | Operations Counter AL | 146 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0607 | BreakerAirMagnetic | MG-1329 | AMCB Readings | Operations Counter AF | 146 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0607 | BreakerAirMagnetic | MG-1329 | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0607 | BreakerAirMagnetic | MG-1329 | AMCB Readings | General Comments | VC not working | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0607 | BreakerAirMagnetic | MG-1329 | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0607 | BreakerAirMagnetic | MG-1329 | AMCB Readings | Follow-up Action Required? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0607 | BreakerAirMagnetic | MG-1329 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0607 | BreakerAirMagnetic | MG-1329 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0607 | BreakerAirMagnetic | MG-1329 | AMCB Readings | Fault Operations C Ø | 1 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0607 | BreakerAirMagnetic | MG-1329 | AMCB Readings | Fault Operations B Ø | 1 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0607 | BreakerAirMagnetic | MG-1329 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0607 | BreakerAirMagnetic | MG-1329 | AMCB Readings | Fault Adjusted Amps C Phase AM | 11.18 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0607 | BreakerAirMagnetic | MG-1329 | AMCB Readings | Fault Adjusted Amps B Phase AM | 11.18 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0607 | BreakerAirMagnetic | MG-1329 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0607 | BreakerAirMagnetic | MG-1329 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0607 | BreakerAirMagnetic | MG-1329 | AMCB Readings | Amps C Ø | 118.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1197 | BreakerVacuum | WS-FUTURE-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1197 | BreakerVacuum | WS-FUTURE-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1197 | BreakerVacuum | WS-FUTURE-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0607 | BreakerAirMagnetic | MG-1329 | AMCB Readings | Amps B Ø | 122.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0607 | BreakerAirMagnetic | MG-1329 | AMCB Readings | Amps A Ø | 117.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0607 | BreakerAirMagnetic | MG-1329 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0607 | BreakerAirMagnetic | MG-1329 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0607 | BreakerAirMagnetic | MG-1329 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0607 | BreakerAirMagnetic | MG-1329 | AMCB Readings | 9 Months Operations | 2 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0607 | BreakerAirMagnetic | MG-1329 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000568 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | 9 Month Operations | 6 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1175 | BreakerVacuum | WS-1475-1 | VCB Readings | 9 Month Operations | 4 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1175 | BreakerVacuum | WS-1475-1 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1175 | BreakerVacuum | WS-1475-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1175 | BreakerVacuum | WS-1475-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1175 | BreakerVacuum | WS-1475-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1175 | BreakerVacuum | WS-1475-1 | VCB Readings | Amps A Ø | 123.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1175 | BreakerVacuum | WS-1475-1 | VCB Readings | Amps B Ø | 122.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1175 | BreakerVacuum | WS-1475-1 | VCB Readings | Amps C Ø | 122.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1175 | BreakerVacuum | WS-1475-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1175 | BreakerVacuum | WS-1475-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1175 | BreakerVacuum | WS-1475-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1175 | BreakerVacuum | WS-1475-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1175 | BreakerVacuum | WS-1475-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1175 | BreakerVacuum | WS-1475-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1175 | BreakerVacuum | WS-1475-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1175 | BreakerVacuum | WS-1475-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1175 | BreakerVacuum | WS-1475-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1175 | BreakerVacuum | WS-1475-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1175 | BreakerVacuum | WS-1475-1 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1175 | BreakerVacuum | WS-1475-1 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1175 | BreakerVacuum | WS-1475-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1175 | BreakerVacuum | WS-1475-1 | VCB Readings | Operations Counter AF | 102 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1175 | BreakerVacuum | WS-1475-1 | VCB Readings | Operations Counter AL | 102 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1175 | BreakerVacuum | WS-1475-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1175 | BreakerVacuum | WS-1475-1 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1175 | BreakerVacuum | WS-1475-1 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | ST000319 | Structure | 686-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | ST000319 | Structure | 686-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | ST000319 | Structure | 686-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | ST000319 | Structure | 686-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | ST000319 | Structure | 686-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | ST000319 | Structure | 686-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | ST000319 | Structure | 686-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | ST000319 | Structure | 686-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | ST000319 | Structure | 686-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | ST000319 | Structure | 686-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | ST000319 | Structure | 686-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | ST000319 | Structure | 686-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | ST000319 | Structure | 686-Structure | Structure Patrol Inspection | General Comments | | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | ST000319 | Structure | 686-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | ST000319 | Structure | 686-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | ST000319 | Structure | 686-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | ST000319 | Structure | 686-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | ST000319 | Structure | 686-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | ST000319 | Structure | 686-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | ST000319 | Structure | 686-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | ST000319 | Structure | 686-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | ST000319 | Structure | 686-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | YD000312 | Yard | 686-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | YD000312 | Yard | 686-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | YD000312 | Yard | 686-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | YD000312 | Yard | 686-Yard | Yard Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1244 | BreakerVacuum | WS-1335-4 | VCB Readings | 9 Month Operations | 6 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1244 | BreakerVacuum | WS-1335-4 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1244 | BreakerVacuum | WS-1335-4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1244 | BreakerVacuum | WS-1335-4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1244 | BreakerVacuum | WS-1335-4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1244 | BreakerVacuum | WS-1335-4 | VCB Readings | Amps A Ø | 69.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1244 | BreakerVacuum | WS-1335-4 | VCB Readings | Amps B Ø | 65.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1244 | BreakerVacuum | WS-1335-4 | VCB Readings | Amps C Ø | 68.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1244 | BreakerVacuum | WS-1335-4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1244 | BreakerVacuum | WS-1335-4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1244 | BreakerVacuum | WS-1335-4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1244 | BreakerVacuum | WS-1335-4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1244 | BreakerVacuum | WS-1335-4 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1244 | BreakerVacuum | WS-1335-4 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1244 | BreakerVacuum | WS-1335-4 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1244 | BreakerVacuum | WS-1335-4 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1244 | BreakerVacuum | WS-1335-4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | LTCMechanism | 497-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | LTCMechanism | 497-1 | LTC Counter Readings | General Comments | | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | LTCMechanism | 497-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | LTCMechanism | 497-1 | LTC Counter Readings | LTC As Found Counter | 13176 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | LTCMechanism | 497-1 | LTC Counter Readings | LTC As Left Counter | 13182 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | LTCMechanism | 497-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | LTCMechanism | 497-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | LTCMechanism | 497-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | LTCMechanism | 497-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | LTCMechanism | 497-1 | LTC Counter Readings | LTC Operations Since Last Insp | 317 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | LTCMechanism | 497-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | LTCMechanism | 497-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | W0357 | LTCMechanism | 497-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | LTCMechanism | 686-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | LTCMechanism | 686-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | LTCMechanism | 686-2 | LTC Counter Readings | General Comments | | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | LTCMechanism | 686-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | LTCMechanism | 686-2 | LTC Counter Readings | LTC As Found Counter | 13442 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | LTCMechanism | 686-2 | LTC Counter Readings | LTC As Left Counter | 13442 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | LTCMechanism | 686-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | LTCMechanism | 686-2 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | LTCMechanism | 686-2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | LTCMechanism | 686-2 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | LTCMechanism | 686-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | LTCMechanism | 686-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | LTCMechanism | 686-2 | LTC Counter Readings | LTC Operations Since Last Insp | 401 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | LTCMechanism | 686-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | LTCMechanism | 686-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | LTCMechanism | 686-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | C0430 | LTCMechanism | 686-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | YD000227 | Yard | 497-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | YD000227 | Yard | 497-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | YD000227 | Yard | 497-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | YD000227 | Yard | 497-Yard | Yard Patrol Inspection | General Comments | | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | YD000227 | Yard | 497-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | YD000227 | Yard | 497-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | YD000227 | Yard | 497-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | YD000227 | Yard | 497-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | YD000227 | Yard | 497-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | YD000227 | Yard | 497-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | YD000227 | Yard | 497-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | YD000227 | Yard | 497-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | YD000227 | Yard | 497-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | YD000227 | Yard | 497-Yard | Yard Patrol Inspection | Ambient Temp | 46 | °F |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000568 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000568 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000568 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000568 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Operations Counter AL | 314 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000568 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Operations Counter AF | 314 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000568 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000568 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000568 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000568 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000568 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000568 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000568 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000568 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000568 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000568 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000568 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000568 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000568 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000568 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000568 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000568 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000568 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000568 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000568 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000568 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000568 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | 9 Month Operations VCB New | 6 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0117 | NonLTC | MG-TRANS 1 C PHASE | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 270.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0117 | NonLTC | MG-TRANS 1 C PHASE | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0117 | NonLTC | MG-TRANS 1 C PHASE | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0117 | NonLTC | MG-TRANS 1 C PHASE | NonLTC Transformer Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0117 | NonLTC | MG-TRANS 1 C PHASE | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0117 | NonLTC | MG-TRANS 1 C PHASE | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0117 | NonLTC | MG-TRANS 1 C PHASE | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0117 | NonLTC | MG-TRANS 1 C PHASE | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0117 | NonLTC | MG-TRANS 1 C PHASE | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0117 | NonLTC | MG-TRANS 1 C PHASE | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0117 | NonLTC | MG-TRANS 1 C PHASE | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0117 | NonLTC | MG-TRANS 1 C PHASE | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | LTCMechanism | WO-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | LTCMechanism | WO-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | LTCMechanism | WO-TRANS 1 | LTC Counter Readings | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | LTCMechanism | WO-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | LTCMechanism | WO-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 102977 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | LTCMechanism | WO-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 102977 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | LTCMechanism | WO-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | LTCMechanism | WO-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | LTCMechanism | WO-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | LTCMechanism | WO-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | LTCMechanism | WO-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | LTCMechanism | WO-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 403 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | LTCMechanism | WO-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | LTCMechanism | WO-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | LTCMechanism | WO-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | LTCMechanism | WO-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Readings | 9 Month Operations | 2 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Readings | Amps A Ø | 51.0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Readings | Amps B Ø | 66.0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Readings | Amps C Ø | 48.0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Readings | General Comments | 1 TC | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Readings | Maintenance Operations | 1 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Readings | Operations Counter AF | 203 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Readings | Operations Counter AL | 203 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Readings | Operations This Read Vac | 1 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000899 | BreakerVacuum | 736-1911 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | 9 Month Operations | 2 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Amps A Ø | 33.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Amps B Ø | 47.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Amps C Ø | 36.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Operations Counter AF | 474 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Operations Counter AL | 474 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Operations This Read Vac | 3 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Switching Operations | 3 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | 9 Month Operations | 5 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | Amps A Ø | 33.0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | Amps B Ø | 47.0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | Amps C Ø | 36.0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RC000436 | RecloserElectronic | 682-1683 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RC000436 | RecloserElectronic | 682-1683 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RC000436 | RecloserElectronic | 682-1683 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RC000436 | RecloserElectronic | 682-1683 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RC000436 | RecloserElectronic | 682-1683 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RC000436 | RecloserElectronic | 682-1683 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RC000436 | RecloserElectronic | 682-1683 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RC000436 | RecloserElectronic | 682-1683 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RC000436 | RecloserElectronic | 682-1683 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RC000436 | RecloserElectronic | 682-1683 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RC000436 | RecloserElectronic | 682-1683 | Recloser Electronic Patrol Inspection | Amps C Ø | 81.0 | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RC000436 | RecloserElectronic | 682-1683 | Recloser Electronic Patrol Inspection | Amps B Ø | 101.0 | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RC000436 | RecloserElectronic | 682-1683 | Recloser Electronic Patrol Inspection | Amps A Ø | 109.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1158 | BreakerVacuum | WO-1178 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1158 | BreakerVacuum | WO-1178 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1158 | BreakerVacuum | WO-1178 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1158 | BreakerVacuum | WO-1178 | VCB Readings | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1158 | BreakerVacuum | WO-1178 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1158 | BreakerVacuum | WO-1178 | VCB Readings | Operations Counter AF | 474 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1158 | BreakerVacuum | WO-1178 | VCB Readings | Operations Counter AL | 474 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1158 | BreakerVacuum | WO-1178 | VCB Readings | Operations This Read Vac | 3 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1158 | BreakerVacuum | WO-1178 | VCB Readings | Switching Operations | 3 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1158 | BreakerVacuum | WO-1178 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | 9 Month Operations | 5 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | Amps A Ø | 33.0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | Amps B Ø | 47.0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | Amps C Ø | 36.0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | General Comments | 1 TC | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | Maintenance Operations | 1 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | Operations Counter AF | 210 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | Operations Counter AL | 210 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | Operations This Read Vac | 1 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:32 | Distribution | Hartford Quarterly Inspection | BK000898 | BreakerVacuum | 736-1913 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0117 | NonLTC | MG-TRANS 1 C PHASE | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0117 | NonLTC | MG-TRANS 1 C PHASE | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0117 | NonLTC | MG-TRANS 1 C PHASE | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0117 | NonLTC | MG-TRANS 1 C PHASE | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0117 | NonLTC | MG-TRANS 1 C PHASE | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0117 | NonLTC | MG-TRANS 1 C PHASE | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0117 | NonLTC | MG-TRANS 1 C PHASE | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0117 | NonLTC | MG-TRANS 1 C PHASE | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0117 | NonLTC | MG-TRANS 1 C PHASE | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 265.00 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Readings | Fault Adjusted Amps A Phase V | 10.13 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Readings | Fault Adjusted Amps B Phase V | 10.13 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Readings | Fault Adjusted Amps C Phase V | 10.13 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Readings | Fault Operations A Ø | 2 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Readings | Fault Operations B Ø | 2 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Readings | Fault Operations C Ø | 2 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Readings | General Comments | 1 - trip check, 6 ops - STORM | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000879 | Fence | 686-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000879 | Fence | 686-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000879 | Fence | 686-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000879 | Fence | 686-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000879 | Fence | 686-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000879 | Fence | 686-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000879 | Fence | 686-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000879 | Fence | 686-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000879 | Fence | 686-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000879 | Fence | 686-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000879 | Fence | 686-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000879 | Fence | 686-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000879 | Fence | 686-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000879 | Fence | 686-Fence | Fence Patrol Inspection | General Comments | | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000879 | Fence | 686-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | FE000879 | Fence | 686-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Readings | Maintenance Operations | 1 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Readings | Operations Counter AF | 204 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Readings | Operations Counter AL | 204 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Readings | Operations This Read Vac | 7 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0854 | BreakerAirMagnetic | SV-12KV TR 1 | AMCB Readings | 9 Month Ops New | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0854 | BreakerAirMagnetic | SV-12KV TR 1 | AMCB Readings | 9 Months Operations | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0854 | BreakerAirMagnetic | SV-12KV TR 1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0854 | BreakerAirMagnetic | SV-12KV TR 1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0854 | BreakerAirMagnetic | SV-12KV TR 1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0854 | BreakerAirMagnetic | SV-12KV TR 1 | AMCB Readings | Amps A Ø | 47.0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0854 | BreakerAirMagnetic | SV-12KV TR 1 | AMCB Readings | Amps B Ø | 68.0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0854 | BreakerAirMagnetic | SV-12KV TR 1 | AMCB Readings | Amps C Ø | 46.0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0854 | BreakerAirMagnetic | SV-12KV TR 1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0854 | BreakerAirMagnetic | SV-12KV TR 1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0854 | BreakerAirMagnetic | SV-12KV TR 1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0854 | BreakerAirMagnetic | SV-12KV TR 1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0854 | BreakerAirMagnetic | SV-12KV TR 1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0854 | BreakerAirMagnetic | SV-12KV TR 1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0854 | BreakerAirMagnetic | SV-12KV TR 1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0854 | BreakerAirMagnetic | SV-12KV TR 1 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0854 | BreakerAirMagnetic | SV-12KV TR 1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0854 | BreakerAirMagnetic | SV-12KV TR 1 | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0854 | BreakerAirMagnetic | SV-12KV TR 1 | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0854 | BreakerAirMagnetic | SV-12KV TR 1 | AMCB Readings | General Comments | | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0854 | BreakerAirMagnetic | SV-12KV TR 1 | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0854 | BreakerAirMagnetic | SV-12KV TR 1 | AMCB Readings | Operations Counter AF | 530 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0854 | BreakerAirMagnetic | SV-12KV TR 1 | AMCB Readings | Operations Counter AL | 530 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0854 | BreakerAirMagnetic | SV-12KV TR 1 | AMCB Readings | Operations This Read AM | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0854 | BreakerAirMagnetic | SV-12KV TR 1 | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0854 | BreakerAirMagnetic | SV-12KV TR 1 | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Amps A Ø | 130.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Amps B Ø | 130.0 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Readings | 9 Month Operations | 9 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Readings | Amps A Ø | 95.0 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Readings | Amps B Ø | 103.0 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Readings | Amps C Ø | 117.0 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Readings | Fault Adjusted Amps A Phase V | 15.20 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Readings | Fault Adjusted Amps B Phase V | 15.20 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Readings | Fault Adjusted Amps C Phase V | 10.13 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Readings | Fault Operations A Ø | 3 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Readings | Fault Operations B Ø | 3 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Readings | Fault Operations C Ø | 2 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Readings | General Comments | 1- trip check, 8 ops - STORM | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Readings | Maintenance Operations | 1 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Readings | Operations Counter AF | 207 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Readings | Operations Counter AL | 207 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Readings | Operations This Read Vac | 9 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000900 | BreakerVacuum | 439-1612 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Amps C Ø | 95.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Operations Counter AF | 351 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Operations Counter AL | 351 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1159 | BreakerVacuum | WO-1179 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Readings | 9 Month Operations | 7 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Readings | Amps A Ø | 99.0 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Readings | Amps B Ø | 126.0 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Readings | Amps C Ø | 98.0 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BK000901 | BreakerVacuum | 439-1609 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1195 | BreakerVacuum | WS-1336-3 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1195 | BreakerVacuum | WS-1336-3 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1195 | BreakerVacuum | WS-1336-3 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1195 | BreakerVacuum | WS-1336-3 | VCB Readings | Operations Counter AF | 56 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1195 | BreakerVacuum | WS-1336-3 | VCB Readings | Operations Counter AL | 56 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1195 | BreakerVacuum | WS-1336-3 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1195 | BreakerVacuum | WS-1336-3 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1195 | BreakerVacuum | WS-1336-3 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Readings | Amps A Ø | 142.0 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Readings | Amps B Ø | 157.0 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Readings | Amps C Ø | 150.0 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1170 | BreakerVacuum | WS-1330-2 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1170 | BreakerVacuum | WS-1330-2 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1170 | BreakerVacuum | WS-1330-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1170 | BreakerVacuum | WS-1330-2 | VCB Readings | Operations Counter AL | 187 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1170 | BreakerVacuum | WS-1330-2 | VCB Readings | Operations Counter AF | 187 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1170 | BreakerVacuum | WS-1330-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1170 | BreakerVacuum | WS-1330-2 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1170 | BreakerVacuum | WS-1330-2 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Readings | Operations This Read Vac | 1 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Readings | Operations Counter AL | 194 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Readings | Operations Counter AF | 194 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Readings | Maintenance Operations | 1 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Readings | General Comments | | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1170 | BreakerVacuum | WS-1330-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1170 | BreakerVacuum | WS-1330-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1170 | BreakerVacuum | WS-1330-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1170 | BreakerVacuum | WS-1330-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1170 | BreakerVacuum | WS-1330-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1170 | BreakerVacuum | WS-1330-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1170 | BreakerVacuum | WS-1330-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1170 | BreakerVacuum | WS-1330-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1170 | BreakerVacuum | WS-1330-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1170 | BreakerVacuum | WS-1330-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1170 | BreakerVacuum | WS-1330-2 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1170 | BreakerVacuum | WS-1330-2 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1170 | BreakerVacuum | WS-1330-2 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1170 | BreakerVacuum | WS-1330-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1170 | BreakerVacuum | WS-1330-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1170 | BreakerVacuum | WS-1330-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1170 | BreakerVacuum | WS-1330-2 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1170 | BreakerVacuum | WS-1330-2 | VCB Readings | 9 Month Operations | 5 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0628 | BreakerAirMagnetic | MG-407 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0628 | BreakerAirMagnetic | MG-407 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0628 | BreakerAirMagnetic | MG-407 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0628 | BreakerAirMagnetic | MG-407 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0628 | BreakerAirMagnetic | MG-407 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0628 | BreakerAirMagnetic | MG-407 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0628 | BreakerAirMagnetic | MG-407 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0628 | BreakerAirMagnetic | MG-407 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0628 | BreakerAirMagnetic | MG-407 | AMCB Readings | Amps C Ø | 93.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0628 | BreakerAirMagnetic | MG-407 | AMCB Readings | Amps B Ø | 63.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0628 | BreakerAirMagnetic | MG-407 | AMCB Readings | Amps A Ø | 84.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0628 | BreakerAirMagnetic | MG-407 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0628 | BreakerAirMagnetic | MG-407 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0628 | BreakerAirMagnetic | MG-407 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0628 | BreakerAirMagnetic | MG-407 | AMCB Readings | 9 Months Operations | 9 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0628 | BreakerAirMagnetic | MG-407 | AMCB Readings | 9 Month Ops New | 9 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1195 | BreakerVacuum | WS-1336-3 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1195 | BreakerVacuum | WS-1336-3 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1195 | BreakerVacuum | WS-1336-3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1195 | BreakerVacuum | WS-1336-3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1195 | BreakerVacuum | WS-1336-3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1195 | BreakerVacuum | WS-1336-3 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1195 | BreakerVacuum | WS-1336-3 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1195 | BreakerVacuum | WS-1336-3 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1195 | BreakerVacuum | WS-1336-3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1195 | BreakerVacuum | WS-1336-3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Readings | Operations This Read Vac | 3 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Readings | Operations Counter AL | 184 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Readings | Operations Counter AF | 184 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Readings | Maintenance Operations | 2 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Readings | General Comments | TC, IT maint, C-N Inst Trip | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Readings | Fault Operations C Ø | 1 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Readings | Fault Adjusted Amps C Phase V | 16.19 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Readings | Amps C Ø | 64.0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Readings | Amps B Ø | 40.0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Readings | Amps A Ø | 38.0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000432 | BreakerVacuum | 405-1649 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1195 | BreakerVacuum | WS-1336-3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1195 | BreakerVacuum | WS-1336-3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1195 | BreakerVacuum | WS-1336-3 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1195 | BreakerVacuum | WS-1336-3 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1195 | BreakerVacuum | WS-1336-3 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1195 | BreakerVacuum | WS-1336-3 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1195 | BreakerVacuum | WS-1336-3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1195 | BreakerVacuum | WS-1336-3 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0850 | BreakerAirMagnetic | SV-1121 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0850 | BreakerAirMagnetic | SV-1121 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0850 | BreakerAirMagnetic | SV-1121 | AMCB Readings | Amps A Ø | 10.0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0850 | BreakerAirMagnetic | SV-1121 | AMCB Readings | Amps B Ø | 15.0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0850 | BreakerAirMagnetic | SV-1121 | AMCB Readings | Amps C Ø | 20.0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0850 | BreakerAirMagnetic | SV-1121 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0850 | BreakerAirMagnetic | SV-1121 | AMCB Readings | Fault Adjusted Amps A Phase AM | 11.18 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0850 | BreakerAirMagnetic | SV-1121 | AMCB Readings | Fault Adjusted Amps B Phase AM | 11.18 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0850 | BreakerAirMagnetic | SV-1121 | AMCB Readings | Fault Adjusted Amps C Phase AM | 11.18 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0850 | BreakerAirMagnetic | SV-1121 | AMCB Readings | Fault Operations A Ø | 1 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0850 | BreakerAirMagnetic | SV-1121 | AMCB Readings | Fault Operations B Ø | 1 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0850 | BreakerAirMagnetic | SV-1121 | AMCB Readings | Fault Operations C Ø | 1 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0850 | BreakerAirMagnetic | SV-1121 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0850 | BreakerAirMagnetic | SV-1121 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0850 | BreakerAirMagnetic | SV-1121 | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0850 | BreakerAirMagnetic | SV-1121 | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0850 | BreakerAirMagnetic | SV-1121 | AMCB Readings | General Comments | ioc on A,B and C pase | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0850 | BreakerAirMagnetic | SV-1121 | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0850 | BreakerAirMagnetic | SV-1121 | AMCB Readings | Operations Counter AF | 215 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0850 | BreakerAirMagnetic | SV-1121 | AMCB Readings | Operations Counter AL | 215 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0850 | BreakerAirMagnetic | SV-1121 | AMCB Readings | Operations This Read AM | 3 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0850 | BreakerAirMagnetic | SV-1121 | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1247 | BreakerVacuum | WS-FUTURE-6 | VCB Readings | 9 Month Operations | 6 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1247 | BreakerVacuum | WS-FUTURE-6 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1247 | BreakerVacuum | WS-FUTURE-6 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1247 | BreakerVacuum | WS-FUTURE-6 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1247 | BreakerVacuum | WS-FUTURE-6 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1247 | BreakerVacuum | WS-FUTURE-6 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1247 | BreakerVacuum | WS-FUTURE-6 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1247 | BreakerVacuum | WS-FUTURE-6 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1247 | BreakerVacuum | WS-FUTURE-6 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1247 | BreakerVacuum | WS-FUTURE-6 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1247 | BreakerVacuum | WS-FUTURE-6 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1247 | BreakerVacuum | WS-FUTURE-6 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1247 | BreakerVacuum | WS-FUTURE-6 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1247 | BreakerVacuum | WS-FUTURE-6 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1247 | BreakerVacuum | WS-FUTURE-6 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1247 | BreakerVacuum | WS-FUTURE-6 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1247 | BreakerVacuum | WS-FUTURE-6 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1247 | BreakerVacuum | WS-FUTURE-6 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1247 | BreakerVacuum | WS-FUTURE-6 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1247 | BreakerVacuum | WS-FUTURE-6 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1247 | BreakerVacuum | WS-FUTURE-6 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1247 | BreakerVacuum | WS-FUTURE-6 | VCB Readings | Operations Counter AF | 77 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1247 | BreakerVacuum | WS-FUTURE-6 | VCB Readings | Operations Counter AL | 77 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1247 | BreakerVacuum | WS-FUTURE-6 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1247 | BreakerVacuum | WS-FUTURE-6 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1247 | BreakerVacuum | WS-FUTURE-6 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1158 | BreakerVacuum | WO-1178 | VCB Readings | 9 Month Operations | 5 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1158 | BreakerVacuum | WO-1178 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1158 | BreakerVacuum | WO-1178 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1158 | BreakerVacuum | WO-1178 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1158 | BreakerVacuum | WO-1178 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1158 | BreakerVacuum | WO-1178 | VCB Readings | Amps A Ø | 35.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1158 | BreakerVacuum | WO-1178 | VCB Readings | Amps B Ø | 55.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1158 | BreakerVacuum | WO-1178 | VCB Readings | Amps C Ø | 65.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1158 | BreakerVacuum | WO-1178 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1158 | BreakerVacuum | WO-1178 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1158 | BreakerVacuum | WO-1178 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1158 | BreakerVacuum | WO-1178 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1158 | BreakerVacuum | WO-1178 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1158 | BreakerVacuum | WO-1178 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1158 | BreakerVacuum | WO-1178 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1158 | BreakerVacuum | WO-1178 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RC000436 | RecloserElectronic | 682-1683 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RC000436 | RecloserElectronic | 682-1683 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RC000436 | RecloserElectronic | 682-1683 | Recloser Electronic Patrol Inspection | Operations Counter | 206 | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RC000436 | RecloserElectronic | 682-1683 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RC000436 | RecloserElectronic | 682-1683 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | RC000436 | RecloserElectronic | 682-1683 | Recloser Electronic Patrol Inspection | General Comments | 1 trip check when batteries were replaced. | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Readings | Amps C Ø | 100.0 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Readings | Amps B Ø | 100.0 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Readings | Amps A Ø | 100.0 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0120 | BreakerVacuum | 641-0919 | VCB Readings | 9 Month Operations | 2 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Readings | Fault Adjusted Amps C Phase V | 12.58 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Readings | Fault Operations C Ø | 3 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Readings | General Comments | | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Readings | Operations Counter AF | 193 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Readings | Operations Counter AL | 193 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Readings | Operations This Read Vac | 3 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000892 | BreakerVacuum | 570-0545 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LTCC000577 | LTCControl | SV-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LTCC000577 | LTCControl | SV-TRANS 2 | LTC Control Insp | General Comments | | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LTCC000577 | LTCControl | SV-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1242 | BreakerVacuum | WS-GND TR 2 | VCB Readings | 9 Month Operations | 5 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1242 | BreakerVacuum | WS-GND TR 2 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1242 | BreakerVacuum | WS-GND TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1242 | BreakerVacuum | WS-GND TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1242 | BreakerVacuum | WS-GND TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1242 | BreakerVacuum | WS-GND TR 2 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1242 | BreakerVacuum | WS-GND TR 2 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1242 | BreakerVacuum | WS-GND TR 2 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1242 | BreakerVacuum | WS-GND TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1242 | BreakerVacuum | WS-GND TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1242 | BreakerVacuum | WS-GND TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1242 | BreakerVacuum | WS-GND TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1242 | BreakerVacuum | WS-GND TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1242 | BreakerVacuum | WS-GND TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1242 | BreakerVacuum | WS-GND TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1242 | BreakerVacuum | WS-GND TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1242 | BreakerVacuum | WS-GND TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1242 | BreakerVacuum | WS-GND TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1242 | BreakerVacuum | WS-GND TR 2 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1242 | BreakerVacuum | WS-GND TR 2 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1242 | BreakerVacuum | WS-GND TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1242 | BreakerVacuum | WS-GND TR 2 | VCB Readings | Operations Counter AF | 156 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1242 | BreakerVacuum | WS-GND TR 2 | VCB Readings | Operations Counter AL | 156 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1242 | BreakerVacuum | WS-GND TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1242 | BreakerVacuum | WS-GND TR 2 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1242 | BreakerVacuum | WS-GND TR 2 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0850 | BreakerAirMagnetic | SV-1121 | AMCB Readings | 9 Month Ops New | 2 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0850 | BreakerAirMagnetic | SV-1121 | AMCB Readings | 9 Months Operations | 5 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0850 | BreakerAirMagnetic | SV-1121 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1205 | BreakerVacuum | WS-1474-2 | VCB Readings | Amps A Ø | 116.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1205 | BreakerVacuum | WS-1474-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1205 | BreakerVacuum | WS-1474-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1205 | BreakerVacuum | WS-1474-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1205 | BreakerVacuum | WS-1474-2 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1205 | BreakerVacuum | WS-1474-2 | VCB Readings | 9 Month Operations | 5 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0855 | BreakerAirMagnetic | SV-12KV TR 2 | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0855 | BreakerAirMagnetic | SV-12KV TR 2 | AMCB Readings | Operations This Read AM | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0855 | BreakerAirMagnetic | SV-12KV TR 2 | AMCB Readings | Operations Counter AL | 869 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0855 | BreakerAirMagnetic | SV-12KV TR 2 | AMCB Readings | Operations Counter AF | 869 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0855 | BreakerAirMagnetic | SV-12KV TR 2 | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0855 | BreakerAirMagnetic | SV-12KV TR 2 | AMCB Patrol Inspection | General Comments | ok | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0855 | BreakerAirMagnetic | SV-12KV TR 2 | AMCB Readings | General Comments | | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0855 | BreakerAirMagnetic | SV-12KV TR 2 | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0855 | BreakerAirMagnetic | SV-12KV TR 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0855 | BreakerAirMagnetic | SV-12KV TR 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0855 | BreakerAirMagnetic | SV-12KV TR 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0855 | BreakerAirMagnetic | SV-12KV TR 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0855 | BreakerAirMagnetic | SV-12KV TR 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0855 | BreakerAirMagnetic | SV-12KV TR 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0855 | BreakerAirMagnetic | SV-12KV TR 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0855 | BreakerAirMagnetic | SV-12KV TR 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0855 | BreakerAirMagnetic | SV-12KV TR 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0855 | BreakerAirMagnetic | SV-12KV TR 2 | AMCB Readings | Amps C Ø | 120.0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0855 | BreakerAirMagnetic | SV-12KV TR 2 | AMCB Readings | Amps B Ø | 120.0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0855 | BreakerAirMagnetic | SV-12KV TR 2 | AMCB Readings | Amps A Ø | 120.0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0855 | BreakerAirMagnetic | SV-12KV TR 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0855 | BreakerAirMagnetic | SV-12KV TR 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0855 | BreakerAirMagnetic | SV-12KV TR 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0855 | BreakerAirMagnetic | SV-12KV TR 2 | AMCB Readings | 9 Months Operations | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0855 | BreakerAirMagnetic | SV-12KV TR 2 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Readings | 9 Month Operations | 21 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Readings | 9 Month Operations VCB New | 21 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Readings | Amps A Ø | 29.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Readings | Amps B Ø | 29.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Readings | Amps C Ø | 30.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Patrol Inspection | General Comments | Indoor switchgear roll in breaker, fix insp to show | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Readings | Operations Counter AF | 128 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Readings | Operations Counter AL | 128 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001922 | BreakerVacuum | MG-1336-A | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Readings | 9 Month Operations | 21 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Readings | 9 Month Operations VCB New | 21 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000065 | Regulator | 405-1 B | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000065 | Regulator | 405-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000065 | Regulator | 405-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000065 | Regulator | 405-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000065 | Regulator | 405-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000065 | Regulator | 405-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000065 | Regulator | 405-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000065 | Regulator | 405-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 15628 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000065 | Regulator | 405-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000065 | Regulator | 405-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000065 | Regulator | 405-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000065 | Regulator | 405-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Readings | General Comments | TC, 2 Uknown ops | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Readings | Maintenance Operations | 1 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Readings | Operations Counter AF | 209 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Readings | Operations Counter AL | 0 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Readings | Operations This Read Vac | 3 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Readings | Unknown Operations | 2 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1205 | BreakerVacuum | WS-1474-2 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1205 | BreakerVacuum | WS-1474-2 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1205 | BreakerVacuum | WS-1474-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1205 | BreakerVacuum | WS-1474-2 | VCB Readings | Operations Counter AL | 76 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1205 | BreakerVacuum | WS-1474-2 | VCB Readings | Operations Counter AF | 76 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1205 | BreakerVacuum | WS-1474-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1205 | BreakerVacuum | WS-1474-2 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1205 | BreakerVacuum | WS-1474-2 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1205 | BreakerVacuum | WS-1474-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1205 | BreakerVacuum | WS-1474-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1205 | BreakerVacuum | WS-1474-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1205 | BreakerVacuum | WS-1474-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1205 | BreakerVacuum | WS-1474-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1205 | BreakerVacuum | WS-1474-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1205 | BreakerVacuum | WS-1474-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1205 | BreakerVacuum | WS-1474-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000066 | Regulator | 405-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000066 | Regulator | 405-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000066 | Regulator | 405-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000066 | Regulator | 405-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000066 | Regulator | 405-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000066 | Regulator | 405-1 C | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000066 | Regulator | 405-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000066 | Regulator | 405-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000066 | Regulator | 405-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000066 | Regulator | 405-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000066 | Regulator | 405-1 C | Regulator Patrol Inspection | General Comments | | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000066 | Regulator | 405-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000066 | Regulator | 405-1 C | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000066 | Regulator | 405-1 C | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000066 | Regulator | 405-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000066 | Regulator | 405-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000066 | Regulator | 405-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000066 | Regulator | 405-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000066 | Regulator | 405-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000066 | Regulator | 405-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 16611 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000066 | Regulator | 405-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000066 | Regulator | 405-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000066 | Regulator | 405-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000066 | Regulator | 405-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1205 | BreakerVacuum | WS-1474-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1205 | BreakerVacuum | WS-1474-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1205 | BreakerVacuum | WS-1474-2 | VCB Readings | Amps C Ø | 115.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1205 | BreakerVacuum | WS-1474-2 | VCB Readings | Amps B Ø | 109.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1188 | BreakerVacuum | WS-GND TR 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1188 | BreakerVacuum | WS-GND TR 3 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1188 | BreakerVacuum | WS-GND TR 3 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1188 | BreakerVacuum | WS-GND TR 3 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1188 | BreakerVacuum | WS-GND TR 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1188 | BreakerVacuum | WS-GND TR 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1188 | BreakerVacuum | WS-GND TR 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1188 | BreakerVacuum | WS-GND TR 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1188 | BreakerVacuum | WS-GND TR 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1188 | BreakerVacuum | WS-GND TR 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1188 | BreakerVacuum | WS-GND TR 3 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1188 | BreakerVacuum | WS-GND TR 3 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1188 | BreakerVacuum | WS-GND TR 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1188 | BreakerVacuum | WS-GND TR 3 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1188 | BreakerVacuum | WS-GND TR 3 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1188 | BreakerVacuum | WS-GND TR 3 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1188 | BreakerVacuum | WS-GND TR 3 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1188 | BreakerVacuum | WS-GND TR 3 | VCB Readings | Operations Counter AF | 80 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1188 | BreakerVacuum | WS-GND TR 3 | VCB Readings | Operations Counter AL | 80 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1188 | BreakerVacuum | WS-GND TR 3 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1188 | BreakerVacuum | WS-GND TR 3 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1188 | BreakerVacuum | WS-GND TR 3 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Readings | Operations Counter AL | 99960 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Readings | Operations Counter AF | 99960 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Readings | General Comments | | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Readings | General Comments | | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Readings | LTC Totalizer Reading | 2409.12 | kw |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.0038 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | W0282 | WithLTC | 418-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Readings | Amps A Ø | 20.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Readings | Amps B Ø | 23.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Readings | Amps C Ø | 23.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Readings | 9 Month Operations | 0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Readings | Amps A Ø | 90.0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Readings | Amps B Ø | 100.0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Readings | Amps C Ø | 60.0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BB0416 | BreakerVacuum | 596-1498 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Patrol Inspection | General Comments | Indoor switchgear roll in breaker, fix insp to show | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0621 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0621 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0621 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Operations Counter AF | 512 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0621 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Operations Counter AL | 512 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0621 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0621 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0621 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Readings | Operations Counter AF | 140 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Readings | Operations Counter AL | 140 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001924 | BreakerVacuum | MG-14KV BUS TIE SEC 6-7 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1188 | BreakerVacuum | WS-GND TR 3 | VCB Readings | 9 Month Operations | 9 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1188 | BreakerVacuum | WS-GND TR 3 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1188 | BreakerVacuum | WS-GND TR 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1188 | BreakerVacuum | WS-GND TR 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Readings | LTC Totalizer Reading | 3306.24 | kw |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1173 | BreakerVacuum | WS-1473-1 | VCB Readings | 9 Month Operations | 4 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1173 | BreakerVacuum | WS-1473-1 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1173 | BreakerVacuum | WS-1473-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1173 | BreakerVacuum | WS-1473-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1173 | BreakerVacuum | WS-1473-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1173 | BreakerVacuum | WS-1473-1 | VCB Readings | Amps A Ø | 96.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1173 | BreakerVacuum | WS-1473-1 | VCB Readings | Amps B Ø | 96.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1173 | BreakerVacuum | WS-1473-1 | VCB Readings | Amps C Ø | 96.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1173 | BreakerVacuum | WS-1473-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1173 | BreakerVacuum | WS-1473-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1173 | BreakerVacuum | WS-1473-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1173 | BreakerVacuum | WS-1473-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1173 | BreakerVacuum | WS-1473-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1173 | BreakerVacuum | WS-1473-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1173 | BreakerVacuum | WS-1473-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1173 | BreakerVacuum | WS-1473-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1173 | BreakerVacuum | WS-1473-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1173 | BreakerVacuum | WS-1473-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1173 | BreakerVacuum | WS-1473-1 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1173 | BreakerVacuum | WS-1473-1 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1173 | BreakerVacuum | WS-1473-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1173 | BreakerVacuum | WS-1473-1 | VCB Readings | Operations Counter AF | 154 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1173 | BreakerVacuum | WS-1473-1 | VCB Readings | Operations Counter AL | 154 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1173 | BreakerVacuum | WS-1473-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1173 | BreakerVacuum | WS-1473-1 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1173 | BreakerVacuum | WS-1473-1 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1211 | BreakerVacuum | WS-1310-2 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1211 | BreakerVacuum | WS-1310-2 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1211 | BreakerVacuum | WS-1310-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1211 | BreakerVacuum | WS-1310-2 | VCB Readings | Operations Counter AL | 178 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1211 | BreakerVacuum | WS-1310-2 | VCB Readings | Operations Counter AF | 178 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1211 | BreakerVacuum | WS-1310-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1211 | BreakerVacuum | WS-1310-2 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1211 | BreakerVacuum | WS-1310-2 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1211 | BreakerVacuum | WS-1310-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1211 | BreakerVacuum | WS-1310-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1211 | BreakerVacuum | WS-1310-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1211 | BreakerVacuum | WS-1310-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1211 | BreakerVacuum | WS-1310-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1211 | BreakerVacuum | WS-1310-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1211 | BreakerVacuum | WS-1310-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1211 | BreakerVacuum | WS-1310-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1211 | BreakerVacuum | WS-1310-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1211 | BreakerVacuum | WS-1310-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Readings | Operations Counter AL | 363 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Readings | Operations Counter AF | 363 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Readings | General Comments | 190 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Readings | Amps C Ø | 190.0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Readings | Amps B Ø | 165.0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Readings | Amps A Ø | 190.0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 14:00 | Distribution | Carlisle Quarterly Inspection | K0149 | BreakerVacuum | 686-0876 | VCB Readings | 9 Month Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1210 | BreakerVacuum | WS-1306-2 | VCB Readings | 9 Month Operations | 8 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1210 | BreakerVacuum | WS-1306-2 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1210 | BreakerVacuum | WS-1306-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1210 | BreakerVacuum | WS-1306-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1210 | BreakerVacuum | WS-1306-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1210 | BreakerVacuum | WS-1306-2 | VCB Readings | Amps A Ø | 113.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1210 | BreakerVacuum | WS-1306-2 | VCB Readings | Amps B Ø | 113.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1210 | BreakerVacuum | WS-1306-2 | VCB Readings | Amps C Ø | 115.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1210 | BreakerVacuum | WS-1306-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1210 | BreakerVacuum | WS-1306-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1210 | BreakerVacuum | WS-1306-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1210 | BreakerVacuum | WS-1306-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1210 | BreakerVacuum | WS-1306-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1210 | BreakerVacuum | WS-1306-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1210 | BreakerVacuum | WS-1306-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1210 | BreakerVacuum | WS-1306-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1210 | BreakerVacuum | WS-1306-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1210 | BreakerVacuum | WS-1306-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1210 | BreakerVacuum | WS-1306-2 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1210 | BreakerVacuum | WS-1306-2 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1210 | BreakerVacuum | WS-1306-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1210 | BreakerVacuum | WS-1306-2 | VCB Readings | Operations Counter AF | 186 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1210 | BreakerVacuum | WS-1306-2 | VCB Readings | Operations Counter AL | 186 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1210 | BreakerVacuum | WS-1306-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1210 | BreakerVacuum | WS-1306-2 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1210 | BreakerVacuum | WS-1306-2 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Readings | Winding Temp Present | 0 | °C |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Readings | Totalizer Meter Reading | .3444 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0621 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0621 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Readings | 9 Month Operations | 5 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Readings | Amps A Ø | 15.0 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Readings | Amps B Ø | 5.0 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Readings | Amps C Ø | 5.0 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Readings | Fault Adjusted Amps A Phase V | 9.12 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Readings | Fault Adjusted Amps B Phase V | 9.12 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Readings | Fault Adjusted Amps C Phase V | 9.12 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:29 | Distribution | Muhlenberg Prison Quarterly Inspection | WB0153 | BreakerVacuum | 497-0656 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000064 | Regulator | 405-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000064 | Regulator | 405-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000064 | Regulator | 405-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000064 | Regulator | 405-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000064 | Regulator | 405-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000064 | Regulator | 405-1 A | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000064 | Regulator | 405-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000064 | Regulator | 405-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000064 | Regulator | 405-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000064 | Regulator | 405-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000064 | Regulator | 405-1 A | Regulator Patrol Inspection | General Comments | was found at off. When door was closed was turning off switch, fixed issue but needs to be checked before leave. | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000064 | Regulator | 405-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000064 | Regulator | 405-1 A | Regulator Patrol Inspection | Max Tap Position | 6L | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000064 | Regulator | 405-1 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000064 | Regulator | 405-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000064 | Regulator | 405-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000064 | Regulator | 405-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000064 | Regulator | 405-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0621 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0621 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0621 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0621 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0621 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0621 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0621 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0621 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000064 | Regulator | 405-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 122.5 | volts |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000064 | Regulator | 405-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 12431 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000064 | Regulator | 405-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000064 | Regulator | 405-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000064 | Regulator | 405-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000064 | Regulator | 405-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000065 | Regulator | 405-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000065 | Regulator | 405-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000065 | Regulator | 405-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000065 | Regulator | 405-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000065 | Regulator | 405-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000065 | Regulator | 405-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000065 | Regulator | 405-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000065 | Regulator | 405-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000065 | Regulator | 405-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000065 | Regulator | 405-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000065 | Regulator | 405-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | RG000065 | Regulator | 405-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1211 | BreakerVacuum | WS-1310-2 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1211 | BreakerVacuum | WS-1310-2 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1211 | BreakerVacuum | WS-1310-2 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1211 | BreakerVacuum | WS-1310-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1211 | BreakerVacuum | WS-1310-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1211 | BreakerVacuum | WS-1310-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1211 | BreakerVacuum | WS-1310-2 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1211 | BreakerVacuum | WS-1310-2 | VCB Readings | 9 Month Operations | 2 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0642 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0642 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0642 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0642 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Operations Counter AL | 485 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0642 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Operations Counter AF | 485 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0642 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0642 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0642 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0642 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0642 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0642 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0642 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0642 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0642 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0642 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0642 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0642 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0642 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0642 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0642 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0642 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0642 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0642 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0642 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0642 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | 9 Months Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0642 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | W0329 | WithLTC | 641-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1225 | BreakerVacuum | WS-1425-4 | VCB Readings | 9 Month Operations | 2 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1225 | BreakerVacuum | WS-1425-4 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1225 | BreakerVacuum | WS-1425-4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1225 | BreakerVacuum | WS-1425-4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1225 | BreakerVacuum | WS-1425-4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1225 | BreakerVacuum | WS-1425-4 | VCB Readings | Amps A Ø | 90.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1225 | BreakerVacuum | WS-1425-4 | VCB Readings | Amps B Ø | 88.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1225 | BreakerVacuum | WS-1425-4 | VCB Readings | Amps C Ø | 88.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1225 | BreakerVacuum | WS-1425-4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1225 | BreakerVacuum | WS-1425-4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1225 | BreakerVacuum | WS-1425-4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1225 | BreakerVacuum | WS-1425-4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1225 | BreakerVacuum | WS-1425-4 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1225 | BreakerVacuum | WS-1425-4 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1225 | BreakerVacuum | WS-1425-4 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1225 | BreakerVacuum | WS-1425-4 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1225 | BreakerVacuum | WS-1425-4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1225 | BreakerVacuum | WS-1425-4 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1225 | BreakerVacuum | WS-1425-4 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1225 | BreakerVacuum | WS-1425-4 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1225 | BreakerVacuum | WS-1425-4 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1225 | BreakerVacuum | WS-1425-4 | VCB Readings | Operations Counter AF | 98 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1225 | BreakerVacuum | WS-1425-4 | VCB Readings | Operations Counter AL | 98 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1225 | BreakerVacuum | WS-1425-4 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1225 | BreakerVacuum | WS-1425-4 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1225 | BreakerVacuum | WS-1425-4 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0621 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | 9 Month Ops New | 6 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0621 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | 9 Months Operations | 6 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0621 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0621 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0621 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0621 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0621 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0621 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0621 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | BCH001534 | Charger | 418-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | BCH001534 | Charger | 418-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | BCH001534 | Charger | 418-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | BCH001534 | Charger | 418-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 0.0 | amps |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | BCH001534 | Charger | 418-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.1 | VDC |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | BCH001534 | Charger | 418-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.1 | VDC |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | BCH001534 | Charger | 418-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .700 | millivolts |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1160 | BreakerVacuum | WO-1180 | VCB Readings | Amps A Ø | 250.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Readings | 9 Month Operations | 14 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Readings | 9 Month Operations VCB New | 14 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Readings | Amps A Ø | 30.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Readings | Amps B Ø | 30.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Readings | Amps C Ø | 30.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Patrol Inspection | General Comments | Indoor switchgear roll in breaker, fix insp to show | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Readings | Operations Counter AF | 140 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Readings | Operations Counter AL | 140 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Readings | Operations This Read Vac | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001856 | BreakerVacuum | MG-1332-A | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1160 | BreakerVacuum | WO-1180 | VCB Readings | Amps B Ø | 240.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1160 | BreakerVacuum | WO-1180 | VCB Readings | Amps C Ø | 240.0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1160 | BreakerVacuum | WO-1180 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1160 | BreakerVacuum | WO-1180 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1160 | BreakerVacuum | WO-1180 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1160 | BreakerVacuum | WO-1180 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1160 | BreakerVacuum | WO-1180 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1160 | BreakerVacuum | WO-1180 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1160 | BreakerVacuum | WO-1180 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1160 | BreakerVacuum | WO-1180 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1160 | BreakerVacuum | WO-1180 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1160 | BreakerVacuum | WO-1180 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1160 | BreakerVacuum | WO-1180 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1160 | BreakerVacuum | WO-1180 | VCB Readings | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1160 | BreakerVacuum | WO-1180 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1160 | BreakerVacuum | WO-1180 | VCB Readings | Operations Counter AF | 371 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1160 | BreakerVacuum | WO-1180 | VCB Readings | Operations Counter AL | 371 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1160 | BreakerVacuum | WO-1180 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1160 | BreakerVacuum | WO-1180 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1160 | BreakerVacuum | WO-1180 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | 9 Month Operations | 2 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1828.80 | kw |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Readings | Oil Temp Max | 44 | °C |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Readings | Oil Temp Present | 41 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Readings | 9 Month Operations | 19 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Readings | 9 Month Operations VCB New | 19 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .3810 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1160 | BreakerVacuum | WO-1180 | VCB Readings | 9 Month Operations | 1 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1160 | BreakerVacuum | WO-1180 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1160 | BreakerVacuum | WO-1180 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1160 | BreakerVacuum | WO-1180 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LB1160 | BreakerVacuum | WO-1180 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | BCH001534 | Charger | 418-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Patrol Inspection | General Comments | Indoor switchgear roll in breaker, fix insp to show | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Readings | Operations Counter AF | 113 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Readings | Operations Counter AL | 113 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001855 | BreakerVacuum | MG-GND TR 6 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Operations Counter AF | 111 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Operations Counter AL | 111 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Patrol Inspection | General Comments | Indoor switchgear roll in breaker, fix insp to show | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Readings | Operations Counter AF | 143 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Readings | Operations Counter AL | 143 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | LTCMechanism | WS-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | LTCMechanism | WS-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | LTCMechanism | WS-TRANS 1 | LTC Counter Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | LTCMechanism | WS-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | LTCMechanism | WS-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 29401 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | LTCMechanism | WS-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 29401 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | LTCMechanism | WS-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | LTCMechanism | WS-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | LTCMechanism | WS-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | LTCMechanism | WS-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | LTCMechanism | WS-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 26 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | LTCMechanism | WS-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 524 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | LTCMechanism | WS-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | LTCMechanism | WS-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | LTCMechanism | WS-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | LTCMechanism | WS-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | 9 Month Operations VCB New | 3 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Readings | 9 Month Operations | 43 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Readings | 9 Month Operations VCB New | 43 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Readings | Amps A Ø | 37.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Readings | Amps B Ø | 37.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Readings | Amps C Ø | 37.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Patrol Inspection | General Comments | Indoor switchgear roll in breaker, fix insp to show | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Readings | Operations Counter AF | 125 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Readings | Operations Counter AL | 125 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001857 | BreakerVacuum | MG-1333-A | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Readings | 9 Month Operations | 30 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Readings | 9 Month Operations VCB New | 30 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Readings | Amps A Ø | 31.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Readings | Amps B Ø | 31.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Readings | Amps C Ø | 30.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001858 | BreakerVacuum | MG-1334-A | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000875 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | General Comments | Out of service | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1172 | BreakerVacuum | WS-1472-1 | VCB Readings | Amps C Ø | 122.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1172 | BreakerVacuum | WS-1472-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1172 | BreakerVacuum | WS-1472-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1172 | BreakerVacuum | WS-1472-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1172 | BreakerVacuum | WS-1472-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1172 | BreakerVacuum | WS-1472-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1172 | BreakerVacuum | WS-1472-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1172 | BreakerVacuum | WS-1472-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1172 | BreakerVacuum | WS-1472-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1172 | BreakerVacuum | WS-1472-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1172 | BreakerVacuum | WS-1472-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1172 | BreakerVacuum | WS-1472-1 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1172 | BreakerVacuum | WS-1472-1 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1172 | BreakerVacuum | WS-1472-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1172 | BreakerVacuum | WS-1472-1 | VCB Readings | Operations Counter AF | 196 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1172 | BreakerVacuum | WS-1472-1 | VCB Readings | Operations Counter AL | 196 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1172 | BreakerVacuum | WS-1472-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1172 | BreakerVacuum | WS-1472-1 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1172 | BreakerVacuum | WS-1472-1 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1201 | BreakerVacuum | WS-1428-3 | VCB Readings | 9 Month Operations | 4 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1201 | BreakerVacuum | WS-1428-3 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1201 | BreakerVacuum | WS-1428-3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1201 | BreakerVacuum | WS-1428-3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1201 | BreakerVacuum | WS-1428-3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1201 | BreakerVacuum | WS-1428-3 | VCB Readings | Amps A Ø | 92.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1201 | BreakerVacuum | WS-1428-3 | VCB Readings | Amps B Ø | 87.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1201 | BreakerVacuum | WS-1428-3 | VCB Readings | Amps C Ø | 88.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1201 | BreakerVacuum | WS-1428-3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1201 | BreakerVacuum | WS-1428-3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1201 | BreakerVacuum | WS-1428-3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1201 | BreakerVacuum | WS-1428-3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1201 | BreakerVacuum | WS-1428-3 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1201 | BreakerVacuum | WS-1428-3 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1201 | BreakerVacuum | WS-1428-3 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1201 | BreakerVacuum | WS-1428-3 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1201 | BreakerVacuum | WS-1428-3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1201 | BreakerVacuum | WS-1428-3 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1201 | BreakerVacuum | WS-1428-3 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1201 | BreakerVacuum | WS-1428-3 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1201 | BreakerVacuum | WS-1428-3 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1201 | BreakerVacuum | WS-1428-3 | VCB Readings | Operations Counter AF | 111 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1201 | BreakerVacuum | WS-1428-3 | VCB Readings | Operations Counter AL | 111 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1201 | BreakerVacuum | WS-1428-3 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1201 | BreakerVacuum | WS-1428-3 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1201 | BreakerVacuum | WS-1428-3 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | LTCMechanism | MK-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | LTCMechanism | MK-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | LTCMechanism | MK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | LTCMechanism | MK-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 96 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | LTCMechanism | MK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | LTCMechanism | MK-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | LTCMechanism | MK-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | LTCMechanism | MK-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | LTCMechanism | MK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | LTCMechanism | MK-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 1067 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | LTCMechanism | MK-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 1067 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | LTCMechanism | MK-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | LTCMechanism | MK-TRANS 1 | LTC Counter Readings | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | LTCMechanism | MK-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | LTCMechanism | MK-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BAT001611 | Battery | 596-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BAT001611 | Battery | 596-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BAT001611 | Battery | 596-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.8 | VDC |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BAT001611 | Battery | 596-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 28.0 | VDC |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BAT001611 | Battery | 596-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BAT001611 | Battery | 596-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BAT001611 | Battery | 596-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BAT001611 | Battery | 596-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BAT001611 | Battery | 596-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | S0038 | NonLTC | 439-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .5406 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1238 | BreakerVacuum | WS-1425-3 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1238 | BreakerVacuum | WS-1425-3 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1238 | BreakerVacuum | WS-1425-3 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1238 | BreakerVacuum | WS-1425-3 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1238 | BreakerVacuum | WS-1425-3 | VCB Readings | Operations Counter AF | 106 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1238 | BreakerVacuum | WS-1425-3 | VCB Readings | Operations Counter AL | 106 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1238 | BreakerVacuum | WS-1425-3 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1238 | BreakerVacuum | WS-1425-3 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1238 | BreakerVacuum | WS-1425-3 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1178 | BreakerVacuum | WS-1305-1 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1178 | BreakerVacuum | WS-1305-1 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1178 | BreakerVacuum | WS-1305-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1178 | BreakerVacuum | WS-1305-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1178 | BreakerVacuum | WS-1305-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1178 | BreakerVacuum | WS-1305-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1178 | BreakerVacuum | WS-1305-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1178 | BreakerVacuum | WS-1305-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | LTCC000157 | LTCControl | 467-1 | LTC Control Insp | All Connections OK? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | LTCC000157 | LTCControl | 467-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | LTCC000157 | LTCControl | 467-1 | LTC Control Insp | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1226 | BreakerVacuum | WS-1427-4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1226 | BreakerVacuum | WS-1427-4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1226 | BreakerVacuum | WS-1427-4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1226 | BreakerVacuum | WS-1427-4 | VCB Readings | Amps A Ø | 64.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1226 | BreakerVacuum | WS-1427-4 | VCB Readings | Amps B Ø | 62.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1226 | BreakerVacuum | WS-1427-4 | VCB Readings | Amps C Ø | 62.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1226 | BreakerVacuum | WS-1427-4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1226 | BreakerVacuum | WS-1427-4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1226 | BreakerVacuum | WS-1427-4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1226 | BreakerVacuum | WS-1427-4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1226 | BreakerVacuum | WS-1427-4 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1226 | BreakerVacuum | WS-1427-4 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1226 | BreakerVacuum | WS-1427-4 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1226 | BreakerVacuum | WS-1427-4 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1226 | BreakerVacuum | WS-1427-4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1226 | BreakerVacuum | WS-1427-4 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1226 | BreakerVacuum | WS-1427-4 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1226 | BreakerVacuum | WS-1427-4 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1226 | BreakerVacuum | WS-1427-4 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1226 | BreakerVacuum | WS-1427-4 | VCB Readings | Operations Counter AF | 62 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1226 | BreakerVacuum | WS-1427-4 | VCB Readings | Operations Counter AL | 62 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1226 | BreakerVacuum | WS-1427-4 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1226 | BreakerVacuum | WS-1427-4 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1226 | BreakerVacuum | WS-1427-4 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | LTCC000157 | LTCControl | 467-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | LTCC000157 | LTCControl | 467-1 | LTC Control Insp | LTC Output Voltage Level | 124.6 | VAC |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | LTCC000157 | LTCControl | 467-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | LTCC000157 | LTCControl | 467-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | LTCC000157 | LTCControl | 467-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1178 | BreakerVacuum | WS-1305-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1178 | BreakerVacuum | WS-1305-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1178 | BreakerVacuum | WS-1305-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1178 | BreakerVacuum | WS-1305-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1178 | BreakerVacuum | WS-1305-1 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1178 | BreakerVacuum | WS-1305-1 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1178 | BreakerVacuum | WS-1305-1 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1178 | BreakerVacuum | WS-1305-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1178 | BreakerVacuum | WS-1305-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1178 | BreakerVacuum | WS-1305-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1178 | BreakerVacuum | WS-1305-1 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1178 | BreakerVacuum | WS-1305-1 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1172 | BreakerVacuum | WS-1472-1 | VCB Readings | 9 Month Operations | 5 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1172 | BreakerVacuum | WS-1472-1 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1172 | BreakerVacuum | WS-1472-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1172 | BreakerVacuum | WS-1472-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1172 | BreakerVacuum | WS-1472-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1172 | BreakerVacuum | WS-1472-1 | VCB Readings | Amps A Ø | 122.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1172 | BreakerVacuum | WS-1472-1 | VCB Readings | Amps B Ø | 118.0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | BAT001606 | Battery | 418-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | BAT001606 | Battery | 418-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | BAT001606 | Battery | 418-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.7 | VDC |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | BAT001606 | Battery | 418-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.4 | VDC |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | BAT001606 | Battery | 418-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | BAT001606 | Battery | 418-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | BAT001606 | Battery | 418-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | BAT001606 | Battery | 418-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | BAT001606 | Battery | 418-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | BAT001606 | Battery | 418-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | BAT001606 | Battery | 418-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 53 | °F |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | BAT001606 | Battery | 418-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Readings | General Comments | k | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0115 | NonLTC | MG-TRANS 1 A PHASE | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0115 | NonLTC | MG-TRANS 1 A PHASE | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0115 | NonLTC | MG-TRANS 1 A PHASE | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0115 | NonLTC | MG-TRANS 1 A PHASE | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0115 | NonLTC | MG-TRANS 1 A PHASE | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0115 | NonLTC | MG-TRANS 1 A PHASE | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0115 | NonLTC | MG-TRANS 1 A PHASE | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0115 | NonLTC | MG-TRANS 1 A PHASE | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0115 | NonLTC | MG-TRANS 1 A PHASE | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 445.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0115 | NonLTC | MG-TRANS 1 A PHASE | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 460.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0115 | NonLTC | MG-TRANS 1 A PHASE | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0115 | NonLTC | MG-TRANS 1 A PHASE | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0115 | NonLTC | MG-TRANS 1 A PHASE | NonLTC Transformer Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0115 | NonLTC | MG-TRANS 1 A PHASE | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0115 | NonLTC | MG-TRANS 1 A PHASE | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0115 | NonLTC | MG-TRANS 1 A PHASE | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0115 | NonLTC | MG-TRANS 1 A PHASE | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0115 | NonLTC | MG-TRANS 1 A PHASE | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0115 | NonLTC | MG-TRANS 1 A PHASE | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0115 | NonLTC | MG-TRANS 1 A PHASE | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0115 | NonLTC | MG-TRANS 1 A PHASE | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Readings | X3 Winding Temp Present | 46 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Readings | X3 Winding Temp Max | 67 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Readings | X2 Winding Temp Present | 46 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Readings | X2 Winding Temp Max | 67 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Readings | X1 Winding Temp Present | 45 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Readings | X1 Winding Temp Max | 66 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Readings | Oil Temp Max | 57 | °C |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LT0114 | WithLTC | MG-TRANS 5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BAT001611 | Battery | 596-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BAT001611 | Battery | 596-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 46 | °F |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BAT001611 | Battery | 596-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1500 | psi |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 44 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 50 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 36 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 50 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 36 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 50 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0283 | WithLTC | WS-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 36 | °C |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1186 | BreakerVacuum | WS-1330-1 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1186 | BreakerVacuum | WS-1330-1 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1186 | BreakerVacuum | WS-1330-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1186 | BreakerVacuum | WS-1330-1 | VCB Readings | Operations Counter AL | 173 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1186 | BreakerVacuum | WS-1330-1 | VCB Readings | Operations Counter AF | 173 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1186 | BreakerVacuum | WS-1330-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1186 | BreakerVacuum | WS-1330-1 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1186 | BreakerVacuum | WS-1330-1 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1186 | BreakerVacuum | WS-1330-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1186 | BreakerVacuum | WS-1330-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1186 | BreakerVacuum | WS-1330-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1186 | BreakerVacuum | WS-1330-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1186 | BreakerVacuum | WS-1330-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1186 | BreakerVacuum | WS-1330-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1186 | BreakerVacuum | WS-1330-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1186 | BreakerVacuum | WS-1330-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1186 | BreakerVacuum | WS-1330-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1186 | BreakerVacuum | WS-1330-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1186 | BreakerVacuum | WS-1330-1 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1186 | BreakerVacuum | WS-1330-1 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1186 | BreakerVacuum | WS-1330-1 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1186 | BreakerVacuum | WS-1330-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1186 | BreakerVacuum | WS-1330-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1186 | BreakerVacuum | WS-1330-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1186 | BreakerVacuum | WS-1330-1 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1186 | BreakerVacuum | WS-1330-1 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | W0363 | NonLTC | 596-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Patrol Inspection | General Comments | Indoor switchgear roll in breaker, fix insp to show | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Readings | Operations Counter AF | 150 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Readings | Operations Counter AL | 150 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Readings | 9 Month Operations | 34 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Readings | 9 Month Operations VCB New | 34 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Readings | Amps A Ø | 22.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Readings | Amps B Ø | 22.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Readings | Amps C Ø | 22.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Patrol Inspection | General Comments | Indoor switchgear roll in breaker, fix insp to show | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Readings | Operations Counter AF | 113 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Readings | Operations Counter AL | 113 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001866 | BreakerVacuum | MG-1334-B | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Readings | 9 Month Operations | 23 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Readings | 9 Month Operations VCB New | 23 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Readings | Amps A Ø | 22.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Readings | Amps B Ø | 22.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Readings | Amps C Ø | 22.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Patrol Inspection | General Comments | Indoor switchgear roll in breaker, fix insp to show | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Readings | Operations Counter AF | 112 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Readings | Operations Counter AL | 112 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Readings | 9 Month Operations | 20 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Readings | 9 Month Operations VCB New | 20 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Readings | Amps A Ø | 25.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Readings | Amps B Ø | 25.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Readings | Amps C Ø | 25.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Patrol Inspection | General Comments | Indoor switchgear roll in breaker, fix insp to show | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Readings | Operations Counter AF | 118 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Readings | Operations Counter AL | 118 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001864 | BreakerVacuum | MG-1332-B | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Readings | 9 Month Operations | 17 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Readings | 9 Month Operations VCB New | 17 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Readings | Amps A Ø | 27.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Readings | Amps B Ø | 27.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Readings | Amps C Ø | 27.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001865 | BreakerVacuum | MG-1333-B | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Readings | Operations Counter AF | 110 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Readings | Operations Counter AL | 110 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Readings | 9 Month Operations VCB New | 21 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Readings | Amps A Ø | 271.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Readings | Amps B Ø | 271.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Readings | Amps C Ø | 268.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Readings | Amps C Ø | 37.0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Readings | Amps B Ø | 27.0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Readings | Amps A Ø | 36.0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Patrol Inspection | General Comments | Indoor switchgear roll in breaker, fix insp to show | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Readings | Operations Counter AF | 126 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Readings | Operations Counter AL | 126 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001869 | BreakerVacuum | MG-14KV BUS TIE SEC C-5 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0628 | BreakerAirMagnetic | MG-407 | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0628 | BreakerAirMagnetic | MG-407 | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0628 | BreakerAirMagnetic | MG-407 | AMCB Readings | Operations This Read AM | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0628 | BreakerAirMagnetic | MG-407 | AMCB Readings | Operations Counter AL | 449 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0628 | BreakerAirMagnetic | MG-407 | AMCB Readings | Operations Counter AF | 449 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0628 | BreakerAirMagnetic | MG-407 | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0628 | BreakerAirMagnetic | MG-407 | AMCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0628 | BreakerAirMagnetic | MG-407 | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0628 | BreakerAirMagnetic | MG-407 | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0628 | BreakerAirMagnetic | MG-407 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Patrol Inspection | General Comments | Indoor switchgear roll in breaker, fix insp to show | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Readings | Operations Counter AF | 106 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Readings | Operations Counter AL | 106 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001867 | BreakerVacuum | MG-1335-B | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Readings | Unknown Operations | 2 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Readings | Operations This Read Vac | 3 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Readings | Operations Counter AL | 183 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Readings | 9 Month Operations | 36 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Readings | 9 Month Operations VCB New | 36 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Readings | Amps A Ø | 17.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Readings | Amps B Ø | 17.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Readings | Amps C Ø | 17.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Readings | Operations Counter AF | 183 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Readings | Maintenance Operations | 1 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Readings | General Comments | | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Readings | Fault Adjusted Amps C Phase V | 32.38 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Readings | Fault Adjusted Amps B Phase V | 32.38 | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BK000433 | BreakerVacuum | 405-1651 | VCB Readings | Fault Adjusted Amps A Phase V | 32.38 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001868 | BreakerVacuum | MG-1336-B | VCB Patrol Inspection | General Comments | Indoor switchgear roll in breaker, fix insp to show | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Patrol Inspection | General Comments | Indoor switchgear roll in breaker, fix insp to show | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Readings | Operations Counter AF | 113 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Readings | Operations Counter AL | 113 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Readings | General Comments | | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Readings | LTC Totalizer Reading | 6595.20 | kw |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Readings | Oil Temp Max | 59 | °C |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Readings | 9 Month Operations | 31 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Readings | 9 Month Operations VCB New | 31 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Readings | Amps A Ø | 143.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Readings | Amps B Ø | 142.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Readings | Amps C Ø | 143.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Readings | Totalizer Meter Reading | .9160 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | WithLTC | 570-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | General Comments | Out of service | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Operations Counter AF | 125 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Operations Counter AL | 125 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Readings | 9 Month Operations | 21 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Readings | 9 Month Operations VCB New | 21 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Readings | Amps A Ø | 27.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Readings | Amps B Ø | 27.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Readings | Amps C Ø | 27.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001859 | BreakerVacuum | MG-1335-A | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000876 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | 9 Month Operations | 2 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | General Comments | Out of service. | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Operations Counter AF | 120 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK000877 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Operations Counter AL | 120 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000300 | GroundTransformer | MG-GND TR 5 | Ground Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000300 | GroundTransformer | MG-GND TR 5 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000300 | GroundTransformer | MG-GND TR 5 | Ground Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000300 | GroundTransformer | MG-GND TR 5 | Ground Transformer Patrol Inspection | Cleaned Mechanism Cabinet? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000300 | GroundTransformer | MG-GND TR 5 | Ground Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000300 | GroundTransformer | MG-GND TR 5 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000300 | GroundTransformer | MG-GND TR 5 | Ground Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000300 | GroundTransformer | MG-GND TR 5 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Readings | Operations Counter AF | 174 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Readings | Operations Counter AL | 174 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Readings | 9 Month Operations | 28 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Readings | 9 Month Operations VCB New | 28 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Readings | Amps A Ø | 139.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Readings | Amps B Ø | 138.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Readings | Amps C Ø | 138.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Patrol Inspection | General Comments | Indoor switchgear roll in breaker, fix insp to show | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Readings | Operations Counter AF | 129 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Readings | Operations Counter AL | 129 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001862 | BreakerVacuum | MG-14KV TR 7 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Readings | 9 Month Operations | 20 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Readings | 9 Month Operations VCB New | 20 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001863 | BreakerVacuum | MG-GND TR 7 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Patrol Inspection | General Comments | Indoor switchgear roll in breaker, fix insp to show | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LTCC000231 | LTCControl | WS-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LTCC000231 | LTCControl | WS-TRANS 1 | LTC Control Insp | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LTCC000231 | LTCControl | WS-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Readings | Operations Counter AF | 136 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Readings | Operations Counter AL | 136 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001860 | BreakerVacuum | MG-14KV TR 6 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000300 | GroundTransformer | MG-GND TR 5 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000300 | GroundTransformer | MG-GND TR 5 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000300 | GroundTransformer | MG-GND TR 5 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000300 | GroundTransformer | MG-GND TR 5 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000300 | GroundTransformer | MG-GND TR 5 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000300 | GroundTransformer | MG-GND TR 5 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000300 | GroundTransformer | MG-GND TR 5 | Ground Transformer Patrol Inspection | Pumps Operational? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000300 | GroundTransformer | MG-GND TR 5 | Ground Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000300 | GroundTransformer | MG-GND TR 5 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | -1.0 | psi |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000300 | GroundTransformer | MG-GND TR 5 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000300 | GroundTransformer | MG-GND TR 5 | Ground Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000300 | GroundTransformer | MG-GND TR 5 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000300 | GroundTransformer | MG-GND TR 5 | Ground Transformer Patrol Inspection | Gas Accumulation Gauge | Normal | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000300 | GroundTransformer | MG-GND TR 5 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Readings | 9 Month Operations | 27 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Readings | 9 Month Operations VCB New | 27 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Readings | Amps A Ø | 23.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Readings | Amps B Ø | 24.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Readings | Amps C Ø | 25.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Patrol Inspection | General Comments | Indoor switchgear roll in breaker, fix insp to show | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK001861 | BreakerVacuum | MG-14KV BUS TIE SEC 7-6 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000300 | GroundTransformer | MG-GND TR 5 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | TX000300 | GroundTransformer | MG-GND TR 5 | Ground Transformer Patrol Inspection | Fans Operational? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000414 | PowerFuse | WS-1471 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000414 | PowerFuse | WS-1471 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0613 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0613 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0613 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0613 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Operations Counter AL | 1432 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0613 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Operations Counter AF | 1432 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0613 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0613 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0613 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0613 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0613 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0613 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0613 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0613 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0613 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0613 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0613 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0613 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0613 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0613 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0613 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0613 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0613 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0613 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0613 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0613 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | 9 Months Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0613 | BreakerAirMagnetic | MG-Offline-Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | PF000327 | PowerFuse | SV-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | k | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | PF000327 | PowerFuse | SV-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | PF000327 | PowerFuse | SV-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000387 | PowerFuse | WS-14KV BUS SEC 3 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000387 | PowerFuse | WS-14KV BUS SEC 3 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000136 | Switchgear | MG-14KV Sec C Swgr | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000136 | Switchgear | MG-14KV Sec C Swgr | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000136 | Switchgear | MG-14KV Sec C Swgr | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000136 | Switchgear | MG-14KV Sec C Swgr | Switchgear Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000136 | Switchgear | MG-14KV Sec C Swgr | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000136 | Switchgear | MG-14KV Sec C Swgr | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000135 | Switchgear | MG-4KV Sec 2 Swgr | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000135 | Switchgear | MG-4KV Sec 2 Swgr | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000135 | Switchgear | MG-4KV Sec 2 Swgr | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | FE000568 | Fence | MK-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | FE000568 | Fence | MK-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | FE000568 | Fence | MK-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | FE000568 | Fence | MK-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | FE000568 | Fence | MK-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | FE000568 | Fence | MK-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Readings | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Readings | Operations Counter AF | 90 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Readings | Operations Counter AL | 90 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | FE000568 | Fence | MK-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Operations Counter AF | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | FE000568 | Fence | MK-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | FE000568 | Fence | MK-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | FE000568 | Fence | MK-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | FE000568 | Fence | MK-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | FE000568 | Fence | MK-Fence | Fence Patrol Inspection | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | FE000568 | Fence | MK-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | FE000568 | Fence | MK-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1236 | BreakerVacuum | WS-14KV TR 4 | VCB Readings | 9 Month Operations | 1 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Operations Counter AL | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Readings | Amps A Ø | 30.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Readings | Amps B Ø | 30.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Readings | Amps C Ø | 30.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000135 | Switchgear | MG-4KV Sec 2 Swgr | Switchgear Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000135 | Switchgear | MG-4KV Sec 2 Swgr | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000135 | Switchgear | MG-4KV Sec 2 Swgr | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000135 | Switchgear | MG-4KV Sec 2 Swgr | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000135 | Switchgear | MG-4KV Sec 2 Swgr | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Readings | Fault Adjusted Amps B Phase V | 1.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Readings | Fault Adjusted Amps C Phase V | 1.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Readings | Fault Operations B Ø | 1 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Readings | Fault Operations C Ø | 1 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Readings | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Operations Counter AF | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Operations Counter AL | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Readings | Operations Counter AF | 65 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Readings | Operations Counter AL | 65 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Readings | Operations This Read Vac | 2 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | SWG000135 | Switchgear | MG-4KV Sec 2 Swgr | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LTCC000273 | LTCControl | MK-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000417 | PowerFuse | WS-STA SER NO 4 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000417 | PowerFuse | WS-STA SER NO 4 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000416 | PowerFuse | WS-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000416 | PowerFuse | WS-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000415 | PowerFuse | WS-FUTURE SOUTH LINE POTS | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000415 | PowerFuse | WS-FUTURE SOUTH LINE POTS | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LTCC000273 | LTCControl | MK-TRANS 1 | LTC Control Insp | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LTCC000273 | LTCControl | MK-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | 9 Month Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | YD000021 | Yard | 494-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | YD000021 | Yard | 494-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | YD000021 | Yard | 494-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | YD000021 | Yard | 494-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | YD000021 | Yard | 494-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | YD000021 | Yard | 494-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | YD000021 | Yard | 494-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | YD000021 | Yard | 494-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | YD000021 | Yard | 494-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | YD000021 | Yard | 494-Yard | Yard Patrol Inspection | General Comments | | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | YD000021 | Yard | 494-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | YD000021 | Yard | 494-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | YD000021 | Yard | 494-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Readings | Fault Adjusted Amps C Phase V | 1.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Readings | Fault Operations C Ø | 1 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Readings | Follow-up Action Required? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Readings | General Comments | c phase ioc, vc may not be working | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Readings | Operations Counter AF | 93 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Readings | Operations Counter AL | 93 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Readings | Operations This Read Vac | 1 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000216 | PowerFuse | MG-407 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000223 | PowerFuse | MG-14KV BUS SEC C POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000223 | PowerFuse | MG-14KV BUS SEC C POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000223 | PowerFuse | MG-14KV BUS SEC C POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000211 | PowerFuse | MG-4KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000211 | PowerFuse | MG-4KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000211 | PowerFuse | MG-4KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Readings | General Comments | | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 4176.00 | kw |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Readings | Oil Temp Max | 60 | °C |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Readings | Oil Temp Present | 45 | °C |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000406 | PowerFuse | WS-1332 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000406 | PowerFuse | WS-1332 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000394 | PowerFuse | WS-1429 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000394 | PowerFuse | WS-1429 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | PF000429 | PowerFuse | WO-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | PF000429 | PowerFuse | WO-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | PF000429 | PowerFuse | WO-12KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | BCH001088 | Charger | SV-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.200 | millivolts |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | BCH001088 | Charger | SV-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | BCH001088 | Charger | SV-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | BCH001088 | Charger | SV-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 3.1 | amps |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | BCH001088 | Charger | SV-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0851 | BreakerAirMagnetic | SV-1122 | AMCB Readings | Switching Operations | 5 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0851 | BreakerAirMagnetic | SV-1122 | AMCB Readings | Operations This Read AM | 8 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | BCH001088 | Charger | SV-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | BCH001088 | Charger | SV-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Readings | 9 Month Operations | 4 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0851 | BreakerAirMagnetic | SV-1122 | AMCB Readings | Operations Counter AL | 1319 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0851 | BreakerAirMagnetic | SV-1122 | AMCB Readings | Operations Counter AF | 1319 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0851 | BreakerAirMagnetic | SV-1122 | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Readings | Operations Counter AF | 155 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Readings | Operations Counter AL | 155 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Readings | Operations This Read Vac | 2 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Readings | Amps A Ø | 36.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Readings | Amps C Ø | 6.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Readings | Unknown Operations | 1 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000216 | PowerFuse | MG-407 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000216 | PowerFuse | MG-407 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000741 | BreakerVacuum | MK-1291 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000410 | PowerFuse | WS-1475 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1236 | BreakerVacuum | WS-14KV TR 4 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1236 | BreakerVacuum | WS-14KV TR 4 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1236 | BreakerVacuum | WS-14KV TR 4 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1236 | BreakerVacuum | WS-14KV TR 4 | VCB Readings | Operations Counter AL | 188 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1236 | BreakerVacuum | WS-14KV TR 4 | VCB Readings | Operations Counter AF | 188 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1236 | BreakerVacuum | WS-14KV TR 4 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1236 | BreakerVacuum | WS-14KV TR 4 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1236 | BreakerVacuum | WS-14KV TR 4 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1236 | BreakerVacuum | WS-14KV TR 4 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1236 | BreakerVacuum | WS-14KV TR 4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1236 | BreakerVacuum | WS-14KV TR 4 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1236 | BreakerVacuum | WS-14KV TR 4 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1236 | BreakerVacuum | WS-14KV TR 4 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1236 | BreakerVacuum | WS-14KV TR 4 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1236 | BreakerVacuum | WS-14KV TR 4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Readings | 9 Month Operations | 1 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1236 | BreakerVacuum | WS-14KV TR 4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1236 | BreakerVacuum | WS-14KV TR 4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000410 | PowerFuse | WS-1475 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1236 | BreakerVacuum | WS-14KV TR 4 | VCB Readings | Amps C Ø | 410.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1236 | BreakerVacuum | WS-14KV TR 4 | VCB Readings | Amps B Ø | 410.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Readings | Amps A Ø | 350.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Readings | Amps B Ø | 400.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Readings | Amps C Ø | 410.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000742 | BreakerVacuum | MK-12KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1236 | BreakerVacuum | WS-14KV TR 4 | VCB Readings | Amps A Ø | 414.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1236 | BreakerVacuum | WS-14KV TR 4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1236 | BreakerVacuum | WS-14KV TR 4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1236 | BreakerVacuum | WS-14KV TR 4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1236 | BreakerVacuum | WS-14KV TR 4 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | FE000568 | Fence | MK-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | FE000568 | Fence | MK-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0851 | BreakerAirMagnetic | SV-1122 | AMCB Readings | General Comments | | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0851 | BreakerAirMagnetic | SV-1122 | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0851 | BreakerAirMagnetic | SV-1122 | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0851 | BreakerAirMagnetic | SV-1122 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0851 | BreakerAirMagnetic | SV-1122 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0851 | BreakerAirMagnetic | SV-1122 | AMCB Readings | Fault Operations C Ø | 1 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0851 | BreakerAirMagnetic | SV-1122 | AMCB Readings | Fault Operations B Ø | 1 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000227 | PowerFuse | MG-14KV TR 5 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0851 | BreakerAirMagnetic | SV-1122 | AMCB Readings | Fault Operations A Ø | 1 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0851 | BreakerAirMagnetic | SV-1122 | AMCB Readings | Fault Adjusted Amps C Phase AM | 11.18 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0851 | BreakerAirMagnetic | SV-1122 | AMCB Readings | Fault Adjusted Amps B Phase AM | 11.18 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0851 | BreakerAirMagnetic | SV-1122 | AMCB Readings | Fault Adjusted Amps A Phase AM | 11.18 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0851 | BreakerAirMagnetic | SV-1122 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0851 | BreakerAirMagnetic | SV-1122 | AMCB Readings | Amps C Ø | 100.0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0851 | BreakerAirMagnetic | SV-1122 | AMCB Readings | Amps B Ø | 140.0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0851 | BreakerAirMagnetic | SV-1122 | AMCB Readings | Amps A Ø | 120.0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0851 | BreakerAirMagnetic | SV-1122 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0851 | BreakerAirMagnetic | SV-1122 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000227 | PowerFuse | MG-14KV TR 5 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000227 | PowerFuse | MG-14KV TR 5 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0851 | BreakerAirMagnetic | SV-1122 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0851 | BreakerAirMagnetic | SV-1122 | AMCB Readings | 9 Months Operations | 13 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LB0851 | BreakerAirMagnetic | SV-1122 | AMCB Readings | 9 Month Ops New | 5 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | M0057 | NonLTC | 494-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .8700 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | 9 Month Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002325 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000098 | Switchgear | SV-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000098 | Switchgear | SV-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000098 | Switchgear | SV-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1243 | BreakerVacuum | WS-1331-4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1243 | BreakerVacuum | WS-1331-4 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1243 | BreakerVacuum | WS-1331-4 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1243 | BreakerVacuum | WS-1331-4 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1243 | BreakerVacuum | WS-1331-4 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1243 | BreakerVacuum | WS-1331-4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1243 | BreakerVacuum | WS-1331-4 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1243 | BreakerVacuum | WS-1331-4 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1243 | BreakerVacuum | WS-1331-4 | VCB Readings | General Comments | | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000098 | Switchgear | SV-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | heater number 2 not working, replaced | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000098 | Switchgear | SV-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1243 | BreakerVacuum | WS-1331-4 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1243 | BreakerVacuum | WS-1331-4 | VCB Readings | Operations Counter AF | 102 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000098 | Switchgear | SV-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000098 | Switchgear | SV-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000098 | Switchgear | SV-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000098 | Switchgear | SV-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000098 | Switchgear | SV-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000098 | Switchgear | SV-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000098 | Switchgear | SV-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000098 | Switchgear | SV-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000098 | Switchgear | SV-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0523 | BreakerVacuum | JT-1124 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0523 | BreakerVacuum | JT-1124 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0523 | BreakerVacuum | JT-1124 | VCB Readings | Operations This Read Vac | 8 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0523 | BreakerVacuum | JT-1124 | VCB Readings | Operations Counter AL | 430 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0523 | BreakerVacuum | JT-1124 | VCB Readings | Operations Counter AF | 430 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0523 | BreakerVacuum | JT-1124 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0523 | BreakerVacuum | JT-1124 | VCB Readings | General Comments | ABC Phase IOC | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1243 | BreakerVacuum | WS-1331-4 | VCB Readings | Operations Counter AL | 102 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1243 | BreakerVacuum | WS-1331-4 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1243 | BreakerVacuum | WS-1331-4 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1243 | BreakerVacuum | WS-1331-4 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | PF000188 | PowerFuse | JT-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | PF000188 | PowerFuse | JT-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | PF000188 | PowerFuse | JT-12KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | PF000187 | PowerFuse | JT-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | PF000187 | PowerFuse | JT-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | PF000187 | PowerFuse | JT-STA SER NO 2 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000413 | PowerFuse | WS-1472 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000413 | PowerFuse | WS-1472 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000412 | PowerFuse | WS-1473 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000412 | PowerFuse | WS-1473 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0603 | BreakerAirMagnetic | MG-1323 | AMCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0603 | BreakerAirMagnetic | MG-1323 | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1243 | BreakerVacuum | WS-1331-4 | VCB Readings | 9 Month Operations | 5 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1243 | BreakerVacuum | WS-1331-4 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | PF000428 | PowerFuse | WO-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | PF000428 | PowerFuse | WO-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | PF000428 | PowerFuse | WO-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1243 | BreakerVacuum | WS-1331-4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1243 | BreakerVacuum | WS-1331-4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1243 | BreakerVacuum | WS-1331-4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1243 | BreakerVacuum | WS-1331-4 | VCB Readings | Amps A Ø | 67.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1243 | BreakerVacuum | WS-1331-4 | VCB Readings | Amps B Ø | 67.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1243 | BreakerVacuum | WS-1331-4 | VCB Readings | Amps C Ø | 65.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0603 | BreakerAirMagnetic | MG-1323 | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0603 | BreakerAirMagnetic | MG-1323 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0603 | BreakerAirMagnetic | MG-1323 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1243 | BreakerVacuum | WS-1331-4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1243 | BreakerVacuum | WS-1331-4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0603 | BreakerAirMagnetic | MG-1323 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0603 | BreakerAirMagnetic | MG-1323 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0603 | BreakerAirMagnetic | MG-1323 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0603 | BreakerAirMagnetic | MG-1323 | AMCB Readings | Fault Adjusted Amps C Phase AM | 11.18 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0526 | BreakerVacuum | JT-12KV TR 2 | VCB Readings | Amps B Ø | 392.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0526 | BreakerVacuum | JT-12KV TR 2 | VCB Readings | Amps A Ø | 398.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0526 | BreakerVacuum | JT-12KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0526 | BreakerVacuum | JT-12KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0526 | BreakerVacuum | JT-12KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0526 | BreakerVacuum | JT-12KV TR 2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0526 | BreakerVacuum | JT-12KV TR 2 | VCB Readings | 9 Month Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1243 | BreakerVacuum | WS-1331-4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0603 | BreakerAirMagnetic | MG-1323 | AMCB Readings | Fault Adjusted Amps B Phase AM | 11.18 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0603 | BreakerAirMagnetic | MG-1323 | AMCB Readings | Fault Adjusted Amps A Phase AM | 11.18 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0603 | BreakerAirMagnetic | MG-1323 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0603 | BreakerAirMagnetic | MG-1323 | AMCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0603 | BreakerAirMagnetic | MG-1323 | AMCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0603 | BreakerAirMagnetic | MG-1323 | AMCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0603 | BreakerAirMagnetic | MG-1323 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0603 | BreakerAirMagnetic | MG-1323 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0603 | BreakerAirMagnetic | MG-1323 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0603 | BreakerAirMagnetic | MG-1323 | AMCB Readings | 9 Months Operations | 1 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0603 | BreakerAirMagnetic | MG-1323 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000098 | Switchgear | SV-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000098 | Switchgear | SV-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000098 | Switchgear | SV-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000098 | Switchgear | SV-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000098 | Switchgear | SV-Swgr Sec 1 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | SWG000098 | Switchgear | SV-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000132 | Regulator | 571-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0523 | BreakerVacuum | JT-1124 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0523 | BreakerVacuum | JT-1124 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0523 | BreakerVacuum | JT-1124 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0523 | BreakerVacuum | JT-1124 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0523 | BreakerVacuum | JT-1124 | VCB Readings | Fault Operations C Ø | 2 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0523 | BreakerVacuum | JT-1124 | VCB Readings | Fault Operations B Ø | 3 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0523 | BreakerVacuum | JT-1124 | VCB Readings | Fault Operations A Ø | 3 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0523 | BreakerVacuum | JT-1124 | VCB Readings | Fault Adjusted Amps C Phase V | 22.36 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0523 | BreakerVacuum | JT-1124 | VCB Readings | Fault Adjusted Amps B Phase V | 33.54 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0523 | BreakerVacuum | JT-1124 | VCB Readings | Fault Adjusted Amps A Phase V | 33.54 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0523 | BreakerVacuum | JT-1124 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1181 | BreakerVacuum | WS-1310-1 | VCB Readings | Operations Counter AL | 154 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1181 | BreakerVacuum | WS-1310-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1181 | BreakerVacuum | WS-1310-1 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1181 | BreakerVacuum | WS-1310-1 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0627 | BreakerAirMagnetic | MG-14KV TR 5 | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0523 | BreakerVacuum | JT-1124 | VCB Readings | Amps C Ø | 94.0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Readings | General Comments | | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 5094.72 | kw |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0523 | BreakerVacuum | JT-1124 | VCB Readings | Amps B Ø | 44.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0523 | BreakerVacuum | JT-1124 | VCB Readings | Amps A Ø | 59.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0523 | BreakerVacuum | JT-1124 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0523 | BreakerVacuum | JT-1124 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0523 | BreakerVacuum | JT-1124 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0523 | BreakerVacuum | JT-1124 | VCB Readings | 9 Month Operations VCB New | 23 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0523 | BreakerVacuum | JT-1124 | VCB Readings | 9 Month Operations | 31 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1334 | BreakerVacuum | JT-1127 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Readings | Oil Temp Max | 60 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000411 | PowerFuse | WS-1474 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000411 | PowerFuse | WS-1474 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000409 | PowerFuse | WS-1303 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000409 | PowerFuse | WS-1303 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000408 | PowerFuse | WS-1304 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000408 | PowerFuse | WS-1304 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000407 | PowerFuse | WS-1331 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000407 | PowerFuse | WS-1331 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000405 | PowerFuse | WS-1333 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000405 | PowerFuse | WS-1333 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000404 | PowerFuse | WS-1334 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000404 | PowerFuse | WS-1334 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000132 | Regulator | 571-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000132 | Regulator | 571-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000132 | Regulator | 571-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000132 | Regulator | 571-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000132 | Regulator | 571-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 12963 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000132 | Regulator | 571-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000403 | PowerFuse | WS-1335 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000403 | PowerFuse | WS-1335 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1181 | BreakerVacuum | WS-1310-1 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1181 | BreakerVacuum | WS-1310-1 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1181 | BreakerVacuum | WS-1310-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1181 | BreakerVacuum | WS-1310-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1181 | BreakerVacuum | WS-1310-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1181 | BreakerVacuum | WS-1310-1 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1181 | BreakerVacuum | WS-1310-1 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1181 | BreakerVacuum | WS-1310-1 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1181 | BreakerVacuum | WS-1310-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1181 | BreakerVacuum | WS-1310-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1181 | BreakerVacuum | WS-1310-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1181 | BreakerVacuum | WS-1310-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1181 | BreakerVacuum | WS-1310-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1181 | BreakerVacuum | WS-1310-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1181 | BreakerVacuum | WS-1310-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1181 | BreakerVacuum | WS-1310-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1181 | BreakerVacuum | WS-1310-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | BAT001656 | Battery | 481-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.5 | VDC |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | BAT001656 | Battery | 481-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.5 | VDC |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | BAT001656 | Battery | 481-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | BAT001656 | Battery | 481-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1181 | BreakerVacuum | WS-1310-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1181 | BreakerVacuum | WS-1310-1 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1181 | BreakerVacuum | WS-1310-1 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1181 | BreakerVacuum | WS-1310-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1181 | BreakerVacuum | WS-1310-1 | VCB Readings | Operations Counter AF | 154 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000132 | Regulator | 571-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 41 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 28 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 41 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 28 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 41 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations | 1 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | CH000206 | ControlHouse | WO-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | CH000206 | ControlHouse | WO-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | CH000206 | ControlHouse | WO-Control House | Control House Patrol Inspection | General Comments | Theres one light on the outside of the control house not working. | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | CH000206 | ControlHouse | WO-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | CH000206 | ControlHouse | WO-Control House | Control House Patrol Inspection | Follow-up Action Required? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | CH000206 | ControlHouse | WO-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | CH000206 | ControlHouse | WO-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | CH000206 | ControlHouse | WO-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | CH000206 | ControlHouse | WO-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000396 | PowerFuse | WS-1427 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000393 | PowerFuse | WS-FUTURE NORTH LINE POTS | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000393 | PowerFuse | WS-FUTURE NORTH LINE POTS | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000392 | PowerFuse | WS-14KV TR 4 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000392 | PowerFuse | WS-14KV TR 4 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000391 | PowerFuse | WS-14KV TR 3 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000391 | PowerFuse | WS-14KV TR 3 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000390 | PowerFuse | WS-14KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000390 | PowerFuse | WS-14KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | PF000330 | PowerFuse | SV-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | PF000330 | PowerFuse | SV-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | PF000330 | PowerFuse | SV-STA SER NO 2 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | PF000329 | PowerFuse | SV-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | PF000329 | PowerFuse | SV-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | PF000329 | PowerFuse | SV-12KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | PF000328 | PowerFuse | SV-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | k | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | PF000328 | PowerFuse | SV-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | PF000328 | PowerFuse | SV-12KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000389 | PowerFuse | WS-14KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BK002326 | BreakerVacuum | MG-Offline-Distribution | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | BAT001656 | Battery | 481-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | BAT001656 | Battery | 481-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | BAT001656 | Battery | 481-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000743 | BreakerVacuum | MK-1290 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | BAT001656 | Battery | 481-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | BAT001656 | Battery | 481-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | BAT001656 | Battery | 481-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | BAT001656 | Battery | 481-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | BAT001656 | Battery | 481-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000402 | PowerFuse | WS-1336 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000402 | PowerFuse | WS-1336 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000401 | PowerFuse | WS-1337 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 28 | °C |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BAT001127 | Battery | 570-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BAT001127 | Battery | 570-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | CH000206 | ControlHouse | WO-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | CH000206 | ControlHouse | WO-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | CH000206 | ControlHouse | WO-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | CH000206 | ControlHouse | WO-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | CH000206 | ControlHouse | WO-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | CH000206 | ControlHouse | WO-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BAT001127 | Battery | 570-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.2 | VDC |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BAT001127 | Battery | 570-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.3 | VDC |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000401 | PowerFuse | WS-1337 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000400 | PowerFuse | WS-FUTURE 5-6 LINE POTS | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000400 | PowerFuse | WS-FUTURE 5-6 LINE POTS | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000399 | PowerFuse | WS-FUTURE 7-8 LINE POTS | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000399 | PowerFuse | WS-FUTURE 7-8 LINE POTS | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000398 | PowerFuse | WS-1425 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000398 | PowerFuse | WS-1425 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000397 | PowerFuse | WS-1426 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000397 | PowerFuse | WS-1426 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000396 | PowerFuse | WS-1427 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BAT001127 | Battery | 570-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BAT001127 | Battery | 570-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BAT001127 | Battery | 570-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BAT001127 | Battery | 570-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BAT001127 | Battery | 570-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BAT001127 | Battery | 570-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BAT001127 | Battery | 570-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BAT001127 | Battery | 570-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BAT001127 | Battery | 570-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BAT001127 | Battery | 570-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AF | 106 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AL | 106 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 27 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 41 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1600 | psi |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0526 | BreakerVacuum | JT-12KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0284 | WithLTC | WS-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0526 | BreakerVacuum | JT-12KV TR 2 | VCB Readings | Amps C Ø | 519.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000386 | PowerFuse | WS-14KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000385 | PowerFuse | WS-14KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000385 | PowerFuse | WS-14KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0603 | BreakerAirMagnetic | MG-1323 | AMCB Readings | Unknown Operations | 1 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0603 | BreakerAirMagnetic | MG-1323 | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0603 | BreakerAirMagnetic | MG-1323 | AMCB Readings | Operations This Read AM | 1 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0603 | BreakerAirMagnetic | MG-1323 | AMCB Readings | Operations Counter AL | 50 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0603 | BreakerAirMagnetic | MG-1323 | AMCB Readings | Operations Counter AF | 50 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0603 | BreakerAirMagnetic | MG-1323 | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000389 | PowerFuse | WS-14KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000388 | PowerFuse | WS-14KV BUS SEC 4 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000388 | PowerFuse | WS-14KV BUS SEC 4 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000386 | PowerFuse | WS-14KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0526 | BreakerVacuum | JT-12KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0526 | BreakerVacuum | JT-12KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0526 | BreakerVacuum | JT-12KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0526 | BreakerVacuum | JT-12KV TR 2 | VCB Readings | Operations Counter AL | 262 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0526 | BreakerVacuum | JT-12KV TR 2 | VCB Readings | Operations Counter AF | 262 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0526 | BreakerVacuum | JT-12KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0526 | BreakerVacuum | JT-12KV TR 2 | VCB Readings | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0526 | BreakerVacuum | JT-12KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0526 | BreakerVacuum | JT-12KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0526 | BreakerVacuum | JT-12KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0526 | BreakerVacuum | JT-12KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0526 | BreakerVacuum | JT-12KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0526 | BreakerVacuum | JT-12KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0526 | BreakerVacuum | JT-12KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0526 | BreakerVacuum | JT-12KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0526 | BreakerVacuum | JT-12KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0526 | BreakerVacuum | JT-12KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | CH000206 | ControlHouse | WO-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | CH000206 | ControlHouse | WO-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | CH000206 | ControlHouse | WO-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | CH000206 | ControlHouse | WO-Control House | Control House Patrol Inspection | Control House Lighting OK? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | CH000206 | ControlHouse | WO-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | CH000206 | ControlHouse | WO-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | CH000206 | ControlHouse | WO-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Readings | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000744 | BreakerVacuum | MK-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0634 | BreakerAirMagnetic | MG-464 | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0634 | BreakerAirMagnetic | MG-464 | AMCB Readings | Unknown Operations | 1 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1198 | BreakerVacuum | WS-FUTURE-7 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1198 | BreakerVacuum | WS-FUTURE-7 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1198 | BreakerVacuum | WS-FUTURE-7 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1198 | BreakerVacuum | WS-FUTURE-7 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1198 | BreakerVacuum | WS-FUTURE-7 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1198 | BreakerVacuum | WS-FUTURE-7 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1198 | BreakerVacuum | WS-FUTURE-7 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1198 | BreakerVacuum | WS-FUTURE-7 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1198 | BreakerVacuum | WS-FUTURE-7 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1198 | BreakerVacuum | WS-FUTURE-7 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1198 | BreakerVacuum | WS-FUTURE-7 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1198 | BreakerVacuum | WS-FUTURE-7 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1198 | BreakerVacuum | WS-FUTURE-7 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1198 | BreakerVacuum | WS-FUTURE-7 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1198 | BreakerVacuum | WS-FUTURE-7 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1198 | BreakerVacuum | WS-FUTURE-7 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1198 | BreakerVacuum | WS-FUTURE-7 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1198 | BreakerVacuum | WS-FUTURE-7 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1198 | BreakerVacuum | WS-FUTURE-7 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1198 | BreakerVacuum | WS-FUTURE-7 | VCB Readings | Operations Counter AF | 76 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1198 | BreakerVacuum | WS-FUTURE-7 | VCB Readings | Operations Counter AL | 76 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1198 | BreakerVacuum | WS-FUTURE-7 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1198 | BreakerVacuum | WS-FUTURE-7 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1198 | BreakerVacuum | WS-FUTURE-7 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | FE000664 | Fence | WO-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | FE000664 | Fence | WO-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | FE000664 | Fence | WO-Fence | Fence Patrol Inspection | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | FE000664 | Fence | WO-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | FE000664 | Fence | WO-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | FE000664 | Fence | WO-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | FE000664 | Fence | WO-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | FE000664 | Fence | WO-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | FE000664 | Fence | WO-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | FE000664 | Fence | WO-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | FE000664 | Fence | WO-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | FE000664 | Fence | WO-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | FE000664 | Fence | WO-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | FE000664 | Fence | WO-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | FE000664 | Fence | WO-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | FE000664 | Fence | WO-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | LTCC000807 | LTCControl | 418-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | LTCC000807 | LTCControl | 418-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | LTCC000807 | LTCControl | 418-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | LTCC000807 | LTCControl | 418-1 | LTC Control Insp | LTC Output Voltage Level | 124.3 | VAC |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BAT000469 | Battery | 439-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BAT000469 | Battery | 439-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.4 | VDC |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BAT000469 | Battery | 439-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.1 | VDC |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BAT000469 | Battery | 439-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BAT000469 | Battery | 439-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0634 | BreakerAirMagnetic | MG-464 | AMCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0634 | BreakerAirMagnetic | MG-464 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0634 | BreakerAirMagnetic | MG-464 | AMCB Readings | Fault Adjusted Amps A Phase AM | 9.55 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0634 | BreakerAirMagnetic | MG-464 | AMCB Readings | Fault Adjusted Amps B Phase AM | 9.55 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0634 | BreakerAirMagnetic | MG-464 | AMCB Readings | Fault Adjusted Amps C Phase AM | 9.55 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0634 | BreakerAirMagnetic | MG-464 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0634 | BreakerAirMagnetic | MG-464 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0634 | BreakerAirMagnetic | MG-464 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0634 | BreakerAirMagnetic | MG-464 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0634 | BreakerAirMagnetic | MG-464 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0629 | BreakerAirMagnetic | MG-411 | AMCB Readings | General Comments | ABC Phase IOC | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0629 | BreakerAirMagnetic | MG-411 | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0629 | BreakerAirMagnetic | MG-411 | AMCB Readings | Operations Counter AF | 605 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | BCH000452 | Charger | 571-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | BCH000452 | Charger | 571-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | BCH000452 | Charger | 571-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | BCH000452 | Charger | 571-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | BCH000452 | Charger | 571-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.2 | amps |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | BCH000452 | Charger | 571-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | BCH000452 | Charger | 571-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0629 | BreakerAirMagnetic | MG-411 | AMCB Readings | Operations Counter AL | 605 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0629 | BreakerAirMagnetic | MG-411 | AMCB Readings | Operations This Read AM | 6 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0629 | BreakerAirMagnetic | MG-411 | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0629 | BreakerAirMagnetic | MG-411 | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | BCH000452 | Charger | 571-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.300 | millivolts |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BCH000446 | Charger | 405-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BCH000446 | Charger | 405-Battery Charger | Battery Charger Patrol Insp | General Comments | When enter Float volts give Error and have to overide at close, | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BCH000446 | Charger | 405-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | y | |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BCH000446 | Charger | 405-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BCH000446 | Charger | 405-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.5 | amps |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BCH000446 | Charger | 405-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.1 | VDC |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BCH000446 | Charger | 405-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.1 | VDC |
| 3/9/2023 9:31 | Distribution | Central City South Quarterly Inspection | BCH000446 | Charger | 405-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.800 | millivolts |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1198 | BreakerVacuum | WS-FUTURE-7 | VCB Readings | 9 Month Operations | 4 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1198 | BreakerVacuum | WS-FUTURE-7 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0634 | BreakerAirMagnetic | MG-464 | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0634 | BreakerAirMagnetic | MG-464 | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0634 | BreakerAirMagnetic | MG-464 | AMCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0634 | BreakerAirMagnetic | MG-464 | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0634 | BreakerAirMagnetic | MG-464 | AMCB Readings | Operations Counter AF | 351 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0634 | BreakerAirMagnetic | MG-464 | AMCB Readings | Operations Counter AL | 351 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0634 | BreakerAirMagnetic | MG-464 | AMCB Readings | Operations This Read AM | 1 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | ST000071 | Structure | 570-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | ST000071 | Structure | 570-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | ST000071 | Structure | 570-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | ST000071 | Structure | 570-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | ST000071 | Structure | 570-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | ST000071 | Structure | 570-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | YD000063 | Yard | 570-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | YD000063 | Yard | 570-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | YD000063 | Yard | 570-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | YD000063 | Yard | 570-Yard | Yard Patrol Inspection | General Comments | | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | YD000063 | Yard | 570-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | YD000063 | Yard | 570-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | YD000063 | Yard | 570-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | YD000063 | Yard | 570-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | YD000063 | Yard | 570-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | YD000063 | Yard | 570-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | YD000063 | Yard | 570-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | YD000063 | Yard | 570-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | FE000063 | Fence | 570-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | FE000063 | Fence | 570-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0637 | BreakerAirMagnetic | MG-4KV TR 1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0637 | BreakerAirMagnetic | MG-4KV TR 1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0637 | BreakerAirMagnetic | MG-4KV TR 1 | AMCB Readings | Amps A Ø | 233.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0637 | BreakerAirMagnetic | MG-4KV TR 1 | AMCB Readings | Amps B Ø | 215.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0637 | BreakerAirMagnetic | MG-4KV TR 1 | AMCB Readings | Amps C Ø | 230.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0637 | BreakerAirMagnetic | MG-4KV TR 1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0637 | BreakerAirMagnetic | MG-4KV TR 1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0637 | BreakerAirMagnetic | MG-4KV TR 1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0637 | BreakerAirMagnetic | MG-4KV TR 1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0637 | BreakerAirMagnetic | MG-4KV TR 1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0637 | BreakerAirMagnetic | MG-4KV TR 1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0637 | BreakerAirMagnetic | MG-4KV TR 1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0637 | BreakerAirMagnetic | MG-4KV TR 1 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0637 | BreakerAirMagnetic | MG-4KV TR 1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0637 | BreakerAirMagnetic | MG-4KV TR 1 | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0637 | BreakerAirMagnetic | MG-4KV TR 1 | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0637 | BreakerAirMagnetic | MG-4KV TR 1 | AMCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0637 | BreakerAirMagnetic | MG-4KV TR 1 | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | FE000063 | Fence | 570-Fence | Fence Patrol Inspection | General Comments | Limbs growing over top of fence | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | FE000063 | Fence | 570-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | FE000063 | Fence | 570-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | FE000063 | Fence | 570-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1230 | BreakerVacuum | WS-14KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1230 | BreakerVacuum | WS-14KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0637 | BreakerAirMagnetic | MG-4KV TR 1 | AMCB Readings | Operations Counter AF | 277 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0637 | BreakerAirMagnetic | MG-4KV TR 1 | AMCB Readings | Operations Counter AL | 277 | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | LTCC000807 | LTCControl | 418-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | LTCC000807 | LTCControl | 418-1 | LTC Control Insp | General Comments | | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | LTCC000807 | LTCControl | 418-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/9/2023 13:29 | Distribution | Texas Gas Quarterly Inspection | LTCC000807 | LTCControl | 418-1 | LTC Control Insp | All Connections OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0637 | BreakerAirMagnetic | MG-4KV TR 1 | AMCB Readings | 9 Month Ops New | 2 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0637 | BreakerAirMagnetic | MG-4KV TR 1 | AMCB Readings | 9 Months Operations | 2 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0637 | BreakerAirMagnetic | MG-4KV TR 1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1230 | BreakerVacuum | WS-14KV TR 1 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1230 | BreakerVacuum | WS-14KV TR 1 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1230 | BreakerVacuum | WS-14KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1230 | BreakerVacuum | WS-14KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | ST000071 | Structure | 570-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | ST000071 | Structure | 570-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | ST000071 | Structure | 570-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | ST000071 | Structure | 570-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | ST000071 | Structure | 570-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | ST000071 | Structure | 570-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | ST000071 | Structure | 570-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1230 | BreakerVacuum | WS-14KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1230 | BreakerVacuum | WS-14KV TR 1 | VCB Readings | Amps A Ø | 514.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1230 | BreakerVacuum | WS-14KV TR 1 | VCB Readings | Amps B Ø | 501.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1230 | BreakerVacuum | WS-14KV TR 1 | VCB Readings | Amps C Ø | 503.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1230 | BreakerVacuum | WS-14KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1230 | BreakerVacuum | WS-14KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | ST000071 | Structure | 570-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | ST000071 | Structure | 570-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | ST000071 | Structure | 570-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | ST000071 | Structure | 570-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | ST000071 | Structure | 570-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | ST000071 | Structure | 570-Structure | Structure Patrol Inspection | General Comments | 2 blown LA on A and B phase...one structure leg foundation is crumbling and another is starting to | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | ST000071 | Structure | 570-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | ST000071 | Structure | 570-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | ST000071 | Structure | 570-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1230 | BreakerVacuum | WS-14KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1230 | BreakerVacuum | WS-14KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1230 | BreakerVacuum | WS-14KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1230 | BreakerVacuum | WS-14KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1230 | BreakerVacuum | WS-14KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1230 | BreakerVacuum | WS-14KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1230 | BreakerVacuum | WS-14KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1230 | BreakerVacuum | WS-14KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1230 | BreakerVacuum | WS-14KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1230 | BreakerVacuum | WS-14KV TR 1 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1230 | BreakerVacuum | WS-14KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1230 | BreakerVacuum | WS-14KV TR 1 | VCB Readings | Operations Counter AF | 4 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1230 | BreakerVacuum | WS-14KV TR 1 | VCB Readings | Operations Counter AL | 4 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1230 | BreakerVacuum | WS-14KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1218 | BreakerVacuum | WS-1334-4 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1218 | BreakerVacuum | WS-1334-4 | VCB Readings | Operations Counter AF | 113 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1218 | BreakerVacuum | WS-1334-4 | VCB Readings | Operations Counter AL | 113 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1218 | BreakerVacuum | WS-1334-4 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1218 | BreakerVacuum | WS-1334-4 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1218 | BreakerVacuum | WS-1334-4 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0629 | BreakerAirMagnetic | MG-411 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0629 | BreakerAirMagnetic | MG-411 | AMCB Readings | 9 Months Operations | 6 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0629 | BreakerAirMagnetic | MG-411 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0629 | BreakerAirMagnetic | MG-411 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0629 | BreakerAirMagnetic | MG-411 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0629 | BreakerAirMagnetic | MG-411 | AMCB Readings | Amps A Ø | 94.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0629 | BreakerAirMagnetic | MG-411 | AMCB Readings | Amps B Ø | 122.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0629 | BreakerAirMagnetic | MG-411 | AMCB Readings | Amps C Ø | 96.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0629 | BreakerAirMagnetic | MG-411 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0629 | BreakerAirMagnetic | MG-411 | AMCB Readings | Fault Adjusted Amps A Phase AM | 19.09 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0629 | BreakerAirMagnetic | MG-411 | AMCB Readings | Fault Adjusted Amps B Phase AM | 19.09 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0629 | BreakerAirMagnetic | MG-411 | AMCB Readings | Fault Adjusted Amps C Phase AM | 19.09 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0629 | BreakerAirMagnetic | MG-411 | AMCB Readings | Fault Operations A Ø | 2 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1200 | BreakerVacuum | WS-1427-3 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1200 | BreakerVacuum | WS-1427-3 | VCB Readings | Operations Counter AF | 133 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1200 | BreakerVacuum | WS-1427-3 | VCB Readings | Operations Counter AL | 133 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1200 | BreakerVacuum | WS-1427-3 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1200 | BreakerVacuum | WS-1427-3 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1200 | BreakerVacuum | WS-1427-3 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1204 | BreakerVacuum | WS-1473-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BAT000015 | Battery | MG-Battery Bank-Distribution | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BAT000015 | Battery | MG-Battery Bank-Distribution | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BAT000015 | Battery | MG-Battery Bank-Distribution | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BAT000015 | Battery | MG-Battery Bank-Distribution | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BAT000015 | Battery | MG-Battery Bank-Distribution | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BAT000015 | Battery | MG-Battery Bank-Distribution | Battery Patrol Inspection | Bat Volt 1Min After Chgr Trip | 129.8 | VDC |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BAT000015 | Battery | MG-Battery Bank-Distribution | Battery Patrol Inspection | All Connections OK? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1204 | BreakerVacuum | WS-1473-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1204 | BreakerVacuum | WS-1473-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1204 | BreakerVacuum | WS-1473-2 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1204 | BreakerVacuum | WS-1473-2 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1204 | BreakerVacuum | WS-1473-2 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1204 | BreakerVacuum | WS-1473-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1204 | BreakerVacuum | WS-1473-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1204 | BreakerVacuum | WS-1473-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1218 | BreakerVacuum | WS-1334-4 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1218 | BreakerVacuum | WS-1334-4 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1218 | BreakerVacuum | WS-1334-4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1218 | BreakerVacuum | WS-1334-4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1218 | BreakerVacuum | WS-1334-4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1218 | BreakerVacuum | WS-1334-4 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1204 | BreakerVacuum | WS-1473-2 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1204 | BreakerVacuum | WS-1473-2 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1204 | BreakerVacuum | WS-1473-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1204 | BreakerVacuum | WS-1473-2 | VCB Readings | Operations Counter AL | 176 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1204 | BreakerVacuum | WS-1473-2 | VCB Readings | Operations Counter AF | 176 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1204 | BreakerVacuum | WS-1473-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1204 | BreakerVacuum | WS-1473-2 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1204 | BreakerVacuum | WS-1473-2 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1204 | BreakerVacuum | WS-1473-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1204 | BreakerVacuum | WS-1473-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1204 | BreakerVacuum | WS-1473-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1204 | BreakerVacuum | WS-1473-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1204 | BreakerVacuum | WS-1473-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1204 | BreakerVacuum | WS-1473-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1200 | BreakerVacuum | WS-1427-3 | VCB Readings | 9 Month Operations | 4 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1204 | BreakerVacuum | WS-1473-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1200 | BreakerVacuum | WS-1427-3 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1200 | BreakerVacuum | WS-1427-3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1200 | BreakerVacuum | WS-1427-3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1200 | BreakerVacuum | WS-1427-3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1200 | BreakerVacuum | WS-1427-3 | VCB Readings | Amps A Ø | 68.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1200 | BreakerVacuum | WS-1427-3 | VCB Readings | Amps B Ø | 58.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1200 | BreakerVacuum | WS-1427-3 | VCB Readings | Amps C Ø | 59.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1200 | BreakerVacuum | WS-1427-3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1200 | BreakerVacuum | WS-1427-3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1200 | BreakerVacuum | WS-1427-3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1200 | BreakerVacuum | WS-1427-3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1200 | BreakerVacuum | WS-1427-3 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1200 | BreakerVacuum | WS-1427-3 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1200 | BreakerVacuum | WS-1427-3 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1200 | BreakerVacuum | WS-1427-3 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1200 | BreakerVacuum | WS-1427-3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1200 | BreakerVacuum | WS-1427-3 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1200 | BreakerVacuum | WS-1427-3 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BAT000015 | Battery | MG-Battery Bank-Distribution | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BAT000015 | Battery | MG-Battery Bank-Distribution | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1218 | BreakerVacuum | WS-1334-4 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1218 | BreakerVacuum | WS-1334-4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1218 | BreakerVacuum | WS-1334-4 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BAT000015 | Battery | MG-Battery Bank-Distribution | Battery Patrol Inspection | General Comments | water added to all cells | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BAT000015 | Battery | MG-Battery Bank-Distribution | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BAT000015 | Battery | MG-Battery Bank-Distribution | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BAT000015 | Battery | MG-Battery Bank-Distribution | Battery Patrol Inspection | Cell Electrolyte Level | Water Added | If low,note cell #~'s |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1200 | BreakerVacuum | WS-1427-3 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1218 | BreakerVacuum | WS-1334-4 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1218 | BreakerVacuum | WS-1334-4 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1248 | BreakerVacuum | WS-FUTURE-8 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1248 | BreakerVacuum | WS-FUTURE-8 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1248 | BreakerVacuum | WS-FUTURE-8 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1248 | BreakerVacuum | WS-FUTURE-8 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1248 | BreakerVacuum | WS-FUTURE-8 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1248 | BreakerVacuum | WS-FUTURE-8 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1248 | BreakerVacuum | WS-FUTURE-8 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1248 | BreakerVacuum | WS-FUTURE-8 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1248 | BreakerVacuum | WS-FUTURE-8 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1248 | BreakerVacuum | WS-FUTURE-8 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1248 | BreakerVacuum | WS-FUTURE-8 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1248 | BreakerVacuum | WS-FUTURE-8 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1248 | BreakerVacuum | WS-FUTURE-8 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1248 | BreakerVacuum | WS-FUTURE-8 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1248 | BreakerVacuum | WS-FUTURE-8 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1248 | BreakerVacuum | WS-FUTURE-8 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1248 | BreakerVacuum | WS-FUTURE-8 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1248 | BreakerVacuum | WS-FUTURE-8 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1248 | BreakerVacuum | WS-FUTURE-8 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1248 | BreakerVacuum | WS-FUTURE-8 | VCB Readings | 9 Month Operations | 4 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0634 | BreakerAirMagnetic | MG-464 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0629 | BreakerAirMagnetic | MG-411 | AMCB Readings | Fault Operations B Ø | 2 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0629 | BreakerAirMagnetic | MG-411 | AMCB Readings | Fault Operations C Ø | 2 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0629 | BreakerAirMagnetic | MG-411 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0629 | BreakerAirMagnetic | MG-411 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0629 | BreakerAirMagnetic | MG-411 | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0629 | BreakerAirMagnetic | MG-411 | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0634 | BreakerAirMagnetic | MG-464 | AMCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0634 | BreakerAirMagnetic | MG-464 | AMCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BCH000427 | Charger | 596-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .700 | millivolts |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BCH000427 | Charger | 596-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BCH000427 | Charger | 596-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BCH000427 | Charger | 596-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BCH000427 | Charger | 596-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BCH000427 | Charger | 596-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BCH000427 | Charger | 596-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/9/2023 10:13 | Distribution | Perdue Quarterly Inspection | BCH000427 | Charger | 596-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BAT000469 | Battery | 439-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BAT000469 | Battery | 439-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 52 | °F |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BAT000469 | Battery | 439-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BAT000469 | Battery | 439-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BAT000469 | Battery | 439-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BAT000469 | Battery | 439-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BAT000469 | Battery | 439-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BAT000469 | Battery | 439-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | BAT000469 | Battery | 439-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1218 | BreakerVacuum | WS-1334-4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1218 | BreakerVacuum | WS-1334-4 | VCB Readings | Amps C Ø | 83.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1218 | BreakerVacuum | WS-1334-4 | VCB Readings | Amps B Ø | 84.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1218 | BreakerVacuum | WS-1334-4 | VCB Readings | Amps A Ø | 83.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1218 | BreakerVacuum | WS-1334-4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1218 | BreakerVacuum | WS-1334-4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1218 | BreakerVacuum | WS-1334-4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1218 | BreakerVacuum | WS-1334-4 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1218 | BreakerVacuum | WS-1334-4 | VCB Readings | 9 Month Operations | 7 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1204 | BreakerVacuum | WS-1473-2 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1204 | BreakerVacuum | WS-1473-2 | VCB Readings | 9 Month Operations | 4 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1250 | BreakerVacuum | WS-SEC TIE 1-2 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1250 | BreakerVacuum | WS-SEC TIE 1-2 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1250 | BreakerVacuum | WS-SEC TIE 1-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1250 | BreakerVacuum | WS-SEC TIE 1-2 | VCB Readings | Operations Counter AL | 149 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1250 | BreakerVacuum | WS-SEC TIE 1-2 | VCB Readings | Operations Counter AF | 149 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1250 | BreakerVacuum | WS-SEC TIE 1-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1250 | BreakerVacuum | WS-SEC TIE 1-2 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1250 | BreakerVacuum | WS-SEC TIE 1-2 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1250 | BreakerVacuum | WS-SEC TIE 1-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1250 | BreakerVacuum | WS-SEC TIE 1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1250 | BreakerVacuum | WS-SEC TIE 1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1250 | BreakerVacuum | WS-SEC TIE 1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1250 | BreakerVacuum | WS-SEC TIE 1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1250 | BreakerVacuum | WS-SEC TIE 1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1250 | BreakerVacuum | WS-SEC TIE 1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1250 | BreakerVacuum | WS-SEC TIE 1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1250 | BreakerVacuum | WS-SEC TIE 1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0634 | BreakerAirMagnetic | MG-464 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0634 | BreakerAirMagnetic | MG-464 | AMCB Readings | 9 Months Operations | 1 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0634 | BreakerAirMagnetic | MG-464 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0634 | BreakerAirMagnetic | MG-464 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1250 | BreakerVacuum | WS-SEC TIE 1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1250 | BreakerVacuum | WS-SEC TIE 1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1250 | BreakerVacuum | WS-SEC TIE 1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1250 | BreakerVacuum | WS-SEC TIE 1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1250 | BreakerVacuum | WS-SEC TIE 1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1250 | BreakerVacuum | WS-SEC TIE 1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1250 | BreakerVacuum | WS-SEC TIE 1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1250 | BreakerVacuum | WS-SEC TIE 1-2 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1250 | BreakerVacuum | WS-SEC TIE 1-2 | VCB Readings | 9 Month Operations | 2 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1248 | BreakerVacuum | WS-FUTURE-8 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1248 | BreakerVacuum | WS-FUTURE-8 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1248 | BreakerVacuum | WS-FUTURE-8 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1248 | BreakerVacuum | WS-FUTURE-8 | VCB Readings | Operations Counter AL | 165 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1248 | BreakerVacuum | WS-FUTURE-8 | VCB Readings | Operations Counter AF | 165 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1248 | BreakerVacuum | WS-FUTURE-8 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 45 | °C |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 40 | °C |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 40 | °C |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 35 | °C |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 45 | °C |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 40 | °C |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | LTCMechanism | 467-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | LTCMechanism | 467-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | LTCMechanism | 467-1 | LTC Counter Readings | General Comments | | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | LTCMechanism | 467-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Readings | Amps A Ø | 170.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Readings | Amps B Ø | 170.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Readings | Amps C Ø | 170.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | LTCMechanism | 467-1 | LTC Counter Readings | LTC As Found Counter | 47085 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | LTCMechanism | 467-1 | LTC Counter Readings | LTC As Left Counter | 47098 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | LTCMechanism | 467-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | LTCMechanism | 467-1 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0598 | BreakerAirMagnetic | MG-1314 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0598 | BreakerAirMagnetic | MG-1314 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0598 | BreakerAirMagnetic | MG-1314 | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0598 | BreakerAirMagnetic | MG-1314 | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0598 | BreakerAirMagnetic | MG-1314 | AMCB Readings | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0598 | BreakerAirMagnetic | MG-1314 | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0598 | BreakerAirMagnetic | MG-1314 | AMCB Readings | Operations Counter AF | 51 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0598 | BreakerAirMagnetic | MG-1314 | AMCB Readings | Operations Counter AL | 51 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0598 | BreakerAirMagnetic | MG-1314 | AMCB Readings | Operations This Read AM | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0598 | BreakerAirMagnetic | MG-1314 | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0598 | BreakerAirMagnetic | MG-1314 | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0287 | GroundTransformer | WS-GND TR 2 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0287 | GroundTransformer | WS-GND TR 2 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0287 | GroundTransformer | WS-GND TR 2 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0287 | GroundTransformer | WS-GND TR 2 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0287 | GroundTransformer | WS-GND TR 2 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0287 | GroundTransformer | WS-GND TR 2 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0287 | GroundTransformer | WS-GND TR 2 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0287 | GroundTransformer | WS-GND TR 2 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0287 | GroundTransformer | WS-GND TR 2 | Ground Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0287 | GroundTransformer | WS-GND TR 2 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0287 | GroundTransformer | WS-GND TR 2 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0287 | GroundTransformer | WS-GND TR 2 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0287 | GroundTransformer | WS-GND TR 2 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0287 | GroundTransformer | WS-GND TR 2 | Ground Transformer Patrol Inspection | Cleaned Mechanism Cabinet? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0287 | GroundTransformer | WS-GND TR 2 | Ground Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | BCH000425 | Charger | 006-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | BCH000425 | Charger | 006-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | BCH000425 | Charger | 006-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | BCH000425 | Charger | 006-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | BCH000425 | Charger | 006-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | BCH000425 | Charger | 006-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 54.9 | VDC |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | BCH000425 | Charger | 006-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 54.9 | VDC |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | BCH000425 | Charger | 006-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .900 | millivolts |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | LT0118 | WithLTC | MK-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Readings | General Comments | 1TC, 1 unknown | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Readings | Maintenance Operations | 1 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1228 | BreakerVacuum | WS-1333-4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1228 | BreakerVacuum | WS-1333-4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1228 | BreakerVacuum | WS-1333-4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Readings | Follow-up Action Required? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1228 | BreakerVacuum | WS-1333-4 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1228 | BreakerVacuum | WS-1333-4 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1228 | BreakerVacuum | WS-1333-4 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1228 | BreakerVacuum | WS-1333-4 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1228 | BreakerVacuum | WS-1333-4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1228 | BreakerVacuum | WS-1333-4 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1228 | BreakerVacuum | WS-1333-4 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1228 | BreakerVacuum | WS-1333-4 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1228 | BreakerVacuum | WS-1333-4 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Readings | General Comments | a phase ioc, vc may not be working | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1228 | BreakerVacuum | WS-1333-4 | VCB Readings | Operations Counter AF | 308 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1228 | BreakerVacuum | WS-1333-4 | VCB Readings | Operations Counter AL | 308 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1228 | BreakerVacuum | WS-1333-4 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1228 | BreakerVacuum | WS-1333-4 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1228 | BreakerVacuum | WS-1333-4 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Readings | Operations Counter AF | 95 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Readings | Operations Counter AL | 95 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Readings | Operations This Read Vac | 1 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000395 | PowerFuse | WS-1428 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | PF000395 | PowerFuse | WS-1428 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000222 | PowerFuse | MG-14KV BUS SEC B POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000222 | PowerFuse | MG-14KV BUS SEC B POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000222 | PowerFuse | MG-14KV BUS SEC B POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000212 | PowerFuse | MG-417 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000212 | PowerFuse | MG-417 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000212 | PowerFuse | MG-417 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Readings | Fault Adjusted Amps A Phase V | 4.19 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Readings | Fault Adjusted Amps B Phase V | 4.19 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Readings | Fault Adjusted Amps C Phase V | 4.19 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | LTCMechanism | 467-1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | LTCMechanism | 467-1 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1214 | BreakerVacuum | WS-1324-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1214 | BreakerVacuum | WS-1324-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1214 | BreakerVacuum | WS-1324-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1214 | BreakerVacuum | WS-1324-2 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1214 | BreakerVacuum | WS-1324-2 | VCB Readings | 9 Month Operations | 6 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | LTCMechanism | 467-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | LTCMechanism | 467-1 | LTC Counter Readings | LTC Operations Since Last Insp | 311 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | LTCMechanism | 467-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | LTCMechanism | 467-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | LTCMechanism | 467-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Readings | Fault Adjusted Amps A Phase V | 1.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Readings | Fault Operations A Ø | 1 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | S0049 | LTCMechanism | 467-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1228 | BreakerVacuum | WS-1333-4 | VCB Readings | 9 Month Operations | 5 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1228 | BreakerVacuum | WS-1333-4 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1228 | BreakerVacuum | WS-1333-4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1228 | BreakerVacuum | WS-1333-4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1228 | BreakerVacuum | WS-1333-4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1228 | BreakerVacuum | WS-1333-4 | VCB Readings | Amps A Ø | 77.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1228 | BreakerVacuum | WS-1333-4 | VCB Readings | Amps B Ø | 76.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1228 | BreakerVacuum | WS-1333-4 | VCB Readings | Amps C Ø | 74.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1228 | BreakerVacuum | WS-1333-4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000740 | BreakerVacuum | MK-1292 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Readings | Fault Adjusted Amps A Phase V | 2.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Readings | Fault Adjusted Amps B Phase V | 2.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Readings | Fault Operations A Ø | 2 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Readings | Fault Operations B Ø | 2 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Readings | General Comments | A and B phase IOC | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | ST000146 | Structure | 771-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | ST000209 | Structure | 682-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | ST000209 | Structure | 682-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | ST000209 | Structure | 682-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | ST000209 | Structure | 682-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Readings | Operations Counter AF | 100 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Readings | Operations Counter AL | 100 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Readings | Operations This Read Vac | 4 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | ST000209 | Structure | 682-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | ST000209 | Structure | 682-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | ST000209 | Structure | 682-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | ST000209 | Structure | 682-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | ST000209 | Structure | 682-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/9/2023 10:16 | Distribution | Beaver Dam North Quarterly Inspection | K0119 | BreakerVacuum | 641-0918 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | ST000209 | Structure | 682-Structure | Structure Patrol Inspection | General Comments | ok | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | ST000209 | Structure | 682-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | ST000209 | Structure | 682-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | ST000209 | Structure | 682-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | ST000209 | Structure | 682-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | ST000209 | Structure | 682-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | ST000209 | Structure | 682-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | ST000209 | Structure | 682-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | ST000209 | Structure | 682-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BCH000134 | Charger | MG-Battery Charger-Distribution | Battery Charger Patrol Insp | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BCH000134 | Charger | MG-Battery Charger-Distribution | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0637 | BreakerAirMagnetic | MG-4KV TR 1 | AMCB Readings | Operations This Read AM | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0637 | BreakerAirMagnetic | MG-4KV TR 1 | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0637 | BreakerAirMagnetic | MG-4KV TR 1 | AMCB Readings | Unknown Operations | 0 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | FE000063 | Fence | 570-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | FE000063 | Fence | 570-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | FE000063 | Fence | 570-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | FE000063 | Fence | 570-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | FE000063 | Fence | 570-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | FE000063 | Fence | 570-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | FE000063 | Fence | 570-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | FE000063 | Fence | 570-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | FE000063 | Fence | 570-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | n | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | FE000063 | Fence | 570-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | ST000146 | Structure | 771-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | ST000146 | Structure | 771-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | ST000146 | Structure | 771-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | ST000146 | Structure | 771-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Readings | 9 Month Operations | 9 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | ST000146 | Structure | 771-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | ST000146 | Structure | 771-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | ST000146 | Structure | 771-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | ST000146 | Structure | 771-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | ST000146 | Structure | 771-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | ST000146 | Structure | 771-Structure | Structure Patrol Inspection | General Comments | C phase SandC insulator has broken skirt. broken skirt center phase of 303 | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | ST000146 | Structure | 771-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | ST000146 | Structure | 771-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | ST000146 | Structure | 771-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | ST000146 | Structure | 771-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | ST000146 | Structure | 771-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | ST000146 | Structure | 771-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | ST000146 | Structure | 771-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | ST000146 | Structure | 771-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | ST000146 | Structure | 771-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | ST000146 | Structure | 771-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/9/2023 9:01 | Distribution | Livermore Quarterly Inspection | ST000146 | Structure | 771-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Readings | Amps A Ø | 30.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Readings | Amps B Ø | 30.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Readings | Amps C Ø | 30.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000738 | BreakerVacuum | MK-1294 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1214 | BreakerVacuum | WS-1324-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1214 | BreakerVacuum | WS-1324-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1214 | BreakerVacuum | WS-1324-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1214 | BreakerVacuum | WS-1324-2 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1214 | BreakerVacuum | WS-1324-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1214 | BreakerVacuum | WS-1324-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1214 | BreakerVacuum | WS-1324-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1214 | BreakerVacuum | WS-1324-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1214 | BreakerVacuum | WS-1324-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1214 | BreakerVacuum | WS-1324-2 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1214 | BreakerVacuum | WS-1324-2 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1214 | BreakerVacuum | WS-1324-2 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Readings | General Comments | a,b,c, phase ioc | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Readings | Operations Counter AF | 89 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Readings | Operations Counter AL | 89 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Readings | Operations This Read Vac | 27 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0288 | GroundTransformer | WS-GND TR 3 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0288 | GroundTransformer | WS-GND TR 3 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0288 | GroundTransformer | WS-GND TR 3 | Ground Transformer Patrol Inspection | Cleaned Mechanism Cabinet? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0288 | GroundTransformer | WS-GND TR 3 | Ground Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0598 | BreakerAirMagnetic | MG-1314 | AMCB Readings | 9 Month Ops New | 4 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0598 | BreakerAirMagnetic | MG-1314 | AMCB Readings | 9 Months Operations | 4 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0598 | BreakerAirMagnetic | MG-1314 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0598 | BreakerAirMagnetic | MG-1314 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0598 | BreakerAirMagnetic | MG-1314 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0598 | BreakerAirMagnetic | MG-1314 | AMCB Readings | Amps A Ø | 31.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0598 | BreakerAirMagnetic | MG-1314 | AMCB Readings | Amps B Ø | 29.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0598 | BreakerAirMagnetic | MG-1314 | AMCB Readings | Amps C Ø | 31.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0598 | BreakerAirMagnetic | MG-1314 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0598 | BreakerAirMagnetic | MG-1314 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0598 | BreakerAirMagnetic | MG-1314 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0598 | BreakerAirMagnetic | MG-1314 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0598 | BreakerAirMagnetic | MG-1314 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0598 | BreakerAirMagnetic | MG-1314 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0598 | BreakerAirMagnetic | MG-1314 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BCH000134 | Charger | MG-Battery Charger-Distribution | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BCH000134 | Charger | MG-Battery Charger-Distribution | Battery Charger Patrol Insp | Battery Charger Current | 3.3 | amps |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BCH000134 | Charger | MG-Battery Charger-Distribution | Battery Charger Patrol Insp | As Left Float Voltage | 133.2 | VDC |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BCH000134 | Charger | MG-Battery Charger-Distribution | Battery Charger Patrol Insp | As Found Float Voltage | 133.2 | VDC |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | BCH000134 | Charger | MG-Battery Charger-Distribution | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | ST000209 | Structure | 682-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 9:09 | Distribution | Centertown South Quarterly Inspection | ST000209 | Structure | 682-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0288 | GroundTransformer | WS-GND TR 3 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0288 | GroundTransformer | WS-GND TR 3 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0288 | GroundTransformer | WS-GND TR 3 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0288 | GroundTransformer | WS-GND TR 3 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0288 | GroundTransformer | WS-GND TR 3 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0288 | GroundTransformer | WS-GND TR 3 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0288 | GroundTransformer | WS-GND TR 3 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0288 | GroundTransformer | WS-GND TR 3 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0288 | GroundTransformer | WS-GND TR 3 | Ground Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1214 | BreakerVacuum | WS-1324-2 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1214 | BreakerVacuum | WS-1324-2 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1214 | BreakerVacuum | WS-1324-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1214 | BreakerVacuum | WS-1324-2 | VCB Readings | Operations Counter AL | 189 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0288 | GroundTransformer | WS-GND TR 3 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LT0288 | GroundTransformer | WS-GND TR 3 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Readings | 9 Month Operations | 30 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Readings | Amps A Ø | 170.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Readings | Amps B Ø | 170.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Readings | Amps C Ø | 170.0 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Readings | Fault Adjusted Amps A Phase V | 9.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Readings | Fault Adjusted Amps B Phase V | 9.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Readings | Fault Adjusted Amps C Phase V | 9.00 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Readings | Fault Operations A Ø | 9 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Readings | Fault Operations B Ø | 9 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Readings | Fault Operations C Ø | 9 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | BK000739 | BreakerVacuum | MK-1293 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1214 | BreakerVacuum | WS-1324-2 | VCB Readings | Operations Counter AF | 189 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1214 | BreakerVacuum | WS-1324-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1214 | BreakerVacuum | WS-1324-2 | VCB Readings | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1214 | BreakerVacuum | WS-1324-2 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1214 | BreakerVacuum | WS-1324-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0522 | BreakerVacuum | JT-1123 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0522 | BreakerVacuum | JT-1123 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0522 | BreakerVacuum | JT-1123 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0522 | BreakerVacuum | JT-1123 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0522 | BreakerVacuum | JT-1123 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0522 | BreakerVacuum | JT-1123 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | LTCMechanism | 570-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | LTCMechanism | 570-1 | LTC Counter Readings | LTC As Left Counter | 210378 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | LTCMechanism | 570-1 | LTC Counter Readings | LTC As Found Counter | 210367 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | LTCMechanism | 570-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0522 | BreakerVacuum | JT-1123 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | LTCMechanism | 570-1 | LTC Counter Readings | General Comments | | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | LTCMechanism | 570-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1180 | BreakerVacuum | WS-1308-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | LTCMechanism | 570-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1180 | BreakerVacuum | WS-1308-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | BAT001669 | Battery | 006-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | BAT001669 | Battery | 006-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | BAT001669 | Battery | 006-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | BAT001669 | Battery | 006-Battery Bank | Battery Patrol Inspection | Negative DC Ground | .2 | VDC |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | BAT001669 | Battery | 006-Battery Bank | Battery Patrol Inspection | Positive DC Ground | .3 | VDC |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1180 | BreakerVacuum | WS-1308-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1180 | BreakerVacuum | WS-1308-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1180 | BreakerVacuum | WS-1308-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1180 | BreakerVacuum | WS-1308-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Readings | General Comments | unabe to reset winding temp needs new magnet | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | ST000581 | Structure | SV-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | ST000581 | Structure | SV-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000220 | PowerFuse | MG-1322 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000220 | PowerFuse | MG-1322 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000215 | PowerFuse | MG-451 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000215 | PowerFuse | MG-451 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000215 | PowerFuse | MG-451 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000214 | PowerFuse | MG-4KV TFR POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000214 | PowerFuse | MG-4KV TFR POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000214 | PowerFuse | MG-4KV TFR POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000220 | PowerFuse | MG-1322 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | ST000581 | Structure | SV-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | ST000581 | Structure | SV-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | ST000581 | Structure | SV-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | ST000581 | Structure | SV-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | ST000581 | Structure | SV-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | ST000581 | Structure | SV-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000221 | PowerFuse | MG-14KV BUS SEC A POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000221 | PowerFuse | MG-14KV BUS SEC A POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000221 | PowerFuse | MG-14KV BUS SEC A POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | ST000581 | Structure | SV-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0522 | BreakerVacuum | JT-1123 | VCB Readings | Amps C Ø | 169.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0522 | BreakerVacuum | JT-1123 | VCB Readings | Amps B Ø | 135.0 | |
| 3/10/2023 8:30 | Distribution | Middletown Quarterly Inspection | PF000235 | PowerFuse | MT-STA SER NO 4 LINE | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/10/2023 8:30 | Distribution | Middletown Quarterly Inspection | PF000235 | PowerFuse | MT-STA SER NO 4 LINE | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | BAT001666 | Battery | 467-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | BAT001666 | Battery | 467-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | BAT001666 | Battery | 467-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | BAT001666 | Battery | 467-Battery Bank | Battery Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | BAT001666 | Battery | 467-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 28.2 | VDC |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | BAT001666 | Battery | 467-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.0 | VDC |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000131 | Regulator | 571-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000131 | Regulator | 571-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000131 | Regulator | 571-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | BAT001666 | Battery | 467-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | BAT001666 | Battery | 467-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000131 | Regulator | 571-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000131 | Regulator | 571-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000131 | Regulator | 571-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 13512 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000131 | Regulator | 571-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000131 | Regulator | 571-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000131 | Regulator | 571-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000131 | Regulator | 571-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0522 | BreakerVacuum | JT-1123 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0522 | BreakerVacuum | JT-1123 | VCB Readings | Operations Counter AL | 494 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0522 | BreakerVacuum | JT-1123 | VCB Readings | Operations Counter AF | 494 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0522 | BreakerVacuum | JT-1123 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0522 | BreakerVacuum | JT-1123 | VCB Readings | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0522 | BreakerVacuum | JT-1123 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0522 | BreakerVacuum | JT-1123 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | BAT001669 | Battery | 006-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | BAT001669 | Battery | 006-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 54 | °F |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | BAT001669 | Battery | 006-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | BAT001669 | Battery | 006-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | BAT001669 | Battery | 006-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000070 | CapacitorBank | WS-Cap Bank 4 | Capacitor Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000070 | CapacitorBank | WS-Cap Bank 4 | Capacitor Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000070 | CapacitorBank | WS-Cap Bank 4 | Capacitor Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000070 | CapacitorBank | WS-Cap Bank 4 | Capacitor Patrol Inspection | Fuses Blown? Y / N | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000070 | CapacitorBank | WS-Cap Bank 4 | Capacitor Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000070 | CapacitorBank | WS-Cap Bank 4 | Capacitor Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000070 | CapacitorBank | WS-Cap Bank 4 | Capacitor Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000070 | CapacitorBank | WS-Cap Bank 4 | Capacitor Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000070 | CapacitorBank | WS-Cap Bank 4 | Capacitor Patrol Inspection | Capacitor Rack Condition OK? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000070 | CapacitorBank | WS-Cap Bank 4 | Capacitor Patrol Inspection | Capacitor Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000070 | CapacitorBank | WS-Cap Bank 4 | Capacitor Patrol Inspection | Cap bank PT in Good Condition? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000070 | CapacitorBank | WS-Cap Bank 4 | Capacitor Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000070 | CapacitorBank | WS-Cap Bank 4 | Capacitor Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000070 | CapacitorBank | WS-Cap Bank 4 | Capacitor Patrol Inspection | All Connections OK? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000069 | CapacitorBank | WS-Cap Bank 1 | Capacitor Patrol Inspection | Warning Signs OK? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000069 | CapacitorBank | WS-Cap Bank 1 | Capacitor Patrol Inspection | Tank Paint Condition | Adequate | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000069 | CapacitorBank | WS-Cap Bank 1 | Capacitor Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000069 | CapacitorBank | WS-Cap Bank 1 | Capacitor Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000069 | CapacitorBank | WS-Cap Bank 1 | Capacitor Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000069 | CapacitorBank | WS-Cap Bank 1 | Capacitor Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | LTCMechanism | 570-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | LTCMechanism | 570-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0522 | BreakerVacuum | JT-1123 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0522 | BreakerVacuum | JT-1123 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0627 | BreakerAirMagnetic | MG-14KV TR 5 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0627 | BreakerAirMagnetic | MG-14KV TR 5 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0627 | BreakerAirMagnetic | MG-14KV TR 5 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0627 | BreakerAirMagnetic | MG-14KV TR 5 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000129 | Switchgear | JT-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000129 | Switchgear | JT-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000129 | Switchgear | JT-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0627 | BreakerAirMagnetic | MG-14KV TR 5 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0627 | BreakerAirMagnetic | MG-14KV TR 5 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0627 | BreakerAirMagnetic | MG-14KV TR 5 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000129 | Switchgear | JT-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000129 | Switchgear | JT-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000129 | Switchgear | JT-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Readings | Operations Counter AL | 187 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Readings | Operations Counter AF | 187 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Readings | General Comments | | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000129 | Switchgear | JT-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000225 | PowerFuse | MG-STA SER NO 4 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000225 | PowerFuse | MG-STA SER NO 4 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000225 | PowerFuse | MG-STA SER NO 4 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 200.00 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0627 | BreakerAirMagnetic | MG-14KV TR 5 | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0627 | BreakerAirMagnetic | MG-14KV TR 5 | AMCB Patrol Inspection | General Comments | | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0627 | BreakerAirMagnetic | MG-14KV TR 5 | AMCB Readings | General Comments | | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 55 | °C |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Readings | Amps C Ø | 84.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0522 | BreakerVacuum | JT-1123 | VCB Readings | Amps A Ø | 170.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0522 | BreakerVacuum | JT-1123 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0522 | BreakerVacuum | JT-1123 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0522 | BreakerVacuum | JT-1123 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0522 | BreakerVacuum | JT-1123 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | ST000581 | Structure | SV-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | ST000581 | Structure | SV-Structure | Structure Patrol Inspection | General Comments | | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | ST000581 | Structure | SV-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | ST000581 | Structure | SV-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | ST000581 | Structure | SV-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000224 | PowerFuse | MG-STA SER NO 3 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000224 | PowerFuse | MG-STA SER NO 3 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000224 | PowerFuse | MG-STA SER NO 3 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | ST000581 | Structure | SV-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | ST000581 | Structure | SV-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1180 | BreakerVacuum | WS-1308-1 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1180 | BreakerVacuum | WS-1308-1 | VCB Readings | General Comments | | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | ST000581 | Structure | SV-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | ST000581 | Structure | SV-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1349 | CircuitSwitcher | WS-Vista Switchgear | Circuit Switcher Inspection | Ambient Temp | 60 | °F |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1349 | CircuitSwitcher | WS-Vista Switchgear | Circuit Switcher Inspection | Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1349 | CircuitSwitcher | WS-Vista Switchgear | Circuit Switcher Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1349 | CircuitSwitcher | WS-Vista Switchgear | Circuit Switcher Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1349 | CircuitSwitcher | WS-Vista Switchgear | Circuit Switcher Inspection | SF6 Indicator Zone | OK | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | BAT001669 | Battery | 006-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | BAT001669 | Battery | 006-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | CH000415 | ControlHouse | 494-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | CH000415 | ControlHouse | 494-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000069 | CapacitorBank | WS-Cap Bank 1 | Capacitor Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000069 | CapacitorBank | WS-Cap Bank 1 | Capacitor Patrol Inspection | Fuses Blown? Y / N | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0627 | BreakerAirMagnetic | MG-14KV TR 5 | AMCB Readings | 9 Month Ops New | 9 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0627 | BreakerAirMagnetic | MG-14KV TR 5 | AMCB Readings | 9 Months Operations | 9 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0627 | BreakerAirMagnetic | MG-14KV TR 5 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0627 | BreakerAirMagnetic | MG-14KV TR 5 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000213 | PowerFuse | MG-4KV REA TIE POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000213 | PowerFuse | MG-4KV REA TIE POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0627 | BreakerAirMagnetic | MG-14KV TR 5 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0627 | BreakerAirMagnetic | MG-14KV TR 5 | AMCB Readings | Amps A Ø | 821.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0627 | BreakerAirMagnetic | MG-14KV TR 5 | AMCB Readings | Amps B Ø | 791.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0627 | BreakerAirMagnetic | MG-14KV TR 5 | AMCB Readings | Amps C Ø | 788.0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000213 | PowerFuse | MG-4KV REA TIE POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000210 | PowerFuse | MG-411 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000210 | PowerFuse | MG-411 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000210 | PowerFuse | MG-411 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000209 | PowerFuse | MG-464 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000209 | PowerFuse | MG-464 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000209 | PowerFuse | MG-464 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000208 | PowerFuse | MG-454 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000208 | PowerFuse | MG-454 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000208 | PowerFuse | MG-454 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000129 | Switchgear | JT-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0627 | BreakerAirMagnetic | MG-14KV TR 5 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0627 | BreakerAirMagnetic | MG-14KV TR 5 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1180 | BreakerVacuum | WS-1308-1 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1180 | BreakerVacuum | WS-1308-1 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1180 | BreakerVacuum | WS-1308-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1180 | BreakerVacuum | WS-1308-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 30 | °C |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 30 | °C |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 25 | °C |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 40 | °C |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | ST000577 | Structure | MK-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | BCH001449 | Charger | 815-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | BCH001449 | Charger | 815-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | ST000577 | Structure | MK-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | ST000577 | Structure | MK-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | ST000577 | Structure | MK-Structure | Structure Patrol Inspection | General Comments | | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | FE000575 | Fence | SV-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | ST000577 | Structure | MK-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | ST000577 | Structure | MK-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | ST000577 | Structure | MK-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | ST000577 | Structure | MK-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | ST000577 | Structure | MK-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | ST000577 | Structure | MK-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | ST000577 | Structure | MK-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | ST000577 | Structure | MK-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | ST000577 | Structure | MK-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000219 | PowerFuse | MG-1330 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000219 | PowerFuse | MG-1330 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000219 | PowerFuse | MG-1330 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000218 | PowerFuse | MG-452 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1180 | BreakerVacuum | WS-1308-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | FE000575 | Fence | SV-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | FE000575 | Fence | SV-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | FE000575 | Fence | SV-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | FE000575 | Fence | SV-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | FE000575 | Fence | SV-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1180 | BreakerVacuum | WS-1308-1 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1180 | BreakerVacuum | WS-1308-1 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1180 | BreakerVacuum | WS-1308-1 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | FE000575 | Fence | SV-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | FE000575 | Fence | SV-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | BCH001449 | Charger | 815-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .2 | amps |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | FE000575 | Fence | SV-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000067 | CapacitorBank | WS-Cap Bank 3 | Capacitor Patrol Inspection | Capacitor Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000067 | CapacitorBank | WS-Cap Bank 3 | Capacitor Patrol Inspection | Capacitor Rack Condition OK? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000067 | CapacitorBank | WS-Cap Bank 3 | Capacitor Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000067 | CapacitorBank | WS-Cap Bank 3 | Capacitor Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000067 | CapacitorBank | WS-Cap Bank 3 | Capacitor Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000067 | CapacitorBank | WS-Cap Bank 3 | Capacitor Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 40 | °C |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 40 | °C |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000067 | CapacitorBank | WS-Cap Bank 3 | Capacitor Patrol Inspection | Fuses Blown? Y / N | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000067 | CapacitorBank | WS-Cap Bank 3 | Capacitor Patrol Inspection | General Comments | | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000067 | CapacitorBank | WS-Cap Bank 3 | Capacitor Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000067 | CapacitorBank | WS-Cap Bank 3 | Capacitor Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000067 | CapacitorBank | WS-Cap Bank 3 | Capacitor Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000067 | CapacitorBank | WS-Cap Bank 3 | Capacitor Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000067 | CapacitorBank | WS-Cap Bank 3 | Capacitor Patrol Inspection | Tank Paint Condition | Adequate | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000067 | CapacitorBank | WS-Cap Bank 3 | Capacitor Patrol Inspection | Warning Signs OK? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000130 | Regulator | 571-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000130 | Regulator | 571-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000130 | Regulator | 571-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000130 | Regulator | 571-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000130 | Regulator | 571-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000130 | Regulator | 571-1 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000130 | Regulator | 571-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000130 | Regulator | 571-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000130 | Regulator | 571-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000130 | Regulator | 571-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000067 | CapacitorBank | WS-Cap Bank 3 | Capacitor Patrol Inspection | Cap bank PT in Good Condition? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000067 | CapacitorBank | WS-Cap Bank 3 | Capacitor Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000067 | CapacitorBank | WS-Cap Bank 3 | Capacitor Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000067 | CapacitorBank | WS-Cap Bank 3 | Capacitor Patrol Inspection | All Connections OK? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | ST000577 | Structure | MK-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | ST000577 | Structure | MK-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | ST000577 | Structure | MK-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | ST000577 | Structure | MK-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000130 | Regulator | 571-1 C | Regulator Patrol Inspection | General Comments | | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000130 | Regulator | 571-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000130 | Regulator | 571-1 C | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000130 | Regulator | 571-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000130 | Regulator | 571-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000130 | Regulator | 571-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000130 | Regulator | 571-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | BCH001449 | Charger | 815-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | BCH001449 | Charger | 815-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | BAT001666 | Battery | 467-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | BAT001666 | Battery | 467-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Readings | Percent Thermal Load C Ø Max | 0 | % |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Readings | Percent Thermal Load B Ø Max | 50 | % |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | needs nitrogen | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000130 | Regulator | 571-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000130 | Regulator | 571-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.6 | volts |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000130 | Regulator | 571-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 14227 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000130 | Regulator | 571-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000130 | Regulator | 571-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000130 | Regulator | 571-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000130 | Regulator | 571-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000131 | Regulator | 571-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000131 | Regulator | 571-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000131 | Regulator | 571-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000131 | Regulator | 571-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000131 | Regulator | 571-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000131 | Regulator | 571-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000131 | Regulator | 571-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000131 | Regulator | 571-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000131 | Regulator | 571-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000131 | Regulator | 571-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000131 | Regulator | 571-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000131 | Regulator | 571-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000131 | Regulator | 571-1 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000131 | Regulator | 571-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1180 | BreakerVacuum | WS-1308-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | BCH001449 | Charger | 815-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | BCH001449 | Charger | 815-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | BCH001449 | Charger | 815-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | BAT001522 | Battery | 815-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0522 | BreakerVacuum | JT-1123 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB0522 | BreakerVacuum | JT-1123 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1180 | BreakerVacuum | WS-1308-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1180 | BreakerVacuum | WS-1308-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1180 | BreakerVacuum | WS-1308-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | BAT001522 | Battery | 815-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | BAT001522 | Battery | 815-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.5 | VDC |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | BAT001522 | Battery | 815-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.5 | VDC |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | BAT001522 | Battery | 815-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | BAT001522 | Battery | 815-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | BAT001522 | Battery | 815-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | FE000575 | Fence | SV-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | FE000575 | Fence | SV-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | FE000575 | Fence | SV-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | FE000575 | Fence | SV-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | FE000575 | Fence | SV-Fence | Fence Patrol Inspection | General Comments | | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | FE000575 | Fence | SV-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | FE000575 | Fence | SV-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | BAT001522 | Battery | 815-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | BAT001522 | Battery | 815-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | BAT001522 | Battery | 815-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | BAT001522 | Battery | 815-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 62 | °F |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | y | |
| 3/9/2023 14:03 | Distribution | Riverview Quarterly Inspection | BAT001522 | Battery | 815-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0168 | WithLTC | SV-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | needs nitr0gen | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1193 | BreakerVacuum | WS-1334-3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000218 | PowerFuse | MG-452 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000218 | PowerFuse | MG-452 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000217 | PowerFuse | MG-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000217 | PowerFuse | MG-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000217 | PowerFuse | MG-4KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1193 | BreakerVacuum | WS-1334-3 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1193 | BreakerVacuum | WS-1334-3 | VCB Readings | 9 Month Operations | 2 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | LTCMechanism | 570-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | LTCMechanism | 570-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | LTCMechanism | 570-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | LTCMechanism | 570-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | LTCMechanism | 570-1 | LTC Counter Readings | LTC Operations Since Last Insp | 1273 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | M0078 | LTCMechanism | 570-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000070 | CapacitorBank | WS-Cap Bank 4 | Capacitor Patrol Inspection | Warning Signs OK? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000070 | CapacitorBank | WS-Cap Bank 4 | Capacitor Patrol Inspection | Tank Paint Condition | Adequate | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000070 | CapacitorBank | WS-Cap Bank 4 | Capacitor Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000070 | CapacitorBank | WS-Cap Bank 4 | Capacitor Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | BAT001666 | Battery | 467-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/9/2023 13:21 | Distribution | Beaver Dam Quarterly Inspection | BAT001666 | Battery | 467-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1193 | BreakerVacuum | WS-1334-3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1193 | BreakerVacuum | WS-1334-3 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1193 | BreakerVacuum | WS-1334-3 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1193 | BreakerVacuum | WS-1334-3 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1193 | BreakerVacuum | WS-1334-3 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1193 | BreakerVacuum | WS-1334-3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1193 | BreakerVacuum | WS-1334-3 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Readings | Amps C Ø | 56.0 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Readings | Amps B Ø | 75.0 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Readings | Amps A Ø | 80.0 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Readings | 9 Month Operations | 2 | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | YD000577 | Yard | MK-Yard | Yard Patrol Inspection | Ambient Temp | 42 | °F |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | YD000577 | Yard | MK-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | YD000577 | Yard | MK-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | YD000577 | Yard | MK-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | YD000577 | Yard | MK-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | YD000577 | Yard | MK-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | YD000577 | Yard | MK-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | YD000577 | Yard | MK-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | YD000577 | Yard | MK-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | YD000577 | Yard | MK-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | YD000577 | Yard | MK-Yard | Yard Patrol Inspection | General Comments | | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | YD000577 | Yard | MK-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | YD000577 | Yard | MK-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | YD000577 | Yard | MK-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | YD000577 | Yard | MK-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | YD000577 | Yard | MK-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | YD000577 | Yard | MK-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | YD000577 | Yard | MK-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | YD000581 | Yard | SV-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | YD000581 | Yard | SV-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | YD000581 | Yard | SV-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1334 | BreakerVacuum | JT-1127 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | FE000215 | Fence | 439-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | FE000215 | Fence | 439-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | FE000215 | Fence | 439-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | FE000215 | Fence | 439-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | FE000215 | Fence | 439-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | FE000215 | Fence | 439-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | FE000215 | Fence | 439-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Readings | Operations Counter AL | 312 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1 | psi |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 750.0 | psi |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Readings | H2 Winding Temp Present | 25 | °C |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Readings | H2 Winding Temp Max | 40 | °C |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Readings | Operations Counter AF | 312 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Readings | General Comments | | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | There is a boot that fell off the low side bus on the outside phase. | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1193 | BreakerVacuum | WS-1334-3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1193 | BreakerVacuum | WS-1334-3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1193 | BreakerVacuum | WS-1334-3 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1193 | BreakerVacuum | WS-1334-3 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1193 | BreakerVacuum | WS-1334-3 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1193 | BreakerVacuum | WS-1334-3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1193 | BreakerVacuum | WS-1334-3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1193 | BreakerVacuum | WS-1334-3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000226 | PowerFuse | MG-STA SER NO 5 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | YD000581 | Yard | SV-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Readings | Maintenance Operations | 1 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Readings | Operations Counter AF | 226 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Readings | Operations Counter AL | 227 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Readings | Operations This Read Vac | 2 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000132 | Regulator | 571-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000132 | Regulator | 571-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000132 | Regulator | 571-1 A | Regulator Patrol Inspection | General Comments | | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000132 | Regulator | 571-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | YD000581 | Yard | SV-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000132 | Regulator | 571-1 A | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | YD000581 | Yard | SV-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | YD000581 | Yard | SV-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | YD000581 | Yard | SV-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | YD000581 | Yard | SV-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | YD000581 | Yard | SV-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 3/9/2023 9:25 | Distribution | Manslick Quarterly Inspection | YD000577 | Yard | MK-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000132 | Regulator | 571-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000132 | Regulator | 571-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000132 | Regulator | 571-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1334 | BreakerVacuum | JT-1127 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1334 | BreakerVacuum | JT-1127 | VCB Readings | Fault Operations A Ø | 1 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1334 | BreakerVacuum | JT-1127 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1334 | BreakerVacuum | JT-1127 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1334 | BreakerVacuum | JT-1127 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1334 | BreakerVacuum | JT-1127 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1334 | BreakerVacuum | JT-1127 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1334 | BreakerVacuum | JT-1127 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1334 | BreakerVacuum | JT-1127 | VCB Readings | General Comments | A Phase IOC | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1334 | BreakerVacuum | JT-1127 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1334 | BreakerVacuum | JT-1127 | VCB Readings | Operations Counter AF | 171 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1334 | BreakerVacuum | JT-1127 | VCB Readings | Operations Counter AL | 171 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1334 | BreakerVacuum | JT-1127 | VCB Readings | Operations This Read Vac | 1 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1334 | BreakerVacuum | JT-1127 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Readings | Oil Temp Present | 50 | °C |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1209 | BreakerVacuum | WS-1305-2 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1209 | BreakerVacuum | WS-1305-2 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1209 | BreakerVacuum | WS-1305-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1209 | BreakerVacuum | WS-1305-2 | VCB Readings | Operations Counter AL | 198 | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | FE000215 | Fence | 439-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | FE000215 | Fence | 439-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | FE000215 | Fence | 439-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | FE000215 | Fence | 439-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | FE000215 | Fence | 439-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | FE000215 | Fence | 439-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | FE000215 | Fence | 439-Fence | Fence Patrol Inspection | General Comments | | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | FE000215 | Fence | 439-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/9/2023 12:43 | Distribution | Shavers Chapel Quarterly Inspection | FE000215 | Fence | 439-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1334 | BreakerVacuum | JT-1127 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1334 | BreakerVacuum | JT-1127 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1334 | BreakerVacuum | JT-1127 | VCB Readings | Amps A Ø | 41.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1334 | BreakerVacuum | JT-1127 | VCB Readings | Amps B Ø | 77.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1334 | BreakerVacuum | JT-1127 | VCB Readings | Amps C Ø | 44.0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1334 | BreakerVacuum | JT-1127 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1334 | BreakerVacuum | JT-1127 | VCB Readings | Fault Adjusted Amps A Phase V | 11.18 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1334 | BreakerVacuum | JT-1127 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Readings | Fault Operations B Ø | 1 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1209 | BreakerVacuum | WS-1305-2 | VCB Readings | Operations Counter AF | 198 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | YD000581 | Yard | SV-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | YD000581 | Yard | SV-Yard | Yard Patrol Inspection | General Comments | | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Readings | General Comments | | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | YD000581 | Yard | SV-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | YD000581 | Yard | SV-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000226 | PowerFuse | MG-STA SER NO 5 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | PF000226 | PowerFuse | MG-STA SER NO 5 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0627 | BreakerAirMagnetic | MG-14KV TR 5 | AMCB Readings | Switching Operations | 0 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 2.1228 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 3/9/2023 13:28 | Distribution | Graham Quarterly Inspection | W0213 | NonLTC | 006-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | LTCC000731 | LTCControl | 570-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | LTCC000731 | LTCControl | 570-1 | LTC Control Insp | LTC Output Voltage Level | 124.6 | VAC |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | LTCC000731 | LTCControl | 570-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | LTCC000731 | LTCControl | 570-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | LTCC000731 | LTCControl | 570-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 3/9/2023 9:52 | Distribution | Worthington Quarterly Inspection | LT0225 | WithLTC | WO-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | CH000415 | ControlHouse | 494-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | CH000415 | ControlHouse | 494-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | CH000415 | ControlHouse | 494-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | CH000415 | ControlHouse | 494-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | CH000415 | ControlHouse | 494-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000069 | CapacitorBank | WS-Cap Bank 1 | Capacitor Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000069 | CapacitorBank | WS-Cap Bank 1 | Capacitor Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000069 | CapacitorBank | WS-Cap Bank 1 | Capacitor Patrol Inspection | All Connections OK? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0627 | BreakerAirMagnetic | MG-14KV TR 5 | AMCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0627 | BreakerAirMagnetic | MG-14KV TR 5 | AMCB Readings | Operations Counter AF | 151 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | K0108 | BreakerVacuum | 494-0576 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | CH000415 | ControlHouse | 494-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Readings | Amps C Ø | 25.0 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | CH000415 | ControlHouse | 494-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0627 | BreakerAirMagnetic | MG-14KV TR 5 | AMCB Readings | Operations Counter AL | 151 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | CH000415 | ControlHouse | 494-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | CH000415 | ControlHouse | 494-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Readings | Amps A Ø | 92.0 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000132 | Regulator | 571-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1180 | BreakerVacuum | WS-1308-1 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000132 | Regulator | 571-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Readings | Amps B Ø | 20.0 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Readings | Amps A Ø | 10.0 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000132 | Regulator | 571-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000132 | Regulator | 571-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 12:49 | Distribution | Magazine Quarterly Inspection | LB0627 | BreakerAirMagnetic | MG-14KV TR 5 | AMCB Readings | Operations This Read AM | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1180 | BreakerVacuum | WS-1308-1 | VCB Readings | Operations Counter AF | 233 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Readings | 9 Month Operations | 9 | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000132 | Regulator | 571-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000132 | Regulator | 571-1 A | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000132 | Regulator | 571-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 9:56 | Distribution | Central City Quarterly Inspection | RG000132 | Regulator | 571-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1180 | BreakerVacuum | WS-1308-1 | VCB Readings | Operations Counter AL | 233 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1180 | BreakerVacuum | WS-1308-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1180 | BreakerVacuum | WS-1308-1 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000129 | Switchgear | JT-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | LB1180 | BreakerVacuum | WS-1308-1 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | CH000415 | ControlHouse | 494-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Readings | 9 Month Operations | 3 | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | CH000415 | ControlHouse | 494-Control House | Control House Patrol Inspection | General Comments | | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | LT0169 | WithLTC | SV-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 40 | °C |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000129 | Switchgear | JT-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000129 | Switchgear | JT-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000129 | Switchgear | JT-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000069 | CapacitorBank | WS-Cap Bank 1 | Capacitor Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000069 | CapacitorBank | WS-Cap Bank 1 | Capacitor Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | BK000753 | BreakerVacuum | 570-0544 | VCB Readings | Amps B Ø | 96.0 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Readings | Fault Adjusted Amps B Phase V | 4.94 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1334 | BreakerVacuum | JT-1127 | VCB Readings | 9 Month Operations | 1 | |
| 3/9/2023 11:17 | Distribution | Island Quarterly Inspection | K0135 | BreakerVacuum | 481-1638 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000129 | Switchgear | JT-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | LTCC000731 | LTCControl | 570-1 | LTC Control Insp | General Comments | | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | CH000415 | ControlHouse | 494-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | CH000415 | ControlHouse | 494-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | CH000415 | ControlHouse | 494-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/9/2023 13:30 | Distribution | Whitley City Quarterly Inspection | CH000415 | ControlHouse | 494-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | LTCC000731 | LTCControl | 570-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/9/2023 11:27 | Distribution | Burnside Quarterly Inspection | LTCC000731 | LTCControl | 570-1 | LTC Control Insp | All Connections OK? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000129 | Switchgear | JT-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000069 | CapacitorBank | WS-Cap Bank 1 | Capacitor Patrol Inspection | Cap bank PT in Good Condition? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000129 | Switchgear | JT-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000129 | Switchgear | JT-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000129 | Switchgear | JT-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000069 | CapacitorBank | WS-Cap Bank 1 | Capacitor Patrol Inspection | Capacitor Condition | Good | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000069 | CapacitorBank | WS-Cap Bank 1 | Capacitor Patrol Inspection | Capacitor Rack Condition OK? | y | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | YD000581 | Yard | SV-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | YD000581 | Yard | SV-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/9/2023 14:24 | Distribution | Shepherdsville Quarterly Inspection | YD000581 | Yard | SV-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000129 | Switchgear | JT-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | SWG000129 | Switchgear | JT-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000069 | CapacitorBank | WS-Cap Bank 1 | Capacitor Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 10:56 | Distribution | Waterside West Quarterly Inspection | CAP000069 | CapacitorBank | WS-Cap Bank 1 | Capacitor Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | LB1334 | BreakerVacuum | JT-1127 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | LTCMechanism | CS-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0571 | BreakerAirMagnetic | LN-3 | AMCB Readings | Amps A Ø | 370.0 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | LTCMechanism | CS-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | LTCMechanism | CS-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | LTCMechanism | CS-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0571 | BreakerAirMagnetic | LN-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0571 | BreakerAirMagnetic | LN-3 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0571 | BreakerAirMagnetic | LN-3 | AMCB Readings | 9 Months Operations | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0571 | BreakerAirMagnetic | LN-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0571 | BreakerAirMagnetic | LN-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | LTCMechanism | CS-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 33 | °C |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | LTCMechanism | CS-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 639 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | LTCMechanism | LN-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | LTCMechanism | LN-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Readings | Amps C Ø | 211.0 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Readings | Amps B Ø | 250.0 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Readings | Amps A Ø | 205.0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | LTCMechanism | LN-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | LTCMechanism | LN-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | LTCMechanism | LN-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 340 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | LTCMechanism | LN-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Readings | 9 Month Operations | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Readings | Winding Temp Present | 28 | °C |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Readings | Winding Temp Max | 39 | °C |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Readings | Totalizer Meter Reading | .6660 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | LTCMechanism | CS-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | LTCMechanism | CS-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | LTCMechanism | CS-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | LTCMechanism | CS-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0575 | BreakerAirMagnetic | LN-SEC 1 SPARE | AMCB Readings | Unknown Operations | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BCH000035 | Charger | CS-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0575 | BreakerAirMagnetic | LN-SEC 1 SPARE | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0575 | BreakerAirMagnetic | LN-SEC 1 SPARE | AMCB Readings | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0575 | BreakerAirMagnetic | LN-SEC 1 SPARE | AMCB Patrol Inspection | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0575 | BreakerAirMagnetic | LN-SEC 1 SPARE | AMCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BCH000035 | Charger | CS-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.7 | VDC |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0575 | BreakerAirMagnetic | LN-SEC 1 SPARE | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0575 | BreakerAirMagnetic | LN-SEC 1 SPARE | AMCB Readings | Fault Operations Ground | 0 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BAT001387 | Battery | 500-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BAT001387 | Battery | 500-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BAT001387 | Battery | 500-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.1 | VDC |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BAT001387 | Battery | 500-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.2 | VDC |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | FE000831 | Fence | 536-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | FE000831 | Fence | 536-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Readings | Unknown Operations | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Readings | Switching Operations | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | YD000587 | Yard | LN-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | YD000587 | Yard | LN-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Readings | Operations This Read Vac | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0575 | BreakerAirMagnetic | LN-SEC 1 SPARE | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0575 | BreakerAirMagnetic | LN-SEC 1 SPARE | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0575 | BreakerAirMagnetic | LN-SEC 1 SPARE | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0575 | BreakerAirMagnetic | LN-SEC 1 SPARE | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0575 | BreakerAirMagnetic | LN-SEC 1 SPARE | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0575 | BreakerAirMagnetic | LN-SEC 1 SPARE | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0575 | BreakerAirMagnetic | LN-SEC 1 SPARE | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | YD000587 | Yard | LN-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | YD000587 | Yard | LN-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | YD000587 | Yard | LN-Yard | Yard Patrol Inspection | Ambient Temp | 40 | °F |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0575 | BreakerAirMagnetic | LN-SEC 1 SPARE | AMCB Readings | Amps C Ø | 0.0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0575 | BreakerAirMagnetic | LN-SEC 1 SPARE | AMCB Readings | Amps B Ø | 0.0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0575 | BreakerAirMagnetic | LN-SEC 1 SPARE | AMCB Readings | Amps A Ø | 0.0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0575 | BreakerAirMagnetic | LN-SEC 1 SPARE | AMCB Readings | 9 Months Operations | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0575 | BreakerAirMagnetic | LN-SEC 1 SPARE | AMCB Readings | 9 Month Ops New | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | FE000582 | Fence | LN-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | FE000582 | Fence | LN-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | FE000582 | Fence | LN-Fence | Fence Patrol Inspection | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | FE000582 | Fence | LN-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | FE000582 | Fence | LN-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | FE000582 | Fence | LN-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Readings | Operations Counter AL | 107 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Readings | Operations Counter AF | 107 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Readings | Maintenance Operations | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | FE000582 | Fence | LN-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | FE000582 | Fence | LN-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | FE000582 | Fence | LN-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Readings | General Comments | | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Patrol Inspection | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | FE000582 | Fence | LN-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | FE000582 | Fence | LN-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1299 | BreakerVacuum | CS-1263 | VCB Readings | Unknown Operations | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0571 | BreakerAirMagnetic | LN-3 | AMCB Readings | Amps B Ø | 150.0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0571 | BreakerAirMagnetic | LN-3 | AMCB Readings | Amps C Ø | 120.0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0571 | BreakerAirMagnetic | LN-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0571 | BreakerAirMagnetic | LN-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0571 | BreakerAirMagnetic | LN-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0571 | BreakerAirMagnetic | LN-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0571 | BreakerAirMagnetic | LN-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0571 | BreakerAirMagnetic | LN-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0571 | BreakerAirMagnetic | LN-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0571 | BreakerAirMagnetic | LN-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0571 | BreakerAirMagnetic | LN-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0571 | BreakerAirMagnetic | LN-3 | AMCB Readings | Follow-up Action Required? | n | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0571 | BreakerAirMagnetic | LN-3 | AMCB Patrol Inspection | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0571 | BreakerAirMagnetic | LN-3 | AMCB Readings | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0571 | BreakerAirMagnetic | LN-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0571 | BreakerAirMagnetic | LN-3 | AMCB Readings | Maintenance Operations | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0571 | BreakerAirMagnetic | LN-3 | AMCB Readings | Operations Counter AF | 502 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0571 | BreakerAirMagnetic | LN-3 | AMCB Readings | Operations Counter AL | 502 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0571 | BreakerAirMagnetic | LN-3 | AMCB Readings | Operations This Read AM | 0 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Readings | Follow-up Action Required? | n | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Patrol Inspection | General Comments | | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Readings | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | YD000587 | Yard | LN-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0575 | BreakerAirMagnetic | LN-SEC 1 SPARE | AMCB Readings | Switching Operations | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0575 | BreakerAirMagnetic | LN-SEC 1 SPARE | AMCB Readings | Operations This Read AM | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0575 | BreakerAirMagnetic | LN-SEC 1 SPARE | AMCB Readings | Operations Counter AL | 276 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0571 | BreakerAirMagnetic | LN-3 | AMCB Readings | Switching Operations | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | YD000587 | Yard | LN-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | YD000587 | Yard | LN-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | YD000587 | Yard | LN-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | YD000587 | Yard | LN-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | YD000587 | Yard | LN-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | YD000587 | Yard | LN-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | YD000587 | Yard | LN-Yard | Yard Patrol Inspection | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | YD000587 | Yard | LN-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0571 | BreakerAirMagnetic | LN-3 | AMCB Readings | Unknown Operations | 0 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0575 | BreakerAirMagnetic | LN-SEC 1 SPARE | AMCB Readings | Operations Counter AF | 276 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0575 | BreakerAirMagnetic | LN-SEC 1 SPARE | AMCB Readings | Maintenance Operations | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | LTCC000702 | LTCControl | 536-1 | LTC Control Insp | LTC Output Voltage Level | 124.5 | VAC |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Readings | Totalizer Meter Reading | .4830 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | LTCC000702 | LTCControl | 536-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | LTCC000702 | LTCControl | 536-1 | LTC Control Insp | General Comments | | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | LTCC000702 | LTCControl | 536-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | LTCC000702 | LTCControl | 536-1 | LTC Control Insp | All Connections OK? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Readings | Oil Temp Present | 37 | °C |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | LTCMechanism | 478-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | LTCMechanism | 478-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | LTCMechanism | 478-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | LTCMechanism | 478-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | LTCMechanism | 478-1 | LTC Counter Readings | LTC Operations Since Last Insp | 1511 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | LTCMechanism | 478-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | LTCMechanism | 478-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Readings | LTC Totalizer Reading | 4636.80 | kw |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Readings | General Comments | | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Readings | Fault Adjusted Amps A Phase V | 4.94 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Readings | Amps C Ø | 104.0 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Readings | Amps B Ø | 106.0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LTCC000533 | LTCControl | CR-TRANS 2-B | LTC Control Insp | All Connections OK? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LTCC000533 | LTCControl | CR-TRANS 2-B | LTC Control Insp | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LTCC000533 | LTCControl | CR-TRANS 2-B | LTC Control Insp | General Comments | ok | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Readings | Amps A Ø | 97.0 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Readings | 9 Month Operations | 3 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | LTCC000702 | LTCControl | 536-1 | LTC Control Insp | VRR Time Delay | 45 | Seconds |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | LTCC000702 | LTCControl | 536-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | LTCC000702 | LTCControl | 536-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Readings | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Patrol Inspection | General Comments | | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Readings | Maintenance Operations | 0 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Readings | Operations Counter AF | 222 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Readings | Operations Counter AL | 222 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Readings | Operations This Read Vac | 2 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Readings | Switching Operations | 1 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Readings | LTC Totalizer Reading | 9590.40 | kw |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Readings | Percent Thermal Load B Ø Max | 0 | % |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Readings | Oil Temp Present | 18 | °C |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | General Comments | Nitro cyl at 0 psi . transformer at 0 psi. | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Readings | General Comments | | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Readings | General Comments | | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Readings | Unknown Operations | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | LTCMechanism | LN-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | LTCMechanism | LN-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | LTCMechanism | LN-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 5L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | LTCMechanism | LN-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | LTCMechanism | CS-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | LTCMechanism | CS-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | LTCMechanism | CS-TRANS 1 | LTC Counter Readings | General Comments | | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | LTCMechanism | CS-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | LTCMechanism | CS-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 49820 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | LTCMechanism | CS-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 49820 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | WithLTC | CR-TRANS 1-A | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | WithLTC | 721-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | LTCMechanism | 478-1 | LTC Counter Readings | LTC Max Tap Position | 10R | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | LTCMechanism | 478-1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | LTCMechanism | 478-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | LTCMechanism | 478-1 | LTC Counter Readings | LTC As Left Counter | 46379 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | LTCMechanism | 478-1 | LTC Counter Readings | LTC As Found Counter | 46366 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | LTCMechanism | 478-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | LTCMechanism | 478-1 | LTC Counter Readings | General Comments | | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | LTCMechanism | 478-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | LTCMechanism | 478-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Readings | Fault Operations A Ø | 1 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | WithLTC | 500-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | LTCMechanism | LN-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | LTCMechanism | LN-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | LTCMechanism | LN-TRANS 2 | LTC Counter Readings | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | LTCMechanism | LN-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | LTCMechanism | LN-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 262887 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | LTCMechanism | LN-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 262887 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Readings | Fault Operations Ground | 0 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Readings | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Patrol Inspection | General Comments | | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Readings | General Comments | | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001253 | BreakerVacuum | 500-0540 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000127 | Switchgear | LN-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000127 | Switchgear | LN-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000127 | Switchgear | LN-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000127 | Switchgear | LN-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000127 | Switchgear | LN-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000127 | Switchgear | LN-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000127 | Switchgear | LN-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000127 | Switchgear | LN-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000127 | Switchgear | LN-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000127 | Switchgear | LN-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000127 | Switchgear | LN-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000127 | Switchgear | LN-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000127 | Switchgear | LN-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000127 | Switchgear | LN-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BAT001497 | Battery | 478-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BAT001497 | Battery | 478-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BAT001497 | Battery | 478-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 34 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 17 | °C |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 41 | °C |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 23 | °C |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 42 | °C |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 24 | °C |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BAT001497 | Battery | 478-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.0 | VDC |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BAT001497 | Battery | 478-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BAT001497 | Battery | 478-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BAT001497 | Battery | 478-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BAT001497 | Battery | 478-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BAT001497 | Battery | 478-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BAT001497 | Battery | 478-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BAT001497 | Battery | 478-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BAT001497 | Battery | 478-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BAT001497 | Battery | 478-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | LTCC000877 | LTCControl | 721-1 | LTC Control Insp | All Connections OK? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | LTCC000877 | LTCControl | 721-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | LTCC000877 | LTCControl | 721-1 | LTC Control Insp | General Comments | | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | LTCC000877 | LTCControl | 721-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | LTCC000877 | LTCControl | 721-1 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | LTCC000877 | LTCControl | 721-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | LTCC000877 | LTCControl | 721-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | LTCC000877 | LTCControl | 721-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | LTCC000877 | LTCControl | 721-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BAT001497 | Battery | 478-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BAT000143 | Battery | CS-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Readings | Follow-up Action Required? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Patrol Inspection | General Comments | | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Readings | General Comments | | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Readings | Maintenance Operations | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Readings | Operations Counter AF | 194 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Readings | Operations Counter AL | 194 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Readings | Operations This Read Vac | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Readings | Switching Operations | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000127 | Switchgear | LN-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000127 | Switchgear | LN-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.2 | psi |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1000 | psi |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 41 | °C |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 23 | °C |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LT0300 | WithLTC | CS-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1298 | BreakerVacuum | CS-1262 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1298 | BreakerVacuum | CS-1262 | VCB Readings | General Comments | | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1298 | BreakerVacuum | CS-1262 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1298 | BreakerVacuum | CS-1262 | VCB Readings | Operations Counter AF | 230 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1298 | BreakerVacuum | CS-1262 | VCB Readings | Operations Counter AL | 230 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1298 | BreakerVacuum | CS-1262 | VCB Readings | Operations This Read Vac | 1 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1298 | BreakerVacuum | CS-1262 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1298 | BreakerVacuum | CS-1262 | VCB Readings | Unknown Operations | 1 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | LTCMechanism | 536-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | LTCMechanism | 536-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | LTCMechanism | 536-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | LTCMechanism | 536-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | LTCMechanism | 536-1 | LTC Counter Readings | LTC Operations Since Last Insp | 1064 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | LTCMechanism | 536-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | LTCMechanism | 536-1 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | LTCMechanism | 536-1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | LTCMechanism | 536-1 | LTC Counter Readings | LTC Current Tap Position | 12L | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | LTCMechanism | 536-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | LTCMechanism | 536-1 | LTC Counter Readings | LTC As Left Counter | 356802 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | LTCMechanism | 536-1 | LTC Counter Readings | LTC As Found Counter | 356791 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | LTCMechanism | 536-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | LTCMechanism | 536-1 | LTC Counter Readings | General Comments | | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | LTCMechanism | 536-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | LTCMechanism | 536-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | FE000666 | Fence | CS-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | FE000666 | Fence | CS-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | FE000666 | Fence | CS-Fence | Fence Patrol Inspection | General Comments | | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1294 | BreakerVacuum | CS-12KV TR 1 | VCB Readings | 9 Month Operations | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1294 | BreakerVacuum | CS-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1294 | BreakerVacuum | CS-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1294 | BreakerVacuum | CS-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1294 | BreakerVacuum | CS-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1294 | BreakerVacuum | CS-12KV TR 1 | VCB Readings | Amps A Ø | 299.0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1294 | BreakerVacuum | CS-12KV TR 1 | VCB Readings | Amps B Ø | 244.0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1294 | BreakerVacuum | CS-12KV TR 1 | VCB Readings | Amps C Ø | 214.0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1294 | BreakerVacuum | CS-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1294 | BreakerVacuum | CS-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1294 | BreakerVacuum | CS-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1294 | BreakerVacuum | CS-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1294 | BreakerVacuum | CS-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1294 | BreakerVacuum | CS-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1294 | BreakerVacuum | CS-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1294 | BreakerVacuum | CS-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1294 | BreakerVacuum | CS-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1294 | BreakerVacuum | CS-12KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BAT000143 | Battery | CS-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BAT000143 | Battery | CS-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BAT000143 | Battery | CS-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BAT000143 | Battery | CS-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1298 | BreakerVacuum | CS-1262 | VCB Readings | 9 Month Operations | 4 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1298 | BreakerVacuum | CS-1262 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1298 | BreakerVacuum | CS-1262 | VCB Readings | Accumulated Fault Duty A Ph V | 23.92 | % |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1298 | BreakerVacuum | CS-1262 | VCB Readings | Accumulated Fault Duty B Ph V | 35.87 | % |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1298 | BreakerVacuum | CS-1262 | VCB Readings | Accumulated Fault Duty C Ph V | 21.52 | % |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1298 | BreakerVacuum | CS-1262 | VCB Readings | Amps A Ø | 108.0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1298 | BreakerVacuum | CS-1262 | VCB Readings | Amps B Ø | 100.0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1298 | BreakerVacuum | CS-1262 | VCB Readings | Amps C Ø | 77.0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1298 | BreakerVacuum | CS-1262 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BAT000143 | Battery | CS-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BAT000143 | Battery | CS-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | ST000648 | Structure | CS-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | ST000648 | Structure | CS-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | ST000648 | Structure | CS-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | ST000648 | Structure | CS-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | ST000648 | Structure | CS-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | ST000648 | Structure | CS-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | ST000648 | Structure | CS-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | ST000648 | Structure | CS-Structure | Structure Patrol Inspection | General Comments | | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | ST000648 | Structure | CS-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | ST000648 | Structure | CS-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | ST000648 | Structure | CS-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | ST000648 | Structure | CS-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | ST000648 | Structure | CS-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | ST000648 | Structure | CS-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | ST000648 | Structure | CS-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | ST000648 | Structure | CS-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | ST000648 | Structure | CS-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BAT000143 | Battery | CS-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BAT000143 | Battery | CS-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BAT000143 | Battery | CS-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1298 | BreakerVacuum | CS-1262 | VCB Readings | Fault Adjusted Amps A Phase V | 11.18 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1298 | BreakerVacuum | CS-1262 | VCB Readings | Fault Adjusted Amps B Phase V | 11.18 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1298 | BreakerVacuum | CS-1262 | VCB Readings | Fault Adjusted Amps C Phase V | 11.18 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1298 | BreakerVacuum | CS-1262 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1298 | BreakerVacuum | CS-1262 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BAT000143 | Battery | CS-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BAT000143 | Battery | CS-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1298 | BreakerVacuum | CS-1262 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1298 | BreakerVacuum | CS-1262 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1298 | BreakerVacuum | CS-1262 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1298 | BreakerVacuum | CS-1262 | VCB Readings | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Readings | Amps A Ø | 251.0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Readings | Accumulated Fault Duty C Ph V | 10.72 | % |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Readings | Accumulated Fault Duty B Ph V | 16.84 | % |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Readings | Accumulated Fault Duty A Ph V | 16.84 | % |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | BCH001478 | Charger | 536-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | BCH001478 | Charger | 536-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Readings | Unknown Operations | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Readings | Switching Operations | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Readings | Operations This Read Vac | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Readings | Operations Counter AL | 203 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Readings | Operations Counter AF | 203 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Readings | Maintenance Operations | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Readings | General Comments | | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Patrol Inspection | General Comments | | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Readings | Follow-up Action Required? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Readings | Fault Operations Ground | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Readings | Amps C Ø | 97.0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Readings | Amps B Ø | 99.0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Readings | Amps A Ø | 95.0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001443 | BreakerVacuum | 478-0230 | VCB Readings | 9 Month Operations | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Readings | Maintenance Operations | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Readings | Fault Operations A Ø | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Readings | Fault Operations B Ø | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Readings | Fault Operations C Ø | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Readings | Fault Operations Ground | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Readings | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Patrol Inspection | General Comments | | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Readings | General Comments | | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | BCH001478 | Charger | 536-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.823 | millivolts |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | BCH001478 | Charger | 536-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | BCH001478 | Charger | 536-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | BCH001478 | Charger | 536-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.1 | amps |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | SWG000124 | Switchgear | CS-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | SWG000124 | Switchgear | CS-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | SWG000124 | Switchgear | CS-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | SWG000124 | Switchgear | CS-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | SWG000124 | Switchgear | CS-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | SWG000124 | Switchgear | CS-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | SWG000124 | Switchgear | CS-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | SWG000124 | Switchgear | CS-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | SWG000124 | Switchgear | CS-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | SWG000124 | Switchgear | CS-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | SWG000124 | Switchgear | CS-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | SWG000124 | Switchgear | CS-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | SWG000124 | Switchgear | CS-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | SWG000124 | Switchgear | CS-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | SWG000124 | Switchgear | CS-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | SWG000124 | Switchgear | CS-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | SWG000124 | Switchgear | CS-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | SWG000124 | Switchgear | CS-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | SWG000124 | Switchgear | CS-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | BCH001478 | Charger | 536-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | BCH001478 | Charger | 536-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Readings | Amps C Ø | 249.0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Readings | Amps B Ø | 257.0 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | BAT000162 | Battery | 536-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | BAT000162 | Battery | 536-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.0 | VDC |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | BAT000162 | Battery | 536-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | BAT000162 | Battery | 536-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | BAT000162 | Battery | 536-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Readings | Amps C Ø | 82.0 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Readings | Amps B Ø | 100.0 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Readings | Amps A Ø | 118.0 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Readings | 9 Month Operations | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Readings | 9 Month Operations | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Readings | Amps A Ø | 70.0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Readings | Amps B Ø | 76.0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Readings | Amps C Ø | 81.0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Readings | Fault Operations Ground | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK001444 | BreakerVacuum | 478-0231 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Readings | Operations Counter AF | 127 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Readings | Operations Counter AL | 127 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Readings | Operations This Read Vac | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Readings | Switching Operations | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Readings | Unknown Operations | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1277 | BreakerVacuum | CR-1421-A | VCB Readings | 9 Month Operations | 0 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Readings | Unknown Operations | 0 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Readings | Switching Operations | 0 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Readings | Operations This Read Vac | 0 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Readings | Operations Counter AL | 467 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | BAT000162 | Battery | 536-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | BAT000162 | Battery | 536-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | BAT000162 | Battery | 536-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | BAT000162 | Battery | 536-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | BAT000162 | Battery | 536-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | BAT000162 | Battery | 536-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | BAT000162 | Battery | 536-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | BAT000162 | Battery | 536-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | LTCC000951 | LTCControl | 478-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Readings | Operations Counter AF | 467 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Readings | Maintenance Operations | 0 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Readings | General Comments | | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Patrol Inspection | General Comments | | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Readings | Follow-up Action Required? | n | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Readings | Fault Operations Ground | 0 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0004 | BreakerVacuum | 536-0236 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | LTCC000951 | LTCControl | 478-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | LTCC000951 | LTCControl | 478-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | LTCC000951 | LTCControl | 478-1 | LTC Control Insp | LTC Output Voltage Level | 124.3 | VAC |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | LTCC000951 | LTCControl | 478-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | LTCC000951 | LTCControl | 478-1 | LTC Control Insp | General Comments | | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | LTCC000951 | LTCControl | 478-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | LTCC000951 | LTCControl | 478-1 | LTC Control Insp | All Connections OK? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | BAT000162 | Battery | 536-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Readings | MegaWatt Demand Meter Min | 1.00 | MegaWatts |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Readings | MegaWatt Demand Meter Max | 2.00 | MegaWatts |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Readings | MegaVar Demand Meter Min | -.20 | MegaVars |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Readings | MegaVar Demand Meter Max | -.20 | MegaVars |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BCH000035 | Charger | CS-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BCH000035 | Charger | CS-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BCH000035 | Charger | CS-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BCH000035 | Charger | CS-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | LTCMechanism | LN-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | LTCMechanism | LN-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | LTCMechanism | LN-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | LTCMechanism | LN-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | LTCMechanism | LN-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 82 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BCH000035 | Charger | CS-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.3 | amps |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BCH000035 | Charger | CS-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.7 | VDC |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | ST000086 | Structure | 856-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | ST000086 | Structure | 856-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | ST000086 | Structure | 856-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | ST000086 | Structure | 856-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | ST000086 | Structure | 856-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | ST000086 | Structure | 856-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | CH000208 | ControlHouse | CS-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | CH000208 | ControlHouse | CS-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | ST000086 | Structure | 856-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | ST000086 | Structure | 856-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | ST000086 | Structure | 856-Structure | Structure Patrol Inspection | General Comments | | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | ST000086 | Structure | 856-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | ST000086 | Structure | 856-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | ST000086 | Structure | 856-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | LTCMechanism | LN-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | LTCMechanism | LN-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | LTCMechanism | LN-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 7L | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | LTCMechanism | LN-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | LTCMechanism | LN-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | LTCMechanism | LN-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 8934 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | CH000208 | ControlHouse | CS-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | CH000208 | ControlHouse | CS-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | CH000208 | ControlHouse | CS-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Readings | 9 Month Operations | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | FE000666 | Fence | CS-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | FE000666 | Fence | CS-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | FE000666 | Fence | CS-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | FE000666 | Fence | CS-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | FE000666 | Fence | CS-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | FE000666 | Fence | CS-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | FE000666 | Fence | CS-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | PF000075 | PowerFuse | CS-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | PF000075 | PowerFuse | CS-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | PF000076 | PowerFuse | CS-12KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | PF000076 | PowerFuse | CS-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | YD000673 | Yard | CS-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | YD000673 | Yard | CS-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | YD000673 | Yard | CS-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | YD000673 | Yard | CS-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | YD000673 | Yard | CS-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | YD000673 | Yard | CS-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | YD000673 | Yard | CS-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | YD000673 | Yard | CS-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | YD000673 | Yard | CS-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | YD000673 | Yard | CS-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | YD000673 | Yard | CS-Yard | Yard Patrol Inspection | General Comments | | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | YD000673 | Yard | CS-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | YD000673 | Yard | CS-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | YD000673 | Yard | CS-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | YD000673 | Yard | CS-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | YD000673 | Yard | CS-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | YD000673 | Yard | CS-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | YD000673 | Yard | CS-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | PF000076 | PowerFuse | CS-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 245.00 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PF001324 | PowerFuse | LN-4KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PF001324 | PowerFuse | LN-4KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PF001324 | PowerFuse | LN-4KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PF001323 | PowerFuse | LN-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PF001323 | PowerFuse | LN-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PF001323 | PowerFuse | LN-4KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN61 | WithLTC | LN-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 15 | °C |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1299 | BreakerVacuum | CS-1263 | VCB Readings | Accumulated Fault Duty C Ph V | 5.58 | % |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1299 | BreakerVacuum | CS-1263 | VCB Readings | Amps A Ø | 0.0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1299 | BreakerVacuum | CS-1263 | VCB Readings | Amps B Ø | 0.0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1299 | BreakerVacuum | CS-1263 | VCB Readings | Amps C Ø | 0.0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1299 | BreakerVacuum | CS-1263 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1299 | BreakerVacuum | CS-1263 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1299 | BreakerVacuum | CS-1263 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1299 | BreakerVacuum | CS-1263 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1299 | BreakerVacuum | CS-1263 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1299 | BreakerVacuum | CS-1263 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1299 | BreakerVacuum | CS-1263 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1299 | BreakerVacuum | CS-1263 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1299 | BreakerVacuum | CS-1263 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1299 | BreakerVacuum | CS-1263 | VCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1299 | BreakerVacuum | CS-1263 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1299 | BreakerVacuum | CS-1263 | VCB Readings | General Comments | | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1299 | BreakerVacuum | CS-1263 | VCB Readings | Maintenance Operations | 0 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Readings | Fault Operations Ground | 0 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Readings | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1299 | BreakerVacuum | CS-1263 | VCB Readings | Operations Counter AF | 144 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1299 | BreakerVacuum | CS-1263 | VCB Readings | Operations Counter AL | 144 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Readings | General Comments | | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Readings | Maintenance Operations | 0 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Readings | Operations Counter AF | 230 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Readings | Operations Counter AL | 230 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Readings | Operations This Read Vac | 2 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Readings | Switching Operations | 2 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | CH000208 | ControlHouse | CS-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | FE000582 | Fence | LN-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | FE000582 | Fence | LN-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | FE000582 | Fence | LN-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | FE000582 | Fence | LN-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | FE000582 | Fence | LN-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1299 | BreakerVacuum | CS-1263 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1299 | BreakerVacuum | CS-1263 | VCB Readings | Switching Operations | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | LTCMechanism | LN-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 8934 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | LTCMechanism | LN-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | LTCMechanism | LN-TRANS 1 | LTC Counter Readings | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | LTCMechanism | LN-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | CH000208 | ControlHouse | CS-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | CH000208 | ControlHouse | CS-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | CH000208 | ControlHouse | CS-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | CH000208 | ControlHouse | CS-Control House | Control House Patrol Inspection | General Comments | | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | CH000208 | ControlHouse | CS-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | CH000208 | ControlHouse | CS-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | CH000208 | ControlHouse | CS-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | CH000208 | ControlHouse | CS-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | CH000208 | ControlHouse | CS-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | CH000208 | ControlHouse | CS-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | CH000208 | ControlHouse | CS-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | CH000208 | ControlHouse | CS-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | CH000208 | ControlHouse | CS-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | CH000208 | ControlHouse | CS-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | LTCMechanism | LN-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | ST000086 | Structure | 856-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | ST000086 | Structure | 856-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | ST000086 | Structure | 856-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | CH000208 | ControlHouse | CS-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | CH000208 | ControlHouse | CS-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Readings | 9 Month Operations | 5 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Readings | Amps A Ø | 83.0 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Readings | Amps B Ø | 77.0 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Readings | Amps C Ø | 56.0 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BK001252 | BreakerVacuum | 500-0539 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1299 | BreakerVacuum | CS-1263 | VCB Readings | 9 Month Operations | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1299 | BreakerVacuum | CS-1263 | VCB Readings | 9 Month Operations VCB New | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1299 | BreakerVacuum | CS-1263 | VCB Readings | Accumulated Fault Duty A Ph V | 5.58 | % |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1299 | BreakerVacuum | CS-1263 | VCB Readings | Accumulated Fault Duty B Ph V | 5.58 | % |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BCH001284 | Charger | 721-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BCH001284 | Charger | 721-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Patrol Inspection | Ambient Temperature | 35 | °F |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1294 | BreakerVacuum | CS-12KV TR 1 | VCB Readings | General Comments | | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1294 | BreakerVacuum | CS-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1294 | BreakerVacuum | CS-12KV TR 1 | VCB Readings | Operations Counter AF | 172 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1294 | BreakerVacuum | CS-12KV TR 1 | VCB Readings | Operations Counter AL | 172 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1294 | BreakerVacuum | CS-12KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1294 | BreakerVacuum | CS-12KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BCH001284 | Charger | 721-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BCH001284 | Charger | 721-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BAT001299 | Battery | 721-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Readings | Follow-up Action Required? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Readings | Fault Operations Ground | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BAT001299 | Battery | 721-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BAT001299 | Battery | 721-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BAT001299 | Battery | 721-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BAT001299 | Battery | 721-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1294 | BreakerVacuum | CS-12KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | FE000666 | Fence | CS-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | FE000666 | Fence | CS-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | FE000666 | Fence | CS-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | FE000666 | Fence | CS-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | FE000666 | Fence | CS-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | FE000666 | Fence | CS-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BAT001299 | Battery | 721-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BAT001299 | Battery | 721-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.2 | VDC |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BAT001299 | Battery | 721-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.2 | VDC |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BAT001299 | Battery | 721-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1294 | BreakerVacuum | CS-12KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Readings | Switching Operations | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Patrol Inspection | SF6 Pressure Indicator | good | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Patrol Inspection | SF6 Pressure | 68 | psi |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Readings | Operations This Read SF6 | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Readings | Operations Counter AL | 59 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Readings | Operations Counter AF | 59 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Patrol Inspection | Grounds in Place? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Patrol Inspection | General Comments | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Readings | General Comments | | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Patrol Inspection | Foundation Condition | Good | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Readings | Fault Operations | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BAT001299 | Battery | 721-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BAT001299 | Battery | 721-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Readings | Unknown Operations | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Readings | Switching Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Readings | Operations This Read Vac | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Readings | Operations Counter AL | 535 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Readings | Operations Counter AF | 535 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Readings | Maintenance Operations | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Readings | General Comments | | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | BK000223 | BreakerSF6 | CS-6676 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BCH001284 | Charger | 721-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 2.000 | millivolts |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BCH001284 | Charger | 721-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BAT001299 | Battery | 721-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BAT001299 | Battery | 721-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BCH001284 | Charger | 721-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BCH001284 | Charger | 721-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.1 | amps |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Readings | Amps C Ø | 20.0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Readings | Amps B Ø | 11.0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Readings | Amps A Ø | 9.0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0570 | BreakerAirMagnetic | LN-2 | AMCB Readings | Unknown Operations | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0570 | BreakerAirMagnetic | LN-2 | AMCB Readings | Switching Operations | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0570 | BreakerAirMagnetic | LN-2 | AMCB Readings | Operations This Read AM | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0570 | BreakerAirMagnetic | LN-2 | AMCB Readings | Operations Counter AL | 378 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0570 | BreakerAirMagnetic | LN-2 | AMCB Readings | Operations Counter AF | 378 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0570 | BreakerAirMagnetic | LN-2 | AMCB Readings | Maintenance Operations | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0570 | BreakerAirMagnetic | LN-2 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0570 | BreakerAirMagnetic | LN-2 | AMCB Readings | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0570 | BreakerAirMagnetic | LN-2 | AMCB Patrol Inspection | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0570 | BreakerAirMagnetic | LN-2 | AMCB Readings | Follow-up Action Required? | n | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0570 | BreakerAirMagnetic | LN-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0570 | BreakerAirMagnetic | LN-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0570 | BreakerAirMagnetic | LN-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0570 | BreakerAirMagnetic | LN-2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0570 | BreakerAirMagnetic | LN-2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0570 | BreakerAirMagnetic | LN-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0570 | BreakerAirMagnetic | LN-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0570 | BreakerAirMagnetic | LN-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0570 | BreakerAirMagnetic | LN-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0570 | BreakerAirMagnetic | LN-2 | AMCB Readings | Amps C Ø | 225.0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0570 | BreakerAirMagnetic | LN-2 | AMCB Readings | Amps B Ø | 210.0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0570 | BreakerAirMagnetic | LN-2 | AMCB Readings | Amps A Ø | 140.0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0570 | BreakerAirMagnetic | LN-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0570 | BreakerAirMagnetic | LN-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0570 | BreakerAirMagnetic | LN-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0570 | BreakerAirMagnetic | LN-2 | AMCB Readings | 9 Months Operations | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0570 | BreakerAirMagnetic | LN-2 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BAT001299 | Battery | 721-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | PF000075 | PowerFuse | CS-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Readings | Amps C Ø | 85.0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Readings | Amps B Ø | 107.0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Readings | Amps A Ø | 119.0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | MB0171 | BreakerVacuum | 478-0226 | VCB Readings | 9 Month Operations | 2 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Readings | Switching Operations | 0 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | CH000410 | ControlHouse | 500-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | CH000410 | ControlHouse | 500-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | CH000410 | ControlHouse | 500-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | CH000410 | ControlHouse | 500-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | CH000410 | ControlHouse | 500-Control House | Control House Patrol Inspection | General Comments | | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | CH000410 | ControlHouse | 500-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | CH000410 | ControlHouse | 500-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | CH000410 | ControlHouse | 500-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | CH000410 | ControlHouse | 500-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | CH000410 | ControlHouse | 500-Control House | Control House Patrol Inspection | Filters Condition OK? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | CH000410 | ControlHouse | 500-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | CH000410 | ControlHouse | 500-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | CH000410 | ControlHouse | 500-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | CH000410 | ControlHouse | 500-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | CH000410 | ControlHouse | 500-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | CH000410 | ControlHouse | 500-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | CH000410 | ControlHouse | 500-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Readings | Operations This Read Vac | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Readings | Operations Counter AL | 218 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Readings | Operations Counter AF | 218 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Readings | Maintenance Operations | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Readings | General Comments | | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Patrol Inspection | General Comments | | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Readings | Follow-up Action Required? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Readings | Fault Operations Ground | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | K0030 | BreakerVacuum | 478-0227 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | ST000060 | Structure | 721-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | ST000060 | Structure | 721-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | ST000060 | Structure | 721-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Readings | Maintenance Operations | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Readings | Operations Counter AF | 180 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Readings | Operations Counter AL | 180 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Readings | Operations This Read Vac | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Readings | Switching Operations | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Readings | Unknown Operations | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Readings | Totalizer Meter Reading | .5610 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | ST000060 | Structure | 721-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | ST000060 | Structure | 721-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | ST000060 | Structure | 721-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | ST000060 | Structure | 721-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | ST000060 | Structure | 721-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | ST000060 | Structure | 721-Structure | Structure Patrol Inspection | General Comments | | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | ST000060 | Structure | 721-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | ST000060 | Structure | 721-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | ST000060 | Structure | 721-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | ST000060 | Structure | 721-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | ST000060 | Structure | 721-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | ST000060 | Structure | 721-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | ST000060 | Structure | 721-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | CH000441 | ControlHouse | LN-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | CH000441 | ControlHouse | LN-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | CH000441 | ControlHouse | LN-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | CH000441 | ControlHouse | LN-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | CH000441 | ControlHouse | LN-Battery Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | CH000441 | ControlHouse | LN-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | CH000441 | ControlHouse | LN-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | CH000441 | ControlHouse | LN-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | CH000441 | ControlHouse | LN-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | LTCMechanism | CR-TRANS 1-A | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | FE000595 | Fence | JT-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | PF001260 | PowerFuse | CR-GEN STA SER NO 1-A | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | PF001260 | PowerFuse | CR-GEN STA SER NO 1-A | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | PF001260 | PowerFuse | CR-GEN STA SER NO 1-A | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | PF001259 | PowerFuse | CR-GEN EMERG STA SER | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | LTCMechanism | CR-TRANS 1-A | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | LTCMechanism | CR-TRANS 1-A | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | PF001259 | PowerFuse | CR-GEN EMERG STA SER | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | PF001259 | PowerFuse | CR-GEN EMERG STA SER | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Readings | 9 Month Operations | 2 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Readings | Amps A Ø | 119.0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Readings | Amps B Ø | 83.0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Readings | Amps C Ø | 101.0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Readings | Fault Operations Ground | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Readings | Follow-up Action Required? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Patrol Inspection | General Comments | | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001267 | BreakerVacuum | 721-0210 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | ST000060 | Structure | 721-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | ST000060 | Structure | 721-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | ST000060 | Structure | 721-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | ST000060 | Structure | 721-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Readings | LTC Totalizer Reading | 5385.60 | kw |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Patrol Inspection | Grounds in Place? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Readings | General Comments | | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | FE000169 | Fence | 500-Fence | Fence Patrol Inspection | General Comments | top fence rails are rusty, fence fabric seperated from post on the left hand side of the station | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | FE000169 | Fence | 500-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | FE000169 | Fence | 500-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | YD000167 | Yard | 500-Yard | Yard Patrol Inspection | Ambient Temp | 40 | °F |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Readings | Unknown Operations | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Readings | Switching Operations | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | FE000053 | Fence | 721-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | FE000053 | Fence | 721-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | FE000053 | Fence | 721-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | FE000053 | Fence | 721-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | FE000053 | Fence | 721-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | FE000053 | Fence | 721-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | FE000053 | Fence | 721-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Readings | Operations This Read Vac | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Readings | Operations Counter AL | 180 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Readings | Operations Counter AF | 180 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Readings | Maintenance Operations | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Readings | General Comments | | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Patrol Inspection | General Comments | | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Readings | Follow-up Action Required? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Readings | Fault Operations Ground | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1297 | BreakerVacuum | CS-1261 | VCB Readings | Unknown Operations | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | BAT001284 | Battery | LN-Battery Charger | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | BAT001284 | Battery | LN-Battery Charger | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | BAT001284 | Battery | LN-Battery Charger | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | BAT001284 | Battery | LN-Battery Charger | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | BAT001284 | Battery | LN-Battery Charger | Battery Patrol Inspection | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | BAT001284 | Battery | LN-Battery Charger | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | BAT001284 | Battery | LN-Battery Charger | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | BAT001284 | Battery | LN-Battery Charger | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | BAT001284 | Battery | LN-Battery Charger | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | BAT001284 | Battery | LN-Battery Charger | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | ST000060 | Structure | 721-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | ST000060 | Structure | 721-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | YD000055 | Yard | 721-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | YD000055 | Yard | 721-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | YD000055 | Yard | 721-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | YD000055 | Yard | 721-Yard | Yard Patrol Inspection | General Comments | | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | YD000055 | Yard | 721-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | YD000055 | Yard | 721-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | YD000055 | Yard | 721-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | YD000055 | Yard | 721-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | YD000055 | Yard | 721-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | YD000055 | Yard | 721-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | YD000055 | Yard | 721-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | YD000055 | Yard | 721-Yard | Yard Patrol Inspection | Ambient Temp | 44 | °F |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | FE000169 | Fence | 500-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | FE000169 | Fence | 500-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | FE000169 | Fence | 500-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | n | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | FE000169 | Fence | 500-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | FE000169 | Fence | 500-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | FE000169 | Fence | 500-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | FE000169 | Fence | 500-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | FE000169 | Fence | 500-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | FE000169 | Fence | 500-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | FE000169 | Fence | 500-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | FE000169 | Fence | 500-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | FE000169 | Fence | 500-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | FE000169 | Fence | 500-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | FE000053 | Fence | 721-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | FE000053 | Fence | 721-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | FE000053 | Fence | 721-Fence | Fence Patrol Inspection | General Comments | large gaps under fence | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | FE000053 | Fence | 721-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | FE000053 | Fence | 721-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | FE000053 | Fence | 721-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | FE000053 | Fence | 721-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | FE000053 | Fence | 721-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | FE000053 | Fence | 721-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1296 | BreakerVacuum | CS-1260 | VCB Readings | Accumulated Fault Duty B Ph V | 11.16 | % |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1296 | BreakerVacuum | CS-1260 | VCB Readings | Accumulated Fault Duty A Ph V | 10.36 | % |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1296 | BreakerVacuum | CS-1260 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1296 | BreakerVacuum | CS-1260 | VCB Readings | 9 Month Operations | 1 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | CH000241 | ControlHouse | 536-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | CH000241 | ControlHouse | 536-Control House | Control House Patrol Inspection | General Comments | | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | CH000241 | ControlHouse | 536-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | CH000241 | ControlHouse | 536-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | CH000489 | ControlHouse | 478-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | CH000489 | ControlHouse | 478-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | CH000489 | ControlHouse | 478-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | CH000489 | ControlHouse | 478-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | CH000489 | ControlHouse | 478-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | CH000489 | ControlHouse | 478-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | CH000489 | ControlHouse | 478-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | CH000489 | ControlHouse | 478-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | CH000241 | ControlHouse | 536-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | CH000241 | ControlHouse | 536-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | CH000489 | ControlHouse | 478-Control House | Control House Patrol Inspection | General Comments | | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | CH000489 | ControlHouse | 478-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | CH000489 | ControlHouse | 478-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | CH000489 | ControlHouse | 478-Control House | Control House Patrol Inspection | Floor Swept? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | CH000489 | ControlHouse | 478-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | YD000079 | Yard | 856-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | YD000079 | Yard | 856-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | YD000079 | Yard | 856-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | YD000079 | Yard | 856-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | YD000079 | Yard | 856-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | YD000079 | Yard | 856-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | YD000079 | Yard | 856-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | YD000079 | Yard | 856-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | YD000079 | Yard | 856-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | YD000079 | Yard | 856-Yard | Yard Patrol Inspection | General Comments | | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | YD000079 | Yard | 856-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | CH000489 | ControlHouse | 478-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | CH000489 | ControlHouse | 478-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | CH000489 | ControlHouse | 478-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | CH000489 | ControlHouse | 478-Control House | Control House Patrol Inspection | Door Alarms OK? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | CH000489 | ControlHouse | 478-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | CH000489 | ControlHouse | 478-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Readings | Totalizer Meter Reading | .4540 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 200.00 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Patrol Inspection | General Comments | | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Readings | General Comments | b,c,n ioc | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Readings | Maintenance Operations | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | CH000241 | ControlHouse | 536-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | CH000241 | ControlHouse | 536-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1296 | BreakerVacuum | CS-1260 | VCB Readings | Unknown Operations | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1296 | BreakerVacuum | CS-1260 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1296 | BreakerVacuum | CS-1260 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1296 | BreakerVacuum | CS-1260 | VCB Readings | Operations Counter AL | 212 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1296 | BreakerVacuum | CS-1260 | VCB Readings | Operations Counter AF | 212 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1296 | BreakerVacuum | CS-1260 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1296 | BreakerVacuum | CS-1260 | VCB Readings | General Comments | | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1296 | BreakerVacuum | CS-1260 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1296 | BreakerVacuum | CS-1260 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1296 | BreakerVacuum | CS-1260 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1296 | BreakerVacuum | CS-1260 | VCB Readings | Fault Operations Ground | 0 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | CH000241 | ControlHouse | 536-Control House | Control House Patrol Inspection | Floor Swept? | n | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | CH000241 | ControlHouse | 536-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1296 | BreakerVacuum | CS-1260 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1296 | BreakerVacuum | CS-1260 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1296 | BreakerVacuum | CS-1260 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1296 | BreakerVacuum | CS-1260 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1296 | BreakerVacuum | CS-1260 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1296 | BreakerVacuum | CS-1260 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1296 | BreakerVacuum | CS-1260 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1296 | BreakerVacuum | CS-1260 | VCB Readings | Amps C Ø | 15.0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1296 | BreakerVacuum | CS-1260 | VCB Readings | Amps B Ø | 9.0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1296 | BreakerVacuum | CS-1260 | VCB Readings | Amps A Ø | 51.0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1296 | BreakerVacuum | CS-1260 | VCB Readings | Accumulated Fault Duty C Ph V | 31.09 | % |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Readings | Amps C Ø | 23.0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Readings | Amps B Ø | 17.0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Readings | Amps A Ø | 40.0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Readings | 9 Month Operations | 0 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | FE000595 | Fence | JT-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | FE000595 | Fence | JT-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | LTCMechanism | CR-TRANS 2-B | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | LTCMechanism | CR-TRANS 2-B | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | LTCMechanism | CR-TRANS 2-B | LTC Counter Readings | General Comments | | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | LTCMechanism | CR-TRANS 2-B | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | LTCMechanism | CR-TRANS 2-B | LTC Counter Readings | LTC As Found Counter | 77072 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | LTCMechanism | CR-TRANS 2-B | LTC Counter Readings | LTC As Left Counter | 77072 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | LTCMechanism | CR-TRANS 2-B | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | LTCMechanism | CR-TRANS 2-B | LTC Counter Readings | LTC Current Tap Position | 14 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | LTCMechanism | CR-TRANS 2-B | LTC Counter Readings | LTC Operations Since Last Insp | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | LTCMechanism | CR-TRANS 2-B | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | FE000595 | Fence | JT-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | FE000595 | Fence | JT-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | FE000595 | Fence | JT-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | FE000595 | Fence | JT-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | LTCMechanism | CR-TRANS 2-B | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | LTCMechanism | CR-TRANS 1-A | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | LTCMechanism | CR-TRANS 1-A | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | LTCMechanism | CR-TRANS 1-A | LTC Counter Readings | General Comments | | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | LTCMechanism | CR-TRANS 1-A | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | LTCMechanism | CR-TRANS 1-A | LTC Counter Readings | LTC As Found Counter | 121525 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | FE000595 | Fence | JT-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | FE000595 | Fence | JT-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | FE000595 | Fence | JT-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | LTCMechanism | CR-TRANS 1-A | LTC Counter Readings | LTC As Left Counter | 121525 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | LTCMechanism | CR-TRANS 1-A | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | LTCMechanism | CR-TRANS 1-A | LTC Counter Readings | LTC Current Tap Position | 5 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | LTCMechanism | CR-TRANS 1-A | LTC Counter Readings | LTC Max Tap Position | 5 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | LTCMechanism | CR-TRANS 1-A | LTC Counter Readings | LTC Min Tap Position | 5 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0045 | LTCMechanism | CR-TRANS 1-A | LTC Counter Readings | LTC Operations Since Last Insp | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | CH000489 | ControlHouse | 478-Control House | Control House Patrol Inspection | Broom on Site? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | CH000489 | ControlHouse | 478-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | CH000489 | ControlHouse | 478-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Readings | Operations Counter AF | 147 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Readings | Operations Counter AL | 147 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Readings | Operations This Read Vac | 9 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Readings | Switching Operations | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Readings | Unknown Operations | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Readings | Unknown Operations | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Readings | Switching Operations | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Readings | Operations This Read Vac | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Readings | Operations Counter AL | 223 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Readings | Operations Counter AF | 223 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Readings | Maintenance Operations | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Readings | General Comments | | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Patrol Inspection | General Comments | | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Readings | Follow-up Action Required? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Readings | Fault Operations Ground | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | FE000595 | Fence | JT-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | FE000595 | Fence | JT-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | FE000595 | Fence | JT-Fence | Fence Patrol Inspection | General Comments | | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | FE000595 | Fence | JT-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | FE000595 | Fence | JT-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/9/2023 11:52 | Distribution | Jeffersontown Quarterly Inspection | FE000595 | Fence | JT-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001273 | BreakerVacuum | 721-0213 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | YD000034 | Yard | 536-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | YD000034 | Yard | 536-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | YD000034 | Yard | 536-Yard | Yard Patrol Inspection | General Comments | | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | YD000034 | Yard | 536-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | YD000034 | Yard | 536-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | ST000037 | Structure | 536-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | ST000037 | Structure | 536-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | ST000037 | Structure | 536-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | ST000174 | Structure | 500-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | ST000174 | Structure | 500-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | ST000174 | Structure | 500-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | ST000174 | Structure | 500-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Readings | Amps C Ø | 138.0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Readings | Amps B Ø | 145.0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Readings | Amps A Ø | 155.0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LTCC000522 | LTCControl | CS-TRANS 1 | LTC Control Insp | General Comments | ok | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LTCC000522 | LTCControl | CS-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | PF000066 | PowerFuse | CR-14KV TR 1-A POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | PF000066 | PowerFuse | CR-14KV TR 1-A POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | PF000066 | PowerFuse | CR-14KV TR 1-A POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001272 | BreakerVacuum | 721-0212 | VCB Readings | 9 Month Operations | 1 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | ST000037 | Structure | 536-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | ST000037 | Structure | 536-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | ST000037 | Structure | 536-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0572 | BreakerAirMagnetic | LN-4 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0572 | BreakerAirMagnetic | LN-4 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0572 | BreakerAirMagnetic | LN-4 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0572 | BreakerAirMagnetic | LN-4 | AMCB Readings | Amps C Ø | 180.0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0572 | BreakerAirMagnetic | LN-4 | AMCB Readings | Amps B Ø | 230.0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0572 | BreakerAirMagnetic | LN-4 | AMCB Readings | Amps A Ø | 230.0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0572 | BreakerAirMagnetic | LN-4 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0572 | BreakerAirMagnetic | LN-4 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0572 | BreakerAirMagnetic | LN-4 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0572 | BreakerAirMagnetic | LN-4 | AMCB Readings | 9 Months Operations | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0572 | BreakerAirMagnetic | LN-4 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Readings | Fault Operations Ground | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Readings | Follow-up Action Required? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Patrol Inspection | General Comments | | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Readings | General Comments | | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Readings | Maintenance Operations | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Readings | Operations Counter AF | 235 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Readings | Operations Counter AL | 235 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Readings | Operations This Read Vac | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Readings | Switching Operations | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Readings | Unknown Operations | 0 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | ST000174 | Structure | 500-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | ST000174 | Structure | 500-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | YD000034 | Yard | 536-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | YD000034 | Yard | 536-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | YD000034 | Yard | 536-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | YD000034 | Yard | 536-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | YD000034 | Yard | 536-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | YD000034 | Yard | 536-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | YD000034 | Yard | 536-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | YD000035 | Yard | 478-Yard | Yard Patrol Inspection | Clear of Trash? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | YD000035 | Yard | 478-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | YD000035 | Yard | 478-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | YD000035 | Yard | 478-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | YD000035 | Yard | 478-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | YD000035 | Yard | 478-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | YD000035 | Yard | 478-Yard | Yard Patrol Inspection | General Comments | | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | YD000035 | Yard | 478-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | YD000035 | Yard | 478-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | YD000035 | Yard | 478-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | YD000035 | Yard | 478-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | ST000039 | Structure | 478-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | ST000039 | Structure | 478-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | ST000039 | Structure | 478-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | ST000039 | Structure | 478-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | ST000039 | Structure | 478-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | ST000039 | Structure | 478-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | ST000039 | Structure | 478-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | ST000039 | Structure | 478-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | ST000039 | Structure | 478-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | ST000039 | Structure | 478-Structure | Structure Patrol Inspection | General Comments | | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | ST000039 | Structure | 478-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | ST000039 | Structure | 478-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | ST000039 | Structure | 478-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | ST000039 | Structure | 478-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | ST000039 | Structure | 478-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | ST000039 | Structure | 478-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | ST000039 | Structure | 478-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | ST000039 | Structure | 478-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | ST000039 | Structure | 478-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | ST000039 | Structure | 478-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | ST000039 | Structure | 478-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | ST000039 | Structure | 478-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | LTCC000822 | LTCControl | 500-1 | LTC Control Insp | VRR Time Delay | 45 | Seconds |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | LTCC000822 | LTCControl | 500-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | LTCC000822 | LTCControl | 500-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | LTCC000822 | LTCControl | 500-1 | LTC Control Insp | LTC Output Voltage Level | 124.7 | VAC |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | LTCC000822 | LTCControl | 500-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | LTCC000822 | LTCControl | 500-1 | LTC Control Insp | General Comments | | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | LTCC000822 | LTCControl | 500-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | LTCC000822 | LTCControl | 500-1 | LTC Control Insp | All Connections OK? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | ST000037 | Structure | 536-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | ST000037 | Structure | 536-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | ST000037 | Structure | 536-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | ST000037 | Structure | 536-Structure | Structure Patrol Inspection | General Comments | | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | ST000037 | Structure | 536-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | ST000037 | Structure | 536-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | ST000037 | Structure | 536-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | ST000037 | Structure | 536-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | ST000037 | Structure | 536-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | ST000037 | Structure | 536-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000033 | Switchgear | LN-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000033 | Switchgear | LN-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000033 | Switchgear | LN-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000033 | Switchgear | LN-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | ST000037 | Structure | 536-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | ST000037 | Structure | 536-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | ST000037 | Structure | 536-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | ST000037 | Structure | 536-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | ST000037 | Structure | 536-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | ST000037 | Structure | 536-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | YD000035 | Yard | 478-Yard | Yard Patrol Inspection | Ambient Temp | 40 | °F |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | YD000035 | Yard | 478-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | YD000634 | Yard | CR-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | YD000634 | Yard | CR-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | YD000634 | Yard | CR-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | YD000634 | Yard | CR-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | YD000634 | Yard | CR-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | YD000634 | Yard | CR-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | YD000634 | Yard | CR-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | YD000634 | Yard | CR-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | YD000634 | Yard | CR-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | YD000634 | Yard | CR-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | YD000634 | Yard | CR-Yard | Yard Patrol Inspection | General Comments | handle on valve missing. | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | YD000634 | Yard | CR-Yard | Yard Patrol Inspection | Oil stop valve operational? | n | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | YD000634 | Yard | CR-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | YD000634 | Yard | CR-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | YD000634 | Yard | CR-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | YD000634 | Yard | CR-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | YD000634 | Yard | CR-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | YD000634 | Yard | CR-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | YD000634 | Yard | CR-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | YD000035 | Yard | 478-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | YD000167 | Yard | 500-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000033 | Switchgear | LN-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000033 | Switchgear | LN-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000033 | Switchgear | LN-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000033 | Switchgear | LN-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1297 | BreakerVacuum | CS-1261 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Readings | 9 Month Operations | 1 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Readings | Amps A Ø | 107.0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Readings | Amps B Ø | 113.0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Readings | Amps C Ø | 114.0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Readings | Fault Operations Ground | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Patrol Inspection | General Comments | | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1297 | BreakerVacuum | CS-1261 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1297 | BreakerVacuum | CS-1261 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1297 | BreakerVacuum | CS-1261 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Readings | General Comments | | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Readings | Maintenance Operations | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Readings | Operations Counter AF | 191 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1297 | BreakerVacuum | CS-1261 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | BAT001284 | Battery | LN-Battery Charger | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | BAT001284 | Battery | LN-Battery Charger | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1297 | BreakerVacuum | CS-1261 | VCB Readings | Switching Operations | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1297 | BreakerVacuum | CS-1261 | VCB Readings | Operations This Read Vac | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1297 | BreakerVacuum | CS-1261 | VCB Readings | Operations Counter AL | 199 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1297 | BreakerVacuum | CS-1261 | VCB Readings | Operations Counter AF | 199 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1297 | BreakerVacuum | CS-1261 | VCB Readings | Maintenance Operations | 0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1297 | BreakerVacuum | CS-1261 | VCB Readings | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | BAT001284 | Battery | LN-Battery Charger | Battery Patrol Inspection | Battery Bank Volts | 26.7 | VDC |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | BAT001284 | Battery | LN-Battery Charger | Battery Patrol Inspection | Battery Bank Amps | .1 | AMPS |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0479 | WithLTC | 478-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1297 | BreakerVacuum | CS-1261 | VCB Patrol Inspection | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | BAT001284 | Battery | LN-Battery Charger | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1297 | BreakerVacuum | CS-1261 | VCB Readings | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1297 | BreakerVacuum | CS-1261 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1297 | BreakerVacuum | CS-1261 | VCB Readings | Fault Operations Ground | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000033 | Switchgear | LN-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000033 | Switchgear | LN-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000033 | Switchgear | LN-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000033 | Switchgear | LN-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | YD000167 | Yard | 500-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | YD000167 | Yard | 500-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | YD000167 | Yard | 500-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | YD000167 | Yard | 500-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | YD000167 | Yard | 500-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | YD000167 | Yard | 500-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | YD000167 | Yard | 500-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | YD000167 | Yard | 500-Yard | Yard Patrol Inspection | General Comments | | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BCH001389 | Charger | 478-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BCH001389 | Charger | 478-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BCH001389 | Charger | 478-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BCH001389 | Charger | 478-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.4 | amps |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BCH001389 | Charger | 478-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BCH001389 | Charger | 478-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BCH001389 | Charger | 478-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 3.350 | millivolts |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | ST000174 | Structure | 500-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | ST000174 | Structure | 500-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | ST000174 | Structure | 500-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | ST000174 | Structure | 500-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Readings | 9 Month Operations | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0572 | BreakerAirMagnetic | LN-4 | AMCB Readings | Unknown Operations | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0572 | BreakerAirMagnetic | LN-4 | AMCB Readings | Switching Operations | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0572 | BreakerAirMagnetic | LN-4 | AMCB Readings | Operations This Read AM | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0572 | BreakerAirMagnetic | LN-4 | AMCB Readings | Operations Counter AL | 6 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0572 | BreakerAirMagnetic | LN-4 | AMCB Readings | Operations Counter AF | 6 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0572 | BreakerAirMagnetic | LN-4 | AMCB Readings | Maintenance Operations | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0572 | BreakerAirMagnetic | LN-4 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0572 | BreakerAirMagnetic | LN-4 | AMCB Readings | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0572 | BreakerAirMagnetic | LN-4 | AMCB Patrol Inspection | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0572 | BreakerAirMagnetic | LN-4 | AMCB Readings | Follow-up Action Required? | n | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0572 | BreakerAirMagnetic | LN-4 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0572 | BreakerAirMagnetic | LN-4 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0572 | BreakerAirMagnetic | LN-4 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0572 | BreakerAirMagnetic | LN-4 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0572 | BreakerAirMagnetic | LN-4 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Readings | Amps A Ø | 72.0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Readings | Amps B Ø | 75.0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Readings | Amps C Ø | 69.0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | BK001271 | BreakerVacuum | 721-0211 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0572 | BreakerAirMagnetic | LN-4 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1297 | BreakerVacuum | CS-1261 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1297 | BreakerVacuum | CS-1261 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Readings | Operations Counter AL | 191 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Readings | Operations This Read Vac | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Readings | Switching Operations | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BK000894 | BreakerVacuum | 478-0225 | VCB Readings | Unknown Operations | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000033 | Switchgear | LN-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000033 | Switchgear | LN-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000033 | Switchgear | LN-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | SWG000033 | Switchgear | LN-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | BCH001228 | Charger | LN-Battery Bank | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | BCH001228 | Charger | LN-Battery Bank | Battery Charger Patrol Insp | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | BCH001228 | Charger | LN-Battery Bank | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | BCH001228 | Charger | LN-Battery Bank | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | BCH001228 | Charger | LN-Battery Bank | Battery Charger Patrol Insp | Battery Charger Current | 0.0 | amps |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | BCH001228 | Charger | LN-Battery Bank | Battery Charger Patrol Insp | As Left Float Voltage | 26.7 | VDC |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | BCH001228 | Charger | LN-Battery Bank | Battery Charger Patrol Insp | As Found Float Voltage | 26.7 | VDC |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | BCH001228 | Charger | LN-Battery Bank | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1297 | BreakerVacuum | CS-1261 | VCB Readings | Amps C Ø | 122.0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1297 | BreakerVacuum | CS-1261 | VCB Readings | Amps B Ø | 136.0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1297 | BreakerVacuum | CS-1261 | VCB Readings | Amps A Ø | 142.0 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1297 | BreakerVacuum | CS-1261 | VCB Readings | Accumulated Fault Duty C Ph V | 20.73 | % |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1297 | BreakerVacuum | CS-1261 | VCB Readings | Accumulated Fault Duty B Ph V | 31.09 | % |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1297 | BreakerVacuum | CS-1261 | VCB Readings | Accumulated Fault Duty A Ph V | 26.31 | % |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1297 | BreakerVacuum | CS-1261 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/9/2023 8:06 | Distribution | Conestoga Quarterly Inspection | LB1297 | BreakerVacuum | CS-1261 | VCB Readings | 9 Month Operations | 4 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | YD000167 | Yard | 500-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | YD000167 | Yard | 500-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | ST000174 | Structure | 500-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | ST000174 | Structure | 500-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | ST000174 | Structure | 500-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | ST000174 | Structure | 500-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | ST000174 | Structure | 500-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | ST000174 | Structure | 500-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | ST000174 | Structure | 500-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | ST000174 | Structure | 500-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | ST000174 | Structure | 500-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | ST000174 | Structure | 500-Structure | Structure Patrol Inspection | General Comments | | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | ST000174 | Structure | 500-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | ST000174 | Structure | 500-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | BCH001389 | Charger | 478-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | LTCC000887 | LTCControl | 478-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | LTCC000887 | LTCControl | 478-2 | LTC Control Insp | VRR Time Delay | 45 | Seconds |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Readings | Maintenance Operations | 0 | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | FE000079 | Fence | 856-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | FE000079 | Fence | 856-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | FE000079 | Fence | 856-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | FE000079 | Fence | 856-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | FE000079 | Fence | 856-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Readings | Follow-up Action Required? | n | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | FE000079 | Fence | 856-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | FE000079 | Fence | 856-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | FE000079 | Fence | 856-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | FE000079 | Fence | 856-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | FE000079 | Fence | 856-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | FE000079 | Fence | 856-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | FE000079 | Fence | 856-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | FE000079 | Fence | 856-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | FE000079 | Fence | 856-Fence | Fence Patrol Inspection | General Comments | two large gaps in corner next to the scrap yard, brabed wire rusty and sagging, one bayonet broken, fence post very loose | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | FE000079 | Fence | 856-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/8/2023 10:30 | Distribution | Ferguson Quarterly Inspection | FE000079 | Fence | 856-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Readings | Unknown Operations | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Readings | Switching Operations | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Readings | Operations Counter AL | 163 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Readings | Fault Operations Ground | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Readings | Fault Operations C Ø | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Readings | Fault Operations B Ø | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Readings | Fault Operations A Ø | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Readings | Operations Counter AF | 163 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Readings | Maintenance Operations | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Readings | General Comments | | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Patrol Inspection | General Comments | | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Readings | Follow-up Action Required? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Readings | Operations Counter AF | 506 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Readings | Operations Counter AL | 506 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Readings | Operations This Read Vac | 0 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Readings | Switching Operations | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Readings | 9 Month Operations | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Readings | Amps C Ø | 286.0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Readings | Amps B Ø | 291.0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Readings | Accumulated Fault Duty A Ph V | .3 | % |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Readings | Accumulated Fault Duty B Ph V | .3 | % |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Readings | Amps A Ø | 288.0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Readings | Accumulated Fault Duty C Ph V | .3 | % |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Readings | Amps A Ø | 0.0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Readings | Accumulated Fault Duty C Ph V | .15 | % |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Readings | Accumulated Fault Duty B Ph V | .15 | % |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | LTCMechanism | 478-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | LTCMechanism | 478-2 | LTC Counter Readings | LTC As Left Counter | 15199 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | LTCMechanism | 478-2 | LTC Counter Readings | LTC As Found Counter | 15186 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | LTCMechanism | 478-2 | LTC Mechanism Patrol Inspection | General Comments | Desiccant needs to be moved down for easier access. | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | LTCMechanism | 478-2 | LTC Counter Readings | General Comments | | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LTCC000883 | LTCControl | CR-TRANS 1-A | LTC Control Insp | All Connections OK? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LTCC000883 | LTCControl | CR-TRANS 1-A | LTC Control Insp | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LTCC000883 | LTCControl | CR-TRANS 1-A | LTC Control Insp | General Comments | | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BCH001292 | Charger | 500-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BCH001292 | Charger | 500-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BCH001292 | Charger | 500-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BCH001292 | Charger | 500-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BCH001292 | Charger | 500-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.4 | amps |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BCH001292 | Charger | 500-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BCH001292 | Charger | 500-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BCH001292 | Charger | 500-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.900 | millivolts |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Readings | Unknown Operations | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Readings | Switching Operations | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Readings | Operations This Read Vac | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | FE000038 | Fence | 478-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | FE000038 | Fence | 478-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | n | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 35 | °C |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 65 | °C |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 165.00 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Readings | Operations Counter AL | 188 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Readings | Operations Counter AF | 188 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Readings | Maintenance Operations | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Readings | General Comments | | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Patrol Inspection | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Readings | MegaWatt Demand Meter Min | .30 | MegaWatts |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Readings | MegaWatt Demand Meter Max | 1.00 | MegaWatts |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Readings | MegaVar Demand Meter Min | -.40 | MegaVars |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Readings | MegaVar Demand Meter Max | -.10 | MegaVars |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | LTCC000887 | LTCControl | 478-2 | LTC Control Insp | All Connections OK? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | LTCC000887 | LTCControl | 478-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | LTCC000887 | LTCControl | 478-2 | LTC Control Insp | General Comments | | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | LTCC000887 | LTCControl | 478-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | LTCC000887 | LTCControl | 478-2 | LTC Control Insp | LTC Output Voltage Level | 124.5 | VAC |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | LTCC000887 | LTCControl | 478-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | CH000146 | ControlHouse | CR-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Readings | Maintenance Operations | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | CH000146 | ControlHouse | CR-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | CH000146 | ControlHouse | CR-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | CH000146 | ControlHouse | CR-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | CH000146 | ControlHouse | CR-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | CH000146 | ControlHouse | CR-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | CH000146 | ControlHouse | CR-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | CH000467 | ControlHouse | 721-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | CH000467 | ControlHouse | 721-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | CH000467 | ControlHouse | 721-Control House | Control House Patrol Inspection | Broom on Site? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | CH000467 | ControlHouse | 721-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | CH000467 | ControlHouse | 721-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | CH000467 | ControlHouse | 721-Control House | Control House Patrol Inspection | Door Alarms OK? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | CH000467 | ControlHouse | 721-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | CH000467 | ControlHouse | 721-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | CH000467 | ControlHouse | 721-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | CH000467 | ControlHouse | 721-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | CH000467 | ControlHouse | 721-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | CH000467 | ControlHouse | 721-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | CH000467 | ControlHouse | 721-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | CH000467 | ControlHouse | 721-Control House | Control House Patrol Inspection | General Comments | | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | CH000467 | ControlHouse | 721-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | CH000467 | ControlHouse | 721-Control House | Control House Patrol Inspection | Panel Lights OK? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | CH000467 | ControlHouse | 721-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | CH000467 | ControlHouse | 721-Control House | Control House Patrol Inspection | Station Ground Set On Site? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | CH000467 | ControlHouse | 721-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | CH000467 | ControlHouse | 721-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | CH000467 | ControlHouse | 721-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | CH000467 | ControlHouse | 721-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | CH000146 | ControlHouse | CR-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | LTCMechanism | 721-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | LTCMechanism | 721-1 | LTC Counter Readings | LTC As Found Counter | 210144 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | LTCMechanism | 721-1 | LTC Counter Readings | LTC As Left Counter | 210152 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | LTCMechanism | 721-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | LTCMechanism | 721-1 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | LTCMechanism | 721-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | LTCMechanism | 721-1 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | LTCMechanism | 721-1 | LTC Counter Readings | LTC Operations Since Last Insp | 898 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | CH000146 | ControlHouse | CR-Control House | Control House Patrol Inspection | Basement Condition Acceptible | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Readings | Fault Operations C Ø | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Readings | Fault Operations Ground | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | CH000146 | ControlHouse | CR-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Readings | General Comments | | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | CH000146 | ControlHouse | CR-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Patrol Inspection | General Comments | | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Readings | Follow-up Action Required? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | LTCMechanism | 721-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | LTCMechanism | 721-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | LTCMechanism | 721-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Readings | 9 Month Operations | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Readings | Amps A Ø | 320.0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Readings | Amps B Ø | 320.0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Readings | Amps C Ø | 320.0 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | MB0151 | BreakerVacuum | 721-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Readings | Accumulated Fault Duty A Ph V | .37 | % |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Readings | Amps B Ø | 0.0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Readings | Amps C Ø | 0.0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0569 | BreakerAirMagnetic | LN-1 | AMCB Readings | Unknown Operations | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0569 | BreakerAirMagnetic | LN-1 | AMCB Readings | Switching Operations | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0569 | BreakerAirMagnetic | LN-1 | AMCB Readings | Operations This Read AM | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0569 | BreakerAirMagnetic | LN-1 | AMCB Readings | Operations Counter AL | 520 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0569 | BreakerAirMagnetic | LN-1 | AMCB Readings | Operations Counter AF | 520 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0569 | BreakerAirMagnetic | LN-1 | AMCB Readings | Maintenance Operations | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0569 | BreakerAirMagnetic | LN-1 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0569 | BreakerAirMagnetic | LN-1 | AMCB Readings | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0569 | BreakerAirMagnetic | LN-1 | AMCB Patrol Inspection | General Comments | | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0569 | BreakerAirMagnetic | LN-1 | AMCB Readings | Follow-up Action Required? | n | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0569 | BreakerAirMagnetic | LN-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0569 | BreakerAirMagnetic | LN-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0569 | BreakerAirMagnetic | LN-1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0569 | BreakerAirMagnetic | LN-1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0569 | BreakerAirMagnetic | LN-1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0569 | BreakerAirMagnetic | LN-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0569 | BreakerAirMagnetic | LN-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | K0003 | BreakerVacuum | 536-0235 | VCB Readings | Unknown Operations | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0569 | BreakerAirMagnetic | LN-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0569 | BreakerAirMagnetic | LN-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0569 | BreakerAirMagnetic | LN-1 | AMCB Readings | Amps C Ø | 190.0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0569 | BreakerAirMagnetic | LN-1 | AMCB Readings | Amps B Ø | 210.0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000914 | BreakerVacuum | CR-14KV TRANS 1-A | VCB Readings | 9 Month Operations | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Readings | Unknown Operations | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Readings | Switching Operations | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Readings | Operations This Read Vac | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Readings | Operations Counter AL | 208 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Readings | Operations Counter AF | 208 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0569 | BreakerAirMagnetic | LN-1 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0569 | BreakerAirMagnetic | LN-1 | AMCB Readings | 9 Months Operations | 0 | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0569 | BreakerAirMagnetic | LN-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0569 | BreakerAirMagnetic | LN-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0569 | BreakerAirMagnetic | LN-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | LB0569 | BreakerAirMagnetic | LN-1 | AMCB Readings | Amps A Ø | 150.0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | LTCMechanism | 721-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | LTCMechanism | 721-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 13:10 | Distribution | Caron Quarterly Inspection | M0092 | LTCMechanism | 721-1 | LTC Counter Readings | General Comments | | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Readings | Fault Operations A Ø | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | BK000913 | BreakerVacuum | CR-GND TRANS 1-A | VCB Readings | Fault Operations B Ø | 0 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | LTCMechanism | 478-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | LTCMechanism | 478-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | CH000146 | ControlHouse | CR-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | CH000146 | ControlHouse | CR-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | CH000146 | ControlHouse | CR-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | CH000146 | ControlHouse | CR-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | CH000146 | ControlHouse | CR-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | CH000146 | ControlHouse | CR-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | CH000146 | ControlHouse | CR-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | CH000146 | ControlHouse | CR-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | CH000146 | ControlHouse | CR-Control House | Control House Patrol Inspection | General Comments | Bathroom out of service, no heat for building, lighting is very poor. | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | CH000146 | ControlHouse | CR-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | CH000146 | ControlHouse | CR-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | CH000146 | ControlHouse | CR-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Readings | Amps C Ø | 36.0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Readings | Amps B Ø | 35.0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Readings | Amps A Ø | 36.0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Readings | Amps C Ø | 0.0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Readings | Amps B Ø | 0.0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Readings | Amps A Ø | 0.0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Readings | Accumulated Fault Duty C Ph V | 4.59 | % |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Readings | Accumulated Fault Duty B Ph V | 15.31 | % |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Readings | Accumulated Fault Duty A Ph V | 16.84 | % |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Readings | 9 Month Operations | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Readings | Accumulated Fault Duty C Ph V | 4.59 | % |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Readings | Accumulated Fault Duty B Ph V | 18.37 | % |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Readings | Accumulated Fault Duty A Ph V | 13.78 | % |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | FE000831 | Fence | 536-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | FE000831 | Fence | 536-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | FE000831 | Fence | 536-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | FE000831 | Fence | 536-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | FE000831 | Fence | 536-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | FE000831 | Fence | 536-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | FE000831 | Fence | 536-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Readings | 9 Month Operations | 12 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Readings | Totalizer Meter Reading | .6102 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | FE000831 | Fence | 536-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | FE000831 | Fence | 536-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | FE000831 | Fence | 536-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | FE000831 | Fence | 536-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BAT001387 | Battery | 500-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BAT001387 | Battery | 500-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BAT001387 | Battery | 500-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BAT001387 | Battery | 500-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BAT001387 | Battery | 500-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BAT001387 | Battery | 500-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BAT001387 | Battery | 500-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BAT001387 | Battery | 500-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BAT001387 | Battery | 500-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | BAT001387 | Battery | 500-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0037 | WithLTC | CR-TRANS 2-B | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 40 | °C |
| 3/8/2023 10:16 | Distribution | Lynn Quarterly Inspection | PN40 | WithLTC | LN-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 65 | °C |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | FE000038 | Fence | 478-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | FE000038 | Fence | 478-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | FE000038 | Fence | 478-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | FE000038 | Fence | 478-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | FE000038 | Fence | 478-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | FE000038 | Fence | 478-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | FE000038 | Fence | 478-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | FE000038 | Fence | 478-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | FE000038 | Fence | 478-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | FE000038 | Fence | 478-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | FE000038 | Fence | 478-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | FE000038 | Fence | 478-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | FE000038 | Fence | 478-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | FE000038 | Fence | 478-Fence | Fence Patrol Inspection | General Comments | gap under fence in right hand corner. some posts show rust | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Readings | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Readings | Fault Operations Ground | 3 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Readings | Fault Operations C Ø | 3 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Readings | Fault Operations B Ø | 3 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Readings | Fault Operations A Ø | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Readings | Fault Adjusted Amps C Phase V | 348.57 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Readings | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Readings | Fault Adjusted Amps B Phase V | 348.57 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Readings | Fault Adjusted Amps A Phase V | 174.28 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Readings | Fault Operations Ground | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Readings | Fault Operations C Ø | 0 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Readings | Oil Temp Present | 33 | °C |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Readings | Fault Operations B Ø | 0 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | FE000831 | Fence | 536-Fence | Fence Patrol Inspection | General Comments | | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | FE000831 | Fence | 536-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Readings | LTC Totalizer Reading | 2179.20 | kw |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Readings | General Comments | | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0272 | GroundTransformer | CR-GND TRANS 1-A | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0272 | GroundTransformer | CR-GND TRANS 1-A | Ground Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0272 | GroundTransformer | CR-GND TRANS 1-A | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0272 | GroundTransformer | CR-GND TRANS 1-A | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0272 | GroundTransformer | CR-GND TRANS 1-A | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0272 | GroundTransformer | CR-GND TRANS 1-A | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0272 | GroundTransformer | CR-GND TRANS 1-A | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0272 | GroundTransformer | CR-GND TRANS 1-A | Ground Transformer Patrol Inspection | General Comments | | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0272 | GroundTransformer | CR-GND TRANS 1-A | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0272 | GroundTransformer | CR-GND TRANS 1-A | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | .8 | psi |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0272 | GroundTransformer | CR-GND TRANS 1-A | Ground Transformer Patrol Inspection | Oil Temp Max | 50 | °C |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0272 | GroundTransformer | CR-GND TRANS 1-A | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0272 | GroundTransformer | CR-GND TRANS 1-A | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0272 | GroundTransformer | CR-GND TRANS 1-A | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0272 | GroundTransformer | CR-GND TRANS 1-A | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0272 | GroundTransformer | CR-GND TRANS 1-A | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0272 | GroundTransformer | CR-GND TRANS 1-A | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LT0272 | GroundTransformer | CR-GND TRANS 1-A | Ground Transformer Patrol Inspection | Winding Temp Max | 55 | °C |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | CH000241 | ControlHouse | 536-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | CH000241 | ControlHouse | 536-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | CH000241 | ControlHouse | 536-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | CH000241 | ControlHouse | 536-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | CH000241 | ControlHouse | 536-Control House | Control House Patrol Inspection | Broom on Site? | n | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | CH000241 | ControlHouse | 536-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | CH000241 | ControlHouse | 536-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | FE000831 | Fence | 536-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Readings | Fault Operations A Ø | 0 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1280 | BreakerVacuum | CR-1422-A | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/8/2023 11:00 | Distribution | Cane Run Generating Quarterly Inspection | LB1276 | BreakerVacuum | CR-1420-A | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | LTCMechanism | 500-1 | LTC Counter Readings | LTC Operations Since Last Insp | 670 | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | LTCMechanism | 500-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | LTCMechanism | 500-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | LTCMechanism | 500-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | LTCMechanism | 500-1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | LTCMechanism | 500-1 | LTC Counter Readings | LTC Max Tap Position | 16R | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | LTCMechanism | 500-1 | LTC Counter Readings | LTC Current Tap Position | 3R | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | LTCMechanism | 500-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | LTCMechanism | 500-1 | LTC Counter Readings | LTC As Left Counter | 17961 | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | LTCMechanism | 500-1 | LTC Counter Readings | LTC As Found Counter | 17953 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | LTCMechanism | 500-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | LTCMechanism | 500-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | LTCMechanism | 478-2 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | LTCMechanism | 478-2 | LTC Counter Readings | LTC Max Tap Position | 8R | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | LTCMechanism | 478-2 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | LTCMechanism | 478-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | LTCMechanism | 478-2 | LTC Counter Readings | LTC Operations Since Last Insp | 1033 | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | LTCMechanism | 478-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | LTCMechanism | 478-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | LTCMechanism | 478-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | LTCMechanism | 478-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | LTCMechanism | 500-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/8/2023 11:00 | Distribution | Ferguson South Quarterly Inspection | C0511 | LTCMechanism | 500-1 | LTC Counter Readings | General Comments | | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Readings | Oil Temp Max | 70 | °C |
| 3/8/2023 12:10 | Distribution | Williamsburg Quarterly Inspection | B0289 | WithLTC | 536-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Readings | LTC Totalizer Reading | 4393.44 | kw |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/8/2023 10:17 | Distribution | Williamsburg South Quarterly Inspection | B0378 | WithLTC | 478-2 | LTC Transformer Readings | General Comments | | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | YD000632 | Yard | CG-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | TX000284 | GroundTransformer | AL-GND TR 3 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001477 | BreakerVacuum | AL-GND TR 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001477 | BreakerVacuum | AL-GND TR 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001477 | BreakerVacuum | AL-GND TR 2 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | TX000284 | GroundTransformer | AL-GND TR 3 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 135.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001477 | BreakerVacuum | AL-GND TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001477 | BreakerVacuum | AL-GND TR 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001477 | BreakerVacuum | AL-GND TR 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001477 | BreakerVacuum | AL-GND TR 2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001477 | BreakerVacuum | AL-GND TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | TX000284 | GroundTransformer | AL-GND TR 3 | Ground Transformer Patrol Inspection | Gas Accumulation Gauge | Normal | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | YD000632 | Yard | CG-Yard | Yard Patrol Inspection | Ambient Temp | 48 | °F |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001049 | BreakerVacuum | AL-1379 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0026 | GroundTransformer | CG-GND TR 1 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001049 | BreakerVacuum | AL-1379 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0026 | GroundTransformer | CG-GND TR 1 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0026 | GroundTransformer | CG-GND TR 1 | Ground Transformer Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001477 | BreakerVacuum | AL-GND TR 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001477 | BreakerVacuum | AL-GND TR 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001477 | BreakerVacuum | AL-GND TR 2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 29 | °C |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0026 | GroundTransformer | CG-GND TR 1 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0026 | GroundTransformer | CG-GND TR 1 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0026 | GroundTransformer | CG-GND TR 1 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0026 | GroundTransformer | CG-GND TR 1 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001477 | BreakerVacuum | AL-GND TR 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001477 | BreakerVacuum | AL-GND TR 2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001477 | BreakerVacuum | AL-GND TR 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0026 | GroundTransformer | CG-GND TR 1 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | TX000284 | GroundTransformer | AL-GND TR 3 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | TX000284 | GroundTransformer | AL-GND TR 3 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | TX000284 | GroundTransformer | AL-GND TR 3 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | TX000284 | GroundTransformer | AL-GND TR 3 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | TX000284 | GroundTransformer | AL-GND TR 3 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | TX000284 | GroundTransformer | AL-GND TR 3 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | TX000284 | GroundTransformer | AL-GND TR 3 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | .4 | psi |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | TX000284 | GroundTransformer | AL-GND TR 3 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | TX000284 | GroundTransformer | AL-GND TR 3 | Ground Transformer Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | TX000284 | GroundTransformer | AL-GND TR 3 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0008 | GroundTransformer | AL-GND TR 4 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Readings | H2 Winding Temp Max | 41 | °C |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Readings | H2 Winding Temp Present | 31 | °C |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0005 | BreakerSF6 | AK-1295 | GCB Patrol Inspection | General Comments | | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0005 | BreakerSF6 | AK-1295 | GCB Readings | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0005 | BreakerSF6 | AK-1295 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0005 | BreakerSF6 | AK-1295 | GCB Readings | Fault Operations | 4 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0005 | BreakerSF6 | AK-1295 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | YD000632 | Yard | CG-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | PF000001 | PowerFuse | AK-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | PF000001 | PowerFuse | AK-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0117 | BreakerVacuum | CG-1436 | VCB Readings | Operations This Read Vac | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0117 | BreakerVacuum | CG-1436 | VCB Readings | Switching Operations | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0117 | BreakerVacuum | CG-1436 | VCB Readings | Unknown Operations | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | YD000632 | Yard | CG-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | PF000001 | PowerFuse | AK-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | PF000002 | PowerFuse | AK-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | PF000002 | PowerFuse | AK-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | PF000004 | PowerFuse | AK-STA SER NO 2 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | PF000004 | PowerFuse | AK-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | YD000632 | Yard | CG-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000016 | PowerFuse | AL-14KV BUS SEC 4 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000016 | PowerFuse | AL-14KV BUS SEC 4 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000016 | PowerFuse | AL-14KV BUS SEC 4 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000015 | PowerFuse | AL-14KV BUS SEC 3 POT | Disconnect Powerfuse Inspection | General Comments | ok | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000015 | PowerFuse | AL-14KV BUS SEC 3 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000015 | PowerFuse | AL-14KV BUS SEC 3 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000014 | PowerFuse | AL-14KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000014 | PowerFuse | AL-14KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000014 | PowerFuse | AL-14KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001049 | BreakerVacuum | AL-1379 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001049 | BreakerVacuum | AL-1379 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001049 | BreakerVacuum | AL-1379 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001049 | BreakerVacuum | AL-1379 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001049 | BreakerVacuum | AL-1379 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001049 | BreakerVacuum | AL-1379 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001049 | BreakerVacuum | AL-1379 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001049 | BreakerVacuum | AL-1379 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001049 | BreakerVacuum | AL-1379 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | YD000632 | Yard | CG-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | YD000632 | Yard | CG-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | YD000632 | Yard | CG-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | YD000632 | Yard | CG-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | YD000632 | Yard | CG-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | YD000632 | Yard | CG-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0008 | GroundTransformer | AL-GND TR 4 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0008 | GroundTransformer | AL-GND TR 4 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | YD000632 | Yard | CG-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | YD000632 | Yard | CG-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | YD000632 | Yard | CG-Yard | Yard Patrol Inspection | General Comments | | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | YD000632 | Yard | CG-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | YD000632 | Yard | CG-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 41 | °C |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 31 | °C |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001477 | BreakerVacuum | AL-GND TR 2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 41 | °C |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 21 | °C |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 41 | °C |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0026 | GroundTransformer | CG-GND TR 1 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0026 | GroundTransformer | CG-GND TR 1 | Ground Transformer Patrol Inspection | Oil Temp Max | 25 | °C |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0026 | GroundTransformer | CG-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | TX000284 | GroundTransformer | AL-GND TR 3 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | TX000284 | GroundTransformer | AL-GND TR 3 | Ground Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | TX000284 | GroundTransformer | AL-GND TR 3 | Ground Transformer Patrol Inspection | Cleaned Mechanism Cabinet? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | TX000284 | GroundTransformer | AL-GND TR 3 | Ground Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | TX000284 | GroundTransformer | AL-GND TR 3 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | TX000284 | GroundTransformer | AL-GND TR 3 | Ground Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | TX000284 | GroundTransformer | AL-GND TR 3 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | WithLTC | AK-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 31 | °C |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0008 | GroundTransformer | AL-GND TR 4 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0026 | GroundTransformer | CG-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0026 | GroundTransformer | CG-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0008 | GroundTransformer | AL-GND TR 4 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0008 | GroundTransformer | AL-GND TR 4 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0008 | GroundTransformer | AL-GND TR 4 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0026 | GroundTransformer | CG-GND TR 1 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0026 | GroundTransformer | CG-GND TR 1 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0008 | GroundTransformer | AL-GND TR 4 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0026 | GroundTransformer | CG-GND TR 1 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0026 | GroundTransformer | CG-GND TR 1 | Ground Transformer Patrol Inspection | Winding Temp Max | 25 | °C |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0008 | GroundTransformer | AL-GND TR 4 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0008 | GroundTransformer | AL-GND TR 4 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0008 | GroundTransformer | AL-GND TR 4 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0008 | GroundTransformer | AL-GND TR 4 | Ground Transformer Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0008 | GroundTransformer | AL-GND TR 4 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001049 | BreakerVacuum | AL-1379 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001049 | BreakerVacuum | AL-1379 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0008 | GroundTransformer | AL-GND TR 4 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | PF000004 | PowerFuse | AK-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001049 | BreakerVacuum | AL-1379 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001049 | BreakerVacuum | AL-1379 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0005 | BreakerSF6 | AK-1295 | GCB Readings | Switching Operations | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0005 | BreakerSF6 | AK-1295 | GCB Readings | Operations This Read SF6 | 4 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0005 | BreakerSF6 | AK-1295 | GCB Readings | Operations Counter AL | 633 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0005 | BreakerSF6 | AK-1295 | GCB Readings | Operations Counter AF | 633 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0005 | BreakerSF6 | AK-1295 | GCB Readings | Num Operations Last 9 Months | 12 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0005 | BreakerSF6 | AK-1295 | GCB Readings | 9 Month Operations GCB New | 8 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0005 | BreakerSF6 | AK-1295 | GCB Readings | Amps A Ø | 235.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0005 | BreakerSF6 | AK-1295 | GCB Readings | Amps B Ø | 240.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0005 | BreakerSF6 | AK-1295 | GCB Readings | Amps C Ø | 253.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0005 | BreakerSF6 | AK-1295 | GCB Readings | Maintenance Operations | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0005 | BreakerSF6 | AK-1295 | GCB Readings | General Comments | BC Phase IOC | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Readings | Maintenance Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Readings | Operations Counter AF | 242 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | PF000003 | PowerFuse | AK-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | PF000003 | PowerFuse | AK-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Readings | Operations Counter AL | 242 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Readings | Operations This Read Vac | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .8 | psi |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Readings | Switching Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | Nitrogen cyl missing. | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Readings | LV Winding Temp Max | 0 | °C |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Readings | LV Winding Temp Present | 0 | °C |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Readings | Operations Counter AF | 307 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Readings | Operations Counter AL | 307 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Readings | Operations This Read Vac | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Readings | Switching Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0117 | BreakerVacuum | CG-1436 | VCB Readings | 9 Month Operations | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0117 | BreakerVacuum | CG-1436 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0117 | BreakerVacuum | CG-1436 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0117 | BreakerVacuum | CG-1436 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0117 | BreakerVacuum | CG-1436 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0117 | BreakerVacuum | CG-1436 | VCB Readings | Amps A Ø | 175.0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0117 | BreakerVacuum | CG-1436 | VCB Readings | Amps B Ø | 175.0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0117 | BreakerVacuum | CG-1436 | VCB Readings | Amps C Ø | 175.0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0117 | BreakerVacuum | CG-1436 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0117 | BreakerVacuum | CG-1436 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0117 | BreakerVacuum | CG-1436 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0117 | BreakerVacuum | CG-1436 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0117 | BreakerVacuum | CG-1436 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0117 | BreakerVacuum | CG-1436 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LB1275 | BreakerVacuum | AL-1380 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Readings | Fault Operations Ground | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Readings | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Readings | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000007 | PowerFuse | AL-GND TR 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001187 | BreakerVacuum | AL-1441 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001187 | BreakerVacuum | AL-1441 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001187 | BreakerVacuum | AL-1441 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001187 | BreakerVacuum | AL-1441 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001187 | BreakerVacuum | AL-1441 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001187 | BreakerVacuum | AL-1441 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001187 | BreakerVacuum | AL-1441 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001187 | BreakerVacuum | AL-1441 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001187 | BreakerVacuum | AL-1441 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001187 | BreakerVacuum | AL-1441 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001187 | BreakerVacuum | AL-1441 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001187 | BreakerVacuum | AL-1441 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001187 | BreakerVacuum | AL-1441 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001187 | BreakerVacuum | AL-1441 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001187 | BreakerVacuum | AL-1441 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 100.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 67 | °C |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Readings | Maintenance Operations | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0120 | BreakerVacuum | CG-1439 | VCB Readings | 9 Month Operations | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0120 | BreakerVacuum | CG-1439 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0120 | BreakerVacuum | CG-1439 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0120 | BreakerVacuum | CG-1439 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0120 | BreakerVacuum | CG-1439 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0120 | BreakerVacuum | CG-1439 | VCB Readings | Amps A Ø | 0.0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0120 | BreakerVacuum | CG-1439 | VCB Readings | Amps B Ø | 0.0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0120 | BreakerVacuum | CG-1439 | VCB Readings | Amps C Ø | 0.0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0120 | BreakerVacuum | CG-1439 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | SWG000001 | Switchgear | CG-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001481 | BreakerVacuum | AL-14KV BUS TIE 3-4 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000008 | PowerFuse | AL-GND TR 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000008 | PowerFuse | AL-GND TR 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000008 | PowerFuse | AL-GND TR 2 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000006 | PowerFuse | AL-STA SER NO 3 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001481 | BreakerVacuum | AL-14KV BUS TIE 3-4 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001481 | BreakerVacuum | AL-14KV BUS TIE 3-4 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001481 | BreakerVacuum | AL-14KV BUS TIE 3-4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001481 | BreakerVacuum | AL-14KV BUS TIE 3-4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001481 | BreakerVacuum | AL-14KV BUS TIE 3-4 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001481 | BreakerVacuum | AL-14KV BUS TIE 3-4 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001481 | BreakerVacuum | AL-14KV BUS TIE 3-4 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | SWG000001 | Switchgear | CG-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001481 | BreakerVacuum | AL-14KV BUS TIE 3-4 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001481 | BreakerVacuum | AL-14KV BUS TIE 3-4 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001481 | BreakerVacuum | AL-14KV BUS TIE 3-4 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0120 | BreakerVacuum | CG-1439 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0120 | BreakerVacuum | CG-1439 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0120 | BreakerVacuum | CG-1439 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0120 | BreakerVacuum | CG-1439 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0120 | BreakerVacuum | CG-1439 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0120 | BreakerVacuum | CG-1439 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0120 | BreakerVacuum | CG-1439 | VCB Readings | Fault Operations Ground | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0120 | BreakerVacuum | CG-1439 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0120 | BreakerVacuum | CG-1439 | VCB Readings | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0120 | BreakerVacuum | CG-1439 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0120 | BreakerVacuum | CG-1439 | VCB Readings | General Comments | | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0120 | BreakerVacuum | CG-1439 | VCB Readings | Maintenance Operations | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0120 | BreakerVacuum | CG-1439 | VCB Readings | Operations Counter AF | 149 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0120 | BreakerVacuum | CG-1439 | VCB Readings | Operations Counter AL | 149 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0120 | BreakerVacuum | CG-1439 | VCB Readings | Operations This Read Vac | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0120 | BreakerVacuum | CG-1439 | VCB Readings | Switching Operations | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0120 | BreakerVacuum | CG-1439 | VCB Readings | Unknown Operations | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | SWG000001 | Switchgear | CG-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | SWG000001 | Switchgear | CG-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | SWG000001 | Switchgear | CG-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | SWG000001 | Switchgear | CG-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | SWG000001 | Switchgear | CG-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | SWG000001 | Switchgear | CG-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000006 | PowerFuse | AL-STA SER NO 3 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000006 | PowerFuse | AL-STA SER NO 3 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000012 | PowerFuse | AL-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000012 | PowerFuse | AL-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000012 | PowerFuse | AL-STA SER NO 2 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LB1275 | BreakerVacuum | AL-1380 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LB1275 | BreakerVacuum | AL-1380 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LB1275 | BreakerVacuum | AL-1380 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LB1275 | BreakerVacuum | AL-1380 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LB1275 | BreakerVacuum | AL-1380 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LB1275 | BreakerVacuum | AL-1380 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LB1275 | BreakerVacuum | AL-1380 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LB1275 | BreakerVacuum | AL-1380 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001051 | BreakerVacuum | AL-1373 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001051 | BreakerVacuum | AL-1373 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001051 | BreakerVacuum | AL-1373 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001051 | BreakerVacuum | AL-1373 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001051 | BreakerVacuum | AL-1373 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001051 | BreakerVacuum | AL-1373 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001051 | BreakerVacuum | AL-1373 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001051 | BreakerVacuum | AL-1373 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001051 | BreakerVacuum | AL-1373 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001051 | BreakerVacuum | AL-1373 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001051 | BreakerVacuum | AL-1373 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001051 | BreakerVacuum | AL-1373 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001051 | BreakerVacuum | AL-1373 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001051 | BreakerVacuum | AL-1373 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001051 | BreakerVacuum | AL-1373 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LB1275 | BreakerVacuum | AL-1380 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LB1275 | BreakerVacuum | AL-1380 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LB1275 | BreakerVacuum | AL-1380 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LB1275 | BreakerVacuum | AL-1380 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LB1275 | BreakerVacuum | AL-1380 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LB1275 | BreakerVacuum | AL-1380 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | SWG000001 | Switchgear | CG-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | SWG000001 | Switchgear | CG-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | SWG000001 | Switchgear | CG-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | SWG000001 | Switchgear | CG-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | SWG000001 | Switchgear | CG-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | SWG000001 | Switchgear | CG-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | SWG000001 | Switchgear | CG-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001481 | BreakerVacuum | AL-14KV BUS TIE 3-4 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001481 | BreakerVacuum | AL-14KV BUS TIE 3-4 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001481 | BreakerVacuum | AL-14KV BUS TIE 3-4 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Readings | Unknown Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001481 | BreakerVacuum | AL-14KV BUS TIE 3-4 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | SWG000001 | Switchgear | CG-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | SWG000001 | Switchgear | CG-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | SWG000001 | Switchgear | CG-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | SWG000001 | Switchgear | CG-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000882 | BreakerVacuum | AL-1442 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000882 | BreakerVacuum | AL-1442 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0119 | BreakerVacuum | CG-1438 | VCB Readings | Unknown Operations | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0119 | BreakerVacuum | CG-1438 | VCB Readings | Switching Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000882 | BreakerVacuum | AL-1442 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000882 | BreakerVacuum | AL-1442 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000882 | BreakerVacuum | AL-1442 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000882 | BreakerVacuum | AL-1442 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000882 | BreakerVacuum | AL-1442 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000882 | BreakerVacuum | AL-1442 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000882 | BreakerVacuum | AL-1442 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000882 | BreakerVacuum | AL-1442 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000882 | BreakerVacuum | AL-1442 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0119 | BreakerVacuum | CG-1438 | VCB Readings | Operations This Read Vac | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0119 | BreakerVacuum | CG-1438 | VCB Readings | Operations Counter AL | 198 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0119 | BreakerVacuum | CG-1438 | VCB Readings | Operations Counter AF | 198 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0119 | BreakerVacuum | CG-1438 | VCB Readings | Maintenance Operations | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0119 | BreakerVacuum | CG-1438 | VCB Readings | General Comments | | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0119 | BreakerVacuum | CG-1438 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000013 | PowerFuse | AL-14KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000013 | PowerFuse | AL-14KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000013 | PowerFuse | AL-14KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000883 | BreakerVacuum | AL-1443 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0119 | BreakerVacuum | CG-1438 | VCB Readings | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0119 | BreakerVacuum | CG-1438 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0119 | BreakerVacuum | CG-1438 | VCB Readings | Fault Operations Ground | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000883 | BreakerVacuum | AL-1443 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0119 | BreakerVacuum | CG-1438 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0119 | BreakerVacuum | CG-1438 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0119 | BreakerVacuum | CG-1438 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0119 | BreakerVacuum | CG-1438 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0119 | BreakerVacuum | CG-1438 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000883 | BreakerVacuum | AL-1443 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000883 | BreakerVacuum | AL-1443 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000883 | BreakerVacuum | AL-1443 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000883 | BreakerVacuum | AL-1443 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000883 | BreakerVacuum | AL-1443 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0119 | BreakerVacuum | CG-1438 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0119 | BreakerVacuum | CG-1438 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000883 | BreakerVacuum | AL-1443 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000883 | BreakerVacuum | AL-1443 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000883 | BreakerVacuum | AL-1443 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000883 | BreakerVacuum | AL-1443 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000883 | BreakerVacuum | AL-1443 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000883 | BreakerVacuum | AL-1443 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | PF000036 | PowerFuse | CG-14KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | PF000036 | PowerFuse | CG-14KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | PF000036 | PowerFuse | CG-14KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | PF000037 | PowerFuse | CG-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | PF000037 | PowerFuse | CG-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | PF000037 | PowerFuse | CG-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000104 | Switchgear | AK-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000104 | Switchgear | AK-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000104 | Switchgear | AK-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000104 | Switchgear | AK-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000104 | Switchgear | AK-Swgr Sec 2 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000104 | Switchgear | AK-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000104 | Switchgear | AK-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000104 | Switchgear | AK-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000104 | Switchgear | AK-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000104 | Switchgear | AK-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000104 | Switchgear | AK-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000104 | Switchgear | AK-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000104 | Switchgear | AK-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000104 | Switchgear | AK-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000104 | Switchgear | AK-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000104 | Switchgear | AK-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000104 | Switchgear | AK-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000104 | Switchgear | AK-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001238 | BreakerVacuum | AL-14KV TR 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000104 | Switchgear | AK-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000104 | Switchgear | AK-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001238 | BreakerVacuum | AL-14KV TR 2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001238 | BreakerVacuum | AL-14KV TR 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001238 | BreakerVacuum | AL-14KV TR 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001238 | BreakerVacuum | AL-14KV TR 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001238 | BreakerVacuum | AL-14KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001238 | BreakerVacuum | AL-14KV TR 2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001238 | BreakerVacuum | AL-14KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001238 | BreakerVacuum | AL-14KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001238 | BreakerVacuum | AL-14KV TR 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001238 | BreakerVacuum | AL-14KV TR 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001238 | BreakerVacuum | AL-14KV TR 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001238 | BreakerVacuum | AL-14KV TR 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001238 | BreakerVacuum | AL-14KV TR 2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001238 | BreakerVacuum | AL-14KV TR 2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000882 | BreakerVacuum | AL-1442 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000882 | BreakerVacuum | AL-1442 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000882 | BreakerVacuum | AL-1442 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000882 | BreakerVacuum | AL-1442 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Readings | Amps A Ø | 0.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Readings | Amps B Ø | 0.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Readings | Amps C Ø | 0.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000009 | PowerFuse | AL-GND TR 3 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000009 | PowerFuse | AL-GND TR 3 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000007 | PowerFuse | AL-GND TR 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Readings | Fault Operations Ground | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Readings | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000007 | PowerFuse | AL-GND TR 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Readings | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | WithLTC | AL-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000883 | BreakerVacuum | AL-1443 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000883 | BreakerVacuum | AL-1443 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0119 | BreakerVacuum | CG-1438 | VCB Readings | Amps C Ø | 65.0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0119 | BreakerVacuum | CG-1438 | VCB Readings | Amps B Ø | 65.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000011 | PowerFuse | AL-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000011 | PowerFuse | AL-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0117 | BreakerVacuum | CG-1436 | VCB Readings | Operations Counter AL | 222 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0117 | BreakerVacuum | CG-1436 | VCB Readings | Operations Counter AF | 222 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0117 | BreakerVacuum | CG-1436 | VCB Readings | Maintenance Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000011 | PowerFuse | AL-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000010 | PowerFuse | AL-GND TR 4 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0117 | BreakerVacuum | CG-1436 | VCB Readings | General Comments | | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0117 | BreakerVacuum | CG-1436 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0117 | BreakerVacuum | CG-1436 | VCB Readings | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0117 | BreakerVacuum | CG-1436 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0117 | BreakerVacuum | CG-1436 | VCB Readings | Fault Operations Ground | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Readings | 9 Month Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Readings | Amps A Ø | 0.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Readings | Amps B Ø | 0.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Readings | Amps C Ø | 0.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001050 | BreakerVacuum | AL-1375 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0117 | BreakerVacuum | CG-1436 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0119 | BreakerVacuum | CG-1438 | VCB Readings | Amps A Ø | 65.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000010 | PowerFuse | AL-GND TR 4 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000010 | PowerFuse | AL-GND TR 4 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF000009 | PowerFuse | AL-GND TR 3 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0119 | BreakerVacuum | CG-1438 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0119 | BreakerVacuum | CG-1438 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0119 | BreakerVacuum | CG-1438 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0119 | BreakerVacuum | CG-1438 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0119 | BreakerVacuum | CG-1438 | VCB Readings | 9 Month Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Readings | 9 Month Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001478 | BreakerVacuum | AL-GND TR 3 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Readings | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.2 | psi |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Max | 60 | °C |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Present | 40 | °C |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Max | 60 | °C |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Present | 45 | °C |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Max | 55 | °C |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | WithLTC | AL-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Present | 40 | °C |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | LTCMechanism | AK-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | LTCMechanism | AK-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | LTCMechanism | AK-TRANS 2 | LTC Counter Readings | General Comments | | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | LTCMechanism | AK-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | LTCMechanism | AK-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 180613 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | LTCMechanism | AK-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | LTCMechanism | AK-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | LTCMechanism | AK-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | LTCMechanism | AK-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | LTCMechanism | AK-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | LTCMechanism | AK-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 751 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | LTCMechanism | AK-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | LTCMechanism | AK-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | LTCMechanism | AK-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | LTCMechanism | AK-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000012 | BreakerVacuum | AK-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000012 | BreakerVacuum | AK-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000012 | BreakerVacuum | AK-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000012 | BreakerVacuum | AK-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000012 | BreakerVacuum | AK-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000012 | BreakerVacuum | AK-12KV BUS TIE SEC 2 | VCB Readings | Amps A Ø | 0.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000012 | BreakerVacuum | AK-12KV BUS TIE SEC 2 | VCB Readings | Amps B Ø | 0.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000012 | BreakerVacuum | AK-12KV BUS TIE SEC 2 | VCB Readings | Amps C Ø | 0.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000012 | BreakerVacuum | AK-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000012 | BreakerVacuum | AK-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000012 | BreakerVacuum | AK-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000012 | BreakerVacuum | AK-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0007 | BreakerSF6 | AK-1296 | GCB Readings | Switching Operations | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 35 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 50 | °C |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 35 | °C |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 50 | °C |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 35 | °C |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 50 | °C |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | ANN000019 | Annunciator | CG-Annunciator Panel | Annunciator Patrol Inspection | General Comments | | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | ANN000019 | Annunciator | CG-Annunciator Panel | Annunciator Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | ANN000019 | Annunciator | CG-Annunciator Panel | Annunciator Patrol Inspection | ESOC  Received Alarm Test? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | ANN000019 | Annunciator | CG-Annunciator Panel | Annunciator Patrol Inspection | Control House Alarm Audible? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | ANN000019 | Annunciator | CG-Annunciator Panel | Annunciator Patrol Inspection | All Lights Functioning? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0004 | BreakerSF6 | AK-1293 | GCB Readings | Switching Operations | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0004 | BreakerSF6 | AK-1293 | GCB Readings | Operations This Read SF6 | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0004 | BreakerSF6 | AK-1293 | GCB Readings | Operations Counter AL | 277 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0004 | BreakerSF6 | AK-1293 | GCB Readings | Operations Counter AF | 277 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0004 | BreakerSF6 | AK-1293 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0004 | BreakerSF6 | AK-1293 | GCB Readings | Maintenance Operations | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0004 | BreakerSF6 | AK-1293 | GCB Readings | General Comments | | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0004 | BreakerSF6 | AK-1293 | GCB Patrol Inspection | General Comments | | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0004 | BreakerSF6 | AK-1293 | GCB Readings | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0004 | BreakerSF6 | AK-1293 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0004 | BreakerSF6 | AK-1293 | GCB Readings | Fault Operations | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0004 | BreakerSF6 | AK-1293 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0004 | BreakerSF6 | AK-1293 | GCB Readings | Amps C Ø | 48.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0004 | BreakerSF6 | AK-1293 | GCB Readings | Amps B Ø | 47.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0004 | BreakerSF6 | AK-1293 | GCB Readings | Amps A Ø | 49.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0004 | BreakerSF6 | AK-1293 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1400 | psi |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .9 | psi |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0002 | WithLTC | AK-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Readings | Amps C Ø | 0.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Readings | Amps B Ø | 0.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Readings | Amps A Ø | 0.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000013 | BreakerVacuum | AK-1290 | VCB Readings | Switching Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Readings | Unknown Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Readings | Switching Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Readings | Operations This Read Vac | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Readings | Operations Counter AL | 332 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Readings | Operations Counter AF | 332 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Readings | Maintenance Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Readings | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Readings | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Readings | 9 Month Operations | 7 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Readings | Fault Operations Ground | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Readings | Amps A Ø | 49.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Readings | Amps B Ø | 67.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Readings | Amps C Ø | 59.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Readings | Amps C Ø | 0.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Readings | Amps B Ø | 0.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Readings | Amps A Ø | 0.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000016 | BreakerVacuum | AK-1291 | VCB Readings | 9 Month Operations | 13 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000016 | BreakerVacuum | AK-1291 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000016 | BreakerVacuum | AK-1291 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000016 | BreakerVacuum | AK-1291 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000016 | BreakerVacuum | AK-1291 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000016 | BreakerVacuum | AK-1291 | VCB Readings | Amps A Ø | 187.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000016 | BreakerVacuum | AK-1291 | VCB Readings | Amps B Ø | 202.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000016 | BreakerVacuum | AK-1291 | VCB Readings | Amps C Ø | 206.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000016 | BreakerVacuum | AK-1291 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000016 | BreakerVacuum | AK-1291 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000016 | BreakerVacuum | AK-1291 | VCB Readings | Fault Adjusted Amps B Phase V | 67.08 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000016 | BreakerVacuum | AK-1291 | VCB Readings | Fault Adjusted Amps C Phase V | 55.90 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000012 | BreakerVacuum | AK-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000012 | BreakerVacuum | AK-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000012 | BreakerVacuum | AK-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000012 | BreakerVacuum | AK-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000012 | BreakerVacuum | AK-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000012 | BreakerVacuum | AK-12KV BUS TIE SEC 2 | VCB Readings | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000012 | BreakerVacuum | AK-12KV BUS TIE SEC 2 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000012 | BreakerVacuum | AK-12KV BUS TIE SEC 2 | VCB Readings | General Comments | | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000012 | BreakerVacuum | AK-12KV BUS TIE SEC 2 | VCB Readings | Maintenance Operations | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000012 | BreakerVacuum | AK-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AF | 156 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000012 | BreakerVacuum | AK-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AL | 156 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000012 | BreakerVacuum | AK-12KV BUS TIE SEC 2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000012 | BreakerVacuum | AK-12KV BUS TIE SEC 2 | VCB Readings | Switching Operations | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000013 | BreakerVacuum | AK-1290 | VCB Readings | 9 Month Operations | 10 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000013 | BreakerVacuum | AK-1290 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000013 | BreakerVacuum | AK-1290 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000013 | BreakerVacuum | AK-1290 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000013 | BreakerVacuum | AK-1290 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Readings | 9 Month Operations | 1 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000013 | BreakerVacuum | AK-1290 | VCB Readings | Amps A Ø | 125.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000013 | BreakerVacuum | AK-1290 | VCB Readings | Amps B Ø | 94.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000013 | BreakerVacuum | AK-1290 | VCB Readings | Amps C Ø | 89.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000013 | BreakerVacuum | AK-1290 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000013 | BreakerVacuum | AK-1290 | VCB Readings | Fault Adjusted Amps A Phase V | 44.72 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000013 | BreakerVacuum | AK-1290 | VCB Readings | Fault Adjusted Amps B Phase V | 44.72 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000013 | BreakerVacuum | AK-1290 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LTCC000472 | LTCControl | AL-TRANS 3 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LTCC000472 | LTCControl | AL-TRANS 3 | LTC Control Insp | General Comments | | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000013 | BreakerVacuum | AK-1290 | VCB Readings | Fault Operations A Ø | 4 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000013 | BreakerVacuum | AK-1290 | VCB Readings | Fault Operations B Ø | 4 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000013 | BreakerVacuum | AK-1290 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000013 | BreakerVacuum | AK-1290 | VCB Readings | Fault Operations Ground | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LTCC000472 | LTCControl | AL-TRANS 3 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000013 | BreakerVacuum | AK-1290 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000013 | BreakerVacuum | AK-1290 | VCB Readings | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000013 | BreakerVacuum | AK-1290 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LTCC000471 | LTCControl | AL-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LTCC000471 | LTCControl | AL-TRANS 2 | LTC Control Insp | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LTCC000471 | LTCControl | AL-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000013 | BreakerVacuum | AK-1290 | VCB Readings | General Comments | AB Phase IOC / Storms in Area | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000013 | BreakerVacuum | AK-1290 | VCB Readings | Maintenance Operations | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000013 | BreakerVacuum | AK-1290 | VCB Readings | Operations Counter AF | 125 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000013 | BreakerVacuum | AK-1290 | VCB Readings | Operations Counter AL | 125 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000013 | BreakerVacuum | AK-1290 | VCB Readings | Operations This Read Vac | 8 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Readings | Switching Operations | 1 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Readings | Operations This Read Vac | 1 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Readings | Operations Counter AL | 388 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Readings | Operations Counter AF | 388 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Readings | Maintenance Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Readings | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Readings | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Readings | Fault Operations Ground | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001521 | BreakerVacuum | AL-14KV BUS TIE 2-3 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0123 | BreakerVacuum | CG-14KV GND TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0123 | BreakerVacuum | CG-14KV GND TR 1 | VCB Readings | Switching Operations | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0123 | BreakerVacuum | CG-14KV GND TR 1 | VCB Readings | Unknown Operations | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0122 | BreakerVacuum | CG-14KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000082 | BreakerSF6 | AK-1294 | GCB Readings | 9 Month Operations GCB New | 1 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000082 | BreakerSF6 | AK-1294 | GCB Readings | Amps A Ø | 31.0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | LTCMechanism | CG-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | LTCMechanism | CG-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | LTCMechanism | CG-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 120 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | LTCMechanism | CG-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | LTCMechanism | CG-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | LTCMechanism | CG-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | LTCMechanism | CG-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | LTCMechanism | CG-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 105685 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | LTCMechanism | CG-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 105685 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | LTCMechanism | CG-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | LTCMechanism | CG-TRANS 1 | LTC Counter Readings | General Comments | | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | LTCMechanism | CG-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | LTCMechanism | CG-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | LTCMechanism | AL-TRANS 3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | LTCMechanism | AL-TRANS 3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | LTCMechanism | AL-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | LTCMechanism | AL-TRANS 3 | LTC Counter Readings | LTC Operations Since Last Insp | 170 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | LTCMechanism | AL-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | LTCMechanism | AL-TRANS 3 | LTC Counter Readings | LTC Min Tap Position | 3L | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | LTCMechanism | AL-TRANS 3 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000082 | BreakerSF6 | AK-1294 | GCB Readings | Amps B Ø | 32.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000082 | BreakerSF6 | AK-1294 | GCB Readings | Amps C Ø | 21.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000082 | BreakerSF6 | AK-1294 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000082 | BreakerSF6 | AK-1294 | GCB Readings | Fault Operations | 7 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000082 | BreakerSF6 | AK-1294 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000082 | BreakerSF6 | AK-1294 | GCB Readings | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000082 | BreakerSF6 | AK-1294 | GCB Patrol Inspection | General Comments | | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000082 | BreakerSF6 | AK-1294 | GCB Readings | General Comments | B Phase TOC | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000082 | BreakerSF6 | AK-1294 | GCB Readings | Maintenance Operations | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000082 | BreakerSF6 | AK-1294 | GCB Readings | Num Operations Last 9 Months | 8 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000082 | BreakerSF6 | AK-1294 | GCB Readings | Operations Counter AF | 1353 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0122 | BreakerVacuum | CG-14KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0122 | BreakerVacuum | CG-14KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0122 | BreakerVacuum | CG-14KV TR 1 | VCB Readings | Amps C Ø | 530.0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0122 | BreakerVacuum | CG-14KV TR 1 | VCB Readings | Amps B Ø | 530.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | LTCMechanism | AL-TRANS 3 | LTC Counter Readings | LTC Current Tap Position | 1R | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | LTCMechanism | AL-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | LTCMechanism | AL-TRANS 3 | LTC Counter Readings | LTC As Left Counter | 21168 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | LTCMechanism | AL-TRANS 3 | LTC Counter Readings | LTC As Found Counter | 21168 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | LTCMechanism | AL-TRANS 3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | LTCMechanism | AL-TRANS 3 | LTC Counter Readings | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | LTCMechanism | AL-TRANS 3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0010 | LTCMechanism | AL-TRANS 3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0122 | BreakerVacuum | CG-14KV TR 1 | VCB Readings | Amps A Ø | 530.0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0122 | BreakerVacuum | CG-14KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0122 | BreakerVacuum | CG-14KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0122 | BreakerVacuum | CG-14KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000082 | BreakerSF6 | AK-1294 | GCB Readings | Operations Counter AL | 1353 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000082 | BreakerSF6 | AK-1294 | GCB Readings | Operations This Read SF6 | 7 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000082 | BreakerSF6 | AK-1294 | GCB Readings | Switching Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | LTCMechanism | AL-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | LTCMechanism | AL-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | LTCMechanism | AL-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | LTCMechanism | AL-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0003 | LTCMechanism | AL-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0001 | BreakerSF6 | AK-1289 | GCB Readings | 9 Month Operations GCB New | 1 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001291 | BreakerVacuum | AL-14KV TR 3 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001291 | BreakerVacuum | AL-14KV TR 3 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001291 | BreakerVacuum | AL-14KV TR 3 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001291 | BreakerVacuum | AL-14KV TR 3 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001291 | BreakerVacuum | AL-14KV TR 3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001291 | BreakerVacuum | AL-14KV TR 3 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001291 | BreakerVacuum | AL-14KV TR 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001291 | BreakerVacuum | AL-14KV TR 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001291 | BreakerVacuum | AL-14KV TR 3 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001291 | BreakerVacuum | AL-14KV TR 3 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000020 | Switchgear | AK-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000020 | Switchgear | AK-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000020 | Switchgear | AK-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000020 | Switchgear | AK-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000020 | Switchgear | AK-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000020 | Switchgear | AK-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000020 | Switchgear | AK-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000020 | Switchgear | AK-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000020 | Switchgear | AK-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000020 | Switchgear | AK-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000020 | Switchgear | AK-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000020 | Switchgear | AK-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000020 | Switchgear | AK-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000020 | Switchgear | AK-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000020 | Switchgear | AK-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000020 | Switchgear | AK-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000020 | Switchgear | AK-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000020 | Switchgear | AK-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | SWG000020 | Switchgear | AK-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0122 | BreakerVacuum | CG-14KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0122 | BreakerVacuum | CG-14KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0122 | BreakerVacuum | CG-14KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0122 | BreakerVacuum | CG-14KV TR 1 | VCB Readings | Operations Counter AL | 237 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0122 | BreakerVacuum | CG-14KV TR 1 | VCB Readings | Operations Counter AF | 237 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0122 | BreakerVacuum | CG-14KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0122 | BreakerVacuum | CG-14KV TR 1 | VCB Readings | General Comments | | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0122 | BreakerVacuum | CG-14KV TR 1 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0122 | BreakerVacuum | CG-14KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0122 | BreakerVacuum | CG-14KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0122 | BreakerVacuum | CG-14KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0122 | BreakerVacuum | CG-14KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0122 | BreakerVacuum | CG-14KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0122 | BreakerVacuum | CG-14KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Readings | Switching Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Readings | Operations This Read Vac | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Readings | Operations Counter AL | 367 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Readings | Operations Counter AF | 367 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0256 | GroundTransformer | AL-GND TR 2 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0256 | GroundTransformer | AL-GND TR 2 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0256 | GroundTransformer | AL-GND TR 2 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0256 | GroundTransformer | AL-GND TR 2 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | .2 | psi |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0256 | GroundTransformer | AL-GND TR 2 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0256 | GroundTransformer | AL-GND TR 2 | Ground Transformer Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0256 | GroundTransformer | AL-GND TR 2 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0256 | GroundTransformer | AL-GND TR 2 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | LTCMechanism | CG-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | LTCMechanism | CG-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0122 | BreakerVacuum | CG-14KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0123 | BreakerVacuum | CG-14KV GND TR 1 | VCB Readings | 9 Month Operations | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0123 | BreakerVacuum | CG-14KV GND TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0123 | BreakerVacuum | CG-14KV GND TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0123 | BreakerVacuum | CG-14KV GND TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0123 | BreakerVacuum | CG-14KV GND TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0123 | BreakerVacuum | CG-14KV GND TR 1 | VCB Readings | Amps A Ø | 0.0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0123 | BreakerVacuum | CG-14KV GND TR 1 | VCB Readings | Amps B Ø | 0.0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0123 | BreakerVacuum | CG-14KV GND TR 1 | VCB Readings | Amps C Ø | 0.0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0123 | BreakerVacuum | CG-14KV GND TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0123 | BreakerVacuum | CG-14KV GND TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0123 | BreakerVacuum | CG-14KV GND TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0123 | BreakerVacuum | CG-14KV GND TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0123 | BreakerVacuum | CG-14KV GND TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0123 | BreakerVacuum | CG-14KV GND TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0123 | BreakerVacuum | CG-14KV GND TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0123 | BreakerVacuum | CG-14KV GND TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0123 | BreakerVacuum | CG-14KV GND TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0123 | BreakerVacuum | CG-14KV GND TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0123 | BreakerVacuum | CG-14KV GND TR 1 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0123 | BreakerVacuum | CG-14KV GND TR 1 | VCB Readings | General Comments | | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0123 | BreakerVacuum | CG-14KV GND TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0123 | BreakerVacuum | CG-14KV GND TR 1 | VCB Readings | Operations Counter AF | 150 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0123 | BreakerVacuum | CG-14KV GND TR 1 | VCB Readings | Operations Counter AL | 150 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB1323 | BreakerVacuum | AK-12KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB1323 | BreakerVacuum | AK-12KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB1323 | BreakerVacuum | AK-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB1323 | BreakerVacuum | AK-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB1323 | BreakerVacuum | AK-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB1323 | BreakerVacuum | AK-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | FE000627 | Fence | CG-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | FE000627 | Fence | CG-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | FE000627 | Fence | CG-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | FE000627 | Fence | CG-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | FE000627 | Fence | CG-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | FE000627 | Fence | CG-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000567 | BreakerVacuum | AL-1444 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000567 | BreakerVacuum | AL-1444 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000567 | BreakerVacuum | AL-1444 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000567 | BreakerVacuum | AL-1444 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000567 | BreakerVacuum | AL-1444 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000567 | BreakerVacuum | AL-1444 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000567 | BreakerVacuum | AL-1444 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000567 | BreakerVacuum | AL-1444 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000567 | BreakerVacuum | AL-1444 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000567 | BreakerVacuum | AL-1444 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000567 | BreakerVacuum | AL-1444 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000567 | BreakerVacuum | AL-1444 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000567 | BreakerVacuum | AL-1444 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000567 | BreakerVacuum | AL-1444 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK000567 | BreakerVacuum | AL-1444 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0007 | BreakerSF6 | AK-1296 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0007 | BreakerSF6 | AK-1296 | GCB Readings | Amps A Ø | 145.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0007 | BreakerSF6 | AK-1296 | GCB Readings | Amps B Ø | 151.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB1323 | BreakerVacuum | AK-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB1323 | BreakerVacuum | AK-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB1323 | BreakerVacuum | AK-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB1323 | BreakerVacuum | AK-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0007 | BreakerSF6 | AK-1296 | GCB Readings | Amps C Ø | 137.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0007 | BreakerSF6 | AK-1296 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0007 | BreakerSF6 | AK-1296 | GCB Readings | Fault Operations | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0007 | BreakerSF6 | AK-1296 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0007 | BreakerSF6 | AK-1296 | GCB Readings | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB1323 | BreakerVacuum | AK-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB1323 | BreakerVacuum | AK-12KV TR 1 | VCB Readings | Amps C Ø | 584.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB1323 | BreakerVacuum | AK-12KV TR 1 | VCB Readings | Amps B Ø | 590.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB1323 | BreakerVacuum | AK-12KV TR 1 | VCB Readings | Amps A Ø | 615.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB1323 | BreakerVacuum | AK-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB1323 | BreakerVacuum | AK-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB1323 | BreakerVacuum | AK-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB1323 | BreakerVacuum | AK-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB1323 | BreakerVacuum | AK-12KV TR 1 | VCB Readings | 9 Month Operations | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0007 | BreakerSF6 | AK-1296 | GCB Patrol Inspection | General Comments | | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0007 | BreakerSF6 | AK-1296 | GCB Readings | General Comments | | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0007 | BreakerSF6 | AK-1296 | GCB Readings | Maintenance Operations | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0007 | BreakerSF6 | AK-1296 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0007 | BreakerSF6 | AK-1296 | GCB Readings | Operations Counter AF | 944 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0007 | BreakerSF6 | AK-1296 | GCB Readings | Operations Counter AL | 944 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0007 | BreakerSF6 | AK-1296 | GCB Readings | Operations This Read SF6 | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.5 | psi |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Patrol Inspection | General Comments | Trans in vacuum needs nitro. | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Readings | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001291 | BreakerVacuum | AL-14KV TR 3 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001291 | BreakerVacuum | AL-14KV TR 3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001291 | BreakerVacuum | AL-14KV TR 3 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001291 | BreakerVacuum | AL-14KV TR 3 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001291 | BreakerVacuum | AL-14KV TR 3 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0122 | BreakerVacuum | CG-14KV TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0122 | BreakerVacuum | CG-14KV TR 1 | VCB Readings | 9 Month Operations | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0001 | BreakerSF6 | AK-1289 | GCB Readings | Amps A Ø | 154.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0001 | BreakerSF6 | AK-1289 | GCB Readings | Amps B Ø | 138.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0001 | BreakerSF6 | AK-1289 | GCB Readings | Amps C Ø | 140.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0001 | BreakerSF6 | AK-1289 | GCB Readings | Fault Operations | 2 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0001 | BreakerSF6 | AK-1289 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0001 | BreakerSF6 | AK-1289 | GCB Readings | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0001 | BreakerSF6 | AK-1289 | GCB Patrol Inspection | General Comments | | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0001 | BreakerSF6 | AK-1289 | GCB Readings | General Comments | AB Phase IOC | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0001 | BreakerSF6 | AK-1289 | GCB Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0001 | BreakerSF6 | AK-1289 | GCB Readings | Maintenance Operations | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0001 | BreakerSF6 | AK-1289 | GCB Readings | Num Operations Last 9 Months | 3 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0001 | BreakerSF6 | AK-1289 | GCB Readings | Operations Counter AF | 725 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0001 | BreakerSF6 | AK-1289 | GCB Readings | Operations Counter AL | 725 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0001 | BreakerSF6 | AK-1289 | GCB Readings | Operations This Read SF6 | 2 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB0001 | BreakerSF6 | AK-1289 | GCB Readings | Switching Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Readings | Maintenance Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Readings | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Readings | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Readings | Fault Operations Ground | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Readings | Amps C Ø | 128.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Readings | Amps B Ø | 142.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Readings | Amps A Ø | 137.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001290 | BreakerVacuum | AL-14KV TR 4 | VCB Readings | 9 Month Operations | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | FE000627 | Fence | CG-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | FE000627 | Fence | CG-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | FE000627 | Fence | CG-Fence | Fence Patrol Inspection | General Comments | | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | FE000627 | Fence | CG-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Readings | X2 Winding Temp Present | 45 | °C |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Readings | X2 Winding Temp Max | 45 | °C |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | WithLTC | AL-TRANS 4 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | FE000627 | Fence | CG-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | FE000627 | Fence | CG-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | FE000627 | Fence | CG-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | FE000627 | Fence | CG-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | FE000627 | Fence | CG-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | FE000627 | Fence | CG-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB1323 | BreakerVacuum | AK-12KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB1323 | BreakerVacuum | AK-12KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB1323 | BreakerVacuum | AK-12KV TR 1 | VCB Readings | Operations Counter AL | 283 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB1323 | BreakerVacuum | AK-12KV TR 1 | VCB Readings | Operations Counter AF | 283 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB1323 | BreakerVacuum | AK-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LB1323 | BreakerVacuum | AK-12KV TR 1 | VCB Readings | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0118 | BreakerVacuum | CG-1437 | VCB Readings | Fault Operations C Ø | 1 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0118 | BreakerVacuum | CG-1437 | VCB Readings | Fault Operations B Ø | 1 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0118 | BreakerVacuum | CG-1437 | VCB Readings | Fault Operations A Ø | 1 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000018 | BreakerVacuum | AK-12KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000018 | BreakerVacuum | AK-12KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000018 | BreakerVacuum | AK-12KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000018 | BreakerVacuum | AK-12KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000018 | BreakerVacuum | AK-12KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000018 | BreakerVacuum | AK-12KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000018 | BreakerVacuum | AK-12KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000018 | BreakerVacuum | AK-12KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000018 | BreakerVacuum | AK-12KV TR 2 | VCB Readings | General Comments | | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000018 | BreakerVacuum | AK-12KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000018 | BreakerVacuum | AK-12KV TR 2 | VCB Readings | Operations Counter AF | 106 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000018 | BreakerVacuum | AK-12KV TR 2 | VCB Readings | Operations Counter AL | 106 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000018 | BreakerVacuum | AK-12KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000018 | BreakerVacuum | AK-12KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001388 | BreakerVacuum | AL-1377 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001388 | BreakerVacuum | AL-1377 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001388 | BreakerVacuum | AL-1377 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001388 | BreakerVacuum | AL-1377 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001388 | BreakerVacuum | AL-1377 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001388 | BreakerVacuum | AL-1377 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0118 | BreakerVacuum | CG-1437 | VCB Readings | Fault Adjusted Amps C Phase V | 14.70 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0118 | BreakerVacuum | CG-1437 | VCB Readings | Fault Adjusted Amps B Phase V | 14.70 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0118 | BreakerVacuum | CG-1437 | VCB Readings | Fault Adjusted Amps A Phase V | 14.70 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0118 | BreakerVacuum | CG-1437 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0118 | BreakerVacuum | CG-1437 | VCB Readings | Amps C Ø | 265.0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0116 | BreakerVacuum | CG-1435 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0116 | BreakerVacuum | CG-1435 | VCB Readings | Fault Operations Ground | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0116 | BreakerVacuum | CG-1435 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0116 | BreakerVacuum | CG-1435 | VCB Readings | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0116 | BreakerVacuum | CG-1435 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0116 | BreakerVacuum | CG-1435 | VCB Readings | General Comments | | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0116 | BreakerVacuum | CG-1435 | VCB Readings | Maintenance Operations | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0116 | BreakerVacuum | CG-1435 | VCB Readings | Operations Counter AF | 203 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0116 | BreakerVacuum | CG-1435 | VCB Readings | Operations Counter AL | 203 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0116 | BreakerVacuum | CG-1435 | VCB Readings | Operations This Read Vac | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0116 | BreakerVacuum | CG-1435 | VCB Readings | Switching Operations | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0116 | BreakerVacuum | CG-1435 | VCB Readings | Unknown Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Readings | Operations Counter AL | 384 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Readings | Operations This Read Vac | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Readings | Switching Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0118 | BreakerVacuum | CG-1437 | VCB Readings | Amps B Ø | 265.0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0118 | BreakerVacuum | CG-1437 | VCB Readings | Amps A Ø | 265.0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0118 | BreakerVacuum | CG-1437 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0118 | BreakerVacuum | CG-1437 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0118 | BreakerVacuum | CG-1437 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0118 | BreakerVacuum | CG-1437 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF001205 | PowerFuse | AL-14KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF001205 | PowerFuse | AL-14KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF001205 | PowerFuse | AL-14KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Readings | Fault Operations Ground | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Readings | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF001206 | PowerFuse | AL-14KV TR 3 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Readings | Switching Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1374 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Readings | Operations Counter AF | 383 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Readings | Maintenance Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001244 | BreakerVacuum | AL-1374 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001244 | BreakerVacuum | AL-1374 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001244 | BreakerVacuum | AL-1374 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001244 | BreakerVacuum | AL-1374 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001244 | BreakerVacuum | AL-1374 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Readings | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Readings | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Readings | Fault Operations Ground | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Readings | Amps C Ø | 0.0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0118 | BreakerVacuum | CG-1437 | VCB Readings | Unknown Operations | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0118 | BreakerVacuum | CG-1437 | VCB Readings | Switching Operations | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0118 | BreakerVacuum | CG-1437 | VCB Readings | Operations This Read Vac | 3 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Readings | Amps B Ø | 0.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Readings | Amps A Ø | 0.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Readings | 9 Month Operations | 1 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0116 | BreakerVacuum | CG-1435 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0116 | BreakerVacuum | CG-1435 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0118 | BreakerVacuum | CG-1437 | VCB Readings | Operations Counter AL | 184 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0118 | BreakerVacuum | CG-1437 | VCB Readings | Operations Counter AF | 184 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0118 | BreakerVacuum | CG-1437 | VCB Readings | Maintenance Operations | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0118 | BreakerVacuum | CG-1437 | VCB Readings | General Comments | | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0118 | BreakerVacuum | CG-1437 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0118 | BreakerVacuum | CG-1437 | VCB Readings | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0118 | BreakerVacuum | CG-1437 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0118 | BreakerVacuum | CG-1437 | VCB Readings | Fault Operations Ground | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | LTCMechanism | AL-TRANS 4 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | LTCMechanism | AL-TRANS 4 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | LTCMechanism | AL-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | LTCMechanism | AL-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | LTCMechanism | AL-TRANS 4 | LTC Counter Readings | LTC Operations Since Last Insp | 79 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Readings | 9 Month Operations | 1 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Readings | Amps A Ø | 0.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Readings | Amps B Ø | 0.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Readings | Amps C Ø | 0.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LTCC000531 | LTCControl | CG-TRANS 1 | LTC Control Insp | General Comments | ok | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LTCC000531 | LTCControl | CG-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Readings | Maintenance Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Readings | Operations Counter AF | 511 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Readings | Operations Counter AL | 511 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Readings | Operations This Read Vac | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Readings | Switching Operations | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | ST000615 | Structure | CG-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | ST000615 | Structure | CG-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | ST000615 | Structure | CG-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | LTCMechanism | AL-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | CH000127 | ControlHouse | CG-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | CH000127 | ControlHouse | CG-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | ST000615 | Structure | CG-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | ST000615 | Structure | CG-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | ST000615 | Structure | CG-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | ST000615 | Structure | CG-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | ST000615 | Structure | CG-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | ST000615 | Structure | CG-Structure | Structure Patrol Inspection | General Comments | | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | ST000615 | Structure | CG-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | ST000615 | Structure | CG-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | ST000615 | Structure | CG-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | ST000615 | Structure | CG-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | ST000615 | Structure | CG-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | ST000615 | Structure | CG-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | ST000615 | Structure | CG-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | ST000615 | Structure | CG-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | ST000615 | Structure | CG-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | ST000615 | Structure | CG-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | ST000615 | Structure | CG-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | ST000615 | Structure | CG-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | ST000615 | Structure | CG-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LTCC000494 | LTCControl | AL-TRANS 4 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LTCC000494 | LTCControl | AL-TRANS 4 | LTC Control Insp | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LTCC000494 | LTCControl | AL-TRANS 4 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | LTCMechanism | AL-TRANS 4 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | LTCMechanism | AL-TRANS 4 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | LTCMechanism | AL-TRANS 4 | LTC Counter Readings | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | LTCMechanism | AL-TRANS 4 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | LTCMechanism | AL-TRANS 4 | LTC Counter Readings | LTC As Found Counter | 81198 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | LTCMechanism | AL-TRANS 4 | LTC Counter Readings | LTC As Left Counter | 81198 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | LTCMechanism | AL-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | LTCMechanism | AL-TRANS 4 | LTC Counter Readings | LTC Current Tap Position | 6 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | LTCMechanism | AL-TRANS 4 | LTC Counter Readings | LTC Max Tap Position | 8 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | LT0009 | LTCMechanism | AL-TRANS 4 | LTC Counter Readings | LTC Min Tap Position | 6 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | CH000127 | ControlHouse | CG-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | CH000127 | ControlHouse | CG-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | CH000127 | ControlHouse | CG-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | CH000127 | ControlHouse | CG-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | n | If Bkr is Closed |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | CH000127 | ControlHouse | CG-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | CH000127 | ControlHouse | CG-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | CH000127 | ControlHouse | CG-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | CH000127 | ControlHouse | CG-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | CH000127 | ControlHouse | CG-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | CH000127 | ControlHouse | CG-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | CH000127 | ControlHouse | CG-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | CH000127 | ControlHouse | CG-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Readings | Operations Counter AL | 366 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Readings | Operations Counter AF | 366 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Readings | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | CH000130 | ControlHouse | AL-Control House 1 | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | CH000130 | ControlHouse | AL-Control House 1 | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | CH000130 | ControlHouse | AL-Control House 1 | Control House Patrol Inspection | Trash Emptied? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | CH000130 | ControlHouse | AL-Control House 1 | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | CH000130 | ControlHouse | AL-Control House 1 | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | CH000130 | ControlHouse | AL-Control House 1 | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | CH000130 | ControlHouse | AL-Control House 1 | Control House Patrol Inspection | Panel Lights OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | CH000130 | ControlHouse | AL-Control House 1 | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | CH000130 | ControlHouse | AL-Control House 1 | Control House Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | CH000130 | ControlHouse | AL-Control House 1 | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | CH000130 | ControlHouse | AL-Control House 1 | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | CH000130 | ControlHouse | AL-Control House 1 | Control House Patrol Inspection | Floor Swept? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | CH000130 | ControlHouse | AL-Control House 1 | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | CH000130 | ControlHouse | AL-Control House 1 | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | CH000130 | ControlHouse | AL-Control House 1 | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | CH000130 | ControlHouse | AL-Control House 1 | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | CH000130 | ControlHouse | AL-Control House 1 | Control House Patrol Inspection | Door Alarms OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | CH000130 | ControlHouse | AL-Control House 1 | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | CH000130 | ControlHouse | AL-Control House 1 | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF001206 | PowerFuse | AL-14KV TR 3 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF001206 | PowerFuse | AL-14KV TR 3 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | CH000130 | ControlHouse | AL-Control House 1 | Control House Patrol Inspection | Broom on Site? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | CH000130 | ControlHouse | AL-Control House 1 | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | CH000130 | ControlHouse | AL-Control House 1 | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | CH000127 | ControlHouse | CG-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | CH000127 | ControlHouse | CG-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | CH000127 | ControlHouse | CG-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | CH000127 | ControlHouse | CG-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0118 | BreakerVacuum | CG-1437 | VCB Readings | 9 Month Operations | 3 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | CH000127 | ControlHouse | CG-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | CH000127 | ControlHouse | CG-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | CH000127 | ControlHouse | CG-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF001207 | PowerFuse | AL-14KV TR 4 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF001207 | PowerFuse | AL-14KV TR 4 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001388 | BreakerVacuum | AL-1377 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001388 | BreakerVacuum | AL-1377 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001388 | BreakerVacuum | AL-1377 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001388 | BreakerVacuum | AL-1377 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | PF001207 | PowerFuse | AL-14KV TR 4 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001388 | BreakerVacuum | AL-1377 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001388 | BreakerVacuum | AL-1377 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | CH000127 | ControlHouse | CG-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | CH000127 | ControlHouse | CG-Control House | Control House Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Readings | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001245 | BreakerVacuum | AL-1376 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Readings | 9 Month Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001295 | BreakerVacuum | AL-14KV BUS TIE 1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Readings | Operations Counter AF | 384 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | LTCMechanism | AK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000017 | BreakerVacuum | AK-1292 | VCB Readings | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000017 | BreakerVacuum | AK-1292 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000017 | BreakerVacuum | AK-1292 | VCB Readings | Fault Operations Ground | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000017 | BreakerVacuum | AK-1292 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001244 | BreakerVacuum | AL-1374 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | LTCMechanism | AK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | LTCMechanism | AK-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001244 | BreakerVacuum | AL-1374 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | LTCMechanism | AK-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 30 | °C |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 55 | °C |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 40 | °C |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 50 | °C |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000017 | BreakerVacuum | AK-1292 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000017 | BreakerVacuum | AK-1292 | VCB Readings | General Comments | | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000017 | BreakerVacuum | AK-1292 | VCB Readings | Maintenance Operations | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000017 | BreakerVacuum | AK-1292 | VCB Readings | Operations Counter AF | 183 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000017 | BreakerVacuum | AK-1292 | VCB Readings | Operations Counter AL | 183 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000017 | BreakerVacuum | AK-1292 | VCB Readings | Operations This Read Vac | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000017 | BreakerVacuum | AK-1292 | VCB Readings | Switching Operations | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000018 | BreakerVacuum | AK-12KV TR 2 | VCB Readings | 9 Month Operations | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000018 | BreakerVacuum | AK-12KV TR 2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000018 | BreakerVacuum | AK-12KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000018 | BreakerVacuum | AK-12KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000018 | BreakerVacuum | AK-12KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001389 | BreakerVacuum | AL-1440 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001389 | BreakerVacuum | AL-1440 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001389 | BreakerVacuum | AL-1440 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001389 | BreakerVacuum | AL-1440 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001389 | BreakerVacuum | AL-1440 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001389 | BreakerVacuum | AL-1440 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001389 | BreakerVacuum | AL-1440 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001389 | BreakerVacuum | AL-1440 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001389 | BreakerVacuum | AL-1440 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001389 | BreakerVacuum | AL-1440 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001389 | BreakerVacuum | AL-1440 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000017 | BreakerVacuum | AK-1292 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001389 | BreakerVacuum | AL-1440 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001389 | BreakerVacuum | AL-1440 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001389 | BreakerVacuum | AL-1440 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001389 | BreakerVacuum | AL-1440 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000018 | BreakerVacuum | AK-12KV TR 2 | VCB Readings | Amps A Ø | 418.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | LTCMechanism | AK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | LTCMechanism | AK-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | LTCMechanism | AK-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 136453 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | LTCMechanism | AK-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 136453 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | LTCMechanism | AK-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Readings | Fault Operations Ground | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | LTCMechanism | AK-TRANS 1 | LTC Counter Readings | General Comments | | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | LTCMechanism | AK-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | LTCMechanism | AK-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | LTCMechanism | AK-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | LTCMechanism | AK-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 607 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | LT0001 | LTCMechanism | AK-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 55 | °C |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Readings | Follow-up Action Required? | n | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Readings | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Readings | Maintenance Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001294 | BreakerVacuum | AL-1372 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 30 | °C |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 20.00 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 55 | °C |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.5 | psi |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Readings | H2 Winding Temp Present | 55 | °C |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Readings | H2 Winding Temp Max | 30 | °C |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | Needs nitrogen. | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000016 | BreakerVacuum | AK-1291 | VCB Readings | Fault Operations C Ø | 5 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000018 | BreakerVacuum | AK-12KV TR 2 | VCB Readings | Amps B Ø | 400.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000018 | BreakerVacuum | AK-12KV TR 2 | VCB Readings | Amps C Ø | 385.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000018 | BreakerVacuum | AK-12KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000018 | BreakerVacuum | AK-12KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001388 | BreakerVacuum | AL-1377 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001388 | BreakerVacuum | AL-1377 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001388 | BreakerVacuum | AL-1377 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000018 | BreakerVacuum | AK-12KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000017 | BreakerVacuum | AK-1292 | VCB Readings | Amps A Ø | 112.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000017 | BreakerVacuum | AK-1292 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000017 | BreakerVacuum | AK-1292 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000017 | BreakerVacuum | AK-1292 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000017 | BreakerVacuum | AK-1292 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0116 | BreakerVacuum | CG-1435 | VCB Readings | 9 Month Operations | 2 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000016 | BreakerVacuum | AK-1291 | VCB Readings | Fault Operations Ground | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000016 | BreakerVacuum | AK-1291 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000016 | BreakerVacuum | AK-1291 | VCB Readings | Follow-up Action Required? | n | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0116 | BreakerVacuum | CG-1435 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0116 | BreakerVacuum | CG-1435 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0116 | BreakerVacuum | CG-1435 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0116 | BreakerVacuum | CG-1435 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0116 | BreakerVacuum | CG-1435 | VCB Readings | Amps A Ø | 65.0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0116 | BreakerVacuum | CG-1435 | VCB Readings | Amps B Ø | 65.0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0116 | BreakerVacuum | CG-1435 | VCB Readings | Amps C Ø | 65.0 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0116 | BreakerVacuum | CG-1435 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0116 | BreakerVacuum | CG-1435 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0116 | BreakerVacuum | CG-1435 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LB0116 | BreakerVacuum | CG-1435 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000017 | BreakerVacuum | AK-1292 | VCB Readings | 9 Month Operations | 8 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000016 | BreakerVacuum | AK-1291 | VCB Readings | Switching Operations | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000016 | BreakerVacuum | AK-1291 | VCB Readings | Operations This Read Vac | 11 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000016 | BreakerVacuum | AK-1291 | VCB Readings | Operations Counter AL | 190 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000016 | BreakerVacuum | AK-1291 | VCB Readings | Operations Counter AF | 190 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000016 | BreakerVacuum | AK-1291 | VCB Readings | Maintenance Operations | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000016 | BreakerVacuum | AK-1291 | VCB Readings | General Comments | BC Phase IOC / Storms in Area | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000016 | BreakerVacuum | AK-1291 | VCB Patrol Inspection | General Comments | | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Readings | Switching Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Readings | Operations This Read Vac | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001246 | BreakerVacuum | AL-1378 | VCB Readings | Operations Counter AL | 383 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001244 | BreakerVacuum | AL-1374 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001244 | BreakerVacuum | AL-1374 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000016 | BreakerVacuum | AK-1291 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001244 | BreakerVacuum | AL-1374 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001244 | BreakerVacuum | AL-1374 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001244 | BreakerVacuum | AL-1374 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001244 | BreakerVacuum | AL-1374 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001244 | BreakerVacuum | AL-1374 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/7/2023 9:11 | Distribution | Campground Quarterly Inspection | LT0027 | WithLTC | CG-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000017 | BreakerVacuum | AK-1292 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000017 | BreakerVacuum | AK-1292 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000017 | BreakerVacuum | AK-1292 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000016 | BreakerVacuum | AK-1291 | VCB Readings | Fault Operations B Ø | 6 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Readings | 9 Month Operations | 0 | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000017 | BreakerVacuum | AK-1292 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000017 | BreakerVacuum | AK-1292 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/7/2023 10:44 | Distribution | Algonquin Quarterly Inspection | BK001391 | BreakerVacuum | AL-GND TR 4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000017 | BreakerVacuum | AK-1292 | VCB Readings | Amps B Ø | 113.0 | |
| 3/7/2023 13:30 | Distribution | Aiken Quarterly Inspection | BK000017 | BreakerVacuum | AK-1292 | VCB Readings | Amps C Ø | 101.0 | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | ST000050 | Structure | 346-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | ST000050 | Structure | 346-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | ST000050 | Structure | 346-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | ST000050 | Structure | 346-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | ST000050 | Structure | 346-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | ST000050 | Structure | 346-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | ST000050 | Structure | 346-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | ST000050 | Structure | 346-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | ST000050 | Structure | 346-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | ST000050 | Structure | 346-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | ST000050 | Structure | 346-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | ST000050 | Structure | 346-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | ST000050 | Structure | 346-Structure | Structure Patrol Inspection | General Comments | | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | ST000050 | Structure | 346-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | ST000050 | Structure | 346-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | ST000050 | Structure | 346-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | ST000050 | Structure | 346-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | ST000050 | Structure | 346-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000172 | Regulator | 346-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000172 | Regulator | 346-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | ST000050 | Structure | 346-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | ST000050 | Structure | 346-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000178 | Regulator | 346-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000178 | Regulator | 346-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000178 | Regulator | 346-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000172 | Regulator | 346-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 19703 | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000172 | Regulator | 346-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000172 | Regulator | 346-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0092 | RecloserHydraulic | 346-0760 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0092 | RecloserHydraulic | 346-0760 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0092 | RecloserHydraulic | 346-0760 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 8 | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0092 | RecloserHydraulic | 346-0760 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 67 | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0092 | RecloserHydraulic | 346-0760 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 6.2 | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0092 | RecloserHydraulic | 346-0760 | Recloser Hydraulic Patrol Inspection | Amps B Ø | .6 | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0092 | RecloserHydraulic | 346-0760 | Recloser Hydraulic Patrol Inspection | Amps C Ø | .1 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | ST000050 | Structure | 346-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | ST000050 | Structure | 346-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0092 | RecloserHydraulic | 346-0760 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 72 | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0092 | RecloserHydraulic | 346-0760 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0092 | RecloserHydraulic | 346-0760 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0092 | RecloserHydraulic | 346-0760 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0092 | RecloserHydraulic | 346-0760 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0092 | RecloserHydraulic | 346-0760 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0092 | RecloserHydraulic | 346-0760 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0092 | RecloserHydraulic | 346-0760 | Recloser Hydraulic Patrol Inspection | Operations Counter | 0 | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .8292 | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0092 | RecloserHydraulic | 346-0760 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Readings | Oil Temp Max | 37 | °C |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 97.50 | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 995.04 | kw |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | O0173 | NonLTC | 346-1 | NonLTC Transformer Readings | General Comments | | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000178 | Regulator | 346-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000178 | Regulator | 346-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | YD000011 | Yard | 346-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000178 | Regulator | 346-1 C | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000178 | Regulator | 346-1 C | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000178 | Regulator | 346-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000178 | Regulator | 346-1 C | Regulator Patrol Inspection | General Comments | | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000178 | Regulator | 346-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000178 | Regulator | 346-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000178 | Regulator | 346-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000178 | Regulator | 346-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000178 | Regulator | 346-1 C | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000178 | Regulator | 346-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000178 | Regulator | 346-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000178 | Regulator | 346-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | YD000011 | Yard | 346-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | YD000011 | Yard | 346-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | YD000011 | Yard | 346-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | YD000011 | Yard | 346-Yard | Yard Patrol Inspection | General Comments | | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | FE000013 | Fence | 346-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | FE000013 | Fence | 346-Fence | Fence Patrol Inspection | General Comments | Still has brush growing at fence behind station | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | FE000013 | Fence | 346-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | FE000013 | Fence | 346-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | FE000013 | Fence | 346-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | FE000013 | Fence | 346-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000172 | Regulator | 346-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.2 | volts |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000172 | Regulator | 346-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000172 | Regulator | 346-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | YD000011 | Yard | 346-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | YD000011 | Yard | 346-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000178 | Regulator | 346-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000178 | Regulator | 346-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | YD000011 | Yard | 346-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | YD000011 | Yard | 346-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | YD000011 | Yard | 346-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | FE000013 | Fence | 346-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | FE000013 | Fence | 346-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | FE000013 | Fence | 346-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | FE000013 | Fence | 346-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | FE000013 | Fence | 346-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | FE000013 | Fence | 346-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | FE000013 | Fence | 346-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | FE000013 | Fence | 346-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | FE000013 | Fence | 346-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | YD000011 | Yard | 346-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000172 | Regulator | 346-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0189 | RecloserHydraulic | 346-0762 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0189 | RecloserHydraulic | 346-0762 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0189 | RecloserHydraulic | 346-0762 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0189 | RecloserHydraulic | 346-0762 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0189 | RecloserHydraulic | 346-0762 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0189 | RecloserHydraulic | 346-0762 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0189 | RecloserHydraulic | 346-0762 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0189 | RecloserHydraulic | 346-0762 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 795 | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0189 | RecloserHydraulic | 346-0762 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0189 | RecloserHydraulic | 346-0762 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0189 | RecloserHydraulic | 346-0762 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 0 | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0189 | RecloserHydraulic | 346-0762 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 27.7 | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0189 | RecloserHydraulic | 346-0762 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 27.2 | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0189 | RecloserHydraulic | 346-0762 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 24.6 | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | MX0189 | RecloserHydraulic | 346-0762 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 0 | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000172 | Regulator | 346-1 B | Regulator Patrol Inspection | Max Tap Position | 4L | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000172 | Regulator | 346-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000172 | Regulator | 346-1 B | Regulator Patrol Inspection | General Comments | Control was locked up again | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000172 | Regulator | 346-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000172 | Regulator | 346-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000172 | Regulator | 346-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000172 | Regulator | 346-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000172 | Regulator | 346-1 B | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000172 | Regulator | 346-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000172 | Regulator | 346-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000172 | Regulator | 346-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000172 | Regulator | 346-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000172 | Regulator | 346-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000172 | Regulator | 346-1 B | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000172 | Regulator | 346-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000171 | Regulator | 346-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000171 | Regulator | 346-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000171 | Regulator | 346-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000171 | Regulator | 346-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000171 | Regulator | 346-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 7297 | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000171 | Regulator | 346-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | FE000013 | Fence | 346-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000171 | Regulator | 346-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000171 | Regulator | 346-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000171 | Regulator | 346-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000178 | Regulator | 346-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000178 | Regulator | 346-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 3319 | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000171 | Regulator | 346-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000171 | Regulator | 346-1 A | Regulator Patrol Inspection | Min Tap Position | 4L | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000178 | Regulator | 346-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | YD000011 | Yard | 346-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | YD000011 | Yard | 346-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000178 | Regulator | 346-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000178 | Regulator | 346-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000171 | Regulator | 346-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000171 | Regulator | 346-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000171 | Regulator | 346-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000171 | Regulator | 346-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000171 | Regulator | 346-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000171 | Regulator | 346-1 A | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000171 | Regulator | 346-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000171 | Regulator | 346-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000171 | Regulator | 346-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000171 | Regulator | 346-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000171 | Regulator | 346-1 A | Regulator Patrol Inspection | General Comments | | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000171 | Regulator | 346-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/6/2023 10:40 | Distribution | St Charles ODP Quarterly Inspection | RG000171 | Regulator | 346-1 A | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001058 | BreakerVacuum | CL-1228 | VCB Readings | Operations Counter AF | 13 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001058 | BreakerVacuum | CL-1228 | VCB Readings | Switching Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001059 | BreakerVacuum | CL-1230 | VCB Readings | 9 Month Operations | 3 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001058 | BreakerVacuum | CL-1228 | VCB Readings | Unknown Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001058 | BreakerVacuum | CL-1228 | VCB Readings | Operations This Read Vac | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 50 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001058 | BreakerVacuum | CL-1228 | VCB Readings | Operations Counter AL | 13 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Readings | Amps C Ø | 0.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Readings | Operations Counter AL | 96 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Readings | Operations Counter AF | 96 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 50 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 550 | psi |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Readings | 9 Month Operations | 7 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Readings | Amps A Ø | 9.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Readings | Amps B Ø | 9.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Readings | Amps C Ø | 9.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | 3 fans not working. Need to troubleshoot and repair. | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Readings | Unknown Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Readings | Switching Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Readings | Operations This Read Vac | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Readings | Operations Counter AL | 88 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Readings | Operations Counter AF | 88 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Readings | Fault Operations Ground | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Readings | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Readings | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Readings | Fault Operations Ground | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Readings | Fault Operations C Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Readings | Fault Operations B Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Readings | Fault Operations A Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001056 | BreakerVacuum | CL-1226 | VCB Readings | Operations Counter AF | 96 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001056 | BreakerVacuum | CL-1226 | VCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001056 | BreakerVacuum | CL-1226 | VCB Readings | General Comments | IOC A,B & C Phase | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001056 | BreakerVacuum | CL-1226 | VCB Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000060 | Switchgear | CL-Swgr Sec 5 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000060 | Switchgear | CL-Swgr Sec 5 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000060 | Switchgear | CL-Swgr Sec 5 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000060 | Switchgear | CL-Swgr Sec 5 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000060 | Switchgear | CL-Swgr Sec 5 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000060 | Switchgear | CL-Swgr Sec 5 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001056 | BreakerVacuum | CL-1226 | VCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001056 | BreakerVacuum | CL-1226 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001056 | BreakerVacuum | CL-1226 | VCB Readings | Fault Operations Ground | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001056 | BreakerVacuum | CL-1226 | VCB Readings | Fault Operations C Ø | 1 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001056 | BreakerVacuum | CL-1226 | VCB Readings | Fault Operations B Ø | 1 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001056 | BreakerVacuum | CL-1226 | VCB Readings | Fault Operations A Ø | 1 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0197 | BreakerAirMagnetic | CL-1225 | AMCB Readings | Unknown Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0197 | BreakerAirMagnetic | CL-1225 | AMCB Readings | Switching Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0197 | BreakerAirMagnetic | CL-1225 | AMCB Readings | Operations This Read AM | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0197 | BreakerAirMagnetic | CL-1225 | AMCB Readings | Operations Counter AL | 325 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0197 | BreakerAirMagnetic | CL-1225 | AMCB Readings | Operations Counter AF | 325 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0197 | BreakerAirMagnetic | CL-1225 | AMCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0197 | BreakerAirMagnetic | CL-1225 | AMCB Readings | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0197 | BreakerAirMagnetic | CL-1225 | AMCB Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0197 | BreakerAirMagnetic | CL-1225 | AMCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0197 | BreakerAirMagnetic | CL-1225 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0197 | BreakerAirMagnetic | CL-1225 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0197 | BreakerAirMagnetic | CL-1225 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0197 | BreakerAirMagnetic | CL-1225 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0197 | BreakerAirMagnetic | CL-1225 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0197 | BreakerAirMagnetic | CL-1225 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0197 | BreakerAirMagnetic | CL-1225 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0197 | BreakerAirMagnetic | CL-1225 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0197 | BreakerAirMagnetic | CL-1225 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0197 | BreakerAirMagnetic | CL-1225 | AMCB Readings | Amps C Ø | 0.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0197 | BreakerAirMagnetic | CL-1225 | AMCB Readings | Amps B Ø | 0.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0197 | BreakerAirMagnetic | CL-1225 | AMCB Readings | Amps A Ø | 0.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0197 | BreakerAirMagnetic | CL-1225 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0197 | BreakerAirMagnetic | CL-1225 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0197 | BreakerAirMagnetic | CL-1225 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0197 | BreakerAirMagnetic | CL-1225 | AMCB Readings | 9 Months Operations | 7 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0197 | BreakerAirMagnetic | CL-1225 | AMCB Readings | 9 Month Ops New | 7 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000058 | Switchgear | CL-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Readings | Switching Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Readings | 9 Month Operations | 13 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Readings | 9 Month Operations VCB New | 13 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Readings | Amps A Ø | 75.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Readings | Amps B Ø | 75.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000060 | Switchgear | CL-Swgr Sec 5 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000060 | Switchgear | CL-Swgr Sec 5 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000060 | Switchgear | CL-Swgr Sec 5 | Switchgear Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000060 | Switchgear | CL-Swgr Sec 5 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000060 | Switchgear | CL-Swgr Sec 5 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000060 | Switchgear | CL-Swgr Sec 5 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000060 | Switchgear | CL-Swgr Sec 5 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000060 | Switchgear | CL-Swgr Sec 5 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000060 | Switchgear | CL-Swgr Sec 5 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000060 | Switchgear | CL-Swgr Sec 5 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Readings | Amps C Ø | 75.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001056 | BreakerVacuum | CL-1226 | VCB Readings | Unknown Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001056 | BreakerVacuum | CL-1226 | VCB Readings | Switching Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000060 | Switchgear | CL-Swgr Sec 5 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | PF000089 | PowerFuse | CL-STA SER NO 5 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | PF000089 | PowerFuse | CL-STA SER NO 5 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | PF000088 | PowerFuse | CL-14KV TR 3 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | PF000088 | PowerFuse | CL-14KV TR 3 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001056 | BreakerVacuum | CL-1226 | VCB Readings | Operations This Read Vac | 3 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | PF000086 | PowerFuse | CL-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | PF000086 | PowerFuse | CL-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001946 | BreakerVacuum | CL-1403 | VCB Readings | Operations This Read Vac | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000058 | Switchgear | CL-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000058 | Switchgear | CL-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000058 | Switchgear | CL-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000058 | Switchgear | CL-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000058 | Switchgear | CL-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000058 | Switchgear | CL-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000058 | Switchgear | CL-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001056 | BreakerVacuum | CL-1226 | VCB Readings | Operations Counter AL | 96 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001056 | BreakerVacuum | CL-1226 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001056 | BreakerVacuum | CL-1226 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001056 | BreakerVacuum | CL-1226 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001056 | BreakerVacuum | CL-1226 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001056 | BreakerVacuum | CL-1226 | VCB Readings | 9 Month Operations | 3 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000058 | Switchgear | CL-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000058 | Switchgear | CL-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000058 | Switchgear | CL-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | PF000090 | PowerFuse | CL-12KV TR 5 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 40 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 40 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 30 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 50 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | WithLTC | CL-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 50 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001058 | BreakerVacuum | CL-1228 | VCB Readings | 9 Month Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001058 | BreakerVacuum | CL-1228 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001058 | BreakerVacuum | CL-1228 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001058 | BreakerVacuum | CL-1228 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001058 | BreakerVacuum | CL-1228 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001058 | BreakerVacuum | CL-1228 | VCB Readings | Amps A Ø | 0.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001058 | BreakerVacuum | CL-1228 | VCB Readings | Amps B Ø | 0.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001058 | BreakerVacuum | CL-1228 | VCB Readings | Amps C Ø | 0.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001058 | BreakerVacuum | CL-1228 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001058 | BreakerVacuum | CL-1228 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001058 | BreakerVacuum | CL-1228 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | PF000090 | PowerFuse | CL-12KV TR 5 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000058 | Switchgear | CL-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000058 | Switchgear | CL-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000058 | Switchgear | CL-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000058 | Switchgear | CL-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001058 | BreakerVacuum | CL-1228 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001058 | BreakerVacuum | CL-1228 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001058 | BreakerVacuum | CL-1228 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001058 | BreakerVacuum | CL-1228 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001058 | BreakerVacuum | CL-1228 | VCB Readings | Fault Operations Ground | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001058 | BreakerVacuum | CL-1228 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001058 | BreakerVacuum | CL-1228 | VCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001058 | BreakerVacuum | CL-1228 | VCB Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001058 | BreakerVacuum | CL-1228 | VCB Readings | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001058 | BreakerVacuum | CL-1228 | VCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000058 | Switchgear | CL-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001057 | BreakerVacuum | CL-1227 | VCB Readings | 9 Month Operations | 2 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001057 | BreakerVacuum | CL-1227 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001057 | BreakerVacuum | CL-1227 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001057 | BreakerVacuum | CL-1227 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001057 | BreakerVacuum | CL-1227 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001057 | BreakerVacuum | CL-1227 | VCB Readings | Amps A Ø | 42.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001057 | BreakerVacuum | CL-1227 | VCB Readings | Amps B Ø | 31.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001057 | BreakerVacuum | CL-1227 | VCB Readings | Amps C Ø | 36.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001057 | BreakerVacuum | CL-1227 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001057 | BreakerVacuum | CL-1227 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001057 | BreakerVacuum | CL-1227 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001057 | BreakerVacuum | CL-1227 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001057 | BreakerVacuum | CL-1227 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001057 | BreakerVacuum | CL-1227 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001057 | BreakerVacuum | CL-1227 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000058 | Switchgear | CL-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001057 | BreakerVacuum | CL-1227 | VCB Readings | Fault Operations Ground | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001057 | BreakerVacuum | CL-1227 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001057 | BreakerVacuum | CL-1227 | VCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001057 | BreakerVacuum | CL-1227 | VCB Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001057 | BreakerVacuum | CL-1227 | VCB Readings | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001057 | BreakerVacuum | CL-1227 | VCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001057 | BreakerVacuum | CL-1227 | VCB Readings | Operations Counter AF | 93 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001057 | BreakerVacuum | CL-1227 | VCB Readings | Operations Counter AL | 93 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001057 | BreakerVacuum | CL-1227 | VCB Readings | Operations This Read Vac | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001057 | BreakerVacuum | CL-1227 | VCB Readings | Switching Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001057 | BreakerVacuum | CL-1227 | VCB Readings | Unknown Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | PF000085 | PowerFuse | CL-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | PF000085 | PowerFuse | CL-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000058 | Switchgear | CL-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000058 | Switchgear | CL-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000018 | Switchgear | CL-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000018 | Switchgear | CL-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000018 | Switchgear | CL-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000018 | Switchgear | CL-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001056 | BreakerVacuum | CL-1226 | VCB Readings | Fault Adjusted Amps C Phase V | 11.18 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001056 | BreakerVacuum | CL-1226 | VCB Readings | Fault Adjusted Amps B Phase V | 11.18 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001056 | BreakerVacuum | CL-1226 | VCB Readings | Fault Adjusted Amps A Phase V | 11.18 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001056 | BreakerVacuum | CL-1226 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001056 | BreakerVacuum | CL-1226 | VCB Readings | Amps C Ø | 180.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001056 | BreakerVacuum | CL-1226 | VCB Readings | Amps B Ø | 180.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001056 | BreakerVacuum | CL-1226 | VCB Readings | Amps A Ø | 150.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Readings | 9 Month Operations | 6 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000059 | Switchgear | CL-Swgr Sec 3 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000059 | Switchgear | CL-Swgr Sec 3 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000059 | Switchgear | CL-Swgr Sec 3 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | 6 pack needs to be refilled. At 0 psi. | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Readings | LV Winding Temp Max | 35 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Readings | LV Winding Temp Present | 25 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | WithLTC | CL-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0215 | BreakerAirMagnetic | CL-1405 | AMCB Readings | 9 Month Ops New | 2 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0215 | BreakerAirMagnetic | CL-1405 | AMCB Readings | 9 Months Operations | 2 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0215 | BreakerAirMagnetic | CL-1405 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0215 | BreakerAirMagnetic | CL-1405 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0215 | BreakerAirMagnetic | CL-1405 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0215 | BreakerAirMagnetic | CL-1405 | AMCB Readings | Amps A Ø | 160.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0215 | BreakerAirMagnetic | CL-1405 | AMCB Readings | Amps B Ø | 160.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0215 | BreakerAirMagnetic | CL-1405 | AMCB Readings | Amps C Ø | 170.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0215 | BreakerAirMagnetic | CL-1405 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0215 | BreakerAirMagnetic | CL-1405 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0215 | BreakerAirMagnetic | CL-1405 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0215 | BreakerAirMagnetic | CL-1405 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0215 | BreakerAirMagnetic | CL-1405 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0215 | BreakerAirMagnetic | CL-1405 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0215 | BreakerAirMagnetic | CL-1405 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0215 | BreakerAirMagnetic | CL-1405 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0215 | BreakerAirMagnetic | CL-1405 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0215 | BreakerAirMagnetic | CL-1405 | AMCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0215 | BreakerAirMagnetic | CL-1405 | AMCB Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Readings | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCC000658 | LTCControl | CL-TRANS 3 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCC000658 | LTCControl | CL-TRANS 3 | LTC Control Insp | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCC000658 | LTCControl | CL-TRANS 3 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCM000040 | LTCMechanism | CL-TRANS 3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCM000040 | LTCMechanism | CL-TRANS 3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCM000040 | LTCMechanism | CL-TRANS 3 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCM000040 | LTCMechanism | CL-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCM000040 | LTCMechanism | CL-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCM000040 | LTCMechanism | CL-TRANS 3 | LTC Counter Readings | LTC Operations Since Last Insp | 1000 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCM000040 | LTCMechanism | CL-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 60 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000059 | Switchgear | CL-Swgr Sec 3 | Switchgear Patrol Inspection | General Comments | Vent fan isn't working. Needs troubleshooting and to be repaired. | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000059 | Switchgear | CL-Swgr Sec 3 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000059 | Switchgear | CL-Swgr Sec 3 | Switchgear Patrol Inspection | Follow-up Action Required? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000059 | Switchgear | CL-Swgr Sec 3 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000059 | Switchgear | CL-Swgr Sec 3 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000059 | Switchgear | CL-Swgr Sec 3 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000059 | Switchgear | CL-Swgr Sec 3 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000059 | Switchgear | CL-Swgr Sec 3 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCM000040 | LTCMechanism | CL-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 35 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCM000040 | LTCMechanism | CL-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCM000040 | LTCMechanism | CL-TRANS 3 | LTC Counter Readings | LTC Min Tap Position | 3L | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCM000040 | LTCMechanism | CL-TRANS 3 | LTC Counter Readings | LTC Max Tap Position | 7R | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCM000040 | LTCMechanism | CL-TRANS 3 | LTC Counter Readings | LTC Current Tap Position | 5R | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCM000040 | LTCMechanism | CL-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCM000040 | LTCMechanism | CL-TRANS 3 | LTC Counter Readings | LTC As Left Counter | 42829 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCM000040 | LTCMechanism | CL-TRANS 3 | LTC Counter Readings | LTC As Found Counter | 42829 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCM000040 | LTCMechanism | CL-TRANS 3 | LTC Mechanism Patrol Inspection | General Comments | Tap Changer filter was kicked off on low pressure. Tap changer was low on oil. We added roughly 5 gallons. The tap changer filter is l | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCM000040 | LTCMechanism | CL-TRANS 3 | LTC Counter Readings | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCM000040 | LTCMechanism | CL-TRANS 3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCM000040 | LTCMechanism | CL-TRANS 3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Readings | Fault Operations Ground | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Readings | Amps C Ø | 0.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Readings | Amps B Ø | 0.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Readings | Amps A Ø | 0.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | 9 Month Operations | 17 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | 9 Month Operations VCB New | 17 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Accumulated Fault Duty A Ph V | 46.1 | % |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Accumulated Fault Duty B Ph V | 51.01 | % |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Accumulated Fault Duty C Ph V | 39.95 | % |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Amps A Ø | 66.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Amps B Ø | 66.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Amps C Ø | 61.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Operations Counter AF | 660 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Operations Counter AL | 660 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Operations This Read Vac | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Switching Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Present | 38 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Max | 60 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Present | 38 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Max | 60 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Present | 38 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Max | 60 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Readings | Oil Temp Present | 33 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Readings | Oil Temp Max | 56 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Readings | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | TX000075 | WithLTC | CL-TRANS 3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0215 | BreakerAirMagnetic | CL-1405 | AMCB Readings | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0215 | BreakerAirMagnetic | CL-1405 | AMCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0215 | BreakerAirMagnetic | CL-1405 | AMCB Readings | Operations Counter AF | 767 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0215 | BreakerAirMagnetic | CL-1405 | AMCB Readings | Operations Counter AL | 767 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0215 | BreakerAirMagnetic | CL-1405 | AMCB Readings | Operations This Read AM | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0215 | BreakerAirMagnetic | CL-1405 | AMCB Readings | Switching Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0215 | BreakerAirMagnetic | CL-1405 | AMCB Readings | Unknown Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0201 | BreakerAirMagnetic | CL-1229 | AMCB Readings | 9 Month Ops New | 1 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0201 | BreakerAirMagnetic | CL-1229 | AMCB Readings | 9 Months Operations | 1 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0201 | BreakerAirMagnetic | CL-1229 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0201 | BreakerAirMagnetic | CL-1229 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0201 | BreakerAirMagnetic | CL-1229 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0201 | BreakerAirMagnetic | CL-1229 | AMCB Readings | Amps A Ø | 86.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0201 | BreakerAirMagnetic | CL-1229 | AMCB Readings | Amps B Ø | 98.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0201 | BreakerAirMagnetic | CL-1229 | AMCB Readings | Amps C Ø | 102.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0201 | BreakerAirMagnetic | CL-1229 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0201 | BreakerAirMagnetic | CL-1229 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0201 | BreakerAirMagnetic | CL-1229 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0201 | BreakerAirMagnetic | CL-1229 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0201 | BreakerAirMagnetic | CL-1229 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0201 | BreakerAirMagnetic | CL-1229 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0201 | BreakerAirMagnetic | CL-1229 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0201 | BreakerAirMagnetic | CL-1229 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0220 | BreakerAirMagnetic | CL-GND TR 3 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0220 | BreakerAirMagnetic | CL-GND TR 3 | AMCB Readings | 9 Months Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0220 | BreakerAirMagnetic | CL-GND TR 3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0220 | BreakerAirMagnetic | CL-GND TR 3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0220 | BreakerAirMagnetic | CL-GND TR 3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0220 | BreakerAirMagnetic | CL-GND TR 3 | AMCB Readings | Amps A Ø | 0.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0220 | BreakerAirMagnetic | CL-GND TR 3 | AMCB Readings | Amps B Ø | 0.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0220 | BreakerAirMagnetic | CL-GND TR 3 | AMCB Readings | Amps C Ø | 0.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0220 | BreakerAirMagnetic | CL-GND TR 3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0220 | BreakerAirMagnetic | CL-GND TR 3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0220 | BreakerAirMagnetic | CL-GND TR 3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0220 | BreakerAirMagnetic | CL-GND TR 3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0220 | BreakerAirMagnetic | CL-GND TR 3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0220 | BreakerAirMagnetic | CL-GND TR 3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0220 | BreakerAirMagnetic | CL-GND TR 3 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0220 | BreakerAirMagnetic | CL-GND TR 3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0220 | BreakerAirMagnetic | CL-GND TR 3 | AMCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0220 | BreakerAirMagnetic | CL-GND TR 3 | AMCB Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0220 | BreakerAirMagnetic | CL-GND TR 3 | AMCB Readings | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0220 | BreakerAirMagnetic | CL-GND TR 3 | AMCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0220 | BreakerAirMagnetic | CL-GND TR 3 | AMCB Readings | Operations Counter AF | 311 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0220 | BreakerAirMagnetic | CL-GND TR 3 | AMCB Readings | Operations Counter AL | 311 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0220 | BreakerAirMagnetic | CL-GND TR 3 | AMCB Readings | Operations This Read AM | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0201 | BreakerAirMagnetic | CL-1229 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0201 | BreakerAirMagnetic | CL-1229 | AMCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0201 | BreakerAirMagnetic | CL-1229 | AMCB Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0201 | BreakerAirMagnetic | CL-1229 | AMCB Readings | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0201 | BreakerAirMagnetic | CL-1229 | AMCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0201 | BreakerAirMagnetic | CL-1229 | AMCB Readings | Operations Counter AF | 960 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0201 | BreakerAirMagnetic | CL-1229 | AMCB Readings | Operations Counter AL | 960 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0201 | BreakerAirMagnetic | CL-1229 | AMCB Readings | Operations This Read AM | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0201 | BreakerAirMagnetic | CL-1229 | AMCB Readings | Switching Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0201 | BreakerAirMagnetic | CL-1229 | AMCB Readings | Unknown Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0220 | BreakerAirMagnetic | CL-GND TR 3 | AMCB Readings | Switching Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0220 | BreakerAirMagnetic | CL-GND TR 3 | AMCB Readings | Unknown Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0216 | BreakerAirMagnetic | CL-1406 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0216 | BreakerAirMagnetic | CL-1406 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0216 | BreakerAirMagnetic | CL-1406 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0216 | BreakerAirMagnetic | CL-1406 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0216 | BreakerAirMagnetic | CL-1406 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0216 | BreakerAirMagnetic | CL-1406 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0216 | BreakerAirMagnetic | CL-1406 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0216 | BreakerAirMagnetic | CL-1406 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0216 | BreakerAirMagnetic | CL-1406 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0216 | BreakerAirMagnetic | CL-1406 | AMCB Readings | Amps C Ø | 0.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0216 | BreakerAirMagnetic | CL-1406 | AMCB Readings | Amps B Ø | 0.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0216 | BreakerAirMagnetic | CL-1406 | AMCB Readings | Amps A Ø | 0.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0216 | BreakerAirMagnetic | CL-1406 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0216 | BreakerAirMagnetic | CL-1406 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0216 | BreakerAirMagnetic | CL-1406 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0216 | BreakerAirMagnetic | CL-1406 | AMCB Readings | 9 Months Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0216 | BreakerAirMagnetic | CL-1406 | AMCB Readings | 9 Month Ops New | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001060 | BreakerVacuum | CL-12KV BUS TIE SEC 5 | VCB Readings | 9 Month Operations | 9 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001060 | BreakerVacuum | CL-12KV BUS TIE SEC 5 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001060 | BreakerVacuum | CL-12KV BUS TIE SEC 5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001060 | BreakerVacuum | CL-12KV BUS TIE SEC 5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001060 | BreakerVacuum | CL-12KV BUS TIE SEC 5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001060 | BreakerVacuum | CL-12KV BUS TIE SEC 5 | VCB Readings | Amps A Ø | 0.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001060 | BreakerVacuum | CL-12KV BUS TIE SEC 5 | VCB Readings | Amps B Ø | 0.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001060 | BreakerVacuum | CL-12KV BUS TIE SEC 5 | VCB Readings | Amps C Ø | 0.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001060 | BreakerVacuum | CL-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001060 | BreakerVacuum | CL-12KV BUS TIE SEC 5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001060 | BreakerVacuum | CL-12KV BUS TIE SEC 5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001060 | BreakerVacuum | CL-12KV BUS TIE SEC 5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001060 | BreakerVacuum | CL-12KV BUS TIE SEC 5 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001060 | BreakerVacuum | CL-12KV BUS TIE SEC 5 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001060 | BreakerVacuum | CL-12KV BUS TIE SEC 5 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | LTCMechanism | CL-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0218 | BreakerAirMagnetic | CL-14KV TR 3 | AMCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0218 | BreakerAirMagnetic | CL-14KV TR 3 | AMCB Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0218 | BreakerAirMagnetic | CL-14KV TR 3 | AMCB Readings | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0218 | BreakerAirMagnetic | CL-14KV TR 3 | AMCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0218 | BreakerAirMagnetic | CL-14KV TR 3 | AMCB Readings | Operations Counter AF | 609 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0218 | BreakerAirMagnetic | CL-14KV TR 3 | AMCB Readings | Operations Counter AL | 609 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0218 | BreakerAirMagnetic | CL-14KV TR 3 | AMCB Readings | Operations This Read AM | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0218 | BreakerAirMagnetic | CL-14KV TR 3 | AMCB Readings | Switching Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0218 | BreakerAirMagnetic | CL-14KV TR 3 | AMCB Readings | Unknown Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | LTCMechanism | CL-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | LTCMechanism | CL-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | LTCMechanism | CL-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | LTCMechanism | CL-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 238 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | LTCMechanism | CL-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | LTCMechanism | CL-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | LTCMechanism | CL-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | LTCMechanism | CL-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | LTCMechanism | CL-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | LTCMechanism | CL-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 203588 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | LTCMechanism | CL-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 203588 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | LTCMechanism | CL-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | LTCMechanism | CL-TRANS 2 | LTC Counter Readings | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | LTCMechanism | CL-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0057 | LTCMechanism | CL-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001060 | BreakerVacuum | CL-12KV BUS TIE SEC 5 | VCB Readings | Fault Operations Ground | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Readings | Amps B Ø | 0.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Readings | Amps A Ø | 0.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001945 | BreakerVacuum | CL-1402/1404 TFR | VCB Readings | 9 Month Operations | 2 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001059 | BreakerVacuum | CL-1230 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001059 | BreakerVacuum | CL-1230 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001059 | BreakerVacuum | CL-1230 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001059 | BreakerVacuum | CL-1230 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001059 | BreakerVacuum | CL-1230 | VCB Readings | Amps A Ø | 89.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001059 | BreakerVacuum | CL-1230 | VCB Readings | Amps B Ø | 100.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001059 | BreakerVacuum | CL-1230 | VCB Readings | Amps C Ø | 100.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001059 | BreakerVacuum | CL-1230 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001059 | BreakerVacuum | CL-1230 | VCB Readings | Fault Adjusted Amps A Phase V | 11.18 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001059 | BreakerVacuum | CL-1230 | VCB Readings | Fault Adjusted Amps B Phase V | 11.18 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001059 | BreakerVacuum | CL-1230 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001059 | BreakerVacuum | CL-1230 | VCB Readings | Fault Operations A Ø | 1 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001059 | BreakerVacuum | CL-1230 | VCB Readings | Fault Operations B Ø | 1 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001059 | BreakerVacuum | CL-1230 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001059 | BreakerVacuum | CL-1230 | VCB Readings | Fault Operations Ground | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001059 | BreakerVacuum | CL-1230 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001059 | BreakerVacuum | CL-1230 | VCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001059 | BreakerVacuum | CL-1230 | VCB Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0218 | BreakerAirMagnetic | CL-14KV TR 3 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0218 | BreakerAirMagnetic | CL-14KV TR 3 | AMCB Readings | 9 Months Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0218 | BreakerAirMagnetic | CL-14KV TR 3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0218 | BreakerAirMagnetic | CL-14KV TR 3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0218 | BreakerAirMagnetic | CL-14KV TR 3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0218 | BreakerAirMagnetic | CL-14KV TR 3 | AMCB Readings | Amps A Ø | 600.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0218 | BreakerAirMagnetic | CL-14KV TR 3 | AMCB Readings | Amps B Ø | 600.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0218 | BreakerAirMagnetic | CL-14KV TR 3 | AMCB Readings | Amps C Ø | 590.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0218 | BreakerAirMagnetic | CL-14KV TR 3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0218 | BreakerAirMagnetic | CL-14KV TR 3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0218 | BreakerAirMagnetic | CL-14KV TR 3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0218 | BreakerAirMagnetic | CL-14KV TR 3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0218 | BreakerAirMagnetic | CL-14KV TR 3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0218 | BreakerAirMagnetic | CL-14KV TR 3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0218 | BreakerAirMagnetic | CL-14KV TR 3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0218 | BreakerAirMagnetic | CL-14KV TR 3 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001059 | BreakerVacuum | CL-1230 | VCB Readings | General Comments | IOC A & B Phase | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001059 | BreakerVacuum | CL-1230 | VCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001059 | BreakerVacuum | CL-1230 | VCB Readings | Operations Counter AF | 100 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001059 | BreakerVacuum | CL-1230 | VCB Readings | Operations Counter AL | 100 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001059 | BreakerVacuum | CL-1230 | VCB Readings | Operations This Read Vac | 2 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001059 | BreakerVacuum | CL-1230 | VCB Readings | Switching Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001059 | BreakerVacuum | CL-1230 | VCB Readings | Unknown Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0216 | BreakerAirMagnetic | CL-1406 | AMCB Readings | Unknown Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0216 | BreakerAirMagnetic | CL-1406 | AMCB Readings | Switching Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0216 | BreakerAirMagnetic | CL-1406 | AMCB Readings | Operations This Read AM | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0216 | BreakerAirMagnetic | CL-1406 | AMCB Readings | Operations Counter AL | 747 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0216 | BreakerAirMagnetic | CL-1406 | AMCB Readings | Operations Counter AF | 747 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0216 | BreakerAirMagnetic | CL-1406 | AMCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0216 | BreakerAirMagnetic | CL-1406 | AMCB Readings | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0218 | BreakerAirMagnetic | CL-14KV TR 3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0216 | BreakerAirMagnetic | CL-1406 | AMCB Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0216 | BreakerAirMagnetic | CL-1406 | AMCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCC000540 | LTCControl | CL-TRANS 5 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCC000540 | LTCControl | CL-TRANS 5 | LTC Control Insp | General Comments | ok | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCC000541 | LTCControl | CL-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCC000541 | LTCControl | CL-TRANS 2 | LTC Control Insp | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCC000541 | LTCControl | CL-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000059 | Switchgear | CL-Swgr Sec 3 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000059 | Switchgear | CL-Swgr Sec 3 | Switchgear Patrol Inspection | Vent Fans OK? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000059 | Switchgear | CL-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000059 | Switchgear | CL-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Readings | Amps C Ø | 102.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Readings | Amps B Ø | 104.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Readings | Amps A Ø | 100.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Readings | 9 Month Operations | 3 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001061 | BreakerVacuum | CL-12KV TR 5 | VCB Readings | Amps B Ø | 320.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001061 | BreakerVacuum | CL-12KV TR 5 | VCB Readings | Amps C Ø | 315.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001061 | BreakerVacuum | CL-12KV TR 5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001061 | BreakerVacuum | CL-12KV TR 5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001061 | BreakerVacuum | CL-12KV TR 5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001061 | BreakerVacuum | CL-12KV TR 5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001061 | BreakerVacuum | CL-12KV TR 5 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001061 | BreakerVacuum | CL-12KV TR 5 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001061 | BreakerVacuum | CL-12KV TR 5 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001061 | BreakerVacuum | CL-12KV TR 5 | VCB Readings | Fault Operations Ground | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001061 | BreakerVacuum | CL-12KV TR 5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001061 | BreakerVacuum | CL-12KV TR 5 | VCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001061 | BreakerVacuum | CL-12KV TR 5 | VCB Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001061 | BreakerVacuum | CL-12KV TR 5 | VCB Readings | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001061 | BreakerVacuum | CL-12KV TR 5 | VCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001061 | BreakerVacuum | CL-12KV TR 5 | VCB Readings | Operations Counter AF | 72 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001061 | BreakerVacuum | CL-12KV TR 5 | VCB Readings | Operations Counter AL | 72 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001061 | BreakerVacuum | CL-12KV TR 5 | VCB Readings | Operations This Read Vac | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001061 | BreakerVacuum | CL-12KV TR 5 | VCB Readings | Switching Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001061 | BreakerVacuum | CL-12KV TR 5 | VCB Readings | Unknown Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000059 | Switchgear | CL-Swgr Sec 3 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000059 | Switchgear | CL-Swgr Sec 3 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000059 | Switchgear | CL-Swgr Sec 3 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000059 | Switchgear | CL-Swgr Sec 3 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Readings | Switching Operations | 3 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Readings | Operations This Read Vac | 3 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Readings | Operations Counter AL | 154 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Readings | Operations Counter AF | 154 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001943 | BreakerVacuum | CL-1401 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001060 | BreakerVacuum | CL-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001060 | BreakerVacuum | CL-12KV BUS TIE SEC 5 | VCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001060 | BreakerVacuum | CL-12KV BUS TIE SEC 5 | VCB Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001060 | BreakerVacuum | CL-12KV BUS TIE SEC 5 | VCB Readings | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001060 | BreakerVacuum | CL-12KV BUS TIE SEC 5 | VCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001060 | BreakerVacuum | CL-12KV BUS TIE SEC 5 | VCB Readings | Operations Counter AF | 93 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001060 | BreakerVacuum | CL-12KV BUS TIE SEC 5 | VCB Readings | Operations Counter AL | 93 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001060 | BreakerVacuum | CL-12KV BUS TIE SEC 5 | VCB Readings | Operations This Read Vac | 2 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001060 | BreakerVacuum | CL-12KV BUS TIE SEC 5 | VCB Readings | Switching Operations | 2 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001060 | BreakerVacuum | CL-12KV BUS TIE SEC 5 | VCB Readings | Unknown Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | PF000084 | PowerFuse | CL-14KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | PF000084 | PowerFuse | CL-14KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | PF000083 | PowerFuse | CL-14KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | PF000083 | PowerFuse | CL-14KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000060 | Switchgear | CL-Swgr Sec 5 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | SWG000060 | Switchgear | CL-Swgr Sec 5 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | LTCMechanism | CL-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | LTCMechanism | CL-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | LTCMechanism | CL-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 237 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | LTCMechanism | CL-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 3 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | LTCMechanism | CL-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 3 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | LTCMechanism | CL-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 3 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | LTCMechanism | CL-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | LTCMechanism | CL-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 29723 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | LTCMechanism | CL-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 29723 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | LTCMechanism | CL-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | LTCMechanism | CL-TRANS 1 | LTC Counter Readings | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | LTCMechanism | CL-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0055 | LTCMechanism | CL-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCC000489 | LTCControl | CL-TRANS 1 | LTC Control Insp | General Comments | ok | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LTCC000489 | LTCControl | CL-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001061 | BreakerVacuum | CL-12KV TR 5 | VCB Readings | 9 Month Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001061 | BreakerVacuum | CL-12KV TR 5 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001061 | BreakerVacuum | CL-12KV TR 5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001061 | BreakerVacuum | CL-12KV TR 5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001061 | BreakerVacuum | CL-12KV TR 5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001061 | BreakerVacuum | CL-12KV TR 5 | VCB Readings | Amps A Ø | 277.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Readings | Unknown Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Readings | Switching Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Readings | Operations This Read Vac | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Readings | Operations Counter AL | 96 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Readings | Operations Counter AF | 96 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Readings | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Readings | Fault Operations Ground | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001944 | BreakerVacuum | CL-1402 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0217 | BreakerAirMagnetic | CL-1407 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0217 | BreakerAirMagnetic | CL-1407 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0217 | BreakerAirMagnetic | CL-1407 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Readings | Amps A Ø | 0.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Readings | 9 Months Operations OCB New | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | PF000082 | PowerFuse | CL-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | PF000082 | PowerFuse | CL-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0217 | BreakerAirMagnetic | CL-1407 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0217 | BreakerAirMagnetic | CL-1407 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0217 | BreakerAirMagnetic | CL-1407 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0217 | BreakerAirMagnetic | CL-1407 | AMCB Readings | Amps C Ø | 450.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0217 | BreakerAirMagnetic | CL-1407 | AMCB Readings | Amps B Ø | 460.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0217 | BreakerAirMagnetic | CL-1407 | AMCB Readings | Amps A Ø | 457.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0217 | BreakerAirMagnetic | CL-1407 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0217 | BreakerAirMagnetic | CL-1407 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0203 | BreakerAirMagnetic | CL-1231 | AMCB Readings | Operations This Read AM | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0203 | BreakerAirMagnetic | CL-1231 | AMCB Readings | Operations Counter AL | 907 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0203 | BreakerAirMagnetic | CL-1231 | AMCB Readings | Operations Counter AF | 907 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0217 | BreakerAirMagnetic | CL-1407 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0217 | BreakerAirMagnetic | CL-1407 | AMCB Readings | 9 Months Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0217 | BreakerAirMagnetic | CL-1407 | AMCB Readings | 9 Month Ops New | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | LTCMechanism | CL-TRANS 5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | LTCMechanism | CL-TRANS 5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | LTCMechanism | CL-TRANS 5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | LTCMechanism | CL-TRANS 5 | LTC Counter Readings | LTC Operations Since Last Insp | 317 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | LTCMechanism | CL-TRANS 5 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | LTCMechanism | CL-TRANS 5 | LTC Counter Readings | LTC Max Tap Position | 10L | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | LTCMechanism | CL-TRANS 5 | LTC Counter Readings | LTC Current Tap Position | 13L | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | LTCMechanism | CL-TRANS 5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | LTCMechanism | CL-TRANS 5 | LTC Counter Readings | LTC As Left Counter | 216078 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | LTCMechanism | CL-TRANS 5 | LTC Counter Readings | LTC As Found Counter | 216078 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | LTCMechanism | CL-TRANS 5 | LTC Mechanism Patrol Inspection | General Comments | The screw on desicant filters need to be replaced.  There are two of them. | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | LTCMechanism | CL-TRANS 5 | LTC Counter Readings | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | LTCMechanism | CL-TRANS 5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | LTCMechanism | CL-TRANS 5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | 9 Month Operations | 20 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | 9 Month Operations VCB New | 20 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0203 | BreakerAirMagnetic | CL-1231 | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Accumulated Fault Duty A Ph V | 1.71 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0203 | BreakerAirMagnetic | CL-1231 | AMCB Readings | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0203 | BreakerAirMagnetic | CL-1231 | AMCB Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0203 | BreakerAirMagnetic | CL-1231 | AMCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0203 | BreakerAirMagnetic | CL-1231 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0203 | BreakerAirMagnetic | CL-1231 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0250 | GroundTransformer | CL-GND TR 1 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0250 | GroundTransformer | CL-GND TR 1 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0250 | GroundTransformer | CL-GND TR 1 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0250 | GroundTransformer | CL-GND TR 1 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0250 | GroundTransformer | CL-GND TR 1 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0250 | GroundTransformer | CL-GND TR 1 | Ground Transformer Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0250 | GroundTransformer | CL-GND TR 1 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0250 | GroundTransformer | CL-GND TR 1 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0250 | GroundTransformer | CL-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0250 | GroundTransformer | CL-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0250 | GroundTransformer | CL-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Patrol Inspection | Fans Operational? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0203 | BreakerAirMagnetic | CL-1231 | AMCB Readings | Unknown Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0203 | BreakerAirMagnetic | CL-1231 | AMCB Readings | Switching Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0217 | BreakerAirMagnetic | CL-1407 | AMCB Readings | Unknown Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0217 | BreakerAirMagnetic | CL-1407 | AMCB Readings | Switching Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0217 | BreakerAirMagnetic | CL-1407 | AMCB Readings | Operations This Read AM | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0217 | BreakerAirMagnetic | CL-1407 | AMCB Readings | Operations Counter AL | 636 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0217 | BreakerAirMagnetic | CL-1407 | AMCB Readings | Operations Counter AF | 636 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0217 | BreakerAirMagnetic | CL-1407 | AMCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0217 | BreakerAirMagnetic | CL-1407 | AMCB Readings | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0217 | BreakerAirMagnetic | CL-1407 | AMCB Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | PF000087 | PowerFuse | CL-STA SER NO 3 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | PF000087 | PowerFuse | CL-STA SER NO 3 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0217 | BreakerAirMagnetic | CL-1407 | AMCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0217 | BreakerAirMagnetic | CL-1407 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0217 | BreakerAirMagnetic | CL-1407 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0217 | BreakerAirMagnetic | CL-1407 | AMCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Readings | Unknown Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Patrol Inspection | Tank Oil Level | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Patrol Inspection | Tank Leaks | None | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Readings | Switching Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Readings | Operations This Read Oil | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Readings | Operations Counter AL | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Readings | Operations Counter AF | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Readings | Number of Ops last 9 Months | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Patrol Inspection | Grounds in Place? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Readings | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Patrol Inspection | Foundation Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Readings | Fault Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Patrol Inspection | Bushing Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Readings | Amps C Ø | 0.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0219 | BreakerOil | CL-GND TR 1 | OCB Readings | Amps B Ø | 0.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Readings | X1 Winding Temp Max | 40 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Readings | X1 Winding Temp Present | 40 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Readings | X2 Winding Temp Max | 45 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Readings | X2 Winding Temp Present | 20 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Readings | X3 Winding Temp Max | 40 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Readings | X3 Winding Temp Present | 20 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0203 | BreakerAirMagnetic | CL-1231 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0203 | BreakerAirMagnetic | CL-1231 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0203 | BreakerAirMagnetic | CL-1231 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0203 | BreakerAirMagnetic | CL-1231 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0203 | BreakerAirMagnetic | CL-1231 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0203 | BreakerAirMagnetic | CL-1231 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0203 | BreakerAirMagnetic | CL-1231 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0203 | BreakerAirMagnetic | CL-1231 | AMCB Readings | Amps C Ø | 53.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0203 | BreakerAirMagnetic | CL-1231 | AMCB Readings | Amps B Ø | 59.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0203 | BreakerAirMagnetic | CL-1231 | AMCB Readings | Amps A Ø | 42.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0203 | BreakerAirMagnetic | CL-1231 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0203 | BreakerAirMagnetic | CL-1231 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0203 | BreakerAirMagnetic | CL-1231 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0203 | BreakerAirMagnetic | CL-1231 | AMCB Readings | 9 Months Operations | 4 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0203 | BreakerAirMagnetic | CL-1231 | AMCB Readings | 9 Month Ops New | 4 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | 9 Month Operations | 15 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | 9 Month Operations VCB New | 15 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Accumulated Fault Duty A Ph V | .05 | % |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Accumulated Fault Duty B Ph V | .05 | % |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Accumulated Fault Duty C Ph V | .05 | % |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Amps A Ø | 0.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Amps B Ø | 0.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Amps C Ø | 0.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0297 | GroundTransformer | CL-GND TR 3 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0297 | GroundTransformer | CL-GND TR 3 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0297 | GroundTransformer | CL-GND TR 3 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0297 | GroundTransformer | CL-GND TR 3 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0297 | GroundTransformer | CL-GND TR 3 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0297 | GroundTransformer | CL-GND TR 3 | Ground Transformer Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0297 | GroundTransformer | CL-GND TR 3 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0297 | GroundTransformer | CL-GND TR 3 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0297 | GroundTransformer | CL-GND TR 3 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0297 | GroundTransformer | CL-GND TR 3 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0297 | GroundTransformer | CL-GND TR 3 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0297 | GroundTransformer | CL-GND TR 3 | Ground Transformer Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0297 | GroundTransformer | CL-GND TR 3 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0297 | GroundTransformer | CL-GND TR 3 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0204 | BreakerAirMagnetic | CL-1232 | AMCB Readings | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Operations Counter AF | 87 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Operations Counter AL | 87 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Operations This Read Vac | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Switching Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0250 | GroundTransformer | CL-GND TR 1 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0250 | GroundTransformer | CL-GND TR 1 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0250 | GroundTransformer | CL-GND TR 1 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Accumulated Fault Duty B Ph V | 1.71 | % |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Accumulated Fault Duty C Ph V | .85 | % |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Amps A Ø | 25.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Amps B Ø | 24.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Amps C Ø | 24.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Operations Counter AF | 362 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Operations Counter AL | 362 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Operations This Read Vac | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Switching Operations | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Unknown Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0204 | BreakerAirMagnetic | CL-1232 | AMCB Readings | 9 Month Ops New | 1 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0204 | BreakerAirMagnetic | CL-1232 | AMCB Readings | 9 Months Operations | 1 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0204 | BreakerAirMagnetic | CL-1232 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0204 | BreakerAirMagnetic | CL-1232 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0204 | BreakerAirMagnetic | CL-1232 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0204 | BreakerAirMagnetic | CL-1232 | AMCB Readings | Amps A Ø | 221.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0204 | BreakerAirMagnetic | CL-1232 | AMCB Readings | Amps B Ø | 192.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0204 | BreakerAirMagnetic | CL-1232 | AMCB Readings | Amps C Ø | 179.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0204 | BreakerAirMagnetic | CL-1232 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0204 | BreakerAirMagnetic | CL-1232 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0204 | BreakerAirMagnetic | CL-1232 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0204 | BreakerAirMagnetic | CL-1232 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Readings | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Patrol Inspection | General Comments | 1 fan is not working.  Needs to be repaired. | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0204 | BreakerAirMagnetic | CL-1232 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0204 | BreakerAirMagnetic | CL-1232 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0204 | BreakerAirMagnetic | CL-1232 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0204 | BreakerAirMagnetic | CL-1232 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0204 | BreakerAirMagnetic | CL-1232 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0204 | BreakerAirMagnetic | CL-1232 | AMCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0204 | BreakerAirMagnetic | CL-1232 | AMCB Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LT0056 | WithLTC | CL-TRANS 5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0207 | BreakerAirMagnetic | CL-12KV TR 2 | AMCB Readings | Operations Counter AL | 329 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0207 | BreakerAirMagnetic | CL-12KV TR 2 | AMCB Readings | Operations This Read AM | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0207 | BreakerAirMagnetic | CL-12KV TR 2 | AMCB Readings | Operations Counter AF | 329 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Readings | Unknown Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0207 | BreakerAirMagnetic | CL-12KV TR 2 | AMCB Readings | Switching Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0207 | BreakerAirMagnetic | CL-12KV TR 2 | AMCB Readings | Unknown Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0207 | BreakerAirMagnetic | CL-12KV TR 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0207 | BreakerAirMagnetic | CL-12KV TR 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0207 | BreakerAirMagnetic | CL-12KV TR 2 | AMCB Readings | Amps A Ø | 342.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0207 | BreakerAirMagnetic | CL-12KV TR 2 | AMCB Readings | Amps B Ø | 338.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0207 | BreakerAirMagnetic | CL-12KV TR 2 | AMCB Readings | Amps C Ø | 330.0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0207 | BreakerAirMagnetic | CL-12KV TR 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | PF000081 | PowerFuse | CL-GND TR 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | PF000081 | PowerFuse | CL-GND TR 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Readings | Fault Operations Ground | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0207 | BreakerAirMagnetic | CL-12KV TR 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0207 | BreakerAirMagnetic | CL-12KV TR 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0207 | BreakerAirMagnetic | CL-12KV TR 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0207 | BreakerAirMagnetic | CL-12KV TR 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Readings | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Readings | Operations Counter AF | 102 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0207 | BreakerAirMagnetic | CL-12KV TR 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0207 | BreakerAirMagnetic | CL-12KV TR 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0207 | BreakerAirMagnetic | CL-12KV TR 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0207 | BreakerAirMagnetic | CL-12KV TR 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0207 | BreakerAirMagnetic | CL-12KV TR 2 | AMCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0207 | BreakerAirMagnetic | CL-12KV TR 2 | AMCB Patrol Inspection | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0207 | BreakerAirMagnetic | CL-12KV TR 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0207 | BreakerAirMagnetic | CL-12KV TR 2 | AMCB Readings | 9 Months Operations | 2 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0204 | BreakerAirMagnetic | CL-1232 | AMCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0204 | BreakerAirMagnetic | CL-1232 | AMCB Readings | Operations Counter AF | 890 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Readings | Switching Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Readings | Operations This Read Vac | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | BK001947 | BreakerVacuum | CL-1404 | VCB Readings | Operations Counter AL | 102 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0207 | BreakerAirMagnetic | CL-12KV TR 2 | AMCB Readings | 9 Month Ops New | 2 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0204 | BreakerAirMagnetic | CL-1232 | AMCB Readings | Operations Counter AL | 890 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0207 | BreakerAirMagnetic | CL-12KV TR 2 | AMCB Readings | General Comments | | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0207 | BreakerAirMagnetic | CL-12KV TR 2 | AMCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0204 | BreakerAirMagnetic | CL-1232 | AMCB Readings | Operations This Read AM | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0204 | BreakerAirMagnetic | CL-1232 | AMCB Readings | Switching Operations | 0 | |
| 3/3/2023 11:37 | Distribution | Clifton Quarterly Inspection | LB0204 | BreakerAirMagnetic | CL-1232 | AMCB Readings | Unknown Operations | 0 | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1219 | BreakerVacuum | FM-12KV BUS TIE SEC 2 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1219 | BreakerVacuum | FM-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1219 | BreakerVacuum | FM-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1224 | BreakerVacuum | FM-1263 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1224 | BreakerVacuum | FM-1263 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1224 | BreakerVacuum | FM-1263 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1223 | BreakerVacuum | FM-1262 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1223 | BreakerVacuum | FM-1262 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1223 | BreakerVacuum | FM-1262 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1222 | BreakerVacuum | FM-1261 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1222 | BreakerVacuum | FM-1261 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1222 | BreakerVacuum | FM-1261 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1221 | BreakerVacuum | FM-1260 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1221 | BreakerVacuum | FM-1260 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1221 | BreakerVacuum | FM-1260 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1220 | BreakerVacuum | FM-1258 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1220 | BreakerVacuum | FM-1258 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1220 | BreakerVacuum | FM-1258 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1171 | BreakerVacuum | FM-12KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1171 | BreakerVacuum | FM-12KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB1171 | BreakerVacuum | FM-12KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | PF000127 | PowerFuse | FM-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | PF000127 | PowerFuse | FM-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | PF000126 | PowerFuse | FM-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | PF000126 | PowerFuse | FM-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000109 | Switchgear | FM-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000109 | Switchgear | FM-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000109 | Switchgear | FM-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000109 | Switchgear | FM-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000109 | Switchgear | FM-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000109 | Switchgear | FM-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000109 | Switchgear | FM-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000109 | Switchgear | FM-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000109 | Switchgear | FM-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000109 | Switchgear | FM-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000109 | Switchgear | FM-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000109 | Switchgear | FM-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000109 | Switchgear | FM-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000109 | Switchgear | FM-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000109 | Switchgear | FM-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000109 | Switchgear | FM-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000109 | Switchgear | FM-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000109 | Switchgear | FM-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000109 | Switchgear | FM-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB0301 | BreakerVacuum | FM-1256 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB0301 | BreakerVacuum | FM-1256 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LB0301 | BreakerVacuum | FM-1256 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | PF000125 | PowerFuse | FM-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | PF000125 | PowerFuse | FM-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | PF000124 | PowerFuse | FM-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | PF000124 | PowerFuse | FM-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000014 | Switchgear | FM-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000014 | Switchgear | FM-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000014 | Switchgear | FM-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000014 | Switchgear | FM-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000014 | Switchgear | FM-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000014 | Switchgear | FM-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000014 | Switchgear | FM-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000014 | Switchgear | FM-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000014 | Switchgear | FM-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000014 | Switchgear | FM-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000014 | Switchgear | FM-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000014 | Switchgear | FM-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000014 | Switchgear | FM-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000014 | Switchgear | FM-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | SWG000014 | Switchgear | FM-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.8 | psi |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1500 | psi |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | LT0292 | WithLTC | FM-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | ST000600 | Structure | FM-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | ST000600 | Structure | FM-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | ST000600 | Structure | FM-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | ST000600 | Structure | FM-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | ST000600 | Structure | FM-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | ST000600 | Structure | FM-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | ST000600 | Structure | FM-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | ST000600 | Structure | FM-Structure | Structure Patrol Inspection | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | ST000600 | Structure | FM-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | ST000600 | Structure | FM-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | ST000600 | Structure | FM-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | ST000600 | Structure | FM-Structure | Structure Patrol Inspection | Interruptrs/Puffrs Visual OK? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | ST000600 | Structure | FM-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | ST000600 | Structure | FM-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | ST000600 | Structure | FM-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | ST000600 | Structure | FM-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | ST000600 | Structure | FM-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BAT000093 | Battery | FM-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BAT000093 | Battery | FM-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BAT000093 | Battery | FM-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BAT000093 | Battery | FM-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BAT000093 | Battery | FM-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BAT000093 | Battery | FM-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BAT000093 | Battery | FM-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BAT000093 | Battery | FM-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BAT000093 | Battery | FM-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BAT000093 | Battery | FM-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BAT000093 | Battery | FM-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BAT000093 | Battery | FM-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | CH000140 | ControlHouse | FM-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | CH000140 | ControlHouse | FM-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | CH000140 | ControlHouse | FM-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | CH000140 | ControlHouse | FM-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | CH000140 | ControlHouse | FM-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | CH000140 | ControlHouse | FM-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | CH000140 | ControlHouse | FM-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | CH000140 | ControlHouse | FM-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | CH000140 | ControlHouse | FM-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | CH000140 | ControlHouse | FM-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | CH000140 | ControlHouse | FM-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | CH000140 | ControlHouse | FM-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | CH000140 | ControlHouse | FM-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | CH000140 | ControlHouse | FM-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | CH000140 | ControlHouse | FM-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | CH000140 | ControlHouse | FM-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | CH000140 | ControlHouse | FM-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | CH000140 | ControlHouse | FM-Control House | Control House Patrol Inspection | Restroom Clean & OK? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | CH000140 | ControlHouse | FM-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | CH000140 | ControlHouse | FM-Control House | Control House Patrol Inspection | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | CH000140 | ControlHouse | FM-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | CH000140 | ControlHouse | FM-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | CH000140 | ControlHouse | FM-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | YD000612 | Yard | FM-Yard | Yard Patrol Inspection | Ambient Temp | 53 | °F |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | YD000612 | Yard | FM-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | YD000612 | Yard | FM-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | YD000612 | Yard | FM-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | YD000612 | Yard | FM-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | YD000612 | Yard | FM-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | YD000612 | Yard | FM-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | YD000612 | Yard | FM-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | YD000612 | Yard | FM-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | YD000612 | Yard | FM-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | YD000612 | Yard | FM-Yard | Yard Patrol Inspection | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | YD000612 | Yard | FM-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | YD000612 | Yard | FM-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | YD000612 | Yard | FM-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | YD000612 | Yard | FM-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | YD000612 | Yard | FM-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | YD000612 | Yard | FM-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | YD000612 | Yard | FM-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | FE000566 | Fence | FM-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | FE000566 | Fence | FM-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | FE000566 | Fence | FM-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | FE000566 | Fence | FM-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | FE000566 | Fence | FM-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | FE000566 | Fence | FM-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | FE000566 | Fence | FM-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | FE000566 | Fence | FM-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | FE000566 | Fence | FM-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | FE000566 | Fence | FM-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | FE000566 | Fence | FM-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | FE000566 | Fence | FM-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | FE000566 | Fence | FM-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | FE000566 | Fence | FM-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | FE000566 | Fence | FM-Fence | Fence Patrol Inspection | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | FE000566 | Fence | FM-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001350 | BreakerVacuum | FM-1257 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001351 | BreakerVacuum | FM-1259 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/14/2023 9:51 | Distribution | Fairmount Quarterly Inspection | BK001352 | BreakerVacuum | FM-12KV TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0754 | BreakerSF6 | Retired Distribution | GCB Readings | Operations Counter AF | 649 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0754 | BreakerSF6 | Retired Distribution | GCB Readings | Operations Counter AL | 649 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0754 | BreakerSF6 | Retired Distribution | GCB Readings | Operations This Read SF6 | 1 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0754 | BreakerSF6 | Retired Distribution | GCB Readings | Switching Operations | 0 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0754 | BreakerSF6 | Retired Distribution | GCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0754 | BreakerSF6 | Retired Distribution | GCB Readings | Num Operations Last 9 Months | 13 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0754 | BreakerSF6 | Retired Distribution | GCB Readings | General Comments | C phase | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0754 | BreakerSF6 | Retired Distribution | GCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0754 | BreakerSF6 | Retired Distribution | GCB Readings | Fault Operations | 1 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0754 | BreakerSF6 | Retired Distribution | GCB Readings | 9 Month Operations GCB New | 12 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0752 | BreakerSF6 | Retired Distribution | GCB Readings | 9 Month Operations GCB New | 2 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0752 | BreakerSF6 | Retired Distribution | GCB Readings | Fault Operations | 0 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0752 | BreakerSF6 | Retired Distribution | GCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0752 | BreakerSF6 | Retired Distribution | GCB Readings | General Comments | | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0752 | BreakerSF6 | Retired Distribution | GCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0752 | BreakerSF6 | Retired Distribution | GCB Readings | Num Operations Last 9 Months | 2 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0752 | BreakerSF6 | Retired Distribution | GCB Readings | Operations Counter AF | 677 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0752 | BreakerSF6 | Retired Distribution | GCB Readings | Operations Counter AL | 677 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0752 | BreakerSF6 | Retired Distribution | GCB Readings | Operations This Read SF6 | 0 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0752 | BreakerSF6 | Retired Distribution | GCB Readings | Switching Operations | 0 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0754 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0754 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0754 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0754 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0754 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0754 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0754 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Foundation Condition | Good | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0754 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | General Comments | | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0754 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Grounds in Place? | y | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0754 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0754 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0754 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0754 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0754 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0752 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0752 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0752 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0752 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0752 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0752 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0752 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Grounds in Place? | y | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0752 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | General Comments | | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0752 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Foundation Condition | Good | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0752 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0752 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0752 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0752 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0752 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0753 | BreakerSF6 | Retired Distribution | GCB Readings | Switching Operations | 1 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0753 | BreakerSF6 | Retired Distribution | GCB Readings | Operations This Read SF6 | 1 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0753 | BreakerSF6 | Retired Distribution | GCB Readings | Operations Counter AL | 438 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0753 | BreakerSF6 | Retired Distribution | GCB Readings | Operations Counter AF | 438 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0753 | BreakerSF6 | Retired Distribution | GCB Readings | Num Operations Last 9 Months | 1 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0753 | BreakerSF6 | Retired Distribution | GCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0753 | BreakerSF6 | Retired Distribution | GCB Readings | General Comments | | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0753 | BreakerSF6 | Retired Distribution | GCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0753 | BreakerSF6 | Retired Distribution | GCB Readings | Fault Operations | 0 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0753 | BreakerSF6 | Retired Distribution | GCB Readings | 9 Month Operations GCB New | 0 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0753 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0753 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0753 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0753 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0753 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0753 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Grounds in Place? | y | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0753 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | General Comments | | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0753 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Foundation Condition | Good | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0753 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0753 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0753 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0753 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0753 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | TB0753 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0698 | Regulator | 797-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0698 | Regulator | 797-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0698 | Regulator | 797-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.2 | volts |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Readings | 9 Month Operations | 1 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0698 | Regulator | 797-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 120164 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0698 | Regulator | 797-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0698 | Regulator | 797-1 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0698 | Regulator | 797-1 A | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1199 | Regulator | 693-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0698 | Regulator | 797-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0698 | Regulator | 797-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0698 | Regulator | 797-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1199 | Regulator | 693-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1199 | Regulator | 693-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Readings | Amps A Ø | 50.0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Readings | Amps C Ø | 40.0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Readings | Amps B Ø | 40.0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | LTCMechanism | 433-2 | LTC Counter Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | LTCMechanism | 433-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Readings | Amps C Ø | 70.0 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Readings | Amps B Ø | 69.0 | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0208 | RecloserElectronic | 562-2440 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0208 | RecloserElectronic | 562-2440 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0208 | RecloserElectronic | 562-2440 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0208 | RecloserElectronic | 562-2440 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0208 | RecloserElectronic | 562-2440 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0208 | RecloserElectronic | 562-2440 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0208 | RecloserElectronic | 562-2440 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0208 | RecloserElectronic | 562-2440 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0208 | RecloserElectronic | 562-2440 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Readings | Fault Operations Ground | 0 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0208 | RecloserElectronic | 562-2440 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0208 | RecloserElectronic | 562-2440 | Recloser Electronic Patrol Inspection | Operations Counter | 99997 | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Readings | Amps A Ø | 72.0 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Readings | 9 Month Operations | 2 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Readings | General Comments | | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Readings | LTC Totalizer Reading | 9061.20 | kw |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Readings | Follow-up Action Required? | n | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Patrol Inspection | General Comments | | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Readings | General Comments | | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | LTCMechanism | 433-2 | LTC Counter Readings | General Comments | | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Readings | Totalizer Meter Reading | .7662 | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | LTCMechanism | 433-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | LTCMechanism | 433-2 | LTC Counter Readings | LTC As Found Counter | 61124 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | LTCMechanism | 433-2 | LTC Counter Readings | LTC As Left Counter | 61124 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | LTCMechanism | 433-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0698 | Regulator | 797-1 A | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0698 | Regulator | 797-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0698 | Regulator | 797-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0698 | Regulator | 797-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0698 | Regulator | 797-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0698 | Regulator | 797-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0208 | RecloserElectronic | 562-2440 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0208 | RecloserElectronic | 562-2440 | Recloser Electronic Patrol Inspection | Amps A Ø | 24 | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0208 | RecloserElectronic | 562-2440 | Recloser Electronic Patrol Inspection | Amps B Ø | 38 | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0208 | RecloserElectronic | 562-2440 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0208 | RecloserElectronic | 562-2440 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | LTCMechanism | 433-2 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | LTCMechanism | 433-2 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | LTCMechanism | 433-2 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | LTCMechanism | 433-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | LTCMechanism | 433-2 | LTC Counter Readings | LTC Operations Since Last Insp | 639 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | LTCMechanism | 433-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | LTCMechanism | 433-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | LTCMechanism | 433-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0208 | RecloserElectronic | 562-2440 | Recloser Electronic Patrol Inspection | Amps C Ø | 35 | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0208 | RecloserElectronic | 562-2440 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0208 | RecloserElectronic | 562-2440 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0208 | RecloserElectronic | 562-2440 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Readings | Follow-up Action Required? | n | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Readings | Fault Operations Ground | 0 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1199 | Regulator | 693-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1199 | Regulator | 693-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | FE000146 | Fence | 576-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | FE000146 | Fence | 576-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | FE000146 | Fence | 576-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0698 | Regulator | 797-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1199 | Regulator | 693-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1199 | Regulator | 693-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | FE000146 | Fence | 576-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1199 | Regulator | 693-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1199 | Regulator | 693-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1199 | Regulator | 693-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1199 | Regulator | 693-1 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1199 | Regulator | 693-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | FE000146 | Fence | 576-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0 | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5 | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 2122.56 | kw |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Readings | Fault Operations Ground | 0 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | FE000146 | Fence | 576-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | FE000146 | Fence | 576-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | FE000146 | Fence | 576-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | FE000146 | Fence | 576-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Readings | Fault Operations C Ø | 1 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 4 | psi |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Readings | 9 Month Operations | 2 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1199 | Regulator | 693-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Readings | General Comments | | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Readings | Amps C Ø | 7.0 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Readings | Amps B Ø | 0.0 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Readings | Amps A Ø | 0.0 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0698 | Regulator | 797-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BCH001344 | Charger | 370-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BCH001344 | Charger | 370-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BCH001344 | Charger | 370-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.5 | amps |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BCH001344 | Charger | 370-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BCH001344 | Charger | 370-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BCH001344 | Charger | 370-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1199 | Regulator | 693-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 107804 | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1199 | Regulator | 693-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1199 | Regulator | 693-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1199 | Regulator | 693-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1199 | Regulator | 693-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1199 | Regulator | 693-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1199 | Regulator | 693-1 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1199 | Regulator | 693-1 B | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1199 | Regulator | 693-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Readings | Unknown Operations | 0 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Readings | Switching Operations | 0 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Readings | Operations This Read Vac | 1 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Readings | Operations Counter AL | 205 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Readings | Operations Counter AF | 205 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Readings | Fault Adjusted Amps C Phase V | 5.99 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | FE000146 | Fence | 576-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | FE000146 | Fence | 576-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Readings | Winding Temp Present | 20 | °C |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Readings | Winding Temp Max | 30 | °C |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .4422 | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KT0049 | NonLTC | 562-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | FE000146 | Fence | 576-Fence | Fence Patrol Inspection | General Comments | | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0698 | Regulator | 797-1 A | Regulator Patrol Inspection | General Comments | ok | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0698 | Regulator | 797-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0698 | Regulator | 797-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0698 | Regulator | 797-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Readings | Maintenance Operations | 1 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Readings | General Comments | TC | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Patrol Inspection | General Comments | | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | FE000146 | Fence | 576-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | FE000146 | Fence | 576-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | FE000146 | Fence | 576-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | FE000146 | Fence | 576-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1199 | Regulator | 693-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000721 | BreakerVacuum | 866-1617 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0111 | Regulator | 562-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0111 | Regulator | 562-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0111 | Regulator | 562-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0111 | Regulator | 562-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0111 | Regulator | 562-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Readings | Amps C Ø | 73.0 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Readings | Amps B Ø | 71.0 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Readings | Amps A Ø | 57.0 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1408 | Regulator | 866-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1408 | Regulator | 866-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1408 | Regulator | 866-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1408 | Regulator | 866-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1408 | Regulator | 866-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1408 | Regulator | 866-1 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1408 | Regulator | 866-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1408 | Regulator | 866-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1408 | Regulator | 866-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1408 | Regulator | 866-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1408 | Regulator | 866-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1408 | Regulator | 866-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1408 | Regulator | 866-1 B | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1408 | Regulator | 866-1 B | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1408 | Regulator | 866-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1408 | Regulator | 866-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1408 | Regulator | 866-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1408 | Regulator | 866-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1408 | Regulator | 866-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1408 | Regulator | 866-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 50883 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1408 | Regulator | 866-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1408 | Regulator | 866-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1408 | Regulator | 866-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1408 | Regulator | 866-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1410 | Regulator | 866-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Readings | 9 Month Operations | 1 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Readings | Unknown Operations | 0 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Readings | Switching Operations | 0 | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | W0210 | NonLTC | 375-1 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | W0210 | NonLTC | 375-1 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | W0210 | NonLTC | 375-1 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | W0210 | NonLTC | 375-1 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | W0210 | NonLTC | 375-1 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Readings | Operations This Read Vac | 0 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Readings | Operations Counter AL | 194 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Readings | Operations Counter AF | 194 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1410 | Regulator | 866-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Readings | Amps A Ø | 85.0 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0112 | Regulator | 562-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0112 | Regulator | 562-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0112 | Regulator | 562-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0112 | Regulator | 562-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0112 | Regulator | 562-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 36381 | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0112 | Regulator | 562-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123 | volts |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0112 | Regulator | 562-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0112 | Regulator | 562-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0112 | Regulator | 562-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0112 | Regulator | 562-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0112 | Regulator | 562-1 C | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0112 | Regulator | 562-1 C | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0112 | Regulator | 562-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0112 | Regulator | 562-1 C | Regulator Patrol Inspection | General Comments | | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0112 | Regulator | 562-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | LTCC000730 | LTCControl | 370-1 | LTC Control Insp | All Connections OK? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | LTCC000730 | LTCControl | 370-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | LTCC000730 | LTCControl | 370-1 | LTC Control Insp | General Comments | | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | LTCC000730 | LTCControl | 370-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | LTCC000730 | LTCControl | 370-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | LTCMechanism | 576-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | LTCMechanism | 576-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | LTCC000730 | LTCControl | 370-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0112 | Regulator | 562-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0112 | Regulator | 562-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0112 | Regulator | 562-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0112 | Regulator | 562-1 C | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0112 | Regulator | 562-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0112 | Regulator | 562-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0112 | Regulator | 562-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0112 | Regulator | 562-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0112 | Regulator | 562-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0111 | Regulator | 562-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0111 | Regulator | 562-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0111 | Regulator | 562-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0111 | Regulator | 562-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0111 | Regulator | 562-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 34598 | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0111 | Regulator | 562-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123 | volts |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0111 | Regulator | 562-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0111 | Regulator | 562-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0111 | Regulator | 562-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0111 | Regulator | 562-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0111 | Regulator | 562-1 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0111 | Regulator | 562-1 B | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0111 | Regulator | 562-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0111 | Regulator | 562-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0111 | Regulator | 562-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0111 | Regulator | 562-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0111 | Regulator | 562-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0111 | Regulator | 562-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0111 | Regulator | 562-1 B | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Readings | Fault Operations Ground | 0 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Readings | Follow-up Action Required? | n | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Readings | General Comments | 1 trip check, 3 unknown ops | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Patrol Inspection | General Comments | ok | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | LTCMechanism | 576-1 | LTC Counter Readings | General Comments | | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | LTCMechanism | 576-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | LTCMechanism | 576-1 | LTC Counter Readings | LTC As Found Counter | 14194 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | LTCMechanism | 576-1 | LTC Counter Readings | LTC As Left Counter | 14201 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | LTCMechanism | 576-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | W0210 | NonLTC | 375-1 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | LTCMechanism | 576-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | LTCMechanism | 576-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | LTCMechanism | 576-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | LTCMechanism | 576-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | -.5 | psi |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | LTCMechanism | 576-1 | LTC Counter Readings | LTC Operations Since Last Insp | 228 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | LTCMechanism | 576-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | LTCMechanism | 576-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | LTCMechanism | 576-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | W0210 | NonLTC | 375-1 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Readings | Amps C Ø | 25.0 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Readings | Amps B Ø | 31.0 | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | W0210 | NonLTC | 375-1 C | NonLTC Transformer Readings | General Comments | | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | W0210 | NonLTC | 375-1 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | W0210 | NonLTC | 375-1 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 150.00 | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | W0210 | NonLTC | 375-1 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 145.00 | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | W0210 | NonLTC | 375-1 C | NonLTC Transformer Readings | Oil Temp Max | 30 | °C |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | W0210 | NonLTC | 375-1 C | NonLTC Transformer Readings | Oil Temp Present | 27 | °C |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Readings | Maintenance Operations | 1 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Readings | Operations Counter AF | 148 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Readings | Operations Counter AL | 148 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Readings | Operations This Read Vac | 4 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Readings | Switching Operations | 0 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Readings | Unknown Operations | 3 | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | W0210 | NonLTC | 375-1 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Readings | 9 Month Operations | 4 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Readings | Amps A Ø | 25.0 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1410 | Regulator | 866-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1410 | Regulator | 866-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1410 | Regulator | 866-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1410 | Regulator | 866-1 C | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1410 | Regulator | 866-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1410 | Regulator | 866-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1410 | Regulator | 866-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1410 | Regulator | 866-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1410 | Regulator | 866-1 C | Regulator Patrol Inspection | General Comments | | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1410 | Regulator | 866-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1410 | Regulator | 866-1 C | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1410 | Regulator | 866-1 C | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1410 | Regulator | 866-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1410 | Regulator | 866-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1410 | Regulator | 866-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1410 | Regulator | 866-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1410 | Regulator | 866-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.1 | volts |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1410 | Regulator | 866-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 41030 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1410 | Regulator | 866-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1410 | Regulator | 866-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1410 | Regulator | 866-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1410 | Regulator | 866-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Readings | Maintenance Operations | 0 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Readings | General Comments | | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Patrol Inspection | General Comments | | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Readings | Follow-up Action Required? | n | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Readings | Amps B Ø | 85.0 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Readings | Amps C Ø | 100.0 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Readings | Fault Operations Ground | 0 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | LTCC000730 | LTCControl | 370-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | LTCC000730 | LTCControl | 370-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000495 | BreakerVacuum | 843-0216 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Readings | Fault Adjusted Amps A Phase V | 18.81 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Readings | Fault Adjusted Amps B Phase V | 18.81 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Readings | Fault Adjusted Amps C Phase V | 18.81 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Patrol Inspection | General Comments | ok | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Readings | General Comments | 1 trip check | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Readings | Follow-up Action Required? | n | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Readings | Fault Operations Ground | 0 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | BAT001671 | Battery | 008-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | BAT001671 | Battery | 008-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | BAT001671 | Battery | 008-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | BAT001671 | Battery | 008-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | BAT001671 | Battery | 008-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | BAT001671 | Battery | 008-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | BAT001671 | Battery | 008-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | BAT001671 | Battery | 008-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | BAT001671 | Battery | 008-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 70.1 | VDC |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | BAT001671 | Battery | 008-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 65.9 | VDC |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | BAT001671 | Battery | 008-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | BAT001671 | Battery | 008-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Readings | Amps C Ø | 75.0 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Readings | Amps B Ø | 80.0 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Readings | Amps A Ø | 75.0 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Readings | 9 Month Operations | 1 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Readings | Totalizer Meter Reading | .2800 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Readings | Oil Temp Present | 27 | °C |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Readings | LTC Totalizer Reading | 2688.00 | kw |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Readings | General Comments | | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Readings | Maintenance Operations | 1 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Readings | Operations Counter AF | 190 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Readings | Operations Counter AL | 190 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Readings | Operations This Read Vac | 1 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Readings | Switching Operations | 0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BK000903 | BreakerVacuum | 576-1614 | VCB Readings | Unknown Operations | 0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Readings | Follow-up Action Required? | n | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Patrol Inspection | General Comments | | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Readings | General Comments | | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | LTCC000675 | LTCControl | 843-1 | LTC Control Insp | All Connections OK? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | LTCC000675 | LTCControl | 843-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | LTCC000675 | LTCControl | 843-1 | LTC Control Insp | General Comments | | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | LTCC000675 | LTCControl | 843-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | LTCC000675 | LTCControl | 843-1 | LTC Control Insp | LTC Output Voltage Level | 124.6 | VAC |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | LTCC000675 | LTCControl | 843-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | LTCC000675 | LTCControl | 843-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | LTCC000675 | LTCControl | 843-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Readings | Maintenance Operations | 0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Readings | Operations Counter AF | 176 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Readings | Operations Counter AL | 176 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | LTCMechanism | 370-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | LTCMechanism | 370-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | LTCMechanism | 370-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Low | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | LTCMechanism | 370-1 | LTC Counter Readings | LTC Operations Since Last Insp | 575 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | LTCMechanism | 370-1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | LTCMechanism | 370-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | LTCMechanism | 370-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | LTCMechanism | 370-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | LTCMechanism | 370-1 | LTC Counter Readings | LTC As Left Counter | 286121 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | LTCMechanism | 370-1 | LTC Counter Readings | LTC As Found Counter | 286117 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | LTCMechanism | 370-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | LTCMechanism | 370-1 | LTC Counter Readings | General Comments | | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | LTCMechanism | 370-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | LTCMechanism | 370-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Readings | Unknown Operations | 0 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Readings | Switching Operations | 0 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Readings | Operations This Read Vac | 1 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Readings | Operations Counter AL | 154 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Readings | Operations Counter AF | 154 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Readings | Maintenance Operations | 1 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0111 | BreakerVacuum | 797-1607 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Readings | Unknown Operations | 0 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Readings | Totalizer Meter Reading | .5034 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Readings | Winding Temp Max | 75 | °C |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Readings | Switching Operations | 0 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Readings | Operations This Read Vac | 0 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Readings | Operations Counter AL | 190 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Readings | Operations Counter AF | 190 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | LTCMechanism | 778-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | LTCMechanism | 778-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | LTCMechanism | 778-1 | LTC Counter Readings | General Comments | | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | LTCMechanism | 778-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | LTCMechanism | 778-1 | LTC Counter Readings | LTC As Found Counter | 106339 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | LTCMechanism | 778-1 | LTC Counter Readings | LTC As Left Counter | 106351 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | LTCMechanism | 778-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | LTCMechanism | 778-1 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | LTCMechanism | 778-1 | LTC Counter Readings | LTC Max Tap Position | 16R | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | LTCMechanism | 778-1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | LTCMechanism | 778-1 | LTC Counter Readings | LTC Operations Since Last Insp | 721 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | LTCMechanism | 778-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | LTCMechanism | 778-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | LTCMechanism | 778-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BAT001197 | Battery | 370-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BAT001197 | Battery | 370-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BAT001197 | Battery | 370-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.1 | VDC |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BAT001197 | Battery | 370-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.3 | VDC |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BAT001197 | Battery | 370-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BAT001197 | Battery | 370-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BAT001197 | Battery | 370-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Exp/Missing Not Repl | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BAT001197 | Battery | 370-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BAT001197 | Battery | 370-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #'s |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BAT001197 | Battery | 370-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BAT001197 | Battery | 370-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BAT001197 | Battery | 370-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BAT001197 | Battery | 370-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BAT001197 | Battery | 370-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 80 | °F |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BAT001197 | Battery | 370-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Readings | Maintenance Operations | 0 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Readings | General Comments | | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Patrol Inspection | General Comments | | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Readings | Follow-up Action Required? | n | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Readings | Fault Operations Ground | 0 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BK000496 | BreakerVacuum | 843-0217 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Readings | 9 Month Operations | 4 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | K0114 | BreakerVacuum | 797-1606 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Readings | Operations This Read Vac | 1 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Readings | Switching Operations | 0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001439 | BreakerVacuum | 433-0626 | VCB Readings | Unknown Operations | 0 | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0856 | RecloserElectronic | 793-2437 | Recloser Electronic Patrol Inspection | Amps A Ø | 106 | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0856 | RecloserElectronic | 793-2437 | Recloser Electronic Patrol Inspection | Amps B Ø | 111 | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0856 | RecloserElectronic | 793-2437 | Recloser Electronic Patrol Inspection | Amps C Ø | 96 | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0856 | RecloserElectronic | 793-2437 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0856 | RecloserElectronic | 793-2437 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0856 | RecloserElectronic | 793-2437 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0856 | RecloserElectronic | 793-2437 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0856 | RecloserElectronic | 793-2437 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0856 | RecloserElectronic | 793-2437 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0856 | RecloserElectronic | 793-2437 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0856 | RecloserElectronic | 793-2437 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0856 | RecloserElectronic | 793-2437 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0856 | RecloserElectronic | 793-2437 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0856 | RecloserElectronic | 793-2437 | Recloser Electronic Patrol Inspection | General Comments | SEL control installed | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0856 | RecloserElectronic | 793-2437 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0856 | RecloserElectronic | 793-2437 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0856 | RecloserElectronic | 793-2437 | Recloser Electronic Patrol Inspection | Operations Counter | 2 | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0856 | RecloserElectronic | 793-2437 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0856 | RecloserElectronic | 793-2437 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0856 | RecloserElectronic | 793-2437 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0328 | NonLTC | 375-1 A | NonLTC Transformer Readings | Totalizer Meter Reading | .1050 | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0328 | NonLTC | 375-1 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 300 | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0328 | NonLTC | 375-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0328 | NonLTC | 375-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | B0476 | WithLTC | 778-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0328 | NonLTC | 375-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0328 | NonLTC | 375-1 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0328 | NonLTC | 375-1 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0328 | NonLTC | 375-1 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0328 | NonLTC | 375-1 A | NonLTC Transformer Readings | Oil Temp Present | 27 | °C |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0328 | NonLTC | 375-1 A | NonLTC Transformer Readings | Oil Temp Max | 27 | °C |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0328 | NonLTC | 375-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 65.00 | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0328 | NonLTC | 375-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 70.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0328 | NonLTC | 375-1 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 31.50 | kw |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0328 | NonLTC | 375-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0328 | NonLTC | 375-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0328 | NonLTC | 375-1 A | NonLTC Transformer Readings | General Comments | | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0328 | NonLTC | 375-1 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0328 | NonLTC | 375-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0328 | NonLTC | 375-1 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0328 | NonLTC | 375-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0328 | NonLTC | 375-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0328 | NonLTC | 375-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0328 | NonLTC | 375-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0328 | NonLTC | 375-1 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0328 | NonLTC | 375-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0328 | NonLTC | 375-1 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Readings | Amps C Ø | 14.0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Readings | Amps B Ø | 12.0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Readings | Amps A Ø | 24.0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Patrol Inspection | General Comments | | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Readings | General Comments | TC | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Readings | Maintenance Operations | 1 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Readings | Operations Counter AF | 191 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Readings | Operations Counter AL | 191 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Readings | Operations This Read Vac | 1 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Readings | Switching Operations | 0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Readings | Unknown Operations | 0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Readings | 9 Month Operations | 0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Readings | Unknown Operations | 0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Readings | Switching Operations | 1 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Readings | Operations This Read Vac | 4 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Readings | Operations Counter AL | 195 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Readings | Operations Counter AF | 195 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Readings | General Comments | | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Patrol Inspection | General Comments | | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Readings | Fault Operations Ground | 0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Readings | Fault Operations A Ø | 3 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Readings | Fault Adjusted Amps A Phase V | 30.57 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Readings | Amps C Ø | 23.0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Readings | Amps B Ø | 24.0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Readings | Amps A Ø | 23.0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | YD000170 | Yard | 778-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | YD000170 | Yard | 778-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | YD000170 | Yard | 778-Yard | Yard Patrol Inspection | Clear of Trash? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | YD000170 | Yard | 778-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | YD000170 | Yard | 778-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | YD000170 | Yard | 778-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Readings | Unknown Operations | 0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Readings | Switching Operations | 0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Readings | Operations This Read Vac | 0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Readings | Operations Counter AL | 191 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Readings | 9 Month Operations | 1 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Readings | Amps A Ø | 66.0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Readings | Amps B Ø | 36.0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Readings | Amps C Ø | 72.0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Readings | Operations Counter AF | 191 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Readings | Maintenance Operations | 0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Readings | General Comments | | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Patrol Inspection | General Comments | | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Readings | Fault Operations Ground | 0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000727 | BreakerVacuum | 480-1621 | VCB Readings | Fault Operations Ground | 0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000543 | BreakerVacuum | 370-4732 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Readings | Amps A Ø | 54.0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Readings | Amps B Ø | 64.0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Readings | Amps C Ø | 29.0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Readings | Fault Adjusted Amps C Phase V | 15.07 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Readings | Fault Operations C Ø | 1 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Readings | Fault Operations Ground | 0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Readings | Follow-up Action Required? | n | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | LTCMechanism | 793-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Patrol Inspection | General Comments | | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Readings | General Comments | TC, C-G ops | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Readings | Maintenance Operations | 1 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Readings | Operations Counter AF | 204 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Readings | Operations Counter AL | 204 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Readings | Operations This Read Vac | 2 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Readings | Switching Operations | 0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Readings | Unknown Operations | 0 | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0110 | Regulator | 562-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0110 | Regulator | 562-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0110 | Regulator | 562-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0110 | Regulator | 562-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0110 | Regulator | 562-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 37684 | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0110 | Regulator | 562-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 122.7 | volts |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0110 | Regulator | 562-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0110 | Regulator | 562-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0110 | Regulator | 562-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0110 | Regulator | 562-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0110 | Regulator | 562-1 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0110 | Regulator | 562-1 A | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0110 | Regulator | 562-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0110 | Regulator | 562-1 A | Regulator Patrol Inspection | General Comments | | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0110 | Regulator | 562-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0110 | Regulator | 562-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0110 | Regulator | 562-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0110 | Regulator | 562-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0110 | Regulator | 562-1 A | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0110 | Regulator | 562-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0110 | Regulator | 562-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0110 | Regulator | 562-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0110 | Regulator | 562-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000542 | BreakerVacuum | 370-4731 | VCB Readings | 9 Month Operations | 4 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Readings | Unknown Operations | 0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Readings | Switching Operations | 0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Readings | Operations This Read Vac | 0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Readings | Operations Counter AL | 181 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Readings | Operations Counter AF | 181 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Readings | General Comments | | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | LTCMechanism | 793-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | LTCMechanism | 793-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | LTCMechanism | 793-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | LTCMechanism | 793-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | LTCMechanism | 793-1 | LTC Counter Readings | LTC Operations Since Last Insp | 489 | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | LTCMechanism | 793-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | LTCMechanism | 793-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | LTCMechanism | 793-1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | LTCMechanism | 793-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | LTCMechanism | 793-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | LTCMechanism | 793-1 | LTC Counter Readings | LTC As Left Counter | 21279 | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | LTCMechanism | 793-1 | LTC Counter Readings | LTC As Found Counter | 21276 | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | LTCMechanism | 793-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | LTCMechanism | 793-1 | LTC Counter Readings | General Comments | | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | LTCMechanism | 793-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Patrol Inspection | General Comments | | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Readings | Fault Operations Ground | 0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Readings | 9 Month Operations | 2 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Readings | Amps C Ø | 28.0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Readings | Amps B Ø | 23.0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Readings | Amps A Ø | 26.0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | BK000541 | BreakerVacuum | 370-4730 | VCB Readings | 9 Month Operations | 0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000728 | BreakerVacuum | 480-1623 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Readings | Fault Operations Ground | 0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Readings | Follow-up Action Required? | n | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Patrol Inspection | General Comments | | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Readings | General Comments | TC | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | LTCMechanism | 480-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1409 | Regulator | 866-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 49151 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1409 | Regulator | 866-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.3 | volts |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1409 | Regulator | 866-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1409 | Regulator | 866-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1409 | Regulator | 866-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1409 | Regulator | 866-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1409 | Regulator | 866-1 A | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1409 | Regulator | 866-1 A | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0327 | NonLTC | 375-1 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0327 | NonLTC | 375-1 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | ST000217 | Structure | 693-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | ST000217 | Structure | 693-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | ST000217 | Structure | 693-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | ST000217 | Structure | 693-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | ST000217 | Structure | 693-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | ST000217 | Structure | 693-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | ST000217 | Structure | 693-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | ST000217 | Structure | 693-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | ST000217 | Structure | 693-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | ST000217 | Structure | 693-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | ST000217 | Structure | 693-Structure | Structure Patrol Inspection | UG Pothead Condition Good? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | ST000217 | Structure | 693-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1409 | Regulator | 866-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1409 | Regulator | 866-1 A | Regulator Patrol Inspection | General Comments | | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1409 | Regulator | 866-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1409 | Regulator | 866-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1409 | Regulator | 866-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1409 | Regulator | 866-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1409 | Regulator | 866-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1409 | Regulator | 866-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | LTCMechanism | 480-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | LTCMechanism | 480-1 | LTC Counter Readings | LTC Operations Since Last Insp | 233 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | LTCMechanism | 480-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1409 | Regulator | 866-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1409 | Regulator | 866-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1409 | Regulator | 866-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1409 | Regulator | 866-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | LTCMechanism | 480-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | LTCMechanism | 480-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | ST000217 | Structure | 693-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | ST000217 | Structure | 693-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | ST000217 | Structure | 693-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | ST000217 | Structure | 693-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | ST000217 | Structure | 693-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | LTCMechanism | 480-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | LTCMechanism | 480-1 | LTC Counter Readings | General Comments | | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | LTCMechanism | 480-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Readings | 9 Month Operations | 1 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Readings | Amps A Ø | 85.0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Readings | Amps B Ø | 61.0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | LTCMechanism | 480-1 | LTC Counter Readings | LTC As Found Counter | 696348 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1409 | Regulator | 866-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1409 | Regulator | 866-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1409 | Regulator | 866-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | R1409 | Regulator | 866-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | LTCMechanism | 480-1 | LTC Counter Readings | LTC As Left Counter | 696356 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | LTCMechanism | 480-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | LTCMechanism | 480-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | LTCMechanism | 480-1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | LTCMechanism | 480-1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | ST000217 | Structure | 693-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | ST000217 | Structure | 693-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | ST000217 | Structure | 693-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | ST000217 | Structure | 693-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | n | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Readings | Amps C Ø | 69.0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | ST000217 | Structure | 693-Structure | Structure Patrol Inspection | General Comments | Xfmr fuse barrels and spares are exposing fibers | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | ST000217 | Structure | 693-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0327 | NonLTC | 375-1 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0327 | NonLTC | 375-1 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0327 | NonLTC | 375-1 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0327 | NonLTC | 375-1 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0327 | NonLTC | 375-1 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0327 | NonLTC | 375-1 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0327 | NonLTC | 375-1 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0327 | NonLTC | 375-1 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0327 | NonLTC | 375-1 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0327 | NonLTC | 375-1 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0327 | NonLTC | 375-1 B | NonLTC Transformer Readings | General Comments | | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0327 | NonLTC | 375-1 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0327 | NonLTC | 375-1 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0327 | NonLTC | 375-1 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 70.00 | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0327 | NonLTC | 375-1 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 65.00 | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0327 | NonLTC | 375-1 B | NonLTC Transformer Readings | Oil Temp Max | 30 | °C |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0327 | NonLTC | 375-1 B | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0327 | NonLTC | 375-1 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0327 | NonLTC | 375-1 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0327 | NonLTC | 375-1 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | C0327 | NonLTC | 375-1 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | LTCC000842 | LTCControl | 433-2 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | LTCC000842 | LTCControl | 433-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | LTCC000842 | LTCControl | 433-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0910 | Regulator | 797-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0910 | Regulator | 797-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0910 | Regulator | 797-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0910 | Regulator | 797-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0910 | Regulator | 797-1 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MX0350 | RecloserElectronic | 778-0222 | Recloser Electronic Patrol Inspection | Amps A Ø | 22.0 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MX0350 | RecloserElectronic | 778-0222 | Recloser Electronic Patrol Inspection | Amps B Ø | 17.0 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MX0350 | RecloserElectronic | 778-0222 | Recloser Electronic Patrol Inspection | Amps C Ø | 45.0 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MX0350 | RecloserElectronic | 778-0222 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MX0350 | RecloserElectronic | 778-0222 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MX0350 | RecloserElectronic | 778-0222 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MX0350 | RecloserElectronic | 778-0222 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MX0350 | RecloserElectronic | 778-0222 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MX0350 | RecloserElectronic | 778-0222 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MX0350 | RecloserElectronic | 778-0222 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MX0350 | RecloserElectronic | 778-0222 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MX0350 | RecloserElectronic | 778-0222 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MX0350 | RecloserElectronic | 778-0222 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MX0350 | RecloserElectronic | 778-0222 | Recloser Electronic Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MX0350 | RecloserElectronic | 778-0222 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MX0350 | RecloserElectronic | 778-0222 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MX0350 | RecloserElectronic | 778-0222 | Recloser Electronic Patrol Inspection | Operations Counter | 31 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MX0350 | RecloserElectronic | 778-0222 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MX0350 | RecloserElectronic | 778-0222 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MX0350 | RecloserElectronic | 778-0222 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0910 | Regulator | 797-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0910 | Regulator | 797-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0910 | Regulator | 797-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0910 | Regulator | 797-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0910 | Regulator | 797-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | LTCC000842 | LTCControl | 433-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | LTCMechanism | 843-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | LTCMechanism | 843-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | LTCMechanism | 843-1 | LTC Counter Readings | General Comments | | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | LTCMechanism | 843-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | LTCMechanism | 843-1 | LTC Counter Readings | LTC As Found Counter | 417573 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | LTCMechanism | 843-1 | LTC Counter Readings | LTC As Left Counter | 417588 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | LTCMechanism | 843-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | LTCMechanism | 843-1 | LTC Counter Readings | LTC Current Tap Position | 2R | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | LTCMechanism | 843-1 | LTC Counter Readings | LTC Max Tap Position | 9R | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | LTCMechanism | 843-1 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | LTCMechanism | 843-1 | LTC Counter Readings | LTC Operations Since Last Insp | 998 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | LTCMechanism | 843-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | LTCMechanism | 843-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | LTCMechanism | 843-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | YD000170 | Yard | 778-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | YD000170 | Yard | 778-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | YD000170 | Yard | 778-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | YD000170 | Yard | 778-Yard | Yard Patrol Inspection | General Comments | | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | YD000170 | Yard | 778-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | YD000170 | Yard | 778-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | YD000170 | Yard | 778-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | YD000170 | Yard | 778-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | LTCMechanism | 480-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Readings | Maintenance Operations | 1 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Readings | Operations Counter AF | 172 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Readings | Operations Counter AL | 172 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Readings | Operations This Read Vac | 1 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Readings | Switching Operations | 0 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BK000434 | BreakerVacuum | 480-1622 | VCB Readings | Unknown Operations | 0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BX1057 | RecloserHydraulic | 433-0625 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 5.0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BX1057 | RecloserHydraulic | 433-0625 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 5.0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BX1057 | RecloserHydraulic | 433-0625 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 5.0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BX1057 | RecloserHydraulic | 433-0625 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | FE000233 | Fence | 480-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | FE000233 | Fence | 480-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | FE000233 | Fence | 480-Fence | Fence Patrol Inspection | General Comments | | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | FE000233 | Fence | 480-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | FE000233 | Fence | 480-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | FE000233 | Fence | 480-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | FE000233 | Fence | 480-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | FE000233 | Fence | 480-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | FE000233 | Fence | 480-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | FE000233 | Fence | 480-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | FE000233 | Fence | 480-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | FE000233 | Fence | 480-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | FE000233 | Fence | 480-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BX1057 | RecloserHydraulic | 433-0625 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BX1057 | RecloserHydraulic | 433-0625 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BX1057 | RecloserHydraulic | 433-0625 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BX1057 | RecloserHydraulic | 433-0625 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BX1057 | RecloserHydraulic | 433-0625 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BX1057 | RecloserHydraulic | 433-0625 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | FE000233 | Fence | 480-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | FE000233 | Fence | 480-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | FE000233 | Fence | 480-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BX1057 | RecloserHydraulic | 433-0625 | Recloser Hydraulic Patrol Inspection | Operations Counter | 404 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BX1057 | RecloserHydraulic | 433-0625 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BX1057 | RecloserHydraulic | 433-0625 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0910 | Regulator | 797-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0910 | Regulator | 797-1 C | Regulator Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0910 | Regulator | 797-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0910 | Regulator | 797-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0910 | Regulator | 797-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 127066 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0910 | Regulator | 797-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0910 | Regulator | 797-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0910 | Regulator | 797-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0910 | Regulator | 797-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0910 | Regulator | 797-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0910 | Regulator | 797-1 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0910 | Regulator | 797-1 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0910 | Regulator | 797-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0910 | Regulator | 797-1 C | Regulator Patrol Inspection | General Comments | ok | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | LTCC000842 | LTCControl | 433-2 | LTC Control Insp | All Connections OK? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | LTCC000842 | LTCControl | 433-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | LTCC000842 | LTCControl | 433-2 | LTC Control Insp | General Comments | | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | LTCC000842 | LTCControl | 433-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Readings | Unknown Operations | 0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Readings | Amps C Ø | 175.0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Readings | Amps B Ø | 175.0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Readings | Amps A Ø | 150.0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Readings | 9 Month Operations | 6 | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1140 | Regulator | 693-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1140 | Regulator | 693-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | BAT001609 | Battery | 797-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | BAT001609 | Battery | 797-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 58 | °F |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | BAT001609 | Battery | 797-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | BAT001609 | Battery | 797-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | BAT001609 | Battery | 797-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | BAT001609 | Battery | 797-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | BAT001609 | Battery | 797-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | BAT001609 | Battery | 797-Battery Bank | Battery Patrol Inspection | General Comments | ok | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | BAT001609 | Battery | 797-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.5 | VDC |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | BAT001609 | Battery | 797-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.5 | VDC |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | BCH001099 | Charger | 008-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BAT001659 | Battery | 576-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BAT001659 | Battery | 576-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 63 | °F |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BAT001659 | Battery | 576-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BAT001659 | Battery | 576-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BAT001659 | Battery | 576-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | BAT001609 | Battery | 797-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | BAT001609 | Battery | 797-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BAT001659 | Battery | 576-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BAT001659 | Battery | 576-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BAT001659 | Battery | 576-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BAT001659 | Battery | 576-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 28.2 | VDC |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BAT001659 | Battery | 576-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.9 | VDC |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BAT001659 | Battery | 576-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BAT001659 | Battery | 576-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Unreadable | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Readings | General Comments | | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Patrol Inspection | General Comments | Needs new nitro gauge. Has moisture in it and can barely read it. | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Readings | Operations Counter AF | 179 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Readings | General Comments | | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Patrol Inspection | General Comments | | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Readings | Follow-up Action Required? | n | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Readings | 9 Month Operations | 0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Readings | Amps A Ø | 375.0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Readings | Amps B Ø | 415.0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Readings | Amps C Ø | 380.0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | BCH001099 | Charger | 008-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 136.2 | VDC |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | BCH001099 | Charger | 008-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | BCH001099 | Charger | 008-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | BCH001099 | Charger | 008-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | BCH001099 | Charger | 008-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Readings | Fault Operations Ground | 0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Readings | Fault Operations C Ø | 2 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Readings | Fault Operations B Ø | 2 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Readings | Fault Adjusted Amps C Phase V | 11.99 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Readings | Fault Adjusted Amps B Phase V | 11.99 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Patrol Inspection | General Comments | | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Readings | General Comments | | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Readings | Operations Counter AF | 148 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Readings | Operations Counter AL | 148 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Readings | Switching Operations | 0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK000576 | BreakerVacuum | 433-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Readings | Totalizer Meter Reading | .3438 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Readings | Oil Temp Present | 26 | °C |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Readings | Oil Temp Max | 26 | °C |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Readings | LTC Totalizer Reading | 1650.24 | kw |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Readings | General Comments | | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Readings | Amps C Ø | 85.0 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Readings | Amps B Ø | 77.0 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Readings | Amps A Ø | 73.0 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Readings | 9 Month Operations | 2 | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | LTCC000261 | LTCControl | 793-1 | LTC Control Insp | LTC Output Voltage Level | 123.4 | VAC |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | LTCC000261 | LTCControl | 793-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | LTCC000261 | LTCControl | 793-1 | LTC Control Insp | General Comments | | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | LTCC000261 | LTCControl | 793-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | LTCC000261 | LTCControl | 793-1 | LTC Control Insp | All Connections OK? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | LTCMechanism | 433-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 919.44 | kw |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0223 | NonLTC | 693-1 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | LTCC000261 | LTCControl | 793-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | LTCC000261 | LTCControl | 793-1 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | LTCC000261 | LTCControl | 793-1 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Readings | Unknown Operations | 0 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Readings | Switching Operations | 0 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Readings | Operations This Read Vac | 1 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Readings | Operations Counter AL | 192 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Readings | Operations Counter AF | 192 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Readings | Maintenance Operations | 1 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Readings | General Comments | TC | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Patrol Inspection | General Comments | | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Readings | Follow-up Action Required? | n | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BK000722 | BreakerVacuum | 866-1618 | VCB Readings | Fault Operations Ground | 0 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BCH001554 | Charger | 843-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BCH001554 | Charger | 843-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BCH001554 | Charger | 843-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BCH001554 | Charger | 843-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BCH001554 | Charger | 843-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.1 | amps |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BCH001554 | Charger | 843-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BCH001554 | Charger | 843-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | FE000126 | Fence | 008-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | FE000126 | Fence | 008-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | FE000126 | Fence | 008-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | FE000126 | Fence | 008-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | FE000126 | Fence | 008-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | FE000126 | Fence | 008-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | FE000126 | Fence | 008-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | FE000126 | Fence | 008-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | FE000126 | Fence | 008-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | FE000126 | Fence | 008-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | FE000126 | Fence | 008-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | FE000126 | Fence | 008-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | FE000126 | Fence | 008-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | FE000126 | Fence | 008-Fence | Fence Patrol Inspection | General Comments | | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | FE000126 | Fence | 008-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | FE000126 | Fence | 008-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | B0469 | WithLTC | 433-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BCH001554 | Charger | 843-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.450 | millivolts |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | W0295 | WithLTC | 480-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Readings | General Comments | | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Readings | LTC Totalizer Reading | 4106.88 | kw |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1142 | Regulator | 693-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1142 | Regulator | 693-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1142 | Regulator | 693-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1142 | Regulator | 693-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1142 | Regulator | 693-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1142 | Regulator | 693-1 C | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1142 | Regulator | 693-1 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1142 | Regulator | 693-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Readings | Totalizer Meter Reading | .4278 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 200.00 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Readings | 9 Month Operations | 2 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Readings | Amps A Ø | 100.0 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Readings | Amps B Ø | 100.0 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Readings | Amps C Ø | 80.0 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Readings | Fault Operations Ground | 0 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Readings | Follow-up Action Required? | n | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Patrol Inspection | General Comments | | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Readings | General Comments | | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Readings | Maintenance Operations | 0 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KR0110 | Regulator | 562-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1142 | Regulator | 693-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Readings | 9 Month Operations | 1 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Readings | Fault Operations Ground | 0 | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Readings | Follow-up Action Required? | n | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Patrol Inspection | General Comments | | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Readings | General Comments | | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Readings | Maintenance Operations | 1 | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Readings | Operations Counter AF | 137 | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Readings | Operations Counter AL | 138 | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Readings | Operations This Read Vac | 1 | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1142 | Regulator | 693-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1142 | Regulator | 693-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1142 | Regulator | 693-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 185388 | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Readings | Switching Operations | 0 | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | KB0071 | BreakerVacuum | 008-3424 | VCB Readings | Unknown Operations | 0 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | W0322 | WithLTC | 576-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 52.50 | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1142 | Regulator | 693-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1142 | Regulator | 693-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1142 | Regulator | 693-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1235.52 | kw |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Readings | General Comments | ok | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Patrol Inspection | General Comments | ok | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | BCH001099 | Charger | 008-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.100 | millivolts |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | BCH001099 | Charger | 008-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 136.2 | VDC |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1142 | Regulator | 693-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1142 | Regulator | 693-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1142 | Regulator | 693-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1142 | Regulator | 693-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1142 | Regulator | 693-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1142 | Regulator | 693-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1140 | Regulator | 693-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1140 | Regulator | 693-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1140 | Regulator | 693-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1140 | Regulator | 693-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 86243 | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1140 | Regulator | 693-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1140 | Regulator | 693-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1140 | Regulator | 693-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1140 | Regulator | 693-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1140 | Regulator | 693-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1140 | Regulator | 693-1 A | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1140 | Regulator | 693-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1140 | Regulator | 693-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1140 | Regulator | 693-1 A | Regulator Patrol Inspection | General Comments | | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1140 | Regulator | 693-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1140 | Regulator | 693-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1140 | Regulator | 693-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1140 | Regulator | 693-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1140 | Regulator | 693-1 A | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1140 | Regulator | 693-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1140 | Regulator | 693-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1140 | Regulator | 693-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Readings | Unknown Operations | 0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Readings | Switching Operations | 0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Readings | Operations This Read Vac | 4 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001285 | BreakerVacuum | 433-0627 | VCB Readings | Operations Counter AL | 179 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Readings | Operations Counter AF | 161 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Readings | Operations Counter AL | 161 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Readings | Operations This Read Vac | 0 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Readings | Switching Operations | 0 | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | MB0121 | BreakerVacuum | 778-0221 | VCB Readings | Unknown Operations | 0 | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1142 | Regulator | 693-1 C | Regulator Patrol Inspection | General Comments | | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | R1142 | Regulator | 693-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | BCH001537 | Charger | 797-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.300 | millivolts |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | BCH001537 | Charger | 797-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.1 | VDC |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | BCH001537 | Charger | 797-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.1 | VDC |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | BCH001537 | Charger | 797-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .2 | amps |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | BCH001537 | Charger | 797-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | BCH001537 | Charger | 797-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | BCH001537 | Charger | 797-Battery Charger | Battery Charger Patrol Insp | General Comments | ok | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | BCH001537 | Charger | 797-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .5406 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Readings | Oil Temp Max | 30 | °C |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .5148 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1297.44 | kw |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Readings | General Comments | | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | W0251 | NonLTC | 866-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Readings | Oil Temp Present | 29 | °C |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | C0343 | NonLTC | 797-1 | NonLTC Transformer Readings | Oil Temp Max | 29 | °C |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | ST000094 | Structure | 370-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | ST000094 | Structure | 370-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | ST000094 | Structure | 370-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | ST000094 | Structure | 370-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | ST000094 | Structure | 370-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | ST000094 | Structure | 370-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | ST000094 | Structure | 370-Structure | Structure Patrol Inspection | General Comments | | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | ST000094 | Structure | 370-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | YD000450 | Yard | 562-Yard | Yard Patrol Inspection | Ambient Temp | 56 | °F |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | YD000450 | Yard | 562-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | YD000450 | Yard | 562-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | YD000450 | Yard | 562-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | YD000450 | Yard | 562-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | YD000450 | Yard | 562-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | YD000450 | Yard | 562-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | YD000450 | Yard | 562-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | YD000450 | Yard | 562-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | YD000450 | Yard | 562-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | YD000450 | Yard | 562-Yard | Yard Patrol Inspection | General Comments | | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | YD000450 | Yard | 562-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | YD000450 | Yard | 562-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | YD000450 | Yard | 562-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | YD000450 | Yard | 562-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | ST000094 | Structure | 370-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | ST000094 | Structure | 370-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | ST000094 | Structure | 370-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | ST000094 | Structure | 370-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | ST000094 | Structure | 370-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | ST000094 | Structure | 370-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | ST000094 | Structure | 370-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | ST000094 | Structure | 370-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | YD000088 | Yard | 370-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | YD000088 | Yard | 370-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | YD000088 | Yard | 370-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | YD000088 | Yard | 370-Yard | Yard Patrol Inspection | General Comments | | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | YD000088 | Yard | 370-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | YD000088 | Yard | 370-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | YD000088 | Yard | 370-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | YD000088 | Yard | 370-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | YD000088 | Yard | 370-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | YD000088 | Yard | 370-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | YD000088 | Yard | 370-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | YD000088 | Yard | 370-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | YD000088 | Yard | 370-Yard | Yard Patrol Inspection | Ambient Temp | 58 | °F |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | FE000090 | Fence | 370-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | FE000090 | Fence | 370-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | FE000090 | Fence | 370-Fence | Fence Patrol Inspection | General Comments | | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | FE000090 | Fence | 370-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | FE000090 | Fence | 370-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | FE000090 | Fence | 370-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | FE000090 | Fence | 370-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | FE000090 | Fence | 370-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | FE000090 | Fence | 370-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | FE000090 | Fence | 370-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | FE000090 | Fence | 370-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | FE000090 | Fence | 370-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | FE000090 | Fence | 370-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Readings | Amps C Ø | 100.0 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Readings | Amps B Ø | 30.0 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Readings | Amps A Ø | 30.0 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Readings | 9 Month Operations | 1 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BCH001221 | Charger | 480-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BCH001221 | Charger | 480-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BCH001221 | Charger | 480-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BCH001221 | Charger | 480-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BCH001221 | Charger | 480-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.6 | amps |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BCH001221 | Charger | 480-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 54.9 | VDC |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BCH001221 | Charger | 480-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 54.9 | VDC |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BCH001221 | Charger | 480-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.100 | millivolts |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BAT001276 | Battery | Retired Distribution | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BAT001276 | Battery | Retired Distribution | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BAT001276 | Battery | Retired Distribution | Battery Patrol Inspection | Positive DC Ground | 26.8 | VDC |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BAT001276 | Battery | Retired Distribution | Battery Patrol Inspection | Negative DC Ground | 28.0 | VDC |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BAT001276 | Battery | Retired Distribution | Battery Patrol Inspection | General Comments | | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BAT001276 | Battery | Retired Distribution | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BAT001276 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BAT001276 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BAT001276 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BAT001276 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BAT001276 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Area Ambient Temp | 53 | °F |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | BAT001276 | Battery | Retired Distribution | Battery Patrol Inspection | All Connections OK? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | ST000094 | Structure | 370-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | ST000094 | Structure | 370-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | ST000094 | Structure | 370-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | ST000094 | Structure | 370-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | ST000094 | Structure | 370-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | ST000094 | Structure | 370-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | YD000211 | Yard | 866-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | YD000211 | Yard | 866-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | YD000211 | Yard | 866-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | YD000211 | Yard | 866-Yard | Yard Patrol Inspection | General Comments | | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | YD000211 | Yard | 866-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | YD000211 | Yard | 866-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | YD000211 | Yard | 866-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | YD000211 | Yard | 866-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | YD000211 | Yard | 866-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | YD000211 | Yard | 866-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | YD000211 | Yard | 866-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | YD000211 | Yard | 866-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | YD000211 | Yard | 866-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | YD000211 | Yard | 866-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Patrol Inspection | General Comments | | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Readings | Follow-up Action Required? | n | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Readings | Fault Operations Ground | 0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Readings | Amps C Ø | 185.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Readings | Amps B Ø | 205.0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Readings | Amps A Ø | 175.0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Readings | 9 Month Operations | 10 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BAT001309 | Battery | 433-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BAT001309 | Battery | 433-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 52 | °F |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BAT001309 | Battery | 433-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BAT001309 | Battery | 433-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BAT001309 | Battery | 433-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BAT001309 | Battery | 433-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BAT001309 | Battery | 433-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BAT001309 | Battery | 433-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BAT001309 | Battery | 433-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BAT001309 | Battery | 433-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BAT001309 | Battery | 433-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BAT001309 | Battery | 433-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BAT001309 | Battery | 433-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BAT001309 | Battery | 433-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BCH001248 | Charger | 433-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BCH001248 | Charger | 433-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BCH001248 | Charger | 433-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BCH001248 | Charger | 433-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.0 | amps |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BCH001248 | Charger | 433-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BCH001248 | Charger | 433-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BCH001248 | Charger | 433-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BCH001248 | Charger | 433-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | FE000170 | Fence | 778-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | FE000170 | Fence | 778-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | FE000170 | Fence | 778-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | FE000170 | Fence | 778-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | FE000170 | Fence | 778-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | FE000170 | Fence | 778-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | FE000170 | Fence | 778-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | FE000170 | Fence | 778-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | FE000090 | Fence | 370-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | FE000090 | Fence | 370-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | FE000090 | Fence | 370-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | ST000092 | Structure | 375-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | ST000092 | Structure | 375-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | ST000092 | Structure | 375-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | ST000092 | Structure | 375-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | ST000092 | Structure | 375-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | ST000092 | Structure | 375-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | ST000092 | Structure | 375-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | ST000092 | Structure | 375-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | ST000092 | Structure | 375-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | ST000092 | Structure | 375-Structure | Structure Patrol Inspection | General Comments | | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | ST000092 | Structure | 375-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | ST000092 | Structure | 375-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | ST000092 | Structure | 375-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | ST000092 | Structure | 375-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | ST000092 | Structure | 375-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | ST000092 | Structure | 375-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | ST000092 | Structure | 375-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | YD000086 | Yard | 375-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | YD000086 | Yard | 375-Yard | Yard Patrol Inspection | General Comments | | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | YD000086 | Yard | 375-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | YD000086 | Yard | 375-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | YD000086 | Yard | 375-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | YD000086 | Yard | 375-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | YD000086 | Yard | 375-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | YD000086 | Yard | 375-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | YD000086 | Yard | 375-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | YD000086 | Yard | 375-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | YD000086 | Yard | 375-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | YD000086 | Yard | 375-Yard | Yard Patrol Inspection | Ambient Temp | 54 | °F |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | FE000088 | Fence | 375-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | FE000088 | Fence | 375-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | FE000088 | Fence | 375-Fence | Fence Patrol Inspection | General Comments | | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | FE000088 | Fence | 375-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | FE000088 | Fence | 375-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | FE000088 | Fence | 375-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | FE000088 | Fence | 375-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | FE000088 | Fence | 375-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | FE000088 | Fence | 375-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | FE000088 | Fence | 375-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | FE000088 | Fence | 375-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | FE000088 | Fence | 375-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | FE000088 | Fence | 375-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | FE000088 | Fence | 375-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | FE000088 | Fence | 375-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/3/2023 7:15 | Distribution | Bens Branch Quarterly Inspection | FE000088 | Fence | 375-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Readings | Unknown Operations | 0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Readings | Switching Operations | 2 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Readings | Operations This Read Vac | 2 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Readings | Operations Counter AL | 188 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Readings | Operations Counter AF | 186 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Readings | Maintenance Operations | 0 | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | BK001565 | BreakerVacuum | 433-0628 | VCB Readings | General Comments | | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | ST000179 | Structure | 843-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | ST000179 | Structure | 843-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | ST000179 | Structure | 843-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | ST000179 | Structure | 843-Structure | Structure Patrol Inspection | General Comments | | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | ST000179 | Structure | 843-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | ST000179 | Structure | 843-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | ST000179 | Structure | 843-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | ST000179 | Structure | 843-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | ST000179 | Structure | 843-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | ST000179 | Structure | 843-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | ST000179 | Structure | 843-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | ST000179 | Structure | 843-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | ST000179 | Structure | 843-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | YD000172 | Yard | 843-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | YD000172 | Yard | 843-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | YD000172 | Yard | 843-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | YD000172 | Yard | 843-Yard | Yard Patrol Inspection | General Comments | | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | YD000172 | Yard | 843-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | YD000172 | Yard | 843-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | YD000172 | Yard | 843-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | YD000172 | Yard | 843-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | YD000172 | Yard | 843-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | YD000172 | Yard | 843-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | YD000172 | Yard | 843-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | YD000172 | Yard | 843-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | YD000172 | Yard | 843-Yard | Yard Patrol Inspection | Ambient Temp | 59 | °F |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | FE000173 | Fence | 843-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | FE000173 | Fence | 843-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | FE000173 | Fence | 843-Fence | Fence Patrol Inspection | General Comments | | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | FE000173 | Fence | 843-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | FE000173 | Fence | 843-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | FE000173 | Fence | 843-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | FE000173 | Fence | 843-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | FE000173 | Fence | 843-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | FE000173 | Fence | 843-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | FE000173 | Fence | 843-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | FE000173 | Fence | 843-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | FE000173 | Fence | 843-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | FE000173 | Fence | 843-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | FE000173 | Fence | 843-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | FE000173 | Fence | 843-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | FE000173 | Fence | 843-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BCH000257 | Charger | 576-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.300 | millivolts |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BCH000257 | Charger | 576-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.1 | VDC |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BCH000257 | Charger | 576-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.1 | VDC |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BCH000257 | Charger | 576-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.1 | amps |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BCH000257 | Charger | 576-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BCH000257 | Charger | 576-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BCH000257 | Charger | 576-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | BCH000257 | Charger | 576-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | YD000210 | Yard | 693-Yard | Yard Patrol Inspection | Ambient Temp | 52 | °F |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | YD000210 | Yard | 693-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | YD000210 | Yard | 693-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | YD000210 | Yard | 693-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | YD000210 | Yard | 693-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | YD000210 | Yard | 693-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | YD000210 | Yard | 693-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | YD000468 | Yard | 793-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | YD000468 | Yard | 793-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | YD000468 | Yard | 793-Yard | Yard Patrol Inspection | General Comments | | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | YD000468 | Yard | 793-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | YD000468 | Yard | 793-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | YD000468 | Yard | 793-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | YD000468 | Yard | 793-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | YD000468 | Yard | 793-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | YD000468 | Yard | 793-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | YD000468 | Yard | 793-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | YD000468 | Yard | 793-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | YD000468 | Yard | 793-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | YD000468 | Yard | 793-Yard | Yard Patrol Inspection | Ambient Temp | 70 | °F |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0808 | RecloserElectronic | 793-2438 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0808 | RecloserElectronic | 793-2438 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0808 | RecloserElectronic | 793-2438 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0808 | RecloserElectronic | 793-2438 | Recloser Electronic Patrol Inspection | Operations Counter | 895 | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0808 | RecloserElectronic | 793-2438 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0808 | RecloserElectronic | 793-2438 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0808 | RecloserElectronic | 793-2438 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0808 | RecloserElectronic | 793-2438 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0808 | RecloserElectronic | 793-2438 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0808 | RecloserElectronic | 793-2438 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0808 | RecloserElectronic | 793-2438 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0808 | RecloserElectronic | 793-2438 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0808 | RecloserElectronic | 793-2438 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0808 | RecloserElectronic | 793-2438 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0808 | RecloserElectronic | 793-2438 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0808 | RecloserElectronic | 793-2438 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0808 | RecloserElectronic | 793-2438 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0808 | RecloserElectronic | 793-2438 | Recloser Electronic Patrol Inspection | Amps C Ø | 10 | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0808 | RecloserElectronic | 793-2438 | Recloser Electronic Patrol Inspection | Amps B Ø | 10 | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | FE000210 | Fence | 693-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | n | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | FE000210 | Fence | 693-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | FE000210 | Fence | 693-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | n | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | FE000210 | Fence | 693-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | FE000210 | Fence | 693-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | FE000210 | Fence | 693-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | BX0808 | RecloserElectronic | 793-2438 | Recloser Electronic Patrol Inspection | Amps A Ø | 20 | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | FE000210 | Fence | 693-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | n | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | FE000210 | Fence | 693-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | FE000210 | Fence | 693-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | FE000210 | Fence | 693-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | FE000210 | Fence | 693-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | FE000210 | Fence | 693-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | FE000210 | Fence | 693-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | FE000210 | Fence | 693-Fence | Fence Patrol Inspection | General Comments | Several pieces of pipe are badly rusted. Fabric has been cut in places and tied together with wire. Barb wire has been broken in places | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | FE000210 | Fence | 693-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | FE000210 | Fence | 693-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | ST000179 | Structure | 843-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | ST000179 | Structure | 843-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | ST000179 | Structure | 843-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | ST000179 | Structure | 843-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | ST000179 | Structure | 843-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | ST000179 | Structure | 843-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | ST000179 | Structure | 843-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | ST000179 | Structure | 843-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | ST000179 | Structure | 843-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | LTCC000922 | LTCControl | 778-1 | LTC Control Insp | General Comments | | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | LTCC000922 | LTCControl | 778-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | LTCC000922 | LTCControl | 778-1 | LTC Control Insp | All Connections OK? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BAT001508 | Battery | 866-Battery Bank 1 | Battery Patrol Inspection | All Connections OK? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BAT001508 | Battery | 866-Battery Bank 1 | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BAT001508 | Battery | 866-Battery Bank 1 | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BAT001508 | Battery | 866-Battery Bank 1 | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BAT001508 | Battery | 866-Battery Bank 1 | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BAT001508 | Battery | 866-Battery Bank 1 | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BAT001508 | Battery | 866-Battery Bank 1 | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BAT001508 | Battery | 866-Battery Bank 1 | Battery Patrol Inspection | General Comments | | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | FE000445 | Fence | 562-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | FE000445 | Fence | 562-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | FE000445 | Fence | 562-Fence | Fence Patrol Inspection | General Comments | | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | FE000445 | Fence | 562-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | FE000445 | Fence | 562-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | FE000445 | Fence | 562-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | FE000445 | Fence | 562-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | FE000445 | Fence | 562-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | FE000445 | Fence | 562-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | FE000445 | Fence | 562-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | FE000445 | Fence | 562-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | FE000445 | Fence | 562-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | FE000445 | Fence | 562-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | FE000445 | Fence | 562-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | FE000445 | Fence | 562-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | FE000445 | Fence | 562-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BAT001508 | Battery | 866-Battery Bank 1 | Battery Patrol Inspection | Negative DC Ground | 27.6 | VDC |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BAT001508 | Battery | 866-Battery Bank 1 | Battery Patrol Inspection | Positive DC Ground | 27.5 | VDC |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BAT001508 | Battery | 866-Battery Bank 1 | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BAT001508 | Battery | 866-Battery Bank 1 | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BCH001439 | Charger | 866-Battery Charger 1 | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .700 | millivolts |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BCH001439 | Charger | 866-Battery Charger 1 | Battery Charger Patrol Insp | As Found Float Voltage | 55.2 | VDC |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BCH001439 | Charger | 866-Battery Charger 1 | Battery Charger Patrol Insp | As Left Float Voltage | 55.2 | VDC |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BCH001439 | Charger | 866-Battery Charger 1 | Battery Charger Patrol Insp | Battery Charger Current | .8 | amps |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BCH001439 | Charger | 866-Battery Charger 1 | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BCH001439 | Charger | 866-Battery Charger 1 | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BCH001439 | Charger | 866-Battery Charger 1 | Battery Charger Patrol Insp | General Comments | | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | BCH001439 | Charger | 866-Battery Charger 1 | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Readings | Unknown Operations | 0 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Readings | Switching Operations | 0 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Readings | Operations This Read Vac | 1 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Readings | Operations Counter AL | 269 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Readings | Operations Counter AF | 269 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Readings | Maintenance Operations | 1 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Readings | General Comments | | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Patrol Inspection | General Comments | | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Readings | Follow-up Action Required? | n | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Readings | Fault Operations Ground | 0 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | WB0156 | BreakerVacuum | 576-1615 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | YD000210 | Yard | 693-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | YD000210 | Yard | 693-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | YD000210 | Yard | 693-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | YD000210 | Yard | 693-Yard | Yard Patrol Inspection | General Comments | | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | YD000210 | Yard | 693-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | YD000210 | Yard | 693-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | YD000210 | Yard | 693-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | FE000211 | Fence | 866-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | FE000211 | Fence | 866-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | FE000211 | Fence | 866-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | FE000211 | Fence | 866-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | FE000211 | Fence | 866-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | FE000211 | Fence | 866-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | FE000211 | Fence | 866-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | FE000211 | Fence | 866-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | FE000211 | Fence | 866-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | FE000211 | Fence | 866-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | FE000211 | Fence | 866-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | FE000211 | Fence | 866-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | FE000211 | Fence | 866-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | FE000211 | Fence | 866-Fence | Fence Patrol Inspection | General Comments | | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | FE000211 | Fence | 866-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | FE000211 | Fence | 866-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | ST000218 | Structure | 866-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | ST000218 | Structure | 866-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | ST000218 | Structure | 866-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | ST000218 | Structure | 866-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | ST000218 | Structure | 866-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | ST000218 | Structure | 866-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | ST000218 | Structure | 866-Structure | Structure Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | ST000218 | Structure | 866-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | ST000218 | Structure | 866-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | ST000218 | Structure | 866-Structure | Structure Patrol Inspection | General Comments | | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | ST000218 | Structure | 866-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | ST000218 | Structure | 866-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | ST000218 | Structure | 866-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | ST000218 | Structure | 866-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | ST000218 | Structure | 866-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | ST000218 | Structure | 866-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | ST000218 | Structure | 866-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | ST000218 | Structure | 866-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | ST000218 | Structure | 866-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | ST000218 | Structure | 866-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | ST000218 | Structure | 866-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/2/2023 11:59 | Distribution | Greenville West Quarterly Inspection | ST000218 | Structure | 866-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | LTCC000819 | LTCControl | 480-1 | LTC Control Insp | All Connections OK? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | LTCC000819 | LTCControl | 480-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | LTCC000819 | LTCControl | 480-1 | LTC Control Insp | General Comments | | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | LTCC000819 | LTCControl | 480-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | LTCC000819 | LTCControl | 480-1 | LTC Control Insp | LTC Output Voltage Level | 123.9 | VAC |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | LTCC000819 | LTCControl | 480-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | LTCC000819 | LTCControl | 480-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | LTCC000819 | LTCControl | 480-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | LTCC000922 | LTCControl | 778-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | LTCC000922 | LTCControl | 778-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | LTCC000922 | LTCControl | 778-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | LTCC000922 | LTCControl | 778-1 | LTC Control Insp | LTC Output Voltage Level | 124.7 | VAC |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | LTCC000922 | LTCControl | 778-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | ST000135 | Structure | 008-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | ST000135 | Structure | 008-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | ST000135 | Structure | 008-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | ST000135 | Structure | 008-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | ST000135 | Structure | 008-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | ST000135 | Structure | 008-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | ST000135 | Structure | 008-Structure | Structure Patrol Inspection | Interruptrs/Puffrs Visual OK? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | ST000135 | Structure | 008-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | ST000135 | Structure | 008-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | ST000135 | Structure | 008-Structure | Structure Patrol Inspection | General Comments | Station does not use fuses. | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | ST000135 | Structure | 008-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | n | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | ST000135 | Structure | 008-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | ST000135 | Structure | 008-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | ST000135 | Structure | 008-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | ST000135 | Structure | 008-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | ST000135 | Structure | 008-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | ST000135 | Structure | 008-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | ST000135 | Structure | 008-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | ST000135 | Structure | 008-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | ST000451 | Structure | 562-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | ST000451 | Structure | 562-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | ST000451 | Structure | 562-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | ST000451 | Structure | 562-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | ST000451 | Structure | 562-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | ST000451 | Structure | 562-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | ST000451 | Structure | 562-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | ST000451 | Structure | 562-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | ST000451 | Structure | 562-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | ST000451 | Structure | 562-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | ST000451 | Structure | 562-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | ST000451 | Structure | 562-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | ST000451 | Structure | 562-Structure | Structure Patrol Inspection | General Comments | | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | ST000451 | Structure | 562-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | ST000451 | Structure | 562-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | ST000451 | Structure | 562-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | ST000451 | Structure | 562-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | ST000451 | Structure | 562-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | ST000451 | Structure | 562-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | ST000451 | Structure | 562-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | ST000451 | Structure | 562-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | ST000451 | Structure | 562-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | FE000837 | Fence | 433-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | FE000837 | Fence | 433-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | FE000837 | Fence | 433-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | FE000837 | Fence | 433-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | FE000837 | Fence | 433-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | FE000837 | Fence | 433-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | FE000837 | Fence | 433-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | FE000837 | Fence | 433-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | FE000837 | Fence | 433-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | FE000837 | Fence | 433-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | FE000837 | Fence | 433-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | FE000837 | Fence | 433-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | FE000837 | Fence | 433-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | FE000837 | Fence | 433-Fence | Fence Patrol Inspection | General Comments | | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | FE000837 | Fence | 433-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | FE000837 | Fence | 433-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | ST000201 | Structure | 797-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | ST000201 | Structure | 797-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | ST000201 | Structure | 797-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | ST000201 | Structure | 797-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | ST000201 | Structure | 797-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | ST000201 | Structure | 797-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | ST000201 | Structure | 797-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | ST000201 | Structure | 797-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | ST000201 | Structure | 797-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | ST000201 | Structure | 797-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | ST000201 | Structure | 797-Structure | Structure Patrol Inspection | General Comments | Needs enhanced wildlife discs on bus because the old style discs are falling off due to wind. | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | ST000201 | Structure | 797-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | ST000201 | Structure | 797-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | ST000201 | Structure | 797-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | ST000201 | Structure | 797-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | ST000201 | Structure | 797-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | ST000201 | Structure | 797-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | ST000201 | Structure | 797-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | ST000201 | Structure | 797-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | ST000201 | Structure | 797-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | YD000194 | Yard | 797-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | YD000194 | Yard | 797-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | YD000194 | Yard | 797-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | YD000194 | Yard | 797-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | YD000194 | Yard | 797-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | YD000194 | Yard | 797-Yard | Yard Patrol Inspection | General Comments | ok | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | YD000194 | Yard | 797-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | YD000194 | Yard | 797-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | YD000194 | Yard | 797-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | YD000194 | Yard | 797-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | YD000194 | Yard | 797-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | YD000194 | Yard | 797-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | YD000194 | Yard | 797-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | YD000194 | Yard | 797-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | YD000194 | Yard | 797-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | YD000194 | Yard | 797-Yard | Yard Patrol Inspection | Ambient Temp | 58 | °F |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | FE000196 | Fence | 797-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | FE000196 | Fence | 797-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | FE000196 | Fence | 797-Fence | Fence Patrol Inspection | General Comments | ok | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | FE000196 | Fence | 797-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | FE000196 | Fence | 797-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | FE000196 | Fence | 797-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | FE000196 | Fence | 797-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | FE000196 | Fence | 797-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | FE000196 | Fence | 797-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | FE000196 | Fence | 797-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | FE000196 | Fence | 797-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | FE000196 | Fence | 797-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | FE000196 | Fence | 797-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | FE000196 | Fence | 797-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | FE000196 | Fence | 797-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | FE000196 | Fence | 797-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | ST000135 | Structure | 008-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | ST000135 | Structure | 008-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | ST000135 | Structure | 008-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | ST000135 | Structure | 008-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | ST000135 | Structure | 008-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | ST000135 | Structure | 008-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Readings | LTC Totalizer Reading | 4919.04 | kw |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Readings | General Comments | | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Readings | General Comments | | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Readings | LTC Totalizer Reading | 4510.08 | kw |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Readings | Oil Temp Present | 26 | °C |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Readings | Totalizer Meter Reading | .9396 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 290.00 | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | M0036 | WithLTC | 843-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | YD000328 | Yard | 480-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | YD000328 | Yard | 480-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | YD000328 | Yard | 480-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | YD000328 | Yard | 480-Yard | Yard Patrol Inspection | General Comments | | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | YD000328 | Yard | 480-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | YD000328 | Yard | 480-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | YD000328 | Yard | 480-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | YD000328 | Yard | 480-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | YD000328 | Yard | 480-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | YD000328 | Yard | 480-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | YD000328 | Yard | 480-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | YD000328 | Yard | 480-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | YD000127 | Yard | 008-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | YD000127 | Yard | 008-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | YD000127 | Yard | 008-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | YD000127 | Yard | 008-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | YD000127 | Yard | 008-Yard | Yard Patrol Inspection | General Comments | Small washout on containment berm on right side of station when entering through gate. | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | YD000127 | Yard | 008-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | YD000127 | Yard | 008-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | YD000127 | Yard | 008-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | YD000127 | Yard | 008-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | YD000328 | Yard | 480-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | YD000328 | Yard | 480-Yard | Yard Patrol Inspection | Ambient Temp | 53 | °F |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | YD000127 | Yard | 008-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | YD000127 | Yard | 008-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | YD000127 | Yard | 008-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | YD000127 | Yard | 008-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | YD000127 | Yard | 008-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | YD000127 | Yard | 008-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | CH000039 | ControlHouse | 008-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | CH000039 | ControlHouse | 008-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | CH000039 | ControlHouse | 008-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | CH000039 | ControlHouse | 008-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | CH000039 | ControlHouse | 008-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | CH000039 | ControlHouse | 008-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | CH000039 | ControlHouse | 008-Control House | Control House Patrol Inspection | General Comments | | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | CH000039 | ControlHouse | 008-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | CH000039 | ControlHouse | 008-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | CH000039 | ControlHouse | 008-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | CH000039 | ControlHouse | 008-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | CH000039 | ControlHouse | 008-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | CH000039 | ControlHouse | 008-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | CH000039 | ControlHouse | 008-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | CH000039 | ControlHouse | 008-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | CH000039 | ControlHouse | 008-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | CH000039 | ControlHouse | 008-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | CH000039 | ControlHouse | 008-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | CH000039 | ControlHouse | 008-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90 | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Readings | Totalizer Meter Reading | .5124 | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | C0442 | WithLTC | 793-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | CH000397 | ControlHouse | 370-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | CH000397 | ControlHouse | 370-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | CH000397 | ControlHouse | 370-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | CH000397 | ControlHouse | 370-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | CH000397 | ControlHouse | 370-Control House | Control House Patrol Inspection | General Comments | | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | CH000397 | ControlHouse | 370-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | CH000397 | ControlHouse | 370-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | CH000397 | ControlHouse | 370-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | CH000397 | ControlHouse | 370-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | CH000397 | ControlHouse | 370-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | CH000397 | ControlHouse | 370-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | CH000397 | ControlHouse | 370-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | CH000397 | ControlHouse | 370-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | CH000397 | ControlHouse | 370-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | CH000397 | ControlHouse | 370-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | CH000397 | ControlHouse | 370-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | CH000397 | ControlHouse | 370-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Readings | General Comments | | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Readings | LTC Totalizer Reading | 1497.60 | kw |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Readings | Oil Temp Max | 37 | °C |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Readings | Oil Temp Present | 34 | °C |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Readings | Totalizer Meter Reading | .1560 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0226 | NonLTC | 693-1 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0226 | NonLTC | 693-1 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0226 | NonLTC | 693-1 C | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0226 | NonLTC | 693-1 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0226 | NonLTC | 693-1 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0226 | NonLTC | 693-1 C | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0226 | NonLTC | 693-1 C | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0226 | NonLTC | 693-1 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0226 | NonLTC | 693-1 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0226 | NonLTC | 693-1 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0226 | NonLTC | 693-1 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0226 | NonLTC | 693-1 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | FE000170 | Fence | 778-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | FE000170 | Fence | 778-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | FE000170 | Fence | 778-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | FE000170 | Fence | 778-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | FE000170 | Fence | 778-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | FE000170 | Fence | 778-Fence | Fence Patrol Inspection | General Comments | | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | FE000170 | Fence | 778-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | FE000170 | Fence | 778-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | ST000239 | Structure | 480-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | ST000239 | Structure | 480-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | ST000239 | Structure | 480-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | ST000239 | Structure | 480-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | ST000239 | Structure | 480-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | ST000239 | Structure | 480-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | ST000239 | Structure | 480-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | ST000239 | Structure | 480-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | ST000239 | Structure | 480-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | ST000239 | Structure | 480-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | ST000239 | Structure | 480-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | ST000239 | Structure | 480-Structure | Structure Patrol Inspection | General Comments | No spare fuse. | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | ST000239 | Structure | 480-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | ST000239 | Structure | 480-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | ST000239 | Structure | 480-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | ST000239 | Structure | 480-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | ST000239 | Structure | 480-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | ST000239 | Structure | 480-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | ST000239 | Structure | 480-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/2/2023 10:22 | Distribution | Greenville Quarterly Inspection | ST000239 | Structure | 480-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | LTCC000782 | LTCControl | 576-1 | LTC Control Insp | All Connections OK? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | LTCC000782 | LTCControl | 576-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | LTCC000782 | LTCControl | 576-1 | LTC Control Insp | General Comments | | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | LTCC000782 | LTCControl | 576-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | LTCC000782 | LTCControl | 576-1 | LTC Control Insp | LTC Output Voltage Level | 123.3 | VAC |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | LTCC000782 | LTCControl | 576-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | LTCC000782 | LTCControl | 576-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | LTCC000782 | LTCControl | 576-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | M0060 | WithLTC | 370-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | CH000398 | ControlHouse | 843-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | CH000398 | ControlHouse | 843-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | CH000398 | ControlHouse | 843-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | CH000398 | ControlHouse | 843-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | CH000398 | ControlHouse | 843-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | CH000398 | ControlHouse | 843-Control House | Control House Patrol Inspection | General Comments | | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | CH000398 | ControlHouse | 843-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | CH000398 | ControlHouse | 843-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | CH000398 | ControlHouse | 843-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | CH000398 | ControlHouse | 843-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | CH000398 | ControlHouse | 843-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | CH000398 | ControlHouse | 843-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | CH000398 | ControlHouse | 843-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | CH000398 | ControlHouse | 843-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | CH000398 | ControlHouse | 843-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | CH000398 | ControlHouse | 843-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | CH000398 | ControlHouse | 843-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | CH000397 | ControlHouse | 370-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/3/2023 7:34 | Distribution | Appalachia Quarterly Inspection | CH000397 | ControlHouse | 370-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | FE000463 | Fence | 793-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Readings | Amps A Ø | 0.0 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Readings | Amps B Ø | 0.0 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Readings | Amps C Ø | 0.0 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Readings | Fault Operations Ground | 0 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Readings | Follow-up Action Required? | n | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Patrol Inspection | General Comments | | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Readings | General Comments | | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Readings | Maintenance Operations | 0 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Readings | Operations Counter AF | 185 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Readings | Operations Counter AL | 185 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Readings | Operations This Read Vac | 0 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Readings | Switching Operations | 0 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Readings | Unknown Operations | 0 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0912 | Regulator | 797-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0912 | Regulator | 797-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0912 | Regulator | 797-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0912 | Regulator | 797-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0912 | Regulator | 797-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0912 | Regulator | 797-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0912 | Regulator | 797-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0912 | Regulator | 797-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0912 | Regulator | 797-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0912 | Regulator | 797-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0912 | Regulator | 797-1 B | Regulator Patrol Inspection | General Comments | ok | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0912 | Regulator | 797-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0912 | Regulator | 797-1 B | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0912 | Regulator | 797-1 B | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0912 | Regulator | 797-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0912 | Regulator | 797-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0912 | Regulator | 797-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0912 | Regulator | 797-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0912 | Regulator | 797-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0912 | Regulator | 797-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 315790 | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0912 | Regulator | 797-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0912 | Regulator | 797-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0912 | Regulator | 797-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | R0912 | Regulator | 797-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | ST000201 | Structure | 797-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 14:15 | Distribution | Calhoun Quarterly Inspection | ST000201 | Structure | 797-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0226 | NonLTC | 693-1 C | NonLTC Transformer Readings | General Comments | | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0226 | NonLTC | 693-1 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0226 | NonLTC | 693-1 C | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0226 | NonLTC | 693-1 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0226 | NonLTC | 693-1 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0226 | NonLTC | 693-1 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0226 | NonLTC | 693-1 C | NonLTC Transformer Readings | Oil Temp Max | 48 | °C |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0226 | NonLTC | 693-1 C | NonLTC Transformer Readings | Oil Temp Present | 48 | °C |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0226 | NonLTC | 693-1 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0226 | NonLTC | 693-1 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0226 | NonLTC | 693-1 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | ST000177 | Structure | 778-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | ST000177 | Structure | 778-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | ST000177 | Structure | 778-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | ST000177 | Structure | 778-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | ST000177 | Structure | 778-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | ST000177 | Structure | 778-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | ST000177 | Structure | 778-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | ST000177 | Structure | 778-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | ST000177 | Structure | 778-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | ST000177 | Structure | 778-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | ST000177 | Structure | 778-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | ST000177 | Structure | 778-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | ST000177 | Structure | 778-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | ST000177 | Structure | 778-Structure | Structure Patrol Inspection | General Comments | | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | ST000177 | Structure | 778-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | ST000177 | Structure | 778-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | ST000177 | Structure | 778-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | ST000177 | Structure | 778-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | ST000177 | Structure | 778-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | ST000177 | Structure | 778-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | ST000177 | Structure | 778-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | ST000177 | Structure | 778-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | ST000177 | Structure | 778-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0226 | NonLTC | 693-1 C | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0226 | NonLTC | 693-1 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0226 | NonLTC | 693-1 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0226 | NonLTC | 693-1 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Readings | 9 Month Operations | 0 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/3/2023 7:33 | Distribution | Imboden Quarterly Inspection | BK000931 | BreakerVacuum | 071-3415 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | FE000463 | Fence | 793-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | FE000463 | Fence | 793-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | FE000463 | Fence | 793-Fence | Fence Patrol Inspection | General Comments | | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | FE000463 | Fence | 793-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | FE000463 | Fence | 793-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | FE000463 | Fence | 793-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | FE000463 | Fence | 793-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | FE000463 | Fence | 793-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | FE000463 | Fence | 793-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | FE000463 | Fence | 793-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | FE000463 | Fence | 793-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | FE000463 | Fence | 793-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | FE000463 | Fence | 793-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | FE000463 | Fence | 793-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | FE000463 | Fence | 793-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | ST000149 | Structure | 576-Structure | Structure Patrol Inspection | General Comments | | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | WX0258 | RecloserElectronic | 793-2439 | Recloser Electronic Patrol Inspection | Amps A Ø | 12 | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | WX0258 | RecloserElectronic | 793-2439 | Recloser Electronic Patrol Inspection | Amps B Ø | 15 | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | ST000149 | Structure | 576-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | ST000149 | Structure | 576-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | ST000149 | Structure | 576-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | ST000149 | Structure | 576-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | ST000149 | Structure | 576-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | ST000149 | Structure | 576-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | ST000149 | Structure | 576-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | WX0258 | RecloserElectronic | 793-2439 | Recloser Electronic Patrol Inspection | Amps C Ø | 15 | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | WX0258 | RecloserElectronic | 793-2439 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | ST000149 | Structure | 576-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | ST000149 | Structure | 576-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | WX0258 | RecloserElectronic | 793-2439 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | WX0258 | RecloserElectronic | 793-2439 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | WX0258 | RecloserElectronic | 793-2439 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | WX0258 | RecloserElectronic | 793-2439 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | WX0258 | RecloserElectronic | 793-2439 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | WX0258 | RecloserElectronic | 793-2439 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | WX0258 | RecloserElectronic | 793-2439 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | WX0258 | RecloserElectronic | 793-2439 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | WX0258 | RecloserElectronic | 793-2439 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | WX0258 | RecloserElectronic | 793-2439 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | ST000149 | Structure | 576-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | ST000149 | Structure | 576-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | ST000149 | Structure | 576-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | CH000492 | ControlHouse | 778-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | CH000492 | ControlHouse | 778-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | CH000492 | ControlHouse | 778-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | CH000492 | ControlHouse | 778-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | CH000492 | ControlHouse | 778-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | CH000492 | ControlHouse | 778-Control House | Control House Patrol Inspection | General Comments | | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | YD000145 | Yard | 576-Yard | Yard Patrol Inspection | Vegetation | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | YD000145 | Yard | 576-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | YD000145 | Yard | 576-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | YD000145 | Yard | 576-Yard | Yard Patrol Inspection | General Comments | | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | YD000145 | Yard | 576-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | YD000145 | Yard | 576-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | YD000145 | Yard | 576-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | ST000471 | Structure | 793-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | ST000471 | Structure | 793-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | ST000471 | Structure | 793-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | ST000471 | Structure | 793-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | ST000471 | Structure | 793-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | ST000471 | Structure | 793-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | ST000471 | Structure | 793-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0224 | NonLTC | 693-1 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0224 | NonLTC | 693-1 B | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0224 | NonLTC | 693-1 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0224 | NonLTC | 693-1 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0224 | NonLTC | 693-1 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | WX0258 | RecloserElectronic | 793-2439 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | WX0258 | RecloserElectronic | 793-2439 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | WX0258 | RecloserElectronic | 793-2439 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | WX0258 | RecloserElectronic | 793-2439 | Recloser Electronic Patrol Inspection | Operations Counter | 1509 | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | WX0258 | RecloserElectronic | 793-2439 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | WX0258 | RecloserElectronic | 793-2439 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | YD000145 | Yard | 576-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | YD000145 | Yard | 576-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | YD000402 | Yard | 433-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | YD000402 | Yard | 433-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | YD000402 | Yard | 433-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | YD000402 | Yard | 433-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | YD000402 | Yard | 433-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | YD000402 | Yard | 433-Yard | Yard Patrol Inspection | General Comments | | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | YD000402 | Yard | 433-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | YD000402 | Yard | 433-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | YD000402 | Yard | 433-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | YD000402 | Yard | 433-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | YD000402 | Yard | 433-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | YD000402 | Yard | 433-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | YD000402 | Yard | 433-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | YD000402 | Yard | 433-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | YD000402 | Yard | 433-Yard | Yard Patrol Inspection | Ambient Temp | 52 | °F |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | CH000492 | ControlHouse | 778-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | CH000492 | ControlHouse | 778-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | CH000492 | ControlHouse | 778-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | CH000492 | ControlHouse | 778-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | YD000145 | Yard | 576-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | YD000145 | Yard | 576-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | BAT001474 | Battery | 778-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | BAT001474 | Battery | 778-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | BAT001474 | Battery | 778-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | BAT001474 | Battery | 778-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | BAT001474 | Battery | 778-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | T0193 | NonLTC | 008-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | T0193 | NonLTC | 008-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | T0193 | NonLTC | 008-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | T0193 | NonLTC | 008-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | T0193 | NonLTC | 008-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | CH000492 | ControlHouse | 778-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | CH000492 | ControlHouse | 778-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | CH000492 | ControlHouse | 778-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | CH000492 | ControlHouse | 778-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | T0193 | NonLTC | 008-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | T0193 | NonLTC | 008-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | T0193 | NonLTC | 008-1 | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | T0193 | NonLTC | 008-1 | NonLTC Transformer Readings | Oil Temp Max | 20 | °C |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | T0193 | NonLTC | 008-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | T0193 | NonLTC | 008-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 52.50 | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | T0193 | NonLTC | 008-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | T0193 | NonLTC | 008-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.5 | psi |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | T0193 | NonLTC | 008-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | T0193 | NonLTC | 008-1 | NonLTC Transformer Readings | General Comments | needs a fan | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | T0193 | NonLTC | 008-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | T0193 | NonLTC | 008-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | T0193 | NonLTC | 008-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | T0193 | NonLTC | 008-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0207 | RecloserElectronic | 562-2441 | Recloser Electronic Patrol Inspection | Amps A Ø | 28 | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0207 | RecloserElectronic | 562-2441 | Recloser Electronic Patrol Inspection | Amps B Ø | 25 | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0207 | RecloserElectronic | 562-2441 | Recloser Electronic Patrol Inspection | Amps C Ø | 25 | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0207 | RecloserElectronic | 562-2441 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0207 | RecloserElectronic | 562-2441 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0207 | RecloserElectronic | 562-2441 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0207 | RecloserElectronic | 562-2441 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | T0193 | NonLTC | 008-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | T0193 | NonLTC | 008-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | T0193 | NonLTC | 008-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | T0193 | NonLTC | 008-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | T0193 | NonLTC | 008-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | ST000149 | Structure | 576-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | ST000149 | Structure | 576-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | ST000149 | Structure | 576-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | ST000149 | Structure | 576-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | BAT001474 | Battery | 778-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | BAT001474 | Battery | 778-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | BAT001474 | Battery | 778-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | ST000149 | Structure | 576-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | BAT001474 | Battery | 778-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.0 | VDC |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | BAT001474 | Battery | 778-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | BAT001474 | Battery | 778-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | BAT001474 | Battery | 778-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | BAT001474 | Battery | 778-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | ST000149 | Structure | 576-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | ST000149 | Structure | 576-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | ST000149 | Structure | 576-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | YD000145 | Yard | 576-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | T0193 | NonLTC | 008-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | T0193 | NonLTC | 008-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | ST000377 | Structure | 433-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | ST000377 | Structure | 433-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | ST000377 | Structure | 433-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | ST000377 | Structure | 433-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | ST000377 | Structure | 433-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | ST000377 | Structure | 433-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | ST000377 | Structure | 433-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | ST000377 | Structure | 433-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | ST000377 | Structure | 433-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | ST000377 | Structure | 433-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | ST000377 | Structure | 433-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | ST000377 | Structure | 433-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | ST000377 | Structure | 433-Structure | Structure Patrol Inspection | General Comments | | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | ST000377 | Structure | 433-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | ST000377 | Structure | 433-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | ST000377 | Structure | 433-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | ST000377 | Structure | 433-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | ST000377 | Structure | 433-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | ST000377 | Structure | 433-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | ST000377 | Structure | 433-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | ST000377 | Structure | 433-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/2/2023 14:04 | Distribution | Rockwell Quarterly Inspection | ST000377 | Structure | 433-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BAT001297 | Battery | 843-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BAT001297 | Battery | 843-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BAT001297 | Battery | 843-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BAT001297 | Battery | 843-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BAT001297 | Battery | 843-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BAT001297 | Battery | 843-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BAT001297 | Battery | 843-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BAT001297 | Battery | 843-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BAT001297 | Battery | 843-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 14.0 | VDC |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BAT001297 | Battery | 843-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0207 | RecloserElectronic | 562-2441 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0207 | RecloserElectronic | 562-2441 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0207 | RecloserElectronic | 562-2441 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0207 | RecloserElectronic | 562-2441 | Recloser Electronic Patrol Inspection | Operations Counter | 57 | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0207 | RecloserElectronic | 562-2441 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0207 | RecloserElectronic | 562-2441 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0207 | RecloserElectronic | 562-2441 | Recloser Electronic Patrol Inspection | General Comments | | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0207 | RecloserElectronic | 562-2441 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0207 | RecloserElectronic | 562-2441 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0207 | RecloserElectronic | 562-2441 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0207 | RecloserElectronic | 562-2441 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0207 | RecloserElectronic | 562-2441 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 11:02 | Distribution | Millwood Quarterly Inspection | KX0207 | RecloserElectronic | 562-2441 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | BCH001408 | Charger | 778-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | BCH001408 | Charger | 778-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0224 | NonLTC | 693-1 B | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | BCH001408 | Charger | 778-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0224 | NonLTC | 693-1 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0224 | NonLTC | 693-1 B | NonLTC Transformer Readings | Oil Temp Present | 27 | °C |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0224 | NonLTC | 693-1 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0224 | NonLTC | 693-1 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0224 | NonLTC | 693-1 B | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.5 | psi |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0224 | NonLTC | 693-1 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0224 | NonLTC | 693-1 B | NonLTC Transformer Readings | General Comments | | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0224 | NonLTC | 693-1 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0224 | NonLTC | 693-1 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | YD000145 | Yard | 576-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BAT001297 | Battery | 843-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 14.0 | VDC |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | ST000471 | Structure | 793-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | ST000471 | Structure | 793-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | ST000471 | Structure | 793-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | ST000471 | Structure | 793-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | ST000471 | Structure | 793-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | ST000471 | Structure | 793-Structure | Structure Patrol Inspection | General Comments | | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | ST000471 | Structure | 793-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | ST000471 | Structure | 793-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | ST000471 | Structure | 793-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | ST000471 | Structure | 793-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | ST000471 | Structure | 793-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | ST000471 | Structure | 793-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | ST000471 | Structure | 793-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0224 | NonLTC | 693-1 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/2/2023 13:11 | Distribution | Rumsey Quarterly Inspection | T0193 | NonLTC | 008-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0224 | NonLTC | 693-1 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0224 | NonLTC | 693-1 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0224 | NonLTC | 693-1 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0224 | NonLTC | 693-1 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0224 | NonLTC | 693-1 B | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0224 | NonLTC | 693-1 B | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0224 | NonLTC | 693-1 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | YD000468 | Yard | 793-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | YD000468 | Yard | 793-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | BCH001408 | Charger | 778-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.830 | millivolts |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | BCH001408 | Charger | 778-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0224 | NonLTC | 693-1 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0224 | NonLTC | 693-1 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | ST000471 | Structure | 793-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/2/2023 13:44 | Distribution | Leitchfield City Quarterly Inspection | ST000471 | Structure | 793-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BAT001297 | Battery | 843-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/2/2023 15:05 | Distribution | Fariston Quarterly Inspection | BAT001297 | Battery | 843-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | BCH001408 | Charger | 778-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | BCH001408 | Charger | 778-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .3 | amps |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | YD000145 | Yard | 576-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/2/2023 12:54 | Distribution | East Bernstadt Quarterly Inspection | BCH001408 | Charger | 778-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0224 | NonLTC | 693-1 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/2/2023 9:49 | Distribution | Stringtown Quarterly Inspection | W0224 | NonLTC | 693-1 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 12:56 | Distribution | Greenville 12kV Quarterly Inspection | YD000145 | Yard | 576-Yard | Yard Patrol Inspection | Ambient Temp | 63 | °F |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations | 0 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty A Ph V | 13.12 | % |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty B Ph V | 14.66 | % |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty C Ph V | 6.17 | % |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Readings | Amps A Ø | 30.0 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Readings | Amps B Ø | 60.0 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Readings | Unknown Operations | 0 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Readings | Switching Operations | 0 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Readings | Operations This Read Vac | 0 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AL | 249 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AF | 249 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Readings | Maintenance Operations | 0 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Readings | General Comments | | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Readings | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations Ground | 0 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations C Ø | 0 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations B Ø | 0 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations A Ø | 0 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Readings | Amps C Ø | 40.0 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | General Comments | | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0039 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | KX0066 | RecloserElectronic | 817-1673 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | KX0066 | RecloserElectronic | 817-1673 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | KX0066 | RecloserElectronic | 817-1673 | Recloser Electronic Patrol Inspection | Amps C Ø | 55.0 | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | KX0066 | RecloserElectronic | 817-1673 | Recloser Electronic Patrol Inspection | Amps B Ø | 48.0 | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | KX0066 | RecloserElectronic | 817-1673 | Recloser Electronic Patrol Inspection | Amps A Ø | 98.0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | LTCM000077 | LTCMechanism | 361-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | LTCM000077 | LTCMechanism | 361-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | LTCM000077 | LTCMechanism | 361-1 | LTC Counter Readings | General Comments | | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | LTCM000077 | LTCMechanism | 361-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | LTCM000077 | LTCMechanism | 361-1 | LTC Counter Readings | LTC As Found Counter | 23369 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | LTCM000077 | LTCMechanism | 361-1 | LTC Counter Readings | LTC As Left Counter | 23371 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | LTCMechanism | 566-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | LTCMechanism | 566-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1359 | Regulator | 411-1 C | Regulator Patrol Inspection | General Comments | | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | LTCMechanism | 566-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000154 | Structure | 142-Structure 34.5 | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000154 | Structure | 142-Structure 34.5 | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | WX0339 | RecloserHydraulic | 646-1693 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 27.0 | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | WX0339 | RecloserHydraulic | 646-1693 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 29.4 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1359 | Regulator | 411-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1359 | Regulator | 411-1 C | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1359 | Regulator | 411-1 C | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | WX0339 | RecloserHydraulic | 646-1693 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 26.5 | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | WX0339 | RecloserHydraulic | 646-1693 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | WX0339 | RecloserHydraulic | 646-1693 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1359 | Regulator | 411-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | WX0339 | RecloserHydraulic | 646-1693 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | WX0339 | RecloserHydraulic | 646-1693 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1359 | Regulator | 411-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1359 | Regulator | 411-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1359 | Regulator | 411-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1359 | Regulator | 411-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1359 | Regulator | 411-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 158038 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1359 | Regulator | 411-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | WX0339 | RecloserHydraulic | 646-1693 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | WX0339 | RecloserHydraulic | 646-1693 | Recloser Hydraulic Patrol Inspection | General Comments | Ops: A 130, B 198, C 210 | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | WX0339 | RecloserHydraulic | 646-1693 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1359 | Regulator | 411-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | WX0339 | RecloserHydraulic | 646-1693 | Recloser Hydraulic Patrol Inspection | Operations Counter | 0 | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | WX0339 | RecloserHydraulic | 646-1693 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | WX0339 | RecloserHydraulic | 646-1693 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1229 | Regulator | 817-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1229 | Regulator | 817-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1229 | Regulator | 817-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1359 | Regulator | 411-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1359 | Regulator | 411-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | FE000151 | Fence | 142-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | FE000151 | Fence | 142-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | FE000151 | Fence | 142-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | FE000151 | Fence | 142-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | LTCM000077 | LTCMechanism | 361-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | LTCM000077 | LTCMechanism | 361-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | KX0066 | RecloserElectronic | 817-1673 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | YD000150 | Yard | 142-Yard | Yard Patrol Inspection | General Comments | Small washout is developing to the right of gate. | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | YD000150 | Yard | 142-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | YD000150 | Yard | 142-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | YD000150 | Yard | 142-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | YD000150 | Yard | 142-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000154 | Structure | 142-Structure 34.5 | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000154 | Structure | 142-Structure 34.5 | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000154 | Structure | 142-Structure 34.5 | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000154 | Structure | 142-Structure 34.5 | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000154 | Structure | 142-Structure 34.5 | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000154 | Structure | 142-Structure 34.5 | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000154 | Structure | 142-Structure 34.5 | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000154 | Structure | 142-Structure 34.5 | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000154 | Structure | 142-Structure 34.5 | Structure Patrol Inspection | General Comments | ok | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | KX0066 | RecloserElectronic | 817-1673 | Recloser Electronic Patrol Inspection | Operations Counter | 381 | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | KX0066 | RecloserElectronic | 817-1673 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | KX0066 | RecloserElectronic | 817-1673 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | KX0066 | RecloserElectronic | 817-1673 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000154 | Structure | 142-Structure 34.5 | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000154 | Structure | 142-Structure 34.5 | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000154 | Structure | 142-Structure 34.5 | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000154 | Structure | 142-Structure 34.5 | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000154 | Structure | 142-Structure 34.5 | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000154 | Structure | 142-Structure 34.5 | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000154 | Structure | 142-Structure 34.5 | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000154 | Structure | 142-Structure 34.5 | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000154 | Structure | 142-Structure 34.5 | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000154 | Structure | 142-Structure 34.5 | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1359 | Regulator | 411-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1359 | Regulator | 411-1 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1359 | Regulator | 411-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1359 | Regulator | 411-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1359 | Regulator | 411-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1359 | Regulator | 411-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | KX0066 | RecloserElectronic | 817-1673 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | KX0066 | RecloserElectronic | 817-1673 | Recloser Electronic Patrol Inspection | General Comments | 1 AG op, 1 trip check | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | KX0066 | RecloserElectronic | 817-1673 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | KX0066 | RecloserElectronic | 817-1673 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | KX0066 | RecloserElectronic | 817-1673 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | KX0066 | RecloserElectronic | 817-1673 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | KX0066 | RecloserElectronic | 817-1673 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000154 | Structure | 142-Structure 34.5 | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | KX0066 | RecloserElectronic | 817-1673 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | KX0066 | RecloserElectronic | 817-1673 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | KX0066 | RecloserElectronic | 817-1673 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | BCH001143 | Charger | 410-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | BCH001143 | Charger | 410-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | BCH001143 | Charger | 410-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000218 | Regulator | 643-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000218 | Regulator | 643-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000218 | Regulator | 643-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000218 | Regulator | 643-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000218 | Regulator | 643-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 4964 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000218 | Regulator | 643-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000218 | Regulator | 643-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000218 | Regulator | 643-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000218 | Regulator | 643-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Readings | General Comments | | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Readings | LTC Totalizer Reading | 6614.40 | kw |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1211 | Regulator | 323-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1211 | Regulator | 323-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1211 | Regulator | 323-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Readings | Totalizer Meter Reading | .6890 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1211 | Regulator | 323-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1211 | Regulator | 323-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | WithLTC | 566-2 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1211 | Regulator | 323-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1211 | Regulator | 323-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1211 | Regulator | 323-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1211 | Regulator | 323-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 68932 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1211 | Regulator | 323-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.9 | volts |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1211 | Regulator | 323-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1211 | Regulator | 323-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1211 | Regulator | 323-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1211 | Regulator | 323-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1211 | Regulator | 323-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1211 | Regulator | 323-1 A | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1211 | Regulator | 323-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1211 | Regulator | 323-1 A | Regulator Patrol Inspection | General Comments | | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1211 | Regulator | 323-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1211 | Regulator | 323-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1211 | Regulator | 323-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1211 | Regulator | 323-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1211 | Regulator | 323-1 A | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | LTCM000077 | LTCMechanism | 361-1 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | LTCM000077 | LTCMechanism | 361-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | ST000384 | Structure | 743-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | ST000384 | Structure | 743-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | ST000384 | Structure | 743-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | ST000384 | Structure | 743-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | ST000384 | Structure | 743-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | ST000384 | Structure | 743-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | ST000384 | Structure | 743-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | ST000384 | Structure | 743-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | ST000384 | Structure | 743-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | ST000384 | Structure | 743-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000218 | Regulator | 643-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000218 | Regulator | 643-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000218 | Regulator | 643-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000218 | Regulator | 643-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | ST000384 | Structure | 743-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | ST000384 | Structure | 743-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | LTCM000077 | LTCMechanism | 361-1 | LTC Counter Readings | LTC Operations Since Last Insp | 731 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | LTCM000077 | LTCMechanism | 361-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | LTCM000077 | LTCMechanism | 361-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | LTCM000077 | LTCMechanism | 361-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | LTCM000077 | LTCMechanism | 361-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | ST000384 | Structure | 743-Structure | Structure Patrol Inspection | General Comments | | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | ST000384 | Structure | 743-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | ST000384 | Structure | 743-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | ST000384 | Structure | 743-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | ST000384 | Structure | 743-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | ST000384 | Structure | 743-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | ST000384 | Structure | 743-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | ST000384 | Structure | 743-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | ST000384 | Structure | 743-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | ST000384 | Structure | 743-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | YD000150 | Yard | 142-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000218 | Regulator | 643-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | YD000150 | Yard | 142-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | YD000150 | Yard | 142-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | YD000150 | Yard | 142-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000218 | Regulator | 643-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000218 | Regulator | 643-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000218 | Regulator | 643-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000218 | Regulator | 643-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000218 | Regulator | 643-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000218 | Regulator | 643-1 B | Regulator Patrol Inspection | General Comments | ok | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000218 | Regulator | 643-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | YD000150 | Yard | 142-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | YD000150 | Yard | 142-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | YD000150 | Yard | 142-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | YD000150 | Yard | 142-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | YD000150 | Yard | 142-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | YD000150 | Yard | 142-Yard | Yard Patrol Inspection | Ambient Temp | 79 | °F |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | FE000151 | Fence | 142-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | FE000151 | Fence | 142-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | FE000151 | Fence | 142-Fence | Fence Patrol Inspection | General Comments | ok | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000218 | Regulator | 643-1 B | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000218 | Regulator | 643-1 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000218 | Regulator | 643-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | FE000151 | Fence | 142-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | FE000151 | Fence | 142-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | FE000151 | Fence | 142-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | FE000151 | Fence | 142-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | BCH001143 | Charger | 410-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.000 | millivolts |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | BCH001143 | Charger | 410-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | BCH001143 | Charger | 410-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | BCH001143 | Charger | 410-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .8 | amps |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | BCH001143 | Charger | 410-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Readings | Unknown Operations | 0 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Readings | Switching Operations | 0 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Readings | Operations This Read Vac | 1 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Readings | Operations Counter AL | 8 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Readings | Operations Counter AF | 8 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Readings | Maintenance Operations | 1 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Readings | General Comments | TRIP CHECK | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Patrol Inspection | General Comments | | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Readings | Follow-up Action Required? | n | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Readings | Fault Operations Ground | 0 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Readings | Amps C Ø | 44.0 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Readings | Amps B Ø | 56.0 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Readings | Amps A Ø | 50.0 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0034 | BreakerVacuum | 410-1327 | VCB Readings | 9 Month Operations | 1 | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Readings | 9 Month Operations | 6 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Readings | General Comments | | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Patrol Inspection | General Comments | | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Readings | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Readings | Fault Operations Ground | 0 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Readings | 9 Month Operations | 3 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Readings | Amps C Ø | 96.0 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Readings | Amps B Ø | 85.0 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Readings | Amps A Ø | 88.0 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Readings | Accumulated Fault Duty C Ph V | 6.57 | % |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Readings | Accumulated Fault Duty B Ph V | 4.38 | % |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Readings | Accumulated Fault Duty A Ph V | 4.38 | % |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Readings | 9 Month Operations | 1 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | LTCM000051 | LTCMechanism | 743-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | LTCM000051 | LTCMechanism | 743-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | LTCM000051 | LTCMechanism | 743-2 | LTC Counter Readings | General Comments | | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | LTCM000051 | LTCMechanism | 743-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | LTCM000051 | LTCMechanism | 743-2 | LTC Counter Readings | LTC As Found Counter | 421 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | LTCM000051 | LTCMechanism | 743-2 | LTC Counter Readings | LTC As Left Counter | 421 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | LTCM000051 | LTCMechanism | 743-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | LTCM000051 | LTCMechanism | 743-2 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | LTCM000051 | LTCMechanism | 743-2 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | LTCM000051 | LTCMechanism | 743-2 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | LTCM000051 | LTCMechanism | 743-2 | LTC Counter Readings | LTC Operations Since Last Insp | 376 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | LTCM000051 | LTCMechanism | 743-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | LTCM000051 | LTCMechanism | 743-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | LTCM000051 | LTCMechanism | 743-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | FE000052 | Fence | 411-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | FE000052 | Fence | 411-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | FE000052 | Fence | 411-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | FE000052 | Fence | 411-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | FE000052 | Fence | 411-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | FE000052 | Fence | 411-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | FE000052 | Fence | 411-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | FE000052 | Fence | 411-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | FE000052 | Fence | 411-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | LTCC000565 | LTCControl | 743-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | LTCMechanism | 665-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | LTCMechanism | 665-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | LTCMechanism | 665-1 | LTC Counter Readings | General Comments | | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | LTCMechanism | 665-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | LTCMechanism | 665-1 | LTC Counter Readings | LTC As Found Counter | 13340 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | LTCMechanism | 665-1 | LTC Counter Readings | LTC As Left Counter | 13356 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | LTCMechanism | 665-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | LTCMechanism | 665-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | LTCMechanism | 665-1 | LTC Counter Readings | LTC Max Tap Position | 3R | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | LTCMechanism | 665-1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | LTCMechanism | 665-1 | LTC Counter Readings | LTC Operations Since Last Insp | 176 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | LTCMechanism | 665-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | LTCMechanism | 665-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | LTCMechanism | 665-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | YD000380 | Yard | 743-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | YD000380 | Yard | 743-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | YD000380 | Yard | 743-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | YD000380 | Yard | 743-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | YD000380 | Yard | 743-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | YD000380 | Yard | 743-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | YD000380 | Yard | 743-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | YD000380 | Yard | 743-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | YD000380 | Yard | 743-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | YD000380 | Yard | 743-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | YD000380 | Yard | 743-Yard | Yard Patrol Inspection | General Comments | | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | YD000380 | Yard | 743-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | YD000380 | Yard | 743-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | YD000380 | Yard | 743-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | YD000380 | Yard | 743-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | BAT001660 | Battery | 410-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | BAT001660 | Battery | 410-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | BAT001660 | Battery | 410-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.9 | VDC |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Readings | Unknown Operations | 0 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Readings | Switching Operations | 0 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Readings | Operations This Read Vac | 1 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Readings | Operations Counter AL | 191 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Readings | Operations Counter AF | 191 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Readings | Maintenance Operations | 1 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Readings | General Comments | 1 trip check | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Patrol Inspection | General Comments | | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Readings | Follow-up Action Required? | n | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Readings | Fault Operations Ground | 0 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Readings | Amps C Ø | 70.0 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Readings | Amps B Ø | 73.0 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Readings | Amps A Ø | 73.0 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000782 | BreakerVacuum | 665-1625 | VCB Readings | 9 Month Operations | 2 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | FE000052 | Fence | 411-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | FE000052 | Fence | 411-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | FE000052 | Fence | 411-Fence | Fence Patrol Inspection | General Comments | | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | FE000052 | Fence | 411-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | FE000052 | Fence | 411-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | FE000052 | Fence | 411-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | KX0129 | RecloserElectronic | 142-3405 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | KX0129 | RecloserElectronic | 142-3405 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | KX0129 | RecloserElectronic | 142-3405 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | KX0129 | RecloserElectronic | 142-3405 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | KX0129 | RecloserElectronic | 142-3405 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | KX0129 | RecloserElectronic | 142-3405 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | KX0129 | RecloserElectronic | 142-3405 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | KX0129 | RecloserElectronic | 142-3405 | Recloser Electronic Patrol Inspection | General Comments | 1 trip check. Needs wildlife protection. | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | KX0129 | RecloserElectronic | 142-3405 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | KX0129 | RecloserElectronic | 142-3405 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | KX0129 | RecloserElectronic | 142-3405 | Recloser Electronic Patrol Inspection | Operations Counter | 213 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | KX0129 | RecloserElectronic | 142-3405 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | KX0129 | RecloserElectronic | 142-3405 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | KX0129 | RecloserElectronic | 142-3405 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1233 | Regulator | 817-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1233 | Regulator | 817-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1233 | Regulator | 817-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1233 | Regulator | 817-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1233 | Regulator | 817-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1233 | Regulator | 817-1 C | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1233 | Regulator | 817-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1233 | Regulator | 817-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1233 | Regulator | 817-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1233 | Regulator | 817-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1233 | Regulator | 817-1 C | Regulator Patrol Inspection | General Comments | ok | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1233 | Regulator | 817-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1233 | Regulator | 817-1 C | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1233 | Regulator | 817-1 C | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1233 | Regulator | 817-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1233 | Regulator | 817-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1233 | Regulator | 817-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1233 | Regulator | 817-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1233 | Regulator | 817-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1233 | Regulator | 817-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 54726 | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1233 | Regulator | 817-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1233 | Regulator | 817-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1233 | Regulator | 817-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Readings | Unknown Operations | 0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Readings | Switching Operations | 0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Readings | Operations This Read Vac | 0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Readings | Operations Counter AL | 168 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Readings | Operations Counter AF | 168 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Readings | Maintenance Operations | 0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1229 | Regulator | 817-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1229 | Regulator | 817-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1229 | Regulator | 817-1 A | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1229 | Regulator | 817-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1229 | Regulator | 817-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1229 | Regulator | 817-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1229 | Regulator | 817-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1229 | Regulator | 817-1 A | Regulator Patrol Inspection | General Comments | ok | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1229 | Regulator | 817-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1229 | Regulator | 817-1 A | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1229 | Regulator | 817-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1229 | Regulator | 817-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1229 | Regulator | 817-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1229 | Regulator | 817-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1229 | Regulator | 817-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1229 | Regulator | 817-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1229 | Regulator | 817-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 53547 | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1229 | Regulator | 817-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1229 | Regulator | 817-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1229 | Regulator | 817-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | BAT001101 | Battery | 343-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | BAT001101 | Battery | 343-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 76 | °F |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | BAT001101 | Battery | 343-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | BAT001101 | Battery | 343-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | BAT001101 | Battery | 343-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | BAT001101 | Battery | 343-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | BAT001101 | Battery | 343-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | BAT001101 | Battery | 343-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | BAT001101 | Battery | 343-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | BAT001101 | Battery | 343-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | BAT001101 | Battery | 343-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | BAT001101 | Battery | 343-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | BAT001101 | Battery | 343-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | BAT001101 | Battery | 343-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | BCH001062 | Charger | 343-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.400 | millivolts |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | BCH001062 | Charger | 343-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.3 | VDC |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | BCH001062 | Charger | 343-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.3 | VDC |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | BCH001062 | Charger | 343-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .2 | amps |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | BCH001062 | Charger | 343-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | BCH001062 | Charger | 343-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | KX0129 | RecloserElectronic | 142-3405 | Recloser Electronic Patrol Inspection | Amps A Ø | 49.0 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | KX0129 | RecloserElectronic | 142-3405 | Recloser Electronic Patrol Inspection | Amps B Ø | 47.0 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | KX0129 | RecloserElectronic | 142-3405 | Recloser Electronic Patrol Inspection | Amps C Ø | 46.0 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | KX0129 | RecloserElectronic | 142-3405 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | KX0129 | RecloserElectronic | 142-3405 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | KX0129 | RecloserElectronic | 142-3405 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Readings | Amps C Ø | 107.0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Readings | Amps B Ø | 108.0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Readings | Amps A Ø | 77.0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0177 | NonLTC | 646-1 A | NonLTC Transformer Readings | Totalizer Meter Reading | .4650 | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0177 | NonLTC | 646-1 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0177 | NonLTC | 646-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0177 | NonLTC | 646-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0177 | NonLTC | 646-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0177 | NonLTC | 646-1 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0177 | NonLTC | 646-1 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0177 | NonLTC | 646-1 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0177 | NonLTC | 646-1 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0177 | NonLTC | 646-1 A | NonLTC Transformer Readings | Oil Temp Present | 38 | °C |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0177 | NonLTC | 646-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0177 | NonLTC | 646-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0177 | NonLTC | 646-1 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 558.00 | kw |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0177 | NonLTC | 646-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0177 | NonLTC | 646-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0177 | NonLTC | 646-1 A | NonLTC Transformer Readings | General Comments | ok | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0177 | NonLTC | 646-1 A | NonLTC Transformer Patrol Inspection | General Comments | ok | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0177 | NonLTC | 646-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0177 | NonLTC | 646-1 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0177 | NonLTC | 646-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0177 | NonLTC | 646-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0177 | NonLTC | 646-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0177 | NonLTC | 646-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0177 | NonLTC | 646-1 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0177 | NonLTC | 646-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Readings | Unknown Operations | 0 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Readings | Switching Operations | 0 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Readings | Operations This Read Vac | 0 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Readings | Operations Counter AL | 293 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Readings | Operations Counter AF | 293 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | MB0179 | BreakerVacuum | 323-0755 | VCB Readings | Maintenance Operations | 0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Readings | General Comments | | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Patrol Inspection | General Comments | | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Readings | Follow-up Action Required? | n | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Readings | Fault Operations Ground | 0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Readings | Amps C Ø | 82.0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Readings | Amps B Ø | 62.0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Readings | Amps A Ø | 107.0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001791 | BreakerVacuum | 361-0757 | VCB Readings | 9 Month Operations | 0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Readings | Unknown Operations | 0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Readings | Switching Operations | 0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Readings | Operations This Read Vac | 0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Readings | Operations Counter AL | 157 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Readings | Operations Counter AF | 157 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Readings | Maintenance Operations | 0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Readings | General Comments | | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Patrol Inspection | General Comments | | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Readings | Follow-up Action Required? | n | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Readings | Fault Operations Ground | 0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BK001790 | BreakerVacuum | 361-0756 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | ST000161 | Structure | 646-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | ST000161 | Structure | 646-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | ST000161 | Structure | 646-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | ST000161 | Structure | 646-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | ST000161 | Structure | 646-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | ST000161 | Structure | 646-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | ST000161 | Structure | 646-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | ST000161 | Structure | 646-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | ST000161 | Structure | 646-Structure | Structure Patrol Inspection | General Comments | Spare cutout fuse barrels need replacing. Xfmr fuse barrels are starting to fray. Station could also use upgraded wildlife protection. | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | ST000161 | Structure | 646-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | n | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | ST000161 | Structure | 646-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | ST000161 | Structure | 646-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | ST000161 | Structure | 646-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | ST000161 | Structure | 646-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | ST000161 | Structure | 646-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | ST000161 | Structure | 646-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | ST000161 | Structure | 646-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | ST000161 | Structure | 646-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BCH001466 | Charger | 142-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BCH001466 | Charger | 142-Battery Charger | Battery Charger Patrol Insp | General Comments | ok | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BCH001466 | Charger | 142-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BCH001466 | Charger | 142-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BCH001466 | Charger | 142-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | FE000318 | Fence | 643-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | FE000318 | Fence | 643-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | FE000318 | Fence | 643-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | FE000318 | Fence | 643-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | FE000318 | Fence | 643-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Readings | Maintenance Operations | 0 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Readings | General Comments | | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Patrol Inspection | General Comments | | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Readings | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Readings | Fault Operations Ground | 0 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Readings | Operations This Read Vac | 0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Readings | Switching Operations | 0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Readings | Unknown Operations | 0 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Readings | Switching Operations | 0 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Readings | Operations This Read Vac | 0 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Readings | Operations Counter AL | 537 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Readings | Unknown Operations | 0 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Readings | 9 Month Operations | 1 | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | FE000161 | Fence | 817-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | FE000161 | Fence | 817-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Readings | Amps A Ø | 140.0 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Readings | Amps B Ø | 200.0 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Readings | Amps C Ø | 220.0 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Readings | Operations Counter AF | 537 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | FE000318 | Fence | 643-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | FE000318 | Fence | 643-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | FE000318 | Fence | 643-Fence | Fence Patrol Inspection | General Comments | ok | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | FE000318 | Fence | 643-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | FE000318 | Fence | 643-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | FE000318 | Fence | 643-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | FE000318 | Fence | 643-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | FE000318 | Fence | 643-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | FE000318 | Fence | 643-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | FE000318 | Fence | 643-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | FE000318 | Fence | 643-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Readings | Unknown Operations | 0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Readings | Switching Operations | 0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | ST000161 | Structure | 646-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | ST000161 | Structure | 646-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | ST000161 | Structure | 646-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | ST000161 | Structure | 646-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Readings | Amps C Ø | 50.0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Readings | Amps B Ø | 45.0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Readings | Amps A Ø | 55.0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Readings | 9 Month Operations | 2 | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Readings | Unknown Operations | 0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Readings | Switching Operations | 2 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Readings | Operations This Read Vac | 2 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Readings | Operations Counter AL | 1072 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Readings | Operations Counter AF | 1070 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Readings | Maintenance Operations | 0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Readings | General Comments | | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Readings | Operations This Read Vac | 1 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Readings | Operations Counter AL | 191 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Readings | Operations Counter AF | 191 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Readings | Maintenance Operations | 1 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Readings | General Comments | ok | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Patrol Inspection | General Comments | ok | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Readings | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Readings | Amps C Ø | 120.0 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Readings | Amps B Ø | 120.0 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Readings | Amps A Ø | 90.0 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Readings | Accumulated Fault Duty C Ph V | 37.04 | % |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Readings | Accumulated Fault Duty B Ph V | 62.5 | % |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Readings | Accumulated Fault Duty A Ph V | 53.24 | % |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | DB0040 | BreakerVacuum | 343-0752 | VCB Readings | 9 Month Operations | 5 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | LTCMechanism | 100-6 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | LTCMechanism | 100-6 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | LTCMechanism | 100-6 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | LTCMechanism | 100-6 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | LTCMechanism | 100-6 | LTC Counter Readings | LTC Operations Since Last Insp | 150 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | LTCMechanism | 100-6 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | LTCMechanism | 100-6 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | LTCMechanism | 100-6 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | LTCMechanism | 100-6 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | LTCMechanism | 100-6 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | LTCMechanism | 100-6 | LTC Counter Readings | LTC As Left Counter | 6042 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | LTCMechanism | 100-6 | LTC Counter Readings | LTC As Found Counter | 6033 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | LTCMechanism | 100-6 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | LTCMechanism | 100-6 | LTC Counter Readings | General Comments | | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | LTCMechanism | 100-6 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | LTCMechanism | 100-6 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BCH001466 | Charger | 142-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.7 | VDC |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BCH001466 | Charger | 142-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.7 | VDC |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BCH001466 | Charger | 142-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.300 | millivolts |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Readings | Unknown Operations | 0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Readings | Switching Operations | 2 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Readings | Operations This Read Vac | 2 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Readings | Operations Counter AL | 190 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Readings | Operations Counter AF | 188 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Readings | Maintenance Operations | 0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Readings | General Comments | | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Patrol Inspection | General Comments | | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Readings | Follow-up Action Required? | n | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK001827 | BreakerVacuum | 743-0883 | VCB Readings | Fault Operations Ground | 0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | LTCC000941 | LTCControl | 819-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | LTCC000941 | LTCControl | 819-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | LTCC000941 | LTCControl | 819-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | LTCC000941 | LTCControl | 819-1 | LTC Control Insp | General Comments | | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | LTCC000941 | LTCControl | 819-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | LTCC000941 | LTCControl | 819-1 | LTC Control Insp | All Connections OK? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Readings | Amps B Ø | 10.0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Readings | Amps A Ø | 3.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Readings | 9 Month Operations | 1 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | LTCMechanism | 100-7 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | LTCMechanism | 100-7 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | LTCMechanism | 100-7 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Readings | Unknown Operations | 0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Readings | Switching Operations | 0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Readings | Operations This Read Vac | 1 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Readings | Operations Counter AL | 203 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Readings | Operations Counter AF | 203 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Readings | Maintenance Operations | 0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Readings | General Comments | | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Patrol Inspection | General Comments | | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Readings | Follow-up Action Required? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Readings | Fault Operations Ground | 0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Readings | Fault Operations C Ø | 1 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Readings | Fault Adjusted Amps C Phase V | 4.94 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Readings | Amps C Ø | 157.0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Readings | Amps B Ø | 138.0 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | LTCMechanism | 100-7 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | LTCMechanism | 100-7 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | LTCMechanism | 100-7 | LTC Counter Readings | General Comments | | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | LTCMechanism | 100-7 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | LTCMechanism | 100-7 | LTC Counter Readings | LTC As Found Counter | 776 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | LTCMechanism | 100-7 | LTC Counter Readings | LTC As Left Counter | 783 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Readings | Unknown Operations | 0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Readings | Switching Operations | 0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Readings | Operations This Read Vac | 1 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Readings | Operations Counter AL | 222 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Readings | Operations Counter AF | 222 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Readings | Maintenance Operations | 1 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Patrol Inspection | General Comments | ok | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Readings | General Comments | 1 trip check | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Readings | Follow-up Action Required? | n | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Readings | Fault Operations Ground | 0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001324 | BreakerVacuum | 468-1671 | VCB Readings | Amps C Ø | 0.0 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | LTCC000948 | LTCControl | 343-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | LTCC000948 | LTCControl | 343-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | LTCC000948 | LTCControl | 343-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | LTCC000948 | LTCControl | 343-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | LTCC000948 | LTCControl | 343-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | LTCC000948 | LTCControl | 343-1 | LTC Control Insp | General Comments | | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | LTCC000948 | LTCControl | 343-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | LTCC000948 | LTCControl | 343-1 | LTC Control Insp | All Connections OK? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | LTCC000941 | LTCControl | 819-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | LTCC000941 | LTCControl | 819-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | LTCC000941 | LTCControl | 819-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | YD000158 | Yard | 817-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | YD000158 | Yard | 817-Yard | Yard Patrol Inspection | Ambient Temp | 72 | °F |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | FE000161 | Fence | 817-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | FE000161 | Fence | 817-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | FE000161 | Fence | 817-Fence | Fence Patrol Inspection | General Comments | ok | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | FE000161 | Fence | 817-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | FE000161 | Fence | 817-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | FE000161 | Fence | 817-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | FE000161 | Fence | 817-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | FE000161 | Fence | 817-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | FE000161 | Fence | 817-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | FE000161 | Fence | 817-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | FE000161 | Fence | 817-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | FE000161 | Fence | 817-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | FE000161 | Fence | 817-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | FE000161 | Fence | 817-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Readings | Amps A Ø | 7.0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Readings | Amps B Ø | 8.0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Readings | Amps C Ø | 5.0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Readings | Fault Operations Ground | 0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Readings | Follow-up Action Required? | n | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Patrol Inspection | General Comments | ok | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Readings | General Comments | ok | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Readings | Maintenance Operations | 0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Readings | Operations Counter AF | 194 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Readings | Operations Counter AL | 194 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Readings | Amps A Ø | 199.0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK001442 | BreakerVacuum | 566-0286 | VCB Readings | 9 Month Operations | 3 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | LTCMechanism | 100-7 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | LTCMechanism | 100-7 | LTC Counter Readings | LTC Operations Since Last Insp | 0 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | LTCMechanism | 100-7 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | LTCMechanism | 100-7 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | LTCMechanism | 100-7 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001325 | BreakerVacuum | 468-308 | VCB Readings | 9 Month Operations | 0 | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | ST000164 | Structure | 817-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | ST000164 | Structure | 817-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | ST000164 | Structure | 817-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | ST000164 | Structure | 817-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | ST000164 | Structure | 817-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | ST000164 | Structure | 817-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | ST000164 | Structure | 817-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | ST000164 | Structure | 817-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | ST000164 | Structure | 817-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | ST000164 | Structure | 817-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | ST000164 | Structure | 817-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | ST000164 | Structure | 817-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | ST000164 | Structure | 817-Structure | Structure Patrol Inspection | General Comments | Whole station needs wildlife protection. | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | ST000164 | Structure | 817-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | ST000164 | Structure | 817-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | ST000164 | Structure | 817-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | ST000164 | Structure | 817-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | ST000164 | Structure | 817-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | ST000164 | Structure | 817-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | ST000164 | Structure | 817-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | ST000164 | Structure | 817-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | ST000164 | Structure | 817-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | YD000158 | Yard | 817-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | YD000158 | Yard | 817-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | YD000158 | Yard | 817-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | YD000158 | Yard | 817-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | YD000158 | Yard | 817-Yard | Yard Patrol Inspection | General Comments | ok | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | YD000158 | Yard | 817-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | YD000158 | Yard | 817-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | YD000158 | Yard | 817-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | YD000158 | Yard | 817-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | YD000158 | Yard | 817-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | YD000158 | Yard | 817-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | YD000158 | Yard | 817-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | YD000158 | Yard | 817-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Readings | Fault Operations Ground | 0 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Readings | Amps C Ø | 79.0 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Readings | Amps B Ø | 78.0 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Readings | Amps A Ø | 96.0 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Readings | 9 Month Operations | 1 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1359 | Regulator | 411-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1359 | Regulator | 411-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | ST000044 | Structure | 566-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | ST000044 | Structure | 566-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | ST000044 | Structure | 566-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BCH001054 | Charger | 665-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BCH001054 | Charger | 665-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BCH001054 | Charger | 665-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .8 | amps |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BCH001054 | Charger | 665-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BCH001054 | Charger | 665-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BCH001054 | Charger | 665-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | ST000044 | Structure | 566-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | ST000044 | Structure | 566-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | ST000044 | Structure | 566-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | ST000044 | Structure | 566-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | ST000044 | Structure | 566-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | ST000044 | Structure | 566-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | ST000044 | Structure | 566-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000217 | Regulator | 643-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000217 | Regulator | 643-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000217 | Regulator | 643-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000217 | Regulator | 643-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1357 | Regulator | 411-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1357 | Regulator | 411-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Readings | Operations Counter AF | 218 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Readings | Operations Counter AL | 218 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Readings | Operations This Read Vac | 1 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Readings | Switching Operations | 0 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Readings | Unknown Operations | 0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | LTCMechanism | 566-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | LTCMechanism | 566-1 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | LTCMechanism | 566-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | ST000044 | Structure | 566-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | ST000044 | Structure | 566-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | ST000044 | Structure | 566-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | ST000044 | Structure | 566-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | ST000044 | Structure | 566-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | ST000044 | Structure | 566-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | ST000044 | Structure | 566-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | ST000044 | Structure | 566-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | ST000044 | Structure | 566-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | ST000044 | Structure | 566-Structure | Structure Patrol Inspection | General Comments | | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | ST000044 | Structure | 566-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | ST000044 | Structure | 566-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | FE000151 | Fence | 142-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | FE000151 | Fence | 142-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | FE000151 | Fence | 142-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | FE000151 | Fence | 142-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | FE000151 | Fence | 142-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | LTCMechanism | 566-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | LTCMechanism | 566-1 | LTC Counter Readings | LTC Operations Since Last Insp | 752 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | LTCMechanism | 566-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1359 | Regulator | 411-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1359 | Regulator | 411-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Readings | Unknown Operations | 0 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Readings | Switching Operations | 0 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Readings | Operations This Read Vac | 1 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Readings | Operations Counter AL | 196 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Readings | Operations Counter AF | 196 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Readings | Maintenance Operations | 1 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Readings | General Comments | 1 trip check | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Patrol Inspection | General Comments | | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Readings | Follow-up Action Required? | n | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BK000829 | BreakerVacuum | 665-1626 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Readings | Oil Temp Present | 38 | °C |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1371.84 | kw |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Readings | General Comments | | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Readings | Totalizer Meter Reading | .6888 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Readings | Oil Temp Max | 51 | °C |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Readings | LTC Totalizer Reading | 4959.36 | kw |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Readings | General Comments | | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | O0196 | WithLTC | 361-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1357 | Regulator | 411-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1357 | Regulator | 411-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1357 | Regulator | 411-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1357 | Regulator | 411-1 A | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1357 | Regulator | 411-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1357 | Regulator | 411-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1357 | Regulator | 411-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1357 | Regulator | 411-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1357 | Regulator | 411-1 A | Regulator Patrol Inspection | General Comments | | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1357 | Regulator | 411-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1357 | Regulator | 411-1 A | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1357 | Regulator | 411-1 A | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1357 | Regulator | 411-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1357 | Regulator | 411-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1357 | Regulator | 411-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1357 | Regulator | 411-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1357 | Regulator | 411-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 1245.0 | volts |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1357 | Regulator | 411-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 110656 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1357 | Regulator | 411-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1357 | Regulator | 411-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1357 | Regulator | 411-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1357 | Regulator | 411-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000217 | Regulator | 643-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000217 | Regulator | 643-1 A | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000217 | Regulator | 643-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000217 | Regulator | 643-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000217 | Regulator | 643-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000217 | Regulator | 643-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000217 | Regulator | 643-1 A | Regulator Patrol Inspection | General Comments | ok | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000217 | Regulator | 643-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000217 | Regulator | 643-1 A | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000217 | Regulator | 643-1 A | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000217 | Regulator | 643-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000217 | Regulator | 643-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000217 | Regulator | 643-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000217 | Regulator | 643-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000217 | Regulator | 643-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000217 | Regulator | 643-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 5106 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000217 | Regulator | 643-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000217 | Regulator | 643-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000217 | Regulator | 643-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000217 | Regulator | 643-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .8574 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1600 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Low | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | O0176 | NonLTC | 323-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Readings | Winding Temp Max | 55 | °C |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Readings | Winding Temp Present | 25 | °C |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Readings | Amps C Ø | 130.0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Readings | Amps B Ø | 145.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Readings | Amps A Ø | 120.0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Readings | 9 Month Operations | 4 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BAT001418 | Battery | 142-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BAT001418 | Battery | 142-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BAT001418 | Battery | 142-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.1 | VDC |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BAT001418 | Battery | 142-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.4 | VDC |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BAT001418 | Battery | 142-Battery Bank | Battery Patrol Inspection | General Comments | ok | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BAT001418 | Battery | 142-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BAT001418 | Battery | 142-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BAT001418 | Battery | 142-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BAT001418 | Battery | 142-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BAT001418 | Battery | 142-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BAT001418 | Battery | 142-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 68 | °F |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BAT001418 | Battery | 142-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | FE000066 | Fence | 361-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | FE000066 | Fence | 361-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | FE000066 | Fence | 361-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | FE000066 | Fence | 361-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | FE000066 | Fence | 361-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | FE000066 | Fence | 361-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | FE000066 | Fence | 361-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | FE000066 | Fence | 361-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | FE000066 | Fence | 361-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | FE000066 | Fence | 361-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Readings | Fault Operations Ground | 0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Patrol Inspection | General Comments | | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Readings | Follow-up Action Required? | n | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Readings | Fault Operations Ground | 0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BB0372 | BreakerVacuum | 743-0802 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Readings | General Comments | | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 2400 | psi |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 217.50 | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 210.00 | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | T0240 | NonLTC | 009-9 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1214 | Regulator | 323-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1214 | Regulator | 323-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1214 | Regulator | 323-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1214 | Regulator | 323-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1214 | Regulator | 323-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1214 | Regulator | 323-1 C | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1214 | Regulator | 323-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1214 | Regulator | 323-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1214 | Regulator | 323-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1214 | Regulator | 323-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1214 | Regulator | 323-1 C | Regulator Patrol Inspection | General Comments | | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1214 | Regulator | 323-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1214 | Regulator | 323-1 C | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1214 | Regulator | 323-1 C | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1214 | Regulator | 323-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1214 | Regulator | 323-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1214 | Regulator | 323-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1214 | Regulator | 323-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1214 | Regulator | 323-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.8 | volts |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1214 | Regulator | 323-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 71909 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1214 | Regulator | 323-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1214 | Regulator | 323-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1214 | Regulator | 323-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Readings | Fault Operations Ground | 0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | LTCMechanism | 566-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | LTCMechanism | 566-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | LTCMechanism | 566-1 | LTC Counter Readings | General Comments | | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | LTCMechanism | 566-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | LTCMechanism | 566-1 | LTC Counter Readings | LTC As Found Counter | 104264 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | LTCMechanism | 566-1 | LTC Counter Readings | LTC As Left Counter | 104278 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | LTCMechanism | 566-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Readings | Follow-up Action Required? | n | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Patrol Inspection | General Comments | | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Readings | General Comments | Tripp Check | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | WB0162 | BreakerVacuum | 100-1676 | VCB Readings | Maintenance Operations | 1 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | FE000066 | Fence | 361-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | FE000066 | Fence | 361-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | FE000066 | Fence | 361-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | FE000066 | Fence | 361-Fence | Fence Patrol Inspection | General Comments | | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | FE000066 | Fence | 361-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | FE000066 | Fence | 361-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | FE000323 | Fence | 468-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | FE000323 | Fence | 468-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | FE000323 | Fence | 468-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | FE000323 | Fence | 468-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | FE000323 | Fence | 468-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | FE000323 | Fence | 468-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | FE000323 | Fence | 468-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | FE000323 | Fence | 468-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | FE000323 | Fence | 468-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | FE000323 | Fence | 468-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | FE000323 | Fence | 468-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | FE000323 | Fence | 468-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | FE000323 | Fence | 468-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | FE000323 | Fence | 468-Fence | Fence Patrol Inspection | General Comments | ok | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | FE000323 | Fence | 468-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | FE000323 | Fence | 468-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | YD000326 | Yard | 468-Yard | Yard Patrol Inspection | Ambient Temp | 67 | °F |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | YD000326 | Yard | 468-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | YD000326 | Yard | 468-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | YD000326 | Yard | 468-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | YD000326 | Yard | 468-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | YD000326 | Yard | 468-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | YD000326 | Yard | 468-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | YD000326 | Yard | 468-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | YD000326 | Yard | 468-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | YD000326 | Yard | 468-Yard | Yard Patrol Inspection | General Comments | ok | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | YD000326 | Yard | 468-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | YD000326 | Yard | 468-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | YD000326 | Yard | 468-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | YD000326 | Yard | 468-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Readings | Amps C Ø | 10.0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Readings | Amps B Ø | 8.0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Readings | Amps A Ø | 18.0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BK001323 | BreakerVacuum | 468-1668 | VCB Readings | 9 Month Operations | 1 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BAT001506 | Battery | 643-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BAT001506 | Battery | 643-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BAT001506 | Battery | 643-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BAT001506 | Battery | 643-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BAT001506 | Battery | 643-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BAT001506 | Battery | 643-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BAT001506 | Battery | 643-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 69 | °F |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BAT001506 | Battery | 643-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BAT001648 | Battery | 665-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 13.6 | VDC |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BAT001648 | Battery | 665-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BAT001648 | Battery | 665-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BAT001648 | Battery | 665-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BAT001648 | Battery | 665-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BAT001648 | Battery | 665-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BAT001648 | Battery | 665-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BAT001648 | Battery | 665-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 80 | °F |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BCH001436 | Charger | 643-Battery Charger | Battery Charger Patrol Insp | General Comments | ok | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BCH001436 | Charger | 643-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BCH001436 | Charger | 643-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BCH001436 | Charger | 643-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.8 | amps |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BCH001436 | Charger | 643-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.6 | VDC |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BCH001436 | Charger | 643-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.6 | VDC |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BAT001648 | Battery | 665-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Readings | 9 Month Operations | 0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | CH000231 | ControlHouse | 361-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | CH000231 | ControlHouse | 361-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | CH000231 | ControlHouse | 361-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | CH000231 | ControlHouse | 361-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | CH000231 | ControlHouse | 361-Control House | Control House Patrol Inspection | General Comments | | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | CH000231 | ControlHouse | 361-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | CH000231 | ControlHouse | 361-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | CH000231 | ControlHouse | 361-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | CH000231 | ControlHouse | 361-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | CH000231 | ControlHouse | 361-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | CH000231 | ControlHouse | 361-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | CH000231 | ControlHouse | 361-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | CH000231 | ControlHouse | 361-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | CH000231 | ControlHouse | 361-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | CH000231 | ControlHouse | 361-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | CH000231 | ControlHouse | 361-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Readings | Amps A Ø | 18.0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Readings | Amps B Ø | 18.0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Readings | Amps C Ø | 17.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000714 | Structure | 142-Structure Dist | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000714 | Structure | 142-Structure Dist | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000714 | Structure | 142-Structure Dist | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | CH000499 | ControlHouse | 643-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | CH000499 | ControlHouse | 643-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | CH000499 | ControlHouse | 643-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | CH000499 | ControlHouse | 643-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | CH000499 | ControlHouse | 643-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | CH000499 | ControlHouse | 643-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | CH000499 | ControlHouse | 643-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | CH000499 | ControlHouse | 643-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | CH000499 | ControlHouse | 643-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | CH000499 | ControlHouse | 643-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | CH000499 | ControlHouse | 643-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | CH000499 | ControlHouse | 643-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | CH000499 | ControlHouse | 643-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | CH000499 | ControlHouse | 643-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | CH000499 | ControlHouse | 643-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | CH000499 | ControlHouse | 643-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | CH000499 | ControlHouse | 643-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | CH000499 | ControlHouse | 643-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | CH000499 | ControlHouse | 643-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | CH000499 | ControlHouse | 643-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | CH000499 | ControlHouse | 643-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | CH000239 | ControlHouse | 411-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | CH000239 | ControlHouse | 411-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | CH000239 | ControlHouse | 411-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | CH000239 | ControlHouse | 411-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | CH000239 | ControlHouse | 411-Control House | Control House Patrol Inspection | General Comments | | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | CH000239 | ControlHouse | 411-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | CH000239 | ControlHouse | 411-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | CH000239 | ControlHouse | 411-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | CH000239 | ControlHouse | 411-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | CH000239 | ControlHouse | 411-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | CH000239 | ControlHouse | 411-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | CH000239 | ControlHouse | 411-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | CH000239 | ControlHouse | 411-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | CH000239 | ControlHouse | 411-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | CH000239 | ControlHouse | 411-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | CH000239 | ControlHouse | 411-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BAT001506 | Battery | 643-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BAT001506 | Battery | 643-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BAT001506 | Battery | 643-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 25.6 | VDC |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BAT001506 | Battery | 643-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.8 | VDC |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BAT001506 | Battery | 643-Battery Bank | Battery Patrol Inspection | General Comments | ok | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BAT001506 | Battery | 643-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BAT001506 | Battery | 643-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Readings | Fault Operations Ground | 0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Readings | Follow-up Action Required? | n | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Patrol Inspection | General Comments | ok | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Readings | General Comments | ok | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Readings | Maintenance Operations | 0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Readings | Operations Counter AF | 173 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Readings | Operations Counter AL | 173 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Readings | Operations This Read Vac | 0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Readings | Switching Operations | 0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Readings | Unknown Operations | 0 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BAT001471 | Battery | 411-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BAT001471 | Battery | 411-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0176 | NonLTC | 646-1 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0176 | NonLTC | 646-1 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0176 | NonLTC | 646-1 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0176 | NonLTC | 646-1 B | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0176 | NonLTC | 646-1 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0176 | NonLTC | 646-1 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0176 | NonLTC | 646-1 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0176 | NonLTC | 646-1 B | NonLTC Transformer Readings | Oil Temp Present | 33 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0176 | NonLTC | 646-1 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0176 | NonLTC | 646-1 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0176 | NonLTC | 646-1 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0176 | NonLTC | 646-1 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0176 | NonLTC | 646-1 B | NonLTC Transformer Readings | General Comments | ok | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0176 | NonLTC | 646-1 B | NonLTC Transformer Patrol Inspection | General Comments | H2 bushing has a chipped skirt. | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0176 | NonLTC | 646-1 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0176 | NonLTC | 646-1 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0176 | NonLTC | 646-1 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0176 | NonLTC | 646-1 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0176 | NonLTC | 646-1 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0176 | NonLTC | 646-1 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0176 | NonLTC | 646-1 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0176 | NonLTC | 646-1 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .6666 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BAT001466 | Battery | 819-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BAT001466 | Battery | 819-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | YD000112 | Yard | 323-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | YD000112 | Yard | 323-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | YD000112 | Yard | 323-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | YD000112 | Yard | 323-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | YD000112 | Yard | 323-Yard | Yard Patrol Inspection | General Comments | | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | YD000112 | Yard | 323-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | YD000112 | Yard | 323-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | YD000112 | Yard | 323-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | ST000065 | Structure | 361-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | ST000065 | Structure | 361-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | ST000065 | Structure | 361-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | ST000065 | Structure | 361-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | ST000065 | Structure | 361-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | ST000065 | Structure | 361-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | ST000065 | Structure | 361-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | ST000065 | Structure | 361-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | ST000065 | Structure | 361-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | ST000065 | Structure | 361-Structure | Structure Patrol Inspection | General Comments | | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | ST000065 | Structure | 361-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | ST000065 | Structure | 361-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | ST000065 | Structure | 361-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | ST000065 | Structure | 361-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | ST000065 | Structure | 361-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | ST000065 | Structure | 361-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | ST000065 | Structure | 361-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | ST000065 | Structure | 361-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | ST000065 | Structure | 361-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | YD000112 | Yard | 323-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | YD000112 | Yard | 323-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | YD000112 | Yard | 323-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | YD000112 | Yard | 323-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | YD000112 | Yard | 323-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | YD000112 | Yard | 323-Yard | Yard Patrol Inspection | Ambient Temp | 70 | °F |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | ST000065 | Structure | 361-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | ST000065 | Structure | 361-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | ST000065 | Structure | 361-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001636 | BreakerVacuum | 643-308 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.0410 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Readings | Winding Temp Max | 86 | °C |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Readings | Winding Temp Present | 68 | °C |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Readings | Maintenance Operations | 1 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Readings | Operations Counter AF | 188 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Readings | Operations Counter AL | 188 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Readings | Operations This Read Vac | 1 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | BAT001475 | Battery | 323-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | BAT001475 | Battery | 323-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | BAT001475 | Battery | 323-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.3 | VDC |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | BAT001475 | Battery | 323-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.4 | VDC |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | BAT001475 | Battery | 323-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1358 | Regulator | 411-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1358 | Regulator | 411-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 117255 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1358 | Regulator | 411-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1358 | Regulator | 411-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1358 | Regulator | 411-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1358 | Regulator | 411-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1358 | Regulator | 411-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1358 | Regulator | 411-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1358 | Regulator | 411-1 B | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1358 | Regulator | 411-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1358 | Regulator | 411-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1358 | Regulator | 411-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1358 | Regulator | 411-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1358 | Regulator | 411-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1358 | Regulator | 411-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1358 | Regulator | 411-1 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1358 | Regulator | 411-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1358 | Regulator | 411-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1358 | Regulator | 411-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1358 | Regulator | 411-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1358 | Regulator | 411-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | YD000304 | Yard | 819-Yard | Yard Patrol Inspection | Ambient Temp | 65 | °F |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | YD000304 | Yard | 819-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | YD000304 | Yard | 819-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | YD000304 | Yard | 819-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | YD000304 | Yard | 819-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | YD000304 | Yard | 819-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | YD000304 | Yard | 819-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | YD000304 | Yard | 819-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | YD000304 | Yard | 819-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | YD000304 | Yard | 819-Yard | Yard Patrol Inspection | General Comments | | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | YD000304 | Yard | 819-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | YD000304 | Yard | 819-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | YD000304 | Yard | 819-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | YD000304 | Yard | 819-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | ST000312 | Structure | 819-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | ST000312 | Structure | 819-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | ST000312 | Structure | 819-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | ST000312 | Structure | 819-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | ST000312 | Structure | 819-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | ST000312 | Structure | 819-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | ST000312 | Structure | 819-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | ST000312 | Structure | 819-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | ST000312 | Structure | 819-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | ST000312 | Structure | 819-Structure | Structure Patrol Inspection | General Comments | | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | ST000312 | Structure | 819-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | ST000312 | Structure | 819-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | ST000312 | Structure | 819-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | ST000312 | Structure | 819-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | ST000312 | Structure | 819-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | ST000312 | Structure | 819-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | ST000312 | Structure | 819-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | ST000312 | Structure | 819-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | ST000312 | Structure | 819-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | ST000312 | Structure | 819-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | ST000312 | Structure | 819-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | ST000312 | Structure | 819-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Readings | Totalizer Meter Reading | .4596 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1358 | Regulator | 411-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1358 | Regulator | 411-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | R1358 | Regulator | 411-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | ST000056 | Structure | 411-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | ST000056 | Structure | 411-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | ST000056 | Structure | 411-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | ST000056 | Structure | 411-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | ST000056 | Structure | 411-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | ST000056 | Structure | 411-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | ST000056 | Structure | 411-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | ST000056 | Structure | 411-Structure | Structure Patrol Inspection | General Comments | | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | ST000056 | Structure | 411-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | ST000056 | Structure | 411-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | ST000056 | Structure | 411-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | ST000056 | Structure | 411-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | ST000056 | Structure | 411-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | ST000056 | Structure | 411-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | ST000056 | Structure | 411-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | ST000056 | Structure | 411-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | ST000056 | Structure | 411-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000714 | Structure | 142-Structure Dist | Structure Patrol Inspection | Wood Structures OK? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000714 | Structure | 142-Structure Dist | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000714 | Structure | 142-Structure Dist | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000714 | Structure | 142-Structure Dist | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000714 | Structure | 142-Structure Dist | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000714 | Structure | 142-Structure Dist | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000714 | Structure | 142-Structure Dist | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000714 | Structure | 142-Structure Dist | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | BAT001475 | Battery | 323-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | BAT001475 | Battery | 323-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | BAT001475 | Battery | 323-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | BAT001475 | Battery | 323-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | BAT001475 | Battery | 323-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | BAT001475 | Battery | 323-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | BAT001475 | Battery | 323-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 85 | °F |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | BAT001475 | Battery | 323-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Readings | Switching Operations | 0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Readings | Unknown Operations | 0 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000714 | Structure | 142-Structure Dist | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000714 | Structure | 142-Structure Dist | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BAT001648 | Battery | 665-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BAT001648 | Battery | 665-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | BAT001648 | Battery | 665-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 13.5 | VDC |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000714 | Structure | 142-Structure Dist | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000714 | Structure | 142-Structure Dist | Structure Patrol Inspection | General Comments | Xfmr fuse barrels are starting to fray. Whole structure needs wildlife protection. | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000714 | Structure | 142-Structure Dist | Structure Patrol Inspection | Fuse Barrels Good Condition? | n | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000714 | Structure | 142-Structure Dist | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000714 | Structure | 142-Structure Dist | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | ST000714 | Structure | 142-Structure Dist | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Readings | LTC Totalizer Reading | 4412.16 | kw |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Readings | General Comments | | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | C0504 | WithLTC | 665-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1051 | Regulator | 142-5 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1051 | Regulator | 142-5 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1051 | Regulator | 142-5 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1051 | Regulator | 142-5 B | Regulator Patrol Inspection | Regulator As Left Counter | 212182 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1051 | Regulator | 142-5 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1051 | Regulator | 142-5 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1051 | Regulator | 142-5 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1051 | Regulator | 142-5 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1051 | Regulator | 142-5 B | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1051 | Regulator | 142-5 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1051 | Regulator | 142-5 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1051 | Regulator | 142-5 B | Regulator Patrol Inspection | General Comments | ok | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1051 | Regulator | 142-5 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1051 | Regulator | 142-5 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1051 | Regulator | 142-5 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1051 | Regulator | 142-5 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1051 | Regulator | 142-5 B | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1051 | Regulator | 142-5 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1051 | Regulator | 142-5 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1051 | Regulator | 142-5 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1051 | Regulator | 142-5 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1051 | Regulator | 142-5 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | ST000056 | Structure | 411-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | ST000056 | Structure | 411-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | ST000056 | Structure | 411-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | ST000056 | Structure | 411-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | ST000056 | Structure | 411-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BAT001471 | Battery | 411-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BAT001471 | Battery | 411-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BAT001471 | Battery | 411-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BAT001471 | Battery | 411-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | BCH001409 | Charger | 323-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | BCH001409 | Charger | 323-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | BCH001409 | Charger | 323-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | BCH001409 | Charger | 323-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | BCH001409 | Charger | 323-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .2 | amps |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1212 | Regulator | 323-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1212 | Regulator | 323-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1212 | Regulator | 323-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1212 | Regulator | 323-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 70015 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1212 | Regulator | 323-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1212 | Regulator | 323-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1212 | Regulator | 323-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1212 | Regulator | 323-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1212 | Regulator | 323-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1212 | Regulator | 323-1 B | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1212 | Regulator | 323-1 B | Regulator Patrol Inspection | Max Tap Position | 1L | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1212 | Regulator | 323-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1212 | Regulator | 323-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1212 | Regulator | 323-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1212 | Regulator | 323-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1212 | Regulator | 323-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1212 | Regulator | 323-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1212 | Regulator | 323-1 B | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1212 | Regulator | 323-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1212 | Regulator | 323-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1212 | Regulator | 323-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1212 | Regulator | 323-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | R1212 | Regulator | 323-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BAT001391 | Battery | 361-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BAT001391 | Battery | 361-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BAT001391 | Battery | 361-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.1 | VDC |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BAT001391 | Battery | 361-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.3 | VDC |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BAT001391 | Battery | 361-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BAT001391 | Battery | 361-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BAT001391 | Battery | 361-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BAT001391 | Battery | 361-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BAT001391 | Battery | 361-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BAT001391 | Battery | 361-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BAT001391 | Battery | 361-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BAT001391 | Battery | 361-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 78 | °F |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BAT001391 | Battery | 361-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | BCH001409 | Charger | 323-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | BCH001409 | Charger | 323-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Readings | Oil Temp Present | 28 | °C |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Readings | Oil Temp Max | 48 | °C |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0661 | Regulator | 646-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0661 | Regulator | 646-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 52829 | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0661 | Regulator | 646-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0661 | Regulator | 646-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Readings | LTC Totalizer Reading | 7420.80 | kw |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Readings | General Comments | | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0661 | Regulator | 646-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0661 | Regulator | 646-1 A | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0661 | Regulator | 646-1 A | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0661 | Regulator | 646-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0661 | Regulator | 646-1 A | Regulator Patrol Inspection | General Comments | ok | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0661 | Regulator | 646-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0661 | Regulator | 646-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0661 | Regulator | 646-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0661 | Regulator | 646-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0661 | Regulator | 646-1 A | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0661 | Regulator | 646-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0661 | Regulator | 646-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0661 | Regulator | 646-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0661 | Regulator | 646-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0661 | Regulator | 646-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BAT001471 | Battery | 411-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | RLY027319 | RelayMicroprocessor | 009-3412 Panel | Relay Microprocessor DC Circuit Check | Prove All BFI DC Paths | na | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | RLY027319 | RelayMicroprocessor | 009-3412 Panel | Relay Microprocessor DC Circuit Check | General Comments | | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | RLY027319 | RelayMicroprocessor | 009-3412 Panel | Relay Microprocessor DC Circuit Check | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BCH001406 | Charger | 411-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BCH001406 | Charger | 411-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .6 | amps |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BCH001406 | Charger | 411-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BCH001406 | Charger | 411-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | FE000895 | Fence | 566-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | FE000895 | Fence | 566-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | FE000895 | Fence | 566-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | FE000895 | Fence | 566-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | FE000895 | Fence | 566-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | FE000895 | Fence | 566-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | FE000895 | Fence | 566-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | FE000895 | Fence | 566-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | FE000895 | Fence | 566-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | FE000895 | Fence | 566-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | FE000895 | Fence | 566-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | FE000895 | Fence | 566-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | FE000895 | Fence | 566-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | FE000895 | Fence | 566-Fence | Fence Patrol Inspection | General Comments | | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | FE000895 | Fence | 566-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | FE000895 | Fence | 566-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BCH001406 | Charger | 411-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BCH001406 | Charger | 411-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | RLY027319 | RelayMicroprocessor | 009-3412 Panel | Relay Microprocessor DC Circuit Check | Alarm Operation Correct? | n | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | RLY027318 | RelayMicroprocessor | 009-3412 Panel | Relay Microprocessor DC Circuit Check | Trip Bkr Coil 2 or Aux Rly | na | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | RLY027318 | RelayMicroprocessor | 009-3412 Panel | Relay Microprocessor DC Circuit Check | Trip Bkr Coil 1 or Aux Rly | n | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | RLY027318 | RelayMicroprocessor | 009-3412 Panel | Relay Microprocessor DC Circuit Check | Prove All BFI DC Paths | na | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | RLY027318 | RelayMicroprocessor | 009-3412 Panel | Relay Microprocessor DC Circuit Check | General Comments | | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | RLY027318 | RelayMicroprocessor | 009-3412 Panel | Relay Microprocessor DC Circuit Check | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | BCH001409 | Charger | 323-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .600 | millivolts |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000136 | Regulator | 468-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000136 | Regulator | 468-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000136 | Regulator | 468-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000136 | Regulator | 468-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000136 | Regulator | 468-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 8365 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000136 | Regulator | 468-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000136 | Regulator | 468-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000136 | Regulator | 468-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000136 | Regulator | 468-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000136 | Regulator | 468-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000136 | Regulator | 468-1 B | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Readings | Totalizer Meter Reading | .7656 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Readings | Oil Temp Max | 39 | °C |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Readings | LTC Totalizer Reading | 7349.76 | kw |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BCH001406 | Charger | 411-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 2.400 | millivolts |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BCH001406 | Charger | 411-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | WithLTC | 343-1 | LTC Transformer Readings | General Comments | | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000136 | Regulator | 468-1 B | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000136 | Regulator | 468-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000136 | Regulator | 468-1 B | Regulator Patrol Inspection | General Comments | ok | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000136 | Regulator | 468-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000136 | Regulator | 468-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000136 | Regulator | 468-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000136 | Regulator | 468-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000136 | Regulator | 468-1 B | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000136 | Regulator | 468-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000136 | Regulator | 468-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000136 | Regulator | 468-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000136 | Regulator | 468-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000136 | Regulator | 468-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | RLY027319 | RelayMicroprocessor | 009-3412 Panel | Relay Microprocessor DC Circuit Check | Trip Bkr Coil 2 or Aux Rly | na | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | RLY027319 | RelayMicroprocessor | 009-3412 Panel | Relay Microprocessor DC Circuit Check | Trip Bkr Coil 1 or Aux Rly | n | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | RLY027319 | RelayMicroprocessor | 009-3412 Panel | Relay Microprocessor DC Circuit Check | Relay Trip Targets OK? | na | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Readings | Amps A Ø | 0.0 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Readings | Amps B Ø | 0.0 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Readings | Amps C Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BAT001471 | Battery | 411-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BAT001471 | Battery | 411-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.0 | VDC |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BAT001471 | Battery | 411-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BAT001471 | Battery | 411-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BAT001471 | Battery | 411-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BAT001471 | Battery | 411-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0661 | Regulator | 646-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0661 | Regulator | 646-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1320 | Regulator | 410-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1320 | Regulator | 410-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1320 | Regulator | 410-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1320 | Regulator | 410-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1320 | Regulator | 410-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1320 | Regulator | 410-1 A | Regulator Patrol Inspection | Current Tap Position | 9L | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1320 | Regulator | 410-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1320 | Regulator | 410-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1320 | Regulator | 410-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1320 | Regulator | 410-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1320 | Regulator | 410-1 A | Regulator Patrol Inspection | General Comments | | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1320 | Regulator | 410-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1320 | Regulator | 410-1 A | Regulator Patrol Inspection | Max Tap Position | 1L | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1320 | Regulator | 410-1 A | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1320 | Regulator | 410-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1320 | Regulator | 410-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1320 | Regulator | 410-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1320 | Regulator | 410-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1320 | Regulator | 410-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.6 | volts |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1320 | Regulator | 410-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 38793 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1320 | Regulator | 410-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BAT001466 | Battery | 819-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BAT001466 | Battery | 819-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BAT001466 | Battery | 819-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BAT001466 | Battery | 819-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BAT001466 | Battery | 819-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BAT001466 | Battery | 819-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BAT001466 | Battery | 819-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BAT001466 | Battery | 819-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BAT001466 | Battery | 819-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BAT001466 | Battery | 819-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BAT001466 | Battery | 819-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BCH001402 | Charger | 819-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Readings | Oil Temp Present | 55 | °C |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Readings | Oil Temp Max | 55 | °C |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 6399.36 | kw |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Readings | General Comments | | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | S0021 | NonLTC | 410-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BCH001402 | Charger | 819-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BCH001402 | Charger | 819-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BCH001402 | Charger | 819-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.3 | amps |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BCH001402 | Charger | 819-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BCH001402 | Charger | 819-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BCH001402 | Charger | 819-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BCH001402 | Charger | 819-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Readings | 9 Month Operations | 2 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | YD000042 | Yard | 566-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | YD000042 | Yard | 566-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1322 | Regulator | 410-1 C | Regulator Patrol Inspection | Current Tap Position | 9L | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1322 | Regulator | 410-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1322 | Regulator | 410-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1322 | Regulator | 410-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1322 | Regulator | 410-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1322 | Regulator | 410-1 C | Regulator Patrol Inspection | General Comments | | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1322 | Regulator | 410-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1322 | Regulator | 410-1 C | Regulator Patrol Inspection | Max Tap Position | 1L | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1322 | Regulator | 410-1 C | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1322 | Regulator | 410-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1322 | Regulator | 410-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1322 | Regulator | 410-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1322 | Regulator | 410-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1322 | Regulator | 410-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.4 | volts |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1322 | Regulator | 410-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 43798 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1322 | Regulator | 410-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1322 | Regulator | 410-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1322 | Regulator | 410-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | YD000042 | Yard | 566-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | YD000042 | Yard | 566-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | YD000042 | Yard | 566-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | YD000042 | Yard | 566-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | YD000042 | Yard | 566-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | YD000042 | Yard | 566-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | YD000042 | Yard | 566-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | YD000042 | Yard | 566-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | YD000042 | Yard | 566-Yard | Yard Patrol Inspection | General Comments | | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | YD000042 | Yard | 566-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | YD000042 | Yard | 566-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | YD000042 | Yard | 566-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BCH001319 | Charger | 361-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BCH001319 | Charger | 361-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BCH001319 | Charger | 361-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BCH001319 | Charger | 361-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BCH001319 | Charger | 361-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.1 | amps |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BCH001319 | Charger | 361-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.3 | VDC |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BCH001319 | Charger | 361-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.3 | VDC |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | BCH001319 | Charger | 361-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.500 | millivolts |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Readings | Totalizer Meter Reading | .7730 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | C0531 | WithLTC | 566-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1320 | Regulator | 410-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1320 | Regulator | 410-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1321 | Regulator | 410-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1321 | Regulator | 410-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1321 | Regulator | 410-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1321 | Regulator | 410-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1321 | Regulator | 410-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1321 | Regulator | 410-1 B | Regulator Patrol Inspection | Current Tap Position | 9L | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1321 | Regulator | 410-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1321 | Regulator | 410-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1321 | Regulator | 410-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1321 | Regulator | 410-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1321 | Regulator | 410-1 B | Regulator Patrol Inspection | General Comments | | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1321 | Regulator | 410-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1321 | Regulator | 410-1 B | Regulator Patrol Inspection | Max Tap Position | 4L | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1321 | Regulator | 410-1 B | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1321 | Regulator | 410-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1321 | Regulator | 410-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1321 | Regulator | 410-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1321 | Regulator | 410-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1321 | Regulator | 410-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1321 | Regulator | 410-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 38578 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1321 | Regulator | 410-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Readings | Fault Operations Ground | 0 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Readings | Follow-up Action Required? | n | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Patrol Inspection | General Comments | | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Readings | General Comments | | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1321 | Regulator | 410-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1321 | Regulator | 410-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1322 | Regulator | 410-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1322 | Regulator | 410-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1322 | Regulator | 410-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1322 | Regulator | 410-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | R1322 | Regulator | 410-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Readings | Maintenance Operations | 0 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Readings | Operations Counter AF | 294 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Readings | Operations Counter AL | 294 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Readings | Operations This Read Vac | 0 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Readings | Switching Operations | 0 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | K0063 | BreakerVacuum | 411-4618 | VCB Readings | Unknown Operations | 0 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Readings | General Comments | | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | ST000101 | Structure | 343-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | ST000101 | Structure | 343-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | ST000101 | Structure | 343-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | ST000101 | Structure | 343-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | ST000101 | Structure | 343-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | ST000101 | Structure | 343-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 97.50 | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 2262.24 | kw |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Readings | General Comments | ok | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Patrol Inspection | General Comments | ok | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | ST000101 | Structure | 343-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | ST000101 | Structure | 343-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | ST000101 | Structure | 343-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | ST000101 | Structure | 343-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | ST000101 | Structure | 343-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | ST000101 | Structure | 343-Structure | Structure Patrol Inspection | General Comments | | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | ST000101 | Structure | 343-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | ST000101 | Structure | 343-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | ST000101 | Structure | 343-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | ST000101 | Structure | 343-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | ST000101 | Structure | 343-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | ST000101 | Structure | 343-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | ST000101 | Structure | 343-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | ST000101 | Structure | 343-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | ST000101 | Structure | 343-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Readings | LTC Totalizer Reading | 4757.76 | kw |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Readings | Oil Temp Max | 52 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | YD000165 | Yard | 361-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | YD000165 | Yard | 361-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | YD000165 | Yard | 361-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | YD000165 | Yard | 361-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | YD000165 | Yard | 361-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | YD000165 | Yard | 361-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | YD000165 | Yard | 361-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | YD000165 | Yard | 361-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | YD000165 | Yard | 361-Yard | Yard Patrol Inspection | Ambient Temp | 65 | °F |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BAT001305 | Battery | 743-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BAT001305 | Battery | 743-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BAT001305 | Battery | 743-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BAT001305 | Battery | 743-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BAT001305 | Battery | 743-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BAT001305 | Battery | 743-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BAT001305 | Battery | 743-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BAT001305 | Battery | 743-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BAT001305 | Battery | 743-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BAT001305 | Battery | 743-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BAT001305 | Battery | 743-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BAT001305 | Battery | 743-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BAT001305 | Battery | 743-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 55 | °F |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BAT001305 | Battery | 743-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .9426 | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Adequate | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Readings | Amps A Ø | 398.0 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Readings | Amps B Ø | 408.0 | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Readings | Oil Temp Present | 38 | °C |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Readings | Oil Temp Max | 55 | °C |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | T0170 | NonLTC | 142-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | T0170 | NonLTC | 142-2 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | T0170 | NonLTC | 142-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | T0170 | NonLTC | 142-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | T0170 | NonLTC | 142-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | T0170 | NonLTC | 142-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | T0170 | NonLTC | 142-2 | NonLTC Transformer Patrol Inspection | General Comments | 2 fans on LV radiator side not working | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | T0170 | NonLTC | 142-2 | NonLTC Transformer Readings | General Comments | ok | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | T0170 | NonLTC | 142-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | T0170 | NonLTC | 142-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | T0170 | NonLTC | 142-2 | NonLTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 625 | psi |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | T0170 | NonLTC | 142-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | T0170 | NonLTC | 142-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | T0170 | NonLTC | 142-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | T0170 | NonLTC | 142-2 | NonLTC Transformer Readings | Oil Temp Present | 51 | °C |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | T0170 | NonLTC | 142-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | T0170 | NonLTC | 142-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | T0170 | NonLTC | 142-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | T0170 | NonLTC | 142-2 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | T0170 | NonLTC | 142-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | T0170 | NonLTC | 142-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | T0170 | NonLTC | 142-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | T0170 | NonLTC | 142-2 | NonLTC Transformer Readings | Winding Temp Present | 54 | °C |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Readings | Amps C Ø | 401.0 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Readings | Fault Operations Ground | 0 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Readings | Follow-up Action Required? | n | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Patrol Inspection | General Comments | | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Readings | General Comments | | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Readings | Maintenance Operations | 0 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Readings | Operations Counter AF | 209 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Readings | Totalizer Meter Reading | .4956 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 200.00 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0316 | WithLTC | 100-6 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | YD000094 | Yard | 343-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | YD000094 | Yard | 343-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | YD000094 | Yard | 343-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | YD000094 | Yard | 343-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | YD000094 | Yard | 343-Yard | Yard Patrol Inspection | General Comments | | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | YD000094 | Yard | 343-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | YD000094 | Yard | 343-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | B0202 | NonLTC | 817-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | YD000094 | Yard | 343-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | YD000094 | Yard | 343-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | YD000094 | Yard | 343-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | YD000094 | Yard | 343-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | YD000094 | Yard | 343-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | YD000094 | Yard | 343-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | YD000094 | Yard | 343-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | YD000094 | Yard | 343-Yard | Yard Patrol Inspection | Ambient Temp | 70 | °F |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | FE000094 | Fence | 343-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | FE000094 | Fence | 343-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | FE000094 | Fence | 343-Fence | Fence Patrol Inspection | General Comments | | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | FE000094 | Fence | 343-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | FE000094 | Fence | 343-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | FE000094 | Fence | 343-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | FE000094 | Fence | 343-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | FE000094 | Fence | 343-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | FE000094 | Fence | 343-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | FE000094 | Fence | 343-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | FE000094 | Fence | 343-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | FE000094 | Fence | 343-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | FE000094 | Fence | 343-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | FE000094 | Fence | 343-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | FE000094 | Fence | 343-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | FE000094 | Fence | 343-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | T0170 | NonLTC | 142-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | T0170 | NonLTC | 142-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | T0170 | NonLTC | 142-2 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | T0170 | NonLTC | 142-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Readings | Unknown Operations | 0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | LTCC000565 | LTCControl | 743-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | LTCC000565 | LTCControl | 743-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | LTCC000565 | LTCControl | 743-2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | LTCC000565 | LTCControl | 743-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | LTCC000565 | LTCControl | 743-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | LTCC000565 | LTCControl | 743-2 | LTC Control Insp | General Comments | | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | LTCC000565 | LTCControl | 743-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | LTCC000565 | LTCControl | 743-2 | LTC Control Insp | All Connections OK? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | FE000052 | Fence | 411-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Readings | Unknown Operations | 0 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Readings | Switching Operations | 0 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Readings | Operations This Read Vac | 1 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Readings | Operations Counter AL | 190 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Readings | Operations Counter AF | 190 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Readings | Maintenance Operations | 1 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Readings | General Comments | Trip Check | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Patrol Inspection | General Comments | | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Readings | Follow-up Action Required? | n | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Readings | Fault Operations Ground | 0 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BK000781 | BreakerVacuum | 100-1679 | VCB Readings | 9 Month Operations | 1 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | YD000051 | Yard | 411-Yard | Yard Patrol Inspection | Ambient Temp | 75 | °F |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | YD000051 | Yard | 411-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | BAT001660 | Battery | 410-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 28.1 | VDC |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | BAT001660 | Battery | 410-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Readings | Fault Operations Ground | 0 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | BAT001660 | Battery | 410-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | BAT001660 | Battery | 410-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | BAT001660 | Battery | 410-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | BAT001660 | Battery | 410-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | BAT001660 | Battery | 410-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | BAT001660 | Battery | 410-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 80 | °F |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | BAT001660 | Battery | 410-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BAT001655 | Battery | 100-Battery Bank 2 | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BAT001655 | Battery | 100-Battery Bank 2 | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BAT001655 | Battery | 100-Battery Bank 2 | Battery Patrol Inspection | Positive DC Ground | 8.5 | VDC |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BAT001655 | Battery | 100-Battery Bank 2 | Battery Patrol Inspection | Negative DC Ground | 8.4 | VDC |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BAT001655 | Battery | 100-Battery Bank 2 | Battery Patrol Inspection | General Comments | | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BAT001655 | Battery | 100-Battery Bank 2 | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BAT001655 | Battery | 100-Battery Bank 2 | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BAT001655 | Battery | 100-Battery Bank 2 | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BAT001655 | Battery | 100-Battery Bank 2 | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BAT001655 | Battery | 100-Battery Bank 2 | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BAT001655 | Battery | 100-Battery Bank 2 | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BAT001655 | Battery | 100-Battery Bank 2 | Battery Patrol Inspection | All Connections OK? | y | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Readings | Follow-up Action Required? | n | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Readings | Winding Temp Present | 31 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Readings | Winding Temp Max | 34 | °C |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Patrol Inspection | General Comments | | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Readings | General Comments | | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Readings | Maintenance Operations | 0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .2634 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Readings | Operations Counter AF | 245 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Readings | Operations Counter AL | 245 | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Readings | Operations This Read Vac | 0 | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/1/2023 12:05 | Distribution | Green River Quarterly Inspection | KB0034 | BreakerVacuum | 009-3412 | VCB Readings | Switching Operations | 0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | ST000324 | Structure | 643-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | ST000324 | Structure | 643-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | ST000324 | Structure | 643-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | ST000324 | Structure | 643-Structure | Structure Patrol Inspection | General Comments | Xfmr is not fused, has high side breaker. | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | ST000324 | Structure | 643-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | n | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | ST000324 | Structure | 643-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | ST000324 | Structure | 643-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | ST000324 | Structure | 643-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | ST000324 | Structure | 643-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | ST000324 | Structure | 643-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | ST000324 | Structure | 643-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | ST000324 | Structure | 643-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | ST000324 | Structure | 643-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | YD000319 | Yard | 643-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | YD000319 | Yard | 643-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | YD000319 | Yard | 643-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | n | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | YD000319 | Yard | 643-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | YD000319 | Yard | 643-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | YD000319 | Yard | 643-Yard | Yard Patrol Inspection | General Comments | There is no longer an SPR. | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | YD000319 | Yard | 643-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | YD000319 | Yard | 643-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | YD000319 | Yard | 643-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | YD000319 | Yard | 643-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | YD000319 | Yard | 643-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | YD000319 | Yard | 643-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | YD000319 | Yard | 643-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | YD000319 | Yard | 643-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | YD000319 | Yard | 643-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | YD000319 | Yard | 643-Yard | Yard Patrol Inspection | Ambient Temp | 69 | °F |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Readings | 9 Month Operations | 4 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | YD000165 | Yard | 361-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | YD000165 | Yard | 361-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | YD000165 | Yard | 361-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | YD000165 | Yard | 361-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | YD000165 | Yard | 361-Yard | Yard Patrol Inspection | General Comments | | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | YD000051 | Yard | 411-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | YD000051 | Yard | 411-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | YD000051 | Yard | 411-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | YD000051 | Yard | 411-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | YD000051 | Yard | 411-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | YD000051 | Yard | 411-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | YD000051 | Yard | 411-Yard | Yard Patrol Inspection | General Comments | | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | YD000051 | Yard | 411-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | YD000051 | Yard | 411-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | YD000051 | Yard | 411-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | LTCC000830 | LTCControl | 100-6 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | LTCC000830 | LTCControl | 100-6 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | LTCC000830 | LTCControl | 100-6 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | LTCC000830 | LTCControl | 100-6 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | LTCC000830 | LTCControl | 100-6 | LTC Control Insp | LTC Output Voltage Level | 124.1 | VAC |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | LTCC000830 | LTCControl | 100-6 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | LTCC000830 | LTCControl | 100-6 | LTC Control Insp | General Comments | | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | LTCC000830 | LTCControl | 100-6 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | LTCC000830 | LTCControl | 100-6 | LTC Control Insp | All Connections OK? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Readings | Oil Temp Present | 31 | °C |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Readings | Oil Temp Max | 36 | °C |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1896.48 | kw |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Readings | General Comments | ok | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Patrol Inspection | General Comments | ok | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | TX000254 | NonLTC | 643-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | ST000324 | Structure | 643-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | ST000324 | Structure | 643-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | ST000324 | Structure | 643-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | ST000324 | Structure | 643-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | ST000324 | Structure | 643-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | ST000324 | Structure | 643-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | ST000324 | Structure | 643-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | ST000324 | Structure | 643-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | ST000324 | Structure | 643-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Readings | Operations This Read Vac | 1 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Readings | Switching Operations | 0 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Readings | Unknown Operations | 0 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R0758 | Regulator | 142-5 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R0758 | Regulator | 142-5 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R0758 | Regulator | 142-5 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R0758 | Regulator | 142-5 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R0758 | Regulator | 142-5 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R0758 | Regulator | 142-5 A | Regulator Patrol Inspection | Current Tap Position | 2R | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R0758 | Regulator | 142-5 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R0758 | Regulator | 142-5 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R0758 | Regulator | 142-5 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R0758 | Regulator | 142-5 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R0758 | Regulator | 142-5 A | Regulator Patrol Inspection | General Comments | ok | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R0758 | Regulator | 142-5 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R0758 | Regulator | 142-5 A | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R0758 | Regulator | 142-5 A | Regulator Patrol Inspection | Min Tap Position | 1L | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R0758 | Regulator | 142-5 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R0758 | Regulator | 142-5 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R0758 | Regulator | 142-5 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R0758 | Regulator | 142-5 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R0758 | Regulator | 142-5 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R0758 | Regulator | 142-5 A | Regulator Patrol Inspection | Regulator As Left Counter | 1343 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R0758 | Regulator | 142-5 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | FE000264 | Fence | 410-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | FE000264 | Fence | 410-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | FE000264 | Fence | 410-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | FE000264 | Fence | 410-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | FE000264 | Fence | 410-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | FE000264 | Fence | 410-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Readings | General Comments | 1 trip check | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Patrol Inspection | General Comments | ok | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R0758 | Regulator | 142-5 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R0758 | Regulator | 142-5 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | YD000266 | Yard | 410-Yard | Yard Patrol Inspection | Ambient Temp | 80 | °F |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | FE000264 | Fence | 410-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | FE000264 | Fence | 410-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | FE000264 | Fence | 410-Fence | Fence Patrol Inspection | General Comments | | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | FE000264 | Fence | 410-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | FE000264 | Fence | 410-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | FE000264 | Fence | 410-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | FE000264 | Fence | 410-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | FE000264 | Fence | 410-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | FE000264 | Fence | 410-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | FE000264 | Fence | 410-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Readings | Fault Operations Ground | 0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Readings | Follow-up Action Required? | n | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Readings | Fault Operations Ground | 0 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Readings | Follow-up Action Required? | n | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Patrol Inspection | General Comments | | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Readings | General Comments | TIP CHECK | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Readings | Maintenance Operations | 1 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Readings | Operations Counter AF | 328 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Readings | Operations Counter AL | 328 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BCH001217 | Charger | 743-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | YD000262 | Yard | 665-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | YD000262 | Yard | 665-Yard | Yard Patrol Inspection | General Comments | No SPR system | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | YD000262 | Yard | 665-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | YD000262 | Yard | 665-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | YD000262 | Yard | 665-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | YD000262 | Yard | 665-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | YD000262 | Yard | 665-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | YD000262 | Yard | 665-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | YD000262 | Yard | 665-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | YD000262 | Yard | 665-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | YD000262 | Yard | 665-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | YD000262 | Yard | 665-Yard | Yard Patrol Inspection | Ambient Temp | 79 | °F |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | FE000260 | Fence | 665-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | FE000260 | Fence | 665-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | FE000260 | Fence | 665-Fence | Fence Patrol Inspection | General Comments | | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | FE000260 | Fence | 665-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | LTCMechanism | 566-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | LTCMechanism | 566-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | LTCMechanism | 566-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | LTCMechanism | 566-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | LTCMechanism | 566-2 | LTC Counter Readings | LTC Operations Since Last Insp | 810 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | LTCMechanism | 566-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | LTCMechanism | 566-2 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | LTCMechanism | 566-2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | LTCMechanism | 566-2 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | LTCMechanism | 566-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | LTCMechanism | 566-2 | LTC Counter Readings | LTC As Left Counter | 177940 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | LTCMechanism | 566-2 | LTC Counter Readings | LTC As Found Counter | 177928 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | LTCMechanism | 566-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | LTCMechanism | 566-2 | LTC Counter Readings | General Comments | | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | LTCMechanism | 566-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | M0100 | LTCMechanism | 566-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | FE000260 | Fence | 665-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | FE000260 | Fence | 665-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | FE000260 | Fence | 665-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | FE000260 | Fence | 665-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | FE000260 | Fence | 665-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | FE000260 | Fence | 665-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | FE000260 | Fence | 665-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | FE000260 | Fence | 665-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Readings | Oil Temp Max | 53 | °C |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Readings | Oil Temp Present | 53 | °C |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | FE000260 | Fence | 665-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | FE000260 | Fence | 665-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | FE000260 | Fence | 665-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | FE000260 | Fence | 665-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Readings | General Comments | | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 9993.60 | kw |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | S0074 | NonLTC | 411-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | ST000270 | Structure | 665-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | ST000270 | Structure | 665-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | ST000270 | Structure | 665-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | ST000270 | Structure | 665-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | ST000270 | Structure | 665-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | ST000270 | Structure | 665-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | ST000270 | Structure | 665-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | ST000270 | Structure | 665-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | ST000270 | Structure | 665-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | ST000270 | Structure | 665-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | ST000270 | Structure | 665-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | ST000270 | Structure | 665-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | ST000270 | Structure | 665-Structure | Structure Patrol Inspection | General Comments | | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | ST000270 | Structure | 665-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | ST000270 | Structure | 665-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | ST000270 | Structure | 665-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | ST000270 | Structure | 665-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | ST000270 | Structure | 665-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | ST000270 | Structure | 665-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | ST000270 | Structure | 665-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | ST000270 | Structure | 665-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | ST000270 | Structure | 665-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | YD000262 | Yard | 665-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | YD000262 | Yard | 665-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | YD000262 | Yard | 665-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | n | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | YD000262 | Yard | 665-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BCH001217 | Charger | 743-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BCH001217 | Charger | 743-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BCH001217 | Charger | 743-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BCH001217 | Charger | 743-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.8 | amps |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BCH001217 | Charger | 743-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BCH001217 | Charger | 743-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BCH001217 | Charger | 743-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Readings | Amps B Ø | 17.0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Readings | Amps C Ø | 14.0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BCH000851 | Charger | 100-Battery Charger 2 | Battery Charger Patrol Insp | General Comments | | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BCH000851 | Charger | 100-Battery Charger 2 | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BCH000851 | Charger | 100-Battery Charger 2 | Battery Charger Patrol Insp | As Left Float Voltage | 55.9 | VDC |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | BCH000851 | Charger | 100-Battery Charger 2 | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .700 | millivolts |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Readings | Fault Operations Ground | 0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | ST000273 | Structure | 410-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | ST000273 | Structure | 410-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | ST000273 | Structure | 410-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | ST000273 | Structure | 410-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | ST000273 | Structure | 410-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | ST000273 | Structure | 410-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | ST000273 | Structure | 410-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | ST000273 | Structure | 410-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | ST000273 | Structure | 410-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | ST000273 | Structure | 410-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | ST000273 | Structure | 410-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | ST000273 | Structure | 410-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | ST000273 | Structure | 410-Structure | Structure Patrol Inspection | General Comments | | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | ST000273 | Structure | 410-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | ST000273 | Structure | 410-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | ST000273 | Structure | 410-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | ST000273 | Structure | 410-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | ST000273 | Structure | 410-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Readings | Follow-up Action Required? | n | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Readings | 9 Month Operations | 6 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Readings | Operations Counter AL | 209 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Readings | Operations This Read Vac | 0 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Readings | Switching Operations | 0 | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 14:19 | Distribution | Aisin Quarterly Inspection | BK001334 | BreakerVacuum | 411-4619 | VCB Readings | Unknown Operations | 0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Readings | 9 Month Operations | 3 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Readings | Winding Temp Present | 28 | °C |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Readings | Winding Temp Max | 34 | °C |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .3954 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Readings | Oil Temp Present | 31 | °C |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Readings | Oil Temp Max | 36 | °C |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 948.96 | kw |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Readings | General Comments | ok | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Patrol Inspection | General Comments | ok | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | TX000253 | NonLTC | 468-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Readings | Amps A Ø | 12.0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Readings | LTC Totalizer Reading | 5347.20 | kw |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Readings | General Comments | | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | ST000273 | Structure | 410-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | ST000273 | Structure | 410-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | ST000273 | Structure | 410-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | ST000273 | Structure | 410-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | YD000266 | Yard | 410-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | YD000266 | Yard | 410-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | YD000266 | Yard | 410-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | n | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | YD000266 | Yard | 410-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | YD000266 | Yard | 410-Yard | Yard Patrol Inspection | General Comments | SPR has been disabled | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | YD000266 | Yard | 410-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | YD000266 | Yard | 410-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | YD000266 | Yard | 410-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | YD000266 | Yard | 410-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | YD000266 | Yard | 410-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | YD000266 | Yard | 410-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | YD000266 | Yard | 410-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | YD000266 | Yard | 410-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Readings | Amps A Ø | 134.0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Readings | General Comments | 1 trip check | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Patrol Inspection | General Comments | ok | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Readings | Maintenance Operations | 1 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Readings | Operations Counter AF | 197 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Readings | Operations Counter AL | 197 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Readings | Operations This Read Vac | 1 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Readings | Switching Operations | 0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001631 | BreakerVacuum | 643-0695 | VCB Readings | Unknown Operations | 0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Readings | 9 Month Operations | 1 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Readings | Amps A Ø | 40.0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Readings | Amps B Ø | 29.0 | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | LTCC000699 | LTCControl | 361-1 | LTC Control Insp | All Connections OK? | y | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | LTCC000699 | LTCControl | 361-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | LTCC000699 | LTCControl | 361-1 | LTC Control Insp | General Comments | | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | LTCC000699 | LTCControl | 361-1 | LTC Control Insp | LTC Operation Checked? | n | |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | LTCC000699 | LTCControl | 361-1 | LTC Control Insp | LTC Output Voltage Level | 124.9 | VAC |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | LTCC000699 | LTCControl | 361-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | LTCC000699 | LTCControl | 361-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/2/2023 7:06 | Distribution | Hamblin Quarterly Inspection | LTCC000699 | LTCControl | 361-1 | LTC Control Insp | VRR Time Delay | 45 | Seconds |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Readings | Amps C Ø | 38.0 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | BK001632 | BreakerVacuum | 643-0696 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Readings | Amps B Ø | 128.0 | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Readings | Amps C Ø | 132.0 | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | LTCC000750 | LTCControl | 665-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | LTCC000750 | LTCControl | 665-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | LTCC000750 | LTCControl | 665-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | LTCC000750 | LTCControl | 665-1 | LTC Control Insp | LTC Output Voltage Level | 123.6 | VAC |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | LTCC000750 | LTCControl | 665-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | LTCC000750 | LTCControl | 665-1 | LTC Control Insp | General Comments | | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | LTCC000750 | LTCControl | 665-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/1/2023 10:31 | Distribution | Powderly Quarterly Inspection | LTCC000750 | LTCControl | 665-1 | LTC Control Insp | All Connections OK? | y | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 11:41 | Distribution | Greenville North Quarterly Inspection | K0033 | BreakerVacuum | 410-1328 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Readings | Totalizer Meter Reading | .5570 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | WithLTC | 819-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | YD000239 | Yard | 646-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | YD000239 | Yard | 646-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Readings | Amps C Ø | 140.0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Readings | Amps B Ø | 150.0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Readings | Amps A Ø | 135.0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Readings | 9 Month Operations | 0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Readings | Unknown Operations | 0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | YD000239 | Yard | 646-Yard | Yard Patrol Inspection | Ambient Temp | 82 | °F |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | FE000240 | Fence | 646-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | FE000240 | Fence | 646-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | FE000240 | Fence | 646-Fence | Fence Patrol Inspection | General Comments | Some strands are rusted heavily | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | FE000240 | Fence | 646-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | FE000240 | Fence | 646-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | FE000240 | Fence | 646-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | FE000240 | Fence | 646-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | FE000240 | Fence | 646-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Readings | Switching Operations | 0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Readings | Operations This Read Vac | 4 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Readings | Operations Counter AL | 260 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Readings | Operations Counter AF | 260 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Readings | Maintenance Operations | 4 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Readings | General Comments | | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Patrol Inspection | General Comments | | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Readings | Follow-up Action Required? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | FE000240 | Fence | 646-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | FE000240 | Fence | 646-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | FE000240 | Fence | 646-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000010 | Regulator | 819-2 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000010 | Regulator | 819-2 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000010 | Regulator | 819-2 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000010 | Regulator | 819-2 B | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000010 | Regulator | 819-2 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000010 | Regulator | 819-2 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Readings | Unknown Operations | 0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Readings | Switching Operations | 0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Readings | Operations This Read Vac | 0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Readings | Operations Counter AL | 179 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Readings | Operations Counter AF | 179 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Readings | Maintenance Operations | 0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Readings | General Comments | | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Patrol Inspection | General Comments | | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Readings | Follow-up Action Required? | n | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Readings | Fault Operations Ground | 0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | K0199 | BreakerVacuum | 819-0806 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | YD000239 | Yard | 646-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | YD000239 | Yard | 646-Yard | Yard Patrol Inspection | Vegetation | None | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | YD000239 | Yard | 646-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | YD000239 | Yard | 646-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | YD000239 | Yard | 646-Yard | Yard Patrol Inspection | General Comments | ok | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | YD000239 | Yard | 646-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | YD000239 | Yard | 646-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | YD000239 | Yard | 646-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | YD000239 | Yard | 646-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | YD000239 | Yard | 646-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | YD000239 | Yard | 646-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | YD000239 | Yard | 646-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1206 | Regulator | 142-5 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1206 | Regulator | 142-5 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1206 | Regulator | 142-5 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1206 | Regulator | 142-5 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1206 | Regulator | 142-5 C | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1206 | Regulator | 142-5 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1206 | Regulator | 142-5 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1206 | Regulator | 142-5 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1206 | Regulator | 142-5 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1206 | Regulator | 142-5 C | Regulator Patrol Inspection | General Comments | ok | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1206 | Regulator | 142-5 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1206 | Regulator | 142-5 C | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | ST000002 | Structure | 323-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | ST000002 | Structure | 323-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1206 | Regulator | 142-5 C | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1206 | Regulator | 142-5 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1206 | Regulator | 142-5 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1206 | Regulator | 142-5 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1206 | Regulator | 142-5 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1206 | Regulator | 142-5 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Readings | Amps C Ø | 151.0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Readings | Amps B Ø | 140.0 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | ST000002 | Structure | 323-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | ST000002 | Structure | 323-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | ST000002 | Structure | 323-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | ST000002 | Structure | 323-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | FE000240 | Fence | 646-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | FE000240 | Fence | 646-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | FE000240 | Fence | 646-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | FE000240 | Fence | 646-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | FE000240 | Fence | 646-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0026 | NonLTC | 819-2 | NonLTC Transformer Readings | Totalizer Meter Reading | .7890 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0026 | NonLTC | 819-2 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0026 | NonLTC | 819-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0026 | NonLTC | 819-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0026 | NonLTC | 819-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0026 | NonLTC | 819-2 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0026 | NonLTC | 819-2 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0026 | NonLTC | 819-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 55.00 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0026 | NonLTC | 819-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 63.33 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0026 | NonLTC | 819-2 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 7574.40 | kw |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0026 | NonLTC | 819-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0026 | NonLTC | 819-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0026 | NonLTC | 819-2 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0026 | NonLTC | 819-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0026 | NonLTC | 819-2 | NonLTC Transformer Readings | General Comments | | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0026 | NonLTC | 819-2 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0026 | NonLTC | 819-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Readings | Winding Temp Present | 35 | °C |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Readings | Totalizer Meter Reading | .4914 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0026 | NonLTC | 819-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0026 | NonLTC | 819-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0026 | NonLTC | 819-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0026 | NonLTC | 819-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0026 | NonLTC | 819-2 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0026 | NonLTC | 819-2 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0026 | NonLTC | 819-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0026 | NonLTC | 819-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0026 | NonLTC | 819-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Readings | Fault Operations Ground | 0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1206 | Regulator | 142-5 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1231 | Regulator | 817-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1231 | Regulator | 817-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1231 | Regulator | 817-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Readings | Maintenance Operations | 0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BCH001392 | Charger | 468-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BCH001392 | Charger | 468-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BCH001392 | Charger | 468-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.7 | amps |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BCH001392 | Charger | 468-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BCH001392 | Charger | 468-Battery Charger | Battery Charger Patrol Insp | General Comments | ok | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Readings | Operations Counter AF | 170 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Readings | Operations Counter AL | 170 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Readings | Operations This Read Vac | 0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Readings | Switching Operations | 0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Readings | Unknown Operations | 0 | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0662 | Regulator | 646-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0662 | Regulator | 646-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0662 | Regulator | 646-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0662 | Regulator | 646-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0662 | Regulator | 646-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0662 | Regulator | 646-1 B | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0662 | Regulator | 646-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0662 | Regulator | 646-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0662 | Regulator | 646-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0662 | Regulator | 646-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0662 | Regulator | 646-1 B | Regulator Patrol Inspection | General Comments | ok | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0662 | Regulator | 646-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0662 | Regulator | 646-1 B | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0662 | Regulator | 646-1 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0662 | Regulator | 646-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0662 | Regulator | 646-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0662 | Regulator | 646-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0662 | Regulator | 646-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 217261 | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0662 | Regulator | 646-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0662 | Regulator | 646-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0662 | Regulator | 646-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | CH000520 | ControlHouse | 566-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | CH000520 | ControlHouse | 566-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | CH000514 | ControlHouse | 142 Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | CH000514 | ControlHouse | 142 Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | CH000514 | ControlHouse | 142 Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | CH000514 | ControlHouse | 142 Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | CH000514 | ControlHouse | 142 Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | CH000514 | ControlHouse | 142 Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | CH000514 | ControlHouse | 142 Control House | Control House Patrol Inspection | Evidence of Insects | Yes_needs_sprayed | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | CH000514 | ControlHouse | 142 Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | CH000514 | ControlHouse | 142 Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | CH000514 | ControlHouse | 142 Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Readings | Fault Operations Ground | 0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Readings | Follow-up Action Required? | n | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Patrol Inspection | General Comments | | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Readings | General Comments | | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | CH000514 | ControlHouse | 142 Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | CH000514 | ControlHouse | 142 Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | CH000514 | ControlHouse | 142 Control House | Control House Patrol Inspection | General Comments | ok | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | CH000514 | ControlHouse | 142 Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | CH000514 | ControlHouse | 142 Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | CH000514 | ControlHouse | 142 Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BAT001442 | Battery | 468-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BAT001442 | Battery | 468-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 69 | °F |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BAT001442 | Battery | 468-Battery Bank | Battery Patrol Inspection | Battery Bank Amps | 2.6 | AMPS |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BAT001442 | Battery | 468-Battery Bank | Battery Patrol Inspection | Battery Bank Volts | 53.5 | VDC |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BAT001442 | Battery | 468-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BAT001442 | Battery | 468-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BAT001442 | Battery | 468-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BAT001442 | Battery | 468-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BAT001442 | Battery | 468-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BAT001442 | Battery | 468-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BAT001442 | Battery | 468-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BAT001442 | Battery | 468-Battery Bank | Battery Patrol Inspection | General Comments | ok | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BAT001442 | Battery | 468-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.1 | VDC |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BAT001442 | Battery | 468-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 25.9 | VDC |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BAT001442 | Battery | 468-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | BAT001442 | Battery | 468-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1231 | Regulator | 817-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1231 | Regulator | 817-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1231 | Regulator | 817-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 75533 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000011 | Regulator | 819-2 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000011 | Regulator | 819-2 A | Regulator Patrol Inspection | Regulator As Left Counter | 16232 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000011 | Regulator | 819-2 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000011 | Regulator | 819-2 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | CS000007 | CircuitSwitcher | 819-2 Trans-Rupter | Circuit Switcher Patrol Inspection | SF6 Indicator Zone | OK | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | CS000007 | CircuitSwitcher | 819-2 Trans-Rupter | Circuit Switcher Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | CS000007 | CircuitSwitcher | 819-2 Trans-Rupter | Circuit Switcher Patrol Inspection | General Comments | | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | CS000007 | CircuitSwitcher | 819-2 Trans-Rupter | Circuit Switcher Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | CS000007 | CircuitSwitcher | 819-2 Trans-Rupter | Circuit Switcher Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | CS000007 | CircuitSwitcher | 819-2 Trans-Rupter | Circuit Switcher Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | CS000007 | CircuitSwitcher | 819-2 Trans-Rupter | Circuit Switcher Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000011 | Regulator | 819-2 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000011 | Regulator | 819-2 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000011 | Regulator | 819-2 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000011 | Regulator | 819-2 A | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000011 | Regulator | 819-2 A | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000011 | Regulator | 819-2 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000011 | Regulator | 819-2 A | Regulator Patrol Inspection | General Comments | | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000011 | Regulator | 819-2 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | CS000007 | CircuitSwitcher | 819-2 Trans-Rupter | Circuit Switcher Patrol Inspection | Ambient Temperature | 65 | °F |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000011 | Regulator | 819-2 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000011 | Regulator | 819-2 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000011 | Regulator | 819-2 A | Regulator Patrol Inspection | Current Tap Position | 10L | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000011 | Regulator | 819-2 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000011 | Regulator | 819-2 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000011 | Regulator | 819-2 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000011 | Regulator | 819-2 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000011 | Regulator | 819-2 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000010 | Regulator | 819-2 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000010 | Regulator | 819-2 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000010 | Regulator | 819-2 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000010 | Regulator | 819-2 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000010 | Regulator | 819-2 B | Regulator Patrol Inspection | Regulator As Left Counter | 18300 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000010 | Regulator | 819-2 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000010 | Regulator | 819-2 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | CH000520 | ControlHouse | 566-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | CH000520 | ControlHouse | 566-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | CH000520 | ControlHouse | 566-Control House | Control House Patrol Inspection | Station Ground Set On Site? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | CH000520 | ControlHouse | 566-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | CH000520 | ControlHouse | 566-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | CH000520 | ControlHouse | 566-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | CH000520 | ControlHouse | 566-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | CH000520 | ControlHouse | 566-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | CH000520 | ControlHouse | 566-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | CH000520 | ControlHouse | 566-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | CH000520 | ControlHouse | 566-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | CH000520 | ControlHouse | 566-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | CH000520 | ControlHouse | 566-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | CH000520 | ControlHouse | 566-Control House | Control House Patrol Inspection | Door Alarms OK? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | CH000520 | ControlHouse | 566-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | CH000520 | ControlHouse | 566-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | CH000520 | ControlHouse | 566-Control House | Control House Patrol Inspection | Broom on Site? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | CH000520 | ControlHouse | 566-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | CH000520 | ControlHouse | 566-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Readings | Totalizer Meter Reading | .9012 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 800 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Readings | Oil Temp Present | 41 | °C |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 720.96 | kw |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Readings | General Comments | ok | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Patrol Inspection | General Comments | Fans not hooked up | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | B0256 | NonLTC | 142-5 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000011 | Regulator | 819-2 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000011 | Regulator | 819-2 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000011 | Regulator | 819-2 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | LTCC000843 | LTCControl | 100-7 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | LTCC000843 | LTCControl | 100-7 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | LTCC000843 | LTCControl | 100-7 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000009 | Regulator | 819-2 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000009 | Regulator | 819-2 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000009 | Regulator | 819-2 C | Regulator Patrol Inspection | General Comments | | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000009 | Regulator | 819-2 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000009 | Regulator | 819-2 C | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000009 | Regulator | 819-2 C | Regulator Patrol Inspection | Min Tap Position | 15L | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Readings | Amps A Ø | 14.0 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Readings | Amps B Ø | 34.0 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Readings | Amps C Ø | 21.0 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000009 | Regulator | 819-2 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000009 | Regulator | 819-2 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000009 | Regulator | 819-2 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000009 | Regulator | 819-2 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000009 | Regulator | 819-2 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000009 | Regulator | 819-2 C | Regulator Patrol Inspection | Regulator As Left Counter | 16324 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000009 | Regulator | 819-2 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000009 | Regulator | 819-2 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000009 | Regulator | 819-2 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Readings | General Comments | ok | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Patrol Inspection | General Comments | ok | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Readings | Follow-up Action Required? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BCH001348 | Charger | 566-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000009 | Regulator | 819-2 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000010 | Regulator | 819-2 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000010 | Regulator | 819-2 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000197 | Regulator | 468-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000197 | Regulator | 468-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000197 | Regulator | 468-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000009 | Regulator | 819-2 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000206 | Regulator | 643-1 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000206 | Regulator | 643-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000206 | Regulator | 643-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000206 | Regulator | 643-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000206 | Regulator | 643-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000206 | Regulator | 643-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Readings | Amps C Ø | 70.0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Readings | Amps B Ø | 71.0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Readings | Amps A Ø | 78.0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Readings | 9 Month Operations | 0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | LTCC000893 | LTCControl | 566-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | LTCC000893 | LTCControl | 566-1 | LTC Control Insp | General Comments | | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | LTCC000893 | LTCControl | 566-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | LTCC000893 | LTCControl | 566-1 | LTC Control Insp | LTC Output Voltage Level | 123.6 | VAC |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | LTCC000893 | LTCControl | 566-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | LTCC000893 | LTCControl | 566-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | LTCC000893 | LTCControl | 566-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | ST000002 | Structure | 323-Structure | Structure Patrol Inspection | General Comments | | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | ST000002 | Structure | 323-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | ST000002 | Structure | 323-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | ST000002 | Structure | 323-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | ST000002 | Structure | 323-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | ST000002 | Structure | 323-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | ST000002 | Structure | 323-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | LTCC000843 | LTCControl | 100-7 | LTC Control Insp | All Connections OK? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | LTCC000843 | LTCControl | 100-7 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | LTCC000843 | LTCControl | 100-7 | LTC Control Insp | General Comments | | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | LTCC000843 | LTCControl | 100-7 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | LTCC000843 | LTCControl | 100-7 | LTC Control Insp | LTC Output Voltage Level | 124.5 | VAC |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | LTCC000843 | LTCControl | 100-7 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | ST000002 | Structure | 323-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | ST000002 | Structure | 323-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Readings | Amps C Ø | 55.0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Readings | Amps B Ø | 55.0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Readings | Amps A Ø | 55.0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000196 | Regulator | 468-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000196 | Regulator | 468-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000196 | Regulator | 468-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000196 | Regulator | 468-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000196 | Regulator | 468-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 8023 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Readings | 9 Month Operations | 0 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000196 | Regulator | 468-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000196 | Regulator | 468-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000196 | Regulator | 468-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000196 | Regulator | 468-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000196 | Regulator | 468-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000196 | Regulator | 468-1 A | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000196 | Regulator | 468-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000196 | Regulator | 468-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000196 | Regulator | 468-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000196 | Regulator | 468-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000196 | Regulator | 468-1 A | Regulator Patrol Inspection | General Comments | ok | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000196 | Regulator | 468-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000196 | Regulator | 468-1 A | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000196 | Regulator | 468-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000196 | Regulator | 468-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000196 | Regulator | 468-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000196 | Regulator | 468-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000196 | Regulator | 468-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000196 | Regulator | 468-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Readings | Fault Operations Ground | 0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BCH001348 | Charger | 566-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.1 | amps |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BCH001348 | Charger | 566-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BCH001348 | Charger | 566-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BCH001348 | Charger | 566-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BCH001348 | Charger | 566-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | ST000332 | Structure | 468-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | ST000332 | Structure | 468-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | ST000332 | Structure | 468-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | ST000332 | Structure | 468-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | ST000332 | Structure | 468-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Readings | Unknown Operations | 0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Readings | Switching Operations | 0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Readings | Operations This Read Vac | 0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Readings | Operations Counter AL | 222 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Readings | Operations Counter AF | 222 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Readings | Maintenance Operations | 0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Readings | General Comments | | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Patrol Inspection | General Comments | | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Readings | Follow-up Action Required? | n | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Readings | Fault Operations Ground | 0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000888 | BreakerVacuum | 819-0795 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000010 | Regulator | 819-2 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000010 | Regulator | 819-2 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000010 | Regulator | 819-2 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000010 | Regulator | 819-2 B | Regulator Patrol Inspection | Current Tap Position | 10L | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000010 | Regulator | 819-2 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000010 | Regulator | 819-2 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000010 | Regulator | 819-2 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000010 | Regulator | 819-2 B | Regulator Patrol Inspection | General Comments | | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | ST000332 | Structure | 468-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | ST000332 | Structure | 468-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | ST000332 | Structure | 468-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | ST000332 | Structure | 468-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | ST000332 | Structure | 468-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Readings | Unknown Operations | 0 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0663 | Regulator | 646-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0663 | Regulator | 646-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0663 | Regulator | 646-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Readings | Operations This Read Vac | 1 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Readings | Operations Counter AL | 201 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Readings | Operations Counter AF | 201 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Readings | Maintenance Operations | 1 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0663 | Regulator | 646-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0663 | Regulator | 646-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0663 | Regulator | 646-1 C | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0663 | Regulator | 646-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0663 | Regulator | 646-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0663 | Regulator | 646-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0663 | Regulator | 646-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0663 | Regulator | 646-1 C | Regulator Patrol Inspection | General Comments | ok | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0663 | Regulator | 646-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0663 | Regulator | 646-1 C | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0663 | Regulator | 646-1 C | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0663 | Regulator | 646-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0663 | Regulator | 646-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0663 | Regulator | 646-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0663 | Regulator | 646-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 162842 | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0663 | Regulator | 646-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0663 | Regulator | 646-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | R0663 | Regulator | 646-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BCH001348 | Charger | 566-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 2.900 | millivolts |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | ST000002 | Structure | 323-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Readings | Amps A Ø | 127.0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | ST000002 | Structure | 323-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | ST000002 | Structure | 323-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | ST000002 | Structure | 323-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | KB0114 | BreakerVacuum | 566-0285 | VCB Readings | 9 Month Operations | 4 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | BK000902 | BreakerVacuum | 142-1666 | VCB Readings | 9 Month Operations | 3 | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1206 | Regulator | 142-5 C | Regulator Patrol Inspection | Regulator As Left Counter | 95071 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Readings | LTC Totalizer Reading | 8845.20 | kw |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Readings | General Comments | | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | B0392 | WithLTC | 743-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | ST000332 | Structure | 468-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | ST000332 | Structure | 468-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | ST000332 | Structure | 468-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | ST000332 | Structure | 468-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | ST000332 | Structure | 468-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | ST000332 | Structure | 468-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | ST000332 | Structure | 468-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | ST000332 | Structure | 468-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | ST000332 | Structure | 468-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | n | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | ST000332 | Structure | 468-Structure | Structure Patrol Inspection | General Comments | Station does not utilize xfmr fuses | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000009 | Regulator | 819-2 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000009 | Regulator | 819-2 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000009 | Regulator | 819-2 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000009 | Regulator | 819-2 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000009 | Regulator | 819-2 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | RG000009 | Regulator | 819-2 C | Regulator Patrol Inspection | Current Tap Position | 12L | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000197 | Regulator | 468-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000197 | Regulator | 468-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000197 | Regulator | 468-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000197 | Regulator | 468-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000197 | Regulator | 468-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 8192 | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000197 | Regulator | 468-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000197 | Regulator | 468-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000197 | Regulator | 468-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000197 | Regulator | 468-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000197 | Regulator | 468-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000197 | Regulator | 468-1 C | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000197 | Regulator | 468-1 C | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000197 | Regulator | 468-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000197 | Regulator | 468-1 C | Regulator Patrol Inspection | General Comments | ok | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000197 | Regulator | 468-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000197 | Regulator | 468-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000197 | Regulator | 468-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000197 | Regulator | 468-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000197 | Regulator | 468-1 C | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000206 | Regulator | 643-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000206 | Regulator | 643-1 C | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000206 | Regulator | 643-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000206 | Regulator | 643-1 C | Regulator Patrol Inspection | General Comments | ok | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000206 | Regulator | 643-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000206 | Regulator | 643-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000206 | Regulator | 643-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000206 | Regulator | 643-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000197 | Regulator | 468-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 9:04 | Distribution | Beech Creek Quarterly Inspection | RG000197 | Regulator | 468-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BCH001348 | Charger | 566-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | ST000002 | Structure | 323-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | LTCC000892 | LTCControl | 566-2 | LTC Control Insp | All Connections OK? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Readings | Unknown Operations | 0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Readings | Switching Operations | 0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Readings | Operations This Read Vac | 0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Readings | Operations Counter AL | 194 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Readings | Operations Counter AF | 194 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Readings | Maintenance Operations | 0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Readings | General Comments | | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000206 | Regulator | 643-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000206 | Regulator | 643-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | LTCC000892 | LTCControl | 566-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | LTCC000892 | LTCControl | 566-2 | LTC Control Insp | General Comments | | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | LTCC000892 | LTCControl | 566-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | LTCC000892 | LTCControl | 566-2 | LTC Control Insp | LTC Output Voltage Level | 128.4 | VAC |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | LTCC000892 | LTCControl | 566-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | LTCC000892 | LTCControl | 566-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | LTCC000892 | LTCControl | 566-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | LTCC000893 | LTCControl | 566-1 | LTC Control Insp | All Connections OK? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000206 | Regulator | 643-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000206 | Regulator | 643-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000206 | Regulator | 643-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 4464 | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000206 | Regulator | 643-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000206 | Regulator | 643-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1206 | Regulator | 142-5 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1206 | Regulator | 142-5 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 13:51 | Distribution | Bevier Quarterly Inspection | R1206 | Regulator | 142-5 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000206 | Regulator | 643-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000206 | Regulator | 643-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 10:20 | Distribution | Beechmont Quarterly Inspection | RG000206 | Regulator | 643-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Patrol Inspection | General Comments | | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Readings | Follow-up Action Required? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Readings | Fault Operations Ground | 0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BK000890 | BreakerVacuum | 566-0287 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BAT000970 | Battery | 566-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BAT000970 | Battery | 566-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BAT000970 | Battery | 566-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BAT000970 | Battery | 566-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BAT000970 | Battery | 566-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BAT000970 | Battery | 566-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BAT000970 | Battery | 566-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1231 | Regulator | 817-1 B | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BAT000970 | Battery | 566-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BAT000970 | Battery | 566-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BAT000970 | Battery | 566-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BAT000970 | Battery | 566-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.0 | VDC |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BAT000970 | Battery | 566-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BAT000970 | Battery | 566-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BAT000970 | Battery | 566-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Readings | Unknown Operations | 0 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | LTCMechanism | 343-1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | LTCMechanism | 343-1 | LTC Counter Readings | LTC Operations Since Last Insp | 509 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | LTCMechanism | 343-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | LTCMechanism | 343-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | LTCMechanism | 343-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Patrol Inspection | General Comments | | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Readings | General Comments | | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Readings | LTC Totalizer Reading | 0.00 | kw |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1231 | Regulator | 817-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Readings | Oil Temp Max | 56 | °C |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Readings | Oil Temp Present | 53 | °C |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0178 | NonLTC | 646-1 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0178 | NonLTC | 646-1 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0178 | NonLTC | 646-1 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0178 | NonLTC | 646-1 C | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1231 | Regulator | 817-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1231 | Regulator | 817-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Readings | Operations Counter AF | 202 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Readings | Operations Counter AL | 202 | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0178 | NonLTC | 646-1 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0178 | NonLTC | 646-1 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0178 | NonLTC | 646-1 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | RC000434 | RecloserElectronic | 817-1674 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Readings | Operations This Read Vac | 0 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | RC000434 | RecloserElectronic | 817-1674 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | LTCMechanism | 343-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | LTCMechanism | 343-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | LTCMechanism | 343-1 | LTC Counter Readings | General Comments | | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | LTCMechanism | 343-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | LTCMechanism | 343-1 | LTC Counter Readings | LTC As Found Counter | 90460 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | LTCMechanism | 343-1 | LTC Counter Readings | LTC As Left Counter | 90463 | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | LTCMechanism | 343-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | LTCMechanism | 343-1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 3/2/2023 8:04 | Distribution | Poor Valley Quarterly Inspection | O0234 | LTCMechanism | 343-1 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | LTCMechanism | 819-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | LTCMechanism | 819-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | LTCMechanism | 819-1 | LTC Counter Readings | LTC As Left Counter | 16378 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | LTCMechanism | 819-1 | LTC Counter Readings | LTC As Found Counter | 16378 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | LTCMechanism | 819-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | LTCMechanism | 819-1 | LTC Counter Readings | General Comments | | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | LTCMechanism | 819-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | LTCMechanism | 819-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1231 | Regulator | 817-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1231 | Regulator | 817-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1231 | Regulator | 817-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1231 | Regulator | 817-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1231 | Regulator | 817-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Readings | Switching Operations | 0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Readings | Unknown Operations | 0 | |
| 3/1/2023 10:28 | Distribution | Hopewell Quarterly Inspection | BAT000970 | Battery | 566-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Readings | Totalizer Meter Multiplier | 0 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Readings | Amps A Ø | 265.0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Readings | Amps B Ø | 270.0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Readings | Amps C Ø | 265.0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Readings | Maintenance Operations | 0 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Readings | Fault Operations Ground | 0 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Readings | General Comments | | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Patrol Inspection | General Comments | | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Readings | Follow-up Action Required? | n | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Readings | Switching Operations | 2 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Readings | Operations This Read Vac | 2 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Readings | Operations Counter AL | 239 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Readings | Operations Counter AF | 237 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Readings | Maintenance Operations | 0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Readings | Amps C Ø | 50.0 | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | RC000434 | RecloserElectronic | 817-1674 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | RC000434 | RecloserElectronic | 817-1674 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Readings | General Comments | | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | RC000434 | RecloserElectronic | 817-1674 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | RC000434 | RecloserElectronic | 817-1674 | Recloser Electronic Patrol Inspection | Amps C Ø | 50.0 | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | RC000434 | RecloserElectronic | 817-1674 | Recloser Electronic Patrol Inspection | Amps B Ø | 80.0 | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | RC000434 | RecloserElectronic | 817-1674 | Recloser Electronic Patrol Inspection | Amps A Ø | 55.0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Readings | Fault Operations C Ø | 0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Readings | Fault Operations Ground | 0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Readings | Follow-up Action Required? | n | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Patrol Inspection | General Comments | | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 3/1/2023 11:26 | Distribution | Green River Steel Quarterly Inspection | W0333 | WithLTC | 100-7 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | LTCMechanism | 819-1 | LTC Counter Readings | LTC Operations Since Last Insp | 133 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | LTCMechanism | 819-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | LTCMechanism | 819-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | FE000300 | Fence | 819-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Readings | Amps B Ø | 50.0 | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1231 | Regulator | 817-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1231 | Regulator | 817-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1231 | Regulator | 817-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1231 | Regulator | 817-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Readings | Amps A Ø | 65.0 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | FE000300 | Fence | 819-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0178 | NonLTC | 646-1 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | FE000300 | Fence | 819-Fence | Fence Patrol Inspection | General Comments | | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | FE000300 | Fence | 819-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Patrol Inspection | Bushing Condition | Good | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Readings | Amps C Ø | 100.0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Readings | Amps B Ø | 90.0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Readings | Amps A Ø | 105.0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | BK000249 | BreakerVacuum | 743-0801 | VCB Readings | 9 Month Operations | 5 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | FE000300 | Fence | 819-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | FE000300 | Fence | 819-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | FE000300 | Fence | 819-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | FE000300 | Fence | 819-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | FE000300 | Fence | 819-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | FE000300 | Fence | 819-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | FE000300 | Fence | 819-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | FE000300 | Fence | 819-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | LTCMechanism | 819-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | FE000867 | Fence | 743-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | LTCMechanism | 819-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Readings | 9 Month Operations | 3 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | BK000292 | BreakerVacuum | 819-0805 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | FE000300 | Fence | 819-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | FE000867 | Fence | 743-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | FE000867 | Fence | 743-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | FE000867 | Fence | 743-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | FE000867 | Fence | 743-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Readings | 9 Month Operations | 0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | KB0083 | BreakerVacuum | 743-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | FE000867 | Fence | 743-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | FE000867 | Fence | 743-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | FE000867 | Fence | 743-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | FE000867 | Fence | 743-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | FE000867 | Fence | 743-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | FE000867 | Fence | 743-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | FE000867 | Fence | 743-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | FE000867 | Fence | 743-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | FE000867 | Fence | 743-Fence | Fence Patrol Inspection | General Comments | | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | FE000867 | Fence | 743-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/1/2023 7:32 | Distribution | Detroit Harvester Quarterly Inspection | FE000867 | Fence | 743-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | FE000878 | Fence | 323-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | FE000878 | Fence | 323-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0178 | NonLTC | 646-1 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0178 | NonLTC | 646-1 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0178 | NonLTC | 646-1 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0178 | NonLTC | 646-1 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0178 | NonLTC | 646-1 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0178 | NonLTC | 646-1 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1231 | Regulator | 817-1 B | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | FE000878 | Fence | 323-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | FE000878 | Fence | 323-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | FE000878 | Fence | 323-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | FE000878 | Fence | 323-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | FE000878 | Fence | 323-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | FE000878 | Fence | 323-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | FE000878 | Fence | 323-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0178 | NonLTC | 646-1 C | NonLTC Transformer Patrol Inspection | General Comments | ok | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0178 | NonLTC | 646-1 C | NonLTC Transformer Readings | General Comments | ok | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0178 | NonLTC | 646-1 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0178 | NonLTC | 646-1 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1231 | Regulator | 817-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1231 | Regulator | 817-1 B | Regulator Patrol Inspection | General Comments | ok | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | R1231 | Regulator | 817-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0178 | NonLTC | 646-1 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | FE000878 | Fence | 323-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0178 | NonLTC | 646-1 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0178 | NonLTC | 646-1 C | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | RC000434 | RecloserElectronic | 817-1674 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | RC000434 | RecloserElectronic | 817-1674 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | FE000878 | Fence | 323-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | FE000878 | Fence | 323-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | FE000878 | Fence | 323-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | FE000878 | Fence | 323-Fence | Fence Patrol Inspection | General Comments | | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | FE000878 | Fence | 323-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | RC000434 | RecloserElectronic | 817-1674 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | RC000434 | RecloserElectronic | 817-1674 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | RC000434 | RecloserElectronic | 817-1674 | Recloser Electronic Patrol Inspection | Operations Counter | 163 | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | FE000300 | Fence | 819-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | RC000434 | RecloserElectronic | 817-1674 | Recloser Electronic Patrol Inspection | General Comments | ok | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | RC000434 | RecloserElectronic | 817-1674 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 3/1/2023 12:38 | Distribution | Reed Minerals Quarterly Inspection | W0178 | NonLTC | 646-1 C | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | RC000434 | RecloserElectronic | 817-1674 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | RC000434 | RecloserElectronic | 817-1674 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | RC000434 | RecloserElectronic | 817-1674 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | LTCMechanism | 819-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | S0008 | LTCMechanism | 819-1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 3/2/2023 8:04 | Distribution | Pennington Gap Quarterly Inspection | FE000878 | Fence | 323-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | RC000434 | RecloserElectronic | 817-1674 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 3/1/2023 11:42 | Distribution | Drakesboro Quarterly Inspection | RC000434 | RecloserElectronic | 817-1674 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | FE000300 | Fence | 819-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 3/1/2023 11:24 | Distribution | Paris 12kV Quarterly Inspection | FE000300 | Fence | 819-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | LTCMechanism | LG-TRANS 2 | LTC Counter Readings | General Comments | this is the correct VC | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | LTCMechanism | LG-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.2350 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Readings | Winding Temp Max | 80 | °C |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 10.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | FE000345 | Fence | 723-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | FE000345 | Fence | 723-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Readings | Unknown Operations | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Patrol Inspection | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Readings | Follow-up Action Required? | n | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Readings | Fault Operations Ground | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Readings | 9 Month Operations | 1 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Readings | Oil Temp Max | 75 | °C |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1100 | psi |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Readings | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Readings | LTC Totalizer Reading | 17784.00 | kw |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Readings | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Readings | Maintenance Operations | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Readings | Operations Counter AF | 153 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0554 | BreakerAirMagnetic | LG-4 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0554 | BreakerAirMagnetic | LG-4 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0554 | BreakerAirMagnetic | LG-4 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0554 | BreakerAirMagnetic | LG-4 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Readings | Operations Counter AL | 154 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0554 | BreakerAirMagnetic | LG-4 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Readings | Operations This Read Vac | 13 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Readings | Switching Operations | 13 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Readings | Amps C Ø | 120.0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Readings | Amps B Ø | 120.0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Readings | Amps A Ø | 120.0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Readings | 9 Month Operations | 8 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0554 | BreakerAirMagnetic | LG-4 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0554 | BreakerAirMagnetic | LG-4 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0554 | BreakerAirMagnetic | LG-4 | AMCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0554 | BreakerAirMagnetic | LG-4 | AMCB Readings | General Comments | | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0554 | BreakerAirMagnetic | LG-4 | AMCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0554 | BreakerAirMagnetic | LG-4 | AMCB Readings | Operations Counter AF | 418 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0233 | BreakerAirMagnetic | CW-1224 | AMCB Readings | 9 Month Ops New | 2 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0233 | BreakerAirMagnetic | CW-1224 | AMCB Readings | 9 Months Operations | 2 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Readings | 9 Month Operations | 2 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0233 | BreakerAirMagnetic | CW-1224 | AMCB Readings | Accumulated Fault Duty A Ph AM | 6.02 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0233 | BreakerAirMagnetic | CW-1224 | AMCB Readings | Accumulated Fault Duty B Ph AM | 6.02 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0233 | BreakerAirMagnetic | CW-1224 | AMCB Readings | Accumulated Fault Duty C Ph AM | 3.61 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0233 | BreakerAirMagnetic | CW-1224 | AMCB Readings | Amps A Ø | 250.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0233 | BreakerAirMagnetic | CW-1224 | AMCB Readings | Amps B Ø | 250.0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0554 | BreakerAirMagnetic | LG-4 | AMCB Readings | Operations Counter AL | 418 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0233 | BreakerAirMagnetic | CW-1224 | AMCB Readings | Amps C Ø | 250.0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | LTCMechanism | 723-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | LTCMechanism | 723-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0233 | BreakerAirMagnetic | CW-1224 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0233 | BreakerAirMagnetic | CW-1224 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Readings | Winding Temp Max | 60 | °C |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Readings | Totalizer Meter Reading | .2800 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | LTCMechanism | LG-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 384460 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | LTCMechanism | LG-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 384460 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | LTCMechanism | LG-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 10L | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | LTCMechanism | LG-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | LTCMechanism | LG-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | FE000345 | Fence | 723-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | FE000345 | Fence | 723-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | FE000345 | Fence | 723-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | FE000345 | Fence | 723-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | FE000345 | Fence | 723-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | FE000345 | Fence | 723-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | FE000345 | Fence | 723-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | FE000345 | Fence | 723-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | FE000345 | Fence | 723-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Readings | Unknown Operations | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Readings | Switching Operations | 4 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Readings | Operations This Read Vac | 4 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Readings | Operations Counter AL | 99963 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Readings | Operations Counter AF | 99959 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Readings | Maintenance Operations | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | LTCMechanism | LG-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 367 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | LTCMechanism | LG-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Readings | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Patrol Inspection | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Readings | Follow-up Action Required? | n | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Readings | Fault Operations Ground | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0552 | BreakerAirMagnetic | LG-2 | AMCB Readings | Amps B Ø | 75.0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0552 | BreakerAirMagnetic | LG-2 | AMCB Readings | Amps A Ø | 100.0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0552 | BreakerAirMagnetic | LG-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 3.2 | % |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0552 | BreakerAirMagnetic | LG-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 1.07 | % |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0552 | BreakerAirMagnetic | LG-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 1.07 | % |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0552 | BreakerAirMagnetic | LG-2 | AMCB Readings | 9 Months Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0552 | BreakerAirMagnetic | LG-2 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0226 | BreakerVacuum | 069-2329 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Patrol Inspection | General Comments | | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Readings | General Comments | | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Readings | Maintenance Operations | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Readings | Operations Counter AF | 318 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Readings | Operations Counter AL | 320 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Readings | Operations This Read Vac | 2 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Readings | Switching Operations | 2 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0552 | BreakerAirMagnetic | LG-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0552 | BreakerAirMagnetic | LG-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0552 | BreakerAirMagnetic | LG-2 | AMCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0552 | BreakerAirMagnetic | LG-2 | AMCB Readings | General Comments | | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0552 | BreakerAirMagnetic | LG-2 | AMCB Readings | Unknown Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0552 | BreakerAirMagnetic | LG-2 | AMCB Readings | Switching Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0552 | BreakerAirMagnetic | LG-2 | AMCB Readings | Operations This Read AM | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0552 | BreakerAirMagnetic | LG-2 | AMCB Readings | Operations Counter AL | 413 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0552 | BreakerAirMagnetic | LG-2 | AMCB Readings | Operations Counter AF | 413 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0552 | BreakerAirMagnetic | LG-2 | AMCB Readings | Maintenance Operations | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Readings | 9 Month Operations | 4 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Readings | Amps A Ø | 100.0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Readings | Amps B Ø | 100.0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Readings | Amps C Ø | 100.0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | LTCMechanism | CW-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | LTCMechanism | 723-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | LTCMechanism | 723-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | LTCMechanism | 723-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | LTCMechanism | 723-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | LTCMechanism | 723-1 | LTC Counter Readings | LTC Operations Since Last Insp | 1319 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | LTCMechanism | 723-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 25 | °C |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | LTCMechanism | 723-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 50 | °C |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0552 | BreakerAirMagnetic | LG-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0552 | BreakerAirMagnetic | LG-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Readings | Switching Operations | 3 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0552 | BreakerAirMagnetic | LG-2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0552 | BreakerAirMagnetic | LG-2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | LTCMechanism | 723-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | LTCMechanism | 723-1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | LTCMechanism | 723-1 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | LTCMechanism | 723-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | LTCMechanism | 723-1 | LTC Counter Readings | LTC As Left Counter | 73566 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | LTCMechanism | 723-1 | LTC Counter Readings | LTC As Found Counter | 73566 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | LTCMechanism | 723-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | LTCMechanism | 723-1 | LTC Counter Readings | General Comments | | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | LTCMechanism | 723-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | LTCMechanism | 723-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Readings | Amps B Ø | 180.0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Readings | Amps C Ø | 175.0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Readings | Fault Operations Ground | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Readings | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0554 | BreakerAirMagnetic | LG-4 | AMCB Readings | Accumulated Fault Duty C Ph AM | 1.07 | % |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0554 | BreakerAirMagnetic | LG-4 | AMCB Readings | Accumulated Fault Duty B Ph AM | 3.2 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0235 | BreakerAirMagnetic | CW-1226 | AMCB Readings | Unknown Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0235 | BreakerAirMagnetic | CW-1226 | AMCB Readings | Switching Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0235 | BreakerAirMagnetic | CW-1226 | AMCB Readings | Operations This Read AM | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | LTCMechanism | CW-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 799 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | LTCMechanism | CW-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | LTCMechanism | CW-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 5R | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | LTCMechanism | CW-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | LTCMechanism | CW-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 835 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | LTCMechanism | CW-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0235 | BreakerAirMagnetic | CW-1226 | AMCB Readings | Operations Counter AL | 319 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0235 | BreakerAirMagnetic | CW-1226 | AMCB Readings | Operations Counter AF | 319 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0235 | BreakerAirMagnetic | CW-1226 | AMCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0235 | BreakerAirMagnetic | CW-1226 | AMCB Readings | General Comments | | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Readings | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Patrol Inspection | General Comments | | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Readings | General Comments | | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0554 | BreakerAirMagnetic | LG-4 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0554 | BreakerAirMagnetic | LG-4 | AMCB Readings | 9 Months Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0554 | BreakerAirMagnetic | LG-4 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0235 | BreakerAirMagnetic | CW-1226 | AMCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0235 | BreakerAirMagnetic | CW-1226 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0235 | BreakerAirMagnetic | CW-1226 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0235 | BreakerAirMagnetic | CW-1226 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0235 | BreakerAirMagnetic | CW-1226 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0235 | BreakerAirMagnetic | CW-1226 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0235 | BreakerAirMagnetic | CW-1226 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0235 | BreakerAirMagnetic | CW-1226 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0235 | BreakerAirMagnetic | CW-1226 | AMCB Readings | Amps C Ø | 100.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0235 | BreakerAirMagnetic | CW-1226 | AMCB Readings | Amps B Ø | 100.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0235 | BreakerAirMagnetic | CW-1226 | AMCB Readings | Amps A Ø | 100.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0235 | BreakerAirMagnetic | CW-1226 | AMCB Readings | Accumulated Fault Duty C Ph AM | 1.2 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0235 | BreakerAirMagnetic | CW-1226 | AMCB Readings | Accumulated Fault Duty B Ph AM | 12.05 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0235 | BreakerAirMagnetic | CW-1226 | AMCB Readings | Accumulated Fault Duty A Ph AM | 6.02 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0235 | BreakerAirMagnetic | CW-1226 | AMCB Readings | 9 Months Operations | 3 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0235 | BreakerAirMagnetic | CW-1226 | AMCB Readings | 9 Month Ops New | 3 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | LTCMechanism | CW-TRANS 2 | LTC Counter Readings | General Comments | It appears the Operation Counter on the Tap Changer has been changed.  The operations since last inspection is off. | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | LTCMechanism | CW-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 100799 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Readings | Fault Operations Ground | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Readings | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Patrol Inspection | General Comments | | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Readings | General Comments | | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Readings | Operations This Read Vac | 3 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Readings | Operations Counter AL | 479 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Readings | Maintenance Operations | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Readings | Operations Counter AF | 466 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Readings | Operations Counter AF | 366 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Readings | Operations Counter AL | 370 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Readings | Operations This Read Vac | 4 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Readings | Amps A Ø | 240.0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Readings | Amps B Ø | 240.0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Readings | Amps C Ø | 240.0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Readings | Switching Operations | 4 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0042 | BreakerVacuum | 723-0442 | VCB Readings | Unknown Operations | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0554 | BreakerAirMagnetic | LG-4 | AMCB Readings | Amps C Ø | 150.0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0554 | BreakerAirMagnetic | LG-4 | AMCB Readings | Amps B Ø | 180.0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0554 | BreakerAirMagnetic | LG-4 | AMCB Readings | Amps A Ø | 225.0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | FE000345 | Fence | 723-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | FE000345 | Fence | 723-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | LTCMechanism | 069-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | LTCMechanism | 069-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | LTCMechanism | 069-5 | LTC Counter Readings | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | LTCMechanism | 069-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | LTCMechanism | 069-5 | LTC Counter Readings | LTC As Found Counter | 104484 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | LTCMechanism | 069-5 | LTC Counter Readings | LTC As Left Counter | 104484 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | LTCMechanism | 069-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | LTCMechanism | 069-5 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | LTCMechanism | 069-5 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | LTCMechanism | 069-5 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | LTCMechanism | 069-5 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 2.0 | psi |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | FE000345 | Fence | 723-Fence | Fence Patrol Inspection | General Comments | | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Readings | Winding Temp Present | 50 | °C |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Readings | Winding Temp Max | 80 | °C |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Readings | Totalizer Meter Reading | 1.2500 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | LTCMechanism | 069-5 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | LTCMechanism | 069-5 | LTC Counter Readings | LTC Operations Since Last Insp | 795 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | LTCMechanism | 069-5 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | LTCMechanism | 069-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | LTCMechanism | 069-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | LTCMechanism | 069-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | FE000345 | Fence | 723-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | FE000345 | Fence | 723-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | ST000352 | Structure | 723-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Readings | 9 Month Operations | 4 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0032 | BreakerVacuum | 723-0440 | VCB Readings | Amps A Ø | 155.0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0011 | WithLTC | 723-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Readings | General Comments | | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Readings | Amps C Ø | 0.0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Readings | Amps B Ø | 0.0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Readings | Amps A Ø | 0.0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK000499 | BreakerVacuum | 069-BT6-5 | VCB Readings | 9 Month Operations | 13 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Readings | Operations Counter AF | 304 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Readings | Operations Counter AL | 305 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Readings | Operations This Read Vac | 1 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Readings | Switching Operations | 1 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0013 | BreakerVacuum | 723-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Readings | General Comments | | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0237 | BreakerAirMagnetic | CW-1228 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0237 | BreakerAirMagnetic | CW-1228 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | LTCMechanism | 069-6 | LTC Counter Readings | LTC As Found Counter | 122164 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | LTCMechanism | 069-6 | LTC Counter Readings | LTC As Left Counter | 122164 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0237 | BreakerAirMagnetic | CW-1228 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0237 | BreakerAirMagnetic | CW-1228 | AMCB Readings | Amps C Ø | 200.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0237 | BreakerAirMagnetic | CW-1228 | AMCB Readings | Amps B Ø | 200.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0237 | BreakerAirMagnetic | CW-1228 | AMCB Readings | Amps A Ø | 200.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0237 | BreakerAirMagnetic | CW-1228 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0237 | BreakerAirMagnetic | CW-1228 | AMCB Readings | Accumulated Fault Duty B Ph AM | 2.41 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0237 | BreakerAirMagnetic | CW-1228 | AMCB Readings | Accumulated Fault Duty A Ph AM | 1.2 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0237 | BreakerAirMagnetic | CW-1228 | AMCB Readings | 9 Months Operations | 1 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0237 | BreakerAirMagnetic | CW-1228 | AMCB Readings | 9 Month Ops New | 1 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0552 | BreakerAirMagnetic | LG-2 | AMCB Readings | Amps C Ø | 120.0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0552 | BreakerAirMagnetic | LG-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Readings | 9 Month Operations | 11 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | LTCMechanism | 069-6 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | LTCMechanism | 069-6 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | LTCMechanism | 069-6 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | LTCMechanism | 069-6 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | LTCMechanism | 069-6 | LTC Counter Readings | LTC Operations Since Last Insp | 872 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | LTCMechanism | 069-6 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | LTCMechanism | 069-6 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | LTCMechanism | 069-6 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | ST000352 | Structure | 723-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | ST000352 | Structure | 723-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | ST000352 | Structure | 723-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | ST000352 | Structure | 723-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0237 | BreakerAirMagnetic | CW-1228 | AMCB Readings | Unknown Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0237 | BreakerAirMagnetic | CW-1228 | AMCB Readings | Switching Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0237 | BreakerAirMagnetic | CW-1228 | AMCB Readings | Operations This Read AM | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0237 | BreakerAirMagnetic | CW-1228 | AMCB Readings | Operations Counter AL | 479 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0237 | BreakerAirMagnetic | CW-1228 | AMCB Readings | Operations Counter AF | 479 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BB0415 | BreakerVacuum | 723-0441 | VCB Readings | Unknown Operations | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | ST000352 | Structure | 723-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | ST000352 | Structure | 723-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | ST000352 | Structure | 723-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | ST000352 | Structure | 723-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | ST000352 | Structure | 723-Structure | Structure Patrol Inspection | General Comments | | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | ST000352 | Structure | 723-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | ST000352 | Structure | 723-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | ST000352 | Structure | 723-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | ST000352 | Structure | 723-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | ST000352 | Structure | 723-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | ST000352 | Structure | 723-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | ST000352 | Structure | 723-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | ST000352 | Structure | 723-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | ST000352 | Structure | 723-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | ST000352 | Structure | 723-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | ST000352 | Structure | 723-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0237 | BreakerAirMagnetic | CW-1228 | AMCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0237 | BreakerAirMagnetic | CW-1228 | AMCB Readings | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0237 | BreakerAirMagnetic | CW-1228 | AMCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0237 | BreakerAirMagnetic | CW-1228 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | LTCMechanism | 069-6 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | LTCMechanism | 069-6 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | LTCMechanism | 069-6 | LTC Counter Readings | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | LTCMechanism | 069-6 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0237 | BreakerAirMagnetic | CW-1228 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | ST000352 | Structure | 723-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0237 | BreakerAirMagnetic | CW-1228 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0237 | BreakerAirMagnetic | CW-1228 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Readings | Oil Temp Max | 65 | °C |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 700 | psi |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | WithLTC | 723-2 | LTC Transformer Readings | LTC Totalizer Reading | 18000.00 | kw |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Readings | Switching Operations | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | LTCMechanism | LG-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | LTCMechanism | LG-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 5L | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | LTCMechanism | LG-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BAT001465 | Battery | 723-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BAT001465 | Battery | 723-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BAT001465 | Battery | 723-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BAT001465 | Battery | 723-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | YD000349 | Yard | 723-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | YD000349 | Yard | 723-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | YD000349 | Yard | 723-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | YD000349 | Yard | 723-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Readings | Fault Operations Ground | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Readings | Follow-up Action Required? | n | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Patrol Inspection | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Readings | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | YD000349 | Yard | 723-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | YD000349 | Yard | 723-Yard | Yard Patrol Inspection | General Comments | | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | YD000349 | Yard | 723-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Readings | Maintenance Operations | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Readings | Operations Counter AF | 416 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Readings | Operations Counter AL | 416 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | YD000349 | Yard | 723-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | YD000349 | Yard | 723-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | LTCMechanism | LG-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 333318 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | LTCMechanism | LG-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 333318 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BAT001465 | Battery | 723-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BAT001465 | Battery | 723-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BAT001465 | Battery | 723-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BAT001465 | Battery | 723-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | YD000349 | Yard | 723-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | YD000349 | Yard | 723-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | YD000349 | Yard | 723-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Readings | Unknown Operations | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Readings | Switching Operations | 1 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Readings | Operations This Read Vac | 1 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Readings | Operations Counter AL | 150 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Readings | 9 Month Operations | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Readings | General Comments | | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Readings | Amps A Ø | 198.0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Readings | Amps B Ø | 214.0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Readings | Amps C Ø | 264.0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | LTCMechanism | LG-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BAT001465 | Battery | 723-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BAT001465 | Battery | 723-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 35 | °F |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BCH001376 | Charger | 723-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BCH001376 | Charger | 723-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BCH001376 | Charger | 723-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BCH001376 | Charger | 723-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.4 | amps |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BCH001376 | Charger | 723-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BCH001376 | Charger | 723-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Readings | Operations Counter AF | 255 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Readings | Operations Counter AL | 255 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BAT001465 | Battery | 723-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | LTCMechanism | LG-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 224 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Readings | Follow-up Action Required? | n | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Readings | Fault Operations Ground | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Readings | Amps C Ø | 238.0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Readings | Amps B Ø | 229.0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Readings | Amps A Ø | 249.0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Readings | 9 Month Operations VCB New | 12 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Readings | 9 Month Operations | 13 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Readings | 9 Month Operations | 14 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Readings | 9 Month Operations VCB New | 13 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Readings | Amps A Ø | 279.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Readings | Amps B Ø | 278.0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Readings | Amps C Ø | 232.0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Readings | Amps C Ø | 73.0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Readings | Amps B Ø | 78.0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Readings | Amps A Ø | 85.0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Readings | 9 Month Operations VCB New | 16 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Readings | 9 Month Operations | 17 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Readings | Operations Counter AF | 149 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Readings | Maintenance Operations | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Readings | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Patrol Inspection | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Readings | Follow-up Action Required? | n | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Readings | Fault Operations Ground | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | YD000349 | Yard | 723-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | YD000349 | Yard | 723-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | YD000349 | Yard | 723-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | YD000349 | Yard | 723-Yard | Yard Patrol Inspection | Ambient Temp | 34 | °F |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BAT001465 | Battery | 723-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Readings | Operations This Read Vac | 2 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BAT001465 | Battery | 723-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Readings | Switching Operations | 2 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BAT001465 | Battery | 723-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Readings | 9 Month Operations | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Readings | Unknown Operations | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001824 | BreakerVacuum | 069-2327 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Readings | Unknown Operations | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Readings | Switching Operations | 1 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Readings | Operations This Read Vac | 1 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Readings | Operations Counter AL | 194 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Readings | Operations Counter AF | 193 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Readings | Maintenance Operations | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Readings | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | KB0129 | BreakerVacuum | 069-5 | VCB Patrol Inspection | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Readings | Operations Counter AF | 326 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Readings | Operations Counter AL | 327 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Readings | Operations This Read Vac | 1 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Readings | Switching Operations | 1 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Readings | Fault Operations Ground | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Readings | Follow-up Action Required? | n | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Patrol Inspection | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Readings | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Readings | Maintenance Operations | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Readings | Operations Counter AF | 212 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Readings | Operations Counter AL | 212 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Readings | Operations This Read Vac | 2 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Readings | Switching Operations | 2 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Readings | Unknown Operations | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Readings | Unknown Operations | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Readings | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Readings | LTC Totalizer Reading | 5972.40 | kw |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Readings | Fault Operations Ground | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Readings | Follow-up Action Required? | n | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Patrol Inspection | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Readings | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Readings | Maintenance Operations | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Readings | Amps C Ø | 147.0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Readings | Amps B Ø | 155.0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Readings | Amps A Ø | 160.0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | K0031 | BreakerVacuum | 069-2237 | VCB Readings | 9 Month Operations | 3 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Readings | 9 Month Operations | 2 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Readings | Amps A Ø | 20.0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Readings | Amps B Ø | 27.0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001106 | BreakerVacuum | 069-2325 | VCB Readings | Amps C Ø | 19.0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | LTCC000346 | LTCControl | 723-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | LTCC000346 | LTCControl | 723-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | LTCC000346 | LTCControl | 723-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | LTCC000582 | LTCControl | 723-1 | LTC Control Insp | All Connections OK? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | LTCC000582 | LTCControl | 723-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | LTCC000582 | LTCControl | 723-1 | LTC Control Insp | General Comments | | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | LTCC000582 | LTCControl | 723-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | LTCC000582 | LTCControl | 723-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | LTCC000582 | LTCControl | 723-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | LTCC000582 | LTCControl | 723-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | LTCC000582 | LTCControl | 723-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Readings | 9 Month Operations | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Readings | Amps A Ø | 500.0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Readings | Amps B Ø | 515.0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Readings | Amps C Ø | 535.0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0014 | BreakerVacuum | 723-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Readings | Amps C Ø | 200.0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Readings | Amps B Ø | 200.0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Readings | Amps A Ø | 200.0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Readings | 9 Month Operations | 1 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Readings | Amps A Ø | 129.0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Readings | Amps B Ø | 95.0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Readings | Amps C Ø | 87.0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Readings | Fault Operations Ground | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Readings | Follow-up Action Required? | n | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Patrol Inspection | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Readings | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Readings | Maintenance Operations | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Readings | Operations Counter AF | 211 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Readings | Operations Counter AL | 211 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Readings | Operations This Read Vac | 1 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Readings | Switching Operations | 1 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | BK001107 | BreakerVacuum | 069-2328 | VCB Readings | Unknown Operations | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Readings | 9 Month Operations | 7 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0299 | BreakerVacuum | 069-2326 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | LTCC000346 | LTCControl | 723-2 | LTC Control Insp | All Connections OK? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | LTCC000346 | LTCControl | 723-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | LTCC000346 | LTCControl | 723-2 | LTC Control Insp | General Comments | | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | LTCC000346 | LTCControl | 723-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | LTCC000346 | LTCControl | 723-2 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Readings | General Comments | | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | LTCC000679 | LTCControl | 069-6 | LTC Control Insp | All Connections OK? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | LTCC000679 | LTCControl | 069-6 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | LTCC000679 | LTCControl | 069-6 | LTC Control Insp | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | LTCC000679 | LTCControl | 069-6 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | LTCC000679 | LTCControl | 069-6 | LTC Control Insp | LTC Output Voltage Level | 123.3 | VAC |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | LTCC000679 | LTCControl | 069-6 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Readings | Maintenance Operations | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Readings | Operations Counter AF | 323 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Readings | Operations Counter AL | 323 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Readings | Operations This Read Vac | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Readings | Switching Operations | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0233 | BreakerAirMagnetic | CW-1224 | AMCB Readings | Unknown Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0233 | BreakerAirMagnetic | CW-1224 | AMCB Readings | Switching Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0233 | BreakerAirMagnetic | CW-1224 | AMCB Readings | Operations This Read AM | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0233 | BreakerAirMagnetic | CW-1224 | AMCB Readings | Operations Counter AL | 369 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0233 | BreakerAirMagnetic | CW-1224 | AMCB Readings | Operations Counter AF | 369 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0233 | BreakerAirMagnetic | CW-1224 | AMCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0233 | BreakerAirMagnetic | CW-1224 | AMCB Readings | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0233 | BreakerAirMagnetic | CW-1224 | AMCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0233 | BreakerAirMagnetic | CW-1224 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Readings | Fault Operations Ground | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Readings | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Patrol Inspection | General Comments | | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Readings | General Comments | | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Readings | Maintenance Operations | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0233 | BreakerAirMagnetic | CW-1224 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0233 | BreakerAirMagnetic | CW-1224 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Readings | Amps B Ø | 650.0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Readings | Amps A Ø | 665.0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0233 | BreakerAirMagnetic | CW-1224 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0554 | BreakerAirMagnetic | LG-4 | AMCB Readings | Unknown Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0554 | BreakerAirMagnetic | LG-4 | AMCB Readings | Switching Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0554 | BreakerAirMagnetic | LG-4 | AMCB Readings | Operations This Read AM | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0233 | BreakerAirMagnetic | CW-1224 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | LTCMechanism | 723-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | LTCMechanism | 723-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | LTCMechanism | 723-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | LTCMechanism | 723-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Readings | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Patrol Inspection | General Comments | | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Readings | General Comments | | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Readings | Maintenance Operations | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Readings | Operations Counter AF | 265 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Readings | Operations Counter AL | 265 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Readings | Switching Operations | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Readings | Unknown Operations | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Readings | Amps C Ø | 665.0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Readings | Totalizer Meter Reading | .3318 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Readings | Winding Temp Max | 65 | °C |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Readings | Winding Temp Present | 20 | °C |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0525 | WithLTC | 069-6 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | LTCMechanism | LG-TRANS 1 | LTC Counter Readings | General Comments | this is the correct VC | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | LTCMechanism | LG-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BCH001376 | Charger | 723-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | BCH001376 | Charger | 723-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Readings | Fault Operations Ground | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Readings | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0012 | BreakerVacuum | 723-0444 | VCB Patrol Inspection | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Readings | LTC Totalizer Reading | 5040.00 | kw |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | LTCC000679 | LTCControl | 069-6 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | LTCC000679 | LTCControl | 069-6 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | LTCC000679 | LTCControl | 069-6 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Readings | General Comments | | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Readings | Operations Counter AF | 310 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Readings | Operations Counter AL | 310 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Readings | Operations This Read Vac | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Readings | Switching Operations | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | K0043 | BreakerVacuum | 723-0443 | VCB Readings | Unknown Operations | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | LTCMechanism | 723-2 | LTC Counter Readings | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | C0486 | WithLTC | 069-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | LTCMechanism | 723-2 | LTC Counter Readings | LTC Operations Since Last Insp | 19121 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | LTCMechanism | 723-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 25 | °C |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | LTCMechanism | 723-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 50 | °C |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | LTCMechanism | 723-2 | LTC Counter Readings | LTC Min Tap Position | 16L | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Readings | Unknown Operations | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Readings | Switching Operations | 1 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Readings | Operations This Read Vac | 1 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Readings | Operations Counter AL | 71 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Readings | Operations Counter AF | 70 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Readings | Maintenance Operations | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Readings | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Patrol Inspection | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Readings | Follow-up Action Required? | n | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | LTCMechanism | 723-2 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | LTCMechanism | 723-2 | LTC Counter Readings | LTC Current Tap Position | 4R | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | LTCMechanism | 723-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | LTCMechanism | 723-2 | LTC Counter Readings | LTC As Left Counter | 870242 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | LTCMechanism | 723-2 | LTC Counter Readings | LTC As Found Counter | 870242 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Readings | Fault Operations Ground | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Readings | Amps C Ø | 865.0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Readings | Amps B Ø | 850.0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KT0014 | LTCMechanism | 723-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/24/2023 11:15 | Distribution | Richmond Quarterly Inspection | CB0270 | BreakerVacuum | 069-6 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Readings | Amps A Ø | 865.0 | |
| 2/24/2023 14:56 | Distribution | Lemons Mill Quarterly Inspection | KB0015 | BreakerVacuum | 723-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0523 | Regulator | 729-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0523 | Regulator | 729-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0523 | Regulator | 729-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.2 | volts |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0523 | Regulator | 729-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 117424 | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0523 | Regulator | 729-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0523 | Regulator | 729-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0523 | Regulator | 729-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Readings | Winding Temp Max | 85 | °C |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Readings | General Comments | | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Readings | LTC Totalizer Reading | 16686 | kw |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Readings | Totalizer Meter Reading | .927 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2 | psi |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Readings | Oil Temp Max | 65 | °C |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Readings | Oil Temp Present | 34 | °C |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | WithLTC | 639-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0525 | Regulator | 729-1 C | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0525 | Regulator | 729-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0525 | Regulator | 729-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0525 | Regulator | 729-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0525 | Regulator | 729-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0525 | Regulator | 729-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0523 | Regulator | 729-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0523 | Regulator | 729-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0523 | Regulator | 729-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0523 | Regulator | 729-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0523 | Regulator | 729-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0525 | Regulator | 729-1 C | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | FE000448 | Fence | 545-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0525 | Regulator | 729-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0525 | Regulator | 729-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0525 | Regulator | 729-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0525 | Regulator | 729-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0525 | Regulator | 729-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.3 | volts |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | LTCMechanism | 871-1 | LTC Counter Readings | LTC As Found Counter | 87233 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | LTCMechanism | 871-1 | LTC Counter Readings | LTC As Left Counter | 87233 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | LTCMechanism | 871-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | LTCMechanism | 871-1 | LTC Counter Readings | LTC Current Tap Position | 2R | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | LTCMechanism | 871-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | LTCMechanism | 871-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | LTCMechanism | 871-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0525 | Regulator | 729-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 65852 | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0525 | Regulator | 729-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0525 | Regulator | 729-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0525 | Regulator | 729-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | LTCMechanism | 871-1 | LTC Counter Readings | LTC Operations Since Last Insp | 528 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | LTCMechanism | 871-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | LTCMechanism | 833-1 | LTC Counter Readings | General Comments | | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | LTCMechanism | 833-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | LTCMechanism | 871-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | LTCMechanism | 871-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | LTCMechanism | 871-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0523 | Regulator | 729-1 A | Regulator Patrol Inspection | Current Tap Position | 11L | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0523 | Regulator | 729-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0523 | Regulator | 729-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0523 | Regulator | 729-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | LTCMechanism | 833-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0523 | Regulator | 729-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0523 | Regulator | 729-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0523 | Regulator | 729-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0525 | Regulator | 729-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0525 | Regulator | 729-1 C | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0525 | Regulator | 729-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0525 | Regulator | 729-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0525 | Regulator | 729-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Readings | General Comments | | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0523 | Regulator | 729-1 A | Regulator Patrol Inspection | Max Tap Position | 16R | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0523 | Regulator | 729-1 A | Regulator Patrol Inspection | Min Tap Position | 16L | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Readings | General Comments | | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Readings | Operations Counter AF | 182 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Readings | Operations Counter AL | 182 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Readings | Switching Operations | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0523 | Regulator | 729-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0523 | Regulator | 729-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | FE000448 | Fence | 545-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | FE000448 | Fence | 545-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | YD000452 | Yard | 545-Yard | Yard Patrol Inspection | Ambient Temp | 65 | °F |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | YD000452 | Yard | 545-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | YD000452 | Yard | 545-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | YD000452 | Yard | 545-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | YD000452 | Yard | 545-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | YD000452 | Yard | 545-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | YD000452 | Yard | 545-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | LTCMechanism | 639-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | YD000446 | Yard | 871-Yard | Yard Patrol Inspection | Ambient Temp | 70 | °F |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | YD000446 | Yard | 871-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | YD000446 | Yard | 871-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Readings | 9 Month Operations | 1 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | YD000446 | Yard | 871-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | YD000446 | Yard | 871-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | LTCMechanism | 639-1 | LTC Counter Readings | General Comments | | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | LTCMechanism | 639-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | FE000448 | Fence | 545-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | YD000446 | Yard | 871-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Readings | Amps A Ø | 208.0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Readings | Amps B Ø | 188.0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Readings | Amps C Ø | 209.0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | YD000446 | Yard | 871-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | YD000446 | Yard | 871-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | YD000446 | Yard | 871-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | YD000446 | Yard | 871-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | YD000446 | Yard | 871-Yard | Yard Patrol Inspection | General Comments | | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | YD000446 | Yard | 871-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | YD000446 | Yard | 871-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | YD000446 | Yard | 871-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | YD000446 | Yard | 871-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | ST000447 | Structure | 871-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | ST000447 | Structure | 871-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | ST000447 | Structure | 871-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | ST000447 | Structure | 871-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | ST000447 | Structure | 871-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | ST000447 | Structure | 871-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | ST000447 | Structure | 871-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | ST000447 | Structure | 871-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | ST000447 | Structure | 871-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | ST000447 | Structure | 871-Structure | Structure Patrol Inspection | General Comments | | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | ST000447 | Structure | 871-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | ST000447 | Structure | 871-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | ST000447 | Structure | 871-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | ST000447 | Structure | 871-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | LTCMechanism | 639-1 | LTC Counter Readings | LTC Operations Since Last Insp | 801 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | LTCMechanism | 639-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | LTCMechanism | 639-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | LTCMechanism | 639-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BAT001306 | Battery | 829-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BAT001306 | Battery | 829-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BAT001306 | Battery | 829-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BAT001306 | Battery | 829-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BAT001306 | Battery | 829-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BAT001306 | Battery | 829-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BAT001306 | Battery | 829-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BAT001306 | Battery | 829-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BAT001306 | Battery | 829-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BCH001245 | Charger | 829-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BCH001245 | Charger | 829-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BCH001245 | Charger | 829-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BCH001245 | Charger | 829-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BCH001245 | Charger | 829-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.1 | amps |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BCH001245 | Charger | 829-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | LTCMechanism | 639-1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | LTCMechanism | 639-1 | LTC Counter Readings | LTC Max Tap Position | 7R | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | LTCMechanism | 639-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | FE000448 | Fence | 545-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | FE000448 | Fence | 545-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | FE000448 | Fence | 545-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | LTCMechanism | 639-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | LTCMechanism | 639-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | LTCMechanism | 639-1 | LTC Counter Readings | LTC As Left Counter | 61542 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BCH001245 | Charger | 829-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BCH001245 | Charger | 829-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | FE000461 | Fence | 871-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | FE000461 | Fence | 871-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | FE000461 | Fence | 871-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | FE000461 | Fence | 871-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | FE000461 | Fence | 871-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | FE000461 | Fence | 871-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | LTCMechanism | 871-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | FE000461 | Fence | 871-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | FE000461 | Fence | 871-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | LTCMechanism | 871-1 | LTC Counter Readings | General Comments | | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | LTCMechanism | 871-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | FE000461 | Fence | 871-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | FE000461 | Fence | 871-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | FE000461 | Fence | 871-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | FE000461 | Fence | 871-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | FE000461 | Fence | 871-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | FE000461 | Fence | 871-Fence | Fence Patrol Inspection | General Comments | | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | FE000461 | Fence | 871-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | FE000461 | Fence | 871-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | LTCMechanism | 871-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BAT001306 | Battery | 829-Battery Bank | Battery Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BAT001306 | Battery | 829-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BAT001306 | Battery | 829-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BAT001306 | Battery | 829-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BAT001306 | Battery | 829-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | LTCMechanism | 639-1 | LTC Counter Readings | LTC As Found Counter | 61536 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | LTCMechanism | 639-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | FE000448 | Fence | 545-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | FE000448 | Fence | 545-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | FE000448 | Fence | 545-Fence | Fence Patrol Inspection | General Comments | | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | LTCMechanism | 833-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | LTCMechanism | 833-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 68 | °C |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | LTCMechanism | 833-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 30 | °C |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0524 | Regulator | 729-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0524 | Regulator | 729-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0524 | Regulator | 729-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.5 | volts |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | LTCMechanism | 833-1 | LTC Counter Readings | LTC As Found Counter | 110886 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | LTCMechanism | 833-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0524 | Regulator | 729-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 120168 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | LTCMechanism | 833-1 | LTC Counter Readings | LTC Operations Since Last Insp | 938 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | ST000454 | Structure | 545-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | LTCMechanism | 833-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | LTCMechanism | 833-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | LTCMechanism | 833-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | LTCMechanism | 833-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0524 | Regulator | 729-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | ST000447 | Structure | 871-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | ST000447 | Structure | 871-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | ST000447 | Structure | 871-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | ST000447 | Structure | 871-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Readings | General Comments | | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Readings | Operations Counter AF | 158 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Readings | Operations Counter AL | 158 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Readings | Switching Operations | 0 | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0524 | Regulator | 729-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0524 | Regulator | 729-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0525 | Regulator | 729-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0525 | Regulator | 729-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Readings | 9 Month Operations | 7 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Readings | Amps A Ø | 102.0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Readings | Amps B Ø | 111.0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Readings | Amps C Ø | 118.0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | LTCMechanism | 639-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000988 | BreakerVacuum | 461-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | ST000454 | Structure | 545-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | ST000447 | Structure | 871-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | ST000454 | Structure | 545-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | ST000454 | Structure | 545-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | ST000454 | Structure | 545-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | ST000447 | Structure | 871-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | ST000447 | Structure | 871-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Readings | 9 Month Operations | 5 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Readings | Amps A Ø | 283.0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Readings | Amps B Ø | 249.0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Readings | Amps C Ø | 285.0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | ST000454 | Structure | 545-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0524 | Regulator | 729-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0524 | Regulator | 729-1 B | Regulator Patrol Inspection | Min Tap Position | 15L | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0524 | Regulator | 729-1 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0524 | Regulator | 729-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0524 | Regulator | 729-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0524 | Regulator | 729-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | KB0085 | BreakerVacuum | 829-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0524 | Regulator | 729-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0524 | Regulator | 729-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0524 | Regulator | 729-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0524 | Regulator | 729-1 B | Regulator Patrol Inspection | Current Tap Position | 10L | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0524 | Regulator | 729-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | ST000454 | Structure | 545-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | ST000454 | Structure | 545-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | ST000447 | Structure | 871-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | ST000454 | Structure | 545-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | ST000454 | Structure | 545-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | ST000454 | Structure | 545-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0524 | Regulator | 729-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | ST000454 | Structure | 545-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | ST000454 | Structure | 545-Structure | Structure Patrol Inspection | General Comments | | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | ST000454 | Structure | 545-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | ST000454 | Structure | 545-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | ST000454 | Structure | 545-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | ST000454 | Structure | 545-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | ST000454 | Structure | 545-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | ST000454 | Structure | 545-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | ST000454 | Structure | 545-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | ST000454 | Structure | 545-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | ST000454 | Structure | 545-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0524 | Regulator | 729-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0524 | Regulator | 729-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0524 | Regulator | 729-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | R0524 | Regulator | 729-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | LTCMechanism | 833-1 | LTC Counter Readings | LTC As Left Counter | 110886 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | LTCMechanism | 833-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | LTCMechanism | 833-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | LTCMechanism | 833-1 | LTC Counter Readings | LTC Max Tap Position | 8R | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | ST000848 | Structure | 461-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | ST000848 | Structure | 461-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | ST000848 | Structure | 461-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | ST000848 | Structure | 461-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | ST000848 | Structure | 461-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | ST000848 | Structure | 461-Structure | Structure Patrol Inspection | General Comments | | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | ST000848 | Structure | 461-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | ST000848 | Structure | 461-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | ST000848 | Structure | 461-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | ST000848 | Structure | 461-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | ST000848 | Structure | 461-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | ST000848 | Structure | 461-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | ST000848 | Structure | 461-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | ST000848 | Structure | 461-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | ST000848 | Structure | 461-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | ST000848 | Structure | 461-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | ST000848 | Structure | 461-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | FE000846 | Fence | 461-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | FE000846 | Fence | 461-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | FE000846 | Fence | 461-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | FE000846 | Fence | 461-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | ST000468 | Structure | 833-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | ST000468 | Structure | 833-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | ST000468 | Structure | 833-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | ST000468 | Structure | 833-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | ST000468 | Structure | 833-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | ST000468 | Structure | 833-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | ST000468 | Structure | 833-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | ST000468 | Structure | 833-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | ST000468 | Structure | 833-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | ST000468 | Structure | 833-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | ST000468 | Structure | 833-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | ST000468 | Structure | 833-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | ST000468 | Structure | 833-Structure | Structure Patrol Inspection | General Comments | | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | ST000468 | Structure | 833-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | ST000468 | Structure | 833-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | ST000468 | Structure | 833-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | ST000468 | Structure | 833-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | ST000468 | Structure | 833-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | ST000468 | Structure | 833-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | FE000846 | Fence | 461-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | FE000846 | Fence | 461-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | FE000846 | Fence | 461-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | FE000846 | Fence | 461-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | FE000846 | Fence | 461-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | FE000846 | Fence | 461-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | FE000846 | Fence | 461-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | FE000846 | Fence | 461-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | ST000468 | Structure | 833-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | ST000468 | Structure | 833-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | ST000468 | Structure | 833-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Readings | Oil Temp Present | 37 | °C |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Readings | Switching Operations | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Readings | Operations This Read Vac | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AL | 257 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AF | 257 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Readings | General Comments | | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Readings | Totalizer Meter Reading | .8124 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Readings | Winding Temp Max | 60 | °C |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Readings | Winding Temp Present | 38 | °C |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Readings | Amps C Ø | 123.0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Readings | Amps B Ø | 125.0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Readings | Amps A Ø | 125.0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations VCB New | 11 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0106 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations | 11 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | ST000848 | Structure | 461-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | ST000848 | Structure | 461-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | YD000533 | Yard | 429-Yard | Yard Patrol Inspection | Ambient Temp | 70 | °F |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Readings | General Comments | | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Readings | LTC Totalizer Reading | 8143.20 | kw |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Readings | Totalizer Meter Reading | .4524 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | YD000533 | Yard | 429-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | YD000533 | Yard | 429-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | YD000533 | Yard | 429-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | YD000533 | Yard | 429-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | YD000533 | Yard | 429-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | YD000533 | Yard | 429-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | YD000533 | Yard | 429-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | YD000533 | Yard | 429-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | YD000533 | Yard | 429-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | YD000533 | Yard | 429-Yard | Yard Patrol Inspection | General Comments | | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | YD000533 | Yard | 429-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | YD000533 | Yard | 429-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | YD000533 | Yard | 429-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | YD000533 | Yard | 429-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | LTCC000722 | LTCControl | 545-1 | LTC Control Insp | All Connections OK? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | LTCC000722 | LTCControl | 545-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | LTCC000722 | LTCControl | 545-1 | LTC Control Insp | General Comments | | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | LTCC000722 | LTCControl | 545-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | LTCC000722 | LTCControl | 545-1 | LTC Control Insp | LTC Output Voltage Level | 123.8 | VAC |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | LTCC000722 | LTCControl | 545-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | FE000459 | Fence | 833-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | FE000459 | Fence | 833-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | FE000459 | Fence | 833-Fence | Fence Patrol Inspection | General Comments | | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | FE000459 | Fence | 833-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | FE000459 | Fence | 833-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | FE000459 | Fence | 833-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | FE000459 | Fence | 833-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | FE000459 | Fence | 833-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | FE000459 | Fence | 833-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | FE000459 | Fence | 833-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | FE000459 | Fence | 833-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | FE000459 | Fence | 833-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | FE000459 | Fence | 833-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | FE000459 | Fence | 833-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | FE000459 | Fence | 833-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | FE000459 | Fence | 833-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | FE000846 | Fence | 461-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | FE000846 | Fence | 461-Fence | Fence Patrol Inspection | General Comments | | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | FE000846 | Fence | 461-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | FE000846 | Fence | 461-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Readings | 9 Month Operations | 1 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Readings | Amps A Ø | 283.0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | LTCM000061 | LTCMechanism | 545-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | LTCM000061 | LTCMechanism | 545-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | LTCM000061 | LTCMechanism | 545-1 | LTC Counter Readings | General Comments | | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | LTCM000061 | LTCMechanism | 545-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | LTCM000061 | LTCMechanism | 545-1 | LTC Counter Readings | LTC As Found Counter | 20962 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | LTCM000061 | LTCMechanism | 545-1 | LTC Counter Readings | LTC As Left Counter | 20962 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | LTCM000061 | LTCMechanism | 545-1 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | LTCM000061 | LTCMechanism | 545-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | LTCM000061 | LTCMechanism | 545-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Readings | Amps B Ø | 249.0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Readings | Amps C Ø | 285.0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | LTCM000061 | LTCMechanism | 545-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | LTCM000061 | LTCMechanism | 545-1 | LTC Counter Readings | LTC Operations Since Last Insp | 678 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | LTCM000061 | LTCMechanism | 545-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | LTCM000061 | LTCMechanism | 545-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | WithLTC | 833-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | LTCM000061 | LTCMechanism | 545-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | LTCM000061 | LTCMechanism | 545-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Readings | Switching Operations | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Readings | General Comments | | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Readings | Operations Counter AF | 216 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Readings | Operations Counter AL | 216 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Readings | Operations This Read Vac | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Readings | Switching Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | ST000337 | Structure | 639-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | ST000337 | Structure | 639-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | ST000337 | Structure | 639-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | ST000337 | Structure | 639-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | ST000337 | Structure | 639-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | ST000337 | Structure | 639-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | ST000337 | Structure | 639-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | ST000337 | Structure | 639-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | ST000337 | Structure | 639-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | ST000337 | Structure | 639-Structure | Structure Patrol Inspection | General Comments | | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | ST000337 | Structure | 639-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | ST000337 | Structure | 639-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | ST000337 | Structure | 639-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | ST000337 | Structure | 639-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | ST000337 | Structure | 639-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | ST000337 | Structure | 639-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | ST000337 | Structure | 639-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | ST000337 | Structure | 639-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | ST000337 | Structure | 639-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | ST000337 | Structure | 639-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | ST000337 | Structure | 639-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | ST000337 | Structure | 639-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | ST000337 | Structure | 639-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | FE000328 | Fence | 639-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | FE000328 | Fence | 639-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | FE000328 | Fence | 639-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | FE000328 | Fence | 639-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | FE000328 | Fence | 639-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | FE000328 | Fence | 639-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | FE000328 | Fence | 639-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Readings | 9 Month Operations | 1 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Readings | Accumulated Fault Duty B Ph V | .47 | % |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Readings | Amps A Ø | 186 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Readings | Amps B Ø | 150 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Readings | Amps C Ø | 161 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | LTCC000836 | LTCControl | 639-1 | LTC Control Insp | All Connections OK? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | LTCC000836 | LTCControl | 639-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | LTCC000836 | LTCControl | 639-1 | LTC Control Insp | General Comments | | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | LTCC000836 | LTCControl | 639-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | LTCC000836 | LTCControl | 639-1 | LTC Control Insp | LTC Output Voltage Level | 123.7 | VAC |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | LTCC000836 | LTCControl | 639-1 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | LTCC000836 | LTCControl | 639-1 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | LTCC000836 | LTCControl | 639-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Readings | General Comments | | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Readings | Operations Counter AF | 287 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Readings | Operations Counter AL | 287 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Readings | Operations This Read Vac | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0001 | BreakerVacuum | 639-0160 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Readings | 9 Month Operations | 12 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Readings | 9 Month Operations VCB New | 12 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Readings | Amps A Ø | 155.0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Readings | Amps B Ø | 177.0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Readings | Amps C Ø | 171.0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BCH001261 | Charger | 461-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.7 | VDC |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BCH001261 | Charger | 461-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.1 | amps |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BCH000610 | Charger | 833-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BCH000610 | Charger | 833-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.8 | VDC |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BCH000610 | Charger | 833-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.8 | VDC |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BCH000610 | Charger | 833-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 3.8 | amps |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BCH000610 | Charger | 833-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BCH000610 | Charger | 833-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BCH001261 | Charger | 461-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BCH001261 | Charger | 461-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BCH001261 | Charger | 461-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BCH001261 | Charger | 461-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Readings | Amps C Ø | 41.0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BAT001321 | Battery | 461-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BAT001321 | Battery | 461-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BAT001321 | Battery | 461-Battery Bank | Battery Patrol Inspection | Battery Bank Volts | 133.7 | VDC |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BAT001321 | Battery | 461-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Readings | Amps B Ø | 33.0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Readings | Amps A Ø | 43.0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Readings | 9 Month Operations | 8 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BAT001321 | Battery | 461-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BAT001321 | Battery | 461-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BAT001321 | Battery | 461-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BAT001321 | Battery | 461-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #'s |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BAT001321 | Battery | 461-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BAT001321 | Battery | 461-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BAT001321 | Battery | 461-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BAT001321 | Battery | 461-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 68.4 | VDC |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BAT001321 | Battery | 461-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 65.3 | VDC |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BAT001321 | Battery | 461-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BAT001321 | Battery | 461-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Readings | General Comments | | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Readings | LTC Totalizer Reading | 14623.20 | kw |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | TX000129 | WithLTC | 545-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | FE000328 | Fence | 639-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | FE000328 | Fence | 639-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | FE000328 | Fence | 639-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | FE000328 | Fence | 639-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | FE000328 | Fence | 639-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | FE000328 | Fence | 639-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | FE000328 | Fence | 639-Fence | Fence Patrol Inspection | General Comments | | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | FE000328 | Fence | 639-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | FE000328 | Fence | 639-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Readings | Switching Operations | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Readings | Operations This Read Vac | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Readings | Operations Counter AL | 228 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Readings | Operations Counter AF | 228 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000424 | BreakerVacuum | 545-2321 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | BAT000569 | Battery | 429-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | BAT000569 | Battery | 429-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | BAT000569 | Battery | 429-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Readings | General Comments | | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK000650 | BreakerVacuum | 545-2323 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | BAT000569 | Battery | 429-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | BAT000569 | Battery | 429-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | BAT000569 | Battery | 429-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | BAT000569 | Battery | 429-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | BAT000569 | Battery | 429-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | BAT000569 | Battery | 429-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | BAT000569 | Battery | 429-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | BAT000569 | Battery | 429-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | BAT000569 | Battery | 429-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 53.4 | VDC |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | BAT000569 | Battery | 429-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | BAT000569 | Battery | 429-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | BAT000569 | Battery | 429-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BCH001261 | Charger | 461-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BCH001261 | Charger | 461-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.7 | VDC |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BAT001113 | Battery | 833-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BAT001113 | Battery | 833-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BAT001113 | Battery | 833-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BAT001113 | Battery | 833-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BAT001113 | Battery | 833-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | BCH001182 | Charger | 429-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | BCH001182 | Charger | 429-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | BCH001182 | Charger | 429-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | ST000537 | Structure | 429-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | ST000537 | Structure | 429-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | ST000537 | Structure | 429-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | ST000537 | Structure | 429-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | ST000537 | Structure | 429-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | ST000537 | Structure | 429-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | ST000537 | Structure | 429-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | ST000537 | Structure | 429-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | ST000537 | Structure | 429-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | ST000537 | Structure | 429-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | ST000537 | Structure | 429-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | ST000537 | Structure | 429-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | ST000537 | Structure | 429-Structure | Structure Patrol Inspection | General Comments | | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | ST000537 | Structure | 429-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | ST000537 | Structure | 429-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | ST000537 | Structure | 429-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | BCH001182 | Charger | 429-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.5 | amps |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | BCH001182 | Charger | 429-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | BCH001182 | Charger | 429-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | BCH001182 | Charger | 429-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | BCH001182 | Charger | 429-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | ST000537 | Structure | 429-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | ST000537 | Structure | 429-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | ST000537 | Structure | 429-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | ST000537 | Structure | 429-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | ST000537 | Structure | 429-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | ST000537 | Structure | 429-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | LTCC000694 | LTCControl | 829-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | LTCC000694 | LTCControl | 829-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | LTCC000694 | LTCControl | 829-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | LTCC000694 | LTCControl | 829-1 | LTC Control Insp | LTC Output Voltage Level | 123.4 | VAC |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | LTCC000694 | LTCControl | 829-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | LTCC000694 | LTCControl | 829-1 | LTC Control Insp | General Comments | | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | LTCC000694 | LTCControl | 829-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | LTCC000694 | LTCControl | 829-1 | LTC Control Insp | All Connections OK? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | YD000465 | Yard | 833-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | YD000465 | Yard | 833-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | YD000465 | Yard | 833-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | YD000465 | Yard | 833-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | YD000465 | Yard | 833-Yard | Yard Patrol Inspection | General Comments | | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | YD000465 | Yard | 833-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | YD000465 | Yard | 833-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | YD000465 | Yard | 833-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | YD000465 | Yard | 833-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | YD000465 | Yard | 833-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | YD000465 | Yard | 833-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | YD000465 | Yard | 833-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | LTCM000090 | LTCMechanism | 461-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | LTCM000090 | LTCMechanism | 461-1 | LTC Counter Readings | General Comments | | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | LTCM000090 | LTCMechanism | 461-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Readings | General Comments | | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Readings | LTC Totalizer Reading | 11779.20 | kw |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1400 | psi |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Readings | Oil Temp Max | 42 | °C |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Readings | Totalizer Meter Reading | .8180 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | LTCM000090 | LTCMechanism | 461-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | LTCC000797 | LTCControl | 461-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | LTCC000797 | LTCControl | 461-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | LTCC000797 | LTCControl | 461-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | LTCC000797 | LTCControl | 461-1 | LTC Control Insp | LTC Output Voltage Level | 123.6 | VAC |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | LTCC000797 | LTCControl | 461-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | LTCC000797 | LTCControl | 461-1 | LTC Control Insp | General Comments | | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | LTCC000797 | LTCControl | 461-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | LTCC000797 | LTCControl | 461-1 | LTC Control Insp | All Connections OK? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BAT001113 | Battery | 833-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BAT001113 | Battery | 833-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BAT001113 | Battery | 833-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 17.0 | VDC |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BAT001113 | Battery | 833-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 30.0 | VDC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BAT001113 | Battery | 833-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BAT001113 | Battery | 833-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BAT001113 | Battery | 833-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BAT001113 | Battery | 833-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BAT001113 | Battery | 833-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BAT001113 | Battery | 833-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BCH001330 | Charger | 545-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BCH001330 | Charger | 545-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BCH001330 | Charger | 545-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BCH001330 | Charger | 545-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Readings | Switching Operations | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Readings | Operations This Read Vac | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | YD000334 | Yard | 639-Yard | Yard Patrol Inspection | Ambient Temp | 74 | °F |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | YD000334 | Yard | 639-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | YD000334 | Yard | 639-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | YD000334 | Yard | 639-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | YD000334 | Yard | 639-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | YD000334 | Yard | 639-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | YD000334 | Yard | 639-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | YD000334 | Yard | 639-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | YD000334 | Yard | 639-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | YD000334 | Yard | 639-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | YD000334 | Yard | 639-Yard | Yard Patrol Inspection | General Comments | | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | YD000334 | Yard | 639-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | YD000334 | Yard | 639-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | YD000334 | Yard | 639-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | YD000334 | Yard | 639-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | YD000334 | Yard | 639-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Readings | Operations Counter AL | 244 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Readings | Operations Counter AF | 244 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | LTCMechanism | 429-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | LTCMechanism | 429-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | LTCMechanism | 429-1 | LTC Counter Readings | General Comments | | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | LTCMechanism | 429-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | LTCMechanism | 429-1 | LTC Counter Readings | LTC As Found Counter | 46004 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | LTCMechanism | 429-1 | LTC Counter Readings | LTC As Left Counter | 46004 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | LTCMechanism | 429-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | LTCMechanism | 429-1 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | LTCMechanism | 429-1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | LTCMechanism | 429-1 | LTC Counter Readings | LTC Min Tap Position | 15L | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | LTCMechanism | 429-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 35 | °C |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | LTCMechanism | 429-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 30 | °C |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | LTCMechanism | 429-1 | LTC Counter Readings | LTC Operations Since Last Insp | 891 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | LTCMechanism | 429-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | LTCMechanism | 429-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | LTCMechanism | 429-1 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | LTCMechanism | 429-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | LTCMechanism | 429-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0193 | BreakerVacuum | 833-2314 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | YD000465 | Yard | 833-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | YD000465 | Yard | 833-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | YD000465 | Yard | 833-Yard | Yard Patrol Inspection | Ambient Temp | 70 | °F |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Readings | Winding Temp Present | 32 | °C |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BAT001411 | Battery | 545-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BAT001411 | Battery | 545-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BAT001411 | Battery | 545-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BAT001411 | Battery | 545-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BAT001411 | Battery | 545-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BAT001411 | Battery | 545-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BAT001411 | Battery | 545-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BAT001411 | Battery | 545-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BAT001411 | Battery | 545-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BAT001411 | Battery | 545-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BAT001411 | Battery | 545-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.3 | VDC |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BAT001411 | Battery | 545-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.1 | VDC |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BAT001411 | Battery | 545-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BAT001411 | Battery | 545-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Readings | Winding Temp Max | 32 | °C |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Readings | Totalizer Meter Reading | .4130 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Readings | Oil Temp Present | 32 | °C |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Readings | Oil Temp Max | 32 | °C |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1000 | psi |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Readings | LTC Totalizer Reading | 9912.00 | kw |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Readings | General Comments | | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | TX000220 | WithLTC | 461-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BCH001330 | Charger | 545-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BCH001330 | Charger | 545-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BCH001330 | Charger | 545-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BCH001330 | Charger | 545-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.5 | amps |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BAT001561 | Battery | 871-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BAT001561 | Battery | 871-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BAT001561 | Battery | 871-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BAT001561 | Battery | 871-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BAT001561 | Battery | 871-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | ST000458 | Structure | 829-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | FE000505 | Fence | 729-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | FE000505 | Fence | 729-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | FE000505 | Fence | 729-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | FE000505 | Fence | 729-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Readings | General Comments | | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BAT001561 | Battery | 871-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BAT001561 | Battery | 871-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Readings | Operations Counter AF | 158 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Readings | Operations Counter AL | 158 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Readings | Operations This Read Vac | 1 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Readings | Switching Operations | 1 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0122 | BreakerVacuum | 429-1 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | ST000458 | Structure | 829-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | ST000458 | Structure | 829-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | ST000458 | Structure | 829-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | ST000458 | Structure | 829-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | ST000458 | Structure | 829-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | ST000458 | Structure | 829-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | ST000458 | Structure | 829-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | ST000458 | Structure | 829-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BAT001561 | Battery | 871-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BAT001561 | Battery | 871-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | ST000458 | Structure | 829-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | ST000458 | Structure | 829-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | ST000458 | Structure | 829-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | ST000458 | Structure | 829-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | ST000458 | Structure | 829-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | ST000458 | Structure | 829-Structure | Structure Patrol Inspection | General Comments | | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | ST000458 | Structure | 829-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | ST000458 | Structure | 829-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | ST000458 | Structure | 829-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | ST000458 | Structure | 829-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | ST000458 | Structure | 829-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | ST000458 | Structure | 829-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | ST000458 | Structure | 829-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | ST000458 | Structure | 829-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | ST000458 | Structure | 829-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | YD000456 | Yard | 829-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | YD000456 | Yard | 829-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | YD000456 | Yard | 829-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | LTCC000722 | LTCControl | 545-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | LTCC000722 | LTCControl | 545-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | YD000510 | Yard | 729-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | YD000510 | Yard | 729-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | LTCMechanism | 829-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | LTCMechanism | 829-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | LTCMechanism | 829-1 | LTC Counter Readings | General Comments | | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | LTCMechanism | 829-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | LTCMechanism | 829-1 | LTC Counter Readings | LTC As Found Counter | 25509 | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | YD000510 | Yard | 729-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | YD000510 | Yard | 729-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | YD000510 | Yard | 729-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | YD000510 | Yard | 729-Yard | Yard Patrol Inspection | General Comments | | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | YD000510 | Yard | 729-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | YD000510 | Yard | 729-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | YD000510 | Yard | 729-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | YD000510 | Yard | 729-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | YD000510 | Yard | 729-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | YD000510 | Yard | 729-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | YD000510 | Yard | 729-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | YD000510 | Yard | 729-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | YD000510 | Yard | 729-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | YD000510 | Yard | 729-Yard | Yard Patrol Inspection | Ambient Temp | 65 | °F |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | LTCMechanism | 829-1 | LTC Counter Readings | LTC As Left Counter | 25509 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | LTCMechanism | 829-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | LTCMechanism | 829-1 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | LTCMechanism | 829-1 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | LTCMechanism | 829-1 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | LTCMechanism | 829-1 | LTC Counter Readings | LTC Operations Since Last Insp | 759 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | LTCMechanism | 829-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | FE000505 | Fence | 729-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | FE000505 | Fence | 729-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | FE000505 | Fence | 729-Fence | Fence Patrol Inspection | General Comments | | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | FE000505 | Fence | 729-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | FE000505 | Fence | 729-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | FE000505 | Fence | 729-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | FE000505 | Fence | 729-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | LTCMechanism | 829-1 | LTC Counter Readings | Reset Tap Drag Hands | Unable to Reset | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | LTCMechanism | 829-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | FE000505 | Fence | 729-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | FE000505 | Fence | 729-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | FE000505 | Fence | 729-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | FE000505 | Fence | 729-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | FE000505 | Fence | 729-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BCH001496 | Charger | 871-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BCH001496 | Charger | 871-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BCH001496 | Charger | 871-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BCH001496 | Charger | 871-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BCH001496 | Charger | 871-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.2 | amps |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BCH001496 | Charger | 871-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.1 | VDC |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BCH001496 | Charger | 871-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.1 | VDC |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BCH001496 | Charger | 871-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BAT001561 | Battery | 871-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BAT001561 | Battery | 871-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BAT001561 | Battery | 871-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BAT001561 | Battery | 871-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | FE000448 | Fence | 545-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | FE000448 | Fence | 545-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | FE000448 | Fence | 545-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | FE000448 | Fence | 545-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | FE000448 | Fence | 545-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Readings | Oil Temp Present | 50 | °C |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Readings | Oil Temp Max | 80 | °C |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | FE000448 | Fence | 545-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Readings | LTC Totalizer Reading | 7581.60 | kw |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Readings | General Comments | | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | LTCM000090 | LTCMechanism | 461-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | LTCM000090 | LTCMechanism | 461-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | LTCM000090 | LTCMechanism | 461-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | LTCM000090 | LTCMechanism | 461-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | LTCM000090 | LTCMechanism | 461-1 | LTC Counter Readings | LTC Operations Since Last Insp | 483 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | LTCM000090 | LTCMechanism | 461-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 27 | °C |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | LTCM000090 | LTCMechanism | 461-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 27 | °C |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | LTCM000090 | LTCMechanism | 461-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | LTCM000090 | LTCMechanism | 461-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | LTCM000090 | LTCMechanism | 461-1 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | LTCM000090 | LTCMechanism | 461-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | LTCM000090 | LTCMechanism | 461-1 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | LTCM000090 | LTCMechanism | 461-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | LTCM000090 | LTCMechanism | 461-1 | LTC Counter Readings | LTC As Left Counter | 9455 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | LTCM000090 | LTCMechanism | 461-1 | LTC Counter Readings | LTC As Found Counter | 9455 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KT0042 | WithLTC | 429-1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | YD000456 | Yard | 829-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | YD000456 | Yard | 829-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | YD000456 | Yard | 829-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | YD000456 | Yard | 829-Yard | Yard Patrol Inspection | General Comments | | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | YD000456 | Yard | 829-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | YD000456 | Yard | 829-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | YD000456 | Yard | 829-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | YD000456 | Yard | 829-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | YD000456 | Yard | 829-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | YD000456 | Yard | 829-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | YD000456 | Yard | 829-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | YD000456 | Yard | 829-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | YD000456 | Yard | 829-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | YD000456 | Yard | 829-Yard | Yard Patrol Inspection | Ambient Temp | 70 | °F |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CS000002 | CircuitSwitcher | 429-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Ambient Temperature | 70 | °F |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CS000002 | CircuitSwitcher | 429-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CS000002 | CircuitSwitcher | 429-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CS000002 | CircuitSwitcher | 429-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CS000002 | CircuitSwitcher | 429-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CS000002 | CircuitSwitcher | 429-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CS000002 | CircuitSwitcher | 429-1 Trans-Rupter | Circuit Switcher Patrol Inspection | General Comments | | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CS000002 | CircuitSwitcher | 429-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CS000002 | CircuitSwitcher | 429-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CS000002 | CircuitSwitcher | 429-1 Trans-Rupter | Circuit Switcher Patrol Inspection | SF6 Bushing Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CS000002 | CircuitSwitcher | 429-1 Trans-Rupter | Circuit Switcher Patrol Inspection | SF6 Indicator Zone | OK | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CS000002 | CircuitSwitcher | 429-1 Trans-Rupter | Circuit Switcher Patrol Inspection | Trip-energy Supply Verified | y | LED lights? |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CH000418 | ControlHouse | 429-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CH000418 | ControlHouse | 429-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CH000418 | ControlHouse | 429-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CH000418 | ControlHouse | 429-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CH000418 | ControlHouse | 429-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CH000418 | ControlHouse | 429-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CH000418 | ControlHouse | 429-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CH000418 | ControlHouse | 429-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CH000418 | ControlHouse | 429-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CH000418 | ControlHouse | 429-Control House | Control House Patrol Inspection | Filters Condition OK? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CH000418 | ControlHouse | 429-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CH000418 | ControlHouse | 429-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CH000418 | ControlHouse | 429-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CH000418 | ControlHouse | 429-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CH000418 | ControlHouse | 429-Control House | Control House Patrol Inspection | General Comments | | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CH000418 | ControlHouse | 429-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CH000418 | ControlHouse | 429-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CH000418 | ControlHouse | 429-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CH000418 | ControlHouse | 429-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CH000418 | ControlHouse | 429-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | CH000418 | ControlHouse | 429-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 65.00 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Readings | Winding Temp Max | 70 | °C |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Readings | Totalizer Meter Reading | .4212 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | C0499 | WithLTC | 829-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Readings | Operations This Read Vac | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Readings | Switching Operations | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | LTCMechanism | 639-2 | LTC Counter Readings | LTC As Found Counter | 79788 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | LTCC000906 | LTCControl | 871-1 | LTC Control Insp | All Connections OK? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | LTCC000906 | LTCControl | 871-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | LTCC000906 | LTCControl | 871-1 | LTC Control Insp | General Comments | | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | LTCC000906 | LTCControl | 871-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | LTCC000906 | LTCControl | 871-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | LTCC000906 | LTCControl | 871-1 | LTC Control Insp | VRR Base Voltage AF | 124.5 | VAC |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | LTCC000906 | LTCControl | 871-1 | LTC Control Insp | VRR Base Voltage AL | 124.5 | VAC |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | LTCC000906 | LTCControl | 871-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | LTCC000884 | LTCControl | 639-2 | LTC Control Insp | All Connections OK? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | LTCC000884 | LTCControl | 639-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | LTCC000884 | LTCControl | 639-2 | LTC Control Insp | General Comments | | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | LTCC000884 | LTCControl | 639-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | LTCC000884 | LTCControl | 639-2 | LTC Control Insp | LTC Output Voltage Level | 123 | VAC |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | LTCC000884 | LTCControl | 639-2 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | LTCC000884 | LTCControl | 639-2 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | LTCMechanism | 639-2 | LTC Counter Readings | LTC As Left Counter | 79796 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | LTCMechanism | 639-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | LTCC000884 | LTCControl | 639-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | LTCMechanism | 639-2 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | LTCMechanism | 639-2 | LTC Counter Readings | LTC Max Tap Position | 9R | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | LTCMechanism | 639-2 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Readings | 9 Month Operations | 2 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | LTCMechanism | 639-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | LTCMechanism | 639-2 | LTC Counter Readings | LTC Operations Since Last Insp | 557 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | LTCMechanism | 639-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | LTCMechanism | 639-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | LTCC000586 | LTCControl | 833-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | LTCC000586 | LTCControl | 833-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | LTCC000586 | LTCControl | 833-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Readings | 9 Month Operations | 3 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Readings | Accumulated Fault Duty A Ph V | .47 | % |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Readings | Accumulated Fault Duty B Ph V | .47 | % |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Readings | Accumulated Fault Duty C Ph V | .47 | % |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Readings | Amps A Ø | 143 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Readings | Amps B Ø | 181 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Readings | Amps C Ø | 60.0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Readings | Amps B Ø | 54.0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Readings | Amps A Ø | 57.0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Readings | 9 Month Operations | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | LTCMechanism | 639-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | LTCMechanism | 639-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | LTCMechanism | 639-2 | LTC Counter Readings | General Comments | | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Readings | General Comments | | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | LTCMechanism | 639-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Readings | Operations Counter AF | 182 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Readings | Operations Counter AL | 182 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | LTCC000586 | LTCControl | 833-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | LTCC000586 | LTCControl | 833-1 | LTC Control Insp | LTC Output Voltage Level | 122.9 | VAC |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | LTCC000586 | LTCControl | 833-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | LTCC000586 | LTCControl | 833-1 | LTC Control Insp | General Comments | | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | LTCC000586 | LTCControl | 833-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Readings | Operations Counter AF | 153 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Readings | Operations Counter AL | 153 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Readings | Operations This Read Vac | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Readings | Switching Operations | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Readings | Amps C Ø | 132 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Readings | General Comments | | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Readings | Operations Counter AF | 180 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Readings | Operations Counter AL | 180 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Readings | Operations This Read Vac | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Readings | Switching Operations | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001158 | BreakerVacuum | 639-2515 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Readings | Amps A Ø | 164.0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Readings | Amps B Ø | 133.0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 65.00 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.5660 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001793 | BreakerVacuum | 829-2320 | VCB Readings | Amps C Ø | 147.0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Readings | Operations Counter AL | 182 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Readings | Operations Counter AF | 182 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Readings | General Comments | | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Readings | Fault Operations Ground | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Readings | General Comments | | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Readings | Amps C Ø | 330.0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Readings | Amps B Ø | 356.0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Readings | Amps A Ø | 323.0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Readings | 9 Month Operations | 6 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Readings | 9 Month Operations | 2 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Readings | Amps A Ø | 61.0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Readings | Amps B Ø | 94.0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Readings | Amps C Ø | 65.0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Readings | General Comments | | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Readings | Operations Counter AF | 186 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Readings | Operations Counter AL | 186 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Readings | Operations This Read Vac | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Readings | Switching Operations | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Readings | Switching Operations | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0056 | BreakerVacuum | 833-2 | VCB Readings | Operations This Read Vac | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Readings | Operations Counter AF | 176 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Readings | Operations Counter AL | 176 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Readings | Operations This Read Vac | 2 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Readings | Amps C Ø | 10.0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Readings | Amps B Ø | 10.0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Readings | Amps A Ø | 6.0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Readings | 9 Month Operations VCB New | 25 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Readings | 9 Month Operations | 25 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Readings | Switching Operations | 2 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Readings | Switching Operations | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Readings | 9 Month Operations | 1 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Readings | Operations This Read Vac | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Readings | Operations Counter AL | 166 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Readings | Operations Counter AF | 166 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Readings | General Comments | | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Readings | Amps A Ø | 40.0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Readings | Amps B Ø | 35.0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001792 | BreakerVacuum | 829-2318 | VCB Readings | Amps C Ø | 44.0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | BK001821 | BreakerVacuum | 545-2324 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Readings | General Comments | | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0099 | BreakerVacuum | 429-2154 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Readings | Switching Operations | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Readings | Operations This Read Vac | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Readings | Operations Counter AL | 375 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Readings | Operations Counter AF | 375 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Readings | General Comments | | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Readings | Operations Counter AF | 247 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Readings | Operations Counter AL | 247 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Readings | Operations This Read Vac | 2 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Readings | Switching Operations | 2 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0091 | BreakerVacuum | 545-2322 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Readings | Operations Counter AL | 263 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Readings | Operations Counter AF | 263 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Readings | General Comments | | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Readings | 9 Month Operations | 3 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Readings | Amps A Ø | 70.0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Readings | Amps B Ø | 66.0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Readings | Amps C Ø | 82.0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Readings | Switching Operations | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Patrol Inspection | SF6 Pressure Pole 3 | 82 | psi |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Patrol Inspection | SF6 Pressure Pole 2 | 82 | psi |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Patrol Inspection | SF6 Pressure Pole 1 | 80 | psi |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Readings | Amps A Ø | 600.0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Readings | 9 Month Operations | 5 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Readings | General Comments | | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | LTCC000158 | LTCControl | 833-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | FE000451 | Fence | 829-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | FE000451 | Fence | 829-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | FE000451 | Fence | 829-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Readings | Operations Counter AF | 193 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Readings | Operations Counter AL | 193 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Readings | Switching Operations | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BAT001210 | Battery | 639-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BAT001210 | Battery | 639-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BAT001210 | Battery | 639-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 30.2 | VDC |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BAT001210 | Battery | 639-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 21.8 | VDC |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BAT001210 | Battery | 639-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BAT001210 | Battery | 639-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BAT001210 | Battery | 639-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BAT001210 | Battery | 639-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #'s |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BAT001210 | Battery | 639-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BAT001210 | Battery | 639-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BAT001210 | Battery | 639-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BAT001210 | Battery | 639-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BAT001210 | Battery | 639-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 74 | °F |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BAT001210 | Battery | 639-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Readings | Switching Operations | 1 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Readings | Operations This Read Vac | 1 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Readings | General Comments | | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Readings | Operations Counter AF | 224 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Readings | Operations Counter AL | 224 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Readings | Operations This Read Vac | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Readings | Switching Operations | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | FE000451 | Fence | 829-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | FE000451 | Fence | 829-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | FE000451 | Fence | 829-Fence | Fence Patrol Inspection | General Comments | | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | FE000451 | Fence | 829-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | CX0122 | RecloserHydraulic | 729-2309 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | CX0122 | RecloserHydraulic | 729-2309 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | FE000451 | Fence | 829-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | CX0122 | RecloserHydraulic | 729-2309 | Recloser Hydraulic Patrol Inspection | Operations Counter | 0 | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | CX0122 | RecloserHydraulic | 729-2309 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | CX0122 | RecloserHydraulic | 729-2309 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | CX0122 | RecloserHydraulic | 729-2309 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | CX0122 | RecloserHydraulic | 729-2309 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | CX0122 | RecloserHydraulic | 729-2309 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | CX0122 | RecloserHydraulic | 729-2309 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 199 | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | CX0122 | RecloserHydraulic | 729-2309 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | CX0122 | RecloserHydraulic | 729-2309 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | CX0122 | RecloserHydraulic | 729-2309 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 149 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | FE000451 | Fence | 829-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | CX0122 | RecloserHydraulic | 729-2309 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 30.0 | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | CX0122 | RecloserHydraulic | 729-2309 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 30.0 | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | CX0122 | RecloserHydraulic | 729-2309 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 30.0 | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | CX0122 | RecloserHydraulic | 729-2309 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 149 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | FE000451 | Fence | 829-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | FE000451 | Fence | 829-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | FE000451 | Fence | 829-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | FE000451 | Fence | 829-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | FE000451 | Fence | 829-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | FE000451 | Fence | 829-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | FE000451 | Fence | 829-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Readings | Amps C Ø | 44.0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Readings | Amps B Ø | 50.0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Readings | Amps A Ø | 44.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Readings | Operations This Read SF6 | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Readings | Operations Counter AL | 17 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Readings | Operations Counter AF | 17 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0098 | BreakerVacuum | 429-2162 | VCB Readings | 9 Month Operations | 1 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | LTCC000158 | LTCControl | 833-2 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | LTCC000158 | LTCControl | 833-2 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | LTCC000158 | LTCControl | 833-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | LTCC000158 | LTCControl | 833-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | LTCC000158 | LTCControl | 833-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Patrol Inspection | General Comments | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Readings | General Comments | | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Readings | Fault Operations | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Patrol Inspection | Ambient Temperature | 70 | °F |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000983 | BreakerSF6 | 461-708 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 13:49 | Distribution | Richmond East Quarterly Inspection | BK001795 | BreakerVacuum | 829-2319 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | LTCC000158 | LTCControl | 833-2 | LTC Control Insp | All Connections OK? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | LTCC000158 | LTCControl | 833-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | LTCC000158 | LTCControl | 833-2 | LTC Control Insp | General Comments | | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Readings | General Comments | | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Readings | General Comments | | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1647.36 | kw |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | B0264 | NonLTC | 729-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .6864 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | LTCC000586 | LTCControl | 833-1 | LTC Control Insp | All Connections OK? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | LTCMechanism | 639-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0522 | LTCMechanism | 639-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Readings | 9 Month Operations | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Readings | Accumulated Fault Duty A Ph V | 1.2 | % |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Readings | Accumulated Fault Duty B Ph V | 1.2 | % |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Readings | Accumulated Fault Duty C Ph V | 1.2 | % |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Readings | Amps A Ø | 412 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Readings | Amps B Ø | 282 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Readings | Amps C Ø | 397 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | KB0088 | BreakerVacuum | 639-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Readings | 9 Month Operations | 9 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Readings | Amps C Ø | 448.0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Readings | Amps B Ø | 447.0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Readings | Amps A Ø | 433.0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Readings | 9 Month Operations | 1 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Readings | Switching Operations | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Readings | Switching Operations | 1 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Readings | Operations This Read Vac | 1 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Readings | Operations Counter AL | 196 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Readings | Operations Counter AF | 196 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Readings | General Comments | | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Readings | Amps C Ø | 595.0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000545 | BreakerVacuum | 871-2163 | VCB Readings | Amps B Ø | 594.0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Readings | Operations Counter AF | 203 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Readings | Operations Counter AL | 203 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KB0057 | BreakerVacuum | 833-BT1-2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Readings | Switching Operations | 1 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Readings | Operations This Read Vac | 1 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Readings | Operations Counter AL | 181 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Readings | Operations Counter AF | 181 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Readings | General Comments | | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Readings | General Comments | | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Readings | LTC Totalizer Reading | 7516.80 | kw |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Readings | Oil Temp Max | 65 | °C |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Readings | Oil Temp Present | 60 | °C |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | C0390 | WithLTC | 871-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | BK000546 | BreakerVacuum | 871-2317 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Readings | General Comments | | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | YD000884 | Yard | 461-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | YD000884 | Yard | 461-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | YD000884 | Yard | 461-Yard | Yard Patrol Inspection | Ambient Temp | 70 | °F |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Readings | 9 Month Operations | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | FE000528 | Fence | 429-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | FE000528 | Fence | 429-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | FE000528 | Fence | 429-Fence | Fence Patrol Inspection | General Comments | | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | FE000528 | Fence | 429-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | FE000528 | Fence | 429-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Readings | Amps A Ø | 200 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Readings | Amps B Ø | 224 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Readings | Amps C Ø | 160 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | LTCC000570 | LTCControl | 429-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Readings | Winding Temp Present | 45 | °C |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | LTCC000570 | LTCControl | 429-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | FE000528 | Fence | 429-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | FE000528 | Fence | 429-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | FE000528 | Fence | 429-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | FE000528 | Fence | 429-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | FE000528 | Fence | 429-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | FE000528 | Fence | 429-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | FE000528 | Fence | 429-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | FE000528 | Fence | 429-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | FE000528 | Fence | 429-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | FE000528 | Fence | 429-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Readings | Amps C Ø | 56 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Readings | Amps B Ø | 53 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Readings | Amps A Ø | 45 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Readings | 9 Month Operations | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Readings | Operations This Read Vac | 5 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Readings | Switching Operations | 5 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | YD000884 | Yard | 461-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | YD000884 | Yard | 461-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | YD000884 | Yard | 461-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | YD000884 | Yard | 461-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | YD000884 | Yard | 461-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | YD000884 | Yard | 461-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | YD000884 | Yard | 461-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | YD000884 | Yard | 461-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | YD000884 | Yard | 461-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | YD000884 | Yard | 461-Yard | Yard Patrol Inspection | General Comments | | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | YD000884 | Yard | 461-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | YD000884 | Yard | 461-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | YD000884 | Yard | 461-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Readings | Switching Operations | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Readings | Operations This Read Vac | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Readings | Operations Counter AL | 195 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Readings | Operations Counter AF | 195 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | YD000884 | Yard | 461-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | YD000884 | Yard | 461-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | YD000884 | Yard | 461-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | YD000884 | Yard | 461-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Readings | LTC Totalizer Reading | 14112 | kw |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Readings | General Comments | | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | FE000528 | Fence | 429-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Readings | 9 Month Operations | 11 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Readings | Amps A Ø | 140.0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Readings | Amps B Ø | 137.0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Readings | Amps C Ø | 125.0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | LTCC000570 | LTCControl | 429-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | LTCC000570 | LTCControl | 429-1 | LTC Control Insp | LTC Output Voltage Level | 123.3 | VAC |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | LTCC000570 | LTCControl | 429-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | LTCC000570 | LTCControl | 429-1 | LTC Control Insp | General Comments | | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | LTCC000570 | LTCControl | 429-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | LTCC000570 | LTCControl | 429-1 | LTC Control Insp | All Connections OK? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Readings | Winding Temp Max | 45 | °C |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Readings | Totalizer Meter Reading | .784 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Readings | 9 Month Operations | 0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Readings | Amps A Ø | 0.0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Readings | Amps B Ø | 0.0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Readings | Amps C Ø | 0.0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Readings | 9 Month Operations | 1 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Readings | Accumulated Fault Duty A Ph V | .5 | % |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Readings | Accumulated Fault Duty B Ph V | .5 | % |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Readings | Accumulated Fault Duty C Ph V | 1 | % |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Readings | Amps A Ø | 200 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Readings | Amps B Ø | 196 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Readings | Amps C Ø | 187 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Readings | General Comments | | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Readings | Amps C Ø | 149.0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Readings | Amps B Ø | 139.0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Readings | Amps A Ø | 149.0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Readings | Switching Operations | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Readings | Operations Counter AL | 217 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Readings | Operations Counter AF | 217 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Readings | General Comments | | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Readings | Operations Counter AF | 247 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Readings | Switching Operations | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Readings | Operations This Read Vac | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Readings | Operations Counter AL | 199 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Readings | Operations Counter AF | 199 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Readings | 9 Month Operations | 5 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Readings | General Comments | | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Readings | Amps A Ø | 162.0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Readings | Amps B Ø | 174.0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Readings | Amps C Ø | 179.0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | ST000513 | Structure | 729-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | ST000513 | Structure | 729-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | X0052 | RecloserHydraulic | 729-2310 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 179 | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | X0052 | RecloserHydraulic | 729-2310 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 20.0 | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | X0052 | RecloserHydraulic | 729-2310 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 20.0 | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | X0052 | RecloserHydraulic | 729-2310 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 20.0 | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | X0052 | RecloserHydraulic | 729-2310 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 166 | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | X0052 | RecloserHydraulic | 729-2310 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | X0052 | RecloserHydraulic | 729-2310 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | X0052 | RecloserHydraulic | 729-2310 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 192 | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | X0052 | RecloserHydraulic | 729-2310 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | X0052 | RecloserHydraulic | 729-2310 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | X0052 | RecloserHydraulic | 729-2310 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | X0052 | RecloserHydraulic | 729-2310 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | X0052 | RecloserHydraulic | 729-2310 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | X0052 | RecloserHydraulic | 729-2310 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | X0052 | RecloserHydraulic | 729-2310 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Readings | General Comments | | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | ST000513 | Structure | 729-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | ST000513 | Structure | 729-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | ST000513 | Structure | 729-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | ST000513 | Structure | 729-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | ST000513 | Structure | 729-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | ST000513 | Structure | 729-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | YD000452 | Yard | 545-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 14:30 | Distribution | Richmond 2 Quarterly Inspection | KB0097 | BreakerVacuum | 429-2313 | VCB Readings | Operations Counter AL | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000987 | BreakerVacuum | 461-2171 | VCB Readings | 9 Month Operations | 0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | ST000513 | Structure | 729-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | ST000513 | Structure | 729-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | ST000513 | Structure | 729-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | ST000513 | Structure | 729-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | ST000513 | Structure | 729-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | ST000513 | Structure | 729-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | ST000513 | Structure | 729-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | ST000513 | Structure | 729-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | ST000513 | Structure | 729-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | ST000513 | Structure | 729-Structure | Structure Patrol Inspection | General Comments | | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | ST000513 | Structure | 729-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | ST000513 | Structure | 729-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | ST000513 | Structure | 729-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/23/2023 9:00 | Distribution | Paint Lick Quarterly Inspection | ST000513 | Structure | 729-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Readings | Amps C Ø | 287.0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Readings | Amps B Ø | 284.0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Readings | Amps A Ø | 264.0 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Readings | 9 Month Operations VCB New | 14 | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | K0174 | BreakerVacuum | 545-1 | VCB Readings | 9 Month Operations | 14 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Readings | Switching Operations | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Readings | Operations This Read Vac | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Readings | Operations Counter AL | 178 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Readings | Operations Counter AF | 178 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001152 | BreakerVacuum | 639-2518 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BCH001305 | Charger | 639-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BCH001305 | Charger | 639-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.7 | amps |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BCH001305 | Charger | 639-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BCH001305 | Charger | 639-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BCH001305 | Charger | 639-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BCH001305 | Charger | 639-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Readings | 9 Month Operations | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Readings | Switching Operations | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | LTCMechanism | 833-2 | LTC Counter Readings | LTC Operations Since Last Insp | 720 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | LTCMechanism | 833-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 30 | °C |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | LTCMechanism | 833-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 52 | °C |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | LTCMechanism | 833-2 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | LTCMechanism | 833-2 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | LTCMechanism | 833-2 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | LTCMechanism | 833-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | LTCMechanism | 833-2 | LTC Counter Readings | LTC As Left Counter | 54030 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | LTCMechanism | 833-2 | LTC Counter Readings | LTC As Found Counter | 54030 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | LTCMechanism | 833-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | LTCMechanism | 833-2 | LTC Counter Readings | General Comments | | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | LTCMechanism | 833-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | LTCMechanism | 833-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Readings | 9 Month Operations | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Readings | General Comments | | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Readings | Operations Counter AF | 227 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Readings | Amps A Ø | 136 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Readings | Amps A Ø | 58.0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Readings | Amps B Ø | 57.0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Readings | Amps C Ø | 56.0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Readings | LTC Totalizer Reading | 14277.60 | kw |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Readings | General Comments | | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BCH001305 | Charger | 639-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Readings | General Comments | | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BCH001305 | Charger | 639-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0 | millivolts |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | YD000452 | Yard | 545-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | YD000452 | Yard | 545-Yard | Yard Patrol Inspection | General Comments | | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | YD000452 | Yard | 545-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | YD000452 | Yard | 545-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/23/2023 9:47 | Distribution | Richmond South Quarterly Inspection | YD000452 | Yard | 545-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Readings | Operations Counter AF | 194 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Readings | Operations Counter AL | 194 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Readings | Operations This Read Vac | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Readings | Totalizer Meter Reading | .7932 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Readings | Switching Operations | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | K0200 | BreakerVacuum | 639-2517 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Readings | 9 Month Operations | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Readings | Amps A Ø | 351.0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Readings | Amps B Ø | 344.0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Readings | Amps C Ø | 350.0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Readings | General Comments | | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | LTCMechanism | 833-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | LTCMechanism | 833-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | LTCMechanism | 833-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | KT0031 | LTCMechanism | 833-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Readings | Operations Counter AF | 162 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Readings | Operations Counter AL | 162 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | BK002055 | BreakerVacuum | 833-1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Readings | Switching Operations | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Readings | General Comments | | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Patrol Inspection | General Comments | | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | K0194 | BreakerVacuum | 833-2109 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Readings | Unknown Operations | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Readings | Switching Operations | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Readings | Operations This Read Vac | 0 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Readings | Operations Counter AL | 323 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Readings | Operations Counter AF | 323 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | CB0243 | BreakerVacuum | 639-2 | VCB Readings | Operations Counter AL | 227 | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/23/2023 11:01 | Distribution | Richmond 4 Quarterly Inspection | K0087 | BreakerVacuum | 871-2315 | VCB Readings | Maintenance Operations | 0 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | C0467 | WithLTC | 639-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Readings | Amps C Ø | 179 | |
| 2/23/2023 14:17 | Distribution | Lawrenceburg Quarterly Inspection | BK001157 | BreakerVacuum | 639-2516 | VCB Readings | Amps B Ø | 134 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Readings | Follow-up Action Required? | n | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Readings | Fault Operations Ground | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/23/2023 11:52 | Distribution | Richmond North Quarterly Inspection | BK000986 | BreakerVacuum | 461-2170 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/23/2023 10:28 | Distribution | Richmond 3 Quarterly Inspection | S0068 | WithLTC | 833-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Readings | Follow-up Action Required? | n | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Patrol Inspection | General Comments | | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Readings | General Comments | | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Readings | Amps A Ø | 47.0 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Readings | Amps B Ø | 49.0 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Readings | Amps C Ø | 53.0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BCH001405 | Charger | 818-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.0 | VDC |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BCH001405 | Charger | 818-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.0 | VDC |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BCH001405 | Charger | 818-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BAT001470 | Battery | 818-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Readings | Maintenance Operations | 0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BAT001470 | Battery | 818-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BAT001470 | Battery | 818-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Readings | Operations Counter AL | 280 | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | X0125 | RecloserElectronic | 687-2224 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | X0125 | RecloserElectronic | 687-2224 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | BAT000632 | Battery | 432-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | BAT000632 | Battery | 432-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | BAT000632 | Battery | 432-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Readings | Operations Counter AF | 280 | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | X0125 | RecloserElectronic | 687-2224 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | X0125 | RecloserElectronic | 687-2224 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | X0125 | RecloserElectronic | 687-2224 | Recloser Electronic Patrol Inspection | Operations Counter | 4 | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | X0125 | RecloserElectronic | 687-2224 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | FE000500 | Fence | 432-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | X0125 | RecloserElectronic | 687-2224 | Recloser Electronic Patrol Inspection | Amps A Ø | 67.0 | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | X0125 | RecloserElectronic | 687-2224 | Recloser Electronic Patrol Inspection | Amps B Ø | 51.0 | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | X0125 | RecloserElectronic | 687-2224 | Recloser Electronic Patrol Inspection | Amps C Ø | 47.0 | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | X0125 | RecloserElectronic | 687-2224 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | X0125 | RecloserElectronic | 687-2224 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | FE000500 | Fence | 432-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | X0125 | RecloserElectronic | 687-2224 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | FE000500 | Fence | 432-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | FE000500 | Fence | 432-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | FE000500 | Fence | 432-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | X0125 | RecloserElectronic | 687-2224 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | X0125 | RecloserElectronic | 687-2224 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | X0125 | RecloserElectronic | 687-2224 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | X0125 | RecloserElectronic | 687-2224 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | FE000500 | Fence | 432-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BAT001470 | Battery | 818-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | X0125 | RecloserElectronic | 687-2224 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | X0125 | RecloserElectronic | 687-2224 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | X0125 | RecloserElectronic | 687-2224 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | LTCC000355 | LTCControl | 687-1 | LTC Control Insp | All Connections OK? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | LTCC000355 | LTCControl | 687-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | LTCC000355 | LTCControl | 687-1 | LTC Control Insp | General Comments | | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | LTCC000355 | LTCControl | 687-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Readings | 9 Month Operations | 1 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BAT001470 | Battery | 818-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | X0125 | RecloserElectronic | 687-2224 | Recloser Electronic Patrol Inspection | General Comments | Control replaced counter is a 4 ops on new counter | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BAT001470 | Battery | 818-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BAT001470 | Battery | 818-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BAT001470 | Battery | 818-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BAT001470 | Battery | 818-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BAT001470 | Battery | 818-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BAT001470 | Battery | 818-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BAT001470 | Battery | 818-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BAT001470 | Battery | 818-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Readings | Fault Operations Ground | 0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BAT001470 | Battery | 818-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | LTCC000130 | LTCControl | 432-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | LTCC000130 | LTCControl | 432-1 | LTC Control Insp | LTC Output Voltage Level | 123.3 | VAC |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | LTCC000130 | LTCControl | 432-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | LTCC000130 | LTCControl | 432-1 | LTC Control Insp | General Comments | | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | LTCC000130 | LTCControl | 432-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | LTCC000130 | LTCControl | 432-1 | LTC Control Insp | All Connections OK? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0109 | RecloserElectronic | 687-2311 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0109 | RecloserElectronic | 687-2311 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0109 | RecloserElectronic | 687-2311 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0109 | RecloserElectronic | 687-2311 | Recloser Electronic Patrol Inspection | Operations Counter | 1802 | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0109 | RecloserElectronic | 687-2311 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0109 | RecloserElectronic | 687-2311 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0109 | RecloserElectronic | 687-2311 | Recloser Electronic Patrol Inspection | General Comments | | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | YD000557 | Yard | 651-Yard | Yard Patrol Inspection | Ambient Temp | 79 | °F |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0110 | RecloserElectronic | 687-2312 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0109 | RecloserElectronic | 687-2311 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0109 | RecloserElectronic | 687-2311 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0109 | RecloserElectronic | 687-2311 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0109 | RecloserElectronic | 687-2311 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0109 | RecloserElectronic | 687-2311 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0110 | RecloserElectronic | 687-2312 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0110 | RecloserElectronic | 687-2312 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0110 | RecloserElectronic | 687-2312 | Recloser Electronic Patrol Inspection | Operations Counter | 2007 | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0110 | RecloserElectronic | 687-2312 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0110 | RecloserElectronic | 687-2312 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0110 | RecloserElectronic | 687-2312 | Recloser Electronic Patrol Inspection | General Comments | | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0110 | RecloserElectronic | 687-2312 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0110 | RecloserElectronic | 687-2312 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0110 | RecloserElectronic | 687-2312 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0110 | RecloserElectronic | 687-2312 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0110 | RecloserElectronic | 687-2312 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0110 | RecloserElectronic | 687-2312 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0110 | RecloserElectronic | 687-2312 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0110 | RecloserElectronic | 687-2312 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0110 | RecloserElectronic | 687-2312 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0110 | RecloserElectronic | 687-2312 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0110 | RecloserElectronic | 687-2312 | Recloser Electronic Patrol Inspection | Amps C Ø | 60.0 | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0110 | RecloserElectronic | 687-2312 | Recloser Electronic Patrol Inspection | Amps B Ø | 60.0 | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0110 | RecloserElectronic | 687-2312 | Recloser Electronic Patrol Inspection | Amps A Ø | 60.0 | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0109 | RecloserElectronic | 687-2311 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0109 | RecloserElectronic | 687-2311 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0109 | RecloserElectronic | 687-2311 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0109 | RecloserElectronic | 687-2311 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0109 | RecloserElectronic | 687-2311 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0109 | RecloserElectronic | 687-2311 | Recloser Electronic Patrol Inspection | Amps A Ø | 10.0 | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0109 | RecloserElectronic | 687-2311 | Recloser Electronic Patrol Inspection | Amps B Ø | 10.0 | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | CX0109 | RecloserElectronic | 687-2311 | Recloser Electronic Patrol Inspection | Amps C Ø | 10.0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BCH001405 | Charger | 818-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .7 | amps |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BCH001405 | Charger | 818-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BCH001405 | Charger | 818-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BCH001405 | Charger | 818-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BCH001405 | Charger | 818-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Readings | Operations This Read Vac | 0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Readings | Switching Operations | 0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Readings | Unknown Operations | 0 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | BAT000632 | Battery | 432-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | BAT000632 | Battery | 432-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | BAT000632 | Battery | 432-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | BAT000632 | Battery | 432-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | BAT000632 | Battery | 432-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | BAT000632 | Battery | 432-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | BAT000632 | Battery | 432-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | BAT000632 | Battery | 432-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | BAT000632 | Battery | 432-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | YD000557 | Yard | 651-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | YD000557 | Yard | 651-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | YD000557 | Yard | 651-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | BAT000632 | Battery | 432-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | BAT000632 | Battery | 432-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | BAT000632 | Battery | 432-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | BCH000567 | Charger | 432-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | ST000509 | Structure | 432-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | FE000500 | Fence | 432-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | FE000500 | Fence | 432-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | FE000500 | Fence | 432-Fence | Fence Patrol Inspection | General Comments | | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | FE000500 | Fence | 432-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | FE000500 | Fence | 432-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | FE000500 | Fence | 432-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | FE000500 | Fence | 432-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | FE000500 | Fence | 432-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | FE000500 | Fence | 432-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | FE000500 | Fence | 432-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | BCH000567 | Charger | 432-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | BCH000567 | Charger | 432-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | BCH000567 | Charger | 432-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.0 | amps |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | BCH000567 | Charger | 432-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | BCH000567 | Charger | 432-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | YD000557 | Yard | 651-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | YD000557 | Yard | 651-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | YD000557 | Yard | 651-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | LTCC000130 | LTCControl | 432-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | LTCC000130 | LTCControl | 432-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Readings | Switching Operations | 0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Readings | Unknown Operations | 0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Readings | Fault Operations | 0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Readings | Follow-up Action Required? | n | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | LTCC000817 | LTCControl | 818-1 | LTC Control Insp | All Connections OK? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | LTCC000817 | LTCControl | 818-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | LTCC000817 | LTCControl | 818-1 | LTC Control Insp | General Comments | | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | LTCC000817 | LTCControl | 818-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | LTCC000817 | LTCControl | 818-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | LTCC000817 | LTCControl | 818-1 | LTC Control Insp | VRR Base Voltage AF | 123.0 | VAC |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | LTCC000817 | LTCControl | 818-1 | LTC Control Insp | VRR Base Voltage AL | 123.0 | VAC |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Readings | Totalizer Meter Reading | .3060 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | ST000509 | Structure | 432-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | ST000509 | Structure | 432-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | ST000509 | Structure | 432-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | ST000509 | Structure | 432-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | ST000509 | Structure | 432-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | ST000509 | Structure | 432-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | ST000509 | Structure | 432-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | ST000509 | Structure | 432-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | ST000509 | Structure | 432-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | ST000509 | Structure | 432-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | ST000509 | Structure | 432-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | ST000509 | Structure | 432-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | ST000509 | Structure | 432-Structure | Structure Patrol Inspection | General Comments | | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | ST000509 | Structure | 432-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Readings | LTC Totalizer Reading | 2937.60 | kw |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Readings | General Comments | | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | ST000509 | Structure | 432-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | ST000509 | Structure | 432-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | ST000509 | Structure | 432-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | ST000509 | Structure | 432-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | ST000509 | Structure | 432-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | ST000509 | Structure | 432-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | ST000509 | Structure | 432-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | LTCC000817 | LTCControl | 818-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Patrol Inspection | Foundation Condition | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Patrol Inspection | General Comments | | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Readings | General Comments | | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Patrol Inspection | Grounds in Place? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | ST000335 | Structure | 687-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BCH001378 | Charger | 895-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BCH001378 | Charger | 895-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BCH001378 | Charger | 895-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BCH001378 | Charger | 895-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BCH001378 | Charger | 895-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .2 | amps |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BCH001378 | Charger | 895-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BCH001378 | Charger | 895-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BCH001378 | Charger | 895-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Readings | 9 Months Operations OCB New | 0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Patrol Inspection | Air Compressor Belt Condition | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Patrol Inspection | Air Compressor Oil Status | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Patrol Inspection | Air Leaks | None | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Patrol Inspection | Air Pressure OK? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | CH000429 | ControlHouse | 818-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | CH000429 | ControlHouse | 818-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | CH000429 | ControlHouse | 818-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | CH000429 | ControlHouse | 818-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | CH000429 | ControlHouse | 818-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | CH000429 | ControlHouse | 818-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | CH000429 | ControlHouse | 818-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | CH000429 | ControlHouse | 818-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | CH000429 | ControlHouse | 818-Control House | Control House Patrol Inspection | Evidence of Insects | Yes_needs_sprayed | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | CH000429 | ControlHouse | 818-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | CH000429 | ControlHouse | 818-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | CH000429 | ControlHouse | 818-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | CH000429 | ControlHouse | 818-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | CH000429 | ControlHouse | 818-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | CH000429 | ControlHouse | 818-Control House | Control House Patrol Inspection | General Comments | | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | CH000429 | ControlHouse | 818-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | CH000429 | ControlHouse | 818-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | CH000429 | ControlHouse | 818-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | CH000429 | ControlHouse | 818-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | CH000429 | ControlHouse | 818-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | CH000429 | ControlHouse | 818-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | CH000429 | ControlHouse | 818-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Patrol Inspection | Air Tank Bleed (> 40°F)? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Patrol Inspection | AirCompressor Heater Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Patrol Inspection | Bushing Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Readings | General Comments | | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Readings | LTC Totalizer Reading | 3663.36 | kw |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Readings | Totalizer Meter Reading | .3816 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | WithLTC | 895-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Readings | Operations Counter AF | 239 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Readings | Operations Counter AL | 239 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Readings | Operations This Read Vac | 0 | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | YD000331 | Yard | 687-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | YD000331 | Yard | 687-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | YD000331 | Yard | 687-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | YD000331 | Yard | 687-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | YD000331 | Yard | 687-Yard | Yard Patrol Inspection | Ambient Temp | 70 | °F |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Patrol Inspection | Pop-off Valve Tested Date | 2023-02-22 00:00:00.000000 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Patrol Inspection | Pressure Vessel Condition | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Readings | Switching Operations | 0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Patrol Inspection | Tank Leaks | None | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Readings | Unknown Operations | 0 | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | LTCC000355 | LTCControl | 687-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | LTCC000355 | LTCControl | 687-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | LTCC000355 | LTCControl | 687-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Readings | Maintenance Operations | 0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Readings | General Comments | | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Patrol Inspection | General Comments | | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Readings | Follow-up Action Required? | n | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Readings | Fault Operations Ground | 0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | LTCC000355 | LTCControl | 687-1 | LTC Control Insp | LTC Output Voltage Level | 124.6 | VAC |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Readings | Unknown Operations | 0 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Readings | Switching Operations | 1 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Readings | Operations This Read Vac | 1 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Readings | Operations Counter AL | 227 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Readings | Operations Counter AF | 226 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Readings | Maintenance Operations | 0 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Readings | Amps C Ø | 0.0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Readings | Amps B Ø | 0.0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Readings | Amps A Ø | 0.0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | WB0139 | BreakerVacuum | 895-0714 | VCB Readings | 9 Month Operations | 0 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Readings | General Comments | | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Patrol Inspection | General Comments | | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Readings | Follow-up Action Required? | n | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Readings | Fault Operations Ground | 0 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0069 | BreakerVacuum | 432-0624 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | ST000335 | Structure | 687-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | ST000335 | Structure | 687-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | ST000335 | Structure | 687-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | ST000335 | Structure | 687-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | ST000335 | Structure | 687-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | ST000335 | Structure | 687-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | ST000335 | Structure | 687-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | ST000335 | Structure | 687-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Readings | LTC Totalizer Reading | 1823.04 | kw |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | ST000335 | Structure | 687-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | ST000335 | Structure | 687-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | ST000335 | Structure | 687-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | ST000335 | Structure | 687-Structure | Structure Patrol Inspection | General Comments | | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | ST000335 | Structure | 687-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | ST000335 | Structure | 687-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Readings | Maintenance Operations | 0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Readings | Number of Ops last 9 Months | 0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Readings | Operations Counter AF | 340 | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | ST000335 | Structure | 687-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | ST000335 | Structure | 687-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | ST000335 | Structure | 687-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | ST000335 | Structure | 687-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | ST000335 | Structure | 687-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | WithLTC | 818-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Readings | Oil Temp Max | 32 | °C |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | ST000335 | Structure | 687-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | ST000335 | Structure | 687-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | YD000331 | Yard | 687-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | YD000331 | Yard | 687-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | YD000331 | Yard | 687-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Readings | Totalizer Meter Reading | .2532 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | WithLTC | 432-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | YD000331 | Yard | 687-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | YD000331 | Yard | 687-Yard | Yard Patrol Inspection | General Comments | | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | YD000331 | Yard | 687-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | YD000331 | Yard | 687-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | YD000331 | Yard | 687-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | YD000331 | Yard | 687-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Readings | Operations Counter AL | 340 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | TB0589 | BreakerOil | 818-708 | OCB Readings | Operations This Read Oil | 0 | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | YD000331 | Yard | 687-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | FE000326 | Fence | 687-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | FE000326 | Fence | 687-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | FE000326 | Fence | 687-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | ST000561 | Structure | 651-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | ST000561 | Structure | 651-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | ST000382 | Structure | 895-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | ST000382 | Structure | 895-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | ST000382 | Structure | 895-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | ST000382 | Structure | 895-Structure | Structure Patrol Inspection | General Comments | | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | ST000382 | Structure | 895-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | ST000382 | Structure | 895-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | YD000381 | Yard | 818-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | YD000381 | Yard | 818-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | ST000382 | Structure | 895-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | ST000382 | Structure | 895-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | ST000382 | Structure | 895-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | ST000382 | Structure | 895-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | ST000382 | Structure | 895-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | ST000382 | Structure | 895-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | ST000382 | Structure | 895-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | ST000382 | Structure | 895-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Readings | Unknown Operations | 0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Readings | Switching Operations | 0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Readings | Operations This Read Vac | 0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Readings | Operations Counter AL | 176 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Readings | Operations Counter AF | 176 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Readings | Maintenance Operations | 0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Readings | General Comments | | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Patrol Inspection | General Comments | | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Readings | Follow-up Action Required? | n | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Readings | Fault Operations Ground | 0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Readings | Amps C Ø | 70.0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Readings | Amps B Ø | 65.0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Readings | Amps A Ø | 70.0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001401 | BreakerVacuum | 818-0710 | VCB Readings | 9 Month Operations | 4 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | ST000382 | Structure | 895-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | LTCMechanism | 818-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | LTCMechanism | 818-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | LTCMechanism | 818-1 | LTC Counter Readings | LTC Operations Since Last Insp | 34 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | LTCMechanism | 818-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | -1.0 | psi |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | LTCMechanism | 818-1 | LTC Counter Readings | LTC Min Tap Position | Neutral | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | LTCMechanism | 818-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | LTCMechanism | 818-1 | LTC Counter Readings | LTC Current Tap Position | 3R | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | LTCMechanism | 818-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BAT001460 | Battery | 895-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BAT001460 | Battery | 895-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BAT001460 | Battery | 895-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BAT001460 | Battery | 895-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BAT001460 | Battery | 895-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BAT001460 | Battery | 895-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BAT001460 | Battery | 895-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BAT001460 | Battery | 895-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BAT001460 | Battery | 895-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Readings | Totalizer Meter Reading | .5478 | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 20.00 | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | YD000381 | Yard | 818-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | YD000381 | Yard | 818-Yard | Yard Patrol Inspection | General Comments | | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | YD000381 | Yard | 818-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | YD000557 | Yard | 651-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | YD000557 | Yard | 651-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | YD000557 | Yard | 651-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | FE000326 | Fence | 687-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | FE000326 | Fence | 687-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | FE000326 | Fence | 687-Fence | Fence Patrol Inspection | General Comments | | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | FE000326 | Fence | 687-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | FE000326 | Fence | 687-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | FE000326 | Fence | 687-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | FE000326 | Fence | 687-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | FE000326 | Fence | 687-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | FE000326 | Fence | 687-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | FE000326 | Fence | 687-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | FE000326 | Fence | 687-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | FE000326 | Fence | 687-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | FE000326 | Fence | 687-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | YD000557 | Yard | 651-Yard | Yard Patrol Inspection | General Comments | | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | YD000557 | Yard | 651-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | ST000561 | Structure | 651-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | ST000561 | Structure | 651-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | ST000561 | Structure | 651-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | ST000561 | Structure | 651-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | YD000381 | Yard | 818-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | YD000381 | Yard | 818-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | YD000381 | Yard | 818-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | YD000381 | Yard | 818-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | YD000381 | Yard | 818-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | YD000381 | Yard | 818-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | ST000561 | Structure | 651-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | ST000561 | Structure | 651-Structure | Structure Patrol Inspection | General Comments | | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | ST000561 | Structure | 651-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | ST000561 | Structure | 651-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Readings | Fault Operations Ground | 0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | ST000561 | Structure | 651-Structure | Structure Patrol Inspection | Platform/Walkway/Railing OK? | y | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | ST000561 | Structure | 651-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | ST000561 | Structure | 651-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | ST000561 | Structure | 651-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | ST000561 | Structure | 651-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Readings | Amps C Ø | 80.0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Readings | Amps B Ø | 80.0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Readings | Amps A Ø | 80.0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Readings | 9 Month Operations | 0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | LTCMechanism | 818-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | YD000378 | Yard | 895-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | ST000382 | Structure | 895-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | ST000382 | Structure | 895-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | ST000382 | Structure | 895-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | ST000382 | Structure | 895-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | ST000382 | Structure | 895-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | ST000382 | Structure | 895-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | LTCMechanism | 818-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0221 | NonLTC | 651-1 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | FE000372 | Fence | 895-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0221 | NonLTC | 651-1 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | FE000372 | Fence | 895-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | FE000372 | Fence | 895-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | FE000372 | Fence | 895-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | FE000372 | Fence | 895-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0221 | NonLTC | 651-1 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0221 | NonLTC | 651-1 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0221 | NonLTC | 651-1 B | NonLTC Transformer Readings | Oil Temp Max | 0 | °C |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0221 | NonLTC | 651-1 B | NonLTC Transformer Readings | Oil Temp Present | 0 | °C |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0221 | NonLTC | 651-1 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0221 | NonLTC | 651-1 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0221 | NonLTC | 651-1 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0221 | NonLTC | 651-1 B | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0221 | NonLTC | 651-1 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0221 | NonLTC | 651-1 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0221 | NonLTC | 651-1 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | FE000372 | Fence | 895-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | FE000372 | Fence | 895-Fence | Fence Patrol Inspection | General Comments | | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | FE000372 | Fence | 895-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | FE000372 | Fence | 895-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Readings | 9 Month Operations | 3 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Readings | Amps A Ø | 33.0 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Readings | Amps B Ø | 38.0 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Readings | Amps C Ø | 42.0 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | LTCMechanism | 432-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | LTCMechanism | 432-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | LTCMechanism | 432-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | LTCMechanism | 432-1 | LTC Counter Readings | LTC Operations Since Last Insp | 802 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | LTCMechanism | 432-1 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | LTCMechanism | 432-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | LTCMechanism | 432-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Readings | Maintenance Operations | 0 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Readings | General Comments | | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Patrol Inspection | General Comments | | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Readings | Follow-up Action Required? | n | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Readings | Fault Operations Ground | 0 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | LTCMechanism | 432-1 | LTC Counter Readings | LTC As Left Counter | 307454 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | LTCMechanism | 432-1 | LTC Counter Readings | LTC As Found Counter | 307454 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | LTCMechanism | 432-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | LTCMechanism | 432-1 | LTC Counter Readings | General Comments | | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | LTCMechanism | 432-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | C0448 | LTCMechanism | 432-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | FE000375 | Fence | 818-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | FE000375 | Fence | 818-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | FE000375 | Fence | 818-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | FE000375 | Fence | 818-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | FE000375 | Fence | 818-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | FE000375 | Fence | 818-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | FE000375 | Fence | 818-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | FE000375 | Fence | 818-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | ST000385 | Structure | 818-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BAT001460 | Battery | 895-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BAT001460 | Battery | 895-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BAT001460 | Battery | 895-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BAT001460 | Battery | 895-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | LTCMechanism | 818-1 | LTC Counter Readings | LTC As Left Counter | 4541 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | LTCMechanism | 818-1 | LTC Counter Readings | LTC As Found Counter | 4541 | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0222 | NonLTC | 651-1 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0222 | NonLTC | 651-1 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0222 | NonLTC | 651-1 C | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0222 | NonLTC | 651-1 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0222 | NonLTC | 651-1 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0222 | NonLTC | 651-1 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0222 | NonLTC | 651-1 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0222 | NonLTC | 651-1 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0222 | NonLTC | 651-1 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0222 | NonLTC | 651-1 C | NonLTC Transformer Readings | General Comments | no temp guages | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0222 | NonLTC | 651-1 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0222 | NonLTC | 651-1 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0222 | NonLTC | 651-1 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0222 | NonLTC | 651-1 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0222 | NonLTC | 651-1 C | NonLTC Transformer Readings | Oil Temp Max | 0 | °C |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0222 | NonLTC | 651-1 C | NonLTC Transformer Readings | Oil Temp Present | 0 | °C |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0222 | NonLTC | 651-1 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | YD000381 | Yard | 818-Yard | Yard Patrol Inspection | Ambient Temp | 68 | °F |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | FE000375 | Fence | 818-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Readings | Unknown Operations | 0 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Readings | Switching Operations | 1 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Readings | Operations This Read Vac | 1 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | FE000375 | Fence | 818-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | FE000375 | Fence | 818-Fence | Fence Patrol Inspection | General Comments | | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | FE000375 | Fence | 818-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | FE000375 | Fence | 818-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0222 | NonLTC | 651-1 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0222 | NonLTC | 651-1 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0222 | NonLTC | 651-1 C | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0222 | NonLTC | 651-1 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0222 | NonLTC | 651-1 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0222 | NonLTC | 651-1 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | FE000375 | Fence | 818-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | FE000375 | Fence | 818-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | FE000375 | Fence | 818-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | LTCC000234 | LTCControl | 895-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | LTCC000234 | LTCControl | 895-1 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | LTCC000234 | LTCControl | 895-1 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0221 | NonLTC | 651-1 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0221 | NonLTC | 651-1 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0221 | NonLTC | 651-1 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0221 | NonLTC | 651-1 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0221 | NonLTC | 651-1 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0221 | NonLTC | 651-1 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0221 | NonLTC | 651-1 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | LTCC000234 | LTCControl | 895-1 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | LTCC000234 | LTCControl | 895-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | LTCC000234 | LTCControl | 895-1 | LTC Control Insp | General Comments | | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | LTCC000234 | LTCControl | 895-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | LTCC000234 | LTCControl | 895-1 | LTC Control Insp | All Connections OK? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Readings | Operations Counter AL | 255 | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0221 | NonLTC | 651-1 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0221 | NonLTC | 651-1 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Readings | Operations Counter AF | 254 | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | KB0068 | BreakerVacuum | 432-0643 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | FE000372 | Fence | 895-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | FE000372 | Fence | 895-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | FE000372 | Fence | 895-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | FE000372 | Fence | 895-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | FE000372 | Fence | 895-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | FE000372 | Fence | 895-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | FE000372 | Fence | 895-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0221 | NonLTC | 651-1 B | NonLTC Transformer Readings | General Comments | | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | ST000382 | Structure | 895-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | ST000382 | Structure | 895-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | ST000382 | Structure | 895-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | LTCMechanism | 818-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | LTCMechanism | 818-1 | LTC Counter Readings | General Comments | | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | B0410 | LTCMechanism | 818-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Readings | 9 Month Operations | 0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Readings | Operations This Read Vac | 0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Readings | Operations Counter AL | 1590 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Readings | Operations Counter AF | 1590 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Readings | Maintenance Operations | 0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Readings | General Comments | | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Patrol Inspection | General Comments | | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | YD000378 | Yard | 895-Yard | Yard Patrol Inspection | Ambient Temp | 65 | °F |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | YD000378 | Yard | 895-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | YD000378 | Yard | 895-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | YD000378 | Yard | 895-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | LTCMechanism | 687-1 | LTC Counter Readings | LTC Operations Since Last Insp | 439 | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | LTCMechanism | 687-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 24 | °C |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | LTCMechanism | 687-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 29 | °C |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | LTCMechanism | 687-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | LTCMechanism | 687-1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | LTCMechanism | 687-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | LTCMechanism | 687-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | LTCMechanism | 687-1 | LTC Counter Readings | LTC As Left Counter | 72506 | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | LTCMechanism | 687-1 | LTC Counter Readings | LTC As Found Counter | 72506 | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | LTCMechanism | 687-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | LTCMechanism | 687-1 | LTC Counter Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | LTCMechanism | 687-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | LTCMechanism | 687-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Readings | Follow-up Action Required? | n | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | YD000378 | Yard | 895-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | YD000378 | Yard | 895-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | YD000378 | Yard | 895-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | YD000378 | Yard | 895-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | YD000378 | Yard | 895-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | ST000385 | Structure | 818-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | ST000385 | Structure | 818-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | ST000385 | Structure | 818-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | ST000385 | Structure | 818-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | YD000378 | Yard | 895-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | YD000378 | Yard | 895-Yard | Yard Patrol Inspection | General Comments | | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | YD000378 | Yard | 895-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | YD000378 | Yard | 895-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | YD000378 | Yard | 895-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0220 | NonLTC | 651-1 A | NonLTC Transformer Readings | Oil Temp Max | 0 | °C |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0220 | NonLTC | 651-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0220 | NonLTC | 651-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0220 | NonLTC | 651-1 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 22.98 | kw |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0220 | NonLTC | 651-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0220 | NonLTC | 651-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0220 | NonLTC | 651-1 A | NonLTC Transformer Readings | General Comments | | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0220 | NonLTC | 651-1 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0220 | NonLTC | 651-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0220 | NonLTC | 651-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0220 | NonLTC | 651-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0220 | NonLTC | 651-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0220 | NonLTC | 651-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0220 | NonLTC | 651-1 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0220 | NonLTC | 651-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0220 | NonLTC | 651-1 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Readings | Fault Operations Ground | 0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | YD000507 | Yard | 432-Yard | Yard Patrol Inspection | Ambient Temp | 65 | °F |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | YD000507 | Yard | 432-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | YD000507 | Yard | 432-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | YD000507 | Yard | 432-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | YD000507 | Yard | 432-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | YD000507 | Yard | 432-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | YD000507 | Yard | 432-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | YD000507 | Yard | 432-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | YD000507 | Yard | 432-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | YD000507 | Yard | 432-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | LTCMechanism | 687-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | LTCMechanism | 687-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | LTCMechanism | 687-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | YD000507 | Yard | 432-Yard | Yard Patrol Inspection | General Comments | | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | YD000507 | Yard | 432-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | YD000507 | Yard | 432-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | YD000507 | Yard | 432-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | YD000507 | Yard | 432-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/22/2023 10:25 | Distribution | Boonesboro Park Quarterly Inspection | YD000507 | Yard | 432-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | ST000385 | Structure | 818-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | ST000385 | Structure | 818-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | ST000385 | Structure | 818-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | ST000385 | Structure | 818-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | ST000385 | Structure | 818-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | ST000385 | Structure | 818-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | LTCMechanism | 895-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | ST000385 | Structure | 818-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | ST000385 | Structure | 818-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | ST000385 | Structure | 818-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | ST000385 | Structure | 818-Structure | Structure Patrol Inspection | General Comments | | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | LTCMechanism | 895-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | LTCMechanism | 895-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | LTCMechanism | 895-1 | LTC Counter Readings | LTC Operations Since Last Insp | 98 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | LTCMechanism | 895-1 | LTC Counter Readings | LTC Min Tap Position | Neutral | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | LTCMechanism | 895-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | LTCMechanism | 895-1 | LTC Counter Readings | LTC Current Tap Position | 4R | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | LTCMechanism | 895-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | LTCMechanism | 895-1 | LTC Counter Readings | LTC As Left Counter | 11356 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | LTCMechanism | 895-1 | LTC Counter Readings | LTC As Found Counter | 11356 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | LTCMechanism | 895-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | LTCMechanism | 895-1 | LTC Counter Readings | General Comments | | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | LTCMechanism | 895-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | B0320 | LTCMechanism | 895-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0220 | NonLTC | 651-1 A | NonLTC Transformer Readings | Totalizer Meter Reading | .0383 | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0220 | NonLTC | 651-1 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 600 | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0220 | NonLTC | 651-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0220 | NonLTC | 651-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0220 | NonLTC | 651-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0220 | NonLTC | 651-1 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0220 | NonLTC | 651-1 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0220 | NonLTC | 651-1 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0220 | NonLTC | 651-1 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/22/2023 14:13 | Distribution | Estill Stone Quarterly Inspection | W0220 | NonLTC | 651-1 A | NonLTC Transformer Readings | Oil Temp Present | 0 | °C |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Readings | Unknown Operations | 0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Readings | Switching Operations | 0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Readings | Amps C Ø | 190.0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Readings | Amps B Ø | 160.0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Readings | Amps A Ø | 160.0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | K0140 | BreakerVacuum | 895-0712 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | YD000381 | Yard | 818-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | YD000381 | Yard | 818-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | YD000381 | Yard | 818-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | YD000381 | Yard | 818-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | YD000381 | Yard | 818-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Readings | General Comments | | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Readings | LTC Totalizer Reading | 5258.88 | kw |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Readings | Oil Temp Present | 32 | °C |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | YD000378 | Yard | 895-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Readings | Unknown Operations | 0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Readings | Switching Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Readings | Operations This Read Vac | 0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Readings | Operations Counter AL | 194 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Readings | Operations Counter AF | 194 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Readings | Maintenance Operations | 0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Readings | General Comments | | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Patrol Inspection | General Comments | | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Readings | Follow-up Action Required? | n | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | BK001402 | BreakerVacuum | 818-0711 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | ST000385 | Structure | 818-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | ST000385 | Structure | 818-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Readings | 9 Month Operations | 0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Readings | Amps A Ø | 0.0 | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/22/2023 12:03 | Distribution | Red House Quarterly Inspection | S0054 | WithLTC | 687-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Readings | Amps B Ø | 0.0 | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | ST000385 | Structure | 818-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | ST000385 | Structure | 818-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Readings | Amps C Ø | 0.0 | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/22/2023 12:33 | Distribution | Dow Corning Quarterly Inspection | BB0216 | BreakerVacuum | 895-0713 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/22/2023 12:26 | Distribution | Dayton-Walther Quarterly Inspection | ST000385 | Structure | 818-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1155 | Regulator | 849-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1155 | Regulator | 849-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1155 | Regulator | 849-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1155 | Regulator | 849-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 131432 | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1155 | Regulator | 849-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1155 | Regulator | 849-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1155 | Regulator | 849-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1155 | Regulator | 849-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1156 | Regulator | 589-2 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1154 | Regulator | 849-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1154 | Regulator | 849-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1155 | Regulator | 849-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1154 | Regulator | 849-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.8 | volts |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1154 | Regulator | 849-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 115873 | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1154 | Regulator | 849-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1156 | Regulator | 589-2 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1154 | Regulator | 849-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1154 | Regulator | 849-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1154 | Regulator | 849-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1155 | Regulator | 849-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1155 | Regulator | 849-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1155 | Regulator | 849-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Readings | Amps A Ø | 96.0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1155 | Regulator | 849-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1155 | Regulator | 849-1 C | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1153 | Regulator | 849-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BAT001323 | Battery | 094-Battery Bank Distribution | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BAT001323 | Battery | 094-Battery Bank Distribution | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1153 | Regulator | 849-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1153 | Regulator | 849-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1153 | Regulator | 849-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | YD000460 | Yard | 589-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | YD000460 | Yard | 589-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Readings | Operations Counter AL | 197 | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1155 | Regulator | 849-1 C | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1155 | Regulator | 849-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | YD000460 | Yard | 589-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | YD000460 | Yard | 589-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | YD000460 | Yard | 589-Yard | Yard Patrol Inspection | Ambient Temp | 62 | °F |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1155 | Regulator | 849-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1155 | Regulator | 849-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1155 | Regulator | 849-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1155 | Regulator | 849-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Readings | Operations Counter AF | 196 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BAT001323 | Battery | 094-Battery Bank Distribution | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BAT001323 | Battery | 094-Battery Bank Distribution | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1155 | Regulator | 849-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BAT001323 | Battery | 094-Battery Bank Distribution | Battery Patrol Inspection | Battery Area Ambient Temp | 68 | °F |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Readings | Fault Operations Ground | 0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Readings | Follow-up Action Required? | n | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BAT001323 | Battery | 094-Battery Bank Distribution | Battery Patrol Inspection | All Connections OK? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1155 | Regulator | 849-1 C | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1155 | Regulator | 849-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1155 | Regulator | 849-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1156 | Regulator | 589-2 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1156 | Regulator | 589-2 A | Regulator Patrol Inspection | Regulator As Left Counter | 0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1156 | Regulator | 589-2 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.7 | volts |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1156 | Regulator | 589-2 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1156 | Regulator | 589-2 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | LTCM000086 | LTCMechanism | 094-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | LTCM000086 | LTCMechanism | 094-5 | LTC Counter Readings | General Comments | | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | LTCM000086 | LTCMechanism | 094-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | LTCM000086 | LTCMechanism | 094-5 | LTC Counter Readings | LTC As Found Counter | 18588 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | LTCM000086 | LTCMechanism | 094-5 | LTC Counter Readings | LTC As Left Counter | 18588 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | LTCM000086 | LTCMechanism | 094-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | LTCM000086 | LTCMechanism | 094-5 | LTC Counter Readings | LTC Current Tap Position | 10L | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | LTCM000086 | LTCMechanism | 094-5 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | LTCM000086 | LTCMechanism | 094-5 | LTC Counter Readings | LTC Min Tap Position | 16L | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | LTCM000086 | LTCMechanism | 094-5 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | YD000460 | Yard | 589-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | LTCM000086 | LTCMechanism | 094-5 | LTC Counter Readings | LTC Operations Since Last Insp | 1102 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | LTCM000086 | LTCMechanism | 094-5 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | LTCM000086 | LTCMechanism | 094-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1156 | Regulator | 589-2 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1156 | Regulator | 589-2 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1156 | Regulator | 589-2 A | Regulator Patrol Inspection | Min Tap Position | 16L | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1156 | Regulator | 589-2 A | Regulator Patrol Inspection | Max Tap Position | 1L | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | YD000460 | Yard | 589-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | YD000460 | Yard | 589-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | YD000460 | Yard | 589-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Readings | Operations This Read Vac | 1 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Readings | Switching Operations | 1 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BAT001323 | Battery | 094-Battery Bank Distribution | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BAT001323 | Battery | 094-Battery Bank Distribution | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1156 | Regulator | 589-2 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1156 | Regulator | 589-2 A | Regulator Patrol Inspection | General Comments | | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1156 | Regulator | 589-2 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1156 | Regulator | 589-2 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1156 | Regulator | 589-2 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1156 | Regulator | 589-2 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1156 | Regulator | 589-2 A | Regulator Patrol Inspection | Current Tap Position | 9L | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1156 | Regulator | 589-2 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1156 | Regulator | 589-2 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1156 | Regulator | 589-2 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | LTCM000086 | LTCMechanism | 094-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BAT001323 | Battery | 094-Battery Bank Distribution | Battery Patrol Inspection | Positive DC Ground | 26.1 | VDC |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BAT001323 | Battery | 094-Battery Bank Distribution | Battery Patrol Inspection | Negative DC Ground | 27.4 | VDC |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BAT001323 | Battery | 094-Battery Bank Distribution | Battery Patrol Inspection | General Comments | | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BAT001323 | Battery | 094-Battery Bank Distribution | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BAT001323 | Battery | 094-Battery Bank Distribution | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BAT001323 | Battery | 094-Battery Bank Distribution | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Readings | Unknown Operations | 0 | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1153 | Regulator | 849-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1153 | Regulator | 849-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.9 | volts |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1153 | Regulator | 849-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 133154 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1153 | Regulator | 849-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | YD000460 | Yard | 589-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | YD000460 | Yard | 589-Yard | Yard Patrol Inspection | General Comments | | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | YD000460 | Yard | 589-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1153 | Regulator | 849-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Readings | 9 Month Operations | 1 | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | KX0028 | RecloserElectronic | 849-2103 | Recloser Electronic Patrol Inspection | Amps A Ø | 70.0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1153 | Regulator | 849-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1153 | Regulator | 849-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | YD000460 | Yard | 589-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | YD000460 | Yard | 589-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | YD000460 | Yard | 589-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Readings | Fault Operations Ground | 0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | YD000460 | Yard | 589-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | ST000463 | Structure | 589-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | ST000463 | Structure | 589-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | ST000463 | Structure | 589-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | ST000463 | Structure | 589-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | ST000463 | Structure | 589-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | ST000463 | Structure | 589-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | ST000463 | Structure | 589-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | ST000463 | Structure | 589-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | ST000463 | Structure | 589-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | ST000463 | Structure | 589-Structure | Structure Patrol Inspection | General Comments | | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | ST000463 | Structure | 589-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | ST000463 | Structure | 589-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | ST000463 | Structure | 589-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | ST000463 | Structure | 589-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | ST000463 | Structure | 589-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | ST000463 | Structure | 589-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | ST000463 | Structure | 589-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | ST000463 | Structure | 589-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | ST000463 | Structure | 589-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | ST000463 | Structure | 589-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | ST000463 | Structure | 589-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | ST000463 | Structure | 589-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1154 | Regulator | 849-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1154 | Regulator | 849-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1154 | Regulator | 849-1 B | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1154 | Regulator | 849-1 B | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1154 | Regulator | 849-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1154 | Regulator | 849-1 B | Regulator Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1154 | Regulator | 849-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1154 | Regulator | 849-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1154 | Regulator | 849-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1154 | Regulator | 849-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1154 | Regulator | 849-1 B | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1154 | Regulator | 849-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1154 | Regulator | 849-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1154 | Regulator | 849-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1154 | Regulator | 849-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1154 | Regulator | 849-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Readings | Amps A Ø | 11.0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Readings | Amps B Ø | 9.0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Readings | Amps C Ø | 136.0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Readings | Amps B Ø | 125.0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Readings | Amps A Ø | 96.0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Readings | Amps C Ø | 12.0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Readings | Amps B Ø | 125.0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Readings | Amps C Ø | 140.0 | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | KX0028 | RecloserElectronic | 849-2103 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | KX0028 | RecloserElectronic | 849-2103 | Recloser Electronic Patrol Inspection | Operations Counter | 10 | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | KX0028 | RecloserElectronic | 849-2103 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | KX0028 | RecloserElectronic | 849-2103 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | KX0028 | RecloserElectronic | 849-2103 | Recloser Electronic Patrol Inspection | General Comments | | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | KX0028 | RecloserElectronic | 849-2103 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | KX0028 | RecloserElectronic | 849-2103 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Readings | Maintenance Operations | 0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Readings | General Comments | | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Patrol Inspection | General Comments | | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Readings | Follow-up Action Required? | n | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1153 | Regulator | 849-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | KX0028 | RecloserElectronic | 849-2103 | Recloser Electronic Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | KX0028 | RecloserElectronic | 849-2103 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | KX0028 | RecloserElectronic | 849-2103 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | KX0028 | RecloserElectronic | 849-2103 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1153 | Regulator | 849-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1153 | Regulator | 849-1 A | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1153 | Regulator | 849-1 A | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1153 | Regulator | 849-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1153 | Regulator | 849-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | KX0028 | RecloserElectronic | 849-2103 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | KX0028 | RecloserElectronic | 849-2103 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | KX0028 | RecloserElectronic | 849-2103 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | KX0028 | RecloserElectronic | 849-2103 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | KX0028 | RecloserElectronic | 849-2103 | Recloser Electronic Patrol Inspection | Amps C Ø | 68.0 | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | KX0028 | RecloserElectronic | 849-2103 | Recloser Electronic Patrol Inspection | Amps B Ø | 80.0 | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1153 | Regulator | 849-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1153 | Regulator | 849-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1153 | Regulator | 849-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1153 | Regulator | 849-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1153 | Regulator | 849-1 A | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | R1153 | Regulator | 849-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Readings | Amps B Ø | 81.0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1305 | Regulator | 589-2 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1305 | Regulator | 589-2 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1305 | Regulator | 589-2 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1305 | Regulator | 589-2 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.7 | volts |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1305 | Regulator | 589-2 B | Regulator Patrol Inspection | Regulator As Left Counter | 79654 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1305 | Regulator | 589-2 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1305 | Regulator | 589-2 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1305 | Regulator | 589-2 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1306 | Regulator | 589-2 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1306 | Regulator | 589-2 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1306 | Regulator | 589-2 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1306 | Regulator | 589-2 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Readings | Amps A Ø | 66.0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Readings | 9 Month Operations | 2 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1306 | Regulator | 589-2 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1306 | Regulator | 589-2 C | Regulator Patrol Inspection | Current Tap Position | 9L | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1306 | Regulator | 589-2 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1306 | Regulator | 589-2 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1306 | Regulator | 589-2 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1306 | Regulator | 589-2 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1306 | Regulator | 589-2 C | Regulator Patrol Inspection | General Comments | | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1306 | Regulator | 589-2 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1306 | Regulator | 589-2 C | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1306 | Regulator | 589-2 C | Regulator Patrol Inspection | Min Tap Position | 16L | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1306 | Regulator | 589-2 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1306 | Regulator | 589-2 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1306 | Regulator | 589-2 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1306 | Regulator | 589-2 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1306 | Regulator | 589-2 C | Regulator Patrol Inspection | Reg Output Voltage Level | 125.5 | volts |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1306 | Regulator | 589-2 C | Regulator Patrol Inspection | Regulator As Left Counter | 110837 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1306 | Regulator | 589-2 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1306 | Regulator | 589-2 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1306 | Regulator | 589-2 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | LTCMechanism | OK-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | LTCMechanism | OK-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | LTCMechanism | OK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | LTCMechanism | OK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Readings | Operations This Read Vac | 1 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Readings | Operations Counter AL | 325 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Readings | Operations Counter AF | 324 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Readings | Maintenance Operations | 0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Readings | General Comments | | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Patrol Inspection | General Comments | | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Readings | Follow-up Action Required? | n | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Readings | Fault Operations Ground | 0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1305 | Regulator | 589-2 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1305 | Regulator | 589-2 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1305 | Regulator | 589-2 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1305 | Regulator | 589-2 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1305 | Regulator | 589-2 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1305 | Regulator | 589-2 B | Regulator Patrol Inspection | Current Tap Position | 12L | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1305 | Regulator | 589-2 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1305 | Regulator | 589-2 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1305 | Regulator | 589-2 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1305 | Regulator | 589-2 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1305 | Regulator | 589-2 B | Regulator Patrol Inspection | General Comments | | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1305 | Regulator | 589-2 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1305 | Regulator | 589-2 B | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1305 | Regulator | 589-2 B | Regulator Patrol Inspection | Min Tap Position | 16L | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1305 | Regulator | 589-2 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Readings | Amps C Ø | 58.0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | FE000650 | Fence | OK-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | FE000650 | Fence | OK-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | ST000634 | Structure | OK-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | ST000634 | Structure | OK-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | ST000634 | Structure | OK-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | ST000634 | Structure | OK-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | ST000634 | Structure | OK-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | ST000634 | Structure | OK-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | ST000634 | Structure | OK-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | ST000634 | Structure | OK-Structure | Structure Patrol Inspection | General Comments | | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | ST000634 | Structure | OK-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | ST000634 | Structure | OK-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | ST000634 | Structure | OK-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | ST000634 | Structure | OK-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | ST000634 | Structure | OK-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | ST000634 | Structure | OK-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | ST000634 | Structure | OK-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | ST000634 | Structure | OK-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | ST000634 | Structure | OK-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | ST000634 | Structure | OK-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | ST000634 | Structure | OK-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | ST000634 | Structure | OK-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | ST000634 | Structure | OK-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | YD000655 | Yard | OK-Yard | Yard Patrol Inspection | Ambient Temp | 58 | °F |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | YD000655 | Yard | OK-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | YD000655 | Yard | OK-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | YD000655 | Yard | OK-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | YD000655 | Yard | OK-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | YD000655 | Yard | OK-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | YD000655 | Yard | OK-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | YD000655 | Yard | OK-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | YD000655 | Yard | OK-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | YD000655 | Yard | OK-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | YD000655 | Yard | OK-Yard | Yard Patrol Inspection | General Comments | | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | YD000655 | Yard | OK-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | YD000655 | Yard | OK-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | YD000655 | Yard | OK-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | YD000655 | Yard | OK-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | YD000655 | Yard | OK-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | YD000655 | Yard | OK-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | YD000655 | Yard | OK-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | YD000655 | Yard | OK-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | LTCMechanism | OK-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 417 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | LTCMechanism | OK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | LTCMechanism | OK-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | LTCMechanism | OK-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 5L | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | LTCMechanism | OK-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | LTCMechanism | OK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | LTCMechanism | OK-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 115132 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | LTCMechanism | OK-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 115312 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | LTCMechanism | OK-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | LTCMechanism | OK-TRANS 1 | LTC Counter Readings | General Comments | | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | LTCMechanism | OK-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | LTCMechanism | OK-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | BCH001289 | Charger | 589-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | BCH001289 | Charger | 589-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | BCH001289 | Charger | 589-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | BCH001289 | Charger | 589-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.3 | amps |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | BCH001289 | Charger | 589-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | BCH001289 | Charger | 589-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | BCH001289 | Charger | 589-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | BCH001289 | Charger | 589-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | BAT001374 | Battery | 589-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | BAT001374 | Battery | 589-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 62 | °F |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | BAT001374 | Battery | 589-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | BAT001374 | Battery | 589-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | BAT001374 | Battery | 589-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | BAT001374 | Battery | 589-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | BAT001374 | Battery | 589-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | BAT001374 | Battery | 589-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | BAT001374 | Battery | 589-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | BAT001374 | Battery | 589-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | BAT001374 | Battery | 589-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | BAT001374 | Battery | 589-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | BAT001374 | Battery | 589-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | BAT001374 | Battery | 589-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | FE000650 | Fence | OK-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | FE000650 | Fence | OK-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | FE000650 | Fence | OK-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | FE000650 | Fence | OK-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | FE000650 | Fence | OK-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | FE000650 | Fence | OK-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | FE000650 | Fence | OK-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | FE000650 | Fence | OK-Fence | Fence Patrol Inspection | General Comments | | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | FE000454 | Fence | 589-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | FE000454 | Fence | 589-Fence | Fence Patrol Inspection | General Comments | | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | FE000454 | Fence | 589-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | FE000454 | Fence | 589-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Readings | LTC Totalizer Reading | 5299.20 | kw |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Readings | General Comments | | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0698 | BreakerSF6 | OK-1271 | GCB Patrol Inspection | General Comments | | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0698 | BreakerSF6 | OK-1271 | GCB Readings | Follow-up Action Required? | n | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0698 | BreakerSF6 | OK-1271 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0698 | BreakerSF6 | OK-1271 | GCB Readings | Fault Operations | 0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0698 | BreakerSF6 | OK-1271 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0698 | BreakerSF6 | OK-1271 | GCB Readings | Amps C Ø | 152.0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0699 | BreakerSF6 | OK-1272 | GCB Readings | 9 Month Operations GCB New | 9 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0699 | BreakerSF6 | OK-1272 | GCB Readings | Amps A Ø | 129.0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Readings | 9 Month Operations | 1 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0698 | BreakerSF6 | OK-1271 | GCB Readings | Amps B Ø | 156.0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0698 | BreakerSF6 | OK-1271 | GCB Readings | Amps A Ø | 154.0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0698 | BreakerSF6 | OK-1271 | GCB Readings | 9 Month Operations GCB New | 16 | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | ST000496 | Structure | 849-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | ST000496 | Structure | 849-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | ST000496 | Structure | 849-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | ST000496 | Structure | 849-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | ST000496 | Structure | 849-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | ST000496 | Structure | 849-Structure | Structure Patrol Inspection | General Comments | | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | ST000496 | Structure | 849-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1156 | Regulator | 589-2 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | R1156 | Regulator | 589-2 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Readings | Fault Operations Ground | 0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | LTCM000086 | LTCMechanism | 094-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | LTCC000792 | LTCControl | 094-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | LTCC000792 | LTCControl | 094-5 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | LTCC000792 | LTCControl | 094-5 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | LTCC000792 | LTCControl | 094-5 | LTC Control Insp | LTC Output Voltage Level | 124.6 | VAC |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | LTCC000792 | LTCControl | 094-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | LTCC000792 | LTCControl | 094-5 | LTC Control Insp | General Comments | | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | LTCC000792 | LTCControl | 094-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | LTCC000792 | LTCControl | 094-5 | LTC Control Insp | All Connections OK? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0698 | BreakerSF6 | OK-1271 | GCB Readings | Unknown Operations | 0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0698 | BreakerSF6 | OK-1271 | GCB Readings | Switching Operations | 0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0698 | BreakerSF6 | OK-1271 | GCB Readings | Operations This Read SF6 | 0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0698 | BreakerSF6 | OK-1271 | GCB Readings | Operations Counter AL | 403 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0698 | BreakerSF6 | OK-1271 | GCB Readings | Operations Counter AF | 403 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0698 | BreakerSF6 | OK-1271 | GCB Readings | Num Operations Last 9 Months | 16 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0698 | BreakerSF6 | OK-1271 | GCB Readings | Maintenance Operations | 0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0698 | BreakerSF6 | OK-1271 | GCB Readings | General Comments | | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Readings | Winding Temp Present | 25 | °C |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Readings | Winding Temp Max | 32 | °C |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Readings | Totalizer Meter Reading | .3680 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | TX000215 | WithLTC | 094-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | FE000454 | Fence | 589-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | YD000494 | Yard | 849-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | YD000494 | Yard | 849-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | YD000494 | Yard | 849-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | YD000494 | Yard | 849-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | YD000494 | Yard | 849-Yard | Yard Patrol Inspection | General Comments | | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Readings | Operations Counter AF | 158 | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | YD000494 | Yard | 849-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | YD000494 | Yard | 849-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | YD000494 | Yard | 849-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | YD000494 | Yard | 849-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | YD000494 | Yard | 849-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | YD000494 | Yard | 849-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | YD000494 | Yard | 849-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | YD000494 | Yard | 849-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | YD000494 | Yard | 849-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | YD000494 | Yard | 849-Yard | Yard Patrol Inspection | Ambient Temp | 56 | °F |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0700 | BreakerSF6 | OK-1273 | GCB Readings | Unknown Operations | 0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0700 | BreakerSF6 | OK-1273 | GCB Readings | Switching Operations | 0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Readings | Operations Counter AL | 158 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Readings | Operations This Read Vac | 1 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Readings | Switching Operations | 1 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Readings | Unknown Operations | 0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0700 | BreakerSF6 | OK-1273 | GCB Readings | Operations This Read SF6 | 0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0700 | BreakerSF6 | OK-1273 | GCB Readings | Operations Counter AL | 571 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0700 | BreakerSF6 | OK-1273 | GCB Readings | Operations Counter AF | 571 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0700 | BreakerSF6 | OK-1273 | GCB Readings | Num Operations Last 9 Months | 27 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0700 | BreakerSF6 | OK-1273 | GCB Readings | Maintenance Operations | 0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0700 | BreakerSF6 | OK-1273 | GCB Patrol Inspection | General Comments | ok | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0700 | BreakerSF6 | OK-1273 | GCB Readings | General Comments | | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0700 | BreakerSF6 | OK-1273 | GCB Readings | Follow-up Action Required? | n | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0700 | BreakerSF6 | OK-1273 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0700 | BreakerSF6 | OK-1273 | GCB Readings | Fault Operations | 0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0700 | BreakerSF6 | OK-1273 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0700 | BreakerSF6 | OK-1273 | GCB Readings | Amps C Ø | 68.0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0700 | BreakerSF6 | OK-1273 | GCB Readings | Amps B Ø | 62.0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0700 | BreakerSF6 | OK-1273 | GCB Readings | Amps A Ø | 67.0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0700 | BreakerSF6 | OK-1273 | GCB Readings | 9 Month Operations GCB New | 27 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Readings | Unknown Operations | 0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Readings | Switching Operations | 1 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0252 | BreakerVacuum | 589-2146 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | FE000454 | Fence | 589-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | FE000454 | Fence | 589-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | FE000454 | Fence | 589-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | FE000454 | Fence | 589-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | FE000454 | Fence | 589-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | FE000454 | Fence | 589-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | FE000454 | Fence | 589-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | ST000496 | Structure | 849-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0699 | BreakerSF6 | OK-1272 | GCB Readings | Amps B Ø | 135.0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0699 | BreakerSF6 | OK-1272 | GCB Readings | Amps C Ø | 129.0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0699 | BreakerSF6 | OK-1272 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0699 | BreakerSF6 | OK-1272 | GCB Readings | Fault Operations | 0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0699 | BreakerSF6 | OK-1272 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0699 | BreakerSF6 | OK-1272 | GCB Readings | Follow-up Action Required? | n | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Readings | Follow-up Action Required? | n | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Patrol Inspection | General Comments | | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Readings | General Comments | | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Readings | Maintenance Operations | 0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000934 | BreakerVacuum | 094-5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0699 | BreakerSF6 | OK-1272 | GCB Patrol Inspection | General Comments | | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0699 | BreakerSF6 | OK-1272 | GCB Readings | General Comments | | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0699 | BreakerSF6 | OK-1272 | GCB Readings | Maintenance Operations | 0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0699 | BreakerSF6 | OK-1272 | GCB Readings | Num Operations Last 9 Months | 9 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0699 | BreakerSF6 | OK-1272 | GCB Readings | Operations Counter AF | 749 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0699 | BreakerSF6 | OK-1272 | GCB Readings | Operations Counter AL | 749 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0699 | BreakerSF6 | OK-1272 | GCB Readings | Operations This Read SF6 | 0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0699 | BreakerSF6 | OK-1272 | GCB Readings | Switching Operations | 0 | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | ST000496 | Structure | 849-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | ST000496 | Structure | 849-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | ST000496 | Structure | 849-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | ST000496 | Structure | 849-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | FE000454 | Fence | 589-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | FE000454 | Fence | 589-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | FE000454 | Fence | 589-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | FE000454 | Fence | 589-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0699 | BreakerSF6 | OK-1272 | GCB Readings | Unknown Operations | 0 | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | ST000496 | Structure | 849-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | ST000496 | Structure | 849-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | ST000496 | Structure | 849-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | YD000494 | Yard | 849-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | ST000496 | Structure | 849-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | ST000496 | Structure | 849-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Readings | Amps A Ø | 59.0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Readings | Amps B Ø | 60.0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Readings | Amps C Ø | 59.0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | PF000262 | PowerFuse | OK-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | PF000263 | PowerFuse | OK-12KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | PF000263 | PowerFuse | OK-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0702 | BreakerSF6 | OK-1275 | GCB Readings | Maintenance Operations | 0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0702 | BreakerSF6 | OK-1275 | GCB Readings | Num Operations Last 9 Months | 12 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0702 | BreakerSF6 | OK-1275 | GCB Readings | Operations Counter AF | 388 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0702 | BreakerSF6 | OK-1275 | GCB Readings | Operations Counter AL | 388 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0702 | BreakerSF6 | OK-1275 | GCB Readings | Operations This Read SF6 | 0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0702 | BreakerSF6 | OK-1275 | GCB Readings | Switching Operations | 0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | PF000263 | PowerFuse | OK-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0702 | BreakerSF6 | OK-1275 | GCB Readings | Unknown Operations | 0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Patrol Inspection | General Comments | | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Readings | General Comments | | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Patrol Inspection | General Comments | | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Readings | General Comments | | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Readings | General Comments | | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Readings | Maintenance Operations | 0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Readings | Operations Counter AF | 324 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Readings | Operations Counter AL | 325 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Readings | Amps C Ø | 0.0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Readings | Amps B Ø | 0.0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Readings | Amps A Ø | 0.0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0702 | BreakerSF6 | OK-1275 | GCB Readings | Amps C Ø | 53.0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0702 | BreakerSF6 | OK-1275 | GCB Readings | Amps B Ø | 45.0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0702 | BreakerSF6 | OK-1275 | GCB Readings | Amps A Ø | 49.0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0702 | BreakerSF6 | OK-1275 | GCB Readings | 9 Month Operations GCB New | 12 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .7746 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Readings | 9 Month Operations | 1 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0704 | BreakerSF6 | OK-12KV TR 1 | GCB Readings | Maintenance Operations | 0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0704 | BreakerSF6 | OK-12KV TR 1 | GCB Readings | Num Operations Last 9 Months | 6 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0704 | BreakerSF6 | OK-12KV TR 1 | GCB Readings | Operations Counter AF | 370 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0704 | BreakerSF6 | OK-12KV TR 1 | GCB Readings | Operations Counter AL | 370 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0704 | BreakerSF6 | OK-12KV TR 1 | GCB Readings | Operations This Read SF6 | 0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0704 | BreakerSF6 | OK-12KV TR 1 | GCB Readings | Switching Operations | 0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0704 | BreakerSF6 | OK-12KV TR 1 | GCB Readings | Unknown Operations | 0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | needs nitrogen added | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Readings | H2 Winding Temp Max | 40 | °C |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Readings | H2 Winding Temp Present | 25 | °C |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | ST000496 | Structure | 849-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | ST000496 | Structure | 849-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | ST000496 | Structure | 849-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Readings | Maintenance Operations | 0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Readings | Operations Counter AF | 401 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Readings | Operations Counter AL | 402 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BCH001265 | Charger | 094-Battery Charger Distribution | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BCH001265 | Charger | 094-Battery Charger Distribution | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BCH001265 | Charger | 094-Battery Charger Distribution | Battery Charger Patrol Insp | General Comments | | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BCH001265 | Charger | 094-Battery Charger Distribution | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | SWG000088 | Switchgear | OK-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | SWG000088 | Switchgear | OK-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | SWG000088 | Switchgear | OK-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | SWG000088 | Switchgear | OK-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | SWG000088 | Switchgear | OK-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | SWG000088 | Switchgear | OK-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | SWG000088 | Switchgear | OK-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Readings | Operations Counter AF | 181 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Readings | Maintenance Operations | 0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Readings | Operations This Read Vac | 1 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Readings | Switching Operations | 1 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Readings | Unknown Operations | 0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0701 | BreakerSF6 | OK-1274 | GCB Readings | Unknown Operations | 0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0701 | BreakerSF6 | OK-1274 | GCB Readings | Switching Operations | 0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0701 | BreakerSF6 | OK-1274 | GCB Readings | Operations This Read SF6 | 0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0701 | BreakerSF6 | OK-1274 | GCB Readings | Operations Counter AL | 661 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0701 | BreakerSF6 | OK-1274 | GCB Readings | Operations Counter AF | 660 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0701 | BreakerSF6 | OK-1274 | GCB Readings | Num Operations Last 9 Months | 5 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0701 | BreakerSF6 | OK-1274 | GCB Readings | Maintenance Operations | 0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0701 | BreakerSF6 | OK-1274 | GCB Readings | General Comments | | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0701 | BreakerSF6 | OK-1274 | GCB Patrol Inspection | General Comments | | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0701 | BreakerSF6 | OK-1274 | GCB Readings | Follow-up Action Required? | n | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0701 | BreakerSF6 | OK-1274 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0701 | BreakerSF6 | OK-1274 | GCB Readings | Fault Operations | 0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0701 | BreakerSF6 | OK-1274 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0701 | BreakerSF6 | OK-1274 | GCB Readings | Amps C Ø | 74.0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0701 | BreakerSF6 | OK-1274 | GCB Readings | Amps B Ø | 87.0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0701 | BreakerSF6 | OK-1274 | GCB Readings | Amps A Ø | 66.0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0701 | BreakerSF6 | OK-1274 | GCB Readings | 9 Month Operations GCB New | 5 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 38 | °C |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 30 | °C |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 45 | °C |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 28 | °C |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 40 | °C |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 30 | °C |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | ST000496 | Structure | 849-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | ST000496 | Structure | 849-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Readings | Operations This Read Vac | 1 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Readings | Unknown Operations | 0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Readings | Switching Operations | 1 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Readings | Operations This Read Vac | 1 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Readings | Operations Counter AL | 182 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | SWG000088 | Switchgear | OK-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | SWG000088 | Switchgear | OK-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | SWG000088 | Switchgear | OK-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | SWG000088 | Switchgear | OK-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | SWG000088 | Switchgear | OK-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 5577.12 | kw |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Readings | Oil Temp Max | 30 | °C |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | SWG000088 | Switchgear | OK-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | SWG000088 | Switchgear | OK-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | SWG000088 | Switchgear | OK-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | SWG000088 | Switchgear | OK-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | SWG000088 | Switchgear | OK-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | SWG000088 | Switchgear | OK-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Readings | Switching Operations | 1 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | SWG000088 | Switchgear | OK-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0253 | BreakerVacuum | 589-2144 | VCB Readings | Unknown Operations | 0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BCH001265 | Charger | 094-Battery Charger Distribution | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BCH001265 | Charger | 094-Battery Charger Distribution | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BCH001265 | Charger | 094-Battery Charger Distribution | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BCH001265 | Charger | 094-Battery Charger Distribution | Battery Charger Patrol Insp | Battery Charger Current | 6.2 | amps |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | C0519 | NonLTC | 589-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Readings | Fault Operations Ground | 0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Readings | Follow-up Action Required? | n | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Patrol Inspection | General Comments | | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Readings | General Comments | | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | CH000193 | ControlHouse | OK-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | CH000193 | ControlHouse | OK-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Readings | 9 Month Operations | 3 | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0702 | BreakerSF6 | OK-1275 | GCB Readings | General Comments | | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0702 | BreakerSF6 | OK-1275 | GCB Patrol Inspection | General Comments | | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0702 | BreakerSF6 | OK-1275 | GCB Readings | Follow-up Action Required? | n | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0704 | BreakerSF6 | OK-12KV TR 1 | GCB Readings | 9 Month Operations GCB New | 6 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0704 | BreakerSF6 | OK-12KV TR 1 | GCB Readings | Amps A Ø | 414.0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0704 | BreakerSF6 | OK-12KV TR 1 | GCB Readings | Amps B Ø | 415.0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0704 | BreakerSF6 | OK-12KV TR 1 | GCB Readings | Amps C Ø | 417.0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0704 | BreakerSF6 | OK-12KV TR 1 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | PF000262 | PowerFuse | OK-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3261.60 | kw |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LT0139 | WithLTC | OK-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Readings | General Comments | | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | CH000193 | ControlHouse | OK-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | CH000193 | ControlHouse | OK-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.3590 | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | CH000193 | ControlHouse | OK-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | CH000193 | ControlHouse | OK-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | CH000193 | ControlHouse | OK-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/21/2023 14:23 | Distribution | Mount Vernon Quarterly Inspection | CB0251 | BreakerVacuum | 589-2145 | VCB Readings | 9 Month Operations | 1 | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | FE000488 | Fence | 849-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | FE000488 | Fence | 849-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | FE000488 | Fence | 849-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | FE000488 | Fence | 849-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | FE000488 | Fence | 849-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | FE000488 | Fence | 849-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | FE000488 | Fence | 849-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | FE000488 | Fence | 849-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | FE000488 | Fence | 849-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | FE000488 | Fence | 849-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | FE000488 | Fence | 849-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | FE000488 | Fence | 849-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | FE000488 | Fence | 849-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | FE000488 | Fence | 849-Fence | Fence Patrol Inspection | General Comments | | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | FE000488 | Fence | 849-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | FE000488 | Fence | 849-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | CH000193 | ControlHouse | OK-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | CH000193 | ControlHouse | OK-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | CH000193 | ControlHouse | OK-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | CH000193 | ControlHouse | OK-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | CH000193 | ControlHouse | OK-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | CH000193 | ControlHouse | OK-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | CH000193 | ControlHouse | OK-Control House | Control House Patrol Inspection | General Comments | | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | CH000193 | ControlHouse | OK-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | CH000193 | ControlHouse | OK-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | CH000193 | ControlHouse | OK-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | CH000193 | ControlHouse | OK-Control House | Control House Patrol Inspection | Restroom Clean & OK? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | CH000193 | ControlHouse | OK-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | CH000193 | ControlHouse | OK-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | CH000193 | ControlHouse | OK-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | CH000193 | ControlHouse | OK-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | CH000193 | ControlHouse | OK-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | PF000262 | PowerFuse | OK-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Readings | Follow-up Action Required? | n | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0704 | BreakerSF6 | OK-12KV TR 1 | GCB Readings | Fault Operations | 0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0704 | BreakerSF6 | OK-12KV TR 1 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0704 | BreakerSF6 | OK-12KV TR 1 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0704 | BreakerSF6 | OK-12KV TR 1 | GCB Readings | Follow-up Action Required? | n | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0704 | BreakerSF6 | OK-12KV TR 1 | GCB Patrol Inspection | General Comments | | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0704 | BreakerSF6 | OK-12KV TR 1 | GCB Readings | General Comments | | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0702 | BreakerSF6 | OK-1275 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0702 | BreakerSF6 | OK-1275 | GCB Readings | Fault Operations | 0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000933 | BreakerVacuum | 094-2166 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Readings | Fault Operations Ground | 0 | |
| 2/21/2023 11:41 | Distribution | Mount Vernon Tap Quarterly Inspection | BK000932 | BreakerVacuum | 094-2165 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/21/2023 11:43 | Distribution | Okolona Quarterly Inspection | LB0702 | BreakerSF6 | OK-1275 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/21/2023 10:11 | Distribution | Brodhead Quarterly Inspection | B0296 | NonLTC | 849-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Readings | General Comments | | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Readings | Maintenance Operations | 0 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Patrol Inspection | General Comments | | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Readings | Follow-up Action Required? | n | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | CH000332 | ControlHouse | 431-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Readings | Fault Operations Ground | 0 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | LTCMechanism | 197-5 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | LTCMechanism | 197-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Readings | Operations Counter AF | 311 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Readings | Operations Counter AL | 312 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Readings | Operations This Read Vac | 1 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Readings | Switching Operations | 1 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Readings | Unknown Operations | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | LTCMechanism | 197-5 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | LTCMechanism | 197-5 | LTC Counter Readings | LTC Min Tap Position | 9L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | CH000332 | ControlHouse | 431-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | LTCMechanism | 197-5 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | LTCMechanism | 197-5 | LTC Counter Readings | LTC Operations Since Last Insp | 355 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | LTCMechanism | 197-5 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Readings | Follow-up Action Required? | n | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Readings | Fault Operations Ground | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | LTCMechanism | 197-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | X0313 | RecloserElectronic | 647-2529 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | X0313 | RecloserElectronic | 647-2529 | Recloser Electronic Patrol Inspection | Operations Counter | 25 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | X0313 | RecloserElectronic | 647-2529 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | LTCMechanism | 197-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | LTCMechanism | 197-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | X0313 | RecloserElectronic | 647-2529 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | X0313 | RecloserElectronic | 647-2529 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Readings | Operations Counter AF | 1241 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Readings | Operations Counter AL | 1242 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | LTCC000363 | LTCControl | 197-6 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Readings | Totalizer Meter Reading | .7272 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | LTCC000363 | LTCControl | 197-6 | LTC Control Insp | General Comments | | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1353 | Regulator | 634-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1353 | Regulator | 634-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1353 | Regulator | 634-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1353 | Regulator | 634-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1353 | Regulator | 634-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1353 | Regulator | 634-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1353 | Regulator | 634-1 A | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1353 | Regulator | 634-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1353 | Regulator | 634-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Readings | 9 Month Operations | 1 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | X0313 | RecloserElectronic | 647-2529 | Recloser Electronic Patrol Inspection | Amps B Ø | 65.0 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | X0313 | RecloserElectronic | 647-2529 | Recloser Electronic Patrol Inspection | Amps C Ø | 68.0 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | CH000332 | ControlHouse | 431-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | X0313 | RecloserElectronic | 647-2529 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | X0313 | RecloserElectronic | 647-2529 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | CH000332 | ControlHouse | 431-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | X0313 | RecloserElectronic | 647-2529 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | X0313 | RecloserElectronic | 647-2529 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | X0313 | RecloserElectronic | 647-2529 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | X0313 | RecloserElectronic | 647-2529 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | X0313 | RecloserElectronic | 647-2529 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | X0313 | RecloserElectronic | 647-2529 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | X0313 | RecloserElectronic | 647-2529 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | TB0940 | BreakerSF6 | 431-708 | GCB Patrol Inspection | Grounds in Place? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | TB0940 | BreakerSF6 | 431-708 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | LTCC000164 | LTCControl | 647-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | LTCC000164 | LTCControl | 647-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | X0313 | RecloserElectronic | 647-2529 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | X0313 | RecloserElectronic | 647-2529 | Recloser Electronic Patrol Inspection | General Comments | | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | X0313 | RecloserElectronic | 647-2529 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Readings | General Comments | | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Patrol Inspection | General Comments | | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | LTCMechanism | 197-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | LTCMechanism | 197-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | LTCMechanism | 197-5 | LTC Counter Readings | General Comments | | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | LTCMechanism | 197-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | LTCMechanism | 197-5 | LTC Counter Readings | LTC As Found Counter | 193538 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | LTCMechanism | 197-5 | LTC Counter Readings | LTC As Left Counter | 193538 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Readings | Follow-up Action Required? | n | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | BAT001578 | Battery | 473-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | BAT001578 | Battery | 473-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 55 | °F |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | BAT001578 | Battery | 473-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | BAT001578 | Battery | 473-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | BAT001578 | Battery | 473-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | BAT001578 | Battery | 473-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Readings | Maintenance Operations | 0 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | CH000332 | ControlHouse | 431-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | CH000332 | ControlHouse | 431-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | CH000332 | ControlHouse | 431-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Readings | Oil Temp Present | 37 | °C |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Readings | LTC Totalizer Reading | 6981.12 | kw |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Readings | General Comments | | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | ST000426 | Structure | 647-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | BAT001578 | Battery | 473-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | BAT001578 | Battery | 473-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | CH000332 | ControlHouse | 431-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Patrol Inspection | General Comments | | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1353 | Regulator | 634-1 A | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1353 | Regulator | 634-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1353 | Regulator | 634-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1353 | Regulator | 634-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1353 | Regulator | 634-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1353 | Regulator | 634-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Readings | General Comments | | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | BAT001578 | Battery | 473-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | ST000426 | Structure | 647-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | ST000426 | Structure | 647-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | ST000426 | Structure | 647-Structure | Structure Patrol Inspection | General Comments | | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | ST000426 | Structure | 647-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | ST000426 | Structure | 647-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | ST000426 | Structure | 647-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | ST000426 | Structure | 647-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | ST000426 | Structure | 647-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Readings | Maintenance Operations | 0 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | CH000332 | ControlHouse | 431-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | CH000332 | ControlHouse | 431-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Readings | Operations Counter AF | 296 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Readings | Operations Counter AL | 297 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Readings | Operations This Read Vac | 1 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Readings | Switching Operations | 1 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Readings | Unknown Operations | 0 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | X0313 | RecloserElectronic | 647-2529 | Recloser Electronic Patrol Inspection | Amps A Ø | 87.0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | LTCC000363 | LTCControl | 197-6 | LTC Control Insp | All Connections OK? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | BAT001578 | Battery | 473-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0 | VDC |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | CH000332 | ControlHouse | 431-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | CH000332 | ControlHouse | 431-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | CH000332 | ControlHouse | 431-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | CH000332 | ControlHouse | 431-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | CH000332 | ControlHouse | 431-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | CH000332 | ControlHouse | 431-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | CH000332 | ControlHouse | 431-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | BAT001578 | Battery | 473-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0 | VDC |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | BAT001578 | Battery | 473-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | BAT001578 | Battery | 473-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | ST000426 | Structure | 647-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | ST000426 | Structure | 647-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | ST000426 | Structure | 647-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | ST000426 | Structure | 647-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | ST000426 | Structure | 647-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | ST000426 | Structure | 647-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | CH000332 | ControlHouse | 431-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | CH000332 | ControlHouse | 431-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | CH000332 | ControlHouse | 431-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | CH000332 | ControlHouse | 431-Control House | Control House Patrol Inspection | General Comments | | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | CH000332 | ControlHouse | 431-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Readings | Amps A Ø | 60.0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Readings | 9 Month Operations | 7 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Readings | Amps A Ø | 21.0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Readings | Amps B Ø | 19.0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Readings | Amps C Ø | 32.0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Readings | Fault Operations Ground | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Readings | Follow-up Action Required? | n | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Patrol Inspection | General Comments | | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Readings | Fault Operations Ground | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Readings | Follow-up Action Required? | n | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Patrol Inspection | General Comments | | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Readings | General Comments | | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Readings | Maintenance Operations | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Readings | Operations Counter AF | 177 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Readings | Operations Counter AL | 177 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Readings | Operations This Read Vac | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Readings | Switching Operations | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK002051 | BreakerVacuum | 197-2535 | VCB Readings | Unknown Operations | 0 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Readings | Amps B Ø | 82.0 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Readings | Amps C Ø | 48.0 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | ST000426 | Structure | 647-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | ST000426 | Structure | 647-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Readings | General Comments | | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Readings | Fault Operations Ground | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | KB0117 | BreakerVacuum | 647-2530 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Readings | Fault Operations Ground | 0 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Readings | Follow-up Action Required? | n | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Patrol Inspection | General Comments | | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Readings | General Comments | | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Readings | Follow-up Action Required? | n | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Readings | Fault Operations Ground | 0 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Readings | 9 Month Operations | 9 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Readings | Unknown Operations | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Readings | Switching Operations | 1 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Readings | Operations This Read Vac | 1 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Readings | Operations Counter AL | 203 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Readings | Operations Counter AF | 202 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Readings | Maintenance Operations | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Readings | General Comments | | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Patrol Inspection | General Comments | | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Readings | Follow-up Action Required? | n | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Readings | Fault Operations Ground | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | FE000499 | Fence | 431-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | FE000499 | Fence | 431-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | FE000499 | Fence | 431-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | FE000499 | Fence | 431-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | FE000499 | Fence | 431-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | YD000506 | Yard | 431-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | BAT000551 | Battery | 647-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | BAT000551 | Battery | 647-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | BAT000551 | Battery | 647-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | BAT000551 | Battery | 647-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 52 | °F |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | BAT000551 | Battery | 647-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | TB0940 | BreakerSF6 | 431-708 | GCB Readings | Maintenance Operations | 0 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | TB0940 | BreakerSF6 | 431-708 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | TB0940 | BreakerSF6 | 431-708 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | TB0940 | BreakerSF6 | 431-708 | GCB Readings | Operations Counter AF | 15 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | TB0940 | BreakerSF6 | 431-708 | GCB Readings | Operations Counter AL | 15 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | TB0940 | BreakerSF6 | 431-708 | GCB Readings | Operations This Read SF6 | 0 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | TB0940 | BreakerSF6 | 431-708 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | TB0940 | BreakerSF6 | 431-708 | GCB Patrol Inspection | SF6 Pressure Indicator | good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | TB0940 | BreakerSF6 | 431-708 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | TB0940 | BreakerSF6 | 431-708 | GCB Readings | Switching Operations | 0 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | YD000424 | Yard | 647-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | YD000424 | Yard | 647-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | YD000424 | Yard | 647-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Readings | Amps C Ø | 355 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | TB0940 | BreakerSF6 | 431-708 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | YD000424 | Yard | 647-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | YD000424 | Yard | 647-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | YD000424 | Yard | 647-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | YD000424 | Yard | 647-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | YD000424 | Yard | 647-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | YD000424 | Yard | 647-Yard | Yard Patrol Inspection | Ambient Temp | 52 | °F |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | FE000420 | Fence | 647-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | n | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | FE000420 | Fence | 647-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | FE000420 | Fence | 647-Fence | Fence Patrol Inspection | General Comments | | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | FE000420 | Fence | 647-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | FE000420 | Fence | 647-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | FE000420 | Fence | 647-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | FE000499 | Fence | 431-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | FE000420 | Fence | 647-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Readings | Amps C Ø | 85.0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Readings | Amps B Ø | 89.0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Readings | Amps A Ø | 100.0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Readings | 9 Month Operations | 9 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | FE000420 | Fence | 647-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | FE000420 | Fence | 647-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | FE000420 | Fence | 647-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Readings | Amps C Ø | 180 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Readings | Amps B Ø | 180 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Readings | Amps A Ø | 160 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Readings | Accumulated Fault Duty C Ph V | 2.1 | % |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Readings | Maintenance Operations | 0 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | FE000499 | Fence | 431-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | FE000499 | Fence | 431-Fence | Fence Patrol Inspection | General Comments | | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | FE000499 | Fence | 431-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | FE000499 | Fence | 431-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | FE000499 | Fence | 431-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | FE000499 | Fence | 431-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | FE000499 | Fence | 431-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | FE000499 | Fence | 431-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | FE000499 | Fence | 431-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | FE000499 | Fence | 431-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Readings | Operations Counter AF | 162 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Readings | Operations Counter AL | 162 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Readings | Operations This Read Vac | 0 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | FE000420 | Fence | 647-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | FE000420 | Fence | 647-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | FE000420 | Fence | 647-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | FE000420 | Fence | 647-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | FE000420 | Fence | 647-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | YD000506 | Yard | 431-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | YD000506 | Yard | 431-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | YD000506 | Yard | 431-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | YD000506 | Yard | 431-Yard | Yard Patrol Inspection | General Comments | | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | YD000506 | Yard | 431-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | YD000506 | Yard | 431-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | LTCMechanism | 647-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | LTCMechanism | 647-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | YD000506 | Yard | 431-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | YD000506 | Yard | 431-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0066 | BreakerVacuum | 197-2502 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | YD000506 | Yard | 431-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | YD000506 | Yard | 431-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | YD000506 | Yard | 431-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | YD000506 | Yard | 431-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | LTCMechanism | 647-1 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | LTCMechanism | 647-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | LTCMechanism | 647-1 | LTC Counter Readings | LTC Operations Since Last Insp | 360 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | LTCMechanism | 647-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | LTCMechanism | 647-1 | LTC Counter Readings | LTC Max Tap Position | 5R | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | LTCMechanism | 647-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | LTCMechanism | 647-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | LTCMechanism | 647-1 | LTC Counter Readings | LTC As Left Counter | 51744 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | LTCMechanism | 647-1 | LTC Counter Readings | LTC As Found Counter | 51744 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | LTCMechanism | 647-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | LTCMechanism | 647-1 | LTC Counter Readings | General Comments | | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | LTCMechanism | 647-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | LTCMechanism | 647-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | FE000420 | Fence | 647-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | YD000506 | Yard | 431-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | YD000506 | Yard | 431-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | BAT001632 | Battery | 634-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | BAT001632 | Battery | 634-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | BAT001632 | Battery | 634-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.7 | VDC |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | BAT001632 | Battery | 634-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.7 | VDC |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | BAT001632 | Battery | 634-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | BAT001632 | Battery | 634-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | LTCC000833 | LTCControl | 473-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | LTCC000833 | LTCControl | 473-1 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | LTCC000833 | LTCControl | 473-1 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | LTCC000833 | LTCControl | 473-1 | LTC Control Insp | LTC Output Voltage Level | 124 | VAC |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | LTCC000833 | LTCControl | 473-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | LTCC000833 | LTCControl | 473-1 | LTC Control Insp | General Comments | | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | LTCC000833 | LTCControl | 473-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | LTCC000833 | LTCControl | 473-1 | LTC Control Insp | All Connections OK? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Readings | Amps C Ø | 103.0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Readings | Amps B Ø | 82.0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Readings | Amps A Ø | 99.0 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1353 | Regulator | 634-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1353 | Regulator | 634-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1353 | Regulator | 634-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1353 | Regulator | 634-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1353 | Regulator | 634-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 53955 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1353 | Regulator | 634-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1353 | Regulator | 634-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1353 | Regulator | 634-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1353 | Regulator | 634-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | ST000523 | Structure | 634-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | ST000523 | Structure | 634-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Readings | Totalizer Meter Reading | .6234 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | LTCC000363 | LTCControl | 197-6 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | LTCC000363 | LTCControl | 197-6 | LTC Control Insp | LTC Output Voltage Level | 123.1 | VAC |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Readings | Operations This Read Vac | 1 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Readings | Switching Operations | 1 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Readings | Unknown Operations | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | LTCC000363 | LTCControl | 197-6 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | LTCC000363 | LTCControl | 197-6 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | LTCC000363 | LTCControl | 197-6 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | LTCM000095 | LTCMechanism | 473-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | LTCM000095 | LTCMechanism | 473-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | LTCM000095 | LTCMechanism | 473-1 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | LTCM000095 | LTCMechanism | 473-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | LTCM000095 | LTCMechanism | 473-1 | LTC Counter Readings | LTC Operations Since Last Insp | 1 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | LTCM000095 | LTCMechanism | 473-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0 | psi |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | LTCM000095 | LTCMechanism | 473-1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | LTCM000095 | LTCMechanism | 473-1 | LTC Counter Readings | LTC Max Tap Position | 7R | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | LTCM000095 | LTCMechanism | 473-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | LTCM000095 | LTCMechanism | 473-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | LTCM000095 | LTCMechanism | 473-1 | LTC Counter Readings | LTC As Left Counter | 2751 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | LTCM000095 | LTCMechanism | 473-1 | LTC Counter Readings | LTC As Found Counter | 2751 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | LTCM000095 | LTCMechanism | 473-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | LTCM000095 | LTCMechanism | 473-1 | LTC Counter Readings | General Comments | | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | LTCM000095 | LTCMechanism | 473-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | LTCM000095 | LTCMechanism | 473-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | BCH001581 | Charger | 634-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | BCH001581 | Charger | 634-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | BCH001581 | Charger | 634-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .3 | amps |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | BCH001581 | Charger | 634-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | BCH001581 | Charger | 634-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | BCH001581 | Charger | 634-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | BAT001632 | Battery | 634-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | BAT001632 | Battery | 634-Battery Bank | Battery Patrol Inspection | Bat Volt 1Min After Chgr Trip | 51.7 | VDC |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | BAT001632 | Battery | 634-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 55 | °F |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | BAT001632 | Battery | 634-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | BAT001632 | Battery | 634-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | BAT001632 | Battery | 634-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | BAT001632 | Battery | 634-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | BAT001632 | Battery | 634-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Readings | Unknown Operations | 0 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Readings | Switching Operations | 0 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Readings | Operations This Read Vac | 0 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Readings | Operations Counter AL | 296 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Readings | Operations Counter AF | 296 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Readings | Maintenance Operations | 0 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | ST000426 | Structure | 647-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | ST000426 | Structure | 647-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | ST000426 | Structure | 647-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | ST000426 | Structure | 647-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | ST000426 | Structure | 647-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | YD000424 | Yard | 647-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | YD000424 | Yard | 647-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | YD000424 | Yard | 647-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | YD000424 | Yard | 647-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | n | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | YD000424 | Yard | 647-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | YD000424 | Yard | 647-Yard | Yard Patrol Inspection | General Comments | | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | YD000424 | Yard | 647-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Readings | General Comments | | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Patrol Inspection | General Comments | | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Readings | 9 Month Operations | 0 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Readings | Amps A Ø | 355 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Readings | Amps B Ø | 360 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | BAT000551 | Battery | 647-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | BAT000551 | Battery | 647-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | BAT000551 | Battery | 647-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.3 | VDC |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | BAT000551 | Battery | 647-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.5 | VDC |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | BAT000551 | Battery | 647-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | BAT000551 | Battery | 647-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | BAT000551 | Battery | 647-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | BAT000551 | Battery | 647-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | BAT000551 | Battery | 647-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Water Added | If low,note cell #~'s |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | BAT000551 | Battery | 647-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | ST000523 | Structure | 634-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | ST000523 | Structure | 634-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | ST000523 | Structure | 634-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | ST000523 | Structure | 634-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | ST000523 | Structure | 634-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | ST000523 | Structure | 634-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | LTCMechanism | 197-6 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3 | psi |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Readings | LTC Totalizer Reading | 5984.64 | kw |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Readings | General Comments | | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | LTCMechanism | 197-6 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | LTCMechanism | 197-6 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | LTCMechanism | 197-6 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | LTCMechanism | 197-6 | LTC Counter Readings | LTC Operations Since Last Insp | 158 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | LTCMechanism | 197-6 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | LTCMechanism | 197-6 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | LTCMechanism | 197-6 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | LTCMechanism | 197-6 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | LTCMechanism | 197-6 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | LTCMechanism | 197-6 | LTC Counter Readings | LTC As Left Counter | 88312 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | LTCMechanism | 197-6 | LTC Counter Readings | LTC As Found Counter | 88308 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | LTCMechanism | 197-6 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | LTCMechanism | 197-6 | LTC Counter Readings | General Comments | | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | LTCMechanism | 197-6 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | LTCMechanism | 197-6 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | TX000237 | WithLTC | 473-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | LTCMechanism | 431-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | LTCMechanism | 431-1 | LTC Counter Readings | LTC Min Tap Position | Neutral | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | LTCMechanism | 431-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | LTCMechanism | 431-1 | LTC Counter Readings | LTC Current Tap Position | 2R | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | LTCMechanism | 431-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | LTCMechanism | 431-1 | LTC Counter Readings | LTC As Left Counter | 41154 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | LTCMechanism | 431-1 | LTC Counter Readings | LTC As Found Counter | 41154 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | LTCMechanism | 431-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | LTCMechanism | 431-1 | LTC Counter Readings | General Comments | | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | LTCMechanism | 431-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | LTCMechanism | 431-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Readings | General Comments | | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Readings | LTC Totalizer Reading | 7211.52 | kw |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Patrol Inspection | General Comments | | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Readings | General Comments | | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | FE000514 | Fence | 634-Fence | Fence Patrol Inspection | General Comments | | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | FE000514 | Fence | 634-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | FE000514 | Fence | 634-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Readings | General Comments | | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Readings | LTC Totalizer Reading | 9144 | kw |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | FE000861 | Fence | 473-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | FE000861 | Fence | 473-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | FE000861 | Fence | 473-Fence | Fence Patrol Inspection | General Comments | | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | FE000861 | Fence | 473-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | FE000861 | Fence | 473-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Readings | Fault Adjusted Amps C Phase V | 4.56 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | YD000383 | Yard | 473-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | YD000383 | Yard | 473-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 700 | psi |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Readings | Maintenance Operations | 0 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Readings | Operations Counter AF | 369 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | FE000861 | Fence | 473-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | FE000861 | Fence | 473-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | FE000861 | Fence | 473-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | YD000383 | Yard | 473-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | FE000861 | Fence | 473-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Readings | Operations Counter AL | 469 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | FE000861 | Fence | 473-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | FE000861 | Fence | 473-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | FE000861 | Fence | 473-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | FE000861 | Fence | 473-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | FE000861 | Fence | 473-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Readings | Operations This Read Vac | 4 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Readings | Switching Operations | 0 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | FE000861 | Fence | 473-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | BAT000631 | Battery | 431-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | ST000523 | Structure | 634-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | ST000375 | Structure | 473-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | BAT000631 | Battery | 431-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | BAT000631 | Battery | 431-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 55 | °F |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | BAT000631 | Battery | 431-Battery Bank | Battery Patrol Inspection | Bat Volt 1Min After Chgr Trip | 50.4 | VDC |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | ST000375 | Structure | 473-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | ST000375 | Structure | 473-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | ST000375 | Structure | 473-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | ST000375 | Structure | 473-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | ST000375 | Structure | 473-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | ST000375 | Structure | 473-Structure | Structure Patrol Inspection | General Comments | | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | ST000523 | Structure | 634-Structure | Structure Patrol Inspection | General Comments | | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | ST000523 | Structure | 634-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | ST000523 | Structure | 634-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | ST000523 | Structure | 634-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | ST000523 | Structure | 634-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | BAT000631 | Battery | 431-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Readings | Fault Adjusted Amps A Phase V | 9.37 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Readings | Fault Adjusted Amps B Phase V | 9.37 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Readings | Fault Adjusted Amps C Phase V | 9.37 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Readings | 9 Month Operations | 8 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | ST000375 | Structure | 473-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | ST000375 | Structure | 473-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | ST000375 | Structure | 473-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | ST000375 | Structure | 473-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | ST000375 | Structure | 473-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | ST000375 | Structure | 473-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | ST000375 | Structure | 473-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Readings | Fault Operations A Ø | 1 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Readings | Fault Operations B Ø | 1 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Readings | Accumulated Fault Duty A Ph V | 1.75 | % |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Readings | Unknown Operations | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Readings | Switching Operations | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Readings | Operations This Read Vac | 1 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Readings | Operations Counter AL | 193 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Readings | Operations Counter AF | 192 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Readings | Fault Operations C Ø | 1 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | LTCMechanism | 431-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Readings | Fault Operations Ground | 0 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Readings | Follow-up Action Required? | n | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | LTCMechanism | 431-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | LTCMechanism | 431-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | LTCMechanism | 431-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | LTCMechanism | 431-1 | LTC Counter Readings | LTC Operations Since Last Insp | 675 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | LTCMechanism | 431-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 35 | °C |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | LTCMechanism | 431-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 40 | °C |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Readings | Maintenance Operations | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Readings | General Comments | | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Patrol Inspection | General Comments | | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Readings | Follow-up Action Required? | n | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Readings | Fault Operations Ground | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Readings | Fault Operations C Ø | 1 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | FE000514 | Fence | 634-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | FE000514 | Fence | 634-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | ST000508 | Structure | 431-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | ST000508 | Structure | 431-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | ST000508 | Structure | 431-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | ST000508 | Structure | 431-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | ST000508 | Structure | 431-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | ST000508 | Structure | 431-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Readings | Operations Counter AF | 200 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Readings | Operations Counter AL | 201 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Readings | Operations This Read Vac | 1 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Readings | Switching Operations | 1 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Readings | Unknown Operations | 0 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | ST000375 | Structure | 473-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | ST000375 | Structure | 473-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | FE000514 | Fence | 634-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | FE000514 | Fence | 634-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | FE000514 | Fence | 634-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | FE000514 | Fence | 634-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | FE000514 | Fence | 634-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | FE000514 | Fence | 634-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | FE000514 | Fence | 634-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | FE000514 | Fence | 634-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | FE000514 | Fence | 634-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | n | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Readings | Unknown Operations | 1 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Readings | Winding Temp Present | 35 | °C |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Readings | Totalizer Meter Reading | .9 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0153 | BreakerVacuum | 473-0721 | VCB Readings | Accumulated Fault Duty B Ph V | 2.1 | % |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | ST000375 | Structure | 473-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | ST000375 | Structure | 473-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | ST000375 | Structure | 473-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | ST000375 | Structure | 473-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Readings | Winding Temp Present | 32 | °C |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Readings | Winding Temp Max | 35 | °C |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .6102 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 10160 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Readings | General Comments | | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 5857.92 | kw |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | FE000861 | Fence | 473-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | YD000383 | Yard | 473-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | YD000383 | Yard | 473-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | YD000383 | Yard | 473-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | YD000383 | Yard | 473-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Readings | Maintenance Operations | 0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0067 | BreakerVacuum | 197-2501 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | YD000383 | Yard | 473-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | YD000383 | Yard | 473-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Readings | LTC Totalizer Reading | 5552.64 | kw |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | YD000383 | Yard | 473-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | YD000383 | Yard | 473-Yard | Yard Patrol Inspection | General Comments | | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | YD000383 | Yard | 473-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | YD000383 | Yard | 473-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | YD000383 | Yard | 473-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | YD000383 | Yard | 473-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | YD000383 | Yard | 473-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | ST000508 | Structure | 431-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Readings | Oil Temp Max | 32 | °C |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Readings | Totalizer Meter Reading | .7512 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Readings | Winding Temp Present | 27 | °C |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Readings | Oil Temp Max | 56 | °C |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Readings | Oil Temp Present | 31 | °C |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KT0034 | NonLTC | 634-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | ST000508 | Structure | 431-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | ST000508 | Structure | 431-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | ST000508 | Structure | 431-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | ST000508 | Structure | 431-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | ST000508 | Structure | 431-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Readings | Totalizer Meter Reading | .5784 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | C0475 | WithLTC | 197-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | ST000508 | Structure | 431-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | ST000508 | Structure | 431-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | ST000508 | Structure | 431-Structure | Structure Patrol Inspection | General Comments | | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | ST000508 | Structure | 431-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | ST000508 | Structure | 431-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | ST000508 | Structure | 431-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | ST000508 | Structure | 431-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | ST000508 | Structure | 431-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | LTCC000031 | LTCControl | 431-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | LTCC000031 | LTCControl | 431-1 | LTC Control Insp | LTC Output Voltage Level | 127 | VAC |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | LTCC000164 | LTCControl | 647-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | LTCC000164 | LTCControl | 647-1 | LTC Control Insp | LTC Output Voltage Level | 123.7 | VAC |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | LTCC000164 | LTCControl | 647-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | LTCC000164 | LTCControl | 647-1 | LTC Control Insp | General Comments | | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | LTCC000164 | LTCControl | 647-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | LTCC000164 | LTCControl | 647-1 | LTC Control Insp | All Connections OK? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1355 | Regulator | 634-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1355 | Regulator | 634-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1355 | Regulator | 634-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.7 | volts |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1355 | Regulator | 634-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 54141 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1355 | Regulator | 634-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | TB0940 | BreakerSF6 | 431-708 | GCB Readings | Fault Operations | 0 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | LTCC000031 | LTCControl | 431-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | LTCC000031 | LTCControl | 431-1 | LTC Control Insp | General Comments | | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | BCH001366 | Charger | 647-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | BCH001366 | Charger | 647-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | TB0940 | BreakerSF6 | 431-708 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | TB0940 | BreakerSF6 | 431-708 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | TB0940 | BreakerSF6 | 431-708 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | TB0940 | BreakerSF6 | 431-708 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | BCH001366 | Charger | 647-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .6 | amps |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | BCH001366 | Charger | 647-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | BCH001366 | Charger | 647-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | BCH001366 | Charger | 647-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | BCH001490 | Charger | 431-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | BCH001490 | Charger | 431-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0 | millivolts |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | TB0940 | BreakerSF6 | 431-708 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1354 | Regulator | 634-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1354 | Regulator | 634-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 50867 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1354 | Regulator | 634-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1354 | Regulator | 634-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1354 | Regulator | 634-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1354 | Regulator | 634-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1354 | Regulator | 634-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1354 | Regulator | 634-1 B | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1354 | Regulator | 634-1 B | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1354 | Regulator | 634-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1354 | Regulator | 634-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1354 | Regulator | 634-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1354 | Regulator | 634-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | TB0940 | BreakerSF6 | 431-708 | GCB Patrol Inspection | Ambient Temperature | 55 | °F |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | TB0940 | BreakerSF6 | 431-708 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1355 | Regulator | 634-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1355 | Regulator | 634-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1355 | Regulator | 634-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Readings | Switching Operations | 0 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KB0033 | BreakerVacuum | 431-4311 | VCB Readings | Unknown Operations | 0 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1354 | Regulator | 634-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1354 | Regulator | 634-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Readings | 9 Month Operations | 1 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Readings | Amps A Ø | 96.0 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Readings | Amps B Ø | 127.0 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Readings | Amps C Ø | 117.0 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | FE000514 | Fence | 634-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | FE000514 | Fence | 634-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | BCH001366 | Charger | 647-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | BCH001366 | Charger | 647-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1354 | Regulator | 634-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1354 | Regulator | 634-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1354 | Regulator | 634-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | TB0940 | BreakerSF6 | 431-708 | GCB Readings | General Comments | | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | TB0940 | BreakerSF6 | 431-708 | GCB Patrol Inspection | General Comments | | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | TB0940 | BreakerSF6 | 431-708 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Readings | 9 Month Operations | 3 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1355 | Regulator | 634-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1355 | Regulator | 634-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Readings | Amps A Ø | 156.0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Readings | Amps B Ø | 131.0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Readings | Amps C Ø | 169.0 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1355 | Regulator | 634-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1355 | Regulator | 634-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1355 | Regulator | 634-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | BCH001490 | Charger | 431-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1355 | Regulator | 634-1 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1355 | Regulator | 634-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1355 | Regulator | 634-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | LTCC000031 | LTCControl | 431-1 | LTC Control Insp | VRR Base Voltage AF | 127 | VAC |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | LTCC000031 | LTCControl | 431-1 | LTC Control Insp | VRR Base Voltage AL | 127 | VAC |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | LTCC000031 | LTCControl | 431-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | BCH001490 | Charger | 431-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | BCH001490 | Charger | 431-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | BCH001490 | Charger | 431-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | BK001415 | BreakerVacuum | 197-2500 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | LTCC000031 | LTCControl | 431-1 | LTC Control Insp | All Connections OK? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | BCH001492 | Charger | 473-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0 | millivolts |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | BCH001492 | Charger | 473-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53 | VDC |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | BCH001492 | Charger | 473-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53 | VDC |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | BCH001492 | Charger | 473-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | BCH001492 | Charger | 473-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | LTCC000031 | LTCControl | 431-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | BCH001490 | Charger | 431-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | BCH001490 | Charger | 431-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | TB0940 | BreakerSF6 | 431-708 | GCB Patrol Inspection | Foundation Condition | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | TB0940 | BreakerSF6 | 431-708 | GCB Readings | Follow-up Action Required? | n | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | TB0940 | BreakerSF6 | 431-708 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1355 | Regulator | 634-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1355 | Regulator | 634-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1355 | Regulator | 634-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1355 | Regulator | 634-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1355 | Regulator | 634-1 C | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1355 | Regulator | 634-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1355 | Regulator | 634-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1355 | Regulator | 634-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | KT0024 | WithLTC | 431-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | LTCC000619 | LTCControl | 197-5 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | LTCC000619 | LTCControl | 197-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Readings | Amps C Ø | 0.0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Readings | Amps B Ø | 0.0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Readings | Amps A Ø | 0.0 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Readings | 9 Month Operations | 11 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | ST000375 | Structure | 473-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | ST000375 | Structure | 473-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1354 | Regulator | 634-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | ST000375 | Structure | 473-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | YD000518 | Yard | 634-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | ST000523 | Structure | 634-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | ST000523 | Structure | 634-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | ST000523 | Structure | 634-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | ST000523 | Structure | 634-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | ST000523 | Structure | 634-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Readings | 9 Month Operations | 5 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | BAT000631 | Battery | 431-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | BAT000631 | Battery | 431-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | BAT000631 | Battery | 431-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0 | VDC |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | BAT000631 | Battery | 431-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0 | VDC |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | BAT000631 | Battery | 431-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | BAT000631 | Battery | 431-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | BAT000631 | Battery | 431-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | BAT000631 | Battery | 431-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | BAT000631 | Battery | 431-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | BAT000631 | Battery | 431-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/20/2023 17:14 | Distribution | Airgas Quarterly Inspection | BAT000631 | Battery | 431-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1354 | Regulator | 634-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1354 | Regulator | 634-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | ST000523 | Structure | 634-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | ST000523 | Structure | 634-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | ST000523 | Structure | 634-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Readings | Accumulated Fault Duty A Ph V | 3.84 | % |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Readings | Accumulated Fault Duty B Ph V | 5.59 | % |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Readings | Accumulated Fault Duty C Ph V | 2.44 | % |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Readings | Amps A Ø | 30 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Readings | Amps B Ø | 60 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Readings | Amps C Ø | 60 | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | K0185 | BreakerVacuum | 473-0722 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | YD000518 | Yard | 634-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | n | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1354 | Regulator | 634-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | YD000518 | Yard | 634-Yard | Yard Patrol Inspection | Clear of Obstacles? | n | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | YD000518 | Yard | 634-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | YD000518 | Yard | 634-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1354 | Regulator | 634-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | YD000518 | Yard | 634-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Fair | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | BCH001492 | Charger | 473-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | BCH001492 | Charger | 473-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/20/2023 17:21 | Distribution | Metal And Thermit Quarterly Inspection | BCH001492 | Charger | 473-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | LTCC000619 | LTCControl | 197-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | R1354 | Regulator | 634-1 B | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | LTCC000619 | LTCControl | 197-5 | LTC Control Insp | General Comments | | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | LTCC000619 | LTCControl | 197-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/20/2023 14:25 | Distribution | Taylorsville Quarterly Inspection | S0073 | WithLTC | 647-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | LTCC000619 | LTCControl | 197-5 | LTC Control Insp | All Connections OK? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | YD000518 | Yard | 634-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | YD000518 | Yard | 634-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | n | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | YD000518 | Yard | 634-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | n | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | YD000518 | Yard | 634-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | KB0063 | BreakerVacuum | 197-BT5-6 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | YD000518 | Yard | 634-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | YD000518 | Yard | 634-Yard | Yard Patrol Inspection | General Comments | | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | YD000518 | Yard | 634-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | n | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | LTCC000619 | LTCControl | 197-5 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | YD000518 | Yard | 634-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | YD000518 | Yard | 634-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | YD000518 | Yard | 634-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | LTCC000619 | LTCControl | 197-5 | LTC Control Insp | LTC Output Voltage Level | 123.8 | VAC |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | LTCC000619 | LTCControl | 197-5 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/20/2023 15:53 | Distribution | Fairfield Quarterly Inspection | KB0070 | BreakerVacuum | 634-2503 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/20/2023 10:58 | Distribution | Eminence Quarterly Inspection | B0350 | WithLTC | 197-6 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0402 | BreakerVacuum | GL-1333-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0399 | BreakerVacuum | GL-1332-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0399 | BreakerVacuum | GL-1332-1 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1262 | BreakerVacuum | GL-1336 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0402 | BreakerVacuum | GL-1333-2 | VCB Readings | Operations Counter AL | 204 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0402 | BreakerVacuum | GL-1333-2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0402 | BreakerVacuum | GL-1333-2 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1262 | BreakerVacuum | GL-1336 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1262 | BreakerVacuum | GL-1336 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1262 | BreakerVacuum | GL-1336 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0402 | BreakerVacuum | GL-1333-2 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0402 | BreakerVacuum | GL-1333-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1262 | BreakerVacuum | GL-1336 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0402 | BreakerVacuum | GL-1333-2 | VCB Readings | Amps C Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1263 | BreakerVacuum | GL-1337 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | LTCMechanism | 897-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1262 | BreakerVacuum | GL-1336 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1262 | BreakerVacuum | GL-1336 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1262 | BreakerVacuum | GL-1336 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0402 | BreakerVacuum | GL-1333-2 | VCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1262 | BreakerVacuum | GL-1336 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1262 | BreakerVacuum | GL-1336 | VCB Readings | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0402 | BreakerVacuum | GL-1333-2 | VCB Readings | Amps A Ø | 0.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1262 | BreakerVacuum | GL-1336 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | ST000603 | Structure | TE-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | ST000603 | Structure | TE-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | ST000603 | Structure | TE-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1262 | BreakerVacuum | GL-1336 | VCB Readings | Operations Counter AL | 140 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1262 | BreakerVacuum | GL-1336 | VCB Readings | Operations Counter AF | 140 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1262 | BreakerVacuum | GL-1336 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0402 | BreakerVacuum | GL-1333-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | ST000603 | Structure | TE-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BCH001360 | Charger | 638-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Readings | Amps A Ø | 0.0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BCH001360 | Charger | 638-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BCH001360 | Charger | 638-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BCH001360 | Charger | 638-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.7 | amps |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BCH001360 | Charger | 638-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0402 | BreakerVacuum | GL-1333-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0402 | BreakerVacuum | GL-1333-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0402 | BreakerVacuum | GL-1333-2 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Readings | Amps C Ø | 0.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0399 | BreakerVacuum | GL-1332-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1263 | BreakerVacuum | GL-1337 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1263 | BreakerVacuum | GL-1337 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0399 | BreakerVacuum | GL-1332-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0399 | BreakerVacuum | GL-1332-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0399 | BreakerVacuum | GL-1332-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Readings | 9 Month Operations | 29 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0402 | BreakerVacuum | GL-1333-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0402 | BreakerVacuum | GL-1333-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0402 | BreakerVacuum | GL-1333-2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BCH001360 | Charger | 638-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BCH001360 | Charger | 638-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BCH001360 | Charger | 638-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0402 | BreakerVacuum | GL-1333-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0402 | BreakerVacuum | GL-1333-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0402 | BreakerVacuum | GL-1333-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0402 | BreakerVacuum | GL-1333-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0402 | BreakerVacuum | GL-1333-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0402 | BreakerVacuum | GL-1333-2 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0402 | BreakerVacuum | GL-1333-2 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0402 | BreakerVacuum | GL-1333-2 | VCB Readings | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0402 | BreakerVacuum | GL-1333-2 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0402 | BreakerVacuum | GL-1333-2 | VCB Readings | Operations Counter AF | 204 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | LTCMechanism | 897-2 | LTC Counter Readings | LTC Max Tap Position | 7R | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | LTCMechanism | 897-2 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | LTCMechanism | 897-2 | LTC Counter Readings | LTC Operations Since Last Insp | 1016 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0993 | BreakerAirMagnetic | TE-1242 | AMCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 37 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 60 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 30 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 25 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 47 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 35 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 50 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 20.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | LTCMechanism | 897-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | LTCMechanism | 897-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | LTCMechanism | 897-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Readings | Totalizer Meter Reading | .6948 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 100.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0399 | BreakerVacuum | GL-1332-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0399 | BreakerVacuum | GL-1332-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0399 | BreakerVacuum | GL-1332-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0399 | BreakerVacuum | GL-1332-1 | VCB Readings | Amps C Ø | 0.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LTCC000576 | LTCControl | TE-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LTCC000576 | LTCControl | TE-TRANS 1 | LTC Control Insp | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LTCC000576 | LTCControl | TE-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0399 | BreakerVacuum | GL-1332-1 | VCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1263 | BreakerVacuum | GL-1337 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1263 | BreakerVacuum | GL-1337 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1263 | BreakerVacuum | GL-1337 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1263 | BreakerVacuum | GL-1337 | VCB Readings | Operations Counter AL | 125 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | LTCM000033 | LTCMechanism | 669-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | LTCM000033 | LTCMechanism | 669-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | LTCM000033 | LTCMechanism | 669-2 | LTC Counter Readings | General Comments | | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | LTCM000033 | LTCMechanism | 669-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | LTCM000033 | LTCMechanism | 669-2 | LTC Counter Readings | LTC As Found Counter | 41047 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | LTCM000033 | LTCMechanism | 669-2 | LTC Counter Readings | LTC As Left Counter | 41047 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | LTCM000033 | LTCMechanism | 669-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000232 | Switchgear | 830-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000232 | Switchgear | 830-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000232 | Switchgear | 830-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000232 | Switchgear | 830-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000232 | Switchgear | 830-Swgr Sec 2 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000232 | Switchgear | 830-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000232 | Switchgear | 830-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000232 | Switchgear | 830-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000232 | Switchgear | 830-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0399 | BreakerVacuum | GL-1332-1 | VCB Readings | Amps A Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0399 | BreakerVacuum | GL-1332-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0399 | BreakerVacuum | GL-1332-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0399 | BreakerVacuum | GL-1332-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000232 | Switchgear | 830-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000232 | Switchgear | 830-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000232 | Switchgear | 830-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000232 | Switchgear | 830-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000232 | Switchgear | 830-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000232 | Switchgear | 830-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000232 | Switchgear | 830-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000232 | Switchgear | 830-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | ST000603 | Structure | TE-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | ST000603 | Structure | TE-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1263 | BreakerVacuum | GL-1337 | VCB Readings | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1263 | BreakerVacuum | GL-1337 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | ST000603 | Structure | TE-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | ST000603 | Structure | TE-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | ST000603 | Structure | TE-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | LTCM000033 | LTCMechanism | 669-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0 | psi |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | LTCM000033 | LTCMechanism | 669-2 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | LTCM000033 | LTCMechanism | 669-2 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | LTCM000033 | LTCMechanism | 669-2 | LTC Counter Readings | LTC Current Tap Position | 2R | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000232 | Switchgear | 830-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1263 | BreakerVacuum | GL-1337 | VCB Readings | Operations Counter AF | 125 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | ST000603 | Structure | TE-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | ST000603 | Structure | TE-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1263 | BreakerVacuum | GL-1337 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Readings | H2 Winding Temp Max | 37 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1263 | BreakerVacuum | GL-1337 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0399 | BreakerVacuum | GL-1332-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1263 | BreakerVacuum | GL-1337 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1263 | BreakerVacuum | GL-1337 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1263 | BreakerVacuum | GL-1337 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Readings | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Readings | Maintenance Operations | 27 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Readings | Operations Counter AF | 110 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Readings | Operations Counter AL | 110 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Readings | Operations This Read Vac | 27 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1263 | BreakerVacuum | GL-1337 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1263 | BreakerVacuum | GL-1337 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1263 | BreakerVacuum | GL-1337 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0399 | BreakerVacuum | GL-1332-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1263 | BreakerVacuum | GL-1337 | VCB Readings | Amps C Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1263 | BreakerVacuum | GL-1337 | VCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002302 | BreakerVacuum | 830-0397 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0993 | BreakerAirMagnetic | TE-1242 | AMCB Readings | Amps C Ø | 49.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0993 | BreakerAirMagnetic | TE-1242 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0993 | BreakerAirMagnetic | TE-1242 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0993 | BreakerAirMagnetic | TE-1242 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0993 | BreakerAirMagnetic | TE-1242 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0993 | BreakerAirMagnetic | TE-1242 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0993 | BreakerAirMagnetic | TE-1242 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0993 | BreakerAirMagnetic | TE-1242 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0993 | BreakerAirMagnetic | TE-1242 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0993 | BreakerAirMagnetic | TE-1242 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0993 | BreakerAirMagnetic | TE-1242 | AMCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0993 | BreakerAirMagnetic | TE-1242 | AMCB Patrol Inspection | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0993 | BreakerAirMagnetic | TE-1242 | AMCB Readings | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0993 | BreakerAirMagnetic | TE-1242 | AMCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1263 | BreakerVacuum | GL-1337 | VCB Readings | Amps A Ø | 0.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0993 | BreakerAirMagnetic | TE-1242 | AMCB Readings | Operations Counter AF | 1028 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1263 | BreakerVacuum | GL-1337 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1263 | BreakerVacuum | GL-1337 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1263 | BreakerVacuum | GL-1337 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1263 | BreakerVacuum | GL-1337 | VCB Readings | 9 Month Operations VCB New | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0399 | BreakerVacuum | GL-1332-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1263 | BreakerVacuum | GL-1337 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Readings | H2 Winding Temp Present | 22 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .3 | psi |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0993 | BreakerAirMagnetic | TE-1242 | AMCB Readings | Operations Counter AL | 1028 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0993 | BreakerAirMagnetic | TE-1242 | AMCB Readings | Operations This Read AM | 1 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0993 | BreakerAirMagnetic | TE-1242 | AMCB Readings | Switching Operations | 1 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | LTCMechanism | 897-2 | LTC Counter Readings | LTC As Found Counter | 31497 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | LTCMechanism | 897-2 | LTC Counter Readings | LTC As Left Counter | 31497 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | LTCMechanism | 897-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | LTCMechanism | 897-2 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0409 | BreakerVacuum | GL-GND TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0409 | BreakerVacuum | GL-GND TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0409 | BreakerVacuum | GL-GND TR 1 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | FE000613 | Fence | TE-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | FE000613 | Fence | TE-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | FE000613 | Fence | TE-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | FE000613 | Fence | TE-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | FE000613 | Fence | TE-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | FE000613 | Fence | TE-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | FE000613 | Fence | TE-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | FE000613 | Fence | TE-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | FE000613 | Fence | TE-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | FE000613 | Fence | TE-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | FE000613 | Fence | TE-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | FE000613 | Fence | TE-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | FE000613 | Fence | TE-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 27 | °C |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 27 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Readings | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Readings | 9 Month Operations | 31 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Readings | Amps A Ø | 309.0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Readings | Amps B Ø | 331.0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Readings | Amps C Ø | 254.0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Readings | 9 Month Operations | 28 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Readings | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | LTCMechanism | 897-2 | LTC Counter Readings | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 45 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 27 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 37 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 20 | °C |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Readings | Operations Counter AF | 254 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Readings | Operations Counter AL | 255 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Readings | Operations This Read Vac | 1 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | LTCMechanism | 897-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | LTCMechanism | 897-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Readings | 9 Month Operations | 27 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Readings | Switching Operations | 1 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | LTCMechanism | 638-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | LTCMechanism | 638-1 | LTC Counter Readings | LTC As Found Counter | 18071 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | LTCMechanism | 638-1 | LTC Counter Readings | LTC As Left Counter | 18071 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | LTCMechanism | 638-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | LTCMechanism | 638-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | LTCMechanism | 638-1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | LTCMechanism | 638-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | LTCMechanism | 638-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 22 | °C |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | LTCMechanism | 638-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 22 | °C |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | LTCMechanism | 638-1 | LTC Counter Readings | LTC Operations Since Last Insp | 89 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | LTCMechanism | 638-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | LTCMechanism | 638-1 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | LTCMechanism | 638-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | LTCMechanism | 638-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Readings | Amps C Ø | 0.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Readings | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Readings | Operations Counter AF | 82 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Readings | Operations Counter AL | 82 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Readings | Maintenance Operations | 23 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Readings | Operations This Read Vac | 25 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Readings | Operations Counter AL | 87 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Readings | Operations Counter AF | 87 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Readings | Maintenance Operations | 25 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Readings | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Readings | Operations Counter AF | 113 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Readings | Operations Counter AL | 113 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Readings | Operations This Read Vac | 23 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002298 | BreakerVacuum | 830-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Readings | 9 Month Operations | 3 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Readings | Amps A Ø | 0.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002299 | BreakerVacuum | 830-0412 | VCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Readings | Amps A Ø | 275.0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Readings | Amps B Ø | 300.0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Readings | Amps C Ø | 300.0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | LTCMechanism | 638-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | LTCMechanism | 638-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | LTCMechanism | 638-1 | LTC Counter Readings | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Readings | Amps C Ø | 0.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002300 | BreakerVacuum | 830-0396 | VCB Readings | Amps A Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0409 | BreakerVacuum | GL-GND TR 1 | VCB Readings | Operations Counter AF | 126 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0409 | BreakerVacuum | GL-GND TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0409 | BreakerVacuum | GL-GND TR 1 | VCB Readings | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0409 | BreakerVacuum | GL-GND TR 1 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0409 | BreakerVacuum | GL-GND TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0409 | BreakerVacuum | GL-GND TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0409 | BreakerVacuum | GL-GND TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0409 | BreakerVacuum | GL-GND TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Readings | LTC Totalizer Reading | 12506.40 | kw |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Readings | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0993 | BreakerAirMagnetic | TE-1242 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0993 | BreakerAirMagnetic | TE-1242 | AMCB Readings | 9 Months Operations | 3 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0993 | BreakerAirMagnetic | TE-1242 | AMCB Readings | 9 Month Ops New | 2 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Readings | 9 Month Operations | 1 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0190 | BreakerVacuum | 897-2472 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | FE000613 | Fence | TE-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | FE000613 | Fence | TE-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | FE000613 | Fence | TE-Fence | Fence Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0409 | BreakerVacuum | GL-GND TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0409 | BreakerVacuum | GL-GND TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0409 | BreakerVacuum | GL-GND TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0409 | BreakerVacuum | GL-GND TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0409 | BreakerVacuum | GL-GND TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0409 | BreakerVacuum | GL-GND TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0409 | BreakerVacuum | GL-GND TR 1 | VCB Readings | Amps C Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0409 | BreakerVacuum | GL-GND TR 1 | VCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0409 | BreakerVacuum | GL-GND TR 1 | VCB Readings | Amps A Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0409 | BreakerVacuum | GL-GND TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0409 | BreakerVacuum | GL-GND TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1262 | BreakerVacuum | GL-1336 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Readings | Operations This Read Vac | 29 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Readings | Operations Counter AL | 104 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Readings | Operations Counter AF | 104 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Readings | Amps A Ø | 0.0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1262 | BreakerVacuum | GL-1336 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1262 | BreakerVacuum | GL-1336 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1262 | BreakerVacuum | GL-1336 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1262 | BreakerVacuum | GL-1336 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1262 | BreakerVacuum | GL-1336 | VCB Readings | Amps C Ø | 392.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1262 | BreakerVacuum | GL-1336 | VCB Readings | Amps B Ø | 406.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1262 | BreakerVacuum | GL-1336 | VCB Readings | Amps A Ø | 413.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | ST000603 | Structure | TE-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | ST000603 | Structure | TE-Structure | Structure Patrol Inspection | Interruptrs/Puffrs Visual OK? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000233 | Switchgear | 830-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000233 | Switchgear | 830-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000233 | Switchgear | 830-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000233 | Switchgear | 830-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000233 | Switchgear | 830-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000233 | Switchgear | 830-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000233 | Switchgear | 830-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | ST000603 | Structure | TE-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | ST000603 | Structure | TE-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | ST000603 | Structure | TE-Structure | Structure Patrol Inspection | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | ST000603 | Structure | TE-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | ST000603 | Structure | TE-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | ST000603 | Structure | TE-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | ST000603 | Structure | TE-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | ST000603 | Structure | TE-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000233 | Switchgear | 830-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000233 | Switchgear | 830-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000233 | Switchgear | 830-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000233 | Switchgear | 830-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000233 | Switchgear | 830-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000233 | Switchgear | 830-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000233 | Switchgear | 830-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000233 | Switchgear | 830-Swgr Sec 1 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | ST000603 | Structure | TE-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | ST000603 | Structure | TE-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | ST000603 | Structure | TE-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0993 | BreakerAirMagnetic | TE-1242 | AMCB Readings | Amps B Ø | 54.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0993 | BreakerAirMagnetic | TE-1242 | AMCB Readings | Amps A Ø | 48.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0993 | BreakerAirMagnetic | TE-1242 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0993 | BreakerAirMagnetic | TE-1242 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0409 | BreakerVacuum | GL-GND TR 1 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0409 | BreakerVacuum | GL-GND TR 1 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0409 | BreakerVacuum | GL-GND TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0409 | BreakerVacuum | GL-GND TR 1 | VCB Readings | Operations Counter AL | 126 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1262 | BreakerVacuum | GL-1336 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1262 | BreakerVacuum | GL-1336 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1262 | BreakerVacuum | GL-1336 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1262 | BreakerVacuum | GL-1336 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000233 | Switchgear | 830-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000233 | Switchgear | 830-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000233 | Switchgear | 830-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | SWG000233 | Switchgear | 830-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Readings | 9 Month Operations | 16 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0399 | BreakerVacuum | GL-1332-1 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0399 | BreakerVacuum | GL-1332-1 | VCB Readings | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0399 | BreakerVacuum | GL-1332-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0399 | BreakerVacuum | GL-1332-1 | VCB Readings | Operations Counter AF | 232 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0399 | BreakerVacuum | GL-1332-1 | VCB Readings | Operations Counter AL | 232 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0399 | BreakerVacuum | GL-1332-1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0399 | BreakerVacuum | GL-1332-1 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0399 | BreakerVacuum | GL-1332-1 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 32 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 32 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.5 | psi |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Readings | General Comments | | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Readings | Amps C Ø | 0.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Readings | Amps A Ø | 0.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Readings | H2 Winding Temp Present | 42 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Readings | H2 Winding Temp Max | 42 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0488 | WithLTC | 897-1 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | WithLTC | GL-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Readings | Maintenance Operations | 29 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Readings | Amps C Ø | 0.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Readings | General Comments | | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BCH001303 | Charger | 669-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BCH001303 | Charger | 669-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BCH001303 | Charger | 669-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BCH001303 | Charger | 669-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BCH001303 | Charger | 669-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.4 | amps |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BCH001303 | Charger | 669-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53 | VDC |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BCH001303 | Charger | 669-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53 | VDC |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BCH001303 | Charger | 669-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0 | millivolts |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Readings | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Readings | Maintenance Operations | 14 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Readings | Operations Counter AF | 111 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Readings | Operations Counter AL | 111 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Readings | Operations This Read Vac | 14 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002297 | BreakerVacuum | 830-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002301 | BreakerVacuum | 830-0411 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | WithLTC | GL-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Readings | Amps A Ø | 81.0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Readings | Amps B Ø | 48.0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Readings | Amps C Ø | 16.0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Readings | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Readings | Operations Counter AF | 386 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Readings | Operations Counter AL | 387 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Readings | Operations This Read Vac | 1 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Readings | Switching Operations | 1 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Readings | Operations Counter AL | 292 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Readings | Operations Counter AF | 292 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0298 | GroundTransformer | GL-GND TR 3 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0298 | GroundTransformer | GL-GND TR 3 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0298 | GroundTransformer | GL-GND TR 3 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0298 | GroundTransformer | GL-GND TR 3 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0298 | GroundTransformer | GL-GND TR 3 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0298 | GroundTransformer | GL-GND TR 3 | Ground Transformer Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0298 | GroundTransformer | GL-GND TR 3 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0298 | GroundTransformer | GL-GND TR 3 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0298 | GroundTransformer | GL-GND TR 3 | Ground Transformer Patrol Inspection | Oil Temp Max | 35 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0298 | GroundTransformer | GL-GND TR 3 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0298 | GroundTransformer | GL-GND TR 3 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0298 | GroundTransformer | GL-GND TR 3 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0298 | GroundTransformer | GL-GND TR 3 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0298 | GroundTransformer | GL-GND TR 3 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0298 | GroundTransformer | GL-GND TR 3 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Readings | Amps A Ø | 134.0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Readings | 9 Month Operations | 1 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0995 | BreakerVacuum | TE-1244 | VCB Readings | 9 Month Operations | 3 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0995 | BreakerVacuum | TE-1244 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0995 | BreakerVacuum | TE-1244 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0995 | BreakerVacuum | TE-1244 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0995 | BreakerVacuum | TE-1244 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0995 | BreakerVacuum | TE-1244 | VCB Readings | Amps A Ø | 156.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0995 | BreakerVacuum | TE-1244 | VCB Readings | Amps B Ø | 140.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0995 | BreakerVacuum | TE-1244 | VCB Readings | Amps C Ø | 232.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0995 | BreakerVacuum | TE-1244 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0995 | BreakerVacuum | TE-1244 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0995 | BreakerVacuum | TE-1244 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0995 | BreakerVacuum | TE-1244 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0995 | BreakerVacuum | TE-1244 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0995 | BreakerVacuum | TE-1244 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0995 | BreakerVacuum | TE-1244 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0995 | BreakerVacuum | TE-1244 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0995 | BreakerVacuum | TE-1244 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0995 | BreakerVacuum | TE-1244 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0995 | BreakerVacuum | TE-1244 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0995 | BreakerVacuum | TE-1244 | VCB Readings | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0995 | BreakerVacuum | TE-1244 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0995 | BreakerVacuum | TE-1244 | VCB Readings | Operations Counter AF | 599 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0995 | BreakerVacuum | TE-1244 | VCB Readings | Operations Counter AL | 599 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0995 | BreakerVacuum | TE-1244 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0995 | BreakerVacuum | TE-1244 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0995 | BreakerVacuum | TE-1244 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | KRC000414 | RegulatorControl | 897-1 | Regulator Annual Control Inspection | VRR X Compensation AL | 0 | Position |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | KRC000414 | RegulatorControl | 897-1 | Regulator Annual Control Inspection | VRR X Compensation AF | 0 | Position |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | KRC000414 | RegulatorControl | 897-1 | Regulator Annual Control Inspection | VRR Time Delay | 30 | Seconds |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | KRC000414 | RegulatorControl | 897-1 | Regulator Annual Control Inspection | VRR R Compensation AL | 0 | Position |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | KRC000414 | RegulatorControl | 897-1 | Regulator Annual Control Inspection | VRR R Compensation AF | 0 | Position |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | KRC000414 | RegulatorControl | 897-1 | Regulator Annual Control Inspection | VRR Counter AL | 144631 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | KRC000414 | RegulatorControl | 897-1 | Regulator Annual Control Inspection | VRR Counter AF | 144631 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | KRC000414 | RegulatorControl | 897-1 | Regulator Annual Control Inspection | VRR Base Voltage AL | 124.0 | VAC |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | KRC000414 | RegulatorControl | 897-1 | Regulator Annual Control Inspection | VRR Base Voltage AF | 124.0 | VAC |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | KRC000414 | RegulatorControl | 897-1 | Regulator Annual Control Inspection | VRR Bandwidth AL | 3.0 | VAC |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | KRC000414 | RegulatorControl | 897-1 | Regulator Annual Control Inspection | VRR Bandwidth AF | 3.0 | VAC |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | KRC000414 | RegulatorControl | 897-1 | Regulator Annual Control Inspection | Reset Tap Drag Hands | Reset | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | KRC000414 | RegulatorControl | 897-1 | Regulator Annual Control Inspection | Min Tap Position | 8L | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | KRC000414 | RegulatorControl | 897-1 | Regulator Annual Control Inspection | Max Tap Position | 3R | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | KRC000414 | RegulatorControl | 897-1 | Regulator Annual Control Inspection | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | KRC000414 | RegulatorControl | 897-1 | Regulator Annual Control Inspection | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | KRC000414 | RegulatorControl | 897-1 | Regulator Annual Control Inspection | FCP Lower AL | 0.0 | VAC |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | KRC000414 | RegulatorControl | 897-1 | Regulator Annual Control Inspection | FCP Lower AF | 0.0 | VAC |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | KRC000414 | RegulatorControl | 897-1 | Regulator Annual Control Inspection | FCP Block Raise AL | 0.0 | VAC |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | KRC000414 | RegulatorControl | 897-1 | Regulator Annual Control Inspection | FCP Block Raise AF | 0.0 | VAC |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | KRC000414 | RegulatorControl | 897-1 | Regulator Annual Control Inspection | Current Tap Position | 4L | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | KRC000414 | RegulatorControl | 897-1 | Regulator Annual Control Inspection | All Connections OK? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Readings | 9 Month Operations | 1 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0044 | BreakerVacuum | 897-2508 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0407 | BreakerVacuum | GL-14KV TR 1 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | YD000590 | Yard | GL-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | YD000590 | Yard | GL-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | YD000590 | Yard | GL-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | YD000590 | Yard | GL-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | YD000590 | Yard | GL-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | YD000590 | Yard | GL-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | YD000590 | Yard | GL-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | YD000590 | Yard | GL-Yard | Yard Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | YD000590 | Yard | GL-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | YD000590 | Yard | GL-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | YD000590 | Yard | GL-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | YD000590 | Yard | GL-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | YD000590 | Yard | GL-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | YD000590 | Yard | GL-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | YD000590 | Yard | GL-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | YD000590 | Yard | GL-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | YD000590 | Yard | GL-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | YD000590 | Yard | GL-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | ST000585 | Structure | GL-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | ST000585 | Structure | GL-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | ST000585 | Structure | GL-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | ST000585 | Structure | GL-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | ST000585 | Structure | GL-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | ST000585 | Structure | GL-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | ST000585 | Structure | GL-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | ST000585 | Structure | GL-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | ST000585 | Structure | GL-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | ST000585 | Structure | GL-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | ST000585 | Structure | GL-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | ST000585 | Structure | GL-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | ST000585 | Structure | GL-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | ST000585 | Structure | GL-Structure | Structure Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | ST000585 | Structure | GL-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | ST000585 | Structure | GL-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | ST000585 | Structure | GL-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | ST000585 | Structure | GL-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | ST000585 | Structure | GL-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | ST000585 | Structure | GL-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | ST000585 | Structure | GL-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | ST000585 | Structure | GL-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | FE000586 | Fence | GL-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | FE000586 | Fence | GL-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | FE000586 | Fence | GL-Fence | Fence Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | FE000586 | Fence | GL-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | FE000586 | Fence | GL-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | FE000586 | Fence | GL-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | FE000586 | Fence | GL-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | FE000586 | Fence | GL-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | FE000586 | Fence | GL-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | FE000586 | Fence | GL-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | FE000586 | Fence | GL-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | FE000586 | Fence | GL-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | FE000586 | Fence | GL-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | FE000586 | Fence | GL-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | FE000586 | Fence | GL-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0298 | GroundTransformer | GL-GND TR 3 | Ground Transformer Patrol Inspection | Winding Temp Max | 35 | °C |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Readings | General Comments | | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Readings | Amps C Ø | 190 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Readings | Amps B Ø | 175 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Readings | Amps A Ø | 160 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Readings | Accumulated Fault Duty C Ph V | .77 | % |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Readings | Accumulated Fault Duty B Ph V | .77 | % |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Readings | Accumulated Fault Duty A Ph V | 1.54 | % |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0094 | BreakerVacuum | 669-0420 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0407 | BreakerVacuum | GL-14KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0407 | BreakerVacuum | GL-14KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0407 | BreakerVacuum | GL-14KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0407 | BreakerVacuum | GL-14KV TR 1 | VCB Readings | Operations Counter AL | 226 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0407 | BreakerVacuum | GL-14KV TR 1 | VCB Readings | Operations Counter AF | 226 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0407 | BreakerVacuum | GL-14KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0407 | BreakerVacuum | GL-14KV TR 1 | VCB Readings | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0407 | BreakerVacuum | GL-14KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0407 | BreakerVacuum | GL-14KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0407 | BreakerVacuum | GL-14KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0407 | BreakerVacuum | GL-14KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0407 | BreakerVacuum | GL-14KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0407 | BreakerVacuum | GL-14KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0407 | BreakerVacuum | GL-14KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0407 | BreakerVacuum | GL-14KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0407 | BreakerVacuum | GL-14KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0407 | BreakerVacuum | GL-14KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0407 | BreakerVacuum | GL-14KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0407 | BreakerVacuum | GL-14KV TR 1 | VCB Readings | Amps C Ø | 266.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0407 | BreakerVacuum | GL-14KV TR 1 | VCB Readings | Amps B Ø | 236.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0407 | BreakerVacuum | GL-14KV TR 1 | VCB Readings | Amps A Ø | 262.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0407 | BreakerVacuum | GL-14KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0407 | BreakerVacuum | GL-14KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0407 | BreakerVacuum | GL-14KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0407 | BreakerVacuum | GL-14KV TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | FE000411 | Fence | 669-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | FE000411 | Fence | 669-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | FE000411 | Fence | 669-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | FE000411 | Fence | 669-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | FE000411 | Fence | 669-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | FE000411 | Fence | 669-Fence | Fence Patrol Inspection | General Comments | | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | FE000411 | Fence | 669-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | FE000411 | Fence | 669-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Readings | Switching Operations | 1 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Readings | Operations This Read Vac | 1 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Readings | Operations Counter AL | 184 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Readings | Operations Counter AF | 183 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Readings | General Comments | | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Readings | Amps C Ø | 22.0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Readings | Amps B Ø | 9.0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Readings | Amps A Ø | 14.0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001461 | BreakerVacuum | 638-2514 | VCB Readings | 9 Month Operations | 4 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Readings | Switching Operations | 1 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Readings | Operations This Read Vac | 1 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Readings | Operations Counter AL | 184 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Readings | Operations Counter AF | 183 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Readings | General Comments | | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1000 | psi |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Readings | LTC Totalizer Reading | 7927.20 | kw |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Readings | General Comments | | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | TX000262 | GroundTransformer | GL-GND TR 2 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | TX000262 | GroundTransformer | GL-GND TR 2 | Ground Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | TX000262 | GroundTransformer | GL-GND TR 2 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | TX000262 | GroundTransformer | GL-GND TR 2 | Ground Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | TX000262 | GroundTransformer | GL-GND TR 2 | Ground Transformer Patrol Inspection | Cleaned Mechanism Cabinet? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | TX000262 | GroundTransformer | GL-GND TR 2 | Ground Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | TX000262 | GroundTransformer | GL-GND TR 2 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | TX000262 | GroundTransformer | GL-GND TR 2 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | TX000262 | GroundTransformer | GL-GND TR 2 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | TX000262 | GroundTransformer | GL-GND TR 2 | Ground Transformer Patrol Inspection | Gas Accumulation Gauge | Normal | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | TX000262 | GroundTransformer | GL-GND TR 2 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | TX000262 | GroundTransformer | GL-GND TR 2 | Ground Transformer Patrol Inspection | General Comments | no nitro bottle | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | TX000262 | GroundTransformer | GL-GND TR 2 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | TX000262 | GroundTransformer | GL-GND TR 2 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | TX000262 | GroundTransformer | GL-GND TR 2 | Ground Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | TX000262 | GroundTransformer | GL-GND TR 2 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | TX000262 | GroundTransformer | GL-GND TR 2 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | TX000262 | GroundTransformer | GL-GND TR 2 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | TX000262 | GroundTransformer | GL-GND TR 2 | Ground Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | TX000262 | GroundTransformer | GL-GND TR 2 | Ground Transformer Patrol Inspection | Surge Arrester Counter A Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | TX000262 | GroundTransformer | GL-GND TR 2 | Ground Transformer Patrol Inspection | Surge Arrester Counter B Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | TX000262 | GroundTransformer | GL-GND TR 2 | Ground Transformer Patrol Inspection | Surge Arrester Counter C Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | TX000262 | GroundTransformer | GL-GND TR 2 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | TX000262 | GroundTransformer | GL-GND TR 2 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | TX000262 | GroundTransformer | GL-GND TR 2 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | FE000411 | Fence | 669-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | FE000411 | Fence | 669-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | FE000411 | Fence | 669-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | FE000411 | Fence | 669-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | FE000411 | Fence | 669-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | FE000411 | Fence | 669-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | FE000411 | Fence | 669-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | FE000411 | Fence | 669-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | FE000439 | Fence | 638-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | FE000439 | Fence | 638-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | FE000439 | Fence | 638-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | FE000439 | Fence | 638-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | FE000439 | Fence | 638-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | FE000439 | Fence | 638-Fence | Fence Patrol Inspection | General Comments | Signs need to be updated. | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | FE000439 | Fence | 638-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | FE000439 | Fence | 638-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0410 | BreakerVacuum | GL-GND TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0410 | BreakerVacuum | GL-GND TR 2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0410 | BreakerVacuum | GL-GND TR 2 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LTCC000407 | LTCControl | GL-TRANS 3 | LTC Control Insp | VRR Base Voltage AF | 117.1 | VAC |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LTCC000407 | LTCControl | GL-TRANS 3 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LTCC000407 | LTCControl | GL-TRANS 3 | LTC Control Insp | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LTCC000407 | LTCControl | GL-TRANS 3 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BX1218 | RecloserHydraulic | 638-2475 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BX1218 | RecloserHydraulic | 638-2475 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BX1218 | RecloserHydraulic | 638-2475 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BX1218 | RecloserHydraulic | 638-2475 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BX1218 | RecloserHydraulic | 638-2475 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BX1218 | RecloserHydraulic | 638-2475 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BX1218 | RecloserHydraulic | 638-2475 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BX1218 | RecloserHydraulic | 638-2475 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BX1218 | RecloserHydraulic | 638-2475 | Recloser Hydraulic Patrol Inspection | Operations Counter | 307 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BX1218 | RecloserHydraulic | 638-2475 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BX1218 | RecloserHydraulic | 638-2475 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Readings | Switching Operations | 1 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Readings | Operations This Read Vac | 1 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Readings | Operations Counter AL | 172 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Readings | Operations Counter AF | 171 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Readings | General Comments | | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Readings | Amps C Ø | 138.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001459 | BreakerVacuum | 638-2512 | VCB Readings | Amps B Ø | 136.0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0410 | BreakerVacuum | GL-GND TR 2 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0410 | BreakerVacuum | GL-GND TR 2 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0410 | BreakerVacuum | GL-GND TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0410 | BreakerVacuum | GL-GND TR 2 | VCB Readings | Operations Counter AL | 130 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0410 | BreakerVacuum | GL-GND TR 2 | VCB Readings | Operations Counter AF | 130 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0410 | BreakerVacuum | GL-GND TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0410 | BreakerVacuum | GL-GND TR 2 | VCB Readings | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0410 | BreakerVacuum | GL-GND TR 2 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0410 | BreakerVacuum | GL-GND TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0410 | BreakerVacuum | GL-GND TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0410 | BreakerVacuum | GL-GND TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0410 | BreakerVacuum | GL-GND TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Readings | Amps C Ø | 139.0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Readings | Amps B Ø | 141.0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Readings | Amps A Ø | 158.0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0410 | BreakerVacuum | GL-GND TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0410 | BreakerVacuum | GL-GND TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0410 | BreakerVacuum | GL-GND TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0410 | BreakerVacuum | GL-GND TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0410 | BreakerVacuum | GL-GND TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0410 | BreakerVacuum | GL-GND TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0410 | BreakerVacuum | GL-GND TR 2 | VCB Readings | Amps C Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0410 | BreakerVacuum | GL-GND TR 2 | VCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0410 | BreakerVacuum | GL-GND TR 2 | VCB Readings | Amps A Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0410 | BreakerVacuum | GL-GND TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0410 | BreakerVacuum | GL-GND TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BK001460 | BreakerVacuum | 638-2513 | VCB Readings | 9 Month Operations | 6 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BX1218 | RecloserHydraulic | 638-2475 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BX1218 | RecloserHydraulic | 638-2475 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0.0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | FE000439 | Fence | 638-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | FE000439 | Fence | 638-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | FE000439 | Fence | 638-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | FE000439 | Fence | 638-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | FE000439 | Fence | 638-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | FE000439 | Fence | 638-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | FE000439 | Fence | 638-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | FE000439 | Fence | 638-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | ST000450 | Structure | 897-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | ST000450 | Structure | 897-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | ST000450 | Structure | 897-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | ST000450 | Structure | 897-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | ST000450 | Structure | 897-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | ST000450 | Structure | 897-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | ST000450 | Structure | 897-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | ST000450 | Structure | 897-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | ST000450 | Structure | 897-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | ST000450 | Structure | 897-Structure | Structure Patrol Inspection | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | ST000450 | Structure | 897-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | ST000450 | Structure | 897-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | ST000450 | Structure | 897-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | LTCMechanism | TE-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | LTCMechanism | TE-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | LTCMechanism | TE-TRANS 1 | LTC Counter Readings | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | LTCMechanism | TE-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | LTCMechanism | TE-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 225872 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | LTCMechanism | TE-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 225872 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | LTCMechanism | TE-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | LTCMechanism | TE-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | LTCMechanism | TE-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | LTCMechanism | TE-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | LTCMechanism | TE-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 1685 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | LTCMechanism | TE-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | LTCMechanism | TE-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | LTCMechanism | TE-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | ST000450 | Structure | 897-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | ST000450 | Structure | 897-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | ST000450 | Structure | 897-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | ST000450 | Structure | 897-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | ST000450 | Structure | 897-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | ST000450 | Structure | 897-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | FE000444 | Fence | 897-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | FE000444 | Fence | 897-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | FE000444 | Fence | 897-Fence | Fence Patrol Inspection | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | FE000444 | Fence | 897-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | FE000444 | Fence | 897-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | FE000444 | Fence | 897-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | FE000444 | Fence | 897-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | FE000444 | Fence | 897-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | FE000444 | Fence | 897-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | FE000444 | Fence | 897-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | FE000444 | Fence | 897-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | FE000444 | Fence | 897-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | FE000444 | Fence | 897-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | FE000444 | Fence | 897-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | FE000444 | Fence | 897-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | FE000444 | Fence | 897-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1265 | BreakerVacuum | GL-1339 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1265 | BreakerVacuum | GL-1339 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | ST000403 | Structure | 830-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | ST000403 | Structure | 830-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | ST000403 | Structure | 830-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | ST000403 | Structure | 830-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | ST000403 | Structure | 830-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000101 | Switchgear | TE-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000101 | Switchgear | TE-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000101 | Switchgear | TE-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000101 | Switchgear | TE-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | CH000200 | ControlHouse | TE-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | CH000200 | ControlHouse | TE-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | CH000200 | ControlHouse | TE-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | CH000200 | ControlHouse | TE-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | CH000200 | ControlHouse | TE-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | CH000200 | ControlHouse | TE-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | CH000200 | ControlHouse | TE-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | CH000200 | ControlHouse | TE-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | CH000200 | ControlHouse | TE-Control House | Control House Patrol Inspection | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | CH000200 | ControlHouse | TE-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | CH000200 | ControlHouse | TE-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | CH000200 | ControlHouse | TE-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | CH000200 | ControlHouse | TE-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | CH000200 | ControlHouse | TE-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | CH000200 | ControlHouse | TE-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | CH000200 | ControlHouse | TE-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | CH000200 | ControlHouse | TE-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | CH000200 | ControlHouse | TE-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | CH000200 | ControlHouse | TE-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | CH000200 | ControlHouse | TE-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | CH000200 | ControlHouse | TE-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | CH000200 | ControlHouse | TE-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1002 | BreakerAirMagnetic | TE-12KV TR 1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1002 | BreakerAirMagnetic | TE-12KV TR 1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1002 | BreakerAirMagnetic | TE-12KV TR 1 | AMCB Readings | Amps C Ø | 1033.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1002 | BreakerAirMagnetic | TE-12KV TR 1 | AMCB Readings | Amps B Ø | 950.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1002 | BreakerAirMagnetic | TE-12KV TR 1 | AMCB Readings | Amps A Ø | 1003.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1002 | BreakerAirMagnetic | TE-12KV TR 1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1002 | BreakerAirMagnetic | TE-12KV TR 1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1002 | BreakerAirMagnetic | TE-12KV TR 1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1002 | BreakerAirMagnetic | TE-12KV TR 1 | AMCB Readings | 9 Months Operations | 1 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1002 | BreakerAirMagnetic | TE-12KV TR 1 | AMCB Readings | 9 Month Ops New | 1 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | LTCMechanism | TE-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | LTCMechanism | TE-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | LTCMechanism | TE-TRANS 2 | LTC Counter Readings | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | LTCMechanism | TE-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | LTCMechanism | TE-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 198374 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | LTCMechanism | TE-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 198374 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | LTCMechanism | TE-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | LTCMechanism | TE-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | LTCMechanism | TE-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | LTCMechanism | TE-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | LTCMechanism | TE-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 290 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | LTCMechanism | TE-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | LTCMechanism | TE-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | LTCMechanism | TE-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | LTCMechanism | TE-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | ST000450 | Structure | 897-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | ST000450 | Structure | 897-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | ST000450 | Structure | 897-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | ST000450 | Structure | 897-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | ST000450 | Structure | 897-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | ST000403 | Structure | 830-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | ST000403 | Structure | 830-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | YD000400 | Yard | 830-Yard Distribution | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | YD000400 | Yard | 830-Yard Distribution | Yard Patrol Inspection | Vegetation | None | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | YD000400 | Yard | 830-Yard Distribution | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | YD000400 | Yard | 830-Yard Distribution | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | YD000400 | Yard | 830-Yard Distribution | Yard Patrol Inspection | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | YD000400 | Yard | 830-Yard Distribution | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1265 | BreakerVacuum | GL-1339 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1265 | BreakerVacuum | GL-1339 | VCB Readings | Operations Counter AL | 142 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1265 | BreakerVacuum | GL-1339 | VCB Readings | Operations Counter AF | 142 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1265 | BreakerVacuum | GL-1339 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | YD000400 | Yard | 830-Yard Distribution | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | YD000400 | Yard | 830-Yard Distribution | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | YD000400 | Yard | 830-Yard Distribution | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | YD000400 | Yard | 830-Yard Distribution | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | YD000400 | Yard | 830-Yard Distribution | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1265 | BreakerVacuum | GL-1339 | VCB Readings | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1265 | BreakerVacuum | GL-1339 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1265 | BreakerVacuum | GL-1339 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1265 | BreakerVacuum | GL-1339 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1265 | BreakerVacuum | GL-1339 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1265 | BreakerVacuum | GL-1339 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1265 | BreakerVacuum | GL-1339 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1265 | BreakerVacuum | GL-1339 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1265 | BreakerVacuum | GL-1339 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1265 | BreakerVacuum | GL-1339 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1265 | BreakerVacuum | GL-1339 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1265 | BreakerVacuum | GL-1339 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1265 | BreakerVacuum | GL-1339 | VCB Readings | Amps C Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1265 | BreakerVacuum | GL-1339 | VCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1265 | BreakerVacuum | GL-1339 | VCB Readings | Amps A Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1265 | BreakerVacuum | GL-1339 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | YD000400 | Yard | 830-Yard Distribution | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | YD000400 | Yard | 830-Yard Distribution | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | YD000400 | Yard | 830-Yard Distribution | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | FE000394 | Fence | 830-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | FE000394 | Fence | 830-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | FE000394 | Fence | 830-Fence | Fence Patrol Inspection | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | FE000394 | Fence | 830-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | FE000394 | Fence | 830-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | FE000394 | Fence | 830-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | FE000394 | Fence | 830-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | FE000394 | Fence | 830-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | FE000394 | Fence | 830-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | FE000394 | Fence | 830-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | FE000394 | Fence | 830-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | FE000394 | Fence | 830-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | FE000394 | Fence | 830-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | FE000394 | Fence | 830-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | FE000394 | Fence | 830-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | FE000394 | Fence | 830-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1265 | BreakerVacuum | GL-1339 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1265 | BreakerVacuum | GL-1339 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1265 | BreakerVacuum | GL-1339 | VCB Readings | 9 Month Operations VCB New | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1265 | BreakerVacuum | GL-1339 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | ST000403 | Structure | 830-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | ST000403 | Structure | 830-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | ST000403 | Structure | 830-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | ST000403 | Structure | 830-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | ST000403 | Structure | 830-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | ST000403 | Structure | 830-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | ST000403 | Structure | 830-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | ST000403 | Structure | 830-Structure | Structure Patrol Inspection | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | ST000403 | Structure | 830-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | ST000403 | Structure | 830-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | ST000403 | Structure | 830-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Readings | General Comments | | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Readings | LTC Totalizer Reading | 9523.2 | kw |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Readings | Oil Temp Max | 80 | °C |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Readings | Totalizer Meter Reading | .992 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 65 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0412 | WithLTC | 669-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | LTCC000358 | LTCControl | 897-2 | LTC Control Insp | All Connections OK? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | LTCC000358 | LTCControl | 897-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | LTCC000358 | LTCControl | 897-2 | LTC Control Insp | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | LTCC000358 | LTCControl | 897-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | LTCC000358 | LTCControl | 897-2 | LTC Control Insp | LTC Output Voltage Level | 124.7 | VAC |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | LTCC000358 | LTCControl | 897-2 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | LTCC000358 | LTCControl | 897-2 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | LTCC000358 | LTCControl | 897-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | ST000403 | Structure | 830-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | ST000403 | Structure | 830-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | ST000403 | Structure | 830-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | ST000403 | Structure | 830-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0403 | BreakerVacuum | GL-1334-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0403 | BreakerVacuum | GL-1334-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0403 | BreakerVacuum | GL-1334-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0403 | BreakerVacuum | GL-1334-1 | VCB Readings | Amps C Ø | 89.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0403 | BreakerVacuum | GL-1334-1 | VCB Readings | Amps B Ø | 79.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0403 | BreakerVacuum | GL-1334-1 | VCB Readings | Amps A Ø | 89.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0403 | BreakerVacuum | GL-1334-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0403 | BreakerVacuum | GL-1334-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0403 | BreakerVacuum | GL-1334-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0403 | BreakerVacuum | GL-1334-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0403 | BreakerVacuum | GL-1334-1 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | LTCMechanism | GL-TRANS 3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | LTCMechanism | GL-TRANS 3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | LTCMechanism | GL-TRANS 3 | LTC Counter Readings | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | LTCMechanism | GL-TRANS 3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | LTCMechanism | GL-TRANS 3 | LTC Counter Readings | LTC As Found Counter | 25878 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | LTCMechanism | GL-TRANS 3 | LTC Counter Readings | LTC As Left Counter | 25878 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | LTCMechanism | GL-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | LTCMechanism | GL-TRANS 3 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | LTCMechanism | GL-TRANS 3 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | LTCMechanism | GL-TRANS 3 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | LTCMechanism | GL-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | LTCMechanism | GL-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 27 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | LTCMechanism | GL-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 7 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | LTCMechanism | GL-TRANS 3 | LTC Counter Readings | LTC Operations Since Last Insp | 443 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | LTCMechanism | GL-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | LTCMechanism | GL-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | LTCMechanism | GL-TRANS 3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | LTCMechanism | GL-TRANS 3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | ST000410 | Structure | 669-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | ST000410 | Structure | 669-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | ST000410 | Structure | 669-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | ST000410 | Structure | 669-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | ST000410 | Structure | 669-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | ST000410 | Structure | 669-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | ST000410 | Structure | 669-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | ST000410 | Structure | 669-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | ST000410 | Structure | 669-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | ST000410 | Structure | 669-Structure | Structure Patrol Inspection | General Comments | | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | ST000410 | Structure | 669-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | ST000410 | Structure | 669-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | ST000410 | Structure | 669-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | ST000410 | Structure | 669-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | ST000410 | Structure | 669-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | ST000410 | Structure | 669-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | ST000410 | Structure | 669-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | ST000410 | Structure | 669-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | ST000410 | Structure | 669-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | ST000410 | Structure | 669-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | ST000410 | Structure | 669-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | ST000410 | Structure | 669-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1004 | BreakerVacuum | TE-SPARE-1 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1004 | BreakerVacuum | TE-SPARE-1 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1004 | BreakerVacuum | TE-SPARE-1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1004 | BreakerVacuum | TE-SPARE-1 | VCB Readings | Operations Counter AL | 149 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1004 | BreakerVacuum | TE-SPARE-1 | VCB Readings | Operations Counter AF | 149 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | FE000586 | Fence | GL-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0403 | BreakerVacuum | GL-1334-1 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0403 | BreakerVacuum | GL-1334-1 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0403 | BreakerVacuum | GL-1334-1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0403 | BreakerVacuum | GL-1334-1 | VCB Readings | Operations Counter AL | 237 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0403 | BreakerVacuum | GL-1334-1 | VCB Readings | Operations Counter AF | 237 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0403 | BreakerVacuum | GL-1334-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0403 | BreakerVacuum | GL-1334-1 | VCB Readings | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0403 | BreakerVacuum | GL-1334-1 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0403 | BreakerVacuum | GL-1334-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0403 | BreakerVacuum | GL-1334-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0403 | BreakerVacuum | GL-1334-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0403 | BreakerVacuum | GL-1334-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0403 | BreakerVacuum | GL-1334-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0403 | BreakerVacuum | GL-1334-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | CH000175 | ControlHouse | GL-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | CH000175 | ControlHouse | GL-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | CH000175 | ControlHouse | GL-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | CH000175 | ControlHouse | GL-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | CH000175 | ControlHouse | GL-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | CH000175 | ControlHouse | GL-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | CH000175 | ControlHouse | GL-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | CH000175 | ControlHouse | GL-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | CH000175 | ControlHouse | GL-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | CH000175 | ControlHouse | GL-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | CH000175 | ControlHouse | GL-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | CH000175 | ControlHouse | GL-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | CH000175 | ControlHouse | GL-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | CH000175 | ControlHouse | GL-Control House | Control House Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | CH000175 | ControlHouse | GL-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | CH000175 | ControlHouse | GL-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | CH000175 | ControlHouse | GL-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | CH000175 | ControlHouse | GL-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | CH000175 | ControlHouse | GL-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | CH000175 | ControlHouse | GL-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | CH000175 | ControlHouse | GL-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | CH000175 | ControlHouse | GL-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000063 | Switchgear | GL-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000063 | Switchgear | GL-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000063 | Switchgear | GL-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000063 | Switchgear | GL-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000063 | Switchgear | GL-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000063 | Switchgear | GL-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000063 | Switchgear | GL-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000063 | Switchgear | GL-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000063 | Switchgear | GL-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000063 | Switchgear | GL-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000063 | Switchgear | GL-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000063 | Switchgear | GL-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000063 | Switchgear | GL-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000063 | Switchgear | GL-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000063 | Switchgear | GL-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000063 | Switchgear | GL-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000063 | Switchgear | GL-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000063 | Switchgear | GL-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0403 | BreakerVacuum | GL-1334-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1259 | BreakerVacuum | GL-14KV TR 3 | VCB Readings | Amps C Ø | 392.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1259 | BreakerVacuum | GL-14KV TR 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1259 | BreakerVacuum | GL-14KV TR 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1259 | BreakerVacuum | GL-14KV TR 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1259 | BreakerVacuum | GL-14KV TR 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1259 | BreakerVacuum | GL-14KV TR 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1259 | BreakerVacuum | GL-14KV TR 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1259 | BreakerVacuum | GL-14KV TR 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1259 | BreakerVacuum | GL-14KV TR 3 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1259 | BreakerVacuum | GL-14KV TR 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1259 | BreakerVacuum | GL-14KV TR 3 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1259 | BreakerVacuum | GL-14KV TR 3 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1259 | BreakerVacuum | GL-14KV TR 3 | VCB Readings | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1259 | BreakerVacuum | GL-14KV TR 3 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1259 | BreakerVacuum | GL-14KV TR 3 | VCB Readings | Operations Counter AF | 249 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1259 | BreakerVacuum | GL-14KV TR 3 | VCB Readings | Operations Counter AL | 249 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1259 | BreakerVacuum | GL-14KV TR 3 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1259 | BreakerVacuum | GL-14KV TR 3 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1259 | BreakerVacuum | GL-14KV TR 3 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | PF001269 | PowerFuse | GL-14KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | PF001269 | PowerFuse | GL-14KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | PF001269 | PowerFuse | GL-14KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | PF001268 | PowerFuse | GL-14KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | PF001268 | PowerFuse | GL-14KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | PF001268 | PowerFuse | GL-14KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1002 | BreakerAirMagnetic | TE-12KV TR 1 | AMCB Readings | Unknown Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1002 | BreakerAirMagnetic | TE-12KV TR 1 | AMCB Readings | Switching Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1002 | BreakerAirMagnetic | TE-12KV TR 1 | AMCB Readings | Operations This Read AM | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1002 | BreakerAirMagnetic | TE-12KV TR 1 | AMCB Readings | Operations Counter AL | 99970 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1002 | BreakerAirMagnetic | TE-12KV TR 1 | AMCB Readings | Operations Counter AF | 99970 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1002 | BreakerAirMagnetic | TE-12KV TR 1 | AMCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1002 | BreakerAirMagnetic | TE-12KV TR 1 | AMCB Readings | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1002 | BreakerAirMagnetic | TE-12KV TR 1 | AMCB Patrol Inspection | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1002 | BreakerAirMagnetic | TE-12KV TR 1 | AMCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1002 | BreakerAirMagnetic | TE-12KV TR 1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1002 | BreakerAirMagnetic | TE-12KV TR 1 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1002 | BreakerAirMagnetic | TE-12KV TR 1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1002 | BreakerAirMagnetic | TE-12KV TR 1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1002 | BreakerAirMagnetic | TE-12KV TR 1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1002 | BreakerAirMagnetic | TE-12KV TR 1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1002 | BreakerAirMagnetic | TE-12KV TR 1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000101 | Switchgear | TE-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000101 | Switchgear | TE-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000101 | Switchgear | TE-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000101 | Switchgear | TE-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000101 | Switchgear | TE-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000101 | Switchgear | TE-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000101 | Switchgear | TE-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000101 | Switchgear | TE-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000101 | Switchgear | TE-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000101 | Switchgear | TE-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000101 | Switchgear | TE-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000101 | Switchgear | TE-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000101 | Switchgear | TE-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000101 | Switchgear | TE-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000101 | Switchgear | TE-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1004 | BreakerVacuum | TE-SPARE-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1004 | BreakerVacuum | TE-SPARE-1 | VCB Readings | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1004 | BreakerVacuum | TE-SPARE-1 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1004 | BreakerVacuum | TE-SPARE-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1004 | BreakerVacuum | TE-SPARE-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1004 | BreakerVacuum | TE-SPARE-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1004 | BreakerVacuum | TE-SPARE-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1004 | BreakerVacuum | TE-SPARE-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1004 | BreakerVacuum | TE-SPARE-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1004 | BreakerVacuum | TE-SPARE-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1004 | BreakerVacuum | TE-SPARE-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1004 | BreakerVacuum | TE-SPARE-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1004 | BreakerVacuum | TE-SPARE-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1004 | BreakerVacuum | TE-SPARE-1 | VCB Readings | Amps C Ø | 0.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1004 | BreakerVacuum | TE-SPARE-1 | VCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LTCC000364 | LTCControl | TE-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LTCC000364 | LTCControl | TE-TRANS 2 | LTC Control Insp | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LTCC000364 | LTCControl | TE-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1004 | BreakerVacuum | TE-SPARE-1 | VCB Readings | Amps A Ø | 0.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1004 | BreakerVacuum | TE-SPARE-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1004 | BreakerVacuum | TE-SPARE-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1004 | BreakerVacuum | TE-SPARE-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1004 | BreakerVacuum | TE-SPARE-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1004 | BreakerVacuum | TE-SPARE-1 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1000 | BreakerAirMagnetic | TE-12KV BUS TIE SEC 1 | AMCB Readings | 9 Month Ops New | 1 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1000 | BreakerAirMagnetic | TE-12KV BUS TIE SEC 1 | AMCB Readings | 9 Months Operations | 4 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1000 | BreakerAirMagnetic | TE-12KV BUS TIE SEC 1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1000 | BreakerAirMagnetic | TE-12KV BUS TIE SEC 1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1000 | BreakerAirMagnetic | TE-12KV BUS TIE SEC 1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1000 | BreakerAirMagnetic | TE-12KV BUS TIE SEC 1 | AMCB Readings | Amps A Ø | 860.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1000 | BreakerAirMagnetic | TE-12KV BUS TIE SEC 1 | AMCB Readings | Amps B Ø | 805.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1000 | BreakerAirMagnetic | TE-12KV BUS TIE SEC 1 | AMCB Readings | Amps C Ø | 917.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1000 | BreakerAirMagnetic | TE-12KV BUS TIE SEC 1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1000 | BreakerAirMagnetic | TE-12KV BUS TIE SEC 1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1000 | BreakerAirMagnetic | TE-12KV BUS TIE SEC 1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1000 | BreakerAirMagnetic | TE-12KV BUS TIE SEC 1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1000 | BreakerAirMagnetic | TE-12KV BUS TIE SEC 1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1000 | BreakerAirMagnetic | TE-12KV BUS TIE SEC 1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1000 | BreakerAirMagnetic | TE-12KV BUS TIE SEC 1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1000 | BreakerAirMagnetic | TE-12KV BUS TIE SEC 1 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1000 | BreakerAirMagnetic | TE-12KV BUS TIE SEC 1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1000 | BreakerAirMagnetic | TE-12KV BUS TIE SEC 1 | AMCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1000 | BreakerAirMagnetic | TE-12KV BUS TIE SEC 1 | AMCB Patrol Inspection | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1000 | BreakerAirMagnetic | TE-12KV BUS TIE SEC 1 | AMCB Readings | General Comments | Hold card 488 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1000 | BreakerAirMagnetic | TE-12KV BUS TIE SEC 1 | AMCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1000 | BreakerAirMagnetic | TE-12KV BUS TIE SEC 1 | AMCB Readings | Operations Counter AF | 670 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1000 | BreakerAirMagnetic | TE-12KV BUS TIE SEC 1 | AMCB Readings | Operations Counter AL | 670 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1000 | BreakerAirMagnetic | TE-12KV BUS TIE SEC 1 | AMCB Readings | Operations This Read AM | 3 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1000 | BreakerAirMagnetic | TE-12KV BUS TIE SEC 1 | AMCB Readings | Switching Operations | 3 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1000 | BreakerAirMagnetic | TE-12KV BUS TIE SEC 1 | AMCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1259 | BreakerVacuum | GL-14KV TR 3 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1259 | BreakerVacuum | GL-14KV TR 3 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1259 | BreakerVacuum | GL-14KV TR 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1259 | BreakerVacuum | GL-14KV TR 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1259 | BreakerVacuum | GL-14KV TR 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1259 | BreakerVacuum | GL-14KV TR 3 | VCB Readings | Amps A Ø | 413.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1259 | BreakerVacuum | GL-14KV TR 3 | VCB Readings | Amps B Ø | 406.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Readings | Operations This Read Vac | 2 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Readings | Operations Counter AL | 119 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Readings | Operations Counter AF | 119 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Readings | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Readings | Amps A Ø | 132.0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Readings | Amps B Ø | 100.0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Readings | Amps C Ø | 102.0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0404 | BreakerVacuum | GL-1334-2 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0404 | BreakerVacuum | GL-1334-2 | VCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0404 | BreakerVacuum | GL-1334-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0404 | BreakerVacuum | GL-1334-2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0404 | BreakerVacuum | GL-1334-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0404 | BreakerVacuum | GL-1334-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0404 | BreakerVacuum | GL-1334-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0404 | BreakerVacuum | GL-1334-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0404 | BreakerVacuum | GL-1334-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0404 | BreakerVacuum | GL-1334-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0404 | BreakerVacuum | GL-1334-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0404 | BreakerVacuum | GL-1334-2 | VCB Readings | Amps C Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0404 | BreakerVacuum | GL-1334-2 | VCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0404 | BreakerVacuum | GL-1334-2 | VCB Readings | Amps A Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0404 | BreakerVacuum | GL-1334-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0404 | BreakerVacuum | GL-1334-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0404 | BreakerVacuum | GL-1334-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0404 | BreakerVacuum | GL-1334-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0404 | BreakerVacuum | GL-1334-2 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Readings | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Readings | Operations Counter AF | 95 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1261 | BreakerVacuum | GL-Offline-Distribution | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1261 | BreakerVacuum | GL-Offline-Distribution | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1261 | BreakerVacuum | GL-Offline-Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1261 | BreakerVacuum | GL-Offline-Distribution | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1261 | BreakerVacuum | GL-Offline-Distribution | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1261 | BreakerVacuum | GL-Offline-Distribution | VCB Readings | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1261 | BreakerVacuum | GL-Offline-Distribution | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1261 | BreakerVacuum | GL-Offline-Distribution | VCB Readings | Operations Counter AF | 114 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1261 | BreakerVacuum | GL-Offline-Distribution | VCB Readings | Operations Counter AL | 114 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1261 | BreakerVacuum | GL-Offline-Distribution | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1261 | BreakerVacuum | GL-Offline-Distribution | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1261 | BreakerVacuum | GL-Offline-Distribution | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | LTCC000350 | LTCControl | 638-1 | LTC Control Insp | All Connections OK? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | LTCC000350 | LTCControl | 638-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | LTCC000350 | LTCControl | 638-1 | LTC Control Insp | General Comments | | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | LTCC000350 | LTCControl | 638-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | LTCC000350 | LTCControl | 638-1 | LTC Control Insp | LTC Output Voltage Level | 124.1 | VAC |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | LTCC000350 | LTCControl | 638-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | LTCC000350 | LTCControl | 638-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | LTCC000350 | LTCControl | 638-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001886 | BreakerSF6 | 830-628 | GCB Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001886 | BreakerSF6 | 830-628 | GCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001886 | BreakerSF6 | 830-628 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001886 | BreakerSF6 | 830-628 | GCB Readings | Fault Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001886 | BreakerSF6 | 830-628 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0404 | BreakerVacuum | GL-1334-2 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001886 | BreakerSF6 | 830-628 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001886 | BreakerSF6 | 830-628 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001886 | BreakerSF6 | 830-628 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001886 | BreakerSF6 | 830-628 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001886 | BreakerSF6 | 830-628 | GCB Patrol Inspection | Ambient Temperature | 35 | °F |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001886 | BreakerSF6 | 830-628 | GCB Readings | 9 Month Operations GCB New | 20 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001885 | BreakerSF6 | 830-618 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001885 | BreakerSF6 | 830-618 | GCB Patrol Inspection | SF6 Pressure | 66 | psi |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001885 | BreakerSF6 | 830-618 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001885 | BreakerSF6 | 830-618 | GCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001885 | BreakerSF6 | 830-618 | GCB Patrol Inspection | General Comments | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001885 | BreakerSF6 | 830-618 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001885 | BreakerSF6 | 830-618 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001885 | BreakerSF6 | 830-618 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001885 | BreakerSF6 | 830-618 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0404 | BreakerVacuum | GL-1334-2 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0404 | BreakerVacuum | GL-1334-2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0404 | BreakerVacuum | GL-1334-2 | VCB Readings | Operations Counter AL | 213 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0404 | BreakerVacuum | GL-1334-2 | VCB Readings | Operations Counter AF | 213 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0404 | BreakerVacuum | GL-1334-2 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0404 | BreakerVacuum | GL-1334-2 | VCB Readings | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001885 | BreakerSF6 | 830-618 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001885 | BreakerSF6 | 830-618 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001885 | BreakerSF6 | 830-618 | GCB Patrol Inspection | Ambient Temperature | 35 | °F |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Readings | 9 Month Operations | 1 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Readings | Switching Operations | 2 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0401 | BreakerVacuum | GL-1333-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0401 | BreakerVacuum | GL-1333-1 | VCB Readings | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0401 | BreakerVacuum | GL-1333-1 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0401 | BreakerVacuum | GL-1333-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0401 | BreakerVacuum | GL-1333-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0401 | BreakerVacuum | GL-1333-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0401 | BreakerVacuum | GL-1333-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0401 | BreakerVacuum | GL-1333-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0401 | BreakerVacuum | GL-1333-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0401 | BreakerVacuum | GL-1333-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0401 | BreakerVacuum | GL-1333-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0401 | BreakerVacuum | GL-1333-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0401 | BreakerVacuum | GL-1333-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0401 | BreakerVacuum | GL-1333-1 | VCB Readings | Amps C Ø | 91.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0401 | BreakerVacuum | GL-1333-1 | VCB Readings | Amps B Ø | 82.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0401 | BreakerVacuum | GL-1333-1 | VCB Readings | Amps A Ø | 89.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0401 | BreakerVacuum | GL-1333-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0401 | BreakerVacuum | GL-1333-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0401 | BreakerVacuum | GL-1333-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0401 | BreakerVacuum | GL-1333-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0401 | BreakerVacuum | GL-1333-1 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000121 | Switchgear | TE-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000121 | Switchgear | TE-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000121 | Switchgear | TE-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000121 | Switchgear | TE-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000121 | Switchgear | TE-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000121 | Switchgear | TE-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000121 | Switchgear | TE-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000121 | Switchgear | TE-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000121 | Switchgear | TE-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000121 | Switchgear | TE-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000121 | Switchgear | TE-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Readings | Switching Operations | 2 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Readings | Operations This Read Vac | 2 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Readings | Operations Counter AL | 113 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Readings | Operations Counter AF | 113 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Readings | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Readings | Amps C Ø | 230.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Readings | Amps B Ø | 225.0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Readings | Operations Counter AL | 96 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Readings | Operations This Read Vac | 1 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Readings | Switching Operations | 1 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | CB0287 | BreakerVacuum | 897-2511 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BAT001443 | Battery | 638-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Readings | Amps C Ø | 265.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Readings | Amps B Ø | 285.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Readings | Amps A Ø | 245.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002213 | BreakerVacuum | 830-0410 | VCB Readings | 9 Month Operations | 2 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0398 | BreakerVacuum | GL-1331-2 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0398 | BreakerVacuum | GL-1331-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BAT001443 | Battery | 638-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 37 | °F |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BAT001443 | Battery | 638-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BAT001443 | Battery | 638-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BAT001443 | Battery | 638-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BAT001443 | Battery | 638-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Water Added | If low,note cell #~'s |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BAT001443 | Battery | 638-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BAT001443 | Battery | 638-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BAT001443 | Battery | 638-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BAT001443 | Battery | 638-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.3 | VDC |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BAT001443 | Battery | 638-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BAT001443 | Battery | 638-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | BAT001443 | Battery | 638-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0398 | BreakerVacuum | GL-1331-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0398 | BreakerVacuum | GL-1331-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0398 | BreakerVacuum | GL-1331-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0398 | BreakerVacuum | GL-1331-2 | VCB Readings | Amps A Ø | 127.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0398 | BreakerVacuum | GL-1331-2 | VCB Readings | Amps B Ø | 119.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0398 | BreakerVacuum | GL-1331-2 | VCB Readings | Amps C Ø | 124.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0398 | BreakerVacuum | GL-1331-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0398 | BreakerVacuum | GL-1331-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0398 | BreakerVacuum | GL-1331-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0398 | BreakerVacuum | GL-1331-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0398 | BreakerVacuum | GL-1331-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0398 | BreakerVacuum | GL-1331-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0401 | BreakerVacuum | GL-1333-1 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0401 | BreakerVacuum | GL-1333-1 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0401 | BreakerVacuum | GL-1333-1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0401 | BreakerVacuum | GL-1333-1 | VCB Readings | Operations Counter AL | 246 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0401 | BreakerVacuum | GL-1333-1 | VCB Readings | Operations Counter AF | 246 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1264 | BreakerVacuum | GL-GND TR 3 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1264 | BreakerVacuum | GL-GND TR 3 | VCB Readings | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1264 | BreakerVacuum | GL-GND TR 3 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1264 | BreakerVacuum | GL-GND TR 3 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1264 | BreakerVacuum | GL-GND TR 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1264 | BreakerVacuum | GL-GND TR 3 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1264 | BreakerVacuum | GL-GND TR 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1264 | BreakerVacuum | GL-GND TR 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1264 | BreakerVacuum | GL-GND TR 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1264 | BreakerVacuum | GL-GND TR 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1264 | BreakerVacuum | GL-GND TR 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1264 | BreakerVacuum | GL-GND TR 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1264 | BreakerVacuum | GL-GND TR 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1264 | BreakerVacuum | GL-GND TR 3 | VCB Readings | Amps C Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1264 | BreakerVacuum | GL-GND TR 3 | VCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1264 | BreakerVacuum | GL-GND TR 3 | VCB Readings | Amps A Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1264 | BreakerVacuum | GL-GND TR 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1264 | BreakerVacuum | GL-GND TR 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1264 | BreakerVacuum | GL-GND TR 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BCH001341 | Charger | 897-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BCH001341 | Charger | 897-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BCH001341 | Charger | 897-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BCH001341 | Charger | 897-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BCH001341 | Charger | 897-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 3.3 | amps |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BCH001341 | Charger | 897-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BCH001341 | Charger | 897-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BCH001341 | Charger | 897-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0397 | BreakerVacuum | GL-1331-1 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0397 | BreakerVacuum | GL-1331-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0397 | BreakerVacuum | GL-1331-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0397 | BreakerVacuum | GL-1331-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0397 | BreakerVacuum | GL-1331-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0397 | BreakerVacuum | GL-1331-1 | VCB Readings | Amps A Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0397 | BreakerVacuum | GL-1331-1 | VCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0397 | BreakerVacuum | GL-1331-1 | VCB Readings | Amps C Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0397 | BreakerVacuum | GL-1331-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0397 | BreakerVacuum | GL-1331-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0397 | BreakerVacuum | GL-1331-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0397 | BreakerVacuum | GL-1331-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0397 | BreakerVacuum | GL-1331-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0397 | BreakerVacuum | GL-1331-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0397 | BreakerVacuum | GL-1331-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0397 | BreakerVacuum | GL-1331-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0397 | BreakerVacuum | GL-1331-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0397 | BreakerVacuum | GL-1331-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0397 | BreakerVacuum | GL-1331-1 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0397 | BreakerVacuum | GL-1331-1 | VCB Readings | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0397 | BreakerVacuum | GL-1331-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0397 | BreakerVacuum | GL-1331-1 | VCB Readings | Operations Counter AF | 223 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0397 | BreakerVacuum | GL-1331-1 | VCB Readings | Operations Counter AL | 223 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0397 | BreakerVacuum | GL-1331-1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0397 | BreakerVacuum | GL-1331-1 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0397 | BreakerVacuum | GL-1331-1 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1264 | BreakerVacuum | GL-GND TR 3 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1264 | BreakerVacuum | GL-GND TR 3 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000192 | Switchgear | GL-Swgr Sec 3 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Readings | Operations Counter AF | 43 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Readings | Operations Counter AL | 43 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | CB0223 | BreakerVacuum | 638-1 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0998 | BreakerAirMagnetic | TE-1247 | AMCB Readings | Unknown Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0998 | BreakerAirMagnetic | TE-1247 | AMCB Readings | Switching Operations | 4 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0998 | BreakerAirMagnetic | TE-1247 | AMCB Readings | Operations This Read AM | 4 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0998 | BreakerAirMagnetic | TE-1247 | AMCB Readings | Operations Counter AL | 784 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0998 | BreakerAirMagnetic | TE-1247 | AMCB Readings | Operations Counter AF | 784 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0998 | BreakerAirMagnetic | TE-1247 | AMCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0998 | BreakerAirMagnetic | TE-1247 | AMCB Readings | General Comments | open for loading | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0998 | BreakerAirMagnetic | TE-1247 | AMCB Patrol Inspection | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0998 | BreakerAirMagnetic | TE-1247 | AMCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0998 | BreakerAirMagnetic | TE-1247 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0998 | BreakerAirMagnetic | TE-1247 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0998 | BreakerAirMagnetic | TE-1247 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0998 | BreakerAirMagnetic | TE-1247 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0998 | BreakerAirMagnetic | TE-1247 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0998 | BreakerAirMagnetic | TE-1247 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0998 | BreakerAirMagnetic | TE-1247 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0998 | BreakerAirMagnetic | TE-1247 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0998 | BreakerAirMagnetic | TE-1247 | AMCB Readings | Amps C Ø | 0.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0998 | BreakerAirMagnetic | TE-1247 | AMCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0998 | BreakerAirMagnetic | TE-1247 | AMCB Readings | Amps A Ø | 0.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0998 | BreakerAirMagnetic | TE-1247 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0998 | BreakerAirMagnetic | TE-1247 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0998 | BreakerAirMagnetic | TE-1247 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0998 | BreakerAirMagnetic | TE-1247 | AMCB Readings | 9 Months Operations | 9 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0998 | BreakerAirMagnetic | TE-1247 | AMCB Readings | 9 Month Ops New | 5 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | LTCM000033 | LTCMechanism | 669-2 | LTC Counter Readings | LTC Operations Since Last Insp | 1321 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | LTCM000033 | LTCMechanism | 669-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | LTCM000033 | LTCMechanism | 669-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | LTCM000033 | LTCMechanism | 669-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BAT001487 | Battery | 897-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BAT001487 | Battery | 897-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 34 | °F |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BAT001487 | Battery | 897-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BAT001487 | Battery | 897-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BAT001487 | Battery | 897-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BAT001487 | Battery | 897-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BAT001487 | Battery | 897-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Water Added | If low,note cell #~'s |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BAT001487 | Battery | 897-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BAT001487 | Battery | 897-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BAT001487 | Battery | 897-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BAT001487 | Battery | 897-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BAT001487 | Battery | 897-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BAT001487 | Battery | 897-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BAT001487 | Battery | 897-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1264 | BreakerVacuum | GL-GND TR 3 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1264 | BreakerVacuum | GL-GND TR 3 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1264 | BreakerVacuum | GL-GND TR 3 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1264 | BreakerVacuum | GL-GND TR 3 | VCB Readings | Operations Counter AL | 134 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1264 | BreakerVacuum | GL-GND TR 3 | VCB Readings | Operations Counter AF | 134 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Readings | Oil Temp Present | 0 | °C |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Readings | Oil Temp Max | 0 | °C |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 500 | psi |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Readings | LTC Totalizer Reading | 0.00 | kw |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Readings | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001886 | BreakerSF6 | 830-628 | GCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001886 | BreakerSF6 | 830-628 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001886 | BreakerSF6 | 830-628 | GCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001886 | BreakerSF6 | 830-628 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001886 | BreakerSF6 | 830-628 | GCB Patrol Inspection | SF6 Pressure | 66 | psi |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001886 | BreakerSF6 | 830-628 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001886 | BreakerSF6 | 830-628 | GCB Readings | Operations This Read SF6 | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001886 | BreakerSF6 | 830-628 | GCB Readings | Operations Counter AL | 146 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001886 | BreakerSF6 | 830-628 | GCB Readings | Operations Counter AF | 146 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001886 | BreakerSF6 | 830-628 | GCB Readings | Num Operations Last 9 Months | 20 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001886 | BreakerSF6 | 830-628 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001886 | BreakerSF6 | 830-628 | GCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001886 | BreakerSF6 | 830-628 | GCB Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001886 | BreakerSF6 | 830-628 | GCB Patrol Inspection | General Comments | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001886 | BreakerSF6 | 830-628 | GCB Readings | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK001886 | BreakerSF6 | 830-628 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1261 | BreakerVacuum | GL-Offline-Distribution | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1261 | BreakerVacuum | GL-Offline-Distribution | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1261 | BreakerVacuum | GL-Offline-Distribution | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1261 | BreakerVacuum | GL-Offline-Distribution | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1261 | BreakerVacuum | GL-Offline-Distribution | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1261 | BreakerVacuum | GL-Offline-Distribution | VCB Readings | Amps A Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1261 | BreakerVacuum | GL-Offline-Distribution | VCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1261 | BreakerVacuum | GL-Offline-Distribution | VCB Readings | Amps C Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1261 | BreakerVacuum | GL-Offline-Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1261 | BreakerVacuum | GL-Offline-Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1261 | BreakerVacuum | GL-Offline-Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1261 | BreakerVacuum | GL-Offline-Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1261 | BreakerVacuum | GL-Offline-Distribution | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1261 | BreakerVacuum | GL-Offline-Distribution | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000192 | Switchgear | GL-Swgr Sec 3 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000192 | Switchgear | GL-Swgr Sec 3 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000192 | Switchgear | GL-Swgr Sec 3 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000192 | Switchgear | GL-Swgr Sec 3 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000192 | Switchgear | GL-Swgr Sec 3 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000192 | Switchgear | GL-Swgr Sec 3 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000192 | Switchgear | GL-Swgr Sec 3 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000192 | Switchgear | GL-Swgr Sec 3 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000192 | Switchgear | GL-Swgr Sec 3 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000192 | Switchgear | GL-Swgr Sec 3 | Switchgear Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000192 | Switchgear | GL-Swgr Sec 3 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000192 | Switchgear | GL-Swgr Sec 3 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000192 | Switchgear | GL-Swgr Sec 3 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000192 | Switchgear | GL-Swgr Sec 3 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000192 | Switchgear | GL-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000192 | Switchgear | GL-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000192 | Switchgear | GL-Swgr Sec 3 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | SWG000192 | Switchgear | GL-Swgr Sec 3 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000124 | LTCMechanism | 830-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000124 | LTCMechanism | 830-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000124 | LTCMechanism | 830-1 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000124 | LTCMechanism | 830-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000124 | LTCMechanism | 830-1 | LTC Counter Readings | LTC Operations Since Last Insp | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000124 | LTCMechanism | 830-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 0 | °C |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000124 | LTCMechanism | 830-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 0 | °C |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000124 | LTCMechanism | 830-1 | LTC Counter Readings | LTC Min Tap Position | 16L | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000124 | LTCMechanism | 830-1 | LTC Counter Readings | LTC Max Tap Position | 16R | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000124 | LTCMechanism | 830-1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000124 | LTCMechanism | 830-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000124 | LTCMechanism | 830-1 | LTC Counter Readings | LTC As Left Counter | 1216 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000124 | LTCMechanism | 830-1 | LTC Counter Readings | LTC As Found Counter | 1216 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000124 | LTCMechanism | 830-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000124 | LTCMechanism | 830-1 | LTC Counter Readings | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000124 | LTCMechanism | 830-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000124 | LTCMechanism | 830-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCC000957 | LTCControl | 830-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCC000957 | LTCControl | 830-1 | LTC Control Insp | VRR Base Voltage AL | 0.0 | VAC |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCC000957 | LTCControl | 830-1 | LTC Control Insp | VRR Base Voltage AF | 0.0 | VAC |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCC000957 | LTCControl | 830-1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCC000957 | LTCControl | 830-1 | LTC Control Insp | LTC Output Voltage Level | 0.0 | VAC |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCC000957 | LTCControl | 830-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCC000957 | LTCControl | 830-1 | LTC Control Insp | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCC000957 | LTCControl | 830-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCC000957 | LTCControl | 830-1 | LTC Control Insp | All Connections OK? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Readings | X3 Winding Temp Present | 0 | °C |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Readings | X3 Winding Temp Max | 0 | °C |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Readings | X2 Winding Temp Present | 0 | °C |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Readings | X2 Winding Temp Max | 0 | °C |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Readings | X1 Winding Temp Present | 0 | °C |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Readings | X1 Winding Temp Max | 0 | °C |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000288 | WithLTC | 830-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Readings | Totalizer Meter Reading | .6509 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Readings | Winding Temp Max | 21 | °C |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Readings | Winding Temp Present | 21 | °C |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCC000925 | LTCControl | 830-2 | LTC Control Insp | All Connections OK? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCC000925 | LTCControl | 830-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCC000925 | LTCControl | 830-2 | LTC Control Insp | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCC000925 | LTCControl | 830-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCC000925 | LTCControl | 830-2 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCC000925 | LTCControl | 830-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCC000925 | LTCControl | 830-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCC000925 | LTCControl | 830-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000121 | LTCMechanism | 830-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000121 | LTCMechanism | 830-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000121 | LTCMechanism | 830-2 | LTC Counter Readings | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000121 | LTCMechanism | 830-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000121 | LTCMechanism | 830-2 | LTC Counter Readings | LTC As Found Counter | 2482 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000121 | LTCMechanism | 830-2 | LTC Counter Readings | LTC As Left Counter | 2482 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000121 | LTCMechanism | 830-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000121 | LTCMechanism | 830-2 | LTC Counter Readings | LTC Current Tap Position | 7R | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000121 | LTCMechanism | 830-2 | LTC Counter Readings | LTC Max Tap Position | 8R | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000121 | LTCMechanism | 830-2 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000121 | LTCMechanism | 830-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 35 | °C |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000121 | LTCMechanism | 830-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 15 | °C |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000121 | LTCMechanism | 830-2 | LTC Counter Readings | LTC Operations Since Last Insp | 589 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000121 | LTCMechanism | 830-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000121 | LTCMechanism | 830-2 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000121 | LTCMechanism | 830-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | LTCM000121 | LTCMechanism | 830-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | TR needs nitro | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Readings | H2 Winding Temp Max | 32 | °C |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Readings | H2 Winding Temp Present | 10 | °C |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.5 | psi |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | LTCMechanism | GL-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | LTCMechanism | GL-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | LTCMechanism | GL-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | LTCMechanism | GL-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 1291 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | LTCMechanism | GL-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | LTCMechanism | GL-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | LTCMechanism | GL-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | LTCMechanism | GL-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | LTCMechanism | GL-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 101875 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | LTCMechanism | GL-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 101875 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | LTCMechanism | GL-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | LTCMechanism | GL-TRANS 1 | LTC Counter Readings | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | LTCMechanism | GL-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | LTCMechanism | GL-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | LTCMechanism | GL-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | LTCMechanism | GL-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | LTCMechanism | GL-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | LTCMechanism | GL-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | LTCMechanism | GL-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 37 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | LTCMechanism | GL-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | LTCMechanism | GL-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | LTCMechanism | GL-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | LTCMechanism | GL-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | LTCMechanism | GL-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 34174 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | LTCMechanism | GL-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 34174 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | LTCMechanism | GL-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | LTCMechanism | GL-TRANS 2 | LTC Counter Readings | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | LTCMechanism | GL-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0083 | LTCMechanism | GL-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Readings | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Readings | LTC Totalizer Reading | 15621.60 | kw |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1000 | psi |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Readings | Oil Temp Max | 20 | °C |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | TX000285 | WithLTC | 830-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LTCC000445 | LTCControl | GL-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LTCC000445 | LTCControl | GL-TRANS 2 | LTC Control Insp | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LTCC000445 | LTCControl | GL-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LTCC000445 | LTCControl | GL-TRANS 2 | LTC Control Insp | VRR Base Voltage AF | 116.9 | VAC |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Readings | General Comments | | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 2582.4 | kw |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .807 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LTCC000446 | LTCControl | GL-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LTCC000446 | LTCControl | GL-TRANS 1 | LTC Control Insp | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LTCC000446 | LTCControl | GL-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LTCC000446 | LTCControl | GL-TRANS 1 | LTC Control Insp | VRR Base Voltage AF | 116.4 | VAC |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Readings | Winding Temp Present | 20 | °C |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Readings | Winding Temp Max | 20 | °C |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Readings | Totalizer Meter Reading | .4404 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Readings | Oil Temp Present | 26 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | KT0050 | WithLTC | 638-1 | LTC Transformer Readings | Oil Temp Max | 26 | °C |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 15 | °C |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 100.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 25 | °C |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 5 | °C |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 47 | °C |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 22 | °C |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 39 | °C |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0192 | WithLTC | TE-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 17 | °C |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | TR needs nitro | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 68 | °C |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 59 | °C |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 80 | °C |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 50 | °C |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 50 | °C |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LT0193 | WithLTC | TE-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 45 | °C |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | B0274 | NonLTC | 669-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Readings | 9 Month Operations | 2 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Readings | Operations Counter AL | 113 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Readings | Operations Counter AF | 113 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Readings | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Readings | Amps C Ø | 0.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Readings | Amps A Ø | 0.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002210 | BreakerVacuum | 830-0398 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Readings | Operations Counter AL | 113 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Readings | Operations Counter AF | 113 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Readings | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000121 | Switchgear | TE-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000121 | Switchgear | TE-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000121 | Switchgear | TE-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000121 | Switchgear | TE-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Readings | Amps A Ø | 235.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002212 | BreakerVacuum | 830-0400 | VCB Readings | 9 Month Operations | 2 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0398 | BreakerVacuum | GL-1331-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0398 | BreakerVacuum | GL-1331-2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0398 | BreakerVacuum | GL-1331-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0398 | BreakerVacuum | GL-1331-2 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0398 | BreakerVacuum | GL-1331-2 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0398 | BreakerVacuum | GL-1331-2 | VCB Readings | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0398 | BreakerVacuum | GL-1331-2 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0398 | BreakerVacuum | GL-1331-2 | VCB Readings | Operations Counter AF | 187 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0398 | BreakerVacuum | GL-1331-2 | VCB Readings | Operations Counter AL | 187 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0398 | BreakerVacuum | GL-1331-2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0398 | BreakerVacuum | GL-1331-2 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0398 | BreakerVacuum | GL-1331-2 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000121 | Switchgear | TE-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000121 | Switchgear | TE-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000121 | Switchgear | TE-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | SWG000121 | Switchgear | TE-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Readings | Operations This Read Vac | 2 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Readings | Operations Counter AL | 118 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Readings | Operations Counter AF | 118 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Readings | Maintenance Operations | 2 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Readings | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0406 | BreakerVacuum | GL-1335-2 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0406 | BreakerVacuum | GL-1335-2 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0406 | BreakerVacuum | GL-1335-2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0406 | BreakerVacuum | GL-1335-2 | VCB Readings | Operations Counter AL | 209 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0406 | BreakerVacuum | GL-1335-2 | VCB Readings | Operations Counter AF | 209 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0406 | BreakerVacuum | GL-1335-2 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Readings | Amps C Ø | 0.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Readings | Amps A Ø | 0.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002211 | BreakerVacuum | 830-0399 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0406 | BreakerVacuum | GL-1335-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0406 | BreakerVacuum | GL-1335-2 | VCB Readings | Amps C Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0406 | BreakerVacuum | GL-1335-2 | VCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0406 | BreakerVacuum | GL-1335-2 | VCB Readings | Amps A Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0406 | BreakerVacuum | GL-1335-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0406 | BreakerVacuum | GL-1335-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0406 | BreakerVacuum | GL-1335-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0406 | BreakerVacuum | GL-1335-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0406 | BreakerVacuum | GL-1335-2 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1292 | BreakerVacuum | GL-14KV BUS TIE SEC 1 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1292 | BreakerVacuum | GL-14KV BUS TIE SEC 1 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1292 | BreakerVacuum | GL-14KV BUS TIE SEC 1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1292 | BreakerVacuum | GL-14KV BUS TIE SEC 1 | VCB Readings | Operations Counter AL | 144 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1292 | BreakerVacuum | GL-14KV BUS TIE SEC 1 | VCB Readings | Operations Counter AF | 144 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1292 | BreakerVacuum | GL-14KV BUS TIE SEC 1 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1292 | BreakerVacuum | GL-14KV BUS TIE SEC 1 | VCB Readings | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1292 | BreakerVacuum | GL-14KV BUS TIE SEC 1 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1292 | BreakerVacuum | GL-14KV BUS TIE SEC 1 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1292 | BreakerVacuum | GL-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1292 | BreakerVacuum | GL-14KV BUS TIE SEC 1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1292 | BreakerVacuum | GL-14KV BUS TIE SEC 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1292 | BreakerVacuum | GL-14KV BUS TIE SEC 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1292 | BreakerVacuum | GL-14KV BUS TIE SEC 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1292 | BreakerVacuum | GL-14KV BUS TIE SEC 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1292 | BreakerVacuum | GL-14KV BUS TIE SEC 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1292 | BreakerVacuum | GL-14KV BUS TIE SEC 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1292 | BreakerVacuum | GL-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1292 | BreakerVacuum | GL-14KV BUS TIE SEC 1 | VCB Readings | Amps C Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1292 | BreakerVacuum | GL-14KV BUS TIE SEC 1 | VCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1292 | BreakerVacuum | GL-14KV BUS TIE SEC 1 | VCB Readings | Amps A Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1292 | BreakerVacuum | GL-14KV BUS TIE SEC 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1292 | BreakerVacuum | GL-14KV BUS TIE SEC 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1292 | BreakerVacuum | GL-14KV BUS TIE SEC 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1292 | BreakerVacuum | GL-14KV BUS TIE SEC 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1292 | BreakerVacuum | GL-14KV BUS TIE SEC 1 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0996 | BreakerVacuum | TE-1245 | VCB Readings | Amps B Ø | 125.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0996 | BreakerVacuum | TE-1245 | VCB Readings | Amps C Ø | 147.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0996 | BreakerVacuum | TE-1245 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0996 | BreakerVacuum | TE-1245 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0996 | BreakerVacuum | TE-1245 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0996 | BreakerVacuum | TE-1245 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0996 | BreakerVacuum | TE-1245 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0996 | BreakerVacuum | TE-1245 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0996 | BreakerVacuum | TE-1245 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0996 | BreakerVacuum | TE-1245 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0996 | BreakerVacuum | TE-1245 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0996 | BreakerVacuum | TE-1245 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0996 | BreakerVacuum | TE-1245 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0996 | BreakerVacuum | TE-1245 | VCB Readings | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0996 | BreakerVacuum | TE-1245 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0996 | BreakerVacuum | TE-1245 | VCB Readings | Operations Counter AF | 446 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0996 | BreakerVacuum | TE-1245 | VCB Readings | Operations Counter AL | 446 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0996 | BreakerVacuum | TE-1245 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0996 | BreakerVacuum | TE-1245 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0996 | BreakerVacuum | TE-1245 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0084 | LTCMechanism | GL-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Readings | Amps C Ø | 0.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Readings | Amps A Ø | 0.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002209 | BreakerVacuum | 830-BT2-1 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0996 | BreakerVacuum | TE-1245 | VCB Readings | 9 Month Operations | 9 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0996 | BreakerVacuum | TE-1245 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0996 | BreakerVacuum | TE-1245 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0996 | BreakerVacuum | TE-1245 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0996 | BreakerVacuum | TE-1245 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0996 | BreakerVacuum | TE-1245 | VCB Readings | Amps A Ø | 162.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Readings | Operations Counter AL | 114 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Readings | Operations Counter AF | 114 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Readings | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Readings | Amps C Ø | 490.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Readings | Amps B Ø | 515.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Readings | Amps A Ø | 480.0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:03 | Distribution | Hoover 1 Quarterly Inspection | BK002208 | BreakerVacuum | 830-2 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0406 | BreakerVacuum | GL-1335-2 | VCB Readings | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0406 | BreakerVacuum | GL-1335-2 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0406 | BreakerVacuum | GL-1335-2 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0406 | BreakerVacuum | GL-1335-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0406 | BreakerVacuum | GL-1335-2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0406 | BreakerVacuum | GL-1335-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0406 | BreakerVacuum | GL-1335-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0406 | BreakerVacuum | GL-1335-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0406 | BreakerVacuum | GL-1335-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0406 | BreakerVacuum | GL-1335-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0406 | BreakerVacuum | GL-1335-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BAT000372 | Battery | 669-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0 | VDC |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BAT000372 | Battery | 669-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0997 | BreakerVacuum | TE-1246 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0997 | BreakerVacuum | TE-1246 | VCB Readings | Switching Operations | 10 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0997 | BreakerVacuum | TE-1246 | VCB Readings | Operations This Read Vac | 10 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0997 | BreakerVacuum | TE-1246 | VCB Readings | Operations Counter AL | 270 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Readings | Amps C Ø | 394.0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Readings | Amps B Ø | 354.0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Readings | Amps A Ø | 455.0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Readings | 9 Month Operations | 1 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0997 | BreakerVacuum | TE-1246 | VCB Readings | Operations Counter AF | 270 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0997 | BreakerVacuum | TE-1246 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0997 | BreakerVacuum | TE-1246 | VCB Readings | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0997 | BreakerVacuum | TE-1246 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0997 | BreakerVacuum | TE-1246 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BAT000372 | Battery | 669-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BAT000372 | Battery | 669-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BAT000372 | Battery | 669-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000026 | Regulator | 669-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000026 | Regulator | 669-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000026 | Regulator | 669-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000026 | Regulator | 669-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000026 | Regulator | 669-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000026 | Regulator | 669-1 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0997 | BreakerVacuum | TE-1246 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0997 | BreakerVacuum | TE-1246 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000026 | Regulator | 669-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0997 | BreakerVacuum | TE-1246 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0997 | BreakerVacuum | TE-1246 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0997 | BreakerVacuum | TE-1246 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0997 | BreakerVacuum | TE-1246 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0997 | BreakerVacuum | TE-1246 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0997 | BreakerVacuum | TE-1246 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0997 | BreakerVacuum | TE-1246 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0997 | BreakerVacuum | TE-1246 | VCB Readings | Amps C Ø | 238.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0997 | BreakerVacuum | TE-1246 | VCB Readings | Amps B Ø | 253.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0997 | BreakerVacuum | TE-1246 | VCB Readings | Amps A Ø | 255.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0997 | BreakerVacuum | TE-1246 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0997 | BreakerVacuum | TE-1246 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1260 | BreakerVacuum | GL-14KV BUS TIE SEC 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1260 | BreakerVacuum | GL-14KV BUS TIE SEC 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1260 | BreakerVacuum | GL-14KV BUS TIE SEC 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1260 | BreakerVacuum | GL-14KV BUS TIE SEC 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1260 | BreakerVacuum | GL-14KV BUS TIE SEC 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1260 | BreakerVacuum | GL-14KV BUS TIE SEC 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0997 | BreakerVacuum | TE-1246 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0997 | BreakerVacuum | TE-1246 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0997 | BreakerVacuum | TE-1246 | VCB Readings | 9 Month Operations | 10 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BAT000372 | Battery | 669-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BAT000372 | Battery | 669-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BAT000372 | Battery | 669-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BAT000372 | Battery | 669-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BAT000372 | Battery | 669-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BAT000372 | Battery | 669-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 35 | °F |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BAT000372 | Battery | 669-Battery Bank | Battery Patrol Inspection | Bat Volt 1Min After Chgr Trip | 48.5 | VDC |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BAT000372 | Battery | 669-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000026 | Regulator | 669-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000026 | Regulator | 669-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000026 | Regulator | 669-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000026 | Regulator | 669-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000026 | Regulator | 669-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124 | volts |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000026 | Regulator | 669-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 26634 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000026 | Regulator | 669-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000026 | Regulator | 669-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0396 | BreakerVacuum | GL-1330-2 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0396 | BreakerVacuum | GL-1330-2 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Readings | Amps C Ø | 75 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Readings | Amps B Ø | 125 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Readings | Amps A Ø | 90 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Readings | Accumulated Fault Duty C Ph V | .7 | % |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Readings | Accumulated Fault Duty B Ph V | 3.14 | % |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Readings | Accumulated Fault Duty A Ph V | 2.45 | % |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Readings | 9 Month Operations | 4 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | PF000377 | PowerFuse | TE-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | PF000377 | PowerFuse | TE-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | PF000377 | PowerFuse | TE-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | PF000378 | PowerFuse | TE-12KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | PF000378 | PowerFuse | TE-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | PF000378 | PowerFuse | TE-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000025 | Regulator | 669-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 26597 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000025 | Regulator | 669-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000025 | Regulator | 669-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | ST000445 | Structure | 638-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | ST000445 | Structure | 638-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | ST000445 | Structure | 638-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000025 | Regulator | 669-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000025 | Regulator | 669-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000026 | Regulator | 669-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000026 | Regulator | 669-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000026 | Regulator | 669-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000026 | Regulator | 669-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000026 | Regulator | 669-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1260 | BreakerVacuum | GL-14KV BUS TIE SEC 3 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1260 | BreakerVacuum | GL-14KV BUS TIE SEC 3 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1260 | BreakerVacuum | GL-14KV BUS TIE SEC 3 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000026 | Regulator | 669-1 B | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000026 | Regulator | 669-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | BCH001071 | Charger | TE-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.9 | VDC |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | BCH001071 | Charger | TE-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | BCH001071 | Charger | TE-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.9 | VDC |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1260 | BreakerVacuum | GL-14KV BUS TIE SEC 3 | VCB Readings | Operations Counter AL | 197 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1260 | BreakerVacuum | GL-14KV BUS TIE SEC 3 | VCB Readings | Operations Counter AF | 197 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1260 | BreakerVacuum | GL-14KV BUS TIE SEC 3 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1260 | BreakerVacuum | GL-14KV BUS TIE SEC 3 | VCB Readings | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1260 | BreakerVacuum | GL-14KV BUS TIE SEC 3 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1260 | BreakerVacuum | GL-14KV BUS TIE SEC 3 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1260 | BreakerVacuum | GL-14KV BUS TIE SEC 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1260 | BreakerVacuum | GL-14KV BUS TIE SEC 3 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1260 | BreakerVacuum | GL-14KV BUS TIE SEC 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | BCH001071 | Charger | TE-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 3.4 | amps |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | BCH001071 | Charger | TE-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | BCH001071 | Charger | TE-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | BCH001071 | Charger | TE-Battery Charger | Battery Charger Patrol Insp | General Comments | The voltage 1 mintue after trip is 126.5 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | BCH001071 | Charger | TE-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BAT000372 | Battery | 669-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BAT000372 | Battery | 669-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BAT000372 | Battery | 669-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0 | VDC |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1340 | BreakerVacuum | GL-1330-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1340 | BreakerVacuum | GL-1330-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1340 | BreakerVacuum | GL-1330-1 | VCB Readings | Amps C Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1340 | BreakerVacuum | GL-1330-1 | VCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1340 | BreakerVacuum | GL-1330-1 | VCB Readings | Amps A Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1340 | BreakerVacuum | GL-1330-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1340 | BreakerVacuum | GL-1330-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1340 | BreakerVacuum | GL-1330-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1340 | BreakerVacuum | GL-1330-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1340 | BreakerVacuum | GL-1330-1 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Readings | Switching Operations | 1 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Readings | Operations This Read Vac | 1 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Readings | Operations Counter AL | 344 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0994 | BreakerAirMagnetic | TE-1243 | AMCB Readings | Unknown Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0994 | BreakerAirMagnetic | TE-1243 | AMCB Readings | Switching Operations | 1 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0994 | BreakerAirMagnetic | TE-1243 | AMCB Readings | Operations This Read AM | 1 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | YD000616 | Yard | TE-Yard | Yard Patrol Inspection | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | YD000616 | Yard | TE-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | YD000616 | Yard | TE-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | YD000616 | Yard | TE-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | YD000616 | Yard | TE-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | YD000616 | Yard | TE-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | YD000616 | Yard | TE-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0994 | BreakerAirMagnetic | TE-1243 | AMCB Readings | Operations Counter AL | 654 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0994 | BreakerAirMagnetic | TE-1243 | AMCB Readings | Operations Counter AF | 654 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0994 | BreakerAirMagnetic | TE-1243 | AMCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0994 | BreakerAirMagnetic | TE-1243 | AMCB Readings | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0994 | BreakerAirMagnetic | TE-1243 | AMCB Patrol Inspection | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0994 | BreakerAirMagnetic | TE-1243 | AMCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0994 | BreakerAirMagnetic | TE-1243 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0994 | BreakerAirMagnetic | TE-1243 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0994 | BreakerAirMagnetic | TE-1243 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0994 | BreakerAirMagnetic | TE-1243 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0994 | BreakerAirMagnetic | TE-1243 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0994 | BreakerAirMagnetic | TE-1243 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0994 | BreakerAirMagnetic | TE-1243 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0994 | BreakerAirMagnetic | TE-1243 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0994 | BreakerAirMagnetic | TE-1243 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0994 | BreakerAirMagnetic | TE-1243 | AMCB Readings | Amps C Ø | 94.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0994 | BreakerAirMagnetic | TE-1243 | AMCB Readings | Amps B Ø | 101.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0994 | BreakerAirMagnetic | TE-1243 | AMCB Readings | Amps A Ø | 124.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0994 | BreakerAirMagnetic | TE-1243 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0994 | BreakerAirMagnetic | TE-1243 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0994 | BreakerAirMagnetic | TE-1243 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0994 | BreakerAirMagnetic | TE-1243 | AMCB Readings | 9 Months Operations | 3 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0994 | BreakerAirMagnetic | TE-1243 | AMCB Readings | 9 Month Ops New | 2 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Readings | Operations Counter AF | 343 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Readings | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | PF000379 | PowerFuse | TE-STA SER NO 2 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | PF000379 | PowerFuse | TE-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | PF000379 | PowerFuse | TE-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Readings | Amps C Ø | 218.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0396 | BreakerVacuum | GL-1330-2 | VCB Readings | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0396 | BreakerVacuum | GL-1330-2 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0396 | BreakerVacuum | GL-1330-2 | VCB Readings | Operations Counter AF | 236 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Readings | Operations Counter AL | 222 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Readings | Operations This Read Vac | 1 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000026 | Regulator | 669-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Readings | Switching Operations | 1 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0396 | BreakerVacuum | GL-1330-2 | VCB Readings | Operations Counter AL | 236 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0396 | BreakerVacuum | GL-1330-2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0396 | BreakerVacuum | GL-1330-2 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0396 | BreakerVacuum | GL-1330-2 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | YD000443 | Yard | 638-Yard | Yard Patrol Inspection | Ambient Temp | 37 | °F |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1260 | BreakerVacuum | GL-14KV BUS TIE SEC 3 | VCB Readings | Amps C Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1260 | BreakerVacuum | GL-14KV BUS TIE SEC 3 | VCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1260 | BreakerVacuum | GL-14KV BUS TIE SEC 3 | VCB Readings | Amps A Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1260 | BreakerVacuum | GL-14KV BUS TIE SEC 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1260 | BreakerVacuum | GL-14KV BUS TIE SEC 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1260 | BreakerVacuum | GL-14KV BUS TIE SEC 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1260 | BreakerVacuum | GL-14KV BUS TIE SEC 3 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1260 | BreakerVacuum | GL-14KV BUS TIE SEC 3 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0400 | BreakerVacuum | GL-1332-2 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0400 | BreakerVacuum | GL-1332-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0400 | BreakerVacuum | GL-1332-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0400 | BreakerVacuum | GL-1332-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0400 | BreakerVacuum | GL-1332-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0400 | BreakerVacuum | GL-1332-2 | VCB Readings | Amps A Ø | 167.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0400 | BreakerVacuum | GL-1332-2 | VCB Readings | Amps B Ø | 157.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0400 | BreakerVacuum | GL-1332-2 | VCB Readings | Amps C Ø | 156.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0400 | BreakerVacuum | GL-1332-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0400 | BreakerVacuum | GL-1332-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000026 | Regulator | 669-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0400 | BreakerVacuum | GL-1332-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0400 | BreakerVacuum | GL-1332-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0400 | BreakerVacuum | GL-1332-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0400 | BreakerVacuum | GL-1332-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0400 | BreakerVacuum | GL-1332-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0400 | BreakerVacuum | GL-1332-2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0400 | BreakerVacuum | GL-1332-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0400 | BreakerVacuum | GL-1332-2 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0400 | BreakerVacuum | GL-1332-2 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0400 | BreakerVacuum | GL-1332-2 | VCB Readings | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0400 | BreakerVacuum | GL-1332-2 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0400 | BreakerVacuum | GL-1332-2 | VCB Readings | Operations Counter AF | 29 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0400 | BreakerVacuum | GL-1332-2 | VCB Readings | Operations Counter AL | 29 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0400 | BreakerVacuum | GL-1332-2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0400 | BreakerVacuum | GL-1332-2 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | YD000616 | Yard | TE-Yard | Yard Patrol Inspection | Ambient Temp | 36 | °F |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | YD000616 | Yard | TE-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | YD000616 | Yard | TE-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | YD000616 | Yard | TE-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | YD000616 | Yard | TE-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | YD000616 | Yard | TE-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | YD000616 | Yard | TE-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | YD000616 | Yard | TE-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | YD000616 | Yard | TE-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1340 | BreakerVacuum | GL-1330-1 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1340 | BreakerVacuum | GL-1330-1 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1340 | BreakerVacuum | GL-1330-1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1340 | BreakerVacuum | GL-1330-1 | VCB Readings | Operations Counter AL | 73 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1340 | BreakerVacuum | GL-1330-1 | VCB Readings | Operations Counter AF | 73 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1340 | BreakerVacuum | GL-1330-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1340 | BreakerVacuum | GL-1330-1 | VCB Readings | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1340 | BreakerVacuum | GL-1330-1 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1340 | BreakerVacuum | GL-1330-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1340 | BreakerVacuum | GL-1330-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1340 | BreakerVacuum | GL-1330-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | YD000616 | Yard | TE-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1340 | BreakerVacuum | GL-1330-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1340 | BreakerVacuum | GL-1330-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1340 | BreakerVacuum | GL-1330-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1340 | BreakerVacuum | GL-1330-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB1340 | BreakerVacuum | GL-1330-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Readings | Amps C Ø | 205 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Readings | Amps B Ø | 150 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Readings | Amps A Ø | 210 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Readings | Accumulated Fault Duty C Ph V | 2.1 | % |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Readings | Operations Counter AF | 277 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Readings | Operations Counter AL | 277 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Readings | General Comments | | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Readings | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Readings | Operations Counter AF | 193 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Readings | Operations Counter AL | 194 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Readings | Operations This Read Vac | 1 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Readings | Switching Operations | 1 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001249 | BreakerVacuum | 897-1 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0396 | BreakerVacuum | GL-1330-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0396 | BreakerVacuum | GL-1330-2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0396 | BreakerVacuum | GL-1330-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0396 | BreakerVacuum | GL-1330-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0396 | BreakerVacuum | GL-1330-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Readings | Amps C Ø | 60 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Readings | Amps B Ø | 55 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Readings | Amps A Ø | 45 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Readings | Accumulated Fault Duty C Ph V | 1.05 | % |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Readings | Accumulated Fault Duty A Ph V | 1.05 | % |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Readings | Operations Counter AF | 275 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Readings | Operations Counter AL | 275 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Readings | Accumulated Fault Duty B Ph V | 4.19 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0396 | BreakerVacuum | GL-1330-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0396 | BreakerVacuum | GL-1330-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Readings | Accumulated Fault Duty A Ph V | 5.24 | % |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Readings | 9 Month Operations | 2 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0396 | BreakerVacuum | GL-1330-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0396 | BreakerVacuum | GL-1330-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0396 | BreakerVacuum | GL-1330-2 | VCB Readings | Amps C Ø | 155.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0396 | BreakerVacuum | GL-1330-2 | VCB Readings | Amps B Ø | 158.0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | KB0060 | BreakerVacuum | 669-0426 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Readings | Accumulated Fault Duty B Ph V | .77 | % |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Readings | Accumulated Fault Duty C Ph V | .77 | % |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Readings | Amps A Ø | 110 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Readings | Operations Counter AF | 221 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Readings | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Readings | Amps B Ø | 125 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Readings | Amps C Ø | 75 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Readings | General Comments | | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | K0095 | BreakerVacuum | 669-0421 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001127 | BreakerVacuum | 897-BT1-2 | VCB Readings | 9 Month Operations | 5 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | ST000445 | Structure | 638-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | ST000445 | Structure | 638-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | ST000445 | Structure | 638-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1350 | psi |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | ST000445 | Structure | 638-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Readings | General Comments | | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | ST000445 | Structure | 638-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | ST000445 | Structure | 638-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | ST000445 | Structure | 638-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000025 | Regulator | 669-1 C | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | YD000449 | Yard | 897-Yard Distribution | Yard Patrol Inspection | Ambient Temp | 34 | °F |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | YD000449 | Yard | 897-Yard Distribution | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | YD000449 | Yard | 897-Yard Distribution | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | YD000449 | Yard | 897-Yard Distribution | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | YD000449 | Yard | 897-Yard Distribution | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000025 | Regulator | 669-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000025 | Regulator | 669-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000025 | Regulator | 669-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | YD000449 | Yard | 897-Yard Distribution | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | YD000449 | Yard | 897-Yard Distribution | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | YD000449 | Yard | 897-Yard Distribution | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | YD000449 | Yard | 897-Yard Distribution | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | YD000449 | Yard | 897-Yard Distribution | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | YD000449 | Yard | 897-Yard Distribution | Yard Patrol Inspection | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | YD000449 | Yard | 897-Yard Distribution | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | YD000449 | Yard | 897-Yard Distribution | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000025 | Regulator | 669-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000025 | Regulator | 669-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123 | volts |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | YD000449 | Yard | 897-Yard Distribution | Yard Patrol Inspection | Vegetation | None | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | YD000449 | Yard | 897-Yard Distribution | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Readings | Operations Counter AL | 195 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Readings | Operations Counter AF | 195 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Readings | General Comments | | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001035 | BreakerVacuum | 669-0425 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0396 | BreakerVacuum | GL-1330-2 | VCB Readings | Amps A Ø | 160.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0396 | BreakerVacuum | GL-1330-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0396 | BreakerVacuum | GL-1330-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0396 | BreakerVacuum | GL-1330-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0396 | BreakerVacuum | GL-1330-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0396 | BreakerVacuum | GL-1330-2 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Readings | General Comments | | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Readings | Operations Counter AF | 204 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Readings | Operations Counter AL | 204 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000024 | Regulator | 669-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000024 | Regulator | 669-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000024 | Regulator | 669-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000024 | Regulator | 669-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000024 | Regulator | 669-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000024 | Regulator | 669-1 A | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000024 | Regulator | 669-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000024 | Regulator | 669-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | BK001036 | BreakerVacuum | 669-0427 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000024 | Regulator | 669-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000024 | Regulator | 669-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000024 | Regulator | 669-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000024 | Regulator | 669-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000024 | Regulator | 669-1 A | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000024 | Regulator | 669-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000024 | Regulator | 669-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000024 | Regulator | 669-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000024 | Regulator | 669-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000024 | Regulator | 669-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000024 | Regulator | 669-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123 | volts |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000024 | Regulator | 669-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 28107 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000024 | Regulator | 669-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000024 | Regulator | 669-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000024 | Regulator | 669-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000024 | Regulator | 669-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000025 | Regulator | 669-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000025 | Regulator | 669-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000025 | Regulator | 669-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000025 | Regulator | 669-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000025 | Regulator | 669-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000025 | Regulator | 669-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000025 | Regulator | 669-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000025 | Regulator | 669-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000025 | Regulator | 669-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000025 | Regulator | 669-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000025 | Regulator | 669-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000025 | Regulator | 669-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | RG000025 | Regulator | 669-1 C | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | ST000445 | Structure | 638-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | ST000445 | Structure | 638-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | ST000445 | Structure | 638-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | ST000445 | Structure | 638-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | ST000445 | Structure | 638-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | ST000445 | Structure | 638-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | ST000445 | Structure | 638-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | ST000445 | Structure | 638-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | ST000445 | Structure | 638-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | ST000445 | Structure | 638-Structure | Structure Patrol Inspection | General Comments | | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | ST000445 | Structure | 638-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | ST000445 | Structure | 638-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Present | 20 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Max | 40 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Present | 20 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Max | 40 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Present | 20 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0293 | WithLTC | GL-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Max | 40 | °C |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1003 | BreakerVacuum | TE-12KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1003 | BreakerVacuum | TE-12KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1003 | BreakerVacuum | TE-12KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1003 | BreakerVacuum | TE-12KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1003 | BreakerVacuum | TE-12KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1003 | BreakerVacuum | TE-12KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1003 | BreakerVacuum | TE-12KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1003 | BreakerVacuum | TE-12KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1003 | BreakerVacuum | TE-12KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1003 | BreakerVacuum | TE-12KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1003 | BreakerVacuum | TE-12KV TR 2 | VCB Readings | Amps C Ø | 875.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0408 | BreakerVacuum | GL-14KV TR 2 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0408 | BreakerVacuum | GL-14KV TR 2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0408 | BreakerVacuum | GL-14KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0408 | BreakerVacuum | GL-14KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0408 | BreakerVacuum | GL-14KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0408 | BreakerVacuum | GL-14KV TR 2 | VCB Readings | Amps A Ø | 460.0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | LTCC000744 | LTCControl | 669-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | LTCC000744 | LTCControl | 669-2 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | LTCC000744 | LTCControl | 669-2 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0408 | BreakerVacuum | GL-14KV TR 2 | VCB Readings | Amps B Ø | 440.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0408 | BreakerVacuum | GL-14KV TR 2 | VCB Readings | Amps C Ø | 441.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0408 | BreakerVacuum | GL-14KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0408 | BreakerVacuum | GL-14KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0408 | BreakerVacuum | GL-14KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0408 | BreakerVacuum | GL-14KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | LTCC000744 | LTCControl | 669-2 | LTC Control Insp | LTC Output Voltage Level | 123 | VAC |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | LTCC000744 | LTCControl | 669-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | LTCC000744 | LTCControl | 669-2 | LTC Control Insp | General Comments | | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | LTCC000744 | LTCControl | 669-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | LTCC000744 | LTCControl | 669-2 | LTC Control Insp | All Connections OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0408 | BreakerVacuum | GL-14KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0408 | BreakerVacuum | GL-14KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0408 | BreakerVacuum | GL-14KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0408 | BreakerVacuum | GL-14KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0408 | BreakerVacuum | GL-14KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0408 | BreakerVacuum | GL-14KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0999 | BreakerVacuum | TE-1248 | VCB Readings | Switching Operations | 8 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0999 | BreakerVacuum | TE-1248 | VCB Readings | Operations This Read Vac | 8 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0999 | BreakerVacuum | TE-1248 | VCB Readings | Operations Counter AL | 315 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0999 | BreakerVacuum | TE-1248 | VCB Readings | Operations Counter AF | 315 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0999 | BreakerVacuum | TE-1248 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0999 | BreakerVacuum | TE-1248 | VCB Readings | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0999 | BreakerVacuum | TE-1248 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0999 | BreakerVacuum | TE-1248 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0999 | BreakerVacuum | TE-1248 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0999 | BreakerVacuum | TE-1248 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0999 | BreakerVacuum | TE-1248 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0999 | BreakerVacuum | TE-1248 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0999 | BreakerVacuum | TE-1248 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0999 | BreakerVacuum | TE-1248 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0999 | BreakerVacuum | TE-1248 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0999 | BreakerVacuum | TE-1248 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0999 | BreakerVacuum | TE-1248 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0999 | BreakerVacuum | TE-1248 | VCB Readings | Amps C Ø | 250.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0999 | BreakerVacuum | TE-1248 | VCB Readings | Amps B Ø | 239.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0999 | BreakerVacuum | TE-1248 | VCB Readings | Amps A Ø | 230.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0408 | BreakerVacuum | GL-14KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0408 | BreakerVacuum | GL-14KV TR 2 | VCB Readings | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0408 | BreakerVacuum | GL-14KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0999 | BreakerVacuum | TE-1248 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0408 | BreakerVacuum | GL-14KV TR 2 | VCB Readings | Operations Counter AF | 184 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0408 | BreakerVacuum | GL-14KV TR 2 | VCB Readings | Operations Counter AL | 184 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0408 | BreakerVacuum | GL-14KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0408 | BreakerVacuum | GL-14KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0408 | BreakerVacuum | GL-14KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | YD000408 | Yard | 669-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | YD000408 | Yard | 669-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | YD000408 | Yard | 669-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | YD000408 | Yard | 669-Yard | Yard Patrol Inspection | General Comments | | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | YD000408 | Yard | 669-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | YD000408 | Yard | 669-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | YD000408 | Yard | 669-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0255 | GroundTransformer | GL-GND TR 1 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0255 | GroundTransformer | GL-GND TR 1 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0999 | BreakerVacuum | TE-1248 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0405 | BreakerVacuum | GL-1335-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0405 | BreakerVacuum | GL-1335-1 | VCB Readings | Amps A Ø | 91.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0405 | BreakerVacuum | GL-1335-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0405 | BreakerVacuum | GL-1335-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0405 | BreakerVacuum | GL-1335-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0405 | BreakerVacuum | GL-1335-1 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | PF000114 | PowerFuse | GL-14KV TR 3 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | PF000114 | PowerFuse | GL-14KV TR 3 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | PF000114 | PowerFuse | GL-14KV TR 3 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | PF000113 | PowerFuse | GL-STA SER NO 3 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | PF000113 | PowerFuse | GL-STA SER NO 3 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | PF000113 | PowerFuse | GL-STA SER NO 3 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | PF000112 | PowerFuse | GL-14KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | PF000112 | PowerFuse | GL-14KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | PF000112 | PowerFuse | GL-14KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | PF000110 | PowerFuse | GL-14KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | PF000110 | PowerFuse | GL-14KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | PF000110 | PowerFuse | GL-14KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | YD000616 | Yard | TE-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | YD000616 | Yard | TE-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | PF000109 | PowerFuse | GL-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | PF000109 | PowerFuse | GL-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | PF000109 | PowerFuse | GL-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Readings | 9 Month Operations | 2 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0999 | BreakerVacuum | TE-1248 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Readings | Amps A Ø | 59.0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Readings | Amps B Ø | 63.0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Readings | Amps C Ø | 56.0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Readings | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Readings | LTC Totalizer Reading | 8991.36 | kw |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Readings | Oil Temp Max | 48 | °C |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0255 | GroundTransformer | GL-GND TR 1 | Ground Transformer Patrol Inspection | Winding Temp Max | 25 | °C |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0255 | GroundTransformer | GL-GND TR 1 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1003 | BreakerVacuum | TE-12KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0255 | GroundTransformer | GL-GND TR 1 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0255 | GroundTransformer | GL-GND TR 1 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0255 | GroundTransformer | GL-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0255 | GroundTransformer | GL-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0255 | GroundTransformer | GL-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0255 | GroundTransformer | GL-GND TR 1 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | .3 | psi |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0255 | GroundTransformer | GL-GND TR 1 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0255 | GroundTransformer | GL-GND TR 1 | Ground Transformer Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0255 | GroundTransformer | GL-GND TR 1 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0255 | GroundTransformer | GL-GND TR 1 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0255 | GroundTransformer | GL-GND TR 1 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LT0255 | GroundTransformer | GL-GND TR 1 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1003 | BreakerVacuum | TE-12KV TR 2 | VCB Readings | Switching Operations | 1 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1003 | BreakerVacuum | TE-12KV TR 2 | VCB Readings | Operations This Read Vac | 1 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1003 | BreakerVacuum | TE-12KV TR 2 | VCB Readings | Operations Counter AL | 269 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1003 | BreakerVacuum | TE-12KV TR 2 | VCB Readings | Operations Counter AF | 269 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1003 | BreakerVacuum | TE-12KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1003 | BreakerVacuum | TE-12KV TR 2 | VCB Readings | General Comments | Hold card 488 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1003 | BreakerVacuum | TE-12KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | YD000408 | Yard | 669-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | YD000408 | Yard | 669-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | YD000408 | Yard | 669-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | YD000408 | Yard | 669-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | YD000408 | Yard | 669-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | BAT001015 | Battery | TE-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | BAT001015 | Battery | TE-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/17/2023 15:07 | Distribution | Georgetown Quarterly Inspection | YD000408 | Yard | 669-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | BAT001015 | Battery | TE-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | BAT001015 | Battery | TE-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | BAT001015 | Battery | TE-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | BAT001015 | Battery | TE-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | BAT001015 | Battery | TE-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | BAT001015 | Battery | TE-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | BAT001015 | Battery | TE-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | YD000443 | Yard | 638-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | YD000443 | Yard | 638-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | YD000443 | Yard | 638-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | YD000443 | Yard | 638-Yard | Yard Patrol Inspection | General Comments | | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | YD000443 | Yard | 638-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | YD000443 | Yard | 638-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | YD000443 | Yard | 638-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | YD000443 | Yard | 638-Yard | Yard Patrol Inspection | Yard Lights Working? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | PF000111 | PowerFuse | GL-STA SER NO 2 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | PF000111 | PowerFuse | GL-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | PF000111 | PowerFuse | GL-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Readings | Totalizer Meter Reading | .9366 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | C0537 | WithLTC | 897-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | LTCM000047 | LTCMechanism | 897-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | LTCM000047 | LTCMechanism | 897-1 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | LTCM000047 | LTCMechanism | 897-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | LTCM000047 | LTCMechanism | 897-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Readings | Amps B Ø | 181.0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Readings | Amps A Ø | 248.0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | K0139 | BreakerVacuum | 897-2509 | VCB Readings | 9 Month Operations | 1 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | LTCM000047 | LTCMechanism | 897-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0400 | BreakerVacuum | GL-1332-2 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | LTCM000047 | LTCMechanism | 897-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | LTCM000047 | LTCMechanism | 897-1 | LTC Counter Readings | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | LTCM000047 | LTCMechanism | 897-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | LTCM000047 | LTCMechanism | 897-1 | LTC Counter Readings | LTC As Found Counter | 144631 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | LTCM000047 | LTCMechanism | 897-1 | LTC Counter Readings | LTC As Left Counter | 144631 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | LTCM000047 | LTCMechanism | 897-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | YD000443 | Yard | 638-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | YD000443 | Yard | 638-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | YD000443 | Yard | 638-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | BAT001015 | Battery | TE-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | BAT001015 | Battery | TE-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Readings | Switching Operations | 1 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Readings | Operations This Read Vac | 1 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Readings | Operations Counter AL | 182 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Readings | Operations Counter AF | 181 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Readings | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | YD000443 | Yard | 638-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/17/2023 14:42 | Distribution | Lagrange Penal Quarterly Inspection | YD000443 | Yard | 638-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | BAT001015 | Battery | TE-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | BK001283 | BreakerVacuum | 897-2510 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0999 | BreakerVacuum | TE-1248 | VCB Readings | 9 Month Operations | 12 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | LTCM000047 | LTCMechanism | 897-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1003 | BreakerVacuum | TE-12KV TR 2 | VCB Readings | Amps B Ø | 790.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0405 | BreakerVacuum | GL-1335-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0405 | BreakerVacuum | GL-1335-1 | VCB Readings | Amps C Ø | 89.0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0405 | BreakerVacuum | GL-1335-1 | VCB Readings | Amps B Ø | 80.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1003 | BreakerVacuum | TE-12KV TR 2 | VCB Readings | Amps A Ø | 840.0 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1003 | BreakerVacuum | TE-12KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1003 | BreakerVacuum | TE-12KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1003 | BreakerVacuum | TE-12KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0999 | BreakerVacuum | TE-1248 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1003 | BreakerVacuum | TE-12KV TR 2 | VCB Readings | 9 Month Operations VCB New | 11 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB1003 | BreakerVacuum | TE-12KV TR 2 | VCB Readings | 9 Month Operations | 12 | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | PF000380 | PowerFuse | TE-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | PF000380 | PowerFuse | TE-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | PF000380 | PowerFuse | TE-12KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 13:47 | Distribution | Terry Quarterly Inspection | LB0999 | BreakerVacuum | TE-1248 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | LTCM000047 | LTCMechanism | 897-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | LTCM000047 | LTCMechanism | 897-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0405 | BreakerVacuum | GL-1335-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0405 | BreakerVacuum | GL-1335-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0405 | BreakerVacuum | GL-1335-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0405 | BreakerVacuum | GL-1335-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0405 | BreakerVacuum | GL-1335-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0405 | BreakerVacuum | GL-1335-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0405 | BreakerVacuum | GL-1335-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0405 | BreakerVacuum | GL-1335-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0405 | BreakerVacuum | GL-1335-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0405 | BreakerVacuum | GL-1335-1 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0405 | BreakerVacuum | GL-1335-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0405 | BreakerVacuum | GL-1335-1 | VCB Readings | Operations Counter AF | 246 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0405 | BreakerVacuum | GL-1335-1 | VCB Readings | Operations Counter AL | 246 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0405 | BreakerVacuum | GL-1335-1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0405 | BreakerVacuum | GL-1335-1 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 15:16 | Distribution | Grade Lane Quarterly Inspection | LB0405 | BreakerVacuum | GL-1335-1 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 12:36 | Distribution | Lagrange East Quarterly Inspection | LTCM000047 | LTCMechanism | 897-1 | LTC Counter Readings | LTC Operations Since Last Insp | 453 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | LTCMechanism | SM-TRANS 3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1272 | BreakerVacuum | SM-1387 | VCB Readings | Operations Counter AL | 143 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1272 | BreakerVacuum | SM-1387 | VCB Readings | Operations Counter AF | 143 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1272 | BreakerVacuum | SM-1387 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1272 | BreakerVacuum | SM-1387 | VCB Readings | General Comments | DNO | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1272 | BreakerVacuum | SM-1387 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1272 | BreakerVacuum | SM-1387 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1272 | BreakerVacuum | SM-1387 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | LTCMechanism | SM-TRANS 3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | LTCMechanism | SM-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | LTCMechanism | SM-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | LTCMechanism | SM-TRANS 3 | LTC Counter Readings | LTC Operations Since Last Insp | 91 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | LTCMechanism | SM-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | LTCMechanism | SM-TRANS 3 | LTC Counter Readings | LTC Min Tap Position | 4 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | LTCMechanism | SM-TRANS 3 | LTC Counter Readings | LTC Max Tap Position | 6 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | LTCMechanism | SM-TRANS 3 | LTC Counter Readings | LTC Current Tap Position | 6 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1268 | BreakerVacuum | SM-GND TR 5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1268 | BreakerVacuum | SM-GND TR 5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1268 | BreakerVacuum | SM-GND TR 5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1268 | BreakerVacuum | SM-GND TR 5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1268 | BreakerVacuum | SM-GND TR 5 | VCB Readings | Amps C Ø | 0.0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Readings | Operations Counter AL | 344 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Readings | Operations Counter AF | 343 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Readings | Amps A Ø | 277.0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1268 | BreakerVacuum | SM-GND TR 5 | VCB Readings | Amps B Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1268 | BreakerVacuum | SM-GND TR 5 | VCB Readings | Amps A Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1268 | BreakerVacuum | SM-GND TR 5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1268 | BreakerVacuum | SM-GND TR 5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1268 | BreakerVacuum | SM-GND TR 5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1268 | BreakerVacuum | SM-GND TR 5 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1268 | BreakerVacuum | SM-GND TR 5 | VCB Readings | 9 Month Operations | 1 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Readings | Unknown Operations | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Readings | Switching Operations | 1 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Readings | Operations This Read Vac | 1 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Readings | Operations Counter AL | 407 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Readings | Operations Counter AF | 406 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Readings | General Comments | | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Readings | Amps B Ø | 274.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Readings | Amps C Ø | 278.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1272 | BreakerVacuum | SM-1387 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1272 | BreakerVacuum | SM-1387 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Readings | General Comments | | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1272 | BreakerVacuum | SM-1387 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0296 | GroundTransformer | SM-GND TR 5 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | LTCMechanism | SM-TRANS 3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | LTCMechanism | SM-TRANS 3 | LTC Counter Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | LTCMechanism | SM-TRANS 3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | LTCMechanism | SM-TRANS 3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | LTCMechanism | SM-TRANS 6 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0296 | GroundTransformer | SM-GND TR 5 | Ground Transformer Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | LTCMechanism | SM-TRANS 6 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | LTCMechanism | SM-TRANS 6 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0296 | GroundTransformer | SM-GND TR 5 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0296 | GroundTransformer | SM-GND TR 5 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0296 | GroundTransformer | SM-GND TR 5 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0296 | GroundTransformer | SM-GND TR 5 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0296 | GroundTransformer | SM-GND TR 5 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1272 | BreakerVacuum | SM-1387 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | LTCMechanism | SM-TRANS 6 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | LTCMechanism | SM-TRANS 6 | LTC Counter Readings | LTC Operations Since Last Insp | 40 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | LTCMechanism | SM-TRANS 6 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1272 | BreakerVacuum | SM-1387 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1272 | BreakerVacuum | SM-1387 | VCB Readings | Amps A Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1272 | BreakerVacuum | SM-1387 | VCB Readings | Amps B Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1272 | BreakerVacuum | SM-1387 | VCB Readings | Amps C Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1272 | BreakerVacuum | SM-1387 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1272 | BreakerVacuum | SM-1387 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1272 | BreakerVacuum | SM-1387 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1272 | BreakerVacuum | SM-1387 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1272 | BreakerVacuum | SM-1387 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1272 | BreakerVacuum | SM-1387 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1272 | BreakerVacuum | SM-1387 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1272 | BreakerVacuum | SM-1387 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Readings | Amps C Ø | 0.0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Readings | Amps B Ø | 0.0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Readings | Amps A Ø | 0.0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | LTCMechanism | SM-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | LTCMechanism | SM-TRANS 3 | LTC Counter Readings | LTC As Left Counter | 226 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0148 | BreakerVacuum | 705-0726 | VCB Readings | 9 Month Operations | 1 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | LTCMechanism | SM-TRANS 3 | LTC Counter Readings | LTC As Found Counter | 226 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Readings | 9 Month Operations | 1 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Readings | Amps A Ø | 46.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Readings | Amps B Ø | 43.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Readings | Amps C Ø | 44.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0296 | GroundTransformer | SM-GND TR 5 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0296 | GroundTransformer | SM-GND TR 5 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0296 | GroundTransformer | SM-GND TR 5 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0296 | GroundTransformer | SM-GND TR 5 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Readings | 9 Month Operations | 2 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1272 | BreakerVacuum | SM-1387 | VCB Readings | 9 Month Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1272 | BreakerVacuum | SM-1387 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1266 | BreakerVacuum | SM-14KV TR 5 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1266 | BreakerVacuum | SM-14KV TR 5 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LTCM000030 | LTCMechanism | SM-TRANS 4 | LTC Counter Readings | LTC As Found Counter | 39960 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LTCM000030 | LTCMechanism | SM-TRANS 4 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LTCM000030 | LTCMechanism | SM-TRANS 4 | LTC Counter Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LTCM000030 | LTCMechanism | SM-TRANS 4 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LTCM000030 | LTCMechanism | SM-TRANS 4 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Readings | Amps A Ø | 163.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Readings | Amps B Ø | 170.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Readings | Amps C Ø | 180.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Readings | Operations Counter AF | 345 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Readings | Operations Counter AL | 345 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Readings | Unknown Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Readings | Operations Counter AF | 349 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Readings | Operations Counter AL | 349 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1266 | BreakerVacuum | SM-14KV TR 5 | VCB Readings | Operations Counter AL | 167 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Readings | Operations This Read Vac | 8 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1266 | BreakerVacuum | SM-14KV TR 5 | VCB Readings | Operations Counter AF | 167 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1266 | BreakerVacuum | SM-14KV TR 5 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1266 | BreakerVacuum | SM-14KV TR 5 | VCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1266 | BreakerVacuum | SM-14KV TR 5 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1266 | BreakerVacuum | SM-14KV TR 5 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1266 | BreakerVacuum | SM-14KV TR 5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1266 | BreakerVacuum | SM-14KV TR 5 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1266 | BreakerVacuum | SM-14KV TR 5 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1266 | BreakerVacuum | SM-14KV TR 5 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1266 | BreakerVacuum | SM-14KV TR 5 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1266 | BreakerVacuum | SM-14KV TR 5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Readings | Switching Operations | 8 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Readings | Amps A Ø | 163.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Readings | Amps B Ø | 70.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Readings | 9 Month Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LTCM000030 | LTCMechanism | SM-TRANS 4 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0822 | BreakerVacuum | SM-1396 | VCB Patrol Inspection | General Comments | ok | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0822 | BreakerVacuum | SM-1396 | VCB Readings | General Comments | DNO | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0822 | BreakerVacuum | SM-1396 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0822 | BreakerVacuum | SM-1396 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0822 | BreakerVacuum | SM-1396 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0822 | BreakerVacuum | SM-1396 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0822 | BreakerVacuum | SM-1396 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0822 | BreakerVacuum | SM-1396 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LTCM000030 | LTCMechanism | SM-TRANS 4 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Readings | 9 Month Operations | 11 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Readings | Amps C Ø | 183.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0822 | BreakerVacuum | SM-1396 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0822 | BreakerVacuum | SM-1396 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0822 | BreakerVacuum | SM-1396 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0822 | BreakerVacuum | SM-1396 | VCB Readings | Amps C Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0822 | BreakerVacuum | SM-1396 | VCB Readings | Amps B Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0822 | BreakerVacuum | SM-1396 | VCB Readings | Amps A Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0822 | BreakerVacuum | SM-1396 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0822 | BreakerVacuum | SM-1396 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0822 | BreakerVacuum | SM-1396 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0822 | BreakerVacuum | SM-1396 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0822 | BreakerVacuum | SM-1396 | VCB Readings | Operations Counter AF | 223 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0822 | BreakerVacuum | SM-1396 | VCB Readings | Operations Counter AL | 223 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0822 | BreakerVacuum | SM-1396 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0822 | BreakerVacuum | SM-1396 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0822 | BreakerVacuum | SM-1396 | VCB Readings | 9 Month Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LTCM000030 | LTCMechanism | SM-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LTCM000030 | LTCMechanism | SM-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LTCM000030 | LTCMechanism | SM-TRANS 4 | LTC Counter Readings | LTC Operations Since Last Insp | 331 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LTCM000030 | LTCMechanism | SM-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LTCM000030 | LTCMechanism | SM-TRANS 4 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LTCM000030 | LTCMechanism | SM-TRANS 4 | LTC Counter Readings | LTC Max Tap Position | 8L | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LTCM000030 | LTCMechanism | SM-TRANS 4 | LTC Counter Readings | LTC Current Tap Position | 12L | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LTCM000030 | LTCMechanism | SM-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LTCM000030 | LTCMechanism | SM-TRANS 4 | LTC Counter Readings | LTC As Left Counter | 39960 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0822 | BreakerVacuum | SM-1396 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001843 | BreakerVacuum | SM-14KV BUS TIE | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Readings | Amps C Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Readings | Amps B Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Readings | Amps A Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Readings | 9 Month Operations | 4 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Readings | Operations Counter AL | 350 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Readings | Operations Counter AF | 350 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PT002285 | PT | SM-14KV BUS SEC 1 POT | PT Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PT002285 | PT | SM-14KV BUS SEC 1 POT | PT Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PT002285 | PT | SM-14KV BUS SEC 1 POT | PT Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PT002285 | PT | SM-14KV BUS SEC 1 POT | PT Patrol Inspection | General Comments | | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Readings | Switching Operations | 1 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Readings | Operations This Read Vac | 1 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PT002285 | PT | SM-14KV BUS SEC 1 POT | PT Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PT002285 | PT | SM-14KV BUS SEC 1 POT | PT Patrol Inspection | PT Free of Leaks? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PT002285 | PT | SM-14KV BUS SEC 1 POT | PT Patrol Inspection | Tank Oil Level | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PT002285 | PT | SM-14KV BUS SEC 1 POT | PT Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001841 | BreakerVacuum | SM-14KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Readings | Operations Counter AL | 368 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Readings | Operations Counter AF | 368 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001186 | BreakerVacuum | SM-1364 | VCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1268 | BreakerVacuum | SM-GND TR 5 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1268 | BreakerVacuum | SM-GND TR 5 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1268 | BreakerVacuum | SM-GND TR 5 | VCB Readings | Operations Counter AL | 145 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1268 | BreakerVacuum | SM-GND TR 5 | VCB Readings | Operations Counter AF | 145 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1268 | BreakerVacuum | SM-GND TR 5 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1268 | BreakerVacuum | SM-GND TR 5 | VCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1268 | BreakerVacuum | SM-GND TR 5 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1268 | BreakerVacuum | SM-GND TR 5 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1268 | BreakerVacuum | SM-GND TR 5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1268 | BreakerVacuum | SM-GND TR 5 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1268 | BreakerVacuum | SM-GND TR 5 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1268 | BreakerVacuum | SM-GND TR 5 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1268 | BreakerVacuum | SM-GND TR 5 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0868 | Regulator | 705-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0868 | Regulator | 705-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0868 | Regulator | 705-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0868 | Regulator | 705-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1266 | BreakerVacuum | SM-14KV TR 5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1266 | BreakerVacuum | SM-14KV TR 5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1266 | BreakerVacuum | SM-14KV TR 5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1266 | BreakerVacuum | SM-14KV TR 5 | VCB Readings | Amps C Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1266 | BreakerVacuum | SM-14KV TR 5 | VCB Readings | Amps B Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1266 | BreakerVacuum | SM-14KV TR 5 | VCB Readings | Amps A Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1266 | BreakerVacuum | SM-14KV TR 5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1266 | BreakerVacuum | SM-14KV TR 5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1266 | BreakerVacuum | SM-14KV TR 5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1266 | BreakerVacuum | SM-14KV TR 5 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1266 | BreakerVacuum | SM-14KV TR 5 | VCB Readings | 9 Month Operations | 1 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Readings | Unknown Operations | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0868 | Regulator | 705-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 19130 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0868 | Regulator | 705-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0868 | Regulator | 705-1 A | Regulator Patrol Inspection | Reg Operation Checked? | n | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0868 | Regulator | 705-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0868 | Regulator | 705-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0868 | Regulator | 705-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0868 | Regulator | 705-1 A | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0868 | Regulator | 705-1 A | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0868 | Regulator | 705-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0868 | Regulator | 705-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0868 | Regulator | 705-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0868 | Regulator | 705-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0868 | Regulator | 705-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0868 | Regulator | 705-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0868 | Regulator | 705-1 A | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0868 | Regulator | 705-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0868 | Regulator | 705-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0868 | Regulator | 705-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0868 | Regulator | 705-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0868 | Regulator | 705-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000556 | BreakerVacuum | SM-1366 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Readings | Unknown Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Readings | Operations Counter AL | 350 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Readings | Operations Counter AF | 350 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001842 | BreakerVacuum | SM-14KV BUS TIE SEC 1-2-3 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Readings | Oil Temp Max | 60 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Readings | X1 Winding Temp Max | 50 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Readings | X1 Winding Temp Present | 40 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Readings | X2 Winding Temp Max | 50 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Readings | X2 Winding Temp Present | 40 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Readings | X3 Winding Temp Max | 48 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0163 | WithLTC | SM-TRANS 4 | LTC Transformer Readings | X3 Winding Temp Present | 40 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0820 | BreakerVacuum | SM-1393 | VCB Readings | Amps C Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0823 | BreakerVacuum | SM-1397 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0820 | BreakerVacuum | SM-1393 | VCB Readings | 9 Month Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0820 | BreakerVacuum | SM-1393 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0820 | BreakerVacuum | SM-1393 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0269 | GroundTransformer | SM-GND TR 3 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0269 | GroundTransformer | SM-GND TR 3 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0269 | GroundTransformer | SM-GND TR 3 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0269 | GroundTransformer | SM-GND TR 3 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0269 | GroundTransformer | SM-GND TR 3 | Ground Transformer Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0269 | GroundTransformer | SM-GND TR 3 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0269 | GroundTransformer | SM-GND TR 3 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0269 | GroundTransformer | SM-GND TR 3 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0269 | GroundTransformer | SM-GND TR 3 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0269 | GroundTransformer | SM-GND TR 3 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0269 | GroundTransformer | SM-GND TR 3 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0820 | BreakerVacuum | SM-1393 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0820 | BreakerVacuum | SM-1393 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0820 | BreakerVacuum | SM-1393 | VCB Readings | Amps A Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0820 | BreakerVacuum | SM-1393 | VCB Readings | Amps B Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0823 | BreakerVacuum | SM-1397 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0823 | BreakerVacuum | SM-1397 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0823 | BreakerVacuum | SM-1397 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0823 | BreakerVacuum | SM-1397 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0823 | BreakerVacuum | SM-1397 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0823 | BreakerVacuum | SM-1397 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0823 | BreakerVacuum | SM-1397 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0823 | BreakerVacuum | SM-1397 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0823 | BreakerVacuum | SM-1397 | VCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0823 | BreakerVacuum | SM-1397 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0823 | BreakerVacuum | SM-1397 | VCB Readings | Operations Counter AF | 446 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0823 | BreakerVacuum | SM-1397 | VCB Readings | Operations Counter AL | 446 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0823 | BreakerVacuum | SM-1397 | VCB Readings | Operations This Read Vac | 1 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0823 | BreakerVacuum | SM-1397 | VCB Readings | Switching Operations | 1 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.7244 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000182 | Switchgear | SM-Swgr Sec 6 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000182 | Switchgear | SM-Swgr Sec 6 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000182 | Switchgear | SM-Swgr Sec 6 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000182 | Switchgear | SM-Swgr Sec 6 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000182 | Switchgear | SM-Swgr Sec 6 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000182 | Switchgear | SM-Swgr Sec 6 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000182 | Switchgear | SM-Swgr Sec 6 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000182 | Switchgear | SM-Swgr Sec 6 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000182 | Switchgear | SM-Swgr Sec 6 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | YD000412 | Yard | 705-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | YD000412 | Yard | 705-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | YD000412 | Yard | 705-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | YD000412 | Yard | 705-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | ST000849 | Structure | 415-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | ST000849 | Structure | 415-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | ST000849 | Structure | 415-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000318 | PowerFuse | SM-14KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000318 | PowerFuse | SM-14KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000318 | PowerFuse | SM-14KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000321 | PowerFuse | SM-14KV TR 3 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000321 | PowerFuse | SM-14KV TR 3 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000321 | PowerFuse | SM-14KV TR 3 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000316 | PowerFuse | SM-GND TR 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000316 | PowerFuse | SM-GND TR 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | YD000412 | Yard | 705-Yard | Yard Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000326 | PowerFuse | SM-14KV TR 5 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000326 | PowerFuse | SM-14KV TR 5 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000326 | PowerFuse | SM-14KV TR 5 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000311 | PowerFuse | SM-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000311 | PowerFuse | SM-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000311 | PowerFuse | SM-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | YD000412 | Yard | 705-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | ST000849 | Structure | 415-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | ST000849 | Structure | 415-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | ST000849 | Structure | 415-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | ST000849 | Structure | 415-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0820 | BreakerVacuum | SM-1393 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0820 | BreakerVacuum | SM-1393 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0820 | BreakerVacuum | SM-1393 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0820 | BreakerVacuum | SM-1393 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0820 | BreakerVacuum | SM-1393 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0820 | BreakerVacuum | SM-1393 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0820 | BreakerVacuum | SM-1393 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0820 | BreakerVacuum | SM-1393 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 52.50 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 4138.56 | kw |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Readings | General Comments | | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | O0171 | NonLTC | 705-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000182 | Switchgear | SM-Swgr Sec 6 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000182 | Switchgear | SM-Swgr Sec 6 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000182 | Switchgear | SM-Swgr Sec 6 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000182 | Switchgear | SM-Swgr Sec 6 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000182 | Switchgear | SM-Swgr Sec 6 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000182 | Switchgear | SM-Swgr Sec 6 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000182 | Switchgear | SM-Swgr Sec 6 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000182 | Switchgear | SM-Swgr Sec 6 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000182 | Switchgear | SM-Swgr Sec 6 | Switchgear Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000182 | Switchgear | SM-Swgr Sec 6 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Readings | X2 Winding Temp Max | 45 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Readings | X1 Winding Temp Present | 30 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Readings | X1 Winding Temp Max | 35 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 10.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0823 | BreakerVacuum | SM-1397 | VCB Readings | 9 Month Operations | 5 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.3 | psi |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Readings | H2 Winding Temp Present | 30 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0823 | BreakerVacuum | SM-1397 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0823 | BreakerVacuum | SM-1397 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0823 | BreakerVacuum | SM-1397 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0823 | BreakerVacuum | SM-1397 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Readings | H2 Winding Temp Max | 35 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0900 | Regulator | 705-2 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0900 | Regulator | 705-2 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0900 | Regulator | 705-2 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0900 | Regulator | 705-2 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0900 | Regulator | 705-2 A | Regulator Patrol Inspection | Regulator As Left Counter | 71609 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0900 | Regulator | 705-2 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.0 | volts |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0900 | Regulator | 705-2 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | ST000414 | Structure | 705-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | ST000414 | Structure | 705-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | ST000414 | Structure | 705-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0900 | Regulator | 705-2 A | Regulator Patrol Inspection | Reg Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0900 | Regulator | 705-2 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0900 | Regulator | 705-2 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | ST000414 | Structure | 705-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | ST000414 | Structure | 705-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | ST000414 | Structure | 705-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | ST000414 | Structure | 705-Structure | Structure Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 135.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Readings | Oil Temp Present | 50 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Readings | Oil Temp Max | 70 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Readings | HV Winding Temp Present | 50 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Readings | HV Winding Temp Max | 60 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0167 | WithLTC | SM-TRANS 3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Readings | X3 Winding Temp Present | 30 | °C |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | ST000414 | Structure | 705-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | ST000414 | Structure | 705-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | ST000414 | Structure | 705-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | ST000414 | Structure | 705-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | ST000414 | Structure | 705-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | ST000414 | Structure | 705-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Readings | X3 Winding Temp Max | 30 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Readings | X2 Winding Temp Present | 30 | °C |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0900 | Regulator | 705-2 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0900 | Regulator | 705-2 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0900 | Regulator | 705-2 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BAT001324 | Battery | 415-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BAT001324 | Battery | 415-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 53 | °F |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BAT001324 | Battery | 415-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BAT001324 | Battery | 415-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BAT001324 | Battery | 415-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BAT001324 | Battery | 415-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BAT001324 | Battery | 415-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BAT001324 | Battery | 415-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BAT001324 | Battery | 415-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BAT001324 | Battery | 415-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BAT001324 | Battery | 415-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BAT001324 | Battery | 415-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BAT001324 | Battery | 415-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BAT001324 | Battery | 415-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0900 | Regulator | 705-2 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0900 | Regulator | 705-2 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Patrol Inspection | Fans Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | WithLTC | SM-TRANS 6 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0823 | BreakerVacuum | SM-1397 | VCB Readings | Amps A Ø | 280.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0823 | BreakerVacuum | SM-1397 | VCB Readings | Amps B Ø | 280.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0823 | BreakerVacuum | SM-1397 | VCB Readings | Amps C Ø | 272.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0823 | BreakerVacuum | SM-1397 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0823 | BreakerVacuum | SM-1397 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | ST000414 | Structure | 705-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | ST000414 | Structure | 705-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | ST000414 | Structure | 705-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | ST000414 | Structure | 705-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | ST000414 | Structure | 705-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | ST000414 | Structure | 705-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | ST000414 | Structure | 705-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | ST000414 | Structure | 705-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | ST000414 | Structure | 705-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | FE000407 | Fence | 705-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | FE000407 | Fence | 705-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | FE000407 | Fence | 705-Fence | Fence Patrol Inspection | General Comments | | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | FE000407 | Fence | 705-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | FE000407 | Fence | 705-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | FE000407 | Fence | 705-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | FE000407 | Fence | 705-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | FE000407 | Fence | 705-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | FE000407 | Fence | 705-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | FE000407 | Fence | 705-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | FE000407 | Fence | 705-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | FE000407 | Fence | 705-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | FE000407 | Fence | 705-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | FE000407 | Fence | 705-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | FE000407 | Fence | 705-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | FE000407 | Fence | 705-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0900 | Regulator | 705-2 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0900 | Regulator | 705-2 A | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0900 | Regulator | 705-2 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0900 | Regulator | 705-2 A | Regulator Patrol Inspection | General Comments | | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0900 | Regulator | 705-2 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0900 | Regulator | 705-2 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0900 | Regulator | 705-2 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0900 | Regulator | 705-2 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0900 | Regulator | 705-2 A | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BCH001266 | Charger | 415-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BCH001266 | Charger | 415-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BCH001266 | Charger | 415-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BCH001266 | Charger | 415-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.4 | amps |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BCH001266 | Charger | 415-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BCH001266 | Charger | 415-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BCH001266 | Charger | 415-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BCH001266 | Charger | 415-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | bottle empty | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0834 | BreakerVacuum | SM-GND TR 3 | VCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0834 | BreakerVacuum | SM-GND TR 3 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0834 | BreakerVacuum | SM-GND TR 3 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0267 | GroundTransformer | SM-GND TR 1 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0267 | GroundTransformer | SM-GND TR 1 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0267 | GroundTransformer | SM-GND TR 1 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0834 | BreakerVacuum | SM-GND TR 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0834 | BreakerVacuum | SM-GND TR 3 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0834 | BreakerVacuum | SM-GND TR 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0834 | BreakerVacuum | SM-GND TR 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0834 | BreakerVacuum | SM-GND TR 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0834 | BreakerVacuum | SM-GND TR 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0834 | BreakerVacuum | SM-GND TR 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0834 | BreakerVacuum | SM-GND TR 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0834 | BreakerVacuum | SM-GND TR 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0834 | BreakerVacuum | SM-GND TR 3 | VCB Readings | Amps C Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0834 | BreakerVacuum | SM-GND TR 3 | VCB Readings | Amps B Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0834 | BreakerVacuum | SM-GND TR 3 | VCB Readings | Amps A Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0834 | BreakerVacuum | SM-GND TR 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0834 | BreakerVacuum | SM-GND TR 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0834 | BreakerVacuum | SM-GND TR 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000313 | PowerFuse | SM-14KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000312 | PowerFuse | SM-14KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000312 | PowerFuse | SM-14KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000312 | PowerFuse | SM-14KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0267 | GroundTransformer | SM-GND TR 1 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0267 | GroundTransformer | SM-GND TR 1 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0267 | GroundTransformer | SM-GND TR 1 | Ground Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0267 | GroundTransformer | SM-GND TR 1 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0267 | GroundTransformer | SM-GND TR 1 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0267 | GroundTransformer | SM-GND TR 1 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0267 | GroundTransformer | SM-GND TR 1 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0267 | GroundTransformer | SM-GND TR 1 | Ground Transformer Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0267 | GroundTransformer | SM-GND TR 1 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0268 | GroundTransformer | SM-GND TR 2 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0268 | GroundTransformer | SM-GND TR 2 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0268 | GroundTransformer | SM-GND TR 2 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0268 | GroundTransformer | SM-GND TR 2 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0268 | GroundTransformer | SM-GND TR 2 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0268 | GroundTransformer | SM-GND TR 2 | Ground Transformer Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0268 | GroundTransformer | SM-GND TR 2 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0268 | GroundTransformer | SM-GND TR 2 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0268 | GroundTransformer | SM-GND TR 2 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0268 | GroundTransformer | SM-GND TR 2 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0268 | GroundTransformer | SM-GND TR 2 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0268 | GroundTransformer | SM-GND TR 2 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0267 | GroundTransformer | SM-GND TR 1 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 100.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0834 | BreakerVacuum | SM-GND TR 3 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0834 | BreakerVacuum | SM-GND TR 3 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0834 | BreakerVacuum | SM-GND TR 3 | VCB Readings | Operations Counter AL | 172 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0834 | BreakerVacuum | SM-GND TR 3 | VCB Readings | Operations Counter AF | 172 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0834 | BreakerVacuum | SM-GND TR 3 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | WithLTC | SM-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000082 | Switchgear | SM-Swgr Sec 3 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000082 | Switchgear | SM-Swgr Sec 3 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000082 | Switchgear | SM-Swgr Sec 3 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000082 | Switchgear | SM-Swgr Sec 3 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000082 | Switchgear | SM-Swgr Sec 3 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000082 | Switchgear | SM-Swgr Sec 3 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Readings | 9 Month Operations | 1 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | LTCMechanism | SM-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | LTCMechanism | SM-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | LTCMechanism | SM-TRANS 1 | LTC Counter Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | LTCMechanism | SM-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | LTCMechanism | SM-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 86405 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | LTCMechanism | SM-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 86405 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | LTCMechanism | SM-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | LTCMechanism | SM-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 3 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | LTCMechanism | SM-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 20 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Readings | Amps A Ø | 150.0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Readings | Amps B Ø | 135.0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Readings | Amps C Ø | 150.0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | LTCMechanism | SM-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | LTCMechanism | SM-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | LTCMechanism | SM-TRANS 6 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | LTCMechanism | SM-TRANS 6 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | LTCMechanism | SM-TRANS 6 | LTC Counter Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | LTCMechanism | SM-TRANS 6 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | LTCMechanism | SM-TRANS 6 | LTC Counter Readings | LTC As Found Counter | 43752 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | LTCMechanism | SM-TRANS 6 | LTC Counter Readings | LTC As Left Counter | 43752 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | LTCMechanism | SM-TRANS 6 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | LTCMechanism | SM-TRANS 6 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | LTCMechanism | SM-TRANS 6 | LTC Counter Readings | LTC Max Tap Position | 5L | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0166 | LTCMechanism | SM-TRANS 6 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | K0147 | BreakerVacuum | 705-0725 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0834 | BreakerVacuum | SM-GND TR 3 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0834 | BreakerVacuum | SM-GND TR 3 | VCB Readings | 9 Month Operations | 1 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | LTCC000027 | LTCControl | 415-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | LTCC000027 | LTCControl | 415-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | LTCC000027 | LTCControl | 415-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | LTCC000027 | LTCControl | 415-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | LTCC000027 | LTCControl | 415-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | LTCC000027 | LTCControl | 415-1 | LTC Control Insp | General Comments | | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | LTCC000027 | LTCControl | 415-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | LTCC000027 | LTCControl | 415-1 | LTC Control Insp | All Connections OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | LTCMechanism | SM-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | LTCMechanism | SM-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | LTCMechanism | SM-TRANS 2 | LTC Counter Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | LTCMechanism | SM-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | LTCMechanism | SM-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 24526 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | LTCMechanism | SM-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 24526 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | LTCMechanism | SM-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | LTCMechanism | SM-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 3 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | LTCMechanism | SM-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 20 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | LTCMechanism | SM-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0164 | LTCMechanism | SM-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BCH001177 | Charger | 705-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BCH001177 | Charger | 705-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BCH001177 | Charger | 705-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BCH001177 | Charger | 705-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.9 | amps |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BCH001177 | Charger | 705-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BCH001177 | Charger | 705-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BCH001177 | Charger | 705-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BCH001177 | Charger | 705-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000082 | Switchgear | SM-Swgr Sec 3 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000082 | Switchgear | SM-Swgr Sec 3 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000082 | Switchgear | SM-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000082 | Switchgear | SM-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000082 | Switchgear | SM-Swgr Sec 3 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000082 | Switchgear | SM-Swgr Sec 3 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000082 | Switchgear | SM-Swgr Sec 3 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000082 | Switchgear | SM-Swgr Sec 3 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000082 | Switchgear | SM-Swgr Sec 3 | Switchgear Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000082 | Switchgear | SM-Swgr Sec 3 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000082 | Switchgear | SM-Swgr Sec 3 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000082 | Switchgear | SM-Swgr Sec 3 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000082 | Switchgear | SM-Swgr Sec 3 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | ST000849 | Structure | 415-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | ST000849 | Structure | 415-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | ST000849 | Structure | 415-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | YD000412 | Yard | 705-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | YD000412 | Yard | 705-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | YD000412 | Yard | 705-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | YD000412 | Yard | 705-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0824 | BreakerVacuum | SM-1398 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0824 | BreakerVacuum | SM-1398 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0824 | BreakerVacuum | SM-1398 | VCB Readings | Operations Counter AL | 373 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0824 | BreakerVacuum | SM-1398 | VCB Readings | Operations Counter AF | 373 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0824 | BreakerVacuum | SM-1398 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0824 | BreakerVacuum | SM-1398 | VCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0824 | BreakerVacuum | SM-1398 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0824 | BreakerVacuum | SM-1398 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0824 | BreakerVacuum | SM-1398 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0824 | BreakerVacuum | SM-1398 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0824 | BreakerVacuum | SM-1398 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0824 | BreakerVacuum | SM-1398 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0824 | BreakerVacuum | SM-1398 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0824 | BreakerVacuum | SM-1398 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0824 | BreakerVacuum | SM-1398 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0824 | BreakerVacuum | SM-1398 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0824 | BreakerVacuum | SM-1398 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0824 | BreakerVacuum | SM-1398 | VCB Readings | Amps C Ø | 105.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0824 | BreakerVacuum | SM-1398 | VCB Readings | Amps B Ø | 99.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0824 | BreakerVacuum | SM-1398 | VCB Readings | Amps A Ø | 102.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0824 | BreakerVacuum | SM-1398 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0824 | BreakerVacuum | SM-1398 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | ST000849 | Structure | 415-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | ST000849 | Structure | 415-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | ST000849 | Structure | 415-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | ST000849 | Structure | 415-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | ST000849 | Structure | 415-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | ST000849 | Structure | 415-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | ST000849 | Structure | 415-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0824 | BreakerVacuum | SM-1398 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | FE000848 | Fence | 415-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | FE000848 | Fence | 415-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | FE000848 | Fence | 415-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | FE000848 | Fence | 415-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1000 | psi |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Readings | Oil Temp Present | 36 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Readings | X1 Winding Temp Max | 41 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Readings | X1 Winding Temp Present | 36 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Readings | X2 Winding Temp Max | 41 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Readings | X2 Winding Temp Present | 36 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Readings | X3 Winding Temp Max | 41 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | WithLTC | SM-TRANS 5 | LTC Transformer Readings | X3 Winding Temp Present | 36 | °C |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | ST000849 | Structure | 415-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | ST000849 | Structure | 415-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | ST000849 | Structure | 415-Structure | Structure Patrol Inspection | General Comments | | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | ST000849 | Structure | 415-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | YD000412 | Yard | 705-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | YD000412 | Yard | 705-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | YD000412 | Yard | 705-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | YD000412 | Yard | 705-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | YD000412 | Yard | 705-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | ST000849 | Structure | 415-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BAT001228 | Battery | 705-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BAT001228 | Battery | 705-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BAT001228 | Battery | 705-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BAT001228 | Battery | 705-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BAT001228 | Battery | 705-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0820 | BreakerVacuum | SM-1393 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0820 | BreakerVacuum | SM-1393 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0820 | BreakerVacuum | SM-1393 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0820 | BreakerVacuum | SM-1393 | VCB Readings | General Comments | DNO | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0820 | BreakerVacuum | SM-1393 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0820 | BreakerVacuum | SM-1393 | VCB Readings | Operations Counter AF | 226 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0820 | BreakerVacuum | SM-1393 | VCB Readings | Operations Counter AL | 226 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0820 | BreakerVacuum | SM-1393 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0820 | BreakerVacuum | SM-1393 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000325 | PowerFuse | SM-STA SER NO 5 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000325 | PowerFuse | SM-STA SER NO 5 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000325 | PowerFuse | SM-STA SER NO 5 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000324 | PowerFuse | SM-STA SER NO 6 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000324 | PowerFuse | SM-STA SER NO 6 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000324 | PowerFuse | SM-STA SER NO 6 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000323 | PowerFuse | SM-STA SER NO 3 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000323 | PowerFuse | SM-STA SER NO 3 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000323 | PowerFuse | SM-STA SER NO 3 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000322 | PowerFuse | SM-14KV TR 6 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000322 | PowerFuse | SM-14KV TR 6 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000322 | PowerFuse | SM-14KV TR 6 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000320 | PowerFuse | SM-14KV TR 4 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000320 | PowerFuse | SM-14KV TR 4 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000320 | PowerFuse | SM-14KV TR 4 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000319 | PowerFuse | SM-STA SER NO 4 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000319 | PowerFuse | SM-STA SER NO 4 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000319 | PowerFuse | SM-STA SER NO 4 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000317 | PowerFuse | SM-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000317 | PowerFuse | SM-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000317 | PowerFuse | SM-STA SER NO 2 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000315 | PowerFuse | SM-GND TR 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000315 | PowerFuse | SM-GND TR 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000315 | PowerFuse | SM-GND TR 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000314 | PowerFuse | SM-14KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000314 | PowerFuse | SM-14KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000313 | PowerFuse | SM-14KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | PF000313 | PowerFuse | SM-14KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | FE000848 | Fence | 415-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | FE000848 | Fence | 415-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | FE000848 | Fence | 415-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | FE000848 | Fence | 415-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | FE000848 | Fence | 415-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | FE000848 | Fence | 415-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | FE000848 | Fence | 415-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | FE000848 | Fence | 415-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | FE000848 | Fence | 415-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | FE000848 | Fence | 415-Fence | Fence Patrol Inspection | General Comments | | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | FE000848 | Fence | 415-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | FE000848 | Fence | 415-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000181 | Switchgear | SM-Swgr Sec 4 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000181 | Switchgear | SM-Swgr Sec 4 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000181 | Switchgear | SM-Swgr Sec 4 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000181 | Switchgear | SM-Swgr Sec 4 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000181 | Switchgear | SM-Swgr Sec 4 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0824 | BreakerVacuum | SM-1398 | VCB Readings | 9 Month Operations | 1 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BAT001228 | Battery | 705-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BAT001228 | Battery | 705-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BAT001228 | Battery | 705-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BAT001228 | Battery | 705-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BAT001228 | Battery | 705-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BAT001228 | Battery | 705-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BAT001228 | Battery | 705-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BAT001228 | Battery | 705-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BAT001228 | Battery | 705-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BAT001228 | Battery | 705-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000181 | Switchgear | SM-Swgr Sec 4 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000181 | Switchgear | SM-Swgr Sec 4 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000181 | Switchgear | SM-Swgr Sec 4 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000181 | Switchgear | SM-Swgr Sec 4 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000181 | Switchgear | SM-Swgr Sec 4 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000181 | Switchgear | SM-Swgr Sec 4 | Switchgear Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000181 | Switchgear | SM-Swgr Sec 4 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000181 | Switchgear | SM-Swgr Sec 4 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000181 | Switchgear | SM-Swgr Sec 4 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000181 | Switchgear | SM-Swgr Sec 4 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000181 | Switchgear | SM-Swgr Sec 4 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000181 | Switchgear | SM-Swgr Sec 4 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000181 | Switchgear | SM-Swgr Sec 4 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000181 | Switchgear | SM-Swgr Sec 4 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0817 | BreakerVacuum | SM-1380 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0817 | BreakerVacuum | SM-1380 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .8 | psi |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Readings | Totalizer Meter Reading | .2570 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0817 | BreakerVacuum | SM-1380 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0817 | BreakerVacuum | SM-1380 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0817 | BreakerVacuum | SM-1380 | VCB Readings | Operations Counter AL | 195 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0817 | BreakerVacuum | SM-1380 | VCB Readings | Operations Counter AF | 195 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0817 | BreakerVacuum | SM-1380 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0817 | BreakerVacuum | SM-1380 | VCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0817 | BreakerVacuum | SM-1380 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 100.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0165 | WithLTC | SM-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0817 | BreakerVacuum | SM-1380 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0817 | BreakerVacuum | SM-1380 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0817 | BreakerVacuum | SM-1380 | VCB Readings | Fault Operations Ground | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0817 | BreakerVacuum | SM-1380 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0817 | BreakerVacuum | SM-1380 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0817 | BreakerVacuum | SM-1380 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0817 | BreakerVacuum | SM-1380 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0817 | BreakerVacuum | SM-1380 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0817 | BreakerVacuum | SM-1380 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0817 | BreakerVacuum | SM-1380 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0817 | BreakerVacuum | SM-1380 | VCB Readings | Amps C Ø | 10.0 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | LTCMechanism | 415-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | LTCMechanism | 415-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | LTCMechanism | 415-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | LTCMechanism | 415-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | LTCMechanism | 415-1 | LTC Counter Readings | LTC Operations Since Last Insp | 62 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | LTCMechanism | 415-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | LTCMechanism | 415-1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | LTCMechanism | 415-1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | LTCMechanism | 415-1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | LTCMechanism | 415-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | LTCMechanism | 415-1 | LTC Counter Readings | LTC As Left Counter | 479798 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | LTCMechanism | 415-1 | LTC Counter Readings | LTC As Found Counter | 479798 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | LTCMechanism | 415-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | LTCMechanism | 415-1 | LTC Counter Readings | General Comments | | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | LTCMechanism | 415-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | LTCMechanism | 415-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0817 | BreakerVacuum | SM-1380 | VCB Readings | Amps B Ø | 10.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0817 | BreakerVacuum | SM-1380 | VCB Readings | Amps A Ø | 10.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0830 | BreakerVacuum | SM-14KV TR 3 | VCB Readings | Amps A Ø | 445.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0830 | BreakerVacuum | SM-14KV TR 3 | VCB Readings | Amps B Ø | 443.0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0899 | Regulator | 705-2 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0899 | Regulator | 705-2 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0899 | Regulator | 705-2 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0899 | Regulator | 705-2 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0899 | Regulator | 705-2 C | Regulator Patrol Inspection | Regulator As Left Counter | 65700 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0899 | Regulator | 705-2 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0899 | Regulator | 705-2 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0899 | Regulator | 705-2 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0899 | Regulator | 705-2 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0899 | Regulator | 705-2 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0899 | Regulator | 705-2 C | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0899 | Regulator | 705-2 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0899 | Regulator | 705-2 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0899 | Regulator | 705-2 C | Regulator Patrol Inspection | General Comments | | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0899 | Regulator | 705-2 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0899 | Regulator | 705-2 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0899 | Regulator | 705-2 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0899 | Regulator | 705-2 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0899 | Regulator | 705-2 C | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0899 | Regulator | 705-2 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0899 | Regulator | 705-2 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LTCC000421 | LTCControl | SM-TRANS 5 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LTCC000421 | LTCControl | SM-TRANS 5 | LTC Control Insp | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LTCC000421 | LTCControl | SM-TRANS 5 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0899 | Regulator | 705-2 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0899 | Regulator | 705-2 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0899 | Regulator | 705-2 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Readings | Operations Counter AL | 149 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Readings | Operations Counter AF | 149 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Readings | LTC Totalizer Reading | 1233.60 | kw |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Readings | General Comments | | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | W0309 | WithLTC | 415-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0817 | BreakerVacuum | SM-1380 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0817 | BreakerVacuum | SM-1380 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0817 | BreakerVacuum | SM-1380 | VCB Readings | 9 Month Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | LTCMechanism | SM-TRANS 5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | LTCMechanism | SM-TRANS 5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | LTCMechanism | SM-TRANS 5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | LTCMechanism | SM-TRANS 5 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | LTCMechanism | SM-TRANS 5 | LTC Counter Readings | LTC Operations Since Last Insp | 51 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | LTCMechanism | SM-TRANS 5 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | LTCMechanism | SM-TRANS 5 | LTC Counter Readings | LTC Max Tap Position | 5L | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | LTCMechanism | SM-TRANS 5 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | LTCMechanism | SM-TRANS 5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | LTCMechanism | SM-TRANS 5 | LTC Counter Readings | LTC As Left Counter | 20424 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | LTCMechanism | SM-TRANS 5 | LTC Counter Readings | LTC As Found Counter | 20424 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | LTCMechanism | SM-TRANS 5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | LTCMechanism | SM-TRANS 5 | LTC Counter Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | LTCMechanism | SM-TRANS 5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0295 | LTCMechanism | SM-TRANS 5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0830 | BreakerVacuum | SM-14KV TR 3 | VCB Readings | 9 Month Operations | 2 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0830 | BreakerVacuum | SM-14KV TR 3 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0830 | BreakerVacuum | SM-14KV TR 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0830 | BreakerVacuum | SM-14KV TR 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0830 | BreakerVacuum | SM-14KV TR 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Readings | Amps A Ø | 105.0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Readings | Amps B Ø | 100.0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Readings | Amps C Ø | 100.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1267 | BreakerVacuum | SM-14KV BUS TIE SEC 5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1267 | BreakerVacuum | SM-14KV BUS TIE SEC 5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1267 | BreakerVacuum | SM-14KV BUS TIE SEC 5 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1267 | BreakerVacuum | SM-14KV BUS TIE SEC 5 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1267 | BreakerVacuum | SM-14KV BUS TIE SEC 5 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1267 | BreakerVacuum | SM-14KV BUS TIE SEC 5 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1267 | BreakerVacuum | SM-14KV BUS TIE SEC 5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1267 | BreakerVacuum | SM-14KV BUS TIE SEC 5 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1267 | BreakerVacuum | SM-14KV BUS TIE SEC 5 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1267 | BreakerVacuum | SM-14KV BUS TIE SEC 5 | VCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1267 | BreakerVacuum | SM-14KV BUS TIE SEC 5 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1267 | BreakerVacuum | SM-14KV BUS TIE SEC 5 | VCB Readings | Operations Counter AF | 180 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1267 | BreakerVacuum | SM-14KV BUS TIE SEC 5 | VCB Readings | Operations Counter AL | 180 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1267 | BreakerVacuum | SM-14KV BUS TIE SEC 5 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1267 | BreakerVacuum | SM-14KV BUS TIE SEC 5 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0835 | BreakerVacuum | SM-GND TR 6 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0835 | BreakerVacuum | SM-GND TR 6 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0835 | BreakerVacuum | SM-GND TR 6 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0835 | BreakerVacuum | SM-GND TR 6 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0835 | BreakerVacuum | SM-GND TR 6 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0835 | BreakerVacuum | SM-GND TR 6 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0835 | BreakerVacuum | SM-GND TR 6 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Readings | Amps A Ø | 81.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Readings | 9 Month Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Readings | Operations Counter AL | 252 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Readings | Operations Counter AF | 252 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Readings | Fault Operations C Ø | 1 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Readings | Fault Adjusted Amps C Phase V | 11.18 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0593 | Regulator | 705-2 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0593 | Regulator | 705-2 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0835 | BreakerVacuum | SM-GND TR 6 | VCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0835 | BreakerVacuum | SM-GND TR 6 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0835 | BreakerVacuum | SM-GND TR 6 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0835 | BreakerVacuum | SM-GND TR 6 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0593 | Regulator | 705-2 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0593 | Regulator | 705-2 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0593 | Regulator | 705-2 B | Regulator Patrol Inspection | Regulator As Left Counter | 27298 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0593 | Regulator | 705-2 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.0 | volts |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0593 | Regulator | 705-2 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0593 | Regulator | 705-2 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0593 | Regulator | 705-2 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0593 | Regulator | 705-2 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0593 | Regulator | 705-2 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Readings | 9 Month Operations | 1 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Readings | Amps B Ø | 90.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Readings | Amps A Ø | 88.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Readings | 9 Month Operations | 4 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Readings | 9 Month Operations | 7 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Readings | Amps A Ø | 166.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Readings | Amps B Ø | 166.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Readings | Amps C Ø | 161.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Readings | Operations Counter AF | 217 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Readings | Operations Counter AL | 217 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1273 | BreakerVacuum | SM-1360 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Readings | General Comments | | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Readings | Operations Counter AF | 191 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Readings | Operations Counter AL | 192 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Readings | Operations This Read Vac | 1 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Readings | Switching Operations | 1 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001418 | BreakerVacuum | 705-0716 | VCB Readings | Unknown Operations | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0593 | Regulator | 705-2 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0593 | Regulator | 705-2 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0593 | Regulator | 705-2 B | Regulator Patrol Inspection | General Comments | | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0593 | Regulator | 705-2 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0593 | Regulator | 705-2 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0593 | Regulator | 705-2 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0593 | Regulator | 705-2 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0593 | Regulator | 705-2 B | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0593 | Regulator | 705-2 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0593 | Regulator | 705-2 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0593 | Regulator | 705-2 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0593 | Regulator | 705-2 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0593 | Regulator | 705-2 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0835 | BreakerVacuum | SM-GND TR 6 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0835 | BreakerVacuum | SM-GND TR 6 | VCB Readings | Amps C Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0835 | BreakerVacuum | SM-GND TR 6 | VCB Readings | Amps B Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0835 | BreakerVacuum | SM-GND TR 6 | VCB Readings | Amps A Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0835 | BreakerVacuum | SM-GND TR 6 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0835 | BreakerVacuum | SM-GND TR 6 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0835 | BreakerVacuum | SM-GND TR 6 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0835 | BreakerVacuum | SM-GND TR 6 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0835 | BreakerVacuum | SM-GND TR 6 | VCB Readings | 9 Month Operations | 1 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Readings | Amps C Ø | 92.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Readings | Amps C Ø | 80.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Readings | Amps B Ø | 80.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Readings | Amps A Ø | 80.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Readings | 9 Month Operations VCB New | 2 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Readings | 9 Month Operations | 2 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Readings | 9 Month Operations | 5 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Readings | Amps A Ø | 115.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Readings | Amps B Ø | 115.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Readings | Amps C Ø | 115.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0870 | Regulator | 705-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0870 | Regulator | 705-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0870 | Regulator | 705-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0870 | Regulator | 705-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0870 | Regulator | 705-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 159092 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.7586 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0830 | BreakerVacuum | SM-14KV TR 3 | VCB Readings | Amps C Ø | 445.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0830 | BreakerVacuum | SM-14KV TR 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0830 | BreakerVacuum | SM-14KV TR 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0830 | BreakerVacuum | SM-14KV TR 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0830 | BreakerVacuum | SM-14KV TR 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0830 | BreakerVacuum | SM-14KV TR 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0830 | BreakerVacuum | SM-14KV TR 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0830 | BreakerVacuum | SM-14KV TR 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0830 | BreakerVacuum | SM-14KV TR 3 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0830 | BreakerVacuum | SM-14KV TR 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0830 | BreakerVacuum | SM-14KV TR 3 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Readings | Operations Counter AF | 239 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Readings | Operations Counter AL | 239 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Readings | 9 Month Operations | 5 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0830 | BreakerVacuum | SM-14KV TR 3 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0830 | BreakerVacuum | SM-14KV TR 3 | VCB Readings | General Comments | | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0870 | Regulator | 705-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0870 | Regulator | 705-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0870 | Regulator | 705-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0870 | Regulator | 705-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0870 | Regulator | 705-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0870 | Regulator | 705-1 C | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0870 | Regulator | 705-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0870 | Regulator | 705-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0870 | Regulator | 705-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0870 | Regulator | 705-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0870 | Regulator | 705-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0830 | BreakerVacuum | SM-14KV TR 3 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0830 | BreakerVacuum | SM-14KV TR 3 | VCB Readings | Operations Counter AF | 260 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0830 | BreakerVacuum | SM-14KV TR 3 | VCB Readings | Operations Counter AL | 260 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0830 | BreakerVacuum | SM-14KV TR 3 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0830 | BreakerVacuum | SM-14KV TR 3 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Readings | Operations Counter AL | 126 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Readings | Operations Counter AF | 126 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000866 | BreakerVacuum | SM-1235 | VCB Readings | General Comments | | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0870 | Regulator | 705-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0870 | Regulator | 705-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0870 | Regulator | 705-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0870 | Regulator | 705-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0870 | Regulator | 705-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0870 | Regulator | 705-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0870 | Regulator | 705-1 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0870 | Regulator | 705-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Readings | Unknown Operations | 0 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Readings | Switching Operations | 2 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Readings | Operations This Read Vac | 5 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Readings | Operations Counter AL | 222 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Readings | Operations Counter AF | 219 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Readings | General Comments | | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Readings | Fault Operations C Ø | 1 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Readings | Fault Operations B Ø | 1 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Readings | Fault Operations A Ø | 1 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Readings | Fault Adjusted Amps C Phase V | 1.00 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Readings | Fault Adjusted Amps B Phase V | 1.00 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Readings | Fault Adjusted Amps A Phase V | 1.00 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Readings | Amps C Ø | 0.0 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Readings | Amps B Ø | 0.0 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Readings | Amps A Ø | 0.0 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001122 | BreakerVacuum | 415-0740 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0821 | BreakerVacuum | SM-1394 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0821 | BreakerVacuum | SM-1394 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0821 | BreakerVacuum | SM-1394 | VCB Readings | Operations Counter AL | 250 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0821 | BreakerVacuum | SM-1394 | VCB Readings | Operations Counter AF | 250 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0821 | BreakerVacuum | SM-1394 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0821 | BreakerVacuum | SM-1394 | VCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0821 | BreakerVacuum | SM-1394 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0821 | BreakerVacuum | SM-1394 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0821 | BreakerVacuum | SM-1394 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0821 | BreakerVacuum | SM-1394 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Readings | Amps C Ø | 120.0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Readings | Amps C Ø | 73.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Readings | Amps B Ø | 73.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Readings | Amps A Ø | 73.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000869 | BreakerVacuum | SM-1232 | VCB Readings | 9 Month Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Readings | Operations Counter AL | 148 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Readings | Operations Counter AF | 148 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Readings | 9 Months Operations OCB New | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Readings | Amps A Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Readings | Amps B Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Readings | Amps C Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Readings | Operations Counter AL | 172 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Readings | Operations Counter AF | 172 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Readings | 9 Month Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Readings | Amps A Ø | 110.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Readings | Amps B Ø | 110.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Readings | Amps C Ø | 110.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000865 | BreakerVacuum | SM-1234 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0821 | BreakerVacuum | SM-1394 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0821 | BreakerVacuum | SM-1394 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0821 | BreakerVacuum | SM-1394 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0821 | BreakerVacuum | SM-1394 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0821 | BreakerVacuum | SM-1394 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0821 | BreakerVacuum | SM-1394 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0821 | BreakerVacuum | SM-1394 | VCB Readings | Amps C Ø | 66.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0821 | BreakerVacuum | SM-1394 | VCB Readings | Amps B Ø | 62.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0821 | BreakerVacuum | SM-1394 | VCB Readings | Amps A Ø | 64.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0821 | BreakerVacuum | SM-1394 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0821 | BreakerVacuum | SM-1394 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0821 | BreakerVacuum | SM-1394 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0821 | BreakerVacuum | SM-1394 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0821 | BreakerVacuum | SM-1394 | VCB Readings | 9 Month Operations | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Readings | General Comments | | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 4220.64 | kw |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | B0292 | NonLTC | 705-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Readings | Fault Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Readings | Amps B Ø | 120.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Readings | Amps A Ø | 120.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000868 | BreakerVacuum | SM-1233 | VCB Readings | 9 Month Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Readings | Number of Ops last 9 Months | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Readings | Operations Counter AF | 515 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Readings | Operations Counter AL | 515 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Readings | Operations This Read Oil | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Patrol Inspection | Tank Oil Level | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0833 | BreakerOil | SM-GND TR 2 | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000867 | BreakerVacuum | SM-1231 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Readings | Operations Counter AF | 229 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Readings | General Comments | | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Readings | Amps C Ø | 285.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Readings | Amps B Ø | 291.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Readings | Amps A Ø | 287.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Readings | 9 Month Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Readings | Unknown Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Readings | Switching Operations | 2 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Readings | Operations This Read Vac | 2 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Readings | Operations Counter AL | 348 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Readings | Operations Counter AF | 348 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Readings | Amps C Ø | 36.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Readings | Amps B Ø | 37.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Readings | Amps A Ø | 36.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001839 | BreakerVacuum | SM-1362 | VCB Readings | 9 Month Operations | 3 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1269 | BreakerVacuum | SM-1384 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1269 | BreakerVacuum | SM-1384 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1269 | BreakerVacuum | SM-1384 | VCB Readings | Operations Counter AL | 152 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Readings | Unknown Operations | 0 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Readings | Switching Operations | 3 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1271 | BreakerVacuum | SM-1386 | VCB Readings | 9 Month Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1271 | BreakerVacuum | SM-1386 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1271 | BreakerVacuum | SM-1386 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1271 | BreakerVacuum | SM-1386 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1271 | BreakerVacuum | SM-1386 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1271 | BreakerVacuum | SM-1386 | VCB Readings | Amps A Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1271 | BreakerVacuum | SM-1386 | VCB Readings | Amps B Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1271 | BreakerVacuum | SM-1386 | VCB Readings | Amps C Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1271 | BreakerVacuum | SM-1386 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1271 | BreakerVacuum | SM-1386 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1271 | BreakerVacuum | SM-1386 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1271 | BreakerVacuum | SM-1386 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1271 | BreakerVacuum | SM-1386 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0270 | GroundTransformer | SM-GND TR 6 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0270 | GroundTransformer | SM-GND TR 6 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0270 | GroundTransformer | SM-GND TR 6 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Readings | Operations This Read Vac | 3 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Readings | Operations Counter AL | 232 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0270 | GroundTransformer | SM-GND TR 6 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.5 | psi |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0270 | GroundTransformer | SM-GND TR 6 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0270 | GroundTransformer | SM-GND TR 6 | Ground Transformer Patrol Inspection | General Comments | needs nitro | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0270 | GroundTransformer | SM-GND TR 6 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0270 | GroundTransformer | SM-GND TR 6 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0270 | GroundTransformer | SM-GND TR 6 | Ground Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0270 | GroundTransformer | SM-GND TR 6 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0270 | GroundTransformer | SM-GND TR 6 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LT0270 | GroundTransformer | SM-GND TR 6 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1271 | BreakerVacuum | SM-1386 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1271 | BreakerVacuum | SM-1386 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1271 | BreakerVacuum | SM-1386 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1271 | BreakerVacuum | SM-1386 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0869 | Regulator | 705-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0869 | Regulator | 705-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0869 | Regulator | 705-1 B | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0869 | Regulator | 705-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0869 | Regulator | 705-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0869 | Regulator | 705-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0869 | Regulator | 705-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0869 | Regulator | 705-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1271 | BreakerVacuum | SM-1386 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1271 | BreakerVacuum | SM-1386 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1271 | BreakerVacuum | SM-1386 | VCB Readings | General Comments | DNO | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1271 | BreakerVacuum | SM-1386 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1271 | BreakerVacuum | SM-1386 | VCB Readings | Operations Counter AF | 131 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1271 | BreakerVacuum | SM-1386 | VCB Readings | Operations Counter AL | 131 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1271 | BreakerVacuum | SM-1386 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1271 | BreakerVacuum | SM-1386 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1270 | BreakerVacuum | SM-1385 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1270 | BreakerVacuum | SM-1385 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1270 | BreakerVacuum | SM-1385 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1270 | BreakerVacuum | SM-1385 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1270 | BreakerVacuum | SM-1385 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1270 | BreakerVacuum | SM-1385 | VCB Readings | General Comments | DNO | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1270 | BreakerVacuum | SM-1385 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1270 | BreakerVacuum | SM-1385 | VCB Readings | Operations Counter AF | 138 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1270 | BreakerVacuum | SM-1385 | VCB Readings | Operations Counter AL | 138 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1270 | BreakerVacuum | SM-1385 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1270 | BreakerVacuum | SM-1385 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1269 | BreakerVacuum | SM-1384 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1269 | BreakerVacuum | SM-1384 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1269 | BreakerVacuum | SM-1384 | VCB Readings | Amps C Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1269 | BreakerVacuum | SM-1384 | VCB Readings | Amps B Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1269 | BreakerVacuum | SM-1384 | VCB Readings | Amps A Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1269 | BreakerVacuum | SM-1384 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1269 | BreakerVacuum | SM-1384 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1269 | BreakerVacuum | SM-1384 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1269 | BreakerVacuum | SM-1384 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1269 | BreakerVacuum | SM-1384 | VCB Readings | 9 Month Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000189 | Switchgear | SM-Swgr Sec 5 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000189 | Switchgear | SM-Swgr Sec 5 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000189 | Switchgear | SM-Swgr Sec 5 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000189 | Switchgear | SM-Swgr Sec 5 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000189 | Switchgear | SM-Swgr Sec 5 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000189 | Switchgear | SM-Swgr Sec 5 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000189 | Switchgear | SM-Swgr Sec 5 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000189 | Switchgear | SM-Swgr Sec 5 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000189 | Switchgear | SM-Swgr Sec 5 | Switchgear Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000189 | Switchgear | SM-Swgr Sec 5 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000189 | Switchgear | SM-Swgr Sec 5 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000189 | Switchgear | SM-Swgr Sec 5 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000189 | Switchgear | SM-Swgr Sec 5 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000189 | Switchgear | SM-Swgr Sec 5 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000189 | Switchgear | SM-Swgr Sec 5 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000189 | Switchgear | SM-Swgr Sec 5 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000189 | Switchgear | SM-Swgr Sec 5 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000189 | Switchgear | SM-Swgr Sec 5 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | SWG000189 | Switchgear | SM-Swgr Sec 5 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0818 | BreakerVacuum | SM-1381 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0818 | BreakerVacuum | SM-1381 | VCB Readings | 9 Month Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0818 | BreakerVacuum | SM-1381 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0818 | BreakerVacuum | SM-1381 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0818 | BreakerVacuum | SM-1381 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0818 | BreakerVacuum | SM-1381 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0818 | BreakerVacuum | SM-1381 | VCB Readings | Amps A Ø | 10.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0818 | BreakerVacuum | SM-1381 | VCB Readings | Amps B Ø | 10.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0818 | BreakerVacuum | SM-1381 | VCB Readings | Amps C Ø | 10.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0818 | BreakerVacuum | SM-1381 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0818 | BreakerVacuum | SM-1381 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0818 | BreakerVacuum | SM-1381 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0818 | BreakerVacuum | SM-1381 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0818 | BreakerVacuum | SM-1381 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0818 | BreakerVacuum | SM-1381 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0818 | BreakerVacuum | SM-1381 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0818 | BreakerVacuum | SM-1381 | VCB Readings | Operations Counter AL | 244 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0818 | BreakerVacuum | SM-1381 | VCB Readings | Operations Counter AF | 244 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0818 | BreakerVacuum | SM-1381 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0818 | BreakerVacuum | SM-1381 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0818 | BreakerVacuum | SM-1381 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0818 | BreakerVacuum | SM-1381 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0818 | BreakerVacuum | SM-1381 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0818 | BreakerVacuum | SM-1381 | VCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0818 | BreakerVacuum | SM-1381 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1269 | BreakerVacuum | SM-1384 | VCB Readings | Operations Counter AF | 152 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1269 | BreakerVacuum | SM-1384 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1269 | BreakerVacuum | SM-1384 | VCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1269 | BreakerVacuum | SM-1384 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1269 | BreakerVacuum | SM-1384 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1269 | BreakerVacuum | SM-1384 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1269 | BreakerVacuum | SM-1384 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1269 | BreakerVacuum | SM-1384 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1269 | BreakerVacuum | SM-1384 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1269 | BreakerVacuum | SM-1384 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1269 | BreakerVacuum | SM-1384 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1269 | BreakerVacuum | SM-1384 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1270 | BreakerVacuum | SM-1385 | VCB Readings | 9 Month Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1270 | BreakerVacuum | SM-1385 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1270 | BreakerVacuum | SM-1385 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1270 | BreakerVacuum | SM-1385 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1270 | BreakerVacuum | SM-1385 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1270 | BreakerVacuum | SM-1385 | VCB Readings | Amps A Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1270 | BreakerVacuum | SM-1385 | VCB Readings | Amps B Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1270 | BreakerVacuum | SM-1385 | VCB Readings | Amps C Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1270 | BreakerVacuum | SM-1385 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Readings | Operations This Read Vac | 1 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1270 | BreakerVacuum | SM-1385 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1274 | BreakerVacuum | SM-1363 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Readings | General Comments | | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1270 | BreakerVacuum | SM-1385 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Readings | Amps C Ø | 110.0 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Readings | Amps B Ø | 100.0 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Readings | Amps A Ø | 90.0 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | BK001093 | BreakerVacuum | 415-0717 | VCB Readings | 9 Month Operations | 3 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Readings | Operations Counter AF | 146 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Readings | Operations Counter AL | 146 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1270 | BreakerVacuum | SM-1385 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1270 | BreakerVacuum | SM-1385 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1270 | BreakerVacuum | SM-1385 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Readings | Operations Counter AL | 186 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Readings | Operations This Read Vac | 1 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Readings | Switching Operations | 1 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Readings | Unknown Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0831 | BreakerVacuum | SM-14KV TR 6 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0831 | BreakerVacuum | SM-14KV TR 6 | VCB Readings | Amps C Ø | 30.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0831 | BreakerVacuum | SM-14KV TR 6 | VCB Readings | Amps B Ø | 30.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0831 | BreakerVacuum | SM-14KV TR 6 | VCB Readings | Amps A Ø | 30.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0831 | BreakerVacuum | SM-14KV TR 6 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0819 | BreakerVacuum | SM-1382 | VCB Readings | Operations This Read Vac | 1 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0819 | BreakerVacuum | SM-1382 | VCB Readings | Operations Counter AL | 241 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0819 | BreakerVacuum | SM-1382 | VCB Readings | Operations Counter AF | 241 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0819 | BreakerVacuum | SM-1382 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0819 | BreakerVacuum | SM-1382 | VCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Readings | Amps A Ø | 480.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Readings | Amps B Ø | 480.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Readings | Amps C Ø | 480.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0819 | BreakerVacuum | SM-1382 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Readings | Amps C Ø | 45.0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Readings | Amps B Ø | 55.0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Readings | Amps A Ø | 50.0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Readings | 9 Month Operations | 1 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0831 | BreakerVacuum | SM-14KV TR 6 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0832 | BreakerOil | SM-GND TR 1 | OCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0832 | BreakerOil | SM-GND TR 1 | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0832 | BreakerOil | SM-GND TR 1 | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0832 | BreakerOil | SM-GND TR 1 | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0831 | BreakerVacuum | SM-14KV TR 6 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0831 | BreakerVacuum | SM-14KV TR 6 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0832 | BreakerOil | SM-GND TR 1 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0832 | BreakerOil | SM-GND TR 1 | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0832 | BreakerOil | SM-GND TR 1 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0832 | BreakerOil | SM-GND TR 1 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0832 | BreakerOil | SM-GND TR 1 | OCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0832 | BreakerOil | SM-GND TR 1 | OCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0832 | BreakerOil | SM-GND TR 1 | OCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0832 | BreakerOil | SM-GND TR 1 | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0832 | BreakerOil | SM-GND TR 1 | OCB Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0832 | BreakerOil | SM-GND TR 1 | OCB Patrol Inspection | Tank Oil Level | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0832 | BreakerOil | SM-GND TR 1 | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0819 | BreakerVacuum | SM-1382 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0831 | BreakerVacuum | SM-14KV TR 6 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0831 | BreakerVacuum | SM-14KV TR 6 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0831 | BreakerVacuum | SM-14KV TR 6 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Readings | Operations Counter AF | 299 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Readings | Operations Counter AL | 299 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Readings | Operations Counter AF | 185 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Readings | General Comments | | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1267 | BreakerVacuum | SM-14KV BUS TIE SEC 5 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1267 | BreakerVacuum | SM-14KV BUS TIE SEC 5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1267 | BreakerVacuum | SM-14KV BUS TIE SEC 5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1267 | BreakerVacuum | SM-14KV BUS TIE SEC 5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1267 | BreakerVacuum | SM-14KV BUS TIE SEC 5 | VCB Readings | Amps A Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1267 | BreakerVacuum | SM-14KV BUS TIE SEC 5 | VCB Readings | Amps B Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1267 | BreakerVacuum | SM-14KV BUS TIE SEC 5 | VCB Readings | Amps C Ø | 0.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1267 | BreakerVacuum | SM-14KV BUS TIE SEC 5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1267 | BreakerVacuum | SM-14KV BUS TIE SEC 5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | BK001417 | BreakerVacuum | 705-0715 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Readings | 9 Month Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB1267 | BreakerVacuum | SM-14KV BUS TIE SEC 5 | VCB Readings | 9 Month Operations | 4 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0819 | BreakerVacuum | SM-1382 | VCB Readings | Switching Operations | 1 | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | YD000386 | Yard | 415-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | YD000386 | Yard | 415-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | YD000386 | Yard | 415-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | YD000386 | Yard | 415-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | YD000386 | Yard | 415-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | YD000386 | Yard | 415-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0819 | BreakerVacuum | SM-1382 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0819 | BreakerVacuum | SM-1382 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0819 | BreakerVacuum | SM-1382 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Readings | Operations Counter AL | 339 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0869 | Regulator | 705-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0869 | Regulator | 705-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0869 | Regulator | 705-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0869 | Regulator | 705-1 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0869 | Regulator | 705-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0869 | Regulator | 705-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0869 | Regulator | 705-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | YD000386 | Yard | 415-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | YD000386 | Yard | 415-Yard | Yard Patrol Inspection | General Comments | | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | YD000386 | Yard | 415-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | YD000386 | Yard | 415-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | YD000386 | Yard | 415-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | YD000386 | Yard | 415-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | YD000386 | Yard | 415-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0819 | BreakerVacuum | SM-1382 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0819 | BreakerVacuum | SM-1382 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0819 | BreakerVacuum | SM-1382 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0819 | BreakerVacuum | SM-1382 | VCB Readings | Amps C Ø | 10.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0819 | BreakerVacuum | SM-1382 | VCB Readings | Amps B Ø | 10.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0819 | BreakerVacuum | SM-1382 | VCB Readings | Amps A Ø | 10.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0819 | BreakerVacuum | SM-1382 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0819 | BreakerVacuum | SM-1382 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0819 | BreakerVacuum | SM-1382 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0819 | BreakerVacuum | SM-1382 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0819 | BreakerVacuum | SM-1382 | VCB Readings | 9 Month Operations | 1 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0869 | Regulator | 705-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Readings | Operations Counter AF | 339 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0835 | BreakerVacuum | SM-GND TR 6 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0835 | BreakerVacuum | SM-GND TR 6 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0835 | BreakerVacuum | SM-GND TR 6 | VCB Readings | Operations Counter AL | 144 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0835 | BreakerVacuum | SM-GND TR 6 | VCB Readings | Operations Counter AF | 144 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0835 | BreakerVacuum | SM-GND TR 6 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Readings | Amps C Ø | 81.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Readings | Amps B Ø | 76.0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0831 | BreakerVacuum | SM-14KV TR 6 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0831 | BreakerVacuum | SM-14KV TR 6 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0831 | BreakerVacuum | SM-14KV TR 6 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0831 | BreakerVacuum | SM-14KV TR 6 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0831 | BreakerVacuum | SM-14KV TR 6 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0831 | BreakerVacuum | SM-14KV TR 6 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0831 | BreakerVacuum | SM-14KV TR 6 | VCB Readings | General Comments | | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0831 | BreakerVacuum | SM-14KV TR 6 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0831 | BreakerVacuum | SM-14KV TR 6 | VCB Readings | Operations Counter AF | 189 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0831 | BreakerVacuum | SM-14KV TR 6 | VCB Readings | Operations Counter AL | 189 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0831 | BreakerVacuum | SM-14KV TR 6 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0831 | BreakerVacuum | SM-14KV TR 6 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0831 | BreakerVacuum | SM-14KV TR 6 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0831 | BreakerVacuum | SM-14KV TR 6 | VCB Readings | 9 Month Operations | 1 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000178 | BreakerVacuum | SM-1361 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0819 | BreakerVacuum | SM-1382 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0819 | BreakerVacuum | SM-1382 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK001840 | BreakerVacuum | SM-14KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0869 | Regulator | 705-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0869 | Regulator | 705-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0869 | Regulator | 705-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | LB0819 | BreakerVacuum | SM-1382 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:15 | Distribution | Seminole Quarterly Inspection | BK000179 | BreakerVacuum | SM-12KV TR 4 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | YD000386 | Yard | 415-Yard | Yard Patrol Inspection | Ambient Temp | 53 | °F |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | YD000386 | Yard | 415-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/16/2023 14:39 | Distribution | Ghent City Quarterly Inspection | YD000386 | Yard | 415-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0869 | Regulator | 705-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0869 | Regulator | 705-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0869 | Regulator | 705-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0869 | Regulator | 705-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 209577 | |
| 2/16/2023 15:02 | Distribution | Owenton Quarterly Inspection | R0869 | Regulator | 705-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Readings | Fault Adjusted Amps A Phase V | 33.54 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Readings | Fault Adjusted Amps B Phase V | 33.54 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Readings | 9 Month Operations | 12 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | FE000293 | Fence | 400-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Readings | Fault Operations A Ø | 3 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Readings | Amps C Ø | 69.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Readings | Amps B Ø | 72.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Readings | Amps A Ø | 81.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Readings | Amps C Ø | 120.0 | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Readings | Amps B Ø | 120.0 | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Readings | Amps A Ø | 120.0 | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000067 | Switchgear | WT-Swgr Sec 5 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Readings | 9 Month Operations | 3 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1129 | BreakerAirMagnetic | WT-1151 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1129 | BreakerAirMagnetic | WT-1151 | AMCB Readings | Fault Operations A Ø | 3 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1129 | BreakerAirMagnetic | WT-1151 | AMCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1129 | BreakerAirMagnetic | WT-1151 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1129 | BreakerAirMagnetic | WT-1151 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1129 | BreakerAirMagnetic | WT-1151 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1129 | BreakerAirMagnetic | WT-1151 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | FE000293 | Fence | 400-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | FE000293 | Fence | 400-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | FE000293 | Fence | 400-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1129 | BreakerAirMagnetic | WT-1151 | AMCB Patrol Inspection | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1129 | BreakerAirMagnetic | WT-1151 | AMCB Readings | General Comments | A phase IOC | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1129 | BreakerAirMagnetic | WT-1151 | AMCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1129 | BreakerAirMagnetic | WT-1151 | AMCB Readings | Operations Counter AF | 899 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1129 | BreakerAirMagnetic | WT-1151 | AMCB Readings | Operations Counter AL | 899 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1129 | BreakerAirMagnetic | WT-1151 | AMCB Readings | Operations This Read AM | 3 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1129 | BreakerAirMagnetic | WT-1151 | AMCB Readings | Switching Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1129 | BreakerAirMagnetic | WT-1151 | AMCB Readings | Unknown Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001651 | BreakerVacuum | WT-1153 | VCB Readings | Operations Counter AF | 52 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001651 | BreakerVacuum | WT-1153 | VCB Readings | Operations Counter AL | 52 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001651 | BreakerVacuum | WT-1153 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001651 | BreakerVacuum | WT-1153 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001651 | BreakerVacuum | WT-1153 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001652 | BreakerVacuum | WT-1154 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001652 | BreakerVacuum | WT-1154 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001652 | BreakerVacuum | WT-1154 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001652 | BreakerVacuum | WT-1154 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001652 | BreakerVacuum | WT-1154 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001652 | BreakerVacuum | WT-1154 | VCB Readings | Amps A Ø | 142.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001652 | BreakerVacuum | WT-1154 | VCB Readings | Amps B Ø | 132.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001652 | BreakerVacuum | WT-1154 | VCB Readings | Amps C Ø | 143.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001652 | BreakerVacuum | WT-1154 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001652 | BreakerVacuum | WT-1154 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001652 | BreakerVacuum | WT-1154 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001652 | BreakerVacuum | WT-1154 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001652 | BreakerVacuum | WT-1154 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001652 | BreakerVacuum | WT-1154 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001652 | BreakerVacuum | WT-1154 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001652 | BreakerVacuum | WT-1154 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001652 | BreakerVacuum | WT-1154 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001652 | BreakerVacuum | WT-1154 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001652 | BreakerVacuum | WT-1154 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001652 | BreakerVacuum | WT-1154 | VCB Readings | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001652 | BreakerVacuum | WT-1154 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001652 | BreakerVacuum | WT-1154 | VCB Readings | Operations Counter AF | 36 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001652 | BreakerVacuum | WT-1154 | VCB Readings | Operations Counter AL | 36 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001652 | BreakerVacuum | WT-1154 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001652 | BreakerVacuum | WT-1154 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1129 | BreakerAirMagnetic | WT-1151 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1129 | BreakerAirMagnetic | WT-1151 | AMCB Readings | Fault Adjusted Amps A Phase AM | 33.54 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1129 | BreakerAirMagnetic | WT-1151 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1129 | BreakerAirMagnetic | WT-1151 | AMCB Readings | Amps C Ø | 98.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1129 | BreakerAirMagnetic | WT-1151 | AMCB Readings | Amps B Ø | 111.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1129 | BreakerAirMagnetic | WT-1151 | AMCB Readings | Amps A Ø | 104.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1129 | BreakerAirMagnetic | WT-1151 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1129 | BreakerAirMagnetic | WT-1151 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1129 | BreakerAirMagnetic | WT-1151 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1129 | BreakerAirMagnetic | WT-1151 | AMCB Readings | 9 Months Operations | 7 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1129 | BreakerAirMagnetic | WT-1151 | AMCB Readings | 9 Month Ops New | 4 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BAT001450 | Battery | 400-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BAT001450 | Battery | 400-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 72 | °F |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001652 | BreakerVacuum | WT-1154 | VCB Readings | Unknown Operations | 0 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BAT001450 | Battery | 400-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BAT001450 | Battery | 400-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BAT001450 | Battery | 400-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BAT001450 | Battery | 400-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.0 | VDC |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BAT001450 | Battery | 400-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BAT001450 | Battery | 400-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BAT001450 | Battery | 400-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BAT001450 | Battery | 400-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BAT001450 | Battery | 400-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BAT001450 | Battery | 400-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BAT001450 | Battery | 400-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000067 | Switchgear | WT-Swgr Sec 5 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000067 | Switchgear | WT-Swgr Sec 5 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000067 | Switchgear | WT-Swgr Sec 5 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000067 | Switchgear | WT-Swgr Sec 5 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000067 | Switchgear | WT-Swgr Sec 5 | Switchgear Patrol Inspection | Panels Dusted? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000067 | Switchgear | WT-Swgr Sec 5 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000067 | Switchgear | WT-Swgr Sec 5 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Patrol Inspection | General Comments | | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Readings | General Comments | | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Readings | Operations Counter AF | 509 | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Readings | Operations Counter AL | 512 | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Readings | Operations This Read Vac | 3 | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Readings | Switching Operations | 3 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001653 | BreakerVacuum | WT-1155 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001653 | BreakerVacuum | WT-1155 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001653 | BreakerVacuum | WT-1155 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001653 | BreakerVacuum | WT-1155 | VCB Readings | Operations Counter AL | 63 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001653 | BreakerVacuum | WT-1155 | VCB Readings | Operations Counter AF | 63 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001653 | BreakerVacuum | WT-1155 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001653 | BreakerVacuum | WT-1155 | VCB Readings | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001653 | BreakerVacuum | WT-1155 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001653 | BreakerVacuum | WT-1155 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001653 | BreakerVacuum | WT-1155 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BB0411 | BreakerVacuum | 733-2536 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000067 | Switchgear | WT-Swgr Sec 5 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000067 | Switchgear | WT-Swgr Sec 5 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000067 | Switchgear | WT-Swgr Sec 5 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000067 | Switchgear | WT-Swgr Sec 5 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000067 | Switchgear | WT-Swgr Sec 5 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000067 | Switchgear | WT-Swgr Sec 5 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000067 | Switchgear | WT-Swgr Sec 5 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000067 | Switchgear | WT-Swgr Sec 5 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000067 | Switchgear | WT-Swgr Sec 5 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000067 | Switchgear | WT-Swgr Sec 5 | Switchgear Patrol Inspection | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001653 | BreakerVacuum | WT-1155 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001653 | BreakerVacuum | WT-1155 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001653 | BreakerVacuum | WT-1155 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001653 | BreakerVacuum | WT-1155 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001653 | BreakerVacuum | WT-1155 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001653 | BreakerVacuum | WT-1155 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001653 | BreakerVacuum | WT-1155 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001653 | BreakerVacuum | WT-1155 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001653 | BreakerVacuum | WT-1155 | VCB Readings | Amps C Ø | 65.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001653 | BreakerVacuum | WT-1155 | VCB Readings | Amps B Ø | 66.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001653 | BreakerVacuum | WT-1155 | VCB Readings | Amps A Ø | 66.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001653 | BreakerVacuum | WT-1155 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001653 | BreakerVacuum | WT-1155 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001653 | BreakerVacuum | WT-1155 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001653 | BreakerVacuum | WT-1155 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001653 | BreakerVacuum | WT-1155 | VCB Readings | 9 Month Operations | 1 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000067 | Switchgear | WT-Swgr Sec 5 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001651 | BreakerVacuum | WT-1153 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001651 | BreakerVacuum | WT-1153 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001651 | BreakerVacuum | WT-1153 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001651 | BreakerVacuum | WT-1153 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001651 | BreakerVacuum | WT-1153 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001651 | BreakerVacuum | WT-1153 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001651 | BreakerVacuum | WT-1153 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001651 | BreakerVacuum | WT-1153 | VCB Readings | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001651 | BreakerVacuum | WT-1153 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1143 | Regulator | 476-1 C | Regulator Patrol Inspection | Min Tap Position | 3L | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001655 | BreakerVacuum | WT-1210 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001655 | BreakerVacuum | WT-1210 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001655 | BreakerVacuum | WT-1210 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001655 | BreakerVacuum | WT-1210 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001655 | BreakerVacuum | WT-1210 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001655 | BreakerVacuum | WT-1210 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001655 | BreakerVacuum | WT-1210 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001655 | BreakerVacuum | WT-1210 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001655 | BreakerVacuum | WT-1210 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001655 | BreakerVacuum | WT-1210 | VCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001655 | BreakerVacuum | WT-1210 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001655 | BreakerVacuum | WT-1210 | VCB Readings | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001655 | BreakerVacuum | WT-1210 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001655 | BreakerVacuum | WT-1210 | VCB Readings | Operations Counter AF | 86 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001655 | BreakerVacuum | WT-1210 | VCB Readings | Operations Counter AL | 86 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001655 | BreakerVacuum | WT-1210 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001655 | BreakerVacuum | WT-1210 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001655 | BreakerVacuum | WT-1210 | VCB Readings | Unknown Operations | 0 | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | ST000511 | Structure | 733-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | ST000511 | Structure | 733-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | ST000511 | Structure | 733-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | ST000511 | Structure | 733-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | ST000511 | Structure | 733-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Readings | Amps B Ø | 180.0 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Readings | Amps C Ø | 160.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001744 | BreakerVacuum | WT-12KV TR 4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001744 | BreakerVacuum | WT-12KV TR 4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001744 | BreakerVacuum | WT-12KV TR 4 | VCB Readings | Amps A Ø | 450.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001744 | BreakerVacuum | WT-12KV TR 4 | VCB Readings | Amps B Ø | 415.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001744 | BreakerVacuum | WT-12KV TR 4 | VCB Readings | Amps C Ø | 431.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001744 | BreakerVacuum | WT-12KV TR 4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001744 | BreakerVacuum | WT-12KV TR 4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001744 | BreakerVacuum | WT-12KV TR 4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1141 | BreakerAirMagnetic | WT-12KV TR 5 | AMCB Readings | Unknown Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1141 | BreakerAirMagnetic | WT-12KV TR 5 | AMCB Readings | Switching Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1141 | BreakerAirMagnetic | WT-12KV TR 5 | AMCB Readings | Operations This Read AM | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1141 | BreakerAirMagnetic | WT-12KV TR 5 | AMCB Readings | Operations Counter AL | 368 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1141 | BreakerAirMagnetic | WT-12KV TR 5 | AMCB Readings | Operations Counter AF | 368 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1141 | BreakerAirMagnetic | WT-12KV TR 5 | AMCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1141 | BreakerAirMagnetic | WT-12KV TR 5 | AMCB Readings | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1141 | BreakerAirMagnetic | WT-12KV TR 5 | AMCB Patrol Inspection | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1141 | BreakerAirMagnetic | WT-12KV TR 5 | AMCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001744 | BreakerVacuum | WT-12KV TR 4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Readings | Unknown Operations | 0 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Readings | Switching Operations | 0 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Readings | Operations This Read Vac | 1 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Readings | Operations Counter AL | 167 | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | X0314 | RecloserElectronic | 422-0700 | Recloser Electronic Patrol Inspection | Amps A Ø | 65.0 | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | X0314 | RecloserElectronic | 422-0700 | Recloser Electronic Patrol Inspection | Amps B Ø | 88.0 | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | X0314 | RecloserElectronic | 422-0700 | Recloser Electronic Patrol Inspection | Amps C Ø | 93.0 | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | X0314 | RecloserElectronic | 422-0700 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | X0314 | RecloserElectronic | 422-0700 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | X0314 | RecloserElectronic | 422-0700 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | X0314 | RecloserElectronic | 422-0700 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | X0314 | RecloserElectronic | 422-0700 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | X0314 | RecloserElectronic | 422-0700 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | X0314 | RecloserElectronic | 422-0700 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | X0314 | RecloserElectronic | 422-0700 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | X0314 | RecloserElectronic | 422-0700 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | X0314 | RecloserElectronic | 422-0700 | Recloser Electronic Patrol Inspection | General Comments | | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | X0314 | RecloserElectronic | 422-0700 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | X0314 | RecloserElectronic | 422-0700 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | X0314 | RecloserElectronic | 422-0700 | Recloser Electronic Patrol Inspection | Operations Counter | 312418 | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | X0314 | RecloserElectronic | 422-0700 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | X0314 | RecloserElectronic | 422-0700 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | X0314 | RecloserElectronic | 422-0700 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1137 | BreakerAirMagnetic | WT-1212 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1137 | BreakerAirMagnetic | WT-1212 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1137 | BreakerAirMagnetic | WT-1212 | AMCB Readings | 9 Months Operations | 4 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1137 | BreakerAirMagnetic | WT-1212 | AMCB Readings | 9 Month Ops New | 1 | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | ST000511 | Structure | 733-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001655 | BreakerVacuum | WT-1210 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001655 | BreakerVacuum | WT-1210 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001655 | BreakerVacuum | WT-1210 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001655 | BreakerVacuum | WT-1210 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001655 | BreakerVacuum | WT-1210 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | ST000511 | Structure | 733-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | ST000511 | Structure | 733-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | ST000511 | Structure | 733-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | ST000511 | Structure | 733-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1143 | Regulator | 476-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1143 | Regulator | 476-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1143 | Regulator | 476-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1143 | Regulator | 476-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1143 | Regulator | 476-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1143 | Regulator | 476-1 C | Regulator Patrol Inspection | Current Tap Position | 3R | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1143 | Regulator | 476-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1143 | Regulator | 476-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001655 | BreakerVacuum | WT-1210 | VCB Readings | Amps A Ø | 111.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001655 | BreakerVacuum | WT-1210 | VCB Readings | Amps B Ø | 79.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001655 | BreakerVacuum | WT-1210 | VCB Readings | Amps C Ø | 110.0 | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1143 | Regulator | 476-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1143 | Regulator | 476-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1143 | Regulator | 476-1 C | Regulator Patrol Inspection | General Comments | ok | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1143 | Regulator | 476-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1143 | Regulator | 476-1 C | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Readings | Amps A Ø | 0.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Readings | Amps C Ø | 0.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Readings | General Comments | open | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BCH001455 | Charger | 400-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BCH001455 | Charger | 400-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BCH001455 | Charger | 400-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BCH001455 | Charger | 400-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BCH001455 | Charger | 400-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.5 | amps |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BCH001455 | Charger | 400-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BCH001455 | Charger | 400-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BCH001455 | Charger | 400-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Readings | Operations Counter AF | 22 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Readings | Operations Counter AL | 22 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001745 | BreakerVacuum | WT-12KV BUS TIE SEC 4 | VCB Readings | Unknown Operations | 0 | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1143 | Regulator | 476-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1143 | Regulator | 476-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1143 | Regulator | 476-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1143 | Regulator | 476-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1143 | Regulator | 476-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.5 | volts |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1143 | Regulator | 476-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 55930 | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1143 | Regulator | 476-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1143 | Regulator | 476-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001744 | BreakerVacuum | WT-12KV TR 4 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001744 | BreakerVacuum | WT-12KV TR 4 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001744 | BreakerVacuum | WT-12KV TR 4 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001744 | BreakerVacuum | WT-12KV TR 4 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001744 | BreakerVacuum | WT-12KV TR 4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001744 | BreakerVacuum | WT-12KV TR 4 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001744 | BreakerVacuum | WT-12KV TR 4 | VCB Patrol Inspection | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001744 | BreakerVacuum | WT-12KV TR 4 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001744 | BreakerVacuum | WT-12KV TR 4 | VCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001744 | BreakerVacuum | WT-12KV TR 4 | VCB Readings | Operations Counter AF | 36 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001744 | BreakerVacuum | WT-12KV TR 4 | VCB Readings | Operations Counter AL | 36 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001744 | BreakerVacuum | WT-12KV TR 4 | VCB Readings | Operations This Read Vac | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001744 | BreakerVacuum | WT-12KV TR 4 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001744 | BreakerVacuum | WT-12KV TR 4 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1141 | BreakerAirMagnetic | WT-12KV TR 5 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1141 | BreakerAirMagnetic | WT-12KV TR 5 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1141 | BreakerAirMagnetic | WT-12KV TR 5 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1141 | BreakerAirMagnetic | WT-12KV TR 5 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1141 | BreakerAirMagnetic | WT-12KV TR 5 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1141 | BreakerAirMagnetic | WT-12KV TR 5 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1141 | BreakerAirMagnetic | WT-12KV TR 5 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1141 | BreakerAirMagnetic | WT-12KV TR 5 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1141 | BreakerAirMagnetic | WT-12KV TR 5 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1141 | BreakerAirMagnetic | WT-12KV TR 5 | AMCB Readings | Amps C Ø | 291.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1141 | BreakerAirMagnetic | WT-12KV TR 5 | AMCB Readings | Amps B Ø | 313.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1141 | BreakerAirMagnetic | WT-12KV TR 5 | AMCB Readings | Amps A Ø | 267.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1141 | BreakerAirMagnetic | WT-12KV TR 5 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1141 | BreakerAirMagnetic | WT-12KV TR 5 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1141 | BreakerAirMagnetic | WT-12KV TR 5 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1141 | BreakerAirMagnetic | WT-12KV TR 5 | AMCB Readings | 9 Months Operations | 0 | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1143 | Regulator | 476-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Readings | Operations Counter AF | 167 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Readings | Maintenance Operations | 1 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Readings | General Comments | | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1141 | BreakerAirMagnetic | WT-12KV TR 5 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | FE000293 | Fence | 400-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | n | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | LTCMechanism | 733-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | LTCMechanism | 733-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | LTCMechanism | 733-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | LTCMechanism | 733-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | LTCMechanism | 733-1 | LTC Counter Readings | LTC Operations Since Last Insp | 378 | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | FE000502 | Fence | 733-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | FE000502 | Fence | 733-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | FE000502 | Fence | 733-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | FE000502 | Fence | 733-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | FE000502 | Fence | 733-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | FE000502 | Fence | 733-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | FE000502 | Fence | 733-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | FE000502 | Fence | 733-Fence | Fence Patrol Inspection | General Comments | signs need to be updated | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | FE000502 | Fence | 733-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 135.00 | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.8665 | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 1800 | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | CH000338 | ControlHouse | 422-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | CH000338 | ControlHouse | 422-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | CH000338 | ControlHouse | 422-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | CH000338 | ControlHouse | 422-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | FE000502 | Fence | 733-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | n | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | YD000508 | Yard | 733-Yard | Yard Patrol Inspection | Ambient Temp | 66 | °F |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | YD000508 | Yard | 733-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | YD000508 | Yard | 733-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | YD000508 | Yard | 733-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | YD000508 | Yard | 733-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | YD000508 | Yard | 733-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | YD000508 | Yard | 733-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | YD000508 | Yard | 733-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Readings | Operations Counter AF | 19 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Readings | Operations Counter AL | 19 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Readings | Operations This Read Vac | 6 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Readings | Unknown Operations | 0 | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | YD000508 | Yard | 733-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | YD000508 | Yard | 733-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | YD000508 | Yard | 733-Yard | Yard Patrol Inspection | General Comments | | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | YD000508 | Yard | 733-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | LTCMechanism | 733-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | LTCMechanism | 733-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | LTCMechanism | 733-1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Readings | Fault Operations B Ø | 3 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Patrol Inspection | General Comments | | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | FE000502 | Fence | 733-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Readings | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001654 | BreakerVacuum | WT-1209 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | FE000502 | Fence | 733-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | FE000502 | Fence | 733-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | FE000502 | Fence | 733-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | FE000502 | Fence | 733-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | FE000502 | Fence | 733-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1050 | Regulator | 476-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1050 | Regulator | 476-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1050 | Regulator | 476-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1050 | Regulator | 476-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 79446 | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1050 | Regulator | 476-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.7 | volts |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1050 | Regulator | 476-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1050 | Regulator | 476-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1050 | Regulator | 476-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1050 | Regulator | 476-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1050 | Regulator | 476-1 A | Regulator Patrol Inspection | Min Tap Position | Neutral | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1050 | Regulator | 476-1 A | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1050 | Regulator | 476-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1050 | Regulator | 476-1 A | Regulator Patrol Inspection | General Comments | ok | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1050 | Regulator | 476-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1050 | Regulator | 476-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1050 | Regulator | 476-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1050 | Regulator | 476-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1050 | Regulator | 476-1 A | Regulator Patrol Inspection | Current Tap Position | 4R | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1050 | Regulator | 476-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1050 | Regulator | 476-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1050 | Regulator | 476-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1050 | Regulator | 476-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1050 | Regulator | 476-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | FE000293 | Fence | 400-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | FE000293 | Fence | 400-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | FE000293 | Fence | 400-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | FE000293 | Fence | 400-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | FE000293 | Fence | 400-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | FE000293 | Fence | 400-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | FE000293 | Fence | 400-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | FE000293 | Fence | 400-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | FE000293 | Fence | 400-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | FE000293 | Fence | 400-Fence | Fence Patrol Inspection | General Comments | signs need to be pdated | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | FE000293 | Fence | 400-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Readings | General Comments | | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | ST000511 | Structure | 733-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | ST000511 | Structure | 733-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | ST000511 | Structure | 733-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | ST000511 | Structure | 733-Structure | Structure Patrol Inspection | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1137 | BreakerAirMagnetic | WT-1212 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1137 | BreakerAirMagnetic | WT-1212 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001744 | BreakerVacuum | WT-12KV TR 4 | VCB Readings | 9 Month Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001744 | BreakerVacuum | WT-12KV TR 4 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001744 | BreakerVacuum | WT-12KV TR 4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Readings | Accumulated Fault Duty A Ph V | 13.43 | % |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BCH000893 | Charger | 733-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BCH000893 | Charger | 733-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BCH000893 | Charger | 733-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BCH000893 | Charger | 733-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Readings | Accumulated Fault Duty B Ph V | 10.99 | % |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Readings | Accumulated Fault Duty C Ph V | 15.87 | % |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Readings | Amps A Ø | 180.0 | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | ST000511 | Structure | 733-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | ST000511 | Structure | 733-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1137 | BreakerAirMagnetic | WT-1212 | AMCB Readings | Fault Operations B Ø | 3 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1137 | BreakerAirMagnetic | WT-1212 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1137 | BreakerAirMagnetic | WT-1212 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1137 | BreakerAirMagnetic | WT-1212 | AMCB Readings | Fault Adjusted Amps B Phase AM | 33.54 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1137 | BreakerAirMagnetic | WT-1212 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1137 | BreakerAirMagnetic | WT-1212 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1137 | BreakerAirMagnetic | WT-1212 | AMCB Readings | Amps C Ø | 87.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1137 | BreakerAirMagnetic | WT-1212 | AMCB Readings | Amps B Ø | 63.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1137 | BreakerAirMagnetic | WT-1212 | AMCB Readings | Amps A Ø | 50.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1137 | BreakerAirMagnetic | WT-1212 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | LTCMechanism | 733-1 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | LTCMechanism | 733-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | LTCMechanism | 733-1 | LTC Counter Readings | LTC As Left Counter | 86272 | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | LTCMechanism | 733-1 | LTC Counter Readings | LTC As Found Counter | 86268 | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | LTCMechanism | 733-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | LTCMechanism | 733-1 | LTC Counter Readings | General Comments | | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | LTCMechanism | 733-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | LTCMechanism | 733-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Readings | 9 Month Operations | 1 | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | CH000338 | ControlHouse | 422-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | CH000338 | ControlHouse | 422-Control House | Control House Patrol Inspection | General Comments | | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | CH000338 | ControlHouse | 422-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | CH000338 | ControlHouse | 422-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | CH000338 | ControlHouse | 422-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | CH000338 | ControlHouse | 422-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | CH000338 | ControlHouse | 422-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | CH000338 | ControlHouse | 422-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1137 | BreakerAirMagnetic | WT-1212 | AMCB Readings | Unknown Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1137 | BreakerAirMagnetic | WT-1212 | AMCB Readings | Switching Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1137 | BreakerAirMagnetic | WT-1212 | AMCB Readings | Operations This Read AM | 3 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1137 | BreakerAirMagnetic | WT-1212 | AMCB Readings | Operations Counter AL | 759 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1137 | BreakerAirMagnetic | WT-1212 | AMCB Readings | Operations Counter AF | 759 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1137 | BreakerAirMagnetic | WT-1212 | AMCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1137 | BreakerAirMagnetic | WT-1212 | AMCB Readings | General Comments | B phase IOC | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1137 | BreakerAirMagnetic | WT-1212 | AMCB Patrol Inspection | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1137 | BreakerAirMagnetic | WT-1212 | AMCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1137 | BreakerAirMagnetic | WT-1212 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | CH000338 | ControlHouse | 422-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | CH000338 | ControlHouse | 422-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | CH000338 | ControlHouse | 422-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | CH000338 | ControlHouse | 422-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | CH000338 | ControlHouse | 422-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | YD000508 | Yard | 733-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | YD000508 | Yard | 733-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | YD000508 | Yard | 733-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | ST000511 | Structure | 733-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | ST000511 | Structure | 733-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | ST000511 | Structure | 733-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | ST000511 | Structure | 733-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | ST000511 | Structure | 733-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | ST000511 | Structure | 733-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | WithLTC | 422-1 | LTC Transformer Readings | LTC Totalizer Reading | 3359.70 | kw |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.1000 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Readings | Winding Temp Max | 50 | °C |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Readings | Winding Temp Present | 50 | °C |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | ST000305 | Structure | 400-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | ST000305 | Structure | 400-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | ST000305 | Structure | 400-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1130 | BreakerAirMagnetic | WT-1152 | AMCB Readings | 9 Month Ops New | 8 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1130 | BreakerAirMagnetic | WT-1152 | AMCB Readings | 9 Months Operations | 8 | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1052 | Regulator | 476-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1052 | Regulator | 476-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1052 | Regulator | 476-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1052 | Regulator | 476-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 66469 | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Readings | Totalizer Meter Reading | .1900 | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1130 | BreakerAirMagnetic | WT-1152 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1130 | BreakerAirMagnetic | WT-1152 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1130 | BreakerAirMagnetic | WT-1152 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1130 | BreakerAirMagnetic | WT-1152 | AMCB Readings | Amps A Ø | 116.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1130 | BreakerAirMagnetic | WT-1152 | AMCB Readings | Amps B Ø | 149.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1130 | BreakerAirMagnetic | WT-1152 | AMCB Readings | Amps C Ø | 115.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1130 | BreakerAirMagnetic | WT-1152 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1130 | BreakerAirMagnetic | WT-1152 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1130 | BreakerAirMagnetic | WT-1152 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1130 | BreakerAirMagnetic | WT-1152 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1130 | BreakerAirMagnetic | WT-1152 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1130 | BreakerAirMagnetic | WT-1152 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1130 | BreakerAirMagnetic | WT-1152 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1130 | BreakerAirMagnetic | WT-1152 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1130 | BreakerAirMagnetic | WT-1152 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1130 | BreakerAirMagnetic | WT-1152 | AMCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1130 | BreakerAirMagnetic | WT-1152 | AMCB Patrol Inspection | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1130 | BreakerAirMagnetic | WT-1152 | AMCB Readings | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1130 | BreakerAirMagnetic | WT-1152 | AMCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1130 | BreakerAirMagnetic | WT-1152 | AMCB Readings | Operations Counter AF | 563 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1130 | BreakerAirMagnetic | WT-1152 | AMCB Readings | Operations Counter AL | 563 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1130 | BreakerAirMagnetic | WT-1152 | AMCB Readings | Operations This Read AM | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1130 | BreakerAirMagnetic | WT-1152 | AMCB Readings | Switching Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1130 | BreakerAirMagnetic | WT-1152 | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1052 | Regulator | 476-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1052 | Regulator | 476-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1052 | Regulator | 476-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Readings | Unknown Operations | 1 | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 6000 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000068 | Switchgear | WT-Swgr Sec 4 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000068 | Switchgear | WT-Swgr Sec 4 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000068 | Switchgear | WT-Swgr Sec 4 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000068 | Switchgear | WT-Swgr Sec 4 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000068 | Switchgear | WT-Swgr Sec 4 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000068 | Switchgear | WT-Swgr Sec 4 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1136 | BreakerAirMagnetic | WT-1211 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1136 | BreakerAirMagnetic | WT-1211 | AMCB Readings | 9 Months Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1136 | BreakerAirMagnetic | WT-1211 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1136 | BreakerAirMagnetic | WT-1211 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1136 | BreakerAirMagnetic | WT-1211 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1136 | BreakerAirMagnetic | WT-1211 | AMCB Readings | Amps A Ø | 0.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1136 | BreakerAirMagnetic | WT-1211 | AMCB Readings | Amps B Ø | 0.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1136 | BreakerAirMagnetic | WT-1211 | AMCB Readings | Amps C Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1136 | BreakerAirMagnetic | WT-1211 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1136 | BreakerAirMagnetic | WT-1211 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1136 | BreakerAirMagnetic | WT-1211 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1136 | BreakerAirMagnetic | WT-1211 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1136 | BreakerAirMagnetic | WT-1211 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1136 | BreakerAirMagnetic | WT-1211 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | PF000421 | PowerFuse | WT-STA SER NO 4 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | PF000421 | PowerFuse | WT-STA SER NO 4 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | PF000422 | PowerFuse | WT-12KV TR 4 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | PF000422 | PowerFuse | WT-12KV TR 4 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1136 | BreakerAirMagnetic | WT-1211 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1136 | BreakerAirMagnetic | WT-1211 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1136 | BreakerAirMagnetic | WT-1211 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1136 | BreakerAirMagnetic | WT-1211 | AMCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1136 | BreakerAirMagnetic | WT-1211 | AMCB Patrol Inspection | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | PF000423 | PowerFuse | WT-STA SER NO 5 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | PF000423 | PowerFuse | WT-STA SER NO 5 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | PF000424 | PowerFuse | WT-12KV TR 5 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | PF000424 | PowerFuse | WT-12KV TR 5 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1136 | BreakerAirMagnetic | WT-1211 | AMCB Readings | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1136 | BreakerAirMagnetic | WT-1211 | AMCB Readings | Maintenance Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1136 | BreakerAirMagnetic | WT-1211 | AMCB Readings | Operations Counter AF | 914 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1136 | BreakerAirMagnetic | WT-1211 | AMCB Readings | Operations Counter AL | 914 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1136 | BreakerAirMagnetic | WT-1211 | AMCB Readings | Operations This Read AM | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1136 | BreakerAirMagnetic | WT-1211 | AMCB Readings | Switching Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LB1136 | BreakerAirMagnetic | WT-1211 | AMCB Readings | Unknown Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | LTCC000728 | LTCControl | 400-1 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | LTCC000728 | LTCControl | 400-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | YD000297 | Yard | 400-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | YD000297 | Yard | 400-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | YD000297 | Yard | 400-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | YD000297 | Yard | 400-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | YD000297 | Yard | 400-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | YD000297 | Yard | 400-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | YD000297 | Yard | 400-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | YD000297 | Yard | 400-Yard | Yard Patrol Inspection | Ambient Temp | 74 | °F |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | LTCMechanism | 400-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | LTCMechanism | 400-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | LTCMechanism | 400-1 | LTC Counter Readings | General Comments | | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | LTCMechanism | 400-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | LTCMechanism | 400-1 | LTC Counter Readings | LTC As Found Counter | 64382 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | LTCMechanism | 400-1 | LTC Counter Readings | LTC As Left Counter | 64386 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | LTCMechanism | 400-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | LTCMechanism | 400-1 | LTC Counter Readings | LTC Current Tap Position | 2R | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | LTCMechanism | 400-1 | LTC Counter Readings | LTC Max Tap Position | 8R | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | LTCMechanism | 400-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | LTCMechanism | 400-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 20 | °C |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | LTCMechanism | 400-1 | LTC Counter Readings | LTC Operations Since Last Insp | 6933 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | LTCMechanism | 400-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | LTCMechanism | 400-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | LTCMechanism | 400-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | LTCMechanism | WT-TRANS 4 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | LTCMechanism | WT-TRANS 4 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | LTCMechanism | WT-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | LTCMechanism | WT-TRANS 4 | LTC Counter Readings | LTC Operations Since Last Insp | 193 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | LTCMechanism | WT-TRANS 4 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | LTCMechanism | WT-TRANS 4 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BAT001484 | Battery | 733-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BAT001484 | Battery | 733-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 66 | °F |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BAT001484 | Battery | 733-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BAT001484 | Battery | 733-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BAT001484 | Battery | 733-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BAT001484 | Battery | 733-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BAT001484 | Battery | 733-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BAT001484 | Battery | 733-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BAT001484 | Battery | 733-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BAT001484 | Battery | 733-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | BAT001484 | Battery | 733-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | LTCMechanism | WT-TRANS 4 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | LTCC000669 | LTCControl | 733-1 | LTC Control Insp | All Connections OK? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | LTCC000669 | LTCControl | 733-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | LTCC000669 | LTCControl | 733-1 | LTC Control Insp | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | LTCC000669 | LTCControl | 733-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | LTCC000669 | LTCControl | 733-1 | LTC Control Insp | LTC Output Voltage Level | 120.3 | VAC |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | LTCC000669 | LTCControl | 733-1 | LTC Control Insp | VRR Base Voltage AF | 120.0 | VAC |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | LTCC000669 | LTCControl | 733-1 | LTC Control Insp | VRR Base Voltage AL | 120.0 | VAC |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | LTCC000669 | LTCControl | 733-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1052 | Regulator | 476-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1052 | Regulator | 476-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1052 | Regulator | 476-1 B | Regulator Patrol Inspection | Min Tap Position | 2L | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1052 | Regulator | 476-1 B | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1052 | Regulator | 476-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1052 | Regulator | 476-1 B | Regulator Patrol Inspection | General Comments | ok | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1052 | Regulator | 476-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1052 | Regulator | 476-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1052 | Regulator | 476-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1052 | Regulator | 476-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1052 | Regulator | 476-1 B | Regulator Patrol Inspection | Current Tap Position | 3R | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1052 | Regulator | 476-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1052 | Regulator | 476-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1052 | Regulator | 476-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1052 | Regulator | 476-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | R1052 | Regulator | 476-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | ST000305 | Structure | 400-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | ST000305 | Structure | 400-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | ST000305 | Structure | 400-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | ST000305 | Structure | 400-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | ST000305 | Structure | 400-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | ST000305 | Structure | 400-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | ST000305 | Structure | 400-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | ST000305 | Structure | 400-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | ST000305 | Structure | 400-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | ST000305 | Structure | 400-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | ST000305 | Structure | 400-Structure | Structure Patrol Inspection | General Comments | | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | ST000305 | Structure | 400-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | ST000305 | Structure | 400-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | PF000418 | PowerFuse | WT-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | PF000418 | PowerFuse | WT-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | PF000420 | PowerFuse | WT-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | PF000420 | PowerFuse | WT-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | ST000305 | Structure | 400-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | ST000305 | Structure | 400-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | ST000305 | Structure | 400-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | ST000305 | Structure | 400-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | ST000305 | Structure | 400-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | ST000305 | Structure | 400-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | ST000305 | Structure | 400-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | YD000297 | Yard | 400-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | YD000297 | Yard | 400-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | YD000297 | Yard | 400-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | YD000297 | Yard | 400-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | YD000297 | Yard | 400-Yard | Yard Patrol Inspection | General Comments | | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | LTCC000728 | LTCControl | 400-1 | LTC Control Insp | All Connections OK? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | LTCC000728 | LTCControl | 400-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | LTCC000728 | LTCControl | 400-1 | LTC Control Insp | General Comments | | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | LTCC000728 | LTCControl | 400-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | LTCC000728 | LTCControl | 400-1 | LTC Control Insp | LTC Output Voltage Level | 124.2 | VAC |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | LTCC000728 | LTCControl | 400-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | LTCC000728 | LTCControl | 400-1 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Readings | Amps A Ø | 40.0 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Readings | Amps B Ø | 50.0 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Readings | Amps C Ø | 56.0 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Patrol Inspection | General Comments | | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Readings | General Comments | | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Readings | Operations Counter AF | 182 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Readings | Operations Counter AL | 183 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Readings | Operations This Read Vac | 1 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Readings | Switching Operations | 1 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Readings | X3 Winding Temp Present | 40 | °C |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Readings | X3 Winding Temp Max | 50 | °C |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Readings | X2 Winding Temp Present | 38 | °C |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Readings | X2 Winding Temp Max | 48 | °C |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Readings | X1 Winding Temp Present | 30 | °C |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Readings | X1 Winding Temp Max | 54 | °C |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Readings | X3 Winding Temp Present | 40 | °C |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Readings | X3 Winding Temp Max | 49 | °C |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Readings | X2 Winding Temp Present | 36 | °C |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Readings | X2 Winding Temp Max | 46 | °C |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Readings | X1 Winding Temp Present | 39 | °C |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Readings | X1 Winding Temp Max | 45 | °C |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .6 | psi |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Readings | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | WithLTC | WT-TRANS 5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | BCH001050 | Charger | 610-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0 | millivolts |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | BCH001050 | Charger | 610-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 57.7 | VDC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | BCH001050 | Charger | 610-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 57.7 | VDC |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | BCH001050 | Charger | 610-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .8 | amps |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | BCH001050 | Charger | 610-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | BCH001050 | Charger | 610-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | BCH001050 | Charger | 610-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | BCH001050 | Charger | 610-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001609 | BreakerVacuum | 400-2505 | VCB Readings | 9 Month Operations | 2 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Readings | Accumulated Fault Duty C Ph V | 9.77 | % |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Readings | Amps A Ø | 180.0 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Readings | Amps B Ø | 180.0 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Readings | Amps C Ø | 170.0 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Readings | Fault Adjusted Amps A Phase V | 16.38 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Readings | Fault Adjusted Amps B Phase V | 16.38 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Readings | Fault Adjusted Amps C Phase V | 16.38 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Readings | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000068 | Switchgear | WT-Swgr Sec 4 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000068 | Switchgear | WT-Swgr Sec 4 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000068 | Switchgear | WT-Swgr Sec 4 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000068 | Switchgear | WT-Swgr Sec 4 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000068 | Switchgear | WT-Swgr Sec 4 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000068 | Switchgear | WT-Swgr Sec 4 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000068 | Switchgear | WT-Swgr Sec 4 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000068 | Switchgear | WT-Swgr Sec 4 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000068 | Switchgear | WT-Swgr Sec 4 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000068 | Switchgear | WT-Swgr Sec 4 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000068 | Switchgear | WT-Swgr Sec 4 | Switchgear Patrol Inspection | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000068 | Switchgear | WT-Swgr Sec 4 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | SWG000068 | Switchgear | WT-Swgr Sec 4 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Readings | General Comments | | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Readings | LTC Totalizer Reading | 1140.00 | kw |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LTCC000341 | LTCControl | WT-TRANS 4 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LTCC000341 | LTCControl | WT-TRANS 4 | LTC Control Insp | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LTCC000341 | LTCControl | WT-TRANS 4 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/15/2023 11:41 | Distribution | Mid Valley Simpsonville Quarterly Inspection | C0451 | WithLTC | 733-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Readings | Operations Counter AF | 148 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Readings | Operations Counter AL | 148 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Readings | Operations This Read Vac | 1 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Readings | Switching Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Readings | Oil Temp Present | 32 | °C |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 100 | psi |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .8 | psi |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Patrol Inspection | General Comments | TR nitro bottle low | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Readings | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | WithLTC | WT-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Readings | General Comments | | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Readings | LTC Totalizer Reading | 10560.00 | kw |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Readings | Oil Temp Present | 46 | °C |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | S0052 | WithLTC | 400-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Readings | 9 Month Operations | 1 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Readings | Accumulated Fault Duty A Ph V | 4.88 | % |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Readings | Accumulated Fault Duty B Ph V | 3.66 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | LTCMechanism | WT-TRANS 4 | LTC Counter Readings | LTC As Left Counter | 83575 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | LTCMechanism | WT-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Patrol Inspection | General Comments | | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Readings | General Comments | | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Readings | Operations Counter AF | 203 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Readings | Operations Counter AL | 204 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Readings | Operations This Read Vac | 1 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Readings | Switching Operations | 1 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Readings | Unknown Operations | 0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | LTCMechanism | WT-TRANS 5 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | LTCMechanism | WT-TRANS 5 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Readings | General Comments | | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Patrol Inspection | General Comments | | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Readings | Amps C Ø | 202.0 | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | LTCMechanism | 422-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | LTCC000682 | LTCControl | 422-1 | LTC Control Insp | All Connections OK? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | LTCC000682 | LTCControl | 422-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | LTCC000682 | LTCControl | 422-1 | LTC Control Insp | General Comments | | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | LTCC000682 | LTCControl | 422-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | LTCC000682 | LTCControl | 422-1 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | LTCC000682 | LTCControl | 422-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | LTCC000682 | LTCControl | 422-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | LTCC000682 | LTCControl | 422-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | YD000499 | Yard | 422-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | YD000499 | Yard | 422-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | YD000499 | Yard | 422-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | LTCMechanism | 422-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | LTCMechanism | 422-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | LTCMechanism | 422-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | LTCMechanism | 422-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | LTCMechanism | 422-1 | LTC Counter Readings | LTC Operations Since Last Insp | 283 | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | LTCMechanism | 422-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | LTCMechanism | 422-1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | LTCMechanism | 422-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | LTCMechanism | 422-1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | LTCMechanism | 422-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Readings | Unknown Operations | 0 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Readings | Switching Operations | 1 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Readings | Operations This Read Vac | 1 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | LTCMechanism | WT-TRANS 5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | LTCMechanism | WT-TRANS 5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Readings | 9 Month Operations | 3 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Readings | Amps A Ø | 180.0 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Readings | Amps B Ø | 182.0 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Readings | Amps C Ø | 172.0 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | LTCMechanism | WT-TRANS 5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | LTCMechanism | WT-TRANS 5 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | LTCMechanism | WT-TRANS 5 | LTC Counter Readings | LTC Operations Since Last Insp | 215 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | LTCMechanism | WT-TRANS 5 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | LTCMechanism | WT-TRANS 5 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Readings | Operations Counter AL | 180 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Readings | Operations Counter AF | 179 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001577 | BreakerVacuum | 400-2507 | VCB Readings | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | LTCMechanism | WT-TRANS 4 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | LTCMechanism | WT-TRANS 4 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | LTCMechanism | WT-TRANS 4 | LTC Counter Readings | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | LTCMechanism | WT-TRANS 4 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0220 | LTCMechanism | WT-TRANS 4 | LTC Counter Readings | LTC As Found Counter | 83575 | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | YD000499 | Yard | 422-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001651 | BreakerVacuum | WT-1153 | VCB Readings | 9 Month Operations | 1 | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | YD000499 | Yard | 422-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | YD000499 | Yard | 422-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | YD000499 | Yard | 422-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | YD000499 | Yard | 422-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | ST000502 | Structure | 422-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | ST000502 | Structure | 422-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | ST000502 | Structure | 422-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | ST000502 | Structure | 422-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | ST000502 | Structure | 422-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | ST000502 | Structure | 422-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | ST000502 | Structure | 422-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | ST000502 | Structure | 422-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | ST000502 | Structure | 422-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | ST000502 | Structure | 422-Structure | Structure Patrol Inspection | General Comments | | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | ST000502 | Structure | 422-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | ST000502 | Structure | 422-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | ST000502 | Structure | 422-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | ST000502 | Structure | 422-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | LTCMechanism | 422-1 | LTC Counter Readings | LTC As Left Counter | 213552 | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | LTCMechanism | 422-1 | LTC Counter Readings | LTC As Found Counter | 213552 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Readings | Amps B Ø | 200.0 | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | LTCMechanism | 422-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | LTCMechanism | 422-1 | LTC Counter Readings | General Comments | | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Readings | Amps A Ø | 200.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | LTCMechanism | WT-TRANS 5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | LTCMechanism | WT-TRANS 5 | LTC Counter Readings | LTC As Left Counter | 280859 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | LTCMechanism | WT-TRANS 5 | LTC Counter Readings | LTC As Found Counter | 280859 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | B0338 | LTCMechanism | 422-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | ST000502 | Structure | 422-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | ST000502 | Structure | 422-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | LTCMechanism | WT-TRANS 5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | LTCMechanism | WT-TRANS 5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | LTCMechanism | WT-TRANS 5 | LTC Counter Readings | General Comments | | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | LT0221 | LTCMechanism | WT-TRANS 5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | ST000502 | Structure | 422-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | ST000502 | Structure | 422-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/15/2023 14:34 | Distribution | Florida Tile Quarterly Inspection | BK001576 | BreakerVacuum | 400-2506 | VCB Readings | 9 Month Operations | 1 | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | ST000502 | Structure | 422-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | ST000502 | Structure | 422-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | ST000502 | Structure | 422-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | ST000502 | Structure | 422-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | YD000499 | Yard | 422-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | YD000499 | Yard | 422-Yard | Yard Patrol Inspection | General Comments | | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | YD000499 | Yard | 422-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001651 | BreakerVacuum | WT-1153 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001651 | BreakerVacuum | WT-1153 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001651 | BreakerVacuum | WT-1153 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001651 | BreakerVacuum | WT-1153 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001651 | BreakerVacuum | WT-1153 | VCB Readings | Amps C Ø | 54.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001651 | BreakerVacuum | WT-1153 | VCB Readings | Amps B Ø | 71.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001651 | BreakerVacuum | WT-1153 | VCB Readings | Amps A Ø | 58.0 | |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001651 | BreakerVacuum | WT-1153 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001651 | BreakerVacuum | WT-1153 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001651 | BreakerVacuum | WT-1153 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/17/2023 7:33 | Distribution | Watterson Quarterly Inspection | BK001651 | BreakerVacuum | WT-1153 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | YD000499 | Yard | 422-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | YD000499 | Yard | 422-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | YD000499 | Yard | 422-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | YD000499 | Yard | 422-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | YD000499 | Yard | 422-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | BCH000455 | Charger | Retired Distribution | Battery Charger Patrol Insp | As Left Float Voltage | 55.1 | VDC |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | BCH000455 | Charger | Retired Distribution | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | BCH000455 | Charger | Retired Distribution | Battery Charger Patrol Insp | As Found Float Voltage | 55.1 | VDC |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | BCH000455 | Charger | Retired Distribution | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .700 | millivolts |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | BCH000455 | Charger | Retired Distribution | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | BCH000455 | Charger | Retired Distribution | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | BCH000455 | Charger | Retired Distribution | Battery Charger Patrol Insp | General Comments | ok | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | BCH000455 | Charger | Retired Distribution | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Amps C Ø | 65.0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Amps B Ø | 65.0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Amps A Ø | 65.0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | 9 Month Operations | 0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Operations This Read Vac | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Operations Counter AL | 12 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Operations Counter AF | 12 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | General Comments | ok | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | General Comments | ok | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0149 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Operations Counter AL | 7 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Operations Counter AF | 7 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | General Comments | ok | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Amps C Ø | 85.0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Amps B Ø | 60.0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Amps A Ø | 75.0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | 9 Month Operations | 0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | General Comments | ok | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | WB0150 | BreakerVacuum | 912-Offline-Distribution | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Readings | 9 Month Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Readings | Amps A Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Readings | Amps B Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Readings | Amps C Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1316 | BreakerVacuum | OH-1173 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1316 | BreakerVacuum | OH-1173 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1316 | BreakerVacuum | OH-1173 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1316 | BreakerVacuum | OH-1173 | VCB Readings | Operations Counter AL | 191 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1316 | BreakerVacuum | OH-1173 | VCB Readings | Operations Counter AF | 191 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Readings | 9 Month Ops New | 2 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Readings | 9 Months Operations | 4 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Readings | Accumulated Fault Duty A Ph AM | 26.48 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Readings | Accumulated Fault Duty B Ph AM | 6.11 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Readings | Accumulated Fault Duty C Ph AM | 4.07 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Readings | Amps A Ø | 92.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Readings | Amps A Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Readings | Amps B Ø | 102.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1316 | BreakerVacuum | OH-1173 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Readings | Amps B Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0588 | BreakerAirMagnetic | MD-1452 | AMCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0588 | BreakerAirMagnetic | MD-1452 | AMCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0588 | BreakerAirMagnetic | MD-1452 | AMCB Readings | Operations This Read AM | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0588 | BreakerAirMagnetic | MD-1452 | AMCB Readings | Operations Counter AL | 974 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0588 | BreakerAirMagnetic | MD-1452 | AMCB Readings | Operations Counter AF | 974 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0588 | BreakerAirMagnetic | MD-1452 | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCM000019 | LTCMechanism | PV-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 18 | °C |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Readings | Amps C Ø | 67.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Readings | Amps C Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Readings | Fault Adjusted Amps B Phase AM | 19.09 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | needs nitro | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCM000019 | LTCMechanism | PV-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 189 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCM000019 | LTCMechanism | PV-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 36 | °C |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Readings | Fault Operations B Ø | 2 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | LTCMechanism | 221-2 | LTC Counter Readings | LTC As Left Counter | 220987 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | LTCMechanism | 221-2 | LTC Counter Readings | LTC As Found Counter | 220987 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Counter Readings | LTC Current Tap Position | 6 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Counter Readings | LTC Operations Since Last Insp | 8 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | LTCMechanism | 221-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | LTCMechanism | 221-2 | LTC Counter Readings | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | LTCMechanism | 221-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | LTCMechanism | 221-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1316 | BreakerVacuum | OH-1173 | VCB Readings | General Comments | | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1316 | BreakerVacuum | OH-1173 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1316 | BreakerVacuum | OH-1173 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1316 | BreakerVacuum | OH-1173 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1316 | BreakerVacuum | OH-1173 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1316 | BreakerVacuum | OH-1173 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1316 | BreakerVacuum | OH-1173 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1316 | BreakerVacuum | OH-1173 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1316 | BreakerVacuum | OH-1173 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCM000019 | LTCMechanism | PV-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 2.5 | psi |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCM000019 | LTCMechanism | PV-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCM000019 | LTCMechanism | PV-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 5L | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCM000019 | LTCMechanism | PV-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCM000019 | LTCMechanism | PV-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCM000019 | LTCMechanism | PV-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 13019 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCM000019 | LTCMechanism | PV-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 13019 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCM000019 | LTCMechanism | PV-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCM000019 | LTCMechanism | PV-TRANS 2 | LTC Counter Readings | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCM000019 | LTCMechanism | PV-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCM000019 | LTCMechanism | PV-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | TX000035 | WithLTC | PV-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | TX000035 | WithLTC | PV-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | TX000035 | WithLTC | PV-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | TX000035 | WithLTC | PV-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | TX000035 | WithLTC | PV-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1000 | psi |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | TX000035 | WithLTC | PV-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | TX000035 | WithLTC | PV-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | TX000035 | WithLTC | PV-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | TX000035 | WithLTC | PV-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1316 | BreakerVacuum | OH-1173 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1316 | BreakerVacuum | OH-1173 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1316 | BreakerVacuum | OH-1173 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | TX000035 | WithLTC | PV-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | TX000035 | WithLTC | PV-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | TX000035 | WithLTC | PV-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | TX000035 | WithLTC | PV-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1308 | BreakerVacuum | MD-14KV BUS TIE SEC 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1308 | BreakerVacuum | MD-14KV BUS TIE SEC 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1308 | BreakerVacuum | MD-14KV BUS TIE SEC 3 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1308 | BreakerVacuum | MD-14KV BUS TIE SEC 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1308 | BreakerVacuum | MD-14KV BUS TIE SEC 3 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1308 | BreakerVacuum | MD-14KV BUS TIE SEC 3 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1308 | BreakerVacuum | MD-14KV BUS TIE SEC 3 | VCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1308 | BreakerVacuum | MD-14KV BUS TIE SEC 3 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1308 | BreakerVacuum | MD-14KV BUS TIE SEC 3 | VCB Readings | Operations Counter AF | 235 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1308 | BreakerVacuum | MD-14KV BUS TIE SEC 3 | VCB Readings | Operations Counter AL | 235 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1308 | BreakerVacuum | MD-14KV BUS TIE SEC 3 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1308 | BreakerVacuum | MD-14KV BUS TIE SEC 3 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1308 | BreakerVacuum | MD-14KV BUS TIE SEC 3 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Readings | 9 Month Operations | 1 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Readings | Amps A Ø | 400.0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Readings | Amps B Ø | 400.0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Readings | Amps C Ø | 400.0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | FE000198 | Fence | 496-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | FE000198 | Fence | 496-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | FE000198 | Fence | 496-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 55 | °C |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 50 | °C |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1308 | BreakerVacuum | MD-14KV BUS TIE SEC 3 | VCB Readings | 9 Month Operations | 1 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCM000019 | LTCMechanism | PV-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1308 | BreakerVacuum | MD-14KV BUS TIE SEC 3 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1308 | BreakerVacuum | MD-14KV BUS TIE SEC 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1308 | BreakerVacuum | MD-14KV BUS TIE SEC 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1308 | BreakerVacuum | MD-14KV BUS TIE SEC 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0472 | RecloserHydraulic | 865-1731 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 252 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1308 | BreakerVacuum | MD-14KV BUS TIE SEC 3 | VCB Readings | Amps A Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1308 | BreakerVacuum | MD-14KV BUS TIE SEC 3 | VCB Readings | Amps B Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1308 | BreakerVacuum | MD-14KV BUS TIE SEC 3 | VCB Readings | Amps C Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1308 | BreakerVacuum | MD-14KV BUS TIE SEC 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1308 | BreakerVacuum | MD-14KV BUS TIE SEC 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1308 | BreakerVacuum | MD-14KV BUS TIE SEC 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Readings | Operations Counter AF | 170 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Readings | Operations Counter AL | 170 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0595 | BreakerVacuum | MD-CAP BK 2 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | LTCMechanism | 221-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1308 | BreakerVacuum | MD-14KV BUS TIE SEC 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1308 | BreakerVacuum | MD-14KV BUS TIE SEC 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0472 | RecloserHydraulic | 865-1731 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0472 | RecloserHydraulic | 865-1731 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0472 | RecloserHydraulic | 865-1731 | Recloser Hydraulic Patrol Inspection | General Comments | ok | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0472 | RecloserHydraulic | 865-1731 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0472 | RecloserHydraulic | 865-1731 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0472 | RecloserHydraulic | 865-1731 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Counter Readings | LTC As Found Counter | 60144 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Counter Readings | LTC As Left Counter | 60144 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | LTCMechanism | 221-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | LTCMechanism | 221-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | LTCMechanism | 221-2 | LTC Counter Readings | LTC Operations Since Last Insp | 146 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | LTCMechanism | 221-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | LTCMechanism | 221-2 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | LTCMechanism | 221-2 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | LTCMechanism | 221-2 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | LTCMechanism | 221-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | needs nitro | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Readings | 9 Month Operations | 2 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Readings | Switching Operations | 1 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Readings | Operations This Read AM | 1 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Readings | Operations Counter AL | 750 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Readings | Operations Counter AF | 750 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Readings | General Comments | ok | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Readings | Amps C Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Readings | Amps C Ø | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Readings | Amps B Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Readings | Amps B Ø | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Readings | Amps A Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Readings | Amps A Ø | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Readings | 9 Months Operations | 2 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0919 | BreakerAirMagnetic | S-1496 | AMCB Readings | 9 Month Ops New | 1 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 135.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 34 | °C |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 32 | °C |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Readings | Switching Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Readings | Operations This Read AM | 2 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Readings | Operations Counter AL | 4517 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Readings | Operations Counter AF | 4517 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Readings | General Comments | B phase TOC | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0927 | BreakerAirMagnetic | S-453 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | YD000657 | Yard | PV-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | LTCMechanism | 220-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Readings | Operations Counter AL | 99885 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Readings | Operations Counter AF | 99885 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Readings | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | LTCMechanism | 220-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | LTCMechanism | 220-2 | LTC Counter Readings | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | LTCMechanism | 220-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | LTCMechanism | 220-2 | LTC Counter Readings | LTC As Found Counter | 309775 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | LTCMechanism | 220-2 | LTC Counter Readings | LTC As Left Counter | 309775 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | LTCMechanism | 220-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | LTCMechanism | 220-2 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | LTCMechanism | 220-2 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | WithLTC | S-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | LTCMechanism | 220-2 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | LTCMechanism | 220-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.5 | psi |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | LTCMechanism | 220-2 | LTC Counter Readings | LTC Operations Since Last Insp | 464 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | LTCMechanism | 220-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | LTCMechanism | 220-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | LTCMechanism | 220-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Readings | Amps C Ø | 0.0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Readings | Amps B Ø | 0.0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Readings | Amps A Ø | 0.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0420 | BreakerVacuum | 221-102 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Readings | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCC000623 | LTCControl | PV-TRANS 2 | LTC Control Insp | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCC000623 | LTCControl | PV-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0588 | BreakerAirMagnetic | MD-1452 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0588 | BreakerAirMagnetic | MD-1452 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0588 | BreakerAirMagnetic | MD-1452 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0588 | BreakerAirMagnetic | MD-1452 | AMCB Readings | Amps A Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0588 | BreakerAirMagnetic | MD-1452 | AMCB Readings | Amps B Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0588 | BreakerAirMagnetic | MD-1452 | AMCB Readings | Amps C Ø | 0.0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0588 | BreakerAirMagnetic | MD-1452 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0588 | BreakerAirMagnetic | MD-1452 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0588 | BreakerAirMagnetic | MD-1452 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Readings | Amps C Ø | 0.0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Readings | Amps B Ø | 0.0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Readings | Amps A Ø | 0.0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Readings | 9 Month Operations VCB New | 19 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Readings | 9 Month Operations | 19 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | YD000657 | Yard | PV-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | YD000657 | Yard | PV-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | YD000657 | Yard | PV-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | YD000657 | Yard | PV-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | YD000657 | Yard | PV-Yard | Yard Patrol Inspection | Ambient Temp | 44 | °F |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0588 | BreakerAirMagnetic | MD-1452 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0588 | BreakerAirMagnetic | MD-1452 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0588 | BreakerAirMagnetic | MD-1452 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0588 | BreakerAirMagnetic | MD-1452 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0588 | BreakerAirMagnetic | MD-1452 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0588 | BreakerAirMagnetic | MD-1452 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0588 | BreakerAirMagnetic | MD-1452 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0588 | BreakerAirMagnetic | MD-1452 | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0588 | BreakerAirMagnetic | MD-1452 | AMCB Readings | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCC000623 | LTCControl | PV-TRANS 2 | LTC Control Insp | All Connections OK? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCM000019 | LTCMechanism | PV-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCM000019 | LTCMechanism | PV-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCM000019 | LTCMechanism | PV-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCM000019 | LTCMechanism | PV-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | WithLTC | S-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | YD000657 | Yard | PV-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | YD000657 | Yard | PV-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | YD000657 | Yard | PV-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | YD000657 | Yard | PV-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | YD000657 | Yard | PV-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | YD000657 | Yard | PV-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | YD000657 | Yard | PV-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000548 | LTCControl | 220-3 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000548 | LTCControl | 220-3 | LTC Control Insp | VRR Base Voltage AL | 121.0 | VAC |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000548 | LTCControl | 220-3 | LTC Control Insp | VRR Base Voltage AF | 121.0 | VAC |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000548 | LTCControl | 220-3 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000548 | LTCControl | 220-3 | LTC Control Insp | LTC Output Voltage Level | 121.0 | VAC |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000548 | LTCControl | 220-3 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000548 | LTCControl | 220-3 | LTC Control Insp | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000548 | LTCControl | 220-3 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000548 | LTCControl | 220-3 | LTC Control Insp | All Connections OK? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | YD000657 | Yard | PV-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | YD000657 | Yard | PV-Yard | Yard Patrol Inspection | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | YD000657 | Yard | PV-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | YD000657 | Yard | PV-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | YD000657 | Yard | PV-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | YD000657 | Yard | PV-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | YD000657 | Yard | PV-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | LTCMechanism | OH-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | LTCMechanism | OH-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0472 | RecloserHydraulic | 865-1731 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 281 | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0472 | RecloserHydraulic | 865-1731 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 11.7 | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0472 | RecloserHydraulic | 865-1731 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 12.5 | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0472 | RecloserHydraulic | 865-1731 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 9.9 | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0472 | RecloserHydraulic | 865-1731 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 258 | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0472 | RecloserHydraulic | 865-1731 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0472 | RecloserHydraulic | 865-1731 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | LTCMechanism | OH-TRANS 1 | LTC Counter Readings | General Comments | | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | LTCMechanism | OH-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | LTCMechanism | OH-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 48745 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | LTCMechanism | OH-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 48745 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | LTCMechanism | OH-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | LTCMechanism | OH-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | LTCMechanism | OH-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | LTCMechanism | OH-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | LTCMechanism | OH-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | LTCMechanism | OH-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 28 | °C |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | LTCMechanism | OH-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 16 | °C |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | LTCMechanism | OH-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 245 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | LTCMechanism | OH-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | LTCMechanism | OH-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | LTCMechanism | OH-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | LTCMechanism | OH-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Readings | Operations Counter AL | 145 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0588 | BreakerAirMagnetic | MD-1452 | AMCB Readings | 9 Month Ops New | 20 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0588 | BreakerAirMagnetic | MD-1452 | AMCB Readings | 9 Months Operations | 20 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCC000623 | LTCControl | PV-TRANS 2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCC000623 | LTCControl | PV-TRANS 2 | LTC Control Insp | VRR Base Voltage AL | 123.0 | VAC |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCC000623 | LTCControl | PV-TRANS 2 | LTC Control Insp | VRR Base Voltage AF | 123.3 | VAC |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCC000623 | LTCControl | PV-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCC000623 | LTCControl | PV-TRANS 2 | LTC Control Insp | LTC Output Voltage Level | 123.3 | VAC |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LTCC000623 | LTCControl | PV-TRANS 2 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Readings | Operations Counter AF | 145 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0023 | BreakerVacuum | 221-122 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | ST000262 | Structure | 648-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | ST000262 | Structure | 648-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | ST000262 | Structure | 648-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | ST000262 | Structure | 648-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | ST000262 | Structure | 648-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | ST000262 | Structure | 648-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | ST000262 | Structure | 648-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | ST000262 | Structure | 648-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | ST000262 | Structure | 648-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | LTCMechanism | MD-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .8 | psi |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | LTCMechanism | MD-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 7 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | LTCMechanism | MD-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 17 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | LTCMechanism | MD-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 16 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | LTCMechanism | MD-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | LTCMechanism | MD-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 174547 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | LTCMechanism | MD-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 174547 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | LTCMechanism | MD-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | LTCMechanism | MD-TRANS 2 | LTC Counter Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | LTCMechanism | MD-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | LTCMechanism | MD-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | LTCMechanism | MD-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | LTCMechanism | MD-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | LTCMechanism | MD-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | LTCMechanism | MD-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 167 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | LTCMechanism | MD-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000766 | LTCControl | 221-4 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000766 | LTCControl | 221-4 | LTC Control Insp | VRR Base Voltage AL | 120.0 | VAC |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000766 | LTCControl | 221-4 | LTC Control Insp | VRR Base Voltage AF | 120.0 | VAC |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | ST000262 | Structure | 648-Structure | Structure Patrol Inspection | General Comments | ok | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LTCC000473 | LTCControl | AS-TRANS 4 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LTCC000473 | LTCControl | AS-TRANS 4 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001370 | BreakerVacuum | PV-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations | 3 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001370 | BreakerVacuum | PV-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001370 | BreakerVacuum | PV-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001370 | BreakerVacuum | PV-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000766 | LTCControl | 221-4 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000766 | LTCControl | 221-4 | LTC Control Insp | LTC Output Voltage Level | 121.0 | VAC |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | LTCMechanism | MD-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 3L | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | LTCMechanism | MD-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 9 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | LTCMechanism | MD-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 7 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | LTCMechanism | MD-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | LTCMechanism | MD-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 12130 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Readings | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Readings | Amps C Ø | 535.0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Readings | Amps B Ø | 570.0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Readings | Amps A Ø | 545.0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Readings | 9 Month Operations VCB New | 15 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Readings | 9 Month Operations | 15 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LTCC000419 | LTCControl | AS-TRANS 3 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LTCC000419 | LTCControl | AS-TRANS 3 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | LTCMechanism | MD-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | LTCMechanism | MD-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | LTCMechanism | MD-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | LTCMechanism | MD-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | LTCMechanism | MD-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 422 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | LTCMechanism | MD-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 44 | °C |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | LTCMechanism | MD-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 25 | °C |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | LTCMechanism | MD-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | ST000262 | Structure | 648-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | ST000262 | Structure | 648-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | ST000262 | Structure | 648-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0794 | BreakerAirMagnetic | PV-1254 | AMCB Readings | Operations This Read AM | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0794 | BreakerAirMagnetic | PV-1254 | AMCB Readings | Operations Counter AL | 42 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0794 | BreakerAirMagnetic | PV-1254 | AMCB Readings | Operations Counter AF | 42 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0596 | BreakerAirMagnetic | MD-GND TR 1 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | LTCMechanism | MD-TRANS 1 | LTC Counter Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | LTCMechanism | MD-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | LTCMechanism | MD-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCM000079 | LTCMechanism | 221-4 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCM000079 | LTCMechanism | 221-4 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCM000079 | LTCMechanism | 221-4 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0596 | BreakerAirMagnetic | MD-GND TR 1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0596 | BreakerAirMagnetic | MD-GND TR 1 | AMCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0596 | BreakerAirMagnetic | MD-GND TR 1 | AMCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0596 | BreakerAirMagnetic | MD-GND TR 1 | AMCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0596 | BreakerAirMagnetic | MD-GND TR 1 | AMCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0596 | BreakerAirMagnetic | MD-GND TR 1 | AMCB Readings | Operations Counter AF | 322 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0596 | BreakerAirMagnetic | MD-GND TR 1 | AMCB Readings | Operations Counter AL | 322 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0596 | BreakerAirMagnetic | MD-GND TR 1 | AMCB Readings | Operations This Read AM | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0596 | BreakerAirMagnetic | MD-GND TR 1 | AMCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0596 | BreakerAirMagnetic | MD-GND TR 1 | AMCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCM000079 | LTCMechanism | 221-4 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCM000079 | LTCMechanism | 221-4 | LTC Counter Readings | LTC Operations Since Last Insp | 597 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCM000079 | LTCMechanism | 221-4 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 25 | °C |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCM000079 | LTCMechanism | 221-4 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 35 | °C |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCM000079 | LTCMechanism | 221-4 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCM000079 | LTCMechanism | 221-4 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCM000079 | LTCMechanism | 221-4 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0794 | BreakerAirMagnetic | PV-1254 | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0794 | BreakerAirMagnetic | PV-1254 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0794 | BreakerAirMagnetic | PV-1254 | AMCB Readings | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0794 | BreakerAirMagnetic | PV-1254 | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0794 | BreakerAirMagnetic | PV-1254 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0794 | BreakerAirMagnetic | PV-1254 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0794 | BreakerAirMagnetic | PV-1254 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0794 | BreakerAirMagnetic | PV-1254 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0794 | BreakerAirMagnetic | PV-1254 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0794 | BreakerAirMagnetic | PV-1254 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0794 | BreakerAirMagnetic | PV-1254 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0794 | BreakerAirMagnetic | PV-1254 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0794 | BreakerAirMagnetic | PV-1254 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0794 | BreakerAirMagnetic | PV-1254 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0794 | BreakerAirMagnetic | PV-1254 | AMCB Readings | Amps C Ø | 75.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0794 | BreakerAirMagnetic | PV-1254 | AMCB Readings | Amps B Ø | 75.0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000766 | LTCControl | 221-4 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000766 | LTCControl | 221-4 | LTC Control Insp | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000766 | LTCControl | 221-4 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000766 | LTCControl | 221-4 | LTC Control Insp | All Connections OK? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | LTCMechanism | MD-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 12130 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | LTCMechanism | MD-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001370 | BreakerVacuum | PV-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001370 | BreakerVacuum | PV-12KV BUS TIE SEC 2 | VCB Readings | Amps A Ø | 0.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001370 | BreakerVacuum | PV-12KV BUS TIE SEC 2 | VCB Readings | Amps B Ø | 0.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001370 | BreakerVacuum | PV-12KV BUS TIE SEC 2 | VCB Readings | Amps C Ø | 0.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001370 | BreakerVacuum | PV-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001370 | BreakerVacuum | PV-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001370 | BreakerVacuum | PV-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001370 | BreakerVacuum | PV-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001370 | BreakerVacuum | PV-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001370 | BreakerVacuum | PV-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001370 | BreakerVacuum | PV-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001370 | BreakerVacuum | PV-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001370 | BreakerVacuum | PV-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001370 | BreakerVacuum | PV-12KV BUS TIE SEC 2 | VCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001370 | BreakerVacuum | PV-12KV BUS TIE SEC 2 | VCB Patrol Inspection | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001370 | BreakerVacuum | PV-12KV BUS TIE SEC 2 | VCB Readings | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001370 | BreakerVacuum | PV-12KV BUS TIE SEC 2 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001370 | BreakerVacuum | PV-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AF | 120 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001370 | BreakerVacuum | PV-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AL | 120 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001370 | BreakerVacuum | PV-12KV BUS TIE SEC 2 | VCB Readings | Operations This Read Vac | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001370 | BreakerVacuum | PV-12KV BUS TIE SEC 2 | VCB Readings | Switching Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001370 | BreakerVacuum | PV-12KV BUS TIE SEC 2 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | ST000262 | Structure | 648-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | ST000262 | Structure | 648-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0596 | BreakerAirMagnetic | MD-GND TR 1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0596 | BreakerAirMagnetic | MD-GND TR 1 | AMCB Readings | Amps A Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0596 | BreakerAirMagnetic | MD-GND TR 1 | AMCB Readings | Amps B Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0596 | BreakerAirMagnetic | MD-GND TR 1 | AMCB Readings | Amps C Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0596 | BreakerAirMagnetic | MD-GND TR 1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0596 | BreakerAirMagnetic | MD-GND TR 1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0596 | BreakerAirMagnetic | MD-GND TR 1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0596 | BreakerAirMagnetic | MD-GND TR 1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0596 | BreakerAirMagnetic | MD-GND TR 1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0596 | BreakerAirMagnetic | MD-GND TR 1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0596 | BreakerAirMagnetic | MD-GND TR 1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0794 | BreakerAirMagnetic | PV-1254 | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0794 | BreakerAirMagnetic | PV-1254 | AMCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0583 | BreakerAirMagnetic | MD-1448-B | AMCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0583 | BreakerAirMagnetic | MD-1448-B | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0583 | BreakerAirMagnetic | MD-1448-B | AMCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0583 | BreakerAirMagnetic | MD-1448-B | AMCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0583 | BreakerAirMagnetic | MD-1448-B | AMCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0583 | BreakerAirMagnetic | MD-1448-B | AMCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0583 | BreakerAirMagnetic | MD-1448-B | AMCB Readings | Operations Counter AF | 517 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0583 | BreakerAirMagnetic | MD-1448-B | AMCB Readings | Operations Counter AL | 517 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0583 | BreakerAirMagnetic | MD-1448-B | AMCB Readings | Operations This Read AM | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0583 | BreakerAirMagnetic | MD-1448-B | AMCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0583 | BreakerAirMagnetic | MD-1448-B | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001368 | BreakerVacuum | PV-1259 | VCB Readings | 9 Month Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001368 | BreakerVacuum | PV-1259 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001368 | BreakerVacuum | PV-1259 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001368 | BreakerVacuum | PV-1259 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001368 | BreakerVacuum | PV-1259 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001368 | BreakerVacuum | PV-1259 | VCB Readings | Amps A Ø | 0.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001368 | BreakerVacuum | PV-1259 | VCB Readings | Amps B Ø | 0.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001368 | BreakerVacuum | PV-1259 | VCB Readings | Amps C Ø | 0.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001368 | BreakerVacuum | PV-1259 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001368 | BreakerVacuum | PV-1259 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001368 | BreakerVacuum | PV-1259 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001368 | BreakerVacuum | PV-1259 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1312 | BreakerVacuum | OH-12KV TR 1 | VCB Readings | Operations Counter AL | 152 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1312 | BreakerVacuum | OH-12KV TR 1 | VCB Readings | Operations Counter AF | 152 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1312 | BreakerVacuum | OH-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1312 | BreakerVacuum | OH-12KV TR 1 | VCB Readings | General Comments | | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1312 | BreakerVacuum | OH-12KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1312 | BreakerVacuum | OH-12KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1312 | BreakerVacuum | OH-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1312 | BreakerVacuum | OH-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1312 | BreakerVacuum | OH-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1312 | BreakerVacuum | OH-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1312 | BreakerVacuum | OH-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1312 | BreakerVacuum | OH-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1312 | BreakerVacuum | OH-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1312 | BreakerVacuum | OH-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1312 | BreakerVacuum | OH-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1312 | BreakerVacuum | OH-12KV TR 1 | VCB Readings | Amps C Ø | 765.0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1312 | BreakerVacuum | OH-12KV TR 1 | VCB Readings | Amps B Ø | 764.0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1312 | BreakerVacuum | OH-12KV TR 1 | VCB Readings | Amps A Ø | 787.0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1312 | BreakerVacuum | OH-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001368 | BreakerVacuum | PV-1259 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001367 | BreakerVacuum | PV-1258 | VCB Readings | 9 Month Operations | 1 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001367 | BreakerVacuum | PV-1258 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001367 | BreakerVacuum | PV-1258 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001367 | BreakerVacuum | PV-1258 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001367 | BreakerVacuum | PV-1258 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001367 | BreakerVacuum | PV-1258 | VCB Readings | Amps A Ø | 1.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001367 | BreakerVacuum | PV-1258 | VCB Readings | Amps B Ø | 1.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001367 | BreakerVacuum | PV-1258 | VCB Readings | Amps C Ø | 1.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001367 | BreakerVacuum | PV-1258 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001367 | BreakerVacuum | PV-1258 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001367 | BreakerVacuum | PV-1258 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001367 | BreakerVacuum | PV-1258 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001367 | BreakerVacuum | PV-1258 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001367 | BreakerVacuum | PV-1258 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001367 | BreakerVacuum | PV-1258 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001367 | BreakerVacuum | PV-1258 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001367 | BreakerVacuum | PV-1258 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001367 | BreakerVacuum | PV-1258 | VCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001367 | BreakerVacuum | PV-1258 | VCB Patrol Inspection | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001367 | BreakerVacuum | PV-1258 | VCB Readings | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001367 | BreakerVacuum | PV-1258 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001367 | BreakerVacuum | PV-1258 | VCB Readings | Operations Counter AF | 137 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001367 | BreakerVacuum | PV-1258 | VCB Readings | Operations Counter AL | 137 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001367 | BreakerVacuum | PV-1258 | VCB Readings | Operations This Read Vac | 1 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001367 | BreakerVacuum | PV-1258 | VCB Readings | Switching Operations | 1 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001367 | BreakerVacuum | PV-1258 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0583 | BreakerAirMagnetic | MD-1448-B | AMCB Readings | 9 Months Operations | 12 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0583 | BreakerAirMagnetic | MD-1448-B | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0583 | BreakerAirMagnetic | MD-1448-B | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0583 | BreakerAirMagnetic | MD-1448-B | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0583 | BreakerAirMagnetic | MD-1448-B | AMCB Readings | Amps A Ø | 120.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0583 | BreakerAirMagnetic | MD-1448-B | AMCB Readings | Amps B Ø | 120.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0583 | BreakerAirMagnetic | MD-1448-B | AMCB Readings | Amps C Ø | 120.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0583 | BreakerAirMagnetic | MD-1448-B | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0583 | BreakerAirMagnetic | MD-1448-B | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0583 | BreakerAirMagnetic | MD-1448-B | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0583 | BreakerAirMagnetic | MD-1448-B | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1312 | BreakerVacuum | OH-12KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1312 | BreakerVacuum | OH-12KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1312 | BreakerVacuum | OH-12KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0583 | BreakerAirMagnetic | MD-1448-B | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0583 | BreakerAirMagnetic | MD-1448-B | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0583 | BreakerAirMagnetic | MD-1448-B | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001369 | BreakerVacuum | PV-12KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001369 | BreakerVacuum | PV-12KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001369 | BreakerVacuum | PV-12KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001369 | BreakerVacuum | PV-12KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001369 | BreakerVacuum | PV-12KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001369 | BreakerVacuum | PV-12KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001369 | BreakerVacuum | PV-12KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001369 | BreakerVacuum | PV-12KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001369 | BreakerVacuum | PV-12KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001369 | BreakerVacuum | PV-12KV TR 2 | VCB Readings | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001369 | BreakerVacuum | PV-12KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1312 | BreakerVacuum | OH-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1312 | BreakerVacuum | OH-12KV TR 1 | VCB Readings | 9 Month Operations | 10 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | LTCMechanism | 648-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | LTCMechanism | 648-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | LTCMechanism | 648-1 | LTC Counter Readings | General Comments | low indicator arm follows step | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | LTCMechanism | 648-1 | LTC Mechanism Patrol Inspection | General Comments | ok | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | LTCMechanism | 648-1 | LTC Counter Readings | LTC As Found Counter | 15083 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | LTCMechanism | 648-1 | LTC Counter Readings | LTC As Left Counter | 15093 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | LTCMechanism | 648-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | LTCMechanism | 648-1 | LTC Counter Readings | LTC Current Tap Position | 2R | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | LTCMechanism | 648-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | LTCMechanism | 648-1 | LTC Counter Readings | LTC Min Tap Position | 2R | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | LTCMechanism | 648-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | LTCMechanism | 648-1 | LTC Counter Readings | LTC Operations Since Last Insp | 251 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | LTCMechanism | 648-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | LTCMechanism | 648-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | LTCMechanism | 648-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | LTCMechanism | 648-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001369 | BreakerVacuum | PV-12KV TR 2 | VCB Readings | Operations Counter AF | 153 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001369 | BreakerVacuum | PV-12KV TR 2 | VCB Readings | Operations Counter AL | 153 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001369 | BreakerVacuum | PV-12KV TR 2 | VCB Readings | Operations This Read Vac | 1 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001369 | BreakerVacuum | PV-12KV TR 2 | VCB Readings | Switching Operations | 1 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001369 | BreakerVacuum | PV-12KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Readings | Operations Counter AL | 99913 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Readings | Operations Counter AF | 99913 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0421 | BreakerVacuum | 221-118 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001368 | BreakerVacuum | PV-1259 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001368 | BreakerVacuum | PV-1259 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001368 | BreakerVacuum | PV-1259 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001368 | BreakerVacuum | PV-1259 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001368 | BreakerVacuum | PV-1259 | VCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001368 | BreakerVacuum | PV-1259 | VCB Patrol Inspection | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001368 | BreakerVacuum | PV-1259 | VCB Readings | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001368 | BreakerVacuum | PV-1259 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001368 | BreakerVacuum | PV-1259 | VCB Readings | Operations Counter AF | 103 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001368 | BreakerVacuum | PV-1259 | VCB Readings | Operations Counter AL | 103 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001368 | BreakerVacuum | PV-1259 | VCB Readings | Operations This Read Vac | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001368 | BreakerVacuum | PV-1259 | VCB Readings | Switching Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001368 | BreakerVacuum | PV-1259 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | YD000255 | Yard | 648-Yard | Yard Patrol Inspection | Ambient Temp | 54 | °F |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0596 | BreakerAirMagnetic | MD-GND TR 1 | AMCB Readings | 9 Month Ops New | 3 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0596 | BreakerAirMagnetic | MD-GND TR 1 | AMCB Readings | 9 Months Operations | 3 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0596 | BreakerAirMagnetic | MD-GND TR 1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0596 | BreakerAirMagnetic | MD-GND TR 1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | YD000255 | Yard | 648-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | YD000255 | Yard | 648-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | YD000255 | Yard | 648-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | YD000255 | Yard | 648-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | YD000255 | Yard | 648-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | YD000255 | Yard | 648-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | YD000255 | Yard | 648-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | YD000255 | Yard | 648-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | YD000255 | Yard | 648-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | YD000255 | Yard | 648-Yard | Yard Patrol Inspection | General Comments | SPR removed | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | YD000255 | Yard | 648-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | YD000255 | Yard | 648-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | n | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | YD000255 | Yard | 648-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | YD000255 | Yard | 648-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001369 | BreakerVacuum | PV-12KV TR 2 | VCB Readings | 9 Month Operations | 1 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001369 | BreakerVacuum | PV-12KV TR 2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1312 | BreakerVacuum | OH-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1312 | BreakerVacuum | OH-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001369 | BreakerVacuum | PV-12KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001369 | BreakerVacuum | PV-12KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001369 | BreakerVacuum | PV-12KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001369 | BreakerVacuum | PV-12KV TR 2 | VCB Readings | Amps A Ø | 160.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001369 | BreakerVacuum | PV-12KV TR 2 | VCB Readings | Amps B Ø | 151.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001369 | BreakerVacuum | PV-12KV TR 2 | VCB Readings | Amps C Ø | 215.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001369 | BreakerVacuum | PV-12KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | CH000210 | ControlHouse | OH-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | CH000210 | ControlHouse | OH-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | CH000210 | ControlHouse | OH-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | CH000210 | ControlHouse | OH-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | CH000210 | ControlHouse | OH-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | CH000210 | ControlHouse | OH-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | CH000210 | ControlHouse | OH-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | CH000210 | ControlHouse | OH-Control House | Control House Patrol Inspection | General Comments | | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | CH000210 | ControlHouse | OH-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | CH000210 | ControlHouse | OH-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | CH000210 | ControlHouse | OH-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | CH000210 | ControlHouse | OH-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | CH000210 | ControlHouse | OH-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | CH000210 | ControlHouse | OH-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.2 | psi |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1200 | psi |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 39 | °C |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | CH000210 | ControlHouse | OH-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | CH000210 | ControlHouse | OH-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | FE000670 | Fence | OH-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | FE000670 | Fence | OH-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | FE000670 | Fence | OH-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | FE000670 | Fence | OH-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | FE000670 | Fence | OH-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | FE000670 | Fence | OH-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | FE000670 | Fence | OH-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | FE000670 | Fence | OH-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | FE000670 | Fence | OH-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | FE000670 | Fence | OH-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | FE000670 | Fence | OH-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | FE000670 | Fence | OH-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | FE000670 | Fence | OH-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | FE000670 | Fence | OH-Fence | Fence Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | FE000670 | Fence | OH-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | FE000670 | Fence | OH-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0591 | BreakerAirMagnetic | MD-14KV BUS TIE | AMCB Readings | Unknown Operations | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1316 | BreakerVacuum | OH-1173 | VCB Readings | 9 Month Operations | 6 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1316 | BreakerVacuum | OH-1173 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1316 | BreakerVacuum | OH-1173 | VCB Readings | Accumulated Fault Duty A Ph V | 21.52 | % |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1316 | BreakerVacuum | OH-1173 | VCB Readings | Accumulated Fault Duty B Ph V | 19.13 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LTCC000331 | LTCControl | S-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1303 | BreakerVacuum | MD-1456 | VCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1303 | BreakerVacuum | MD-1456 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1303 | BreakerVacuum | MD-1456 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1303 | BreakerVacuum | MD-1456 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1303 | BreakerVacuum | MD-1456 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1303 | BreakerVacuum | MD-1456 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1303 | BreakerVacuum | MD-1456 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1303 | BreakerVacuum | MD-1456 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1303 | BreakerVacuum | MD-1456 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1303 | BreakerVacuum | MD-1456 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1303 | BreakerVacuum | MD-1456 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1303 | BreakerVacuum | MD-1456 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1303 | BreakerVacuum | MD-1456 | VCB Readings | Amps C Ø | 120.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1303 | BreakerVacuum | MD-1456 | VCB Readings | Amps B Ø | 120.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1303 | BreakerVacuum | MD-1456 | VCB Readings | Amps A Ø | 120.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1303 | BreakerVacuum | MD-1456 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1303 | BreakerVacuum | MD-1456 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1303 | BreakerVacuum | MD-1456 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1303 | BreakerVacuum | MD-1456 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1303 | BreakerVacuum | MD-1456 | VCB Readings | 9 Month Operations | 1 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | CH000210 | ControlHouse | OH-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | CH000210 | ControlHouse | OH-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | CH000210 | ControlHouse | OH-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | CH000210 | ControlHouse | OH-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | CH000210 | ControlHouse | OH-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | CH000210 | ControlHouse | OH-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0792 | BreakerAirMagnetic | PV-1252 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0792 | BreakerAirMagnetic | PV-1252 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0792 | BreakerAirMagnetic | PV-1252 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0792 | BreakerAirMagnetic | PV-1252 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0792 | BreakerAirMagnetic | PV-1252 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0792 | BreakerAirMagnetic | PV-1252 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0792 | BreakerAirMagnetic | PV-1252 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0792 | BreakerAirMagnetic | PV-1252 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0792 | BreakerAirMagnetic | PV-1252 | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0792 | BreakerAirMagnetic | PV-1252 | AMCB Readings | General Comments | DNO | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0792 | BreakerAirMagnetic | PV-1252 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0792 | BreakerAirMagnetic | PV-1252 | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0792 | BreakerAirMagnetic | PV-1252 | AMCB Readings | Operations Counter AF | 747 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0792 | BreakerAirMagnetic | PV-1252 | AMCB Readings | Operations Counter AL | 747 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0792 | BreakerAirMagnetic | PV-1252 | AMCB Readings | Operations This Read AM | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0591 | BreakerAirMagnetic | MD-14KV BUS TIE | AMCB Readings | Amps C Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0591 | BreakerAirMagnetic | MD-14KV BUS TIE | AMCB Readings | Amps B Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0591 | BreakerAirMagnetic | MD-14KV BUS TIE | AMCB Readings | Amps A Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0591 | BreakerAirMagnetic | MD-14KV BUS TIE | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0591 | BreakerAirMagnetic | MD-14KV BUS TIE | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0591 | BreakerAirMagnetic | MD-14KV BUS TIE | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0591 | BreakerAirMagnetic | MD-14KV BUS TIE | AMCB Readings | 9 Months Operations | 48 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0591 | BreakerAirMagnetic | MD-14KV BUS TIE | AMCB Readings | 9 Month Ops New | 13 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | FE000198 | Fence | 496-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | FE000198 | Fence | 496-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | FE000198 | Fence | 496-Fence | Fence Patrol Inspection | General Comments | Needs Grounding upgrade | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | FE000198 | Fence | 496-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | FE000198 | Fence | 496-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | FE000198 | Fence | 496-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | FE000198 | Fence | 496-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | FE000198 | Fence | 496-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | FE000198 | Fence | 496-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | FE000198 | Fence | 496-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | FE000198 | Fence | 496-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0792 | BreakerAirMagnetic | PV-1252 | AMCB Readings | Switching Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0792 | BreakerAirMagnetic | PV-1252 | AMCB Readings | Unknown Operations | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1316 | BreakerVacuum | OH-1173 | VCB Readings | Accumulated Fault Duty C Ph V | 13.55 | % |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1316 | BreakerVacuum | OH-1173 | VCB Readings | Amps A Ø | 173.0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1316 | BreakerVacuum | OH-1173 | VCB Readings | Amps B Ø | 141.0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1316 | BreakerVacuum | OH-1173 | VCB Readings | Amps C Ø | 175.0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | FE000198 | Fence | 496-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | FE000198 | Fence | 496-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 29 | °C |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 17 | °C |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 41 | °C |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 32 | °C |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 41 | °C |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LT0310 | WithLTC | OH-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 32 | °C |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0792 | BreakerAirMagnetic | PV-1252 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0591 | BreakerAirMagnetic | MD-14KV BUS TIE | AMCB Readings | Switching Operations | 35 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0591 | BreakerAirMagnetic | MD-14KV BUS TIE | AMCB Readings | Operations This Read AM | 35 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0591 | BreakerAirMagnetic | MD-14KV BUS TIE | AMCB Readings | Operations Counter AL | 593 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0591 | BreakerAirMagnetic | MD-14KV BUS TIE | AMCB Readings | Operations Counter AF | 593 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0591 | BreakerAirMagnetic | MD-14KV BUS TIE | AMCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0591 | BreakerAirMagnetic | MD-14KV BUS TIE | AMCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0591 | BreakerAirMagnetic | MD-14KV BUS TIE | AMCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0591 | BreakerAirMagnetic | MD-14KV BUS TIE | AMCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0591 | BreakerAirMagnetic | MD-14KV BUS TIE | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0591 | BreakerAirMagnetic | MD-14KV BUS TIE | AMCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0591 | BreakerAirMagnetic | MD-14KV BUS TIE | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0591 | BreakerAirMagnetic | MD-14KV BUS TIE | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0591 | BreakerAirMagnetic | MD-14KV BUS TIE | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0591 | BreakerAirMagnetic | MD-14KV BUS TIE | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0591 | BreakerAirMagnetic | MD-14KV BUS TIE | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0591 | BreakerAirMagnetic | MD-14KV BUS TIE | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0591 | BreakerAirMagnetic | MD-14KV BUS TIE | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0792 | BreakerAirMagnetic | PV-1252 | AMCB Readings | 9 Months Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0792 | BreakerAirMagnetic | PV-1252 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0792 | BreakerAirMagnetic | PV-1252 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0792 | BreakerAirMagnetic | PV-1252 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0792 | BreakerAirMagnetic | PV-1252 | AMCB Readings | Amps A Ø | 0.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0792 | BreakerAirMagnetic | PV-1252 | AMCB Readings | Amps B Ø | 0.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0792 | BreakerAirMagnetic | PV-1252 | AMCB Readings | Amps C Ø | 0.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0792 | BreakerAirMagnetic | PV-1252 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0792 | BreakerAirMagnetic | PV-1252 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0794 | BreakerAirMagnetic | PV-1254 | AMCB Readings | 9 Months Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0794 | BreakerAirMagnetic | PV-1254 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | FE000242 | Fence | 476-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | FE000242 | Fence | 476-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | FE000242 | Fence | 476-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | FE000242 | Fence | 476-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | FE000242 | Fence | 476-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | FE000242 | Fence | 476-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | FE000242 | Fence | 476-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | FE000242 | Fence | 476-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | FE000242 | Fence | 476-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | FE000242 | Fence | 476-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | FE000242 | Fence | 476-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | FE000242 | Fence | 476-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | FE000242 | Fence | 476-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | FE000242 | Fence | 476-Fence | Fence Patrol Inspection | General Comments | ok | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | FE000242 | Fence | 476-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | FE000242 | Fence | 476-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | ST000247 | Structure | 476-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | ST000247 | Structure | 476-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | ST000247 | Structure | 476-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | ST000247 | Structure | 476-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | ST000247 | Structure | 476-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | ST000247 | Structure | 476-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | ST000247 | Structure | 476-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | ST000247 | Structure | 476-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | ST000247 | Structure | 476-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | ST000247 | Structure | 476-Structure | Structure Patrol Inspection | General Comments | Could use new spare fuse barrels because fiberglass is coming apart. Whole station needs wildlife protection and secondary cover for | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | ST000247 | Structure | 476-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | ST000247 | Structure | 476-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | ST000247 | Structure | 476-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | ST000247 | Structure | 476-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | ST000247 | Structure | 476-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | ST000247 | Structure | 476-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | ST000247 | Structure | 476-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | ST000247 | Structure | 476-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | ST000247 | Structure | 476-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | ST000247 | Structure | 476-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | ST000247 | Structure | 476-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | ST000247 | Structure | 476-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | ST000247 | Structure | 476-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | ST000247 | Structure | 476-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCM000079 | LTCMechanism | 221-4 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCM000079 | LTCMechanism | 221-4 | LTC Counter Readings | LTC As Left Counter | 15308 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCM000079 | LTCMechanism | 221-4 | LTC Counter Readings | LTC As Found Counter | 15308 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | ST000262 | Structure | 648-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | ST000262 | Structure | 648-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | ST000262 | Structure | 648-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | ST000262 | Structure | 648-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | ST000262 | Structure | 648-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | ST000262 | Structure | 648-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCM000079 | LTCMechanism | 221-4 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCM000079 | LTCMechanism | 221-4 | LTC Counter Readings | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCM000079 | LTCMechanism | 221-4 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCM000079 | LTCMechanism | 221-4 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | PF001333 | PowerFuse | PV-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | PF001333 | PowerFuse | PV-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | ST000262 | Structure | 648-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Readings | Operations Counter AL | 169 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Readings | Operations Counter AF | 69 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Readings | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0794 | BreakerAirMagnetic | PV-1254 | AMCB Readings | Amps A Ø | 75.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0794 | BreakerAirMagnetic | PV-1254 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0794 | BreakerAirMagnetic | PV-1254 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0794 | BreakerAirMagnetic | PV-1254 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1190 | Regulator | 508-1 A | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1190 | Regulator | 508-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1190 | Regulator | 508-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1190 | Regulator | 508-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1190 | Regulator | 508-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1190 | Regulator | 508-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0585 | BreakerAirMagnetic | MD-1449-B | AMCB Readings | 9 Month Ops New | 14 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0585 | BreakerAirMagnetic | MD-1449-B | AMCB Readings | 9 Months Operations | 14 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0585 | BreakerAirMagnetic | MD-1449-B | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0585 | BreakerAirMagnetic | MD-1449-B | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0585 | BreakerAirMagnetic | MD-1449-B | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0585 | BreakerAirMagnetic | MD-1449-B | AMCB Readings | Amps A Ø | 100.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0585 | BreakerAirMagnetic | MD-1449-B | AMCB Readings | Amps B Ø | 100.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0585 | BreakerAirMagnetic | MD-1449-B | AMCB Readings | Amps C Ø | 100.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0585 | BreakerAirMagnetic | MD-1449-B | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0585 | BreakerAirMagnetic | MD-1449-B | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0585 | BreakerAirMagnetic | MD-1449-B | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0585 | BreakerAirMagnetic | MD-1449-B | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0585 | BreakerAirMagnetic | MD-1449-B | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0585 | BreakerAirMagnetic | MD-1449-B | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0585 | BreakerAirMagnetic | MD-1449-B | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0585 | BreakerAirMagnetic | MD-1449-B | AMCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0585 | BreakerAirMagnetic | MD-1449-B | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0585 | BreakerAirMagnetic | MD-1449-B | AMCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0585 | BreakerAirMagnetic | MD-1449-B | AMCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0585 | BreakerAirMagnetic | MD-1449-B | AMCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0585 | BreakerAirMagnetic | MD-1449-B | AMCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0585 | BreakerAirMagnetic | MD-1449-B | AMCB Readings | Operations Counter AF | 617 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0585 | BreakerAirMagnetic | MD-1449-B | AMCB Readings | Operations Counter AL | 617 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0585 | BreakerAirMagnetic | MD-1449-B | AMCB Readings | Operations This Read AM | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0585 | BreakerAirMagnetic | MD-1449-B | AMCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0585 | BreakerAirMagnetic | MD-1449-B | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LTCC000330 | LTCControl | S-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LTCC000330 | LTCControl | S-TRANS 2 | LTC Control Insp | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LTCC000330 | LTCControl | S-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1303 | BreakerVacuum | MD-1456 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1303 | BreakerVacuum | MD-1456 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1303 | BreakerVacuum | MD-1456 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1303 | BreakerVacuum | MD-1456 | VCB Readings | Operations Counter AL | 143 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1303 | BreakerVacuum | MD-1456 | VCB Readings | Operations Counter AF | 143 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1303 | BreakerVacuum | MD-1456 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LTCC000331 | LTCControl | S-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LTCC000331 | LTCControl | S-TRANS 1 | LTC Control Insp | General Comments | | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | BAT001400 | Battery | 496-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | BAT001400 | Battery | 496-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 54 | °F |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | BAT001400 | Battery | 496-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | BAT001400 | Battery | 496-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | BAT001400 | Battery | 496-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | BAT001400 | Battery | 496-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | BAT001400 | Battery | 496-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | BAT001400 | Battery | 496-Battery Bank | Battery Patrol Inspection | General Comments | ok | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | BAT001400 | Battery | 496-Battery Bank | Battery Patrol Inspection | Negative DC Ground | .1 | VDC |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | BAT001400 | Battery | 496-Battery Bank | Battery Patrol Inspection | Positive DC Ground | .5 | VDC |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | BAT001400 | Battery | 496-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | BAT001400 | Battery | 496-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Readings | Amps C Ø | 200.0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Readings | Amps B Ø | 200.0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Readings | Amps A Ø | 200.0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0407 | BreakerVacuum | 220-122 | VCB Readings | 9 Month Operations | 1 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1190 | Regulator | 508-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1190 | Regulator | 508-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1190 | Regulator | 508-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1190 | Regulator | 508-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 118506 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1190 | Regulator | 508-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1190 | Regulator | 508-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1190 | Regulator | 508-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1190 | Regulator | 508-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1190 | Regulator | 508-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1190 | Regulator | 508-1 A | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1190 | Regulator | 508-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1190 | Regulator | 508-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1190 | Regulator | 508-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1190 | Regulator | 508-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1190 | Regulator | 508-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1190 | Regulator | 508-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1190 | Regulator | 508-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001275 | PowerFuse | MD-1447 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001275 | PowerFuse | MD-1447 POT | Disconnect Powerfuse Inspection | General Comments | IOK | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001276 | PowerFuse | MD-1448 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001276 | PowerFuse | MD-1448 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001276 | PowerFuse | MD-1448 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001277 | PowerFuse | MD-1449 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001277 | PowerFuse | MD-1449 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Readings | Maintenance Operations | 1 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Readings | Operations Counter AF | 200 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Readings | Operations Counter AL | 200 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Readings | Operations This Read Vac | 4 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Readings | 9 Month Operations | 1 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Readings | Amps A Ø | 76.0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Readings | Amps B Ø | 57.0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Readings | Amps C Ø | 89.0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001277 | PowerFuse | MD-1449 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001278 | PowerFuse | MD-1450 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001278 | PowerFuse | MD-1450 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001278 | PowerFuse | MD-1450 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001279 | PowerFuse | MD-1451 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001279 | PowerFuse | MD-1451 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001279 | PowerFuse | MD-1451 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0343 | RecloserHydraulic | 865-1732 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0343 | RecloserHydraulic | 865-1732 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0343 | RecloserHydraulic | 865-1732 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0343 | RecloserHydraulic | 865-1732 | Recloser Hydraulic Patrol Inspection | General Comments | ok | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0343 | RecloserHydraulic | 865-1732 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0343 | RecloserHydraulic | 865-1732 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Readings | Fault Adjusted Amps A Phase V | 1.57 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Readings | Fault Adjusted Amps B Phase V | 1.57 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Readings | Fault Adjusted Amps C Phase V | 1.57 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Readings | Fault Operations A Ø | 1 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Readings | Fault Operations B Ø | 1 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Readings | Fault Operations C Ø | 1 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Readings | General Comments | | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001271 | PowerFuse | MD-14KV BUS SEC A POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001271 | PowerFuse | MD-14KV BUS SEC A POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001271 | PowerFuse | MD-14KV BUS SEC A POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001272 | PowerFuse | MD-14KV BUS SEC B POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001272 | PowerFuse | MD-14KV BUS SEC B POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001272 | PowerFuse | MD-14KV BUS SEC B POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001273 | PowerFuse | MD-1445 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001273 | PowerFuse | MD-1445 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001273 | PowerFuse | MD-1445 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0303 | GroundTransformer | MD-GND TR 3 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0303 | GroundTransformer | MD-GND TR 3 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0303 | GroundTransformer | MD-GND TR 3 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0303 | GroundTransformer | MD-GND TR 3 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0303 | GroundTransformer | MD-GND TR 3 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0303 | GroundTransformer | MD-GND TR 3 | Ground Transformer Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0303 | GroundTransformer | MD-GND TR 3 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0303 | GroundTransformer | MD-GND TR 3 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0303 | GroundTransformer | MD-GND TR 3 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0303 | GroundTransformer | MD-GND TR 3 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0303 | GroundTransformer | MD-GND TR 3 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0303 | GroundTransformer | MD-GND TR 3 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0303 | GroundTransformer | MD-GND TR 3 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0303 | GroundTransformer | MD-GND TR 3 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001274 | PowerFuse | MD-1446 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001274 | PowerFuse | MD-1446 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001274 | PowerFuse | MD-1446 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001275 | PowerFuse | MD-1447 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0580 | BreakerAirMagnetic | MD-1447-A | AMCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0580 | BreakerAirMagnetic | MD-1447-A | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0580 | BreakerAirMagnetic | MD-1447-A | AMCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0580 | BreakerAirMagnetic | MD-1447-A | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0580 | BreakerAirMagnetic | MD-1447-A | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0580 | BreakerAirMagnetic | MD-1447-A | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0580 | BreakerAirMagnetic | MD-1447-A | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0580 | BreakerAirMagnetic | MD-1447-A | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Readings | General Comments | | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Readings | Maintenance Operations | 1 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Readings | Operations Counter AF | 173 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Readings | Operations Counter AL | 173 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Readings | Operations This Read Vac | 1 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Readings | 9 Month Operations | 1 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Readings | Amps A Ø | 45.0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Readings | Amps B Ø | 32.0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Readings | Amps C Ø | 75.0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000538 | BreakerVacuum | 508-1725 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Readings | Winding Temp Present | 29 | °C |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Readings | Winding Temp Max | 38 | °C |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Readings | Totalizer Meter Reading | .7916 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Readings | Totalizer Meter Multiplier | 15240 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001280 | PowerFuse | MD-1452 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001280 | PowerFuse | MD-1452 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF001280 | PowerFuse | MD-1452 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0343 | RecloserHydraulic | 865-1732 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 112 | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0343 | RecloserHydraulic | 865-1732 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0343 | RecloserHydraulic | 865-1732 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0343 | RecloserHydraulic | 865-1732 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 141 | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0343 | RecloserHydraulic | 865-1732 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 8.8 | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0343 | RecloserHydraulic | 865-1732 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 7.9 | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0343 | RecloserHydraulic | 865-1732 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 9.3 | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | WX0343 | RecloserHydraulic | 865-1732 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 118 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0580 | BreakerAirMagnetic | MD-1447-A | AMCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0580 | BreakerAirMagnetic | MD-1447-A | AMCB Readings | Switching Operations | 7 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0580 | BreakerAirMagnetic | MD-1447-A | AMCB Readings | Operations This Read AM | 7 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Readings | Oil Temp Present | 28 | °C |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Readings | Oil Temp Max | 37 | °C |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1000 | psi |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Readings | LTC Totalizer Reading | 12063.98 | kw |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Readings | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | TX000193 | WithLTC | 221-4 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0580 | BreakerAirMagnetic | MD-1447-A | AMCB Readings | Operations Counter AL | 503 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0580 | BreakerAirMagnetic | MD-1447-A | AMCB Readings | Operations Counter AF | 503 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0580 | BreakerAirMagnetic | MD-1447-A | AMCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0580 | BreakerAirMagnetic | MD-1447-A | AMCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0580 | BreakerAirMagnetic | MD-1447-A | AMCB Patrol Inspection | General Comments | | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Readings | Totalizer Meter Reading | .4836 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | ST000204 | Structure | 496-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | ST000204 | Structure | 496-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | ST000204 | Structure | 496-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | ST000204 | Structure | 496-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | ST000204 | Structure | 496-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | ST000204 | Structure | 496-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | ST000204 | Structure | 496-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | ST000204 | Structure | 496-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | ST000204 | Structure | 496-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | ST000204 | Structure | 496-Structure | Structure Patrol Inspection | General Comments | ok | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | ST000204 | Structure | 496-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | ST000204 | Structure | 496-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | ST000204 | Structure | 496-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | ST000204 | Structure | 496-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | ST000204 | Structure | 496-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | ST000204 | Structure | 496-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | ST000204 | Structure | 496-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | ST000204 | Structure | 496-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | ST000204 | Structure | 496-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | ST000204 | Structure | 496-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | ST000204 | Structure | 496-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | ST000204 | Structure | 496-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Readings | Percent Thermal Load Y2 Max | 50 | % |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Readings | Percent Thermal Load X2 Max | 60 | % |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 850 | psi |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BCH001275 | Charger | 648-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BCH001275 | Charger | 648-Battery Charger | Battery Charger Patrol Insp | General Comments | ok | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BCH001275 | Charger | 648-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BCH001275 | Charger | 648-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1314 | BreakerVacuum | OH-1171 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1314 | BreakerVacuum | OH-1171 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1314 | BreakerVacuum | OH-1171 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1314 | BreakerVacuum | OH-1171 | VCB Readings | Operations Counter AL | 196 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1314 | BreakerVacuum | OH-1171 | VCB Readings | Operations Counter AF | 196 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1314 | BreakerVacuum | OH-1171 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1314 | BreakerVacuum | OH-1171 | VCB Readings | General Comments | | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1314 | BreakerVacuum | OH-1171 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1314 | BreakerVacuum | OH-1171 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1314 | BreakerVacuum | OH-1171 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1314 | BreakerVacuum | OH-1171 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1314 | BreakerVacuum | OH-1171 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1314 | BreakerVacuum | OH-1171 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1314 | BreakerVacuum | OH-1171 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1314 | BreakerVacuum | OH-1171 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1314 | BreakerVacuum | OH-1171 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1314 | BreakerVacuum | OH-1171 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1314 | BreakerVacuum | OH-1171 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1314 | BreakerVacuum | OH-1171 | VCB Readings | Amps C Ø | 199.0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1314 | BreakerVacuum | OH-1171 | VCB Readings | Amps B Ø | 204.0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1314 | BreakerVacuum | OH-1171 | VCB Readings | Amps A Ø | 193.0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1314 | BreakerVacuum | OH-1171 | VCB Readings | Accumulated Fault Duty C Ph V | 4.78 | % |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1314 | BreakerVacuum | OH-1171 | VCB Readings | Accumulated Fault Duty B Ph V | 7.97 | % |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1314 | BreakerVacuum | OH-1171 | VCB Readings | Accumulated Fault Duty A Ph V | 5.58 | % |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1314 | BreakerVacuum | OH-1171 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1314 | BreakerVacuum | OH-1171 | VCB Readings | 9 Month Operations | 6 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Patrol Inspection | General Comments | ok | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Readings | General Comments | ok | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Readings | LTC Totalizer Reading | 2321.28 | kw |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.5 | psi |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Readings | Amps A Ø | 175.0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Readings | Amps B Ø | 190.0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Readings | Amps C Ø | 185.0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Readings | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Readings | Operations Counter AF | 126 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Readings | Operations Counter AL | 126 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Readings | 9 Month Operations | 7 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Readings | Amps A Ø | 83.0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Readings | Amps B Ø | 94.0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Readings | Amps C Ø | 89.0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000537 | BreakerVacuum | 508-1728 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BCH001275 | Charger | 648-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .8 | amps |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BCH001275 | Charger | 648-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.1 | VDC |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BCH001275 | Charger | 648-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.1 | VDC |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BCH001275 | Charger | 648-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.700 | millivolts |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Readings | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Readings | LTC Totalizer Reading | 10370.82 | kw |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Readings | Totalizer Meter Multiplier | 15240 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Readings | Totalizer Meter Reading | .6805 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | WithLTC | 220-3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | PF001291 | PowerFuse | AS-14KV BUS SEC 3 POT | Disconnect Powerfuse Inspection | General Comments | ok | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | PF001291 | PowerFuse | AS-14KV BUS SEC 3 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | PF001291 | PowerFuse | AS-14KV BUS SEC 3 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Readings | 9 Month Operations | 16 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | K0022 | BreakerVacuum | 221-112 | VCB Readings | 9 Month Operations VCB New | 16 | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1242 | Regulator | 865-1 C | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1242 | Regulator | 865-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1242 | Regulator | 865-1 C | Regulator Patrol Inspection | General Comments | ok | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1242 | Regulator | 865-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1242 | Regulator | 865-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1242 | Regulator | 865-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1242 | Regulator | 865-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1242 | Regulator | 865-1 C | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1242 | Regulator | 865-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1242 | Regulator | 865-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1242 | Regulator | 865-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1242 | Regulator | 865-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1242 | Regulator | 865-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1241 | Regulator | 865-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1241 | Regulator | 865-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1241 | Regulator | 865-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1241 | Regulator | 865-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1241 | Regulator | 865-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 40588 | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1241 | Regulator | 865-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1241 | Regulator | 865-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1241 | Regulator | 865-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1241 | Regulator | 865-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1241 | Regulator | 865-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1241 | Regulator | 865-1 B | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Readings | Amps A Ø | 515.0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Readings | Amps B Ø | 540.0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Readings | Amps C Ø | 515.0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1242 | Regulator | 865-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1242 | Regulator | 865-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1242 | Regulator | 865-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1242 | Regulator | 865-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1242 | Regulator | 865-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 148939 | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1242 | Regulator | 865-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.7 | volts |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1242 | Regulator | 865-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1242 | Regulator | 865-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1242 | Regulator | 865-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1242 | Regulator | 865-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1242 | Regulator | 865-1 C | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1241 | Regulator | 865-1 B | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1241 | Regulator | 865-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1241 | Regulator | 865-1 B | Regulator Patrol Inspection | General Comments | ok | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1241 | Regulator | 865-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1241 | Regulator | 865-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1241 | Regulator | 865-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1241 | Regulator | 865-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1241 | Regulator | 865-1 B | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1241 | Regulator | 865-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1241 | Regulator | 865-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1241 | Regulator | 865-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1241 | Regulator | 865-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1241 | Regulator | 865-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 25 | °C |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 35 | °C |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 35 | °C |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 45 | °C |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 35 | °C |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 55 | °C |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 20.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Readings | 9 Months Operations | 1 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Readings | Accumulated Fault Duty A Ph AM | 5.63 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Readings | Accumulated Fault Duty B Ph AM | 5.63 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Readings | Accumulated Fault Duty C Ph AM | 5.63 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Readings | Amps A Ø | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Readings | Amps A Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Readings | Amps B Ø | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Readings | Amps B Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Readings | Amps C Ø | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Readings | Amps C Ø Max | 0.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Readings | Switching Operations | 1 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Readings | Operations This Read AM | 1 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Readings | Operations Counter AL | 803 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Readings | Operations Counter AF | 803 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Readings | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Readings | Amps C Ø | 185.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Readings | Amps B Ø | 190.0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Readings | Amps A Ø | 180.0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Readings | 9 Month Operations | 3 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | WithLTC | PV-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0916 | BreakerAirMagnetic | S-1308 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Readings | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Readings | Operations Counter AF | 173 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Readings | Operations Counter AL | 173 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Readings | Switching Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | PF001282 | PowerFuse | S-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | PF001282 | PowerFuse | S-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Readings | Amps C Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Readings | Amps C Ø | 50.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Readings | Amps B Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Readings | Amps B Ø | 30.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Readings | Amps A Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Readings | Amps A Ø | 60.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Readings | Accumulated Fault Duty C Ph AM | 3.38 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Readings | Accumulated Fault Duty B Ph AM | 3.38 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Readings | Accumulated Fault Duty A Ph AM | 3.38 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Readings | 9 Months Operations | 1 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0580 | BreakerAirMagnetic | MD-1447-A | AMCB Readings | Amps B Ø | 0.0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0580 | BreakerAirMagnetic | MD-1447-A | AMCB Readings | Amps A Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0580 | BreakerAirMagnetic | MD-1447-A | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0580 | BreakerAirMagnetic | MD-1447-A | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0580 | BreakerAirMagnetic | MD-1447-A | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0580 | BreakerAirMagnetic | MD-1447-A | AMCB Readings | 9 Months Operations | 10 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0580 | BreakerAirMagnetic | MD-1447-A | AMCB Readings | 9 Month Ops New | 3 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | LTCC000757 | LTCControl | 648-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | LTCC000757 | LTCControl | 648-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | LTCC000757 | LTCControl | 648-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | LTCC000757 | LTCControl | 648-1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | LTCC000757 | LTCControl | 648-1 | LTC Control Insp | LTC Output Voltage Level | 124.5 | VAC |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | LTCC000757 | LTCControl | 648-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | LTCC000757 | LTCControl | 648-1 | LTC Control Insp | General Comments | ok | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | LTCC000757 | LTCControl | 648-1 | LTC Control Insp | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | LTCC000757 | LTCControl | 648-1 | LTC Control Insp | All Connections OK? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | YD000151 | Yard | 508-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | YD000151 | Yard | 508-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | YD000151 | Yard | 508-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | YD000151 | Yard | 508-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | YD000151 | Yard | 508-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | YD000151 | Yard | 508-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | YD000151 | Yard | 508-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | YD000151 | Yard | 508-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | YD000151 | Yard | 508-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Readings | General Comments | | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Readings | Switching Operations | 1 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Readings | Operations This Read AM | 1 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | PF001281 | PowerFuse | S-4KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Readings | Maintenance Operations | 1 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0580 | BreakerAirMagnetic | MD-1447-A | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Readings | Operations Counter AF | 184 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Readings | Operations Counter AL | 184 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Readings | Operations This Read Vac | 1 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BK000539 | BreakerVacuum | 508-1726 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0580 | BreakerAirMagnetic | MD-1447-A | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | PF001281 | PowerFuse | S-4KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | PF001281 | PowerFuse | S-4KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Readings | Operations Counter AL | 1134 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Readings | Operations Counter AF | 1134 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0580 | BreakerAirMagnetic | MD-1447-A | AMCB Readings | Amps C Ø | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Readings | General Comments | ok | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0918 | BreakerAirMagnetic | S-1378 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | PF001282 | PowerFuse | S-4KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Readings | LTC Totalizer Reading | 12665.96 | kw |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Readings | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | SWG000190 | Switchgear | OH-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | SWG000190 | Switchgear | OH-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Readings | Operations Counter AL | 148 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Readings | Operations Counter AF | 148 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | SWG000190 | Switchgear | OH-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | SWG000190 | Switchgear | OH-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | SWG000190 | Switchgear | OH-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | SWG000190 | Switchgear | OH-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | SWG000190 | Switchgear | OH-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | SWG000190 | Switchgear | OH-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | SWG000190 | Switchgear | OH-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | SWG000190 | Switchgear | OH-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | SWG000190 | Switchgear | OH-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | SWG000190 | Switchgear | OH-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | SWG000190 | Switchgear | OH-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | SWG000190 | Switchgear | OH-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | SWG000190 | Switchgear | OH-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | SWG000190 | Switchgear | OH-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | SWG000190 | Switchgear | OH-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | SWG000190 | Switchgear | OH-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | SWG000190 | Switchgear | OH-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Readings | 9 Month Operations | 5 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000791 | BreakerVacuum | 221-132 | VCB Readings | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BK000790 | BreakerVacuum | 221-128 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | YD000151 | Yard | 508-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | YD000151 | Yard | 508-Yard | Yard Patrol Inspection | General Comments | SPR disabled | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | YD000151 | Yard | 508-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | YD000151 | Yard | 508-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | n | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | YD000151 | Yard | 508-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | YD000151 | Yard | 508-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Readings | 9 Months Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Readings | Accumulated Fault Duty A Ph AM | 8.15 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Readings | Accumulated Fault Duty B Ph AM | 8.15 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Readings | Accumulated Fault Duty C Ph AM | 8.15 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Readings | Amps A Ø | 69.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Readings | Amps A Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Readings | Amps B Ø | 63.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Readings | Amps B Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Readings | Amps C Ø | 55.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Readings | Amps C Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Readings | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Readings | Operations Counter AF | 11589 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Readings | Operations Counter AL | 11589 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Readings | Operations This Read AM | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Readings | Switching Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0926 | BreakerAirMagnetic | S-451 | AMCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 100.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Readings | Winding Temp Present | 45 | °C |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Readings | Winding Temp Max | 50 | °C |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Readings | Totalizer Meter Reading | .8311 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 15240 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0452 | WithLTC | 221-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Readings | Totalizer Meter Multiplier | 15240 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Readings | Totalizer Meter Reading | .3499 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Readings | Winding Temp Max | 30 | °C |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0579 | BreakerAirMagnetic | MD-1446-B | AMCB Readings | 9 Month Ops New | 12 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0579 | BreakerAirMagnetic | MD-1446-B | AMCB Readings | 9 Months Operations | 12 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0579 | BreakerAirMagnetic | MD-1446-B | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0579 | BreakerAirMagnetic | MD-1446-B | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0579 | BreakerAirMagnetic | MD-1446-B | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0579 | BreakerAirMagnetic | MD-1446-B | AMCB Readings | Amps A Ø | 130.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0579 | BreakerAirMagnetic | MD-1446-B | AMCB Readings | Amps B Ø | 130.0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Readings | Totalizer Meter Reading | .3978 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0579 | BreakerAirMagnetic | MD-1446-B | AMCB Readings | Amps C Ø | 130.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0579 | BreakerAirMagnetic | MD-1446-B | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0579 | BreakerAirMagnetic | MD-1446-B | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0579 | BreakerAirMagnetic | MD-1446-B | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0579 | BreakerAirMagnetic | MD-1446-B | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0579 | BreakerAirMagnetic | MD-1446-B | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0579 | BreakerAirMagnetic | MD-1446-B | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0579 | BreakerAirMagnetic | MD-1446-B | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0579 | BreakerAirMagnetic | MD-1446-B | AMCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0579 | BreakerAirMagnetic | MD-1446-B | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0579 | BreakerAirMagnetic | MD-1446-B | AMCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0579 | BreakerAirMagnetic | MD-1446-B | AMCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0579 | BreakerAirMagnetic | MD-1446-B | AMCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0579 | BreakerAirMagnetic | MD-1446-B | AMCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Readings | LTC Totalizer Reading | 5422.39 | kw |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Readings | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0299 | GroundTransformer | MD-GND TR 1 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0299 | GroundTransformer | MD-GND TR 1 | Ground Transformer Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0299 | GroundTransformer | MD-GND TR 1 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0299 | GroundTransformer | MD-GND TR 1 | Ground Transformer Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0299 | GroundTransformer | MD-GND TR 1 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0299 | GroundTransformer | MD-GND TR 1 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0299 | GroundTransformer | MD-GND TR 1 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0299 | GroundTransformer | MD-GND TR 1 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0299 | GroundTransformer | MD-GND TR 1 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Readings | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Readings | LTC Totalizer Reading | 5332.48 | kw |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1304 | BreakerVacuum | MD-1459 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1304 | BreakerVacuum | MD-1459 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1304 | BreakerVacuum | MD-1459 | VCB Readings | 9 Month Operations | 2 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0589 | BreakerAirMagnetic | MD-14KV BUS TIE SEC A | AMCB Readings | 9 Month Ops New | 22 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0589 | BreakerAirMagnetic | MD-14KV BUS TIE SEC A | AMCB Readings | 9 Months Operations | 22 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0589 | BreakerAirMagnetic | MD-14KV BUS TIE SEC A | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0589 | BreakerAirMagnetic | MD-14KV BUS TIE SEC A | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | LTCMechanism | 220-3 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Readings | LTC Totalizer Reading | 10110.22 | kw |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Readings | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0589 | BreakerAirMagnetic | MD-14KV BUS TIE SEC A | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0589 | BreakerAirMagnetic | MD-14KV BUS TIE SEC A | AMCB Readings | Amps A Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0589 | BreakerAirMagnetic | MD-14KV BUS TIE SEC A | AMCB Readings | Amps B Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0589 | BreakerAirMagnetic | MD-14KV BUS TIE SEC A | AMCB Readings | Amps C Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0589 | BreakerAirMagnetic | MD-14KV BUS TIE SEC A | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0589 | BreakerAirMagnetic | MD-14KV BUS TIE SEC A | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0589 | BreakerAirMagnetic | MD-14KV BUS TIE SEC A | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0589 | BreakerAirMagnetic | MD-14KV BUS TIE SEC A | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0589 | BreakerAirMagnetic | MD-14KV BUS TIE SEC A | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0589 | BreakerAirMagnetic | MD-14KV BUS TIE SEC A | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0589 | BreakerAirMagnetic | MD-14KV BUS TIE SEC A | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0589 | BreakerAirMagnetic | MD-14KV BUS TIE SEC A | AMCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0589 | BreakerAirMagnetic | MD-14KV BUS TIE SEC A | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0589 | BreakerAirMagnetic | MD-14KV BUS TIE SEC A | AMCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0579 | BreakerAirMagnetic | MD-1446-B | AMCB Readings | Operations Counter AF | 518 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0579 | BreakerAirMagnetic | MD-1446-B | AMCB Readings | Operations Counter AL | 518 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0579 | BreakerAirMagnetic | MD-1446-B | AMCB Readings | Operations This Read AM | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0579 | BreakerAirMagnetic | MD-1446-B | AMCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0579 | BreakerAirMagnetic | MD-1446-B | AMCB Readings | Unknown Operations | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | LTCMechanism | 220-3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | LTCMechanism | 220-3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | LTCMechanism | 220-3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Readings | Winding Temp Present | 50 | °C |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Readings | Winding Temp Max | 55 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Readings | Totalizer Meter Reading | .6634 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 15240 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | LTCMechanism | 220-3 | LTC Counter Readings | LTC Operations Since Last Insp | 650 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | LTCMechanism | 220-3 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.5 | psi |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | LTCMechanism | 220-3 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | LTCMechanism | 220-3 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1304 | BreakerVacuum | MD-1459 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1304 | BreakerVacuum | MD-1459 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1304 | BreakerVacuum | MD-1459 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1304 | BreakerVacuum | MD-1459 | VCB Readings | Operations Counter AL | 182 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1304 | BreakerVacuum | MD-1459 | VCB Readings | Operations Counter AF | 182 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1304 | BreakerVacuum | MD-1459 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1304 | BreakerVacuum | MD-1459 | VCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1304 | BreakerVacuum | MD-1459 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1304 | BreakerVacuum | MD-1459 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1304 | BreakerVacuum | MD-1459 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1304 | BreakerVacuum | MD-1459 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1304 | BreakerVacuum | MD-1459 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1304 | BreakerVacuum | MD-1459 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1304 | BreakerVacuum | MD-1459 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1304 | BreakerVacuum | MD-1459 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1304 | BreakerVacuum | MD-1459 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1304 | BreakerVacuum | MD-1459 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1304 | BreakerVacuum | MD-1459 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1304 | BreakerVacuum | MD-1459 | VCB Readings | Amps C Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1304 | BreakerVacuum | MD-1459 | VCB Readings | Amps B Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1304 | BreakerVacuum | MD-1459 | VCB Readings | Amps A Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1304 | BreakerVacuum | MD-1459 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1304 | BreakerVacuum | MD-1459 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0791 | BreakerAirMagnetic | PV-1251 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0791 | BreakerAirMagnetic | PV-1251 | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0791 | BreakerAirMagnetic | PV-1251 | AMCB Readings | General Comments | ABC Phase IOC | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0791 | BreakerAirMagnetic | PV-1251 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0791 | BreakerAirMagnetic | PV-1251 | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0791 | BreakerAirMagnetic | PV-1251 | AMCB Readings | Operations Counter AF | 222 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0791 | BreakerAirMagnetic | PV-1251 | AMCB Readings | Operations Counter AL | 222 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0791 | BreakerAirMagnetic | PV-1251 | AMCB Readings | Operations This Read AM | 3 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0791 | BreakerAirMagnetic | PV-1251 | AMCB Readings | Switching Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0791 | BreakerAirMagnetic | PV-1251 | AMCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | WithLTC | 221-3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1240 | Regulator | 865-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1240 | Regulator | 865-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1240 | Regulator | 865-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1240 | Regulator | 865-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1240 | Regulator | 865-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 60053 | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1240 | Regulator | 865-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1240 | Regulator | 865-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1240 | Regulator | 865-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1240 | Regulator | 865-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1240 | Regulator | 865-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1240 | Regulator | 865-1 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1240 | Regulator | 865-1 A | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1240 | Regulator | 865-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1240 | Regulator | 865-1 A | Regulator Patrol Inspection | General Comments | ok | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1240 | Regulator | 865-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1240 | Regulator | 865-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1240 | Regulator | 865-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1240 | Regulator | 865-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1240 | Regulator | 865-1 A | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1240 | Regulator | 865-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1240 | Regulator | 865-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Readings | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Readings | Operations Counter AF | 270 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Readings | Operations Counter AL | 270 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0370 | BreakerVacuum | 220-118 | VCB Readings | Unknown Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0791 | BreakerAirMagnetic | PV-1251 | AMCB Readings | 9 Month Ops New | 2 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0791 | BreakerAirMagnetic | PV-1251 | AMCB Readings | 9 Months Operations | 5 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0791 | BreakerAirMagnetic | PV-1251 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0791 | BreakerAirMagnetic | PV-1251 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0791 | BreakerAirMagnetic | PV-1251 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0791 | BreakerAirMagnetic | PV-1251 | AMCB Readings | Amps A Ø | 50.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0791 | BreakerAirMagnetic | PV-1251 | AMCB Readings | Amps B Ø | 50.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0791 | BreakerAirMagnetic | PV-1251 | AMCB Readings | Amps C Ø | 50.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0791 | BreakerAirMagnetic | PV-1251 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0791 | BreakerAirMagnetic | PV-1251 | AMCB Readings | Fault Adjusted Amps A Phase AM | 11.18 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0791 | BreakerAirMagnetic | PV-1251 | AMCB Readings | Fault Adjusted Amps B Phase AM | 11.18 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0791 | BreakerAirMagnetic | PV-1251 | AMCB Readings | Fault Adjusted Amps C Phase AM | 11.18 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0791 | BreakerAirMagnetic | PV-1251 | AMCB Readings | Fault Operations A Ø | 1 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0791 | BreakerAirMagnetic | PV-1251 | AMCB Readings | Fault Operations B Ø | 1 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0791 | BreakerAirMagnetic | PV-1251 | AMCB Readings | Fault Operations C Ø | 1 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0791 | BreakerAirMagnetic | PV-1251 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0791 | BreakerAirMagnetic | PV-1251 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0581 | BreakerAirMagnetic | MD-1447-B | AMCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0581 | BreakerAirMagnetic | MD-1447-B | AMCB Readings | Operations Counter AF | 605 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0581 | BreakerAirMagnetic | MD-1447-B | AMCB Readings | Operations Counter AL | 605 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0581 | BreakerAirMagnetic | MD-1447-B | AMCB Readings | Operations This Read AM | 1 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0581 | BreakerAirMagnetic | MD-1447-B | AMCB Readings | Switching Operations | 1 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0581 | BreakerAirMagnetic | MD-1447-B | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | LTCMechanism | PV-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 157449 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | LTCMechanism | PV-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 157449 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | LTCMechanism | PV-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | LTCMechanism | PV-TRANS 1 | LTC Counter Readings | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | LTCMechanism | PV-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | LTCMechanism | PV-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 10.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Readings | Totalizer Meter Reading | .3558 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 15240 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | WithLTC | 221-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Patrol Inspection | General Comments | ok | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Readings | General Comments | ok | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Readings | LTC Totalizer Reading | 3818.88 | kw |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Readings | Oil Temp Max | 43 | °C |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Readings | Oil Temp Present | 37 | °C |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | W0321 | WithLTC | 648-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1240 | Regulator | 865-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1240 | Regulator | 865-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | R1240 | Regulator | 865-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0581 | BreakerAirMagnetic | MD-1447-B | AMCB Readings | 9 Month Ops New | 19 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0581 | BreakerAirMagnetic | MD-1447-B | AMCB Readings | 9 Months Operations | 20 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0581 | BreakerAirMagnetic | MD-1447-B | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0581 | BreakerAirMagnetic | MD-1447-B | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | 9 Month Operations | 17 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Amps A Ø | 313.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Amps B Ø | 302.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Amps C Ø | 300.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Operations Counter AF | 172 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Operations Counter AL | 172 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Switching Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | LTCMechanism | PV-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | LTCMechanism | PV-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | LTCMechanism | PV-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | LTCMechanism | PV-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | LTCMechanism | PV-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 433 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | LTCMechanism | PV-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | LTCMechanism | PV-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | LTCMechanism | PV-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | LTCMechanism | PV-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LT0161 | LTCMechanism | PV-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0581 | BreakerAirMagnetic | MD-1447-B | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0581 | BreakerAirMagnetic | MD-1447-B | AMCB Readings | Amps A Ø | 113.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0581 | BreakerAirMagnetic | MD-1447-B | AMCB Readings | Amps B Ø | 113.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0581 | BreakerAirMagnetic | MD-1447-B | AMCB Readings | Amps C Ø | 113.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0581 | BreakerAirMagnetic | MD-1447-B | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0581 | BreakerAirMagnetic | MD-1447-B | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0581 | BreakerAirMagnetic | MD-1447-B | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0581 | BreakerAirMagnetic | MD-1447-B | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0581 | BreakerAirMagnetic | MD-1447-B | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0581 | BreakerAirMagnetic | MD-1447-B | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0581 | BreakerAirMagnetic | MD-1447-B | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0581 | BreakerAirMagnetic | MD-1447-B | AMCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0581 | BreakerAirMagnetic | MD-1447-B | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0581 | BreakerAirMagnetic | MD-1447-B | AMCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0581 | BreakerAirMagnetic | MD-1447-B | AMCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0581 | BreakerAirMagnetic | MD-1447-B | AMCB Readings | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Readings | Amps C Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Readings | Amps C Ø | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Readings | Amps B Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Readings | Amps B Ø | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Readings | Amps A Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Readings | Amps A Ø | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Readings | Accumulated Fault Duty C Ph AM | 4.44 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Readings | Accumulated Fault Duty B Ph AM | 4.44 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Readings | Accumulated Fault Duty A Ph AM | 4.44 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Readings | 9 Months Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Readings | 9 Month Ops New | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Readings | 9 Months Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0578 | BreakerAirMagnetic | MD-1446-A | AMCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0578 | BreakerAirMagnetic | MD-1446-A | AMCB Readings | Switching Operations | 1 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0578 | BreakerAirMagnetic | MD-1446-A | AMCB Readings | Operations This Read AM | 1 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0578 | BreakerAirMagnetic | MD-1446-A | AMCB Readings | Operations Counter AL | 504 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0578 | BreakerAirMagnetic | MD-1446-A | AMCB Readings | Operations Counter AF | 504 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0578 | BreakerAirMagnetic | MD-1446-A | AMCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0578 | BreakerAirMagnetic | MD-1446-A | AMCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0578 | BreakerAirMagnetic | MD-1446-A | AMCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0578 | BreakerAirMagnetic | MD-1446-A | AMCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0578 | BreakerAirMagnetic | MD-1446-A | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0578 | BreakerAirMagnetic | MD-1446-A | AMCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0578 | BreakerAirMagnetic | MD-1446-A | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0578 | BreakerAirMagnetic | MD-1446-A | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0578 | BreakerAirMagnetic | MD-1446-A | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0578 | BreakerAirMagnetic | MD-1446-A | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0578 | BreakerAirMagnetic | MD-1446-A | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0578 | BreakerAirMagnetic | MD-1446-A | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0578 | BreakerAirMagnetic | MD-1446-A | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0578 | BreakerAirMagnetic | MD-1446-A | AMCB Readings | Amps C Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0578 | BreakerAirMagnetic | MD-1446-A | AMCB Readings | Amps B Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0578 | BreakerAirMagnetic | MD-1446-A | AMCB Readings | Amps A Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0578 | BreakerAirMagnetic | MD-1446-A | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0578 | BreakerAirMagnetic | MD-1446-A | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0578 | BreakerAirMagnetic | MD-1446-A | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0790 | BreakerAirMagnetic | PV-1250 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0790 | BreakerAirMagnetic | PV-1250 | AMCB Readings | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Readings | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Readings | Operations Counter AF | 1044 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Readings | Operations Counter AL | 1044 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Readings | Operations This Read AM | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Readings | Switching Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Readings | Unknown Operations | 0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BAT001361 | Battery | 648-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BAT001361 | Battery | 648-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BAT001361 | Battery | 648-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BAT001361 | Battery | 648-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 54 | °F |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0790 | BreakerAirMagnetic | PV-1250 | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0790 | BreakerAirMagnetic | PV-1250 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0790 | BreakerAirMagnetic | PV-1250 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0790 | BreakerAirMagnetic | PV-1250 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0790 | BreakerAirMagnetic | PV-1250 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0790 | BreakerAirMagnetic | PV-1250 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0790 | BreakerAirMagnetic | PV-1250 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0790 | BreakerAirMagnetic | PV-1250 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0790 | BreakerAirMagnetic | PV-1250 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0790 | BreakerAirMagnetic | PV-1250 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0790 | BreakerAirMagnetic | PV-1250 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0790 | BreakerAirMagnetic | PV-1250 | AMCB Readings | Amps C Ø | 125.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0790 | BreakerAirMagnetic | PV-1250 | AMCB Readings | Amps B Ø | 125.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0790 | BreakerAirMagnetic | PV-1250 | AMCB Readings | Amps A Ø | 125.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0790 | BreakerAirMagnetic | PV-1250 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0790 | BreakerAirMagnetic | PV-1250 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0790 | BreakerAirMagnetic | PV-1250 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0790 | BreakerAirMagnetic | PV-1250 | AMCB Readings | 9 Months Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0790 | BreakerAirMagnetic | PV-1250 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BAT001361 | Battery | 648-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Readings | Switching Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Readings | Operations This Read AM | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Readings | Operations Counter AL | 398 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Readings | Operations Counter AF | 398 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Readings | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0933 | BreakerAirMagnetic | S-4KV TR 1 TFR | AMCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Readings | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Patrol Inspection | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Readings | Operations Counter AF | 2559 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Readings | Operations Counter AL | 2559 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Readings | Operations This Read AM | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Readings | Switching Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Readings | Unknown Operations | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | Y2 Winding Temp Present | 40 | °C |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Readings | Amps C Ø | 100.0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Readings | Amps B Ø | 100.0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Readings | Amps A Ø | 100.0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Readings | 9 Month Operations | 1 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | Y2 Winding Temp Max | 40 | °C |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Present | 45 | °C |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Max | 50 | °C |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | H2 Winding Temp Present | 40 | °C |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | H2 Winding Temp Max | 45 | °C |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | WithLTC | 496-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0578 | BreakerAirMagnetic | MD-1446-A | AMCB Readings | 9 Months Operations | 13 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0578 | BreakerAirMagnetic | MD-1446-A | AMCB Readings | 9 Month Ops New | 12 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Readings | Accumulated Fault Duty A Ph AM | 2.04 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Readings | Accumulated Fault Duty B Ph AM | 2.04 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Readings | Accumulated Fault Duty C Ph AM | 2.04 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Readings | Amps A Ø | .6 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Readings | Amps A Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Readings | Amps B Ø | .7 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Readings | Amps B Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Readings | Amps C Ø | .7 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Readings | Amps C Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | LTCMechanism | 220-Offline-Distribution | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | LTCMechanism | 220-Offline-Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | LTCMechanism | 220-Offline-Distribution | LTC Counter Readings | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | LTCMechanism | 220-Offline-Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | LTCMechanism | 220-Offline-Distribution | LTC Counter Readings | LTC As Found Counter | 13386 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | LTCMechanism | 220-Offline-Distribution | LTC Counter Readings | LTC As Left Counter | 13386 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | LTCMechanism | 220-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | LTCMechanism | 220-Offline-Distribution | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | LTCMechanism | 220-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | LTCMechanism | 220-Offline-Distribution | LTC Counter Readings | LTC Operations Since Last Insp | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | LTCMechanism | 220-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | LTCMechanism | 220-Offline-Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Readings | Switching Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Readings | General Comments | ok | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0921 | BreakerAirMagnetic | S-406 | AMCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Readings | Operations Counter AL | 67 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Readings | Operations Counter AF | 67 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0371 | BreakerVacuum | 220-102 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Readings | Operations Counter AL | 275 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Readings | Operations This Read AM | 2 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Readings | Switching Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000038 | Switchgear | MD-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000038 | Switchgear | MD-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000038 | Switchgear | MD-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000038 | Switchgear | MD-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000038 | Switchgear | MD-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000038 | Switchgear | MD-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000038 | Switchgear | MD-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000038 | Switchgear | MD-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000038 | Switchgear | MD-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000038 | Switchgear | MD-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000038 | Switchgear | MD-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000038 | Switchgear | MD-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000038 | Switchgear | MD-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000038 | Switchgear | MD-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000038 | Switchgear | MD-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000038 | Switchgear | MD-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000038 | Switchgear | MD-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000038 | Switchgear | MD-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000038 | Switchgear | MD-Swgr Sec 1 & 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Readings | General Comments | ok | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Patrol Inspection | General Comments | Secondary of xfmr needs wildlife protection. | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.5 | psi |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1357.92 | kw |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0589 | BreakerAirMagnetic | MD-14KV BUS TIE SEC A | AMCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0589 | BreakerAirMagnetic | MD-14KV BUS TIE SEC A | AMCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0589 | BreakerAirMagnetic | MD-14KV BUS TIE SEC A | AMCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0589 | BreakerAirMagnetic | MD-14KV BUS TIE SEC A | AMCB Readings | Operations Counter AF | 570 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0589 | BreakerAirMagnetic | MD-14KV BUS TIE SEC A | AMCB Readings | Operations Counter AL | 570 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0589 | BreakerAirMagnetic | MD-14KV BUS TIE SEC A | AMCB Readings | Operations This Read AM | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0589 | BreakerAirMagnetic | MD-14KV BUS TIE SEC A | AMCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0589 | BreakerAirMagnetic | MD-14KV BUS TIE SEC A | AMCB Readings | Unknown Operations | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0436 | WithLTC | 220-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | LTCMechanism | 220-3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | LTCMechanism | 220-3 | LTC Counter Readings | LTC As Left Counter | 168334 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | LTCMechanism | 220-3 | LTC Counter Readings | LTC As Found Counter | 168334 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | LTCMechanism | 220-3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | LTCMechanism | 220-3 | LTC Counter Readings | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | LTCMechanism | 220-3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0449 | LTCMechanism | 220-3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Readings | 9 Months Operations | 2 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Readings | Accumulated Fault Duty A Ph AM | 5.5 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Readings | Accumulated Fault Duty B Ph AM | 5.5 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Readings | Accumulated Fault Duty C Ph AM | 5.5 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Readings | Amps A Ø | 35.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Readings | Amps A Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Readings | Amps B Ø | 24.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Readings | Amps B Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Readings | Amps C Ø | 31.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Readings | Amps C Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Readings | Fault Adjusted Amps A Phase AM | 9.55 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Readings | Fault Adjusted Amps C Phase AM | 9.55 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Readings | Fault Operations A Ø | 1 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .6048 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Readings | Fault Operations C Ø | 1 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Readings | General Comments | A and C phase TOC | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0922 | BreakerAirMagnetic | S-409 | AMCB Readings | Operations Counter AF | 275 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0793 | BreakerAirMagnetic | PV-1253 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0793 | BreakerAirMagnetic | PV-1253 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0793 | BreakerAirMagnetic | PV-1253 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0793 | BreakerAirMagnetic | PV-1253 | AMCB Readings | Amps C Ø | 100.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0793 | BreakerAirMagnetic | PV-1253 | AMCB Readings | Amps B Ø | 100.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LTCC000588 | LTCControl | MD-TRANS 3 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LTCC000588 | LTCControl | MD-TRANS 3 | LTC Control Insp | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LTCC000588 | LTCControl | MD-TRANS 3 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0793 | BreakerAirMagnetic | PV-1253 | AMCB Readings | Amps A Ø | 100.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0793 | BreakerAirMagnetic | PV-1253 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0793 | BreakerAirMagnetic | PV-1253 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0793 | BreakerAirMagnetic | PV-1253 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0793 | BreakerAirMagnetic | PV-1253 | AMCB Readings | 9 Months Operations | 2 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0793 | BreakerAirMagnetic | PV-1253 | AMCB Readings | 9 Month Ops New | 2 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BAT001361 | Battery | 648-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BAT001361 | Battery | 648-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BAT001361 | Battery | 648-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.9 | VDC |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BAT001361 | Battery | 648-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 28.0 | VDC |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BAT001361 | Battery | 648-Battery Bank | Battery Patrol Inspection | General Comments | ok | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BAT001361 | Battery | 648-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BAT001361 | Battery | 648-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Readings | 9 Month Ops New | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Readings | 9 Months Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Readings | Accumulated Fault Duty A Ph AM | 1.12 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Readings | Accumulated Fault Duty B Ph AM | 1.12 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Readings | Accumulated Fault Duty C Ph AM | 1.12 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Readings | Amps A Ø | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Readings | Amps A Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Readings | Amps B Ø | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Readings | Amps B Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Readings | Amps C Ø | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Readings | Amps C Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0935 | BreakerAirMagnetic | S-4KV TR 2 TFR | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0790 | BreakerAirMagnetic | PV-1250 | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0790 | BreakerAirMagnetic | PV-1250 | AMCB Readings | Switching Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0790 | BreakerAirMagnetic | PV-1250 | AMCB Readings | Operations This Read AM | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0790 | BreakerAirMagnetic | PV-1250 | AMCB Readings | Operations Counter AL | 256 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0790 | BreakerAirMagnetic | PV-1250 | AMCB Readings | Operations Counter AF | 256 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0790 | BreakerAirMagnetic | PV-1250 | AMCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Readings | Oil Temp Present | 37 | °C |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Readings | Oil Temp Present | 45 | °C |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1451.52 | kw |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Readings | General Comments | | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0793 | BreakerAirMagnetic | PV-1253 | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0793 | BreakerAirMagnetic | PV-1253 | AMCB Readings | Switching Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0793 | BreakerAirMagnetic | PV-1253 | AMCB Readings | Operations This Read AM | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0793 | BreakerAirMagnetic | PV-1253 | AMCB Readings | Operations Counter AL | 130 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0793 | BreakerAirMagnetic | PV-1253 | AMCB Readings | Operations Counter AF | 130 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | W0276 | NonLTC | 508-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0793 | BreakerAirMagnetic | PV-1253 | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0793 | BreakerAirMagnetic | PV-1253 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | W0359 | NonLTC | 865-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .5658 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0793 | BreakerAirMagnetic | PV-1253 | AMCB Readings | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0793 | BreakerAirMagnetic | PV-1253 | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0793 | BreakerAirMagnetic | PV-1253 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0793 | BreakerAirMagnetic | PV-1253 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0793 | BreakerAirMagnetic | PV-1253 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0793 | BreakerAirMagnetic | PV-1253 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0793 | BreakerAirMagnetic | PV-1253 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0793 | BreakerAirMagnetic | PV-1253 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0793 | BreakerAirMagnetic | PV-1253 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Readings | Amps C Ø | 100.0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Readings | Amps B Ø | 100.0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Readings | Amps A Ø | 100.0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Readings | 9 Month Operations | 1 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Readings | Operations This Read Vac | 1 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Readings | Operations Counter AL | 234 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Readings | Operations Counter AF | 234 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Patrol Inspection | General Comments | ok | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Readings | General Comments | 1 BG op | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Readings | Fault Operations B Ø | 1 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Readings | Fault Adjusted Amps B Phase V | 4.44 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Readings | Amps C Ø | 22.0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Readings | Amps B Ø | 23.0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Readings | Amps A Ø | 23.0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Patrol Inspection | General Comments | H2 bushing has broken skirt. Needs wildlife protection. | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Readings | General Comments | ok | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 2100 | psi |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 52.50 | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Readings | Top Oil Temperature Max | 30 | °C |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Readings | Top Oil Temperature Present | 18 | °C |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Counter Readings | LTC Operations Since Last Insp | 3 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Counter Readings | LTC Min Tap Position | 19 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Counter Readings | LTC Max Tap Position | 20 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Counter Readings | LTC Current Tap Position | 19 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Counter Readings | LTC As Left Counter | 17198 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Counter Readings | LTC As Found Counter | 17198 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1306 | BreakerVacuum | MD-1458 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1306 | BreakerVacuum | MD-1458 | VCB Readings | Amps C Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1306 | BreakerVacuum | MD-1458 | VCB Readings | Amps B Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1306 | BreakerVacuum | MD-1458 | VCB Readings | Amps A Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1306 | BreakerVacuum | MD-1458 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1306 | BreakerVacuum | MD-1458 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1306 | BreakerVacuum | MD-1458 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1306 | BreakerVacuum | MD-1458 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1306 | BreakerVacuum | MD-1458 | VCB Readings | 9 Month Operations | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Readings | Operations Counter AL | 60 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Readings | Operations Counter AF | 60 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Readings | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0408 | BreakerVacuum | 220-112 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Amps C Ø | 0.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Amps B Ø | 0.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Amps A Ø | 0.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | 9 Month Operations | 21 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | FE000646 | Fence | S-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | FE000646 | Fence | S-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | FE000646 | Fence | S-Fence | Fence Patrol Inspection | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | FE000646 | Fence | S-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | FE000646 | Fence | S-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | FE000646 | Fence | S-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | FE000646 | Fence | S-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | FE000646 | Fence | S-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | FE000646 | Fence | S-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | FE000646 | Fence | S-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | FE000646 | Fence | S-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | FE000646 | Fence | S-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | FE000646 | Fence | S-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | FE000646 | Fence | S-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | FE000646 | Fence | S-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | FE000646 | Fence | S-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Readings | Operations Counter AL | 99934 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Readings | Operations Counter AF | 99934 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Readings | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Readings | Amps C Ø | 200.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Unknown Operations | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Switching Operations | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Operations Counter AL | 354 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Operations Counter AF | 354 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000611 | BreakerVacuum | 648-1761 | VCB Readings | 9 Month Operations | 1 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0593 | BreakerAirMagnetic | MD-14KV TR 2 | AMCB Readings | 9 Month Ops New | 4 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0593 | BreakerAirMagnetic | MD-14KV TR 2 | AMCB Readings | 9 Months Operations | 5 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0593 | BreakerAirMagnetic | MD-14KV TR 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0593 | BreakerAirMagnetic | MD-14KV TR 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0593 | BreakerAirMagnetic | MD-14KV TR 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0593 | BreakerAirMagnetic | MD-14KV TR 2 | AMCB Readings | Amps A Ø | 700.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0593 | BreakerAirMagnetic | MD-14KV TR 2 | AMCB Readings | Amps B Ø | 700.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0593 | BreakerAirMagnetic | MD-14KV TR 2 | AMCB Readings | Amps C Ø | 700.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0593 | BreakerAirMagnetic | MD-14KV TR 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0593 | BreakerAirMagnetic | MD-14KV TR 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0593 | BreakerAirMagnetic | MD-14KV TR 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0593 | BreakerAirMagnetic | MD-14KV TR 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0593 | BreakerAirMagnetic | MD-14KV TR 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0593 | BreakerAirMagnetic | MD-14KV TR 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0593 | BreakerAirMagnetic | MD-14KV TR 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0593 | BreakerAirMagnetic | MD-14KV TR 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0593 | BreakerAirMagnetic | MD-14KV TR 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0593 | BreakerAirMagnetic | MD-14KV TR 2 | AMCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0593 | BreakerAirMagnetic | MD-14KV TR 2 | AMCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0593 | BreakerAirMagnetic | MD-14KV TR 2 | AMCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0593 | BreakerAirMagnetic | MD-14KV TR 2 | AMCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0593 | BreakerAirMagnetic | MD-14KV TR 2 | AMCB Readings | Operations Counter AF | 538 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0593 | BreakerAirMagnetic | MD-14KV TR 2 | AMCB Readings | Operations Counter AL | 538 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0593 | BreakerAirMagnetic | MD-14KV TR 2 | AMCB Readings | Operations This Read AM | 1 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0593 | BreakerAirMagnetic | MD-14KV TR 2 | AMCB Readings | Switching Operations | 1 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0593 | BreakerAirMagnetic | MD-14KV TR 2 | AMCB Readings | Unknown Operations | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | YD000677 | Yard | OH-Yard | Yard Patrol Inspection | Ambient Temp | 36 | °F |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | YD000677 | Yard | OH-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | YD000677 | Yard | OH-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | YD000677 | Yard | OH-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | YD000677 | Yard | OH-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | YD000677 | Yard | OH-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | YD000677 | Yard | OH-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | YD000677 | Yard | OH-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | YD000677 | Yard | OH-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | YD000677 | Yard | OH-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | YD000677 | Yard | OH-Yard | Yard Patrol Inspection | General Comments | | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | YD000677 | Yard | OH-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | YD000677 | Yard | OH-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | YD000677 | Yard | OH-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | YD000677 | Yard | OH-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | YD000677 | Yard | OH-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | YD000677 | Yard | OH-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Unknown Operations | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Switching Operations | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Operations Counter AL | 385 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Operations Counter AF | 385 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF000204 | PowerFuse | MD-14KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF000204 | PowerFuse | MD-14KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF000205 | PowerFuse | MD-14KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF000205 | PowerFuse | MD-14KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1100.0 | psi |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1 | psi |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Readings | Oil Temp Max | 39 | °C |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Readings | Oil Temp Present | 23 | °C |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Max | 40 | °C |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Present | 24 | °C |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Max | 40 | °C |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF000205 | PowerFuse | MD-14KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | PF000342 | PowerFuse | S-4KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | PF000342 | PowerFuse | S-4KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | PF000342 | PowerFuse | S-4KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Present | 24 | °C |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Max | 40 | °C |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | WithLTC | MD-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Present | 24 | °C |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | YD000409 | Yard | 220-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | YD000409 | Yard | 220-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | YD000409 | Yard | 220-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | YD000409 | Yard | 220-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | YD000409 | Yard | 220-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | YD000409 | Yard | 220-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | YD000409 | Yard | 220-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | YD000409 | Yard | 220-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | YD000409 | Yard | 220-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Readings | Operations Counter AL | 849 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Readings | Operations This Read AM | 1 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Readings | Switching Operations | 1 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Readings | Unknown Operations | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | PF000264 | PowerFuse | OH-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | PF000264 | PowerFuse | OH-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | PF000265 | PowerFuse | OH-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | PF000265 | PowerFuse | OH-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | 9 Month Operations | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Amps A Ø | 245.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Amps B Ø | 234.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Amps C Ø | 238.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Patrol Inspection | General Comments | ok | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Operations Counter AF | 255 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Operations Counter AL | 255 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Switching Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | PF000335 | PowerFuse | S-14KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | PF000335 | PowerFuse | S-14KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | PF000335 | PowerFuse | S-14KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | PF000336 | PowerFuse | S-14KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | PF000336 | PowerFuse | S-14KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | PF000336 | PowerFuse | S-14KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | SWG000115 | Switchgear | PV-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | SWG000115 | Switchgear | PV-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | SWG000115 | Switchgear | PV-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | SWG000115 | Switchgear | PV-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | SWG000115 | Switchgear | PV-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | SWG000115 | Switchgear | PV-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | SWG000115 | Switchgear | PV-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | SWG000115 | Switchgear | PV-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | SWG000115 | Switchgear | PV-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | SWG000115 | Switchgear | PV-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | SWG000115 | Switchgear | PV-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | SWG000115 | Switchgear | PV-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | SWG000115 | Switchgear | PV-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | SWG000115 | Switchgear | PV-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | SWG000115 | Switchgear | PV-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | SWG000115 | Switchgear | PV-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | SWG000115 | Switchgear | PV-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | SWG000115 | Switchgear | PV-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | PF000022 | PowerFuse | AS-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | PF000022 | PowerFuse | AS-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | PF000022 | PowerFuse | AS-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF000202 | PowerFuse | MD-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF000202 | PowerFuse | MD-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF000202 | PowerFuse | MD-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | PF000024 | PowerFuse | AS-GND TR 3 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | PF000024 | PowerFuse | AS-GND TR 3 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | PF000024 | PowerFuse | AS-GND TR 3 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF000204 | PowerFuse | MD-14KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | ST000411 | Structure | 220-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | ST000411 | Structure | 220-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | ST000411 | Structure | 220-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | ST000411 | Structure | 220-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1306 | BreakerVacuum | MD-1458 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1306 | BreakerVacuum | MD-1458 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1306 | BreakerVacuum | MD-1458 | VCB Readings | Operations This Read Vac | 0 | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1306 | BreakerVacuum | MD-1458 | VCB Readings | Operations Counter AL | 163 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1306 | BreakerVacuum | MD-1458 | VCB Readings | Operations Counter AF | 163 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1306 | BreakerVacuum | MD-1458 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1306 | BreakerVacuum | MD-1458 | VCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1306 | BreakerVacuum | MD-1458 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1306 | BreakerVacuum | MD-1458 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1306 | BreakerVacuum | MD-1458 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1306 | BreakerVacuum | MD-1458 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1306 | BreakerVacuum | MD-1458 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1306 | BreakerVacuum | MD-1458 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1306 | BreakerVacuum | MD-1458 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1306 | BreakerVacuum | MD-1458 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1306 | BreakerVacuum | MD-1458 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1306 | BreakerVacuum | MD-1458 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Patrol Inspection | General Comments | Needs wildlife protection. | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Readings | General Comments | ok | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1800 | psi |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 30.24 | kw |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Readings | Top Oil Temperature Max | 57 | °C |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Readings | Top Oil Temperature Present | 50 | °C |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 800 | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Readings | Totalizer Meter Reading | .0378 | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0161 | NonLTC | 476-1 C | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | YD000409 | Yard | 220-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | YD000409 | Yard | 220-Yard | Yard Patrol Inspection | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | YD000409 | Yard | 220-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | YD000409 | Yard | 220-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | YD000409 | Yard | 220-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | YD000409 | Yard | 220-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | YD000409 | Yard | 220-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | ST000411 | Structure | 220-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | ST000411 | Structure | 220-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | ST000411 | Structure | 220-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | ST000411 | Structure | 220-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | ST000411 | Structure | 220-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | ST000411 | Structure | 220-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | ST000411 | Structure | 220-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | ST000411 | Structure | 220-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | ST000411 | Structure | 220-Structure | Structure Patrol Inspection | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | ST000411 | Structure | 220-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | ST000411 | Structure | 220-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | ST000411 | Structure | 220-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | ST000411 | Structure | 220-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | ST000411 | Structure | 220-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Patrol Inspection | General Comments | Needs wildlife protection. | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Readings | General Comments | ok | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 142.50 | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 135.00 | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Readings | Top Oil Temperature Max | 33 | °C |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0153 | NonLTC | 476-1 B | NonLTC Transformer Readings | Top Oil Temperature Present | 28 | °C |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | W0155 | NonLTC | 476-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | ST000411 | Structure | 220-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | ST000411 | Structure | 220-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | ST000411 | Structure | 220-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | ST000411 | Structure | 220-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Readings | Amps C Ø | 250.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Readings | Amps B Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Readings | Amps B Ø | 250.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Readings | Amps A Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Readings | Amps A Ø | 250.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 3.02 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 3.02 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 3.02 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Readings | 9 Months Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | LTCMechanism | 221-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | LTCMechanism | 221-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | LTCMechanism | 221-1 | LTC Counter Readings | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | LTCMechanism | 221-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | LTCMechanism | 221-1 | LTC Counter Readings | LTC As Found Counter | 135660 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | LTCMechanism | 221-1 | LTC Counter Readings | LTC As Left Counter | 135660 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | LTCMechanism | 221-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | LTCMechanism | 221-1 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | LTCMechanism | 221-1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | LTCMechanism | 221-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | LTCMechanism | 221-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | LTCMechanism | 221-1 | LTC Counter Readings | LTC Operations Since Last Insp | 328 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | LTCMechanism | 221-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | LTCMechanism | 221-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0455 | LTCMechanism | 221-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | LTCMechanism | 221-3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | LTCMechanism | 221-3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | LTCMechanism | 221-3 | LTC Counter Readings | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | LTCMechanism | 221-3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | LTCMechanism | 221-3 | LTC Counter Readings | LTC As Found Counter | 100414 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | LTCMechanism | 221-3 | LTC Counter Readings | LTC As Left Counter | 100414 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | LTCMechanism | 221-3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | LTCMechanism | 221-3 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | LTCMechanism | 221-3 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | LTCMechanism | 221-3 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | LTCMechanism | 221-3 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | LTCMechanism | 221-3 | LTC Counter Readings | LTC Operations Since Last Insp | 313 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | LTCMechanism | 221-3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | LTCMechanism | 221-3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | B0456 | LTCMechanism | 221-3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0594 | BreakerAirMagnetic | MD-14KV TEMP BUS TIE | AMCB Readings | 9 Month Ops New | 7 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0594 | BreakerAirMagnetic | MD-14KV TEMP BUS TIE | AMCB Readings | 9 Months Operations | 7 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0594 | BreakerAirMagnetic | MD-14KV TEMP BUS TIE | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0594 | BreakerAirMagnetic | MD-14KV TEMP BUS TIE | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0594 | BreakerAirMagnetic | MD-14KV TEMP BUS TIE | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0594 | BreakerAirMagnetic | MD-14KV TEMP BUS TIE | AMCB Readings | Amps A Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0594 | BreakerAirMagnetic | MD-14KV TEMP BUS TIE | AMCB Readings | Amps B Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0594 | BreakerAirMagnetic | MD-14KV TEMP BUS TIE | AMCB Readings | Amps C Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0594 | BreakerAirMagnetic | MD-14KV TEMP BUS TIE | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0594 | BreakerAirMagnetic | MD-14KV TEMP BUS TIE | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0594 | BreakerAirMagnetic | MD-14KV TEMP BUS TIE | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0594 | BreakerAirMagnetic | MD-14KV TEMP BUS TIE | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0594 | BreakerAirMagnetic | MD-14KV TEMP BUS TIE | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0594 | BreakerAirMagnetic | MD-14KV TEMP BUS TIE | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0594 | BreakerAirMagnetic | MD-14KV TEMP BUS TIE | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0594 | BreakerAirMagnetic | MD-14KV TEMP BUS TIE | AMCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1301 | BreakerVacuum | MD-14KV TR 3 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1301 | BreakerVacuum | MD-14KV TR 3 | VCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1301 | BreakerVacuum | MD-14KV TR 3 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1301 | BreakerVacuum | MD-14KV TR 3 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1301 | BreakerVacuum | MD-14KV TR 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1301 | BreakerVacuum | MD-14KV TR 3 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1301 | BreakerVacuum | MD-14KV TR 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1301 | BreakerVacuum | MD-14KV TR 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1301 | BreakerVacuum | MD-14KV TR 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1301 | BreakerVacuum | MD-14KV TR 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1301 | BreakerVacuum | MD-14KV TR 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1301 | BreakerVacuum | MD-14KV TR 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1301 | BreakerVacuum | MD-14KV TR 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1301 | BreakerVacuum | MD-14KV TR 3 | VCB Readings | Amps C Ø | 350.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1301 | BreakerVacuum | MD-14KV TR 3 | VCB Readings | Amps B Ø | 350.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1301 | BreakerVacuum | MD-14KV TR 3 | VCB Readings | Amps A Ø | 350.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1301 | BreakerVacuum | MD-14KV TR 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1301 | BreakerVacuum | MD-14KV TR 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Readings | Switching Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Readings | Operations This Read AM | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Readings | Operations Counter AL | 917 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Readings | Operations Counter AF | 917 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Readings | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1301 | BreakerVacuum | MD-14KV TR 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1301 | BreakerVacuum | MD-14KV TR 3 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1301 | BreakerVacuum | MD-14KV TR 3 | VCB Readings | 9 Month Operations | 1 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LTCC000488 | LTCControl | OH-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LTCC000488 | LTCControl | OH-TRANS 1 | LTC Control Insp | General Comments | | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LTCC000488 | LTCControl | OH-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Switching Operations | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Operations Counter AL | 382 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Operations Counter AF | 382 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Amps C Ø | 150.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Amps B Ø | 150.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Amps A Ø | 140.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | 9 Month Operations | 31 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0934 | BreakerAirMagnetic | S-4KV TR 2 | AMCB Readings | Amps C Ø Max | 0.0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Readings | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Readings | LTC Totalizer Reading | 10152.89 | kw |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 15240 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Readings | Totalizer Meter Reading | .6662 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1315 | BreakerVacuum | OH-1172 | VCB Readings | Accumulated Fault Duty C Ph V | 4.78 | % |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1315 | BreakerVacuum | OH-1172 | VCB Readings | Amps A Ø | 211.0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1315 | BreakerVacuum | OH-1172 | VCB Readings | Amps B Ø | 193.0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1315 | BreakerVacuum | OH-1172 | VCB Readings | Amps C Ø | 186.0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1315 | BreakerVacuum | OH-1172 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1315 | BreakerVacuum | OH-1172 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1315 | BreakerVacuum | OH-1172 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1315 | BreakerVacuum | OH-1172 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1315 | BreakerVacuum | OH-1172 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1315 | BreakerVacuum | OH-1172 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1315 | BreakerVacuum | OH-1172 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1315 | BreakerVacuum | OH-1172 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1315 | BreakerVacuum | OH-1172 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1315 | BreakerVacuum | OH-1172 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1315 | BreakerVacuum | OH-1172 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1315 | BreakerVacuum | OH-1172 | VCB Readings | General Comments | | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1315 | BreakerVacuum | OH-1172 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1315 | BreakerVacuum | OH-1172 | VCB Readings | Operations Counter AF | 167 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1315 | BreakerVacuum | OH-1172 | VCB Readings | Operations Counter AL | 167 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1315 | BreakerVacuum | OH-1172 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1315 | BreakerVacuum | OH-1172 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1315 | BreakerVacuum | OH-1172 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | ST000295 | Structure | 221-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | ST000295 | Structure | 221-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | ST000295 | Structure | 221-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | ST000295 | Structure | 221-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | ST000295 | Structure | 221-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | ST000295 | Structure | 221-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | ST000295 | Structure | 221-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | ST000295 | Structure | 221-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | ST000295 | Structure | 221-Structure | Structure Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0594 | BreakerAirMagnetic | MD-14KV TEMP BUS TIE | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0594 | BreakerAirMagnetic | MD-14KV TEMP BUS TIE | AMCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0594 | BreakerAirMagnetic | MD-14KV TEMP BUS TIE | AMCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0594 | BreakerAirMagnetic | MD-14KV TEMP BUS TIE | AMCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0594 | BreakerAirMagnetic | MD-14KV TEMP BUS TIE | AMCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0594 | BreakerAirMagnetic | MD-14KV TEMP BUS TIE | AMCB Readings | Operations Counter AF | 16 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0594 | BreakerAirMagnetic | MD-14KV TEMP BUS TIE | AMCB Readings | Operations Counter AL | 16 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0594 | BreakerAirMagnetic | MD-14KV TEMP BUS TIE | AMCB Readings | Operations This Read AM | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0594 | BreakerAirMagnetic | MD-14KV TEMP BUS TIE | AMCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0594 | BreakerAirMagnetic | MD-14KV TEMP BUS TIE | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Readings | 9 Months Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Readings | Amps A Ø | .6 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Readings | Amps A Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Readings | Amps B Ø | .6 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Readings | Amps B Ø Max | 0.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Readings | Amps C Ø | .5 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Readings | Amps C Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Patrol Inspection | General Comments | | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1315 | BreakerVacuum | OH-1172 | VCB Readings | 9 Month Operations | 12 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1315 | BreakerVacuum | OH-1172 | VCB Readings | 9 Month Operations VCB New | 12 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1315 | BreakerVacuum | OH-1172 | VCB Readings | Accumulated Fault Duty A Ph V | 3.19 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Readings | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1315 | BreakerVacuum | OH-1172 | VCB Readings | Accumulated Fault Duty B Ph V | 3.99 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Readings | Operations Counter AF | 312 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Readings | Operations Counter AL | 312 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Readings | Operations This Read AM | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Readings | Switching Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0928 | BreakerAirMagnetic | S-454 | AMCB Readings | Unknown Operations | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | WithLTC | 220-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0586 | BreakerAirMagnetic | MD-1449-A | AMCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1305 | BreakerVacuum | MD-1457 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1305 | BreakerVacuum | MD-1457 | VCB Readings | Switching Operations | 1 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1305 | BreakerVacuum | MD-1457 | VCB Readings | Operations This Read Vac | 1 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1305 | BreakerVacuum | MD-1457 | VCB Readings | Operations Counter AL | 223 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1305 | BreakerVacuum | MD-1457 | VCB Readings | Operations Counter AF | 223 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1305 | BreakerVacuum | MD-1457 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1305 | BreakerVacuum | MD-1457 | VCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1305 | BreakerVacuum | MD-1457 | VCB Patrol Inspection | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | YD000651 | Yard | S-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1305 | BreakerVacuum | MD-1457 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1305 | BreakerVacuum | MD-1457 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1305 | BreakerVacuum | MD-1457 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1305 | BreakerVacuum | MD-1457 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1305 | BreakerVacuum | MD-1457 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1305 | BreakerVacuum | MD-1457 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1305 | BreakerVacuum | MD-1457 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1305 | BreakerVacuum | MD-1457 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1305 | BreakerVacuum | MD-1457 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1305 | BreakerVacuum | MD-1457 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1305 | BreakerVacuum | MD-1457 | VCB Readings | Amps C Ø | 50.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | YD000651 | Yard | S-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | YD000651 | Yard | S-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | YD000651 | Yard | S-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | YD000651 | Yard | S-Yard | Yard Patrol Inspection | General Comments | Trash in alleyway | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | YD000651 | Yard | S-Yard | Yard Patrol Inspection | Follow-up Action Required? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1305 | BreakerVacuum | MD-1457 | VCB Readings | Amps B Ø | 50.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1305 | BreakerVacuum | MD-1457 | VCB Readings | Amps A Ø | 50.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1305 | BreakerVacuum | MD-1457 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1305 | BreakerVacuum | MD-1457 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1305 | BreakerVacuum | MD-1457 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1305 | BreakerVacuum | MD-1457 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1305 | BreakerVacuum | MD-1457 | VCB Readings | 9 Month Operations | 2 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | YD000651 | Yard | S-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | YD000651 | Yard | S-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | YD000651 | Yard | S-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | YD000651 | Yard | S-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | YD000651 | Yard | S-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | YD000651 | Yard | S-Yard | Yard Patrol Inspection | Clear of Trash? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | YD000651 | Yard | S-Yard | Yard Patrol Inspection | Clear of Obstacles? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | YD000651 | Yard | S-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0597 | BreakerAirMagnetic | MD-GND TR 2 | AMCB Readings | 9 Month Ops New | 4 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0597 | BreakerAirMagnetic | MD-GND TR 2 | AMCB Readings | 9 Months Operations | 4 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0597 | BreakerAirMagnetic | MD-GND TR 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0597 | BreakerAirMagnetic | MD-GND TR 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0597 | BreakerAirMagnetic | MD-GND TR 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0597 | BreakerAirMagnetic | MD-GND TR 2 | AMCB Readings | Amps A Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0597 | BreakerAirMagnetic | MD-GND TR 2 | AMCB Readings | Amps B Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0597 | BreakerAirMagnetic | MD-GND TR 2 | AMCB Readings | Amps C Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0597 | BreakerAirMagnetic | MD-GND TR 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0597 | BreakerAirMagnetic | MD-GND TR 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0597 | BreakerAirMagnetic | MD-GND TR 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0597 | BreakerAirMagnetic | MD-GND TR 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0597 | BreakerAirMagnetic | MD-GND TR 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0597 | BreakerAirMagnetic | MD-GND TR 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0597 | BreakerAirMagnetic | MD-GND TR 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Readings | Amps B Ø | 225.0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Readings | Amps A Ø | 210.0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | BB0422 | BreakerVacuum | 221-108 | VCB Readings | 9 Month Operations | 2 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Amps C Ø | 480.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Amps B Ø | 470.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Amps A Ø | 451.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | 9 Month Operations | 20 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | ST000630 | Structure | S-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | ST000630 | Structure | S-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | ST000630 | Structure | S-Structure | Structure Patrol Inspection | General Comments | graffiti all over side of building | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | ST000630 | Structure | S-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | ST000630 | Structure | S-Structure | Structure Patrol Inspection | Follow-up Action Required? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | ST000630 | Structure | S-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | BCH001073 | Charger | S-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | BCH001073 | Charger | S-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | BCH001073 | Charger | S-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | BCH001073 | Charger | S-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | BCH001073 | Charger | S-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .7 | amps |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | BCH001073 | Charger | S-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.7 | VDC |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | BCH001073 | Charger | S-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.7 | VDC |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | BCH001073 | Charger | S-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0586 | BreakerAirMagnetic | MD-1449-A | AMCB Readings | 9 Month Ops New | 3 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0586 | BreakerAirMagnetic | MD-1449-A | AMCB Readings | 9 Months Operations | 16 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0586 | BreakerAirMagnetic | MD-1449-A | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0586 | BreakerAirMagnetic | MD-1449-A | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0586 | BreakerAirMagnetic | MD-1449-A | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0586 | BreakerAirMagnetic | MD-1449-A | AMCB Readings | Amps A Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0586 | BreakerAirMagnetic | MD-1449-A | AMCB Readings | Amps B Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0586 | BreakerAirMagnetic | MD-1449-A | AMCB Readings | Amps C Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0586 | BreakerAirMagnetic | MD-1449-A | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0586 | BreakerAirMagnetic | MD-1449-A | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0586 | BreakerAirMagnetic | MD-1449-A | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0586 | BreakerAirMagnetic | MD-1449-A | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0586 | BreakerAirMagnetic | MD-1449-A | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0586 | BreakerAirMagnetic | MD-1449-A | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0586 | BreakerAirMagnetic | MD-1449-A | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0586 | BreakerAirMagnetic | MD-1449-A | AMCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0586 | BreakerAirMagnetic | MD-1449-A | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0586 | BreakerAirMagnetic | MD-1449-A | AMCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0586 | BreakerAirMagnetic | MD-1449-A | AMCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0586 | BreakerAirMagnetic | MD-1449-A | AMCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0586 | BreakerAirMagnetic | MD-1449-A | AMCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0586 | BreakerAirMagnetic | MD-1449-A | AMCB Readings | Operations Counter AF | 565 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0586 | BreakerAirMagnetic | MD-1449-A | AMCB Readings | Operations Counter AL | 565 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0586 | BreakerAirMagnetic | MD-1449-A | AMCB Readings | Operations This Read AM | 13 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0586 | BreakerAirMagnetic | MD-1449-A | AMCB Readings | Switching Operations | 13 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Readings | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Readings | Operations Counter AF | 257 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Readings | Operations Counter AL | 257 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Readings | Operations This Read AM | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Readings | Switching Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Readings | Switching Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Readings | Operations This Read AM | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Readings | Operations Counter AL | 499 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Readings | Operations Counter AF | 4991 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Readings | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Readings | Amps C Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Readings | Amps C Ø | 78.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Readings | Amps B Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Readings | Amps B Ø | 116.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Readings | Amps A Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Readings | Amps A Ø | 61.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Readings | Accumulated Fault Duty C Ph AM | 2.23 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Readings | Accumulated Fault Duty B Ph AM | 2.23 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Readings | Accumulated Fault Duty A Ph AM | 2.23 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Readings | 9 Months Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0931 | BreakerAirMagnetic | S-405 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | BAT000118 | Battery | S-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | BAT000118 | Battery | S-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | BAT000118 | Battery | S-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | BAT000118 | Battery | S-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | BAT000118 | Battery | S-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | BAT000118 | Battery | S-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | BAT000118 | Battery | S-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | BAT000118 | Battery | S-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | BAT000118 | Battery | S-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | BAT000118 | Battery | S-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | BAT000118 | Battery | S-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | BAT000118 | Battery | S-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1301 | BreakerVacuum | MD-14KV TR 3 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1301 | BreakerVacuum | MD-14KV TR 3 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1301 | BreakerVacuum | MD-14KV TR 3 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1301 | BreakerVacuum | MD-14KV TR 3 | VCB Readings | Operations Counter AL | 169 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1301 | BreakerVacuum | MD-14KV TR 3 | VCB Readings | Operations Counter AF | 169 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0597 | BreakerAirMagnetic | MD-GND TR 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0590 | BreakerVacuum | MD-1454 | VCB Readings | 9 Month Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0590 | BreakerVacuum | MD-1454 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0590 | BreakerVacuum | MD-1454 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0590 | BreakerVacuum | MD-1454 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0590 | BreakerVacuum | MD-1454 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0590 | BreakerVacuum | MD-1454 | VCB Readings | Amps A Ø | 117.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0590 | BreakerVacuum | MD-1454 | VCB Readings | Amps B Ø | 117.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0590 | BreakerVacuum | MD-1454 | VCB Readings | Amps C Ø | 117.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0590 | BreakerVacuum | MD-1454 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0590 | BreakerVacuum | MD-1454 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0590 | BreakerVacuum | MD-1454 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0590 | BreakerVacuum | MD-1454 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0590 | BreakerVacuum | MD-1454 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0590 | BreakerVacuum | MD-1454 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0590 | BreakerVacuum | MD-1454 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0597 | BreakerAirMagnetic | MD-GND TR 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0597 | BreakerAirMagnetic | MD-GND TR 2 | AMCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0590 | BreakerVacuum | MD-1454 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0590 | BreakerVacuum | MD-1454 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0590 | BreakerVacuum | MD-1454 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0590 | BreakerVacuum | MD-1454 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0590 | BreakerVacuum | MD-1454 | VCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0590 | BreakerVacuum | MD-1454 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0590 | BreakerVacuum | MD-1454 | VCB Readings | Operations Counter AF | 167 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0590 | BreakerVacuum | MD-1454 | VCB Readings | Operations Counter AL | 167 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0590 | BreakerVacuum | MD-1454 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0590 | BreakerVacuum | MD-1454 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0590 | BreakerVacuum | MD-1454 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0597 | BreakerAirMagnetic | MD-GND TR 2 | AMCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0597 | BreakerAirMagnetic | MD-GND TR 2 | AMCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0597 | BreakerAirMagnetic | MD-GND TR 2 | AMCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0597 | BreakerAirMagnetic | MD-GND TR 2 | AMCB Readings | Operations Counter AF | 372 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0597 | BreakerAirMagnetic | MD-GND TR 2 | AMCB Readings | Operations Counter AL | 372 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0597 | BreakerAirMagnetic | MD-GND TR 2 | AMCB Readings | Operations This Read AM | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0597 | BreakerAirMagnetic | MD-GND TR 2 | AMCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0597 | BreakerAirMagnetic | MD-GND TR 2 | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Readings | 9 Month Ops New | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Readings | 9 Months Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Readings | Amps A Ø | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Readings | Amps A Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Readings | Amps B Ø | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Readings | Amps B Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Readings | Amps C Ø | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Readings | Amps C Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0962 | BreakerAirMagnetic | S-STATION SERVICE | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0796 | BreakerAirMagnetic | PV-12KV TR 1 | AMCB Readings | Operations Counter AL | 15 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0796 | BreakerAirMagnetic | PV-12KV TR 1 | AMCB Readings | Operations This Read AM | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0796 | BreakerAirMagnetic | PV-12KV TR 1 | AMCB Readings | Switching Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0796 | BreakerAirMagnetic | PV-12KV TR 1 | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | CH000198 | ControlHouse | S-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | CH000198 | ControlHouse | S-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | CH000198 | ControlHouse | S-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | CH000198 | ControlHouse | S-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | CH000198 | ControlHouse | S-Control House | Control House Patrol Inspection | Restroom Clean & OK? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | CH000198 | ControlHouse | S-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | CH000198 | ControlHouse | S-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | CH000198 | ControlHouse | S-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | CH000198 | ControlHouse | S-Control House | Control House Patrol Inspection | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | CH000198 | ControlHouse | S-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | CH000198 | ControlHouse | S-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | CH000198 | ControlHouse | S-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | CH000198 | ControlHouse | S-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | CH000198 | ControlHouse | S-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | CH000198 | ControlHouse | S-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | CH000198 | ControlHouse | S-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | CH000198 | ControlHouse | S-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | CH000198 | ControlHouse | S-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | CH000198 | ControlHouse | S-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | CH000198 | ControlHouse | S-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | CH000198 | ControlHouse | S-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | CH000198 | ControlHouse | S-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Readings | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Readings | LTC Totalizer Reading | 0.00 | kw |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Readings | Oil Temp Max | 20 | °C |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Readings | Oil Temp Present | 10 | °C |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Readings | Totalizer Meter Multiplier | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Patrol Inspection | General Comments | ok | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Readings | General Comments | ok | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0576 | BreakerAirMagnetic | MD-1445-A | AMCB Readings | 9 Month Ops New | 15 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Readings | Operations Counter AF | 231 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Readings | Operations Counter AL | 231 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Readings | Operations This Read Vac | 1 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000861 | LTCControl | 221-2 | LTC Control Insp | All Connections OK? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000861 | LTCControl | 221-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000861 | LTCControl | 221-2 | LTC Control Insp | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000861 | LTCControl | 221-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000861 | LTCControl | 221-2 | LTC Control Insp | LTC Output Voltage Level | 121.0 | VAC |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000861 | LTCControl | 221-2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000861 | LTCControl | 221-2 | LTC Control Insp | VRR Base Voltage AF | 120.0 | VAC |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000861 | LTCControl | 221-2 | LTC Control Insp | VRR Base Voltage AL | 120.0 | VAC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000861 | LTCControl | 221-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0796 | BreakerAirMagnetic | PV-12KV TR 1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0796 | BreakerAirMagnetic | PV-12KV TR 1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0796 | BreakerAirMagnetic | PV-12KV TR 1 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0796 | BreakerAirMagnetic | PV-12KV TR 1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0796 | BreakerAirMagnetic | PV-12KV TR 1 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0796 | BreakerAirMagnetic | PV-12KV TR 1 | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0796 | BreakerAirMagnetic | PV-12KV TR 1 | AMCB Readings | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0796 | BreakerAirMagnetic | PV-12KV TR 1 | AMCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | LTCMechanism | 496-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | LTCMechanism | 496-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | LTCMechanism | 496-1 | LTC Counter Readings | General Comments | ok | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | LTCMechanism | 496-1 | LTC Mechanism Patrol Inspection | General Comments | ok | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | LTCMechanism | 496-1 | LTC Counter Readings | LTC As Found Counter | 10752 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000862 | LTCControl | 221-3 | LTC Control Insp | All Connections OK? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000862 | LTCControl | 221-3 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000862 | LTCControl | 221-3 | LTC Control Insp | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000862 | LTCControl | 221-3 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000862 | LTCControl | 221-3 | LTC Control Insp | LTC Output Voltage Level | 121.0 | VAC |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000862 | LTCControl | 221-3 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000862 | LTCControl | 221-3 | LTC Control Insp | VRR Base Voltage AF | 120.0 | VAC |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000862 | LTCControl | 221-3 | LTC Control Insp | VRR Base Voltage AL | 120.0 | VAC |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000862 | LTCControl | 221-3 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | LTCMechanism | 496-1 | LTC Counter Readings | LTC As Left Counter | 10760 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | LTCMechanism | 496-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | LTCMechanism | 496-1 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | LTCMechanism | 496-1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | LTCMechanism | 496-1 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | LTCMechanism | 496-1 | LTC Counter Readings | LTC Operations Since Last Insp | 255 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | LTCMechanism | 496-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | LTCMechanism | 496-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | C0510 | LTCMechanism | 496-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0796 | BreakerAirMagnetic | PV-12KV TR 1 | AMCB Readings | Operations Counter AF | 15 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Readings | Operations Counter AL | 533 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Readings | Operations Counter AF | 533 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Readings | Amps C Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Readings | Amps C Ø | 73.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Readings | Amps B Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Readings | Amps B Ø | 79.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Readings | Amps A Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Readings | Amps A Ø | 90.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Readings | Accumulated Fault Duty C Ph AM | 4.44 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Readings | Accumulated Fault Duty B Ph AM | 4.44 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Readings | Accumulated Fault Duty A Ph AM | 7.76 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Readings | 9 Months Operations | 4 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Readings | 9 Month Ops New | 4 | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | FE000209 | Fence | 865-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | FE000209 | Fence | 865-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1317 | BreakerVacuum | OH-1174 | VCB Readings | 9 Month Operations | 10 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1317 | BreakerVacuum | OH-1174 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1317 | BreakerVacuum | OH-1174 | VCB Readings | Accumulated Fault Duty A Ph V | 30.29 | % |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1317 | BreakerVacuum | OH-1174 | VCB Readings | Accumulated Fault Duty B Ph V | 32.68 | % |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1317 | BreakerVacuum | OH-1174 | VCB Readings | Accumulated Fault Duty C Ph V | 17.54 | % |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1317 | BreakerVacuum | OH-1174 | VCB Readings | Amps A Ø | 89.0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1317 | BreakerVacuum | OH-1174 | VCB Readings | Amps B Ø | 105.0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1317 | BreakerVacuum | OH-1174 | VCB Readings | Amps C Ø | 98.0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1317 | BreakerVacuum | OH-1174 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1317 | BreakerVacuum | OH-1174 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1317 | BreakerVacuum | OH-1174 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1317 | BreakerVacuum | OH-1174 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1317 | BreakerVacuum | OH-1174 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1317 | BreakerVacuum | OH-1174 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1317 | BreakerVacuum | OH-1174 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1317 | BreakerVacuum | OH-1174 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1317 | BreakerVacuum | OH-1174 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1317 | BreakerVacuum | OH-1174 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1317 | BreakerVacuum | OH-1174 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1317 | BreakerVacuum | OH-1174 | VCB Readings | General Comments | | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1317 | BreakerVacuum | OH-1174 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1317 | BreakerVacuum | OH-1174 | VCB Readings | Operations Counter AF | 264 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1317 | BreakerVacuum | OH-1174 | VCB Readings | Operations Counter AL | 264 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1317 | BreakerVacuum | OH-1174 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1317 | BreakerVacuum | OH-1174 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1317 | BreakerVacuum | OH-1174 | VCB Readings | Unknown Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Readings | Switching Operations | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Readings | Winding Temp Max | 20 | °C |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Readings | Winding Temp Present | 10 | °C |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | S0012 | WithLTC | 220-Offline-Distribution | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | ST000216 | Structure | 865-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | ST000216 | Structure | 865-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | ST000216 | Structure | 865-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | ST000216 | Structure | 865-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | ST000216 | Structure | 865-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | ST000216 | Structure | 865-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | ST000216 | Structure | 865-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | ST000216 | Structure | 865-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | ST000216 | Structure | 865-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | ST000216 | Structure | 865-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | ST000216 | Structure | 865-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | ST000216 | Structure | 865-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | ST000216 | Structure | 865-Structure | Structure Patrol Inspection | General Comments | Spare fuse barrel is starting to fray. | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | ST000216 | Structure | 865-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | ST000216 | Structure | 865-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | ST000216 | Structure | 865-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | ST000216 | Structure | 865-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | ST000216 | Structure | 865-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | YD000209 | Yard | 865-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | YD000209 | Yard | 865-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | YD000209 | Yard | 865-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | YD000209 | Yard | 865-Yard | Yard Patrol Inspection | General Comments | ok | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | YD000209 | Yard | 865-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | YD000209 | Yard | 865-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | YD000209 | Yard | 865-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | YD000209 | Yard | 865-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | YD000209 | Yard | 865-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | YD000209 | Yard | 865-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | YD000209 | Yard | 865-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | YD000209 | Yard | 865-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | YD000209 | Yard | 865-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | YD000209 | Yard | 865-Yard | Yard Patrol Inspection | Ambient Temp | 49 | °F |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | FE000209 | Fence | 865-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | FE000209 | Fence | 865-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | FE000209 | Fence | 865-Fence | Fence Patrol Inspection | General Comments | ok | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | FE000209 | Fence | 865-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | FE000209 | Fence | 865-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | FE000209 | Fence | 865-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | FE000209 | Fence | 865-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | FE000209 | Fence | 865-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | FE000209 | Fence | 865-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | FE000209 | Fence | 865-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | FE000209 | Fence | 865-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | FE000209 | Fence | 865-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | FE000209 | Fence | 865-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | FE000209 | Fence | 865-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Readings | Switching Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0923 | BreakerAirMagnetic | S-410 | AMCB Readings | Operations This Read AM | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | ST000650 | Structure | OH-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | ST000650 | Structure | OH-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | ST000650 | Structure | OH-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | ST000650 | Structure | OH-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | ST000650 | Structure | OH-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | ST000650 | Structure | OH-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | ST000650 | Structure | OH-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Readings | Switching Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Readings | Operations This Read AM | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Readings | Operations Counter AL | 930 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Readings | Operations Counter AF | 930 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Readings | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Readings | Amps C Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Readings | Amps C Ø | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Readings | Amps B Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Readings | Amps B Ø | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Readings | Amps A Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Readings | Amps A Ø | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Readings | Accumulated Fault Duty C Ph AM | 8.05 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Readings | Accumulated Fault Duty B Ph AM | 8.05 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Readings | Accumulated Fault Duty A Ph AM | 8.05 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Readings | 9 Months Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0929 | BreakerAirMagnetic | S-4KV BUS TIE | AMCB Readings | 9 Month Ops New | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1302 | BreakerVacuum | MD-1455 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1302 | BreakerVacuum | MD-1455 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1302 | BreakerVacuum | MD-1455 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1302 | BreakerVacuum | MD-1455 | VCB Readings | Operations Counter AL | 124 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1302 | BreakerVacuum | MD-1455 | VCB Readings | Operations Counter AF | 124 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1302 | BreakerVacuum | MD-1455 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1302 | BreakerVacuum | MD-1455 | VCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1302 | BreakerVacuum | MD-1455 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1302 | BreakerVacuum | MD-1455 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1302 | BreakerVacuum | MD-1455 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1302 | BreakerVacuum | MD-1455 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1302 | BreakerVacuum | MD-1455 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1302 | BreakerVacuum | MD-1455 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1302 | BreakerVacuum | MD-1455 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1302 | BreakerVacuum | MD-1455 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1302 | BreakerVacuum | MD-1455 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1302 | BreakerVacuum | MD-1455 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1302 | BreakerVacuum | MD-1455 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1302 | BreakerVacuum | MD-1455 | VCB Readings | Amps C Ø | 120.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1302 | BreakerVacuum | MD-1455 | VCB Readings | Amps B Ø | 120.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Readings | Switching Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Readings | Operations This Read AM | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Readings | Operations Counter AL | 794 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Readings | Operations Counter AF | 794 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Readings | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Readings | Amps C Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Readings | Amps C Ø | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Readings | Amps B Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Readings | Amps B Ø | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Readings | Amps A Ø Max | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Readings | Amps A Ø | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Readings | 9 Months Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0930 | BreakerAirMagnetic | S-4KV BUS TIE REACTOR | AMCB Readings | 9 Month Ops New | 0 | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | YD000241 | Yard | 476-Yard | Yard Patrol Inspection | Ambient Temp | 54 | °F |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | YD000241 | Yard | 476-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | YD000241 | Yard | 476-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | YD000241 | Yard | 476-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | YD000241 | Yard | 476-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | YD000241 | Yard | 476-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | YD000241 | Yard | 476-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | YD000241 | Yard | 476-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | YD000241 | Yard | 476-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | YD000241 | Yard | 476-Yard | Yard Patrol Inspection | General Comments | ok | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | YD000241 | Yard | 476-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | YD000241 | Yard | 476-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/15/2023 7:07 | Distribution | Overland South Quarterly Inspection | YD000241 | Yard | 476-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | ST000650 | Structure | OH-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | ST000650 | Structure | OH-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | ST000650 | Structure | OH-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | ST000650 | Structure | OH-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | ST000650 | Structure | OH-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | ST000650 | Structure | OH-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | ST000650 | Structure | OH-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | ST000650 | Structure | OH-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | ST000650 | Structure | OH-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | ST000650 | Structure | OH-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | ST000650 | Structure | OH-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | ST000650 | Structure | OH-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | ST000650 | Structure | OH-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | ST000650 | Structure | OH-Structure | Structure Patrol Inspection | General Comments | | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | ST000650 | Structure | OH-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | FE000652 | Fence | PV-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | FE000652 | Fence | PV-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | FE000652 | Fence | PV-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | FE000652 | Fence | PV-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | FE000652 | Fence | PV-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | FE000652 | Fence | PV-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | FE000652 | Fence | PV-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | FE000652 | Fence | PV-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | FE000652 | Fence | PV-Fence | Fence Patrol Inspection | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | FE000652 | Fence | PV-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | FE000652 | Fence | PV-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0796 | BreakerAirMagnetic | PV-12KV TR 1 | AMCB Readings | 9 Month Ops New | 2 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0796 | BreakerAirMagnetic | PV-12KV TR 1 | AMCB Readings | 9 Months Operations | 2 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0796 | BreakerAirMagnetic | PV-12KV TR 1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0796 | BreakerAirMagnetic | PV-12KV TR 1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0796 | BreakerAirMagnetic | PV-12KV TR 1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0796 | BreakerAirMagnetic | PV-12KV TR 1 | AMCB Readings | Amps A Ø | 475.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0796 | BreakerAirMagnetic | PV-12KV TR 1 | AMCB Readings | Amps B Ø | 475.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0796 | BreakerAirMagnetic | PV-12KV TR 1 | AMCB Readings | Amps C Ø | 500.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0796 | BreakerAirMagnetic | PV-12KV TR 1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0796 | BreakerAirMagnetic | PV-12KV TR 1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0796 | BreakerAirMagnetic | PV-12KV TR 1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0796 | BreakerAirMagnetic | PV-12KV TR 1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | LB0796 | BreakerAirMagnetic | PV-12KV TR 1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Readings | 9 Month Operations | 5 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Readings | Amps A Ø | 31.0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Readings | Amps B Ø | 35.0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Readings | Amps C Ø | 36.0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Readings | Fault Adjusted Amps C Phase V | 4.44 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000860 | LTCControl | 221-1 | LTC Control Insp | All Connections OK? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000860 | LTCControl | 221-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000860 | LTCControl | 221-1 | LTC Control Insp | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000860 | LTCControl | 221-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000860 | LTCControl | 221-1 | LTC Control Insp | LTC Output Voltage Level | 121.0 | VAC |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000860 | LTCControl | 221-1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000860 | LTCControl | 221-1 | LTC Control Insp | VRR Base Voltage AF | 120.0 | VAC |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000860 | LTCControl | 221-1 | LTC Control Insp | VRR Base Voltage AL | 120.0 | VAC |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | LTCC000860 | LTCControl | 221-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Readings | Fault Operations C Ø | 1 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | BK000720 | BreakerVacuum | 648-1762 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1302 | BreakerVacuum | MD-1455 | VCB Readings | Amps A Ø | 120.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1302 | BreakerVacuum | MD-1455 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1302 | BreakerVacuum | MD-1455 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1302 | BreakerVacuum | MD-1455 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1302 | BreakerVacuum | MD-1455 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1302 | BreakerVacuum | MD-1455 | VCB Readings | 9 Month Operations | 10 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | ST000636 | Structure | PV-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | ST000636 | Structure | PV-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | ST000636 | Structure | PV-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | ST000636 | Structure | PV-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | ST000636 | Structure | PV-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0576 | BreakerAirMagnetic | MD-1445-A | AMCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0576 | BreakerAirMagnetic | MD-1445-A | AMCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0576 | BreakerAirMagnetic | MD-1445-A | AMCB Readings | Operations This Read AM | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0576 | BreakerAirMagnetic | MD-1445-A | AMCB Readings | Operations Counter AL | 384 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0576 | BreakerAirMagnetic | MD-1445-A | AMCB Readings | Operations Counter AF | 384 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0576 | BreakerAirMagnetic | MD-1445-A | AMCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0576 | BreakerAirMagnetic | MD-1445-A | AMCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0576 | BreakerAirMagnetic | MD-1445-A | AMCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0576 | BreakerAirMagnetic | MD-1445-A | AMCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0576 | BreakerAirMagnetic | MD-1445-A | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0576 | BreakerAirMagnetic | MD-1445-A | AMCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0576 | BreakerAirMagnetic | MD-1445-A | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0576 | BreakerAirMagnetic | MD-1445-A | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0576 | BreakerAirMagnetic | MD-1445-A | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0576 | BreakerAirMagnetic | MD-1445-A | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0576 | BreakerAirMagnetic | MD-1445-A | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0576 | BreakerAirMagnetic | MD-1445-A | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0576 | BreakerAirMagnetic | MD-1445-A | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0576 | BreakerAirMagnetic | MD-1445-A | AMCB Readings | Amps C Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0576 | BreakerAirMagnetic | MD-1445-A | AMCB Readings | Amps B Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0576 | BreakerAirMagnetic | MD-1445-A | AMCB Readings | Amps A Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0576 | BreakerAirMagnetic | MD-1445-A | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0576 | BreakerAirMagnetic | MD-1445-A | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0576 | BreakerAirMagnetic | MD-1445-A | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0576 | BreakerAirMagnetic | MD-1445-A | AMCB Readings | 9 Months Operations | 15 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | ST000636 | Structure | PV-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | ST000636 | Structure | PV-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | ST000636 | Structure | PV-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | ST000636 | Structure | PV-Structure | Structure Patrol Inspection | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | ST000636 | Structure | PV-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | ST000636 | Structure | PV-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | ST000636 | Structure | PV-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | ST000636 | Structure | PV-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | ST000636 | Structure | PV-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | ST000636 | Structure | PV-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | ST000636 | Structure | PV-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | ST000636 | Structure | PV-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | ST000636 | Structure | PV-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | ST000636 | Structure | PV-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | ST000636 | Structure | PV-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | ST000636 | Structure | PV-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | FE000652 | Fence | PV-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | FE000652 | Fence | PV-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | FE000652 | Fence | PV-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | FE000652 | Fence | PV-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | FE000652 | Fence | PV-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Patrol Inspection | General Comments | ok | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Readings | General Comments | ok | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Readings | Operations Counter AF | 195 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Readings | Operations Counter AL | 195 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Readings | Operations This Read Vac | 1 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Readings | Unknown Operations | 1 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | PF000341 | PowerFuse | S-STA SER | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | PF000341 | PowerFuse | S-STA SER | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | PF000341 | PowerFuse | S-STA SER | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | PF000343 | PowerFuse | S-4KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | PF000343 | PowerFuse | S-4KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | PF000343 | PowerFuse | S-4KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000054 | CapacitorBank | MD-Cap Bank 2 | Capacitor Patrol Inspection | All Connections OK? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000054 | CapacitorBank | MD-Cap Bank 2 | Capacitor Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000054 | CapacitorBank | MD-Cap Bank 2 | Capacitor Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000054 | CapacitorBank | MD-Cap Bank 2 | Capacitor Patrol Inspection | Cap bank PT in Good Condition? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000054 | CapacitorBank | MD-Cap Bank 2 | Capacitor Patrol Inspection | Capacitor Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000054 | CapacitorBank | MD-Cap Bank 2 | Capacitor Patrol Inspection | Capacitor Rack Condition OK? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000054 | CapacitorBank | MD-Cap Bank 2 | Capacitor Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000054 | CapacitorBank | MD-Cap Bank 2 | Capacitor Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000054 | CapacitorBank | MD-Cap Bank 2 | Capacitor Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000054 | CapacitorBank | MD-Cap Bank 2 | Capacitor Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000054 | CapacitorBank | MD-Cap Bank 2 | Capacitor Patrol Inspection | Fuses Blown? Y / N | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000054 | CapacitorBank | MD-Cap Bank 2 | Capacitor Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000054 | CapacitorBank | MD-Cap Bank 2 | Capacitor Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000054 | CapacitorBank | MD-Cap Bank 2 | Capacitor Patrol Inspection | Insulators In Good Condition? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000054 | CapacitorBank | MD-Cap Bank 2 | Capacitor Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000054 | CapacitorBank | MD-Cap Bank 2 | Capacitor Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000054 | CapacitorBank | MD-Cap Bank 2 | Capacitor Patrol Inspection | Tank Paint Condition | Adequate | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000054 | CapacitorBank | MD-Cap Bank 2 | Capacitor Patrol Inspection | Warning Signs OK? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000055 | CapacitorBank | MD-Cap Bank 1 | Capacitor Patrol Inspection | All Connections OK? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000055 | CapacitorBank | MD-Cap Bank 1 | Capacitor Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000055 | CapacitorBank | MD-Cap Bank 1 | Capacitor Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000055 | CapacitorBank | MD-Cap Bank 1 | Capacitor Patrol Inspection | Cap bank PT in Good Condition? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000055 | CapacitorBank | MD-Cap Bank 1 | Capacitor Patrol Inspection | Capacitor Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000055 | CapacitorBank | MD-Cap Bank 1 | Capacitor Patrol Inspection | Capacitor Rack Condition OK? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000055 | CapacitorBank | MD-Cap Bank 1 | Capacitor Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000055 | CapacitorBank | MD-Cap Bank 1 | Capacitor Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000055 | CapacitorBank | MD-Cap Bank 1 | Capacitor Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000055 | CapacitorBank | MD-Cap Bank 1 | Capacitor Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000055 | CapacitorBank | MD-Cap Bank 1 | Capacitor Patrol Inspection | Fuses Blown? Y / N | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000055 | CapacitorBank | MD-Cap Bank 1 | Capacitor Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF000206 | PowerFuse | MD-STA SER NO 3 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF000207 | PowerFuse | MD-14KV TR 3 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF000207 | PowerFuse | MD-14KV TR 3 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF000207 | PowerFuse | MD-14KV TR 3 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | FE000253 | Fence | 648-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | FE000253 | Fence | 648-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | FE000253 | Fence | 648-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | FE000253 | Fence | 648-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | FE000253 | Fence | 648-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | FE000253 | Fence | 648-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | FE000253 | Fence | 648-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | FE000253 | Fence | 648-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | FE000253 | Fence | 648-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | FE000253 | Fence | 648-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | FE000253 | Fence | 648-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | FE000253 | Fence | 648-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | FE000253 | Fence | 648-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | FE000253 | Fence | 648-Fence | Fence Patrol Inspection | General Comments | ok | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | FE000253 | Fence | 648-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | FE000253 | Fence | 648-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | FE000400 | Fence | 220-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | FE000400 | Fence | 220-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | FE000400 | Fence | 220-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | FE000400 | Fence | 220-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | FE000400 | Fence | 220-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | FE000400 | Fence | 220-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | FE000400 | Fence | 220-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | FE000400 | Fence | 220-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | FE000400 | Fence | 220-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | FE000400 | Fence | 220-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | FE000400 | Fence | 220-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | FE000400 | Fence | 220-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | FE000400 | Fence | 220-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | FE000400 | Fence | 220-Fence | Fence Patrol Inspection | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | FE000400 | Fence | 220-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | FE000400 | Fence | 220-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Readings | 9 Month Operations | 1 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Readings | Amps A Ø | 95.0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Readings | Amps B Ø | 90.0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Readings | Amps C Ø | 100.0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Readings | Fault Adjusted Amps A Phase V | 4.44 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Readings | Fault Adjusted Amps B Phase V | 4.44 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Readings | Fault Adjusted Amps C Phase V | 4.44 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 13:25 | Distribution | Morganfield Industrial Quarterly Inspection | WB0154 | BreakerVacuum | 648-1763 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0587 | BreakerAirMagnetic | MD-1451 | AMCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0587 | BreakerAirMagnetic | MD-1451 | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Readings | 9 Month Ops New | 4 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Readings | 9 Months Operations | 5 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Readings | Accumulated Fault Duty A Ph AM | 3.33 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Readings | Accumulated Fault Duty B Ph AM | 5.54 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Readings | Accumulated Fault Duty C Ph AM | 6.65 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Readings | Amps A Ø | 87.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Readings | Amps A Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Readings | Amps B Ø | 61.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Readings | Amps B Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Readings | Amps C Ø | 103.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Readings | Amps C Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Readings | Fault Adjusted Amps A Phase AM | 9.55 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Readings | Fault Operations A Ø | 1 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Readings | General Comments | A phase IOC | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Readings | Operations Counter AF | 393 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Readings | Operations Counter AL | 393 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Readings | Operations This Read AM | 1 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Readings | Switching Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0925 | BreakerAirMagnetic | S-422 | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Readings | 9 Month Ops New | 2 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Readings | 9 Months Operations | 3 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Readings | Accumulated Fault Duty A Ph AM | 5.63 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Readings | Accumulated Fault Duty B Ph AM | 5.63 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Readings | Accumulated Fault Duty C Ph AM | 5.63 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Readings | Amps A Ø | 40.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Readings | Amps A Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Readings | Amps B Ø | 80.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Readings | Amps B Ø Max | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Readings | Amps C Ø | 20.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Readings | Amps C Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Readings | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0917 | BreakerAirMagnetic | S-1372 | AMCB Readings | Operations Counter AF | 849 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000055 | CapacitorBank | MD-Cap Bank 1 | Capacitor Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000055 | CapacitorBank | MD-Cap Bank 1 | Capacitor Patrol Inspection | Insulators In Good Condition? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000055 | CapacitorBank | MD-Cap Bank 1 | Capacitor Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000055 | CapacitorBank | MD-Cap Bank 1 | Capacitor Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000055 | CapacitorBank | MD-Cap Bank 1 | Capacitor Patrol Inspection | Tank Paint Condition | Adequate | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | CAP000055 | CapacitorBank | MD-Cap Bank 1 | Capacitor Patrol Inspection | Warning Signs OK? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | PF000273 | PowerFuse | PV-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | PF000273 | PowerFuse | PV-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | PF000274 | PowerFuse | PV-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | PF000274 | PowerFuse | PV-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | PF000025 | PowerFuse | AS-14KV TR 3 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | PF000025 | PowerFuse | AS-14KV TR 3 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | PF000025 | PowerFuse | AS-14KV TR 3 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | PF000026 | PowerFuse | AS-14KV TR 4 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | PF000026 | PowerFuse | AS-14KV TR 4 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | PF000026 | PowerFuse | AS-14KV TR 4 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | PF000027 | PowerFuse | AS-STA SER NO 4 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | PF000027 | PowerFuse | AS-STA SER NO 4 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | PF000027 | PowerFuse | AS-STA SER NO 4 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Switching Operations | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Operations Counter AL | 172 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Operations Counter AF | 172 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0587 | BreakerAirMagnetic | MD-1451 | AMCB Readings | 9 Month Ops New | 16 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0587 | BreakerAirMagnetic | MD-1451 | AMCB Readings | 9 Months Operations | 16 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0587 | BreakerAirMagnetic | MD-1451 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0587 | BreakerAirMagnetic | MD-1451 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0587 | BreakerAirMagnetic | MD-1451 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0587 | BreakerAirMagnetic | MD-1451 | AMCB Readings | Amps A Ø | 24.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0587 | BreakerAirMagnetic | MD-1451 | AMCB Readings | Amps B Ø | 25.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0587 | BreakerAirMagnetic | MD-1451 | AMCB Readings | Amps C Ø | 25.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0587 | BreakerAirMagnetic | MD-1451 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0587 | BreakerAirMagnetic | MD-1451 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0587 | BreakerAirMagnetic | MD-1451 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0587 | BreakerAirMagnetic | MD-1451 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0587 | BreakerAirMagnetic | MD-1451 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Amps C Ø | 0.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Amps B Ø | 0.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Amps A Ø | 0.0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | 9 Month Operations | 13 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0587 | BreakerAirMagnetic | MD-1451 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0587 | BreakerAirMagnetic | MD-1451 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0587 | BreakerAirMagnetic | MD-1451 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0587 | BreakerAirMagnetic | MD-1451 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0587 | BreakerAirMagnetic | MD-1451 | AMCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0587 | BreakerAirMagnetic | MD-1451 | AMCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0587 | BreakerAirMagnetic | MD-1451 | AMCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0587 | BreakerAirMagnetic | MD-1451 | AMCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0587 | BreakerAirMagnetic | MD-1451 | AMCB Readings | Operations Counter AF | 636 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0587 | BreakerAirMagnetic | MD-1451 | AMCB Readings | Operations Counter AL | 636 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0587 | BreakerAirMagnetic | MD-1451 | AMCB Readings | Operations This Read AM | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | LTCMechanism | 220-1 | LTC Counter Readings | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | LTCMechanism | 220-1 | LTC Mechanism Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | LTCMechanism | 220-1 | LTC Counter Readings | LTC As Found Counter | 951133 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Readings | Amps C Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Readings | Amps C Ø | 98.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Readings | Amps B Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Readings | Amps B Ø | 72.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Readings | Amps A Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Readings | Amps A Ø | 111.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Readings | Accumulated Fault Duty C Ph AM | 1.11 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Readings | Accumulated Fault Duty B Ph AM | 1.11 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Readings | 9 Months Operations | 1 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Readings | 9 Month Ops New | 1 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | LTCMechanism | 220-1 | LTC Counter Readings | LTC As Left Counter | 951133 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | LTCMechanism | 220-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | LTCMechanism | 220-1 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | LTCMechanism | 220-1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | LTCMechanism | 220-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | LTCMechanism | 220-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | LTCMechanism | 220-1 | LTC Counter Readings | LTC Operations Since Last Insp | 521 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | LTCMechanism | 220-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | LTCMechanism | 220-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | LTCMechanism | 220-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000130 | Switchgear | MD-Swgr Sec 3 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000130 | Switchgear | MD-Swgr Sec 3 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000130 | Switchgear | MD-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000130 | Switchgear | MD-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000130 | Switchgear | MD-Swgr Sec 3 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000130 | Switchgear | MD-Swgr Sec 3 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000204 | LTCControl | 220-Offline-Distribution | LTC Control Insp | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000204 | LTCControl | 220-Offline-Distribution | LTC Control Insp | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000204 | LTCControl | 220-Offline-Distribution | LTC Control Insp | All Connections OK? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | LTCC000827 | LTCControl | 496-1 | LTC Control Insp | All Connections OK? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | LTCC000827 | LTCControl | 496-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | LTCC000827 | LTCControl | 496-1 | LTC Control Insp | General Comments | ok | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | LTCC000827 | LTCControl | 496-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | LTCC000827 | LTCControl | 496-1 | LTC Control Insp | LTC Output Voltage Level | 124.5 | VAC |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | LTCC000827 | LTCControl | 496-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | LTCC000827 | LTCControl | 496-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | LTCC000827 | LTCControl | 496-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 20.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 33 | °C |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 61 | °C |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .8 | psi |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Readings | Operations This Read AM | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Readings | Operations Counter AL | 419 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Readings | Operations Counter AF | 419 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Readings | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0924 | BreakerAirMagnetic | S-421 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0592 | BreakerAirMagnetic | MD-14KV TR 1 | AMCB Readings | 9 Month Ops New | 13 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0592 | BreakerAirMagnetic | MD-14KV TR 1 | AMCB Readings | 9 Months Operations | 13 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0592 | BreakerAirMagnetic | MD-14KV TR 1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0592 | BreakerAirMagnetic | MD-14KV TR 1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0592 | BreakerAirMagnetic | MD-14KV TR 1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0592 | BreakerAirMagnetic | MD-14KV TR 1 | AMCB Readings | Amps A Ø | 260.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0592 | BreakerAirMagnetic | MD-14KV TR 1 | AMCB Readings | Amps B Ø | 260.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0592 | BreakerAirMagnetic | MD-14KV TR 1 | AMCB Readings | Amps C Ø | 260.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0592 | BreakerAirMagnetic | MD-14KV TR 1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0592 | BreakerAirMagnetic | MD-14KV TR 1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0592 | BreakerAirMagnetic | MD-14KV TR 1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0592 | BreakerAirMagnetic | MD-14KV TR 1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0592 | BreakerAirMagnetic | MD-14KV TR 1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0592 | BreakerAirMagnetic | MD-14KV TR 1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0592 | BreakerAirMagnetic | MD-14KV TR 1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0592 | BreakerAirMagnetic | MD-14KV TR 1 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0592 | BreakerAirMagnetic | MD-14KV TR 1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0592 | BreakerAirMagnetic | MD-14KV TR 1 | AMCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0592 | BreakerAirMagnetic | MD-14KV TR 1 | AMCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0592 | BreakerAirMagnetic | MD-14KV TR 1 | AMCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0592 | BreakerAirMagnetic | MD-14KV TR 1 | AMCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0592 | BreakerAirMagnetic | MD-14KV TR 1 | AMCB Readings | Operations Counter AF | 644 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0592 | BreakerAirMagnetic | MD-14KV TR 1 | AMCB Readings | Operations Counter AL | 644 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0592 | BreakerAirMagnetic | MD-14KV TR 1 | AMCB Readings | Operations This Read AM | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0592 | BreakerAirMagnetic | MD-14KV TR 1 | AMCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0592 | BreakerAirMagnetic | MD-14KV TR 1 | AMCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000130 | Switchgear | MD-Swgr Sec 3 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000130 | Switchgear | MD-Swgr Sec 3 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000130 | Switchgear | MD-Swgr Sec 3 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000130 | Switchgear | MD-Swgr Sec 3 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000130 | Switchgear | MD-Swgr Sec 3 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000130 | Switchgear | MD-Swgr Sec 3 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000130 | Switchgear | MD-Swgr Sec 3 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000130 | Switchgear | MD-Swgr Sec 3 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000130 | Switchgear | MD-Swgr Sec 3 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000130 | Switchgear | MD-Swgr Sec 3 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000130 | Switchgear | MD-Swgr Sec 3 | Switchgear Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000130 | Switchgear | MD-Swgr Sec 3 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | SWG000130 | Switchgear | MD-Swgr Sec 3 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | LTCMechanism | 220-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | B0437 | LTCMechanism | 220-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0273 | GroundTransformer | MD-GND TR 2 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0273 | GroundTransformer | MD-GND TR 2 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0273 | GroundTransformer | MD-GND TR 2 | Ground Transformer Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0273 | GroundTransformer | MD-GND TR 2 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0273 | GroundTransformer | MD-GND TR 2 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | .8 | psi |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0273 | GroundTransformer | MD-GND TR 2 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0273 | GroundTransformer | MD-GND TR 2 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0273 | GroundTransformer | MD-GND TR 2 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | ST000156 | Structure | 508-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | ST000156 | Structure | 508-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | ST000156 | Structure | 508-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | ST000156 | Structure | 508-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | ST000156 | Structure | 508-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | ST000156 | Structure | 508-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | ST000156 | Structure | 508-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | ST000156 | Structure | 508-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | ST000156 | Structure | 508-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | ST000156 | Structure | 508-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | ST000156 | Structure | 508-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | ST000156 | Structure | 508-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | ST000156 | Structure | 508-Structure | Structure Patrol Inspection | General Comments | | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | ST000156 | Structure | 508-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | ST000156 | Structure | 508-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | ST000156 | Structure | 508-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | ST000156 | Structure | 508-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | ST000156 | Structure | 508-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | ST000156 | Structure | 508-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | ST000156 | Structure | 508-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | ST000156 | Structure | 508-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | ST000156 | Structure | 508-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | FE000152 | Fence | 508-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | FE000152 | Fence | 508-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | FE000152 | Fence | 508-Fence | Fence Patrol Inspection | General Comments | | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | FE000152 | Fence | 508-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | FE000152 | Fence | 508-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | FE000152 | Fence | 508-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | FE000152 | Fence | 508-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | FE000152 | Fence | 508-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | FE000152 | Fence | 508-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | FE000152 | Fence | 508-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | FE000152 | Fence | 508-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | FE000152 | Fence | 508-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | FE000152 | Fence | 508-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | FE000152 | Fence | 508-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | FE000152 | Fence | 508-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | FE000152 | Fence | 508-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF000203 | PowerFuse | MD-STA SER NO 2 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF000203 | PowerFuse | MD-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF000203 | PowerFuse | MD-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF000206 | PowerFuse | MD-STA SER NO 3 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | PF000206 | PowerFuse | MD-STA SER NO 3 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Readings | H2 Winding Temp Present | 33 | °C |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Readings | H2 Winding Temp Max | 65 | °C |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0108 | WithLTC | MD-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 12 | °C |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 30 | °C |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 12 | °C |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 30 | °C |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 12 | °C |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 30 | °C |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 38 | °C |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Readings | H2 Winding Temp Present | 40 | °C |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Readings | H2 Winding Temp Max | 55 | °C |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0107 | WithLTC | MD-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0577 | BreakerAirMagnetic | MD-1445-B | AMCB Readings | Operations Counter AL | 668 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0577 | BreakerAirMagnetic | MD-1445-B | AMCB Readings | Operations Counter AF | 668 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0577 | BreakerAirMagnetic | MD-1445-B | AMCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0577 | BreakerAirMagnetic | MD-1445-B | AMCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0577 | BreakerAirMagnetic | MD-1445-B | AMCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0577 | BreakerAirMagnetic | MD-1445-B | AMCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0577 | BreakerAirMagnetic | MD-1445-B | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0577 | BreakerAirMagnetic | MD-1445-B | AMCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0577 | BreakerAirMagnetic | MD-1445-B | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1307 | BreakerVacuum | MD-GND TR 3 | VCB Readings | Amps A Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1307 | BreakerVacuum | MD-GND TR 3 | VCB Readings | Amps B Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0577 | BreakerAirMagnetic | MD-1445-B | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0577 | BreakerAirMagnetic | MD-1445-B | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0577 | BreakerAirMagnetic | MD-1445-B | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0577 | BreakerAirMagnetic | MD-1445-B | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0577 | BreakerAirMagnetic | MD-1445-B | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | LTCMechanism | MD-TRANS 3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | LTCMechanism | MD-TRANS 3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Readings | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Readings | Operations Counter AF | 355 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Readings | Operations Counter AL | 355 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Readings | Operations This Read AM | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Readings | Switching Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | LTCMechanism | MD-TRANS 3 | LTC Counter Readings | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Readings | 9 Month Operations | 1 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Readings | Amps A Ø | 375.0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | YD000306 | Yard | 221-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | YD000306 | Yard | 221-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | YD000306 | Yard | 221-Yard | Yard Patrol Inspection | Ambient Temp | 37 | °F |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1193 | Regulator | 508-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | LTCMechanism | S-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | LTCMechanism | S-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | LTCMechanism | S-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | LTCMechanism | S-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 14345 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | LTCMechanism | S-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 14345 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | LTCMechanism | S-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | LTCMechanism | S-TRANS 2 | LTC Counter Readings | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | FE000302 | Fence | 221-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | FE000302 | Fence | 221-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | FE000302 | Fence | 221-Fence | Fence Patrol Inspection | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | FE000302 | Fence | 221-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | FE000302 | Fence | 221-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | FE000302 | Fence | 221-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | FE000302 | Fence | 221-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | FE000302 | Fence | 221-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | LTCMechanism | S-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | LTCMechanism | S-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | FE000302 | Fence | 221-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | FE000302 | Fence | 221-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | FE000302 | Fence | 221-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | FE000302 | Fence | 221-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | FE000302 | Fence | 221-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | FE000302 | Fence | 221-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | FE000302 | Fence | 221-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | FE000302 | Fence | 221-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1307 | BreakerVacuum | MD-GND TR 3 | VCB Readings | 9 Month Operations | 1 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1307 | BreakerVacuum | MD-GND TR 3 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1307 | BreakerVacuum | MD-GND TR 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1307 | BreakerVacuum | MD-GND TR 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1307 | BreakerVacuum | MD-GND TR 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | LTCMechanism | 508-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0577 | BreakerAirMagnetic | MD-1445-B | AMCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0577 | BreakerAirMagnetic | MD-1445-B | AMCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0577 | BreakerAirMagnetic | MD-1445-B | AMCB Readings | Operations This Read AM | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Readings | Amps B Ø | 200.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Readings | Amps B Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Readings | Amps C Ø | 280.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Readings | Amps C Ø Max | 0.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1307 | BreakerVacuum | MD-GND TR 3 | VCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1307 | BreakerVacuum | MD-GND TR 3 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1307 | BreakerVacuum | MD-GND TR 3 | VCB Readings | Operations Counter AF | 123 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | LTCMechanism | MD-TRANS 3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | LTCMechanism | MD-TRANS 3 | LTC Counter Readings | LTC As Found Counter | 23069 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | LTCMechanism | MD-TRANS 3 | LTC Counter Readings | LTC As Left Counter | 23069 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | LTCMechanism | MD-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | LTCMechanism | MD-TRANS 3 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1307 | BreakerVacuum | MD-GND TR 3 | VCB Readings | Operations Counter AL | 123 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1307 | BreakerVacuum | MD-GND TR 3 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | ST000295 | Structure | 221-Structure | Structure Patrol Inspection | UG Pothead Condition Good? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | ST000295 | Structure | 221-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1307 | BreakerVacuum | MD-GND TR 3 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1307 | BreakerVacuum | MD-GND TR 3 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0584 | BreakerAirMagnetic | MD-1450 | AMCB Readings | 9 Month Ops New | 15 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0584 | BreakerAirMagnetic | MD-1450 | AMCB Readings | 9 Months Operations | 15 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0584 | BreakerAirMagnetic | MD-1450 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0584 | BreakerAirMagnetic | MD-1450 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0584 | BreakerAirMagnetic | MD-1450 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0584 | BreakerAirMagnetic | MD-1450 | AMCB Readings | Amps A Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0584 | BreakerAirMagnetic | MD-1450 | AMCB Readings | Amps B Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0584 | BreakerAirMagnetic | MD-1450 | AMCB Readings | Amps C Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0584 | BreakerAirMagnetic | MD-1450 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0584 | BreakerAirMagnetic | MD-1450 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | LTCMechanism | MD-TRANS 3 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Readings | General Comments | | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Patrol Inspection | General Comments | one fan needs replacing | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Readings | Amps B Ø | 375.0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Readings | Amps C Ø | 375.0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1307 | BreakerVacuum | MD-GND TR 3 | VCB Readings | Amps C Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1307 | BreakerVacuum | MD-GND TR 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Readings | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Readings | Operations Counter AF | 276 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Readings | Operations Counter AL | 276 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | BB0369 | BreakerVacuum | 220-108 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1307 | BreakerVacuum | MD-GND TR 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1307 | BreakerVacuum | MD-GND TR 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1307 | BreakerVacuum | MD-GND TR 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1307 | BreakerVacuum | MD-GND TR 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1307 | BreakerVacuum | MD-GND TR 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1307 | BreakerVacuum | MD-GND TR 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1307 | BreakerVacuum | MD-GND TR 3 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1307 | BreakerVacuum | MD-GND TR 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1307 | BreakerVacuum | MD-GND TR 3 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB1307 | BreakerVacuum | MD-GND TR 3 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1191 | Regulator | 508-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1191 | Regulator | 508-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1191 | Regulator | 508-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1191 | Regulator | 508-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | CH000204 | ControlHouse | PV-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | CH000204 | ControlHouse | PV-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | CH000204 | ControlHouse | PV-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | CH000204 | ControlHouse | PV-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1313 | BreakerVacuum | OH-1170 | VCB Readings | Amps C Ø | 126.0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1313 | BreakerVacuum | OH-1170 | VCB Readings | Amps B Ø | 143.0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1313 | BreakerVacuum | OH-1170 | VCB Readings | Amps A Ø | 140.0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1313 | BreakerVacuum | OH-1170 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1313 | BreakerVacuum | OH-1170 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1313 | BreakerVacuum | OH-1170 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1313 | BreakerVacuum | OH-1170 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1313 | BreakerVacuum | OH-1170 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1313 | BreakerVacuum | OH-1170 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1313 | BreakerVacuum | OH-1170 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1191 | Regulator | 508-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1313 | BreakerVacuum | OH-1170 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1313 | BreakerVacuum | OH-1170 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1313 | BreakerVacuum | OH-1170 | VCB Readings | Accumulated Fault Duty C Ph V | 4.78 | % |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1313 | BreakerVacuum | OH-1170 | VCB Readings | Accumulated Fault Duty B Ph V | 8.77 | % |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1191 | Regulator | 508-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 88823 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1191 | Regulator | 508-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1191 | Regulator | 508-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1191 | Regulator | 508-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | CH000204 | ControlHouse | PV-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | CH000204 | ControlHouse | PV-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1313 | BreakerVacuum | OH-1170 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1313 | BreakerVacuum | OH-1170 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1313 | BreakerVacuum | OH-1170 | VCB Readings | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | CH000204 | ControlHouse | PV-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1313 | BreakerVacuum | OH-1170 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1313 | BreakerVacuum | OH-1170 | VCB Readings | Operations Counter AF | 176 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1313 | BreakerVacuum | OH-1170 | VCB Readings | Operations Counter AL | 176 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1313 | BreakerVacuum | OH-1170 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1313 | BreakerVacuum | OH-1170 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1313 | BreakerVacuum | OH-1170 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000469 | LTCControl | 220-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000469 | LTCControl | 220-1 | LTC Control Insp | VRR Base Voltage AL | 121.0 | VAC |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000469 | LTCControl | 220-1 | LTC Control Insp | VRR Base Voltage AF | 121.0 | VAC |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | CH000204 | ControlHouse | PV-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | CH000204 | ControlHouse | PV-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | CH000204 | ControlHouse | PV-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | CH000204 | ControlHouse | PV-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | CH000204 | ControlHouse | PV-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | CH000204 | ControlHouse | PV-Control House | Control House Patrol Inspection | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | CH000204 | ControlHouse | PV-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | CH000204 | ControlHouse | PV-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | CH000204 | ControlHouse | PV-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | CH000204 | ControlHouse | PV-Control House | Control House Patrol Inspection | Restroom Clean & OK? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | CH000204 | ControlHouse | PV-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | CH000204 | ControlHouse | PV-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | CH000204 | ControlHouse | PV-Control House | Control House Patrol Inspection | Trash Emptied? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | CH000204 | ControlHouse | PV-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | CH000204 | ControlHouse | PV-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | CH000204 | ControlHouse | PV-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | YD000306 | Yard | 221-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | YD000306 | Yard | 221-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | YD000306 | Yard | 221-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | YD000306 | Yard | 221-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | YD000306 | Yard | 221-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | YD000306 | Yard | 221-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | YD000306 | Yard | 221-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | YD000306 | Yard | 221-Yard | Yard Patrol Inspection | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | YD000306 | Yard | 221-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | YD000306 | Yard | 221-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | YD000306 | Yard | 221-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | YD000306 | Yard | 221-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | YD000306 | Yard | 221-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1191 | Regulator | 508-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1191 | Regulator | 508-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1191 | Regulator | 508-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1191 | Regulator | 508-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1191 | Regulator | 508-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1191 | Regulator | 508-1 B | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1191 | Regulator | 508-1 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1191 | Regulator | 508-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1191 | Regulator | 508-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1191 | Regulator | 508-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1191 | Regulator | 508-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1191 | Regulator | 508-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1191 | Regulator | 508-1 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1191 | Regulator | 508-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1193 | Regulator | 508-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1193 | Regulator | 508-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1193 | Regulator | 508-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1193 | Regulator | 508-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1193 | Regulator | 508-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1193 | Regulator | 508-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1193 | Regulator | 508-1 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1193 | Regulator | 508-1 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1193 | Regulator | 508-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1193 | Regulator | 508-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1193 | Regulator | 508-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000468 | LTCControl | 220-2 | LTC Control Insp | VRR Base Voltage AL | 121.0 | VAC |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000468 | LTCControl | 220-2 | LTC Control Insp | VRR Base Voltage AF | 121.0 | VAC |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000468 | LTCControl | 220-2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000468 | LTCControl | 220-2 | LTC Control Insp | LTC Output Voltage Level | 121.0 | VAC |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000468 | LTCControl | 220-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000468 | LTCControl | 220-2 | LTC Control Insp | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000468 | LTCControl | 220-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000468 | LTCControl | 220-2 | LTC Control Insp | All Connections OK? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1193 | Regulator | 508-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1193 | Regulator | 508-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 125.2 | volts |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1193 | Regulator | 508-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 100493 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1193 | Regulator | 508-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1193 | Regulator | 508-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1193 | Regulator | 508-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | LTCMechanism | S-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | LTCMechanism | S-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | LTCMechanism | S-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | LTCMechanism | S-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 157 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | LTCMechanism | S-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | LTCMechanism | S-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | LTCMechanism | S-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | LTCMechanism | S-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | LTCMechanism | S-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | LTCMechanism | S-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 100408 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | LTCMechanism | S-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 100408 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | LTCMechanism | S-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | LTCMechanism | S-TRANS 1 | LTC Counter Readings | General Comments | | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | LTCMechanism | S-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0186 | LTCMechanism | S-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 2.98 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Readings | Amps A Ø | 280.0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Readings | Amps A Ø Max | 0.0 | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000469 | LTCControl | 220-1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000469 | LTCControl | 220-1 | LTC Control Insp | LTC Output Voltage Level | 121.0 | VAC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000469 | LTCControl | 220-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1313 | BreakerVacuum | OH-1170 | VCB Readings | Accumulated Fault Duty A Ph V | 5.58 | % |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1313 | BreakerVacuum | OH-1170 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 2/14/2023 6:57 | Distribution | Old Henry Quarterly Inspection | LB1313 | BreakerVacuum | OH-1170 | VCB Readings | 9 Month Operations | 8 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | LTCMechanism | 508-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | LTCMechanism | 508-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | LTCMechanism | 508-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | LTCMechanism | 508-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | LTCMechanism | 508-2 | LTC Counter Readings | LTC Operations Since Last Insp | 297 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | LTCMechanism | 508-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | LTCMechanism | 508-2 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | LTCMechanism | 508-2 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | LTCMechanism | 508-2 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | LTCMechanism | 508-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | LTCMechanism | 508-2 | LTC Counter Readings | LTC As Left Counter | 1839 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | LTCMechanism | 508-2 | LTC Counter Readings | LTC As Found Counter | 1833 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | LTCMechanism | 508-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | LTCMechanism | 508-2 | LTC Counter Readings | General Comments | | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | LTCMechanism | 508-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000469 | LTCControl | 220-1 | LTC Control Insp | General Comments | | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000469 | LTCControl | 220-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000469 | LTCControl | 220-1 | LTC Control Insp | All Connections OK? | y | |
| 2/14/2023 11:38 | Distribution | Toyota North Quarterly Inspection | LTCC000468 | LTCControl | 220-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LTCC000023 | LTCControl | MD-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LTCC000023 | LTCControl | MD-TRANS 1 | LTC Control Insp | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LTCC000023 | LTCControl | MD-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Readings | 9 Months Operations | 0 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 2.98 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LB0932 | BreakerAirMagnetic | S-4KV TR 1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 2.98 | % |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | LTCMechanism | S-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | LTCMechanism | S-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | LTCMechanism | S-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | LTCMechanism | S-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 197 | |
| 2/15/2023 15:01 | Distribution | Southern Quarterly Inspection | LT0185 | LTCMechanism | S-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1193 | Regulator | 508-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1193 | Regulator | 508-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1193 | Regulator | 508-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1193 | Regulator | 508-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1193 | Regulator | 508-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | R1193 | Regulator | 508-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001365 | BreakerVacuum | PV-1256 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001365 | BreakerVacuum | PV-1256 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001365 | BreakerVacuum | PV-1256 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001365 | BreakerVacuum | PV-1256 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001365 | BreakerVacuum | PV-1256 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001365 | BreakerVacuum | PV-1256 | VCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001365 | BreakerVacuum | PV-1256 | VCB Patrol Inspection | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001365 | BreakerVacuum | PV-1256 | VCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0582 | BreakerAirMagnetic | MD-1448-A | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0582 | BreakerAirMagnetic | MD-1448-A | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0582 | BreakerAirMagnetic | MD-1448-A | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0582 | BreakerAirMagnetic | MD-1448-A | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001365 | BreakerVacuum | PV-1256 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001365 | BreakerVacuum | PV-1256 | VCB Readings | Operations Counter AF | 152 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001365 | BreakerVacuum | PV-1256 | VCB Readings | Operations Counter AL | 152 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001365 | BreakerVacuum | PV-1256 | VCB Readings | Operations This Read Vac | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001365 | BreakerVacuum | PV-1256 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0582 | BreakerAirMagnetic | MD-1448-A | AMCB Readings | Amps C Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0582 | BreakerAirMagnetic | MD-1448-A | AMCB Readings | Amps B Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0582 | BreakerAirMagnetic | MD-1448-A | AMCB Readings | Amps A Ø | 0.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0584 | BreakerAirMagnetic | MD-1450 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0584 | BreakerAirMagnetic | MD-1450 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0582 | BreakerAirMagnetic | MD-1448-A | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001365 | BreakerVacuum | PV-1256 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | LTCC000980 | LTCControl | 508-2 | LTC Control Insp | All Connections OK? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0584 | BreakerAirMagnetic | MD-1450 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0584 | BreakerAirMagnetic | MD-1450 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Readings | Totalizer Meter Reading | .5814 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0584 | BreakerAirMagnetic | MD-1450 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0584 | BreakerAirMagnetic | MD-1450 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0584 | BreakerAirMagnetic | MD-1450 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | LTCC000980 | LTCControl | 508-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | LTCC000980 | LTCControl | 508-2 | LTC Control Insp | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0582 | BreakerAirMagnetic | MD-1448-A | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0582 | BreakerAirMagnetic | MD-1448-A | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0582 | BreakerAirMagnetic | MD-1448-A | AMCB Readings | 9 Months Operations | 22 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0582 | BreakerAirMagnetic | MD-1448-A | AMCB Readings | 9 Month Ops New | 13 | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | YD000197 | Yard | 496-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | YD000197 | Yard | 496-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | YD000197 | Yard | 496-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | YD000197 | Yard | 496-Yard | Yard Patrol Inspection | General Comments | ok | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | YD000197 | Yard | 496-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | YD000197 | Yard | 496-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | YD000197 | Yard | 496-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | YD000197 | Yard | 496-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | YD000197 | Yard | 496-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | YD000197 | Yard | 496-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | YD000197 | Yard | 496-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | LTCMechanism | MD-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | LTCC000980 | LTCControl | 508-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | LTCC000980 | LTCControl | 508-2 | LTC Control Insp | LTC Output Voltage Level | 124.4 | VAC |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0582 | BreakerAirMagnetic | MD-1448-A | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0582 | BreakerAirMagnetic | MD-1448-A | AMCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0582 | BreakerAirMagnetic | MD-1448-A | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0582 | BreakerAirMagnetic | MD-1448-A | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001363 | BreakerVacuum | PV-1255 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001363 | BreakerVacuum | PV-1255 | VCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001363 | BreakerVacuum | PV-1255 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BCH001220 | Charger | 508-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BCH001220 | Charger | 508-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001363 | BreakerVacuum | PV-1255 | VCB Readings | General Comments | | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001363 | BreakerVacuum | PV-1255 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001363 | BreakerVacuum | PV-1255 | VCB Readings | Operations Counter AF | 105 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001363 | BreakerVacuum | PV-1255 | VCB Readings | Operations Counter AL | 105 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001363 | BreakerVacuum | PV-1255 | VCB Readings | Operations This Read Vac | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001363 | BreakerVacuum | PV-1255 | VCB Readings | Switching Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001363 | BreakerVacuum | PV-1255 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0584 | BreakerAirMagnetic | MD-1450 | AMCB Readings | Operations Counter AL | 451 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0584 | BreakerAirMagnetic | MD-1450 | AMCB Readings | Operations This Read AM | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0584 | BreakerAirMagnetic | MD-1450 | AMCB Readings | Switching Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0584 | BreakerAirMagnetic | MD-1450 | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001363 | BreakerVacuum | PV-1255 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001363 | BreakerVacuum | PV-1255 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001363 | BreakerVacuum | PV-1255 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001363 | BreakerVacuum | PV-1255 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001365 | BreakerVacuum | PV-1256 | VCB Readings | 9 Month Operations | 3 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001365 | BreakerVacuum | PV-1256 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001363 | BreakerVacuum | PV-1255 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001363 | BreakerVacuum | PV-1255 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001365 | BreakerVacuum | PV-1256 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001365 | BreakerVacuum | PV-1256 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0582 | BreakerAirMagnetic | MD-1448-A | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001365 | BreakerVacuum | PV-1256 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | LTCMechanism | MD-TRANS 3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | LTCMechanism | MD-TRANS 3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | LTCMechanism | MD-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001365 | BreakerVacuum | PV-1256 | VCB Readings | Amps A Ø | 74.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001363 | BreakerVacuum | PV-1255 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001365 | BreakerVacuum | PV-1256 | VCB Readings | Amps B Ø | 58.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001365 | BreakerVacuum | PV-1256 | VCB Readings | Amps C Ø | 106.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001365 | BreakerVacuum | PV-1256 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001365 | BreakerVacuum | PV-1256 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001363 | BreakerVacuum | PV-1255 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001363 | BreakerVacuum | PV-1255 | VCB Readings | Amps C Ø | 48.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001363 | BreakerVacuum | PV-1255 | VCB Readings | Amps B Ø | 25.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001363 | BreakerVacuum | PV-1255 | VCB Readings | Amps A Ø | 31.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001363 | BreakerVacuum | PV-1255 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001363 | BreakerVacuum | PV-1255 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001363 | BreakerVacuum | PV-1255 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001363 | BreakerVacuum | PV-1255 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001363 | BreakerVacuum | PV-1255 | VCB Readings | 9 Month Operations | 5 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0584 | BreakerAirMagnetic | MD-1450 | AMCB Readings | Operations Counter AF | 451 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0584 | BreakerAirMagnetic | MD-1450 | AMCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0584 | BreakerAirMagnetic | MD-1450 | AMCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0584 | BreakerAirMagnetic | MD-1450 | AMCB Patrol Inspection | General Comments | | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0584 | BreakerAirMagnetic | MD-1450 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001365 | BreakerVacuum | PV-1256 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001365 | BreakerVacuum | PV-1256 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0582 | BreakerAirMagnetic | MD-1448-A | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BAT001279 | Battery | Retired Distribution | Battery Patrol Inspection | Positive DC Ground | 26.9 | VDC |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BAT001279 | Battery | Retired Distribution | Battery Patrol Inspection | Negative DC Ground | .6 | VDC |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BAT001279 | Battery | Retired Distribution | Battery Patrol Inspection | General Comments | | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BAT001279 | Battery | Retired Distribution | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BAT001279 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BAT001279 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | RC901735 | RecloserElectronic | 865-1733 | Recloser Electronic Patrol Inspection | Amps C Ø | 28.0 | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | RC901735 | RecloserElectronic | 865-1733 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | RC901735 | RecloserElectronic | 865-1733 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001366 | BreakerVacuum | PV-1257 | VCB Readings | Operations Counter AL | 111 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0582 | BreakerAirMagnetic | MD-1448-A | AMCB Readings | Switching Operations | 9 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BAT001279 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BAT001279 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BAT001279 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Area Ambient Temp | 61 | °F |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001366 | BreakerVacuum | PV-1257 | VCB Readings | Operations This Read Vac | 1 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001366 | BreakerVacuum | PV-1257 | VCB Readings | Switching Operations | 1 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001366 | BreakerVacuum | PV-1257 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BAT001279 | Battery | Retired Distribution | Battery Patrol Inspection | All Connections OK? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0577 | BreakerAirMagnetic | MD-1445-B | AMCB Readings | 9 Month Ops New | 16 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0577 | BreakerAirMagnetic | MD-1445-B | AMCB Readings | 9 Months Operations | 16 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0577 | BreakerAirMagnetic | MD-1445-B | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0577 | BreakerAirMagnetic | MD-1445-B | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0577 | BreakerAirMagnetic | MD-1445-B | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0577 | BreakerAirMagnetic | MD-1445-B | AMCB Readings | Amps A Ø | 124.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0577 | BreakerAirMagnetic | MD-1445-B | AMCB Readings | Amps B Ø | 124.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0577 | BreakerAirMagnetic | MD-1445-B | AMCB Readings | Amps C Ø | 124.0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0577 | BreakerAirMagnetic | MD-1445-B | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | RC901735 | RecloserElectronic | 865-1733 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0582 | BreakerAirMagnetic | MD-1448-A | AMCB Readings | Unknown Operations | 0 | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | RC901735 | RecloserElectronic | 865-1733 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | ST000295 | Structure | 221-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | ST000295 | Structure | 221-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | ST000295 | Structure | 221-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | RC901735 | RecloserElectronic | 865-1733 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | RC901735 | RecloserElectronic | 865-1733 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | RC901735 | RecloserElectronic | 865-1733 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | RC901735 | RecloserElectronic | 865-1733 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | RC901735 | RecloserElectronic | 865-1733 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | RC901735 | RecloserElectronic | 865-1733 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | RC901735 | RecloserElectronic | 865-1733 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | RC901735 | RecloserElectronic | 865-1733 | Recloser Electronic Patrol Inspection | Operations Counter | 0 | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | RC901735 | RecloserElectronic | 865-1733 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | RC901735 | RecloserElectronic | 865-1733 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | RC901735 | RecloserElectronic | 865-1733 | Recloser Electronic Patrol Inspection | General Comments | A-8 ops, B- 7 ops, C-7 ops | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | ST000295 | Structure | 221-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | ST000295 | Structure | 221-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | ST000295 | Structure | 221-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | ST000295 | Structure | 221-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | LTCMechanism | MD-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 18 | °C |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | LTCMechanism | MD-TRANS 3 | LTC Counter Readings | LTC Min Tap Position | 3L | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Readings | Oil Temp Present | 48 | °C |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Readings | Oil Temp Max | 48 | °C |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Readings | LTC Totalizer Reading | 2790.72 | kw |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0582 | BreakerAirMagnetic | MD-1448-A | AMCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0582 | BreakerAirMagnetic | MD-1448-A | AMCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0582 | BreakerAirMagnetic | MD-1448-A | AMCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | LTCMechanism | MD-TRANS 3 | LTC Counter Readings | LTC Operations Since Last Insp | 141 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LT0304 | LTCMechanism | MD-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 35 | °C |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | YD000197 | Yard | 496-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/14/2023 11:00 | Distribution | Camp Breckinridge Quarterly Inspection | YD000197 | Yard | 496-Yard | Yard Patrol Inspection | Ambient Temp | 54 | °F |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0583 | BreakerAirMagnetic | MD-1448-B | AMCB Readings | 9 Month Ops New | 12 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001366 | BreakerVacuum | PV-1257 | VCB Readings | 9 Month Operations | 2 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001366 | BreakerVacuum | PV-1257 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001366 | BreakerVacuum | PV-1257 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001366 | BreakerVacuum | PV-1257 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001366 | BreakerVacuum | PV-1257 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001366 | BreakerVacuum | PV-1257 | VCB Readings | Amps A Ø | 68.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001366 | BreakerVacuum | PV-1257 | VCB Readings | Amps B Ø | 70.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001366 | BreakerVacuum | PV-1257 | VCB Readings | Amps C Ø | 64.0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001366 | BreakerVacuum | PV-1257 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001366 | BreakerVacuum | PV-1257 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001366 | BreakerVacuum | PV-1257 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001366 | BreakerVacuum | PV-1257 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001366 | BreakerVacuum | PV-1257 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001366 | BreakerVacuum | PV-1257 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001366 | BreakerVacuum | PV-1257 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001366 | BreakerVacuum | PV-1257 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001366 | BreakerVacuum | PV-1257 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | LTCC000980 | LTCControl | 508-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | RC901735 | RecloserElectronic | 865-1733 | Recloser Electronic Patrol Inspection | Amps B Ø | 30.0 | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BAT001279 | Battery | Retired Distribution | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BAT001279 | Battery | Retired Distribution | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BCH001220 | Charger | 508-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BCH001220 | Charger | 508-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BCH001220 | Charger | 508-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BCH001220 | Charger | 508-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.2 | amps |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BCH001220 | Charger | 508-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | BCH001220 | Charger | 508-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | RC901735 | RecloserElectronic | 865-1733 | Recloser Electronic Patrol Inspection | Amps A Ø | 32.0 | |
| 2/14/2023 9:45 | Distribution | Sunoco Quarterly Inspection | RC901735 | RecloserElectronic | 865-1733 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001366 | BreakerVacuum | PV-1257 | VCB Readings | Operations Counter AF | 111 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001366 | BreakerVacuum | PV-1257 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001366 | BreakerVacuum | PV-1257 | VCB Readings | General Comments | | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0582 | BreakerAirMagnetic | MD-1448-A | AMCB Readings | Operations This Read AM | 9 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0582 | BreakerAirMagnetic | MD-1448-A | AMCB Readings | Operations Counter AL | 369 | |
| 2/14/2023 10:44 | Distribution | Madison Quarterly Inspection | LB0582 | BreakerAirMagnetic | MD-1448-A | AMCB Readings | Operations Counter AF | 369 | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001366 | BreakerVacuum | PV-1257 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | ST000295 | Structure | 221-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | ST000295 | Structure | 221-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | ST000295 | Structure | 221-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | ST000295 | Structure | 221-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/14/2023 10:20 | Distribution | Toyota South Quarterly Inspection | ST000295 | Structure | 221-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/15/2023 5:11 | Distribution | Plainview Quarterly Inspection | BK001366 | BreakerVacuum | PV-1257 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | LTCC000980 | LTCControl | 508-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | LTCC000980 | LTCControl | 508-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/14/2023 7:44 | Distribution | Sturgis Quarterly Inspection | S0009 | WithLTC | 508-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | BX1352 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | BX1352 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | BX1352 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | BX1352 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Operations Counter | 178 | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | BX1352 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | BX1352 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | BX1352 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | General Comments | | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | BX1352 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | BX1352 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | BX1352 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | BX1352 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | BX1352 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | BX1352 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | BX1352 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | BX1352 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | BX1352 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | BX1352 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | BX1352 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Amps C Ø | 41.0 | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | BX1352 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Amps B Ø | 31.0 | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | BX1352 | RecloserElectronic | Retired Distribution | Recloser Electronic Patrol Inspection | Amps A Ø | 37.0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | LTCC000129 | LTCControl | 588-1 | LTC Control Insp | LTC Output Voltage Level | 123.9 | VAC |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | LTCC000129 | LTCControl | 588-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | LTCC000129 | LTCControl | 588-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | LTCC000129 | LTCControl | 588-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Readings | General Comments | | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | LTCC000133 | LTCControl | 198-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | LTCC000133 | LTCControl | 198-5 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | LTCC000133 | LTCControl | 198-5 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | LTCC000133 | LTCControl | 198-5 | LTC Control Insp | LTC Output Voltage Level | 124.5 | VAC |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | LTCC000133 | LTCControl | 198-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | LTCC000133 | LTCControl | 198-5 | LTC Control Insp | General Comments | | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | LTCC000133 | LTCControl | 198-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | LTCC000133 | LTCControl | 198-5 | LTC Control Insp | All Connections OK? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 862.08 | kw |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 47 | °C |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 60 | °C |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | LTCC000974 | LTCControl | 588-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | LTCC000974 | LTCControl | 588-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | CX0553 | RecloserHydraulic | 501-1410 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 26.1 | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | CX0553 | RecloserHydraulic | 501-1410 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | CX0553 | RecloserHydraulic | 501-1410 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | CX0553 | RecloserHydraulic | 501-1410 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | CX0553 | RecloserHydraulic | 501-1410 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | CX0553 | RecloserHydraulic | 501-1410 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | CX0553 | RecloserHydraulic | 501-1410 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | CX0553 | RecloserHydraulic | 501-1410 | Recloser Hydraulic Patrol Inspection | Operations Counter | 179 | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | CX0553 | RecloserHydraulic | 501-1410 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | CX0553 | RecloserHydraulic | 501-1410 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Readings | Fault Operations Ground | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000216 | Regulator | 067-5 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000216 | Regulator | 067-5 A | Regulator Patrol Inspection | General Comments | | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Readings | Amps C Ø | 277.0 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000216 | Regulator | 067-5 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000216 | Regulator | 067-5 A | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000216 | Regulator | 067-5 A | Regulator Patrol Inspection | Min Tap Position | 4L | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000216 | Regulator | 067-5 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000216 | Regulator | 067-5 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000216 | Regulator | 067-5 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000216 | Regulator | 067-5 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000216 | Regulator | 067-5 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000216 | Regulator | 067-5 A | Regulator Patrol Inspection | Regulator As Left Counter | 1214 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000216 | Regulator | 067-5 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000216 | Regulator | 067-5 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Readings | 9 Month Operations | 2 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000216 | Regulator | 067-5 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000216 | Regulator | 067-5 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 65.00 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BCH000014 | Charger | SK-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BCH000014 | Charger | SK-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BCH000014 | Charger | SK-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BCH000014 | Charger | SK-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BCH000014 | Charger | SK-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.3 | amps |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BCH000014 | Charger | SK-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.7 | VDC |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BCH000014 | Charger | SK-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.7 | VDC |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BCH000014 | Charger | SK-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.000 | millivolts |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Readings | Winding Temp Present | 35 | °C |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Readings | Totalizer Meter Reading | .5724 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Readings | Totalizer Meter Reading | .5790 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 800 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Readings | General Comments | | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Readings | Top Oil Temperature Present | 43 | °C |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Readings | LTC Totalizer Reading | 5558.40 | kw |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Readings | Unknown Operations | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Readings | Switching Operations | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Readings | Operations This Read Vac | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Readings | Operations Counter AL | 199 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Readings | Operations Counter AF | 199 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Readings | Maintenance Operations | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Readings | General Comments | | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Patrol Inspection | General Comments | | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Readings | Follow-up Action Required? | n | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Readings | Fault Operations Ground | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Readings | 9 Month Operations | 15 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Readings | 9 Month Operations VCB New | 15 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Readings | Amps A Ø | 130.0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Readings | Amps B Ø | 145.0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Readings | Amps C Ø | 135.0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001407 | BreakerVacuum | 067-0707 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | WithLTC | BB-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Gas Accumulation Gauge | Normal | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Readings | Amps B Ø | 270.0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Readings | Amps A Ø | 278.0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Readings | 9 Month Operations | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Readings | Oil Temp Max | 80 | °C |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Readings | LTC Totalizer Reading | 10303.20 | kw |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Readings | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 100 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | LTCC000974 | LTCControl | 588-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | LTCC000974 | LTCControl | 588-2 | LTC Control Insp | LTC Output Voltage Level | 123.5 | VAC |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | LTCC000974 | LTCControl | 588-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Readings | Top Oil Temperature Max | 46 | °C |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | C0480 | WithLTC | 198-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | LTCC000974 | LTCControl | 588-2 | LTC Control Insp | General Comments | | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | LTCC000974 | LTCControl | 588-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | LTCC000974 | LTCControl | 588-2 | LTC Control Insp | All Connections OK? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.0776 | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Readings | Totalizer Meter Reading | .2724 | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | PF000034 | PowerFuse | BB-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | PF000034 | PowerFuse | BB-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | PF000034 | PowerFuse | BB-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Readings | Amps A Ø | 50.0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Readings | 9 Month Operations | 11 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | PF000302 | PowerFuse | SK-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | PF000302 | PowerFuse | SK-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | PF000302 | PowerFuse | SK-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000214 | Regulator | 067-5 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000214 | Regulator | 067-5 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000214 | Regulator | 067-5 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000214 | Regulator | 067-5 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000214 | Regulator | 067-5 C | Regulator Patrol Inspection | Regulator As Left Counter | 1162 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000214 | Regulator | 067-5 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000214 | Regulator | 067-5 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000214 | Regulator | 067-5 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000214 | Regulator | 067-5 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BAT000106 | Battery | BB-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BAT000106 | Battery | BB-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BAT000106 | Battery | BB-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 55 | °F |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BAT000106 | Battery | BB-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ST000621 | Structure | BB-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ST000621 | Structure | BB-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Operations This Read Vac | 0 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | PF000303 | PowerFuse | SK-12KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | PF000303 | PowerFuse | SK-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | PF000303 | PowerFuse | SK-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | ST000202 | Structure | 458-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | ST000202 | Structure | 458-Structure | Structure Patrol Inspection | General Comments | | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | ST000202 | Structure | 458-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | ST000202 | Structure | 458-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | ST000202 | Structure | 458-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | ST000202 | Structure | 458-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | ST000202 | Structure | 458-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | ST000202 | Structure | 458-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | ST000202 | Structure | 458-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | ST000202 | Structure | 458-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Readings | General Comments | | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Readings | LTC Totalizer Reading | 3922.56 | kw |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | WithLTC | 591-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | ST000589 | Structure | SK-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 24.17 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 10.00 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Readings | Oil Temp Max | 53 | °C |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Readings | Oil Temp Present | 37 | °C |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Readings | Percent Thermal Load H2 Max | -60 | % |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | ST000589 | Structure | SK-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | ST000589 | Structure | SK-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | ST000589 | Structure | SK-Structure | Structure Patrol Inspection | General Comments | | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | ST000589 | Structure | SK-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | ST000589 | Structure | SK-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Readings | Percent Thermal Load X2 Max | -60 | % |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Readings | Percent Thermal Load Y2 Max | -60 | % |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | ST000589 | Structure | SK-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | ST000589 | Structure | SK-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | ST000589 | Structure | SK-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Readings | 9 Month Operations | 1 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Readings | Amps A Ø | 31.0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Readings | Amps B Ø | 25.0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Readings | Amps C Ø | 31.0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | ST000589 | Structure | SK-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | ST000589 | Structure | SK-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Patrol Inspection | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | ST000589 | Structure | SK-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | ST000589 | Structure | SK-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000214 | Regulator | 067-5 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000214 | Regulator | 067-5 C | Regulator Patrol Inspection | Min Tap Position | 4L | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000214 | Regulator | 067-5 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000214 | Regulator | 067-5 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000214 | Regulator | 067-5 C | Regulator Patrol Inspection | General Comments | | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000214 | Regulator | 067-5 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000214 | Regulator | 067-5 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000214 | Regulator | 067-5 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000214 | Regulator | 067-5 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000214 | Regulator | 067-5 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000214 | Regulator | 067-5 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000214 | Regulator | 067-5 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000214 | Regulator | 067-5 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000214 | Regulator | 067-5 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000214 | Regulator | 067-5 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | YD000640 | Yard | BB-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | YD000640 | Yard | BB-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | YD000640 | Yard | BB-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | YD000640 | Yard | BB-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | YD000640 | Yard | BB-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | YD000640 | Yard | BB-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | YD000640 | Yard | BB-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Readings | General Comments | | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0019 | NonLTC | BB-PORT TRANS 4 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | YD000640 | Yard | BB-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | YD000640 | Yard | BB-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | YD000640 | Yard | BB-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | YD000640 | Yard | BB-Yard | Yard Patrol Inspection | General Comments | | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | YD000640 | Yard | BB-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | YD000640 | Yard | BB-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | YD000640 | Yard | BB-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | YD000640 | Yard | BB-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | ST000589 | Structure | SK-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | ST000589 | Structure | SK-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | ST000589 | Structure | SK-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | ST000589 | Structure | SK-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 100.00 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 73 | °C |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 50 | °C |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | WithLTC | 588-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000215 | Regulator | 067-5 B | Regulator Patrol Inspection | Min Tap Position | 4L | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000215 | Regulator | 067-5 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000215 | Regulator | 067-5 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000215 | Regulator | 067-5 B | Regulator Patrol Inspection | General Comments | | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000215 | Regulator | 067-5 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000215 | Regulator | 067-5 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000215 | Regulator | 067-5 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000215 | Regulator | 067-5 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000215 | Regulator | 067-5 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000215 | Regulator | 067-5 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000215 | Regulator | 067-5 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000215 | Regulator | 067-5 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000215 | Regulator | 067-5 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000215 | Regulator | 067-5 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Operations This Read Vac | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Patrol Inspection | General Comments | | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ST000621 | Structure | BB-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ST000621 | Structure | BB-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Readings | Unknown Operations | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Counter Readings | General Comments | | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Readings | Switching Operations | 1 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Readings | Operations This Read Vac | 1 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Readings | Operations Counter AL | 167 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Readings | Operations Counter AF | 166 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Readings | Maintenance Operations | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Readings | General Comments | | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Patrol Inspection | General Comments | | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ST000621 | Structure | BB-Structure | Structure Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ST000621 | Structure | BB-Structure | Structure Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ST000621 | Structure | BB-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ST000621 | Structure | BB-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ST000621 | Structure | BB-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | ST000202 | Structure | 458-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | ST000202 | Structure | 458-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Readings | Follow-up Action Required? | n | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Readings | General Comments | | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Readings | Maintenance Operations | 0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Readings | Operations Counter AF | 139 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Readings | Operations Counter AL | 139 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Readings | Operations This Read Vac | 0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Readings | Switching Operations | 0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001265 | BreakerVacuum | 198-5 | VCB Readings | Unknown Operations | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000216 | Regulator | 067-5 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000216 | Regulator | 067-5 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000216 | Regulator | 067-5 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000216 | Regulator | 067-5 A | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000216 | Regulator | 067-5 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000216 | Regulator | 067-5 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000216 | Regulator | 067-5 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 75 | °C |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000216 | Regulator | 067-5 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000216 | Regulator | 067-5 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000215 | Regulator | 067-5 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000215 | Regulator | 067-5 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 50 | °C |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | WithLTC | SK-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000215 | Regulator | 067-5 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000215 | Regulator | 067-5 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000215 | Regulator | 067-5 B | Regulator Patrol Inspection | Regulator As Left Counter | 1060 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000215 | Regulator | 067-5 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000215 | Regulator | 067-5 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000215 | Regulator | 067-5 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000215 | Regulator | 067-5 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | RG000215 | Regulator | 067-5 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Readings | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BAT000106 | Battery | BB-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BAT000106 | Battery | BB-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BAT000106 | Battery | BB-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | 9 Month Operations VCB New | 13 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Fans Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BAT000106 | Battery | BB-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BAT000106 | Battery | BB-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BAT000106 | Battery | BB-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BAT000106 | Battery | BB-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Readings | Amps C Ø | 64.0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Readings | Amps B Ø | 60.0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ST000621 | Structure | BB-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ST000621 | Structure | BB-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | ST000202 | Structure | 458-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | ST000202 | Structure | 458-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | ST000202 | Structure | 458-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | ST000202 | Structure | 458-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | ST000202 | Structure | 458-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | ST000202 | Structure | 458-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | ST000202 | Structure | 458-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | ST000202 | Structure | 458-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | ST000202 | Structure | 458-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ST000621 | Structure | BB-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ST000621 | Structure | BB-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ST000621 | Structure | BB-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ST000621 | Structure | BB-Structure | Structure Patrol Inspection | General Comments | | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ST000621 | Structure | BB-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ST000621 | Structure | BB-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ST000621 | Structure | BB-Structure | Structure Patrol Inspection | Interruptrs/Puffrs Visual OK? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ST000621 | Structure | BB-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ST000621 | Structure | BB-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ST000621 | Structure | BB-Structure | Structure Patrol Inspection | MOD Cabinet Internals Clean? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ST000621 | Structure | BB-Structure | Structure Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ST000621 | Structure | BB-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ST000621 | Structure | BB-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Readings | Follow-up Action Required? | n | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Readings | Fault Operations Ground | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001279 | BreakerVacuum | 588-2525 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BAT000106 | Battery | BB-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BAT000106 | Battery | BB-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BAT000106 | Battery | BB-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Readings | Fault Operations Ground | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Readings | Amps A Ø | 150.0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Readings | Amps B Ø | 175.0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Readings | Amps C Ø | 125.0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Readings | Amps C Ø | 107.0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Readings | Amps B Ø | 130.0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Readings | Amps A Ø | 108.0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Readings | 9 Month Operations | 1 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Readings | Fault Operations Ground | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Patrol Inspection | General Comments | | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Readings | 9 Month Operations | 1 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | SWG000049 | Switchgear | BB-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | SWG000049 | Switchgear | BB-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | SWG000049 | Switchgear | BB-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | SWG000049 | Switchgear | BB-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | SWG000049 | Switchgear | BB-Swgr Sec 1 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | SWG000049 | Switchgear | BB-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | SWG000049 | Switchgear | BB-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | SWG000049 | Switchgear | BB-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | SWG000049 | Switchgear | BB-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | SWG000049 | Switchgear | BB-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | R1039 | Regulator | 501-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | R1039 | Regulator | 501-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | R1039 | Regulator | 501-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | R1039 | Regulator | 501-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | R1039 | Regulator | 501-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 153483 | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | R1039 | Regulator | 501-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | R1039 | Regulator | 501-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | R1039 | Regulator | 501-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | R1039 | Regulator | 501-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | R1039 | Regulator | 501-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | R1039 | Regulator | 501-1 A | Regulator Patrol Inspection | Min Tap Position | 13L | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | R1039 | Regulator | 501-1 A | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | R1039 | Regulator | 501-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | R1039 | Regulator | 501-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | R1039 | Regulator | 501-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | R1039 | Regulator | 501-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | R1039 | Regulator | 501-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | R1039 | Regulator | 501-1 A | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | R1039 | Regulator | 501-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | R1039 | Regulator | 501-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | R1039 | Regulator | 501-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | R1039 | Regulator | 501-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | R1039 | Regulator | 501-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | SWG000049 | Switchgear | BB-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | SWG000049 | Switchgear | BB-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | SWG000049 | Switchgear | BB-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | SWG000049 | Switchgear | BB-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | SWG000049 | Switchgear | BB-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | SWG000049 | Switchgear | BB-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | SWG000049 | Switchgear | BB-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | SWG000049 | Switchgear | BB-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | SWG000049 | Switchgear | BB-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | SWG000049 | Switchgear | BB-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Readings | Follow-up Action Required? | n | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Readings | Fault Operations Ground | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1035 | Regulator | 458-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 256597 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1035 | Regulator | 458-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 125.1 | volts |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1035 | Regulator | 458-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1035 | Regulator | 458-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1035 | Regulator | 458-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | ST000255 | Structure | 501-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | ST000255 | Structure | 501-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | ST000255 | Structure | 501-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | ST000255 | Structure | 501-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | ST000255 | Structure | 501-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | ST000255 | Structure | 501-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | ST000255 | Structure | 501-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | ST000255 | Structure | 501-Structure | Structure Patrol Inspection | Platform/Walkway/Railing OK? | y | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | ST000255 | Structure | 501-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | ST000255 | Structure | 501-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | ST000255 | Structure | 501-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | ST000255 | Structure | 501-Structure | Structure Patrol Inspection | General Comments | | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | ST000255 | Structure | 501-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | ST000255 | Structure | 501-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | ST000255 | Structure | 501-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | ST000255 | Structure | 501-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | ST000255 | Structure | 501-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | ST000255 | Structure | 501-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | ST000255 | Structure | 501-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1035 | Regulator | 458-1 C | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1035 | Regulator | 458-1 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1035 | Regulator | 458-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | YD000249 | Yard | 501-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | YD000249 | Yard | 501-Yard | Yard Patrol Inspection | General Comments | | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | YD000249 | Yard | 501-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | YD000249 | Yard | 501-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | YD000249 | Yard | 501-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | YD000249 | Yard | 501-Yard | Yard Patrol Inspection | Ambient Temp | 47 | °F |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1035 | Regulator | 458-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1035 | Regulator | 458-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1035 | Regulator | 458-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1035 | Regulator | 458-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Readings | Follow-up Action Required? | n | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Patrol Inspection | General Comments | | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Readings | General Comments | | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Readings | Maintenance Operations | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Readings | Operations Counter AF | 277 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Readings | Operations Counter AL | 277 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Readings | Operations This Read Vac | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Readings | Switching Operations | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0083 | BreakerVacuum | 067-0704 | VCB Readings | Unknown Operations | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Readings | Amps C Ø | 160.0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Readings | Unknown Operations | 0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Readings | Switching Operations | 1 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Readings | Operations This Read Vac | 1 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Readings | Operations Counter AL | 182 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Readings | Operations Counter AF | 181 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Readings | Amps B Ø | 177.0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Readings | Amps A Ø | 140.0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Readings | 9 Month Operations | 1 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Readings | Maintenance Operations | 0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Readings | General Comments | | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Patrol Inspection | General Comments | | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Readings | Follow-up Action Required? | n | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Readings | Fault Operations Ground | 0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | B0188 | NonLTC | 501-1 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | B0188 | NonLTC | 501-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | B0188 | NonLTC | 501-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | B0188 | NonLTC | 501-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1035 | Regulator | 458-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1035 | Regulator | 458-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1035 | Regulator | 458-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | ST000519 | Structure | 591-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | ST000519 | Structure | 591-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | ST000519 | Structure | 591-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | ST000519 | Structure | 591-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | ST000519 | Structure | 591-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | ST000519 | Structure | 591-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | ST000519 | Structure | 591-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | ST000519 | Structure | 591-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | LTCC000324 | LTCControl | 067-6 | LTC Control Insp | All Connections OK? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | LTCC000324 | LTCControl | 067-6 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | LTCC000324 | LTCControl | 067-6 | LTC Control Insp | General Comments | | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | LTCC000324 | LTCControl | 067-6 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | LTCC000324 | LTCControl | 067-6 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | LTCC000324 | LTCControl | 067-6 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | LTCC000324 | LTCControl | 067-6 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | LTCC000324 | LTCControl | 067-6 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | YD000514 | Yard | 591-Yard | Yard Patrol Inspection | Ambient Temp | 40 | °F |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | YD000514 | Yard | 591-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LTCC000419 | LTCControl | AS-TRANS 3 | LTC Control Insp | General Comments | | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | YD000514 | Yard | 591-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | YD000514 | Yard | 591-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | YD000514 | Yard | 591-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | YD000514 | Yard | 591-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | YD000514 | Yard | 591-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | YD000514 | Yard | 591-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | BAT001610 | Battery | 458-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | BAT001610 | Battery | 458-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | BAT001610 | Battery | 458-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.5 | VDC |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | BAT001610 | Battery | 458-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.5 | VDC |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | BAT001610 | Battery | 458-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | BAT001610 | Battery | 458-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | BAT001610 | Battery | 458-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | BAT001610 | Battery | 458-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | BAT001610 | Battery | 458-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | BAT001610 | Battery | 458-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | BAT001610 | Battery | 458-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 55 | °F |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | BAT001610 | Battery | 458-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | YD000514 | Yard | 591-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | YD000514 | Yard | 591-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | YD000514 | Yard | 591-Yard | Yard Patrol Inspection | General Comments | | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | YD000514 | Yard | 591-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | YD000514 | Yard | 591-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | YD000514 | Yard | 591-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | YD000514 | Yard | 591-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | LTCMechanism | 591-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | LTCMechanism | 591-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | LTCMechanism | 591-1 | LTC Counter Readings | General Comments | | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | LTCMechanism | 591-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | BCH001536 | Charger | 458-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | BCH001536 | Charger | 458-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | LTCMechanism | 591-1 | LTC Counter Readings | LTC As Found Counter | 4748 | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | LTCMechanism | 591-1 | LTC Counter Readings | LTC As Left Counter | 4752 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LB1281 | BreakerOil | BB-1105 | OCB Readings | 9 Months Operations OCB New | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LB1281 | BreakerOil | BB-1105 | OCB Readings | Amps A Ø | 0.0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LB1281 | BreakerOil | BB-1105 | OCB Readings | Amps B Ø | 0.0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LB1281 | BreakerOil | BB-1105 | OCB Readings | Amps C Ø | 0.0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LB1281 | BreakerOil | BB-1105 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LB1281 | BreakerOil | BB-1105 | OCB Readings | Fault Operations | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LB1281 | BreakerOil | BB-1105 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LB1281 | BreakerOil | BB-1105 | OCB Readings | Follow-up Action Required? | n | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LB1281 | BreakerOil | BB-1105 | OCB Patrol Inspection | General Comments | | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LB1281 | BreakerOil | BB-1105 | OCB Readings | General Comments | | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LB1281 | BreakerOil | BB-1105 | OCB Readings | Maintenance Operations | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LB1281 | BreakerOil | BB-1105 | OCB Readings | Number of Ops last 9 Months | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LB1281 | BreakerOil | BB-1105 | OCB Readings | Operations Counter AF | 524 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LB1281 | BreakerOil | BB-1105 | OCB Readings | Operations Counter AL | 524 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LB1281 | BreakerOil | BB-1105 | OCB Readings | Operations This Read Oil | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LB1281 | BreakerOil | BB-1105 | OCB Readings | Switching Operations | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LB1281 | BreakerOil | BB-1105 | OCB Patrol Inspection | Tank Leaks | None | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LB1281 | BreakerOil | BB-1105 | OCB Patrol Inspection | Tank Oil Level | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LB1281 | BreakerOil | BB-1105 | OCB Readings | Unknown Operations | 0 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | SWG000064 | Switchgear | SK-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | SWG000064 | Switchgear | SK-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | SWG000064 | Switchgear | SK-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | SWG000064 | Switchgear | SK-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | SWG000064 | Switchgear | SK-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | SWG000064 | Switchgear | SK-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | SWG000064 | Switchgear | SK-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | SWG000064 | Switchgear | SK-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | SWG000064 | Switchgear | SK-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | SWG000064 | Switchgear | SK-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | SWG000064 | Switchgear | SK-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | SWG000064 | Switchgear | SK-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | SWG000064 | Switchgear | SK-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | SWG000064 | Switchgear | SK-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | SWG000064 | Switchgear | SK-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | SWG000064 | Switchgear | SK-Swgr Sec 1 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | SWG000064 | Switchgear | SK-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | SWG000064 | Switchgear | SK-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | SWG000064 | Switchgear | SK-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | SWG000064 | Switchgear | SK-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | ST000519 | Structure | 591-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | ST000519 | Structure | 591-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | ST000519 | Structure | 591-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | ST000519 | Structure | 591-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | ST000519 | Structure | 591-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | ST000519 | Structure | 591-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | ST000519 | Structure | 591-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | ST000519 | Structure | 591-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | ST000519 | Structure | 591-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | ST000519 | Structure | 591-Structure | Structure Patrol Inspection | General Comments | | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | ST000519 | Structure | 591-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | ST000519 | Structure | 591-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | ST000519 | Structure | 591-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | ST000519 | Structure | 591-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Surge Arrester Counter A Ø | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Surge Arrester Counter B Ø | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Surge Arrester Counter C Ø | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Readings | Totalizer Meter Reading | .8778 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LTCC000473 | LTCControl | AS-TRANS 4 | LTC Control Insp | General Comments | | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | LTCC000504 | LTCControl | 591-1 | LTC Control Insp | All Connections OK? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | LTCC000504 | LTCControl | 591-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | LTCC000504 | LTCControl | 591-1 | LTC Control Insp | General Comments | | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | LTCC000504 | LTCControl | 591-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | LTCC000504 | LTCControl | 591-1 | LTC Control Insp | LTC Output Voltage Level | 124.9 | VAC |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | LTCC000504 | LTCControl | 591-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | LTCC000504 | LTCControl | 591-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | LTCC000504 | LTCControl | 591-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Readings | Unknown Operations | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Readings | Switching Operations | 1 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Readings | Operations This Read Vac | 1 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Readings | Operations Counter AL | 156 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Readings | Unknown Operations | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Readings | Switching Operations | 1 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Readings | Operations This Read Vac | 1 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Readings | Operations Counter AL | 226 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Readings | Operations Counter AF | 225 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Readings | Maintenance Operations | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Readings | General Comments | | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Patrol Inspection | General Comments | | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | K0010 | BreakerVacuum | 588-2526 | VCB Readings | Follow-up Action Required? | n | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Readings | Operations Counter AF | 155 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Readings | Maintenance Operations | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK001280 | BreakerVacuum | 588-2537 | VCB Readings | General Comments | | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | LTCMechanism | 591-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | LTCMechanism | 591-1 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | LTCMechanism | 591-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | BCH001536 | Charger | 458-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | BCH001536 | Charger | 458-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | BCH001536 | Charger | 458-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 0.0 | amps |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | BCH001536 | Charger | 458-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | BCH001536 | Charger | 458-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | BCH001536 | Charger | 458-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 3.800 | millivolts |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | LTCMechanism | 591-1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | LTCMechanism | 591-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | LTCMechanism | 591-1 | LTC Counter Readings | LTC Operations Since Last Insp | 255 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | LTCMechanism | SK-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | LTCMechanism | SK-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | LTCMechanism | SK-TRANS 1 | LTC Counter Readings | General Comments | | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | LTCMechanism | SK-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | LTCMechanism | SK-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 11271 | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | LTCMechanism | 591-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | LTCMechanism | 591-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | LTCMechanism | 591-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | B0393 | LTCMechanism | 591-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | LTCMechanism | SK-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 11271 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | LTCMechanism | SK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | LTCMechanism | SK-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 10L | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | LTCMechanism | SK-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | LTCMechanism | SK-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 16L | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | LTCMechanism | SK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | LTCMechanism | SK-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 3655 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | LTCMechanism | SK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | LTCMechanism | SK-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | LT0172 | LTCMechanism | SK-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Gas Accumulation Gauge | Normal | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Readings | General Comments | | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | C0443 | WithLTC | 067-6 | LTC Transformer Readings | LTC Totalizer Reading | 8426.88 | kw |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Readings | 9 Month Operations | 1 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Readings | 9 Month Operations | 1 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Readings | Unknown Operations | 0 | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | B0188 | NonLTC | 501-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | B0188 | NonLTC | 501-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | B0188 | NonLTC | 501-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | B0188 | NonLTC | 501-1 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 600 | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | B0188 | NonLTC | 501-1 A | NonLTC Transformer Readings | Totalizer Meter Reading | .4899 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Readings | Switching Operations | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Readings | Operations This Read Vac | 1 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Readings | Operations Counter AL | 342 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Readings | Operations Counter AF | 342 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Readings | Maintenance Operations | 1 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Readings | General Comments | | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Patrol Inspection | General Comments | | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Readings | Follow-up Action Required? | n | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Readings | Fault Operations Ground | 0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | W0243 | NonLTC | 458-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | PF000035 | PowerFuse | BB-12KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | PF000035 | PowerFuse | BB-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | PF000035 | PowerFuse | BB-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Readings | Unknown Operations | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Readings | Switching Operations | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Readings | Operations This Read Vac | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Readings | Operations Counter AL | 172 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Readings | Operations Counter AF | 172 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Readings | Maintenance Operations | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Readings | General Comments | | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Patrol Inspection | General Comments | | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Readings | Follow-up Action Required? | n | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Readings | Fault Operations Ground | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Readings | Unknown Operations | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Readings | Switching Operations | 1 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Readings | Operations This Read Vac | 1 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Readings | Operations Counter AL | 74 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Readings | Operations Counter AF | 73 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Readings | Maintenance Operations | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Readings | General Comments | | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Patrol Inspection | General Comments | | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Readings | Follow-up Action Required? | n | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Readings | Amps C Ø | 58.0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Readings | Amps B Ø | 60.0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Readings | Amps A Ø | 42.0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Readings | Fault Operations Ground | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Readings | Amps C Ø | 70.0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Readings | Amps B Ø | 81.0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Readings | Amps A Ø | 100.0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0279 | BreakerVacuum | 588-2534 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Readings | Totalizer Meter Reading | .6288 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Readings | Amps C Ø | 88.0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Readings | Amps B Ø | 87.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Readings | Amps A Ø | 85.0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Readings | 9 Month Operations VCB New | 72 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Readings | 9 Month Operations | 73 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | LTCC000129 | LTCControl | 588-1 | LTC Control Insp | All Connections OK? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | LTCC000129 | LTCControl | 588-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | LTCC000129 | LTCControl | 588-1 | LTC Control Insp | General Comments | | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | LTCC000129 | LTCControl | 588-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Readings | Unknown Operations | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Readings | Switching Operations | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Readings | Operations This Read Vac | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Readings | Operations Counter AL | 189 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Readings | Operations Counter AF | 189 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Readings | Maintenance Operations | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Readings | General Comments | | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Patrol Inspection | General Comments | | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Readings | Follow-up Action Required? | n | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Readings | Fault Operations Ground | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Readings | Amps C Ø | 110.0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Readings | Amps B Ø | 115.0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Readings | Amps A Ø | 110.0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001408 | BreakerVacuum | 067-0708 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Readings | Amps C Ø | 30.0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Readings | Amps B Ø | 20.0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Readings | Amps A Ø | 45.0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | BK001409 | BreakerVacuum | 067-0709 | VCB Readings | 9 Month Operations | 3 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Patrol Inspection | General Comments | | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Readings | Follow-up Action Required? | n | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Readings | Fault Operations Ground | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Readings | General Comments | | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Readings | LTC Totalizer Reading | 11318.40 | kw |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Readings | Oil Temp Max | 70 | °C |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000680 | BreakerVacuum | BB-1102 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | WithLTC | 588-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1035 | Regulator | 458-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1035 | Regulator | 458-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1035 | Regulator | 458-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1035 | Regulator | 458-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Readings | 9 Month Operations | 1 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Readings | Maintenance Operations | 1 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Readings | General Comments | 1 op for a trip check | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Patrol Inspection | General Comments | | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | YD000195 | Yard | 458-Yard | Yard Patrol Inspection | Ambient Temp | 54 | °F |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | YD000195 | Yard | 458-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | YD000195 | Yard | 458-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | YD000195 | Yard | 458-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | YD000195 | Yard | 458-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | YD000195 | Yard | 458-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | YD000195 | Yard | 458-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | YD000195 | Yard | 458-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | YD000195 | Yard | 458-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | YD000195 | Yard | 458-Yard | Yard Patrol Inspection | General Comments | | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | YD000195 | Yard | 458-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | YD000195 | Yard | 458-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | YD000195 | Yard | 458-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | LTCMechanism | 588-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | LTCMechanism | 588-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | LTCMechanism | 588-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | LTCMechanism | 588-1 | LTC Counter Readings | LTC Operations Since Last Insp | 262 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | LTCMechanism | 588-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | LTCMechanism | 588-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | LTCMechanism | 588-1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | LTCMechanism | 588-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | LTCMechanism | 588-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | LTCMechanism | 588-1 | LTC Counter Readings | LTC As Left Counter | 277911 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | LTCMechanism | 588-1 | LTC Counter Readings | LTC As Found Counter | 277905 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | LTCMechanism | 588-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | LTCMechanism | 588-1 | LTC Counter Readings | General Comments | | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | LTCMechanism | 588-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | B0273 | LTCMechanism | 588-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | CX0129 | RecloserElectronic | 591-2532 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | CX0129 | RecloserElectronic | 591-2532 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | CX0129 | RecloserElectronic | 591-2532 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | CX0129 | RecloserElectronic | 591-2532 | Recloser Electronic Patrol Inspection | Operations Counter | 501 | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | CX0129 | RecloserElectronic | 591-2532 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | CX0129 | RecloserElectronic | 591-2532 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | CX0129 | RecloserElectronic | 591-2532 | Recloser Electronic Patrol Inspection | General Comments | | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | CX0129 | RecloserElectronic | 591-2532 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | CX0129 | RecloserElectronic | 591-2532 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | CX0129 | RecloserElectronic | 591-2532 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | CX0129 | RecloserElectronic | 591-2532 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | CX0129 | RecloserElectronic | 591-2532 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | YD000596 | Yard | SK-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | YD000596 | Yard | SK-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | YD000596 | Yard | SK-Yard | Yard Patrol Inspection | Clear of Trash? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | YD000596 | Yard | SK-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | YD000596 | Yard | SK-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | YD000596 | Yard | SK-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | YD000596 | Yard | SK-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | YD000596 | Yard | SK-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | YD000596 | Yard | SK-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | YD000596 | Yard | SK-Yard | Yard Patrol Inspection | General Comments | Replaced 4 outdoor lights. All are working now. | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | YD000596 | Yard | SK-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | YD000596 | Yard | SK-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | YD000596 | Yard | SK-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | YD000596 | Yard | SK-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | YD000596 | Yard | SK-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | YD000596 | Yard | SK-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | LTCMechanism | BB-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | LTCMechanism | BB-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | LTCMechanism | BB-TRANS 1 | LTC Counter Readings | General Comments | | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | LTCMechanism | BB-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | LTCMechanism | BB-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 57478 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | LTCMechanism | BB-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 57478 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Readings | Unknown Operations | 0 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Readings | Switching Operations | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | LTCMechanism | BB-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | LTCMechanism | BB-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | LTCMechanism | BB-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 7L | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | LTCMechanism | BB-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 3L | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | LTCMechanism | BB-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 116 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | LTCMechanism | BB-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | LTCMechanism | BB-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | LT0020 | LTCMechanism | BB-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Readings | Operations This Read Vac | 1 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Readings | Operations Counter AL | 143 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Readings | Operations Counter AF | 143 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Counter Readings | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Readings | Amps C Ø | 56.0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Readings | Amps B Ø | 66.0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Readings | Amps A Ø | 66.0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001163 | BreakerVacuum | 198-2521 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1035 | Regulator | 458-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1035 | Regulator | 458-1 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1035 | Regulator | 458-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | B0188 | NonLTC | 501-1 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | B0188 | NonLTC | 501-1 A | NonLTC Transformer Readings | General Comments | | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | B0188 | NonLTC | 501-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | B0188 | NonLTC | 501-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | B0188 | NonLTC | 501-1 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 293.94 | kw |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | B0188 | NonLTC | 501-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 207.50 | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | B0188 | NonLTC | 501-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 200.00 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Readings | General Comments | | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | B0188 | NonLTC | 501-1 A | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | B0188 | NonLTC | 501-1 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | B0188 | NonLTC | 501-1 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | B0188 | NonLTC | 501-1 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | B0188 | NonLTC | 501-1 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Readings | Follow-up Action Required? | n | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Readings | Fault Operations Ground | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Readings | Unknown Operations | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Readings | Switching Operations | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Readings | Operations This Read Vac | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Readings | Operations Counter AL | 186 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Readings | Operations Counter AF | 186 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Readings | General Comments | | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Patrol Inspection | General Comments | | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Readings | Follow-up Action Required? | n | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Readings | Amps C Ø | 25.0 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Readings | Amps B Ø | 60.0 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Readings | Amps A Ø | 15.0 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | K0113 | BreakerVacuum | 458-1404 | VCB Readings | 9 Month Operations | 1 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Readings | Fault Operations Ground | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000681 | BreakerVacuum | BB-1103 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | CX0129 | RecloserElectronic | 591-2532 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | CX0129 | RecloserElectronic | 591-2532 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | CX0129 | RecloserElectronic | 591-2532 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | CX0129 | RecloserElectronic | 591-2532 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | CX0129 | RecloserElectronic | 591-2532 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | CX0129 | RecloserElectronic | 591-2532 | Recloser Electronic Patrol Inspection | Amps C Ø | 92.0 | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | CX0129 | RecloserElectronic | 591-2532 | Recloser Electronic Patrol Inspection | Amps B Ø | 68.0 | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | CX0129 | RecloserElectronic | 591-2532 | Recloser Electronic Patrol Inspection | Amps A Ø | 120.0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Readings | Unknown Operations | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Readings | Switching Operations | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Readings | Operations Counter AL | 163 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Readings | Operations Counter AF | 163 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Readings | Maintenance Operations | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Readings | General Comments | | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Patrol Inspection | General Comments | | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Readings | Follow-up Action Required? | n | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Readings | Amps C Ø | 143.0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Readings | Amps B Ø | 148.0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Readings | Amps A Ø | 127.0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BK000682 | BreakerVacuum | BB-12KV TR1 | VCB Readings | 9 Month Operations | 0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Readings | Unknown Operations | 0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Readings | Switching Operations | 1 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Readings | Operations This Read Vac | 1 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Readings | Operations Counter AL | 172 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Readings | Operations Counter AF | 171 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001162 | BreakerVacuum | 198-2520 | VCB Readings | Maintenance Operations | 0 | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | B0188 | NonLTC | 501-1 A | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | B0188 | NonLTC | 501-1 A | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | B0188 | NonLTC | 501-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | B0188 | NonLTC | 501-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/13/2023 9:36 | Distribution | Diamond Quarterly Inspection | B0188 | NonLTC | 501-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Readings | Unknown Operations | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BAT001114 | Battery | 588-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 57 | °F |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BAT001114 | Battery | 588-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Readings | General Comments | | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Readings | General Comments | | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 2675.20 | kw |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Readings | Oil Temp Max | 60 | °C |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Readings | Unknown Operations | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Readings | Switching Operations | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Readings | Maintenance Operations | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Readings | Operations Counter AF | 210 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Readings | Operations Counter AL | 211 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Operations This Read Vac | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Readings | Follow-up Action Required? | n | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Patrol Inspection | General Comments | | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Readings | General Comments | | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Readings | Maintenance Operations | 0 | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | CS000014 | CircuitSwitcher | 591-1 Trans-Rupter | Circuit Switcher Inspection | Ambient Temp | 40 | °F |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | CS000014 | CircuitSwitcher | 591-1 Trans-Rupter | Circuit Switcher Inspection | Comments | | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | CS000014 | CircuitSwitcher | 591-1 Trans-Rupter | Circuit Switcher Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | CS000014 | CircuitSwitcher | 591-1 Trans-Rupter | Circuit Switcher Inspection | Follow-up Action Required? | n | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | CS000014 | CircuitSwitcher | 591-1 Trans-Rupter | Circuit Switcher Inspection | SF6 Indicator Zone | OK | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | 9 Month Operations VCB New | 21 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Readings | Operations Counter AF | 27 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Readings | Operations Counter AL | 27 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Readings | Operations This Read Vac | 1 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Readings | Switching Operations | 1 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Patrol Inspection | General Comments | | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Readings | Follow-up Action Required? | n | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | LTCMechanism | 588-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | LTCMechanism | 588-2 | LTC Counter Readings | LTC As Found Counter | 94754 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | LTCMechanism | 588-2 | LTC Counter Readings | LTC As Left Counter | 94758 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | LTCMechanism | 588-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Readings | Amps C Ø | 26.0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | ST000488 | Structure | 588-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Readings | Amps A Ø | 320.0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Readings | Amps B Ø | 340.0 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1033 | Regulator | 458-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1033 | Regulator | 458-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1033 | Regulator | 458-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 455806 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Operations This Read Vac | 0 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1033 | Regulator | 458-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1033 | Regulator | 458-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1033 | Regulator | 458-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1034 | Regulator | 458-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1034 | Regulator | 458-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1034 | Regulator | 458-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1034 | Regulator | 458-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1034 | Regulator | 458-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Readings | Operations This Read Vac | 1 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Readings | Switching Operations | 1 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Readings | Unknown Operations | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Readings | 9 Month Operations | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | FE000482 | Fence | 588-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Readings | General Comments | | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Patrol Inspection | General Comments | | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | FE000482 | Fence | 588-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | FE000482 | Fence | 588-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Readings | Follow-up Action Required? | n | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Readings | Totalizer Meter Reading | .8360 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1033 | Regulator | 458-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1033 | Regulator | 458-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Readings | Fault Operations Ground | 0 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Operations This Read Vac | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Readings | Operations Counter AL | 99956 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Readings | Operations Counter AF | 99956 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Readings | Maintenance Operations | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Readings | General Comments | | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Readings | Amps A Ø | 110.0 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | FE000591 | Fence | SK-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | LTCMechanism | 588-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | LTCMechanism | 588-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | LTCMechanism | 588-2 | LTC Counter Readings | General Comments | | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BCH001383 | Charger | 588-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Readings | Amps B Ø | 100.0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Readings | Amps C Ø | 100.0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | FE000636 | Fence | BB-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | FE000636 | Fence | BB-Fence | Fence Patrol Inspection | General Comments | | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | FE000636 | Fence | BB-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | FE000636 | Fence | BB-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | FE000636 | Fence | BB-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | FE000636 | Fence | BB-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | FE000636 | Fence | BB-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | FE000636 | Fence | BB-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | FE000636 | Fence | BB-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | FE000636 | Fence | BB-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | FE000636 | Fence | BB-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | FE000636 | Fence | BB-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | FE000636 | Fence | BB-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | FE000636 | Fence | BB-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | FE000636 | Fence | BB-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BAT001114 | Battery | 588-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BAT001114 | Battery | 588-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BAT001114 | Battery | 588-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BAT001114 | Battery | 588-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BAT001114 | Battery | 588-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BAT001114 | Battery | 588-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Readings | Fault Operations Ground | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BCH001383 | Charger | 588-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BCH001383 | Charger | 588-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | ST000488 | Structure | 588-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | ST000488 | Structure | 588-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | ST000488 | Structure | 588-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | ST000488 | Structure | 588-Structure | Structure Patrol Inspection | General Comments | | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | ST000488 | Structure | 588-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | ST000488 | Structure | 588-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | ST000488 | Structure | 588-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | ST000488 | Structure | 588-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | ST000488 | Structure | 588-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | ST000488 | Structure | 588-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | ST000488 | Structure | 588-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | FE000591 | Fence | SK-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | ST000488 | Structure | 588-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | ST000488 | Structure | 588-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | ST000488 | Structure | 588-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | ST000488 | Structure | 588-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | ST000488 | Structure | 588-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | ST000488 | Structure | 588-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | ST000488 | Structure | 588-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | ST000488 | Structure | 588-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | ST000488 | Structure | 588-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | FE000636 | Fence | BB-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BCH001383 | Charger | 588-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BCH001383 | Charger | 588-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.4 | amps |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BCH001383 | Charger | 588-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | FE000591 | Fence | SK-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | FE000591 | Fence | SK-Fence | Fence Patrol Inspection | General Comments | | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | FE000591 | Fence | SK-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | FE000591 | Fence | SK-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | FE000591 | Fence | SK-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | FE000591 | Fence | SK-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | FE000591 | Fence | SK-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | FE000591 | Fence | SK-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | FE000591 | Fence | SK-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | FE000591 | Fence | SK-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | FE000591 | Fence | SK-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Readings | 9 Month Operations | 1 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | FE000591 | Fence | SK-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | FE000591 | Fence | SK-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | FE000591 | Fence | SK-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Readings | Fault Operations Ground | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Readings | Follow-up Action Required? | n | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Patrol Inspection | General Comments | | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Readings | Amps A Ø | 165.0 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Readings | Amps B Ø | 180.0 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Readings | Amps C Ø | 178.0 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Readings | Fault Operations Ground | 0 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Readings | Follow-up Action Required? | n | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Patrol Inspection | General Comments | | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Readings | General Comments | | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BCH001383 | Charger | 588-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BCH001383 | Charger | 588-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Readings | Unknown Operations | 0 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Readings | Switching Operations | 3 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Readings | Operations This Read Vac | 3 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Readings | Operations Counter AL | 31 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Readings | Operations Counter AF | 31 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Readings | 9 Month Operations | 5 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Readings | Amps A Ø | 167.0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Readings | Amps B Ø | 186.0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Readings | Amps C Ø | 172.0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Readings | Maintenance Operations | 0 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Readings | 9 Month Operations | 1 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002120 | BreakerVacuum | SK-1128 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BK000319 | BreakerVacuum | 588-2524 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | 0987 | NonLTC | 067-5 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | LTCM000113 | LTCMechanism | 067-6 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | LTCM000113 | LTCMechanism | 067-6 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | LTCM000113 | LTCMechanism | 067-6 | LTC Counter Readings | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | LTCM000113 | LTCMechanism | 067-6 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | LTCM000113 | LTCMechanism | 067-6 | LTC Counter Readings | LTC As Found Counter | 43197 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Readings | Unknown Operations | 0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Readings | Switching Operations | 1 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Readings | Operations This Read Vac | 1 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Readings | Operations Counter AL | 163 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Readings | Operations Counter AF | 162 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | LTCM000113 | LTCMechanism | 067-6 | LTC Counter Readings | LTC As Left Counter | 43197 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | LTCM000113 | LTCMechanism | 067-6 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Readings | Maintenance Operations | 0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Readings | General Comments | | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Patrol Inspection | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | LTCM000064 | LTCMechanism | 198-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | LTCM000064 | LTCMechanism | 198-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | General Comments | | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ANN000008 | Annunciator | BB-Annunciator Panel | Annunciator Patrol Inspection | ESOC  Received Alarm Test? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ANN000008 | Annunciator | BB-Annunciator Panel | Annunciator Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ANN000008 | Annunciator | BB-Annunciator Panel | Annunciator Patrol Inspection | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1033 | Regulator | 458-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | YD000487 | Yard | 588-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Readings | Follow-up Action Required? | n | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Readings | Fault Operations Ground | 0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Readings | Amps C Ø | 187.0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Readings | Amps B Ø | 187.0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Readings | Amps A Ø | 190.0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | BK001161 | BreakerVacuum | 198-2519 | VCB Readings | 9 Month Operations | 1 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1033 | Regulator | 458-1 A | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | FE000482 | Fence | 588-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | n | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1033 | Regulator | 458-1 A | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | YD000487 | Yard | 588-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BAT001114 | Battery | 588-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BAT001114 | Battery | 588-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BCH000113 | Charger | BB-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BCH000113 | Charger | BB-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BCH000113 | Charger | BB-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | YD000487 | Yard | 588-Yard | Yard Patrol Inspection | Ambient Temp | 57 | °F |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BCH000113 | Charger | BB-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.4 | amps |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ANN000008 | Annunciator | BB-Annunciator Panel | Annunciator Patrol Inspection | All Lights Functioning? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | ANN000008 | Annunciator | BB-Annunciator Panel | Annunciator Patrol Inspection | Control House Alarm Audible? | y | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BCH000113 | Charger | BB-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | LTCM000064 | LTCMechanism | 198-5 | LTC Counter Readings | LTC As Left Counter | 227549 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | 9 Month Operations VCB New | 31 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Accumulated Fault Duty A Ph V | 1.28 | % |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Accumulated Fault Duty B Ph V | 1.28 | % |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Accumulated Fault Duty C Ph V | 1.28 | % |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | General Comments | | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | LTCM000064 | LTCMechanism | 198-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | LTCM000064 | LTCMechanism | 198-5 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | LTCM000064 | LTCMechanism | 198-5 | LTC Counter Readings | LTC Max Tap Position | Neutral | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | LTCM000064 | LTCMechanism | 198-5 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | LTCM000064 | LTCMechanism | 198-5 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | LTCM000064 | LTCMechanism | 198-5 | LTC Counter Readings | LTC Operations Since Last Insp | 312 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Operations This Read Vac | 0 | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | FE000509 | Fence | 591-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | FE000509 | Fence | 591-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | FE000509 | Fence | 591-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | FE000509 | Fence | 591-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | FE000509 | Fence | 591-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | FE000509 | Fence | 591-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | FE000509 | Fence | 591-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | FE000509 | Fence | 591-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | FE000509 | Fence | 591-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | FE000509 | Fence | 591-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | FE000509 | Fence | 591-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | FE000509 | Fence | 591-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | FE000509 | Fence | 591-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | LTCM000064 | LTCMechanism | 198-5 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | LTCM000064 | LTCMechanism | 198-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BCH000113 | Charger | BB-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BCH000113 | Charger | BB-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | LTCM000064 | LTCMechanism | 198-5 | LTC Counter Readings | LTC As Found Counter | 227544 | |
| 2/13/2023 8:21 | Distribution | Brandenburg Quarterly Inspection | BCH000113 | Charger | BB-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BAT000122 | Battery | SK-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BAT000122 | Battery | SK-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | LTCM000064 | LTCMechanism | 198-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BAT000122 | Battery | SK-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BAT000122 | Battery | SK-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BAT000122 | Battery | SK-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BAT000122 | Battery | SK-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BAT000122 | Battery | SK-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BAT000122 | Battery | SK-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | LTCM000064 | LTCMechanism | 198-5 | LTC Counter Readings | General Comments | | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BAT001114 | Battery | 588-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BAT001114 | Battery | 588-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BAT001114 | Battery | 588-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BAT001114 | Battery | 588-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | LTCM000064 | LTCMechanism | 198-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 15:11 | Distribution | Shelbyville Quarterly Inspection | LTCM000064 | LTCMechanism | 198-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BAT000122 | Battery | SK-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BAT000122 | Battery | SK-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BAT000122 | Battery | SK-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BAT000122 | Battery | SK-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | BAT001114 | Battery | 588-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | LTCM000113 | LTCMechanism | 067-6 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | YD000487 | Yard | 588-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | YD000487 | Yard | 588-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | YD000487 | Yard | 588-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | LTCM000113 | LTCMechanism | 067-6 | LTC Counter Readings | LTC Min Tap Position | 2L | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | LTCM000113 | LTCMechanism | 067-6 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | YD000487 | Yard | 588-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | YD000487 | Yard | 588-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | LTCM000113 | LTCMechanism | 067-6 | LTC Counter Readings | LTC Operations Since Last Insp | 66 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | LTCM000113 | LTCMechanism | 067-6 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | LTCM000113 | LTCMechanism | 067-6 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | LTCM000113 | LTCMechanism | 067-6 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | LTCM000113 | LTCMechanism | 067-6 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1034 | Regulator | 458-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1034 | Regulator | 458-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1034 | Regulator | 458-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1034 | Regulator | 458-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 908287 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1034 | Regulator | 458-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1034 | Regulator | 458-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1034 | Regulator | 458-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1034 | Regulator | 458-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1034 | Regulator | 458-1 B | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1034 | Regulator | 458-1 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1034 | Regulator | 458-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1034 | Regulator | 458-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1034 | Regulator | 458-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | General Comments | | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | LTCMechanism | 588-2 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Readings | 9 Month Operations | 9 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1034 | Regulator | 458-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1034 | Regulator | 458-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1034 | Regulator | 458-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1034 | Regulator | 458-1 B | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Readings | Amps A Ø | 29.0 | |
| 2/13/2023 10:26 | Distribution | Skylight Quarterly Inspection | BK002119 | BreakerVacuum | SK-1127 | VCB Readings | Amps B Ø | 29.0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | ST000488 | Structure | 588-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Readings | Amps C Ø | 330.0 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | CB0274 | BreakerVacuum | 588-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | YD000487 | Yard | 588-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | YD000487 | Yard | 588-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | LTCM000113 | LTCMechanism | 067-6 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1033 | Regulator | 458-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1033 | Regulator | 458-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1033 | Regulator | 458-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1033 | Regulator | 458-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1033 | Regulator | 458-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1033 | Regulator | 458-1 A | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | FE000482 | Fence | 588-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | FE000482 | Fence | 588-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | FE000482 | Fence | 588-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | FE000482 | Fence | 588-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | FE000482 | Fence | 588-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1033 | Regulator | 458-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | YD000487 | Yard | 588-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | 9 Month Operations VCB New | 17 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1033 | Regulator | 458-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | YD000487 | Yard | 588-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | YD000487 | Yard | 588-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1033 | Regulator | 458-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | FE000482 | Fence | 588-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | FE000482 | Fence | 588-Fence | Fence Patrol Inspection | General Comments | signs need to be updated | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | YD000487 | Yard | 588-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | FE000482 | Fence | 588-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | FE000482 | Fence | 588-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | FE000482 | Fence | 588-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | FE000482 | Fence | 588-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | YD000487 | Yard | 588-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | YD000487 | Yard | 588-Yard | Yard Patrol Inspection | General Comments | | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | FE000482 | Fence | 588-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Readings | Unknown Operations | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Readings | Switching Operations | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Readings | Operations This Read Vac | 0 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Readings | Operations Counter AL | 313 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Readings | Operations Counter AF | 313 | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/13/2023 7:14 | Distribution | Carrollton Quarterly Inspection | K0084 | BreakerVacuum | 067-0705 | VCB Readings | Maintenance Operations | 0 | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1033 | Regulator | 458-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/13/2023 11:00 | Distribution | Christian Quarterly Inspection | R1033 | Regulator | 458-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | LTCMechanism | 588-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | LTCMechanism | 588-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | LTCMechanism | 588-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | LTCMechanism | 588-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | LTCMechanism | 588-2 | LTC Counter Readings | LTC Operations Since Last Insp | 220 | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | LTCMechanism | 588-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | YD000487 | Yard | 588-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | YD000487 | Yard | 588-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | LTCMechanism | 588-2 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 2/13/2023 14:04 | Distribution | Shelbyville South Quarterly Inspection | C0528 | LTCMechanism | 588-2 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | FE000509 | Fence | 591-Fence | Fence Patrol Inspection | General Comments | needs updated signs | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | FE000509 | Fence | 591-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/13/2023 10:38 | Distribution | Lockport Quarterly Inspection | FE000509 | Fence | 591-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | n | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | 9 Month Operations VCB New | 20 | |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 2/15/2023 15:45 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000095 | Regulator | 004-5 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000095 | Regulator | 004-5 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000095 | Regulator | 004-5 C | Regulator Patrol Inspection | Regulator As Left Counter | 20594 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000095 | Regulator | 004-5 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.5 | volts |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000095 | Regulator | 004-5 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000095 | Regulator | 004-5 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000095 | Regulator | 004-5 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000095 | Regulator | 004-5 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000095 | Regulator | 004-5 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000095 | Regulator | 004-5 C | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000095 | Regulator | 004-5 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000095 | Regulator | 004-5 C | Regulator Patrol Inspection | General Comments | | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000095 | Regulator | 004-5 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000095 | Regulator | 004-5 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000095 | Regulator | 004-5 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000095 | Regulator | 004-5 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000095 | Regulator | 004-5 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000095 | Regulator | 004-5 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000095 | Regulator | 004-5 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000095 | Regulator | 004-5 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000095 | Regulator | 004-5 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000095 | Regulator | 004-5 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000095 | Regulator | 004-5 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000093 | Regulator | Retired Distribution | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000093 | Regulator | Retired Distribution | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000093 | Regulator | Retired Distribution | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000093 | Regulator | Retired Distribution | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000093 | Regulator | Retired Distribution | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000093 | Regulator | Retired Distribution | Regulator Patrol Inspection | General Comments | | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000093 | Regulator | Retired Distribution | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000093 | Regulator | Retired Distribution | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000093 | Regulator | Retired Distribution | Regulator Patrol Inspection | Reg Output Voltage Level | 123.5 | volts |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000093 | Regulator | Retired Distribution | Regulator Patrol Inspection | Regulator As Left Counter | 19525 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000093 | Regulator | Retired Distribution | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000093 | Regulator | Retired Distribution | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000093 | Regulator | Retired Distribution | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000093 | Regulator | Retired Distribution | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000093 | Regulator | Retired Distribution | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000093 | Regulator | Retired Distribution | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000093 | Regulator | Retired Distribution | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000093 | Regulator | Retired Distribution | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000093 | Regulator | Retired Distribution | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000093 | Regulator | Retired Distribution | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000093 | Regulator | Retired Distribution | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000093 | Regulator | Retired Distribution | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000093 | Regulator | Retired Distribution | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LTCC000544 | LTCControl | MC-Offline-Distribution | LTC Control Insp | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LTCC000544 | LTCControl | MC-Offline-Distribution | LTC Control Insp | General Comments | | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LTCC000544 | LTCControl | MC-Offline-Distribution | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0267 | NonLTC | 489-1 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Readings | Maintenance Operations | 0 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Readings | Operations Counter AF | 128 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Readings | Operations Counter AL | 128 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Readings | Operations This Read Vac | 1 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | FE000216 | Fence | 622-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | FE000216 | Fence | 622-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1195 | Regulator | 689-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1195 | Regulator | 689-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1195 | Regulator | 689-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1195 | Regulator | 689-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 86534 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1195 | Regulator | 689-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0267 | NonLTC | 489-1 B | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0267 | NonLTC | 489-1 B | NonLTC Transformer Readings | Totalizer Meter Reading | .2580 | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0267 | NonLTC | 489-1 B | NonLTC Transformer Readings | Totalizer Meter Multiplier | 800 | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0267 | NonLTC | 489-1 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0267 | NonLTC | 489-1 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0267 | NonLTC | 489-1 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0267 | NonLTC | 489-1 B | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0267 | NonLTC | 489-1 B | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0267 | NonLTC | 489-1 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0267 | NonLTC | 489-1 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0267 | NonLTC | 489-1 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0267 | NonLTC | 489-1 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0267 | NonLTC | 489-1 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0267 | NonLTC | 489-1 B | NonLTC Transformer Readings | General Comments | | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0267 | NonLTC | 489-1 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0267 | NonLTC | 489-1 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0267 | NonLTC | 489-1 B | NonLTC Transformer Readings | Non LTC Totalizer Reading | 206.40 | kw |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0267 | NonLTC | 489-1 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0267 | NonLTC | 489-1 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0267 | NonLTC | 489-1 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0267 | NonLTC | 489-1 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0267 | NonLTC | 489-1 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0562 | BreakerAirMagnetic | LY-12KV TR 2 | AMCB Readings | General Comments | | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0562 | BreakerAirMagnetic | LY-12KV TR 2 | AMCB Readings | Maintenance Operations | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0562 | BreakerAirMagnetic | LY-12KV TR 2 | AMCB Readings | Operations Counter AF | 51 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0562 | BreakerAirMagnetic | LY-12KV TR 2 | AMCB Readings | Operations Counter AL | 51 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0562 | BreakerAirMagnetic | LY-12KV TR 2 | AMCB Readings | Operations This Read AM | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | BK000563 | BreakerVacuum | LY-LS 12KV BUS TIE | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | BK000563 | BreakerVacuum | LY-LS 12KV BUS TIE | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | BK000563 | BreakerVacuum | LY-LS 12KV BUS TIE | VCB Readings | 9 Month Operations | 1 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Readings | Fault Operations Ground | 0 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0562 | BreakerAirMagnetic | LY-12KV TR 2 | AMCB Readings | Switching Operations | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0562 | BreakerAirMagnetic | LY-12KV TR 2 | AMCB Readings | Unknown Operations | 0 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Readings | Follow-up Action Required? | n | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Readings | Amps A Ø | 137.0 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Readings | Amps B Ø | 172.0 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Readings | Amps C Ø | 155.0 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Readings | Fault Operations Ground | 0 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Readings | Follow-up Action Required? | n | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Patrol Inspection | General Comments | | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Readings | General Comments | 1 op for trip check 1/20/23 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Readings | Maintenance Operations | 1 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BCH001051 | Charger | 689-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BCH001051 | Charger | 689-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BCH001051 | Charger | 689-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .8 | amps |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BCH001051 | Charger | 689-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Readings | 9 Month Operations | 2 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Readings | Fault Adjusted Amps A Phase V | 10.19 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0562 | BreakerAirMagnetic | LY-12KV TR 2 | AMCB Readings | 9 Month Ops New | 1 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0562 | BreakerAirMagnetic | LY-12KV TR 2 | AMCB Readings | 9 Months Operations | 1 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0562 | BreakerAirMagnetic | LY-12KV TR 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0562 | BreakerAirMagnetic | LY-12KV TR 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0562 | BreakerAirMagnetic | LY-12KV TR 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0562 | BreakerAirMagnetic | LY-12KV TR 2 | AMCB Readings | Amps A Ø | 310.0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0562 | BreakerAirMagnetic | LY-12KV TR 2 | AMCB Readings | Amps B Ø | 310.0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0562 | BreakerAirMagnetic | LY-12KV TR 2 | AMCB Readings | Amps C Ø | 310.0 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Readings | Fault Adjusted Amps B Phase V | 10.19 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Readings | Fault Adjusted Amps C Phase V | 10.19 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | BK000563 | BreakerVacuum | LY-LS 12KV BUS TIE | VCB Readings | Fault Operations B Ø | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | BK000563 | BreakerVacuum | LY-LS 12KV BUS TIE | VCB Readings | Fault Operations A Ø | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | BK000563 | BreakerVacuum | LY-LS 12KV BUS TIE | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | BK000563 | BreakerVacuum | LY-LS 12KV BUS TIE | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | BK000563 | BreakerVacuum | LY-LS 12KV BUS TIE | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | BK000563 | BreakerVacuum | LY-LS 12KV BUS TIE | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | BK000563 | BreakerVacuum | LY-LS 12KV BUS TIE | VCB Readings | Amps C Ø | 2.0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | BK000563 | BreakerVacuum | LY-LS 12KV BUS TIE | VCB Readings | Amps B Ø | 2.0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | BK000563 | BreakerVacuum | LY-LS 12KV BUS TIE | VCB Readings | Amps A Ø | 3.0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | BK000563 | BreakerVacuum | LY-LS 12KV BUS TIE | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | BK000563 | BreakerVacuum | LY-LS 12KV BUS TIE | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0562 | BreakerAirMagnetic | LY-12KV TR 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0562 | BreakerAirMagnetic | LY-12KV TR 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0562 | BreakerAirMagnetic | LY-12KV TR 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0562 | BreakerAirMagnetic | LY-12KV TR 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0562 | BreakerAirMagnetic | LY-12KV TR 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0562 | BreakerAirMagnetic | LY-12KV TR 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0562 | BreakerAirMagnetic | LY-12KV TR 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0562 | BreakerAirMagnetic | LY-12KV TR 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0562 | BreakerAirMagnetic | LY-12KV TR 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0562 | BreakerAirMagnetic | LY-12KV TR 2 | AMCB Readings | Follow-up Action Required? | n | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0562 | BreakerAirMagnetic | LY-12KV TR 2 | AMCB Patrol Inspection | General Comments | | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | FE000322 | Fence | 689-Fence | Fence Patrol Inspection | General Comments | | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | FE000322 | Fence | 689-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Readings | Switching Operations | 0 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | FE000322 | Fence | 689-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | FE000322 | Fence | 689-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | FE000322 | Fence | 689-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | FE000322 | Fence | 689-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | FE000322 | Fence | 689-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | FE000322 | Fence | 689-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | FE000322 | Fence | 689-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | FE000322 | Fence | 689-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Readings | Operations This Read Vac | 1 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Readings | Operations Counter AL | 169 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | FE000322 | Fence | 689-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | FE000322 | Fence | 689-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | FE000322 | Fence | 689-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | FE000322 | Fence | 689-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Readings | Operations Counter AF | 169 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Readings | Maintenance Operations | 1 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | LTCC000781 | LTCControl | 610-1 | LTC Control Insp | All Connections OK? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | LTCC000781 | LTCControl | 610-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | LTCC000781 | LTCControl | 610-1 | LTC Control Insp | General Comments | | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | LTCC000781 | LTCControl | 610-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | LTCC000781 | LTCControl | 610-1 | LTC Control Insp | LTC Output Voltage Level | 124.2 | VAC |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | LTCC000781 | LTCControl | 610-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | LTCC000781 | LTCControl | 610-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | LTCC000781 | LTCControl | 610-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Readings | General Comments | | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Patrol Inspection | General Comments | | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Readings | Follow-up Action Required? | n | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Readings | Fault Operations Ground | 0 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Readings | General Comments | | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BCH001051 | Charger | 689-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Readings | Operations Counter AF | 183 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Readings | Operations Counter AL | 183 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Readings | Operations This Read Vac | 1 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Readings | Switching Operations | 0 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | BK000723 | BreakerVacuum | 004-1751 | VCB Readings | Unknown Operations | 0 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Patrol Inspection | General Comments | | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Readings | Unknown Operations | 0 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | LTCMechanism | 610-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | LTCMechanism | 610-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | LTCMechanism | 610-1 | LTC Counter Readings | General Comments | | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | LTCMechanism | 610-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | LTCMechanism | 610-1 | LTC Counter Readings | LTC As Found Counter | 1271 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | LTCMechanism | 610-1 | LTC Counter Readings | LTC As Left Counter | 1279 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | LTCMechanism | 610-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | LTCMechanism | 610-1 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | LTCMechanism | 610-1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | LTCMechanism | 610-1 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | LTCMechanism | 610-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | LTCMechanism | 610-1 | LTC Counter Readings | LTC Operations Since Last Insp | 142 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | LTCMechanism | 610-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | LTCMechanism | 610-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | LTCMechanism | 610-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | YD000325 | Yard | 689-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | YD000325 | Yard | 689-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | YD000325 | Yard | 689-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | YD000325 | Yard | 689-Yard | Yard Patrol Inspection | General Comments | | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | YD000325 | Yard | 689-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | YD000325 | Yard | 689-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | YD000325 | Yard | 689-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | YD000325 | Yard | 689-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | YD000325 | Yard | 689-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | YD000325 | Yard | 689-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | YD000325 | Yard | 689-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | YD000325 | Yard | 689-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | YD000325 | Yard | 689-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | YD000325 | Yard | 689-Yard | Yard Patrol Inspection | Ambient Temp | 42 | °F |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | FE000322 | Fence | 689-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | FE000322 | Fence | 689-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Readings | Amps C Ø | 119.0 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Readings | Amps B Ø | 125.0 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Readings | Amps A Ø | 145.0 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Readings | 9 Month Operations | 1 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1194 | Regulator | 689-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 89227 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1194 | Regulator | 689-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1194 | Regulator | 689-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1194 | Regulator | 689-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1194 | Regulator | 689-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | YD000375 | Yard | 489-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | YD000375 | Yard | 489-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | YD000375 | Yard | 489-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | YD000375 | Yard | 489-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | YD000375 | Yard | 489-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | YD000375 | Yard | 489-Yard | Yard Patrol Inspection | General Comments | | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | YD000375 | Yard | 489-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | YD000375 | Yard | 489-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | YD000375 | Yard | 489-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | YD000375 | Yard | 489-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | ST000379 | Structure | 489-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | ST000379 | Structure | 489-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | ST000379 | Structure | 489-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | ST000379 | Structure | 489-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | ST000379 | Structure | 489-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | ST000379 | Structure | 489-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | ST000379 | Structure | 489-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | ST000379 | Structure | 489-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | ST000379 | Structure | 489-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | ST000379 | Structure | 489-Structure | Structure Patrol Inspection | General Comments | | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | ST000379 | Structure | 489-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | ST000379 | Structure | 489-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LTCC000020 | LTCControl | LY-TRANS 2 | LTC Control Insp | General Comments | ok | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LTCC000020 | LTCControl | LY-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | LTCMechanism | MC-TRANS 9 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | LTCMechanism | MC-TRANS 9 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | LTCMechanism | MC-TRANS 9 | LTC Counter Readings | General Comments | | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | LTCMechanism | MC-TRANS 9 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | LTCMechanism | MC-TRANS 9 | LTC Counter Readings | LTC As Found Counter | 239985 | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | ST000379 | Structure | 489-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | ST000379 | Structure | 489-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | ST000379 | Structure | 489-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | ST000379 | Structure | 489-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | ST000379 | Structure | 489-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | ST000379 | Structure | 489-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | ST000379 | Structure | 489-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | ST000379 | Structure | 489-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | BAT001401 | Battery | 610-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | BAT001401 | Battery | 610-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1194 | Regulator | 689-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1194 | Regulator | 689-1 A | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1194 | Regulator | 689-1 A | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | ST000083 | Structure | 644-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | ST000083 | Structure | 644-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | ST000083 | Structure | 644-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | BAT001401 | Battery | 610-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 28.2 | VDC |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | RC000435 | RecloserElectronic | 622-1416 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | RC000435 | RecloserElectronic | 622-1416 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Readings | Operations This Read Vac | 1 | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | RC000435 | RecloserElectronic | 622-1416 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | RC000435 | RecloserElectronic | 622-1416 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | RC000435 | RecloserElectronic | 622-1416 | Recloser Electronic Patrol Inspection | General Comments | | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | RC000435 | RecloserElectronic | 622-1416 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | RC000435 | RecloserElectronic | 622-1416 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | RC000435 | RecloserElectronic | 622-1416 | Recloser Electronic Patrol Inspection | Operations Counter | 211 | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | RC000435 | RecloserElectronic | 622-1416 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | RC000435 | RecloserElectronic | 622-1416 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | RC000435 | RecloserElectronic | 622-1416 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Readings | Operations Counter AL | 159 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Readings | Operations Counter AF | 159 | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | ST000083 | Structure | 644-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1194 | Regulator | 689-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Readings | Maintenance Operations | 1 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | FE000369 | Fence | 489-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | FE000369 | Fence | 489-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | FE000369 | Fence | 489-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | FE000369 | Fence | 489-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | FE000369 | Fence | 489-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | FE000369 | Fence | 489-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | FE000369 | Fence | 489-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | FE000369 | Fence | 489-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | FE000369 | Fence | 489-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | FE000369 | Fence | 489-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | FE000369 | Fence | 489-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | FE000369 | Fence | 489-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | FE000369 | Fence | 489-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | FE000369 | Fence | 489-Fence | Fence Patrol Inspection | General Comments | | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | FE000369 | Fence | 489-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | FE000369 | Fence | 489-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | YD000375 | Yard | 489-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Patrol Inspection | General Comments | | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Readings | Follow-up Action Required? | n | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Readings | Fault Operations Ground | 0 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | YD000375 | Yard | 489-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | YD000375 | Yard | 489-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | YD000375 | Yard | 489-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | YD000375 | Yard | 489-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | LTCMechanism | MC-TRANS 9 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | FE000075 | Fence | 644-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | FE000075 | Fence | 644-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | FE000075 | Fence | 644-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | FE000075 | Fence | 644-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | FE000075 | Fence | 644-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | FE000075 | Fence | 644-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | FE000075 | Fence | 644-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | FE000075 | Fence | 644-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | n | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1194 | Regulator | 689-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1194 | Regulator | 689-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1194 | Regulator | 689-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1194 | Regulator | 689-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1194 | Regulator | 689-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1194 | Regulator | 689-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1194 | Regulator | 689-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1194 | Regulator | 689-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1194 | Regulator | 689-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1194 | Regulator | 689-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1194 | Regulator | 689-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1194 | Regulator | 689-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000094 | Regulator | 004-5 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000094 | Regulator | 004-5 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000094 | Regulator | 004-5 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000094 | Regulator | 004-5 B | Regulator Patrol Inspection | Regulator As Left Counter | 20586 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | FE000245 | Fence | 610-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | FE000245 | Fence | 610-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | FE000245 | Fence | 610-Fence | Fence Patrol Inspection | General Comments | | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | FE000245 | Fence | 610-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | FE000245 | Fence | 610-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | FE000245 | Fence | 610-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | FE000245 | Fence | 610-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | FE000245 | Fence | 610-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | FE000245 | Fence | 610-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | FE000245 | Fence | 610-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | FE000245 | Fence | 610-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | FE000245 | Fence | 610-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | FE000245 | Fence | 610-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | FE000245 | Fence | 610-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | FE000245 | Fence | 610-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | FE000245 | Fence | 610-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000094 | Regulator | 004-5 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.2 | volts |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000094 | Regulator | 004-5 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000094 | Regulator | 004-5 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000094 | Regulator | 004-5 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000094 | Regulator | 004-5 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000094 | Regulator | 004-5 B | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000094 | Regulator | 004-5 B | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000094 | Regulator | 004-5 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000094 | Regulator | 004-5 B | Regulator Patrol Inspection | General Comments | | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000094 | Regulator | 004-5 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000094 | Regulator | 004-5 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000094 | Regulator | 004-5 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000094 | Regulator | 004-5 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000094 | Regulator | 004-5 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000094 | Regulator | 004-5 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000094 | Regulator | 004-5 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000094 | Regulator | 004-5 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000094 | Regulator | 004-5 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | RG000094 | Regulator | 004-5 B | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | BAT001401 | Battery | 610-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 29.4 | VDC |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | BAT001401 | Battery | 610-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | BAT001401 | Battery | 610-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | BAT001401 | Battery | 610-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | BAT001401 | Battery | 610-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | BAT001401 | Battery | 610-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | BAT001401 | Battery | 610-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | BAT001401 | Battery | 610-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | BAT001401 | Battery | 610-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 40 | °F |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | BAT001401 | Battery | 610-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | ST000083 | Structure | 644-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | ST000083 | Structure | 644-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | ST000083 | Structure | 644-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | ST000083 | Structure | 644-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | ST000083 | Structure | 644-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | ST000083 | Structure | 644-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | ST000083 | Structure | 644-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Readings | Unknown Operations | 1 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Readings | Switching Operations | 0 | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | ST000379 | Structure | 489-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | ST000379 | Structure | 489-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | ST000083 | Structure | 644-Structure | Structure Patrol Inspection | General Comments | | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | ST000083 | Structure | 644-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | ST000083 | Structure | 644-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | ST000083 | Structure | 644-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | ST000083 | Structure | 644-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | ST000083 | Structure | 644-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | ST000083 | Structure | 644-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | ST000083 | Structure | 644-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | ST000083 | Structure | 644-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | YD000075 | Yard | 644-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | YD000075 | Yard | 644-Yard | Yard Patrol Inspection | General Comments | | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | YD000075 | Yard | 644-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | YD000075 | Yard | 644-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | n | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | YD000075 | Yard | 644-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | n | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | YD000075 | Yard | 644-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | n | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | YD000075 | Yard | 644-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Fair | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | YD000075 | Yard | 644-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | YD000075 | Yard | 644-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | YD000075 | Yard | 644-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | YD000075 | Yard | 644-Yard | Yard Patrol Inspection | Ambient Temp | 40 | °F |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | FE000075 | Fence | 644-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | FE000075 | Fence | 644-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | FE000075 | Fence | 644-Fence | Fence Patrol Inspection | General Comments | | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | FE000075 | Fence | 644-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | FE000075 | Fence | 644-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | LTCMechanism | MC-TRANS 9 | LTC Counter Readings | LTC As Left Counter | 239985 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | LTCMechanism | MC-TRANS 9 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | LTCMechanism | MC-TRANS 9 | LTC Counter Readings | LTC Current Tap Position | 10L | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | LTCMechanism | MC-TRANS 9 | LTC Counter Readings | LTC Max Tap Position | 6L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | LTCMechanism | MC-TRANS 9 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | LTCMechanism | MC-TRANS 9 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | LTCMechanism | MC-TRANS 9 | LTC Counter Readings | LTC Operations Since Last Insp | 2 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | LTCMechanism | MC-TRANS 9 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | LTCMechanism | MC-TRANS 9 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | FE000075 | Fence | 644-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | FE000075 | Fence | 644-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | FE000075 | Fence | 644-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | LTCMechanism | MC-TRANS 9 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Readings | 9 Month Operations | 1 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1195 | Regulator | 689-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1195 | Regulator | 689-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0560 | BreakerVacuum | LY-1163 | VCB Patrol Inspection | General Comments | | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0560 | BreakerVacuum | LY-1163 | VCB Readings | General Comments | | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0560 | BreakerVacuum | LY-1163 | VCB Readings | Maintenance Operations | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0560 | BreakerVacuum | LY-1163 | VCB Readings | Operations Counter AF | 666 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0560 | BreakerVacuum | LY-1163 | VCB Readings | Operations Counter AL | 666 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0560 | BreakerVacuum | LY-1163 | VCB Readings | Operations This Read Vac | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0560 | BreakerVacuum | LY-1163 | VCB Readings | Switching Operations | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0560 | BreakerVacuum | LY-1163 | VCB Readings | Unknown Operations | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Readings | X3 Winding Temp Present | 40 | °C |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Readings | X3 Winding Temp Max | 45 | °C |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Readings | X2 Winding Temp Present | 45 | °C |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1195 | Regulator | 689-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1195 | Regulator | 689-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1195 | Regulator | 689-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | ST000251 | Structure | 610-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | ST000251 | Structure | 610-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | ST000251 | Structure | 610-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | ST000251 | Structure | 610-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | ST000251 | Structure | 610-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | ST000251 | Structure | 610-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0971 | Regulator | 489-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0971 | Regulator | 489-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0971 | Regulator | 489-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0971 | Regulator | 489-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 17077 | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0971 | Regulator | 489-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0971 | Regulator | 489-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0971 | Regulator | 489-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0971 | Regulator | 489-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0971 | Regulator | 489-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0971 | Regulator | 489-1 A | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0971 | Regulator | 489-1 A | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0971 | Regulator | 489-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0971 | Regulator | 489-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0971 | Regulator | 489-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0971 | Regulator | 489-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0971 | Regulator | 489-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0971 | Regulator | 489-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0971 | Regulator | 489-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0971 | Regulator | 489-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0971 | Regulator | 489-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0971 | Regulator | 489-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0971 | Regulator | 489-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0971 | Regulator | 489-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | ST000251 | Structure | 610-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | ST000251 | Structure | 610-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | ST000251 | Structure | 610-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | ST000251 | Structure | 610-Structure | Structure Patrol Inspection | General Comments | | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | ST000251 | Structure | 610-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | ST000251 | Structure | 610-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | ST000251 | Structure | 610-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | ST000251 | Structure | 610-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | ST000251 | Structure | 610-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | ST000251 | Structure | 610-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | ST000251 | Structure | 610-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | ST000251 | Structure | 610-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0267 | NonLTC | 489-1 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0267 | NonLTC | 489-1 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0267 | NonLTC | 489-1 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0560 | BreakerVacuum | LY-1163 | VCB Readings | 9 Month Operations | 3 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0560 | BreakerVacuum | LY-1163 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0560 | BreakerVacuum | LY-1163 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0560 | BreakerVacuum | LY-1163 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0560 | BreakerVacuum | LY-1163 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | C0392 | NonLTC | 644-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0560 | BreakerVacuum | LY-1163 | VCB Readings | Amps A Ø | 162.0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0560 | BreakerVacuum | LY-1163 | VCB Readings | Amps B Ø | 181.0 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Readings | Amps C Ø | 110.0 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Readings | Amps B Ø | 154.0 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1195 | Regulator | 689-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1195 | Regulator | 689-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1195 | Regulator | 689-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1195 | Regulator | 689-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1195 | Regulator | 689-1 B | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1195 | Regulator | 689-1 B | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1195 | Regulator | 689-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | C0392 | NonLTC | 644-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | C0392 | NonLTC | 644-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | C0392 | NonLTC | 644-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | C0392 | NonLTC | 644-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | C0392 | NonLTC | 644-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | C0392 | NonLTC | 644-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Crumbling | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | C0392 | NonLTC | 644-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | C0392 | NonLTC | 644-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | C0392 | NonLTC | 644-1 | NonLTC Transformer Readings | General Comments | | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | C0392 | NonLTC | 644-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | C0392 | NonLTC | 644-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | C0392 | NonLTC | 644-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3.00 | kw |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | C0392 | NonLTC | 644-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | C0392 | NonLTC | 644-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | C0392 | NonLTC | 644-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | C0392 | NonLTC | 644-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | C0392 | NonLTC | 644-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Adequate | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | C0392 | NonLTC | 644-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 100 | |
| 2/10/2023 9:51 | Distribution | Chunklick Branch Quarterly Inspection | C0392 | NonLTC | 644-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .0300 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0560 | BreakerVacuum | LY-1163 | VCB Readings | Amps C Ø | 190.0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0560 | BreakerVacuum | LY-1163 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0560 | BreakerVacuum | LY-1163 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0560 | BreakerVacuum | LY-1163 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0560 | BreakerVacuum | LY-1163 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0560 | BreakerVacuum | LY-1163 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0560 | BreakerVacuum | LY-1163 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0560 | BreakerVacuum | LY-1163 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0560 | BreakerVacuum | LY-1163 | VCB Readings | Fault Operations Ground | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | PF000245 | PowerFuse | MC-STA SER NO 9 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | PF000245 | PowerFuse | MC-STA SER NO 9 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | PF000245 | PowerFuse | MC-STA SER NO 9 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Readings | Amps A Ø | 119.0 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000455 | BreakerVacuum | 689-1407 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0560 | BreakerVacuum | LY-1163 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0560 | BreakerVacuum | LY-1163 | VCB Readings | Follow-up Action Required? | n | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Readings | Unknown Operations | 0 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Readings | Switching Operations | 0 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BK000454 | BreakerVacuum | 689-1408 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | YD000245 | Yard | 610-Yard | Yard Patrol Inspection | General Comments | | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | YD000245 | Yard | 610-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | YD000245 | Yard | 610-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | YD000245 | Yard | 610-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | W0272 | NonLTC | 689-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | W0272 | NonLTC | 689-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -1.5 | psi |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | W0272 | NonLTC | 689-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | W0272 | NonLTC | 689-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | W0272 | NonLTC | 689-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | W0272 | NonLTC | 689-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | W0272 | NonLTC | 689-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1194 | Regulator | 689-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 40 | °C |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 80 | °C |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 155.00 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 80 | °C |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | needs nitrogen | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | WithLTC | LY-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | RC000435 | RecloserElectronic | 622-1416 | Recloser Electronic Patrol Inspection | Amps A Ø | 17.0 | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | RC000435 | RecloserElectronic | 622-1416 | Recloser Electronic Patrol Inspection | Amps B Ø | 18.0 | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | RC000435 | RecloserElectronic | 622-1416 | Recloser Electronic Patrol Inspection | Amps C Ø | 18.0 | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | RC000435 | RecloserElectronic | 622-1416 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | RC000435 | RecloserElectronic | 622-1416 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | RC000435 | RecloserElectronic | 622-1416 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | RC000435 | RecloserElectronic | 622-1416 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | RC000435 | RecloserElectronic | 622-1416 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | RC000435 | RecloserElectronic | 622-1416 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | ST000251 | Structure | 610-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | ST000251 | Structure | 610-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | ST000251 | Structure | 610-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | ST000251 | Structure | 610-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1195 | Regulator | 689-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1195 | Regulator | 689-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1195 | Regulator | 689-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1195 | Regulator | 689-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1195 | Regulator | 689-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1195 | Regulator | 689-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1194 | Regulator | 689-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Readings | X2 Winding Temp Max | 40 | °C |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Readings | X1 Winding Temp Present | 50 | °C |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | W0272 | NonLTC | 689-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | W0272 | NonLTC | 689-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | W0272 | NonLTC | 689-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | YD000245 | Yard | 610-Yard | Yard Patrol Inspection | Ambient Temp | 38 | °F |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | YD000245 | Yard | 610-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Readings | General Comments | | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LT0132 | WithLTC | MC-TRANS 9 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | YD000245 | Yard | 610-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | YD000245 | Yard | 610-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | YD000245 | Yard | 610-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | YD000245 | Yard | 610-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | YD000245 | Yard | 610-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | YD000245 | Yard | 610-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | YD000245 | Yard | 610-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | YD000245 | Yard | 610-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | ST000223 | Structure | 622-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | ST000223 | Structure | 622-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | YD000217 | Yard | 622-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | YD000217 | Yard | 622-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | YD000217 | Yard | 622-Yard | Yard Patrol Inspection | General Comments | | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | YD000217 | Yard | 622-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | SWG000108 | Switchgear | MC-Swgr Sec 9 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | SWG000108 | Switchgear | MC-Swgr Sec 9 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0269 | NonLTC | 489-1 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0559 | BreakerAirMagnetic | LY-1112 | AMCB Readings | Switching Operations | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0559 | BreakerAirMagnetic | LY-1112 | AMCB Readings | Unknown Operations | 0 | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | WX0257 | RecloserElectronic | 489-0729 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | WX0257 | RecloserElectronic | 489-0729 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | WX0257 | RecloserElectronic | 489-0729 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | WX0257 | RecloserElectronic | 489-0729 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | WX0257 | RecloserElectronic | 489-0729 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | n | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | WX0257 | RecloserElectronic | 489-0729 | Recloser Electronic Patrol Inspection | Amps C Ø | 10.0 | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | WX0257 | RecloserElectronic | 489-0729 | Recloser Electronic Patrol Inspection | Amps B Ø | 10.0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | LTCMechanism | LY-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | LTCMechanism | LY-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | ST000223 | Structure | 622-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | ST000223 | Structure | 622-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | ST000223 | Structure | 622-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | ST000223 | Structure | 622-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | ST000223 | Structure | 622-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | LTCMechanism | LY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | LTCMechanism | LY-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 557 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0558 | BreakerAirMagnetic | LY-1111 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0558 | BreakerAirMagnetic | LY-1111 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0558 | BreakerAirMagnetic | LY-1111 | AMCB Readings | 9 Months Operations | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0558 | BreakerAirMagnetic | LY-1111 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | LTCMechanism | LY-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | LTCMechanism | LY-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | LTCMechanism | LY-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1196 | Regulator | 689-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1196 | Regulator | 689-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Readings | Totalizer Meter Reading | .5466 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 6000 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | LTCMechanism | LY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | LTCMechanism | LY-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 15458 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | LTCMechanism | LY-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 15458 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | LTCMechanism | LY-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | LTCMechanism | LY-TRANS 2 | LTC Counter Readings | General Comments | | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | LTCMechanism | LY-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LT0105 | LTCMechanism | LY-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Readings | LTC Totalizer Reading | 3279.60 | kw |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Readings | General Comments | | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1196 | Regulator | 689-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1196 | Regulator | 689-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 89603 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1196 | Regulator | 689-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1196 | Regulator | 689-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1196 | Regulator | 689-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1196 | Regulator | 689-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1196 | Regulator | 689-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0244 | NonLTC | 489-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | ST000331 | Structure | 689-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | ST000331 | Structure | 689-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Patrol Inspection | General Comments | | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | ST000331 | Structure | 689-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | BK000563 | BreakerVacuum | LY-LS 12KV BUS TIE | VCB Readings | Operations Counter AL | 156 | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0559 | BreakerAirMagnetic | LY-1112 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0558 | BreakerAirMagnetic | LY-1111 | AMCB Readings | Amps B Ø | 110.0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0558 | BreakerAirMagnetic | LY-1111 | AMCB Readings | Amps A Ø | 100.0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0558 | BreakerAirMagnetic | LY-1111 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0559 | BreakerAirMagnetic | LY-1112 | AMCB Readings | 9 Months Operations | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0559 | BreakerAirMagnetic | LY-1112 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | BK000563 | BreakerVacuum | LY-LS 12KV BUS TIE | VCB Readings | Operations This Read Vac | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0559 | BreakerAirMagnetic | LY-1112 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0559 | BreakerAirMagnetic | LY-1112 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0559 | BreakerAirMagnetic | LY-1112 | AMCB Readings | Amps A Ø | 100.0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | BK000563 | BreakerVacuum | LY-LS 12KV BUS TIE | VCB Readings | Switching Operations | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | BK000563 | BreakerVacuum | LY-LS 12KV BUS TIE | VCB Readings | Unknown Operations | 0 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | ST000331 | Structure | 689-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | ST000331 | Structure | 689-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | ST000331 | Structure | 689-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | ST000331 | Structure | 689-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | ST000331 | Structure | 689-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0559 | BreakerAirMagnetic | LY-1112 | AMCB Readings | Amps B Ø | 230.0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0559 | BreakerAirMagnetic | LY-1112 | AMCB Readings | Amps C Ø | 100.0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0559 | BreakerAirMagnetic | LY-1112 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0559 | BreakerAirMagnetic | LY-1112 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0559 | BreakerAirMagnetic | LY-1112 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | Seeping | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0559 | BreakerAirMagnetic | LY-1112 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | WX0257 | RecloserElectronic | 489-0729 | Recloser Electronic Patrol Inspection | General Comments | | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | WX0257 | RecloserElectronic | 489-0729 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | WX0257 | RecloserElectronic | 489-0729 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0559 | BreakerAirMagnetic | LY-1112 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0559 | BreakerAirMagnetic | LY-1112 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0559 | BreakerAirMagnetic | LY-1112 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0559 | BreakerAirMagnetic | LY-1112 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0559 | BreakerAirMagnetic | LY-1112 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0559 | BreakerAirMagnetic | LY-1112 | AMCB Readings | Follow-up Action Required? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0559 | BreakerAirMagnetic | LY-1112 | AMCB Patrol Inspection | General Comments | | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0559 | BreakerAirMagnetic | LY-1112 | AMCB Readings | General Comments | Amp gauge on B phase isnt right | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0559 | BreakerAirMagnetic | LY-1112 | AMCB Readings | Maintenance Operations | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0559 | BreakerAirMagnetic | LY-1112 | AMCB Readings | Operations Counter AF | 665 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0559 | BreakerAirMagnetic | LY-1112 | AMCB Readings | Operations Counter AL | 665 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0559 | BreakerAirMagnetic | LY-1112 | AMCB Readings | Operations This Read AM | 0 | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | WX0257 | RecloserElectronic | 489-0729 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | WX0257 | RecloserElectronic | 489-0729 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | WX0257 | RecloserElectronic | 489-0729 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | ST000223 | Structure | 622-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0969 | Regulator | 489-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0969 | Regulator | 489-1 C | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0969 | Regulator | 489-1 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0969 | Regulator | 489-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0969 | Regulator | 489-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0969 | Regulator | 489-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0969 | Regulator | 489-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0969 | Regulator | 489-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0269 | NonLTC | 489-1 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0269 | NonLTC | 489-1 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0269 | NonLTC | 489-1 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0269 | NonLTC | 489-1 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0269 | NonLTC | 489-1 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0269 | NonLTC | 489-1 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0269 | NonLTC | 489-1 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0269 | NonLTC | 489-1 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0269 | NonLTC | 489-1 C | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0269 | NonLTC | 489-1 C | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0269 | NonLTC | 489-1 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0269 | NonLTC | 489-1 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0269 | NonLTC | 489-1 C | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0969 | Regulator | 489-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Readings | Totalizer Meter Reading | .7890 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Readings | Top Oil Temperature Present | 42 | °C |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Readings | Top Oil Temperature Max | 48 | °C |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0969 | Regulator | 489-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0969 | Regulator | 489-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0969 | Regulator | 489-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0969 | Regulator | 489-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0969 | Regulator | 489-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0969 | Regulator | 489-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1196 | Regulator | 689-1 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1196 | Regulator | 689-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 2524.80 | kw |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1196 | Regulator | 689-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1196 | Regulator | 689-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1196 | Regulator | 689-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1196 | Regulator | 689-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Readings | General Comments | | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | YD000217 | Yard | 622-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | YD000217 | Yard | 622-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | YD000217 | Yard | 622-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1196 | Regulator | 689-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1196 | Regulator | 689-1 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1196 | Regulator | 689-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1196 | Regulator | 689-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1196 | Regulator | 689-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1196 | Regulator | 689-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1196 | Regulator | 689-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | R1196 | Regulator | 689-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | ST000331 | Structure | 689-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | ST000331 | Structure | 689-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | ST000331 | Structure | 689-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | ST000331 | Structure | 689-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | ST000331 | Structure | 689-Structure | Structure Patrol Inspection | General Comments | | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | ST000331 | Structure | 689-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | ST000331 | Structure | 689-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | ST000331 | Structure | 689-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | ST000331 | Structure | 689-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | ST000331 | Structure | 689-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | ST000331 | Structure | 689-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | ST000331 | Structure | 689-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | ST000331 | Structure | 689-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | ST000331 | Structure | 689-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0269 | NonLTC | 489-1 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0269 | NonLTC | 489-1 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0269 | NonLTC | 489-1 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0269 | NonLTC | 489-1 C | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0269 | NonLTC | 489-1 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Readings | Oil Temp Max | 43 | °C |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | C0431 | WithLTC | 610-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | WX0257 | RecloserElectronic | 489-0729 | Recloser Electronic Patrol Inspection | Amps A Ø | 10.0 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | W0217 | NonLTC | 004-5 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0969 | Regulator | 489-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 244.44 | kw |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0969 | Regulator | 489-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0969 | Regulator | 489-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0969 | Regulator | 489-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 48444 | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0969 | Regulator | 489-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0969 | Regulator | 489-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Readings | General Comments | oil leaking from level siteglass | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Patrol Inspection | General Comments | has slow leak under oil level guage | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0969 | Regulator | 489-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R0969 | Regulator | 489-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 B | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | WX0257 | RecloserElectronic | 489-0729 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | WX0257 | RecloserElectronic | 489-0729 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | WX0257 | RecloserElectronic | 489-0729 | Recloser Electronic Patrol Inspection | Operations Counter | 9 | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 B | NonLTC Transformer Readings | General Comments | | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 B | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | PF000246 | PowerFuse | MC-12KV TR 9 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | PF000246 | PowerFuse | MC-12KV TR 9 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LB0659 | BreakerAirMagnetic | MC-Offline-Distribution | AMCB Readings | Unknown Operations | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LB0659 | BreakerAirMagnetic | MC-Offline-Distribution | AMCB Readings | Switching Operations | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LB0659 | BreakerAirMagnetic | MC-Offline-Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LB0659 | BreakerAirMagnetic | MC-Offline-Distribution | AMCB Readings | Operations Counter AL | 188 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LB0659 | BreakerAirMagnetic | MC-Offline-Distribution | AMCB Readings | Operations Counter AF | 188 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LB0659 | BreakerAirMagnetic | MC-Offline-Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LB0659 | BreakerAirMagnetic | MC-Offline-Distribution | AMCB Readings | General Comments | | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LB0659 | BreakerAirMagnetic | MC-Offline-Distribution | AMCB Patrol Inspection | General Comments | | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LB0659 | BreakerAirMagnetic | MC-Offline-Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LB0659 | BreakerAirMagnetic | MC-Offline-Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LB0659 | BreakerAirMagnetic | MC-Offline-Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LB0659 | BreakerAirMagnetic | MC-Offline-Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LB0659 | BreakerAirMagnetic | MC-Offline-Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | PF000246 | PowerFuse | MC-12KV TR 9 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | WX0257 | RecloserElectronic | 489-0729 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 95.00 | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | FE000216 | Fence | 622-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R1276 | Regulator | 489-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R1276 | Regulator | 489-1 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R1276 | Regulator | 489-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R1276 | Regulator | 489-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R1276 | Regulator | 489-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R1276 | Regulator | 489-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R1276 | Regulator | 489-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | YD000217 | Yard | 622-Yard | Yard Patrol Inspection | Ambient Temp | 41 | °F |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0336 | NonLTC | 622-1 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 B | NonLTC Transformer Readings | Oil Temp Max | 46 | °C |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 B | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R1276 | Regulator | 489-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R1276 | Regulator | 489-1 B | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R1276 | Regulator | 489-1 B | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | ST000223 | Structure | 622-Structure | Structure Patrol Inspection | General Comments | Whole station needs wildlife protection. | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R1276 | Regulator | 489-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R1276 | Regulator | 489-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R1276 | Regulator | 489-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R1276 | Regulator | 489-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0336 | NonLTC | 622-1 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Readings | Totalizer Meter Reading | .0582 | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0336 | NonLTC | 622-1 C | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0336 | NonLTC | 622-1 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0336 | NonLTC | 622-1 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0336 | NonLTC | 622-1 C | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0336 | NonLTC | 622-1 C | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | WX0257 | RecloserElectronic | 489-0729 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LB0659 | BreakerAirMagnetic | MC-Offline-Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LB0659 | BreakerAirMagnetic | MC-Offline-Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LB0659 | BreakerAirMagnetic | MC-Offline-Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | ST000223 | Structure | 622-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | SWG000108 | Switchgear | MC-Swgr Sec 9 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | SWG000108 | Switchgear | MC-Swgr Sec 9 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | SWG000108 | Switchgear | MC-Swgr Sec 9 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | SWG000108 | Switchgear | MC-Swgr Sec 9 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | SWG000108 | Switchgear | MC-Swgr Sec 9 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | ST000223 | Structure | 622-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | ST000223 | Structure | 622-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | ST000223 | Structure | 622-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | ST000223 | Structure | 622-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | SWG000108 | Switchgear | MC-Swgr Sec 9 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | SWG000108 | Switchgear | MC-Swgr Sec 9 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | SWG000108 | Switchgear | MC-Swgr Sec 9 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | SWG000108 | Switchgear | MC-Swgr Sec 9 | Switchgear Patrol Inspection | General Comments | | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | SWG000108 | Switchgear | MC-Swgr Sec 9 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | SWG000108 | Switchgear | MC-Swgr Sec 9 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | SWG000108 | Switchgear | MC-Swgr Sec 9 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | SWG000108 | Switchgear | MC-Swgr Sec 9 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | SWG000108 | Switchgear | MC-Swgr Sec 9 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | SWG000108 | Switchgear | MC-Swgr Sec 9 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | SWG000108 | Switchgear | MC-Swgr Sec 9 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | ST000223 | Structure | 622-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | ST000223 | Structure | 622-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | ST000223 | Structure | 622-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | ST000223 | Structure | 622-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | ST000223 | Structure | 622-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | YD000217 | Yard | 622-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | FE000216 | Fence | 622-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | FE000216 | Fence | 622-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | FE000216 | Fence | 622-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | FE000216 | Fence | 622-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | FE000216 | Fence | 622-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | SWG000047 | Switchgear | LY-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | SWG000047 | Switchgear | LY-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | SWG000047 | Switchgear | LY-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | SWG000047 | Switchgear | LY-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | FE000216 | Fence | 622-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Readings | Amps C Ø | 10.0 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Readings | Amps B Ø | 140.0 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Readings | Amps A Ø | 80.0 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/10/2023 14:11 | Distribution | Morganfield Quarterly Inspection | WB0155 | BreakerVacuum | 004-1750 | VCB Readings | 9 Month Operations | 2 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | BK000563 | BreakerVacuum | LY-LS 12KV BUS TIE | VCB Readings | Fault Operations C Ø | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | BK000563 | BreakerVacuum | LY-LS 12KV BUS TIE | VCB Readings | Fault Operations Ground | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | BK000563 | BreakerVacuum | LY-LS 12KV BUS TIE | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | BK000563 | BreakerVacuum | LY-LS 12KV BUS TIE | VCB Readings | Follow-up Action Required? | n | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | FE000216 | Fence | 622-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | FE000216 | Fence | 622-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | BK000563 | BreakerVacuum | LY-LS 12KV BUS TIE | VCB Patrol Inspection | General Comments | | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R1276 | Regulator | 489-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R1276 | Regulator | 489-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R1276 | Regulator | 489-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R1276 | Regulator | 489-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | FE000216 | Fence | 622-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | FE000216 | Fence | 622-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | FE000216 | Fence | 622-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | FE000216 | Fence | 622-Fence | Fence Patrol Inspection | General Comments | | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | FE000216 | Fence | 622-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 B | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0336 | NonLTC | 622-1 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0336 | NonLTC | 622-1 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LB0659 | BreakerAirMagnetic | MC-Offline-Distribution | AMCB Readings | Amps B Ø | 0.0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LB0659 | BreakerAirMagnetic | MC-Offline-Distribution | AMCB Readings | Amps A Ø | 0.0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LB0659 | BreakerAirMagnetic | MC-Offline-Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LB0659 | BreakerAirMagnetic | MC-Offline-Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | ST000223 | Structure | 622-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LB0659 | BreakerAirMagnetic | MC-Offline-Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LB0659 | BreakerAirMagnetic | MC-Offline-Distribution | AMCB Readings | 9 Months Operations | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LB0659 | BreakerAirMagnetic | MC-Offline-Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | SWG000047 | Switchgear | LY-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | YD000217 | Yard | 622-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | YD000217 | Yard | 622-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | YD000217 | Yard | 622-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | YD000217 | Yard | 622-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0558 | BreakerAirMagnetic | LY-1111 | AMCB Readings | Unknown Operations | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0558 | BreakerAirMagnetic | LY-1111 | AMCB Readings | Switching Operations | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0558 | BreakerAirMagnetic | LY-1111 | AMCB Readings | Operations This Read AM | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0558 | BreakerAirMagnetic | LY-1111 | AMCB Readings | Operations Counter AL | 58 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0558 | BreakerAirMagnetic | LY-1111 | AMCB Readings | Operations Counter AF | 58 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | BK000563 | BreakerVacuum | LY-LS 12KV BUS TIE | VCB Readings | Operations Counter AF | 156 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0558 | BreakerAirMagnetic | LY-1111 | AMCB Readings | Maintenance Operations | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0558 | BreakerAirMagnetic | LY-1111 | AMCB Readings | General Comments | | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0558 | BreakerAirMagnetic | LY-1111 | AMCB Patrol Inspection | General Comments | | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0558 | BreakerAirMagnetic | LY-1111 | AMCB Readings | Follow-up Action Required? | n | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0558 | BreakerAirMagnetic | LY-1111 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0558 | BreakerAirMagnetic | LY-1111 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BAT001665 | Battery | 689-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BAT001665 | Battery | 689-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 42 | °F |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BAT001665 | Battery | 689-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BAT001665 | Battery | 689-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BAT001665 | Battery | 689-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BAT001665 | Battery | 689-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BAT001665 | Battery | 689-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BAT001665 | Battery | 689-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BAT001665 | Battery | 689-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0558 | BreakerAirMagnetic | LY-1111 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0558 | BreakerAirMagnetic | LY-1111 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0558 | BreakerAirMagnetic | LY-1111 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0558 | BreakerAirMagnetic | LY-1111 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BAT001665 | Battery | 689-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 28.0 | VDC |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0558 | BreakerAirMagnetic | LY-1111 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0558 | BreakerAirMagnetic | LY-1111 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0558 | BreakerAirMagnetic | LY-1111 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | LB0558 | BreakerAirMagnetic | LY-1111 | AMCB Readings | Amps C Ø | 100.0 | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 B | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0335 | NonLTC | 622-1 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BAT001665 | Battery | 689-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.8 | VDC |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BAT001665 | Battery | 689-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/10/2023 14:08 | Distribution | Clay KU Quarterly Inspection | BAT001665 | Battery | 689-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0244 | NonLTC | 489-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0244 | NonLTC | 489-1 A | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0244 | NonLTC | 489-1 A | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0244 | NonLTC | 489-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0244 | NonLTC | 489-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0244 | NonLTC | 489-1 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0244 | NonLTC | 489-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0244 | NonLTC | 489-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 95.00 | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0157 | BreakerVacuum | 610-0747 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0244 | NonLTC | 489-1 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0244 | NonLTC | 489-1 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0244 | NonLTC | 489-1 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0244 | NonLTC | 489-1 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0244 | NonLTC | 489-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0244 | NonLTC | 489-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 4200 | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | ST000223 | Structure | 622-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | ST000223 | Structure | 622-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0337 | NonLTC | 622-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Patrol Inspection | General Comments | | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LB0659 | BreakerAirMagnetic | MC-Offline-Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LB0659 | BreakerAirMagnetic | MC-Offline-Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | SWG000047 | Switchgear | LY-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | SWG000047 | Switchgear | LY-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | SWG000047 | Switchgear | LY-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | LB0659 | BreakerAirMagnetic | MC-Offline-Distribution | AMCB Readings | Amps C Ø | 0.0 | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | SWG000047 | Switchgear | LY-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | SWG000047 | Switchgear | LY-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | SWG000047 | Switchgear | LY-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | heater Thermostat not picking up | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | SWG000047 | Switchgear | LY-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | n | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | SWG000047 | Switchgear | LY-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | SWG000047 | Switchgear | LY-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | SWG000047 | Switchgear | LY-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | SWG000047 | Switchgear | LY-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | SWG000047 | Switchgear | LY-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | SWG000047 | Switchgear | LY-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/15/2023 7:25 | Distribution | Morganfield City Quarterly Inspection | K0158 | BreakerVacuum | 610-0746 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0244 | NonLTC | 489-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0244 | NonLTC | 489-1 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | B0244 | NonLTC | 489-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0336 | NonLTC | 622-1 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0336 | NonLTC | 622-1 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0336 | NonLTC | 622-1 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R1276 | Regulator | 489-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R1276 | Regulator | 489-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 11417 | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R1276 | Regulator | 489-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R1276 | Regulator | 489-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/10/2023 15:29 | Distribution | Markland Dam Quarterly Inspection | R1276 | Regulator | 489-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0336 | NonLTC | 622-1 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0336 | NonLTC | 622-1 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0336 | NonLTC | 622-1 C | NonLTC Transformer Readings | General Comments | | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0336 | NonLTC | 622-1 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | PF000197 | PowerFuse | LY-12KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | PF000197 | PowerFuse | LY-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | PF000197 | PowerFuse | LY-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | PF000198 | PowerFuse | LY-STA SER NO 2 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | PF000198 | PowerFuse | LY-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | PF000198 | PowerFuse | LY-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0336 | NonLTC | 622-1 C | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0336 | NonLTC | 622-1 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0336 | NonLTC | 622-1 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 95.00 | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0336 | NonLTC | 622-1 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0336 | NonLTC | 622-1 C | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0336 | NonLTC | 622-1 C | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0336 | NonLTC | 622-1 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0336 | NonLTC | 622-1 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | BK000563 | BreakerVacuum | LY-LS 12KV BUS TIE | VCB Readings | General Comments | | |
| 2/10/2023 8:58 | Distribution | Lyndon Quarterly Inspection | BK000563 | BreakerVacuum | LY-LS 12KV BUS TIE | VCB Readings | Maintenance Operations | 0 | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0336 | NonLTC | 622-1 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0336 | NonLTC | 622-1 C | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/10/2023 11:26 | Distribution | Webcoal 2 Quarterly Inspection | W0336 | NonLTC | 622-1 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0472 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | 9 Month Ops New | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0472 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | 9 Months Operations | 1 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0472 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0472 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0472 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0472 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Amps A Ø | 120.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0472 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Amps B Ø | 118.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0472 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Amps C Ø | 117.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0472 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Fault Adjusted Amps A Phase AM | 8.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0472 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0472 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0472 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0472 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Switching Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0472 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Operations This Read AM | 1 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0472 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Operations Counter AL | 67 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0472 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Fault Operations A Ø | 1 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0472 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0472 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0472 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0472 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0472 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | General Comments | A Phase IOC | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0472 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0472 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Readings | Operations Counter AF | 67 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0472 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0472 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0472 | BreakerAirMagnetic | S-Offline Distribution Breakers | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | LTCMechanism | 358-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | ST000469 | Structure | 540-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | ST000469 | Structure | 540-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | ST000469 | Structure | 540-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | LTCMechanism | 358-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | YD000119 | Yard | 379-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | YD000119 | Yard | 379-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | LTCMechanism | 358-1 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | LTCMechanism | 358-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | LTCMechanism | 358-1 | LTC Counter Readings | LTC Operations Since Last Insp | 560 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | LTCMechanism | 358-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | LTCMechanism | 358-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | LTCMechanism | 358-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | LTCMechanism | 358-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | YD000119 | Yard | 379-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | YD000119 | Yard | 379-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | YD000119 | Yard | 379-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | LTCC000950 | LTCControl | 379-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | LTCC000950 | LTCControl | 379-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | LTCC000950 | LTCControl | 379-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | LTCC000950 | LTCControl | 379-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | LTCC000950 | LTCControl | 379-1 | LTC Control Insp | LTC Output Voltage Level | 122.8 | VAC |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | YD000119 | Yard | 379-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Readings | Totalizer Meter Reading | .5154 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | LTCMechanism | 358-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | LTCMechanism | 358-1 | LTC Counter Readings | LTC As Left Counter | 14983 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | LTCMechanism | 358-1 | LTC Counter Readings | LTC As Found Counter | 14979 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | LTCMechanism | 358-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | LTCMechanism | 358-1 | LTC Counter Readings | General Comments | | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | LTCMechanism | 358-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | LTCMechanism | 358-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | LTCMechanism | GD-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | LTCMechanism | GD-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | LTCMechanism | GD-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | LTCMechanism | GD-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | LTCMechanism | GD-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 388 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | LTCMechanism | GD-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Readings | Switching Operations | 0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Readings | Operations Counter AL | 35 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Readings | Operations Counter AF | 35 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 40 | °C |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 35 | °C |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | FE000452 | Fence | 542-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | FE000452 | Fence | 542-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | FE000452 | Fence | 542-Fence | Fence Patrol Inspection | General Comments | | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | FE000452 | Fence | 542-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | FE000452 | Fence | 542-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | FE000452 | Fence | 542-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | FE000452 | Fence | 542-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | FE000452 | Fence | 542-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | FE000452 | Fence | 542-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | FE000452 | Fence | 542-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | FE000452 | Fence | 542-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | FE000452 | Fence | 542-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | FE000452 | Fence | 542-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | FE000452 | Fence | 542-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Readings | General Comments | | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Patrol Inspection | General Comments | seeping at radiator repair | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Readings | LTC Totalizer Reading | 3710.88 | kw |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Readings | Oil Temp Max | 32 | °C |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | FE000452 | Fence | 542-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | FE000452 | Fence | 542-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 35 | °C |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 30 | °C |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 35 | °C |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 30 | °C |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Patrol Inspection | Radiator Leaks | Seeping | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | FE000093 | Fence | 358-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | FE000093 | Fence | 358-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | FE000093 | Fence | 358-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | FE000093 | Fence | 358-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | FE000093 | Fence | 358-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | CH000211 | ControlHouse | 358-Control house | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | CH000211 | ControlHouse | 358-Control house | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | FE000093 | Fence | 358-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | FE000093 | Fence | 358-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | FE000093 | Fence | 358-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | FE000093 | Fence | 358-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | FE000093 | Fence | 358-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | FE000093 | Fence | 358-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | FE000093 | Fence | 358-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | FE000093 | Fence | 358-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | FE000093 | Fence | 358-Fence | Fence Patrol Inspection | General Comments | | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | FE000093 | Fence | 358-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | FE000093 | Fence | 358-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | YD000119 | Yard | 379-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | YD000119 | Yard | 379-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | YD000119 | Yard | 379-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | YD000119 | Yard | 379-Yard | Yard Patrol Inspection | General Comments | | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | YD000119 | Yard | 379-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | YD000119 | Yard | 379-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | LTCMechanism | GD-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Readings | 9 Month Operations | 3 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Readings | Amps A Ø | 249.0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Readings | Amps B Ø | 252.0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Readings | Amps C Ø | 247.0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0424 | BreakerAirMagnetic | GD-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0424 | BreakerAirMagnetic | GD-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0424 | BreakerAirMagnetic | GD-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0424 | BreakerAirMagnetic | GD-3 | AMCB Readings | 9 Months Operations | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0424 | BreakerAirMagnetic | GD-3 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0475 | BreakerAirMagnetic | HI-14KV TR 1 | AMCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0475 | BreakerAirMagnetic | HI-14KV TR 1 | AMCB Readings | Switching Operations | 0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0475 | BreakerAirMagnetic | HI-14KV TR 1 | AMCB Readings | Operations This Read AM | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0475 | BreakerAirMagnetic | HI-14KV TR 1 | AMCB Readings | Operations Counter AL | 432 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0475 | BreakerAirMagnetic | HI-14KV TR 1 | AMCB Readings | Operations Counter AF | 432 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0475 | BreakerAirMagnetic | HI-14KV TR 1 | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0475 | BreakerAirMagnetic | HI-14KV TR 1 | AMCB Readings | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0475 | BreakerAirMagnetic | HI-14KV TR 1 | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0475 | BreakerAirMagnetic | HI-14KV TR 1 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0475 | BreakerAirMagnetic | HI-14KV TR 1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0475 | BreakerAirMagnetic | HI-14KV TR 1 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Readings | General Comments | | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | CH000170 | ControlHouse | KC-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | CH000170 | ControlHouse | KC-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | CH000170 | ControlHouse | KC-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0475 | BreakerAirMagnetic | HI-14KV TR 1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | CH000170 | ControlHouse | KC-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | CH000170 | ControlHouse | KC-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0475 | BreakerAirMagnetic | HI-14KV TR 1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0475 | BreakerAirMagnetic | HI-14KV TR 1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | CH000170 | ControlHouse | KC-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | CH000170 | ControlHouse | KC-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | CH000170 | ControlHouse | KC-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | SWG000008 | Switchgear | HA-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | SWG000008 | Switchgear | HA-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | SWG000008 | Switchgear | HA-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0475 | BreakerAirMagnetic | HI-14KV TR 1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0475 | BreakerAirMagnetic | HI-14KV TR 1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0475 | BreakerAirMagnetic | HI-14KV TR 1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0475 | BreakerAirMagnetic | HI-14KV TR 1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0475 | BreakerAirMagnetic | HI-14KV TR 1 | AMCB Readings | Amps C Ø | 255.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0475 | BreakerAirMagnetic | HI-14KV TR 1 | AMCB Readings | Amps B Ø | 247.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0475 | BreakerAirMagnetic | HI-14KV TR 1 | AMCB Readings | Amps A Ø | 258.0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | ST000469 | Structure | 540-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | ST000469 | Structure | 540-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | ST000469 | Structure | 540-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | ST000469 | Structure | 540-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | ST000469 | Structure | 540-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0475 | BreakerAirMagnetic | HI-14KV TR 1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0475 | BreakerAirMagnetic | HI-14KV TR 1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0475 | BreakerAirMagnetic | HI-14KV TR 1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0475 | BreakerAirMagnetic | HI-14KV TR 1 | AMCB Readings | 9 Months Operations | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | ST000469 | Structure | 540-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | ST000469 | Structure | 540-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0475 | BreakerAirMagnetic | HI-14KV TR 1 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Readings | General Comments | | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Readings | Amps C Ø | 95.0 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Readings | Amps B Ø | 90.0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | CH000170 | ControlHouse | KC-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | CH000170 | ControlHouse | KC-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | CH000170 | ControlHouse | KC-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | CH000170 | ControlHouse | KC-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | CH000170 | ControlHouse | KC-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | CH000170 | ControlHouse | KC-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | CH000170 | ControlHouse | KC-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | CH000170 | ControlHouse | KC-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | CH000170 | ControlHouse | KC-Control House | Control House Patrol Inspection | General Comments | | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | CH000170 | ControlHouse | KC-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | CH000170 | ControlHouse | KC-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | CH000170 | ControlHouse | KC-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | CH000170 | ControlHouse | KC-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | CH000170 | ControlHouse | KC-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Readings | Amps A Ø | 81.0 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Readings | 9 Month Operations | 1 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Readings | Switching Operations | 1 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Readings | Operations This Read Vac | 1 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Readings | Operations Counter AL | 169 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Readings | Operations Counter AF | 168 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Readings | Amps C Ø | 660.0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Readings | Amps B Ø | 683.0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Readings | Amps A Ø | 675.0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK001783 | BreakerVacuum | 542-0344 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | ST000469 | Structure | 540-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | ST000469 | Structure | 540-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0300 | BreakerVacuum | 542-1 | VCB Readings | 9 Month Operations | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | LTCMechanism | GD-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | LTCMechanism | GD-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | LTCMechanism | GD-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | LTCMechanism | GD-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | LTCMechanism | GD-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 594700 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | LTCMechanism | GD-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 594700 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | LTCMechanism | GD-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | LTCMechanism | GD-TRANS 1 | LTC Counter Readings | General Comments | | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | LTCMechanism | GD-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | CH000446 | ControlHouse | LG-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | CH000446 | ControlHouse | LG-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | CH000446 | ControlHouse | LG-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Readings | Operations Counter AF | 214 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Readings | Operations Counter AL | 215 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Readings | Operations This Read Vac | 3 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Readings | Switching Operations | 1 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.5 | psi |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1600 | psi |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 37 | °C |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 29 | °C |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Readings | General Comments | | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | FE000175 | Fence | 379-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | FE000175 | Fence | 379-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | FE000175 | Fence | 379-Fence | Fence Patrol Inspection | General Comments | | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | FE000175 | Fence | 379-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | FE000175 | Fence | 379-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | FE000175 | Fence | 379-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | FE000175 | Fence | 379-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | FE000175 | Fence | 379-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Readings | LTC Totalizer Reading | 12435.84 | kw |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | FE000175 | Fence | 379-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | FE000175 | Fence | 379-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | FE000175 | Fence | 379-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | FE000175 | Fence | 379-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.1 | psi |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | FE000175 | Fence | 379-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0466 | BreakerVacuum | HI-1103 | VCB Readings | 9 Month Operations VCB New | 14 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0425 | BreakerAirMagnetic | GD-4 | AMCB Readings | Operations Counter AF | 486 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0425 | BreakerAirMagnetic | GD-4 | AMCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0425 | BreakerAirMagnetic | GD-4 | AMCB Readings | General Comments | | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0425 | BreakerAirMagnetic | GD-4 | AMCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0425 | BreakerAirMagnetic | GD-4 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0425 | BreakerAirMagnetic | GD-4 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0425 | BreakerAirMagnetic | GD-4 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0425 | BreakerAirMagnetic | GD-4 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0425 | BreakerAirMagnetic | GD-4 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0425 | BreakerAirMagnetic | GD-4 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0425 | BreakerAirMagnetic | GD-4 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0425 | BreakerAirMagnetic | GD-4 | AMCB Readings | Amps C Ø | 10.0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0425 | BreakerAirMagnetic | GD-4 | AMCB Readings | Amps B Ø | 10.0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0425 | BreakerAirMagnetic | GD-4 | AMCB Readings | Amps A Ø | 10.0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0425 | BreakerAirMagnetic | GD-4 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0425 | BreakerAirMagnetic | GD-4 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0425 | BreakerAirMagnetic | GD-4 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0425 | BreakerAirMagnetic | GD-4 | AMCB Readings | 9 Months Operations | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0425 | BreakerAirMagnetic | GD-4 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | CH000446 | ControlHouse | LG-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | CH000446 | ControlHouse | LG-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | CH000446 | ControlHouse | LG-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | CH000446 | ControlHouse | LG-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | CH000446 | ControlHouse | LG-Battery Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | CH000446 | ControlHouse | LG-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | ST000573 | Structure | KC-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | ST000573 | Structure | KC-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | ST000573 | Structure | KC-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | ST000573 | Structure | KC-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | ST000573 | Structure | KC-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | FE000559 | Fence | KC-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | FE000559 | Fence | KC-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | FE000559 | Fence | KC-Fence | Fence Patrol Inspection | General Comments | | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | FE000559 | Fence | KC-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | FE000559 | Fence | KC-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | FE000559 | Fence | KC-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | FE000559 | Fence | KC-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | FE000559 | Fence | KC-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | FE000559 | Fence | KC-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | FE000559 | Fence | KC-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | FE000559 | Fence | KC-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | FE000559 | Fence | KC-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | FE000559 | Fence | KC-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | FE000559 | Fence | KC-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | FE000559 | Fence | KC-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | FE000559 | Fence | KC-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 37 | °C |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 30 | °C |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 37 | °C |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 30 | °C |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 37 | °C |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 30 | °C |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000054 | Switchgear | IN-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000054 | Switchgear | IN-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000054 | Switchgear | IN-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000054 | Switchgear | IN-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000054 | Switchgear | IN-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000054 | Switchgear | IN-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000054 | Switchgear | IN-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000054 | Switchgear | IN-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000054 | Switchgear | IN-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000054 | Switchgear | IN-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000054 | Switchgear | IN-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000054 | Switchgear | IN-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000054 | Switchgear | IN-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000054 | Switchgear | IN-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000054 | Switchgear | IN-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000054 | Switchgear | IN-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000054 | Switchgear | IN-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000054 | Switchgear | IN-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000054 | Switchgear | IN-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | needs nitrogen | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Readings | H2 Winding Temp Max | 35 | °C |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Readings | H2 Winding Temp Present | 30 | °C |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | FE000175 | Fence | 379-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | FE000175 | Fence | 379-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | FE000175 | Fence | 379-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.2954 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0466 | BreakerVacuum | HI-1103 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Readings | Winding Temp Max | 31 | °C |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Readings | Winding Temp Present | 29 | °C |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | WithLTC | 379-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | FE000561 | Fence | HA-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | WithLTC | IN-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | ST000573 | Structure | KC-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | ST000573 | Structure | KC-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | ST000573 | Structure | KC-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | ST000573 | Structure | KC-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | ST000573 | Structure | KC-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | ST000573 | Structure | KC-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | ST000573 | Structure | KC-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | ST000573 | Structure | KC-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | ST000573 | Structure | KC-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | ST000573 | Structure | KC-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | ST000573 | Structure | KC-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | ST000573 | Structure | KC-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | ST000573 | Structure | KC-Structure | Structure Patrol Inspection | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | ST000573 | Structure | KC-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | ST000573 | Structure | KC-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | ST000573 | Structure | KC-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | CH000213 | ControlHouse | 379-Control House | Control House Patrol Inspection | General Comments | | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | CH000213 | ControlHouse | 379-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | CH000213 | ControlHouse | 379-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | CH000213 | ControlHouse | 379-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | CH000213 | ControlHouse | 379-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000012 | Switchgear | Hi Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000012 | Switchgear | Hi Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000012 | Switchgear | Hi Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000012 | Switchgear | Hi Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000012 | Switchgear | Hi Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000012 | Switchgear | Hi Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000012 | Switchgear | Hi Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000012 | Switchgear | Hi Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000012 | Switchgear | Hi Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0466 | BreakerVacuum | HI-1103 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0466 | BreakerVacuum | HI-1103 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0466 | BreakerVacuum | HI-1103 | VCB Readings | Amps C Ø | 85.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0466 | BreakerVacuum | HI-1103 | VCB Readings | Amps B Ø | 60.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0466 | BreakerVacuum | HI-1103 | VCB Readings | Amps A Ø | 72.0 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 25 | °C |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 70 | °C |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 20 | °C |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 65 | °C |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 20 | °C |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 65 | °C |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 335.00 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | CH000211 | ControlHouse | 358-Control house | Control House Patrol Inspection | Broom on Site? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Readings | General Comments | | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Readings | Operations Counter AF | 174 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Readings | Operations Counter AL | 174 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Readings | Operations This Read Vac | 0 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Readings | Switching Operations | 0 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK001785 | BreakerVacuum | 358-4720 | VCB Readings | Unknown Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0466 | BreakerVacuum | HI-1103 | VCB Readings | Unknown Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0466 | BreakerVacuum | HI-1103 | VCB Readings | Switching Operations | 0 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | CH000211 | ControlHouse | 358-Control house | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | CH000211 | ControlHouse | 358-Control house | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | CH000211 | ControlHouse | 358-Control house | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | CH000211 | ControlHouse | 358-Control house | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | CH000211 | ControlHouse | 358-Control house | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | CH000211 | ControlHouse | 358-Control house | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | CH000211 | ControlHouse | 358-Control house | Control House Patrol Inspection | Floor Swept? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | CH000211 | ControlHouse | 358-Control house | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | CH000211 | ControlHouse | 358-Control house | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | CH000211 | ControlHouse | 358-Control house | Control House Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | CH000211 | ControlHouse | 358-Control house | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | CH000211 | ControlHouse | 358-Control house | Control House Patrol Inspection | Trash Emptied? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | CH000211 | ControlHouse | 358-Control house | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | CH000211 | ControlHouse | 358-Control house | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | CH000213 | ControlHouse | 379-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | CH000213 | ControlHouse | 379-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | CH000213 | ControlHouse | 379-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | CH000213 | ControlHouse | 379-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | CH000213 | ControlHouse | 379-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | CH000213 | ControlHouse | 379-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0466 | BreakerVacuum | HI-1103 | VCB Readings | Operations This Read Vac | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0466 | BreakerVacuum | HI-1103 | VCB Readings | Operations Counter AL | 204 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0466 | BreakerVacuum | HI-1103 | VCB Readings | Operations Counter AF | 204 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0466 | BreakerVacuum | HI-1103 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0466 | BreakerVacuum | HI-1103 | VCB Readings | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0466 | BreakerVacuum | HI-1103 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | B0329 | WithLTC | 358-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | CH000213 | ControlHouse | 379-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0466 | BreakerVacuum | HI-1103 | VCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0466 | BreakerVacuum | HI-1103 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0466 | BreakerVacuum | HI-1103 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0466 | BreakerVacuum | HI-1103 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0466 | BreakerVacuum | HI-1103 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0466 | BreakerVacuum | HI-1103 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0466 | BreakerVacuum | HI-1103 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0466 | BreakerVacuum | HI-1103 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | CH000213 | ControlHouse | 379-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | CH000213 | ControlHouse | 379-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | CH000213 | ControlHouse | 379-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | CH000213 | ControlHouse | 379-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | CH000213 | ControlHouse | 379-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Readings | Amps A Ø | 159.0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Readings | Amps B Ø | 182.0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Readings | Amps C Ø | 161.0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | YD000570 | Yard | HA-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | YD000570 | Yard | HA-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 35 | °C |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 31 | °C |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 31 | °C |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Readings | Fault Adjusted Amps A Phase V | 6.13 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | ST000469 | Structure | 540-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | ST000469 | Structure | 540-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0425 | BreakerAirMagnetic | GD-4 | AMCB Readings | Unknown Operations | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Readings | Fault Adjusted Amps B Phase V | 6.13 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Readings | Fault Operations A Ø | 1 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Readings | Fault Operations B Ø | 1 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0425 | BreakerAirMagnetic | GD-4 | AMCB Readings | Switching Operations | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0425 | BreakerAirMagnetic | GD-4 | AMCB Readings | Operations This Read AM | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0425 | BreakerAirMagnetic | GD-4 | AMCB Readings | Operations Counter AL | 486 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | ST000469 | Structure | 540-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | ST000469 | Structure | 540-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | WithLTC | HI-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0552 | BreakerAirMagnetic | LG-2 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0552 | BreakerAirMagnetic | LG-2 | AMCB Patrol Inspection | General Comments | | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0552 | BreakerAirMagnetic | LG-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0552 | BreakerAirMagnetic | LG-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Readings | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0466 | BreakerVacuum | HI-1103 | VCB Readings | 9 Month Operations | 14 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | FE000840 | Fence | 540-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | FE000840 | Fence | 540-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | FE000840 | Fence | 540-Fence | Fence Patrol Inspection | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | FE000840 | Fence | 540-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0466 | BreakerVacuum | HI-1103 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0466 | BreakerVacuum | HI-1103 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | ST000469 | Structure | 540-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | ST000469 | Structure | 540-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | ST000469 | Structure | 540-Structure | Structure Patrol Inspection | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | ST000469 | Structure | 540-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | ST000469 | Structure | 540-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | ST000469 | Structure | 540-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | ST000469 | Structure | 540-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | ST000469 | Structure | 540-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | FE000840 | Fence | 540-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | FE000840 | Fence | 540-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | FE000840 | Fence | 540-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | FE000840 | Fence | 540-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | FE000840 | Fence | 540-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | FE000840 | Fence | 540-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000012 | Switchgear | Hi Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000012 | Switchgear | Hi Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000012 | Switchgear | Hi Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | FE000840 | Fence | 540-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | FE000840 | Fence | 540-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | FE000840 | Fence | 540-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | FE000840 | Fence | 540-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | FE000840 | Fence | 540-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | FE000840 | Fence | 540-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000012 | Switchgear | Hi Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000012 | Switchgear | Hi Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000012 | Switchgear | Hi Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | LTCMechanism | LG-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000012 | Switchgear | Hi Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000012 | Switchgear | Hi Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000012 | Switchgear | Hi Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000012 | Switchgear | Hi Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | LTCMechanism | LG-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | LTCMechanism | LG-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | LTCMechanism | LG-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | LTCMechanism | LG-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | WithLTC | GD-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 32 | °C |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 35 | °C |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | WithLTC | IN-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 30 | °C |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | LTCMechanism | LG-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | LTCMechanism | LG-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | LTCMechanism | LG-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | LTCMechanism | LG-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | LTCMechanism | LG-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | LTCMechanism | LG-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | LTCMechanism | LG-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | LTCMechanism | LG-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | LTCMechanism | LG-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0053 | BreakerVacuum | 540-0334 | VCB Readings | 9 Month Operations | 3 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Readings | Amps C Ø | 343.0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0510 | BreakerVacuum | IN-1295 | VCB Readings | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0510 | BreakerVacuum | IN-1295 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0510 | BreakerVacuum | IN-1295 | VCB Readings | Operations Counter AF | 158 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0510 | BreakerVacuum | IN-1295 | VCB Readings | Operations Counter AL | 158 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0510 | BreakerVacuum | IN-1295 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0510 | BreakerVacuum | IN-1295 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0510 | BreakerVacuum | IN-1295 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Readings | Amps C Ø | 252.0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Readings | Amps B Ø | 273.0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Readings | Amps A Ø | 251.0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Readings | Amps B Ø | 348.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0476 | BreakerAirMagnetic | HI-GND TR 1 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0476 | BreakerAirMagnetic | HI-GND TR 1 | AMCB Readings | 9 Months Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0476 | BreakerAirMagnetic | HI-GND TR 1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0476 | BreakerAirMagnetic | HI-GND TR 1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0476 | BreakerAirMagnetic | HI-GND TR 1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0476 | BreakerAirMagnetic | HI-GND TR 1 | AMCB Readings | Amps A Ø | 0.0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Readings | 9 Month Operations | 9 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LTCC000598 | LTCControl | HI-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LTCC000598 | LTCControl | HI-TRANS 2 | LTC Control Insp | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0510 | BreakerVacuum | IN-1295 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0510 | BreakerVacuum | IN-1295 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0510 | BreakerVacuum | IN-1295 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0510 | BreakerVacuum | IN-1295 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0510 | BreakerVacuum | IN-1295 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0510 | BreakerVacuum | IN-1295 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0510 | BreakerVacuum | IN-1295 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0510 | BreakerVacuum | IN-1295 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0510 | BreakerVacuum | IN-1295 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0510 | BreakerVacuum | IN-1295 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0429 | BreakerAirMagnetic | HA-2 | AMCB Readings | Unknown Operations | 0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0429 | BreakerAirMagnetic | HA-2 | AMCB Readings | Switching Operations | 0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0429 | BreakerAirMagnetic | HA-2 | AMCB Readings | Operations Counter AL | 525 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0429 | BreakerAirMagnetic | HA-2 | AMCB Readings | Operations Counter AF | 525 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0429 | BreakerAirMagnetic | HA-2 | AMCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0429 | BreakerAirMagnetic | HA-2 | AMCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0429 | BreakerAirMagnetic | HA-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0429 | BreakerAirMagnetic | HA-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0429 | BreakerAirMagnetic | HA-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0429 | BreakerAirMagnetic | HA-2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0429 | BreakerAirMagnetic | HA-2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0429 | BreakerAirMagnetic | HA-2 | AMCB Readings | Amps C Ø | 80.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0429 | BreakerAirMagnetic | HA-2 | AMCB Readings | Amps B Ø | 80.0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0429 | BreakerAirMagnetic | HA-2 | AMCB Readings | Amps A Ø | 20.0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Readings | Switching Operations | 1 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Readings | Operations This Read Vac | 1 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Readings | Operations Counter AL | 364 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Readings | Operations Counter AF | 363 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Readings | General Comments | | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BK000411 | BreakerVacuum | 542-0343 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Readings | X2 Winding Temp Max | 40 | °C |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Readings | X2 Winding Temp Present | 35 | °C |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Readings | Amps A Ø | 350.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Readings | 9 Month Operations | 1 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0465 | BreakerVacuum | HI-1102 | VCB Readings | Amps A Ø | 70.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0465 | BreakerVacuum | HI-1102 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0465 | BreakerVacuum | HI-1102 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0465 | BreakerVacuum | HI-1102 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0465 | BreakerVacuum | HI-1102 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0465 | BreakerVacuum | HI-1102 | VCB Readings | 9 Month Operations | 6 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | FE000647 | Fence | IN-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | FE000647 | Fence | IN-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | FE000647 | Fence | IN-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | FE000647 | Fence | IN-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | FE000647 | Fence | IN-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | FE000647 | Fence | IN-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | FE000647 | Fence | IN-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | FE000647 | Fence | IN-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | FE000647 | Fence | IN-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | FE000647 | Fence | IN-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | FE000647 | Fence | IN-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | FE000647 | Fence | IN-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | FE000647 | Fence | IN-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | FE000647 | Fence | IN-Fence | Fence Patrol Inspection | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | FE000647 | Fence | IN-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | FE000647 | Fence | IN-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | YD000576 | Yard | HI-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | YD000576 | Yard | HI-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | YD000576 | Yard | HI-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | YD000576 | Yard | HI-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | YD000576 | Yard | HI-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | YD000576 | Yard | HI-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Patrol Inspection | Gas Accumulation Gauge | Normal | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Readings | General Comments | | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Readings | H2 Winding Temp Max | 45 | °C |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Readings | H2 Winding Temp Present | 40 | °C |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0476 | BreakerAirMagnetic | HI-GND TR 1 | AMCB Readings | Amps B Ø | 0.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0476 | BreakerAirMagnetic | HI-GND TR 1 | AMCB Readings | Amps C Ø | 0.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0476 | BreakerAirMagnetic | HI-GND TR 1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0476 | BreakerAirMagnetic | HI-GND TR 1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0476 | BreakerAirMagnetic | HI-GND TR 1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0476 | BreakerAirMagnetic | HI-GND TR 1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0476 | BreakerAirMagnetic | HI-GND TR 1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0476 | BreakerAirMagnetic | HI-GND TR 1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0476 | BreakerAirMagnetic | HI-GND TR 1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0476 | BreakerAirMagnetic | HI-GND TR 1 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0476 | BreakerAirMagnetic | HI-GND TR 1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 26.00 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 20.00 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | LT0103 | NonLTC | KC-TRANS 1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0476 | BreakerAirMagnetic | HI-GND TR 1 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0476 | BreakerAirMagnetic | HI-GND TR 1 | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0476 | BreakerAirMagnetic | HI-GND TR 1 | AMCB Readings | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0476 | BreakerAirMagnetic | HI-GND TR 1 | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0476 | BreakerAirMagnetic | HI-GND TR 1 | AMCB Readings | Operations Counter AF | 308 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0476 | BreakerAirMagnetic | HI-GND TR 1 | AMCB Readings | Operations Counter AL | 308 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0476 | BreakerAirMagnetic | HI-GND TR 1 | AMCB Readings | Operations This Read AM | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0476 | BreakerAirMagnetic | HI-GND TR 1 | AMCB Readings | Switching Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0476 | BreakerAirMagnetic | HI-GND TR 1 | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | PF000165 | PowerFuse | HI-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | PF000165 | PowerFuse | HI-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0474 | BreakerAirMagnetic | HI-1475 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0474 | BreakerAirMagnetic | HI-1475 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0474 | BreakerAirMagnetic | HI-1475 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0474 | BreakerAirMagnetic | HI-1475 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0474 | BreakerAirMagnetic | HI-1475 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0474 | BreakerAirMagnetic | HI-1475 | AMCB Readings | Amps C Ø | 72.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0474 | BreakerAirMagnetic | HI-1475 | AMCB Readings | Amps B Ø | 69.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0474 | BreakerAirMagnetic | HI-1475 | AMCB Readings | Amps A Ø | 73.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0474 | BreakerAirMagnetic | HI-1475 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0474 | BreakerAirMagnetic | HI-1475 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0474 | BreakerAirMagnetic | HI-1475 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Patrol Inspection | SF6 Pressure Pole 1 | 92 | psi |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Patrol Inspection | SF6 Pressure Pole 2 | 92 | psi |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Patrol Inspection | SF6 Pressure Pole 3 | 92 | psi |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0474 | BreakerAirMagnetic | HI-1475 | AMCB Readings | 9 Months Operations | 2 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0474 | BreakerAirMagnetic | HI-1475 | AMCB Readings | 9 Month Ops New | 2 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0470 | BreakerVacuum | HI-12KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0470 | BreakerVacuum | HI-12KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0470 | BreakerVacuum | HI-12KV TR 2 | VCB Readings | Operations Counter AL | 269 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0470 | BreakerVacuum | HI-12KV TR 2 | VCB Readings | Operations Counter AF | 269 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0470 | BreakerVacuum | HI-12KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0470 | BreakerVacuum | HI-12KV TR 2 | VCB Readings | General Comments | | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | BAT001435 | Battery | HA-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | BAT001435 | Battery | HA-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | YD000586 | Yard | LG-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Readings | Switching Operations | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Readings | Unknown Operations | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Readings | Switching Operations | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Readings | Operations Counter AL | 125 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Readings | Operations Counter AF | 125 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Readings | General Comments | | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | YD000586 | Yard | LG-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | YD000586 | Yard | LG-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | YD000586 | Yard | LG-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | YD000586 | Yard | LG-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | YD000586 | Yard | LG-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | YD000586 | Yard | LG-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0464 | BreakerVacuum | HI-1101 | VCB Readings | Amps C Ø | 97.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0464 | BreakerVacuum | HI-1101 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0464 | BreakerVacuum | HI-1101 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0464 | BreakerVacuum | HI-1101 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0464 | BreakerVacuum | HI-1101 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0464 | BreakerVacuum | HI-1101 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0464 | BreakerVacuum | HI-1101 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0464 | BreakerVacuum | HI-1101 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0464 | BreakerVacuum | HI-1101 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0464 | BreakerVacuum | HI-1101 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0464 | BreakerVacuum | HI-1101 | VCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0464 | BreakerVacuum | HI-1101 | VCB Patrol Inspection | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0464 | BreakerVacuum | HI-1101 | VCB Readings | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0464 | BreakerVacuum | HI-1101 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0464 | BreakerVacuum | HI-1101 | VCB Readings | Operations Counter AF | 225 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0464 | BreakerVacuum | HI-1101 | VCB Readings | Operations Counter AL | 225 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0464 | BreakerVacuum | HI-1101 | VCB Readings | Operations This Read Vac | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0464 | BreakerVacuum | HI-1101 | VCB Readings | Switching Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0464 | BreakerVacuum | HI-1101 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | SWG000075 | Switchgear | GA-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | SWG000075 | Switchgear | GA-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | SWG000075 | Switchgear | GA-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Readings | Operations Counter AF | 152 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Readings | Operations Counter AL | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Readings | Operations This Read SF6 | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0474 | BreakerAirMagnetic | HI-1475 | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0474 | BreakerAirMagnetic | HI-1475 | AMCB Readings | Switching Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0474 | BreakerAirMagnetic | HI-1475 | AMCB Readings | Operations This Read AM | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0474 | BreakerAirMagnetic | HI-1475 | AMCB Readings | Operations Counter AL | 805 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0474 | BreakerAirMagnetic | HI-1475 | AMCB Readings | Operations Counter AF | 805 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0474 | BreakerAirMagnetic | HI-1475 | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0474 | BreakerAirMagnetic | HI-1475 | AMCB Readings | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0474 | BreakerAirMagnetic | HI-1475 | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0474 | BreakerAirMagnetic | HI-1475 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0474 | BreakerAirMagnetic | HI-1475 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0474 | BreakerAirMagnetic | HI-1475 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0474 | BreakerAirMagnetic | HI-1475 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0474 | BreakerAirMagnetic | HI-1475 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0470 | BreakerVacuum | HI-12KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0470 | BreakerVacuum | HI-12KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0510 | BreakerVacuum | IN-1295 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0510 | BreakerVacuum | IN-1295 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0510 | BreakerVacuum | IN-1295 | VCB Readings | Amps A Ø | 185.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0510 | BreakerVacuum | IN-1295 | VCB Readings | Amps B Ø | 187.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0510 | BreakerVacuum | IN-1295 | VCB Readings | Amps C Ø | 190.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0510 | BreakerVacuum | IN-1295 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | BAT001593 | Battery | HI-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | BAT001593 | Battery | HI-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | BAT001593 | Battery | HI-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | BAT001593 | Battery | HI-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | BAT001593 | Battery | HI-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | BAT001593 | Battery | HI-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | BAT001593 | Battery | HI-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | BAT001593 | Battery | HI-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | BAT001593 | Battery | HI-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | BAT001593 | Battery | HI-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | BAT001593 | Battery | HI-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 68 | °F |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Readings | Operations Counter AL | 47 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Readings | Operations Counter AF | 47 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | BAT001593 | Battery | HI-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0470 | BreakerVacuum | HI-12KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0470 | BreakerVacuum | HI-12KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0470 | BreakerVacuum | HI-12KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0470 | BreakerVacuum | HI-12KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0470 | BreakerVacuum | HI-12KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0470 | BreakerVacuum | HI-12KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0470 | BreakerVacuum | HI-12KV TR 2 | VCB Readings | Amps C Ø | 431.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0470 | BreakerVacuum | HI-12KV TR 2 | VCB Readings | Amps B Ø | 384.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0470 | BreakerVacuum | HI-12KV TR 2 | VCB Readings | Amps A Ø | 396.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Readings | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001466 | BreakerVacuum | IN-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Readings | Amps C Ø | 256.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0465 | BreakerVacuum | HI-1102 | VCB Readings | Unknown Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0465 | BreakerVacuum | HI-1102 | VCB Readings | Switching Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0465 | BreakerVacuum | HI-1102 | VCB Readings | Operations This Read Vac | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0465 | BreakerVacuum | HI-1102 | VCB Readings | Operations Counter AL | 879 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0465 | BreakerVacuum | HI-1102 | VCB Readings | Operations Counter AF | 879 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0465 | BreakerVacuum | HI-1102 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0465 | BreakerVacuum | HI-1102 | VCB Readings | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0465 | BreakerVacuum | HI-1102 | VCB Patrol Inspection | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0465 | BreakerVacuum | HI-1102 | VCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0465 | BreakerVacuum | HI-1102 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0465 | BreakerVacuum | HI-1102 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Readings | Amps B Ø | 256.0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Readings | Amps A Ø | 224.0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | MB0176 | BreakerVacuum | 379-1 | VCB Readings | 9 Month Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0465 | BreakerVacuum | HI-1102 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0465 | BreakerVacuum | HI-1102 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0465 | BreakerVacuum | HI-1102 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0465 | BreakerVacuum | HI-1102 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0465 | BreakerVacuum | HI-1102 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0465 | BreakerVacuum | HI-1102 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0465 | BreakerVacuum | HI-1102 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0465 | BreakerVacuum | HI-1102 | VCB Readings | Amps C Ø | 72.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0465 | BreakerVacuum | HI-1102 | VCB Readings | Amps B Ø | 73.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0510 | BreakerVacuum | IN-1295 | VCB Readings | 9 Month Operations | 2 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0510 | BreakerVacuum | IN-1295 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0510 | BreakerVacuum | IN-1295 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0470 | BreakerVacuum | HI-12KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0470 | BreakerVacuum | HI-12KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0470 | BreakerVacuum | HI-12KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0426 | BreakerAirMagnetic | GD-SEC 1 SPARE | AMCB Readings | Operations Counter AL | 306 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0426 | BreakerAirMagnetic | GD-SEC 1 SPARE | AMCB Readings | Operations This Read AM | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0426 | BreakerAirMagnetic | GD-SEC 1 SPARE | AMCB Readings | Switching Operations | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0426 | BreakerAirMagnetic | GD-SEC 1 SPARE | AMCB Readings | Unknown Operations | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Readings | 9 Month Operations | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Readings | Amps A Ø | 44.0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Readings | Amps B Ø | 33.0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Readings | Amps C Ø | 34.0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Readings | Switching Operations | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Readings | Operations This Read Vac | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Readings | Operations Counter AL | 229 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Readings | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Readings | Operations Counter AF | 229 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Readings | General Comments | | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | YD000569 | Yard | KC-Yard | Yard Patrol Inspection | Ambient Temp | 65 | °F |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | YD000569 | Yard | KC-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | YD000569 | Yard | KC-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | ST000631 | Structure | IN-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | ST000631 | Structure | IN-Structure | Structure Patrol Inspection | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | YD000569 | Yard | KC-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | YD000569 | Yard | KC-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | YD000569 | Yard | KC-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | YD000569 | Yard | KC-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | YD000569 | Yard | KC-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Readings | Operations This Read Vac | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | YD000569 | Yard | KC-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Readings | Operations Counter AL | 36 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Readings | Operations Counter AF | 36 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | ST000631 | Structure | IN-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | ST000631 | Structure | IN-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0430 | BreakerAirMagnetic | HA-3 | AMCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0430 | BreakerAirMagnetic | HA-3 | AMCB Readings | Operations Counter AF | 362 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0430 | BreakerAirMagnetic | HA-3 | AMCB Readings | Operations Counter AL | 362 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0430 | BreakerAirMagnetic | HA-3 | AMCB Readings | Switching Operations | 0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0430 | BreakerAirMagnetic | HA-3 | AMCB Readings | Unknown Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | ST000631 | Structure | IN-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | ST000631 | Structure | IN-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | ST000631 | Structure | IN-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | ST000631 | Structure | IN-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | ST000631 | Structure | IN-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | ST000631 | Structure | IN-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | ST000631 | Structure | IN-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | ST000631 | Structure | IN-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | ST000631 | Structure | IN-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0426 | BreakerAirMagnetic | GD-SEC 1 SPARE | AMCB Readings | 9 Month Ops New | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0426 | BreakerAirMagnetic | GD-SEC 1 SPARE | AMCB Readings | 9 Months Operations | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0426 | BreakerAirMagnetic | GD-SEC 1 SPARE | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0426 | BreakerAirMagnetic | GD-SEC 1 SPARE | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0426 | BreakerAirMagnetic | GD-SEC 1 SPARE | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0426 | BreakerAirMagnetic | GD-SEC 1 SPARE | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0426 | BreakerAirMagnetic | GD-SEC 1 SPARE | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0426 | BreakerAirMagnetic | GD-SEC 1 SPARE | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0426 | BreakerAirMagnetic | GD-SEC 1 SPARE | AMCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0426 | BreakerAirMagnetic | GD-SEC 1 SPARE | AMCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0426 | BreakerAirMagnetic | GD-SEC 1 SPARE | AMCB Readings | General Comments | | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0426 | BreakerAirMagnetic | GD-SEC 1 SPARE | AMCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0426 | BreakerAirMagnetic | GD-SEC 1 SPARE | AMCB Readings | Operations Counter AF | 306 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Readings | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Readings | Operations Counter AF | 53 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Readings | Operations Counter AL | 53 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Readings | Operations This Read Vac | 4 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Readings | Switching Operations | 4 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | YD000569 | Yard | KC-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | BCH000026 | Charger | HA-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | BCH000026 | Charger | HA-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.8 | VDC |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | BCH000026 | Charger | HA-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.8 | VDC |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | BCH000026 | Charger | HA-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 0.0 | amps |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | BCH000026 | Charger | HA-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | BAT001291 | Battery | LG-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | BAT001291 | Battery | LG-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | BAT001291 | Battery | LG-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | BAT001291 | Battery | LG-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | BAT001291 | Battery | LG-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | BAT001291 | Battery | LG-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | BAT001291 | Battery | LG-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | BAT001291 | Battery | LG-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | BAT001291 | Battery | LG-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | BAT001291 | Battery | LG-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | BAT001291 | Battery | LG-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | BAT001291 | Battery | LG-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | BAT001291 | Battery | LG-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 75 | °F |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | BAT001291 | Battery | LG-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | YD000569 | Yard | KC-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Readings | Amps B Ø | 190.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Readings | Amps A Ø | 187.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Readings | 9 Month Operations | 2 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001464 | BreakerVacuum | IN-1293 | VCB Readings | Amps C Ø | 182.0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | KB0065 | BreakerVacuum | 379-4615 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | YD000569 | Yard | KC-Yard | Yard Patrol Inspection | General Comments | No oil stop valve on site | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | YD000569 | Yard | KC-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | YD000569 | Yard | KC-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | YD000569 | Yard | KC-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | YD000569 | Yard | KC-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | YD000569 | Yard | KC-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Readings | 9 Month Operations | 6 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Readings | Amps A Ø | 145.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Readings | Amps B Ø | 149.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Readings | Amps C Ø | 142.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001463 | BreakerVacuum | IN-1292 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | BCH000103 | Charger | GD-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | CH000459 | ControlHouse | HA-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | CH000459 | ControlHouse | HA-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | CH000459 | ControlHouse | HA-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | BCH000103 | Charger | GD-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | BCH000103 | Charger | GD-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | BCH000103 | Charger | GD-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000077 | Switchgear | Hi Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000077 | Switchgear | Hi Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000077 | Switchgear | Hi Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000022 | Switchgear | LG-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000022 | Switchgear | LG-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000022 | Switchgear | LG-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000022 | Switchgear | LG-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000022 | Switchgear | LG-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000022 | Switchgear | LG-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000022 | Switchgear | LG-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000022 | Switchgear | LG-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000022 | Switchgear | LG-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000022 | Switchgear | LG-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000022 | Switchgear | LG-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000022 | Switchgear | LG-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000022 | Switchgear | LG-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000022 | Switchgear | LG-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000022 | Switchgear | LG-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000022 | Switchgear | LG-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000077 | Switchgear | Hi Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000077 | Switchgear | Hi Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000077 | Switchgear | Hi Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000077 | Switchgear | Hi Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000077 | Switchgear | Hi Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000077 | Switchgear | Hi Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000077 | Switchgear | Hi Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000077 | Switchgear | Hi Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0554 | BreakerAirMagnetic | LG-4 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0554 | BreakerAirMagnetic | LG-4 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0554 | BreakerAirMagnetic | LG-4 | AMCB Patrol Inspection | General Comments | | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0554 | BreakerAirMagnetic | LG-4 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Readings | Operations Counter AL | 48 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Readings | Operations Counter AF | 48 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | YD000576 | Yard | HI-Yard | Yard Patrol Inspection | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | YD000576 | Yard | HI-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | YD000576 | Yard | HI-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | YD000576 | Yard | HI-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | YD000576 | Yard | HI-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | YD000576 | Yard | HI-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | YD000576 | Yard | HI-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | YD000576 | Yard | HI-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | YD000576 | Yard | HI-Yard | Yard Patrol Inspection | Ambient Temp | 64 | °F |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | PF000176 | PowerFuse | IN-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | PF000176 | PowerFuse | IN-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | YD000652 | Yard | IN-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | YD000652 | Yard | IN-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | YD000652 | Yard | IN-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | YD000652 | Yard | IN-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | YD000652 | Yard | IN-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | YD000652 | Yard | IN-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | YD000652 | Yard | IN-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | YD000652 | Yard | IN-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0470 | BreakerVacuum | HI-12KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0470 | BreakerVacuum | HI-12KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0470 | BreakerVacuum | HI-12KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0470 | BreakerVacuum | HI-12KV TR 2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0470 | BreakerVacuum | HI-12KV TR 2 | VCB Readings | 9 Month Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | YD000652 | Yard | IN-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | YD000652 | Yard | IN-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | YD000652 | Yard | IN-Yard | Yard Patrol Inspection | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000077 | Switchgear | Hi Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000077 | Switchgear | Hi Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000077 | Switchgear | Hi Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | PF000175 | PowerFuse | IN-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | PF000175 | PowerFuse | IN-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000077 | Switchgear | Hi Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000077 | Switchgear | Hi Swgr Sec 1 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000077 | Switchgear | Hi Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000077 | Switchgear | Hi Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000077 | Switchgear | Hi Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | SWG000077 | Switchgear | Hi Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | BCH000102 | Charger | GA-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | BCH000102 | Charger | GA-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.8 | VDC |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | BCH000102 | Charger | GA-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.8 | VDC |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | BCH000102 | Charger | GA-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | BCH000102 | Charger | GA-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | BCH000103 | Charger | GD-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | BCH000103 | Charger | GD-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.6 | VDC |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | BCH000103 | Charger | GD-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.6 | VDC |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | YD000652 | Yard | IN-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | YD000652 | Yard | IN-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | YD000652 | Yard | IN-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Readings | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Readings | LTC Totalizer Reading | 4809.60 | kw |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | YD000652 | Yard | IN-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | YD000652 | Yard | IN-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | YD000652 | Yard | IN-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | ST000631 | Structure | IN-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | ST000631 | Structure | IN-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | ST000631 | Structure | IN-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | ST000631 | Structure | IN-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | ST000631 | Structure | IN-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | ST000631 | Structure | IN-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Readings | Oil Temp Max | 36 | °C |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Readings | Oil Temp Present | 36 | °C |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Readings | Totalizer Meter Reading | .5010 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | ST000631 | Structure | IN-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | BAT001431 | Battery | GA-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0430 | BreakerAirMagnetic | HA-3 | AMCB Readings | Amps A Ø | 20.0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0430 | BreakerAirMagnetic | HA-3 | AMCB Readings | Amps B Ø | 20.0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0430 | BreakerAirMagnetic | HA-3 | AMCB Readings | Amps C Ø | 20.0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0430 | BreakerAirMagnetic | HA-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0430 | BreakerAirMagnetic | HA-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0430 | BreakerAirMagnetic | HA-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0430 | BreakerAirMagnetic | HA-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0430 | BreakerAirMagnetic | HA-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0430 | BreakerAirMagnetic | HA-3 | AMCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | BAT001431 | Battery | GA-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | BAT001431 | Battery | GA-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | BAT001431 | Battery | GA-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 76 | °F |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Readings | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | YD000569 | Yard | KC-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Readings | Amps C Ø | 1.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Readings | Amps B Ø | 1.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Readings | Amps A Ø | 1.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | WithLTC | 540-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001465 | BreakerVacuum | IN-1294 | VCB Readings | 9 Month Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | YD000652 | Yard | IN-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | YD000652 | Yard | IN-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0467 | BreakerVacuum | HI-1104 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0467 | BreakerVacuum | HI-1104 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0467 | BreakerVacuum | HI-1104 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0467 | BreakerVacuum | HI-1104 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0467 | BreakerVacuum | HI-1104 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0467 | BreakerVacuum | HI-1104 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0467 | BreakerVacuum | HI-1104 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0467 | BreakerVacuum | HI-1104 | VCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0467 | BreakerVacuum | HI-1104 | VCB Patrol Inspection | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0467 | BreakerVacuum | HI-1104 | VCB Readings | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0467 | BreakerVacuum | HI-1104 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0467 | BreakerVacuum | HI-1104 | VCB Readings | Operations Counter AF | 923 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0467 | BreakerVacuum | HI-1104 | VCB Readings | Operations Counter AL | 923 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0467 | BreakerVacuum | HI-1104 | VCB Readings | Operations This Read Vac | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0467 | BreakerVacuum | HI-1104 | VCB Readings | Switching Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0467 | BreakerVacuum | HI-1104 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0424 | BreakerAirMagnetic | GD-3 | AMCB Readings | Operations This Read AM | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0424 | BreakerAirMagnetic | GD-3 | AMCB Readings | Switching Operations | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0424 | BreakerAirMagnetic | GD-3 | AMCB Readings | Unknown Operations | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0422 | BreakerAirMagnetic | GD-1 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0422 | BreakerAirMagnetic | GD-1 | AMCB Readings | 9 Months Operations | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0422 | BreakerAirMagnetic | GD-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0422 | BreakerAirMagnetic | GD-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0422 | BreakerAirMagnetic | GD-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0422 | BreakerAirMagnetic | GD-1 | AMCB Readings | Amps A Ø | 220.0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0422 | BreakerAirMagnetic | GD-1 | AMCB Readings | Amps B Ø | 240.0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0422 | BreakerAirMagnetic | GD-1 | AMCB Readings | Amps C Ø | 280.0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0422 | BreakerAirMagnetic | GD-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0422 | BreakerAirMagnetic | GD-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0422 | BreakerAirMagnetic | GD-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0422 | BreakerAirMagnetic | GD-1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0422 | BreakerAirMagnetic | GD-1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0422 | BreakerAirMagnetic | GD-1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0422 | BreakerAirMagnetic | GD-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0422 | BreakerAirMagnetic | GD-1 | AMCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0422 | BreakerAirMagnetic | GD-1 | AMCB Readings | General Comments | | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0422 | BreakerAirMagnetic | GD-1 | AMCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0422 | BreakerAirMagnetic | GD-1 | AMCB Readings | Operations Counter AF | 466 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0422 | BreakerAirMagnetic | GD-1 | AMCB Readings | Operations Counter AL | 466 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0422 | BreakerAirMagnetic | GD-1 | AMCB Readings | Operations This Read AM | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0422 | BreakerAirMagnetic | GD-1 | AMCB Readings | Switching Operations | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0422 | BreakerAirMagnetic | GD-1 | AMCB Readings | Unknown Operations | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0385 | BreakerAirMagnetic | GA-3 | AMCB Readings | Unknown Operations | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0385 | BreakerAirMagnetic | GA-3 | AMCB Readings | Switching Operations | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0385 | BreakerAirMagnetic | GA-3 | AMCB Readings | Operations Counter AL | 99939 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0385 | BreakerAirMagnetic | GA-3 | AMCB Readings | Operations Counter AF | 99939 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0516 | BreakerVacuum | IN-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AF | 201 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LTCC000039 | LTCControl | IN-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LTCC000039 | LTCControl | IN-TRANS 2 | LTC Control Insp | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0516 | BreakerVacuum | IN-12KV BUS TIE SEC 2 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0516 | BreakerVacuum | IN-12KV BUS TIE SEC 2 | VCB Readings | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0516 | BreakerVacuum | IN-12KV BUS TIE SEC 2 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0516 | BreakerVacuum | IN-12KV BUS TIE SEC 2 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0516 | BreakerVacuum | IN-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0516 | BreakerVacuum | IN-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0516 | BreakerVacuum | IN-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0516 | BreakerVacuum | IN-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0516 | BreakerVacuum | IN-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0516 | BreakerVacuum | IN-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0516 | BreakerVacuum | IN-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0516 | BreakerVacuum | IN-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0516 | BreakerVacuum | IN-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0516 | BreakerVacuum | IN-12KV BUS TIE SEC 2 | VCB Readings | Amps C Ø | 0.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0516 | BreakerVacuum | IN-12KV BUS TIE SEC 2 | VCB Readings | Amps B Ø | 0.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0516 | BreakerVacuum | IN-12KV BUS TIE SEC 2 | VCB Readings | Amps A Ø | 0.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0516 | BreakerVacuum | IN-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0516 | BreakerVacuum | IN-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0516 | BreakerVacuum | IN-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0516 | BreakerVacuum | IN-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0516 | BreakerVacuum | IN-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations | 2 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LTCC000039 | LTCControl | IN-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | ST000460 | Structure | 542-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | ST000460 | Structure | 542-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | ST000460 | Structure | 542-Structure | Structure Patrol Inspection | General Comments | | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | ST000460 | Structure | 542-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | ST000460 | Structure | 542-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | ST000460 | Structure | 542-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | ST000460 | Structure | 542-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LTCC000040 | LTCControl | IN-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LTCC000040 | LTCControl | IN-TRANS 1 | LTC Control Insp | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LTCC000040 | LTCControl | IN-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0424 | BreakerAirMagnetic | GD-3 | AMCB Readings | Operations Counter AL | 622 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0467 | BreakerVacuum | HI-1104 | VCB Readings | 9 Month Operations | 5 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0467 | BreakerVacuum | HI-1104 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0467 | BreakerVacuum | HI-1104 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0467 | BreakerVacuum | HI-1104 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0467 | BreakerVacuum | HI-1104 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0467 | BreakerVacuum | HI-1104 | VCB Readings | Amps A Ø | 75.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0467 | BreakerVacuum | HI-1104 | VCB Readings | Amps B Ø | 74.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0467 | BreakerVacuum | HI-1104 | VCB Readings | Amps C Ø | 98.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0467 | BreakerVacuum | HI-1104 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0467 | BreakerVacuum | HI-1104 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Readings | Winding Temp Present | 69 | °C |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Readings | Winding Temp Max | 73 | °C |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Readings | Totalizer Meter Reading | .9192 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Readings | Oil Temp Present | 55 | °C |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Readings | Oil Temp Max | 56 | °C |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Readings | LTC Totalizer Reading | 16545.60 | kw |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Readings | General Comments | | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0512 | BreakerVacuum | IN-1297 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0512 | BreakerVacuum | IN-1297 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0512 | BreakerVacuum | IN-1297 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0512 | BreakerVacuum | IN-1297 | VCB Readings | Amps A Ø | 0.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0512 | BreakerVacuum | IN-1297 | VCB Readings | Amps B Ø | 0.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0512 | BreakerVacuum | IN-1297 | VCB Readings | Amps C Ø | 0.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0512 | BreakerVacuum | IN-1297 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0512 | BreakerVacuum | IN-1297 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0512 | BreakerVacuum | IN-1297 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0512 | BreakerVacuum | IN-1297 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0512 | BreakerVacuum | IN-1297 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0512 | BreakerVacuum | IN-1297 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0512 | BreakerVacuum | IN-1297 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0512 | BreakerVacuum | IN-1297 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0553 | BreakerAirMagnetic | LG-3 | AMCB Readings | Unknown Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0512 | BreakerVacuum | IN-1297 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0512 | BreakerVacuum | IN-1297 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0512 | BreakerVacuum | IN-1297 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0512 | BreakerVacuum | IN-1297 | VCB Readings | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0512 | BreakerVacuum | IN-1297 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0512 | BreakerVacuum | IN-1297 | VCB Readings | Operations Counter AF | 162 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0512 | BreakerVacuum | IN-1297 | VCB Readings | Operations Counter AL | 162 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0385 | BreakerAirMagnetic | GA-3 | AMCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0385 | BreakerAirMagnetic | GA-3 | AMCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0385 | BreakerAirMagnetic | GA-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0385 | BreakerAirMagnetic | GA-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0385 | BreakerAirMagnetic | GA-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0385 | BreakerAirMagnetic | GA-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0385 | BreakerAirMagnetic | GA-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0385 | BreakerAirMagnetic | GA-3 | AMCB Readings | Amps C Ø | 140.0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0385 | BreakerAirMagnetic | GA-3 | AMCB Readings | Amps B Ø | 140.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0473 | BreakerAirMagnetic | HI-1474 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0473 | BreakerAirMagnetic | HI-1474 | AMCB Readings | 9 Months Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0473 | BreakerAirMagnetic | HI-1474 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0473 | BreakerAirMagnetic | HI-1474 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0473 | BreakerAirMagnetic | HI-1474 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0473 | BreakerAirMagnetic | HI-1474 | AMCB Readings | Amps A Ø | 4.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0473 | BreakerAirMagnetic | HI-1474 | AMCB Readings | Amps B Ø | 5.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0473 | BreakerAirMagnetic | HI-1474 | AMCB Readings | Amps C Ø | 7.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0473 | BreakerAirMagnetic | HI-1474 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0473 | BreakerAirMagnetic | HI-1474 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0473 | BreakerAirMagnetic | HI-1474 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0473 | BreakerAirMagnetic | HI-1474 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0385 | BreakerAirMagnetic | GA-3 | AMCB Readings | Amps A Ø | 100.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0473 | BreakerAirMagnetic | HI-1474 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0473 | BreakerAirMagnetic | HI-1474 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0473 | BreakerAirMagnetic | HI-1474 | AMCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0473 | BreakerAirMagnetic | HI-1474 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0473 | BreakerAirMagnetic | HI-1474 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0473 | BreakerAirMagnetic | HI-1474 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0473 | BreakerAirMagnetic | HI-1474 | AMCB Patrol Inspection | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0473 | BreakerAirMagnetic | HI-1474 | AMCB Readings | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0473 | BreakerAirMagnetic | HI-1474 | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0473 | BreakerAirMagnetic | HI-1474 | AMCB Readings | Operations Counter AF | 769 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0473 | BreakerAirMagnetic | HI-1474 | AMCB Readings | Operations Counter AL | 769 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0473 | BreakerAirMagnetic | HI-1474 | AMCB Readings | Operations This Read AM | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0473 | BreakerAirMagnetic | HI-1474 | AMCB Readings | Switching Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0473 | BreakerAirMagnetic | HI-1474 | AMCB Readings | Unknown Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0512 | BreakerVacuum | IN-1297 | VCB Readings | 9 Month Operations | 1 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0512 | BreakerVacuum | IN-1297 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | PF000236 | PowerFuse | KC-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | PF000236 | PowerFuse | KC-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | PF000236 | PowerFuse | KC-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | PF000244 | PowerFuse | MC-STA SER A 440V | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | PF000244 | PowerFuse | MC-STA SER A 440V | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | PF000244 | PowerFuse | MC-STA SER A 440V | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | PT000660 | PT | KC-34KV WEST BUS POT | PT Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0514 | BreakerVacuum | IN-1299 | VCB Readings | 9 Month Operations | 2 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0514 | BreakerVacuum | IN-1299 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0514 | BreakerVacuum | IN-1299 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0514 | BreakerVacuum | IN-1299 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0514 | BreakerVacuum | IN-1299 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0514 | BreakerVacuum | IN-1299 | VCB Readings | Amps A Ø | 0.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0514 | BreakerVacuum | IN-1299 | VCB Readings | Amps B Ø | 0.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0514 | BreakerVacuum | IN-1299 | VCB Readings | Amps C Ø | 0.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0514 | BreakerVacuum | IN-1299 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0514 | BreakerVacuum | IN-1299 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0514 | BreakerVacuum | IN-1299 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0514 | BreakerVacuum | IN-1299 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0514 | BreakerVacuum | IN-1299 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0514 | BreakerVacuum | IN-1299 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0514 | BreakerVacuum | IN-1299 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0514 | BreakerVacuum | IN-1299 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0514 | BreakerVacuum | IN-1299 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0514 | BreakerVacuum | IN-1299 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0514 | BreakerVacuum | IN-1299 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0514 | BreakerVacuum | IN-1299 | VCB Readings | General Comments | DNO | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0514 | BreakerVacuum | IN-1299 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0514 | BreakerVacuum | IN-1299 | VCB Readings | Operations Counter AF | 218 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0518 | BreakerVacuum | IN-12KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0518 | BreakerVacuum | IN-12KV TR 2 | VCB Readings | Amps A Ø | 209.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0518 | BreakerVacuum | IN-12KV TR 2 | VCB Readings | Amps B Ø | 209.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0518 | BreakerVacuum | IN-12KV TR 2 | VCB Readings | Amps C Ø | 209.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0518 | BreakerVacuum | IN-12KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0518 | BreakerVacuum | IN-12KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0518 | BreakerVacuum | IN-12KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0518 | BreakerVacuum | IN-12KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0424 | BreakerAirMagnetic | GD-3 | AMCB Readings | Amps A Ø | 100.0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0424 | BreakerAirMagnetic | GD-3 | AMCB Readings | Amps B Ø | 110.0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0424 | BreakerAirMagnetic | GD-3 | AMCB Readings | Amps C Ø | 105.0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0424 | BreakerAirMagnetic | GD-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0424 | BreakerAirMagnetic | GD-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0424 | BreakerAirMagnetic | GD-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0424 | BreakerAirMagnetic | GD-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0424 | BreakerAirMagnetic | GD-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0514 | BreakerVacuum | IN-1299 | VCB Readings | Operations Counter AL | 218 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0514 | BreakerVacuum | IN-1299 | VCB Readings | Operations This Read Vac | 2 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0514 | BreakerVacuum | IN-1299 | VCB Readings | Switching Operations | 2 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0514 | BreakerVacuum | IN-1299 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PF001318 | PowerFuse | LG-4KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PF001318 | PowerFuse | LG-4KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PF001318 | PowerFuse | LG-4KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | LTCC000950 | LTCControl | 379-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | LTCC000950 | LTCControl | 379-1 | LTC Control Insp | General Comments | | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | LTCC000950 | LTCControl | 379-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | LTCC000950 | LTCControl | 379-1 | LTC Control Insp | All Connections OK? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | LTCC000949 | LTCControl | 358-2 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | LTCC000949 | LTCControl | 358-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | LTCC000949 | LTCControl | 358-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | LTCC000949 | LTCControl | 358-2 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | LTCC000949 | LTCControl | 358-2 | LTC Control Insp | LTC Output Voltage Level | 124.7 | VAC |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | LTCC000949 | LTCControl | 358-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | LTCC000949 | LTCControl | 358-2 | LTC Control Insp | General Comments | | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | LTCC000949 | LTCControl | 358-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | LTCC000949 | LTCControl | 358-2 | LTC Control Insp | All Connections OK? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | ST000123 | Structure | 379-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | ST000123 | Structure | 379-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | ST000123 | Structure | 379-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | ST000123 | Structure | 379-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | ST000123 | Structure | 379-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | ST000123 | Structure | 379-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | ST000123 | Structure | 379-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | ST000123 | Structure | 379-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | ST000123 | Structure | 379-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | ST000123 | Structure | 379-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | ST000123 | Structure | 379-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | ST000123 | Structure | 379-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | ST000123 | Structure | 379-Structure | Structure Patrol Inspection | General Comments | | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | ST000123 | Structure | 379-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | ST000123 | Structure | 379-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | ST000123 | Structure | 379-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | ST000123 | Structure | 379-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | ST000123 | Structure | 379-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | ST000123 | Structure | 379-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | ST000123 | Structure | 379-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | ST000123 | Structure | 379-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | ST000123 | Structure | 379-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0518 | BreakerVacuum | IN-12KV TR 2 | VCB Readings | 9 Month Operations | 1 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | PT000660 | PT | KC-34KV WEST BUS POT | PT Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0518 | BreakerVacuum | IN-12KV TR 2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0518 | BreakerVacuum | IN-12KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0518 | BreakerVacuum | IN-12KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | PT000660 | PT | KC-34KV WEST BUS POT | PT Patrol Inspection | Tank Oil Level | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | PT000660 | PT | KC-34KV WEST BUS POT | PT Patrol Inspection | PT Free of Leaks? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | PT000660 | PT | KC-34KV WEST BUS POT | PT Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | PT000660 | PT | KC-34KV WEST BUS POT | PT Patrol Inspection | General Comments | | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | PT000660 | PT | KC-34KV WEST BUS POT | PT Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | PT000660 | PT | KC-34KV WEST BUS POT | PT Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | ST000460 | Structure | 542-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | ST000460 | Structure | 542-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | ST000460 | Structure | 542-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Readings | Amps A Ø | 92.0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Readings | Amps B Ø | 97.0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Readings | Amps C Ø | 114.0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | ST000460 | Structure | 542-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | ST000460 | Structure | 542-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Readings | General Comments | | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Readings | Operations Counter AF | 84 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Readings | Operations Counter AL | 84 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Readings | Operations This Read Vac | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Readings | Switching Operations | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | ST000460 | Structure | 542-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | ST000460 | Structure | 542-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | ST000460 | Structure | 542-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | ST000460 | Structure | 542-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | ST000460 | Structure | 542-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PF001317 | PowerFuse | LG-4KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PF001317 | PowerFuse | LG-4KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PF001317 | PowerFuse | LG-4KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PF001316 | PowerFuse | HA-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PF001316 | PowerFuse | HA-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PF001316 | PowerFuse | HA-4KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0424 | BreakerAirMagnetic | GD-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0424 | BreakerAirMagnetic | GD-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0518 | BreakerVacuum | IN-12KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0518 | BreakerVacuum | IN-12KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0518 | BreakerVacuum | IN-12KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0518 | BreakerVacuum | IN-12KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0518 | BreakerVacuum | IN-12KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0518 | BreakerVacuum | IN-12KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0518 | BreakerVacuum | IN-12KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0518 | BreakerVacuum | IN-12KV TR 2 | VCB Readings | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0518 | BreakerVacuum | IN-12KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0518 | BreakerVacuum | IN-12KV TR 2 | VCB Readings | Operations Counter AF | 161 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0518 | BreakerVacuum | IN-12KV TR 2 | VCB Readings | Operations Counter AL | 161 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0518 | BreakerVacuum | IN-12KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0518 | BreakerVacuum | IN-12KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0518 | BreakerVacuum | IN-12KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0424 | BreakerAirMagnetic | GD-3 | AMCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0424 | BreakerAirMagnetic | GD-3 | AMCB Readings | General Comments | | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0424 | BreakerAirMagnetic | GD-3 | AMCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0424 | BreakerAirMagnetic | GD-3 | AMCB Readings | Operations Counter AF | 622 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0516 | BreakerVacuum | IN-12KV BUS TIE SEC 2 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0516 | BreakerVacuum | IN-12KV BUS TIE SEC 2 | VCB Readings | Switching Operations | 1 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0516 | BreakerVacuum | IN-12KV BUS TIE SEC 2 | VCB Readings | Operations This Read Vac | 1 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | LTCMechanism | 542-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | LTCMechanism | 542-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | LTCMechanism | 542-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | LTCMechanism | 542-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | LTCMechanism | 542-1 | LTC Counter Readings | LTC Operations Since Last Insp | 1174 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | LTCMechanism | 542-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | LTCMechanism | 542-1 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | LTCMechanism | 542-1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | LTCMechanism | 542-1 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | LTCMechanism | 542-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | LTCMechanism | 542-1 | LTC Counter Readings | LTC As Left Counter | 235998 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | LTCMechanism | 542-1 | LTC Counter Readings | LTC As Found Counter | 235998 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | LTCMechanism | 542-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | LTCMechanism | 542-1 | LTC Counter Readings | General Comments | | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | LTCMechanism | 542-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | LTCMechanism | 542-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0516 | BreakerVacuum | IN-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AL | 201 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0061 | BreakerVacuum | 379-4614 | VCB Readings | 9 Month Operations | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Readings | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Readings | Operations Counter AF | 196 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Readings | Operations Counter AL | 197 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Readings | Operations This Read Vac | 2 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Readings | Switching Operations | 1 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Readings | Unknown Operations | 1 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Readings | 9 Month Operations | 1 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Readings | Amps A Ø | 15.0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Readings | Amps B Ø | 14.0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Readings | Amps C Ø | 12.0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0427 | BreakerAirMagnetic | GD-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0427 | BreakerAirMagnetic | GD-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0427 | BreakerAirMagnetic | GD-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0427 | BreakerAirMagnetic | GD-2 | AMCB Readings | Amps C Ø | 100.0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0427 | BreakerAirMagnetic | GD-2 | AMCB Readings | Amps B Ø | 60.0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0427 | BreakerAirMagnetic | GD-2 | AMCB Readings | Amps A Ø | 100.0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0427 | BreakerAirMagnetic | GD-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0427 | BreakerAirMagnetic | GD-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0427 | BreakerAirMagnetic | GD-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0427 | BreakerAirMagnetic | GD-2 | AMCB Readings | 9 Months Operations | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0427 | BreakerAirMagnetic | GD-2 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000126 | Switchgear | LG-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000126 | Switchgear | LG-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000126 | Switchgear | LG-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Readings | General Comments | | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Readings | Operations Counter AF | 38 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Readings | Operations Counter AL | 39 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Readings | Operations This Read Vac | 1 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Readings | Switching Operations | 1 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | YD000618 | Yard | GA-Yard | Yard Patrol Inspection | Ambient Temp | 64 | °F |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | YD000618 | Yard | GA-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Readings | Fault Operations | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0427 | BreakerAirMagnetic | GD-2 | AMCB Readings | Unknown Operations | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0427 | BreakerAirMagnetic | GD-2 | AMCB Readings | Switching Operations | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0427 | BreakerAirMagnetic | GD-2 | AMCB Readings | Operations This Read AM | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0427 | BreakerAirMagnetic | GD-2 | AMCB Readings | Operations Counter AL | 176 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0427 | BreakerAirMagnetic | GD-2 | AMCB Readings | Operations Counter AF | 176 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0427 | BreakerAirMagnetic | GD-2 | AMCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0427 | BreakerAirMagnetic | GD-2 | AMCB Readings | General Comments | | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0427 | BreakerAirMagnetic | GD-2 | AMCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0427 | BreakerAirMagnetic | GD-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0427 | BreakerAirMagnetic | GD-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0427 | BreakerAirMagnetic | GD-2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0427 | BreakerAirMagnetic | GD-2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Readings | 9 Month Operations | 2 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Readings | Amps A Ø | 0.0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Readings | Amps B Ø | 0.0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Readings | Amps C Ø | 0.0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Readings | Fault Adjusted Amps A Phase V | 6.13 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Readings | Fault Adjusted Amps B Phase V | 6.13 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0051 | BreakerVacuum | 540-2308 | VCB Readings | Fault Adjusted Amps C Phase V | 6.13 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000126 | Switchgear | LG-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000126 | Switchgear | LG-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000126 | Switchgear | LG-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000126 | Switchgear | LG-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000126 | Switchgear | LG-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000126 | Switchgear | LG-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000126 | Switchgear | LG-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000126 | Switchgear | LG-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | YD000466 | Yard | 540-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | YD000466 | Yard | 540-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | YD000466 | Yard | 540-Yard | Yard Patrol Inspection | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | YD000466 | Yard | 540-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | YD000466 | Yard | 540-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000126 | Switchgear | LG-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | PF000193 | PowerFuse | IN-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | PF000193 | PowerFuse | IN-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | PF000194 | PowerFuse | KC-34KV WEST BUS POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | PF000194 | PowerFuse | KC-34KV WEST BUS POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | PF000194 | PowerFuse | KC-34KV WEST BUS POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0464 | BreakerVacuum | HI-1101 | VCB Readings | 9 Month Operations | 1 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0464 | BreakerVacuum | HI-1101 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0464 | BreakerVacuum | HI-1101 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0464 | BreakerVacuum | HI-1101 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0464 | BreakerVacuum | HI-1101 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | YD000466 | Yard | 540-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | YD000466 | Yard | 540-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0464 | BreakerVacuum | HI-1101 | VCB Readings | Amps A Ø | 92.0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | YD000586 | Yard | LG-Yard | Yard Patrol Inspection | Ambient Temp | 65 | °F |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | YD000586 | Yard | LG-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | YD000586 | Yard | LG-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | YD000586 | Yard | LG-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | YD000586 | Yard | LG-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | YD000586 | Yard | LG-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0464 | BreakerVacuum | HI-1101 | VCB Readings | Amps B Ø | 94.0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | PF000247 | PowerFuse | MC-208/120 STA SER A | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | PF000247 | PowerFuse | MC-208/120 STA SER A | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | PF000247 | PowerFuse | MC-208/120 STA SER A | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | PF000162 | PowerFuse | HI-14KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | PF000162 | PowerFuse | HI-14KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | PF000163 | PowerFuse | HI-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | PF000163 | PowerFuse | HI-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | PF000164 | PowerFuse | HI-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | PF000164 | PowerFuse | HI-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0470 | BreakerVacuum | HI-12KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | YD000586 | Yard | LG-Yard | Yard Patrol Inspection | General Comments | | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000126 | Switchgear | LG-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000126 | Switchgear | LG-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000126 | Switchgear | LG-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Readings | General Comments | | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Patrol Inspection | General Comments | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | YD000466 | Yard | 540-Yard | Yard Patrol Inspection | Ambient Temp | 67 | °F |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Readings | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Readings | Operations Counter AF | 188 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Readings | Operations Counter AL | 189 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Readings | Operations This Read Vac | 1 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | YD000466 | Yard | 540-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | YD000466 | Yard | 540-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | YD000466 | Yard | 540-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | YD000466 | Yard | 540-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | YD000466 | Yard | 540-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Readings | Switching Operations | 1 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0121 | BreakerVacuum | 540-2306 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | YD000466 | Yard | 540-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | YD000466 | Yard | 540-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | SWG000126 | Switchgear | LG-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | ST000108 | Structure | 358-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | ST000108 | Structure | 358-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | ST000108 | Structure | 358-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | ST000108 | Structure | 358-Structure | Structure Patrol Inspection | General Comments | | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | ST000108 | Structure | 358-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | ST000108 | Structure | 358-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0553 | BreakerAirMagnetic | LG-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0553 | BreakerAirMagnetic | LG-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0553 | BreakerAirMagnetic | LG-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0553 | BreakerAirMagnetic | LG-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0553 | BreakerAirMagnetic | LG-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0553 | BreakerAirMagnetic | LG-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0553 | BreakerAirMagnetic | LG-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0553 | BreakerAirMagnetic | LG-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | ST000108 | Structure | 358-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | ST000108 | Structure | 358-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0512 | BreakerVacuum | IN-1297 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0512 | BreakerVacuum | IN-1297 | VCB Readings | Switching Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0553 | BreakerAirMagnetic | LG-3 | AMCB Readings | Amps C Ø | 75.0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0553 | BreakerAirMagnetic | LG-3 | AMCB Readings | Amps B Ø | 10.0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0553 | BreakerAirMagnetic | LG-3 | AMCB Readings | Amps A Ø | 100.0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0553 | BreakerAirMagnetic | LG-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | LTCMechanism | 540-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 26 | °C |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | LTCMechanism | 540-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 32 | °C |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | LTCMechanism | 540-2 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | LTCMechanism | 540-2 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | LTCMechanism | 540-2 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | LTCMechanism | 540-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | LTCMechanism | 540-2 | LTC Counter Readings | LTC As Left Counter | 67921 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | LTCMechanism | 540-2 | LTC Counter Readings | LTC As Found Counter | 67921 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | LTCMechanism | 540-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | LTCMechanism | 540-2 | LTC Counter Readings | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | LTCMechanism | 540-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | LTCMechanism | 540-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0553 | BreakerAirMagnetic | LG-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0553 | BreakerAirMagnetic | LG-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0553 | BreakerAirMagnetic | LG-3 | AMCB Readings | 9 Months Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0553 | BreakerAirMagnetic | LG-3 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0512 | BreakerVacuum | IN-1297 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | ST000108 | Structure | 358-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | ST000108 | Structure | 358-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | ST000108 | Structure | 358-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | ST000108 | Structure | 358-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | ST000108 | Structure | 358-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | YD000102 | Yard | 358-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | YD000102 | Yard | 358-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | ST000108 | Structure | 358-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | ST000108 | Structure | 358-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | ST000108 | Structure | 358-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | ST000108 | Structure | 358-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | ST000108 | Structure | 358-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0553 | BreakerAirMagnetic | LG-3 | AMCB Readings | Switching Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0553 | BreakerAirMagnetic | LG-3 | AMCB Readings | Operations This Read AM | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0553 | BreakerAirMagnetic | LG-3 | AMCB Readings | Operations Counter AL | 365 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0553 | BreakerAirMagnetic | LG-3 | AMCB Readings | Operations Counter AF | 365 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | ST000460 | Structure | 542-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | ST000460 | Structure | 542-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | ST000460 | Structure | 542-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | ST000460 | Structure | 542-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | ST000460 | Structure | 542-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | YD000458 | Yard | 542-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | YD000458 | Yard | 542-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | YD000458 | Yard | 542-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | YD000458 | Yard | 542-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | YD000458 | Yard | 542-Yard | Yard Patrol Inspection | General Comments | | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | YD000458 | Yard | 542-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | YD000458 | Yard | 542-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | YD000458 | Yard | 542-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | YD000458 | Yard | 542-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | YD000458 | Yard | 542-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | LTCMechanism | 540-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | LTCMechanism | 540-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | LTCMechanism | 540-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | LTCMechanism | 540-2 | LTC Counter Readings | LTC Operations Since Last Insp | 1171 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0553 | BreakerAirMagnetic | LG-3 | AMCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0553 | BreakerAirMagnetic | LG-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0553 | BreakerAirMagnetic | LG-3 | AMCB Readings | General Comments | | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0553 | BreakerAirMagnetic | LG-3 | AMCB Patrol Inspection | General Comments | | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0553 | BreakerAirMagnetic | LG-3 | AMCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0553 | BreakerAirMagnetic | LG-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | ST000108 | Structure | 358-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | ST000108 | Structure | 358-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | ST000108 | Structure | 358-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | ST000108 | Structure | 358-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Readings | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Readings | Operations Counter AF | 191 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Readings | Operations Counter AL | 192 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Readings | Operations This Read Vac | 1 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Readings | Switching Operations | 1 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Readings | Amps A Ø | 10.0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Readings | Amps B Ø | 11.0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Readings | Amps C Ø | 10.0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | PF000174 | PowerFuse | IN-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | PF000174 | PowerFuse | IN-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | YD000102 | Yard | 358-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | YD000102 | Yard | 358-Yard | Yard Patrol Inspection | General Comments | | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | YD000102 | Yard | 358-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | YD000102 | Yard | 358-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | YD000102 | Yard | 358-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | YD000102 | Yard | 358-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | YD000102 | Yard | 358-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | YD000102 | Yard | 358-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | YD000102 | Yard | 358-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | YD000102 | Yard | 358-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | YD000102 | Yard | 358-Yard | Yard Patrol Inspection | Ambient Temp | 58 | °F |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | YD000458 | Yard | 542-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | YD000458 | Yard | 542-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | YD000458 | Yard | 542-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | YD000458 | Yard | 542-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | YD000458 | Yard | 542-Yard | Yard Patrol Inspection | Ambient Temp | 66 | °F |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Readings | 9 Month Operations | 1 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK001743 | BreakerSF6 | KC-138KV TR 1 | GCB Patrol Inspection | Ambient Temperature | 65 | °F |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | C0539 | WithLTC | 542-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Readings | 9 Month Operations | 3 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Readings | Amps A Ø | 174.0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Readings | Amps B Ø | 200.0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Readings | Amps C Ø | 176.0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | CB0298 | BreakerVacuum | 542-0342 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0055 | BreakerVacuum | 540-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Readings | 9 Month Operations | 5 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Readings | Amps A Ø | 280.0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Readings | Amps B Ø | 220.0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Readings | Amps C Ø | 260.0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Readings | Fault Operations Ground | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Readings | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | LTCMechanism | 379-1 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | LTCMechanism | 379-1 | LTC Counter Readings | LTC Max Tap Position | 5R | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | LTCMechanism | 379-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | LTCMechanism | 379-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | LTCMechanism | 379-1 | LTC Counter Readings | LTC As Left Counter | 113107 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | LTCMechanism | 379-1 | LTC Counter Readings | LTC As Found Counter | 113105 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | LTCMechanism | 379-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | LTCMechanism | 379-1 | LTC Counter Readings | General Comments | | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | LTCMechanism | 379-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | LTCMechanism | 379-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Readings | General Comments | | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Readings | General Comments | | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Readings | Operations Counter AF | 99965 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Readings | Operations Counter AL | 99965 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Readings | Operations This Read Vac | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Readings | Switching Operations | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0383 | BreakerAirMagnetic | GA-1 | AMCB Readings | Unknown Operations | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0383 | BreakerAirMagnetic | GA-1 | AMCB Readings | Switching Operations | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0383 | BreakerAirMagnetic | GA-1 | AMCB Readings | Operations Counter AL | 400 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0383 | BreakerAirMagnetic | GA-1 | AMCB Readings | Operations Counter AF | 400 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | LTCMechanism | 358-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 27 | °C |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Readings | Amps C Ø | 106.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Readings | Amps B Ø | 121.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Readings | Amps A Ø | 118.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | BCH001092 | Charger | HI-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | BCH001092 | Charger | HI-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | BCH001092 | Charger | HI-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | BCH001092 | Charger | HI-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | BCH001092 | Charger | HI-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 8.1 | amps |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | BCH001092 | Charger | HI-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 155.00 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 25 | °C |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 20 | °C |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | LTCMechanism | HI-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | LTCMechanism | 379-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | LTCMechanism | 379-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | LTCMechanism | 379-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | LTCMechanism | 379-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Needs Replaced | check oil cup |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | LTCMechanism | 379-1 | LTC Counter Readings | LTC Operations Since Last Insp | 555 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | O0238 | LTCMechanism | 379-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | BCH001092 | Charger | HI-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | BCH001092 | Charger | HI-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 75 | °C |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 80 | °C |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 70 | °C |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BCH001578 | Charger | 542-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BCH001578 | Charger | 542-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BCH001578 | Charger | 542-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BCH001578 | Charger | 542-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BCH001578 | Charger | 542-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.0 | amps |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BCH001578 | Charger | 542-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BCH001578 | Charger | 542-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BCH001578 | Charger | 542-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Readings | Switching Operations | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | LTCC000693 | LTCControl | 540-1 | LTC Control Insp | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | LTCC000693 | LTCControl | 540-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | LTCC000693 | LTCControl | 540-1 | LTC Control Insp | LTC Output Voltage Level | 123.7 | VAC |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | LTCC000693 | LTCControl | 540-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | LTCC000693 | LTCControl | 540-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | BCH001037 | Charger | LG-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | BCH001037 | Charger | LG-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | BCH001037 | Charger | LG-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | BCH001037 | Charger | LG-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 0.0 | amps |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | BCH001037 | Charger | LG-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.7 | VDC |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | LTCC000693 | LTCControl | 540-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0511 | BreakerVacuum | IN-1296 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | BCH001037 | Charger | LG-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.7 | VDC |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | BCH001037 | Charger | LG-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Readings | Operations Counter AL | 96 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | PF001247 | PowerFuse | MC-208/120 STA SER B | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | PF001247 | PowerFuse | MC-208/120 STA SER B | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0383 | BreakerAirMagnetic | GA-1 | AMCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0383 | BreakerAirMagnetic | GA-1 | AMCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0383 | BreakerAirMagnetic | GA-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0383 | BreakerAirMagnetic | GA-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0383 | BreakerAirMagnetic | GA-1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0383 | BreakerAirMagnetic | GA-1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0383 | BreakerAirMagnetic | GA-1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0383 | BreakerAirMagnetic | GA-1 | AMCB Readings | Amps C Ø | 100.0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0383 | BreakerAirMagnetic | GA-1 | AMCB Readings | Amps B Ø | 130.0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0383 | BreakerAirMagnetic | GA-1 | AMCB Readings | Amps A Ø | 100.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Readings | Operations Counter AF | 96 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Readings | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | LTCMechanism | 358-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | LTCMechanism | 358-2 | LTC Counter Readings | General Comments | | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | LTCMechanism | 358-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | LTCMechanism | 358-2 | LTC Counter Readings | LTC As Found Counter | 14419 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | LTCMechanism | 358-2 | LTC Counter Readings | LTC As Left Counter | 14421 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | LTCMechanism | 358-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | LTCMechanism | 358-2 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | LTCMechanism | 358-2 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | LTCMechanism | 358-2 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | LTCMechanism | 358-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | LTCMechanism | 358-2 | LTC Counter Readings | LTC Operations Since Last Insp | 480 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0471 | BreakerAirMagnetic | HI-1472 | AMCB Readings | Unknown Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0471 | BreakerAirMagnetic | HI-1472 | AMCB Readings | Switching Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0471 | BreakerAirMagnetic | HI-1472 | AMCB Readings | Operations This Read AM | 2 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0471 | BreakerAirMagnetic | HI-1472 | AMCB Readings | Operations Counter AL | 819 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0471 | BreakerAirMagnetic | HI-1472 | AMCB Readings | Operations Counter AF | 819 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0471 | BreakerAirMagnetic | HI-1472 | AMCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0471 | BreakerAirMagnetic | HI-1472 | AMCB Readings | General Comments | B Phase IOC | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0471 | BreakerAirMagnetic | HI-1472 | AMCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0471 | BreakerAirMagnetic | HI-1472 | AMCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0471 | BreakerAirMagnetic | HI-1472 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0471 | BreakerAirMagnetic | HI-1472 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0471 | BreakerAirMagnetic | HI-1472 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0471 | BreakerAirMagnetic | HI-1472 | AMCB Readings | Fault Operations B Ø | 2 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0471 | BreakerAirMagnetic | HI-1472 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0471 | BreakerAirMagnetic | HI-1472 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0471 | BreakerAirMagnetic | HI-1472 | AMCB Readings | Fault Adjusted Amps B Phase AM | 16.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0471 | BreakerAirMagnetic | HI-1472 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0471 | BreakerAirMagnetic | HI-1472 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0471 | BreakerAirMagnetic | HI-1472 | AMCB Readings | Amps C Ø | 57.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0471 | BreakerAirMagnetic | HI-1472 | AMCB Readings | Amps B Ø | 54.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0471 | BreakerAirMagnetic | HI-1472 | AMCB Readings | Amps A Ø | 60.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0471 | BreakerAirMagnetic | HI-1472 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0471 | BreakerAirMagnetic | HI-1472 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0471 | BreakerAirMagnetic | HI-1472 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0471 | BreakerAirMagnetic | HI-1472 | AMCB Readings | 9 Months Operations | 6 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0471 | BreakerAirMagnetic | HI-1472 | AMCB Readings | 9 Month Ops New | 4 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | LTCMechanism | 358-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | LTCMechanism | 358-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | LTCMechanism | 358-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | LTCMechanism | 358-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Readings | Maintenance Operations | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Readings | Operations Counter AF | 44 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Readings | Operations Counter AL | 44 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0468 | BreakerVacuum | HI-1105 | VCB Readings | 9 Month Operations | 5 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0468 | BreakerVacuum | HI-1105 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0468 | BreakerVacuum | HI-1105 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0468 | BreakerVacuum | HI-1105 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0468 | BreakerVacuum | HI-1105 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | LTCC000693 | LTCControl | 540-1 | LTC Control Insp | All Connections OK? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | LTCC000693 | LTCControl | 540-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0557 | BreakerAirMagnetic | LG-SEC 1 SPARE | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0557 | BreakerAirMagnetic | LG-SEC 1 SPARE | AMCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0557 | BreakerAirMagnetic | LG-SEC 1 SPARE | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0557 | BreakerAirMagnetic | LG-SEC 1 SPARE | AMCB Patrol Inspection | General Comments | | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0557 | BreakerAirMagnetic | LG-SEC 1 SPARE | AMCB Readings | General Comments | | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0557 | BreakerAirMagnetic | LG-SEC 1 SPARE | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0557 | BreakerAirMagnetic | LG-SEC 1 SPARE | AMCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0557 | BreakerAirMagnetic | LG-SEC 1 SPARE | AMCB Readings | Operations Counter AF | 272 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Readings | Switching Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0557 | BreakerAirMagnetic | LG-SEC 1 SPARE | AMCB Readings | Operations Counter AL | 272 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0557 | BreakerAirMagnetic | LG-SEC 1 SPARE | AMCB Readings | Operations This Read AM | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0557 | BreakerAirMagnetic | LG-SEC 1 SPARE | AMCB Readings | Switching Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0557 | BreakerAirMagnetic | LG-SEC 1 SPARE | AMCB Readings | Unknown Operations | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Readings | Operations This Read Vac | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Readings | Operations Counter AL | 303 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Readings | Operations Counter AF | 303 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Readings | General Comments | | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Readings | Amps C Ø | 35.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Readings | Amps B Ø | 38.0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Readings | Amps A Ø | 37.0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | LTCMechanism | HI-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | LTCMechanism | HI-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | LTCMechanism | HI-TRANS 2 | LTC Counter Readings | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | LTCMechanism | HI-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | LTCMechanism | HI-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 35573 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | LTCMechanism | HI-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 35573 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BAT001390 | Battery | 358-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 62 | °F |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BAT001390 | Battery | 358-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | LTCMechanism | HA-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | LTCMechanism | HA-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 633 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | LTCMechanism | HA-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Readings | Switching Operations | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | LTCMechanism | 540-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BAT001630 | Battery | 542-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BAT001630 | Battery | 542-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BAT001630 | Battery | 542-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.7 | VDC |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BAT001630 | Battery | 542-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.7 | VDC |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BAT001630 | Battery | 542-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BAT001630 | Battery | 542-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BAT001630 | Battery | 542-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BAT001630 | Battery | 542-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BAT001630 | Battery | 542-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BAT001630 | Battery | 542-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BAT001630 | Battery | 542-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BAT001630 | Battery | 542-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 66 | °F |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | BAT001630 | Battery | 542-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0384 | BreakerAirMagnetic | GA-2 | AMCB Readings | Amps A Ø | 25.0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0384 | BreakerAirMagnetic | GA-2 | AMCB Readings | Amps B Ø | 25.0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0384 | BreakerAirMagnetic | GA-2 | AMCB Readings | Amps C Ø | 25.0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0384 | BreakerAirMagnetic | GA-2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0384 | BreakerAirMagnetic | GA-2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0384 | BreakerAirMagnetic | GA-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0384 | BreakerAirMagnetic | GA-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0384 | BreakerAirMagnetic | GA-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0384 | BreakerAirMagnetic | GA-2 | AMCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0384 | BreakerAirMagnetic | GA-2 | AMCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0384 | BreakerAirMagnetic | GA-2 | AMCB Readings | Operations Counter AF | 224 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0384 | BreakerAirMagnetic | GA-2 | AMCB Readings | Operations Counter AL | 224 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0384 | BreakerAirMagnetic | GA-2 | AMCB Readings | Switching Operations | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0384 | BreakerAirMagnetic | GA-2 | AMCB Readings | Unknown Operations | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Readings | 9 Month Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0557 | BreakerAirMagnetic | LG-SEC 1 SPARE | AMCB Readings | 9 Month Ops New | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0557 | BreakerAirMagnetic | LG-SEC 1 SPARE | AMCB Readings | 9 Months Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0557 | BreakerAirMagnetic | LG-SEC 1 SPARE | AMCB Readings | Amps A Ø | 0.0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0557 | BreakerAirMagnetic | LG-SEC 1 SPARE | AMCB Readings | Amps B Ø | 0.0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0557 | BreakerAirMagnetic | LG-SEC 1 SPARE | AMCB Readings | Amps C Ø | 0.0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0557 | BreakerAirMagnetic | LG-SEC 1 SPARE | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0557 | BreakerAirMagnetic | LG-SEC 1 SPARE | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0557 | BreakerAirMagnetic | LG-SEC 1 SPARE | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0557 | BreakerAirMagnetic | LG-SEC 1 SPARE | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0557 | BreakerAirMagnetic | LG-SEC 1 SPARE | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0557 | BreakerAirMagnetic | LG-SEC 1 SPARE | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | LTCMechanism | GA-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Readings | 9 Month Operations | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Readings | Operations Counter AF | 64 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Readings | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Readings | Fault Operations C Ø | 5 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Readings | Fault Adjusted Amps C Phase V | 55.90 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | LTCMechanism | GA-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 504941 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | LTCMechanism | GA-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 504941 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | LTCMechanism | GA-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | LTCMechanism | GA-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | LTCMechanism | GA-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 3L | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | LTCMechanism | GA-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 714 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | LTCMechanism | GA-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | LTCMechanism | HI-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | LTCMechanism | HI-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN21 | WithLTC | GD-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | LTCMechanism | HI-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | LTCMechanism | HI-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | LTCMechanism | HI-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | LTCMechanism | HI-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | LTCMechanism | HI-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 347 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | LTCMechanism | HI-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | LTCMechanism | HI-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | LTCMechanism | HI-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0091 | LTCMechanism | HI-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | LTCMechanism | HI-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | LTCMechanism | HI-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | LTCMechanism | HI-TRANS 1 | LTC Counter Readings | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | LTCMechanism | HI-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | LTCMechanism | HI-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 195604 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | LTCMechanism | HI-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 195604 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | LTCMechanism | HI-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | LTCMechanism | HI-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | LTCMechanism | HI-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 5L | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | LTCMechanism | HI-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Readings | 9 Month Operations | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Readings | Amps A Ø | 101.0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Readings | Amps B Ø | 108.0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Readings | Amps C Ø | 99.0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | DB0063 | BreakerVacuum | 379-4613 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | K0012 | BreakerVacuum | 379-0772 | VCB Readings | 9 Month Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | LTCMechanism | HI-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | LTCMechanism | HI-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 34 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | LTCMechanism | GA-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Readings | Operations This Read Vac | 5 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001383 | BreakerVacuum | IN-1291 | VCB Readings | Operations Counter AL | 64 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Readings | Operations This Read Vac | 1 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Readings | Switching Operations | 1 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Readings | Unknown Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | needs nitrogen | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Readings | Operations Counter AF | 184 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Readings | Operations Counter AL | 184 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Readings | Operations This Read Vac | 0 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Readings | Switching Operations | 0 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0468 | BreakerVacuum | HI-1105 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0468 | BreakerVacuum | HI-1105 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0468 | BreakerVacuum | HI-1105 | VCB Readings | Fault Operations Ground | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0468 | BreakerVacuum | HI-1105 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0468 | BreakerVacuum | HI-1105 | VCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0468 | BreakerVacuum | HI-1105 | VCB Patrol Inspection | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0468 | BreakerVacuum | HI-1105 | VCB Readings | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0468 | BreakerVacuum | HI-1105 | VCB Readings | Maintenance Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0468 | BreakerVacuum | HI-1105 | VCB Readings | Operations Counter AF | 713 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0468 | BreakerVacuum | HI-1105 | VCB Readings | Operations Counter AL | 713 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0468 | BreakerVacuum | HI-1105 | VCB Readings | Operations This Read Vac | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0468 | BreakerVacuum | HI-1105 | VCB Readings | Switching Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0468 | BreakerVacuum | HI-1105 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0511 | BreakerVacuum | IN-1296 | VCB Readings | Amps C Ø | 0.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LTCC000432 | LTCControl | HI-TRANS 1 | LTC Control Insp | General Comments | OK | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LTCC000432 | LTCControl | HI-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0511 | BreakerVacuum | IN-1296 | VCB Readings | Amps B Ø | 0.0 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Readings | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Readings | Operations Counter AF | 215 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0511 | BreakerVacuum | IN-1296 | VCB Readings | Amps A Ø | 0.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0511 | BreakerVacuum | IN-1296 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0511 | BreakerVacuum | IN-1296 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0511 | BreakerVacuum | IN-1296 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0511 | BreakerVacuum | IN-1296 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Readings | Operations Counter AL | 216 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0511 | BreakerVacuum | IN-1296 | VCB Readings | 9 Month Operations | 0 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Readings | General Comments | | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Readings | Amps B Ø | 129.0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Readings | Amps C Ø | 125.0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Readings | Totalizer Meter Reading | .5208 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Readings | General Comments | | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Readings | LTC Totalizer Reading | 4999.68 | kw |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Readings | 9 Month Operations | 1 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | S0001 | WithLTC | 358-2 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Readings | Amps C Ø | 166.0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Readings | Amps B Ø | 177.0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Readings | Amps A Ø | 166.0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0513 | BreakerVacuum | IN-1298 | VCB Readings | 9 Month Operations | 2 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0513 | BreakerVacuum | IN-1298 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0513 | BreakerVacuum | IN-1298 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0513 | BreakerVacuum | IN-1298 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0513 | BreakerVacuum | IN-1298 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0513 | BreakerVacuum | IN-1298 | VCB Readings | Amps A Ø | 23.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0513 | BreakerVacuum | IN-1298 | VCB Readings | Amps B Ø | 24.0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Readings | Switching Operations | 1 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Readings | Operations This Read Vac | 1 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Readings | Operations Counter AL | 213 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Readings | Operations Counter AF | 212 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0513 | BreakerVacuum | IN-1298 | VCB Readings | Amps C Ø | 23.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 45 | °C |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0513 | BreakerVacuum | IN-1298 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0513 | BreakerVacuum | IN-1298 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0513 | BreakerVacuum | IN-1298 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | LTCC000032 | LTCControl | 540-2 | LTC Control Insp | LTC Output Voltage Level | 124.7 | VAC |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | LTCC000032 | LTCControl | 540-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | LTCC000032 | LTCControl | 540-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | LTCC000032 | LTCControl | 540-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0092 | WithLTC | HI-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 45 | °C |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Readings | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Readings | 9 Month Operations | 1 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0052 | BreakerVacuum | 540-2238 | VCB Readings | Amps A Ø | 122.0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0551 | BreakerAirMagnetic | LG-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0551 | BreakerAirMagnetic | LG-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0551 | BreakerAirMagnetic | LG-1 | AMCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0551 | BreakerAirMagnetic | LG-1 | AMCB Patrol Inspection | General Comments | | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0551 | BreakerAirMagnetic | LG-1 | AMCB Readings | General Comments | | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0551 | BreakerAirMagnetic | LG-1 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0551 | BreakerAirMagnetic | LG-1 | AMCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0551 | BreakerAirMagnetic | LG-1 | AMCB Readings | Operations Counter AF | 196 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0551 | BreakerAirMagnetic | LG-1 | AMCB Readings | Operations Counter AL | 196 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0551 | BreakerAirMagnetic | LG-1 | AMCB Readings | Operations This Read AM | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0551 | BreakerAirMagnetic | LG-1 | AMCB Readings | Switching Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0551 | BreakerAirMagnetic | LG-1 | AMCB Readings | Unknown Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .8 | psi |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Readings | Switching Operations | 1 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Readings | Operations This Read Vac | 1 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Readings | Operations Counter AL | 207 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Readings | Operations Counter AF | 206 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Readings | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0511 | BreakerVacuum | IN-1296 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | PF001247 | PowerFuse | MC-208/120 STA SER B | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | PF001248 | PowerFuse | MC-STA SER B 440V | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0511 | BreakerVacuum | IN-1296 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0511 | BreakerVacuum | IN-1296 | VCB Readings | Operations This Read Vac | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0511 | BreakerVacuum | IN-1296 | VCB Readings | Operations Counter AL | 150 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0511 | BreakerVacuum | IN-1296 | VCB Readings | Operations Counter AF | 150 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0511 | BreakerVacuum | IN-1296 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0511 | BreakerVacuum | IN-1296 | VCB Readings | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0511 | BreakerVacuum | IN-1296 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0511 | BreakerVacuum | IN-1296 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0511 | BreakerVacuum | IN-1296 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | PF001248 | PowerFuse | MC-STA SER B 440V | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | PF001248 | PowerFuse | MC-STA SER B 440V | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Readings | Amps C Ø | 64.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Readings | Amps B Ø | 65.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Readings | Amps A Ø | 72.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | BK001382 | BreakerVacuum | IN-1290 | VCB Readings | 9 Month Operations | 6 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0511 | BreakerVacuum | IN-1296 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0511 | BreakerVacuum | IN-1296 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0511 | BreakerVacuum | IN-1296 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Readings | Operations This Read Vac | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001356 | BreakerVacuum | MC-12KV TR 9 | VCB Readings | Switching Operations | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0551 | BreakerAirMagnetic | LG-1 | AMCB Readings | 9 Month Ops New | 1 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0551 | BreakerAirMagnetic | LG-1 | AMCB Readings | 9 Months Operations | 1 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0551 | BreakerAirMagnetic | LG-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0551 | BreakerAirMagnetic | LG-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0551 | BreakerAirMagnetic | LG-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0551 | BreakerAirMagnetic | LG-1 | AMCB Readings | Amps A Ø | 120.0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0551 | BreakerAirMagnetic | LG-1 | AMCB Readings | Amps B Ø | 190.0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0551 | BreakerAirMagnetic | LG-1 | AMCB Readings | Amps C Ø | 120.0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0551 | BreakerAirMagnetic | LG-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0551 | BreakerAirMagnetic | LG-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0551 | BreakerAirMagnetic | LG-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0259 | GroundTransformer | HI-GND TR 1 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0259 | GroundTransformer | HI-GND TR 1 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0259 | GroundTransformer | HI-GND TR 1 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0259 | GroundTransformer | HI-GND TR 1 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0259 | GroundTransformer | HI-GND TR 1 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0259 | GroundTransformer | HI-GND TR 1 | Ground Transformer Patrol Inspection | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0259 | GroundTransformer | HI-GND TR 1 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0259 | GroundTransformer | HI-GND TR 1 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LT0259 | GroundTransformer | HI-GND TR 1 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0551 | BreakerAirMagnetic | LG-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0551 | BreakerAirMagnetic | LG-1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0551 | BreakerAirMagnetic | LG-1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | LB0551 | BreakerAirMagnetic | LG-1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 0 | °C |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 0 | °C |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 0 | °C |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Readings | 9 Month Operations | 2 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | LTCC000032 | LTCControl | 540-2 | LTC Control Insp | All Connections OK? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | LTCC000032 | LTCControl | 540-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | LTCC000032 | LTCControl | 540-2 | LTC Control Insp | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | LTCC000032 | LTCControl | 540-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Readings | 9 Month Operations | 4 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Readings | Amps A Ø | 117.0 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Readings | Amps B Ø | 117.0 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Readings | Amps C Ø | 114.0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Readings | Amps A Ø | 24.0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Readings | Amps B Ø | 24.0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Readings | Amps C Ø | 24.0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0513 | BreakerVacuum | IN-1298 | VCB Patrol Inspection | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0513 | BreakerVacuum | IN-1298 | VCB Readings | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0513 | BreakerVacuum | IN-1298 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0513 | BreakerVacuum | IN-1298 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0513 | BreakerVacuum | IN-1298 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0513 | BreakerVacuum | IN-1298 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0513 | BreakerVacuum | IN-1298 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0513 | BreakerVacuum | IN-1298 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0468 | BreakerVacuum | HI-1105 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0468 | BreakerVacuum | HI-1105 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0468 | BreakerVacuum | HI-1105 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0468 | BreakerVacuum | HI-1105 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0468 | BreakerVacuum | HI-1105 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BK000544 | BreakerVacuum | 358-4721 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001261 | BreakerVacuum | 540-0335 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0511 | BreakerVacuum | IN-1296 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0511 | BreakerVacuum | IN-1296 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | BK001262 | BreakerVacuum | 540-2307 | VCB Readings | Fault Operations Ground | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0511 | BreakerVacuum | IN-1296 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0511 | BreakerVacuum | IN-1296 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0468 | BreakerVacuum | HI-1105 | VCB Readings | Amps A Ø | 95.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0468 | BreakerVacuum | HI-1105 | VCB Readings | Amps B Ø | 95.0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | LB0468 | BreakerVacuum | HI-1105 | VCB Readings | Amps C Ø | 93.0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN37 | WithLTC | LG-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 0 | °C |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 0 | °C |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | PN48 | WithLTC | LG-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 0 | °C |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Readings | Amps C Ø | 41.0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Readings | Amps B Ø | 40.0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Readings | Amps A Ø | 37.0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Readings | 9 Month Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Readings | Switching Operations | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Readings | Operations This Read Vac | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Readings | Operations Counter AL | 277 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Readings | Operations Counter AF | 277 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Readings | General Comments | | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | LTCC000734 | LTCControl | 358-1 | LTC Control Insp | All Connections OK? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | LTCC000734 | LTCControl | 358-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Readings | Amps A Ø | 289.0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Readings | Oil Temp Max | 44 | °C |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Readings | LTC Totalizer Reading | 11871.36 | kw |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | LTCC000734 | LTCControl | 358-1 | LTC Control Insp | General Comments | | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | LTCC000734 | LTCControl | 358-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | LTCC000734 | LTCControl | 358-1 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | LTCC000734 | LTCControl | 358-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | LTCC000734 | LTCControl | 358-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | LTCC000734 | LTCControl | 358-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Readings | Switching Operations | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | LTCMechanism | GD-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | LTCMechanism | GD-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 419952 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | LTCMechanism | GD-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 419952 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | CH000188 | ControlHouse | IN-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | CH000188 | ControlHouse | IN-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | CH000188 | ControlHouse | IN-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | CH000188 | ControlHouse | IN-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | LTCMechanism | GD-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Readings | Operations Counter AL | 189 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Readings | Operations Counter AF | 189 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Readings | Winding Temp Present | 35 | °C |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Readings | Winding Temp Max | 50 | °C |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Readings | Totalizer Meter Reading | .8244 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | CH000188 | ControlHouse | IN-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | CH000188 | ControlHouse | IN-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | CH000188 | ControlHouse | IN-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | CH000188 | ControlHouse | IN-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | CH000188 | ControlHouse | IN-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | CH000188 | ControlHouse | IN-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Readings | Amps C Ø | 297.0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Readings | Amps B Ø | 313.0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Readings | General Comments | | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000716 | BreakerVacuum | KC-34KV TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | BAT001395 | Battery | 379-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.1 | VDC |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | BAT001395 | Battery | 379-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.3 | VDC |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | BAT001395 | Battery | 379-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | BAT001395 | Battery | 379-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | BAT001395 | Battery | 379-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | BAT001395 | Battery | 379-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | BAT001395 | Battery | 379-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Readings | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | BAT001395 | Battery | 379-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | BAT001395 | Battery | 379-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | LTCMechanism | IN-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | LTCMechanism | IN-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 58829 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | LTCMechanism | IN-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 58829 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | LTCMechanism | IN-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | BAT001395 | Battery | 379-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | BAT001395 | Battery | 379-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 85 | °F |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | BAT001395 | Battery | 379-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | LTCMechanism | HA-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Readings | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Readings | Operations Counter AF | 168 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Readings | Operations Counter AL | 168 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | LTCMechanism | IN-TRANS 2 | LTC Counter Readings | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | LTCMechanism | IN-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | LTCMechanism | IN-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | ST000576 | Structure | HI-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | ST000576 | Structure | HI-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | ST000576 | Structure | HI-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | ST000576 | Structure | HI-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | ST000576 | Structure | HI-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KT0027 | WithLTC | 540-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | ST000576 | Structure | HI-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | ST000576 | Structure | HI-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | ST000576 | Structure | HI-Structure | Structure Patrol Inspection | General Comments | | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0428 | BreakerAirMagnetic | HA-1 | AMCB Readings | Amps A Ø | 100.0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | LTCMechanism | IN-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | LTCMechanism | IN-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | LTCMechanism | IN-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | LTCMechanism | IN-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Needs Replaced | check oil cup |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | LTCMechanism | IN-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 123 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | LTCMechanism | IN-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | LTCMechanism | IN-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | LTCMechanism | IN-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | LTCMechanism | IN-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | LTCMechanism | IN-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | LTCMechanism | GD-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | LTCMechanism | GD-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | LTCMechanism | GD-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | LTCMechanism | GD-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | LTCMechanism | GD-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 275 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Readings | Amps C Ø | 0.0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Readings | Amps B Ø | 0.0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Readings | Amps A Ø | 0.0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | LTCMechanism | GD-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | LTCMechanism | GD-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | WithLTC | GA-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 24 | °C |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | WithLTC | GA-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | WithLTC | GA-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | WithLTC | GA-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | WithLTC | GA-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | LTCMechanism | GD-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | LTCMechanism | GD-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | LTCMechanism | IN-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 62580 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | LTCMechanism | IN-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 62580 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | LTCMechanism | IN-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | Desicant | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | LTCMechanism | IN-TRANS 1 | LTC Counter Readings | General Comments | | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000715 | BreakerVacuum | KC-3321 | VCB Readings | 9 Month Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | LTCMechanism | IN-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0098 | LTCMechanism | IN-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | LTCMechanism | IN-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | LTCMechanism | IN-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | LTCMechanism | IN-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | LTCMechanism | IN-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | LTCMechanism | IN-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 1775 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | LTCMechanism | IN-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 25 | °C |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | LTCMechanism | IN-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 30 | °C |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | LTCMechanism | IN-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | LTCMechanism | IN-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LT0097 | LTCMechanism | IN-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | BAT001395 | Battery | 379-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | BAT001395 | Battery | 379-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BCH001318 | Charger | 358-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BCH001318 | Charger | 358-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BCH001318 | Charger | 358-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BCH001318 | Charger | 358-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.1 | amps |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Readings | Fault Operations Ground | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Patrol Inspection | General Comments | | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Readings | General Comments | | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BCH001318 | Charger | 358-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BCH001318 | Charger | 358-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BCH001318 | Charger | 358-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 2.000 | millivolts |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000191 | Switchgear | IN-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000191 | Switchgear | IN-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000191 | Switchgear | IN-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000191 | Switchgear | IN-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000191 | Switchgear | IN-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Readings | Operations Counter AF | 120 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Readings | Operations Counter AL | 120 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Readings | Operations This Read Vac | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Readings | Switching Operations | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Readings | Unknown Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000191 | Switchgear | IN-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000191 | Switchgear | IN-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000191 | Switchgear | IN-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000191 | Switchgear | IN-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000191 | Switchgear | IN-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | CH000188 | ControlHouse | IN-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | CH000188 | ControlHouse | IN-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | CH000188 | ControlHouse | IN-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Readings | 9 Month Operations | 2 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Readings | Amps A Ø | 24.0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Readings | Amps B Ø | 27.0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Readings | Amps C Ø | 27.0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | CH000188 | ControlHouse | IN-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | CH000188 | ControlHouse | IN-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | CH000188 | ControlHouse | IN-Control House | Control House Patrol Inspection | Restroom Clean & OK? | y | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | BCH001321 | Charger | 379-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.600 | millivolts |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | BCH001321 | Charger | 379-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | BCH001321 | Charger | 379-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | BCH001321 | Charger | 379-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.8 | amps |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | BCH001321 | Charger | 379-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | BCH001321 | Charger | 379-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | BCH001321 | Charger | 379-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/9/2023 15:20 | Distribution | Esserville Quarterly Inspection | BCH001321 | Charger | 379-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000191 | Switchgear | IN-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000191 | Switchgear | IN-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000191 | Switchgear | IN-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000191 | Switchgear | IN-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000191 | Switchgear | IN-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000191 | Switchgear | IN-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Readings | 9 Month Operations | 15 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Readings | 9 Month Operations VCB New | 15 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Readings | Amps A Ø | 100.0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Readings | Amps B Ø | 240.0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Readings | Amps C Ø | 210.0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | FE000581 | Fence | LG-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | FE000581 | Fence | LG-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | FE000581 | Fence | LG-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | FE000581 | Fence | LG-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | FE000581 | Fence | LG-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | FE000581 | Fence | LG-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | FE000581 | Fence | LG-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | FE000581 | Fence | LG-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | FE000581 | Fence | LG-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | FE000581 | Fence | LG-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001354 | BreakerVacuum | MC-1262 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | SWG000191 | Switchgear | IN-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | FE000581 | Fence | LG-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | FE000581 | Fence | LG-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | FE000581 | Fence | LG-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | FE000581 | Fence | LG-Fence | Fence Patrol Inspection | General Comments | | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | FE000581 | Fence | LG-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/9/2023 13:56 | Distribution | Logan Quarterly Inspection | FE000581 | Fence | LG-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Readings | Amps A Ø | 13.0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Readings | Amps B Ø | 13.0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Readings | Amps C Ø | 12.0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | CH000188 | ControlHouse | IN-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | CH000188 | ControlHouse | IN-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Readings | Amps C Ø | 600.0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Readings | Amps B Ø | 410.0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Readings | Amps A Ø | 200.0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Readings | 9 Month Operations | 3 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | CH000188 | ControlHouse | IN-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | CH000188 | ControlHouse | IN-Control House | Control House Patrol Inspection | General Comments | | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | CH000188 | ControlHouse | IN-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | CH000188 | ControlHouse | IN-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | CH000188 | ControlHouse | IN-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | LTCMechanism | GD-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | LTCMechanism | GD-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PN25 | LTCMechanism | GD-TRANS 2 | LTC Counter Readings | General Comments | | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Readings | Operations Counter AF | 187 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Readings | Operations Counter AL | 187 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Readings | Operations This Read Vac | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Readings | Unknown Operations | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Readings | Switching Operations | 0 | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | KRC000415 | RegulatorControl | 542-1 | Regulator Annual Control Inspection | VRR X Compensation AL | 0 | Position |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | KRC000415 | RegulatorControl | 542-1 | Regulator Annual Control Inspection | VRR X Compensation AF | 0 | Position |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | KRC000415 | RegulatorControl | 542-1 | Regulator Annual Control Inspection | VRR Time Delay | 30 | Seconds |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | KRC000415 | RegulatorControl | 542-1 | Regulator Annual Control Inspection | VRR R Compensation AL | 0 | Position |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | KRC000415 | RegulatorControl | 542-1 | Regulator Annual Control Inspection | VRR R Compensation AF | 0 | Position |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | KRC000415 | RegulatorControl | 542-1 | Regulator Annual Control Inspection | VRR Base Voltage AL | 124.0 | VAC |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | KRC000415 | RegulatorControl | 542-1 | Regulator Annual Control Inspection | VRR Base Voltage AF | 124.0 | VAC |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | KRC000415 | RegulatorControl | 542-1 | Regulator Annual Control Inspection | VRR Bandwidth AL | 3.0 | VAC |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | KRC000415 | RegulatorControl | 542-1 | Regulator Annual Control Inspection | VRR Bandwidth AF | 3.0 | VAC |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | KRC000415 | RegulatorControl | 542-1 | Regulator Annual Control Inspection | General Comments | | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | KRC000415 | RegulatorControl | 542-1 | Regulator Annual Control Inspection | Follow-up Action Required? | n | |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | KRC000415 | RegulatorControl | 542-1 | Regulator Annual Control Inspection | FCP Lower AL | 118.0 | VAC |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | KRC000415 | RegulatorControl | 542-1 | Regulator Annual Control Inspection | FCP Lower AF | 118.0 | VAC |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | KRC000415 | RegulatorControl | 542-1 | Regulator Annual Control Inspection | FCP Block Raise AL | 128.0 | VAC |
| 2/9/2023 9:47 | Distribution | Richmond Industrial Quarterly Inspection | KRC000415 | RegulatorControl | 542-1 | Regulator Annual Control Inspection | FCP Block Raise AF | 128.0 | VAC |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Readings | Operations This Read Vac | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Readings | Operations Counter AL | 99 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Readings | Operations Counter AF | 99 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Readings | Maintenance Operations | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Readings | General Comments | | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Patrol Inspection | General Comments | | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Readings | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Readings | Fault Operations Ground | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Readings | General Comments | | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Readings | Operations Counter AF | 296 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Readings | Operations Counter AL | 296 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Readings | Operations This Read Vac | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Readings | Switching Operations | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000486 | BreakerVacuum | KC-3322 | VCB Readings | Unknown Operations | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001353 | BreakerVacuum | MC-1261 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Readings | 9 Month Operations | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/9/2023 11:48 | Distribution | Knob Creek Quarterly Inspection | BK000487 | BreakerVacuum | KC-3323 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BAT001390 | Battery | 358-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Low | If low,note cell #~'s |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BAT001390 | Battery | 358-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | LTCMechanism | 540-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | LTCMechanism | 540-1 | LTC Counter Readings | LTC As Left Counter | 26865 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Readings | Maintenance Operations | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Readings | Operations Counter AF | 78 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Readings | Operations Counter AL | 78 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Readings | Operations This Read Vac | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Readings | 9 Month Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | ST000576 | Structure | HI-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BAT001390 | Battery | 358-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BAT001390 | Battery | 358-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0428 | BreakerAirMagnetic | HA-1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0428 | BreakerAirMagnetic | HA-1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Readings | Unknown Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | ST000576 | Structure | HI-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BAT001390 | Battery | 358-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0428 | BreakerAirMagnetic | HA-1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0428 | BreakerAirMagnetic | HA-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0428 | BreakerAirMagnetic | HA-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0428 | BreakerAirMagnetic | HA-1 | AMCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | LTCMechanism | 540-1 | LTC Counter Readings | LTC As Found Counter | 26865 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | LTCMechanism | 540-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | LTCMechanism | 540-1 | LTC Counter Readings | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | LTCMechanism | 540-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Patrol Inspection | General Comments | | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Readings | Follow-up Action Required? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | ST000576 | Structure | HI-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | FE000567 | Fence | HI-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | LTCMechanism | HA-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BAT001390 | Battery | 358-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BAT001390 | Battery | 358-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BAT001390 | Battery | 358-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.1 | VDC |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BAT001390 | Battery | 358-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.3 | VDC |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | FE000567 | Fence | HI-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | KB0054 | BreakerVacuum | 540-2 | VCB Readings | Switching Operations | 0 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | FE000567 | Fence | HI-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | FE000567 | Fence | HI-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | FE000567 | Fence | HI-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | ST000576 | Structure | HI-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | ST000576 | Structure | HI-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | ST000576 | Structure | HI-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | FE000567 | Fence | HI-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | FE000567 | Fence | HI-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | FE000567 | Fence | HI-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | FE000567 | Fence | HI-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | LTCMechanism | HA-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Readings | Amps C Ø | 50.0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0428 | BreakerAirMagnetic | HA-1 | AMCB Readings | Amps B Ø | 125.0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0428 | BreakerAirMagnetic | HA-1 | AMCB Readings | Amps C Ø | 80.0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Readings | Amps B Ø | 50.0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0513 | BreakerVacuum | IN-1298 | VCB Readings | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | ST000576 | Structure | HI-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | FE000567 | Fence | HI-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | FE000567 | Fence | HI-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | FE000567 | Fence | HI-Fence | Fence Patrol Inspection | General Comments | | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | FE000567 | Fence | HI-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | FE000567 | Fence | HI-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | FE000567 | Fence | HI-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | ST000576 | Structure | HI-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Readings | General Comments | | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | LTCMechanism | 540-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | LTCMechanism | 540-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0513 | BreakerVacuum | IN-1298 | VCB Readings | Maintenance Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0513 | BreakerVacuum | IN-1298 | VCB Readings | Operations Counter AF | 249 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0513 | BreakerVacuum | IN-1298 | VCB Readings | Operations Counter AL | 249 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0513 | BreakerVacuum | IN-1298 | VCB Readings | Operations This Read Vac | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0428 | BreakerAirMagnetic | HA-1 | AMCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0513 | BreakerVacuum | IN-1298 | VCB Readings | Switching Operations | 0 | |
| 2/14/2023 8:05 | Distribution | International Quarterly Inspection | LB0513 | BreakerVacuum | IN-1298 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0428 | BreakerAirMagnetic | HA-1 | AMCB Readings | Switching Operations | 0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0428 | BreakerAirMagnetic | HA-1 | AMCB Readings | Operations Counter AL | 399 | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BAT001390 | Battery | 358-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Readings | Amps A Ø | 50.0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | LTCMechanism | 540-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | LTCMechanism | 540-1 | LTC Counter Readings | LTC Operations Since Last Insp | 670 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | LTCMechanism | 540-1 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BAT001390 | Battery | 358-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BAT001390 | Battery | 358-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/9/2023 13:20 | Distribution | East Stone Gap Quarterly Inspection | BAT001390 | Battery | 358-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0428 | BreakerAirMagnetic | HA-1 | AMCB Readings | Operations Counter AF | 399 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0428 | BreakerAirMagnetic | HA-1 | AMCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | LTCMechanism | 540-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | LTCMechanism | HA-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 330508 | |
| 2/15/2023 5:24 | Distribution | Highland Quarterly Inspection | FE000567 | Fence | HI-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/10/2023 8:02 | Distribution | Mill Creek Switching Quarterly Inspection | BK001355 | BreakerVacuum | MC-1264 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | LTCMechanism | HA-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 330508 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | LTCMechanism | HA-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | LTCMechanism | 540-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 2/9/2023 11:44 | Distribution | Okonite Quarterly Inspection | C0513 | LTCMechanism | 540-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Readings | Operations This Read Vac | 2 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Readings | Operations Counter AL | 358 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0459 | BreakerAirMagnetic | HE-3 | AMCB Readings | Amps A Ø | 78.0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0459 | BreakerAirMagnetic | HE-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0459 | BreakerAirMagnetic | HE-3 | AMCB Readings | Amps B Ø | 90.0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0459 | BreakerAirMagnetic | HE-3 | AMCB Readings | Amps C Ø | 59.0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0459 | BreakerAirMagnetic | HE-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0459 | BreakerAirMagnetic | HE-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0459 | BreakerAirMagnetic | HE-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Readings | Operations Counter AF | 358 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Readings | Maintenance Operations | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0459 | BreakerAirMagnetic | HE-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0459 | BreakerAirMagnetic | HE-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Readings | General Comments | B Phase IOC | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0459 | BreakerAirMagnetic | HE-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0459 | BreakerAirMagnetic | HE-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0459 | BreakerAirMagnetic | HE-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0422 | BreakerAirMagnetic | GD-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0422 | BreakerAirMagnetic | GD-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0422 | BreakerAirMagnetic | GD-1 | AMCB Patrol Inspection | General Comments | | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0422 | BreakerAirMagnetic | GD-1 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0459 | BreakerAirMagnetic | HE-3 | AMCB Readings | Unknown Operations | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0459 | BreakerAirMagnetic | HE-3 | AMCB Readings | Switching Operations | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0459 | BreakerAirMagnetic | HE-3 | AMCB Readings | Operations This Read AM | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0459 | BreakerAirMagnetic | HE-3 | AMCB Readings | Operations Counter AL | 862 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0459 | BreakerAirMagnetic | HE-3 | AMCB Readings | Operations Counter AF | 862 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0459 | BreakerAirMagnetic | HE-3 | AMCB Readings | Maintenance Operations | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0459 | BreakerAirMagnetic | HE-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0459 | BreakerAirMagnetic | HE-3 | AMCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0459 | BreakerAirMagnetic | HE-3 | AMCB Readings | General Comments | | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0459 | BreakerAirMagnetic | HE-3 | AMCB Patrol Inspection | General Comments | | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0457 | BreakerAirMagnetic | HE-1 | AMCB Readings | Switching Operations | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0457 | BreakerAirMagnetic | HE-1 | AMCB Readings | Unknown Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Readings | Fault Operations B Ø | 4 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Readings | Fault Operations A Ø | 4 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | CH000234 | ControlHouse | 337-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | CH000234 | ControlHouse | 337-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | CH000234 | ControlHouse | 337-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | CH000234 | ControlHouse | 337-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | CH000234 | ControlHouse | 337-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | CH000234 | ControlHouse | 337-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Readings | Fault Adjusted Amps B Phase V | 44.72 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Readings | Fault Adjusted Amps A Phase V | 44.72 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Readings | Amps C Ø | 95.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Readings | Amps B Ø | 95.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | CH000234 | ControlHouse | 337-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | CH000234 | ControlHouse | 337-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | CH000234 | ControlHouse | 337-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | CH000234 | ControlHouse | 337-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | CH000234 | ControlHouse | 337-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | CH000234 | ControlHouse | 337-Control House | Control House Patrol Inspection | General Comments | | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | CH000234 | ControlHouse | 337-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Readings | Amps A Ø | 95.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Readings | Accumulated Fault Duty C Ph V | 6.56 | % |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0458 | BreakerAirMagnetic | HE-2 | AMCB Readings | Unknown Operations | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0458 | BreakerAirMagnetic | HE-2 | AMCB Readings | Switching Operations | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0458 | BreakerAirMagnetic | HE-2 | AMCB Readings | Operations This Read AM | 1 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0458 | BreakerAirMagnetic | HE-2 | AMCB Readings | Operations Counter AL | 411 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Readings | Accumulated Fault Duty B Ph V | 5.96 | % |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | LTCMechanism | HE-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | LTCMechanism | HE-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | LTCMechanism | HE-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | LTCMechanism | HE-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | LTCMechanism | HE-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 396 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | LTCMechanism | HE-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0458 | BreakerAirMagnetic | HE-2 | AMCB Readings | Operations Counter AF | 411 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0458 | BreakerAirMagnetic | HE-2 | AMCB Readings | Maintenance Operations | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0458 | BreakerAirMagnetic | HE-2 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0458 | BreakerAirMagnetic | HE-2 | AMCB Readings | General Comments | A phase ioc | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0458 | BreakerAirMagnetic | HE-2 | AMCB Patrol Inspection | General Comments | | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0458 | BreakerAirMagnetic | HE-2 | AMCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0458 | BreakerAirMagnetic | HE-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0458 | BreakerAirMagnetic | HE-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | LTCMechanism | HE-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | LTCMechanism | HE-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | LTCMechanism | HE-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | LTCMechanism | HE-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | LTCC000384 | LTCControl | 020-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Readings | Unknown Operations | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | YD000083 | Yard | 715-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | n | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | YD000083 | Yard | 715-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | n | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Readings | General Comments | | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Readings | Operations Counter AF | 347 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Readings | Operations Counter AL | 347 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Readings | Operations This Read Vac | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Readings | Switching Operations | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Readings | Unknown Operations | 0 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | LTCMechanism | 601-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | LTCMechanism | 601-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | LTCMechanism | 601-1 | LTC Counter Readings | General Comments | | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | LTCMechanism | 601-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | LTCMechanism | 601-1 | LTC Counter Readings | LTC As Found Counter | 74719 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | LTCMechanism | 601-1 | LTC Counter Readings | LTC As Left Counter | 74719 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | LTCMechanism | 601-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | LTCMechanism | 601-1 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | LTCMechanism | 601-1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | LTCMechanism | 601-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | CH000234 | ControlHouse | 337-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0457 | BreakerAirMagnetic | HE-1 | AMCB Readings | Operations Counter AF | 509 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0457 | BreakerAirMagnetic | HE-1 | AMCB Readings | Operations Counter AL | 509 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0457 | BreakerAirMagnetic | HE-1 | AMCB Readings | Operations This Read AM | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | FE000563 | Fence | HE-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | FE000563 | Fence | HE-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | FE000563 | Fence | HE-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | FE000563 | Fence | HE-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | FE000419 | Fence | 857-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | FE000419 | Fence | 857-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0427 | BreakerAirMagnetic | GD-2 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0427 | BreakerAirMagnetic | GD-2 | AMCB Patrol Inspection | General Comments | | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0427 | BreakerAirMagnetic | GD-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0427 | BreakerAirMagnetic | GD-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | FE000419 | Fence | 857-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | FE000419 | Fence | 857-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | FE000419 | Fence | 857-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Readings | Unknown Operations | 0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | FE000563 | Fence | HE-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0383 | BreakerAirMagnetic | GA-1 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .4 | psi |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Readings | Operations Counter AL | 377 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Readings | Operations Counter AF | 377 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BAT001393 | Battery | 337-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | FE000419 | Fence | 857-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BAT001393 | Battery | 337-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BAT001393 | Battery | 337-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BAT001393 | Battery | 337-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0383 | BreakerAirMagnetic | GA-1 | AMCB Readings | 9 Months Operations | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0383 | BreakerAirMagnetic | GA-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 3.2 | % |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0383 | BreakerAirMagnetic | GA-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 2.14 | % |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0383 | BreakerAirMagnetic | GA-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 11.74 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BAT001393 | Battery | 337-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BAT001393 | Battery | 337-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BAT001393 | Battery | 337-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Readings | Switching Operations | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Readings | 9 Month Operations | 7 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Readings | Operations Counter AL | 357 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Readings | Operations Counter AF | 357 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Readings | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | FE000061 | Fence | 312-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | n | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | FE000061 | Fence | 312-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | FE000061 | Fence | 312-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | FE000061 | Fence | 312-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | FE000061 | Fence | 312-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | FE000061 | Fence | 312-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | FE000061 | Fence | 312-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RG000205 | Regulator | 140-1 | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RG000205 | Regulator | 140-1 | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RG000205 | Regulator | 140-1 | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RG000205 | Regulator | 140-1 | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RG000205 | Regulator | 140-1 | Regulator Patrol Inspection | Regulator As Left Counter | 5634 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BAT001393 | Battery | 337-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BAT001393 | Battery | 337-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RG000205 | Regulator | 140-1 | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RG000205 | Regulator | 140-1 | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RG000205 | Regulator | 140-1 | Regulator Patrol Inspection | Reg Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RG000205 | Regulator | 140-1 | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BAT001393 | Battery | 337-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BAT001393 | Battery | 337-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BAT001393 | Battery | 337-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BAT001393 | Battery | 337-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Readings | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0459 | BreakerAirMagnetic | HE-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0459 | BreakerAirMagnetic | HE-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0459 | BreakerAirMagnetic | HE-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0459 | BreakerAirMagnetic | HE-3 | AMCB Readings | 9 Months Operations | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0459 | BreakerAirMagnetic | HE-3 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Readings | Amps C Ø | 61.0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Readings | Amps B Ø | 43.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Readings | Fault Operations B Ø | 2 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Readings | Fault Adjusted Amps B Phase V | 22.36 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Readings | Amps C Ø | 8.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Readings | Amps B Ø | 8.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Readings | Amps A Ø | 8.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Readings | Accumulated Fault Duty C Ph V | 3.58 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Readings | Accumulated Fault Duty B Ph V | 5.96 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Readings | Accumulated Fault Duty A Ph V | 4.17 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Readings | 9 Month Operations | 9 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Readings | Amps A Ø | 46.0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0021 | BreakerVacuum | 312-4646 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | YD000572 | Yard | HE-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | YD000572 | Yard | HE-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | YD000572 | Yard | HE-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | YD000572 | Yard | HE-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | YD000572 | Yard | HE-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | YD000572 | Yard | HE-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | YD000572 | Yard | HE-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | YD000572 | Yard | HE-Yard | Yard Patrol Inspection | General Comments | | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | YD000572 | Yard | HE-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | YD000572 | Yard | HE-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | YD000572 | Yard | HE-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | YD000572 | Yard | HE-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | YD000572 | Yard | HE-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | YD000572 | Yard | HE-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | FE000563 | Fence | HE-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | FE000563 | Fence | HE-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | FE000563 | Fence | HE-Fence | Fence Patrol Inspection | General Comments | | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | FE000563 | Fence | HE-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | FE000563 | Fence | HE-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | FE000563 | Fence | HE-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | FE000563 | Fence | HE-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | FE000563 | Fence | HE-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | FE000419 | Fence | 857-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | FE000419 | Fence | 857-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | FE000419 | Fence | 857-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | FE000419 | Fence | 857-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | FE000419 | Fence | 857-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | YD000083 | Yard | 715-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | YD000083 | Yard | 715-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Bad | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | YD000083 | Yard | 715-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | YD000083 | Yard | 715-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | YD000083 | Yard | 715-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | FE000563 | Fence | HE-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | FE000563 | Fence | HE-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0460 | BreakerAirMagnetic | HE-4 | AMCB Readings | Unknown Operations | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0460 | BreakerAirMagnetic | HE-4 | AMCB Readings | Switching Operations | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0460 | BreakerAirMagnetic | HE-4 | AMCB Readings | Operations This Read AM | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0460 | BreakerAirMagnetic | HE-4 | AMCB Readings | Operations Counter AL | 383 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | FE000563 | Fence | HE-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0429 | BreakerAirMagnetic | HA-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0429 | BreakerAirMagnetic | HA-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0429 | BreakerAirMagnetic | HA-2 | AMCB Patrol Inspection | General Comments | | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0429 | BreakerAirMagnetic | HA-2 | AMCB Readings | General Comments | | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0429 | BreakerAirMagnetic | HA-2 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0429 | BreakerAirMagnetic | HA-2 | AMCB Readings | Operations This Read AM | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | CH000444 | ControlHouse | GD-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | CH000444 | ControlHouse | GD-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | CH000444 | ControlHouse | GD-Battery Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | CH000444 | ControlHouse | GD-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0391 | BreakerAirMagnetic | GO-1 | AMCB Readings | Amps B Ø | 10.0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0391 | BreakerAirMagnetic | GO-1 | AMCB Readings | Amps C Ø | 10.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Readings | Switching Operations | 2 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Readings | 9 Month Operations | 4 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Readings | Operations This Read Vac | 2 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Readings | Operations Counter AL | 213 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Readings | Operations Counter AF | 213 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Readings | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0391 | BreakerAirMagnetic | GO-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0391 | BreakerAirMagnetic | GO-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0391 | BreakerAirMagnetic | GO-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0391 | BreakerAirMagnetic | GO-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0391 | BreakerAirMagnetic | GO-1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0391 | BreakerAirMagnetic | GO-1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0391 | BreakerAirMagnetic | GO-1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0391 | BreakerAirMagnetic | GO-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0391 | BreakerAirMagnetic | GO-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0391 | BreakerAirMagnetic | GO-1 | AMCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0391 | BreakerAirMagnetic | GO-1 | AMCB Patrol Inspection | General Comments | | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | CH000475 | ControlHouse | GO-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | CH000475 | ControlHouse | GO-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Readings | Amps C Ø | 105.0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BCH001317 | Charger | 337-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BCH001317 | Charger | 337-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | LTCMechanism | HE-TRANS 2 | LTC Counter Readings | General Comments | | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | LTCMechanism | HE-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | LTCMechanism | HE-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Readings | Switching Operations | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Readings | Operations Counter AL | 127 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Readings | Operations Counter AF | 127 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Readings | General Comments | | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Readings | 9 Month Operations | 2 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Readings | Switching Operations | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Readings | Operations This Read Vac | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Readings | Operations Counter AL | 211 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Readings | Operations Counter AF | 211 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | FE000869 | Fence | 140-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | FE000869 | Fence | 140-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | FE000869 | Fence | 140-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | FE000869 | Fence | 140-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | FE000869 | Fence | 140-Fence | Fence Patrol Inspection | General Comments | | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | FE000869 | Fence | 140-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | FE000869 | Fence | 140-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | CH000444 | ControlHouse | GD-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | CH000444 | ControlHouse | GD-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0429 | BreakerAirMagnetic | HA-2 | AMCB Readings | 9 Month Ops New | 1 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0429 | BreakerAirMagnetic | HA-2 | AMCB Readings | 9 Months Operations | 1 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0429 | BreakerAirMagnetic | HA-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 9.61 | % |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0429 | BreakerAirMagnetic | HA-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 12.81 | % |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0429 | BreakerAirMagnetic | HA-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 1.07 | % |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0429 | BreakerAirMagnetic | HA-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0429 | BreakerAirMagnetic | HA-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Readings | General Comments | | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Readings | LTC Totalizer Reading | 3782.40 | kw |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Readings | General Comments | | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Readings | Oil Temp Max | 42 | °C |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Readings | 9 Month Operations | 3 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Readings | Unknown Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Readings | Amps B Ø | 105.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Readings | Amps A Ø | 105.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Readings | Accumulated Fault Duty C Ph V | 15 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Readings | Accumulated Fault Duty B Ph V | 12.5 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Readings | Accumulated Fault Duty A Ph V | 11.67 | % |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0385 | BreakerAirMagnetic | GA-3 | AMCB Readings | Operations This Read AM | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0385 | BreakerAirMagnetic | GA-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0385 | BreakerAirMagnetic | GA-3 | AMCB Readings | General Comments | | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0385 | BreakerAirMagnetic | GA-3 | AMCB Patrol Inspection | General Comments | | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0385 | BreakerAirMagnetic | GA-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0385 | BreakerAirMagnetic | GA-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0385 | BreakerAirMagnetic | GA-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0385 | BreakerAirMagnetic | GA-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0385 | BreakerAirMagnetic | GA-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 1.07 | % |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0385 | BreakerAirMagnetic | GA-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 3.2 | % |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0385 | BreakerAirMagnetic | GA-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 9.61 | % |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0385 | BreakerAirMagnetic | GA-3 | AMCB Readings | 9 Months Operations | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | CH000444 | ControlHouse | GD-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | CH000444 | ControlHouse | GD-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | CH000444 | ControlHouse | GD-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | CH000445 | ControlHouse | HE-Battery Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | CH000445 | ControlHouse | HE-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | CH000445 | ControlHouse | HE-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0385 | BreakerAirMagnetic | GA-3 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | CH000445 | ControlHouse | HE-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | CH000445 | ControlHouse | HE-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | CH000445 | ControlHouse | HE-Battery Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | CH000445 | ControlHouse | HE-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | CH000445 | ControlHouse | HE-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | CH000445 | ControlHouse | HE-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | CH000445 | ControlHouse | HE-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Readings | Totalizer Meter Reading | .3940 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | WithLTC | 601-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0426 | BreakerAirMagnetic | GD-SEC 1 SPARE | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | YD000083 | Yard | 715-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0426 | BreakerAirMagnetic | GD-SEC 1 SPARE | AMCB Patrol Inspection | General Comments | | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0426 | BreakerAirMagnetic | GD-SEC 1 SPARE | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0426 | BreakerAirMagnetic | GD-SEC 1 SPARE | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | SWG000034 | Switchgear | FO-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | SWG000034 | Switchgear | FO-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | SWG000034 | Switchgear | FO-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | SWG000034 | Switchgear | FO-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | SWG000034 | Switchgear | FO-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | SWG000034 | Switchgear | FO-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | SWG000034 | Switchgear | FO-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | SWG000034 | Switchgear | FO-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | SWG000034 | Switchgear | FO-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | CH000234 | ControlHouse | 337-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | LTCMechanism | HE-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | YD000083 | Yard | 715-Yard | Yard Patrol Inspection | General Comments | | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | YD000083 | Yard | 715-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | YD000083 | Yard | 715-Yard | Yard Patrol Inspection | Yard Lights Working? | n | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | ST000089 | Structure | 715-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | ST000089 | Structure | 715-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | ST000089 | Structure | 715-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | ST000089 | Structure | 715-Structure | Structure Patrol Inspection | General Comments | All equipment has been removed. ALL GROUND HAVE BEEN REMOVED | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | ST000089 | Structure | 715-Structure | Structure Patrol Inspection | Ground Connections Intact? | n | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | ST000089 | Structure | 715-Structure | Structure Patrol Inspection | Insulators In Good Condition? | n | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | ST000089 | Structure | 715-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | BCH001339 | Charger | FO-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | BCH001339 | Charger | FO-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.7 | VDC |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | FE000869 | Fence | 140-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | FE000869 | Fence | 140-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | BCH001339 | Charger | FO-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.7 | VDC |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | BCH001339 | Charger | FO-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 0.0 | amps |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | BCH001339 | Charger | FO-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | BCH001339 | Charger | FO-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | BCH001339 | Charger | FO-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | BCH001339 | Charger | FO-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | FE000869 | Fence | 140-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | FE000869 | Fence | 140-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | LTCMechanism | HE-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | LTCMechanism | HE-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0391 | BreakerAirMagnetic | GO-1 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0391 | BreakerAirMagnetic | GO-1 | AMCB Readings | 9 Months Operations | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | LTCMechanism | HE-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 415498 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0458 | BreakerAirMagnetic | HE-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0458 | BreakerAirMagnetic | HE-2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | LTCMechanism | HE-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 415498 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | LTCMechanism | HE-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | LTCMechanism | HE-TRANS 1 | LTC Counter Readings | General Comments | | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | LTCMechanism | HE-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | LTCMechanism | HE-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Readings | Accumulated Fault Duty A Ph V | 7.75 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Readings | 9 Month Operations | 15 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | LTCMechanism | HE-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | LTCMechanism | HE-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | LTCMechanism | HE-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | LTCMechanism | HE-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | LTCMechanism | HE-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 234 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | LTCMechanism | HE-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BAT001290 | Battery | HE-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BAT001290 | Battery | HE-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BAT001290 | Battery | HE-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BAT001290 | Battery | HE-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BAT001290 | Battery | HE-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BAT001290 | Battery | HE-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BAT001290 | Battery | HE-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BAT001290 | Battery | HE-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BAT001290 | Battery | HE-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BAT001290 | Battery | HE-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BAT001290 | Battery | HE-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BAT001290 | Battery | HE-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BAT001290 | Battery | HE-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 71 | °F |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BAT001290 | Battery | HE-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | LTCMechanism | HE-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | SWG000034 | Switchgear | FO-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | SWG000034 | Switchgear | FO-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | SWG000034 | Switchgear | FO-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | SWG000034 | Switchgear | FO-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | SWG000034 | Switchgear | FO-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | SWG000034 | Switchgear | FO-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | SWG000034 | Switchgear | FO-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | CH000234 | ControlHouse | 337-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | CH000234 | ControlHouse | 337-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | SWG000034 | Switchgear | FO-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Readings | Operations This Read Vac | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Readings | Operations Counter AL | 201 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Readings | Operations Counter AF | 201 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Readings | General Comments | | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Readings | Amps C Ø | 140.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Readings | Amps B Ø | 140.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Readings | Amps A Ø | 140.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Readings | Accumulated Fault Duty C Ph V | 2.98 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Readings | Accumulated Fault Duty B Ph V | 4.77 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Readings | Accumulated Fault Duty A Ph V | 3.58 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BCH001317 | Charger | 337-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.5 | amps |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Readings | Amps C Ø | 60.0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Readings | Amps B Ø | 63.0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Readings | Amps A Ø | 76.0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BCH001317 | Charger | 337-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BCH001317 | Charger | 337-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0391 | BreakerAirMagnetic | GO-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | ST000089 | Structure | 715-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0391 | BreakerAirMagnetic | GO-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0391 | BreakerAirMagnetic | GO-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0391 | BreakerAirMagnetic | GO-1 | AMCB Readings | Amps A Ø | 10.0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BCH001317 | Charger | 337-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 2.500 | millivolts |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | LTCMechanism | HE-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 454057 | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | FE000869 | Fence | 140-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | FE000869 | Fence | 140-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0458 | BreakerAirMagnetic | HE-2 | AMCB Readings | Fault Operations A Ø | 1 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0458 | BreakerAirMagnetic | HE-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0458 | BreakerAirMagnetic | HE-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0458 | BreakerAirMagnetic | HE-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 9.55 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0458 | BreakerAirMagnetic | HE-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0458 | BreakerAirMagnetic | HE-2 | AMCB Readings | Amps C Ø | 150.0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0458 | BreakerAirMagnetic | HE-2 | AMCB Readings | Amps B Ø | 150.0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0458 | BreakerAirMagnetic | HE-2 | AMCB Readings | Amps A Ø | 150.0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0458 | BreakerAirMagnetic | HE-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0458 | BreakerAirMagnetic | HE-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0458 | BreakerAirMagnetic | HE-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0458 | BreakerAirMagnetic | HE-2 | AMCB Readings | 9 Months Operations | 1 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0458 | BreakerAirMagnetic | HE-2 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | FE000869 | Fence | 140-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | FE000869 | Fence | 140-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | FE000869 | Fence | 140-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | LTCMechanism | HE-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 454057 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | LTCMechanism | HE-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BCH001317 | Charger | 337-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BCH001317 | Charger | 337-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000389 | BreakerVacuum | 337-4642 | VCB Readings | Switching Operations | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BK000263 | BreakerAirMagnetic | HE-SEC 1 SPARE | AMCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | SWG000069 | Switchgear | GO-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | SWG000069 | Switchgear | GO-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | SWG000069 | Switchgear | GO-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | SWG000069 | Switchgear | GO-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | SWG000069 | Switchgear | GO-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BK000263 | BreakerAirMagnetic | HE-SEC 1 SPARE | AMCB Patrol Inspection | General Comments | | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | LTCMechanism | GO-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | LTCMechanism | GO-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BK000263 | BreakerAirMagnetic | HE-SEC 1 SPARE | AMCB Readings | General Comments | | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BK000263 | BreakerAirMagnetic | HE-SEC 1 SPARE | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BK000263 | BreakerAirMagnetic | HE-SEC 1 SPARE | AMCB Readings | Maintenance Operations | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BK000263 | BreakerAirMagnetic | HE-SEC 1 SPARE | AMCB Readings | Operations Counter AF | 383 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BK000263 | BreakerAirMagnetic | HE-SEC 1 SPARE | AMCB Readings | Operations Counter AL | 383 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BK000263 | BreakerAirMagnetic | HE-SEC 1 SPARE | AMCB Readings | Operations This Read AM | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BK000263 | BreakerAirMagnetic | HE-SEC 1 SPARE | AMCB Readings | Switching Operations | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BK000263 | BreakerAirMagnetic | HE-SEC 1 SPARE | AMCB Readings | Unknown Operations | 0 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Readings | Unknown Operations | 0 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0460 | BreakerAirMagnetic | HE-4 | AMCB Patrol Inspection | General Comments | | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0460 | BreakerAirMagnetic | HE-4 | AMCB Readings | General Comments | | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0460 | BreakerAirMagnetic | HE-4 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0460 | BreakerAirMagnetic | HE-4 | AMCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | CH000458 | ControlHouse | GA-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | CH000458 | ControlHouse | GA-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | CH000458 | ControlHouse | GA-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | CH000458 | ControlHouse | GA-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Readings | Amps C Ø | 43.0 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Readings | Amps B Ø | 51.0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | SWG000069 | Switchgear | GO-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | SWG000069 | Switchgear | GO-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Readings | Amps A Ø | 43.0 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | SWG000069 | Switchgear | GO-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | SWG000069 | Switchgear | GO-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | SWG000069 | Switchgear | GO-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | SWG000069 | Switchgear | GO-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0391 | BreakerAirMagnetic | GO-1 | AMCB Readings | General Comments | | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000011 | Switchgear | HE-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000011 | Switchgear | HE-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0368 | BreakerAirMagnetic | FO-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0368 | BreakerAirMagnetic | FO-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0368 | BreakerAirMagnetic | FO-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0368 | BreakerAirMagnetic | FO-3 | AMCB Readings | 9 Months Operations | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0368 | BreakerAirMagnetic | FO-3 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | LTCMechanism | HA-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | LTCMechanism | HA-TRANS 1 | LTC Counter Readings | General Comments | | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | WithLTC | GA-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | CH000458 | ControlHouse | GA-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | CH000458 | ControlHouse | GA-Battery Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0460 | BreakerAirMagnetic | HE-4 | AMCB Readings | Amps C Ø | 50.0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0460 | BreakerAirMagnetic | HE-4 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0460 | BreakerAirMagnetic | HE-4 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0460 | BreakerAirMagnetic | HE-4 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0460 | BreakerAirMagnetic | HE-4 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0460 | BreakerAirMagnetic | HE-4 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0460 | BreakerAirMagnetic | HE-4 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0460 | BreakerAirMagnetic | HE-4 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0460 | BreakerAirMagnetic | HE-4 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0460 | BreakerAirMagnetic | HE-4 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0460 | BreakerAirMagnetic | HE-4 | AMCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | LTCMechanism | GO-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 344384 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | LTCMechanism | GO-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | LTCMechanism | GO-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | LTCMechanism | GO-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | LTCMechanism | GO-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | LTCMechanism | GO-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 275 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | LTCMechanism | GO-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | WithLTC | GA-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | WithLTC | GA-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Readings | General Comments | Breaker is open | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Readings | Maintenance Operations | 0 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Readings | Operations Counter AF | 134 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Readings | Operations Counter AL | 135 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | WithLTC | GA-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Readings | Operations This Read Vac | 1 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Readings | Switching Operations | 1 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BK000263 | BreakerAirMagnetic | HE-SEC 1 SPARE | AMCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | FE000017 | Fence | 337-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | n | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | FE000017 | Fence | 337-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | FE000017 | Fence | 337-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | FE000017 | Fence | 337-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | FE000017 | Fence | 337-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | FE000017 | Fence | 337-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | FE000017 | Fence | 337-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | FE000017 | Fence | 337-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | FE000017 | Fence | 337-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | FE000017 | Fence | 337-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | FE000017 | Fence | 337-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | FE000017 | Fence | 337-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | FE000017 | Fence | 337-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | FE000017 | Fence | 337-Fence | Fence Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | FE000017 | Fence | 337-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | FE000017 | Fence | 337-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | LTCC000712 | LTCControl | 601-1 | LTC Control Insp | All Connections OK? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | LTCC000712 | LTCControl | 601-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | LTCC000712 | LTCControl | 601-1 | LTC Control Insp | General Comments | | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | LTCC000712 | LTCControl | 601-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | LTCC000712 | LTCControl | 601-1 | LTC Control Insp | LTC Output Voltage Level | 124.8 | VAC |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | LTCC000712 | LTCControl | 601-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | LTCC000712 | LTCControl | 601-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | LTCC000712 | LTCControl | 601-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BK000263 | BreakerAirMagnetic | HE-SEC 1 SPARE | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BK000263 | BreakerAirMagnetic | HE-SEC 1 SPARE | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BK000263 | BreakerAirMagnetic | HE-SEC 1 SPARE | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BK000263 | BreakerAirMagnetic | HE-SEC 1 SPARE | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BK000263 | BreakerAirMagnetic | HE-SEC 1 SPARE | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BK000263 | BreakerAirMagnetic | HE-SEC 1 SPARE | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BK000263 | BreakerAirMagnetic | HE-SEC 1 SPARE | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | WithLTC | GA-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | WithLTC | GA-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | WithLTC | GA-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000002 | Switchgear | GD-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000011 | Switchgear | HE-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000011 | Switchgear | HE-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000011 | Switchgear | HE-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000011 | Switchgear | HE-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000011 | Switchgear | HE-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000011 | Switchgear | HE-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000002 | Switchgear | GD-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000011 | Switchgear | HE-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | CH000459 | ControlHouse | HA-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | CH000459 | ControlHouse | HA-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | CH000459 | ControlHouse | HA-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | CH000459 | ControlHouse | HA-Battery Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | CH000459 | ControlHouse | HA-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | CH000459 | ControlHouse | HA-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | WithLTC | GA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 40 | °C |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 60 | °C |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 40 | °C |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 60 | °C |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 40 | °C |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 60 | °C |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 135.00 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | BCH000102 | Charger | GA-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | BCH000102 | Charger | GA-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0460 | BreakerAirMagnetic | HE-4 | AMCB Readings | Operations Counter AF | 383 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | WithLTC | FO-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | WithLTC | GA-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | WithLTC | GA-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | WithLTC | GA-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Readings | 9 Month Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | YD000496 | Yard | 140-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BK000263 | BreakerAirMagnetic | HE-SEC 1 SPARE | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0457 | BreakerAirMagnetic | HE-1 | AMCB Readings | Amps C Ø | 89.0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0457 | BreakerAirMagnetic | HE-1 | AMCB Readings | Amps B Ø | 80.0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0457 | BreakerAirMagnetic | HE-1 | AMCB Readings | Amps A Ø | 80.0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0457 | BreakerAirMagnetic | HE-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0457 | BreakerAirMagnetic | HE-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0457 | BreakerAirMagnetic | HE-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0457 | BreakerAirMagnetic | HE-1 | AMCB Readings | 9 Months Operations | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0457 | BreakerAirMagnetic | HE-1 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | LTCMechanism | FO-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | LTCMechanism | FO-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | LTCMechanism | FO-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 390 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | LTCMechanism | FO-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | LTCMechanism | FO-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | LTCMechanism | FO-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0424 | BreakerAirMagnetic | GD-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0424 | BreakerAirMagnetic | GD-3 | AMCB Patrol Inspection | General Comments | | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0424 | BreakerAirMagnetic | GD-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | LTCMechanism | FO-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | LTCMechanism | FO-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 44170 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | LTCMechanism | FO-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 44170 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | LTCMechanism | FO-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | LTCMechanism | FO-TRANS 1 | LTC Counter Readings | General Comments | | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | LTCMechanism | FO-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | LTCMechanism | FO-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000011 | Switchgear | HE-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000011 | Switchgear | HE-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PN41 | LTCMechanism | FO-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | LTCMechanism | GA-TRANS 1 | LTC Counter Readings | General Comments | | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | LTCMechanism | GA-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | LTCMechanism | GA-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | LTCMechanism | GA-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | LTCMechanism | GA-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | LTCMechanism | GA-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | LTCMechanism | GA-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Readings | 9 Month Operations | 1 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Readings | Amps A Ø | 0.0 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Readings | Amps B Ø | 0.0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | WithLTC | GA-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0457 | BreakerAirMagnetic | HE-1 | AMCB Readings | Maintenance Operations | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0457 | BreakerAirMagnetic | HE-1 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0075 | BreakerVacuum | 020-2543 | VCB Readings | Amps C Ø | 0.0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0457 | BreakerAirMagnetic | HE-1 | AMCB Readings | General Comments | | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0424 | BreakerAirMagnetic | GD-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0457 | BreakerAirMagnetic | HE-1 | AMCB Patrol Inspection | General Comments | | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0457 | BreakerAirMagnetic | HE-1 | AMCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0457 | BreakerAirMagnetic | HE-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0457 | BreakerAirMagnetic | HE-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0457 | BreakerAirMagnetic | HE-1 | AMCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0457 | BreakerAirMagnetic | HE-1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0457 | BreakerAirMagnetic | HE-1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0457 | BreakerAirMagnetic | HE-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0457 | BreakerAirMagnetic | HE-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0457 | BreakerAirMagnetic | HE-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0457 | BreakerAirMagnetic | HE-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0368 | BreakerAirMagnetic | FO-3 | AMCB Readings | Unknown Operations | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0368 | BreakerAirMagnetic | FO-3 | AMCB Readings | Switching Operations | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0368 | BreakerAirMagnetic | FO-3 | AMCB Readings | Operations This Read AM | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0368 | BreakerAirMagnetic | FO-3 | AMCB Readings | Operations Counter AL | 288 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0368 | BreakerAirMagnetic | FO-3 | AMCB Readings | Operations Counter AF | 288 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0368 | BreakerAirMagnetic | FO-3 | AMCB Readings | Maintenance Operations | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0368 | BreakerAirMagnetic | FO-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0368 | BreakerAirMagnetic | FO-3 | AMCB Readings | General Comments | | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0430 | BreakerAirMagnetic | HA-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0430 | BreakerAirMagnetic | HA-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0430 | BreakerAirMagnetic | HA-3 | AMCB Readings | 9 Months Operations | 0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0430 | BreakerAirMagnetic | HA-3 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | CH000457 | ControlHouse | FO-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | LTCMechanism | HA-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | LTCMechanism | HA-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | LTCMechanism | HA-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | LTCMechanism | HA-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | LTCMechanism | HA-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | CH000457 | ControlHouse | FO-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | CH000457 | ControlHouse | FO-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | CH000457 | ControlHouse | FO-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | CH000457 | ControlHouse | FO-Battery Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | CH000457 | ControlHouse | FO-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | CH000457 | ControlHouse | FO-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | CH000457 | ControlHouse | FO-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | CH000457 | ControlHouse | FO-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | CH000458 | ControlHouse | GA-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | CH000458 | ControlHouse | GA-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | CH000458 | ControlHouse | GA-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0368 | BreakerAirMagnetic | FO-3 | AMCB Patrol Inspection | General Comments | | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0368 | BreakerAirMagnetic | FO-3 | AMCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0368 | BreakerAirMagnetic | FO-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0368 | BreakerAirMagnetic | FO-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0368 | BreakerAirMagnetic | FO-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0368 | BreakerAirMagnetic | FO-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0368 | BreakerAirMagnetic | FO-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0368 | BreakerAirMagnetic | FO-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0368 | BreakerAirMagnetic | FO-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0368 | BreakerAirMagnetic | FO-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0368 | BreakerAirMagnetic | FO-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0368 | BreakerAirMagnetic | FO-3 | AMCB Readings | Amps C Ø | 100.0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0368 | BreakerAirMagnetic | FO-3 | AMCB Readings | Amps B Ø | 100.0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0368 | BreakerAirMagnetic | FO-3 | AMCB Readings | Amps A Ø | 100.0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000011 | Switchgear | HE-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000011 | Switchgear | HE-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000011 | Switchgear | HE-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Patrol Inspection | General Comments | | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Readings | General Comments | | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | WithLTC | GA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | LTCMechanism | GO-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | LTCMechanism | GO-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | WithLTC | GA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | WithLTC | GA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0460 | BreakerAirMagnetic | HE-4 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0460 | BreakerAirMagnetic | HE-4 | AMCB Readings | 9 Months Operations | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0460 | BreakerAirMagnetic | HE-4 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0460 | BreakerAirMagnetic | HE-4 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0460 | BreakerAirMagnetic | HE-4 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0460 | BreakerAirMagnetic | HE-4 | AMCB Readings | Amps A Ø | 50.0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0460 | BreakerAirMagnetic | HE-4 | AMCB Readings | Amps B Ø | 50.0 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Readings | Maintenance Operations | 0 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Readings | Operations Counter AF | 335 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Readings | Operations Counter AL | 336 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Readings | Operations This Read Vac | 1 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | LTCMechanism | GO-TRANS 1 | LTC Counter Readings | General Comments | | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | LTCMechanism | GO-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | LTCMechanism | GO-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 344384 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Readings | Switching Operations | 1 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0430 | BreakerAirMagnetic | HA-3 | AMCB Readings | Operations This Read AM | 0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0430 | BreakerAirMagnetic | HA-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0430 | BreakerAirMagnetic | HA-3 | AMCB Readings | General Comments | | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0430 | BreakerAirMagnetic | HA-3 | AMCB Patrol Inspection | General Comments | | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0430 | BreakerAirMagnetic | HA-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0430 | BreakerAirMagnetic | HA-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0430 | BreakerAirMagnetic | HA-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0430 | BreakerAirMagnetic | HA-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0430 | BreakerAirMagnetic | HA-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | ST000847 | Structure | 020-Structure Distribution | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | YD000060 | Yard | 312-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | YD000060 | Yard | 312-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0383 | BreakerAirMagnetic | GA-1 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0383 | BreakerAirMagnetic | GA-1 | AMCB Readings | General Comments | | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0383 | BreakerAirMagnetic | GA-1 | AMCB Patrol Inspection | General Comments | | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0383 | BreakerAirMagnetic | GA-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0383 | BreakerAirMagnetic | GA-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | ST000847 | Structure | 020-Structure Distribution | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | BCH000024 | Charger | GO-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0383 | BreakerAirMagnetic | GA-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0383 | BreakerAirMagnetic | GA-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | YD000060 | Yard | 312-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | YD000060 | Yard | 312-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | YD000060 | Yard | 312-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | YD000060 | Yard | 312-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | YD000060 | Yard | 312-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | YD000060 | Yard | 312-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | YD000060 | Yard | 312-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | YD000060 | Yard | 312-Yard | Yard Patrol Inspection | Ambient Temp | 57 | °F |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | FE000061 | Fence | 312-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | FE000061 | Fence | 312-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | FE000061 | Fence | 312-Fence | Fence Patrol Inspection | General Comments | | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | FE000061 | Fence | 312-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Readings | Unknown Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Readings | Operations Counter AL | 357 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Readings | Operations Counter AF | 357 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Readings | Maintenance Operations | 0 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | ST000847 | Structure | 020-Structure Distribution | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | ST000847 | Structure | 020-Structure Distribution | Structure Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | ST000847 | Structure | 020-Structure Distribution | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Readings | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | FE000061 | Fence | 312-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | FE000061 | Fence | 312-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | BAT000096 | Battery | GD-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | BAT000096 | Battery | GD-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 75 | °F |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | BAT000096 | Battery | GD-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 80 | °C |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | ST000425 | Structure | 857-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | ST000425 | Structure | 857-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | ST000425 | Structure | 857-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | ST000425 | Structure | 857-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Readings | General Comments | b,c phase ioc | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | ST000847 | Structure | 020-Structure Distribution | Structure Patrol Inspection | Wood Structures OK? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | ST000543 | Structure | 601-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | ST000543 | Structure | 601-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | ST000543 | Structure | 601-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | ST000543 | Structure | 601-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | ST000543 | Structure | 601-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | ST000847 | Structure | 020-Structure Distribution | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | ST000847 | Structure | 020-Structure Distribution | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | ST000847 | Structure | 020-Structure Distribution | Structure Patrol Inspection | Signage Visible, and Proper? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | ST000847 | Structure | 020-Structure Distribution | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | ST000847 | Structure | 020-Structure Distribution | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | ST000543 | Structure | 601-Structure | Structure Patrol Inspection | General Comments | | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | ST000543 | Structure | 601-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | ST000543 | Structure | 601-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | ST000543 | Structure | 601-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | ST000543 | Structure | 601-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | SWG000069 | Switchgear | GO-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | ST000543 | Structure | 601-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | ST000543 | Structure | 601-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | ST000543 | Structure | 601-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | ST000543 | Structure | 601-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | ST000543 | Structure | 601-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | ST000543 | Structure | 601-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | ST000543 | Structure | 601-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | ST000543 | Structure | 601-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0383 | BreakerAirMagnetic | GA-1 | AMCB Readings | Operations This Read AM | 0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | SWG000069 | Switchgear | GO-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | ST000847 | Structure | 020-Structure Distribution | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | ST000847 | Structure | 020-Structure Distribution | Structure Patrol Inspection | General Comments | | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | ST000847 | Structure | 020-Structure Distribution | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | ST000847 | Structure | 020-Structure Distribution | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | ST000847 | Structure | 020-Structure Distribution | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | ST000847 | Structure | 020-Structure Distribution | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | SWG000069 | Switchgear | GO-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | SWG000069 | Switchgear | GO-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | SWG000069 | Switchgear | GO-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0392 | BreakerAirMagnetic | GO-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0392 | BreakerAirMagnetic | GO-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0392 | BreakerAirMagnetic | GO-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0392 | BreakerAirMagnetic | GO-2 | AMCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0392 | BreakerAirMagnetic | GO-2 | AMCB Patrol Inspection | General Comments | | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0392 | BreakerAirMagnetic | GO-2 | AMCB Readings | General Comments | | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0392 | BreakerAirMagnetic | GO-2 | AMCB Readings | Maintenance Operations | 0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0392 | BreakerAirMagnetic | GO-2 | AMCB Readings | Operations Counter AF | 386 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0392 | BreakerAirMagnetic | GO-2 | AMCB Readings | Operations Counter AL | 386 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0392 | BreakerAirMagnetic | GO-2 | AMCB Readings | Operations This Read AM | 0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0392 | BreakerAirMagnetic | GO-2 | AMCB Readings | Switching Operations | 0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0392 | BreakerAirMagnetic | GO-2 | AMCB Readings | Unknown Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Readings | Accumulated Fault Duty A Ph V | 1.19 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Readings | Accumulated Fault Duty B Ph V | 1.19 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Readings | Accumulated Fault Duty C Ph V | 1.19 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Readings | Amps A Ø | 355.0 | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RG000205 | Regulator | 140-1 | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RG000205 | Regulator | 140-1 | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Readings | Amps B Ø | 355.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Readings | Amps C Ø | 355.0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RG000205 | Regulator | 140-1 | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RG000205 | Regulator | 140-1 | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RG000205 | Regulator | 140-1 | Regulator Patrol Inspection | Current Tap Position | 2R | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RG000205 | Regulator | 140-1 | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RG000205 | Regulator | 140-1 | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RG000205 | Regulator | 140-1 | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RG000205 | Regulator | 140-1 | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RG000205 | Regulator | 140-1 | Regulator Patrol Inspection | General Comments | | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RG000205 | Regulator | 140-1 | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RG000205 | Regulator | 140-1 | Regulator Patrol Inspection | Max Tap Position | 10R | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RG000205 | Regulator | 140-1 | Regulator Patrol Inspection | Min Tap Position | 3L | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RG000205 | Regulator | 140-1 | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | BAT000096 | Battery | GD-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | BAT000096 | Battery | GD-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | BAT000096 | Battery | GD-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 75 | °C |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 80 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PN43 | WithLTC | GO-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | BCH000024 | Charger | GO-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | BCH000026 | Charger | HA-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | BCH000026 | Charger | HA-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | BAT000096 | Battery | GD-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | BAT000096 | Battery | GD-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | BAT000096 | Battery | GD-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | BAT000096 | Battery | GD-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | BAT000096 | Battery | GD-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | BAT000096 | Battery | GD-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | BAT000096 | Battery | GD-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | BAT000096 | Battery | GD-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0392 | BreakerAirMagnetic | GO-2 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0392 | BreakerAirMagnetic | GO-2 | AMCB Readings | 9 Months Operations | 0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0392 | BreakerAirMagnetic | GO-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0392 | BreakerAirMagnetic | GO-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0392 | BreakerAirMagnetic | GO-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0392 | BreakerAirMagnetic | GO-2 | AMCB Readings | Amps A Ø | 85.0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0392 | BreakerAirMagnetic | GO-2 | AMCB Readings | Amps B Ø | 80.0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0392 | BreakerAirMagnetic | GO-2 | AMCB Readings | Amps C Ø | 50.0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0392 | BreakerAirMagnetic | GO-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0392 | BreakerAirMagnetic | GO-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0392 | BreakerAirMagnetic | GO-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0392 | BreakerAirMagnetic | GO-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | FE000419 | Fence | 857-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | n | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | FE000061 | Fence | 312-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | FE000061 | Fence | 312-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | FE000061 | Fence | 312-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RG000205 | Regulator | 140-1 | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | FE000419 | Fence | 857-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | FE000419 | Fence | 857-Fence | Fence Patrol Inspection | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Readings | 9 Month Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | FE000419 | Fence | 857-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | FE000419 | Fence | 857-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0392 | BreakerAirMagnetic | GO-2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0392 | BreakerAirMagnetic | GO-2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BCH001553 | Charger | 312-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BCH001553 | Charger | 312-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.3 | amps |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BCH001553 | Charger | 312-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BCH001553 | Charger | 312-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Readings | Accumulated Fault Duty A Ph V | 1.19 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Readings | Accumulated Fault Duty B Ph V | 1.19 | % |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BCH001553 | Charger | 312-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 2.600 | millivolts |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Readings | Accumulated Fault Duty C Ph V | 1.19 | % |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0391 | BreakerAirMagnetic | GO-1 | AMCB Readings | Operations Counter AL | 472 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0391 | BreakerAirMagnetic | GO-1 | AMCB Readings | Operations This Read AM | 0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0391 | BreakerAirMagnetic | GO-1 | AMCB Readings | Switching Operations | 0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0391 | BreakerAirMagnetic | GO-1 | AMCB Readings | Unknown Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Readings | Amps A Ø | 0.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Readings | Amps B Ø | 0.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Readings | Amps C Ø | 0.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | FE000534 | Fence | 601-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | FE000534 | Fence | 601-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | FE000534 | Fence | 601-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | FE000534 | Fence | 601-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | FE000534 | Fence | 601-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | FE000534 | Fence | 601-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | FE000534 | Fence | 601-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | FE000534 | Fence | 601-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | FE000534 | Fence | 601-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | FE000534 | Fence | 601-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | FE000534 | Fence | 601-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | FE000534 | Fence | 601-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | FE000534 | Fence | 601-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | CH000535 | ControlHouse | 312-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | CH000535 | ControlHouse | 312-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | CH000535 | ControlHouse | 312-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | CH000535 | ControlHouse | 312-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | WithLTC | GA-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | WithLTC | GA-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | CH000535 | ControlHouse | 312-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | LTCC000384 | LTCControl | 020-5 | LTC Control Insp | All Connections OK? | y | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | LTCC000384 | LTCControl | 020-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | CH000535 | ControlHouse | 312-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | LTCC000384 | LTCControl | 020-5 | LTC Control Insp | General Comments | | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000002 | Switchgear | GD-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BK000263 | BreakerAirMagnetic | HE-SEC 1 SPARE | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | YD000496 | Yard | 140-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | YD000496 | Yard | 140-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | YD000496 | Yard | 140-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | YD000496 | Yard | 140-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | YD000496 | Yard | 140-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | YD000496 | Yard | 140-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | YD000496 | Yard | 140-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BK000263 | BreakerAirMagnetic | HE-SEC 1 SPARE | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BK000263 | BreakerAirMagnetic | HE-SEC 1 SPARE | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BK000263 | BreakerAirMagnetic | HE-SEC 1 SPARE | AMCB Readings | 9 Months Operations | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BK000263 | BreakerAirMagnetic | HE-SEC 1 SPARE | AMCB Readings | 9 Month Ops New | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000002 | Switchgear | GD-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000002 | Switchgear | GD-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000002 | Switchgear | GD-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000002 | Switchgear | GD-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000002 | Switchgear | GD-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000002 | Switchgear | GD-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000002 | Switchgear | GD-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000002 | Switchgear | GD-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000002 | Switchgear | GD-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000002 | Switchgear | GD-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000002 | Switchgear | GD-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000002 | Switchgear | GD-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000002 | Switchgear | GD-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | WithLTC | GA-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | WithLTC | GA-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | WithLTC | GA-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PN68 | WithLTC | GA-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000011 | Switchgear | HE-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000011 | Switchgear | HE-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0391 | BreakerAirMagnetic | GO-1 | AMCB Readings | Maintenance Operations | 0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0391 | BreakerAirMagnetic | GO-1 | AMCB Readings | Operations Counter AF | 472 | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | YD000496 | Yard | 140-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | YD000496 | Yard | 140-Yard | Yard Patrol Inspection | General Comments | | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | YD000496 | Yard | 140-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | YD000496 | Yard | 140-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | YD000496 | Yard | 140-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | YD000496 | Yard | 140-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BCH001553 | Charger | 312-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BCH001553 | Charger | 312-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BCH001553 | Charger | 312-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BCH001035 | Charger | HE-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BCH001035 | Charger | HE-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BCH001035 | Charger | HE-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 0.0 | amps |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BCH001035 | Charger | HE-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.7 | VDC |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BCH001035 | Charger | HE-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.7 | VDC |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BCH001035 | Charger | HE-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | ST000067 | Structure | 312-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | ST000067 | Structure | 312-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | ST000067 | Structure | 312-Structure | Structure Patrol Inspection | General Comments | | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | ST000067 | Structure | 312-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | ST000067 | Structure | 312-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | ST000067 | Structure | 312-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | ST000067 | Structure | 312-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | ST000067 | Structure | 312-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | ST000067 | Structure | 312-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | ST000067 | Structure | 312-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | ST000067 | Structure | 312-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | ST000067 | Structure | 312-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | YD000060 | Yard | 312-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | YD000060 | Yard | 312-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | YD000060 | Yard | 312-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | ST000425 | Structure | 857-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | ST000425 | Structure | 857-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | ST000425 | Structure | 857-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | YD000060 | Yard | 312-Yard | Yard Patrol Inspection | General Comments | | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | ST000425 | Structure | 857-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | ST000425 | Structure | 857-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | ST000425 | Structure | 857-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | ST000425 | Structure | 857-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | ST000425 | Structure | 857-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | ST000425 | Structure | 857-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | ST000425 | Structure | 857-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | ST000425 | Structure | 857-Structure | Structure Patrol Inspection | General Comments | | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | ST000425 | Structure | 857-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | ST000425 | Structure | 857-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | ST000425 | Structure | 857-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | ST000425 | Structure | 857-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | FE000534 | Fence | 601-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | ST000543 | Structure | 601-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | ST000543 | Structure | 601-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | ST000543 | Structure | 601-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | ST000543 | Structure | 601-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | ST000425 | Structure | 857-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | LTCC000384 | LTCControl | 020-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | LTCC000384 | LTCControl | 020-5 | LTC Control Insp | LTC Output Voltage Level | 133.8 | VAC |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | LTCC000384 | LTCControl | 020-5 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | LTCC000384 | LTCControl | 020-5 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | WB0171 | BreakerVacuum | 601-0337 | VCB Readings | 9 Month Operations | 5 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | BCH000024 | Charger | GO-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | BCH000024 | Charger | GO-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.7 | VDC |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | CH000535 | ControlHouse | 312-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | CH000535 | ControlHouse | 312-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | CH000535 | ControlHouse | 312-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | CH000535 | ControlHouse | 312-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | CH000535 | ControlHouse | 312-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | CH000535 | ControlHouse | 312-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | CH000535 | ControlHouse | 312-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | CH000535 | ControlHouse | 312-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | CH000535 | ControlHouse | 312-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | CH000535 | ControlHouse | 312-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | BCH000024 | Charger | GO-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.7 | VDC |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | BCH000024 | Charger | GO-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 0.0 | amps |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Readings | Unknown Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Readings | Operations This Read Vac | 8 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | FE000534 | Fence | 601-Fence | Fence Patrol Inspection | General Comments | | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | FE000534 | Fence | 601-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | ST000067 | Structure | 312-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | ST000067 | Structure | 312-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | ST000067 | Structure | 312-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | ST000067 | Structure | 312-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | ST000067 | Structure | 312-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | ST000067 | Structure | 312-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | ST000067 | Structure | 312-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | ST000067 | Structure | 312-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | ST000067 | Structure | 312-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Readings | Operations Counter AL | 399 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Readings | Operations Counter AF | 399 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | ST000067 | Structure | 312-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | ST000425 | Structure | 857-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | ST000425 | Structure | 857-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | BCH001035 | Charger | HE-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000076 | Switchgear | GD-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000076 | Switchgear | GD-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000076 | Switchgear | GD-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000076 | Switchgear | GD-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000076 | Switchgear | GD-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000076 | Switchgear | GD-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000076 | Switchgear | GD-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000076 | Switchgear | GD-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000076 | Switchgear | GD-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000076 | Switchgear | GD-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000071 | Switchgear | HE-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000071 | Switchgear | HE-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000071 | Switchgear | HE-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000071 | Switchgear | HE-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000071 | Switchgear | HE-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000071 | Switchgear | HE-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000071 | Switchgear | HE-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000071 | Switchgear | HE-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000071 | Switchgear | HE-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000071 | Switchgear | HE-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000071 | Switchgear | HE-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000071 | Switchgear | HE-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000071 | Switchgear | HE-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000071 | Switchgear | HE-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | BAT001431 | Battery | GA-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 0 | °C |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 0 | °C |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 0 | °C |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 0 | °C |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 0 | °C |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 0 | °C |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 100.00 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Readings | Switching Operations | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Readings | Operations Counter AL | 179 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Readings | Operations Counter AF | 179 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Readings | General Comments | | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0393 | BreakerAirMagnetic | GO-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0393 | BreakerAirMagnetic | GO-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0393 | BreakerAirMagnetic | GO-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0393 | BreakerAirMagnetic | GO-3 | AMCB Readings | Amps A Ø | 50.0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0393 | BreakerAirMagnetic | GO-3 | AMCB Readings | Amps B Ø | 55.0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0393 | BreakerAirMagnetic | GO-3 | AMCB Readings | Amps C Ø | 55.0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0393 | BreakerAirMagnetic | GO-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0393 | BreakerAirMagnetic | GO-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0393 | BreakerAirMagnetic | GO-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0393 | BreakerAirMagnetic | GO-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0393 | BreakerAirMagnetic | GO-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | LTCC000991 | LTCControl | 337-1 | LTC Control Insp | All Connections OK? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | LTCC000991 | LTCControl | 337-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | LTCC000991 | LTCControl | 337-1 | LTC Control Insp | General Comments | | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | LTCC000991 | LTCControl | 337-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0393 | BreakerAirMagnetic | GO-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | LTCC000991 | LTCControl | 337-1 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | LTCC000991 | LTCControl | 337-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | LTCC000991 | LTCControl | 337-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | LTCC000991 | LTCControl | 337-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001240 | RecloserHydraulic | 140-0333-2 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | LTCC000991 | LTCControl | 337-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0114 | Regulator | 857-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0114 | Regulator | 857-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0114 | Regulator | 857-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0114 | Regulator | 857-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0114 | Regulator | 857-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 26001 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0114 | Regulator | 857-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.8 | volts |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0114 | Regulator | 857-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0114 | Regulator | 857-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0114 | Regulator | 857-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0114 | Regulator | 857-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0114 | Regulator | 857-1 B | Regulator Patrol Inspection | Min Tap Position | 13L | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0393 | BreakerAirMagnetic | GO-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0393 | BreakerAirMagnetic | GO-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0393 | BreakerAirMagnetic | GO-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0393 | BreakerAirMagnetic | GO-3 | AMCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0393 | BreakerAirMagnetic | GO-3 | AMCB Patrol Inspection | General Comments | | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0393 | BreakerAirMagnetic | GO-3 | AMCB Readings | General Comments | | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0393 | BreakerAirMagnetic | GO-3 | AMCB Readings | Maintenance Operations | 0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0393 | BreakerAirMagnetic | GO-3 | AMCB Readings | Operations Counter AF | 446 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0393 | BreakerAirMagnetic | GO-3 | AMCB Readings | Operations Counter AL | 446 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0393 | BreakerAirMagnetic | GO-3 | AMCB Readings | Operations This Read AM | 0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0393 | BreakerAirMagnetic | GO-3 | AMCB Readings | Switching Operations | 0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0393 | BreakerAirMagnetic | GO-3 | AMCB Readings | Unknown Operations | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000076 | Switchgear | GD-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000076 | Switchgear | GD-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000076 | Switchgear | GD-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000076 | Switchgear | GD-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000076 | Switchgear | GD-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | SWG000076 | Switchgear | GD-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Readings | Fault Adjusted Amps A Phase V | 5.07 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Readings | Amps C Ø | 90.0 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Readings | Amps B Ø | 78.0 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Readings | Amps A Ø | 100.0 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Readings | 9 Month Operations | 2 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Readings | Amps C Ø | 286.0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Readings | Amps B Ø | 290.0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Readings | Amps A Ø | 267.0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Readings | 9 Month Operations | 1 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | BAT001431 | Battery | GA-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | BAT001431 | Battery | GA-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | BAT001431 | Battery | GA-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | BAT001431 | Battery | GA-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | BAT001431 | Battery | GA-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | BAT001431 | Battery | GA-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | BAT001431 | Battery | GA-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK000498 | BreakerVacuum | 312-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Readings | 9 Month Operations | 10 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Readings | Amps A Ø | 36.0 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Readings | Amps B Ø | 49.0 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Readings | Amps C Ø | 54.0 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Patrol Inspection | General Comments | | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Readings | General Comments | | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Readings | Maintenance Operations | 5 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Readings | Operations Counter AF | 224 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Readings | Operations Counter AL | 225 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Readings | Operations This Read Vac | 8 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Readings | Switching Operations | 3 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Readings | Unknown Operations | 0 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Readings | Switching Operations | 1 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Readings | Operations This Read Vac | 2 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Readings | Operations Counter AL | 158 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Readings | Operations Counter AF | 157 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Readings | Maintenance Operations | 0 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Readings | General Comments | | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Patrol Inspection | General Comments | | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Readings | Fault Operations A Ø | 1 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001433 | BreakerVacuum | 857-0331 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 110.00 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Readings | Operations Counter AF | 152 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Readings | Operations Counter AL | 152 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Readings | Operations This Read Vac | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Readings | Switching Operations | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | ST000499 | Structure | 140-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | PN45 | WithLTC | HA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | ST000499 | Structure | 140-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | ST000499 | Structure | 140-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | ST000499 | Structure | 140-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | ST000499 | Structure | 140-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | ST000499 | Structure | 140-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | ST000499 | Structure | 140-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | ST000499 | Structure | 140-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | ST000499 | Structure | 140-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | ST000499 | Structure | 140-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | ST000499 | Structure | 140-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | ST000499 | Structure | 140-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | ST000499 | Structure | 140-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | ST000499 | Structure | 140-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | ST000499 | Structure | 140-Structure | Structure Patrol Inspection | General Comments | | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | ST000499 | Structure | 140-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | ST000499 | Structure | 140-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Readings | 9 Month Operations | 9 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Readings | Amps A Ø | 52.0 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | BAT001435 | Battery | HA-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | BAT001435 | Battery | HA-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | BAT001435 | Battery | HA-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | BAT001435 | Battery | HA-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | BAT001435 | Battery | HA-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | BAT001435 | Battery | HA-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | BAT001435 | Battery | HA-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | BAT001435 | Battery | HA-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | BAT001435 | Battery | HA-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | BAT001435 | Battery | HA-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001237 | RecloserHydraulic | 140-0333-1 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | YD000570 | Yard | HA-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | YD000570 | Yard | HA-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | YD000570 | Yard | HA-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | YD000570 | Yard | HA-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | YD000570 | Yard | HA-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | YD000570 | Yard | HA-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | YD000570 | Yard | HA-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | YD000570 | Yard | HA-Yard | Yard Patrol Inspection | General Comments | | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | YD000570 | Yard | HA-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | YD000570 | Yard | HA-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | YD000570 | Yard | HA-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | YD000570 | Yard | HA-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Readings | 9 Month Operations | 3 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Readings | Amps A Ø | 86.0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Readings | Amps B Ø | 83.0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Readings | Amps C Ø | 82.0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Readings | Fault Operations Ground | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001250 | BreakerVacuum | 312-4643 | VCB Readings | General Comments | | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .8 | psi |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 30 | °C |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 60 | °C |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 25 | °C |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 60 | °C |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 24 | °C |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 60 | °C |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | B0357 | LTCMechanism | 020-5 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | B0357 | LTCMechanism | 020-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | B0357 | LTCMechanism | 020-5 | LTC Counter Readings | LTC As Left Counter | 102884 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | B0357 | LTCMechanism | 020-5 | LTC Counter Readings | LTC As Found Counter | 102884 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | B0357 | LTCMechanism | 020-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | B0357 | LTCMechanism | 020-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | B0357 | LTCMechanism | 020-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0115 | Regulator | 857-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0115 | Regulator | 857-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0115 | Regulator | 857-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0115 | Regulator | 857-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0115 | Regulator | 857-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | BAT001432 | Battery | GO-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | BAT001432 | Battery | GO-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | BAT001432 | Battery | GO-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | BAT001432 | Battery | GO-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | BAT001432 | Battery | GO-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | BAT001432 | Battery | GO-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | BAT001432 | Battery | GO-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | BAT001432 | Battery | GO-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | BAT001432 | Battery | GO-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | BAT001432 | Battery | GO-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | BAT001432 | Battery | GO-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 71 | °F |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | BAT001432 | Battery | GO-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0393 | BreakerAirMagnetic | GO-3 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | LB0393 | BreakerAirMagnetic | GO-3 | AMCB Readings | 9 Months Operations | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Readings | Amps B Ø | 56.0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Readings | Amps C Ø | 61.0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | ST000499 | Structure | 140-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | ST000499 | Structure | 140-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | ST000499 | Structure | 140-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | ST000499 | Structure | 140-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | ST000499 | Structure | 140-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | ST000499 | Structure | 140-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | ST000499 | Structure | 140-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0425 | BreakerAirMagnetic | GD-4 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0425 | BreakerAirMagnetic | GD-4 | AMCB Patrol Inspection | General Comments | | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0425 | BreakerAirMagnetic | GD-4 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | LB0425 | BreakerAirMagnetic | GD-4 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Readings | General Comments | | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Readings | Operations Counter AF | 180 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Readings | Operations Counter AL | 180 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Readings | Operations This Read Vac | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Readings | Switching Operations | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BK001251 | BreakerVacuum | 312-4644 | VCB Readings | Unknown Operations | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | B0357 | LTCMechanism | 020-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | B0357 | LTCMechanism | 020-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | B0357 | LTCMechanism | 020-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | B0357 | LTCMechanism | 020-5 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | B0357 | LTCMechanism | 020-5 | LTC Counter Readings | LTC Operations Since Last Insp | 1857 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | B0357 | LTCMechanism | 020-5 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | B0357 | LTCMechanism | 020-5 | LTC Counter Readings | LTC Min Tap Position | 1L | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | B0357 | LTCMechanism | 020-5 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN46 | WithLTC | HE-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | SWG000008 | Switchgear | HA-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | SWG000008 | Switchgear | HA-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | SWG000008 | Switchgear | HA-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | SWG000008 | Switchgear | HA-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | SWG000008 | Switchgear | HA-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BAT001307 | Battery | 601-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.2 | VDC |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BAT001307 | Battery | 601-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.3 | VDC |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BAT001307 | Battery | 601-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BAT001307 | Battery | 601-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BAT001307 | Battery | 601-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BAT001307 | Battery | 601-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BAT001307 | Battery | 601-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BAT001307 | Battery | 601-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BAT001307 | Battery | 601-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BAT001307 | Battery | 601-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BAT001307 | Battery | 601-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BAT001307 | Battery | 601-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 53 | °F |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BAT001307 | Battery | 601-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0114 | Regulator | 857-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0114 | Regulator | 857-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0114 | Regulator | 857-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0367 | BreakerAirMagnetic | FO-2 | AMCB Readings | Unknown Operations | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0367 | BreakerAirMagnetic | FO-2 | AMCB Readings | Switching Operations | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0367 | BreakerAirMagnetic | FO-2 | AMCB Readings | Operations This Read AM | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0367 | BreakerAirMagnetic | FO-2 | AMCB Readings | Operations Counter AL | 373 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0367 | BreakerAirMagnetic | FO-2 | AMCB Readings | Operations Counter AF | 373 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0367 | BreakerAirMagnetic | FO-2 | AMCB Readings | Maintenance Operations | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0367 | BreakerAirMagnetic | FO-2 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0367 | BreakerAirMagnetic | FO-2 | AMCB Readings | General Comments | | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0367 | BreakerAirMagnetic | FO-2 | AMCB Patrol Inspection | General Comments | | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0367 | BreakerAirMagnetic | FO-2 | AMCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0367 | BreakerAirMagnetic | FO-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0367 | BreakerAirMagnetic | FO-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0367 | BreakerAirMagnetic | FO-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0367 | BreakerAirMagnetic | FO-2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0367 | BreakerAirMagnetic | FO-2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0367 | BreakerAirMagnetic | FO-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0114 | Regulator | 857-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0114 | Regulator | 857-1 B | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0114 | Regulator | 857-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0114 | Regulator | 857-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0114 | Regulator | 857-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 7361.28 | kw |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0428 | BreakerAirMagnetic | HA-1 | AMCB Readings | 9 Months Operations | 1 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0428 | BreakerAirMagnetic | HA-1 | AMCB Readings | 9 Month Ops New | 1 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0113 | Regulator | 857-1 A | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Readings | LTC Totalizer Reading | 12706.56 | kw |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Readings | General Comments | | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0113 | Regulator | 857-1 A | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0113 | Regulator | 857-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0113 | Regulator | 857-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0113 | Regulator | 857-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0113 | Regulator | 857-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0113 | Regulator | 857-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 125.3 | volts |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | LTCC000920 | LTCControl | 312-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | LTCC000920 | LTCControl | 312-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | LTCC000920 | LTCControl | 312-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | LTCC000920 | LTCControl | 312-1 | LTC Control Insp | LTC Output Voltage Level | 124.4 | VAC |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | LTCC000920 | LTCControl | 312-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | LTCC000920 | LTCControl | 312-1 | LTC Control Insp | General Comments | | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | LTCC000920 | LTCControl | 312-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | LTCC000920 | LTCControl | 312-1 | LTC Control Insp | All Connections OK? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Readings | General Comments | | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BCH001246 | Charger | 601-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.0 | amps |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BCH001246 | Charger | 601-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BCH001246 | Charger | 601-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BCH001246 | Charger | 601-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BAT001307 | Battery | 601-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BAT001307 | Battery | 601-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | SWG000008 | Switchgear | HA-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | SWG000008 | Switchgear | HA-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | SWG000008 | Switchgear | HA-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | SWG000008 | Switchgear | HA-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | SWG000008 | Switchgear | HA-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | SWG000008 | Switchgear | HA-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | SWG000008 | Switchgear | HA-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | SWG000008 | Switchgear | HA-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | SWG000008 | Switchgear | HA-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | YD000423 | Yard | 857-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | YD000423 | Yard | 857-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | YD000423 | Yard | 857-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | YD000423 | Yard | 857-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | YD000423 | Yard | 857-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | YD000423 | Yard | 857-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | YD000423 | Yard | 857-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | YD000423 | Yard | 857-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | FE000082 | Fence | 715-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | FE000082 | Fence | 715-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | FE000082 | Fence | 715-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | n | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | FE000082 | Fence | 715-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | FE000082 | Fence | 715-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | FE000082 | Fence | 715-Fence | Fence Patrol Inspection | Fence Grounds in Place? | n | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | FE000082 | Fence | 715-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | FE000082 | Fence | 715-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | FE000082 | Fence | 715-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | FE000082 | Fence | 715-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | FE000082 | Fence | 715-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | FE000082 | Fence | 715-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | FE000082 | Fence | 715-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | FE000082 | Fence | 715-Fence | Fence Patrol Inspection | General Comments | | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | FE000082 | Fence | 715-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/8/2023 7:13 | Distribution | Gardner Quarterly Inspection | FE000082 | Fence | 715-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Readings | 9 Month Operations | 1 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Readings | Accumulated Fault Duty A Ph V | 1.79 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Readings | Accumulated Fault Duty B Ph V | 1.19 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Readings | Accumulated Fault Duty C Ph V | 1.19 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Readings | Amps A Ø | 380.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Readings | Amps B Ø | 380.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Readings | Amps C Ø | 380.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | B0357 | WithLTC | 020-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | B0357 | WithLTC | 020-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | B0357 | WithLTC | 020-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | B0357 | WithLTC | 020-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | B0357 | WithLTC | 020-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | B0357 | WithLTC | 020-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Readings | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Readings | Operations Counter AF | 365 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Readings | Operations Counter AL | 365 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Readings | Operations This Read Vac | 1 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Readings | Switching Operations | 1 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Readings | Unknown Operations | 0 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0114 | Regulator | 857-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0114 | Regulator | 857-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0367 | BreakerAirMagnetic | FO-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0367 | BreakerAirMagnetic | FO-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0367 | BreakerAirMagnetic | FO-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0367 | BreakerAirMagnetic | FO-2 | AMCB Readings | Amps C Ø | 150.0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0367 | BreakerAirMagnetic | FO-2 | AMCB Readings | Amps B Ø | 150.0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0367 | BreakerAirMagnetic | FO-2 | AMCB Readings | Amps A Ø | 100.0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0367 | BreakerAirMagnetic | FO-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0367 | BreakerAirMagnetic | FO-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0367 | BreakerAirMagnetic | FO-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0113 | Regulator | 857-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0367 | BreakerAirMagnetic | FO-2 | AMCB Readings | 9 Months Operations | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0367 | BreakerAirMagnetic | FO-2 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0113 | Regulator | 857-1 A | Regulator Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0113 | Regulator | 857-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0113 | Regulator | 857-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0113 | Regulator | 857-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 32628 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | YD000539 | Yard | 601-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | YD000539 | Yard | 601-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | YD000539 | Yard | 601-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | YD000539 | Yard | 601-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | YD000539 | Yard | 601-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | YD000539 | Yard | 601-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | YD000539 | Yard | 601-Yard | Yard Patrol Inspection | General Comments | | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | YD000539 | Yard | 601-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | YD000539 | Yard | 601-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | YD000539 | Yard | 601-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | YD000539 | Yard | 601-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | YD000539 | Yard | 601-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | YD000539 | Yard | 601-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | YD000539 | Yard | 601-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | YD000539 | Yard | 601-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | YD000539 | Yard | 601-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | YD000539 | Yard | 601-Yard | Yard Patrol Inspection | Ambient Temp | 53 | °F |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | YD000423 | Yard | 857-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | YD000423 | Yard | 857-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | YD000423 | Yard | 857-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | YD000423 | Yard | 857-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | n | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | YD000423 | Yard | 857-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | YD000423 | Yard | 857-Yard | Yard Patrol Inspection | General Comments | | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | YD000423 | Yard | 857-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Readings | Unknown Operations | 0 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Readings | Switching Operations | 1 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Readings | Operations This Read Vac | 1 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Readings | Operations Counter AL | 208 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Readings | Operations Counter AF | 207 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Readings | Maintenance Operations | 0 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Readings | General Comments | | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Patrol Inspection | General Comments | | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Readings | Amps C Ø | 64.0 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Readings | Amps B Ø | 59.0 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Readings | Amps A Ø | 62.0 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BK001432 | BreakerVacuum | 857-0330 | VCB Readings | 9 Month Operations | 7 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | FE000561 | Fence | HA-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | FE000561 | Fence | HA-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | FE000561 | Fence | HA-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | FE000561 | Fence | HA-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | FE000561 | Fence | HA-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | FE000561 | Fence | HA-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PF001319 | PowerFuse | GO-4KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PF001319 | PowerFuse | GO-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | PF001319 | PowerFuse | GO-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | FE000561 | Fence | HA-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | FE000561 | Fence | HA-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | FE000561 | Fence | HA-Fence | Fence Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | FE000561 | Fence | HA-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | FE000561 | Fence | HA-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001240 | RecloserHydraulic | 140-0333-2 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PF001320 | PowerFuse | HE-4KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PF001320 | PowerFuse | HE-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | BAT001431 | Battery | GA-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | BAT001431 | Battery | GA-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000071 | Switchgear | HE-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BK000476 | BreakerVacuum | 601-0336 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0384 | BreakerAirMagnetic | GA-2 | AMCB Readings | Operations This Read AM | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0384 | BreakerAirMagnetic | GA-2 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0384 | BreakerAirMagnetic | GA-2 | AMCB Readings | General Comments | | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0384 | BreakerAirMagnetic | GA-2 | AMCB Patrol Inspection | General Comments | | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0384 | BreakerAirMagnetic | GA-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0384 | BreakerAirMagnetic | GA-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | SWG000071 | Switchgear | HE-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0384 | BreakerAirMagnetic | GA-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0384 | BreakerAirMagnetic | GA-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0384 | BreakerAirMagnetic | GA-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 2.13 | % |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0384 | BreakerAirMagnetic | GA-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 2.13 | % |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0384 | BreakerAirMagnetic | GA-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 2.13 | % |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0384 | BreakerAirMagnetic | GA-2 | AMCB Readings | 9 Months Operations | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | LB0384 | BreakerAirMagnetic | GA-2 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PN54 | WithLTC | HE-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Readings | Amps C Ø | 73.0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Readings | Amps B Ø | 80.0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Readings | Amps A Ø | 69.0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Readings | 9 Month Operations | 4 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | FE000561 | Fence | HA-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | FE000561 | Fence | HA-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | FE000561 | Fence | HA-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | FE000561 | Fence | HA-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.3236 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0114 | Regulator | 857-1 B | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0114 | Regulator | 857-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0114 | Regulator | 857-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0428 | BreakerAirMagnetic | HA-1 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0428 | BreakerAirMagnetic | HA-1 | AMCB Readings | General Comments | | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0428 | BreakerAirMagnetic | HA-1 | AMCB Patrol Inspection | General Comments | | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0428 | BreakerAirMagnetic | HA-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0428 | BreakerAirMagnetic | HA-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0428 | BreakerAirMagnetic | HA-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0428 | BreakerAirMagnetic | HA-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0428 | BreakerAirMagnetic | HA-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 1.07 | % |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0428 | BreakerAirMagnetic | HA-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0428 | BreakerAirMagnetic | HA-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0113 | Regulator | 857-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0113 | Regulator | 857-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0113 | Regulator | 857-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0113 | Regulator | 857-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0113 | Regulator | 857-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0113 | Regulator | 857-1 A | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0113 | Regulator | 857-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0113 | Regulator | 857-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0113 | Regulator | 857-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0113 | Regulator | 857-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0113 | Regulator | 857-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0113 | Regulator | 857-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BAT000952 | Battery | 857-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BAT000952 | Battery | 857-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BAT000952 | Battery | 857-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.1 | VDC |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BAT000952 | Battery | 857-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.3 | VDC |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BAT000952 | Battery | 857-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BAT000952 | Battery | 857-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BAT000952 | Battery | 857-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BAT000952 | Battery | 857-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BAT000952 | Battery | 857-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BAT000952 | Battery | 857-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BAT000952 | Battery | 857-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BAT000952 | Battery | 857-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BAT000952 | Battery | 857-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BAT000952 | Battery | 857-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 55 | °F |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BAT000952 | Battery | 857-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 95.00 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PF001320 | PowerFuse | HE-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001240 | RecloserHydraulic | 140-0333-2 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0.0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PF001321 | PowerFuse | HE-4KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PF001321 | PowerFuse | HE-4KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | PF001321 | PowerFuse | HE-4KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001240 | RecloserHydraulic | 140-0333-2 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001240 | RecloserHydraulic | 140-0333-2 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 0 | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001240 | RecloserHydraulic | 140-0333-2 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001240 | RecloserHydraulic | 140-0333-2 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001240 | RecloserHydraulic | 140-0333-2 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 0 | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001240 | RecloserHydraulic | 140-0333-2 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001240 | RecloserHydraulic | 140-0333-2 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001240 | RecloserHydraulic | 140-0333-2 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001240 | RecloserHydraulic | 140-0333-2 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001240 | RecloserHydraulic | 140-0333-2 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001240 | RecloserHydraulic | 140-0333-2 | Recloser Hydraulic Patrol Inspection | Operations Counter | 31 | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001240 | RecloserHydraulic | 140-0333-2 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BCH001246 | Charger | 601-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BCH001246 | Charger | 601-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | BCH001246 | Charger | 601-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | YD000664 | Yard | GO-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | YD000664 | Yard | GO-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | YD000664 | Yard | GO-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | YD000664 | Yard | GO-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | YD000664 | Yard | GO-Yard | Yard Patrol Inspection | General Comments | | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | YD000664 | Yard | GO-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | YD000664 | Yard | GO-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | YD000664 | Yard | GO-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | YD000664 | Yard | GO-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | YD000664 | Yard | GO-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | YD000664 | Yard | GO-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | YD000664 | Yard | GO-Yard | Yard Patrol Inspection | Ambient Temp | 44 | °F |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | FE000659 | Fence | GO-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | FE000659 | Fence | GO-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | FE000659 | Fence | GO-Fence | Fence Patrol Inspection | General Comments | | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | FE000659 | Fence | GO-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | FE000659 | Fence | GO-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | FE000659 | Fence | GO-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | FE000659 | Fence | GO-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | FE000659 | Fence | GO-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | FE000659 | Fence | GO-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | FE000659 | Fence | GO-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | FE000659 | Fence | GO-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | FE000659 | Fence | GO-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | FE000659 | Fence | GO-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | FE000659 | Fence | GO-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | FE000659 | Fence | GO-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | FE000659 | Fence | GO-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001240 | RecloserHydraulic | 140-0333-2 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 5:02 | Distribution | Hale Quarterly Inspection | LB0428 | BreakerAirMagnetic | HA-1 | AMCB Readings | Operations This Read AM | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | WithLTC | 337-1 | LTC Transformer Readings | Winding Temp Max | 35 | °C |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | YD000669 | Yard | FO-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | YD000669 | Yard | FO-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | YD000669 | Yard | FO-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | YD000669 | Yard | FO-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | YD000669 | Yard | FO-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | YD000669 | Yard | FO-Yard | Yard Patrol Inspection | General Comments | | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | YD000669 | Yard | FO-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | YD000669 | Yard | FO-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | YD000604 | Yard | GD-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | YD000604 | Yard | GD-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | YD000604 | Yard | GD-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | YD000604 | Yard | GD-Yard | Yard Patrol Inspection | General Comments | | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | YD000604 | Yard | GD-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | YD000604 | Yard | GD-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | YD000604 | Yard | GD-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | YD000604 | Yard | GD-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | YD000604 | Yard | GD-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | YD000604 | Yard | GD-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Readings | Winding Temp Present | 32 | °C |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Readings | Winding Temp Max | 46 | °C |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.4826 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | YD000604 | Yard | GD-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | YD000669 | Yard | FO-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | YD000669 | Yard | FO-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | YD000669 | Yard | FO-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | YD000669 | Yard | FO-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Readings | Switching Operations | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Readings | Operations This Read Vac | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Readings | Oil Temp Present | 32 | °C |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Readings | Oil Temp Max | 32 | °C |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Readings | LTC Totalizer Reading | 14232.96 | kw |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Readings | General Comments | | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | FE000662 | Fence | FO-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | FE000662 | Fence | FO-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | FE000662 | Fence | FO-Fence | Fence Patrol Inspection | General Comments | 3'9" tall and 5'7" from fence | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | FE000662 | Fence | FO-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0463 | BreakerAirMagnetic | HE-SEC 2 SPARE | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0463 | BreakerAirMagnetic | HE-SEC 2 SPARE | AMCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0463 | BreakerAirMagnetic | HE-SEC 2 SPARE | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0463 | BreakerAirMagnetic | HE-SEC 2 SPARE | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0463 | BreakerAirMagnetic | HE-SEC 2 SPARE | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0463 | BreakerAirMagnetic | HE-SEC 2 SPARE | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0463 | BreakerAirMagnetic | HE-SEC 2 SPARE | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0463 | BreakerAirMagnetic | HE-SEC 2 SPARE | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0463 | BreakerAirMagnetic | HE-SEC 2 SPARE | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0463 | BreakerAirMagnetic | HE-SEC 2 SPARE | AMCB Readings | 9 Months Operations | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0463 | BreakerAirMagnetic | HE-SEC 2 SPARE | AMCB Readings | 9 Month Ops New | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | YD000669 | Yard | FO-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | FE000601 | Fence | GD-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | FE000601 | Fence | GD-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | FE000601 | Fence | GD-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | FE000601 | Fence | GD-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | FE000601 | Fence | GD-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BAT001298 | Battery | 312-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BAT001298 | Battery | 312-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BAT001298 | Battery | 312-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BAT001298 | Battery | 312-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BAT001298 | Battery | 312-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BAT001298 | Battery | 312-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BAT001298 | Battery | 312-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BAT001298 | Battery | 312-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BAT001298 | Battery | 312-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BAT001298 | Battery | 312-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BAT001298 | Battery | 312-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.7 | VDC |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BAT001298 | Battery | 312-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.0 | VDC |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BAT001298 | Battery | 312-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | BAT001298 | Battery | 312-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | FE000601 | Fence | GD-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | FE000601 | Fence | GD-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | FE000601 | Fence | GD-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | FE000601 | Fence | GD-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | FE000601 | Fence | GD-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | FE000601 | Fence | GD-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | FE000601 | Fence | GD-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | FE000601 | Fence | GD-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | FE000601 | Fence | GD-Fence | Fence Patrol Inspection | General Comments | | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | FE000601 | Fence | GD-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0115 | Regulator | 857-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0115 | Regulator | 857-1 C | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0115 | Regulator | 857-1 C | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | FE000601 | Fence | GD-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | YD000604 | Yard | GD-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | YD000604 | Yard | GD-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | YD000604 | Yard | GD-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | YD000669 | Yard | FO-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Readings | Amps A Ø | 140.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Readings | Accumulated Fault Duty C Ph V | 1.19 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Readings | Accumulated Fault Duty B Ph V | 5.37 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Readings | Accumulated Fault Duty A Ph V | 5.96 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Readings | 9 Month Operations | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | FE000662 | Fence | FO-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | FE000662 | Fence | FO-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | FE000662 | Fence | FO-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | FE000662 | Fence | FO-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | FE000662 | Fence | FO-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | FE000662 | Fence | FO-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0115 | Regulator | 857-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0115 | Regulator | 857-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0115 | Regulator | 857-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0115 | Regulator | 857-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0115 | Regulator | 857-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0115 | Regulator | 857-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0115 | Regulator | 857-1 C | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Readings | Operations Counter AL | 199 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Readings | Operations Counter AF | 199 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Readings | General Comments | | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Readings | 9 Month Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Readings | Accumulated Fault Duty A Ph V | 2.98 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Readings | Accumulated Fault Duty B Ph V | 2.39 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Readings | Accumulated Fault Duty C Ph V | 2.39 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Readings | Amps A Ø | 0.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Readings | Amps B Ø | 0.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Readings | Amps C Ø | 0.0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | BAT001437 | Battery | FO-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | WithLTC | 312-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Readings | Unknown Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Readings | Operations Counter AL | 405 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Readings | Operations Counter AF | 405 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0366 | BreakerAirMagnetic | FO-1 | AMCB Readings | Unknown Operations | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0366 | BreakerAirMagnetic | FO-1 | AMCB Readings | Switching Operations | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0366 | BreakerAirMagnetic | FO-1 | AMCB Readings | Operations This Read AM | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0366 | BreakerAirMagnetic | FO-1 | AMCB Readings | Operations Counter AL | 99955 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0366 | BreakerAirMagnetic | FO-1 | AMCB Readings | Operations Counter AF | 99955 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0366 | BreakerAirMagnetic | FO-1 | AMCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Readings | Maintenance Operations | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | FE000662 | Fence | FO-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | FE000662 | Fence | FO-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | FE000662 | Fence | FO-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | FE000662 | Fence | FO-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | FE000662 | Fence | FO-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | FE000662 | Fence | FO-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Readings | General Comments | | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0366 | BreakerAirMagnetic | FO-1 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0366 | BreakerAirMagnetic | FO-1 | AMCB Readings | General Comments | | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0366 | BreakerAirMagnetic | FO-1 | AMCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0366 | BreakerAirMagnetic | FO-1 | AMCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0366 | BreakerAirMagnetic | FO-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0366 | BreakerAirMagnetic | FO-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0366 | BreakerAirMagnetic | FO-1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0366 | BreakerAirMagnetic | FO-1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0366 | BreakerAirMagnetic | FO-1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0366 | BreakerAirMagnetic | FO-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0366 | BreakerAirMagnetic | FO-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0366 | BreakerAirMagnetic | FO-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0366 | BreakerAirMagnetic | FO-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0366 | BreakerAirMagnetic | FO-1 | AMCB Readings | Amps C Ø | 50.0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0366 | BreakerAirMagnetic | FO-1 | AMCB Readings | Amps B Ø | 50.0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0366 | BreakerAirMagnetic | FO-1 | AMCB Readings | Amps A Ø | 50.0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0366 | BreakerAirMagnetic | FO-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0366 | BreakerAirMagnetic | FO-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0366 | BreakerAirMagnetic | FO-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0366 | BreakerAirMagnetic | FO-1 | AMCB Readings | 9 Months Operations | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | LB0366 | BreakerAirMagnetic | FO-1 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Readings | Amps C Ø | 140.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Readings | Amps B Ø | 140.0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | ST000011 | Structure | 337-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | ST000011 | Structure | 337-Structure | Structure Patrol Inspection | General Comments | | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | ST000011 | Structure | 337-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | ST000011 | Structure | 337-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | ST000011 | Structure | 337-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | ST000011 | Structure | 337-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | ST000011 | Structure | 337-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | ST000011 | Structure | 337-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | ST000011 | Structure | 337-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | ST000011 | Structure | 337-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | ST000011 | Structure | 337-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | YD000012 | Yard | 337-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | YD000012 | Yard | 337-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | YD000012 | Yard | 337-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | YD000012 | Yard | 337-Yard | Yard Patrol Inspection | General Comments | | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | YD000012 | Yard | 337-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | YD000012 | Yard | 337-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | YD000012 | Yard | 337-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | YD000012 | Yard | 337-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | YD000012 | Yard | 337-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | YD000012 | Yard | 337-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | YD000012 | Yard | 337-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | YD000012 | Yard | 337-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | YD000012 | Yard | 337-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | YD000012 | Yard | 337-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | SWG000075 | Switchgear | GA-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | SWG000075 | Switchgear | GA-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | SWG000075 | Switchgear | GA-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | SWG000075 | Switchgear | GA-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | SWG000075 | Switchgear | GA-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | SWG000075 | Switchgear | GA-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | SWG000075 | Switchgear | GA-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | SWG000075 | Switchgear | GA-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | SWG000075 | Switchgear | GA-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | SWG000075 | Switchgear | GA-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | SWG000075 | Switchgear | GA-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | SWG000075 | Switchgear | GA-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | SWG000075 | Switchgear | GA-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | C0536 | NonLTC | 140-1 AC | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | C0536 | NonLTC | 140-1 AC | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Readings | Operations Counter AL | 361 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Readings | Operations Counter AF | 361 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Readings | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | CH000475 | ControlHouse | GO-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | CH000475 | ControlHouse | GO-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | CH000475 | ControlHouse | GO-Battery Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Readings | Amps C Ø | 60.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Readings | Amps B Ø | 60.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Readings | Amps A Ø | 60.0 | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | CH000475 | ControlHouse | GO-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | CH000475 | ControlHouse | GO-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | CH000475 | ControlHouse | GO-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 2/8/2023 11:19 | Distribution | Goss Quarterly Inspection | CH000475 | ControlHouse | GO-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Readings | Accumulated Fault Duty C Ph V | .6 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Readings | Accumulated Fault Duty B Ph V | 1.19 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Readings | Accumulated Fault Duty A Ph V | 1.19 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Readings | 9 Month Operations | 9 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Readings | Amps C Ø | 64.0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Readings | Amps B Ø | 41.0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Readings | Amps A Ø | 46.0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | ST000011 | Structure | 337-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | ST000011 | Structure | 337-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | ST000011 | Structure | 337-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | ST000011 | Structure | 337-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | ST000011 | Structure | 337-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | ST000011 | Structure | 337-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | ST000011 | Structure | 337-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | ST000011 | Structure | 337-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | ST000011 | Structure | 337-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | ST000011 | Structure | 337-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | ST000011 | Structure | 337-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Readings | Amps C Ø | 100.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Readings | Amps B Ø | 100.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Readings | Amps A Ø | 100.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Readings | Accumulated Fault Duty C Ph V | 5.83 | % |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0115 | Regulator | 857-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0115 | Regulator | 857-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0115 | Regulator | 857-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0115 | Regulator | 857-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0115 | Regulator | 857-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 29172 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0115 | Regulator | 857-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.8 | volts |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0115 | Regulator | 857-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0115 | Regulator | 857-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | KR0115 | Regulator | 857-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Readings | Accumulated Fault Duty B Ph V | 13.33 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Readings | Accumulated Fault Duty A Ph V | 10 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Readings | 9 Month Operations | 0 | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | C0536 | NonLTC | 140-1 AC | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | C0536 | NonLTC | 140-1 AC | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | C0536 | NonLTC | 140-1 AC | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PF001310 | PowerFuse | FO-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | PF001310 | PowerFuse | FO-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PF001311 | PowerFuse | GA-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | PF001311 | PowerFuse | GA-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | LTCMechanism | 601-1 | LTC Counter Readings | LTC Operations Since Last Insp | 337 | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | LTCMechanism | 601-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | LTCMechanism | 601-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/8/2023 14:52 | Distribution | Dark Hollow Quarterly Inspection | C0530 | LTCMechanism | 601-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000388 | BreakerVacuum | 337-4641 | VCB Readings | 9 Month Operations | 6 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | BK000387 | BreakerVacuum | 337-4640 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PF001313 | PowerFuse | GD-4KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PF001313 | PowerFuse | GD-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PF001313 | PowerFuse | GD-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PF001314 | PowerFuse | GD-4KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PF001314 | PowerFuse | GD-4KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/9/2023 10:05 | Distribution | Grand Quarterly Inspection | PF001314 | PowerFuse | GD-4KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0463 | BreakerAirMagnetic | HE-SEC 2 SPARE | AMCB Readings | Unknown Operations | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0463 | BreakerAirMagnetic | HE-SEC 2 SPARE | AMCB Readings | Switching Operations | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0463 | BreakerAirMagnetic | HE-SEC 2 SPARE | AMCB Readings | Operations This Read AM | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0463 | BreakerAirMagnetic | HE-SEC 2 SPARE | AMCB Readings | Operations Counter AL | 392 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0463 | BreakerAirMagnetic | HE-SEC 2 SPARE | AMCB Readings | Operations Counter AF | 392 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0463 | BreakerAirMagnetic | HE-SEC 2 SPARE | AMCB Readings | Maintenance Operations | 0 | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0463 | BreakerAirMagnetic | HE-SEC 2 SPARE | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0463 | BreakerAirMagnetic | HE-SEC 2 SPARE | AMCB Readings | General Comments | | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0463 | BreakerAirMagnetic | HE-SEC 2 SPARE | AMCB Patrol Inspection | General Comments | | |
| 2/8/2023 15:08 | Distribution | Herman Quarterly Inspection | LB0463 | BreakerAirMagnetic | HE-SEC 2 SPARE | AMCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | C0536 | NonLTC | 140-1 AC | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | C0536 | NonLTC | 140-1 AC | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | C0536 | NonLTC | 140-1 AC | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | C0536 | NonLTC | 140-1 AC | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | C0536 | NonLTC | 140-1 AC | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | C0536 | NonLTC | 140-1 AC | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | C0536 | NonLTC | 140-1 AC | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | C0536 | NonLTC | 140-1 AC | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | C0536 | NonLTC | 140-1 AC | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | C0536 | NonLTC | 140-1 AC | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | C0536 | NonLTC | 140-1 AC | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | C0536 | NonLTC | 140-1 AC | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | C0536 | NonLTC | 140-1 AC | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Readings | Amps C Ø | 170.0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Readings | Amps B Ø | 160.0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Readings | Amps A Ø | 170.0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | DB0064 | BreakerVacuum | 337-1 | VCB Readings | 9 Month Operations | 1 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | YD000618 | Yard | GA-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | YD000618 | Yard | GA-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | YD000618 | Yard | GA-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | YD000618 | Yard | GA-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | YD000618 | Yard | GA-Yard | Yard Patrol Inspection | General Comments | | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | YD000618 | Yard | GA-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | YD000618 | Yard | GA-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | YD000618 | Yard | GA-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | YD000618 | Yard | GA-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | YD000618 | Yard | GA-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | YD000618 | Yard | GA-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Readings | Unknown Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Readings | Operations Counter AL | 207 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Readings | Operations Counter AF | 207 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Readings | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | FE000608 | Fence | GA-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001237 | RecloserHydraulic | 140-0333-1 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | LTCMechanism | 312-1 | LTC Counter Readings | LTC As Found Counter | 127075 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | LTCMechanism | 312-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | LTCMechanism | 312-1 | LTC Counter Readings | General Comments | | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | LTCMechanism | 312-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | FE000608 | Fence | GA-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | FE000608 | Fence | GA-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001237 | RecloserHydraulic | 140-0333-1 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0.0 | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001237 | RecloserHydraulic | 140-0333-1 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Readings | Winding Temp Present | 0 | °C |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | LTCMechanism | 337-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001237 | RecloserHydraulic | 140-0333-1 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Readings | Amps C Ø | 105.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Readings | Amps C Ø | 3.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Readings | Amps B Ø | 3.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Readings | Amps B Ø | 105.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Readings | Amps A Ø | 105.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Readings | Amps A Ø | 3.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Readings | Accumulated Fault Duty C Ph V | .6 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Readings | Accumulated Fault Duty B Ph V | 2.39 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Readings | Accumulated Fault Duty A Ph V | .6 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Readings | 9 Month Operations VCB New | 3 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Readings | 9 Month Operations | 3 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Readings | Accumulated Fault Duty B Ph V | 4.77 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Readings | Accumulated Fault Duty C Ph V | 2.98 | % |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Patrol Inspection | General Comments | | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Readings | General Comments | fault A/B/N | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Readings | Maintenance Operations | 0 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Readings | Operations Counter AF | 99942 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Readings | Operations Counter AL | 99942 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Readings | Operations This Read Vac | 1 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | LTCMechanism | 312-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | LTCMechanism | 312-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | LTCMechanism | 312-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | LTCMechanism | 312-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001237 | RecloserHydraulic | 140-0333-1 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001237 | RecloserHydraulic | 140-0333-1 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Readings | Switching Operations | 0 | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001237 | RecloserHydraulic | 140-0333-1 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BCH001367 | Charger | 857-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BCH001367 | Charger | 857-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Readings | 9 Month Operations | 1 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | FE000608 | Fence | GA-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | FE000608 | Fence | GA-Fence | Fence Patrol Inspection | General Comments | | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | FE000608 | Fence | GA-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Readings | Amps A Ø | 46.0 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Readings | Amps B Ø | 41.0 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Readings | Amps C Ø | 45.0 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001237 | RecloserHydraulic | 140-0333-1 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 6 | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001237 | RecloserHydraulic | 140-0333-1 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 17.0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | FE000608 | Fence | GA-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Readings | Fault Adjusted Amps A Phase V | 1.00 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | FE000608 | Fence | GA-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | FE000608 | Fence | GA-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Readings | Fault Operations A Ø | 1 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Readings | Unknown Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Readings | Operations Counter AL | 359 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | FE000608 | Fence | GA-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | FE000608 | Fence | GA-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | FE000608 | Fence | GA-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | LTCMechanism | 312-1 | LTC Counter Readings | LTC Operations Since Last Insp | 780 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | LTCMechanism | 312-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | LTCMechanism | 312-1 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | LTCMechanism | 312-1 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | LTCMechanism | 312-1 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | LTCMechanism | 312-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | LTCMechanism | 312-1 | LTC Counter Readings | LTC As Left Counter | 127079 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | FE000608 | Fence | GA-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Readings | Operations Counter AF | 359 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Readings | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | FE000608 | Fence | GA-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/9/2023 8:53 | Distribution | Gaulbert Quarterly Inspection | FE000608 | Fence | GA-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001237 | RecloserHydraulic | 140-0333-1 | Recloser Hydraulic Patrol Inspection | Operations Counter | 67 | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001237 | RecloserHydraulic | 140-0333-1 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Readings | Unknown Operations | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Readings | Amps B Ø | 115.0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Readings | Amps C Ø | 91.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Readings | Operations Counter AL | 354 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Readings | Operations Counter AF | 354 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Readings | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Readings | Fault Operations C Ø | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | BAT001437 | Battery | FO-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | BAT001437 | Battery | FO-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 71 | °F |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | BAT001437 | Battery | FO-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | BAT001437 | Battery | FO-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | BAT001437 | Battery | FO-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | BAT001437 | Battery | FO-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Readings | Winding Temp Max | 0 | °C |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .7668 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Readings | Fault Operations Ground | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Patrol Inspection | General Comments | | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Readings | General Comments | | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | S0033 | NonLTC | 857-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Readings | Maintenance Operations | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | LTCMechanism | 337-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Readings | Operations Counter AF | 176 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Readings | Operations Counter AL | 176 | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001237 | RecloserHydraulic | 140-0333-1 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Readings | Accumulated Fault Duty A Ph V | 4.17 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Readings | 9 Month Operations | 1 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Readings | Unknown Operations | 0 | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | BAT001437 | Battery | FO-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Water Added | If low,note cell #~'s |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | BAT001437 | Battery | FO-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | BAT001437 | Battery | FO-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | BAT001437 | Battery | FO-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/8/2023 10:25 | Distribution | Forty Fourth Street Quarterly Inspection | BAT001437 | Battery | FO-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | LTCMechanism | 337-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | LTCMechanism | 337-1 | LTC Counter Readings | LTC Operations Since Last Insp | 711 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | LTCMechanism | 337-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | LTCMechanism | 337-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | LTCMechanism | 337-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | LTCMechanism | 337-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Readings | Amps A Ø | 105.0 | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Readings | Unknown Operations | 0 | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BCH001367 | Charger | 857-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Readings | Follow-up Action Required? | n | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Readings | Switching Operations | 0 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Readings | General Comments | B Phase IOC | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Readings | Operations Counter AF | 370 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Readings | Operations Counter AL | 370 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Readings | Switching Operations | 0 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | LTCMechanism | 337-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | KB0064 | BreakerVacuum | 312-4645 | VCB Readings | 9 Month Operations | 4 | |
| 2/9/2023 7:37 | Distribution | Clinch Valley Quarterly Inspection | S0003 | LTCMechanism | 312-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | LTCMechanism | 337-1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001237 | RecloserHydraulic | 140-0333-1 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BCH001367 | Charger | 857-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/8/2023 14:18 | Distribution | Finchville Quarterly Inspection | K0076 | BreakerVacuum | 020-2504 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BCH001367 | Charger | 857-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | LTCMechanism | 337-1 | LTC Counter Readings | General Comments | | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | LTCMechanism | 337-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | LTCMechanism | 337-1 | LTC Counter Readings | LTC As Found Counter | 142423 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | LTCMechanism | 337-1 | LTC Counter Readings | LTC As Left Counter | 142426 | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | LTCMechanism | 337-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/9/2023 7:35 | Distribution | Wise Quarterly Inspection | O0232 | LTCMechanism | 337-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BCH001367 | Charger | 857-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.1 | amps |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BCH001367 | Charger | 857-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/8/2023 16:12 | Distribution | Waco Quarterly Inspection | BCH001367 | Charger | 857-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001237 | RecloserHydraulic | 140-0333-1 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 13:55 | Distribution | Bear Track Quarterly Inspection | RC001237 | RecloserHydraulic | 140-0333-1 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:21 | Distribution | Bonds Mill Quarterly Inspection | PT000085 | PT | 930-Offline-Distribution | PT Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:21 | Distribution | Bonds Mill Quarterly Inspection | PT000085 | PT | 930-Offline-Distribution | PT Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:21 | Distribution | Bonds Mill Quarterly Inspection | PT000085 | PT | 930-Offline-Distribution | PT Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 13:21 | Distribution | Bonds Mill Quarterly Inspection | PT000085 | PT | 930-Offline-Distribution | PT Patrol Inspection | General Comments | | |
| 2/7/2023 13:21 | Distribution | Bonds Mill Quarterly Inspection | PT000085 | PT | 930-Offline-Distribution | PT Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 13:21 | Distribution | Bonds Mill Quarterly Inspection | PT000085 | PT | 930-Offline-Distribution | PT Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:21 | Distribution | Bonds Mill Quarterly Inspection | PT000085 | PT | 930-Offline-Distribution | PT Patrol Inspection | PT Free of Leaks? | y | |
| 2/7/2023 13:21 | Distribution | Bonds Mill Quarterly Inspection | PT000085 | PT | 930-Offline-Distribution | PT Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 13:21 | Distribution | Bonds Mill Quarterly Inspection | PT000084 | PT | 930-Offline-Distribution | PT Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:21 | Distribution | Bonds Mill Quarterly Inspection | PT000084 | PT | 930-Offline-Distribution | PT Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 13:21 | Distribution | Bonds Mill Quarterly Inspection | PT000084 | PT | 930-Offline-Distribution | PT Patrol Inspection | PT Free of Leaks? | y | |
| 2/7/2023 13:21 | Distribution | Bonds Mill Quarterly Inspection | PT000084 | PT | 930-Offline-Distribution | PT Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 13:21 | Distribution | Bonds Mill Quarterly Inspection | PT000084 | PT | 930-Offline-Distribution | PT Patrol Inspection | General Comments | | |
| 2/7/2023 13:21 | Distribution | Bonds Mill Quarterly Inspection | PT000084 | PT | 930-Offline-Distribution | PT Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 13:21 | Distribution | Bonds Mill Quarterly Inspection | PT000084 | PT | 930-Offline-Distribution | PT Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:21 | Distribution | Bonds Mill Quarterly Inspection | PT000084 | PT | 930-Offline-Distribution | PT Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:21 | Distribution | Bonds Mill Quarterly Inspection | PT000083 | PT | 930-Offline-Distribution | PT Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:21 | Distribution | Bonds Mill Quarterly Inspection | PT000083 | PT | 930-Offline-Distribution | PT Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:21 | Distribution | Bonds Mill Quarterly Inspection | PT000083 | PT | 930-Offline-Distribution | PT Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 13:21 | Distribution | Bonds Mill Quarterly Inspection | PT000083 | PT | 930-Offline-Distribution | PT Patrol Inspection | General Comments | | |
| 2/7/2023 13:21 | Distribution | Bonds Mill Quarterly Inspection | PT000083 | PT | 930-Offline-Distribution | PT Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 13:21 | Distribution | Bonds Mill Quarterly Inspection | PT000083 | PT | 930-Offline-Distribution | PT Patrol Inspection | PT Free of Leaks? | y | |
| 2/7/2023 13:21 | Distribution | Bonds Mill Quarterly Inspection | PT000083 | PT | 930-Offline-Distribution | PT Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 13:21 | Distribution | Bonds Mill Quarterly Inspection | PT000083 | PT | 930-Offline-Distribution | PT Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCC000900 | LTCControl | 951-Offline-Distribution | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCC000900 | LTCControl | 951-Offline-Distribution | LTC Control Insp | LTC Output Voltage Level | 124.8 | VAC |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCC000900 | LTCControl | 951-Offline-Distribution | LTC Control Insp | VRR Time Delay | 45 | Seconds |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCC000900 | LTCControl | 951-Offline-Distribution | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCC000900 | LTCControl | 951-Offline-Distribution | LTC Control Insp | All Connections OK? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCC000900 | LTCControl | 951-Offline-Distribution | LTC Control Insp | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCC000900 | LTCControl | 951-Offline-Distribution | LTC Control Insp | LTC Operation Checked? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCC000900 | LTCControl | 951-Offline-Distribution | LTC Control Insp | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Readings | Maintenance Operations | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Readings | Operations Counter AF | 342 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Readings | Operations Counter AL | 342 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | FE000399 | Fence | 670-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | FE000399 | Fence | 670-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1148 | Regulator | 718-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Readings | Switching Operations | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Readings | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Readings | Switching Operations | 1 | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1147 | Regulator | 718-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Readings | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Readings | Num Operations Last 9 Months | 1 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Readings | Operations Counter AF | 106 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Readings | Operations Counter AL | 106 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Readings | Operations This Read SF6 | 1 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1147 | Regulator | 718-1 A | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1147 | Regulator | 718-1 A | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1147 | Regulator | 718-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1147 | Regulator | 718-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1147 | Regulator | 718-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1147 | Regulator | 718-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.4 | volts |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1147 | Regulator | 718-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 88796 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1147 | Regulator | 718-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1147 | Regulator | 718-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1192 | Regulator | 787-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1192 | Regulator | 787-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1192 | Regulator | 787-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1192 | Regulator | 787-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.6 | volts |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1192 | Regulator | 787-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 101151 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1192 | Regulator | 787-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1192 | Regulator | 787-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1192 | Regulator | 787-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1147 | Regulator | 718-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1148 | Regulator | 718-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1148 | Regulator | 718-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1148 | Regulator | 718-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1148 | Regulator | 718-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1148 | Regulator | 718-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1148 | Regulator | 718-1 B | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Readings | Amps C Ø | 80.0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Readings | Amps B Ø | 80.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Readings | 9 Month Operations | 0 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Readings | 9 Month Operations | 13 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Readings | 9 Month Operations | 1 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Readings | Oil Temp Max | 70 | °C |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Readings | Amps A Ø | 180.0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Readings | Amps B Ø | 180.0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Readings | Amps C Ø | 180.0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | FE000874 | Fence | 600-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | FE000874 | Fence | 600-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | FE000874 | Fence | 600-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | FE000874 | Fence | 600-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | FE000874 | Fence | 600-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | FE000874 | Fence | 600-Fence | Fence Patrol Inspection | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Readings | Winding Temp Max | 45 | °C |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Readings | Top Oil Temperature Present | 30 | °C |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Readings | Top Oil Temperature Max | 50 | °C |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1197 | Regulator | 787-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1197 | Regulator | 787-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1197 | Regulator | 787-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1197 | Regulator | 787-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1197 | Regulator | 787-1 C | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1197 | Regulator | 787-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1197 | Regulator | 787-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1197 | Regulator | 787-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1197 | Regulator | 787-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Readings | Amps C Ø | 100.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Readings | Amps B Ø | 130.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Readings | Amps A Ø | 80.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | FE000874 | Fence | 600-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | FE000874 | Fence | 600-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | FE000874 | Fence | 600-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | FE000874 | Fence | 600-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | FE000874 | Fence | 600-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | FE000874 | Fence | 600-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | FE000874 | Fence | 600-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | FE000874 | Fence | 600-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1197 | Regulator | 787-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Readings | Amps C Ø | 50.0 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Readings | Amps B Ø | 60.0 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Readings | Amps A Ø | 60.0 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Readings | Amps A Ø | 0.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1148 | Regulator | 718-1 B | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1148 | Regulator | 718-1 B | Regulator Patrol Inspection | Max Tap Position | 16R | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1148 | Regulator | 718-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1148 | Regulator | 718-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1148 | Regulator | 718-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Readings | Amps A Ø | 80.0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Patrol Inspection | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Readings | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | FE000399 | Fence | 670-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Readings | Maintenance Operations | 1 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | FE000399 | Fence | 670-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | FE000399 | Fence | 670-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1148 | Regulator | 718-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1148 | Regulator | 718-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Readings | Operations Counter AF | 14 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Readings | Operations Counter AL | 14 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Readings | Accumulated Fault Duty B Ph V | 13.13 | % |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Readings | Accumulated Fault Duty C Ph V | 11.29 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1500 | psi |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Readings | H3 Winding Temp Present | 40 | °C |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Readings | H3 Winding Temp Max | 20 | °C |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Readings | H2 Winding Temp Present | 30 | °C |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Readings | Switching Operations | 1 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Patrol Inspection | SF6 Pressure Pole 3 | 68 | psi |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Patrol Inspection | SF6 Pressure Pole 2 | 69 | psi |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Patrol Inspection | SF6 Pressure Pole 1 | 68 | psi |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | FE000874 | Fence | 600-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | FE000874 | Fence | 600-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | FE000399 | Fence | 670-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | FE000399 | Fence | 670-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | FE000399 | Fence | 670-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | FE000399 | Fence | 670-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | FE000399 | Fence | 670-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Readings | Amps A Ø | 46.0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Readings | Amps B Ø | 46.0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Readings | Amps C Ø | 46.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Readings | General Comments | | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | FE000057 | Fence | 517-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | FE000057 | Fence | 517-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Patrol Inspection | General Comments | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Readings | Operations Counter AF | 149 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Readings | Operations Counter AL | 149 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Readings | Operations This Read SF6 | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Patrol Inspection | SF6 Pressure Pole 1 | 67 | psi |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Patrol Inspection | SF6 Pressure Pole 2 | 67 | psi |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Patrol Inspection | SF6 Pressure Pole 3 | 67 | psi |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Readings | General Comments | | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Readings | Switching Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Readings | Unknown Operations | 0 | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1149 | Regulator | 718-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1145 | Regulator | 514-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1145 | Regulator | 514-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1145 | Regulator | 514-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1145 | Regulator | 514-1 B | Regulator Patrol Inspection | Max Tap Position | 1L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1145 | Regulator | 514-1 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1145 | Regulator | 514-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Readings | Unknown Operations | 0 | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | FE000057 | Fence | 517-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | FE000057 | Fence | 517-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | FE000057 | Fence | 517-Fence | Fence Patrol Inspection | General Comments | fabric and fence rusty in muiltple places | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | FE000057 | Fence | 517-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | FE000057 | Fence | 517-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | FE000057 | Fence | 517-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | n | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | FE000057 | Fence | 517-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | FE000057 | Fence | 517-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | FE000057 | Fence | 517-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | FE000057 | Fence | 517-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | FE000057 | Fence | 517-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | FE000057 | Fence | 517-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | FE000057 | Fence | 517-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Readings | Operations Counter AF | 172 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Readings | Operations Counter AL | 172 | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | FE000057 | Fence | 517-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Patrol Inspection | Ambient Temperature | 47 | °F |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Readings | Fault Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001750 | BreakerSF6 | 124-668 | GCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1145 | Regulator | 514-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 260542 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1146 | Regulator | 514-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1146 | Regulator | 514-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1146 | Regulator | 514-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 137552 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1146 | Regulator | 514-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1146 | Regulator | 514-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1146 | Regulator | 514-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1145 | Regulator | 514-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1145 | Regulator | 514-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1145 | Regulator | 514-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1146 | Regulator | 514-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1146 | Regulator | 514-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1146 | Regulator | 514-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1146 | Regulator | 514-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1146 | Regulator | 514-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1146 | Regulator | 514-1 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1146 | Regulator | 514-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1146 | Regulator | 514-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Readings | Operations Counter AL | 169 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1146 | Regulator | 514-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1146 | Regulator | 514-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1146 | Regulator | 514-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1146 | Regulator | 514-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1146 | Regulator | 514-1 C | Regulator Patrol Inspection | Max Tap Position | 1L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1146 | Regulator | 514-1 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1146 | Regulator | 514-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1146 | Regulator | 514-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1149 | Regulator | 718-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1149 | Regulator | 718-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1149 | Regulator | 718-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 136271 | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1149 | Regulator | 718-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.4 | volts |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1149 | Regulator | 718-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1149 | Regulator | 718-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1149 | Regulator | 718-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1149 | Regulator | 718-1 C | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1149 | Regulator | 718-1 C | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1149 | Regulator | 718-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1149 | Regulator | 718-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1149 | Regulator | 718-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1149 | Regulator | 718-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1149 | Regulator | 718-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1149 | Regulator | 718-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1149 | Regulator | 718-1 C | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1149 | Regulator | 718-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1149 | Regulator | 718-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1149 | Regulator | 718-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1149 | Regulator | 718-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1149 | Regulator | 718-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1148 | Regulator | 718-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1148 | Regulator | 718-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1148 | Regulator | 718-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1148 | Regulator | 718-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 91237 | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1148 | Regulator | 718-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.4 | volts |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Readings | Amps C Ø | 136.0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Readings | Amps B Ø | 128.0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Readings | Amps A Ø | 136.0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Readings | 9 Month Operations | 3 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1145 | Regulator | 514-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1145 | Regulator | 514-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1145 | Regulator | 514-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1145 | Regulator | 514-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.5 | volts |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | YD000404 | Yard | 670-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1147 | Regulator | 718-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1147 | Regulator | 718-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1147 | Regulator | 718-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1192 | Regulator | 787-1 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1192 | Regulator | 787-1 B | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1192 | Regulator | 787-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1147 | Regulator | 718-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1147 | Regulator | 718-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Readings | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Readings | 9 Month Operations | 1 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1147 | Regulator | 718-1 A | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1147 | Regulator | 718-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1147 | Regulator | 718-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1192 | Regulator | 787-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1192 | Regulator | 787-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1192 | Regulator | 787-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1192 | Regulator | 787-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | YD000404 | Yard | 670-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | YD000404 | Yard | 670-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | YD000404 | Yard | 670-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1144 | Regulator | 514-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1148 | Regulator | 718-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1148 | Regulator | 718-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1148 | Regulator | 718-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Readings | Switching Operations | 1 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1192 | Regulator | 787-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1192 | Regulator | 787-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1192 | Regulator | 787-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1192 | Regulator | 787-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1192 | Regulator | 787-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1192 | Regulator | 787-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1192 | Regulator | 787-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Readings | Operations Counter AL | 210 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Readings | Operations Counter AF | 209 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Patrol Inspection | General Comments | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Readings | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Readings | Fault Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | FE000399 | Fence | 670-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | FE000399 | Fence | 670-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | FE000399 | Fence | 670-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | FE000399 | Fence | 670-Fence | Fence Patrol Inspection | General Comments | | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | FE000399 | Fence | 670-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | FE000399 | Fence | 670-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | YD000404 | Yard | 670-Yard | Yard Patrol Inspection | Ambient Temp | 51 | °F |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | YD000404 | Yard | 670-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | YD000404 | Yard | 670-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | YD000404 | Yard | 670-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | YD000404 | Yard | 670-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | YD000404 | Yard | 670-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Readings | Operations Counter AF | 169 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1192 | Regulator | 787-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | YD000404 | Yard | 670-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Patrol Inspection | Ambient Temperature | 47 | °F |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001749 | BreakerSF6 | 124-658 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Readings | H2 Winding Temp Max | 40 | °C |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Readings | H1 Winding Temp Present | 20 | °C |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | WithLTC | LS-TRANS 5 | LTC Transformer Readings | H1 Winding Temp Max | 40 | °C |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | YD000404 | Yard | 670-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | YD000404 | Yard | 670-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | YD000404 | Yard | 670-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | YD000404 | Yard | 670-Yard | Yard Patrol Inspection | General Comments | | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | YD000404 | Yard | 670-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1144 | Regulator | 514-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1144 | Regulator | 514-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Readings | 9 Month Operations | 0 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1144 | Regulator | 514-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1144 | Regulator | 514-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.5 | volts |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1144 | Regulator | 514-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 204191 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1144 | Regulator | 514-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1144 | Regulator | 514-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1144 | Regulator | 514-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1145 | Regulator | 514-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1145 | Regulator | 514-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1145 | Regulator | 514-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0178 | BreakerVacuum | 888-1438 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1145 | Regulator | 514-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1145 | Regulator | 514-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1145 | Regulator | 514-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Readings | Operations Counter AF | 2 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Readings | Operations Counter AL | 2 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | WB0177 | BreakerVacuum | 888-1437 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1145 | Regulator | 514-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1145 | Regulator | 514-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1145 | Regulator | 514-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Readings | General Comments | | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1147 | Regulator | 718-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1147 | Regulator | 718-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | R1147 | Regulator | 718-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1146 | Regulator | 514-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BCH001224 | Charger | 585-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BCH001224 | Charger | 585-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BCH001224 | Charger | 585-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BCH001224 | Charger | 585-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | KB0080 | BreakerVacuum | 786-2540 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BCH001224 | Charger | 585-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.3 | amps |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BCH001224 | Charger | 585-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BCH001224 | Charger | 585-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BCH001224 | Charger | 585-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1144 | Regulator | 514-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1144 | Regulator | 514-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000765 | BreakerVacuum | LS-1246 | VCB Readings | General Comments | | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1144 | Regulator | 514-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1144 | Regulator | 514-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1144 | Regulator | 514-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1144 | Regulator | 514-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1144 | Regulator | 514-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1144 | Regulator | 514-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1144 | Regulator | 514-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1144 | Regulator | 514-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1144 | Regulator | 514-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1144 | Regulator | 514-1 A | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1144 | Regulator | 514-1 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | R1144 | Regulator | 514-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | ST000850 | Structure | 124-Structure Distribution | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R1167 | Regulator | 890-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R1167 | Regulator | 890-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R1167 | Regulator | 890-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R1167 | Regulator | 890-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Readings | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 4347.00 | kw |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Readings | Oil Temp Max | 30 | °C |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R1167 | Regulator | 890-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R1167 | Regulator | 890-1 A | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R1167 | Regulator | 890-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R1167 | Regulator | 890-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R1167 | Regulator | 890-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R1167 | Regulator | 890-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R1167 | Regulator | 890-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R1167 | Regulator | 890-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R1167 | Regulator | 890-1 A | Regulator Patrol Inspection | Max Tap Position | 1L | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R1167 | Regulator | 890-1 A | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R1167 | Regulator | 890-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R1167 | Regulator | 890-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R1167 | Regulator | 890-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R1167 | Regulator | 890-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LTCM000014 | LTCMechanism | LS-TRANS 3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LTCM000014 | LTCMechanism | LS-TRANS 3 | LTC Counter Readings | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LTCM000014 | LTCMechanism | LS-TRANS 3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | CD0186 | NonLTC | 514-1 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | CD0186 | NonLTC | 514-1 B | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | CD0186 | NonLTC | 514-1 B | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | CD0186 | NonLTC | 514-1 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | CD0186 | NonLTC | 514-1 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | CD0186 | NonLTC | 514-1 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | CD0186 | NonLTC | 514-1 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | CD0186 | NonLTC | 514-1 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Very Low | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | CD0186 | NonLTC | 514-1 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Readings | Amps C Ø | 620.0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Readings | Amps B Ø | 618.0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Readings | Amps A Ø | 629.0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Readings | 9 Month Operations VCB New | 15 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Readings | 9 Month Operations | 15 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | ST000850 | Structure | 124-Structure Distribution | Structure Patrol Inspection | Wood Structures OK? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | ST000850 | Structure | 124-Structure Distribution | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | ST000850 | Structure | 124-Structure Distribution | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | ST000850 | Structure | 124-Structure Distribution | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | ST000850 | Structure | 124-Structure Distribution | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | ST000850 | Structure | 124-Structure Distribution | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | ST000850 | Structure | 124-Structure Distribution | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | ST000850 | Structure | 124-Structure Distribution | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | ST000850 | Structure | 124-Structure Distribution | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | ST000850 | Structure | 124-Structure Distribution | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | ST000850 | Structure | 124-Structure Distribution | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | ST000850 | Structure | 124-Structure Distribution | Structure Patrol Inspection | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | ST000850 | Structure | 124-Structure Distribution | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | ST000850 | Structure | 124-Structure Distribution | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | ST000850 | Structure | 124-Structure Distribution | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | ST000850 | Structure | 124-Structure Distribution | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | ST000850 | Structure | 124-Structure Distribution | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | ST000850 | Structure | 124-Structure Distribution | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | ST000480 | Structure | 786-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Readings | 9 Month Operations | 1 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Readings | Amps A Ø | 42.0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Readings | Amps B Ø | 67.0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Readings | Amps C Ø | 82.0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R1167 | Regulator | 890-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 371528 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | YD000478 | Yard | 786-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | YD000478 | Yard | 786-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | YD000478 | Yard | 786-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R1167 | Regulator | 890-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R1167 | Regulator | 890-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | YD000478 | Yard | 786-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | YD000478 | Yard | 786-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | YD000478 | Yard | 786-Yard | Yard Patrol Inspection | General Comments | | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | YD000478 | Yard | 786-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | YD000478 | Yard | 786-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | YD000478 | Yard | 786-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | YD000478 | Yard | 786-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | YD000478 | Yard | 786-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | YD000478 | Yard | 786-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | YD000478 | Yard | 786-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | YD000478 | Yard | 786-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | YD000478 | Yard | 786-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | YD000478 | Yard | 786-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Readings | General Comments | | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Readings | Operations Counter AF | 188 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Readings | Operations Counter AL | 189 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Readings | Switching Operations | 1 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LTCM000014 | LTCMechanism | LS-TRANS 3 | LTC Counter Readings | LTC As Found Counter | 47594 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LTCM000014 | LTCMechanism | LS-TRANS 3 | LTC Counter Readings | LTC As Left Counter | 47594 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LTCM000014 | LTCMechanism | LS-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LTCM000014 | LTCMechanism | LS-TRANS 3 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LTCM000014 | LTCMechanism | LS-TRANS 3 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LTCM000014 | LTCMechanism | LS-TRANS 3 | LTC Counter Readings | LTC Min Tap Position | 16L | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LTCM000014 | LTCMechanism | LS-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LTCM000014 | LTCMechanism | LS-TRANS 3 | LTC Counter Readings | LTC Operations Since Last Insp | 667 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LTCM000014 | LTCMechanism | LS-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | FE000077 | Fence | 890-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 10500 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .4140 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Readings | Winding Temp Max | 25 | °C |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | FE000077 | Fence | 890-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | FE000077 | Fence | 890-Fence | Fence Patrol Inspection | General Comments | Barbwire rusty, large gap in bak of lot and right post washed out. | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | FE000077 | Fence | 890-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | FE000077 | Fence | 890-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | FE000077 | Fence | 890-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | n | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | FE000077 | Fence | 890-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | FE000077 | Fence | 890-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | FE000077 | Fence | 890-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | FE000077 | Fence | 890-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | n | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | FE000077 | Fence | 890-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | FE000077 | Fence | 890-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | FE000077 | Fence | 890-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | FE000077 | Fence | 890-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | FE000077 | Fence | 890-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | FE000077 | Fence | 890-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LTCM000014 | LTCMechanism | LS-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LTCM000014 | LTCMechanism | LS-TRANS 3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LTCM000014 | LTCMechanism | LS-TRANS 3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | ST000480 | Structure | 786-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | ST000480 | Structure | 786-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | ST000480 | Structure | 786-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | ST000480 | Structure | 786-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | ST000480 | Structure | 786-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | ST000480 | Structure | 786-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | ST000480 | Structure | 786-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | ST000480 | Structure | 786-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | ST000480 | Structure | 786-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | ST000480 | Structure | 786-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | ST000480 | Structure | 786-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | ST000480 | Structure | 786-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | ST000480 | Structure | 786-Structure | Structure Patrol Inspection | General Comments | no spare fuses | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | ST000480 | Structure | 786-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | ST000480 | Structure | 786-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KT0009 | NonLTC | 072-1 | NonLTC Transformer Readings | Winding Temp Present | 19 | °C |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R1167 | Regulator | 890-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 125.7 | volts |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | ST000480 | Structure | 786-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | ST000480 | Structure | 786-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | ST000480 | Structure | 786-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | ST000480 | Structure | 786-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | ST000480 | Structure | 786-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | ST000480 | Structure | 786-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Readings | Amps C Ø | 98.0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Readings | Amps B Ø | 98.0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Readings | Amps A Ø | 98.0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Readings | 9 Month Operations VCB New | 13 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Readings | 9 Month Operations | 14 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LTCC000404 | LTCControl | BY-TRANS 1 | LTC Control Insp | General Comments | ok | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LTCC000404 | LTCControl | BY-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Readings | Switching Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Readings | Operations Counter AL | 99988 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Readings | Operations Counter AF | 99988 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Readings | 9 Month Operations | 12 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Readings | Amps A Ø | 87.0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Readings | Amps B Ø | 90.0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Readings | Amps C Ø | 96.0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Readings | General Comments | | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Readings | Amps A Ø | 66.0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Readings | Amps B Ø | 75.0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Readings | Amps C Ø | 88.0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Readings | Switching Operations | 1 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Readings | Operations Counter AL | 75 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Readings | Operations Counter AF | 75 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Readings | General Comments | | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Readings | Operations Counter AF | 161 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Readings | Operations Counter AL | 164 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Readings | Operations This Read Vac | 3 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Readings | Switching Operations | 3 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002140 | BreakerVacuum | FL-1495 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0124 | NonLTC | 514-1 A | NonLTC Transformer Readings | Oil Temp Present | 23 | °C |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0124 | NonLTC | 514-1 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0124 | NonLTC | 514-1 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0124 | NonLTC | 514-1 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Adequate | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0124 | NonLTC | 514-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0124 | NonLTC | 514-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Very Low | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0124 | NonLTC | 514-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Adequate | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0124 | NonLTC | 514-1 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0124 | NonLTC | 514-1 A | NonLTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0126 | NonLTC | 514-1 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0126 | NonLTC | 514-1 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0126 | NonLTC | 514-1 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0126 | NonLTC | 514-1 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0126 | NonLTC | 514-1 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0126 | NonLTC | 514-1 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0126 | NonLTC | 514-1 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Unreadable | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0126 | NonLTC | 514-1 C | NonLTC Transformer Readings | General Comments | max hand broken | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0126 | NonLTC | 514-1 C | NonLTC Transformer Patrol Inspection | General Comments | rusted tank, max arm broken | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0126 | NonLTC | 514-1 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0126 | NonLTC | 514-1 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0126 | NonLTC | 514-1 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0126 | NonLTC | 514-1 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0126 | NonLTC | 514-1 C | NonLTC Transformer Readings | Oil Temp Max | 0 | °C |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0126 | NonLTC | 514-1 C | NonLTC Transformer Readings | Oil Temp Present | 22 | °C |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0126 | NonLTC | 514-1 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0126 | NonLTC | 514-1 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0126 | NonLTC | 514-1 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Adequate | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0126 | NonLTC | 514-1 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0126 | NonLTC | 514-1 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Very Low | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0126 | NonLTC | 514-1 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Adequate | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | CD0186 | NonLTC | 514-1 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | CD0186 | NonLTC | 514-1 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | CD0186 | NonLTC | 514-1 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | CD0186 | NonLTC | 514-1 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | CD0186 | NonLTC | 514-1 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | CD0186 | NonLTC | 514-1 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Readings | Operations Counter AL | 44 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Readings | Operations Counter AF | 44 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002138 | BreakerVacuum | FL-14KV TR 1 | VCB Readings | General Comments | | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | CD0186 | NonLTC | 514-1 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | CD0186 | NonLTC | 514-1 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | CD0186 | NonLTC | 514-1 B | NonLTC Transformer Readings | General Comments | | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | CD0186 | NonLTC | 514-1 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | CD0186 | NonLTC | 514-1 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | CD0186 | NonLTC | 514-1 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Readings | Amps C Ø | 0.0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Readings | Amps B Ø | 0.0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Readings | Amps A Ø | 0.0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Readings | General Comments | | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Readings | Operations Counter AF | 164 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Readings | Operations Counter AL | 167 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Readings | Operations This Read Vac | 3 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Readings | Switching Operations | 3 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001789 | BreakerVacuum | 670-0407 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Readings | 9 Month Operations VCB New | 13 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002139 | BreakerVacuum | FL-GND TR 1 | VCB Readings | 9 Month Operations | 13 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0124 | NonLTC | 514-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0124 | NonLTC | 514-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0124 | NonLTC | 514-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0124 | NonLTC | 514-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0124 | NonLTC | 514-1 A | NonLTC Transformer Readings | Follow-up Action Required? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0124 | NonLTC | 514-1 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0124 | NonLTC | 514-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Broken | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0124 | NonLTC | 514-1 A | NonLTC Transformer Readings | General Comments | meter unreadable | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0124 | NonLTC | 514-1 A | NonLTC Transformer Patrol Inspection | General Comments | Rusted tank, max gauge arm broken | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0124 | NonLTC | 514-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0124 | NonLTC | 514-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0124 | NonLTC | 514-1 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 0.00 | kw |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0124 | NonLTC | 514-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0124 | NonLTC | 514-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | WD0124 | NonLTC | 514-1 A | NonLTC Transformer Readings | Oil Temp Max | 0 | °C |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Readings | Amps B Ø | 0.0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Readings | Amps A Ø | 0.0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Readings | 9 Month Operations | 1 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1349 | Regulator | 888-2 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1349 | Regulator | 888-2 C | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1349 | Regulator | 888-2 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1349 | Regulator | 888-2 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1349 | Regulator | 888-2 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1349 | Regulator | 888-2 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1349 | Regulator | 888-2 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1348 | Regulator | 888-2 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1348 | Regulator | 888-2 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1348 | Regulator | 888-2 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1348 | Regulator | 888-2 B | Regulator Patrol Inspection | Regulator As Left Counter | 82127 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1348 | Regulator | 888-2 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.0 | volts |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1348 | Regulator | 888-2 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1348 | Regulator | 888-2 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1348 | Regulator | 888-2 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1348 | Regulator | 888-2 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1348 | Regulator | 888-2 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1348 | Regulator | 888-2 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1348 | Regulator | 888-2 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1348 | Regulator | 888-2 B | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Readings | 9 Month Operations | 3 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Readings | Amps A Ø | 38.0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Readings | Amps B Ø | 37.0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Readings | Amps C Ø | 37.0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Readings | Maintenance Operations | 1 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1349 | Regulator | 888-2 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1349 | Regulator | 888-2 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1349 | Regulator | 888-2 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1349 | Regulator | 888-2 C | Regulator Patrol Inspection | Regulator As Left Counter | 78577 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1349 | Regulator | 888-2 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1349 | Regulator | 888-2 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1349 | Regulator | 888-2 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1349 | Regulator | 888-2 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1349 | Regulator | 888-2 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1349 | Regulator | 888-2 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1349 | Regulator | 888-2 C | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1349 | Regulator | 888-2 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Readings | General Comments | Breaker is offline | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1349 | Regulator | 888-2 C | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1349 | Regulator | 888-2 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1349 | Regulator | 888-2 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1349 | Regulator | 888-2 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 75 | °C |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | needs nitro in bottle | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Readings | Amps C Ø | 0.0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Readings | General Comments | | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Readings | Operations Counter AF | 160 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Readings | Operations Counter AL | 161 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Readings | Switching Operations | 1 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Readings | Operations Counter AL | 2 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Readings | Operations Counter AF | 2 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Readings | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | ST000327 | Structure | 510-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | ST000327 | Structure | 510-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | ST000327 | Structure | 510-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | ST000327 | Structure | 510-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | ST000327 | Structure | 510-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | ST000327 | Structure | 510-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | ST000327 | Structure | 510-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Readings | General Comments | | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Readings | Operations Counter AF | 170 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Readings | Operations Counter AL | 171 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Readings | Switching Operations | 1 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001818 | BreakerVacuum | 786-2539 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1348 | Regulator | 888-2 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1348 | Regulator | 888-2 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1348 | Regulator | 888-2 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1348 | Regulator | 888-2 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1348 | Regulator | 888-2 B | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1348 | Regulator | 888-2 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1348 | Regulator | 888-2 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1348 | Regulator | 888-2 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1348 | Regulator | 888-2 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1348 | Regulator | 888-2 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000515 | RecloserElectronic | 891-0718 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000515 | RecloserElectronic | 891-0718 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000515 | RecloserElectronic | 891-0718 | Recloser Electronic Patrol Inspection | Operations Counter | 84 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000515 | RecloserElectronic | 891-0718 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000515 | RecloserElectronic | 891-0718 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000515 | RecloserElectronic | 891-0718 | Recloser Electronic Patrol Inspection | General Comments | | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Readings | 9 Month Operations | 1 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Readings | Amps A Ø | 80.0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Readings | Amps B Ø | 75.0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Readings | Amps C Ø | 70.0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK001820 | BreakerVacuum | 786-2528 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Readings | General Comments | | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1643.04 | kw |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 97.50 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Readings | Oil Temp Max | 25 | °C |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .6846 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R0748 | Regulator | 012-5 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R0748 | Regulator | 012-5 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R0748 | Regulator | 012-5 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R0748 | Regulator | 012-5 A | Regulator Patrol Inspection | Regulator As Left Counter | 38737 | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R0748 | Regulator | 012-5 A | Regulator Patrol Inspection | Reg Output Voltage Level | 125.3 | volts |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R0748 | Regulator | 012-5 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R0748 | Regulator | 012-5 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R0748 | Regulator | 012-5 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R0748 | Regulator | 012-5 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R0748 | Regulator | 012-5 A | Regulator Patrol Inspection | Min Tap Position | 6L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R0748 | Regulator | 012-5 A | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R0748 | Regulator | 012-5 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R0748 | Regulator | 012-5 A | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R0748 | Regulator | 012-5 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R0748 | Regulator | 012-5 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R0748 | Regulator | 012-5 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R0748 | Regulator | 012-5 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R0748 | Regulator | 012-5 A | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R0748 | Regulator | 012-5 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | LTCMechanism | BY-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | LTCMechanism | BY-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | LTCMechanism | BY-TRANS 2 | LTC Counter Readings | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | LTCMechanism | BY-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | LTCMechanism | BY-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 46899 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | LTCMechanism | BY-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 46899 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | FE000472 | Fence | 786-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | FE000472 | Fence | 786-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | FE000472 | Fence | 786-Fence | Fence Patrol Inspection | General Comments | | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | FE000472 | Fence | 786-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | FE000472 | Fence | 786-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | FE000472 | Fence | 786-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | FE000472 | Fence | 786-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | FE000472 | Fence | 786-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | FE000472 | Fence | 786-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | FE000472 | Fence | 786-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R1167 | Regulator | 890-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R1167 | Regulator | 890-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | FE000472 | Fence | 786-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | FE000472 | Fence | 786-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | FE000472 | Fence | 786-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | FE000472 | Fence | 786-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | FE000472 | Fence | 786-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | FE000472 | Fence | 786-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BK000156 | BreakerVacuum | 786-2541 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1249 | Regulator | 725-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1249 | Regulator | 725-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1249 | Regulator | 725-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1249 | Regulator | 725-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1249 | Regulator | 725-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 575120 | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1249 | Regulator | 725-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1249 | Regulator | 725-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1249 | Regulator | 725-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1249 | Regulator | 725-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1249 | Regulator | 725-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1249 | Regulator | 725-1 A | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1249 | Regulator | 725-1 A | Regulator Patrol Inspection | Max Tap Position | 1L | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1249 | Regulator | 725-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1249 | Regulator | 725-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1249 | Regulator | 725-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1249 | Regulator | 725-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1249 | Regulator | 725-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1249 | Regulator | 725-1 A | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1249 | Regulator | 725-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1249 | Regulator | 725-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1249 | Regulator | 725-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1249 | Regulator | 725-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1249 | Regulator | 725-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | C0337 | NonLTC | 613-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 95.00 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Readings | General Comments | | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | ST000062 | Structure | 517-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | ST000062 | Structure | 517-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | ST000062 | Structure | 517-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | ST000062 | Structure | 517-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | ST000062 | Structure | 517-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | ST000062 | Structure | 517-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | ST000062 | Structure | 517-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | ST000062 | Structure | 517-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | ST000062 | Structure | 517-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | ST000062 | Structure | 517-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | ST000062 | Structure | 517-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | ST000062 | Structure | 517-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | ST000062 | Structure | 517-Structure | Structure Patrol Inspection | General Comments | | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | ST000062 | Structure | 517-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | ST000062 | Structure | 517-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | ST000062 | Structure | 517-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | ST000062 | Structure | 517-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | ST000062 | Structure | 517-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | ST000062 | Structure | 517-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | ST000062 | Structure | 517-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | ST000062 | Structure | 517-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | ST000062 | Structure | 517-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 60 | °C |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 75 | °C |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 60 | °C |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 70 | °C |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 60 | °C |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 80 | °C |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 10.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | WithLTC | ET-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Readings | Operations Counter AL | 74 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | CB0272 | BreakerVacuum | 888-1440 | VCB Readings | Operations Counter AF | 74 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | LTCMechanism | BY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R0748 | Regulator | 012-5 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R0748 | Regulator | 012-5 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R0748 | Regulator | 012-5 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R0748 | Regulator | 012-5 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | LTCMechanism | BY-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | LTCMechanism | BY-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | LTCMechanism | BY-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | LTCMechanism | BY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | LTCMechanism | BY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 33 | °C |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | LTCMechanism | BY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 18 | °C |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | LTCMechanism | BY-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 376 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | LTCMechanism | BY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | LTCMechanism | BY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | LTCMechanism | BY-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | LTCMechanism | BY-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Readings | X3 Winding Temp Present | 45 | °C |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Readings | X3 Winding Temp Max | 65 | °C |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Readings | X2 Winding Temp Present | 50 | °C |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Readings | X2 Winding Temp Max | 65 | °C |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Readings | X1 Winding Temp Present | 60 | °C |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Readings | X1 Winding Temp Max | 80 | °C |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Readings | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LTCC000521 | LTCControl | BY-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LTCC000521 | LTCControl | BY-TRANS 2 | LTC Control Insp | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LTCC000521 | LTCControl | BY-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | WithLTC | ET-TRANS 6 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | CH000171 | ControlHouse | FL-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | CH000171 | ControlHouse | FL-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | CH000171 | ControlHouse | FL-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | CH000171 | ControlHouse | FL-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | CH000171 | ControlHouse | FL-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | CH000171 | ControlHouse | FL-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | CH000171 | ControlHouse | FL-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | CH000171 | ControlHouse | FL-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1257 | BreakerVacuum | BY-1279 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Readings | 9 Month Operations | 9 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Readings | Amps A Ø | 240.0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Readings | 9 Month Operations | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Readings | Accumulated Fault Duty C Ph V | .36 | % |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Readings | Amps A Ø | 21.0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Readings | Amps B Ø | 15.0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Readings | Amps C Ø | 3.0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Patrol Inspection | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Readings | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Readings | Maintenance Operations | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Readings | Operations Counter AF | 168 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Readings | Operations Counter AL | 168 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Readings | Operations This Read Vac | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Readings | Switching Operations | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001778 | BreakerVacuum | 072-4600 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Readings | Amps B Ø | 232.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Readings | Amps C Ø | 228.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | FE000189 | Fence | 888-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | FE000189 | Fence | 888-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | FE000189 | Fence | 888-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | FE000189 | Fence | 888-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | FE000189 | Fence | 888-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | FE000189 | Fence | 888-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | FE000189 | Fence | 888-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | FE000189 | Fence | 888-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | FE000189 | Fence | 888-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | FE000189 | Fence | 888-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | FE000189 | Fence | 888-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | CH000370 | ControlHouse | 600-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | CH000370 | ControlHouse | 600-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | CH000370 | ControlHouse | 600-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | CH000370 | ControlHouse | 600-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | CH000370 | ControlHouse | 600-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | CH000370 | ControlHouse | 600-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | CH000370 | ControlHouse | 600-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | CH000370 | ControlHouse | 600-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | CH000370 | ControlHouse | 600-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | CH000370 | ControlHouse | 600-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | CH000370 | ControlHouse | 600-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1257 | BreakerVacuum | BY-1279 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1257 | BreakerVacuum | BY-1279 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1257 | BreakerVacuum | BY-1279 | VCB Readings | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1257 | BreakerVacuum | BY-1279 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1257 | BreakerVacuum | BY-1279 | VCB Readings | Operations Counter AF | 270 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1257 | BreakerVacuum | BY-1279 | VCB Readings | Operations Counter AL | 270 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1257 | BreakerVacuum | BY-1279 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1257 | BreakerVacuum | BY-1279 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | CH000370 | ControlHouse | 600-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | CH000370 | ControlHouse | 600-Control House | Control House Patrol Inspection | General Comments | | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | CH000370 | ControlHouse | 600-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | CH000370 | ControlHouse | 600-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | CH000370 | ControlHouse | 600-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | CH000370 | ControlHouse | 600-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | CH000370 | ControlHouse | 600-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | CH000370 | ControlHouse | 600-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | CH000171 | ControlHouse | FL-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | CH000171 | ControlHouse | FL-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | CH000171 | ControlHouse | FL-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | CH000171 | ControlHouse | FL-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | CH000171 | ControlHouse | FL-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | CH000171 | ControlHouse | FL-Control House | Control House Patrol Inspection | Restroom Clean & OK? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | CH000171 | ControlHouse | FL-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | CH000171 | ControlHouse | FL-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | CH000171 | ControlHouse | FL-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | CH000171 | ControlHouse | FL-Control House | Control House Patrol Inspection | General Comments | | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | CH000171 | ControlHouse | FL-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | CH000171 | ControlHouse | FL-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | CH000171 | ControlHouse | FL-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | CH000171 | ControlHouse | FL-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | CH000171 | ControlHouse | FL-Control House | Control House Patrol Inspection | Filters Condition OK? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | CH000171 | ControlHouse | FL-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000768 | BreakerVacuum | ET-1173 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000768 | BreakerVacuum | ET-1173 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000768 | BreakerVacuum | ET-1173 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Readings | Unknown Operations | 1 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Readings | Operations Counter AL | 14 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Readings | Operations Counter AF | 14 | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | ST000387 | Structure | 029-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | ST000387 | Structure | 029-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | ST000387 | Structure | 029-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | ST000387 | Structure | 029-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | ST000387 | Structure | 029-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | ST000387 | Structure | 029-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | ST000387 | Structure | 029-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | ST000387 | Structure | 029-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | ST000387 | Structure | 029-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | ST000387 | Structure | 029-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | ST000387 | Structure | 029-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | ST000387 | Structure | 029-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | ST000387 | Structure | 029-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | ST000387 | Structure | 029-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | ST000387 | Structure | 029-Structure | Structure Patrol Inspection | General Comments | | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | ST000387 | Structure | 029-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | ST000387 | Structure | 029-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | ST000387 | Structure | 029-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | ST000387 | Structure | 029-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | ST000387 | Structure | 029-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | ST000387 | Structure | 029-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | ST000387 | Structure | 029-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | ST000387 | Structure | 029-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | ST000387 | Structure | 029-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | YD000384 | Yard | 029-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | YD000384 | Yard | 029-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | YD000384 | Yard | 029-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | YD000384 | Yard | 029-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | YD000384 | Yard | 029-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | YD000384 | Yard | 029-Yard | Yard Patrol Inspection | General Comments | | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | YD000384 | Yard | 029-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | YD000384 | Yard | 029-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | YD000384 | Yard | 029-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | YD000384 | Yard | 029-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | YD000384 | Yard | 029-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | YD000384 | Yard | 029-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Readings | 9 Month Operations | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Readings | Amps A Ø | 89.0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Readings | Amps B Ø | 104.0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Readings | Amps C Ø | 105.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | FE000887 | Fence | 891-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | FE000887 | Fence | 891-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | FE000887 | Fence | 891-Fence | Fence Patrol Inspection | General Comments | | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | FE000887 | Fence | 891-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | FE000887 | Fence | 891-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | FE000887 | Fence | 891-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | FE000887 | Fence | 891-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | FE000887 | Fence | 891-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | FE000887 | Fence | 891-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | FE000887 | Fence | 891-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | FE000887 | Fence | 891-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | FE000887 | Fence | 891-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | FE000887 | Fence | 891-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | FE000887 | Fence | 891-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | FE000887 | Fence | 891-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | FE000887 | Fence | 891-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Readings | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Readings | Operations Counter AF | 187 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Readings | Operations Counter AL | 187 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Readings | Operations This Read Vac | 4 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Readings | Switching Operations | 4 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000767 | BreakerVacuum | LS-1248 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000768 | BreakerVacuum | ET-1173 | VCB Readings | 9 Month Operations | 2 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000768 | BreakerVacuum | ET-1173 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000768 | BreakerVacuum | ET-1173 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000768 | BreakerVacuum | ET-1173 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000768 | BreakerVacuum | ET-1173 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000768 | BreakerVacuum | ET-1173 | VCB Readings | Amps A Ø | 176.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000768 | BreakerVacuum | ET-1173 | VCB Readings | Amps B Ø | 147.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000768 | BreakerVacuum | ET-1173 | VCB Readings | Amps C Ø | 124.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000768 | BreakerVacuum | ET-1173 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000768 | BreakerVacuum | ET-1173 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Readings | Amps C Ø | 20.0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Readings | Amps B Ø | 20.0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Readings | Amps A Ø | 20.0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | FE000231 | Fence | 718-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | FE000231 | Fence | 718-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | FE000231 | Fence | 718-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | FE000231 | Fence | 718-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | FE000231 | Fence | 718-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | FE000231 | Fence | 718-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | FE000231 | Fence | 718-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Readings | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | FE000231 | Fence | 718-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | FE000231 | Fence | 718-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | FE000231 | Fence | 718-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | FE000231 | Fence | 718-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | FE000231 | Fence | 718-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | FE000231 | Fence | 718-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | FE000231 | Fence | 718-Fence | Fence Patrol Inspection | General Comments | | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | FE000231 | Fence | 718-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | FE000231 | Fence | 718-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | YD000420 | Yard | 785-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | YD000420 | Yard | 785-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Readings | Amps B Ø | 0.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Readings | Amps C Ø | 0.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Readings | General Comments | | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Readings | Operations Counter AF | 127 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Readings | Operations Counter AL | 131 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Readings | Operations This Read Vac | 4 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Readings | Switching Operations | 4 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0263 | BreakerVacuum | 600-0475 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Readings | Operations Counter AL | 441 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Readings | Operations Counter AF | 441 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Readings | General Comments | | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0359 | BreakerVacuum | 441-0728 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 52.50 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 402.72 | kw |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Patrol Inspection | General Comments | Needs wildlife protection on secondary side. | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1257 | BreakerVacuum | BY-1279 | VCB Readings | 9 Month Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1257 | BreakerVacuum | BY-1279 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1257 | BreakerVacuum | BY-1279 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1257 | BreakerVacuum | BY-1279 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1257 | BreakerVacuum | BY-1279 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | YD000187 | Yard | 888-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | YD000187 | Yard | 888-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | YD000187 | Yard | 888-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | YD000187 | Yard | 888-Yard | Yard Patrol Inspection | General Comments | | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | YD000187 | Yard | 888-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | YD000187 | Yard | 888-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | YD000187 | Yard | 888-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | YD000187 | Yard | 888-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | YD000187 | Yard | 888-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | YD000187 | Yard | 888-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | YD000187 | Yard | 888-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1257 | BreakerVacuum | BY-1279 | VCB Readings | Amps A Ø | 170.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1257 | BreakerVacuum | BY-1279 | VCB Readings | Amps B Ø | 113.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1257 | BreakerVacuum | BY-1279 | VCB Readings | Amps C Ø | 125.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1257 | BreakerVacuum | BY-1279 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Readings | General Comments | | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1257 | BreakerVacuum | BY-1279 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1257 | BreakerVacuum | BY-1279 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1257 | BreakerVacuum | BY-1279 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1257 | BreakerVacuum | BY-1279 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1257 | BreakerVacuum | BY-1279 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1257 | BreakerVacuum | BY-1279 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1257 | BreakerVacuum | BY-1279 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1257 | BreakerVacuum | BY-1279 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | YD000187 | Yard | 888-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | YD000187 | Yard | 888-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | FE000189 | Fence | 888-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | FE000189 | Fence | 888-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | FE000189 | Fence | 888-Fence | Fence Patrol Inspection | General Comments | The plant has a small section of fence connected to ours. Pictures were taken and will be uploaded to distsubs. | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | FE000189 | Fence | 888-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | FE000189 | Fence | 888-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | YD000420 | Yard | 785-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | YD000420 | Yard | 785-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | YD000420 | Yard | 785-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | YD000420 | Yard | 785-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | YD000420 | Yard | 785-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | YD000420 | Yard | 785-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | YD000420 | Yard | 785-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | YD000420 | Yard | 785-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | YD000420 | Yard | 785-Yard | Yard Patrol Inspection | General Comments | | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | YD000420 | Yard | 785-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | YD000420 | Yard | 785-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | YD000420 | Yard | 785-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | ST000422 | Structure | 785-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | ST000422 | Structure | 785-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | ST000422 | Structure | 785-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | ST000422 | Structure | 785-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | ST000422 | Structure | 785-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | ST000422 | Structure | 785-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | ST000422 | Structure | 785-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | ST000422 | Structure | 785-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | ST000422 | Structure | 785-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | ST000422 | Structure | 785-Structure | Structure Patrol Inspection | General Comments | | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | ST000422 | Structure | 785-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | ST000422 | Structure | 785-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | ST000422 | Structure | 785-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | ST000422 | Structure | 785-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | ST000422 | Structure | 785-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | ST000422 | Structure | 785-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | ST000422 | Structure | 785-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | ST000422 | Structure | 785-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | ST000422 | Structure | 785-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | ST000422 | Structure | 785-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | ST000422 | Structure | 785-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | ST000422 | Structure | 785-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | ST000422 | Structure | 785-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Readings | Operations Counter AF | 145 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Readings | Operations Counter AL | 145 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000766 | BreakerVacuum | LS-1247 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.0068 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 400 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | W0270 | NonLTC | 502-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Readings | Fault Adjusted Amps C Phase V | 8.00 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Readings | Fault Adjusted Amps B Phase V | 8.00 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Readings | Fault Adjusted Amps A Phase V | 8.00 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Readings | Amps C Ø | 320.0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Readings | Amps B Ø | 316.0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Readings | Amps A Ø | 325.0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Readings | 9 Month Operations VCB New | 12 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Readings | 9 Month Operations | 13 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LTCC000410 | LTCControl | C-TRANS 3 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LTCC000410 | LTCControl | C-TRANS 3 | LTC Control Insp | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LTCC000410 | LTCControl | C-TRANS 3 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Readings | Operations Counter AL | 16 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Readings | Operations Counter AF | 16 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Readings | General Comments | | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | YD000230 | Yard | 718-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | YD000230 | Yard | 718-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | YD000230 | Yard | 718-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | YD000230 | Yard | 718-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | YD000230 | Yard | 718-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | ST000415 | Structure | 600-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Readings | Amps C Ø | 34.0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Readings | Amps B Ø | 34.0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Readings | Amps A Ø | 33.0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Readings | 9 Month Operations | 8 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | ST000415 | Structure | 600-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | ST000415 | Structure | 600-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | ST000415 | Structure | 600-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | ST000415 | Structure | 600-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | ST000415 | Structure | 600-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | ST000415 | Structure | 600-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | ST000415 | Structure | 600-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | ST000415 | Structure | 600-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | ST000415 | Structure | 600-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | ST000415 | Structure | 600-Structure | Structure Patrol Inspection | General Comments | | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Readings | Unknown Operations | 1 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Readings | Operations Counter AL | 32 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Readings | Operations Counter AF | 32 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | ST000415 | Structure | 600-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | ST000415 | Structure | 600-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | ST000415 | Structure | 600-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | ST000415 | Structure | 600-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | ST000415 | Structure | 600-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | ST000415 | Structure | 600-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | ST000415 | Structure | 600-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | ST000415 | Structure | 600-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002142 | BreakerVacuum | FL-1497 | VCB Readings | General Comments | | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Readings | General Comments | | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Readings | Operations Counter AF | 178 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Readings | Operations Counter AL | 182 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Readings | Operations This Read Vac | 4 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Readings | Switching Operations | 4 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | FE000832 | Fence | 585-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | FE000832 | Fence | 585-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | FE000832 | Fence | 585-Fence | Fence Patrol Inspection | General Comments | | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | FE000832 | Fence | 585-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | FE000832 | Fence | 585-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | FE000832 | Fence | 585-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | FE000832 | Fence | 585-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | FE000832 | Fence | 585-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | FE000832 | Fence | 585-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | FE000832 | Fence | 585-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | FE000832 | Fence | 585-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | FE000832 | Fence | 585-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | FE000832 | Fence | 585-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | FE000832 | Fence | 585-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | FE000832 | Fence | 585-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | FE000832 | Fence | 585-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Readings | 9 Month Operations | 3 | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | BX0714 | RecloserHydraulic | 785-0730 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | BX0714 | RecloserHydraulic | 785-0730 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | BX0714 | RecloserHydraulic | 785-0730 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | BX0714 | RecloserHydraulic | 785-0730 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | BX0714 | RecloserHydraulic | 785-0730 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | BX0714 | RecloserHydraulic | 785-0730 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | BX0714 | RecloserHydraulic | 785-0730 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | BX0714 | RecloserHydraulic | 785-0730 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 126 | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | BX0714 | RecloserHydraulic | 785-0730 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | BX0714 | RecloserHydraulic | 785-0730 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | BX0714 | RecloserHydraulic | 785-0730 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 123 | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | BX0714 | RecloserHydraulic | 785-0730 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 38.0 | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | BX0714 | RecloserHydraulic | 785-0730 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 35.0 | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | BX0714 | RecloserHydraulic | 785-0730 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 35.0 | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | BX0714 | RecloserHydraulic | 785-0730 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 105 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001788 | BreakerVacuum | 670-0406 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Readings | Amps C Ø | 67.0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Readings | Amps B Ø | 73.0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Readings | Amps A Ø | 74.0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002141 | BreakerVacuum | FL-1496 | VCB Readings | 9 Month Operations | 4 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1256 | BreakerVacuum | BY-1278 | VCB Readings | 9 Month Operations | 3 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1256 | BreakerVacuum | BY-1278 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1256 | BreakerVacuum | BY-1278 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1256 | BreakerVacuum | BY-1278 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1256 | BreakerVacuum | BY-1278 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1256 | BreakerVacuum | BY-1278 | VCB Readings | Amps A Ø | 118.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1256 | BreakerVacuum | BY-1278 | VCB Readings | Amps B Ø | 148.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1256 | BreakerVacuum | BY-1278 | VCB Readings | Amps C Ø | 122.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1256 | BreakerVacuum | BY-1278 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1256 | BreakerVacuum | BY-1278 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1256 | BreakerVacuum | BY-1278 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1256 | BreakerVacuum | BY-1278 | VCB Readings | Fault Adjusted Amps C Phase V | 22.36 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1256 | BreakerVacuum | BY-1278 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1256 | BreakerVacuum | BY-1278 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1256 | BreakerVacuum | BY-1278 | VCB Readings | Fault Operations C Ø | 2 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1256 | BreakerVacuum | BY-1278 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1256 | BreakerVacuum | BY-1278 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1256 | BreakerVacuum | BY-1278 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1256 | BreakerVacuum | BY-1278 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1256 | BreakerVacuum | BY-1278 | VCB Readings | General Comments | c ioc | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1256 | BreakerVacuum | BY-1278 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1256 | BreakerVacuum | BY-1278 | VCB Readings | Operations Counter AF | 305 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1256 | BreakerVacuum | BY-1278 | VCB Readings | Operations Counter AL | 305 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1256 | BreakerVacuum | BY-1278 | VCB Readings | Operations This Read Vac | 2 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1256 | BreakerVacuum | BY-1278 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1256 | BreakerVacuum | BY-1278 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Readings | 9 Month Operations | 4 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Readings | Amps A Ø | 42.0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Readings | Amps B Ø | 53.0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Readings | Amps C Ø | 56.0 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BK001787 | BreakerVacuum | 670-0405 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Readings | Amps A Ø | 95.0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Readings | Amps B Ø | 120.0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Readings | Amps C Ø | 92.0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Readings | General Comments | | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Patrol Inspection | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Patrol Inspection | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Readings | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Readings | Maintenance Operations | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Readings | Operations Counter AF | 169 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Readings | Operations Counter AL | 169 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Readings | Fault Adjusted Amps C Phase V | 8.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Readings | Operations This Read Vac | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Readings | Switching Operations | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | ST000240 | Structure | 502-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | ST000240 | Structure | 502-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | ST000240 | Structure | 502-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | ST000240 | Structure | 502-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | ST000240 | Structure | 502-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | ST000240 | Structure | 502-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | ST000240 | Structure | 502-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | ST000240 | Structure | 502-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | ST000240 | Structure | 502-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | ST000240 | Structure | 502-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Patrol Inspection | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Readings | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Readings | Maintenance Operations | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Readings | Operations Counter AF | 170 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Readings | Operations Counter AL | 170 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Readings | Operations This Read Vac | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Readings | Switching Operations | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001779 | BreakerVacuum | 072-4601 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | YD000384 | Yard | 029-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | YD000384 | Yard | 029-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | YD000384 | Yard | 029-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | YD000384 | Yard | 029-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | FE000378 | Fence | 029-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | FE000378 | Fence | 029-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | FE000378 | Fence | 029-Fence | Fence Patrol Inspection | General Comments | | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | FE000378 | Fence | 029-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | FE000378 | Fence | 029-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | FE000378 | Fence | 029-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | FE000378 | Fence | 029-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | FE000378 | Fence | 029-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | FE000378 | Fence | 029-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | FE000378 | Fence | 029-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | FE000378 | Fence | 029-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | FE000378 | Fence | 029-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | FE000378 | Fence | 029-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | FE000378 | Fence | 029-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | FE000378 | Fence | 029-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | FE000378 | Fence | 029-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Readings | 9 Month Operations | 1 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Readings | Accumulated Fault Duty B Ph V | .36 | % |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK001780 | BreakerVacuum | 072-4603 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000768 | BreakerVacuum | ET-1173 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000768 | BreakerVacuum | ET-1173 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000768 | BreakerVacuum | ET-1173 | VCB Readings | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000768 | BreakerVacuum | ET-1173 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000768 | BreakerVacuum | ET-1173 | VCB Readings | Operations Counter AF | 208 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000768 | BreakerVacuum | ET-1173 | VCB Readings | Operations Counter AL | 208 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000768 | BreakerVacuum | ET-1173 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000768 | BreakerVacuum | ET-1173 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Readings | Operations Counter AL | 5 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Readings | Operations Counter AF | 5 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Readings | General Comments | VC is 5 not 6 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002143 | BreakerVacuum | FL-1498 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | ST000237 | Structure | 718-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | ST000237 | Structure | 718-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | ST000237 | Structure | 718-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | ST000237 | Structure | 718-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | ST000237 | Structure | 718-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | ST000237 | Structure | 718-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | ST000237 | Structure | 718-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | ST000237 | Structure | 718-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | ST000237 | Structure | 718-Structure | Structure Patrol Inspection | General Comments | | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | ST000237 | Structure | 718-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | ST000237 | Structure | 718-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | ST000237 | Structure | 718-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | ST000237 | Structure | 718-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | ST000237 | Structure | 718-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | ST000237 | Structure | 718-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | ST000237 | Structure | 718-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | ST000237 | Structure | 718-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | YD000230 | Yard | 718-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | YD000230 | Yard | 718-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | YD000230 | Yard | 718-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | YD000230 | Yard | 718-Yard | Yard Patrol Inspection | General Comments | | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | YD000230 | Yard | 718-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | YD000230 | Yard | 718-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | YD000230 | Yard | 718-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | YD000230 | Yard | 718-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | YD000230 | Yard | 718-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | ST000240 | Structure | 502-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | ST000240 | Structure | 502-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | ST000240 | Structure | 502-Structure | Structure Patrol Inspection | General Comments | | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | ST000240 | Structure | 502-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | ST000240 | Structure | 502-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | ST000240 | Structure | 502-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | ST000240 | Structure | 502-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | ST000240 | Structure | 502-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | ST000240 | Structure | 502-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | ST000240 | Structure | 502-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | ST000240 | Structure | 502-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | ST000240 | Structure | 502-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | FE000234 | Fence | 502-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | FE000234 | Fence | 502-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | FE000234 | Fence | 502-Fence | Fence Patrol Inspection | General Comments | | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | FE000234 | Fence | 502-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | FE000234 | Fence | 502-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | FE000234 | Fence | 502-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | FE000234 | Fence | 502-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | FE000234 | Fence | 502-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | FE000234 | Fence | 502-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | FE000234 | Fence | 502-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | FE000234 | Fence | 502-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | FE000234 | Fence | 502-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | FE000234 | Fence | 502-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | FE000234 | Fence | 502-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | FE000234 | Fence | 502-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | FE000234 | Fence | 502-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Readings | Fault Adjusted Amps B Phase V | 8.00 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Readings | Fault Adjusted Amps A Phase V | 8.00 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Readings | Amps C Ø | 99.0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Readings | Amps B Ø | 101.0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Readings | Amps A Ø | 97.0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | ST000237 | Structure | 718-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | ST000237 | Structure | 718-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | ST000237 | Structure | 718-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | ST000237 | Structure | 718-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | ST000237 | Structure | 718-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | ST000237 | Structure | 718-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Readings | 9 Month Operations VCB New | 14 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BK002144 | BreakerVacuum | FL-1499 | VCB Readings | 9 Month Operations | 15 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000768 | BreakerVacuum | ET-1173 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000768 | BreakerVacuum | ET-1173 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000768 | BreakerVacuum | ET-1173 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000768 | BreakerVacuum | ET-1173 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF000121 | PowerFuse | ET-STA SER NO 6 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF000122 | PowerFuse | ET-12KV TR 6 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF000122 | PowerFuse | ET-12KV TR 6 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF000122 | PowerFuse | ET-12KV TR 6 POT | Disconnect Powerfuse Inspection | General Comments | ok | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | PF000200 | PowerFuse | LS-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | FE000423 | Fence | 724-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | FE000423 | Fence | 724-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | FE000423 | Fence | 724-Fence | Fence Patrol Inspection | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | FE000423 | Fence | 724-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | FE000423 | Fence | 724-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | FE000423 | Fence | 724-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | FE000423 | Fence | 724-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | FE000423 | Fence | 724-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | FE000423 | Fence | 724-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | FE000423 | Fence | 724-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | FE000423 | Fence | 724-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | FE000423 | Fence | 724-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | FE000423 | Fence | 724-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | FE000423 | Fence | 724-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | FE000423 | Fence | 724-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | FE000423 | Fence | 724-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | YD000479 | Yard | 724-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | YD000479 | Yard | 724-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | YD000479 | Yard | 724-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | YD000479 | Yard | 724-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | YD000479 | Yard | 724-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | YD000479 | Yard | 724-Yard | Yard Patrol Inspection | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | YD000479 | Yard | 724-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | YD000479 | Yard | 724-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | YD000479 | Yard | 724-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | YD000479 | Yard | 724-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | YD000479 | Yard | 724-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | YD000479 | Yard | 724-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | YD000479 | Yard | 724-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | YD000479 | Yard | 724-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | YD000479 | Yard | 724-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | YD000479 | Yard | 724-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BAT001130 | Battery | 072-Battery Bank Distribution | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BAT001130 | Battery | 072-Battery Bank Distribution | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BAT001130 | Battery | 072-Battery Bank Distribution | Battery Patrol Inspection | Positive DC Ground | 66.9 | VDC |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BAT001130 | Battery | 072-Battery Bank Distribution | Battery Patrol Inspection | Negative DC Ground | 66.9 | VDC |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BAT001130 | Battery | 072-Battery Bank Distribution | Battery Patrol Inspection | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BAT001130 | Battery | 072-Battery Bank Distribution | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BAT001130 | Battery | 072-Battery Bank Distribution | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BAT001130 | Battery | 072-Battery Bank Distribution | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BAT001130 | Battery | 072-Battery Bank Distribution | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BAT001130 | Battery | 072-Battery Bank Distribution | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BAT001130 | Battery | 072-Battery Bank Distribution | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BAT001130 | Battery | 072-Battery Bank Distribution | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Readings | Oil Temp Max | 36 | °C |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1450 | psi |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1454 | Regulator | 613-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1454 | Regulator | 613-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1454 | Regulator | 613-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1454 | Regulator | 613-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1454 | Regulator | 613-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1454 | Regulator | 613-1 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1454 | Regulator | 613-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1454 | Regulator | 613-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1454 | Regulator | 613-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1454 | Regulator | 613-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1454 | Regulator | 613-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1454 | Regulator | 613-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1454 | Regulator | 613-1 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1454 | Regulator | 613-1 B | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1454 | Regulator | 613-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1454 | Regulator | 613-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1454 | Regulator | 613-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1454 | Regulator | 613-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1454 | Regulator | 613-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.6 | volts |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1454 | Regulator | 613-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 33736 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1454 | Regulator | 613-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1454 | Regulator | 613-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1454 | Regulator | 613-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | PF000058 | PowerFuse | C-GND TR 3 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | PF000058 | PowerFuse | C-GND TR 3 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | PF000058 | PowerFuse | C-GND TR 3 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | PF000059 | PowerFuse | C-GND TR 4 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | PF000059 | PowerFuse | C-GND TR 4 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | PF000059 | PowerFuse | C-GND TR 4 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | PF000060 | PowerFuse | C-14KV BUS SEC 3 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | PF000060 | PowerFuse | C-14KV BUS SEC 3 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | PF000060 | PowerFuse | C-14KV BUS SEC 3 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | PF000061 | PowerFuse | C-14KV BUS SEC 4 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | PF000061 | PowerFuse | C-14KV BUS SEC 4 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | PF000061 | PowerFuse | C-14KV BUS SEC 4 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Readings | LTC Totalizer Reading | 11610.00 | kw |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Readings | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF000116 | PowerFuse | ET-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF000116 | PowerFuse | ET-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF000116 | PowerFuse | ET-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF000117 | PowerFuse | ET-14KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF000117 | PowerFuse | ET-14KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF000117 | PowerFuse | ET-14KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF000121 | PowerFuse | ET-STA SER NO 6 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF000121 | PowerFuse | ET-STA SER NO 6 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | LTCC000852 | LTCControl | 600-1 | LTC Control Insp | VRR Base Voltage AF | 123.0 | VAC |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | LTCC000852 | LTCControl | 600-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | LTCC000852 | LTCControl | 600-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | LTCC000852 | LTCControl | 600-1 | LTC Control Insp | General Comments | | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | LTCC000852 | LTCControl | 600-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | LTCC000852 | LTCControl | 600-1 | LTC Control Insp | All Connections OK? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | PF000098 | PowerFuse | DE-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | PF000098 | PowerFuse | DE-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | PF000099 | PowerFuse | DE-14KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | PF000099 | PowerFuse | DE-14KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | FE000317 | Fence | 725-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | FE000317 | Fence | 725-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | FE000317 | Fence | 725-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | FE000317 | Fence | 725-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | FE000317 | Fence | 725-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | FE000317 | Fence | 725-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | FE000317 | Fence | 725-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | FE000317 | Fence | 725-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | FE000317 | Fence | 725-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | FE000317 | Fence | 725-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | FE000317 | Fence | 725-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | FE000317 | Fence | 725-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | FE000317 | Fence | 725-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | FE000317 | Fence | 725-Fence | Fence Patrol Inspection | General Comments | Fence is not connected but within two feet. | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | FE000317 | Fence | 725-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | FE000317 | Fence | 725-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | YD000320 | Yard | 892-Yard | Yard Patrol Inspection | Ambient Temp | 56 | °F |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | YD000320 | Yard | 892-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | YD000320 | Yard | 892-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | YD000320 | Yard | 892-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | YD000320 | Yard | 892-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | YD000320 | Yard | 892-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | YD000320 | Yard | 892-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | YD000320 | Yard | 892-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | YD000320 | Yard | 892-Yard | Yard Patrol Inspection | General Comments | | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | YD000320 | Yard | 892-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Readings | 9 Month Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Readings | Amps A Ø | 244.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Readings | Amps B Ø | 194.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Readings | Amps C Ø | 163.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BAT001130 | Battery | 072-Battery Bank Distribution | Battery Patrol Inspection | Battery Area Ambient Temp | 67 | °F |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BAT001130 | Battery | 072-Battery Bank Distribution | Battery Patrol Inspection | All Connections OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | PF000200 | PowerFuse | LS-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | PF000200 | PowerFuse | LS-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | LTCC000811 | LTCControl | 670-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | LTCC000811 | LTCControl | 670-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | LTCC000811 | LTCControl | 670-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | LTCC000811 | LTCControl | 670-1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | LTCC000811 | LTCControl | 670-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | LTCC000811 | LTCControl | 670-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | LTCC000811 | LTCControl | 670-1 | LTC Control Insp | General Comments | | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | LTCC000811 | LTCControl | 670-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | LTCC000811 | LTCControl | 670-1 | LTC Control Insp | All Connections OK? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | LTCC000308 | LTCControl | 786-1 | LTC Control Insp | All Connections OK? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | LTCC000308 | LTCControl | 786-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | LTCC000308 | LTCControl | 786-1 | LTC Control Insp | General Comments | | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | LTCC000308 | LTCControl | 786-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | LTCC000308 | LTCControl | 786-1 | LTC Control Insp | LTC Output Voltage Level | 124.6 | VAC |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | LTCC000308 | LTCControl | 786-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | LTCC000308 | LTCControl | 786-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | PF000146 | PowerFuse | FL-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | PF000146 | PowerFuse | FL-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | PF000146 | PowerFuse | FL-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | LTCC000308 | LTCControl | 786-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | PF000147 | PowerFuse | FL-14KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | PF000147 | PowerFuse | FL-14KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | PF000147 | PowerFuse | FL-14KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Readings | General Comments | | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 2749.44 | kw |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | W0246 | NonLTC | 787-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .8592 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | LTCC000852 | LTCControl | 600-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | LTCC000852 | LTCControl | 600-1 | LTC Control Insp | VRR Base Voltage AL | 123.0 | VAC |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1438 | Regulator | 786-2 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1438 | Regulator | 786-2 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | WithLTC | 585-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | WithLTC | 585-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | WithLTC | 585-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1438 | Regulator | 786-2 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | WithLTC | 585-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | WithLTC | 585-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | WithLTC | 585-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | WithLTC | 585-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | WithLTC | 585-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | WithLTC | 585-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | WithLTC | 585-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | WithLTC | 585-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | ST000152 | Structure | 640-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | ST000152 | Structure | 640-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | ST000152 | Structure | 640-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | ST000152 | Structure | 640-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | ST000152 | Structure | 640-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | ST000152 | Structure | 640-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | ST000152 | Structure | 640-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | ST000152 | Structure | 640-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | ST000152 | Structure | 640-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | ST000152 | Structure | 640-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | ST000152 | Structure | 640-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | ST000152 | Structure | 640-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | ST000152 | Structure | 640-Structure | Structure Patrol Inspection | General Comments | | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | ST000152 | Structure | 640-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | ST000152 | Structure | 640-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | ST000152 | Structure | 640-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | ST000152 | Structure | 640-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | ST000152 | Structure | 640-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | ST000152 | Structure | 640-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | ST000152 | Structure | 640-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | ST000152 | Structure | 640-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | ST000152 | Structure | 640-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | YD000148 | Yard | 640-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | YD000148 | Yard | 640-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | YD000148 | Yard | 640-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | YD000148 | Yard | 640-Yard | Yard Patrol Inspection | General Comments | | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | YD000148 | Yard | 640-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | YD000148 | Yard | 640-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | YD000148 | Yard | 640-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | YD000148 | Yard | 640-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | YD000148 | Yard | 640-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | YD000148 | Yard | 640-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | YD000148 | Yard | 640-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | YD000148 | Yard | 640-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | YD000148 | Yard | 640-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | YD000148 | Yard | 640-Yard | Yard Patrol Inspection | Ambient Temp | 54 | °F |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | PF000201 | PowerFuse | LS-STA SER NO 3 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | PF000201 | PowerFuse | LS-STA SER NO 3 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | PF000201 | PowerFuse | LS-STA SER NO 3 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1438 | Regulator | 786-2 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1438 | Regulator | 786-2 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1438 | Regulator | 786-2 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1438 | Regulator | 786-2 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1438 | Regulator | 786-2 C | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | YD000376 | Yard | 559-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | YD000376 | Yard | 559-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | YD000376 | Yard | 559-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | YD000376 | Yard | 559-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | YD000376 | Yard | 559-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | FE000370 | Fence | 559-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | FE000370 | Fence | 559-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | FE000370 | Fence | 559-Fence | Fence Patrol Inspection | General Comments | | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | FE000370 | Fence | 559-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | FE000370 | Fence | 559-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | FE000370 | Fence | 559-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | FE000370 | Fence | 559-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | FE000370 | Fence | 559-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | FE000370 | Fence | 559-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | FE000370 | Fence | 559-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | FE000370 | Fence | 559-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | FE000370 | Fence | 559-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | FE000370 | Fence | 559-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | FE000370 | Fence | 559-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | FE000370 | Fence | 559-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | FE000370 | Fence | 559-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0577 | Regulator | 441-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0577 | Regulator | 441-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0577 | Regulator | 441-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0577 | Regulator | 441-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 5856 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0577 | Regulator | 441-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0577 | Regulator | 441-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0577 | Regulator | 441-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0577 | Regulator | 441-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0577 | Regulator | 441-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0577 | Regulator | 441-1 A | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0577 | Regulator | 441-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0577 | Regulator | 441-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0577 | Regulator | 441-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0577 | Regulator | 441-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0577 | Regulator | 441-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0577 | Regulator | 441-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0577 | Regulator | 441-1 A | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0577 | Regulator | 441-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0577 | Regulator | 441-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0577 | Regulator | 441-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0577 | Regulator | 441-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0577 | Regulator | 441-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | WithLTC | 585-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | WithLTC | 585-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | WithLTC | 585-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | WithLTC | 585-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | WithLTC | 585-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | WithLTC | 585-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | WithLTC | 585-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | WithLTC | 585-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -1.0 | psi |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | WithLTC | 585-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | WithLTC | 585-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1438 | Regulator | 786-2 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1438 | Regulator | 786-2 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | WithLTC | 585-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | WithLTC | 585-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | WithLTC | 585-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1438 | Regulator | 786-2 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Present | 50 | °C |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Max | 65 | °C |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Present | 55 | °C |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | ST000406 | Structure | 670-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | ST000406 | Structure | 670-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | ST000406 | Structure | 670-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | ST000406 | Structure | 670-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | ST000406 | Structure | 670-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | ST000406 | Structure | 670-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | ST000406 | Structure | 670-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | ST000406 | Structure | 670-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | ST000406 | Structure | 670-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | ST000406 | Structure | 670-Structure | Structure Patrol Inspection | General Comments | | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | ST000406 | Structure | 670-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | ST000406 | Structure | 670-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | ST000406 | Structure | 670-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | ST000406 | Structure | 670-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | ST000406 | Structure | 670-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | ST000406 | Structure | 670-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | ST000406 | Structure | 670-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | ST000406 | Structure | 670-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | ST000406 | Structure | 670-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | ST000406 | Structure | 670-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | ST000406 | Structure | 670-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1451 | Regulator | 613-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1451 | Regulator | 613-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1451 | Regulator | 613-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Readings | Winding Temp Max | 36 | °C |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Readings | Totalizer Meter Reading | .6450 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1451 | Regulator | 613-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1451 | Regulator | 613-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1451 | Regulator | 613-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1451 | Regulator | 613-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1451 | Regulator | 613-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1451 | Regulator | 613-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1451 | Regulator | 613-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1451 | Regulator | 613-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1451 | Regulator | 613-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1451 | Regulator | 613-1 A | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1451 | Regulator | 613-1 A | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1451 | Regulator | 613-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1451 | Regulator | 613-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1451 | Regulator | 613-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1451 | Regulator | 613-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1451 | Regulator | 613-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.5 | volts |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1451 | Regulator | 613-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 35822 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1451 | Regulator | 613-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1451 | Regulator | 613-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1451 | Regulator | 613-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | TX000128 | WithLTC | 724-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1438 | Regulator | 786-2 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1438 | Regulator | 786-2 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1438 | Regulator | 786-2 C | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1438 | Regulator | 786-2 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1438 | Regulator | 786-2 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1438 | Regulator | 786-2 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1438 | Regulator | 786-2 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1438 | Regulator | 786-2 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.8 | volts |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1438 | Regulator | 786-2 C | Regulator Patrol Inspection | Regulator As Left Counter | 43451 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1438 | Regulator | 786-2 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1438 | Regulator | 786-2 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1438 | Regulator | 786-2 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | PF000032 | PowerFuse | BY-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | PF000032 | PowerFuse | BY-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | PF000033 | PowerFuse | BY-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | PF000033 | PowerFuse | BY-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Patrol Inspection | Fans Operational? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Readings | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Patrol Inspection | General Comments | one fan inop | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Readings | Oil Temp Max | 25 | °C |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Max | 56 | °C |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Present | 50 | °C |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BCH001597 | Charger | ET-Battery Bank 48V | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BCH001597 | Charger | ET-Battery Bank 48V | Battery Charger Patrol Insp | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BCH001597 | Charger | ET-Battery Bank 48V | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BCH001597 | Charger | ET-Battery Bank 48V | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BCH001597 | Charger | ET-Battery Bank 48V | Battery Charger Patrol Insp | Battery Charger Current | 3.7 | amps |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BCH001597 | Charger | ET-Battery Bank 48V | Battery Charger Patrol Insp | As Left Float Voltage | 54.2 | VDC |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BCH001597 | Charger | ET-Battery Bank 48V | Battery Charger Patrol Insp | As Found Float Voltage | 54.2 | VDC |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BCH001597 | Charger | ET-Battery Bank 48V | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0106 | WithLTC | LS-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Max | 60 | °C |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Readings | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Readings | Operations Counter AF | 187 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Readings | Operations Counter AL | 187 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | FE000336 | Fence | 785-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | FE000336 | Fence | 785-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | FE000336 | Fence | 785-Fence | Fence Patrol Inspection | General Comments | | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | FE000336 | Fence | 785-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | FE000336 | Fence | 785-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | FE000336 | Fence | 785-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | FE000336 | Fence | 785-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | FE000336 | Fence | 785-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | FE000336 | Fence | 785-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | FE000336 | Fence | 785-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | FE000336 | Fence | 785-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | FE000336 | Fence | 785-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | FE000336 | Fence | 785-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | FE000336 | Fence | 785-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | FE000336 | Fence | 785-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | FE000336 | Fence | 785-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Readings | 9 Month Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Readings | Amps A Ø | 98.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Readings | Amps B Ø | 98.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Readings | Amps C Ø | 106.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Readings | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Readings | Operations Counter AF | 214 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Readings | Operations Counter AL | 214 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Readings | Switching Operations | 1 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Readings | Unknown Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Readings | 9 Month Operations | 8 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Readings | Amps A Ø | 163.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Readings | Amps B Ø | 135.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Readings | Amps C Ø | 107.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Readings | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Readings | Operations Counter AF | 182 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Readings | Operations Counter AL | 182 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Readings | Switching Operations | 1 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001626 | BreakerVacuum | 124-0364 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Readings | 9 Month Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Readings | Amps A Ø | 129.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Readings | Amps B Ø | 141.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Readings | Amps C Ø | 121.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001627 | BreakerVacuum | 124-0365 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Readings | Oil Temp Max | 52 | °C |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | PF000062 | PowerFuse | C-STA SER NO 3 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | PF000062 | PowerFuse | C-STA SER NO 3 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | PF000062 | PowerFuse | C-STA SER NO 3 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Readings | 9 Month Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Readings | Amps A Ø | 285.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Readings | Amps B Ø | 298.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Readings | Amps C Ø | 258.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Readings | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Readings | Operations Counter AF | 189 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Readings | Operations Counter AL | 189 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001629 | BreakerVacuum | 124-0367 | VCB Readings | Unknown Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Patrol Inspection | General Comments | no nitrogen | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Readings | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Readings | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Readings | Operations Counter AF | 185 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Readings | Operations Counter AL | 185 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001628 | BreakerVacuum | 124-0366 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | ST000147 | Structure | 514-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | ST000147 | Structure | 514-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | ST000147 | Structure | 514-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | ST000147 | Structure | 514-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | ST000147 | Structure | 514-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | ST000147 | Structure | 514-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | ST000147 | Structure | 514-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | ST000147 | Structure | 514-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | ST000147 | Structure | 514-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | ST000147 | Structure | 514-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | ST000147 | Structure | 514-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | ST000147 | Structure | 514-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | ST000147 | Structure | 514-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | ST000147 | Structure | 514-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | ST000147 | Structure | 514-Structure | Structure Patrol Inspection | General Comments | fuse barrells need replacing. | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | ST000147 | Structure | 514-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | n | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | ST000147 | Structure | 514-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | ST000147 | Structure | 514-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | ST000147 | Structure | 514-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | ST000147 | Structure | 514-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | ST000147 | Structure | 514-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | ST000147 | Structure | 514-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | ST000147 | Structure | 514-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | ST000147 | Structure | 514-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | FE000144 | Fence | 514-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | FE000144 | Fence | 514-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | FE000144 | Fence | 514-Fence | Fence Patrol Inspection | General Comments | lots of rust on top rails | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | FE000144 | Fence | 514-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | FE000144 | Fence | 514-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | FE000144 | Fence | 514-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | FE000144 | Fence | 514-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | FE000144 | Fence | 514-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | FE000144 | Fence | 514-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | FE000144 | Fence | 514-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | n | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | FE000144 | Fence | 514-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | FE000144 | Fence | 514-Fence | Fence Patrol Inspection | Fence Gates Aligned? | n | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | FE000144 | Fence | 514-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | FE000144 | Fence | 514-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | FE000144 | Fence | 514-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | FE000144 | Fence | 514-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Readings | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Readings | Operations Counter AF | 168 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Readings | Operations Counter AL | 168 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Readings | 9 Month Operations | 2 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Readings | Amps A Ø | 78.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Readings | Amps B Ø | 47.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Readings | Amps C Ø | 51.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Readings | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Readings | Operations Counter AF | 201 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Readings | Operations Counter AL | 201 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Readings | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Readings | Operations Counter AF | 160 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Readings | Operations Counter AL | 160 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001620 | BreakerVacuum | 124-5 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Readings | 9 Month Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Readings | Amps A Ø | 578.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Readings | Amps B Ø | 575.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Readings | Amps C Ø | 518.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Readings | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Readings | Operations Counter AF | 160 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Readings | Operations Counter AL | 160 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001621 | BreakerVacuum | 124-6 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Readings | 9 Month Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Readings | Amps A Ø | 0.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Readings | Amps B Ø | 0.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Readings | Amps C Ø | 0.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001622 | BreakerVacuum | 124-BT5-6 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Readings | Amps A Ø | 74.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Readings | Amps B Ø | 39.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Readings | Amps C Ø | 45.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Readings | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Readings | Operations Counter AF | 210 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Readings | Operations Counter AL | 210 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Readings | Switching Operations | 1 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF000120 | PowerFuse | ET-STA SER NO 4 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF000120 | PowerFuse | ET-STA SER NO 4 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF000120 | PowerFuse | ET-STA SER NO 4 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Readings | 9 Month Operations | 3 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Readings | Amps A Ø | 17.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Readings | Amps B Ø | 19.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Readings | Amps C Ø | 26.0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001625 | BreakerVacuum | 124-0371 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001623 | BreakerVacuum | 124-0370 | VCB Readings | Unknown Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000074 | Switchgear | LS-Swgr Sec 3 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000074 | Switchgear | LS-Swgr Sec 3 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000074 | Switchgear | LS-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000074 | Switchgear | LS-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000074 | Switchgear | LS-Swgr Sec 3 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000074 | Switchgear | LS-Swgr Sec 3 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000074 | Switchgear | LS-Swgr Sec 3 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000074 | Switchgear | LS-Swgr Sec 3 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000074 | Switchgear | LS-Swgr Sec 3 | Switchgear Patrol Inspection | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000074 | Switchgear | LS-Swgr Sec 3 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000074 | Switchgear | LS-Swgr Sec 3 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000074 | Switchgear | LS-Swgr Sec 3 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000074 | Switchgear | LS-Swgr Sec 3 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000074 | Switchgear | LS-Swgr Sec 3 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000074 | Switchgear | LS-Swgr Sec 3 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000074 | Switchgear | LS-Swgr Sec 3 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000074 | Switchgear | LS-Swgr Sec 3 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000074 | Switchgear | LS-Swgr Sec 3 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000074 | Switchgear | LS-Swgr Sec 3 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | CH000161 | ControlHouse | C-Control House-Distribution | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | CH000161 | ControlHouse | C-Control House-Distribution | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | CH000161 | ControlHouse | C-Control House-Distribution | Control House Patrol Inspection | Trash Emptied? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | CH000161 | ControlHouse | C-Control House-Distribution | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | CH000161 | ControlHouse | C-Control House-Distribution | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | CH000161 | ControlHouse | C-Control House-Distribution | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | CH000161 | ControlHouse | C-Control House-Distribution | Control House Patrol Inspection | Panel Lights OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | CH000161 | ControlHouse | C-Control House-Distribution | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | CH000161 | ControlHouse | C-Control House-Distribution | Control House Patrol Inspection | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | CH000161 | ControlHouse | C-Control House-Distribution | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | CH000161 | ControlHouse | C-Control House-Distribution | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | CH000161 | ControlHouse | C-Control House-Distribution | Control House Patrol Inspection | Floor Swept? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | CH000161 | ControlHouse | C-Control House-Distribution | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | CH000161 | ControlHouse | C-Control House-Distribution | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | CH000161 | ControlHouse | C-Control House-Distribution | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | CH000161 | ControlHouse | C-Control House-Distribution | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | CH000161 | ControlHouse | C-Control House-Distribution | Control House Patrol Inspection | Door Alarms OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | CH000161 | ControlHouse | C-Control House-Distribution | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | CH000161 | ControlHouse | C-Control House-Distribution | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | CH000161 | ControlHouse | C-Control House-Distribution | Control House Patrol Inspection | Broom on Site? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | CH000161 | ControlHouse | C-Control House-Distribution | Control House Patrol Inspection | Basement Condition Acceptible | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | CH000161 | ControlHouse | C-Control House-Distribution | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | CH000161 | ControlHouse | C-Control House-Distribution | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Readings | 9 Month Operations | 1 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | BK001624 | BreakerVacuum | 124-0372 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 38 | °C |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | C0355 | NonLTC | 892-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .5779 | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | C0355 | NonLTC | 892-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 200 | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | C0355 | NonLTC | 892-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | C0355 | NonLTC | 892-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | C0355 | NonLTC | 892-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | C0355 | NonLTC | 892-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | C0355 | NonLTC | 892-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | C0355 | NonLTC | 892-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | C0355 | NonLTC | 892-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | C0355 | NonLTC | 892-1 | NonLTC Transformer Readings | Oil Temp Present | 18 | °C |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | C0355 | NonLTC | 892-1 | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | C0355 | NonLTC | 892-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | C0355 | NonLTC | 892-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | C0355 | NonLTC | 892-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 115.58 | kw |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | C0355 | NonLTC | 892-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | C0355 | NonLTC | 892-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | C0355 | NonLTC | 892-1 | NonLTC Transformer Readings | General Comments | | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | C0355 | NonLTC | 892-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | C0355 | NonLTC | 892-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | C0355 | NonLTC | 892-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | C0355 | NonLTC | 892-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | C0355 | NonLTC | 892-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | C0355 | NonLTC | 892-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | C0355 | NonLTC | 892-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | C0355 | NonLTC | 892-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | C0355 | NonLTC | 892-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0610 | Regulator | 510-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0610 | Regulator | 510-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0610 | Regulator | 510-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1250 | Regulator | 725-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1250 | Regulator | 725-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1250 | Regulator | 725-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1250 | Regulator | 725-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1250 | Regulator | 725-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | YD000406 | Yard | 585-Yard | Yard Patrol Inspection | General Comments | | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | YD000406 | Yard | 585-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | YD000406 | Yard | 585-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | YD000406 | Yard | 585-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | YD000406 | Yard | 585-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Readings | General Comments | | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Readings | Maintenance Operations | 1 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Readings | Operations Counter AF | 189 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Readings | Operations Counter AL | 189 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000085 | Switchgear | ET-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000085 | Switchgear | ET-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000085 | Switchgear | ET-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000085 | Switchgear | ET-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000085 | Switchgear | ET-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000085 | Switchgear | ET-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000085 | Switchgear | ET-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000085 | Switchgear | ET-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000085 | Switchgear | ET-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000085 | Switchgear | ET-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000085 | Switchgear | ET-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000085 | Switchgear | ET-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000085 | Switchgear | ET-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000085 | Switchgear | ET-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000085 | Switchgear | ET-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000085 | Switchgear | ET-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000085 | Switchgear | ET-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000085 | Switchgear | ET-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000085 | Switchgear | ET-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 35 | °C |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 45 | °C |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0064 | WithLTC | DE-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Readings | Oil Temp Max | 80 | °C |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Readings | LTC Totalizer Reading | 6752.16 | kw |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Readings | General Comments | | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BAT001670 | Battery | 888-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BAT001670 | Battery | 888-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BAT001670 | Battery | 888-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.7 | VDC |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BAT001670 | Battery | 888-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 28.1 | VDC |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BAT001670 | Battery | 888-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BAT001670 | Battery | 888-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BAT001670 | Battery | 888-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BAT001670 | Battery | 888-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BAT001670 | Battery | 888-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BAT001670 | Battery | 888-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BAT001670 | Battery | 888-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 55 | °F |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BAT001670 | Battery | 888-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BAT001379 | Battery | 600-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BAT001379 | Battery | 600-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 51 | °F |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BAT001379 | Battery | 600-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BAT001379 | Battery | 600-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BAT001379 | Battery | 600-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BAT001379 | Battery | 600-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BAT001379 | Battery | 600-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BAT001379 | Battery | 600-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BAT001379 | Battery | 600-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BAT001379 | Battery | 600-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BAT001379 | Battery | 600-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BAT001379 | Battery | 600-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BAT001379 | Battery | 600-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BAT001379 | Battery | 600-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BCH001302 | Charger | 600-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BCH001302 | Charger | 600-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.0 | VDC |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1250 | Regulator | 725-1 B | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1250 | Regulator | 725-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1250 | Regulator | 725-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1250 | Regulator | 725-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1250 | Regulator | 725-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1250 | Regulator | 725-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1250 | Regulator | 725-1 B | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1250 | Regulator | 725-1 B | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1250 | Regulator | 725-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1250 | Regulator | 725-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1250 | Regulator | 725-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1250 | Regulator | 725-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1250 | Regulator | 725-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1250 | Regulator | 725-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 360490 | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1250 | Regulator | 725-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1250 | Regulator | 725-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1250 | Regulator | 725-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1250 | Regulator | 725-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | FE000133 | Fence | 492-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | FE000133 | Fence | 492-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | FE000133 | Fence | 492-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | FE000133 | Fence | 492-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | FE000133 | Fence | 492-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | FE000133 | Fence | 492-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | FE000133 | Fence | 492-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | FE000133 | Fence | 492-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | FE000133 | Fence | 492-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | FE000133 | Fence | 492-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0610 | Regulator | 510-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0610 | Regulator | 510-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 48763 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0610 | Regulator | 510-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0610 | Regulator | 510-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0610 | Regulator | 510-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0610 | Regulator | 510-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0610 | Regulator | 510-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0610 | Regulator | 510-1 B | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0610 | Regulator | 510-1 B | Regulator Patrol Inspection | Max Tap Position | 1L | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0610 | Regulator | 510-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0610 | Regulator | 510-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0610 | Regulator | 510-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0610 | Regulator | 510-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0610 | Regulator | 510-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0610 | Regulator | 510-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0610 | Regulator | 510-1 B | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0610 | Regulator | 510-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0610 | Regulator | 510-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0610 | Regulator | 510-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0610 | Regulator | 510-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0610 | Regulator | 510-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | FE000133 | Fence | 492-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | FE000133 | Fence | 492-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | FE000133 | Fence | 492-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | FE000133 | Fence | 492-Fence | Fence Patrol Inspection | General Comments | | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | FE000133 | Fence | 492-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | FE000133 | Fence | 492-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 65.00 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Readings | Totalizer Meter Reading | .9378 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | WithLTC | 786-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | LTCMechanism | 640-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | LTCMechanism | 640-1 | LTC Mechanism Patrol Inspection | General Comments | at below low mark | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | LTCMechanism | 640-1 | LTC Counter Readings | General Comments | hands drag a bit but reset | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | LTCMechanism | 640-1 | LTC Counter Readings | LTC As Found Counter | 8143 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | LTCMechanism | 640-1 | LTC Counter Readings | LTC As Left Counter | 8149 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | LTCMechanism | 640-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | LTCMechanism | 640-1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | LTCMechanism | 640-1 | LTC Counter Readings | LTC Max Tap Position | 9L | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | LTCMechanism | 640-1 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Readings | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Readings | 9 Month Operations | 3 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Readings | Amps A Ø | 100.0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Readings | Amps B Ø | 93.0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Readings | Amps C Ø | 84.0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0075 | BreakerVacuum | BY-1281 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0075 | BreakerVacuum | BY-1281 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0075 | BreakerVacuum | BY-1281 | VCB Readings | Operations This Read Vac | 5 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0075 | BreakerVacuum | BY-1281 | VCB Readings | Operations Counter AL | 818 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0075 | BreakerVacuum | BY-1281 | VCB Readings | Operations Counter AF | 818 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0075 | BreakerVacuum | BY-1281 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0075 | BreakerVacuum | BY-1281 | VCB Readings | General Comments | b ioc | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0075 | BreakerVacuum | BY-1281 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0075 | BreakerVacuum | BY-1281 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0075 | BreakerVacuum | BY-1281 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0075 | BreakerVacuum | BY-1281 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0075 | BreakerVacuum | BY-1281 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0075 | BreakerVacuum | BY-1281 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0075 | BreakerVacuum | BY-1281 | VCB Readings | Fault Operations A Ø | 5 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0075 | BreakerVacuum | BY-1281 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0075 | BreakerVacuum | BY-1281 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0075 | BreakerVacuum | BY-1281 | VCB Readings | Fault Adjusted Amps A Phase V | 55.90 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0075 | BreakerVacuum | BY-1281 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0075 | BreakerVacuum | BY-1281 | VCB Readings | Amps C Ø | 220.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0075 | BreakerVacuum | BY-1281 | VCB Readings | Amps B Ø | 220.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0075 | BreakerVacuum | BY-1281 | VCB Readings | Amps A Ø | 220.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0075 | BreakerVacuum | BY-1281 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0075 | BreakerVacuum | BY-1281 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0075 | BreakerVacuum | BY-1281 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0075 | BreakerVacuum | BY-1281 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.4574 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Readings | Switching Operations | 1 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Readings | Operations Counter AL | 205 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Readings | Operations Counter AF | 204 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | YD000243 | Yard | 725-Yard | Yard Patrol Inspection | Ambient Temp | 57 | °F |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | YD000243 | Yard | 725-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | YD000243 | Yard | 725-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | YD000243 | Yard | 725-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | YD000243 | Yard | 725-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | YD000243 | Yard | 725-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | YD000243 | Yard | 725-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | YD000243 | Yard | 725-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | YD000243 | Yard | 725-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | YD000243 | Yard | 725-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | YD000243 | Yard | 725-Yard | Yard Patrol Inspection | General Comments | | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Readings | LTC Totalizer Reading | 10493.28 | kw |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Readings | General Comments | | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | WithLTC | 600-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | YD000243 | Yard | 725-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | YD000243 | Yard | 725-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | YD000243 | Yard | 725-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | YD000243 | Yard | 725-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | LTCMechanism | 640-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Readings | General Comments | | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1584.00 | kw |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Readings | Oil Temp Max | 30 | °C |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1800 | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .8800 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Readings | 9 Month Operations | 1 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Readings | Amps A Ø | 30.0 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Readings | Amps B Ø | 20.0 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Readings | Amps C Ø | 50.0 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | WB0158 | BreakerVacuum | 502-1427 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | YD000406 | Yard | 585-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Readings | Amps C Ø | 176.0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Readings | Amps B Ø | 180.0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Readings | Amps A Ø | 178.0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Readings | 9 Month Operations | 1 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | YD000406 | Yard | 585-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | YD000406 | Yard | 585-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | YD000406 | Yard | 585-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | YD000406 | Yard | 585-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | YD000406 | Yard | 585-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | YD000406 | Yard | 585-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | YD000406 | Yard | 585-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | YD000406 | Yard | 585-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | YD000406 | Yard | 585-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0075 | BreakerVacuum | BY-1281 | VCB Readings | 9 Month Operations | 10 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | FE000599 | Fence | DE-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | FE000599 | Fence | DE-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | FE000599 | Fence | DE-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | FE000599 | Fence | DE-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | FE000599 | Fence | DE-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | FE000599 | Fence | DE-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | FE000599 | Fence | DE-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | FE000599 | Fence | DE-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | FE000599 | Fence | DE-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | FE000599 | Fence | DE-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | FE000599 | Fence | DE-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | FE000599 | Fence | DE-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | FE000599 | Fence | DE-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | FE000599 | Fence | DE-Fence | Fence Patrol Inspection | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | LTCMechanism | 640-1 | LTC Counter Readings | LTC Operations Since Last Insp | 181 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | LTCMechanism | 640-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Very Low | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | LTCMechanism | 640-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | LTCMechanism | 640-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Readings | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Readings | Operations Counter AF | 227 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Readings | Operations Counter AL | 228 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Readings | Switching Operations | 1 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000718 | BreakerVacuum | 724-2542 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000717 | BreakerVacuum | 724-2523 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | FE000599 | Fence | DE-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | FE000599 | Fence | DE-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | B0258 | NonLTC | 785-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | LTCMechanism | 072-6 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | LTCMechanism | 072-6 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | LTCMechanism | 072-6 | LTC Counter Readings | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | LTCMechanism | 072-6 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | LTCMechanism | 072-6 | LTC Counter Readings | LTC As Found Counter | 261994 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | LTCMechanism | 072-6 | LTC Counter Readings | LTC As Left Counter | 261998 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | LTCMechanism | 072-6 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | LTCMechanism | 072-6 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | LTCMechanism | 072-6 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | LTCMechanism | 072-6 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | LTCMechanism | 072-6 | LTC Counter Readings | LTC Operations Since Last Insp | 1804 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | LTCMechanism | 072-6 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | LTCMechanism | 072-6 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | LTCMechanism | 072-6 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Readings | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Readings | LTC Totalizer Reading | 8820.00 | kw |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Readings | Oil Temp Max | 48 | °C |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Readings | Oil Temp Present | 38 | °C |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Readings | Totalizer Meter Reading | .4900 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Readings | Winding Temp Max | 35 | °C |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Readings | Winding Temp Present | 28 | °C |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 135.00 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LTCC000284 | LTCControl | FL-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LTCC000284 | LTCControl | FL-TRANS 1 | LTC Control Insp | General Comments | | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LTCC000284 | LTCControl | FL-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | ST000215 | Structure | 613-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | ST000215 | Structure | 613-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | ST000215 | Structure | 613-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | ST000215 | Structure | 613-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | ST000215 | Structure | 613-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | ST000215 | Structure | 613-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | ST000215 | Structure | 613-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | ST000215 | Structure | 613-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | ST000215 | Structure | 613-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Readings | Operations Counter AF | 183 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Readings | Operations Counter AL | 183 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Readings | Unknown Operations | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BCH001090 | Charger | DE-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BCH001090 | Charger | DE-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BCH001090 | Charger | DE-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | LTCC000825 | LTCControl | 640-1 | LTC Control Insp | All Connections OK? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | LTCC000825 | LTCControl | 640-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | LTCC000825 | LTCControl | 640-1 | LTC Control Insp | General Comments | | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | LTCC000825 | LTCControl | 640-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | LTCC000825 | LTCControl | 640-1 | LTC Control Insp | LTC Output Voltage Level | 123.9 | VAC |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | LTCC000825 | LTCControl | 640-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | LTCC000825 | LTCControl | 640-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | LTCC000825 | LTCControl | 640-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BCH001090 | Charger | DE-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BCH001090 | Charger | DE-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 4.9 | amps |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BCH001090 | Charger | DE-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BCH001090 | Charger | DE-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BCH001090 | Charger | DE-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | LTCC000721 | LTCControl | 724-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | LTCC000721 | LTCControl | 724-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | LTCC000721 | LTCControl | 724-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | LTCC000721 | LTCControl | 724-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | LTCC000721 | LTCControl | 724-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | LTCC000721 | LTCControl | 724-2 | LTC Control Insp | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | LTCC000721 | LTCControl | 724-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | LTCC000721 | LTCControl | 724-2 | LTC Control Insp | All Connections OK? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | LTCM000060 | LTCMechanism | 724-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | LTCM000060 | LTCMechanism | 724-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | LTCM000060 | LTCMechanism | 724-2 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | LTCM000060 | LTCMechanism | 724-2 | LTC Counter Readings | LTC Operations Since Last Insp | 349 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | LTCM000060 | LTCMechanism | 724-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 25 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | LTCM000060 | LTCMechanism | 724-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 30 | °C |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | LTCM000060 | LTCMechanism | 724-2 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | LTCM000060 | LTCMechanism | 724-2 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | LTCM000060 | LTCMechanism | 724-2 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | LTCM000060 | LTCMechanism | 724-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | LTCM000060 | LTCMechanism | 724-2 | LTC Counter Readings | LTC As Left Counter | 19944 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | LTCM000060 | LTCMechanism | 724-2 | LTC Counter Readings | LTC As Found Counter | 19944 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | LTCM000060 | LTCMechanism | 724-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | LTCM000060 | LTCMechanism | 724-2 | LTC Counter Readings | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | LTCM000060 | LTCMechanism | 724-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | LTCM000060 | LTCMechanism | 724-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | WithLTC | 724-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | YD000379 | Yard | 441-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | YD000379 | Yard | 441-Yard | Yard Patrol Inspection | Ambient Temp | 53 | °F |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | FE000373 | Fence | 441-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | FE000373 | Fence | 441-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | FE000373 | Fence | 441-Fence | Fence Patrol Inspection | General Comments | | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | FE000373 | Fence | 441-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | FE000373 | Fence | 441-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | FE000373 | Fence | 441-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | FE000373 | Fence | 441-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | FE000373 | Fence | 441-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | FE000373 | Fence | 441-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | FE000373 | Fence | 441-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | FE000373 | Fence | 441-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | FE000373 | Fence | 441-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | FE000373 | Fence | 441-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | FE000373 | Fence | 441-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | FE000373 | Fence | 441-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | FE000373 | Fence | 441-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | ST000380 | Structure | 559-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | ST000380 | Structure | 559-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | ST000380 | Structure | 559-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | ST000380 | Structure | 559-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | ST000380 | Structure | 559-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | ST000380 | Structure | 559-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | ST000380 | Structure | 559-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | ST000380 | Structure | 559-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | ST000380 | Structure | 559-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | ST000380 | Structure | 559-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | ST000380 | Structure | 559-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | ST000380 | Structure | 559-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | ST000380 | Structure | 559-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | ST000380 | Structure | 559-Structure | Structure Patrol Inspection | General Comments | | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | ST000380 | Structure | 559-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | ST000380 | Structure | 559-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | ST000380 | Structure | 559-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | ST000380 | Structure | 559-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | ST000380 | Structure | 559-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | ST000380 | Structure | 559-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | ST000380 | Structure | 559-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | ST000380 | Structure | 559-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | ST000380 | Structure | 559-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | YD000376 | Yard | 559-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | YD000376 | Yard | 559-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | YD000376 | Yard | 559-Yard | Yard Patrol Inspection | Switch Stick Next Test Date | 2023-05-11 00:00:00.000000 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | YD000376 | Yard | 559-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1437 | Regulator | 786-2 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1437 | Regulator | 786-2 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1437 | Regulator | 786-2 B | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1437 | Regulator | 786-2 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1437 | Regulator | 786-2 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1437 | Regulator | 786-2 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1437 | Regulator | 786-2 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1437 | Regulator | 786-2 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | YD000376 | Yard | 559-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | YD000376 | Yard | 559-Yard | Yard Patrol Inspection | General Comments | | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | YD000376 | Yard | 559-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | YD000376 | Yard | 559-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | YD000376 | Yard | 559-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | YD000376 | Yard | 559-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Readings | General Comments | | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Readings | LTC Totalizer Reading | 12643.20 | kw |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Readings | Oil Temp Max | 80 | °C |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.3170 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Readings | Winding Temp Max | 50 | °C |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Readings | Winding Temp Present | 35 | °C |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 20.00 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | WithLTC | 670-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1437 | Regulator | 786-2 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1437 | Regulator | 786-2 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1437 | Regulator | 786-2 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1437 | Regulator | 786-2 B | Regulator Patrol Inspection | Regulator As Left Counter | 43155 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | YD000379 | Yard | 441-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1437 | Regulator | 786-2 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1437 | Regulator | 786-2 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1437 | Regulator | 786-2 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1437 | Regulator | 786-2 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1437 | Regulator | 786-2 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1437 | Regulator | 786-2 B | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1437 | Regulator | 786-2 B | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1437 | Regulator | 786-2 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1437 | Regulator | 786-2 B | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1437 | Regulator | 786-2 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1437 | Regulator | 786-2 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | YD000379 | Yard | 441-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | YD000379 | Yard | 441-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | YD000379 | Yard | 441-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | YD000379 | Yard | 441-Yard | Yard Patrol Inspection | General Comments | | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | YD000379 | Yard | 441-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | YD000379 | Yard | 441-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | YD000379 | Yard | 441-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | YD000379 | Yard | 441-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | YD000379 | Yard | 441-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | YD000379 | Yard | 441-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | YD000379 | Yard | 441-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | YD000379 | Yard | 441-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | ST000192 | Structure | 888-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | ST000192 | Structure | 888-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | ST000192 | Structure | 888-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | ST000192 | Structure | 888-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | ST000192 | Structure | 888-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | ST000192 | Structure | 888-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | YD000207 | Yard | 613-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | YD000207 | Yard | 613-Yard | Yard Patrol Inspection | Vegetation | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | YD000207 | Yard | 613-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | YD000207 | Yard | 613-Yard | Yard Patrol Inspection | General Comments | | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | YD000207 | Yard | 613-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | YD000207 | Yard | 613-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | YD000207 | Yard | 613-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | YD000207 | Yard | 613-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | YD000207 | Yard | 613-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | YD000207 | Yard | 613-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | YD000207 | Yard | 613-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | YD000207 | Yard | 613-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | YD000207 | Yard | 613-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | YD000207 | Yard | 613-Yard | Yard Patrol Inspection | Ambient Temp | 65 | °F |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | FE000208 | Fence | 613-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | FE000208 | Fence | 613-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | FE000208 | Fence | 613-Fence | Fence Patrol Inspection | General Comments | | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | FE000208 | Fence | 613-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | FE000208 | Fence | 613-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | FE000208 | Fence | 613-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | FE000208 | Fence | 613-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | FE000208 | Fence | 613-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | FE000208 | Fence | 613-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | FE000208 | Fence | 613-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | FE000208 | Fence | 613-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | FE000208 | Fence | 613-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | FE000208 | Fence | 613-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | FE000208 | Fence | 613-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | FE000208 | Fence | 613-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | FE000208 | Fence | 613-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | ST000214 | Structure | 492-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | ST000214 | Structure | 492-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | ST000214 | Structure | 492-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | ST000214 | Structure | 492-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | ST000214 | Structure | 492-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | ST000214 | Structure | 492-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | ST000214 | Structure | 492-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | ST000214 | Structure | 492-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | ST000214 | Structure | 492-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | ST000214 | Structure | 492-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | ST000214 | Structure | 492-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | ST000214 | Structure | 492-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | ST000214 | Structure | 492-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | ST000214 | Structure | 492-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | ST000214 | Structure | 492-Structure | Structure Patrol Inspection | General Comments | | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | ST000214 | Structure | 492-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | ST000214 | Structure | 492-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | ST000214 | Structure | 492-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | ST000214 | Structure | 492-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | ST000214 | Structure | 492-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | ST000214 | Structure | 492-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BCH001302 | Charger | 600-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.0 | VDC |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BCH001302 | Charger | 600-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .4 | amps |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BCH001302 | Charger | 600-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BCH001302 | Charger | 600-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BCH001302 | Charger | 600-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BCH001302 | Charger | 600-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | BAT001662 | Battery | 640-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | BAT001662 | Battery | 640-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | BAT001662 | Battery | 640-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.9 | VDC |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | BAT001662 | Battery | 640-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 28.1 | VDC |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | BAT001662 | Battery | 640-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | BAT001662 | Battery | 640-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | BAT001662 | Battery | 640-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | BAT001662 | Battery | 640-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | BAT001662 | Battery | 640-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | BAT001662 | Battery | 640-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | BAT001662 | Battery | 640-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 54 | °F |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | BAT001662 | Battery | 640-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1066 | Regulator | 785-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1066 | Regulator | 785-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1066 | Regulator | 785-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1066 | Regulator | 785-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1066 | Regulator | 785-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1066 | Regulator | 785-1 B | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1066 | Regulator | 785-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1066 | Regulator | 785-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1066 | Regulator | 785-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1066 | Regulator | 785-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1066 | Regulator | 785-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1066 | Regulator | 785-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1066 | Regulator | 785-1 B | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1066 | Regulator | 785-1 B | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1066 | Regulator | 785-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1066 | Regulator | 785-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1066 | Regulator | 785-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1066 | Regulator | 785-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1066 | Regulator | 785-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1066 | Regulator | 785-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 103699 | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1066 | Regulator | 785-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1066 | Regulator | 785-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1066 | Regulator | 785-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1066 | Regulator | 785-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | ST000192 | Structure | 888-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | ST000192 | Structure | 888-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | ST000192 | Structure | 888-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | ST000192 | Structure | 888-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | ST000192 | Structure | 888-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | ST000192 | Structure | 888-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | ST000192 | Structure | 888-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | ST000192 | Structure | 888-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | ST000192 | Structure | 888-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | ST000192 | Structure | 888-Structure | Structure Patrol Inspection | General Comments | | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | ST000192 | Structure | 888-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | ST000192 | Structure | 888-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | ST000192 | Structure | 888-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | ST000192 | Structure | 888-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | ST000192 | Structure | 888-Structure | Structure Patrol Inspection | MOD Cabinet Internals Clean? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | ST000192 | Structure | 888-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | ST000192 | Structure | 888-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 3600 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Readings | Totalizer Meter Reading | .7686 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1456 | Regulator | 613-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1456 | Regulator | 613-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1456 | Regulator | 613-1 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1456 | Regulator | 613-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1456 | Regulator | 613-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1456 | Regulator | 613-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1456 | Regulator | 613-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1456 | Regulator | 613-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Readings | Winding Temp Max | 0 | °C |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Readings | Winding Temp Present | 0 | °C |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | ST000215 | Structure | 613-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | ST000215 | Structure | 613-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | ST000215 | Structure | 613-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | ST000215 | Structure | 613-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | ST000215 | Structure | 613-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | ST000215 | Structure | 613-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | ST000215 | Structure | 613-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | ST000215 | Structure | 613-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | ST000215 | Structure | 613-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | ST000215 | Structure | 613-Structure | Structure Patrol Inspection | General Comments | | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Readings | 9 Month Operations | 1 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Readings | Amps A Ø | 330.0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Readings | Amps B Ø | 339.0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Readings | Amps C Ø | 324.0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | ST000215 | Structure | 613-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | ST000215 | Structure | 613-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | ST000215 | Structure | 613-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | ST000215 | Structure | 613-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Readings | General Comments | | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BK000726 | BreakerVacuum | 888-0437 | VCB Readings | Maintenance Operations | 1 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | ST000214 | Structure | 492-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | ST000214 | Structure | 492-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | ST000214 | Structure | 492-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1456 | Regulator | 613-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1456 | Regulator | 613-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1456 | Regulator | 613-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1456 | Regulator | 613-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 31155 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1456 | Regulator | 613-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1456 | Regulator | 613-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1456 | Regulator | 613-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1456 | Regulator | 613-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1456 | Regulator | 613-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1456 | Regulator | 613-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1456 | Regulator | 613-1 C | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1456 | Regulator | 613-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1456 | Regulator | 613-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1456 | Regulator | 613-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | R1456 | Regulator | 613-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Readings | General Comments | No winding temp gauge. | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Readings | LTC Totalizer Reading | 2766.96 | kw |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | YD000142 | Yard | 514-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | YD000142 | Yard | 514-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | YD000142 | Yard | 514-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | YD000142 | Yard | 514-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | YD000142 | Yard | 514-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | YD000142 | Yard | 514-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | YD000142 | Yard | 514-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | YD000142 | Yard | 514-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | YD000142 | Yard | 514-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | YD000142 | Yard | 514-Yard | Yard Patrol Inspection | General Comments | | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | YD000142 | Yard | 514-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | YD000142 | Yard | 514-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | YD000142 | Yard | 514-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | W0352 | WithLTC | 640-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Readings | Amps C Ø | 44.0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Readings | General Comments | | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Readings | Maintenance Operations | 1 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Readings | Operations Counter AF | 171 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Readings | Operations Counter AL | 171 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Readings | Unknown Operations | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | ANN000027 | Annunciator | DE-Annunciator Panel | Annunciator Patrol Inspection | All Lights Functioning? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | ANN000027 | Annunciator | DE-Annunciator Panel | Annunciator Patrol Inspection | Control House Alarm Audible? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | ANN000027 | Annunciator | DE-Annunciator Panel | Annunciator Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | ANN000027 | Annunciator | DE-Annunciator Panel | Annunciator Patrol Inspection | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | ANN000013 | Annunciator | BY-Annunciator Panel | Annunciator Patrol Inspection | All Lights Functioning? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | ANN000013 | Annunciator | BY-Annunciator Panel | Annunciator Patrol Inspection | Control House Alarm Audible? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | ANN000013 | Annunciator | BY-Annunciator Panel | Annunciator Patrol Inspection | ESOC  Received Alarm Test? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | ANN000013 | Annunciator | BY-Annunciator Panel | Annunciator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | ANN000013 | Annunciator | BY-Annunciator Panel | Annunciator Patrol Inspection | General Comments | | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Readings | Unknown Operations | 3 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Readings | Operations This Read Vac | 5 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Readings | Operations Counter AL | 0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Readings | 9 Month Operations | 1 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Readings | Amps A Ø | 19.0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Readings | Amps B Ø | 18.0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Readings | Amps C Ø | 24.0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | ST000070 | Structure | 890-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | ST000070 | Structure | 890-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | ST000070 | Structure | 890-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | ST000070 | Structure | 890-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | ST000070 | Structure | 890-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | ST000070 | Structure | 890-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | ST000070 | Structure | 890-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | ST000070 | Structure | 890-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | ST000070 | Structure | 890-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | ST000070 | Structure | 890-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | ST000070 | Structure | 890-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | ST000070 | Structure | 890-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | ST000070 | Structure | 890-Structure | Structure Patrol Inspection | General Comments | | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | ST000070 | Structure | 890-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Patrol Inspection | Ambient Temperature | 60 | °F |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Readings | Amps A Ø | 21.0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Readings | Amps B Ø | 18.0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Readings | Amps C Ø | 24.0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Readings | Fault Operations | 0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Readings | General Comments | | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Patrol Inspection | General Comments | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Readings | Operations Counter AF | 101 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Readings | Operations Counter AL | 0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Readings | Operations This Read SF6 | 0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Patrol Inspection | SF6 Pressure | 65 | psi |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Readings | Switching Operations | 0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001674 | BreakerSF6 | 492-608 | GCB Readings | Unknown Operations | 0 | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | ST000070 | Structure | 890-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | ST000070 | Structure | 890-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | ST000070 | Structure | 890-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | ST000070 | Structure | 890-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | ST000070 | Structure | 890-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | ST000070 | Structure | 890-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | ST000070 | Structure | 890-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Readings | 9 Month Operations | 1 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Readings | Amps A Ø | 36.0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001677 | BreakerVacuum | 492-1742 | VCB Readings | Amps B Ø | 35.0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Readings | General Comments | | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Readings | Fault Operations C Ø | 1 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Readings | Fault Adjusted Amps C Phase V | 6.98 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Readings | Fault Adjusted Amps B Phase V | 5.24 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Readings | Fault Adjusted Amps A Phase V | 5.24 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Readings | Amps C Ø | 5.0 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Readings | Amps B Ø | 5.0 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Readings | Amps A Ø | 10.0 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Readings | 9 Month Operations | 8 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BCH001437 | Charger | 492-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 4.300 | millivolts |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BCH001437 | Charger | 492-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.6 | VDC |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BCH001437 | Charger | 492-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.6 | VDC |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BCH001437 | Charger | 492-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 3.3 | amps |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BCH001437 | Charger | 492-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BCH001437 | Charger | 492-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BCH001437 | Charger | 492-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BCH001437 | Charger | 492-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BAT001507 | Battery | 492-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BAT001507 | Battery | 492-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 69 | °F |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BAT001507 | Battery | 492-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BAT001507 | Battery | 492-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BAT001507 | Battery | 492-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BAT001507 | Battery | 492-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BAT001507 | Battery | 492-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BAT001507 | Battery | 492-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BAT001507 | Battery | 492-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BAT001507 | Battery | 492-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.7 | VDC |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BAT001507 | Battery | 492-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.8 | VDC |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BAT001507 | Battery | 492-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BAT001507 | Battery | 492-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Readings | General Comments | | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Readings | Maintenance Operations | 1 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Readings | Operations Counter AF | 178 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Readings | Operations Counter AL | 178 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | BK001678 | BreakerVacuum | 492-1743 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Readings | Operations Counter AF | 1562 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Readings | Maintenance Operations | 1 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0146 | BreakerVacuum | 640-1467 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .3744 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Readings | Oil Temp Max | 30 | °C |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 2695.68 | kw |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1 | psi |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Patrol Inspection | Gas Accumulation Gauge | Normal | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | TX000274 | NonLTC | 492-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | CH000182 | ControlHouse | DE-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | CH000182 | ControlHouse | DE-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000602 | BreakerSF6 | 724-618 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000602 | BreakerSF6 | 724-618 | GCB Readings | Fault Operations | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000602 | BreakerSF6 | 724-618 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000602 | BreakerSF6 | 724-618 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000602 | BreakerSF6 | 724-618 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000602 | BreakerSF6 | 724-618 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000602 | BreakerSF6 | 724-618 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000602 | BreakerSF6 | 724-618 | GCB Patrol Inspection | Ambient Temperature | 60 | °F |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BAT000371 | Battery | 585-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BAT000371 | Battery | 585-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BAT000371 | Battery | 585-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BAT000371 | Battery | 585-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BAT000371 | Battery | 585-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BAT000371 | Battery | 585-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BAT000371 | Battery | 585-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BAT000371 | Battery | 585-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BAT000371 | Battery | 585-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BAT000371 | Battery | 585-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BAT000371 | Battery | 585-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BAT000371 | Battery | 585-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BAT000371 | Battery | 585-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BAT000371 | Battery | 585-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000602 | BreakerSF6 | 724-618 | GCB Readings | 9 Month Operations GCB New | 1 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000601 | BreakerSF6 | 724-608 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000601 | BreakerSF6 | 724-608 | GCB Readings | Switching Operations | 2 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000601 | BreakerSF6 | 724-608 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000601 | BreakerSF6 | 724-608 | GCB Patrol Inspection | SF6 Pressure Indicator | good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000601 | BreakerSF6 | 724-608 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000601 | BreakerSF6 | 724-608 | GCB Readings | Operations This Read SF6 | 2 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000601 | BreakerSF6 | 724-608 | GCB Readings | Operations Counter AL | 35 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000601 | BreakerSF6 | 724-608 | GCB Readings | Operations Counter AF | 34 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000601 | BreakerSF6 | 724-608 | GCB Readings | Num Operations Last 9 Months | 3 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000601 | BreakerSF6 | 724-608 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000601 | BreakerSF6 | 724-608 | GCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000601 | BreakerSF6 | 724-608 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000601 | BreakerSF6 | 724-608 | GCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000601 | BreakerSF6 | 724-608 | GCB Patrol Inspection | General Comments | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000601 | BreakerSF6 | 724-608 | GCB Readings | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000601 | BreakerSF6 | 724-608 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000601 | BreakerSF6 | 724-608 | GCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000601 | BreakerSF6 | 724-608 | GCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000601 | BreakerSF6 | 724-608 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000601 | BreakerSF6 | 724-608 | GCB Readings | Fault Operations | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000601 | BreakerSF6 | 724-608 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000601 | BreakerSF6 | 724-608 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000601 | BreakerSF6 | 724-608 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000601 | BreakerSF6 | 724-608 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000601 | BreakerSF6 | 724-608 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000601 | BreakerSF6 | 724-608 | GCB Patrol Inspection | Ambient Temperature | 60 | °F |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000601 | BreakerSF6 | 724-608 | GCB Readings | 9 Month Operations GCB New | 1 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1255 | BreakerVacuum | BY-1277 | VCB Readings | 9 Month Operations | 15 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1255 | BreakerVacuum | BY-1277 | VCB Readings | 9 Month Operations VCB New | 15 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1255 | BreakerVacuum | BY-1277 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1255 | BreakerVacuum | BY-1277 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1255 | BreakerVacuum | BY-1277 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1255 | BreakerVacuum | BY-1277 | VCB Readings | Amps A Ø | 188.0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Readings | 9 Month Operations | 22 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000602 | BreakerSF6 | 724-618 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000602 | BreakerSF6 | 724-618 | GCB Readings | Switching Operations | 2 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000602 | BreakerSF6 | 724-618 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000602 | BreakerSF6 | 724-618 | GCB Patrol Inspection | SF6 Pressure Indicator | good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000602 | BreakerSF6 | 724-618 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | YD000370 | Yard | 891-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | YD000370 | Yard | 891-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | YD000370 | Yard | 891-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | YD000370 | Yard | 891-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | YD000370 | Yard | 891-Yard | Yard Patrol Inspection | General Comments | | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | YD000370 | Yard | 891-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | YD000370 | Yard | 891-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | YD000370 | Yard | 891-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | YD000370 | Yard | 891-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | YD000370 | Yard | 891-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | YD000370 | Yard | 891-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | YD000370 | Yard | 891-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | YD000370 | Yard | 891-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LTCC000120 | LTCControl | ET-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LTCC000120 | LTCControl | ET-TRANS 2 | LTC Control Insp | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LTCC000120 | LTCControl | ET-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | YD000370 | Yard | 891-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | YD000370 | Yard | 891-Yard | Yard Patrol Inspection | Ambient Temp | 38 | °F |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000602 | BreakerSF6 | 724-618 | GCB Readings | Operations This Read SF6 | 2 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000602 | BreakerSF6 | 724-618 | GCB Readings | Operations Counter AL | 47 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000602 | BreakerSF6 | 724-618 | GCB Readings | Operations Counter AF | 46 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000602 | BreakerSF6 | 724-618 | GCB Readings | Num Operations Last 9 Months | 3 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000602 | BreakerSF6 | 724-618 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000602 | BreakerSF6 | 724-618 | GCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000602 | BreakerSF6 | 724-618 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000602 | BreakerSF6 | 724-618 | GCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000602 | BreakerSF6 | 724-618 | GCB Patrol Inspection | General Comments | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000602 | BreakerSF6 | 724-618 | GCB Readings | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000602 | BreakerSF6 | 724-618 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000602 | BreakerSF6 | 724-618 | GCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000602 | BreakerSF6 | 724-618 | GCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | CH000182 | ControlHouse | DE-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | CH000182 | ControlHouse | DE-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | CH000182 | ControlHouse | DE-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | CH000182 | ControlHouse | DE-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | CH000182 | ControlHouse | DE-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | CH000182 | ControlHouse | DE-Control House | Control House Patrol Inspection | Restroom Clean & OK? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | CH000182 | ControlHouse | DE-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | CH000182 | ControlHouse | DE-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | CH000182 | ControlHouse | DE-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | CH000182 | ControlHouse | DE-Control House | Control House Patrol Inspection | General Comments | | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | CH000182 | ControlHouse | DE-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | CH000182 | ControlHouse | DE-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | CH000182 | ControlHouse | DE-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | CH000182 | ControlHouse | DE-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | CH000182 | ControlHouse | DE-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | CH000182 | ControlHouse | DE-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | CH000182 | ControlHouse | DE-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | CH000182 | ControlHouse | DE-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | CH000182 | ControlHouse | DE-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | CH000182 | ControlHouse | DE-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | CH000182 | ControlHouse | DE-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | CH000169 | ControlHouse | BY-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | CH000169 | ControlHouse | BY-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | CH000169 | ControlHouse | BY-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BCH001132 | Charger | 072-Battery Charger Distribution | Battery Charger Patrol Insp | As Found Float Voltage | 134.2 | VDC |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BCH001132 | Charger | 072-Battery Charger Distribution | Battery Charger Patrol Insp | As Left Float Voltage | 134.2 | VDC |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BCH001132 | Charger | 072-Battery Charger Distribution | Battery Charger Patrol Insp | Battery Charger Current | 1.8 | amps |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BCH001132 | Charger | 072-Battery Charger Distribution | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BCH001132 | Charger | 072-Battery Charger Distribution | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BCH001132 | Charger | 072-Battery Charger Distribution | Battery Charger Patrol Insp | General Comments | | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LTCC000491 | LTCControl | DE-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LTCC000491 | LTCControl | DE-TRANS 1 | LTC Control Insp | General Comments | | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LTCC000491 | LTCControl | DE-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | CH000413 | ControlHouse | 786-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | CH000413 | ControlHouse | 786-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | CH000413 | ControlHouse | 786-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BCH000056 | Charger | C-Battery Charger-Distribution | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BCH000056 | Charger | C-Battery Charger-Distribution | Battery Charger Patrol Insp | As Found Float Voltage | 133.4 | VDC |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BCH000056 | Charger | C-Battery Charger-Distribution | Battery Charger Patrol Insp | As Left Float Voltage | 133.4 | VDC |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BCH000056 | Charger | C-Battery Charger-Distribution | Battery Charger Patrol Insp | Battery Charger Current | 4.1 | amps |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BCH000056 | Charger | C-Battery Charger-Distribution | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BCH000056 | Charger | C-Battery Charger-Distribution | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BCH000056 | Charger | C-Battery Charger-Distribution | Battery Charger Patrol Insp | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BCH000056 | Charger | C-Battery Charger-Distribution | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | CH000413 | ControlHouse | 786-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | CH000413 | ControlHouse | 786-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | CH000413 | ControlHouse | 786-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | CH000413 | ControlHouse | 786-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | CH000413 | ControlHouse | 786-Control House | Control House Patrol Inspection | General Comments | | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | CH000413 | ControlHouse | 786-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | CH000413 | ControlHouse | 786-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LTCM000068 | LTCMechanism | DE-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LTCM000068 | LTCMechanism | DE-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LTCM000068 | LTCMechanism | DE-TRANS 1 | LTC Counter Readings | General Comments | | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LTCM000068 | LTCMechanism | DE-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LTCM000068 | LTCMechanism | DE-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 434479 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LTCM000068 | LTCMechanism | DE-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 434479 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LTCM000068 | LTCMechanism | DE-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LTCM000068 | LTCMechanism | DE-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LTCM000068 | LTCMechanism | DE-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LTCM000068 | LTCMechanism | DE-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LTCM000068 | LTCMechanism | DE-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LTCM000068 | LTCMechanism | DE-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 1391 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LTCM000068 | LTCMechanism | DE-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LTCM000068 | LTCMechanism | DE-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LTCM000068 | LTCMechanism | DE-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LTCM000068 | LTCMechanism | DE-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | CH000413 | ControlHouse | 786-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | CH000413 | ControlHouse | 786-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | CH000413 | ControlHouse | 786-Control House | Control House Patrol Inspection | Filters Condition OK? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | CH000413 | ControlHouse | 786-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | CH000413 | ControlHouse | 786-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | CH000413 | ControlHouse | 786-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | CH000413 | ControlHouse | 786-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | CH000413 | ControlHouse | 786-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | CH000413 | ControlHouse | 786-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | CH000413 | ControlHouse | 786-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | CH000413 | ControlHouse | 786-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | CH000413 | ControlHouse | 786-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | CH000413 | ControlHouse | 786-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1255 | BreakerVacuum | BY-1277 | VCB Readings | Amps B Ø | 189.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1255 | BreakerVacuum | BY-1277 | VCB Readings | Amps C Ø | 186.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1255 | BreakerVacuum | BY-1277 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1255 | BreakerVacuum | BY-1277 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1255 | BreakerVacuum | BY-1277 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1255 | BreakerVacuum | BY-1277 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000052 | Switchgear | BY-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000052 | Switchgear | BY-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000052 | Switchgear | BY-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000052 | Switchgear | BY-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000052 | Switchgear | BY-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000052 | Switchgear | BY-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000052 | Switchgear | BY-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000052 | Switchgear | BY-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000052 | Switchgear | BY-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000052 | Switchgear | BY-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000052 | Switchgear | BY-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000052 | Switchgear | BY-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000052 | Switchgear | BY-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000052 | Switchgear | BY-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000052 | Switchgear | BY-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000052 | Switchgear | BY-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000052 | Switchgear | BY-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000052 | Switchgear | BY-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000052 | Switchgear | BY-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | CH000169 | ControlHouse | BY-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | CH000169 | ControlHouse | BY-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | CH000169 | ControlHouse | BY-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | CH000169 | ControlHouse | BY-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | CH000169 | ControlHouse | BY-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | CH000169 | ControlHouse | BY-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1255 | BreakerVacuum | BY-1277 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1255 | BreakerVacuum | BY-1277 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1255 | BreakerVacuum | BY-1277 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1255 | BreakerVacuum | BY-1277 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1255 | BreakerVacuum | BY-1277 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1255 | BreakerVacuum | BY-1277 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1255 | BreakerVacuum | BY-1277 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1255 | BreakerVacuum | BY-1277 | VCB Readings | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1255 | BreakerVacuum | BY-1277 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1255 | BreakerVacuum | BY-1277 | VCB Readings | Operations Counter AF | 159 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1255 | BreakerVacuum | BY-1277 | VCB Readings | Operations Counter AL | 159 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1255 | BreakerVacuum | BY-1277 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1255 | BreakerVacuum | BY-1277 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1255 | BreakerVacuum | BY-1277 | VCB Readings | Unknown Operations | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BCH001132 | Charger | 072-Battery Charger Distribution | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 3.100 | millivolts |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | CH000169 | ControlHouse | BY-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | CH000169 | ControlHouse | BY-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | CH000169 | ControlHouse | BY-Control House | Control House Patrol Inspection | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | CH000169 | ControlHouse | BY-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | CH000169 | ControlHouse | BY-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | CH000169 | ControlHouse | BY-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | CH000169 | ControlHouse | BY-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | CH000169 | ControlHouse | BY-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | CH000169 | ControlHouse | BY-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | CH000169 | ControlHouse | BY-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | CH000169 | ControlHouse | BY-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | CH000169 | ControlHouse | BY-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | CH000169 | ControlHouse | BY-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Readings | LTC Totalizer Reading | 7246.80 | kw |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | General Comments | no pumps only fans | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Readings | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | FE000220 | Fence | 787-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | FE000220 | Fence | 787-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | FE000220 | Fence | 787-Fence | Fence Patrol Inspection | General Comments | | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | FE000220 | Fence | 787-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | FE000220 | Fence | 787-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | FE000220 | Fence | 787-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | FE000220 | Fence | 787-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | FE000220 | Fence | 787-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | FE000220 | Fence | 787-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | FE000220 | Fence | 787-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | FE000220 | Fence | 787-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | LR0019 | Regulator | 029-5 A | Regulator Patrol Inspection | Regulator As Left Counter | 7874 | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | LR0019 | Regulator | 029-5 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | LR0019 | Regulator | 029-5 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | LR0019 | Regulator | 029-5 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | LR0019 | Regulator | 029-5 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | FE000220 | Fence | 787-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | FE000220 | Fence | 787-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | FE000220 | Fence | 787-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | FE000220 | Fence | 787-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | FE000220 | Fence | 787-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Readings | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Readings | Operations Counter AF | 155 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | YD000220 | Yard | 787-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1018 | Regulator | 785-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1018 | Regulator | 785-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1018 | Regulator | 785-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1018 | Regulator | 785-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1018 | Regulator | 785-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 52959 | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1018 | Regulator | 785-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | YD000220 | Yard | 787-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | YD000220 | Yard | 787-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | YD000220 | Yard | 787-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | YD000220 | Yard | 787-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | YD000220 | Yard | 787-Yard | Yard Patrol Inspection | Ambient Temp | 62 | °F |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1018 | Regulator | 785-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1018 | Regulator | 785-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1018 | Regulator | 785-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1018 | Regulator | 785-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1018 | Regulator | 785-1 C | Regulator Patrol Inspection | Min Tap Position | Neutral | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1018 | Regulator | 785-1 C | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1018 | Regulator | 785-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1018 | Regulator | 785-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1018 | Regulator | 785-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1018 | Regulator | 785-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1018 | Regulator | 785-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1018 | Regulator | 785-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1018 | Regulator | 785-1 C | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1018 | Regulator | 785-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1018 | Regulator | 785-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1018 | Regulator | 785-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1018 | Regulator | 785-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | R1018 | Regulator | 785-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Readings | X3 Winding Temp Present | 24 | °C |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Readings | X3 Winding Temp Max | 24 | °C |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Readings | X2 Winding Temp Present | 24 | °C |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Readings | X2 Winding Temp Max | 24 | °C |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Readings | X1 Winding Temp Present | 24 | °C |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Readings | X1 Winding Temp Max | 24 | °C |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Readings | Totalizer Meter Reading | .4026 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Readings | Oil Temp Present | 19 | °C |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Readings | Oil Temp Max | 19 | °C |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000273 | WithLTC | 124-5 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1200 | psi |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Readings | Oil Temp Present | 29 | °C |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Readings | Oil Temp Max | 29 | °C |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1900 | psi |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Readings | LTC Totalizer Reading | 15192.00 | kw |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | General Comments | No pumps only fans. | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Readings | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | CH000449 | ControlHouse | 585-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | ST000372 | Structure | 891-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | ST000372 | Structure | 891-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | ST000372 | Structure | 891-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | ST000372 | Structure | 891-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | ST000372 | Structure | 891-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | ST000372 | Structure | 891-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | ST000372 | Structure | 891-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | ST000372 | Structure | 891-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | ST000372 | Structure | 891-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | ST000372 | Structure | 891-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | ST000372 | Structure | 891-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1197 | Regulator | 787-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1197 | Regulator | 787-1 C | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | CH000449 | ControlHouse | 585-Control House | Control House Patrol Inspection | General Comments | | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | CH000449 | ControlHouse | 585-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | CH000449 | ControlHouse | 585-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | CH000449 | ControlHouse | 585-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | CH000449 | ControlHouse | 585-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | CH000449 | ControlHouse | 585-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | CH000449 | ControlHouse | 585-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | CH000449 | ControlHouse | 585-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | CH000449 | ControlHouse | 585-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | CH000449 | ControlHouse | 585-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | CH000449 | ControlHouse | 585-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | CH000449 | ControlHouse | 585-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | CH000449 | ControlHouse | 585-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Readings | 9 Month Operations | 12 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Readings | 9 Month Operations VCB New | 12 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000006 | BreakerVacuum | 072-3406 | VCB Readings | Accumulated Fault Duty A Ph V | 20.15 | % |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1197 | Regulator | 787-1 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1197 | Regulator | 787-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1197 | Regulator | 787-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Readings | Operations Counter AL | 155 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Readings | Switching Operations | 1 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Readings | 9 Month Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Readings | Amps A Ø | 300.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Readings | Amps B Ø | 260.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Readings | Amps C Ø | 400.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000764 | BreakerVacuum | LS-1245 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | WithLTC | C-TRANS 4 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1197 | Regulator | 787-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1197 | Regulator | 787-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1197 | Regulator | 787-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1197 | Regulator | 787-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 109789 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1197 | Regulator | 787-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1197 | Regulator | 787-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1197 | Regulator | 787-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1197 | Regulator | 787-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | CH000449 | ControlHouse | 585-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | CH000449 | ControlHouse | 585-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | CH000449 | ControlHouse | 585-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | CH000449 | ControlHouse | 585-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | ST000372 | Structure | 891-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | ST000372 | Structure | 891-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | ST000372 | Structure | 891-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | ST000372 | Structure | 891-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | ST000372 | Structure | 891-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | ST000372 | Structure | 891-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | ST000372 | Structure | 891-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | ST000372 | Structure | 891-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | ST000372 | Structure | 891-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | ST000372 | Structure | 891-Structure | Structure Patrol Inspection | General Comments | | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | ST000372 | Structure | 891-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Readings | Winding Temp Present | 31 | °C |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Readings | Winding Temp Max | 31 | °C |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Readings | Totalizer Meter Reading | .8440 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | TX000272 | WithLTC | 124-6 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | CH000272 | ControlHouse | 072-Control House Distribution | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | CH000272 | ControlHouse | 072-Control House Distribution | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | CH000272 | ControlHouse | 072-Control House Distribution | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | CH000272 | ControlHouse | 072-Control House Distribution | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001044 | BreakerVacuum | C-1342 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Readings | General Comments | | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3324.00 | kw |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 140.00 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 135.00 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BCH000780 | Charger | 514-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 56.1 | VDC |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BCH000780 | Charger | 514-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 56.1 | VDC |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BCH000780 | Charger | 514-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BCH000780 | Charger | 514-Battery Charger | Battery Charger Patrol Insp | General Comments | Fiber cabinet needs replacing | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0175 | NonLTC | 891-1 A | NonLTC Transformer Readings | Totalizer Meter Reading | 1.3850 | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | LR0019 | Regulator | 029-5 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | LR0019 | Regulator | 029-5 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | ST000225 | Structure | 787-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | ST000225 | Structure | 787-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | ST000225 | Structure | 787-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | ST000225 | Structure | 787-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001045 | BreakerVacuum | C-1346 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Readings | Operations Counter AL | 358 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Readings | Operations Counter AF | 358 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Readings | General Comments | | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Readings | Amps C Ø | 120.0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Readings | Amps B Ø | 180.0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Readings | Amps A Ø | 120.0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0235 | BreakerVacuum | 441-0727 | VCB Readings | 9 Month Operations | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | CH000272 | ControlHouse | 072-Control House Distribution | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | CH000272 | ControlHouse | 072-Control House Distribution | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | CH000272 | ControlHouse | 072-Control House Distribution | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | CH000272 | ControlHouse | 072-Control House Distribution | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | CH000272 | ControlHouse | 072-Control House Distribution | Control House Patrol Inspection | Door Alarms OK? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | CH000272 | ControlHouse | 072-Control House Distribution | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | CH000272 | ControlHouse | 072-Control House Distribution | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | CH000272 | ControlHouse | 072-Control House Distribution | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | CH000272 | ControlHouse | 072-Control House Distribution | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | CH000272 | ControlHouse | 072-Control House Distribution | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | LR0019 | Regulator | 029-5 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000118 | LTCMechanism | 124-6 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000118 | LTCMechanism | 124-6 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000118 | LTCMechanism | 124-6 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000118 | LTCMechanism | 124-6 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000118 | LTCMechanism | 124-6 | LTC Counter Readings | LTC Operations Since Last Insp | 913 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000118 | LTCMechanism | 124-6 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 23 | °C |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000118 | LTCMechanism | 124-6 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 23 | °C |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000118 | LTCMechanism | 124-6 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000118 | LTCMechanism | 124-6 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000118 | LTCMechanism | 124-6 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000118 | LTCMechanism | 124-6 | LTC Counter Readings | LTC Max Tap Position | 9R | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000118 | LTCMechanism | 124-6 | LTC Counter Readings | LTC Current Tap Position | 4R | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000118 | LTCMechanism | 124-6 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000118 | LTCMechanism | 124-6 | LTC Counter Readings | LTC As Left Counter | 8913 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000118 | LTCMechanism | 124-6 | LTC Counter Readings | LTC As Found Counter | 8902 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000118 | LTCMechanism | 124-6 | LTC Mechanism Patrol Inspection | General Comments | . | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000118 | LTCMechanism | 124-6 | LTC Counter Readings | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000118 | LTCMechanism | 124-6 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000118 | LTCMechanism | 124-6 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | LR0019 | Regulator | 029-5 A | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | LR0019 | Regulator | 029-5 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | LR0019 | Regulator | 029-5 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | LR0019 | Regulator | 029-5 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | LR0019 | Regulator | 029-5 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | LR0019 | Regulator | 029-5 A | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | LR0019 | Regulator | 029-5 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | LR0019 | Regulator | 029-5 A | Regulator Patrol Inspection | Max Tap Position | 9R | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | LR0019 | Regulator | 029-5 A | Regulator Patrol Inspection | Min Tap Position | 3L | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | LR0019 | Regulator | 029-5 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | LR0019 | Regulator | 029-5 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | LR0019 | Regulator | 029-5 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | LR0019 | Regulator | 029-5 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | LR0019 | Regulator | 029-5 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Readings | 9 Month Operations | 2 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Readings | Amps A Ø | 390.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Readings | Amps B Ø | 370.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Readings | Amps C Ø | 400.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000763 | BreakerVacuum | LS-12KV TR 3 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCC000899 | LTCControl | 124-6 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCC000899 | LTCControl | 124-6 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCC000899 | LTCControl | 124-6 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCC000899 | LTCControl | 124-6 | LTC Control Insp | LTC Output Voltage Level | 124.5 | VAC |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCC000899 | LTCControl | 124-6 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCC000899 | LTCControl | 124-6 | LTC Control Insp | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCC000899 | LTCControl | 124-6 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCC000899 | LTCControl | 124-6 | LTC Control Insp | All Connections OK? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | YD000220 | Yard | 787-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | YD000220 | Yard | 787-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | YD000220 | Yard | 787-Yard | Yard Patrol Inspection | General Comments | | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | YD000220 | Yard | 787-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | YD000220 | Yard | 787-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | YD000220 | Yard | 787-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | YD000220 | Yard | 787-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | ST000225 | Structure | 787-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | ST000225 | Structure | 787-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | ST000225 | Structure | 787-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | ST000225 | Structure | 787-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | ST000225 | Structure | 787-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | ST000225 | Structure | 787-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000007 | Switchgear | ET-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000007 | Switchgear | ET-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000007 | Switchgear | ET-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000007 | Switchgear | ET-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000007 | Switchgear | ET-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000007 | Switchgear | ET-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000007 | Switchgear | ET-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000007 | Switchgear | ET-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000007 | Switchgear | ET-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000007 | Switchgear | ET-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000007 | Switchgear | ET-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000007 | Switchgear | ET-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000007 | Switchgear | ET-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000007 | Switchgear | ET-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000007 | Switchgear | ET-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000007 | Switchgear | ET-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000007 | Switchgear | ET-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000119 | LTCMechanism | 124-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000119 | LTCMechanism | 124-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000119 | LTCMechanism | 124-5 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000119 | LTCMechanism | 124-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000119 | LTCMechanism | 124-5 | LTC Counter Readings | LTC Operations Since Last Insp | 897 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000119 | LTCMechanism | 124-5 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 19 | °C |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000119 | LTCMechanism | 124-5 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 19 | °C |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000119 | LTCMechanism | 124-5 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000119 | LTCMechanism | 124-5 | LTC Counter Readings | LTC Max Tap Position | 9R | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000119 | LTCMechanism | 124-5 | LTC Counter Readings | LTC Current Tap Position | 3R | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000119 | LTCMechanism | 124-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000119 | LTCMechanism | 124-5 | LTC Counter Readings | LTC As Left Counter | 8993 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000119 | LTCMechanism | 124-5 | LTC Counter Readings | LTC As Found Counter | 8984 | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000119 | LTCMechanism | 124-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000119 | LTCMechanism | 124-5 | LTC Counter Readings | General Comments | | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000119 | LTCMechanism | 124-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:08 | Distribution | Middlesboro 1 Quarterly Inspection | LTCM000119 | LTCMechanism | 124-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000007 | Switchgear | ET-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000007 | Switchgear | ET-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | ST000225 | Structure | 787-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | ST000225 | Structure | 787-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | ST000225 | Structure | 787-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | ST000225 | Structure | 787-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | ST000225 | Structure | 787-Structure | Structure Patrol Inspection | General Comments | | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | ST000225 | Structure | 787-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | ST000225 | Structure | 787-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | ST000225 | Structure | 787-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | ST000225 | Structure | 787-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | ST000225 | Structure | 787-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | ST000225 | Structure | 787-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | ST000225 | Structure | 787-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | ST000225 | Structure | 787-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | ST000225 | Structure | 787-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | YD000220 | Yard | 787-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | LR0019 | Regulator | 029-5 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | LR0019 | Regulator | 029-5 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000222 | Regulator | 492-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000222 | Regulator | 492-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000222 | Regulator | 492-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000222 | Regulator | 492-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000222 | Regulator | 492-1 A | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000222 | Regulator | 492-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000222 | Regulator | 492-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000222 | Regulator | 492-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000222 | Regulator | 492-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000222 | Regulator | 492-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 800 | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .7902 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000221 | Regulator | 492-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000221 | Regulator | 492-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000221 | Regulator | 492-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000221 | Regulator | 492-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000221 | Regulator | 492-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 4023 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000221 | Regulator | 492-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.3 | volts |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000221 | Regulator | 492-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000221 | Regulator | 492-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000221 | Regulator | 492-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000221 | Regulator | 492-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000221 | Regulator | 492-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000221 | Regulator | 492-1 B | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000221 | Regulator | 492-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000221 | Regulator | 492-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000221 | Regulator | 492-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000221 | Regulator | 492-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000221 | Regulator | 492-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000221 | Regulator | 492-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000221 | Regulator | 492-1 B | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000221 | Regulator | 492-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000221 | Regulator | 492-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000221 | Regulator | 492-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000221 | Regulator | 492-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000221 | Regulator | 492-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LTCC000532 | LTCControl | C-TRANS 4 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LTCC000532 | LTCControl | C-TRANS 4 | LTC Control Insp | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LTCC000532 | LTCControl | C-TRANS 4 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | YD000413 | Yard | 600-Yard | Yard Patrol Inspection | Ambient Temp | 51 | °F |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | YD000413 | Yard | 600-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | YD000413 | Yard | 600-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | YD000413 | Yard | 600-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | YD000413 | Yard | 600-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | YD000413 | Yard | 600-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | YD000413 | Yard | 600-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | YD000413 | Yard | 600-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | YD000413 | Yard | 600-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | YD000413 | Yard | 600-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | YD000413 | Yard | 600-Yard | Yard Patrol Inspection | General Comments | | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | YD000413 | Yard | 600-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | YD000413 | Yard | 600-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | YD000413 | Yard | 600-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | YD000413 | Yard | 600-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000220 | Regulator | 492-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | LTCMechanism | BY-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | LTCMechanism | BY-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | LTCMechanism | BY-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | LTCMechanism | BY-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 433 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | LTCMechanism | BY-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | LTCMechanism | BY-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | LTCMechanism | BY-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | LTCMechanism | BY-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | LTCMechanism | BY-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 141715 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | LTCMechanism | BY-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 141715 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | LTCMechanism | BY-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | LTCMechanism | BY-TRANS 1 | LTC Counter Readings | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | LTCMechanism | BY-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | LTCMechanism | BY-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Readings | 9 Month Operations | 1 | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Readings | General Comments | | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 632.16 | kw |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | B0249 | NonLTC | 718-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000222 | Regulator | 492-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000222 | Regulator | 492-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000222 | Regulator | 492-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000222 | Regulator | 492-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000222 | Regulator | 492-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 3809 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000222 | Regulator | 492-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.3 | volts |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000222 | Regulator | 492-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000222 | Regulator | 492-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000222 | Regulator | 492-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000222 | Regulator | 492-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000222 | Regulator | 492-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000222 | Regulator | 492-1 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000222 | Regulator | 492-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000222 | Regulator | 492-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0077 | BreakerVacuum | BY-1283 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0077 | BreakerVacuum | BY-1283 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0077 | BreakerVacuum | BY-1283 | VCB Readings | Operations This Read Vac | 7 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0077 | BreakerVacuum | BY-1283 | VCB Readings | Operations Counter AL | 69 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0077 | BreakerVacuum | BY-1283 | VCB Readings | Operations Counter AF | 69 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0077 | BreakerVacuum | BY-1283 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0077 | BreakerVacuum | BY-1283 | VCB Readings | General Comments | a,b ioc | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0077 | BreakerVacuum | BY-1283 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0077 | BreakerVacuum | BY-1283 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0077 | BreakerVacuum | BY-1283 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0077 | BreakerVacuum | BY-1283 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0077 | BreakerVacuum | BY-1283 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0077 | BreakerVacuum | BY-1283 | VCB Readings | Fault Operations B Ø | 3 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0077 | BreakerVacuum | BY-1283 | VCB Readings | Fault Operations A Ø | 4 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0077 | BreakerVacuum | BY-1283 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0077 | BreakerVacuum | BY-1283 | VCB Readings | Fault Adjusted Amps B Phase V | 33.54 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0077 | BreakerVacuum | BY-1283 | VCB Readings | Fault Adjusted Amps A Phase V | 44.72 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0077 | BreakerVacuum | BY-1283 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0077 | BreakerVacuum | BY-1283 | VCB Readings | Amps C Ø | 380.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0077 | BreakerVacuum | BY-1283 | VCB Readings | Amps B Ø | 360.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0077 | BreakerVacuum | BY-1283 | VCB Readings | Amps A Ø | 330.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0077 | BreakerVacuum | BY-1283 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0077 | BreakerVacuum | BY-1283 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0077 | BreakerVacuum | BY-1283 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0077 | BreakerVacuum | BY-1283 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0077 | BreakerVacuum | BY-1283 | VCB Readings | 9 Month Operations | 10 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Readings | 9 Month Operations | 3 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Readings | Amps A Ø | 23.0 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Readings | Amps B Ø | 30.0 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Readings | Amps C Ø | 30.0 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Readings | General Comments | | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Readings | Maintenance Operations | 2 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Readings | Operations Counter AF | 186 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000220 | Regulator | 492-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000220 | Regulator | 492-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000220 | Regulator | 492-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000220 | Regulator | 492-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 3923 | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000220 | Regulator | 492-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.2 | volts |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000220 | Regulator | 492-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000220 | Regulator | 492-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000220 | Regulator | 492-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000220 | Regulator | 492-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000220 | Regulator | 492-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000220 | Regulator | 492-1 C | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000220 | Regulator | 492-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000220 | Regulator | 492-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000220 | Regulator | 492-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000220 | Regulator | 492-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000220 | Regulator | 492-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000220 | Regulator | 492-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000220 | Regulator | 492-1 C | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000220 | Regulator | 492-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000220 | Regulator | 492-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000220 | Regulator | 492-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000220 | Regulator | 492-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | RG000220 | Regulator | 492-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Readings | General Comments | | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.2 | psi |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 5232.96 | kw |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | S0025 | NonLTC | 888-2 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.0902 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Readings | Operations This Read Vac | 6 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Readings | Operations Counter AL | 66 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Readings | Operations Counter AF | 66 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Readings | Maintenance Operations | 6 | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Readings | General Comments | | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Readings | General Comments | | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Patrol Inspection | General Comments | no nitrogen to add to transformer | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001054 | BreakerVacuum | ET-12KV TR 6 | VCB Readings | Switching Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 694.08 | kw |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001054 | BreakerVacuum | ET-12KV TR 6 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001054 | BreakerVacuum | ET-12KV TR 6 | VCB Readings | Operations Counter AL | 49 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001054 | BreakerVacuum | ET-12KV TR 6 | VCB Readings | Operations Counter AF | 49 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001054 | BreakerVacuum | ET-12KV TR 6 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001054 | BreakerVacuum | ET-12KV TR 6 | VCB Readings | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001054 | BreakerVacuum | ET-12KV TR 6 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001054 | BreakerVacuum | ET-12KV TR 6 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001054 | BreakerVacuum | ET-12KV TR 6 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001054 | BreakerVacuum | ET-12KV TR 6 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001054 | BreakerVacuum | ET-12KV TR 6 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001054 | BreakerVacuum | ET-12KV TR 6 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001054 | BreakerVacuum | ET-12KV TR 6 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001054 | BreakerVacuum | ET-12KV TR 6 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001054 | BreakerVacuum | ET-12KV TR 6 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001054 | BreakerVacuum | ET-12KV TR 6 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001054 | BreakerVacuum | ET-12KV TR 6 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001054 | BreakerVacuum | ET-12KV TR 6 | VCB Readings | Amps C Ø | 376.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001054 | BreakerVacuum | ET-12KV TR 6 | VCB Readings | Amps B Ø | 420.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001054 | BreakerVacuum | ET-12KV TR 6 | VCB Readings | Amps A Ø | 456.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001054 | BreakerVacuum | ET-12KV TR 6 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001054 | BreakerVacuum | ET-12KV TR 6 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001054 | BreakerVacuum | ET-12KV TR 6 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001054 | BreakerVacuum | ET-12KV TR 6 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001054 | BreakerVacuum | ET-12KV TR 6 | VCB Readings | 9 Month Operations | 1 | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Readings | Oil Temp Max | 39 | °C |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Readings | Oil Temp Present | 24 | °C |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF000119 | PowerFuse | ET-STA SER NO 2 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF000119 | PowerFuse | ET-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF000119 | PowerFuse | ET-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001055 | BreakerVacuum | ET-12KV BUS TIE SEC 6 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001055 | BreakerVacuum | ET-12KV BUS TIE SEC 6 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001055 | BreakerVacuum | ET-12KV BUS TIE SEC 6 | VCB Readings | Operations Counter AL | 54 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001055 | BreakerVacuum | ET-12KV BUS TIE SEC 6 | VCB Readings | Operations Counter AF | 54 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001055 | BreakerVacuum | ET-12KV BUS TIE SEC 6 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001055 | BreakerVacuum | ET-12KV BUS TIE SEC 6 | VCB Readings | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001055 | BreakerVacuum | ET-12KV BUS TIE SEC 6 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001055 | BreakerVacuum | ET-12KV BUS TIE SEC 6 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001055 | BreakerVacuum | ET-12KV BUS TIE SEC 6 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | WithLTC | C-TRANS 3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Readings | 9 Month Operations | 2 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Readings | Amps A Ø | 0.0 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Readings | Amps B Ø | 0.0 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Readings | Amps C Ø | 0.0 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001055 | BreakerVacuum | ET-12KV BUS TIE SEC 6 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001055 | BreakerVacuum | ET-12KV BUS TIE SEC 6 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001055 | BreakerVacuum | ET-12KV BUS TIE SEC 6 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001055 | BreakerVacuum | ET-12KV BUS TIE SEC 6 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001055 | BreakerVacuum | ET-12KV BUS TIE SEC 6 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001055 | BreakerVacuum | ET-12KV BUS TIE SEC 6 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001055 | BreakerVacuum | ET-12KV BUS TIE SEC 6 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001055 | BreakerVacuum | ET-12KV BUS TIE SEC 6 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001055 | BreakerVacuum | ET-12KV BUS TIE SEC 6 | VCB Readings | Amps C Ø | 0.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001055 | BreakerVacuum | ET-12KV BUS TIE SEC 6 | VCB Readings | Amps B Ø | 0.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001055 | BreakerVacuum | ET-12KV BUS TIE SEC 6 | VCB Readings | Amps A Ø | 0.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001055 | BreakerVacuum | ET-12KV BUS TIE SEC 6 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001055 | BreakerVacuum | ET-12KV BUS TIE SEC 6 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001055 | BreakerVacuum | ET-12KV BUS TIE SEC 6 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001055 | BreakerVacuum | ET-12KV BUS TIE SEC 6 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK001055 | BreakerVacuum | ET-12KV BUS TIE SEC 6 | VCB Readings | 9 Month Operations | 3 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 750 | psi |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 95.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Readings | Oil Temp Max | 34 | °C |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Readings | Oil Temp Present | 24 | °C |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Readings | TV Winding Temp Max | 35 | °C |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Readings | TV Winding Temp Present | 27 | °C |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Readings | Winding Temp Max | 35 | °C |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Readings | Winding Temp Present | 21 | °C |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | BCH000109 | Charger | BY-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | BCH000109 | Charger | BY-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.0 | VDC |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | BCH000109 | Charger | BY-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.0 | VDC |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | BCH000109 | Charger | BY-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.2 | amps |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | BCH000109 | Charger | BY-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | BCH000109 | Charger | BY-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | BCH000109 | Charger | BY-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | BCH000109 | Charger | BY-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Readings | Operations Counter AL | 146 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Readings | Operations Counter AF | 145 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Readings | Maintenance Operations | 1 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Readings | General Comments | | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | LTCMechanism | BY-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Readings | Amps C Ø | 120.0 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Readings | Amps B Ø | 105.0 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Readings | Amps A Ø | 100.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0104 | BreakerVacuum | 787-1472 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | M0087 | NonLTC | 890-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .2892 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Readings | Operations Counter AF | 214 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Readings | Operations Counter AL | 216 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Readings | Operations This Read Vac | 2 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | ST000408 | Structure | 585-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | ST000408 | Structure | 585-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | ST000408 | Structure | 585-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | ST000408 | Structure | 585-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | ST000408 | Structure | 585-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | ST000408 | Structure | 585-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | ST000408 | Structure | 585-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | ST000408 | Structure | 585-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | ST000408 | Structure | 585-Structure | Structure Patrol Inspection | General Comments | | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | ST000408 | Structure | 585-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | ST000408 | Structure | 585-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | ST000408 | Structure | 585-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | ST000408 | Structure | 585-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | ST000408 | Structure | 585-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | ST000408 | Structure | 585-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | ST000408 | Structure | 585-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | ST000408 | Structure | 585-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | ST000408 | Structure | 585-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | ST000408 | Structure | 585-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | ST000408 | Structure | 585-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | ST000408 | Structure | 585-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Readings | Switching Operations | 2 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | KB0107 | BreakerVacuum | 559-0871 | VCB Readings | Unknown Operations | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF000118 | PowerFuse | ET-12KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF000118 | PowerFuse | ET-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF000118 | PowerFuse | ET-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Readings | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Readings | HV Winding Temp Max | 35 | °C |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Readings | HV Winding Temp Present | 21 | °C |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Readings | LV Winding Temp Max | 41 | °C |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Readings | LV Winding Temp Present | 37 | °C |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | T0341 | NonLTC | 072-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0251 | GroundTransformer | DE-GND TR 1 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0251 | GroundTransformer | DE-GND TR 1 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0251 | GroundTransformer | DE-GND TR 1 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0251 | GroundTransformer | DE-GND TR 1 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0251 | GroundTransformer | DE-GND TR 1 | Ground Transformer Patrol Inspection | General Comments | | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0251 | GroundTransformer | DE-GND TR 1 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0251 | GroundTransformer | DE-GND TR 1 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.6 | psi |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0251 | GroundTransformer | DE-GND TR 1 | Ground Transformer Patrol Inspection | Oil Temp Max | 35 | °C |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0251 | GroundTransformer | DE-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0251 | GroundTransformer | DE-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0251 | GroundTransformer | DE-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0251 | GroundTransformer | DE-GND TR 1 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0251 | GroundTransformer | DE-GND TR 1 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0251 | GroundTransformer | DE-GND TR 1 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Readings | 9 Month Operations VCB New | 14 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Readings | 9 Month Operations | 23 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BCH001074 | Charger | FL-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BCH001074 | Charger | FL-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BCH001074 | Charger | FL-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BCH001074 | Charger | FL-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BCH001074 | Charger | FL-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.0 | amps |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BCH001074 | Charger | FL-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.9 | VDC |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Readings | General Comments | | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BCH001074 | Charger | FL-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.9 | VDC |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BCH001074 | Charger | FL-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Readings | Amps C Ø | 120.0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Readings | Amps B Ø | 120.0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Readings | Amps A Ø | 120.0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Readings | 9 Month Operations | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BAT001492 | Battery | 724-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BAT001492 | Battery | 724-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 67 | °F |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Readings | 9 Month Operations VCB New | 23 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Readings | 9 Month Operations | 32 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Readings | Unknown Operations | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Readings | Switching Operations | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Readings | Operations This Read Vac | 9 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Readings | Operations Counter AL | 23 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Readings | Operations Counter AF | 23 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Readings | Maintenance Operations | 9 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Patrol Inspection | General Comments | Roll in breaker, please adjust insp | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Readings | General Comments | | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BAT000092 | Battery | FL-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BAT000092 | Battery | FL-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BAT000092 | Battery | FL-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BAT000092 | Battery | FL-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BAT000092 | Battery | FL-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BAT000092 | Battery | FL-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BAT000092 | Battery | FL-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BAT000092 | Battery | FL-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BAT000092 | Battery | FL-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BAT000092 | Battery | FL-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BAT000092 | Battery | FL-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | BAT000092 | Battery | FL-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Readings | Switching Operations | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Readings | Amps C Ø | 226.0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Readings | Amps B Ø | 218.0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002184 | BreakerVacuum | DE-1407 | VCB Readings | Amps A Ø | 225.0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Readings | Operations Counter AL | 117 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Readings | Operations Counter AF | 117 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | BB0293 | BreakerVacuum | 441-0734 | VCB Readings | Maintenance Operations | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0251 | GroundTransformer | DE-GND TR 1 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | LT0251 | GroundTransformer | DE-GND TR 1 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Readings | General Comments | | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Readings | Operations This Read Vac | 15 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Readings | Operations Counter AL | 22 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Readings | Operations Counter AF | 22 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Readings | Maintenance Operations | 15 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Patrol Inspection | General Comments | Roll in breaker, please adjust insp | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Readings | General Comments | | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Readings | Amps C Ø | 15.0 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Readings | Amps B Ø | 15.0 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Readings | Amps A Ø | 40.0 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Readings | 9 Month Operations | 1 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Readings | Amps C Ø | 92.0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Readings | Amps B Ø | 90.0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Readings | Amps A Ø | 92.0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BAT001492 | Battery | 724-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BAT001492 | Battery | 724-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BAT001492 | Battery | 724-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BAT001492 | Battery | 724-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BAT001492 | Battery | 724-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BAT001492 | Battery | 724-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BAT001492 | Battery | 724-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BAT001492 | Battery | 724-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BAT001492 | Battery | 724-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BAT001492 | Battery | 724-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BAT001492 | Battery | 724-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | BAT000519 | Battery | 891-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | BAT000519 | Battery | 891-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 38 | °F |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | BAT000519 | Battery | 891-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | BAT000519 | Battery | 891-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | BAT000519 | Battery | 891-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BCH001423 | Charger | 724-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BCH001423 | Charger | 724-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BCH001423 | Charger | 724-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BCH001423 | Charger | 724-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 5.6 | amps |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BCH001423 | Charger | 724-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BCH001423 | Charger | 724-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BCH001423 | Charger | 724-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BCH001423 | Charger | 724-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | LTCMechanism | ET-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | LTCMechanism | ET-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | High | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | LTCMechanism | ET-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 10 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | LTCMechanism | ET-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 6 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | LTCMechanism | ET-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | LTCMechanism | ET-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 46826 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | LTCMechanism | ET-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 46826 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | LTCMechanism | ET-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | LTC oil high | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | LTCMechanism | ET-TRANS 1 | LTC Counter Readings | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | LTCMechanism | ET-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | LTCMechanism | ET-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | BAT000519 | Battery | 891-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | BAT000519 | Battery | 891-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | BAT000519 | Battery | 891-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | BAT000519 | Battery | 891-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | BAT000519 | Battery | 891-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | BAT000519 | Battery | 891-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | BAT000519 | Battery | 891-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | BAT000519 | Battery | 891-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | BAT000519 | Battery | 891-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | BAT000519 | Battery | 891-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Readings | Operations Counter AL | 41 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Readings | Operations Counter AF | 41 | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Readings | Maintenance Operations | 1 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Readings | Switching Operations | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002183 | BreakerVacuum | DE-1406 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | WB0147 | BreakerVacuum | 640-1468 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 900 | psi |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Readings | Percent Thermal Load X2 Max | 120 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000611 | RecloserElectronic | 891-0719 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000611 | RecloserElectronic | 891-0719 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000611 | RecloserElectronic | 891-0719 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000611 | RecloserElectronic | 891-0719 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | n | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000611 | RecloserElectronic | 891-0719 | Recloser Electronic Patrol Inspection | Amps C Ø | 65.0 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000611 | RecloserElectronic | 891-0719 | Recloser Electronic Patrol Inspection | Amps B Ø | 60.0 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000611 | RecloserElectronic | 891-0719 | Recloser Electronic Patrol Inspection | Amps A Ø | 68.0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Readings | Unknown Operations | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Readings | Switching Operations | 2 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Readings | Operations This Read Vac | 4 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Readings | Operations Counter AL | 24 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Readings | Operations Counter AF | 24 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Readings | Maintenance Operations | 2 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Patrol Inspection | General Comments | Roll in breaker, please adjust insp | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Readings | General Comments | | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Readings | Amps C Ø | 0.0 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Readings | Operations Counter AL | 186 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Readings | Operations This Read Vac | 2 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BK001143 | BreakerVacuum | 613-1443 | VCB Readings | Unknown Operations | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Patrol Inspection | General Comments | Roll in breaker, please adjust insp | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Readings | General Comments | | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Readings | Amps C Ø | 450.0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Readings | Amps B Ø | 454.0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Readings | Amps A Ø | 460.0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002200 | BreakerVacuum | DE-14KV TR 1 | VCB Readings | 9 Month Operations | 16 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000611 | RecloserElectronic | 891-0719 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000611 | RecloserElectronic | 891-0719 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000611 | RecloserElectronic | 891-0719 | Recloser Electronic Patrol Inspection | Operations Counter | 88 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000611 | RecloserElectronic | 891-0719 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000611 | RecloserElectronic | 891-0719 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000611 | RecloserElectronic | 891-0719 | Recloser Electronic Patrol Inspection | General Comments | | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000611 | RecloserElectronic | 891-0719 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000611 | RecloserElectronic | 891-0719 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000611 | RecloserElectronic | 891-0719 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000611 | RecloserElectronic | 891-0719 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000611 | RecloserElectronic | 891-0719 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0066 | WithLTC | ET-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Readings | Amps C Ø | 10.0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Readings | Amps B Ø | 11.0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Readings | Amps A Ø | 11.0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Readings | 9 Month Operations | 47 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Readings | Unknown Operations | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Readings | Switching Operations | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Readings | Operations This Read Vac | 9 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Readings | Operations Counter AL | 32 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Readings | Operations Counter AF | 32 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Readings | Maintenance Operations | 9 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Patrol Inspection | General Comments | Roll in breaker, please adjust insp | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Readings | Amps C Ø | 108.0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Readings | Amps B Ø | 115.0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Readings | Amps A Ø | 112.0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002185 | BreakerVacuum | DE-1408 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Readings | Amps B Ø | 0.0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Readings | Amps A Ø | 0.0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002188 | BreakerVacuum | DE-GND TR 1 | VCB Readings | 9 Month Operations | 14 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Readings | Unknown Operations | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Readings | Switching Operations | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Readings | Operations This Read Vac | 21 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Readings | Operations Counter AL | 21 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Readings | Operations Counter AF | 100 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Readings | Maintenance Operations | 21 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Patrol Inspection | General Comments | Roll in breaker, please adjust insp | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Readings | General Comments | | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Patrol Inspection | Follow-up Action Required? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Readings | Amps C Ø | 74.0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Readings | Amps B Ø | 82.0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Readings | Amps A Ø | 78.0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Readings | 9 Month Operations VCB New | 79 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002187 | BreakerVacuum | DE-1410 | VCB Readings | 9 Month Operations | 100 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Readings | Unknown Operations | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Readings | Switching Operations | 0 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Readings | Operations This Read Vac | 37 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Readings | Operations Counter AL | 47 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Readings | Operations Counter AF | 47 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Readings | Maintenance Operations | 37 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Patrol Inspection | General Comments | Roll in breaker, please adjust insp | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Readings | General Comments | | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BK002186 | BreakerVacuum | DE-1409 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | KR0044 | Regulator | 785-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | KR0044 | Regulator | 785-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | KR0044 | Regulator | 785-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | KR0044 | Regulator | 785-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 12454 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BAT001068 | Battery | 786-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BAT001068 | Battery | 786-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BAT001068 | Battery | 786-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 25.9 | VDC |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001190 | BreakerVacuum | C-14KV BUS TIE | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0079 | BreakerVacuum | BY-1285 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0079 | BreakerVacuum | BY-1285 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0079 | BreakerVacuum | BY-1285 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0079 | BreakerVacuum | BY-1285 | VCB Readings | Operations Counter AL | 53 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0079 | BreakerVacuum | BY-1285 | VCB Readings | Operations Counter AF | 53 | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | KR0044 | Regulator | 785-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | KR0044 | Regulator | 785-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | KR0044 | Regulator | 785-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | KR0044 | Regulator | 785-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | KR0044 | Regulator | 785-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | KR0044 | Regulator | 785-1 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | KR0044 | Regulator | 785-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | KR0044 | Regulator | 785-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | KR0044 | Regulator | 785-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | KR0044 | Regulator | 785-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | KR0044 | Regulator | 785-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | KR0044 | Regulator | 785-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | KR0044 | Regulator | 785-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | KR0044 | Regulator | 785-1 A | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | KR0044 | Regulator | 785-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | KR0044 | Regulator | 785-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0079 | BreakerVacuum | BY-1285 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0079 | BreakerVacuum | BY-1285 | VCB Readings | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0079 | BreakerVacuum | BY-1285 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0079 | BreakerVacuum | BY-1285 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0079 | BreakerVacuum | BY-1285 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0079 | BreakerVacuum | BY-1285 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0079 | BreakerVacuum | BY-1285 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0079 | BreakerVacuum | BY-1285 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0079 | BreakerVacuum | BY-1285 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0079 | BreakerVacuum | BY-1285 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0079 | BreakerVacuum | BY-1285 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0079 | BreakerVacuum | BY-1285 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0079 | BreakerVacuum | BY-1285 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0079 | BreakerVacuum | BY-1285 | VCB Readings | Amps C Ø | 150.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0079 | BreakerVacuum | BY-1285 | VCB Readings | Amps B Ø | 150.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0079 | BreakerVacuum | BY-1285 | VCB Readings | Amps A Ø | 150.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0079 | BreakerVacuum | BY-1285 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0079 | BreakerVacuum | BY-1285 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0079 | BreakerVacuum | BY-1285 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0079 | BreakerVacuum | BY-1285 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0079 | BreakerVacuum | BY-1285 | VCB Readings | 9 Month Operations | 3 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | FE000629 | Fence | BY-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | FE000629 | Fence | BY-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | FE000629 | Fence | BY-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | FE000629 | Fence | BY-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | FE000629 | Fence | BY-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | FE000629 | Fence | BY-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | FE000629 | Fence | BY-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | FE000629 | Fence | BY-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | FE000629 | Fence | BY-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | FE000629 | Fence | BY-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | FE000629 | Fence | BY-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | FE000629 | Fence | BY-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | FE000629 | Fence | BY-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1135 | Regulator | 012-5 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1135 | Regulator | 012-5 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1135 | Regulator | 012-5 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1135 | Regulator | 012-5 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1135 | Regulator | 012-5 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1135 | Regulator | 012-5 C | Regulator Patrol Inspection | Regulator As Left Counter | 72903 | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1135 | Regulator | 012-5 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1135 | Regulator | 012-5 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1135 | Regulator | 012-5 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | LTCC000033 | LTCControl | 888-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | LTCC000033 | LTCControl | 888-1 | LTC Control Insp | VRR Base Voltage AL | 121.5 | VAC |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | LTCC000033 | LTCControl | 888-1 | LTC Control Insp | VRR Base Voltage AF | 121.5 | VAC |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | LTCC000033 | LTCControl | 888-1 | LTC Control Insp | LTC Output Voltage Level | 121.2 | VAC |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | LTCC000033 | LTCControl | 888-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | LTCC000033 | LTCControl | 888-1 | LTC Control Insp | General Comments | | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | LTCC000033 | LTCControl | 888-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | LTCC000033 | LTCControl | 888-1 | LTC Control Insp | All Connections OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | SWG000080 | Switchgear | DE-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | SWG000080 | Switchgear | DE-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | SWG000080 | Switchgear | DE-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | SWG000080 | Switchgear | DE-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | SWG000080 | Switchgear | DE-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | SWG000080 | Switchgear | DE-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | SWG000080 | Switchgear | DE-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | SWG000080 | Switchgear | DE-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | SWG000080 | Switchgear | DE-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | SWG000080 | Switchgear | DE-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | SWG000080 | Switchgear | DE-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001393 | BreakerVacuum | C-1343 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MR0086 | Regulator | 517-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MR0086 | Regulator | 517-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MR0086 | Regulator | 517-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MR0086 | Regulator | 517-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.1 | volts |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MR0086 | Regulator | 517-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MR0086 | Regulator | 517-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MR0086 | Regulator | 517-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MR0086 | Regulator | 517-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MR0086 | Regulator | 517-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MR0086 | Regulator | 517-1 C | Regulator Patrol Inspection | Max Tap Position | 4L | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MR0086 | Regulator | 517-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MR0086 | Regulator | 517-1 C | Regulator Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MR0086 | Regulator | 517-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MR0086 | Regulator | 517-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MR0086 | Regulator | 517-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MR0086 | Regulator | 517-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MR0086 | Regulator | 517-1 C | Regulator Patrol Inspection | Current Tap Position | 13L | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MR0086 | Regulator | 517-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MR0086 | Regulator | 517-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MR0086 | Regulator | 517-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MR0086 | Regulator | 517-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MR0086 | Regulator | 517-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | KR0044 | Regulator | 785-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Readings | H2 Winding Temp Max | 35 | °C |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Readings | H2 Winding Temp Present | 30 | °C |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 4.0 | psi |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1150 | psi |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BAT001068 | Battery | 786-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BAT001068 | Battery | 786-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BAT001068 | Battery | 786-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BAT001068 | Battery | 786-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 35 | °C |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 32 | °C |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001189 | BreakerVacuum | C-1341 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BAT001068 | Battery | 786-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 40 | °C |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 35 | °C |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 37 | °C |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 35 | °C |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BAT001068 | Battery | 786-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Readings | 9 Month Operations | 1 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Readings | Amps A Ø | 4.0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Readings | Amps B Ø | 1.0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Readings | Amps C Ø | 7.0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Patrol Inspection | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Readings | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Readings | Maintenance Operations | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Readings | Operations Counter AF | 302 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Readings | Operations Counter AL | 302 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | FE000629 | Fence | BY-Fence | Fence Patrol Inspection | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | FE000629 | Fence | BY-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | FE000629 | Fence | BY-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | YD000631 | Yard | BY-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | YD000631 | Yard | BY-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | YD000631 | Yard | BY-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | YD000631 | Yard | BY-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | YD000631 | Yard | BY-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | YD000631 | Yard | BY-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | YD000631 | Yard | BY-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | YD000631 | Yard | BY-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | YD000631 | Yard | BY-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | YD000631 | Yard | BY-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | YD000631 | Yard | BY-Yard | Yard Patrol Inspection | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | YD000631 | Yard | BY-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | YD000631 | Yard | BY-Yard | Yard Patrol Inspection | Oil stop valve operational? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | YD000631 | Yard | BY-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | YD000631 | Yard | BY-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | YD000631 | Yard | BY-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | YD000631 | Yard | BY-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | YD000631 | Yard | BY-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | YD000631 | Yard | BY-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | ST000614 | Structure | BY-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | ST000614 | Structure | BY-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | ST000614 | Structure | BY-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | ST000614 | Structure | BY-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | ST000614 | Structure | BY-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | ST000614 | Structure | BY-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | ST000614 | Structure | BY-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | ST000614 | Structure | BY-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | ST000614 | Structure | BY-Structure | Structure Patrol Inspection | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | ST000614 | Structure | BY-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | ST000614 | Structure | BY-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | ST000614 | Structure | BY-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | ST000614 | Structure | BY-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | KR0044 | Regulator | 785-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | KR0044 | Regulator | 785-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | ST000614 | Structure | BY-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | ST000614 | Structure | BY-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | ST000614 | Structure | BY-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | ST000614 | Structure | BY-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | KR0044 | Regulator | 785-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | ST000614 | Structure | BY-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | ST000614 | Structure | BY-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | ST000614 | Structure | BY-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | ST000614 | Structure | BY-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | ST000614 | Structure | BY-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BAT001068 | Battery | 786-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.3 | VDC |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | LTCMechanism | 585-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | LTCMechanism | 585-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | LTCMechanism | 585-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | LTCMechanism | 585-1 | LTC Counter Readings | General Comments | Put in temp cap for LTC Motor | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | LTCMechanism | 585-1 | LTC Counter Readings | LTC As Found Counter | 270944 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | LTCMechanism | 585-1 | LTC Counter Readings | LTC As Left Counter | 270951 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | LTCMechanism | 585-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | LTCMechanism | 585-1 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | LTCMechanism | 585-1 | LTC Counter Readings | LTC Max Tap Position | 7L | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | LTCMechanism | 585-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | LTCMechanism | 585-1 | LTC Counter Readings | LTC Operations Since Last Insp | 0 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | LTCMechanism | 585-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | LTCMechanism | 585-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | B0247 | LTCMechanism | 585-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0018 | WithLTC | BY-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000286 | GroundTransformer | C-GND TR 3 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000286 | GroundTransformer | C-GND TR 3 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000286 | GroundTransformer | C-GND TR 3 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000286 | GroundTransformer | C-GND TR 3 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.8 | psi |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000286 | GroundTransformer | C-GND TR 3 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000286 | GroundTransformer | C-GND TR 3 | Ground Transformer Patrol Inspection | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000286 | GroundTransformer | C-GND TR 3 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000286 | GroundTransformer | C-GND TR 3 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000286 | GroundTransformer | C-GND TR 3 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000286 | GroundTransformer | C-GND TR 3 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000286 | GroundTransformer | C-GND TR 3 | Ground Transformer Patrol Inspection | Cleaned Mechanism Cabinet? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000286 | GroundTransformer | C-GND TR 3 | Ground Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000286 | GroundTransformer | C-GND TR 3 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000286 | GroundTransformer | C-GND TR 3 | Ground Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000286 | GroundTransformer | C-GND TR 3 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | BCH001491 | Charger | 891-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | BCH001491 | Charger | 891-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | BCH001491 | Charger | 891-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | BCH001491 | Charger | 891-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | BCH001491 | Charger | 891-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | BCH001491 | Charger | 891-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | BCH001491 | Charger | 891-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | BCH001491 | Charger | 891-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | PF001270 | PowerFuse | LS-STA SER NO 5 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | PF001270 | PowerFuse | LS-STA SER NO 5 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | PF001270 | PowerFuse | LS-STA SER NO 5 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Readings | Totalizer Meter Reading | .1972 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 8000 | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BCH001488 | Charger | 029-Battery Charger 1 | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BCH001488 | Charger | 029-Battery Charger 1 | Battery Charger Patrol Insp | General Comments | | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BCH001488 | Charger | 029-Battery Charger 1 | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BCH001488 | Charger | 029-Battery Charger 1 | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BCH001488 | Charger | 029-Battery Charger 1 | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BCH001488 | Charger | 029-Battery Charger 1 | Battery Charger Patrol Insp | As Left Float Voltage | 133.0 | VDC |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BCH001488 | Charger | 029-Battery Charger 1 | Battery Charger Patrol Insp | As Found Float Voltage | 133.0 | VDC |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BCH001488 | Charger | 029-Battery Charger 1 | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BAT001556 | Battery | 029-Battery Bank 1 | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BAT001556 | Battery | 029-Battery Bank 1 | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BAT001556 | Battery | 029-Battery Bank 1 | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BAT001556 | Battery | 029-Battery Bank 1 | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Readings | Operations Counter AL | 213 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Readings | Operations Counter AF | 213 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Readings | Maintenance Operations | 1 | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BAT001556 | Battery | 029-Battery Bank 1 | Battery Patrol Inspection | General Comments | | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BAT001556 | Battery | 029-Battery Bank 1 | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BAT001556 | Battery | 029-Battery Bank 1 | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BAT001556 | Battery | 029-Battery Bank 1 | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BAT001556 | Battery | 029-Battery Bank 1 | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | AirCompressor Heater Condition | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | Air Tank Bleed (> 40°F)? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | Air Pressure OK? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | Air Leaks | None | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | Air Compressor Oil Status | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | Air Compressor Belt Condition | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Readings | 9 Months Operations OCB New | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0081 | BreakerVacuum | BY-12KV TR 1 | VCB Readings | 9 Month Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0081 | BreakerVacuum | BY-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0081 | BreakerVacuum | BY-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0081 | BreakerVacuum | BY-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0081 | BreakerVacuum | BY-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0081 | BreakerVacuum | BY-12KV TR 1 | VCB Readings | Amps A Ø | 900.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0081 | BreakerVacuum | BY-12KV TR 1 | VCB Readings | Amps B Ø | 925.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0081 | BreakerVacuum | BY-12KV TR 1 | VCB Readings | Amps C Ø | 900.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0081 | BreakerVacuum | BY-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0081 | BreakerVacuum | BY-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0081 | BreakerVacuum | BY-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0081 | BreakerVacuum | BY-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0081 | BreakerVacuum | BY-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0081 | BreakerVacuum | BY-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0081 | BreakerVacuum | BY-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0081 | BreakerVacuum | BY-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0081 | BreakerVacuum | BY-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0081 | BreakerVacuum | BY-12KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0081 | BreakerVacuum | BY-12KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0081 | BreakerVacuum | BY-12KV TR 1 | VCB Readings | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0081 | BreakerVacuum | BY-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0081 | BreakerVacuum | BY-12KV TR 1 | VCB Readings | Operations Counter AF | 434 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0081 | BreakerVacuum | BY-12KV TR 1 | VCB Readings | Operations Counter AL | 434 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0081 | BreakerVacuum | BY-12KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0081 | BreakerVacuum | BY-12KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0081 | BreakerVacuum | BY-12KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | BCH001524 | Charger | 787-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | BCH001524 | Charger | 787-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | BCH001524 | Charger | 787-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | BCH001524 | Charger | 787-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | BCH001524 | Charger | 787-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | BAT001595 | Battery | 787-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | BAT001595 | Battery | 787-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | BAT001595 | Battery | 787-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | BAT001595 | Battery | 787-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | BAT001595 | Battery | 787-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | BAT001595 | Battery | 787-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | BAT001595 | Battery | 787-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | BAT001595 | Battery | 787-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | BAT001595 | Battery | 787-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | BAT001595 | Battery | 787-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.5 | VDC |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | BAT001595 | Battery | 787-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.4 | VDC |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | BAT001595 | Battery | 787-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | BAT001595 | Battery | 787-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001395 | BreakerVacuum | C-14KV TR 4 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000287 | GroundTransformer | C-GND TR 4 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000287 | GroundTransformer | C-GND TR 4 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000287 | GroundTransformer | C-GND TR 4 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000287 | GroundTransformer | C-GND TR 4 | Ground Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000287 | GroundTransformer | C-GND TR 4 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000287 | GroundTransformer | C-GND TR 4 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000287 | GroundTransformer | C-GND TR 4 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000287 | GroundTransformer | C-GND TR 4 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000287 | GroundTransformer | C-GND TR 4 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000287 | GroundTransformer | C-GND TR 4 | Ground Transformer Patrol Inspection | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000287 | GroundTransformer | C-GND TR 4 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000287 | GroundTransformer | C-GND TR 4 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000287 | GroundTransformer | C-GND TR 4 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000287 | GroundTransformer | C-GND TR 4 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000287 | GroundTransformer | C-GND TR 4 | Ground Transformer Patrol Inspection | Cleaned Mechanism Cabinet? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000287 | GroundTransformer | C-GND TR 4 | Ground Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000287 | GroundTransformer | C-GND TR 4 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000287 | GroundTransformer | C-GND TR 4 | Ground Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000287 | GroundTransformer | C-GND TR 4 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000286 | GroundTransformer | C-GND TR 3 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000286 | GroundTransformer | C-GND TR 3 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000286 | GroundTransformer | C-GND TR 3 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | TX000286 | GroundTransformer | C-GND TR 3 | Ground Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | LTCMechanism | C-TRANS 4 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | LTCMechanism | C-TRANS 4 | LTC Counter Readings | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | LTCMechanism | C-TRANS 4 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | LTCMechanism | C-TRANS 4 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1134 | Regulator | 012-5 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1134 | Regulator | 012-5 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1134 | Regulator | 012-5 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1134 | Regulator | 012-5 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1134 | Regulator | 012-5 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1134 | Regulator | 012-5 B | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1134 | Regulator | 012-5 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1134 | Regulator | 012-5 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1134 | Regulator | 012-5 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1134 | Regulator | 012-5 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1134 | Regulator | 012-5 B | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1134 | Regulator | 012-5 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1134 | Regulator | 012-5 B | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1134 | Regulator | 012-5 B | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1134 | Regulator | 012-5 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1134 | Regulator | 012-5 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1134 | Regulator | 012-5 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1134 | Regulator | 012-5 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1134 | Regulator | 012-5 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.3 | volts |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1134 | Regulator | 012-5 B | Regulator Patrol Inspection | Regulator As Left Counter | 79291 | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1134 | Regulator | 012-5 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1134 | Regulator | 012-5 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1134 | Regulator | 012-5 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1135 | Regulator | 012-5 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1135 | Regulator | 012-5 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1135 | Regulator | 012-5 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1135 | Regulator | 012-5 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1135 | Regulator | 012-5 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1135 | Regulator | 012-5 C | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1135 | Regulator | 012-5 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1135 | Regulator | 012-5 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | ST000604 | Structure | DE-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | ST000604 | Structure | DE-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | ST000604 | Structure | DE-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | ST000604 | Structure | DE-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | ST000604 | Structure | DE-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | ST000604 | Structure | DE-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | ST000604 | Structure | DE-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | ST000604 | Structure | DE-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | ST000604 | Structure | DE-Structure | Structure Patrol Inspection | General Comments | | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | ST000604 | Structure | DE-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | ST000604 | Structure | DE-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | ST000604 | Structure | DE-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | ST000604 | Structure | DE-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | ST000604 | Structure | DE-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | ST000604 | Structure | DE-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | ST000604 | Structure | DE-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1135 | Regulator | 012-5 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1135 | Regulator | 012-5 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1135 | Regulator | 012-5 C | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1135 | Regulator | 012-5 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1135 | Regulator | 012-5 C | Regulator Patrol Inspection | Max Tap Position | 16R | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | R1135 | Regulator | 012-5 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BAT001556 | Battery | 029-Battery Bank 1 | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Readings | General Comments | | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Readings | Amps C Ø | 38.0 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Readings | Amps B Ø | 34.0 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Readings | Amps A Ø | 23.0 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BAT001556 | Battery | 029-Battery Bank 1 | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BAT001556 | Battery | 029-Battery Bank 1 | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BAT001556 | Battery | 029-Battery Bank 1 | Battery Patrol Inspection | All Connections OK? | y | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/7/2023 13:30 | Distribution | Waverly Quarterly Inspection | BK000904 | BreakerVacuum | 514-1764 | VCB Readings | 9 Month Operations | 2 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1253 | BreakerVacuum | BY-12KV BUS TIE SEC 2 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1253 | BreakerVacuum | BY-12KV BUS TIE SEC 2 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1253 | BreakerVacuum | BY-12KV BUS TIE SEC 2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1253 | BreakerVacuum | BY-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AL | 205 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1253 | BreakerVacuum | BY-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AF | 205 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1253 | BreakerVacuum | BY-12KV BUS TIE SEC 2 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1253 | BreakerVacuum | BY-12KV BUS TIE SEC 2 | VCB Readings | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1253 | BreakerVacuum | BY-12KV BUS TIE SEC 2 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1253 | BreakerVacuum | BY-12KV BUS TIE SEC 2 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1253 | BreakerVacuum | BY-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1253 | BreakerVacuum | BY-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1253 | BreakerVacuum | BY-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1253 | BreakerVacuum | BY-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1253 | BreakerVacuum | BY-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1253 | BreakerVacuum | BY-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1253 | BreakerVacuum | BY-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1253 | BreakerVacuum | BY-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1253 | BreakerVacuum | BY-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1253 | BreakerVacuum | BY-12KV BUS TIE SEC 2 | VCB Readings | Amps C Ø | 0.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1253 | BreakerVacuum | BY-12KV BUS TIE SEC 2 | VCB Readings | Amps B Ø | 0.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1253 | BreakerVacuum | BY-12KV BUS TIE SEC 2 | VCB Readings | Amps A Ø | 0.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1253 | BreakerVacuum | BY-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1253 | BreakerVacuum | BY-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1253 | BreakerVacuum | BY-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | LTCMechanism | C-TRANS 4 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | LTCMechanism | C-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | LTCMechanism | C-TRANS 4 | LTC Counter Readings | LTC Operations Since Last Insp | 34 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | LTCMechanism | C-TRANS 4 | LTC Counter Readings | LTC Current Tap Position | 4 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | LTCMechanism | C-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | LTCMechanism | C-TRANS 4 | LTC Counter Readings | LTC As Left Counter | 82474 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0029 | LTCMechanism | C-TRANS 4 | LTC Counter Readings | LTC As Found Counter | 82474 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1253 | BreakerVacuum | BY-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1253 | BreakerVacuum | BY-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations | 1 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 4.0 | psi |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Readings | LTC Totalizer Reading | 1577.60 | kw |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | WithLTC | 888-1 | LTC Transformer Readings | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001394 | BreakerVacuum | C-14KV REACTOR TIE | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Readings | Totalizer Meter Reading | .9972 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Readings | Winding Temp Max | 35 | °C |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Readings | Winding Temp Present | 25 | °C |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | LTCMechanism | 786-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | LTCMechanism | 786-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | LTCMechanism | 786-1 | LTC Counter Readings | General Comments | | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | LTCMechanism | 786-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | LTCMechanism | 786-1 | LTC Counter Readings | LTC As Found Counter | 11702 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | LTCMechanism | 786-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | LTCMechanism | 786-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | LTCMechanism | 786-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | LTCMechanism | 786-1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | LTCMechanism | 786-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | LTCMechanism | 786-1 | LTC Counter Readings | LTC Operations Since Last Insp | 376 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | LTCMechanism | 786-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | LTCMechanism | 786-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | M0055 | LTCMechanism | 786-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0078 | BreakerVacuum | BY-1284 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0078 | BreakerVacuum | BY-1284 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0078 | BreakerVacuum | BY-1284 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0078 | BreakerVacuum | BY-1284 | VCB Readings | Operations Counter AL | 662 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0078 | BreakerVacuum | BY-1284 | VCB Readings | Operations Counter AF | 662 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0078 | BreakerVacuum | BY-1284 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0078 | BreakerVacuum | BY-1284 | VCB Readings | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0078 | BreakerVacuum | BY-1284 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0078 | BreakerVacuum | BY-1284 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0078 | BreakerVacuum | BY-1284 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0078 | BreakerVacuum | BY-1284 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0078 | BreakerVacuum | BY-1284 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0078 | BreakerVacuum | BY-1284 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0078 | BreakerVacuum | BY-1284 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0078 | BreakerVacuum | BY-1284 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Readings | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Readings | Operations Counter AF | 24 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Readings | Operations Counter AL | 24 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0078 | BreakerVacuum | BY-1284 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0078 | BreakerVacuum | BY-1284 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0078 | BreakerVacuum | BY-1284 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0123 | Regulator | 891-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0123 | Regulator | 891-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0123 | Regulator | 891-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0123 | Regulator | 891-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0123 | Regulator | 891-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 27515 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0123 | Regulator | 891-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0123 | Regulator | 891-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0123 | Regulator | 891-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0123 | Regulator | 891-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0123 | Regulator | 891-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0078 | BreakerVacuum | BY-1284 | VCB Readings | Amps C Ø | 220.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0078 | BreakerVacuum | BY-1284 | VCB Readings | Amps B Ø | 220.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0078 | BreakerVacuum | BY-1284 | VCB Readings | Amps A Ø | 210.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0078 | BreakerVacuum | BY-1284 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0078 | BreakerVacuum | BY-1284 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0078 | BreakerVacuum | BY-1284 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0078 | BreakerVacuum | BY-1284 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0078 | BreakerVacuum | BY-1284 | VCB Readings | 9 Month Operations | 0 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0123 | Regulator | 891-1 C | Regulator Patrol Inspection | Min Tap Position | 13R | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0123 | Regulator | 891-1 C | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0123 | Regulator | 891-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0123 | Regulator | 891-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0123 | Regulator | 891-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0123 | Regulator | 891-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0123 | Regulator | 891-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0123 | Regulator | 891-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0123 | Regulator | 891-1 C | Regulator Patrol Inspection | Current Tap Position | 7R | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0787 | Regulator | 029-5 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | X0026 | RecloserHydraulic | 718-0446 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 49.6 | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | X0026 | RecloserHydraulic | 718-0446 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 47.6 | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | X0026 | RecloserHydraulic | 718-0446 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 53.6 | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | X0026 | RecloserHydraulic | 718-0446 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | X0026 | RecloserHydraulic | 718-0446 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | X0026 | RecloserHydraulic | 718-0446 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | X0026 | RecloserHydraulic | 718-0446 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | 0926 | NonLTC | 517-1 C | NonLTC Transformer Patrol Inspection | All Temp Gauges MAX Reset | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | 0926 | NonLTC | 517-1 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | 0926 | NonLTC | 517-1 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | 0926 | NonLTC | 517-1 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | 0926 | NonLTC | 517-1 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | 0926 | NonLTC | 517-1 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | 0926 | NonLTC | 517-1 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | 0926 | NonLTC | 517-1 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | 0926 | NonLTC | 517-1 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | 0926 | NonLTC | 517-1 C | NonLTC Transformer Readings | General Comments | | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | 0926 | NonLTC | 517-1 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | 0926 | NonLTC | 517-1 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | 0926 | NonLTC | 517-1 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | 0926 | NonLTC | 517-1 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | 0926 | NonLTC | 517-1 C | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | 0926 | NonLTC | 517-1 C | NonLTC Transformer Readings | Oil Temp Present | 26 | °C |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | 0926 | NonLTC | 517-1 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | X0026 | RecloserHydraulic | 718-0446 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | X0026 | RecloserHydraulic | 718-0446 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | X0026 | RecloserHydraulic | 718-0446 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | X0026 | RecloserHydraulic | 718-0446 | Recloser Hydraulic Patrol Inspection | Operations Counter | 250 | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | X0026 | RecloserHydraulic | 718-0446 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | X0026 | RecloserHydraulic | 718-0446 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | 0926 | NonLTC | 517-1 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | 0926 | NonLTC | 517-1 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | 0926 | NonLTC | 517-1 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | 0926 | NonLTC | 517-1 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BCH001031 | Charger | 786-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.3 | VDC |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BCH001031 | Charger | 786-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 7179.84 | kw |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | 0926 | NonLTC | 517-1 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Readings | Oil Temp Max | 26 | °C |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Readings | Oil Temp Present | 19 | °C |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Readings | 9 Month Operations | 24 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Readings | 9 Month Operations VCB New | 24 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Readings | Amps A Ø | 67.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Readings | Amps B Ø | 65.0 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0314 | NonLTC | 510-1 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0314 | NonLTC | 510-1 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0314 | NonLTC | 510-1 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Readings | Amps C Ø | 75.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002121 | BreakerVacuum | ET-1166 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000193 | Switchgear | BY-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000193 | Switchgear | BY-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000193 | Switchgear | BY-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000193 | Switchgear | BY-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000193 | Switchgear | BY-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000193 | Switchgear | BY-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000193 | Switchgear | BY-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000193 | Switchgear | BY-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000193 | Switchgear | BY-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000193 | Switchgear | BY-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | LTCMechanism | 600-1 | LTC Counter Readings | General Comments | | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Readings | 9 Month Operations | 4 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Readings | Amps A Ø | 60.0 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Readings | Amps B Ø | 60.0 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Readings | Amps C Ø | 60.0 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | LTCMechanism | 600-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | LTCMechanism | 600-1 | LTC Counter Readings | LTC As Found Counter | 104084 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | LTCMechanism | 600-1 | LTC Counter Readings | LTC As Left Counter | 104084 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | LTCMechanism | 600-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | LTCMechanism | 600-1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | LTCMechanism | 600-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | LTCMechanism | 600-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | LTCMechanism | 600-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000193 | Switchgear | BY-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | LTCMechanism | 600-1 | LTC Counter Readings | LTC Operations Since Last Insp | 130 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | LTCMechanism | 600-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | LTCMechanism | 600-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | LTCMechanism | 600-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | LTCMechanism | 600-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | LTCMechanism | 724-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | LTCMechanism | 724-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | LTCMechanism | 724-1 | LTC Counter Readings | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | LTCMechanism | 724-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Readings | 9 Month Operations | 38 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Readings | 9 Month Operations VCB New | 38 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0076 | BreakerVacuum | BY-1282 | VCB Readings | 9 Month Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0076 | BreakerVacuum | BY-1282 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0076 | BreakerVacuum | BY-1282 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0076 | BreakerVacuum | BY-1282 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Readings | Amps A Ø | 108.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Readings | Amps B Ø | 117.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Readings | Amps C Ø | 101.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | LTCMechanism | 724-1 | LTC Counter Readings | LTC As Found Counter | 76221 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | LTCMechanism | 724-1 | LTC Counter Readings | LTC As Left Counter | 76221 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | LTCMechanism | 724-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | LTCMechanism | 724-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0123 | Regulator | 891-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0123 | Regulator | 891-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0123 | Regulator | 891-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0123 | Regulator | 891-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | R1209 | Regulator | 892-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | R1209 | Regulator | 892-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | R1209 | Regulator | 892-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | R1209 | Regulator | 892-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | R1209 | Regulator | 892-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | R1209 | Regulator | 892-1 A | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | R1209 | Regulator | 892-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | R1209 | Regulator | 892-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | R1209 | Regulator | 892-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | R1209 | Regulator | 892-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | R1209 | Regulator | 892-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | R1209 | Regulator | 892-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | R1209 | Regulator | 892-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | R1209 | Regulator | 892-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | R1209 | Regulator | 892-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | R1209 | Regulator | 892-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | R1209 | Regulator | 892-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | R1209 | Regulator | 892-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | R1209 | Regulator | 892-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.6 | volts |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | R1209 | Regulator | 892-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 443261 | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | R1209 | Regulator | 892-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | R1209 | Regulator | 892-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | R1209 | Regulator | 892-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MX0396 | RecloserHydraulic | 517-0323 C | Recloser Hydraulic Patrol Inspection | Amps A Ø | 14.0 | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MX0396 | RecloserHydraulic | 517-0323 C | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MX0396 | RecloserHydraulic | 517-0323 C | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MX0396 | RecloserHydraulic | 517-0323 C | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MX0396 | RecloserHydraulic | 517-0323 C | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MX0396 | RecloserHydraulic | 517-0323 C | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MX0396 | RecloserHydraulic | 517-0323 C | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MX0396 | RecloserHydraulic | 517-0323 C | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MX0396 | RecloserHydraulic | 517-0323 C | Recloser Hydraulic Patrol Inspection | Operations Counter | 499 | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MX0396 | RecloserHydraulic | 517-0323 C | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MX0396 | RecloserHydraulic | 517-0323 C | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Readings | 9 Month Operations | 15 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Readings | 9 Month Operations VCB New | 15 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Readings | Amps A Ø | 80.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Readings | Amps B Ø | 58.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Readings | Amps C Ø | 76.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Readings | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Readings | Operations Counter AF | 15 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Readings | Operations Counter AL | 15 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002122 | BreakerVacuum | ET-1167 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | LTCMechanism | 600-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | B0377 | LTCMechanism | 600-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1252 | BreakerVacuum | BY-12KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1252 | BreakerVacuum | BY-12KV TR 2 | VCB Readings | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1252 | BreakerVacuum | BY-12KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1252 | BreakerVacuum | BY-12KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1252 | BreakerVacuum | BY-12KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1252 | BreakerVacuum | BY-12KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1252 | BreakerVacuum | BY-12KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1252 | BreakerVacuum | BY-12KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1252 | BreakerVacuum | BY-12KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1252 | BreakerVacuum | BY-12KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1252 | BreakerVacuum | BY-12KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1252 | BreakerVacuum | BY-12KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1252 | BreakerVacuum | BY-12KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1252 | BreakerVacuum | BY-12KV TR 2 | VCB Readings | Amps C Ø | 598.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1252 | BreakerVacuum | BY-12KV TR 2 | VCB Readings | Amps B Ø | 623.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1252 | BreakerVacuum | BY-12KV TR 2 | VCB Readings | Amps A Ø | 650.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1252 | BreakerVacuum | BY-12KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1252 | BreakerVacuum | BY-12KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1252 | BreakerVacuum | BY-12KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1252 | BreakerVacuum | BY-12KV TR 2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1252 | BreakerVacuum | BY-12KV TR 2 | VCB Readings | 9 Month Operations | 0 | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | KX0126 | RecloserElectronic | 725-0844 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | KX0126 | RecloserElectronic | 725-0844 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | KX0126 | RecloserElectronic | 725-0844 | Recloser Electronic Patrol Inspection | Operations Counter | 228 | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | KX0126 | RecloserElectronic | 725-0844 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | KX0126 | RecloserElectronic | 725-0844 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | KX0126 | RecloserElectronic | 725-0844 | Recloser Electronic Patrol Inspection | General Comments | Breaker was open and hold carded | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | KX0126 | RecloserElectronic | 725-0844 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | KX0126 | RecloserElectronic | 725-0844 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | KX0126 | RecloserElectronic | 725-0844 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001480 | BreakerVacuum | C-14KV TR 3 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | KX0126 | RecloserElectronic | 725-0844 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | KX0126 | RecloserElectronic | 725-0844 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | KX0126 | RecloserElectronic | 725-0844 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | KX0126 | RecloserElectronic | 725-0844 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | RC000444 | RecloserElectronic | 012-1431 | Recloser Electronic Patrol Inspection | Amps A Ø | 92.0 | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | RC000444 | RecloserElectronic | 012-1431 | Recloser Electronic Patrol Inspection | Amps B Ø | 86.0 | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | RC000444 | RecloserElectronic | 012-1431 | Recloser Electronic Patrol Inspection | Amps C Ø | 93.0 | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | RC000444 | RecloserElectronic | 012-1431 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | RC000444 | RecloserElectronic | 012-1431 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | RC000444 | RecloserElectronic | 012-1431 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | RC000444 | RecloserElectronic | 012-1431 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | RC000444 | RecloserElectronic | 012-1431 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | RC000444 | RecloserElectronic | 012-1431 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | RC000444 | RecloserElectronic | 012-1431 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | RC000444 | RecloserElectronic | 012-1431 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | RC000444 | RecloserElectronic | 012-1431 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | RC000444 | RecloserElectronic | 012-1431 | Recloser Electronic Patrol Inspection | General Comments | counters 134-117-119 | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | RC000444 | RecloserElectronic | 012-1431 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | RC000444 | RecloserElectronic | 012-1431 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | RC000444 | RecloserElectronic | 012-1431 | Recloser Electronic Patrol Inspection | Operations Counter | 0 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Readings | Switching Operations | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000929 | BreakerVacuum | 072-2 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Readings | Operations Counter AL | 132 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Readings | Operations Counter AF | 131 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Readings | Maintenance Operations | 1 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Readings | General Comments | | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Readings | 9 Month Operations | 3 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Readings | Accumulated Fault Duty A Ph V | 7.12 | % |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Readings | Accumulated Fault Duty B Ph V | 2.09 | % |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Readings | Accumulated Fault Duty C Ph V | 11.72 | % |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Readings | Amps A Ø | 2.0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Readings | Amps B Ø | 0.0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Readings | Amps C Ø | 2.0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BX0733 | RecloserElectronic | 029-0701 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BX0733 | RecloserElectronic | 029-0701 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BX0733 | RecloserElectronic | 029-0701 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BX0733 | RecloserElectronic | 029-0701 | Recloser Electronic Patrol Inspection | Operations Counter | 16 | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BX0733 | RecloserElectronic | 029-0701 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BX0733 | RecloserElectronic | 029-0701 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BX0733 | RecloserElectronic | 029-0701 | Recloser Electronic Patrol Inspection | General Comments | | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BX0733 | RecloserElectronic | 029-0701 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BX0733 | RecloserElectronic | 029-0701 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BX0733 | RecloserElectronic | 029-0701 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BX0733 | RecloserElectronic | 029-0701 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BX0733 | RecloserElectronic | 029-0701 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1252 | BreakerVacuum | BY-12KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1252 | BreakerVacuum | BY-12KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BX0733 | RecloserElectronic | 029-0701 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BX0733 | RecloserElectronic | 029-0701 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BX0733 | RecloserElectronic | 029-0701 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BX0733 | RecloserElectronic | 029-0701 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BX0733 | RecloserElectronic | 029-0701 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | n | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BX0733 | RecloserElectronic | 029-0701 | Recloser Electronic Patrol Inspection | Amps C Ø | 75.0 | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BX0733 | RecloserElectronic | 029-0701 | Recloser Electronic Patrol Inspection | Amps B Ø | 91.0 | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | BX0733 | RecloserElectronic | 029-0701 | Recloser Electronic Patrol Inspection | Amps A Ø | 71.0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Patrol Inspection | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Readings | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Readings | Maintenance Operations | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Readings | Operations Counter AF | 242 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Readings | Operations Counter AL | 242 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Readings | Operations This Read Vac | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Readings | Switching Operations | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000930 | BreakerVacuum | 072-0284 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1252 | BreakerVacuum | BY-12KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1252 | BreakerVacuum | BY-12KV TR 2 | VCB Readings | Operations Counter AL | 178 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1252 | BreakerVacuum | BY-12KV TR 2 | VCB Readings | Operations Counter AF | 178 | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0813 | Regulator | 029-5 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0813 | Regulator | 029-5 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BCH001525 | Charger | 613-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BCH001525 | Charger | 613-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BCH001525 | Charger | 613-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BCH001525 | Charger | 613-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0813 | Regulator | 029-5 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0813 | Regulator | 029-5 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0314 | NonLTC | 510-1 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0314 | NonLTC | 510-1 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0314 | NonLTC | 510-1 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0314 | NonLTC | 510-1 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0314 | NonLTC | 510-1 B | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0314 | NonLTC | 510-1 B | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0314 | NonLTC | 510-1 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0314 | NonLTC | 510-1 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0787 | Regulator | 029-5 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0787 | Regulator | 029-5 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0787 | Regulator | 029-5 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0787 | Regulator | 029-5 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0787 | Regulator | 029-5 B | Regulator Patrol Inspection | Regulator As Left Counter | 133646 | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0787 | Regulator | 029-5 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.0 | volts |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0787 | Regulator | 029-5 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0787 | Regulator | 029-5 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0787 | Regulator | 029-5 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0787 | Regulator | 029-5 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0787 | Regulator | 029-5 B | Regulator Patrol Inspection | Min Tap Position | 1R | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | BCH001529 | Charger | 502-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | BCH001529 | Charger | 502-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | BCH001529 | Charger | 502-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | BCH001529 | Charger | 502-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | BCH001529 | Charger | 502-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Readings | General Comments | | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | BAT001600 | Battery | 502-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | BAT001600 | Battery | 502-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | BAT001600 | Battery | 502-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | BAT001600 | Battery | 502-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | BAT001600 | Battery | 502-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | BAT001600 | Battery | 502-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | BAT001600 | Battery | 502-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | BAT001600 | Battery | 502-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0787 | Regulator | 029-5 B | Regulator Patrol Inspection | Max Tap Position | 9R | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0787 | Regulator | 029-5 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0787 | Regulator | 029-5 B | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | BAT001600 | Battery | 502-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | BAT001600 | Battery | 502-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.5 | VDC |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | BAT001600 | Battery | 502-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.5 | VDC |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | BAT001600 | Battery | 502-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | BAT001600 | Battery | 502-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0787 | Regulator | 029-5 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0787 | Regulator | 029-5 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0787 | Regulator | 029-5 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0787 | Regulator | 029-5 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0787 | Regulator | 029-5 B | Regulator Patrol Inspection | Current Tap Position | 3R | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0787 | Regulator | 029-5 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0787 | Regulator | 029-5 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | S0063 | NonLTC | 786-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0787 | Regulator | 029-5 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0787 | Regulator | 029-5 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Readings | Amps C Ø | 90.0 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Readings | Amps B Ø | 50.0 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Readings | Amps A Ø | 45.0 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | K0103 | BreakerVacuum | 787-1473 | VCB Readings | 9 Month Operations | 1 | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | RC000444 | RecloserElectronic | 012-1431 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | RC000444 | RecloserElectronic | 012-1431 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | KX0126 | RecloserElectronic | 725-0844 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | KX0126 | RecloserElectronic | 725-0844 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | KX0126 | RecloserElectronic | 725-0844 | Recloser Electronic Patrol Inspection | Amps C Ø | 0.0 | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | KX0126 | RecloserElectronic | 725-0844 | Recloser Electronic Patrol Inspection | Amps B Ø | 0.0 | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | KX0126 | RecloserElectronic | 725-0844 | Recloser Electronic Patrol Inspection | Amps A Ø | 0.0 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BAT001068 | Battery | 786-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BAT001596 | Battery | 613-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BAT001596 | Battery | 613-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BAT001596 | Battery | 613-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BAT001596 | Battery | 613-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BAT001596 | Battery | 613-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BAT001596 | Battery | 613-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BAT001596 | Battery | 613-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BAT001596 | Battery | 613-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BAT001596 | Battery | 613-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BAT001596 | Battery | 613-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.2 | VDC |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BAT001596 | Battery | 613-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.3 | VDC |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BAT001596 | Battery | 613-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/7/2023 12:00 | Distribution | Tunnel Hill Quarterly Inspection | BAT001596 | Battery | 613-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BAT001068 | Battery | 786-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BAT001068 | Battery | 786-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BAT001068 | Battery | 786-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 41 | °F |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BAT001068 | Battery | 786-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BCH001031 | Charger | 786-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BCH001031 | Charger | 786-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BCH001031 | Charger | 786-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BCH001031 | Charger | 786-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BCH001031 | Charger | 786-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 3.8 | amps |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0813 | Regulator | 029-5 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0813 | Regulator | 029-5 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0813 | Regulator | 029-5 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0813 | Regulator | 029-5 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0813 | Regulator | 029-5 C | Regulator Patrol Inspection | Regulator As Left Counter | 153913 | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0813 | Regulator | 029-5 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0813 | Regulator | 029-5 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0813 | Regulator | 029-5 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0813 | Regulator | 029-5 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0314 | NonLTC | 510-1 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0314 | NonLTC | 510-1 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0314 | NonLTC | 510-1 B | NonLTC Transformer Patrol Inspection | Tank Leaks | Seeping | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0314 | NonLTC | 510-1 B | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0314 | NonLTC | 510-1 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0314 | NonLTC | 510-1 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0314 | NonLTC | 510-1 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | BCH001031 | Charger | 786-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.3 | VDC |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0314 | NonLTC | 510-1 B | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0314 | NonLTC | 510-1 B | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0314 | NonLTC | 510-1 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0314 | NonLTC | 510-1 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0314 | NonLTC | 510-1 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0314 | NonLTC | 510-1 B | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0314 | NonLTC | 510-1 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0314 | NonLTC | 510-1 B | NonLTC Transformer Readings | General Comments | oil seems to be seeping from gauge | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0813 | Regulator | 029-5 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0813 | Regulator | 029-5 C | Regulator Patrol Inspection | Min Tap Position | 3L | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0813 | Regulator | 029-5 C | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0813 | Regulator | 029-5 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0813 | Regulator | 029-5 C | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0813 | Regulator | 029-5 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0813 | Regulator | 029-5 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0813 | Regulator | 029-5 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0813 | Regulator | 029-5 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0813 | Regulator | 029-5 C | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0314 | NonLTC | 510-1 B | NonLTC Transformer Patrol Inspection | General Comments | looks like seeping fron temp gauge. wiped and placed diapers to see amount leaking. | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | R0813 | Regulator | 029-5 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | LTCC000778 | LTCControl | 072-6 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | LTCC000778 | LTCControl | 072-6 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | LTCC000778 | LTCControl | 072-6 | LTC Control Insp | LTC Output Voltage Level | 123.5 | VAC |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | LTCC000778 | LTCControl | 072-6 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | LTCC000778 | LTCControl | 072-6 | LTC Control Insp | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | LTCC000778 | LTCControl | 072-6 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | LTCC000778 | LTCControl | 072-6 | LTC Control Insp | All Connections OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BAT001035 | Battery | C-Battery Bank-Distribution | Battery Patrol Inspection | All Connections OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BAT001035 | Battery | C-Battery Bank-Distribution | Battery Patrol Inspection | Battery Area Ambient Temp | 62 | °F |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BCH001152 | Charger | 559-Battery Charger-Distribution | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BCH001152 | Charger | 559-Battery Charger-Distribution | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BCH001152 | Charger | 559-Battery Charger-Distribution | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BAT001209 | Battery | 559-Battery Bank-Distribution | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BAT001209 | Battery | 559-Battery Bank-Distribution | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BAT001209 | Battery | 559-Battery Bank-Distribution | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BAT001209 | Battery | 559-Battery Bank-Distribution | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BAT001209 | Battery | 559-Battery Bank-Distribution | Battery Patrol Inspection | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BAT001035 | Battery | C-Battery Bank-Distribution | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BAT001035 | Battery | C-Battery Bank-Distribution | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BAT001035 | Battery | C-Battery Bank-Distribution | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BAT001035 | Battery | C-Battery Bank-Distribution | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BAT001035 | Battery | C-Battery Bank-Distribution | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BAT001035 | Battery | C-Battery Bank-Distribution | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BAT001035 | Battery | C-Battery Bank-Distribution | Battery Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BAT001035 | Battery | C-Battery Bank-Distribution | Battery Patrol Inspection | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BAT001035 | Battery | C-Battery Bank-Distribution | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BAT001035 | Battery | C-Battery Bank-Distribution | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Readings | Operations Counter AL | 177 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Readings | Operations Counter AF | 177 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Readings | Maintenance Operations | 1 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Readings | General Comments | TC | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | DX0120 | RecloserHydraulic | 890-0257 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 48 | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | DX0120 | RecloserHydraulic | 890-0257 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | DX0120 | RecloserHydraulic | 890-0257 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0.0 | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | DX0120 | RecloserHydraulic | 890-0257 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | DX0120 | RecloserHydraulic | 890-0257 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 36 | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | DX0120 | RecloserHydraulic | 890-0257 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | DX0120 | RecloserHydraulic | 890-0257 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | DX0120 | RecloserHydraulic | 890-0257 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 44 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BAT001209 | Battery | 559-Battery Bank-Distribution | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BAT001014 | Battery | DE-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BAT001014 | Battery | DE-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BAT001014 | Battery | DE-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BAT001014 | Battery | DE-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BAT001014 | Battery | DE-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BAT001014 | Battery | DE-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BAT001014 | Battery | DE-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BAT001014 | Battery | DE-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BAT001014 | Battery | DE-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BAT001014 | Battery | DE-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | BAT001029 | Battery | BY-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | BAT001029 | Battery | BY-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | BAT001029 | Battery | BY-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | BAT001029 | Battery | BY-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | BAT001029 | Battery | BY-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | BAT001029 | Battery | BY-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | BAT001029 | Battery | BY-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | BAT001029 | Battery | BY-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | BAT001029 | Battery | BY-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | BAT001029 | Battery | BY-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | BAT001029 | Battery | BY-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 200 | psi |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Readings | 9 Month Operations VCB New | 15 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Readings | 9 Month Operations | 15 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Readings | Operations Counter AL | 144 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Readings | Operations Counter AF | 144 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Readings | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Readings | Foundation Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Readings | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Readings | Operations Counter AF | 135 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Readings | Operations Counter AL | 135 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BCH001152 | Charger | 559-Battery Charger-Distribution | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BCH001152 | Charger | 559-Battery Charger-Distribution | Battery Charger Patrol Insp | General Comments | | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BCH001152 | Charger | 559-Battery Charger-Distribution | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BCH001152 | Charger | 559-Battery Charger-Distribution | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BCH001152 | Charger | 559-Battery Charger-Distribution | Battery Charger Patrol Insp | Battery Charger Current | .4 | amps |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | LTCC000778 | LTCControl | 072-6 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1436 | Regulator | 786-2 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Readings | Operations Counter AL | 150 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Readings | Operations Counter AF | 150 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | CH000425 | ControlHouse | 724-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | CH000425 | ControlHouse | 724-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | CH000425 | ControlHouse | 724-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | CH000425 | ControlHouse | 724-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | CH000425 | ControlHouse | 724-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | CH000425 | ControlHouse | 724-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | CH000425 | ControlHouse | 724-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | CH000425 | ControlHouse | 724-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | CH000425 | ControlHouse | 724-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | CH000425 | ControlHouse | 724-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | CH000425 | ControlHouse | 724-Control House | Control House Patrol Inspection | Filters Condition OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | CH000425 | ControlHouse | 724-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | CH000425 | ControlHouse | 724-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | CH000425 | ControlHouse | 724-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | CH000425 | ControlHouse | 724-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | CH000425 | ControlHouse | 724-Control House | Control House Patrol Inspection | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | CH000425 | ControlHouse | 724-Control House | Control House Patrol Inspection | HVAC Filter Replaced? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | CH000425 | ControlHouse | 724-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BAT001209 | Battery | 559-Battery Bank-Distribution | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BAT001209 | Battery | 559-Battery Bank-Distribution | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BAT001209 | Battery | 559-Battery Bank-Distribution | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BAT001209 | Battery | 559-Battery Bank-Distribution | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BAT001209 | Battery | 559-Battery Bank-Distribution | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BAT001209 | Battery | 559-Battery Bank-Distribution | Battery Patrol Inspection | Battery Area Ambient Temp | 68 | °F |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BAT001209 | Battery | 559-Battery Bank-Distribution | Battery Patrol Inspection | All Connections OK? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | CH000425 | ControlHouse | 724-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | CH000425 | ControlHouse | 724-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | CH000425 | ControlHouse | 724-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1436 | Regulator | 786-2 A | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1436 | Regulator | 786-2 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1436 | Regulator | 786-2 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1436 | Regulator | 786-2 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1436 | Regulator | 786-2 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1436 | Regulator | 786-2 A | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1436 | Regulator | 786-2 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1436 | Regulator | 786-2 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1436 | Regulator | 786-2 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1436 | Regulator | 786-2 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1436 | Regulator | 786-2 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | CH000425 | ControlHouse | 724-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | RC000365 | RecloserElectronic | 029-0702 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | RC000365 | RecloserElectronic | 029-0702 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | RC000365 | RecloserElectronic | 029-0702 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | RC000365 | RecloserElectronic | 029-0702 | Recloser Electronic Patrol Inspection | Operations Counter | 31 | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | RC000365 | RecloserElectronic | 029-0702 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | RC000365 | RecloserElectronic | 029-0702 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | RC000365 | RecloserElectronic | 029-0702 | Recloser Electronic Patrol Inspection | General Comments | | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | RC000365 | RecloserElectronic | 029-0702 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | RC000365 | RecloserElectronic | 029-0702 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | RC000365 | RecloserElectronic | 029-0702 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | RC000365 | RecloserElectronic | 029-0702 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | RC000365 | RecloserElectronic | 029-0702 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | RC000365 | RecloserElectronic | 029-0702 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | RC000365 | RecloserElectronic | 029-0702 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | CH000425 | ControlHouse | 724-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Readings | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | RC000365 | RecloserElectronic | 029-0702 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | RC000365 | RecloserElectronic | 029-0702 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | RC000365 | RecloserElectronic | 029-0702 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | n | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | RC000365 | RecloserElectronic | 029-0702 | Recloser Electronic Patrol Inspection | Amps C Ø | 0.0 | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | RC000365 | RecloserElectronic | 029-0702 | Recloser Electronic Patrol Inspection | Amps B Ø | 0.0 | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | RC000365 | RecloserElectronic | 029-0702 | Recloser Electronic Patrol Inspection | Amps A Ø | 0.0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | RG000039 | Regulator | 072-3 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BAT001014 | Battery | DE-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 75 | °F |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | BAT001014 | Battery | DE-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Readings | Amps C Ø | 0.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Readings | Amps B Ø | 0.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Readings | Amps A Ø | 0.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000522 | BreakerVacuum | LS-1242 | VCB Readings | 9 Month Operations | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Readings | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Patrol Inspection | General Comments | added nitrogen | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Readings | Amps C Ø | 74.0 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Readings | Amps B Ø | 57.0 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Readings | Amps A Ø | 62.0 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | K0137 | BreakerVacuum | 510-1461 | VCB Readings | 9 Month Operations | 2 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Readings | LTC Totalizer Reading | 10661.76 | kw |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Readings | Oil Temp Max | 54 | °C |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | DX0120 | RecloserHydraulic | 890-0257 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | DX0120 | RecloserHydraulic | 890-0257 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | DX0120 | RecloserHydraulic | 890-0257 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | DX0120 | RecloserHydraulic | 890-0257 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | DX0120 | RecloserHydraulic | 890-0257 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | DX0120 | RecloserHydraulic | 890-0257 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | DX0120 | RecloserHydraulic | 890-0257 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Readings | Totalizer Meter Reading | 1.4808 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | O0220 | WithLTC | 072-6 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1436 | Regulator | 786-2 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1436 | Regulator | 786-2 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1436 | Regulator | 786-2 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1436 | Regulator | 786-2 A | Regulator Patrol Inspection | Regulator As Left Counter | 44399 | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1436 | Regulator | 786-2 A | Regulator Patrol Inspection | Reg Output Voltage Level | 125.4 | volts |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1436 | Regulator | 786-2 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1436 | Regulator | 786-2 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1436 | Regulator | 786-2 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1436 | Regulator | 786-2 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1436 | Regulator | 786-2 A | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 2/7/2023 15:07 | Distribution | Simpsonville Quarterly Inspection | R1436 | Regulator | 786-2 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF001292 | PowerFuse | ET-1421 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF001292 | PowerFuse | ET-1421 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF001292 | PowerFuse | ET-1421 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BAT001592 | Battery | ET-Battery Bank 48V | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Readings | Operations Counter AL | 131 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Readings | Operations Counter AF | 131 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Readings | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BAT001592 | Battery | ET-Battery Bank 48V | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BAT001592 | Battery | ET-Battery Bank 48V | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BAT001592 | Battery | ET-Battery Bank 48V | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BAT001592 | Battery | ET-Battery Bank 48V | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BAT001592 | Battery | ET-Battery Bank 48V | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BAT001592 | Battery | ET-Battery Bank 48V | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BAT001592 | Battery | ET-Battery Bank 48V | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BAT001592 | Battery | ET-Battery Bank 48V | Battery Patrol Inspection | All Connections OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF001293 | PowerFuse | ET-1422 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF001293 | PowerFuse | ET-1422 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF001293 | PowerFuse | ET-1422 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Readings | Amps C Ø | 168.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Readings | Amps B Ø | 119.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF001294 | PowerFuse | ET-1423 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF001294 | PowerFuse | ET-1423 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF001294 | PowerFuse | ET-1423 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Readings | Amps A Ø | 136.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0532 | Regulator | 510-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0532 | Regulator | 510-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0532 | Regulator | 510-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0532 | Regulator | 510-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0532 | Regulator | 510-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0532 | Regulator | 510-1 A | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0532 | Regulator | 510-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0532 | Regulator | 510-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0532 | Regulator | 510-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0532 | Regulator | 510-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0532 | Regulator | 510-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0532 | Regulator | 510-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0532 | Regulator | 510-1 A | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | PF001289 | PowerFuse | BY-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | PF001289 | PowerFuse | BY-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0532 | Regulator | 510-1 A | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0532 | Regulator | 510-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0532 | Regulator | 510-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0532 | Regulator | 510-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0532 | Regulator | 510-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0532 | Regulator | 510-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0532 | Regulator | 510-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 66798 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0532 | Regulator | 510-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0532 | Regulator | 510-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0532 | Regulator | 510-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | WX0358 | RecloserHydraulic | 718-0447 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 3.7 | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | WX0358 | RecloserHydraulic | 718-0447 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 2.8 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Readings | Amps A Ø | 0.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Readings | Amps B Ø | 0.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Readings | Amps C Ø | 0.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Readings | 9 Month Operations | 3 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Readings | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Readings | Operations Counter AF | 165 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Readings | Operations Counter AL | 165 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0177 | NonLTC | 891-1 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0177 | NonLTC | 891-1 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Readings | Switching Operations | 1 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000529 | BreakerVacuum | LS-12KV BUS TIE SEC 5 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Readings | 9 Month Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Readings | Amps A Ø | 0.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Readings | Amps B Ø | 0.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Readings | Amps C Ø | 0.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BAT001592 | Battery | ET-Battery Bank 48V | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0177 | NonLTC | 891-1 C | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0177 | NonLTC | 891-1 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0177 | NonLTC | 891-1 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0177 | NonLTC | 891-1 C | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0177 | NonLTC | 891-1 C | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0177 | NonLTC | 891-1 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0177 | NonLTC | 891-1 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0177 | NonLTC | 891-1 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0177 | NonLTC | 891-1 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0177 | NonLTC | 891-1 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0177 | NonLTC | 891-1 C | NonLTC Transformer Readings | General Comments | | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0177 | NonLTC | 891-1 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0177 | NonLTC | 891-1 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0177 | NonLTC | 891-1 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 95.00 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0177 | NonLTC | 891-1 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0177 | NonLTC | 891-1 C | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0177 | NonLTC | 891-1 C | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0177 | NonLTC | 891-1 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0177 | NonLTC | 891-1 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0177 | NonLTC | 891-1 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0177 | NonLTC | 891-1 C | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0177 | NonLTC | 891-1 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0177 | NonLTC | 891-1 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0177 | NonLTC | 891-1 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BAT001592 | Battery | ET-Battery Bank 48V | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BAT001592 | Battery | ET-Battery Bank 48V | Battery Patrol Inspection | General Comments | | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1347 | Regulator | 888-2 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1347 | Regulator | 888-2 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1347 | Regulator | 888-2 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1347 | Regulator | 888-2 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1347 | Regulator | 888-2 A | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1347 | Regulator | 888-2 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1347 | Regulator | 888-2 A | Regulator Patrol Inspection | Max Tap Position | 4R | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1347 | Regulator | 888-2 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1347 | Regulator | 888-2 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1347 | Regulator | 888-2 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1347 | Regulator | 888-2 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1347 | Regulator | 888-2 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1347 | Regulator | 888-2 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.3 | volts |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1347 | Regulator | 888-2 A | Regulator Patrol Inspection | Regulator As Left Counter | 81514 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1347 | Regulator | 888-2 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1347 | Regulator | 888-2 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1347 | Regulator | 888-2 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 40 | °C |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 50 | °C |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | WithLTC | FL-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Readings | Amps C Ø | 97.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Readings | Amps B Ø | 49.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Readings | Amps A Ø | 90.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Readings | 9 Month Operations | 4 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Readings | Operations Counter AL | 167 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Readings | Operations Counter AF | 167 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Readings | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Readings | Amps C Ø | 47.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Readings | Amps B Ø | 50.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Readings | Amps A Ø | 38.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000524 | BreakerVacuum | LS-1243 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | BAT001029 | Battery | BY-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | WX0358 | RecloserHydraulic | 718-0447 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 2.6 | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | WX0358 | RecloserHydraulic | 718-0447 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | WX0358 | RecloserHydraulic | 718-0447 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | WX0358 | RecloserHydraulic | 718-0447 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | WX0358 | RecloserHydraulic | 718-0447 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | WX0358 | RecloserHydraulic | 718-0447 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000528 | BreakerVacuum | LS-12KV TR 5 | VCB Readings | 9 Month Operations | 1 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF001295 | PowerFuse | ET-1424 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF001295 | PowerFuse | ET-1424 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | PF001295 | PowerFuse | ET-1424 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | WX0358 | RecloserHydraulic | 718-0447 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | WX0358 | RecloserHydraulic | 718-0447 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | WX0358 | RecloserHydraulic | 718-0447 | Recloser Hydraulic Patrol Inspection | Operations Counter | 304 | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | WX0358 | RecloserHydraulic | 718-0447 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 11:29 | Distribution | Poole Quarterly Inspection | WX0358 | RecloserHydraulic | 718-0447 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000530 | BreakerVacuum | LS-LY 12KV BUS TIE | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Readings | Operations Counter AL | 113 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Readings | Operations Counter AF | 113 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Readings | General Comments | | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Readings | LTC Totalizer Reading | 2112.00 | kw |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Readings | Totalizer Meter Reading | .2200 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1347 | Regulator | 888-2 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1347 | Regulator | 888-2 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | B0462 | WithLTC | 559-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Readings | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000526 | BreakerVacuum | LS-1244 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1347 | Regulator | 888-2 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1347 | Regulator | 888-2 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1347 | Regulator | 888-2 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | R1347 | Regulator | 888-2 A | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Readings | General Comments | | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3264.00 | kw |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Readings | Oil Temp Max | 70 | °C |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.3600 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0021 | Regulator | 072-3 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0021 | Regulator | 072-3 B | Regulator Patrol Inspection | Regulator As Left Counter | 57280 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0021 | Regulator | 072-3 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.0 | volts |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0021 | Regulator | 072-3 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0021 | Regulator | 072-3 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0021 | Regulator | 072-3 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0021 | Regulator | 072-3 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0021 | Regulator | 072-3 B | Regulator Patrol Inspection | Min Tap Position | 3L | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0021 | Regulator | 072-3 B | Regulator Patrol Inspection | Max Tap Position | 12R | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0021 | Regulator | 072-3 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0021 | Regulator | 072-3 B | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0021 | Regulator | 072-3 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0021 | Regulator | 072-3 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0021 | Regulator | 072-3 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0021 | Regulator | 072-3 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0021 | Regulator | 072-3 B | Regulator Patrol Inspection | Current Tap Position | 2R | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0021 | Regulator | 072-3 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0021 | Regulator | 072-3 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0021 | Regulator | 072-3 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0021 | Regulator | 072-3 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0021 | Regulator | 072-3 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Readings | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Readings | Operations Counter AF | 181 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Readings | Operations Counter AL | 182 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Readings | Switching Operations | 1 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Readings | 9 Month Operations | 2 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Readings | Amps A Ø | 256.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Readings | Amps B Ø | 268.0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0022 | Regulator | 072-3 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0021 | Regulator | 072-3 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0021 | Regulator | 072-3 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0021 | Regulator | 072-3 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Readings | 9 Month Operations | 2 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Readings | Amps A Ø | 170.0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Readings | Amps B Ø | 170.0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Readings | Amps C Ø | 166.0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Readings | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Readings | Operations Counter AF | 191 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Readings | Operations Counter AL | 192 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Readings | Operations This Read Vac | 2 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Readings | Switching Operations | 2 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000548 | BreakerVacuum | 724-2522 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Readings | 9 Month Operations | 2 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000207 | Switchgear | LS-Swgr Sec 5 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000207 | Switchgear | LS-Swgr Sec 5 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000207 | Switchgear | LS-Swgr Sec 5 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000207 | Switchgear | LS-Swgr Sec 5 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000207 | Switchgear | LS-Swgr Sec 5 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000207 | Switchgear | LS-Swgr Sec 5 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000207 | Switchgear | LS-Swgr Sec 5 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000207 | Switchgear | LS-Swgr Sec 5 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000207 | Switchgear | LS-Swgr Sec 5 | Switchgear Patrol Inspection | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000207 | Switchgear | LS-Swgr Sec 5 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000207 | Switchgear | LS-Swgr Sec 5 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000207 | Switchgear | LS-Swgr Sec 5 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000207 | Switchgear | LS-Swgr Sec 5 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000207 | Switchgear | LS-Swgr Sec 5 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000207 | Switchgear | LS-Swgr Sec 5 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000207 | Switchgear | LS-Swgr Sec 5 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000549 | BreakerVacuum | 724-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | B0260 | NonLTC | 441-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000207 | Switchgear | LS-Swgr Sec 5 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000207 | Switchgear | LS-Swgr Sec 5 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | SWG000207 | Switchgear | LS-Swgr Sec 5 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | RC000483 | RecloserElectronic | 725-0843 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | RC000483 | RecloserElectronic | 725-0843 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | RC000483 | RecloserElectronic | 725-0843 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | RC000483 | RecloserElectronic | 725-0843 | Recloser Electronic Patrol Inspection | Amps C Ø | 18.0 | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | RC000483 | RecloserElectronic | 725-0843 | Recloser Electronic Patrol Inspection | Amps B Ø | 7.0 | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | RC000483 | RecloserElectronic | 725-0843 | Recloser Electronic Patrol Inspection | Amps A Ø | 10.0 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Readings | Unknown Operations | 0 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 33 | °C |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 45 | °C |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 32 | °C |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 45 | °C |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 32 | °C |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 45 | °C |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 31 | °C |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 44 | °C |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 800 | psi |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LT0294 | WithLTC | BY-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Readings | Switching Operations | 1 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | Pressure Vessel Condition | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | Pop-off Valve Tested Date | 2022-05-10 00:00:00.000000 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Readings | Operations This Read Oil | 1 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Readings | Operations Counter AL | 57 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Readings | Operations Counter AF | 57 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Readings | Number of Ops last 9 Months | 1 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Readings | General Comments | | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Readings | Fault Operations | 0 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0669 | Regulator | 510-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0669 | Regulator | 510-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0669 | Regulator | 510-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | TB0189 | BreakerOil | 600-708 | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Readings | Amps C Ø | 252.0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0252 | GroundTransformer | ET-GND TR 1 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0252 | GroundTransformer | ET-GND TR 1 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0669 | Regulator | 510-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0669 | Regulator | 510-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0669 | Regulator | 510-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0669 | Regulator | 510-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0669 | Regulator | 510-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 19887 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0669 | Regulator | 510-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.0 | volts |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0669 | Regulator | 510-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0669 | Regulator | 510-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0669 | Regulator | 510-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0669 | Regulator | 510-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0669 | Regulator | 510-1 C | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0669 | Regulator | 510-1 C | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0669 | Regulator | 510-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0669 | Regulator | 510-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0669 | Regulator | 510-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0669 | Regulator | 510-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0669 | Regulator | 510-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0669 | Regulator | 510-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0669 | Regulator | 510-1 C | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Readings | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0669 | Regulator | 510-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | R0669 | Regulator | 510-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Readings | Operations Counter AF | 221 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Readings | Operations Counter AL | 222 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Readings | Switching Operations | 1 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0252 | GroundTransformer | ET-GND TR 1 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0252 | GroundTransformer | ET-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0252 | GroundTransformer | ET-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0252 | GroundTransformer | ET-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0252 | GroundTransformer | ET-GND TR 1 | Ground Transformer Patrol Inspection | Oil Temp Max | 30 | °C |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0252 | GroundTransformer | ET-GND TR 1 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0252 | GroundTransformer | ET-GND TR 1 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0252 | GroundTransformer | ET-GND TR 1 | Ground Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000550 | BreakerVacuum | 724-2 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | RC000483 | RecloserElectronic | 725-0843 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0252 | GroundTransformer | ET-GND TR 1 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0252 | GroundTransformer | ET-GND TR 1 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0252 | GroundTransformer | ET-GND TR 1 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0252 | GroundTransformer | ET-GND TR 1 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0252 | GroundTransformer | ET-GND TR 1 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | RC000483 | RecloserElectronic | 725-0843 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | RC000483 | RecloserElectronic | 725-0843 | Recloser Electronic Patrol Inspection | Operations Counter | 0 | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | RC000483 | RecloserElectronic | 725-0843 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | RC000483 | RecloserElectronic | 725-0843 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | RC000483 | RecloserElectronic | 725-0843 | Recloser Electronic Patrol Inspection | General Comments | Counters  A-239, B-245, C-263 | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | RC000483 | RecloserElectronic | 725-0843 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | RC000483 | RecloserElectronic | 725-0843 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | RC000483 | RecloserElectronic | 725-0843 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | RC000483 | RecloserElectronic | 725-0843 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | RC000483 | RecloserElectronic | 725-0843 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | RC000483 | RecloserElectronic | 725-0843 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000037 | Regulator | 502-1 B | Regulator Patrol Inspection | Min Tap Position | 13L | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000037 | Regulator | 502-1 B | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000037 | Regulator | 502-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000037 | Regulator | 502-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Readings | Operations Counter AL | 139 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Readings | Operations Counter AF | 139 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Readings | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000037 | Regulator | 502-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000037 | Regulator | 502-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000037 | Regulator | 502-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000037 | Regulator | 502-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000037 | Regulator | 502-1 B | Regulator Patrol Inspection | Current Tap Position | 9L | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000037 | Regulator | 502-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000037 | Regulator | 502-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000037 | Regulator | 502-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000037 | Regulator | 502-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000037 | Regulator | 502-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000036 | Regulator | 502-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000036 | Regulator | 502-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000036 | Regulator | 502-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000036 | Regulator | 502-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000036 | Regulator | 502-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 22627 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000036 | Regulator | 502-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000036 | Regulator | 502-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Readings | Amps C Ø | 0.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Readings | Amps B Ø | 0.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Readings | Amps A Ø | 0.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Readings | 9 Month Operations | 0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BCH001145 | Charger | 888-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BCH001145 | Charger | 888-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BCH001145 | Charger | 888-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BCH001145 | Charger | 888-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BCH001145 | Charger | 888-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BCH001145 | Charger | 888-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BCH001145 | Charger | 888-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | BCH001145 | Charger | 888-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .900 | millivolts |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | BCH001144 | Charger | 640-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | BCH001144 | Charger | 640-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000036 | Regulator | 502-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000036 | Regulator | 502-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000036 | Regulator | 502-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000036 | Regulator | 502-1 A | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000036 | Regulator | 502-1 A | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000036 | Regulator | 502-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000036 | Regulator | 502-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000036 | Regulator | 502-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000036 | Regulator | 502-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000036 | Regulator | 502-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000036 | Regulator | 502-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000036 | Regulator | 502-1 A | Regulator Patrol Inspection | Current Tap Position | 10L | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000036 | Regulator | 502-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | RG000039 | Regulator | 072-3 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | RG000039 | Regulator | 072-3 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | RG000039 | Regulator | 072-3 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | RG000039 | Regulator | 072-3 C | Regulator Patrol Inspection | Regulator As Left Counter | 15703 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | RG000039 | Regulator | 072-3 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.5 | volts |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | RG000039 | Regulator | 072-3 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | RG000039 | Regulator | 072-3 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | RG000039 | Regulator | 072-3 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | RG000039 | Regulator | 072-3 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | RG000039 | Regulator | 072-3 C | Regulator Patrol Inspection | Min Tap Position | 4L | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | RG000039 | Regulator | 072-3 C | Regulator Patrol Inspection | Max Tap Position | 10R | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | RG000039 | Regulator | 072-3 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | RG000039 | Regulator | 072-3 C | Regulator Patrol Inspection | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | RG000039 | Regulator | 072-3 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | RG000039 | Regulator | 072-3 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | RG000039 | Regulator | 072-3 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | RG000039 | Regulator | 072-3 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | RG000039 | Regulator | 072-3 C | Regulator Patrol Inspection | Current Tap Position | 2R | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | RG000039 | Regulator | 072-3 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | RG000039 | Regulator | 072-3 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | RG000039 | Regulator | 072-3 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | RG000039 | Regulator | 072-3 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | RG000039 | Regulator | 072-3 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000038 | Regulator | 502-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000038 | Regulator | 502-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000038 | Regulator | 502-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000038 | Regulator | 502-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000038 | Regulator | 502-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 21707 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000038 | Regulator | 502-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000038 | Regulator | 502-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000038 | Regulator | 502-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000038 | Regulator | 502-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000038 | Regulator | 502-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000038 | Regulator | 502-1 C | Regulator Patrol Inspection | Min Tap Position | 13L | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000038 | Regulator | 502-1 C | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000038 | Regulator | 502-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000038 | Regulator | 502-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000038 | Regulator | 502-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000038 | Regulator | 502-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000038 | Regulator | 502-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000038 | Regulator | 502-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Readings | Amps C Ø | 19.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Readings | Amps B Ø | 20.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Readings | Amps A Ø | 21.0 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000520 | BreakerVacuum | LS-1241 | VCB Readings | 9 Month Operations | 1 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | BK000518 | BreakerVacuum | LS-1240 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000038 | Regulator | 502-1 C | Regulator Patrol Inspection | Current Tap Position | 9L | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000038 | Regulator | 502-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000038 | Regulator | 502-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000038 | Regulator | 502-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000038 | Regulator | 502-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000038 | Regulator | 502-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000037 | Regulator | 502-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000037 | Regulator | 502-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000037 | Regulator | 502-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000037 | Regulator | 502-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000037 | Regulator | 502-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 23870 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000037 | Regulator | 502-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.7 | volts |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000037 | Regulator | 502-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000037 | Regulator | 502-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000037 | Regulator | 502-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000037 | Regulator | 502-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Readings | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Readings | Operations Counter AF | 234 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Readings | Operations Counter AL | 235 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Readings | Switching Operations | 1 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | LTCMechanism | FL-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | LTCMechanism | FL-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | LTCMechanism | FL-TRANS 1 | LTC Counter Readings | General Comments | | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | LTCMechanism | FL-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | LTCMechanism | FL-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 6543 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | LTCMechanism | FL-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | LTCMechanism | FL-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | LTCMechanism | FL-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 5L | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | LTCMechanism | FL-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 16L | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | LTCMechanism | FL-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | LTCMechanism | FL-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 369 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | LTCMechanism | FL-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | LTCMechanism | FL-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0078 | LTCMechanism | FL-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0022 | Regulator | 072-3 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Readings | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Readings | Operations Counter AF | 212 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Readings | Operations Counter AL | 213 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Readings | Switching Operations | 1 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Readings | Unknown Operations | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0022 | Regulator | 072-3 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0022 | Regulator | 072-3 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0022 | Regulator | 072-3 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0022 | Regulator | 072-3 A | Regulator Patrol Inspection | Regulator As Left Counter | 60778 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0022 | Regulator | 072-3 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.0 | volts |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0022 | Regulator | 072-3 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0022 | Regulator | 072-3 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0022 | Regulator | 072-3 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0022 | Regulator | 072-3 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0022 | Regulator | 072-3 A | Regulator Patrol Inspection | Min Tap Position | 2L | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0022 | Regulator | 072-3 A | Regulator Patrol Inspection | Max Tap Position | 12R | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0022 | Regulator | 072-3 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0022 | Regulator | 072-3 A | Regulator Patrol Inspection | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0022 | Regulator | 072-3 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0022 | Regulator | 072-3 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0022 | Regulator | 072-3 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0022 | Regulator | 072-3 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0022 | Regulator | 072-3 A | Regulator Patrol Inspection | Current Tap Position | 3R | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0022 | Regulator | 072-3 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0022 | Regulator | 072-3 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0022 | Regulator | 072-3 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | KR0022 | Regulator | 072-3 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000036 | Regulator | 502-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000036 | Regulator | 502-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000036 | Regulator | 502-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | RG000036 | Regulator | 502-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | BCH001144 | Charger | 640-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | BCH001144 | Charger | 640-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | BCH001144 | Charger | 640-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | BCH001144 | Charger | 640-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | BCH001144 | Charger | 640-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .900 | millivolts |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | LTCC000754 | LTCControl | 585-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | LTCC000754 | LTCControl | 585-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | LTCC000754 | LTCControl | 585-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | LTCC000754 | LTCControl | 585-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0315 | NonLTC | 510-1 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0315 | NonLTC | 510-1 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | LTCC000754 | LTCControl | 585-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | LTCC000754 | LTCControl | 585-1 | LTC Control Insp | General Comments | | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | LTCC000754 | LTCControl | 585-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | LTCC000754 | LTCControl | 585-1 | LTC Control Insp | All Connections OK? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0315 | NonLTC | 510-1 C | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0315 | NonLTC | 510-1 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0315 | NonLTC | 510-1 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0315 | NonLTC | 510-1 C | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0315 | NonLTC | 510-1 C | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0315 | NonLTC | 510-1 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0315 | NonLTC | 510-1 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0315 | NonLTC | 510-1 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0315 | NonLTC | 510-1 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0315 | NonLTC | 510-1 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0315 | NonLTC | 510-1 C | NonLTC Transformer Readings | General Comments | | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0315 | NonLTC | 510-1 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0315 | NonLTC | 510-1 C | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.2 | psi |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0315 | NonLTC | 510-1 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0315 | NonLTC | 510-1 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0315 | NonLTC | 510-1 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0315 | NonLTC | 510-1 C | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0315 | NonLTC | 510-1 C | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0315 | NonLTC | 510-1 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0315 | NonLTC | 510-1 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0315 | NonLTC | 510-1 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0315 | NonLTC | 510-1 C | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0315 | NonLTC | 510-1 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0315 | NonLTC | 510-1 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0315 | NonLTC | 510-1 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Readings | 9 Month Operations | 2 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Readings | Amps A Ø | 275.0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Readings | Amps B Ø | 268.0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Readings | Amps C Ø | 256.0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Readings | 9 Month Operations | 1 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | KB0003 | BreakerVacuum | 724-1 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Readings | Amps A Ø | 76.0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Readings | Amps B Ø | 100.0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | BK000547 | BreakerVacuum | 724-2533 | VCB Readings | Amps C Ø | 85.0 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000515 | RecloserElectronic | 891-0718 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000515 | RecloserElectronic | 891-0718 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Readings | Amps C Ø | 0.0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Readings | Amps B Ø | 0.0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Readings | Amps A Ø | 0.0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Readings | Accumulated Fault Duty C Ph V | 7.12 | % |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Readings | Accumulated Fault Duty B Ph V | 4.61 | % |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000086 | Switchgear | ET-Swgr Sec 6 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000086 | Switchgear | ET-Swgr Sec 6 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Readings | General Comments | | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000086 | Switchgear | ET-Swgr Sec 6 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000086 | Switchgear | ET-Swgr Sec 6 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000086 | Switchgear | ET-Swgr Sec 6 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000086 | Switchgear | ET-Swgr Sec 6 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000086 | Switchgear | ET-Swgr Sec 6 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000086 | Switchgear | ET-Swgr Sec 6 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000086 | Switchgear | ET-Swgr Sec 6 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000086 | Switchgear | ET-Swgr Sec 6 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | YD000617 | Yard | DE-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | YD000617 | Yard | DE-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | YD000617 | Yard | DE-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | YD000617 | Yard | DE-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | YD000617 | Yard | DE-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | YD000617 | Yard | DE-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | YD000617 | Yard | DE-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | YD000617 | Yard | DE-Yard | Yard Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000086 | Switchgear | ET-Swgr Sec 6 | Switchgear Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000086 | Switchgear | ET-Swgr Sec 6 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000086 | Switchgear | ET-Swgr Sec 6 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000086 | Switchgear | ET-Swgr Sec 6 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000086 | Switchgear | ET-Swgr Sec 6 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000086 | Switchgear | ET-Swgr Sec 6 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000086 | Switchgear | ET-Swgr Sec 6 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000086 | Switchgear | ET-Swgr Sec 6 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | SWG000086 | Switchgear | ET-Swgr Sec 6 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Readings | Amps C Ø | 64.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1258 | BreakerVacuum | BY-1280 | VCB Readings | 9 Month Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1258 | BreakerVacuum | BY-1280 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1258 | BreakerVacuum | BY-1280 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1258 | BreakerVacuum | BY-1280 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1258 | BreakerVacuum | BY-1280 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1258 | BreakerVacuum | BY-1280 | VCB Readings | Amps A Ø | 0.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1258 | BreakerVacuum | BY-1280 | VCB Readings | Amps B Ø | 0.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1258 | BreakerVacuum | BY-1280 | VCB Readings | Amps C Ø | 0.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1258 | BreakerVacuum | BY-1280 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1258 | BreakerVacuum | BY-1280 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1258 | BreakerVacuum | BY-1280 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1258 | BreakerVacuum | BY-1280 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | YD000232 | Yard | 502-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | YD000232 | Yard | 502-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | YD000232 | Yard | 502-Yard | Yard Patrol Inspection | Ambient Temp | 65 | °F |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1258 | BreakerVacuum | BY-1280 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1258 | BreakerVacuum | BY-1280 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1258 | BreakerVacuum | BY-1280 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1258 | BreakerVacuum | BY-1280 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1258 | BreakerVacuum | BY-1280 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1258 | BreakerVacuum | BY-1280 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1258 | BreakerVacuum | BY-1280 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1258 | BreakerVacuum | BY-1280 | VCB Readings | General Comments | | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000515 | RecloserElectronic | 891-0718 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000515 | RecloserElectronic | 891-0718 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000515 | RecloserElectronic | 891-0718 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000515 | RecloserElectronic | 891-0718 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Readings | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Readings | Operations Counter AF | 119 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000515 | RecloserElectronic | 891-0718 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | LTCMechanism | 670-1 | LTC Counter Readings | LTC As Left Counter | 68580 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | LTCMechanism | 670-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | LTCMechanism | 670-1 | LTC Counter Readings | LTC Current Tap Position | 8R | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | LTCMechanism | 670-1 | LTC Counter Readings | LTC Max Tap Position | 16R | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | LTCMechanism | 670-1 | LTC Counter Readings | LTC Min Tap Position | 6L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | LTCMechanism | 670-1 | LTC Counter Readings | LTC Operations Since Last Insp | 572 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | LTCMechanism | 670-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | LTCMechanism | 670-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | LTCMechanism | 670-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1254 | BreakerVacuum | BY-1276 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1254 | BreakerVacuum | BY-1276 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1254 | BreakerVacuum | BY-1276 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1254 | BreakerVacuum | BY-1276 | VCB Readings | Operations Counter AL | 209 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1254 | BreakerVacuum | BY-1276 | VCB Readings | Operations Counter AF | 209 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | ST000481 | Structure | 724-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | ST000481 | Structure | 724-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | ST000481 | Structure | 724-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | ST000481 | Structure | 724-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | ST000481 | Structure | 724-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | ST000481 | Structure | 724-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | ST000481 | Structure | 724-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1254 | BreakerVacuum | BY-1276 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1254 | BreakerVacuum | BY-1276 | VCB Readings | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1254 | BreakerVacuum | BY-1276 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1254 | BreakerVacuum | BY-1276 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1254 | BreakerVacuum | BY-1276 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1254 | BreakerVacuum | BY-1276 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1254 | BreakerVacuum | BY-1276 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1254 | BreakerVacuum | BY-1276 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1254 | BreakerVacuum | BY-1276 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1254 | BreakerVacuum | BY-1276 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1254 | BreakerVacuum | BY-1276 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1254 | BreakerVacuum | BY-1276 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1254 | BreakerVacuum | BY-1276 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1254 | BreakerVacuum | BY-1276 | VCB Readings | Amps C Ø | 170.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1254 | BreakerVacuum | BY-1276 | VCB Readings | Amps B Ø | 172.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1254 | BreakerVacuum | BY-1276 | VCB Readings | Amps A Ø | 175.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1254 | BreakerVacuum | BY-1276 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1254 | BreakerVacuum | BY-1276 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1254 | BreakerVacuum | BY-1276 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1254 | BreakerVacuum | BY-1276 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1254 | BreakerVacuum | BY-1276 | VCB Readings | 9 Month Operations | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | ST000481 | Structure | 724-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | ST000481 | Structure | 724-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | ST000481 | Structure | 724-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | ST000481 | Structure | 724-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | ST000481 | Structure | 724-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | ST000481 | Structure | 724-Structure | Structure Patrol Inspection | General Comments | | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | ST000481 | Structure | 724-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | ST000481 | Structure | 724-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | ST000481 | Structure | 724-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | ST000481 | Structure | 724-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | ST000481 | Structure | 724-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | ST000481 | Structure | 724-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | ST000481 | Structure | 724-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | ST000481 | Structure | 724-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | ST000249 | Structure | 725-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | ST000249 | Structure | 725-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | ST000249 | Structure | 725-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | YD000206 | Yard | 492-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | YD000206 | Yard | 492-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | ST000249 | Structure | 725-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | ST000249 | Structure | 725-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | ST000249 | Structure | 725-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | YD000617 | Yard | DE-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | YD000617 | Yard | DE-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | YD000617 | Yard | DE-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | YD000617 | Yard | DE-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | YD000617 | Yard | DE-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | YD000617 | Yard | DE-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | YD000617 | Yard | DE-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | YD000617 | Yard | DE-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | ST000249 | Structure | 725-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Readings | Switching Operations | 4 | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3965.76 | kw |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Readings | Operations Counter AL | 119 | |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | YD000617 | Yard | DE-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Readings | Oil Temp Max | 70 | °C |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | ST000249 | Structure | 725-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Readings | Accumulated Fault Duty A Ph V | 7.54 | % |
| 2/8/2023 5:04 | Distribution | Del Park Quarterly Inspection | YD000617 | Yard | DE-Yard | Yard Patrol Inspection | Ambient Temp | 51 | °F |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Readings | Unknown Operations | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | ST000249 | Structure | 725-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | ST000249 | Structure | 725-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | ST000249 | Structure | 725-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | ST000249 | Structure | 725-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | ST000249 | Structure | 725-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | ST000249 | Structure | 725-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | ST000249 | Structure | 725-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | ST000249 | Structure | 725-Structure | Structure Patrol Inspection | General Comments | | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Readings | Operations This Read Vac | 4 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Readings | Operations Counter AL | 132 | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 2/7/2023 10:40 | Distribution | Bromley Quarterly Inspection | B0211 | NonLTC | 029-5 | NonLTC Transformer Readings | Totalizer Meter Reading | .8262 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000515 | RecloserElectronic | 891-0718 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | ST000249 | Structure | 725-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Readings | 9 Month Operations | 5 | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | LTCMechanism | 670-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | LTCMechanism | 670-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | LTCMechanism | 670-1 | LTC Counter Readings | General Comments | | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | LTCMechanism | 670-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | W0318 | LTCMechanism | 670-1 | LTC Counter Readings | LTC As Found Counter | 68580 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | LTCC000876 | LTCControl | 559-1 | LTC Control Insp | General Comments | | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | LTCC000876 | LTCControl | 559-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Readings | Amps B Ø | 112.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Readings | Amps C Ø | 113.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Readings | Fault Adjusted Amps B Phase V | 24.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Readings | Fault Operations B Ø | 3 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Readings | General Comments | B phase TOC | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | LTCC000876 | LTCControl | 559-1 | LTC Control Insp | All Connections OK? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0122 | Regulator | 891-1 B | Regulator Patrol Inspection | Current Tap Position | 8R | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0122 | Regulator | 891-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0122 | Regulator | 891-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0122 | Regulator | 891-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0122 | Regulator | 891-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0122 | Regulator | 891-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0122 | Regulator | 891-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0122 | Regulator | 891-1 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0122 | Regulator | 891-1 B | Regulator Patrol Inspection | Min Tap Position | 12R | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0122 | Regulator | 891-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0122 | Regulator | 891-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0122 | Regulator | 891-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | YD000206 | Yard | 492-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | YD000206 | Yard | 492-Yard | Yard Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Readings | Operations Counter AF | 27 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Readings | Operations Counter AL | 27 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Readings | Operations This Read Vac | 3 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Readings | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0122 | Regulator | 891-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | CX0643 | RecloserHydraulic | 785-0731 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 91 | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | CX0643 | RecloserHydraulic | 785-0731 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 5.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Readings | Operations Counter AF | 36 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Readings | Operations Counter AL | 36 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Readings | Unknown Operations | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Readings | 9 Month Operations | 3 | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | CX0643 | RecloserHydraulic | 785-0731 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 5.0 | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | CX0643 | RecloserHydraulic | 785-0731 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 5.0 | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | CX0643 | RecloserHydraulic | 785-0731 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 65 | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | CX0643 | RecloserHydraulic | 785-0731 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | YD000206 | Yard | 492-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | YD000206 | Yard | 492-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Readings | Accumulated Fault Duty A Ph V | 5.44 | % |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Readings | Accumulated Fault Duty B Ph V | 4.19 | % |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Readings | Accumulated Fault Duty C Ph V | 14.65 | % |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Readings | Amps A Ø | 2.0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Readings | Amps B Ø | 1.0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Readings | Amps C Ø | 5.0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Readings | 9 Month Operations | 12 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002127 | BreakerVacuum | ET-1422 | VCB Readings | Amps A Ø | 107.0 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | LTCC000876 | LTCControl | 559-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | LTCC000876 | LTCControl | 559-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | LTCC000876 | LTCControl | 559-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | LTCC000876 | LTCControl | 559-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001184 | BreakerVacuum | C-1345 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | LTCC000876 | LTCControl | 559-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | BAT001612 | Battery | 510-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | LTCM000034 | LTCMechanism | 559-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | LTCM000034 | LTCMechanism | 559-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | LTCM000034 | LTCMechanism | 559-1 | LTC Counter Readings | General Comments | | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | LTCM000034 | LTCMechanism | 559-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | LTCM000034 | LTCMechanism | 559-1 | LTC Counter Readings | LTC As Found Counter | 260409 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | LTCM000034 | LTCMechanism | 559-1 | LTC Counter Readings | LTC As Left Counter | 260409 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | LTCM000034 | LTCMechanism | 559-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | LTCM000034 | LTCMechanism | 559-1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | LTCM000034 | LTCMechanism | 559-1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | LTCM000034 | LTCMechanism | 559-1 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | LTCM000034 | LTCMechanism | 559-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | LTCM000034 | LTCMechanism | 559-1 | LTC Counter Readings | LTC Operations Since Last Insp | 60 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | LTCM000034 | LTCMechanism | 559-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | LTCM000034 | LTCMechanism | 559-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | LTCM000034 | LTCMechanism | 559-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | CX0643 | RecloserHydraulic | 785-0731 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | CX0643 | RecloserHydraulic | 785-0731 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | CX0643 | RecloserHydraulic | 785-0731 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | CX0643 | RecloserHydraulic | 785-0731 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | CX0643 | RecloserHydraulic | 785-0731 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | CX0643 | RecloserHydraulic | 785-0731 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000870 | BreakerVacuum | ET-1170 | VCB Readings | Operations Counter AF | 117 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000870 | BreakerVacuum | ET-1170 | VCB Readings | Operations Counter AL | 117 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0122 | Regulator | 891-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0122 | Regulator | 891-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0122 | Regulator | 891-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0122 | Regulator | 891-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Readings | 9 Month Operations | 11 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Readings | 9 Month Operations VCB New | 11 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000870 | BreakerVacuum | ET-1170 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000870 | BreakerVacuum | ET-1170 | VCB Readings | Switching Operations | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Readings | Unknown Operations | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Readings | Amps A Ø | 70.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002128 | BreakerVacuum | ET-1423 | VCB Readings | Amps B Ø | 62.0 | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | YD000232 | Yard | 502-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | YD000232 | Yard | 502-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | YD000232 | Yard | 502-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | YD000232 | Yard | 502-Yard | Yard Patrol Inspection | General Comments | | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | YD000232 | Yard | 502-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | YD000232 | Yard | 502-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | YD000232 | Yard | 502-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | YD000232 | Yard | 502-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | YD000232 | Yard | 502-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/7/2023 13:12 | Distribution | Dixon Quarterly Inspection | YD000232 | Yard | 502-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Readings | Operations This Read Vac | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Readings | Operations Counter AL | 125 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Readings | Operations Counter AF | 125 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0100 | Regulator | 891-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0100 | Regulator | 891-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0100 | Regulator | 891-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0100 | Regulator | 891-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0100 | Regulator | 891-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Readings | Maintenance Operations | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000482 | BreakerVacuum | 072-0283 | VCB Readings | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Readings | Fault Adjusted Amps C Phase V | 7.85 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Readings | Fault Operations C Ø | 1 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Readings | Fault Operations Ground | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | PF001325 | PowerFuse | LS-12KV TR 5 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | PF001325 | PowerFuse | LS-12KV TR 5 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | PF001325 | PowerFuse | LS-12KV TR 5 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | CX0643 | RecloserHydraulic | 785-0731 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | CX0643 | RecloserHydraulic | 785-0731 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 84 | |
| 2/7/2023 10:50 | Distribution | Sparta Quarterly Inspection | CX0643 | RecloserHydraulic | 785-0731 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000870 | BreakerVacuum | ET-1170 | VCB Readings | 9 Month Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000870 | BreakerVacuum | ET-1170 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000870 | BreakerVacuum | ET-1170 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000870 | BreakerVacuum | ET-1170 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Patrol Inspection | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Readings | General Comments | | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Readings | Maintenance Operations | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Readings | Operations Counter AF | 160 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Readings | Operations Counter AL | 160 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000870 | BreakerVacuum | ET-1170 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Readings | Operations This Read Vac | 1 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Readings | Switching Operations | 0 | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 11:49 | Distribution | Dorchester Quarterly Inspection | BK000560 | BreakerVacuum | 072-0282 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000870 | BreakerVacuum | ET-1170 | VCB Readings | Amps A Ø | 100.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000870 | BreakerVacuum | ET-1170 | VCB Readings | Amps B Ø | 72.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000870 | BreakerVacuum | ET-1170 | VCB Readings | Amps C Ø | 63.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000870 | BreakerVacuum | ET-1170 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0122 | Regulator | 891-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0122 | Regulator | 891-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0122 | Regulator | 891-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 31432 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000870 | BreakerVacuum | ET-1170 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000870 | BreakerVacuum | ET-1170 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000870 | BreakerVacuum | ET-1170 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000870 | BreakerVacuum | ET-1170 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000870 | BreakerVacuum | ET-1170 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000870 | BreakerVacuum | ET-1170 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000870 | BreakerVacuum | ET-1170 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000870 | BreakerVacuum | ET-1170 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000870 | BreakerVacuum | ET-1170 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000870 | BreakerVacuum | ET-1170 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000870 | BreakerVacuum | ET-1170 | VCB Readings | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000870 | BreakerVacuum | ET-1170 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | BAT001612 | Battery | 510-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | BAT001612 | Battery | 510-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | BAT001612 | Battery | 510-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.5 | VDC |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | BAT001612 | Battery | 510-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.5 | VDC |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | BAT001612 | Battery | 510-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | BAT001612 | Battery | 510-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | BAT001612 | Battery | 510-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | BAT001612 | Battery | 510-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | BAT001612 | Battery | 510-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | BAT001612 | Battery | 510-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | BAT001612 | Battery | 510-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 54 | °F |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 230.88 | kw |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.5 | psi |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Readings | General Comments | | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | YD000062 | Yard | 890-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | YD000062 | Yard | 890-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | YD000062 | Yard | 890-Yard | Yard Patrol Inspection | General Comments | | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | YD000062 | Yard | 890-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | YD000062 | Yard | 890-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | YD000062 | Yard | 890-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | YD000062 | Yard | 890-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | YD000614 | Yard | FL-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | YD000614 | Yard | FL-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | YD000614 | Yard | FL-Yard | Yard Patrol Inspection | Oil stop valve operational? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | YD000614 | Yard | FL-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | YD000614 | Yard | FL-Yard | Yard Patrol Inspection | General Comments | | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | YD000614 | Yard | FL-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | YD000614 | Yard | FL-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | YD000614 | Yard | FL-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | YD000614 | Yard | FL-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | YD000614 | Yard | FL-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | YD000614 | Yard | FL-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0579 | Regulator | 441-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001182 | BreakerVacuum | C-1306 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0579 | Regulator | 441-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | YD000614 | Yard | FL-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | YD000614 | Yard | FL-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | YD000614 | Yard | FL-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Readings | Amps C Ø | 85.0 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Readings | Amps B Ø | 79.0 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Readings | Amps A Ø | 68.0 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | LTCMechanism | C-TRANS 3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | LTCMechanism | C-TRANS 3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | LTCMechanism | C-TRANS 3 | LTC Counter Readings | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | LTCMechanism | C-TRANS 3 | LTC Mechanism Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | LTCMechanism | C-TRANS 3 | LTC Counter Readings | LTC As Found Counter | 93290 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | LTCMechanism | C-TRANS 3 | LTC Counter Readings | LTC As Left Counter | 93290 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | LTCMechanism | C-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | LTCMechanism | C-TRANS 3 | LTC Counter Readings | LTC Current Tap Position | 4 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | LTCMechanism | C-TRANS 3 | LTC Counter Readings | LTC Operations Since Last Insp | 34 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | LTCMechanism | C-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | LT0028 | LTCMechanism | C-TRANS 3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | SWG000013 | Switchgear | FL-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | YD000614 | Yard | FL-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | YD000614 | Yard | FL-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | SWG000013 | Switchgear | FL-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | SWG000013 | Switchgear | FL-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | SWG000013 | Switchgear | FL-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | SWG000013 | Switchgear | FL-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | SWG000013 | Switchgear | FL-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | SWG000013 | Switchgear | FL-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | SWG000013 | Switchgear | FL-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | SWG000013 | Switchgear | FL-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | SWG000013 | Switchgear | FL-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | SWG000013 | Switchgear | FL-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | SWG000013 | Switchgear | FL-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | SWG000013 | Switchgear | FL-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | SWG000013 | Switchgear | FL-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | SWG000013 | Switchgear | FL-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | SWG000013 | Switchgear | FL-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | SWG000013 | Switchgear | FL-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Readings | 9 Month Operations | 1 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | SWG000013 | Switchgear | FL-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | SWG000013 | Switchgear | FL-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .2886 | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 800 | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | B0321 | NonLTC | 725-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000872 | BreakerVacuum | ET-1172 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000872 | BreakerVacuum | ET-1172 | VCB Readings | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1258 | BreakerVacuum | BY-1280 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1258 | BreakerVacuum | BY-1280 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000872 | BreakerVacuum | ET-1172 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0578 | Regulator | 441-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0578 | Regulator | 441-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 96545 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0578 | Regulator | 441-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0578 | Regulator | 441-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1258 | BreakerVacuum | BY-1280 | VCB Readings | Operations Counter AL | 131 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1258 | BreakerVacuum | BY-1280 | VCB Readings | Operations Counter AF | 131 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1258 | BreakerVacuum | BY-1280 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Readings | Amps C Ø | 0.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Readings | Amps B Ø | 0.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Readings | Amps A Ø | 0.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0578 | Regulator | 441-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0578 | Regulator | 441-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0578 | Regulator | 441-1 B | Regulator Patrol Inspection | Min Tap Position | 3L | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Readings | 9 Month Operations | 8 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Readings | 9 Month Operations VCB New | 8 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0578 | Regulator | 441-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0578 | Regulator | 441-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0578 | Regulator | 441-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0578 | Regulator | 441-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0578 | Regulator | 441-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | FE000610 | Fence | FL-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | FE000610 | Fence | FL-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | FE000610 | Fence | FL-Fence | Fence Patrol Inspection | General Comments | | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | FE000610 | Fence | FL-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0578 | Regulator | 441-1 B | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0578 | Regulator | 441-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0578 | Regulator | 441-1 B | Regulator Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0578 | Regulator | 441-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000872 | BreakerVacuum | ET-1172 | VCB Readings | Operations Counter AF | 119 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000872 | BreakerVacuum | ET-1172 | VCB Readings | Operations Counter AL | 119 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000872 | BreakerVacuum | ET-1172 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | BCH001533 | Charger | 510-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | BCH001533 | Charger | 510-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | FE000610 | Fence | FL-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | FE000610 | Fence | FL-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | FE000610 | Fence | FL-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | FE000610 | Fence | FL-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | FE000610 | Fence | FL-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | FE000610 | Fence | FL-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | FE000610 | Fence | FL-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | FE000610 | Fence | FL-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | FE000610 | Fence | FL-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | FE000610 | Fence | FL-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | FE000610 | Fence | FL-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | FE000610 | Fence | FL-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0578 | Regulator | 441-1 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0578 | Regulator | 441-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0578 | Regulator | 441-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0578 | Regulator | 441-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | BCH001533 | Charger | 510-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | BCH001533 | Charger | 510-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0579 | Regulator | 441-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0579 | Regulator | 441-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | YD000614 | Yard | FL-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0579 | Regulator | 441-1 C | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0579 | Regulator | 441-1 C | Regulator Patrol Inspection | Max Tap Position | 1L | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0579 | Regulator | 441-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | YD000062 | Yard | 890-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | YD000062 | Yard | 890-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | YD000062 | Yard | 890-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | YD000062 | Yard | 890-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | YD000062 | Yard | 890-Yard | Yard Patrol Inspection | Ambient Temp | 31 | °F |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0579 | Regulator | 441-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0579 | Regulator | 441-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0579 | Regulator | 441-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0579 | Regulator | 441-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0579 | Regulator | 441-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000872 | BreakerVacuum | ET-1172 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | BCH001533 | Charger | 510-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.200 | millivolts |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | BCH001533 | Charger | 510-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.1 | VDC |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | BCH001533 | Charger | 510-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.1 | VDC |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | BCH001533 | Charger | 510-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .4 | amps |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000872 | BreakerVacuum | ET-1172 | VCB Readings | 9 Month Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000872 | BreakerVacuum | ET-1172 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0579 | Regulator | 441-1 C | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0579 | Regulator | 441-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0579 | Regulator | 441-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0579 | Regulator | 441-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | YD000614 | Yard | FL-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | YD000614 | Yard | FL-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | YD000614 | Yard | FL-Yard | Yard Patrol Inspection | Ambient Temp | 40 | °F |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Readings | General Comments | | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Readings | Operations Counter AF | 194 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Readings | Operations Counter AL | 196 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Readings | Operations This Read Vac | 2 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Readings | Switching Operations | 2 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0579 | Regulator | 441-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0579 | Regulator | 441-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0578 | Regulator | 441-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB1258 | BreakerVacuum | BY-1280 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000872 | BreakerVacuum | ET-1172 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000872 | BreakerVacuum | ET-1172 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000872 | BreakerVacuum | ET-1172 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000872 | BreakerVacuum | ET-1172 | VCB Readings | Amps A Ø | 70.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000872 | BreakerVacuum | ET-1172 | VCB Readings | Amps B Ø | 75.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000872 | BreakerVacuum | ET-1172 | VCB Readings | Amps C Ø | 72.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000872 | BreakerVacuum | ET-1172 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0578 | Regulator | 441-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000872 | BreakerVacuum | ET-1172 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000872 | BreakerVacuum | ET-1172 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000872 | BreakerVacuum | ET-1172 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000872 | BreakerVacuum | ET-1172 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000872 | BreakerVacuum | ET-1172 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000872 | BreakerVacuum | ET-1172 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000872 | BreakerVacuum | ET-1172 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000872 | BreakerVacuum | ET-1172 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000872 | BreakerVacuum | ET-1172 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0100 | Regulator | 891-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Readings | Amps C Ø | 40.0 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Readings | Amps B Ø | 60.0 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Readings | Amps A Ø | 60.0 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | YD000321 | Yard | 510-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | YD000321 | Yard | 510-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | YD000321 | Yard | 510-Yard | Yard Patrol Inspection | General Comments | | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | YD000321 | Yard | 510-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | YD000321 | Yard | 510-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | YD000321 | Yard | 510-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | YD000321 | Yard | 510-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | YD000321 | Yard | 510-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | YD000321 | Yard | 510-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | YD000321 | Yard | 510-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Readings | 9 Month Operations VCB New | 18 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Readings | 9 Month Operations | 22 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Readings | Switching Operations | 1 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0100 | Regulator | 891-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0100 | Regulator | 891-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | YD000321 | Yard | 510-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | YD000321 | Yard | 510-Yard | Yard Patrol Inspection | Ambient Temp | 54 | °F |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0100 | Regulator | 891-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0100 | Regulator | 891-1 A | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0100 | Regulator | 891-1 A | Regulator Patrol Inspection | Min Tap Position | 11R | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0100 | Regulator | 891-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0100 | Regulator | 891-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0100 | Regulator | 891-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0100 | Regulator | 891-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Readings | Operations Counter AL | 206 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Readings | Operations Counter AF | 205 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0100 | Regulator | 891-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.0 | volts |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0100 | Regulator | 891-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 31998 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0100 | Regulator | 891-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0100 | Regulator | 891-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | YD000206 | Yard | 492-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | YD000206 | Yard | 492-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | YD000206 | Yard | 492-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | ST000481 | Structure | 724-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | YD000321 | Yard | 510-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | YD000321 | Yard | 510-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | YD000206 | Yard | 492-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | YD000206 | Yard | 492-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | YD000206 | Yard | 492-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/7/2023 14:08 | Distribution | Uniontown Quarterly Inspection | YD000206 | Yard | 492-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | ST000249 | Structure | 725-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | ST000249 | Structure | 725-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | ST000249 | Structure | 725-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | ST000249 | Structure | 725-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000515 | RecloserElectronic | 891-0718 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | n | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000515 | RecloserElectronic | 891-0718 | Recloser Electronic Patrol Inspection | Amps C Ø | 60.0 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000515 | RecloserElectronic | 891-0718 | Recloser Electronic Patrol Inspection | Amps B Ø | 60.0 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | RC000515 | RecloserElectronic | 891-0718 | Recloser Electronic Patrol Inspection | Amps A Ø | 60.0 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0100 | Regulator | 891-1 A | Regulator Patrol Inspection | Current Tap Position | 7R | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0100 | Regulator | 891-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Readings | Operations Counter AF | 128 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | FE000149 | Fence | 640-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | FE000149 | Fence | 640-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | FE000149 | Fence | 640-Fence | Fence Patrol Inspection | General Comments | | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | FE000149 | Fence | 640-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | FE000149 | Fence | 640-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | FE000149 | Fence | 640-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | FE000149 | Fence | 640-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | FE000149 | Fence | 640-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Readings | General Comments | | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0100 | Regulator | 891-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | FE000149 | Fence | 640-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | FE000149 | Fence | 640-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | FE000149 | Fence | 640-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | FE000149 | Fence | 640-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | FE000149 | Fence | 640-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | FE000149 | Fence | 640-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | FE000149 | Fence | 640-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/7/2023 9:08 | Distribution | Zion Quarterly Inspection | FE000149 | Fence | 640-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Readings | Operations Counter AL | 11 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Readings | Operations Counter AF | 11 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:04 | Distribution | Shadrack Quarterly Inspection | BB0262 | BreakerVacuum | 600-0476 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1251 | Regulator | 725-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1251 | Regulator | 725-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1251 | Regulator | 725-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1251 | Regulator | 725-1 C | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1251 | Regulator | 725-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1251 | Regulator | 725-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1251 | Regulator | 725-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1251 | Regulator | 725-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0579 | Regulator | 441-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0579 | Regulator | 441-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0579 | Regulator | 441-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | R0579 | Regulator | 441-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 84531 | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1251 | Regulator | 725-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1251 | Regulator | 725-1 C | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1251 | Regulator | 725-1 C | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1251 | Regulator | 725-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1251 | Regulator | 725-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1251 | Regulator | 725-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1251 | Regulator | 725-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1251 | Regulator | 725-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1251 | Regulator | 725-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 274503 | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1251 | Regulator | 725-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1251 | Regulator | 725-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1251 | Regulator | 725-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1251 | Regulator | 725-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | ST000601 | Structure | FL-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | ST000601 | Structure | FL-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | ST000601 | Structure | FL-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | ST000601 | Structure | FL-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | ST000601 | Structure | FL-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | ST000601 | Structure | FL-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | ST000601 | Structure | FL-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | ST000601 | Structure | FL-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | ST000601 | Structure | FL-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | ST000601 | Structure | FL-Structure | Structure Patrol Inspection | General Comments | | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | ST000601 | Structure | FL-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | ST000601 | Structure | FL-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | ST000601 | Structure | FL-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | ST000601 | Structure | FL-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | ST000601 | Structure | FL-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | ST000601 | Structure | FL-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | ST000601 | Structure | FL-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Readings | Amps A Ø | 43.0 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Readings | Amps B Ø | 42.0 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Readings | Amps C Ø | 24.0 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0100 | Regulator | 891-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0100 | Regulator | 891-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000871 | BreakerVacuum | ET-1171 | VCB Readings | 9 Month Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000871 | BreakerVacuum | ET-1171 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000871 | BreakerVacuum | ET-1171 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000871 | BreakerVacuum | ET-1171 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000871 | BreakerVacuum | ET-1171 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000871 | BreakerVacuum | ET-1171 | VCB Readings | Amps A Ø | 109.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000871 | BreakerVacuum | ET-1171 | VCB Readings | Amps B Ø | 113.0 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Readings | General Comments | | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001183 | BreakerVacuum | C-1340 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Readings | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Readings | Fault Operations Ground | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000871 | BreakerVacuum | ET-1171 | VCB Readings | Amps C Ø | 107.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000871 | BreakerVacuum | ET-1171 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000871 | BreakerVacuum | ET-1171 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000871 | BreakerVacuum | ET-1171 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002129 | BreakerVacuum | ET-14KV TFR | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000871 | BreakerVacuum | ET-1171 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000871 | BreakerVacuum | ET-1171 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000871 | BreakerVacuum | ET-1171 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000871 | BreakerVacuum | ET-1171 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000871 | BreakerVacuum | ET-1171 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000871 | BreakerVacuum | ET-1171 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000871 | BreakerVacuum | ET-1171 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000871 | BreakerVacuum | ET-1171 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000871 | BreakerVacuum | ET-1171 | VCB Readings | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000871 | BreakerVacuum | ET-1171 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000871 | BreakerVacuum | ET-1171 | VCB Readings | Operations Counter AF | 90 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000871 | BreakerVacuum | ET-1171 | VCB Readings | Operations Counter AL | 90 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000871 | BreakerVacuum | ET-1171 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK000871 | BreakerVacuum | ET-1171 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Readings | 9 Month Operations | 2 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000945 | BreakerVacuum | 585-0723 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1251 | Regulator | 725-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 9:25 | Distribution | Ashbyburg Pump Quarterly Inspection | R1251 | Regulator | 725-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 15:28 | Distribution | Scholls Quarterly Inspection | BK000946 | BreakerVacuum | 585-0724 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | YD000057 | Yard | 517-Yard | Yard Patrol Inspection | General Comments | | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0862 | Regulator | 890-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0862 | Regulator | 890-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0862 | Regulator | 890-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0862 | Regulator | 890-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0862 | Regulator | 890-1 B | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0862 | Regulator | 890-1 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0862 | Regulator | 890-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0862 | Regulator | 890-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0862 | Regulator | 890-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0862 | Regulator | 890-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Readings | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0862 | Regulator | 890-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0862 | Regulator | 890-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0862 | Regulator | 890-1 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0862 | Regulator | 890-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | YD000057 | Yard | 517-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | YD000057 | Yard | 517-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Readings | Follow-up Action Required? | n | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | YD000057 | Yard | 517-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | YD000057 | Yard | 517-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | YD000057 | Yard | 517-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | YD000057 | Yard | 517-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | YD000057 | Yard | 517-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | YD000057 | Yard | 517-Yard | Yard Patrol Inspection | Ambient Temp | 33 | °F |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0862 | Regulator | 890-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0862 | Regulator | 890-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0862 | Regulator | 890-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0862 | Regulator | 890-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Readings | Amps C Ø | 0.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Readings | Amps B Ø | 0.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Readings | Amps A Ø | 0.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Readings | 9 Month Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Readings | Operations Counter AL | 15 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1094 | Regulator | 787-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1094 | Regulator | 787-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1094 | Regulator | 787-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1094 | Regulator | 787-1 A | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1094 | Regulator | 787-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1094 | Regulator | 787-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1094 | Regulator | 787-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1094 | Regulator | 787-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1094 | Regulator | 787-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1094 | Regulator | 787-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 108991 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1094 | Regulator | 787-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1094 | Regulator | 787-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1094 | Regulator | 787-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0863 | Regulator | 890-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0863 | Regulator | 890-1 C | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0863 | Regulator | 890-1 C | Regulator Patrol Inspection | Max Tap Position | 1L | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0863 | Regulator | 890-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0863 | Regulator | 890-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0863 | Regulator | 890-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0863 | Regulator | 890-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0863 | Regulator | 890-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0863 | Regulator | 890-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0863 | Regulator | 890-1 C | Regulator Patrol Inspection | Current Tap Position | 14L | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0863 | Regulator | 890-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0863 | Regulator | 890-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0863 | Regulator | 890-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0863 | Regulator | 890-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0863 | Regulator | 890-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0862 | Regulator | 890-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | ST000326 | Structure | 892-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | ST000326 | Structure | 892-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | ST000326 | Structure | 892-Structure | Structure Patrol Inspection | General Comments | | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0862 | Regulator | 890-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0862 | Regulator | 890-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LTCC000602 | LTCControl | ET-TRANS 6 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LTCC000602 | LTCControl | ET-TRANS 6 | LTC Control Insp | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LTCC000602 | LTCControl | ET-TRANS 6 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0862 | Regulator | 890-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0862 | Regulator | 890-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 414277 | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0862 | Regulator | 890-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.7 | volts |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | ST000326 | Structure | 892-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | ST000326 | Structure | 892-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | ST000326 | Structure | 892-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | ST000326 | Structure | 892-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | ST000326 | Structure | 892-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Readings | Unknown Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Readings | Operations Counter AL | 335 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Readings | Operations Counter AF | 335 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001837 | BreakerVacuum | C-GND TR 3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | ST000326 | Structure | 892-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | ST000326 | Structure | 892-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | ST000326 | Structure | 892-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | YD000057 | Yard | 517-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | YD000057 | Yard | 517-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Readings | Amps B Ø | 326.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Readings | Amps C Ø | 345.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Readings | Amps C Ø | 215.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Readings | Amps B Ø | 218.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Readings | Amps A Ø | 222.0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | LTCMechanism | 888-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Readings | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Readings | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Readings | Operations Counter AF | 163 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Readings | Operations Counter AL | 163 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Readings | Operations This Read Vac | 1 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Readings | Switching Operations | 1 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0254 | GroundTransformer | FL-GND TR 1 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0254 | GroundTransformer | FL-GND TR 1 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | LTCMechanism | 888-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | LTCMechanism | 888-1 | LTC Counter Readings | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | LTCMechanism | ET-TRANS 6 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | LTCMechanism | ET-TRANS 6 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | LTCMechanism | ET-TRANS 6 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | High | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | LTCMechanism | ET-TRANS 6 | LTC Counter Readings | LTC Operations Since Last Insp | 584 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | LTCMechanism | ET-TRANS 6 | LTC Counter Readings | LTC Min Tap Position | 3L | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | LTCMechanism | ET-TRANS 6 | LTC Counter Readings | LTC Max Tap Position | 9R | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | LTCMechanism | ET-TRANS 6 | LTC Counter Readings | LTC Current Tap Position | 2R | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | LTCMechanism | ET-TRANS 6 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Readings | Switching Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Readings | Operations Counter AL | 19 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Readings | Operations Counter AF | 19 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | LTCMechanism | ET-TRANS 6 | LTC Counter Readings | LTC As Left Counter | 21878 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | LTCMechanism | ET-TRANS 6 | LTC Counter Readings | LTC As Found Counter | 21878 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | LTCMechanism | ET-TRANS 6 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | LTCMechanism | ET-TRANS 6 | LTC Counter Readings | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | LTCMechanism | ET-TRANS 6 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0068 | LTCMechanism | ET-TRANS 6 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | LTCMechanism | ET-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | LTCMechanism | ET-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | LTCMechanism | ET-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | LTCMechanism | ET-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | LTCMechanism | ET-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 357 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | LTCMechanism | ET-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | LTCMechanism | ET-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | LTCMechanism | ET-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | LTCMechanism | ET-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | LTCMechanism | ET-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 220452 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | LTCMechanism | ET-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 220452 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | LTCMechanism | ET-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | LTCMechanism | ET-TRANS 2 | LTC Counter Readings | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | LTCMechanism | ET-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | LT0067 | LTCMechanism | ET-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Readings | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Patrol Inspection | All Temp Gauges MAX Reset | n | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Readings | 9 Month Operations | 15 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Readings | 9 Month Operations VCB New | 14 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002125 | BreakerVacuum | ET-12KV TR 2 | VCB Readings | Amps A Ø | 348.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Readings | Switching Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Readings | Operations This Read Vac | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Readings | Operations Counter AL | 341 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Readings | Operations Counter AF | 341 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Readings | Maintenance Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Readings | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | ST000327 | Structure | 510-Structure | Structure Patrol Inspection | General Comments | | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | ST000327 | Structure | 510-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | ST000327 | Structure | 510-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | ST000327 | Structure | 510-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | ST000327 | Structure | 510-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | ST000327 | Structure | 510-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | ST000327 | Structure | 510-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | ST000327 | Structure | 510-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | ST000327 | Structure | 510-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | ST000327 | Structure | 510-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | FE000319 | Fence | 510-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0076 | BreakerVacuum | BY-1282 | VCB Readings | Amps A Ø | 0.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0076 | BreakerVacuum | BY-1282 | VCB Readings | Amps B Ø | 0.0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0076 | BreakerVacuum | BY-1282 | VCB Readings | Amps C Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0076 | BreakerVacuum | BY-1282 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0076 | BreakerVacuum | BY-1282 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0076 | BreakerVacuum | BY-1282 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0076 | BreakerVacuum | BY-1282 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0076 | BreakerVacuum | BY-1282 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0076 | BreakerVacuum | BY-1282 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0076 | BreakerVacuum | BY-1282 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0076 | BreakerVacuum | BY-1282 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0076 | BreakerVacuum | BY-1282 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0076 | BreakerVacuum | BY-1282 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Readings | 9 Month Operations | 15 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Readings | 9 Month Operations VCB New | 15 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Readings | Fault Operations Ground | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Readings | Amps C Ø | 0.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Readings | Amps B Ø | 0.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Readings | Amps A Ø | 0.0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | LTCMechanism | 724-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | LTCMechanism | 724-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | LTCMechanism | 724-1 | LTC Counter Readings | LTC Operations Since Last Insp | 241 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | LTCMechanism | 724-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | LTCMechanism | 724-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000193 | Switchgear | BY-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000193 | Switchgear | BY-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000193 | Switchgear | BY-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000193 | Switchgear | BY-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000193 | Switchgear | BY-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000193 | Switchgear | BY-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000193 | Switchgear | BY-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | SWG000193 | Switchgear | BY-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Readings | General Comments | | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Readings | Operations Counter AF | 370 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Readings | Operations Counter AL | 374 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Readings | Operations This Read Vac | 4 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Readings | Switching Operations | 4 | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 15:29 | Distribution | Warsaw East Quarterly Inspection | BB0424 | BreakerVacuum | 559-0872 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 13:53 | Distribution | Shelbyville East Quarterly Inspection | B0382 | LTCMechanism | 724-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | ST000327 | Structure | 510-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | ST000327 | Structure | 510-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | ST000327 | Structure | 510-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | ST000327 | Structure | 510-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | ST000327 | Structure | 510-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | ST000327 | Structure | 510-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MX0330 | RecloserHydraulic | 517-0324 C | Recloser Hydraulic Patrol Inspection | Amps A Ø | 18.0 | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MX0330 | RecloserHydraulic | 517-0324 C | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Readings | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Readings | Operations Counter AF | 38 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Readings | Operations Counter AL | 38 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Readings | Operations This Read Vac | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002123 | BreakerVacuum | ET-1168 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0076 | BreakerVacuum | BY-1282 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Readings | Unknown Operations | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Patrol Inspection | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MX0330 | RecloserHydraulic | 517-0324 C | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MX0330 | RecloserHydraulic | 517-0324 C | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Readings | Fault Operations Ground | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0076 | BreakerVacuum | BY-1282 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0076 | BreakerVacuum | BY-1282 | VCB Readings | General Comments | | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0076 | BreakerVacuum | BY-1282 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0076 | BreakerVacuum | BY-1282 | VCB Readings | Operations Counter AF | 670 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0076 | BreakerVacuum | BY-1282 | VCB Readings | Operations Counter AL | 670 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0076 | BreakerVacuum | BY-1282 | VCB Readings | Operations This Read Vac | 0 | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MX0330 | RecloserHydraulic | 517-0324 C | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MX0330 | RecloserHydraulic | 517-0324 C | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MX0330 | RecloserHydraulic | 517-0324 C | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MX0330 | RecloserHydraulic | 517-0324 C | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MX0330 | RecloserHydraulic | 517-0324 C | Recloser Hydraulic Patrol Inspection | Operations Counter | 140 | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MX0330 | RecloserHydraulic | 517-0324 C | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/8/2023 7:11 | Distribution | Brush Creek Quarterly Inspection | MX0330 | RecloserHydraulic | 517-0324 C | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1094 | Regulator | 787-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1094 | Regulator | 787-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0076 | BreakerVacuum | BY-1282 | VCB Readings | Switching Operations | 0 | |
| 2/7/2023 10:24 | Distribution | Bluegrass Parkway Quarterly Inspection | LB0076 | BreakerVacuum | BY-1282 | VCB Readings | Unknown Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Readings | General Comments | | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Readings | Maintenance Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Readings | Operations Counter AF | 15 | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1094 | Regulator | 787-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1094 | Regulator | 787-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1094 | Regulator | 787-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1094 | Regulator | 787-1 A | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1094 | Regulator | 787-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1094 | Regulator | 787-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | ST000326 | Structure | 892-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | ST000326 | Structure | 892-Structure | Structure Patrol Inspection | Platform/Walkway/Railing OK? | y | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | ST000326 | Structure | 892-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0863 | Regulator | 890-1 C | Regulator Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0863 | Regulator | 890-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1094 | Regulator | 787-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 10:19 | Distribution | Sebree Quarterly Inspection | R1094 | Regulator | 787-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | FE000319 | Fence | 510-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001838 | BreakerVacuum | C-GND TR 4 | VCB Readings | 9 Month Operations | 0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Readings | Amps A Ø | 94.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Readings | Amps B Ø | 91.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Readings | Amps C Ø | 97.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0123 | Regulator | 891-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002124 | BreakerVacuum | ET-1169 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | FE000319 | Fence | 510-Fence | Fence Patrol Inspection | General Comments | | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | FE000319 | Fence | 510-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | FE000319 | Fence | 510-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | FE000319 | Fence | 510-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | FE000319 | Fence | 510-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | FE000319 | Fence | 510-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | FE000319 | Fence | 510-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | FE000319 | Fence | 510-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | FE000319 | Fence | 510-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | FE000319 | Fence | 510-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | FE000319 | Fence | 510-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | FE000319 | Fence | 510-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | FE000319 | Fence | 510-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | FE000319 | Fence | 510-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0863 | Regulator | 890-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0863 | Regulator | 890-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0863 | Regulator | 890-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0863 | Regulator | 890-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 125.6 | volts |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0863 | Regulator | 890-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 199913 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Readings | Amps C Ø | 0.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Readings | Amps B Ø | 0.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Readings | Amps A Ø | 0.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002131 | BreakerVacuum | ET-GND TR 1 | VCB Readings | 9 Month Operations | 8 | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0863 | Regulator | 890-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/7/2023 9:31 | Distribution | Garrard Quarterly Inspection | R0863 | Regulator | 890-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | ST000326 | Structure | 892-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | ST000326 | Structure | 892-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | ST000326 | Structure | 892-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | ST000326 | Structure | 892-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 8:08 | Distribution | Fies City Quarterly Inspection | ST000326 | Structure | 892-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001248 | BreakerVacuum | C-1344 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BAT001552 | Battery | 670-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BAT001552 | Battery | 670-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BAT001552 | Battery | 670-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BAT001552 | Battery | 670-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BAT001552 | Battery | 670-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BAT001552 | Battery | 670-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BAT001552 | Battery | 670-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BAT001552 | Battery | 670-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0254 | GroundTransformer | FL-GND TR 1 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BCH001483 | Charger | 670-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0254 | GroundTransformer | FL-GND TR 1 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0254 | GroundTransformer | FL-GND TR 1 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0254 | GroundTransformer | FL-GND TR 1 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0254 | GroundTransformer | FL-GND TR 1 | Ground Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0254 | GroundTransformer | FL-GND TR 1 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0254 | GroundTransformer | FL-GND TR 1 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0254 | GroundTransformer | FL-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0254 | GroundTransformer | FL-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0254 | GroundTransformer | FL-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BCH001483 | Charger | 670-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BCH001483 | Charger | 670-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0254 | GroundTransformer | FL-GND TR 1 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | ST000383 | Structure | 441-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | ST000383 | Structure | 441-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | ST000383 | Structure | 441-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Patrol Inspection | General Comments | | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | ST000383 | Structure | 441-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | ST000383 | Structure | 441-Structure | Structure Patrol Inspection | General Comments | | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | LTCMechanism | 888-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | ST000383 | Structure | 441-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | ST000383 | Structure | 441-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Readings | Totalizer Meter Reading | .2592 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | ST000383 | Structure | 441-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | LTCMechanism | LS-TRANS 5 | LTC Counter Readings | LTC Operations Since Last Insp | 116 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | LTCMechanism | LS-TRANS 5 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | LTCMechanism | LS-TRANS 5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Low | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | LTCMechanism | LS-TRANS 5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | LTCMechanism | LS-TRANS 5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | LTCMechanism | 888-1 | LTC Counter Readings | LTC Current Tap Position | 2R | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | LTCMechanism | 888-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | LTCMechanism | 888-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | LTCMechanism | 888-1 | LTC Counter Readings | LTC As Left Counter | 214666 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | LTCMechanism | 888-1 | LTC Counter Readings | LTC As Found Counter | 214657 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | LTCMechanism | 888-1 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | LTCMechanism | 888-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | LTCMechanism | 888-1 | LTC Counter Readings | LTC Operations Since Last Insp | 402 | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | LTCMechanism | LS-TRANS 5 | LTC Counter Readings | LTC As Found Counter | 83936 | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | LTCMechanism | LS-TRANS 5 | LTC Counter Readings | LTC As Left Counter | 83936 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BCH001483 | Charger | 670-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BCH001483 | Charger | 670-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BCH001483 | Charger | 670-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | LTCMechanism | LS-TRANS 5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | LTCMechanism | LS-TRANS 5 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | LTCMechanism | LS-TRANS 5 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | LTCMechanism | LS-TRANS 5 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | LTCMechanism | LS-TRANS 5 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | ST000383 | Structure | 441-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | ST000383 | Structure | 441-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | ST000383 | Structure | 441-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BCH001483 | Charger | 670-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.6 | amps |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BCH001483 | Charger | 670-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | ST000383 | Structure | 441-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | ST000383 | Structure | 441-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BAT001552 | Battery | 670-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BAT001552 | Battery | 670-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 51 | °F |
| 2/16/2023 13:40 | Distribution | Canal Quarterly Inspection | BK001185 | BreakerVacuum | C-1304 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BAT001552 | Battery | 670-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | LTCMechanism | 888-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | ST000383 | Structure | 441-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | ST000383 | Structure | 441-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | ST000383 | Structure | 441-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0122 | Regulator | 891-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | ST000383 | Structure | 441-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | ST000383 | Structure | 441-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0122 | Regulator | 891-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0122 | Regulator | 891-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Readings | 9 Month Operations | 9 | |
| 2/7/2023 14:33 | Distribution | Floyd Quarterly Inspection | LT0254 | GroundTransformer | FL-GND TR 1 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Readings | Oil Temp Present | 42 | °C |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Readings | Oil Temp Max | 52 | °C |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | KR0122 | Regulator | 891-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BAT001552 | Battery | 670-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/7/2023 15:16 | Distribution | Forks Of Elkhorn Quarterly Inspection | BAT001552 | Battery | 670-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1866.24 | kw |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | ST000383 | Structure | 441-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | LTCMechanism | LS-TRANS 5 | LTC Mechanism Patrol Inspection | General Comments | needs oil | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | LTCMechanism | LS-TRANS 5 | LTC Counter Readings | General Comments | | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | LTCMechanism | LS-TRANS 5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/7/2023 9:07 | Distribution | Lyndon South Quarterly Inspection | LT0080 | LTCMechanism | LS-TRANS 5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 97.50 | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1025.76 | kw |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/7/2023 7:12 | Distribution | Hunters Bottom Quarterly Inspection | C0176 | NonLTC | 891-1 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Readings | General Comments | | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | ST000383 | Structure | 441-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | ST000383 | Structure | 441-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | ST000383 | Structure | 441-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/7/2023 11:17 | Distribution | Warsaw Quarterly Inspection | ST000383 | Structure | 441-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 2/7/2023 12:45 | Distribution | Corydon Quarterly Inspection | W0188 | NonLTC | 012-5 | NonLTC Transformer Readings | Totalizer Meter Reading | .4274 | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002130 | BreakerVacuum | ET-14KV TR 1 | VCB Readings | 9 Month Operations | 9 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Readings | Amps C Ø | 40.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Readings | Amps B Ø | 43.0 | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | LTCMechanism | 888-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Readings | Amps A Ø | 45.0 | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/7/2023 10:09 | Distribution | Airline Road Quarterly Inspection | W0313 | NonLTC | 510-1 A | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | LTCMechanism | 888-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/7/2023 11:10 | Distribution | Spencer Chemical Quarterly Inspection | W0262 | LTCMechanism | 888-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/7/2023 16:56 | Distribution | Ethel Quarterly Inspection | BK002126 | BreakerVacuum | ET-1421 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Readings | Switching Operations | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Readings | Operations This Read Vac | 2 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Readings | Operations Counter AL | 193 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Readings | Operations Counter AF | 193 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Readings | Maintenance Operations | 1 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Readings | General Comments | 1 op - AG, 1 - trip check | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 1.00 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Readings | Amps C Ø | 64.0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Readings | Fault Operations A Ø | 1 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Readings | 9 Month Operations | 2 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Readings | Amps B Ø | 69.0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Readings | Amps A Ø | 55.0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000494 | BreakerVacuum | 930-Offline-Distribution | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BAT001275 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BAT001275 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BAT001275 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BAT001275 | Battery | Retired Distribution | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BAT001275 | Battery | Retired Distribution | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BAT001275 | Battery | Retired Distribution | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BAT001275 | Battery | Retired Distribution | Battery Patrol Inspection | General Comments | | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BAT001275 | Battery | Retired Distribution | Battery Patrol Inspection | Negative DC Ground | 28.0 | VDC |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BAT001275 | Battery | Retired Distribution | Battery Patrol Inspection | Positive DC Ground | 26.8 | VDC |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BAT001275 | Battery | Retired Distribution | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BAT001275 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BAT001275 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Area Ambient Temp | 46 | °F |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BAT001275 | Battery | Retired Distribution | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BAT001275 | Battery | Retired Distribution | Battery Patrol Inspection | All Connections OK? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Readings | Operations This Read SF6 | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Readings | Operations Counter AL | 78 | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Readings | Operations Counter AF | 78 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | ST000180 | Structure | 844-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | ST000180 | Structure | 844-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | ST000180 | Structure | 844-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Readings | General Comments | | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Readings | Maintenance Operations | 0 | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Readings | Maintenance Operations | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Patrol Inspection | General Comments | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Readings | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Readings | Operations Counter AF | 265 | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Readings | Operations Counter AL | 267 | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Readings | Operations This Read Vac | 2 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | MX0271 | RecloserHydraulic | 632-0380 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | ST000180 | Structure | 844-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | ST000180 | Structure | 844-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | ST000180 | Structure | 844-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | ST000180 | Structure | 844-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | ST000180 | Structure | 844-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | LTCC000765 | LTCControl | 844-1 | LTC Control Insp | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | LTCC000765 | LTCControl | 844-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | MX0271 | RecloserHydraulic | 632-0380 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | LTCC000765 | LTCControl | 844-1 | LTC Control Insp | All Connections OK? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | LTCC000763 | LTCControl | 519-2 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | LTCC000763 | LTCControl | 519-2 | LTC Control Insp | VRR Base Voltage AL | 123.6 | VAC |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | LTCC000763 | LTCControl | 519-2 | LTC Control Insp | VRR Base Voltage AF | 124.8 | VAC |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | MX0271 | RecloserHydraulic | 632-0380 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | MX0271 | RecloserHydraulic | 632-0380 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | MX0271 | RecloserHydraulic | 632-0380 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | ST000111 | Structure | 795-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | LTCC000763 | LTCControl | 519-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | ST000180 | Structure | 844-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | ST000180 | Structure | 844-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | ST000180 | Structure | 844-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | ST000111 | Structure | 795-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | ST000111 | Structure | 795-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | ST000111 | Structure | 795-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Readings | Fault Operations | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | ST000180 | Structure | 844-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | ST000180 | Structure | 844-Structure | Structure Patrol Inspection | General Comments | | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Readings | Switching Operations | 2 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | ST000180 | Structure | 844-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | ST000180 | Structure | 844-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | ST000180 | Structure | 844-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Readings | Amps C Ø | 83.0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Readings | General Comments | | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1000 | psi |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 114.17 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 100.00 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Readings | Oil Temp Max | 42 | °C |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Readings | Oil Temp Present | 29 | °C |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Readings | Winding Temp Max | 14 | °C |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Readings | Winding Temp Present | 5 | °C |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Patrol Inspection | SF6 Pressure Pole 3 | 60 | psi |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | T0117 | NonLTC | 005-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Readings | Switching Operations | 0 | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | MX0271 | RecloserHydraulic | 632-0380 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | MX0271 | RecloserHydraulic | 632-0380 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Patrol Inspection | SF6 Pressure Pole 2 | 60 | psi |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Patrol Inspection | SF6 Pressure Pole 1 | 60 | psi |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | ST000119 | Structure | 881-Structure | Structure Patrol Inspection | General Comments | | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | ST000119 | Structure | 881-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | ST000119 | Structure | 881-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | ST000119 | Structure | 881-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Readings | General Comments | | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | ST000119 | Structure | 881-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | ST000119 | Structure | 881-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | ST000119 | Structure | 881-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | ST000119 | Structure | 881-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | ST000119 | Structure | 881-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | ST000119 | Structure | 881-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3964.32 | kw |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | YD000401 | Yard | 694-Yard | Yard Patrol Inspection | Ambient Temp | 54 | °F |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | YD000401 | Yard | 694-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | YD000401 | Yard | 694-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | YD000401 | Yard | 694-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | YD000401 | Yard | 694-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | YD000401 | Yard | 694-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | YD000401 | Yard | 694-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | YD000401 | Yard | 694-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | YD000401 | Yard | 694-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | YD000401 | Yard | 694-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | YD000401 | Yard | 694-Yard | Yard Patrol Inspection | General Comments | | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | YD000401 | Yard | 694-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | YD000401 | Yard | 694-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | YD000401 | Yard | 694-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | YD000401 | Yard | 694-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | YD000401 | Yard | 694-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | YD000401 | Yard | 694-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Readings | General Comments | | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | ST000393 | Structure | 701-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | ST000393 | Structure | 701-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | ST000393 | Structure | 701-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1289 | Regulator | 447-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1289 | Regulator | 447-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1289 | Regulator | 447-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1289 | Regulator | 447-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1289 | Regulator | 447-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | BCH001301 | Charger | 022-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | BCH001301 | Charger | 022-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | BCH001301 | Charger | 022-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | BCH001301 | Charger | 022-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | BCH001301 | Charger | 022-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .4 | amps |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | BCH001301 | Charger | 022-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.0 | VDC |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | BCH001301 | Charger | 022-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.0 | VDC |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | BCH001301 | Charger | 022-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | ST000393 | Structure | 701-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | ST000393 | Structure | 701-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | ST000393 | Structure | 701-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | LTCMechanism | 694-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | LTCMechanism | 694-1 | LTC Counter Readings | LTC Operations Since Last Insp | 341 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | LTCMechanism | 694-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | LTCMechanism | 694-1 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | LTCMechanism | 694-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | LTCMechanism | 694-1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | LTCMechanism | 694-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Readings | Oil Temp Max | 70 | °C |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1267 | Regulator | 632-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1267 | Regulator | 632-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | CH000089 | ControlHouse | 022-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | CH000089 | ControlHouse | 022-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | LTCMechanism | 694-1 | LTC Counter Readings | LTC As Left Counter | 32540 | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1267 | Regulator | 632-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1267 | Regulator | 632-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1267 | Regulator | 632-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 138848 | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1267 | Regulator | 632-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1267 | Regulator | 632-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1267 | Regulator | 632-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1267 | Regulator | 632-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Readings | General Comments | 1 - AG, 1 - trip check | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | CH000089 | ControlHouse | 022-Control House | Control House Patrol Inspection | General Comments | | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | CH000089 | ControlHouse | 022-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | CH000089 | ControlHouse | 022-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | CH000089 | ControlHouse | 022-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | CH000089 | ControlHouse | 022-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | CH000089 | ControlHouse | 022-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | CH000089 | ControlHouse | 022-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Readings | Fault Operations A Ø | 1 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Readings | Fault Adjusted Amps A Phase V | 5.46 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1267 | Regulator | 632-1 B | Regulator Patrol Inspection | Current Tap Position | 9L | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1267 | Regulator | 632-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1267 | Regulator | 632-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1267 | Regulator | 632-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1267 | Regulator | 632-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | ST000119 | Structure | 881-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | ST000119 | Structure | 881-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | ST000119 | Structure | 881-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | ST000119 | Structure | 881-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | ST000119 | Structure | 881-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | ST000119 | Structure | 881-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | ST000119 | Structure | 881-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | ST000119 | Structure | 881-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Readings | 9 Month Operations | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Readings | Amps A Ø | 19.0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Readings | Amps B Ø | 19.0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Readings | Amps C Ø | 22.0 | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | BAT001378 | Battery | 022-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Readings | Amps A Ø | 0.0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | ST000180 | Structure | 844-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | ST000180 | Structure | 844-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | ST000180 | Structure | 844-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | ST000180 | Structure | 844-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | LTCC000763 | LTCControl | 519-2 | LTC Control Insp | All Connections OK? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | LTCC000763 | LTCControl | 519-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | LTCC000763 | LTCControl | 519-2 | LTC Control Insp | General Comments | | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | LTCC000763 | LTCControl | 519-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | ST000180 | Structure | 844-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | ST000180 | Structure | 844-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | LTCMechanism | 694-1 | LTC Counter Readings | LTC As Found Counter | 31540 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | LTCMechanism | 694-1 | LTC Counter Readings | General Comments | LTC is in manual | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | LTCMechanism | 694-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | LTCMechanism | 694-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | LTCMechanism | 694-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Readings | Amps C Ø | 0.0 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Readings | Amps B Ø | 0.0 | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | BAT001378 | Battery | 022-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | BAT001378 | Battery | 022-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | BAT001378 | Battery | 022-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | BAT001378 | Battery | 022-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | BAT001378 | Battery | 022-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | BAT001378 | Battery | 022-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | BAT001378 | Battery | 022-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.6518 | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | ST000119 | Structure | 881-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | ST000119 | Structure | 881-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | ST000119 | Structure | 881-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | ST000119 | Structure | 881-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1267 | Regulator | 632-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1267 | Regulator | 632-1 B | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1267 | Regulator | 632-1 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | BAT001378 | Battery | 022-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | BAT001378 | Battery | 022-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | BAT001378 | Battery | 022-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | BAT001378 | Battery | 022-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | BAT001378 | Battery | 022-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | BAT001378 | Battery | 022-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1267 | Regulator | 632-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1267 | Regulator | 632-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1267 | Regulator | 632-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1267 | Regulator | 632-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1267 | Regulator | 632-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1267 | Regulator | 632-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | O0180 | NonLTC | 881-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000061 | Regulator | 701-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000061 | Regulator | 701-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000061 | Regulator | 701-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000061 | Regulator | 701-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 7329 | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000061 | Regulator | 701-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 125.0 | volts |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000061 | Regulator | 701-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000061 | Regulator | 701-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000061 | Regulator | 701-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000061 | Regulator | 701-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000061 | Regulator | 701-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000061 | Regulator | 701-1 C | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000061 | Regulator | 701-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000061 | Regulator | 701-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000061 | Regulator | 701-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000061 | Regulator | 701-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000061 | Regulator | 701-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000061 | Regulator | 701-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000061 | Regulator | 701-1 C | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BCH000174 | Charger | 005-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.6 | VDC |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BCH000174 | Charger | 005-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.6 | VDC |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BCH000174 | Charger | 005-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.6 | amps |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BCH000174 | Charger | 005-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BCH000174 | Charger | 005-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000061 | Regulator | 701-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000061 | Regulator | 701-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000061 | Regulator | 701-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000061 | Regulator | 701-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000061 | Regulator | 701-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Readings | Amps B Ø | 11.0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Readings | Amps A Ø | 10.0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Readings | 9 Month Operations | 1 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Readings | Switching Operations | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Readings | Operations This Read Vac | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Readings | Operations Counter AL | 62 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Readings | Switching Operations | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1266 | Regulator | 632-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 130811 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Readings | Operations This Read Vac | 2 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Readings | Operations Counter AF | 62 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Readings | Maintenance Operations | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000062 | Regulator | 701-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 6605 | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000062 | Regulator | 701-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000062 | Regulator | 701-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000062 | Regulator | 701-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000062 | Regulator | 701-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000062 | Regulator | 701-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000062 | Regulator | 701-1 A | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Readings | Amps C Ø | 14.0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000062 | Regulator | 701-1 A | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000062 | Regulator | 701-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000062 | Regulator | 701-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000062 | Regulator | 701-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000062 | Regulator | 701-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000062 | Regulator | 701-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000062 | Regulator | 701-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000062 | Regulator | 701-1 A | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000062 | Regulator | 701-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000062 | Regulator | 701-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000062 | Regulator | 701-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000062 | Regulator | 701-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000062 | Regulator | 701-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Readings | LTC Totalizer Reading | 5253.12 | kw |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Readings | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000061 | Regulator | 701-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1266 | Regulator | 632-1 A | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1266 | Regulator | 632-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1266 | Regulator | 632-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | KX0238 | RecloserElectronic | 519-0304 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1266 | Regulator | 632-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1266 | Regulator | 632-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1266 | Regulator | 632-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1266 | Regulator | 632-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1266 | Regulator | 632-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1266 | Regulator | 632-1 A | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1266 | Regulator | 632-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1266 | Regulator | 632-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1266 | Regulator | 632-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | LTCMechanism | 844-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | LTCMechanism | 844-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | LTCMechanism | 844-2 | LTC Counter Readings | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | LTCMechanism | 844-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1266 | Regulator | 632-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Readings | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | LTCMechanism | 844-2 | LTC Counter Readings | LTC As Found Counter | 259620 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | LTCMechanism | 844-2 | LTC Counter Readings | LTC As Left Counter | 259632 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | LTCMechanism | 844-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Readings | Maintenance Operations | 0 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Readings | Operations Counter AF | 183 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Readings | Operations Counter AL | 185 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Readings | Operations This Read Vac | 2 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Readings | Switching Operations | 2 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | LTCMechanism | 844-2 | LTC Counter Readings | LTC Current Tap Position | 12L | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | LTCMechanism | 844-2 | LTC Counter Readings | LTC Max Tap Position | 6L | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | LTCMechanism | 844-2 | LTC Counter Readings | LTC Min Tap Position | 1L | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | LTCMechanism | 844-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Readings | Amps B Ø | 55.0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Readings | Amps C Ø | 80.0 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | KX0238 | RecloserElectronic | 519-0304 | Recloser Electronic Patrol Inspection | Operations Counter | 30 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | KX0238 | RecloserElectronic | 519-0304 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | KX0238 | RecloserElectronic | 519-0304 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | LTCMechanism | 844-2 | LTC Counter Readings | LTC Operations Since Last Insp | 515 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | LTCMechanism | 844-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | LTCMechanism | 844-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | LTCMechanism | 844-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | KX0238 | RecloserElectronic | 519-0304 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Readings | General Comments | | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BCH001567 | Charger | 694-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BCH001567 | Charger | 694-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BCH001567 | Charger | 694-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BCH001567 | Charger | 694-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BCH001567 | Charger | 694-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.2 | amps |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BCH001567 | Charger | 694-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BCH001567 | Charger | 694-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | LTCC000765 | LTCControl | 844-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1266 | Regulator | 632-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1266 | Regulator | 632-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1266 | Regulator | 632-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1266 | Regulator | 632-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BCH001567 | Charger | 694-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Readings | Operations Counter AL | 208 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Readings | Switching Operations | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Readings | Operations This Read Vac | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Readings | Operations Counter AL | 842 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Readings | Operations Counter AF | 842 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Readings | Maintenance Operations | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Readings | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Readings | Operations Counter AF | 208 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Readings | Maintenance Operations | 1 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | LTCC000765 | LTCControl | 844-1 | LTC Control Insp | LTC Output Voltage Level | 123.8 | VAC |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | LTCC000765 | LTCControl | 844-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | LTCC000765 | LTCControl | 844-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | LTCC000765 | LTCControl | 844-1 | LTC Control Insp | VRR Time Delay | 45 | Seconds |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1266 | Regulator | 632-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1266 | Regulator | 632-1 A | Regulator Patrol Inspection | Min Tap Position | 15L | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | ST000111 | Structure | 795-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | ST000111 | Structure | 795-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | ST000111 | Structure | 795-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | ST000111 | Structure | 795-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | ST000111 | Structure | 795-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | ST000111 | Structure | 795-Structure | Structure Patrol Inspection | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | ST000111 | Structure | 795-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | ST000111 | Structure | 795-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | ST000111 | Structure | 795-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | ST000111 | Structure | 795-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | ST000111 | Structure | 795-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000063 | Regulator | 701-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000063 | Regulator | 701-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000063 | Regulator | 701-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000063 | Regulator | 701-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000063 | Regulator | 701-1 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000063 | Regulator | 701-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000063 | Regulator | 701-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000063 | Regulator | 701-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000063 | Regulator | 701-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | KX0238 | RecloserElectronic | 519-0304 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1267 | Regulator | 632-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Readings | 9 Month Operations | 1 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0492 | RecloserHydraulic | 881-0315 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Readings | 9 Month Operations | 2 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1266 | Regulator | 632-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1266 | Regulator | 632-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0150 | BreakerVacuum | 844-0277 | VCB Readings | Amps A Ø | 74.0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | ST000111 | Structure | 795-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | ST000111 | Structure | 795-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | ST000111 | Structure | 795-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | ST000111 | Structure | 795-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | ST000081 | Structure | 632-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | ST000081 | Structure | 632-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | ST000081 | Structure | 632-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | ST000081 | Structure | 632-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | ST000081 | Structure | 632-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | YD000366 | Yard | 022-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | YD000366 | Yard | 022-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | YD000366 | Yard | 022-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | YD000366 | Yard | 022-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | YD000366 | Yard | 022-Yard | Yard Patrol Inspection | General Comments | | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | YD000366 | Yard | 022-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0492 | RecloserHydraulic | 881-0315 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | YD000366 | Yard | 022-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Patrol Inspection | Ambient Temperature | 45 | °F |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000805 | BreakerSF6 | 795-618 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000063 | Regulator | 701-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000063 | Regulator | 701-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | MX0271 | RecloserHydraulic | 632-0380 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 103 | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | MX0271 | RecloserHydraulic | 632-0380 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | MX0271 | RecloserHydraulic | 632-0380 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Readings | 9 Month Operations | 2 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000484 | BreakerVacuum | 005-3410 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | KX0238 | RecloserElectronic | 519-0304 | Recloser Electronic Patrol Inspection | Amps A Ø | 15.0 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | KX0238 | RecloserElectronic | 519-0304 | Recloser Electronic Patrol Inspection | Amps B Ø | 18.0 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | KX0238 | RecloserElectronic | 519-0304 | Recloser Electronic Patrol Inspection | Amps C Ø | 16.0 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | KX0238 | RecloserElectronic | 519-0304 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | KX0238 | RecloserElectronic | 519-0304 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | KX0238 | RecloserElectronic | 519-0304 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | KX0238 | RecloserElectronic | 519-0304 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Readings | Amps C Ø | 0.0 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | KX0238 | RecloserElectronic | 519-0304 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Readings | Amps B Ø | 0.0 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Readings | Amps A Ø | 0.0 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Readings | Amps C Ø | 110.0 | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Readings | Amps B Ø | 90.0 | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | MX0271 | RecloserHydraulic | 632-0380 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 591 | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | MX0271 | RecloserHydraulic | 632-0380 | Recloser Hydraulic Patrol Inspection | Amps C Ø | .3 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | KX0238 | RecloserElectronic | 519-0304 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Readings | Amps A Ø | 115.0 | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Readings | 9 Month Operations VCB New | 11 | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BK001052 | BreakerVacuum | 655-0703 | VCB Readings | 9 Month Operations | 13 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | KX0238 | RecloserElectronic | 519-0304 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | KX0238 | RecloserElectronic | 519-0304 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | KX0238 | RecloserElectronic | 519-0304 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000063 | Regulator | 701-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000063 | Regulator | 701-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000063 | Regulator | 701-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 4552 | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000063 | Regulator | 701-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000063 | Regulator | 701-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | ST000111 | Structure | 795-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | ST000111 | Structure | 795-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | ST000111 | Structure | 795-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Readings | Maintenance Operations | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Readings | General Comments | | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Readings | 9 Month Operations | 3 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | MX0454 | RecloserHydraulic | 519-0306 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | MX0454 | RecloserHydraulic | 519-0306 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000062 | Regulator | 701-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000062 | Regulator | 701-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000062 | Regulator | 701-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000062 | Regulator | 701-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | ST000081 | Structure | 632-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | ST000081 | Structure | 632-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | ST000081 | Structure | 632-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | ST000081 | Structure | 632-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | ST000081 | Structure | 632-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | ST000081 | Structure | 632-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | ST000081 | Structure | 632-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | ST000081 | Structure | 632-Structure | Structure Patrol Inspection | General Comments | | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | ST000081 | Structure | 632-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | ST000081 | Structure | 632-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | ST000081 | Structure | 632-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | ST000081 | Structure | 632-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | ST000081 | Structure | 632-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | MX0454 | RecloserHydraulic | 519-0306 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | MX0454 | RecloserHydraulic | 519-0306 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | MX0454 | RecloserHydraulic | 519-0306 | Recloser Hydraulic Patrol Inspection | Operations Counter | 287 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Readings | Totalizer Meter Reading | .7296 | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | ST000081 | Structure | 632-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | ST000081 | Structure | 632-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | WithLTC | 844-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1266 | Regulator | 632-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1266 | Regulator | 632-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | MX0454 | RecloserHydraulic | 519-0306 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | MX0454 | RecloserHydraulic | 519-0306 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | ST000081 | Structure | 632-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0492 | RecloserHydraulic | 881-0315 | Recloser Hydraulic Patrol Inspection | Operations Counter | 514 | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0492 | RecloserHydraulic | 881-0315 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0492 | RecloserHydraulic | 881-0315 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | YD000366 | Yard | 022-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | YD000366 | Yard | 022-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | YD000366 | Yard | 022-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | YD000366 | Yard | 022-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | YD000366 | Yard | 022-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | YD000366 | Yard | 022-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | YD000366 | Yard | 022-Yard | Yard Patrol Inspection | Ambient Temp | 37 | °F |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0492 | RecloserHydraulic | 881-0315 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0492 | RecloserHydraulic | 881-0315 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0492 | RecloserHydraulic | 881-0315 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0492 | RecloserHydraulic | 881-0315 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0492 | RecloserHydraulic | 881-0315 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0492 | RecloserHydraulic | 881-0315 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 60.0 | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0492 | RecloserHydraulic | 881-0315 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 82.0 | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000063 | Regulator | 701-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000063 | Regulator | 701-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000063 | Regulator | 701-1 B | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000063 | Regulator | 701-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000063 | Regulator | 701-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000063 | Regulator | 701-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000063 | Regulator | 701-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | RG000063 | Regulator | 701-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0492 | RecloserHydraulic | 881-0315 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 50.0 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | KX0238 | RecloserElectronic | 519-0304 | Recloser Electronic Patrol Inspection | General Comments | 27.3/25 | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | MX0271 | RecloserHydraulic | 632-0380 | Recloser Hydraulic Patrol Inspection | Amps B Ø | .3 | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | MX0271 | RecloserHydraulic | 632-0380 | Recloser Hydraulic Patrol Inspection | Amps A Ø | .2 | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | MX0271 | RecloserHydraulic | 632-0380 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 142 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | KX0238 | RecloserElectronic | 519-0304 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000915 | BreakerVacuum | 694-0460 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | MX0454 | RecloserHydraulic | 519-0306 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 15.0 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | MX0454 | RecloserHydraulic | 519-0306 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 20.0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | MX0454 | RecloserHydraulic | 519-0306 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 17.0 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | MX0454 | RecloserHydraulic | 519-0306 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | MX0454 | RecloserHydraulic | 519-0306 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | MX0454 | RecloserHydraulic | 519-0306 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Readings | Amps B Ø | 49.0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | KB0113 | BreakerVacuum | 005-1476 | VCB Readings | Amps A Ø | 60.0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Readings | Switching Operations | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Readings | Operations Counter AL | 53 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000485 | BreakerVacuum | 005-2 | VCB Readings | Operations Counter AF | 53 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | YD000951 | Yard | 462-Yard | Yard Patrol Inspection | Ambient Temp | 39 | °F |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | YD000951 | Yard | 462-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | YD000951 | Yard | 462-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | YD000951 | Yard | 462-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | YD000951 | Yard | 462-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | YD000951 | Yard | 462-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | YD000951 | Yard | 462-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | YD000951 | Yard | 462-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | YD000951 | Yard | 462-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000154 | Regulator | 795-2 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000154 | Regulator | 795-2 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Readings | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Readings | Maintenance Operations | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Readings | Operations Counter AF | 219 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000154 | Regulator | 795-2 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000154 | Regulator | 795-2 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000154 | Regulator | 795-2 C | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000154 | Regulator | 795-2 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000154 | Regulator | 795-2 C | Regulator Patrol Inspection | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000154 | Regulator | 795-2 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000154 | Regulator | 795-2 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | KR0004 | Regulator | 447-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Readings | Operations Counter AL | 219 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Readings | Operations This Read Vac | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Readings | Switching Operations | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Readings | Operations This Read Vac | 3 | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Readings | Operations Counter AL | 193 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | YD000951 | Yard | 462-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | YD000951 | Yard | 462-Yard | Yard Patrol Inspection | General Comments | | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | KR0004 | Regulator | 447-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | KR0004 | Regulator | 447-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | KR0004 | Regulator | 447-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | KR0004 | Regulator | 447-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | KR0004 | Regulator | 447-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Readings | Amps C Ø | 9.0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | KR0004 | Regulator | 447-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | KR0004 | Regulator | 447-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | KR0004 | Regulator | 447-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | KR0004 | Regulator | 447-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 25942 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | KR0004 | Regulator | 447-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | KR0004 | Regulator | 447-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | KR0004 | Regulator | 447-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | KR0004 | Regulator | 447-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | KR0004 | Regulator | 447-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | KR0004 | Regulator | 447-1 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | KR0004 | Regulator | 447-1 C | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | KR0004 | Regulator | 447-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | KR0004 | Regulator | 447-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | KR0004 | Regulator | 447-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | KR0004 | Regulator | 447-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | FE000223 | Fence | 447-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | FE000223 | Fence | 447-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | FE000223 | Fence | 447-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | FE000223 | Fence | 447-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | FE000223 | Fence | 447-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | FE000223 | Fence | 447-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | FE000223 | Fence | 447-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | FE000223 | Fence | 447-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | FE000223 | Fence | 447-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | FE000223 | Fence | 447-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | FE000223 | Fence | 447-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | FE000223 | Fence | 447-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | FE000223 | Fence | 447-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | FE000223 | Fence | 447-Fence | Fence Patrol Inspection | General Comments | Neighbors fence is within inches of station fence. | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | FE000223 | Fence | 447-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | FE000223 | Fence | 447-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000154 | Regulator | 795-2 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.6 | volts |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000154 | Regulator | 795-2 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000154 | Regulator | 795-2 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000154 | Regulator | 795-2 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000154 | Regulator | 795-2 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000154 | Regulator | 795-2 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Readings | Oil Temp Present | 55 | °C |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000154 | Regulator | 795-2 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000154 | Regulator | 795-2 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Readings | Totalizer Meter Reading | .7578 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000154 | Regulator | 795-2 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Readings | 9 Month Operations | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Readings | Amps A Ø | 20.0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Readings | Amps B Ø | 20.0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Readings | Amps C Ø | 42.0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | KR0004 | Regulator | 447-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | KR0004 | Regulator | 447-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | YD000951 | Yard | 462-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | YD000951 | Yard | 462-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | YD000951 | Yard | 462-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | YD000951 | Yard | 462-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | YD000951 | Yard | 462-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | YD000951 | Yard | 462-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | YD000951 | Yard | 462-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Readings | Operations Counter AF | 193 | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Readings | Maintenance Operations | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Readings | General Comments | | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Readings | Fault Operations B Ø | 3 | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Readings | Fault Adjusted Amps B Phase V | 19.64 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Readings | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Readings | LTC Totalizer Reading | 7274.88 | kw |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | WithLTC | 795-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | LTCMechanism | 844-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | LTCMechanism | 844-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | LTCMechanism | 844-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | LTCMechanism | 844-1 | LTC Counter Readings | General Comments | Indicator hand not working again. | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | LTCMechanism | 844-1 | LTC Counter Readings | LTC As Found Counter | 233682 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | LTCMechanism | 844-1 | LTC Counter Readings | LTC As Left Counter | 233694 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | LTCMechanism | 844-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | LTCMechanism | 844-1 | LTC Counter Readings | LTC Current Tap Position | 4R | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1102 | Regulator | 519-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1102 | Regulator | 519-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000154 | Regulator | 795-2 C | Regulator Patrol Inspection | Regulator As Left Counter | 23640 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | LTCMechanism | 844-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1102 | Regulator | 519-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | LTCMechanism | 844-1 | LTC Counter Readings | LTC Min Tap Position | 4R | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | LTCMechanism | 844-1 | LTC Counter Readings | LTC Operations Since Last Insp | 819 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | LTCMechanism | 844-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | LTCMechanism | 844-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1102 | Regulator | 519-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | LTCMechanism | 699-1 | LTC Counter Readings | LTC Operations Since Last Insp | 281 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | LTCMechanism | 699-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | LTCMechanism | 699-1 | LTC Counter Readings | LTC Min Tap Position | 15L | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | LTCMechanism | 699-1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | LTCMechanism | 699-1 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | LTCMechanism | 699-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | LTCMechanism | 699-1 | LTC Counter Readings | LTC As Left Counter | 15654 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1102 | Regulator | 519-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1102 | Regulator | 519-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1102 | Regulator | 519-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1102 | Regulator | 519-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1102 | Regulator | 519-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | B0362 | LTCMechanism | 844-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Readings | 9 Month Operations | 1 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0313 | RecloserElectronic | 881-0316 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0313 | RecloserElectronic | 881-0316 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Readings | Amps A Ø | 180.0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Readings | Amps B Ø | 80.0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Readings | Amps C Ø | 180.0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0313 | RecloserElectronic | 881-0316 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | ST000347 | Structure | 655-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | ST000347 | Structure | 655-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | ST000347 | Structure | 655-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | ST000347 | Structure | 655-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | ST000347 | Structure | 655-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | ST000347 | Structure | 655-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | LTCC000878 | LTCControl | 844-2 | LTC Control Insp | VRR Time Delay | 45 | Seconds |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | LTCC000878 | LTCControl | 844-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | LTCC000878 | LTCControl | 844-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | LTCC000878 | LTCControl | 844-2 | LTC Control Insp | LTC Output Voltage Level | 124.8 | VAC |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | LTCC000878 | LTCControl | 844-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | LTCMechanism | 699-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | LTCMechanism | 699-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | LTCMechanism | 699-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | LTCMechanism | 699-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | LTCC000878 | LTCControl | 844-2 | LTC Control Insp | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | LTCC000878 | LTCControl | 844-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | LTCC000878 | LTCControl | 844-2 | LTC Control Insp | All Connections OK? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Readings | Amps C Ø | 110.0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Readings | Amps B Ø | 159.0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Readings | Amps A Ø | 141.0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Readings | 9 Month Operations | 0 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1102 | Regulator | 519-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1102 | Regulator | 519-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1102 | Regulator | 519-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1102 | Regulator | 519-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1102 | Regulator | 519-1 B | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1102 | Regulator | 519-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1102 | Regulator | 519-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1102 | Regulator | 519-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000154 | Regulator | 795-2 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000154 | Regulator | 795-2 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000154 | Regulator | 795-2 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000154 | Regulator | 795-2 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0313 | RecloserElectronic | 881-0316 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0313 | RecloserElectronic | 881-0316 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0313 | RecloserElectronic | 881-0316 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0313 | RecloserElectronic | 881-0316 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0313 | RecloserElectronic | 881-0316 | Recloser Electronic Patrol Inspection | Amps C Ø | 113.0 | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0313 | RecloserElectronic | 881-0316 | Recloser Electronic Patrol Inspection | Amps B Ø | 115.0 | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0313 | RecloserElectronic | 881-0316 | Recloser Electronic Patrol Inspection | Amps A Ø | 101.0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Readings | General Comments | | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Readings | LTC Totalizer Reading | 5621.76 | kw |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Readings | Oil Temp Max | 36 | °C |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Readings | Oil Temp Present | 36 | °C |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BCH001413 | Charger | 844-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.400 | millivolts |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BCH001413 | Charger | 844-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BCH001413 | Charger | 844-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BCH001413 | Charger | 844-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.3 | amps |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BCH001413 | Charger | 844-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BCH001413 | Charger | 844-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BCH001413 | Charger | 844-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BCH001413 | Charger | 844-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Readings | Totalizer Meter Reading | .5856 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Readings | 9 Month Operations | 1 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Readings | Amps A Ø | 9.0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000833 | BreakerVacuum | 795-0290 | VCB Readings | Amps B Ø | 9.0 | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0313 | RecloserElectronic | 881-0316 | Recloser Electronic Patrol Inspection | Operations Counter | 9 | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0313 | RecloserElectronic | 881-0316 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0313 | RecloserElectronic | 881-0316 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0313 | RecloserElectronic | 881-0316 | Recloser Electronic Patrol Inspection | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0313 | RecloserElectronic | 881-0316 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Readings | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Readings | Maintenance Operations | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Readings | Operations Counter AF | 231 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Readings | Operations Counter AL | 231 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Readings | Switching Operations | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0148 | BreakerVacuum | 844-2 | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | W0338 | WithLTC | 005-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | LTCMechanism | 699-1 | LTC Counter Readings | LTC As Found Counter | 15647 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | LTCMechanism | 699-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | LTCMechanism | 699-1 | LTC Counter Readings | General Comments | | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | LTCMechanism | 699-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | LTCMechanism | 699-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0313 | RecloserElectronic | 881-0316 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0313 | RecloserElectronic | 881-0316 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0313 | RecloserElectronic | 881-0316 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0313 | RecloserElectronic | 881-0316 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | MX0313 | RecloserElectronic | 881-0316 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Readings | Totalizer Meter Reading | .5832 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Readings | Winding Temp Max | 46 | °C |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | LTCMechanism | 795-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | LTCMechanism | 795-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | LTCMechanism | 795-1 | LTC Counter Readings | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | LTCMechanism | 795-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | LTCMechanism | 795-1 | LTC Counter Readings | LTC As Found Counter | 2401 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | LTCMechanism | 795-1 | LTC Counter Readings | LTC As Left Counter | 2412 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | LTCMechanism | 795-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | LTCMechanism | 795-1 | LTC Counter Readings | LTC Current Tap Position | 6R | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000152 | Regulator | 795-2 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000152 | Regulator | 795-2 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000152 | Regulator | 795-2 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000152 | Regulator | 795-2 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000152 | Regulator | 795-2 A | Regulator Patrol Inspection | Regulator As Left Counter | 21916 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000152 | Regulator | 795-2 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.6 | volts |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000152 | Regulator | 795-2 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000152 | Regulator | 795-2 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | LTCMechanism | 795-1 | LTC Counter Readings | LTC Max Tap Position | 10R | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | LTCMechanism | 795-1 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | LTCMechanism | 795-1 | LTC Counter Readings | LTC Operations Since Last Insp | 1258 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | LTCMechanism | 795-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | LTCMechanism | 795-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | M0061 | LTCMechanism | 795-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | FE000868 | Fence | 881-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | FE000868 | Fence | 881-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | FE000868 | Fence | 881-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | FE000868 | Fence | 881-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | FE000868 | Fence | 881-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Readings | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Readings | Maintenance Operations | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Readings | Operations Counter AF | 188 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Readings | Operations Counter AL | 188 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Readings | Operations This Read Vac | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Readings | Switching Operations | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | FE000105 | Fence | 795-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | FE000105 | Fence | 795-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | FE000105 | Fence | 795-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | FE000105 | Fence | 795-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | FE000105 | Fence | 795-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | FE000105 | Fence | 795-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | FE000105 | Fence | 795-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | FE000105 | Fence | 795-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | FE000105 | Fence | 795-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | FE000105 | Fence | 795-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | FE000105 | Fence | 795-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | FE000105 | Fence | 795-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | FE000105 | Fence | 795-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | FE000105 | Fence | 795-Fence | Fence Patrol Inspection | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | FE000105 | Fence | 795-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | FE000105 | Fence | 795-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | YD000106 | Yard | 795-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | YD000106 | Yard | 795-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | YD000106 | Yard | 795-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Readings | General Comments | | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Readings | LTC Totalizer Reading | 8398.08 | kw |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | YD000173 | Yard | 844-Yard | Yard Patrol Inspection | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | YD000173 | Yard | 844-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | YD000173 | Yard | 844-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Readings | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | YD000173 | Yard | 844-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | YD000173 | Yard | 844-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | FE000894 | Fence | 844-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | FE000894 | Fence | 844-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | FE000894 | Fence | 844-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000152 | Regulator | 795-2 A | Regulator Patrol Inspection | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000152 | Regulator | 795-2 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000152 | Regulator | 795-2 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Readings | Operations Counter AF | 172 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Readings | Operations Counter AL | 172 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Readings | Switching Operations | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000152 | Regulator | 795-2 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000152 | Regulator | 795-2 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000152 | Regulator | 795-2 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000152 | Regulator | 795-2 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000152 | Regulator | 795-2 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000152 | Regulator | 795-2 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000152 | Regulator | 795-2 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | FE000894 | Fence | 844-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | FE000894 | Fence | 844-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | FE000868 | Fence | 881-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | FE000868 | Fence | 881-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | FE000868 | Fence | 881-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | FE000868 | Fence | 881-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | FE000868 | Fence | 881-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | FE000868 | Fence | 881-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | FE000868 | Fence | 881-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | FE000868 | Fence | 881-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | FE000868 | Fence | 881-Fence | Fence Patrol Inspection | General Comments | | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | FE000868 | Fence | 881-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | FE000868 | Fence | 881-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | YD000173 | Yard | 844-Yard | Yard Patrol Inspection | Ambient Temp | 39 | °F |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | YD000173 | Yard | 844-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | YD000173 | Yard | 844-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | YD000173 | Yard | 844-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | YD000173 | Yard | 844-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | YD000173 | Yard | 844-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | YD000173 | Yard | 844-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | YD000173 | Yard | 844-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | YD000173 | Yard | 844-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | YD000173 | Yard | 844-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Readings | 9 Month Operations | 3 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000152 | Regulator | 795-2 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000152 | Regulator | 795-2 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000152 | Regulator | 795-2 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000152 | Regulator | 795-2 A | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000152 | Regulator | 795-2 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | FE000894 | Fence | 844-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | FE000894 | Fence | 844-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | FE000894 | Fence | 844-Fence | Fence Patrol Inspection | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | FE000894 | Fence | 844-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | FE000894 | Fence | 844-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | FE000894 | Fence | 844-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | FE000894 | Fence | 844-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | FE000894 | Fence | 844-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | FE000894 | Fence | 844-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | FE000894 | Fence | 844-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | FE000894 | Fence | 844-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000835 | BreakerVacuum | 795-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | LTCMechanism | 519-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Needs Replaced | check oil cup |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | LTCMechanism | 519-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | LTCMechanism | 519-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | LTCMechanism | 519-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Readings | 9 Month Operations | 4 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Readings | Switching Operations | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Readings | Operations This Read Vac | 1 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Readings | Operations Counter AL | 205 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Readings | Operations Counter AF | 205 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Readings | Maintenance Operations | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Readings | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Readings | Fault Operations B Ø | 1 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Readings | Fault Adjusted Amps B Phase V | 6.13 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Readings | 9 Month Operations | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000153 | Regulator | 795-2 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000153 | Regulator | 795-2 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000153 | Regulator | 795-2 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000153 | Regulator | 795-2 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000153 | Regulator | 795-2 B | Regulator Patrol Inspection | Regulator As Left Counter | 20546 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000153 | Regulator | 795-2 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000153 | Regulator | 795-2 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000153 | Regulator | 795-2 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000153 | Regulator | 795-2 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Readings | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Readings | Maintenance Operations | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Readings | Operations Counter AF | 255 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Readings | Operations Counter AL | 255 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Readings | Operations This Read Vac | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Readings | Switching Operations | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0178 | BreakerVacuum | 844-0279 | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | CAP000031 | CapacitorBank | 694-302 Cap Bank | Capacitor Patrol Inspection | Warning Signs OK? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | CAP000031 | CapacitorBank | 694-302 Cap Bank | Capacitor Patrol Inspection | Tank Paint Condition | Adequate | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | CAP000031 | CapacitorBank | 694-302 Cap Bank | Capacitor Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | CAP000031 | CapacitorBank | 694-302 Cap Bank | Capacitor Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | CAP000031 | CapacitorBank | 694-302 Cap Bank | Capacitor Patrol Inspection | Insulators In Good Condition? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | CAP000031 | CapacitorBank | 694-302 Cap Bank | Capacitor Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | CAP000031 | CapacitorBank | 694-302 Cap Bank | Capacitor Patrol Inspection | General Comments | | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | CAP000031 | CapacitorBank | 694-302 Cap Bank | Capacitor Patrol Inspection | Fuses Blown? Y / N | n | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | CAP000031 | CapacitorBank | 694-302 Cap Bank | Capacitor Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | CAP000031 | CapacitorBank | 694-302 Cap Bank | Capacitor Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | CAP000031 | CapacitorBank | 694-302 Cap Bank | Capacitor Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | CAP000031 | CapacitorBank | 694-302 Cap Bank | Capacitor Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | CAP000031 | CapacitorBank | 694-302 Cap Bank | Capacitor Patrol Inspection | Capacitor Rack Condition OK? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | CAP000031 | CapacitorBank | 694-302 Cap Bank | Capacitor Patrol Inspection | Capacitor Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | CAP000031 | CapacitorBank | 694-302 Cap Bank | Capacitor Patrol Inspection | Cap bank CT in Good Condition? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | CAP000031 | CapacitorBank | 694-302 Cap Bank | Capacitor Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | CAP000031 | CapacitorBank | 694-302 Cap Bank | Capacitor Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | CAP000031 | CapacitorBank | 694-302 Cap Bank | Capacitor Patrol Inspection | All Connections OK? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | LTCMechanism | 519-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | LTCMechanism | 519-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | LTCMechanism | 519-2 | LTC Counter Readings | General Comments | | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | LTCMechanism | 519-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | LTCMechanism | 519-2 | LTC Counter Readings | LTC As Found Counter | 385149 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | LTCMechanism | 519-2 | LTC Counter Readings | LTC As Left Counter | 385158 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | LTCMechanism | 519-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | LTCMechanism | 519-2 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | LTCMechanism | 519-2 | LTC Counter Readings | LTC Max Tap Position | 9R | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | LTCMechanism | 519-2 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | LTCMechanism | 519-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | LTCMechanism | 519-2 | LTC Counter Readings | LTC Operations Since Last Insp | 1225 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | YD000106 | Yard | 795-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | YD000106 | Yard | 795-Yard | Yard Patrol Inspection | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | YD000106 | Yard | 795-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | YD000106 | Yard | 795-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | YD000106 | Yard | 795-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | YD000106 | Yard | 795-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000153 | Regulator | 795-2 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000153 | Regulator | 795-2 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000153 | Regulator | 795-2 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000153 | Regulator | 795-2 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | FE000493 | Fence | 422-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | FE000493 | Fence | 422-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | FE000493 | Fence | 422-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | FE000493 | Fence | 422-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | FE000493 | Fence | 422-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | FE000493 | Fence | 422-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000153 | Regulator | 795-2 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000153 | Regulator | 795-2 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | FE000493 | Fence | 422-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | FE000493 | Fence | 422-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | FE000493 | Fence | 422-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | W0311 | WithLTC | 699-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | YD000106 | Yard | 795-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | FE000493 | Fence | 422-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | FE000493 | Fence | 422-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | FE000493 | Fence | 422-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | FE000493 | Fence | 422-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | FE000493 | Fence | 422-Fence | Fence Patrol Inspection | General Comments | | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | FE000493 | Fence | 422-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/7/2023 10:17 | Distribution | Bedford Quarterly Inspection | FE000493 | Fence | 422-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Readings | Amps A Ø | 0.0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Readings | Amps B Ø | 0.0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Readings | Amps C Ø | 0.0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000834 | BreakerVacuum | 795-0291 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000153 | Regulator | 795-2 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000153 | Regulator | 795-2 B | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Readings | Amps C Ø | 15.0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Readings | Amps B Ø | 72.0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Readings | Amps A Ø | 38.0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000153 | Regulator | 795-2 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000153 | Regulator | 795-2 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000153 | Regulator | 795-2 B | Regulator Patrol Inspection | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000153 | Regulator | 795-2 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000153 | Regulator | 795-2 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | RG000153 | Regulator | 795-2 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BK000735 | BreakerVacuum | 844-0276 | VCB Readings | 9 Month Operations | 7 | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | FE000842 | Fence | 022-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | FE000842 | Fence | 022-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | FE000842 | Fence | 022-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | FE000842 | Fence | 022-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | FE000842 | Fence | 022-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | FE000842 | Fence | 022-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | FE000842 | Fence | 022-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | FE000842 | Fence | 022-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | FE000842 | Fence | 022-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | FE000842 | Fence | 022-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | FE000842 | Fence | 022-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | FE000842 | Fence | 022-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | FE000842 | Fence | 022-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | FE000842 | Fence | 022-Fence | Fence Patrol Inspection | General Comments | Frankfort sub fence attached to ours | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | FE000842 | Fence | 022-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | FE000842 | Fence | 022-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | YD000106 | Yard | 795-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | YD000106 | Yard | 795-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | YD000106 | Yard | 795-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | n | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | YD000115 | Yard | 881-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | YD000115 | Yard | 881-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | YD000115 | Yard | 881-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | YD000115 | Yard | 881-Yard | Yard Patrol Inspection | General Comments | | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | YD000115 | Yard | 881-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | YD000115 | Yard | 881-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | YD000115 | Yard | 881-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | YD000115 | Yard | 881-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | YD000115 | Yard | 881-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | YD000115 | Yard | 881-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | YD000115 | Yard | 881-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | YD000115 | Yard | 881-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | YD000115 | Yard | 881-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | YD000115 | Yard | 881-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Readings | Totalizer Meter Reading | .8736 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0007 | NonLTC | 519-1 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0007 | NonLTC | 519-1 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0007 | NonLTC | 519-1 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0007 | NonLTC | 519-1 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | R0763 | Regulator | 881-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Readings | 9 Month Operations | 2 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Readings | Amps A Ø | 162.0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Readings | Amps B Ø | 128.0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Readings | Amps C Ø | 132.0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 1800 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | FE000176 | Fence | 519-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Patrol Inspection | General Comments | Needs new nitrogen gauge. | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Readings | General Comments | | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Readings | 9 Month Operations | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Readings | General Comments | | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Readings | Operations Counter AF | 63 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Readings | Operations Counter AL | 63 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Readings | Switching Operations | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001526 | BreakerVacuum | 462-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Readings | Maintenance Operations | 1 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Readings | Operations Counter AF | 11 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Readings | Operations Counter AL | 11 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Readings | Operations This Read Vac | 1 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Readings | Switching Operations | 0 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0007 | NonLTC | 519-1 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0007 | NonLTC | 519-1 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0007 | NonLTC | 519-1 B | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0007 | NonLTC | 519-1 B | NonLTC Transformer Readings | Oil Temp Present | 23 | °C |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0007 | NonLTC | 519-1 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Readings | 9 Month Operations | 2 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Readings | Amps A Ø | 0.0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Readings | Amps B Ø | 0.0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Readings | Amps C Ø | 0.0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Readings | General Comments | | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Readings | Maintenance Operations | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Readings | Operations Counter AF | 172 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Readings | Operations Counter AL | 172 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Readings | Operations This Read Vac | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Readings | Switching Operations | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001528 | BreakerVacuum | 462-0297 | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0007 | NonLTC | 519-1 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0007 | NonLTC | 519-1 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Readings | General Comments | | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Readings | Maintenance Operations | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Readings | Operations Counter AF | 94 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Readings | Operations Counter AL | 94 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Readings | Operations This Read Vac | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Readings | Switching Operations | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001527 | BreakerVacuum | 462-0296 | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | R0763 | Regulator | 881-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | R0763 | Regulator | 881-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | R0763 | Regulator | 881-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | R0763 | Regulator | 881-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | LTCMechanism | 655-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0007 | NonLTC | 519-1 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0007 | NonLTC | 519-1 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0007 | NonLTC | 519-1 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0007 | NonLTC | 519-1 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0007 | NonLTC | 519-1 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0007 | NonLTC | 519-1 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0007 | NonLTC | 519-1 B | NonLTC Transformer Readings | General Comments | | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0007 | NonLTC | 519-1 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0007 | NonLTC | 519-1 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Readings | General Comments | | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Readings | Amps A Ø | 225.0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Readings | Amps B Ø | 175.0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Readings | Amps C Ø | 226.0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Readings | General Comments | | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Readings | Operations Counter AF | 128 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Readings | Operations Counter AL | 128 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Readings | Switching Operations | 0 | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | ST000393 | Structure | 701-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | ST000393 | Structure | 701-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | ST000393 | Structure | 701-Structure | Structure Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | ST000393 | Structure | 701-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | ST000393 | Structure | 701-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | ST000393 | Structure | 701-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | ST000393 | Structure | 701-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | ST000393 | Structure | 701-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | ST000393 | Structure | 701-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | LTCMechanism | 694-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | LTCMechanism | 694-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | LTCMechanism | 694-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | ST000181 | Structure | 519-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | ST000181 | Structure | 519-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | ST000181 | Structure | 519-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | ST000393 | Structure | 701-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | ST000393 | Structure | 701-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | ST000393 | Structure | 701-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1289 | Regulator | 447-1 A | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1289 | Regulator | 447-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1289 | Regulator | 447-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1289 | Regulator | 447-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1289 | Regulator | 447-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1289 | Regulator | 447-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1289 | Regulator | 447-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1289 | Regulator | 447-1 A | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | FE000386 | Fence | 701-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | FE000386 | Fence | 701-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | FE000386 | Fence | 701-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | FE000386 | Fence | 701-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | FE000386 | Fence | 701-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | FE000386 | Fence | 701-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | FE000386 | Fence | 701-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | FE000386 | Fence | 701-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | FE000386 | Fence | 701-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | FE000386 | Fence | 701-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | FE000386 | Fence | 701-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | FE000386 | Fence | 701-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | FE000386 | Fence | 701-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | ST000393 | Structure | 701-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | ST000393 | Structure | 701-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | ST000393 | Structure | 701-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | ST000393 | Structure | 701-Structure | Structure Patrol Inspection | General Comments | | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | FE000386 | Fence | 701-Fence | Fence Patrol Inspection | General Comments | | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | FE000386 | Fence | 701-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | FE000386 | Fence | 701-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1289 | Regulator | 447-1 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1289 | Regulator | 447-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1289 | Regulator | 447-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1289 | Regulator | 447-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1289 | Regulator | 447-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1289 | Regulator | 447-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1289 | Regulator | 447-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 64957 | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1289 | Regulator | 447-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1289 | Regulator | 447-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1289 | Regulator | 447-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Readings | 9 Month Operations | 1 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Readings | 9 Month Operations | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001525 | BreakerVacuum | 462-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | YD000174 | Yard | 519-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | YD000174 | Yard | 519-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | YD000174 | Yard | 519-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | YD000174 | Yard | 519-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | FE000176 | Fence | 519-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .5094 | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | FE000176 | Fence | 519-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | FE000176 | Fence | 519-Fence | Fence Patrol Inspection | General Comments | fence fabric and railing rusty | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | FE000176 | Fence | 519-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | FE000176 | Fence | 519-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | FE000176 | Fence | 519-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | FE000176 | Fence | 519-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | FE000176 | Fence | 519-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | FE000176 | Fence | 519-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | FE000176 | Fence | 519-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | FE000176 | Fence | 519-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | FE000176 | Fence | 519-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | FE000176 | Fence | 519-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | FE000176 | Fence | 519-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | n | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | FE000176 | Fence | 519-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Readings | Top Oil Temperature Present | 30 | °C |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Readings | Top Oil Temperature Max | 35 | °C |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 10.00 | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1222.56 | kw |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | W0219 | NonLTC | 447-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Readings | General Comments | | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Readings | LTC Totalizer Reading | 1572.48 | kw |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Readings | Oil Temp Max | 48 | °C |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Readings | Oil Temp Present | 32 | °C |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | ST000181 | Structure | 519-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | ST000181 | Structure | 519-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | ST000181 | Structure | 519-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | ST000181 | Structure | 519-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | ST000181 | Structure | 519-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | ST000181 | Structure | 519-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Readings | Amps A Ø | 240.0 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Readings | Amps B Ø | 235.0 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Readings | Amps C Ø | 225.0 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0013 | BreakerVacuum | 699-1805 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | ST000181 | Structure | 519-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | ST000181 | Structure | 519-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | ST000181 | Structure | 519-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | ST000181 | Structure | 519-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | ST000181 | Structure | 519-Structure | Structure Patrol Inspection | General Comments | | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | ST000181 | Structure | 519-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | ST000181 | Structure | 519-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | ST000181 | Structure | 519-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | O0189 | WithLTC | 519-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | ST000181 | Structure | 519-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | ST000181 | Structure | 519-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | ST000181 | Structure | 519-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | ST000181 | Structure | 519-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | ST000181 | Structure | 519-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | ST000181 | Structure | 519-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | YD000174 | Yard | 519-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | YD000174 | Yard | 519-Yard | Yard Patrol Inspection | Vegetation | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | YD000174 | Yard | 519-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | YD000174 | Yard | 519-Yard | Yard Patrol Inspection | General Comments | | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | YD000174 | Yard | 519-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | YD000174 | Yard | 519-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | YD000174 | Yard | 519-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | YD000174 | Yard | 519-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | YD000174 | Yard | 519-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Readings | 9 Month Operations | 1 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1103 | Regulator | 519-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1103 | Regulator | 519-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1103 | Regulator | 519-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1103 | Regulator | 519-1 C | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1103 | Regulator | 519-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1103 | Regulator | 519-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1103 | Regulator | 519-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1103 | Regulator | 519-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1103 | Regulator | 519-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1103 | Regulator | 519-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1103 | Regulator | 519-1 C | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1103 | Regulator | 519-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1103 | Regulator | 519-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1103 | Regulator | 519-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1103 | Regulator | 519-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1103 | Regulator | 519-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | FE000206 | Fence | 005-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | FE000206 | Fence | 005-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | FE000206 | Fence | 005-Fence | Fence Patrol Inspection | General Comments | | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | FE000206 | Fence | 005-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | FE000206 | Fence | 005-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | FE000206 | Fence | 005-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | FE000206 | Fence | 005-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | FE000206 | Fence | 005-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | FE000206 | Fence | 005-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | FE000206 | Fence | 005-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | FE000206 | Fence | 005-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | FE000206 | Fence | 005-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | FE000206 | Fence | 005-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Readings | General Comments | trip check | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | KB0103 | BreakerVacuum | 022-3411 | VCB Readings | Switching Operations | 0 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1103 | Regulator | 519-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1103 | Regulator | 519-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1103 | Regulator | 519-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1103 | Regulator | 519-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1103 | Regulator | 519-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 116739 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1103 | Regulator | 519-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 125.5 | volts |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1000 | psi |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Readings | LTC Totalizer Reading | 18624.00 | kw |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1103 | Regulator | 519-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1103 | Regulator | 519-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Readings | Amps C Ø | 32.0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Readings | Amps B Ø | 29.0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Readings | General Comments | | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Readings | Amps A Ø | 30.0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | YD000344 | Yard | 655-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | YD000344 | Yard | 655-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | YD000344 | Yard | 655-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | YD000344 | Yard | 655-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | YD000344 | Yard | 655-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | YD000344 | Yard | 655-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | YD000344 | Yard | 655-Yard | Yard Patrol Inspection | General Comments | | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | YD000344 | Yard | 655-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | YD000344 | Yard | 655-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | YD000344 | Yard | 655-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | YD000344 | Yard | 655-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | ST000347 | Structure | 655-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | ST000347 | Structure | 655-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | ST000347 | Structure | 655-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | ST000347 | Structure | 655-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | ST000347 | Structure | 655-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | ST000347 | Structure | 655-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | ST000347 | Structure | 655-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Readings | Switching Operations | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Readings | Operations This Read Vac | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Readings | Operations Counter AL | 331 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Readings | Operations Counter AF | 331 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | ST000347 | Structure | 655-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | ST000347 | Structure | 655-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | ST000347 | Structure | 655-Structure | Structure Patrol Inspection | General Comments | | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | ST000347 | Structure | 655-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | ST000347 | Structure | 655-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | ST000347 | Structure | 655-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | ST000347 | Structure | 655-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | ST000347 | Structure | 655-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Readings | Maintenance Operations | 0 | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | ST000347 | Structure | 655-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Readings | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0180 | BreakerVacuum | 844-0278 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | FE000206 | Fence | 005-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | FE000206 | Fence | 005-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | FE000206 | Fence | 005-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BAT001472 | Battery | 844-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BAT001472 | Battery | 844-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 55 | °F |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BAT001472 | Battery | 844-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BAT001472 | Battery | 844-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BAT001472 | Battery | 844-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BAT001472 | Battery | 844-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BAT001472 | Battery | 844-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BAT001472 | Battery | 844-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BAT001472 | Battery | 844-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BAT001472 | Battery | 844-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BAT001472 | Battery | 844-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1102 | Regulator | 519-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1102 | Regulator | 519-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1102 | Regulator | 519-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1102 | Regulator | 519-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1102 | Regulator | 519-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 134361 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BAT001472 | Battery | 844-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1102 | Regulator | 519-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.4 | volts |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1102 | Regulator | 519-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BAT001472 | Battery | 844-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | BAT001472 | Battery | 844-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | CH000069 | ControlHouse | 005-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | CH000069 | ControlHouse | 005-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | CH000069 | ControlHouse | 005-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | CH000069 | ControlHouse | 005-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | CH000069 | ControlHouse | 005-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | CH000069 | ControlHouse | 005-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | CH000069 | ControlHouse | 005-Control House | Control House Patrol Inspection | General Comments | | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | CH000069 | ControlHouse | 005-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | CH000069 | ControlHouse | 005-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | CH000069 | ControlHouse | 005-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | CH000069 | ControlHouse | 005-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | CH000069 | ControlHouse | 005-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | CH000069 | ControlHouse | 005-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | CH000069 | ControlHouse | 005-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | CH000069 | ControlHouse | 005-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | CH000069 | ControlHouse | 005-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | CH000069 | ControlHouse | 005-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | CH000069 | ControlHouse | 005-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | CH000069 | ControlHouse | 005-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | YD000344 | Yard | 655-Yard | Yard Patrol Inspection | Ambient Temp | 32 | °F |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | YD000344 | Yard | 655-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | YD000344 | Yard | 655-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | YD000344 | Yard | 655-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Readings | General Comments | | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Readings | Maintenance Operations | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Readings | Operations Counter AF | 140 | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | R0763 | Regulator | 881-1 C | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | R0763 | Regulator | 881-1 C | Regulator Patrol Inspection | Min Tap Position | 4L | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | R0763 | Regulator | 881-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | R0763 | Regulator | 881-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | R0763 | Regulator | 881-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | R0763 | Regulator | 881-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | R0763 | Regulator | 881-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 125.0 | volts |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | R0763 | Regulator | 881-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 181345 | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | R0763 | Regulator | 881-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Readings | Operations Counter AL | 140 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Readings | Operations This Read Vac | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Readings | Switching Operations | 0 | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | R0763 | Regulator | 881-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | R0763 | Regulator | 881-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0008 | NonLTC | 519-1 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0008 | NonLTC | 519-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0008 | NonLTC | 519-1 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0008 | NonLTC | 519-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0008 | NonLTC | 519-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0008 | NonLTC | 519-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0008 | NonLTC | 519-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Readings | X3 Winding Temp Present | 20 | °C |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Readings | X3 Winding Temp Max | 40 | °C |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Readings | X2 Winding Temp Present | 20 | °C |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Readings | X2 Winding Temp Max | 40 | °C |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Readings | X1 Winding Temp Present | 20 | °C |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Readings | X1 Winding Temp Max | 40 | °C |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0007 | NonLTC | 519-1 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | LTCMechanism | 655-1 | LTC Counter Readings | LTC As Found Counter | 161232 | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | LTCMechanism | 655-1 | LTC Counter Readings | LTC As Left Counter | 161232 | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | LTCMechanism | 655-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | LTCMechanism | 655-1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | LTCMechanism | 655-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | LTCMechanism | 655-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | LTCMechanism | 655-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | LTCMechanism | 655-1 | LTC Counter Readings | LTC Operations Since Last Insp | 220 | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | LTCMechanism | 655-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | LTCMechanism | 655-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | LTCMechanism | 655-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | LTCMechanism | 655-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0007 | NonLTC | 519-1 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0007 | NonLTC | 519-1 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | R0763 | Regulator | 881-1 C | Regulator Patrol Inspection | Current Tap Position | 2R | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | R0763 | Regulator | 881-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | R0763 | Regulator | 881-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | R0763 | Regulator | 881-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | R0763 | Regulator | 881-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | R0763 | Regulator | 881-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | R0763 | Regulator | 881-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | CH000534 | ControlHouse | 844-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | CH000534 | ControlHouse | 844-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | CH000534 | ControlHouse | 844-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | CH000534 | ControlHouse | 844-Control House | Control House Patrol Inspection | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | CH000534 | ControlHouse | 844-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | CH000534 | ControlHouse | 844-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | CH000534 | ControlHouse | 844-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | CH000534 | ControlHouse | 844-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | CH000534 | ControlHouse | 844-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | CH000534 | ControlHouse | 844-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | CH000534 | ControlHouse | 844-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | CH000534 | ControlHouse | 844-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | CH000534 | ControlHouse | 844-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | CH000534 | ControlHouse | 844-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Readings | 9 Month Operations | 5 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Readings | Amps A Ø | 63.0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Readings | Amps B Ø | 46.0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Readings | Amps C Ø | 89.0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001529 | BreakerVacuum | 462-0298 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Readings | General Comments | | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Readings | Operations Counter AF | 186 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Readings | Operations Counter AL | 186 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Readings | Operations This Read Vac | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Readings | Switching Operations | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0009 | NonLTC | 519-1 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0009 | NonLTC | 519-1 C | NonLTC Transformer Readings | General Comments | | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0009 | NonLTC | 519-1 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0009 | NonLTC | 519-1 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0009 | NonLTC | 519-1 C | NonLTC Transformer Readings | Non LTC Totalizer Reading | 697.20 | kw |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0009 | NonLTC | 519-1 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0009 | NonLTC | 519-1 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0009 | NonLTC | 519-1 C | NonLTC Transformer Readings | Oil Temp Max | 46 | °C |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0009 | NonLTC | 519-1 C | NonLTC Transformer Readings | Oil Temp Present | 23 | °C |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0009 | NonLTC | 519-1 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0009 | NonLTC | 519-1 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0009 | NonLTC | 519-1 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0009 | NonLTC | 519-1 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0009 | NonLTC | 519-1 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0009 | NonLTC | 519-1 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0009 | NonLTC | 519-1 C | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0009 | NonLTC | 519-1 C | NonLTC Transformer Readings | Totalizer Meter Reading | .5810 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Readings | Switching Operations | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Readings | Operations This Read Vac | 1 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Readings | Operations Counter AL | 203 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Readings | Operations Counter AF | 203 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Readings | Maintenance Operations | 1 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000906 | BreakerVacuum | 005-1477 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Readings | Winding Temp Present | 20 | °C |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Readings | Totalizer Meter Reading | .7760 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0008 | NonLTC | 519-1 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0008 | NonLTC | 519-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0008 | NonLTC | 519-1 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0008 | NonLTC | 519-1 A | NonLTC Transformer Readings | General Comments | | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0008 | NonLTC | 519-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0008 | NonLTC | 519-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0008 | NonLTC | 519-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0008 | NonLTC | 519-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0008 | NonLTC | 519-1 A | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0008 | NonLTC | 519-1 A | NonLTC Transformer Readings | Oil Temp Present | 22 | °C |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0008 | NonLTC | 519-1 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0008 | NonLTC | 519-1 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0008 | NonLTC | 519-1 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0008 | NonLTC | 519-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0008 | NonLTC | 519-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0008 | NonLTC | 519-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0009 | NonLTC | 519-1 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0009 | NonLTC | 519-1 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0009 | NonLTC | 519-1 C | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0009 | NonLTC | 519-1 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0009 | NonLTC | 519-1 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | TX000255 | WithLTC | 462-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0009 | NonLTC | 519-1 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0009 | NonLTC | 519-1 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0009 | NonLTC | 519-1 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | M0009 | NonLTC | 519-1 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Readings | 9 Month Operations | 2 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Readings | Amps A Ø | 0.0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Readings | Amps B Ø | 0.0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Readings | Amps C Ø | 0.0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | BK001530 | BreakerVacuum | 462-0299 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | ST000213 | Structure | 005-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | ST000213 | Structure | 005-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | ST000213 | Structure | 005-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | ST000213 | Structure | 005-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | ST000213 | Structure | 005-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | ST000213 | Structure | 005-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | ST000213 | Structure | 005-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | ST000213 | Structure | 005-Structure | Structure Patrol Inspection | General Comments | | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | ST000213 | Structure | 005-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | ST000213 | Structure | 005-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | ST000213 | Structure | 005-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Readings | General Comments | | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Readings | LTC Totalizer Reading | 0.00 | kw |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Readings | Amps C Ø | 310.0 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Readings | Amps B Ø | 273.0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Readings | Amps A Ø | 252.0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1288 | Regulator | 447-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1288 | Regulator | 447-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1288 | Regulator | 447-1 B | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1288 | Regulator | 447-1 B | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1288 | Regulator | 447-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1288 | Regulator | 447-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1288 | Regulator | 447-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1288 | Regulator | 447-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1288 | Regulator | 447-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1288 | Regulator | 447-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | FE000340 | Fence | 655-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | FE000340 | Fence | 655-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | FE000340 | Fence | 655-Fence | Fence Patrol Inspection | General Comments | | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | FE000340 | Fence | 655-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | FE000340 | Fence | 655-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000027 | ControlHouse | 795-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000027 | ControlHouse | 795-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000027 | ControlHouse | 795-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000027 | ControlHouse | 795-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000027 | ControlHouse | 795-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000027 | ControlHouse | 795-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000027 | ControlHouse | 795-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1288 | Regulator | 447-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1288 | Regulator | 447-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1288 | Regulator | 447-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 60546 | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1288 | Regulator | 447-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000027 | ControlHouse | 795-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000027 | ControlHouse | 795-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000027 | ControlHouse | 795-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000027 | ControlHouse | 795-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000027 | ControlHouse | 795-Control House | Control House Patrol Inspection | General Comments | NIT IN USE | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000027 | ControlHouse | 795-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000027 | ControlHouse | 795-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1288 | Regulator | 447-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1288 | Regulator | 447-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000027 | ControlHouse | 795-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000027 | ControlHouse | 795-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | ST000213 | Structure | 005-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | ST000213 | Structure | 005-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | ST000281 | Structure | 022-Structure | Structure Patrol Inspection | General Comments | | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | ST000281 | Structure | 022-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | ST000281 | Structure | 022-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | ST000281 | Structure | 022-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | ST000281 | Structure | 022-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | ST000213 | Structure | 005-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | ST000213 | Structure | 005-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | ST000281 | Structure | 022-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | ST000213 | Structure | 005-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | ST000213 | Structure | 005-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | ST000213 | Structure | 005-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | ST000213 | Structure | 005-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | ST000213 | Structure | 005-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | ST000213 | Structure | 005-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | ST000213 | Structure | 005-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | ST000213 | Structure | 005-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | ST000213 | Structure | 005-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | ST000281 | Structure | 022-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | ST000281 | Structure | 022-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | ST000281 | Structure | 022-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | ST000281 | Structure | 022-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | ST000281 | Structure | 022-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | ST000281 | Structure | 022-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | ST000281 | Structure | 022-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | LTCC000801 | LTCControl | 655-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | LTCC000801 | LTCControl | 655-1 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | LTCC000801 | LTCControl | 655-1 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000435 | ControlHouse | 795-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | LTCC000801 | LTCControl | 655-1 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | LTCC000801 | LTCControl | 655-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | LTCC000801 | LTCControl | 655-1 | LTC Control Insp | General Comments | | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | LTCC000801 | LTCControl | 655-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | LTCC000801 | LTCControl | 655-1 | LTC Control Insp | All Connections OK? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Readings | Oil Temp Present | 15 | °C |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | B0399 | WithLTC | 694-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1288 | Regulator | 447-1 B | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Readings | 9 Month Operations | 5 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | LTCC000647 | LTCControl | 694-1 | LTC Control Insp | All Connections OK? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | LTCC000647 | LTCControl | 694-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | LTCC000647 | LTCControl | 694-1 | LTC Control Insp | General Comments | | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | LTCC000647 | LTCControl | 694-1 | LTC Control Insp | LTC Operation Checked? | n | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | LTCC000647 | LTCControl | 694-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | LTCC000647 | LTCControl | 694-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | LTCC000647 | LTCControl | 694-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | LTCC000647 | LTCControl | 694-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | LTCC000784 | LTCControl | 699-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | LTCC000784 | LTCControl | 699-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | LTCC000784 | LTCControl | 699-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | LTCC000784 | LTCControl | 699-1 | LTC Control Insp | LTC Output Voltage Level | 124.8 | VAC |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | LTCC000784 | LTCControl | 699-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | LTCC000784 | LTCControl | 699-1 | LTC Control Insp | General Comments | | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | LTCC000784 | LTCControl | 699-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1288 | Regulator | 447-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1288 | Regulator | 447-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1288 | Regulator | 447-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1288 | Regulator | 447-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | R1288 | Regulator | 447-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | LTCC000784 | LTCControl | 699-1 | LTC Control Insp | All Connections OK? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000435 | ControlHouse | 795-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000435 | ControlHouse | 795-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000435 | ControlHouse | 795-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | ST000281 | Structure | 022-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | ST000281 | Structure | 022-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | ST000281 | Structure | 022-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | ST000281 | Structure | 022-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | ST000281 | Structure | 022-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | ST000281 | Structure | 022-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | ST000281 | Structure | 022-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | FE000340 | Fence | 655-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | FE000340 | Fence | 655-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | FE000340 | Fence | 655-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | FE000340 | Fence | 655-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | FE000340 | Fence | 655-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | FE000340 | Fence | 655-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | FE000340 | Fence | 655-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | FE000340 | Fence | 655-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | FE000340 | Fence | 655-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Readings | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | LTCC000747 | LTCControl | 005-5 | LTC Control Insp | All Connections OK? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | LTCC000747 | LTCControl | 005-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | LTCC000747 | LTCControl | 005-5 | LTC Control Insp | General Comments | | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | LTCC000747 | LTCControl | 005-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | LTCC000747 | LTCControl | 005-5 | LTC Control Insp | LTC Output Voltage Level | 124.6 | VAC |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | LTCC000747 | LTCControl | 005-5 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BAT001369 | Battery | 655-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BAT001369 | Battery | 655-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BAT001369 | Battery | 655-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BAT001369 | Battery | 655-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BAT001369 | Battery | 655-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BAT001369 | Battery | 655-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BAT001369 | Battery | 655-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Readings | Maintenance Operations | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | YD000074 | Yard | 632-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | YD000074 | Yard | 632-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | YD000074 | Yard | 632-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | YD000074 | Yard | 632-Yard | Yard Patrol Inspection | General Comments | | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | YD000074 | Yard | 632-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | YD000074 | Yard | 632-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | YD000074 | Yard | 632-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Readings | 9 Month Operations | 4 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Readings | Amps A Ø | 0.0 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Readings | Amps B Ø | 0.0 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Readings | Amps C Ø | 0.0 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BCH001283 | Charger | 655-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BCH001283 | Charger | 655-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BCH001283 | Charger | 655-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BCH001283 | Charger | 655-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BCH001283 | Charger | 655-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BCH001283 | Charger | 655-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BCH001283 | Charger | 655-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BCH001283 | Charger | 655-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BAT001369 | Battery | 655-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BAT001369 | Battery | 655-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 35 | °F |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BAT001369 | Battery | 655-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Readings | Amps C Ø | 89.0 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Readings | General Comments | | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Readings | Maintenance Operations | 1 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Readings | Operations Counter AF | 208 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Readings | Operations Counter AL | 208 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Readings | Operations This Read Vac | 1 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Readings | Switching Operations | 0 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BAT001202 | Battery | 005-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BAT001202 | Battery | 005-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BAT001202 | Battery | 005-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 66.3 | VDC |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BAT001202 | Battery | 005-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 67.0 | VDC |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BAT001202 | Battery | 005-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BAT001202 | Battery | 005-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BAT001202 | Battery | 005-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BAT001202 | Battery | 005-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BAT001202 | Battery | 005-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BAT001202 | Battery | 005-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BAT001202 | Battery | 005-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BAT001202 | Battery | 005-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BAT001202 | Battery | 005-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 69 | °F |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BAT001202 | Battery | 005-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | FE000340 | Fence | 655-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | FE000340 | Fence | 655-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Readings | Amps C Ø | 8.0 | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BAT001369 | Battery | 655-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | LTCC000747 | LTCControl | 005-5 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | LTCC000747 | LTCControl | 005-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Readings | Amps B Ø | 8.0 | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BAT001369 | Battery | 655-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | BAT001369 | Battery | 655-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Readings | 9 Month Operations | 1 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Readings | Amps A Ø | 8.0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Readings | 9 Month Operations | 2 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BCH001223 | Charger | 699-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .700 | millivolts |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BCH001223 | Charger | 699-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BCH001223 | Charger | 699-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BCH001223 | Charger | 699-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .8 | amps |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Readings | Switching Operations | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Readings | Operations This Read Vac | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Readings | Operations Counter AL | 195 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Readings | Operations Counter AF | 195 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Readings | Maintenance Operations | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Readings | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Readings | Amps A Ø | 93.0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BCH001223 | Charger | 699-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BCH001223 | Charger | 699-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000925 | BreakerVacuum | 795-0288 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | BK000540 | BreakerVacuum | 699-1807 | VCB Readings | Amps B Ø | 104.0 | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | YD000223 | Yard | 447-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | YD000223 | Yard | 447-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | YD000223 | Yard | 447-Yard | Yard Patrol Inspection | General Comments | | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | YD000223 | Yard | 447-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | YD000223 | Yard | 447-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | YD000223 | Yard | 447-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Gas Accumulation Gauge | Normal | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Readings | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1400 | psi |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 172.80 | kw |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Readings | Oil Temp Max | 30 | °C |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | LTCM000052 | LTCMechanism | 005-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | LTCM000052 | LTCMechanism | 005-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | LTCM000052 | LTCMechanism | 005-5 | LTC Counter Readings | General Comments | | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | LTCM000052 | LTCMechanism | 005-5 | LTC Mechanism Patrol Inspection | General Comments | Not a LTC Temp. guage | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | LTCM000052 | LTCMechanism | 005-5 | LTC Counter Readings | LTC As Found Counter | 21540 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | LTCM000052 | LTCMechanism | 005-5 | LTC Counter Readings | LTC As Left Counter | 21548 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | LTCM000052 | LTCMechanism | 005-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | LTCM000052 | LTCMechanism | 005-5 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | LTCM000052 | LTCMechanism | 005-5 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | LTCM000052 | LTCMechanism | 005-5 | LTC Counter Readings | LTC Min Tap Position | 16L | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Readings | Totalizer Meter Reading | .5076 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Readings | Winding Temp Max | 45 | °C |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Readings | Winding Temp Present | 37 | °C |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 20.00 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | YD000223 | Yard | 447-Yard | Yard Patrol Inspection | Ambient Temp | 38 | °F |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | YD000223 | Yard | 447-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | YD000223 | Yard | 447-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | YD000223 | Yard | 447-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCM000108 | LTCMechanism | 462-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCM000108 | LTCMechanism | 462-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCM000108 | LTCMechanism | 462-1 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCM000108 | LTCMechanism | 462-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCM000108 | LTCMechanism | 462-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCM000108 | LTCMechanism | 462-1 | LTC Counter Readings | LTC Operations Since Last Insp | 322 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCM000108 | LTCMechanism | 462-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 20 | °C |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCM000108 | LTCMechanism | 462-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 35 | °C |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCM000108 | LTCMechanism | 462-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCM000108 | LTCMechanism | 462-1 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCM000108 | LTCMechanism | 462-1 | LTC Counter Readings | LTC Max Tap Position | 5R | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCM000108 | LTCMechanism | 462-1 | LTC Counter Readings | LTC Current Tap Position | 1R | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCM000108 | LTCMechanism | 462-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCM000108 | LTCMechanism | 462-1 | LTC Counter Readings | LTC As Left Counter | 3900 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCM000108 | LTCMechanism | 462-1 | LTC Counter Readings | LTC As Found Counter | 3900 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCM000108 | LTCMechanism | 462-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCM000108 | LTCMechanism | 462-1 | LTC Counter Readings | General Comments | | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCM000108 | LTCMechanism | 462-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCM000108 | LTCMechanism | 462-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | YD000223 | Yard | 447-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | YD000223 | Yard | 447-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | YD000223 | Yard | 447-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | YD000223 | Yard | 447-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Readings | Fault Adjusted Amps C Phase V | 8.38 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Readings | Fault Adjusted Amps B Phase V | 8.38 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Readings | Fault Adjusted Amps A Phase V | 8.38 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Readings | Amps C Ø | 3.0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Readings | Amps B Ø | 4.0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Readings | Amps A Ø | 0.0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Readings | 9 Month Operations | 5 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Readings | Amps C Ø | 340.0 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Readings | Amps B Ø | 360.0 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Readings | Amps A Ø | 340.0 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Readings | 9 Month Operations | 1 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Readings | Totalizer Meter Reading | .0180 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | LTCM000052 | LTCMechanism | 005-5 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Readings | Winding Temp Max | 30 | °C |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Readings | Unknown Operations | 2 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Readings | Switching Operations | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Readings | Operations This Read Vac | 2 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Readings | Operations Counter AL | 199 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | LTCM000052 | LTCMechanism | 005-5 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | LTCM000052 | LTCMechanism | 005-5 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 0 | °C |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | LTCM000052 | LTCMechanism | 005-5 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 0 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | TX000204 | NonLTC | 795-2 | NonLTC Transformer Readings | Winding Temp Present | 18 | °C |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | LTCM000052 | LTCMechanism | 005-5 | LTC Counter Readings | LTC Operations Since Last Insp | 573 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | LTCM000052 | LTCMechanism | 005-5 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | LTCM000052 | LTCMechanism | 005-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | LTCM000052 | LTCMechanism | 005-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | LTCM000052 | LTCMechanism | 005-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Readings | Switching Operations | 0 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Readings | Operations This Read Vac | 1 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Readings | Operations Counter AL | 161 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Readings | Operations Counter AF | 161 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Readings | Maintenance Operations | 1 | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | K0136 | BreakerVacuum | 699-1 | VCB Readings | General Comments | | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Readings | Operations Counter AF | 199 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Readings | Maintenance Operations | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Readings | General Comments | | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | BK000009 | BreakerVacuum | 005-3409 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000435 | ControlHouse | 795-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000435 | ControlHouse | 795-Control House | Control House Patrol Inspection | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000435 | ControlHouse | 795-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000435 | ControlHouse | 795-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | FE000871 | Fence | 462-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | FE000871 | Fence | 462-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | FE000871 | Fence | 462-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | FE000871 | Fence | 462-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | FE000871 | Fence | 462-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | FE000871 | Fence | 462-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | FE000871 | Fence | 462-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | FE000871 | Fence | 462-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | FE000871 | Fence | 462-Fence | Fence Patrol Inspection | General Comments | | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | FE000871 | Fence | 462-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | FE000871 | Fence | 462-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000435 | ControlHouse | 795-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000435 | ControlHouse | 795-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000435 | ControlHouse | 795-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Readings | Winding Temp Present | 30 | °C |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Readings | Winding Temp Max | 70 | °C |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | X0354 | RecloserHydraulic | 701-0720 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 5.0 | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | X0354 | RecloserHydraulic | 701-0720 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 9.0 | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | X0354 | RecloserHydraulic | 701-0720 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 22.0 | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | X0354 | RecloserHydraulic | 701-0720 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 0 | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Readings | Oil Temp Max | 60 | °C |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1300 | psi |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | ST000853 | Structure | 462-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | ST000853 | Structure | 462-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | ST000853 | Structure | 462-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | ST000853 | Structure | 462-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Readings | General Comments | | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Readings | LTC Totalizer Reading | 3585.60 | kw |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Readings | Totalizer Meter Reading | .7470 | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 200.00 | |
| 2/6/2023 12:06 | Distribution | Campbellsburg Quarterly Inspection | W0299 | WithLTC | 655-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | X0354 | RecloserHydraulic | 701-0720 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | X0354 | RecloserHydraulic | 701-0720 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | X0354 | RecloserHydraulic | 701-0720 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | X0354 | RecloserHydraulic | 701-0720 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | X0354 | RecloserHydraulic | 701-0720 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | X0354 | RecloserHydraulic | 701-0720 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | X0354 | RecloserHydraulic | 701-0720 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | X0354 | RecloserHydraulic | 701-0720 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 0 | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | X0354 | RecloserHydraulic | 701-0720 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | X0354 | RecloserHydraulic | 701-0720 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | X0354 | RecloserHydraulic | 701-0720 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | FE000871 | Fence | 462-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | FE000871 | Fence | 462-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | FE000871 | Fence | 462-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | FE000871 | Fence | 462-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | FE000871 | Fence | 462-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000435 | ControlHouse | 795-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000435 | ControlHouse | 795-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000435 | ControlHouse | 795-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000435 | ControlHouse | 795-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Readings | Operations Counter AF | 402 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Readings | Operations Counter AL | 404 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Readings | Operations This Read Vac | 2 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000435 | ControlHouse | 795-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000435 | ControlHouse | 795-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | CH000435 | ControlHouse | 795-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0051 | Regulator | 881-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0051 | Regulator | 881-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.7 | volts |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0051 | Regulator | 881-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 194139 | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0051 | Regulator | 881-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0051 | Regulator | 881-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0051 | Regulator | 881-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Readings | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Readings | LTC Totalizer Reading | 7309.44 | kw |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCC000869 | LTCControl | 462-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCC000869 | LTCControl | 462-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCC000869 | LTCControl | 462-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCC000869 | LTCControl | 462-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCC000869 | LTCControl | 462-1 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCC000869 | LTCControl | 462-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCC000869 | LTCControl | 462-1 | LTC Control Insp | General Comments | | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCC000869 | LTCControl | 462-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | LTCC000869 | LTCControl | 462-1 | LTC Control Insp | All Connections OK? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Readings | Oil Temp Max | 80 | °C |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Readings | Oil Temp Present | 43 | °C |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | ST000853 | Structure | 462-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | ST000853 | Structure | 462-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | ST000853 | Structure | 462-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | ST000853 | Structure | 462-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | ST000853 | Structure | 462-Structure | Structure Patrol Inspection | General Comments | | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | ST000853 | Structure | 462-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | ST000853 | Structure | 462-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | ST000853 | Structure | 462-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | ST000853 | Structure | 462-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | ST000853 | Structure | 462-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | ST000853 | Structure | 462-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | ST000853 | Structure | 462-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Readings | Switching Operations | 2 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | ST000853 | Structure | 462-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | ST000853 | Structure | 462-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | ST000853 | Structure | 462-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | ST000853 | Structure | 462-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000558 | BreakerVacuum | 694-302 | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Readings | General Comments | | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | TX000213 | NonLTC | 022-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | M0089 | WithLTC | 844-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0051 | Regulator | 881-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0051 | Regulator | 881-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0051 | Regulator | 881-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0051 | Regulator | 881-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0051 | Regulator | 881-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0051 | Regulator | 881-1 A | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0051 | Regulator | 881-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0051 | Regulator | 881-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0051 | Regulator | 881-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0051 | Regulator | 881-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0051 | Regulator | 881-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0051 | Regulator | 881-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0051 | Regulator | 881-1 A | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0051 | Regulator | 881-1 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0051 | Regulator | 881-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0051 | Regulator | 881-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0051 | Regulator | 881-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | FE000862 | Fence | 694-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | FE000862 | Fence | 694-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Readings | Switching Operations | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Readings | Operations This Read Vac | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Readings | Operations Counter AL | 731 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Readings | Operations Counter AF | 731 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Readings | Maintenance Operations | 0 | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | ST000229 | Structure | 447-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | ST000229 | Structure | 447-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | ST000229 | Structure | 447-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | ST000229 | Structure | 447-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | ST000229 | Structure | 447-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | ST000229 | Structure | 447-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | ST000229 | Structure | 447-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | ST000229 | Structure | 447-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | ST000229 | Structure | 447-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | ST000229 | Structure | 447-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | ST000229 | Structure | 447-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | ST000229 | Structure | 447-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | ST000229 | Structure | 447-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | ST000229 | Structure | 447-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | ST000229 | Structure | 447-Structure | Structure Patrol Inspection | General Comments | | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | ST000229 | Structure | 447-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | ST000229 | Structure | 447-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Readings | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | WX0241 | RecloserElectronic | 447-0832 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | WX0241 | RecloserElectronic | 447-0832 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | WX0241 | RecloserElectronic | 447-0832 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BAT001499 | Battery | 694-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BAT001499 | Battery | 694-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BAT001499 | Battery | 694-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BAT001499 | Battery | 694-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BAT001499 | Battery | 694-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BAT001499 | Battery | 694-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BAT001499 | Battery | 694-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BAT001499 | Battery | 694-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BAT001499 | Battery | 694-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BAT001499 | Battery | 694-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BAT001499 | Battery | 694-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .1098 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | LTCC000803 | LTCControl | 795-1 | LTC Control Insp | All Connections OK? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | LTCC000803 | LTCControl | 795-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | LTCC000803 | LTCControl | 795-1 | LTC Control Insp | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | LTCC000803 | LTCControl | 795-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | LTCC000803 | LTCControl | 795-1 | LTC Control Insp | LTC Output Voltage Level | 123.8 | VAC |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | LTCC000803 | LTCControl | 795-1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | LTCC000803 | LTCControl | 795-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | LTCC000803 | LTCControl | 795-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1005 | Regulator | 632-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 272822 | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1005 | Regulator | 632-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1005 | Regulator | 632-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | LTCC000803 | LTCControl | 795-1 | LTC Control Insp | VRR Time Delay | 45 | Seconds |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | FE000862 | Fence | 694-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | FE000862 | Fence | 694-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | FE000862 | Fence | 694-Fence | Fence Patrol Inspection | General Comments | | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | FE000862 | Fence | 694-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | FE000862 | Fence | 694-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | FE000862 | Fence | 694-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | FE000862 | Fence | 694-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | FE000862 | Fence | 694-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | FE000862 | Fence | 694-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | FE000862 | Fence | 694-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | FE000862 | Fence | 694-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | FE000862 | Fence | 694-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | FE000862 | Fence | 694-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | FE000862 | Fence | 694-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1101 | Regulator | 519-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1101 | Regulator | 519-1 A | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1101 | Regulator | 519-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1101 | Regulator | 519-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1101 | Regulator | 519-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1101 | Regulator | 519-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1101 | Regulator | 519-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1101 | Regulator | 519-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1101 | Regulator | 519-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1101 | Regulator | 519-1 A | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1101 | Regulator | 519-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1101 | Regulator | 519-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1101 | Regulator | 519-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1101 | Regulator | 519-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1101 | Regulator | 519-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 125.3 | volts |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | ST000404 | Structure | 694-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | ST000404 | Structure | 694-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | ST000404 | Structure | 694-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | ST000404 | Structure | 694-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | ST000404 | Structure | 694-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | ST000404 | Structure | 694-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1101 | Regulator | 519-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 113066 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | ST000404 | Structure | 694-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | ST000404 | Structure | 694-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | ST000404 | Structure | 694-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | ST000404 | Structure | 694-Structure | Structure Patrol Inspection | General Comments | | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | ST000404 | Structure | 694-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | ST000404 | Structure | 694-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | ST000404 | Structure | 694-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | ST000404 | Structure | 694-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | ST000404 | Structure | 694-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | ST000404 | Structure | 694-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | ST000404 | Structure | 694-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | ST000404 | Structure | 694-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | ST000404 | Structure | 694-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BAT001287 | Battery | 795-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BAT001287 | Battery | 795-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BAT001287 | Battery | 795-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BAT001287 | Battery | 795-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.0 | VDC |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BAT001287 | Battery | 795-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BAT001287 | Battery | 795-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BAT001287 | Battery | 795-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BAT001287 | Battery | 795-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BAT001287 | Battery | 795-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | WX0241 | RecloserElectronic | 447-0832 | Recloser Electronic Patrol Inspection | Operations Counter | 1044 | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | WX0241 | RecloserElectronic | 447-0832 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | WX0241 | RecloserElectronic | 447-0832 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | WX0241 | RecloserElectronic | 447-0832 | Recloser Electronic Patrol Inspection | General Comments | trip checks | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | WX0241 | RecloserElectronic | 447-0832 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | WX0241 | RecloserElectronic | 447-0832 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | WX0241 | RecloserElectronic | 447-0832 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | ST000229 | Structure | 447-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | WX0241 | RecloserElectronic | 447-0832 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | WX0241 | RecloserElectronic | 447-0832 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | WX0241 | RecloserElectronic | 447-0832 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | WX0241 | RecloserElectronic | 447-0832 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | WX0241 | RecloserElectronic | 447-0832 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | WX0241 | RecloserElectronic | 447-0832 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | WX0241 | RecloserElectronic | 447-0832 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | WX0241 | RecloserElectronic | 447-0832 | Recloser Electronic Patrol Inspection | Amps C Ø | 18.0 | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | WX0241 | RecloserElectronic | 447-0832 | Recloser Electronic Patrol Inspection | Amps B Ø | 19.0 | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | WX0241 | RecloserElectronic | 447-0832 | Recloser Electronic Patrol Inspection | Amps A Ø | 18.0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Readings | Amps C Ø | 140.0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Readings | Amps B Ø | 100.0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Readings | Amps A Ø | 140.0 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | ST000229 | Structure | 447-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | ST000229 | Structure | 447-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | ST000229 | Structure | 447-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | ST000229 | Structure | 447-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/6/2023 10:38 | Distribution | Corbin East Quarterly Inspection | MB0149 | BreakerVacuum | 844-0275 | VCB Readings | 9 Month Operations | 2 | |
| 2/6/2023 9:15 | Distribution | Onton Quarterly Inspection | ST000229 | Structure | 447-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | ST000404 | Structure | 694-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | ST000404 | Structure | 694-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | ST000404 | Structure | 694-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1101 | Regulator | 519-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1101 | Regulator | 519-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1101 | Regulator | 519-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1101 | Regulator | 519-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | DX0078 | RecloserHydraulic | 519-0305 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 212 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | DX0078 | RecloserHydraulic | 519-0305 | Recloser Hydraulic Patrol Inspection | Amps C Ø | .4 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | DX0078 | RecloserHydraulic | 519-0305 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 1.2 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | DX0078 | RecloserHydraulic | 519-0305 | Recloser Hydraulic Patrol Inspection | Amps A Ø | .3 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | DX0078 | RecloserHydraulic | 519-0305 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 333 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | SWG000219 | Switchgear | 462-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | SWG000219 | Switchgear | 462-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | SWG000219 | Switchgear | 462-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | SWG000219 | Switchgear | 462-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | SWG000219 | Switchgear | 462-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | SWG000219 | Switchgear | 462-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | SWG000219 | Switchgear | 462-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | SWG000219 | Switchgear | 462-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | SWG000219 | Switchgear | 462-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | SWG000219 | Switchgear | 462-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | SWG000219 | Switchgear | 462-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | SWG000219 | Switchgear | 462-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | SWG000219 | Switchgear | 462-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | SWG000219 | Switchgear | 462-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | YD000204 | Yard | 005-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | YD000204 | Yard | 005-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | YD000204 | Yard | 005-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | YD000204 | Yard | 005-Yard | Yard Patrol Inspection | General Comments | | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | YD000204 | Yard | 005-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | YD000204 | Yard | 005-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | YD000204 | Yard | 005-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | YD000204 | Yard | 005-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | YD000204 | Yard | 005-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | YD000204 | Yard | 005-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | YD000204 | Yard | 005-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | YD000204 | Yard | 005-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | YD000204 | Yard | 005-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/6/2023 14:17 | Distribution | Earlington Quarterly Inspection | YD000204 | Yard | 005-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | SWG000219 | Switchgear | 462-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | SWG000219 | Switchgear | 462-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | FE000324 | Fence | 699-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | FE000324 | Fence | 699-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | FE000324 | Fence | 699-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | CH000089 | ControlHouse | 022-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | CH000089 | ControlHouse | 022-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | CH000089 | ControlHouse | 022-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | CH000089 | ControlHouse | 022-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | CH000089 | ControlHouse | 022-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | CH000089 | ControlHouse | 022-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | CH000089 | ControlHouse | 022-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | CH000089 | ControlHouse | 022-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | CH000089 | ControlHouse | 022-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/6/2023 10:13 | Distribution | Frankfort Quarterly Inspection | CH000089 | ControlHouse | 022-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Readings | General Comments | | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | SWG000219 | Switchgear | 462-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/6/2023 12:27 | Distribution | White Sulphur Quarterly Inspection | SWG000219 | Switchgear | 462-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1005 | Regulator | 632-1 C | Regulator Patrol Inspection | Current Tap Position | 12L | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1005 | Regulator | 632-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1005 | Regulator | 632-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1005 | Regulator | 632-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1005 | Regulator | 632-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Readings | Maintenance Operations | 0 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Readings | Operations Counter AF | 183 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Readings | Operations Counter AL | 185 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Readings | Operations This Read Vac | 2 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Readings | Switching Operations | 2 | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BK000916 | BreakerVacuum | 694-0461 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | DX0078 | RecloserHydraulic | 519-0305 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | DX0078 | RecloserHydraulic | 519-0305 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | DX0078 | RecloserHydraulic | 519-0305 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | DX0078 | RecloserHydraulic | 519-0305 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | DX0078 | RecloserHydraulic | 519-0305 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | DX0078 | RecloserHydraulic | 519-0305 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | DX0078 | RecloserHydraulic | 519-0305 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1005 | Regulator | 632-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | DX0078 | RecloserHydraulic | 519-0305 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 299 | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | DX0078 | RecloserHydraulic | 519-0305 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | DX0078 | RecloserHydraulic | 519-0305 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | YD000327 | Yard | 699-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | YD000327 | Yard | 699-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | YD000327 | Yard | 699-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | YD000327 | Yard | 699-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | YD000327 | Yard | 699-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | YD000327 | Yard | 699-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | YD000327 | Yard | 699-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | YD000327 | Yard | 699-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | YD000327 | Yard | 699-Yard | Yard Patrol Inspection | General Comments | | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | YD000327 | Yard | 699-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | YD000327 | Yard | 699-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | YD000327 | Yard | 699-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | YD000327 | Yard | 699-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 131.76 | kw |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 96.00 | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Readings | Oil Temp Max | 44 | °C |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | ST000333 | Structure | 699-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | ST000333 | Structure | 699-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | ST000333 | Structure | 699-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | ST000333 | Structure | 699-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | ST000333 | Structure | 699-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | ST000333 | Structure | 699-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | ST000333 | Structure | 699-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | ST000333 | Structure | 699-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | ST000333 | Structure | 699-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | ST000333 | Structure | 699-Structure | Structure Patrol Inspection | General Comments | | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | ST000333 | Structure | 699-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | ST000333 | Structure | 699-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | ST000333 | Structure | 699-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | ST000333 | Structure | 699-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | ST000333 | Structure | 699-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | ST000333 | Structure | 699-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | ST000333 | Structure | 699-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | ST000333 | Structure | 699-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | ST000333 | Structure | 699-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | ST000333 | Structure | 699-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | ST000333 | Structure | 699-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | ST000333 | Structure | 699-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BAT001499 | Battery | 694-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/6/2023 14:17 | Distribution | Pepper Pike Quarterly Inspection | BAT001499 | Battery | 694-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | FE000324 | Fence | 699-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | FE000324 | Fence | 699-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | FE000324 | Fence | 699-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | YD000390 | Yard | 701-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | YD000390 | Yard | 701-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | YD000390 | Yard | 701-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | YD000390 | Yard | 701-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | YD000390 | Yard | 701-Yard | Yard Patrol Inspection | General Comments | | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | YD000390 | Yard | 701-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | YD000390 | Yard | 701-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | YD000390 | Yard | 701-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | YD000390 | Yard | 701-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | YD000390 | Yard | 701-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | YD000390 | Yard | 701-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | YD000390 | Yard | 701-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | YD000390 | Yard | 701-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1005 | Regulator | 632-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1005 | Regulator | 632-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1005 | Regulator | 632-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1005 | Regulator | 632-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1005 | Regulator | 632-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | FE000324 | Fence | 699-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | FE000324 | Fence | 699-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | FE000324 | Fence | 699-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | FE000324 | Fence | 699-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | FE000324 | Fence | 699-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | FE000324 | Fence | 699-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | FE000324 | Fence | 699-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | 0986 | NonLTC | 632-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | FE000324 | Fence | 699-Fence | Fence Patrol Inspection | General Comments | Old sub from factory has fence connected to ours and 2 sides of site fence. | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | FE000324 | Fence | 699-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | YD000390 | Yard | 701-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | YD000390 | Yard | 701-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1005 | Regulator | 632-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1005 | Regulator | 632-1 C | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1005 | Regulator | 632-1 C | Regulator Patrol Inspection | Min Tap Position | 15L | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1005 | Regulator | 632-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1005 | Regulator | 632-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1005 | Regulator | 632-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1005 | Regulator | 632-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1005 | Regulator | 632-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | FE000324 | Fence | 699-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/6/2023 10:17 | Distribution | Borg-Warner Quarterly Inspection | YD000327 | Yard | 699-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | FE000073 | Fence | 632-Fence | Fence Patrol Inspection | General Comments | | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | FE000073 | Fence | 632-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | FE000073 | Fence | 632-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0052 | Regulator | 881-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0052 | Regulator | 881-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0052 | Regulator | 881-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0052 | Regulator | 881-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0052 | Regulator | 881-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0052 | Regulator | 881-1 B | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0052 | Regulator | 881-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0052 | Regulator | 881-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | FE000073 | Fence | 632-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | FE000073 | Fence | 632-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | n | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | FE000073 | Fence | 632-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | FE000073 | Fence | 632-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | FE000073 | Fence | 632-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | FE000073 | Fence | 632-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | FE000073 | Fence | 632-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | FE000073 | Fence | 632-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | FE000073 | Fence | 632-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0052 | Regulator | 881-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0052 | Regulator | 881-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0052 | Regulator | 881-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0052 | Regulator | 881-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0052 | Regulator | 881-1 B | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0052 | Regulator | 881-1 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0052 | Regulator | 881-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0052 | Regulator | 881-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0052 | Regulator | 881-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | FE000073 | Fence | 632-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | n | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | FE000073 | Fence | 632-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1005 | Regulator | 632-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | R1005 | Regulator | 632-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1101 | Regulator | 519-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1101 | Regulator | 519-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1101 | Regulator | 519-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 14:30 | Distribution | Crockett Quarterly Inspection | R1101 | Regulator | 519-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0052 | Regulator | 881-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0052 | Regulator | 881-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.0 | volts |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BCH001230 | Charger | 795-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BCH001230 | Charger | 795-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BCH001230 | Charger | 795-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BCH001230 | Charger | 795-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BCH001230 | Charger | 795-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.7 | amps |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BCH001230 | Charger | 795-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BCH001230 | Charger | 795-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BCH001230 | Charger | 795-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 2.200 | millivolts |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 600 | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .8700 | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0052 | Regulator | 881-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0052 | Regulator | 881-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 98023 | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0052 | Regulator | 881-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/6/2023 11:54 | Distribution | Mill Creek KU Quarterly Inspection | OR0052 | Regulator | 881-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 522.00 | kw |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Readings | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Readings | Fault Operations Ground | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Readings | Follow-up Action Required? | n | |
| 2/6/2023 12:14 | Distribution | Lawrence Quarterly Inspection | C0315 | NonLTC | 701-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | YD000074 | Yard | 632-Yard | Yard Patrol Inspection | Ambient Temp | 54 | °F |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | YD000074 | Yard | 632-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | YD000074 | Yard | 632-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | YD000074 | Yard | 632-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | YD000074 | Yard | 632-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | YD000074 | Yard | 632-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Patrol Inspection | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Readings | General Comments | | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Readings | Maintenance Operations | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BAT001287 | Battery | 795-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Readings | Operations Counter AF | 197 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BAT001287 | Battery | 795-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BAT001287 | Battery | 795-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BAT001287 | Battery | 795-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BAT001287 | Battery | 795-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Readings | Operations Counter AL | 197 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Readings | Operations This Read Vac | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Readings | Switching Operations | 0 | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/6/2023 12:42 | Distribution | Corbin US Steel Quarterly Inspection | BK000926 | BreakerVacuum | 795-0289 | VCB Readings | Unknown Operations | 0 | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | FE000073 | Fence | 632-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/6/2023 13:39 | Distribution | Apollo Quarterly Inspection | FE000073 | Fence | 632-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | LTCC000773 | LTCControl | 696-1 | LTC Control Insp | All Connections OK? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | LTCC000773 | LTCControl | 696-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | LTCC000773 | LTCControl | 696-1 | LTC Control Insp | General Comments | | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | LTCC000773 | LTCControl | 696-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | LTCC000773 | LTCControl | 696-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | LTCC000773 | LTCControl | 696-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | LTCC000773 | LTCControl | 696-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | LTCC000773 | LTCControl | 696-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Readings | 9 Month Operations | 0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Readings | Operations Counter AL | 579 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Readings | Amps A Ø | 130.0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | MX0328 | RecloserElectronic | 534-0250 | Recloser Electronic Patrol Inspection | Amps A Ø | 130.0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LT0079 | LTCMechanism | FD-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | ok | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LT0079 | LTCMechanism | FD-Offline Distribution | LTC Counter Readings | General Comments | ok | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Readings | Operations Counter AF | 579 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Readings | General Comments | | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | BAT001549 | Battery | 704-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.0 | VDC |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | BAT001549 | Battery | 704-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Readings | General Comments | | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | BCH001480 | Charger | 704-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | BAT001549 | Battery | 704-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | BAT001549 | Battery | 704-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | BAT001549 | Battery | 704-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | BAT001549 | Battery | 704-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | BAT001549 | Battery | 704-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | BAT001549 | Battery | 704-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Readings | Amps C Ø | 310.0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Readings | Amps B Ø | 400.0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Readings | Amps A Ø | 325.0 | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LT0079 | LTCMechanism | FD-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LT0079 | LTCMechanism | FD-Offline Distribution | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Readings | Operations Counter AL | 200 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Readings | Operations Counter AF | 200 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | BAT001549 | Battery | 704-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | BAT001549 | Battery | 704-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | C0306 | NonLTC | 434-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | C0306 | NonLTC | 434-1 | NonLTC Transformer Readings | Oil Temp Present | 15 | °C |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | CH000363 | ControlHouse | 747-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | CH000363 | ControlHouse | 747-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | CH000363 | ControlHouse | 747-Control House | Control House Patrol Inspection | General Comments | | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | CH000363 | ControlHouse | 747-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | CH000363 | ControlHouse | 747-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | CH000363 | ControlHouse | 747-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | CH000363 | ControlHouse | 747-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | CH000363 | ControlHouse | 747-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | ST000007 | Structure | 704-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | ST000007 | Structure | 704-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | CH000363 | ControlHouse | 747-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | CH000363 | ControlHouse | 747-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | CH000363 | ControlHouse | 747-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | CH000363 | ControlHouse | 747-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | CH000363 | ControlHouse | 747-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | MX0328 | RecloserElectronic | 534-0250 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | ST000007 | Structure | 704-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | ST000007 | Structure | 704-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | ST000007 | Structure | 704-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | ST000007 | Structure | 704-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | ST000007 | Structure | 704-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | ST000007 | Structure | 704-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | MX0328 | RecloserElectronic | 534-0250 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | MX0328 | RecloserElectronic | 534-0250 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | MX0328 | RecloserElectronic | 534-0250 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | MX0328 | RecloserElectronic | 534-0250 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | MX0328 | RecloserElectronic | 534-0250 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | ST000007 | Structure | 704-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | ST000007 | Structure | 704-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | ST000007 | Structure | 704-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | C0306 | NonLTC | 434-1 | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | C0306 | NonLTC | 434-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | C0306 | NonLTC | 434-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 55.00 | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | C0306 | NonLTC | 434-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | C0306 | NonLTC | 434-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | MX0328 | RecloserElectronic | 534-0250 | Recloser Electronic Patrol Inspection | Amps B Ø | 120.0 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | MX0328 | RecloserElectronic | 534-0250 | Recloser Electronic Patrol Inspection | Amps C Ø | 95.0 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | MX0328 | RecloserElectronic | 534-0250 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | BAT001549 | Battery | 704-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | MX0328 | RecloserElectronic | 534-0250 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | CH000363 | ControlHouse | 747-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | CH000363 | ControlHouse | 747-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | BAT001549 | Battery | 704-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | BAT001549 | Battery | 704-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BCH001349 | Charger | 338-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BCH001349 | Charger | 338-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BCH001349 | Charger | 338-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BCH001349 | Charger | 338-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BCH001349 | Charger | 338-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.5 | amps |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BCH001349 | Charger | 338-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BCH001349 | Charger | 338-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BCH001349 | Charger | 338-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.100 | millivolts |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | CH000363 | ControlHouse | 747-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | CH000363 | ControlHouse | 747-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Readings | General Comments | | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Readings | Operations Counter AF | 191 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Readings | Operations Counter AL | 191 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Readings | Amps B Ø | 80.0 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Readings | Amps C Ø | 80.0 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | C0306 | NonLTC | 434-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | C0306 | NonLTC | 434-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | C0306 | NonLTC | 434-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | C0306 | NonLTC | 434-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | C0306 | NonLTC | 434-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | C0306 | NonLTC | 434-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0232 | BreakerVacuum | CW-1223 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0232 | BreakerVacuum | CW-1223 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0232 | BreakerVacuum | CW-1223 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0232 | BreakerVacuum | CW-1223 | VCB Readings | Amps A Ø | 0.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0232 | BreakerVacuum | CW-1223 | VCB Readings | Amps B Ø | 0.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | CH000141 | ControlHouse | CW-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | CH000141 | ControlHouse | CW-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | CH000141 | ControlHouse | CW-Control House | Control House Patrol Inspection | General Comments | 2 four foot bulbs out on same light fixture.. Need to replace with LED. | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0232 | BreakerVacuum | CW-1223 | VCB Readings | Amps C Ø | 0.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0376 | BreakerVacuum | FH-1215 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0376 | BreakerVacuum | FH-1215 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0376 | BreakerVacuum | FH-1215 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0232 | BreakerVacuum | CW-1223 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0232 | BreakerVacuum | CW-1223 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0232 | BreakerVacuum | CW-1223 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0232 | BreakerVacuum | CW-1223 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | CH000141 | ControlHouse | CW-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | CH000141 | ControlHouse | CW-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0232 | BreakerVacuum | CW-1223 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0232 | BreakerVacuum | CW-1223 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0232 | BreakerVacuum | CW-1223 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0232 | BreakerVacuum | CW-1223 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0232 | BreakerVacuum | CW-1223 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | C0173 | NonLTC | 880-1 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | C0173 | NonLTC | 880-1 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | C0173 | NonLTC | 880-1 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | C0173 | NonLTC | 880-1 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0232 | BreakerVacuum | CW-1223 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0232 | BreakerVacuum | CW-1223 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0232 | BreakerVacuum | CW-1223 | VCB Readings | General Comments | | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | C0173 | NonLTC | 880-1 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | C0173 | NonLTC | 880-1 C | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Readings | 9 Month Operations | 10 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0232 | BreakerVacuum | CW-1223 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0232 | BreakerVacuum | CW-1223 | VCB Readings | Operations Counter AF | 254 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0232 | BreakerVacuum | CW-1223 | VCB Readings | Operations Counter AL | 254 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0232 | BreakerVacuum | CW-1223 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0232 | BreakerVacuum | CW-1223 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0232 | BreakerVacuum | CW-1223 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BCH001477 | Charger | 534-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.700 | millivolts |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BCH001477 | Charger | 534-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.3 | VDC |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | LTCMechanism | 376-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | LTCMechanism | 376-1 | LTC Counter Readings | LTC Operations Since Last Insp | 0 | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | LTCMechanism | 376-1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | LTCMechanism | 376-1 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | LTCMechanism | 376-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | LTCMechanism | 376-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | LTCMechanism | 376-1 | LTC Counter Readings | LTC As Left Counter | 85419 | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | LTCMechanism | 376-1 | LTC Counter Readings | LTC As Found Counter | 85419 | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | LTCMechanism | 376-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | LTCMechanism | 376-1 | LTC Counter Readings | General Comments | | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | LTCMechanism | 376-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | LTCMechanism | 376-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | LTCMechanism | 376-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BAT001548 | Battery | 534-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | LTCMechanism | 854-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | LTCMechanism | 854-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | LTCMechanism | 376-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | CH000141 | ControlHouse | CW-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | CH000141 | ControlHouse | CW-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | C0173 | NonLTC | 880-1 C | NonLTC Transformer Readings | Totalizer Meter Reading | .6564 | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | C0173 | NonLTC | 880-1 C | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | C0173 | NonLTC | 880-1 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | CH000141 | ControlHouse | CW-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | CH000141 | ControlHouse | CW-Control House | Control House Patrol Inspection | Control House Lighting OK? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | CH000141 | ControlHouse | CW-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | CH000141 | ControlHouse | CW-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | CH000141 | ControlHouse | CW-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | CH000141 | ControlHouse | CW-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | CH000141 | ControlHouse | CW-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | CH000141 | ControlHouse | CW-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | CH000141 | ControlHouse | CW-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | LTCMechanism | 854-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0232 | BreakerVacuum | CW-1223 | VCB Readings | 9 Month Operations | 7 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0232 | BreakerVacuum | CW-1223 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | KX0236 | RecloserElectronic | 575-0319 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | KX0236 | RecloserElectronic | 575-0319 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | KX0236 | RecloserElectronic | 575-0319 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | KX0236 | RecloserElectronic | 575-0319 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | KX0236 | RecloserElectronic | 575-0319 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | KX0236 | RecloserElectronic | 575-0319 | Recloser Electronic Patrol Inspection | General Comments | | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | KX0236 | RecloserElectronic | 575-0319 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | KX0236 | RecloserElectronic | 575-0319 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | KX0236 | RecloserElectronic | 575-0319 | Recloser Electronic Patrol Inspection | Operations Counter | 18 | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | KX0236 | RecloserElectronic | 575-0319 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | KX0236 | RecloserElectronic | 575-0319 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | KX0236 | RecloserElectronic | 575-0319 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | FE000822 | Fence | 534-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | FE000822 | Fence | 534-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | FE000822 | Fence | 534-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | FE000822 | Fence | 534-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | FE000822 | Fence | 534-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | FE000822 | Fence | 534-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | FE000822 | Fence | 534-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | FE000822 | Fence | 534-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | FE000822 | Fence | 534-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | BCH001480 | Charger | 704-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.000 | millivolts |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | BCH001480 | Charger | 704-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | BCH001480 | Charger | 704-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | BCH001480 | Charger | 704-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .2 | amps |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | BCH001480 | Charger | 704-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | BCH001480 | Charger | 704-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | BCH001480 | Charger | 704-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Readings | 9 Month Operations | 4 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Readings | Amps A Ø | 142.0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Readings | Amps B Ø | 180.0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Readings | Amps C Ø | 148.0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001435 | BreakerVacuum | 338-4607 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BCH001477 | Charger | 534-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.3 | VDC |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BCH001477 | Charger | 534-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .4 | amps |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BCH001477 | Charger | 534-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | CH000141 | ControlHouse | CW-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | CH000141 | ControlHouse | CW-Control House | Control House Patrol Inspection | Restroom Clean & OK? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | CH000141 | ControlHouse | CW-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | KX0236 | RecloserElectronic | 575-0319 | Recloser Electronic Patrol Inspection | Amps A Ø | 33.0 | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | KX0236 | RecloserElectronic | 575-0319 | Recloser Electronic Patrol Inspection | Amps B Ø | 7.0 | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | KX0236 | RecloserElectronic | 575-0319 | Recloser Electronic Patrol Inspection | Amps C Ø | 22.0 | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | KX0236 | RecloserElectronic | 575-0319 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | KX0236 | RecloserElectronic | 575-0319 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | KX0236 | RecloserElectronic | 575-0319 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | KX0236 | RecloserElectronic | 575-0319 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BCH001477 | Charger | 534-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BCH001477 | Charger | 534-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BCH001477 | Charger | 534-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | C0173 | NonLTC | 880-1 C | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | C0173 | NonLTC | 880-1 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | C0173 | NonLTC | 880-1 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 95.00 | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | C0173 | NonLTC | 880-1 C | NonLTC Transformer Readings | Non LTC Totalizer Reading | 787.68 | kw |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | C0173 | NonLTC | 880-1 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | C0173 | NonLTC | 880-1 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | C0173 | NonLTC | 880-1 C | NonLTC Transformer Readings | General Comments | | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | C0173 | NonLTC | 880-1 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | C0173 | NonLTC | 880-1 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | C0173 | NonLTC | 880-1 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | C0173 | NonLTC | 880-1 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | C0173 | NonLTC | 880-1 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | C0173 | NonLTC | 880-1 C | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | C0173 | NonLTC | 880-1 C | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | KX0236 | RecloserElectronic | 575-0319 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | CH000141 | ControlHouse | CW-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | C0173 | NonLTC | 880-1 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | C0173 | NonLTC | 880-1 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | C0173 | NonLTC | 880-1 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | C0173 | NonLTC | 880-1 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | CH000141 | ControlHouse | CW-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | CH000141 | ControlHouse | CW-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | FE000822 | Fence | 534-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | FE000822 | Fence | 534-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | FE000822 | Fence | 534-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | CH000141 | ControlHouse | CW-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Readings | Oil Temp Max | 70 | °C |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | LTCMechanism | 534-1 | LTC Counter Readings | LTC Max Tap Position | 15R | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 46 | °C |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 40 | °C |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 40 | °C |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 135.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Readings | General Comments | X1 Gauge is not wired up. It has the cord hanging, but is not wired up. The gauge was replaced, but alarms/fans wiring has not been t | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0374 | BreakerVacuum | FH-1213 | VCB Readings | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0374 | BreakerVacuum | FH-1213 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0374 | BreakerVacuum | FH-1213 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0374 | BreakerVacuum | FH-1213 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0374 | BreakerVacuum | FH-1213 | VCB Readings | Fault Operations Ground | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0374 | BreakerVacuum | FH-1213 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0374 | BreakerVacuum | FH-1213 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0374 | BreakerVacuum | FH-1213 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0374 | BreakerVacuum | FH-1213 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0374 | BreakerVacuum | FH-1213 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0374 | BreakerVacuum | FH-1213 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0374 | BreakerVacuum | FH-1213 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | LTCMechanism | 534-1 | LTC Counter Readings | LTC Current Tap Position | 6R | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | LTCMechanism | 534-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | LTCMechanism | 534-1 | LTC Counter Readings | LTC As Left Counter | 52157 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0374 | BreakerVacuum | FH-1213 | VCB Readings | Amps C Ø | 252.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0374 | BreakerVacuum | FH-1213 | VCB Readings | Amps B Ø | 242.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0374 | BreakerVacuum | FH-1213 | VCB Readings | Amps A Ø | 190.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0374 | BreakerVacuum | FH-1213 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0374 | BreakerVacuum | FH-1213 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | LTCMechanism | 534-1 | LTC Counter Readings | LTC As Found Counter | 52145 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | LTCMechanism | 534-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0010 | NonLTC | 880-1 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0010 | NonLTC | 880-1 B | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0010 | NonLTC | 880-1 B | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0010 | NonLTC | 880-1 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0010 | NonLTC | 880-1 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0010 | NonLTC | 880-1 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0010 | NonLTC | 880-1 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0010 | NonLTC | 880-1 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | FE000120 | Fence | 575-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | FE000120 | Fence | 575-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | FE000120 | Fence | 575-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | FE000120 | Fence | 575-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | n | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | FE000120 | Fence | 575-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | FE000120 | Fence | 575-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | LTCMechanism | 534-1 | LTC Counter Readings | LTC Operations Since Last Insp | 278 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | LTCMechanism | 534-1 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LTCC000285 | LTCControl | FH-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LTCC000285 | LTCControl | FH-TRANS 1 | LTC Control Insp | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LTCC000285 | LTCControl | FH-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Readings | Operations Counter AL | 292 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Readings | General Comments | | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Readings | LTC Totalizer Reading | 5731.20 | kw |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0374 | BreakerVacuum | FH-1213 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0374 | BreakerVacuum | FH-1213 | VCB Readings | Operations Counter AL | 99799 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0374 | BreakerVacuum | FH-1213 | VCB Readings | Operations Counter AF | 99799 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0374 | BreakerVacuum | FH-1213 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | ST000510 | Structure | 652-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | ST000510 | Structure | 652-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0374 | BreakerVacuum | FH-1213 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0374 | BreakerVacuum | FH-1213 | VCB Readings | 9 Month Operations | 1 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | ST000510 | Structure | 652-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | ST000510 | Structure | 652-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0382 | BreakerVacuum | FH-12KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0382 | BreakerVacuum | FH-12KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0382 | BreakerVacuum | FH-12KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0382 | BreakerVacuum | FH-12KV TR 2 | VCB Readings | Operations Counter AL | 200 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0382 | BreakerVacuum | FH-12KV TR 2 | VCB Readings | Operations Counter AF | 200 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0382 | BreakerVacuum | FH-12KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0382 | BreakerVacuum | FH-12KV TR 2 | VCB Readings | General Comments | vc is hard to read last numbers | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0382 | BreakerVacuum | FH-12KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | ST000510 | Structure | 652-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0382 | BreakerVacuum | FH-12KV TR 2 | VCB Readings | Follow-up Action Required? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0382 | BreakerVacuum | FH-12KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0382 | BreakerVacuum | FH-12KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0382 | BreakerVacuum | FH-12KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0382 | BreakerVacuum | FH-12KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0382 | BreakerVacuum | FH-12KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0382 | BreakerVacuum | FH-12KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0382 | BreakerVacuum | FH-12KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0382 | BreakerVacuum | FH-12KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0382 | BreakerVacuum | FH-12KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0382 | BreakerVacuum | FH-12KV TR 2 | VCB Readings | Amps C Ø | 657.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0382 | BreakerVacuum | FH-12KV TR 2 | VCB Readings | Amps B Ø | 641.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0382 | BreakerVacuum | FH-12KV TR 2 | VCB Readings | Amps A Ø | 580.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0382 | BreakerVacuum | FH-12KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0382 | BreakerVacuum | FH-12KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0382 | BreakerVacuum | FH-12KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0382 | BreakerVacuum | FH-12KV TR 2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0382 | BreakerVacuum | FH-12KV TR 2 | VCB Readings | 9 Month Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | ST000510 | Structure | 652-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Readings | Totalizer Meter Reading | .5970 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | WithLTC | 652-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | LTCMechanism | 534-1 | LTC Counter Readings | General Comments | | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | LTCMechanism | 534-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | LTCMechanism | 534-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | CH000363 | ControlHouse | 747-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | CH000363 | ControlHouse | 747-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | There is a fan that will operate when you help it start spinning. It appears the start up capacitor is bad and needs to be replaced. | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Readings | 9 Month Operations VCB New | 16 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Readings | Amps A Ø | 0.0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Readings | Amps B Ø | 0.0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Readings | Amps C Ø | 0.0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | BK000557 | BreakerVacuum | 108-3401 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | ST000510 | Structure | 652-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | ST000510 | Structure | 652-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | ST000510 | Structure | 652-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | ST000510 | Structure | 652-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | ST000510 | Structure | 652-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | ST000510 | Structure | 652-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | ST000510 | Structure | 652-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | ST000510 | Structure | 652-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | ST000510 | Structure | 652-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | ST000510 | Structure | 652-Structure | Structure Patrol Inspection | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0374 | BreakerVacuum | FH-1213 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | ST000510 | Structure | 652-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | ST000510 | Structure | 652-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | ST000510 | Structure | 652-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | ST000510 | Structure | 652-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | ST000510 | Structure | 652-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | ST000510 | Structure | 652-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Readings | General Comments | | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | MX0328 | RecloserElectronic | 534-0250 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | MX0328 | RecloserElectronic | 534-0250 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0241 | BreakerVacuum | CW-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0241 | BreakerVacuum | CW-12KV TR 1 | VCB Readings | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0241 | BreakerVacuum | CW-12KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0241 | BreakerVacuum | CW-12KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0241 | BreakerVacuum | CW-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0241 | BreakerVacuum | CW-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0241 | BreakerVacuum | CW-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0241 | BreakerVacuum | CW-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0241 | BreakerVacuum | CW-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0241 | BreakerVacuum | CW-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | MX0328 | RecloserElectronic | 534-0250 | Recloser Electronic Patrol Inspection | General Comments | | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | MX0328 | RecloserElectronic | 534-0250 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | MX0328 | RecloserElectronic | 534-0250 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | MX0328 | RecloserElectronic | 534-0250 | Recloser Electronic Patrol Inspection | Operations Counter | 13 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | MX0328 | RecloserElectronic | 534-0250 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | MX0328 | RecloserElectronic | 534-0250 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | MX0328 | RecloserElectronic | 534-0250 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Readings | Operations Counter AF | 292 | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0010 | NonLTC | 880-1 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0010 | NonLTC | 880-1 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0374 | BreakerVacuum | FH-1213 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0374 | BreakerVacuum | FH-1213 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | FE000498 | Fence | 434-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | FE000498 | Fence | 434-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | FE000498 | Fence | 434-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | FE000498 | Fence | 434-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | FE000498 | Fence | 434-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0010 | NonLTC | 880-1 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0010 | NonLTC | 880-1 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0010 | NonLTC | 880-1 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0010 | NonLTC | 880-1 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0010 | NonLTC | 880-1 B | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0010 | NonLTC | 880-1 B | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0010 | NonLTC | 880-1 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0010 | NonLTC | 880-1 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 96.00 | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0010 | NonLTC | 880-1 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0010 | NonLTC | 880-1 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0010 | NonLTC | 880-1 B | NonLTC Transformer Readings | General Comments | | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | FE000498 | Fence | 434-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | FE000498 | Fence | 434-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | C0306 | NonLTC | 434-1 | NonLTC Transformer Readings | General Comments | | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | C0306 | NonLTC | 434-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | C0306 | NonLTC | 434-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | C0306 | NonLTC | 434-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | C0306 | NonLTC | 434-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | C0306 | NonLTC | 434-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | C0306 | NonLTC | 434-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | C0306 | NonLTC | 434-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | LTCMechanism | 534-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | ST000007 | Structure | 704-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | ST000007 | Structure | 704-Structure | Structure Patrol Inspection | General Comments | | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | ST000007 | Structure | 704-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | ST000007 | Structure | 704-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | ST000007 | Structure | 704-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | ST000007 | Structure | 704-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | ST000007 | Structure | 704-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | ST000007 | Structure | 704-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | ST000007 | Structure | 704-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | ST000007 | Structure | 704-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | ST000007 | Structure | 704-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0241 | BreakerVacuum | CW-12KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0241 | BreakerVacuum | CW-12KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0241 | BreakerVacuum | CW-12KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0241 | BreakerVacuum | CW-12KV TR 1 | VCB Readings | Operations Counter AL | 218 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0241 | BreakerVacuum | CW-12KV TR 1 | VCB Readings | Operations Counter AF | 218 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | LTCMechanism | 534-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | LTCMechanism | 534-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Readings | General Comments | | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0180 | BreakerVacuum | 108-0453 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | ST000126 | Structure | 575-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | ST000126 | Structure | 575-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | ST000126 | Structure | 575-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | ST000126 | Structure | 575-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | ST000126 | Structure | 575-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | ST000126 | Structure | 575-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | ST000126 | Structure | 575-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | ST000126 | Structure | 575-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | ST000126 | Structure | 575-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | ST000126 | Structure | 575-Structure | Structure Patrol Inspection | General Comments | | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | ST000126 | Structure | 575-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0241 | BreakerVacuum | CW-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0241 | BreakerVacuum | CW-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0241 | BreakerVacuum | CW-12KV TR 1 | VCB Readings | 9 Month Operations | 10 | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | ST000126 | Structure | 575-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | ST000126 | Structure | 575-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | ST000126 | Structure | 575-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | ST000126 | Structure | 575-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | ST000126 | Structure | 575-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | ST000126 | Structure | 575-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | ST000126 | Structure | 575-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | YD000122 | Yard | 575-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | YD000122 | Yard | 575-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | YD000122 | Yard | 575-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Exp Boom Needs Corr | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | YD000122 | Yard | 575-Yard | Yard Patrol Inspection | General Comments | Boom needs gravel on high side | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | YD000122 | Yard | 575-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | YD000122 | Yard | 575-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | YD000122 | Yard | 575-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | YD000122 | Yard | 575-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | YD000122 | Yard | 575-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | YD000122 | Yard | 575-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | YD000122 | Yard | 575-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | YD000122 | Yard | 575-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | YD000122 | Yard | 575-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | YD000122 | Yard | 575-Yard | Yard Patrol Inspection | Ambient Temp | 29 | °F |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | FE000120 | Fence | 575-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | FE000120 | Fence | 575-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | FE000120 | Fence | 575-Fence | Fence Patrol Inspection | General Comments | the back right corner of fence is a foot off ground....left corner post of station is washing out. Fence has places that has been pieced to | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 40 | °C |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 46 | °C |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | WithLTC | CW-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 40 | °C |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | FE000120 | Fence | 575-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | FE000120 | Fence | 575-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | FE000120 | Fence | 575-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | FE000120 | Fence | 575-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | FE000120 | Fence | 575-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | FE000120 | Fence | 575-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | FE000120 | Fence | 575-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | FE000498 | Fence | 434-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | FE000498 | Fence | 434-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | FE000498 | Fence | 434-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | FE000498 | Fence | 434-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0010 | NonLTC | 880-1 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Readings | Operations Counter AF | 56 | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | FE000498 | Fence | 434-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | FE000498 | Fence | 434-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | FE000498 | Fence | 434-Fence | Fence Patrol Inspection | General Comments | | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | FE000498 | Fence | 434-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | FE000498 | Fence | 434-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0241 | BreakerVacuum | CW-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0241 | BreakerVacuum | CW-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0241 | BreakerVacuum | CW-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0241 | BreakerVacuum | CW-12KV TR 1 | VCB Readings | Amps C Ø | 443.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0241 | BreakerVacuum | CW-12KV TR 1 | VCB Readings | Amps B Ø | 485.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0241 | BreakerVacuum | CW-12KV TR 1 | VCB Readings | Amps A Ø | 420.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0241 | BreakerVacuum | CW-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | ST000507 | Structure | 434-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | ST000507 | Structure | 434-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | ST000507 | Structure | 434-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | ST000507 | Structure | 434-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | ST000507 | Structure | 434-Structure | Structure Patrol Inspection | General Comments | | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | ST000507 | Structure | 434-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | ST000507 | Structure | 434-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | ST000507 | Structure | 434-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | ST000507 | Structure | 434-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | ST000507 | Structure | 434-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | ST000507 | Structure | 434-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0241 | BreakerVacuum | CW-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Readings | Operations Counter AL | 56 | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0010 | NonLTC | 880-1 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0010 | NonLTC | 880-1 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0010 | NonLTC | 880-1 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | C0306 | NonLTC | 434-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | C0306 | NonLTC | 434-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | C0306 | NonLTC | 434-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0131 | BreakerVacuum | 704-0253 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | ST000126 | Structure | 575-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | ST000126 | Structure | 575-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | ST000126 | Structure | 575-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | CH000187 | ControlHouse | FH-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | CH000187 | ControlHouse | FH-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | CH000187 | ControlHouse | FH-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | CH000187 | ControlHouse | FH-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | CH000187 | ControlHouse | FH-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | CH000187 | ControlHouse | FH-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | CH000187 | ControlHouse | FH-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0380 | BreakerVacuum | FH-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations | 6 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0380 | BreakerVacuum | FH-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0380 | BreakerVacuum | FH-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | LTCM000046 | LTCMechanism | 704-1 | LTC Counter Readings | LTC Operations Since Last Insp | 1039 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | LTCM000046 | LTCMechanism | 704-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | LTCM000046 | LTCMechanism | 704-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | LTCM000046 | LTCMechanism | 704-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | LTCM000046 | LTCMechanism | 704-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0380 | BreakerVacuum | FH-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0380 | BreakerVacuum | FH-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0380 | BreakerVacuum | FH-12KV BUS TIE SEC 2 | VCB Readings | Amps A Ø | 0.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0380 | BreakerVacuum | FH-12KV BUS TIE SEC 2 | VCB Readings | Amps B Ø | 0.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0380 | BreakerVacuum | FH-12KV BUS TIE SEC 2 | VCB Readings | Amps C Ø | 0.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0380 | BreakerVacuum | FH-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0380 | BreakerVacuum | FH-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0380 | BreakerVacuum | FH-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0380 | BreakerVacuum | FH-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0380 | BreakerVacuum | FH-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0380 | BreakerVacuum | FH-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0380 | BreakerVacuum | FH-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0380 | BreakerVacuum | FH-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0380 | BreakerVacuum | FH-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0380 | BreakerVacuum | FH-12KV BUS TIE SEC 2 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0380 | BreakerVacuum | FH-12KV BUS TIE SEC 2 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0380 | BreakerVacuum | FH-12KV BUS TIE SEC 2 | VCB Readings | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0380 | BreakerVacuum | FH-12KV BUS TIE SEC 2 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0380 | BreakerVacuum | FH-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AF | 409 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0380 | BreakerVacuum | FH-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AL | 409 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0380 | BreakerVacuum | FH-12KV BUS TIE SEC 2 | VCB Readings | Operations This Read Vac | 4 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0380 | BreakerVacuum | FH-12KV BUS TIE SEC 2 | VCB Readings | Switching Operations | 4 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0380 | BreakerVacuum | FH-12KV BUS TIE SEC 2 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Readings | Totalizer Meter Reading | .3070 | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Readings | General Comments | | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Readings | LTC Totalizer Reading | 7378.56 | kw |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Readings | Oil Temp Max | 58 | °C |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Readings | Oil Temp Present | 10 | °C |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | YD000364 | Yard | 747-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | YD000364 | Yard | 747-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | YD000364 | Yard | 747-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | YD000364 | Yard | 747-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | YD000364 | Yard | 747-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | YD000364 | Yard | 747-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | YD000364 | Yard | 747-Yard | Yard Patrol Inspection | Ambient Temp | 24 | °F |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | FE000358 | Fence | 747-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | FE000358 | Fence | 747-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | FE000358 | Fence | 747-Fence | Fence Patrol Inspection | General Comments | | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | FE000358 | Fence | 747-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | FE000358 | Fence | 747-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | FE000358 | Fence | 747-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0242 | BreakerAirMagnetic | CW-12KV TR 2 | AMCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0242 | BreakerAirMagnetic | CW-12KV TR 2 | AMCB Readings | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0242 | BreakerAirMagnetic | CW-12KV TR 2 | AMCB Patrol Inspection | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0242 | BreakerAirMagnetic | CW-12KV TR 2 | AMCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | FE000358 | Fence | 747-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | CH000187 | ControlHouse | FH-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | CH000187 | ControlHouse | FH-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0242 | BreakerAirMagnetic | CW-12KV TR 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0242 | BreakerAirMagnetic | CW-12KV TR 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0242 | BreakerAirMagnetic | CW-12KV TR 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0242 | BreakerAirMagnetic | CW-12KV TR 2 | AMCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0242 | BreakerAirMagnetic | CW-12KV TR 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0242 | BreakerAirMagnetic | CW-12KV TR 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0242 | BreakerAirMagnetic | CW-12KV TR 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | CH000408 | ControlHouse | 704-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | CH000408 | ControlHouse | 704-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | CH000408 | ControlHouse | 704-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | CH000408 | ControlHouse | 704-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | CH000408 | ControlHouse | 704-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | CH000408 | ControlHouse | 704-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | CH000408 | ControlHouse | 704-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | CH000408 | ControlHouse | 704-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | CH000408 | ControlHouse | 704-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | CH000408 | ControlHouse | 704-Control House | Control House Patrol Inspection | General Comments | | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | CH000408 | ControlHouse | 704-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | CH000408 | ControlHouse | 704-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | CH000408 | ControlHouse | 704-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | CH000408 | ControlHouse | 704-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | LTCM000046 | LTCMechanism | 704-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | LTCM000046 | LTCMechanism | 704-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | LTCM000046 | LTCMechanism | 704-1 | LTC Counter Readings | General Comments | | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | LTCM000046 | LTCMechanism | 704-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | LTCM000046 | LTCMechanism | 704-1 | LTC Counter Readings | LTC As Found Counter | 67880 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | CH000187 | ControlHouse | FH-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | FE000358 | Fence | 747-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | FE000358 | Fence | 747-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | FE000358 | Fence | 747-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | FE000358 | Fence | 747-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | FE000358 | Fence | 747-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | FE000358 | Fence | 747-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | FE000358 | Fence | 747-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | FE000358 | Fence | 747-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | FE000358 | Fence | 747-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | CH000187 | ControlHouse | FH-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | CH000187 | ControlHouse | FH-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | CH000187 | ControlHouse | FH-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | CH000187 | ControlHouse | FH-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | LTCM000046 | LTCMechanism | 704-1 | LTC Counter Readings | LTC As Left Counter | 67891 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | LTCM000046 | LTCMechanism | 704-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | LTCM000046 | LTCMechanism | 704-1 | LTC Counter Readings | LTC Current Tap Position | 1R | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | LTCM000046 | LTCMechanism | 704-1 | LTC Counter Readings | LTC Max Tap Position | 11R | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | LTCM000046 | LTCMechanism | 704-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | CH000187 | ControlHouse | FH-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | CH000187 | ControlHouse | FH-Control House | Control House Patrol Inspection | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | CH000187 | ControlHouse | FH-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | CH000187 | ControlHouse | FH-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | CH000187 | ControlHouse | FH-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | CH000187 | ControlHouse | FH-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | CH000187 | ControlHouse | FH-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | CH000187 | ControlHouse | FH-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Readings | 9 Month Operations | 0 | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Patrol Inspection | General Comments | no nitrogen on truck to fill with | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Readings | General Comments | | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 20 | °C |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 40 | °C |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 20 | °C |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 40 | °C |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 20 | °C |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 40 | °C |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Readings | Winding Temp Present | 20 | °C |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 19 | °C |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 400 | psi |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Readings | Totalizer Meter Reading | .7686 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 290.00 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | WithLTC | 338-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | Needs nitro filled | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Readings | Operations Counter AL | 52 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Readings | Operations Counter AF | 52 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | WithLTC | 575-1 | LTC Transformer Readings | LTC Totalizer Reading | 736.80 | kw |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | YD000440 | Yard | 652-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | YD000440 | Yard | 652-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | YD000440 | Yard | 652-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | YD000440 | Yard | 652-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | YD000440 | Yard | 652-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | YD000440 | Yard | 652-Yard | Yard Patrol Inspection | General Comments | | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | YD000440 | Yard | 652-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | YD000440 | Yard | 652-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | YD000440 | Yard | 652-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | YD000440 | Yard | 652-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | YD000440 | Yard | 652-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | YD000440 | Yard | 652-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | YD000440 | Yard | 652-Yard | Yard Patrol Inspection | Clear of Trash? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Readings | General Comments | | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | YD000440 | Yard | 652-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | YD000440 | Yard | 652-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | YD000440 | Yard | 652-Yard | Yard Patrol Inspection | Ambient Temp | 27 | °F |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | FE000436 | Fence | 652-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | FE000436 | Fence | 652-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | FE000436 | Fence | 652-Fence | Fence Patrol Inspection | General Comments | | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | FE000436 | Fence | 652-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | FE000436 | Fence | 652-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | FE000436 | Fence | 652-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | FE000436 | Fence | 652-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | FE000436 | Fence | 652-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | FE000436 | Fence | 652-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | FE000436 | Fence | 652-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | FE000436 | Fence | 652-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | FE000436 | Fence | 652-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | FE000436 | Fence | 652-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | FE000436 | Fence | 652-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | FE000436 | Fence | 652-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | FE000436 | Fence | 652-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Readings | Amps C Ø | 12.0 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Readings | Amps B Ø | 12.0 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Readings | Amps A Ø | 12.0 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | MB0132 | BreakerVacuum | 704-0254 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0012 | NonLTC | 880-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0012 | NonLTC | 880-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000045 | LTCMechanism | FD-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000045 | LTCMechanism | FD-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000045 | LTCMechanism | FD-TRANS 1 | LTC Counter Readings | General Comments | | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000045 | LTCMechanism | FD-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000045 | LTCMechanism | FD-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 20482 | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000045 | LTCMechanism | FD-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 20482 | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000045 | LTCMechanism | FD-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000045 | LTCMechanism | FD-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000045 | LTCMechanism | FD-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000045 | LTCMechanism | FD-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000045 | LTCMechanism | FD-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 33 | °C |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000045 | LTCMechanism | FD-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 7 | °C |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000045 | LTCMechanism | FD-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 364 | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000045 | LTCMechanism | FD-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000045 | LTCMechanism | FD-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000045 | LTCMechanism | FD-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000044 | LTCMechanism | FD-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000044 | LTCMechanism | FD-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000044 | LTCMechanism | FD-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000044 | LTCMechanism | FD-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000044 | LTCMechanism | FD-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 17099 | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000044 | LTCMechanism | FD-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 17099 | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000044 | LTCMechanism | FD-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000044 | LTCMechanism | FD-TRANS 2 | LTC Counter Readings | General Comments | | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000044 | LTCMechanism | FD-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000044 | LTCMechanism | FD-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000045 | LTCMechanism | FD-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0242 | BreakerAirMagnetic | CW-12KV TR 2 | AMCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0242 | BreakerAirMagnetic | CW-12KV TR 2 | AMCB Readings | Switching Operations | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | YD000621 | Yard | FH-Yard | Yard Patrol Inspection | Ambient Temp | 28 | °F |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | YD000621 | Yard | FH-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | YD000621 | Yard | FH-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | YD000621 | Yard | FH-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | YD000621 | Yard | FH-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | YD000621 | Yard | FH-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | YD000621 | Yard | FH-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | YD000621 | Yard | FH-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | YD000621 | Yard | FH-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | YD000621 | Yard | FH-Yard | Yard Patrol Inspection | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | YD000621 | Yard | FH-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | YD000621 | Yard | FH-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | YD000621 | Yard | FH-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | YD000621 | Yard | FH-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | YD000621 | Yard | FH-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | YD000621 | Yard | FH-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | CH000408 | ControlHouse | 704-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | CH000408 | ControlHouse | 704-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0242 | BreakerAirMagnetic | CW-12KV TR 2 | AMCB Readings | Operations This Read AM | 0 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | YD000005 | Yard | 704-Yard | Yard Patrol Inspection | Ambient Temp | 32 | °F |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | YD000005 | Yard | 704-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | YD000005 | Yard | 704-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | YD000005 | Yard | 704-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | YD000005 | Yard | 704-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | YD000005 | Yard | 704-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | YD000005 | Yard | 704-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | YD000005 | Yard | 704-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | YD000005 | Yard | 704-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | YD000005 | Yard | 704-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | YD000005 | Yard | 704-Yard | Yard Patrol Inspection | General Comments | | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | YD000005 | Yard | 704-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | YD000005 | Yard | 704-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | YD000005 | Yard | 704-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | YD000005 | Yard | 704-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | LTCMechanism | CW-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | LTCMechanism | CW-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | The jar of dessicant needs to be refilled. | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | LTCMechanism | CW-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | LTCMechanism | CW-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Needs Replaced | check oil cup |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | LTCMechanism | CW-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0061 | LTCMechanism | CW-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0242 | BreakerAirMagnetic | CW-12KV TR 2 | AMCB Readings | Operations Counter AL | 130 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0242 | BreakerAirMagnetic | CW-12KV TR 2 | AMCB Readings | Operations Counter AF | 130 | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000044 | LTCMechanism | FD-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000044 | LTCMechanism | FD-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000044 | LTCMechanism | FD-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000044 | LTCMechanism | FD-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000044 | LTCMechanism | FD-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 165 | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000044 | LTCMechanism | FD-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 36 | °C |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LTCM000044 | LTCMechanism | FD-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 12 | °C |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0012 | NonLTC | 880-1 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0012 | NonLTC | 880-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0012 | NonLTC | 880-1 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0012 | NonLTC | 880-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0012 | NonLTC | 880-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0012 | NonLTC | 880-1 A | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0012 | NonLTC | 880-1 A | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0012 | NonLTC | 880-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0012 | NonLTC | 880-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0012 | NonLTC | 880-1 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0012 | NonLTC | 880-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1000 | psi |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 37 | °C |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 13 | °C |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Readings | Winding Temp Max | 38 | °C |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Readings | Winding Temp Present | 14 | °C |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 38 | °C |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 14 | °C |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 38 | °C |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 14 | °C |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 38 | °C |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000093 | WithLTC | FD-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 14 | °C |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0012 | NonLTC | 880-1 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0012 | NonLTC | 880-1 A | NonLTC Transformer Readings | General Comments | | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0012 | NonLTC | 880-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0012 | NonLTC | 880-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0012 | NonLTC | 880-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0012 | NonLTC | 880-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0012 | NonLTC | 880-1 A | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0012 | NonLTC | 880-1 A | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0012 | NonLTC | 880-1 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0012 | NonLTC | 880-1 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0012 | NonLTC | 880-1 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | M0012 | NonLTC | 880-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000083 | Switchgear | FH-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000083 | Switchgear | FH-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000083 | Switchgear | FH-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000083 | Switchgear | FH-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000083 | Switchgear | FH-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000083 | Switchgear | FH-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000083 | Switchgear | FH-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000083 | Switchgear | FH-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000083 | Switchgear | FH-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000083 | Switchgear | FH-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Readings | General Comments | h2 missing | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Readings | H2 Winding Temp Max | 0 | °C |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Readings | H2 Winding Temp Present | 0 | °C |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.5 | psi |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 15 | °C |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 45 | °C |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 15 | °C |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 40 | °C |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 15 | °C |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 40 | °C |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 20 | °C |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | ST000367 | Structure | 747-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | ST000367 | Structure | 747-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | ST000367 | Structure | 747-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | ST000367 | Structure | 747-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | ST000367 | Structure | 747-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | ST000367 | Structure | 747-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | ST000367 | Structure | 747-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | ST000367 | Structure | 747-Structure | Structure Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | ST000367 | Structure | 747-Structure | Structure Patrol Inspection | MOD Motor Jaw Coupling | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | ST000367 | Structure | 747-Structure | Structure Patrol Inspection | MOD Cabinet Internals Clean? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | ST000367 | Structure | 747-Structure | Structure Patrol Inspection | MOD Cabinet Heater functional? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | ST000367 | Structure | 747-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | ST000367 | Structure | 747-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | ST000367 | Structure | 747-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | ST000367 | Structure | 747-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | ST000367 | Structure | 747-Structure | Structure Patrol Inspection | General Comments | | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | ST000367 | Structure | 747-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | ST000367 | Structure | 747-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | ST000367 | Structure | 747-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | ST000367 | Structure | 747-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | ST000367 | Structure | 747-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | ST000367 | Structure | 747-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | ST000367 | Structure | 747-Structure | Structure Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | ST000367 | Structure | 747-Structure | Structure Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | ST000367 | Structure | 747-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | ST000367 | Structure | 747-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | YD000364 | Yard | 747-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | YD000364 | Yard | 747-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | YD000364 | Yard | 747-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | YD000364 | Yard | 747-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | YD000364 | Yard | 747-Yard | Yard Patrol Inspection | General Comments | | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | YD000364 | Yard | 747-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | YD000373 | Yard | 854-Yard | Yard Patrol Inspection | Ambient Temp | 22 | °F |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | YD000373 | Yard | 854-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BAT000951 | Battery | 747-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BAT000951 | Battery | 747-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BAT000951 | Battery | 747-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BAT000951 | Battery | 747-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BAT000951 | Battery | 747-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BAT000951 | Battery | 747-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BAT000951 | Battery | 747-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BAT000951 | Battery | 747-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BAT000951 | Battery | 747-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | YD000373 | Yard | 854-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | YD000373 | Yard | 854-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | YD000373 | Yard | 854-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | YD000373 | Yard | 854-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | YD000373 | Yard | 854-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | YD000373 | Yard | 854-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | YD000373 | Yard | 854-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | YD000373 | Yard | 854-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | YD000373 | Yard | 854-Yard | Yard Patrol Inspection | General Comments | | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | YD000373 | Yard | 854-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | YD000373 | Yard | 854-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | YD000373 | Yard | 854-Yard | Yard Patrol Inspection | Switch Stick Next Test Date | 2023-05-10 00:00:00.000000 | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | YD000373 | Yard | 854-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | YD000373 | Yard | 854-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BAT000951 | Battery | 747-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BAT000951 | Battery | 747-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0378 | BreakerVacuum | FH-1217 | VCB Readings | 9 Month Operations | 1 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BAT000951 | Battery | 747-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BAT000951 | Battery | 747-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BAT000951 | Battery | 747-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0378 | BreakerVacuum | FH-1217 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0378 | BreakerVacuum | FH-1217 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0378 | BreakerVacuum | FH-1217 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000083 | Switchgear | FH-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0378 | BreakerVacuum | FH-1217 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0378 | BreakerVacuum | FH-1217 | VCB Readings | Amps A Ø | 121.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0378 | BreakerVacuum | FH-1217 | VCB Readings | Amps B Ø | 146.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000083 | Switchgear | FH-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000083 | Switchgear | FH-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000083 | Switchgear | FH-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0378 | BreakerVacuum | FH-1217 | VCB Readings | Amps C Ø | 161.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0378 | BreakerVacuum | FH-1217 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0378 | BreakerVacuum | FH-1217 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000083 | Switchgear | FH-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000083 | Switchgear | FH-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000083 | Switchgear | FH-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000083 | Switchgear | FH-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0378 | BreakerVacuum | FH-1217 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0378 | BreakerVacuum | FH-1217 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0378 | BreakerVacuum | FH-1217 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0378 | BreakerVacuum | FH-1217 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0378 | BreakerVacuum | FH-1217 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0378 | BreakerVacuum | FH-1217 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0378 | BreakerVacuum | FH-1217 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0378 | BreakerVacuum | FH-1217 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0378 | BreakerVacuum | FH-1217 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0378 | BreakerVacuum | FH-1217 | VCB Readings | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0378 | BreakerVacuum | FH-1217 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0378 | BreakerVacuum | FH-1217 | VCB Readings | Operations Counter AF | 707 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0378 | BreakerVacuum | FH-1217 | VCB Readings | Operations Counter AL | 707 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0378 | BreakerVacuum | FH-1217 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0378 | BreakerVacuum | FH-1217 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0378 | BreakerVacuum | FH-1217 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | WithLTC | FH-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0233 | BreakerAirMagnetic | CW-1224 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0233 | BreakerAirMagnetic | CW-1224 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0233 | BreakerAirMagnetic | CW-1224 | AMCB Patrol Inspection | General Comments | | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0242 | BreakerAirMagnetic | CW-12KV TR 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0242 | BreakerAirMagnetic | CW-12KV TR 2 | AMCB Readings | 9 Months Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0242 | BreakerAirMagnetic | CW-12KV TR 2 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Readings | General Comments | | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Readings | Operations Counter AF | 179 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Readings | Operations Counter AL | 179 | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0931 | Regulator | 880-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0931 | Regulator | 880-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0931 | Regulator | 880-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0931 | Regulator | 880-1 C | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0931 | Regulator | 880-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0931 | Regulator | 880-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0931 | Regulator | 880-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0931 | Regulator | 880-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0931 | Regulator | 880-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0931 | Regulator | 880-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0931 | Regulator | 880-1 C | Regulator Patrol Inspection | Max Tap Position | 8R | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0931 | Regulator | 880-1 C | Regulator Patrol Inspection | Min Tap Position | 4L | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 100.00 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Readings | Totalizer Meter Reading | .5280 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Readings | General Comments | | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Patrol Inspection | General Comments | good | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Readings | LTC Totalizer Reading | 1975.68 | kw |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LTCM000013 | LTCMechanism | FH-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LTCM000013 | LTCMechanism | FH-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LTCM000013 | LTCMechanism | FH-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 624 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Readings | Operations Counter AL | 269 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Readings | Operations Counter AF | 269 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Readings | General Comments | | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | LTCC000889 | LTCControl | 575-1 | LTC Control Insp | All Connections OK? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | LTCC000889 | LTCControl | 575-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | LTCC000889 | LTCControl | 575-1 | LTC Control Insp | General Comments | | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | LTCC000889 | LTCControl | 575-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | LTCC000889 | LTCControl | 575-1 | LTC Control Insp | LTC Output Voltage Level | 123.6 | VAC |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | LTCC000889 | LTCControl | 575-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | LTCC000889 | LTCControl | 575-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | LTCC000889 | LTCControl | 575-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | LTCC000889 | LTCControl | 575-1 | LTC Control Insp | VRR Time Delay | 45 | Seconds |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Readings | Amps A Ø | 0.0 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Readings | Amps B Ø | 0.0 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Readings | Amps C Ø | 15.0 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Readings | Amps C Ø | 126.0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Readings | Amps B Ø | 158.0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Readings | Amps A Ø | 106.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LTCC000219 | LTCControl | CW-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LTCC000219 | LTCControl | CW-TRANS 1 | LTC Control Insp | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LTCC000219 | LTCControl | CW-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0931 | Regulator | 880-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0931 | Regulator | 880-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001798 | BreakerVacuum | 652-2303 | VCB Readings | 9 Month Operations | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LTCM000013 | LTCMechanism | FH-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LTCM000013 | LTCMechanism | FH-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LTCM000013 | LTCMechanism | FH-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LTCM000013 | LTCMechanism | FH-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LTCM000013 | LTCMechanism | FH-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LTCM000013 | LTCMechanism | FH-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 64937 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LTCM000013 | LTCMechanism | FH-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 64937 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LTCM000013 | LTCMechanism | FH-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LTCM000013 | LTCMechanism | FH-TRANS 1 | LTC Counter Readings | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LTCM000013 | LTCMechanism | FH-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LTCM000013 | LTCMechanism | FH-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | ST000018 | Structure | 880-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | DX0129 | RecloserElectronic | 376-4649 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | DX0129 | RecloserElectronic | 376-4649 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | DX0129 | RecloserElectronic | 376-4649 | Recloser Electronic Patrol Inspection | Amps C Ø | 0.0 | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | DX0129 | RecloserElectronic | 376-4649 | Recloser Electronic Patrol Inspection | Amps B Ø | 0.0 | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | DX0129 | RecloserElectronic | 376-4649 | Recloser Electronic Patrol Inspection | Amps A Ø | 0.0 | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | ST000018 | Structure | 880-Structure | Structure Patrol Inspection | General Comments | | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | ST000018 | Structure | 880-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | ST000018 | Structure | 880-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | ST000018 | Structure | 880-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | ST000018 | Structure | 880-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | ST000018 | Structure | 880-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | ST000018 | Structure | 880-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | ST000018 | Structure | 880-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | LTCMechanism | 854-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | LTCMechanism | 854-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | LTCMechanism | 854-1 | LTC Counter Readings | General Comments | | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | LTCMechanism | 854-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | LTCMechanism | 854-1 | LTC Counter Readings | LTC As Found Counter | 33855 | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | LTCMechanism | 854-1 | LTC Counter Readings | LTC As Left Counter | 33855 | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | LTCMechanism | 854-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | LTCMechanism | 854-1 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | LTCMechanism | 854-1 | LTC Counter Readings | LTC Max Tap Position | 16R | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | LTCMechanism | 854-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | LTCMechanism | 854-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 25 | °C |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | LTCMechanism | 854-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 10 | °C |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | LTCMechanism | 854-1 | LTC Counter Readings | LTC Operations Since Last Insp | 835 | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | LTCMechanism | 854-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | ST000018 | Structure | 880-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | ST000018 | Structure | 880-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | ST000018 | Structure | 880-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | ST000018 | Structure | 880-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | ST000018 | Structure | 880-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0376 | BreakerVacuum | FH-1215 | VCB Readings | 9 Month Operations | 1 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0376 | BreakerVacuum | FH-1215 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0376 | BreakerVacuum | FH-1215 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0376 | BreakerVacuum | FH-1215 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0376 | BreakerVacuum | FH-1215 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0376 | BreakerVacuum | FH-1215 | VCB Readings | Amps A Ø | 104.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0376 | BreakerVacuum | FH-1215 | VCB Readings | Amps B Ø | 92.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0376 | BreakerVacuum | FH-1215 | VCB Readings | Amps C Ø | 95.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0376 | BreakerVacuum | FH-1215 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0376 | BreakerVacuum | FH-1215 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0376 | BreakerVacuum | FH-1215 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BAT001548 | Battery | 534-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BAT001548 | Battery | 534-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 35 | °F |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BAT001548 | Battery | 534-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BAT001548 | Battery | 534-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BAT001548 | Battery | 534-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BAT001548 | Battery | 534-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BAT001548 | Battery | 534-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BAT001548 | Battery | 534-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BAT001548 | Battery | 534-Battery Bank | Battery Patrol Inspection | General Comments | Turned heater on | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BAT001548 | Battery | 534-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.0 | VDC |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BAT001548 | Battery | 534-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0376 | BreakerVacuum | FH-1215 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0376 | BreakerVacuum | FH-1215 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0376 | BreakerVacuum | FH-1215 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0376 | BreakerVacuum | FH-1215 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0376 | BreakerVacuum | FH-1215 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0376 | BreakerVacuum | FH-1215 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0376 | BreakerVacuum | FH-1215 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0376 | BreakerVacuum | FH-1215 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0376 | BreakerVacuum | FH-1215 | VCB Readings | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0376 | BreakerVacuum | FH-1215 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0376 | BreakerVacuum | FH-1215 | VCB Readings | Operations Counter AF | 329 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0376 | BreakerVacuum | FH-1215 | VCB Readings | Operations Counter AL | 329 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BAT001548 | Battery | 534-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Readings | Oil Temp Max | 33 | °C |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Readings | Totalizer Meter Reading | .8232 | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | M0041 | WithLTC | 376-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | DX0129 | RecloserElectronic | 376-4649 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | DX0129 | RecloserElectronic | 376-4649 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | DX0129 | RecloserElectronic | 376-4649 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | DX0129 | RecloserElectronic | 376-4649 | Recloser Electronic Patrol Inspection | Operations Counter | 6 | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | DX0129 | RecloserElectronic | 376-4649 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | DX0129 | RecloserElectronic | 376-4649 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | DX0129 | RecloserElectronic | 376-4649 | Recloser Electronic Patrol Inspection | General Comments | | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | DX0129 | RecloserElectronic | 376-4649 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | DX0129 | RecloserElectronic | 376-4649 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Readings | LTC Totalizer Reading | 3801.60 | kw |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | ST000018 | Structure | 880-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | ST000018 | Structure | 880-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | ST000018 | Structure | 880-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | ST000018 | Structure | 880-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | ST000018 | Structure | 880-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | ST000018 | Structure | 880-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | ST000018 | Structure | 880-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | ST000018 | Structure | 880-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0931 | Regulator | 880-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0931 | Regulator | 880-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0931 | Regulator | 880-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0931 | Regulator | 880-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0931 | Regulator | 880-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 125.0 | volts |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0931 | Regulator | 880-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 302052 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0931 | Regulator | 880-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0931 | Regulator | 880-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0931 | Regulator | 880-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0931 | Regulator | 880-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Readings | General Comments | | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | M0075 | WithLTC | 704-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | DX0129 | RecloserElectronic | 376-4649 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | DX0129 | RecloserElectronic | 376-4649 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | DX0129 | RecloserElectronic | 376-4649 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | DX0129 | RecloserElectronic | 376-4649 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | DX0129 | RecloserElectronic | 376-4649 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | DX0129 | RecloserElectronic | 376-4649 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | LTCC000823 | LTCControl | 376-1 | LTC Control Insp | All Connections OK? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | LTCC000823 | LTCControl | 376-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | LTCC000823 | LTCControl | 376-1 | LTC Control Insp | General Comments | | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | LTCC000823 | LTCControl | 376-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | LTCC000823 | LTCControl | 376-1 | LTC Control Insp | LTC Output Voltage Level | 125.2 | VAC |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | LTCC000823 | LTCControl | 376-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | LTCC000823 | LTCControl | 376-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | LTCC000823 | LTCControl | 376-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | ST000639 | Structure | CW-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | ST000639 | Structure | CW-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | ST000639 | Structure | CW-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | ST000639 | Structure | CW-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | ST000639 | Structure | CW-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | ST000639 | Structure | CW-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | ST000639 | Structure | CW-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0242 | BreakerAirMagnetic | CW-12KV TR 2 | AMCB Readings | Amps C Ø | 200.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0242 | BreakerAirMagnetic | CW-12KV TR 2 | AMCB Readings | Amps B Ø | 200.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0242 | BreakerAirMagnetic | CW-12KV TR 2 | AMCB Readings | Amps A Ø | 200.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0242 | BreakerAirMagnetic | CW-12KV TR 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0242 | BreakerAirMagnetic | CW-12KV TR 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0236 | BreakerVacuum | CW-1227 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0236 | BreakerVacuum | CW-1227 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0236 | BreakerVacuum | CW-1227 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0236 | BreakerVacuum | CW-1227 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0236 | BreakerVacuum | CW-1227 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Readings | 9 Month Operations | 0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Readings | Amps A Ø | 21.0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Readings | Amps B Ø | 58.0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Readings | Amps C Ø | 29.0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0236 | BreakerVacuum | CW-1227 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0236 | BreakerVacuum | CW-1227 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0236 | BreakerVacuum | CW-1227 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0236 | BreakerVacuum | CW-1227 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 51 | °C |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 26 | °C |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 60 | °C |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 27 | °C |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 64 | °C |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 28 | °C |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 60 | °C |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 28 | °C |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0236 | BreakerVacuum | CW-1227 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Readings | Operations Counter AL | 167 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Readings | Operations Counter AF | 167 | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | FE000820 | Fence | 704-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | FE000820 | Fence | 704-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | FE000820 | Fence | 704-Fence | Fence Patrol Inspection | General Comments | | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | FE000820 | Fence | 704-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | FE000820 | Fence | 704-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | FE000820 | Fence | 704-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | FE000820 | Fence | 704-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | FE000820 | Fence | 704-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | FE000820 | Fence | 704-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | FE000820 | Fence | 704-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | FE000820 | Fence | 704-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | FE000820 | Fence | 704-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | FE000820 | Fence | 704-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | FE000656 | Fence | CW-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | FE000656 | Fence | CW-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | FE000656 | Fence | CW-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | FE000656 | Fence | CW-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | FE000656 | Fence | CW-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | FE000656 | Fence | CW-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | FE000656 | Fence | CW-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | FE000656 | Fence | CW-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | FE000656 | Fence | CW-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | FE000656 | Fence | CW-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | FE000656 | Fence | CW-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | FE000656 | Fence | CW-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | FE000656 | Fence | CW-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | FE000656 | Fence | CW-Fence | Fence Patrol Inspection | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | FE000656 | Fence | CW-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | FE000656 | Fence | CW-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | FE000820 | Fence | 704-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | FE000820 | Fence | 704-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | FE000820 | Fence | 704-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0242 | BreakerAirMagnetic | CW-12KV TR 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0242 | BreakerAirMagnetic | CW-12KV TR 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | ST000639 | Structure | CW-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | ST000639 | Structure | CW-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | ST000639 | Structure | CW-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | ST000639 | Structure | CW-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | ST000639 | Structure | CW-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | ST000639 | Structure | CW-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | ST000639 | Structure | CW-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | ST000639 | Structure | CW-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0235 | BreakerAirMagnetic | CW-1226 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0235 | BreakerAirMagnetic | CW-1226 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0235 | BreakerAirMagnetic | CW-1226 | AMCB Patrol Inspection | General Comments | | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Readings | 9 Month Operations | 8 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | TR needs Nitrogen | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Readings | H2 Winding Temp Max | 51 | °C |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | WithLTC | CW-TRANS 1 | LTC Transformer Readings | H2 Winding Temp Present | 26 | °C |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0236 | BreakerVacuum | CW-1227 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0236 | BreakerVacuum | CW-1227 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0236 | BreakerVacuum | CW-1227 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0236 | BreakerVacuum | CW-1227 | VCB Readings | Operations Counter AL | 435 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0236 | BreakerVacuum | CW-1227 | VCB Readings | Operations Counter AF | 435 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0236 | BreakerVacuum | CW-1227 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0236 | BreakerVacuum | CW-1227 | VCB Readings | General Comments | | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | TX000092 | WithLTC | FD-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | ST000639 | Structure | CW-Structure | Structure Patrol Inspection | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | ST000639 | Structure | CW-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | ST000639 | Structure | CW-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | ST000639 | Structure | CW-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | ST000639 | Structure | CW-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | ST000639 | Structure | CW-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | ST000639 | Structure | CW-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | YD000179 | Yard | 376-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | YD000179 | Yard | 376-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | YD000179 | Yard | 376-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | YD000179 | Yard | 376-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | YD000179 | Yard | 376-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | YD000179 | Yard | 376-Yard | Yard Patrol Inspection | Ambient Temp | 32 | °F |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | FE000180 | Fence | 376-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | FE000180 | Fence | 376-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | FE000180 | Fence | 376-Fence | Fence Patrol Inspection | General Comments | | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | FE000180 | Fence | 376-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | FE000180 | Fence | 376-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | FE000180 | Fence | 376-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | FE000180 | Fence | 376-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | FE000180 | Fence | 376-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | FE000180 | Fence | 376-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | FE000180 | Fence | 376-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | FE000180 | Fence | 376-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | FE000180 | Fence | 376-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | FE000180 | Fence | 376-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | FE000180 | Fence | 376-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | FE000180 | Fence | 376-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | FE000180 | Fence | 376-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Readings | 9 Month Operations | 0 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | BK000250 | BreakerVacuum | 534-0251 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0236 | BreakerVacuum | CW-1227 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0236 | BreakerVacuum | CW-1227 | VCB Readings | Amps C Ø | 120.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0236 | BreakerVacuum | CW-1227 | VCB Readings | Amps B Ø | 130.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0236 | BreakerVacuum | CW-1227 | VCB Readings | Amps A Ø | 100.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0236 | BreakerVacuum | CW-1227 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0236 | BreakerVacuum | CW-1227 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0236 | BreakerVacuum | CW-1227 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0236 | BreakerVacuum | CW-1227 | VCB Readings | 9 Month Operations VCB New | 12 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0236 | BreakerVacuum | CW-1227 | VCB Readings | 9 Month Operations | 12 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Readings | Operations Counter AL | 162 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Readings | Operations Counter AF | 162 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Readings | General Comments | | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Readings | Amps C Ø | 88.0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Readings | Amps B Ø | 132.0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Readings | Amps A Ø | 120.0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001799 | BreakerVacuum | 652-2304 | VCB Readings | 9 Month Operations | 3 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LTCM000013 | LTCMechanism | FH-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LTCM000013 | LTCMechanism | FH-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Readings | General Comments | | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Readings | Operations Counter AF | 215 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Readings | Operations Counter AL | 215 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK001581 | BreakerVacuum | 338-4608 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | ST000185 | Structure | 376-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | ST000185 | Structure | 376-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | ST000185 | Structure | 376-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | ST000185 | Structure | 376-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | ST000185 | Structure | 376-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | ST000185 | Structure | 376-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | ST000185 | Structure | 376-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | ST000185 | Structure | 376-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | ST000185 | Structure | 376-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | ST000185 | Structure | 376-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | ST000185 | Structure | 376-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | ST000185 | Structure | 376-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | ST000185 | Structure | 376-Structure | Structure Patrol Inspection | General Comments | | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | ST000185 | Structure | 376-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | ST000185 | Structure | 376-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | ST000185 | Structure | 376-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | ST000185 | Structure | 376-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | ST000185 | Structure | 376-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | ST000185 | Structure | 376-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | ST000185 | Structure | 376-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | ST000185 | Structure | 376-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Readings | Amps C Ø | 8.0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Readings | Amps B Ø | 15.0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Readings | Amps A Ø | 14.0 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BK001800 | BreakerVacuum | 652-2305 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | YD000179 | Yard | 376-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | YD000179 | Yard | 376-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | YD000179 | Yard | 376-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | YD000179 | Yard | 376-Yard | Yard Patrol Inspection | General Comments | | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | YD000179 | Yard | 376-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | YD000179 | Yard | 376-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | YD000179 | Yard | 376-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | YD000179 | Yard | 376-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | LTCMechanism | 108-5 | LTC Counter Readings | LTC As Left Counter | 34644 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | LTCMechanism | 108-5 | LTC Counter Readings | LTC As Found Counter | 34644 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | LTCMechanism | 108-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | LTCMechanism | 108-5 | LTC Counter Readings | General Comments | | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | LTCMechanism | 108-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | FE000617 | Fence | FH-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | FE000617 | Fence | FH-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | FE000617 | Fence | FH-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | FE000617 | Fence | FH-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | FE000617 | Fence | FH-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | FE000617 | Fence | FH-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | FE000617 | Fence | FH-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | FE000617 | Fence | FH-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | FE000617 | Fence | FH-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | FE000617 | Fence | FH-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | FE000617 | Fence | FH-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | FE000617 | Fence | FH-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | FE000617 | Fence | FH-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | FE000617 | Fence | FH-Fence | Fence Patrol Inspection | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | FE000617 | Fence | FH-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | LTCC000075 | LTCControl | 108-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | LTCC000075 | LTCControl | 108-5 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | LTCC000075 | LTCControl | 108-5 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | LTCC000075 | LTCControl | 108-5 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | LTCC000075 | LTCControl | 108-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | LTCC000075 | LTCControl | 108-5 | LTC Control Insp | General Comments | | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | LTCC000075 | LTCControl | 108-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | LTCC000075 | LTCControl | 108-5 | LTC Control Insp | All Connections OK? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | FE000617 | Fence | FH-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | LTCMechanism | 108-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | ST000605 | Structure | FH-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | ST000605 | Structure | FH-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | ST000605 | Structure | FH-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | ST000605 | Structure | FH-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Readings | Operations Counter AL | 196 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Readings | Operations Counter AF | 196 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Readings | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | ST000605 | Structure | FH-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | ST000605 | Structure | FH-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | ST000605 | Structure | FH-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | ST000605 | Structure | FH-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | ST000605 | Structure | FH-Structure | Structure Patrol Inspection | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | ST000605 | Structure | FH-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | ST000605 | Structure | FH-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | ST000605 | Structure | FH-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | ST000605 | Structure | FH-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | ST000605 | Structure | FH-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LT0079 | WithLTC | FD-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Readings | Amps C Ø | 585.0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Readings | Amps B Ø | 635.0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Readings | Operations This Read Vac | 1 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Readings | Operations Counter AL | 294 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Readings | Operations Counter AF | 294 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Readings | Amps A Ø | 590.0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Readings | 9 Month Operations | 9 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | LTCMechanism | 108-5 | LTC Counter Readings | LTC Operations Since Last Insp | 702 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | LTCMechanism | 108-5 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 35 | °C |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LT0079 | WithLTC | FD-Offline Distribution | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LT0079 | WithLTC | FD-Offline Distribution | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LT0079 | WithLTC | FD-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LT0079 | WithLTC | FD-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LT0079 | WithLTC | FD-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LT0079 | WithLTC | FD-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LT0079 | WithLTC | FD-Offline Distribution | LTC Transformer Readings | General Comments | LTC oil is low | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LT0079 | WithLTC | FD-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | LTCMechanism | 652-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | LTCMechanism | 652-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | LTCMechanism | 652-1 | LTC Counter Readings | General Comments | | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | LTCMechanism | 652-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | LTCMechanism | 652-1 | LTC Counter Readings | LTC As Found Counter | 243398 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | LTCMechanism | 652-1 | LTC Counter Readings | LTC As Left Counter | 243401 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | LTCMechanism | 652-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | LTCMechanism | 652-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | LTCMechanism | 652-1 | LTC Counter Readings | LTC Max Tap Position | 5R | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | LTCMechanism | 652-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | LTCMechanism | 652-1 | LTC Counter Readings | LTC Operations Since Last Insp | 345 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | LTCMechanism | 652-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | LTCMechanism | 652-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | M0053 | LTCMechanism | 652-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LT0079 | WithLTC | FD-Offline Distribution | LTC Transformer Readings | Follow-up Action Required? | y | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LT0079 | WithLTC | FD-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LT0079 | WithLTC | FD-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LT0079 | WithLTC | FD-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 11:43 | Distribution | Ford Quarterly Inspection | LT0079 | WithLTC | FD-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | LTCMechanism | 108-5 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | LTCMechanism | 108-5 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | LTCMechanism | 108-5 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | LTCMechanism | 108-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000120 | Switchgear | CW-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000120 | Switchgear | CW-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000120 | Switchgear | CW-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000120 | Switchgear | CW-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000120 | Switchgear | CW-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | FE000844 | Fence | 338-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | FE000844 | Fence | 338-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | FE000844 | Fence | 338-Fence | Fence Patrol Inspection | General Comments | | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | FE000844 | Fence | 338-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | FE000844 | Fence | 338-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0643 | Regulator | 880-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0643 | Regulator | 880-1 B | Regulator Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | FE000844 | Fence | 338-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | FE000844 | Fence | 338-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | FE000844 | Fence | 338-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | FE000844 | Fence | 338-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | FE000844 | Fence | 338-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | FE000844 | Fence | 338-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | FE000844 | Fence | 338-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | FE000844 | Fence | 338-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | FE000844 | Fence | 338-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | FE000844 | Fence | 338-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | FE000844 | Fence | 338-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Readings | 9 Month Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000120 | Switchgear | CW-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000120 | Switchgear | CW-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000120 | Switchgear | CW-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000120 | Switchgear | CW-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000120 | Switchgear | CW-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000120 | Switchgear | CW-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000120 | Switchgear | CW-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000120 | Switchgear | CW-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000120 | Switchgear | CW-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0643 | Regulator | 880-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0643 | Regulator | 880-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0643 | Regulator | 880-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 36794 | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0643 | Regulator | 880-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.0 | volts |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0643 | Regulator | 880-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | LTCC000700 | LTCControl | 338-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | LTCC000700 | LTCControl | 338-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | LTCC000700 | LTCControl | 338-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | LTCC000700 | LTCControl | 338-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | LTCC000700 | LTCControl | 338-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | LTCC000700 | LTCControl | 338-1 | LTC Control Insp | General Comments | | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | LTCC000700 | LTCControl | 338-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | LTCC000700 | LTCControl | 338-1 | LTC Control Insp | All Connections OK? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | CH000034 | ControlHouse | 338-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | CH000034 | ControlHouse | 338-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | CH000034 | ControlHouse | 338-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | CH000034 | ControlHouse | 338-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | CH000034 | ControlHouse | 338-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | CH000034 | ControlHouse | 338-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | ST000605 | Structure | FH-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | ST000605 | Structure | FH-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | ST000605 | Structure | FH-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | ST000605 | Structure | FH-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | ST000605 | Structure | FH-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | ST000605 | Structure | FH-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | ST000605 | Structure | FH-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | ST000605 | Structure | FH-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | YD000505 | Yard | 434-Yard | Yard Patrol Inspection | General Comments | | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | YD000505 | Yard | 434-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | YD000505 | Yard | 434-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Readings | Amps C Ø | 67.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | PF000078 | PowerFuse | CW-12KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | PF000078 | PowerFuse | CW-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | PF000078 | PowerFuse | CW-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000120 | Switchgear | CW-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000120 | Switchgear | CW-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000120 | Switchgear | CW-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000120 | Switchgear | CW-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Readings | General Comments | | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000120 | Switchgear | CW-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Readings | Amps B Ø | 70.0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Readings | Amps A Ø | 45.0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Readings | Fault Adjusted Amps C Phase V | 6.27 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Readings | Fault Adjusted Amps B Phase V | 6.27 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Readings | Fault Adjusted Amps A Phase V | 6.27 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BK000911 | BreakerVacuum | 338-4609 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Readings | General Comments | | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | BAT001013 | Battery | CW-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0231 | BreakerVacuum | CW-1222 | VCB Readings | 9 Month Operations | 26 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | BAT001013 | Battery | CW-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | BAT001013 | Battery | CW-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | BAT001013 | Battery | CW-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | BAT001013 | Battery | CW-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | BAT001013 | Battery | CW-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | BAT001013 | Battery | CW-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0063 | RecloserElectronic | 854-0480 | Recloser Electronic Patrol Inspection | Amps A Ø | 60.0 | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0063 | RecloserElectronic | 854-0480 | Recloser Electronic Patrol Inspection | Amps B Ø | 118.0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Readings | Amps C Ø | 85.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | PF000079 | PowerFuse | CW-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | PF000079 | PowerFuse | CW-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | PF000079 | PowerFuse | CW-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0234 | BreakerVacuum | CW-1225 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0234 | BreakerVacuum | CW-1225 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0234 | BreakerVacuum | CW-1225 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0234 | BreakerVacuum | CW-1225 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0234 | BreakerVacuum | CW-1225 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0234 | BreakerVacuum | CW-1225 | VCB Readings | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0234 | BreakerVacuum | CW-1225 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0234 | BreakerVacuum | CW-1225 | VCB Readings | Operations Counter AF | 670 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0234 | BreakerVacuum | CW-1225 | VCB Readings | Operations Counter AL | 670 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0234 | BreakerVacuum | CW-1225 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0234 | BreakerVacuum | CW-1225 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0234 | BreakerVacuum | CW-1225 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0063 | RecloserElectronic | 854-0480 | Recloser Electronic Patrol Inspection | Amps C Ø | 37.0 | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0063 | RecloserElectronic | 854-0480 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | LTCMechanism | 108-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | LTCMechanism | 108-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0063 | RecloserElectronic | 854-0480 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Readings | Amps B Ø | 115.0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Readings | Amps A Ø | 85.0 | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Readings | General Comments | | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Readings | LTC Totalizer Reading | 7142.40 | kw |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Readings | Oil Temp Present | 15 | °C |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | LTCC000656 | LTCControl | 534-1 | LTC Control Insp | All Connections OK? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | LTCC000656 | LTCControl | 534-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0234 | BreakerVacuum | CW-1225 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0234 | BreakerVacuum | CW-1225 | VCB Readings | Amps A Ø | 135.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0234 | BreakerVacuum | CW-1225 | VCB Readings | Amps B Ø | 135.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0234 | BreakerVacuum | CW-1225 | VCB Readings | Amps C Ø | 135.0 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | LTCC000656 | LTCControl | 534-1 | LTC Control Insp | General Comments | | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | LTCC000656 | LTCControl | 534-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | LTCC000656 | LTCControl | 534-1 | LTC Control Insp | LTC Output Voltage Level | 124.3 | VAC |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | LTCC000656 | LTCControl | 534-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | LTCC000656 | LTCControl | 534-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | LTCC000656 | LTCControl | 534-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | LTCC000656 | LTCControl | 534-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0234 | BreakerVacuum | CW-1225 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0234 | BreakerVacuum | CW-1225 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0234 | BreakerVacuum | CW-1225 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0234 | BreakerVacuum | CW-1225 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0234 | BreakerVacuum | CW-1225 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0234 | BreakerVacuum | CW-1225 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Readings | Totalizer Meter Reading | .7440 | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Readings | Winding Temp Present | 25 | °C |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | BAT001013 | Battery | CW-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | BAT001013 | Battery | CW-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Readings | Operations Counter AL | 562 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Readings | Operations Counter AF | 562 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0231 | BreakerVacuum | CW-1222 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0231 | BreakerVacuum | CW-1222 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0231 | BreakerVacuum | CW-1222 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0231 | BreakerVacuum | CW-1222 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0231 | BreakerVacuum | CW-1222 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0231 | BreakerVacuum | CW-1222 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0231 | BreakerVacuum | CW-1222 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0231 | BreakerVacuum | CW-1222 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0231 | BreakerVacuum | CW-1222 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0231 | BreakerVacuum | CW-1222 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0231 | BreakerVacuum | CW-1222 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0231 | BreakerVacuum | CW-1222 | VCB Readings | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0231 | BreakerVacuum | CW-1222 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0231 | BreakerVacuum | CW-1222 | VCB Readings | Operations Counter AF | 737 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0231 | BreakerVacuum | CW-1222 | VCB Readings | Operations Counter AL | 737 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0231 | BreakerVacuum | CW-1222 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0231 | BreakerVacuum | CW-1222 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0231 | BreakerVacuum | CW-1222 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000091 | Switchgear | FH-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000091 | Switchgear | FH-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000091 | Switchgear | FH-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000091 | Switchgear | FH-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000091 | Switchgear | FH-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000091 | Switchgear | FH-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000091 | Switchgear | FH-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000091 | Switchgear | FH-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000091 | Switchgear | FH-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000091 | Switchgear | FH-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000091 | Switchgear | FH-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000091 | Switchgear | FH-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000091 | Switchgear | FH-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000091 | Switchgear | FH-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000091 | Switchgear | FH-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000091 | Switchgear | FH-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000091 | Switchgear | FH-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000091 | Switchgear | FH-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | SWG000091 | Switchgear | FH-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Readings | Operations Counter AL | 243 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Readings | Operations Counter AF | 243 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Readings | General Comments | | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KB0091 | BreakerVacuum | 108-5 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BB0464 | BreakerVacuum | 747-0504 | VCB Readings | 9 Month Operations | 0 | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0063 | RecloserElectronic | 854-0480 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0063 | RecloserElectronic | 854-0480 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0063 | RecloserElectronic | 854-0480 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0063 | RecloserElectronic | 854-0480 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0063 | RecloserElectronic | 854-0480 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0063 | RecloserElectronic | 854-0480 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0063 | RecloserElectronic | 854-0480 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0063 | RecloserElectronic | 854-0480 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0063 | RecloserElectronic | 854-0480 | Recloser Electronic Patrol Inspection | General Comments | | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0063 | RecloserElectronic | 854-0480 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0063 | RecloserElectronic | 854-0480 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0063 | RecloserElectronic | 854-0480 | Recloser Electronic Patrol Inspection | Operations Counter | 206 | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0063 | RecloserElectronic | 854-0480 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0063 | RecloserElectronic | 854-0480 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | BAT001013 | Battery | CW-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | BAT001013 | Battery | CW-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 25 | °F |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | LTCMechanism | 108-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | LTCMechanism | 108-5 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | BAT001013 | Battery | CW-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BCH001313 | Charger | 747-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BCH001313 | Charger | 747-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BCH001313 | Charger | 747-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BCH001313 | Charger | 747-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BCH001313 | Charger | 747-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.1 | amps |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BCH001313 | Charger | 747-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.0 | VDC |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BCH001313 | Charger | 747-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.0 | VDC |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BCH001313 | Charger | 747-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | LTCMechanism | 575-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | LTCMechanism | 575-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | LTCMechanism | 575-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | LTCMechanism | 575-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | LTCMechanism | 575-1 | LTC Counter Readings | LTC Operations Since Last Insp | 270 | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | LTCMechanism | 575-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | LTCMechanism | 575-1 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | LTCMechanism | 575-1 | LTC Counter Readings | LTC Max Tap Position | 8R | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | LTCMechanism | 575-1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | LTCMechanism | 575-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | LTCMechanism | 575-1 | LTC Counter Readings | LTC As Left Counter | 284 | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | LTCMechanism | 575-1 | LTC Counter Readings | LTC As Found Counter | 275 | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | LTCMechanism | 575-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | LTCMechanism | 575-1 | LTC Counter Readings | General Comments | | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | LTCMechanism | 575-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | B0466 | LTCMechanism | 575-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Readings | Unknown Operations | 1 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0231 | BreakerVacuum | CW-1222 | VCB Readings | 9 Month Operations VCB New | 26 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0231 | BreakerVacuum | CW-1222 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0231 | BreakerVacuum | CW-1222 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0231 | BreakerVacuum | CW-1222 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0231 | BreakerVacuum | CW-1222 | VCB Readings | Amps A Ø | 185.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0231 | BreakerVacuum | CW-1222 | VCB Readings | Amps B Ø | 215.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0231 | BreakerVacuum | CW-1222 | VCB Readings | Amps C Ø | 175.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000096 | Switchgear | CW-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002112 | BreakerVacuum | FH-1211 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002112 | BreakerVacuum | FH-1211 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000096 | Switchgear | CW-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000096 | Switchgear | CW-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002112 | BreakerVacuum | FH-1211 | VCB Readings | 9 Month Operations | 17 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000096 | Switchgear | CW-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000096 | Switchgear | CW-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000096 | Switchgear | CW-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000096 | Switchgear | CW-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000096 | Switchgear | CW-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000096 | Switchgear | CW-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | BCH000116 | Charger | CW-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.2 | amps |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | BCH000116 | Charger | CW-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 54.0 | VDC |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | BCH000116 | Charger | CW-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 54.0 | VDC |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | BCH000116 | Charger | CW-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | DX0110 | RecloserHydraulic | 880-0317 | Recloser Hydraulic Patrol Inspection | Operations Counter | 361 | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | DX0110 | RecloserHydraulic | 880-0317 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | DX0110 | RecloserHydraulic | 880-0317 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LTCC000442 | LTCControl | FH-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LTCC000442 | LTCControl | FH-TRANS 2 | LTC Control Insp | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LTCC000442 | LTCControl | FH-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002111 | BreakerVacuum | FH-1210 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Readings | General Comments | | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002111 | BreakerVacuum | FH-1210 | VCB Readings | Switching Operations | 8 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1100 | psi |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 0.00 | kw |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 52.50 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | DX0110 | RecloserHydraulic | 880-0317 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 240 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Readings | Winding Temp Present | 60 | °C |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Readings | Winding Temp Max | 65 | °C |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Readings | Totalizer Meter Reading | .7960 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | DX0110 | RecloserHydraulic | 880-0317 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | DX0110 | RecloserHydraulic | 880-0317 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0.0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 300 | psi |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Readings | LTC Totalizer Reading | 14328.00 | kw |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Readings | General Comments | | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | YD000505 | Yard | 434-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002112 | BreakerVacuum | FH-1211 | VCB Readings | Amps C Ø | 66.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002112 | BreakerVacuum | FH-1211 | VCB Readings | Amps B Ø | 91.0 | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | DX0110 | RecloserHydraulic | 880-0317 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | DX0110 | RecloserHydraulic | 880-0317 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 96 | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | DX0110 | RecloserHydraulic | 880-0317 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | DX0110 | RecloserHydraulic | 880-0317 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | DX0110 | RecloserHydraulic | 880-0317 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 25 | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | DX0110 | RecloserHydraulic | 880-0317 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | DX0110 | RecloserHydraulic | 880-0317 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | DX0110 | RecloserHydraulic | 880-0317 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | DX0110 | RecloserHydraulic | 880-0317 | Recloser Hydraulic Patrol Inspection | General Comments | amp probe is broken | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | DX0110 | RecloserHydraulic | 880-0317 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | BCH000116 | Charger | CW-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | BCH000116 | Charger | CW-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | BCH000116 | Charger | CW-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | BCH000116 | Charger | CW-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000096 | Switchgear | CW-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000096 | Switchgear | CW-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002112 | BreakerVacuum | FH-1211 | VCB Readings | Amps A Ø | 96.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002112 | BreakerVacuum | FH-1211 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002112 | BreakerVacuum | FH-1211 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000096 | Switchgear | CW-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000096 | Switchgear | CW-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000096 | Switchgear | CW-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000096 | Switchgear | CW-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000096 | Switchgear | CW-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000096 | Switchgear | CW-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000096 | Switchgear | CW-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | SWG000096 | Switchgear | CW-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | MX0465 | RecloserHydraulic | 575-0320 | Recloser Hydraulic Patrol Inspection | Operations Counter | 87 | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | MX0465 | RecloserHydraulic | 575-0320 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | MX0465 | RecloserHydraulic | 575-0320 | Recloser Hydraulic Patrol Inspection | General Comments | Amp probe is broken.  Could not get amp readings | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | MX0465 | RecloserHydraulic | 575-0320 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | MX0465 | RecloserHydraulic | 575-0320 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | MX0465 | RecloserHydraulic | 575-0320 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | MX0465 | RecloserHydraulic | 575-0320 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | MX0465 | RecloserHydraulic | 575-0320 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | MX0465 | RecloserHydraulic | 575-0320 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | MX0465 | RecloserHydraulic | 575-0320 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0.0 | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | MX0465 | RecloserHydraulic | 575-0320 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | YD000505 | Yard | 434-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002110 | BreakerVacuum | FH-1209 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | YD000505 | Yard | 434-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | YD000505 | Yard | 434-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002109 | BreakerVacuum | FH-12KV TR 1 | VCB Readings | Operations This Read Vac | 7 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002109 | BreakerVacuum | FH-12KV TR 1 | VCB Readings | Switching Operations | 7 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002109 | BreakerVacuum | FH-12KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002110 | BreakerVacuum | FH-1209 | VCB Readings | 9 Month Operations | 12 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002110 | BreakerVacuum | FH-1209 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002110 | BreakerVacuum | FH-1209 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002110 | BreakerVacuum | FH-1209 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002110 | BreakerVacuum | FH-1209 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002110 | BreakerVacuum | FH-1209 | VCB Readings | Amps A Ø | 71.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002110 | BreakerVacuum | FH-1209 | VCB Readings | Amps B Ø | 54.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002110 | BreakerVacuum | FH-1209 | VCB Readings | Amps C Ø | 103.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002110 | BreakerVacuum | FH-1209 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002110 | BreakerVacuum | FH-1209 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 42000 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002110 | BreakerVacuum | FH-1209 | VCB Readings | Switching Operations | 8 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002110 | BreakerVacuum | FH-1209 | VCB Readings | Operations This Read Vac | 8 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002110 | BreakerVacuum | FH-1209 | VCB Readings | Operations Counter AL | 14 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002110 | BreakerVacuum | FH-1209 | VCB Readings | Operations Counter AF | 14 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002110 | BreakerVacuum | FH-1209 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002110 | BreakerVacuum | FH-1209 | VCB Readings | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002110 | BreakerVacuum | FH-1209 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002110 | BreakerVacuum | FH-1209 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002110 | BreakerVacuum | FH-1209 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002110 | BreakerVacuum | FH-1209 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002110 | BreakerVacuum | FH-1209 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002110 | BreakerVacuum | FH-1209 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002110 | BreakerVacuum | FH-1209 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002110 | BreakerVacuum | FH-1209 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002110 | BreakerVacuum | FH-1209 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Readings | Winding Temp Present | 10 | °C |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Readings | Winding Temp Max | 40 | °C |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | T0182 | NonLTC | 108-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002109 | BreakerVacuum | FH-12KV TR 1 | VCB Readings | 9 Month Operations | 12 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002109 | BreakerVacuum | FH-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002109 | BreakerVacuum | FH-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002109 | BreakerVacuum | FH-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002109 | BreakerVacuum | FH-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002109 | BreakerVacuum | FH-12KV TR 1 | VCB Readings | Amps A Ø | 480.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002109 | BreakerVacuum | FH-12KV TR 1 | VCB Readings | Amps B Ø | 436.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002109 | BreakerVacuum | FH-12KV TR 1 | VCB Readings | Amps C Ø | 130.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002109 | BreakerVacuum | FH-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002109 | BreakerVacuum | FH-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002109 | BreakerVacuum | FH-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002109 | BreakerVacuum | FH-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002109 | BreakerVacuum | FH-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002109 | BreakerVacuum | FH-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002109 | BreakerVacuum | FH-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002109 | BreakerVacuum | FH-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002109 | BreakerVacuum | FH-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002109 | BreakerVacuum | FH-12KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002109 | BreakerVacuum | FH-12KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002109 | BreakerVacuum | FH-12KV TR 1 | VCB Readings | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002111 | BreakerVacuum | FH-1210 | VCB Readings | Operations This Read Vac | 8 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002111 | BreakerVacuum | FH-1210 | VCB Readings | Operations Counter AL | 30 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002111 | BreakerVacuum | FH-1210 | VCB Readings | Operations Counter AF | 30 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002111 | BreakerVacuum | FH-1210 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002111 | BreakerVacuum | FH-1210 | VCB Readings | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002111 | BreakerVacuum | FH-1210 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002111 | BreakerVacuum | FH-1210 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002111 | BreakerVacuum | FH-1210 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002111 | BreakerVacuum | FH-1210 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002109 | BreakerVacuum | FH-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002109 | BreakerVacuum | FH-12KV TR 1 | VCB Readings | Operations Counter AF | 130 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002109 | BreakerVacuum | FH-12KV TR 1 | VCB Readings | Operations Counter AL | 130 | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | YD000505 | Yard | 434-Yard | Yard Patrol Inspection | Ambient Temp | 22 | °F |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002111 | BreakerVacuum | FH-1210 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002111 | BreakerVacuum | FH-1210 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002111 | BreakerVacuum | FH-1210 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002111 | BreakerVacuum | FH-1210 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002111 | BreakerVacuum | FH-1210 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002111 | BreakerVacuum | FH-1210 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002111 | BreakerVacuum | FH-1210 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002111 | BreakerVacuum | FH-1210 | VCB Readings | Amps C Ø | 302.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002111 | BreakerVacuum | FH-1210 | VCB Readings | Amps B Ø | 298.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002111 | BreakerVacuum | FH-1210 | VCB Readings | Amps A Ø | 308.0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002111 | BreakerVacuum | FH-1210 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002111 | BreakerVacuum | FH-1210 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | YD000505 | Yard | 434-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/3/2023 9:24 | Distribution | Woodlake Quarterly Inspection | YD000505 | Yard | 434-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002111 | BreakerVacuum | FH-1210 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002111 | BreakerVacuum | FH-1210 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002111 | BreakerVacuum | FH-1210 | VCB Readings | 9 Month Operations | 17 | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | MX0465 | RecloserHydraulic | 575-0320 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 12:01 | Distribution | Deer Branch Quarterly Inspection | MX0465 | RecloserHydraulic | 575-0320 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | ST000115 | Structure | 338-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | ST000115 | Structure | 338-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | ST000115 | Structure | 338-Structure | Structure Patrol Inspection | General Comments | | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | ST000115 | Structure | 338-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Readings | 9 Month Operations VCB New | 11 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Readings | 9 Month Operations | 12 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | ST000115 | Structure | 338-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | ST000115 | Structure | 338-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | ST000115 | Structure | 338-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | ST000115 | Structure | 338-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | ST000115 | Structure | 338-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | ST000115 | Structure | 338-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0643 | Regulator | 880-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0643 | Regulator | 880-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0643 | Regulator | 880-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0642 | Regulator | 880-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0642 | Regulator | 880-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0642 | Regulator | 880-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0642 | Regulator | 880-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0642 | Regulator | 880-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 259456 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002113 | BreakerVacuum | FH-1212 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002113 | BreakerVacuum | FH-1212 | VCB Readings | Switching Operations | 7 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | YD000661 | Yard | CW-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | YD000661 | Yard | CW-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | YD000661 | Yard | CW-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0642 | Regulator | 880-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0642 | Regulator | 880-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0642 | Regulator | 880-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0642 | Regulator | 880-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0642 | Regulator | 880-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0642 | Regulator | 880-1 A | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0642 | Regulator | 880-1 A | Regulator Patrol Inspection | Max Tap Position | 9R | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0642 | Regulator | 880-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0642 | Regulator | 880-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0642 | Regulator | 880-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0642 | Regulator | 880-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0642 | Regulator | 880-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0642 | Regulator | 880-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0642 | Regulator | 880-1 A | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0642 | Regulator | 880-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0642 | Regulator | 880-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0642 | Regulator | 880-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0642 | Regulator | 880-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0642 | Regulator | 880-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | YD000661 | Yard | CW-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | YD000661 | Yard | CW-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BCH001044 | Charger | 652-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BCH001044 | Charger | 652-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BCH001044 | Charger | 652-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BCH001044 | Charger | 652-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.6 | amps |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BCH001044 | Charger | 652-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BCH001044 | Charger | 652-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BCH001044 | Charger | 652-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BCH001044 | Charger | 652-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | YD000661 | Yard | CW-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | CH000034 | ControlHouse | 338-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0643 | Regulator | 880-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0643 | Regulator | 880-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0643 | Regulator | 880-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0643 | Regulator | 880-1 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0643 | Regulator | 880-1 B | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0643 | Regulator | 880-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0643 | Regulator | 880-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0643 | Regulator | 880-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0643 | Regulator | 880-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0643 | Regulator | 880-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0643 | Regulator | 880-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0643 | Regulator | 880-1 B | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0643 | Regulator | 880-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | R0643 | Regulator | 880-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | CH000034 | ControlHouse | 338-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | CH000034 | ControlHouse | 338-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | CH000034 | ControlHouse | 338-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | CH000034 | ControlHouse | 338-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | YD000019 | Yard | 880-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | YD000019 | Yard | 880-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | YD000019 | Yard | 880-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | YD000019 | Yard | 880-Yard | Yard Patrol Inspection | General Comments | | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | YD000019 | Yard | 880-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | YD000019 | Yard | 880-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | YD000019 | Yard | 880-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Readings | Amps C Ø | 250.0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Readings | Amps B Ø | 225.0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Readings | Amps A Ø | 295.0 | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | K0179 | BreakerVacuum | 108-0452 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | YD000019 | Yard | 880-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | YD000019 | Yard | 880-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | YD000019 | Yard | 880-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | YD000019 | Yard | 880-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | YD000019 | Yard | 880-Yard | Yard Patrol Inspection | Ambient Temp | 31 | °F |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | CH000034 | ControlHouse | 338-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | CH000034 | ControlHouse | 338-Control House | Control House Patrol Inspection | General Comments | | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | CH000034 | ControlHouse | 338-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | CH000034 | ControlHouse | 338-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | CH000034 | ControlHouse | 338-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | CH000034 | ControlHouse | 338-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | ST000115 | Structure | 338-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | ST000115 | Structure | 338-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | ST000115 | Structure | 338-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | ST000115 | Structure | 338-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | ST000115 | Structure | 338-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LTCC000543 | LTCControl | CW-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LTCC000543 | LTCControl | CW-TRANS 2 | LTC Control Insp | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LTCC000543 | LTCControl | CW-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | ST000115 | Structure | 338-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | ST000115 | Structure | 338-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002113 | BreakerVacuum | FH-1212 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | YD000661 | Yard | CW-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | YD000661 | Yard | CW-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | YD000661 | Yard | CW-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | YD000661 | Yard | CW-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | YD000661 | Yard | CW-Yard | Yard Patrol Inspection | Ambient Temp | 25 | °F |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002113 | BreakerVacuum | FH-1212 | VCB Readings | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002113 | BreakerVacuum | FH-1212 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002113 | BreakerVacuum | FH-1212 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002113 | BreakerVacuum | FH-1212 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002113 | BreakerVacuum | FH-1212 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002113 | BreakerVacuum | FH-1212 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002113 | BreakerVacuum | FH-1212 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002113 | BreakerVacuum | FH-1212 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002113 | BreakerVacuum | FH-1212 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002113 | BreakerVacuum | FH-1212 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002113 | BreakerVacuum | FH-1212 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002113 | BreakerVacuum | FH-1212 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002113 | BreakerVacuum | FH-1212 | VCB Readings | Amps C Ø | 0.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002113 | BreakerVacuum | FH-1212 | VCB Readings | Amps B Ø | 0.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002113 | BreakerVacuum | FH-1212 | VCB Readings | Amps A Ø | 0.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002113 | BreakerVacuum | FH-1212 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002113 | BreakerVacuum | FH-1212 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002113 | BreakerVacuum | FH-1212 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002113 | BreakerVacuum | FH-1212 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002113 | BreakerVacuum | FH-1212 | VCB Readings | 9 Month Operations | 14 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002112 | BreakerVacuum | FH-1211 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002112 | BreakerVacuum | FH-1211 | VCB Readings | Switching Operations | 8 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002112 | BreakerVacuum | FH-1211 | VCB Readings | Operations This Read Vac | 8 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002112 | BreakerVacuum | FH-1211 | VCB Readings | Operations Counter AL | 33 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002112 | BreakerVacuum | FH-1211 | VCB Readings | Operations Counter AF | 33 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002112 | BreakerVacuum | FH-1211 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002112 | BreakerVacuum | FH-1211 | VCB Readings | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002112 | BreakerVacuum | FH-1211 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002112 | BreakerVacuum | FH-1211 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002112 | BreakerVacuum | FH-1211 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002112 | BreakerVacuum | FH-1211 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002112 | BreakerVacuum | FH-1211 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002112 | BreakerVacuum | FH-1211 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002112 | BreakerVacuum | FH-1211 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002112 | BreakerVacuum | FH-1211 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002112 | BreakerVacuum | FH-1211 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002112 | BreakerVacuum | FH-1211 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002112 | BreakerVacuum | FH-1211 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 10:09 | Distribution | Adams Quarterly Inspection | KT0036 | WithLTC | 108-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | PF000150 | PowerFuse | FH-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | PF000150 | PowerFuse | FH-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | PF000150 | PowerFuse | FH-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | YD000661 | Yard | CW-Yard | Yard Patrol Inspection | Oil stop valve operational? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | YD000661 | Yard | CW-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | YD000661 | Yard | CW-Yard | Yard Patrol Inspection | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | YD000661 | Yard | CW-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | YD000661 | Yard | CW-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | YD000661 | Yard | CW-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | YD000661 | Yard | CW-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | ST000115 | Structure | 338-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | ST000115 | Structure | 338-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | ST000115 | Structure | 338-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | LTCMechanism | FH-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | LTCMechanism | FH-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | LTCMechanism | FH-TRANS 2 | LTC Counter Readings | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | LTCMechanism | FH-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | LTCMechanism | FH-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 116936 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | LTCMechanism | FH-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 116936 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | LTCMechanism | FH-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | YD000661 | Yard | CW-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | LTCMechanism | FH-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | LTCMechanism | FH-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | LTCMechanism | FH-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | LTCMechanism | FH-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | LTCMechanism | FH-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 113 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002113 | BreakerVacuum | FH-1212 | VCB Readings | Operations This Read Vac | 7 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002113 | BreakerVacuum | FH-1212 | VCB Readings | Operations Counter AL | 20 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | LTCMechanism | FH-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | LTCMechanism | FH-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | LTCMechanism | FH-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | ST000115 | Structure | 338-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | ST000115 | Structure | 338-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0082 | LTCMechanism | FH-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Readings | Totalizer Meter Reading | .6872 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Readings | Oil Temp Present | 43 | °C |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Readings | Oil Temp Max | 66 | °C |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Readings | LTC Totalizer Reading | 3298.56 | kw |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Readings | General Comments | | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | M0059 | WithLTC | 534-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BK002113 | BreakerVacuum | FH-1212 | VCB Readings | Operations Counter AF | 20 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | ST000090 | Structure | 534-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | ST000090 | Structure | 534-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | ST000090 | Structure | 534-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0239 | BreakerVacuum | CW-12KV BUS TIE SEC 1 | VCB Readings | 9 Month Operations | 7 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0239 | BreakerVacuum | CW-12KV BUS TIE SEC 1 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0239 | BreakerVacuum | CW-12KV BUS TIE SEC 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0239 | BreakerVacuum | CW-12KV BUS TIE SEC 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0239 | BreakerVacuum | CW-12KV BUS TIE SEC 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0239 | BreakerVacuum | CW-12KV BUS TIE SEC 1 | VCB Readings | Amps A Ø | 0.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0239 | BreakerVacuum | CW-12KV BUS TIE SEC 1 | VCB Readings | Amps B Ø | 0.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0239 | BreakerVacuum | CW-12KV BUS TIE SEC 1 | VCB Readings | Amps C Ø | 0.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0239 | BreakerVacuum | CW-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0239 | BreakerVacuum | CW-12KV BUS TIE SEC 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0239 | BreakerVacuum | CW-12KV BUS TIE SEC 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0239 | BreakerVacuum | CW-12KV BUS TIE SEC 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | ST000090 | Structure | 534-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | ST000090 | Structure | 534-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | ST000090 | Structure | 534-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | ST000090 | Structure | 534-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | ST000090 | Structure | 534-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | ST000090 | Structure | 534-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0238 | BreakerAirMagnetic | CW-1229 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0238 | BreakerAirMagnetic | CW-1229 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0238 | BreakerAirMagnetic | CW-1229 | AMCB Readings | Amps C Ø | 0.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0238 | BreakerAirMagnetic | CW-1229 | AMCB Readings | Amps B Ø | 0.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0238 | BreakerAirMagnetic | CW-1229 | AMCB Readings | Amps A Ø | 0.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0238 | BreakerAirMagnetic | CW-1229 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0238 | BreakerAirMagnetic | CW-1229 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0238 | BreakerAirMagnetic | CW-1229 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0238 | BreakerAirMagnetic | CW-1229 | AMCB Readings | 9 Months Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0238 | BreakerAirMagnetic | CW-1229 | AMCB Readings | 9 Month Ops New | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0239 | BreakerVacuum | CW-12KV BUS TIE SEC 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0239 | BreakerVacuum | CW-12KV BUS TIE SEC 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0239 | BreakerVacuum | CW-12KV BUS TIE SEC 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0239 | BreakerVacuum | CW-12KV BUS TIE SEC 1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0239 | BreakerVacuum | CW-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | PF000077 | PowerFuse | CW-STA SET NO 2 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | PF000077 | PowerFuse | CW-STA SET NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | PF000077 | PowerFuse | CW-STA SET NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | PF000080 | PowerFuse | CW-12KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | PF000080 | PowerFuse | CW-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | PF000080 | PowerFuse | CW-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | LTCMechanism | 338-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | LTCMechanism | 338-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | LTCMechanism | 338-1 | LTC Counter Readings | General Comments | | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | LTCMechanism | 338-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | LTCMechanism | 338-1 | LTC Counter Readings | LTC As Found Counter | 50789 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | LTCMechanism | 338-1 | LTC Counter Readings | LTC As Left Counter | 50791 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | LTCMechanism | 338-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | LTCMechanism | 338-1 | LTC Counter Readings | LTC Current Tap Position | 5L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | LTCMechanism | 338-1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | LTCMechanism | 338-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | LTCC000663 | LTCControl | 704-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | LTCC000663 | LTCControl | 704-1 | LTC Control Insp | All Connections OK? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0064 | RecloserElectronic | 854-0481 | Recloser Electronic Patrol Inspection | Operations Counter | 210 | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0064 | RecloserElectronic | 854-0481 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0064 | RecloserElectronic | 854-0481 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BAT001189 | Battery | 652-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BAT001189 | Battery | 652-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BAT001189 | Battery | 652-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 25.7 | VDC |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BAT001189 | Battery | 652-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.5 | VDC |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BAT001189 | Battery | 652-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BAT001189 | Battery | 652-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BAT001189 | Battery | 652-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BAT001189 | Battery | 652-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BAT001189 | Battery | 652-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BAT001189 | Battery | 652-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BAT001189 | Battery | 652-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BAT001189 | Battery | 652-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BAT001189 | Battery | 652-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 27 | °F |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0064 | RecloserElectronic | 854-0481 | Recloser Electronic Patrol Inspection | General Comments | | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | YD000110 | Yard | 338-Yard | Yard Patrol Inspection | Ambient Temp | 32 | °F |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0064 | RecloserElectronic | 854-0481 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0064 | RecloserElectronic | 854-0481 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0064 | RecloserElectronic | 854-0481 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0064 | RecloserElectronic | 854-0481 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0064 | RecloserElectronic | 854-0481 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0064 | RecloserElectronic | 854-0481 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0064 | RecloserElectronic | 854-0481 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0064 | RecloserElectronic | 854-0481 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0064 | RecloserElectronic | 854-0481 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0064 | RecloserElectronic | 854-0481 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0064 | RecloserElectronic | 854-0481 | Recloser Electronic Patrol Inspection | Amps C Ø | 105.0 | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0064 | RecloserElectronic | 854-0481 | Recloser Electronic Patrol Inspection | Amps B Ø | 190.0 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | YD000084 | Yard | 534-Yard | Yard Patrol Inspection | General Comments | | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | YD000084 | Yard | 534-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | YD000084 | Yard | 534-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | YD000084 | Yard | 534-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | ST000090 | Structure | 534-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0064 | RecloserElectronic | 854-0481 | Recloser Electronic Patrol Inspection | Amps A Ø | 190.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | LTCMechanism | CW-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | ST000090 | Structure | 534-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | ST000090 | Structure | 534-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | ST000090 | Structure | 534-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | ST000090 | Structure | 534-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | ST000090 | Structure | 534-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | ST000090 | Structure | 534-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | ST000090 | Structure | 534-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | ST000090 | Structure | 534-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | ST000090 | Structure | 534-Structure | Structure Patrol Inspection | General Comments | | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | ST000090 | Structure | 534-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | ST000090 | Structure | 534-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | ST000090 | Structure | 534-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | ST000090 | Structure | 534-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | ST000090 | Structure | 534-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | PF000151 | PowerFuse | FH-12KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | PF000151 | PowerFuse | FH-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | PF000151 | PowerFuse | FH-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -1.0 | psi |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Readings | Totalizer Meter Reading | .9250 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BAT001031 | Battery | FH-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BAT001031 | Battery | FH-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | LTCC000970 | LTCControl | 652-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Readings | Winding Temp Max | 0 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Readings | Winding Temp Present | 0 | °C |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | LTCC000970 | LTCControl | 652-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | LTCC000970 | LTCControl | 652-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BAT001031 | Battery | FH-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BAT001031 | Battery | FH-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BAT001031 | Battery | FH-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0375 | BreakerVacuum | FH-1214 | VCB Readings | 9 Month Operations | 1 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0375 | BreakerVacuum | FH-1214 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0375 | BreakerVacuum | FH-1214 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0375 | BreakerVacuum | FH-1214 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Readings | Operations This Read Vac | 2 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Readings | Operations Counter AL | 162 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Readings | Operations Counter AF | 162 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Readings | General Comments | | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Readings | Fault Operations C Ø | 1 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0375 | BreakerVacuum | FH-1214 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0375 | BreakerVacuum | FH-1214 | VCB Readings | Amps A Ø | 76.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0375 | BreakerVacuum | FH-1214 | VCB Readings | Amps B Ø | 73.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0375 | BreakerVacuum | FH-1214 | VCB Readings | Amps C Ø | 91.0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0239 | BreakerVacuum | CW-12KV BUS TIE SEC 1 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | LTCMechanism | CW-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | LTCMechanism | CW-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | LTCMechanism | CW-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | LTCMechanism | CW-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 720 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0239 | BreakerVacuum | CW-12KV BUS TIE SEC 1 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0239 | BreakerVacuum | CW-12KV BUS TIE SEC 1 | VCB Readings | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0239 | BreakerVacuum | CW-12KV BUS TIE SEC 1 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0239 | BreakerVacuum | CW-12KV BUS TIE SEC 1 | VCB Readings | Operations Counter AF | 259 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0239 | BreakerVacuum | CW-12KV BUS TIE SEC 1 | VCB Readings | Operations Counter AL | 259 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0239 | BreakerVacuum | CW-12KV BUS TIE SEC 1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | LTCMechanism | 338-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | LTCMechanism | 338-1 | LTC Counter Readings | LTC Operations Since Last Insp | 226 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | LTCMechanism | 338-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | LTCMechanism | 338-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | B0413 | LTCMechanism | 338-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | LTCMechanism | CW-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | LTCMechanism | CW-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 5R | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | LTCMechanism | CW-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0239 | BreakerVacuum | CW-12KV BUS TIE SEC 1 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0239 | BreakerVacuum | CW-12KV BUS TIE SEC 1 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | LTCC000970 | LTCControl | 652-1 | LTC Control Insp | All Connections OK? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | LTCC000970 | LTCControl | 652-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | LTCC000970 | LTCControl | 652-1 | LTC Control Insp | General Comments | | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | LTCC000970 | LTCControl | 652-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | LTCC000970 | LTCControl | 652-1 | LTC Control Insp | LTC Output Voltage Level | 124.2 | VAC |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | LTCC000970 | LTCControl | 652-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | LTCMechanism | CW-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | LTCMechanism | CW-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 116907 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | LTCMechanism | CW-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 116907 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | LTCMechanism | CW-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | LTCMechanism | CW-TRANS 1 | LTC Counter Readings | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | LTCMechanism | CW-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LT0060 | LTCMechanism | CW-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Readings | General Comments | | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | WithLTC | 747-1 | LTC Transformer Readings | LTC Totalizer Reading | 8880.00 | kw |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0377 | BreakerVacuum | FH-1216 | VCB Readings | Amps B Ø | 97.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0377 | BreakerVacuum | FH-1216 | VCB Readings | Amps C Ø | 94.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0377 | BreakerVacuum | FH-1216 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0377 | BreakerVacuum | FH-1216 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0377 | BreakerVacuum | FH-1216 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0377 | BreakerVacuum | FH-1216 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0377 | BreakerVacuum | FH-1216 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0377 | BreakerVacuum | FH-1216 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0377 | BreakerVacuum | FH-1216 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0377 | BreakerVacuum | FH-1216 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0377 | BreakerVacuum | FH-1216 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0377 | BreakerVacuum | FH-1216 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0377 | BreakerVacuum | FH-1216 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0377 | BreakerVacuum | FH-1216 | VCB Readings | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0377 | BreakerVacuum | FH-1216 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | PF000152 | PowerFuse | FH-STA SER NO 2 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | PF000152 | PowerFuse | FH-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | PF000152 | PowerFuse | FH-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0377 | BreakerVacuum | FH-1216 | VCB Readings | Operations Counter AF | 251 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0377 | BreakerVacuum | FH-1216 | VCB Readings | Operations Counter AL | 251 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0377 | BreakerVacuum | FH-1216 | VCB Readings | Operations This Read Vac | 3 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0377 | BreakerVacuum | FH-1216 | VCB Readings | Switching Operations | 3 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0377 | BreakerVacuum | FH-1216 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | LTCMechanism | 747-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | LTCMechanism | 747-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | LTCMechanism | 747-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0238 | BreakerAirMagnetic | CW-1229 | AMCB Readings | Unknown Operations | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BAT001495 | Battery | 338-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.4 | VDC |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BAT001495 | Battery | 338-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 25.8 | VDC |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BAT001495 | Battery | 338-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BAT001495 | Battery | 338-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | LTCC000459 | LTCControl | 854-1 | LTC Control Insp | All Connections OK? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | LTCC000459 | LTCControl | 854-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | LTCC000459 | LTCControl | 854-1 | LTC Control Insp | General Comments | | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | LTCC000459 | LTCControl | 854-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | LTCC000459 | LTCControl | 854-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | LTCC000459 | LTCControl | 854-1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | LTCC000459 | LTCControl | 854-1 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | LTCC000459 | LTCControl | 854-1 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | LTCC000459 | LTCControl | 854-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | ST000376 | Structure | 854-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | ST000376 | Structure | 854-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | ST000376 | Structure | 854-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | ST000376 | Structure | 854-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | ST000376 | Structure | 854-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | FE000822 | Fence | 534-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | FE000822 | Fence | 534-Fence | Fence Patrol Inspection | General Comments | | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | FE000822 | Fence | 534-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | FE000822 | Fence | 534-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Readings | Amps C Ø | 165.0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Readings | Amps B Ø | 125.0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Readings | Amps A Ø | 130.0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Readings | 9 Month Operations VCB New | 2 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001414 | BreakerVacuum | 747-0516 | VCB Readings | 9 Month Operations | 2 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0237 | BreakerAirMagnetic | CW-1228 | AMCB Patrol Inspection | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0237 | BreakerAirMagnetic | CW-1228 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0237 | BreakerAirMagnetic | CW-1228 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BAT001495 | Battery | 338-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BAT001495 | Battery | 338-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 74 | °F |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BAT001495 | Battery | 338-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | LTCMechanism | 747-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | LTCMechanism | 747-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | LTCMechanism | 747-1 | LTC Counter Readings | General Comments | | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | LTCMechanism | 747-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | LTCMechanism | 747-1 | LTC Counter Readings | LTC As Found Counter | 13056 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | LTCMechanism | 747-1 | LTC Counter Readings | LTC As Left Counter | 13056 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | LTCMechanism | 747-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | LTCMechanism | 747-1 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | LTCMechanism | 747-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | LTCMechanism | 747-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | LTCMechanism | 747-1 | LTC Counter Readings | LTC Operations Since Last Insp | 120 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | B0408 | LTCMechanism | 747-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0377 | BreakerVacuum | FH-1216 | VCB Readings | 9 Month Operations | 4 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0377 | BreakerVacuum | FH-1216 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0377 | BreakerVacuum | FH-1216 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0377 | BreakerVacuum | FH-1216 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0377 | BreakerVacuum | FH-1216 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0377 | BreakerVacuum | FH-1216 | VCB Readings | Amps A Ø | 108.0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BAT001495 | Battery | 338-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BAT001495 | Battery | 338-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BAT001495 | Battery | 338-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BAT001495 | Battery | 338-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BAT001495 | Battery | 338-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BAT001495 | Battery | 338-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | BAT001495 | Battery | 338-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 25 | °C |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 70 | °C |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 35 | °C |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 80 | °C |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 20 | °C |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 65 | °C |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | FE000367 | Fence | 854-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | FE000367 | Fence | 854-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0238 | BreakerAirMagnetic | CW-1229 | AMCB Readings | Switching Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0238 | BreakerAirMagnetic | CW-1229 | AMCB Readings | Operations This Read AM | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0238 | BreakerAirMagnetic | CW-1229 | AMCB Readings | Operations Counter AL | 2063 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0238 | BreakerAirMagnetic | CW-1229 | AMCB Readings | Operations Counter AF | 2063 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0238 | BreakerAirMagnetic | CW-1229 | AMCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0238 | BreakerAirMagnetic | CW-1229 | AMCB Readings | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0238 | BreakerAirMagnetic | CW-1229 | AMCB Patrol Inspection | General Comments | | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0238 | BreakerAirMagnetic | CW-1229 | AMCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0238 | BreakerAirMagnetic | CW-1229 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0238 | BreakerAirMagnetic | CW-1229 | AMCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0238 | BreakerAirMagnetic | CW-1229 | AMCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0238 | BreakerAirMagnetic | CW-1229 | AMCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0238 | BreakerAirMagnetic | CW-1229 | AMCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0238 | BreakerAirMagnetic | CW-1229 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0238 | BreakerAirMagnetic | CW-1229 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | YD000084 | Yard | 534-Yard | Yard Patrol Inspection | Ambient Temp | 32 | °F |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | YD000084 | Yard | 534-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | YD000084 | Yard | 534-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | YD000084 | Yard | 534-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | YD000084 | Yard | 534-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | YD000084 | Yard | 534-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0064 | RecloserElectronic | 854-0481 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0064 | RecloserElectronic | 854-0481 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KX0064 | RecloserElectronic | 854-0481 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | YD000084 | Yard | 534-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | FE000016 | Fence | 880-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | FE000016 | Fence | 880-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | FE000016 | Fence | 880-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | FE000016 | Fence | 880-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | FE000016 | Fence | 880-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | FE000016 | Fence | 880-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | FE000016 | Fence | 880-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | FE000016 | Fence | 880-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | FE000016 | Fence | 880-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | FE000016 | Fence | 880-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | FE000016 | Fence | 880-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | FE000016 | Fence | 880-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | FE000016 | Fence | 880-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | FE000016 | Fence | 880-Fence | Fence Patrol Inspection | General Comments | some top rail and post showing signs of rust  as well as fabric | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | FE000016 | Fence | 880-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/3/2023 12:53 | Distribution | Straight Creek Quarterly Inspection | FE000016 | Fence | 880-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | YD000084 | Yard | 534-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | YD000084 | Yard | 534-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/3/2023 12:43 | Distribution | Manchester Quarterly Inspection | YD000084 | Yard | 534-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | LTCC000663 | LTCControl | 704-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | LTCC000663 | LTCControl | 704-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | LTCC000663 | LTCControl | 704-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | LTCC000663 | LTCControl | 704-1 | LTC Control Insp | LTC Output Voltage Level | 124.8 | VAC |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | LTCC000663 | LTCControl | 704-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/3/2023 15:02 | Distribution | Manchester South Quarterly Inspection | LTCC000663 | LTCControl | 704-1 | LTC Control Insp | General Comments | | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | ST000376 | Structure | 854-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | ST000376 | Structure | 854-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | ST000376 | Structure | 854-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | ST000376 | Structure | 854-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | ST000376 | Structure | 854-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | ST000376 | Structure | 854-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | ST000376 | Structure | 854-Structure | Structure Patrol Inspection | General Comments | | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | ST000376 | Structure | 854-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | ST000376 | Structure | 854-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | ST000376 | Structure | 854-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | ST000376 | Structure | 854-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | ST000376 | Structure | 854-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | ST000376 | Structure | 854-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | ST000376 | Structure | 854-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | ST000376 | Structure | 854-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | ST000376 | Structure | 854-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | FE000367 | Fence | 854-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | FE000367 | Fence | 854-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | FE000367 | Fence | 854-Fence | Fence Patrol Inspection | General Comments | | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | FE000367 | Fence | 854-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | FE000367 | Fence | 854-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | FE000367 | Fence | 854-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | FE000367 | Fence | 854-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | nitrogen at 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LT0081 | WithLTC | FH-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | FE000367 | Fence | 854-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | FE000367 | Fence | 854-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | FE000367 | Fence | 854-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | FE000367 | Fence | 854-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | FE000367 | Fence | 854-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | FE000367 | Fence | 854-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | FE000367 | Fence | 854-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | ANN000107 | Annunciator | FH-Annunciator Panel | Annunciator Patrol Inspection | All Lights Functioning? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BAT001031 | Battery | FH-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BAT001031 | Battery | FH-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BAT001031 | Battery | FH-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | ANN000107 | Annunciator | FH-Annunciator Panel | Annunciator Patrol Inspection | Control House Alarm Audible? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | ANN000107 | Annunciator | FH-Annunciator Panel | Annunciator Patrol Inspection | ESOC Received Alarm Test? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Readings | 9 Month Operations | 2 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | YD000110 | Yard | 338-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/3/2023 9:54 | Distribution | Irvine Quarterly Inspection | BAT001189 | Battery | 652-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BAT001031 | Battery | FH-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BAT001031 | Battery | FH-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BCH001075 | Charger | FH-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BCH001075 | Charger | FH-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.9 | VDC |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Readings | Amps A Ø | 140.0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | ANN000107 | Annunciator | FH-Annunciator Panel | Annunciator Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BCH001075 | Charger | FH-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.9 | VDC |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BCH001075 | Charger | FH-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 3.8 | amps |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BCH001075 | Charger | FH-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BCH001075 | Charger | FH-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BCH001075 | Charger | FH-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0375 | BreakerVacuum | FH-1214 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0375 | BreakerVacuum | FH-1214 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BCH001075 | Charger | FH-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0375 | BreakerVacuum | FH-1214 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | ANN000107 | Annunciator | FH-Annunciator Panel | Annunciator Patrol Inspection | General Comments | | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | MX0451 | RecloserHydraulic | 376-0650 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | MX0451 | RecloserHydraulic | 376-0650 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | MX0451 | RecloserHydraulic | 376-0650 | Recloser Hydraulic Patrol Inspection | Operations Counter | 492 | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | MX0451 | RecloserHydraulic | 376-0650 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0375 | BreakerVacuum | FH-1214 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Readings | Amps B Ø | 125.0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Readings | Amps C Ø | 130.0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | MX0451 | RecloserHydraulic | 376-0650 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | MX0451 | RecloserHydraulic | 376-0650 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | MX0451 | RecloserHydraulic | 376-0650 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | MX0451 | RecloserHydraulic | 376-0650 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 98.0 | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | MX0451 | RecloserHydraulic | 376-0650 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 22.0 | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | MX0451 | RecloserHydraulic | 376-0650 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 20.0 | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | MX0451 | RecloserHydraulic | 376-0650 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0375 | BreakerVacuum | FH-1214 | VCB Readings | Operations Counter AF | 99816 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0375 | BreakerVacuum | FH-1214 | VCB Readings | Operations Counter AL | 99816 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | MX0451 | RecloserHydraulic | 376-0650 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Readings | Fault Adjusted Amps B Phase V | 4.31 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Readings | Fault Adjusted Amps C Phase V | 4.31 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 11:56 | Distribution | Midway Quarterly Inspection | BK001413 | BreakerVacuum | 747-0503 | VCB Readings | Fault Operations B Ø | 1 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0375 | BreakerVacuum | FH-1214 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0375 | BreakerVacuum | FH-1214 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0375 | BreakerVacuum | FH-1214 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0375 | BreakerVacuum | FH-1214 | VCB Readings | Switching Operations | 1 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0375 | BreakerVacuum | FH-1214 | VCB Readings | Operations This Read Vac | 1 | |
| 2/3/2023 15:20 | Distribution | Addington Quarterly Inspection | MX0451 | RecloserHydraulic | 376-0650 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0375 | BreakerVacuum | FH-1214 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0375 | BreakerVacuum | FH-1214 | VCB Readings | General Comments | | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0375 | BreakerVacuum | FH-1214 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | YD000110 | Yard | 338-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | YD000110 | Yard | 338-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | YD000110 | Yard | 338-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | YD000110 | Yard | 338-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | YD000110 | Yard | 338-Yard | Yard Patrol Inspection | General Comments | | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | YD000110 | Yard | 338-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | YD000110 | Yard | 338-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | YD000110 | Yard | 338-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | YD000110 | Yard | 338-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0375 | BreakerVacuum | FH-1214 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0375 | BreakerVacuum | FH-1214 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0375 | BreakerVacuum | FH-1214 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0234 | BreakerVacuum | CW-1225 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0234 | BreakerVacuum | CW-1225 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | LB0375 | BreakerVacuum | FH-1214 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | YD000110 | Yard | 338-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BAT001031 | Battery | FH-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | BAT001031 | Battery | FH-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/3/2023 15:20 | Distribution | Norton East Quarterly Inspection | YD000110 | Yard | 338-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | PF000153 | PowerFuse | FH-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | PF000153 | PowerFuse | FH-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/3/2023 12:27 | Distribution | Freys Hill Quarterly Inspection | PF000153 | PowerFuse | FH-12KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0234 | BreakerVacuum | CW-1225 | VCB Readings | 9 Month Operations VCB New | 14 | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 11:47 | Distribution | Stamping Ground Quarterly Inspection | KT0023 | WithLTC | 854-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 12:30 | Distribution | Crestwood Quarterly Inspection | LB0234 | BreakerVacuum | CW-1225 | VCB Readings | 9 Month Operations | 14 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | BAT001143 | Battery | Retired Distribution | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | BAT001143 | Battery | Retired Distribution | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | BAT001143 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | BAT001143 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | BAT001143 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | BAT001143 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | BAT001143 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | BAT001143 | Battery | Retired Distribution | Battery Patrol Inspection | All Connections OK? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | BAT001143 | Battery | Retired Distribution | Battery Patrol Inspection | General Comments | | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | BAT001143 | Battery | Retired Distribution | Battery Patrol Inspection | Negative DC Ground | .4 | VDC |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | BAT001143 | Battery | Retired Distribution | Battery Patrol Inspection | Positive DC Ground | .7 | VDC |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | BAT001143 | Battery | Retired Distribution | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | BAT001143 | Battery | Retired Distribution | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | BCH000255 | Charger | Retired Distribution | Battery Charger Patrol Insp | Battery Charger Current | 1.2 | amps |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | BCH000255 | Charger | Retired Distribution | Battery Charger Patrol Insp | As Left Float Voltage | 52.4 | VDC |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | BCH000255 | Charger | Retired Distribution | Battery Charger Patrol Insp | As Found Float Voltage | 52.4 | VDC |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | BCH000255 | Charger | Retired Distribution | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | BCH000255 | Charger | Retired Distribution | Battery Charger Patrol Insp | General Comments | | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | LTCC000637 | LTCControl | 912-Offline-Distribution | LTC Control Insp | All Connections OK? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | LTCC000637 | LTCControl | 912-Offline-Distribution | LTC Control Insp | Follow-up Action Required? | n | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | LTCC000637 | LTCControl | 912-Offline-Distribution | LTC Control Insp | General Comments | | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | LTCC000637 | LTCControl | 912-Offline-Distribution | LTC Control Insp | LTC Operation Checked? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | LTCC000637 | LTCControl | 912-Offline-Distribution | LTC Control Insp | LTC Output Voltage Level | 124.2 | VAC |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | LTCC000637 | LTCControl | 912-Offline-Distribution | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | LTCC000637 | LTCControl | 912-Offline-Distribution | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | LTCC000637 | LTCControl | 912-Offline-Distribution | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | YD000043 | Yard | 538-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 30 | °C |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | LTCMechanism | FA-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | YD000043 | Yard | 538-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | YD000043 | Yard | 538-Yard | Yard Patrol Inspection | General Comments | | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | YD000043 | Yard | 538-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BAT001110 | Battery | 609-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BAT001110 | Battery | 609-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | ST000045 | Structure | 538-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | ST000045 | Structure | 538-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | ST000045 | Structure | 538-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | LTCMechanism | 722-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BAT001110 | Battery | 609-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BAT001110 | Battery | 609-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 32 | °C |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | LTCMechanism | 609-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BAT001110 | Battery | 609-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BAT001110 | Battery | 609-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | LTCMechanism | 722-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | LTCMechanism | 722-1 | LTC Counter Readings | LTC As Left Counter | 245733 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | LTCMechanism | 722-1 | LTC Counter Readings | LTC As Found Counter | 245726 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | LTCMechanism | 722-1 | LTC Mechanism Patrol Inspection | General Comments | Found LTC oil level very low. Added oil to LTC to normal levels | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | LTCMechanism | 722-1 | LTC Counter Readings | General Comments | | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | LTCMechanism | 722-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | LTCMechanism | 722-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BAT001110 | Battery | 609-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BAT001110 | Battery | 609-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | YD000043 | Yard | 538-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | LTCMechanism | 609-1 | LTC Counter Readings | General Comments | | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Readings | Maintenance Operations | 0 | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | ST000045 | Structure | 538-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 45 | °C |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Readings | Switching Operations | 1 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | LTCMechanism | 609-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Readings | Operations Counter AF | 178 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Readings | Operations Counter AL | 178 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | LTCMechanism | 609-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Readings | Operations This Read Vac | 3 | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | YD000043 | Yard | 538-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | YD000043 | Yard | 538-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | YD000043 | Yard | 538-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | ST000267 | Structure | 702-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | ST000045 | Structure | 538-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | ST000045 | Structure | 538-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LTCC000434 | LTCControl | FA-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LTCC000434 | LTCControl | FA-TRANS 1 | LTC Control Insp | General Comments | | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LTCC000434 | LTCControl | FA-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | ST000267 | Structure | 702-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | ST000267 | Structure | 702-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LTCC000435 | LTCControl | FA-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | ST000267 | Structure | 702-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | ST000267 | Structure | 702-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | LTCMechanism | FA-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LTCC000435 | LTCControl | FA-TRANS 2 | LTC Control Insp | General Comments | | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LTCC000435 | LTCControl | FA-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | ST000045 | Structure | 538-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | ST000045 | Structure | 538-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | ST000045 | Structure | 538-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | ST000045 | Structure | 538-Structure | Structure Patrol Inspection | General Comments | multiple insulators have chipped skirts | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | ST000045 | Structure | 538-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | ST000045 | Structure | 538-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000517 | BreakerSF6 | 609-608 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000517 | BreakerSF6 | 609-608 | GCB Readings | Switching Operations | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000517 | BreakerSF6 | 609-608 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000517 | BreakerSF6 | 609-608 | GCB Patrol Inspection | SF6 Pressure Indicator | good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | LTCMechanism | FA-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 231 | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | ST000267 | Structure | 702-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | ST000267 | Structure | 702-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Readings | General Comments | | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Patrol Inspection | General Comments | low side bushing discoloration | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Readings | Fault Operations C Ø | 1 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Readings | Fault Operations B Ø | 1 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | YD000264 | Yard | 869-Yard | Yard Patrol Inspection | Ambient Temp | 29 | °F |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | YD000264 | Yard | 869-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | FE000389 | Fence | 666-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | YD000264 | Yard | 869-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | FE000389 | Fence | 666-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | FE000389 | Fence | 666-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | FE000389 | Fence | 666-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | FE000389 | Fence | 666-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | FE000389 | Fence | 666-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | YD000264 | Yard | 869-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | YD000264 | Yard | 869-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | YD000264 | Yard | 869-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | LTCMechanism | 722-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | YD000264 | Yard | 869-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | YD000264 | Yard | 869-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | LTCMechanism | 722-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | LTCMechanism | 722-1 | LTC Counter Readings | LTC Operations Since Last Insp | 593 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | LTCC000934 | LTCControl | 666-1 | LTC Control Insp | All Connections OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | LTCC000934 | LTCControl | 666-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | LTCC000934 | LTCControl | 666-1 | LTC Control Insp | General Comments | | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | LTCC000934 | LTCControl | 666-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | LTCC000934 | LTCControl | 666-1 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Readings | Fault Adjusted Amps C Phase V | 4.31 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 20.00 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | LTCMechanism | 722-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | LTCMechanism | 722-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Readings | Fault Adjusted Amps B Phase V | 4.31 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | LTCMechanism | 722-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | FE000389 | Fence | 666-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | FE000389 | Fence | 666-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | LTCC000934 | LTCControl | 666-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | LTCC000934 | LTCControl | 666-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BAT001110 | Battery | 609-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BAT001110 | Battery | 609-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | LTCC000934 | LTCControl | 666-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | LTCMechanism | FA-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | LTCMechanism | FA-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Readings | Amps C Ø | 76.0 | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Readings | Amps B Ø | 96.0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Readings | Amps A Ø | 55.0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Readings | 9 Month Operations VCB New | 12 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Readings | 9 Month Operations | 15 | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3421.44 | kw |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | FE000389 | Fence | 666-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 45 | °C |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 30 | °C |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 45 | °C |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | LTCMechanism | FA-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | LTCMechanism | FA-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | LTCMechanism | FA-TRANS 1 | LTC Counter Readings | General Comments | | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | LTCMechanism | FA-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | LTCMechanism | FA-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 17202 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | LTCMechanism | FA-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 17202 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Readings | Unknown Operations | 0 | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | YD000043 | Yard | 538-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | FE000067 | Fence | 386-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Readings | Fault Operations Ground | 0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | LTCC000940 | LTCControl | 777-1 | LTC Control Insp | All Connections OK? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | LTCC000940 | LTCControl | 777-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | LTCC000940 | LTCControl | 777-1 | LTC Control Insp | General Comments | | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | LTCC000940 | LTCControl | 777-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | LTCC000940 | LTCControl | 777-1 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | LTCC000940 | LTCControl | 777-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | LTCC000940 | LTCControl | 777-1 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | LTCC000940 | LTCControl | 777-1 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | LTCC000940 | LTCControl | 777-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | FE000058 | Fence | 356-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | FE000058 | Fence | 356-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | FE000058 | Fence | 356-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | FE000058 | Fence | 356-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | FE000058 | Fence | 356-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000517 | BreakerSF6 | 609-608 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000517 | BreakerSF6 | 609-608 | GCB Patrol Inspection | Ambient Temperature | 30 | °F |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | ST000046 | Structure | 722-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | ST000046 | Structure | 722-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | ST000046 | Structure | 722-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | ST000046 | Structure | 722-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Patrol Inspection | General Comments | | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Readings | General Comments | | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Readings | Maintenance Operations | 1 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000517 | BreakerSF6 | 609-608 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000517 | BreakerSF6 | 609-608 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000517 | BreakerSF6 | 609-608 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Readings | Operations Counter AF | 236 | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | FE000058 | Fence | 356-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | FE000058 | Fence | 356-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BAT000500 | Battery | 777-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BAT000500 | Battery | 777-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BAT000500 | Battery | 777-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BAT000500 | Battery | 777-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BAT000500 | Battery | 777-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BAT000500 | Battery | 777-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BAT000500 | Battery | 777-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BAT000500 | Battery | 777-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BAT000500 | Battery | 777-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BAT000500 | Battery | 777-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BAT000500 | Battery | 777-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BAT000169 | Battery | 722-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BAT000169 | Battery | 722-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BAT000169 | Battery | 722-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.3 | VDC |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BAT000169 | Battery | 722-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.2 | VDC |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BAT000169 | Battery | 722-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BAT000169 | Battery | 722-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BAT000169 | Battery | 722-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BAT000500 | Battery | 777-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BAT000500 | Battery | 777-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 68 | °F |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BAT000500 | Battery | 777-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BAT000169 | Battery | 722-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BAT000169 | Battery | 722-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BAT000169 | Battery | 722-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BAT000169 | Battery | 722-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BAT000169 | Battery | 722-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BAT000169 | Battery | 722-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 55 | °F |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BAT000169 | Battery | 722-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | LTCC000657 | LTCControl | 722-1 | LTC Control Insp | All Connections OK? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | LTCC000657 | LTCControl | 722-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | FE000389 | Fence | 666-Fence | Fence Patrol Inspection | General Comments | | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | FE000389 | Fence | 666-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | LTCC000657 | LTCControl | 722-1 | LTC Control Insp | General Comments | | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | LTCC000657 | LTCControl | 722-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | LTCC000657 | LTCControl | 722-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | LTCC000657 | LTCControl | 722-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | LTCC000657 | LTCControl | 722-1 | LTC Control Insp | VRR Base Voltage AL | 123.7 | VAC |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | LTCC000657 | LTCControl | 722-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | FE000067 | Fence | 386-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | FE000067 | Fence | 386-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | FE000067 | Fence | 386-Fence | Fence Patrol Inspection | General Comments | | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | FE000067 | Fence | 386-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | FE000389 | Fence | 666-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | FE000389 | Fence | 666-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | FE000067 | Fence | 386-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | FE000067 | Fence | 386-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | FE000067 | Fence | 386-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | FE000067 | Fence | 386-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | FE000067 | Fence | 386-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | ST000046 | Structure | 722-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | ST000046 | Structure | 722-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | ST000046 | Structure | 722-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | ST000046 | Structure | 722-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | ST000046 | Structure | 722-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | ST000046 | Structure | 722-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | ST000046 | Structure | 722-Structure | Structure Patrol Inspection | General Comments | two arresters missing above cir 302 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | ST000046 | Structure | 722-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | ST000046 | Structure | 722-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | ST000046 | Structure | 722-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | ST000046 | Structure | 722-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | ST000046 | Structure | 722-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | ST000046 | Structure | 722-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | ST000046 | Structure | 722-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | ST000046 | Structure | 722-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | ST000046 | Structure | 722-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Readings | Unknown Operations | 0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | ST000045 | Structure | 538-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | ST000045 | Structure | 538-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | ST000045 | Structure | 538-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | ST000045 | Structure | 538-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | ST000045 | Structure | 538-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | ST000045 | Structure | 538-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | ST000045 | Structure | 538-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | ST000045 | Structure | 538-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | ST000045 | Structure | 538-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | ST000045 | Structure | 538-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Readings | 9 Month Operations | 2 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000517 | BreakerSF6 | 609-608 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000517 | BreakerSF6 | 609-608 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000517 | BreakerSF6 | 609-608 | GCB Readings | Fault Operations | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000517 | BreakerSF6 | 609-608 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000517 | BreakerSF6 | 609-608 | GCB Readings | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000517 | BreakerSF6 | 609-608 | GCB Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000517 | BreakerSF6 | 609-608 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000517 | BreakerSF6 | 609-608 | GCB Readings | General Comments | | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000517 | BreakerSF6 | 609-608 | GCB Patrol Inspection | General Comments | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000517 | BreakerSF6 | 609-608 | GCB Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000517 | BreakerSF6 | 609-608 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000517 | BreakerSF6 | 609-608 | GCB Readings | Maintenance Operations | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000517 | BreakerSF6 | 609-608 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000517 | BreakerSF6 | 609-608 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000517 | BreakerSF6 | 609-608 | GCB Readings | Operations Counter AF | 60 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000517 | BreakerSF6 | 609-608 | GCB Readings | Operations Counter AL | 60 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000517 | BreakerSF6 | 609-608 | GCB Readings | Operations This Read SF6 | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000517 | BreakerSF6 | 609-608 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | FE000058 | Fence | 356-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | FE000058 | Fence | 356-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | FE000058 | Fence | 356-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | FE000058 | Fence | 356-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | FE000058 | Fence | 356-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | FE000058 | Fence | 356-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Readings | Operations Counter AL | 236 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Readings | Operations This Read Vac | 1 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Readings | Switching Operations | 0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Readings | Unknown Operations | 0 | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | FE000067 | Fence | 386-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | FE000067 | Fence | 386-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | FE000067 | Fence | 386-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | FE000067 | Fence | 386-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | FE000067 | Fence | 386-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | FE000067 | Fence | 386-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | FE000058 | Fence | 356-Fence | Fence Patrol Inspection | General Comments | | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | FE000058 | Fence | 356-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | FE000058 | Fence | 356-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | ST000063 | Structure | 356-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | ST000063 | Structure | 356-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | ST000063 | Structure | 356-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | ST000063 | Structure | 356-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | ST000063 | Structure | 356-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | ST000063 | Structure | 356-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | ST000063 | Structure | 356-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | FE000389 | Fence | 666-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Readings | Amps C Ø | 19.0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | FE000389 | Fence | 666-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Readings | Amps B Ø | 14.0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | YD000264 | Yard | 869-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | YD000264 | Yard | 869-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | YD000264 | Yard | 869-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | YD000264 | Yard | 869-Yard | Yard Patrol Inspection | General Comments | | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | YD000264 | Yard | 869-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | YD000264 | Yard | 869-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Readings | Amps A Ø | 17.0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0127 | BreakerVacuum | 869-0809 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | ST000046 | Structure | 722-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | ST000046 | Structure | 722-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | LTCMechanism | 777-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | LTCMechanism | 777-1 | LTC Counter Readings | General Comments | | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | LTCMechanism | 777-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | LTCMechanism | 777-1 | LTC Counter Readings | LTC As Found Counter | 111968 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | LTCMechanism | 777-1 | LTC Counter Readings | LTC As Left Counter | 111968 | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | FE000046 | Fence | 538-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | n | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | FE000046 | Fence | 538-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | FE000046 | Fence | 538-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | LTCMechanism | 777-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | LTCMechanism | 777-1 | LTC Counter Readings | LTC Current Tap Position | 2R | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | YD000067 | Yard | 386-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | YD000067 | Yard | 386-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Readings | Totalizer Meter Reading | .6090 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 10.00 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | YD000067 | Yard | 386-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | LTCMechanism | 777-1 | LTC Counter Readings | LTC Max Tap Position | 10R | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | LTCMechanism | 777-1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | LTCMechanism | 777-1 | LTC Counter Readings | LTC Operations Since Last Insp | 501 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | LTCMechanism | 777-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | LTCMechanism | 777-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | LTCMechanism | 777-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BCH001069 | Charger | 609-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BCH001069 | Charger | 609-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BCH001069 | Charger | 609-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BAT001110 | Battery | 609-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BAT001110 | Battery | 609-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 68 | °F |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BAT001110 | Battery | 609-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BAT001110 | Battery | 609-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | YD000067 | Yard | 386-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BAT001110 | Battery | 609-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | YD000067 | Yard | 386-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | YD000067 | Yard | 386-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | YD000067 | Yard | 386-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | YD000067 | Yard | 386-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | YD000067 | Yard | 386-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | YD000067 | Yard | 386-Yard | Yard Patrol Inspection | General Comments | | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | YD000067 | Yard | 386-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | YD000067 | Yard | 386-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | YD000067 | Yard | 386-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | YD000041 | Yard | 722-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | YD000041 | Yard | 722-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | YD000041 | Yard | 722-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0131 | CircuitSwitcher | 666-2 Trans-Rupter | Circuit Switcher Patrol Inspection | Ambient Temperature | 28 | °F |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0131 | CircuitSwitcher | 666-2 Trans-Rupter | Circuit Switcher Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | LTCMechanism | FA-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BCH001069 | Charger | 609-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BCH001069 | Charger | 609-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.3 | amps |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Readings | Maintenance Operations | 1 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 44.40 | kw |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | LTCMechanism | FA-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Readings | Fault Operations Ground | 0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | FE000046 | Fence | 538-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Readings | General Comments | | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Readings | LTC Totalizer Reading | 5846.40 | kw |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | FE000046 | Fence | 538-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Readings | Oil Temp Max | 75 | °C |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Readings | Oil Temp Present | 11 | °C |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | FE000046 | Fence | 538-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BCH001069 | Charger | 609-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Readings | Oil Temp Max | 30 | °C |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Readings | Oil Temp Present | 18 | °C |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Patrol Inspection | General Comments | Bottom insulator on bus side disconnect has a chipped skirt. | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Readings | General Comments | | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | LTCMechanism | 777-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCM000053 | LTCMechanism | 609-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCM000053 | LTCMechanism | 609-2 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCM000053 | LTCMechanism | 609-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCM000053 | LTCMechanism | 609-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | YD000058 | Yard | 356-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | YD000058 | Yard | 356-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | YD000041 | Yard | 722-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | YD000041 | Yard | 722-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | YD000041 | Yard | 722-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Readings | Follow-up Action Required? | n | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | YD000058 | Yard | 356-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | YD000058 | Yard | 356-Yard | Yard Patrol Inspection | General Comments | | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | YD000058 | Yard | 356-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | YD000058 | Yard | 356-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | YD000058 | Yard | 356-Yard | Yard Patrol Inspection | Ambient Temp | 37 | °F |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | YD000058 | Yard | 356-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | YD000058 | Yard | 356-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | YD000058 | Yard | 356-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1000 | psi |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | YD000058 | Yard | 356-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | YD000058 | Yard | 356-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | YD000058 | Yard | 356-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | YD000058 | Yard | 356-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0131 | CircuitSwitcher | 666-2 Trans-Rupter | Circuit Switcher Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0131 | CircuitSwitcher | 666-2 Trans-Rupter | Circuit Switcher Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0131 | CircuitSwitcher | 666-2 Trans-Rupter | Circuit Switcher Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0131 | CircuitSwitcher | 666-2 Trans-Rupter | Circuit Switcher Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0131 | CircuitSwitcher | 666-2 Trans-Rupter | Circuit Switcher Patrol Inspection | General Comments | | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0131 | CircuitSwitcher | 666-2 Trans-Rupter | Circuit Switcher Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0131 | CircuitSwitcher | 666-2 Trans-Rupter | Circuit Switcher Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0131 | CircuitSwitcher | 666-2 Trans-Rupter | Circuit Switcher Patrol Inspection | SF6 Bushing Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0131 | CircuitSwitcher | 666-2 Trans-Rupter | Circuit Switcher Patrol Inspection | SF6 Indicator Zone | OK | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0131 | CircuitSwitcher | 666-2 Trans-Rupter | Circuit Switcher Patrol Inspection | Trip-energy Supply Verified | y | LED lights? |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | YD000041 | Yard | 722-Yard | Yard Patrol Inspection | General Comments | | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | YD000041 | Yard | 722-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | YD000041 | Yard | 722-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | YD000041 | Yard | 722-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | YD000041 | Yard | 722-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 25 | °C |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 7 | °C |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 35 | °C |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 15 | °C |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 45 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 30 | °C |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCM000053 | LTCMechanism | 609-2 | LTC Counter Readings | LTC As Left Counter | 146357 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCM000053 | LTCMechanism | 609-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCM000053 | LTCMechanism | 609-2 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCM000053 | LTCMechanism | 609-2 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCM000053 | LTCMechanism | 609-2 | LTC Counter Readings | LTC Min Tap Position | 16L | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCM000053 | LTCMechanism | 609-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCM000053 | LTCMechanism | 609-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 39 | °C |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCM000053 | LTCMechanism | 609-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 15 | °C |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCM000053 | LTCMechanism | 609-2 | LTC Counter Readings | LTC Operations Since Last Insp | 3138 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | WithLTC | FA-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Readings | Amps A Ø | 130.0 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Readings | Amps B Ø | 170.0 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Readings | Amps C Ø | 130.0 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Readings | Oil Temp Max | 30 | °C |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BCH001515 | Charger | 722-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BCH001515 | Charger | 722-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.3 | amps |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BCH001515 | Charger | 722-Battery Charger | Battery Charger Patrol Insp | Battery Charger Alarms Present | None | note in comments if present |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .7128 | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Readings | Winding Temp Max | 22 | °C |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Readings | Winding Temp Present | 22 | °C |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Readings | Amps B Ø | 195.0 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Readings | Amps C Ø | 240.0 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | FE000043 | Fence | 722-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | FE000043 | Fence | 722-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | FE000043 | Fence | 722-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BCH001515 | Charger | 722-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Readings | Fault Operations Ground | 0 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | YD000260 | Yard | 702-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | YD000260 | Yard | 702-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | YD000260 | Yard | 702-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | YD000260 | Yard | 702-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | YD000260 | Yard | 702-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | YD000260 | Yard | 702-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | YD000260 | Yard | 702-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | YD000260 | Yard | 702-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | YD000260 | Yard | 702-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | YD000260 | Yard | 702-Yard | Yard Patrol Inspection | Ambient Temp | 33 | °F |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | YD000043 | Yard | 538-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | YD000043 | Yard | 538-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | YD000043 | Yard | 538-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | YD000043 | Yard | 538-Yard | Yard Patrol Inspection | Ambient Temp | 40 | °F |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Readings | Follow-up Action Required? | n | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | ST000267 | Structure | 702-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | ST000267 | Structure | 702-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | ST000267 | Structure | 702-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | ST000267 | Structure | 702-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | ST000267 | Structure | 702-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | ST000267 | Structure | 702-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | ST000267 | Structure | 702-Structure | Structure Patrol Inspection | General Comments | There are no spare fuse barrels. | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | ST000267 | Structure | 702-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | ST000267 | Structure | 702-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | ST000267 | Structure | 702-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | LTCMechanism | 609-1 | LTC Counter Readings | LTC As Found Counter | 70192 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | LTCMechanism | 609-1 | LTC Counter Readings | LTC As Left Counter | 70192 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | LTCMechanism | 609-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | LTCMechanism | 609-1 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | LTCMechanism | 609-1 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | ST000267 | Structure | 702-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | ST000267 | Structure | 702-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | ST000267 | Structure | 702-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | ST000267 | Structure | 702-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | ST000267 | Structure | 702-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | LTCMechanism | FA-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | LTCMechanism | 609-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | LTCMechanism | 609-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | LTCMechanism | 609-1 | LTC Counter Readings | LTC Operations Since Last Insp | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | LTCMechanism | 609-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | LTCMechanism | 609-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | LTCMechanism | 609-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | LTCMechanism | 609-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Readings | Switching Operations | 0 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Readings | Operations This Read Vac | 1 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Readings | Operations Counter AL | 185 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Readings | Operations Counter AF | 185 | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | ST000267 | Structure | 702-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | YD000260 | Yard | 702-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | YD000260 | Yard | 702-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | YD000260 | Yard | 702-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | YD000260 | Yard | 702-Yard | Yard Patrol Inspection | General Comments | ok | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | FE000043 | Fence | 722-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | FE000043 | Fence | 722-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Readings | 9 Month Operations | 293 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Readings | 9 Month Operations VCB New | 293 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | FE000043 | Fence | 722-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | FE000043 | Fence | 722-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Readings | Amps A Ø | 260.0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BCH001515 | Charger | 722-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 3.400 | millivolts |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BCH001515 | Charger | 722-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | KT0013 | NonLTC | 538-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | LTCMechanism | FA-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | LTCMechanism | FA-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Readings | Maintenance Operations | 0 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Readings | Operations Counter AF | 293 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Readings | Operations Counter AL | 293 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Readings | Operations This Read Vac | 0 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Readings | Switching Operations | 0 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | ST000063 | Structure | 356-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | ST000063 | Structure | 356-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | LTCMechanism | FA-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | LTCMechanism | FA-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 211 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | LTCMechanism | FA-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 16L | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | LTCMechanism | FA-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 12L | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | ST000063 | Structure | 356-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | ST000063 | Structure | 356-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | ST000063 | Structure | 356-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | FE000389 | Fence | 666-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | FE000043 | Fence | 722-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | FE000043 | Fence | 722-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | YD000041 | Yard | 722-Yard | Yard Patrol Inspection | Ambient Temp | 34 | °F |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | LTCMechanism | FA-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 14L | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | LTCMechanism | FA-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | LTCMechanism | FA-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 17112 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | CH000412 | ControlHouse | 609-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BCH001069 | Charger | 609-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BCH001069 | Charger | 609-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | FE000046 | Fence | 538-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | FE000046 | Fence | 538-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | FE000046 | Fence | 538-Fence | Fence Patrol Inspection | General Comments | wire and fabric rusty in ultiple places aroud the fence | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | FE000046 | Fence | 538-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | FE000046 | Fence | 538-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | FE000046 | Fence | 538-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | FE000046 | Fence | 538-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | FE000046 | Fence | 538-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | FE000046 | Fence | 538-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | FE000046 | Fence | 538-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Readings | General Comments | | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | LTCMechanism | FA-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 17112 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0071 | WithLTC | FA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | LTCMechanism | FA-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | LTCMechanism | FA-TRANS 2 | LTC Counter Readings | General Comments | | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | LTCMechanism | FA-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | LTCMechanism | FA-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Patrol Inspection | General Comments | | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Readings | General Comments | | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | FE000043 | Fence | 722-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | FE000043 | Fence | 722-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | FE000043 | Fence | 722-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | FE000043 | Fence | 722-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BCH001515 | Charger | 722-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BCH001515 | Charger | 722-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | FE000043 | Fence | 722-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | FE000043 | Fence | 722-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Readings | 9 Month Operations | 7 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0122 | BreakerVacuum | 712-0825 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | FE000043 | Fence | 722-Fence | Fence Patrol Inspection | General Comments | | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | ST000063 | Structure | 356-Structure | Structure Patrol Inspection | General Comments | | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | ST000063 | Structure | 356-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | ST000063 | Structure | 356-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | ST000063 | Structure | 356-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | ST000063 | Structure | 356-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | ST000063 | Structure | 356-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | KB0061 | BreakerVacuum | 777-0431 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | CH000412 | ControlHouse | 609-Control House | Control House Patrol  Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | CH000412 | ControlHouse | 609-Control House | Control House Patrol  Inspection | Acceptable Building Appearnce? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | CH000412 | ControlHouse | 609-Control House | Control House Patrol  Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | CH000412 | ControlHouse | 609-Control House | Control House Patrol  Inspection | Control House Lighting OK? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | CH000412 | ControlHouse | 609-Control House | Control House Patrol  Inspection | Controlhouse Grounds in Place? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | CH000412 | ControlHouse | 609-Control House | Control House Patrol  Inspection | Door Alarms OK? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | CH000412 | ControlHouse | 609-Control House | Control House Patrol  Inspection | Doors and Locks Secure? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Readings | General Comments | | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Patrol Inspection | General Comments | | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK000797 | BreakerVacuum | 722-0300 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LT0072 | LTCMechanism | FA-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | CH000412 | ControlHouse | 609-Control House | Control House Patrol Inspection | Evidence of Insects | Yes_needs_sprayed | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | CH000412 | ControlHouse | 609-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | CH000412 | ControlHouse | 609-Control House | Control House Patrol Inspection | Filters Condition OK? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | CH000412 | ControlHouse | 609-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | CH000412 | ControlHouse | 609-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | WithLTC | 722-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | CH000412 | ControlHouse | 609-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | CH000412 | ControlHouse | 609-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | CH000412 | ControlHouse | 609-Control House | Control House Patrol Inspection | General Comments | | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | CH000412 | ControlHouse | 609-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | CH000412 | ControlHouse | 609-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | CH000412 | ControlHouse | 609-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | CH000412 | ControlHouse | 609-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .0370 | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | O0212 | NonLTC | 356-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | CH000412 | ControlHouse | 609-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | FE000232 | Fence | 457-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | FE000232 | Fence | 457-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | FE000232 | Fence | 457-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | FE000232 | Fence | 457-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | FE000232 | Fence | 457-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | FE000232 | Fence | 457-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | FE000232 | Fence | 457-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | FE000232 | Fence | 457-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | FE000232 | Fence | 457-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | FE000232 | Fence | 457-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | FE000232 | Fence | 457-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | FE000232 | Fence | 457-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | FE000232 | Fence | 457-Fence | Fence Patrol Inspection | General Comments | | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | FE000232 | Fence | 457-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | FE000232 | Fence | 457-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | YD000231 | Yard | 457-Yard | Yard Patrol Inspection | Ambient Temp | 34 | °F |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | YD000231 | Yard | 457-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | YD000231 | Yard | 457-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | YD000231 | Yard | 457-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | YD000231 | Yard | 457-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | YD000231 | Yard | 457-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | YD000231 | Yard | 457-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | YD000231 | Yard | 457-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | YD000231 | Yard | 457-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | YD000231 | Yard | 457-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | YD000231 | Yard | 457-Yard | Yard Patrol Inspection | General Comments | | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | YD000231 | Yard | 457-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | YD000231 | Yard | 457-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | ST000238 | Structure | 457-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | ST000238 | Structure | 457-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | ST000238 | Structure | 457-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | ST000238 | Structure | 457-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | ST000238 | Structure | 457-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | ST000238 | Structure | 457-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | ST000238 | Structure | 457-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BCH001186 | Charger | 666-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BCH001186 | Charger | 666-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BCH001186 | Charger | 666-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BCH001186 | Charger | 666-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.5 | amps |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BCH001186 | Charger | 666-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BCH001186 | Charger | 666-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BCH001186 | Charger | 666-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BCH001186 | Charger | 666-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Readings | 9 Month Operations | 0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Readings | Amps A Ø | 320.0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Readings | Amps B Ø | 340.0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Readings | Amps C Ø | 340.0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Readings | General Comments | | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Readings | LTC Totalizer Reading | 9725.76 | kw |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | FE000232 | Fence | 457-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Readings | Unknown Operations | 0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | LTCM000029 | LTCMechanism | 869-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | LTCM000029 | LTCMechanism | 869-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Readings | General Comments | | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Readings | Operations Counter AF | 35 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Readings | Operations Counter AL | 35 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Readings | Unknown Operations | 0 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Readings | Switching Operations | 0 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Readings | Operations This Read Vac | 2 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Readings | Operations Counter AL | 214 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Readings | Operations Counter AF | 214 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Readings | Maintenance Operations | 2 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Readings | General Comments | Trip Checks | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Patrol Inspection | General Comments | | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Readings | Follow-up Action Required? | n | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Readings | Fault Operations Ground | 0 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | KX0080 | RecloserElectronic | 702-1451 | Recloser Electronic Patrol Inspection | Amps A Ø | 87.0 | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | KX0080 | RecloserElectronic | 702-1451 | Recloser Electronic Patrol Inspection | Amps B Ø | 61.0 | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | KX0080 | RecloserElectronic | 702-1451 | Recloser Electronic Patrol Inspection | Amps C Ø | 53.0 | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | KX0080 | RecloserElectronic | 702-1451 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | KX0080 | RecloserElectronic | 702-1451 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | ST000238 | Structure | 457-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | ST000238 | Structure | 457-Structure | Structure Patrol Inspection | General Comments | Station needs additional wildlife protection. | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | ST000238 | Structure | 457-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | ST000238 | Structure | 457-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | ST000238 | Structure | 457-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | ST000238 | Structure | 457-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | ST000238 | Structure | 457-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | ST000238 | Structure | 457-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | ST000238 | Structure | 457-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | ST000238 | Structure | 457-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | ST000238 | Structure | 457-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | ST000238 | Structure | 457-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | ST000238 | Structure | 457-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | ST000238 | Structure | 457-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Readings | Totalizer Meter Reading | .6754 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Readings | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Patrol Inspection | General Comments | | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Readings | General Comments | | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Readings | Maintenance Operations | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | TX000045 | WithLTC | 869-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Readings | Operations Counter AF | 176 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Readings | Operations Counter AL | 176 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Readings | Switching Operations | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000506 | BreakerVacuum | 609-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Readings | Maintenance Operations | 0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Readings | General Comments | | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Patrol Inspection | General Comments | | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Readings | Follow-up Action Required? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Readings | Fault Operations Ground | 0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Readings | Amps C Ø | 80.0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Readings | Amps B Ø | 68.0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Readings | Amps A Ø | 89.0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Readings | 9 Month Operations | 4 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Readings | Amps A Ø | 55.0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Readings | Amps B Ø | 56.0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Readings | Operations Counter AF | 114 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Readings | Operations Counter AL | 114 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Readings | Unknown Operations | 0 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Patrol Inspection | General Comments | | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Readings | General Comments | | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Readings | Maintenance Operations | 0 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Readings | Operations Counter AF | 142 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Readings | Operations Counter AL | 142 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Readings | Operations This Read Vac | 0 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Readings | Switching Operations | 0 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Readings | 9 Month Operations | 10 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 10967.04 | kw |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Readings | Switching Operations | 0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Readings | Unknown Operations | 0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Readings | Switching Operations | 0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Readings | Operations This Read Vac | 0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Readings | Operations Counter AL | 221 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Readings | Operations Counter AF | 221 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001092 | BreakerVacuum | 722-0303 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Readings | General Comments | | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Readings | Amps C Ø | 162.0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Readings | Amps B Ø | 180.0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Readings | Amps A Ø | 130.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Readings | 9 Month Operations | 3 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Patrol Inspection | General Comments | | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Readings | General Comments | | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Readings | Maintenance Operations | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Readings | Operations Counter AF | 205 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Readings | Operations Counter AL | 205 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Readings | Operations This Read Vac | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Readings | Switching Operations | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Readings | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Readings | Amps C Ø | 54.0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | LTCC000982 | LTCControl | 653-1 | LTC Control Insp | LTC Output Voltage Level | 124.7 | VAC |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | LTCC000982 | LTCControl | 653-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | LTCC000982 | LTCControl | 653-1 | LTC Control Insp | General Comments | | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | LTCC000982 | LTCControl | 653-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | LTCC000982 | LTCControl | 653-1 | LTC Control Insp | All Connections OK? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Readings | Fault Operations Ground | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Readings | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Readings | Unknown Operations | 0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Readings | Switching Operations | 1 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Readings | Operations This Read Vac | 1 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Readings | Operations Counter AL | 216 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Readings | Operations Counter AF | 216 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Readings | Maintenance Operations | 0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Readings | General Comments | | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Patrol Inspection | General Comments | | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Readings | Follow-up Action Required? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Readings | Fault Operations Ground | 0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001091 | BreakerVacuum | 722-0301 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Readings | 9 Month Operations | 3 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Readings | Fault Operations Ground | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Readings | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Patrol Inspection | General Comments | | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Readings | General Comments | | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Readings | Maintenance Operations | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Readings | Operations Counter AF | 60 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Readings | Operations Counter AL | 60 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Readings | 9 Month Operations | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Readings | Operations This Read Vac | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Readings | Switching Operations | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Readings | Amps A Ø | 260.0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Readings | Amps B Ø | 285.0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Readings | Amps C Ø | 270.0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Patrol Inspection | General Comments | | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Readings | Totalizer Meter Reading | .6420 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Readings | 9 Month Operations | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Readings | Amps A Ø | 220.0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Readings | Amps B Ø | 230.0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Readings | Amps C Ø | 225.0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Readings | Amps C Ø | 73.0 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Readings | Amps B Ø | 61.0 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Readings | Amps A Ø | 65.0 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Readings | Fault Operations Ground | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Readings | Follow-up Action Required? | n | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Readings | Amps B Ø | 0.0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Readings | Amps C Ø | 0.0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Patrol Inspection | Spring Compression Ind. | springdischarged | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Readings | Operations Counter AL | 13 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Readings | Operations Counter AF | 13 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Readings | General Comments | DNO | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Readings | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCC000165 | LTCControl | 609-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCC000165 | LTCControl | 609-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCC000165 | LTCControl | 609-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCC000165 | LTCControl | 609-1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCC000165 | LTCControl | 609-1 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCC000165 | LTCControl | 609-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCC000165 | LTCControl | 609-1 | LTC Control Insp | General Comments | | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCC000165 | LTCControl | 609-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCC000165 | LTCControl | 609-1 | LTC Control Insp | All Connections OK? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Readings | Fault Operations Ground | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Readings | Follow-up Action Required? | n | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Patrol Inspection | General Comments | | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Readings | General Comments | | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Readings | Maintenance Operations | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Readings | Operations Counter AF | 243 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Readings | Operations Counter AL | 243 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Readings | Operations This Read Vac | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Readings | Maintenance Operations | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Readings | Operations Counter AF | 301 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Readings | Operations Counter AL | 301 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Readings | Operations This Read Vac | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Readings | Switching Operations | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0382 | BreakerVacuum | 666-0470 | VCB Readings | Unknown Operations | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Readings | 9 Month Operations | 8 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002118 | BreakerVacuum | FA-1150 | VCB Readings | Amps A Ø | 0.0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KB0087 | BreakerVacuum | 666-0472 | VCB Readings | Switching Operations | 0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | LTCM000029 | LTCMechanism | 869-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Readings | 9 Month Operations | 1 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002117 | BreakerVacuum | FA-1149 | VCB Readings | Unknown Operations | 0 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Readings | Unknown Operations | 0 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Readings | Switching Operations | 0 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Readings | Operations This Read Vac | 1 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Readings | Operations Counter AL | 203 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Readings | Operations Counter AF | 203 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Readings | Maintenance Operations | 1 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Readings | Amps A Ø | 180.0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Readings | Amps B Ø | 120.0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Readings | Amps C Ø | 190.0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0423 | BreakerVacuum | 609-0401 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .2340 | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Readings | Oil Temp Present | 28 | °C |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Readings | Oil Temp Max | 39 | °C |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 561.60 | kw |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Readings | General Comments | | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | KX0080 | RecloserElectronic | 702-1451 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | KX0080 | RecloserElectronic | 702-1451 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | KX0080 | RecloserElectronic | 702-1451 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | KX0080 | RecloserElectronic | 702-1451 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | KX0080 | RecloserElectronic | 702-1451 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | KX0080 | RecloserElectronic | 702-1451 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | KX0080 | RecloserElectronic | 702-1451 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | KX0080 | RecloserElectronic | 702-1451 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | KX0080 | RecloserElectronic | 702-1451 | Recloser Electronic Patrol Inspection | General Comments | 1 op - Trip check | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | KX0080 | RecloserElectronic | 702-1451 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | KX0080 | RecloserElectronic | 702-1451 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | KX0080 | RecloserElectronic | 702-1451 | Recloser Electronic Patrol Inspection | Operations Counter | 320 | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | KX0080 | RecloserElectronic | 702-1451 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | KX0080 | RecloserElectronic | 702-1451 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Readings | Amps C Ø | 62.0 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Readings | Amps B Ø | 65.0 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Readings | Amps A Ø | 95.0 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | LTCM000029 | LTCMechanism | 869-1 | LTC Counter Readings | General Comments | | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | LTCM000029 | LTCMechanism | 869-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | LTCM000029 | LTCMechanism | 869-1 | LTC Counter Readings | LTC As Found Counter | 21320 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | LTCM000029 | LTCMechanism | 869-1 | LTC Counter Readings | LTC As Left Counter | 21331 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | LTCM000029 | LTCMechanism | 869-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | LTCM000029 | LTCMechanism | 869-1 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | LTCM000029 | LTCMechanism | 869-1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | LTCM000029 | LTCMechanism | 869-1 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000897 | BreakerVacuum | 653-0815 | VCB Readings | 9 Month Operations | 5 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | LTCM000029 | LTCMechanism | 869-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 10 | °C |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | LTCM000029 | LTCMechanism | 869-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 30 | °C |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | LTCM000029 | LTCMechanism | 869-1 | LTC Counter Readings | LTC Operations Since Last Insp | 336 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | LTCM000029 | LTCMechanism | 869-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | LTCM000029 | LTCMechanism | 869-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | LTCM000029 | LTCMechanism | 869-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Patrol Inspection | General Comments | added 1 pound of nitrogen | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Readings | LTC Totalizer Reading | 4622.40 | kw |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Readings | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Readings | Oil Temp Max | 54 | °C |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Readings | Oil Temp Present | 23 | °C |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.2288 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Readings | LTC Totalizer Reading | 11796.48 | kw |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Readings | General Comments | | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | M0068 | WithLTC | 609-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | C0515 | NonLTC | 386-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Readings | General Comments | TRIP cHECK | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Patrol Inspection | General Comments | | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Readings | Follow-up Action Required? | n | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Readings | Fault Operations Ground | 0 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | PF000128 | PowerFuse | FA-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | PF000128 | PowerFuse | FA-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BK000896 | BreakerVacuum | 653-0816 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | PF000129 | PowerFuse | FA-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | PF000129 | PowerFuse | FA-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | M0071 | WithLTC | 722-1 | LTC Transformer Readings | General Comments | | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BCH001096 | Charger | 869-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BCH001096 | Charger | 869-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | YD000224 | Yard | 712-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | YD000224 | Yard | 712-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | YD000224 | Yard | 712-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | ST000230 | Structure | 712-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | ST000230 | Structure | 712-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | ST000230 | Structure | 712-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | ST000230 | Structure | 712-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | ST000230 | Structure | 712-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | ST000230 | Structure | 712-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | ST000230 | Structure | 712-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | ST000230 | Structure | 712-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | ST000230 | Structure | 712-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | n | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | ST000230 | Structure | 712-Structure | Structure Patrol Inspection | General Comments | Whole station needs wildlife protection.Xfmr fuse barrels are starting to fray and warp. | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | LTCMechanism | 722-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | LTCMechanism | 722-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | LTCMechanism | 722-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BCH001096 | Charger | 869-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BCH001096 | Charger | 869-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.8 | amps |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BCH001096 | Charger | 869-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BCH001096 | Charger | 869-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BCH001096 | Charger | 869-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.600 | millivolts |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | LTCMechanism | 722-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | ST000230 | Structure | 712-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | ST000230 | Structure | 712-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | ST000230 | Structure | 712-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | ST000230 | Structure | 712-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | ST000230 | Structure | 712-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | ST000230 | Structure | 712-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | ST000230 | Structure | 712-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | ST000230 | Structure | 712-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | ST000230 | Structure | 712-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | ST000230 | Structure | 712-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | ST000230 | Structure | 712-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | ST000230 | Structure | 712-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | ST000230 | Structure | 712-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | PF000131 | PowerFuse | FA-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | PF000131 | PowerFuse | FA-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Readings | 9 Month Operations | 12 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 12 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Readings | Unknown Operations | 0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | LTCMechanism | 722-2 | LTC Counter Readings | LTC Max Tap Position | 16R | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | LTCMechanism | 722-2 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | LTCMechanism | 722-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | LTCMechanism | 722-2 | LTC Counter Readings | LTC Operations Since Last Insp | 184 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BAT001661 | Battery | 869-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BAT001661 | Battery | 869-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BAT001661 | Battery | 869-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.7 | VDC |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BAT001661 | Battery | 869-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.8 | VDC |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BAT001661 | Battery | 869-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BAT001661 | Battery | 869-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BAT001661 | Battery | 869-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BAT001661 | Battery | 869-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BAT001661 | Battery | 869-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BAT001661 | Battery | 869-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BAT001661 | Battery | 869-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 55 | °F |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BAT001661 | Battery | 869-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | FE000224 | Fence | 712-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | FE000224 | Fence | 712-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | FE000224 | Fence | 712-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | FE000224 | Fence | 712-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | FE000224 | Fence | 712-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | FE000224 | Fence | 712-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | FE000224 | Fence | 712-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | FE000224 | Fence | 712-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | FE000224 | Fence | 712-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | FE000224 | Fence | 712-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | FE000224 | Fence | 712-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | FE000224 | Fence | 712-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | FE000224 | Fence | 712-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | FE000224 | Fence | 712-Fence | Fence Patrol Inspection | General Comments | | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | FE000224 | Fence | 712-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | FE000224 | Fence | 712-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | YD000224 | Yard | 712-Yard | Yard Patrol Inspection | Ambient Temp | 31 | °F |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | YD000224 | Yard | 712-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | YD000224 | Yard | 712-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | YD000224 | Yard | 712-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | YD000224 | Yard | 712-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | YD000224 | Yard | 712-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | YD000224 | Yard | 712-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | YD000224 | Yard | 712-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | YD000224 | Yard | 712-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | YD000224 | Yard | 712-Yard | Yard Patrol Inspection | General Comments | The back right corner of station is starting to develop small washouts under fence. | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BCH001096 | Charger | 869-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Readings | Amps C Ø | 297.0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Readings | General Comments | | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Readings | Totalizer Meter Reading | .9966 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Readings | Oil Temp Present | 26 | °C |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Readings | Oil Temp Max | 26 | °C |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Readings | Operations Counter AF | 17 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Readings | Amps A Ø | 344.0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Readings | Switching Operations | 0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Readings | Operations This Read Vac | 1 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Readings | Operations Counter AL | 154 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Readings | Operations Counter AF | 154 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Readings | Maintenance Operations | 1 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Readings | Amps B Ø | 295.0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Readings | Amps C Ø | 295.0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Readings | General Comments | | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Patrol Inspection | General Comments | | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 600 | psi |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Readings | LTC Totalizer Reading | 7437.12 | kw |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Readings | General Comments | | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Readings | General Comments | | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Readings | LTC Totalizer Reading | 16951.68 | kw |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Readings | Winding Temp Max | 45 | °C |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Readings | Totalizer Meter Reading | .4880 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3931.20 | kw |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -1.0 | psi |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Patrol Inspection | General Comments | Needs wildlife protection. | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 15240 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Readings | General Comments | | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | CH000521 | ControlHouse | 722-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | CH000521 | ControlHouse | 722-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | CH000521 | ControlHouse | 722-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | CH000521 | ControlHouse | 722-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | CH000521 | ControlHouse | 722-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | CH000521 | ControlHouse | 722-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | CH000521 | ControlHouse | 722-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Readings | General Comments | | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.6380 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Readings | LTC Totalizer Reading | 19111.68 | kw |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | CH000521 | ControlHouse | 722-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | PF000130 | PowerFuse | FA-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | PF000130 | PowerFuse | FA-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | CH000521 | ControlHouse | 722-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | CH000521 | ControlHouse | 722-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | CH000521 | ControlHouse | 722-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | CH000521 | ControlHouse | 722-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCM000053 | LTCMechanism | 609-2 | LTC Counter Readings | LTC As Found Counter | 146357 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCM000053 | LTCMechanism | 609-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCM000053 | LTCMechanism | 609-2 | LTC Counter Readings | General Comments | | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCM000053 | LTCMechanism | 609-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCM000053 | LTCMechanism | 609-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Readings | Winding Temp Present | 23 | °C |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Readings | Amps C Ø | 180.0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Readings | Amps B Ø | 195.0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Readings | Amps A Ø | 180.0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Readings | 9 Month Operations | 4 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Readings | Oil Temp Present | 22 | °C |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Readings | Oil Temp Max | 44 | °C |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Readings | Totalizer Meter Reading | 2.6544 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | LTCMechanism | 722-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | LTCMechanism | 722-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | LTCMechanism | 722-2 | LTC Counter Readings | General Comments | | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | LTCMechanism | 722-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | LTCMechanism | 722-2 | LTC Counter Readings | LTC As Found Counter | 38316 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | LTCMechanism | 722-2 | LTC Counter Readings | LTC As Left Counter | 38321 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | LTCMechanism | 722-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | S0048 | LTCMechanism | 722-2 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | CH000521 | ControlHouse | 722-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | CH000521 | ControlHouse | 722-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Readings | Totalizer Meter Reading | 2.3544 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | WithLTC | 666-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Readings | Unknown Operations | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Readings | Switching Operations | 1 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Readings | Operations This Read Vac | 1 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | W0291 | NonLTC | 712-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | S0004 | WithLTC | 777-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Readings | Operations Counter AL | 494 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Readings | Operations Counter AF | 494 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Readings | Maintenance Operations | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Readings | General Comments | | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Patrol Inspection | General Comments | | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Readings | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Readings | Fault Operations Ground | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BB0436 | BreakerVacuum | 609-0402 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Readings | Amps C Ø | 140.0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Readings | Amps B Ø | 130.0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Readings | Amps A Ø | 0.0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Readings | Amps B Ø | 0.0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Readings | Amps A Ø | 145.0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Readings | Amps C Ø | 0.0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Readings | 9 Month Operations | 0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Readings | Fault Operations Ground | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Readings | Follow-up Action Required? | n | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Readings | Amps A Ø | 91.0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Readings | Amps B Ø | 145.0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Readings | Amps C Ø | 105.0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | LTCC000986 | LTCControl | 386-1 A | LTC Control Insp | LTC Output Voltage Level | 125.4 | VAC |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | LTCC000986 | LTCControl | 386-1 A | LTC Control Insp | LTC Operation Checked? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | LTCC000986 | LTCControl | 386-1 A | LTC Control Insp | General Comments | | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | LTCC000986 | LTCControl | 386-1 A | LTC Control Insp | Follow-up Action Required? | n | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | LTCC000986 | LTCControl | 386-1 A | LTC Control Insp | All Connections OK? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Readings | 9 Month Operations | 106 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Readings | 9 Month Operations VCB New | 106 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Readings | Amps A Ø | 209.0 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Readings | 9 Month Operations | 0 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Readings | 9 Month Operations | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Readings | Amps A Ø | 180.0 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Readings | Amps B Ø | 140.0 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Readings | Amps C Ø | 230.0 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Readings | Amps B Ø | 170.0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Readings | Amps C Ø | 156.0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Readings | 9 Month Operations | 1 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Patrol Inspection | General Comments | | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Readings | Fault Operations Ground | 0 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | LTCC000982 | LTCControl | 653-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Readings | General Comments | | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Readings | Maintenance Operations | 0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Readings | General Comments | | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Readings | Maintenance Operations | 1 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Readings | Operations Counter AF | 201 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Readings | Operations Counter AL | 201 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Readings | Operations This Read Vac | 1 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Readings | Winding Temp Present | 30 | °C |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Readings | Winding Temp Max | 30 | °C |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.1424 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KT0039 | NonLTC | 666-2 | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | LTCC000982 | LTCControl | 653-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Readings | Fault Operations Ground | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Patrol Inspection | General Comments | | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Readings | General Comments | | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Readings | Maintenance Operations | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Readings | Operations Counter AF | 207 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Readings | Operations Counter AL | 207 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Readings | Operations This Read Vac | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Readings | Switching Operations | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000504 | BreakerVacuum | 609-0408 | VCB Readings | Unknown Operations | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Readings | 9 Month Operations | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Readings | Amps A Ø | 320.0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Readings | Amps B Ø | 340.0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Readings | Amps C Ø | 340.0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | BK000505 | BreakerVacuum | 609-0403 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | LTCC000982 | LTCControl | 653-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002116 | BreakerVacuum | FA-1148 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | K0123 | BreakerVacuum | 712-0827 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Readings | Follow-up Action Required? | n | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000256 | BreakerVacuum | 869-0810 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Readings | 9 Month Operations | 11 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Readings | 9 Month Operations VCB New | 11 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | LTCMechanism | 653-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | LTCMechanism | 653-1 | LTC Counter Readings | LTC As Left Counter | 538 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | LTCMechanism | 653-1 | LTC Counter Readings | LTC As Found Counter | 529 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | LTCMechanism | 653-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | LTCMechanism | 653-1 | LTC Counter Readings | General Comments | | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | LTCMechanism | 653-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | LTCMechanism | 653-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Readings | Amps A Ø | 85.0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Readings | Amps B Ø | 77.0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Readings | Amps C Ø | 92.0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1322 | BreakerVacuum | FA-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations | 792 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1322 | BreakerVacuum | FA-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations VCB New | 791 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Readings | Fault Operations Ground | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Patrol Inspection | General Comments | | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Readings | Amps B Ø | 341.0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Readings | Amps A Ø | 285.0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Readings | LTC Totalizer Reading | 4783.68 | kw |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Readings | General Comments | | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | BK000385 | BreakerVacuum | 869-1 | VCB Readings | 9 Month Operations | 1 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | TX000120 | WithLTC | 609-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | WithLTC | 653-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | LTCMechanism | 653-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | LTCMechanism | 653-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | LTCMechanism | 653-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | LTCMechanism | 653-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | LTCMechanism | 653-1 | LTC Counter Readings | LTC Operations Since Last Insp | 113 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | LTCMechanism | 653-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | LTCMechanism | 653-1 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | LTCMechanism | 653-1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | S0036 | LTCMechanism | 653-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002114 | BreakerVacuum | FA-12KV TR 1 | VCB Readings | Operations Counter AL | 17 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1322 | BreakerVacuum | FA-12KV BUS TIE SEC 2 | VCB Readings | Operations This Read Vac | 1 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1322 | BreakerVacuum | FA-12KV BUS TIE SEC 2 | VCB Readings | Switching Operations | 1 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1322 | BreakerVacuum | FA-12KV BUS TIE SEC 2 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Readings | Operations Counter AF | 13 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Readings | Operations Counter AL | 13 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Readings | Unknown Operations | 0 | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | LTCC000986 | LTCControl | 386-1 A | LTC Control Insp | VRR Time Delay | 45 | Seconds |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | LTCC000986 | LTCControl | 386-1 A | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Readings | Unknown Operations | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Readings | Switching Operations | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Readings | Operations This Read Vac | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Readings | Operations Counter AL | 42 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Readings | Operations Counter AF | 42 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Readings | Maintenance Operations | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Patrol Inspection | General Comments | | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Readings | Follow-up Action Required? | n | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Readings | Fault Operations Ground | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BB0383 | BreakerVacuum | 666-0471 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | LTCC000986 | LTCControl | 386-1 A | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | BK002115 | BreakerVacuum | FA-1123 | VCB Readings | General Comments | | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BAT001229 | Battery | 666-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BAT001229 | Battery | 666-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 35 | °F |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BAT001229 | Battery | 666-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BAT001229 | Battery | 666-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BAT001229 | Battery | 666-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BAT001229 | Battery | 666-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BAT001229 | Battery | 666-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BAT001229 | Battery | 666-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BAT001229 | Battery | 666-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BAT001229 | Battery | 666-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BAT001229 | Battery | 666-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BAT001229 | Battery | 666-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BAT001229 | Battery | 666-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | BAT001229 | Battery | 666-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | LTCC000987 | LTCControl | 722-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | LTCC000987 | LTCControl | 722-2 | LTC Control Insp | VRR Base Voltage AL | 123.6 | VAC |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | LTCC000987 | LTCControl | 722-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | LTCC000987 | LTCControl | 722-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | LTCC000987 | LTCControl | 722-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | LTCC000987 | LTCControl | 722-2 | LTC Control Insp | General Comments | | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | LTCC000987 | LTCControl | 722-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | LTCC000987 | LTCControl | 722-2 | LTC Control Insp | All Connections OK? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1322 | BreakerVacuum | FA-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1322 | BreakerVacuum | FA-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1322 | BreakerVacuum | FA-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1322 | BreakerVacuum | FA-12KV BUS TIE SEC 2 | VCB Readings | Amps A Ø | 0.0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1322 | BreakerVacuum | FA-12KV BUS TIE SEC 2 | VCB Readings | Amps B Ø | 0.0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1322 | BreakerVacuum | FA-12KV BUS TIE SEC 2 | VCB Readings | Amps C Ø | 0.0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1322 | BreakerVacuum | FA-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1322 | BreakerVacuum | FA-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1322 | BreakerVacuum | FA-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1322 | BreakerVacuum | FA-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1322 | BreakerVacuum | FA-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1322 | BreakerVacuum | FA-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1322 | BreakerVacuum | FA-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1322 | BreakerVacuum | FA-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1322 | BreakerVacuum | FA-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1322 | BreakerVacuum | FA-12KV BUS TIE SEC 2 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1322 | BreakerVacuum | FA-12KV BUS TIE SEC 2 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1322 | BreakerVacuum | FA-12KV BUS TIE SEC 2 | VCB Readings | General Comments | | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1322 | BreakerVacuum | FA-12KV BUS TIE SEC 2 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1322 | BreakerVacuum | FA-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AF | 917 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1322 | BreakerVacuum | FA-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AL | 917 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1318 | BreakerVacuum | FA-12KV TR 2 | VCB Readings | Operations Counter AL | 61 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1318 | BreakerVacuum | FA-12KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1318 | BreakerVacuum | FA-12KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1318 | BreakerVacuum | FA-12KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | MX0371 | RecloserHydraulic | 356-4627 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | MX0371 | RecloserHydraulic | 356-4627 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | MX0371 | RecloserHydraulic | 356-4627 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1131 | Regulator | 356-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1131 | Regulator | 356-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1131 | Regulator | 356-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1131 | Regulator | 356-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1131 | Regulator | 356-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1131 | Regulator | 356-1 B | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1131 | Regulator | 356-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1131 | Regulator | 356-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1131 | Regulator | 356-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1131 | Regulator | 356-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1131 | Regulator | 356-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1131 | Regulator | 356-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1131 | Regulator | 356-1 B | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1131 | Regulator | 356-1 B | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1131 | Regulator | 356-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1131 | Regulator | 356-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1131 | Regulator | 356-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1131 | Regulator | 356-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1131 | Regulator | 356-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1131 | Regulator | 356-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 173344 | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1131 | Regulator | 356-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1131 | Regulator | 356-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1131 | Regulator | 356-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1131 | Regulator | 356-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0779 | Regulator | 386-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0779 | Regulator | 386-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Readings | General Comments | | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | W0218 | NonLTC | 457-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | W0218 | NonLTC | 457-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0520 | Regulator | 702-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0520 | Regulator | 702-1 A | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0520 | Regulator | 702-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0520 | Regulator | 702-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0520 | Regulator | 702-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0520 | Regulator | 702-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0520 | Regulator | 702-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1318 | BreakerVacuum | FA-12KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1318 | BreakerVacuum | FA-12KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1318 | BreakerVacuum | FA-12KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1318 | BreakerVacuum | FA-12KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1318 | BreakerVacuum | FA-12KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1318 | BreakerVacuum | FA-12KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1318 | BreakerVacuum | FA-12KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1071 | Regulator | 356-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1071 | Regulator | 356-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1071 | Regulator | 356-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1318 | BreakerVacuum | FA-12KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BAT001357 | Battery | 653-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BAT001357 | Battery | 653-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BAT001357 | Battery | 653-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 12.8 | VDC |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BAT001357 | Battery | 653-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 13.1 | VDC |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BAT001357 | Battery | 653-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BAT001357 | Battery | 653-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BAT001357 | Battery | 653-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BAT001357 | Battery | 653-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BAT001357 | Battery | 653-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BAT001357 | Battery | 653-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BAT001357 | Battery | 653-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BAT001357 | Battery | 653-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BAT001357 | Battery | 653-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 39 | °F |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BAT001357 | Battery | 653-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | MX0371 | RecloserHydraulic | 356-4627 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 434 | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | MX0371 | RecloserHydraulic | 356-4627 | Recloser Hydraulic Patrol Inspection | Amps A Ø | .5 | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | MX0371 | RecloserHydraulic | 356-4627 | Recloser Hydraulic Patrol Inspection | Amps B Ø | .6 | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | MX0371 | RecloserHydraulic | 356-4627 | Recloser Hydraulic Patrol Inspection | Amps C Ø | .7 | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | MX0371 | RecloserHydraulic | 356-4627 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 406 | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | MX0371 | RecloserHydraulic | 356-4627 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | MX0371 | RecloserHydraulic | 356-4627 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | MX0371 | RecloserHydraulic | 356-4627 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 185 | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | MX0371 | RecloserHydraulic | 356-4627 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | MX0371 | RecloserHydraulic | 356-4627 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | MX0371 | RecloserHydraulic | 356-4627 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | MX0371 | RecloserHydraulic | 356-4627 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1318 | BreakerVacuum | FA-12KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1318 | BreakerVacuum | FA-12KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1318 | BreakerVacuum | FA-12KV TR 2 | VCB Readings | General Comments | actual VC | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1318 | BreakerVacuum | FA-12KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1318 | BreakerVacuum | FA-12KV TR 2 | VCB Readings | Operations Counter AF | 61 | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0522 | Regulator | 702-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0522 | Regulator | 702-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0522 | Regulator | 702-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0522 | Regulator | 702-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0522 | Regulator | 702-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0522 | Regulator | 702-1 C | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0522 | Regulator | 702-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0522 | Regulator | 702-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0522 | Regulator | 702-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0522 | Regulator | 702-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0522 | Regulator | 702-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0765 | Regulator | 538-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0765 | Regulator | 538-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0765 | Regulator | 538-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0765 | Regulator | 538-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 16819 | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0765 | Regulator | 538-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 126.4 | volts |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0765 | Regulator | 538-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0765 | Regulator | 538-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0765 | Regulator | 538-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0765 | Regulator | 538-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0765 | Regulator | 538-1 A | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0765 | Regulator | 538-1 A | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0765 | Regulator | 538-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0765 | Regulator | 538-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0765 | Regulator | 538-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0765 | Regulator | 538-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0765 | Regulator | 538-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0765 | Regulator | 538-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | FE000401 | Fence | 777-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0765 | Regulator | 538-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0765 | Regulator | 538-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0765 | Regulator | 538-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0765 | Regulator | 538-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0765 | Regulator | 538-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0765 | Regulator | 538-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1294 | Regulator | 457-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1294 | Regulator | 457-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1294 | Regulator | 457-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1294 | Regulator | 457-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1294 | Regulator | 457-1 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | FE000414 | Fence | 609-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1321 | BreakerVacuum | FA-1216 | VCB Readings | Unknown Operations | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1321 | BreakerVacuum | FA-1216 | VCB Readings | Switching Operations | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | FE000414 | Fence | 609-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | FE000414 | Fence | 609-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | FE000414 | Fence | 609-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | FE000414 | Fence | 609-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1321 | BreakerVacuum | FA-1216 | VCB Readings | Operations This Read Vac | 0 | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | W0218 | NonLTC | 457-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | W0218 | NonLTC | 457-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | W0218 | NonLTC | 457-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | W0218 | NonLTC | 457-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | W0218 | NonLTC | 457-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | W0218 | NonLTC | 457-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | W0218 | NonLTC | 457-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | W0218 | NonLTC | 457-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | W0218 | NonLTC | 457-1 | NonLTC Transformer Readings | General Comments | | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | W0218 | NonLTC | 457-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | W0218 | NonLTC | 457-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | W0218 | NonLTC | 457-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 570.96 | kw |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | W0218 | NonLTC | 457-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 52.50 | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | W0218 | NonLTC | 457-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | W0218 | NonLTC | 457-1 | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | W0218 | NonLTC | 457-1 | NonLTC Transformer Readings | Oil Temp Present | 24 | °C |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | W0218 | NonLTC | 457-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | W0218 | NonLTC | 457-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | W0218 | NonLTC | 457-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Adequate | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | W0218 | NonLTC | 457-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | W0218 | NonLTC | 457-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | W0218 | NonLTC | 457-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | W0218 | NonLTC | 457-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | W0218 | NonLTC | 457-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 600 | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | W0218 | NonLTC | 457-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .9516 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | FE000414 | Fence | 609-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | FE000414 | Fence | 609-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | FE000414 | Fence | 609-Fence | Fence Patrol Inspection | General Comments | | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1294 | Regulator | 457-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1294 | Regulator | 457-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1294 | Regulator | 457-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1294 | Regulator | 457-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 64212 | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1294 | Regulator | 457-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.9 | volts |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0522 | Regulator | 702-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0522 | Regulator | 702-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0522 | Regulator | 702-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0522 | Regulator | 702-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 6094 | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0522 | Regulator | 702-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 125.2 | volts |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0522 | Regulator | 702-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0522 | Regulator | 702-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .3 | psi |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1939.20 | kw |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 117.50 | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 110.00 | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0522 | Regulator | 702-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0522 | Regulator | 702-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0522 | Regulator | 702-1 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0522 | Regulator | 702-1 C | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0522 | Regulator | 702-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0781 | Regulator | 386-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0781 | Regulator | 386-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 273069 | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1295 | Regulator | 457-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | ST000242 | Structure | 653-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0781 | Regulator | 386-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 125.0 | volts |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0781 | Regulator | 386-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0781 | Regulator | 386-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0781 | Regulator | 386-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0781 | Regulator | 386-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0781 | Regulator | 386-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0781 | Regulator | 386-1 C | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0781 | Regulator | 386-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0781 | Regulator | 386-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0781 | Regulator | 386-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0781 | Regulator | 386-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0781 | Regulator | 386-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0781 | Regulator | 386-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0781 | Regulator | 386-1 C | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0781 | Regulator | 386-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0781 | Regulator | 386-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0781 | Regulator | 386-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0781 | Regulator | 386-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0781 | Regulator | 386-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000089 | Switchgear | FA-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000089 | Switchgear | FA-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1295 | Regulator | 457-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1295 | Regulator | 457-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1295 | Regulator | 457-1 C | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1295 | Regulator | 457-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1295 | Regulator | 457-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1295 | Regulator | 457-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000089 | Switchgear | FA-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000089 | Switchgear | FA-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0103 | Regulator | 027-5 B | Regulator Patrol Inspection | General Comments | | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0103 | Regulator | 027-5 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0103 | Regulator | 027-5 B | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0103 | Regulator | 027-5 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0103 | Regulator | 027-5 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0103 | Regulator | 027-5 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0103 | Regulator | 027-5 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0780 | Regulator | 386-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0780 | Regulator | 386-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0780 | Regulator | 386-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0780 | Regulator | 386-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 13834 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0780 | Regulator | 386-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 125.4 | volts |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0780 | Regulator | 386-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0780 | Regulator | 386-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0780 | Regulator | 386-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0780 | Regulator | 386-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | ST000242 | Structure | 653-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | ST000242 | Structure | 653-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000089 | Switchgear | FA-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000089 | Switchgear | FA-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000089 | Switchgear | FA-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000089 | Switchgear | FA-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000089 | Switchgear | FA-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1318 | BreakerVacuum | FA-12KV TR 2 | VCB Readings | 9 Month Operations | 7 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1318 | BreakerVacuum | FA-12KV TR 2 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1318 | BreakerVacuum | FA-12KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1318 | BreakerVacuum | FA-12KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1295 | Regulator | 457-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1295 | Regulator | 457-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1295 | Regulator | 457-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1295 | Regulator | 457-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 65952 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1318 | BreakerVacuum | FA-12KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1318 | BreakerVacuum | FA-12KV TR 2 | VCB Readings | Amps A Ø | 271.0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1318 | BreakerVacuum | FA-12KV TR 2 | VCB Readings | Amps B Ø | 283.0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCC000908 | LTCControl | 609-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCC000908 | LTCControl | 609-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | ST000242 | Structure | 653-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | ST000242 | Structure | 653-Structure | Structure Patrol Inspection | General Comments | | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | ST000242 | Structure | 653-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1295 | Regulator | 457-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1295 | Regulator | 457-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1295 | Regulator | 457-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | ST000242 | Structure | 653-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | ST000242 | Structure | 653-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000089 | Switchgear | FA-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | ST000242 | Structure | 653-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | ST000242 | Structure | 653-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCC000908 | LTCControl | 609-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCC000908 | LTCControl | 609-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0781 | Regulator | 386-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000089 | Switchgear | FA-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000089 | Switchgear | FA-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000089 | Switchgear | FA-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000089 | Switchgear | FA-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000089 | Switchgear | FA-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000089 | Switchgear | FA-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000089 | Switchgear | FA-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000089 | Switchgear | FA-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1295 | Regulator | 457-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1295 | Regulator | 457-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1295 | Regulator | 457-1 C | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1295 | Regulator | 457-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1295 | Regulator | 457-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1295 | Regulator | 457-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000089 | Switchgear | FA-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0781 | Regulator | 386-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | ST000341 | Structure | 666-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | ST000341 | Structure | 666-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | ST000341 | Structure | 666-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | ST000341 | Structure | 666-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | ST000341 | Structure | 666-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | ST000341 | Structure | 666-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | ST000341 | Structure | 666-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | ST000341 | Structure | 666-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | ST000341 | Structure | 666-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | ST000341 | Structure | 666-Structure | Structure Patrol Inspection | General Comments | | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | ST000341 | Structure | 666-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | ST000341 | Structure | 666-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | ST000341 | Structure | 666-Structure | Structure Patrol Inspection | Interruptrs/Puffrs Visual OK? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | ST000341 | Structure | 666-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | ST000341 | Structure | 666-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | ST000341 | Structure | 666-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | ST000341 | Structure | 666-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | ST000341 | Structure | 666-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | ST000341 | Structure | 666-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | ST000341 | Structure | 666-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | ST000341 | Structure | 666-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | ST000341 | Structure | 666-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | ST000341 | Structure | 666-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | ST000242 | Structure | 653-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | ST000242 | Structure | 653-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | ST000242 | Structure | 653-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | ST000242 | Structure | 653-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | ST000242 | Structure | 653-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0520 | Regulator | 702-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0520 | Regulator | 702-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0520 | Regulator | 702-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0520 | Regulator | 702-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 5043 | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0520 | Regulator | 702-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0520 | Regulator | 702-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0520 | Regulator | 702-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0520 | Regulator | 702-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0520 | Regulator | 702-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0520 | Regulator | 702-1 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0520 | Regulator | 702-1 A | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1318 | BreakerVacuum | FA-12KV TR 2 | VCB Readings | Amps C Ø | 296.0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1318 | BreakerVacuum | FA-12KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0520 | Regulator | 702-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0520 | Regulator | 702-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0520 | Regulator | 702-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0520 | Regulator | 702-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0520 | Regulator | 702-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0780 | Regulator | 386-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0780 | Regulator | 386-1 A | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1295 | Regulator | 457-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1295 | Regulator | 457-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0780 | Regulator | 386-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0780 | Regulator | 386-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0780 | Regulator | 386-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0780 | Regulator | 386-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0780 | Regulator | 386-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0780 | Regulator | 386-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0780 | Regulator | 386-1 A | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0780 | Regulator | 386-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0780 | Regulator | 386-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0780 | Regulator | 386-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0780 | Regulator | 386-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0780 | Regulator | 386-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000029 | Switchgear | FA-Swgr Sec 1 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000029 | Switchgear | FA-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000029 | Switchgear | FA-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000029 | Switchgear | FA-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000029 | Switchgear | FA-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0103 | Regulator | 027-5 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0103 | Regulator | 027-5 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.7 | volts |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0103 | Regulator | 027-5 B | Regulator Patrol Inspection | Regulator As Left Counter | 5853 | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0103 | Regulator | 027-5 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0103 | Regulator | 027-5 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0103 | Regulator | 027-5 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0103 | Regulator | 027-5 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000029 | Switchgear | FA-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000029 | Switchgear | FA-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000029 | Switchgear | FA-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | ST000242 | Structure | 653-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000029 | Switchgear | FA-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000029 | Switchgear | FA-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000029 | Switchgear | FA-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000029 | Switchgear | FA-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000029 | Switchgear | FA-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000029 | Switchgear | FA-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000029 | Switchgear | FA-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1293 | Regulator | 457-1 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1293 | Regulator | 457-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Readings | Fault Operations Ground | 0 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Readings | Follow-up Action Required? | n | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Readings | Oil Temp Max | 55 | °C |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Readings | Oil Temp Present | 15 | °C |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0269 | RecloserElectronic | 538-0314 | Recloser Electronic Patrol Inspection | Amps A Ø | 40.0 | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0269 | RecloserElectronic | 538-0314 | Recloser Electronic Patrol Inspection | Amps B Ø | 41.0 | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0269 | RecloserElectronic | 538-0314 | Recloser Electronic Patrol Inspection | Amps C Ø | 69.0 | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0269 | RecloserElectronic | 538-0314 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0269 | RecloserElectronic | 538-0314 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0269 | RecloserElectronic | 538-0314 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0269 | RecloserElectronic | 538-0314 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0269 | RecloserElectronic | 538-0314 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0269 | RecloserElectronic | 538-0314 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0269 | RecloserElectronic | 538-0314 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0269 | RecloserElectronic | 538-0314 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0269 | RecloserElectronic | 538-0314 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0269 | RecloserElectronic | 538-0314 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0269 | RecloserElectronic | 538-0314 | Recloser Electronic Patrol Inspection | General Comments | 27.7/25.5 | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0269 | RecloserElectronic | 538-0314 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0269 | RecloserElectronic | 538-0314 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1600 | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | W0179 | NonLTC | 702-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.2120 | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0269 | RecloserElectronic | 538-0314 | Recloser Electronic Patrol Inspection | Operations Counter | 17 | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0269 | RecloserElectronic | 538-0314 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0269 | RecloserElectronic | 538-0314 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0269 | RecloserElectronic | 538-0314 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | ST000407 | Structure | 777-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | ST000407 | Structure | 777-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | ST000407 | Structure | 777-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | ST000407 | Structure | 777-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | ST000407 | Structure | 777-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | ST000407 | Structure | 777-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | ST000407 | Structure | 777-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | ST000407 | Structure | 777-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0101 | Regulator | 027-5 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | ST000271 | Structure | 869-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | ST000271 | Structure | 869-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | ST000271 | Structure | 869-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Readings | Amps C Ø | 165.0 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1293 | Regulator | 457-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1293 | Regulator | 457-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1293 | Regulator | 457-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1293 | Regulator | 457-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 54570 | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1293 | Regulator | 457-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1293 | Regulator | 457-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1293 | Regulator | 457-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0102 | Regulator | 027-5 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0102 | Regulator | 027-5 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0102 | Regulator | 027-5 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0102 | Regulator | 027-5 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1293 | Regulator | 457-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1293 | Regulator | 457-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0102 | Regulator | 027-5 C | Regulator Patrol Inspection | Regulator As Left Counter | 29808 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1321 | BreakerVacuum | FA-1216 | VCB Readings | Amps C Ø | 95.0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1321 | BreakerVacuum | FA-1216 | VCB Readings | Amps B Ø | 94.0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1321 | BreakerVacuum | FA-1216 | VCB Readings | Amps A Ø | 88.0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1321 | BreakerVacuum | FA-1216 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1321 | BreakerVacuum | FA-1216 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1321 | BreakerVacuum | FA-1216 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1321 | BreakerVacuum | FA-1216 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1321 | BreakerVacuum | FA-1216 | VCB Readings | 9 Month Operations | 6 | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | X0335 | RecloserElectronic | 702-1450 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | X0335 | RecloserElectronic | 702-1450 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | X0335 | RecloserElectronic | 702-1450 | Recloser Electronic Patrol Inspection | Operations Counter | 78 | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | X0335 | RecloserElectronic | 702-1450 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | X0335 | RecloserElectronic | 702-1450 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | X0335 | RecloserElectronic | 702-1450 | Recloser Electronic Patrol Inspection | General Comments | 1 op - Trip check | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | X0335 | RecloserElectronic | 702-1450 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | X0335 | RecloserElectronic | 702-1450 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | X0335 | RecloserElectronic | 702-1450 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | X0335 | RecloserElectronic | 702-1450 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | X0335 | RecloserElectronic | 702-1450 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0102 | Regulator | 027-5 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.6 | volts |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0102 | Regulator | 027-5 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0102 | Regulator | 027-5 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Readings | Maintenance Operations | 0 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Readings | Operations Counter AF | 189 | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0102 | Regulator | 027-5 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0102 | Regulator | 027-5 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0102 | Regulator | 027-5 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0102 | Regulator | 027-5 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Readings | Operations Counter AL | 189 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Readings | Operations This Read Vac | 0 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Readings | Switching Operations | 0 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Readings | Unknown Operations | 0 | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1293 | Regulator | 457-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1293 | Regulator | 457-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1293 | Regulator | 457-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1293 | Regulator | 457-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | YD000405 | Yard | 777-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | YD000405 | Yard | 777-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | YD000405 | Yard | 777-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | YD000405 | Yard | 777-Yard | Yard Patrol Inspection | General Comments | | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | YD000405 | Yard | 777-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | YD000405 | Yard | 777-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | YD000405 | Yard | 777-Yard | Yard Patrol Inspection | Ambient Temp | 34 | °F |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | YD000405 | Yard | 777-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | YD000405 | Yard | 777-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | YD000405 | Yard | 777-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | YD000405 | Yard | 777-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1293 | Regulator | 457-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0166 | RecloserElectronic | 027-0309 | Recloser Electronic Patrol Inspection | Amps A Ø | 42.0 | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0166 | RecloserElectronic | 027-0309 | Recloser Electronic Patrol Inspection | Amps B Ø | 52.0 | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0166 | RecloserElectronic | 027-0309 | Recloser Electronic Patrol Inspection | Amps C Ø | 25.0 | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0166 | RecloserElectronic | 027-0309 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0166 | RecloserElectronic | 027-0309 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0166 | RecloserElectronic | 027-0309 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | YD000405 | Yard | 777-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0166 | RecloserElectronic | 027-0309 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0166 | RecloserElectronic | 027-0309 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0166 | RecloserElectronic | 027-0309 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0166 | RecloserElectronic | 027-0309 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0166 | RecloserElectronic | 027-0309 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0166 | RecloserElectronic | 027-0309 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0166 | RecloserElectronic | 027-0309 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0166 | RecloserElectronic | 027-0309 | Recloser Electronic Patrol Inspection | General Comments | 27.6/25.4 | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0166 | RecloserElectronic | 027-0309 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0166 | RecloserElectronic | 027-0309 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0166 | RecloserElectronic | 027-0309 | Recloser Electronic Patrol Inspection | Operations Counter | 68 | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0166 | RecloserElectronic | 027-0309 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0166 | RecloserElectronic | 027-0309 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0166 | RecloserElectronic | 027-0309 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | ST000407 | Structure | 777-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | ST000407 | Structure | 777-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | ST000407 | Structure | 777-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | ST000407 | Structure | 777-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | ST000407 | Structure | 777-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | ST000407 | Structure | 777-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | ST000407 | Structure | 777-Structure | Structure Patrol Inspection | General Comments | | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | ST000407 | Structure | 777-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | ST000407 | Structure | 777-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | ST000407 | Structure | 777-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | ST000407 | Structure | 777-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | ST000407 | Structure | 777-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | ST000407 | Structure | 777-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | ST000407 | Structure | 777-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | ST000407 | Structure | 777-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | ST000407 | Structure | 777-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | X0335 | RecloserElectronic | 702-1450 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | X0335 | RecloserElectronic | 702-1450 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | X0335 | RecloserElectronic | 702-1450 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | X0335 | RecloserElectronic | 702-1450 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | X0335 | RecloserElectronic | 702-1450 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | X0335 | RecloserElectronic | 702-1450 | Recloser Electronic Patrol Inspection | Amps C Ø | 131.0 | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0102 | Regulator | 027-5 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0102 | Regulator | 027-5 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0102 | Regulator | 027-5 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0102 | Regulator | 027-5 C | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0102 | Regulator | 027-5 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | X0335 | RecloserElectronic | 702-1450 | Recloser Electronic Patrol Inspection | Amps B Ø | 97.0 | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | X0335 | RecloserElectronic | 702-1450 | Recloser Electronic Patrol Inspection | Amps A Ø | 119.0 | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0102 | Regulator | 027-5 C | Regulator Patrol Inspection | General Comments | | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0102 | Regulator | 027-5 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0102 | Regulator | 027-5 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0102 | Regulator | 027-5 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0102 | Regulator | 027-5 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0102 | Regulator | 027-5 C | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1293 | Regulator | 457-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0102 | Regulator | 027-5 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1293 | Regulator | 457-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1293 | Regulator | 457-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1293 | Regulator | 457-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1293 | Regulator | 457-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BCH001272 | Charger | 653-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BCH001272 | Charger | 653-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BCH001272 | Charger | 653-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .7 | amps |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BCH001272 | Charger | 653-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | BCH001272 | Charger | 653-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1293 | Regulator | 457-1 A | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Patrol Inspection | General Comments | | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Readings | General Comments | | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | MX0171 | RecloserHydraulic | 386-4404 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | MX0171 | RecloserHydraulic | 386-4404 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | MX0171 | RecloserHydraulic | 386-4404 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | MX0171 | RecloserHydraulic | 386-4404 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | MX0171 | RecloserHydraulic | 386-4404 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | MX0171 | RecloserHydraulic | 386-4404 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | MX0171 | RecloserHydraulic | 386-4404 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | MX0171 | RecloserHydraulic | 386-4404 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 12.5 | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0779 | Regulator | 386-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1321 | BreakerVacuum | FA-1216 | VCB Readings | Follow-up Action Required? | n | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0779 | Regulator | 386-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 348504 | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0779 | Regulator | 386-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.2 | volts |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | FE000401 | Fence | 777-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | FE000401 | Fence | 777-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1321 | BreakerVacuum | FA-1216 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | FE000401 | Fence | 777-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | FE000401 | Fence | 777-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1093 | Regulator | 712-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1093 | Regulator | 712-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1093 | Regulator | 712-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | FE000401 | Fence | 777-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | FE000401 | Fence | 777-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | FE000401 | Fence | 777-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1093 | Regulator | 712-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1093 | Regulator | 712-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1093 | Regulator | 712-1 C | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | FE000401 | Fence | 777-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | FE000401 | Fence | 777-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | FE000401 | Fence | 777-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0779 | Regulator | 386-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0779 | Regulator | 386-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0779 | Regulator | 386-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | FE000401 | Fence | 777-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | FE000401 | Fence | 777-Fence | Fence Patrol Inspection | General Comments | | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | FE000401 | Fence | 777-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | FE000401 | Fence | 777-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0779 | Regulator | 386-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0779 | Regulator | 386-1 B | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1093 | Regulator | 712-1 C | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1093 | Regulator | 712-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1093 | Regulator | 712-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1093 | Regulator | 712-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1093 | Regulator | 712-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1093 | Regulator | 712-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.6 | volts |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1093 | Regulator | 712-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 175450 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1093 | Regulator | 712-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1093 | Regulator | 712-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1093 | Regulator | 712-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0779 | Regulator | 386-1 B | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1321 | BreakerVacuum | FA-1216 | VCB Readings | Operations Counter AL | 191 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1321 | BreakerVacuum | FA-1216 | VCB Readings | Operations Counter AF | 191 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1321 | BreakerVacuum | FA-1216 | VCB Readings | Maintenance Operations | 0 | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | FE000414 | Fence | 609-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | FE000414 | Fence | 609-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | FE000414 | Fence | 609-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | FE000414 | Fence | 609-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | FE000414 | Fence | 609-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | FE000414 | Fence | 609-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | FE000414 | Fence | 609-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1092 | Regulator | 712-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1092 | Regulator | 712-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1092 | Regulator | 712-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1092 | Regulator | 712-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1092 | Regulator | 712-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1092 | Regulator | 712-1 B | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1092 | Regulator | 712-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1092 | Regulator | 712-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1092 | Regulator | 712-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1092 | Regulator | 712-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1092 | Regulator | 712-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1092 | Regulator | 712-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1092 | Regulator | 712-1 B | Regulator Patrol Inspection | Max Tap Position | 6L | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1321 | BreakerVacuum | FA-1216 | VCB Readings | General Comments | | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1321 | BreakerVacuum | FA-1216 | VCB Patrol Inspection | General Comments | | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1092 | Regulator | 712-1 B | Regulator Patrol Inspection | Min Tap Position | 13L | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1092 | Regulator | 712-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1092 | Regulator | 712-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1092 | Regulator | 712-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1092 | Regulator | 712-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1092 | Regulator | 712-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1092 | Regulator | 712-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 302606 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1092 | Regulator | 712-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1092 | Regulator | 712-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1092 | Regulator | 712-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1093 | Regulator | 712-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1093 | Regulator | 712-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1093 | Regulator | 712-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1093 | Regulator | 712-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1093 | Regulator | 712-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1093 | Regulator | 712-1 C | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R1093 | Regulator | 712-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | FE000414 | Fence | 609-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1294 | Regulator | 457-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1294 | Regulator | 457-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1294 | Regulator | 457-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1294 | Regulator | 457-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | MX0171 | RecloserHydraulic | 386-4404 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | MX0171 | RecloserHydraulic | 386-4404 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | MX0171 | RecloserHydraulic | 386-4404 | Recloser Hydraulic Patrol Inspection | Operations Counter | 168 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | ST000271 | Structure | 869-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | ST000271 | Structure | 869-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | ST000271 | Structure | 869-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0168 | RecloserElectronic | 027-0310 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0101 | Regulator | 027-5 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0779 | Regulator | 386-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0779 | Regulator | 386-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0779 | Regulator | 386-1 B | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1321 | BreakerVacuum | FA-1216 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1321 | BreakerVacuum | FA-1216 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1321 | BreakerVacuum | FA-1216 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1321 | BreakerVacuum | FA-1216 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1321 | BreakerVacuum | FA-1216 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1321 | BreakerVacuum | FA-1216 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1321 | BreakerVacuum | FA-1216 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0779 | Regulator | 386-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0779 | Regulator | 386-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0779 | Regulator | 386-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0779 | Regulator | 386-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0779 | Regulator | 386-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | ST000271 | Structure | 869-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | ST000271 | Structure | 869-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | ST000271 | Structure | 869-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | ST000271 | Structure | 869-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1321 | BreakerVacuum | FA-1216 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | ST000271 | Structure | 869-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | ST000271 | Structure | 869-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0101 | Regulator | 027-5 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0101 | Regulator | 027-5 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0101 | Regulator | 027-5 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0101 | Regulator | 027-5 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0101 | Regulator | 027-5 A | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0101 | Regulator | 027-5 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0101 | Regulator | 027-5 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0101 | Regulator | 027-5 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0101 | Regulator | 027-5 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0101 | Regulator | 027-5 A | Regulator Patrol Inspection | General Comments | | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0101 | Regulator | 027-5 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0101 | Regulator | 027-5 A | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0101 | Regulator | 027-5 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0101 | Regulator | 027-5 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0101 | Regulator | 027-5 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0101 | Regulator | 027-5 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0101 | Regulator | 027-5 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0101 | Regulator | 027-5 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.4 | volts |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0101 | Regulator | 027-5 A | Regulator Patrol Inspection | Regulator As Left Counter | 32494 | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0101 | Regulator | 027-5 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0101 | Regulator | 027-5 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0101 | Regulator | 027-5 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0779 | Regulator | 386-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0779 | Regulator | 386-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | MX0171 | RecloserHydraulic | 386-4404 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 11.4 | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1294 | Regulator | 457-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1294 | Regulator | 457-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1294 | Regulator | 457-1 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1294 | Regulator | 457-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1294 | Regulator | 457-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1294 | Regulator | 457-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1294 | Regulator | 457-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 12:16 | Distribution | Sentry Quarterly Inspection | R1294 | Regulator | 457-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | MX0171 | RecloserHydraulic | 386-4404 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 13.9 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Readings | 9 Month Operations | 0 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Readings | Amps A Ø | 85.0 | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BK001160 | BreakerVacuum | 777-0430 | VCB Readings | Amps B Ø | 95.0 | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0779 | Regulator | 386-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | R0779 | Regulator | 386-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | ST000271 | Structure | 869-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | ST000271 | Structure | 869-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | ST000271 | Structure | 869-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | ST000271 | Structure | 869-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0168 | RecloserElectronic | 027-0310 | Recloser Electronic Patrol Inspection | Amps A Ø | 31.0 | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0168 | RecloserElectronic | 027-0310 | Recloser Electronic Patrol Inspection | Amps B Ø | 12.0 | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0168 | RecloserElectronic | 027-0310 | Recloser Electronic Patrol Inspection | Amps C Ø | 59.0 | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0168 | RecloserElectronic | 027-0310 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0168 | RecloserElectronic | 027-0310 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0168 | RecloserElectronic | 027-0310 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0168 | RecloserElectronic | 027-0310 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0168 | RecloserElectronic | 027-0310 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0168 | RecloserElectronic | 027-0310 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0168 | RecloserElectronic | 027-0310 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0168 | RecloserElectronic | 027-0310 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0168 | RecloserElectronic | 027-0310 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0168 | RecloserElectronic | 027-0310 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0168 | RecloserElectronic | 027-0310 | Recloser Electronic Patrol Inspection | General Comments | 27.7/25.6 | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0168 | RecloserElectronic | 027-0310 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0168 | RecloserElectronic | 027-0310 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0168 | RecloserElectronic | 027-0310 | Recloser Electronic Patrol Inspection | Operations Counter | 60 | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0168 | RecloserElectronic | 027-0310 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KX0168 | RecloserElectronic | 027-0310 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | ST000271 | Structure | 869-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | ST000271 | Structure | 869-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | ST000271 | Structure | 869-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | ST000271 | Structure | 869-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | ST000271 | Structure | 869-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | ST000271 | Structure | 869-Structure | Structure Patrol Inspection | General Comments | | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Readings | General Comments | | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0521 | Regulator | 702-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R0730 | Regulator | 712-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R0730 | Regulator | 712-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0521 | Regulator | 702-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R0730 | Regulator | 712-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Readings | 9 Month Operations | 3 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R0730 | Regulator | 712-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R0730 | Regulator | 712-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R0730 | Regulator | 712-1 A | Regulator Patrol Inspection | Min Tap Position | 13L | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R0730 | Regulator | 712-1 A | Regulator Patrol Inspection | Max Tap Position | 5L | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R0730 | Regulator | 712-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R0730 | Regulator | 712-1 A | Regulator Patrol Inspection | General Comments | Counter is not operating. | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R0730 | Regulator | 712-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R0730 | Regulator | 712-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R0730 | Regulator | 712-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R0730 | Regulator | 712-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R0730 | Regulator | 712-1 A | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1320 | BreakerVacuum | FA-1215 | VCB Readings | 9 Month Operations | 12 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Readings | Amps A Ø | 171.0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Readings | Amps B Ø | 187.0 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R0730 | Regulator | 712-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R0730 | Regulator | 712-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R0730 | Regulator | 712-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R0730 | Regulator | 712-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R0730 | Regulator | 712-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Readings | Amps C Ø | 168.0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0521 | Regulator | 702-1 B | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0521 | Regulator | 702-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0521 | Regulator | 702-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0087 | Regulator | 666-2 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0521 | Regulator | 702-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1071 | Regulator | 356-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0087 | Regulator | 666-2 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0087 | Regulator | 666-2 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0087 | Regulator | 666-2 C | Regulator Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0521 | Regulator | 702-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0521 | Regulator | 702-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1071 | Regulator | 356-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1071 | Regulator | 356-1 A | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1071 | Regulator | 356-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1071 | Regulator | 356-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1319 | BreakerVacuum | FA-1214 | VCB Readings | 9 Month Operations | 8 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1319 | BreakerVacuum | FA-1214 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1319 | BreakerVacuum | FA-1214 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1319 | BreakerVacuum | FA-1214 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1319 | BreakerVacuum | FA-1214 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1071 | Regulator | 356-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1071 | Regulator | 356-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1071 | Regulator | 356-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0521 | Regulator | 702-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.7 | volts |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0521 | Regulator | 702-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0521 | Regulator | 702-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0521 | Regulator | 702-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0934 | Regulator | 538-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0934 | Regulator | 538-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0934 | Regulator | 538-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0934 | Regulator | 538-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0934 | Regulator | 538-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0934 | Regulator | 538-1 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0934 | Regulator | 538-1 C | Regulator Patrol Inspection | Min Tap Position | 13L | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0521 | Regulator | 702-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0521 | Regulator | 702-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0521 | Regulator | 702-1 B | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0521 | Regulator | 702-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0521 | Regulator | 702-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0521 | Regulator | 702-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R0730 | Regulator | 712-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R0730 | Regulator | 712-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | FE000262 | Fence | 869-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | FE000262 | Fence | 869-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | FE000262 | Fence | 869-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | FE000262 | Fence | 869-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | FE000262 | Fence | 869-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | ST000420 | Structure | 609-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | ST000420 | Structure | 609-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | ST000420 | Structure | 609-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | ST000420 | Structure | 609-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | ST000420 | Structure | 609-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | ST000420 | Structure | 609-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | ST000420 | Structure | 609-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | ST000420 | Structure | 609-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | ST000420 | Structure | 609-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | ST000420 | Structure | 609-Structure | Structure Patrol Inspection | General Comments | | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | ST000420 | Structure | 609-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | ST000420 | Structure | 609-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | ST000420 | Structure | 609-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | ST000420 | Structure | 609-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | FE000262 | Fence | 869-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | FE000262 | Fence | 869-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | FE000262 | Fence | 869-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0521 | Regulator | 702-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0791 | Regulator | 538-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0791 | Regulator | 538-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | FE000262 | Fence | 869-Fence | Fence Patrol Inspection | General Comments | | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | FE000262 | Fence | 869-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | FE000262 | Fence | 869-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0934 | Regulator | 538-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0934 | Regulator | 538-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0934 | Regulator | 538-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | ST000420 | Structure | 609-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | ST000420 | Structure | 609-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | ST000420 | Structure | 609-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | ST000420 | Structure | 609-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | ST000420 | Structure | 609-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | ST000420 | Structure | 609-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | ST000420 | Structure | 609-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | ST000420 | Structure | 609-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0934 | Regulator | 538-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0934 | Regulator | 538-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 125.0 | volts |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0934 | Regulator | 538-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 144676 | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0934 | Regulator | 538-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0934 | Regulator | 538-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0934 | Regulator | 538-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1320 | BreakerVacuum | FA-1215 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1320 | BreakerVacuum | FA-1215 | VCB Readings | 9 Month Operations VCB New | 11 | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R0730 | Regulator | 712-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/2/2023 9:22 | Distribution | East Diamond Quarterly Inspection | R0730 | Regulator | 712-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 10300 | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0791 | Regulator | 538-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 2154.24 | kw |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1319 | BreakerVacuum | FA-1214 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1319 | BreakerVacuum | FA-1214 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1319 | BreakerVacuum | FA-1214 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1319 | BreakerVacuum | FA-1214 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1319 | BreakerVacuum | FA-1214 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1319 | BreakerVacuum | FA-1214 | VCB Patrol Inspection | General Comments | | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1319 | BreakerVacuum | FA-1214 | VCB Readings | General Comments | | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1319 | BreakerVacuum | FA-1214 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1319 | BreakerVacuum | FA-1214 | VCB Readings | Operations Counter AF | 132 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1319 | BreakerVacuum | FA-1214 | VCB Readings | Operations Counter AL | 132 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1319 | BreakerVacuum | FA-1214 | VCB Readings | Operations This Read Vac | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | LTCMechanism | 666-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1319 | BreakerVacuum | FA-1214 | VCB Readings | Switching Operations | 0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Readings | Fault Operations Ground | 0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Readings | Follow-up Action Required? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Patrol Inspection | General Comments | | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Readings | General Comments | | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1319 | BreakerVacuum | FA-1214 | VCB Readings | Unknown Operations | 0 | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1071 | Regulator | 356-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0791 | Regulator | 538-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0791 | Regulator | 538-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0791 | Regulator | 538-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0791 | Regulator | 538-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0791 | Regulator | 538-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0791 | Regulator | 538-1 B | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0791 | Regulator | 538-1 B | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Readings | Maintenance Operations | 0 | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0791 | Regulator | 538-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0791 | Regulator | 538-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000029 | Switchgear | FA-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0791 | Regulator | 538-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0791 | Regulator | 538-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0791 | Regulator | 538-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.0 | volts |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0791 | Regulator | 538-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 207171 | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0791 | Regulator | 538-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Readings | Operations Counter AF | 206 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Readings | Operations Counter AL | 206 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Readings | Operations This Read Vac | 0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Readings | Switching Operations | 0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Readings | Unknown Operations | 0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Readings | Unknown Operations | 0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Readings | Switching Operations | 0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Readings | Operations This Read Vac | 1 | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0791 | Regulator | 538-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0791 | Regulator | 538-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Readings | Operations Counter AL | 202 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Readings | Operations Counter AF | 202 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Readings | Maintenance Operations | 1 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Readings | Fault Operations Ground | 0 | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Readings | Follow-up Action Required? | n | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Patrol Inspection | General Comments | | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Readings | General Comments | | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | K0129 | BreakerVacuum | 869-0811 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1071 | Regulator | 356-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1071 | Regulator | 356-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1071 | Regulator | 356-1 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1071 | Regulator | 356-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1071 | Regulator | 356-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1071 | Regulator | 356-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1071 | Regulator | 356-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1071 | Regulator | 356-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.7 | volts |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1071 | Regulator | 356-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 376121 | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1071 | Regulator | 356-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1071 | Regulator | 356-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1071 | Regulator | 356-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | LTCMechanism | 666-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | LTCMechanism | 666-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | LTCMechanism | 666-1 | LTC Counter Readings | General Comments | | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | LTCMechanism | 666-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | LTCMechanism | 666-1 | LTC Counter Readings | LTC As Found Counter | 57981 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | LTCMechanism | 666-1 | LTC Counter Readings | LTC As Left Counter | 57981 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | LTCMechanism | 666-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | LTCMechanism | 666-1 | LTC Counter Readings | LTC Current Tap Position | 1R | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | LTCMechanism | 666-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | LTCMechanism | 666-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | LTCMechanism | 666-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | LTCMechanism | 666-1 | LTC Counter Readings | LTC Operations Since Last Insp | 349 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | LTCMechanism | 666-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | LTCMechanism | 666-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | S0002 | LTCMechanism | 666-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1319 | BreakerVacuum | FA-1214 | VCB Readings | Amps A Ø | 77.0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1319 | BreakerVacuum | FA-1214 | VCB Readings | Amps B Ø | 100.0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1319 | BreakerVacuum | FA-1214 | VCB Readings | Amps C Ø | 118.0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1319 | BreakerVacuum | FA-1214 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1319 | BreakerVacuum | FA-1214 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1319 | BreakerVacuum | FA-1214 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1021 | Regulator | 356-1 C | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Readings | 9 Month Operations | 5 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Readings | Amps A Ø | 76.0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Readings | Amps B Ø | 71.0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Readings | Amps C Ø | 128.0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1021 | Regulator | 356-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1021 | Regulator | 356-1 C | Regulator Patrol Inspection | General Comments | Drag hands do not work | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1021 | Regulator | 356-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1021 | Regulator | 356-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1021 | Regulator | 356-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/2/2023 10:11 | Distribution | Pineville Quarterly Inspection | BK001146 | BreakerVacuum | 722-0302 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1021 | Regulator | 356-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1021 | Regulator | 356-1 C | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1021 | Regulator | 356-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1021 | Regulator | 356-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1021 | Regulator | 356-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1021 | Regulator | 356-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1021 | Regulator | 356-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1319 | BreakerVacuum | FA-1214 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1319 | BreakerVacuum | FA-1214 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | YD000234 | Yard | 653-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | YD000234 | Yard | 653-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | YD000234 | Yard | 653-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | YD000234 | Yard | 653-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | YD000234 | Yard | 653-Yard | Yard Patrol Inspection | Ambient Temp | 36 | °F |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | FE000236 | Fence | 653-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | FE000236 | Fence | 653-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | FE000236 | Fence | 653-Fence | Fence Patrol Inspection | General Comments | | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | FE000236 | Fence | 653-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0087 | Regulator | 666-2 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0087 | Regulator | 666-2 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0087 | Regulator | 666-2 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0087 | Regulator | 666-2 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0087 | Regulator | 666-2 C | Regulator Patrol Inspection | Regulator As Left Counter | 36943 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0087 | Regulator | 666-2 C | Regulator Patrol Inspection | Reg Output Voltage Level | 125.0 | volts |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0087 | Regulator | 666-2 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0087 | Regulator | 666-2 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | FE000236 | Fence | 653-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Readings | Winding Temp Present | 15 | °C |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Readings | Winding Temp Max | 28 | °C |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Readings | Totalizer Meter Reading | .4488 | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | ST000038 | Structure | 386-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | FE000236 | Fence | 653-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | FE000236 | Fence | 653-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | FE000236 | Fence | 653-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0088 | Regulator | 666-2 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0088 | Regulator | 666-2 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0088 | Regulator | 666-2 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0088 | Regulator | 666-2 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | ST000038 | Structure | 386-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | ST000038 | Structure | 386-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | ST000038 | Structure | 386-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | ST000038 | Structure | 386-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | ST000038 | Structure | 386-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | ST000038 | Structure | 386-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | ST000038 | Structure | 386-Structure | Structure Patrol Inspection | General Comments | | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | ST000038 | Structure | 386-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | ST000038 | Structure | 386-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | ST000038 | Structure | 386-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | ST000038 | Structure | 386-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | ST000038 | Structure | 386-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | ST000038 | Structure | 386-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | ST000038 | Structure | 386-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | ST000038 | Structure | 386-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | ST000038 | Structure | 386-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/16/2023 7:33 | Distribution | Laurel Grove Quarterly Inspection | ST000038 | Structure | 386-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0089 | Regulator | 666-2 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0089 | Regulator | 666-2 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0089 | Regulator | 666-2 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0089 | Regulator | 666-2 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0089 | Regulator | 666-2 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0089 | Regulator | 666-2 A | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0089 | Regulator | 666-2 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0089 | Regulator | 666-2 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0089 | Regulator | 666-2 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | FE000236 | Fence | 653-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | FE000236 | Fence | 653-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | FE000236 | Fence | 653-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | FE000236 | Fence | 653-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | FE000236 | Fence | 653-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | FE000236 | Fence | 653-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | FE000236 | Fence | 653-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | FE000257 | Fence | 702-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | FE000257 | Fence | 702-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | FE000257 | Fence | 702-Fence | Fence Patrol Inspection | General Comments | | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | FE000257 | Fence | 702-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | FE000236 | Fence | 653-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0089 | Regulator | 666-2 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0089 | Regulator | 666-2 A | Regulator Patrol Inspection | General Comments | | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0089 | Regulator | 666-2 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0089 | Regulator | 666-2 A | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0089 | Regulator | 666-2 A | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1320 | BreakerVacuum | FA-1215 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | ST000242 | Structure | 653-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | ST000242 | Structure | 653-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | ST000242 | Structure | 653-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | ST000242 | Structure | 653-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | ST000242 | Structure | 653-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | ST000242 | Structure | 653-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCC000908 | LTCControl | 609-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCC000908 | LTCControl | 609-2 | LTC Control Insp | General Comments | | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | YD000338 | Yard | 666-Yard | Yard Patrol Inspection | General Comments | | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | YD000338 | Yard | 666-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | YD000338 | Yard | 666-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCC000908 | LTCControl | 609-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | LTCC000908 | LTCControl | 609-2 | LTC Control Insp | All Connections OK? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | YD000338 | Yard | 666-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | YD000338 | Yard | 666-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | YD000338 | Yard | 666-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | YD000338 | Yard | 666-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1320 | BreakerVacuum | FA-1215 | VCB Readings | Unknown Operations | 1 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1320 | BreakerVacuum | FA-1215 | VCB Readings | Switching Operations | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1320 | BreakerVacuum | FA-1215 | VCB Readings | Operations This Read Vac | 1 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1320 | BreakerVacuum | FA-1215 | VCB Readings | Operations Counter AL | 136 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1320 | BreakerVacuum | FA-1215 | VCB Readings | Operations Counter AF | 136 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1320 | BreakerVacuum | FA-1215 | VCB Readings | Maintenance Operations | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1320 | BreakerVacuum | FA-1215 | VCB Readings | General Comments | | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1320 | BreakerVacuum | FA-1215 | VCB Patrol Inspection | General Comments | | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1320 | BreakerVacuum | FA-1215 | VCB Readings | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1320 | BreakerVacuum | FA-1215 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1320 | BreakerVacuum | FA-1215 | VCB Readings | Fault Operations Ground | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1320 | BreakerVacuum | FA-1215 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1320 | BreakerVacuum | FA-1215 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0088 | Regulator | 666-2 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0088 | Regulator | 666-2 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0088 | Regulator | 666-2 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0088 | Regulator | 666-2 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0088 | Regulator | 666-2 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0088 | Regulator | 666-2 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | YD000234 | Yard | 653-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | YD000338 | Yard | 666-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | YD000338 | Yard | 666-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | YD000338 | Yard | 666-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | YD000338 | Yard | 666-Yard | Yard Patrol Inspection | Ambient Temp | 28 | °F |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | YD000234 | Yard | 653-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | YD000234 | Yard | 653-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | n | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | YD000234 | Yard | 653-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0103 | Regulator | 027-5 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0103 | Regulator | 027-5 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0103 | Regulator | 027-5 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0103 | Regulator | 027-5 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0103 | Regulator | 027-5 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | YD000234 | Yard | 653-Yard | Yard Patrol Inspection | General Comments | SPR is no longer in station  washout starting in back right corner | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | YD000234 | Yard | 653-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | YD000234 | Yard | 653-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | YD000234 | Yard | 653-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0088 | Regulator | 666-2 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0088 | Regulator | 666-2 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0088 | Regulator | 666-2 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0088 | Regulator | 666-2 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0088 | Regulator | 666-2 B | Regulator Patrol Inspection | General Comments | | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000029 | Switchgear | FA-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000029 | Switchgear | FA-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000029 | Switchgear | FA-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | SWG000029 | Switchgear | FA-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0088 | Regulator | 666-2 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0088 | Regulator | 666-2 B | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0103 | Regulator | 027-5 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0103 | Regulator | 027-5 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0103 | Regulator | 027-5 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0103 | Regulator | 027-5 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KR0103 | Regulator | 027-5 B | Regulator Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0088 | Regulator | 666-2 B | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0088 | Regulator | 666-2 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0088 | Regulator | 666-2 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0088 | Regulator | 666-2 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0088 | Regulator | 666-2 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0088 | Regulator | 666-2 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.0 | volts |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0088 | Regulator | 666-2 B | Regulator Patrol Inspection | Regulator As Left Counter | 41372 | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | YD000234 | Yard | 653-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/2/2023 15:00 | Distribution | Dozier Heights Quarterly Inspection | YD000234 | Yard | 653-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0325 | RecloserElectronic | 538-0313 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0325 | RecloserElectronic | 538-0313 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0325 | RecloserElectronic | 538-0313 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0325 | RecloserElectronic | 538-0313 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0325 | RecloserElectronic | 538-0313 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0325 | RecloserElectronic | 538-0313 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0325 | RecloserElectronic | 538-0313 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0325 | RecloserElectronic | 538-0313 | Recloser Electronic Patrol Inspection | Amps C Ø | 136.0 | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0325 | RecloserElectronic | 538-0313 | Recloser Electronic Patrol Inspection | Amps B Ø | 84.0 | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0325 | RecloserElectronic | 538-0313 | Recloser Electronic Patrol Inspection | Amps A Ø | 103.0 | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1021 | Regulator | 356-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1021 | Regulator | 356-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1021 | Regulator | 356-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0089 | Regulator | 666-2 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0089 | Regulator | 666-2 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0087 | Regulator | 666-2 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | FE000257 | Fence | 702-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | FE000257 | Fence | 702-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | FE000257 | Fence | 702-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | FE000257 | Fence | 702-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | YD000418 | Yard | 609-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | YD000418 | Yard | 609-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | YD000418 | Yard | 609-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | YD000418 | Yard | 609-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | YD000418 | Yard | 609-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | YD000418 | Yard | 609-Yard | Yard Patrol Inspection | General Comments | | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | YD000418 | Yard | 609-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | YD000418 | Yard | 609-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | YD000418 | Yard | 609-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1021 | Regulator | 356-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1021 | Regulator | 356-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 91349 | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | FE000257 | Fence | 702-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | FE000257 | Fence | 702-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | FE000257 | Fence | 702-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | FE000257 | Fence | 702-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | FE000257 | Fence | 702-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | FE000257 | Fence | 702-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | FE000257 | Fence | 702-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BCH001307 | Charger | 777-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BCH001307 | Charger | 777-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BCH001307 | Charger | 777-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BCH001307 | Charger | 777-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BCH001307 | Charger | 777-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.3 | amps |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BCH001307 | Charger | 777-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BCH001307 | Charger | 777-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 2/2/2023 12:54 | Distribution | Newtown Quarterly Inspection | BCH001307 | Charger | 777-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | FE000257 | Fence | 702-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0934 | Regulator | 538-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0934 | Regulator | 538-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0087 | Regulator | 666-2 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0087 | Regulator | 666-2 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0087 | Regulator | 666-2 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0087 | Regulator | 666-2 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | FE000262 | Fence | 869-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | FE000262 | Fence | 869-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | FE000262 | Fence | 869-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1021 | Regulator | 356-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1021 | Regulator | 356-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1021 | Regulator | 356-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1021 | Regulator | 356-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1021 | Regulator | 356-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 13:25 | Distribution | Blackwood Quarterly Inspection | R1021 | Regulator | 356-1 C | Regulator Patrol Inspection | Min Tap Position | 3L | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0791 | Regulator | 538-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | FE000262 | Fence | 869-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0934 | Regulator | 538-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0934 | Regulator | 538-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 8:55 | Distribution | Hanson Quarterly Inspection | FE000262 | Fence | 869-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0934 | Regulator | 538-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0934 | Regulator | 538-1 C | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0934 | Regulator | 538-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0791 | Regulator | 538-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0791 | Regulator | 538-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | R0791 | Regulator | 538-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0521 | Regulator | 702-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0521 | Regulator | 702-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0521 | Regulator | 702-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/2/2023 10:58 | Distribution | Manitou Quarterly Inspection | R0521 | Regulator | 702-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 131730 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1320 | BreakerVacuum | FA-1215 | VCB Readings | Fault Adjusted Amps C Phase V | 11.18 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1320 | BreakerVacuum | FA-1215 | VCB Readings | Fault Adjusted Amps B Phase V | 11.18 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1320 | BreakerVacuum | FA-1215 | VCB Readings | Fault Adjusted Amps A Phase V | 11.18 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1320 | BreakerVacuum | FA-1215 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1320 | BreakerVacuum | FA-1215 | VCB Readings | Amps C Ø | 90.0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1320 | BreakerVacuum | FA-1215 | VCB Readings | Amps B Ø | 99.0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1320 | BreakerVacuum | FA-1215 | VCB Readings | Amps A Ø | 106.0 | |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1320 | BreakerVacuum | FA-1215 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/3/2023 7:01 | Distribution | Farnsley Quarterly Inspection | LB1320 | BreakerVacuum | FA-1215 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0089 | Regulator | 666-2 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0089 | Regulator | 666-2 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0087 | Regulator | 666-2 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0087 | Regulator | 666-2 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | YD000418 | Yard | 609-Yard | Yard Patrol Inspection | Ambient Temp | 30 | °F |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0087 | Regulator | 666-2 C | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0087 | Regulator | 666-2 C | Regulator Patrol Inspection | Max Tap Position | 4L | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0087 | Regulator | 666-2 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0087 | Regulator | 666-2 C | Regulator Patrol Inspection | General Comments | | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0087 | Regulator | 666-2 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0089 | Regulator | 666-2 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | YD000418 | Yard | 609-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | YD000338 | Yard | 666-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | YD000338 | Yard | 666-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | YD000338 | Yard | 666-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | YD000418 | Yard | 609-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/2/2023 13:16 | Distribution | Delaplain Quarterly Inspection | YD000418 | Yard | 609-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0089 | Regulator | 666-2 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0089 | Regulator | 666-2 A | Regulator Patrol Inspection | Reg Output Voltage Level | 125.0 | volts |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0089 | Regulator | 666-2 A | Regulator Patrol Inspection | Regulator As Left Counter | 41220 | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0089 | Regulator | 666-2 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | KR0089 | Regulator | 666-2 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 13:05 | Distribution | Oxford Quarterly Inspection | YD000338 | Yard | 666-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Readings | Oil Temp Present | 23 | °C |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/2/2023 10:17 | Distribution | KU Park-Greasy Creek Quarterly Inspection | KT0048 | NonLTC | 027-5 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0325 | RecloserElectronic | 538-0313 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0325 | RecloserElectronic | 538-0313 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0325 | RecloserElectronic | 538-0313 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0325 | RecloserElectronic | 538-0313 | Recloser Electronic Patrol Inspection | Operations Counter | 36 | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0325 | RecloserElectronic | 538-0313 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0325 | RecloserElectronic | 538-0313 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0325 | RecloserElectronic | 538-0313 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0325 | RecloserElectronic | 538-0313 | Recloser Electronic Patrol Inspection | General Comments | 1 fault wihtout lockout, BG | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0325 | RecloserElectronic | 538-0313 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 14:08 | Distribution | Stinking Creek Quarterly Inspection | MX0325 | RecloserElectronic | 538-0313 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Readings | General Comments | | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AF | 142 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Readings | Amps A Ø | 400.0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Readings | Amps B Ø | 320.0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Readings | Amps C Ø | 400.0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AL | 142 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Readings | Operations This Read Vac | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BB0474 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Readings | Oil Temp Max | 29 | °C |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0978 | Regulator | 321-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0978 | Regulator | 321-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0978 | Regulator | 321-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0978 | Regulator | 321-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0978 | Regulator | 321-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 54325 | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0978 | Regulator | 321-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 125.1 | volts |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0978 | Regulator | 321-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0978 | Regulator | 321-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0978 | Regulator | 321-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0978 | Regulator | 321-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0978 | Regulator | 321-1 A | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0978 | Regulator | 321-1 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0978 | Regulator | 321-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0978 | Regulator | 321-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0978 | Regulator | 321-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0978 | Regulator | 321-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0852 | Regulator | 800-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0978 | Regulator | 321-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0978 | Regulator | 321-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0978 | Regulator | 321-1 A | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0978 | Regulator | 321-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0978 | Regulator | 321-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0978 | Regulator | 321-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0978 | Regulator | 321-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0978 | Regulator | 321-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | ST000057 | Structure | 882-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | ST000057 | Structure | 882-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | ST000057 | Structure | 882-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | ST000057 | Structure | 882-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | ST000057 | Structure | 882-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | ST000057 | Structure | 882-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | ST000057 | Structure | 882-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | ST000057 | Structure | 882-Structure | Structure Patrol Inspection | General Comments | tower leg crumbling | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | ST000057 | Structure | 882-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | ST000057 | Structure | 882-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | ST000057 | Structure | 882-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0977 | Regulator | 321-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0977 | Regulator | 321-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | ST000057 | Structure | 882-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0852 | Regulator | 800-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0852 | Regulator | 800-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0852 | Regulator | 800-1 B | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0852 | Regulator | 800-1 B | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0852 | Regulator | 800-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0852 | Regulator | 800-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0852 | Regulator | 800-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0852 | Regulator | 800-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0852 | Regulator | 800-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.6 | volts |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0852 | Regulator | 800-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 310705 | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0852 | Regulator | 800-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | RC000166 | RecloserHydraulic | 800-0321 | Recloser Hydraulic Patrol Inspection | Operations Counter | 150 | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | RC000166 | RecloserHydraulic | 800-0321 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCC000580 | LTCControl | 695-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCC000580 | LTCControl | 695-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCC000580 | LTCControl | 695-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | RC000166 | RecloserHydraulic | 800-0321 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0126 | Regulator | 182-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0126 | Regulator | 182-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0734 | Regulator | 800-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0734 | Regulator | 800-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0734 | Regulator | 800-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0852 | Regulator | 800-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0852 | Regulator | 800-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0852 | Regulator | 800-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0852 | Regulator | 800-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0126 | Regulator | 182-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0126 | Regulator | 182-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0734 | Regulator | 800-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0734 | Regulator | 800-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | YD000052 | Yard | 882-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | YD000052 | Yard | 882-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | YD000052 | Yard | 882-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | YD000052 | Yard | 882-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | YD000052 | Yard | 882-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | YD000052 | Yard | 882-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0734 | Regulator | 800-1 A | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0734 | Regulator | 800-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0734 | Regulator | 800-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0734 | Regulator | 800-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0734 | Regulator | 800-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0734 | Regulator | 800-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | YD000052 | Yard | 882-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0852 | Regulator | 800-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0852 | Regulator | 800-1 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0852 | Regulator | 800-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0852 | Regulator | 800-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0852 | Regulator | 800-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | YD000052 | Yard | 882-Yard | Yard Patrol Inspection | General Comments | | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | YD000052 | Yard | 882-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | YD000052 | Yard | 882-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | YD000052 | Yard | 882-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | ST000057 | Structure | 882-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | ST000057 | Structure | 882-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Readings | 9 Month Operations | 4 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BAT001458 | Battery | 402-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 30 | °F |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BAT001458 | Battery | 402-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | CH000478 | ControlHouse | 855-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | CH000478 | ControlHouse | 855-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | CH000478 | ControlHouse | 855-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | CH000478 | ControlHouse | 855-Control House | Control House Patrol Inspection | Floor Swept? | n | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | CH000478 | ControlHouse | 855-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | CH000478 | ControlHouse | 855-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | CH000478 | ControlHouse | 855-Control House | Control House Patrol Inspection | General Comments | | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | CH000478 | ControlHouse | 855-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | CH000478 | ControlHouse | 855-Control House | Control House Patrol Inspection | Panel Lights OK? | n | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | CH000478 | ControlHouse | 855-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Readings | Operations This Read Vac | 1 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Readings | Operations Counter AL | 174 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Readings | Operations Counter AF | 174 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Readings | Totalizer Meter Reading | .9450 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | ST000553 | Structure | 649-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Readings | LTC Totalizer Reading | 4536.00 | kw |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | CH000478 | ControlHouse | 855-Control House | Control House Patrol Inspection | Station Ground Set On Site? | n | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0852 | Regulator | 800-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | ST000057 | Structure | 882-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | ST000057 | Structure | 882-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | ST000057 | Structure | 882-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | ST000057 | Structure | 882-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | ST000057 | Structure | 882-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | ST000057 | Structure | 882-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0852 | Regulator | 800-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | CH000478 | ControlHouse | 855-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | CH000478 | ControlHouse | 855-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | CH000478 | ControlHouse | 855-Control House | Control House Patrol Inspection | Broom on Site? | n | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | CH000478 | ControlHouse | 855-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | CH000478 | ControlHouse | 855-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | ST000057 | Structure | 882-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | ST000057 | Structure | 882-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | ST000553 | Structure | 649-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | ST000553 | Structure | 649-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | ST000553 | Structure | 649-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | ST000553 | Structure | 649-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | ST000553 | Structure | 649-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | ST000553 | Structure | 649-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Readings | LTC Totalizer Reading | 5884.80 | kw |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | CH000478 | ControlHouse | 855-Control House | Control House Patrol Inspection | Door Alarms OK? | n | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | CH000478 | ControlHouse | 855-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Readings | General Comments | | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BAT001458 | Battery | 402-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BAT001458 | Battery | 402-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BAT001458 | Battery | 402-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BAT001458 | Battery | 402-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BAT001458 | Battery | 402-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BAT001458 | Battery | 402-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BAT001458 | Battery | 402-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BAT001458 | Battery | 402-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BAT001458 | Battery | 402-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BAT001458 | Battery | 402-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Readings | Operations This Read Vac | 2 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Readings | Operations Counter AL | 184 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BAT001458 | Battery | 402-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BAT001458 | Battery | 402-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Readings | Operations Counter AF | 184 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Readings | 9 Month Operations | 4 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Readings | General Comments | | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | YD000052 | Yard | 882-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | YD000052 | Yard | 882-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0734 | Regulator | 800-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0734 | Regulator | 800-1 A | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0734 | Regulator | 800-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0734 | Regulator | 800-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0734 | Regulator | 800-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0734 | Regulator | 800-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0734 | Regulator | 800-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0734 | Regulator | 800-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 42754 | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0734 | Regulator | 800-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0734 | Regulator | 800-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0734 | Regulator | 800-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Readings | Amps C Ø | 60.0 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Readings | Amps B Ø | 90.0 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Readings | Amps A Ø | 65.0 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Readings | Fault Adjusted Amps C Phase V | 11.99 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BAT001100 | Battery | 350-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Readings | Operations Counter AF | 292 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Readings | Operations Counter AL | 294 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BAT001100 | Battery | 350-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BAT001100 | Battery | 350-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.7 | VDC |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BAT001100 | Battery | 350-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.3 | VDC |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BAT001100 | Battery | 350-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BAT001100 | Battery | 350-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCC000580 | LTCControl | 695-1 | LTC Control Insp | General Comments | | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Readings | Operations This Read Vac | 2 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Readings | Switching Operations | 2 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BAT001100 | Battery | 350-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BAT001100 | Battery | 350-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BAT001100 | Battery | 350-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BAT001100 | Battery | 350-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BAT001100 | Battery | 350-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BAT001100 | Battery | 350-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BAT001100 | Battery | 350-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 45 | °F |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BAT001100 | Battery | 350-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | MX0452 | RecloserHydraulic | 503-4330 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | MX0452 | RecloserHydraulic | 503-4330 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0.0 | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | MX0452 | RecloserHydraulic | 503-4330 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | MX0452 | RecloserHydraulic | 503-4330 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | MX0452 | RecloserHydraulic | 503-4330 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | MX0452 | RecloserHydraulic | 503-4330 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | MX0452 | RecloserHydraulic | 503-4330 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | MX0452 | RecloserHydraulic | 503-4330 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | MX0452 | RecloserHydraulic | 503-4330 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | MX0452 | RecloserHydraulic | 503-4330 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | MX0452 | RecloserHydraulic | 503-4330 | Recloser Hydraulic Patrol Inspection | Operations Counter | 145 | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | MX0452 | RecloserHydraulic | 503-4330 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | MX0452 | RecloserHydraulic | 503-4330 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCC000580 | LTCControl | 695-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCC000580 | LTCControl | 695-1 | LTC Control Insp | All Connections OK? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Readings | Oil Temp Present | 17 | °C |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 894.24 | kw |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Patrol Inspection | General Comments | added nitrogen | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Readings | General Comments | | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCC000580 | LTCControl | 695-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCC000580 | LTCControl | 695-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCC000580 | LTCControl | 695-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Readings | Amps C Ø | 212.0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Readings | Amps B Ø | 186.0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Readings | Amps A Ø | 235.0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Readings | Totalizer Meter Reading | .6130 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | WithLTC | 780-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0734 | Regulator | 800-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | RC000166 | RecloserHydraulic | 800-0321 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0126 | Regulator | 182-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0126 | Regulator | 182-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0126 | Regulator | 182-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0126 | Regulator | 182-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0126 | Regulator | 182-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 45258 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0126 | Regulator | 182-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0126 | Regulator | 182-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0126 | Regulator | 182-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0126 | Regulator | 182-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0126 | Regulator | 182-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0126 | Regulator | 182-1 B | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0126 | Regulator | 182-1 B | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0126 | Regulator | 182-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Readings | Fault Operations C Ø | 2 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | K0188 | BreakerVacuum | 563-0867 | VCB Readings | 9 Month Operations | 6 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001151 | BreakerVacuum | 402-0501 | VCB Readings | General Comments | | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Readings | General Comments | | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0126 | Regulator | 182-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0126 | Regulator | 182-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0126 | Regulator | 182-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | WithLTC | 602-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0126 | Regulator | 182-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0126 | Regulator | 182-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0126 | Regulator | 182-1 B | Regulator Patrol Inspection | Current Tap Position | 3R | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0126 | Regulator | 182-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | RC000166 | RecloserHydraulic | 800-0321 | Recloser Hydraulic Patrol Inspection | Amps A Ø | .5 | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | RC000166 | RecloserHydraulic | 800-0321 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 13.0 | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | RC000166 | RecloserHydraulic | 800-0321 | Recloser Hydraulic Patrol Inspection | Amps C Ø | .4 | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | RC000166 | RecloserHydraulic | 800-0321 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | RC000166 | RecloserHydraulic | 800-0321 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | RC000166 | RecloserHydraulic | 800-0321 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | RC000166 | RecloserHydraulic | 800-0321 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | RC000166 | RecloserHydraulic | 800-0321 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | RC000166 | RecloserHydraulic | 800-0321 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .3726 | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | C0331 | NonLTC | 321-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | LTCMechanism | 838-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | LTCMechanism | 838-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | LTCMechanism | 838-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Readings | Operations Counter AL | 254 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Readings | Operations Counter AF | 254 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Readings | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Readings | Amps C Ø | 680.0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Readings | Amps B Ø | 640.0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Readings | Amps A Ø | 680.0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | FE000886 | Fence | 855-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | FE000886 | Fence | 855-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | FE000886 | Fence | 855-Fence | Fence Patrol Inspection | General Comments | | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | FE000886 | Fence | 855-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | FE000886 | Fence | 855-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | FE000886 | Fence | 855-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | FE000886 | Fence | 855-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | FE000886 | Fence | 855-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | FE000886 | Fence | 855-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | FE000886 | Fence | 855-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | FE000886 | Fence | 855-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | FE000886 | Fence | 855-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | FE000886 | Fence | 855-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | FE000886 | Fence | 855-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | FE000886 | Fence | 855-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | FE000886 | Fence | 855-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0854 | Regulator | 800-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | LTCC000821 | LTCControl | 780-3 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | LTCC000821 | LTCControl | 780-3 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | LTCC000821 | LTCControl | 780-3 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | LTCC000821 | LTCControl | 780-3 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BCH001346 | Charger | 882-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BCH001346 | Charger | 882-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BCH001346 | Charger | 882-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BCH001346 | Charger | 882-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BCH001346 | Charger | 882-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.1 | amps |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BCH001346 | Charger | 882-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BCH001346 | Charger | 882-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Readings | Amps C Ø | 256.0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Readings | Amps B Ø | 294.0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Readings | Amps A Ø | 364.0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Readings | 9 Month Operations | 1 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BCH001346 | Charger | 882-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.800 | millivolts |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | LTCMechanism | 838-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | LTCMechanism | 838-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | LTCMechanism | 838-1 | LTC Counter Readings | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | LTCMechanism | 838-1 | LTC Mechanism Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | LTCMechanism | 838-1 | LTC Counter Readings | LTC As Found Counter | 57347 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | LTCMechanism | 838-1 | LTC Counter Readings | LTC As Left Counter | 57347 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | LTCMechanism | 838-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | LTCMechanism | 838-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | LTCMechanism | 838-1 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | LTCMechanism | 838-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | LTCMechanism | 838-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | LTCMechanism | 838-1 | LTC Counter Readings | LTC Operations Since Last Insp | 443 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | LTCMechanism | 838-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | YD000438 | Yard | 592-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | YD000438 | Yard | 592-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | YD000438 | Yard | 592-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | YD000438 | Yard | 592-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | ST000068 | Structure | 504-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | ST000068 | Structure | 504-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | ST000068 | Structure | 504-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | ST000068 | Structure | 504-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | ST000068 | Structure | 504-Structure | Structure Patrol Inspection | General Comments | | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | ST000068 | Structure | 504-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | ST000068 | Structure | 504-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | ST000068 | Structure | 504-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | ST000068 | Structure | 504-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | ST000068 | Structure | 504-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | ST000068 | Structure | 504-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | ST000068 | Structure | 504-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | ST000068 | Structure | 504-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | ST000068 | Structure | 504-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | ST000068 | Structure | 504-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | ST000068 | Structure | 504-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | ST000068 | Structure | 504-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | FE000355 | Fence | 522-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | FE000355 | Fence | 522-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | FE000355 | Fence | 522-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | FE000355 | Fence | 522-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | FE000355 | Fence | 522-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | FE000355 | Fence | 522-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | FE000355 | Fence | 522-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | FE000355 | Fence | 522-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | FE000355 | Fence | 522-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | FE000355 | Fence | 522-Fence | Fence Patrol Inspection | General Comments | | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | FE000355 | Fence | 522-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | FE000355 | Fence | 522-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | YD000361 | Yard | 522-Yard | Yard Patrol Inspection | Ambient Temp | 25 | °F |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | YD000361 | Yard | 522-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | YD000361 | Yard | 522-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | YD000361 | Yard | 522-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | YD000361 | Yard | 522-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | YD000361 | Yard | 522-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0854 | Regulator | 800-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0854 | Regulator | 800-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0854 | Regulator | 800-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 293747 | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0854 | Regulator | 800-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0854 | Regulator | 800-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0854 | Regulator | 800-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0854 | Regulator | 800-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0854 | Regulator | 800-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0854 | Regulator | 800-1 C | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0854 | Regulator | 800-1 C | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0854 | Regulator | 800-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0854 | Regulator | 800-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0854 | Regulator | 800-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0854 | Regulator | 800-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0854 | Regulator | 800-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0854 | Regulator | 800-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0854 | Regulator | 800-1 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0854 | Regulator | 800-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0854 | Regulator | 800-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0854 | Regulator | 800-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0854 | Regulator | 800-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | R0854 | Regulator | 800-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0368 | BreakerVacuum | 838-2 | VCB Readings | 9 Month Operations | 0 | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | ST000068 | Structure | 504-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | ST000068 | Structure | 504-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | ST000068 | Structure | 504-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | ST000068 | Structure | 504-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | FE000355 | Fence | 522-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | FE000355 | Fence | 522-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | FE000355 | Fence | 522-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | FE000355 | Fence | 522-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | YD000438 | Yard | 592-Yard | Yard Patrol Inspection | Ambient Temp | 27 | °F |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | YD000438 | Yard | 592-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | YD000438 | Yard | 592-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | YD000438 | Yard | 592-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | YD000438 | Yard | 592-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | YD000438 | Yard | 592-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | YD000438 | Yard | 592-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | YD000438 | Yard | 592-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | YD000438 | Yard | 592-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | YD000438 | Yard | 592-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | YD000438 | Yard | 592-Yard | Yard Patrol Inspection | General Comments | | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | LTCM000091 | LTCMechanism | 450-1 | LTC Counter Readings | LTC As Found Counter | 6415 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | LTCM000091 | LTCMechanism | 450-1 | LTC Counter Readings | LTC As Left Counter | 6415 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | LTCM000091 | LTCMechanism | 450-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | LTCM000091 | LTCMechanism | 450-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | LTCM000091 | LTCMechanism | 450-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | LTCM000091 | LTCMechanism | 450-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | LTCM000091 | LTCMechanism | 450-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | LTCM000091 | LTCMechanism | 450-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | LTCM000091 | LTCMechanism | 450-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 10 | °C |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | LTCM000091 | LTCMechanism | 450-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 5 | °C |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | LTCM000091 | LTCMechanism | 450-1 | LTC Counter Readings | LTC Operations Since Last Insp | 380 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | LTCM000091 | LTCMechanism | 450-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | LTCM000091 | LTCMechanism | 450-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | LTCM000091 | LTCMechanism | 450-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | LTCM000091 | LTCMechanism | 450-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | CH000232 | ControlHouse | 350-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | CH000232 | ControlHouse | 350-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | CH000232 | ControlHouse | 350-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | CH000232 | ControlHouse | 350-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | CH000232 | ControlHouse | 350-Control House | Control House Patrol Inspection | General Comments | | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | CH000232 | ControlHouse | 350-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | CH000232 | ControlHouse | 350-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | CH000232 | ControlHouse | 350-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | CH000232 | ControlHouse | 350-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | CH000232 | ControlHouse | 350-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | CH000232 | ControlHouse | 350-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | CH000232 | ControlHouse | 350-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | CH000232 | ControlHouse | 350-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | CH000232 | ControlHouse | 350-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | CH000232 | ControlHouse | 350-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | CH000232 | ControlHouse | 350-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | CH000232 | ControlHouse | 350-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BAT001547 | Battery | 780-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BAT001547 | Battery | 780-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BAT001547 | Battery | 780-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BAT001547 | Battery | 780-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BAT001547 | Battery | 780-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BAT001547 | Battery | 780-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BAT001547 | Battery | 780-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BAT001547 | Battery | 780-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BAT001547 | Battery | 780-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Exp/Missing Not Repl | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BAT001547 | Battery | 780-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BAT001547 | Battery | 780-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BAT001547 | Battery | 780-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BAT001547 | Battery | 780-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BAT001547 | Battery | 780-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BAT001547 | Battery | 780-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BCH001352 | Charger | 780-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BCH001352 | Charger | 780-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BCH001352 | Charger | 780-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BCH001371 | Charger | 402-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Readings | General Comments | | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Readings | Operations Counter AF | 142 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Readings | Operations Counter AL | 142 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BCH001371 | Charger | 402-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BCH001371 | Charger | 402-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | SWG000226 | Switchgear | 695-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | SWG000226 | Switchgear | 695-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | SWG000226 | Switchgear | 695-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | LTCC000802 | LTCControl | 450-1 | LTC Control Insp | All Connections OK? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | LTCC000802 | LTCControl | 450-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | LTCC000802 | LTCControl | 450-1 | LTC Control Insp | General Comments | | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | LTCC000802 | LTCControl | 450-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | LTCC000802 | LTCControl | 450-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | LTCC000802 | LTCControl | 450-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | LTCC000802 | LTCControl | 450-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | LTCC000802 | LTCControl | 450-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | SWG000226 | Switchgear | 695-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | SWG000226 | Switchgear | 695-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | SWG000226 | Switchgear | 695-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | SWG000226 | Switchgear | 695-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | SWG000226 | Switchgear | 695-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | SWG000226 | Switchgear | 695-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | SWG000226 | Switchgear | 695-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | SWG000226 | Switchgear | 695-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | SWG000226 | Switchgear | 695-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | SWG000226 | Switchgear | 695-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | SWG000226 | Switchgear | 695-Swgr Sec 2 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | SWG000226 | Switchgear | 695-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | SWG000226 | Switchgear | 695-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | SWG000226 | Switchgear | 695-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | SWG000226 | Switchgear | 695-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | LTCM000091 | LTCMechanism | 450-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | LTCM000091 | LTCMechanism | 450-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | LTCM000091 | LTCMechanism | 450-1 | LTC Counter Readings | General Comments | | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | LTCM000091 | LTCMechanism | 450-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Readings | General Comments | | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Readings | LTC Totalizer Reading | 2406.24 | kw |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | ST000175 | Structure | 380-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | ST000175 | Structure | 380-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | ST000175 | Structure | 380-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Readings | Oil Temp Max | 42 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Readings | Oil Temp Present | 50 | °C |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.0026 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | YD000168 | Yard | 380-Yard | Yard Patrol Inspection | Ambient Temp | 32 | °F |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | YD000168 | Yard | 380-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | YD000168 | Yard | 380-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | YD000168 | Yard | 380-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | YD000168 | Yard | 380-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | YD000168 | Yard | 380-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | YD000168 | Yard | 380-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | YD000168 | Yard | 380-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | YD000168 | Yard | 380-Yard | Yard Patrol Inspection | General Comments | | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | YD000168 | Yard | 380-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | YD000168 | Yard | 380-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | YD000168 | Yard | 380-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Readings | Operations This Read Vac | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Readings | Operations Counter AL | 185 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Readings | Operations Counter AF | 185 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Readings | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | LTCC000821 | LTCControl | 780-3 | LTC Control Insp | All Connections OK? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | LTCC000821 | LTCControl | 780-3 | LTC Control Insp | General Comments | | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | LTCC000821 | LTCControl | 780-3 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BCH001352 | Charger | 780-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BCH001352 | Charger | 780-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 3.1 | amps |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BCH001352 | Charger | 780-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BCH001352 | Charger | 780-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BCH001352 | Charger | 780-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.900 | millivolts |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BCH001479 | Charger | 350-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.900 | millivolts |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BCH001479 | Charger | 350-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BCH001479 | Charger | 350-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BCH001479 | Charger | 350-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.0 | amps |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BCH001479 | Charger | 350-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BCH001479 | Charger | 350-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BCH001479 | Charger | 350-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BCH001479 | Charger | 350-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001155 | BreakerVacuum | 838-0509 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | LTCC000989 | LTCControl | 780-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | LTCC000989 | LTCControl | 780-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | LTCC000989 | LTCControl | 780-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | LTCC000989 | LTCControl | 780-2 | LTC Control Insp | LTC Output Voltage Level | 124.6 | VAC |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | LTCC000989 | LTCControl | 780-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | LTCC000989 | LTCControl | 780-2 | LTC Control Insp | General Comments | | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | LTCC000989 | LTCControl | 780-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | LTCC000989 | LTCControl | 780-2 | LTC Control Insp | All Connections OK? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | ST000175 | Structure | 380-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | ST000175 | Structure | 380-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | ST000175 | Structure | 380-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | ST000175 | Structure | 380-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | ST000175 | Structure | 380-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | ST000175 | Structure | 380-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | ST000175 | Structure | 380-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | ST000175 | Structure | 380-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | ST000175 | Structure | 380-Structure | Structure Patrol Inspection | General Comments | | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | ST000175 | Structure | 380-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | ST000175 | Structure | 380-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | ST000175 | Structure | 380-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | ST000175 | Structure | 380-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | ST000175 | Structure | 380-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | ST000175 | Structure | 380-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | ST000175 | Structure | 380-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | ST000175 | Structure | 380-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | ST000175 | Structure | 380-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | WithLTC | 592-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | SWG000217 | Switchgear | 450-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | SWG000217 | Switchgear | 450-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | SWG000217 | Switchgear | 450-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | SWG000217 | Switchgear | 450-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | SWG000217 | Switchgear | 450-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | SWG000217 | Switchgear | 450-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | SWG000217 | Switchgear | 450-Swgr Sec 1 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | SWG000217 | Switchgear | 450-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | SWG000217 | Switchgear | 450-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | SWG000217 | Switchgear | 450-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | SWG000217 | Switchgear | 450-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001409 | Battery | 182-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001409 | Battery | 182-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 58 | °F |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001409 | Battery | 182-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001409 | Battery | 182-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001409 | Battery | 182-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001409 | Battery | 182-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001409 | Battery | 182-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001409 | Battery | 182-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001409 | Battery | 182-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001409 | Battery | 182-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001409 | Battery | 182-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 67.8 | VDC |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001409 | Battery | 182-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 65.8 | VDC |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001409 | Battery | 182-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001409 | Battery | 182-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | FE000064 | Fence | 380-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | FE000064 | Fence | 380-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | n | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | FE000064 | Fence | 380-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | FE000064 | Fence | 380-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | FE000064 | Fence | 380-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | FE000064 | Fence | 380-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | FE000064 | Fence | 380-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | FE000064 | Fence | 380-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | FE000064 | Fence | 380-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | FE000064 | Fence | 380-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | FE000064 | Fence | 380-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | FE000064 | Fence | 380-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | FE000064 | Fence | 380-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | FE000064 | Fence | 380-Fence | Fence Patrol Inspection | General Comments | | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | FE000064 | Fence | 380-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | FE000064 | Fence | 380-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BCH001328 | Charger | 182-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 2.400 | millivolts |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BCH001328 | Charger | 182-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 134.4 | VDC |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BCH001328 | Charger | 182-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 134.4 | VDC |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BCH001328 | Charger | 182-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .6 | amps |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BCH001328 | Charger | 182-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BCH001328 | Charger | 182-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BCH001328 | Charger | 182-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | FE000065 | Fence | 321-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | FE000065 | Fence | 321-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | n | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Readings | General Comments | | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Readings | Operations Counter AF | 109 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Readings | Operations Counter AL | 109 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Readings | Operations This Read Vac | 1 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Readings | Switching Operations | 1 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | MOD Motor Jaw Coupling | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | MOD Cabinet Internals Clean? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | MOD Cabinet Heater functional? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | General Comments | | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | SWG000217 | Switchgear | 450-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | SWG000217 | Switchgear | 450-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | SWG000217 | Switchgear | 450-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | SWG000217 | Switchgear | 450-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | SWG000217 | Switchgear | 450-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | SWG000217 | Switchgear | 450-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | SWG000217 | Switchgear | 450-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | SWG000217 | Switchgear | 450-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | SWG000217 | Switchgear | 450-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | ST000072 | Structure | 321-Structure | Structure Patrol Inspection | General Comments | | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | ST000072 | Structure | 321-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | ST000072 | Structure | 321-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | ST000072 | Structure | 321-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | ST000072 | Structure | 321-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | ST000072 | Structure | 321-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | ST000072 | Structure | 321-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | ST000072 | Structure | 321-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | ST000072 | Structure | 321-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | ST000072 | Structure | 321-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | ST000072 | Structure | 321-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Readings | Winding Temp Present | 22 | °C |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0239 | NonLTC | 314-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0239 | NonLTC | 314-1 | NonLTC Transformer Readings | Oil Temp Max | 30 | °C |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0239 | NonLTC | 314-1 | NonLTC Transformer Readings | Oil Temp Present | 19 | °C |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0239 | NonLTC | 314-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0239 | NonLTC | 314-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0239 | NonLTC | 314-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0239 | NonLTC | 314-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0239 | NonLTC | 314-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0239 | NonLTC | 314-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0239 | NonLTC | 314-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0239 | NonLTC | 314-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .2150 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | CH000478 | ControlHouse | 855-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | CH000478 | ControlHouse | 855-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | CH000478 | ControlHouse | 855-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | CH000478 | ControlHouse | 855-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Readings | Winding Temp Max | 22 | °C |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Readings | Totalizer Meter Reading | .9340 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Readings | Oil Temp Present | 21 | °C |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Readings | Oil Temp Max | 21 | °C |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1800 | psi |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Readings | LTC Totalizer Reading | 22416.00 | kw |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Readings | General Comments | | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | TX000282 | WithLTC | 695-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | FE000065 | Fence | 321-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | FE000065 | Fence | 321-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | FE000065 | Fence | 321-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | FE000065 | Fence | 321-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | FE000065 | Fence | 321-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | FE000065 | Fence | 321-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | FE000065 | Fence | 321-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | FE000065 | Fence | 321-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | n | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | FE000065 | Fence | 321-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | FE000065 | Fence | 321-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | FE000065 | Fence | 321-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | FE000065 | Fence | 321-Fence | Fence Patrol Inspection | General Comments | | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | FE000065 | Fence | 321-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | FE000065 | Fence | 321-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | YD000064 | Yard | 321-Yard | Yard Patrol Inspection | Ambient Temp | 32 | °F |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | YD000064 | Yard | 321-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | YD000064 | Yard | 321-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | YD000064 | Yard | 321-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | YD000064 | Yard | 321-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | YD000064 | Yard | 321-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | YD000064 | Yard | 321-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | YD000064 | Yard | 321-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | YD000064 | Yard | 321-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | YD000064 | Yard | 321-Yard | Yard Patrol Inspection | General Comments | | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | YD000064 | Yard | 321-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | YD000064 | Yard | 321-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | YD000064 | Yard | 321-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | ST000072 | Structure | 321-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | ST000072 | Structure | 321-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | ST000072 | Structure | 321-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | ST000072 | Structure | 321-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | ST000072 | Structure | 321-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | ST000072 | Structure | 321-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0239 | NonLTC | 314-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0239 | NonLTC | 314-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0239 | NonLTC | 314-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0239 | NonLTC | 314-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0239 | NonLTC | 314-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0239 | NonLTC | 314-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0239 | NonLTC | 314-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0239 | NonLTC | 314-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0239 | NonLTC | 314-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0239 | NonLTC | 314-1 | NonLTC Transformer Readings | General Comments | | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0239 | NonLTC | 314-1 | NonLTC Transformer Patrol Inspection | General Comments | added nitrogen | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0239 | NonLTC | 314-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0239 | NonLTC | 314-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0239 | NonLTC | 314-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0239 | NonLTC | 314-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 516.00 | kw |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0239 | NonLTC | 314-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | ST000072 | Structure | 321-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | ST000072 | Structure | 321-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | YD000361 | Yard | 522-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | YD000361 | Yard | 522-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | YD000361 | Yard | 522-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | YD000361 | Yard | 522-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | ST000082 | Structure | 182-Structure | Structure Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Readings | 9 Month Operations | 3 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Readings | Amps A Ø | 90.0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Readings | Amps B Ø | 81.0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Readings | Amps C Ø | 78.0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Readings | General Comments | | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | LTCMechanism | 592-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | LTCMechanism | 592-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | LTCMechanism | 592-1 | LTC Counter Readings | General Comments | | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | LTCMechanism | 592-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | LTCMechanism | 592-1 | LTC Counter Readings | LTC As Found Counter | 89951 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | LTCMechanism | 592-1 | LTC Counter Readings | LTC As Left Counter | 89951 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | LTCMechanism | 592-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | LTCMechanism | 592-1 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | LTCMechanism | 592-1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | LTCMechanism | 592-1 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | LTCMechanism | 592-1 | LTC Counter Readings | LTC Operations Since Last Insp | 711 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | LTCMechanism | 592-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | LTCMechanism | 592-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | C0438 | LTCMechanism | 592-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Readings | Operations Counter AF | 60 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | YD000361 | Yard | 522-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | YD000361 | Yard | 522-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | YD000361 | Yard | 522-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Readings | General Comments | | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Readings | LTC Totalizer Reading | 33194.88 | kw |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Readings | Totalizer Meter Reading | 2.3052 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCM000120 | LTCMechanism | 695-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCM000120 | LTCMechanism | 695-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCM000120 | LTCMechanism | 695-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCM000120 | LTCMechanism | 695-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCM000120 | LTCMechanism | 695-2 | LTC Counter Readings | LTC Operations Since Last Insp | 424 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCM000120 | LTCMechanism | 695-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 21 | °C |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCM000120 | LTCMechanism | 695-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 21 | °C |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCM000120 | LTCMechanism | 695-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCM000120 | LTCMechanism | 695-2 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCM000120 | LTCMechanism | 695-2 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCM000120 | LTCMechanism | 695-2 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCM000120 | LTCMechanism | 695-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCM000120 | LTCMechanism | 695-2 | LTC Counter Readings | LTC As Left Counter | 5283 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCM000120 | LTCMechanism | 695-2 | LTC Counter Readings | LTC As Found Counter | 5283 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCM000120 | LTCMechanism | 695-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCM000120 | LTCMechanism | 695-2 | LTC Counter Readings | General Comments | | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCM000120 | LTCMechanism | 695-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCM000120 | LTCMechanism | 695-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Readings | Winding Temp Max | 90 | °C |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Readings | Winding Temp Present | 50 | °C |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | WithLTC | 402-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | YD000361 | Yard | 522-Yard | Yard Patrol Inspection | General Comments | | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Readings | General Comments | | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Readings | LTC Totalizer Reading | 38.40 | kw |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Readings | Oil Temp Max | 39 | °C |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Readings | Oil Temp Present | 24 | °C |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Readings | Totalizer Meter Reading | .0080 | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Readings | 9 Month Operations | 4 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCC000917 | LTCControl | 695-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCC000917 | LTCControl | 695-2 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCC000917 | LTCControl | 695-2 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCC000917 | LTCControl | 695-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCC000917 | LTCControl | 695-2 | LTC Control Insp | General Comments | | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCC000917 | LTCControl | 695-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCC000917 | LTCControl | 695-2 | LTC Control Insp | All Connections OK? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Readings | Amps A Ø | 18.0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Readings | Amps B Ø | 37.0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Readings | Amps C Ø | 46.0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001387 | BreakerVacuum | 450-0519 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Readings | Operations Counter AL | 60 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Readings | Operations This Read Vac | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001385 | BreakerVacuum | 450-0517 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Readings | 9 Month Operations | 3 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Readings | Amps A Ø | 146.0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Readings | Amps B Ø | 180.0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Readings | Amps C Ø | 175.0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Readings | General Comments | | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Readings | Operations Counter AF | 193 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Readings | Operations Counter AL | 193 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Readings | Operations This Read Vac | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001386 | BreakerVacuum | 450-0518 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCC000917 | LTCControl | 695-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | LTCC000917 | LTCControl | 695-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | WithLTC | 503-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Readings | General Comments | | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | YD000026 | Yard | 381-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | YD000026 | Yard | 381-Yard | Yard Patrol Inspection | General Comments | | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | YD000026 | Yard | 381-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | YD000026 | Yard | 381-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | YD000026 | Yard | 381-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | YD000026 | Yard | 381-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | YD000026 | Yard | 381-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | YD000026 | Yard | 381-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | YD000026 | Yard | 381-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | YD000026 | Yard | 381-Yard | Yard Patrol Inspection | Ambient Temp | 32 | °F |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Readings | Operations Counter AF | 421 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Readings | Operations Counter AL | 421 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Readings | Operations This Read Vac | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Readings | Unknown Operations | 0 | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | FE000031 | Fence | 381-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | FE000031 | Fence | 381-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | FE000031 | Fence | 381-Fence | Fence Patrol Inspection | General Comments | | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | FE000031 | Fence | 381-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | FE000031 | Fence | 381-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | FE000031 | Fence | 381-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | FE000031 | Fence | 381-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | FE000031 | Fence | 381-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | FE000031 | Fence | 381-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | FE000031 | Fence | 381-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | FE000031 | Fence | 381-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | FE000031 | Fence | 381-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | FE000031 | Fence | 381-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | FE000031 | Fence | 381-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | FE000031 | Fence | 381-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | FE000031 | Fence | 381-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | LTCC000071 | LTCControl | 838-1 | LTC Control Insp | All Connections OK? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | LTCC000071 | LTCControl | 838-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | LTCC000071 | LTCControl | 838-1 | LTC Control Insp | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | LTCC000071 | LTCControl | 838-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | X0073 | RecloserHydraulic | 800-0322 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 33.0 | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | X0073 | RecloserHydraulic | 800-0322 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | X0073 | RecloserHydraulic | 800-0322 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | X0073 | RecloserHydraulic | 800-0322 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | X0073 | RecloserHydraulic | 800-0322 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | X0073 | RecloserHydraulic | 800-0322 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | X0073 | RecloserHydraulic | 800-0322 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | X0073 | RecloserHydraulic | 800-0322 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | X0073 | RecloserHydraulic | 800-0322 | Recloser Hydraulic Patrol Inspection | Operations Counter | 626 | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | X0073 | RecloserHydraulic | 800-0322 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | X0073 | RecloserHydraulic | 800-0322 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Readings | General Comments | | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Readings | LTC Totalizer Reading | 2508.80 | kw |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Readings | Totalizer Meter Reading | .7840 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | WithLTC | 649-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Readings | 9 Month Operations | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Readings | Amps A Ø | 350.0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Readings | Amps B Ø | 367.0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Readings | Amps C Ø | 380.0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0434 | BreakerVacuum | 838-0510 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 21000 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .2838 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Readings | Winding Temp Max | 33 | °C |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Readings | Winding Temp Present | 21 | °C |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | LTCMechanism | 838-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | LTCMechanism | 838-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | LTCMechanism | 838-2 | LTC Counter Readings | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | LTCMechanism | 838-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | LTCMechanism | 838-2 | LTC Counter Readings | LTC As Found Counter | 102021 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | LTCMechanism | 838-2 | LTC Counter Readings | LTC As Left Counter | 102021 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | LTCMechanism | 838-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | LTCMechanism | 838-2 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | LTCMechanism | 838-2 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | LTCMechanism | 838-2 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | LTCMechanism | 838-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | LTCMechanism | 838-2 | LTC Counter Readings | LTC Operations Since Last Insp | 507 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | LTCMechanism | 838-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | LTCMechanism | 838-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | LTCMechanism | 838-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Readings | 9 Month Operations | 3 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Readings | Amps A Ø | 236.0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Readings | Amps B Ø | 253.0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Readings | Amps C Ø | 214.0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | LTCMechanism | 314-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | LTCMechanism | 314-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | LTCMechanism | 314-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | LTCMechanism | 314-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | LTCMechanism | 314-2 | LTC Counter Readings | LTC Operations Since Last Insp | 669 | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | LTCMechanism | 314-2 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | LTCMechanism | 314-2 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | LTCMechanism | 314-2 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | LTCMechanism | 314-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | LTCMechanism | 314-2 | LTC Counter Readings | LTC As Left Counter | 10244 | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | LTCMechanism | 314-2 | LTC Counter Readings | LTC As Found Counter | 10241 | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | LTCMechanism | 314-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | LTCMechanism | 314-2 | LTC Counter Readings | General Comments | | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | LTCMechanism | 314-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | LTCMechanism | 314-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | LTCMechanism | 882-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | LTCMechanism | 882-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | LTCMechanism | 882-1 | LTC Counter Readings | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | LTCC000071 | LTCControl | 838-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | LTCC000071 | LTCControl | 838-1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | LTCC000071 | LTCControl | 838-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | LTCC000071 | LTCControl | 838-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | LTCC000071 | LTCControl | 838-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | CH000405 | ControlHouse | 882-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | CH000405 | ControlHouse | 882-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | CH000405 | ControlHouse | 882-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | CH000405 | ControlHouse | 882-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | CH000405 | ControlHouse | 882-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | CH000405 | ControlHouse | 882-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | CH000405 | ControlHouse | 882-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | CH000405 | ControlHouse | 882-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | CH000405 | ControlHouse | 882-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | CH000405 | ControlHouse | 882-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | CH000405 | ControlHouse | 882-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | CH000405 | ControlHouse | 882-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | CH000405 | ControlHouse | 882-Control House | Control House Patrol Inspection | General Comments | | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | CH000405 | ControlHouse | 882-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | CH000405 | ControlHouse | 882-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | CH000405 | ControlHouse | 882-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | CH000405 | ControlHouse | 882-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Readings | General Comments | | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Patrol Inspection | General Comments | will make an mxorder to replace the nitrogen bottle | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 100 | psi |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 5959.80 | kw |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Readings | Oil Temp Max | 31 | °C |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | TX000076 | NonLTC | 182-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0070 | Regulator | 350-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0070 | Regulator | 350-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0070 | Regulator | 350-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0070 | Regulator | 350-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | ST000417 | Structure | 695-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | ST000417 | Structure | 695-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | ST000417 | Structure | 695-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | ST000417 | Structure | 695-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | ST000417 | Structure | 695-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | ST000417 | Structure | 695-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | ST000417 | Structure | 695-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | ST000417 | Structure | 695-Structure | Structure Patrol Inspection | General Comments | | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | ST000417 | Structure | 695-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | ST000417 | Structure | 695-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | ST000417 | Structure | 695-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | ST000417 | Structure | 695-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | ST000417 | Structure | 695-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | ST000417 | Structure | 695-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | ST000417 | Structure | 695-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | ST000417 | Structure | 695-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | ST000417 | Structure | 695-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | YD000415 | Yard | 695-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | YD000415 | Yard | 695-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | YD000415 | Yard | 695-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | YD000415 | Yard | 695-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | YD000415 | Yard | 695-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | YD000415 | Yard | 695-Yard | Yard Patrol Inspection | General Comments | | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | YD000415 | Yard | 695-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | YD000415 | Yard | 695-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | YD000415 | Yard | 695-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | YD000415 | Yard | 695-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | YD000415 | Yard | 695-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | YD000415 | Yard | 695-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | YD000415 | Yard | 695-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | YD000415 | Yard | 695-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | YD000415 | Yard | 695-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | YD000415 | Yard | 695-Yard | Yard Patrol Inspection | Ambient Temp | 28 | °F |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | FE000408 | Fence | 695-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | FE000408 | Fence | 695-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | FE000408 | Fence | 695-Fence | Fence Patrol Inspection | General Comments | | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | FE000408 | Fence | 695-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | FE000408 | Fence | 695-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | FE000408 | Fence | 695-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | FE000408 | Fence | 695-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | FE000408 | Fence | 695-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | FE000408 | Fence | 695-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | FE000408 | Fence | 695-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | FE000408 | Fence | 695-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | FE000408 | Fence | 695-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | FE000408 | Fence | 695-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | FE000408 | Fence | 695-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Readings | General Comments | | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Readings | Operations Counter AF | 260 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Readings | Operations Counter AL | 261 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Readings | Operations This Read Vac | 1 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Readings | Switching Operations | 1 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | ST000417 | Structure | 695-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | ST000417 | Structure | 695-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | ST000417 | Structure | 695-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Readings | Operations Counter AL | 94 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Readings | Operations Counter AF | 94 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Readings | General Comments | | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | ST000417 | Structure | 695-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | ST000417 | Structure | 695-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0070 | Regulator | 350-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0070 | Regulator | 350-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0070 | Regulator | 350-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0070 | Regulator | 350-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0070 | Regulator | 350-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0070 | Regulator | 350-1 C | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Readings | Amps C Ø | 0.0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Readings | Amps B Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Readings | Amps A Ø | 0.0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Readings | 9 Month Operations | 0 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0070 | Regulator | 350-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | MX0491 | RecloserHydraulic | 380-0766 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | MX0491 | RecloserHydraulic | 380-0766 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | MX0491 | RecloserHydraulic | 380-0766 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | MX0491 | RecloserHydraulic | 380-0766 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | MX0491 | RecloserHydraulic | 380-0766 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | MX0491 | RecloserHydraulic | 380-0766 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | MX0491 | RecloserHydraulic | 380-0766 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | MX0491 | RecloserHydraulic | 380-0766 | Recloser Hydraulic Patrol Inspection | Operations Counter | 276 | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | MX0491 | RecloserHydraulic | 380-0766 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | MX0491 | RecloserHydraulic | 380-0766 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | MX0464 | RecloserHydraulic | 381-0744 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 46.2 | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | MX0464 | RecloserHydraulic | 381-0744 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | MX0464 | RecloserHydraulic | 381-0744 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | MX0464 | RecloserHydraulic | 381-0744 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | MX0464 | RecloserHydraulic | 381-0744 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | MX0464 | RecloserHydraulic | 381-0744 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | MX0464 | RecloserHydraulic | 381-0744 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | MX0464 | RecloserHydraulic | 381-0744 | Recloser Hydraulic Patrol Inspection | Operations Counter | 80 | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | MX0464 | RecloserHydraulic | 381-0744 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | MX0464 | RecloserHydraulic | 381-0744 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Readings | Totalizer Meter Reading | .7026 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Readings | LTC Totalizer Reading | 6744.96 | kw |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Readings | General Comments | | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | WithLTC | 563-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | X0073 | RecloserHydraulic | 800-0322 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 34.0 | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | X0073 | RecloserHydraulic | 800-0322 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 31.0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Readings | Operations This Read Vac | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Readings | Operations Counter AL | 122 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Readings | Operations Counter AF | 122 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Readings | General Comments | | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Readings | Amps C Ø | 285.0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Readings | Amps B Ø | 250.0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Readings | Amps A Ø | 265.0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | LTCC000772 | LTCControl | 314-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | LTCC000772 | LTCControl | 314-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | FE000408 | Fence | 695-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | FE000408 | Fence | 695-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | LTCC000772 | LTCControl | 314-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | LTCC000772 | LTCControl | 314-2 | LTC Control Insp | LTC Output Voltage Level | 124.9 | VAC |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | LTCC000772 | LTCControl | 314-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | LTCC000772 | LTCControl | 314-2 | LTC Control Insp | General Comments | | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | LTCC000772 | LTCControl | 314-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | LTCC000772 | LTCControl | 314-2 | LTC Control Insp | All Connections OK? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001538 | BreakerVacuum | 695-2 | VCB Readings | 9 Month Operations | 0 | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | MX0053 | RecloserHydraulic | 504-4340 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 398 | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | MX0053 | RecloserHydraulic | 504-4340 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | MX0053 | RecloserHydraulic | 504-4340 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0.0 | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | MX0053 | RecloserHydraulic | 504-4340 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | MX0053 | RecloserHydraulic | 504-4340 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 20 | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | MX0053 | RecloserHydraulic | 504-4340 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | MX0053 | RecloserHydraulic | 504-4340 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | MX0053 | RecloserHydraulic | 504-4340 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 442 | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | MX0053 | RecloserHydraulic | 504-4340 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | MX0053 | RecloserHydraulic | 504-4340 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | MX0053 | RecloserHydraulic | 504-4340 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | MX0053 | RecloserHydraulic | 504-4340 | Recloser Hydraulic Patrol Inspection | General Comments | Amp probe not working at this time | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | MX0053 | RecloserHydraulic | 504-4340 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | MX0053 | RecloserHydraulic | 504-4340 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | MX0053 | RecloserHydraulic | 504-4340 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | MX0491 | RecloserHydraulic | 380-0766 | Recloser Hydraulic Patrol Inspection | Amps A Ø | .4 | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | MX0491 | RecloserHydraulic | 380-0766 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 3.8 | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | MX0491 | RecloserHydraulic | 380-0766 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 4.7 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Readings | Operations Counter AF | 200 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Readings | Operations Counter AL | 200 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Readings | Operations This Read Vac | 1 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | LTCMechanism | 780-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | LTCMechanism | 780-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | LTCMechanism | 780-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | LTCMechanism | 780-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | LTCMechanism | 780-2 | LTC Counter Readings | LTC Operations Since Last Insp | 587 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | LTCMechanism | 780-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | LTCMechanism | 780-2 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | LTCMechanism | 780-2 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | LTCMechanism | 780-2 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | LTCMechanism | 780-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | LTCMechanism | 780-2 | LTC Counter Readings | LTC As Left Counter | 47644 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | LTCMechanism | 780-2 | LTC Counter Readings | LTC As Found Counter | 47640 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | LTCMechanism | 780-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | LTCMechanism | 780-2 | LTC Counter Readings | General Comments | | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | LTCMechanism | 780-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | S0044 | LTCMechanism | 780-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Readings | LTC Totalizer Reading | 11913.60 | kw |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Readings | Oil Temp Max | 49 | °C |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | LTCMechanism | 649-1 | LTC Counter Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | LTCMechanism | 649-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | LTCMechanism | 649-1 | LTC Counter Readings | General Comments | | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | ST000048 | Structure | 780-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | ST000048 | Structure | 780-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | ST000048 | Structure | 780-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | ST000048 | Structure | 780-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Readings | Oil Temp Present | 49 | °C |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | ST000048 | Structure | 780-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | ST000048 | Structure | 780-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | ST000048 | Structure | 780-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | ST000048 | Structure | 780-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | ST000048 | Structure | 780-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | ST000048 | Structure | 780-Structure | Structure Patrol Inspection | General Comments | | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | ST000048 | Structure | 780-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | ST000048 | Structure | 780-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | ST000048 | Structure | 780-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | ST000048 | Structure | 780-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | ST000048 | Structure | 780-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | ST000048 | Structure | 780-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | ST000048 | Structure | 780-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | LTCMechanism | 649-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | LTCMechanism | 649-1 | LTC Counter Readings | LTC As Found Counter | 67001 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | LTCMechanism | 649-1 | LTC Counter Readings | LTC As Left Counter | 67001 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | LTCMechanism | 649-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | LTCMechanism | 649-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | MX0474 | RecloserHydraulic | 380-4630 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 112.0 | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | MX0474 | RecloserHydraulic | 380-4630 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 117.0 | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | MX0474 | RecloserHydraulic | 380-4630 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | MX0474 | RecloserHydraulic | 380-4630 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | MX0474 | RecloserHydraulic | 380-4630 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | MX0474 | RecloserHydraulic | 380-4630 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | MX0474 | RecloserHydraulic | 380-4630 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | MX0474 | RecloserHydraulic | 380-4630 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | MX0474 | RecloserHydraulic | 380-4630 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | MX0474 | RecloserHydraulic | 380-4630 | Recloser Hydraulic Patrol Inspection | Operations Counter | 125 | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | MX0474 | RecloserHydraulic | 380-4630 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | MX0474 | RecloserHydraulic | 380-4630 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | LTCMechanism | 855-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | LTCMechanism | 855-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | LTCMechanism | 855-1 | LTC Counter Readings | General Comments | | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | LTCMechanism | 855-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | LTCMechanism | 855-1 | LTC Counter Readings | LTC As Found Counter | 42050 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | LTCMechanism | 855-1 | LTC Counter Readings | LTC As Left Counter | 42050 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | LTCMechanism | 855-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | LTCMechanism | 855-1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | LTCMechanism | 855-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | LTCMechanism | 855-1 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | LTCMechanism | 855-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | LTCMechanism | 855-1 | LTC Counter Readings | LTC Operations Since Last Insp | 176 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | LTCMechanism | 855-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Needs Replaced | check oil cup |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | LTCMechanism | 855-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | LTCMechanism | 855-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | LTCMechanism | 855-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Readings | 9 Month Operations | 2 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Readings | Amps A Ø | 107.0 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Readings | Amps B Ø | 94.0 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Readings | Amps C Ø | 97.0 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Readings | Fault Adjusted Amps B Phase V | 1.57 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Readings | Fault Operations B Ø | 1 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Readings | General Comments | BG | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BK001434 | BreakerVacuum | 855-0395 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BAT001058 | Battery | 882-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BAT001058 | Battery | 882-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BAT001058 | Battery | 882-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BAT001058 | Battery | 882-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.4 | VDC |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BAT001058 | Battery | 882-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.1 | VDC |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BAT001058 | Battery | 882-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BAT001058 | Battery | 882-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | LTCMechanism | 563-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | LTCMechanism | 563-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | LTCMechanism | 563-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | LTCMechanism | 563-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | LTCMechanism | 563-1 | LTC Counter Readings | LTC Operations Since Last Insp | 550 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | LTCMechanism | 563-1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | LTCMechanism | 563-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | LTCMechanism | 563-1 | LTC Counter Readings | LTC Current Tap Position | 1R | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | LTCMechanism | 563-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | LTCMechanism | 563-1 | LTC Counter Readings | LTC As Left Counter | 11350 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | LTCMechanism | 563-1 | LTC Counter Readings | LTC As Found Counter | 11900 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | LTCMechanism | 563-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | LTCMechanism | 563-1 | LTC Counter Readings | General Comments | | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | LTCMechanism | 563-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | S0007 | LTCMechanism | 563-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Readings | General Comments | | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Readings | LTC Totalizer Reading | 2462.40 | kw |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Readings | Oil Temp Present | 15 | °C |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 3600 | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Readings | Totalizer Meter Reading | .6840 | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | WithLTC | 380-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | LTCMechanism | 649-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | LTCMechanism | 649-1 | LTC Counter Readings | LTC Min Tap Position | 15L | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | LTCMechanism | 649-1 | LTC Counter Readings | LTC Operations Since Last Insp | 239 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | LTCMechanism | 649-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | LTCMechanism | 649-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | C0373 | LTCMechanism | 649-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | X0059 | RecloserHydraulic | 321-4734 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | ST000048 | Structure | 780-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | ST000048 | Structure | 780-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | ST000048 | Structure | 780-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | ST000048 | Structure | 780-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | ST000048 | Structure | 780-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Readings | Totalizer Meter Reading | 1.2410 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | LTCMechanism | 602-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | LTCMechanism | 602-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | LTCMechanism | 602-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | LTCMechanism | 602-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | LTCMechanism | 602-1 | LTC Counter Readings | LTC Operations Since Last Insp | 815 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | LTCMechanism | 602-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | LTCMechanism | 602-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | LTCMechanism | 602-1 | LTC Counter Readings | LTC Max Tap Position | 7R | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | LTCMechanism | 602-1 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | LTCMechanism | 602-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | LTCMechanism | 602-1 | LTC Counter Readings | LTC As Left Counter | 27383 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | LTCMechanism | 602-1 | LTC Counter Readings | LTC As Found Counter | 27374 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | LTCMechanism | 602-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BAT001058 | Battery | 882-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BAT001058 | Battery | 882-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 72 | °F |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BAT001058 | Battery | 882-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BAT001058 | Battery | 882-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | X0059 | RecloserHydraulic | 321-4734 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | X0059 | RecloserHydraulic | 321-4734 | Recloser Hydraulic Patrol Inspection | Operations Counter | 260 | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | X0059 | RecloserHydraulic | 321-4734 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | X0059 | RecloserHydraulic | 321-4734 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | X0059 | RecloserHydraulic | 321-4734 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | X0059 | RecloserHydraulic | 321-4734 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | X0059 | RecloserHydraulic | 321-4734 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | X0059 | RecloserHydraulic | 321-4734 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | X0059 | RecloserHydraulic | 321-4734 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | X0059 | RecloserHydraulic | 321-4734 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 65.0 | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | X0059 | RecloserHydraulic | 321-4734 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 54.0 | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | X0059 | RecloserHydraulic | 321-4734 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 33.0 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | LTCMechanism | 602-1 | LTC Counter Readings | General Comments | | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | LTCMechanism | 602-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | B0387 | LTCMechanism | 602-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BAT001058 | Battery | 882-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BAT001058 | Battery | 882-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BAT001058 | Battery | 882-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Low | If low,note cell #~'s |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | LTCC000674 | LTCControl | 602-1 | LTC Control Insp | All Connections OK? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0069 | Regulator | 350-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0069 | Regulator | 350-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0069 | Regulator | 350-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0069 | Regulator | 350-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 57748 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0069 | Regulator | 350-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.7 | volts |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0069 | Regulator | 350-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0069 | Regulator | 350-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0069 | Regulator | 350-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0069 | Regulator | 350-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0069 | Regulator | 350-1 B | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0069 | Regulator | 350-1 B | Regulator Patrol Inspection | Max Tap Position | 10R | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0069 | Regulator | 350-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0069 | Regulator | 350-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0069 | Regulator | 350-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0069 | Regulator | 350-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0069 | Regulator | 350-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0069 | Regulator | 350-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0069 | Regulator | 350-1 B | Regulator Patrol Inspection | Current Tap Position | 2R | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0069 | Regulator | 350-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0069 | Regulator | 350-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0069 | Regulator | 350-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0069 | Regulator | 350-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0069 | Regulator | 350-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0068 | Regulator | 350-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0068 | Regulator | 350-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0068 | Regulator | 350-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0068 | Regulator | 350-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 50608 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0068 | Regulator | 350-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0068 | Regulator | 350-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0068 | Regulator | 350-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0068 | Regulator | 350-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0068 | Regulator | 350-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0068 | Regulator | 350-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0068 | Regulator | 350-1 A | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0068 | Regulator | 350-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0068 | Regulator | 350-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0068 | Regulator | 350-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0068 | Regulator | 350-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0068 | Regulator | 350-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0068 | Regulator | 350-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0068 | Regulator | 350-1 A | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0068 | Regulator | 350-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0068 | Regulator | 350-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0068 | Regulator | 350-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0068 | Regulator | 350-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0068 | Regulator | 350-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | DX0153 | RecloserHydraulic | 321-4733 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | DX0153 | RecloserHydraulic | 321-4733 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | DX0153 | RecloserHydraulic | 321-4733 | Recloser Hydraulic Patrol Inspection | Operations Counter | 106 | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | DX0153 | RecloserHydraulic | 321-4733 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | DX0153 | RecloserHydraulic | 321-4733 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | DX0153 | RecloserHydraulic | 321-4733 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | DX0153 | RecloserHydraulic | 321-4733 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | LTCMechanism | 882-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Readings | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | LTCMechanism | 882-1 | LTC Counter Readings | LTC As Found Counter | 290854 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | LTCMechanism | 882-1 | LTC Counter Readings | LTC As Left Counter | 290862 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | LTCMechanism | 882-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | LTCMechanism | 882-1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | LTCMechanism | 882-1 | LTC Counter Readings | LTC Max Tap Position | 8R | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | LTCMechanism | 882-1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | LTCMechanism | 882-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | LTCMechanism | 882-1 | LTC Counter Readings | LTC Operations Since Last Insp | 710 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | LTCMechanism | 882-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | LTCMechanism | 882-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Readings | Operations Counter AF | 498 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Readings | Operations Counter AL | 498 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Readings | Operations This Read Vac | 0 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | LTCMechanism | 882-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | LTCMechanism | 882-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | KX0167 | RecloserElectronic | 882-0318 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | KX0167 | RecloserElectronic | 882-0318 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | KX0167 | RecloserElectronic | 882-0318 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | KX0167 | RecloserElectronic | 882-0318 | Recloser Electronic Patrol Inspection | Operations Counter | 70 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | KX0167 | RecloserElectronic | 882-0318 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | KX0167 | RecloserElectronic | 882-0318 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | KX0167 | RecloserElectronic | 882-0318 | Recloser Electronic Patrol Inspection | General Comments | 27.6/25.5 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | KX0167 | RecloserElectronic | 882-0318 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | KX0167 | RecloserElectronic | 882-0318 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | KX0167 | RecloserElectronic | 882-0318 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | KX0167 | RecloserElectronic | 882-0318 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | KX0167 | RecloserElectronic | 882-0318 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | KX0167 | RecloserElectronic | 882-0318 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | KX0167 | RecloserElectronic | 882-0318 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | KX0167 | RecloserElectronic | 882-0318 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | KX0167 | RecloserElectronic | 882-0318 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | KX0167 | RecloserElectronic | 882-0318 | Recloser Electronic Patrol Inspection | Amps C Ø | 61.0 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | KX0167 | RecloserElectronic | 882-0318 | Recloser Electronic Patrol Inspection | Amps B Ø | 65.0 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | KX0167 | RecloserElectronic | 882-0318 | Recloser Electronic Patrol Inspection | Amps A Ø | 62.0 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | LTCC000674 | LTCControl | 602-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | LTCC000674 | LTCControl | 602-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | LTCC000674 | LTCControl | 602-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | LTCC000674 | LTCControl | 602-1 | LTC Control Insp | LTC Output Voltage Level | 124.5 | VAC |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | LTCC000674 | LTCControl | 602-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | LTCC000674 | LTCControl | 602-1 | LTC Control Insp | General Comments | | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | LTCC000674 | LTCControl | 602-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | LTCC000664 | LTCControl | 855-1 | LTC Control Insp | LTC Output Voltage Level | 123.5 | VAC |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | LTCC000664 | LTCControl | 855-1 | LTC Control Insp | VRR Base Voltage AF | 124.2 | VAC |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | LTCC000664 | LTCControl | 855-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | LTCC000664 | LTCControl | 855-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Readings | Operations This Read Vac | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Readings | Operations Counter AL | 206 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Readings | Operations Counter AF | 206 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Readings | General Comments | | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Readings | Amps C Ø | 26.0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Readings | Amps B Ø | 55.0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Readings | Amps A Ø | 57.0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK000891 | BreakerVacuum | 780-0360 | VCB Readings | 9 Month Operations | 1 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | WithLTC | 780-3 | LTC Transformer Readings | General Comments | | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | MX0474 | RecloserHydraulic | 380-4630 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 123.0 | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | DX0153 | RecloserHydraulic | 321-4733 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | DX0153 | RecloserHydraulic | 321-4733 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | DX0153 | RecloserHydraulic | 321-4733 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | DX0153 | RecloserHydraulic | 321-4733 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 42.0 | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | DX0153 | RecloserHydraulic | 321-4733 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 1.6 | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | DX0153 | RecloserHydraulic | 321-4733 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 48.0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BB0433 | BreakerVacuum | 838-0508 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BAT001049 | Battery | 649-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BAT001049 | Battery | 649-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 35 | °F |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BAT001049 | Battery | 649-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BAT001049 | Battery | 649-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BAT001049 | Battery | 649-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BAT001049 | Battery | 649-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BAT001049 | Battery | 649-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BAT001049 | Battery | 649-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BAT001049 | Battery | 649-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BAT001049 | Battery | 649-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BAT001049 | Battery | 649-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BAT001049 | Battery | 649-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BAT001049 | Battery | 649-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BAT001049 | Battery | 649-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BAT001049 | Battery | 649-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BAT001050 | Battery | 838-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BAT001050 | Battery | 838-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 28 | °F |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BAT001050 | Battery | 838-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BAT001050 | Battery | 838-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BAT001050 | Battery | 838-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BAT001050 | Battery | 838-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BAT001050 | Battery | 838-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BAT001050 | Battery | 838-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BAT001050 | Battery | 838-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BAT001050 | Battery | 838-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BAT001050 | Battery | 838-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BAT001050 | Battery | 838-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BAT001050 | Battery | 838-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | FE000081 | Fence | 314-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | FE000081 | Fence | 314-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | FE000081 | Fence | 314-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | FE000081 | Fence | 314-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | FE000081 | Fence | 314-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | FE000081 | Fence | 314-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | FE000081 | Fence | 314-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | FE000081 | Fence | 314-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | FE000081 | Fence | 314-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | FE000081 | Fence | 314-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | FE000081 | Fence | 314-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | FE000081 | Fence | 314-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | FE000081 | Fence | 314-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | FE000081 | Fence | 314-Fence | Fence Patrol Inspection | General Comments | | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | FE000081 | Fence | 314-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | FE000081 | Fence | 314-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | LTCC000664 | LTCControl | 855-1 | LTC Control Insp | All Connections OK? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | LTCC000664 | LTCControl | 855-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | LTCC000664 | LTCControl | 855-1 | LTC Control Insp | General Comments | | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | LTCC000664 | LTCControl | 855-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0127 | Regulator | 182-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0127 | Regulator | 182-1 C | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0127 | Regulator | 182-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0127 | Regulator | 182-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0127 | Regulator | 182-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0127 | Regulator | 182-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0127 | Regulator | 182-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | ST000368 | Structure | 402-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | ST000368 | Structure | 402-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | ST000368 | Structure | 402-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | ST000368 | Structure | 402-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | ST000368 | Structure | 402-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | ST000368 | Structure | 402-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | ST000368 | Structure | 402-Structure | Structure Patrol Inspection | General Comments | | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | ST000368 | Structure | 402-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | ST000368 | Structure | 402-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | ST000368 | Structure | 402-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | ST000368 | Structure | 402-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | ST000368 | Structure | 402-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | ST000368 | Structure | 402-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | ST000368 | Structure | 402-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | ST000368 | Structure | 402-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | ST000368 | Structure | 402-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Readings | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Readings | LTC Totalizer Reading | 8294.40 | kw |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Readings | Totalizer Meter Reading | .5760 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Readings | Winding Temp Max | 30 | °C |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BAT001208 | Battery | 522-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BAT001208 | Battery | 522-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 25 | °F |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BAT001208 | Battery | 522-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BAT001208 | Battery | 522-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BAT001208 | Battery | 522-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BAT001208 | Battery | 522-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BAT001208 | Battery | 522-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BAT001208 | Battery | 522-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BAT001208 | Battery | 522-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BAT001208 | Battery | 522-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BAT001208 | Battery | 522-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BAT001208 | Battery | 522-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BAT001208 | Battery | 522-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BAT001208 | Battery | 522-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BAT001208 | Battery | 522-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0127 | Regulator | 182-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0127 | Regulator | 182-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0127 | Regulator | 182-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0127 | Regulator | 182-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0127 | Regulator | 182-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 42941 | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000108 | Regulator | 504-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000108 | Regulator | 504-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000108 | Regulator | 504-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000108 | Regulator | 504-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000108 | Regulator | 504-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 12844 | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000108 | Regulator | 504-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.2 | volts |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000108 | Regulator | 504-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000108 | Regulator | 504-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000108 | Regulator | 504-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000108 | Regulator | 504-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000108 | Regulator | 504-1 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000108 | Regulator | 504-1 B | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000108 | Regulator | 504-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000108 | Regulator | 504-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000108 | Regulator | 504-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000108 | Regulator | 504-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000108 | Regulator | 504-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000108 | Regulator | 504-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000108 | Regulator | 504-1 B | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000108 | Regulator | 504-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000108 | Regulator | 504-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000108 | Regulator | 504-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000108 | Regulator | 504-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000108 | Regulator | 504-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0127 | Regulator | 182-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0127 | Regulator | 182-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0127 | Regulator | 182-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0127 | Regulator | 182-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0127 | Regulator | 182-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0127 | Regulator | 182-1 C | Regulator Patrol Inspection | Min Tap Position | 5L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0127 | Regulator | 182-1 C | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0127 | Regulator | 182-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0127 | Regulator | 182-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0127 | Regulator | 182-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0127 | Regulator | 182-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0127 | Regulator | 182-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Readings | Operations Counter AF | 215 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Readings | Operations Counter AL | 215 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Readings | Operations This Read Vac | 1 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Readings | Switching Operations | 1 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Readings | Amps B Ø | 0.0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Readings | Amps A Ø | 0.0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Readings | 9 Month Operations | 2 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Readings | 9 Month Operations | 16 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Readings | Amps A Ø | 42.0 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Readings | Amps B Ø | 51.0 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Readings | Amps C Ø | 22.0 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Readings | Fault Adjusted Amps B Phase V | 33.48 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Readings | Fault Operations B Ø | 11 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Readings | General Comments | | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Readings | Operations Counter AF | 234 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Readings | Operations Counter AL | 234 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Readings | Operations This Read Vac | 11 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001406 | BreakerVacuum | 882-0312 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | FE000001 | Fence | 350-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | FE000001 | Fence | 350-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | FE000001 | Fence | 350-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | FE000001 | Fence | 350-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | FE000001 | Fence | 350-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | FE000001 | Fence | 350-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Readings | Winding Temp Present | 50 | °C |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0371 | WithLTC | 838-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Readings | Switching Operations | 2 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Readings | Operations This Read Vac | 2 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Readings | Operations Counter AL | 176 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Readings | Operations Counter AF | 176 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Readings | 9 Month Operations | 1 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Readings | Amps A Ø | 105.0 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Readings | Amps B Ø | 101.0 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Readings | Amps C Ø | 140.0 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001543 | BreakerVacuum | 695-0456 | VCB Readings | Amps C Ø | 0.0 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Readings | General Comments | | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | BK001405 | BreakerVacuum | 882-0311 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0976 | Regulator | 321-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0976 | Regulator | 321-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0976 | Regulator | 321-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 167801 | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0976 | Regulator | 321-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0976 | Regulator | 321-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0976 | Regulator | 321-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0976 | Regulator | 321-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0976 | Regulator | 321-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0976 | Regulator | 321-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0976 | Regulator | 321-1 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0976 | Regulator | 321-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0976 | Regulator | 321-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0976 | Regulator | 321-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | FE000056 | Fence | 882-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | FE000056 | Fence | 882-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | n | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | FE000056 | Fence | 882-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | FE000056 | Fence | 882-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | FE000056 | Fence | 882-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | FE000056 | Fence | 882-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0976 | Regulator | 321-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0976 | Regulator | 321-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0976 | Regulator | 321-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Readings | Amps A Ø | 120.0 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Readings | Amps B Ø | 120.0 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Readings | Amps C Ø | 120.0 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Readings | General Comments | | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Readings | Operations Counter AF | 81 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Readings | Operations Counter AL | 85 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Readings | Operations This Read Vac | 4 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Readings | Switching Operations | 4 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Readings | General Comments | | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0977 | Regulator | 321-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0977 | Regulator | 321-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0977 | Regulator | 321-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 124638 | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0977 | Regulator | 321-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0977 | Regulator | 321-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0977 | Regulator | 321-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0977 | Regulator | 321-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0977 | Regulator | 321-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0977 | Regulator | 321-1 B | Regulator Patrol Inspection | Min Tap Position | Neutral | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0977 | Regulator | 321-1 B | Regulator Patrol Inspection | Max Tap Position | 14R | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0977 | Regulator | 321-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0977 | Regulator | 321-1 B | Regulator Patrol Inspection | General Comments | | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0977 | Regulator | 321-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0977 | Regulator | 321-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0977 | Regulator | 321-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0977 | Regulator | 321-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0977 | Regulator | 321-1 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0977 | Regulator | 321-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0977 | Regulator | 321-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0977 | Regulator | 321-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0977 | Regulator | 321-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0977 | Regulator | 321-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Readings | Fault Operations A Ø | 1 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Readings | Fault Adjusted Amps A Phase V | 5.99 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Readings | Amps C Ø | 129.0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Readings | Amps B Ø | 114.0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Readings | Amps A Ø | 151.0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001150 | BreakerVacuum | 402-0500 | VCB Readings | 9 Month Operations | 1 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Readings | Switching Operations | 4 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Readings | Operations This Read Vac | 5 | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0976 | Regulator | 321-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0976 | Regulator | 321-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | ST000553 | Structure | 649-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | ST000553 | Structure | 649-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | ST000553 | Structure | 649-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | YD000045 | Yard | 780-Yard | Yard Patrol Inspection | Ambient Temp | 34 | °F |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | YD000045 | Yard | 780-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | YD000045 | Yard | 780-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | YD000045 | Yard | 780-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | YD000045 | Yard | 780-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | YD000045 | Yard | 780-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | YD000045 | Yard | 780-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | YD000045 | Yard | 780-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | YD000045 | Yard | 780-Yard | Yard Patrol Inspection | General Comments | | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | YD000045 | Yard | 780-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | YD000045 | Yard | 780-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | YD000045 | Yard | 780-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | LTCC000905 | LTCControl | 649-1 | LTC Control Insp | All Connections OK? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | LTCC000905 | LTCControl | 649-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | LTCC000905 | LTCControl | 649-1 | LTC Control Insp | General Comments | | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | LTCC000905 | LTCControl | 649-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | LTCC000905 | LTCControl | 649-1 | LTC Control Insp | LTC Output Voltage Level | 124.7 | VAC |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | LTCC000905 | LTCControl | 649-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | LTCC000905 | LTCControl | 649-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | LTCC000905 | LTCControl | 649-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | ST000553 | Structure | 649-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | ST000553 | Structure | 649-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | ST000553 | Structure | 649-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | ST000553 | Structure | 649-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | ST000553 | Structure | 649-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | CH000522 | ControlHouse | 780-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | CH000522 | ControlHouse | 780-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | CH000522 | ControlHouse | 780-Control House | Control House Patrol Inspection | Broom on Site? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | CH000522 | ControlHouse | 780-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | CH000522 | ControlHouse | 780-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | CH000522 | ControlHouse | 780-Control House | Control House Patrol Inspection | Door Alarms OK? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | CH000522 | ControlHouse | 780-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | CH000522 | ControlHouse | 780-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | CH000522 | ControlHouse | 780-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | CH000522 | ControlHouse | 780-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | CH000522 | ControlHouse | 780-Control House | Control House Patrol Inspection | Floor Swept? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | CH000522 | ControlHouse | 780-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | CH000522 | ControlHouse | 780-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | CH000522 | ControlHouse | 780-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | CH000522 | ControlHouse | 780-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | CH000522 | ControlHouse | 780-Control House | Control House Patrol Inspection | Panels Dusted? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | CH000522 | ControlHouse | 780-Control House | Control House Patrol Inspection | Station Ground Set On Site? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | CH000522 | ControlHouse | 780-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | CH000522 | ControlHouse | 780-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | CH000522 | ControlHouse | 780-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | CH000522 | ControlHouse | 780-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | ST000368 | Structure | 402-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | ST000368 | Structure | 402-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | ST000368 | Structure | 402-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | ST000368 | Structure | 402-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | ST000368 | Structure | 402-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | ST000368 | Structure | 402-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | ST000368 | Structure | 402-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | CB0197 | BreakerVacuum | 649-2301 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0976 | Regulator | 321-1 C | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0976 | Regulator | 321-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0976 | Regulator | 321-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0976 | Regulator | 321-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0976 | Regulator | 321-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 11:12 | Distribution | Osaka East Quarterly Inspection | R0976 | Regulator | 321-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Readings | Operations Counter AL | 210 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Readings | Operations Counter AF | 210 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | FE000056 | Fence | 882-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | FE000056 | Fence | 882-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | FE000056 | Fence | 882-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | FE000056 | Fence | 882-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | n | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | FE000056 | Fence | 882-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | FE000056 | Fence | 882-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | FE000056 | Fence | 882-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | FE000056 | Fence | 882-Fence | Fence Patrol Inspection | General Comments | tree hanging into station on the right side when looking at the station from the gate | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | FE000056 | Fence | 882-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | FE000056 | Fence | 882-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Readings | Fault Operations A Ø | 1 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Readings | Fault Adjusted Amps A Phase V | 5.99 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Readings | Amps C Ø | 147.0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Readings | Amps B Ø | 188.0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Readings | Amps A Ø | 214.0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | ST000553 | Structure | 649-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | ST000553 | Structure | 649-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BK001149 | BreakerVacuum | 402-0515 | VCB Readings | 9 Month Operations | 7 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | ST000553 | Structure | 649-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | ST000553 | Structure | 649-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | ST000553 | Structure | 649-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | ST000553 | Structure | 649-Structure | Structure Patrol Inspection | General Comments | | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | ST000553 | Structure | 649-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | CAP000015 | CapacitorBank | 503-Cap Bank | Capacitor Patrol Inspection | Tank Paint Condition | Adequate | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Readings | Switching Operations | 3 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Readings | Operations This Read Vac | 3 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Readings | Operations Counter AL | 111 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Readings | Operations Counter AF | 111 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Readings | General Comments | | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1100 | Regulator | 314-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1100 | Regulator | 314-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1100 | Regulator | 314-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1100 | Regulator | 314-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1100 | Regulator | 314-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 127962 | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1100 | Regulator | 314-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1100 | Regulator | 314-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1100 | Regulator | 314-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1100 | Regulator | 314-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1100 | Regulator | 314-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1100 | Regulator | 314-1 A | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1100 | Regulator | 314-1 A | Regulator Patrol Inspection | Max Tap Position | 7L | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1100 | Regulator | 314-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1100 | Regulator | 314-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1100 | Regulator | 314-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1100 | Regulator | 314-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1100 | Regulator | 314-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Readings | Follow-up Action Required? | n | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1100 | Regulator | 314-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1100 | Regulator | 314-1 A | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1100 | Regulator | 314-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1100 | Regulator | 314-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1100 | Regulator | 314-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1100 | Regulator | 314-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1100 | Regulator | 314-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | MX0453 | RecloserHydraulic | 503-4331 | Recloser Hydraulic Patrol Inspection | Amps A Ø | .2 | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | MX0453 | RecloserHydraulic | 503-4331 | Recloser Hydraulic Patrol Inspection | Amps B Ø | .2 | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | MX0453 | RecloserHydraulic | 503-4331 | Recloser Hydraulic Patrol Inspection | Amps C Ø | .2 | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | MX0453 | RecloserHydraulic | 503-4331 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | MX0453 | RecloserHydraulic | 503-4331 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | MX0453 | RecloserHydraulic | 503-4331 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | MX0453 | RecloserHydraulic | 503-4331 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Readings | Amps C Ø | 75.0 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Readings | Amps A Ø | 140.0 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Readings | Amps B Ø | 130.0 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Readings | Amps C Ø | 148.0 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Readings | General Comments | | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Readings | Operations Counter AF | 288 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Readings | Operations Counter AL | 288 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Readings | Operations This Read Vac | 0 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Readings | Unknown Operations | 0 | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | LTCC000810 | LTCControl | 380-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | LTCC000810 | LTCControl | 380-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | LTCC000810 | LTCControl | 380-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | LTCC000810 | LTCControl | 380-1 | LTC Control Insp | LTC Output Voltage Level | 124.5 | VAC |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | LTCC000810 | LTCControl | 380-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | LTCC000810 | LTCControl | 380-1 | LTC Control Insp | General Comments | | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | LTCC000810 | LTCControl | 380-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | LTCC000810 | LTCControl | 380-1 | LTC Control Insp | All Connections OK? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | CAP000015 | CapacitorBank | 503-Cap Bank | Capacitor Patrol Inspection | All Connections OK? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | CAP000015 | CapacitorBank | 503-Cap Bank | Capacitor Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | CAP000015 | CapacitorBank | 503-Cap Bank | Capacitor Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | CAP000015 | CapacitorBank | 503-Cap Bank | Capacitor Patrol Inspection | Capacitor Condition | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | CAP000015 | CapacitorBank | 503-Cap Bank | Capacitor Patrol Inspection | Capacitor Rack Condition OK? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | CAP000015 | CapacitorBank | 503-Cap Bank | Capacitor Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | CAP000015 | CapacitorBank | 503-Cap Bank | Capacitor Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | CAP000015 | CapacitorBank | 503-Cap Bank | Capacitor Patrol Inspection | Fuse Barrels Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | CAP000015 | CapacitorBank | 503-Cap Bank | Capacitor Patrol Inspection | Fuses Blown? Y / N | n | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | CAP000015 | CapacitorBank | 503-Cap Bank | Capacitor Patrol Inspection | General Comments | cap bank had been disconnected from buss | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | CAP000015 | CapacitorBank | 503-Cap Bank | Capacitor Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | CAP000015 | CapacitorBank | 503-Cap Bank | Capacitor Patrol Inspection | Insulators In Good Condition? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | CAP000015 | CapacitorBank | 503-Cap Bank | Capacitor Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Readings | General Comments | | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Readings | Operations Counter AF | 181 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Readings | Operations Counter AL | 182 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Readings | Operations This Read Vac | 1 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Readings | Switching Operations | 1 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Readings | 9 Month Operations | 1 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Readings | Amps A Ø | 232.0 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Readings | Amps B Ø | 173.0 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Readings | Amps C Ø | 199.0 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0070 | Regulator | 350-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001539 | BreakerVacuum | 695-BT2-1 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0070 | Regulator | 350-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0070 | Regulator | 350-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0070 | Regulator | 350-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 47017 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0070 | Regulator | 350-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0070 | Regulator | 350-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0070 | Regulator | 350-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0070 | Regulator | 350-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0070 | Regulator | 350-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0070 | Regulator | 350-1 C | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0070 | Regulator | 350-1 C | Regulator Patrol Inspection | Max Tap Position | 9R | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | KR0070 | Regulator | 350-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BK000416 | BreakerVacuum | 649-2300 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Readings | Amps B Ø | 80.0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Readings | Amps A Ø | 100.0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001540 | BreakerVacuum | 695-0450 | VCB Readings | 9 Month Operations | 3 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Readings | General Comments | | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Patrol Inspection | General Comments | Added Nitrogen | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 4347.84 | kw |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Readings | Oil Temp Max | 60 | °C |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Readings | Oil Temp Present | 39 | °C |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | O0190 | NonLTC | 350-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .9058 | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | MX0453 | RecloserHydraulic | 503-4331 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | MX0453 | RecloserHydraulic | 503-4331 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | MX0453 | RecloserHydraulic | 503-4331 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | MX0453 | RecloserHydraulic | 503-4331 | Recloser Hydraulic Patrol Inspection | Operations Counter | 276 | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | MX0453 | RecloserHydraulic | 503-4331 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | MX0453 | RecloserHydraulic | 503-4331 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Readings | 9 Month Operations | 3 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Readings | Amps A Ø | 77.0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Readings | Amps B Ø | 68.0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Readings | Amps C Ø | 77.0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000415 | BreakerVacuum | 182-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Readings | Operations Counter AL | 101 | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | YD000061 | Yard | 504-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | YD000061 | Yard | 504-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | YD000061 | Yard | 504-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | YD000061 | Yard | 504-Yard | Yard Patrol Inspection | General Comments | | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | YD000061 | Yard | 504-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | YD000061 | Yard | 504-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | YD000061 | Yard | 504-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Readings | Operations Counter AF | 101 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Readings | General Comments | | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Readings | Amps C Ø | 0.0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Readings | Amps B Ø | 0.0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Readings | Amps A Ø | 0.0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Readings | 9 Month Operations | 2 | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | YD000061 | Yard | 504-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | YD000061 | Yard | 504-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | YD000061 | Yard | 504-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BCH001041 | Charger | 838-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BCH001041 | Charger | 838-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BCH001041 | Charger | 838-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BCH001041 | Charger | 838-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BCH001041 | Charger | 838-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 3.7 | amps |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BCH001041 | Charger | 838-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BCH001041 | Charger | 838-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BCH001041 | Charger | 838-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | YD000061 | Yard | 504-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | YD000061 | Yard | 504-Yard | Yard Patrol Inspection | Ambient Temp | 34 | °F |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | FE000001 | Fence | 350-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | FE000001 | Fence | 350-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | FE000001 | Fence | 350-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | FE000001 | Fence | 350-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | FE000001 | Fence | 350-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | FE000001 | Fence | 350-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | FE000001 | Fence | 350-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | FE000001 | Fence | 350-Fence | Fence Patrol Inspection | General Comments | | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | FE000001 | Fence | 350-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | FE000001 | Fence | 350-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Readings | 9 Month Operations | 0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Readings | Amps A Ø | 600.0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Readings | Amps B Ø | 530.0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Readings | Amps C Ø | 600.0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Readings | General Comments | | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Readings | Operations Counter AF | 99748 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Readings | Operations Counter AL | 99748 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BB0453 | BreakerVacuum | 402-1 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Readings | Operations This Read Vac | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Readings | Operations Counter AL | 212 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Readings | Switching Operations | 2 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001542 | BreakerVacuum | 695-0449 | VCB Readings | Operations This Read Vac | 2 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | FE000048 | Fence | 780-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | FE000048 | Fence | 780-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | FE000048 | Fence | 780-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | FE000048 | Fence | 780-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Readings | Switching Operations | 3 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Readings | Operations This Read Vac | 3 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Readings | Operations Counter AL | 98 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Readings | Operations Counter AF | 98 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Readings | General Comments | | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Readings | Amps C Ø | 220.0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Readings | Amps B Ø | 165.0 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Readings | 9 Month Operations | 3 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | LTCC000870 | LTCControl | 838-2 | LTC Control Insp | All Connections OK? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | LTCC000870 | LTCControl | 838-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | LTCC000870 | LTCControl | 838-2 | LTC Control Insp | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | LTCC000870 | LTCControl | 838-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | LTCC000870 | LTCControl | 838-2 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | LTCC000870 | LTCControl | 838-2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | LTCC000870 | LTCControl | 838-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | LTCC000870 | LTCControl | 838-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | LTCC000870 | LTCControl | 838-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Readings | Amps A Ø | 165.0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001541 | BreakerVacuum | 695-0451 | VCB Readings | 9 Month Operations | 3 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BCH001543 | Charger | 649-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BCH001543 | Charger | 649-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BCH001543 | Charger | 649-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BCH001543 | Charger | 649-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .6 | amps |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BCH001543 | Charger | 649-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | BCH001543 | Charger | 649-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | KB0078 | BreakerVacuum | 602-0308 | VCB Readings | 9 Month Operations | 2 | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Readings | General Comments | | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1762.56 | kw |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 17.50 | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Readings | Oil Temp Present | 19 | °C |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | 0961 | NonLTC | 800-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .7344 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Readings | Operations Counter AF | 212 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Readings | General Comments | | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | FE000048 | Fence | 780-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | FE000048 | Fence | 780-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | FE000048 | Fence | 780-Fence | Fence Patrol Inspection | General Comments | | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | FE000048 | Fence | 780-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | FE000048 | Fence | 780-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | FE000048 | Fence | 780-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | FE000048 | Fence | 780-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | FE000048 | Fence | 780-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | FE000048 | Fence | 780-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | FE000048 | Fence | 780-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | FE000048 | Fence | 780-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Readings | Amps C Ø | 17.0 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Readings | Amps B Ø | 42.0 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BK001145 | BreakerVacuum | 602-0390 | VCB Readings | Amps A Ø | 28.0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | FE000048 | Fence | 780-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Readings | Operations This Read SF6 | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Readings | Operations Counter AL | 88 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Readings | Operations Counter AF | 88 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Patrol Inspection | General Comments | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Readings | General Comments | | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | FE000870 | Fence | 450-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | FE000870 | Fence | 450-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | FE000870 | Fence | 450-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | FE000870 | Fence | 450-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | FE000870 | Fence | 450-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | FE000870 | Fence | 450-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | FE000870 | Fence | 450-Fence | Fence Patrol Inspection | General Comments | | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | FE000870 | Fence | 450-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | FE000870 | Fence | 450-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Readings | Fault Operations | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Readings | Amps B Ø | 180.0 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Readings | Amps A Ø | 215.0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Patrol Inspection | Ambient Temperature | 28 | °F |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Readings | 9 Month Operations | 1 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1098 | Regulator | 314-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 299567 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Readings | Amps A Ø | 155.0 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Readings | Amps B Ø | 131.0 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Readings | Amps C Ø | 101.0 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1098 | Regulator | 314-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1098 | Regulator | 314-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Readings | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Readings | LTC Totalizer Reading | 18936.00 | kw |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Readings | Amps B Ø | 53.0 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Readings | Amps C Ø | 68.0 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1098 | Regulator | 314-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1098 | Regulator | 314-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Readings | Fault Adjusted Amps B Phase V | 5.66 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Readings | Fault Operations B Ø | 2 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Readings | General Comments | BC/T-I | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Readings | Operations This Read Vac | 2 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Readings | Operations Counter AL | 240 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Readings | Operations Counter AF | 238 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Readings | Maintenance Operations | 2 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | YD000178 | Yard | 503-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | YD000178 | Yard | 503-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Readings | Operations Counter AF | 165 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Readings | Operations Counter AL | 165 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Readings | Operations This Read Vac | 2 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Readings | Unknown Operations | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Readings | Switching Operations | 0 | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | YD000178 | Yard | 503-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | YD000178 | Yard | 503-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | YD000178 | Yard | 503-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | YD000178 | Yard | 503-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | YD000178 | Yard | 503-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | YD000178 | Yard | 503-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | YD000178 | Yard | 503-Yard | Yard Patrol Inspection | Ambient Temp | 34 | °F |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Readings | General Comments | | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Patrol Inspection | SF6 Pressure | 60 | psi |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001725 | BreakerSF6 | 695-618 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Readings | Amps C Ø | 175.0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | ST000087 | Structure | 314-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | ST000087 | Structure | 314-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | ST000087 | Structure | 314-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | ST000087 | Structure | 314-Structure | Structure Patrol Inspection | General Comments | | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | ST000087 | Structure | 314-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | ST000087 | Structure | 314-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | ST000087 | Structure | 314-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001099 | Battery | 182-603 MOS Battery and Charger | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001099 | Battery | 182-603 MOS Battery and Charger | Battery Patrol Inspection | General Comments | | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001099 | Battery | 182-603 MOS Battery and Charger | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001099 | Battery | 182-603 MOS Battery and Charger | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001099 | Battery | 182-603 MOS Battery and Charger | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001099 | Battery | 182-603 MOS Battery and Charger | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001099 | Battery | 182-603 MOS Battery and Charger | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001099 | Battery | 182-603 MOS Battery and Charger | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001099 | Battery | 182-603 MOS Battery and Charger | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001099 | Battery | 182-603 MOS Battery and Charger | Battery Patrol Inspection | Battery Area Ambient Temp | 79 | °F |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001099 | Battery | 182-603 MOS Battery and Charger | Battery Patrol Inspection | All Connections OK? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BCH001059 | Charger | 182-603 MOS Battery and Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Readings | 9 Month Operations | 12 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Readings | Amps A Ø | 74.0 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Readings | Amps B Ø | 42.0 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Readings | Amps C Ø | 38.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Readings | General Comments | | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Readings | Operations Counter AF | 223 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Readings | Operations Counter AL | 223 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Readings | Operations This Read Vac | 6 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Readings | Switching Operations | 6 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001103 | BreakerVacuum | 592-2147 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BCH001059 | Charger | 182-603 MOS Battery and Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BCH001059 | Charger | 182-603 MOS Battery and Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BCH001059 | Charger | 182-603 MOS Battery and Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.1 | VDC |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BCH001059 | Charger | 182-603 MOS Battery and Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.1 | VDC |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BCH001059 | Charger | 182-603 MOS Battery and Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .500 | millivolts |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | LTCMechanism | 522-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | LTCMechanism | 522-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | LTCMechanism | 522-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | 0929 | NonLTC | 381-1 A | NonLTC Transformer Readings | Totalizer Meter Reading | .4476 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Readings | Totalizer Meter Reading | 1.3150 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Readings | Winding Temp Max | 50 | °C |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Readings | Winding Temp Present | 50 | °C |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | ST000852 | Structure | 450-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | 0929 | NonLTC | 381-1 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 800 | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | 0929 | NonLTC | 381-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | 0929 | NonLTC | 381-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Low | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | 0929 | NonLTC | 381-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | ST000300 | Structure | 838-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | ST000300 | Structure | 838-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | ST000300 | Structure | 838-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | ST000300 | Structure | 838-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | ST000300 | Structure | 838-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | ST000300 | Structure | 838-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | ST000300 | Structure | 838-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | ST000300 | Structure | 838-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | ST000300 | Structure | 838-Structure | Structure Patrol Inspection | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | ST000300 | Structure | 838-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | ST000300 | Structure | 838-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | ST000300 | Structure | 838-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | ST000300 | Structure | 838-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | ST000300 | Structure | 838-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | ST000300 | Structure | 838-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BCH001391 | Charger | 602-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BCH001391 | Charger | 602-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BCH001391 | Charger | 602-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BCH001391 | Charger | 602-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BCH001391 | Charger | 602-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .9 | amps |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1098 | Regulator | 314-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1098 | Regulator | 314-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BCH001391 | Charger | 602-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.3 | VDC |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BCH001391 | Charger | 602-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.3 | VDC |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BCH001391 | Charger | 602-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | ST000300 | Structure | 838-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | ST000300 | Structure | 838-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | ST000300 | Structure | 838-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | ST000300 | Structure | 838-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | ST000300 | Structure | 838-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | ST000300 | Structure | 838-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | ST000300 | Structure | 838-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | ST000300 | Structure | 838-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001099 | Battery | 182-603 MOS Battery and Charger | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001099 | Battery | 182-603 MOS Battery and Charger | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BAT001099 | Battery | 182-603 MOS Battery and Charger | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | ST000087 | Structure | 314-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Readings | Unknown Operations | 0 | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | ST000087 | Structure | 314-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | ST000087 | Structure | 314-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | ST000087 | Structure | 314-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | ST000087 | Structure | 314-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | ST000087 | Structure | 314-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC000019 | RecloserElectronic | 314-0736 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC000019 | RecloserElectronic | 314-0736 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC000019 | RecloserElectronic | 314-0736 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC000019 | RecloserElectronic | 314-0736 | Recloser Electronic Patrol Inspection | Operations Counter | 18 | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC000019 | RecloserElectronic | 314-0736 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | YD000929 | Yard | 450-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | YD000929 | Yard | 450-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | YD000929 | Yard | 450-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BK000704 | BreakerVacuum | 563-0868 | VCB Readings | 9 Month Operations | 6 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | YD000929 | Yard | 450-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | YD000929 | Yard | 450-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | YD000929 | Yard | 450-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | YD000929 | Yard | 450-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | YD000929 | Yard | 450-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | ST000087 | Structure | 314-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Readings | Operations This Read Vac | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Readings | Operations Counter AL | 149 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Readings | Operations Counter AF | 149 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | YD000001 | Yard | 350-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Readings | Unknown Operations | 0 | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1098 | Regulator | 314-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1098 | Regulator | 314-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1098 | Regulator | 314-1 C | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | YD000001 | Yard | 350-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | YD000001 | Yard | 350-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | YD000001 | Yard | 350-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | YD000001 | Yard | 350-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | YD000001 | Yard | 350-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | YD000001 | Yard | 350-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | YD000001 | Yard | 350-Yard | Yard Patrol Inspection | General Comments | | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | YD000001 | Yard | 350-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | YD000001 | Yard | 350-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | YD000001 | Yard | 350-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Readings | 9 Month Operations | 2 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1098 | Regulator | 314-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1098 | Regulator | 314-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Readings | Amps A Ø | 58.0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Readings | Amps B Ø | 132.0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Readings | Amps C Ø | 20.0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1098 | Regulator | 314-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1098 | Regulator | 314-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1098 | Regulator | 314-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1098 | Regulator | 314-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1098 | Regulator | 314-1 C | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1098 | Regulator | 314-1 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1098 | Regulator | 314-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1098 | Regulator | 314-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Readings | General Comments | | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Readings | Operations Counter AF | 164 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Readings | Operations Counter AL | 164 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Readings | Operations This Read Vac | 1 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Readings | Switching Operations | 1 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001813 | BreakerVacuum | 780-0356 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Readings | 9 Month Operations | 2 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Readings | Amps A Ø | 67.0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Readings | Amps B Ø | 63.0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Readings | Amps C Ø | 62.0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Readings | Oil Temp Max | 42 | °C |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Readings | Amps C Ø | 0.0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Readings | Amps B Ø | 0.0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Readings | Amps A Ø | 0.0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Readings | General Comments | | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | YD000001 | Yard | 350-Yard | Yard Patrol Inspection | Ambient Temp | 38 | °F |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Readings | 9 Month Operations VCB New | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Readings | LTC Totalizer Reading | 278.40 | kw |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Patrol Inspection | General Comments | added nitrogen | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Readings | General Comments | | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | CH000064 | ControlHouse | 182-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | CH000064 | ControlHouse | 182-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | CH000064 | ControlHouse | 182-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | CH000064 | ControlHouse | 182-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | CH000064 | ControlHouse | 182-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | CH000064 | ControlHouse | 182-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | CH000064 | ControlHouse | 182-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | CH000064 | ControlHouse | 182-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | CH000064 | ControlHouse | 182-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | CH000064 | ControlHouse | 182-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | CH000064 | ControlHouse | 182-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | CH000064 | ControlHouse | 182-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | CH000064 | ControlHouse | 182-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | CH000064 | ControlHouse | 182-Control House | Control House Patrol Inspection | General Comments | | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | CH000064 | ControlHouse | 182-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | CH000064 | ControlHouse | 182-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | CH000064 | ControlHouse | 182-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | CH000064 | ControlHouse | 182-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | CH000064 | ControlHouse | 182-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Readings | 9 Month Operations | 0 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | YD000001 | Yard | 350-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Readings | Operations Counter AF | 166 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Readings | Operations Counter AL | 166 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Readings | Operations This Read Vac | 2 | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | YD000292 | Yard | 838-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | YD000292 | Yard | 838-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BCH001310 | Charger | 592-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BCH001310 | Charger | 592-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Readings | Operations Counter AL | 161 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Readings | Operations Counter AF | 161 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Readings | General Comments | | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Readings | General Comments | | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Readings | Amps C Ø | 0.0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Readings | Amps B Ø | 0.0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Readings | Amps A Ø | 0.0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001828 | BreakerVacuum | 695-1 | VCB Readings | 9 Month Operations | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | YD000292 | Yard | 838-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | ST000300 | Structure | 838-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Readings | Operations Counter AF | 124 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | FE000870 | Fence | 450-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | FE000870 | Fence | 450-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | FE000870 | Fence | 450-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | FE000870 | Fence | 450-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | FE000870 | Fence | 450-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | FE000870 | Fence | 450-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | FE000870 | Fence | 450-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Readings | Operations Counter AL | 124 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Readings | Operations This Read Vac | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Readings | 9 Month Operations | 4 | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | YD000178 | Yard | 503-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | YD000178 | Yard | 503-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | YD000178 | Yard | 503-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | YD000178 | Yard | 503-Yard | Yard Patrol Inspection | General Comments | | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001816 | BreakerVacuum | 350-0776 | VCB Readings | Amps A Ø | 58.0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | ST000364 | Structure | 522-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | ST000364 | Structure | 522-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | ST000364 | Structure | 522-Structure | Structure Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | ST000364 | Structure | 522-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | LTCC000132 | LTCControl | 592-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | LTCC000132 | LTCControl | 592-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | LTCC000132 | LTCControl | 592-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | ST000364 | Structure | 522-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | ST000364 | Structure | 522-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | ST000364 | Structure | 522-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | ST000364 | Structure | 522-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | ST000364 | Structure | 522-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | ST000364 | Structure | 522-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | ST000364 | Structure | 522-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | LTCMechanism | 695-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | LTCMechanism | 695-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | LTCMechanism | 695-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | LTCMechanism | 695-1 | LTC Counter Readings | LTC Operations Since Last Insp | 1 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | LTCMechanism | 695-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 10 | °C |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | LTCMechanism | 695-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 20 | °C |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | LTCMechanism | 695-1 | LTC Counter Readings | LTC Min Tap Position | 4L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | FE000289 | Fence | 838-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | FE000289 | Fence | 838-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | FE000289 | Fence | 838-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | FE000289 | Fence | 838-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | FE000289 | Fence | 838-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | FE000289 | Fence | 838-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | FE000289 | Fence | 838-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | FE000289 | Fence | 838-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | FE000289 | Fence | 838-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | FE000289 | Fence | 838-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | FE000289 | Fence | 838-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | LTCC000132 | LTCControl | 592-1 | LTC Control Insp | LTC Output Voltage Level | 124.1 | VAC |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | LTCC000132 | LTCControl | 592-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | LTCC000132 | LTCControl | 592-1 | LTC Control Insp | General Comments | | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | LTCC000132 | LTCControl | 592-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | LTCC000132 | LTCControl | 592-1 | LTC Control Insp | All Connections OK? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1098 | Regulator | 314-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001814 | BreakerVacuum | 780-0361 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | FE000289 | Fence | 838-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | FE000289 | Fence | 838-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | FE000289 | Fence | 838-Fence | Fence Patrol Inspection | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | FE000289 | Fence | 838-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | FE000289 | Fence | 838-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | LTCMechanism | 695-1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | LTCMechanism | 695-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | LTCMechanism | 695-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | LTCMechanism | 695-1 | LTC Counter Readings | LTC As Left Counter | 43616 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | LTCMechanism | 695-1 | LTC Counter Readings | LTC As Found Counter | 43616 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | LTCMechanism | 695-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | LTCMechanism | 695-1 | LTC Counter Readings | General Comments | | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BCH001310 | Charger | 592-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BCH001310 | Charger | 592-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BCH001310 | Charger | 592-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.8 | amps |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BCH001310 | Charger | 592-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | LTCMechanism | 695-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | LTCMechanism | 695-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | YD000292 | Yard | 838-Yard | Yard Patrol Inspection | Ambient Temp | 28 | °F |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | YD000292 | Yard | 838-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | YD000292 | Yard | 838-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | YD000292 | Yard | 838-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | YD000292 | Yard | 838-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | YD000292 | Yard | 838-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | YD000292 | Yard | 838-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | YD000292 | Yard | 838-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | YD000292 | Yard | 838-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | YD000292 | Yard | 838-Yard | Yard Patrol Inspection | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | YD000292 | Yard | 838-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | YD000292 | Yard | 838-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | YD000292 | Yard | 838-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | YD000292 | Yard | 838-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | n | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Readings | 9 Month Operations | 15 | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000138 | Regulator | 504-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000138 | Regulator | 504-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000138 | Regulator | 504-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.9 | volts |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000138 | Regulator | 504-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 13634 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | YD000547 | Yard | 649-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | YD000547 | Yard | 649-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | KR0029 | Regulator | 504-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | KR0029 | Regulator | 504-1 A | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | YD000929 | Yard | 450-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | YD000929 | Yard | 450-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | YD000929 | Yard | 450-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | YD000929 | Yard | 450-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | YD000547 | Yard | 649-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | YD000547 | Yard | 649-Yard | Yard Patrol Inspection | General Comments | | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | YD000547 | Yard | 649-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | YD000547 | Yard | 649-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | LTCMechanism | 402-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | LTCMechanism | 402-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | LTCMechanism | 402-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | LTCMechanism | 402-1 | LTC Counter Readings | LTC Operations Since Last Insp | 786 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | LTCMechanism | 402-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | YD000929 | Yard | 450-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | YD000929 | Yard | 450-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | YD000929 | Yard | 450-Yard | Yard Patrol Inspection | Ambient Temp | 28 | °F |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | YD000081 | Yard | 314-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | YD000081 | Yard | 314-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | YD000081 | Yard | 314-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | YD000081 | Yard | 314-Yard | Yard Patrol Inspection | General Comments | | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | YD000081 | Yard | 314-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | YD000081 | Yard | 314-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | FE000447 | Fence | 592-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | FE000447 | Fence | 592-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | FE000447 | Fence | 592-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | FE000447 | Fence | 592-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | FE000447 | Fence | 592-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BCH001403 | Charger | 563-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BCH001403 | Charger | 563-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BCH001403 | Charger | 563-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BCH001403 | Charger | 563-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BCH001403 | Charger | 563-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .9 | amps |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BCH001403 | Charger | 563-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BCH001403 | Charger | 563-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BCH001403 | Charger | 563-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | FE000447 | Fence | 592-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | FE000447 | Fence | 592-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Readings | Operations This Read Vac | 6 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | FE000447 | Fence | 592-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | FE000447 | Fence | 592-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | FE000447 | Fence | 592-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | FE000447 | Fence | 592-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | FE000447 | Fence | 592-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Readings | Switching Operations | 6 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | FE000447 | Fence | 592-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | FE000447 | Fence | 592-Fence | Fence Patrol Inspection | General Comments | | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | FE000447 | Fence | 592-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | FE000447 | Fence | 592-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | YD000081 | Yard | 314-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | YD000081 | Yard | 314-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | YD000081 | Yard | 314-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | YD000081 | Yard | 314-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | YD000081 | Yard | 314-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Readings | 9 Month Operations | 1 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000138 | Regulator | 504-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000138 | Regulator | 504-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC901736 | RecloserElectronic | 314-0737 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC901736 | RecloserElectronic | 314-0737 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC901736 | RecloserElectronic | 314-0737 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC901736 | RecloserElectronic | 314-0737 | Recloser Electronic Patrol Inspection | Operations Counter | 13 | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC901736 | RecloserElectronic | 314-0737 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC901736 | RecloserElectronic | 314-0737 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC901736 | RecloserElectronic | 314-0737 | Recloser Electronic Patrol Inspection | General Comments | | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC901736 | RecloserElectronic | 314-0737 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Readings | LTC Totalizer Reading | 2211.84 | kw |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Readings | General Comments | | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC901736 | RecloserElectronic | 314-0737 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Readings | Amps C Ø | 35.0 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Readings | Amps B Ø | 26.0 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Readings | Amps A Ø | 43.0 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC901736 | RecloserElectronic | 314-0737 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC901736 | RecloserElectronic | 314-0737 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Readings | Operations Counter AF | 248 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Readings | Operations Counter AL | 248 | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC901736 | RecloserElectronic | 314-0737 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC901736 | RecloserElectronic | 314-0737 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC901736 | RecloserElectronic | 314-0737 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC901736 | RecloserElectronic | 314-0737 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC901736 | RecloserElectronic | 314-0737 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC901736 | RecloserElectronic | 314-0737 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC901736 | RecloserElectronic | 314-0737 | Recloser Electronic Patrol Inspection | Amps C Ø | 7.9 | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC901736 | RecloserElectronic | 314-0737 | Recloser Electronic Patrol Inspection | Amps B Ø | 8.4 | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC901736 | RecloserElectronic | 314-0737 | Recloser Electronic Patrol Inspection | Amps A Ø | 12.6 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | YD000002 | Yard | 602-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | YD000002 | Yard | 602-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | YD000002 | Yard | 602-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | YD000002 | Yard | 602-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | LTCMechanism | 402-1 | LTC Counter Readings | LTC As Found Counter | 42595 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | LTCMechanism | 402-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | LTCMechanism | 402-1 | LTC Counter Readings | General Comments | | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | LTCMechanism | 402-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | ST000001 | Structure | 350-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | ST000001 | Structure | 350-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | ST000001 | Structure | 350-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | ST000001 | Structure | 350-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | ST000001 | Structure | 350-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | ST000001 | Structure | 350-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | ST000001 | Structure | 350-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | ST000001 | Structure | 350-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | ST000001 | Structure | 350-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | ST000001 | Structure | 350-Structure | Structure Patrol Inspection | General Comments | | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | ST000001 | Structure | 350-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | ST000001 | Structure | 350-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | YD000002 | Yard | 602-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | YD000002 | Yard | 602-Yard | Yard Patrol Inspection | Ambient Temp | 34 | °F |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | ST000001 | Structure | 350-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | ST000001 | Structure | 350-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | ST000001 | Structure | 350-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | ST000001 | Structure | 350-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | ST000001 | Structure | 350-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | ST000001 | Structure | 350-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Readings | Operations Counter AF | 446 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Readings | Operations Counter AL | 446 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Readings | Operations This Read Vac | 1 | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | YD000547 | Yard | 649-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | YD000547 | Yard | 649-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | YD000547 | Yard | 649-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | YD000547 | Yard | 649-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Readings | Switching Operations | 1 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | YD000547 | Yard | 649-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | YD000547 | Yard | 649-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | YD000547 | Yard | 649-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | YD000547 | Yard | 649-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | FE000542 | Fence | 649-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | FE000542 | Fence | 649-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | FE000542 | Fence | 649-Fence | Fence Patrol Inspection | General Comments | | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | FE000542 | Fence | 649-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | FE000542 | Fence | 649-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | FE000542 | Fence | 649-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | FE000542 | Fence | 649-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | FE000542 | Fence | 649-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | FE000542 | Fence | 649-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | FE000542 | Fence | 649-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | FE000542 | Fence | 649-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Readings | 9 Month Operations | 1 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | ST000001 | Structure | 350-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | ST000001 | Structure | 350-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | ST000001 | Structure | 350-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | ST000001 | Structure | 350-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | LTCMechanism | 402-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | KR0029 | Regulator | 504-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | KR0029 | Regulator | 504-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | KR0029 | Regulator | 504-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000138 | Regulator | 504-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000138 | Regulator | 504-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000138 | Regulator | 504-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000138 | Regulator | 504-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | FE000542 | Fence | 649-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | FE000542 | Fence | 649-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | FE000542 | Fence | 649-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | FE000542 | Fence | 649-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | FE000542 | Fence | 649-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Readings | Amps A Ø | 78.0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Readings | Amps B Ø | 69.0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Readings | Amps C Ø | 78.0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Readings | Amps C Ø | 0.0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Readings | Amps B Ø | 0.0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Readings | Amps A Ø | 0.0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | YD000081 | Yard | 314-Yard | Yard Patrol Inspection | Ambient Temp | 32 | °F |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | LTCMechanism | 402-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | LTCMechanism | 402-1 | LTC Counter Readings | LTC Max Tap Position | 16R | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | LTCMechanism | 402-1 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | LTCMechanism | 402-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | KR0029 | Regulator | 504-1 A | Regulator Patrol Inspection | Max Tap Position | 8R | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | KR0029 | Regulator | 504-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | KR0029 | Regulator | 504-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | KR0029 | Regulator | 504-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | KR0029 | Regulator | 504-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | KR0029 | Regulator | 504-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | KR0029 | Regulator | 504-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | KR0029 | Regulator | 504-1 A | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BAT001467 | Battery | 563-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BAT001467 | Battery | 563-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BAT001467 | Battery | 563-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BAT001467 | Battery | 563-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BAT001467 | Battery | 563-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BAT001467 | Battery | 563-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BAT001467 | Battery | 563-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BAT001467 | Battery | 563-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #'s |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | KR0029 | Regulator | 504-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | KR0029 | Regulator | 504-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | C0483 | LTCMechanism | 402-1 | LTC Counter Readings | LTC As Left Counter | 42959 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BAT001467 | Battery | 563-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BAT001467 | Battery | 563-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BAT001467 | Battery | 563-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BAT001467 | Battery | 563-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BAT001467 | Battery | 563-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 30 | °F |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | BAT001467 | Battery | 563-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Readings | General Comments | | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000004 | BreakerVacuum | 182-3402 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | ST000005 | Structure | 602-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | ST000005 | Structure | 602-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | ST000005 | Structure | 602-Structure | Structure Patrol Inspection | General Comments | | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | ST000005 | Structure | 602-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | ST000005 | Structure | 602-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | ST000005 | Structure | 602-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | ST000005 | Structure | 602-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | ST000005 | Structure | 602-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | ST000005 | Structure | 602-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | ST000005 | Structure | 602-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | ST000005 | Structure | 602-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | ST000005 | Structure | 602-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | YD000002 | Yard | 602-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | YD000002 | Yard | 602-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | YD000002 | Yard | 602-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | YD000002 | Yard | 602-Yard | Yard Patrol Inspection | General Comments | left of the gate in the corner of station a hole has formed from wash out and is starting to run water under the fence. | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | YD000002 | Yard | 602-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | YD000002 | Yard | 602-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Readings | Operations Counter AF | 116 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Readings | Num Operations Last 9 Months | 1 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Patrol Inspection | General Comments | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Readings | General Comments | | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Readings | Fault Operations | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Readings | Amps C Ø | 0.0 | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | KR0029 | Regulator | 504-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | KR0029 | Regulator | 504-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Readings | Amps B Ø | 0.0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Readings | Amps A Ø | 0.0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | ST000852 | Structure | 450-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | B0439 | WithLTC | 838-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | LTCMechanism | 522-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | LTCMechanism | 522-1 | LTC Counter Readings | LTC Operations Since Last Insp | 429 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | LTCMechanism | 522-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | LTCMechanism | 522-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | LTCMechanism | 522-1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | LTCMechanism | 522-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | LTCMechanism | 522-1 | LTC Counter Readings | LTC As Left Counter | 12806 | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | 0929 | NonLTC | 381-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | 0929 | NonLTC | 381-1 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | 0929 | NonLTC | 381-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | 0929 | NonLTC | 381-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | 0929 | NonLTC | 381-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | 0929 | NonLTC | 381-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | 0929 | NonLTC | 381-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | 0929 | NonLTC | 381-1 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | LTCMechanism | 522-1 | LTC Counter Readings | LTC As Found Counter | 12806 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | LTCMechanism | 522-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | LTCMechanism | 522-1 | LTC Counter Readings | General Comments | | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | LTCMechanism | 522-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | LTCMechanism | 522-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | ST000005 | Structure | 602-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | ST000005 | Structure | 602-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Readings | General Comments | | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Patrol Inspection | Ambient Temperature | 28 | °F |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Readings | Operations Counter AL | 172 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Readings | Operations This Read Vac | 0 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Readings | Switching Operations | 1 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Readings | Operations This Read Vac | 1 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Readings | Operations Counter AL | 254 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Readings | Operations Counter AF | 254 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | 0929 | NonLTC | 381-1 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | 0929 | NonLTC | 381-1 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | 0929 | NonLTC | 381-1 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | 0929 | NonLTC | 381-1 A | NonLTC Transformer Readings | Oil Temp Present | 18 | °C |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | 0929 | NonLTC | 381-1 A | NonLTC Transformer Readings | Oil Temp Max | 28 | °C |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | 0929 | NonLTC | 381-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | 0929 | NonLTC | 381-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | 0929 | NonLTC | 381-1 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 358.08 | kw |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | 0929 | NonLTC | 381-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | 0929 | NonLTC | 381-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | 0929 | NonLTC | 381-1 A | NonLTC Transformer Readings | General Comments | | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | 0929 | NonLTC | 381-1 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | ST000852 | Structure | 450-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | ST000852 | Structure | 450-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | ST000852 | Structure | 450-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | ST000852 | Structure | 450-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | ST000852 | Structure | 450-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | ST000852 | Structure | 450-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | ST000852 | Structure | 450-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | ST000852 | Structure | 450-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | ST000852 | Structure | 450-Structure | Structure Patrol Inspection | General Comments | | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | ST000852 | Structure | 450-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | ST000852 | Structure | 450-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | ST000852 | Structure | 450-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | ST000852 | Structure | 450-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | ST000852 | Structure | 450-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | ST000852 | Structure | 450-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | ST000852 | Structure | 450-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | ST000852 | Structure | 450-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | ST000852 | Structure | 450-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | ST000852 | Structure | 450-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | ST000852 | Structure | 450-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | ST000087 | Structure | 314-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | ST000087 | Structure | 314-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | ST000087 | Structure | 314-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | ST000087 | Structure | 314-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | YD000929 | Yard | 450-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | YD000929 | Yard | 450-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | YD000929 | Yard | 450-Yard | Yard Patrol Inspection | General Comments | | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | YD000929 | Yard | 450-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC000019 | RecloserElectronic | 314-0736 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC000019 | RecloserElectronic | 314-0736 | Recloser Electronic Patrol Inspection | General Comments | | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC000019 | RecloserElectronic | 314-0736 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Readings | Follow-up Action Required? | n | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC000019 | RecloserElectronic | 314-0736 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC000019 | RecloserElectronic | 314-0736 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC000019 | RecloserElectronic | 314-0736 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC000019 | RecloserElectronic | 314-0736 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC000019 | RecloserElectronic | 314-0736 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC000019 | RecloserElectronic | 314-0736 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC000019 | RecloserElectronic | 314-0736 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC000019 | RecloserElectronic | 314-0736 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC000019 | RecloserElectronic | 314-0736 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | YD000929 | Yard | 450-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | YD000929 | Yard | 450-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Readings | General Comments | | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 9:28 | Distribution | Rose Hill Quarterly Inspection | BK001817 | BreakerVacuum | 350-0777 | VCB Readings | Operations Counter AF | 172 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Readings | Unknown Operations | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Readings | Switching Operations | 1 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Patrol Inspection | SF6 Pressure Pole 3 | 86 | psi |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Patrol Inspection | SF6 Pressure Pole 2 | 86 | psi |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Patrol Inspection | SF6 Pressure Pole 1 | 86 | psi |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Readings | Operations This Read SF6 | 1 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | BK001724 | BreakerSF6 | 695-728 | GCB Readings | Operations Counter AL | 116 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | CH000504 | ControlHouse | 695-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | CH000504 | ControlHouse | 695-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | CH000504 | ControlHouse | 695-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | CH000504 | ControlHouse | 695-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | CH000504 | ControlHouse | 695-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | CH000504 | ControlHouse | 695-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | ST000441 | Structure | 592-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | ST000441 | Structure | 592-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | ST000441 | Structure | 592-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | ST000441 | Structure | 592-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | ST000441 | Structure | 592-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | ST000441 | Structure | 592-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | ST000441 | Structure | 592-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | ST000441 | Structure | 592-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | ST000441 | Structure | 592-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | ST000441 | Structure | 592-Structure | Structure Patrol Inspection | General Comments | | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | ST000441 | Structure | 592-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | ST000441 | Structure | 592-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | ST000441 | Structure | 592-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | ST000441 | Structure | 592-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | ST000441 | Structure | 592-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | ST000441 | Structure | 592-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | ST000441 | Structure | 592-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | ST000441 | Structure | 592-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | ST000441 | Structure | 592-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | ST000441 | Structure | 592-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | ST000441 | Structure | 592-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | ST000441 | Structure | 592-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | ST000005 | Structure | 602-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | ST000005 | Structure | 602-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | ST000005 | Structure | 602-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | ST000005 | Structure | 602-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | ST000005 | Structure | 602-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | ST000005 | Structure | 602-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | ST000005 | Structure | 602-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | ST000005 | Structure | 602-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | CH000504 | ControlHouse | 695-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | CH000504 | ControlHouse | 695-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | CH000504 | ControlHouse | 695-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | CH000504 | ControlHouse | 695-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | CH000504 | ControlHouse | 695-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | CH000504 | ControlHouse | 695-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | CH000504 | ControlHouse | 695-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | CH000504 | ControlHouse | 695-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | CH000504 | ControlHouse | 695-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | CH000504 | ControlHouse | 695-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | CH000504 | ControlHouse | 695-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | CH000504 | ControlHouse | 695-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000138 | Regulator | 504-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000138 | Regulator | 504-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000138 | Regulator | 504-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000138 | Regulator | 504-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | CH000504 | ControlHouse | 695-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | KR0029 | Regulator | 504-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000138 | Regulator | 504-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Readings | Switching Operations | 6 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Readings | Operations This Read Vac | 6 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Readings | Operations Counter AL | 241 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Readings | Operations Counter AF | 241 | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000138 | Regulator | 504-1 C | Regulator Patrol Inspection | General Comments | | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000138 | Regulator | 504-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000138 | Regulator | 504-1 C | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000138 | Regulator | 504-1 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | KR0029 | Regulator | 504-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | KR0029 | Regulator | 504-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 14208 | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | KR0029 | Regulator | 504-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | KR0029 | Regulator | 504-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | KR0029 | Regulator | 504-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | KR0029 | Regulator | 504-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001105 | BreakerVacuum | 592-2149 | VCB Readings | General Comments | | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Readings | Amps C Ø | 0.0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Readings | Amps B Ø | 0.0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Readings | Amps A Ø | 3.0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001514 | BreakerVacuum | 450-0520 | VCB Readings | 9 Month Operations | 2 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Readings | Totalizer Meter Reading | .4608 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Readings | 9 Month Operations | 12 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Readings | Oil Temp Present | 48 | °C |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Readings | Oil Temp Max | 53 | °C |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | M0043 | WithLTC | 855-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Readings | General Comments | | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC000019 | RecloserElectronic | 314-0736 | Recloser Electronic Patrol Inspection | Amps C Ø | 22.0 | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC000019 | RecloserElectronic | 314-0736 | Recloser Electronic Patrol Inspection | Amps B Ø | 22.0 | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | RC000019 | RecloserElectronic | 314-0736 | Recloser Electronic Patrol Inspection | Amps A Ø | 19.0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | BK000005 | BreakerVacuum | 182-3403 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | YD000547 | Yard | 649-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/1/2023 11:58 | Distribution | Beattyville City Quarterly Inspection | YD000547 | Yard | 649-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000138 | Regulator | 504-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000138 | Regulator | 504-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000138 | Regulator | 504-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000138 | Regulator | 504-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | RG000138 | Regulator | 504-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | CH000504 | ControlHouse | 695-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Readings | Amps A Ø | 0.0 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Readings | Amps B Ø | 0.0 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Readings | Amps C Ø | 14.0 | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | CH000504 | ControlHouse | 695-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BK001104 | BreakerVacuum | 592-2148 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Readings | General Comments | | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Readings | Operations Counter AF | 168 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Readings | Operations Counter AL | 168 | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | FE000100 | Fence | 800-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | FE000100 | Fence | 800-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Readings | Operations This Read Vac | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | FE000836 | Fence | 182-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | FE000836 | Fence | 182-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | FE000836 | Fence | 182-Fence | Fence Patrol Inspection | General Comments | | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | FE000836 | Fence | 182-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | FE000836 | Fence | 182-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | FE000836 | Fence | 182-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | FE000836 | Fence | 182-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | FE000836 | Fence | 182-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | FE000836 | Fence | 182-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | FE000836 | Fence | 182-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | FE000836 | Fence | 182-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | FE000836 | Fence | 182-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | FE000836 | Fence | 182-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | FE000836 | Fence | 182-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | FE000836 | Fence | 182-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | FE000836 | Fence | 182-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Readings | 9 Month Operations | 2 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Readings | Amps A Ø | 10.0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Readings | Amps B Ø | 12.0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Readings | Amps C Ø | 12.0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | CH000334 | ControlHouse | 602-Control house | Control House Patrol  Inspection | Acceptable Building Appearnce? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | CH000334 | ControlHouse | 602-Control house | Control House Patrol  Inspection | AC/DC Dist Panels Labeled? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Readings | General Comments | | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Readings | Operations Counter AF | 165 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Readings | Operations Counter AL | 165 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Readings | Operations This Read Vac | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | FE000179 | Fence | 503-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | FE000179 | Fence | 503-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | FE000179 | Fence | 503-Fence | Fence Patrol Inspection | General Comments | Barbed wire rusty, and trees overhanging fence | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | FE000179 | Fence | 503-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | FE000179 | Fence | 503-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | FE000179 | Fence | 503-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | FE000179 | Fence | 503-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | FE000179 | Fence | 503-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | FE000179 | Fence | 503-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | FE000179 | Fence | 503-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | FE000179 | Fence | 503-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Readings | 9 Month Operations | 0 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Readings | General Comments | | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Readings | LTC Totalizer Reading | 5477.76 | kw |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Readings | 9 Month Operations | 0 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Readings | Totalizer Meter Reading | .5706 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Readings | Amps A Ø | 163.0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Readings | Amps B Ø | 96.0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Readings | Amps C Ø | 171.0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 500 | psi |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Readings | Oil Temp Max | 20 | °C |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Readings | Oil Temp Present | 10 | °C |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | ST000370 | Structure | 563-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | FE000100 | Fence | 800-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | FE000100 | Fence | 800-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | FE000100 | Fence | 800-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | FE000100 | Fence | 800-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | FE000100 | Fence | 800-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | FE000100 | Fence | 800-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | FE000100 | Fence | 800-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | FE000100 | Fence | 800-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Readings | Winding Temp Max | 20 | °C |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Readings | Winding Temp Present | 10 | °C |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0128 | Regulator | 182-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0128 | Regulator | 182-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0128 | Regulator | 182-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0128 | Regulator | 182-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.7 | volts |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0128 | Regulator | 182-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 2730 | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0128 | Regulator | 182-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0128 | Regulator | 182-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0128 | Regulator | 182-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0128 | Regulator | 182-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Readings | 9 Month Operations | 5 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Readings | General Comments | | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Readings | Operations Counter AF | 168 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Readings | Operations Counter AL | 168 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Readings | Amps A Ø | 83.0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Readings | Amps B Ø | 113.0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Readings | Amps C Ø | 108.0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Readings | Winding Temp Max | 50 | °C |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.1600 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BAT001388 | Battery | 855-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BAT001388 | Battery | 855-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BAT001388 | Battery | 855-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 25.0 | VDC |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BAT001388 | Battery | 855-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BAT001388 | Battery | 855-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BAT001388 | Battery | 855-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BAT001388 | Battery | 855-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BAT001388 | Battery | 855-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BAT001388 | Battery | 855-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BAT001388 | Battery | 855-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BAT001388 | Battery | 855-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BAT001388 | Battery | 855-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BAT001388 | Battery | 855-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Readings | General Comments | | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Readings | Operations Counter AF | 241 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Readings | Operations Counter AL | 241 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Readings | Operations This Read Vac | 1 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Readings | Switching Operations | 1 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001336 | BreakerVacuum | 780-0355 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | FE000179 | Fence | 503-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | FE000179 | Fence | 503-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | FE000179 | Fence | 503-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | FE000179 | Fence | 503-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | n | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | FE000179 | Fence | 503-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | n | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001167 | BreakerVacuum | 522-0514 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Readings | 9 Month Operations | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Readings | Amps A Ø | 280.0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Readings | Amps B Ø | 210.0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Readings | Amps C Ø | 245.0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | FE000100 | Fence | 800-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | YD000100 | Yard | 800-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | YD000100 | Yard | 800-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | YD000100 | Yard | 800-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | YD000100 | Yard | 800-Yard | Yard Patrol Inspection | General Comments | Yard light is not working, wired directly into staion supply. ...needs to be moved | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | YD000100 | Yard | 800-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | YD000100 | Yard | 800-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | YD000100 | Yard | 800-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | ST000032 | Structure | 855-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | ST000032 | Structure | 855-Structure | Structure Patrol Inspection | General Comments | | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | ST000032 | Structure | 855-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | ST000032 | Structure | 855-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | ST000032 | Structure | 855-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | ST000032 | Structure | 855-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | ST000032 | Structure | 855-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | ST000032 | Structure | 855-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | ST000032 | Structure | 855-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | ST000032 | Structure | 855-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | ST000032 | Structure | 855-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0128 | Regulator | 182-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0128 | Regulator | 182-1 A | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0128 | Regulator | 182-1 A | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0128 | Regulator | 182-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0128 | Regulator | 182-1 A | Regulator Patrol Inspection | General Comments | | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0128 | Regulator | 182-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0128 | Regulator | 182-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0128 | Regulator | 182-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | YD000100 | Yard | 800-Yard | Yard Patrol Inspection | Ambient Temp | 34 | °F |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | YD000100 | Yard | 800-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | YD000100 | Yard | 800-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | YD000100 | Yard | 800-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | YD000100 | Yard | 800-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | YD000100 | Yard | 800-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0128 | Regulator | 182-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0128 | Regulator | 182-1 A | Regulator Patrol Inspection | Current Tap Position | 3R | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0128 | Regulator | 182-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0128 | Regulator | 182-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0128 | Regulator | 182-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0128 | Regulator | 182-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | KR0128 | Regulator | 182-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | B0261 | NonLTC | 504-1 | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | B0261 | NonLTC | 504-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | B0261 | NonLTC | 504-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | B0261 | NonLTC | 504-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | B0261 | NonLTC | 504-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | B0261 | NonLTC | 504-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | B0261 | NonLTC | 504-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | B0261 | NonLTC | 504-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | B0261 | NonLTC | 504-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .3624 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1600 | psi |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Readings | LTC Totalizer Reading | 12873.60 | kw |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Readings | General Comments | | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | YD000031 | Yard | 855-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | YD000031 | Yard | 855-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | YD000031 | Yard | 855-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | YD000031 | Yard | 855-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | YD000031 | Yard | 855-Yard | Yard Patrol Inspection | General Comments | | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | YD000031 | Yard | 855-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | YD000031 | Yard | 855-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | YD000031 | Yard | 855-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Readings | Switching Operations | 4 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Readings | Operations This Read Vac | 4 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Readings | Operations Counter AL | 160 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Readings | Operations Counter AF | 160 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | YD000368 | Yard | 563-Yard | Yard Patrol Inspection | Ambient Temp | 30 | °F |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Readings | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Patrol Inspection | General Comments | | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1022 | Regulator | 314-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1022 | Regulator | 314-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1022 | Regulator | 314-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1022 | Regulator | 314-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1022 | Regulator | 314-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 53695 | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1022 | Regulator | 314-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.5 | volts |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1022 | Regulator | 314-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1022 | Regulator | 314-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1022 | Regulator | 314-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1022 | Regulator | 314-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1022 | Regulator | 314-1 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1022 | Regulator | 314-1 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | FE000100 | Fence | 800-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | FE000100 | Fence | 800-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | FE000362 | Fence | 563-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1022 | Regulator | 314-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1022 | Regulator | 314-1 B | Regulator Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1022 | Regulator | 314-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1022 | Regulator | 314-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1022 | Regulator | 314-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1022 | Regulator | 314-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1022 | Regulator | 314-1 B | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1022 | Regulator | 314-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1022 | Regulator | 314-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1022 | Regulator | 314-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1022 | Regulator | 314-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1022 | Regulator | 314-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | ST000370 | Structure | 563-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | ST000370 | Structure | 563-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | ST000370 | Structure | 563-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | ST000370 | Structure | 563-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | ST000370 | Structure | 563-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | ST000370 | Structure | 563-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | ST000370 | Structure | 563-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | ST000370 | Structure | 563-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | ST000370 | Structure | 563-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | ST000370 | Structure | 563-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | ST000370 | Structure | 563-Structure | Structure Patrol Inspection | General Comments | | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | ST000370 | Structure | 563-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | ST000370 | Structure | 563-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | ST000370 | Structure | 563-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | ST000370 | Structure | 563-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | ST000370 | Structure | 563-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | ST000370 | Structure | 563-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | ST000370 | Structure | 563-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | ST000370 | Structure | 563-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | ST000370 | Structure | 563-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | YD000368 | Yard | 563-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | YD000368 | Yard | 563-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | YD000368 | Yard | 563-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | YD000368 | Yard | 563-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | YD000368 | Yard | 563-Yard | Yard Patrol Inspection | General Comments | | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | YD000368 | Yard | 563-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | YD000368 | Yard | 563-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | YD000368 | Yard | 563-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | YD000368 | Yard | 563-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | YD000368 | Yard | 563-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | YD000368 | Yard | 563-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Readings | 9 Month Operations | 1 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | YD000368 | Yard | 563-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | YD000368 | Yard | 563-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | YD000031 | Yard | 855-Yard | Yard Patrol Inspection | Ambient Temp | 34 | °F |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BCH001371 | Charger | 402-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.6 | amps |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BCH001371 | Charger | 402-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BCH001371 | Charger | 402-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BCH001371 | Charger | 402-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | BCH001371 | Charger | 402-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | YD000031 | Yard | 855-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | YD000031 | Yard | 855-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Readings | Winding Temp Present | 20 | °C |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Readings | Winding Temp Max | 25 | °C |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Readings | Totalizer Meter Reading | .5364 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | YD000031 | Yard | 855-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | YD000031 | Yard | 855-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | B0261 | NonLTC | 504-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | B0261 | NonLTC | 504-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Readings | Oil Temp Present | 15 | °C |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Readings | Oil Temp Max | 20 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | B0261 | NonLTC | 504-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | B0261 | NonLTC | 504-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | B0261 | NonLTC | 504-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | B0261 | NonLTC | 504-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | B0261 | NonLTC | 504-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | B0261 | NonLTC | 504-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | B0261 | NonLTC | 504-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | B0261 | NonLTC | 504-1 | NonLTC Transformer Readings | General Comments | | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | B0261 | NonLTC | 504-1 | NonLTC Transformer Patrol Inspection | General Comments | tank seaping around oil drain | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | B0261 | NonLTC | 504-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | B0261 | NonLTC | 504-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | B0261 | NonLTC | 504-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | B0261 | NonLTC | 504-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 434.88 | kw |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | B0261 | NonLTC | 504-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | B0261 | NonLTC | 504-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | B0261 | NonLTC | 504-1 | NonLTC Transformer Readings | Oil Temp Max | 25 | °C |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Readings | Amps C Ø | 413.0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Readings | Amps C Ø | 194.0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Readings | Amps B Ø | 198.0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Readings | Amps A Ø | 185.0 | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | FE000362 | Fence | 563-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | FE000362 | Fence | 563-Fence | Fence Patrol Inspection | General Comments | | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | FE000362 | Fence | 563-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | FE000362 | Fence | 563-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | FE000362 | Fence | 563-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | FE000362 | Fence | 563-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | FE000362 | Fence | 563-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | FE000362 | Fence | 563-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | FE000362 | Fence | 563-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | FE000362 | Fence | 563-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | FE000362 | Fence | 563-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | FE000362 | Fence | 563-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | FE000362 | Fence | 563-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | FE000362 | Fence | 563-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | FE000362 | Fence | 563-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Readings | 9 Month Operations | 4 | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | CH000334 | ControlHouse | 602-Control house | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | CH000334 | ControlHouse | 602-Control house | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | CH000334 | ControlHouse | 602-Control house | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | CH000334 | ControlHouse | 602-Control house | Control House Patrol Inspection | General Comments | | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | CH000334 | ControlHouse | 602-Control house | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | CH000334 | ControlHouse | 602-Control house | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | CH000334 | ControlHouse | 602-Control house | Control House Patrol Inspection | Floor Swept? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | CH000334 | ControlHouse | 602-Control house | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | CH000334 | ControlHouse | 602-Control house | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | CH000334 | ControlHouse | 602-Control house | Control House Patrol Inspection | Evidence of Insects | None | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | CH000334 | ControlHouse | 602-Control house | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | CH000334 | ControlHouse | 602-Control house | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | CH000334 | ControlHouse | 602-Control house | Control House Patrol Inspection | Control House Lighting OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | CH000334 | ControlHouse | 602-Control house | Control House Patrol Inspection | Broom on Site? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Readings | 9 Month Operations | 4 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001166 | BreakerVacuum | 522-0513 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | FE000100 | Fence | 800-Fence | Fence Patrol Inspection | General Comments | barbed wire on front half of station is rusty | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | FE000100 | Fence | 800-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | FE000100 | Fence | 800-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Readings | General Comments | | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Readings | Amps B Ø | 449.0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Readings | Amps A Ø | 415.0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Readings | LTC Totalizer Reading | 0.00 | kw |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | O0187 | WithLTC | 882-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Readings | Amps A Ø | 11.0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Readings | Amps B Ø | 9.0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Readings | Amps C Ø | 16.0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | TX000221 | WithLTC | 450-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Readings | Amps C Ø | 296.0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Readings | Amps B Ø | 288.0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | LTCC000732 | LTCControl | 882-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | LTCC000732 | LTCControl | 882-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | LTCC000732 | LTCControl | 882-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | LTCC000732 | LTCControl | 882-1 | LTC Control Insp | LTC Output Voltage Level | 124.7 | VAC |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Readings | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Readings | Operations Counter AF | 155 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Readings | Operations Counter AL | 155 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Readings | Operations This Read Vac | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Readings | Switching Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001349 | BreakerVacuum | 838-1 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001164 | BreakerVacuum | 838-0507 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | LTCC000732 | LTCControl | 882-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | LTCC000732 | LTCControl | 882-1 | LTC Control Insp | General Comments | | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | LTCC000732 | LTCControl | 882-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/1/2023 13:03 | Distribution | Calloway Quarterly Inspection | LTCC000732 | LTCControl | 882-1 | LTC Control Insp | All Connections OK? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Readings | Operations This Read Vac | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Readings | Operations Counter AL | 151 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Readings | Operations Counter AF | 151 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001516 | BreakerVacuum | 450-1 | VCB Readings | Amps A Ø | 251.0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Readings | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 7:07 | Distribution | Versailles Bypass Quarterly Inspection | BK001165 | BreakerVacuum | 838-0511 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Readings | Amps A Ø | 104.0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Readings | Amps B Ø | 70.0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Readings | Fault Operations C Ø | 0 | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | ST000026 | Structure | 381-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | ST000026 | Structure | 381-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | ST000026 | Structure | 381-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | ST000026 | Structure | 381-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | ST000026 | Structure | 381-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | ST000026 | Structure | 381-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | ST000026 | Structure | 381-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | YD000177 | Yard | 182-Yard | Yard Patrol Inspection | Ambient Temp | 32 | °F |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | YD000177 | Yard | 182-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | YD000177 | Yard | 182-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | YD000177 | Yard | 182-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | YD000177 | Yard | 182-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | YD000177 | Yard | 182-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | YD000177 | Yard | 182-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | YD000177 | Yard | 182-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | YD000177 | Yard | 182-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | YD000177 | Yard | 182-Yard | Yard Patrol Inspection | General Comments | | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | YD000177 | Yard | 182-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | YD000177 | Yard | 182-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/1/2023 12:33 | Distribution | Andover Quarterly Inspection | YD000177 | Yard | 182-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | ST000184 | Structure | 503-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | ST000184 | Structure | 503-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | ST000184 | Structure | 503-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | ST000184 | Structure | 503-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | ST000184 | Structure | 503-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | ST000184 | Structure | 503-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | ST000184 | Structure | 503-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | ST000184 | Structure | 503-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | ST000026 | Structure | 381-Structure | Structure Patrol Inspection | General Comments | | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | ST000026 | Structure | 381-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | ST000026 | Structure | 381-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | ST000026 | Structure | 381-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | ST000026 | Structure | 381-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | LTCC000855 | LTCControl | 402-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | LTCC000855 | LTCControl | 402-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | LTCC000855 | LTCControl | 402-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | LTCC000855 | LTCControl | 402-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | LTCC000855 | LTCControl | 402-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | LTCC000855 | LTCControl | 402-1 | LTC Control Insp | General Comments | | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | LTCC000855 | LTCControl | 402-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | LTCC000855 | LTCControl | 402-1 | LTC Control Insp | All Connections OK? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | LTCC000885 | LTCControl | 563-1 | LTC Control Insp | All Connections OK? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | LTCC000885 | LTCControl | 563-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | LTCC000885 | LTCControl | 563-1 | LTC Control Insp | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | LTCC000885 | LTCControl | 563-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | LTCC000885 | LTCControl | 563-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | LTCC000885 | LTCControl | 563-1 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | LTCC000885 | LTCControl | 563-1 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 2/1/2023 7:22 | Distribution | Shannon Run Quarterly Inspection | LTCC000885 | LTCControl | 563-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | FE000006 | Fence | 602-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | FE000006 | Fence | 602-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | FE000006 | Fence | 602-Fence | Fence Patrol Inspection | General Comments | | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Readings | Amps C Ø | 70.0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | YD000365 | Yard | 402-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | YD000365 | Yard | 402-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | YD000365 | Yard | 402-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | YD000365 | Yard | 402-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | YD000365 | Yard | 402-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | YD000365 | Yard | 402-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | YD000365 | Yard | 402-Yard | Yard Patrol Inspection | Ambient Temp | 30 | °F |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | FE000359 | Fence | 402-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | FE000359 | Fence | 402-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | FE000359 | Fence | 402-Fence | Fence Patrol Inspection | General Comments | | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | FE000359 | Fence | 402-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | FE000359 | Fence | 402-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | ST000032 | Structure | 855-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | FE000359 | Fence | 402-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | FE000359 | Fence | 402-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | FE000359 | Fence | 402-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | FE000359 | Fence | 402-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | FE000359 | Fence | 402-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | FE000359 | Fence | 402-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | FE000359 | Fence | 402-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | FE000359 | Fence | 402-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | FE000359 | Fence | 402-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | FE000359 | Fence | 402-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | FE000359 | Fence | 402-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BCH001308 | Charger | 522-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BCH001308 | Charger | 522-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BCH001308 | Charger | 522-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Readings | 9 Month Operations | 3 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | ST000026 | Structure | 381-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | ST000026 | Structure | 381-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | ST000026 | Structure | 381-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Readings | Operations This Read Vac | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Readings | Operations Counter AL | 175 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Readings | Operations Counter AF | 175 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Readings | General Comments | | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | ST000364 | Structure | 522-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | ST000364 | Structure | 522-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | ST000364 | Structure | 522-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | ST000364 | Structure | 522-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | ST000364 | Structure | 522-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | ST000364 | Structure | 522-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | ST000364 | Structure | 522-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | ST000364 | Structure | 522-Structure | Structure Patrol Inspection | General Comments | | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | ST000364 | Structure | 522-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | ST000364 | Structure | 522-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BAT001240 | Battery | 602-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BAT001240 | Battery | 602-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BAT001240 | Battery | 602-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BAT001240 | Battery | 602-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BAT001382 | Battery | 592-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BAT001382 | Battery | 592-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BAT001382 | Battery | 592-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.2 | VDC |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BAT001382 | Battery | 592-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.3 | VDC |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BAT001382 | Battery | 592-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BAT001382 | Battery | 592-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BAT001382 | Battery | 592-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BAT001382 | Battery | 592-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Water Added | If low,note cell #~'s |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BAT001382 | Battery | 592-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BAT001382 | Battery | 592-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BAT001382 | Battery | 592-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BAT001382 | Battery | 592-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BAT001382 | Battery | 592-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 28 | °F |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BAT001382 | Battery | 592-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BCH001310 | Charger | 592-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/1/2023 11:04 | Distribution | Pine Hill Quarterly Inspection | BCH001310 | Charger | 592-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Readings | Winding Temp Present | 0 | °C |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Readings | Totalizer Meter Reading | .0290 | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BAT001240 | Battery | 602-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BAT001240 | Battery | 602-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BAT001240 | Battery | 602-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BAT001240 | Battery | 602-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BAT001240 | Battery | 602-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BAT001240 | Battery | 602-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BAT001240 | Battery | 602-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BAT001240 | Battery | 602-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | BAT001240 | Battery | 602-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Readings | Fault Adjusted Amps A Phase V | 9.39 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Readings | Fault Adjusted Amps C Phase V | 9.39 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Readings | Fault Operations A Ø | 1 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Readings | Fault Operations C Ø | 1 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 2/1/2023 7:16 | Distribution | Paynes Mill Quarterly Inspection | BK001515 | BreakerVacuum | 450-BT1-2 FUT | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | B0356 | WithLTC | 314-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Readings | Fault Operations A Ø | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Readings | Fault Operations B Ø | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Readings | Fault Operations C Ø | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Readings | Fault Operations Ground | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Readings | Follow-up Action Required? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Patrol Inspection | General Comments | | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Readings | General Comments | | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Readings | Maintenance Operations | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Readings | Operations Counter AF | 229 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Readings | Operations Counter AL | 229 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Readings | Operations This Read Vac | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001810 | BreakerVacuum | 780-0350 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Readings | 9 Month Operations | 3 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1098 | Regulator | 314-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1098 | Regulator | 314-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/2/2023 7:31 | Distribution | Hamer Quarterly Inspection | R1098 | Regulator | 314-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | ST000184 | Structure | 503-Structure | Structure Patrol Inspection | General Comments | | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | ST000184 | Structure | 503-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | ST000184 | Structure | 503-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | ST000184 | Structure | 503-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | ST000184 | Structure | 503-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | ST000184 | Structure | 503-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | ST000184 | Structure | 503-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | ST000184 | Structure | 503-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | ST000184 | Structure | 503-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | ST000184 | Structure | 503-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | ST000184 | Structure | 503-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | ST000184 | Structure | 503-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | ST000184 | Structure | 503-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Readings | Amps A Ø | 80.0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Readings | Amps B Ø | 76.0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Readings | Amps C Ø | 73.0 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | BK001811 | BreakerVacuum | 780-0351 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | ST000026 | Structure | 381-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | ST000026 | Structure | 381-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | ST000026 | Structure | 381-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/2/2023 7:08 | Distribution | Roaring Fork Quarterly Inspection | ST000026 | Structure | 381-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | FE000006 | Fence | 602-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | FE000006 | Fence | 602-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | FE000006 | Fence | 602-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | FE000006 | Fence | 602-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | FE000006 | Fence | 602-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | FE000006 | Fence | 602-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | FE000006 | Fence | 602-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | FE000006 | Fence | 602-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | FE000006 | Fence | 602-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | FE000006 | Fence | 602-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | FE000006 | Fence | 602-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | FE000006 | Fence | 602-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/1/2023 11:22 | Distribution | Meldrum Quarterly Inspection | FE000006 | Fence | 602-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | ST000364 | Structure | 522-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | ST000364 | Structure | 522-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | ST000364 | Structure | 522-Structure | Structure Patrol Inspection | Cabinet Door Seals OK? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | ST000364 | Structure | 522-Structure | Structure Patrol Inspection | Cabinet Paint Condition | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | LTCMechanism | 503-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | LTCMechanism | 503-1 | LTC Counter Readings | LTC Operations Since Last Insp | 391 | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | FE000060 | Fence | 504-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | FE000060 | Fence | 504-Fence | Fence Patrol Inspection | General Comments | | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | FE000060 | Fence | 504-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | FE000060 | Fence | 504-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | ST000032 | Structure | 855-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | ST000032 | Structure | 855-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | ST000032 | Structure | 855-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | ST000032 | Structure | 855-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | ST000032 | Structure | 855-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Readings | LTC Totalizer Reading | 16704.00 | kw |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Readings | General Comments | | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | LTCC000953 | LTCControl | 503-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | LTCC000953 | LTCControl | 503-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | LTCMechanism | 503-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | LTCMechanism | 503-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | LTCMechanism | 503-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | LTCC000953 | LTCControl | 503-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | LTCC000953 | LTCControl | 503-1 | LTC Control Insp | LTC Output Voltage Level | 124.6 | VAC |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | LTCC000301 | LTCControl | 522-1 | LTC Control Insp | All Connections OK? | y | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | LTCMechanism | 780-3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | LTCMechanism | 780-3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | LTCMechanism | 780-3 | LTC Counter Readings | General Comments | | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | LTCMechanism | 780-3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | LTCMechanism | 780-3 | LTC Counter Readings | LTC As Found Counter | 22357 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | LTCMechanism | 780-3 | LTC Counter Readings | LTC As Left Counter | 22365 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | LTCMechanism | 780-3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | LTCMechanism | 780-3 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | LTCMechanism | 780-3 | LTC Counter Readings | LTC Max Tap Position | 9R | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | LTCMechanism | 780-3 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | LTCMechanism | 780-3 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BCH001294 | Charger | 855-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BCH001294 | Charger | 855-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | LTCC000953 | LTCControl | 503-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | LTCC000953 | LTCControl | 503-1 | LTC Control Insp | General Comments | | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | LTCMechanism | 380-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | LTCMechanism | 380-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | LTCMechanism | 380-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | LTCMechanism | 780-3 | LTC Counter Readings | LTC Operations Since Last Insp | 1008 | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | LTCMechanism | 780-3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | LTCMechanism | 780-3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 2/1/2023 9:33 | Distribution | Middlesboro 2 Quarterly Inspection | M0096 | LTCMechanism | 780-3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | ST000106 | Structure | 800-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | LTCMechanism | 380-1 | LTC Counter Readings | LTC Operations Since Last Insp | 843 | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | LTCMechanism | 380-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | LTCMechanism | 380-1 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | LTCMechanism | 380-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | LTCMechanism | 380-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | LTCC000301 | LTCControl | 522-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | ST000106 | Structure | 800-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | ST000106 | Structure | 800-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | ST000106 | Structure | 800-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | LTCC000301 | LTCControl | 522-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | LTCC000301 | LTCControl | 522-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | ST000106 | Structure | 800-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | ST000106 | Structure | 800-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | ST000106 | Structure | 800-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | ST000106 | Structure | 800-Structure | Structure Patrol Inspection | General Comments | | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | LTCC000301 | LTCControl | 522-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | LTCC000301 | LTCControl | 522-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | LTCC000301 | LTCControl | 522-1 | LTC Control Insp | General Comments | | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | ST000106 | Structure | 800-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | ST000106 | Structure | 800-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | ST000106 | Structure | 800-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | LTCC000301 | LTCControl | 522-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | FE000060 | Fence | 504-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | FE000060 | Fence | 504-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | FE000060 | Fence | 504-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | FE000060 | Fence | 504-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | FE000060 | Fence | 504-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | FE000060 | Fence | 504-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | ST000106 | Structure | 800-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | ST000106 | Structure | 800-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | LTCMechanism | 503-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | LTCMechanism | 503-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | ST000032 | Structure | 855-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | ST000032 | Structure | 855-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | ST000032 | Structure | 855-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | ST000032 | Structure | 855-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | ST000032 | Structure | 855-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | LTCMechanism | 503-1 | LTC Counter Readings | General Comments | | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | LTCMechanism | 503-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | LTCMechanism | 503-1 | LTC Counter Readings | LTC As Found Counter | 3787 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Readings | Operations This Read Vac | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Readings | Switching Operations | 0 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | LTCMechanism | 503-1 | LTC Counter Readings | LTC As Left Counter | 3796 | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BK001168 | BreakerVacuum | 522-0512 | VCB Readings | Unknown Operations | 0 | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | FE000060 | Fence | 504-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | LTCMechanism | 503-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | LTCMechanism | 503-1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | LTCMechanism | 503-1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | FE000060 | Fence | 504-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | FE000060 | Fence | 504-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | FE000060 | Fence | 504-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | FE000060 | Fence | 504-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 2/1/2023 13:39 | Distribution | Fourmile Quarterly Inspection | FE000060 | Fence | 504-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | M0095 | LTCMechanism | 503-1 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | LTCMechanism | 380-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | LTCMechanism | 380-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BCH001308 | Charger | 522-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | LTCC000953 | LTCControl | 503-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | LTCMechanism | 380-1 | LTC Counter Readings | General Comments | | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | LTCMechanism | 380-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 2/1/2023 9:43 | Distribution | Alva Quarterly Inspection | LTCC000953 | LTCControl | 503-1 | LTC Control Insp | All Connections OK? | y | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 2/1/2023 13:43 | Distribution | Rogers Gap Quarterly Inspection | KT0016 | WithLTC | 695-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | ST000106 | Structure | 800-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | ST000106 | Structure | 800-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | ST000106 | Structure | 800-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | ST000106 | Structure | 800-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BCH001294 | Charger | 855-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BCH001294 | Charger | 855-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BCH001294 | Charger | 855-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .6 | amps |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BCH001294 | Charger | 855-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | ST000106 | Structure | 800-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BCH001294 | Charger | 855-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 2/1/2023 11:12 | Distribution | Harrogate Quarterly Inspection | BCH001294 | Charger | 855-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.300 | millivolts |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | ST000106 | Structure | 800-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 2/1/2023 10:21 | Distribution | Puckett Creek Quarterly Inspection | ST000106 | Structure | 800-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | YD000365 | Yard | 402-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | YD000365 | Yard | 402-Yard | Yard Patrol Inspection | Vegetation | None | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | YD000365 | Yard | 402-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | YD000365 | Yard | 402-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | YD000365 | Yard | 402-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BCH001308 | Charger | 522-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.2 | amps |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BCH001308 | Charger | 522-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BCH001308 | Charger | 522-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | LTCMechanism | 380-1 | LTC Counter Readings | LTC As Left Counter | 163718 | |
| 2/2/2023 7:32 | Distribution | Bear Branch Quarterly Inspection | B0468 | LTCMechanism | 380-1 | LTC Counter Readings | LTC As Found Counter | 163715 | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | YD000365 | Yard | 402-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | YD000365 | Yard | 402-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 2/1/2023 14:23 | Distribution | Alexander Quarterly Inspection | YD000365 | Yard | 402-Yard | Yard Patrol Inspection | General Comments | | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 300 | psi |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | KT0032 | WithLTC | 522-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 2/1/2023 9:39 | Distribution | Versailles West Quarterly Inspection | BCH001308 | Charger | 522-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Counter Readings | LTC Operations Since Last Insp | 336 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Amps A Ø | 119.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Accumulated Fault Duty C Ph V | 2.68 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | General Comments | | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Operations Counter AF | 385 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Operations Counter AL | 387 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Operations This Read Vac | 2 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | General Comments | | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | General Comments | | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Operations Counter AF | 193 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Switching Operations | 2 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Operations Counter AF | 299 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Operations Counter AL | 301 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Operations This Read Vac | 2 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Switching Operations | 2 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Accumulated Fault Duty B Ph V | 1.34 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Accumulated Fault Duty A Ph V | 2.68 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | 9 Month Operations | 2 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Switching Operations | 2 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Operations This Read Vac | 2 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Operations Counter AL | 366 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Switching Operations | 2 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Operations Counter AF | 264 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | General Comments | | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | 9 Month Operations | 2 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Accumulated Fault Duty A Ph V | 2.16 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Accumulated Fault Duty B Ph V | 2.16 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Accumulated Fault Duty C Ph V | 3.24 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | General Comments | | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Amps A Ø | 435.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Amps B Ø | 415.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Amps C Ø | 489.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Operations This Read Vac | 2 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Operations Counter AL | 241 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Operations Counter AF | 239 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | 9 Month Operations | 8 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Accumulated Fault Duty A Ph V | .89 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Accumulated Fault Duty B Ph V | 2.68 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Accumulated Fault Duty C Ph V | .89 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Amps A Ø | 166.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Amps B Ø | 204.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Amps C Ø | 167.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Counter Readings | General Comments | Counter was entered wrong on last check : LTC mech was replaced. Counter spot inspection performed. Quarter check reopened an | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Mechanism Patrol Inspection | General Comments | no temp gauge : JB removed temp gauge questions | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Counter Readings | LTC As Found Counter | 50981 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Counter Readings | LTC As Left Counter | 50981 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Counter Readings | LTC Current Tap Position | 1R | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCM000142 | LTCMechanism | 846-2 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Fault Operations A Ø | 1 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | General Comments | | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Operations Counter AF | 406 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Operations Counter AL | 409 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Operations This Read Vac | 3 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Switching Operations | 2 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Operations Counter AL | 193 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Amps B Ø | 147.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Amps C Ø | 130.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Operations This Read Vac | 1 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Switching Operations | 1 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | 9 Month Operations | 4 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Accumulated Fault Duty B Ph V | .45 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Accumulated Fault Duty C Ph V | .45 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Amps A Ø | 234.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Amps B Ø | 230.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Amps C Ø | 260.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | General Comments | | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Operations Counter AF | 258 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Operations Counter AL | 360 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Operations This Read Vac | 2 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Switching Operations | 2 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Amps C Ø | 69.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Accumulated Fault Duty B Ph V | .45 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Accumulated Fault Duty C Ph V | 2.68 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Amps B Ø | 79.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Amps A Ø | 84.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Accumulated Fault Duty C Ph V | 4.91 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Accumulated Fault Duty B Ph V | 2.68 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | Accumulated Fault Duty A Ph V | 4.91 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Readings | 9 Month Operations | 4 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Amps C Ø | 173.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Accumulated Fault Duty A Ph V | 1.79 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | 9 Month Operations VCB New | 8 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | 9 Month Operations | 11 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | 9 Month Operations | 5 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Accumulated Fault Duty A Ph V | .89 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Accumulated Fault Duty B Ph V | .89 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Amps A Ø | 130.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Amps B Ø | 132.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Accumulated Fault Duty C Ph V | .45 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Readings | Amps A Ø | 129.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Amps B Ø | 137.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Amps C Ø | 163.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Fault Adjusted Amps A Phase V | 5.99 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0172 | NonLTC | 582-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0172 | NonLTC | 582-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0172 | NonLTC | 582-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0172 | NonLTC | 582-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0172 | NonLTC | 582-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0172 | NonLTC | 582-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0172 | NonLTC | 582-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0172 | NonLTC | 582-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0172 | NonLTC | 582-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0172 | NonLTC | 582-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0172 | NonLTC | 582-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0172 | NonLTC | 582-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0172 | NonLTC | 582-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0172 | NonLTC | 582-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0172 | NonLTC | 582-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0172 | NonLTC | 582-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 80.00 | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0172 | NonLTC | 582-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0172 | NonLTC | 582-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0172 | NonLTC | 582-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Readings | General Comments | | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1042.56 | kw |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Readings | Totalizer Meter Reading | .3258 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 5.0 | psi |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0304 | NonLTC | Retired Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | FE000893 | Fence | 451-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | FE000893 | Fence | 451-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Readings | Operations Counter AF | 171 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | FE000893 | Fence | 451-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Readings | Operations Counter AL | 171 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Readings | Operations This Read Vac | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | FE000893 | Fence | 451-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | FE000893 | Fence | 451-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Current Tap Position | 11L | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | FE000893 | Fence | 451-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 9250 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | LTCC000720 | LTCControl | 451-1 | LTC Control Insp | LTC Output Voltage Level | 123.5 | VAC |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Switching Operations | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Operations This Read Vac | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Max Tap Position | 8L | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.7 | volts |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | LTCC000720 | LTCControl | 451-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | LTCC000720 | LTCControl | 451-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | LTCC000720 | LTCControl | 451-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | General Comments | | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Readings | Switching Operations | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Current Tap Position | 11L | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | FE000893 | Fence | 451-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | FE000893 | Fence | 451-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | FE000893 | Fence | 451-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | FE000893 | Fence | 451-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | FE000893 | Fence | 451-Fence | Fence Patrol Inspection | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | FE000893 | Fence | 451-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0533 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0533 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Amps A Ø | 120.0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Amps B Ø | 125.0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Amps C Ø | 120.0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0533 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0533 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0414 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0414 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Readings | General Comments | | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | FE000893 | Fence | 451-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Readings | Fault Operations Ground | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | LTCC000121 | LTCControl | 451-2 | LTC Control Insp | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | LTCC000121 | LTCControl | 451-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | LTCC000121 | LTCControl | 451-2 | LTC Control Insp | All Connections OK? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Operations Counter AF | 433 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Operations Counter AL | 433 | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0414 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0414 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0533 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0533 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0533 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0533 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0414 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0414 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Current Tap Position | 12L | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0414 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0414 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0414 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0414 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0414 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0414 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0414 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0414 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0414 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0414 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0414 | LTCMechanism | 920-Offline-Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | 9 Month Operations | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0414 | LTCMechanism | 920-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0414 | LTCMechanism | 920-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0414 | LTCMechanism | 920-Offline-Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0414 | LTCMechanism | 920-Offline-Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 9386 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0533 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0533 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0533 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0533 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0533 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0533 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0533 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0533 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0533 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | FE000893 | Fence | 451-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | FE000893 | Fence | 451-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Min Tap Position | 15L | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Max Tap Position | 6L | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Max Tap Position | 4L | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000051 | Regulator | 582-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | FE000893 | Fence | 451-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0533 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0533 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0533 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0533 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Readings | Amps C Ø | 40.0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Readings | Amps B Ø | 40.0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Readings | Amps A Ø | 40.0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.7 | volts |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0278 | BreakerVacuum | 590-0167 | VCB Readings | 9 Month Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | LTCC000720 | LTCControl | 451-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | LTCC000720 | LTCControl | 451-1 | LTC Control Insp | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | LTCC000720 | LTCControl | 451-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 10755 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000053 | Regulator | 582-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | LTCC000720 | LTCControl | 451-1 | LTC Control Insp | All Connections OK? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0414 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0414 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0414 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | LTCC000121 | LTCControl | 451-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0244 | BreakerVacuum | 582-0162 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | LTCC000121 | LTCControl | 451-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | LTCC000121 | LTCControl | 451-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | RG000052 | Regulator | 582-1 B | Regulator Patrol Inspection | Min Tap Position | 15L | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | LTCC000121 | LTCControl | 451-2 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | LTCC000121 | LTCControl | 451-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | FE000522 | Fence | 920-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Readings | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Readings | Operations Counter AF | 194 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Readings | Operations Counter AL | 197 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Readings | Operations This Read Vac | 3 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Readings | Switching Operations | 3 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | FE000522 | Fence | 920-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Readings | 9 Month Operations | 5 | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | FE000522 | Fence | 920-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | FE000522 | Fence | 920-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | FE000522 | Fence | 920-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 55.00 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Readings | Winding Temp Max | 45 | °C |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Readings | Totalizer Meter Reading | .4230 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Readings | LTC Totalizer Reading | 7614.00 | kw |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Readings | General Comments | | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | LTCMechanism | 664-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | LTCMechanism | 664-1 | LTC Counter Readings | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | LTCMechanism | 664-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | LTCMechanism | 664-1 | LTC Counter Readings | LTC As Found Counter | 216108 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | LTCMechanism | 664-1 | LTC Counter Readings | LTC As Left Counter | 216108 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | LTCMechanism | 664-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | LTCMechanism | 664-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | LTCMechanism | 664-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | LTCMechanism | 664-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | LTCMechanism | 664-1 | LTC Counter Readings | LTC Operations Since Last Insp | 477 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | LTCMechanism | 664-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | LTCMechanism | 664-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | LTCMechanism | 664-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | YD000528 | Yard | 920-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | YD000528 | Yard | 920-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | YD000528 | Yard | 920-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | YD000528 | Yard | 920-Yard | Yard Patrol Inspection | General Comments | | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | YD000528 | Yard | 920-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | YD000528 | Yard | 920-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | YD000528 | Yard | 920-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | YD000528 | Yard | 920-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | YD000528 | Yard | 920-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | YD000528 | Yard | 920-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | YD000528 | Yard | 920-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | FE000522 | Fence | 920-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | FE000522 | Fence | 920-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | FE000522 | Fence | 920-Fence | Fence Patrol Inspection | General Comments | | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | FE000522 | Fence | 920-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | FE000522 | Fence | 920-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | FE000522 | Fence | 920-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0534 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0534 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0534 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0534 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0534 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0534 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0534 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0534 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0534 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0534 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0534 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0534 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0534 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0534 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0534 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0534 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0534 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0534 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0534 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0534 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0534 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Readings | 9 Month Operations | 6 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Readings | Amps A Ø | 0.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Readings | Amps B Ø | 0.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000078 | BreakerVacuum | 664-0138 | VCB Readings | Amps C Ø | 0.0 | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0335 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0335 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0335 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0335 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0335 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0335 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0335 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0335 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0335 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000064 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000064 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000064 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000064 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000064 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000064 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000064 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000064 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000064 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000064 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000064 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000064 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000064 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0335 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0335 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0335 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0335 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0335 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 217.50 | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0335 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0335 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0335 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0335 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0335 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0335 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000064 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Readings | Operations Counter AF | 204 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Readings | Operations Counter AL | 207 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Readings | Operations This Read Vac | 3 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Readings | Switching Operations | 3 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | ST000565 | Structure | 451-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | ST000565 | Structure | 451-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | ST000565 | Structure | 451-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | ST000565 | Structure | 451-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | ST000565 | Structure | 451-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | ST000565 | Structure | 451-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | ST000565 | Structure | 451-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | ST000565 | Structure | 451-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | ST000565 | Structure | 451-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | ST000565 | Structure | 451-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | ST000565 | Structure | 451-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | ST000565 | Structure | 451-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | ST000565 | Structure | 451-Structure | Structure Patrol Inspection | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | ST000565 | Structure | 451-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | ST000565 | Structure | 451-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | ST000565 | Structure | 451-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Readings | Amps A Ø | 105.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Readings | Amps B Ø | 105.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Readings | Amps C Ø | 110.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | WithLTC | 582-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000079 | BreakerVacuum | 664-0139 | VCB Readings | General Comments | | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | FE000522 | Fence | 920-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | FE000522 | Fence | 920-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | FE000522 | Fence | 920-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | FE000522 | Fence | 920-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | FE000522 | Fence | 920-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000065 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000065 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000065 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000065 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000065 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000065 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 15.00 | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000065 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000065 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000065 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000065 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000065 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000065 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000065 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000065 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000065 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000065 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000064 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | TX000064 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | General Comments | | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | General Comments | | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | ST000436 | Structure | 587-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Switching Operations | 0 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Operations This Read Vac | 0 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Operations Counter AL | 332 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Operations Counter AF | 332 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | General Comments | | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Counter Readings | General Comments | | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Counter Readings | LTC As Found Counter | 96009 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Operations Counter AF | 357 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | General Comments | | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Amps C Ø | 55.0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Amps B Ø | 90.0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Amps A Ø | 60.0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Operations Counter AL | 357 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Operations This Read Vac | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Switching Operations | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0246 | BreakerVacuum | 582-0164 | VCB Readings | 9 Month Operations | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCM000096 | LTCMechanism | 664-3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCM000096 | LTCMechanism | 664-3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCM000096 | LTCMechanism | 664-3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCM000096 | LTCMechanism | 664-3 | LTC Counter Readings | LTC Operations Since Last Insp | 38 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCM000096 | LTCMechanism | 664-3 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCM000096 | LTCMechanism | 664-3 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCM000096 | LTCMechanism | 664-3 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCM000096 | LTCMechanism | 664-3 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCM000096 | LTCMechanism | 664-3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCM000096 | LTCMechanism | 664-3 | LTC Counter Readings | LTC As Left Counter | 9779 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCM000096 | LTCMechanism | 664-3 | LTC Counter Readings | LTC As Found Counter | 9779 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCM000096 | LTCMechanism | 664-3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCM000096 | LTCMechanism | 664-3 | LTC Counter Readings | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCM000096 | LTCMechanism | 664-3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCM000096 | LTCMechanism | 664-3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | YD000433 | Yard | 587-Yard | Yard Patrol Inspection | Ambient Temp | 49 | °F |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | General Comments | | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Operations Counter AF | 330 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Operations Counter AL | 330 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Operations This Read Vac | 2 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Switching Operations | 2 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | General Comments | | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | FE000538 | Fence | 582-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Readings | Switching Operations | 2 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Readings | Operations This Read Vac | 2 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Readings | Operations Counter AL | 220 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Readings | Operations Counter AF | 218 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Readings | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000425 | BreakerVacuum | 664-BT1-2 | VCB Readings | 9 Month Operations | 6 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | LTCMechanism | 664-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Counter Readings | LTC As Left Counter | 96009 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Counter Readings | LTC Current Tap Position | 12L | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Counter Readings | LTC Max Tap Position | 7L | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Counter Readings | LTC Min Tap Position | 15L | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Counter Readings | LTC Operations Since Last Insp | 289 | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | LTCMechanism | 449-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | LTCMechanism | 449-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | LTCMechanism | 449-1 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | LTCMechanism | 449-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | LTCMechanism | 449-1 | LTC Counter Readings | LTC Operations Since Last Insp | 347 | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | LTCMechanism | 449-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 40 | °C |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | LTCMechanism | 449-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 20 | °C |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | LTCMechanism | 449-1 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | LTCMechanism | 449-1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | LTCMechanism | 449-1 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | LTCMechanism | 449-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | LTCMechanism | 449-1 | LTC Counter Readings | LTC As Left Counter | 21165 | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | LTCMechanism | 449-1 | LTC Counter Readings | LTC As Found Counter | 21165 | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | LTCMechanism | 449-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | LTCMechanism | 449-1 | LTC Counter Readings | General Comments | | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | LTCMechanism | 449-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | LTCMechanism | 449-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | C0516 | LTCMechanism | 582-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCC000960 | LTCControl | 664-3 | LTC Control Insp | All Connections OK? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCC000960 | LTCControl | 664-3 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCC000960 | LTCControl | 664-3 | LTC Control Insp | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCC000960 | LTCControl | 664-3 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCC000960 | LTCControl | 664-3 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCC000960 | LTCControl | 664-3 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCC000960 | LTCControl | 664-3 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCC000960 | LTCControl | 664-3 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | 9 Month Operations | 2 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Amps A Ø | 160.0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Amps B Ø | 160.0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Amps C Ø | 160.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0238 | BreakerVacuum | 582-2110 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Readings | Amps C Ø | 25.0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Readings | General Comments | | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Readings | Operations Counter AF | 353 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Readings | Operations Counter AL | 353 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Readings | Operations This Read Vac | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Readings | Switching Operations | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Readings | 9 Month Operations | 4 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Readings | Amps A Ø | 180.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Readings | Amps B Ø | 170.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Readings | Amps C Ø | 140.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | LTCMechanism | 451-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | LTCMechanism | 451-2 | LTC Counter Readings | LTC Min Tap Position | 16L | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | LTCMechanism | 451-2 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | LTCMechanism | 451-2 | LTC Counter Readings | LTC Current Tap Position | 10L | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | LTCMechanism | 451-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | LTCMechanism | 451-2 | LTC Counter Readings | LTC As Left Counter | 157729 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | LTCMechanism | 451-2 | LTC Counter Readings | LTC As Found Counter | 157729 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | LTCMechanism | 451-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | LTCMechanism | 451-2 | LTC Counter Readings | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | LTCMechanism | 451-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | LTCMechanism | 451-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BAT001215 | Battery | 664-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Amps C Ø | 30.0 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Amps B Ø | 60.0 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Amps A Ø | 25.0 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Readings | 9 Month Operations | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Readings | Amps A Ø | 20.0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0281 | BreakerVacuum | 590-0166 | VCB Readings | Amps B Ø | 25.0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Readings | Amps C Ø | 30.0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Readings | Amps B Ø | 29.0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Readings | Amps A Ø | 29.0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | LTCMechanism | 451-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | LTCMechanism | 451-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | LTCMechanism | 451-1 | LTC Counter Readings | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | LTCMechanism | 451-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | LTCMechanism | 451-1 | LTC Counter Readings | LTC As Found Counter | 20737 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | LTCMechanism | 451-1 | LTC Counter Readings | LTC As Left Counter | 20737 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | LTCMechanism | 451-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | LTCMechanism | 451-1 | LTC Counter Readings | LTC Current Tap Position | 12L | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | LTCMechanism | 451-1 | LTC Counter Readings | LTC Max Tap Position | 5L | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | LTCMechanism | 451-1 | LTC Counter Readings | LTC Min Tap Position | 16L | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | LTCMechanism | 451-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | LTCMechanism | 451-1 | LTC Counter Readings | LTC Operations Since Last Insp | 476 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | LTCMechanism | 451-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | LTCMechanism | 451-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | LTCMechanism | 451-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Readings | 9 Month Operations | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Switching Operations | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Operations This Read Vac | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Operations Counter AL | 186 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Operations Counter AF | 186 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | General Comments | | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Amps C Ø | 36.0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Amps B Ø | 40.0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Amps A Ø | 35.0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BK001612 | BreakerVacuum | 582-0161 | VCB Readings | 9 Month Operations | 0 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | 9 Month Operations | 1 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Readings | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Readings | Operations Counter AF | 209 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Readings | Operations Counter AL | 211 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Readings | Operations This Read Vac | 2 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Readings | Switching Operations | 2 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK000501 | BreakerVacuum | 664-0015 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Readings | Switching Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Readings | Operations This Read Vac | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Readings | Operations Counter AL | 342 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Readings | Operations Counter AF | 342 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Readings | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0128 | BreakerVacuum | 451-2122 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | KT0001 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | KT0001 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | KT0001 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | KT0001 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | KT0001 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Amps C Ø | 20.0 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Amps B Ø | 25.0 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Amps A Ø | 20.0 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | K0036 | BreakerVacuum | 587-2136 | VCB Readings | 9 Month Operations | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | ST000564 | Structure | 590-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | ST000564 | Structure | 590-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | YD000560 | Yard | 590-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | YD000560 | Yard | 590-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | YD000560 | Yard | 590-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | General Comments | | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | YD000560 | Yard | 590-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | YD000560 | Yard | 590-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | YD000560 | Yard | 590-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | YD000560 | Yard | 590-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | YD000560 | Yard | 590-Yard | Yard Patrol Inspection | General Comments | | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | YD000560 | Yard | 590-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BAT001043 | Battery | 204-Battery Bank Dist | Battery Patrol Inspection | All Connections OK? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Switching Operations | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Readings | Totalizer Meter Reading | .1962 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | YD000560 | Yard | 590-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | YD000560 | Yard | 590-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | ST000565 | Structure | 451-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | ST000565 | Structure | 451-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | ST000565 | Structure | 451-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | ST000565 | Structure | 451-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | ST000565 | Structure | 451-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | ST000565 | Structure | 451-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | YD000561 | Yard | 451-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | YD000561 | Yard | 451-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | YD000561 | Yard | 451-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | YD000561 | Yard | 451-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | YD000561 | Yard | 451-Yard | Yard Patrol Inspection | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | YD000561 | Yard | 451-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | YD000561 | Yard | 451-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | YD000561 | Yard | 451-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | YD000561 | Yard | 451-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | YD000561 | Yard | 451-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | YD000561 | Yard | 451-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | YD000561 | Yard | 451-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | YD000561 | Yard | 451-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | YD000561 | Yard | 451-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | YD000561 | Yard | 451-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | ST000564 | Structure | 590-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | ST000564 | Structure | 590-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | ST000564 | Structure | 590-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | ST000564 | Structure | 590-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | ST000564 | Structure | 590-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | ST000564 | Structure | 590-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | ST000564 | Structure | 590-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | ST000564 | Structure | 590-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | ST000564 | Structure | 590-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | ST000564 | Structure | 590-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | ST000564 | Structure | 590-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | ST000564 | Structure | 590-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | ST000564 | Structure | 590-Structure | Structure Patrol Inspection | General Comments | | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | ST000564 | Structure | 590-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | ST000564 | Structure | 590-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | ST000564 | Structure | 590-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | ST000564 | Structure | 590-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | ST000564 | Structure | 590-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | ST000564 | Structure | 590-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | ST000564 | Structure | 590-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | KT0001 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | KT0001 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | KT0001 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | KT0001 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | KT0001 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | KT0001 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | KT0001 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | KT0001 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | KT0001 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | KT0001 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | KT0001 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gas Accumulation Gauge | Normal | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | KT0001 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | KT0001 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | KT0001 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | KT0001 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | KT0001 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | KT0001 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | KT0001 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | KT0001 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Readings | Amps C Ø | 298.0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Readings | Amps B Ø | 314.0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Readings | Amps A Ø | 291.0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Readings | 9 Month Operations | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Readings | LTC Totalizer Reading | 3531.60 | kw |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Readings | General Comments | | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | General Comments | | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | YD000544 | Yard | 582-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | General Comments | | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | ST000548 | Structure | 582-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | LTCMechanism | 451-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | LTCMechanism | 451-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | LTCMechanism | 451-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | LTCMechanism | 451-2 | LTC Counter Readings | LTC Operations Since Last Insp | 440 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | YD000560 | Yard | 590-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | YD000560 | Yard | 590-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Operations This Read Vac | 0 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Operations Counter AL | 15 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Operations Counter AF | 15 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | YD000560 | Yard | 590-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | YD000560 | Yard | 590-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | YD000560 | Yard | 590-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | YD000560 | Yard | 590-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | YD000560 | Yard | 590-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | FE000553 | Fence | 590-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | FE000553 | Fence | 590-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | FE000553 | Fence | 590-Fence | Fence Patrol Inspection | General Comments | | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | FE000553 | Fence | 590-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | FE000553 | Fence | 590-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | FE000553 | Fence | 590-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | FE000553 | Fence | 590-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | FE000553 | Fence | 590-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | FE000553 | Fence | 590-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | FE000553 | Fence | 590-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | FE000553 | Fence | 590-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | FE000553 | Fence | 590-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | FE000553 | Fence | 590-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | FE000553 | Fence | 590-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | FE000553 | Fence | 590-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | FE000553 | Fence | 590-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | WithLTC | 590-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Readings | Switching Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Readings | Operations Counter AL | 414 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Readings | Operations Counter AF | 414 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Readings | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | CB0233 | BreakerVacuum | 587-2138 | VCB Readings | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | CB0204 | BreakerVacuum | 451-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0535 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0535 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0535 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0535 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0535 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0535 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0535 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0535 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0535 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0535 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0535 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0535 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0535 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Readings | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Readings | Operations Counter AF | 373 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Readings | Operations Counter AL | 375 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Readings | Operations This Read Vac | 2 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Readings | Switching Operations | 2 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0535 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | BX0734 | RecloserElectronic | 449-0581 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | BX0734 | RecloserElectronic | 449-0581 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | BX0734 | RecloserElectronic | 449-0581 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | BX0734 | RecloserElectronic | 449-0581 | Recloser Electronic Patrol Inspection | Operations Counter | 29 | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0535 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0535 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0535 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | BX0734 | RecloserElectronic | 449-0581 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | BX0734 | RecloserElectronic | 449-0581 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | BX0734 | RecloserElectronic | 449-0581 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | BX0734 | RecloserElectronic | 449-0581 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | BX0734 | RecloserElectronic | 449-0581 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | BX0734 | RecloserElectronic | 449-0581 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | BX0734 | RecloserElectronic | 449-0581 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | BX0734 | RecloserElectronic | 449-0581 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Readings | LTC Totalizer Reading | 6240.00 | kw |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Readings | 9 Month Operations | 3 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Readings | Amps A Ø | 170.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Readings | Amps B Ø | 155.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Readings | Amps C Ø | 195.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0126 | BreakerVacuum | 664-0067 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Counter Readings | LTC Operations Since Last Insp | 417 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Counter Readings | LTC As Left Counter | 190761 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Counter Readings | LTC As Found Counter | 190761 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Counter Readings | General Comments | | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | LTCMechanism | 204-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0535 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0535 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0535 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0535 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Readings | LTC Totalizer Reading | 5736.00 | kw |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Readings | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | 9 Month Operations | 0 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Amps A Ø | 20.0 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Amps B Ø | 25.0 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Amps C Ø | 20.0 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Readings | General Comments | | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | BX0734 | RecloserElectronic | 449-0581 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | BX0734 | RecloserElectronic | 449-0581 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | BX0734 | RecloserElectronic | 449-0581 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | BX0734 | RecloserElectronic | 449-0581 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | BX0734 | RecloserElectronic | 449-0581 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | BX0734 | RecloserElectronic | 449-0581 | Recloser Electronic Patrol Inspection | Amps C Ø | 45.0 | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | BX0734 | RecloserElectronic | 449-0581 | Recloser Electronic Patrol Inspection | Amps B Ø | 60.0 | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | BX0734 | RecloserElectronic | 449-0581 | Recloser Electronic Patrol Inspection | Amps A Ø | 55.0 | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | LTCC000162 | LTCControl | 449-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | LTCC000162 | LTCControl | 449-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | LTCC000162 | LTCControl | 449-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | LTCC000162 | LTCControl | 449-1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | LTCC000162 | LTCControl | 449-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | LTCC000162 | LTCControl | 449-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | LTCC000162 | LTCControl | 449-1 | LTC Control Insp | General Comments | | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | LTCC000162 | LTCControl | 449-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | LTCC000162 | LTCControl | 449-1 | LTC Control Insp | All Connections OK? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 49 | °F |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | BAT001631 | Battery | 587-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | YD000340 | Yard | 664-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0326 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0326 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0326 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0326 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0326 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0326 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 340.00 | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0326 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0326 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0326 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0326 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0326 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0326 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0326 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0326 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0326 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0326 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0326 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0326 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0326 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Readings | Totalizer Meter Reading | .5424 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Readings | Winding Temp Max | 45 | °C |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Switching Operations | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Operations Counter AL | 113 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Readings | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Readings | Operations Counter AF | 362 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Readings | Operations Counter AL | 264 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Readings | Operations This Read Vac | 2 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Readings | Switching Operations | 2 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Readings | 9 Month Operations | 5 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Readings | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Readings | LTC Totalizer Reading | 9763.20 | kw |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | B0431 | WithLTC | 451-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0326 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Counter Readings | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BCH001238 | Charger | 451-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BCH001238 | Charger | 451-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BCH001238 | Charger | 451-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BCH001238 | Charger | 451-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BCH001238 | Charger | 451-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 4.7 | amps |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BCH001238 | Charger | 451-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.3 | VDC |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BCH001238 | Charger | 451-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.3 | VDC |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BCH001238 | Charger | 451-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Readings | Winding Temp Max | 45 | °C |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Readings | Totalizer Meter Reading | .3999 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | FE000334 | Fence | 664-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Counter Readings | LTC As Found Counter | 1249 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Counter Readings | LTC As Left Counter | 1249 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Counter Readings | LTC Operations Since Last Insp | 316 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Very Low | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BAT000966 | Battery | 582-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Operations Counter AF | 113 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | General Comments | | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Amps C Ø | 320.0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Amps B Ø | 325.0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Amps A Ø | 320.0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | K0039 | BreakerVacuum | 582-2 | VCB Readings | 9 Month Operations | 0 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Readings | Totalizer Meter Reading | .6500 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | C0450 | WithLTC | 204-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Readings | Totalizer Meter Reading | .9560 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 6000 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | C0423 | WithLTC | 664-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | LTCMechanism | 587-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Readings | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | LTCC000395 | LTCControl | 587-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | LTCC000395 | LTCControl | 587-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | LTCC000395 | LTCControl | 587-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | LTCC000395 | LTCControl | 587-1 | LTC Control Insp | LTC Output Voltage Level | 123.2 | VAC |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | LTCC000395 | LTCControl | 587-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | LTCC000395 | LTCControl | 587-1 | LTC Control Insp | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | LTCC000395 | LTCControl | 587-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | LTCC000395 | LTCControl | 587-1 | LTC Control Insp | All Connections OK? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Amps C Ø | 29.0 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Amps B Ø | 33.0 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Amps A Ø | 32.0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Readings | Switching Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Readings | Operations Counter AL | 153 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Readings | Operations Counter AF | 153 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Readings | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | General Comments | | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | YD000398 | Yard | 449-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | YD000398 | Yard | 449-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | YD000398 | Yard | 449-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Readings | Switching Operations | 2 | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | FE000393 | Fence | 449-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | FE000393 | Fence | 449-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | FE000393 | Fence | 449-Fence | Fence Patrol Inspection | General Comments | | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | FE000393 | Fence | 449-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | FE000393 | Fence | 449-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | FE000393 | Fence | 449-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | FE000393 | Fence | 449-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | FE000393 | Fence | 449-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | FE000393 | Fence | 449-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | FE000393 | Fence | 449-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | FE000393 | Fence | 449-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | FE000393 | Fence | 449-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | FE000393 | Fence | 449-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | FE000393 | Fence | 449-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | FE000393 | Fence | 449-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | FE000393 | Fence | 449-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Operations Counter | 12 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Readings | LTC Totalizer Reading | 7198.20 | kw |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Readings | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Readings | Operations Counter AF | 166 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Readings | Operations Counter AL | 166 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Readings | Switching Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Readings | Amps C Ø | 306.0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Amps A Ø | 15.0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Amps B Ø | 20.0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Amps C Ø | 15.0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Readings | 9 Month Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Readings | Amps C Ø | 372.0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Readings | Amps B Ø | 411.0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Readings | Amps A Ø | 416.0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001591 | BreakerVacuum | 451-1 | VCB Readings | 9 Month Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Switching Operations | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Operations This Read Vac | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Operations Counter AL | 419 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Operations Counter AF | 419 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | General Comments | | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Readings | 9 Month Operations | 2 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Readings | Amps A Ø | 300.0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Readings | Amps B Ø | 327.0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Readings | Amps A Ø | 0.0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Readings | Amps B Ø | 0.0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001590 | BreakerVacuum | 451-BT2-1 | VCB Readings | Amps C Ø | 0.0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Readings | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Readings | LTC Totalizer Reading | 5562.00 | kw |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Readings | Oil Temp Present | 50 | °C |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 6000 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Readings | Totalizer Meter Reading | .9270 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | ST000401 | Structure | 449-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | ST000401 | Structure | 449-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | ST000401 | Structure | 449-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | ST000401 | Structure | 449-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | ST000401 | Structure | 449-Structure | Structure Patrol Inspection | General Comments | | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | BCH001579 | Charger | 587-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | BCH001579 | Charger | 587-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Readings | General Comments | | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Readings | 9 Month Operations | 6 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Readings | Amps A Ø | 275.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Readings | Amps B Ø | 280.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Readings | Amps C Ø | 220.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | BCH001579 | Charger | 587-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | BCH001579 | Charger | 587-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | BCH001579 | Charger | 587-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | BCH001579 | Charger | 587-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | BCH001579 | Charger | 587-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | BCH001579 | Charger | 587-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | ST000401 | Structure | 449-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | ST000401 | Structure | 449-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | ST000401 | Structure | 449-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | ST000401 | Structure | 449-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | ST000401 | Structure | 449-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | ST000401 | Structure | 449-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | ST000401 | Structure | 449-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | ST000401 | Structure | 449-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | ST000401 | Structure | 449-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | WithLTC | 664-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | YD000398 | Yard | 449-Yard | Yard Patrol Inspection | General Comments | | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | YD000398 | Yard | 449-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | YD000398 | Yard | 449-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | YD000398 | Yard | 449-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | YD000398 | Yard | 449-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | YD000398 | Yard | 449-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Counter Readings | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | YD000398 | Yard | 449-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | YD000398 | Yard | 449-Yard | Yard Patrol Inspection | Clear of Trash? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Operations This Read Vac | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | C0497 | WithLTC | 451-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Readings | Switching Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Readings | Operations This Read Vac | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Readings | Operations Counter AL | 251 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Readings | Operations Counter AF | 251 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Readings | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | 9 Month Operations | 2 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | CB0245 | BreakerVacuum | 582-0163 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0008 | BreakerVacuum | 451-2120 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | KX0065 | RecloserElectronic | 587-2137 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Operations Counter AL | 749 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Operations Counter AF | 749 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Readings | Operations Counter AF | 342 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Readings | Operations Counter AL | 344 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Readings | Operations This Read Vac | 2 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0040 | BreakerVacuum | 664-0030 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | ST000401 | Structure | 449-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | ST000401 | Structure | 449-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | ST000343 | Structure | 664-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | ST000401 | Structure | 449-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | ST000401 | Structure | 449-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | ST000401 | Structure | 449-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | ST000401 | Structure | 449-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | ST000401 | Structure | 449-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Counter Readings | LTC Operations Since Last Insp | 327 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Counter Readings | LTC As Left Counter | 10028 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Counter Readings | LTC As Found Counter | 10028 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0297 | LTCMechanism | 664-2 | LTC Mechanism Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | ST000401 | Structure | 449-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | ST000401 | Structure | 449-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | YD000398 | Yard | 449-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | YD000398 | Yard | 449-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | YD000398 | Yard | 449-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | YD000398 | Yard | 449-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | YD000398 | Yard | 449-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0224 | BreakerVacuum | 204-2124 | VCB Readings | Switching Operations | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Readings | Switching Operations | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Operations Counter AL | 235 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Operations This Read Vac | 0 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Switching Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Readings | Switching Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | X0025 | RecloserElectronic | 449-0580 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | X0025 | RecloserElectronic | 449-0580 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | X0025 | RecloserElectronic | 449-0580 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | X0025 | RecloserElectronic | 449-0580 | Recloser Electronic Patrol Inspection | Operations Counter | 38 | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | X0025 | RecloserElectronic | 449-0580 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | X0025 | RecloserElectronic | 449-0580 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | X0025 | RecloserElectronic | 449-0580 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | X0025 | RecloserElectronic | 449-0580 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | X0025 | RecloserElectronic | 449-0580 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | X0025 | RecloserElectronic | 449-0580 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | X0025 | RecloserElectronic | 449-0580 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | X0025 | RecloserElectronic | 449-0580 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | X0025 | RecloserElectronic | 449-0580 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | X0025 | RecloserElectronic | 449-0580 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | X0025 | RecloserElectronic | 449-0580 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | X0025 | RecloserElectronic | 449-0580 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | n | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | X0025 | RecloserElectronic | 449-0580 | Recloser Electronic Patrol Inspection | Amps C Ø | 140.0 | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | X0025 | RecloserElectronic | 449-0580 | Recloser Electronic Patrol Inspection | Amps B Ø | 145.0 | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | X0025 | RecloserElectronic | 449-0580 | Recloser Electronic Patrol Inspection | Amps A Ø | 155.0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Readings | 9 Month Operations | 0 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | 9 Month Operations | 9 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Amps A Ø | 91.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Readings | Operations This Read Vac | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Readings | Operations Counter AL | 213 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Readings | Operations Counter AF | 213 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Readings | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Readings | 9 Month Operations | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Readings | Amps A Ø | 100.0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Readings | Amps B Ø | 100.0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Readings | Amps C Ø | 110.0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Readings | General Comments | | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | General Comments | | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Operations Counter AF | 235 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Readings | Operations Counter AF | 44 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Readings | Operations Counter AL | 44 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0275 | BreakerVacuum | 590-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Readings | Operations This Read Vac | 0 | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | LTCMechanism | 920-Offline-Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | LTCMechanism | 920-Offline-Distribution | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | LTCMechanism | 920-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | LTCMechanism | 920-Offline-Distribution | LTC Counter Readings | LTC Operations Since Last Insp | 0 | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | LTCMechanism | 920-Offline-Distribution | LTC Counter Readings | LTC Min Tap Position | Neutral | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | LTCMechanism | 920-Offline-Distribution | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | LTCMechanism | 920-Offline-Distribution | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | LTCMechanism | 920-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | LTCMechanism | 920-Offline-Distribution | LTC Counter Readings | LTC As Left Counter | 4829 | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | LTCMechanism | 920-Offline-Distribution | LTC Counter Readings | LTC As Found Counter | 4829 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Readings | Operations Counter AL | 180 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Readings | Operations Counter AF | 180 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.1184 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Readings | General Comments | | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Readings | LTC Totalizer Reading | 6157.44 | kw |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Readings | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Readings | Amps C Ø | 0.0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Readings | Amps B Ø | 0.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Readings | Totalizer Meter Reading | .6414 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0381 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0381 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0381 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0381 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0381 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0381 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0381 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0381 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Readings | Switching Operations | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0381 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Readings | Amps A Ø | 0.0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | K0007 | BreakerVacuum | 451-2121 | VCB Readings | 9 Month Operations | 0 | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0381 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0381 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0381 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0381 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0381 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0381 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0381 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0381 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0381 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0381 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Readings | General Comments | | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Readings | LTC Totalizer Reading | 0.00 | kw |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Readings | 9 Month Operations | 0 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BCH001472 | Charger | 204-Battery Charger Dist | Battery Charger Patrol Insp | General Comments | | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BCH001472 | Charger | 204-Battery Charger Dist | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BCH001472 | Charger | 204-Battery Charger Dist | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BCH001472 | Charger | 204-Battery Charger Dist | Battery Charger Patrol Insp | Battery Charger Current | .6 | amps |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BCH001472 | Charger | 204-Battery Charger Dist | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BCH001472 | Charger | 204-Battery Charger Dist | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BAT001542 | Battery | 451-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BAT001542 | Battery | 451-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BAT001542 | Battery | 451-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BAT001542 | Battery | 451-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BAT001542 | Battery | 451-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BAT001542 | Battery | 451-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BAT001542 | Battery | 451-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BAT001542 | Battery | 451-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BAT001542 | Battery | 451-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BAT001542 | Battery | 451-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Readings | Oil Temp Max | 85 | °C |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BAT001542 | Battery | 451-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BAT001542 | Battery | 451-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Readings | Oil Temp Present | 10 | °C |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0174 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0174 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0174 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0174 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Readings | Amps A Ø | 11.0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Readings | Amps B Ø | 13.0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Readings | Amps C Ø | 12.0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Readings | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Readings | Operations Counter AF | 172 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Readings | Operations Counter AL | 172 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Readings | Operations This Read Vac | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Readings | Switching Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001589 | BreakerVacuum | 451-2119 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | General Comments | | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | FE000429 | Fence | 587-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Readings | Amps C Ø | 282.0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Readings | Amps B Ø | 320.0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Readings | Amps A Ø | 336.0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCC000320 | LTCControl | 664-1 | LTC Control Insp | All Connections OK? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCC000320 | LTCControl | 664-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCC000320 | LTCControl | 664-1 | LTC Control Insp | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCC000320 | LTCControl | 664-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCC000320 | LTCControl | 664-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCC000320 | LTCControl | 664-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCC000320 | LTCControl | 664-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCC000320 | LTCControl | 664-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCC000320 | LTCControl | 664-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | 9 Month Operations | 2 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Amps A Ø | 20.0 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Amps B Ø | 40.0 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Amps C Ø | 40.0 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BCH001156 | Charger | 664-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BCH001156 | Charger | 664-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BCH001156 | Charger | 664-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BCH001156 | Charger | 664-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BCH001156 | Charger | 664-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 3.8 | amps |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BCH001156 | Charger | 664-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.0 | VDC |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BCH001156 | Charger | 664-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.0 | VDC |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BCH001156 | Charger | 664-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | CB0258 | BreakerVacuum | 204-2125 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0174 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0174 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0174 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0174 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0174 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0174 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0174 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0174 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0174 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0174 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 70.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0174 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0174 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0174 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0174 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0174 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0174 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0174 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0174 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCC000717 | LTCControl | 664-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCC000717 | LTCControl | 664-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCC000717 | LTCControl | 664-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCC000717 | LTCControl | 664-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCC000717 | LTCControl | 664-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCC000717 | LTCControl | 664-2 | LTC Control Insp | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCC000717 | LTCControl | 664-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | LTCC000717 | LTCControl | 664-2 | LTC Control Insp | All Connections OK? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Readings | Totalizer Meter Multiplier | 0 | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Readings | WithLTC Trn Dynamic Health | 20.00 | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | WithLTC | 920-Offline-Distribution | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BAT001542 | Battery | 451-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Readings | Switching Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Readings | Operations This Read Vac | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Readings | Operations Counter AL | 157 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Readings | Operations Counter AF | 157 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Readings | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001588 | BreakerVacuum | 451-2118 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Readings | General Comments | | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Readings | Operations Counter AF | 172 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Readings | Operations Counter AL | 172 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Readings | Operations This Read Vac | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Readings | Switching Operations | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | BCH001179 | Charger | 590-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | BCH001179 | Charger | 590-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | BCH001179 | Charger | 590-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Readings | Operations Counter AF | 215 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0370 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0370 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0370 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0370 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0370 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0370 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0370 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0370 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Readings | Operations This Read Vac | 2 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Readings | Operations Counter AL | 217 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Readings | Operations Counter AF | 168 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0370 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0370 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0370 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0370 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0370 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0370 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Readings | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | General Comments | | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Operations Counter AF | 196 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Operations Counter AL | 196 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Operations This Read Vac | 0 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Switching Operations | 0 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Readings | 9 Month Operations | 2 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Readings | Amps A Ø | 20.0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Readings | Amps B Ø | 20.0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0280 | BreakerVacuum | 590-0169 | VCB Readings | Amps C Ø | 20.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Readings | Amps A Ø | 275.0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BCH000609 | Charger | 582-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BCH000609 | Charger | 582-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.3 | VDC |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BCH000609 | Charger | 582-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.3 | VDC |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BCH000609 | Charger | 582-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.0 | amps |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BCH000609 | Charger | 582-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | BCH000609 | Charger | 582-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Readings | Switching Operations | 3 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Readings | Operations This Read Vac | 3 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Readings | Operations Counter AL | 210 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Readings | Operations Counter AF | 208 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Readings | Maintenance Operations | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Readings | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Readings | Amps C Ø | 75.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Readings | Amps B Ø | 75.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Readings | Amps A Ø | 70.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001047 | BreakerVacuum | 664-0863 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Readings | Amps B Ø | 275.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Readings | Amps C Ø | 225.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Readings | Amps C Ø | 86.0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Readings | Amps B Ø | 86.0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Readings | Amps A Ø | 76.0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Readings | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Patrol Inspection | General Comments | | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | BCH001179 | Charger | 590-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.0 | amps |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Readings | Amps C Ø | 190.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Readings | Amps B Ø | 190.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Readings | Amps A Ø | 190.0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Readings | 9 Month Operations | 4 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | BCH001179 | Charger | 590-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | BCH001179 | Charger | 590-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | BCH001179 | Charger | 590-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | BCH001179 | Charger | 590-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Readings | 9 Month Operations VCB New | 2 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Readings | 9 Month Operations | 2 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Readings | 9 Month Operations | 6 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | K0125 | BreakerVacuum | 664-0014 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Readings | Winding Temp Present | 25 | °C |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Readings | Winding Temp Max | 60 | °C |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.3840 | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Readings | LTC Totalizer Reading | 13286.40 | kw |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Readings | General Comments | | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | LTCMechanism | 590-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | LTCMechanism | 590-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Readings | Amps C Ø | 25.0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Readings | Amps B Ø | 20.0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Readings | Amps A Ø | 25.0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | CB0277 | BreakerVacuum | 590-0168 | VCB Readings | 9 Month Operations | 0 | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | LTCMechanism | 920-Offline-Distribution | LTC Mechanism Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | LTCMechanism | 920-Offline-Distribution | LTC Counter Readings | General Comments | | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | LTCMechanism | 920-Offline-Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | B0277 | LTCMechanism | 920-Offline-Distribution | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Readings | Oil Temp Max | 70 | °C |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Readings | LTC Totalizer Reading | 5368.32 | kw |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Readings | General Comments | | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 11:25 | Distribution | Kentucky State Hospital Quarterly Inspection | B0385 | WithLTC | 587-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | LTCC000977 | LTCControl | 204-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | LTCC000977 | LTCControl | 204-5 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | LTCC000977 | LTCControl | 204-5 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | LTCC000977 | LTCControl | 204-5 | LTC Control Insp | LTC Output Voltage Level | 123.5 | VAC |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | LTCC000977 | LTCControl | 204-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | LTCC000977 | LTCControl | 204-5 | LTC Control Insp | General Comments | | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | LTCC000977 | LTCControl | 204-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | LTCC000977 | LTCControl | 204-5 | LTC Control Insp | All Connections OK? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Amps B Ø | 103.0 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Amps C Ø | 64.0 | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | LTCC000972 | LTCControl | 582-2 | LTC Control Insp | All Connections OK? | y | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Fault Operations Ground | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | BAT001231 | Battery | 590-DC System | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | BAT001231 | Battery | 590-DC System | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | BAT001231 | Battery | 590-DC System | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | BAT001231 | Battery | 590-DC System | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | BAT001231 | Battery | 590-DC System | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | BAT001231 | Battery | 590-DC System | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | BAT001231 | Battery | 590-DC System | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | BAT001231 | Battery | 590-DC System | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | BAT001231 | Battery | 590-DC System | Battery Patrol Inspection | General Comments | | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | LTCMechanism | 590-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | LTCMechanism | 590-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | BAT001231 | Battery | 590-DC System | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Follow-up Action Required? | n | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | BAT001231 | Battery | 590-DC System | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | BAT001231 | Battery | 590-DC System | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | BAT001231 | Battery | 590-DC System | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | LTCMechanism | 590-1 | LTC Counter Readings | LTC Operations Since Last Insp | 409 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | LTCMechanism | 590-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | LTCMechanism | 590-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | LTCMechanism | 590-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | LTCMechanism | 590-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0370 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0370 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0370 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | B0418 | WithLTC | 664-3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Readings | Unknown Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Readings | Switching Operations | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Readings | Operations This Read Vac | 0 | |
| 1/30/2023 13:13 | Distribution | Danville Industrial Quarterly Inspection | BK001587 | BreakerVacuum | 451-2117 | VCB Readings | Operations Counter AL | 168 | |
| 1/30/2023 13:50 | Distribution | Race Street Quarterly Inspection | BK001048 | BreakerVacuum | 664-0031 | VCB Readings | Switching Operations | 2 | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0370 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/30/2023 14:54 | Distribution | Danville Substation Department Quarterly Transformer Pad Inspection | C0370 | NonLTC | 920-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/30/2023 14:45 | Distribution | Danville North Quarterly Inspection | BK000253 | BreakerVacuum | 204-2123 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | LTCC000973 | LTCControl | 590-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | LTCC000973 | LTCControl | 590-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | LTCC000973 | LTCControl | 590-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | LTCC000973 | LTCControl | 590-1 | LTC Control Insp | LTC Output Voltage Level | 123.5 | VAC |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | LTCC000973 | LTCControl | 590-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | LTCC000973 | LTCControl | 590-1 | LTC Control Insp | General Comments | | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | LTCC000973 | LTCControl | 590-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | LTCC000973 | LTCControl | 590-1 | LTC Control Insp | All Connections OK? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | LTCC000972 | LTCControl | 582-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | LTCC000972 | LTCControl | 582-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | LTCC000972 | LTCControl | 582-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | LTCC000972 | LTCControl | 582-2 | LTC Control Insp | LTC Output Voltage Level | 123.5 | VAC |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | LTCC000972 | LTCControl | 582-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | LTCC000972 | LTCControl | 582-2 | LTC Control Insp | General Comments | | |
| 1/30/2023 12:26 | Distribution | Danville Central Quarterly Inspection | LTCC000972 | LTCControl | 582-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | BAT001231 | Battery | 590-DC System | Battery Patrol Inspection | All Connections OK? | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | LTCMechanism | 590-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | LTCMechanism | 590-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | LTCMechanism | 590-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/30/2023 13:19 | Distribution | Shun Pike Quarterly Inspection | S0070 | WithLTC | 449-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | LTCMechanism | 590-1 | LTC Counter Readings | General Comments | | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | LTCMechanism | 590-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | LTCMechanism | 590-1 | LTC Counter Readings | LTC As Found Counter | 107493 | |
| 1/30/2023 13:54 | Distribution | Danville West Quarterly Inspection | C0527 | LTCMechanism | 590-1 | LTC Counter Readings | LTC As Left Counter | 107493 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations Ground | 0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations C Ø | 0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations B Ø | 0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations A Ø | 0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Readings | Follow-up Action Required? | n | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Readings | General Comments | | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Readings | Maintenance Operations | 0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AF | 156 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AL | 156 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Readings | Operations This Read Vac | 0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Readings | Switching Operations | 0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Readings | Unknown Operations | 0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Readings | Amps C Ø | 40.0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Readings | Amps B Ø | 40.0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Readings | Amps A Ø | 40.0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations | 4 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | General Comments | | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0241 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Readings | Unknown Operations | 0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Readings | Amps A Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Readings | Amps B Ø | 0.0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Readings | Amps C Ø | 0.0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations A Ø | 0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations B Ø | 0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations C Ø | 0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations Ground | 0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Readings | Follow-up Action Required? | n | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Readings | General Comments | | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Readings | Maintenance Operations | 0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AF | 518 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AL | 518 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Readings | Operations This Read Vac | 0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Readings | Switching Operations | 0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations | 5 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations VCB New | 5 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | General Comments | | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0236 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations B Ø | 0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations C Ø | 0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations Ground | 0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations | 6 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Readings | Follow-up Action Required? | n | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Readings | General Comments | | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Readings | Maintenance Operations | 0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AF | 17 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations A Ø | 0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AL | 17 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Readings | Operations This Read Vac | 2 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Readings | Amps C Ø | 120.0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Readings | Amps B Ø | 80.0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Readings | Amps A Ø | 60.0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Readings | Switching Operations | 2 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Readings | Unknown Operations | 0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | General Comments | | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BB0237 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BAT001408 | Battery | 930-Offline-Distribution | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BAT001408 | Battery | 930-Offline-Distribution | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BAT001408 | Battery | 930-Offline-Distribution | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BAT001408 | Battery | 930-Offline-Distribution | Battery Patrol Inspection | General Comments | | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BAT001408 | Battery | 930-Offline-Distribution | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BAT001408 | Battery | 930-Offline-Distribution | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BAT001408 | Battery | 930-Offline-Distribution | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BAT001408 | Battery | 930-Offline-Distribution | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BAT001408 | Battery | 930-Offline-Distribution | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BAT001408 | Battery | 930-Offline-Distribution | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BAT001408 | Battery | 930-Offline-Distribution | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BAT001408 | Battery | 930-Offline-Distribution | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BAT001408 | Battery | 930-Offline-Distribution | Battery Patrol Inspection | Battery Area Ambient Temp | 30 | °F |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BAT001408 | Battery | 930-Offline-Distribution | Battery Patrol Inspection | All Connections OK? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BCH001326 | Charger | 930-Offline-Distribution | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BCH001326 | Charger | 930-Offline-Distribution | Battery Charger Patrol Insp | General Comments | | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BCH001326 | Charger | 930-Offline-Distribution | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BCH001326 | Charger | 930-Offline-Distribution | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BCH001326 | Charger | 930-Offline-Distribution | Battery Charger Patrol Insp | Battery Charger Current | 1.4 | amps |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BCH001326 | Charger | 930-Offline-Distribution | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BCH001326 | Charger | 930-Offline-Distribution | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | BCH001326 | Charger | 930-Offline-Distribution | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | UG Pothead Condition Good? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | MOD Motor Jaw Coupling | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | General Comments | | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | MOD Cabinet Heater functional? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | ST000412 | Structure | Retired Distribution | Structure Patrol Inspection | MOD Cabinet Internals Clean? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000294 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000294 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1 | psi |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000294 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gas Accumulation Gauge | Normal | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000294 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000294 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000294 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000294 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000294 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000294 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000294 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000294 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000294 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000294 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Amps C Ø | 215.0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Amps B Ø | 166.0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Amps A Ø | 152.0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | 9 Month Operations | 2 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | CH000350 | ControlHouse | 825-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Readings | General Comments | | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 9504.00 | kw |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Amps C Ø | 0.0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Amps B Ø | 0.0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Amps A Ø | 0.0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | 9 Month Operations | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Clear of Trash? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Ambient Temp | 25 | °F |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .9900 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Readings | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | YD000545 | Yard | 825-Yard | Yard Patrol Inspection | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Unknown Operations | 0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Switching Operations | 0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Operations This Read Vac | 0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Operations Counter AL | 156 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Operations Counter AF | 156 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Maintenance Operations | 0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Patrol Inspection | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Fault Operations Ground | 0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001769 | BreakerVacuum | 746-0171 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Readings | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0049 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0049 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0049 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .4 | psi |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0049 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0049 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0049 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | S0040 | NonLTC | 580-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | General Comments | | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BAT001488 | Battery | 446-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BAT001488 | Battery | 446-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 42 | °F |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BAT001488 | Battery | 446-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BAT001488 | Battery | 446-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BAT001488 | Battery | 446-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BAT001488 | Battery | 446-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BAT001488 | Battery | 446-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BAT001488 | Battery | 446-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BAT001488 | Battery | 446-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BAT001488 | Battery | 446-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BAT001488 | Battery | 446-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BAT001488 | Battery | 446-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BAT001488 | Battery | 446-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | YD000519 | Yard | 446-Yard | Yard Patrol Inspection | Ambient Temp | 42 | °F |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BCH001385 | Charger | 446-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BCH001385 | Charger | 446-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BCH001385 | Charger | 446-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BCH001385 | Charger | 446-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BCH001385 | Charger | 446-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.4 | amps |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BCH001385 | Charger | 446-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BCH001385 | Charger | 446-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | Ambient Temp | 32 | °F |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | Clear of Trash? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0413 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0413 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | General Comments | ADDED 1 LB | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0413 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0413 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | General Comments | | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | YD000512 | Yard | 580-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | General Comments | | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | FE000507 | Fence | 580-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | General Comments | | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | FE000515 | Fence | 446-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BCH001357 | Charger | 580-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BCH001357 | Charger | 580-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BCH001357 | Charger | 580-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BCH001357 | Charger | 580-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BCH001357 | Charger | 580-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.5 | amps |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BCH001357 | Charger | 580-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BCH001357 | Charger | 580-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BCH001357 | Charger | 580-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | General Comments | | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | ST000524 | Structure | 446-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000292 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gas Accumulation Gauge | Normal | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000292 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000292 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1 | psi |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000292 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000292 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000292 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Unknown Operations | 0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Switching Operations | 1 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Operations This Read Vac | 1 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Operations Counter AL | 190 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Operations Counter AF | 189 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Maintenance Operations | 0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Patrol Inspection | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Fault Operations Ground | 0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000292 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000292 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000293 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000293 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000293 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000293 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000293 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000293 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gas Accumulation Gauge | Normal | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000293 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000293 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1 | psi |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000293 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000293 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000293 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000293 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000293 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | ADDED 1 LB | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 15.00 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BK001770 | BreakerVacuum | 746-0172 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BCH001385 | Charger | 446-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | LTCC000907 | LTCControl | 446-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | General Comments | | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | LTCMechanism | 739-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | LTCMechanism | 739-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | ST000517 | Structure | 580-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | LTCC000907 | LTCControl | 446-1 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | LTCC000907 | LTCControl | 446-1 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0507 | NonLTC | 746-3 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | LTCMechanism | 739-2 | LTC Counter Readings | General Comments | | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | LTCC000907 | LTCControl | 446-1 | LTC Control Insp | LTC Output Voltage Level | 126.0 | VAC |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | LTCC000907 | LTCControl | 446-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | LTCC000907 | LTCControl | 446-1 | LTC Control Insp | General Comments | | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | LTCC000907 | LTCControl | 446-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | LTCMechanism | 739-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | LTCMechanism | 739-2 | LTC Counter Readings | LTC As Found Counter | 103919 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | LTCMechanism | 739-2 | LTC Counter Readings | LTC As Left Counter | 103919 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | LTCMechanism | 739-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | LTCMechanism | 739-2 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | LTCMechanism | 739-2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | LTCMechanism | 739-2 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | LTCMechanism | 739-2 | LTC Counter Readings | LTC Operations Since Last Insp | 507 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | LTCC000907 | LTCControl | 446-1 | LTC Control Insp | All Connections OK? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000292 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000292 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000292 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000292 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | LTCMechanism | 739-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | LTCMechanism | 739-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000292 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | ST000549 | Structure | 825-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3852.00 | kw |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Readings | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 25 | °F |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BAT001541 | Battery | 746-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000081 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BCH001470 | Charger | 746-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BCH001470 | Charger | 746-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BCH001470 | Charger | 746-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BCH001470 | Charger | 746-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.0 | amps |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BCH001470 | Charger | 746-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000081 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000081 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | BCH001470 | Charger | 746-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Readings | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | YD000535 | Yard | 746-Yard | Yard Patrol Inspection | Ambient Temp | 25 | °F |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | FE000530 | Fence | 746-Fence | Fence Patrol Inspection | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | FE000405 | Fence | 739-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | FE000405 | Fence | 739-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | FE000405 | Fence | 739-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | FE000405 | Fence | 739-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | FE000405 | Fence | 739-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | FE000405 | Fence | 739-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | YD000410 | Yard | 739-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | YD000410 | Yard | 739-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | YD000410 | Yard | 739-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | YD000410 | Yard | 739-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | YD000410 | Yard | 739-Yard | Yard Patrol Inspection | General Comments | | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | YD000410 | Yard | 739-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | YD000410 | Yard | 739-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | YD000410 | Yard | 739-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | YD000410 | Yard | 739-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | FE000405 | Fence | 739-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | FE000405 | Fence | 739-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000212 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000212 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000212 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000212 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000212 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | leaking from top of transformer | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000212 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000212 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000212 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000212 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000212 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000212 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000212 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000212 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000212 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | YD000410 | Yard | 739-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | YD000410 | Yard | 739-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | YD000410 | Yard | 739-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | YD000410 | Yard | 739-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Counter Readings | LTC Operations Since Last Insp | 1600 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Counter Readings | LTC As Left Counter | 110385 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Counter Readings | LTC As Found Counter | 110380 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | YD000410 | Yard | 739-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | YD000410 | Yard | 739-Yard | Yard Patrol Inspection | Ambient Temp | 30 | °F |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | FE000405 | Fence | 739-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | FE000405 | Fence | 739-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | FE000405 | Fence | 739-Fence | Fence Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Counter Readings | General Comments | | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | LTCMechanism | 884-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Readings | General Comments | | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Readings | LTC Totalizer Reading | 5664.00 | kw |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 6000 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Readings | Totalizer Meter Reading | .9440 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | WithLTC | 446-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | LTCC000069 | LTCControl | 825-2 | LTC Control Insp | All Connections OK? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | LTCC000069 | LTCControl | 825-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | LTCC000069 | LTCControl | 825-2 | LTC Control Insp | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | LTCC000069 | LTCControl | 825-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | LTCC000069 | LTCControl | 825-2 | LTC Control Insp | LTC Output Voltage Level | 121.1 | VAC |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | LTCC000069 | LTCControl | 825-2 | LTC Control Insp | VRR Base Voltage AF | 121.0 | VAC |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | LTCC000069 | LTCControl | 825-2 | LTC Control Insp | VRR Base Voltage AL | 121.0 | VAC |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | LTCC000069 | LTCControl | 825-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | FE000405 | Fence | 739-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | FE000405 | Fence | 739-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | FE000405 | Fence | 739-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | FE000405 | Fence | 739-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | FE000405 | Fence | 739-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000212 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000212 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000212 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | 9 Month Operations | 1 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0038 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0038 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0038 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0038 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0038 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0038 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | B0270 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | B0270 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | B0270 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | B0270 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0038 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0038 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0038 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0282 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0282 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0282 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0282 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 25.00 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0282 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0282 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0282 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0282 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Readings | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000061 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000061 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000061 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000061 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000061 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000061 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000061 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000061 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000061 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000061 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | ADDED 1 LB | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000061 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000061 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000061 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0368 | NonLTC | 746-2 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | BCH000587 | Charger | 825-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | BCH000587 | Charger | 825-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 132.0 | VDC |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | BCH000587 | Charger | 825-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 132.0 | VDC |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | BCH000587 | Charger | 825-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.0 | amps |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | BCH000587 | Charger | 825-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | BCH000587 | Charger | 825-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | BCH000587 | Charger | 825-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Unknown Operations | 0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Switching Operations | 0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Operations This Read Vac | 0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Operations Counter AL | 240 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Operations Counter AF | 240 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Maintenance Operations | 0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Fault Operations Ground | 0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Amps C Ø | 250.0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Amps B Ø | 260.0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Amps A Ø | 360.0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | K0090 | BreakerVacuum | 746-0170 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Readings | Totalizer Meter Reading | .6420 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000063 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000063 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000063 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0200 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0200 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0200 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0200 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0200 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0200 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | Glass for the oil temp is cracked | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0200 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0200 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 95.00 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0200 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0200 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0200 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0200 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0200 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0200 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | LTCC000589 | LTCControl | 825-3 | LTC Control Insp | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | LTCC000589 | LTCControl | 825-3 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | LTCC000589 | LTCControl | 825-3 | LTC Control Insp | LTC Output Voltage Level | 121.6 | VAC |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | LTCC000589 | LTCControl | 825-3 | LTC Control Insp | VRR Base Voltage AF | 121.0 | VAC |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | LTCC000589 | LTCControl | 825-3 | LTC Control Insp | VRR Base Voltage AL | 121.0 | VAC |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | LTCC000589 | LTCControl | 825-3 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 6000 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000081 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000081 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000081 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000081 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000081 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000081 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000081 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000081 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000081 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000081 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000081 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0509 | NonLTC | 746-3 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0371 | NonLTC | 746-2 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | ST000539 | Structure | 746-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000061 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000061 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000061 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000061 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000061 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000061 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000062 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000062 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000062 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000062 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000062 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000062 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000062 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000062 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000062 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000062 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000062 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000062 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000062 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 15.00 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000062 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000062 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000062 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000062 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000062 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000062 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000081 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000081 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000081 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000081 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000081 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000081 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000081 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000081 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0369 | NonLTC | 746-2 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | LTCC000589 | LTCControl | 825-3 | LTC Control Insp | All Connections OK? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | LTCC000589 | LTCControl | 825-3 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000063 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000063 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000063 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000063 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000063 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000063 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000063 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000063 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000063 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000063 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | ADDED 1 LB | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000063 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000063 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000063 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 105.00 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000063 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000063 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000063 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Readings | LTC Totalizer Reading | 2940.00 | kw |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Readings | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Maintenance Operations | 0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Operations Counter AF | 198 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Operations Counter AL | 198 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Operations This Read Vac | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Switching Operations | 0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 42 | °F |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | LTCC000706 | LTCControl | 739-2 | LTC Control Insp | All Connections OK? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | LTCC000706 | LTCControl | 739-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | LTCC000706 | LTCControl | 739-2 | LTC Control Insp | General Comments | | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | LTCC000706 | LTCControl | 739-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | LTCC000706 | LTCControl | 739-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | LTCC000706 | LTCControl | 739-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Unknown Operations | 0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | 9 Month Operations | 1 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Amps A Ø | 95.0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Amps B Ø | 130.0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Amps C Ø | 140.0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BAT001456 | Battery | 580-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BAT001456 | Battery | 580-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BAT001456 | Battery | 580-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BAT001456 | Battery | 580-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BAT001456 | Battery | 580-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 32 | °F |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BAT001456 | Battery | 580-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Fault Operations Ground | 0 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Amps C Ø | 82.0 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Amps B Ø | 127.0 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Amps A Ø | 107.0 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | 9 Month Operations | 3 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Readings | Totalizer Meter Reading | .4900 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 6000 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BCH001309 | Charger | 884-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BCH001309 | Charger | 884-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BCH001309 | Charger | 884-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BCH001309 | Charger | 884-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BCH001309 | Charger | 884-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.0 | amps |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BCH001309 | Charger | 884-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BCH001309 | Charger | 884-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BCH001309 | Charger | 884-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BAT001381 | Battery | 884-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Maintenance Operations | 0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Operations Counter AF | 173 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | W0074 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | W0074 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Operations Counter AL | 173 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Operations This Read Vac | 0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Switching Operations | 0 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | W0074 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | W0074 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Unknown Operations | 0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | LTCM000063 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | LTCM000063 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | LTCM000063 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | LTCM000063 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | LTCM000063 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | LTCM000063 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | LTCM000063 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | Ambient Temp | 42 | °F |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | W0074 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | W0074 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | W0074 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | W0074 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | WithLTC | 746-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | S0043 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | S0043 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | S0043 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | S0043 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | S0043 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | YD000439 | Yard | 884-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Interruptrs/Puffrs Visual OK? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Follow-up Action Required? | n | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Patrol Inspection | General Comments | | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | General Comments | | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Maintenance Operations | 0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Operations Counter AF | 202 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Operations Counter AL | 202 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Operations This Read Vac | 1 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Switching Operations | 0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001571 | BreakerVacuum | 580-2104 | VCB Readings | Unknown Operations | 0 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | LTCC000706 | LTCControl | 739-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | LTCC000706 | LTCControl | 739-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | FE000435 | Fence | 884-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | B0426 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | B0426 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | B0426 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | B0426 | LTCMechanism | 951-Offline-Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | 9 Month Operations | 0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Amps A Ø | 64.0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Amps B Ø | 64.0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Amps C Ø | 68.0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Fault Operations Ground | 0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | Follow-up Action Required? | n | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Patrol Inspection | General Comments | | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Readings | General Comments | | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001572 | BreakerVacuum | 580-2105 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Amps C Ø | 132.0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Amps B Ø | 166.0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Amps A Ø | 145.0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Unknown Operations | 0 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Switching Operations | 5 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Operations This Read Vac | 5 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0947 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0947 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Operations Counter AL | 387 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0947 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Operations Counter AF | 386 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Maintenance Operations | 0 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | General Comments | | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | General Comments | | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Follow-up Action Required? | n | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Fault Operations Ground | 0 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Amps C Ø | 241.0 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Amps B Ø | 309.0 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Amps A Ø | 273.0 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0265 | BreakerVacuum | 446-2140 | VCB Readings | 9 Month Operations | 5 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0013 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0013 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0013 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0013 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0013 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0013 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0013 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0013 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | W0075 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Counter Readings | LTC Operations Since Last Insp | 475 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Counter Readings | LTC Max Tap Position | 5R | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Counter Readings | LTC As Left Counter | 84483 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Counter Readings | LTC As Found Counter | 84478 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Counter Readings | General Comments | | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | BAT001186 | Battery | 825-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Maintenance Operations | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Operations Counter AF | 126 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Operations Counter AL | 126 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Operations This Read Vac | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Switching Operations | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Unknown Operations | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | BAT001186 | Battery | 825-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | BAT001186 | Battery | 825-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 67.0 | VDC |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | BAT001186 | Battery | 825-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 66.0 | VDC |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | BAT001186 | Battery | 825-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | BAT001186 | Battery | 825-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | BAT001186 | Battery | 825-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | BAT001186 | Battery | 825-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | BAT001186 | Battery | 825-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | BAT001186 | Battery | 825-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | BAT001186 | Battery | 825-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | BAT001186 | Battery | 825-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | BAT001186 | Battery | 825-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Unknown Operations | 0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Switching Operations | 1 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Operations This Read Vac | 1 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Operations Counter AL | 182 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Operations Counter AF | 181 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Maintenance Operations | 0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | General Comments | | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Fault Operations Ground | 0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | 9 Month Operations | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Amps A Ø | 0.0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Amps B Ø | 0.0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Amps C Ø | 0.0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Readings | Totalizer Meter Reading | .4120 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Unknown Operations | 0 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Switching Operations | 2 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Operations This Read Vac | 2 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Operations Counter AL | 279 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Operations Counter AF | 277 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Maintenance Operations | 0 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Fault Operations Ground | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | Follow-up Action Required? | n | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BAT001456 | Battery | 580-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BAT001456 | Battery | 580-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BAT001456 | Battery | 580-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BAT001456 | Battery | 580-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BAT001456 | Battery | 580-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BAT001456 | Battery | 580-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Patrol Inspection | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0100 | BreakerVacuum | 825-BT2-3 | VCB Readings | General Comments | | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | General Comments | | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Readings | Follow-up Action Required? | n | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | CB0271 | BreakerVacuum | 446-2141 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BAT001456 | Battery | 580-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | W0075 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | W0075 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | W0075 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 15.00 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | W0075 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | W0075 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | W0075 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | W0075 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Regulator As Left Counter | 83607 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Reg Output Voltage Level | 120.5 | volts |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Min Tap Position | 3L | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R0925 | Regulator | 746-3 AB | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0947 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0947 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0947 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0947 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0947 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0947 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0947 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Readings | General Comments | | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Readings | LTC Totalizer Reading | 3955.20 | kw |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001563 | BreakerVacuum | 884-2142 | VCB Readings | 9 Month Operations | 1 | |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/27/2023 14:13 | Distribution | Vine Street Quarterly Inspection | B0373 | WithLTC | 739-2 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0388 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0388 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0388 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0388 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0388 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0388 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | ADDED 1 LB | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0388 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0388 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0388 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0388 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0388 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0388 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0381 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0381 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Maintenance Operations | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Fault Operations Ground | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Amps C Ø | 140.0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Amps B Ø | 280.0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Amps A Ø | 283.0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | 9 Month Operations | 0 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | B0426 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | B0426 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | B0426 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | B0426 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | B0426 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | B0426 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | B0426 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | B0426 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Readings | Fault Operations | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Amps C Ø | 140.0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Amps B Ø | 280.0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Amps A Ø | 283.0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | 9 Month Operations | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Ambient Temperature | 25 | °F |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000138 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000138 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000138 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000138 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000138 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000138 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000138 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000138 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | B0270 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | B0270 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | B0270 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | ADDED 1 LB | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | B0270 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0381 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0381 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0381 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0381 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0381 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0381 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0381 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0381 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0381 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0381 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0381 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Unknown Operations | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Switching Operations | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Operations This Read Vac | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Operations Counter AL | 138 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Readings | Operations Counter AF | 138 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0024 | BreakerVacuum | 825-0176 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0388 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0388 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0388 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0388 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Readings | Oil Temp Present | 15 | °C |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Readings | Totalizer Meter Reading | .3290 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Readings | Winding Temp Max | 50 | °C |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Readings | Winding Temp Present | 14 | °C |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 20.00 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Readings | Totalizer Meter Reading | .2894 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Readings | Winding Temp Max | 50 | °C |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Readings | Winding Temp Present | 16 | °C |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0980 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0980 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0980 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0980 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0931 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0931 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0931 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0931 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0931 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0931 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | Cracked Glass | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0931 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0931 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0930 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0930 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0930 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0930 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000257 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000257 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000257 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000257 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0930 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0930 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0930 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0930 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0980 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0980 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0980 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0980 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0980 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000257 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000257 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000257 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000257 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | BOTTLE IS EMPTY, MADE wo | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000257 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .8 | psi |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000257 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000257 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000257 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000257 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000257 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Readings | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Readings | LTC Totalizer Reading | 4167.36 | kw |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | WithLTC | 825-3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | B0270 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | B0270 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | B0270 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | B0270 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | FE000891 | Fence | 825-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Readings | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Readings | LTC Totalizer Reading | 4737.60 | kw |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Readings | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Readings | Oil Temp Present | 13 | °C |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | WithLTC | 825-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 41460 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.3 | volts |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000131 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000131 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000131 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1100 | psi |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000131 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000131 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000131 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000131 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000131 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000131 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000131 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000131 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000131 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000131 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0283 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0283 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0283 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | Cracked Glass | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0283 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0283 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0283 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0283 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0283 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Reg Output Voltage Level | 121.0 | volts |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | ST000442 | Structure | 884-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Readings | Switching Operations | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | SF6 Pressure | 64 | psi |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Readings | Operations This Read SF6 | 0 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0284 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0284 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0284 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0284 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0284 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0284 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0284 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0284 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | 9 Month Operations | 0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Amps A Ø | 175.0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Amps B Ø | 100.0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Amps C Ø | 102.0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Fault Operations Ground | 0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Patrol Inspection | General Comments | | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | General Comments | | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Maintenance Operations | 0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Operations Counter AF | 173 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Operations Counter AL | 173 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Operations This Read Vac | 0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Switching Operations | 0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | BK001573 | BreakerVacuum | 580-2106 | VCB Readings | Unknown Operations | 0 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000131 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000131 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000131 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0413 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Readings | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0413 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0413 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0413 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0413 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0413 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | LTCC000319 | LTCControl | 746-1 | LTC Control Insp | All Connections OK? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000138 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000138 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000138 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000138 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000138 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000138 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | TX000138 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Unknown Operations | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Switching Operations | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Operations This Read Vac | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Operations Counter AL | 180 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Operations Counter AF | 180 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Maintenance Operations | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Fault Operations Ground | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Readings | Fault Operations | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Ambient Temperature | 25 | °F |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Readings | Switching Operations | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | SF6 Pressure | 68 | psi |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Readings | Operations This Read SF6 | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Readings | Operations Counter AL | 84 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Readings | Operations Counter AF | 84 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Readings | Maintenance Operations | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0130 | BreakerVacuum | 825-3 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1479 | BreakerSF6 | 825-618 | GCB Readings | Follow-up Action Required? | n | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1401 | Regulator | 580-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Regulator As Left Counter | 21059 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1308 | Regulator | 746-3 BC | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Readings | Operations Counter AL | 83 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Readings | Operations Counter AF | 83 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | 9 Month Operations | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Amps A Ø | 222.0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Amps B Ø | 257.0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Amps C Ø | 244.0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | LTCC000319 | LTCControl | 746-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | LTCC000319 | LTCControl | 746-1 | LTC Control Insp | VRR Base Voltage AL | 121.0 | VAC |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | LTCC000319 | LTCControl | 746-1 | LTC Control Insp | VRR Base Voltage AF | 121.0 | VAC |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | LTCC000319 | LTCControl | 746-1 | LTC Control Insp | LTC Output Voltage Level | 120.8 | VAC |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | LTCC000319 | LTCControl | 746-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Operations Counter AF | 174 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Operations Counter AL | 174 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Switching Operations | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0413 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0413 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KB0128 | BreakerVacuum | 825-2 | VCB Readings | Unknown Operations | 0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | LTCC000319 | LTCControl | 746-1 | LTC Control Insp | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | LTCC000319 | LTCControl | 746-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Readings | Maintenance Operations | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Readings | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | TB1480 | BreakerSF6 | 825-608 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Readings | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Operations Counter AF | 310 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Maintenance Operations | 0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | PF001322 | PowerFuse | 746-1F | Disconnect Powerfuse Inspection | General Comments | x | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | PF001322 | PowerFuse | 746-1F | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | PF001322 | PowerFuse | 746-1F | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | General Comments | | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Fault Operations Ground | 0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Amps C Ø | 6.0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Amps B Ø | 42.0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Amps A Ø | 18.0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0410 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0410 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0410 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0410 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Readings | LTC Totalizer Reading | 2815.20 | kw |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Readings | Oil Temp Max | 65 | °C |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Readings | Oil Temp Present | 55 | °C |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Operations Counter AF | 157 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Maintenance Operations | 0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Min Tap Position | 1L | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Fault Operations Ground | 0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | LTCC000553 | LTCControl | 884-1 | LTC Control Insp | General Comments | | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | LTCC000553 | LTCControl | 884-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | LTCC000553 | LTCControl | 884-1 | LTC Control Insp | LTC Output Voltage Level | 125.2 | VAC |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | LTCC000553 | LTCControl | 884-1 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | LTCC000553 | LTCControl | 884-1 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | LTCC000553 | LTCControl | 884-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | S0043 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | Bushing oil on A and C phases turning red | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | S0043 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | S0043 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | S0043 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | S0043 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | S0043 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | S0043 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Reg Output Voltage Level | 120.7 | volts |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Regulator As Left Counter | 50505 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.1730 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0508 | NonLTC | 746-3 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Fault Operations Ground | 0 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Follow-up Action Required? | n | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Patrol Inspection | General Comments | | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | General Comments | | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Operations Counter AF | 178 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Operations Counter AL | 180 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Operations This Read Vac | 2 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Switching Operations | 2 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Unknown Operations | 0 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Amps C Ø | 90.0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Amps B Ø | 120.0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Amps A Ø | 130.0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | 9 Month Operations | 4 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0271 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0271 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0271 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0271 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0271 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 125.3 | volts |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 47060 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0271 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 15.00 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0271 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0271 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0271 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | 0271 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Max Tap Position | 1L | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | 9 Month Operations | 2 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Amps A Ø | 252.0 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Amps B Ø | 192.0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Counter Readings | LTC Operations Since Last Insp | 595 | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Readings | Amps C Ø | 202.0 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Min Tap Position | 1L | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Reg Output Voltage Level | 120.0 | volts |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Regulator As Left Counter | 53097 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1016 | Regulator | 746-2 BC | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Counter Readings | LTC As Left Counter | 334236 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Counter Readings | LTC As Found Counter | 334232 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Counter Readings | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | C0417 | LTCMechanism | 746-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | S0043 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0202 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | BK001274 | BreakerVacuum | 446-2139 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | 9 Month Operations | 1 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | S0043 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | S0043 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/27/2023 14:02 | Distribution | Lancaster 1 Quarterly Inspection | C0433 | LTCMechanism | 446-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0049 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0049 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0049 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0049 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0049 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0049 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0049 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0049 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0049 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0049 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0049 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0049 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0049 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Unknown Operations | 0 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 52040 | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 125.4 | volts |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Amps A Ø | 231.0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Amps B Ø | 263.0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Amps C Ø | 250.0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | S0043 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Counter Readings | LTC Operations Since Last Insp | 120 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 10 | °C |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 45 | °C |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | S0043 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | S0043 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | S0043 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | S0043 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | S0043 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | S0043 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | S0043 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0207 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0207 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0207 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0207 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0207 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0207 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0207 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 95.00 | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0207 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0207 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | Glass for the oil temp is cracked | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0207 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0207 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0207 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0207 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | O0207 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1400 | Regulator | 580-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0049 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0049 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Counter Readings | LTC Operations Since Last Insp | 894 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 10 | °C |
| 1/27/2023 11:25 | Distribution | Buena Vista Quarterly Inspection | R1402 | Regulator | 580-1 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 45 | °C |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Counter Readings | LTC As Left Counter | 26764 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Counter Readings | LTC As Found Counter | 26760 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Counter Readings | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0052 | LTCMechanism | 825-3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0049 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0049 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0049 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0049 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | M0049 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Fault Operations Ground | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Counter Readings | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Counter Readings | LTC As Found Counter | 26102 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Counter Readings | LTC As Left Counter | 26108 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | KT0051 | LTCMechanism | 825-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Max Tap Position | 1L | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Operations Counter AL | 314 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Operations This Read Vac | 4 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Switching Operations | 4 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | 9 Month Operations | 0 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BB0484 | BreakerVacuum | 884-2176 | VCB Readings | Unknown Operations | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Readings | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/27/2023 9:38 | Distribution | Corning 12kV Quarterly Inspection | K0002 | BreakerVacuum | 825-0177 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | S0043 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | S0043 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | S0043 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | S0043 | WithLTC | 951-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0410 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 20.00 | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0410 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0410 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0410 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Pineville Substation Department Transformer Quarterly Inspection | C0410 | NonLTC | 951-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Readings | General Comments | | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Operations Counter AL | 158 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Operations This Read Vac | 1 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | BK001564 | BreakerVacuum | 884-2143 | VCB Readings | Switching Operations | 1 | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | LTCC000553 | LTCControl | 884-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | LTCC000553 | LTCControl | 884-1 | LTC Control Insp | All Connections OK? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | General Comments | | |
| 1/27/2023 8:52 | Distribution | Corning Harrodsburg Quarterly Inspection | R1015 | Regulator | 746-2 AB | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/27/2023 14:42 | Distribution | Lancaster 2 Quarterly Inspection | C0394 | WithLTC | 884-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | LTCMechanism | 930-Offline-Distribution | LTC Counter Readings | LTC Operations Since Last Insp | 596 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | LTCMechanism | 930-Offline-Distribution | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | LTCMechanism | 930-Offline-Distribution | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | LTCMechanism | 930-Offline-Distribution | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | LTCMechanism | 930-Offline-Distribution | LTC Counter Readings | LTC As Left Counter | 154466 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | LTCMechanism | 930-Offline-Distribution | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | LTCMechanism | 930-Offline-Distribution | LTC Counter Readings | LTC As Found Counter | 154466 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | LTCMechanism | 930-Offline-Distribution | LTC Counter Readings | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | LTCMechanism | 930-Offline-Distribution | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | LTCMechanism | 930-Offline-Distribution | LTC Mechanism Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | LTCMechanism | 930-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | LTCMechanism | 930-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | LTCMechanism | 930-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | LTCMechanism | 930-Offline-Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | LTCMechanism | 930-Offline-Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Amps A Ø | 121.0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Amps B Ø | 121.0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Amps C Ø | 121.0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Operations Counter AL | 71 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Operations Counter AF | 71 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | General Comments | | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Readings | 9 Month Operations | 2 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Readings | Amps A Ø | 3.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Readings | Amps B Ø | 2.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Readings | Amps C Ø | 4.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Operations Counter AF | 176 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Operations Counter AL | 176 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Switching Operations | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | FE000839 | Fence | 662-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Amps A Ø | 105.0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Amps B Ø | 160.0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Readings | Oil Temp Present | 50 | °C |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Amps C Ø | 165.0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | LTCC000914 | LTCControl | 662-3 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | LTCC000914 | LTCControl | 662-3 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | LTCC000914 | LTCControl | 662-3 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | LTCC000914 | LTCControl | 662-3 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | LTCC000914 | LTCControl | 662-3 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | LTCC000914 | LTCControl | 662-3 | LTC Control Insp | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Readings | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Readings | Operations Counter AF | 273 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Readings | Operations Counter AL | 275 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | LTCC000914 | LTCControl | 662-3 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | LTCC000914 | LTCControl | 662-3 | LTC Control Insp | All Connections OK? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Readings | Operations This Read Vac | 2 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Readings | Switching Operations | 2 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.8170 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BCH001565 | Charger | 717-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BCH001565 | Charger | 717-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BCH001565 | Charger | 717-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BCH001565 | Charger | 717-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BCH001565 | Charger | 717-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 4.3 | amps |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BCH001565 | Charger | 717-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Switching Operations | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Operations Counter AL | 151 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Operations Counter AF | 151 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BCH001565 | Charger | 717-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BCH001565 | Charger | 717-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | 9 Month Operations | 11 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | FE000839 | Fence | 662-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | FE000839 | Fence | 662-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | FE000839 | Fence | 662-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | FE000839 | Fence | 662-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | FE000839 | Fence | 662-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | FE000839 | Fence | 662-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | FE000839 | Fence | 662-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | FE000839 | Fence | 662-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | FE000839 | Fence | 662-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | FE000839 | Fence | 662-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | FE000839 | Fence | 662-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | FE000839 | Fence | 662-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | FE000839 | Fence | 662-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | FE000839 | Fence | 662-Fence | Fence Patrol Inspection | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | FE000839 | Fence | 662-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Readings | General Comments | | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | YD000350 | Yard | 662-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | YD000350 | Yard | 662-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | YD000350 | Yard | 662-Yard | Yard Patrol Inspection | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | YD000350 | Yard | 662-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | YD000350 | Yard | 662-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | YD000350 | Yard | 662-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | YD000350 | Yard | 662-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | YD000350 | Yard | 662-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | YD000350 | Yard | 662-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | YD000350 | Yard | 662-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | YD000350 | Yard | 662-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | YD000350 | Yard | 662-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | YD000350 | Yard | 662-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Readings | LTC Totalizer Reading | 13232.00 | kw |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Operations Counter AF | 203 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Operations Counter AL | 205 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Operations This Read Vac | 2 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Switching Operations | 2 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | ST000353 | Structure | 662-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | ST000353 | Structure | 662-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | ST000353 | Structure | 662-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | ST000353 | Structure | 662-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | ST000353 | Structure | 662-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | ST000353 | Structure | 662-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | ST000353 | Structure | 662-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | ST000353 | Structure | 662-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | ST000353 | Structure | 662-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | LTCMechanism | 662-3 | LTC Counter Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | LTCMechanism | 662-3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | LTCMechanism | 662-3 | LTC Counter Readings | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | LTCMechanism | 662-3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | LTCMechanism | 662-3 | LTC Counter Readings | LTC As Found Counter | 42993 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | LTCMechanism | 662-3 | LTC Counter Readings | LTC As Left Counter | 42993 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | LTCMechanism | 662-3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | YD000350 | Yard | 662-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | YD000350 | Yard | 662-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | YD000350 | Yard | 662-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | LTCMechanism | 662-3 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | LTCMechanism | 662-3 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | LTCMechanism | 662-3 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | LTCMechanism | 662-3 | LTC Counter Readings | LTC Operations Since Last Insp | 422 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | LTCMechanism | 662-3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | LTCMechanism | 662-3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | LTCMechanism | 662-3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 136348 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | LTCC000814 | LTCControl | 662-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | LTCC000814 | LTCControl | 662-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | LTCC000814 | LTCControl | 662-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Readings | Oil Temp Max | 65 | °C |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 8000 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Readings | Totalizer Meter Reading | 1.6540 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Operations Counter AF | 217 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Operations Counter AL | 219 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | LTCC000814 | LTCControl | 662-2 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Operations This Read Vac | 2 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Switching Operations | 2 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Switching Operations | 2 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Operations This Read Vac | 2 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | ST000353 | Structure | 662-Structure | Structure Patrol Inspection | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | ST000353 | Structure | 662-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | ST000353 | Structure | 662-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | ST000353 | Structure | 662-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | ST000353 | Structure | 662-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | ST000353 | Structure | 662-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | ST000353 | Structure | 662-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | ST000353 | Structure | 662-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | ST000353 | Structure | 662-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | ST000353 | Structure | 662-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | ST000353 | Structure | 662-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | ST000353 | Structure | 662-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | ST000353 | Structure | 662-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | ST000353 | Structure | 662-Structure | Structure Patrol Inspection | UG Pothead Condition Good? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | 9 Month Operations | 2 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Amps A Ø | 73.0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Amps B Ø | 121.0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Amps C Ø | 84.0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000970 | BreakerVacuum | 621-0189 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | 9 Month Operations | 8 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Amps C Ø | 0.0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Amps B Ø | 0.0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Amps A Ø | 0.0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | 9 Month Operations | 4 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Readings | LTC Totalizer Reading | 5712.00 | kw |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Readings | General Comments | | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Fans Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Amps A Ø | 134.0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Amps B Ø | 148.0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Amps C Ø | 143.0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Amps C Ø | 380.0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Amps B Ø | 364.0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Amps A Ø | 385.0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001042 | BreakerVacuum | 621-1 | VCB Readings | 9 Month Operations | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1360 | BreakerVacuum | TT-34KV TR 1 | VCB Readings | 9 Month Operations | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Operations Counter AF | 203 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Operations Counter AL | 205 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Operations This Read Vac | 2 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Switching Operations | 2 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | KB0079 | BreakerVacuum | 717-0599 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCC000690 | LTCControl | 621-1 | LTC Control Insp | All Connections OK? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCC000690 | LTCControl | 621-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | 9 Month Operations | 3 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | WithLTC | 028-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCC000690 | LTCControl | 621-1 | LTC Control Insp | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCC000690 | LTCControl | 621-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCC000690 | LTCControl | 621-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCC000690 | LTCControl | 621-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCC000690 | LTCControl | 621-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCC000690 | LTCControl | 621-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | ST000419 | Structure | 717-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Switching Operations | 2 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Operations This Read Vac | 2 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Operations Counter AL | 225 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Operations Counter AF | 223 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Amps C Ø | 117.0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Amps B Ø | 130.0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000969 | BreakerVacuum | 621-0116 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Amps A Ø | 129.0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001041 | BreakerVacuum | 621-0190 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | 9 Month Operations | 18 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | 9 Month Operations VCB New | 16 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Amps A Ø | 195.0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Amps B Ø | 190.0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Amps C Ø | 210.0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Operations Counter AF | 182 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Operations Counter AL | 184 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Operations This Read Vac | 2 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Readings | Switching Operations | 2 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK001102 | BreakerVacuum | 717-0099 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BCH001471 | Charger | 550-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BCH001471 | Charger | 550-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BCH001471 | Charger | 550-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Readings | Totalizer Meter Reading | 1.2340 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Readings | Totalizer Meter Reading | .8040 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | LTCC000739 | LTCControl | 028-6 | LTC Control Insp | All Connections OK? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | LTCC000739 | LTCControl | 028-6 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Readings | Amps C Ø | 140.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Readings | Amps B Ø | 220.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Readings | Amps A Ø | 180.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Readings | 9 Month Operations | 2 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | LTCC000739 | LTCControl | 028-6 | LTC Control Insp | General Comments | | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | LTCC000739 | LTCControl | 028-6 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | LTCC000739 | LTCControl | 028-6 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | LTCC000739 | LTCControl | 028-6 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | LTCC000739 | LTCControl | 028-6 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | LTCC000739 | LTCControl | 028-6 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BCH001471 | Charger | 550-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BCH001471 | Charger | 550-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BCH001471 | Charger | 550-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BCH001471 | Charger | 550-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BCH001471 | Charger | 550-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Readings | Operations This Read Vac | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Readings | Operations Counter AL | 120 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Readings | Operations Counter AF | 120 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Readings | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Readings | Amps C Ø | 365.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Readings | Amps B Ø | 550.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Readings | Amps A Ø | 450.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Readings | 9 Month Operations | 6 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Counter Readings | LTC Operations Since Last Insp | 301 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BAT000531 | Battery | 662-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BAT000531 | Battery | 662-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BAT000531 | Battery | 662-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BAT000531 | Battery | 662-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BAT000531 | Battery | 662-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BAT000531 | Battery | 662-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BAT000531 | Battery | 662-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BAT000531 | Battery | 662-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BAT000531 | Battery | 662-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BAT000531 | Battery | 662-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BAT000531 | Battery | 662-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BAT000531 | Battery | 662-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | LTCC000799 | LTCControl | 028-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | LTCC000799 | LTCControl | 028-5 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | LTCC000799 | LTCControl | 028-5 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | LTCC000799 | LTCControl | 028-5 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | LTCC000799 | LTCControl | 028-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | LTCC000799 | LTCControl | 028-5 | LTC Control Insp | General Comments | | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | LTCC000799 | LTCControl | 028-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | LTCC000799 | LTCControl | 028-5 | LTC Control Insp | All Connections OK? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Readings | Switching Operations | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Counter Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Counter Readings | General Comments | | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Counter Readings | LTC As Found Counter | 18057 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Counter Readings | LTC As Left Counter | 18057 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0345 | LTCMechanism | 028-5 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Readings | Oil Temp Present | 15 | °C |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Readings | LTC Totalizer Reading | 17769.60 | kw |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Readings | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Readings | LTC Totalizer Reading | 9650.40 | kw |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Readings | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | LTCC000942 | LTCControl | 717-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | LTCC000942 | LTCControl | 717-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | LTCC000942 | LTCControl | 717-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | LTCC000942 | LTCControl | 717-1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | LTCC000942 | LTCControl | 717-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | LTCC000942 | LTCControl | 717-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | LTCC000942 | LTCControl | 717-1 | LTC Control Insp | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | LTCC000942 | LTCControl | 717-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | LTCC000942 | LTCControl | 717-1 | LTC Control Insp | All Connections OK? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BAT001121 | Battery | 550-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BAT001121 | Battery | 550-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BAT001121 | Battery | 550-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BAT001121 | Battery | 550-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.0 | VDC |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BAT001121 | Battery | 550-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BAT001121 | Battery | 550-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BAT001121 | Battery | 550-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BAT001121 | Battery | 550-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BAT001121 | Battery | 550-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BAT001121 | Battery | 550-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BAT001121 | Battery | 550-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BAT001121 | Battery | 550-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 34 | °F |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BAT001121 | Battery | 550-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Readings | Totalizer Meter Reading | .4021 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Readings | Winding Temp Max | 45 | °C |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Readings | Winding Temp Present | 35 | °C |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Readings | Switching Operations | 2 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Readings | Operations This Read Vac | 2 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Readings | Operations Counter AL | 99833 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Readings | Operations Counter AF | 99831 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | All Connections OK? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Cap bank CT in Good Condition? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Cap bank PT in Good Condition? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Capacitor Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Capacitor Rack Condition OK? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Fuses Blown? Y / N | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | General Comments | | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Insulators In Good Condition? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Tank Leaks | None | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Tank Paint Condition | Adequate | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000133 | CapacitorBank | TT-Cap Bank 1 | Capacitor Patrol Inspection | Warning Signs OK? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | WithLTC | 621-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 125.2 | volts |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 469285 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Readings | General Comments | | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Readings | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0054 | BreakerVacuum | 662-0109 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 130 | °C |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 200.00 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 35 | °C |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 25 | °C |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 21 | °C |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 10 | °C |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 35 | °C |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Readings | LTC Totalizer Reading | 3859.20 | kw |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 22 | °C |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | WithLTC | TT-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1300 | psi |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | WithLTC | 662-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1121 | Regulator | 550-1 C | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Readings | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Readings | LTC Totalizer Reading | 16891.20 | kw |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Readings | Totalizer Meter Reading | .7140 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Readings | Totalizer Meter Multiplier | 8000 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 75601 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Readings | Oil Temp Max | 20 | °C |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Readings | Totalizer Meter Reading | 1.1730 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Readings | Winding Temp Max | 80 | °C |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BCH001354 | Charger | 662-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BCH001354 | Charger | 662-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Amps C Ø | 180.0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Amps B Ø | 260.0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Amps A Ø | 205.0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | 9 Month Operations | 7 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1117 | Regulator | 550-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | WithLTC | 028-6 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | 9 Month Operations | 7 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Amps A Ø | 370.0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Amps B Ø | 440.0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Amps C Ø | 340.0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000649 | BreakerVacuum | 717-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Readings | Winding Temp Present | 25 | °C |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 135.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | WithLTC | 717-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | FE000412 | Fence | 717-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Readings | Switching Operations | 2 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Readings | Operations This Read Vac | 2 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Readings | Operations Counter AL | 80 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Readings | Operations Counter AF | 78 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Readings | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Readings | 9 Month Operations | 2 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Readings | Amps A Ø | 0.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Readings | Amps B Ø | 0.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Readings | Amps C Ø | 0.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0053 | BreakerVacuum | 662-0179 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Readings | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | WithLTC | 717-1 | LTC Transformer Readings | LTC Totalizer Reading | 13082.40 | kw |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0047 | BreakerVacuum | 662-0085 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Readings | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Readings | Operations Counter AF | 365 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Readings | Operations Counter AL | 367 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Readings | Operations This Read Vac | 2 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Readings | Switching Operations | 2 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | R1086 | Regulator | 550-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Readings | Oil Temp Max | 60 | °C |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 55.00 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 62.50 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 8.64 | kw |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Readings | General Comments | | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Switching Operations | 2 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | S0029 | WithLTC | 662-3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BAT000531 | Battery | 662-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BAT000531 | Battery | 662-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 35 | °F |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BAT000531 | Battery | 662-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Readings | Amps A Ø | 280.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Readings | Amps B Ø | 315.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Readings | Amps C Ø | 230.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0058 | BreakerVacuum | 662-3 | VCB Readings | 9 Month Operations | 0 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .0108 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 800 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | C0319 | NonLTC | 550-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | K0052 | BreakerVacuum | 662-0039 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | 9 Month Operations | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | General Comments | | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BCH001354 | Charger | 662-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BCH001354 | Charger | 662-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BCH001354 | Charger | 662-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BCH001354 | Charger | 662-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BCH001354 | Charger | 662-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 5.6 | amps |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BCH001354 | Charger | 662-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Switching Operations | 1 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Operations This Read Vac | 1 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Operations Counter AL | 178 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Operations Counter AF | 177 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | General Comments | | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001825 | BreakerVacuum | 028-0004 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Operations This Read Vac | 2 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Operations Counter AL | 345 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | LTCC000835 | LTCControl | 717-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | LTCC000835 | LTCControl | 717-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | LTCC000835 | LTCControl | 717-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | LTCC000835 | LTCControl | 717-2 | LTC Control Insp | LTC Output Voltage Level | 123.7 | VAC |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | LTCC000835 | LTCControl | 717-2 | LTC Control Insp | LTC Operation Checked? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | LTCC000835 | LTCControl | 717-2 | LTC Control Insp | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | LTCC000835 | LTCControl | 717-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | LTCC000835 | LTCControl | 717-2 | LTC Control Insp | All Connections OK? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Switching Operations | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Operations This Read Vac | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Operations Counter AL | 140 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Operations Counter AF | 140 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | General Comments | | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Readings | Operations Counter AF | 343 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0081 | BreakerVacuum | 028-0002 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Amps C Ø | 0.0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Amps B Ø | 0.0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Amps A Ø | 0.0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1357 | BreakerVacuum | TT-34KV BUS TIE & TFR | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Counter Readings | LTC Operations Since Last Insp | 340 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Readings | Switching Operations | 2 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Readings | Operations This Read Vac | 2 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Readings | Operations Counter AL | 165 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Readings | Operations Counter AF | 163 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Readings | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Counter Readings | LTC As Left Counter | 33721 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Counter Readings | LTC As Found Counter | 33721 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Counter Readings | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 90 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 2L | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 56180 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 56180 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LT0194 | LTCMechanism | TT-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | General Comments | | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Operations Counter AF | 209 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Operations Counter AL | 210 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Operations This Read Vac | 1 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Switching Operations | 1 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Readings | LTC Totalizer Reading | 19094.40 | kw |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Readings | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Readings | Amps C Ø | 0.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Readings | Amps B Ø | 0.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Readings | Amps A Ø | 0.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Readings | 9 Month Operations | 2 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0351 | LTCMechanism | 717-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Amps C Ø | 1.0 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Amps B Ø | 2.0 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Amps A Ø | 1.0 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | 9 Month Operations | 2 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | 9 Month Operations | 5 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Amps A Ø | 300.0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Amps B Ø | 350.0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Amps C Ø | 350.0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | General Comments | | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Operations Counter AF | 550 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Operations Counter AL | 551 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Operations This Read Vac | 1 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Switching Operations | 1 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Readings | Amps C Ø | 410.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Readings | Amps B Ø | 405.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Readings | Amps A Ø | 375.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001328 | BreakerVacuum | 662-0130 | VCB Readings | 9 Month Operations | 8 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Switching Operations | 1 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Operations This Read Vac | 1 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Operations Counter AL | 176 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Operations Counter AF | 175 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | General Comments | | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | Ambient Temp | 37 | °F |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | YD000417 | Yard | 717-Yard | Yard Patrol Inspection | General Comments | | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | BK001786 | BreakerVacuum | 550-0165 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Operations Counter AF | 300 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | 9 Month Operations | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Amps A Ø | 122.0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Amps B Ø | 122.0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Amps C Ø | 122.0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | General Comments | | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Operations Counter AF | 119 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Operations Counter AL | 119 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Operations This Read Vac | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Readings | Switching Operations | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1363 | BreakerVacuum | TT-3314 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Operations Counter AL | 300 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Switching Operations | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | 9 Month Operations | 20 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | 9 Month Operations VCB New | 18 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Amps A Ø | 80.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Amps B Ø | 80.0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Amps C Ø | 25.0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Operations Counter AF | 198 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Operations Counter AL | 200 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Operations This Read Vac | 2 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Switching Operations | 2 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000844 | BreakerVacuum | 717-0047 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Readings | Switching Operations | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Readings | Operations Counter AL | 153 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Readings | Operations Counter AF | 153 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Readings | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Readings | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Readings | Winding Temp Present | 35 | °C |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Readings | Winding Temp Max | 45 | °C |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Readings | Totalizer Meter Reading | 1.3260 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0417 | WithLTC | 662-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | 9 Month Operations | 3 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Amps A Ø | 175.0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Amps B Ø | 195.0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Amps C Ø | 180.0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BK001423 | BreakerVacuum | 028-0001 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | General Comments | | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | ST000556 | Structure | 550-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Readings | Amps C Ø | 400.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Readings | Amps B Ø | 425.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Readings | Amps A Ø | 390.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001330 | BreakerVacuum | 662-2 | VCB Readings | 9 Month Operations | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Readings | Switching Operations | 2 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Readings | Operations This Read Vac | 2 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Readings | Operations Counter AL | 182 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Readings | Operations Counter AF | 180 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001329 | BreakerVacuum | 662-0180 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Readings | Switching Operations | 2 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Readings | Operations This Read Vac | 2 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Readings | Operations Counter AL | 202 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Readings | Operations Counter AF | 200 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Readings | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | FE000851 | Fence | 621-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Readings | Amps C Ø | 160.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Readings | Amps B Ø | 145.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Readings | Amps A Ø | 155.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Readings | 9 Month Operations | 2 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | MOD Motor Jaw Coupling | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | MOD Cabinet Internals Clean? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | MOD Cabinet Heater functional? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | ST000351 | Structure | 621-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BAT001674 | Battery | 717-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BAT001674 | Battery | 717-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 37 | °F |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BAT001674 | Battery | 717-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BAT001674 | Battery | 717-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BAT001674 | Battery | 717-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BAT001674 | Battery | 717-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BAT001674 | Battery | 717-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BAT001674 | Battery | 717-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BAT001674 | Battery | 717-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BAT001674 | Battery | 717-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BAT001674 | Battery | 717-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BAT001674 | Battery | 717-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BAT001674 | Battery | 717-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001327 | BreakerVacuum | 662-0016 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Counter Readings | LTC Operations Since Last Insp | 323 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Counter Readings | LTC As Left Counter | 31670 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Counter Readings | LTC As Found Counter | 31670 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Counter Readings | General Comments | | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | B0342 | LTCMechanism | 028-6 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Readings | Amps C Ø | 130.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Readings | Amps B Ø | 135.0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Readings | Amps A Ø | 135.0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | 9 Month Operations | 1 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Readings | 9 Month Operations | 2 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Counter Readings | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Counter Readings | LTC As Found Counter | 35283 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Counter Readings | LTC As Left Counter | 35283 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Counter Readings | LTC Operations Since Last Insp | 407 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | B0380 | LTCMechanism | 717-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Switching Operations | 1 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Operations This Read Vac | 1 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Operations Counter AL | 126 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Operations Counter AF | 126 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | General Comments | | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Amps C Ø | 51.0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Amps B Ø | 51.0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Amps A Ø | 51.0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1359 | BreakerVacuum | TT-3311 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Readings | Switching Operations | 2 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Readings | Operations This Read Vac | 2 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Readings | Operations Counter AL | 225 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Readings | Operations Counter AF | 223 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Readings | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | BK001326 | BreakerVacuum | 662-0011 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Counter Readings | LTC As Found Counter | 10506 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Counter Readings | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Counter Readings | LTC Operations Since Last Insp | 459 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 25 | °C |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 50 | °C |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Counter Readings | LTC Min Tap Position | 13L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Counter Readings | LTC As Left Counter | 12202 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Counter Readings | LTC As Found Counter | 12202 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Counter Readings | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCM000089 | LTCMechanism | 621-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | LTCMechanism | 662-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | LTCMechanism | 662-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | LTCMechanism | 662-1 | LTC Counter Readings | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | LTCMechanism | 662-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | LTCMechanism | 662-1 | LTC Counter Readings | LTC As Found Counter | 8883 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | LTCMechanism | 662-1 | LTC Counter Readings | LTC As Left Counter | 8883 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | LTCMechanism | 662-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | LTCMechanism | 662-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | LTCMechanism | 662-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | LTCMechanism | 662-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | LTCMechanism | 662-1 | LTC Counter Readings | LTC Operations Since Last Insp | 485 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | LTCMechanism | 662-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0438 | BreakerVacuum | 028-0003 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Counter Readings | LTC Operations Since Last Insp | 804 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | 9 Month Operations | 5 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Amps A Ø | 300.0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Amps B Ø | 400.0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Amps C Ø | 375.0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Switching Operations | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Operations This Read Vac | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Operations Counter AL | 106 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Operations Counter AF | 106 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | General Comments | | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | B0383 | LTCMechanism | 621-1 | LTC Counter Readings | LTC As Left Counter | 10506 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Amps A Ø | 0.0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCC000796 | LTCControl | 621-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCC000796 | LTCControl | 621-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCC000796 | LTCControl | 621-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCC000796 | LTCControl | 621-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCC000796 | LTCControl | 621-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCC000796 | LTCControl | 621-2 | LTC Control Insp | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCC000796 | LTCControl | 621-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | LTCC000796 | LTCControl | 621-2 | LTC Control Insp | All Connections OK? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | LTCC000665 | LTCControl | 662-1 | LTC Control Insp | All Connections OK? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | LTCC000665 | LTCControl | 662-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | LTCC000665 | LTCControl | 662-1 | LTC Control Insp | General Comments | | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | LTCC000665 | LTCControl | 662-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | LTCC000665 | LTCControl | 662-1 | LTC Control Insp | LTC Output Voltage Level | 123.5 | VAC |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | LTCC000665 | LTCControl | 662-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | 9 Month Operations | 9 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | LTCC000665 | LTCControl | 662-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Readings | Winding Temp Present | 23 | °C |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Readings | Winding Temp Max | 55 | °C |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Readings | Totalizer Meter Reading | .5650 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Readings | Oil Temp Present | 23 | °C |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1700 | psi |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Readings | LTC Totalizer Reading | 13560.00 | kw |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Readings | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | LTCC000665 | LTCControl | 662-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | TX000218 | WithLTC | 621-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | LTCMechanism | 662-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | B0281 | LTCMechanism | 662-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Amps C Ø | 99.0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Amps B Ø | 100.0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Amps A Ø | 97.0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1356 | BreakerVacuum | TT-3316 | VCB Readings | 9 Month Operations | 1 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Switching Operations | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Operations This Read Vac | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Operations Counter AL | 116 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Operations Counter AF | 116 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | General Comments | | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | General Comments | | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Operations Counter AF | 89 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Operations Counter AL | 90 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Operations This Read Vac | 1 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Switching Operations | 1 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | BB0469 | BreakerVacuum | 028-0007 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Amps C Ø | 0.0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1361 | BreakerVacuum | TT-3313 | VCB Readings | Amps B Ø | 0.0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Amps C Ø | 149.0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Amps B Ø | 155.0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Amps A Ø | 147.0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | 9 Month Operations | 8 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Switching Operations | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | 9 Month Operations | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | 9 Month Operations | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Switching Operations | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Operations Counter AL | 310 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Operations Counter AF | 310 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | General Comments | | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Amps C Ø | 205.0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Amps B Ø | 205.0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Amps A Ø | 205.0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | General Comments | 3 fuses blown on bank. | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Fuses Blown? Y / N | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Operations Counter AF | 193 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Operations Counter AL | 195 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Operations This Read Vac | 2 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Switching Operations | 2 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Switching Operations | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Operations Counter AL | 190 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Operations Counter AF | 190 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | General Comments | | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | All Connections OK? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Amps C Ø | 0.0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Amps B Ø | 0.0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Amps A Ø | 0.0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Amps C Ø | 150.0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | 9 Month Operations VCB New | 21 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | 9 Month Operations | 21 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Amps C Ø | 393.0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Amps B Ø | 449.0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Amps A Ø | 390.0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Operations Counter AF | 195 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Operations Counter AL | 197 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Operations This Read Vac | 2 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Switching Operations | 2 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Ambient Temp | 34 | °F |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | General Comments | there is no berm in staton | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | YD000552 | Yard | 550-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Operations This Read Vac | 2 | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Operations Counter AL | 196 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Operations Counter AF | 194 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Maintenance Operations | 2 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | 9 Month Operations | 2 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Amps A Ø | 150.0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000971 | BreakerVacuum | 621-0041 | VCB Readings | Amps B Ø | 171.0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | 9 Month Operations | 3 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000974 | BreakerVacuum | 621-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1362 | BreakerVacuum | TT-CAP BK 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Follow-up Action Required? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | General Comments | | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Operations Counter AF | 198 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Operations Counter AL | 200 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Operations Counter AL | 197 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Operations Counter AF | 195 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Operations This Read Vac | 2 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Switching Operations | 2 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Amps C Ø | 165.0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Capacitor Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Cap bank PT in Good Condition? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Cap bank CT in Good Condition? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Amps B Ø | 210.0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Amps A Ø | 165.0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | 9 Month Operations | 2 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | 9 Month Operations VCB New | 11 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000843 | BreakerVacuum | 717-0025 | VCB Readings | 9 Month Operations | 13 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | 9 Month Operations | 11 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Amps A Ø | 20.0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Amps B Ø | 50.0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Amps C Ø | 50.0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Switching Operations | 2 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Capacitor Rack Condition OK? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Operations This Read Vac | 2 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Operations Counter AL | 223 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Operations Counter AF | 221 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000973 | BreakerVacuum | 621-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Operations Counter AL | 69 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Insulators In Good Condition? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | 9 Month Operations VCB New | 19 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | PF000360 | PowerFuse | TT-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | PF000360 | PowerFuse | TT-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | PF000360 | PowerFuse | TT-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | PF000361 | PowerFuse | TT-34KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | PF000361 | PowerFuse | TT-34KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | PF000361 | PowerFuse | TT-34KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | PF000362 | PowerFuse | TT-34KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | PF000362 | PowerFuse | TT-34KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | PF000362 | PowerFuse | TT-34KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | 9 Month Operations | 3 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | Ambient Temp | 42 | °F |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Unknown Operations | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Switching Operations | 1 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Operations This Read Vac | 1 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Operations Counter AL | 254 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Operations Counter AF | 253 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Tank Leaks | None | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Tank Paint Condition | Adequate | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | CAP000064 | CapacitorBank | TT-Cap Bank 2 | Capacitor Patrol Inspection | Warning Signs OK? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 13:59 | Distribution | Lexington Plant Quarterly Inspection | K0082 | BreakerVacuum | 028-0006 | VCB Readings | General Comments | | |
| 1/26/2023 14:20 | Distribution | Garrard Ct Quarterly Inspection | FE000545 | Fence | 550-Fence | Fence Patrol Inspection | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Amps C Ø | 165.0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Amps B Ø | 161.0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Amps A Ø | 167.0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Amps C Ø | 141.0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Amps B Ø | 98.0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Amps A Ø | 150.0 | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK001040 | BreakerVacuum | 621-0159 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | LTCC000814 | LTCControl | 662-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Readings | Follow-up Action Required? | n | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | BK000909 | BreakerVacuum | 717-0071 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | YD000348 | Yard | 621-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | LTCC000814 | LTCControl | 662-2 | LTC Control Insp | General Comments | | |
| 1/26/2023 8:24 | Distribution | Viley Road Quarterly Inspection | BK000972 | BreakerVacuum | 621-0115 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | LTCC000814 | LTCControl | 662-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/26/2023 10:14 | Distribution | Lexington Water Company Quarterly Inspection | LTCC000814 | LTCControl | 662-2 | LTC Control Insp | All Connections OK? | y | |
| 1/26/2023 8:51 | Distribution | Joyland Quarterly Inspection | K0186 | BreakerVacuum | 717-BT1-2 | VCB Readings | 9 Month Operations | 19 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | General Comments | | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/26/2023 11:43 | Distribution | Tip Top Quarterly Inspection | LB1364 | BreakerVacuum | TT-34KV TR 2 | VCB Readings | Operations Counter AF | 69 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Ambient Temp | 52 | °F |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Operations Counter AF | 705 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Operations Counter AL | 705 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | General Comments | | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Operations This Read AM | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Switching Operations | 0 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | n | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | n | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | YD000437 | Yard | 586-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Patrol Inspection | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Operations Counter AF | 1239 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Patrol Inspection | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Fault Adjusted Amps B Phase AM | 33.54 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Fault Adjusted Amps C Phase AM | 22.36 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Fault Operations B Ø | 3 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Fault Operations C Ø | 2 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Patrol Inspection | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | General Comments | B and C phase IOC | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Operations Counter AF | 161 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Operations Counter AL | 161 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Operations This Read AM | 5 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Switching Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Unknown Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Counter Readings | General Comments | | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Counter Readings | LTC As Found Counter | 242549 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Counter Readings | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Counter Readings | LTC As Found Counter | 42590 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Counter Readings | LTC As Left Counter | 42593 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Counter Readings | LTC Max Tap Position | 5R | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 30 | °C |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Counter Readings | LTC Operations Since Last Insp | 556 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Counter Readings | LTC As Left Counter | 242553 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Counter Readings | LTC Operations Since Last Insp | 646 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | LTCMechanism | 549-3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Switching Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Operations This Read Vac | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Operations Counter AL | 304 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Operations Counter AF | 304 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 65 | °C |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 50 | °C |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Operations Counter AF | 46 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Operations Counter AL | 46 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Switching Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 35 | °C |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 55 | °C |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 35 | °C |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 55 | °C |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 35 | °C |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Unknown Operations | 0 | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | 9 Month Ops New | 1 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | 9 Months Operations | 6 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Amps A Ø | 350.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Amps B Ø | 360.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Amps C Ø | 390.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0055 | BreakerAirMagnetic | AB-1205 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | 9 Month Operations | 2 | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | General Comments | | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | LTCC000287 | LTCControl | 404-1 | LTC Control Insp | General Comments | | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | LTCC000287 | LTCControl | 404-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | LTCC000287 | LTCControl | 404-1 | LTC Control Insp | All Connections OK? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Switching Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Operations This Read AM | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Operations Counter AL | 1239 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Switching Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Operations This Read AM | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Operations Counter AL | 577 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | LTCC000969 | LTCControl | 586-1 | LTC Control Insp | All Connections OK? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | LTCC000969 | LTCControl | 586-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | LTCC000969 | LTCControl | 586-1 | LTC Control Insp | General Comments | | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | LTCC000969 | LTCControl | 586-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | LTCC000969 | LTCControl | 586-1 | LTC Control Insp | LTC Output Voltage Level | 123.4 | VAC |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | LTCC000969 | LTCControl | 586-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Operations Counter AL | 125 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Operations Counter AF | 125 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Patrol Inspection | General Comments | | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | LTCC000969 | LTCControl | 586-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | LTCC000969 | LTCControl | 586-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | LTCC000969 | LTCControl | 586-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LTCC000016 | LTCControl | KE-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LTCC000016 | LTCControl | KE-TRANS 1 | LTC Control Insp | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LTCC000016 | LTCControl | KE-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Operations Counter AF | 577 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Patrol Inspection | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Switching Operations | 2 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Operations This Read Vac | 2 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Operations Counter AL | 386 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LTCC000016 | LTCControl | KE-TRANS 1 | LTC Control Insp | All Connections OK? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LTCC000015 | LTCControl | KE-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LTCC000015 | LTCControl | KE-TRANS 2 | LTC Control Insp | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LTCC000015 | LTCControl | KE-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LTCC000015 | LTCControl | KE-TRANS 2 | LTC Control Insp | All Connections OK? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Amps C Ø | 691.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Amps B Ø | 691.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Amps A Ø | 716.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | 9 Months Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0679 | BreakerAirMagnetic | ML-12KV TR 6 | AMCB Readings | 9 Month Ops New | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Patrol Inspection | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Operations Counter AF | 82 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Operations Counter AL | 82 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Operations This Read AM | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Switching Operations | 0 | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | General Comments | | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | n | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | 9 Month Operations | 2 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | YD000421 | Yard | 627-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Amps A Ø | 132.0 | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.9 | volts |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 71734 | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0949 | Regulator | 627-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Amps B Ø | 137.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Amps C Ø | 133.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Unknown Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Switching Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Operations This Read AM | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Operations Counter AF | 621 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Operations Counter AL | 621 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Operations This Read Vac | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0671 | BreakerVacuum | ML-1286 | VCB Readings | Switching Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | YD000648 | Yard | KE-Yard | Yard Patrol Inspection | Ambient Temp | 38 | °F |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Amps C Ø | 90 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Amps B Ø | 70 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Amps A Ø | 95 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Accumulated Fault Duty C Ph V | 4.11 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Accumulated Fault Duty B Ph V | 4.57 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Accumulated Fault Duty A Ph V | 3.2 | % |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | General Comments | | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | 9 Months Operations | 0 | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | Ambient Temp | 38 | °F |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | YD000481 | Yard | 742-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | PF001352 | PowerFuse | 627-1F | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | PF001352 | PowerFuse | 627-1F | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | PF001352 | PowerFuse | 627-1F | Disconnect Powerfuse Inspection | General Comments | All Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | LTCC000287 | LTCControl | 404-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | LTCC000287 | LTCControl | 404-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | LTCC000287 | LTCControl | 404-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | LTCC000287 | LTCControl | 404-1 | LTC Control Insp | LTC Output Voltage Level | 123.9 | VAC |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | LTCC000287 | LTCControl | 404-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Amps C Ø | 198.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Amps A Ø | 71.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Amps B Ø | 56.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Amps C Ø | 57.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Amps B Ø | 203.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Amps A Ø | 212.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | 9 Month Operations VCB New | 4 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | 9 Month Operations | 4 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0528 | BreakerAirMagnetic | KE-1155 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | WithLTC | KE-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Amps C Ø | 300.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Amps B Ø | 250.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Amps A Ø | 300.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | 9 Months Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0062 | BreakerAirMagnetic | AB-12KV TR 2 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Switching Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Operations This Read Vac | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Operations Counter AL | 585 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Operations Counter AF | 585 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | 9 Month Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Amps A Ø | 380 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Operations Counter AF | 384 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | General Comments | | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | FE000450 | Fence | 417-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0673 | BreakerVacuum | ML-1291 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Amps B Ø | 390 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0462 | BreakerVacuum | 549-1 | VCB Readings | Amps C Ø | 380 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0056 | BreakerVacuum | 549-0904 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | FE000474 | Fence | 742-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Switching Operations | 0 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | General Comments | | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Operations This Read AM | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Operations Counter AL | 861 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Operations Counter AF | 861 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Patrol Inspection | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Amps C Ø | 47.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Amps B Ø | 81.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Amps A Ø | 70.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | 9 Month Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Operations This Read Vac | 0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 2L | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 4L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 97303 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 97303 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 106 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 190584 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 190584 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Counter Readings | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | LTCMechanism | AB-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Unknown Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Operations Counter AL | 383 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Operations Counter AF | 383 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Amps C Ø | 203.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Amps B Ø | 213.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Amps A Ø | 207.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | 9 Month Operations | 2 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Amps C Ø | 70.0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Amps B Ø | 89.0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Amps A Ø | 67.0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | 9 Month Operations | 2 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Amps A Ø | 183.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Amps B Ø | 72.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Amps C Ø | 66.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000103 | Switchgear | AB-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Switching Operations | 3 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Operations This Read Vac | 3 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Operations Counter AL | 1696 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Amps C Ø | 140.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Amps B Ø | 180.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Amps A Ø | 120.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | 9 Months Operations | 2 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | FE000455 | Fence | 404-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Operations Counter AF | 1696 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | General Comments | | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Switching Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Operations This Read Vac | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Operations Counter AL | 235 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Operations Counter AF | 235 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0535 | BreakerVacuum | KE-1162 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Readings | Totalizer Meter Reading | .805 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0 | VDC |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0 | VDC |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Readings | Winding Temp Max | 45 | °C |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 36175 | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BAT001248 | Battery | 507-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Readings | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.2 | volts |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Restroom Clean & OK? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Panels Dusted? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Readings | LTC Totalizer Reading | 11592 | kw |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2 | psi |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | WithLTC | 549-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | CH000147 | ControlHouse | AB-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Amps C Ø | 1.0 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Amps B Ø | 1.0 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Amps A Ø | 0.0 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | 9 Month Operations | 2 | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1525 | Regulator | 742-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | 9 Month Ops New | 4 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | 9 Months Operations | 4 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Amps A Ø | 200.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Amps B Ø | 180.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Amps C Ø | 180.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Patrol Inspection | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Operations Counter AF | 903 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Operations Counter AL | 903 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Operations This Read AM | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Switching Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0054 | BreakerAirMagnetic | AB-1204 | AMCB Readings | Unknown Operations | 0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | LTCMechanism | AB-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 69 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | ST000456 | Structure | 417-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0674 | BreakerVacuum | ML-1289 | VCB Readings | Switching Operations | 0 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Interruptrs/Puffrs Visual OK? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | General Comments | | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | ST000440 | Structure | 586-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Switching Operations | 2 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Operations This Read Vac | 2 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Operations Counter AL | 227 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Operations Counter AF | 227 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | General Comments | | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0289 | BreakerVacuum | 404-0774 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Patrol Inspection | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Operations Counter AF | 417 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Operations Counter AL | 417 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Operations This Read AM | 4 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Switching Operations | 4 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Amps B Ø | 225 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Amps C Ø | 255 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | FE000833 | Fence | 507-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Operations Counter AF | 165 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Operations Counter AL | 165 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BAT001376 | Battery | 586-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BAT001376 | Battery | 586-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 52 | °F |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BAT001376 | Battery | 586-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BAT001376 | Battery | 586-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BAT001376 | Battery | 586-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BAT001376 | Battery | 586-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BAT001376 | Battery | 586-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Counter Readings | LTC Operations Since Last Insp | 208 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Counter Readings | LTC Min Tap Position | 3L | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Counter Readings | LTC Current Tap Position | 1R | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Counter Readings | LTC As Left Counter | 83817 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Counter Readings | LTC As Found Counter | 83817 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Counter Readings | General Comments | ok | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | LTCMechanism | ML-TRANS 3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BAT001376 | Battery | 586-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BAT001376 | Battery | 586-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BAT001376 | Battery | 586-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.3 | VDC |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BAT001376 | Battery | 586-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BAT001376 | Battery | 586-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BAT001376 | Battery | 586-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | 9 Month Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Amps A Ø | 225 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | 9 Month Ops New | 1 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | 9 Months Operations | 5 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Amps A Ø | 156.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Amps B Ø | 167.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Amps C Ø | 173.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0668 | BreakerAirMagnetic | ML-1283 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Unknown Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | 9 Month Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Amps A Ø | 0.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Amps B Ø | 0.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Amps C Ø | 0.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Operations Counter AF | 156 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Operations Counter AL | 156 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Operations This Read Vac | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB1293 | BreakerVacuum | ML-1288 | VCB Readings | Switching Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Operations Counter AF | 325 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Operations Counter AL | 325 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Operations This Read Vac | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Switching Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | LTCMechanism | 586-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | 9 Month Operations | 2 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Amps A Ø | 34.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Amps B Ø | 47.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Amps C Ø | 36.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0534 | BreakerVacuum | KE-1161 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Switching Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BK000707 | BreakerVacuum | 549-2 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | 9 Month Operations | 2 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Amps A Ø | 314.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Amps B Ø | 301.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Amps C Ø | 291.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Amps C Ø | 0.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Amps B Ø | 0.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Amps A Ø | 0.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0533 | BreakerVacuum | KE-1160 | VCB Readings | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Patrol Inspection | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Operations Counter AF | 687 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Operations Counter AL | 687 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Operations This Read AM | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Switching Operations | 0 | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Fault Operations B Ø | 2 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Fault Operations A Ø | 2 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Fault Adjusted Amps B Phase AM | 22.36 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Fault Adjusted Amps A Phase AM | 22.36 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Amps C Ø | 390.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Amps B Ø | 330.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Amps A Ø | 310.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | 9 Months Operations | 4 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Counter Readings | General Comments | | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Switching Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | 9 Months Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Amps A Ø | 400.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Amps B Ø | 400.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Amps C Ø | 350.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Operations Counter | 28 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0061 | BreakerAirMagnetic | AB-12KV TR 1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Counter Readings | LTC As Found Counter | 183139 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Amps A Ø | 84.0 | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Amps B Ø | 85.0 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BCH001299 | Charger | 586-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BCH001299 | Charger | 586-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BCH001299 | Charger | 586-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BCH001299 | Charger | 586-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.0 | amps |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BCH001299 | Charger | 586-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BCH001299 | Charger | 586-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BCH001299 | Charger | 586-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BCH001299 | Charger | 586-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | 9 Month Operations VCB New | 23 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0051 | BreakerVacuum | 417-2132 | VCB Readings | 9 Month Operations | 26 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Unknown Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Switching Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Operations This Read AM | 4 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | General Comments | | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Operations Counter AF | 365 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Operations Counter AL | 365 | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Amps C Ø | 78.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0532 | BreakerVacuum | KE-1159 | VCB Readings | Operations This Read Vac | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Operations Counter AL | 332 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Operations Counter AF | 332 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0052 | BreakerAirMagnetic | AB-1202 | AMCB Readings | 9 Month Ops New | 2 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | General Comments | A and B phase TOC | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Patrol Inspection | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0056 | BreakerAirMagnetic | AB-1206 | AMCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | General Comments | | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | ST000429 | Structure | 742-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Counter Readings | LTC As Left Counter | 115883 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Counter Readings | LTC As Found Counter | 115879 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Counter Readings | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AL | 314 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AF | 314 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Amps A Ø | 100.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Amps B Ø | 130.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Amps C Ø | 108.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Switching Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Operations This Read Vac | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Operations Counter AL | 267 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Operations Counter AF | 267 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Amps C Ø | 56.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Amps B Ø | 57.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Amps A Ø | 55.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0675 | BreakerVacuum | ML-1290 | VCB Readings | 9 Month Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Counter Readings | LTC As Left Counter | 183145 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | FE000382 | Fence | 549-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Counter Readings | LTC Current Tap Position | 10L | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Counter Readings | LTC Min Tap Position | 16L | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | RC000125 | RecloserElectronic | 742-2150 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCC000933 | LTCControl | 507-1 | LTC Control Insp | All Connections OK? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCC000933 | LTCControl | 507-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCC000933 | LTCControl | 507-1 | LTC Control Insp | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCC000933 | LTCControl | 507-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCC000933 | LTCControl | 507-1 | LTC Control Insp | LTC Output Voltage Level | 124 | VAC |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCC000933 | LTCControl | 507-1 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCC000933 | LTCControl | 507-1 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCC000933 | LTCControl | 507-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 1.9 | VDC |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 49.7 | VDC |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BAT000950 | Battery | 417-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Counter Readings | LTC Operations Since Last Insp | 541 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | LTCMechanism | 404-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | 9 Months Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0531 | BreakerAirMagnetic | KE-1158 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0536 | BreakerVacuum | KE-12KV BUS TIE SEC 2 | VCB Readings | Switching Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Counter Readings | LTC Operations Since Last Insp | 591 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | B0464 | LTCMechanism | 549-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Operations Counter AF | 205 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Operations Counter AL | 205 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Operations This Read Vac | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Switching Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Amps C Ø | 165 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Amps B Ø | 155 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Amps A Ø | 125 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Accumulated Fault Duty C Ph V | 3.2 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Accumulated Fault Duty B Ph V | 2.74 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Accumulated Fault Duty A Ph V | 5.03 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | PF000190 | PowerFuse | KE-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | PF000190 | PowerFuse | KE-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | PF000190 | PowerFuse | KE-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | PF000189 | PowerFuse | KE-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | PF000189 | PowerFuse | KE-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | PF000189 | PowerFuse | KE-12KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 91602 | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1216 | Regulator | 742-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Patrol Inspection | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | General Comments | A and B phase IOC | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Operations Counter AF | 985 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Operations Counter AL | 985 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Operations This Read AM | 2 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Switching Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Unknown Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | 9 Month Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Accumulated Fault Duty A Ph V | 1.13 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Accumulated Fault Duty B Ph V | 1.13 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Accumulated Fault Duty C Ph V | 1.13 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Amps A Ø | 255 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Amps B Ø | 265 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Amps C Ø | 240 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0027 | BreakerVacuum | 549-3 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Accumulated Fault Duty A Ph V | .47 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | 9 Month Operations | 2 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Readings | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Readings | LTC Totalizer Reading | 7329.6 | kw |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Readings | Oil Temp Max | 20 | °C |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Readings | Totalizer Meter Reading | .509 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Readings | Winding Temp Max | 25 | °C |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Readings | Winding Temp Present | 25 | °C |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | WithLTC | 507-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Counter Readings | LTC Operations Since Last Insp | 222 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | General Comments | | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | n | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | YD000454 | Yard | 417-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Switching Operations | 2 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Operations This Read Vac | 2 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Operations Counter AL | 263 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | 9 Month Operations | 2 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Operations Counter AF | 261 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Amps C Ø | 90 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Amps B Ø | 125 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0030 | BreakerVacuum | 549-0905 | VCB Readings | Amps A Ø | 115 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 50 | °C |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -1.0 | psi |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | needs nitro | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | PF000192 | PowerFuse | KE-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | PF000192 | PowerFuse | KE-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | PF000192 | PowerFuse | KE-STA SER NO 2 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | PF000191 | PowerFuse | KE-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | PF000191 | PowerFuse | KE-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | PF000191 | PowerFuse | KE-12KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Switching Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Operations Counter AL | 288 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | LTCC000768 | LTCControl | 549-1 | LTC Control Insp | All Connections OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | LTCC000768 | LTCControl | 549-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | LTCC000768 | LTCControl | 549-1 | LTC Control Insp | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | LTCC000768 | LTCControl | 549-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Readings | Totalizer Meter Reading | .8844 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Readings | Winding Temp Max | 45 | °C |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | 9 Month Ops New | 8 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | 9 Months Operations | 8 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Amps A Ø | 240.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Amps B Ø | 230.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Amps C Ø | 260.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Patrol Inspection | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Operations Counter AF | 163 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Operations Counter AL | 163 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Operations This Read AM | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Switching Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0057 | BreakerAirMagnetic | AB-1207 | AMCB Readings | Unknown Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 40 | °C |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 50 | °C |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 38 | °C |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 66 | °C |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0014 | WithLTC | AB-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 42 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Amps C Ø | 0.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Amps B Ø | 0.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Amps A Ø | 0.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | 9 Months Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Switching Operations | 2 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Operations This Read Vac | 2 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | 9 Month Ops New | 4 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | 9 Months Operations | 6 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Amps A Ø | 75.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Amps B Ø | 75.0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Operations Counter AL | 90502 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Operations Counter AF | 90500 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Readings | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0055 | BreakerVacuum | 549-0873 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Amps C Ø | 50.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Fault Adjusted Amps A Phase AM | 11.18 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Fault Adjusted Amps B Phase AM | 11.18 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Fault Operations A Ø | 1 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Fault Operations B Ø | 1 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0053 | BreakerAirMagnetic | AB-1203 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | LTCC000768 | LTCControl | 549-1 | LTC Control Insp | LTC Output Voltage Level | 125 | VAC |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | LTCC000768 | LTCControl | 549-1 | LTC Control Insp | VRR Base Voltage AF | 125 | VAC |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | LTCC000768 | LTCControl | 549-1 | LTC Control Insp | VRR Base Voltage AL | 125 | VAC |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | LTCC000768 | LTCControl | 549-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Operations Counter AF | 288 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Amps C Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Amps B Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Amps A Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | K0059 | BreakerVacuum | 549-BT1-2 | VCB Readings | 9 Month Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | BCH000023 | Charger | KE-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | BCH000023 | Charger | KE-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | BCH000023 | Charger | KE-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | BCH000023 | Charger | KE-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 8.9 | amps |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | BCH000023 | Charger | KE-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | BCH000023 | Charger | KE-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | BCH000023 | Charger | KE-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | BCH000023 | Charger | KE-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Unknown Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Switching Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Operations This Read AM | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Operations Counter AL | 4 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Operations Counter AF | 4 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0060 | BreakerAirMagnetic | AB-12KV BUS TIE SEC 2 | AMCB Readings | General Comments | Open | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Restroom Clean & OK? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | CH000154 | ControlHouse | KE-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Present | 27 | °C |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Max | 27 | °C |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Present | 20 | °C |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Max | 35 | °C |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Present | 14 | °C |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Max | 14 | °C |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 65.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | General Comments | | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Operations Counter AF | 459 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Operations Counter AL | 459 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Operations This Read Vac | 7 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Switching Operations | 7 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | PF000028 | PowerFuse | AB-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | PF000028 | PowerFuse | AB-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | FE000623 | Fence | AB-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Readings | Switching Operations | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | SF6 Pressure Indicator | good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000035 | Switchgear | KE-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Ambient Temperature | 55 | °F |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | 9 Month Operations | 19 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Amps A Ø | 51.0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Amps B Ø | 38.0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Amps C Ø | 41.0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Fault Adjusted Amps A Phase V | 4.69 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Fault Adjusted Amps B Phase V | 4.69 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Fault Operations A Ø | 1 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Fault Operations B Ø | 1 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 55 | °F |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | Oil Temp Present | 15 | °C |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1000 | psi |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | H2 Winding Temp Present | 12 | °C |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | H2 Winding Temp Max | 30 | °C |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0134 | WithLTC | ML-TRANS 3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Readings | Operations This Read SF6 | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Readings | Operations Counter AL | 72 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Readings | Operations Counter AF | 72 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | General Comments | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Readings | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Readings | Fault Operations | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000795 | BreakerSF6 | 507-618 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | General Comments | | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Readings | Totalizer Meter Reading | .8328 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Readings | Winding Temp Max | 60 | °C |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Readings | Winding Temp Present | 25 | °C |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | LTCC000915 | LTCControl | 549-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | LTCC000915 | LTCControl | 549-2 | LTC Control Insp | VRR Base Voltage AL | 125 | VAC |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | LTCC000915 | LTCControl | 549-2 | LTC Control Insp | VRR Base Voltage AF | 125 | VAC |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | LTCC000915 | LTCControl | 549-2 | LTC Control Insp | LTC Output Voltage Level | 126 | VAC |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | LTCC000915 | LTCControl | 549-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | LTCC000915 | LTCControl | 549-2 | LTC Control Insp | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | LTCC000915 | LTCControl | 549-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | LTCC000915 | LTCControl | 549-2 | LTC Control Insp | All Connections OK? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | 9 Month Operations | 32 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | 9 Month Operations VCB New | 25 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Amps A Ø | 134.0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Amps B Ø | 162.0 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Switching Operations | 1 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Operations This Read Vac | 1 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Operations Counter AL | 173 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Operations Counter AF | 172 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | General Comments | | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Counter Readings | LTC As Left Counter | 23953 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Counter Readings | LTC As Found Counter | 23953 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Counter Readings | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LTCM000039 | LTCMechanism | ML-TRANS 6 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | BAT001016 | Battery | KE-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | BAT001016 | Battery | KE-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | BAT001016 | Battery | KE-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | BAT001016 | Battery | KE-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | BAT001016 | Battery | KE-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | BAT001016 | Battery | KE-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | BAT001016 | Battery | KE-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | BAT001016 | Battery | KE-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | BAT001016 | Battery | KE-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | BAT001016 | Battery | KE-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | BAT001016 | Battery | KE-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | BAT001016 | Battery | KE-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Readings | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Readings | LTC Totalizer Reading | 11992.32 | kw |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0 | psi |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | WithLTC | 549-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | YD000461 | Yard | 404-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | 9 Month Operations | 1 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Amps C Ø | 138.0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | PF000030 | PowerFuse | AB-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | PF000030 | PowerFuse | AB-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | PF000029 | PowerFuse | AB-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | PF000029 | PowerFuse | AB-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | YD000625 | Yard | AB-Yard | Yard Patrol Inspection | Ambient Temp | 38 | °F |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | K0025 | BreakerVacuum | 417-2134 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | ST000609 | Structure | AB-Structure | Structure Patrol Inspection | General Comments | | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Amps C Ø | 95.0 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Amps B Ø | 89.0 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Amps A Ø | 84.0 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000391 | BreakerVacuum | 586-2127 | VCB Readings | 9 Month Operations | 1 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Switching Operations | 1 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Operations This Read Vac | 1 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Operations Counter AL | 181 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Operations Counter AF | 180 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | General Comments | | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Amps C Ø | 112.0 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Amps B Ø | 110.0 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Amps A Ø | 113.0 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | BK000390 | BreakerVacuum | 586-2126 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | 9 Month Operations | 4 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Accumulated Fault Duty A Ph V | 4.39 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Accumulated Fault Duty B Ph V | 5.37 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Accumulated Fault Duty C Ph V | 4.88 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Amps A Ø | 20 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Amps B Ø | 20 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Amps C Ø | 20 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Operations Counter AF | 401 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Operations Counter AL | 405 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Operations This Read Vac | 4 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Switching Operations | 4 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0460 | BreakerVacuum | 549-0150 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Switching Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Counter Readings | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 117170 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 117170 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 1R | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 748 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | PF000031 | PowerFuse | AB-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | PF000031 | PowerFuse | AB-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0101 | LTCMechanism | KE-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | LTCC000662 | LTCControl | 549-3 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | LTCC000662 | LTCControl | 549-3 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | LTCC000662 | LTCControl | 549-3 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | LTCC000662 | LTCControl | 549-3 | LTC Control Insp | LTC Output Voltage Level | 124 | VAC |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | LTCC000662 | LTCControl | 549-3 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | LTCC000662 | LTCControl | 549-3 | LTC Control Insp | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | LTCC000662 | LTCControl | 549-3 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | LTCC000662 | LTCControl | 549-3 | LTC Control Insp | All Connections OK? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 204398 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 204398 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | PF000251 | PowerFuse | ML-12KV TR 6 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | PF000251 | PowerFuse | ML-12KV TR 6 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | PF000251 | PowerFuse | ML-12KV TR 6 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 245 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | LTCMechanism | KE-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Amps C Ø | 94.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Amps B Ø | 87.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Amps A Ø | 82.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 25 | °C |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 30 | °C |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 25 | °C |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Switching Operations | 2 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Operations This Read Vac | 2 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Operations Counter AL | 263 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Operations Counter AF | 261 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Patrol Inspection | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Operations Counter AF | 586 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Operations Counter AL | 586 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Operations This Read AM | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Switching Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Unknown Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | ST000423 | Structure | 627-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Amps A Ø | 45.0 | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Amps B Ø | 40.0 | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Amps C Ø | 41.0 | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Operations Counter | 66 | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0148 | RecloserElectronic | 627-2152 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Switching Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Operations This Read AM | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Operations Counter AL | 51 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Operations Counter AF | 51 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Patrol Inspection | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | 9 Months Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Amps A Ø | 339.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Amps B Ø | 321.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Amps C Ø | 349.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0538 | BreakerAirMagnetic | KE-12KV TR 1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Amps A Ø | 56.0 | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Amps B Ø | 36.0 | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Amps C Ø | 34.0 | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | 9 Month Operations | 10 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Accumulated Fault Duty A Ph V | 6.83 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Accumulated Fault Duty B Ph V | 4.39 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Accumulated Fault Duty C Ph V | 7.81 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Amps A Ø | 50 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Amps B Ø | 75 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Amps C Ø | 75 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Fault Adjusted Amps A Phase V | 13.1 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Fault Adjusted Amps B Phase V | 13.1 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Fault Adjusted Amps C Phase V | 13.1 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Operations Counter AF | 408 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Operations Counter AL | 414 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Operations This Read Vac | 6 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Switching Operations | 4 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0459 | BreakerVacuum | 549-0151 | VCB Readings | Unknown Operations | 2 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Unknown Operations | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | YD000343 | Yard | 507-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | ST000346 | Structure | 507-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LTCC000226 | LTCControl | AB-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LTCC000226 | LTCControl | AB-TRANS 2 | LTC Control Insp | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LTCC000226 | LTCControl | AB-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | FE000828 | Fence | 586-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Unknown Operations | 0 | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Operations Counter | 80 | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | 9 Month Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Amps A Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Amps B Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Amps C Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Operations Counter AF | 240 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Operations Counter AL | 240 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0028 | BreakerVacuum | 549-BT3-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Switching Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Operations This Read AM | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Operations Counter AL | 6 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Operations Counter AF | 6 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | General Comments | DNO | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Patrol Inspection | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Amps C Ø | 0.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Amps B Ø | 0.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Amps A Ø | 0.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | 9 Months Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Amps A Ø | 146.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Amps B Ø | 122.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Amps C Ø | 151.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | 9 Months Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0058 | BreakerAirMagnetic | AB-1208 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | KX0147 | RecloserElectronic | 627-2151 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Patrol Inspection | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Operations Counter AF | 999 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Operations Counter AL | 999 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Operations This Read AM | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0529 | BreakerAirMagnetic | KE-1156 | AMCB Readings | Switching Operations | 0 | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | General Comments | | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Counter Readings | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Counter Readings | LTC As Found Counter | 65308 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Counter Readings | LTC As Left Counter | 65311 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | 9 Months Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Amps A Ø | 24.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Amps B Ø | 18.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Amps C Ø | 21.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Counter Readings | LTC Operations Since Last Insp | 446 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | S0028 | LTCMechanism | 549-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Switching Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Operations This Read Vac | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Operations Counter AL | 390 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Operations Counter AF | 390 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Unknown Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Switching Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Accumulated Fault Duty B Ph V | 3.74 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Accumulated Fault Duty A Ph V | 1.87 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | 9 Month Operations | 2 | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | ST000390 | Structure | 549-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | YD000387 | Yard | 549-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 32 | °C |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 40 | °C |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 32 | °C |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 42 | °C |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 32 | °C |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 40 | °C |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Readings | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Readings | LTC Totalizer Reading | 12735.36 | kw |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 700 | psi |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LT0015 | WithLTC | AB-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Operations This Read AM | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Patrol Inspection | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Operations Counter AF | 724 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Operations Counter AL | 724 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Operations This Read AM | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Switching Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0530 | BreakerAirMagnetic | KE-1157 | AMCB Readings | Unknown Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Operations Counter AL | 67 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Operations Counter AF | 67 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Patrol Inspection | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Amps C Ø | 0.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Amps B Ø | 0.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Amps A Ø | 0.0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | 9 Months Operations | 0 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LB0051 | BreakerAirMagnetic | AB-1201 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Amps C Ø | 692.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Amps B Ø | 690.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Amps A Ø | 705.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0678 | BreakerVacuum | ML-12KV TR 3 | VCB Readings | 9 Month Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KT0030 | WithLTC | 549-3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | PF000252 | PowerFuse | ML-STA SER NO 4 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | PF000252 | PowerFuse | ML-STA SER NO 4 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | PF000252 | PowerFuse | ML-STA SER NO 4 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Amps B Ø | 0.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Amps C Ø | 0.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | PF000250 | PowerFuse | ML-12KV TR 3 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | PF000250 | PowerFuse | ML-12KV TR 3 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | PF000250 | PowerFuse | ML-12KV TR 3 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | PF000249 | PowerFuse | ML-STA SER NO 6 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | PF000249 | PowerFuse | ML-STA SER NO 6 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | General Comments | | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | FE000418 | Fence | 627-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | 9 Months Operations | 2 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0666 | BreakerAirMagnetic | ML-1281 | AMCB Readings | 9 Month Ops New | 2 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Operations Counter AF | 355 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Operations Counter AL | 355 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Operations This Read Vac | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Switching Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | 9 Months Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Amps C Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Amps B Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Amps A Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | Accumulated Fault Duty A Ph V | .93 | % |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Counter Readings | LTC Operations Since Last Insp | 625 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Counter Readings | LTC Min Tap Position | 16L | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Counter Readings | LTC As Left Counter | 14615 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Counter Readings | LTC As Found Counter | 14611 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Counter Readings | General Comments | | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | LTCMechanism | 417-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0031 | BreakerVacuum | 549-0875 | VCB Readings | 9 Month Operations | 2 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 40 | °C |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 20 | °C |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 40 | °C |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | 9 Month Operations | 2 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0676 | BreakerVacuum | ML-12KV BUS TIE SEC 3 | VCB Readings | Amps A Ø | 0.0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Amps A Ø | 651.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Amps B Ø | 638.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Amps C Ø | 627.0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Operations Counter AF | 132 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Operations Counter AL | 132 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Amps C Ø | 155 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Amps B Ø | 145 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Amps A Ø | 140 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Accumulated Fault Duty C Ph V | .47 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Amps A Ø | 147.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Amps B Ø | 138.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Amps C Ø | 128.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Operations Counter AF | 620 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Operations Counter AL | 620 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Operations This Read AM | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0667 | BreakerAirMagnetic | ML-1282 | AMCB Readings | Switching Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | PF000249 | PowerFuse | ML-STA SER NO 6 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | PF000248 | PowerFuse | ML-STA SER NO 3 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | PF000248 | PowerFuse | ML-STA SER NO 3 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | PF000248 | PowerFuse | ML-STA SER NO 3 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LT0102 | WithLTC | KE-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | LTCC000678 | LTCControl | 417-1 | LTC Control Insp | All Connections OK? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | LTCC000678 | LTCControl | 417-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | LTCC000678 | LTCControl | 417-1 | LTC Control Insp | General Comments | | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | LTCC000678 | LTCControl | 417-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | LTCC000678 | LTCControl | 417-1 | LTC Control Insp | LTC Output Voltage Level | 124.3 | VAC |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | LTCC000678 | LTCControl | 417-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | LTCC000678 | LTCControl | 417-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | LTCC000678 | LTCControl | 417-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Switching Operations | 2 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Operations This Read Vac | 2 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Operations Counter AL | 261 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Readings | Operations Counter AF | 259 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | KB0029 | BreakerVacuum | 549-0874 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | 9 Month Operations | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | LB0539 | BreakerVacuum | KE-12KV TR 2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Patrol Inspection | Fault Adjusted Amps A Phase V | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0 | psi |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.1 | VDC |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 50 | °C |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 20 | °C |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Counter Readings | LTC Operations Since Last Insp | 449 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.3 | VDC |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 45 | °F |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3273.60 | kw |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCC000753 | LTCControl | 507-2 | LTC Control Insp | All Connections OK? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Amps C Ø | 75 | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Readings | General Comments | | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Amps B Ø | 65 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Amps A Ø | 70 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Accumulated Fault Duty C Ph V | .41 | % |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCC000753 | LTCControl | 507-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCC000753 | LTCControl | 507-2 | LTC Control Insp | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCC000753 | LTCControl | 507-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Accumulated Fault Duty B Ph V | .41 | % |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Accumulated Fault Duty A Ph V | .41 | % |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | 9 Month Operations | 4 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BCH000468 | Charger | 417-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BCH000468 | Charger | 417-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BCH000468 | Charger | 417-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BCH000468 | Charger | 417-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.5 | amps |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BCH000468 | Charger | 417-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BCH000468 | Charger | 417-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BCH000468 | Charger | 417-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 2357.28 | kw |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Readings | Oil Temp Max | 22 | °C |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Readings | Oil Temp Present | 22 | °C |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Amps C Ø | 205 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Amps B Ø | 185 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Amps A Ø | 170 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Accumulated Fault Duty C Ph V | .87 | % |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Accumulated Fault Duty B Ph V | .87 | % |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Accumulated Fault Duty A Ph V | .44 | % |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | 9 Month Operations | 2 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | BCH001329 | Charger | 404-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | BCH001329 | Charger | 404-Battery Charger | Battery Charger Patrol Insp | General Comments | Temperature alarm present.P6 and E08 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | BCH001329 | Charger | 404-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | BCH001329 | Charger | 404-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | BCH001329 | Charger | 404-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .8 | amps |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Readings | Totalizer Meter Reading | .307 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | BCH001329 | Charger | 404-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Switching Operations | 2 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Operations This Read Vac | 2 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | BCH001329 | Charger | 404-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | BCH001329 | Charger | 404-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Operations Counter AL | 192 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Operations Counter AF | 190 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | BAT001410 | Battery | 404-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Readings | Winding Temp Present | 20 | °C |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Counter Readings | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Counter Readings | LTC As Found Counter | 13320 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Counter Readings | LTC As Left Counter | 13324 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCM000074 | LTCMechanism | 507-2 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | PT000854 | PT | ML-12KV TR 3 POT | PT Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | PT000854 | PT | ML-12KV TR 3 POT | PT Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000783 | BreakerVacuum | 507-0020 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Switchgear Lighting OK? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | General Comments | 2 lights are completely out. This switchgear needs six 8 foot led bulbs installed. | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Follow-up Action Required? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Amps C Ø | 0.0 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Switching Operations | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Operations Counter AL | 152 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Amps B Ø | 0.0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Ambient Temperature | 55 | °F |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Readings | Fault Operations | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Operations Counter AF | 152 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Readings | Totalizer Meter Reading | .8670 | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .6820 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | General Comments | | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Readings | Winding Temp Max | 42 | °C |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Readings | Winding Temp Present | 26 | °C |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | SWG000021 | Switchgear | AB-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | ST000464 | Structure | 404-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCC000753 | LTCControl | 507-2 | LTC Control Insp | LTC Output Voltage Level | 124 | VAC |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCC000753 | LTCControl | 507-2 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCC000753 | LTCControl | 507-2 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | LTCC000753 | LTCControl | 507-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Switching Operations | 3 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Operations This Read Vac | 3 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Operations Counter AL | 185 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Operations Counter AF | 185 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | General Comments | | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | 9 Month Ops New | 2 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | 9 Months Operations | 2 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Switching Operations | 2 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Operations This Read Vac | 2 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Operations Counter AL | 156 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | 9 Month Operations | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Operations Counter AF | 154 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | 9 Month Operations | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | 9 Month Operations VCB New | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Amps A Ø | 175 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Amps C Ø | 85 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Amps B Ø | 85 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Amps A Ø | 110 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Amps B Ø | 150 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Amps C Ø | 150 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Amps C Ø | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Amps B Ø | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Amps A Ø | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Operations Counter AF | 186 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Operations Counter AL | 186 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Switching Operations | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Readings | General Comments | | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | S0066 | NonLTC | 742-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Counter Readings | LTC Operations Since Last Insp | 380 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000788 | BreakerVacuum | 507-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Counter Readings | LTC As Left Counter | 62557 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Counter Readings | LTC As Found Counter | 62550 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | 9 Month Operations | 4 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | PT000854 | PT | ML-12KV TR 3 POT | PT Patrol Inspection | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | PT000854 | PT | ML-12KV TR 3 POT | PT Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Counter Readings | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | S0011 | LTCMechanism | 507-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Switching Operations | 2 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Operations This Read Vac | 2 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Operations Counter AL | 202 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Operations Counter AF | 200 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000784 | BreakerVacuum | 507-0864 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BCH001189 | Charger | 507-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0 | millivolts |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BCH001189 | Charger | 507-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133 | VDC |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BCH001189 | Charger | 507-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133 | VDC |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BCH001189 | Charger | 507-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.3 | amps |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BCH001189 | Charger | 507-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BCH001189 | Charger | 507-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BCH001189 | Charger | 507-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BCH001189 | Charger | 507-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000114 | Switchgear | ML-Swgr Sec 3 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Platform/Walkway/Railing OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | ST000628 | Structure | KE-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | FE000643 | Fence | KE-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Readings | General Comments | | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Readings | LTC Totalizer Reading | 6019.20 | kw |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Readings | Oil Temp Max | 62 | °C |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Readings | Oil Temp Present | 33 | °C |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Operations Counter AF | 160 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Operations Counter AL | 160 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Readings | Totalizer Meter Reading | .6270 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Switching Operations | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000789 | BreakerVacuum | 507-2 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Readings | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Readings | LTC Totalizer Reading | 4420.8 | kw |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 500 | psi |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | TX000192 | WithLTC | 507-2 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000785 | BreakerVacuum | 507-0865 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | PT000854 | PT | ML-12KV TR 3 POT | PT Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | PT000854 | PT | ML-12KV TR 3 POT | PT Patrol Inspection | Tank Oil Level | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | PT000854 | PT | ML-12KV TR 3 POT | PT Patrol Inspection | PT Free of Leaks? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | PT000854 | PT | ML-12KV TR 3 POT | PT Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Operations Counter AF | 198 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Switching Operations | 4 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Operations This Read Vac | 1 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Operations Counter AL | 40 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Operations Counter AF | 40 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | General Comments | | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Readings | Operations This Read SF6 | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | SF6 Pressure Indicator | good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Readings | Switching Operations | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Amps A Ø | 0.0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000534 | BreakerVacuum | 417-2135 | VCB Readings | 9 Month Operations | 10 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Operations This Read Vac | 4 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Operations Counter AL | 473 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Operations Counter AF | 469 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Amps A Ø | 235.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Amps B Ø | 217.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Amps C Ø | 204.0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Operations Counter AF | 416 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Operations Counter AL | 416 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Operations This Read Vac | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | Switching Operations | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | 9 Month Operations | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Switching Operations | 2 | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .9822 | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LTCC000401 | LTCControl | AB-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LTCC000401 | LTCControl | AB-TRANS 1 | LTC Control Insp | General Comments | | |
| 1/25/2023 11:36 | Distribution | Ashby Quarterly Inspection | LTCC000401 | LTCControl | AB-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 77441 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Unknown Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Patrol Inspection | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Operations Counter AF | 318 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Operations Counter AL | 318 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Operations This Read AM | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Switching Operations | 0 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Switching Operations | 1 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Operations This Read Vac | 2 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Operations Counter AL | 200 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Amps C Ø | 311.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Readings | X1 Winding Temp Max | 53 | °C |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Readings | X1 Winding Temp Present | 33 | °C |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Amps B Ø | 327.0 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Amps A Ø | 319.0 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BCH001173 | Charger | 549-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Readings | X2 Winding Temp Max | 60 | °C |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Readings | X2 Winding Temp Present | 34 | °C |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Readings | X3 Winding Temp Max | 55 | °C |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Readings | X3 Winding Temp Present | 35 | °C |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Accumulated Fault Duty B Ph V | 2.93 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BCH001173 | Charger | 549-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BCH001173 | Charger | 549-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BCH001173 | Charger | 549-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BCH001173 | Charger | 549-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 5.2 | amps |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BCH001173 | Charger | 549-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53 | VDC |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Accumulated Fault Duty A Ph V | 2.93 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | 9 Month Operations | 2 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Amps A Ø | 85 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Amps B Ø | 75 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | 9 Month Operations | 4 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Amps C Ø | 75 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | 9 Month Ops New | 1 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | 9 Months Operations | 1 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BCH001173 | Charger | 549-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53 | VDC |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BCH001173 | Charger | 549-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0 | millivolts |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Switching Operations | 9 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Operations This Read Vac | 11 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Operations Counter AL | 215 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Operations Counter AF | 215 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Readings | Maintenance Operations | 0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Amps A Ø | 203.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Amps B Ø | 193.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Amps C Ø | 192.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0669 | BreakerAirMagnetic | ML-1284 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | BK000533 | BreakerVacuum | 417-2133 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0 | VDC |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0 | VDC |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BAT001224 | Battery | 549-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:04 | Distribution | Kenwood Quarterly Inspection | SWG000173 | Switchgear | KE-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Readings | General Comments | | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Readings | Oil Temp Present | 31 | °C |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LT0133 | WithLTC | ML-TRANS 6 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0959 | Regulator | 627-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | 9 Month Operations | 2 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000786 | BreakerVacuum | 507-0882 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Amps C Ø | 200 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Amps B Ø | 200 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Amps A Ø | 200 | |
| 1/25/2023 14:48 | Distribution | Bryant Road Quarterly Inspection | BB0461 | BreakerVacuum | 549-0149 | VCB Readings | Accumulated Fault Duty C Ph V | 3.42 | % |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | CB0288 | BreakerVacuum | 404-0773 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 213287 | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Patrol Inspection | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Amps C Ø | 195 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Amps B Ø | 200 | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Min Tap Position | 13L | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Max Tap Position | 1L | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | General Comments | Lower drag hand would not reset. | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Readings | General Comments | | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Readings | LTC Totalizer Reading | 1781.76 | kw |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Readings | Oil Temp Max | 48 | °C |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Readings | Follow-up Action Required? | n | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Readings | Oil Temp Present | 32 | °C |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Readings | Oil Temp Max | 51 | °C |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Amps A Ø | 138.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Amps B Ø | 120.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Amps C Ø | 128.0 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/25/2023 15:10 | Distribution | Harrodsburg North Quarterly Inspection | O0218 | WithLTC | 404-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 34748 | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/25/2023 8:51 | Distribution | Salvisa Quarterly Inspection | R1523 | Regulator | 742-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | R0960 | Regulator | 627-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0670 | BreakerAirMagnetic | ML-1285 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Foundation Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Readings | General Comments | | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | General Comments | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Readings | Oil Temp Max | 48 | °C |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/25/2023 11:01 | Distribution | Shakertown Quarterly Inspection | C0367 | NonLTC | 627-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Readings | LTC Totalizer Reading | 8323.20 | kw |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Readings | Operations Counter AL | 67 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Readings | Operations Counter AF | 67 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | LB0672 | BreakerVacuum | ML-1287 | VCB Readings | 9 Month Operations | 0 | |
| 1/25/2023 14:17 | Distribution | Harrodsburg Industrial Quarterly Inspection | O0229 | WithLTC | 417-1 | LTC Transformer Readings | General Comments | | |
| 1/25/2023 10:36 | Distribution | Mud Lane Quarterly Inspection | SWG000172 | Switchgear | ML-Swgr Sec 6 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/25/2023 11:52 | Distribution | Harrodsburg City Quarterly Inspection | C0422 | WithLTC | 586-1 | LTC Transformer Readings | Totalizer Meter Reading | .5568 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000787 | BreakerVacuum | 507-1 | VCB Readings | Amps A Ø | 175 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/25/2023 15:16 | Distribution | West Hickman Quarterly Inspection | BK000794 | BreakerSF6 | 507-608 | GCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCC000725 | LTCControl | 930-Offline-Distribution | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCC000725 | LTCControl | 930-Offline-Distribution | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCC000725 | LTCControl | 930-Offline-Distribution | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCC000725 | LTCControl | 930-Offline-Distribution | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCC000725 | LTCControl | 930-Offline-Distribution | LTC Control Insp | LTC Operation Checked? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCC000725 | LTCControl | 930-Offline-Distribution | LTC Control Insp | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCC000725 | LTCControl | 930-Offline-Distribution | LTC Control Insp | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCC000725 | LTCControl | 930-Offline-Distribution | LTC Control Insp | All Connections OK? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Switching Operations | 3 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Operations This Read Vac | 3 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AL | 8 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AF | 5 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Amps C Ø | 120.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Amps B Ø | 120.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Amps A Ø | 120.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations | 7 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0356 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations | 6 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Amps A Ø | 0.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Amps B Ø | 0.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Amps C Ø | 0.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Maintenance Operations | 2 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AF | 852 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AL | 854 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Operations This Read Vac | 2 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Switching Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0355 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations | 11 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Amps C Ø | 240.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AF | 445 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AL | 448 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Operations This Read Vac | 3 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Switching Operations | 3 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations VCB New | 8 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Amps A Ø | 240.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Amps B Ø | 240.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0354 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Amps C Ø | 100.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Maintenance Operations | 3 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AF | 990 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Amps B Ø | 60.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Amps A Ø | 60.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AL | 997 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Switching Operations | 4 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations | 11 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | Operations This Read Vac | 7 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Readings | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0353 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AF | 265 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Operations Counter AL | 265 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Operations This Read Vac | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Switching Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Amps C Ø | 600.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Amps B Ø | 550.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Readings | Amps A Ø | 550.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BB0348 | BreakerVacuum | Retired Distribution | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCC000818 | LTCControl | 930-Offline-Distribution | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCC000818 | LTCControl | 930-Offline-Distribution | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCC000818 | LTCControl | 930-Offline-Distribution | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCC000818 | LTCControl | 930-Offline-Distribution | LTC Control Insp | LTC Output Voltage Level | 126.0 | VAC |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCC000818 | LTCControl | 930-Offline-Distribution | LTC Control Insp | LTC Operation Checked? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCC000818 | LTCControl | 930-Offline-Distribution | LTC Control Insp | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCC000818 | LTCControl | 930-Offline-Distribution | LTC Control Insp | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCC000818 | LTCControl | 930-Offline-Distribution | LTC Control Insp | All Connections OK? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Amps C Ø | 300.0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Amps B Ø | 275.0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | 9 Month Operations | 1 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Amps A Ø | 99.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Amps B Ø | 109.0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Fault Adjusted Amps C Phase V | 268.33 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Fault Adjusted Amps B Phase V | 268.33 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Amps A Ø | 265.0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | 9 Month Operations | 2 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Fault Adjusted Amps A Phase V | 268.33 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Amps C Ø | 84.0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Amps B Ø | 87.0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Amps A Ø | 84.0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | 9 Month Operations | 31 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Amps A Ø | 310.0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Amps B Ø | 248.0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Amps C Ø | 201.0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Operations This Read Vac | 2 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Switching Operations | 5 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Amps B Ø | 290.0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Amps A Ø | 300.0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Operations Counter AL | 179 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Operations Counter AF | 177 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Unknown Operations | 24 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Switching Operations | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Operations This Read Vac | 24 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Operations Counter AL | 110 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Operations Counter AF | 110 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Patrol Inspection | General Comments | ok | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | General Comments | | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0546 | BreakerVacuum | LO-1192 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | 9 Month Operations VCB New | 17 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | 9 Month Operations | 17 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Patrol Inspection | General Comments | ok | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Amps C Ø | 130.0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Counter Readings | LTC Operations Since Last Insp | 266 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Switching Operations | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Operations This Read Vac | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Operations Counter AL | 674 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | General Comments | | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Switching Operations | 2 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Switching Operations | 2 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Operations This Read Vac | 8 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Operations Counter AL | 256 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0547 | BreakerVacuum | LO-1193 | VCB Readings | Operations Counter AF | 674 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Amps C Ø | 290.0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Operations Counter AF | 254 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Operations Counter AF | 165 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Operations Counter AL | 165 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Operations This Read Vac | 5 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Maintenance Operations | 6 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001422 | BreakerVacuum | 710-0124 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Counter Readings | LTC As Left Counter | 14863 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 10.0 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 31 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 34 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | General Comments | | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | CH000353 | ControlHouse | 658-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | CH000352 | ControlHouse | 617-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Counter Readings | LTC Operations Since Last Insp | 461 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | General Comments | | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Counter Readings | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Counter Readings | LTC As Found Counter | 130509 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Counter Readings | LTC As Left Counter | 130509 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 33 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 10.0 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0086 | RecloserHydraulic | 122-2158 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 10.0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | LTCC000390 | LTCControl | 710-1 | LTC Control Insp | All Connections OK? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | LTCC000390 | LTCControl | 710-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | LTCC000390 | LTCControl | 710-1 | LTC Control Insp | General Comments | | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | LTCC000390 | LTCControl | 710-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | LTCC000390 | LTCControl | 710-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | LTCC000390 | LTCControl | 710-1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | LTCC000390 | LTCControl | 710-1 | LTC Control Insp | VRR Base Voltage AF | 123.0 | VAC |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | LTCC000390 | LTCControl | 710-1 | LTC Control Insp | VRR Base Voltage AL | 123.0 | VAC |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | LTCC000390 | LTCControl | 710-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Counter Readings | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Counter Readings | LTC As Found Counter | 14863 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000358 | ControlHouse | 853-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Readings | General Comments | | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Counter Readings | General Comments | | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 26738 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 26738 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 16R | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 55 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LTCM000041 | LTCMechanism | LO-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | General Comments | | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | MOD Cabinet Heater functional? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | MOD Cabinet Internals Clean? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | MOD Motor Jaw Coupling | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LTCC000473 | LTCControl | AS-TRANS 4 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LTCC000473 | LTCControl | AS-TRANS 4 | LTC Control Insp | General Comments | | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LTCC000473 | LTCControl | AS-TRANS 4 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | LTCMechanism | 617-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | General Comments | | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | FE000351 | Fence | 658-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | ST000360 | Structure | 658-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Counter Readings | LTC Max Tap Position | 16R | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Counter Readings | LTC Operations Since Last Insp | 520 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | LTCMechanism | 617-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | FE000824 | Fence | 617-Yard | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Counter Readings | LTC Operations Since Last Insp | 169 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Counter Readings | LTC Current Tap Position | 6 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Counter Readings | LTC As Left Counter | 60136 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Counter Readings | LTC As Found Counter | 60136 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Counter Readings | General Comments | | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | LTCMechanism | AS-TRANS 4 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Readings | Totalizer Meter Reading | .7110 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 6000 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Readings | LTC Totalizer Reading | 4266.00 | kw |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | WithLTC | 710-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Reg Output Voltage Level | 122.0 | volts |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Regulator As Left Counter | 32182 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Operations Counter AF | 172 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Operations Counter AL | 172 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Operations This Read Vac | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Switching Operations | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LTCC000419 | LTCControl | AS-TRANS 3 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LTCC000419 | LTCControl | AS-TRANS 3 | LTC Control Insp | General Comments | | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LTCC000419 | LTCControl | AS-TRANS 3 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Counter Readings | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Counter Readings | LTC As Found Counter | 27866 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Counter Readings | LTC As Left Counter | 27866 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Counter Readings | LTC Max Tap Position | 5R | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 37 | °C |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 14 | °C |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Counter Readings | LTC Operations Since Last Insp | 695 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | LTCM000065 | LTCMechanism | 853-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Counter Readings | LTC Operations Since Last Insp | 239 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Counter Readings | LTC Min Tap Position | 6L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Counter Readings | LTC As Left Counter | 40291 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Counter Readings | LTC As Found Counter | 40291 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Counter Readings | General Comments | | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | LTCMechanism | 658-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Amps C Ø | 0.0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Amps B Ø | 0.0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Amps A Ø | 0.0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001256 | BreakerVacuum | 617-BT2-1 | VCB Readings | 9 Month Operations | 5 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Readings | General Comments | | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB1311 | BreakerVacuum | AS-14KV TR 4 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Current Tap Position | 10L | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | General Comments | | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Min Tap Position | 16L | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0009 | Regulator | 710-2 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Regulator As Left Counter | 48390 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | General Comments | | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1257 | Regulator | 122-5 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Regulator As Left Counter | 49238 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | General Comments | | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1256 | Regulator | 122-5 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Regulator As Left Counter | 51442 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | R1255 | Regulator | 122-5 A | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Counter Readings | LTC As Left Counter | 53911 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Counter Readings | LTC As Found Counter | 53911 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Counter Readings | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | LTCMechanism | 853-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Readings | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Readings | LTC Totalizer Reading | 16866.00 | kw |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -2.0 | psi |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BCH000873 | Charger | 658-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BCH000873 | Charger | 658-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BCH000873 | Charger | 658-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BCH000873 | Charger | 658-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.0 | amps |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BCH000873 | Charger | 658-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 132.0 | VDC |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BCH000873 | Charger | 658-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 132.0 | VDC |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BCH000873 | Charger | 658-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Readings | Oil Temp Present | 55 | °C |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BAT001051 | Battery | 658-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Readings | Totalizer Meter Reading | .9370 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Readings | Winding Temp Max | 65 | °C |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | B0445 | WithLTC | 853-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Counter Readings | General Comments | | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Counter Readings | LTC As Found Counter | 1149 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Counter Readings | LTC As Left Counter | 1149 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | B0287 | LTCMechanism | 710-1 | LTC Counter Readings | LTC Operations Since Last Insp | 52 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | General Comments | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Readings | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Readings | Fault Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Ambient Temperature | 35 | °F |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BCH001564 | Charger | 617-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BCH001564 | Charger | 617-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BCH001564 | Charger | 617-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BCH001564 | Charger | 617-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BCH001564 | Charger | 617-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 4.6 | amps |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BCH001564 | Charger | 617-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BCH001564 | Charger | 617-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BCH001564 | Charger | 617-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Readings | LTC Totalizer Reading | 12297.60 | kw |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Readings | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 299 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 10.0 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 10.0 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 10.0 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 300 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 177 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0728 | RecloserHydraulic | 122-2160 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | LTCC000762 | LTCControl | 617-1 | LTC Control Insp | All Connections OK? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | LTCC000762 | LTCControl | 617-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | LTCC000762 | LTCControl | 617-1 | LTC Control Insp | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | LTCC000762 | LTCControl | 617-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | LTCC000762 | LTCControl | 617-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | LTCC000762 | LTCControl | 617-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | LTCC000762 | LTCControl | 617-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | LTCC000762 | LTCControl | 617-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BCH001042 | Charger | 710-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Ambient Temp | 30 | °F |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | General Comments | | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Max Tap Position | 1L | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Min Tap Position | 16L | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Reg Output Voltage Level | 122.0 | volts |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Regulator As Left Counter | 35515 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | General Comments | | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | YD000588 | Yard | LO-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Readings | Switching Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | SF6 Pressure Indicator | good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Readings | Operations This Read SF6 | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Readings | Operations Counter AL | 52 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Readings | Operations Counter AF | 52 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000631 | BreakerSF6 | 853-608 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | General Comments | | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | ST000584 | Structure | LO-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 100.00 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Readings | Totalizer Meter Reading | .6832 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0370 | WithLTC | 617-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Counter Readings | LTC Operations Since Last Insp | 90 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Counter Readings | LTC Min Tap Position | 12 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Counter Readings | LTC Max Tap Position | 27 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Counter Readings | LTC Current Tap Position | 20 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Counter Readings | LTC As Left Counter | 17195 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Counter Readings | LTC As Found Counter | 17195 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Mechanism Patrol Inspection | General Comments | Added Oil to Tap Changer.  Alarm was in. | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Counter Readings | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Readings | Oil Temp Present | 28 | °C |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | LTCMechanism | AS-TRANS 3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 95.00 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Readings | General Comments | | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0079 | NonLTC | 122-5 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Readings | Oil Temp Present | 28 | °C |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | BCH001596 | Charger | LO-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 95.00 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Readings | General Comments | | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | BCH001596 | Charger | LO-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.7 | VDC |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | BCH001596 | Charger | LO-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.7 | VDC |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | BCH001596 | Charger | LO-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.5 | amps |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0077 | NonLTC | 122-5 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BCH001042 | Charger | 710-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BCH001042 | Charger | 710-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BCH001042 | Charger | 710-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BCH001042 | Charger | 710-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 3.5 | amps |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BCH001042 | Charger | 710-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BCH001042 | Charger | 710-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BCH001042 | Charger | 710-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Switching Operations | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Operations This Read Vac | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Operations Counter AL | 291 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Operations Counter AF | 291 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Ambient Temperature | 35 | °F |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Readings | Fault Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Readings | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | General Comments | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Readings | Operations Counter AF | 71 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Readings | Operations Counter AL | 71 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Readings | Operations This Read SF6 | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | SF6 Pressure Indicator | good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Readings | Switching Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000663 | BreakerSF6 | 853-618 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002075 | BreakerVacuum | 617-618 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Switching Operations | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Operations This Read Vac | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Operations Counter AL | 363 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Operations Counter AF | 363 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Amps A Ø | 240.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Amps B Ø | 270.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Amps C Ø | 260.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Current Tap Position | 12L | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Fault Adjusted Amps A Phase V | 12.37 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Fault Adjusted Amps B Phase V | 12.37 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Fault Adjusted Amps C Phase V | 12.37 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Fault Operations A Ø | 1 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Fault Operations B Ø | 1 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Fault Operations C Ø | 1 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 30 | °C |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Counter Readings | LTC Operations Since Last Insp | 435 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Operations Counter AF | 200 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Operations Counter AL | 201 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Operations This Read Vac | 3 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Switching Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | 9 Month Operations | 4 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Amps A Ø | 80.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Amps B Ø | 80.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Amps C Ø | 90.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Current Tap Position | 9L | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0008 | Regulator | 710-2 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | 9 Month Operations | 1 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Regulator As Left Counter | 27184 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Reg Output Voltage Level | 122.0 | volts |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Min Tap Position | 16L | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Max Tap Position | 7L | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | General Comments | | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KR0007 | Regulator | 710-2 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Amps A Ø | 415.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Amps B Ø | 470.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Amps C Ø | 445.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Readings | Totalizer Meter Reading | .1277 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Counter Readings | General Comments | | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Counter Readings | LTC As Found Counter | 25707 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Counter Readings | LTC As Left Counter | 25707 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | LTCMechanism | 710-3 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 40 | °C |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Operations Counter AF | 171 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Operations Counter AL | 171 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Switching Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000640 | BreakerVacuum | 853-2 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | 9 Month Operations | 7 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000641 | BreakerVacuum | 853-0132 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Readings | LTC Totalizer Reading | 1838.88 | kw |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Operations Counter AF | 226 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Operations Counter AL | 228 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Operations This Read Vac | 2 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Switching Operations | 2 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0658 | RecloserHydraulic | 122-2159 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 10.0 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0658 | RecloserHydraulic | 122-2159 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 10.0 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0658 | RecloserHydraulic | 122-2159 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 10.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0658 | RecloserHydraulic | 122-2159 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0658 | RecloserHydraulic | 122-2159 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0658 | RecloserHydraulic | 122-2159 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0658 | RecloserHydraulic | 122-2159 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0658 | RecloserHydraulic | 122-2159 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0658 | RecloserHydraulic | 122-2159 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0658 | RecloserHydraulic | 122-2159 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0658 | RecloserHydraulic | 122-2159 | Recloser Hydraulic Patrol Inspection | Operations Counter | 166 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0658 | RecloserHydraulic | 122-2159 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | CX0658 | RecloserHydraulic | 122-2159 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Readings | General Comments | | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 40 | °F |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BAT001174 | Battery | 710-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | General Comments | | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | FE000583 | Fence | LO-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Operations Counter AF | 202 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Operations Counter AL | 204 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Operations This Read Vac | 2 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Switching Operations | 2 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000646 | BreakerVacuum | 853-0152 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | 9 Month Operations | 4 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Amps A Ø | 180.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Amps B Ø | 195.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Amps C Ø | 185.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Switching Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Operations Counter AL | 198 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Operations Counter AF | 198 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000647 | BreakerVacuum | 853-0195 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BK000639 | BreakerVacuum | 853-BT1-2 | VCB Readings | 9 Month Operations | 0 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | B0361 | WithLTC | 658-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Amps C Ø | 562.0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Amps B Ø | 567.0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Amps A Ø | 627.0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | 9 Month Operations | 9 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | General Comments | | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0240 | GroundTransformer | AS-GND TR 3 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | 9 Month Operations | 12 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000248 | BreakerVacuum | 617-0103 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | General Comments | | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Restroom Clean & OK? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | CH000156 | ControlHouse | LO-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BAT001122 | Battery | 617-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | BAT000887 | Battery | LO-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | BAT000887 | Battery | LO-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | BAT000887 | Battery | LO-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | BAT000887 | Battery | LO-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | BAT000887 | Battery | LO-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | BAT000887 | Battery | LO-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | BAT000887 | Battery | LO-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | BAT000887 | Battery | LO-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | BAT000887 | Battery | LO-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Switching Operations | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Operations This Read Vac | 9 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Operations Counter AL | 225 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Operations Counter AF | 225 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Maintenance Operations | 9 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Gas Accumulation Gauge | Normal | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | General Comments | | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | H2 Winding Temp Max | 65 | °C |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | H2 Winding Temp Present | 40 | °C |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | Oil Temp Max | 65 | °C |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | Oil Temp Present | 37 | °C |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 100.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Max | 65 | °C |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Present | 40 | °C |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | Y2 Winding Temp Max | 65 | °C |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | Y2 Winding Temp Present | 40 | °C |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Patrol Inspection | General Comments | ok | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | General Comments | | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Amps C Ø | 0.0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Amps B Ø | 0.0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Amps A Ø | 0.0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Readings | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Readings | LTC Totalizer Reading | 13032.00 | kw |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1200 | psi |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Readings | Oil Temp Max | 41 | °C |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Readings | Oil Temp Present | 26 | °C |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Readings | Totalizer Meter Reading | .5430 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Readings | Winding Temp Max | 42 | °C |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Readings | Winding Temp Present | 27 | °C |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | 9 Month Operations | 0 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | General Comments | | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Operations Counter AF | 319 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Operations Counter AL | 321 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Operations This Read Vac | 2 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Switching Operations | 2 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | BAT000887 | Battery | LO-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | BAT000887 | Battery | LO-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Readings | Winding Temp Present | 15 | °C |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Readings | Winding Temp Max | 30 | °C |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | SWG000037 | Switchgear | LO-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | BAT000887 | Battery | LO-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Readings | Totalizer Meter Reading | .8570 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 4113.60 | kw |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Readings | General Comments | | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | 9 Month Operations | 2 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0006 | NonLTC | 710-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Amps A Ø | 0.0 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Amps B Ø | 0.0 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Readings | Amps C Ø | 0.0 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0468 | BreakerVacuum | 658-0836 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Switching Operations | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Operations This Read Vac | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Operations Counter AL | 1167 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Operations Counter AF | 1167 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0548 | BreakerVacuum | LO-1194 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | TX000132 | WithLTC | 853-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | 9 Month Operations VCB New | 23 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | 9 Month Operations | 26 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Switching Operations | 17 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Operations This Read Vac | 17 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Operations Counter AL | 660 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Readings | General Comments | | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | General Comments | LTC Pump Filter needs keeps tripping out. Service light is on. It is a filamx filter. | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Readings | Percent Thermal Load X2 Max | 60 | % |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Readings | Percent Thermal Load Y2 Max | 50 | % |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0012 | WithLTC | AS-TRANS 4 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Operations Counter AF | 660 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | General Comments | | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Amps C Ø | 60.0 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Readings | Oil Temp Present | 28 | °C |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Readings | Oil Temp Max | 28 | °C |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | BCH001596 | Charger | LO-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | BCH001596 | Charger | LO-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | BCH001596 | Charger | LO-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | BCH001596 | Charger | LO-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Switching Operations | 3 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Operations This Read Vac | 3 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Operations Counter AL | 153 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Operations Counter AF | 153 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | General Comments | | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 35 | °C |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 55 | °C |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 35 | °C |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 45 | °C |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 35 | °C |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 40 | °C |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | PF001291 | PowerFuse | AS-14KV BUS SEC 3 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | PF001291 | PowerFuse | AS-14KV BUS SEC 3 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | PF001291 | PowerFuse | AS-14KV BUS SEC 3 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 15 | °C |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 20 | °C |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK002074 | BreakerVacuum | 617-608 | VCB Readings | 9 Month Operations | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LT0104 | WithLTC | LO-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | LB1358 | BreakerVacuum | 122-3427 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Switching Operations | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Operations This Read Vac | 6 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Operations Counter AL | 203 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Operations Counter AF | 203 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Maintenance Operations | 6 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | LTCC000300 | LTCControl | 710-3 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | LTCC000300 | LTCControl | 710-3 | LTC Control Insp | VRR Base Voltage AL | 123.0 | VAC |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | LTCC000300 | LTCControl | 710-3 | LTC Control Insp | VRR Base Voltage AF | 123.0 | VAC |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | LTCC000300 | LTCControl | 710-3 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | LTCC000300 | LTCControl | 710-3 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | LTCC000300 | LTCControl | 710-3 | LTC Control Insp | General Comments | | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | LTCC000300 | LTCControl | 710-3 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | LTCC000300 | LTCControl | 710-3 | LTC Control Insp | All Connections OK? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Amps C Ø | 431.0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Amps B Ø | 428.0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Amps A Ø | 494.0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | 9 Month Operations | 6 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BAT001217 | Battery | 853-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BCH001161 | Charger | 853-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | LTCC000775 | LTCControl | 617-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | LTCC000775 | LTCControl | 617-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | LTCC000775 | LTCControl | 617-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | LTCC000775 | LTCControl | 617-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | LTCC000775 | LTCControl | 617-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | LTCC000775 | LTCControl | 617-2 | LTC Control Insp | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | LTCC000775 | LTCControl | 617-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | LTCC000775 | LTCControl | 617-2 | LTC Control Insp | All Connections OK? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000732 | BreakerVacuum | 617-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BCH001161 | Charger | 853-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.0 | VDC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BCH001161 | Charger | 853-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.0 | VDC |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BCH001161 | Charger | 853-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.9 | amps |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BCH001161 | Charger | 853-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | BCH001161 | Charger | 853-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0013 | WithLTC | AS-TRANS 3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | 9 Month Operations | 22 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | ST000349 | Structure | 853-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Amps B Ø | 60.0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Amps A Ø | 60.0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 95.00 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Readings | General Comments | | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | General Comments | | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LT0241 | GroundTransformer | AS-GND TR 4 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | C0078 | NonLTC | 122-5 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0042 | BreakerVacuum | AS-1417 | VCB Readings | 9 Month Operations | 17 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Unknown Operations | 22 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Operations This Read Vac | 22 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Operations Counter AL | 245 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Operations Counter AF | 245 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | General Comments | ok | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 594.00 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 594.00 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 594.00 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Amps C Ø | 498.0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Amps B Ø | 449.0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Amps A Ø | 470.0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0550 | BreakerVacuum | LO-12KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | CH000430 | ControlHouse | 853-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK000500 | BreakerVacuum | 617-1 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | PF000022 | PowerFuse | AS-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | PF000022 | PowerFuse | AS-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Maintenance Operations | 7 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Operations Counter AF | 186 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Amps B Ø | 0.0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Amps C Ø | 0.0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Operations Counter AL | 188 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Operations This Read Vac | 9 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Switching Operations | 2 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | PF000022 | PowerFuse | AS-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | YD000341 | Yard | 617-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | YD000341 | Yard | 617-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | 9 Month Operations | 18 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Switching Operations | 15 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Operations This Read Vac | 15 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Operations Counter AL | 87 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | YD000341 | Yard | 617-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | YD000341 | Yard | 617-Yard | Yard Patrol Inspection | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | YD000341 | Yard | 617-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | YD000341 | Yard | 617-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | YD000341 | Yard | 617-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | YD000341 | Yard | 617-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | YD000341 | Yard | 617-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | YD000341 | Yard | 617-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | YD000341 | Yard | 617-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Operations Counter AF | 87 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | 9 Month Operations | 28 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | 9 Month Operations | 2 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Amps A Ø | 0.0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Operations Counter AL | 161 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Operations This Read Vac | 2 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Switching Operations | 2 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Amps A Ø | 168.0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Amps B Ø | 147.0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Amps C Ø | 167.0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Fault Adjusted Amps A Phase V | 268.33 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Follow-up Action Required? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | General Comments | CHAINLINK FENCE FRONT RIGHT CORNER AT GATE | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | FE000342 | Fence | 853-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | General Comments | | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | y | |
| 1/24/2023 13:04 | Distribution | Lakeshore Quarterly Inspection | YD000346 | Yard | 853-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Switching Operations | 19 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Fault Adjusted Amps B Phase V | 268.33 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Fault Adjusted Amps C Phase V | 268.33 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Amps C Ø | 0.0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Amps C Ø | 0.0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Amps B Ø | 0.0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Amps A Ø | 0.0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | 9 Month Operations | 15 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Amps B Ø | 0.0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Amps A Ø | 0.0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Switching Operations | 2 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | General Comments | ok | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Operations Counter AF | 8 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Operations Counter AL | 8 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Operations This Read Vac | 24 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Switching Operations | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0544 | BreakerVacuum | LO-1190 | VCB Readings | Unknown Operations | 24 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Operations This Read Vac | 12 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Operations Counter AL | 341 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Operations Counter AF | 339 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | 9 Month Operations | 21 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Amps A Ø | 0.0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Amps B Ø | 0.0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Amps C Ø | 0.0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Readings | Winding Temp Present | 20 | °C |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | General Comments | | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | YD000341 | Yard | 617-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | YD000341 | Yard | 617-Yard | Yard Patrol Inspection | Ambient Temp | 40 | °F |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | General Comments | | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001046 | BreakerVacuum | AS-1421 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Operations Counter AF | 385 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Operations Counter AL | 354 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Readings | Operations This Read Vac | 19 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001523 | BreakerVacuum | AS-14KV BUS TIE SEC 3 & 4 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | General Comments | | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Operations Counter AF | 382 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Operations Counter AL | 382 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Operations This Read Vac | 29 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Switching Operations | 29 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | General Comments | | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Operations Counter AF | 267 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Operations Counter AL | 267 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | PF000196 | PowerFuse | LO-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | PF000196 | PowerFuse | LO-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | PF000196 | PowerFuse | LO-12KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | PF000195 | PowerFuse | LO-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | PF000195 | PowerFuse | LO-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Readings | General Comments | | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Switching Operations | 2 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | PF000195 | PowerFuse | LO-STA SER NO 2 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Operations This Read Vac | 2 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Operations Counter AL | 225 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Operations Counter AF | 223 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Amps A Ø | 85.0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Amps B Ø | 100.0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Amps C Ø | 80.0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Readings | Winding Temp Max | 60 | °C |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Readings | LTC Totalizer Reading | 80.00 | kw |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | PF000024 | PowerFuse | AS-GND TR 3 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | General Comments | | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | FE000410 | Fence | 710-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Readings | Totalizer Meter Reading | .5750 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | 9 Month Operations | 31 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Amps A Ø | 130.0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Amps B Ø | 150.0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001517 | BreakerVacuum | AS-1416 | VCB Readings | Amps C Ø | 170.0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Fault Operations Ground | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | General Comments | | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Switching Operations | 0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Amps C Ø | 81.0 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Amps B Ø | 75.0 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Amps A Ø | 71.0 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | General Comments | | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Operations Counter AF | 159 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | 9 Month Operations | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | 9 Month Operations | 15 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Amps A Ø | 329.0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Amps B Ø | 318.0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Amps C Ø | 386.0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | 9 Month Operations | 4 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | BK001580 | BreakerVacuum | 617-0140 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | BB0390 | BreakerVacuum | 658-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | General Comments | | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Operations Counter AF | 354 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Operations Counter AL | 354 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Operations This Read Vac | 20 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Switching Operations | 20 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | ST000344 | Structure | 617-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Amps C Ø | 120.0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Amps B Ø | 120.0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | Amps A Ø | 120.0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Readings | LTC Totalizer Reading | 10350.00 | kw |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Readings | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | BK001595 | BreakerVacuum | 710-0043 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | PF000026 | PowerFuse | AS-14KV TR 4 POT | Disconnect Powerfuse Inspection | General Comments | oik | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | General Comments | | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Operations Counter AF | 262 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Operations Counter AL | 362 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Operations This Read Vac | 19 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Switching Operations | 19 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | PF000027 | PowerFuse | AS-STA SER NO 4 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | PF000027 | PowerFuse | AS-STA SER NO 4 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Switching Operations | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | PF000027 | PowerFuse | AS-STA SER NO 4 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Operations This Read Vac | 0 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Operations Counter AL | 255 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Operations Counter AF | 255 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Patrol Inspection | General Comments | ok | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | General Comments | | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | General Comments | | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Operations Counter AF | 172 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Operations Counter AL | 172 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Operations This Read Vac | 13 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Switching Operations | 13 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | 9 Month Operations | 13 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Amps A Ø | 0.0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Amps B Ø | 0.0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Amps C Ø | 0.0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0050 | BreakerVacuum | AS-GND TR 4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Operations Counter AL | 258 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Operations This Read Vac | 2 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Switching Operations | 2 | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | General Comments | | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Fault Adjusted Amps C Phase V | 201.25 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | PF000024 | PowerFuse | AS-GND TR 3 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | PF000024 | PowerFuse | AS-GND TR 3 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | n | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Fault Adjusted Amps B Phase V | 201.25 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Fault Adjusted Amps A Phase V | 201.25 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | LTCC000910 | LTCControl | 658-1 | LTC Control Insp | All Connections OK? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | LTCC000910 | LTCControl | 658-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | LTCC000910 | LTCControl | 658-1 | LTC Control Insp | General Comments | | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | LTCC000910 | LTCControl | 658-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | LTCC000910 | LTCControl | 658-1 | LTC Control Insp | LTC Output Voltage Level | 122.0 | VAC |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | LTCC000910 | LTCControl | 658-1 | LTC Control Insp | VRR Base Voltage AF | 122.0 | VAC |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | LTCC000910 | LTCControl | 658-1 | LTC Control Insp | VRR Base Voltage AL | 122.0 | VAC |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | LTCC000910 | LTCControl | 658-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Amps C Ø | 117.0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Amps B Ø | 116.0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Amps A Ø | 120.0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | General Comments | | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Readings | Winding Temp Max | 30 | °C |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Readings | Totalizer Meter Reading | .0100 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KT0020 | WithLTC | 710-3 | LTC Transformer Readings | Totalizer Meter Multiplier | 8000 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | 9 Month Operations | 14 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | General Comments | | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Amps A Ø | 39.0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Amps B Ø | 41.0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Amps C Ø | 45.0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | General Comments | | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | ST000416 | Structure | 710-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/24/2023 15:07 | Distribution | IBM North Quarterly Inspection | YD000357 | Yard | 658-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | General Comments | | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 245.00 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 250.00 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Readings | General Comments | | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Maintenance Operations | 16 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Operations Counter AF | 316 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Operations Counter AL | 318 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Operations This Read Vac | 18 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Switching Operations | 2 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Unknown Operations | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | SWG000004 | Switchgear | AS-Swgr Sec 4 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | General Comments | | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0026 | BreakerVacuum | 710-0524 | VCB Readings | 9 Month Operations | 2 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Amps C Ø | 389.0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | General Comments | | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Patrol Inspection | General Comments | ok | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Unknown Operations | 18 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Operations Counter AF | 405 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Operations Counter AL | 405 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Switching Operations | 0 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Readings | Top Oil Temperature Present | 26 | °C |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Readings | Top Oil Temperature Max | 40 | °C |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Operations This Read Vac | 18 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Amps B Ø | 396.0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Amps A Ø | 456.0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | General Comments | | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/24/2023 14:59 | Distribution | West Cliff Quarterly Inspection | T0108 | NonLTC | 122-6 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001522 | BreakerVacuum | AS-14KV TR 3 | VCB Readings | 9 Month Operations | 20 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Amps C Ø | 230.0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Amps B Ø | 230.0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Amps A Ø | 240.0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | 9 Month Operations | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | 9 Month Operations | 20 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Readings | Maintenance Operations | 10 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0154 | BreakerVacuum | 617-0057 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Amps C Ø | 25.0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Amps B Ø | 25.0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Amps A Ø | 25.0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | Ambient Temp | 40 | °F |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | YD000414 | Yard | 710-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Operations Counter AF | 256 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | BK001518 | BreakerVacuum | AS-1419 | VCB Readings | 9 Month Operations | 20 | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 7:57 | Distribution | Locust Quarterly Inspection | LB0545 | BreakerVacuum | LO-1191 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | K0181 | BreakerVacuum | 617-0110 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Fault Operations Ground | 0 | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | PF000026 | PowerFuse | AS-14KV TR 4 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/24/2023 13:32 | Distribution | Kentucky River Quarterly Inspection | KB0025 | BreakerVacuum | 710-BT3-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | PF000026 | PowerFuse | AS-14KV TR 4 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | PF000025 | PowerFuse | AS-14KV TR 3 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | PF000025 | PowerFuse | AS-14KV TR 3 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | LB0045 | BreakerVacuum | AS-1418 | VCB Readings | Follow-up Action Required? | n | |
| 1/24/2023 15:00 | Distribution | IBM Quarterly Inspection | B0358 | WithLTC | 617-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/24/2023 12:10 | Distribution | Ashbottom Quarterly Inspection | PF000025 | PowerFuse | AS-14KV TR 3 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BCH001104 | Charger | 930-Offline-Distribution | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BCH001104 | Charger | 930-Offline-Distribution | Battery Charger Patrol Insp | General Comments | | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BCH001104 | Charger | 930-Offline-Distribution | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BCH001104 | Charger | 930-Offline-Distribution | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BCH001104 | Charger | 930-Offline-Distribution | Battery Charger Patrol Insp | Battery Charger Current | 2.0 | amps |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BCH001104 | Charger | 930-Offline-Distribution | Battery Charger Patrol Insp | As Left Float Voltage | 133.0 | VDC |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BCH001104 | Charger | 930-Offline-Distribution | Battery Charger Patrol Insp | As Found Float Voltage | 133.0 | VDC |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | General Comments | | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Operations Counter AF | 175 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Operations Counter AL | 175 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Counter Readings | LTC Current Tap Position | 12L | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Counter Readings | LTC As Left Counter | 69894 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Counter Readings | LTC As Found Counter | 69894 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | General Comments | | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Counter Readings | LTC Operations Since Last Insp | 2 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Counter Readings | LTC Max Tap Position | 12L | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Amps C Ø | 210.0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Amps B Ø | 185.0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 37 | °F |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | General Comments | | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Counter Readings | General Comments | | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | LTCMechanism | 659-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0171 | BreakerVacuum | 846-0064 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | LTCC000854 | LTCControl | 532-1 | LTC Control Insp | All Connections OK? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | LTCC000854 | LTCControl | 532-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | LTCC000854 | LTCControl | 532-1 | LTC Control Insp | General Comments | | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | LTCC000854 | LTCControl | 532-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | LTCC000854 | LTCControl | 532-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Amps A Ø | 205.0 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Max Tap Position | 4L | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | LTCC000854 | LTCControl | 532-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 10224 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.1 | volts |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Switching Operations | 0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Operations Counter AL | 174 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Operations Counter AF | 174 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Amps A Ø | 0.0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Amps B Ø | 0.0 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | General Comments | | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Switching Operations | 2 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Amps C Ø | 0.0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Amps A Ø | 370.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Amps B Ø | 451.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Amps C Ø | 437.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Operations This Read Vac | 1 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Operations Counter AL | 254 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Operations Counter AF | 253 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Counter Readings | General Comments | | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Counter Readings | LTC As Found Counter | 92471 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Counter Readings | LTC Operations Since Last Insp | 450 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Counter Readings | LTC As Left Counter | 92471 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | LTCMechanism | 812-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | 9 Month Operations VCB New | 17 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000989 | BreakerVacuum | 812-1 | VCB Readings | 9 Month Operations | 17 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | LTCC000110 | LTCControl | 607-2 | LTC Control Insp | All Connections OK? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | LTCC000110 | LTCControl | 607-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | LTCC000110 | LTCControl | 607-2 | LTC Control Insp | General Comments | | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | LTCC000110 | LTCControl | 607-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | LTCC000110 | LTCControl | 607-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | LTCC000110 | LTCControl | 607-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCC000743 | LTCControl | 846-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BAT001153 | Battery | 532-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | LTCC000110 | LTCControl | 607-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | LTCC000110 | LTCControl | 607-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 6000 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 120.0 | volts |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Operations Counter AF | 508 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Operations Counter AL | 510 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Operations This Read Vac | 2 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Switching Operations | 2 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCC000743 | LTCControl | 846-1 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCC000743 | LTCControl | 846-1 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCC000743 | LTCControl | 846-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 120.0 | volts |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 53745 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1044 | Regulator | 607-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1045 | Regulator | 607-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCC000743 | LTCControl | 846-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCC000743 | LTCControl | 846-1 | LTC Control Insp | General Comments | | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | 9 Month Operations | 3 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCC000743 | LTCControl | 846-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCC000743 | LTCControl | 846-1 | LTC Control Insp | All Connections OK? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | 9 Month Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | General Comments | | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | General Comments | | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | General Comments | | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | YD000352 | Yard | 532-Yard | Yard Patrol Inspection | Ambient Temp | 36 | °F |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | General Comments | | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | FE000348 | Fence | 532-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Counter Readings | LTC Operations Since Last Insp | 406 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Counter Readings | LTC As Left Counter | 147090 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Counter Readings | LTC As Found Counter | 147088 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | General Comments | | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Counter Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | LTCMechanism | 860-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Amps C Ø | 150.0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Amps B Ø | 178.0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Amps A Ø | 160.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | 9 Month Operations | 4 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | General Comments | | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | ST000536 | Structure | 860-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | General Comments | | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | YD000532 | Yard | 860-Yard | Yard Patrol Inspection | Ambient Temp | 37 | °F |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | 9 Month Operations | 20 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | 9 Month Operations VCB New | 20 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Amps A Ø | 205.0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Amps B Ø | 185.0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Amps C Ø | 210.0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Readings | General Comments | | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Readings | LTC Totalizer Reading | 3568.00 | kw |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 8000 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Readings | Totalizer Meter Reading | .4460 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 119.0 | volts |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 59885 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | R1043 | Regulator | 607-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Switching Operations | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | General Comments | | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Operations Counter AF | 396 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Operations Counter AL | 396 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Operations Counter AF | 250 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Operations Counter AL | 250 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Operations This Read Vac | 0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Switching Operations | 0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BK000705 | BreakerVacuum | 812-0182 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Switching Operations | 8 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Operations This Read Vac | 8 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Operations Counter AL | 99962 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Operations Counter AF | 99958 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | General Comments | | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Amps C Ø | 120.0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Amps B Ø | 120.0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Amps A Ø | 120.0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0162 | BreakerVacuum | 860-2131 | VCB Readings | 9 Month Operations | 12 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | WithLTC | 847-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | FE000813 | Fence | 847-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BK000706 | BreakerVacuum | 846-0083 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | FE000527 | Fence | 860-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | YD000342 | Yard | 847-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | YD000342 | Yard | 847-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | YD000342 | Yard | 847-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 8989 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.2 | volts |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | MOD Motor Jaw Coupling | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | MOD Cabinet Internals Clean? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | MOD Cabinet Heater functional? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | General Comments | | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | YD000342 | Yard | 847-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | YD000342 | Yard | 847-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | YD000342 | Yard | 847-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | YD000342 | Yard | 847-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | YD000342 | Yard | 847-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | YD000342 | Yard | 847-Yard | Yard Patrol Inspection | General Comments | | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | YD000342 | Yard | 847-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | ST000356 | Structure | 532-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | YD000342 | Yard | 847-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | YD000342 | Yard | 847-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | LTCC000834 | LTCControl | 812-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | LTCC000834 | LTCControl | 812-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | LTCC000834 | LTCControl | 812-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | LTCC000834 | LTCControl | 812-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | LTCC000834 | LTCControl | 812-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | LTCC000834 | LTCControl | 812-1 | LTC Control Insp | General Comments | | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | LTCC000834 | LTCControl | 812-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | LTCC000834 | LTCControl | 812-1 | LTC Control Insp | All Connections OK? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BAT001310 | Battery | 607-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BCH001249 | Charger | 607-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BCH001249 | Charger | 607-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0016 | BreakerVacuum | 846-0074 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BCH001249 | Charger | 607-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BCH001249 | Charger | 607-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.2 | amps |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BCH001249 | Charger | 607-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BCH001249 | Charger | 607-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BCH001249 | Charger | 607-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000072 | Regulator | 860-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 10884 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.4 | volts |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | General Comments | | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | ST000355 | Structure | 607-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000071 | Regulator | 860-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | 9 Month Operations | 6 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | YD000474 | Yard | 659-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | YD000474 | Yard | 659-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | YD000474 | Yard | 659-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | YD000474 | Yard | 659-Yard | Yard Patrol Inspection | General Comments | | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | YD000474 | Yard | 659-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | YD000474 | Yard | 659-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | YD000474 | Yard | 659-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | YD000474 | Yard | 659-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | YD000474 | Yard | 659-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | YD000474 | Yard | 659-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | YD000474 | Yard | 659-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | YD000474 | Yard | 659-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | YD000474 | Yard | 659-Yard | Yard Patrol Inspection | Ambient Temp | 37 | °F |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | LTCC000971 | LTCControl | 860-2 | LTC Control Insp | All Connections OK? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | LTCC000971 | LTCControl | 860-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | LTCC000971 | LTCControl | 860-2 | LTC Control Insp | General Comments | | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | LTCC000971 | LTCControl | 860-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | LTCC000971 | LTCControl | 860-2 | LTC Control Insp | LTC Output Voltage Level | 123.2 | VAC |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | LTCC000971 | LTCControl | 860-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Amps A Ø | 487.0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Amps B Ø | 546.0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Amps C Ø | 519.0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | LTCC000971 | LTCControl | 860-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | LTCC000971 | LTCControl | 860-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Switching Operations | 2 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Operations This Read Vac | 2 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Operations Counter AL | 513 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Operations Counter AF | 511 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | General Comments | | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0446 | BreakerVacuum | 532-0145 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | KB0062 | BreakerVacuum | 846-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | All Connections OK? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | Bat Volt 1Min After Chgr Trip | 49.0 | VDC |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | Battery Area Ambient Temp | 35 | °F |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | General Comments | | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BAT001457 | Battery | 846-Battery Bank Distribution | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | General Comments | | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | ST000476 | Structure | 659-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | General Comments | | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | General Comments | | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | RG000070 | Regulator | 860-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCC000944 | LTCControl | 846-2 | LTC Control Insp | All Connections OK? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCC000944 | LTCControl | 846-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCC000944 | LTCControl | 846-2 | LTC Control Insp | General Comments | | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCC000944 | LTCControl | 846-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCC000944 | LTCControl | 846-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCC000944 | LTCControl | 846-2 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCC000944 | LTCControl | 846-2 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | LTCC000944 | LTCControl | 846-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | 9 Month Operations | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0450 | BreakerVacuum | 532-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | ST000477 | Structure | 812-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Amps C Ø | 86.0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Amps B Ø | 123.0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Amps A Ø | 129.0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0447 | BreakerVacuum | 532-0146 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Operations Counter AL | 173 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Operations Counter AF | 173 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | General Comments | | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Readings | General Comments | | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Amps C Ø | 103.0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Amps B Ø | 195.0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Amps A Ø | 157.0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | General Comments | | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Switching Operations | 2 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Operations This Read Vac | 2 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Operations Counter AL | 604 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Operations Counter AF | 602 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | General Comments | | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | 9 Month Operations | 4 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Switching Operations | 1 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | Operations This Read Vac | 1 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | YD000475 | Yard | 812-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | YD000475 | Yard | 812-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | YD000475 | Yard | 812-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | YD000475 | Yard | 812-Yard | Yard Patrol Inspection | General Comments | | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | YD000475 | Yard | 812-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | YD000475 | Yard | 812-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Amps A Ø | 170.0 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Amps B Ø | 175.0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Counter Readings | LTC As Found Counter | 75058 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Counter Readings | LTC As Left Counter | 75058 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Counter Readings | LTC Operations Since Last Insp | 364 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Amps C Ø | 160.0 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Counter Readings | General Comments | | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Counter Readings | LTC As Found Counter | 265870 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001823 | BreakerVacuum | 860-2129 | VCB Readings | 9 Month Operations | 1 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Amps A Ø | 0.0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Amps B Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Amps C Ø | 0.0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | General Comments | | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Counter Readings | General Comments | | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | LTCMechanism | 532-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | 9 Month Operations | 2 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | YD000475 | Yard | 812-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | YD000475 | Yard | 812-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | YD000475 | Yard | 812-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | YD000475 | Yard | 812-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | YD000475 | Yard | 812-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | YD000475 | Yard | 812-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Amps C Ø | 300.0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Readings | Totalizer Meter Reading | .3130 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Readings | Winding Temp Max | 45 | °C |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BAT001625 | Battery | 812-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BAT001625 | Battery | 812-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BAT001625 | Battery | 812-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BAT001625 | Battery | 812-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BAT001625 | Battery | 812-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BAT001625 | Battery | 812-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BAT001625 | Battery | 812-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BAT001625 | Battery | 812-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BAT001625 | Battery | 812-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BAT001625 | Battery | 812-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BAT001625 | Battery | 812-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BAT001625 | Battery | 812-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 35 | °F |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BAT001625 | Battery | 812-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Readings | Winding Temp Present | 25 | °C |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Readings | Totalizer Meter Reading | 1.2400 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Amps B Ø | 300.0 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Amps A Ø | 350.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | 9 Month Operations | 6 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Counter Readings | General Comments | | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Counter Readings | LTC As Found Counter | 30918 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Counter Readings | LTC As Left Counter | 30918 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | General Comments | CHAIN LINK FENCE TOUCHING OUR BARBED WIRE | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Counter Readings | LTC Operations Since Last Insp | 466 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | B0411 | LTCMechanism | 847-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .9478 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | 9 Month Operations | 6 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Follow-up Action Required? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Readings | LTC Totalizer Reading | 8769.60 | kw |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | YD000470 | Yard | 846-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | Ambient Temp | 37 | °F |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | YD000354 | Yard | 607-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | 9 Month Operations | 4 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Readings | Oil Temp Present | 10 | °C |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | General Comments | CHAINLINK TIED TO BACK CORNERS RAILROAD SIDE OF SUB | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | FE000469 | Fence | 812-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Amps C Ø | 0.0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Amps B Ø | 3.0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Amps A Ø | 4.0 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Readings | Oil Temp Max | 25 | °C |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 35 | °F |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BAT000965 | Battery | 847-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Readings | Totalizer Meter Reading | .6090 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | C0496 | WithLTC | 659-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Readings | LTC Totalizer Reading | 11904.00 | kw |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Readings | General Comments | | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | C0445 | WithLTC | 607-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BCH001545 | Charger | 812-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BCH001545 | Charger | 812-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | 9 Month Operations | 1 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BCH001545 | Charger | 812-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BCH001545 | Charger | 812-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 3.2 | amps |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BCH001545 | Charger | 812-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BCH001545 | Charger | 812-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BCH001545 | Charger | 812-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | BCH001545 | Charger | 812-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | General Comments | | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Amps C Ø | 108.0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Amps B Ø | 102.0 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Amps A Ø | 92.0 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | 9 Month Operations | 2 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Counter Readings | LTC As Found Counter | 69018 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Counter Readings | LTC As Left Counter | 69018 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Counter Readings | LTC Current Tap Position | 2R | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Counter Readings | LTC Operations Since Last Insp | 843 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Amps C Ø | 128.0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Amps B Ø | 118.0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Amps A Ø | 141.0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Operations This Read Vac | 2 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Operations Counter AL | 244 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Operations Counter AF | 242 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BCH001432 | Charger | 846-Battery Charger Distribution | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BCH001432 | Charger | 846-Battery Charger Distribution | Battery Charger Patrol Insp | General Comments | | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | General Comments | | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BCH001432 | Charger | 846-Battery Charger Distribution | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BCH001432 | Charger | 846-Battery Charger Distribution | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BCH001432 | Charger | 846-Battery Charger Distribution | Battery Charger Patrol Insp | Battery Charger Current | 3.8 | amps |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BCH001432 | Charger | 846-Battery Charger Distribution | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BCH001432 | Charger | 846-Battery Charger Distribution | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | BCH001432 | Charger | 846-Battery Charger Distribution | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Operations Counter AF | 198 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Operations Counter AL | 200 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Operations This Read Vac | 2 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Switching Operations | 2 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Operations Counter AF | 211 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Operations Counter AL | 213 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Operations This Read Vac | 2 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Switching Operations | 2 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | General Comments | | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0015 | BreakerVacuum | 846-0939 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0456 | WithLTC | 860-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0126 | BreakerVacuum | 812-0183 | VCB Readings | Switching Operations | 2 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Amps C Ø | 0.0 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | 9 Month Operations | 4 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 65.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Readings | Winding Temp Present | 20 | °C |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Readings | Totalizer Meter Reading | .7240 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Readings | Oil Temp Max | 20 | °C |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Readings | LTC Totalizer Reading | 10425.60 | kw |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Readings | General Comments | | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Counter Readings | LTC As Left Counter | 265870 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Counter Readings | LTC Operations Since Last Insp | 544 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | LTCM000093 | LTCMechanism | 607-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | General Comments | | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Operations Counter AF | 211 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Operations Counter AL | 213 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Operations This Read Vac | 2 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Switching Operations | 2 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000422 | BreakerVacuum | 847-0010 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | 9 Month Operations | 2 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Amps A Ø | 0.0 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BK000423 | BreakerVacuum | 847-0058 | VCB Readings | Amps B Ø | 0.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Readings | Winding Temp Present | 45 | °C |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Readings | Winding Temp Max | 55 | °C |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Readings | Totalizer Meter Reading | .6400 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Readings | LTC Totalizer Reading | 11520.00 | kw |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Readings | General Comments | | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0448 | BreakerVacuum | 532-0147 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Switching Operations | 1 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Operations This Read Vac | 1 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Operations Counter AL | 151 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Operations Counter AF | 151 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | General Comments | | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Amps A Ø | 35.0 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Amps B Ø | 30.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Counter Readings | General Comments | | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | LTCMechanism | 846-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001101 | BreakerVacuum | 607-0143 | VCB Readings | Amps C Ø | 30.0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | General Comments | | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | CH000343 | ControlHouse | 532-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | BK001822 | BreakerVacuum | 860-2128 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 100.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0034 | WithLTC | 846-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 20.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | S0017 | WithLTC | 846-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Amps C Ø | 340.0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Amps B Ø | 347.0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BCH000876 | Charger | 847-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BCH000876 | Charger | 847-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BCH000876 | Charger | 847-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Amps A Ø | 338.0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | General Comments | | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Switching Operations | 2 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Readings | General Comments | | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | 9 Month Operations | 4 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Readings | LTC Totalizer Reading | 4507.20 | kw |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BCH000876 | Charger | 847-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BCH000876 | Charger | 847-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BCH000876 | Charger | 847-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | BCH000876 | Charger | 847-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 3.2 | amps |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Readings | General Comments | | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | General Comments | no oil cup | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3638.40 | kw |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 217.50 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 200.00 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Readings | Oil Temp Max | 100 | °C |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.1370 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | General Comments | | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Operations Counter AF | 202 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Operations Counter AL | 204 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Operations This Read Vac | 2 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Switching Operations | 2 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | FE000416 | Fence | 659-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | LTCC000708 | LTCControl | 659-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | LTCC000708 | LTCControl | 659-1 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | LTCC000708 | LTCControl | 659-1 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | LTCC000708 | LTCControl | 659-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | LTCC000708 | LTCControl | 659-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | LTCC000708 | LTCControl | 659-1 | LTC Control Insp | General Comments | | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | LTCC000708 | LTCControl | 659-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | LTCC000708 | LTCControl | 659-1 | LTC Control Insp | All Connections OK? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Switching Operations | 4 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Operations This Read Vac | 4 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Operations Counter AL | 417 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Operations Counter AF | 413 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | General Comments | | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BCH001127 | Charger | 659-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BCH001127 | Charger | 659-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BCH001127 | Charger | 659-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Switching Operations | 2 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Operations This Read Vac | 2 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Operations Counter AL | 205 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Operations Counter AF | 203 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Operations This Read Vac | 2 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Operations Counter AL | 529 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | B0407 | WithLTC | 812-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | General Comments | | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | General Comments | | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | FE000415 | Fence | 607-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | LTCC000840 | LTCControl | 847-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | LTCC000840 | LTCControl | 847-1 | LTC Control Insp | VRR Base Voltage AL | 123.0 | VAC |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | LTCC000840 | LTCControl | 847-1 | LTC Control Insp | VRR Base Voltage AF | 123.0 | VAC |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | LTCC000840 | LTCControl | 847-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | LTCC000840 | LTCControl | 847-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | LTCC000840 | LTCControl | 847-1 | LTC Control Insp | General Comments | | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | LTCC000840 | LTCControl | 847-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | LTCC000840 | LTCControl | 847-1 | LTC Control Insp | All Connections OK? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0168 | BreakerVacuum | 846-0100 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Switching Operations | 3 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Operations This Read Vac | 3 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Operations Counter AL | 228 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Operations Counter AF | 225 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Amps C Ø | 0.0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Amps B Ø | 8.0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | LTCC000854 | LTCControl | 532-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | LTCC000854 | LTCControl | 532-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Switching Operations | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0020 | BreakerVacuum | 846-1 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | ST000472 | Structure | 846-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Operations This Read Vac | 2 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Operations Counter AL | 192 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Operations Counter AF | 190 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | General Comments | | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | 9 Month Operations | 6 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Amps A Ø | 200.0 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Amps B Ø | 160.0 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Amps C Ø | 160.0 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | General Comments | | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0021 | BreakerVacuum | 846-BT1-2 | VCB Readings | 9 Month Operations | 4 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | C0336 | NonLTC | 860-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Amps A Ø | 31.0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000580 | BreakerVacuum | 659-0094 | VCB Readings | 9 Month Operations | 4 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Switching Operations | 1 | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 13:15 | Distribution | Eastland Quarterly Inspection | KB0124 | BreakerVacuum | 812-0181 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Switching Operations | 2 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Operations This Read Vac | 2 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Operations Counter AL | 185 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Operations Counter AF | 183 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | General Comments | | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Switching Operations | 13 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Operations This Read Vac | 13 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Operations Counter AL | 85 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Operations Counter AF | 81 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000579 | BreakerVacuum | 659-0032 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | BK001100 | BreakerVacuum | 607-0142 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Readings | LTC Totalizer Reading | 16608.00 | kw |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Readings | General Comments | | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | General Comments | | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Unknown Operations | 0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Switching Operations | 2 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Operations This Read Vac | 2 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Operations Counter AL | 183 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Operations Counter AF | 181 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Readings | General Comments | | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1137.36 | kw |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | General Comments | | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000577 | BreakerVacuum | 659-0012 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Amps A Ø | 180.0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Amps B Ø | 120.0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Amps C Ø | 150.0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Fault Operations Ground | 0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 37 | °F |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Amps C Ø | 6.0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Amps B Ø | 5.0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Amps A Ø | 6.0 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | General Comments | | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Operations Counter AF | 527 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Maintenance Operations | 0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | General Comments | | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Readings | 9 Month Operations | 4 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | 9 Month Operations | 15 | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BK000578 | BreakerVacuum | 659-0013 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BAT001184 | Battery | 659-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 13:35 | Distribution | Ashland Pipe Quarterly Inspection | B0201 | NonLTC | 607-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 12:46 | Distribution | Harrodsburg East Quarterly Inspection | CB0161 | BreakerVacuum | 860-2130 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Amps B Ø | 83.0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BCH001127 | Charger | 659-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Amps C Ø | 106.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | General Comments | | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | ST000345 | Structure | 847-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | K0014 | BreakerVacuum | 846-0051 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BCH001127 | Charger | 659-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BCH001127 | Charger | 659-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.0 | amps |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/23/2023 13:23 | Distribution | GE Lamp Works Quarterly Inspection | BCH001127 | Charger | 659-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Amps A Ø | 103.0 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Readings | Winding Temp Max | 60 | °C |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | BB0449 | BreakerVacuum | 532-0148 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 1/23/2023 11:30 | Distribution | Parkers Mill Quarterly Inspection | FE000353 | Fence | 846-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Readings | Totalizer Meter Reading | .6920 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Readings | Follow-up Action Required? | n | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/23/2023 13:24 | Distribution | Buchanan Quarterly Inspection | K0057 | BreakerVacuum | 847-0005 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/23/2023 11:16 | Distribution | Clays Mill Quarterly Inspection | B0458 | WithLTC | 532-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | 9 Month Operations | 6 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Amps A Ø | 130.0 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Amps B Ø | 85.0 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Amps C Ø | 115.0 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | LTCC000856 | LTCControl | 823-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | LTCC000856 | LTCControl | 823-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | LTCC000856 | LTCControl | 823-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | LTCC000856 | LTCControl | 823-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000073 | LTCControl | 898-2 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000073 | LTCControl | 898-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | LTCC000856 | LTCControl | 823-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | LTCC000856 | LTCControl | 823-1 | LTC Control Insp | General Comments | | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | LTCC000856 | LTCControl | 823-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | LTCC000856 | LTCControl | 823-1 | LTC Control Insp | All Connections OK? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000073 | LTCControl | 898-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000073 | LTCControl | 898-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000073 | LTCControl | 898-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000073 | LTCControl | 898-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000073 | LTCControl | 898-2 | LTC Control Insp | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000073 | LTCControl | 898-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000073 | LTCControl | 898-2 | LTC Control Insp | All Connections OK? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Operations Counter AF | 390 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Operations Counter AL | 390 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Operations This Read Vac | 4 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Switching Operations | 0 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Unknown Operations | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | LTCC000856 | LTCControl | 823-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | 9 Month Operations | 3 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | ST000395 | Structure | 898-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Maintenance Operations | 0 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | General Comments | | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Fault Operations Ground | 0 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Fault Operations C Ø | 2 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Fault Operations A Ø | 2 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Fault Adjusted Amps C Phase V | 19.41 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Readings | Fault Adjusted Amps A Phase V | 19.41 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0097 | BreakerVacuum | 745-0026 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Readings | Totalizer Meter Reading | .6170 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1500 | psi |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Readings | LTC Totalizer Reading | 8884.80 | kw |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Unknown Operations | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Switching Operations | 3 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Operations This Read Vac | 3 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Operations Counter AL | 162 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Operations Counter AF | 159 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Maintenance Operations | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Patrol Inspection | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Fault Operations Ground | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Readings | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | General Comments | | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | YD000392 | Yard | 898-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Unknown Operations | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0084 | BreakerVacuum | 898-0404 | VCB Patrol Inspection | General Comments | | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | General Comments | | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | YD000347 | Yard | 823-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | FE000376 | Fence | 898-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | General Comments | | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | ST000350 | Structure | 823-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Amps C Ø | 360.0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Amps B Ø | 240.0 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Amps A Ø | 240.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Fault Operations Ground | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Patrol Inspection | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Maintenance Operations | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Operations Counter AF | 144 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Operations Counter AL | 146 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Operations This Read Vac | 2 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Switching Operations | 2 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Unknown Operations | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | 9 Month Operations | 4 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Amps A Ø | 145.0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Amps B Ø | 160.0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Amps C Ø | 160.0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | FE000343 | Fence | 823-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Switching Operations | 3 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Operations This Read Vac | 3 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Operations Counter AL | 513 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Operations Counter AF | 511 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Maintenance Operations | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Amps C Ø | 130.0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Amps B Ø | 155.0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Amps A Ø | 160.0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001597 | BreakerVacuum | 898-0079 | VCB Readings | 9 Month Operations | 4 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | WithLTC | 898-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | 9 Month Operations | 2 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Fault Operations Ground | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0442 | BreakerVacuum | 898-0077 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Amps A Ø | 0.0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Amps B Ø | 0.0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Readings | Amps C Ø | 0.0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001598 | BreakerVacuum | 898-0087 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Readings | General Comments | | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Readings | Totalizer Meter Reading | .3850 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Counter Readings | General Comments | | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Counter Readings | LTC As Found Counter | 77209 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000740 | LTCControl | 898-1 | LTC Control Insp | All Connections OK? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000740 | LTCControl | 898-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000740 | LTCControl | 898-1 | LTC Control Insp | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000740 | LTCControl | 898-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Unknown Operations | 0 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Switching Operations | 2 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Operations This Read Vac | 3 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Operations Counter AL | 174 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Operations Counter AF | 172 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000740 | LTCControl | 898-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000740 | LTCControl | 898-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000740 | LTCControl | 898-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000740 | LTCControl | 898-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | LTCC000740 | LTCControl | 898-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Maintenance Operations | 0 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | General Comments | | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Follow-up Action Required? | n | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Fault Operations Ground | 0 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Fault Operations A Ø | 1 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Fault Adjusted Amps A Phase V | 1.66 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Counter Readings | LTC As Left Counter | 77209 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | LTCMechanism | 898-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | General Comments | | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | 9 Month Operations | 10 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Operations Counter AF | 197 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Operations Counter AL | 197 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Amps A Ø | 33.0 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Amps B Ø | 32.0 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Amps C Ø | 35.0 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | General Comments | | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | FE000468 | Fence | 745-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Switching Operations | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Unknown Operations | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Amps A Ø | 100.0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Amps B Ø | 100.0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Amps C Ø | 100.0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Operations Counter AL | 246 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Operations This Read Vac | 2 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Switching Operations | 2 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Unknown Operations | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Fault Operations Ground | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Follow-up Action Required? | n | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Readings | LTC Totalizer Reading | 1848.00 | kw |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 35 | °F |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Maintenance Operations | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Operations Counter AF | 514 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Operations Counter AL | 518 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Readings | Oil Temp Present | 15 | °C |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Operations This Read Vac | 4 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 14540 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Switching Operations | 4 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | Unknown Operations | 0 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | BAT001225 | Battery | 745-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Counter Readings | LTC Operations Since Last Insp | 300 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | LTCMechanism | 823-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Readings | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Readings | LTC Totalizer Reading | 3248.00 | kw |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Fault Operations Ground | 0 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Follow-up Action Required? | n | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | General Comments | | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | General Comments | | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 8000 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Readings | Totalizer Meter Reading | .4060 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 155.00 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | B0303 | WithLTC | 898-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Amps C Ø | 30.0 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Amps B Ø | 35.0 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Maintenance Operations | 0 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Amps A Ø | 32.0 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | 9 Month Operations VCB New | 26 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK002057 | BreakerVacuum | 823-0082 | VCB Readings | 9 Month Operations | 29 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BK000252 | BreakerVacuum | 823-0093 | VCB Readings | Operations Counter AF | 244 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | B0465 | WithLTC | 823-1 | LTC Transformer Readings | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | 9 Month Operations | 4 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BB0443 | BreakerVacuum | 898-0078 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BCH001178 | Charger | 823-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BCH001178 | Charger | 823-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BCH001178 | Charger | 823-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.3 | amps |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BCH001178 | Charger | 823-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BCH001178 | Charger | 823-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BCH001178 | Charger | 823-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 35 | °F |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 12456 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Unknown Operations | 0 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Switching Operations | 0 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Operations This Read Vac | 0 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Operations Counter AL | 250 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Operations Counter AF | 250 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000049 | Regulator | 745-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Maintenance Operations | 0 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | General Comments | | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | General Comments | | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | BCH001174 | Charger | 745-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | BCH001174 | Charger | 745-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | BCH001174 | Charger | 745-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | BCH001174 | Charger | 745-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.3 | amps |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | BCH001174 | Charger | 745-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | BCH001174 | Charger | 745-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | BCH001174 | Charger | 745-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | BCH001174 | Charger | 745-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 55.00 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 2503.20 | kw |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Fault Operations Ground | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Patrol Inspection | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Maintenance Operations | 0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Operations Counter AF | 174 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Operations Counter AL | 177 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Operations This Read Vac | 3 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Switching Operations | 3 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BK001599 | BreakerVacuum | 898-0088 | VCB Readings | Unknown Operations | 0 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | General Comments | | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | ST000358 | Structure | 745-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | B0282 | NonLTC | 745-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.0430 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.0 | volts |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 14673 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BCH001178 | Charger | 823-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | 9 Month Operations | 8 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BCH001569 | Charger | 898-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BCH001569 | Charger | 898-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 4.4 | amps |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BCH001569 | Charger | 898-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BCH001569 | Charger | 898-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BCH001569 | Charger | 898-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BCH001569 | Charger | 898-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Amps A Ø | 385.0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Amps B Ø | 425.0 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Readings | Amps C Ø | 385.0 | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BAT000525 | Battery | 898-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 35 | °F |
| 1/20/2023 13:32 | Distribution | Spindletop Quarterly Inspection | BAT001230 | Battery | 823-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | 9 Month Operations | 2 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KB0082 | BreakerVacuum | 898-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Counter Readings | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Counter Readings | LTC As Found Counter | 46889 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Counter Readings | LTC As Left Counter | 46889 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 45 | °C |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Counter Readings | LTC Operations Since Last Insp | 722 | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | KT0022 | LTCMechanism | 898-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Max Tap Position | Neutral | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Fault Operations Ground | 0 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Amps C Ø | 85.0 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Amps B Ø | 45.0 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | YD000355 | Yard | 745-Yard | Yard Patrol Inspection | General Comments | | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BCH001569 | Charger | 898-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 1/20/2023 12:28 | Distribution | Trafton Avenue Quarterly Inspection | BCH001569 | Charger | 898-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | K0096 | BreakerVacuum | 745-0019 | VCB Readings | Amps A Ø | 30.0 | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000050 | Regulator | 745-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/20/2023 12:28 | Distribution | Kunkel Quarterly Inspection | RG000048 | Regulator | 745-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | GND000045 | BreakerGroundDevice | 516-Offline Distribution | Breaker Ground Device Inspection | Vacuum and Clean Breaker? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BCH001424 | Charger | 726-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BCH001424 | Charger | 726-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BCH001424 | Charger | 726-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BCH001424 | Charger | 726-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BCH001424 | Charger | 726-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.4 | amps |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BCH001424 | Charger | 726-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.1 | VDC |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BCH001424 | Charger | 726-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.1 | VDC |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BCH001424 | Charger | 726-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Readings | Operations This Read Vac | 2 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | 9 Month Operations | 0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Readings | Operations Counter AL | 112 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Readings | Operations Counter AF | 110 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | General Comments | | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Operations This Read Vac | 2 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Operations Counter AL | 215 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Readings | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Operations Counter AF | 213 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Operations Counter AF | 161 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Amps A Ø | 577.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Amps C Ø | 80.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Amps B Ø | 50.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Amps B Ø | 605.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Amps C Ø | 634.0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | 9 Month Operations | 2 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Amps A Ø | 80.0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | GND000045 | BreakerGroundDevice | 516-Offline Distribution | Breaker Ground Device Inspection | All Connections OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | GND000045 | BreakerGroundDevice | 516-Offline Distribution | Breaker Ground Device Inspection | Bearings lubricated? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | GND000045 | BreakerGroundDevice | 516-Offline Distribution | Breaker Ground Device Inspection | Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | GND000045 | BreakerGroundDevice | 516-Offline Distribution | Breaker Ground Device Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | GND000045 | BreakerGroundDevice | 516-Offline Distribution | Breaker Ground Device Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | GND000045 | BreakerGroundDevice | 516-Offline Distribution | Breaker Ground Device Inspection | Ground Connections Intact? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | GND000045 | BreakerGroundDevice | 516-Offline Distribution | Breaker Ground Device Inspection | Rosettes Clean and Lubed? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | 9 Month Operations | 11 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Amps A Ø | 25.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Amps B Ø | 45.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Amps C Ø | 30.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Operations Counter AF | 209 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Operations Counter AL | 211 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Operations This Read Vac | 2 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000958 | BreakerVacuum | 509-0098 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 10.00 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | LTCC000800 | LTCControl | 526-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | LTCC000800 | LTCControl | 526-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | LTCC000800 | LTCControl | 526-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | LTCC000800 | LTCControl | 526-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | LTCC000800 | LTCControl | 526-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | LTCC000800 | LTCControl | 526-1 | LTC Control Insp | General Comments | | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | LTCC000800 | LTCControl | 526-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | LTCC000800 | LTCControl | 526-1 | LTC Control Insp | All Connections OK? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 630.00 | kw |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Readings | General Comments | | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Readings | General Comments | | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | General Comments | | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | General Comments | | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Operations Counter AF | 255 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Operations Counter AL | 259 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Operations This Read Vac | 4 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Switching Operations | 4 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | 9 Month Operations | 12 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Amps A Ø | 145.0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Amps B Ø | 110.0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Amps C Ø | 115.0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .5250 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BCH001422 | Charger | 835-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BCH001422 | Charger | 835-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Amps A Ø | 65.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Amps B Ø | 65.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Amps C Ø | 75.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BCH001422 | Charger | 835-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BCH001422 | Charger | 835-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BCH001422 | Charger | 835-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Readings | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Readings | Operations Counter AF | 104 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Readings | Operations Counter AL | 106 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Readings | Operations This Read Vac | 2 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Fault Adjusted Amps B Phase V | 25.80 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Fault Adjusted Amps C Phase V | 25.80 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Fault Operations B Ø | 2 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Fault Operations C Ø | 2 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Operations Counter AF | 209 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Operations Counter AL | 209 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Operations This Read Vac | 6 | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Counter Readings | LTC Operations Since Last Insp | 643 | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Counter Readings | LTC As Left Counter | 28258 | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Counter Readings | LTC As Found Counter | 28258 | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Counter Readings | General Comments | | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | LTCMechanism | 744-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 53 | °F |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 25.9 | VDC |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BAT001493 | Battery | 726-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | General Comments | | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | B0275 | NonLTC | 595-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Readings | 9 Month Operations | 8 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Readings | Amps A Ø | 71.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Readings | Amps B Ø | 76.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Readings | Amps C Ø | 80.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001559 | BreakerVacuum | 516-0131 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Readings | 9 Month Operations | 2 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Operations Counter AF | 212 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Operations Counter AL | 214 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Operations This Read Vac | 2 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK000924 | BreakerVacuum | 526-0129 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 54 | °F |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BAT001188 | Battery | 731-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BAT001491 | Battery | 835-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BAT001491 | Battery | 835-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 61 | °F |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BAT001491 | Battery | 835-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BAT001491 | Battery | 835-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BAT001491 | Battery | 835-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BAT001491 | Battery | 835-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BAT001491 | Battery | 835-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BAT001491 | Battery | 835-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BAT001491 | Battery | 835-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BAT001491 | Battery | 835-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.7 | VDC |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BAT001491 | Battery | 835-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.7 | VDC |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BAT001491 | Battery | 835-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BAT001491 | Battery | 835-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BCH001422 | Charger | 835-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BCH001422 | Charger | 835-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BCH001422 | Charger | 835-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Readings | Switching Operations | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Readings | Operations Counter AL | 242 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Readings | Operations Counter AF | 242 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | 9 Month Operations | 10 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000959 | BreakerVacuum | 509-0198 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Operations Counter AF | 812 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Operations Counter AL | 814 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Operations This Read Vac | 2 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Readings | Operations This Read Vac | 2 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Readings | Operations Counter AL | 117 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | General Comments | | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | FE000838 | Fence | 595-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BCH000612 | Charger | 731-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BCH000612 | Charger | 731-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BCH000612 | Charger | 731-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.8 | amps |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BCH000612 | Charger | 731-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 52.8 | VDC |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BCH000612 | Charger | 731-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 52.8 | VDC |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BCH000612 | Charger | 731-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BCH001263 | Charger | 509-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BCH001263 | Charger | 509-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BCH001263 | Charger | 509-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BCH001263 | Charger | 509-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BCH001263 | Charger | 509-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 4.9 | amps |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BCH001263 | Charger | 509-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 134.0 | VDC |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BCH001263 | Charger | 509-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 134.0 | VDC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BCH001263 | Charger | 509-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Readings | Operations Counter AF | 115 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Readings | Amps A Ø | 130.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Readings | Amps B Ø | 149.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Readings | Amps C Ø | 132.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Readings | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Readings | Amps C Ø | 11.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Readings | Amps B Ø | 12.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Readings | Amps A Ø | 12.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | 9 Month Operations | 3 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Readings | 9 Month Operations | 4 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BAT001322 | Battery | 509-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BAT001322 | Battery | 509-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BAT001322 | Battery | 509-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BAT001322 | Battery | 509-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BAT001322 | Battery | 509-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BAT001322 | Battery | 509-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Amps A Ø | 156.0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Amps B Ø | 181.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BAT001322 | Battery | 509-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BAT001322 | Battery | 509-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BAT001322 | Battery | 509-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BAT001322 | Battery | 509-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BAT001322 | Battery | 509-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BAT001322 | Battery | 509-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BAT001322 | Battery | 509-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | LTCC000641 | LTCControl | 744-1 | LTC Control Insp | All Connections OK? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | LTCC000641 | LTCControl | 744-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | LTCC000641 | LTCControl | 744-1 | LTC Control Insp | General Comments | | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | LTCC000641 | LTCControl | 744-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | LTCC000641 | LTCControl | 744-1 | LTC Control Insp | LTC Output Voltage Level | 123.4 | VAC |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | LTCC000641 | LTCControl | 744-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | LTCC000641 | LTCControl | 744-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | LTCC000641 | LTCControl | 744-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Readings | Operations Counter AF | 125 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Readings | Operations Counter AL | 127 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Readings | Operations This Read Vac | 2 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Readings | Amps C Ø | 175.0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0398 | BreakerVacuum | 463-0044 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Readings | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Readings | 9 Month Operations | 4 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Readings | Operations Counter AF | 96 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Readings | Operations Counter AL | 98 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Readings | Operations This Read Vac | 2 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Readings | Switching Operations | 1 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Readings | Operations This Read Vac | 1 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Readings | Operations Counter AL | 99981 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 90608 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BCH001431 | Charger | 516-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BCH001431 | Charger | 516-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.0 | VDC |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BCH001431 | Charger | 516-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.0 | VDC |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BCH001431 | Charger | 516-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 5.1 | amps |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BCH001431 | Charger | 516-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BCH001431 | Charger | 516-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BCH001431 | Charger | 516-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BCH001431 | Charger | 516-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BAT001501 | Battery | 516-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BAT001501 | Battery | 516-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BAT001501 | Battery | 516-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BAT001501 | Battery | 516-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BAT001501 | Battery | 516-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BAT001501 | Battery | 516-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BAT001501 | Battery | 516-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BAT001501 | Battery | 516-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BAT001501 | Battery | 516-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BAT001501 | Battery | 516-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BAT001501 | Battery | 516-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BAT001501 | Battery | 516-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BAT001501 | Battery | 516-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | SF6 Pressure Pole 1 | 58 | psi |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | SF6 Pressure Pole 2 | 58 | psi |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | SF6 Pressure Pole 3 | 58 | psi |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Current Tap Position | 10L | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Readings | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | n | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0570 | Regulator | 595-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Readings | Amps C Ø | 21.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Readings | Amps B Ø | 21.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Readings | Amps A Ø | 24.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001554 | BreakerVacuum | 516-1104 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | FE000850 | Fence | 509-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 212063 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Readings | 9 Month Operations | 4 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Readings | Amps A Ø | 75.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Readings | Amps B Ø | 74.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Ambient Temperature | 62 | °F |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Readings | Fault Operations | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Readings | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | General Comments | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Readings | Operations Counter AF | 114 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Readings | Operations Counter AL | 114 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Readings | Operations This Read SF6 | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Readings | Amps C Ø | 71.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Amps A Ø | 22.0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | 9 Month Operations | 2 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Readings | General Comments | | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Readings | LTC Totalizer Reading | 9465.60 | kw |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Readings | Totalizer Meter Reading | .9860 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | YD000389 | Yard | 516-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | YD000389 | Yard | 516-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | YD000389 | Yard | 516-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | ST000392 | Structure | 516-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | ST000392 | Structure | 516-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | ST000392 | Structure | 516-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | ST000392 | Structure | 516-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | ST000392 | Structure | 516-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | ST000392 | Structure | 516-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | ST000392 | Structure | 516-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | ST000392 | Structure | 516-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | ST000392 | Structure | 516-Structure | Structure Patrol Inspection | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | ST000392 | Structure | 516-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | ST000392 | Structure | 516-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | ST000392 | Structure | 516-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | ST000392 | Structure | 516-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Readings | Amps C Ø | 276.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Readings | Amps B Ø | 267.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Readings | Amps A Ø | 257.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Readings | 9 Month Operations | 0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Readings | Winding Temp Present | 35 | °C |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Readings | Winding Temp Max | 35 | °C |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | ST000392 | Structure | 516-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Readings | Operations This Read Vac | 2 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Readings | Operations Counter AL | 109 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Readings | Operations Counter AF | 107 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Readings | Totalizer Meter Reading | .5110 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | ST000392 | Structure | 516-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | ST000392 | Structure | 516-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | ST000392 | Structure | 516-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | ST000392 | Structure | 516-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Operations Counter AF | 198 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Operations Counter AL | 200 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Operations This Read Vac | 2 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000960 | BreakerVacuum | 509-0096 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Operations Counter AL | 161 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Switching Operations | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001342 | BreakerVacuum | 463-2 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BAT000530 | Battery | 526-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BAT000530 | Battery | 526-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BAT000530 | Battery | 526-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BAT000530 | Battery | 526-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BAT000530 | Battery | 526-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BAT000530 | Battery | 526-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BAT000530 | Battery | 526-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BAT000530 | Battery | 526-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Amps C Ø | 22.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | YD000389 | Yard | 516-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | YD000389 | Yard | 516-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | YD000389 | Yard | 516-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | YD000389 | Yard | 516-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | YD000389 | Yard | 516-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | YD000389 | Yard | 516-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | YD000389 | Yard | 516-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | YD000389 | Yard | 516-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | YD000389 | Yard | 516-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | YD000389 | Yard | 516-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BAT000530 | Battery | 526-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BAT000530 | Battery | 526-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BAT000530 | Battery | 526-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BAT000530 | Battery | 526-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 52 | °F |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BAT000530 | Battery | 526-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Readings | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001556 | BreakerVacuum | 516-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | WithLTC | 832-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | YD000389 | Yard | 516-Yard | Yard Patrol Inspection | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | YD000389 | Yard | 516-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | YD000389 | Yard | 516-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001281 | BreakerVacuum | 832-0117 | VCB Readings | Amps B Ø | 27.0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | LTCC000079 | LTCControl | 832-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | LTCC000079 | LTCControl | 832-1 | LTC Control Insp | General Comments | | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | LTCC000079 | LTCControl | 832-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | LTCC000079 | LTCControl | 832-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | LTCC000079 | LTCControl | 832-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001553 | BreakerVacuum | 516-0054 | VCB Readings | 9 Month Operations | 4 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | LTCC000079 | LTCControl | 832-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | LTCC000079 | LTCControl | 832-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | LTCC000079 | LTCControl | 832-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Min Tap Position | 4L | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Readings | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | General Comments | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Readings | Operations Counter AF | 82 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Readings | Operations Counter AL | 82 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Readings | Operations This Read SF6 | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | SF6 Pressure Pole 1 | 60 | psi |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | SF6 Pressure Pole 2 | 64 | psi |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | SF6 Pressure Pole 3 | 60 | psi |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Readings | Switching Operations | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Readings | Unknown Operations | 0 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Current Tap Position | 9L | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Readings | Switching Operations | 0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | Bat Volt 1Min After Chgr Trip | 49.0 | VDC |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BAT000996 | Battery | 832-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Readings | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Readings | Operations Counter AL | 226 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Readings | Operations Counter AF | 228 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001555 | BreakerVacuum | 516-1105 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | ST000392 | Structure | 516-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | ST000392 | Structure | 516-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | ST000392 | Structure | 516-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Amps C Ø | 15.0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Amps B Ø | 10.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Ambient Temperature | 62 | °F |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Readings | Fault Operations | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000962 | BreakerSF6 | 509-608 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Amps A Ø | 15.0 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | 9 Month Operations | 150 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Readings | LTC Totalizer Reading | 7358.40 | kw |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Readings | General Comments | | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | FE000872 | Fence | 516-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | FE000872 | Fence | 516-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | FE000872 | Fence | 516-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | FE000872 | Fence | 516-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | FE000872 | Fence | 516-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | FE000872 | Fence | 516-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | FE000872 | Fence | 516-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | FE000872 | Fence | 516-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | FE000872 | Fence | 516-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | FE000872 | Fence | 516-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | FE000872 | Fence | 516-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | FE000872 | Fence | 516-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | FE000872 | Fence | 516-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | FE000872 | Fence | 516-Fence | Fence Patrol Inspection | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | FE000872 | Fence | 516-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | WithLTC | 526-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 43161 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 122.8 | volts |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1350 | Regulator | 726-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | FE000872 | Fence | 516-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | LTCC000079 | LTCControl | 832-1 | LTC Control Insp | All Connections OK? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | General Comments | | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | General Comments | | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Readings | Operations Counter AL | 2176 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Readings | Operations Counter AF | 2175 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Readings | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | Ambient Temp | 62 | °F |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | General Comments | | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Readings | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Readings | Amps C Ø | 0.0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Readings | Amps B Ø | 0.0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Readings | Amps A Ø | 0.0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Readings | 9 Month Operations VCB New | 20 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Readings | LTC Totalizer Reading | 6897.60 | kw |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1400 | psi |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Readings | Totalizer Meter Reading | .2874 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Readings | Winding Temp Max | 30 | °C |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Readings | Winding Temp Present | 25 | °C |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Readings | X1 Winding Temp Max | 30 | °C |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Readings | X1 Winding Temp Present | 25 | °C |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Readings | X2 Winding Temp Max | 30 | °C |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Readings | X2 Winding Temp Present | 25 | °C |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | YD000467 | Yard | 595-Yard | Yard Patrol Inspection | Ambient Temp | 54 | °F |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | General Comments | | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Operations Counter AF | 146 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BAT001634 | Battery | 834-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BAT001634 | Battery | 834-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BAT001634 | Battery | 834-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Operations Counter AL | 150 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BAT001634 | Battery | 834-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BAT001634 | Battery | 834-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BAT001634 | Battery | 834-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BAT001634 | Battery | 834-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BAT001634 | Battery | 834-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BAT001634 | Battery | 834-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BAT001634 | Battery | 834-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.3 | VDC |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BAT001634 | Battery | 834-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.3 | VDC |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BAT001634 | Battery | 834-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Readings | X1 Winding Temp Present | 25 | °C |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Operations Counter AL | 99933 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Operations This Read Vac | 4 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Switching Operations | 4 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Readings | X2 Winding Temp Max | 30 | °C |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Readings | X2 Winding Temp Present | 25 | °C |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Readings | X3 Winding Temp Max | 30 | °C |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Readings | X3 Winding Temp Present | 25 | °C |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Readings | Totalizer Meter Reading | .2904 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Readings | Winding Temp Max | 30 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Min Tap Position | 3L | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.6 | volts |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 102291 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Readings | General Comments | | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | General Comments | | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Operations Counter AF | 99929 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Readings | Winding Temp Present | 25 | °C |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Readings | X1 Winding Temp Max | 30 | °C |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | YD000393 | Yard | 509-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Operations This Read Vac | 2 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Operations Counter AL | 191 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Operations Counter AF | 189 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Readings | Operations This Read Vac | 1 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Readings | Operations Counter AF | 124 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Readings | Operations Counter AL | 126 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Readings | Operations This Read Vac | 2 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | ST000470 | Structure | 595-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | ST000397 | Structure | 463-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | YD000394 | Yard | 463-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | YD000394 | Yard | 463-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | YD000394 | Yard | 463-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | YD000394 | Yard | 463-Yard | Yard Patrol Inspection | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | YD000394 | Yard | 463-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | YD000394 | Yard | 463-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | YD000394 | Yard | 463-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | YD000394 | Yard | 463-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | YD000394 | Yard | 463-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | YD000394 | Yard | 463-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | YD000394 | Yard | 463-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | YD000394 | Yard | 463-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | YD000394 | Yard | 463-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | General Comments | | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | FE000426 | Fence | 848-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | ST000396 | Structure | 509-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCC000983 | LTCControl | 509-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCC000983 | LTCControl | 509-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCC000983 | LTCControl | 509-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCC000983 | LTCControl | 509-2 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCC000983 | LTCControl | 509-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCC000983 | LTCControl | 509-2 | LTC Control Insp | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCC000983 | LTCControl | 509-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCC000983 | LTCControl | 509-2 | LTC Control Insp | All Connections OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000110 | LTCMechanism | 516-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000110 | LTCMechanism | 516-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BCH001365 | Charger | 848-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BCH001365 | Charger | 848-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BCH001365 | Charger | 848-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BCH001365 | Charger | 848-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.9 | amps |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BCH001365 | Charger | 848-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BCH001365 | Charger | 848-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BCH001365 | Charger | 848-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000110 | LTCMechanism | 516-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BCH001365 | Charger | 848-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000110 | LTCMechanism | 516-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000110 | LTCMechanism | 516-1 | LTC Counter Readings | LTC Operations Since Last Insp | 328 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000110 | LTCMechanism | 516-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 20 | °C |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000110 | LTCMechanism | 516-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 15 | °C |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000110 | LTCMechanism | 516-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000110 | LTCMechanism | 516-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000110 | LTCMechanism | 516-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000110 | LTCMechanism | 516-1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000110 | LTCMechanism | 516-1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000110 | LTCMechanism | 516-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000110 | LTCMechanism | 516-1 | LTC Counter Readings | LTC As Left Counter | 5263 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Operations Counter | 11 | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000111 | LTCMechanism | 516-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000111 | LTCMechanism | 516-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000111 | LTCMechanism | 516-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000111 | LTCMechanism | 516-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000111 | LTCMechanism | 516-2 | LTC Counter Readings | LTC Operations Since Last Insp | 348 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000111 | LTCMechanism | 516-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 15 | °C |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000111 | LTCMechanism | 516-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 20 | °C |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000111 | LTCMechanism | 516-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000111 | LTCMechanism | 516-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000111 | LTCMechanism | 516-2 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000111 | LTCMechanism | 516-2 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000111 | LTCMechanism | 516-2 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000111 | LTCMechanism | 516-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000111 | LTCMechanism | 516-2 | LTC Counter Readings | LTC As Left Counter | 5370 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000111 | LTCMechanism | 516-2 | LTC Counter Readings | LTC As Found Counter | 5370 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000111 | LTCMechanism | 516-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000111 | LTCMechanism | 516-2 | LTC Counter Readings | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000111 | LTCMechanism | 516-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000111 | LTCMechanism | 516-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Current Tap Position | 14L | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | GND000037 | BreakerGroundDevice | 516-Offline Distribution | Breaker Ground Device Inspection | Rosettes Clean and Lubed? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | GND000037 | BreakerGroundDevice | 516-Offline Distribution | Breaker Ground Device Inspection | Ground Connections Intact? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | GND000037 | BreakerGroundDevice | 516-Offline Distribution | Breaker Ground Device Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | GND000037 | BreakerGroundDevice | 516-Offline Distribution | Breaker Ground Device Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | GND000037 | BreakerGroundDevice | 516-Offline Distribution | Breaker Ground Device Inspection | Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | GND000037 | BreakerGroundDevice | 516-Offline Distribution | Breaker Ground Device Inspection | Bearings lubricated? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | GND000037 | BreakerGroundDevice | 516-Offline Distribution | Breaker Ground Device Inspection | All Connections OK? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | LTCC000975 | LTCControl | 835-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | LTCC000975 | LTCControl | 835-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | LTCC000975 | LTCControl | 835-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | LTCC000975 | LTCControl | 835-1 | LTC Control Insp | LTC Output Voltage Level | 124.3 | VAC |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | LTCC000975 | LTCControl | 835-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCC000880 | LTCControl | 516-1 | LTC Control Insp | All Connections OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCC000880 | LTCControl | 516-1 | LTC Control Insp | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCC000880 | LTCControl | 516-1 | LTC Control Insp | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCC000880 | LTCControl | 516-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Readings | General Comments | | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCC000880 | LTCControl | 516-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCC000880 | LTCControl | 516-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCC000880 | LTCControl | 516-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCC000880 | LTCControl | 516-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCC000880 | LTCControl | 516-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | LTCC000975 | LTCControl | 835-1 | LTC Control Insp | All Connections OK? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | LTCC000975 | LTCControl | 835-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | LTCC000975 | LTCControl | 835-1 | LTC Control Insp | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Amps C Ø | 80.0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Amps B Ø | 105.0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Amps A Ø | 99.0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000110 | LTCMechanism | 516-1 | LTC Counter Readings | LTC As Found Counter | 5263 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000110 | LTCMechanism | 516-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000110 | LTCMechanism | 516-1 | LTC Counter Readings | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000110 | LTCMechanism | 516-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | 9 Month Operations | 4 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BAT001543 | Battery | 848-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BAT001543 | Battery | 848-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BAT001543 | Battery | 848-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 25.0 | VDC |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BAT001543 | Battery | 848-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BAT001543 | Battery | 848-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BAT001543 | Battery | 848-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BAT001543 | Battery | 848-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BAT001543 | Battery | 848-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BAT001543 | Battery | 848-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BAT001543 | Battery | 848-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BAT001543 | Battery | 848-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BAT001543 | Battery | 848-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 55 | °F |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BAT001543 | Battery | 848-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCM000110 | LTCMechanism | 516-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | LTCC000978 | LTCControl | 413-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | LTCC000978 | LTCControl | 413-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | LTCC000978 | LTCControl | 413-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | LTCC000978 | LTCControl | 413-1 | LTC Control Insp | LTC Output Voltage Level | 123.5 | VAC |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | LTCC000978 | LTCControl | 413-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | LTCC000978 | LTCControl | 413-1 | LTC Control Insp | General Comments | | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | LTCC000978 | LTCControl | 413-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | LTCC000978 | LTCControl | 413-1 | LTC Control Insp | All Connections OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | GND000037 | BreakerGroundDevice | 516-Offline Distribution | Breaker Ground Device Inspection | Vacuum and Clean Breaker? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | General Comments | | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Switching Operations | 1 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Operations This Read Vac | 1 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Operations Counter AL | 189 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Operations Counter AF | 188 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | General Comments | | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Amps C Ø | 51.0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Amps B Ø | 34.0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Readings | X3 Winding Temp Max | 30 | °C |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000264 | WithLTC | 516-2 | LTC Transformer Readings | X3 Winding Temp Present | 25 | °C |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BAT001634 | Battery | 834-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | YD000430 | Yard | 848-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Readings | Totalizer Meter Reading | .8020 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Readings | 9 Month Operations | 21 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | FE000425 | Fence | 726-Fence | Fence Patrol Inspection | General Comments | | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | ST000433 | Structure | 848-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | 9 Month Operations | 2 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Amps C Ø | 13.0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Amps B Ø | 24.0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Amps A Ø | 13.0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | 9 Month Operations | 1 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 32308 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.5 | volts |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Amps A Ø | 38.0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R1158 | Regulator | 848-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Amps B Ø | 44.0 | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Amps C Ø | 30.0 | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | X0304 | RecloserElectronic | 744-0153 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCC000881 | LTCControl | 516-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCC000881 | LTCControl | 516-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCC000881 | LTCControl | 516-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCC000881 | LTCControl | 516-2 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCC000881 | LTCControl | 516-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCC000881 | LTCControl | 516-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCC000881 | LTCControl | 516-2 | LTC Control Insp | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCC000881 | LTCControl | 516-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | LTCC000881 | LTCControl | 516-2 | LTC Control Insp | All Connections OK? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 0 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0.0 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001144 | BreakerVacuum | 731-2100 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Readings | LTC Totalizer Reading | 7699.20 | kw |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | WithLTC | 835-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Operations This Read Vac | 150 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Switching Operations | 150 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 0 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | General Comments | no amp gauge | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | Operations Counter | 231 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Amps A Ø | 35.0 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0495 | RecloserHydraulic | 595-0866 B | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0305 | BreakerVacuum | 413-0281 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001098 | BreakerVacuum | 832-0104 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Amps C Ø | 0.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Amps C Ø | 250.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Amps B Ø | 220.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Amps A Ø | 250.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | 9 Month Operations VCB New | 22 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | 9 Month Operations | 24 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | YD000345 | Yard | 526-Yard | Yard Patrol Inspection | Ambient Temp | 52 | °F |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Readings | Operations Counter AF | 209 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Readings | Operations Counter AL | 209 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Operations Counter AF | 280 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Operations Counter AL | 282 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Operations This Read Vac | 2 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Operations This Read Vac | 2 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Operations Counter AL | 211 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Operations Counter AF | 229 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000956 | BreakerVacuum | 509-0097 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Readings | Amps A Ø | 0.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Readings | Amps B Ø | 0.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Readings | Amps C Ø | 0.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Readings | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Readings | LTC Totalizer Reading | 21780.00 | kw |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Readings | Oil Temp Max | 48 | °C |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Readings | Oil Temp Present | 32 | °C |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Readings | Totalizer Meter Reading | 1.2100 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | WithLTC | 834-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Operations Counter AF | 193 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Readings | Switching Operations | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001547 | BreakerVacuum | 516-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | ST000348 | Structure | 526-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Amps B Ø | 0.0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Amps A Ø | 0.0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | 9 Month Operations | 1 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Operations This Read Vac | 2 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Operations Counter AL | 195 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Operations This Read Vac | 2 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Operations Counter AL | 651 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Operations Counter AF | 649 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0397 | BreakerVacuum | 463-0069 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Readings | 9 Month Operations | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Amps C Ø | 80.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Amps B Ø | 75.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Amps A Ø | 75.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | 9 Month Operations | 10 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Amps A Ø | 90.0 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | 9 Month Operations | 5 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Readings | Amps C Ø | 72.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Readings | Amps B Ø | 68.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Readings | Amps A Ø | 66.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001552 | BreakerVacuum | 516-0029 | VCB Readings | 9 Month Operations | 3 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | 9 Month Operations | 2 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Amps A Ø | 82.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Operations This Read Vac | 5 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Operations Counter AL | 211 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Operations Counter AF | 209 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Fault Operations B Ø | 3 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Amps C Ø | 90.0 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BB0306 | BreakerVacuum | 413-0280 | VCB Readings | Amps B Ø | 80.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Fault Adjusted Amps B Phase V | 38.70 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000957 | BreakerVacuum | 509-0108 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Amps C Ø | 82.0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Operations Counter AF | 247 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Operations Counter AL | 249 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Operations This Read Vac | 2 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Switching Operations | 1 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Operations This Read Vac | 1 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Operations Counter AL | 180 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001551 | BreakerVacuum | 848-0157 | VCB Readings | Operations Counter AF | 179 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Amps B Ø | 87.0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Amps C Ø | 75.0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | 9 Month Operations | 2 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0189 | BreakerVacuum | 463-0040 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Amps A Ø | 64.0 | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Amps B Ø | 66.0 | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Amps C Ø | 58.0 | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Amps A Ø | 82.0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0062 | BreakerVacuum | 463-0053 | VCB Readings | Amps B Ø | 83.0 | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | RC000098 | RecloserElectronic | 744-0553 | Recloser Electronic Patrol Inspection | Operations Counter | 136 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Counter Readings | General Comments | | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Counter Readings | LTC As Found Counter | 73228 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Counter Readings | LTC As Left Counter | 73228 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Counter Readings | LTC Operations Since Last Insp | 333 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | C0532 | LTCMechanism | 835-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | 9 Month Operations | 6 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Readings | 9 Month Operations | 2 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Readings | Amps C Ø | 39.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Readings | Amps B Ø | 37.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Readings | Amps A Ø | 37.0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | 9 Month Operations | 2 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | FE000541 | Fence | 731-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BAT001629 | Battery | 413-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BAT001629 | Battery | 413-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 63 | °F |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BAT001629 | Battery | 413-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BAT001629 | Battery | 413-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BAT001629 | Battery | 413-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BAT001629 | Battery | 413-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BAT001629 | Battery | 413-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BAT001629 | Battery | 413-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BAT001629 | Battery | 413-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BAT001629 | Battery | 413-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.7 | VDC |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BAT001629 | Battery | 413-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.8 | VDC |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BAT001629 | Battery | 413-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BAT001629 | Battery | 413-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Patrol Inspection | Cabinet Door Seals OK? | n | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Amps C Ø | 125.0 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Amps B Ø | 120.0 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Amps A Ø | 122.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Readings | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Readings | LTC Totalizer Reading | 6969.60 | kw |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1300 | psi |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Readings | Switching Operations | 1 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0242 | BreakerVacuum | 834-2116 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | TX000263 | WithLTC | 516-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | 9 Month Operations | 4 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Amps A Ø | 240.0 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Amps B Ø | 240.0 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Amps C Ø | 240.0 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | CB0296 | BreakerVacuum | 835-0174 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Readings | 9 Month Operations | 4 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Readings | Amps A Ø | 47.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Readings | Amps B Ø | 46.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Readings | Amps C Ø | 49.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001549 | BreakerVacuum | 516-0028 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0599 | Regulator | 595-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Switching Operations | 1 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | LTCC000628 | LTCControl | 834-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Operations This Read Vac | 1 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Operations Counter AL | 203 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Operations Counter AF | 202 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Readings | General Comments | | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | Ambient Temp | 53 | °F |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | General Comments | | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | General Comments | | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Readings | Operations This Read Vac | 2 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Readings | Operations Counter AL | 32 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Readings | Operations Counter AF | 30 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Readings | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BCH001577 | Charger | 413-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BCH001577 | Charger | 413-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BCH001577 | Charger | 413-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BCH001577 | Charger | 413-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .7 | amps |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BCH001577 | Charger | 413-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BCH001577 | Charger | 413-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BCH001577 | Charger | 413-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | BCH001577 | Charger | 413-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | LTCC000628 | LTCControl | 834-1 | LTC Control Insp | All Connections OK? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | LTCC000628 | LTCControl | 834-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | LTCC000628 | LTCControl | 834-1 | LTC Control Insp | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | LTCC000628 | LTCControl | 834-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | LTCC000628 | LTCControl | 834-1 | LTC Control Insp | LTC Output Voltage Level | 123.7 | VAC |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | LTCC000628 | LTCControl | 834-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | LTCC000628 | LTCControl | 834-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | LTCC000628 | LTCControl | 834-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BCH001580 | Charger | 834-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BCH001580 | Charger | 834-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 52.8 | VDC |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BCH001580 | Charger | 834-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 52.8 | VDC |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BCH001580 | Charger | 834-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 4.3 | amps |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BCH001580 | Charger | 834-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BCH001580 | Charger | 834-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BCH001580 | Charger | 834-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BCH001580 | Charger | 834-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 7680.00 | kw |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | ST000432 | Structure | 726-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Amps C Ø | 99.0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Amps B Ø | 94.0 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | S0006 | NonLTC | 726-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .8000 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Amps A Ø | 117.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Readings | Operations Counter AF | 194 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Readings | Operations Counter AL | 194 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Readings | Switching Operations | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Readings | General Comments | | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | BK000648 | BreakerVacuum | 726-0767 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001557 | BreakerVacuum | 516-BT2-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001558 | BreakerVacuum | 516-0113 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | General Comments | | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | YD000429 | Yard | 726-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BK001099 | BreakerVacuum | 832-0105 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | 9 Month Operations | 4 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Maintenance Operations | 12 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Operations Counter AF | 192 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Operations Counter AL | 192 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Amps A Ø | 40.0 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Amps B Ø | 45.0 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Amps C Ø | 40.0 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | LTCC000610 | LTCControl | 834-2 | LTC Control Insp | All Connections OK? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | LTCC000610 | LTCControl | 834-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | LTCC000610 | LTCControl | 834-2 | LTC Control Insp | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | LTCC000610 | LTCControl | 834-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | LTCC000610 | LTCControl | 834-2 | LTC Control Insp | LTC Output Voltage Level | 124.4 | VAC |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | LTCC000610 | LTCControl | 834-2 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Counter Readings | General Comments | | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Counter Readings | LTC As Found Counter | 34048 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Counter Readings | LTC As Left Counter | 34048 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Counter Readings | LTC Operations Since Last Insp | 145 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | LTCMechanism | 413-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | General Comments | | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | FE000341 | Fence | 526-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol  Inspection | Broom on Site? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol  Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol  Inspection | Control House Lighting OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol  Inspection | Controlhouse Grounds in Place? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol  Inspection | Door Alarms OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol  Inspection | Doors and Locks Secure? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol  Inspection | Evidence of Insects | None | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol  Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Readings | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Readings | LTC Totalizer Reading | 2000.64 | kw |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | LTCC000610 | LTCControl | 834-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | LTCC000610 | LTCControl | 834-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | LTCC000610 | LTCControl | 834-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Operations This Read Vac | 12 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Switching Operations | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.1800 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Readings | Oil Temp Max | 60 | °C |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 11328.00 | kw |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Readings | General Comments | | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Amps C Ø | 75.0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Amps B Ø | 70.0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Amps A Ø | 65.0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | 9 Month Operations VCB New | 26 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | 9 Month Operations | 28 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 0 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Readings | General Comments | | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Readings | LTC Totalizer Reading | 3974.40 | kw |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | General Comments | | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Operations Counter AF | 181 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Operations Counter AL | 181 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 205 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0.0 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | General Comments | needs updated signs | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | n | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Operations This Read Vac | 2 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Operations Counter AL | 177 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Operations Counter AF | 175 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | General Comments | | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001596 | BreakerVacuum | 526-0086 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | LTCMechanism | 834-1 | LTC Counter Readings | LTC As Found Counter | 596662 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | LTCMechanism | 834-1 | LTC Counter Readings | LTC As Left Counter | 596662 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | LTCMechanism | 834-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | LTCMechanism | 834-1 | LTC Counter Readings | LTC Current Tap Position | 11L | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | LTCMechanism | 834-1 | LTC Counter Readings | LTC Max Tap Position | 7L | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | LTCMechanism | 834-1 | LTC Counter Readings | LTC Min Tap Position | 16L | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | LTCMechanism | 834-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | LTCMechanism | 834-1 | LTC Counter Readings | LTC Operations Since Last Insp | 327 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | LTCMechanism | 834-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | LTCMechanism | 834-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | LTCMechanism | 834-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Maintenance Operations | 16 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Operations Counter AF | 163 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Operations Counter AL | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Operations This Read Vac | 17 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Switching Operations | 1 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | CH000333 | ControlHouse | 463-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | 9 Month Operations | 16 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002045 | BreakerVacuum | 463-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Readings | Totalizer Meter Reading | .4140 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | S0030 | WithLTC | 413-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 7 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | General Comments | counters entered wrong ast check. Can not read B phase counter on circuit 0220 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | Operations Counter | 0 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | CX0124 | RecloserHydraulic | 595-0220 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Switching Operations | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | 9 Month Operations | 21 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Amps A Ø | 408.0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Amps B Ø | 439.0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Amps C Ø | 398.0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | LTCMechanism | 834-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | LTCMechanism | 834-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | LTCMechanism | 834-1 | LTC Counter Readings | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | LTCMechanism | 834-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK002044 | BreakerVacuum | 463-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 8874 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.1 | volts |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Min Tap Position | 13L | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | General Comments | no spare fuses | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 11342 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.4 | volts |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 10823 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.2 | volts |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Readings | Amps C Ø | 117.0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Readings | Amps B Ø | 101.0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Readings | Amps A Ø | 87.0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Max Tap Position | 1L | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Readings | 9 Month Operations | 2 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000088 | Regulator | 731-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Amps C Ø | 9.0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Amps B Ø | 20.0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Amps A Ø | 12.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | 9 Month Operations | 3 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | FE000536 | Fence | 834-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | FE000536 | Fence | 834-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | FE000536 | Fence | 834-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | FE000536 | Fence | 834-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | FE000536 | Fence | 834-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | FE000536 | Fence | 834-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | FE000536 | Fence | 834-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | FE000536 | Fence | 834-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | FE000536 | Fence | 834-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | FE000536 | Fence | 834-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | FE000536 | Fence | 834-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | FE000536 | Fence | 834-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | FE000536 | Fence | 834-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | FE000536 | Fence | 834-Fence | Fence Patrol Inspection | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | FE000536 | Fence | 834-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | FE000536 | Fence | 834-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | YD000541 | Yard | 834-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | YD000541 | Yard | 834-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | YD000541 | Yard | 834-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | YD000541 | Yard | 834-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | YD000541 | Yard | 834-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000087 | Regulator | 731-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Counter Readings | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Counter Readings | LTC As Found Counter | 69038 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Counter Readings | LTC As Left Counter | 69038 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Counter Readings | LTC Operations Since Last Insp | 275 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | LTCMechanism | 463-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Switching Operations | 1 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Operations This Read Vac | 1 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Operations Counter AL | 164 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Operations Counter AF | 163 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Readings | General Comments | | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001594 | BreakerVacuum | 731-2102 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Readings | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | General Comments | | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000223 | Switchgear | 516-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000223 | Switchgear | 516-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000223 | Switchgear | 516-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000223 | Switchgear | 516-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000223 | Switchgear | 516-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | ST000354 | Structure | 832-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000223 | Switchgear | 516-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000223 | Switchgear | 516-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000223 | Switchgear | 516-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | 9 Month Operations | 5 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Readings | Totalizer Meter Reading | .6252 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | C0351 | WithLTC | 834-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | C0481 | NonLTC | 848-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000223 | Switchgear | 516-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000223 | Switchgear | 516-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000223 | Switchgear | 516-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000223 | Switchgear | 516-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000223 | Switchgear | 516-Swgr Sec 2 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000223 | Switchgear | 516-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000223 | Switchgear | 516-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000223 | Switchgear | 516-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000223 | Switchgear | 516-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Readings | General Comments | | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Readings | LTC Totalizer Reading | 4780.80 | kw |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Readings | Oil Temp Max | 34 | °C |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Readings | Totalizer Meter Reading | .9960 | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | M0097 | WithLTC | 744-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Readings | Switching Operations | 1 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Readings | Operations This Read Vac | 1 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Readings | Operations Counter AL | 180 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Readings | Operations Counter AF | 179 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000223 | Switchgear | 516-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | LTCMechanism | 834-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | LTCMechanism | 834-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | General Comments | | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Operations Counter AF | 45 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Operations Counter AL | 49 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Operations This Read Vac | 4 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | LTCMechanism | 834-2 | LTC Counter Readings | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | LTCMechanism | 834-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | LTCMechanism | 834-2 | LTC Counter Readings | LTC As Found Counter | 148636 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | LTCMechanism | 834-2 | LTC Counter Readings | LTC As Left Counter | 148636 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | LTCMechanism | 834-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | LTCMechanism | 834-2 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | LTCMechanism | 834-2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | LTCMechanism | 834-2 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | LTCMechanism | 834-2 | LTC Counter Readings | LTC Operations Since Last Insp | 432 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | LTCMechanism | 834-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | LTCMechanism | 834-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | B0427 | LTCMechanism | 834-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Switching Operations | 4 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | MB0175 | BreakerVacuum | 835-0223 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | FE000388 | Fence | 463-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | RG000089 | Regulator | 731-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Amps A Ø | 108.0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Amps B Ø | 103.0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Amps C Ø | 100.0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Operations Counter AF | 180 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Operations Counter AL | 182 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Operations This Read Vac | 2 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BK001805 | BreakerVacuum | 463-0056 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000223 | Switchgear | 516-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK001611 | BreakerVacuum | 834-2114 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | YD000351 | Yard | 832-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | YD000351 | Yard | 832-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | YD000351 | Yard | 832-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | YD000351 | Yard | 832-Yard | Yard Patrol Inspection | General Comments | | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | YD000351 | Yard | 832-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | YD000351 | Yard | 832-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | YD000351 | Yard | 832-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | YD000351 | Yard | 832-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | YD000351 | Yard | 832-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | YD000351 | Yard | 832-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | YD000351 | Yard | 832-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | YD000351 | Yard | 832-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | YD000351 | Yard | 832-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | General Comments | | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Operations Counter AF | 161 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Operations Counter AL | 162 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Operations This Read Vac | 1 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Switching Operations | 1 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Readings | Switching Operations | 4 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Readings | Operations This Read Vac | 4 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Readings | Operations Counter AL | 228 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Readings | Operations Counter AF | 224 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Readings | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Readings | General Comments | Display is still not working | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Readings | LTC Totalizer Reading | 0.00 | kw |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Readings | Totalizer Meter Reading | .8510 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Readings | Winding Temp Max | 45 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Counter Readings | LTC Operations Since Last Insp | 552 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Counter Readings | LTC Max Tap Position | 5L | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Counter Readings | LTC Current Tap Position | 10L | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Counter Readings | LTC As Left Counter | 214158 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Counter Readings | LTC As Found Counter | 214158 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Counter Readings | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | LTCMechanism | 509-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | 9 Month Operations | 8 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Amps A Ø | 85.0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Amps B Ø | 87.0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Amps C Ø | 77.0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000798 | BreakerVacuum | 848-0154 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Amps C Ø | 54.0 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Amps B Ø | 62.0 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Amps A Ø | 74.0 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | 9 Month Operations VCB New | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | LTCC000859 | LTCControl | 463-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | LTCC000859 | LTCControl | 463-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | 9 Month Operations | 1 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Readings | Amps C Ø | 120.0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Readings | Amps B Ø | 130.0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Readings | Amps A Ø | 120.0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0165 | BreakerVacuum | 834-2113 | VCB Readings | 9 Month Operations | 10 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BCH001561 | Charger | 832-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BCH001561 | Charger | 832-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BCH001561 | Charger | 832-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BCH001561 | Charger | 832-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BCH001561 | Charger | 832-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.0 | amps |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BCH001561 | Charger | 832-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BCH001561 | Charger | 832-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | BCH001561 | Charger | 832-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Readings | 9 Month Operations | 13 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Readings | 9 Month Operations VCB New | 13 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Switching Operations | 1 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Operations This Read Vac | 1 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Operations Counter AL | 280 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Operations Counter AF | 279 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | CB0291 | BreakerVacuum | 726-0768 | VCB Readings | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Readings | Amps A Ø | 276.0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Readings | Amps B Ø | 264.0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Readings | Amps C Ø | 280.0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | LTCC000859 | LTCControl | 463-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Readings | Amps C Ø | 97.0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Readings | Amps B Ø | 77.0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Readings | Amps A Ø | 70.0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Readings | 9 Month Operations VCB New | 12 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Readings | 9 Month Operations | 13 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Readings | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Readings | LTC Totalizer Reading | 20424.00 | kw |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Readings | Amps C Ø | 64.0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Readings | Amps B Ø | 73.0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Readings | Amps A Ø | 65.0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Readings | 9 Month Operations VCB New | 13 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Readings | 9 Month Operations | 14 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Readings | Switching Operations | 1 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Readings | Operations This Read Vac | 1 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Readings | Operations Counter AL | 189 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Readings | Operations Counter AF | 188 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Readings | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000531 | BreakerVacuum | 834-2111 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Counter Readings | LTC As Left Counter | 54212 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Counter Readings | LTC Min Tap Position | 2L | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Counter Readings | LTC Operations Since Last Insp | 334 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Counter Readings | Reset Tap Drag Hands | Unable to Reset | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | General Comments | | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Operations Counter AF | 225 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Operations Counter AL | 226 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Operations This Read Vac | 1 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Switching Operations | 1 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Counter Readings | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Counter Readings | LTC As Found Counter | 78473 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Counter Readings | LTC As Left Counter | 78473 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Counter Readings | LTC Operations Since Last Insp | 442 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | LTCMechanism | 463-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | B0368 | WithLTC | 509-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Readings | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Readings | Operations Counter AF | 201 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Readings | Operations Counter AL | 202 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Readings | Operations This Read Vac | 1 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Readings | Switching Operations | 1 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK000532 | BreakerVacuum | 834-2112 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Counter Readings | General Comments | | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | B0397 | LTCMechanism | 526-1 | LTC Counter Readings | LTC As Found Counter | 54212 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | 9 Month Operations | 22 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | 9 Month Operations VCB New | 21 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Amps A Ø | 64.0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Amps B Ø | 60.0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Amps C Ø | 61.0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK000081 | BreakerVacuum | 848-0155 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Readings | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Readings | LTC Totalizer Reading | 32544.00 | kw |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.6 | volts |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 188793 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | General Comments | | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | General Comments | no spare fuses | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | ST000551 | Structure | 731-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | 9 Month Operations | 2 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BCH001559 | Charger | 526-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BCH001559 | Charger | 526-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 201824 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.7 | volts |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Current Tap Position | 14L | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BCH001559 | Charger | 526-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.8 | amps |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BCH001559 | Charger | 526-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BCH001559 | Charger | 526-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BCH001559 | Charger | 526-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | 9 Month Operations VCB New | 14 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Amps A Ø | 315.0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Amps B Ø | 300.0 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | Amps C Ø | 275.0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | General Comments | | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | FE000537 | Fence | 835-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Readings | Totalizer Meter Reading | 1.3560 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Readings | Winding Temp Max | 65 | °C |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 135.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Counter Readings | LTC Operations Since Last Insp | 493 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Counter Readings | LTC As Left Counter | 41113 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Counter Readings | LTC As Found Counter | 41113 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Counter Readings | General Comments | | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | B0402 | LTCMechanism | 832-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | FE000492 | Fence | 413-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0802 | Regulator | 848-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | KB0050 | BreakerVacuum | 526-1 | VCB Readings | 9 Month Operations | 14 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BCH001559 | Charger | 526-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BCH001559 | Charger | 526-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Amps B Ø | 18.0 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Amps C Ø | 18.0 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | General Comments | | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Operations Counter AF | 161 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Operations Counter AL | 162 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Operations This Read Vac | 1 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Switching Operations | 1 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | LTCC000859 | LTCControl | 463-1 | LTC Control Insp | All Connections OK? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Amps C Ø | 75.0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Amps B Ø | 85.0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Amps A Ø | 80.0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Readings | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | LTCC000859 | LTCControl | 463-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | LTCC000859 | LTCControl | 463-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | LTCC000859 | LTCControl | 463-1 | LTC Control Insp | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Readings | Operations Counter AF | 179 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Readings | Operations Counter AL | 179 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Readings | Switching Operations | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | BK002038 | BreakerVacuum | 834-2 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Operations This Read Vac | 2 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | LTCC000859 | LTCControl | 463-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Operations Counter AL | 223 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Operations Counter AF | 221 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | General Comments | | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | 9 Month Operations | 2 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | BK000113 | BreakerVacuum | 835-0173 | VCB Readings | Amps A Ø | 17.0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | Ambient Temp | 54 | °F |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | General Comments | | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Operations Counter AF | 219 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Operations Counter AL | 220 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Operations This Read Vac | 1 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Switching Operations | 1 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R0804 | Regulator | 726-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0400 | WithLTC | 463-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Amps C Ø | 198.0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Amps B Ø | 168.0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Amps A Ø | 176.0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | YD000548 | Yard | 731-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Operations This Read Vac | 2 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Operations Counter AL | 682 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Operations Counter AF | 680 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 7:02 | Distribution | Belt Line Quarterly Inspection | BK001254 | BreakerVacuum | 526-0036 | VCB Readings | 9 Month Operations | 11 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Readings | Winding Temp Max | 65 | °C |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | B0451 | WithLTC | 463-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | 9 Month Operations | 1 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | BB0401 | BreakerVacuum | 463-0101 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Amps A Ø | 30.0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Amps B Ø | 35.0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Readings | Amps C Ø | 35.0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | BK001431 | BreakerVacuum | 848-0156 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Patrol Inspection | Ambient Temperature | 60 | °F |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Operations Counter AF | 164 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Operations Counter AL | 164 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Switching Operations | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Counter Readings | LTC Operations Since Last Insp | 224 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 19 | °C |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 30 | °C |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Counter Readings | LTC As Left Counter | 11648 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Counter Readings | LTC As Found Counter | 11648 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Counter Readings | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCM000088 | LTCMechanism | 509-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Patrol Inspection | General Comments | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Readings | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Readings | Fault Operations | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCC000815 | LTCControl | 509-1 | LTC Control Insp | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Patrol Inspection | Ambient Temperature | 60 | °F |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCC000815 | LTCControl | 509-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCC000815 | LTCControl | 509-1 | LTC Control Insp | All Connections OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | LTCC000812 | LTCControl | 463-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | LTCC000812 | LTCControl | 463-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | LTCC000812 | LTCControl | 463-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | LTCC000812 | LTCControl | 463-2 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | LTCC000812 | LTCControl | 463-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | LTCC000812 | LTCControl | 463-2 | LTC Control Insp | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | LTCC000812 | LTCControl | 463-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | LTCC000812 | LTCControl | 463-2 | LTC Control Insp | All Connections OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Readings | Unknown Operations | 0 | |
| 1/20/2023 11:44 | Distribution | Beargrass Quarterly Inspection | PF000017 | PowerFuse | BG-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/20/2023 11:44 | Distribution | Beargrass Quarterly Inspection | PF000017 | PowerFuse | BG-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/20/2023 11:44 | Distribution | Beargrass Quarterly Inspection | PF000017 | PowerFuse | BG-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Readings | Switching Operations | 1 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Patrol Inspection | SF6 Pressure | 67 | psi |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Readings | Operations This Read SF6 | 1 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Readings | Operations Counter AL | 181 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Readings | Operations Counter AF | 181 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Readings | Num Operations Last 9 Months | 1 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Patrol Inspection | General Comments | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Readings | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Readings | Fault Operations | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001509 | BreakerSF6 | 516-618 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 86138 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 122.3 | volts |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | n | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Readings | Winding Temp Present | 28 | °C |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Readings | Totalizer Meter Reading | .2922 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Readings | Oil Temp Present | 27 | °C |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | 9 Month Operations | 4 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Amps A Ø | 35.0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Amps B Ø | 42.0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Amps C Ø | 51.0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | 9 Month Operations | 1 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Amps A Ø | 230.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Amps B Ø | 220.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Readings | 9 Month Operations | 5 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Readings | Amps A Ø | 48.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Readings | Amps B Ø | 56.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Amps C Ø | 240.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Readings | Oil Temp Max | 39 | °C |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001736 | BreakerVacuum | 516-Offline Distribution | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001736 | BreakerVacuum | 516-Offline Distribution | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001736 | BreakerVacuum | 516-Offline Distribution | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001736 | BreakerVacuum | 516-Offline Distribution | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001736 | BreakerVacuum | 516-Offline Distribution | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001736 | BreakerVacuum | 516-Offline Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001736 | BreakerVacuum | 516-Offline Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001736 | BreakerVacuum | 516-Offline Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001736 | BreakerVacuum | 516-Offline Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001736 | BreakerVacuum | 516-Offline Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001736 | BreakerVacuum | 516-Offline Distribution | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001736 | BreakerVacuum | 516-Offline Distribution | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001736 | BreakerVacuum | 516-Offline Distribution | VCB Readings | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001736 | BreakerVacuum | 516-Offline Distribution | VCB Readings | Operations Counter AF | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001736 | BreakerVacuum | 516-Offline Distribution | VCB Readings | Operations Counter AL | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001736 | BreakerVacuum | 516-Offline Distribution | VCB Readings | Operations This Read Vac | 0 | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 79825 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 9:34 | Distribution | Stanford North Quarterly Inspection | R1307 | Regulator | 726-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | General Comments | there is not a spill kit here . there is not a berm here. | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Readings | Winding Temp Present | 25 | °C |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Readings | Winding Temp Max | 45 | °C |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .6900 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Readings | Oil Temp Max | 30 | °C |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 6624.00 | kw |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Readings | General Comments | | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | KT0033 | NonLTC | 731-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Readings | Amps C Ø | 46.0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Readings | Amps B Ø | 60.0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Readings | Amps A Ø | 56.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Readings | Amps C Ø | 257.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Readings | Amps B Ø | 259.0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Readings | 9 Month Operations VCB New | 23 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Readings | 9 Month Operations | 24 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Readings | Operations Counter AF | 104 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Readings | Operations Counter AL | 106 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Readings | Operations This Read Vac | 2 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Readings | Switching Operations | 2 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Readings | Amps A Ø | 248.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Readings | 9 Month Operations | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Operations Counter AF | 200 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Operations Counter AL | 202 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Operations This Read Vac | 2 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | Ambient Temp | 63 | °F |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | YD000498 | Yard | 413-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | 9 Month Operations | 4 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Amps A Ø | 175.0 | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 10:45 | Distribution | Stanford Quarterly Inspection | R0831 | Regulator | 848-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Readings | Operations Counter AF | 99980 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Readings | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Readings | Switching Operations | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000964 | BreakerSF6 | 509-618 | GCB Readings | Unknown Operations | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | CB0283 | BreakerVacuum | 834-2115 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001560 | BreakerVacuum | 516-1101 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Readings | 9 Month Operations | 4 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Readings | Amps A Ø | 28.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Readings | Amps B Ø | 24.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Readings | Amps C Ø | 23.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001546 | BreakerVacuum | 516-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | 9 Month Operations | 4 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Amps A Ø | 105.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Amps B Ø | 100.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Amps C Ø | 110.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000965 | BreakerVacuum | 509-0199 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Readings | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001561 | BreakerVacuum | 516-1102 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001735 | BreakerVacuum | 516-Offline Distribution | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001735 | BreakerVacuum | 516-Offline Distribution | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001735 | BreakerVacuum | 516-Offline Distribution | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001735 | BreakerVacuum | 516-Offline Distribution | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001735 | BreakerVacuum | 516-Offline Distribution | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001735 | BreakerVacuum | 516-Offline Distribution | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001735 | BreakerVacuum | 516-Offline Distribution | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001735 | BreakerVacuum | 516-Offline Distribution | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001735 | BreakerVacuum | 516-Offline Distribution | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001735 | BreakerVacuum | 516-Offline Distribution | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001735 | BreakerVacuum | 516-Offline Distribution | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001735 | BreakerVacuum | 516-Offline Distribution | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001735 | BreakerVacuum | 516-Offline Distribution | VCB Readings | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001735 | BreakerVacuum | 516-Offline Distribution | VCB Readings | Operations Counter AF | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001735 | BreakerVacuum | 516-Offline Distribution | VCB Readings | Operations Counter AL | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001735 | BreakerVacuum | 516-Offline Distribution | VCB Readings | Operations This Read Vac | 0 | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Readings | Switching Operations | 1 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Patrol Inspection | SF6 Pressure | 67 | psi |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Readings | Operations This Read SF6 | 1 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Readings | Operations Counter AL | 110 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Readings | Operations Counter AF | 110 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCC000815 | LTCControl | 509-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | General Comments | | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | YD000459 | Yard | 744-Yard | Yard Patrol Inspection | Ambient Temp | 59 | °F |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Readings | Num Operations Last 9 Months | 1 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCC000815 | LTCControl | 509-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | General Comments | | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | FE000453 | Fence | 744-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | 9 Month Operations | 1 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Amps A Ø | 330.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Amps B Ø | 320.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Readings | Amps C Ø | 350.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000966 | BreakerVacuum | 509-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Amps B Ø | 169.0 | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | ST000546 | Structure | 835-Structure | Structure Patrol Inspection | General Comments | | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Amps C Ø | 179.0 | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCC000815 | LTCControl | 509-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCC000815 | LTCControl | 509-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | LTCC000815 | LTCControl | 509-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/19/2023 9:16 | Distribution | Mackville Quarterly Inspection | R0600 | Regulator | 595-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001511 | BreakerSF6 | 516-628 | GCB Readings | Unknown Operations | 0 | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Interruptrs/Puffrs Visual OK? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/19/2023 11:37 | Distribution | Shelby City Quarterly Inspection | ST000461 | Structure | 744-Structure | Structure Patrol Inspection | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Operations Counter AL | 202 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000222 | Switchgear | 516-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Readings | General Comments | | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000222 | Switchgear | 516-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | ST000545 | Structure | 834-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Operations Counter AF | 270 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Operations Counter AL | 272 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Operations This Read Vac | 2 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | General Comments | | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Operations Counter AF | 202 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | ST000545 | Structure | 834-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | ST000545 | Structure | 834-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | ST000545 | Structure | 834-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Amps A Ø | 136.0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Amps B Ø | 163.0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000222 | Switchgear | 516-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000222 | Switchgear | 516-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000222 | Switchgear | 516-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000222 | Switchgear | 516-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000222 | Switchgear | 516-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000222 | Switchgear | 516-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Operations Counter AF | 354 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Readings | Operations This Read Vac | 2 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000222 | Switchgear | 516-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000222 | Switchgear | 516-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000222 | Switchgear | 516-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000222 | Switchgear | 516-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000222 | Switchgear | 516-Swgr Sec 1 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Operations Counter AL | 356 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Operations This Read Vac | 2 | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | General Comments | | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | 9 Month Operations | 8 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000222 | Switchgear | 516-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000222 | Switchgear | 516-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000222 | Switchgear | 516-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Operations Counter AF | 205 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Operations Counter AL | 206 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000222 | Switchgear | 516-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 14:23 | Distribution | Vaksdahl Avenue Quarterly Inspection | ST000501 | Structure | 413-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | ST000545 | Structure | 834-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Switching Operations | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Readings | Amps C Ø | 160.0 | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | KB0112 | BreakerVacuum | 463-0188 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Operations This Read Vac | 1 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Readings | Amps C Ø | 55.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Amps C Ø | 0.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Amps B Ø | 0.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Amps A Ø | 0.0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000222 | Switchgear | 516-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | SWG000222 | Switchgear | 516-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | ST000545 | Structure | 834-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | ST000545 | Structure | 834-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | YD000541 | Yard | 834-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | YD000541 | Yard | 834-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | YD000541 | Yard | 834-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Switching Operations | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | YD000541 | Yard | 834-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | YD000541 | Yard | 834-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | YD000541 | Yard | 834-Yard | Yard Patrol Inspection | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | YD000541 | Yard | 834-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | YD000541 | Yard | 834-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | YD000541 | Yard | 834-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | YD000541 | Yard | 834-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1500 | psi |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | ST000545 | Structure | 834-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | ST000545 | Structure | 834-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | 9 Month Operations | 1 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Readings | General Comments | | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | ST000545 | Structure | 834-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | ST000545 | Structure | 834-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | ST000545 | Structure | 834-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | ST000545 | Structure | 834-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Operations Counter AL | 167 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Operations Counter AF | 167 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | ST000545 | Structure | 834-Structure | Structure Patrol Inspection | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000967 | BreakerVacuum | 509-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | ST000545 | Structure | 834-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | ST000545 | Structure | 834-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Readings | LTC Totalizer Reading | 7012.80 | kw |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | Ambient Temp | 61 | °F |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | ST000545 | Structure | 834-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | TX000217 | WithLTC | 509-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Readings | Switching Operations | 2 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Readings | Unknown Operations | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | ST000545 | Structure | 834-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Switching Operations | 1 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/19/2023 12:14 | Distribution | Donerail Quarterly Inspection | FE000859 | Fence | 832-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | ST000545 | Structure | 834-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | ST000545 | Structure | 834-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | ST000545 | Structure | 834-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Patrol Inspection | General Comments | | |
| 1/19/2023 12:11 | Distribution | Minor Farm Quarterly Inspection | YD000542 | Yard | 835-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Readings | Maintenance Operations | 0 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/19/2023 14:21 | Distribution | Danville East Quarterly Inspection | ST000545 | Structure | 834-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Readings | Operations Counter AF | 98 | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Readings | Operations Counter AL | 100 | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Patrol Inspection | Cabinet Patrol Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 15:25 | Distribution | Reynolds Quarterly Inspection | K0156 | BreakerVacuum | 463-0102 | VCB Readings | General Comments | | |
| 1/19/2023 13:48 | Distribution | Stonewall Quarterly Inspection | BK000968 | BreakerVacuum | 509-BT2-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/19/2023 10:00 | Distribution | West High Street Quarterly Inspection | BK001562 | BreakerVacuum | 516-1103 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/19/2023 10:55 | Distribution | Atoka Quarterly Inspection | BK001593 | BreakerVacuum | 731-2101 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Readings | LTC Totalizer Reading | 5913.60 | kw |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BCH001311 | Charger | 874-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.9 | VDC |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | three fans not working, needs nitro bottle filled | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BCH001311 | Charger | 874-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.9 | VDC |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BCH001311 | Charger | 874-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BCH001311 | Charger | 874-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BCH001311 | Charger | 874-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BCH001311 | Charger | 874-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BCH001311 | Charger | 874-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 50 | °C |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 35 | °C |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Amps A Ø | 100.0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Amps B Ø | 120.0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Amps C Ø | 100.0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | Top Oil Temperature Present | 23 | °C |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | Top Oil Temperature Max | 35 | °C |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 600 | psi |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | LTC Totalizer Reading | 4500.00 | kw |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Amps C Ø | 134.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Amps B Ø | 117.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Amps A Ø | 130.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | 9 Month Operations | 6 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Amps B Ø | 76.0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BCH001311 | Charger | 874-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Readings | Oil Temp Present | 50 | °C |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 55.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 45 | °C |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 35 | °C |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 10.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | Winding Temp Present | 23 | °C |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | Winding Temp Max | 35 | °C |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | Totalizer Meter Reading | 4.5000 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 1000 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Switching Operations | 6 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Operations This Read Vac | 6 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Operations Counter AL | 23 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Operations Counter AF | 23 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | 9 Month Operations | 4 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Readings | General Comments | | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | Ambient Temp | 65 | °F |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | 9 Month Operations | 6 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Amps A Ø | 76.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002204 | BreakerVacuum | HC-1293 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 50 | °C |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 30 | °C |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Min Tap Position | 15L | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Readings | General Comments | | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Readings | LTC Totalizer Reading | 6408.00 | kw |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 83980 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Counter Readings | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Readings | Oil Temp Present | 50 | °C |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Counter Readings | LTC As Left Counter | 11826 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Counter Readings | LTC As Found Counter | 11826 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Fault Adjusted Amps B Phase V | 4.69 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Fault Operations B Ø | 1 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Operations This Read Vac | 3 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Operations Counter AL | 28 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Operations Counter AF | 28 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Operations Counter AF | 227 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Operations Counter AL | 229 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Operations This Read Vac | 3 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Switching Operations | 2 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | LTCC000902 | LTCControl | 826-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Switching Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Operations This Read Vac | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Operations Counter AL | 265 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Operations Counter AF | 265 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Operations Counter AF | 50 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Amps C Ø | 53.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Amps B Ø | 56.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Amps A Ø | 56.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Operations Counter AL | 50 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Operations This Read Vac | 12 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK000267 | BreakerVacuum | HC-1435 | VCB Readings | 9 Month Operations | 3 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | X1 Winding Temp Max | 35 | °C |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Switching Operations | 12 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Readings | General Comments | | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Readings | Totalizer Meter Reading | 1.3350 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Amps A Ø | 63.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Amps B Ø | 66.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Amps C Ø | 89.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Amps B Ø | 78.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Amps A Ø | 101.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Amps C Ø | 85.0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | 9 Month Operations | 3 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | X3 Winding Temp Present | 23 | °C |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | X3 Winding Temp Max | 35 | °C |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | X2 Winding Temp Present | 23 | °C |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | X2 Winding Temp Max | 35 | °C |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | X1 Winding Temp Present | 23 | °C |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | WithLTC | HC-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Readings | Totalizer Meter Reading | .6160 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | SF6 Pressure | 88 | psi |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Readings | Switching Operations | 0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Switching Operations | 2 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Operations This Read Vac | 2 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Operations Counter AL | 268 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Operations Counter AF | 266 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Readings | Totalizer Meter Reading | .7428 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Readings | Switching Operations | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | UG Pothead Condition Good? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | BCH001312 | Charger | 826-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | BCH001312 | Charger | 826-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | BCH001312 | Charger | 826-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | BCH001312 | Charger | 826-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .9 | amps |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | BCH001312 | Charger | 826-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | BCH001312 | Charger | 826-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | BCH001312 | Charger | 826-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Readings | Operations Counter AL | 68 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Readings | Operations This Read SF6 | 0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Readings | Totalizer Meter Reading | .3100 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 10.00 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Operations Counter AL | 268 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Operations Counter AF | 266 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Switching Operations | 2 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Operations This Read Vac | 2 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Operations Counter AL | 230 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Operations Counter AF | 228 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Readings | Totalizer Meter Reading | .5028 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Switching Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Operations Counter AL | 32 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Operations Counter AF | 32 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | BCH001312 | Charger | 826-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Operations Counter AL | 50 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Operations Counter AF | 50 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Amps C Ø | 284.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Amps B Ø | 294.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Amps A Ø | 290.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001985 | BreakerVacuum | HC-14KV TR 1 | VCB Readings | 9 Month Operations | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Switching Operations | 2 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Operations This Read Vac | 2 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Readings | Fault Operations | 0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | LTCC000902 | LTCControl | 826-2 | LTC Control Insp | General Comments | | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | LTCC000902 | LTCControl | 826-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | LTCC000902 | LTCControl | 826-2 | LTC Control Insp | All Connections OK? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | General Comments | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Switching Operations | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Operations Counter AL | 209 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Operations Counter AF | 209 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Amps C Ø | 523.0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Amps B Ø | 630.0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Amps A Ø | 611.0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0044 | BreakerVacuum | 428-1 | VCB Readings | 9 Month Operations | 2 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Readings | General Comments | | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | General Comments | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Amps C Ø | 82.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | Ambient Temperature | 40 | °F |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | TX000137 | WithLTC | 428-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Readings | General Comments | | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Readings | LTC Totalizer Reading | 2232.00 | kw |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Readings | Operations Counter AF | 71 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | ST000643 | Structure | HC-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Readings | Operations Counter AL | 71 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Readings | Operations This Read SF6 | 0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | SF6 Pressure Indicator | good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Readings | General Comments | | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Readings | LTC Totalizer Reading | 7130.88 | kw |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | WithLTC | 874-1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BK001268 | BreakerSF6 | 874-708 | GCB Readings | Operations Counter AF | 68 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Operations Counter AF | 91 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Operations Counter AL | 95 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Operations This Read Vac | 4 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Switching Operations | 4 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0194 | BreakerVacuum | 874-0219 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Operations Counter AF | 19 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Operations Counter AL | 19 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Operations This Read Vac | 6 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Switching Operations | 6 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002203 | BreakerVacuum | HC-1292 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Regulator As Left Counter | 22599 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.3 | volts |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Operations Counter AF | 13 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Operations Counter AL | 13 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Restroom Clean & OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | General Comments | | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | 9 Month Operations | 5 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Amps A Ø | 203.0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Amps B Ø | 210.0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Amps C Ø | 222.0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | General Comments | | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Operations Counter AF | 37 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Operations Counter AL | 37 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Operations This Read Vac | 6 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Switching Operations | 6 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Operations This Read Vac | 4 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Operations Counter AL | 30 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Amps B Ø | 236.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Regulator As Left Counter | 23534 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.2 | volts |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Amps C Ø | 194.0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | 9 Month Operations | 4 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Amps A Ø | 60.0 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Amps B Ø | 60.0 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Amps C Ø | 70.0 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | 9 Month Operations | 2 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | BAT001384 | Battery | 826-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | BAT001384 | Battery | 826-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | BAT001384 | Battery | 826-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Operations Counter AF | 26 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | General Comments | | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.5 | volts |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Amps A Ø | 226.0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Operations Counter AF | 250 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Operations Counter AL | 252 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Operations This Read Vac | 2 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Switching Operations | 2 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | BAT001384 | Battery | 826-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | BAT001384 | Battery | 826-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | BAT001384 | Battery | 826-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Switching Operations | 1 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Operations This Read Vac | 1 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Operations Counter AL | 306 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Operations Counter AF | 305 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | LTCC000904 | LTCControl | 788-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | LTCC000904 | LTCControl | 788-2 | LTC Control Insp | General Comments | | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | LTCC000904 | LTCControl | 788-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | LTCC000904 | LTCControl | 788-2 | LTC Control Insp | LTC Output Voltage Level | 124.2 | VAC |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | BAT001384 | Battery | 826-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | BAT001384 | Battery | 826-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | LTCC000904 | LTCControl | 788-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | LTCC000904 | LTCControl | 788-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | BAT001384 | Battery | 826-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | BAT001384 | Battery | 826-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | General Comments | | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | 9 Month Operations | 1 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 65.0 | VDC |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 68.0 | VDC |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Amps C Ø | 580.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Amps B Ø | 505.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Amps A Ø | 544.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | 9 Month Operations | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | PF000166 | PowerFuse | HC-14KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | PF000166 | PowerFuse | HC-14KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | PF000166 | PowerFuse | HC-14KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | PF000168 | PowerFuse | HC-STA SER NO 2 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | PF000168 | PowerFuse | HC-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | PF000168 | PowerFuse | HC-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | PF000169 | PowerFuse | HC-12KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | PF000169 | PowerFuse | HC-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Min Tap Position | 15L | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | PF000169 | PowerFuse | HC-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002207 | BreakerVacuum | HC-12KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | 9 Month Operations VCB New | 31 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Amps A Ø | 183.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Amps B Ø | 182.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Amps C Ø | 190.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | ST000538 | Structure | 874-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Amps A Ø | 272.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000032 | Switchgear | HC-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Amps B Ø | 275.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | Amps C Ø | 280.0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Switching Operations | 4 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Operations Counter | 1432 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Amps C Ø | 70.0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Amps B Ø | 70.0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0116 | RecloserElectronic | 826-2226 | Recloser Electronic Patrol Inspection | Amps A Ø | 60.0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | LTCC000904 | LTCControl | 788-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | LTCC000904 | LTCControl | 788-2 | LTC Control Insp | All Connections OK? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 66 | °F |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | BAT001383 | Battery | 874-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002201 | BreakerVacuum | HC-1290 | VCB Readings | 9 Month Operations | 37 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0006 | BreakerVacuum | 427-2207 | VCB Readings | 9 Month Operations | 2 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BAT001489 | Battery | 788-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BAT001489 | Battery | 788-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BAT001489 | Battery | 788-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BAT001489 | Battery | 788-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BAT001489 | Battery | 788-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BAT001489 | Battery | 788-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Ambient Temperature | 40 | °F |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Amps B Ø | 75.0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCC000726 | LTCControl | 428-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCC000726 | LTCControl | 428-2 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCC000726 | LTCControl | 428-2 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | Kwh Reading | 52903 | KwH |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | LTC Totalizer Reading | 6700.00 | kw |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | MegaVar Demand Meter Max | 1.00 | MegaVars |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Amps A Ø | 91.0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | 9 Month Operations | 2 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Operations Counter AF | 241 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Operations Counter AL | 242 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Operations This Read Vac | 1 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Switching Operations | 1 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BAT001489 | Battery | 788-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BAT001489 | Battery | 788-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BAT001489 | Battery | 788-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BAT001489 | Battery | 788-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | General Comments | | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BAT001489 | Battery | 788-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BAT001489 | Battery | 788-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | 9 Month Operations | 4 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Readings | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | 9 Month Operations | 12 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | LTCC000902 | LTCControl | 826-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | LTCC000902 | LTCControl | 826-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | LTCC000902 | LTCControl | 826-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | LTCC000902 | LTCControl | 826-2 | LTC Control Insp | LTC Output Voltage Level | 124.5 | VAC |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 100.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | X1 Winding Temp Max | 30 | °C |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | X1 Winding Temp Present | 20 | °C |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | X2 Winding Temp Max | 30 | °C |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCC000726 | LTCControl | 428-2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCC000726 | LTCControl | 428-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCC000726 | LTCControl | 428-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCC000726 | LTCControl | 428-2 | LTC Control Insp | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | X2 Winding Temp Present | 20 | °C |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | X3 Winding Temp Max | 30 | °C |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | X3 Winding Temp Present | 20 | °C |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCC000726 | LTCControl | 428-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCC000726 | LTCControl | 428-2 | LTC Control Insp | All Connections OK? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Counter Readings | LTC Operations Since Last Insp | 844 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 20 | °C |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 30 | °C |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Operations Counter AF | 740 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Operations Counter AL | 744 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Operations This Read Vac | 4 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Switching Operations | 4 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | CB0234 | BreakerVacuum | 719-2236 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002202 | BreakerVacuum | HC-1291 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK002205 | BreakerVacuum | HC-1294 | VCB Readings | Switching Operations | 3 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1511 | Regulator | 427-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCM000066 | LTCMechanism | 428-2 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Readings | Fault Operations | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | FE000866 | Fence | 788-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | WithLTC | 719-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | General Comments | | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000126 | Regulator | 427-2 C | Regulator Patrol Inspection | Regulator As Left Counter | 21239 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | Top Oil Temperature Max | 25 | °C |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | Top Oil Temperature Present | 25 | °C |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 1000 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | Totalizer Meter Reading | 6.7000 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Amps A Ø | 162.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Amps B Ø | 189.0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0073 | BreakerVacuum | 428-0596 | VCB Readings | Amps C Ø | 159.0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | Winding Temp Max | 30 | °C |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | Winding Temp Present | 20 | °C |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000603 | BreakerSF6 | 427-618 | GCB Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | WithLTC | 826-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | General Comments | | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | YD000422 | Yard | 826-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | CH000153 | ControlHouse | HC-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Amps A Ø | 54.0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Amps C Ø | 180.0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Amps B Ø | 200.0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Amps A Ø | 170.0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0276 | BreakerVacuum | 874-2235 | VCB Readings | 9 Month Operations | 4 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BCH001208 | Charger | HC-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BCH001208 | Charger | HC-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BCH001208 | Charger | HC-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BCH001208 | Charger | HC-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 8.5 | amps |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BCH001208 | Charger | HC-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BCH001208 | Charger | HC-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BCH001208 | Charger | HC-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BCH001420 | Charger | 788-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BCH001420 | Charger | 788-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BCH001420 | Charger | 788-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BCH001420 | Charger | 788-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BCH001420 | Charger | 788-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.5 | amps |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BCH001420 | Charger | 788-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Operations Counter AF | 257 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Operations Counter AL | 258 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Operations This Read Vac | 1 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Operations Counter AF | 216 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Operations Counter AL | 218 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Operations This Read Vac | 2 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Switching Operations | 2 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0046 | BreakerVacuum | 428-0592 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | ST000424 | Structure | 826-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000125 | Regulator | 427-2 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BAT001257 | Battery | HC-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | WithLTC | 826-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | RG000124 | Regulator | 427-2 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CH000395 | ControlHouse | 874-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | BAT001384 | Battery | 826-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Readings | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 7075.20 | kw |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | S0027 | NonLTC | 427-2 | NonLTC Transformer Readings | Totalizer Meter Reading | .7370 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | WithLTC | 428-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0047 | BreakerVacuum | 428-0591 | VCB Readings | Amps C Ø | 84.0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | BAT001384 | Battery | 826-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BCH001420 | Charger | 788-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BCH001420 | Charger | 788-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Switching Operations | 1 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000636 | BreakerVacuum | 427-2240 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | 9 Month Operations | 1 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Amps A Ø | 100.0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Amps B Ø | 96.0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Amps C Ø | 97.0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | SWG000030 | Switchgear | HC-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | BAT001384 | Battery | 826-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | CH000414 | ControlHouse | 427-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BAT001489 | Battery | 788-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BK000637 | BreakerVacuum | 427-2241 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Amps B Ø | 51.0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Amps C Ø | 54.0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0037 | BreakerVacuum | 826-0224 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Amps C Ø | 0.0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Amps B Ø | 0.0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Amps A Ø | 0.0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | 9 Month Operations | 1 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | General Comments | | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Amps C Ø | 60.0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Amps B Ø | 40.0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Amps A Ø | 50.0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | 9 Month Operations | 10 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | General Comments | | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | LTCC000976 | LTCControl | 826-1 | LTC Control Insp | All Connections OK? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 33494 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Readings | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 6629.76 | kw |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .6906 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Readings | Winding Temp Max | 40 | °C |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Readings | Winding Temp Present | 30 | °C |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Switching Operations | 2 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Operations This Read Vac | 2 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Operations Counter AL | 241 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Operations Counter AF | 239 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KT0010 | NonLTC | 427-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Operations Counter AF | 219 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 125.3 | volts |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 1509 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1509 | Regulator | 427-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Min Tap Position | 13L | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | R1510 | Regulator | 427-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | LTCC000976 | LTCControl | 826-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Operations Counter AL | 219 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Switching Operations | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | LTCC000976 | LTCControl | 826-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | LTCC000976 | LTCControl | 826-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | LTCC000976 | LTCControl | 826-1 | LTC Control Insp | LTC Output Voltage Level | 125.1 | VAC |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | LTCC000976 | LTCControl | 826-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | LTCC000976 | LTCControl | 826-1 | LTC Control Insp | General Comments | | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | LTCC000976 | LTCControl | 826-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Counter Readings | LTC Operations Since Last Insp | 534 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Switching Operations | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Operations Counter AL | 162 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Amps C Ø | 197.0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Amps B Ø | 175.0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Amps A Ø | 200.0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | 9 Month Operations | 2 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Amps A Ø | 364.0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Amps B Ø | 392.0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Amps C Ø | 330.0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Ambient Temp | 39 | °F |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Amps C Ø | 155.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Amps B Ø | 160.0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Amps A Ø | 150.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | FE000661 | Fence | HC-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Switching Operations | 2 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Operations This Read Vac | 2 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Operations Counter AL | 387 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Operations Counter AF | 385 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Counter Readings | General Comments | | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Counter Readings | LTC As Found Counter | 23550 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Counter Readings | LTC As Left Counter | 23555 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0425 | LTCMechanism | 826-2 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Readings | General Comments | | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | K0038 | BreakerVacuum | 826-2225 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | 9 Month Operations | 2 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Switching Operations | 4 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Operations This Read Vac | 4 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Operations Counter AL | 251 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Operations Counter AF | 247 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Counter Readings | LTC Operations Since Last Insp | 376 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Counter Readings | LTC Min Tap Position | 15L | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Counter Readings | LTC Max Tap Position | 5L | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Counter Readings | LTC As Left Counter | 31251 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Counter Readings | LTC As Found Counter | 31247 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Counter Readings | General Comments | | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | LTCMechanism | 788-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | LTCC000981 | LTCControl | 719-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | LTCC000981 | LTCControl | 719-1 | LTC Control Insp | VRR Base Voltage AL | 123.0 | VAC |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | LTCC000981 | LTCControl | 719-1 | LTC Control Insp | VRR Base Voltage AF | 123.0 | VAC |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | LTCC000981 | LTCControl | 719-1 | LTC Control Insp | LTC Output Voltage Level | 123.2 | VAC |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | LTCC000981 | LTCControl | 719-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | LTCC000981 | LTCControl | 719-1 | LTC Control Insp | General Comments | | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | LTCC000981 | LTCControl | 719-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | LTCC000981 | LTCControl | 719-1 | LTC Control Insp | All Connections OK? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Switching Operations | 1 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Operations This Read Vac | 1 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Operations Counter AL | 293 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Operations Counter AF | 292 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | KB0005 | BreakerVacuum | 427-2206 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0076 | BreakerVacuum | 428-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Counter Readings | LTC Operations Since Last Insp | 502 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 17 | °C |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 20 | °C |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Counter Readings | LTC Max Tap Position | 5R | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Counter Readings | LTC Current Tap Position | 2R | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Counter Readings | LTC As Left Counter | 30515 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Counter Readings | LTC As Found Counter | 30515 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Counter Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KT0008 | LTCMechanism | 428-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Operations Counter AF | 162 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | ST000452 | Structure | 719-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | CB0193 | BreakerVacuum | 874-0218 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Counter Readings | General Comments | | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Counter Readings | LTC As Found Counter | 16038 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Counter Readings | LTC As Left Counter | 16042 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | General Comments | | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Operations Counter AF | 176 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Operations Counter AL | 177 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Operations This Read Vac | 1 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Switching Operations | 1 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Counter Readings | LTC Operations Since Last Insp | 493 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Switching Operations | 1 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | BCH001332 | Charger | 719-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | BCH001332 | Charger | 719-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | BCH001332 | Charger | 719-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | BCH001332 | Charger | 719-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | BCH001332 | Charger | 719-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | BCH001332 | Charger | 719-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | 9 Month Operations | 3 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 68 | °F |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BAT001167 | Battery | 427-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | 9 Month Operations | 3 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Amps A Ø | 69.0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Amps B Ø | 53.0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Readings | Amps C Ø | 61.0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001804 | BreakerVacuum | 788-2217 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 375 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | General Comments | | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Operations Counter AF | 284 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Operations Counter AL | 285 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Operations This Read Vac | 1 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Switching Operations | 1 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | ST000505 | Structure | 428-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BCH001115 | Charger | 427-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BCH001115 | Charger | 427-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BCH001115 | Charger | 427-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 3.7 | amps |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BCH001115 | Charger | 427-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BCH001115 | Charger | 427-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | BCH001115 | Charger | 427-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | General Comments | | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | C0494 | LTCMechanism | 874-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | 9 Month Operations | 2 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | 9 Month Operations | 3 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Amps A Ø | 136.0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Amps B Ø | 125.0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Amps C Ø | 142.0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Counter Readings | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | FE000496 | Fence | 428-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | YD000503 | Yard | 428-Yard | Yard Patrol Inspection | Ambient Temp | 40 | °F |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 105642 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | K0165 | BreakerVacuum | 788-2216 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0094 | LTCMechanism | HC-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 105642 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | General Comments | | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | PF000167 | PowerFuse | HC-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | PF000167 | PowerFuse | HC-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | YD000445 | Yard | 719-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | PF000167 | PowerFuse | HC-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | Ambient Temp | 40 | °F |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | LTCC000047 | LTCControl | 427-1 C | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | LTCC000047 | LTCControl | 427-1 C | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | LTCC000047 | LTCControl | 427-1 C | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | LTCC000047 | LTCControl | 427-1 C | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | LTCC000047 | LTCControl | 427-1 C | LTC Control Insp | LTC Output Voltage Level | 125.3 | VAC |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | LTCC000047 | LTCControl | 427-1 C | LTC Control Insp | LTC Operation Checked? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | LTCC000047 | LTCControl | 427-1 C | LTC Control Insp | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | LTCC000047 | LTCControl | 427-1 C | LTC Control Insp | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | LTCC000047 | LTCControl | 427-1 C | LTC Control Insp | All Connections OK? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Amps C Ø | 0.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | PF001312 | PowerFuse | HC-1431 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | PF001312 | PowerFuse | HC-1431 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | PF001312 | PowerFuse | HC-1431 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Amps B Ø | 0.0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Amps A Ø | 0.0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0045 | BreakerVacuum | 428-0593 | VCB Readings | 9 Month Operations | 5 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | FE000441 | Fence | 719-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCC000299 | LTCControl | 428-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCC000299 | LTCControl | 428-1 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCC000299 | LTCControl | 428-1 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCC000299 | LTCControl | 428-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCC000299 | LTCControl | 428-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCC000299 | LTCControl | 428-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCC000299 | LTCControl | 428-1 | LTC Control Insp | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCC000299 | LTCControl | 428-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | LTCC000299 | LTCControl | 428-1 | LTC Control Insp | All Connections OK? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | General Comments | | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | YD000444 | Yard | 788-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | FE000495 | Fence | 427-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Operations Counter AF | 260 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Operations Counter AL | 262 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Operations This Read Vac | 2 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Switching Operations | 2 | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | 9 Month Operations | 1 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Amps A Ø | 47.0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Amps B Ø | 47.0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Amps C Ø | 36.0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | General Comments | | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Operations Counter AF | 173 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Operations Counter AL | 174 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | BK001803 | BreakerVacuum | 788-2215 | VCB Readings | Operations This Read Vac | 1 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #'s |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | BAT001413 | Battery | 719-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | BCH001332 | Charger | 719-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Switching Operations | 1 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Operations This Read Vac | 1 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | BCH001332 | Charger | 719-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Operations Counter AL | 85 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Operations Counter AF | 85 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | 9 Month Operations | 3 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Amps A Ø | 200.0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Amps B Ø | 197.0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Amps C Ø | 175.0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0072 | BreakerVacuum | 428-0595 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | BK001141 | BreakerVacuum | 428-BT2-1 | VCB Readings | General Comments | | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | YD000502 | Yard | 427-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Amps C Ø | 42.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Amps B Ø | 45.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Amps A Ø | 49.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/18/2023 9:55 | Distribution | Lebanon East Quarterly Inspection | ST000504 | Structure | 427-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | 9 Month Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LTCC000433 | LTCControl | HC-TRANS 2 | LTC Control Insp | All Connections OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LTCC000433 | LTCControl | HC-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LTCC000433 | LTCControl | HC-TRANS 2 | LTC Control Insp | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LTCC000433 | LTCControl | HC-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Switching Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Operations This Read Vac | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Operations Counter AL | 35 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Operations Counter AF | 35 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Operations Counter AF | 46 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Counter Readings | LTC Operations Since Last Insp | 554 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | LTCC000696 | LTCControl | 874-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | LTCC000696 | LTCControl | 874-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | LTCC000696 | LTCControl | 874-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | LTCC000696 | LTCControl | 874-1 | LTC Control Insp | LTC Output Voltage Level | 124.3 | VAC |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | LTCC000696 | LTCControl | 874-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | LTCC000696 | LTCControl | 874-1 | LTC Control Insp | General Comments | | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | LTCC000696 | LTCControl | 874-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | LTCC000696 | LTCControl | 874-1 | LTC Control Insp | All Connections OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Readings | LTC Totalizer Reading | 4826.88 | kw |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Readings | General Comments | | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Counter Readings | General Comments | | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Counter Readings | LTC As Found Counter | 442732 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Counter Readings | LTC As Left Counter | 442737 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LTCC000520 | LTCControl | HC-TRANS 1 | LTC Control Insp | All Connections OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LTCC000520 | LTCControl | HC-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LTCC000520 | LTCControl | HC-TRANS 1 | LTC Control Insp | General Comments | | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Counter Readings | LTC Operations Since Last Insp | 954 | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/18/2023 11:17 | Distribution | Lebanon Industrial Quarterly Inspection | C0462 | LTCMechanism | 719-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LTCC000520 | LTCControl | HC-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Amps C Ø | 14.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Amps B Ø | 14.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Amps A Ø | 15.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Operations Counter AF | 199 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Operations Counter AL | 201 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Operations This Read Vac | 2 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Switching Operations | 2 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Amps C Ø | 102.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Amps B Ø | 104.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Amps A Ø | 102.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001982 | BreakerVacuum | HC-1433 | VCB Readings | 9 Month Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Switching Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Operations This Read Vac | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Operations Counter AL | 53 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Operations Counter AF | 53 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0260 | GroundTransformer | HC-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Amps C Ø | 0.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Amps B Ø | 0.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Amps A Ø | 0.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | 9 Month Operations | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Amps C Ø | 152.0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Amps B Ø | 209.0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Amps A Ø | 191.0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 10.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 50 | °C |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 35 | °C |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 60 | °C |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 40 | °C |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 45 | °C |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | WithLTC | HC-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 35 | °C |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Amps C Ø | 0.0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Amps B Ø | 0.0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Amps A Ø | 0.0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0074 | BreakerVacuum | 428-0597 | VCB Readings | 9 Month Operations | 2 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001984 | BreakerVacuum | HC-GND TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | 9 Month Operations | 2 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Amps A Ø | 0.0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Amps B Ø | 0.0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Amps C Ø | 0.0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0075 | BreakerVacuum | 428-0598 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 74216 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 74216 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 277 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | LT0093 | LTCMechanism | HC-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Operations This Read Vac | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Operations Counter AL | 46 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Counter Readings | General Comments | | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Counter Readings | LTC As Found Counter | 3175 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Counter Readings | LTC As Left Counter | 3180 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | C0538 | LTCMechanism | 826-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | General Comments | | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | FE000529 | Fence | 874-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | Ambient Temp | 40 | °F |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0048 | BreakerVacuum | 428-0594 | VCB Readings | 9 Month Operations | 2 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Operations Counter | 1873 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001983 | BreakerVacuum | HC-1434 | VCB Readings | Switching Operations | 0 | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | General Comments | | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/18/2023 8:52 | Distribution | Lebanon West Quarterly Inspection | YD000534 | Yard | 874-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Amps A Ø | 90.0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Fault Operations Ground | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Maintenance Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | 9 Month Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Operations Counter AF | 28 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Operations Counter AL | 28 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Amps C Ø | 81.0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | General Comments | | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Amps B Ø | 93.0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | General Comments | | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | FE000479 | Fence | 826-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | KB0043 | BreakerVacuum | 428-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | C0455 | WithLTC | 788-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | 9 Month Operations | 0 | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000196 | Switchgear | 428-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001981 | BreakerVacuum | HC-1432 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | YD000667 | Yard | HC-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 1/18/2023 9:12 | Distribution | Innovation Drive Quarterly Inspection | SWG000197 | Switchgear | 428-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Unknown Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Switching Operations | 0 | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/18/2023 10:41 | Distribution | Lebanon City Quarterly Inspection | ST000446 | Structure | 788-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/18/2023 14:39 | Distribution | Hillcrest Quarterly Inspection | BK001980 | BreakerVacuum | HC-1431 | VCB Readings | Operations This Read Vac | 0 | |
| 1/18/2023 14:26 | Distribution | Springfield Quarterly Inspection | CX0120 | RecloserElectronic | 826-2227 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCC000866 | LTCControl | 899-1 | LTC Control Insp | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCC000866 | LTCControl | 899-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Amps A Ø | 250.0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Amps B Ø | 250.0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Amps C Ø | 250.0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000085 | LTCControl | 768-3 | LTC Control Insp | All Connections OK? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000085 | LTCControl | 768-3 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000085 | LTCControl | 768-3 | LTC Control Insp | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000085 | LTCControl | 768-3 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000085 | LTCControl | 768-3 | LTC Control Insp | LTC Output Voltage Level | 124.1 | VAC |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000085 | LTCControl | 768-3 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Counter Readings | LTC Min Tap Position | 12L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Counter Readings | LTC Operations Since Last Insp | 848 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Switching Operations | 1 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Operations This Read Vac | 1 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Operations Counter AL | 242 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Operations Counter AF | 242 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000085 | LTCControl | 768-3 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000085 | LTCControl | 768-3 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Operations Counter AL | 162 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Operations This Read Vac | 1 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Switching Operations | 1 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Operations Counter AF | 161 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | General Comments | | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Operations Counter AF | 227 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Operations Counter AL | 227 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Amps C Ø | 89.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCC000866 | LTCControl | 899-1 | LTC Control Insp | All Connections OK? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Amps B Ø | 87.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Operations This Read Vac | 1 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | General Comments | | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Amps C Ø | 0.0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Counter Readings | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Counter Readings | LTC As Found Counter | 71855 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | LTCMechanism | 768-2 | LTC Counter Readings | LTC As Left Counter | 71860 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Amps B Ø | 0.0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Amps A Ø | 0.0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | 9 Month Operations | 2 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Amps C Ø | 25.0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Amps B Ø | 33.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Switching Operations | 1 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Operations This Read Vac | 1 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Operations Counter AL | 172 | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Operations Counter AF | 171 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Operations Counter AF | 143 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Operations Counter AL | 143 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Counter Readings | LTC Operations Since Last Insp | 9137 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Counter Readings | LTC As Left Counter | 87231 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Switching Operations | 1 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Operations This Read Vac | 2 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Switching Operations | 2 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000429 | BreakerVacuum | 896-0136 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | PF000179 | PowerFuse | HL-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | PF000179 | PowerFuse | HL-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | 9 Month Operations | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Amps A Ø | 305.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Amps B Ø | 288.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Amps C Ø | 255.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Switching Operations | 1 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | PF000179 | PowerFuse | HL-12KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | 9 Month Operations | 2 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 40 | °C |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 30 | °C |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Counter Readings | LTC Operations Since Last Insp | 295 | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Operations This Read Vac | 1 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Operations Counter AL | 401 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Operations Counter AF | 400 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCC000867 | LTCControl | 899-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCC000867 | LTCControl | 899-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCC000867 | LTCControl | 899-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCC000867 | LTCControl | 899-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCC000867 | LTCControl | 899-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCC000867 | LTCControl | 899-2 | LTC Control Insp | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCC000867 | LTCControl | 899-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCC000867 | LTCControl | 899-2 | LTC Control Insp | All Connections OK? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Amps B Ø | 100.0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Amps A Ø | 105.0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Counter Readings | LTC Operations Since Last Insp | 622 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Counter Readings | LTC Max Tap Position | 5R | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | General Comments | | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Counter Readings | LTC As Left Counter | 118292 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Counter Readings | LTC As Found Counter | 118292 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Counter Readings | General Comments | | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | LTCMechanism | 660-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | 9 Month Operations | 5 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Switching Operations | 1 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | General Comments | | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000221 | Switchgear | 899-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | 9 Month Operations | 1 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | 9 Month Operations VCB New | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Amps A Ø | 84.0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Amps B Ø | 76.0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Readings | Amps C Ø | 66.0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001278 | BreakerVacuum | 768-2234 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Amps C Ø | 105.0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Operations This Read Vac | 1 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Operations Counter AL | 255 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Operations Counter AF | 255 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | General Comments | | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | FE000377 | Fence | 475-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Counter Readings | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Counter Readings | LTC As Found Counter | 5051 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | General Comments | | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | FE000406 | Fence | 735-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | 9 Month Operations | 6 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Switching Operations | 1 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Operations This Read Vac | 1 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Operations Counter AL | 342 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Operations Counter AF | 341 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0391 | BreakerVacuum | 896-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | 9 Month Ops New | 3 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | 9 Months Operations | 5 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Amps A Ø | 104.0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Amps B Ø | 99.0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Amps C Ø | 86.0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Patrol Inspection | General Comments | | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | General Comments | | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Operations Counter AF | 940 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Operations Counter AL | 940 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Operations This Read AM | 2 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Switching Operations | 2 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0441 | BreakerAirMagnetic | HL-1157 | AMCB Readings | Unknown Operations | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Counter Readings | LTC Operations Since Last Insp | 339 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 30 | °C |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 35 | °C |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | FE000531 | Fence | 768-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | General Comments | | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCC000866 | LTCControl | 899-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCC000866 | LTCControl | 899-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCC000866 | LTCControl | 899-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCC000866 | LTCControl | 899-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | General Comments | | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCC000866 | LTCControl | 899-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | 9 Month Operations | 2 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Amps A Ø | 277.0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Amps B Ø | 285.0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Readings | Amps C Ø | 293.0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Counter Readings | LTC As Left Counter | 5750 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Counter Readings | LTC As Found Counter | 5750 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Counter Readings | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000106 | LTCMechanism | 899-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0035 | BreakerVacuum | 409-2220 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Operations Counter AF | 187 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | General Comments | | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK000428 | BreakerVacuum | 896-0119 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | SWG000220 | Switchgear | 899-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | YD000411 | Yard | 735-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Amps C Ø | 53.0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Amps B Ø | 54.0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Amps A Ø | 61.0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Amps A Ø | 84.0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | 9 Month Operations | 6 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | LTCM000105 | LTCMechanism | 899-1 | LTC Counter Readings | LTC As Left Counter | 5051 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | ST000540 | Structure | 768-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BK001412 | BreakerVacuum | 409-2219 | VCB Readings | Operations Counter AL | 188 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | WithLTC | HL-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 138206 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | General Comments | | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | ST000475 | Structure | 660-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Readings | General Comments | | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Readings | LTC Totalizer Reading | 9052.80 | kw |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 145796 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.9 | volts |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Readings | Totalizer Meter Reading | .9430 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Readings | Winding Temp Max | 55 | °C |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCC000962 | LTCControl | 412-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCC000962 | LTCControl | 412-1 | LTC Control Insp | VRR Base Voltage AL | 123.0 | VAC |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCC000962 | LTCControl | 412-1 | LTC Control Insp | VRR Base Voltage AF | 123.0 | VAC |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BCH001563 | Charger | 660-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BCH001563 | Charger | 660-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Readings | LTC Totalizer Reading | 10566.00 | kw |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Readings | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Operations Counter AF | 553 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Operations Counter AL | 553 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Operations This Read Vac | 1 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Amps C Ø | 109.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Amps B Ø | 111.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Amps A Ø | 107.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | 9 Month Operations VCB New | 14 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | 9 Month Operations | 16 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Max Tap Position | 1L | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1325 | Regulator | 409-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3312.00 | kw |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 52.50 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BCH001076 | Charger | HL-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BCH001076 | Charger | HL-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | WithLTC | 412-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.0350 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Readings | Winding Temp Present | 25 | °C |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Readings | Winding Temp Max | 35 | °C |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Readings | Totalizer Meter Reading | .1700 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | YD000377 | Yard | 899-Yard | Yard Patrol Inspection | Ambient Temp | 54 | °F |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | YD000377 | Yard | 899-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | YD000377 | Yard | 899-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | YD000377 | Yard | 899-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | YD000377 | Yard | 899-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Readings | LTC Totalizer Reading | 3060.00 | kw |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Readings | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | YD000377 | Yard | 899-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | YD000377 | Yard | 899-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | YD000377 | Yard | 899-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | YD000377 | Yard | 899-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | YD000377 | Yard | 899-Yard | Yard Patrol Inspection | General Comments | | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 55 | °F |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BAT000494 | Battery | 735-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCC000962 | LTCControl | 412-1 | LTC Control Insp | LTC Output Voltage Level | 122.0 | VAC |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCC000962 | LTCControl | 412-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCC000962 | LTCControl | 412-1 | LTC Control Insp | General Comments | | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCC000962 | LTCControl | 412-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Switching Operations | 1 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCC000962 | LTCControl | 412-1 | LTC Control Insp | All Connections OK? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | General Comments | | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | YD000473 | Yard | 660-Yard | Yard Patrol Inspection | Ambient Temp | 660 | °F |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BCH001076 | Charger | HL-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BCH001076 | Charger | HL-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 134.3 | VDC |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Readings | General Comments | | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BCH001076 | Charger | HL-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 134.3 | VDC |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BCH001076 | Charger | HL-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.8 | amps |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BCH001076 | Charger | HL-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BCH001076 | Charger | HL-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | M0037 | NonLTC | 735-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | General Comments | | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | FE000467 | Fence | 660-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Operations Counter AF | 198 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Operations Counter AL | 200 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Readings | LTC Totalizer Reading | 4742.40 | kw |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Readings | Totalizer Meter Reading | 1.4820 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Operations This Read Vac | 2 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | 9 Month Operations | 4 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Amps A Ø | 0.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Amps B Ø | 0.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Amps C Ø | 0.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Operations Counter AF | 107 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Operations Counter AL | 109 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Operations This Read Vac | 2 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Switching Operations | 2 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001537 | BreakerVacuum | 899-B2 FUT | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Switching Operations | 2 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | General Comments | | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | 9 Months Operations | 2 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Amps A Ø | 44.0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Amps B Ø | 25.0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Amps C Ø | 29.0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | 9 Month Operations | 2 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Amps A Ø | 240.0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Amps B Ø | 200.0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Amps C Ø | 250.0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | 9 Month Operations | 4 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Amps A Ø | 100.0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Switching Operations | 2 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Operations This Read Vac | 2 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Operations Counter AL | 112 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Operations Counter AF | 110 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Amps B Ø | 75.0 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Amps C Ø | 90.0 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Readings | General Comments | | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | WithLTC | 735-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | General Comments | | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000919 | BreakerVacuum | 660-0037 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Amps B Ø | 47.0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Amps A Ø | 24.0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | 9 Months Operations | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Counter Readings | LTC Operations Since Last Insp | 893 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Counter Readings | LTC As Left Counter | 46219 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Counter Readings | LTC As Found Counter | 46214 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Counter Readings | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Readings | Winding Temp Present | 35 | °C |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Readings | Totalizer Meter Reading | .5870 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | C0492 | WithLTC | 768-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Patrol Inspection | General Comments | | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | General Comments | | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Operations Counter AF | 865 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Operations Counter AL | 865 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Operations This Read AM | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Switching Operations | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Unknown Operations | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | PF000180 | PowerFuse | HL-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | PF000180 | PowerFuse | HL-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | PF000180 | PowerFuse | HL-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BCH001568 | Charger | 735-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BCH001568 | Charger | 735-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BCH001568 | Charger | 735-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BCH001568 | Charger | 735-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BCH001568 | Charger | 735-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.3 | amps |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BCH001568 | Charger | 735-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BCH001568 | Charger | 735-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BCH001568 | Charger | 735-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001536 | BreakerVacuum | 899-0197 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BCH001563 | Charger | 660-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BCH001563 | Charger | 660-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BCH001563 | Charger | 660-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BCH001563 | Charger | 660-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BCH001563 | Charger | 660-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.1 | amps |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BCH001563 | Charger | 660-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Patrol Inspection | General Comments | | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | General Comments | | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Operations Counter AF | 898 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Operations Counter AL | 898 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Operations This Read AM | 2 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Switching Operations | 2 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0439 | BreakerAirMagnetic | HL-1155 | AMCB Readings | Unknown Operations | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | 9 Month Operations | 2 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Amps A Ø | 20.0 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Amps B Ø | 15.0 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Amps C Ø | 15.0 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BB0392 | BreakerVacuum | 896-2 | VCB Readings | General Comments | | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | General Comments | | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Operations Counter AF | 179 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Operations Counter AL | 181 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Operations This Read Vac | 2 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Switching Operations | 2 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BK000920 | BreakerVacuum | 660-0063 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | LTCMechanism | 768-3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0442 | BreakerAirMagnetic | HL-1158 | AMCB Readings | Amps C Ø | 65.0 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 122.0 | volts |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 14114 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | 9 Month Operations | 1 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Amps A Ø | 74.0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Amps B Ø | 68.0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Amps C Ø | 58.0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Switching Operations | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Operations Counter AL | 108 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Operations Counter AF | 108 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Amps C Ø | 0.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Amps B Ø | 0.0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Operations This Read Vac | 1 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Operations Counter AL | 181 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Operations Counter AF | 180 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Amps A Ø | 0.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001533 | BreakerVacuum | 899-BT2-1 | VCB Readings | 9 Month Operations | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 94604 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 94604 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Unknown Operations | 0 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Counter Readings | LTC Operations Since Last Insp | 357 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Counter Readings | LTC Min Tap Position | 16L | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Counter Readings | LTC As Left Counter | 22291 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Counter Readings | LTC As Found Counter | 22291 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Counter Readings | General Comments | | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCM000080 | LTCMechanism | 412-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Switching Operations | 1 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | General Comments | | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | ST000580 | Structure | HL-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | General Comments | | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | YD000580 | Yard | HL-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Operations Counter AF | 276 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Operations Counter AL | 278 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Operations This Read Vac | 2 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Switching Operations | 2 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | General Comments | | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | FE000464 | Fence | 409-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Operations Counter AF | 160 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Operations Counter AL | 161 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Operations This Read Vac | 1 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Switching Operations | 1 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Switching Operations | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001532 | BreakerVacuum | 899-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | 9 Month Operations | 2 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Amps A Ø | 96.0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Amps B Ø | 80.0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Readings | Amps C Ø | 85.0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001277 | BreakerVacuum | 768-2205 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Counter Readings | General Comments | | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | B0253 | LTCMechanism | 735-2 | LTC Counter Readings | LTC As Found Counter | 87231 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | 9 Month Operations | 4 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0267 | BreakerVacuum | 768-2203 | VCB Readings | Amps A Ø | 17.0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | General Comments | | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | YD000469 | Yard | 409-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Amps C Ø | 215.0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Amps B Ø | 227.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 36 | °C |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 19 | °C |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Amps A Ø | 248.0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 1180 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LT0088 | LTCMechanism | HL-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001264 | BreakerVacuum | 768-2 | VCB Readings | 9 Month Operations | 1 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001276 | BreakerVacuum | 768-0233 | VCB Readings | General Comments | | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Amps A Ø | 165.0 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Amps B Ø | 170.0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Amps C Ø | 170.0 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Switching Operations | 2 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Operations This Read Vac | 2 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Operations Counter AL | 135 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Operations Counter AF | 133 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | General Comments | | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | General Comments | | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Operations Counter AF | 190 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Operations Counter AL | 192 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Operations This Read Vac | 2 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Switching Operations | 2 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | 9 Month Operations | 2 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Amps A Ø | 0.0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Amps B Ø | 0.0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Readings | Amps C Ø | 0.0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0266 | BreakerVacuum | 768-BT3-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | YD000377 | Yard | 899-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | YD000377 | Yard | 899-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | YD000377 | Yard | 899-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | B0444 | WithLTC | 768-3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Switching Operations | 2 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Operations This Read Vac | 2 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Operations Counter AL | 102 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Operations Counter AF | 100 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | FE000673 | Fence | 412-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | FE000673 | Fence | 412-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | FE000673 | Fence | 412-Fence | Fence Patrol Inspection | General Comments | | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | FE000673 | Fence | 412-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | FE000673 | Fence | 412-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | FE000673 | Fence | 412-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | FE000673 | Fence | 412-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | FE000673 | Fence | 412-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | FE000673 | Fence | 412-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | FE000673 | Fence | 412-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1324 | Regulator | 409-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Amps C Ø | 85.0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | LTCC000218 | LTCControl | 896-2 | LTC Control Insp | All Connections OK? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | LTCC000218 | LTCControl | 896-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | LTCC000218 | LTCControl | 896-2 | LTC Control Insp | General Comments | | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | LTCC000218 | LTCControl | 896-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | LTCC000218 | LTCControl | 896-2 | LTC Control Insp | LTC Output Voltage Level | 122.0 | VAC |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | LTCC000218 | LTCControl | 896-2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | LTCC000218 | LTCControl | 896-2 | LTC Control Insp | VRR Base Voltage AF | 123.0 | VAC |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | LTCC000218 | LTCControl | 896-2 | LTC Control Insp | VRR Base Voltage AL | 123.0 | VAC |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | LTCC000218 | LTCControl | 896-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Amps B Ø | 100.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Amps A Ø | 93.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001535 | BreakerVacuum | 899-0137 | VCB Readings | 9 Month Operations | 3 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | BK000419 | BreakerVacuum | 735-0018 | VCB Readings | 9 Month Operations | 4 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Switching Operations | 1 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Operations This Read Vac | 1 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Operations Counter AL | 356 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Operations Counter AF | 355 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | 9 Months Operations | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Amps A Ø | 136.0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Amps B Ø | 147.0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Amps C Ø | 146.0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Patrol Inspection | General Comments | | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | General Comments | | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 122.0 | volts |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 15561 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Operations Counter AF | 1327 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Operations Counter AL | 1327 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Operations This Read AM | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0440 | BreakerAirMagnetic | HL-1156 | AMCB Readings | Switching Operations | 0 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000067 | Regulator | 735-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000068 | Regulator | 735-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | CB0268 | BreakerVacuum | 768-2204 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | General Comments | | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | SWG000036 | Switchgear | HL-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | ST000413 | Structure | 735-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Amps C Ø | 72.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Amps B Ø | 84.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Amps A Ø | 118.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001534 | BreakerVacuum | 899-0072 | VCB Readings | 9 Month Operations | 2 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Counter Readings | General Comments | | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Counter Readings | LTC As Found Counter | 25237 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Counter Readings | LTC As Left Counter | 25237 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 46 | °C |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 36 | °C |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Counter Readings | LTC Operations Since Last Insp | 383 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | LTCMechanism | 896-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | General Comments | | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Operations Counter AF | 241 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Operations Counter AL | 243 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | 9 Month Operations | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Operations This Read Vac | 2 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Switching Operations | 2 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Patrol Inspection | General Comments | | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | General Comments | | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Operations Counter AF | 540 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Operations Counter AL | 540 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Operations This Read AM | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Switching Operations | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Unknown Operations | 0 | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | LTCC000932 | LTCControl | 475-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | LTCC000932 | LTCControl | 475-1 | LTC Control Insp | General Comments | | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | LTCC000932 | LTCControl | 475-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | LTCC000932 | LTCControl | 475-1 | LTC Control Insp | LTC Output Voltage Level | 122.0 | VAC |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | LTCC000932 | LTCControl | 475-1 | LTC Control Insp | VRR Base Voltage AF | 123.0 | VAC |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | LTCC000932 | LTCControl | 475-1 | LTC Control Insp | VRR Base Voltage AL | 123.0 | VAC |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | LTCC000932 | LTCControl | 475-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | LTC Totalizer Reading | 17049.60 | kw |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | 9 Month Operations | 3 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Bat Volt 1Min After Chgr Trip | 134.3 | VDC |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery 1 Pre-test Volts | 134.3 | VDC |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Readings | Switching Operations | 0 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Operations Counter AF | 115 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | General Comments | | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Ambient Temp | 56 | °F |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Amps C Ø | 377.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Amps B Ø | 352.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Amps A Ø | 400.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | General Comments | | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Dry Cell Battery Install Date | 2022-06-01 00:00:00.000000 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Min Tap Position | 13L | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | SF6 Pressure Indicator | good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Readings | Operations This Read SF6 | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery 1 Load Test Volts | 134.3 | VDC |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery 1 Post-test Volts | 134.3 | VDC |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery 2 Load Test Volts | 134.3 | VDC |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery 2 Post-test Volts | 134.3 | VDC |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery 2 Pre-test Volts | 134.3 | VDC |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery 3 Load Test Volts | 134.3 | VDC |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery 3 Post-test Volts | 134.3 | VDC |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery 3 Pre-test Volts | 134.3 | VDC |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery 4 Load Test Volts | 134.3 | VDC |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery 4 Post-test Volts | 134.3 | VDC |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery 4 Pre-test Volts | 134.3 | VDC |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery Bank Amps | 2.8 | AMPS |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery Bank Volts | 134.3 | VDC |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | BAT001649 | Battery | HL-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | General Comments | | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | ST000386 | Structure | 475-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | General Comments | | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | CH000375 | ControlHouse | 412-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCC000013 | LTCControl | 412-2 | LTC Control Insp | All Connections OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCC000013 | LTCControl | 412-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCC000013 | LTCControl | 412-2 | LTC Control Insp | General Comments | | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCC000013 | LTCControl | 412-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCC000013 | LTCControl | 412-2 | LTC Control Insp | LTC Output Voltage Level | 122.0 | VAC |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCC000013 | LTCControl | 412-2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCC000013 | LTCControl | 412-2 | LTC Control Insp | VRR Base Voltage AF | 123.0 | VAC |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCC000013 | LTCControl | 412-2 | LTC Control Insp | VRR Base Voltage AL | 123.0 | VAC |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | 9 Month Operations | 4 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | 9 Months Operations | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Readings | Oil Temp Present | 50 | °C |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Switching Operations | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Operations Counter AL | 154 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Operations Counter AF | 154 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Readings | Totalizer Meter Reading | .5404 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Readings | Winding Temp Max | 55 | °C |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | General Comments | | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | LTCC000886 | LTCControl | 896-1 | LTC Control Insp | VRR Base Voltage AL | 123.0 | VAC |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | LTCC000886 | LTCControl | 896-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | 9 Month Operations | 1 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | LTCC000932 | LTCControl | 475-1 | LTC Control Insp | All Connections OK? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Switching Operations | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001482 | BreakerVacuum | 899-1 | VCB Readings | Operations Counter AL | 115 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Amps A Ø | 297.0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Amps B Ø | 315.0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Amps C Ø | 316.0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | LTCC000013 | LTCControl | 412-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | YD000680 | Yard | 412-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | YD000680 | Yard | 412-Yard | Yard Patrol Inspection | General Comments | | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | YD000680 | Yard | 412-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | YD000680 | Yard | 412-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | YD000680 | Yard | 412-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | YD000680 | Yard | 412-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | YD000680 | Yard | 412-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | YD000680 | Yard | 412-Yard | Yard Patrol Inspection | Ambient Temp | 58 | °F |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Amps A Ø | 280.0 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Amps B Ø | 235.0 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | BAT000964 | Battery | 660-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Amps C Ø | 250.0 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | BK001171 | BreakerVacuum | 896-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | LTCC000886 | LTCControl | 896-1 | LTC Control Insp | All Connections OK? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | LTCC000886 | LTCControl | 896-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | LTCC000886 | LTCControl | 896-1 | LTC Control Insp | General Comments | | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | LTCC000886 | LTCControl | 896-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | LTCC000886 | LTCControl | 896-1 | LTC Control Insp | LTC Output Voltage Level | 122.0 | VAC |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | LTCC000886 | LTCControl | 896-1 | LTC Control Insp | VRR Base Voltage AF | 123.0 | VAC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Counter Readings | General Comments | | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Counter Readings | LTC As Found Counter | 50696 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Counter Readings | LTC As Left Counter | 50696 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000572 | LTCControl | 768-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000572 | LTCControl | 768-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000572 | LTCControl | 768-2 | LTC Control Insp | LTC Output Voltage Level | 124.4 | VAC |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000572 | LTCControl | 768-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000572 | LTCControl | 768-2 | LTC Control Insp | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000572 | LTCControl | 768-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Switching Operations | 1 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Operations This Read Vac | 1 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000572 | LTCControl | 768-2 | LTC Control Insp | All Connections OK? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.3190 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | LTCC000572 | LTCControl | 768-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | X1 Winding Temp Max | 45 | °C |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | X1 Winding Temp Present | 40 | °C |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | X2 Winding Temp Max | 45 | °C |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | X2 Winding Temp Present | 40 | °C |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | X3 Winding Temp Max | 45 | °C |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | X3 Winding Temp Present | 40 | °C |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 9216.00 | kw |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Readings | General Comments | | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | LTCC000937 | LTCControl | 735-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | LTCC000937 | LTCControl | 735-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Counter Readings | LTC Operations Since Last Insp | 378 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | LTCMechanism | 896-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | LTCC000937 | LTCControl | 735-2 | LTC Control Insp | General Comments | | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | LTCC000937 | LTCControl | 735-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | LTCC000937 | LTCControl | 735-2 | LTC Control Insp | All Connections OK? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Amps B Ø | 120.0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Amps C Ø | 107.0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BCH001384 | Charger | 768-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BCH001384 | Charger | 768-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BCH001384 | Charger | 768-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BCH001384 | Charger | 768-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 4.0 | amps |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BCH001384 | Charger | 768-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BCH001384 | Charger | 768-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BCH001384 | Charger | 768-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BCH001384 | Charger | 768-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Readings | LTC Totalizer Reading | 12662.40 | kw |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Readings | General Comments | | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Operations Counter AL | 166 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Operations Counter AF | 165 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | General Comments | | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | 9 Month Operations | 1 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | General Comments | | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BK001341 | BreakerVacuum | 768-3 | VCB Readings | Amps A Ø | 97.0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | LTCC000937 | LTCControl | 735-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | LTCC000937 | LTCControl | 735-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | KB0119 | BreakerVacuum | 735-0017 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | LTCC000937 | LTCControl | 735-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | LTCC000937 | LTCControl | 735-2 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Ambient Temperature | 58 | °F |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Fans Operational? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1000 | psi |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Fans Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Counter Readings | General Comments | | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Counter Readings | LTC As Found Counter | 57237 | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Counter Readings | LTC As Left Counter | 57237 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 56 | °F |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | BAT001424 | Battery | 768-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 132206 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | R1323 | Regulator | 409-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Readings | Operations Counter AL | 52 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Readings | Operations Counter AF | 52 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Readings | General Comments | | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | YD000382 | Yard | 475-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | General Comments | | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 13882 | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 122.0 | volts |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/17/2023 12:44 | Distribution | Scott Street Quarterly Inspection | RG000013 | Regulator | 735-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Readings | Fault Operations | 0 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | BK000061 | BreakerSF6 | 412-618 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | B0367 | WithLTC | 660-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 500 | psi |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | LTC Totalizer Reading | 10728.00 | kw |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Readings | Totalizer Meter Reading | .7104 | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BCH001361 | Charger | 409-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BCH001361 | Charger | 409-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BCH001361 | Charger | 409-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BCH001361 | Charger | 409-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Readings | LTC Totalizer Reading | 12511.20 | kw |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BCH001361 | Charger | 409-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.3 | amps |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Readings | General Comments | | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BCH001361 | Charger | 409-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BCH001361 | Charger | 409-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BCH001361 | Charger | 409-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | BAT000953 | Battery | 409-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | LTCMechanism | 475-1 | LTC Counter Readings | LTC Operations Since Last Insp | 366 | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/17/2023 10:57 | Distribution | Campbellsville 1 Quarterly Inspection | YD000536 | Yard | 768-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Readings | Totalizer Meter Reading | .5213 | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | X3 Winding Temp Present | 40 | °C |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | X3 Winding Temp Max | 45 | °C |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | X2 Winding Temp Present | 40 | °C |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | X2 Winding Temp Max | 45 | °C |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | X1 Winding Temp Present | 40 | °C |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | X1 Winding Temp Max | 45 | °C |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | FE000573 | Fence | HL-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | Totalizer Meter Reading | .4470 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000258 | WithLTC | 899-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | B0472 | WithLTC | 475-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | TX000259 | WithLTC | 899-2 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Readings | General Comments | | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Readings | LTC Totalizer Reading | 9024.00 | kw |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1200 | psi |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Readings | Oil Temp Max | 56 | °C |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Readings | Oil Temp Present | 48 | °C |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Readings | 9 Months Operations OCB New | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | FE000875 | Fence | 899-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Readings | Totalizer Meter Reading | .3760 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Readings | Winding Temp Max | 58 | °C |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Readings | Winding Temp Present | 49 | °C |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Switching Operations | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Operations This Read Vac | 2 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Operations Counter AL | 138 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Operations Counter AF | 136 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Maintenance Operations | 2 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Amps C Ø | 0.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Amps B Ø | 0.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Amps A Ø | 0.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001487 | BreakerVacuum | 899-B1 FUT | VCB Readings | 9 Month Operations | 2 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Readings | LTC Totalizer Reading | 10512.00 | kw |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Readings | General Comments | | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | General Comments | | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Operations Counter AF | 109 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Operations Counter AL | 111 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Operations This Read Vac | 2 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Switching Operations | 2 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | BAT001468 | Battery | 475-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | BAT001468 | Battery | 475-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 55 | °F |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | BAT001468 | Battery | 475-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Switching Operations | 1 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Operations This Read Vac | 1 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Amps A Ø | 13.0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Amps B Ø | 19.0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Amps C Ø | 15.0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | MOD Cabinet Heater functional? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | MOD Cabinet Internals Clean? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | MOD Motor Jaw Coupling | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Readings | Fault Operations | 0 | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Counter Readings | LTC Operations Since Last Insp | 312 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 20 | °C |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Restroom Clean & OK? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 45 | °C |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | General Comments | | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Counter Readings | LTC As Left Counter | 38581 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Counter Readings | LTC As Found Counter | 38581 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Operations Counter AF | 517 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Operations Counter AL | 518 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | General Comments | | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Counter Readings | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | 9 Month Operations | 8 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Amps A Ø | 165.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Amps B Ø | 142.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Amps C Ø | 162.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Operations Counter AF | 126 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Operations Counter AL | 128 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Operations This Read Vac | 2 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Switching Operations | 2 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001486 | BreakerVacuum | 899-0081 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Platform/Walkway/Railing OK? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | 9 Month Operations | 2 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Amps A Ø | 47.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Amps B Ø | 45.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Amps C Ø | 75.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | General Comments | | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | S0055 | LTCMechanism | 412-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | UG Pothead Condition Good? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | ST000381 | Structure | 899-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | K0026 | BreakerVacuum | 409-2218 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | ST000443 | Structure | 409-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | CH000155 | ControlHouse | HL-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Switching Operations | 2 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Operations This Read Vac | 2 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Operations Counter AL | 115 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Readings | Operations Counter AF | 113 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001485 | BreakerVacuum | 899-0114 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Readings | Switching Operations | 0 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Readings | Operations This Read Oil | 0 | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Readings | Operations Counter AL | 31 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Readings | Operations Counter AF | 31 | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Readings | Number of Ops last 9 Months | 0 | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Readings | General Comments | | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Readings | LTC Totalizer Reading | 7781.76 | kw |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Readings | Unknown Operations | 0 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | LTCC000646 | LTCControl | 660-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/17/2023 14:20 | Distribution | Harmony Landing Quarterly Inspection | LB0444 | BreakerAirMagnetic | HL-12KV TR 1 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | LTCC000646 | LTCControl | 660-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | LTCC000646 | LTCControl | 660-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | LTCC000646 | LTCControl | 660-1 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | LTCC000646 | LTCControl | 660-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Hydraulic Pressure Acceptable? | y | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | LTCC000646 | LTCControl | 660-1 | LTC Control Insp | General Comments | | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | LTCC000646 | LTCControl | 660-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Hydraulic Oil Levels OK? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Hydraulic Leaks | None | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Operations Counter AF | 98 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Operations Counter AL | 98 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Switching Operations | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | KT0055 | WithLTC | 896-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | 9 Month Operations | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | BAT001468 | Battery | 475-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | BAT001468 | Battery | 475-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | BAT001468 | Battery | 475-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | BAT001468 | Battery | 475-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | BAT001468 | Battery | 475-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | BAT001468 | Battery | 475-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | BAT001468 | Battery | 475-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | BAT001468 | Battery | 475-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | BAT001468 | Battery | 475-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | BAT001468 | Battery | 475-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | 9 Month Operations | 2 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Amps A Ø | 192.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Amps B Ø | 167.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Amps C Ø | 165.0 | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Tank Oil Level | Good | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Tank Leaks | None | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Readings | Winding Temp Present | 35 | °C |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Readings | Winding Temp Max | 50 | °C |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Readings | Totalizer Meter Reading | .4380 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/17/2023 13:54 | Distribution | Lebanon South Quarterly Inspection | S0015 | NonLTC | 409-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .9600 | |
| 1/17/2023 13:19 | Distribution | UK Med Center Quarterly Inspection | B0478 | WithLTC | 896-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | General Comments | | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Readings | General Comments | | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 1/17/2023 14:12 | Distribution | Hughes Lane Quarterly Inspection | LTCC000646 | LTCControl | 660-1 | LTC Control Insp | All Connections OK? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001483 | BreakerVacuum | 899-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 1/17/2023 12:50 | Distribution | UK Scott Street Quarterly Inspection | TB0625 | BreakerOil | 475-608 | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Fault Operations Ground | 0 | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Readings | Follow-up Action Required? | n | |
| 1/17/2023 10:02 | Distribution | Wilson Downing Quarterly Inspection | BK001484 | BreakerVacuum | 899-0073 | VCB Patrol Inspection | General Comments | | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/17/2023 12:58 | Distribution | UK West Quarterly Inspection | B0379 | WithLTC | 412-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Maintenance Operations | 0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | General Comments | | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Patrol Inspection | General Comments | | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Follow-up Action Required? | n | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Fault Operations Ground | 0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Ambient Temperature | 38 | °F |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | 9 Month Operations GCB New | 1 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Y3 Winding Temp Max | 0 | °C |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Y2 Winding Temp Present | 0 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Y2 Winding Temp Max | 0 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Counter A Ø | 0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Operations Counter AF | 180 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | Amps A Ø | 1.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | Amps B Ø | 1.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Operations Counter AF | 188 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Maintenance Operations | 0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Amps B Ø | 90.0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Operations Counter AL | 181 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Operations This Read Vac | 1 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Switching Operations | 1 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Unknown Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | Amps C Ø | 1.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Fault Operations Ground | 0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Readings | Totalizer Meter Reading | .7410 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | Fault Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Readings | LTC Totalizer Reading | 7113.60 | kw |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Percent Thermal Load B Ø Max | 0 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Percent Thermal Load A Ø Max | 0 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 20 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Patrol Inspection | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Follow-up Action Required? | n | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Fault Operations Ground | 0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Readings | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | 9 Month Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1150 | psi |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Amps C Ø | 0.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Amps B Ø | 0.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Amps A Ø | 0.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Operations Counter AL | 189 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Operations This Read Vac | 1 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Switching Operations | 1 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Amps C Ø | 110.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Unknown Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Switching Operations | 0 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Y3 Winding Temp Present | 0 | °C |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Operations This Read Vac | 1 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Switching Operations | 1 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | LV Winding Temp Present | 0 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | 9 Month Ops New | 6 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Operations This Read Vac | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Operations Counter AL | 86 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Operations Counter AF | 86 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | 9 Month Operations | 5 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | Maintenance Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001880 | BreakerVacuum | CF-1210 | VCB Readings | General Comments | | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Amps A Ø | 20.0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Amps B Ø | 18.0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Amps C Ø | 32.0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001424 | BreakerVacuum | 408-2221 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Percent Thermal Load C Ø Max | 0 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Fault Operations Ground | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Patrol Inspection | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Maintenance Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Operations Counter AF | 76 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Operations Counter AL | 76 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Operations This Read Vac | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Switching Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Unknown Operations | 0 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Amps C Ø | 60.0 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Counter C Ø | 0 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | LTCC000289 | LTCControl | 784-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | LTCC000289 | LTCControl | 784-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | LTCC000289 | LTCControl | 784-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Counter B Ø | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | TV Winding Temp Max | 0 | °C |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Fault Operations Ground | 0 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | Switching Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Totalizer Meter Multiplier | 0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Unknown Operations | 0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Switching Operations | 1 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Operations This Read Vac | 1 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Operations Counter AL | 159 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Operations Counter AF | 158 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Follow-up Action Required? | n | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Patrol Inspection | General Comments | | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Maintenance Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | SF6 Pressure Pole 3 | 90 | psi |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | General Comments | | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Patrol Inspection | General Comments | | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | General Comments | | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Maintenance Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Top Oil Temperature Present | 20 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | SF6 Pressure Pole 2 | 90 | psi |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Amps A Ø | 60.0 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Amps B Ø | 60.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | 9 Month Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Top Oil Temperature Max | 20 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Amps A Ø | 0.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Amps B Ø | 0.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Amps C Ø | 0.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001878 | BreakerVacuum | CF-1208 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Amps B Ø | 0.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Amps C Ø | 0.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Fault Operations Ground | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Patrol Inspection | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Maintenance Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Operations Counter AF | 101 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Operations Counter AL | 101 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Operations This Read Vac | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Switching Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Unknown Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Grounds in Place? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | General Comments | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Foundation Condition | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | Follow-up Action Required? | n | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 20 | °C |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Amps C Ø | 70.0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Amps B Ø | 77.0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Amps A Ø | 50.0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | 9 Month Operations | 6 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 20 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 20 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 20 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 20 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Y1 Winding Temp Max | 0 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Y1 Winding Temp Present | 0 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | TV Winding Temp Present | 0 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Winding Temp Max | 20 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Winding Temp Present | 20 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | General Comments | | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | General Comments | | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | SF6 Pressure Pole 1 | 90 | psi |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | Operations This Read SF6 | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | Operations Counter AL | 195 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | Operations Counter AF | 195 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | Num Operations Last 9 Months | 1 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 331 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Fault Operations Ground | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | Maintenance Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | 9 Month Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 20 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK001425 | BreakerVacuum | 408-2223 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001879 | BreakerVacuum | CF-1209 | VCB Readings | Amps A Ø | 0.0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | LTCC000289 | LTCControl | 784-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Unknown Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | LTCC000289 | LTCControl | 784-1 | LTC Control Insp | All Connections OK? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | Fault Operations | 0 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Foundation Condition | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | 9 Month Operations | 5 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | 9 Month Operations | 4 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Amps A Ø | 160.0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Amps B Ø | 120.0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Amps C Ø | 155.0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | PF001203 | PowerFuse | CF-STA SER NO 6 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | PF001203 | PowerFuse | CF-STA SER NO 6 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | PF001203 | PowerFuse | CF-STA SER NO 6 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | PF001326 | PowerFuse | CF-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | PF001326 | PowerFuse | CF-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Follow-up Action Required? | n | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1365 | Regulator | 407-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 120975 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | LTCC000289 | LTCControl | 784-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Patrol Inspection | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Operations Counter AF | 278 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 121204 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.7 | volts |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Operations Counter AL | 278 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Operations This Read AM | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Switching Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Unknown Operations | 0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Counter Readings | LTC Operations Since Last Insp | 897 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Counter Readings | LTC Current Tap Position | 1R | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | LTCC000289 | LTCControl | 784-1 | LTC Control Insp | General Comments | | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Counter Readings | LTC As Left Counter | 221020 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Counter Readings | LTC As Found Counter | 221016 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | LTCMechanism | 408-1 | LTC Counter Readings | General Comments | | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Amps A Ø | 200.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | 9 Months Operations | 20 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | 9 Month Ops New | 12 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | SF6 Pressure Pole 1 | 92 | psi |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Patrol Inspection | General Comments | | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Follow-up Action Required? | n | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Fault Operations Ground | 0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | Operations This Read SF6 | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | Operations Counter AL | 121 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | Operations Counter AF | 121 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | Maintenance Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Grounds in Place? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | General Comments | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | BAT001486 | Battery | 407-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | BAT001486 | Battery | 407-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 35 | °F |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | BAT001486 | Battery | 407-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | BAT001486 | Battery | 407-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | BAT001486 | Battery | 407-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | BAT001486 | Battery | 407-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | BAT001486 | Battery | 407-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | BAT001486 | Battery | 407-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | BAT001486 | Battery | 407-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | BAT001486 | Battery | 407-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | BAT001486 | Battery | 407-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | BAT001486 | Battery | 407-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | BAT001486 | Battery | 407-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | LTCC000289 | LTCControl | 784-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | LTCC000289 | LTCControl | 784-1 | LTC Control Insp | LTC Output Voltage Level | 124.3 | VAC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Fault Operations A Ø | 4 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Fault Adjusted Amps B Phase AM | 44.72 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Fault Adjusted Amps A Phase AM | 44.72 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | Unknown Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | Switching Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | SF6 Pressure Pole 3 | 90 | psi |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | SF6 Pressure Pole 2 | 90 | psi |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | General Comments | | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Amps C Ø | 190.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Amps B Ø | 200.0 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Fault Operations Ground | 0 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Follow-up Action Required? | n | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | General Comments | | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | General Comments | | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Maintenance Operations | 0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | ANN000018 | Annunciator | CF-Annunciator Panel | Annunciator Patrol Inspection | ESOC  Received Alarm Test? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | ANN000018 | Annunciator | CF-Annunciator Panel | Annunciator Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | ANN000018 | Annunciator | CF-Annunciator Panel | Annunciator Patrol Inspection | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCC000898 | LTCControl | CF-TRANS 2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | 9 Months Operations | 6 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCC000898 | LTCControl | CF-TRANS 2 | LTC Control Insp | VRR Base Voltage AL | 122.5 | VAC |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCC000898 | LTCControl | CF-TRANS 2 | LTC Control Insp | VRR Base Voltage AF | 122.5 | VAC |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCC000898 | LTCControl | CF-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCC000898 | LTCControl | CF-TRANS 2 | LTC Control Insp | LTC Output Voltage Level | 122.5 | VAC |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCC000898 | LTCControl | CF-TRANS 2 | LTC Control Insp | LTC Operation Checked? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCC000898 | LTCControl | CF-TRANS 2 | LTC Control Insp | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCC000898 | LTCControl | CF-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | 9 Month Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Amps A Ø | 130.0 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Ambient Temperature | 38 | °F |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | Amps A Ø | 70.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | Amps B Ø | 79.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Readings | Amps C Ø | 81.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001696 | BreakerSF6 | CF-138KV TR 1 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | B0325 | WithLTC | 408-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Operations Counter AL | 183 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Operations Counter AF | 182 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | General Comments | | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Maintenance Operations | 0 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Operations Counter AF | 227 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Operations Counter AL | 231 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Operations This Read Vac | 4 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Switching Operations | 4 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | FE000535 | Fence | 784-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | LV Winding Temp Max | 0 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | LTC Totalizer Reading | 0.00 | kw |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | HV Winding Temp Present | 0 | °C |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | HV Winding Temp Max | 0 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | H3 Winding Temp Present | 0 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | ANN000018 | Annunciator | CF-Annunciator Panel | Annunciator Patrol Inspection | All Lights Functioning? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Unknown Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | ANN000018 | Annunciator | CF-Annunciator Panel | Annunciator Patrol Inspection | Control House Alarm Audible? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | H3 Winding Temp Max | 0 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | H2 Winding Temp Present | 0 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | H2 Winding Temp Max | 0 | °C |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | H1 Winding Temp Present | 0 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | H1 Winding Temp Max | 0 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Operations This Read Vac | 4 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Readings | General Comments | | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Switching Operations | 4 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Readings | LTC Totalizer Reading | 5287.68 | kw |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Gas Accumulation Gauge | Normal | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | TX000271 | WithLTC | CF-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | PF001326 | PowerFuse | CF-12KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 35 | °F |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BAT001444 | Battery | 408-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Fault Operations B Ø | 4 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Readings | Totalizer Meter Reading | .5508 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | B0438 | WithLTC | 784-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Amps A Ø | 420.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Amps A Ø | 0.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Amps B Ø | 700.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Amps C Ø | 430.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Amps B Ø | 0.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Amps C Ø | 0.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Follow-up Action Required? | n | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Operations Counter AF | 296 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0050 | BreakerVacuum | 407-2209 | VCB Readings | Operations Counter AL | 300 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0175 | BreakerAirMagnetic | CF-1204 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Patrol Inspection | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Maintenance Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Operations Counter AF | 95 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Operations Counter AL | 95 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Switching Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001882 | BreakerVacuum | CF-BUS TIE SEC 2 | VCB Readings | Unknown Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCC000898 | LTCControl | CF-TRANS 2 | LTC Control Insp | All Connections OK? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Unknown Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Switching Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Operations This Read AM | 8 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Operations Counter AL | 15 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Operations Counter AF | 15 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Maintenance Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Patrol Inspection | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Readings | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0176 | BreakerAirMagnetic | CF-1205 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Amps B Ø | 260.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Amps C Ø | 310.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Fault Adjusted Amps C Phase AM | 11.18 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Fault Operations C Ø | 1 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Patrol Inspection | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Maintenance Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Operations Counter AF | 99985 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Operations Counter AL | 99985 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Operations This Read AM | 1 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Switching Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Unknown Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Amps C Ø | 210.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Amps B Ø | 200.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Amps A Ø | 150.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | 9 Months Operations | 4 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 55 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 35 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 55 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 35 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 55 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 35 | °C |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | LTCC000626 | LTCControl | 408-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | LTCC000626 | LTCControl | 408-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | LTCC000626 | LTCControl | 408-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | LTCC000626 | LTCControl | 408-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | needs nitro bottle filled | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Unknown Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Switching Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Operations This Read AM | 3 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Operations Counter AL | 106 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Operations Counter AF | 106 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Maintenance Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Patrol Inspection | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Fault Operations C Ø | 1 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Fault Operations B Ø | 1 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Fault Operations A Ø | 1 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Fault Adjusted Amps C Phase AM | 11.18 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Fault Adjusted Amps B Phase AM | 11.18 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | Fault Adjusted Amps A Phase AM | 11.18 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Amps A Ø | 390.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Amps B Ø | 410.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Amps C Ø | 510.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BCH001364 | Charger | 408-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3697.92 | kw |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 25.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Patrol Inspection | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Maintenance Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Operations Counter AF | 386 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Operations Counter AL | 386 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Operations This Read AM | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Switching Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Unknown Operations | 0 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 20.00 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BCH001364 | Charger | 408-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BCH001364 | Charger | 408-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BCH001364 | Charger | 408-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Readings | Oil Temp Max | 25 | °C |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | General Comments | | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | FE000504 | Fence | 407-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Operations Counter AL | 99785 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Operations This Read AM | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Switching Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Unknown Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCC000536 | LTCControl | CF-TRANS 1 | LTC Control Insp | All Connections OK? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCC000536 | LTCControl | CF-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCC000536 | LTCControl | CF-TRANS 1 | LTC Control Insp | General Comments | | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Readings | General Comments | | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | 9 Month Ops New | 10 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | 9 Months Operations | 10 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0172 | BreakerAirMagnetic | CF-1201 | AMCB Readings | 9 Month Ops New | 1 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0174 | BreakerAirMagnetic | CF-1203 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | General Comments | | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 2822 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 7L | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | 9 Months Operations | 8 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 20 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 20 | °C |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Operations Counter AF | 99785 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Maintenance Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Patrol Inspection | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Amps C Ø | 850.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | Amps A Ø | 260.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Amps B Ø | 850.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Amps A Ø | 725.0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | 9 Month Operations | 1 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | General Comments | | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | FE000421 | Fence | 408-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Counter Readings | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LTCM000117 | LTCMechanism | CF-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 2822 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | PF000107 | PowerFuse | CF-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | PF000107 | PowerFuse | CF-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | PF000107 | PowerFuse | CF-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | PF000108 | PowerFuse | CF-12KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | PF000108 | PowerFuse | CF-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0173 | BreakerAirMagnetic | CF-1202 | AMCB Readings | 9 Month Ops New | 7 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 126240 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | PF000108 | PowerFuse | CF-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BCH001469 | Charger | 784-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1363 | Regulator | 407-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | LTCC000626 | LTCControl | 408-1 | LTC Control Insp | All Connections OK? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | LTCC000626 | LTCControl | 408-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | LTCC000626 | LTCControl | 408-1 | LTC Control Insp | General Comments | | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | LTCC000626 | LTCControl | 408-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | LTCC000626 | LTCControl | 408-1 | LTC Control Insp | LTC Output Voltage Level | 124.4 | VAC |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | R1364 | Regulator | 407-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | YD000425 | Yard | 408-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | General Comments | | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | ST000427 | Structure | 408-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | 9 Months Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LB0178 | BreakerAirMagnetic | CF-12KV TR 1 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BCH001469 | Charger | 784-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BCH001469 | Charger | 784-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BCH001469 | Charger | 784-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BCH001469 | Charger | 784-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BCH001469 | Charger | 784-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.4 | amps |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Amps A Ø | 40.0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Amps B Ø | 65.0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Amps C Ø | 60.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | SWG000019 | Switchgear | CF-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BCH001469 | Charger | 784-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BCH001469 | Charger | 784-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | BCH001359 | Charger | 407-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | BCH001359 | Charger | 407-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | BCH001359 | Charger | 407-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.4 | amps |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | BCH001359 | Charger | 407-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | BCH001359 | Charger | 407-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | BCH001359 | Charger | 407-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Counter Readings | LTC Operations Since Last Insp | 987 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | BCH001359 | Charger | 407-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Fault Operations Ground | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Maintenance Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Operations Counter AF | 121 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Operations Counter AL | 121 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Operations This Read Vac | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Switching Operations | 0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | General Comments | | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Unknown Operations | 0 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001766 | BreakerVacuum | 784-0209 | VCB Readings | Unknown Operations | 0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Counter Readings | LTC As Left Counter | 59125 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Counter Readings | LTC As Found Counter | 59120 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Counter Readings | General Comments | | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BAT001069 | Battery | 784-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BAT001069 | Battery | 784-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Follow-up Action Required? | n | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Fault Operations Ground | 0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BAT001069 | Battery | 784-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BAT001069 | Battery | 784-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BAT001069 | Battery | 784-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BAT001069 | Battery | 784-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | 9 Month Operations | 2 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Amps A Ø | 27.0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Amps B Ø | 25.0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | General Comments | | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Amps C Ø | 9.0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Patrol Inspection | General Comments | | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Maintenance Operations | 0 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BAT001069 | Battery | 784-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BAT001069 | Battery | 784-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 35 | °F |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BAT001069 | Battery | 784-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BAT001069 | Battery | 784-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BAT001069 | Battery | 784-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BAT001069 | Battery | 784-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Fault Operations Ground | 0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | General Comments | | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Follow-up Action Required? | n | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Patrol Inspection | General Comments | | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | General Comments | | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Maintenance Operations | 0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Operations Counter AF | 167 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | ST000512 | Structure | 407-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | 9 Month Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Operations Counter AL | 167 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Operations This Read Vac | 1 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Switching Operations | 1 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | General Comments | | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | YD000540 | Yard | 784-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001767 | BreakerVacuum | 784-2210 | VCB Readings | Unknown Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | BCH001359 | Charger | 407-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | LTCM000097 | LTCMechanism | 784-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Amps A Ø | 0.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Amps B Ø | 0.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Amps C Ø | 0.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001876 | BreakerVacuum | CF-1206 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Unknown Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | 9 Month Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Amps A Ø | 0.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Amps B Ø | 0.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Amps C Ø | 0.0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Fault Operations Ground | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Patrol Inspection | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Maintenance Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Operations Counter AF | 106 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Operations Counter AL | 106 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Operations This Read Vac | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Switching Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001877 | BreakerVacuum | CF-1207 | VCB Readings | Unknown Operations | 0 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | 9 Month Operations | 7 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BK001121 | BreakerVacuum | 784-2211 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | K0049 | BreakerVacuum | 407-2208 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | WithLTC | CF-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | BK001697 | BreakerSF6 | CF-138KV TR 2 | GCB Readings | Unknown Operations | 0 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 28421 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 28421 | |
| 1/13/2023 12:07 | Distribution | Centerfield Quarterly Inspection | LT0051 | LTCMechanism | CF-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Amps C Ø | 215.0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Amps B Ø | 201.0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Amps A Ø | 204.0 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | ST000544 | Structure | 784-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | 9 Month Operations | 5 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BCH001364 | Charger | 408-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Switching Operations | 1 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Operations This Read Vac | 1 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BCH001364 | Charger | 408-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BCH001364 | Charger | 408-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BCH001364 | Charger | 408-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.4 | amps |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Operations Counter AL | 227 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .3852 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | General Comments | | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | S0046 | NonLTC | 407-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Readings | Operations Counter AF | 226 | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/13/2023 11:07 | Distribution | Russell Springs Quarterly Inspection | BK000910 | BreakerVacuum | 408-2222 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/13/2023 13:07 | Distribution | Columbia South Quarterly Inspection | YD000509 | Yard | 407-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/13/2023 13:48 | Distribution | Columbia Quarterly Inspection | BAT001069 | Battery | 784-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | PF001302 | PowerFuse | WH-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Fault Operations Ground | 0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Counter Readings | General Comments | | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 538 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | PT002280 | PT | WH-12KV TR 2 POT | PT Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | PT002280 | PT | WH-12KV TR 2 POT | PT Patrol Inspection | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | PT002280 | PT | WH-12KV TR 2 POT | PT Patrol Inspection | Foundation Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | PT002280 | PT | WH-12KV TR 2 POT | PT Patrol Inspection | General Comments | | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | PT002280 | PT | WH-12KV TR 2 POT | PT Patrol Inspection | Grounds in Place? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 16L | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 11L | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 22531 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 22531 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Amps B Ø | 52.0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Amps C Ø | 49.0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Amps B Ø | 75.0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | PF001302 | PowerFuse | WH-12KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Amps C Ø | 80.0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | 9 Months Operations | 0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BAT001023 | Battery | WH-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BAT001023 | Battery | WH-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 78 | °F |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BAT001023 | Battery | WH-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | PF001301 | PowerFuse | WH-12KV TR 3 POTS | Disconnect Powerfuse Inspection | General Comments | OK | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | PF001301 | PowerFuse | WH-12KV TR 3 POTS | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | PF001301 | PowerFuse | WH-12KV TR 3 POTS | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Fault Adjusted Amps B Phase AM | 22.36 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | PF001302 | PowerFuse | WH-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Fault Operations B Ø | 2 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Amps A Ø | 57.0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Unknown Operations | 0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BCH000122 | Charger | WH-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BCH000122 | Charger | WH-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 5.0 | amps |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BCH000122 | Charger | WH-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 54.0 | VDC |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BCH000122 | Charger | WH-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 54.0 | VDC |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BCH000122 | Charger | WH-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | PF000425 | PowerFuse | WH-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Switching Operations | 0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Operations This Read Vac | 0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Operations Counter AL | 199 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Operations Counter AF | 199 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | PT002280 | PT | WH-12KV TR 2 POT | PT Patrol Inspection | Tank Oil Level | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | PT002280 | PT | WH-12KV TR 2 POT | PT Patrol Inspection | Tank Paint Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | PF000425 | PowerFuse | WH-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BCH000122 | Charger | WH-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | General Comments | | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BCH000122 | Charger | WH-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Maintenance Operations | 0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | General Comments | | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | General Comments | | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Unknown Operations | 0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Switching Operations | 0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Operations This Read AM | 2 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Operations Counter AL | 1486 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Operations Counter AF | 1486 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Maintenance Operations | 0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | General Comments | | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Patrol Inspection | General Comments | | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BCH000122 | Charger | WH-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | 9 Month Operations | 4 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BK001263 | BreakerVacuum | WH-1116 | VCB Readings | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | ST000599 | Structure | WH-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | 9 Months Operations | 2 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Counter Readings | LTC Operations Since Last Insp | 154 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Amps A Ø | 50.0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | PT002280 | PT | WH-12KV TR 2 POT | PT Patrol Inspection | PT Free of Leaks? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1153 | BreakerAirMagnetic | WH-1115 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Counter Readings | LTC Max Tap Position | 5R | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Counter Readings | LTC As Left Counter | 34536 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | LTCMechanism | WH-TRANS 3 | LTC Counter Readings | LTC As Found Counter | 34536 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | LTCMechanism | WH-TRANS 2 | LTC Counter Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | SWG000044 | Switchgear | WH-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LTCC000387 | LTCControl | WH-TRANS 2 | LTC Control Insp | All Connections OK? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LTCC000387 | LTCControl | WH-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LTCC000387 | LTCControl | WH-TRANS 2 | LTC Control Insp | General Comments | | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | General Comments | | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Maintenance Operations | 0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Operations Counter AF | 1342 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Operations Counter AL | 1342 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Operations This Read AM | 0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Switching Operations | 0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Unknown Operations | 0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | PT002279 | PT | WH-12KV TR 3 POT | PT Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | General Comments | | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Patrol Inspection | General Comments | | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Amps C Ø | 0.0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Readings | Percent Thermal Load C Ø Max | 60 | % |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Readings | Percent Thermal Load B Ø Max | 60 | % |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Readings | Percent Thermal Load A Ø Max | 60 | % |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 52 | °C |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .8 | psi |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Readings | H3 Winding Temp Present | 60 | °C |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Readings | H3 Winding Temp Max | 30 | °C |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Amps B Ø | 0.0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Amps A Ø | 0.0 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0224 | WithLTC | WH-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Readings | General Comments | | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LT0223 | WithLTC | WH-TRANS 3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | PT002279 | PT | WH-12KV TR 3 POT | PT Patrol Inspection | Tank Paint Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | PT002279 | PT | WH-12KV TR 3 POT | PT Patrol Inspection | Tank Oil Level | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | PT002279 | PT | WH-12KV TR 3 POT | PT Patrol Inspection | PT Free of Leaks? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BAT001023 | Battery | WH-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BAT001023 | Battery | WH-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LTCC000182 | LTCControl | WH-TRANS 3 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LTCC000182 | LTCControl | WH-TRANS 3 | LTC Control Insp | General Comments | | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BAT001023 | Battery | WH-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BAT001023 | Battery | WH-Battery Bank | Battery Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | PT002279 | PT | WH-12KV TR 3 POT | PT Patrol Inspection | Grounds in Place? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | PT002279 | PT | WH-12KV TR 3 POT | PT Patrol Inspection | General Comments | | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | PT002279 | PT | WH-12KV TR 3 POT | PT Patrol Inspection | Foundation Condition | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | PT002279 | PT | WH-12KV TR 3 POT | PT Patrol Inspection | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LTCC000182 | LTCControl | WH-TRANS 3 | LTC Control Insp | All Connections OK? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BAT001023 | Battery | WH-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BAT001023 | Battery | WH-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | General Comments | | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | General Comments | | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BAT001023 | Battery | WH-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BAT001023 | Battery | WH-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | CH000158 | ControlHouse | WH-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | BAT001023 | Battery | WH-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | FE000606 | Fence | WH-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Ambient Temp | 54 | °F |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | YD000609 | Yard | WH-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/12/2023 9:42 | Distribution | WHAS Quarterly Inspection | LB1152 | BreakerAirMagnetic | WH-1114 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LTCC000146 | LTCControl | SSC-Offline-Distribution | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LTCC000146 | LTCControl | SSC-Offline-Distribution | LTC Control Insp | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LTCC000146 | LTCControl | SSC-Offline-Distribution | LTC Control Insp | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LTCC000146 | LTCControl | SSC-Offline-Distribution | LTC Control Insp | All Connections OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | LTCMechanism | P-TRANS 4A | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0153 | GroundTransformer | P-GND TR 2A | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0153 | GroundTransformer | P-GND TR 2A | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0740 | BreakerVacuum | P-1389-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0740 | BreakerVacuum | P-1389-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | LTCMechanism | P-TRANS 4A | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0153 | GroundTransformer | P-GND TR 2A | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | LTCMechanism | P-TRANS 4A | LTC Counter Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | LTCMechanism | P-TRANS 4A | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | LTCMechanism | P-TRANS 4A | LTC Counter Readings | LTC As Found Counter | 37187 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0776 | BreakerOil | P-SPARE # 10 | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0776 | BreakerOil | P-SPARE # 10 | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0740 | BreakerVacuum | P-1389-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Readings | General Comments | | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Switching Operations | 4 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Operations This Read Vac | 4 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Readings | Operations Counter AL | 1356 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | LTCMechanism | P-TRANS 4A | LTC Counter Readings | LTC As Left Counter | 37187 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Readings | Operations This Read Oil | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0740 | BreakerVacuum | P-1389-2 | VCB Readings | 9 Month Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0740 | BreakerVacuum | P-1389-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0740 | BreakerVacuum | P-1389-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0153 | GroundTransformer | P-GND TR 2A | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0740 | BreakerVacuum | P-1389-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0740 | BreakerVacuum | P-1389-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0740 | BreakerVacuum | P-1389-2 | VCB Readings | Amps A Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0740 | BreakerVacuum | P-1389-2 | VCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0740 | BreakerVacuum | P-1389-2 | VCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0740 | BreakerVacuum | P-1389-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0740 | BreakerVacuum | P-1389-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Operations Counter AF | 670 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Readings | Operations Counter AF | 3256 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Readings | Switching Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Patrol Inspection | Pressure Vessel Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Readings | Operations This Read Oil | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Readings | Operations Counter AL | 132 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0153 | GroundTransformer | P-GND TR 2A | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0153 | GroundTransformer | P-GND TR 2A | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Operations Counter AL | 674 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Readings | Number of Ops last 9 Months | 1 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0153 | GroundTransformer | P-GND TR 2A | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0753 | BreakerVacuum | P-14KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0753 | BreakerVacuum | P-14KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0753 | BreakerVacuum | P-14KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0153 | GroundTransformer | P-GND TR 2A | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0153 | GroundTransformer | P-GND TR 2A | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0153 | GroundTransformer | P-GND TR 2A | Ground Transformer Patrol Inspection | General Comments | | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0776 | BreakerOil | P-SPARE # 10 | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0776 | BreakerOil | P-SPARE # 10 | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Readings | Operations Counter AF | 132 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Readings | Number of Ops last 9 Months | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0776 | BreakerOil | P-SPARE # 10 | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0153 | GroundTransformer | P-GND TR 2A | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0153 | GroundTransformer | P-GND TR 2A | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0740 | BreakerVacuum | P-1389-2 | VCB Readings | Operations Counter AF | 99967 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0740 | BreakerVacuum | P-1389-2 | VCB Readings | Operations Counter AL | 99967 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0740 | BreakerVacuum | P-1389-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0740 | BreakerVacuum | P-1389-2 | VCB Readings | Switching Operations | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Amps C Ø | 60.0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Amps B Ø | 60.0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Amps A Ø | 60.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0740 | BreakerVacuum | P-1389-2 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | 9 Month Operations | 6 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0776 | BreakerOil | P-SPARE # 10 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0776 | BreakerOil | P-SPARE # 10 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0776 | BreakerOil | P-SPARE # 10 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Readings | Switching Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Amps C Ø | 40.0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | 9 Month Operations | 31 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Amps B Ø | 40.0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Amps A Ø | 40.0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Patrol Inspection | Air Compressor Belt Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Patrol Inspection | Air Tank Bleed (> 40°F)? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Patrol Inspection | Air Pressure OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Patrol Inspection | Air Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Patrol Inspection | Pressure Vessel Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Readings | Switching Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0740 | BreakerVacuum | P-1389-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | LTCMechanism | P-TRANS 4A | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | LTCMechanism | P-TRANS 4A | LTC Counter Readings | LTC Current Tap Position | 6 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0776 | BreakerOil | P-SPARE # 10 | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | LTCMechanism | P-TRANS 5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | LTCMechanism | P-TRANS 4A | LTC Counter Readings | LTC Max Tap Position | 6 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | LTCMechanism | P-TRANS 4A | LTC Counter Readings | LTC Min Tap Position | 6 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | LTCMechanism | P-TRANS 4A | LTC Counter Readings | LTC Operations Since Last Insp | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0776 | BreakerOil | P-SPARE # 10 | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | General Comments | | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | LTCMechanism | P-TRANS 4A | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | LTCMechanism | P-TRANS 4A | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | LTCMechanism | P-TRANS 4A | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | LTCMechanism | P-TRANS 5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | LTCMechanism | P-TRANS 5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | LTCMechanism | P-TRANS 5 | LTC Counter Readings | LTC Operations Since Last Insp | 396 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | LTCMechanism | P-TRANS 5 | LTC Counter Readings | LTC Min Tap Position | 5 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | LTCMechanism | P-TRANS 5 | LTC Counter Readings | LTC Max Tap Position | 5 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | LTCMechanism | P-TRANS 5 | LTC Counter Readings | LTC Current Tap Position | 5 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | LTCMechanism | P-TRANS 5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | LTCMechanism | P-TRANS 5 | LTC Counter Readings | LTC As Left Counter | 78034 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | LTCMechanism | P-TRANS 5 | LTC Counter Readings | LTC As Found Counter | 78034 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | LTCMechanism | P-TRANS 5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | LTCMechanism | P-TRANS 5 | LTC Counter Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | LTCMechanism | P-TRANS 5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | LTCMechanism | P-TRANS 5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0740 | BreakerVacuum | P-1389-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | LTCMechanism | P-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0740 | BreakerVacuum | P-1389-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0740 | BreakerVacuum | P-1389-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0740 | BreakerVacuum | P-1389-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | LTCMechanism | P-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Low | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | LTCMechanism | P-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | LTCMechanism | P-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | ltc oil level low | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | LTCMechanism | P-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0740 | BreakerVacuum | P-1389-2 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0740 | BreakerVacuum | P-1389-2 | VCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Readings | 9 Months Operations OCB New | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0740 | BreakerVacuum | P-1389-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0156 | GroundTransformer | P-GND TR 1 A&B | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0156 | GroundTransformer | P-GND TR 1 A&B | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0156 | GroundTransformer | P-GND TR 1 A&B | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | General Comments | | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Readings | Winding Temp Present | 40 | °C |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Readings | General Comments | CANT RESET LIQUID GAUGE | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 400 | psi |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Readings | Oil Temp Max | 120 | °C |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Readings | WithLTC Trn Dynamic Health | 290.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Readings | WLTC Bushing Dynamic Health | 200.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Readings | X2 Winding Temp Max | 30 | °C |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Readings | X2 Winding Temp Present | 20 | °C |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Readings | Switching Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Patrol Inspection | Pressure Vessel Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Readings | Operations This Read Oil | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .2970 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Readings | Winding Temp Max | 40 | °C |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Readings | Winding Temp Present | 30 | °C |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0156 | GroundTransformer | P-GND TR 1 A&B | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0156 | GroundTransformer | P-GND TR 1 A&B | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0156 | GroundTransformer | P-GND TR 1 A&B | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0156 | GroundTransformer | P-GND TR 1 A&B | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Readings | 9 Months Operations OCB New | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0156 | GroundTransformer | P-GND TR 1 A&B | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0156 | GroundTransformer | P-GND TR 1 A&B | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0156 | GroundTransformer | P-GND TR 1 A&B | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0156 | GroundTransformer | P-GND TR 1 A&B | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0156 | GroundTransformer | P-GND TR 1 A&B | Ground Transformer Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0156 | GroundTransformer | P-GND TR 1 A&B | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0156 | GroundTransformer | P-GND TR 1 A&B | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Readings | Number of Ops last 9 Months | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Readings | Operations Counter AF | 829 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Readings | Operations Counter AL | 829 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Readings | Operations This Read Oil | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Readings | Switching Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Patrol Inspection | Tank 1 Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0765 | BreakerOil | P-GND TR 1 A&B-A | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0131 | WithLTC | P-TRANS 4A | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0770 | BreakerOil | P-RES AUX 1-2-3 | OCB Readings | 9 Months Operations OCB New | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0770 | BreakerOil | P-RES AUX 1-2-3 | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0770 | BreakerOil | P-RES AUX 1-2-3 | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0770 | BreakerOil | P-RES AUX 1-2-3 | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0770 | BreakerOil | P-RES AUX 1-2-3 | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0770 | BreakerOil | P-RES AUX 1-2-3 | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0770 | BreakerOil | P-RES AUX 1-2-3 | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0770 | BreakerOil | P-RES AUX 1-2-3 | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0770 | BreakerOil | P-RES AUX 1-2-3 | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0770 | BreakerOil | P-RES AUX 1-2-3 | OCB Readings | Switching Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0770 | BreakerOil | P-RES AUX 1-2-3 | OCB Readings | Operations This Read Oil | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0770 | BreakerOil | P-RES AUX 1-2-3 | OCB Readings | Operations Counter AL | 646 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0770 | BreakerOil | P-RES AUX 1-2-3 | OCB Readings | Operations Counter AF | 646 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0770 | BreakerOil | P-RES AUX 1-2-3 | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0770 | BreakerOil | P-RES AUX 1-2-3 | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0770 | BreakerOil | P-RES AUX 1-2-3 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0770 | BreakerOil | P-RES AUX 1-2-3 | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0770 | BreakerOil | P-RES AUX 1-2-3 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0770 | BreakerOil | P-RES AUX 1-2-3 | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0770 | BreakerOil | P-RES AUX 1-2-3 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0770 | BreakerOil | P-RES AUX 1-2-3 | OCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Readings | General Comments | | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0770 | BreakerOil | P-RES AUX 1-2-3 | OCB Readings | Number of Ops last 9 Months | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0770 | BreakerOil | P-RES AUX 1-2-3 | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0770 | BreakerOil | P-RES AUX 1-2-3 | OCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0770 | BreakerOil | P-RES AUX 1-2-3 | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0770 | BreakerOil | P-RES AUX 1-2-3 | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0770 | BreakerOil | P-RES AUX 1-2-3 | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.4 | volts |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 9348.48 | kw |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 25.00 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 20.00 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 33912 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1490 | Regulator | 642-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Readings | Totalizer Meter Reading | .9738 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Readings | Winding Temp Max | 50 | °C |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Readings | 9 Months Operations OCB New | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Readings | 9 Months Operations OCB New | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Patrol Inspection | Air Compressor Belt Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Patrol Inspection | Air Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LTCC000145 | LTCControl | P-TRANS 2 | LTC Control Insp | All Connections OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LTCC000145 | LTCControl | P-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LTCC000145 | LTCControl | P-TRANS 2 | LTC Control Insp | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LTCC000145 | LTCControl | P-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Readings | Operations Counter AL | 1846 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Patrol Inspection | Air Pressure OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 245.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Readings | Operations Counter AF | 1846 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Readings | Number of Ops last 9 Months | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Patrol Inspection | Air Tank Bleed (> 40°F)? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0737 | BreakerOil | P-1388-A | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | Ambient Temp | 46 | °F |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | YD000484 | Yard | 642-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0147 | WithLTC | P-TRANS 5 | LTC Transformer Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Readings | Operations This Read Oil | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Readings | Operations Counter AL | 1944 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0778 | BreakerOil | P-SPARE # 12 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0778 | BreakerOil | P-SPARE # 12 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0778 | BreakerOil | P-SPARE # 12 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0778 | BreakerOil | P-SPARE # 12 | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0778 | BreakerOil | P-SPARE # 12 | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Patrol Inspection | Air Tank Bleed (> 40°F)? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Patrol Inspection | Air Pressure OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Patrol Inspection | Air Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Patrol Inspection | Air Compressor Belt Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Readings | 9 Months Operations OCB New | 1 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0778 | BreakerOil | P-SPARE # 12 | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0778 | BreakerOil | P-SPARE # 12 | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0778 | BreakerOil | P-SPARE # 12 | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0778 | BreakerOil | P-SPARE # 12 | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0778 | BreakerOil | P-SPARE # 12 | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Readings | Operations Counter AF | 1944 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Readings | Number of Ops last 9 Months | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Readings | 9 Months Operations OCB New | 1 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Readings | Number of Ops last 9 Months | 2 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Readings | Operations Counter AF | 5494 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Readings | Operations Counter AL | 5494 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Readings | Operations This Read Oil | 1 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Readings | Switching Operations | 1 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0767 | BreakerOil | P-GND TR 2-A | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0229 | BreakerVacuum | 642-2233 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | General Comments | Replaced trip arm and latch. Replaced reclosure. | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Maintenance Operations | 25 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Operations Counter AF | 682 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Operations Counter AL | 711 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Operations This Read Vac | 29 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0753 | BreakerVacuum | P-14KV TR 1 | VCB Readings | Operations Counter AL | 141 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0753 | BreakerVacuum | P-14KV TR 1 | VCB Readings | Operations Counter AF | 141 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0753 | BreakerVacuum | P-14KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0753 | BreakerVacuum | P-14KV TR 1 | VCB Readings | General Comments | | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Switching Operations | 4 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CB0230 | BreakerVacuum | 642-2230 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | General Comments | | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | LTCMechanism | P-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | LTCMechanism | P-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | LTCMechanism | P-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | High | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | LTCMechanism | P-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 149 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | LTCMechanism | P-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 9 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | LTCMechanism | P-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 10 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | LTCMechanism | P-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 9 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | LTCMechanism | P-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | LTCMechanism | P-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 303237 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | LTCMechanism | P-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 303237 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | LTCMechanism | P-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | LTCMechanism | P-TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | LTCMechanism | P-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | LTCMechanism | P-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KT0005 | NonLTC | 642-2 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0759 | BreakerOil | P-14KV TR 5-A | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | LTCC000618 | LTCControl | 642-1 B | LTC Control Insp | LTC Operation Checked? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | LTCC000618 | LTCControl | 642-1 B | LTC Control Insp | LTC Output Voltage Level | 123.8 | VAC |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | LTCC000618 | LTCControl | 642-1 B | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | LTCC000618 | LTCControl | 642-1 B | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | LTCC000618 | LTCControl | 642-1 B | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Regulator As Left Counter | 54676 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000292 | PowerFuse | P-14KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Readings | General Comments | | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 2138.40 | kw |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000292 | PowerFuse | P-14KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | General Comments | | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0012 | Regulator | 642-2 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | General Comments | | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | General Comments | | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | ST000485 | Structure | 642-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | S0051 | NonLTC | 642-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0753 | BreakerVacuum | P-14KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0753 | BreakerVacuum | P-14KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0753 | BreakerVacuum | P-14KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0753 | BreakerVacuum | P-14KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0753 | BreakerVacuum | P-14KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0753 | BreakerVacuum | P-14KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0753 | BreakerVacuum | P-14KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0753 | BreakerVacuum | P-14KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0753 | BreakerVacuum | P-14KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0753 | BreakerVacuum | P-14KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0753 | BreakerVacuum | P-14KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0753 | BreakerVacuum | P-14KV TR 1 | VCB Readings | Amps C Ø | 161.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0753 | BreakerVacuum | P-14KV TR 1 | VCB Readings | Amps B Ø | 161.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0753 | BreakerVacuum | P-14KV TR 1 | VCB Readings | Amps A Ø | 164.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0753 | BreakerVacuum | P-14KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0753 | BreakerVacuum | P-14KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0753 | BreakerVacuum | P-14KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0753 | BreakerVacuum | P-14KV TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0753 | BreakerVacuum | P-14KV TR 1 | VCB Readings | 9 Month Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0773 | BreakerOil | P-SEC TIE 1-A | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | LTCC000618 | LTCControl | 642-1 B | LTC Control Insp | All Connections OK? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | LTCC000618 | LTCControl | 642-1 B | LTC Control Insp | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | FE000477 | Fence | 642-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | nitr cyl. at 0 psi | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 50 | °C |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0155 | WithLTC | P-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | LTCC000618 | LTCControl | 642-1 B | LTC Control Insp | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Readings | Operations Counter AF | 1259 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Readings | Operations Counter AL | 1259 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Readings | Operations This Read Oil | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Readings | Switching Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Patrol Inspection | Air Tank Bleed (> 40°F)? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Operations Counter AF | 277 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Operations Counter AL | 278 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Operations This Read Vac | 1 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Switching Operations | 1 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 135.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Patrol Inspection | Tank 3 Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0780 | BreakerOil | P-SPARE # 2 | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0780 | BreakerOil | P-SPARE # 2 | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0780 | BreakerOil | P-SPARE # 2 | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0780 | BreakerOil | P-SPARE # 2 | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0735 | BreakerVacuum | P-1387-1 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0735 | BreakerVacuum | P-1387-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0735 | BreakerVacuum | P-1387-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000093 | Switchgear | P-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000093 | Switchgear | P-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000093 | Switchgear | P-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0780 | BreakerOil | P-SPARE # 2 | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0780 | BreakerOil | P-SPARE # 2 | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0780 | BreakerOil | P-SPARE # 2 | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0780 | BreakerOil | P-SPARE # 2 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0780 | BreakerOil | P-SPARE # 2 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0780 | BreakerOil | P-SPARE # 2 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Readings | 9 Months Operations OCB New | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Patrol Inspection | Air Compressor Belt Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Patrol Inspection | Air Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Readings | 9 Months Operations OCB New | 1 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Patrol Inspection | Air Pressure OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0721 | BreakerOil | P-1380-A | OCB Readings | Number of Ops last 9 Months | 1 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Amps B Ø | 257.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Amps C Ø | 268.0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000295 | PowerFuse | P-14KV TR 5 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000295 | PowerFuse | P-14KV TR 5 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000296 | PowerFuse | P-TR 5 AUX PWR | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000296 | PowerFuse | P-TR 5 AUX PWR | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000297 | PowerFuse | P-14KV TR 4-B POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000297 | PowerFuse | P-14KV TR 4-B POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000299 | PowerFuse | P-1393 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000299 | PowerFuse | P-1393 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Readings | Switching Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Patrol Inspection | Pressure Vessel Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Readings | Operations This Read Oil | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Readings | Operations Counter AL | 1064 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Readings | Operations Counter AF | 1064 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Readings | Number of Ops last 9 Months | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0754 | BreakerVacuum | P-14KV TR 2 | VCB Readings | 9 Month Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0754 | BreakerVacuum | P-14KV TR 2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0754 | BreakerVacuum | P-14KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0754 | BreakerVacuum | P-14KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0754 | BreakerVacuum | P-14KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 66 | °F |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | BAT001301 | Battery | 642-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0754 | BreakerVacuum | P-14KV TR 2 | VCB Readings | Amps A Ø | 290.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0754 | BreakerVacuum | P-14KV TR 2 | VCB Readings | Amps B Ø | 290.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0754 | BreakerVacuum | P-14KV TR 2 | VCB Readings | Amps C Ø | 293.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0754 | BreakerVacuum | P-14KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0754 | BreakerVacuum | P-14KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0754 | BreakerVacuum | P-14KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0754 | BreakerVacuum | P-14KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0754 | BreakerVacuum | P-14KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0754 | BreakerVacuum | P-14KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0754 | BreakerVacuum | P-14KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0754 | BreakerVacuum | P-14KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0754 | BreakerVacuum | P-14KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0754 | BreakerVacuum | P-14KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0754 | BreakerVacuum | P-14KV TR 2 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0754 | BreakerVacuum | P-14KV TR 2 | VCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0754 | BreakerVacuum | P-14KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0754 | BreakerVacuum | P-14KV TR 2 | VCB Readings | Operations Counter AF | 585 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0754 | BreakerVacuum | P-14KV TR 2 | VCB Readings | Operations Counter AL | 585 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0754 | BreakerVacuum | P-14KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0754 | BreakerVacuum | P-14KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0754 | BreakerVacuum | P-14KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | 9 Month Operations | 3 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000289 | PowerFuse | P-STA SER 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000289 | PowerFuse | P-STA SER 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Amps A Ø | 274.0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Amps B Ø | 74.0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Amps A Ø | 96.0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Readings | Switching Operations | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Patrol Inspection | Pressure Vessel Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | 9 Month Operations | 3 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Readings | Operations This Read Oil | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Readings | Operations Counter AL | 6240 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Readings | Operations Counter AF | 6240 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Readings | Number of Ops last 9 Months | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Patrol Inspection | AirCompressor Heater Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Patrol Inspection | Air Tank Bleed (> 40°F)? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Patrol Inspection | Air Pressure OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Patrol Inspection | Air Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0771 | BreakerOil | P-SEC REA TIE 1-A | OCB Readings | 9 Months Operations OCB New | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Readings | 9 Months Operations OCB New | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | General Comments | | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 51586 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0743 | BreakerVacuum | P-1393-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0743 | BreakerVacuum | P-1393-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0743 | BreakerVacuum | P-1393-1 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0016 | BreakerVacuum | 642-2228 | VCB Readings | Amps C Ø | 98.0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000093 | Switchgear | P-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000093 | Switchgear | P-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000093 | Switchgear | P-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000093 | Switchgear | P-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000093 | Switchgear | P-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000093 | Switchgear | P-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000093 | Switchgear | P-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000093 | Switchgear | P-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000093 | Switchgear | P-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000093 | Switchgear | P-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000093 | Switchgear | P-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000093 | Switchgear | P-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000093 | Switchgear | P-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000093 | Switchgear | P-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000093 | Switchgear | P-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000093 | Switchgear | P-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0748 | BreakerVacuum | P-1393-2 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0748 | BreakerVacuum | P-1393-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0748 | BreakerVacuum | P-1393-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 65 | °C |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1489 | Regulator | 642-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Readings | Number of Ops last 9 Months | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Readings | Operations Counter AF | 995 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Readings | Operations Counter AL | 995 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Readings | Operations This Read Oil | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Readings | Switching Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0723 | BreakerOil | P-1381-A | OCB Readings | Unknown Operations | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 44396 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.7 | volts |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF001283 | PowerFuse | P-1392 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF001283 | PowerFuse | P-1392 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0146 | WithLTC | P-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | R1488 | Regulator | 642-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Readings | Switching Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Readings | Operations This Read Oil | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Readings | Operations Counter AL | 1186 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Readings | Operations Counter AF | 1186 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0734 | BreakerVacuum | P-1386-2 | VCB Readings | 9 Month Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0734 | BreakerVacuum | P-1386-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0734 | BreakerVacuum | P-1386-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0734 | BreakerVacuum | P-1386-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0734 | BreakerVacuum | P-1386-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0734 | BreakerVacuum | P-1386-2 | VCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0734 | BreakerVacuum | P-1386-2 | VCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0734 | BreakerVacuum | P-1386-2 | VCB Readings | Amps C Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0734 | BreakerVacuum | P-1386-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0734 | BreakerVacuum | P-1386-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Readings | Number of Ops last 9 Months | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0158 | GroundTransformer | P-GND TR 1 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0158 | GroundTransformer | P-GND TR 1 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0158 | GroundTransformer | P-GND TR 1 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0784 | BreakerOil | P-SPARE # 8 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0784 | BreakerOil | P-SPARE # 8 | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0784 | BreakerOil | P-SPARE # 8 | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0784 | BreakerOil | P-SPARE # 8 | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0784 | BreakerOil | P-SPARE # 8 | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0784 | BreakerOil | P-SPARE # 8 | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0784 | BreakerOil | P-SPARE # 8 | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0158 | GroundTransformer | P-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0158 | GroundTransformer | P-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0784 | BreakerOil | P-SPARE # 8 | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | LTCMechanism | GR-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | LTCMechanism | GR-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 7432 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | LTCMechanism | GR-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 6 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | LTCMechanism | GR-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 9 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | LTCMechanism | GR-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 8 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | LTCMechanism | GR-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 35539 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | LTCMechanism | GR-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 35539 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | LTCMechanism | GR-TRANS 2 | LTC Counter Readings | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | LTCMechanism | GR-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0732 | BreakerVacuum | P-1385-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0159 | GroundTransformer | P-GND TR 2 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0159 | GroundTransformer | P-GND TR 2 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0159 | GroundTransformer | P-GND TR 2 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0159 | GroundTransformer | P-GND TR 2 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | .4 | psi |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0159 | GroundTransformer | P-GND TR 2 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0159 | GroundTransformer | P-GND TR 2 | Ground Transformer Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0159 | GroundTransformer | P-GND TR 2 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0159 | GroundTransformer | P-GND TR 2 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0159 | GroundTransformer | P-GND TR 2 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0159 | GroundTransformer | P-GND TR 2 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Regulator As Left Counter | 56541 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0159 | GroundTransformer | P-GND TR 2 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0732 | BreakerVacuum | P-1385-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | General Comments | | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0732 | BreakerVacuum | P-1385-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0764 | BreakerVacuum | P-GND TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0764 | BreakerVacuum | P-GND TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0764 | BreakerVacuum | P-GND TR 1 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0732 | BreakerVacuum | P-1385-2 | VCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0732 | BreakerVacuum | P-1385-2 | VCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0732 | BreakerVacuum | P-1385-2 | VCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0732 | BreakerVacuum | P-1385-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0732 | BreakerVacuum | P-1385-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0732 | BreakerVacuum | P-1385-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0732 | BreakerVacuum | P-1385-2 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0732 | BreakerVacuum | P-1385-2 | VCB Readings | 9 Month Operations | 3 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Readings | Unknown Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Readings | 9 Months Operations OCB New | 1 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Readings | Switching Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Readings | Operations This Read Oil | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Readings | Operations Counter AL | 1171 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Readings | Operations Counter AF | 1171 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Readings | Number of Ops last 9 Months | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0158 | GroundTransformer | P-GND TR 1 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0158 | GroundTransformer | P-GND TR 1 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0158 | GroundTransformer | P-GND TR 1 | Ground Transformer Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0158 | GroundTransformer | P-GND TR 1 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0158 | GroundTransformer | P-GND TR 1 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0158 | GroundTransformer | P-GND TR 1 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0158 | GroundTransformer | P-GND TR 1 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0158 | GroundTransformer | P-GND TR 1 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Readings | 9 Months Operations OCB New | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0734 | BreakerVacuum | P-1386-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0734 | BreakerVacuum | P-1386-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0725 | BreakerOil | P-1382-A | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0153 | GroundTransformer | P-GND TR 2A | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LTCC000091 | LTCControl | P-TRANS 4A | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LTCC000091 | LTCControl | P-TRANS 4A | LTC Control Insp | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LTCC000091 | LTCControl | P-TRANS 4A | LTC Control Insp | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0011 | Regulator | 642-2 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Readings | Switching Operations | 2 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Readings | Operations This Read Oil | 2 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0158 | GroundTransformer | P-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Readings | Operations Counter AL | 724 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Readings | Operations Counter AF | 724 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Readings | Number of Ops last 9 Months | 3 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0727 | BreakerOil | P-1383-A | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0760 | BreakerOil | P-BUS TIE REA 2 | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0782 | BreakerOil | P-SPARE # 6 | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0782 | BreakerOil | P-SPARE # 6 | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0782 | BreakerOil | P-SPARE # 6 | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0782 | BreakerOil | P-SPARE # 6 | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0782 | BreakerOil | P-SPARE # 6 | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0782 | BreakerOil | P-SPARE # 6 | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0782 | BreakerOil | P-SPARE # 6 | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0782 | BreakerOil | P-SPARE # 6 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0782 | BreakerOil | P-SPARE # 6 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0782 | BreakerOil | P-SPARE # 6 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Patrol Inspection | Air Tank Bleed (> 40°F)? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Patrol Inspection | Air Pressure OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Patrol Inspection | Air Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Readings | Number of Ops last 9 Months | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Readings | Operations Counter AF | 1506 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Readings | Operations Counter AL | 1506 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Readings | Operations This Read Oil | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Readings | Switching Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Operations Counter AF | 352 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Operations Counter AL | 353 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Operations This Read Vac | 1 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Switching Operations | 1 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KB0004 | BreakerVacuum | 642-2229 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Readings | Number of Ops last 9 Months | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Readings | Operations Counter AF | 1171 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Readings | Operations Counter AL | 1171 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Readings | Operations This Read Oil | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Patrol Inspection | Pressure Vessel Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Readings | Switching Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0757 | BreakerOil | P-14KV TR 4-A | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | General Comments | | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF001212 | PowerFuse | P-14KV TR-4A AUX PWR | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF001212 | PowerFuse | P-14KV TR-4A AUX PWR | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Readings | 9 Months Operations OCB New | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | CH000377 | ControlHouse | 642-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0734 | BreakerVacuum | P-1386-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0734 | BreakerVacuum | P-1386-2 | VCB Readings | Operations Counter AL | 1176 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0734 | BreakerVacuum | P-1386-2 | VCB Readings | Operations Counter AF | 1176 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0734 | BreakerVacuum | P-1386-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0734 | BreakerVacuum | P-1386-2 | VCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0734 | BreakerVacuum | P-1386-2 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF001154 | PowerFuse | P-1387 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF001154 | PowerFuse | P-1387 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF001155 | PowerFuse | P-1391 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF001155 | PowerFuse | P-1391 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0732 | BreakerVacuum | P-1385-2 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0739 | BreakerVacuum | P-1389-1 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0732 | BreakerVacuum | P-1385-2 | VCB Readings | Switching Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0732 | BreakerVacuum | P-1385-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0732 | BreakerVacuum | P-1385-2 | VCB Readings | Operations Counter AL | 22 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0734 | BreakerVacuum | P-1386-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0734 | BreakerVacuum | P-1386-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Patrol Inspection | Air Compressor Belt Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0741 | BreakerOil | P-1390-A | OCB Readings | 9 Months Operations OCB New | 0 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0732 | BreakerVacuum | P-1385-2 | VCB Readings | Operations Counter AF | 22 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0732 | BreakerVacuum | P-1385-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0732 | BreakerVacuum | P-1385-2 | VCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0734 | BreakerVacuum | P-1386-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0734 | BreakerVacuum | P-1386-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0734 | BreakerVacuum | P-1386-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0734 | BreakerVacuum | P-1386-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0732 | BreakerVacuum | P-1385-2 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0732 | BreakerVacuum | P-1385-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0732 | BreakerVacuum | P-1385-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0732 | BreakerVacuum | P-1385-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0732 | BreakerVacuum | P-1385-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0732 | BreakerVacuum | P-1385-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LTCC000147 | LTCControl | P-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LTCC000147 | LTCControl | P-TRANS 1 | LTC Control Insp | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LTCC000147 | LTCControl | P-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LTCC000147 | LTCControl | P-TRANS 1 | LTC Control Insp | All Connections OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0732 | BreakerVacuum | P-1385-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0784 | BreakerOil | P-SPARE # 8 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0784 | BreakerOil | P-SPARE # 8 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | BCH001544 | Charger | 642-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0745 | BreakerOil | P-1392-A | OCB Readings | 9 Months Operations OCB New | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000294 | PowerFuse | P-14KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000294 | PowerFuse | P-14KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | BCH001544 | Charger | 642-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | BCH001544 | Charger | 642-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .7 | amps |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0739 | BreakerVacuum | P-1389-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0739 | BreakerVacuum | P-1389-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | BCH001544 | Charger | 642-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | BCH001544 | Charger | 642-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0159 | GroundTransformer | P-GND TR 2 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0159 | GroundTransformer | P-GND TR 2 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0159 | GroundTransformer | P-GND TR 2 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | BCH001544 | Charger | 642-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0732 | BreakerVacuum | P-1385-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0729 | BreakerOil | P-1384-A | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000203 | Switchgear | P-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000203 | Switchgear | P-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000203 | Switchgear | P-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000203 | Switchgear | P-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000203 | Switchgear | P-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000203 | Switchgear | P-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Regulator As Left Counter | 53442 | |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 1/11/2023 9:56 | Distribution | Union Underwear Quarterly Inspection | KR0010 | Regulator | 642-2 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000203 | Switchgear | P-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000203 | Switchgear | P-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000203 | Switchgear | P-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000203 | Switchgear | P-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000203 | Switchgear | P-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000203 | Switchgear | P-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000203 | Switchgear | P-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0734 | BreakerVacuum | P-1386-2 | VCB Readings | Switching Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0734 | BreakerVacuum | P-1386-2 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000203 | Switchgear | P-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000203 | Switchgear | P-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000203 | Switchgear | P-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000203 | Switchgear | P-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000203 | Switchgear | P-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | SWG000203 | Switchgear | P-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Readings | Switching Operations | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Readings | Fault Operations | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Readings | Operations This Read SF6 | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Readings | General Comments | | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Readings | Num Operations Last 9 Months | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Readings | Operations Counter AF | 730 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Readings | Operations Counter AL | 730 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Readings | 9 Month Operations GCB New | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | SF6 Pressure Indicator | good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | General Comments | | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Ambient Temperature | 50 | °F |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | TB0760 | BreakerSF6 | Retired Distribution | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 995 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 995 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 6 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 6 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 100.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 90.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 110.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 756 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 756 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 130.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 150.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 140.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 0.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 0.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 0.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 1 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 1 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 640 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 640 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0963 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 5 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0963 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0963 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0963 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0963 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0963 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0963 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0963 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 80.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0963 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 110.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0963 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0963 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 100.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0963 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0963 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0963 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0963 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 5 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0963 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0963 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 839 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0963 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 839 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0963 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0963 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0963 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0963 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 508 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 300.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 350.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 340.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 508 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0966 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0965 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0964 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0963 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0963 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0963 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0973 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | LTCC000349 | LTCControl | 930-Offline-Distribution | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | LTCC000349 | LTCControl | 930-Offline-Distribution | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | LTCC000349 | LTCControl | 930-Offline-Distribution | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | LTCC000349 | LTCControl | 930-Offline-Distribution | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | LTCC000349 | LTCControl | 930-Offline-Distribution | LTC Control Insp | LTC Output Voltage Level | 124 | VAC |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | LTCC000349 | LTCControl | 930-Offline-Distribution | LTC Control Insp | LTC Operation Checked? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | LTCC000349 | LTCControl | 930-Offline-Distribution | LTC Control Insp | General Comments | | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | LTCC000349 | LTCControl | 930-Offline-Distribution | LTC Control Insp | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | LTCC000349 | LTCControl | 930-Offline-Distribution | LTC Control Insp | All Connections OK? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Amps B Ø | 100.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Amps A Ø | 110.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | 9 Months Operations | 1 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | 9 Month Ops New | 1 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Readings | Oil Temp Max | 42 | °C |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | 9 Month Operations | 2 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Readings | Oil Temp Present | 15 | °C |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Amps C Ø | 300.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | 9 Month Operations | 3 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BCH001600 | Charger | SW-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BCH001600 | Charger | SW-Battery Charger | Battery Charger Patrol Insp | General Comments | Volatage says "out of range"  voltage after one minute trip is 50.8 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BCH001600 | Charger | SW-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BCH001600 | Charger | SW-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BCH001600 | Charger | SW-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 5.0 | amps |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BCH001600 | Charger | SW-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Counter Readings | LTC Operations Since Last Insp | 406 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Counter Readings | LTC Current Tap Position | 4R | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Counter Readings | LTC As Left Counter | 55561 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Counter Readings | LTC As Found Counter | 55561 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0432 | BreakerVacuum | HN-1200 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0432 | BreakerVacuum | HN-1200 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0432 | BreakerVacuum | HN-1200 | VCB Readings | Operations This Read Vac | 1 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Operations Counter AL | 75 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Operations Counter AF | 75 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Amps B Ø | 300.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Amps A Ø | 300.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Accumulated Fault Duty A Ph V | .96 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Accumulated Fault Duty B Ph V | .96 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Accumulated Fault Duty C Ph V | .48 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Amps A Ø | 192 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Amps C Ø | 165.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Amps B Ø | 170.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Amps A Ø | 161.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | 9 Months Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | 9 Month Operations | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Readings | 9 Month Operations | 5 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Amps B Ø | 201 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Amps C Ø | 191 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Amps C Ø | 120.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000290 | PowerFuse | P-STA SER 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000290 | PowerFuse | P-STA SER 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | PF000267 | PowerFuse | OX-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | PF000267 | PowerFuse | OX-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | SWG000079 | Switchgear | HN-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | SWG000079 | Switchgear | HN-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | SWG000079 | Switchgear | HN-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Amps B Ø | 130.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Amps C Ø | 136.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Operations Counter AL | 199 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Operations This Read Vac | 3 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Fault Adjusted Amps A Phase V | 22.36 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Fault Operations A Ø | 2 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | General Comments | a phase ioc | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | 9 Month Operations | 9 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | 9 Month Operations | 7 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Operations This Read Vac | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Operations Counter AL | 83 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Operations Counter AF | 83 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | General Comments | | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Amps A Ø | 100.0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Operations Counter AL | 83 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Operations Counter AF | 83 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Patrol Inspection | General Comments | | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | General Comments | | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Switching Operations | 3 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Operations Counter AF | 24 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Operations Counter AL | 24 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Operations This Read Vac | 2 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001950 | BreakerVacuum | HB-1147 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Readings | LV Winding Temp Max | 45 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Switching Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Operations This Read AM | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000774 | BreakerVacuum | P-1385-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Maintenance Operations | 3 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Operations Counter AF | 10 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Operations Counter AL | 10 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Operations This Read Vac | 4 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Switching Operations | 1 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Readings | 9 Month Operations | 5 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Operations Counter AL | 258 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Operations Counter AF | 258 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001939 | BreakerVacuum | TA-1105 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Operations Counter AL | 86 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0974 | BreakerAirMagnetic | SW-12KV TR 2 | AMCB Readings | Operations Counter AF | 86 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.2 | psi |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Operations Counter AF | 199 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Operations Counter AL | 199 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Operations This Read Vac | 4 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Switching Operations | 4 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | 9 Month Operations | 3 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 119 | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 25.4 | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 42.6 | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 30.2 | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 39 | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 61 | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Accumulated Fault Duty A Ph V | 1.47 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Accumulated Fault Duty B Ph V | 1.77 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Accumulated Fault Duty C Ph V | .59 | % |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | DX0130 | RecloserHydraulic | 564-0495 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Amps A Ø | 127.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Operations Counter AL | 22 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Amps C Ø | 190.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Amps B Ø | 170.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Amps A Ø | 110.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Readings | LV Winding Temp Present | 25 | °C |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Operations Counter AF | 664 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Operations Counter AL | 668 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Operations This Read Vac | 4 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | 9 Month Operations | 4 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | YD000668 | Yard | SY-Yard | Yard Patrol Inspection | Ambient Temp | 37 | °F |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Amps A Ø | 200.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Amps B Ø | 210.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Amps C Ø | 190.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | 9 Month Operations VCB New | 43 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | 9 Month Operations | 43 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Amps B Ø | 116.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Amps C Ø | 114.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Readings | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Readings | Operations Counter AF | 366 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Switching Operations | 4 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Readings | Switching Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Readings | Operations This Read Vac | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Readings | Operations Counter AL | 366 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Readings | Amps A Ø | 126.0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Readings | Amps B Ø | 130.0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Readings | Amps C Ø | 127.0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0432 | BreakerVacuum | HN-1200 | VCB Readings | Operations Counter AL | 696 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | 9 Month Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Readings | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Readings | Operations Counter AF | 355 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Readings | Operations Counter AL | 355 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Readings | Operations This Read Vac | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Readings | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Amps A Ø | 240.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Amps B Ø | 220.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Amps C Ø | 225.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Readings | Operations Counter AF | 117 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Readings | Operations Counter AL | 117 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Readings | General Comments | | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Amps C Ø | 400.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Amps B Ø | 401.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Amps A Ø | 391.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001938 | BreakerVacuum | TA-12KV TR 3 | VCB Readings | 9 Month Operations | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Counter Readings | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | LTCMechanism | 716-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0989 | NonLTC | 342-1 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BCH001600 | Charger | SW-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BCH001600 | Charger | SW-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000051 | Switchgear | TA-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | General Comments | | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Operations Counter AF | 242 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Operations Counter AL | 244 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Operations This Read Vac | 2 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Switching Operations | 2 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000280 | PowerFuse | P-14KV BUS SEC 2-B POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000280 | PowerFuse | P-14KV BUS SEC 2-B POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | 9 Month Operations | 5 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Amps A Ø | 340.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Amps B Ø | 349.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Amps C Ø | 322.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000685 | BreakerVacuum | SY-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Operations Counter AF | 22 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Readings | Switching Operations | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002137 | BreakerVacuum | OX-1280 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Readings | Switching Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Amps A Ø | 0.0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Amps B Ø | 0.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001951 | BreakerVacuum | HB-1146 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000772 | BreakerVacuum | HB-1148 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0109 | BreakerVacuum | 863-0232 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Amps C Ø | 0.0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 584 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 125.4 | volts |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Accumulated Fault Duty A Ph V | 13.85 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Accumulated Fault Duty B Ph V | 9.72 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Accumulated Fault Duty C Ph V | 7.95 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Amps A Ø | 121.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Amps B Ø | 138.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Amps C Ø | 113.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Operations Counter AL | 74 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Operations Counter AF | 74 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Amps A Ø | 60.0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Amps B Ø | 60.0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Amps C Ø | 60.0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Operations Counter AF | 144 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Operations Counter AL | 144 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Amps B Ø | 393 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Amps A Ø | 361 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | 9 Month Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | 9 Month Operations | 3 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Readings | 9 Month Operations | 1 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Maintenance Operations | 2 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Accumulated Fault Duty C Ph V | 3.99 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Accumulated Fault Duty B Ph V | .8 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Accumulated Fault Duty A Ph V | 3.19 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | 9 Month Operations | 5 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Counter Readings | LTC Operations Since Last Insp | 1284 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Operations Counter AF | 24 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Operations Counter AL | 24 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Operations This Read Vac | 3 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Switching Operations | 1 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Counter Readings | LTC As Left Counter | 55220 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Counter Readings | LTC As Found Counter | 55217 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Counter Readings | General Comments | | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | LTCMechanism | 310-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Operations Counter AL | 191 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Operations Counter AF | 191 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LTCC000281 | LTCControl | OX-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LTCC000281 | LTCControl | OX-TRANS 1 | LTC Control Insp | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LTCC000281 | LTCControl | OX-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LTCC000281 | LTCControl | OX-TRANS 1 | LTC Control Insp | All Connections OK? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Operations Counter AF | 258 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Operations Counter AL | 258 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Patrol Inspection | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Operations Counter AF | 236 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Operations Counter AL | 236 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Operations This Read AM | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0967 | BreakerAirMagnetic | SW-1188 | AMCB Readings | Switching Operations | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000688 | BreakerVacuum | SY-1252 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Amps C Ø | 91.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Amps B Ø | 89.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001942 | BreakerVacuum | TA-1172 | VCB Readings | Amps A Ø | 90.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Operations This Read Vac | 8 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Switching Operations | 8 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Amps C Ø | 369 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | 9 Month Operations | 12 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Readings | Operations Counter AF | 1174 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Readings | Winding Temp Present | 20 | °C |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Readings | Winding Temp Max | 30 | °C |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Readings | Totalizer Meter Reading | .4862 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 8 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 9L | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Readings | Amps A Ø | 20.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Readings | Amps B Ø | 20.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Readings | Amps C Ø | 20.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Readings | Fault Operations | 0 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AL | 39 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Operations Counter AF | 39 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Reg Output Voltage Level | 125.4 | volts |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Regulator As Left Counter | 164064 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Amps B Ø | 0.0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002133 | BreakerVacuum | OX-12KV BUS TIE SEC 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Readings | Amps A Ø | 118.0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Readings | Amps B Ø | 123.0 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Readings | Oil Temp Present | 15 | °C |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Readings | Amps C Ø | 115.0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LTCC000518 | LTCControl | HN-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LTCC000518 | LTCControl | HN-TRANS 1 | LTC Control Insp | All Connections OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Operations This Read Vac | 1 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Operations Counter AL | 178 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Operations Counter AF | 178 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Maintenance Operations | 1 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000301 | PowerFuse | P-1380 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | 9 Month Operations | 16 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | 9 Month Operations VCB New | 13 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Amps A Ø | 65.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Amps B Ø | 43.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Amps C Ø | 63.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000301 | PowerFuse | P-1380 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | PF000269 | PowerFuse | OX-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | PF000269 | PowerFuse | OX-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002134 | BreakerVacuum | OX-1277 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Readings | Operations Counter AL | 1174 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 12L | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Readings | Switching Operations | 0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 33671 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 33671 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Counter Readings | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | LTCMechanism | HB-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Readings | General Comments | | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001812 | BreakerVacuum | 863-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Readings | General Comments | | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0990 | NonLTC | 342-1 B | NonLTC Transformer Readings | Oil Temp Max | 42 | °C |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Readings | 9 Month Operations | 2 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0958 | Regulator | 310-2 C | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | 9 Month Operations | 4 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | 9 Month Operations | 7 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Amps A Ø | 415.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Grounds in Place? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Maintenance Operations | 4 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Operations Counter AF | 106 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Operations Counter AL | 106 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Operations This Read Vac | 5 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Switching Operations | 1 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Operations Counter AF | 12 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Operations Counter AL | 12 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Operations Counter AL | 196 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Operations Counter AF | 196 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | General Comments | | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Operations Counter AF | 196 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Amps B Ø | 0.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Maintenance Operations | 3 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | 9 Month Operations | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Amps C Ø | 173.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Amps B Ø | 166.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Amps A Ø | 192.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | 9 Month Operations | 9 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Amps A Ø | 133.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Amps B Ø | 123.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002136 | BreakerVacuum | OX-1279 | VCB Readings | Amps C Ø | 121.0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Amps B Ø | 435.0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Readings | Amps C Ø | 385.0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0441 | BreakerVacuum | 716-0023 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Switching Operations | 1 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Operations Counter AL | 63 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Operations Counter AF | 63 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | WithLTC | GR-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Operations This Read Vac | 4 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Operations Counter AL | 24 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002132 | BreakerVacuum | OX-12KV TR 2 | VCB Readings | Operations Counter AF | 24 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001940 | BreakerVacuum | TA-1131 | VCB Readings | Amps C Ø | 0.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Amps B Ø | 110.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Amps A Ø | 104.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Accumulated Fault Duty C Ph V | 5.3 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Accumulated Fault Duty B Ph V | 6.78 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Accumulated Fault Duty A Ph V | 6.19 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | 9 Month Operations | 2 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000686 | BreakerVacuum | SY-1250 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | 9 Month Operations | 1 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Readings | LTC Totalizer Reading | 7001.28 | kw |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Readings | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | 9 Month Operations | 10 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Amps A Ø | 9.0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Readings | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Readings | Operations Counter AF | 412 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000127 | Structure | 310-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | RG000213 | Regulator | 342-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Amps C Ø | 20.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Amps B Ø | 20.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Amps A Ø | 20.0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 800 | psi |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | WithLTC | 863-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000773 | BreakerVacuum | HB-1149 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BK000687 | BreakerVacuum | SY-1251 | VCB Readings | Amps C Ø | 110.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Amps C Ø | 154.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Amps B Ø | 147.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Amps A Ø | 159.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Accumulated Fault Duty C Ph V | .8 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Accumulated Fault Duty B Ph V | 3.99 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Accumulated Fault Duty A Ph V | 2.39 | % |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0272 | BreakerVacuum | 716-0128 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 485036 | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0882 | Regulator | 564-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | 9 Month Operations | 2 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Readings | Operations Counter AL | 412 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Readings | Operations This Read Vac | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Readings | Switching Operations | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Amps B Ø | 7.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Readings | Amps C Ø | 8.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK002135 | BreakerVacuum | OX-1278 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Operations Counter AL | 70 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Operations Counter AF | 70 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001941 | BreakerVacuum | TA-1130 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000131 | Switchgear | OX-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | 9 Month Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | 9 Month Operations VCB New | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Amps A Ø | 100.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Amps B Ø | 100.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Readings | Amps C Ø | 110.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001949 | BreakerVacuum | HB-1150 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1200 | psi |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.8 | psi |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Readings | General Comments | Unable to reset ALL gauges due to gauges being painted | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000078 | Switchgear | SY-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCC000335 | LTCControl | TA-TRANS 3 | LTC Control Insp | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCC000335 | LTCControl | TA-TRANS 3 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCC000336 | LTCControl | TA-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCC000336 | LTCControl | TA-TRANS 1 | LTC Control Insp | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCC000336 | LTCControl | TA-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCC000337 | LTCControl | TA-TRANS 4 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCC000337 | LTCControl | TA-TRANS 4 | LTC Control Insp | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCC000337 | LTCControl | TA-TRANS 4 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | 9 Month Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Accumulated Fault Duty A Ph V | 14.35 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Accumulated Fault Duty B Ph V | 15.94 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Accumulated Fault Duty C Ph V | 11.16 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Amps A Ø | 130.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Amps B Ø | 104.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Amps C Ø | 145.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | General Comments | | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | FE000122 | Fence | 310-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Operations Counter AF | 95 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Operations Counter AL | 95 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001063 | BreakerVacuum | TA-1106 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | 9 Month Operations | 2 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Amps A Ø | 86 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Amps B Ø | 106 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Amps C Ø | 82 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | PF000177 | PowerFuse | HN-12KV SEC 1 BUS POTS | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | PF000177 | PowerFuse | HN-12KV SEC 1 BUS POTS | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | 9 Month Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Accumulated Fault Duty A Ph V | 1.93 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Accumulated Fault Duty B Ph V | 1.93 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Accumulated Fault Duty C Ph V | 1.93 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Amps A Ø | 0.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Amps B Ø | 0.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Amps C Ø | 0.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | General Comments | | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Operations Counter AF | 202 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Operations Counter AL | 204 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Operations This Read Vac | 2 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Switching Operations | 2 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001607 | BreakerVacuum | 863-0062 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | Transformer needs nitrogen | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 50 | °C |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 40 | °C |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 50 | °C |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 40 | °C |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 50 | °C |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | WithLTC | HB-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 40 | °C |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | 9 Month Operations | 0 | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Amps A Ø | 313.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Amps B Ø | 314.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Amps C Ø | 321.0 | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Operations Counter AF | 57 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Operations Counter AL | 57 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001064 | BreakerVacuum | TA-12KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000284 | PowerFuse | P-1384 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | PF000349 | PowerFuse | SW-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | PF000349 | PowerFuse | SW-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | PF000348 | PowerFuse | SW-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | PF000348 | PowerFuse | SW-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | PF000268 | PowerFuse | OX-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | PF000268 | PowerFuse | OX-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | PF000266 | PowerFuse | OX-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | PF000266 | PowerFuse | OX-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | 9 Month Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Accumulated Fault Duty A Ph V | 15.15 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Accumulated Fault Duty B Ph V | 11.96 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Accumulated Fault Duty C Ph V | 9.57 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Amps A Ø | 138.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Amps B Ø | 140.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Amps C Ø | 177.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Operations Counter AF | 124 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Operations Counter AL | 124 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001062 | BreakerVacuum | TA-1173 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | 9 Month Operations | 7 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Amps A Ø | 46.0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0435 | BreakerVacuum | HN-1203 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Amps B Ø | 46.0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Amps C Ø | 46.0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0435 | BreakerVacuum | HN-1203 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0435 | BreakerVacuum | HN-1203 | VCB Readings | Operations Counter AL | 559 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Fault Adjusted Amps A Phase V | 27.94 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Fault Adjusted Amps B Phase V | 69.84 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Fault Adjusted Amps C Phase V | 27.94 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | General Comments | | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Operations Counter AF | 173 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Operations Counter AL | 175 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Operations This Read Vac | 2 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Switching Operations | 2 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Counter Readings | General Comments | | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Counter Readings | LTC As Found Counter | 150832 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Counter Readings | LTC As Left Counter | 150832 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Counter Readings | LTC Operations Since Last Insp | 457 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | LTCMechanism | 863-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Operations Counter AF | 215 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Operations Counter AL | 217 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Operations This Read Vac | 2 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Switching Operations | 2 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | PF000307 | PowerFuse | SY-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | PF000307 | PowerFuse | SY-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | PF000306 | PowerFuse | SY-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | PF000306 | PowerFuse | SY-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000300 | PowerFuse | P-1382 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000300 | PowerFuse | P-1382 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000282 | PowerFuse | P-1383 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000282 | PowerFuse | P-1383 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000283 | PowerFuse | P-14KV TR 4-A POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000283 | PowerFuse | P-14KV TR 4-A POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000298 | PowerFuse | P-1385 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000298 | PowerFuse | P-1385 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | PF000305 | PowerFuse | SY-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | PF000305 | PowerFuse | SY-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | PF000304 | PowerFuse | SY-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | PF000304 | PowerFuse | SY-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000293 | PowerFuse | P-14KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000293 | PowerFuse | P-14KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000291 | PowerFuse | P-14KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000291 | PowerFuse | P-14KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000288 | PowerFuse | P-STA SER TRANS B | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000288 | PowerFuse | P-STA SER TRANS B | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000287 | PowerFuse | P-BUS TIE REA 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000287 | PowerFuse | P-BUS TIE REA 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000286 | PowerFuse | P-1388 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000286 | PowerFuse | P-1388 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000285 | PowerFuse | P-14KV TR 3-B POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000285 | PowerFuse | P-14KV TR 3-B POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000284 | PowerFuse | P-1384 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Amps C Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Amps B Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Amps A Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | 9 Month Operations | 2 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Operations Counter AL | 194 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Operations This Read Vac | 7 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Switching Operations | 2 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Readings | Oil Temp Present | 19 | °C |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Readings | Oil Temp Max | 52 | °C |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 4.0 | psi |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Readings | LTC Totalizer Reading | 2492.80 | kw |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Readings | General Comments | | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Unknown Operations | 2 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0435 | BreakerVacuum | HN-1203 | VCB Readings | Operations Counter AF | 559 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0435 | BreakerVacuum | HN-1203 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0435 | BreakerVacuum | HN-1203 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0435 | BreakerVacuum | HN-1203 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0435 | BreakerVacuum | HN-1203 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0435 | BreakerVacuum | HN-1203 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0435 | BreakerVacuum | HN-1203 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0435 | BreakerVacuum | HN-1203 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0435 | BreakerVacuum | HN-1203 | VCB Readings | Amps C Ø | 0.0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0435 | BreakerVacuum | HN-1203 | VCB Readings | Amps B Ø | 0.0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0435 | BreakerVacuum | HN-1203 | VCB Readings | Amps A Ø | 0.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LTCC000328 | LTCControl | SY-TRANS 1 | LTC Control Insp | All Connections OK? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LTCC000328 | LTCControl | SY-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LTCC000328 | LTCControl | SY-TRANS 1 | LTC Control Insp | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LTCC000328 | LTCControl | SY-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCC000334 | LTCControl | SW-TRANS 1 | LTC Control Insp | All Connections OK? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCC000334 | LTCControl | SW-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | General Comments | | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | FE000018 | Fence | 342-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCC000334 | LTCControl | SW-TRANS 1 | LTC Control Insp | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCC000334 | LTCControl | SW-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCC000335 | LTCControl | TA-TRANS 3 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 245.00 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Readings | Totalizer Meter Reading | .7790 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Fault Operations B Ø | 3 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 25 | °C |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 45 | °C |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 25 | °C |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | M0039 | WithLTC | 310-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 45 | °C |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 25 | °C |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 45 | °C |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | General Comments | | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001606 | BreakerVacuum | 127-0059 | VCB Readings | Operations Counter AF | 189 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Switching Operations | 2 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Operations This Read Vac | 2 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Operations Counter AL | 182 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Operations Counter AF | 180 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | General Comments | | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | WithLTC | OX-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | ST000846 | Structure | 364-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | ST000846 | Structure | 364-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | ST000846 | Structure | 364-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | ST000846 | Structure | 364-Structure | Structure Patrol Inspection | General Comments | | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | ST000846 | Structure | 364-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | ST000846 | Structure | 364-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | ST000846 | Structure | 364-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | ST000846 | Structure | 364-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | ST000846 | Structure | 364-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KB0123 | BreakerVacuum | 863- BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Operations Counter AF | 262 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Operations Counter AL | 262 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Operations This Read Vac | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Switching Operations | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | 9 Month Operations | 1 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Amps A Ø | 58.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Amps B Ø | 54.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Amps C Ø | 57.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Amps C Ø | 121 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Amps B Ø | 111 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Amps A Ø | 115 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Accumulated Fault Duty C Ph V | .96 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Accumulated Fault Duty A Ph V | .96 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | 9 Month Operations | 7 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | PF000170 | PowerFuse | HB-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | PF000170 | PowerFuse | HB-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | PF000171 | PowerFuse | HB-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Amps A Ø | 135.0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Amps B Ø | 175.0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Amps C Ø | 165.0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Operations Counter AF | 151 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Operations Counter AL | 151 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Operations This Read Vac | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Switching Operations | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000514 | BreakerVacuum | OX-1275 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | 9 Month Operations | 4 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Operations Counter AF | 294 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Operations Counter AL | 294 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Operations This Read Vac | 1 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Switching Operations | 1 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | LTCMechanism | GR-CLASS-B TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | LTCMechanism | GR-CLASS-B TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | LTCMechanism | GR-CLASS-B TRANS 1 | LTC Counter Readings | LTC As Found Counter | 307031 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | LTCMechanism | GR-CLASS-B TRANS 1 | LTC Counter Readings | LTC As Left Counter | 307031 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | LTCMechanism | GR-CLASS-B TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | LTCMechanism | GR-CLASS-B TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | LTCMechanism | GR-CLASS-B TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | LTCMechanism | GR-CLASS-B TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 496 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | LTCMechanism | GR-CLASS-B TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Switching Operations | 2 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Operations This Read Vac | 3 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Operations Counter AL | 154 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Operations Counter AF | 152 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | General Comments | | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Fault Operations C Ø | 1 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Fault Adjusted Amps C Phase V | 6.41 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK001610 | BreakerVacuum | 863-0112 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | 9 Month Operations | 1 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | 9 Month Operations | 3 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | LTCMechanism | GR-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 173 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | LTCMechanism | GR-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 3 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | LTCMechanism | GR-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 106253 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | LTCMechanism | GR-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 106253 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | LTCMechanism | GR-TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | LTCMechanism | GR-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Amps A Ø | 161.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Amps B Ø | 165.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Amps C Ø | 168.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000513 | BreakerVacuum | OX-1273 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Counter Readings | LTC As Left Counter | 23726 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Operations Counter AF | 152 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Operations Counter AL | 152 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Operations This Read Vac | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Switching Operations | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Counter Readings | LTC As Found Counter | 23726 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Switching Operations | 4 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Counter Readings | General Comments | | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | General Comments | | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Max Tap Position | 9R | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Min Tap Position | 16L | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Reg Output Voltage Level | 125.4 | volts |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Regulator As Left Counter | 131639 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0956 | Regulator | 310-2 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | PF000171 | PowerFuse | HB-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | PF000172 | PowerFuse | HB-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | PF000172 | PowerFuse | HB-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | PF000173 | PowerFuse | HB-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | PF000173 | PowerFuse | HB-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Switching Operations | 2 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Operations This Read Vac | 2 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Operations Counter AL | 386 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Operations Counter AF | 384 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Accumulated Fault Duty A Ph V | 5.06 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Accumulated Fault Duty B Ph V | 5.06 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Accumulated Fault Duty C Ph V | 2.53 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Amps A Ø | 80 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Amps B Ø | 80 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Amps C Ø | 80 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0018 | BreakerVacuum | 716-1071 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | General Comments | | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Operations Counter AF | 419 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Operations Counter AL | 423 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0427 | BreakerVacuum | 863-0061 | VCB Readings | Operations This Read Vac | 4 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Counter Readings | LTC Operations Since Last Insp | 375 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0 | psi |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | KT0035 | LTCMechanism | 863-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | PF000355 | PowerFuse | TA-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | PF000355 | PowerFuse | TA-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | PF000355 | PowerFuse | TA-12KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | PF000354 | PowerFuse | TA-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | PF000354 | PowerFuse | TA-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | PF000354 | PowerFuse | TA-STA SER NO 1 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | LTCC000813 | LTCControl | 863-2 | LTC Control Insp | All Connections OK? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | LTCC000813 | LTCControl | 863-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | LTCC000813 | LTCControl | 863-2 | LTC Control Insp | General Comments | | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | LTCC000813 | LTCControl | 863-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | LTCC000813 | LTCControl | 863-2 | LTC Control Insp | LTC Output Voltage Level | 123.5 | VAC |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | LTCC000813 | LTCControl | 863-2 | LTC Control Insp | VRR Base Voltage AF | 124 | VAC |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | LTCC000813 | LTCControl | 863-2 | LTC Control Insp | VRR Base Voltage AL | 124 | VAC |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | LTCC000813 | LTCControl | 863-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | 9 Month Operations | 1 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000515 | BreakerVacuum | OX-1276 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LX0049 | RecloserHydraulic | GR-GND TR 2 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LX0049 | RecloserHydraulic | GR-GND TR 2 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0.0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LX0049 | RecloserHydraulic | GR-GND TR 2 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LX0049 | RecloserHydraulic | GR-GND TR 2 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LX0049 | RecloserHydraulic | GR-GND TR 2 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LX0049 | RecloserHydraulic | GR-GND TR 2 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LX0049 | RecloserHydraulic | GR-GND TR 2 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LX0049 | RecloserHydraulic | GR-GND TR 2 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | 9 Month Operations | 3 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Accumulated Fault Duty A Ph V | 15.17 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Accumulated Fault Duty B Ph V | 8.85 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Accumulated Fault Duty C Ph V | 5.06 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Amps A Ø | 75 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Amps B Ø | 59 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Amps C Ø | 75 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Maintenance Operations | 7 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Operations Counter AF | 137 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | 9 Month Ops New | 1 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | 9 Months Operations | 5 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LX0049 | RecloserHydraulic | GR-GND TR 2 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LX0049 | RecloserHydraulic | GR-GND TR 2 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LX0049 | RecloserHydraulic | GR-GND TR 2 | Recloser Hydraulic Patrol Inspection | Operations Counter | 71 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LX0049 | RecloserHydraulic | GR-GND TR 2 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LX0049 | RecloserHydraulic | GR-GND TR 2 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Amps A Ø | 100.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Amps B Ø | 100.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Amps C Ø | 100.0 | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Fault Adjusted Amps A Phase AM | 22.36 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Fault Adjusted Amps B Phase AM | 22.36 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Operations Counter AF | 165 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Operations Counter AL | 165 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001065 | BreakerVacuum | TA-12KV BUS TIE SEC 1 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000281 | PowerFuse | P-1381 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000281 | PowerFuse | P-1381 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000279 | PowerFuse | P-14KV BUS SEC 2-A POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000279 | PowerFuse | P-14KV BUS SEC 2-A POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000278 | PowerFuse | P-14KV BUS SEC 1-B POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000278 | PowerFuse | P-14KV BUS SEC 1-B POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000277 | PowerFuse | P-14KV BUS SEC 1-A POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF000277 | PowerFuse | P-14KV BUS SEC 1-A POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0433 | BreakerVacuum | HN-1201 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | PF000347 | PowerFuse | SW-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | PF000347 | PowerFuse | SW-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | PF000346 | PowerFuse | SW-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | PF000346 | PowerFuse | SW-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0433 | BreakerVacuum | HN-1201 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0433 | BreakerVacuum | HN-1201 | VCB Readings | Operations This Read Vac | 2 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0433 | BreakerVacuum | HN-1201 | VCB Readings | Operations Counter AL | 337 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0433 | BreakerVacuum | HN-1201 | VCB Readings | Operations Counter AF | 337 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0433 | BreakerVacuum | HN-1201 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0433 | BreakerVacuum | HN-1201 | VCB Readings | General Comments | A ioc | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0433 | BreakerVacuum | HN-1201 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0433 | BreakerVacuum | HN-1201 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0433 | BreakerVacuum | HN-1201 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0433 | BreakerVacuum | HN-1201 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0433 | BreakerVacuum | HN-1201 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0433 | BreakerVacuum | HN-1201 | VCB Readings | Fault Operations A Ø | 2 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0433 | BreakerVacuum | HN-1201 | VCB Readings | Fault Adjusted Amps A Phase V | 22.36 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0433 | BreakerVacuum | HN-1201 | VCB Readings | Amps C Ø | 163.0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0433 | BreakerVacuum | HN-1201 | VCB Readings | Amps B Ø | 147.0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0433 | BreakerVacuum | HN-1201 | VCB Readings | Amps A Ø | 148.0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0433 | BreakerVacuum | HN-1201 | VCB Readings | 9 Month Operations | 11 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | Switchgear heater not working | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | 9 Month Operations | 10 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Accumulated Fault Duty A Ph V | 15.15 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Accumulated Fault Duty B Ph V | 9.57 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Accumulated Fault Duty C Ph V | 4.78 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Amps A Ø | 54.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Amps B Ø | 42.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Amps C Ø | 46.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Readings | Oil Temp Present | 38 | °C |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Readings | Oil Temp Max | 69 | °C |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1170.72 | kw |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Readings | General Comments | | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0775 | BreakerOil | P-SPARE # 1 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK001068 | BreakerVacuum | P-1387-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 125308 | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 4 | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 4 | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | Amps C Ø | .9 | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 8.8 | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 25.0 | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0259 | RecloserHydraulic | 383-0932 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 20 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | 9 Month Operations | 5 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Amps A Ø | 444.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Amps B Ø | 448.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Amps C Ø | 459.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | BK000512 | BreakerVacuum | OX-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Fault Operations A Ø | 2 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Fault Operations B Ø | 2 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Patrol Inspection | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | General Comments | A and B phase IOC | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Operations Counter AF | 239 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Operations Counter AL | 239 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Operations This Read AM | 4 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0969 | BreakerAirMagnetic | SW-1190 | AMCB Readings | Switching Operations | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | General Comments | | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Operations Counter AF | 237 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Operations Counter AL | 239 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Operations This Read Vac | 2 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Switching Operations | 2 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000503 | BreakerVacuum | 863-0158 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Operations Counter AL | 137 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Operations This Read Vac | 7 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001066 | BreakerVacuum | TA-1132 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | SWG000025 | Switchgear | OX-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | ST000091 | Structure | 564-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | YD000085 | Yard | 564-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | YD000085 | Yard | 564-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | YD000085 | Yard | 564-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | YD000085 | Yard | 564-Yard | Yard Patrol Inspection | General Comments | | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | YD000085 | Yard | 564-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | YD000085 | Yard | 564-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | YD000085 | Yard | 564-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | YD000085 | Yard | 564-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | n | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | YD000085 | Yard | 564-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | YD000085 | Yard | 564-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | YD000085 | Yard | 564-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK001067 | BreakerVacuum | P-GND TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | YD000085 | Yard | 564-Yard | Yard Patrol Inspection | Ambient Temp | 44 | °F |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | R0407 | Regulator | 383-1 A | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | M0003 | NonLTC | 564-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .4878 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Readings | Switching Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Readings | Operations This Read Vac | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Readings | Operations Counter AL | 333 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Readings | Operations Counter AF | 333 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Readings | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Readings | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | WithLTC | GR-CLASS-B TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Readings | Amps C Ø | 195.0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Readings | Amps B Ø | 181.0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0493 | RecloserHydraulic | 310-4650 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 15.7 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0493 | RecloserHydraulic | 310-4650 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 16.2 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0493 | RecloserHydraulic | 310-4650 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 17.2 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0493 | RecloserHydraulic | 310-4650 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0493 | RecloserHydraulic | 310-4650 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0493 | RecloserHydraulic | 310-4650 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0493 | RecloserHydraulic | 310-4650 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | YD000120 | Yard | 364-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | YD000120 | Yard | 364-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | YD000120 | Yard | 364-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | YD000120 | Yard | 364-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | YD000120 | Yard | 364-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | General Comments | | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 357 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 104725 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 104725 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Counter Readings | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0140 | LTCMechanism | OX-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | FE000118 | Fence | 364-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 125.3 | volts |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 167248 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 135.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Readings | LV Winding Temp Present | 35 | °C |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Readings | LV Winding Temp Max | 55 | °C |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | WithLTC | GR-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Counter Readings | LTC Operations Since Last Insp | 272 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000874 | LTCControl | 716-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000874 | LTCControl | 716-2 | LTC Control Insp | VRR Base Voltage AL | 0.0 | VAC |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000874 | LTCControl | 716-2 | LTC Control Insp | VRR Base Voltage AF | 0.0 | VAC |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000874 | LTCControl | 716-2 | LTC Control Insp | LTC Output Voltage Level | 0.0 | VAC |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000874 | LTCControl | 716-2 | LTC Control Insp | LTC Operation Checked? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000874 | LTCControl | 716-2 | LTC Control Insp | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000874 | LTCControl | 716-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000874 | LTCControl | 716-2 | LTC Control Insp | All Connections OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Operations Counter AF | 156 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Operations Counter AL | 156 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Regulator As Left Counter | 85184 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Counter Readings | LTC As Left Counter | 73534 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Counter Readings | LTC As Found Counter | 73534 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Counter Readings | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | LTCMechanism | TA-TRANS 3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.5 | volts |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Max Tap Position | 10R | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | General Comments | | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | R0957 | Regulator | 310-2 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0493 | RecloserHydraulic | 310-4650 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0493 | RecloserHydraulic | 310-4650 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Readings | Amps A Ø | 179.0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Readings | 9 Month Operations | 1 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0493 | RecloserHydraulic | 310-4650 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0493 | RecloserHydraulic | 310-4650 | Recloser Hydraulic Patrol Inspection | Operations Counter | 396 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0493 | RecloserHydraulic | 310-4650 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0493 | RecloserHydraulic | 310-4650 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | 9 Month Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Accumulated Fault Duty A Ph V | 38.26 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Accumulated Fault Duty B Ph V | 39.06 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Accumulated Fault Duty C Ph V | 28.7 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Amps A Ø | 49.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Amps B Ø | 45.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Amps C Ø | 50.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000021 | BreakerVacuum | TA-1138 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | CH000191 | ControlHouse | SW-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 342 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 15L | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 11L | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 31688 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 31688 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | LTCMechanism | TA-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Operations Counter AF | 30 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Operations Counter AL | 30 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | YD000120 | Yard | 364-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | YD000120 | Yard | 364-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | YD000120 | Yard | 364-Yard | Yard Patrol Inspection | General Comments | | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | YD000120 | Yard | 364-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | YD000120 | Yard | 364-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | YD000120 | Yard | 364-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/10/2023 15:23 | Distribution | Critical Fork Quarterly Inspection | YD000120 | Yard | 364-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | 9 Month Operations | 3 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Amps A Ø | 760.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Amps B Ø | 750.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Amps C Ø | 750.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Operations Counter AF | 13 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Operations Counter AL | 13 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001954 | BreakerVacuum | HB-12KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Counter Readings | General Comments | | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Counter Readings | LTC As Found Counter | 55512 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Operations Counter AF | 18 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Operations Counter AL | 18 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001952 | BreakerVacuum | HB-1145 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | FE000592 | Fence | SW-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 30 | °C |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 40 | °C |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 27 | °C |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 42 | °C |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Readings | General Comments | | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Readings | Non LTC Totalizer Reading | 151.56 | kw |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Readings | Oil Temp Max | 42 | °C |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Readings | Oil Temp Present | 16 | °C |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Readings | Totalizer Meter Multiplier | 600 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | 0991 | NonLTC | 342-1 C | NonLTC Transformer Readings | Totalizer Meter Reading | .2526 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | 9 Month Operations | 2 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Amps A Ø | 115.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Amps B Ø | 130.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Amps C Ø | 120.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK001953 | BreakerVacuum | HB-1144 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Counter Readings | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Counter Readings | LTC As Found Counter | 13987 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Amps A Ø | 31.0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Amps B Ø | 31.0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Amps C Ø | 37.0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Counter Readings | LTC As Left Counter | 13987 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Counter Readings | LTC Min Tap Position | Neutral | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Counter Readings | LTC Operations Since Last Insp | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Restroom Clean & OK? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | CH000180 | ControlHouse | SY-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Operations Counter | 97 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | MX0329 | RecloserElectronic | 310-4625 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R1099 | Regulator | 342-1 C | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Counter Readings | LTC As Left Counter | 55512 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Counter Readings | LTC Current Tap Position | 4R | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 30 | °C |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 48 | °C |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Counter Readings | LTC Operations Since Last Insp | 746 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | LTCMechanism | 127-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Readings | 9 Month Operations | 1 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Readings | Amps A Ø | 283.0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Readings | Amps B Ø | 293.0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Readings | Amps C Ø | 289.0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Readings | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Readings | Operations Counter AF | 391 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Readings | Operations Counter AL | 391 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0432 | BreakerVacuum | HN-1200 | VCB Readings | Operations Counter AF | 606 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0432 | BreakerVacuum | HN-1200 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0432 | BreakerVacuum | HN-1200 | VCB Readings | General Comments | A,B,C ioc | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0432 | BreakerVacuum | HN-1200 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0432 | BreakerVacuum | HN-1200 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0432 | BreakerVacuum | HN-1200 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0432 | BreakerVacuum | HN-1200 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0432 | BreakerVacuum | HN-1200 | VCB Readings | Fault Operations B Ø | 1 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0432 | BreakerVacuum | HN-1200 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0432 | BreakerVacuum | HN-1200 | VCB Readings | Fault Adjusted Amps B Phase V | 11.18 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0432 | BreakerVacuum | HN-1200 | VCB Readings | Amps C Ø | 130.0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0432 | BreakerVacuum | HN-1200 | VCB Readings | Amps B Ø | 115.0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0432 | BreakerVacuum | HN-1200 | VCB Readings | Amps A Ø | 131.0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0432 | BreakerVacuum | HN-1200 | VCB Readings | 9 Month Operations | 5 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 800 | psi |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | WithLTC | SY-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0783 | BreakerOil | P-SPARE # 7 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | LTCMechanism | 716-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Operations This Read Vac | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Operations Counter AL | 588 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Operations Counter AF | 588 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Amps C Ø | 239.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Amps B Ø | 223.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Amps A Ø | 230.0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | 9 Month Operations | 5 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | General Comments | | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Operations Counter AF | 275 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Operations Counter AL | 275 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | PF000353 | PowerFuse | TA-STA SER NO 3 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | PF000353 | PowerFuse | TA-STA SER NO 3 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | PF000353 | PowerFuse | TA-STA SER NO 3 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | PF000352 | PowerFuse | TA-STA SER NO 4 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | PF000352 | PowerFuse | TA-STA SER NO 4 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | General Comments | Barbed wire is very rusty | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | FE000087 | Fence | 564-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Switching Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Operations This Read AM | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Operations Counter AL | 116 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Operations Counter AF | 116 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Amps C Ø | 0.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Amps B Ø | 0.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Amps A Ø | 0.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | 9 Months Operations | 1 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0972 | BreakerAirMagnetic | SW-12KV BUS TIE SEC 2 | AMCB Readings | 9 Month Ops New | 1 | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | 9 Month Operations | 0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Amps A Ø | 96.0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Amps B Ø | 120.0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Readings | Amps C Ø | 84.0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 120349 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LB0710 | BreakerVacuum | OX-1274 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | K0028 | BreakerVacuum | 310-4623 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Amps C Ø | 0.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Amps B Ø | 0.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Amps A Ø | 0.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | 9 Month Operations | 10 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | 9 Month Operations | 13 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | 9 Month Operations VCB New | 11 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Amps A Ø | 179.0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Amps B Ø | 208.0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Amps C Ø | 221.0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | General Comments | W00DEN PLANK FENCE | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | FE000333 | Fence | 863-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000490 | BreakerVacuum | 127-0060 | VCB Readings | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | PF000352 | PowerFuse | TA-STA SER NO 4 | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | PF000351 | PowerFuse | TA-12KV TR 4 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | PF000351 | PowerFuse | TA-12KV TR 4 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | PF000351 | PowerFuse | TA-12KV TR 4 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LTCC000038 | LTCControl | HB-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LTCC000038 | LTCControl | HB-TRANS 2 | LTC Control Insp | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | PF000350 | PowerFuse | TA-12KV TR 3 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | PF000350 | PowerFuse | TA-12KV TR 3 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | PF000350 | PowerFuse | TA-12KV TR 3 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LTCC000038 | LTCControl | HB-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LTCC000038 | LTCControl | HB-TRANS 2 | LTC Control Insp | All Connections OK? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | YD000573 | Yard | SW-Yard | Yard Patrol Inspection | Ambient Temp | 37 | °F |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0795 | Regulator | 564-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | 9 Month Operations | 2 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Amps A Ø | 339.0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Amps B Ø | 356.0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Readings | Amps C Ø | 365.0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK001605 | BreakerVacuum | 127-0055 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Switching Operations | 8 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Operations This Read Vac | 8 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Operations Counter AL | 164 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Operations Counter AF | 164 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | ST000575 | Structure | SW-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000864 | BreakerVacuum | HB-12KV BUS TIE SEC 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 213619 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 213619 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | General Comments | | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Present | 50 | °C |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Max | 60 | °C |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Present | 55 | °C |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Max | 62 | °C |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Pumps Condition | Leaks | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | General Comments | Pump leaking out of wires on back of motor | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Readings | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | FE000560 | Fence | SY-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 25 | °C |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 50 | °C |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 30 | °C |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 45 | °C |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 33 | °C |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 53 | °C |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 30 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 84216 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 84216 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | LTCMechanism | SW-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0160 | GroundTransformer | P-GND TR 2B | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0160 | GroundTransformer | P-GND TR 2B | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 42 | °C |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -2.0 | psi |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | trans needs nitro | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | WithLTC | SY-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | YD000123 | Yard | 310-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 496 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | LTCMechanism | OX-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Readings | Operations Counter AL | 850 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0781 | BreakerOil | P-SPARE # 5 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Readings | Operations Counter AF | 850 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Amps C Ø | 715.0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Amps B Ø | 825.0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Amps A Ø | 760.0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | 9 Month Operations | 1 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Readings | Amps C Ø | 10.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Readings | Amps B Ø | 10.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Readings | Amps A Ø | 10.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | PF001262 | PowerFuse | SW-B 14KV GND RLY POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | PF001262 | PowerFuse | SW-B 14KV GND RLY POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LTCC000215 | LTCControl | OX-TRANS 2 | LTC Control Insp | All Connections OK? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LTCC000215 | LTCControl | OX-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LTCC000215 | LTCControl | OX-TRANS 2 | LTC Control Insp | General Comments | | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LTCC000215 | LTCControl | OX-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LB0419 | BreakerOil | GR-GND TR 1 | OCB Readings | Unknown Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LB0419 | BreakerOil | GR-GND TR 1 | OCB Readings | Switching Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LB0419 | BreakerOil | GR-GND TR 1 | OCB Readings | Operations This Read Oil | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LB0419 | BreakerOil | GR-GND TR 1 | OCB Readings | Operations Counter AL | 2777 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LB0419 | BreakerOil | GR-GND TR 1 | OCB Readings | Operations Counter AF | 2777 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LB0419 | BreakerOil | GR-GND TR 1 | OCB Readings | Number of Ops last 9 Months | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LB0419 | BreakerOil | GR-GND TR 1 | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LB0419 | BreakerOil | GR-GND TR 1 | OCB Readings | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LB0419 | BreakerOil | GR-GND TR 1 | OCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LB0419 | BreakerOil | GR-GND TR 1 | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LB0419 | BreakerOil | GR-GND TR 1 | OCB Readings | 9 Months Operations OCB New | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Readings | Switching Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Readings | Operations This Read Oil | 12 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Readings | Operations Counter AL | 1099 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Readings | Operations Counter AF | 1099 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Readings | Number of Ops last 9 Months | 13 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Readings | Fault Operations | 12 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Readings | Amps C Ø | 25.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Readings | Amps B Ø | 25.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Readings | Amps A Ø | 25.0 | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | General Comments | | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | FE000110 | Fence | 383-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0189 | WithLTC | TA-TRANS 3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000009 | Switchgear | HB-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | 9 Month Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Accumulated Fault Duty A Ph V | 1.93 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Accumulated Fault Duty B Ph V | 3.85 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Amps A Ø | 297.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Amps B Ø | 265.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Amps C Ø | 315.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Operations Counter AF | 94 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Readings | Switching Operations | 3 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Readings | Operations This Read Oil | 3 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Readings | Operations Counter AL | 1495 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Readings | Operations Counter AF | 1495 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Readings | Number of Ops last 9 Months | 3 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Readings | Amps C Ø | 541.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0785 | BreakerOil | P-SPARE # 9 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Operations Counter AL | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Operations Counter AF | 203 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Readings | Amps B Ø | 574.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Readings | Amps A Ø | 471.0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | KB0049 | BreakerVacuum | 716-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Operations Counter AL | 94 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK000022 | BreakerVacuum | TA-12KV TR 4 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Readings | Switching Operations | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 10L | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 252963 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 252963 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Counter Readings | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | General Comments | REMOVE ALL LINES WITH ZEROS FROM INSPECTION | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | There is no conservator, and there are no pumps on this TR. Remove from inspection. | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | 9 Months Operations | 3 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | 9 Month Ops New | 2 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.4 | VDC |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.1 | VDC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | H1 Winding Temp Max | 0 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | H1 Winding Temp Present | 0 | °C |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | H2 Winding Temp Max | 0 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | H2 Winding Temp Present | 0 | °C |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | H3 Winding Temp Max | 0 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | H3 Winding Temp Present | 0 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | HV Winding Temp Max | 0 | °C |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Operations Counter AL | 61 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Operations Counter AF | 61 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Patrol Inspection | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Readings | Amps B Ø | 108.0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Readings | Amps A Ø | 112.0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Readings | 9 Month Operations | 2 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Amps C Ø | 0.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Amps B Ø | 0.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Amps A Ø | 0.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 71 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0173 | LTCMechanism | SY-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Amps C Ø | 365.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Amps B Ø | 363.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Amps A Ø | 357.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1200 | psi |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Readings | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | HV Winding Temp Present | 0 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | LTC Totalizer Reading | 0.00 | kw |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | LV Winding Temp Max | 0 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | LV Winding Temp Present | 0 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 350 | psi |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 62 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 23 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | Totalizer Meter Multiplier | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | 9 Months Operations | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Accumulated Fault Duty B Ph AM | 1.33 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Amps A Ø | 94.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Amps B Ø | 103.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Amps C Ø | 107.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Readings | Winding Temp Max | 50 | °C |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Readings | Totalizer Meter Reading | .9981 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Readings | X3 Winding Temp Present | 30 | °C |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Readings | X3 Winding Temp Max | 40 | °C |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Readings | X2 Winding Temp Present | 28 | °C |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Readings | X2 Winding Temp Max | 40 | °C |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Readings | X1 Winding Temp Present | 30 | °C |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Readings | X1 Winding Temp Max | 60 | °C |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000206 | WithLTC | SW-B TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Restroom Clean & OK? | n | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Operations Counter AL | 171 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Operations Counter AF | 171 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | CH000139 | ControlHouse | HB-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Readings | Operations Counter AF | 1636 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | General Comments | | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Readings | Operations Counter AF | 1344 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Readings | Operations Counter AL | 1344 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Readings | Switching Operations | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000206 | WithLTC | SW-B TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000206 | WithLTC | SW-B TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000206 | WithLTC | SW-B TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Readings | Switching Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000206 | WithLTC | SW-B TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000206 | WithLTC | SW-B TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000206 | WithLTC | SW-B TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000206 | WithLTC | SW-B TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000206 | WithLTC | SW-B TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000206 | WithLTC | SW-B TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Readings | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Readings | LTC Totalizer Reading | 25320.00 | kw |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Patrol Inspection | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 379939 | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.7 | volts |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 19 | °C |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Readings | Operations Counter AL | 372 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Readings | Operations Counter AF | 372 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Readings | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 68 | °F |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | BAT001473 | Battery | 310-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 9 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 37 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Readings | Amps C Ø | 98.0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | 9 Month Operations | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Switching Operations | 1 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0883 | BreakerAirMagnetic | SY-12KV TR 2 | AMCB Readings | Operations This Read AM | 1 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Readings | Operations Counter AL | 1636 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Readings | Switching Operations | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0434 | BreakerVacuum | HN-1202 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0434 | BreakerVacuum | HN-1202 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0434 | BreakerVacuum | HN-1202 | VCB Readings | Operations Counter AF | 234 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0434 | BreakerVacuum | HN-1202 | VCB Readings | Operations Counter AL | 234 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0434 | BreakerVacuum | HN-1202 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.0550 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Readings | Winding Temp Max | 60 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0434 | BreakerVacuum | HN-1202 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Amps C Ø | 1035.0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Amps B Ø | 1011.0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BK000246 | BreakerVacuum | 127-5 | VCB Readings | Amps A Ø | 956.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | SWG000010 | Switchgear | HB-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Counter Readings | LTC As Found Counter | 12047 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Counter Readings | LTC As Left Counter | 12047 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000082 | LTCMechanism | SW-B TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Switching Operations | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Operations This Read AM | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Operations Counter AL | 123 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Operations Counter AF | 123 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BCH000003 | Charger | P-Battery Charger Sec 1 Swgr | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000187 | Switchgear | TA-Swgr Sec 3 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | YD000013 | Yard | 342-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | YD000013 | Yard | 342-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | YD000013 | Yard | 342-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | YD000013 | Yard | 342-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | YD000013 | Yard | 342-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | YD000013 | Yard | 342-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | YD000013 | Yard | 342-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF001133 | PowerFuse | P-1394 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF001133 | PowerFuse | P-1394 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF001284 | PowerFuse | P-14KV GEN 13 AUX POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | PF001284 | PowerFuse | P-14KV GEN 13 AUX POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | YD000013 | Yard | 342-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | YD000013 | Yard | 342-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | YD000013 | Yard | 342-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | YD000013 | Yard | 342-Yard | Yard Patrol Inspection | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Readings | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Readings | LTC Totalizer Reading | 0.00 | kw |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Readings | Oil Temp Max | 15 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Counter Readings | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | ok | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 6057 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 6057 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | YD000013 | Yard | 342-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000954 | BreakerVacuum | P-1391-2 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | SWG000188 | Switchgear | TA-Swgr Sec 4 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BCH000003 | Charger | P-Battery Charger Sec 1 Swgr | Battery Charger Patrol Insp | Battery Charger Current | 3.5 | amps |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BCH000003 | Charger | P-Battery Charger Sec 1 Swgr | Battery Charger Patrol Insp | As Left Float Voltage | 134.8 | VDC |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BCH000003 | Charger | P-Battery Charger Sec 1 Swgr | Battery Charger Patrol Insp | As Found Float Voltage | 134.8 | VDC |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BCH000003 | Charger | P-Battery Charger Sec 1 Swgr | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 2.3 | psi |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 48 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 12 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 60 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | YD000013 | Yard | 342-Yard | Yard Patrol Inspection | Ambient Temp | 30 | °F |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Readings | Operations Counter AF | 122 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Readings | Operations Counter AL | 122 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Readings | Switching Operations | 0 | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Readings | Oil Temp Present | 0 | °C |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Readings | 9 Month Operations | 1 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Readings | Amps A Ø | 423.0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Readings | Amps B Ø | 422.0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Readings | Amps C Ø | 414.0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Readings | Winding Temp Max | 20 | °C |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Readings | Winding Temp Present | 5 | °C |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | General Comments | | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | SWG000184 | Switchgear | SY-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | LTCMechanism | HN-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | LTCMechanism | HN-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | LTCMechanism | HN-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 62316 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | LTCMechanism | HN-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 62316 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | LTCMechanism | HN-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | LTCMechanism | HN-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 3R | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | LTCMechanism | HN-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | LTCMechanism | HN-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 280 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | LTCMechanism | HN-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000183 | Switchgear | SW-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCM000101 | LTCMechanism | SW-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0438 | BreakerVacuum | HN-12KV TR 1 | VCB Readings | Operations Counter AL | 157 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0438 | BreakerVacuum | HN-12KV TR 1 | VCB Readings | Operations Counter AF | 157 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0191 | WithLTC | TA-TRANS 4 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 40 | °C |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 50 | °C |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0438 | BreakerVacuum | HN-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 35 | °C |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 52 | °C |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 40 | °C |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 55 | °C |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0438 | BreakerVacuum | HN-12KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0438 | BreakerVacuum | HN-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0438 | BreakerVacuum | HN-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0438 | BreakerVacuum | HN-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0438 | BreakerVacuum | HN-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Operations Counter AF | 212 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Operations Counter AL | 212 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Operations This Read AM | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Switching Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0438 | BreakerVacuum | HN-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0438 | BreakerVacuum | HN-12KV TR 1 | VCB Readings | Amps C Ø | 450.0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0438 | BreakerVacuum | HN-12KV TR 1 | VCB Readings | Amps B Ø | 350.0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0438 | BreakerVacuum | HN-12KV TR 1 | VCB Readings | Amps A Ø | 390.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1100 | psi |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -1.5 | psi |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Readings | LTC Totalizer Reading | 14372.64 | kw |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Readings | General Comments | | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Patrol Inspection | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0877 | BreakerAirMagnetic | SY-1254 | AMCB Readings | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 72 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 24 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 71 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 24 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 70 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | TX000250 | WithLTC | SW-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 24 | °C |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Readings | Winding Temp Present | 45 | °C |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0471 | WithLTC | 716-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | B0398 | WithLTC | 863-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0438 | BreakerVacuum | HN-12KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0438 | BreakerVacuum | HN-12KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0879 | BreakerAirMagnetic | SY-1256 | AMCB Readings | 9 Months Operations | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | 9 Months Operations | 7 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Amps A Ø | 0.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Amps B Ø | 0.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Amps C Ø | 0.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations Ground | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Operations Counter AF | 106 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Operations Counter AL | 106 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Operations This Read AM | 2 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | Switching Operations | 2 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000954 | BreakerVacuum | P-1391-2 | VCB Readings | Amps A Ø | 5.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000954 | BreakerVacuum | P-1391-2 | VCB Readings | Amps B Ø | 5.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000954 | BreakerVacuum | P-1391-2 | VCB Readings | Amps C Ø | 5.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000954 | BreakerVacuum | P-1391-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000954 | BreakerVacuum | P-1391-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000954 | BreakerVacuum | P-1391-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000954 | BreakerVacuum | P-1391-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000954 | BreakerVacuum | P-1391-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000954 | BreakerVacuum | P-1391-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000954 | BreakerVacuum | P-1391-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000954 | BreakerVacuum | P-1391-2 | VCB Readings | Operations Counter AF | 115 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000954 | BreakerVacuum | P-1391-2 | VCB Readings | Operations Counter AL | 115 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Readings | General Comments | Trans in vaccum with 1100 psi in bottle | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0079 | Regulator | 383-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LT0190 | WithLTC | TA-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 19 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 33 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 21 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 35 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 21 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 35 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 19 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 33 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.5 | psi |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | TR in Vacuum | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LT0188 | WithLTC | SW-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0881 | BreakerAirMagnetic | SY-12KV BUS TIE SEC 2 | AMCB Readings | 9 Month Ops New | 5 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | General Comments | | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Amps C Ø | 0.0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Amps B Ø | 0.0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Switching Operations | 2 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Operations This Read Vac | 2 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Amps C Ø | 198.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Amps B Ø | 176.0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Operations Counter AL | 183 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Operations Counter AF | 181 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Amps C Ø | 385.0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Amps B Ø | 435.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Patrol Inspection | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Readings | Amps A Ø | 0.0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Readings | Operations Counter AF | 3858 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | ST000359 | Structure | 716-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Readings | Operations Counter AL | 3858 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Readings | Switching Operations | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Patrol Inspection | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Amps A Ø | 185.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Accumulated Fault Duty C Ph AM | 2.66 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Accumulated Fault Duty B Ph AM | 5.32 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | 9 Months Operations | 2 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | 9 Month Ops New | 2 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | LTCC000745 | LTCControl | 127-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | YD000356 | Yard | 716-Yard | Yard Patrol Inspection | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | YD000356 | Yard | 716-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | YD000356 | Yard | 716-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | YD000356 | Yard | 716-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | LTCC000745 | LTCControl | 127-5 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | LTCC000745 | LTCControl | 127-5 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | LTCC000745 | LTCControl | 127-5 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | LTCC000745 | LTCControl | 127-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | LTCC000745 | LTCControl | 127-5 | LTC Control Insp | General Comments | | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | LTCC000745 | LTCControl | 127-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | LTCC000745 | LTCControl | 127-5 | LTC Control Insp | All Connections OK? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0436 | BreakerVacuum | HN-1204 | VCB Readings | Amps A Ø | 25.0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0436 | BreakerVacuum | HN-1204 | VCB Readings | Amps B Ø | 25.0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0436 | BreakerVacuum | HN-1204 | VCB Readings | Amps C Ø | 25.0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0436 | BreakerVacuum | HN-1204 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0436 | BreakerVacuum | HN-1204 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0436 | BreakerVacuum | HN-1204 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0436 | BreakerVacuum | HN-1204 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0436 | BreakerVacuum | HN-1204 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0436 | BreakerVacuum | HN-1204 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0436 | BreakerVacuum | HN-1204 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0436 | BreakerVacuum | HN-1204 | VCB Readings | Operations Counter AF | 497 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0436 | BreakerVacuum | HN-1204 | VCB Readings | Operations Counter AL | 497 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0436 | BreakerVacuum | HN-1204 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0436 | BreakerVacuum | HN-1204 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Operations Counter AF | 424 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Operations Counter AL | 424 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Operations This Read AM | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Switching Operations | 0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | LTCC000985 | LTCControl | 310-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | LTCC000985 | LTCControl | 310-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | LTCC000985 | LTCControl | 310-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | LTCC000985 | LTCControl | 310-1 | LTC Control Insp | LTC Output Voltage Level | 124.6 | VAC |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | LTCC000985 | LTCControl | 310-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | LTCC000985 | LTCControl | 310-1 | LTC Control Insp | General Comments | | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | LTCC000985 | LTCControl | 310-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Amps A Ø | 415.0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | K0017 | BreakerVacuum | 716-BT1-2 | VCB Readings | 9 Month Operations | 3 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Amps B Ø | 110.0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Amps A Ø | 0.0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Amps C Ø | 90.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 445 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | 9 Month Operations | 1 | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 199 | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0.0 | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MX0059 | RecloserHydraulic | 383-4631 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 127 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | BCH001407 | Charger | 310-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BAT001591 | Battery | SY-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BAT001591 | Battery | SY-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BAT001591 | Battery | SY-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BAT001591 | Battery | SY-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BAT001591 | Battery | SY-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BAT001591 | Battery | SY-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BAT001591 | Battery | SY-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BAT001591 | Battery | SY-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BAT001591 | Battery | SY-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | BCH001407 | Charger | 310-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | BCH001407 | Charger | 310-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BAT001591 | Battery | SY-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BAT001591 | Battery | SY-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BAT001591 | Battery | SY-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | BCH001407 | Charger | 310-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .600 | millivolts |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | YD000356 | Yard | 716-Yard | Yard Patrol Inspection | Ambient Temp | 38 | °F |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | YD000356 | Yard | 716-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | YD000356 | Yard | 716-Yard | Yard Patrol Inspection | Clear of Trash? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | YD000356 | Yard | 716-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | YD000356 | Yard | 716-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | YD000356 | Yard | 716-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | YD000356 | Yard | 716-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | YD000356 | Yard | 716-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | YD000356 | Yard | 716-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BCH001482 | Charger | 863-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0 | millivolts |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BCH001482 | Charger | 863-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53 | VDC |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BCH001482 | Charger | 863-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53 | VDC |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BCH001482 | Charger | 863-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 4 | amps |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BCH001482 | Charger | 863-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BCH001482 | Charger | 863-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BCH001482 | Charger | 863-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BCH001482 | Charger | 863-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000936 | BreakerVacuum | P-1386-1 | VCB Readings | Switching Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000936 | BreakerVacuum | P-1386-1 | VCB Readings | Operations Counter AL | 131 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000936 | BreakerVacuum | P-1386-1 | VCB Readings | Operations Counter AF | 131 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0777 | BreakerOil | P-SPARE # 11 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Readings | 9 Month Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Readings | Amps A Ø | 20.0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Readings | Amps B Ø | 15.0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Readings | Amps C Ø | 15.0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | General Comments | | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Readings | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Readings | Operations Counter AF | 216 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Readings | Operations Counter AL | 216 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Readings | Operations This Read Vac | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Readings | Switching Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | ST000012 | Structure | 342-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | BCH001407 | Charger | 310-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | BCH001407 | Charger | 310-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | BCH001407 | Charger | 310-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | BCH001407 | Charger | 310-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Operations Counter AL | 743 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | YD000571 | Yard | HB-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Operations Counter AF | 743 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Readings | Amps C Ø | 0.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 87527 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 87527 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Operations Counter AL | 478 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Operations Counter AF | 474 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 5R | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 199 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Switching Operations | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Operations This Read AM | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Operations Counter AL | 369 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0878 | BreakerAirMagnetic | SY-1255 | AMCB Readings | Operations Counter AF | 369 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000936 | BreakerVacuum | P-1386-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000936 | BreakerVacuum | P-1386-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000936 | BreakerVacuum | P-1386-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000936 | BreakerVacuum | P-1386-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000936 | BreakerVacuum | P-1386-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000936 | BreakerVacuum | P-1386-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000936 | BreakerVacuum | P-1386-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000936 | BreakerVacuum | P-1386-1 | VCB Readings | Amps C Ø | 64.0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BAT001551 | Battery | 863-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | 9 Month Ops New | 1 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BAT001551 | Battery | 863-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 40 | °F |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BAT001551 | Battery | 863-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BAT001551 | Battery | 863-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BAT001551 | Battery | 863-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BAT001551 | Battery | 863-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Switching Operations | 4 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Operations This Read Vac | 4 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BAT001551 | Battery | 863-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BAT001551 | Battery | 863-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BAT001551 | Battery | 863-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BAT001551 | Battery | 863-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0 | VDC |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BAT001551 | Battery | 863-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0 | VDC |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BAT001551 | Battery | 863-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BAT001551 | Battery | 863-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000936 | BreakerVacuum | P-1386-1 | VCB Readings | Amps B Ø | 64.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000936 | BreakerVacuum | P-1386-1 | VCB Readings | Amps A Ø | 64.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LT0176 | LTCMechanism | SY-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | 9 Months Operations | 1 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0970 | BreakerAirMagnetic | SW-1191 | AMCB Readings | Amps A Ø | 100.0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0362 | BreakerVacuum | 716-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | General Comments | | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | ST000116 | Structure | 383-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Amps A Ø | 720.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Amps B Ø | 740.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Amps C Ø | 680.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000916 | LTCControl | 716-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000916 | LTCControl | 716-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000916 | LTCControl | 716-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000916 | LTCControl | 716-1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000916 | LTCControl | 716-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000916 | LTCControl | 716-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000916 | LTCControl | 716-1 | LTC Control Insp | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000916 | LTCControl | 716-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | LTCC000916 | LTCControl | 716-1 | LTC Control Insp | All Connections OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BCH000098 | Charger | SY-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BCH000098 | Charger | SY-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BCH000098 | Charger | SY-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BCH000098 | Charger | SY-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BCH000098 | Charger | SY-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 4.5 | amps |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Operations Counter AL | 182 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 77 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 18.9 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 85 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 92 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Readings | 9 Month Operations | 4 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 85.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 31521 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | 9 Month Operations | 2 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 40 | °C |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 11L | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 9L | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 175 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 30 | °C |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 45 | °C |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 35 | °C |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 45 | °C |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 25 | °C |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | SWG000073 | Switchgear | SW-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BCH000098 | Charger | SY-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 135.0 | VDC |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BCH000098 | Charger | SY-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Operations Counter AF | 131 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Operations Counter AL | 131 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Counter Readings | LTC Operations Since Last Insp | 81 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Operations This Read Vac | 2 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Switching Operations | 2 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0434 | BreakerVacuum | HN-1202 | VCB Readings | Amps A Ø | 0.0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0434 | BreakerVacuum | HN-1202 | VCB Readings | Amps B Ø | 0.0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0434 | BreakerVacuum | HN-1202 | VCB Readings | Amps C Ø | 0.0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0434 | BreakerVacuum | HN-1202 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0434 | BreakerVacuum | HN-1202 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0434 | BreakerVacuum | HN-1202 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0434 | BreakerVacuum | HN-1202 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0434 | BreakerVacuum | HN-1202 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | FE000562 | Fence | HB-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | YD000111 | Yard | 383-Yard | Yard Patrol Inspection | Ambient Temp | 30 | °F |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | YD000111 | Yard | 383-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | YD000111 | Yard | 383-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | YD000111 | Yard | 383-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | YD000111 | Yard | 383-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | YD000111 | Yard | 383-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | YD000111 | Yard | 383-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | YD000111 | Yard | 383-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | YD000111 | Yard | 383-Yard | Yard Patrol Inspection | General Comments | | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | YD000111 | Yard | 383-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | YD000111 | Yard | 383-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | YD000111 | Yard | 383-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Amps A Ø | 259 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | 9 Month Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Readings | Fault Operations | 0 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Operations Counter AF | 182 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | DX0056 | RecloserHydraulic | 342-4620 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | General Comments | | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | Ambient Temp | 40 | °F |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Counter Readings | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Counter Readings | LTC As Found Counter | 237319 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Counter Readings | LTC As Left Counter | 237319 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Counter Readings | LTC Current Tap Position | 11L | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Counter Readings | LTC Max Tap Position | 14L | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Amps C Ø | 267 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BK000247 | BreakerVacuum | 863-1 | VCB Readings | Amps B Ø | 235 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 45 | °C |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | LTCM000075 | LTCMechanism | TA-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 30 | °C |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1324 | BreakerVacuum | HB-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | BCH000098 | Charger | SY-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 135.0 | VDC |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Readings | Amps A Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Operations Counter AL | 536 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Operations This Read AM | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Switching Operations | 0 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Readings | General Comments | | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1880.64 | kw |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 95.00 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Readings | Oil Temp Max | 38 | °C |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Readings | Totalizer Meter Reading | .7836 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Readings | Operations Counter AF | 2080 | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .1662 | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Readings | Oil Temp Present | 23 | °C |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Readings | Oil Temp Max | 37 | °C |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 97.50 | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 398.88 | kw |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Readings | Operations Counter AL | 2080 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Readings | Switching Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 40 | °C |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 50 | °C |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 35 | °C |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | LTCC000985 | LTCControl | 310-1 | LTC Control Insp | All Connections OK? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Amps C Ø | 80 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Amps B Ø | 80 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Amps A Ø | 80 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Accumulated Fault Duty C Ph V | 3.79 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Accumulated Fault Duty B Ph V | 12.64 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | Accumulated Fault Duty A Ph V | 25.28 | % |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | BB0428 | BreakerVacuum | 863-0080 | VCB Readings | 9 Month Operations | 6 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | W0169 | NonLTC | 310-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LTCC000573 | LTCControl | HB-TRANS 1 | LTC Control Insp | All Connections OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LTCC000573 | LTCControl | HB-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LTCC000573 | LTCControl | HB-TRANS 1 | LTC Control Insp | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LTCC000573 | LTCControl | HB-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | 9 Months Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Amps A Ø | 0.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Amps B Ø | 0.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Amps C Ø | 0.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Patrol Inspection | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | General Comments | DNO | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LB0968 | BreakerAirMagnetic | SW-1189 | AMCB Readings | Operations Counter AF | 536 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | N2 cylinder empty | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Readings | General Comments | Unable to reset Oil gauge due to gauge being painted. | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Readings | Amps C Ø | 200.0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Readings | Amps B Ø | 201.0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Readings | Amps A Ø | 198.0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0096 | LTCMechanism | HB-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 31521 | |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .4 | psi |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 1/11/2023 13:10 | Distribution | Oxmoor Quarterly Inspection | LT0141 | WithLTC | OX-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 75 | °C |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 35 | °C |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 35 | °C |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 35 | °C |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Readings | General Comments | | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | B0263 | NonLTC | 383-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Readings | Switching Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Readings | Operations This Read Vac | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Readings | Operations Counter AL | 385 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Readings | Operations Counter AF | 385 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Readings | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LT0095 | WithLTC | HB-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Amps C Ø | 0.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Readings | Amps A Ø | 0.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Amps A Ø | 0.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Accumulated Fault Duty B Ph V | 0 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Accumulated Fault Duty A Ph V | 0 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Readings | Amps B Ø | 0.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | 9 Month Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Readings | General Comments | | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Readings | LTC Totalizer Reading | 23382.00 | kw |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Readings | Operations Counter AF | 1716 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Readings | Operations Counter AL | 1716 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Readings | Switching Operations | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Switching Operations | 1 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Operations This Read Vac | 1 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Operations Counter AL | 70 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Operations Counter AF | 70 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Amps C Ø | 190.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Amps B Ø | 180.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Amps A Ø | 214.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000769 | BreakerVacuum | HB-1141 | VCB Readings | 9 Month Operations | 3 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | 9 Month Operations | 5 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Vacuum Monitor Self-Check OK? | na | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Vacuum Monitor Antenna Paint | NA | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Operations Counter AL | 65 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Operations Counter AF | 65 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001931 | BreakerVacuum | TA-12KV BUS TIE SEC 4 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.5 | volts |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Amps C Ø | 119.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Amps B Ø | 100.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Amps A Ø | 95.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Accumulated Fault Duty B Ph V | .8 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Accumulated Fault Duty A Ph V | .8 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | 9 Month Operations | 4 | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | General Comments | | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | YD000339 | Yard | 863-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Switching Operations | 2 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Readings | Totalizer Meter Reading | 1.2990 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Readings | Winding Temp Max | 66 | °C |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Readings | Winding Temp Present | 50 | °C |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | 9 Month Operations | 2 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Readings | Amps A Ø | 500.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Readings | Amps B Ø | 600.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Readings | Amps C Ø | 571.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Readings | Number of Ops last 9 Months | 2 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Readings | Operations Counter AF | 1286 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Readings | Operations Counter AL | 1286 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | 9 Month Operations | 13 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | 9 Month Operations VCB New | 13 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Readings | Operations This Read Oil | 2 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Readings | Switching Operations | 2 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Amps A Ø | 160.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Amps B Ø | 150.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Amps C Ø | 160.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Amps A Ø | 391.0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Amps B Ø | 385.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Amps C Ø | 382.0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Operations Counter AL | 92 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCC000846 | LTCControl | SW-TRANS 2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCC000846 | LTCControl | SW-TRANS 2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Operations Counter AF | 92 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001930 | BreakerVacuum | TA-1134 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Readings | Amps C Ø | 509.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Readings | Amps B Ø | 549.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Readings | Amps A Ø | 452.0 | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LTCC000485 | LTCControl | SY-TRANS 2 | LTC Control Insp | All Connections OK? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LTCC000485 | LTCControl | SY-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LTCC000485 | LTCControl | SY-TRANS 2 | LTC Control Insp | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LTCC000485 | LTCControl | SY-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.1 | volts |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 15810 | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | 9 Month Ops New | 1 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | 9 Months Operations | 1 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Accumulated Fault Duty A Ph AM | 2.66 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Accumulated Fault Duty C Ph AM | 1.33 | % |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Amps A Ø | 84.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Readings | Switching Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Readings | Operations Counter AL | 916 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Readings | Operations Counter AF | 916 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Readings | Amps B Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Readings | Amps A Ø | 0.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Amps B Ø | 80.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Amps C Ø | 79.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Readings | Amps B Ø | 0.0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Readings | Amps C Ø | 0.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Readings | Fault Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BAT000021 | Battery | P-Battery Bank Sec 1 Swgr | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0779 | BreakerOil | P-SPARE # 13 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BAT000021 | Battery | P-Battery Bank Sec 1 Swgr | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BAT000021 | Battery | P-Battery Bank Sec 1 Swgr | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BAT000021 | Battery | P-Battery Bank Sec 1 Swgr | Battery Patrol Inspection | All Connections OK? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | 9 Month Operations | 4 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BAT000021 | Battery | P-Battery Bank Sec 1 Swgr | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Readings | Operations This Read Oil | 2 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Readings | Operations Counter AL | 1996 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Readings | Number of Ops last 9 Months | 2 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Amps A Ø | 240.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Amps B Ø | 20.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Amps C Ø | 190.0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Fault Operations Ground | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Readings | Operations Counter AF | 1996 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Switching Operations | 4 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Operations This Read Vac | 4 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Operations Counter AL | 227 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Operations Counter AF | 223 | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 12:47 | Distribution | Bailey Creek Quarterly Inspection | R0923 | Regulator | 564-1 A | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Operations Counter AF | 221 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Operations Counter AL | 221 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Operations This Read Vac | 1 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000770 | BreakerVacuum | HB-1142 | VCB Readings | Switching Operations | 1 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Readings | Switching Operations | 2 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Amps C Ø | 3.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Amps B Ø | 4.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Amps A Ø | 4.0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | 9 Month Operations VCB New | 31 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | 9 Month Operations | 31 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | PF001153 | PowerFuse | SW-B 14KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | PF001153 | PowerFuse | SW-B 14KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Patrol Inspection | General Comments | | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Readings | Switching Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Readings | Operations Counter AL | 1315 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Readings | Operations Counter AF | 1315 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Operations Counter AF | 190 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Operations Counter AL | 190 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Operations This Read AM | 0 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Switching Operations | 0 | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | General Comments | | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/10/2023 7:09 | Distribution | Picadome Quarterly Inspection | ST000342 | Structure | 863-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Operations Counter AL | 230 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Operations Counter AF | 230 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 127860 | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.2 | volts |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BAT000089 | Battery | SW-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BAT000089 | Battery | SW-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BAT000089 | Battery | SW-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BAT000089 | Battery | SW-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BAT000089 | Battery | SW-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BAT000089 | Battery | SW-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BAT000089 | Battery | SW-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BAT000089 | Battery | SW-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BAT000089 | Battery | SW-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BAT000089 | Battery | SW-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BAT000089 | Battery | SW-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BAT000089 | Battery | SW-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 15:22 | Distribution | Rocky Fork Quarterly Inspection | R0933 | Regulator | 342-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Readings | Operations Counter AF | 1179 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Readings | Operations Counter AL | 1179 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Readings | Switching Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 12:11 | Distribution | Smyrna Quarterly Inspection | LB0876 | BreakerAirMagnetic | SY-1253 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | BK001475 | BreakerVacuum | SW-1451 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Readings | Amps C Ø | 80.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Readings | Operations Counter AF | 1197 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCC000846 | LTCControl | SW-TRANS 2 | LTC Control Insp | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Readings | Amps B Ø | 80.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Switching Operations | 2 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Readings | Amps A Ø | 80.0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Amps C Ø | 100.0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Amps C Ø | 156.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Amps B Ø | 128.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Amps A Ø | 159.0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Accumulated Fault Duty C Ph V | 0 | % |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | CH000491 | ControlHouse | 310-Control House | Control House Patrol Inspection | General Comments | | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | CH000491 | ControlHouse | 310-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | CH000491 | ControlHouse | 310-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Accumulated Fault Duty B Ph V | 3.99 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Accumulated Fault Duty A Ph V | 3.99 | % |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | 9 Month Operations | 10 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1336 | BreakerVacuum | HB-Sec 1 Spare Vac Bkr | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1336 | BreakerVacuum | HB-Sec 1 Spare Vac Bkr | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | ST000731 | Structure | 310-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Operations Counter AF | 205 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | Operations Counter AL | 205 | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | LB1336 | BreakerVacuum | HB-Sec 1 Spare Vac Bkr | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 10:16 | Distribution | Hurstbourne Quarterly Inspection | BK000771 | BreakerVacuum | HB-1143 | VCB Readings | General Comments | | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Unknown Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Readings | Fault Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Switching Operations | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Operations Counter AL | 75 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Operations Counter AF | 75 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | General Comments | | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Operations Counter AF | 469 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Operations Counter AL | 471 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Operations This Read Vac | 2 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCC000846 | LTCControl | SW-TRANS 2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCC000846 | LTCControl | SW-TRANS 2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCC000846 | LTCControl | SW-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Fault Operations Ground | 0 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCC000846 | LTCControl | SW-TRANS 2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/10/2023 11:39 | Distribution | Taylor Quarterly Inspection | BK001929 | BreakerVacuum | TA-1133 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | CH000491 | ControlHouse | 310-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | CH000491 | ControlHouse | 310-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Readings | Operations Counter AF | 386 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Readings | Operations Counter AL | 386 | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | CH000491 | ControlHouse | 310-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | CH000491 | ControlHouse | 310-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | CH000491 | ControlHouse | 310-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | CH000491 | ControlHouse | 310-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/10/2023 15:23 | Distribution | Dixiana Quarterly Inspection | CH000491 | ControlHouse | 310-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Readings | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Operations Counter AF | 868 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Readings | Maintenance Operations | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Amps A Ø | 120.0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Operations This Read Vac | 2 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Readings | Operations Counter AL | 870 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Readings | Operations Counter AL | 1197 | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | B0376 | WithLTC | 127-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 100.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0394 | BreakerVacuum | 716-0107 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Readings | Switching Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Readings | Amps B Ø | 120.0 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | BB0335 | BreakerVacuum | 716-0070 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 15:22 | Distribution | Lipps Quarterly Inspection | MR0081 | Regulator | 383-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCC000846 | LTCControl | SW-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/10/2023 9:23 | Distribution | Stewart Quarterly Inspection | LTCC000846 | LTCControl | SW-TRANS 2 | LTC Control Insp | All Connections OK? | y | |
| 1/10/2023 14:53 | Distribution | Haefling Quarterly Inspection | BB0470 | BreakerVacuum | 127-0089 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/10/2023 14:22 | Distribution | Higby Mill Distribution Quarterly Inspection | B0433 | WithLTC | 716-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BCH000422 | Charger | Retired Distribution | Battery Charger Patrol Insp | As Left Float Voltage | 0.0 | VDC |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BCH000422 | Charger | Retired Distribution | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BCH000422 | Charger | Retired Distribution | Battery Charger Patrol Insp | General Comments | no longer here | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Operations Counter AF | 236 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Operations Counter AL | 238 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Operations This Read Vac | 2 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Switching Operations | 2 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | 9 Month Ops New | 1 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Amps A Ø | 35.0 | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Amps B Ø | 17.0 | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Amps C Ø | 36.0 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Readings | 9 Months Operations OCB New | 1 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Amps B Ø | 214.0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Amps A Ø | 231.0 | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Readings | LTC Totalizer Reading | 1689.60 | kw |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Readings | Oil Temp Max | 25 | °C |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Readings | Oil Temp Present | 10 | °C |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Amps C Ø | 246.0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Readings | Totalizer Meter Reading | .1760 | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | General Comments | Counter doesn't work. | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Current Tap Position | 7R | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0317 | Regulator | 851-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Operations Counter AL | 204 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Operations This Read Vac | 2 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Switching Operations | 2 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | General Comments | | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Operations Counter AF | 288 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Operations Counter AL | 288 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | 9 Month Operations | 1 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Accumulated Fault Duty A Ph V | 19.93 | % |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Accumulated Fault Duty B Ph V | 15.15 | % |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Accumulated Fault Duty C Ph V | 15.15 | % |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Amps A Ø | 105.0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Amps B Ø | 61.0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Amps C Ø | 93.0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | 9 Month Operations | 4 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | 9 Month Operations VCB New | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Amps A Ø | 120.0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Amps B Ø | 120.0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Amps C Ø | 120.0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | 9 Month Operations | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Readings | 9 Months Operations OCB New | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Patrol Inspection | Air Compressor Belt Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0777 | BreakerOil | P-SPARE # 11 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0777 | BreakerOil | P-SPARE # 11 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0777 | BreakerOil | P-SPARE # 11 | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0777 | BreakerOil | P-SPARE # 11 | OCB Patrol Inspection | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Operations Counter AF | 202 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Readings | 9 Months Operations OCB New | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 300.00 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 324.17 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BCH000890 | Charger | EW-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BCH000890 | Charger | EW-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BCH000890 | Charger | EW-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BCH000890 | Charger | EW-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BCH000890 | Charger | EW-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.1 | amps |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BCH000890 | Charger | EW-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 133.3 | VDC |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BCH000890 | Charger | EW-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 133.3 | VDC |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BCH000890 | Charger | EW-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | General Comments | | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000985 | BreakerVacuum | 060-0126 | VCB Readings | 9 Month Operations | 6 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 0.00 | kw |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Operations Counter AL | 78 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Operations Counter AF | 78 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0436 | BreakerVacuum | HN-1204 | VCB Readings | 9 Month Operations | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0436 | BreakerVacuum | HN-1204 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0436 | BreakerVacuum | HN-1204 | VCB Readings | Accumulated Fault Duty A Ph V | 21.52 | % |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0436 | BreakerVacuum | HN-1204 | VCB Readings | Accumulated Fault Duty B Ph V | 25.11 | % |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0436 | BreakerVacuum | HN-1204 | VCB Readings | Accumulated Fault Duty C Ph V | 10.76 | % |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0436 | BreakerVacuum | HN-1204 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0436 | BreakerVacuum | HN-1204 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0436 | BreakerVacuum | HN-1204 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0436 | BreakerVacuum | HN-1204 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0436 | BreakerVacuum | HN-1204 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0436 | BreakerVacuum | HN-1204 | VCB Readings | General Comments | | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0436 | BreakerVacuum | HN-1204 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0777 | BreakerOil | P-SPARE # 11 | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Patrol Inspection | Air Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Patrol Inspection | Air Pressure OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Patrol Inspection | Air Tank Bleed (> 40°F)? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0777 | BreakerOil | P-SPARE # 11 | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0777 | BreakerOil | P-SPARE # 11 | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0777 | BreakerOil | P-SPARE # 11 | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0777 | BreakerOil | P-SPARE # 11 | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Patrol Inspection | Air Tank Bleed (> 40°F)? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Patrol Inspection | Air Pressure OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Patrol Inspection | Air Leaks | None | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | General Comments | | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Operations Counter AF | 467 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | FE000558 | Fence | 765-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Patrol Inspection | Air Compressor Belt Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Readings | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Readings | LTC Totalizer Reading | 35064.00 | kw |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Readings | Oil Temp Max | 70 | °C |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | General Comments | | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 168404 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | LTCMechanism | GR-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | LTCMechanism | GR-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | LTCMechanism | GR-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | LTCMechanism | GR-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0085 | LTCMechanism | GR-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Amps A Ø | 47.0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Amps B Ø | 38.0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | 9 Month Operations | 2 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Readings | General Comments | | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Readings | Number of Ops last 9 Months | 1 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Readings | Operations This Read Oil | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Amps C Ø | 44.0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 69905 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | BAT000250 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Area Ambient Temp | 40 | °F |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | BAT000250 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1239 | Regulator | 782-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | 9 Month Operations | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Readings | General Comments | | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | General Comments | | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Readings | Totalizer Meter Reading | 1.9480 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Readings | Winding Temp Max | 70 | °C |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Operations Counter AF | 153 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Operations Counter AL | 153 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | 9 Months Operations | 1 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | BAT000250 | Battery | Retired Distribution | Battery Patrol Inspection | All Connections OK? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Operations Counter AL | 196 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Operations Counter AF | 196 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | FE000244 | Fence | 616-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Switching Operations | 1 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Operations This Read Vac | 1 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Operations Counter AL | 57 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Operations Counter AF | 57 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Operations Counter AL | 471 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Operations This Read Vac | 4 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Switching Operations | 4 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0432 | BreakerVacuum | 808-0049 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Amps C Ø | 0.0 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | General Comments | | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Amps B Ø | 0.0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Amps A Ø | 0.0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | General Comments | | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Operations Counter AF | 193 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Operations Counter AL | 193 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000032 | BreakerVacuum | EW-1242 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | 9 Month Operations | 5 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Accumulated Fault Duty A Ph V | 7.97 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Accumulated Fault Duty B Ph V | 7.97 | % |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000033 | BreakerVacuum | EW-1243 | VCB Readings | Accumulated Fault Duty C Ph V | 10.36 | % |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0065 | BreakerVacuum | 158-BT5-6 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | WithLTC | 060-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0774 | BreakerOil | P-SEC TIE 1-B | OCB Patrol Inspection | General Comments | | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Counter Readings | LTC Operations Since Last Insp | 379 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Counter Readings | LTC As Left Counter | 11954 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Readings | 9 Months Operations OCB New | 1 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Patrol Inspection | Pressure Vessel Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Counter Readings | LTC As Found Counter | 11954 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | LTCMechanism | 808-1 | LTC Counter Readings | General Comments | | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | ST000567 | Structure | 765-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | YD000419 | Yard | 808-Yard | Yard Patrol Inspection | Ambient Temp | 40 | °F |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Amps A Ø | 167.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Readings | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Amps C Ø | 603.0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Amps B Ø | 625.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Readings | Number of Ops last 9 Months | 1 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Patrol Inspection | Air Tank Bleed (> 40°F)? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Patrol Inspection | Air Pressure OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Patrol Inspection | Air Leaks | None | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.0542 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Patrol Inspection | Pressure Vessel Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | 9 Month Operations | 1 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 358484 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.8 | volts |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Readings | Totalizer Meter Reading | .8340 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Readings | Oil Temp Present | 45 | °C |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Readings | Oil Temp Max | 60 | °C |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Tank Oil Level | Low | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Readings | Oil Temp Present | 19 | °C |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Readings | Oil Temp Max | 30 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Readings | LTC Totalizer Reading | 8006.40 | kw |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Readings | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 380.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Patrol Inspection | Air Compressor Belt Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0724 | BreakerOil | P-1381-B | OCB Readings | 9 Months Operations OCB New | 1 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000936 | BreakerVacuum | P-1386-1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000936 | BreakerVacuum | P-1386-1 | VCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000936 | BreakerVacuum | P-1386-1 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000936 | BreakerVacuum | P-1386-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000936 | BreakerVacuum | P-1386-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000936 | BreakerVacuum | P-1386-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000936 | BreakerVacuum | P-1386-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000936 | BreakerVacuum | P-1386-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000936 | BreakerVacuum | P-1386-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000936 | BreakerVacuum | P-1386-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000936 | BreakerVacuum | P-1386-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000936 | BreakerVacuum | P-1386-1 | VCB Readings | 9 Month Operations | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .3618 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Amps A Ø | 570.0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Patrol Inspection | Air Leaks | None | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Readings | Operations This Read Oil | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Patrol Inspection | Air Compressor Belt Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Readings | 9 Months Operations OCB New | 1 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Readings | Winding Temp Present | 20 | °C |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Readings | Winding Temp Max | 35 | °C |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Patrol Inspection | Pressure Vessel Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Amps B Ø | 137.0 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Amps C Ø | 127.0 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Switching Operations | 0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Unknown Operations | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Readings | General Comments | | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Amps C Ø | 150.0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Amps B Ø | 150.0 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | LTCC000850 | LTCControl | 158-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Readings | LTC Totalizer Reading | 7912.00 | kw |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | LTCC000850 | LTCControl | 158-2 | LTC Control Insp | VRR Base Voltage AL | 118.0 | VAC |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Operations Counter AL | 200 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Operations Counter AF | 200 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | CH000474 | ControlHouse | GI-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Amps A Ø | .3 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 8000 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Readings | Totalizer Meter Reading | .9890 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BCH001481 | Charger | 158-Battery Charger 1 | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BCH001481 | Charger | 158-Battery Charger 1 | Battery Charger Patrol Insp | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BCH001481 | Charger | 158-Battery Charger 1 | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BCH001481 | Charger | 158-Battery Charger 1 | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BCH001481 | Charger | 158-Battery Charger 1 | Battery Charger Patrol Insp | Battery Charger Current | 2.0 | amps |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | Ambient Temp | 33 | °F |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BCH001481 | Charger | 158-Battery Charger 1 | Battery Charger Patrol Insp | As Left Float Voltage | 134.4 | VDC |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BCH001481 | Charger | 158-Battery Charger 1 | Battery Charger Patrol Insp | As Found Float Voltage | 134.4 | VDC |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BCH001481 | Charger | 158-Battery Charger 1 | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 3.100 | millivolts |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Patrol Inspection | General Comments | | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | General Comments | | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Operations Counter AF | 367 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Operations Counter AL | 367 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Operations This Read AM | 0 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Patrol Inspection | Air Pressure OK? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LB0419 | BreakerOil | GR-GND TR 1 | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LB0419 | BreakerOil | GR-GND TR 1 | OCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Operations Counter | 0 | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | CH000474 | ControlHouse | GI-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | CH000474 | ControlHouse | GI-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | CH000474 | ControlHouse | GI-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0341 | WithLTC | 808-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | LTCC000850 | LTCControl | 158-2 | LTC Control Insp | LTC Output Voltage Level | 118.4 | VAC |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | LTCC000850 | LTCControl | 158-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | LTCC000850 | LTCControl | 158-2 | LTC Control Insp | General Comments | | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0843 | Regulator | 810-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | LTCC000850 | LTCControl | 158-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | LTCC000850 | LTCControl | 158-2 | LTC Control Insp | All Connections OK? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Amps A Ø | 150.0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | 9 Months Operations | 0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0387 | BreakerAirMagnetic | GI-1 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Amps B Ø | .2 | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Amps C Ø | .3 | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900711 | RecloserElectronic | 224-0240 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | Positive DC Ground | 67.3 | VDC |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | Negative DC Ground | 67.1 | VDC |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | General Comments | water needs to be added to all cells in this bank | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | Cell Electrolyte Level | Low | If low,note cell #~'s |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | Battery Area Ambient Temp | 62 | °F |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BAT001550 | Battery | 158-Battery Bank 1 | Battery Patrol Inspection | All Connections OK? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | LTCC000850 | LTCControl | 158-2 | LTC Control Insp | VRR Base Voltage AF | 118.0 | VAC |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LB0419 | BreakerOil | GR-GND TR 1 | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LB0419 | BreakerOil | GR-GND TR 1 | OCB Patrol Inspection | Tank Oil Level | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LB0419 | BreakerOil | GR-GND TR 1 | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LB0419 | BreakerOil | GR-GND TR 1 | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LB0419 | BreakerOil | GR-GND TR 1 | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LB0419 | BreakerOil | GR-GND TR 1 | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LB0419 | BreakerOil | GR-GND TR 1 | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LB0419 | BreakerOil | GR-GND TR 1 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LB0419 | BreakerOil | GR-GND TR 1 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LB0419 | BreakerOil | GR-GND TR 1 | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LB0419 | BreakerOil | GR-GND TR 1 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LB0419 | BreakerOil | GR-GND TR 1 | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LB0419 | BreakerOil | GR-GND TR 1 | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | CH000474 | ControlHouse | GI-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | CH000474 | ControlHouse | GI-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | CH000474 | ControlHouse | GI-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | CH000474 | ControlHouse | GI-Battery Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | CH000474 | ControlHouse | GI-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Patrol Inspection | Air Tank Bleed (> 40°F)? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 0 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | General Comments | | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | General Comments | | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Operations Counter AF | 193 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Operations Counter AL | 193 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Operations This Read Vac | 1 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Switching Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | 9 Month Operations | 1 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Accumulated Fault Duty A Ph V | 49.42 | % |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | YD000666 | Yard | GI-Yard | Yard Patrol Inspection | General Comments | | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Accumulated Fault Duty B Ph V | 42.25 | % |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Accumulated Fault Duty C Ph V | 27.1 | % |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Amps A Ø | 180.0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Amps B Ø | 176.0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol Inspection | Door Alarms OK? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Readings | General Comments | | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Amps B Ø | 132.0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Amps C Ø | 120.0 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0746 | BreakerOil | P-1392-B | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 320 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Amps C Ø | 2.0 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Amps B Ø | 12.0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Amps A Ø | 6.0 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 11R | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000031 | BreakerVacuum | EW-1241 | VCB Readings | Amps C Ø | 168.0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | 9 Month Operations | 2 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol Inspection | General Comments | | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol Inspection | Station Ground Set On Site? | n | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | n | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CH000431 | ControlHouse | 583-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 3L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 21 | °C |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 39 | °C |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 489 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000984 | BreakerVacuum | 060-0118 | VCB Readings | Amps A Ø | 133.0 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Operations Counter AL | 179 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Operations This Read Vac | 1 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 36508 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 36508 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | LTCMechanism | EW-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Readings | General Comments | | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 105.84 | kw |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Operations Counter AL | 181 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Operations Counter AF | 181 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 200 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Readings | Oil Temp Present | 42 | °C |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | General Comments | ok | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | General Comments | trip check | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | 9 Month Operations | 2 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Accumulated Fault Duty A Ph V | 6.38 | % |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Accumulated Fault Duty B Ph V | 8.77 | % |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Accumulated Fault Duty C Ph V | 18.33 | % |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Amps A Ø | 32.0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Amps B Ø | 64.0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Amps C Ø | 75.0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Fault Adjusted Amps A Phase V | 11.18 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Fault Operations A Ø | 1 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000030 | BreakerVacuum | EW-1240 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Maintenance Operations | 1 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BK000724 | BreakerVacuum | 453-1422 | VCB Readings | Operations Counter AF | 178 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Readings | Number of Ops last 9 Months | 1 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Patrol Inspection | Pressure Vessel Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Readings | Operations This Read Oil | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Readings | Number of Ops last 9 Months | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Operations Counter AL | 214 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Operations Counter AF | 214 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | ST000421 | Structure | 808-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0346 | NonLTC | 851-1 A | NonLTC Transformer Readings | Totalizer Meter Reading | .5292 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Patrol Inspection | General Comments | | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Readings | General Comments | | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0766 | BreakerOil | P-GND TR 1 A&B-B | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 96.00 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 434.16 | kw |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | B0265 | NonLTC | 810-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1238 | Regulator | 782-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 397.50 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3373.44 | kw |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Amps A Ø | 120.0 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Amps B Ø | 115.0 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Amps C Ø | 118.0 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Readings | General Comments | | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001089 | BreakerVacuum | 841-0488 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | WithLTC | 158-6 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000832 | BreakerVacuum | 060-5 | VCB Readings | 9 Month Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0728 | BreakerOil | P-1383-B | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | W0166 | NonLTC | 782-1 | NonLTC Transformer Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0750 | BreakerOil | P-1394-B | OCB Readings | Operations This Read Oil | 0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 408639 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | LTCMechanism | GI-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 408639 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 40 | °F |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Max Tap Position | 5L | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 118075 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Amps A Ø | 120.0 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Amps B Ø | 117.0 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Maintenance Operations | 1 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK001067 | BreakerVacuum | P-GND TR 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK001067 | BreakerVacuum | P-GND TR 2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK001067 | BreakerVacuum | P-GND TR 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK001067 | BreakerVacuum | P-GND TR 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK001067 | BreakerVacuum | P-GND TR 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK001067 | BreakerVacuum | P-GND TR 2 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK001067 | BreakerVacuum | P-GND TR 2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK001067 | BreakerVacuum | P-GND TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK001067 | BreakerVacuum | P-GND TR 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK001067 | BreakerVacuum | P-GND TR 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK001067 | BreakerVacuum | P-GND TR 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK001067 | BreakerVacuum | P-GND TR 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK001067 | BreakerVacuum | P-GND TR 2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK001067 | BreakerVacuum | P-GND TR 2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Max Tap Position | 7L | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Min Tap Position | 15L | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 26220 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BAT001125 | Battery | 808-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Amps C Ø | 115.0 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | 9 Month Operations | 10 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Amps A Ø | 53.0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Amps B Ø | 160.0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Amps C Ø | 190.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | BCH001157 | Charger | 912-Offline-Distribution | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | BCH001157 | Charger | 912-Offline-Distribution | Battery Charger Patrol Insp | As Found Float Voltage | 0.0 | VDC |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | BCH001157 | Charger | 912-Offline-Distribution | Battery Charger Patrol Insp | As Left Float Voltage | 0.0 | VDC |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | BCH001157 | Charger | 912-Offline-Distribution | Battery Charger Patrol Insp | Battery Charger Current | 0.0 | amps |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | BCH001157 | Charger | 912-Offline-Distribution | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | BCH001157 | Charger | 912-Offline-Distribution | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | BCH001157 | Charger | 912-Offline-Distribution | Battery Charger Patrol Insp | General Comments | | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0435 | BreakerVacuum | HN-1203 | VCB Readings | 9 Month Operations | 0 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | General Comments | trip check | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Readings | Number of Ops last 9 Months | 0 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Operations Counter AF | 278 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0435 | BreakerVacuum | HN-1203 | VCB Readings | Operations This Read Vac | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0435 | BreakerVacuum | HN-1203 | VCB Readings | General Comments | | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0435 | BreakerVacuum | HN-1203 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0435 | BreakerVacuum | HN-1203 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0435 | BreakerVacuum | HN-1203 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0435 | BreakerVacuum | HN-1203 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0435 | BreakerVacuum | HN-1203 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0435 | BreakerVacuum | HN-1203 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0435 | BreakerVacuum | HN-1203 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0435 | BreakerVacuum | HN-1203 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0435 | BreakerVacuum | HN-1203 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | General Comments | | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Operations Counter AL | 279 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Operations This Read Vac | 1 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | 9 Month Operations | 3 | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Operations Counter AL | 253 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Operations Counter AF | 252 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | BCH001342 | Charger | 583-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | BCH001342 | Charger | 583-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | BCH001342 | Charger | 583-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | BCH001342 | Charger | 583-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | BCH001342 | Charger | 583-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .3 | amps |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Switching Operations | 0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Unknown Operations | 0 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | BCH001342 | Charger | 583-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | BCH001342 | Charger | 583-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | BCH001342 | Charger | 583-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.300 | millivolts |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Counter Readings | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Counter Readings | LTC As Found Counter | 84556 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Counter Readings | LTC As Left Counter | 84558 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Counter Readings | LTC Operations Since Last Insp | 620 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Low | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | General Comments | | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Amps C Ø | 200.0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | BCH000431 | Charger | 753-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 6000 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Amps A Ø | 90.0 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Operations Counter | 1841 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Amps B Ø | 100.0 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Amps C Ø | 100.0 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Readings | Totalizer Meter Reading | 1.2930 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BCH001555 | Charger | 841-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.400 | millivolts |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BCH001555 | Charger | 841-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BCH001555 | Charger | 841-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BCH001555 | Charger | 841-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.0 | amps |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BCH001555 | Charger | 841-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BCH001555 | Charger | 841-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BCH001555 | Charger | 841-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BCH001555 | Charger | 841-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0683 | Regulator | 616-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | YD000003 | Yard | 841-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | YD000003 | Yard | 841-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | YD000003 | Yard | 841-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | YD000003 | Yard | 841-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | YD000003 | Yard | 841-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | YD000003 | Yard | 841-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | YD000003 | Yard | 841-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | YD000003 | Yard | 841-Yard | Yard Patrol Inspection | Ambient Temp | 37 | °F |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Readings | 9 Months Operations OCB New | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | General Comments | | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Patrol Inspection | Air Compressor Belt Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Patrol Inspection | Air Leaks | None | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | YD000563 | Yard | 765-Yard | Yard Patrol Inspection | Ambient Temp | 37 | °F |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Patrol Inspection | Air Pressure OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Patrol Inspection | Air Tank Bleed (> 40°F)? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Operations This Read Vac | 4 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Switching Operations | 4 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | 9 Month Operations | 3 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1424 | Regulator | 453-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 75775 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.8 | volts |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0844 | Regulator | 810-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0032 | LTCMechanism | 158-6 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BCH001562 | Charger | 808-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BCH001562 | Charger | 808-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BCH001562 | Charger | 808-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BCH001562 | Charger | 808-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BCH001562 | Charger | 808-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.0 | amps |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BCH001562 | Charger | 808-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 54.0 | VDC |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BCH001562 | Charger | 808-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 54.0 | VDC |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BCH001562 | Charger | 808-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | General Comments | trip check | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | General Comments | | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Operations Counter AF | 413 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Operations Counter AL | 417 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | YD000003 | Yard | 841-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | YD000003 | Yard | 841-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | YD000003 | Yard | 841-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | YD000003 | Yard | 841-Yard | Yard Patrol Inspection | General Comments | | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | YD000003 | Yard | 841-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | LTCC000705 | LTCControl | 060-6 | LTC Control Insp | All Connections OK? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | LTCC000705 | LTCControl | 060-6 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | LTCC000705 | LTCControl | 060-6 | LTC Control Insp | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | LTCC000705 | LTCControl | 060-6 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | LTCC000705 | LTCControl | 060-6 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | LTCC000705 | LTCControl | 060-6 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | LTCC000705 | LTCControl | 060-6 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Readings | Number of Ops last 9 Months | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Readings | Operations This Read Oil | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Patrol Inspection | Pressure Vessel Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | LTCC000705 | LTCControl | 060-6 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | LTCC000705 | LTCControl | 060-6 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0257 | GroundTransformer | GR-GND TR 1 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0257 | GroundTransformer | GR-GND TR 1 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0257 | GroundTransformer | GR-GND TR 1 | Ground Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0257 | GroundTransformer | GR-GND TR 1 | Ground Transformer Patrol Inspection | Cleaned Mechanism Cabinet? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0257 | GroundTransformer | GR-GND TR 1 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0257 | GroundTransformer | GR-GND TR 1 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0257 | GroundTransformer | GR-GND TR 1 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0257 | GroundTransformer | GR-GND TR 1 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0257 | GroundTransformer | GR-GND TR 1 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0257 | GroundTransformer | GR-GND TR 1 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0257 | GroundTransformer | GR-GND TR 1 | Ground Transformer Patrol Inspection | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0257 | GroundTransformer | GR-GND TR 1 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Readings | LTC Totalizer Reading | 2177.28 | kw |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Readings | General Comments | | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | General Comments | | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | YD000044 | Yard | 224-Yard | Yard Patrol Inspection | Ambient Temp | 37 | °F |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | YD000044 | Yard | 224-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | YD000044 | Yard | 224-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | YD000044 | Yard | 224-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | YD000044 | Yard | 224-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Operations This Read Vac | 1 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Operations Counter AL | 193 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Operations Counter AF | 192 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Readings | Maintenance Operations | 1 | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | YD000044 | Yard | 224-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BK000719 | BreakerVacuum | 782-0822 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | YD000044 | Yard | 224-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | YD000044 | Yard | 224-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Switching Operations | 2 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Readings | 9 Months Operations OCB New | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Patrol Inspection | Air Compressor Belt Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Patrol Inspection | Air Leaks | None | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0433 | BreakerVacuum | HN-1201 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0433 | BreakerVacuum | HN-1201 | VCB Readings | Accumulated Fault Duty A Ph V | 10.76 | % |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0433 | BreakerVacuum | HN-1201 | VCB Readings | Accumulated Fault Duty B Ph V | 8.61 | % |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0433 | BreakerVacuum | HN-1201 | VCB Readings | Accumulated Fault Duty C Ph V | 7.17 | % |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0433 | BreakerVacuum | HN-1201 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0433 | BreakerVacuum | HN-1201 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0433 | BreakerVacuum | HN-1201 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0433 | BreakerVacuum | HN-1201 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Patrol Inspection | Air Pressure OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Patrol Inspection | Air Tank Bleed (> 40°F)? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | 9 Month Operations | 2 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Patrol Inspection | Bushing Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | LTCC000709 | LTCControl | 060-5 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | LTCC000709 | LTCControl | 060-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | General Comments | | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | LTCC000709 | LTCControl | 060-5 | LTC Control Insp | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | LTCC000709 | LTCControl | 060-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | LTCC000709 | LTCControl | 060-5 | LTC Control Insp | All Connections OK? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | YD000044 | Yard | 224-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Amps B Ø | 0.0 | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Amps C Ø | 2.0 | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Operations Counter | 26 | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | YD000044 | Yard | 224-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | YD000044 | Yard | 224-Yard | Yard Patrol Inspection | General Comments | no yard light | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | YD000044 | Yard | 224-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001188 | BreakerVacuum | GR-14KV TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BCH001609 | Charger | 453-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BCH001609 | Charger | 453-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BCH001609 | Charger | 453-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .4 | amps |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BCH001609 | Charger | 453-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BCH001609 | Charger | 453-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BCH001609 | Charger | 453-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | General Comments | | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Floor Swept? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | LTCC000709 | LTCControl | 060-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0722 | BreakerOil | P-1380-B | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | CH000150 | ControlHouse | EW-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | ST000047 | Structure | 224-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Amps A Ø | 1.0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | LTCC000709 | LTCControl | 060-5 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | LTCC000709 | LTCControl | 060-5 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Current Tap Position | 4R | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0291 | RecloserElectronic | 711-0483 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Readings | Winding Temp Present | 25 | °C |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Readings | Winding Temp Max | 30 | °C |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 136890 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | BCH001157 | Charger | 912-Offline-Distribution | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | General Comments | | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Operations Counter AF | 313 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Readings | Operations This Read Oil | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Patrol Inspection | Pressure Vessel Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Amps A Ø | 165.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0749 | BreakerOil | P-1394-A | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Amps B Ø | 166.0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Amps C Ø | 154.0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Max Tap Position | 6L | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 30657 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1426 | Regulator | 453-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | General Comments | | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1129 | Regulator | 765-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Current Tap Position | 6R | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | General Comments | | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Readings | Totalizer Meter Reading | .3024 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Amps C Ø | 322.0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Amps B Ø | 272.0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Amps A Ø | 342.0 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | WithLTC | 583-1 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Operations Counter AL | 315 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Readings | Operations This Read Vac | 2 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0041 | BreakerVacuum | 060-0106 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | FE000047 | Fence | 224-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Readings | Oil Temp Present | 24 | °C |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Readings | Oil Temp Max | 27 | °C |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -1.0 | psi |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Readings | General Comments | (1) not operational | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KT0019 | NonLTC | 753-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Operations Counter AF | 210 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Operations Counter AL | 210 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Operations This Read Vac | 2 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Readings | Switching Operations | 2 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0079 | BreakerVacuum | 158-6 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | FE000900 | Fence | 782-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | R0382 | Regulator | 851-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000742 | LTCControl | 808-2 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000742 | LTCControl | 808-2 | LTC Control Insp | LTC Operation Checked? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000742 | LTCControl | 808-2 | LTC Control Insp | General Comments | | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000742 | LTCControl | 808-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000742 | LTCControl | 808-2 | LTC Control Insp | All Connections OK? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Operations Counter AF | 547 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BAT000021 | Battery | P-Battery Bank Sec 1 Swgr | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BAT000021 | Battery | P-Battery Bank Sec 1 Swgr | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | LTCMechanism | GR-CLASS-B TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | LTCMechanism | GR-CLASS-B TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | LTCMechanism | GR-CLASS-B TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | LTCMechanism | GR-CLASS-B TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | LTCMechanism | GR-CLASS-B TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PN57 | LTCMechanism | GR-CLASS-B TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BAT000021 | Battery | P-Battery Bank Sec 1 Swgr | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BAT000021 | Battery | P-Battery Bank Sec 1 Swgr | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 12.2 | VDC |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 12.2 | VDC |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0166 | BreakerVacuum | 195-1310 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Operations Counter | 944 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Readings | General Comments | ok | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -1.0 | psi |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 0.00 | kw |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Amps B Ø | 38.0 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Amps A Ø | 40.0 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | 9 Month Operations | 6 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 25.0 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 23.0 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 570 | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Operations Counter | 22 | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BAT001277 | Battery | Retired Distribution | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BAT001277 | Battery | Retired Distribution | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BAT001277 | Battery | Retired Distribution | Battery Patrol Inspection | Positive DC Ground | 27.0 | VDC |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BAT001277 | Battery | Retired Distribution | Battery Patrol Inspection | Negative DC Ground | 27.8 | VDC |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BAT001277 | Battery | Retired Distribution | Battery Patrol Inspection | General Comments | | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BAT001277 | Battery | Retired Distribution | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BAT001277 | Battery | Retired Distribution | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BAT001277 | Battery | Retired Distribution | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BAT001277 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BAT001277 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BAT001277 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BAT001277 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BAT001277 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BAT001277 | Battery | Retired Distribution | Battery Patrol Inspection | All Connections OK? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Patrol Inspection | General Comments | | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | General Comments | | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000742 | LTCControl | 808-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000742 | LTCControl | 808-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000742 | LTCControl | 808-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Operations Counter AF | 252 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Operations Counter AL | 254 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Operations This Read Vac | 2 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Switching Operations | 2 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BAT001663 | Battery | 453-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BAT001663 | Battery | 453-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BAT001663 | Battery | 453-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BAT001663 | Battery | 453-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.7 | VDC |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BAT001663 | Battery | 453-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BAT001663 | Battery | 453-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000767 | LTCControl | 808-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000767 | LTCControl | 808-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000767 | LTCControl | 808-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000767 | LTCControl | 808-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000767 | LTCControl | 808-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000767 | LTCControl | 808-1 | LTC Control Insp | General Comments | | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000767 | LTCControl | 808-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | LTCC000767 | LTCControl | 808-1 | LTC Control Insp | All Connections OK? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 100280 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 191205 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | General Comments | | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Readings | Oil Temp Max | 65 | °C |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Readings | Oil Temp Present | 60 | °C |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | 9 Month Operations | 14 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | 9 Month Operations VCB New | 12 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BAT001663 | Battery | 453-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BAT001663 | Battery | 453-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Amps A Ø | 94.0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Amps B Ø | 147.0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Amps C Ø | 115.0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BAT001663 | Battery | 453-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BAT001663 | Battery | 453-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BAT001663 | Battery | 453-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | BAT001663 | Battery | 453-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | CX0137 | RecloserElectronic | 765-0551 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK000921 | BreakerVacuum | 060-0038 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | General Comments | | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | BAT000250 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | BAT000250 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | BAT000250 | Battery | Retired Distribution | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | BAT000250 | Battery | Retired Distribution | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | BAT000250 | Battery | Retired Distribution | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 130173 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | LTCC000111 | LTCControl | 195-5 | LTC Control Insp | All Connections OK? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | LTCC000111 | LTCControl | 195-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | LTCC000111 | LTCControl | 195-5 | LTC Control Insp | General Comments | | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 449 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 388 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | BAT000250 | Battery | Retired Distribution | Battery Patrol Inspection | General Comments | no longer in service | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | BAT000250 | Battery | Retired Distribution | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | BAT000250 | Battery | Retired Distribution | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | BAT000250 | Battery | Retired Distribution | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | BAT000250 | Battery | Retired Distribution | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 40 | °F |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BAT000021 | Battery | P-Battery Bank Sec 1 Swgr | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BCH001219 | Charger | 782-Battery Bank | Battery Charger Patrol Insp | General Comments | | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | WithLTC | 711-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Switching Operations | 2 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Operations This Read Vac | 2 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Amps A Ø | 0.0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Amps A Ø | 100.0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Amps B Ø | 100.0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BAT000021 | Battery | P-Battery Bank Sec 1 Swgr | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BAT000021 | Battery | P-Battery Bank Sec 1 Swgr | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BAT000021 | Battery | P-Battery Bank Sec 1 Swgr | Battery Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BAT000021 | Battery | P-Battery Bank Sec 1 Swgr | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Amps B Ø | 0.0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Amps C Ø | 0.0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | General Comments | | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1128 | Regulator | 765-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Operations Counter AF | 161 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Operations Counter AL | 161 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BK000035 | BreakerVacuum | EW-1244 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Amps C Ø | 100.0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | BAT000250 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Operations This Read Vac | 3 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Operations Counter AL | 208 | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | MX0290 | RecloserElectronic | 711-0484 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | 9 Month Operations | 0 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | 9 Month Operations VCB New | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Amps A Ø | 61.0 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Amps B Ø | 77.0 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Amps C Ø | 95.0 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | General Comments | | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Operations Counter AF | 80 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Operations Counter AL | 80 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | K0167 | BreakerVacuum | 583-0493 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Amps C Ø | 28.0 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BCH001219 | Charger | 782-Battery Bank | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BCH001219 | Charger | 782-Battery Bank | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BCH001219 | Charger | 782-Battery Bank | Battery Charger Patrol Insp | Battery Charger Current | .6 | amps |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BCH001219 | Charger | 782-Battery Bank | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BCH001219 | Charger | 782-Battery Bank | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Operations Counter AF | 208 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | General Comments | | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Fault Operations C Ø | 1 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Fault Operations B Ø | 1 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Fault Operations A Ø | 1 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | BCH001219 | Charger | 782-Battery Bank | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .860 | millivolts |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | DX0126 | RecloserHydraulic | 810-0491 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 23.6 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | FE000602 | Fence | GI-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | LTCC000111 | LTCControl | 195-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | LTCC000111 | LTCControl | 195-5 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | LTCC000111 | LTCControl | 195-5 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | LTCC000111 | LTCControl | 195-5 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | LTCC000111 | LTCControl | 195-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | KB0133 | BreakerVacuum | 195-1311 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Fault Adjusted Amps C Phase V | 2.94 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Fault Adjusted Amps B Phase V | 2.94 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | BAT000344 | Battery | 753-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Readings | Fault Adjusted Amps A Phase V | 2.94 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BK001088 | BreakerVacuum | 841-0487 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Amps C Ø | 200.0 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Amps B Ø | 100.0 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Amps A Ø | 80.0 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | 9 Month Operations | 1 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Operations Counter AF | 179 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Operations Counter AL | 179 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CAP000014 | CapacitorBank | 583-Cap Bank | Capacitor Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CAP000014 | CapacitorBank | 583-Cap Bank | Capacitor Patrol Inspection | Capacitor Condition | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CAP000014 | CapacitorBank | 583-Cap Bank | Capacitor Patrol Inspection | Capacitor Rack Condition OK? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Counter Readings | LTC As Found Counter | 96517 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Counter Readings | LTC As Left Counter | 96519 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Fault Operations Ground | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Readings | LTC Totalizer Reading | 7758.00 | kw |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK001068 | BreakerVacuum | P-1387-2 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK001068 | BreakerVacuum | P-1387-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CAP000014 | CapacitorBank | 583-Cap Bank | Capacitor Patrol Inspection | All Connections OK? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CAP000014 | CapacitorBank | 583-Cap Bank | Capacitor Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Counter Readings | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | General Comments | ok | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CAP000014 | CapacitorBank | 583-Cap Bank | Capacitor Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CAP000014 | CapacitorBank | 583-Cap Bank | Capacitor Patrol Inspection | Insulators In Good Condition? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CAP000014 | CapacitorBank | 583-Cap Bank | Capacitor Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CAP000014 | CapacitorBank | 583-Cap Bank | Capacitor Patrol Inspection | Tank Paint Condition | Adequate | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | 9 Month Operations | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Switching Operations | 1 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Amps A Ø | 120.0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | Amps B Ø | 240.0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | K0046 | BreakerVacuum | 195-1312 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Operations This Read Vac | 1 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | BCH000431 | Charger | 753-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.1 | VDC |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | BCH000431 | Charger | 753-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.1 | VDC |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | BCH000431 | Charger | 753-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | BCH000431 | Charger | 753-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | FE000417 | Fence | 808-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0775 | BreakerOil | P-SPARE # 1 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0775 | BreakerOil | P-SPARE # 1 | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0775 | BreakerOil | P-SPARE # 1 | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0775 | BreakerOil | P-SPARE # 1 | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0775 | BreakerOil | P-SPARE # 1 | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0775 | BreakerOil | P-SPARE # 1 | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0775 | BreakerOil | P-SPARE # 1 | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0775 | BreakerOil | P-SPARE # 1 | OCB Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CAP000014 | CapacitorBank | 583-Cap Bank | Capacitor Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Counter Readings | LTC Current Tap Position | 1R | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Counter Readings | LTC Operations Since Last Insp | 630 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | LTCMechanism | 158-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CAP000014 | CapacitorBank | 583-Cap Bank | Capacitor Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | CAP000014 | CapacitorBank | 583-Cap Bank | Capacitor Patrol Inspection | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | ST000117 | Structure | 158-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Counter Readings | LTC Operations Since Last Insp | 398 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PF000155 | PowerFuse | GR-14KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PF000155 | PowerFuse | GR-14KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PF000154 | PowerFuse | GR-GND TR 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PF000154 | PowerFuse | GR-GND TR 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Counter Readings | LTC As Left Counter | 129000 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Counter Readings | LTC As Found Counter | 129000 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Counter Readings | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | LTCMechanism | 060-6 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Operations Counter AL | 547 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0389 | BreakerAirMagnetic | GI-3 | AMCB Readings | Operations This Read AM | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Operations Counter AL | 250 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Operations Counter AF | 248 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | General Comments | | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | General Comments | | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 16 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 1.0 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 4.2 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | Ambient Temp | 40 | °F |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 1.0 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 20 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 14 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | MX0267 | RecloserHydraulic | 810-0490 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Amps A Ø | 95.0 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Amps B Ø | 96.0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | CH000049 | ControlHouse | Retired Distribution | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | CH000049 | ControlHouse | Retired Distribution | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Min Tap Position | 15L | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Max Tap Position | 5L | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 0 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | W0247 | NonLTC | 616-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | 9 Month Operations | 2 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | R1185 | Regulator | 453-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | R1237 | Regulator | 782-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | ST000140 | Structure | 195-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | n | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | YD000135 | Yard | 195-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 33 | °F |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | BAT000098 | Battery | GI-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PF000161 | PowerFuse | GR-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PF000161 | PowerFuse | GR-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PF000160 | PowerFuse | GR-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PF000160 | PowerFuse | GR-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Amps C Ø | 428.0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Amps B Ø | 418.0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PF000159 | PowerFuse | GR-GND TR 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PF000159 | PowerFuse | GR-GND TR 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PF000157 | PowerFuse | GR-14KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PF000157 | PowerFuse | GR-14KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Amps A Ø | 449.0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0477 | BreakerVacuum | 808-0048 | VCB Readings | 9 Month Operations | 5 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Readings | General Comments | | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | Ambient Temp | 40 | °F |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | YD000221 | Yard | 753-Yard | Yard Patrol Inspection | General Comments | | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | MX0268 | RecloserElectronic | 765-0550 | Recloser Electronic Patrol Inspection | Amps C Ø | 89.0 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Amps A Ø | 75.0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | CH000049 | ControlHouse | Retired Distribution | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | CH000049 | ControlHouse | Retired Distribution | Control House Patrol Inspection | General Comments | is no longer there, [please remove.. | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | CH000049 | ControlHouse | Retired Distribution | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | CH000049 | ControlHouse | Retired Distribution | Control House Patrol Inspection | Follow-up Action Required? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | CH000049 | ControlHouse | Retired Distribution | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | CH000049 | ControlHouse | Retired Distribution | Control House Patrol Inspection | Control Handle "Red Flagged"? | n | If Bkr is Closed |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | CH000049 | ControlHouse | Retired Distribution | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Amps B Ø | 77.0 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Readings | Amps C Ø | 46.0 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0141 | BreakerVacuum | 753-1322 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | K0184 | BreakerVacuum | 060-6 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | 9 Month Operations | 3 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0775 | BreakerOil | P-SPARE # 1 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | WithLTC | 808-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | 9 Month Operations | 14 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | 9 Month Operations VCB New | 14 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Amps A Ø | 165.0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Amps B Ø | 166.0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Readings | Amps C Ø | 154.0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001403 | BreakerVacuum | 158-0662 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Operations Counter AL | 140 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Operations Counter AF | 140 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | CB0273 | BreakerVacuum | 616-1425 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | K0070 | BreakerVacuum | 782-0823 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | KB0086 | BreakerVacuum | 808-0187 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BAT000150 | Battery | EW-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BAT000150 | Battery | EW-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BAT000150 | Battery | EW-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | SWG000062 | Switchgear | GI-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PF000156 | PowerFuse | GR-14KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PF000156 | PowerFuse | GR-14KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Operations Counter AF | 249 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Operations Counter AL | 251 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Operations This Read Vac | 2 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Switching Operations | 2 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Readings | General Comments | | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | General Comments | | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 11780 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | 9 Month Operations | 2 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Amps A Ø | 80.0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Amps B Ø | 80.0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Amps C Ø | 90.0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000245 | BreakerVacuum | 196-0009 | VCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Readings | Operations This Read Oil | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Readings | Number of Ops last 9 Months | 0 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | YD000113 | Yard | 158-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | General Comments | ok | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | General Comments | | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1500 | psi |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Readings | Totalizer Meter Reading | .7880 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Readings | Winding Temp Present | 25 | °C |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Ambient Temp | 30 | °F |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Free of Audible Arcing? | n | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | General Comments | | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | 9 Month Operations | 2 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Min Tap Position | 7L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Readings | LTC Totalizer Reading | 11347.20 | kw |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.7 | volts |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 11634 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0027 | Regulator | 753-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | ST000250 | Structure | 616-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Patrol Inspection | Tank Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 36 | °F |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | General Comments | | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | General Comments | | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BAT000150 | Battery | EW-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BAT000150 | Battery | EW-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BAT000150 | Battery | EW-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BAT000150 | Battery | EW-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Operations Counter AL | 218 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Operations This Read Vac | 2 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Switching Operations | 2 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PF001309 | PowerFuse | GI-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PF001309 | PowerFuse | GI-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | LTCMechanism | HN-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | LTCMechanism | HN-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | LTCMechanism | HN-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | LTCMechanism | HN-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | LTCMechanism | HN-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | LTCMechanism | HN-TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | LTCMechanism | GR-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | LTCMechanism | GR-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | LTCMechanism | GR-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | LTCMechanism | GR-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | LTCMechanism | GR-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | LTCMechanism | GR-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0086 | LTCMechanism | GR-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | 9 Month Operations | 2 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Amps A Ø | 6.0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Amps B Ø | 14.0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Amps C Ø | 7.0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.2 | VDC |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.3 | VDC |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Exp/Missing Not Repl | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | BAT001241 | Battery | 583-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | YD000233 | Yard | 782-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | YD000233 | Yard | 782-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Operations Counter AF | 222 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Operations Counter AL | 224 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Operations This Read Vac | 2 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Switching Operations | 2 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Unknown Operations | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | YD000233 | Yard | 782-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | YD000233 | Yard | 782-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | YD000233 | Yard | 782-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | YD000233 | Yard | 782-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | YD000233 | Yard | 782-Yard | Yard Patrol Inspection | Ambient Temp | 48 | °F |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0438 | BreakerVacuum | HN-12KV TR 1 | VCB Readings | 9 Month Operations | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0438 | BreakerVacuum | HN-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0438 | BreakerVacuum | HN-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0438 | BreakerVacuum | HN-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0438 | BreakerVacuum | HN-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0438 | BreakerVacuum | HN-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0438 | BreakerVacuum | HN-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0438 | BreakerVacuum | HN-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0438 | BreakerVacuum | HN-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001180 | BreakerVacuum | GR-1462 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0438 | BreakerVacuum | HN-12KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0438 | BreakerVacuum | HN-12KV TR 1 | VCB Readings | General Comments | | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0438 | BreakerVacuum | HN-12KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0026 | Regulator | 753-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | FE000137 | Fence | 195-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BAT000150 | Battery | EW-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BAT000150 | Battery | EW-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BAT000150 | Battery | EW-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BAT000150 | Battery | EW-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | BAT000150 | Battery | EW-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | ST000241 | Structure | 782-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | FE000221 | Fence | 753-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000954 | BreakerVacuum | P-1391-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000954 | BreakerVacuum | P-1391-2 | VCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000954 | BreakerVacuum | P-1391-2 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000954 | BreakerVacuum | P-1391-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001177 | BreakerVacuum | GR-14KV BUS TIE | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000954 | BreakerVacuum | P-1391-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000954 | BreakerVacuum | P-1391-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | YD000233 | Yard | 782-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | YD000233 | Yard | 782-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000954 | BreakerVacuum | P-1391-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000954 | BreakerVacuum | P-1391-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000954 | BreakerVacuum | P-1391-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000954 | BreakerVacuum | P-1391-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000954 | BreakerVacuum | P-1391-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000954 | BreakerVacuum | P-1391-2 | VCB Readings | 9 Month Operations | 0 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 195983 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | R0885 | Regulator | 810-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | YD000233 | Yard | 782-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | YD000233 | Yard | 782-Yard | Yard Patrol Inspection | General Comments | | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | YD000233 | Yard | 782-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 13:25 | Distribution | Mortons Gap Quarterly Inspection | YD000233 | Yard | 782-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000583 | BreakerVacuum | 196-0090 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | General Comments | | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 10083 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Operations Counter AF | 206 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Operations Counter AL | 208 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Operations This Read Vac | 2 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001247 | BreakerVacuum | GR-14KV TR 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Switching Operations | 2 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Counter Readings | LTC Operations Since Last Insp | 359 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Counter Readings | LTC Min Tap Position | 15L | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Switching Operations | 2 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Operations This Read Vac | 2 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Operations Counter AL | 183 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Operations Counter AF | 181 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Amps C Ø | 216.0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Amps B Ø | 219.0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Amps A Ø | 241.0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | 9 Month Operations VCB New | 13 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001806 | BreakerVacuum | 060-0024 | VCB Readings | 9 Month Operations | 15 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Amps C Ø | 21.0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Amps B Ø | 28.0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Amps A Ø | 28.0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | 9 Month Operations | 10 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Fault Operations Ground | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0783 | BreakerOil | P-SPARE # 7 | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0783 | BreakerOil | P-SPARE # 7 | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0783 | BreakerOil | P-SPARE # 7 | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0783 | BreakerOil | P-SPARE # 7 | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0783 | BreakerOil | P-SPARE # 7 | OCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0783 | BreakerOil | P-SPARE # 7 | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0783 | BreakerOil | P-SPARE # 7 | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0783 | BreakerOil | P-SPARE # 7 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0783 | BreakerOil | P-SPARE # 7 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Counter Readings | General Comments | | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Counter Readings | LTC As Found Counter | 13602 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Counter Readings | LTC As Left Counter | 13602 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 40 | °C |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 15 | °C |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Counter Readings | LTC Operations Since Last Insp | 318 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCM000062 | LTCMechanism | 196-6 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | General Comments | | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Operations Counter AF | 223 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Operations Counter AL | 225 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Operations This Read Vac | 2 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Counter Readings | LTC As Left Counter | 55716 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Counter Readings | LTC As Found Counter | 55706 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Counter Readings | General Comments | | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | S0039 | LTCMechanism | 583-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0432 | BreakerVacuum | HN-1200 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0432 | BreakerVacuum | HN-1200 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0432 | BreakerVacuum | HN-1200 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0432 | BreakerVacuum | HN-1200 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0432 | BreakerVacuum | HN-1200 | VCB Readings | Accumulated Fault Duty C Ph V | 15.07 | % |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0432 | BreakerVacuum | HN-1200 | VCB Readings | Accumulated Fault Duty B Ph V | 20.09 | % |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0432 | BreakerVacuum | HN-1200 | VCB Readings | Accumulated Fault Duty A Ph V | 20.09 | % |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001181 | BreakerVacuum | GR-1463 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0432 | BreakerVacuum | HN-1200 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | 9 Month Operations | 2 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Amps A Ø | 130.0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Amps B Ø | 165.0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Amps C Ø | 145.0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | High | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | LTCMechanism | 195-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Readings | 9 Months Operations OCB New | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol  Inspection | Windows/Doors Condition OK? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol  Inspection | Ventilation Free of Debris? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol  Inspection | Trash Emptied? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol  Inspection | Station Ground Set On Site? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol  Inspection | Panels Dusted? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol  Inspection | Panel Lights OK? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol  Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol  Inspection | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol  Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol  Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol  Inspection | Floor Swept? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol  Inspection | Floor Condition Acceptable? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Patrol Inspection | Air Compressor Belt Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Patrol Inspection | Air Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Patrol Inspection | Air Pressure OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Patrol Inspection | Air Tank Bleed (> 40°F)? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Amps A Ø | 130.0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Amps B Ø | 120.0 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | General Comments | | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | YD000121 | Yard | 583-Yard | Yard Patrol Inspection | Ambient Temp | 36 | °F |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | KR0028 | Regulator | 753-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Amps C Ø | 90.0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | TX000130 | WithLTC | 196-6 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Vegetation | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | YD000198 | Yard | 851-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | General Comments | | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | ST000125 | Structure | 583-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Platform/Walkway/Railing OK? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | ST000205 | Structure | 851-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | General Comments | | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | YD000244 | Yard | 616-Yard | Yard Patrol Inspection | Ambient Temp | 43 | °F |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | YD000113 | Yard | 158-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | YD000113 | Yard | 158-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | YD000113 | Yard | 158-Yard | Yard Patrol Inspection | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | YD000113 | Yard | 158-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | YD000113 | Yard | 158-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | YD000113 | Yard | 158-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | YD000113 | Yard | 158-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | YD000113 | Yard | 158-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | YD000113 | Yard | 158-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | YD000113 | Yard | 158-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | YD000113 | Yard | 158-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | YD000113 | Yard | 158-Yard | Yard Patrol Inspection | Ambient Temp | 36 | °F |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | FE000112 | Fence | 158-Fence | Fence Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | General Comments | | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0434 | BreakerVacuum | HN-1202 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0434 | BreakerVacuum | HN-1202 | VCB Readings | General Comments | | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0434 | BreakerVacuum | HN-1202 | VCB Patrol Inspection | General Comments | | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0434 | BreakerVacuum | HN-1202 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0434 | BreakerVacuum | HN-1202 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0434 | BreakerVacuum | HN-1202 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0434 | BreakerVacuum | HN-1202 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0434 | BreakerVacuum | HN-1202 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0434 | BreakerVacuum | HN-1202 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Switching Operations | 1 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Operations This Read Vac | 10 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Operations Counter AL | 116 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Operations Counter AF | 116 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0434 | BreakerVacuum | HN-1202 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0434 | BreakerVacuum | HN-1202 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LB0434 | BreakerVacuum | HN-1202 | VCB Readings | 9 Month Operations | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000559 | BreakerVacuum | 158-2 | VCB Readings | Maintenance Operations | 9 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Counter Readings | LTC Operations Since Last Insp | 383 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Counter Readings | LTC As Left Counter | 67174 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Counter Readings | LTC As Found Counter | 67171 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Counter Readings | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | LTCMechanism | 158-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | 9 Month Operations | 4 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Amps A Ø | 240.0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Amps B Ø | 240.0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Amps C Ø | 280.0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000584 | BreakerVacuum | 196-0144 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Patrol Inspection | Pressure Vessel Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Readings | Operations This Read Oil | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Readings | Number of Ops last 9 Months | 1 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | CH000035 | ControlHouse | 158-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | FE000119 | Fence | 583-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Patrol Inspection | Pressure Vessel Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Readings | Operations This Read Oil | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Readings | Number of Ops last 9 Months | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Operations This Read Vac | 4 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Operations Counter AL | 520 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Operations Counter AF | 516 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Patrol Inspection | Air Tank Bleed (> 40°F)? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Patrol Inspection | Air Pressure OK? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Readings | TV Winding Temp Present | 42 | °C |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Readings | TV Winding Temp Max | 40 | °C |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Readings | Oil Temp Present | 23 | °C |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Readings | Oil Temp Max | 46 | °C |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1175 | psi |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Readings | 9 Months Operations OCB New | 3 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Patrol Inspection | Air Compressor Belt Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0779 | BreakerOil | P-SPARE # 13 | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Patrol Inspection | Air Compressor Belt Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Readings | 9 Months Operations OCB New | 1 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Amps C Ø | 350.0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Amps B Ø | 320.0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Amps A Ø | 350.0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | 9 Month Operations | 1 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Readings | Oil Temp Max | 60 | °C |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001179 | BreakerVacuum | GR-1465 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 7884.00 | kw |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Readings | Switching Operations | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | SF6 Pressure Indicator | good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Readings | Operations This Read SF6 | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Readings | Operations Counter AL | 61 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Readings | Operations Counter AF | 61 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Readings | Num Operations Last 9 Months | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Readings | General Comments | | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | General Comments | | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Switching Operations | 4 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Ambient Temperature | 30 | °F |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Readings | 9 Month Operations GCB New | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Patrol Inspection | Air Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Patrol Inspection | Air Compressor Belt Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0758 | BreakerOil | P-14KV TR 4-B | OCB Readings | 9 Months Operations OCB New | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Amps C Ø | 240.0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Amps B Ø | 240.0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Amps A Ø | 240.0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | 9 Month Operations | 4 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | LTCC000918 | LTCControl | 158-5 | LTC Control Insp | All Connections OK? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | LTCC000918 | LTCControl | 158-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | LTCC000918 | LTCControl | 158-5 | LTC Control Insp | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | LTCC000918 | LTCControl | 158-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | LTCC000918 | LTCControl | 158-5 | LTC Control Insp | LTC Output Voltage Level | 125.1 | VAC |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | LTCC000918 | LTCControl | 158-5 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | LTCC000918 | LTCControl | 158-5 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | LTCC000918 | LTCControl | 158-5 | LTC Control Insp | VRR Time Delay | 60 | Seconds |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Readings | General Comments | | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | LTCC000919 | LTCControl | 158-6 | LTC Control Insp | All Connections OK? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | LTCC000919 | LTCControl | 158-6 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | LTCC000919 | LTCControl | 158-6 | LTC Control Insp | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | LTCC000919 | LTCControl | 158-6 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | LTCC000919 | LTCControl | 158-6 | LTC Control Insp | LTC Output Voltage Level | 125.1 | VAC |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | LTCC000919 | LTCControl | 158-6 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Readings | LV Winding Temp Present | 26 | °C |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Readings | LV Winding Temp Max | 42 | °C |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Readings | HV Winding Temp Present | 25 | °C |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Readings | HV Winding Temp Max | 43 | °C |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Readings | General Comments | | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Operations Counter | 38 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | General Comments | | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Patrol Inspection | Air Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Patrol Inspection | Air Pressure OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Patrol Inspection | Air Tank Bleed (> 40°F)? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0431 | BreakerVacuum | 808-0111 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Readings | Fault Operations | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB001375 | BreakerSF6 | EW-6658 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Amps C Ø | 365.0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Operations Counter | 109 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Amps B Ø | 342.0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Amps A Ø | 362.0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Accumulated Fault Duty C Ph V | 1.93 | % |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Accumulated Fault Duty B Ph V | 1.93 | % |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Accumulated Fault Duty A Ph V | 1.93 | % |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | 9 Month Operations | 0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Amps A Ø | 0.0 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Amps B Ø | 0.0 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | KX0079 | RecloserElectronic | 841-0489 | Recloser Electronic Patrol Inspection | Amps C Ø | 0.0 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Readings | H2 Winding Temp Max | 30 | °C |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Readings | H2 Winding Temp Present | 15 | °C |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 4.0 | psi |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 325 | psi |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 32 | °C |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 18 | °C |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Readings | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Readings | LTC Totalizer Reading | 14476.80 | kw |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Readings | Oil Temp Max | 39 | °C |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Readings | Oil Temp Present | 26 | °C |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Readings | Totalizer Meter Reading | 1.5080 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Readings | Winding Temp Max | 50 | °C |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Amps A Ø | 101.0 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Amps B Ø | 65.0 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Amps C Ø | 96.0 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Readings | Winding Temp Present | 27 | °C |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | S0023 | WithLTC | 158-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | RC000429 | RecloserElectronic | 765-0552 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Operations Counter AL | 148 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Operations Counter AF | 148 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | General Comments | | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LB1295 | BreakerVacuum | EW-12KV TR1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.5 | psi |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Readings | LV Winding Temp Present | -60 | °C |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Readings | LV Winding Temp Max | -60 | °C |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Patrol Inspection | Pressure Vessel Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Readings | Operations This Read Oil | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Readings | Number of Ops last 9 Months | 1 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Patrol Inspection | Air Tank Bleed (> 40°F)? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Patrol Inspection | Air Pressure OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0738 | BreakerOil | P-1388-B | OCB Patrol Inspection | Air Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0779 | BreakerOil | P-SPARE # 13 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0779 | BreakerOil | P-SPARE # 13 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0779 | BreakerOil | P-SPARE # 13 | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0779 | BreakerOil | P-SPARE # 13 | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0779 | BreakerOil | P-SPARE # 13 | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0779 | BreakerOil | P-SPARE # 13 | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0779 | BreakerOil | P-SPARE # 13 | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0779 | BreakerOil | P-SPARE # 13 | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Switching Operations | 1 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Operations This Read Vac | 1 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Operations Counter AL | 188 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Operations Counter AF | 188 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 34 | °C |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 15 | °C |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 30 | °C |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.0950 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 15 | °C |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 35 | °C |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LT0087 | WithLTC | HN-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 20 | °C |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | K0066 | BreakerVacuum | 158-5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | PN56 | WithLTC | GI-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | SWG000079 | Switchgear | HN-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | SWG000079 | Switchgear | HN-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | SWG000079 | Switchgear | HN-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | SWG000079 | Switchgear | HN-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | SWG000079 | Switchgear | HN-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | SWG000079 | Switchgear | HN-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | SWG000079 | Switchgear | HN-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | SWG000079 | Switchgear | HN-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | SWG000079 | Switchgear | HN-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | SWG000079 | Switchgear | HN-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | SWG000079 | Switchgear | HN-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | SWG000079 | Switchgear | HN-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | SWG000079 | Switchgear | HN-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | SWG000079 | Switchgear | HN-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | SWG000079 | Switchgear | HN-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | SWG000079 | Switchgear | HN-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000774 | BreakerVacuum | P-1385-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BK000774 | BreakerVacuum | P-1385-1 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Operations Counter AL | 133 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Operations Counter AF | 133 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | General Comments | counter is bad, did not have one | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | General Comments | barb wire rusty and top rail is rusty back left corner posts need replaaced, multiple bayonets loose on fence | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | General Comments | ok | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | 9 Month Operations | 2 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Amps A Ø | 115.0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Amps B Ø | 130.0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Amps C Ø | 115.0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | ST000254 | Structure | 453-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | General Comments | Barbed wire is broken and missing pieces along top of left fence. | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | FE000247 | Fence | 453-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | General Comments | | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Operations Counter AF | 223 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Operations Counter AL | 225 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Operations This Read Vac | 2 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Switching Operations | 2 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PF000158 | PowerFuse | GR-14KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | PF000158 | PowerFuse | GR-14KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000581 | BreakerVacuum | 196-0008 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | 9 Month Operations | 2 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Amps A Ø | 13.0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Amps B Ø | 24.0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Amps C Ø | 10.0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BCH000003 | Charger | P-Battery Charger Sec 1 Swgr | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BCH000003 | Charger | P-Battery Charger Sec 1 Swgr | Battery Charger Patrol Insp | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | BCH000003 | Charger | P-Battery Charger Sec 1 Swgr | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | General Comments | | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000582 | BreakerVacuum | 196-0052 | VCB Readings | Operations Counter AF | 216 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Amps C Ø | 89.0 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Amps B Ø | 100.0 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Amps A Ø | 91.0 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | K0183 | BreakerVacuum | 753-1320 | VCB Readings | 9 Month Operations | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Readings | Winding Temp Present | 50 | °C |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Readings | Winding Temp Max | 85 | °C |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Readings | Totalizer Meter Reading | 1.5660 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | BCH001571 | Charger | 616-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .200 | millivolts |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | BCH001571 | Charger | 616-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | BCH001571 | Charger | 616-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | BCH001571 | Charger | 616-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | BCH001571 | Charger | 616-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | BCH001571 | Charger | 616-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | BCH001571 | Charger | 616-Battery Charger | Battery Charger Patrol Insp | General Comments | ok | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | BCH001571 | Charger | 616-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Readings | Oil Temp Max | 65 | °C |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Readings | LTC Totalizer Reading | 28188.00 | kw |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Readings | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0403 | WithLTC | 060-6 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Amps A Ø | 3.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Amps B Ø | 2.9 | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Amps C Ø | 3.0 | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Operations Counter | 0 | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/9/2023 15:23 | Distribution | Newtown Switching Quarterly Inspection | RC900700 | RecloserElectronic | 224-0228 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/10/2023 7:36 | Distribution | Hancock Quarterly Inspection | LTCC000518 | LTCControl | HN-TRANS 1 | LTC Control Insp | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Readings | 9 Months Operations OCB New | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Patrol Inspection | Air Compressor Belt Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Patrol Inspection | Air Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Patrol Inspection | Air Pressure OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Patrol Inspection | Air Tank Bleed (> 40°F)? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Patrol Inspection | Pressure Vessel Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0730 | BreakerOil | P-1384-B | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | T0178 | WithLTC | 158-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | LTCC000919 | LTCControl | 158-6 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | LTCC000919 | LTCControl | 158-6 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | CH000001 | ControlHouse | 841-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | Ambient Temp | 32 | °F |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | LTCC000804 | LTCControl | 711-1 | LTC Control Insp | All Connections OK? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | LTCC000804 | LTCControl | 711-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | LTCC000804 | LTCControl | 711-1 | LTC Control Insp | General Comments | | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | LTCC000804 | LTCControl | 711-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | LTCC000804 | LTCControl | 711-1 | LTC Control Insp | LTC Output Voltage Level | 124.5 | VAC |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | LTCC000804 | LTCControl | 711-1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | LTCC000804 | LTCControl | 711-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | LTCC000804 | LTCControl | 711-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | LTCC000804 | LTCControl | 711-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | n | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | General Comments | washout back fence | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | YD000248 | Yard | 453-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Readings | General Comments | | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Readings | LTC Totalizer Reading | 8064.00 | kw |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Operations Counter AF | 176 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Operations Counter AL | 176 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | General Comments | | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Readings | Totalizer Meter Reading | .5600 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | FE000849 | Fence | 810-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001178 | BreakerVacuum | GR-1464 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | FE000002 | Fence | 841-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | 9 Month Operations | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Amps A Ø | 155.0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Amps B Ø | 202.0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Readings | Amps C Ø | 124.0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001339 | BreakerVacuum | 158-0660 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | M0070 | NonLTC | 765-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Readings | Number of Ops last 9 Months | 3 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Readings | Operations This Read Oil | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Patrol Inspection | Pressure Vessel Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0742 | BreakerOil | P-1390-B | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | WithLTC | 196-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Patrol Inspection | Pressure Vessel Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Readings | Number of Ops last 9 Months | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Readings | General Comments | | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Switching Operations | 4 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Operations This Read Vac | 4 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Operations Counter AL | 101 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Operations Counter AF | 97 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | General Comments | | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | General Comments | | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Operations Counter AF | 171 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Operations Counter AL | 171 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | 9 Month Operations | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | BAT001653 | Battery | 616-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | YD000009 | Yard | 810-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | YD000009 | Yard | 810-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | BAT001653 | Battery | 616-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 55 | °F |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | BAT001653 | Battery | 616-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | BAT001653 | Battery | 616-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | BAT001653 | Battery | 616-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | BAT001653 | Battery | 616-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | BAT001653 | Battery | 616-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.6 | VDC |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.7 | VDC |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Amps B Ø | 230.0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Amps A Ø | 205.0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | 9 Month Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Readings | Operations This Read Oil | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | BAT001102 | Battery | 841-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Amps C Ø | 0.0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Amps B Ø | 0.0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Amps A Ø | 0.0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | 9 Month Operations | 2 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0160 | GroundTransformer | P-GND TR 2B | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0160 | GroundTransformer | P-GND TR 2B | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Patrol Inspection | Pressure Vessel Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Operations Counter AF | 132 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Operations Counter AL | 132 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | LTCC000776 | LTCControl | 841-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | LTCC000776 | LTCControl | 841-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | LTCC000776 | LTCControl | 841-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | LTCC000776 | LTCControl | 841-1 | LTC Control Insp | LTC Output Voltage Level | 123.9 | VAC |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | LTCC000776 | LTCControl | 841-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | LTCC000776 | LTCControl | 841-1 | LTC Control Insp | General Comments | | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | LTCC000776 | LTCControl | 841-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | LTCC000776 | LTCControl | 841-1 | LTC Control Insp | All Connections OK? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Counter Readings | LTC Operations Since Last Insp | 837 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Counter Readings | LTC As Left Counter | 14307 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Counter Readings | LTC As Found Counter | 14297 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Counter Readings | General Comments | | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Unknown Operations | 0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Switching Operations | 0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Operations This Read AM | 0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Operations Counter AL | 460 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Operations Counter AF | 460 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | LTCMechanism | 841-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | General Comments | | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | BB0430 | BreakerVacuum | 808-0050 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Amps A Ø | 0.0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Amps B Ø | 0.0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Amps C Ø | 0.0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Switching Operations | 2 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Operations This Read Vac | 2 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Operations Counter AL | 170 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Operations Counter AF | 168 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0160 | GroundTransformer | P-GND TR 2B | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0160 | GroundTransformer | P-GND TR 2B | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0258 | GroundTransformer | GR-GND TR 2 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0258 | GroundTransformer | GR-GND TR 2 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0258 | GroundTransformer | GR-GND TR 2 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0258 | GroundTransformer | GR-GND TR 2 | Ground Transformer Patrol Inspection | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0258 | GroundTransformer | GR-GND TR 2 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0258 | GroundTransformer | GR-GND TR 2 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | LTCC000984 | LTCControl | 583-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | LTCC000984 | LTCControl | 583-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | LTCC000984 | LTCControl | 583-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | LTCC000984 | LTCControl | 583-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | LTCC000984 | LTCControl | 583-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0258 | GroundTransformer | GR-GND TR 2 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0258 | GroundTransformer | GR-GND TR 2 | Ground Transformer Patrol Inspection | Cleaned Mechanism Cabinet? | y | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | LTCC000984 | LTCControl | 583-1 | LTC Control Insp | General Comments | | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | LTCC000984 | LTCControl | 583-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/9/2023 11:01 | Distribution | Days Branch Quarterly Inspection | LTCC000984 | LTCControl | 583-1 | LTC Control Insp | All Connections OK? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0258 | GroundTransformer | GR-GND TR 2 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | LT0258 | GroundTransformer | GR-GND TR 2 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BK001287 | BreakerVacuum | 060-BT5-6 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCC000736 | LTCControl | 196-5 | LTC Control Insp | All Connections OK? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCC000736 | LTCControl | 196-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCC000736 | LTCControl | 196-5 | LTC Control Insp | General Comments | | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCC000736 | LTCControl | 196-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCC000736 | LTCControl | 196-5 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCC000736 | LTCControl | 196-5 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Yard Lights Working? | n | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | General Comments | 1 yard light out by gate | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Follow-up Action Required? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | YD000606 | Yard | EW-Yard | Yard Patrol Inspection | Ambient Temp | 30 | °F |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 118621 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | YD000009 | Yard | 810-Yard | Yard Patrol Inspection | Ambient Temp | 36 | °F |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Readings | General Comments | | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Readings | LTC Totalizer Reading | 1627.20 | kw |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Readings | Oil Temp Present | 36 | °C |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Counter Readings | LTC Operations Since Last Insp | 576 | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Counter Readings | LTC Min Tap Position | 16L | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Operations Counter AF | 176 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Operations Counter AL | 176 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Counter Readings | LTC As Left Counter | 62082 | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Counter Readings | LTC As Found Counter | 62073 | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | B0422 | LTCMechanism | 711-1 | LTC Counter Readings | General Comments | | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | 9 Month Operations | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Max Tap Position | 5L | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Min Tap Position | 13L | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Amps A Ø | 8.0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Amps B Ø | 7.6 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | General Comments | | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Readings | Amps C Ø | 200.0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Counter Readings | LTC Operations Since Last Insp | 410 | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Readings | Totalizer Meter Reading | .2260 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | B0394 | WithLTC | 841-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | General Comments | | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Counter Readings | LTC Max Tap Position | 14L | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Counter Readings | LTC As Left Counter | 162500 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Amps C Ø | 235.0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Amps B Ø | 280.0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Amps A Ø | 265.0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | FE000603 | Fence | EW-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Counter Readings | LTC As Found Counter | 162500 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Counter Readings | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | 9 Month Operations | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | BCH001338 | Charger | GI-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | BCH001338 | Charger | GI-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | BCH001338 | Charger | GI-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | BCH001338 | Charger | GI-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | BCH001338 | Charger | GI-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.7 | VDC |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | BCH001338 | Charger | GI-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.7 | VDC |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Max Tap Position | 5L | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | YD000009 | Yard | 810-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | YD000009 | Yard | 810-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0785 | BreakerOil | P-SPARE # 9 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0785 | BreakerOil | P-SPARE # 9 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0785 | BreakerOil | P-SPARE # 9 | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0785 | BreakerOil | P-SPARE # 9 | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0785 | BreakerOil | P-SPARE # 9 | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0785 | BreakerOil | P-SPARE # 9 | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0785 | BreakerOil | P-SPARE # 9 | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0785 | BreakerOil | P-SPARE # 9 | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0785 | BreakerOil | P-SPARE # 9 | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001176 | BreakerVacuum | GR-1466 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | General Comments | | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 69088 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0716 | Regulator | 616-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | ST000597 | Structure | EW-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | YD000009 | Yard | 810-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | YD000009 | Yard | 810-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | YD000009 | Yard | 810-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | YD000009 | Yard | 810-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | YD000009 | Yard | 810-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | YD000009 | Yard | 810-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Readings | Amps C Ø | 5.0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000586 | BreakerVacuum | 196-5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCC000736 | LTCControl | 196-5 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCC000736 | LTCControl | 196-5 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCC000736 | LTCControl | 196-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000480 | BreakerVacuum | 158-0214 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | YD000009 | Yard | 810-Yard | Yard Patrol Inspection | General Comments | | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | YD000009 | Yard | 810-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | R0715 | Regulator | 616-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000588 | BreakerVacuum | 196-6 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | General Comments | | |
| 1/9/2023 10:53 | Distribution | Forrestdale Quarterly Inspection | ST000226 | Structure | 753-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | B0363 | LTCMechanism | 060-5 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Patrol Inspection | Air Tank Bleed (> 40°F)? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCC000723 | LTCControl | 196-6 | LTC Control Insp | General Comments | | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCC000723 | LTCControl | 196-6 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCC000723 | LTCControl | 196-6 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCC000723 | LTCControl | 196-6 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCC000723 | LTCControl | 196-6 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCC000723 | LTCControl | 196-6 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 36 | °C |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 18 | °C |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | 9 Months Operations | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Readings | General Comments | | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 21 | °C |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | YD000070 | Yard | 711-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | LTCMechanism | 196-5 | LTC Counter Readings | LTC As Found Counter | 46129 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | LTCMechanism | 196-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | YD000070 | Yard | 711-Yard | Yard Patrol Inspection | Vegetation | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0781 | BreakerOil | P-SPARE # 5 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | YD000070 | Yard | 711-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0781 | BreakerOil | P-SPARE # 5 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0781 | BreakerOil | P-SPARE # 5 | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0781 | BreakerOil | P-SPARE # 5 | OCB Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0781 | BreakerOil | P-SPARE # 5 | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0781 | BreakerOil | P-SPARE # 5 | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0781 | BreakerOil | P-SPARE # 5 | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0781 | BreakerOil | P-SPARE # 5 | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0781 | BreakerOil | P-SPARE # 5 | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Readings | 9 Months Operations OCB New | 1 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Patrol Inspection | Air Compressor Belt Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Patrol Inspection | Air Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0756 | BreakerOil | P-14KV TR 3-B | OCB Patrol Inspection | Air Pressure OK? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | LTCMechanism | 196-5 | LTC Counter Readings | General Comments | | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .3 | psi |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Readings | LTC Totalizer Reading | 3641.76 | kw |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | LTCMechanism | 196-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | LTCMechanism | 196-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Readings | General Comments | | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | Nitro cyl. at 0 psi and needs refield. | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 39 | °C |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 21 | °C |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Operations Counter AF | 189 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Operations Counter AL | 189 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Amps A Ø | 117.0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Amps B Ø | 137.0 | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Amps C Ø | 142.0 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | ST000077 | Structure | 711-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0160 | GroundTransformer | P-GND TR 2B | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0160 | GroundTransformer | P-GND TR 2B | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Amps C Ø | 13.8 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0160 | GroundTransformer | P-GND TR 2B | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0160 | GroundTransformer | P-GND TR 2B | Ground Transformer Patrol Inspection | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0160 | GroundTransformer | P-GND TR 2B | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Readings | Totalizer Meter Reading | .5058 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Amps B Ø | 18.8 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Amps A Ø | 19.1 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0160 | GroundTransformer | P-GND TR 2B | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0160 | GroundTransformer | P-GND TR 2B | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0160 | GroundTransformer | P-GND TR 2B | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LT0160 | GroundTransformer | P-GND TR 2B | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Patrol Inspection | Tank Leaks | None | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | General Comments | | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0768 | BreakerOil | P-GND TR 2-B | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 40 | °C |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | 9 Month Operations | 10 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK001289 | BreakerVacuum | 158-0661 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | 9 Month Operations | 4 | |
| 1/9/2023 15:22 | Distribution | Bond Quarterly Inspection | BK000481 | BreakerVacuum | 158-0215 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Amps C Ø | 240.0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Amps B Ø | 200.0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Amps A Ø | 240.0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 10:34 | Distribution | Holmes Mill Quarterly Inspection | ST000010 | Structure | 810-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 40 | °C |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 21 | °C |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | General Comments | | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Switching Operations | 4 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Readings | 9 Months Operations OCB New | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 130031 | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Counter Readings | LTC Operations Since Last Insp | 386 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Counter Readings | LTC As Left Counter | 118326 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Counter Readings | LTC As Found Counter | 118326 | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Counter Readings | General Comments | | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | LTCMechanism | 196-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/9/2023 14:42 | Distribution | Ashland Avenue Quarterly Inspection | B0390 | LTCMechanism | 808-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Operations This Read Vac | 4 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Operations Counter AL | 345 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Operations Counter AF | 341 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Maintenance Operations | 0 | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Patrol Inspection | General Comments | | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | YD000070 | Yard | 711-Yard | Yard Patrol Inspection | Ambient Temp | 38 | °F |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | YD000070 | Yard | 711-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | YD000070 | Yard | 711-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | YD000070 | Yard | 711-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | YD000070 | Yard | 711-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.5 | psi |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Amps C Ø | 100.0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Amps B Ø | 100.0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Amps A Ø | 100.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Patrol Inspection | Air Tank Bleed (> 40°F)? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Patrol Inspection | Air Pressure OK? | y | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Patrol Inspection | Air Leaks | None | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Patrol Inspection | Air Compressor Belt Condition | Good | |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0726 | BreakerOil | P-1382-B | OCB Readings | 9 Months Operations OCB New | 0 | |
| 1/9/2023 9:26 | Distribution | Gilligan Quarterly Inspection | LB0388 | BreakerAirMagnetic | GI-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | BAT001653 | Battery | 616-Battery Bank | Battery Patrol Inspection | General Comments | ok | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | BAT001653 | Battery | 616-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.5 | VDC |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | BAT001653 | Battery | 616-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.5 | VDC |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | BAT001653 | Battery | 616-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | SWG000198 | Switchgear | EW-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/9/2023 10:04 | Distribution | Providence East Quarterly Inspection | BAT001653 | Battery | 616-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | YD000070 | Yard | 711-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | LTCMechanism | 196-5 | LTC Counter Readings | LTC As Left Counter | 46129 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | YD000070 | Yard | 711-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | YD000070 | Yard | 711-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | FE000069 | Fence | 711-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Readings | General Comments | | |
| 1/9/2023 9:39 | Distribution | Providence Quarterly Inspection | 0952 | NonLTC | 453-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | LTCMechanism | 196-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | LTCMechanism | 196-5 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | YD000070 | Yard | 711-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | LTCMechanism | 196-5 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | LTCMechanism | 196-5 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | 9 Month Operations | 4 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Readings | Oil Temp Present | 52 | °C |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/11/2023 13:06 | Distribution | Grady Quarterly Inspection | BK001909 | BreakerVacuum | GR-1124 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Current Tap Position | 2R | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 9:12 | Distribution | Liberty Quarterly Inspection | R1130 | Regulator | 765-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/9/2023 12:00 | Distribution | Robbins Quarterly Inspection | ST000075 | Structure | 841-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/9/2023 12:32 | Distribution | Highsplint Quarterly Inspection | YD000070 | Yard | 711-Yard | Yard Patrol Inspection | General Comments | | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 8:46 | Distribution | Barnhill Quarterly Inspection | C0345 | NonLTC | 851-1 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | LTCMechanism | 196-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | B0355 | LTCMechanism | 196-5 | LTC Counter Readings | LTC Operations Since Last Insp | 373 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCC000723 | LTCControl | 196-6 | LTC Control Insp | All Connections OK? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 8:55 | Distribution | Eastwood West Quarterly Inspection | LT0301 | WithLTC | EW-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 15:08 | Distribution | Lansdowne Quarterly Inspection | BB0466 | BreakerVacuum | 060-0033 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | LTCC000723 | LTCControl | 196-6 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000585 | BreakerVacuum | 196-0178 | VCB Readings | Switching Operations | 2 | |
| 1/9/2023 10:34 | Distribution | Barlow Quarterly Inspection | C0449 | WithLTC | 195-5 | LTC Transformer Readings | Oil Temp Max | 59 | °C |
| 1/11/2023 15:04 | Distribution | Paddys Run Quarterly Inspection | LB0772 | BreakerOil | P-SEC REA TIE 1-B | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 13:22 | Distribution | American Avenue Quarterly Inspection | BK000587 | BreakerVacuum | 196-BT5-6 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | BCH000845 | Charger | Retired Distribution | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | BCH000845 | Charger | Retired Distribution | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | BCH000845 | Charger | Retired Distribution | Battery Charger Patrol Insp | General Comments | | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | General Comments | | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Regulator As Left Counter | 428 | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0767 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Regulator As Left Counter | 25380 | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Min Tap Position | 4L | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Max Tap Position | 9R | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | General Comments | | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0769 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | General Comments | | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Regulator As Left Counter | 115087 | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | R0788 | Regulator | 912-Offline-Distribution | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | X0079 | RecloserHydraulic | 912-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Amps C Ø | 44.0 | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | X0079 | RecloserHydraulic | 912-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | X0079 | RecloserHydraulic | 912-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | X0079 | RecloserHydraulic | 912-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | X0079 | RecloserHydraulic | 912-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | X0079 | RecloserHydraulic | 912-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | X0079 | RecloserHydraulic | 912-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | X0079 | RecloserHydraulic | 912-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Operations Counter | 524 | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | X0079 | RecloserHydraulic | 912-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | X0079 | RecloserHydraulic | 912-Offline-Distribution | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | X0079 | RecloserHydraulic | 912-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | X0079 | RecloserHydraulic | 912-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Amps A Ø | 35.0 | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | X0079 | RecloserHydraulic | 912-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Amps B Ø | 43.0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Operations Counter | 188 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Amps B Ø | 220.0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Amps C Ø | 170.0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Amps A Ø | 142.0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | X0124 | RecloserElectronic | 920-Offline-Distribution | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LTCC000117 | LTCControl | Retired Distribution | LTC Control Insp | All Connections OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LTCC000117 | LTCControl | Retired Distribution | LTC Control Insp | Follow-up Action Required? | n | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LTCC000117 | LTCControl | Retired Distribution | LTC Control Insp | General Comments | | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | General Comments | | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | All Connections OK? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | Negative DC Ground | 69.0 | VDC |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | Positive DC Ground | 65.0 | VDC |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | BAT000453 | Battery | Retired Distribution | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Readings | General Comments | | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | General Comments | | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Counter Readings | LTC As Left Counter | 38509 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Readings | LTC Totalizer Reading | 3578.88 | kw |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Amps C Ø | 80.0 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Readings | General Comments | | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.1184 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Patrol Inspection | General Comments | | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Readings | LTC Totalizer Reading | 3496.32 | kw |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | General Comments | | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Operations Counter AL | 536 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Operations Counter AF | 536 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Amps B Ø | 10.0 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Amps C Ø | 10.0 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | LTCC000314 | LTCControl | 629-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | LTCC000314 | LTCControl | 629-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | LTCC000314 | LTCControl | 629-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | LTCC000314 | LTCControl | 629-1 | LTC Control Insp | LTC Output Voltage Level | 0.0 | VAC |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | LTCC000314 | LTCControl | 629-1 | LTC Control Insp | LTC Operation Checked? | n | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | LTCC000314 | LTCControl | 629-1 | LTC Control Insp | General Comments | LTC has no station supply open per mine inspector | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | LTCC000314 | LTCControl | 629-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | General Comments | | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Patrol Inspection | General Comments | | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 42263 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.1 | volts |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | LTCC000314 | LTCControl | 629-1 | LTC Control Insp | All Connections OK? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | General Comments | | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | LTCC000849 | LTCControl | 369-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | LTCC000314 | LTCControl | 629-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | LTCC000849 | LTCControl | 369-1 | LTC Control Insp | VRR Base Voltage AF | 121.0 | VAC |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | LTCC000849 | LTCControl | 369-1 | LTC Control Insp | VRR Base Voltage AL | 121.0 | VAC |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | LTCC000849 | LTCControl | 369-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | 9 Month Operations | 1 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | General Comments | | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | General Comments | Broken porcelain on middle phase fuse holder. Xfmr fuses are starting to fray. | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | n | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Amps A Ø | 24.0 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Unknown Operations | 0 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Switching Operations | 0 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Operations This Read AM | 0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Readings | Oil Temp Max | 35 | °C |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 8553.60 | kw |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Counter Readings | LTC Operations Since Last Insp | 339 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Readings | General Comments | | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1524 | Regulator | 775-1 B | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | ST000265 | Structure | 827-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | General Comments | | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.4568 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | LTCC000849 | LTCControl | 369-1 | LTC Control Insp | LTC Output Voltage Level | 121.1 | VAC |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | General Comments | | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | ST000027 | Structure | 656-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.1880 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Readings | Winding Temp Present | 30 | °C |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Readings | Winding Temp Max | 55 | °C |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Readings | Top Oil Temperature Present | 30 | °C |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Readings | Top Oil Temperature Max | 40 | °C |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KT0037 | NonLTC | 803-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BAT001654 | Battery | 426-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BAT001654 | Battery | 426-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 45 | °F |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BAT001654 | Battery | 426-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BAT001654 | Battery | 426-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BAT001654 | Battery | 426-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BAT001654 | Battery | 426-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BAT001654 | Battery | 426-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BAT001654 | Battery | 426-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BAT001654 | Battery | 426-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BAT001654 | Battery | 426-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.5 | VDC |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BAT001654 | Battery | 426-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.5 | VDC |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BAT001654 | Battery | 426-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BAT001654 | Battery | 426-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | n | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | General Comments | | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | LTCC000688 | LTCControl | 535-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | LTCC000688 | LTCControl | 535-2 | LTC Control Insp | All Connections OK? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 122602 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | LTCC000687 | LTCControl | 535-1 | LTC Control Insp | VRR Time Delay | 45 | Seconds |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | LTCC000687 | LTCControl | 535-1 | LTC Control Insp | VRR Base Voltage AL | 113.5 | VAC |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | LTCC000687 | LTCControl | 535-1 | LTC Control Insp | VRR Base Voltage AF | 113.5 | VAC |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | LTCC000687 | LTCControl | 535-1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | LTCC000687 | LTCControl | 535-1 | LTC Control Insp | LTC Output Voltage Level | 113.7 | VAC |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | LTCC000687 | LTCControl | 535-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | LTCC000687 | LTCControl | 535-1 | LTC Control Insp | General Comments | | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | LTCC000687 | LTCControl | 535-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | LTCC000687 | LTCControl | 535-1 | LTC Control Insp | All Connections OK? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1091 | Regulator | 419-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 12599 | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | General Comments | | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Current Tap Position | 2R | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Readings | Totalizer Meter Reading | .5922 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 70147 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Readings | Oil Temp Present | 28 | °C |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Readings | Oil Temp Max | 56 | °C |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 710.64 | kw |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Readings | General Comments | | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | LTCC000688 | LTCControl | 535-2 | LTC Control Insp | VRR Base Voltage AL | 113.5 | VAC |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | LTCC000688 | LTCControl | 535-2 | LTC Control Insp | VRR Base Voltage AF | 113.5 | VAC |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | LTCC000688 | LTCControl | 535-2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | LTCC000688 | LTCControl | 535-2 | LTC Control Insp | LTC Output Voltage Level | 113.9 | VAC |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | LTCC000688 | LTCControl | 535-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | LTCC000688 | LTCControl | 535-2 | LTC Control Insp | General Comments | | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | General Comments | | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Readings | Oil Temp Present | 26 | °C |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | BAT001403 | Battery | 574-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | BAT001403 | Battery | 574-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | BAT001403 | Battery | 574-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 28.1 | VDC |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | BAT001403 | Battery | 574-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 29.4 | VDC |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | BAT001403 | Battery | 574-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | BAT001403 | Battery | 574-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | BAT001403 | Battery | 574-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | BAT001403 | Battery | 574-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | BAT001403 | Battery | 574-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | BAT001403 | Battery | 574-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | BAT001403 | Battery | 574-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | BAT001403 | Battery | 574-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 55 | °F |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | BAT001403 | Battery | 574-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | Ambient Temp | 40 | °F |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | General Comments | | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | YD000263 | Yard | 574-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | General Comments | | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Amps A Ø | 90.0 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | 9 Months Operations | 0 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | YD000261 | Yard | 426-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | YD000261 | Yard | 426-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | YD000261 | Yard | 426-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | YD000261 | Yard | 426-Yard | Yard Patrol Inspection | General Comments | Back left corner washout under fence | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | YD000261 | Yard | 426-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | YD000261 | Yard | 426-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | n | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | YD000261 | Yard | 426-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | YD000261 | Yard | 426-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | YD000261 | Yard | 426-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | YD000261 | Yard | 426-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | YD000261 | Yard | 426-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | YD000261 | Yard | 426-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | YD000261 | Yard | 426-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | YD000261 | Yard | 426-Yard | Yard Patrol Inspection | Ambient Temp | 44 | °F |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0138 | NonLTC | 426-2 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Readings | Totalizer Meter Reading | .9270 | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Readings | Oil Temp Present | 21 | °C |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Readings | Oil Temp Max | 21 | °C |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Readings | LTC Totalizer Reading | 8899.20 | kw |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Readings | General Comments | | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | General Comments | | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | FE000261 | Fence | 574-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Readings | General Comments | | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0137 | NonLTC | 426-2 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | BAT001406 | Battery | 822-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | BAT001406 | Battery | 822-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | BAT001406 | Battery | 822-Battery Bank | Battery Patrol Inspection | Positive DC Ground | .2 | VDC |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | BAT001406 | Battery | 822-Battery Bank | Battery Patrol Inspection | Negative DC Ground | .2 | VDC |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | BAT001406 | Battery | 822-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | BAT001406 | Battery | 822-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | BAT001406 | Battery | 822-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | BAT001406 | Battery | 822-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | BAT001406 | Battery | 822-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | BAT001406 | Battery | 822-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | BAT001406 | Battery | 822-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | BAT001406 | Battery | 822-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | BAT001406 | Battery | 822-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | WithLTC | 656-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Operations Counter AF | 171 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Operations Counter AL | 172 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Operations This Read Vac | 1 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Switching Operations | 1 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | Ambient Temp | 37 | °F |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Amps B Ø | 100.0 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Operations Counter | 26 | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | General Comments | 26.3/24.3 | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Amps C Ø | 41.0 | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Amps B Ø | 48.0 | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0237 | RecloserElectronic | 656-0468 | Recloser Electronic Patrol Inspection | Amps A Ø | 49.0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | YD000287 | Yard | 677-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Readings | Totalizer Meter Reading | .2536 | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Readings | Oil Temp Max | 90 | °C |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 155.00 | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 170.00 | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 608.64 | kw |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Readings | General Comments | | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | B0074 | NonLTC | 637-1 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | WithLTC | 438-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Counter Readings | LTC As Found Counter | 38504 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Mechanism Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | LTCMechanism | 677-2 | LTC Counter Readings | General Comments | | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 100.00 | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 107.50 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 200 | psi |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Readings | General Comments | | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | YD000253 | Yard | 438-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | General Comments | | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | BCH001557 | Charger | 842-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | BCH001557 | Charger | 842-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | BCH001557 | Charger | 842-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | BCH001557 | Charger | 842-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | BCH001557 | Charger | 842-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .8 | amps |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | BCH001557 | Charger | 842-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | BCH001557 | Charger | 842-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | BCH001557 | Charger | 842-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.700 | millivolts |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Readings | General Comments | | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | BCH001146 | Charger | 191-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | BCH001146 | Charger | 191-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | BCH001146 | Charger | 191-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | BCH001146 | Charger | 191-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 134.1 | VDC |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | BCH001146 | Charger | 191-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 134.1 | VDC |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | T0157 | NonLTC | 191-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | Ambient Temp | 32 | °F |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BK000750 | BreakerVacuum | 775-2108 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | FE000250 | Fence | 438-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | LTCC000689 | LTCControl | 535-3 | LTC Control Insp | VRR Time Delay | 45 | Seconds |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | LTCC000689 | LTCControl | 535-3 | LTC Control Insp | VRR Base Voltage AL | 113.5 | VAC |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | LTCC000689 | LTCControl | 535-3 | LTC Control Insp | VRR Base Voltage AF | 1135.0 | VAC |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | LTCC000689 | LTCControl | 535-3 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | LTCC000689 | LTCControl | 535-3 | LTC Control Insp | LTC Output Voltage Level | 114.0 | VAC |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | LTCC000689 | LTCControl | 535-3 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | LTCC000689 | LTCControl | 535-3 | LTC Control Insp | General Comments | | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | LTCC000689 | LTCControl | 535-3 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | LTCC000689 | LTCControl | 535-3 | LTC Control Insp | All Connections OK? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | WithLTC | 401-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | FE000614 | Fence | DU-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | General Comments | | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Water Spigots OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1447 | Regulator | 822-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | YD000543 | Yard | 775-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0569 | Regulator | 353-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | LTCC000688 | LTCControl | 535-2 | LTC Control Insp | VRR Time Delay | 45 | Seconds |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | ST000547 | Structure | 775-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000070 | Switchgear | FC-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | General Comments | | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | FE000259 | Fence | 426-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 284264 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1222 | Regulator | 426-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | General Comments | | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | General Comments | | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | FE000658 | Fence | DX-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Ambient Temp | 36 | °F |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | YD000663 | Yard | DX-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | ST000268 | Structure | 426-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | W0139 | NonLTC | 426-2 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | FE000032 | Fence | 656-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | YD000324 | Yard | 637-Yard | Yard Patrol Inspection | Ambient Temp | 34 | °F |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 58 | °C |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 22 | °C |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | YD000620 | Yard | EI-Yard | Yard Patrol Inspection | Ambient Temp | 36 | °F |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | General Comments | Washout just inside of gate | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .3 | psi |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Amps C Ø | 148.0 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Amps B Ø | 140.0 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Amps A Ø | 152.0 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | 9 Month Operations | 0 | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ANN000087 | Annunciator | DX-Annunciator Panel | Annunciator Patrol Inspection | General Comments | | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ANN000087 | Annunciator | DX-Annunciator Panel | Annunciator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ANN000087 | Annunciator | DX-Annunciator Panel | Annunciator Patrol Inspection | ESOC Received Alarm Test? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | BCH001411 | Charger | 369-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.200 | millivolts |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | BCH001411 | Charger | 369-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | BCH001411 | Charger | 369-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | BCH001411 | Charger | 369-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .2 | amps |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | BCH001411 | Charger | 369-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | BCH001411 | Charger | 369-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | BCH001411 | Charger | 369-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | YD000324 | Yard | 637-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | YD000324 | Yard | 637-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | BCH001411 | Charger | 369-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ANN000087 | Annunciator | DX-Annunciator Panel | Annunciator Patrol Inspection | Control House Alarm Audible? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ANN000087 | Annunciator | DX-Annunciator Panel | Annunciator Patrol Inspection | All Lights Functioning? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Readings | 9 Month Operations GCB New | 1 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Ambient Temperature | 38 | °F |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Readings | Fault Operations | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 199 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Fault Adjusted Amps A Phase V | 4.44 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Fault Operations A Ø | 1 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Readings | Num Operations Last 9 Months | 1 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Readings | Operations Counter AF | 85 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Readings | Operations Counter AL | 85 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Readings | Operations This Read SF6 | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | SF6 Compressor Belt Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | SF6 Pressure | 63 | psi |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | YD000620 | Yard | EI-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | YD000620 | Yard | EI-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | YD000620 | Yard | EI-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | X0252 | RecloserHydraulic | 419-0557 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Readings | Switching Operations | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Readings | Unknown Operations | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | n | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | YD000205 | Yard | 535-Yard | Yard Patrol Inspection | Ambient Temp | 38 | °F |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | YD000117 | Yard | 691-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | YD000117 | Yard | 691-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | General Comments | | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | WithLTC | FC-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Readings | General Comments | | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | General Comments | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK001133 | BreakerSF6 | 535-628 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 262 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 23.2 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 23.4 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 18.4 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | WX0518 | RecloserHydraulic | 426-1513 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 321 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | YD000324 | Yard | 637-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Operations Counter AF | 168 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | YD000117 | Yard | 691-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | YD000117 | Yard | 691-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | YD000117 | Yard | 691-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | YD000117 | Yard | 691-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | YD000117 | Yard | 691-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | YD000117 | Yard | 691-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | YD000117 | Yard | 691-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | YD000117 | Yard | 691-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | YD000117 | Yard | 691-Yard | Yard Patrol Inspection | General Comments | | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | YD000117 | Yard | 691-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Amps C Ø | 102.0 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Amps B Ø | 118.0 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Readings | Oil Temp Present | 26 | °C |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Readings | LTC Totalizer Reading | 4129.92 | kw |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | General Comments | | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Switching Operations | 0 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Operations This Read Vac | 0 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Operations Counter AL | 168 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Readings | General Comments | | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | YD000324 | Yard | 637-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | YD000324 | Yard | 637-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | YD000324 | Yard | 637-Yard | Yard Patrol Inspection | General Comments | | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | YD000324 | Yard | 637-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | YD000324 | Yard | 637-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | YD000324 | Yard | 637-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | YD000324 | Yard | 637-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | YD000324 | Yard | 637-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | LTCC000824 | LTCControl | 691-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | LTCC000824 | LTCControl | 691-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | LTCC000824 | LTCControl | 691-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | LTCC000824 | LTCControl | 691-1 | LTC Control Insp | LTC Output Voltage Level | 124.8 | VAC |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | LTCC000824 | LTCControl | 691-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | LTCC000824 | LTCControl | 691-1 | LTC Control Insp | General Comments | | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | LTCC000824 | LTCControl | 691-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | LTCC000824 | LTCControl | 691-1 | LTC Control Insp | All Connections OK? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 20228 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | General Comments | | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Patrol Inspection | General Comments | | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001332 | BreakerVacuum | 691-0459 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 133945 | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 100.00 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | ST000151 | Structure | 425-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | RG000133 | Regulator | 803-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 45 | °F |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | n | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | General Comments | No fuses. Has xfmr breaker. | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Switching Operations | 0 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Operations This Read Vac | 7 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Operations Counter AL | 181 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Operations Counter AF | 181 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | General Comments | | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Patrol Inspection | General Comments | | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | General Comments | | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 73372 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 120.8 | volts |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Max Tap Position | 4L | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | General Comments | | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | Ambient Temp | 48 | °F |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Counter Readings | LTC Operations Since Last Insp | 0 | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Counter Readings | LTC Min Tap Position | 16L | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Counter Readings | LTC As Left Counter | 407686 | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Counter Readings | LTC As Found Counter | 407686 | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Counter Readings | General Comments | LTC OFF | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Fault Operations B Ø | 3 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Fault Operations A Ø | 4 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Fault Adjusted Amps B Phase V | 26.28 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Fault Adjusted Amps A Phase V | 35.05 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | BCH001304 | Charger | 677-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | FE000207 | Fence | 535-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Amps C Ø | 84.0 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Amps B Ø | 95.0 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Amps A Ø | 101.0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | BCH001304 | Charger | 677-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | BCH001304 | Charger | 677-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | BCH001304 | Charger | 677-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.0 | amps |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | BCH001304 | Charger | 677-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | 9 Month Operations | 7 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | BCH001304 | Charger | 677-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | BCH001304 | Charger | 677-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | BCH001304 | Charger | 677-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | ST000171 | Structure | 191-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | General Comments | | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | General Comments | | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 32 | °F |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BK001331 | BreakerVacuum | 691-0458 | VCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BAT001112 | Battery | 775-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Operations Counter AL | 365 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Operations This Read Vac | 0 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Switching Operations | 0 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | Ambient Temp | 38 | °F |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | FE000854 | Fence | 677-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | LTCC000979 | LTCControl | 574-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | LTCC000979 | LTCControl | 574-1 | LTC Control Insp | All Connections OK? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | X0252 | RecloserHydraulic | 419-0557 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | X0252 | RecloserHydraulic | 419-0557 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | X0252 | RecloserHydraulic | 419-0557 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | X0252 | RecloserHydraulic | 419-0557 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | X0252 | RecloserHydraulic | 419-0557 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | X0252 | RecloserHydraulic | 419-0557 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | X0252 | RecloserHydraulic | 419-0557 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | BAT001380 | Battery | 677-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | X0252 | RecloserHydraulic | 419-0557 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 30.0 | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | X0252 | RecloserHydraulic | 419-0557 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | General Comments | | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | General Comments | | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | General Comments | | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | General Comments | | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | General Comments | AG on 12-20-22/TC | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Maintenance Operations | 1 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Operations Counter AF | 482 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Operations Counter AL | 483 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Operations This Read Vac | 2 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Switching Operations | 0 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | X0252 | RecloserHydraulic | 419-0557 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | X0252 | RecloserHydraulic | 419-0557 | Recloser Hydraulic Patrol Inspection | Operations Counter | 295 | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | X0252 | RecloserHydraulic | 419-0557 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | YD000620 | Yard | EI-Yard | Yard Patrol Inspection | General Comments | | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Operations Counter AF | 365 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | LTCC000979 | LTCControl | 574-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | LTCC000979 | LTCControl | 574-1 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | LTCC000979 | LTCControl | 574-1 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | LTCC000979 | LTCControl | 574-1 | LTC Control Insp | LTC Output Voltage Level | 124.9 | VAC |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | LTCC000979 | LTCControl | 574-1 | LTC Control Insp | LTC Operation Checked? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | LTCC000979 | LTCControl | 574-1 | LTC Control Insp | General Comments | | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | ST000033 | Structure | 629-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | General Comments | | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | General Comments | trees growing over fence | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | YD000620 | Yard | EI-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | YD000620 | Yard | EI-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | YD000164 | Yard | 191-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | YD000620 | Yard | EI-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | YD000620 | Yard | EI-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | General Comments | fence is connected to neighbor fence | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Current Tap Position | 9L | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1040 | Regulator | 677-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Counter Readings | Reset Tap Drag Hands | Unable to Reset | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | LTCMechanism | 629-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | YD000147 | Yard | 425-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | YD000620 | Yard | EI-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 69947 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 120.7 | volts |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Max Tap Position | 6L | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | FE000116 | Fence | 691-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1042 | Regulator | 677-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.1 | volts |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 126336 | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1319 | Regulator | 328-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | CH000070 | ControlHouse | 535-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .4878 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1170.72 | kw |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Readings | General Comments | | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 853360 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BCH001572 | Charger | 426-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.000 | millivolts |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BCH001572 | Charger | 426-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BCH001572 | Charger | 426-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BCH001572 | Charger | 426-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .4 | amps |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BCH001572 | Charger | 426-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BCH001572 | Charger | 426-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BCH001572 | Charger | 426-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 125.3 | volts |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 5547 | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | General Comments | | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | CH000059 | ControlHouse | 191-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 35377 | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0884 | Regulator | 353-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | C0275 | NonLTC | 822-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | YD000101 | Yard | 842-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | YD000101 | Yard | 842-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | YD000101 | Yard | 842-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | YD000101 | Yard | 842-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | YD000101 | Yard | 842-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | YD000101 | Yard | 842-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | YD000101 | Yard | 842-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | YD000101 | Yard | 842-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | YD000101 | Yard | 842-Yard | Yard Patrol Inspection | General Comments | | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | YD000101 | Yard | 842-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | YD000101 | Yard | 842-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | YD000101 | Yard | 842-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | General Comments | | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BCH001572 | Charger | 426-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Counter Readings | LTC Operations Since Last Insp | 346 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 110187 | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | General Comments | | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | FE000167 | Fence | 191-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Counter Readings | LTC Max Tap Position | 10R | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Counter Readings | LTC Current Tap Position | 4R | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Counter Readings | LTC As Left Counter | 41489 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Counter Readings | LTC As Found Counter | 41480 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Counter Readings | General Comments | | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | LTCMechanism | 535-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0085 | Regulator | 803-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | General Comments | Needs new nitro gauge. | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 529.20 | kw |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Readings | Oil Temp Max | 48 | °C |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Readings | Oil Temp Max | 20 | °C |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Readings | Totalizer Meter Reading | .4410 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | 9 Months Operations | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | General Comments | | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | BAT001477 | Battery | 369-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | BAT001477 | Battery | 369-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | BAT001477 | Battery | 369-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.2 | VDC |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | BAT001477 | Battery | 369-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.4 | VDC |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | BAT001477 | Battery | 369-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | BAT001477 | Battery | 369-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | BAT001477 | Battery | 369-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | General Comments | | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | YD000659 | Yard | FC-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1764.00 | kw |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Amps C Ø | 115.0 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Amps B Ø | 40.0 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Amps A Ø | 15.0 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0280 | BreakerAirMagnetic | EI-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | YD000136 | Yard | 401-Yard | Yard Patrol Inspection | Ambient Temp | 49 | °F |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0205 | NonLTC | 419-1 A | NonLTC Transformer Readings | General Comments | | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Counter Readings | General Comments | | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Counter Readings | LTC As Found Counter | 14784 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | CH000025 | ControlHouse | 842-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Min Tap Position | 10L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 125.5 | volts |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 43196 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Counter Readings | LTC As Left Counter | 14791 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Counter Readings | LTC Max Tap Position | 5R | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1537 | Regulator | 775-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Counter Readings | LTC Operations Since Last Insp | 600 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | LTCMechanism | 691-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | FE000654 | Fence | FC-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | S0067 | NonLTC | 775-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .7350 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | BAT001477 | Battery | 369-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | BAT001477 | Battery | 369-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | BAT001477 | Battery | 369-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | BAT001477 | Battery | 369-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | BAT001477 | Battery | 369-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | BAT001477 | Battery | 369-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | LTCC000849 | LTCControl | 369-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | LTCC000849 | LTCControl | 369-1 | LTC Control Insp | General Comments | | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | LTCC000849 | LTCControl | 369-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | LTCC000849 | LTCControl | 369-1 | LTC Control Insp | All Connections OK? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | R1535 | Regulator | 775-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | General Comments | | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 35 | °C |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 45 | °C |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 40 | °C |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 50 | °C |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 35 | °C |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 45 | °C |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 55.00 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Readings | Oil Temp Max | 0 | °C |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Readings | Oil Temp Present | 0 | °C |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | FE000113 | Fence | 353-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Patrol Inspection | General Comments | | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Readings | Totalizer Meter Reading | .6235 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | 9 Month Operations | 7 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | General Comments | | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Operations Counter AF | 505 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Operations Counter AL | 505 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Operations This Read AM | 0 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Switching Operations | 0 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Unknown Operations | 0 | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Counter Readings | LTC Operations Since Last Insp | 915 | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Counter Readings | LTC As Left Counter | 14302 | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Counter Readings | LTC As Found Counter | 14929 | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Counter Readings | General Comments | | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Readings | Winding Temp Max | 48 | °C |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Readings | Winding Temp Present | 35 | °C |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1089 | Regulator | 419-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.5 | psi |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | 9 Month Operations | 2 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | TR- needs nitrogen | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0089 | BreakerVacuum | 842-0455 | VCB Readings | Amps A Ø | 81.0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | WithLTC | DX-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 95082 | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1318 | Regulator | 328-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Amps A Ø | 153.0 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Amps B Ø | 148.0 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Readings | Amps C Ø | 165.0 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | WB0151 | BreakerVacuum | 574-1710 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | needs nitro | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 10.00 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Readings | General Comments | | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Readings | Oil Temp Max | 70 | °C |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.7208 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | WithLTC | 842-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Readings | Oil Temp Present | 48 | °C |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | S0047 | LTCMechanism | 656-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | General Comments | | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Unreadable | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Readings | General Comments | | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0279 | BreakerAirMagnetic | EI-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | ST000121 | Structure | 691-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | R1317 | Regulator | 328-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | General Comments | | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | FE000138 | Fence | 401-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | General Comments | | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | General Comments | | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | ST000260 | Structure | 438-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | ST000107 | Structure | 842-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | General Comments | | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 40 | °C |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 110.00 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 24 | °C |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Readings | LV Winding Temp Present | 60 | °C |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | WithLTC | DU-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | WithLTC | 535-3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | YD000258 | Yard | 827-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | WithLTC | FC-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | FE000255 | Fence | 827-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | WithLTC | 159-5 | LTC Transformer Readings | LTC Totalizer Reading | 1995.20 | kw |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 15 | °C |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | YD000114 | Yard | 353-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 47 | °C |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .8 | psi |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | FE000899 | Fence | 762-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | WithLTC | EI-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Readings | Totalizer Meter Reading | 1.2942 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Readings | Oil Temp Present | 38 | °C |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Readings | LTC Totalizer Reading | 6212.16 | kw |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | General Comments | added nitrogen | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Readings | General Comments | | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Current Tap Position | 3R | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Amps C Ø | 5.0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Amps B Ø | 30.0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Amps A Ø | 5.0 | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | 9 Month Operations | 1 | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | BAT001608 | Battery | 803-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | BAT001608 | Battery | 803-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | BAT001608 | Battery | 803-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | BAT001608 | Battery | 803-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | BAT001608 | Battery | 803-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | BAT001608 | Battery | 803-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | BAT001608 | Battery | 803-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | BAT001608 | Battery | 803-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | BAT001608 | Battery | 803-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.5 | VDC |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | BAT001608 | Battery | 803-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.5 | VDC |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | BAT001608 | Battery | 803-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Amps A Ø | 300.0 | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Amps B Ø | 285.0 | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Amps C Ø | 310.0 | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | BAT001608 | Battery | 803-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | 9 Months Operations | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 65407 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 62268 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1262 | Regulator | 425-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 69090 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1263 | Regulator | 425-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | BCH001535 | Charger | 803-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .870 | millivolts |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | BCH001535 | Charger | 803-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | BCH001535 | Charger | 803-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | BCH001535 | Charger | 803-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | BCH001535 | Charger | 803-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | BCH001535 | Charger | 803-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | BCH001535 | Charger | 803-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | BCH001535 | Charger | 803-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Trash Emptied? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | General Comments | | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Broom on Site? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | CH000233 | ControlHouse | 328-Contol House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | General Comments | | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | FE000015 | Fence | 369-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | YD000008 | Yard | 629-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | YD000008 | Yard | 629-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | YD000008 | Yard | 629-Yard | Yard Patrol Inspection | Clear of Obstacles? | n | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BCH001334 | Charger | 691-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BCH001334 | Charger | 691-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BCH001334 | Charger | 691-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | YD000008 | Yard | 629-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | YD000008 | Yard | 629-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | YD000008 | Yard | 629-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BCH001334 | Charger | 691-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.1 | amps |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BCH001334 | Charger | 691-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BCH001334 | Charger | 691-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | WithLTC | 369-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | General Comments | New controls | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Min Tap Position | 2L | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 125.0 | volts |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 390 | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1115 | Regulator | 762-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | General Comments | | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | General Comments | replaced counter | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Operations Counter AF | 30 | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Operations Counter AL | 30 | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Operations This Read Vac | 0 | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Switching Operations | 0 | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | WB0179 | BreakerVacuum | 159-1309 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 68.8 | VDC |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 65.4 | VDC |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BAT000445 | Battery | 535-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | SWG000006 | Switchgear | EI-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 878 | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | WX0333 | RecloserHydraulic | 827-1553 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | WX0333 | RecloserHydraulic | 827-1553 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | WX0333 | RecloserHydraulic | 827-1553 | Recloser Hydraulic Patrol Inspection | Operations Counter | 806 | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | WX0333 | RecloserHydraulic | 827-1553 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | WX0333 | RecloserHydraulic | 827-1553 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | WX0333 | RecloserHydraulic | 827-1553 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | WX0333 | RecloserHydraulic | 827-1553 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | WX0333 | RecloserHydraulic | 827-1553 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | WX0333 | RecloserHydraulic | 827-1553 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | WX0333 | RecloserHydraulic | 827-1553 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | WX0333 | RecloserHydraulic | 827-1553 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 5.0 | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | WX0333 | RecloserHydraulic | 827-1553 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 12.0 | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | WX0333 | RecloserHydraulic | 827-1553 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 10.0 | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Current Tap Position | 4R | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | General Comments | New controls | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | General Comments | Adjusted temperature on heater | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Operations Counter | 5 | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Min Tap Position | 1L | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 125.0 | volts |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 290 | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1114 | Regulator | 762-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 55 | °F |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | BAT001242 | Battery | 328-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | LTCC000935 | LTCControl | 677-2 | LTC Control Insp | All Connections OK? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | LTCC000935 | LTCControl | 677-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | LTCC000935 | LTCControl | 677-2 | LTC Control Insp | General Comments | | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 296316 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PF001303 | PowerFuse | EI-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Switching Operations | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Unknown Operations | 0 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PF001303 | PowerFuse | EI-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PF001303 | PowerFuse | EI-4KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Current Tap Position | 2R | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | General Comments | New controls | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Min Tap Position | 3L | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 276 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Exp/Missing Not Repl | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | R1113 | Regulator | 762-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | BAT001243 | Battery | 842-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Amps A Ø | 72.0 | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Amps B Ø | 40.0 | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Amps C Ø | 56.0 | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC901737 | RecloserElectronic | 762-0590 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 1220 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 804 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 17.0 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 19.4 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0420 | RecloserHydraulic | 425-1507 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 23.5 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Fault Operations B Ø | 3 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Fault Adjusted Amps B Phase V | 4.97 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Amps C Ø | 48.0 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Amps B Ø | 60.0 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Amps A Ø | 58.0 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | 9 Month Operations | 9 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 45 | °F |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | BAT001294 | Battery | FC-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BAT001358 | Battery | 438-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BAT001358 | Battery | 438-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BAT001358 | Battery | 438-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.9 | VDC |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BAT001358 | Battery | 438-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 28.1 | VDC |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BAT001358 | Battery | 438-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BAT001358 | Battery | 438-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BAT001358 | Battery | 438-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Switching Operations | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BAT001358 | Battery | 438-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BAT001358 | Battery | 438-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BAT001358 | Battery | 438-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BAT001358 | Battery | 438-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BAT001358 | Battery | 438-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BAT001358 | Battery | 438-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 45 | °F |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BAT001358 | Battery | 438-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Operations This Read Vac | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Operations Counter AL | 79 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Operations Counter AF | 79 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Amps B Ø | 140.0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Amps A Ø | 140.0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | General Comments | | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | General Comments | | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Readings | General Comments | | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -3.0 | psi |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 2707.20 | kw |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 1/6/2023 12:40 | Distribution | St Charles KU Quarterly Inspection | W0181 | NonLTC | 827-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .5640 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | LTCC000935 | LTCControl | 677-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | LTCC000935 | LTCControl | 677-2 | LTC Control Insp | LTC Output Voltage Level | 125.3 | VAC |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | LTCC000935 | LTCControl | 677-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | LTCC000935 | LTCControl | 677-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | LTCC000935 | LTCControl | 677-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Switching Operations | 0 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | R1261 | Regulator | 425-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | General Comments | There are no spare fuses. Bus needs wildlife discs. | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Operations This Read Vac | 4 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Operations Counter AL | 229 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Operations Counter AF | 229 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Maintenance Operations | 1 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | General Comments | 3 op - BG, 1 op - Trip Check | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | General Comments | | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BK000080 | BreakerVacuum | 401-1324 | VCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BCH000619 | Charger | 775-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BCH000619 | Charger | 775-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Amps C Ø | 67.0 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Amps B Ø | 71.0 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Amps A Ø | 56.0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Switching Operations | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Operations This Read Vac | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Operations Counter AL | 76 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Operations Counter AF | 76 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | General Comments | | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | General Comments | | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Amps C Ø | 110.0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Amps B Ø | 105.0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Amps A Ø | 102.0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | General Comments | | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | FE000230 | Fence | 822-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Fault Operations B Ø | 1 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Fault Adjusted Amps B Phase V | 11.18 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Amps C Ø | 198.0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Amps B Ø | 195.0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Amps A Ø | 190.0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | 9 Month Operations VCB New | 16 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | 9 Month Operations | 17 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BCH000619 | Charger | 775-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BCH000619 | Charger | 775-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BCH000619 | Charger | 775-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .7 | amps |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | BCH000619 | Charger | 775-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Amps C Ø | 100.0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Amps B Ø | 125.0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Amps A Ø | 130.0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | 9 Months Operations | 0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Operations Counter | 9 | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | KX0005 | RecloserElectronic | 775-2107 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 9:15 | Distribution | Crab Orchard Quarterly Inspection | FE000503 | Fence | 775-Fence | Fence Patrol Inspection | General Comments | | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | General Comments | Bus needs wildlife protection. | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Amps C Ø | 197.0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Amps B Ø | 219.0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Amps A Ø | 206.0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | 9 Month Operations | 1 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Switching Operations | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Operations This Read Vac | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Operations Counter AL | 72 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Operations Counter AF | 72 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | General Comments | | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | General Comments | | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Amps C Ø | 164.0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Amps B Ø | 160.0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Amps A Ø | 125.0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001902 | BreakerVacuum | DX-1223 | VCB Readings | 9 Month Operations | 1 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | YD000236 | Yard | 803-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | YD000236 | Yard | 803-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | General Comments | insulator skirts cracked | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | General Comments | Needs new pressure gauge | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001904 | BreakerVacuum | DX-1221 | VCB Readings | 9 Month Operations | 1 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Switching Operations | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Operations This Read Vac | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Operations Counter AL | 63 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Operations Counter AF | 63 | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Readings | General Comments | | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | C0204 | NonLTC | 419-1 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | General Comments | | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | General Comments | | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001903 | BreakerVacuum | DX-1222 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | ST000236 | Structure | 822-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | ST000243 | Structure | 803-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PF001300 | PowerFuse | DU-4KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | BCH001277 | Charger | 574-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | BCH001277 | Charger | 574-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | BCH001277 | Charger | 574-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .6 | amps |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | BCH001277 | Charger | 574-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 57.6 | VDC |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | BCH001277 | Charger | 574-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 57.6 | VDC |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | BCH001277 | Charger | 574-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.100 | millivolts |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | WX0177 | RecloserHydraulic | 822-1515 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | WX0177 | RecloserHydraulic | 822-1515 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | WX0177 | RecloserHydraulic | 822-1515 | Recloser Hydraulic Patrol Inspection | Operations Counter | 260 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | WX0177 | RecloserHydraulic | 822-1515 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | WX0177 | RecloserHydraulic | 822-1515 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | WX0177 | RecloserHydraulic | 822-1515 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | WX0177 | RecloserHydraulic | 822-1515 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | WX0177 | RecloserHydraulic | 822-1515 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | WX0177 | RecloserHydraulic | 822-1515 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | WX0177 | RecloserHydraulic | 822-1515 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | WX0177 | RecloserHydraulic | 822-1515 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 11.1 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | WX0177 | RecloserHydraulic | 822-1515 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 13.9 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | WX0177 | RecloserHydraulic | 822-1515 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 18.0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0174 | BreakerVacuum | 5351-0102 | VCB Readings | 9 Month Operations | 1 | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Amps A Ø | 66.0 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Amps B Ø | 48.0 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Amps C Ø | 52.0 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Readings | General Comments | | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 5277.60 | kw |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 56.67 | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Readings | Oil Temp Present | 27 | °C |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | S0018 | NonLTC | 328-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 2.1990 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | YD000008 | Yard | 629-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | YD000008 | Yard | 629-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | YD000008 | Yard | 629-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | YD000008 | Yard | 629-Yard | Yard Patrol Inspection | General Comments | Tree in road way. Large trucks can not pass | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | YD000008 | Yard | 629-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | YD000008 | Yard | 629-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | YD000008 | Yard | 629-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Counter Readings | LTC Operations Since Last Insp | 184 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Counter Readings | LTC As Left Counter | 3820 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Counter Readings | LTC As Found Counter | 3810 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Counter Readings | General Comments | | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | W0289 | LTCMechanism | 438-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Current Tap Position | 3R | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | General Comments | | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | FE000853 | Fence | 842-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | General Comments | lower arm will not reset | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Amps A Ø | 0.0 | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Amps B Ø | 0.0 | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Amps C Ø | 0.0 | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Operations Counter | 5 | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | RC000145 | RecloserElectronic | 762-0589 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 49127 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1446 | Regulator | 822-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PF001300 | PowerFuse | DU-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PF001300 | PowerFuse | DU-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Counter Readings | LTC Min Tap Position | 3L | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Counter Readings | LTC Max Tap Position | 16R | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Counter Readings | LTC Current Tap Position | 11R | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Counter Readings | LTC As Left Counter | 77233 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Counter Readings | LTC As Found Counter | 77224 | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Counter Readings | General Comments | | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Operations Counter AL | 47 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Operations Counter AF | 47 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | General Comments | | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Amps C Ø | 700.0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Amps B Ø | 660.0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Amps A Ø | 600.0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001906 | BreakerVacuum | DX-12KV TR 1 | VCB Readings | 9 Month Operations | 0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Unknown Operations | 0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Switching Operations | 0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Operations This Read AM | 0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Operations Counter AL | 591 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Operations Counter AF | 591 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | General Comments | | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Patrol Inspection | General Comments | | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0275 | BreakerAirMagnetic | DU-1 | AMCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Switching Operations | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Operations This Read Vac | 1 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Operations Counter AL | 75 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Operations Counter AF | 75 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Readings | General Comments | B phase ioc | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | BK001905 | BreakerVacuum | DX-1220 | VCB Patrol Inspection | General Comments | | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Counter Readings | General Comments | | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Counter Readings | LTC As Found Counter | 278097 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Counter Readings | LTC As Left Counter | 278107 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Counter Readings | LTC Current Tap Position | 5R | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Counter Readings | LTC Max Tap Position | 9R | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Counter Readings | LTC Operations Since Last Insp | 343 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | LTCMechanism | 535-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | General Comments | BCG/TC | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Operations Counter | 169 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0128 | RecloserElectronic | 574-1711 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 425820 | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.2 | volts |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | R0744 | Regulator | 353-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | YD000202 | Yard | 419-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | YD000202 | Yard | 419-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | YD000202 | Yard | 419-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | YD000202 | Yard | 419-Yard | Yard Patrol Inspection | General Comments | | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | YD000202 | Yard | 419-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | YD000202 | Yard | 419-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | YD000202 | Yard | 419-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | YD000202 | Yard | 419-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | YD000202 | Yard | 419-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | YD000202 | Yard | 419-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | YD000202 | Yard | 419-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | YD000202 | Yard | 419-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | YD000202 | Yard | 419-Yard | Yard Patrol Inspection | Ambient Temp | 37 | °F |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | General Comments | | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | FE000204 | Fence | 419-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Counter Readings | LTC Operations Since Last Insp | 135 | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | W0362 | LTCMechanism | 159-5 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Readings | Totalizer Meter Reading | .8520 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Readings | Oil Temp Present | 32 | °C |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Readings | Oil Temp Max | 38 | °C |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.5 | psi |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Readings | LTC Totalizer Reading | 8179.20 | kw |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Readings | General Comments | | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | BCH000120 | Charger | DU-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | General Comments | | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | BCH001166 | Charger | 328-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | BCH001166 | Charger | 328-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | BCH001166 | Charger | 328-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | BCH001166 | Charger | 328-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | BCH001166 | Charger | 328-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | BCH001166 | Charger | 328-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | BCH001166 | Charger | 328-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | BCH001166 | Charger | 328-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .700 | millivolts |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | General Comments | | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Counter Readings | General Comments | | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Counter Readings | General Comments | | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Counter Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Counter Readings | LTC As Found Counter | 71792 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Counter Readings | LTC As Left Counter | 71796 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Counter Readings | LTC Operations Since Last Insp | 1201 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | M0051 | LTCMechanism | 369-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | PF000100 | PowerFuse | DX-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | PF000100 | PowerFuse | DX-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Unknown Operations | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Switching Operations | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Operations This Read AM | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Operations Counter AL | 34896 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Operations Counter AF | 34896 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | General Comments | | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Patrol Inspection | General Comments | | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Amps C Ø | 240.0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Amps B Ø | 260.0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Amps A Ø | 80.0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | 9 Months Operations | 2 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0311 | BreakerAirMagnetic | FC-4 | AMCB Readings | 9 Month Ops New | 2 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Battery Bank Amps | .1 | AMPS |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Battery Bank Volts | 26.6 | VDC |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | BAT001430 | Battery | DU-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | WithLTC | 574-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 10.00 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | LTCC000232 | LTCControl | 159-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | LTCC000232 | LTCControl | 159-5 | LTC Control Insp | VRR Base Voltage AL | 115.0 | VAC |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | LTCC000232 | LTCControl | 159-5 | LTC Control Insp | VRR Base Voltage AF | 115.0 | VAC |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | LTCC000232 | LTCControl | 159-5 | LTC Control Insp | LTC Output Voltage Level | 114.3 | VAC |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | LTCC000232 | LTCControl | 159-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | LTCC000232 | LTCControl | 159-5 | LTC Control Insp | General Comments | | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | LTCC000232 | LTCControl | 159-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | LTCC000232 | LTCControl | 159-5 | LTC Control Insp | All Connections OK? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | LTCC000229 | LTCControl | 842-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | LTCC000229 | LTCControl | 842-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | LTCC000229 | LTCControl | 842-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | LTCC000229 | LTCControl | 842-1 | LTC Control Insp | LTC Output Voltage Level | 124.1 | VAC |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | LTCC000229 | LTCControl | 842-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | LTCC000229 | LTCControl | 842-1 | LTC Control Insp | General Comments | | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | LTCC000229 | LTCControl | 842-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | LTCC000229 | LTCControl | 842-1 | LTC Control Insp | All Connections OK? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 316092 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | MX0195 | RecloserHydraulic | 353-0672 | Recloser Hydraulic Patrol Inspection | Amps A Ø | .3 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | BCH000120 | Charger | DU-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.6 | VDC |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | General Comments | lower arm will not reset | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | BCH000120 | Charger | DU-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.6 | VDC |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | BCH000120 | Charger | DU-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | BCH000120 | Charger | DU-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | BCH000120 | Charger | DU-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | BCH000120 | Charger | DU-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | FE000070 | Fence | 629-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1224 | Regulator | 426-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | MX0195 | RecloserHydraulic | 353-0672 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | MX0195 | RecloserHydraulic | 353-0672 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | MX0195 | RecloserHydraulic | 353-0672 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | MX0195 | RecloserHydraulic | 353-0672 | Recloser Hydraulic Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | MX0195 | RecloserHydraulic | 353-0672 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Platform/Walkway/Railing OK? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | General Comments | | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | General Comments | Secondary of metering equipment needs to be rewired. | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | ST000330 | Structure | 637-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | General Comments | | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | MX0195 | RecloserHydraulic | 353-0672 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | MX0195 | RecloserHydraulic | 353-0672 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | MX0195 | RecloserHydraulic | 353-0672 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | MX0195 | RecloserHydraulic | 353-0672 | Recloser Hydraulic Patrol Inspection | Amps C Ø | .2 | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | MX0195 | RecloserHydraulic | 353-0672 | Recloser Hydraulic Patrol Inspection | Amps B Ø | .1 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | YD000229 | Yard | 822-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Operations This Read Vac | 1 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Operations Counter AL | 213 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Operations Counter AF | 212 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Maintenance Operations | 1 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | General Comments | TC | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | General Comments | | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Operations Counter AF | 254 | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Operations Counter AL | 254 | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Readings | Oil Temp Max | 62 | °C |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 135.00 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 145.00 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 2702.88 | kw |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | General Comments | H1 and H3 bushings are pretty badly broken | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Readings | General Comments | | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | MOD Motor Jaw Coupling | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | MOD Cabinet Internals Clean? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | MOD Cabinet Heater functional? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Interruptrs/Puffrs Visual OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | General Comments | | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | KX0140 | RecloserHydraulic | 637-0812 A | Recloser Hydraulic Patrol Inspection | Amps A Ø | 15.0 | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | KX0140 | RecloserHydraulic | 637-0812 A | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | KX0140 | RecloserHydraulic | 637-0812 A | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | KX0140 | RecloserHydraulic | 637-0812 A | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.3 | VDC |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.1 | VDC |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | BAT001056 | Battery | 691-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | 9 Month Operations | 7 | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Amps A Ø | 64.0 | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Amps B Ø | 72.0 | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Amps C Ø | 64.0 | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.1262 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | M0001 | NonLTC | 425-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | K0027 | BreakerVacuum | 328-0674 | VCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Switching Operations | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Switching Operations | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Operations This Read Vac | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Operations Counter AL | 94 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Operations Counter AF | 94 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | General Comments | | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | General Comments | | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 120.8 | volts |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 71014 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Readings | Totalizer Meter Reading | .7818 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | General Comments | | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Readings | LTC Totalizer Reading | 7505.28 | kw |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Readings | General Comments | | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | B0474 | WithLTC | 677-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | ST000641 | Structure | DX-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | KX0140 | RecloserHydraulic | 637-0812 A | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | KX0140 | RecloserHydraulic | 637-0812 A | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | KX0140 | RecloserHydraulic | 637-0812 A | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | KX0140 | RecloserHydraulic | 637-0812 A | Recloser Hydraulic Patrol Inspection | Operations Counter | 95 | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | KX0140 | RecloserHydraulic | 637-0812 A | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | KX0140 | RecloserHydraulic | 637-0812 A | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Amps C Ø | 390.0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Amps B Ø | 400.0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Amps A Ø | 390.0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | WB0173 | BreakerVacuum | 5351-0112 | VCB Readings | 9 Month Operations | 1 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Counter Readings | LTC Operations Since Last Insp | 759 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Counter Readings | LTC Max Tap Position | 7R | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Counter Readings | LTC As Left Counter | 259996 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | 0988 | LTCMechanism | 842-1 | LTC Counter Readings | LTC As Found Counter | 259989 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | 9 Month Operations | 1 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Max Tap Position | 4L | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Amps A Ø | 55.0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Amps B Ø | 54.0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Amps C Ø | 51.0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Amps C Ø | 57.0 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Amps B Ø | 54.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Amps A Ø | 47.0 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK001815 | BreakerVacuum | 438-1713 | VCB Readings | 9 Month Operations | 7 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | General Comments | | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | General Comments | | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Operations Counter AF | 339 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Operations Counter AL | 340 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Operations This Read Vac | 1 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Readings | Switching Operations | 1 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0145 | BreakerVacuum | 677-0588 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | YD000027 | Yard | 656-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | R1041 | Regulator | 677-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Amps A Ø | 30.0 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Amps B Ø | 50.0 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Amps C Ø | 50.0 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Patrol Inspection | General Comments | | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | General Comments | | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Operations Counter AF | 295 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Operations Counter AL | 295 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Operations This Read AM | 0 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Switching Operations | 0 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Unknown Operations | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | 9 Month Ops New | 1 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | 9 Months Operations | 1 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Amps A Ø | 130.0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Amps B Ø | 170.0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Amps C Ø | 195.0 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Readings | Totalizer Meter Reading | .8350 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 6000 | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Readings | Oil Temp Present | 33 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Readings | Oil Temp Max | 56 | °C |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Readings | LTC Totalizer Reading | 5010.00 | kw |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Readings | General Comments | | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Amps C Ø | 180.0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 110.00 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | 9 Month Operations | 1 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Amps A Ø | 60.0 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Amps B Ø | 58.0 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Amps C Ø | 59.0 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | General Comments | Breaker open | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Operations Counter | 0 | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | General Comments | | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Maintenance Operations | 1 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Operations Counter AF | 183 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Operations Counter AL | 184 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Operations This Read Vac | 1 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Switching Operations | 0 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | BK000905 | BreakerVacuum | 426-1511 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BAT001421 | Battery | 401-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BAT001421 | Battery | 401-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BAT001421 | Battery | 401-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BAT001421 | Battery | 401-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | 9 Month Ops New | 3 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | 9 Months Operations | 3 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | LB0278 | BreakerAirMagnetic | EI-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Readings | General Comments | Temp gauge is broke | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 569.88 | kw |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 28.33 | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Readings | Oil Temp Max | 75 | °C |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 600 | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .9498 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Readings | General Comments | winiding temp gauge is broken | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -1.5 | psi |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Readings | Winding Temp Max | 40 | °C |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Readings | Winding Temp Present | 37 | °C |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PF001305 | PowerFuse | FC-4KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PF001305 | PowerFuse | FC-4KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PF001305 | PowerFuse | FC-4KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Patrol Inspection | General Comments | | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | General Comments | | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Operations Counter AF | 409 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Operations Counter AL | 409 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Readings | Operations This Read AM | 0 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PF001304 | PowerFuse | FC-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PF001304 | PowerFuse | FC-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PF001304 | PowerFuse | FC-4KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | R1223 | Regulator | 426-1 B | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | M0091 | WithLTC | 691-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0308 | BreakerAirMagnetic | FC-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | CH000453 | ControlHouse | FC-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | CH000453 | ControlHouse | FC-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | CH000453 | ControlHouse | FC-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | CH000453 | ControlHouse | FC-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | CH000453 | ControlHouse | FC-Battery Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | Ambient Temp | 41 | °F |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | General Comments | | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | YD000015 | Yard | 328-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | CH000453 | ControlHouse | FC-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | C0523 | WithLTC | 535-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | CH000453 | ControlHouse | FC-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | CH000453 | ControlHouse | FC-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | CH000453 | ControlHouse | FC-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | ST000210 | Structure | 419-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | MX0471 | RecloserHydraulic | 629-0469 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | MX0471 | RecloserHydraulic | 629-0469 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | MX0471 | RecloserHydraulic | 629-0469 | Recloser Hydraulic Patrol Inspection | Operations Counter | 432 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | MX0471 | RecloserHydraulic | 629-0469 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | MX0471 | RecloserHydraulic | 629-0469 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | MX0471 | RecloserHydraulic | 629-0469 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | MX0471 | RecloserHydraulic | 629-0469 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | MX0471 | RecloserHydraulic | 629-0469 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | MX0471 | RecloserHydraulic | 629-0469 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | MX0471 | RecloserHydraulic | 629-0469 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | MX0471 | RecloserHydraulic | 629-0469 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | MX0471 | RecloserHydraulic | 629-0469 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0.0 | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | MX0471 | RecloserHydraulic | 629-0469 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | 0939 | NonLTC | 762-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Switching Operations | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Operations This Read AM | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Operations Counter AL | 1302 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Operations Counter AF | 1302 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | General Comments | | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | General Comments | | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Patrol Inspection | General Comments | | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Operations Counter AF | 364 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | General Comments | | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | General Comments | | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | General Comments | | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | FE000148 | Fence | 425-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | BAT000859 | Battery | Retired Distribution | Battery Patrol Inspection | All Connections OK? | y | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | BAT000859 | Battery | Retired Distribution | Battery Patrol Inspection | Bat Volt 1Min After Chgr Trip | 0.0 | VDC |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | BAT000859 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Area Ambient Temp | 54 | °F |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | BAT000859 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | BAT000859 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | BAT000859 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | BAT000859 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | BAT000859 | Battery | Retired Distribution | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | BAT000859 | Battery | Retired Distribution | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | BAT000859 | Battery | Retired Distribution | Battery Patrol Inspection | General Comments | | |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | BAT000859 | Battery | Retired Distribution | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | BAT000859 | Battery | Retired Distribution | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/6/2023 14:11 | Distribution | Wickliffe Quarterly Inspection | BAT000859 | Battery | Retired Distribution | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | 9 Month Operations | 2 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | CH000456 | ControlHouse | EI-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 60458 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | R1445 | Regulator | 822-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | CH000456 | ControlHouse | EI-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | CH000456 | ControlHouse | EI-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | CH000456 | ControlHouse | EI-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | CH000456 | ControlHouse | EI-Battery Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | CH000456 | ControlHouse | EI-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | CH000456 | ControlHouse | EI-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | ST000118 | Structure | 353-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | FE000321 | Fence | 637-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Readings | 9 Month Operations GCB New | 1 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Ambient Temperature | 38 | °F |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Readings | Fault Operations | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | General Comments | | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Readings | General Comments | | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | CH000456 | ControlHouse | EI-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | CH000456 | ControlHouse | EI-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | CH000455 | ControlHouse | DU-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | CH000455 | ControlHouse | DU-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | CH000455 | ControlHouse | DU-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | CH000455 | ControlHouse | DU-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | CH000455 | ControlHouse | DU-Battery Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | CH000455 | ControlHouse | DU-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | CH000455 | ControlHouse | DU-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | CH000455 | ControlHouse | DU-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | CH000455 | ControlHouse | DU-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Readings | Num Operations Last 9 Months | 1 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Readings | Operations Counter AF | 73 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Readings | Operations Counter AL | 73 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Readings | Operations This Read SF6 | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | SF6 Pressure | 66 | psi |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Readings | Switching Operations | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BK000191 | BreakerSF6 | 535-638 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Switching Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Operations This Read Vac | 0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Operations Counter AL | 364 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0309 | BreakerAirMagnetic | FC-2 | AMCB Readings | Unknown Operations | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | General Comments | | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | General Comments | | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Operations Counter AF | 219 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Operations Counter AL | 219 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Operations This Read Vac | 0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Switching Operations | 0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Amps C Ø | 100.0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Amps B Ø | 120.0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Amps A Ø | 100.0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0168 | BreakerVacuum | 803-0819 | VCB Readings | 9 Month Operations | 6 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BAT001421 | Battery | 401-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BAT001421 | Battery | 401-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BAT001421 | Battery | 401-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BAT001421 | Battery | 401-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BAT001421 | Battery | 401-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Amps A Ø | 0.0 | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Amps B Ø | 0.0 | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Amps C Ø | 0.0 | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | n | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | KX0169 | RecloserElectronic | 656-0466 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Readings | General Comments | | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Readings | Oil Temp Max | 80 | °C |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0290 | WithLTC | 535-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | ST000294 | Structure | 677-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BAT001421 | Battery | 401-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BAT001421 | Battery | 401-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BAT001421 | Battery | 401-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 8.2 | VDC |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BAT001421 | Battery | 401-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 8.2 | VDC |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Amps A Ø | 20.0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Amps B Ø | 40.0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Amps C Ø | 20.0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | WB0169 | BreakerVacuum | 803-0818 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | General Comments | | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Floor Swept? | n | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | BAT001433 | Battery | EI-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Door Alarms OK? | n | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Broom on Site? | n | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/6/2023 12:51 | Distribution | Cloverlick Quarterly Inspection | CH000406 | ControlHouse | 691-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | SWG000090 | Switchgear | FC-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Counter Readings | General Comments | | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 134 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 3 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 10 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 9 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 77171 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 77171 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | General Comments | | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | General Comments | | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | General Comments | | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | General Comments | BCG/TC | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Amps C Ø | 80.0 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Amps B Ø | 82.0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | 9 Month Operations | 1 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Amps A Ø | 12.0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Amps B Ø | 16.0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Amps C Ø | 18.0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Min Tap Position | 15L | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 116385 | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | YD000037 | Yard | 369-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | YD000037 | Yard | 369-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | YD000037 | Yard | 369-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | YD000037 | Yard | 369-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Readings | Unknown Operations | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Readings | Switching Operations | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | SF6 Pressure | 67 | psi |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Readings | Operations This Read SF6 | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Readings | Operations Counter AL | 53 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Readings | Operations Counter AF | 53 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Readings | Num Operations Last 9 Months | 1 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | 9 Month Ops New | 1 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | 9 Months Operations | 1 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Readings | General Comments | | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | General Comments | | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Operations This Read Vac | 0 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Operations Counter AL | 223 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Operations Counter AF | 223 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | General Comments | | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | General Comments | | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN32 | LTCMechanism | FC-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Operations Counter AF | 331 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Operations Counter AL | 332 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Operations This Read Vac | 1 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Switching Operations | 1 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | ST000041 | Structure | 369-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | YD000037 | Yard | 369-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | YD000037 | Yard | 369-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | YD000037 | Yard | 369-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | YD000037 | Yard | 369-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | YD000037 | Yard | 369-Yard | Yard Patrol Inspection | General Comments | | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | K0144 | BreakerVacuum | 677-0587 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | YD000037 | Yard | 369-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Counter Readings | General Comments | | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Counter Readings | LTC As Found Counter | 132296 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Counter Readings | LTC As Left Counter | 132304 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Counter Readings | LTC Current Tap Position | 2R | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Counter Readings | LTC Max Tap Position | 5R | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Counter Readings | LTC Operations Since Last Insp | 338 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | W0353 | LTCMechanism | 535-3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | 9 Month Operations | 4 | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BCH000238 | Charger | 401-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 15.000 | millivolts |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BCH000238 | Charger | 401-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.7 | VDC |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BCH000238 | Charger | 401-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.7 | VDC |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BCH000238 | Charger | 401-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BCH000238 | Charger | 401-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | BCH000238 | Charger | 401-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | YD000037 | Yard | 369-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | YD000037 | Yard | 369-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | YD000037 | Yard | 369-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | LTCC000806 | LTCControl | 438-1 | LTC Control Insp | All Connections OK? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | LTCC000806 | LTCControl | 438-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Patrol Inspection | General Comments | | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | General Comments | | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Operations Counter AF | 326 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Operations Counter AL | 326 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Operations This Read AM | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Switching Operations | 0 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | LTCC000806 | LTCControl | 438-1 | LTC Control Insp | General Comments | | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | LTCC000806 | LTCControl | 438-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Unknown Operations | 0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | LTCC000806 | LTCControl | 438-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | LTCC000806 | LTCControl | 438-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | LTCC000806 | LTCControl | 438-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | LTCC000806 | LTCControl | 438-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | 9 Month Operations | 4 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Amps A Ø | 170.0 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Amps B Ø | 120.0 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Amps C Ø | 130.0 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | 9 Month Operations | 1 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Restroom Clean & OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | General Comments | | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | LTCC000912 | LTCControl | 656-1 | LTC Control Insp | VRR Base Voltage AL | 123.5 | VAC |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | LTCC000912 | LTCControl | 656-1 | LTC Control Insp | VRR Base Voltage AF | 124.7 | VAC |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | LTCC000912 | LTCControl | 656-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | LTCC000912 | LTCControl | 656-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | LTCC000912 | LTCControl | 656-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | LTCC000912 | LTCControl | 656-1 | LTC Control Insp | General Comments | | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | LTCC000912 | LTCControl | 656-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/6/2023 13:35 | Distribution | Totz Quarterly Inspection | LTCC000912 | LTCControl | 656-1 | LTC Control Insp | All Connections OK? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 1077 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 5L | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 422757 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | PN52 | LTCMechanism | FC-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 422757 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | General Comments | | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | General Comments | | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Operations Counter AF | 190 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Operations Counter AL | 190 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Operations This Read Vac | 0 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Switching Operations | 0 | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Current Tap Position | 12L | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | R1090 | Regulator | 419-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | BCH000453 | Charger | 822-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.1 | VDC |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | BCH000453 | Charger | 822-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | BCH000453 | Charger | 822-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Operations Counter | 236 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Switching Operations | 0 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | General Comments | | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | General Comments | TC | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Maintenance Operations | 1 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Operations Counter AF | 192 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Operations Counter AL | 193 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Operations This Read Vac | 1 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Switching Operations | 0 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | K0071 | BreakerVacuum | 438-1714 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Counter Readings | General Comments | | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Counter Readings | LTC As Found Counter | 1140 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Counter Readings | LTC As Left Counter | 1151 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Counter Readings | LTC Operations Since Last Insp | 212 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | S0042 | LTCMechanism | 574-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Amps A Ø | 820.0 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Amps B Ø | 860.0 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Readings | Amps C Ø | 860.0 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | K0182 | BreakerVacuum | 369-0681 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Patrol Inspection | General Comments | | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | General Comments | | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Operations Counter AF | 546 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Operations Counter AL | 546 | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Operations This Read AM | 0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Switching Operations | 0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Unknown Operations | 0 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | General Comments | | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | BCH000121 | Charger | EI-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | BCH000121 | Charger | EI-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | General Comments | | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Operations Counter AF | 195 | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Operations Counter AL | 195 | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Operations This Read Vac | 1 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | BCH000121 | Charger | EI-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | BCH000121 | Charger | EI-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 0.0 | amps |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | BCH000121 | Charger | EI-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.8 | VDC |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Amps A Ø | 80.0 | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Amps B Ø | 80.0 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | 9 Month Operations | 0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Counter Readings | LTC As Left Counter | 1775 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Counter Readings | LTC As Found Counter | 1768 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Counter Readings | General Comments | | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Amps C Ø | 80.0 | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | 9 Month Operations | 3 | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Fault Adjusted Amps A Phase V | 2.41 | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Fault Adjusted Amps B Phase V | 2.41 | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Fault Adjusted Amps C Phase V | 2.41 | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Readings | General Comments | | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | BCH000121 | Charger | EI-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.8 | VDC |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | BCH000121 | Charger | EI-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 112 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 7429 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 7429 | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Unknown Operations | 1 | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Switching Operations | 0 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | LT0065 | LTCMechanism | DX-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .0012 | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Readings | Oil Temp Present | 28 | °C |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Readings | Oil Temp Max | 42 | °C |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 101.67 | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1.44 | kw |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Readings | General Comments | | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 15:06 | Distribution | Herald Quarterly Inspection | O0211 | NonLTC | 353-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 553 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 7 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 10 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 13 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 24445 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 24445 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | PN30 | LTCMechanism | EI-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Low | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 614 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 3 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 7 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 5 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 418179 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 418179 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | PN18 | LTCMechanism | DU-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | General Comments | | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | FE000020 | Fence | 328-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BCH000287 | Charger | 535-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BCH000287 | Charger | 535-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BCH000287 | Charger | 535-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 32003 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Amps B Ø | 120.0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | 9 Month Ops New | 1 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | 9 Months Operations | 1 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Amps A Ø | 200.0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Amps B Ø | 205.0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Amps C Ø | 200.0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Readings | Fault Operations | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Patrol Inspection | Ambient Temperature | 38 | °F |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | TB1478 | BreakerSF6 | 535-618 | GCB Readings | 9 Month Operations GCB New | 1 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 39229 | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 125.0 | volts |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Amps A Ø | 90.0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Amps C Ø | 135.0 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Amps B Ø | 148.0 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Amps A Ø | 191.0 | |
| 1/6/2023 12:25 | Distribution | Cumberland Quarterly Inspection | K0187 | BreakerVacuum | 842-0454 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .3534 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 3600 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | KR0086 | Regulator | 803-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 335.00 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 361.67 | |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1272.24 | kw |
| 1/6/2023 11:39 | Distribution | Fredonia Quarry Quarterly Inspection | B0197 | NonLTC | 426-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | KX0127 | RecloserElectronic | 574-1712 | Recloser Electronic Patrol Inspection | Amps A Ø | 84.0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BCH000287 | Charger | 535-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 134.1 | VDC |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BCH000287 | Charger | 535-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 134.1 | VDC |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | BCH000287 | Charger | 535-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .7 | amps |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Amps C Ø | 42.0 | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Amps B Ø | 37.0 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Amps A Ø | 39.0 | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Counter Readings | LTC Operations Since Last Insp | 259 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Counter Readings | LTC Min Tap Position | 4L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Counter Readings | LTC Max Tap Position | 9R | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | S0014 | LTCMechanism | 401-1 | LTC Counter Readings | LTC Current Tap Position | 5R | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Operations This Read AM | 0 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Amps C Ø | 140.0 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Amps B Ø | 180.0 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Amps A Ø | 120.0 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Switching Operations | 0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Unknown Operations | 0 | |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/6/2023 9:54 | Distribution | Oak Hill Quarterly Inspection | KB0089 | BreakerVacuum | 191-3418 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Patrol Inspection | General Comments | | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | General Comments | | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Switching Operations | 0 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Operations This Read Vac | 0 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Operations Counter AL | 161 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Operations Counter AF | 161 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Readings | General Comments | | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Operations Counter AF | 16 | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Amps C Ø | 190.0 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0276 | BreakerAirMagnetic | DU-2 | AMCB Readings | Operations Counter AL | 16 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | LB0277 | BreakerAirMagnetic | DU-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Operations Counter | 2 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | SWG000081 | Switchgear | DU-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/6/2023 8:06 | Distribution | Crossroads Quarterly Inspection | R1151 | Regulator | 637-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | X0334 | RecloserElectronic | 401-1325 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | General Comments | | |
| 1/6/2023 13:22 | Distribution | Cedar Bluff Quarterly Inspection | K0117 | BreakerVacuum | 822-1514 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | YD000236 | Yard | 803-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | YD000236 | Yard | 803-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Amps C Ø | 46.5 | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Amps B Ø | 51.9 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Readings | General Comments | | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Readings | LTC Totalizer Reading | 0.00 | kw |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Amps A Ø | 45.7 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 179 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | YD000236 | Yard | 803-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | YD000236 | Yard | 803-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | YD000236 | Yard | 803-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | YD000236 | Yard | 803-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | YD000236 | Yard | 803-Yard | Yard Patrol Inspection | Ambient Temp | 35 | °F |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 12.6 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 10.0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | General Comments | | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | General Comments | | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | General Comments | | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Operations Counter AF | 175 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Operations Counter AL | 176 | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | YD000619 | Yard | DU-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Operations This Read Vac | 1 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Switching Operations | 0 | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | General Comments | | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | YD000619 | Yard | DU-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | YD000619 | Yard | DU-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | YD000619 | Yard | DU-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | YD000619 | Yard | DU-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | YD000619 | Yard | DU-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | YD000236 | Yard | 803-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Operations Counter | 347 | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | YD000619 | Yard | DU-Yard | Yard Patrol Inspection | General Comments | | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | General Comments | | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | YD000619 | Yard | DU-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Readings | General Comments | | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 507.20 | kw |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 130.00 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | YD000619 | Yard | DU-Yard | Yard Patrol Inspection | Clear of Trash? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | YD000619 | Yard | DU-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | Operations Counter | 0 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 10:30 | Distribution | Marion South Quarterly Inspection | ST000227 | Structure | 574-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 9:10 | Distribution | Dumesnil Quarterly Inspection | YD000619 | Yard | DU-Yard | Yard Patrol Inspection | Ambient Temp | 39 | °F |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 275 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 19.7 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 14.2 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 34.1 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 199 | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 245 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0439 | RecloserHydraulic | 425-1509 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 2800 | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/6/2023 13:59 | Distribution | Jacks Creek Quarterly Inspection | C0406 | WithLTC | 629-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | SWG000023 | Switchgear | DX-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | YD000315 | Yard | 762-Yard | Yard Patrol Inspection | Ambient Temp | 40 | °F |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Readings | General Comments | | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 14.9 | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 210 | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 9:27 | Distribution | Daniel Boone Quarterly Inspection | 0919 | NonLTC | 419-1 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Amps C Ø | 125.0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Amps B Ø | 125.0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Amps A Ø | 135.0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | 9 Months Operations | 0 | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | LB0310 | BreakerAirMagnetic | FC-3 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 12:17 | Distribution | Fredonia Quarterly Inspection | WX0422 | RecloserHydraulic | 425-1508 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 197 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | BCH000129 | Charger | FC-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 0.0 | amps |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | BCH000129 | Charger | FC-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.7 | VDC |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BCH001270 | Charger | 438-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.1 | VDC |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BCH001270 | Charger | 438-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.1 | VDC |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | LTCC000805 | LTCControl | 401-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | LTCC000805 | LTCControl | 401-1 | LTC Control Insp | General Comments | | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | LTCC000805 | LTCControl | 401-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | LTCC000805 | LTCControl | 401-1 | LTC Control Insp | All Connections OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Amps A Ø | 127.0 | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | 9 Month Operations | 3 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Amps C Ø | 112.0 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BCH001270 | Charger | 438-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .9 | amps |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Amps B Ø | 126.0 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BCH001270 | Charger | 438-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BCH001270 | Charger | 438-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Amps A Ø | 93.0 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Amps B Ø | 133.0 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Amps C Ø | 131.0 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | General Comments | TC | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | General Comments | | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | BCH000129 | Charger | FC-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | BCH000129 | Charger | FC-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.7 | VDC |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/9/2023 7:06 | Distribution | Sandy Ridge Quarterly Inspection | ST000014 | Structure | 328-Structure | Structure Patrol Inspection | General Comments | | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | CH000184 | ControlHouse | DX-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1600 | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | C0349 | NonLTC | 677-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .3170 | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | YD000236 | Yard | 803-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | General Comments | | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | YD000236 | Yard | 803-Yard | Yard Patrol Inspection | General Comments | | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | YD000236 | Yard | 803-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | BCH000129 | Charger | FC-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | BCH000129 | Charger | FC-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/6/2023 11:41 | Distribution | Falls City Quarterly Inspection | BCH000129 | Charger | FC-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | LTCC000805 | LTCControl | 401-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Operations Counter | 8 | |
| 1/6/2023 15:05 | Distribution | Toms Creek 2 Quarterly Inspection | DX0124 | RecloserElectronic | 369-0670 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 11:18 | Distribution | Wilmore Quarterly Inspection | CX0135 | RecloserElectronic | 677-0585 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | General Comments | | |
| 1/6/2023 8:44 | Distribution | Nortonville Quarterly Inspection | FE000238 | Fence | 803-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | LTCC000805 | LTCControl | 401-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | LTCC000805 | LTCControl | 401-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | ST000141 | Structure | 401-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | PF000101 | PowerFuse | DX-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:23 | Distribution | Dixie Quarterly Inspection | PF000101 | PowerFuse | DX-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/6/2023 11:55 | Distribution | Wickliffe City Quarterly Inspection | LTCC000805 | LTCControl | 401-1 | LTC Control Insp | LTC Output Voltage Level | 124.4 | VAC |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/6/2023 13:29 | Distribution | High Bridge Quarterly Inspection | ST000322 | Structure | 762-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Readings | Maintenance Operations | 1 | |
| 1/6/2023 9:09 | Distribution | Marion 4kV Quarterly Inspection | BK000492 | BreakerVacuum | 438-1715 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/6/2023 10:27 | Distribution | Westvaco Quarterly Inspection | ST000166 | Structure | 535-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/6/2023 11:03 | Distribution | Eighth Street Quarterly Inspection | FE000615 | Fence | EI-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | LTCC000945 | LTCControl | 951-Offline-Distribution | LTC Control Insp | All Connections OK? | y | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | LTCC000945 | LTCControl | 951-Offline-Distribution | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | LTCC000945 | LTCControl | 951-Offline-Distribution | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | LTCC000945 | LTCControl | 951-Offline-Distribution | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | LTCC000945 | LTCControl | 951-Offline-Distribution | LTC Control Insp | LTC Output Voltage Level | 124.7 | VAC |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | LTCC000945 | LTCControl | 951-Offline-Distribution | LTC Control Insp | LTC Operation Checked? | y | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | LTCC000945 | LTCControl | 951-Offline-Distribution | LTC Control Insp | General Comments | | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | LTCC000945 | LTCControl | 951-Offline-Distribution | LTC Control Insp | Follow-up Action Required? | n | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | BCH000407 | Charger | Retired Distribution | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | BCH000407 | Charger | Retired Distribution | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | BCH000407 | Charger | Retired Distribution | Battery Charger Patrol Insp | General Comments | | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | BCH000449 | Charger | Retired Distribution | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | BCH000449 | Charger | Retired Distribution | Battery Charger Patrol Insp | As Left Float Voltage | 54.7 | VDC |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | BCH000449 | Charger | Retired Distribution | Battery Charger Patrol Insp | As Found Float Voltage | 54.7 | VDC |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | BCH000449 | Charger | Retired Distribution | Battery Charger Patrol Insp | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | BAT000111 | Battery | Retired Distribution | Battery Patrol Inspection | All Connections OK? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | BAT000111 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Area Ambient Temp | 30 | °F |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | BAT000111 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Overall Condition | Fair | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | BAT000111 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | BAT000111 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | BAT000111 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | BAT000111 | Battery | Retired Distribution | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | BAT000111 | Battery | Retired Distribution | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | BAT000111 | Battery | Retired Distribution | Battery Patrol Inspection | Follow-up Action Required? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | BAT000111 | Battery | Retired Distribution | Battery Patrol Inspection | General Comments | Eight battery posts have corrosion. | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | BAT000111 | Battery | Retired Distribution | Battery Patrol Inspection | Straps Corrosion Free? | n | If no, which cells in comments |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | BAT000111 | Battery | Retired Distribution | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 40.45 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 40.45 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 40.45 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 0.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 0.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 0.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 107 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 107 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0259 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 0.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 0.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 0.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 2.66 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 2.66 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 2.66 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 105 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 105 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0257 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 7.97 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 3.99 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 599 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 599 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 88.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 71.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 75.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 5.32 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0256 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 23.92 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 42.52 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 23.92 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 6 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 6 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 60 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 60 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 90.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 88.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 100.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0255 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 1 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 2 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 1 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 278 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 278 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 3 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 11.18 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 27.91 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 11.18 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 26.58 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 11.18 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 109.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 30.56 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 111.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 122.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0254 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 3.11 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 3.11 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 152 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 275.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 261.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 279.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 3.11 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 152 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0261 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 2 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 489 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 489 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 27.7 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 36.14 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 38.54 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 6 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 4 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 2 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 85.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 100.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 91.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 22.36 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 22.36 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 22.36 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0253 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 102.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 91.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 103.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 21.68 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 37.34 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 44.57 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 1 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 1 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 134 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 134 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0252 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 4.82 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 15.66 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 65.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 379 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 74.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 105.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 379 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 9.64 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 1 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 1 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0251 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | A,B phase IOC | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 2.41 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 4 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 61.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 56.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 69.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 22.36 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 6.02 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 3.61 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 235 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 2 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 6 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 235 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 2 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 2 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 22.36 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0250 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations Ground | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Switching Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations This Read AM | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AL | 223 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps C Ø | 370.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps B Ø | 321.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Amps A Ø | 319.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty C Ph AM | 2.6 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty B Ph AM | 2.6 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Accumulated Fault Duty A Ph AM | 2.6 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Months Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Unknown Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | 9 Month Ops New | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Maintenance Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Readings | Operations Counter AF | 223 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LB0260 | BreakerAirMagnetic | Retired Distribution | AMCB Patrol Inspection | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LTCC000116 | LTCControl | SSC-Offline-Distribution | LTC Control Insp | All Connections OK? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LTCC000116 | LTCControl | SSC-Offline-Distribution | LTC Control Insp | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LTCC000116 | LTCControl | SSC-Offline-Distribution | LTC Control Insp | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LTCC000116 | LTCControl | SSC-Offline-Distribution | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Switching Operations | 23 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Readings | General Comments | | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Amps C Ø | 130.0 | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 65.52 | kw |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Amps C Ø | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Amps B Ø | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Accumulated Fault Duty B Ph V | 2.74 | % |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Amps A Ø | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Accumulated Fault Duty C Ph V | 2.74 | % |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Amps B Ø | 125.0 | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 48 | °F |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 600 | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Readings | Totalizer Meter Reading | .1092 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | CH000454 | ControlHouse | CK-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | CH000454 | ControlHouse | CK-Battery Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | CH000454 | ControlHouse | CK-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | CH000454 | ControlHouse | CK-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | CH000454 | ControlHouse | CK-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | CH000454 | ControlHouse | CK-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Amps C Ø | 5.0 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Amps B Ø | 5.0 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Amps A Ø | 10.0 | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | 9 Month Operations | 0 | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | 9 Month Operations | 1 | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | Ambient Temp | 53 | °F |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0119 | NonLTC | 577-1 A | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Operations Counter AF | 260 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Operations Counter AL | 260 | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BCH001494 | Charger | 879-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BCH001494 | Charger | 879-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BCH001494 | Charger | 879-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BCH001494 | Charger | 879-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .6 | amps |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BCH001494 | Charger | 879-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BCH001494 | Charger | 879-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BCH001494 | Charger | 879-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Amps A Ø | 100.0 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BCH001494 | Charger | 879-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Accumulated Fault Duty A Ph V | 2.74 | % |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | 9 Month Operations | 1 | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0118 | NonLTC | 577-1 B | NonLTC Transformer Readings | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Operations Counter AF | 161 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Operations Counter AL | 161 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | General Comments | | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Readings | Totalizer Meter Reading | .7776 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | ST000474 | Structure | 529-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Fault Operations C Ø | 2 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Amps A Ø | 180.0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Amps B Ø | 180.0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Amps A Ø | 17.0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Amps B Ø | 10.0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Patrol Inspection | General Comments | | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | General Comments | | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 10.00 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Readings | Winding Temp Present | 20 | °C |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Operations Counter AF | 412 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Operations Counter AL | 412 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Operations This Read AM | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Switching Operations | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Unknown Operations | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Amps C Ø | 30.0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Readings | Winding Temp Max | 29 | °C |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Ambient Temp | 40 | °F |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Readings | Oil Temp Present | 31 | °C |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BCH001290 | Charger | 529-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 4.8 | amps |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BCH001290 | Charger | 529-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BCH001290 | Charger | 529-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BCH001290 | Charger | 529-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BCH001290 | Charger | 529-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Operations This Read Vac | 2 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Operations Counter AL | 282 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Operations Counter AF | 282 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | General Comments | BC Phase IOC | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Fault Operations C Ø | 1 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Fault Operations B Ø | 1 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Fault Adjusted Amps C Phase V | 8.00 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Operations Counter AF | 181 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Operations Counter AL | 181 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Operations This Read Vac | 4 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Readings | Totalizer Meter Reading | .8012 | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BCH001290 | Charger | 529-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BCH001290 | Charger | 529-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | General Comments | | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | YD000472 | Yard | 529-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Readings | Oil Temp Present | 15 | °C |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Readings | Oil Temp Max | 43 | °C |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 200.00 | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 205.00 | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Operations Counter AF | 99945 | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Operations Counter AL | 99945 | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | WB0167 | BreakerVacuum | 758-1315 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Readings | General Comments | | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BAT001227 | Battery | 769-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | 9 Month Operations | 4 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | All Connections OK? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | Battery Area Ambient Temp | 43 | °F |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | General Comments | | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | 9 Month Ops New | 3 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | 9 Months Operations | 3 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Amps A Ø | 25.0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Amps B Ø | 40.0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Amps C Ø | 60.0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0245 | BreakerAirMagnetic | CB-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | CH000454 | ControlHouse | CK-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | CH000454 | ControlHouse | CK-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | LTCC000857 | LTCControl | 176-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | LTCC000857 | LTCControl | 176-5 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | LTCC000857 | LTCControl | 176-5 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | LTCC000857 | LTCControl | 176-5 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | LTCC000857 | LTCControl | 176-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | LTCC000857 | LTCControl | 176-5 | LTC Control Insp | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | LTCC000857 | LTCControl | 176-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | LTCC000857 | LTCControl | 176-5 | LTC Control Insp | All Connections OK? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | 9 Month Operations | 22 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | 9 Month Operations VCB New | 18 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Amps A Ø | 35.0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Amps B Ø | 66.0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Amps C Ø | 49.0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Fault Adjusted Amps A Phase V | 9.88 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | CH000454 | ControlHouse | CK-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Fault Adjusted Amps C Phase V | 9.88 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK000197 | BreakerVacuum | 116-0686 | VCB Readings | Fault Operations A Ø | 2 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | General Comments | | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | YD000219 | Yard | 862-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001584 | BreakerVacuum | 116-0687 | VCB Readings | 9 Month Operations | 9 | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | W0211 | NonLTC | 577-1 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | FE000858 | Fence | 116-Yard | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | ST000224 | Structure | 862-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Oil Temp Max | 40 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Amps A Ø | 690.0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Amps B Ø | 715.0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Amps C Ø | 715.0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 347150 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.7 | volts |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Amps C Ø | 135.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | General Comments | | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Accumulated Fault Duty A Ph V | 8.64 | % |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Accumulated Fault Duty B Ph V | 10.33 | % |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | LTCC000780 | LTCControl | 875-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | LTCC000780 | LTCControl | 875-1 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | LTCC000780 | LTCControl | 875-1 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | LTCC000780 | LTCControl | 875-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Fault Operations Ground | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0249 | GroundTransformer | CY-GND TR 2 | Ground Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Operations Counter AF | 167 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | YD000629 | Yard | CK-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Operations Counter AL | 167 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | 9 Month Operations | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Accumulated Fault Duty C Ph V | 8.86 | % |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Amps A Ø | 86 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Amps B Ø | 103 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Amps C Ø | 120 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | General Comments | | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Operations Counter AF | 212 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Operations Counter AL | 212 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | YD000629 | Yard | CK-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | YD000629 | Yard | CK-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Counter Readings | General Comments | | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Counter Readings | LTC As Found Counter | 277618 | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Counter Readings | LTC As Left Counter | 277618 | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Counter Readings | LTC Operations Since Last Insp | 336 | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | LTCMechanism | 769-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 21985 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Min Tap Position | 2L | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | YD000629 | Yard | CK-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | YD000629 | Yard | CK-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | YD000629 | Yard | CK-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | YD000629 | Yard | CK-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | YD000629 | Yard | CK-Yard | Yard Patrol Inspection | General Comments | | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | YD000629 | Yard | CK-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | YD000629 | Yard | CK-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Amps B Ø | 90.0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Amps A Ø | 70.0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Fault Adjusted Amps B Phase V | 11.18 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Fault Adjusted Amps A Phase V | 22.36 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Amps C Ø | 100.0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Amps B Ø | 75.0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Amps A Ø | 50.0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | General Comments | drag hands stuck on indicaton | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Min Tap Position | 2L | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 20733 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 310137 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Unknown Operations | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Switching Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Operations This Read AM | 1 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Operations Counter AL | 281 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Operations Counter AF | 281 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | General Comments | B phase IOC | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Patrol Inspection | General Comments | | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Fault Operations B Ø | 1 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Fault Adjusted Amps B Phase AM | 9.55 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Operations Counter AL | 256 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Fault Operations A Ø | 2 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Fault Operations B Ø | 1 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | PF000071 | PowerFuse | CY-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | PF000071 | PowerFuse | CY-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Operations Counter AF | 256 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Amps C Ø | 50.0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Operations Counter AF | 178 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Operations Counter AL | 179 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Amps A Ø | 195.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Amps B Ø | 200.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | Amps C Ø | 195.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LTCC000538 | LTCControl | CY-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Operations This Read Vac | 1 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Switching Operations | 1 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Amps A Ø | 47.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LTCC000538 | LTCControl | CY-TRANS 1 | LTC Control Insp | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LTCC000538 | LTCControl | CY-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Amps B Ø | 37.0 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Amps C Ø | 39.0 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | 9 Months Operations | 5 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0246 | BreakerAirMagnetic | CB-4 | AMCB Readings | 9 Month Ops New | 4 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | LTCC000780 | LTCControl | 875-1 | LTC Control Insp | All Connections OK? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | LTCC000780 | LTCControl | 875-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | LTCC000780 | LTCControl | 875-1 | LTC Control Insp | General Comments | | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | LTCC000780 | LTCControl | 875-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | 9 Month Operations | 1 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | 9 Month Operations | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1006 | Regulator | 351-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000021 | Regulator | 862-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | 9 Month Operations | 8 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000360 | BreakerVacuum | 459-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | 9 Month Operations | 1 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000734 | BreakerVacuum | 879-4480 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | General Comments | | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Operations Counter AF | 186 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Operations Counter AL | 186 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | 9 Month Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Amps A Ø | 60.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Amps B Ø | 75.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Amps C Ø | 65.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BCH001176 | Charger | 769-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Amps C Ø | 15.0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Amps B Ø | 18.0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Amps A Ø | 18.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Amps A Ø | 200.0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Amps B Ø | 180.0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Amps C Ø | 200.0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Fault Adjusted Amps A Phase V | 11.18 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Fault Adjusted Amps B Phase V | 11.18 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Fault Operations A Ø | 1 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Fault Operations B Ø | 1 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | General Comments | | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BCH001176 | Charger | 769-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Operations Counter AF | 467 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Operations Counter AL | 467 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Operations This Read Vac | 2 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BCH001176 | Charger | 769-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BCH001176 | Charger | 769-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | CH000484 | ControlHouse | 351-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BCH001599 | Charger | CO-Battery Charger 1 | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BCH001599 | Charger | CO-Battery Charger 1 | Battery Charger Patrol Insp | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BCH001599 | Charger | CO-Battery Charger 1 | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BCH001599 | Charger | CO-Battery Charger 1 | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BCH001599 | Charger | CO-Battery Charger 1 | Battery Charger Patrol Insp | Battery Charger Current | 5.5 | amps |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BCH001599 | Charger | CO-Battery Charger 1 | Battery Charger Patrol Insp | As Left Float Voltage | 54.7 | VDC |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BCH001599 | Charger | CO-Battery Charger 1 | Battery Charger Patrol Insp | As Found Float Voltage | 54.7 | VDC |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BCH001599 | Charger | CO-Battery Charger 1 | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Switching Operations | 1 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Operations This Read Vac | 1 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Operations Counter AL | 243 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Operations Counter AF | 242 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | General Comments | 1 trip check | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | General Comments | | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0098 | BreakerVacuum | 862-1505 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | 9 Month Operations | 25 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Operations Counter AF | 156 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Operations Counter AF | 225 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Operations Counter AL | 225 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000365 | BreakerVacuum | 459-0193 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | 9 Month Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Amps A Ø | 120.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Amps B Ø | 120.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Readings | Amps C Ø | 120.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000366 | BreakerVacuum | 459-0194 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB1325 | BreakerVacuum | CO-1193 | VCB Readings | Amps C Ø | 160.0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | GND000031 | BreakerGroundDevice | 459-Offline Distribution | Breaker Ground Device Inspection | Vacuum and Clean Breaker? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | GND000031 | BreakerGroundDevice | 459-Offline Distribution | Breaker Ground Device Inspection | Rosettes Clean and Lubed? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | GND000031 | BreakerGroundDevice | 459-Offline Distribution | Breaker Ground Device Inspection | Ground Connections Intact? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | GND000031 | BreakerGroundDevice | 459-Offline Distribution | Breaker Ground Device Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | GND000031 | BreakerGroundDevice | 459-Offline Distribution | Breaker Ground Device Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | GND000031 | BreakerGroundDevice | 459-Offline Distribution | Breaker Ground Device Inspection | Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | GND000031 | BreakerGroundDevice | 459-Offline Distribution | Breaker Ground Device Inspection | Bearings lubricated? | n | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | YD000629 | Yard | CK-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | YD000629 | Yard | CK-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .1 | psi |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | GND000031 | BreakerGroundDevice | 459-Offline Distribution | Breaker Ground Device Inspection | All Connections OK? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | WithLTC | CK-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | YD000629 | Yard | CK-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | FE000628 | Fence | CK-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | FE000628 | Fence | CK-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | FE000628 | Fence | CK-Fence | Fence Patrol Inspection | General Comments | | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1004 | Regulator | 351-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Operations Counter AF | 99942 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Operations Counter AL | 99965 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Readings | Operations This Read Vac | 23 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | General Comments | 1 trip check | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Operations Counter AF | 53 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Operations Counter AL | 54 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Operations This Read Vac | 1 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | K0067 | BreakerVacuum | 862-1506 | VCB Readings | Switching Operations | 1 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 21209 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Amps A Ø | 0.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Amps B Ø | 0.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000364 | BreakerVacuum | 459-0192 | VCB Readings | Amps C Ø | 0.0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0228 | BreakerVacuum | 472-0208 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000022 | Regulator | 862-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BCH001176 | Charger | 769-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BCH001176 | Charger | 769-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BCH001176 | Charger | 769-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BCH001176 | Charger | 769-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .5 | amps |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | General Comments | | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Operations Counter AF | 159 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Operations Counter AL | 159 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000575 | BreakerVacuum | 529-1 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | FE000628 | Fence | CK-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | FE000628 | Fence | CK-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | FE000628 | Fence | CK-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | FE000628 | Fence | CK-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | FE000628 | Fence | CK-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | FE000628 | Fence | CK-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | FE000628 | Fence | CK-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | FE000628 | Fence | CK-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | FE000628 | Fence | CK-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | FE000628 | Fence | CK-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | FE000628 | Fence | CK-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | FE000628 | Fence | CK-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | FE000628 | Fence | CK-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | RG000023 | Regulator | 862-1 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Amps B Ø | 129.0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Amps A Ø | 142.0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BK000574 | BreakerVacuum | 472-0206 | VCB Readings | 9 Month Operations | 1 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | General Comments | | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | FE000526 | Fence | 472-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0224 | BreakerVacuum | CO-1197 | VCB Readings | 9 Month Operations | 5 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Amps C Ø | 0.0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Amps B Ø | 0.0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Amps A Ø | 0.0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | YD000353 | Yard | 875-Yard | Yard Patrol Inspection | Ambient Temp | 48 | °F |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | YD000353 | Yard | 875-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | YD000353 | Yard | 875-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | YD000353 | Yard | 875-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | YD000353 | Yard | 875-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | YD000353 | Yard | 875-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | YD000353 | Yard | 875-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | YD000353 | Yard | 875-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | YD000353 | Yard | 875-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | YD000353 | Yard | 875-Yard | Yard Patrol Inspection | General Comments | | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | YD000353 | Yard | 875-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | YD000353 | Yard | 875-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | 9 Month Operations | 9 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | LTCC000988 | LTCControl | 116-5 | LTC Control Insp | All Connections OK? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | LTCC000988 | LTCControl | 116-5 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | LTCC000988 | LTCControl | 116-5 | LTC Control Insp | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | LTCC000988 | LTCControl | 116-5 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | LTCC000988 | LTCControl | 116-5 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | LTCC000988 | LTCControl | 116-5 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | LTCC000988 | LTCControl | 116-5 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | LTCC000988 | LTCControl | 116-5 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | ST000357 | Structure | 875-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1000 | psi |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Readings | Oil Temp Max | 43 | °C |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Readings | Oil Temp Present | 27 | °C |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | BCH000428 | Charger | 671-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Amps C Ø | 165.0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Amps B Ø | 140.0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Amps A Ø | 160.0 | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | BCH000428 | Charger | 671-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | BCH000428 | Charger | 671-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | BCH000428 | Charger | 671-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | BCH000428 | Charger | 671-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | 9 Month Operations | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCC000592 | LTCControl | 472-1 | LTC Control Insp | All Connections OK? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCC000592 | LTCControl | 472-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCC000592 | LTCControl | 472-1 | LTC Control Insp | General Comments | | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCC000592 | LTCControl | 472-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCC000592 | LTCControl | 472-1 | LTC Control Insp | LTC Output Voltage Level | 123.9 | VAC |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCC000592 | LTCControl | 472-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | 9 Month Operations | 3 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Amps A Ø | 96.0 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Amps B Ø | 85.0 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Amps C Ø | 76.0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Operations Counter AL | 228 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Operations Counter AF | 228 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | BCH000428 | Charger | 671-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .3 | amps |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Readings | Oil Temp Present | 18 | °C |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Readings | Oil Temp Max | 39 | °C |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | General Comments | | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PF001297 | PowerFuse | CB-4KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PF001297 | PowerFuse | CB-4KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PF001296 | PowerFuse | CB-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PF001296 | PowerFuse | CB-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Operations Counter | 102 | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0948 | NonLTC | 031-5 C | NonLTC Transformer Readings | General Comments | | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Operations Counter AL | 53 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Operations Counter AF | 53 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | CB0191 | BreakerVacuum | 472-1 | VCB Readings | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Floor Swept? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Door Alarms OK? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Broom on Site? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 40 | °C |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 30 | °C |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 55 | °C |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 40 | °C |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 55 | °C |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Counter Readings | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Counter Readings | LTC As Found Counter | 173628 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Counter Readings | LTC As Left Counter | 173632 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Counter Readings | LTC Current Tap Position | 1L | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Counter Readings | LTC Operations Since Last Insp | 457 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | LTCMechanism | 116-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 45 | °C |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 50 | °C |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 55.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Amps C Ø | 0.0 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Amps B Ø | 0.0 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Amps A Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | 9 Month Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | nitrogen bottle is empty | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .3 | psi |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Trash Emptied? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | CH000159 | ControlHouse | CO-Control House 1 | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BCH001006 | Charger | 459-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 132.0 | VDC |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BCH001006 | Charger | 459-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 29 | °C |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 43 | °C |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 29 | °C |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 43 | °C |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | Top Oil Temperature Present | 17 | °C |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | Top Oil Temperature Max | 40 | °C |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Readings | General Comments | | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0170 | NonLTC | 362-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 0.00 | kw |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | needs nitro | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BAT001041 | Battery | 459-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BCH001006 | Charger | 459-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BCH001006 | Charger | 459-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BCH001006 | Charger | 459-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BCH001006 | Charger | 459-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 4.3 | amps |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Counter Readings | General Comments | | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | BCH000428 | Charger | 671-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .800 | millivolts |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | BCH000428 | Charger | 671-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 53 | °F |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BAT001126 | Battery | 472-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000119 | Switchgear | CO-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 29 | °C |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | TX000165 | WithLTC | CY-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 43 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | ST000049 | Structure | 116-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BCH001006 | Charger | 459-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 132.0 | VDC |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Amps C Ø | 0.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Amps B Ø | 0.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Amps A Ø | 0.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Patrol Inspection | General Comments | | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | General Comments | | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Operations Counter AF | 487 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Operations Counter AL | 487 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Operations This Read AM | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Switching Operations | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Unknown Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | 9 Month Operations | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | LTCC000738 | LTCControl | 529-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 240 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 72344 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 72344 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Counter Readings | General Comments | | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | LTCMechanism | CB-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | BCH001070 | Charger | DA-Battery Charger | Battery Charger Patrol Insp | General Comments | my multimeter does not read ripple voltage. | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | BCH001070 | Charger | DA-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | BCH001070 | Charger | DA-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 3.6 | amps |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | BCH001070 | Charger | DA-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 134.3 | VDC |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | BCH001070 | Charger | DA-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 134.3 | VDC |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | BCH001070 | Charger | DA-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .0006 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1600 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | LTCC000738 | LTCControl | 529-1 | LTC Control Insp | All Connections OK? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | LTCC000738 | LTCControl | 529-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Operations Counter AL | 124 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Operations Counter AF | 124 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | 9 Month Ops New | 1 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | 9 Months Operations | 1 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000413 | BreakerVacuum | 459-BT1-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | LTCC000738 | LTCControl | 529-1 | LTC Control Insp | General Comments | | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | LTCC000738 | LTCControl | 529-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | LTCC000738 | LTCControl | 529-1 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | LTCC000738 | LTCControl | 529-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | LTCC000738 | LTCControl | 529-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | LTCC000738 | LTCControl | 529-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Amps A Ø | 80.0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Amps B Ø | 95.0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Amps C Ø | 100.0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0244 | BreakerAirMagnetic | CB-2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | YD000068 | Yard | 879-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | YD000068 | Yard | 879-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | YD000068 | Yard | 879-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | YD000068 | Yard | 879-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | YD000068 | Yard | 879-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | YD000068 | Yard | 879-Yard | Yard Patrol Inspection | General Comments | | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | YD000068 | Yard | 879-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | YD000068 | Yard | 879-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | YD000068 | Yard | 879-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BAT001027 | Battery | CO-Battery Bank 1 | Battery Patrol Inspection | All Connections OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BAT001027 | Battery | CO-Battery Bank 1 | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BAT001027 | Battery | CO-Battery Bank 1 | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BAT001027 | Battery | CO-Battery Bank 1 | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BAT001027 | Battery | CO-Battery Bank 1 | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BAT001027 | Battery | CO-Battery Bank 1 | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BAT001027 | Battery | CO-Battery Bank 1 | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BAT001027 | Battery | CO-Battery Bank 1 | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | General Comments | | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | ST000076 | Structure | 879-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BAT001027 | Battery | CO-Battery Bank 1 | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BAT001027 | Battery | CO-Battery Bank 1 | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BAT001027 | Battery | CO-Battery Bank 1 | Battery Patrol Inspection | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BAT001027 | Battery | CO-Battery Bank 1 | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Readings | Oil Temp Present | 24 | °C |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Readings | Oil Temp Max | 39 | °C |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | .96 | kw |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Readings | General Comments | | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000099 | Switchgear | CY-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Amps C Ø | 210.0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Amps B Ø | 240.0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Amps A Ø | 265.0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | 9 Month Operations | 10 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0169 | NonLTC | 362-2-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Operations Counter AF | 213 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Operations Counter AL | 214 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Operations This Read Vac | 1 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | YD000068 | Yard | 879-Yard | Yard Patrol Inspection | Ambient Temp | 47 | °F |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | YD000068 | Yard | 879-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | YD000068 | Yard | 879-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Amps B Ø | 120.0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Amps A Ø | 130.0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | 9 Month Operations | 10 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1500 | psi |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | General Comments | | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Operations Counter AF | 239 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Operations Counter AL | 239 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | BK000589 | BreakerVacuum | 080-4475 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCC000592 | LTCControl | 472-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCC000592 | LTCControl | 472-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000923 | BreakerVacuum | 529-0095 | VCB Readings | Amps C Ø | 165.0 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | 9 Month Operations | 1 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Amps A Ø | 62.0 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Amps B Ø | 60.0 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Amps C Ø | 67.0 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 397 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Amps C Ø | 92.0 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Amps B Ø | 80.0 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Amps A Ø | 95.0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PF001290 | PowerFuse | CK-4KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PF001290 | PowerFuse | CK-4KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | General Comments | 1 op - Trip Check | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Readings | Maintenance Operations | 1 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | KB0118 | BreakerVacuum | 671-1503 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Operations Counter AL | 209 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Operations Counter AF | 209 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | General Comments | | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | BCH000124 | Charger | CK-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | BCH000124 | Charger | CK-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.7 | VDC |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | BCH000124 | Charger | CK-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.7 | VDC |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | BCH000124 | Charger | CK-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 0.0 | amps |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | BCH000124 | Charger | CK-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | BCH000124 | Charger | CK-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | BCH000124 | Charger | CK-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK000922 | BreakerVacuum | 529-0092 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 54 | °C |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 19 | °C |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 10.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 64 | °C |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 20 | °C |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 63 | °C |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 20 | °C |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 63 | °C |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | TX000122 | WithLTC | CO-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 20 | °C |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Counter Readings | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | General Comments | | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | FE000062 | Fence | 493-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | General Comments | TC | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | X0336 | RecloserElectronic | 581-1316 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | General Comments | | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | ST000211 | Structure | 581-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 29623 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LTCM000055 | LTCMechanism | CO-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 29623 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Switching Operations | 1 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Readings | Totalizer Meter Reading | .8210 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | ST000840 | Structure | 459-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | 9 Month Operations | 11 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Operations This Read Vac | 1 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Operations Counter AL | 283 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Amps C Ø | 40.0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Amps B Ø | 40.0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Amps A Ø | 50.0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 1.07 | % |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 1.07 | % |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | 9 Months Operations | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | YD000046 | Yard | 116-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Operations Counter AF | 193 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | 9 Month Operations | 3 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BAT000533 | Battery | 807-Battery Bank Distribution | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Counter Readings | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Mechanism Patrol Inspection | General Comments | oiul level at low | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Counter Readings | LTC As Found Counter | 530853 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Counter Readings | LTC As Left Counter | 530857 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | YD000798 | Yard | 362-2 Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | YD000798 | Yard | 362-2 Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Counter Readings | General Comments | | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | YD000798 | Yard | 362-2 Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | YD000798 | Yard | 362-2 Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | YD000798 | Yard | 362-2 Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | YD000798 | Yard | 362-2 Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | YD000798 | Yard | 362-2 Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | General Comments | | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 48 | °F |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Amps A Ø | 20.0 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Counter Readings | LTC Operations Since Last Insp | 179 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | LTCMechanism | 581-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Adequate | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BAT000512 | Battery | 875-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Operations Counter AF | 283 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Operations Counter AL | 193 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | K0142 | BreakerVacuum | 116-BT6-5 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | 9 Month Operations VCB New | 11 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Amps A Ø | 90.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Amps B Ø | 87.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Amps C Ø | 87.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Operations Counter AF | 411 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0186 | BreakerVacuum | CY-1486 | VCB Readings | Operations Counter AL | 411 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Readings | Oil Temp Max | 59 | °C |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Readings | LTC Totalizer Reading | 5911.20 | kw |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Readings | General Comments | | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | YD000798 | Yard | 362-2 Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | YD000798 | Yard | 362-2 Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Readings | General Comments | | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | YD000798 | Yard | 362-2 Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | YD000798 | Yard | 362-2 Yard | Yard Patrol Inspection | General Comments | | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | YD000798 | Yard | 362-2 Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | YD000798 | Yard | 362-2 Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | General Comments | 1 op - Trip Check | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Maintenance Operations | 1 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Operations Counter AF | 157 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Operations Counter AL | 158 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Operations This Read Vac | 1 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0180 | BreakerAirMagnetic | CK-0002 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0180 | BreakerAirMagnetic | CK-0002 | AMCB Readings | 9 Months Operations | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0180 | BreakerAirMagnetic | CK-0002 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0180 | BreakerAirMagnetic | CK-0002 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Readings | Totalizer Meter Reading | .9768 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 8000 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Readings | Oil Temp Max | 65 | °C |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0180 | BreakerAirMagnetic | CK-0002 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Readings | LTC Totalizer Reading | 7814.40 | kw |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Readings | General Comments | | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Readings | Oil Temp Max | 52 | °C |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 100.00 | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 105.00 | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3845.76 | kw |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | General Comments | | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | ST000473 | Structure | 807-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | BCH000801 | Charger | 362-2 Charger 2 | Battery Charger Patrol Insp | General Comments | | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | BCH000801 | Charger | 362-2 Charger 2 | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | BCH000801 | Charger | 362-2 Charger 2 | Battery Charger Patrol Insp | As Found Float Voltage | 52.5 | VDC |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | BCH000800 | Charger | 362-1 Charger 1 | Battery Charger Patrol Insp | General Comments | | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | BCH000800 | Charger | 362-1 Charger 1 | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | BCH000800 | Charger | 362-1 Charger 1 | Battery Charger Patrol Insp | As Found Float Voltage | 52.8 | VDC |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | General Comments | | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | YD000471 | Yard | 807-Yard | Yard Patrol Inspection | Ambient Temp | 43 | °F |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | General Comments | | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000771 | Structure | 362-2 Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0179 | BreakerAirMagnetic | CK-0001 | AMCB Readings | Unknown Operations | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0179 | BreakerAirMagnetic | CK-0001 | AMCB Readings | Switching Operations | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0179 | BreakerAirMagnetic | CK-0001 | AMCB Readings | Operations This Read AM | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0179 | BreakerAirMagnetic | CK-0001 | AMCB Readings | Operations Counter AL | 328 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0179 | BreakerAirMagnetic | CK-0001 | AMCB Readings | Operations Counter AF | 328 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0179 | BreakerAirMagnetic | CK-0001 | AMCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0179 | BreakerAirMagnetic | CK-0001 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0179 | BreakerAirMagnetic | CK-0001 | AMCB Readings | General Comments | | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0179 | BreakerAirMagnetic | CK-0001 | AMCB Patrol Inspection | General Comments | | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0179 | BreakerAirMagnetic | CK-0001 | AMCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0179 | BreakerAirMagnetic | CK-0001 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0179 | BreakerAirMagnetic | CK-0001 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0179 | BreakerAirMagnetic | CK-0001 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0179 | BreakerAirMagnetic | CK-0001 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0179 | BreakerAirMagnetic | CK-0001 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0179 | BreakerAirMagnetic | CK-0001 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0179 | BreakerAirMagnetic | CK-0001 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0179 | BreakerAirMagnetic | CK-0001 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Unknown Operations | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Switching Operations | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Operations This Read AM | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Operations Counter AL | 380 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Operations Counter AF | 380 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | General Comments | | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0179 | BreakerAirMagnetic | CK-0001 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0179 | BreakerAirMagnetic | CK-0001 | AMCB Readings | Amps C Ø | 100.0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0179 | BreakerAirMagnetic | CK-0001 | AMCB Readings | Amps B Ø | 100.0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0179 | BreakerAirMagnetic | CK-0001 | AMCB Readings | Amps A Ø | 50.0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0179 | BreakerAirMagnetic | CK-0001 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0179 | BreakerAirMagnetic | CK-0001 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0179 | BreakerAirMagnetic | CK-0001 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0179 | BreakerAirMagnetic | CK-0001 | AMCB Readings | 9 Months Operations | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0179 | BreakerAirMagnetic | CK-0001 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | 9 Month Operations | 7 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Ambient Temp | 62 | °F |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | YD000855 | Yard | 459-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Amps A Ø | 116.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Amps B Ø | 112.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Amps C Ø | 112.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0184 | BreakerVacuum | CY-1482 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | WithLTC | 875-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0180 | BreakerAirMagnetic | CK-0002 | AMCB Readings | Amps A Ø | 150.0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0180 | BreakerAirMagnetic | CK-0002 | AMCB Readings | Amps B Ø | 150.0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0180 | BreakerAirMagnetic | CK-0002 | AMCB Readings | Amps C Ø | 150.0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0180 | BreakerAirMagnetic | CK-0002 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0180 | BreakerAirMagnetic | CK-0002 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0180 | BreakerAirMagnetic | CK-0002 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0180 | BreakerAirMagnetic | CK-0002 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0180 | BreakerAirMagnetic | CK-0002 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0180 | BreakerAirMagnetic | CK-0002 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0180 | BreakerAirMagnetic | CK-0002 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0180 | BreakerAirMagnetic | CK-0002 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0180 | BreakerAirMagnetic | CK-0002 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0180 | BreakerAirMagnetic | CK-0002 | AMCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0180 | BreakerAirMagnetic | CK-0002 | AMCB Patrol Inspection | General Comments | | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0180 | BreakerAirMagnetic | CK-0002 | AMCB Readings | General Comments | | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0180 | BreakerAirMagnetic | CK-0002 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0180 | BreakerAirMagnetic | CK-0002 | AMCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0180 | BreakerAirMagnetic | CK-0002 | AMCB Readings | Operations Counter AF | 320 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0180 | BreakerAirMagnetic | CK-0002 | AMCB Readings | Operations Counter AL | 320 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0180 | BreakerAirMagnetic | CK-0002 | AMCB Readings | Operations This Read AM | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0180 | BreakerAirMagnetic | CK-0002 | AMCB Readings | Switching Operations | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0180 | BreakerAirMagnetic | CK-0002 | AMCB Readings | Unknown Operations | 0 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Counter Readings | General Comments | | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Mechanism Patrol Inspection | General Comments | ltc tank leaking | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Counter Readings | LTC As Found Counter | 75554 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Counter Readings | LTC As Left Counter | 75564 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Counter Readings | LTC Operations Since Last Insp | 517 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Low | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | LTCMechanism | 879-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | CB0254 | BreakerVacuum | 671-1504 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | 0272 | NonLTC | 031-5 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | General Comments | 1 trip check | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BCH000548 | Charger | 875-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BCH000548 | Charger | 875-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BCH000548 | Charger | 875-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Counter Readings | LTC Operations Since Last Insp | 795 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 3.0 | psi |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Amps A Ø | 20.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Amps B Ø | 260.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Amps C Ø | 19.0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BCH000548 | Charger | 875-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.6 | amps |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BCH000548 | Charger | 875-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BCH000548 | Charger | 875-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Operations This Read AM | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Switching Operations | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Unknown Operations | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | LTCC000947 | LTCControl | 116-6 | LTC Control Insp | All Connections OK? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | LTCC000947 | LTCControl | 116-6 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | LTCC000947 | LTCControl | 116-6 | LTC Control Insp | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | LTCC000947 | LTCControl | 116-6 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Fault Adjusted Amps C Phase V | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Fault Adjusted Amps B Phase V | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Fault Adjusted Amps A Phase V | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Amps C Ø | 81 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Amps B Ø | 94 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Operations Counter AL | 171 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Patrol Inspection | General Comments | | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | General Comments | DNO | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Operations Counter AF | 336 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Operations Counter AL | 336 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | LTCC000704 | LTCControl | 807-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Switching Operations | 1 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | M0081 | WithLTC | 879-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.7 | VDC |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.8 | VDC |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BAT000156 | Battery | 879-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Operations This Read Vac | 1 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Operations Counter AL | 298 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | 9 Month Operations | 6 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Operations Counter AF | 297 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Operations Counter AF | 323 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | General Comments | | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | LTCMechanism | CK-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Operations Counter AF | 204 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Operations Counter AL | 204 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | LTCMechanism | CK-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | LTCMechanism | CK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | LTCMechanism | CK-TRANS 1 | LTC Counter Readings | LTC Tank Desiccant | Good | check oil cup |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | LTCMechanism | CK-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 604 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | LTCMechanism | CK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | LTCMechanism | CK-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | LTCMechanism | CK-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | LTCMechanism | CK-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | LTCMechanism | CK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | LTCMechanism | CK-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 430568 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | LTCMechanism | CK-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 430568 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | LTCMechanism | CK-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | LTCMechanism | CK-TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | LTCMechanism | CK-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | PN35 | LTCMechanism | CK-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | WithLTC | CY-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Counter Readings | LTC As Left Counter | 44594 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Counter Readings | LTC As Found Counter | 44594 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | SWG000046 | Switchgear | CO-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Amps A Ø | 92 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Accumulated Fault Duty C Ph V | 9.07 | % |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Accumulated Fault Duty B Ph V | 10.89 | % |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | Accumulated Fault Duty A Ph V | 14.52 | % |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | 9 Month Operations VCB New | 3 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | WB0159 | BreakerVacuum | 862-0560 | VCB Readings | 9 Month Operations | 4 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | LTCC000947 | LTCControl | 116-6 | LTC Control Insp | LTC Output Voltage Level | 124.7 | VAC |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | LTCC000947 | LTCControl | 116-6 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | LTCC000947 | LTCControl | 116-6 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | LTCC000947 | LTCControl | 116-6 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | LTCMechanism | 807-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0185 | BreakerVacuum | CY-1483 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0121 | BreakerVacuum | 362-3622 | VCB Readings | Operations Counter AL | 323 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000204 | Switchgear | 459-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | General Comments | installed new counter/TC | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | General Comments | Some water inside cabinet, could not locate where coming in from. | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Operations Counter AL | 1424 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Operations Counter AF | 1424 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Patrol Inspection | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Amps C Ø | 100.0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Amps B Ø | 100.0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Amps A Ø | 100.0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | 9 Months Operations | 11 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | 9 Month Ops New | 9 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LTCC000737 | LTCControl | CY-TRANS 2 | LTC Control Insp | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LTCC000737 | LTCControl | CY-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 126282 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 126282 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | 9 Month Operations | 3 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 6L | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 13L | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 360 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | 9 Month Operations | 0 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Amps A Ø | 1.0 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Amps B Ø | 3.0 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Amps C Ø | 8.0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | LTCC000704 | LTCControl | 807-1 | LTC Control Insp | All Connections OK? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | LTCC000704 | LTCControl | 807-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | LTCC000704 | LTCControl | 807-1 | LTC Control Insp | General Comments | | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | LTCC000704 | LTCControl | 807-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | LTCC000704 | LTCControl | 807-1 | LTC Control Insp | LTC Output Voltage Level | 125.0 | VAC |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | LTCC000704 | LTCControl | 807-1 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | LTCC000704 | LTCControl | 807-1 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 20606 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 20606 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 7L | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 40 | °C |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 17 | °C |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 197 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LTCM000072 | LTCMechanism | CY-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Amps B Ø | 15.0 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Amps C Ø | 15.0 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | FE000807 | Fence | 459-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LTCC000737 | LTCControl | CY-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | WithLTC | CO-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 37 | °C |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Cabinet Internal Condition? | Water | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Switching Operations | 2 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0221 | BreakerAirMagnetic | CO-1192 | AMCB Readings | Operations This Read AM | 2 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000757 | Fence | 362-2 Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | General Comments | | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Operations Counter AF | 169 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Operations Counter AL | 169 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Operations Counter AF | 171 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LT0059 | LTCMechanism | CO-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Readings | LTC Totalizer Reading | 6642.00 | kw |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Readings | General Comments | | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 462 | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 93 | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 1.4 | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 2.1 | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 1.8 | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | DX0108 | RecloserHydraulic | 577-0467 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 82 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Maintenance Operations | 2 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Operations Counter AF | 173 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Operations Counter AL | 1 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Operations This Read Vac | 2 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | 9 Month Ops New | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | 9 Months Operations | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Amps A Ø | 0.0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Amps B Ø | 0.0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0248 | BreakerAirMagnetic | CB-SEC 1 SPARE | AMCB Readings | Amps C Ø | 0.0 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | WB0180 | BreakerVacuum | 581-1318 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Amps A Ø | 136.0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Amps B Ø | 151.0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Amps C Ø | 132.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Readings | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BK001585 | BreakerVacuum | 116-0688 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BK001284 | BreakerVacuum | 351-0689 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Readings | Winding Temp Present | 38 | °C |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Readings | Winding Temp Max | 45 | °C |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Readings | Totalizer Meter Reading | .3690 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | C0485 | WithLTC | 472-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Amps C Ø | 140.0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Amps B Ø | 160.0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Amps A Ø | 150.0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | 9 Month Operations | 2 | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | General Comments | | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BAT001604 | Battery | 529-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BAT001604 | Battery | 529-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BAT001604 | Battery | 529-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BAT001604 | Battery | 529-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BAT001604 | Battery | 529-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BAT001604 | Battery | 529-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BAT001604 | Battery | 529-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BAT001604 | Battery | 529-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BAT001604 | Battery | 529-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BAT001604 | Battery | 529-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BAT001604 | Battery | 529-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BAT001604 | Battery | 529-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BAT001604 | Battery | 529-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | General Comments | | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | Ambient Temp | 48 | °F |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Operations Counter AF | 202 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Fault Operations B Ø | 1 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | YD000416 | Yard | 769-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | General Comments | | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Switching Operations | 2 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Operations This Read Vac | 2 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Operations Counter AL | 185 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Operations Counter AF | 183 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | ST000535 | Structure | 472-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | General Comments | | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001600 | BreakerVacuum | 807-0120 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | General Comments | | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | FE000349 | Fence | 875-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Fault Adjusted Amps B Phase V | 12.90 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Amps C Ø | 100.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Amps B Ø | 115.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Amps A Ø | 105.0 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | 9 Month Operations | 1 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Readings | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Readings | LTC Totalizer Reading | 5109.12 | kw |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | n | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Min Tap Position | 16L | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | General Comments | | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0498 | Regulator | 577-1 [AB] | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Readings | Foundation Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Unreadable | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Readings | General Comments | | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1097.28 | kw |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 10.00 | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | W0268 | NonLTC | 758-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .4572 | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | n | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | General Comments | Metering equipment conduit in need of repair | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | 9 Month Operations | 4 | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | General Comments | | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | General Comments | | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Amps C Ø | 200.0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Amps B Ø | 220.0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Amps A Ø | 220.0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | 9 Months Operations | 3 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | 9 Month Ops New | 3 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Fault Operations C Ø | 1 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Fault Operations A Ø | 1 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Fault Adjusted Amps C Phase V | 6.27 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Fault Adjusted Amps A Phase V | 6.27 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Amps C Ø | 140.0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Amps B Ø | 130.0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Amps A Ø | 150.0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | 9 Month Operations | 2 | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | Ambient Temp | 40 | °F |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | General Comments | | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | General Comments | | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | General Comments | large washout across driveway in front of substation | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | Follow-up Action Required? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | n | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Operations This Read Vac | 2 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Operations Counter AL | 178 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Operations Counter AF | 177 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | BAT001664 | Battery | 671-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 52 | °F |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | BAT001664 | Battery | 671-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Amps C Ø | 0.0 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001601 | BreakerVacuum | 807-0121 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BCH001333 | Charger | 351-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BCH001333 | Charger | 351-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .6 | amps |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BCH001333 | Charger | 351-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BCH001333 | Charger | 351-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BCH001333 | Charger | 351-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BCH001333 | Charger | 351-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | Ambient Temp | 53 | °F |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Amps C Ø | 120.0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Amps B Ø | 125.0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Amps A Ø | 130.0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Readings | Non LTC Totalizer Reading | 2356.80 | kw |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | SWG000212 | Switchgear | 459-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Counter Readings | LTC Operations Since Last Insp | 522 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Amps B Ø | 0.0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Amps A Ø | 0.0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | 9 Months Operations | 10 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | 9 Month Ops New | 9 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Counter Readings | LTC As Left Counter | 69684 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Counter Readings | LTC As Found Counter | 69684 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Counter Readings | General Comments | | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | C0454 | LTCMechanism | 875-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | FE000409 | Fence | 769-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Readings | General Comments | | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | n | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | General Comments | | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | FE000055 | Fence | 577-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Switching Operations | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Unknown Operations | 0 | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | ST000418 | Structure | 769-Structure | Structure Patrol Inspection | Whips Correctly Engaged? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | SPR "System Normal" Light Lit | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | YD000531 | Yard | 472-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Operations Counter AF | 160 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Operations Counter AL | 160 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Counter Readings | LTC Operations Since Last Insp | 96 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Counter Readings | LTC As Left Counter | 79747 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Counter Readings | LTC As Found Counter | 79737 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Counter Readings | General Comments | | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | LTCMechanism | 671-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | BAT001417 | Battery | 862-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | BAT001417 | Battery | 862-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Operations Counter AL | 172 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | BAT001417 | Battery | 862-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | BAT001417 | Battery | 862-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | BAT001417 | Battery | 862-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | BAT001417 | Battery | 862-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | BAT001417 | Battery | 862-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 28.7 | VDC |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | BAT001417 | Battery | 862-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 28.7 | VDC |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | BAT001417 | Battery | 862-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | BAT001417 | Battery | 862-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 9075 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 9075 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 220 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Switching Operations | 2 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | LTCC000024 | LTCControl | 581-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | LTCC000024 | LTCControl | 581-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | LTCC000024 | LTCControl | 581-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | LTCC000024 | LTCControl | 581-1 | LTC Control Insp | LTC Output Voltage Level | 123.9 | VAC |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | LTCC000024 | LTCControl | 581-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | LTCC000024 | LTCControl | 581-1 | LTC Control Insp | General Comments | | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | LTCC000024 | LTCControl | 581-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | LTCC000024 | LTCControl | 581-1 | LTC Control Insp | All Connections OK? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | BAT001441 | Battery | 362-2 Battery Bank 2 | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | BAT001441 | Battery | 362-2 Battery Bank 2 | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | BAT001441 | Battery | 362-2 Battery Bank 2 | Battery Patrol Inspection | General Comments | | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | BAT001441 | Battery | 362-2 Battery Bank 2 | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | BAT001441 | Battery | 362-2 Battery Bank 2 | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | BAT001441 | Battery | 362-2 Battery Bank 2 | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | BAT001441 | Battery | 362-2 Battery Bank 2 | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | BAT001441 | Battery | 362-2 Battery Bank 2 | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | BAT001441 | Battery | 362-2 Battery Bank 2 | Battery Patrol Inspection | All Connections OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | General Comments | | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | BAT001440 | Battery | 362-1 Battery Bank 1 | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | BAT001440 | Battery | 362-1 Battery Bank 1 | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | BAT001440 | Battery | 362-1 Battery Bank 1 | Battery Patrol Inspection | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Amps C Ø | 347.0 | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | YD000093 | Yard | 493-Yard | Yard Patrol Inspection | Ambient Temp | 51 | °F |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Ambient Temp | 30 | °F |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Amps B Ø | 334.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Amps A Ø | 387.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | 9 Month Operations | 1 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 58 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 3 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 16 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 5 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 259644 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 259644 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0053 | LTCMechanism | CY-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | General Comments | | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Maintenance Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Operations Counter AF | 172 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | BAT001417 | Battery | 862-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | BAT001417 | Battery | 862-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 53 | °F |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | BAT001417 | Battery | 862-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | YD000078 | Yard | 362-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Readings | General Comments | Read Wrong  Meter | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Operations Counter AL | 28 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Operations Counter AF | 28 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | YD000078 | Yard | 362-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | YD000078 | Yard | 362-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | YD000078 | Yard | 362-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | YD000078 | Yard | 362-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | YD000078 | Yard | 362-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | YD000078 | Yard | 362-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Patrol Inspection | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | General Comments | | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | BAT001091 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | BAT001440 | Battery | 362-1 Battery Bank 1 | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | 9 Month Operations | -1 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | 9 Month Operations VCB New | -1 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Amps A Ø | 119.0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Amps B Ø | 93.0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Amps C Ø | 87.0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | BAT001440 | Battery | 362-1 Battery Bank 1 | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | BAT001440 | Battery | 362-1 Battery Bank 1 | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | BAT001440 | Battery | 362-1 Battery Bank 1 | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | BAT001440 | Battery | 362-1 Battery Bank 1 | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | BAT001440 | Battery | 362-1 Battery Bank 1 | Battery Patrol Inspection | All Connections OK? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Readings | Oil Temp Present | 32 | °C |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Readings | Oil Temp Max | 32 | °C |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | C0463 | WithLTC | 671-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Counter Readings | General Comments | | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Counter Readings | LTC As Found Counter | 165862 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Counter Readings | LTC As Left Counter | 165862 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Counter Readings | LTC Operations Since Last Insp | 440 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | LTCMechanism | 529-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | 9 Months Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Amps A Ø | 0.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Amps B Ø | 0.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Amps C Ø | 0.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | YD000078 | Yard | 362-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | YD000078 | Yard | 362-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | YD000078 | Yard | 362-Yard | Yard Patrol Inspection | General Comments | | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Readings | Totalizer Meter Reading | .8124 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Readings | Oil Temp Present | 33 | °C |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | General Comments | | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | BCH001055 | Charger | 862-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | BCH001055 | Charger | 862-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | BCH001055 | Charger | 862-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | BCH001055 | Charger | 862-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.2 | amps |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | BCH001055 | Charger | 862-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 56.3 | VDC |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | BCH001055 | Charger | 862-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 56.3 | VDC |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | YD000093 | Yard | 493-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | YD000318 | Yard | 581-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | 9 Month Operations | 4 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Amps A Ø | 130.0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Amps B Ø | 130.0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Amps C Ø | 140.0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Readings | Totalizer Meter Reading | .5322 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Readings | General Comments | | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Readings | LTC Totalizer Reading | 3899.52 | kw |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Readings | Winding Temp Max | 30 | °C |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Readings | Winding Temp Present | 20 | °C |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | WithLTC | 116-6 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | W0296 | WithLTC | 581-1 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000048 | Switchgear | CB-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | 9 Month Operations | -1 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | 9 Month Operations VCB New | -1 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Amps A Ø | 92.0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Amps B Ø | 83.0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002049 | BreakerVacuum | 176-0075 | VCB Readings | Amps C Ø | 89.0 | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | General Comments | corner of foundation next to house is crumbling, multiple insulators are crakced and chipped in the steel | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Readings | Oil Temp Max | 56 | °C |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Readings | Oil Temp Present | 32 | °C |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | YD000093 | Yard | 493-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | YD000093 | Yard | 493-Yard | Yard Patrol Inspection | General Comments | | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | YD000093 | Yard | 493-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | YD000093 | Yard | 493-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | YD000093 | Yard | 493-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | YD000093 | Yard | 493-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | YD000093 | Yard | 493-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | YD000093 | Yard | 493-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | YD000093 | Yard | 493-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Operations Counter AL | 13 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Operations Counter AF | 13 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001963 | BreakerVacuum | CY-14KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Oil Temp Max | 50 | °C |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Nitrogen Blanket Pressure | .3 | psi |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | YD000093 | Yard | 493-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Operations Counter AF | 180 | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | BAT001091 | Battery | Retired Distribution | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | BAT001091 | Battery | Retired Distribution | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | BAT001091 | Battery | Retired Distribution | Battery Patrol Inspection | Positive DC Ground | .1 | VDC |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | BAT001091 | Battery | Retired Distribution | Battery Patrol Inspection | Negative DC Ground | .1 | VDC |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | BAT001091 | Battery | Retired Distribution | Battery Patrol Inspection | General Comments | | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | BAT001091 | Battery | Retired Distribution | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | BAT001091 | Battery | Retired Distribution | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Operations Counter AL | 182 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001259 | BreakerVacuum | 875-0068 | VCB Readings | Operations This Read Vac | 2 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | PF000115 | PowerFuse | DA-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | ST000208 | Structure | 758-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | PF000115 | PowerFuse | DA-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 541236 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 541236 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | ST000100 | Structure | 493-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0311 | NonLTC | 493-2 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LT0248 | GroundTransformer | CY-GND TR 1 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0312 | NonLTC | 493-2 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 737 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | LTCMechanism | CB-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | 9 Month Operations | 7 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Amps A Ø | 160.0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Amps B Ø | 160.0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Amps C Ø | 160.0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Operations Counter AF | 198 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Operations Counter AL | 198 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0173 | BreakerVacuum | 116-5 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Operations Counter AF | 182 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Operations Counter AL | 182 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | 9 Month Operations | 15 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Amps C Ø | 220.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Operations Counter AF | 185 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Operations Counter AL | 185 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | 9 Month Operations | 2 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Amps A Ø | 320.0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Amps B Ø | 320.0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Amps C Ø | 335.0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | General Comments | | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | General Comments | | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | General Comments | | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Operations Counter AF | 369 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Operations Counter AL | 369 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Operations Counter AL | 84 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Operations Counter AF | 84 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Amps C Ø | 95.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Amps B Ø | 70.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Amps A Ø | 55.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | 9 Month Operations | 6 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Amps C Ø | 0.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Amps B Ø | 0.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Amps A Ø | 0.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | TR in Vacuum | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Operations Counter AL | 141 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Operations Counter AF | 141 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | General Comments | | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | General Comments | | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Amps C Ø | 520.0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Amps B Ø | 520.0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Amps A Ø | 530.0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Operations Counter AF | 229 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Operations Counter AL | 231 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001604 | BreakerVacuum | 807-1 | VCB Readings | 9 Month Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Operations Counter AL | 199 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Operations Counter AF | 199 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Operations This Read Vac | 2 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Counter Readings | LTC As Left Counter | 86064 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Counter Readings | LTC As Found Counter | 86059 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Counter Readings | General Comments | | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Amps A Ø | 100.0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Amps B Ø | 100.0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Amps C Ø | 100.0 | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BCH001153 | Charger | 472-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BCH001153 | Charger | 472-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BCH001153 | Charger | 472-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BCH001153 | Charger | 472-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BCH001153 | Charger | 472-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .8 | amps |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BCH001153 | Charger | 472-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BCH001153 | Charger | 472-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | BCH001153 | Charger | 472-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | General Comments | | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | LTCC000327 | LTCControl | 671-1 | LTC Control Insp | VRR Time Delay | 40 | Seconds |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | LTCC000327 | LTCControl | 671-1 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | LTCC000327 | LTCControl | 671-1 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | LTCC000327 | LTCControl | 671-1 | LTC Control Insp | LTC Output Voltage Level | 123.4 | VAC |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | LTCC000327 | LTCControl | 671-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | ST000274 | Structure | 671-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | General Comments | | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | LTCC000327 | LTCControl | 671-1 | LTC Control Insp | General Comments | | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | LTCC000327 | LTCControl | 671-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | LTCC000327 | LTCControl | 671-1 | LTC Control Insp | All Connections OK? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Readings | Totalizer Meter Reading | .8240 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Readings | Oil Temp Max | 41 | °C |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Readings | LTC Totalizer Reading | 7910.40 | kw |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Readings | General Comments | | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Operations Counter AL | 237 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Operations Counter AF | 237 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001135 | BreakerVacuum | 459-0293 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | WithLTC | 080-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | General Comments | | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Counter Readings | LTC Operations Since Last Insp | 571 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | 9 Month Ops New | 4 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | 9 Months Operations | 5 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | LTCM000025 | LTCMechanism | 472-1 | LTC Counter Readings | LTC Min Tap Position | 12L | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | 9 Month Operations VCB New | 13 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | General Comments | | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | 9 Month Operations | 1 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Amps A Ø | 190.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001138 | BreakerVacuum | 459-2 | VCB Readings | Amps B Ø | 220.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | 9 Month Operations | 1 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Amps A Ø | 112.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Amps B Ø | 102.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Amps C Ø | 98.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Trash Emptied? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Restroom Clean & OK? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | 9 Month Operations | 10 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | 9 Month Operations VCB New | 10 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Amps A Ø | 105.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Amps B Ø | 108.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Amps C Ø | 106.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Fault Operations Ground | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0183 | BreakerVacuum | CY-1481 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0187 | BreakerVacuum | CY-1487 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Patrol Inspection | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Operations Counter AF | 794 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Operations Counter AL | 794 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Operations This Read AM | 1 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0226 | BreakerAirMagnetic | CO-1195 | AMCB Readings | Switching Operations | 1 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Operations Counter AF | 195 | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Operations Counter AL | 197 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Operations This Read Vac | 2 | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Switching Operations | 2 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 46561 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 125.3 | volts |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | YD000267 | Yard | 671-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | ST000024 | Structure | 351-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Amps C Ø | 80.0 | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Amps B Ø | 65.0 | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | BK001120 | BreakerVacuum | 769-0027 | VCB Readings | Amps A Ø | 75.0 | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BAT001416 | Battery | 351-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BAT001416 | Battery | 351-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | LTCC000761 | LTCControl | 879-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Switching Operations | 2 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Operations This Read Vac | 2 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Operations Counter AL | 207 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Operations Counter AF | 205 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | General Comments | | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Switching Operations | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Operations This Read AM | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Operations Counter AL | 556 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Operations Counter AF | 556 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Patrol Inspection | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | LTCC000761 | LTCControl | 879-1 | LTC Control Insp | VRR Time Delay | 45 | Seconds |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | General Comments | | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Operations Counter AF | 697 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Operations Counter AL | 697 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Amps C Ø | 120.0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Amps B Ø | 120.0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Amps A Ø | 130.0 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1 | psi |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Operations Counter AL | 836 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Operations Counter AF | 836 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Patrol Inspection | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | LTCC000761 | LTCControl | 879-1 | LTC Control Insp | LTC Output Voltage Level | 124.7 | VAC |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | LTCC000761 | LTCControl | 879-1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | LTCC000761 | LTCControl | 879-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Operations Counter AL | 42 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Operations Counter AF | 42 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Amps C Ø | 0.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Amps B Ø | 0.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Amps A Ø | 0.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001977 | BreakerVacuum | CY-GND TR 2 | VCB Readings | 9 Month Operations | 2 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Amps A Ø | 110.0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Amps B Ø | 150.0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Amps C Ø | 120.0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BAT001416 | Battery | 351-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BAT001416 | Battery | 351-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 49 | °F |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Operations Counter AF | 506 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Operations Counter AL | 506 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Operations This Read AM | 0 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BAT001416 | Battery | 351-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BAT001416 | Battery | 351-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Low | If low,note cell #~'s |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BAT001416 | Battery | 351-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BAT001416 | Battery | 351-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BAT001416 | Battery | 351-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BAT001416 | Battery | 351-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.3 | VDC |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BAT001416 | Battery | 351-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.2 | VDC |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BAT001416 | Battery | 351-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BAT001416 | Battery | 351-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Operations Counter AF | 199 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Operations Counter AL | 201 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Operations This Read Vac | 2 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Switching Operations | 2 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | 9 Month Operations | 2 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Amps A Ø | 268.0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Amps B Ø | 252.0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Amps C Ø | 265.0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Switching Operations | 2 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Operations This Read Vac | 2 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Operations Counter AL | 187 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Operations Counter AF | 185 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Readings | General Comments | | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002043 | BreakerVacuum | 176-5 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | BAT001664 | Battery | 671-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | BAT001664 | Battery | 671-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | BAT001664 | Battery | 671-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.9 | VDC |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | BAT001664 | Battery | 671-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 28.1 | VDC |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | BAT001664 | Battery | 671-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | BAT001664 | Battery | 671-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | BAT001664 | Battery | 671-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | BAT001664 | Battery | 671-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | BAT001664 | Battery | 671-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | BAT001664 | Battery | 671-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BCH001333 | Charger | 351-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.400 | millivolts |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | BCH001333 | Charger | 351-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001399 | BreakerVacuum | 807-0123 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | YD000054 | Yard | 577-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001602 | BreakerVacuum | 807-0122 | VCB Readings | 9 Month Operations | 3 | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0230 | BreakerAirMagnetic | CO-12KV TR 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | General Comments | Multiple insulators have chipped and broken skirts above transformers | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | 9 Month Operations | 2 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Amps A Ø | 100.0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Amps B Ø | 105.0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Amps C Ø | 100.0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | ST000059 | Structure | 577-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | General Comments | | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001258 | BreakerVacuum | 875-0066 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Patrol Inspection | General Comments | | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | General Comments | | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Amps C Ø | 22.0 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Amps B Ø | 28.0 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Amps A Ø | 51.0 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Readings | Totalizer Meter Reading | .9820 | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | General Comments | | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1304 | Regulator | 362-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 48601 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 125.3 | volts |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | FE000219 | Fence | 862-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | General Comments | | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | FE000465 | Fence | 807-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Switching Operations | 2 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Operations This Read Vac | 2 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Operations Counter AL | 177 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Operations Counter AF | 175 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001979 | BreakerVacuum | CY-SPARE | VCB Readings | 9 Month Operations | 0 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Switching Operations | 2 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001257 | BreakerVacuum | 875-0065 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | 9 Month Operations | 14 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | 9 Month Operations VCB New | 14 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Amps A Ø | 130.0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Amps B Ø | 150.0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Amps C Ø | 160.0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 14:17 | Distribution | Eddyville Prison Quarterly Inspection | FE000265 | Fence | 671-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | General Comments | | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Amps C Ø | 0.0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Amps B Ø | 0.0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Amps A Ø | 0.0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | 9 Month Operations | 1 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.2 | psi |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Amps C Ø | 186.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Amps B Ø | 193.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Amps A Ø | 203.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | 9 Month Operations | 2 | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Readings | Oil Temp Present | 33 | °C |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Readings | Oil Temp Max | 52 | °C |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | 9 Month Ops New | 3 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | 9 Months Operations | 3 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0243 | BreakerAirMagnetic | CB-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN67 | WithLTC | CB-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Switching Operations | 1 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0223 | BreakerAirMagnetic | CO-1194 | AMCB Readings | Operations This Read AM | 1 | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | LTCC000761 | LTCControl | 879-1 | LTC Control Insp | All Connections OK? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | LTCC000761 | LTCControl | 879-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | LTCC000761 | LTCControl | 879-1 | LTC Control Insp | General Comments | | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | LTCC000761 | LTCControl | 879-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:34 | Distribution | Eddyville Quarterly Inspection | KT0047 | NonLTC | 862-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | B0313 | NonLTC | 493-2 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Operations Counter AL | 49 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BB0367 | BreakerVacuum | 529-0091 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | FE000835 | Fence | 879-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Operations Counter AF | 49 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1303 | Regulator | 362-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 46911 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 125.2 | volts |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | R1302 | Regulator | 362-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BK001603 | BreakerVacuum | 807-0141 | VCB Readings | 9 Month Operations | 2 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Operations This Read Vac | 1 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001134 | BreakerVacuum | 459-0292 | VCB Readings | Operations Counter AL | 202 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | KB0038 | BreakerVacuum | 080-4476 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001978 | BreakerVacuum | CY-14KV TR 2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 105.00 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Readings | General Comments | | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | 9 Month Operations | 8 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Operations Counter AF | 158 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Operations Counter AL | 158 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Operations This Read Vac | 2 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Switching Operations | 2 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Counter Readings | General Comments | | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Counter Readings | LTC As Found Counter | 156708 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Counter Readings | LTC As Left Counter | 156708 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Counter Readings | LTC Max Tap Position | 2R | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Counter Readings | LTC Operations Since Last Insp | 228 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | LTCMechanism | 176-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | General Comments | Entrance tree needs attention!!! | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | YD000201 | Yard | 758-Yard | Yard Patrol Inspection | Ambient Temp | 51 | °F |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | General Comments | Barbed wire rusty and droopping in areas. | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 24 | °C |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Counter Readings | LTC Operations Since Last Insp | 415 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | 9 Month Operations | 4 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | FE000203 | Fence | 758-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Counter Readings | General Comments | | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | FE000315 | Fence | 581-Fence | Fence Patrol Inspection | General Comments | | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Amps A Ø | 190.0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Amps B Ø | 215.0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Amps C Ø | 200.0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Readings | Oil Temp Present | 29 | °C |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Readings | Oil Temp Max | 41 | °C |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | O0167 | NonLTC | 362-2-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 100.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 40 | °C |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 25 | °C |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Operations Counter AL | 264 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Operations Counter AF | 264 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | General Comments | | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Operations Counter AL | 278 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Operations Counter AF | 278 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Counter Readings | LTC Operations Since Last Insp | 367 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Mechanism Patrol Inspection | MFD Breather green light | OK | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCC000611 | LTCControl | 459-1 | LTC Control Insp | All Connections OK? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCC000611 | LTCControl | 459-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCC000611 | LTCControl | 459-1 | LTC Control Insp | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCC000611 | LTCControl | 459-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCC000611 | LTCControl | 459-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCC000611 | LTCControl | 459-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCC000611 | LTCControl | 459-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Counter Readings | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Counter Readings | LTC As Found Counter | 158642 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Counter Readings | LTC As Left Counter | 158646 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Counter Readings | LTC Min Tap Position | 4L | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Counter Readings | LTC Operations Since Last Insp | 60 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0231 | LTCMechanism | 116-6 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCC000611 | LTCControl | 459-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Switching Operations | 1 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Operations This Read Vac | 1 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Operations Counter AL | 244 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Operations Counter AF | 244 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | General Comments | | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | BCH001034 | Charger | CB-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | BCH001034 | Charger | CB-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | BCH001034 | Charger | CB-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | BCH001034 | Charger | CB-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | BCH001034 | Charger | CB-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.8 | VDC |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | BCH001034 | Charger | CB-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.8 | VDC |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | BCH001034 | Charger | CB-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | 9 Months Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Amps A Ø | 0.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Amps B Ø | 0.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Amps C Ø | 0.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Patrol Inspection | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .2 | psi |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Operations Counter AF | 99968 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Operations Counter AL | 99968 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 38 | °C |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 40 | °C |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 30 | °C |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Max | 35 | °C |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Readings | X2 Winding Temp Present | 28 | °C |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Max | 40 | °C |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Readings | X3 Winding Temp Present | 28 | °C |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Counter Readings | LTC As Found Counter | 27662 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Operations This Read AM | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Switching Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0188 | BreakerAirMagnetic | CY-1488 | AMCB Readings | Unknown Operations | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Operations Counter AF | 161 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Operations Counter AL | 161 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Counter Readings | LTC As Left Counter | 27662 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002056 | BreakerVacuum | 529-0042 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0181 | BreakerAirMagnetic | CK-0003 | AMCB Readings | Unknown Operations | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0181 | BreakerAirMagnetic | CK-0003 | AMCB Readings | Switching Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000016 | LTCMechanism | 459-1 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCC000793 | LTCControl | 459-2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCC000793 | LTCControl | 459-2 | LTC Control Insp | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCC000793 | LTCControl | 459-2 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Readings | Oil Temp Max | 65 | °C |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Readings | LTC Totalizer Reading | 12892.32 | kw |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 122.9 | volts |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Readings | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCC000793 | LTCControl | 459-2 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCC000793 | LTCControl | 459-2 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Min Tap Position | 13L | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCC000793 | LTCControl | 459-2 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCC000793 | LTCControl | 459-2 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | General Comments | | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/5/2023 11:05 | Distribution | Black Mountain Quarterly Inspection | R0499 | Regulator | 577-1 [AC] | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 85667 | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.7 | volts |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Fault Operations A Ø | 1 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Fault Adjusted Amps A Phase V | 4.94 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCC000793 | LTCControl | 459-2 | LTC Control Insp | All Connections OK? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0495 | Regulator | 758-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0494 | Regulator | 758-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 91299 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Counter Readings | LTC Current Tap Position | 9L | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Counter Readings | LTC Max Tap Position | 3L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Readings | Oil Temp Present | 29 | °C |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Readings | Oil Temp Max | 89 | °C |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 65.00 | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 70.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 50 | °C |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Readings | General Comments | | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Readings | Equipment Properly Labeled? | y | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 12:31 | Distribution | Lynch Quarterly Inspection | M0004 | NonLTC | 031-5 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 1000 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BCH001244 | Charger | 807-Battery Charger Distribution | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BCH001244 | Charger | 807-Battery Charger Distribution | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BCH001244 | Charger | 807-Battery Charger Distribution | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BCH001244 | Charger | 807-Battery Charger Distribution | Battery Charger Patrol Insp | Battery Charger Current | 4.0 | amps |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BCH001244 | Charger | 807-Battery Charger Distribution | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BCH001244 | Charger | 807-Battery Charger Distribution | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BCH001244 | Charger | 807-Battery Charger Distribution | Battery Charger Patrol Insp | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Readings | Totalizer Meter Reading | .9410 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Readings | Winding Temp Max | 35 | °C |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Readings | Winding Temp Present | 25 | °C |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | BCH001244 | Charger | 807-Battery Charger Distribution | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Readings | General Comments | | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Operations Counter AF | 162 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | General Comments | | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | ST000066 | Structure | 362-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | SWG000061 | Switchgear | CB-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Readings | Kwh Reading | 42552 | KwH |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Readings | LTC Totalizer Reading | 941.00 | kw |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Readings | MegaVar Demand Meter Max | .92 | MegaVars |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Readings | MegaWatt Demand Meter Max | 4.62 | MegaWatts |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1550 | psi |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Counter Readings | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Counter Readings | LTC As Found Counter | 13575 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | LTCM000087 | LTCMechanism | 459-2 | LTC Counter Readings | LTC As Left Counter | 13575 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Amps C Ø | 62.0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Amps B Ø | 64.0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Amps A Ø | 64.0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Regulator As Left Counter | 162918 | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BAT001624 | Battery | 116-Battery Bank Control House | Battery Patrol Inspection | All Connections OK? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | General Comments | | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Operations Counter AF | 167 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Operations Counter AL | 167 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BAT001624 | Battery | 116-Battery Bank Control House | Battery Patrol Inspection | Battery Area Ambient Temp | 68 | °F |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BAT001624 | Battery | 116-Battery Bank Control House | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BAT001624 | Battery | 116-Battery Bank Control House | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BAT001624 | Battery | 116-Battery Bank Control House | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BAT001624 | Battery | 116-Battery Bank Control House | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BAT001624 | Battery | 116-Battery Bank Control House | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BAT001624 | Battery | 116-Battery Bank Control House | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BAT001624 | Battery | 116-Battery Bank Control House | Battery Patrol Inspection | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BAT001624 | Battery | 116-Battery Bank Control House | Battery Patrol Inspection | Negative DC Ground | 67.0 | VDC |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0181 | BreakerAirMagnetic | CK-0003 | AMCB Readings | Operations Counter AF | 280 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0181 | BreakerAirMagnetic | CK-0003 | AMCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0181 | BreakerAirMagnetic | CK-0003 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0181 | BreakerAirMagnetic | CK-0003 | AMCB Readings | General Comments | | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0181 | BreakerAirMagnetic | CK-0003 | AMCB Patrol Inspection | General Comments | | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0181 | BreakerAirMagnetic | CK-0003 | AMCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0181 | BreakerAirMagnetic | CK-0003 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0181 | BreakerAirMagnetic | CK-0003 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0181 | BreakerAirMagnetic | CK-0003 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0181 | BreakerAirMagnetic | CK-0003 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0181 | BreakerAirMagnetic | CK-0003 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0181 | BreakerAirMagnetic | CK-0003 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0181 | BreakerAirMagnetic | CK-0003 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0181 | BreakerAirMagnetic | CK-0003 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0181 | BreakerAirMagnetic | CK-0003 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0181 | BreakerAirMagnetic | CK-0003 | AMCB Readings | Amps C Ø | 50.0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | BAT001427 | Battery | CK-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Operations Counter AF | 808 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Operations Counter AL | 808 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Operations This Read AM | 1 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Switching Operations | 1 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | BAT001427 | Battery | CK-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | BAT001427 | Battery | CK-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | BAT001427 | Battery | CK-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | BAT001427 | Battery | CK-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | BAT001427 | Battery | CK-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | BAT001427 | Battery | CK-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | BAT001427 | Battery | CK-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Switching Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Operations Counter AL | 176 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Operations Counter AF | 176 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | General Comments | | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1026 | Regulator | 493-2 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.5 | volts |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | 9 Month Operations | 2 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0181 | BreakerAirMagnetic | CK-0003 | AMCB Readings | Operations This Read AM | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0181 | BreakerAirMagnetic | CK-0003 | AMCB Readings | Operations Counter AL | 280 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Amps A Ø | 45.0 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Amps B Ø | 23.0 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Amps C Ø | 77.0 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Readings | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Readings | LTC Totalizer Reading | 7464.96 | kw |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Readings | Oil Temp Max | 27 | °C |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Readings | Oil Temp Present | 27 | °C |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | General Comments | | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | CH000440 | ControlHouse | CB-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | CH000440 | ControlHouse | CB-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | CH000440 | ControlHouse | CB-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BCH001552 | Charger | 116-Battery Charger Control House | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 10.000 | millivolts |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BCH001552 | Charger | 116-Battery Charger Control House | Battery Charger Patrol Insp | As Found Float Voltage | 133.7 | VDC |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BCH001552 | Charger | 116-Battery Charger Control House | Battery Charger Patrol Insp | As Left Float Voltage | 133.7 | VDC |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BCH001552 | Charger | 116-Battery Charger Control House | Battery Charger Patrol Insp | Battery Charger Current | 4.2 | amps |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BCH001552 | Charger | 116-Battery Charger Control House | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BCH001552 | Charger | 116-Battery Charger Control House | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BCH001552 | Charger | 116-Battery Charger Control House | Battery Charger Patrol Insp | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BCH001552 | Charger | 116-Battery Charger Control House | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | FE000892 | Fence | 529-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | LTCC000666 | LTCControl | 769-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | LTCC000666 | LTCControl | 769-1 | LTC Control Insp | VRR Base Voltage AL | 125.0 | VAC |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | LTCC000666 | LTCControl | 769-1 | LTC Control Insp | VRR Base Voltage AF | 125.0 | VAC |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | LTCC000666 | LTCControl | 769-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | LTCC000666 | LTCControl | 769-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | LTCC000666 | LTCControl | 769-1 | LTC Control Insp | General Comments | | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | LTCC000666 | LTCControl | 769-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | LTCC000666 | LTCControl | 769-1 | LTC Control Insp | All Connections OK? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | 9 Month Operations | 6 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Amps A Ø | 152.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Amps B Ø | 105.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Amps C Ø | 119.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB1289 | BreakerVacuum | CY-1484 | VCB Readings | Fault Adjusted Amps B Phase V | 8.00 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0181 | BreakerAirMagnetic | CK-0003 | AMCB Readings | Amps B Ø | 100.0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0181 | BreakerAirMagnetic | CK-0003 | AMCB Readings | Amps A Ø | 50.0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0181 | BreakerAirMagnetic | CK-0003 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0181 | BreakerAirMagnetic | CK-0003 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0181 | BreakerAirMagnetic | CK-0003 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0181 | BreakerAirMagnetic | CK-0003 | AMCB Readings | 9 Months Operations | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | LB0181 | BreakerAirMagnetic | CK-0003 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/5/2023 12:40 | Distribution | Verda Quarterly Inspection | BK000733 | BreakerVacuum | 879-4479 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Max Tap Position | 6R | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Min Tap Position | 4L | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | TR nitro 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Readings | LV Winding Temp Max | 75 | °C |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Readings | LV Winding Temp Present | 30 | °C |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | PN44 | WithLTC | CB-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BAT001624 | Battery | 116-Battery Bank Control House | Battery Patrol Inspection | Positive DC Ground | 66.0 | VDC |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BAT001624 | Battery | 116-Battery Bank Control House | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Amps C Ø | 505.0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Amps B Ø | 513.0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Amps A Ø | 494.0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000684 | BreakerVacuum | CO-12KV TR 1 | VCB Readings | 9 Month Operations | 1 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Operations This Read Vac | 3 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | BK000683 | BreakerVacuum | CO-1196 | VCB Readings | Operations Counter AL | 156 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | BAT001624 | Battery | 116-Battery Bank Control House | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | CH000440 | ControlHouse | CB-Battery Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | CH000440 | ControlHouse | CB-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | R1338 | Regulator | 351-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 158667 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | O0230 | WithLTC | 116-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 28 | °C |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | 9 Month Operations | 6 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | 9 Month Operations | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Switching Operations | 1 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Operations This Read Vac | 1 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Operations Counter AL | 222 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Operations Counter AF | 221 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | PF000074 | PowerFuse | CY-14KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | PF000074 | PowerFuse | CY-14KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 40 | °C |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 30 | °C |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 40 | °C |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 28 | °C |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | PF000073 | PowerFuse | CY-14KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | OK | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | PF000073 | PowerFuse | CY-14KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | BAT001072 | Battery | CB-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Operations Counter AF | 157 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Operations Counter AL | 157 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | PF000072 | PowerFuse | CY-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | OK | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | PF000072 | PowerFuse | CY-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | 9 Month Operations | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | General Comments | | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Amps C Ø | 0.0 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Amps B Ø | 0.0 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Amps A Ø | 0.0 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | K0116 | BreakerVacuum | 362-4628 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Amps C Ø | 180.0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Amps B Ø | 180.0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Amps A Ø | 180.0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | MB0174 | BreakerVacuum | 116-6 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | BK002076 | BreakerVacuum | 529-608 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1300 | psi |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 40 | °C |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Amps C Ø | 0.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Amps B Ø | 0.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Amps A Ø | 0.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | 9 Month Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Amps C Ø | 28.0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Amps B Ø | 30.0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Amps A Ø | 30.0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | 9 Month Operations | 2 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | 9 Month Operations | 0 | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | PF000097 | PowerFuse | DA-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | PF000097 | PowerFuse | DA-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | PF000096 | PowerFuse | DA-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | PF000096 | PowerFuse | DA-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | PF000095 | PowerFuse | DA-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | PF000095 | PowerFuse | DA-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | PF000094 | PowerFuse | CO-12KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | PF000094 | PowerFuse | CO-12KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | PF000093 | PowerFuse | CO-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | PF000093 | PowerFuse | CO-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | PF000092 | PowerFuse | CO-12KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | PF000092 | PowerFuse | CO-12KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | CH000440 | ControlHouse | CB-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | PF000091 | PowerFuse | CO-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | PF000091 | PowerFuse | CO-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | CH000440 | ControlHouse | CB-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Regulator As Left Counter | 151725 | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | BAT001427 | Battery | CK-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | BAT001427 | Battery | CK-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | BAT001427 | Battery | CK-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | BAT001427 | Battery | CK-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | BAT001427 | Battery | CK-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | BAT001427 | Battery | CK-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | CH000440 | ControlHouse | CB-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | CH000440 | ControlHouse | CB-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | 9 Months Operations | 1 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Amps A Ø | 0.0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Amps B Ø | 0.0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Amps C Ø | 0.0 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/5/2023 12:22 | Distribution | Collins Quarterly Inspection | LB0228 | BreakerAirMagnetic | CO-12KV BUS TIE SEC 2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | General Comments | | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | General Comments | | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1025 | Regulator | 493-2 B | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:17 | Distribution | Campbellsville Industrial Quarterly Inspection | KB0106 | BreakerVacuum | 472-0207 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Amps C Ø | 60.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Amps B Ø | 65.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Amps A Ø | 60.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Operations Counter AL | 126 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Operations Counter AF | 126 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK000435 | BreakerVacuum | 459-0191 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Patrol Inspection | General Comments | | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | General Comments | DNO | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Operations Counter AF | 326 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Operations Counter AL | 326 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Operations This Read AM | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Switching Operations | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Unknown Operations | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Operations This Read AM | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Switching Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Unknown Operations | 0 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 234 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 77497 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 77497 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | 9 Month Ops New | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | 9 Months Operations | 0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Amps A Ø | 0.0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Amps B Ø | 0.0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Amps C Ø | 0.0 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Amps C Ø | 114.0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Amps B Ø | 112.0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Amps A Ø | 90.0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Counter Readings | LTC Current Tap Position | Neutral | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Counter Readings | LTC Max Tap Position | 6R | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | 9 Month Operations | 3 | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | LB0249 | BreakerAirMagnetic | CB-SEC 2 SPARE | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Counter Readings | LTC Operations Since Last Insp | 539 | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | BAT001088 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | BAT001088 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | BAT001088 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | BAT001088 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .1164 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | BAT001088 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | BAT001088 | Battery | Retired Distribution | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | BAT001088 | Battery | Retired Distribution | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | BAT001088 | Battery | Retired Distribution | Battery Patrol Inspection | General Comments | cabinet in need of repair or sealing. Wasps heavy inside, covered and taped, but may not hold for fututre | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Readings | Totalizer Meter Reading | .3820 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Readings | Oil Temp Max | 38 | °C |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 279.36 | kw |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Readings | Totalizer Meter Reading | .7080 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Readings | Winding Temp Max | 35 | °C |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Readings | Winding Temp Present | 30 | °C |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Operations Counter AL | 152 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Operations Counter AF | 152 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Amps C Ø | 55.0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002050 | BreakerVacuum | 176-0076 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | SWG000016 | Switchgear | CK-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | SWG000016 | Switchgear | CK-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | SWG000016 | Switchgear | CK-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | SWG000016 | Switchgear | CK-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | SWG000016 | Switchgear | CK-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | SWG000016 | Switchgear | CK-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | SWG000016 | Switchgear | CK-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | SWG000016 | Switchgear | CK-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | SWG000016 | Switchgear | CK-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | SWG000016 | Switchgear | CK-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Unknown Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Switching Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Operations This Read AM | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Operations Counter AL | 433 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | LB0189 | BreakerAirMagnetic | CY-1489 | AMCB Readings | Operations Counter AF | 433 | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | BAT001088 | Battery | Retired Distribution | Battery Patrol Inspection | All Connections OK? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | SWG000005 | Switchgear | CY-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1500 | psi |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | General Comments | | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | 9 Month Operations | 2 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | 9 Month Operations | 1 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Counter Readings | General Comments | | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Counter Readings | LTC As Found Counter | 80000 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Amps A Ø | 0.0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Readings | Winding Temp Max | 65 | °C |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Switching Operations | 1 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Operations This Read Vac | 1 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Operations Counter AL | 162 | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.0 | volts |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 72443 | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Operations Counter AF | 525 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Operations Counter AL | 525 | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Readings | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Readings | Kwh Reading | 9026 | KwH |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Readings | LTC Totalizer Reading | 16992.00 | kw |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Amps B Ø | 125.0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Amps A Ø | 90.0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Readings | LTC Totalizer Reading | 20256.00 | kw |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Accumulated Fault Duty C Ph AM | 17.08 | % |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Accumulated Fault Duty B Ph AM | 17.08 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Accumulated Fault Duty A Ph AM | 18.14 | % |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | 9 Months Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Readings | General Comments | | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Operations Counter AF | 43 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Operations Counter AL | 43 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Readings | Oil Temp Present | 28 | °C |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Operations Counter AF | 162 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | General Comments | | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Amps B Ø | 0.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Amps C Ø | 0.0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/5/2023 15:10 | Distribution | Evarts Quarterly Inspection | B0309 | LTCMechanism | 080-5 | LTC Counter Readings | LTC As Left Counter | 80009 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | B0450 | WithLTC | 176-5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Amps C Ø | 60.0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Amps B Ø | 100.0 | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 7:21 | Distribution | Loudon Avenue Quarterly Inspection | BK002052 | BreakerVacuum | 176-0127 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | R0493 | Regulator | 758-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001960 | BreakerVacuum | CY-14KV TFR SEC 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Readings | Amps A Ø | 80.0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | SWG000016 | Switchgear | CK-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | SWG000016 | Switchgear | CK-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | SWG000016 | Switchgear | CK-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Readings | General Comments | | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Readings | LTC Totalizer Reading | 37008.00 | kw |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | SWG000016 | Switchgear | CK-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | SWG000016 | Switchgear | CK-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | YD000078 | Yard | 362-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | YD000078 | Yard | 362-Yard | Yard Patrol Inspection | Ambient Temp | 48 | °F |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Readings | Oil Temp Max | 80 | °C |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | General Comments | | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Amps C Ø | 0.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Amps B Ø | 0.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Amps A Ø | 0.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | 9 Month Operations | 3 | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Regulator As Left Counter | 155232 | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Amps C Ø | 0.0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Amps B Ø | 0.0 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000021 | WithLTC | 459-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | General Comments | | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Operations Counter AF | 249 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Operations Counter AL | 249 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Operations This Read Vac | 1 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Switching Operations | 0 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 15:28 | Distribution | St Paul Quarterly Inspection | KB0024 | BreakerVacuum | 116-0685 | VCB Readings | Unknown Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001140 | BreakerVacuum | 459-BT2-1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | CH000361 | ControlHouse | 529-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Readings | Winding Temp Present | 28 | °C |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Readings | Winding Temp Max | 56 | °C |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Readings | Totalizer Meter Reading | .8440 | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Readings | Totalizer Meter Multiplier | 24000 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | TX000216 | WithLTC | 459-2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Amps C Ø | 0.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Amps B Ø | 0.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Amps A Ø | 0.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001962 | BreakerVacuum | CY-GND TR 1 | VCB Readings | 9 Month Operations | 1 | |
| 1/5/2023 10:09 | Distribution | Clarks Lane Quarterly Inspection | SWG000016 | Switchgear | CK-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 13:03 | Distribution | Benham Quarterly Inspection | R1024 | Regulator | 493-2 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | BAT001091 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | BAT001091 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | BAT001091 | Battery | Retired Distribution | Battery Patrol Inspection | All Connections OK? | y | |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | BAT001088 | Battery | Retired Distribution | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | BAT001088 | Battery | Retired Distribution | Battery Patrol Inspection | Positive DC Ground | 2.5 | VDC |
| 1/5/2023 12:04 | Distribution | Bardwell Quarterly Inspection | BAT001088 | Battery | Retired Distribution | Battery Patrol Inspection | Negative DC Ground | 2.5 | VDC |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Unknown Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Switching Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Operations Counter AL | 59 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Operations Counter AF | 59 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Maintenance Operations | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | General Comments | | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Switching Operations | 2 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Operations This Read Vac | 2 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Operations Counter AL | 188 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Operations Counter AF | 186 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | General Comments | | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Patrol Inspection | General Comments | | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Amps C Ø | 0.0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Amps B Ø | 0.0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Amps A Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/9/2023 9:09 | Distribution | Clay LGE Quarterly Inspection | BK001961 | BreakerVacuum | CY-14KV BUS TIE SEC 1 | VCB Readings | 9 Month Operations | 3 | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Readings | General Comments | | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | General Comments | added nitrogen | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/5/2023 13:46 | Distribution | Virginia City Distribution Quarterly Inspection | 0985 | NonLTC | 351-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | General Comments | Neighbor's fence is within 6 feet. Trees hanging over fence on east side of station. | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | Ambient Temp | 44 | °F |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 15:12 | Distribution | Procter and Gamble Quarterly Inspection | BK001260 | BreakerVacuum | 875-0084 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Readings | Totalizer Meter Reading | .8953 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 14400 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001137 | BreakerVacuum | 459-0295 | VCB Readings | Operations Counter AL | 162 | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | 9 Month Operations | 0 | |
| 1/5/2023 11:58 | Distribution | FMC Quarterly Inspection | B0409 | WithLTC | 807-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | General Comments | | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | YD000636 | Yard | CB-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 7:27 | Distribution | Hume Road Quarterly Inspection | BK001136 | BreakerVacuum | 459-0294 | VCB Readings | Amps A Ø | 0.0 | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | General Comments | Brush needs cut back to 5' of clearance | |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | BAT001091 | Battery | Retired Distribution | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/5/2023 11:05 | Distribution | Clinton 12kV Quarterly Inspection | BAT001091 | Battery | Retired Distribution | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/5/2023 15:32 | Distribution | Guest River Quarterly Inspection | FE000078 | Fence | 362-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Readings | LTC Totalizer Reading | 1222.40 | kw |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Readings | General Comments | | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | n | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 13:08 | Distribution | Mount Tabor Quarterly Inspection | B0248 | WithLTC | 769-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Follow-up Action Required? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/5/2023 10:56 | Distribution | Crop Quarterly Inspection | FE000632 | Fence | CB-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 165.00 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Readings | Winding Temp Present | 40 | °C |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Readings | Winding Temp Max | 90 | °C |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Readings | Totalizer Meter Reading | 2.0560 | |
| 1/5/2023 10:07 | Distribution | Liberty Road Quarterly Inspection | B0364 | WithLTC | 529-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 18000 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | LTCC000909 | LTCControl | 932-Offline Distribution | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | LTCC000909 | LTCControl | 932-Offline Distribution | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | LTCC000909 | LTCControl | 932-Offline Distribution | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | LTCC000909 | LTCControl | 932-Offline Distribution | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | LTCC000909 | LTCControl | 932-Offline Distribution | LTC Control Insp | LTC Operation Checked? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | LTCC000909 | LTCControl | 932-Offline Distribution | LTC Control Insp | All Connections OK? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | LTCC000909 | LTCControl | 932-Offline Distribution | LTC Control Insp | Follow-up Action Required? | n | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | LTCC000909 | LTCControl | 932-Offline Distribution | LTC Control Insp | General Comments | | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Counter Readings | General Comments | | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Counter Readings | LTC As Found Counter | 157118 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Counter Readings | LTC As Left Counter | 157118 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Counter Readings | LTC Current Tap Position | 1R | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Counter Readings | LTC Operations Since Last Insp | 267 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Counter Readings | LTC Max Tap Position | 7R | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | LTCM000123 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Readings | General Comments | | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Readings | LTC Totalizer Reading | 1161600.00 | kw |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Readings | Totalizer Meter Reading | 121.0000 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Readings | Oil Temp Max | 35 | °C |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Readings | Oil Temp Present | 25 | °C |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | B0349 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Readings | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Readings | LTC Totalizer Reading | 0.00 | kw |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Readings | Oil Temp Max | 30 | °C |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Readings | Oil Temp Present | 15 | °C |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 0 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 20.00 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | LTCMechanism | 667-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | LTCMechanism | 667-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | LTCMechanism | 667-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | LTCMechanism | 667-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | LTCMechanism | 667-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | LTCMechanism | 667-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0526 | WithLTC | 667-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BCH000306 | Charger | Retired Distribution | Battery Charger Patrol Insp | As Found Float Voltage | 132.9 | VDC |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BCH000306 | Charger | Retired Distribution | Battery Charger Patrol Insp | As Left Float Voltage | 132.9 | VDC |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BCH000306 | Charger | Retired Distribution | Battery Charger Patrol Insp | Battery Charger Current | .9 | amps |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BCH000306 | Charger | Retired Distribution | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BCH000306 | Charger | Retired Distribution | Battery Charger Patrol Insp | General Comments | | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 64 | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 35 | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Amps A Ø | 15.0 | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 3 | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Amps C Ø | 22.0 | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | DX0115 | RecloserHydraulic | 951-Offline-Distribution | Recloser Hydraulic Patrol Inspection | Amps B Ø | 19.0 | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Readings | Oil Temp Max | 63 | °C |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Readings | Oil Temp Present | 34 | °C |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Amps C Ø | 243.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Amps B Ø | 254.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Amps A Ø | 245.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | LTCC000785 | LTCControl | 673-1 | LTC Control Insp | All Connections OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | 9 Month Operations | 1 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .8478 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 61170 | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 3600 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Operations Counter AF | 29 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | YD000030 | Yard | 859-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | YD000030 | Yard | 859-Yard | Yard Patrol Inspection | General Comments | | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | YD000030 | Yard | 859-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | YD000030 | Yard | 859-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | YD000030 | Yard | 859-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Fault Operations Ground | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Amps C Ø | 54.0 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Amps B Ø | 57.0 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Amps C Ø | 460.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Amps B Ø | 480.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Switching Operations | 2 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Operations This Read Vac | 2 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Operations Counter AL | 254 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Operations Counter AF | 252 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | YD000030 | Yard | 859-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | YD000030 | Yard | 859-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | YD000030 | Yard | 859-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 500 | psi |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Operations Counter AF | 337 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Operations Counter AL | 337 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Operations This Read Vac | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Operations This Read Vac | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Operations Counter AL | 29 | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | Vegetation | None | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | General Comments | Small washout is forming in back of station by containment berm. | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | 9 Month Operations | 1 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000094 | Switchgear | DA-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | Drive/Lot Free of Washouts? | n | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BCH000881 | Charger | 667-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.0 | amps |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BCH000881 | Charger | 667-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 54.0 | VDC |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BCH000881 | Charger | 667-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 54.0 | VDC |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BCH000881 | Charger | 667-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | YD000030 | Yard | 859-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Operations Counter AF | 82 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Operations Counter AL | 82 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Operations This Read Vac | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Unknown Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Amps C Ø | 10.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Amps B Ø | 10.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Amps A Ø | 10.0 | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Amps A Ø | 80.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | 9 Month Operations | 3 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | YD000030 | Yard | 859-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | YD000030 | Yard | 859-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | YD000030 | Yard | 859-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | LTCC000785 | LTCControl | 673-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | LTCC000785 | LTCControl | 673-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | LTCC000785 | LTCControl | 673-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | LTCC000785 | LTCControl | 673-1 | LTC Control Insp | LTC Output Voltage Level | 124.1 | VAC |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | LTCC000785 | LTCControl | 673-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | LTCC000785 | LTCControl | 673-1 | LTC Control Insp | General Comments | | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | LTCC000785 | LTCControl | 673-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | General Comments | | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | General Comments | ok | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Readings | General Comments | ok | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3052.08 | kw |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | W0241 | NonLTC | 852-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000105 | Switchgear | BR-Swgr Sec 4 | Switchgear Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Amps A Ø | 0.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Amps B Ø | 0.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Amps C Ø | 0.0 | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | General Comments | ok | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | R1369 | Regulator | 635-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000212 | Yard | 421-Yard 4kv | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Amps C Ø | 77.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001852 | BreakerVacuum | BR-1187 | VCB Readings | Amps B Ø | 79.0 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Operations Counter AL | 300 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Operations This Read Vac | 1 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Switching Operations | 1 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BCH000259 | Charger | 673-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BCH000259 | Charger | 673-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .8 | amps |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BCH000259 | Charger | 673-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BCH000259 | Charger | 673-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | General Comments | | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0025 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0025 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Operations Counter AF | 180 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Operations Counter AL | 180 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BCH000259 | Charger | 673-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Operations This Read Vac | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0473 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Readings | Totalizer Meter Reading | .6594 | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 600 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Operations Counter AF | 299 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Operations Counter AF | 364 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 135.00 | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 140.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | General Comments | | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 395.64 | kw |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Readings | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0025 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0025 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0025 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0025 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | ST000031 | Structure | 859-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0127 | NonLTC | 448-2 A | NonLTC Transformer Readings | Oil Temp Max | 51 | °C |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Amps C Ø | 97.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Amps B Ø | 79.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Amps A Ø | 83.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | 9 Month Operations VCB New | 6 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | 9 Month Operations | 9 | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 102025 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Operations This Read Vac | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Operations Counter AL | 364 | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | 9 Month Operations | 0 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | General Comments | | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | General Comments | | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Amps A Ø | 460.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001853 | BreakerVacuum | BR-12KV TR 5 | VCB Readings | 9 Month Operations | 0 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | LTCC000895 | LTCControl | 859-1 | LTC Control Insp | All Connections OK? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | LTCC000895 | LTCControl | 859-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | LTCC000895 | LTCControl | 859-1 | LTC Control Insp | General Comments | | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | LTCC000895 | LTCControl | 859-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001672 | BreakerVacuum | BR-14KV BUS TIE | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Switching Operations | 3 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Operations This Read Vac | 3 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | FE000034 | Fence | 859-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Operations Counter AL | 57 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Operations Counter AF | 57 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | CH000137 | ControlHouse | DA-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0872 | Regulator | 707-1 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Amps A Ø | 248.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Amps B Ø | 236.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Amps C Ø | 245.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BCH001203 | Charger | BR-Battery Charger 48V | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BCH001203 | Charger | BR-Battery Charger 48V | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Counter Readings | General Comments | | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Counter Readings | LTC As Found Counter | 11095 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0271 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0271 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Counter Readings | LTC As Left Counter | 11101 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Counter Readings | LTC Max Tap Position | 3L | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | General Comments | | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Counter Readings | LTC Min Tap Position | 10L | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Counter Readings | LTC Operations Since Last Insp | 190 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001850 | BreakerVacuum | BR-1186 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | LTCMechanism | 673-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000027 | Switchgear | CT-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | LTCC000895 | LTCControl | 859-1 | LTC Control Insp | LTC Output Voltage Level | 122.0 | VAC |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | LTCC000895 | LTCControl | 859-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | LTCC000895 | LTCControl | 859-1 | LTC Control Insp | VRR Base Voltage AF | 122.0 | VAC |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BAT000962 | Battery | 667-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | LTCC000895 | LTCControl | 859-1 | LTC Control Insp | VRR Base Voltage AL | 122.0 | VAC |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | LTCC000895 | LTCControl | 859-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Amps A Ø | 65.0 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0138 | BreakerVacuum | 783-2213 | VCB Readings | 9 Month Operations | 6 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0271 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0271 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 206.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0271 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0271 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0271 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0271 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Operations Counter AF | 143 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Operations Counter AL | 143 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Operations This Read Vac | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000713 | BreakerVacuum | BR-14KV TR 1 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | 9 Month Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000714 | BreakerVacuum | BR-14KV TR 2 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BCH001203 | Charger | BR-Battery Charger 48V | Battery Charger Patrol Insp | General Comments | Voltage after 1 minute trip is 48.9 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BCH001203 | Charger | BR-Battery Charger 48V | Battery Charger Patrol Insp | Follow-up Action Required? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BCH001203 | Charger | BR-Battery Charger 48V | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BCH001203 | Charger | BR-Battery Charger 48V | Battery Charger Patrol Insp | Battery Charger Current | 9.4 | amps |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BCH001203 | Charger | BR-Battery Charger 48V | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001671 | BreakerVacuum | BR-14KV TRANSFER | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | FE000641 | Fence | BK-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000818 | Yard | 421-Yard 34.5 | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000818 | Yard | 421-Yard 34.5 | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000818 | Yard | 421-Yard 34.5 | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000818 | Yard | 421-Yard 34.5 | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000818 | Yard | 421-Yard 34.5 | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 15 | °C |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 35 | °C |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000818 | Yard | 421-Yard 34.5 | Yard Patrol Inspection | Follow-up Action Required? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000818 | Yard | 421-Yard 34.5 | Yard Patrol Inspection | General Comments | 34.5 Cap Bank and all equipment has been removed. Please remove this inspection | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000818 | Yard | 421-Yard 34.5 | Yard Patrol Inspection | Vegetation | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0025 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0025 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0025 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0025 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0025 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0025 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | LTCC000654 | LTCControl | 444-3 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | LTCC000654 | LTCControl | 444-3 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 4.0 | psi |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | LTCC000654 | LTCControl | 444-3 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | LTCC000654 | LTCControl | 444-3 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | LTCC000654 | LTCControl | 444-3 | LTC Control Insp | LTC Output Voltage Level | 124.5 | VAC |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | LTCC000654 | LTCControl | 444-3 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | LTCC000654 | LTCControl | 444-3 | LTC Control Insp | General Comments | | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | LTCC000654 | LTCControl | 444-3 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | LTCC000654 | LTCControl | 444-3 | LTC Control Insp | All Connections OK? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BCH001451 | Charger | 764-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BCH001451 | Charger | 764-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BCH001451 | Charger | 764-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BAT001525 | Battery | 764-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BAT001525 | Battery | 764-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BAT001525 | Battery | 764-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.5 | VDC |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BAT001525 | Battery | 764-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.5 | VDC |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BAT001525 | Battery | 764-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BAT001525 | Battery | 764-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 36560 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.7 | volts |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0464 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0464 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0464 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0464 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0464 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0464 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0464 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Patrol Inspection | General Comments | | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0190 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0190 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0190 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 131996 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000777 | Fence | 421-Fence 34.5 | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000777 | Fence | 421-Fence 34.5 | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000777 | Fence | 421-Fence 34.5 | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000777 | Fence | 421-Fence 34.5 | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000777 | Fence | 421-Fence 34.5 | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000777 | Fence | 421-Fence 34.5 | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000777 | Fence | 421-Fence 34.5 | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000777 | Fence | 421-Fence 34.5 | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000777 | Fence | 421-Fence 34.5 | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000777 | Fence | 421-Fence 34.5 | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000777 | Fence | 421-Fence 34.5 | Fence Patrol Inspection | General Comments | 34.5 equipment has been removed | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000777 | Fence | 421-Fence 34.5 | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000777 | Fence | 421-Fence 34.5 | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000818 | Yard | 421-Yard 34.5 | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000818 | Yard | 421-Yard 34.5 | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | YD000818 | Yard | 421-Yard 34.5 | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0190 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Amps C Ø | 70.0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Amps B Ø | 50.0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Amps A Ø | 60.0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0190 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0190 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 117.50 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0190 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0190 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0190 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cooling Group Position | Bank1 | chg 1st quarter |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | General Comments | | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 20142 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.7 | volts |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Min Tap Position | 13L | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Max Tap Position | 6L | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | General Comments | | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | YD000638 | Yard | CT-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | General Comments | ok | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0313 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Current Tap Position | 10L | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Amps A Ø | 36.0 | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Amps B Ø | 34.0 | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Readings | Winding Temp Present | 30 | °C |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Readings | Winding Temp Max | 30 | °C |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0168 | BreakerAirMagnetic | CT-4 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BAT001525 | Battery | 764-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BAT001525 | Battery | 764-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BAT001525 | Battery | 764-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BAT001525 | Battery | 764-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BAT001525 | Battery | 764-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BAT001525 | Battery | 764-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 55 | °F |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1455 | Regulator | 764-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0041 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BAT001525 | Battery | 764-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1453 | Regulator | 852-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000212 | Fence | 421-Fence 4kv | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | General Comments | | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Maintenance Operations | 1 | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Operations Counter AF | 183 | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Operations Counter AL | 184 | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Operations This Read Vac | 1 | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | BAT001439 | Battery | BK-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 48874 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1220.76 | kw |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | General Comments | no gauges working | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Readings | General Comments | | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | General Comments | | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | Ambient Temp | 47 | °F |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | General Comments | | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0949 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 27.50 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | FE000225 | Fence | 498-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | 9 Month Operations | 1 | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Amps A Ø | 146.0 | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Amps B Ø | 117.0 | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Readings | Amps C Ø | 127.0 | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BK000725 | BreakerVacuum | 421-1526 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | RC001331 | RecloserHydraulic | 861-1523 A | Recloser Hydraulic Patrol Inspection | Operations Counter | 41 | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | RC001331 | RecloserHydraulic | 861-1523 A | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | RC001331 | RecloserHydraulic | 861-1523 A | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | YD000189 | Yard | 560-Yard | Yard Patrol Inspection | Ambient Temp | 48 | °F |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | YD000189 | Yard | 560-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | YD000189 | Yard | 560-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | YD000189 | Yard | 560-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | YD000189 | Yard | 560-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | YD000189 | Yard | 560-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | YD000189 | Yard | 560-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | YD000189 | Yard | 560-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | YD000189 | Yard | 560-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | YD000189 | Yard | 560-Yard | Yard Patrol Inspection | General Comments | Road leqasding to station needs tree trimming | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | YD000189 | Yard | 560-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | YD000189 | Yard | 560-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | YD000189 | Yard | 560-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | All Connections OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BAT001510 | Battery | BR-Battery Bank 48V | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0190 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000777 | Fence | 421-Fence 34.5 | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000777 | Fence | 421-Fence 34.5 | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | FE000777 | Fence | 421-Fence 34.5 | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Readings | Totalizer Meter Reading | .4850 | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Readings | Oil Temp Max | 44 | °C |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0190 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0190 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 52.50 | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Readings | Non LTC Totalizer Reading | 582.00 | kw |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Readings | General Comments | | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0027 | NonLTC | 555-1 C | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Min Tap Position | 13L | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1452 | Regulator | 498-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Chipped | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Readings | General Comments | | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | General Comments | H2 bushing has chipped skirt. | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Unknown Operations | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Switching Operations | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Operations This Read AM | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Operations Counter AL | 298 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Operations Counter AF | 298 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | General Comments | | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Patrol Inspection | General Comments | | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 140.00 | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 135.00 | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Readings | Oil Temp Present | 28 | °C |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0129 | NonLTC | 448-2 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | RC001331 | RecloserHydraulic | 861-1523 A | Recloser Hydraulic Patrol Inspection | Amps A Ø | 5.5 | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | RC001331 | RecloserHydraulic | 861-1523 A | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | RC001331 | RecloserHydraulic | 861-1523 A | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | RC001331 | RecloserHydraulic | 861-1523 A | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | RC001331 | RecloserHydraulic | 861-1523 A | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | RC001331 | RecloserHydraulic | 861-1523 A | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | RC001331 | RecloserHydraulic | 861-1523 A | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | General Comments | | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | FE000256 | Fence | 440-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | General Comments | | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Min Tap Position | 7L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.8 | volts |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | General Comments | | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | General Comments | trees overhanging fence in multiple places. top rail rusty and fabric | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | General Comments | | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | 9 Month Operations | 2 | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | n | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | n | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | FE000115 | Fence | 707-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | ST000528 | Structure | 783-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | ST000198 | Structure | 764-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | General Comments | | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | General Comments | | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | ST000134 | Structure | 082-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | General Comments | Top of containment is exposed by the control house. | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | CH000043 | ControlHouse | 082-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | YD000131 | Yard | 082-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Readings | General Comments | | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Readings | LTC Totalizer Reading | 3990.72 | kw |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Readings | Oil Temp Max | 60 | °C |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1431 | Regulator | 544-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Readings | Totalizer Meter Reading | .8314 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | WithLTC | 420-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000252 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | General Comments | 1 OP Trip Check | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Maintenance Operations | 1 | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Operations Counter AF | 243 | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Operations Counter AL | 243 | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Operations This Read Vac | 1 | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BK000007 | BreakerVacuum | 113-3413 | VCB Readings | Unknown Operations | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | SWG000102 | Switchgear | DA-Swgr Sec 2 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | BCH000842 | Charger | CT-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | BCH000842 | Charger | CT-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | BCH000842 | Charger | CT-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | BCH000842 | Charger | CT-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 0.0 | amps |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | BCH000842 | Charger | CT-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.7 | VDC |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | BCH000842 | Charger | CT-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.7 | VDC |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | BCH000842 | Charger | CT-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | General Comments | Nitro prress gauge needs replacing | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Readings | General Comments | | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | General Comments | | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | ST000206 | Structure | 708-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | YD000199 | Yard | 708-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | YD000199 | Yard | 708-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | YD000199 | Yard | 708-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | YD000199 | Yard | 708-Yard | Yard Patrol Inspection | General Comments | | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | YD000199 | Yard | 708-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | YD000199 | Yard | 708-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | YD000199 | Yard | 708-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | S0062 | NonLTC | 082-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Amps C Ø | 35.0 | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | General Comments | ok | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Operations Counter | 17 | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | RC001268 | RecloserElectronic | 852-1501 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | 9 Months Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0167 | BreakerAirMagnetic | CT-3 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0313 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0313 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0313 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 250.00 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0313 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0313 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0313 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0313 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0313 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0313 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0313 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0313 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0313 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 32322 | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.6 | volts |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1449 | Regulator | 421-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1328 | Regulator | 783-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | YD000214 | Yard | 448-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | YD000214 | Yard | 448-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | YD000214 | Yard | 448-Yard | Yard Patrol Inspection | Ambient Temp | 56 | °F |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | General Comments | TC | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Maintenance Operations | 1 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Operations Counter AF | 183 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Operations Counter AL | 184 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Operations This Read Vac | 1 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Switching Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Readings | General Comments | | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1113.60 | kw |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 97.50 | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Readings | Oil Temp Present | 20 | °C |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 800 | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | W0189 | NonLTC | 440-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.3920 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | FE000511 | Fence | 783-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | YD000199 | Yard | 708-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | YD000199 | Yard | 708-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | YD000199 | Yard | 708-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | YD000199 | Yard | 708-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | YD000199 | Yard | 708-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | YD000199 | Yard | 708-Yard | Yard Patrol Inspection | Ambient Temp | 54 | °F |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | General Comments | | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | FE000200 | Fence | 708-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | 9 Month Operations | 37 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | 9 Month Operations VCB New | 36 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | General Comments | | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Station Ground Set On Site? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | SWG000017 | Switchgear | BK-Swgr Sec 1 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Amps A Ø | 40.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Amps B Ø | 58.0 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Readings | Amps C Ø | 37.0 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001808 | BreakerVacuum | 764-1529 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | YD000214 | Yard | 448-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | YD000214 | Yard | 448-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | YD000214 | Yard | 448-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | YD000214 | Yard | 448-Yard | Yard Patrol Inspection | General Comments | | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | YD000214 | Yard | 448-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | YD000214 | Yard | 448-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | YD000214 | Yard | 448-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | YD000214 | Yard | 448-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | YD000214 | Yard | 448-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | YD000214 | Yard | 448-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 72.50 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | W0242 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | General Comments | | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | General Comments | ok | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | General Comments | | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Operations Counter AF | 36 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Operations Counter AL | 36 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Operations This Read Vac | 0 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Switching Operations | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | BAT001667 | Battery | 082-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | BAT001667 | Battery | 082-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.0 | VDC |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | BAT001667 | Battery | 082-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 28.1 | VDC |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | BAT001667 | Battery | 082-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | BAT001667 | Battery | 082-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | BAT001667 | Battery | 082-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | BAT001667 | Battery | 082-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | BAT001667 | Battery | 082-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | BAT001667 | Battery | 082-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | BAT001667 | Battery | 082-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | BAT001667 | Battery | 082-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Amps B Ø | 0.0 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Amps C Ø | 10.0 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | ANN000006 | Annunciator | BR-Annunciator Panel 1 | Annunciator Patrol Inspection | All Lights Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | ANN000006 | Annunciator | BR-Annunciator Panel 1 | Annunciator Patrol Inspection | Control House Alarm Audible? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | ANN000006 | Annunciator | BR-Annunciator Panel 1 | Annunciator Patrol Inspection | ESOC  Received Alarm Test? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | ANN000006 | Annunciator | BR-Annunciator Panel 1 | Annunciator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | ANN000006 | Annunciator | BR-Annunciator Panel 1 | Annunciator Patrol Inspection | General Comments | | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | General Comments | Whole station needs wildlife protection and fiberglass is exposed on all xfmr fuse barrels including spare. | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | General Comments | | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | Meter Array Visual Inspection | OK | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | General Comments | | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | YD000358 | Yard | 667-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | General Comments | | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | FE000352 | Fence | 667-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | ST000245 | Structure | 635-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 61517 | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.0 | volts |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Switching Operations | 2 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Operations This Read Vac | 2 | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | ST000266 | Structure | 440-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | YD000504 | Yard | 420-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | YD000504 | Yard | 420-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | YD000504 | Yard | 420-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | YD000504 | Yard | 420-Yard | Yard Patrol Inspection | General Comments | | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | YD000504 | Yard | 420-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | YD000504 | Yard | 420-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | YD000504 | Yard | 420-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | YD000504 | Yard | 420-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | YD000504 | Yard | 420-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | YD000504 | Yard | 420-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | YD000504 | Yard | 420-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | YD000504 | Yard | 420-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | YD000504 | Yard | 420-Yard | Yard Patrol Inspection | Ambient Temp | 58 | °F |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | ST000361 | Structure | 667-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | General Comments | | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | 9 Month Operations | 1 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | BCH000565 | Charger | 420-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.0 | VDC |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | BCH000565 | Charger | 420-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.2 | amps |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | BCH000565 | Charger | 420-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | YD000191 | Yard | 764-Yard | Yard Patrol Inspection | Ambient Temp | 54 | °F |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | General Comments | | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LB0112 | BreakerOil | BR-GND TR 2 | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | BCH000565 | Charger | 420-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | BCH000565 | Charger | 420-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Operations This Read Vac | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Operations Counter AL | 21 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Operations Counter AF | 21 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BCH000881 | Charger | 667-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BCH000881 | Charger | 667-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | BCH000565 | Charger | 420-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | BCH000565 | Charger | 420-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.0 | VDC |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Operations This Read Vac | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Operations Counter AL | 24 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Operations Counter AF | 24 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | FE000821 | Fence | 444-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Amps C Ø | 64.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Amps B Ø | 69.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001849 | BreakerVacuum | BR-1185 | VCB Readings | Amps A Ø | 75.0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | FE000635 | Fence | CT-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | YD000228 | Yard | 673-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | 9 Month Operations | 9 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | YD000228 | Yard | 673-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | YD000228 | Yard | 673-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | ST000506 | Structure | 420-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | 9 Month Operations | 1 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | General Comments | | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | FE000129 | Fence | 082-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | YD000228 | Yard | 673-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | YD000228 | Yard | 673-Yard | Yard Patrol Inspection | Ambient Temp | 45 | °F |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | General Comments | ok | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.9 | volts |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Regulator As Left Counter | 63893 | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | MB0133 | BreakerVacuum | 859-0432 | VCB Readings | Amps A Ø | 10.0 | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | FE000228 | Fence | 635-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | BAT001667 | Battery | 082-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Readings | Oil Temp Max | 44 | °C |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 52.50 | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Readings | General Comments | | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0025 | NonLTC | 555-1 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | R1368 | Regulator | 861-2 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Amps C Ø | 252.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Amps B Ø | 258.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Amps A Ø | 260.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001848 | BreakerVacuum | BR-1184 | VCB Readings | 9 Month Operations | 0 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0369 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | YD000228 | Yard | 673-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | YD000228 | Yard | 673-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | YD000228 | Yard | 673-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | YD000228 | Yard | 673-Yard | Yard Patrol Inspection | General Comments | | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BAT001668 | Battery | 498-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BAT001668 | Battery | 498-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BAT001668 | Battery | 498-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.9 | VDC |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BAT001668 | Battery | 498-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 28.0 | VDC |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BAT001668 | Battery | 498-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BAT001668 | Battery | 498-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BAT001668 | Battery | 498-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BAT001668 | Battery | 498-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BAT001668 | Battery | 498-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BAT001668 | Battery | 498-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BAT001668 | Battery | 498-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 47 | °F |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BAT001668 | Battery | 498-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | YD000228 | Yard | 673-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | YD000228 | Yard | 673-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | YD000228 | Yard | 673-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | YD000228 | Yard | 673-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Amps C Ø | 380.0 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Amps B Ø | 400.0 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Amps A Ø | 380.0 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0059 | BreakerVacuum | 420-0186 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Air Tank Bleed (> 40°F)? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | AirCompressor Heater Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Readings | Fault Operations | 0 | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | General Comments | | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0284 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0284 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0284 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0284 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0284 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0284 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0284 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0284 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0284 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0284 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0284 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BCH001098 | Charger | 498-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BCH001098 | Charger | 498-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BCH001098 | Charger | 498-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 54.9 | VDC |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BCH001098 | Charger | 498-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 54.9 | VDC |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Readings | General Comments | | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Readings | Number of Ops last 9 Months | 0 | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Readings | Operations Counter AF | 99992 | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Readings | Operations Counter AL | 99992 | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Readings | Operations This Read Oil | 0 | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Pop-off Valve Tested Date | 2023-01-04 00:00:00.000000 | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Pressure Vessel Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Readings | Switching Operations | 0 | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Tank 1 Oil Level | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Tank 2 Oil level | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Tank 3 Oil Level | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | General Comments | | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | n | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Present | 40 | °C |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Readings | X3 Winding Temp Max | 60 | °C |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Present | 40 | °C |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Readings | X2 Winding Temp Max | 65 | °C |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Present | 40 | °C |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 95.00 | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Readings | X1 Winding Temp Max | 70 | °C |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Readings | General Comments | | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | YD000238 | Yard | 635-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | WithLTC | CT-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Readings | 9 Months Operations OCB New | 0 | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Air Compressor Belt Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Air Compressor Oil Status | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Air Leaks | None | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Patrol Inspection | Air Pressure OK? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | YD000056 | Yard | 555-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | YD000056 | Yard | 555-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | YD000056 | Yard | 555-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | YD000056 | Yard | 555-Yard | Yard Patrol Inspection | Ambient Temp | 55 | °F |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | General Comments | | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | Ambient Temp | 62 | °F |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | General Comments | | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | General Comments | | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | ST000232 | Structure | 498-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | YD000049 | Yard | 883-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | YD000225 | Yard | 498-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 2.0346 | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 600 | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | B0173 | NonLTC | 708-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | TB0099 | BreakerOil | 082-614 | OCB Readings | Unknown Operations | 0 | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | FE000005 | Fence | 544-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | RC001321 | RecloserHydraulic | 635-1707 A | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 0 | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | RC001321 | RecloserHydraulic | 635-1707 A | Recloser Hydraulic Patrol Inspection | Amps A Ø | 11.7 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | YD000056 | Yard | 555-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | YD000056 | Yard | 555-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | YD000056 | Yard | 555-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | YD000056 | Yard | 555-Yard | Yard Patrol Inspection | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | FE000598 | Fence | DA-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | YD000056 | Yard | 555-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | YD000056 | Yard | 555-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | YD000056 | Yard | 555-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | YD000056 | Yard | 555-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | YD000056 | Yard | 555-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | RC001321 | RecloserHydraulic | 635-1707 A | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | RC001321 | RecloserHydraulic | 635-1707 A | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | RC001321 | RecloserHydraulic | 635-1707 A | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | YD000603 | Yard | DA-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | FE000154 | Fence | 861-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | RC001321 | RecloserHydraulic | 635-1707 A | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | RC001321 | RecloserHydraulic | 635-1707 A | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | RC001321 | RecloserHydraulic | 635-1707 A | Recloser Hydraulic Patrol Inspection | General Comments | ok | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | RC001321 | RecloserHydraulic | 635-1707 A | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | RC001321 | RecloserHydraulic | 635-1707 A | Recloser Hydraulic Patrol Inspection | Operations Counter | 259 | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | RC001321 | RecloserHydraulic | 635-1707 A | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | RC001321 | RecloserHydraulic | 635-1707 A | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | 9 Month Operations VCB New | 9 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | 9 Month Operations | 11 | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 167084 | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Counter Readings | General Comments | | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Counter Readings | LTC As Found Counter | 5110 | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Counter Readings | LTC As Left Counter | 5120 | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Counter Readings | LTC Current Tap Position | 4L | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Counter Readings | LTC Max Tap Position | 4R | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Counter Readings | LTC Operations Since Last Insp | 570 | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | LTCMechanism | 883-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 236149 | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Max Tap Position | 1L | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0817 | Regulator | 555-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 30628 | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R0714 | Regulator | 421-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0818 | Regulator | 555-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Operations Counter AL | 253 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Operations Counter AF | 251 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | General Comments | | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | General Comments | | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Door Alarms OK? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | CH000108 | ControlHouse | 420-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Amps C Ø | 90.0 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Amps B Ø | 90.0 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Amps A Ø | 90.0 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | KB0058 | BreakerVacuum | 420-0185 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Readings | Percent Thermal Load C Ø Max | -60 | % |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Readings | Percent Thermal Load B Ø Max | -60 | % |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Readings | Percent Thermal Load A Ø Max | -60 | % |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Readings | Oil Temp Present | 26 | °C |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Readings | Oil Temp Max | 41 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | General Comments | | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | YD000238 | Yard | 635-Yard | Yard Patrol Inspection | General Comments | ok | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | YD000238 | Yard | 635-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | FE000164 | Fence | 113-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | General Comments | | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Control Handle "Red Flagged"? | y | If Bkr is Closed |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | CH000057 | ControlHouse | 113-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 28 | °C |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.2 | psi |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | WithLTC | CT-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | R0816 | Regulator | 555-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0045 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0045 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0045 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0045 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0045 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0045 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0045 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0045 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0045 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0045 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | General Comments | | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | General Comments | | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | CH000238 | ControlHouse | 444-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | YD000161 | Yard | 113-Yard | Yard Patrol Inspection | Ambient Temp | 51 | °F |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | YD000238 | Yard | 635-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | YD000238 | Yard | 635-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | YD000238 | Yard | 635-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | YD000238 | Yard | 635-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | YD000238 | Yard | 635-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | YD000238 | Yard | 635-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | YD000238 | Yard | 635-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | YD000238 | Yard | 635-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | YD000238 | Yard | 635-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | W0128 | NonLTC | 448-2 B | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000047 | PowerFuse | BR-STA SER NO 4 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000047 | PowerFuse | BR-STA SER NO 4 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | General Comments | | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | General Comments | ok | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Readings | General Comments | | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Readings | LTC Totalizer Reading | 56.16 | kw |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Readings | Oil Temp Max | 52 | °C |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Readings | Oil Temp Present | 39 | °C |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Readings | Totalizer Meter Reading | .0234 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | WithLTC | 859-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Operations Counter | 115 | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | FE000191 | Fence | 560-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | FE000191 | Fence | 560-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | FE000191 | Fence | 560-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | FE000191 | Fence | 560-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | FE000191 | Fence | 560-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | FE000191 | Fence | 560-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | FE000191 | Fence | 560-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | FE000191 | Fence | 560-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | FE000191 | Fence | 560-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | FE000191 | Fence | 560-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | FE000191 | Fence | 560-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | FE000191 | Fence | 560-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | FE000191 | Fence | 560-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | FE000191 | Fence | 560-Fence | Fence Patrol Inspection | General Comments | | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | FE000191 | Fence | 560-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | FE000191 | Fence | 560-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | ST000195 | Structure | 560-Structure | Structure Patrol Inspection | All Identified and Legible? | n | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | ST000195 | Structure | 560-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | ST000195 | Structure | 560-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | n | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | ST000195 | Structure | 560-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | n | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | ST000195 | Structure | 560-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | ST000195 | Structure | 560-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | ST000195 | Structure | 560-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | n | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Operations Counter AF | 180 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 135.00 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 159.17 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 5125.68 | kw |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Operations Counter AL | 180 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Operations This Read Vac | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | 9 Month Operations | 16 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | 9 Month Operations VCB New | 16 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Amps A Ø | 157.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Amps B Ø | 149.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Amps C Ø | 157.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | WithLTC | DA-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Operations Counter AF | 43 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Operations Counter AL | 43 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Operations This Read Vac | 1 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Switching Operations | 1 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Min Tap Position | 3L | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 39544 | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | 9 Months Operations | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | General Comments | | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | FE000121 | Fence | 555-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | 9 Month Operations | 1 | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Current Tap Position | 1R | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1512 | Regulator | 082-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Amps A Ø | 0.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Amps B Ø | 0.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Readings | Amps C Ø | 0.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001948 | BreakerVacuum | BR-12KV BUS TIE SEC 5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0182 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Amps A Ø | 29.0 | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Amps B Ø | 29.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | 9 Month Operations | 4 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Amps A Ø | 168.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Amps B Ø | 159.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Readings | Amps C Ø | 169.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000436 | BreakerVacuum | BR-1351 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Amps C Ø | 35.0 | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | KX0165 | RecloserElectronic | 852-1502 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | General Comments | above breaker 4427 on line side, insulator has a large chip in skirt on bottom of line side disconnect | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | ST000053 | Structure | 883-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | General Comments | gap under fence on ditch side, gravel has washed out | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 57861 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | FE000193 | Fence | 764-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.7 | volts |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Min Tap Position | 5L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R0996 | Regulator | 764-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Readings | General Comments | | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Readings | LTC Totalizer Reading | 4472.64 | kw |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Readings | Oil Temp Max | 42 | °C |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Readings | Oil Temp Present | 36 | °C |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Readings | Totalizer Meter Reading | .9318 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | W0355 | WithLTC | 673-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Max Tap Position | 4L | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.2 | volts |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Min Tap Position | 5L | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | BCH001331 | Charger | 783-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | BCH001331 | Charger | 783-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | BCH001331 | Charger | 783-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | BCH001331 | Charger | 783-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 1.2 | amps |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | BCH001331 | Charger | 783-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | BCH001331 | Charger | 783-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | BCH001331 | Charger | 783-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | BCH001331 | Charger | 783-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .2930 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 26057 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | YD000071 | Yard | 544-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | YD000071 | Yard | 544-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | YD000071 | Yard | 544-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | YD000071 | Yard | 544-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 52988 | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.3 | volts |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | YD000071 | Yard | 544-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | YD000071 | Yard | 544-Yard | Yard Patrol Inspection | Ambient Temp | 63 | °F |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R1392 | Regulator | 707-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Current Tap Position | 9L | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1394 | Regulator | 498-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 43069 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.7 | volts |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Min Tap Position | 12L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | R1393 | Regulator | 498-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | YD000071 | Yard | 544-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | YD000071 | Yard | 544-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | YD000071 | Yard | 544-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Exp Boom Needs Corr | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | YD000071 | Yard | 544-Yard | Yard Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | YD000071 | Yard | 544-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | YD000071 | Yard | 544-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | YD000071 | Yard | 544-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | WithLTC | DA-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | General Comments | | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Operations Counter AF | 245 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Operations Counter AL | 245 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Operations This Read Vac | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000437 | BreakerVacuum | BR-1352 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | ST000195 | Structure | 560-Structure | Structure Patrol Inspection | General Comments | No equipment only switches | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | ST000195 | Structure | 560-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | ST000195 | Structure | 560-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | ST000195 | Structure | 560-Structure | Structure Patrol Inspection | Live Parts Good Condition? | n | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | ST000195 | Structure | 560-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | ST000195 | Structure | 560-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | ST000195 | Structure | 560-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | ST000195 | Structure | 560-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | ST000195 | Structure | 560-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | ST000195 | Structure | 560-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 9:36 | Distribution | Cerro-Salem Quarterly Inspection | ST000195 | Structure | 560-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Readings | General Comments | | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Needs Replacing | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 40 | °C |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 20 | °C |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 61 | °F |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.0 | VDC |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.0 | VDC |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | BAT001412 | Battery | 783-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Readings | General Comments | | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 2812.80 | kw |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | R1395 | Regulator | 764-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 50096 | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | General Comments | | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | ST000078 | Structure | 544-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0384 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | S0020 | NonLTC | 783-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0984 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Amps C Ø | 350.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Amps B Ø | 360.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Amps A Ø | 320.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | 9 Month Operations | 1 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Operations This Read Vac | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Operations Counter AL | 136 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Operations Counter AF | 136 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Switching Operations | 1 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Operations This Read Vac | 1 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Operations Counter AL | 69 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Operations Counter AF | 69 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | General Comments | Xfmr fuse barrels are starting to fray. | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | n | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | General Comments | | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BAT001402 | Battery | 673-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BAT001402 | Battery | 673-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BAT001402 | Battery | 673-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BAT001402 | Battery | 673-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BAT001402 | Battery | 673-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Readings | General Comments | | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1396.80 | kw |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Readings | Oil Temp Present | 32 | °C |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .1940 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BAT001402 | Battery | 673-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BAT001402 | Battery | 673-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BAT001402 | Battery | 673-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BAT001402 | Battery | 673-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BAT001402 | Battery | 673-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 28.1 | VDC |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | M0067 | NonLTC | 707-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Amps C Ø | 117.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Amps B Ø | 91.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Amps A Ø | 95.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | General Comments | Gate side fence is not grounded. Every other side is just grounded in one spot. | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | FE000237 | Fence | 448-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Amps C Ø | 12.0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Amps B Ø | 12.0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Amps A Ø | 12.0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | 9 Month Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Amps C Ø | 77.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Amps B Ø | 92.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Amps A Ø | 76.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | 9 Month Operations | 9 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Switching Operations | 1 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Operations This Read Vac | 1 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Operations Counter AL | 372 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Operations Counter AF | 371 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | General Comments | | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Operations This Read Vac | 2 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Operations Counter AL | 52 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Operations Counter AF | 52 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | General Comments | A and B IOC | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Fault Operations B Ø | 1 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Operations This Read Vac | 0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Operations Counter AL | 668 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Operations Counter AF | 668 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | General Comments | | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Fault Operations A Ø | 1 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Fault Adjusted Amps B Phase V | 11.18 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Fault Adjusted Amps A Phase V | 11.18 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Amps C Ø | 0.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Amps B Ø | 0.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Amps A Ø | 0.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | 9 Month Operations | 5 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LTCC000475 | LTCControl | BR-TRANS 3 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LTCC000475 | LTCControl | BR-TRANS 3 | LTC Control Insp | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LTCC000475 | LTCControl | BR-TRANS 3 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | General Comments | | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | ST000258 | Structure | 448-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001640 | BreakerVacuum | BR-12KV TR 3 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Amps C Ø | 10.0 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Amps B Ø | 10.0 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Amps A Ø | 3.0 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0100 | BreakerVacuum | 783-2214 | VCB Readings | 9 Month Operations | 1 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Switching Operations | 1 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Operations This Read Vac | 1 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Operations Counter AL | 90 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Operations Counter AF | 90 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Grounds in Place? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | SWG000107 | Switchgear | CT-Swgr Sec 2 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0252 | Regulator | 708-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001642 | BreakerVacuum | BR-12KV BUS TIE SEC 3 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | 9 Month Operations | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | BCH000115 | Charger | BK-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | BCH000115 | Charger | BK-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | BCH000115 | Charger | BK-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 26.6 | VDC |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | BCH000115 | Charger | BK-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 26.6 | VDC |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | BCH000115 | Charger | BK-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Current Tap Position | 9R | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0984 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0984 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0984 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0984 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | 0984 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000042 | PowerFuse | BR-14KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000042 | PowerFuse | BR-14KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 141245 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Operations This Read Vac | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Operations Counter AL | 142 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Operations Counter AF | 142 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Regulator As Left Counter | 179757 | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Min Tap Position | 2R | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0751 | Regulator | 448-2 B | Regulator Patrol Inspection | Max Tap Position | 16R | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Amps C Ø | 120.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Amps B Ø | 126.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Amps A Ø | 131.0 | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Amps C Ø | 15.0 | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Amps B Ø | 32.0 | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Amps A Ø | 32.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000051 | PowerFuse | BR-STA SER NO 5 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000051 | PowerFuse | BR-STA SER NO 5 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0284 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0284 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0284 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0284 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0284 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.4238 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 3600 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | B0218 | NonLTC | 764-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0369 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0369 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0369 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0369 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0369 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Patrol Inspection | General Comments | | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Amps C Ø | 10.0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Amps B Ø | 10.0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Amps A Ø | 10.0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Counter Readings | General Comments | | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Counter Readings | LTC As Found Counter | 434316 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Counter Readings | LTC As Left Counter | 434323 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Counter Readings | LTC Current Tap Position | 10L | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Counter Readings | LTC Max Tap Position | 4L | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Counter Readings | LTC Operations Since Last Insp | 419 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1198 | Regulator | 444-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | B0257 | LTCMechanism | 859-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Unknown Operations | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Switching Operations | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Operations This Read AM | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Operations Counter AL | 328 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Operations Counter AF | 328 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0171 | BreakerAirMagnetic | CT-5 | AMCB Readings | General Comments | | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Operations Counter | 29 | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | General Comments | 27.2/25 | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0286 | RecloserElectronic | 707-0419 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0046 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0046 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0046 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0046 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0046 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0046 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0046 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0046 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0046 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0046 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0046 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0046 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | General Comments | ok | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | LTCC000392 | LTCControl | 420-1 | LTC Control Insp | VRR Time Delay | 30 | Seconds |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | LTCC000392 | LTCControl | 420-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | LTCC000392 | LTCControl | 420-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | LTCC000392 | LTCControl | 420-1 | LTC Control Insp | LTC Output Voltage Level | 123.0 | VAC |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | LTCC000392 | LTCControl | 420-1 | LTC Control Insp | LTC Operation Checked? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | LTCC000392 | LTCControl | 420-1 | LTC Control Insp | General Comments | | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BAT001402 | Battery | 673-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.9 | VDC |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BAT001402 | Battery | 673-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BAT001402 | Battery | 673-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001639 | BreakerVacuum | BR-1179 | VCB Readings | 9 Month Operations | 0 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | Oil stop valve operational? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | YD000870 | Yard | 932-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0348 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | FE000815 | Fence | 932-Fence | Fence Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Amps C Ø | 130.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Amps B Ø | 120.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Amps A Ø | 134.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | 9 Month Operations | 0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Counter Readings | General Comments | | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Counter Readings | LTC As Found Counter | 13584 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Counter Readings | LTC As Left Counter | 13592 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Counter Readings | LTC Operations Since Last Insp | 611 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | LTCMechanism | 444-3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0182 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | LTCM000076 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | LTCM000076 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | LTCM000076 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | LTCM000076 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | LTCM000076 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0182 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0182 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0182 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0182 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0182 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | BCH000115 | Charger | BK-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | BCH000115 | Charger | BK-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001637 | BreakerVacuum | BR-1176 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | LTCC000392 | LTCControl | 420-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | LTCC000392 | LTCControl | 420-1 | LTC Control Insp | All Connections OK? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | ST000256 | Structure | 852-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | General Comments | ok | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | FE000251 | Fence | 852-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Operations This Read Vac | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Operations Counter AL | 53 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Operations Counter AF | 53 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001638 | BreakerVacuum | BR-1180 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Operations This Read Vac | 2 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Operations Counter AL | 302 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Operations Counter AF | 302 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | General Comments | | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0262 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Current Tap Position | 6L | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0455 | Regulator | 440-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 123.3 | volts |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0454 | Regulator | 440-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Amps C Ø | 31.0 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Amps B Ø | 29.0 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Amps A Ø | 29.0 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | 9 Month Operations | 1 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000039 | PowerFuse | BR-GND TR 1 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000039 | PowerFuse | BR-GND TR 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000038 | PowerFuse | BR-14KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000038 | PowerFuse | BR-14KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 99231 | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Max Tap Position | 9R | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Operations This Read Vac | 1 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Operations Counter AL | 197 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Operations Counter AF | 196 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Maintenance Operations | 1 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | General Comments | TC | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Fault Operations A Ø | 2 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Fault Adjusted Amps A Phase V | 9.12 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Amps C Ø | 85.0 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Amps B Ø | 100.0 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Amps A Ø | 85.0 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | 9 Month Operations VCB New | 13 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | KB0125 | BreakerVacuum | 667-0045 | VCB Readings | 9 Month Operations | 15 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | BK001266 | BreakerVacuum | 764-1530 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Readings | Oil Temp Present | 37 | °C |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .5340 | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | General Comments | deteriorated fuse barrels No spare fuses | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | n | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | ST000219 | Structure | 421-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | LTCC000673 | LTCControl | 883-1 | LTC Control Insp | All Connections OK? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | LTCC000673 | LTCControl | 883-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | LTCC000673 | LTCControl | 883-1 | LTC Control Insp | General Comments | | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | LTCC000673 | LTCControl | 883-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | LTCC000673 | LTCControl | 883-1 | LTC Control Insp | LTC Output Voltage Level | 123.4 | VAC |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | LTCC000673 | LTCControl | 883-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | LTCC000673 | LTCControl | 883-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | LTCC000673 | LTCControl | 883-1 | LTC Control Insp | VRR Time Delay | 40 | Seconds |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 15 | °C |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 30 | °C |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | .5 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Operations Counter | 6 | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | YD000259 | Yard | 440-Yard | Yard Patrol Inspection | Ambient Temp | 51 | °F |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | General Comments | | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | YD000152 | Yard | 861-Yard | Yard Patrol Inspection | Ambient Temp | 52 | °F |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Readings | General Comments | | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.5 | psi |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1281.60 | kw |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | B0213 | NonLTC | 444-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Counter Readings | LTC Operations Since Last Insp | 344 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 110.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BAT001613 | Battery | 421-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BAT001613 | Battery | 421-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 63 | °F |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BAT001613 | Battery | 421-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BAT001613 | Battery | 421-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BAT001613 | Battery | 421-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BAT001613 | Battery | 421-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BAT001613 | Battery | 421-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BAT001613 | Battery | 421-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BAT001613 | Battery | 421-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 8.4 | VDC |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BAT001613 | Battery | 421-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 8.5 | VDC |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BAT001613 | Battery | 421-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BAT001613 | Battery | 421-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | WithLTC | BR-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Readings | General Comments | | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Readings | LTC Totalizer Reading | 2520.00 | kw |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Readings | Oil Temp Max | 59 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Readings | Oil Temp Present | 37 | °C |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Readings | Totalizer Meter Reading | .3500 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | C0411 | WithLTC | 444-3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Counter Readings | General Comments | | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Counter Readings | LTC As Found Counter | 16107 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Counter Readings | LTC As Left Counter | 16107 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Counter Readings | LTC Current Tap Position | 6L | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | B0293 | LTCMechanism | 420-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Amps C Ø | 100.0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Amps B Ø | 40.0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Amps A Ø | 100.0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | 9 Months Operations | 3 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | 9 Month Ops New | 3 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | 9 Month Operations | 1 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Amps A Ø | 0.0 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Amps B Ø | 0.0 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Amps C Ø | 0.0 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | General Comments | TC | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Maintenance Operations | 1 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Operations Counter AF | 193 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Operations Counter AL | 194 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000049 | PowerFuse | BR-12KV TR 3 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000049 | PowerFuse | BR-12KV TR 3 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000046 | PowerFuse | BR-12KV TR 4 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000046 | PowerFuse | BR-12KV TR 4 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000045 | PowerFuse | BR-STA SER NO 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000045 | PowerFuse | BR-STA SER NO 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000044 | PowerFuse | BR-STA SER NO 1 | Disconnect Powerfuse Inspection | General Comments | ok | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000044 | PowerFuse | BR-STA SER NO 1 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Unknown Operations | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Switching Operations | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Operations This Read AM | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Operations Counter AL | 682 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Operations Counter AF | 682 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | General Comments | | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | General Comments | | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Patrol Inspection | General Comments | | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Operations Counter AF | 216 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Operations Counter AL | 216 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Operations This Read Vac | 0 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0114 | BreakerAirMagnetic | BK-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | LTCM000048 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | LTCM000048 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | LTCM000048 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | LTCM000048 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Amps A Ø | 0.0 | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Amps B Ø | 0.0 | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Amps C Ø | 0.0 | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | n | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Operations Counter | 2336 | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | MX0357 | RecloserElectronic | 544-0435 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Amps A Ø | 19.0 | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Amps B Ø | 17.0 | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Amps C Ø | 14.0 | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Operations Counter | 6 | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0312 | RecloserElectronic | 883-4428 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Operations This Read Vac | 1 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | KB0137 | BreakerVacuum | 764-1531 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000043 | PowerFuse | BR-14KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000043 | PowerFuse | BR-14KV BUS SEC 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000041 | PowerFuse | BR-14KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000041 | PowerFuse | BR-14KV BUS SEC 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000040 | PowerFuse | BR-GND TR 2 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000040 | PowerFuse | BR-GND TR 2 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0243 | GroundTransformer | BR-GND TR 1B | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0038 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | LTCM000048 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | LTCM000048 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | LTCM000048 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | LTCM000048 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 20 | °C |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | LTCM000048 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 30 | °C |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | LTCM000048 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 2.0460 | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 94513 | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1432 | Regulator | 544-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0062 | LTCMechanism | DA-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Counter Readings | General Comments | | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | BCH001053 | Charger | 082-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | BCH001053 | Charger | 082-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | BCH001053 | Charger | 082-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | BCH001053 | Charger | 082-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | BCH001053 | Charger | 082-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .3 | amps |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | BCH001053 | Charger | 082-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.2 | VDC |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | BCH001053 | Charger | 082-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.2 | VDC |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | BCH001053 | Charger | 082-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | .900 | millivolts |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | R1434 | Regulator | 421-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000026 | Switchgear | BR-Swgr Sec 3 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Readings | General Comments | | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 4910.40 | kw |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Readings | Oil Temp Max | 42 | °C |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | W0361 | NonLTC | 498-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000050 | PowerFuse | BR-12KV TR 5 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000050 | PowerFuse | BR-12KV TR 5 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | General Comments | | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Landscape Good Condition? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Trench Covers in Place | Good | Need size info and qty |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | YD000645 | Yard | BK-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | 9 Month Operations | 2 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Amps A Ø | 20.0 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Amps B Ø | 30.0 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Amps C Ø | 40.0 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 12:45 | Distribution | Haley Quarterly Inspection | BK000831 | BreakerVacuum | 667-0046 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | LT0063 | LTCMechanism | DA-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.8 | volts |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 267866 | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | R0873 | Regulator | 707-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Readings | Oil Temp Present | 38 | °C |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Readings | General Comments | | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | M0026 | NonLTC | 555-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Counter Readings | LTC Operations Since Last Insp | 348 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Counter Readings | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 337703 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 337703 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 5 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | 7 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 4 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 237 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | LTCMechanism | BK-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Readings | General Comments | | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Readings | LTC Totalizer Reading | 2736.00 | kw |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Regulator As Left Counter | 78416 | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Min Tap Position | 1L | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Max Tap Position | 10R | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Counter Readings | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 104053 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 104053 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 3 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 3 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 2 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 52 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | LTCMechanism | BR-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Counter Readings | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Counter Readings | LTC As Found Counter | 176398 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Counter Readings | LTC As Left Counter | 176398 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Counter Readings | LTC Max Tap Position | 1R | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Counter Readings | LTC Operations Since Last Insp | 532 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | LTCMechanism | BR-TRANS 3 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Counter Readings | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Counter Readings | LTC As Found Counter | 185642 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Counter Readings | LTC As Left Counter | 186542 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | LTCMechanism | BR-TRANS 5 | LTC Counter Readings | LTC Current Tap Position | 3L | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Counter Readings | General Comments | | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Counter Readings | LTC As Found Counter | 506350 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Counter Readings | LTC As Left Counter | 506350 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Counter Readings | LTC Min Tap Position | 9L | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Counter Readings | LTC Operations Since Last Insp | 493 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN38 | LTCMechanism | CT-TRANS 2 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Amps C Ø | 114.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Amps B Ø | 113.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Amps A Ø | 118.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | 9 Month Operations | 4 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 495853 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 495853 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | Ambient Temp | 61 | °F |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Current Tap Position | 3R | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R0746 | Regulator | 448-2 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | Switch Stick and Container OK? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | General Comments | | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | YD000523 | Yard | 783-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Operations This Read Vac | 1 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Operations Counter AL | 235 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Operations Counter AF | 235 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | WX0478 | RecloserHydraulic | 861-1524 A | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | WX0478 | RecloserHydraulic | 861-1524 A | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | WX0478 | RecloserHydraulic | 861-1524 A | Recloser Hydraulic Patrol Inspection | Operations Counter | 296 | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | WX0478 | RecloserHydraulic | 861-1524 A | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | WX0478 | RecloserHydraulic | 861-1524 A | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | WX0478 | RecloserHydraulic | 861-1524 A | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | WX0478 | RecloserHydraulic | 861-1524 A | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | WX0478 | RecloserHydraulic | 861-1524 A | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | WX0478 | RecloserHydraulic | 861-1524 A | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | WX0478 | RecloserHydraulic | 861-1524 A | Recloser Hydraulic Patrol Inspection | Amps A Ø | 11.0 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0244 | GroundTransformer | BR-GND TR 1C | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000048 | PowerFuse | BR-STA SER NO 3 | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Switching Operations | 1 | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Operations Counter | 41 | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | General Comments | 27.3/25 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | PF000048 | PowerFuse | BR-STA SER NO 3 | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Amps C Ø | 45.0 | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Amps B Ø | 47.0 | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | MX0310 | RecloserElectronic | 707-0418 | Recloser Electronic Patrol Inspection | Amps A Ø | 57.0 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0430 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Operations This Read Vac | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Operations Counter AL | 228 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Operations Counter AF | 228 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Readings | Oil Temp Present | 32 | °C |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 0.00 | kw |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Readings | General Comments | | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | O0181 | NonLTC | 544-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Readings | General Comments | | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 459.57 | kw |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 97.50 | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 90.00 | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Readings | Oil Temp Max | 38 | °C |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Readings | Oil Temp Present | 26 | °C |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 300 | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | 0944 | NonLTC | 861-2 A | NonLTC Transformer Readings | Totalizer Meter Reading | 1.5319 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Amps C Ø | 73.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Amps B Ø | 727.0 | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/4/2023 9:59 | Distribution | Daniel Branch Quarterly Inspection | ST000055 | Structure | 555-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Amps A Ø | 75.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | 9 Month Operations VCB New | 8 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000555 | BreakerVacuum | BR-1354 | VCB Readings | 9 Month Operations | 9 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK000554 | BreakerVacuum | BR-1356 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | General Comments | | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Fault Adjusted Amps C Phase V | 6.55 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Fault Adjusted Amps B Phase V | 6.55 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Fault Adjusted Amps A Phase V | 6.55 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Amps C Ø | 152.0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Amps B Ø | 156.0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Amps A Ø | 151.0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | 9 Month Operations | 4 | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | CH000476 | ControlHouse | BK-Battery Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | CH000476 | ControlHouse | BK-Battery Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | CH000476 | ControlHouse | BK-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | CH000476 | ControlHouse | BK-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | CH000476 | ControlHouse | BK-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | CH000476 | ControlHouse | BK-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | CH000476 | ControlHouse | BK-Battery Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | CH000476 | ControlHouse | BK-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | CH000476 | ControlHouse | BK-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | CH000476 | ControlHouse | BK-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | CH000476 | ControlHouse | BK-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | CH000476 | ControlHouse | BK-Battery Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Readings | X3 Winding Temp Present | 39 | °C |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Amps C Ø | 41.0 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Amps B Ø | 35.0 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Amps A Ø | 41.0 | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | 9 Month Operations | 2 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0405 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0405 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0405 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0405 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0405 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Unknown Operations | 1 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Switching Operations | 3 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Operations This Read Vac | 4 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Operations Counter AL | 199 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Operations Counter AF | 199 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BK001090 | BreakerVacuum | 444-4400 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0464 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0464 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0464 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Temp Max | 30 | °C |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0464 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Temp Present | 20 | °C |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0464 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0464 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0464 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | YD000259 | Yard | 440-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | YD000259 | Yard | 440-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | YD000259 | Yard | 440-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | YD000259 | Yard | 440-Yard | Yard Patrol Inspection | General Comments | | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 122.9 | volts |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | YD000259 | Yard | 440-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | YD000259 | Yard | 440-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | YD000259 | Yard | 440-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | YD000259 | Yard | 440-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | YD000259 | Yard | 440-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | YD000259 | Yard | 440-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | YD000259 | Yard | 440-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | YD000259 | Yard | 440-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Amps A Ø | 5.2 | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Amps B Ø | 3.4 | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Amps C Ø | 1.9 | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | MX0351 | RecloserElectronic | 883-4427 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | M0069 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Readings | X3 Winding Temp Max | 62 | °C |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Readings | X2 Winding Temp Present | 40 | °C |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Readings | X2 Winding Temp Max | 62 | °C |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Readings | X1 Winding Temp Present | 40 | °C |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Readings | X1 Winding Temp Max | 53 | °C |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Readings | Oil Temp Present | 39 | °C |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Readings | Oil Temp Max | 55 | °C |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 500 | psi |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 3.0 | psi |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Readings | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Cooling Group Position | Bank2 | chg 1st quarter |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | WithLTC | BR-TRANS 4 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0464 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0464 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0464 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Readings | Totalizer Meter Reading | .3800 | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.0 | volts |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 485871 | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Operations This Read Vac | 1 | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R1258 | Regulator | 708-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 126295 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 74331 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1202 | Regulator | 444-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Readings | Oil Temp Max | 45 | °C |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 3L | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Counter Readings | LTC Min Tap Position | 6L | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 482 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PN53 | LTCMechanism | CT-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Readings | Oil Temp Present | 32 | °C |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | W0308 | WithLTC | 883-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Min Tap Position | 10L | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 36104 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Min Tap Position | 3L | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | 9 Month Operations | 1 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1514 | Regulator | 082-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Operations This Read Vac | 1 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Operations Counter AL | 229 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Operations Counter AF | 228 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Maintenance Operations | 1 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | General Comments | 1 op -Trip Check | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000551 | BreakerVacuum | 498-1541 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | R1430 | Regulator | 544-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Current Tap Position | 5L | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Operations Counter AL | 194 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Operations Counter AF | 193 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Maintenance Operations | 1 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | General Comments | 1 op - Trip Check | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Amps C Ø | 27.0 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Amps B Ø | 29.0 | |
| 1/4/2023 9:01 | Distribution | Sixth Vein Quarterly Inspection | BK000552 | BreakerVacuum | 498-1544 | VCB Readings | Amps A Ø | 33.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | R0456 | Regulator | 440-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Amps C Ø | 150.0 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | General Comments | | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Amps B Ø | 120.0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Amps A Ø | 180.0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Patrol Inspection | General Comments | | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0165 | BreakerAirMagnetic | CT-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Operations Counter AF | 338 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Operations Counter AL | 339 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Operations This Read Vac | 1 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | 9 Months Operations | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Switching Operations | 1 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0177 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0177 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0177 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0177 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0177 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | General Comments | | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/4/2023 12:53 | Distribution | Catrons Creek Quarterly Inspection | FE000050 | Fence | 883-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 108757 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.8 | volts |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Max Tap Position | Neutral | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0404 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Unknown Operations | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Switching Operations | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Operations This Read AM | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Operations Counter AL | 619 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Operations Counter AF | 619 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Maintenance Operations | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | General Comments | | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Patrol Inspection | General Comments | | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Follow-up Action Required? | n | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | LB0166 | BreakerAirMagnetic | CT-2 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 70.00 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | X0080 | RecloserHydraulic | 440-1709 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | X0080 | RecloserHydraulic | 440-1709 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | X0080 | RecloserHydraulic | 440-1709 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 24.7 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | X0080 | RecloserHydraulic | 440-1709 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 13.2 | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | X0080 | RecloserHydraulic | 440-1709 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 11.8 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Trash Emptied? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | General Comments | | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | CH000486 | ControlHouse | 859-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Max Tap Position | 3R | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Readings | Oil Temp Max | 40 | °C |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 0 | psi |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Readings | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PF001299 | PowerFuse | CT-4KV TR 2 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PF001299 | PowerFuse | CT-4KV TR 2 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PF001299 | PowerFuse | CT-4KV TR 2 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PF001298 | PowerFuse | CT-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PF001298 | PowerFuse | CT-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | PF001298 | PowerFuse | CT-4KV TR 1 POT | Disconnect Powerfuse Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0022 | WithLTC | BR-TRANS 2 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | X0080 | RecloserHydraulic | 440-1709 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | X0080 | RecloserHydraulic | 440-1709 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | X0080 | RecloserHydraulic | 440-1709 | Recloser Hydraulic Patrol Inspection | Operations Counter | 435 | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | X0080 | RecloserHydraulic | 440-1709 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | X0080 | RecloserHydraulic | 440-1709 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | X0080 | RecloserHydraulic | 440-1709 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | X0080 | RecloserHydraulic | 440-1709 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | X0080 | RecloserHydraulic | 440-1709 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BCH000310 | Charger | 421-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BCH000310 | Charger | 421-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | BCH000310 | Charger | 421-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.9 | VDC |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0405 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0333 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Readings | General Comments | | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Readings | Oil Temp Present | 30 | °C |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Max | 60 | °C |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Readings | X1 Winding Temp Present | 32 | °C |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | 9 Month Operations | 3 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Readings | X3 Winding Temp Present | 47 | °C |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0529 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0529 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0529 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0529 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0529 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0529 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | YD000116 | Yard | 707-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | YD000116 | Yard | 707-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | YD000116 | Yard | 707-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | YD000116 | Yard | 707-Yard | Yard Patrol Inspection | General Comments | | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | YD000116 | Yard | 707-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | YD000116 | Yard | 707-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | YD000116 | Yard | 707-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | YD000116 | Yard | 707-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | YD000116 | Yard | 707-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | YD000116 | Yard | 707-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | YD000116 | Yard | 707-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | YD000116 | Yard | 707-Yard | Yard Patrol Inspection | Ambient Temp | 59 | °F |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | 9 Month Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Amps A Ø | 175.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Amps B Ø | 222.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Amps C Ø | 218.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Operations Counter AF | 56 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Operations Counter AL | 56 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Operations This Read Vac | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001647 | BreakerVacuum | BR-12KV TR 4 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | General Comments | | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PN16 | WithLTC | BK-TRANS 1 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 500 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | LTCM000038 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | LTCM000038 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | LTCM000038 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | LTCM000038 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Good | check oil cup |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | LTCM000038 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | LTCM000038 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Readings | Oil Temp Present | 45 | °C |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Readings | Oil Temp Max | 57 | °C |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Readings | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | General Comments | | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/4/2023 11:27 | Distribution | Cawood Quarterly Inspection | ST000120 | Structure | 707-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0529 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0529 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0529 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0529 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0529 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0529 | NonLTC | 932-Offline Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | General Comments | | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Readings | X3 Winding Temp Max | 60 | °C |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Readings | X2 Winding Temp Present | 48 | °C |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Readings | X2 Winding Temp Max | 60 | °C |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Readings | X1 Winding Temp Present | 48 | °C |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Operations Counter AF | 717 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1326 | Regulator | 783-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Amps A Ø | 63.0 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Amps B Ø | 50.0 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Amps C Ø | 54.0 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | K0134 | BreakerVacuum | 783-2212 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Readings | X1 Winding Temp Max | 60 | °C |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0024 | WithLTC | BR-TRANS 5 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Operations Counter AL | 717 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Operations This Read Vac | 0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | TX000056 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | LTCMechanism | BR-TRANS 1 | LTC Counter Readings | LTC As Left Counter | 86091 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | LTCMechanism | BR-TRANS 1 | LTC Counter Readings | LTC As Found Counter | 86091 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | LTCMechanism | BR-TRANS 1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | LTCMechanism | BR-TRANS 1 | LTC Counter Readings | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | LTCMechanism | BR-TRANS 1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | LTCMechanism | BR-TRANS 1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 500 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | WX0242 | RecloserElectronic | 912-Offline-Distribution | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | WX0242 | RecloserElectronic | 912-Offline-Distribution | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0245 | GroundTransformer | BR-GND TR 2 | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0245 | GroundTransformer | BR-GND TR 2 | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0245 | GroundTransformer | BR-GND TR 2 | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0245 | GroundTransformer | BR-GND TR 2 | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PF001288 | PowerFuse | BK-4KV TR 1 POT | Disconnect Powerfuse Inspection | General Comments | ok | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | PF001288 | PowerFuse | BK-4KV TR 1 POT | Disconnect Powerfuse Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0245 | GroundTransformer | BR-GND TR 2 | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0245 | GroundTransformer | BR-GND TR 2 | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Readings | General Comments | | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 3634.56 | kw |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Readings | Oil Temp Max | 39 | °C |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Readings | Oil Temp Present | 39 | °C |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 3200 | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.1358 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0245 | GroundTransformer | BR-GND TR 2 | Ground Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0245 | GroundTransformer | BR-GND TR 2 | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0245 | GroundTransformer | BR-GND TR 2 | Ground Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0245 | GroundTransformer | BR-GND TR 2 | Ground Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LTCC000839 | LTCControl | BR-TRANS 2 | LTC Control Insp | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LTCC000839 | LTCControl | BR-TRANS 2 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Amps C Ø | 50.0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Amps B Ø | 80.0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Amps A Ø | 50.0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | 9 Months Operations | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | LTCMechanism | BR-TRANS 1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | LTCMechanism | BR-TRANS 1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | LTCMechanism | BR-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | LTCMechanism | BR-TRANS 1 | LTC Counter Readings | LTC Operations Since Last Insp | 3328 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | LTCMechanism | BR-TRANS 1 | LTC Counter Readings | LTC Current Tap Position | 3 | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0177 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0177 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0177 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0177 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0177 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0177 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0177 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0177 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0177 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0177 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | O0177 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | General Comments | | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | WX0242 | RecloserElectronic | 912-Offline-Distribution | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | WX0242 | RecloserElectronic | 912-Offline-Distribution | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | WX0242 | RecloserElectronic | 912-Offline-Distribution | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | WX0242 | RecloserElectronic | 912-Offline-Distribution | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | WX0242 | RecloserElectronic | 912-Offline-Distribution | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | WX0242 | RecloserElectronic | 912-Offline-Distribution | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | WX0242 | RecloserElectronic | 912-Offline-Distribution | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | WX0242 | RecloserElectronic | 912-Offline-Distribution | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | WX0242 | RecloserElectronic | 912-Offline-Distribution | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0021 | LTCMechanism | BR-TRANS 1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | WX0242 | RecloserElectronic | 912-Offline-Distribution | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | WX0242 | RecloserElectronic | 912-Offline-Distribution | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 13:24 | Distribution | Dawson Springs 12kV Quarterly Inspection | WX0242 | RecloserElectronic | 912-Offline-Distribution | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 14:09 | Distribution | Dawson Springs 4kV Quarterly Inspection | B0176 | NonLTC | 421-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | BCH001070 | Charger | DA-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | BCH001070 | Charger | DA-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BCH001320 | Charger | 444-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BCH001320 | Charger | 444-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BCH001320 | Charger | 444-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BCH001320 | Charger | 444-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BCH001320 | Charger | 444-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .6 | amps |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BCH001320 | Charger | 444-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BCH001320 | Charger | 444-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BCH001320 | Charger | 444-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.700 | millivolts |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | BAT000630 | Battery | 420-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 114466 | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:47 | Distribution | Greensburg Quarterly Inspection | R1327 | Regulator | 783-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.2 | VDC |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.2 | VDC |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | BAT001394 | Battery | 444-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LTCC000496 | LTCControl | BR-TRANS 4 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LTCC000496 | LTCControl | BR-TRANS 4 | LTC Control Insp | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LTCC000496 | LTCControl | BR-TRANS 4 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | BCH001131 | Charger | 859-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | BCH001131 | Charger | 859-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | BCH001131 | Charger | 859-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | BCH001131 | Charger | 859-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 0.0 | amps |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | BCH001131 | Charger | 859-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.5 | VDC |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | BCH001131 | Charger | 859-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.5 | VDC |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | BCH001131 | Charger | 859-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 1.900 | millivolts |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0245 | GroundTransformer | BR-GND TR 2 | Ground Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | ST000172 | Structure | 113-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0430 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0430 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0430 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0430 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0430 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | General Comments | | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | ST000013 | Structure | 444-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Current Tap Position | Neutral | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LTCC000838 | LTCControl | BR-TRANS 1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Min Tap Position | 3L | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 36764 | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Operations Counter | 305 | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | Gauge(s) Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0242 | GroundTransformer | BR-GND TR 1A | Ground Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | General Comments | 2 ops | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Vent Fans OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Switchgear Lighting OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Switchgear Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Panels Dusted? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Panel Lights OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Filters Cleaned or Replaced? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Filter Blanks Install/Remove? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Evidence of Insects | None | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 210599 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | R1200 | Regulator | 444-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0432 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0432 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0432 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 0.0 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0432 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0432 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0432 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | LTCM000049 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | LTCM000049 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | LTCM000049 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | LTCM000049 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | LTCM000049 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Counter Readings | LTC Operations Since Last Insp | 332 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Counter Readings | LTC Min Tap Position | 8L | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Counter Readings | LTC Current Tap Position | 5L | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Counter Readings | LTC As Left Counter | 187342 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Counter Readings | LTC As Found Counter | 187342 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Counter Readings | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0025 | LTCMechanism | BR-TRANS 4 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 132.0 | VDC |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | YD000014 | Yard | 444-Yard | Yard Patrol Inspection | Ambient Temp | 63 | °F |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | YD000014 | Yard | 444-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | YD000014 | Yard | 444-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | YD000014 | Yard | 444-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | YD000014 | Yard | 444-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | YD000014 | Yard | 444-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | YD000014 | Yard | 444-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | YD000014 | Yard | 444-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | YD000014 | Yard | 444-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | YD000014 | Yard | 444-Yard | Yard Patrol Inspection | General Comments | | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | YD000014 | Yard | 444-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | YD000014 | Yard | 444-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | YD000014 | Yard | 444-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | R1513 | Regulator | 082-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Amps A Ø | 50.0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Accumulated Fault Duty C Ph AM | 0.00 | % |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Accumulated Fault Duty B Ph AM | 0.00 | % |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Accumulated Fault Duty A Ph AM | 0.00 | % |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Readings | General Comments | Oil temp gauge is broken. | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | General Comments | ok | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 264.88 | kw |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 45.00 | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Readings | Oil Temp Max | 0 | °C |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Readings | Oil Temp Present | 0 | °C |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 800 | |
| 1/4/2023 14:07 | Distribution | Dycusburg Quarterly Inspection | C0172 | NonLTC | 635-1 A | NonLTC Transformer Readings | Totalizer Meter Reading | .3311 | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Amps C Ø | 100.0 | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Amps B Ø | 119.0 | |
| 1/4/2023 8:54 | Distribution | Salem Quarterly Inspection | X0329 | RecloserElectronic | 082-3425 | Recloser Electronic Patrol Inspection | Amps A Ø | 115.0 | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | General Comments | | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/6/2023 10:19 | Distribution | Dahlia Quarterly Inspection | ST000595 | Structure | DA-Structure | Structure Patrol Inspection | UG Pothead Condition Good? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | General Comments | | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Patrol Inspection | General Comments | | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | 9 Months Operations | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | 9 Month Ops New | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Doors and Locks Secure? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Door Alarms OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Aisles Clean/ Free of Debris? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | SWG000106 | Switchgear | BR-Swgr Sec 5 | Switchgear Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | Vegetation | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | General Comments | ok | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | YD000251 | Yard | 852-Yard | Yard Patrol Inspection | Ambient Temp | 50 | °F |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Unknown Operations | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Switching Operations | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Operations This Read AM | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Operations Counter AL | 454 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Operations Counter AF | 454 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | General Comments | | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Patrol Inspection | General Comments | | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 71 | °F |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | BAT000464 | Battery | 113-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0028 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LTCC000838 | LTCControl | BR-TRANS 1 | LTC Control Insp | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LTCC000838 | LTCControl | BR-TRANS 1 | LTC Control Insp | Parallel / Ind. Sw Position | parallelPAR | Position |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LTCC000839 | LTCControl | BR-TRANS 2 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Unknown Operations | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Fault Adjusted Amps C Phase AM | 0.00 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Switching Operations | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Operations This Read AM | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Operations Counter AL | 413 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Operations Counter AF | 413 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Fault Adjusted Amps B Phase AM | 0.00 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Fault Adjusted Amps A Phase AM | 0.00 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Amps C Ø | 20.0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0115 | BreakerAirMagnetic | BK-3 | AMCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 10:00 | Distribution | Brook Quarterly Inspection | LB0113 | BreakerAirMagnetic | BK-1 | AMCB Readings | Amps B Ø | 80.0 | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Max Tap Position | 12R | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0432 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0432 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 74565 | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | General Comments | | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Foundation Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.4 | volts |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 0.0 | VDC |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0432 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0432 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0432 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0432 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0432 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0432 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0432 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0432 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0432 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Fault Adjusted Amps C Phase V | 22.36 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Fault Operations C Ø | 2 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | General Comments | C phase ioc | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Operations Counter AF | 54 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Operations Counter AL | 54 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Operations This Read Vac | 2 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:43 | Distribution | Claxton Quarterly Inspection | R0254 | Regulator | 708-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Current Tap Position | 9L | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Regulator As Left Counter | 26530 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.7 | volts |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Min Tap Position | 1L | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Max | 50 | °C |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | CH000452 | ControlHouse | CT-Battery Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | CH000452 | ControlHouse | CT-Battery Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | CH000452 | ControlHouse | CT-Battery Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Max Tap Position | 5L | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | General Comments | ok | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | CH000452 | ControlHouse | CT-Battery Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | CH000452 | ControlHouse | CT-Battery Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | CH000452 | ControlHouse | CT-Battery Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | CH000452 | ControlHouse | CT-Battery Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | CH000452 | ControlHouse | CT-Battery Control House | Control House Patrol Inspection | General Comments | | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | CH000452 | ControlHouse | CT-Battery Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Readings | X1 Winding Temp Present | 45 | °C |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Current Tap Position | 3R | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | R1541 | Regulator | 448-2 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Max | 50 | °C |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Readings | X2 Winding Temp Present | 45 | °C |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Max | 50 | °C |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Readings | Winding Temp Present | 32 | °C |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Readings | Winding Temp Max | 48 | °C |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Readings | Top Oil Temperature Present | 30 | °C |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | General Comments | A, B, and C phase TOC. No VC change. Need to inspect. | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Operations Counter AF | 17 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Operations Counter AL | 17 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Operations This Read Vac | 0 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 50 | °F |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | 9 Month Operations | 2 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Amps A Ø | 13.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Amps B Ø | 10.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Amps C Ø | 17.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Follow-up Action Required? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Readings | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Readings | Oil Temp Max | 47 | °C |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Readings | Oil Temp Present | 42 | °C |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Operations Counter AL | 177 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Operations Counter AF | 176 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Maintenance Operations | 1 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | General Comments | TC op | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | General Comments | spare fuse deteriorated | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/4/2023 10:44 | Distribution | Sunset Quarterly Inspection | ST000157 | Structure | 861-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Operational? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Amps C Ø | 27.0 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | WX0332 | RecloserHydraulic | 440-1708 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | WX0332 | RecloserHydraulic | 440-1708 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | WX0332 | RecloserHydraulic | 440-1708 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 700 | psi |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | WX0332 | RecloserHydraulic | 440-1708 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | WX0332 | RecloserHydraulic | 440-1708 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 19.5 | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | WX0332 | RecloserHydraulic | 440-1708 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 32.7 | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | WX0332 | RecloserHydraulic | 440-1708 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 16.5 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0143 | BreakerVacuum | 444-4401 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | 9 Month Operations | 3 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 194 | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 236 | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 6.7 | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 10.6 | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | WX0332 | RecloserHydraulic | 440-1708 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | WX0332 | RecloserHydraulic | 440-1708 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | WX0332 | RecloserHydraulic | 440-1708 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | WX0332 | RecloserHydraulic | 440-1708 | Recloser Hydraulic Patrol Inspection | Operations Counter | 485 | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | WX0332 | RecloserHydraulic | 440-1708 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LTCC000529 | LTCControl | BR-TRANS 5 | LTC Control Insp | Parallel / Ind. Sw Position | parallelIND | Position |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 7.9 | |
| 1/4/2023 12:46 | Distribution | Outwood Quarterly Inspection | WX0453 | RecloserHydraulic | 448-1546 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 204 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Amps A Ø | 31.0 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Amps B Ø | 22.0 | |
| 1/4/2023 11:47 | Distribution | Mexico Quarterly Inspection | WX0332 | RecloserHydraulic | 440-1708 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Operations This Read Vac | 1 | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Max Tap Position | 5L | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | General Comments | ok | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | X0113 | RecloserHydraulic | 544-0429 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LTCC000529 | LTCControl | BR-TRANS 5 | LTC Control Insp | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LTCC000529 | LTCControl | BR-TRANS 5 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | X0113 | RecloserHydraulic | 544-0429 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | X0113 | RecloserHydraulic | 544-0429 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | X0113 | RecloserHydraulic | 544-0429 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | X0113 | RecloserHydraulic | 544-0429 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | 9 Month Operations | 2 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Amps A Ø | 104.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Amps B Ø | 120.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Readings | Amps C Ø | 116.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | General Comments | | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | FE000229 | Fence | 673-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001644 | BreakerVacuum | BR-1181 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Fault Adjusted Amps A Phase V | 3.31 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Fault Adjusted Amps B Phase V | 3.31 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Fault Adjusted Amps C Phase V | 3.31 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | General Comments | TC and 2 ops | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Maintenance Operations | 1 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Operations Counter AF | 223 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Operations Counter AL | 223 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Operations This Read Vac | 3 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000908 | BreakerVacuum | 673-1704 | VCB Readings | Unknown Operations | 2 | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/5/2023 7:42 | Distribution | Carter Quarterly Inspection | BAT001295 | Battery | CT-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 0.0 | VDC |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | X0113 | RecloserHydraulic | 544-0429 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | X0113 | RecloserHydraulic | 544-0429 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | X0113 | RecloserHydraulic | 544-0429 | Recloser Hydraulic Patrol Inspection | Operations Counter | 183 | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | X0113 | RecloserHydraulic | 544-0429 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | X0113 | RecloserHydraulic | 544-0429 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | X0113 | RecloserHydraulic | 544-0429 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | X0113 | RecloserHydraulic | 544-0429 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 14:50 | Distribution | Liggett Quarterly Inspection | X0113 | RecloserHydraulic | 544-0429 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | KT0029 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 192613 | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R0857 | Regulator | 852-1 A | Regulator Patrol Inspection | Min Tap Position | 13L | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 65 | °F |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Station Ground Set On Site? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Readings | General Comments | | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Amps C Ø | 39.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Panel Lights OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Floor Swept? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Operations Counter AL | 54 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Amps B Ø | 120.0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Amps C Ø | 40.0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Operations Counter AF | 54 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Amps B Ø | 46.0 | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Amps A Ø | 28.0 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.8 | psi |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1800 | psi |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | LT0023 | WithLTC | BR-TRANS 3 | LTC Transformer Readings | X3 Winding Temp Present | 45 | °C |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | C0476 | WithLTC | 932-Offline Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | ST000235 | Structure | 673-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | 9 Month Operations | 4 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Fault Operations A Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0473 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0473 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0473 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.7 | VDC |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.8 | VDC |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | Eyewash Solution | Exp/Missing Not Repl | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 9:21 | Distribution | Salem 12kV Quarterly Inspection | BK000907 | BreakerVacuum | 673-1703 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0473 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0473 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 11:03 | Distribution | Eastland Storage Quarterly Inspection | B0473 | LTCMechanism | 932-Offline Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | 9 Month Operations | 0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Switch Diagram Present/Current | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Trash Emptied? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Operations This Read Vac | 0 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 14:00 | Distribution | Shawnee Gas Quarterly Inspection | MB0144 | BreakerVacuum | 444-4402 | VCB Readings | Amps A Ø | 60.0 | |
| 1/4/2023 12:27 | Distribution | Turtle Creek Quarterly Inspection | BAT001559 | Battery | 859-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Door Alarms OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Broom on Site? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | CH000133 | ControlHouse | BR-Control House 1 | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Readings | Top Oil Temperature Max | 49 | °C |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Current Tap Position | 10L | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 12:37 | Distribution | Briar Hill Road Quarterly Inspection | FE000497 | Fence | 420-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 10:01 | Distribution | Hardesty Quarterly Inspection | T0168 | NonLTC | 113-2 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Unknown Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Fault Operations C Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | 9 Month Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | General Comments | | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:43 | Distribution | Kuttawa Quarterly Inspection | R1188 | Regulator | 852-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001645 | BreakerVacuum | BR-1182 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Amps C Ø | 0.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Amps B Ø | 0.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Amps A Ø | 0.0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001646 | BreakerVacuum | BR-1183 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 12:00 | Distribution | Breckenridge Quarterly Inspection | BK001643 | BreakerVacuum | BR-1177 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | BAT001607 | Battery | 770-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | BAT001607 | Battery | 770-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 57 | °F |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | BAT001607 | Battery | 770-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | YD000032 | Yard | 557-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | YD000032 | Yard | 557-Yard | Yard Patrol Inspection | General Comments | | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BAT001658 | Battery | 437-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | YD000032 | Yard | 557-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | YD000032 | Yard | 557-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | YD000032 | Yard | 557-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | BAT001607 | Battery | 770-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | BAT001607 | Battery | 770-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | BAT001607 | Battery | 770-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | BAT001607 | Battery | 770-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | BAT001607 | Battery | 770-Battery Bank | Battery Patrol Inspection | General Comments | ok | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | BAT001607 | Battery | 770-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.1 | VDC |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 18329 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Readings | Oil Temp Max | 52 | °C |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Readings | LTC Totalizer Reading | 4478.40 | kw |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | General Comments | 1 switching op and 2 unknowns. | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | General Comments | ok | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Maintenance Operations | 0 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Operations Counter AF | 208 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Operations Counter AL | 208 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Operations This Read Vac | 3 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BAT001658 | Battery | 437-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BAT001658 | Battery | 437-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BAT001658 | Battery | 437-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.5 | VDC |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BAT001658 | Battery | 437-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.6 | VDC |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BAT001658 | Battery | 437-Battery Bank | Battery Patrol Inspection | General Comments | ok | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BAT001658 | Battery | 437-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BAT001658 | Battery | 437-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.2000 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | No psi gauge | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | General Comments | 2 arrestors blown on cir 414 and one blown on cir 414, center insulator on transfer buss has chipped skirt | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | YD000032 | Yard | 557-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BAT001658 | Battery | 437-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Needs Replacing | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | Needs new nitrogen gauge. | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Max Tap Position | 12R | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Unknown Operations | 2 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Amps C Ø | 56.0 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Amps B Ø | 55.0 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Fault Operations Ground | 0 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Follow-up Action Required? | n | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | General Comments | ok | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 3400 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | General Comments | ok | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Amps A Ø | 65.0 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Readings | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | No psi or oil level gauge | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | BAT001607 | Battery | 770-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.1 | VDC |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | BAT001607 | Battery | 770-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | BAT001607 | Battery | 770-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | Tank oil level high due to radiators empty | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000256 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | YD000080 | Yard | 606-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | General Comments | | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | General Comments | ok | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Grounds in Place? | n | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Max Tap Position | 12L | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BAT001658 | Battery | 437-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BAT001658 | Battery | 437-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 57 | °F |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BAT001658 | Battery | 437-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Switching Operations | 1 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0298 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | ST000034 | Structure | 557-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0298 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0298 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000209 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | General Comments | ok | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0298 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0298 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0375 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Operations Counter AF | 240 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | Needs new oil level gauge. | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0356 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0376 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0376 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0376 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0376 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Maintenance Operations | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | General Comments | | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | YD000053 | Yard | 403-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | YD000053 | Yard | 403-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | YD000053 | Yard | 403-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Patrol Inspection | General Comments | | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0356 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0356 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0356 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0356 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | No psi gauge | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0375 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0375 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0356 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0356 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0356 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Follow-up Action Required? | n | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0375 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1422.36 | kw |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | YD000053 | Yard | 403-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | YD000053 | Yard | 403-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | YD000053 | Yard | 403-Yard | Yard Patrol Inspection | General Comments | | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0356 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | YD000053 | Yard | 403-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | YD000053 | Yard | 403-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | YD000053 | Yard | 403-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Amps C Ø | 19.0 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Amps B Ø | 30.0 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Amps A Ø | 23.0 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Needs Replacing | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | Needs psi gauge | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Readings | Oil Temp Present | 40 | °C |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Maintenance Operations | 0 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 3305 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Operations Counter AF | 184 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Operations Counter AL | 184 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Operations This Read Vac | 0 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Switching Operations | 0 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0123 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0375 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0356 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0356 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0356 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Unknown Operations | 0 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Unknown Operations | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0375 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Switching Operations | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Operations This Read Vac | 0 | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1800 | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .7902 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | YD000053 | Yard | 403-Yard | Yard Patrol Inspection | Ambient Temp | 73 | °F |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | YD000053 | Yard | 403-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | YD000053 | Yard | 403-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | YD000053 | Yard | 403-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Operations Counter AL | 249 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0375 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0375 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0375 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0375 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0375 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 97.50 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0375 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0374 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Regulator As Left Counter | 146376 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | 9 Month Operations | 10 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | 9 Month Operations VCB New | 7 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | General Comments | ok | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Amps A Ø | 0.0 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Amps B Ø | 0.0 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Amps C Ø | 4.0 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Max Tap Position | 9R | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | General Comments | | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 0.00 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Readings | Totalizer Meter Reading | .9330 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Fault Adjusted Amps A Phase V | 2.00 | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Fault Adjusted Amps B Phase V | 2.00 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Fault Adjusted Amps C Phase V | 2.00 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000553 | BreakerVacuum | 437-1801 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Readings | Oil Temp Present | 36 | °C |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | Needs new oil level gauge | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | General Comments | ok | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Max Tap Position | 12R | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 3427 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Tank Leaks | None | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000208 | Regulator | 770-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0236 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BCH001097 | Charger | 437-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BCH001097 | Charger | 437-Battery Charger | Battery Charger Patrol Insp | General Comments | Meter will not read mV. | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BCH001097 | Charger | 437-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BCH001097 | Charger | 437-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0376 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BCH001097 | Charger | 437-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.0 | amps |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0376 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0376 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 52.50 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0376 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0376 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BCH001097 | Charger | 437-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0376 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0376 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0376 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BCH001097 | Charger | 437-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BCH001097 | Charger | 437-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | General Comments | ok | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | S0013 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 325 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0147 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Fault Operations Ground | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0805 | Regulator | 557-2 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | General Comments | There are no spare fuses. | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 169892 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Max Tap Position | 4L | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Current Tap Position | 13L | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | 9 Month Operations VCB New | 14 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | 9 Month Operations | 16 | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0007 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0007 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0007 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0007 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0007 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Amps C Ø | 32.0 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Amps B Ø | 21.0 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | FE000222 | Fence | 437-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Amps A Ø | 21.0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | LTCC000894 | LTCControl | 032-6 | LTC Control Insp | All Connections OK? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | LTCC000894 | LTCControl | 032-6 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | LTCC000894 | LTCControl | 032-6 | LTC Control Insp | General Comments | | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | LTCC000894 | LTCControl | 032-6 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | LTCC000894 | LTCControl | 032-6 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | LTCC000894 | LTCControl | 032-6 | LTC Control Insp | VRR Base Voltage AF | 124.6 | VAC |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | LTCC000894 | LTCControl | 032-6 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | LTCC000894 | LTCControl | 032-6 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Readings | General Comments | ok | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | General Comments | ok | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Current Tap Position | 13L | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Max Tap Position | 1R | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1175 | Regulator | 365-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 125.3 | volts |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Regulator As Left Counter | 36234 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.9 | volts |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Min Tap Position | 12L | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Max Tap Position | 4R | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Readings | Oil Temp Present | 26 | ℃ |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | General Comments | | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Regulator As Left Counter | 31917 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Reg Output Voltage Level | 125.4 | volts |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | General Comments | | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 60 | °F |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 27.4 | VDC |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 26.3 | VDC |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0007 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0007 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0007 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0007 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0007 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | SPCC Strongwell Containment OK | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | General Comments | ok | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | YD000222 | Yard | 437-Yard | Yard Patrol Inspection | Ambient Temp | 57 | °F |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Readings | Oil Temp Max | 38 | °C |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Unknown Operations | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Switching Operations | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Operations This Read Vac | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Operations Counter AL | 355 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Operations Counter AF | 355 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Maintenance Operations | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | General Comments | open | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | General Comments | | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Follow-up Action Required? | n | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Fault Operations Ground | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0094 | Regulator | 032-5 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | Needs psi gauge | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Needs Replacing | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 2.0 | psi |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Readings | General Comments | | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | General Comments | 2 maintenance ops to replace SEL 351S relay. | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | General Comments | ok | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Operations Counter AL | 188 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Operations This Read Vac | 10 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Switching Operations | 0 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Unknown Operations | 2 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Maintenance Operations | 2 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Operations Counter AF | 221 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Operations Counter AL | 221 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Operations This Read Vac | 2 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 252.50 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | General Comments | 4 AB T operations | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Follow-up Action Required? | n | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | General Comments | ok | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Maintenance Operations | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Fault Operations Ground | 0 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Operations Counter AF | 188 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Fault Operations B Ø | 4 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Fault Operations A Ø | 4 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Fault Adjusted Amps C Phase V | 2.00 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Fault Adjusted Amps B Phase V | 6.00 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Fault Adjusted Amps A Phase V | 6.00 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Fault Operations Ground | 0 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0146 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Amps C Ø | 0.0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 4155.84 | kw |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.6 | volts |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1173 | Regulator | 365-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 210439 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Amps B Ø | 0.0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Amps A Ø | 0.0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | 9 Month Operations VCB New | 1 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | 9 Month Operations | 1 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Switching Operations | 0 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0155 | BreakerVacuum | 770-1491 | VCB Readings | Unknown Operations | 0 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Amps C Ø | 14.0 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Amps B Ø | 8.0 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Amps A Ø | 3.0 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | 9 Month Operations VCB New | 13 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | BK000610 | BreakerVacuum | 437-1802 | VCB Readings | 9 Month Operations | 23 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0399 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 15.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | no psi gauge | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | LTCC000760 | LTCControl | 499-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | LTCC000760 | LTCControl | 499-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | LTCC000760 | LTCControl | 499-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | LTCC000760 | LTCControl | 499-1 | LTC Control Insp | LTC Output Voltage Level | 124.8 | VAC |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | LTCC000760 | LTCControl | 499-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | LTCC000760 | LTCControl | 499-1 | LTC Control Insp | General Comments | | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | LTCC000760 | LTCControl | 499-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | LTCC000760 | LTCControl | 499-1 | LTC Control Insp | All Connections OK? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Unknown Operations | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Switching Operations | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Operations This Read Vac | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Operations Counter AL | 184 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Operations Counter AF | 184 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Maintenance Operations | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | General Comments | | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Patrol Inspection | General Comments | | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Follow-up Action Required? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Fault Operations Ground | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Fault Operations B Ø | 0 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001404 | BreakerVacuum | 557-4410 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0003 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0186 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | ST000228 | Structure | 437-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Amps A Ø | 1.0 | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | O0227 | NonLTC | 365-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | 9 Month Operations | 0 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | General Comments | | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | n | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Amps A Ø | 118.0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Amps B Ø | 100.0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Amps C Ø | 99.0 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | LTCC000733 | LTCControl | 403-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | LTCC000733 | LTCControl | 403-1 | LTC Control Insp | VRR Base Voltage AL | 124.0 | VAC |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | No psi gauge | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | FE000054 | Fence | 403-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0.0 | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 0.0 | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | General Comments | Operation Counters: 609,868,448 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Readings | Oil Temp Present | 35 | °C |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 55.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Unknown Operations | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Switching Operations | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Operations This Read Vac | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Operations Counter AL | 241 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Operations Counter AF | 241 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Maintenance Operations | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | General Comments | | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Patrol Inspection | General Comments | | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Follow-up Action Required? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Fault Operations Ground | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 0.0 | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 13.2 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | 9 Month Operations | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Amps C Ø | 2.0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001400 | BreakerVacuum | 557-4407 | VCB Readings | Amps B Ø | 11.0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Fault Operations Ground | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Follow-up Action Required? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Patrol Inspection | General Comments | | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | General Comments | | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Maintenance Operations | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | M0042 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | M0042 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Counter Readings | LTC As Left Counter | 376800 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Counter Readings | LTC As Found Counter | 376792 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Operations Counter AF | 210 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Operations Counter AL | 210 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Operations This Read Vac | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Switching Operations | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Unknown Operations | 0 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | 9 Month Operations | 18 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Counter Readings | General Comments | | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | ST000058 | Structure | 403-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | K0118 | BreakerVacuum | 770-1492 | VCB Readings | 9 Month Operations VCB New | 18 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | WithLTC | 403-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 109 | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | Amps A Ø | 4.7 | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | Amps B Ø | 9.2 | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 14.0 | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 87 | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | RC000195 | RecloserHydraulic | 365-0666 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 94 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000210 | Regulator | 770-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | A Ø Operations Counter | 679 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | LTCC000733 | LTCControl | 403-1 | LTC Control Insp | VRR Base Voltage AF | 124.0 | VAC |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0696 | Regulator | 311-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | BCH000271 | Charger | 403-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | BCH000271 | Charger | 403-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | BCH000271 | Charger | 403-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .1 | amps |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | BCH000271 | Charger | 403-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.3 | VDC |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | LTCC000733 | LTCControl | 403-1 | LTC Control Insp | LTC Output Voltage Level | 124.1 | VAC |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | LTCC000733 | LTCControl | 403-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | LTCC000733 | LTCControl | 403-1 | LTC Control Insp | General Comments | | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | LTCC000733 | LTCControl | 403-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | LTCC000733 | LTCControl | 403-1 | LTC Control Insp | All Connections OK? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | BCH000271 | Charger | 403-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.3 | VDC |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Counter Readings | LTC Operations Since Last Insp | 523 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Counter Readings | LTC Min Tap Position | 7L | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Counter Readings | LTC Max Tap Position | 2L | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | LTCMechanism | 557-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0075 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | M0042 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | M0042 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | M0042 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | M0042 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | There's not a Nitrogen bottle on XFMR, Did not operate pumps | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK000830 | BreakerVacuum | 557-0409 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Amps C Ø | 0.0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Amps B Ø | 0.0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Amps A Ø | 0.0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | 9 Month Operations | 3 | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | YD000007 | Yard | 365-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | YD000007 | Yard | 365-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | YD000007 | Yard | 365-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | YD000007 | Yard | 365-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | YD000007 | Yard | 365-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | YD000007 | Yard | 365-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | YD000007 | Yard | 365-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | YD000007 | Yard | 365-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | YD000007 | Yard | 365-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | YD000007 | Yard | 365-Yard | Yard Patrol Inspection | General Comments | | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | YD000007 | Yard | 365-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | YD000007 | Yard | 365-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | No psi Guage | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0258 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Readings | Winding Temp Present | 27 | °C |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BAT001300 | Battery | 557-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Current Tap Position | 13L | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Max Tap Position | 6L | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Min Tap Position | 16L | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Current Tap Position | 7L | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0093 | Regulator | 032-5 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.2 | volts |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 66866 | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1532 | Regulator | 606-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Readings | Totalizer Meter Reading | .8658 | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | TX000251 | NonLTC | 770-1 | NonLTC Transformer Readings | Winding Temp Max | 36 | °C |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0165 | BreakerVacuum | 032-BT6-5 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | C Ø Operations Counter | 92 | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | B Ø Operations Counter | 310 | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | Amps C Ø | 0.0 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 60.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0382 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 10.00 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Readings | Oil Temp Max | 29 | °C |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | General Comments | large tree growing over top of fence to the right of the station. tree in customer yard. | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | n | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | FE000084 | Fence | 499-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0347 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0349 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | MX0270 | RecloserHydraulic | 311-0690 | Recloser Hydraulic Patrol Inspection | Operations Counter | 609 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | LTCC000676 | LTCControl | 557-1 | LTC Control Insp | VRR Time Delay | 60 | Seconds |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | LTCC000676 | LTCControl | 557-1 | LTC Control Insp | VRR Base Voltage AL | 124.2 | VAC |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | LTCC000676 | LTCControl | 557-1 | LTC Control Insp | VRR Base Voltage AF | 124.8 | VAC |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | LTCC000676 | LTCControl | 557-1 | LTC Control Insp | Parallel / Ind. Sw Position | paralleloff | Position |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | LTCC000676 | LTCControl | 557-1 | LTC Control Insp | LTC Output Voltage Level | 124.0 | VAC |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | LTCC000676 | LTCControl | 557-1 | LTC Control Insp | LTC Operation Checked? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | LTCC000676 | LTCControl | 557-1 | LTC Control Insp | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | LTCC000676 | LTCControl | 557-1 | LTC Control Insp | Follow-up Action Required? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | LTCC000676 | LTCControl | 557-1 | LTC Control Insp | All Connections OK? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Readings | General Comments | | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 8640.00 | kw |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 15.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | -.5 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000203 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 50.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0348 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | General Comments | | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | MX0349 | RecloserHydraulic | 365-0665 | Recloser Hydraulic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Amps A Ø | 22.0 | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Amps B Ø | 31.0 | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Amps C Ø | 19.0 | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Operations Counter | 50 | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | RC000420 | RecloserElectronic | 311-0691 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Fault Operations Ground | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Follow-up Action Required? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Patrol Inspection | General Comments | | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | General Comments | | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Maintenance Operations | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Operations Counter AF | 184 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Operations Counter AL | 184 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Operations This Read Vac | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Switching Operations | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Unknown Operations | 0 | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Operations Counter | 13 | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | CH000235 | ControlHouse | 403-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | CH000235 | ControlHouse | 403-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | CH000235 | ControlHouse | 403-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | CH000235 | ControlHouse | 403-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | CH000235 | ControlHouse | 403-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | AC/DC Dist Panels Labeled? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Acceptable Building Appearnce? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Broom on Site? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Control House Lighting OK? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Controlhouse Grounds in Place? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Doors and Locks Secure? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Evidence of Insects | None | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Fans/AC/Heater(s) Working? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Floor Condition Acceptable? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Floor Swept? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Fresh Rat/Mouse Poison? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | General Comments | | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Min Tap Position | 7L | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.5 | volts |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 92299 | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0516 | Regulator | 311-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Readings | General Comments | ok | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | General Comments | ok | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Conservator Tank Desiccant | Good | check oil cup |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Fault Operations Ground | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Amps C Ø | 62.0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Amps B Ø | 93.0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Amps A Ø | 74.0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | No psi or oil level gauge. | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | General Comments | 27.1/25 | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Amps C Ø | 50.0 | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Readings | Winding Temp Present | 32 | °C |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Readings | General Comments | | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Readings | Winding Temp Max | 33 | °C |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.9932 | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 3600 | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Readings | Top Oil Temperature Present | 33 | °C |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Readings | Top Oil Temperature Max | 33 | °C |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Amps B Ø | 56.0 | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | DX0128 | RecloserElectronic | 499-0422 | Recloser Electronic Patrol Inspection | Amps A Ø | 47.0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | General Comments | LTC tank door leaking from top bolt | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Readings | LTC Totalizer Reading | 2544.00 | kw |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Readings | Oil Temp Max | 44 | °C |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Pumps Operational? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Pumps Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Readings | Oil Temp Present | 28 | °C |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | General Comments | | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Panels Dusted? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Trash Emptied? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Ventilation Free of Debris? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | CH000237 | ControlHouse | 557-Control House | Control House Patrol Inspection | Windows/Doors Condition OK? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 7175.52 | kw |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KT0054 | NonLTC | 794-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | General Comments | | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Free of Audible Arcing? | n | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | Ambient Temp | 57 | °F |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | General Comments | | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 51.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0286 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | General Comments | No spare fuses | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | .5 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | Safety Barrier Condition OK? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | General Comments | ok | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | YD000193 | Yard | 770-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | ST000009 | Structure | 365-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | General Comments | ok | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | FE000213 | Fence | 794-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | General Comments | ok | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0187 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0187 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0187 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0187 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Readings | General Comments | ok | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Readings | Oil Temp Max | 29 | °C |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Readings | Oil Temp Present | 29 | °C |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | 9 Month Operations | 3 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Amps A Ø | 101.0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Amps B Ø | 110.0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Readings | Amps C Ø | 82.0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BK001441 | BreakerVacuum | 557-4406 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0333 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0187 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0187 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0187 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0333 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0333 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0187 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0187 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0187 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0187 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0187 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0187 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0187 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0333 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0333 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0333 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0333 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0333 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0333 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0333 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0333 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0333 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Very Low | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0467 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | FE000009 | Fence | 365-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Unknown Operations | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Switching Operations | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Operations This Read Vac | 0 | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Mechanism Patrol Inspection | LTC Tank Desiccant | Needs Replaced | check oil cup |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Counter Readings | LTC Operations Since Last Insp | 326 | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Mechanism Patrol Inspection | LTC Oil Filter Condition | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Counter Readings | LTC Min Tap Position | 14L | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Counter Readings | LTC Max Tap Position | Neutral | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Counter Readings | LTC Current Tap Position | 10L | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Counter Readings | LTC As Left Counter | 286047 | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Counter Readings | LTC As Found Counter | 286041 | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Counter Readings | General Comments | | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | LTCMechanism | 499-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Operations Counter AL | 227 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Operations Counter AF | 227 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Maintenance Operations | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | General Comments | | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Patrol Inspection | General Comments | | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Follow-up Action Required? | n | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000297 | NonLTC | 437-1 C | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 60.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000067 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 70 | °F |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | Cell Electrolyte Level | Good | If low,note cell #~'s |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | General Comments | 27.2/25.1 | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Operations Counter | 18 | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | General Comments | ok | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Max Tap Position | 12R | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.1 | volts |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 36064 | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0108 | Regulator | 794-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | YD000082 | Yard | 499-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | YD000082 | Yard | 499-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | YD000082 | Yard | 499-Yard | Yard Patrol Inspection | SPCC Spill Kit Complete? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | YD000082 | Yard | 499-Yard | Yard Patrol Inspection | General Comments | small wash out to the left of entrance gate washing gravel into customer yard | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | YD000082 | Yard | 499-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | YD000082 | Yard | 499-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | YD000082 | Yard | 499-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | YD000082 | Yard | 499-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | YD000082 | Yard | 499-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | YD000082 | Yard | 499-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | YD000082 | Yard | 499-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | YD000082 | Yard | 499-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | YD000082 | Yard | 499-Yard | Yard Patrol Inspection | Ambient Temp | 72 | °F |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Readings | Totalizer Meter Reading | .8170 | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 45.00 | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Amps A Ø | 8.0 | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Amps B Ø | 10.0 | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Amps C Ø | 9.0 | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Battery Load Check OK? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | MX0470 | RecloserElectronic | 499-0423 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0292 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 15.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000068 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | BCH001574 | Charger | 770-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | .8 | amps |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | BCH001574 | Charger | 770-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | BCH001574 | Charger | 770-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 55.0 | VDC |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | BCH001574 | Charger | 770-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 0.000 | millivolts |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 3.0 | VDC |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 2.0 | VDC |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | General Comments | | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | BAT000196 | Battery | 403-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Counter Readings | LTC Operations Since Last Insp | 832 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Counter Readings | LTC Min Tap Position | 5L | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Counter Readings | LTC Max Tap Position | 9R | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Current Tap Position | 8L | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Counter Readings | LTC Current Tap Position | 2L | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Counter Readings | LTC As Left Counter | 35056 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Counter Readings | LTC As Found Counter | 35046 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Counter Readings | General Comments | | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0316 | WithLTC | 912-Offline-Distribution | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | W0281 | LTCMechanism | 403-1 | LTC Counter Readings | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | General Comments | | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0263 | LTCMechanism | 912-Offline-Distribution | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Regulator As Left Counter | 31592 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Reg Output Voltage Level | 125.3 | volts |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Min Tap Position | 13L | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 15.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000060 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 60.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000059 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 15.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000058 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Max Tap Position | 2R | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KR0095 | Regulator | 032-5 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | BCH001574 | Charger | 770-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | BCH001574 | Charger | 770-Battery Charger | Battery Charger Patrol Insp | General Comments | ok | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | BCH001574 | Charger | 770-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | BCH001574 | Charger | 770-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | General Comments | ok | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | 9 Month Operations | 13 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | 9 Month Operations VCB New | 2 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | ST000221 | Structure | 794-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Amps A Ø | 12.0 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Amps B Ø | 12.0 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Amps C Ø | 12.0 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | No psi gauge | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0252 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Readings | General Comments | | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Readings | LTC Totalizer Reading | 3921.60 | kw |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.4832 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0266 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | no psi gauge | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | 9 Month Operations VCB New | 4 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0102 | BreakerVacuum | 032-4412 | VCB Readings | 9 Month Operations | 4 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | No psi gauge | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0251 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | TX000080 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Tank Leaks | Seeping | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Readings | Totalizer Meter Multiplier | 4800 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Readings | Totalizer Meter Reading | .5300 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0040 | WithLTC | 557-1 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 60.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | C0045 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Readings | 9 Month Operations GCB New | 1 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | Ambient Temperature | 70 | °F |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Readings | Fault Operations | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Readings | Follow-up Action Required? | n | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Readings | General Comments | | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | General Comments | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Readings | Maintenance Operations | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Readings | Num Operations Last 9 Months | 2 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Readings | Operations Counter AF | 94 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Readings | Operations Counter AL | 94 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Readings | Operations This Read SF6 | 1 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | SF6 Bushing Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | SF6 Pressure | 68 | psi |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Readings | Switching Operations | 1 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | BK001718 | BreakerSF6 | 032-618 | GCB Readings | Unknown Operations | 0 | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | General Comments | | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | ST000715 | Structure | 003-Structure 34.5 | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0225 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 236.00 | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Readings | Oil Temp Present | 24 | °C |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Readings | Oil Temp Max | 25 | °C |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1779.84 | kw |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Fault Adjusted Amps A Phase V | 21.30 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Fault Adjusted Amps B Phase V | 21.30 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Fault Adjusted Amps C Phase V | 9.13 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Fault Operations A Ø | 4 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Fault Operations B Ø | 4 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Fault Operations Ground | 3 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | General Comments | | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Operations Counter AF | 1329 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Operations Counter AL | 1329 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Operations This Read Vac | 11 | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Readings | Oil Temp Max | 56 | °C |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.5 | psi |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Readings | General Comments | | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Switching Operations | 0 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | MB0124 | BreakerVacuum | 403-0415 | VCB Readings | Unknown Operations | 0 | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | O0213 | NonLTC | 311-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Readings | Oil Temp Present | 38 | °C |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | M0054 | WithLTC | 499-1 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | General Comments | | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Readings | Follow-up Action Required? | n | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Readings | General Comments | | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Readings | LTC Totalizer Reading | 9561.60 | kw |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Readings | Oil Temp Max | 36 | °C |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Readings | Oil Temp Present | 36 | °C |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Operations Counter | 88 | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Readings | Totalizer Meter Multiplier | 9600 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Readings | Totalizer Meter Reading | .9960 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Readings | WithLTC Trn Dynamic Health | 90.00 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | WithLTC | 032-6 | LTC Transformer Readings | WLTC Bushing Dynamic Health | 0.00 | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Amps C Ø | 10.0 | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Current Tap Position | 11L | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Readings | Winding Temp Max | 25 | °C |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KT0040 | NonLTC | 032-5 | NonLTC Transformer Readings | Winding Temp Present | 30 | °C |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Fault Operations Ground | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | General Comments | | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | General Comments | | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Maintenance Operations | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Operations Counter AF | 467 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Operations Counter AL | 467 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Operations This Read Vac | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Switching Operations | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Unknown Operations | 0 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Amps A Ø | 0.0 | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Amps B Ø | 0.0 | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Amps C Ø | 0.0 | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | X0325 | RecloserElectronic | 606-0424 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Min Tap Position | 16L | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Max Tap Position | 3L | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | General Comments | | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Current Tap Position | 11L | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | General Comments | | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Max Tap Position | 9R | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Min Tap Position | 8L | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Regulator As Left Counter | 35780 | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | FE000099 | Fence | 311-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Max Tap Position | 10R | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | General Comments | ok | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | General Comments | ok | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Gap Beneath Fence <  4 Inches? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | FE000896 | Fence | 770-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | General Comments | ok | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Unable to Reset | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 37761 | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Min Tap Position | 11L | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Max Tap Position | 16R | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | General Comments | ok | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0109 | Regulator | 794-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 63485 | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1534 | Regulator | 606-1 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Amps A Ø | 10.0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | 9 Month Operations | 3 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Amps B Ø | 10.0 | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Current Tap Position | 3L | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Max Tap Position | 7R | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | BCH001452 | Charger | 794-Battery Charger | Battery Charger Patrol Insp | General Comments | ok | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | BCH001452 | Charger | 794-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | BCH001452 | Charger | 794-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 55.0 | VDC |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 383503 | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | R0625 | Regulator | 311-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 52.50 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | No psi gauge | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0250 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Regulator As Left Counter | 163640 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | YD000032 | Yard | 557-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | YD000032 | Yard | 557-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | YD000032 | Yard | 557-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | YD000032 | Yard | 557-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | YD000032 | Yard | 557-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | YD000032 | Yard | 557-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | YD000032 | Yard | 557-Yard | Yard Patrol Inspection | Ambient Temp | 54 | °F |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | YD000080 | Yard | 606-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | YD000080 | Yard | 606-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | YD000080 | Yard | 606-Yard | Yard Patrol Inspection | General Comments | | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | YD000080 | Yard | 606-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | Needs new oil level gauge and oil temp gauge. | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000230 | Regulator | 437-1 A | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | KB0101 | BreakerVacuum | 032-4411 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 217.50 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 7.50 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Current Tap Position | 1L | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | RG000207 | Regulator | 770-1 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0184 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | YD000080 | Yard | 606-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | YD000080 | Yard | 606-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | YD000080 | Yard | 606-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | YD000080 | Yard | 606-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | YD000080 | Yard | 606-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | YD000080 | Yard | 606-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | YD000080 | Yard | 606-Yard | Yard Patrol Inspection | Ambient Temp | 69 | °F |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | 9 Month Operations | 5 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | MB0166 | BreakerVacuum | 032-0413 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | BAT001526 | Battery | 794-Battery Bank | Battery Patrol Inspection | Positive DC Ground | 27.0 | VDC |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | BAT001526 | Battery | 794-Battery Bank | Battery Patrol Inspection | Negative DC Ground | 26.4 | VDC |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | BAT001526 | Battery | 794-Battery Bank | Battery Patrol Inspection | General Comments | ok | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | BAT001526 | Battery | 794-Battery Bank | Battery Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | BAT001526 | Battery | 794-Battery Bank | Battery Patrol Inspection | Cells Free of Leaks? | y | If no, which cells in comments |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | BAT001526 | Battery | 794-Battery Bank | Battery Patrol Inspection | Cases Free of Cracks? | y | If no, which cells in comments |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | BAT001526 | Battery | 794-Battery Bank | Battery Patrol Inspection | Cases Free of Bulges? | y | If no, which cells in comments |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | General Comments | | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | BAT001526 | Battery | 794-Battery Bank | Battery Patrol Inspection | Battery Post Condition OK? | y | If no, which cells in comments |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | BAT001526 | Battery | 794-Battery Bank | Battery Patrol Inspection | Battery Overall Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | BAT001526 | Battery | 794-Battery Bank | Battery Patrol Inspection | Battery Area Ambient Temp | 57 | °F |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | BAT001526 | Battery | 794-Battery Bank | Battery Patrol Inspection | All Connections OK? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | General Comments | ok | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 123.9 | volts |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 236 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0265 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Neighboring Fence within 6'? | n | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | General Comments | | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | FE000080 | Fence | 606-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000231 | Regulator | 437-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 70866 | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.4 | volts |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Min Tap Position | 16L | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | R1533 | Regulator | 606-1 B | Regulator Patrol Inspection | Max Tap Position | 4L | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0234 | NonLTC | 912-Offline-34 kV | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Min Tap Position | 6L | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Max Tap Position | 8R | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | General Comments | | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Current Tap Position | 2L | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | R0871 | Regulator | 557-2 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Amps A Ø | 19.0 | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Amps B Ø | 23.0 | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Amps C Ø | 27.0 | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | BAT001526 | Battery | 794-Battery Bank | Battery Patrol Inspection | Tray/Cab/Rack Corrosion Free? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | BAT001526 | Battery | 794-Battery Bank | Battery Patrol Inspection | Straps Corrosion Free? | y | If no, which cells in comments |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | General Comments | ok | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Operations Counter | 103 | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Panel Lights OK? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KX0206 | RecloserElectronic | 794-0839 | Recloser Electronic Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Barbed Wire Condition OK? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Fence >5' Clearance To Trees? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Fence Fabric Condition OK? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Fence Gate Gap < 6 Inches? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Fence Gates Aligned? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Fence Grounds in Place? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | KT0018 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Fence Posts Condition OK? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Fence Ties Intact? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Free of Overhanging Limbs? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Gap Beneath Fence < 4 Inches? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Gate Has 911 Info On Sign? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | FE000035 | Fence | 557-Fence | Fence Patrol Inspection | Gate Locks Functioning ? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Amps C Ø | 0.0 | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 100.00 | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 105.00 | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Nitrogen Bottle Pressure | 1200 | psi |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Readings | General Comments | | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Unknown Operations | 0 | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Switching Operations | 0 | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Operations This Read Vac | 0 | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Operations Counter AL | 251 | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Operations Counter AF | 251 | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Maintenance Operations | 0 | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | General Comments | | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | General Comments | | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Follow-up Action Required? | n | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Fault Operations Ground | 0 | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Mechanism Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Counter Readings | General Comments | | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Mechanism Patrol Inspection | General Comments | | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Counter Readings | LTC As Found Counter | 144185 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Counter Readings | LTC As Left Counter | 144196 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | General Comments | ok | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Readings | Winding Temp Present | 50 | °C |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Readings | Winding Temp Max | 60 | °C |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Readings | Top Oil Temperature Present | 45 | °C |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Readings | Top Oil Temperature Max | 50 | °C |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Fault Operations Ground | 0 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Follow-up Action Required? | n | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | General Comments | | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | General Comments | | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Needs Replacing | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Maintenance Operations | 0 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Operations Counter AF | 12 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Operations Counter AL | 12 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Operations This Read Vac | 0 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Switching Operations | 0 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | Needs psi gauge | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Reg Output Voltage Level | 124.7 | volts |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Regulator As Left Counter | 10846 | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | B0145 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | 9 Month Operations | 5 | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | 9 Month Operations VCB New | 5 | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Amps A Ø | 32.0 | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Amps B Ø | 20.0 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | General Comments | ok | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Readings | General Comments | ok | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 15.00 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 10.00 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Readings | Oil Temp Max | 34 | °C |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Readings | Oil Temp Present | 29 | °C |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Unknown Operations | 0 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Fault Adjusted Amps C Phase V | 0.00 | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Amps C Ø | 38.0 | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Amps B Ø | 41.0 | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Amps A Ø | 33.0 | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | 9 Month Operations VCB New | 0 | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | BK000008 | BreakerVacuum | 003-3423 | VCB Readings | 9 Month Operations | 0 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BCH001347 | Charger | 557-Battery Charger | Battery Charger Patrol Insp | A.C. Ripple on Batteries | 3.400 | millivolts |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BCH001347 | Charger | 557-Battery Charger | Battery Charger Patrol Insp | As Found Float Voltage | 53.4 | VDC |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BCH001347 | Charger | 557-Battery Charger | Battery Charger Patrol Insp | As Left Float Voltage | 53.4 | VDC |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BCH001347 | Charger | 557-Battery Charger | Battery Charger Patrol Insp | Battery Charger Current | 2.2 | amps |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BCH001347 | Charger | 557-Battery Charger | Battery Charger Patrol Insp | Charger Alarms Present | None | note in comments if present |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BCH001347 | Charger | 557-Battery Charger | Battery Charger Patrol Insp | Follow-up Action Required? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BCH001347 | Charger | 557-Battery Charger | Battery Charger Patrol Insp | General Comments | | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | BCH001347 | Charger | 557-Battery Charger | Battery Charger Patrol Insp | Ground Lights | None | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/3/2023 13:21 | Distribution | Crofton Quarterly Inspection | ST000200 | Structure | 770-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Readings | General Comments | ok | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Readings | Non LTC Totalizer Reading | 1004.40 | kw |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 60.00 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 55.00 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Mechanism Patrol Inspection | LTC Compartment Gasket | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Counter Readings | LTC Current Tap Position | 8L | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Readings | Oil Temp Max | 29 | °C |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Readings | Oil Temp Present | 29 | °C |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Counter Readings | LTC Max Tap Position | 1L | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Counter Readings | LTC Min Tap Position | 11L | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Mechanism Patrol Inspection | LTC Nitrogen Blanket Press | 1.0 | psi |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Counter Readings | LTC Operations Since Last Insp | 410 | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Mechanism Patrol Inspection | LTC Tank Oil Level | Good | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Counter Readings | Reset Tap Drag Hands | Reset | |
| 1/3/2023 13:22 | Distribution | Harlan Y Quarterly Inspection | M0098 | LTCMechanism | 032-6 | LTC Mechanism Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Readings | Totalizer Meter Multiplier | 1200 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000295 | NonLTC | 437-1 A | NonLTC Transformer Readings | Totalizer Meter Reading | .8370 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Fault Operations A Ø | 0 | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Fault Operations B Ø | 0 | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Fault Operations C Ø | 0 | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Fault Operations Ground | 0 | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Follow-up Action Required? | n | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | General Comments | ok | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | General Comments | ok | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Heaters (All) Functioning? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Maintenance Operations | 0 | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Operations Counter AF | 293 | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Operations Counter AL | 293 | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Operations This Read Vac | 0 | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Spring Compression Ind. | springcharged | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Switching Operations | 0 | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | WB0176 | BreakerVacuum | 794-0837 | VCB Readings | Unknown Operations | 0 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | TX000296 | NonLTC | 437-1 B | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 15:07 | Distribution | Princeton Quarterly Inspection | T0171 | NonLTC | 003-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Readings | Oil Temp Max | 50 | °C |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 10886.40 | kw |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Wood Structures OK? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | General Comments | | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | ST000069 | Structure | 606-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Readings | General Comments | | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | General Comments | There are no high side bushings in xfmr. | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 0.0 | psi |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 6.00 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | n | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Readings | All Temp Gauges MAX Reset | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | YD000099 | Yard | 311-Yard | Yard Patrol Inspection | Ambient Temp | 60 | °F |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | YD000099 | Yard | 311-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | YD000099 | Yard | 311-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | YD000099 | Yard | 311-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | YD000099 | Yard | 311-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | YD000099 | Yard | 311-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | YD000099 | Yard | 311-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | YD000099 | Yard | 311-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | YD000099 | Yard | 311-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | YD000099 | Yard | 311-Yard | Yard Patrol Inspection | General Comments | | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | YD000099 | Yard | 311-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | YD000099 | Yard | 311-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | YD000099 | Yard | 311-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | KR0107 | Regulator | 794-1 A | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | Ambient Temp | 57 | °F |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | Banks/Rip Rap Good Condition? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | Clear of Obstacles? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | Clear of Trash? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | Drainage/Culverts Debris Free? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | Drive/Lot Drainage | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.3 | volts |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Regulator As Left Counter | 248 | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:48 | Distribution | Mannington Quarterly Inspection | RG000232 | Regulator | 437-1 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | Drive/Lot Free of Potholes? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | Drive/Lot Free of Ruts? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | Drive/Lot Free of Washouts? | y | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | General Comments | ok | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | SPCC Berms in Good Condition | Good | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | Vegetation | None | |
| 1/3/2023 12:03 | Distribution | White Plains Quarterly Inspection | YD000215 | Yard | 794-Yard | Yard Patrol Inspection | Yard Lights Working? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | General Comments | | |
| 1/3/2023 13:50 | Distribution | Dwina Quarterly Inspection | ST000105 | Structure | 311-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Readings | Totalizer Meter Reading | 1.5120 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 7200 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | M0074 | NonLTC | 557-2 | NonLTC Transformer Readings | Oil Temp Present | 34 | °C |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Surge Arrester Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Reset Tap Drag Hands | Reset | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Regulator As Left Counter | 824260 | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Reg Output Voltage Level | 124.9 | volts |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Min Tap Position | 9L | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Max Tap Position | 5R | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | General Comments | | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Current Tap Position | 4L | |
| 1/3/2023 11:24 | Distribution | Harlan Quarterly Inspection | KR0120 | Regulator | 557-2 C | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Free of Audible Arcing? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Fuse Barrels Good Condition? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | General Comments | | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Ground Connections Intact? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Readings | Totalizer Meter Reading | 0.0000 | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Readings | Winding Temp Max | 32 | °C |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Readings | Winding Temp Present | 27 | °C |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Insulators In Good Condition? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Linkage Grounds in Place? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Live Parts Good Condition? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Operating Linkage OK? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | PT/CT/CCVT Leaks | None | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | PT/CT/CCVT Oil Level OK? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | PT/CT/CCVT Properly Grounded? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | PT/CT/CCVT Visible Condition | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Signage Visible, and Proper? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Site Service Trans Condition | OK | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Spr Fuse Barrels/Links Qty OK? | n | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Steel Structures Rust Free? | y | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Surge Arrester Condition | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | 9 Month Operations | 3 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | 9 Month Operations VCB New | 3 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Accumulated Fault Duty A Ph V | 0.00 | % |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Accumulated Fault Duty B Ph V | 0.00 | % |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Accumulated Fault Duty C Ph V | 0.00 | % |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Amps A Ø | 20.0 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Amps B Ø | 12.0 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Amps C Ø | 12.0 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | Cabinet Heaters Functioning? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Fault Adjusted Amps A Phase V | 0.00 | |
| 1/4/2023 7:22 | Distribution | Dayhoit Quarterly Inspection | DB0057 | BreakerVacuum | 403-0414 | VCB Readings | Fault Adjusted Amps B Phase V | 0.00 | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Bushing Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Bushing Oil Level | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Fans Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Fans Operational? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Follow-up Action Required? | n | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 14:39 | Distribution | Earlington Substation Department Quarterly Transformer Inspection | W0244 | NonLTC | 912-Offline-Distribution | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | All Identified and Legible? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Bushing Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Bushings Connection/Risers | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Cabinet Door Seals OK? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Cabinet Internal Condition? | Clean | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Cabinet Paint Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Current Tap Position | 12L | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Readings | Follow-up Action Required? | n | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Foundation Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Follow-up Action Required? | n | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Foundation Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Gauge(s) Condition | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | General Comments | | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Grounds in Place? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Max Tap Position | 2L | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Min Tap Position | 14L | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Moisture and Leak Free? | y | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | General Comments | | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Readings | General Comments | | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Grounds in Place? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Nitrogen Blanket Pressure | 1.0 | psi |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Reg Oil Level | Good | |
| 1/4/2023 7:32 | Distribution | White Oak Quarterly Inspection | R1105 | Regulator | 365-1 B | Regulator Patrol Inspection | Reg Operation Checked? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Readings | NLTC Bushing Dyanmic Health | 0.00 | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Readings | Non LTC Totalizer Reading | 0.00 | kw |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Non LTC Trn Health | 5.00 | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Readings | NonLTC Trn Dynamic Health | 0.00 | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Readings | Oil Temp Max | 30 | °C |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Readings | Oil Temp Present | 24 | °C |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Radiator Free of Obstructions? | y | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Radiator Leaks | None | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Radiator Paint Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Tank Leaks | None | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Tank Oil Level | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Patrol Inspection | Tank Paint Condition | Good | |
| 1/3/2023 11:19 | Distribution | Forester Creek Quarterly Inspection | S0064 | NonLTC | 606-1 | NonLTC Transformer Readings | Totalizer Meter Multiplier | 2400 | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Arcing Horns Good Condition? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Conductors and Connectors OK? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Contacts Engaged Properly? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Equipment Properly Labeled? | y | |
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Follow-up Action Required? | n | |

| EndDate | aeoperatingclass | AssetInspectionDesc | EquipmentNumber | EquipmentType | Position | AssetInspectionType | AssetInspectionQuestion | ReadingValue | AssetInspectionQuestionUnit |
|---|---|---|---|---|---|---|---|---|---|
| 1/3/2023 12:43 | Distribution | Kentenia Quarterly Inspection | ST000088 | Structure | 499-Structure | Structure Patrol Inspection | Foundation Condition | Good | |